

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, August 09, 2026

Rules: 0-45



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/08/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	62	76.7%	2,414	425	82.4%	93,286	12,969	86.1%
Central Division	86.0%	55	4	92.7%	436	53	87.8%	17,792	1,619	90.9%
East Division	82.0%	133	35	73.7%	1,310	222	83.1%	48,980	7,640	84.4%
West Division	86.0%	78	23	70.5%	668	150	77.5%	26,514	3,710	86.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00671 00000008701 "UNCLASSIFIED" 9/2/2026

Endpoint Arrival Dates through 8/8/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	102,506	41,468	60%	872,738	277,058	68%	31,205,736	7,918,408	75%
Northeast Corridor	81%	43,559	18,280	58%	375,682	103,836	72%	13,677,195	3,359,864	75%
Acela	83%	6,120	1,458	76%	77,784	17,829	77%	2,738,208	719,380	74%
Northeast Regional	79%	37,439	16,822	55%	297,898	86,007	71%	10,938,987	2,640,484	76%
Richmond / Newport News / Norfolk	77%	11,237	6,137	45%	92,919	36,431	61%	3,392,895	997,892	71%
Springfield Shuttles	89%	0	0	-	4,910	832	83%	192,637	30,700	84%
Roanoke	79%	5,774	2,220	62%	30,292	7,970	74%	1,035,576	226,626	78%
On Spine Northeast Regional	80%	20,428	8,465	59%	169,777	40,774	76%	6,317,879	1,385,266	78%
State Supported	80%	47,479	15,523	67%	394,368	111,068	72%	13,703,987	2,916,993	79%
Borealis	80%	604	0	100%	4,849	671	86%	174,475	36,303	79%
Capitol Corridor	90%	2,756	891	68%	29,188	5,752	80%	1,144,907	151,501	87%
Carolinian	70%	1,153	769	33%	8,951	4,673	48%	353,833	139,672	61%
Cascades	75%	1,754	1,216	31%	14,772	7,935	46%	798,022	222,971	72%
Downeaster	82%	2,249	1,453	35%	16,897	2,105	88%	477,210	58,060	88%
Empire	78%	6,295	1,960	69%	51,864	17,709	66%	1,695,577	401,168	76%
Adirondack	72%	537	470	12%	3,791	1,881	50%	103,754	32,726	68%
Ethan Allen Express	70%	621	540	13%	4,937	3,071	38%	173,845	63,420	64%
Maple Leaf	70%	833	358	57%	7,299	3,030	58%	207,648	79,873	62%
New York - Albany	85%	2,941	442	85%	23,090	5,656	76%	785,438	131,583	83%
New York - Niagara Falls	75%	1,363	150	89%	11,566	2,905	75%	415,598	88,586	79%
Berkshire Flyer	60%	0	0	-	1,181	1,166	1%	9,294	4,980	46%
Gold Runner	73%	2,439	1,366	44%	20,416	11,633	43%	775,982	282,086	64%
Heartland Flyer	70%	292	108	63%	2,301	1,837	20%	66,984	27,259	59%
Hiawatha	90%	1,975	0	100%	16,947	1,154	93%	537,866	58,851	89%
Illinois	78%	2,682	508	81%	21,263	6,697	69%	767,487	211,252	72%
Carl Sandburg / Illinois Zephyr	85%	546	207	62%	3,315	1,498	55%	128,115	35,656	72%
Illini / Saluki	85%	752	28	96%	6,916	2,380	66%	266,803	64,280	76%
Lincoln Service	70%	1,384	273	80%	11,032	2,819	74%	372,569	111,316	70%
Keystone	92%	5,651	152	97%	63,310	3,430	95%	2,345,429	242,976	90%
Lincoln / Missouri	70%	508	313	38%	6,855	4,064	41%	239,346	122,372	49%
Mardi Gras Service	80%	324	69	79%	2,804	824	71%	126,525	28,439	78%
Michigan	70%	2,875	685	76%	20,129	8,512	58%	617,554	200,933	67%
Blue Water	70%	907	44	95%	4,791	2,307	52%	144,449	58,135	60%
Pere Marquette	85%	175	0	100%	2,249	176	92%	80,683	15,300	81%
Wolverine	70%	1,793	641	64%	13,089	6,029	54%	392,422	127,498	68%
Missouri	80%	184	130	29%	2,297	895	61%	68,133	17,331	75%
Pacific Surfliner	85%	12,353	5,299	57%	86,314	25,680	70%	2,498,486	455,387	82%
Pennsylvanian	80%	929	558	40%	7,006	2,007	71%	272,808	53,084	81%
Piedmont	80%	1,402	46	97%	7,822	1,116	86%	348,096	89,768	74%
Vermont	75%	1,054	0	100%	10,383	4,374	58%	395,267	117,580	70%
Long Distance	70%	11,468	7,665	33%	102,688	62,154	39%	3,785,287	1,639,088	57%
Auto Train	70%	926	0	100%	6,948	1,383	80%	241,357	82,172	66%
California Zephyr	70%	1,021	781	24%	8,261	6,309	24%	299,855	112,966	62%
Cardinal	70%	0	0	-	1,483	890	40%	72,964	36,433	50%
City Of New Orleans	75%	690	643	7%	5,207	4,087	22%	196,431	62,266	68%
Coast Starlight	70%	845	296	65%	8,664	5,096	41%	353,341	125,558	64%
Crescent	70%	938	383	59%	7,070	1,297	82%	286,723	87,280	70%
Empire Builder	70%	1,070	875	18%	7,907	6,330	20%	296,274	148,535	50%
Floridian	60%	1,837	1,644	11%	13,966	10,890	22%	491,732	337,932	31%
Lake Shore Ltd	73%	1,143	737	36%	9,602	4,285	55%	296,839	89,391	70%
Palmetto	70%	476	453	5%	7,313	3,926	46%	283,416	86,535	69%
Silver Meteor	70%	1,073	818	24%	8,127	5,620	31%	313,327	142,971	54%
Southwest Chief	60%	1,045	631	40%	8,306	6,152	26%	258,772	168,745	35%
Sunset Ltd	70%	404	404	0%	1,754	1,361	22%	90,120	34,129	62%
Texas Eagle	70%	0	0	-	8,080	4,528	44%	304,136	124,175	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 0000000701 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 08, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	55,574	851,436	653	1,845,653	32,799,374	563

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	3,256	256,322	127	89,168	9,453,324	94
INFRASTRUCTURE PLANNED	135	4,348	256,322	170	100,403	9,453,324	106
FLEET RELIABILITY	90	8,969	851,436	105	295,109	32,799,374	90
TRAIN OPERATIONS	424	39,001	851,436	458	1,360,973	32,799,374	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/08/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	62	76.7%	2,414	425	82.4%	93,286	12,969	86.1%
Central Division	86.0%	55	4	92.7%	436	53	87.8%	17,792	1,619	90.9%
East Division	82.0%	133	35	73.7%	1,310	222	83.1%	48,980	7,640	84.4%
West Division	86.0%	78	23	70.5%	668	150	77.5%	26,514	3,710	86.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/08/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	62	76.7%	2,414	425	82.4%	93,286	12,969	86.1%
Central Division	86.0%	55	4	92.7%	436	53	87.8%	17,792	1,619	90.9%
CDL	95.0%	2	0	100.0%	16	2	87.5%	592	27	95.4%
CHI	86.0%	25	1	96.0%	201	32	84.1%	8,215	996	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	8	0	100.0%	335	36	89.3%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	-	-	-	6	0	100.0%	294	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	1	0	100.0%	8	2	75.0%	565	44	92.2%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	46	3	93.5%	1,826	117	93.6%
MOE	97.5%	2	0	100.0%	16	0	100.0%	621	9	98.6%
MSP	96.5%	1	0	100.0%	8	1	87.5%	305	7	97.7%
NOL	94.5%	5	2	60.0%	36	2	94.4%	1,309	62	95.3%
OKC	97.0%	1	0	100.0%	8	0	100.0%	306	6	98.0%
PNT	88.0%	3	0	100.0%	23	2	91.3%	810	66	91.9%
PTH	93.0%	1	0	100.0%	8	1	87.5%	300	12	96.0%
QCY	91.0%	2	1	50.0%	13	2	84.6%	590	45	92.4%
SAS	90.5%	1	0	100.0%	8	2	75.0%	309	35	88.7%
STL	89.0%	4	0	100.0%	30	3	90.0%	1,199	100	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	133	35	73.7%	1,310	222	83.1%	48,980	7,640	84.4%
ALB	88.5%	8	0	100.0%	62	4	93.5%	2,312	179	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	3	40.0%	40	7	82.5%	1,506	165	89.0%
BOS	85.5%	17	3	82.4%	141	10	92.9%	5,304	614	88.4%
BRK	92.5%	5	2	60.0%	40	3	92.5%	1,492	105	93.0%
BTN	82.0%	1	0	100.0%	8	0	100.0%	298	41	86.2%
CLT	91.5%	5	0	100.0%	40	4	90.0%	1,517	154	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	-	-	-	11	0	100.0%	604	57	90.6%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	7	1	85.7%	86	14	83.7%	3,450	562	83.7%
HFD	-	-	-	-	10	3	70.0%	201	18	91.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	8	0	100.0%	308	38	87.7%
MIA	89.5%	2	0	100.0%	16	2	87.5%	616	70	88.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/08/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	62	76.7%	2,414	425	82.4%	93,286	12,969	86.1%
East Division	82.0%	133	35	73.7%	1,310	222	83.1%	48,980	7,640	84.4%
MTR	79.0%	1	1	0.0%	8	3	62.5%	295	55	81.4%
NFK	84.5%	2	0	100.0%	16	3	81.3%	699	126	82.0%
NFL	93.5%	2	1	50.0%	16	1	93.8%	628	30	95.2%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	3	2	33.3%	38	8	78.9%	1,592	261	83.6%
NPN	93.0%	2	0	100.0%	16	3	81.3%	588	44	92.5%
NYP	75.5%	36	13	63.9%	364	92	74.7%	12,848	2,870	77.7%
PGH	93.0%	1	0	100.0%	8	1	87.5%	309	23	92.6%
PHL	48.0%	4	4	0.0%	37	20	45.9%	1,587	760	52.1%
PIT	76.0%	-	-	-	2	2	0.0%	17	14	17.6%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	0	100.0%	24	0	100.0%	1,182	49	95.9%
RNK	83.5%	2	0	100.0%	16	0	100.0%	612	87	85.8%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	-	-	-	6	0	100.0%	293	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	8	0	100.0%	305	10	96.7%
SFA	88.0%	1	0	100.0%	8	0	100.0%	308	41	86.7%
SPG	92.5%	-	-	-	40	2	95.0%	1,847	107	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	8	1	87.5%	297	61	79.5%
WAS	84.0%	22	5	77.3%	225	39	82.7%	7,697	1,006	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	78	23	70.5%	668	150	77.5%	26,514	3,710	86.0%
ARN	92.0%	1	1	0.0%	8	1	87.5%	310	27	91.3%
BFD	79.0%	7	2	71.4%	55	14	74.5%	1,952	407	79.1%
EMY	72.0%	1	1	0.0%	8	2	75.0%	326	96	70.6%
EUG	86.5%	2	1	50.0%	16	1	93.8%	614	57	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	24	8	66.7%	933	151	83.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	0	100.0%	82	8	90.2%	3,081	334	89.2%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	9	5	44.4%	90	40	55.6%	3,351	868	74.1%
PDX	86.0%	3	3	0.0%	17	10	41.2%	1,505	191	87.3%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/08/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	266	62	76.7%	2,414	425	82.4%	93,286	12,969	86.1%
West Division	86.0%	78	23	70.5%	668	150	77.5%	26,514	3,710	86.0%
SAC	88.5%	12	1	91.7%	114	13	88.6%	4,380	475	89.2%
SAN	90.5%	13	2	84.6%	103	11	89.3%	3,744	355	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	1	66.7%	43	24	44.2%	2,428	371	84.7%
SJC	89.0%	7	2	71.4%	55	6	89.1%	2,179	215	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	24	4	83.3%	696	69	90.1%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	16	0	100.0%	607	14	97.7%
VAN	-	2	2	0.0%	7	5	28.6%	7	5	28.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	226	8	2	75.0%	310	61	80.3%	8	6	25.0%	308	142	53.9%
4		8	0	100.0%	309	46	85.1%	8	5	37.5%	309	204	34.0%
5	134	8	1	87.5%	308	51	83.4%	8	8	0.0%	304	96	68.4%
6	114	8	2	75.0%	307	87	71.7%	8	7	12.5%	307	110	64.2%
7	123	8	3	62.5%	299	45	84.9%	7	5	28.6%	290	79	72.8%
8	44	8	7	12.5%	299	136	54.5%	8	7	12.5%	298	182	38.9%
11		8	6	25.0%	310	63	79.7%	8	2	75.0%	304	62	79.6%
14		8	2	75.0%	311	51	83.6%	7	6	14.3%	308	98	68.2%
19	48	8	1	87.5%	309	78	74.8%	8	1	87.5%	306	72	76.5%
20		8	0	100.0%	309	23	92.6%	8	1	87.5%	309	59	80.9%
21	No OS	8	3	62.5%	306	28	90.8%	8	4	50.0%	305	86	71.8%
22	No OS	8	2	75.0%	307	33	89.3%	8	3	62.5%	305	84	72.5%
23		8	0	100.0%	311	6	98.1%	8	2	75.0%	309	87	71.8%
24		8	0	100.0%	311	16	94.9%	8	3	62.5%	310	59	81.0%
25	53	8	0	100.0%	310	3	99.0%	7	4	42.9%	307	87	71.7%
26		8	0	100.0%	310	5	98.4%	7	1	85.7%	307	61	80.1%
40	174	8	2	75.0%	304	43	85.9%	8	4	50.0%	301	159	47.2%
41		8	3	62.5%	303	117	61.4%	8	6	25.0%	301	230	23.6%
42	26	8	1	87.5%	311	25	92.0%	8	3	62.5%	309	55	82.2%
43	68	8	1	87.5%	310	43	86.1%	8	1	87.5%	309	71	77.0%
48		8	3	62.5%	309	60	80.6%	8	1	87.5%	308	43	86.0%
49	127	8	3	62.5%	309	78	74.8%	8	3	62.5%	309	65	79.0%
52		8	0	100.0%	308	41	86.7%	8	0	100.0%	307	72	76.5%
53		8	0	100.0%	308	38	87.7%	8	3	62.5%	307	98	68.1%
54		3	0	100.0%	112	8	92.9%	3	0	100.0%	112	16	85.7%
57		3	0	100.0%	111	5	95.5%	3	0	100.0%	111	9	91.9%
58		8	1	87.5%	285	17	94.0%	7	6	14.3%	283	79	72.1%
59	43	8	6	25.0%	283	39	86.2%	8	6	25.0%	279	63	77.4%
63	32	8	4	50.0%	312	136	56.4%	8	8	0.0%	306	174	43.1%
64	34	8	1	87.5%	310	69	77.7%	8	6	25.0%	309	115	62.8%
65		3	0	100.0%	96	12	87.5%	3	1	66.7%	94	14	85.1%
66		8	0	100.0%	309	61	80.3%	8	2	75.0%	305	56	81.6%
68	35	8	3	62.5%	312	64	79.5%	8	4	50.0%	311	122	60.8%
69	22	8	6	25.0%	299	74	75.3%	8	5	37.5%	294	48	83.7%
71		8	0	100.0%	307	3	99.0%	7	0	100.0%	305	81	73.4%
72		8	2	75.0%	303	33	89.1%	7	2	71.4%	301	63	79.1%
73		8	0	100.0%	306	19	93.8%	8	1	87.5%	304	143	53.0%
74		8	0	100.0%	304	33	89.1%	8	2	75.0%	302	110	63.6%
75		8	0	100.0%	300	16	94.7%	8	1	87.5%	294	138	53.1%
76		8	0	100.0%	300	29	90.3%	8	3	62.5%	291	120	58.8%
77		8	0	100.0%	302	20	93.4%	8	2	75.0%	300	125	58.3%
78	16	8	0	100.0%	306	25	91.8%	8	3	62.5%	305	66	78.4%

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79		8	1	87.5%	309	57	81.6%	8	2	75.0%	308	103	66.6%
80		8	2	75.0%	309	35	88.7%	8	4	50.0%	306	67	78.1%
82		2	1	50.0%	74	10	86.5%	2	0	100.0%	74	24	67.6%
87	75	3	1	66.7%	115	25	78.3%	3	2	33.3%	115	41	64.3%
88	21	3	0	100.0%	111	15	86.5%	3	1	66.7%	111	24	78.4%
89	60	8	4	50.0%	307	69	77.5%	8	5	37.5%	305	90	70.5%
90	78	8	0	100.0%	307	10	96.7%	8	4	50.0%	306	55	82.0%
97		8	7	12.5%	309	205	33.7%	8	5	37.5%	307	105	65.8%
98	77	8	0	100.0%	309	26	91.6%	8	6	25.0%	307	114	62.9%
99	19	3	0	100.0%	114	12	89.5%	3	2	33.3%	111	63	43.2%
101	37	2	1	50.0%	73	7	90.4%	2	1	50.0%	73	12	83.6%
103	104	3	2	33.3%	113	23	79.6%	3	2	33.3%	113	11	90.3%
106	58	2	2	0.0%	89	11	87.6%	2	2	0.0%	88	14	84.1%
107	52	2	2	0.0%	89	30	66.3%	2	2	0.0%	88	15	83.0%
109		2	1	50.0%	56	9	83.9%	2	0	100.0%	56	6	89.3%
118		3	0	100.0%	113	8	92.9%	3	0	100.0%	113	8	92.9%
124		3	0	100.0%	112	8	92.9%	3	1	66.7%	111	31	72.1%
126	107	2	0	100.0%	52	8	84.6%	2	1	50.0%	52	13	75.0%
127		2	1	50.0%	52	15	71.2%	2	0	100.0%	52	6	88.5%
135		3	0	100.0%	114	17	85.1%	3	0	100.0%	114	56	50.9%
140	20	3	0	100.0%	113	12	89.4%	3	2	33.3%	112	26	76.8%
142		2	1	50.0%	72	8	88.9%	2	0	100.0%	71	9	87.3%
143		3	1	66.7%	112	12	89.3%	3	0	100.0%	112	25	77.7%
144	114	2	2	0.0%	74	50	32.4%	2	2	0.0%	73	11	84.9%
146		3	0	100.0%	112	17	84.8%	3	0	100.0%	112	39	65.2%
147	67	2	1	50.0%	75	9	88.0%	2	1	50.0%	75	25	66.7%
150		3	1	66.7%	111	58	47.7%	3	0	100.0%	109	51	53.2%
151		8	4	50.0%	308	99	67.9%	8	0	100.0%	307	95	69.1%
152		2	0	100.0%	74	6	91.9%	2	0	100.0%	74	27	63.5%
153	34	3	1	66.7%	113	11	90.3%	3	2	33.3%	113	18	84.1%
155		3	1	66.7%	115	19	83.5%	3	0	100.0%	115	40	65.2%
156	17	3	0	100.0%	115	11	90.4%	3	1	66.7%	115	39	66.1%
158		3	2	33.3%	114	22	80.7%	3	1	66.7%	114	27	76.3%
159		2	0	100.0%	72	8	88.9%	2	0	100.0%	72	11	84.7%
160		3	1	66.7%	112	7	93.8%	3	0	100.0%	109	26	76.1%
161	50	3	0	100.0%	113	9	92.0%	3	2	33.3%	112	74	33.9%
162	44	3	3	0.0%	113	10	91.2%	3	1	66.7%	113	56	50.4%
163	62	2	0	100.0%	72	15	79.2%	2	2	0.0%	72	59	18.1%
164		3	0	100.0%	115	9	92.2%	3	0	100.0%	115	47	59.1%
165	34	3	0	100.0%	113	27	76.1%	3	1	66.7%	113	46	59.3%
167		2	0	100.0%	75	16	78.7%	2	0	100.0%	74	22	70.3%
168	49	2	1	50.0%	73	13	82.2%	2	1	50.0%	73	27	63.0%

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178		5	0	100.0%	197	26	86.8%	6	1	83.3%	196	32	83.7%
179		5	1	80.0%	197	24	87.8%	6	1	83.3%	197	71	64.0%
194	29	2	1	50.0%	74	18	75.7%	2	1	50.0%	73	23	68.5%
195	39	3	1	66.7%	113	5	95.6%	3	2	33.3%	113	61	46.0%
198		5	0	100.0%	129	17	86.8%	6	0	100.0%	129	21	83.7%
230		8	0	100.0%	145	4	97.2%	8	0	100.0%	145	7	95.2%
232		8	0	100.0%	311	11	96.5%	8	1	87.5%	311	22	92.9%
233	19	6	1	83.3%	279	62	77.8%	6	4	33.3%	278	92	66.9%
234		8	0	100.0%	312	22	92.9%	8	0	100.0%	311	25	92.0%
235	27	8	4	50.0%	236	38	83.9%	8	2	75.0%	235	54	77.0%
236		8	0	100.0%	296	10	96.6%	8	2	75.0%	295	41	86.1%
237		8	0	100.0%	309	56	81.9%	8	1	87.5%	307	52	83.1%
238		8	3	62.5%	236	23	90.3%	8	1	87.5%	234	19	91.9%
239		8	0	100.0%	310	79	74.5%	8	0	100.0%	309	38	87.7%
240		8	0	100.0%	311	21	93.2%	8	2	75.0%	308	62	79.9%
241		8	1	87.5%	311	75	75.9%	8	3	62.5%	311	74	76.2%
243		8	2	75.0%	247	67	72.9%	8	2	75.0%	246	35	85.8%
244		6	0	100.0%	278	12	95.7%	6	4	33.3%	278	53	80.9%
245		8	1	87.5%	192	34	82.3%	8	2	75.0%	191	24	87.4%
280		8	1	87.5%	312	16	94.9%	8	2	75.0%	311	63	79.7%
281		8	0	100.0%	312	37	88.1%	8	1	87.5%	312	58	81.4%
283		8	4	50.0%	312	78	75.0%	8	2	75.0%	312	63	79.8%
284		8	0	100.0%	312	13	95.8%	8	1	87.5%	309	55	82.2%
290	24	8	0	100.0%	312	50	84.0%	8	5	37.5%	309	119	61.5%
291	49	8	5	37.5%	311	98	68.5%	8	4	50.0%	309	80	74.1%
300		7	1	85.7%	295	21	92.9%	7	1	85.7%	293	69	76.5%
301		8	0	100.0%	309	10	96.8%	8	2	75.0%	305	57	81.3%
302		7	0	100.0%	290	33	88.6%	7	1	85.7%	286	79	72.4%
306		8	1	87.5%	307	17	94.5%	8	2	75.0%	306	84	72.5%
307	43	8	1	87.5%	300	39	87.0%	7	3	57.1%	296	85	71.3%
311	16	8	1	87.5%	305	27	91.1%	8	3	62.5%	299	66	77.9%
316	232	8	2	75.0%	301	20	93.4%	8	5	37.5%	296	83	72.0%
318		8	0	100.0%	310	31	90.0%	8	4	50.0%	307	148	51.8%
319	291	8	0	100.0%	311	20	93.6%	8	7	12.5%	306	172	43.8%
330		7	0	100.0%	265	6	97.7%	7	0	100.0%	265	15	94.3%
331		8	0	100.0%	312	33	89.4%	8	0	100.0%	312	44	85.9%
332		7	0	100.0%	311	17	94.5%	7	0	100.0%	311	43	86.2%
334		8	0	100.0%	312	10	96.8%	8	0	100.0%	311	40	87.1%
335		8	0	100.0%	312	34	89.1%	8	2	75.0%	310	53	82.9%
336		8	0	100.0%	312	10	96.8%	8	0	100.0%	310	28	91.0%
337		8	0	100.0%	312	18	94.2%	8	1	87.5%	308	37	88.0%
338		8	2	75.0%	312	49	84.3%	8	4	50.0%	310	98	68.4%

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
339		8	2	75.0%	312	52	83.3%	8	1	87.5%	312	54	82.7%
341		7	2	71.4%	299	46	84.6%	7	2	71.4%	293	43	85.3%
342		8	1	87.5%	312	25	92.0%	8	0	100.0%	310	60	80.6%
343		1	0	100.0%	44	3	93.2%	2	0	100.0%	44	10	77.3%
350	26	8	0	100.0%	289	18	93.8%	8	6	25.0%	282	157	44.3%
351	17	7	1	85.7%	294	28	90.5%	7	4	42.9%	292	82	71.9%
352		7	1	85.7%	278	22	92.1%	7	3	57.1%	272	84	69.1%
353		8	0	100.0%	250	13	94.8%	8	1	87.5%	244	39	84.0%
354		8	0	100.0%	293	35	88.1%	8	6	25.0%	286	107	62.6%
355	20	8	1	87.5%	302	32	89.4%	8	7	12.5%	295	106	64.1%
364		8	3	62.5%	301	68	77.4%	8	4	50.0%	295	111	62.4%
365		8	1	87.5%	300	12	96.0%	7	3	57.1%	297	112	62.3%
370		6	0	100.0%	301	35	88.4%	6	1	83.3%	291	70	75.9%
380		5	1	80.0%	294	28	90.5%	4	0	100.0%	293	63	78.5%
381		8	0	100.0%	310	12	96.1%	8	3	62.5%	309	63	79.6%
382	35	8	1	87.5%	309	28	90.9%	8	6	25.0%	309	106	65.7%
383	17	6	0	100.0%	299	26	91.3%	6	6	0.0%	296	129	56.4%
390		8	2	75.0%	294	21	92.9%	8	4	50.0%	293	77	73.7%
391		8	1	87.5%	295	12	95.9%	8	5	37.5%	291	81	72.2%
392		8	0	100.0%	308	10	96.8%	8	2	75.0%	305	92	69.8%
393	18	8	0	100.0%	312	18	94.2%	8	4	50.0%	309	95	69.3%
448	330	7	0	100.0%	241	43	82.2%	8	3	62.5%	239	83	65.3%
449		8	0	100.0%	239	32	86.6%	8	2	75.0%	239	44	81.6%
503	28	8	6	25.0%	308	33	89.3%	8	6	25.0%	301	93	69.1%
504		8	0	100.0%	312	19	93.9%	8	2	75.0%	310	92	70.3%
505	16	3	0	100.0%	305	41	86.6%	3	2	33.3%	300	86	71.3%
506		8	5	37.5%	307	47	84.7%	6	2	66.7%	299	48	83.9%
507		8	6	25.0%	312	42	86.5%	8	6	25.0%	312	106	66.0%
508	24	8	1	87.5%	307	42	86.3%	8	6	25.0%	303	74	75.6%
516	47	8	4	50.0%	303	33	89.1%	8	5	37.5%	302	139	54.0%
517	50	8	0	100.0%	312	8	97.4%	8	6	25.0%	308	133	56.8%
518	45	8	5	37.5%	312	42	86.5%	8	8	0.0%	310	215	30.6%
519		8	0	100.0%	303	9	97.0%	8	3	62.5%	301	69	77.1%
562		8	0	100.0%	303	23	92.4%	8	0	100.0%	299	35	88.3%
564		8	0	100.0%	304	19	93.8%	8	2	75.0%	296	40	86.5%
566	17	8	2	75.0%	302	27	91.1%	8	5	37.5%	299	50	83.3%
567		8	0	100.0%	189	10	94.7%	8	2	75.0%	187	11	94.1%
572	21	8	0	100.0%	299	24	92.0%	8	2	75.0%	292	85	70.9%
573		8	0	100.0%	301	40	86.7%	8	2	75.0%	294	53	82.0%
579		8	1	87.5%	189	12	93.7%	7	2	71.4%	183	39	78.7%
580		8	0	100.0%	304	16	94.7%	8	4	50.0%	297	32	89.2%
581	72	8	2	75.0%	304	52	82.9%	8	5	37.5%	302	69	77.2%

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
584	44	8	1	87.5%	188	26	86.2%	8	8	0.0%	183	116	36.6%
587		8	1	87.5%	297	17	94.3%	8	2	75.0%	288	55	80.9%
588	30	8	1	87.5%	189	19	89.9%	8	3	62.5%	188	36	80.9%
591	28	8	1	87.5%	301	22	92.7%	8	3	62.5%	295	42	85.8%
593		7	2	71.4%	297	49	83.5%	7	0	100.0%	276	37	86.6%
595		8	2	75.0%	299	55	81.6%	8	2	75.0%	296	62	79.1%
611	13	2	2	0.0%	45	32	28.9%	2	1	50.0%	45	5	88.9%
624		1	0	100.0%	120	38	68.3%	2	0	100.0%	121	31	74.4%
660		3	0	100.0%	84	12	85.7%	3	0	100.0%	83	25	69.9%
661	16	3	0	100.0%	112	12	89.3%	3	1	66.7%	111	42	62.2%
662		2	0	100.0%	47	0	100.0%	2	0	100.0%	47	1	97.9%
663		3	0	100.0%	85	14	83.5%	3	0	100.0%	84	8	90.5%
664	15	3	0	100.0%	84	8	90.5%	3	1	66.7%	84	12	85.7%
665		3	0	100.0%	85	10	88.2%	3	0	100.0%	85	24	71.8%
666		3	0	100.0%	83	22	73.5%	3	0	100.0%	83	7	91.6%
667		3	0	100.0%	83	7	91.6%	3	0	100.0%	81	16	80.2%
669		3	0	100.0%	83	7	91.6%	3	0	100.0%	81	22	72.8%
670		3	0	100.0%	85	13	84.7%	3	0	100.0%	83	15	81.9%
671		3	0	100.0%	83	8	90.4%	3	0	100.0%	81	9	88.9%
672		3	0	100.0%	85	8	90.6%	3	0	100.0%	85	15	82.4%
674		3	2	33.3%	83	28	66.3%	3	0	100.0%	83	7	91.6%
690	92	3	0	100.0%	89	2	97.8%	3	1	66.7%	88	5	94.3%
691	74	3	1	66.7%	89	8	91.0%	3	1	66.7%	87	24	72.4%
692		3	0	100.0%	89	3	96.6%	3	1	66.7%	88	15	83.0%
693	74	3	0	100.0%	89	12	86.5%	3	2	33.3%	87	26	70.1%
694	21	3	1	66.7%	88	10	88.6%	3	1	66.7%	88	15	83.0%
695	36	3	0	100.0%	87	10	88.5%	3	1	66.7%	87	15	82.8%
696	61	3	1	66.7%	89	10	88.8%	3	1	66.7%	89	26	70.8%
697	65	3	3	0.0%	89	22	75.3%	3	1	66.7%	89	18	79.8%
698	20	3	1	66.7%	87	3	96.6%	3	1	66.7%	87	8	90.8%
701		8	0	100.0%	244	25	89.8%	8	0	100.0%	241	25	89.6%
702		8	0	100.0%	311	32	89.7%	8	3	62.5%	308	73	76.3%
703	61	8	6	25.0%	312	99	68.3%	8	4	50.0%	310	89	71.3%
704		8	2	75.0%	243	39	84.0%	8	2	75.0%	236	48	79.7%
710		8	1	87.5%	312	78	75.0%	8	3	62.5%	308	84	72.7%
711	82	8	0	100.0%	303	34	88.8%	8	5	37.5%	282	57	79.8%
712	112	8	5	37.5%	309	85	72.5%	8	6	25.0%	300	104	65.3%
713	36	7	0	100.0%	179	16	91.1%	5	4	20.0%	161	71	55.9%
714	55	8	7	12.5%	193	82	57.5%	7	7	0.0%	178	83	53.4%
715		8	1	87.5%	311	62	80.1%	6	4	33.3%	286	145	49.3%
716		8	6	25.0%	312	126	59.6%	7	5	28.6%	305	123	59.7%
717		8	2	75.0%	297	70	76.4%	5	3	40.0%	275	89	67.6%

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
718	90	8	6	25.0%	312	159	49.0%	8	6	25.0%	310	115	62.9%
719	83	8	5	37.5%	312	108	65.4%	7	4	42.9%	295	88	70.2%
720		3	0	100.0%	96	9	90.6%	3	0	100.0%	96	6	93.8%
723	20	3	0	100.0%	96	5	94.8%	3	2	33.3%	96	11	88.5%
724	31	3	1	66.7%	96	4	95.8%	2	1	50.0%	95	20	78.9%
727	14	3	0	100.0%	96	7	92.7%	3	1	66.7%	96	15	84.4%
728		3	1	66.7%	96	7	92.7%	3	1	66.7%	96	18	81.3%
729	12	3	1	66.7%	95	16	83.2%	3	2	33.3%	94	23	75.5%
732	17	3	2	33.3%	94	17	81.9%	3	2	33.3%	92	19	79.3%
733	34	3	0	100.0%	96	14	85.4%	3	2	33.3%	91	31	65.9%
734	33	3	1	66.7%	96	15	84.4%	3	1	66.7%	95	22	76.8%
736	22	3	0	100.0%	72	7	90.3%	3	2	33.3%	70	11	84.3%
737		3	0	100.0%	72	7	90.3%	3	1	66.7%	71	13	81.7%
738	Cncld	3	0	100.0%	96	15	84.4%	2	0	100.0%	90	13	85.6%
741		3	0	100.0%	96	13	86.5%	3	0	100.0%	96	18	81.3%
742		2	1	50.0%	94	12	87.2%	2	0	100.0%	92	7	92.4%
743	33	3	2	33.3%	96	19	80.2%	2	1	50.0%	94	11	88.3%
744		3	0	100.0%	96	15	84.4%	3	0	100.0%	96	32	66.7%
745		3	0	100.0%	96	10	89.6%	3	0	100.0%	95	14	85.3%
746		3	1	66.7%	96	9	90.6%	3	1	66.7%	95	14	85.3%
747	55	3	0	100.0%	96	15	84.4%	3	1	66.7%	96	22	77.1%
748		3	0	100.0%	95	13	86.3%	3	0	100.0%	95	13	86.3%
749		3	0	100.0%	93	14	84.9%	3	1	66.7%	84	11	86.9%
751	Cncld	3	0	100.0%	95	16	83.2%	2	0	100.0%	91	11	87.9%
757	27	8	0	100.0%	97	5	94.8%	8	1	87.5%	96	9	90.6%
761	28	8	1	87.5%	308	13	95.8%	8	1	87.5%	305	42	86.2%
765		8	0	100.0%	308	25	91.9%	8	1	87.5%	308	43	86.0%
769		8	0	100.0%	308	27	91.2%	8	1	87.5%	302	58	80.8%
770	39	8	1	87.5%	308	23	92.5%	8	5	37.5%	306	94	69.3%
774		8	0	100.0%	308	16	94.8%	8	3	62.5%	307	72	76.5%
777		8	0	100.0%	193	12	93.8%	8	4	50.0%	192	46	76.0%
782	37	8	7	12.5%	193	89	53.9%	8	4	50.0%	188	29	84.6%
785		8	1	87.5%	308	23	92.5%	8	2	75.0%	308	55	82.1%
786	58	8	2	75.0%	97	21	78.4%	7	4	42.9%	93	51	45.2%
790		8	0	100.0%	308	28	90.9%	8	1	87.5%	305	47	84.6%
794	17	8	2	75.0%	308	35	88.6%	8	2	75.0%	304	68	77.6%
821		8	0	100.0%	306	6	98.0%	8	7	12.5%	306	128	58.2%
822	18	8	0	100.0%	308	16	94.8%	8	8	0.0%	306	150	51.0%
1333		8	1	87.5%	308	33	89.3%	8	1	87.5%	305	100	67.2%
1340		8	1	87.5%	307	7	97.7%	8	1	87.5%	307	52	83.1%
1689		7	1	85.7%	102	6	94.1%	7	1	85.7%	101	12	88.1%
2207	20	2	0	100.0%	25	5	80.0%	2	1	50.0%	25	6	76.0%

Amtrak On Time Performance

Trains Arriving Through: 8/8/2026

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2208		3	1	66.7%	14	4	71.4%	3	0	100.0%	14	3	78.6%
2211	62	2	0	100.0%	8	1	87.5%	2	1	50.0%	8	2	75.0%
2219		3	0	100.0%	14	3	78.6%	3	0	100.0%	14	4	71.4%
2224		3	0	100.0%	29	5	82.8%	3	0	100.0%	29	4	86.2%
2250		2	1	50.0%	106	12	88.7%	2	0	100.0%	105	35	66.7%
2252		3	0	100.0%	109	9	91.7%	3	0	100.0%	107	32	70.1%
2254		3	0	100.0%	44	3	93.2%	3	1	66.7%	44	13	70.5%
2255		3	0	100.0%	111	11	90.1%	3	1	66.7%	110	51	53.6%
2258	40	3	0	100.0%	47	9	80.9%	3	2	33.3%	46	21	54.3%
2259		3	0	100.0%	67	24	64.2%	3	0	100.0%	66	30	54.5%
2260	96	3	0	100.0%	13	2	84.6%	3	2	33.3%	13	10	23.1%
2262	55	2	1	50.0%	23	5	78.3%	2	2	0.0%	23	9	60.9%
2265		3	1	66.7%	48	5	89.6%	3	0	100.0%	47	27	42.6%
2267	377	3	0	100.0%	11	3	72.7%	3	2	33.3%	10	7	30.0%
2271		3	0	100.0%	94	11	88.3%	3	0	100.0%	93	46	50.5%
2293		3	2	33.3%	12	3	75.0%	3	0	100.0%	12	3	75.0%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2207	WAS	20	DCS	12	DCS	8	WIL-XPV	AM	T.O.L, Control Point, ., TOL ON 3TRK PERRY TO GRACE
2211	WAS	62	ENG	62	ENG	62	NWK-MET	AM	Undesired emergency application, 2138, PARKING BRAKE ALARM AT MP17.7
2258	BOS	40	ENG	32	ENG	32	NYP-XSH	AM	Unrecoverable penalty (PCS), 2124 NG NP, STOPPED AT MP6.8 WITH MULTIPLE FAULTS ON PC2124
2260	BOS	96	MTI	88	MTI	45	NYP-XSH	AM	Disabled train ahead, Other, XGG-XPB, HELD AT LEGGETT A/C DISABLED AM2267EQ XING AHEAD NO.2 TRK DUE TO NO.1 TRK OOS
2262	BOS	55	CAR	32	CAR	32	BAL-BAL	AM	Heat / AC, 6 cars, had 6 hot cars, mechanical was able to correct problem
2267	WAS	377	ENG	352	ENG	239	XSH-NYP	AM	Other electrical failure, 2027 LH LP, PHASE GAP AT MANOR WITH NO HEP
87	NFK	75	CAR	46	CAR	46	WAS-WAS	AM	Air / Brake / Wheel, 81513 AX AN, split in brake hose replacement required
88	BOS	21	PTI	12	PTI	7	XHM-TRE	AM	Follow, AM666, Other, XHM-TRE, FOLLOWED AM666
99	NPN	19	PTI	26	SMW	15	XSH-NYP	AM	Scheduled in track usage program, Other, XM9-XM9, HELD FOR AM162 A/C NO.1 TRK OOS MANOR TO LEGGETT
101	WAS	37	UTL	33	UTL	33	NWK-NWK	AM	Commercial power outage, Other, XEO-XUN, HELD A/C FIBER OPTIC CABLE LAYING ACROSS CATENARY
103	WAS	104	ITI	107	ITI	107	NYP-NYP	AM	Service, turn, or wye train, 144, LATE TURN OFF AM144
106	NYP	58	ITI	65	ITI	65	WAS-WAS	AM	Service, turn, or wye train, 103, TRAIN 103 ARRIVED AFTER DEP TIME (2:05PM)
107	WAS	52	ITI	36	ITI	36	NYP-NYP	AM	Service, turn, or wye train, 106, LATE TURN OFF AM106
126	NYP	107	ENG	77	ENG	70	BAL-BAL	AM	HEP, 606 EX ES, met by mechanical a/c intermittent HEP loss, mechanical unable to correct problem, will be met in Philadelphia
140	NHV	20	MTI	19	MTI	19	NYP-XPB	AM	Disabled train ahead, Other, XGG-XPB, AM2258 DISABLED AT MP6.8
144	NYP	114	CTC	131	CTC	109	PHL-PHL	AM	CETC/PSCC system failure, Control Point, ., failed AMTEC cold start
147	RNK	67	CON	26	CON	26	NHV-NHV	MN	Hold for bus with passengers from train

Amtrak Endpoint OTP Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
153	WAS	34	UTL	34	UTL	34	NYP-NYP	AM	Commercial power outage, Other, NYP-NYP, HELD A/C FIBER OPTIC CABLE LAYING ACROSS CATENARY AT MP13.1	
156	NYP	17	DSR	11	PTI	11	BAL-XPV	AM	Cross over or go around, 2259, Milepost, 26.8, 38.4, opr 2 trk for 2259 ahead on 3 trk then followed	
161	WAS	50	OTH	18	CON	12	NHV-NHV	MN	Hold for thruway bus	
162	BOS	44	CTI	26	CAR	13	NHV-NHV	AM	Electrical failure, 43394 AX MF, MECHANICAL WAS CALLED TO FIX REFRIDGERATION	
163	WAS	62	DCS	30	DCS	25	XPV-BAL	AM	T.O.L, Milepost, 90.9, ., TOL left after local freight entered Baltimore Steel, needed 241	
165	WAS	34	CTI	36	CTI	19	BRP-STM	MN	Follow mnrr, Other, brp-stm	
168	BOS	49	MTI	49	MTI	49	NYP-XSH	AM	Disabled train ahead, Other, XGG-XPB, HELD AT LEGGETT A/C DISABLED AM2267EQ XING AHEAD NO.2 TRK DUE TO NO.1 TRK OOS	
194	BOS	29	SMW	29	SMW	21	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK	
195	WAS	39	CTI	11	OTH	7	PHL-WIL	AM	Lost time - N.A.R., PRT	
611	HAR	13	OTH	9	DCS	8	PAO-EXT	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), ., Control Point, ., signal only displays stop and proceed at Glen	
661	HAR	16	OTH	7	DCS	5	PAO-EXT	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), ., Control Point, ., signal only displays stop and proceed at Glen	
664	NYP	15	OTH	13	SMW	13	NWK-NYP	AM	Scheduled in track usage program, Other, NWK-NYP, CONGESTION A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK	
19	NOL	48	FTI	140	FTI	61	ATL-ATN	NS	Cross Traffic csx ???, Control Point, howell tower	
690	BON	92	DMW	79	DMW	79	HHL-WOB	MT	Hold for defect repair Other, mbta Andover station bw 22.7	
691	BRK	74	ITI	49	ITI	49	BON-BON	MT	Service, turn, or wye train 690, Late arrival, job briefing. Boarded and left	
693	BRK	74	FTI	47	FTI	35	POR-POR	CS	Held at Portland due to freight train blowing a air hose lo70, Control Point, Congress, consist	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
694	BON	21	DCS	14	DCS	14	WOB-BON	MT	Issue with automatic road crossing protection Other, Canal St BH 5.3
695	BRK	36	DCS	34	DCS	14	POR-FRE	CS	Restrictive signal(s) from unknown cause Restricted proceed , Other, auto 2 to Royal
696	BON	61	ITI	44	ITI	44	BRK-BRK	CS	Service, turn, or wye train 691
697	BRK	65	DCS	30	ITI	30	BON-BON	MT	Service, turn, or wye train 696
698	BON	20	ENG	21	ENG	21	BRK-BRK	CS	IFD SCREEN KEEPS REBOOTING 108
63	TWO	32	DSR	12	DSR	12	ROC-BUF	CS	Per bulletin Control Point, 380, 25, 2
64	NYP	34	PTI	37	PTI	26	ALB-HUD	AM	Meet Single tracking had to wait for train 237 to clear, 237, Control Point, 142
68	NYP	35	WTR	48	WTR	48	SLQ-RSP	CN	Heat order Milepost, 42, 2
69	MTR	22	WTR	50	WTR	50	XLQ-SLQ	CN	Heat order Other, rsp sub
233	ALB	19	CTI	12	CTI	9	CRT-POU	MN	Follow mnrr, 8819, Milepost, 61, 72
235	ALB	27	WTR	14	ITI	11	NYP-NYP	AM	Service, turn, or wye train, 238, LATE TURN OFF AM238
290	NYP	24	CTI	20	CTI	15	POU-CRT	MN	Follow metro, 8844, Milepost, 62, 39
291	BTN	49	PTI	40	PTI	40	RHI-HUD	AM	Meet 48 244, Control Point, 114
49	CHI	127	DBS	148	DBS	148	XHF-UCA	CS	Downed trees between 176.2 & 177.5. Hold for removal. Other, mp 177.0
448	BOS	330	WTR	216	WTR	208	PIT-SPG	CS	Trees down Control Point, 105
42	NYP	26	SMW	24	SMW	20	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK
43	PGH	68	FTI	45	FTI	36	GNB-PGH	NS	Follow NS 11V, Milepost, 346, 353
78	RGH	16	DSR	20	DSR	8	KAN-SAL	NS	Per dispatcher (radio/phone) Flash flood, Milepost, 356, 347, 40, 1,2
89	SAV	60	ENG	116	ENG	63	XPV-BAL	AM	Other electrical failure, 661 EX ES, STOPPED AT ABERDEEN AND MP 84 WITH HOT JOURNAL ISSUES.
90	NYP	78	FTI	70	FTI	54	SSM-WLN	CS	CSX had a trespasser strike All stop waiting, CSXT Freight, Milepost w/Letters, A 147.0, A 147.0
98	NYP	77	DCS	73	DCS	56	XP8-KIS	FR	PTC- Unplanned PTC system /server outage Red fence onto cfrc property cut out PTC to KIS, Milepost, 814, 814

Amtrak Endpoint OTP Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
40	CHI	174	FTI	69	ITI	60	MIA-MIA	FL	Service, turn, or wye train 4103, Inbound train arrived almost 12 hours late and needed to be serviced
25	NOL	53	FTI	72	FTI	31	BAS-XNO	CS	Meet y101, Control Point, paris rd
5	EMY	134	WTR	136	WTR	48	GSC-XAC	UP	Heat order Milepost, 361.00, 423.00
6	CHI	114	DSR	134	SYS	52	WNN-WNN	UP	Re-crew / job briefing Inbound RNO crew held train at WNN til outbound SLC crew arrived. SLC crew not rested til 19:58, Other, WNN Depot
723	SJC	20	RTE	14	RTE	14	GAC-SCC	UP	Run via siding or slower track due to N.A.R. Control Point, Coast
724	SAC	31	PTI	43	PTI	26	FMT-HAY	UP	Meet AMT 11 & AMT 527, Control Point, FO030
727	SJC	14	DCS	21	DCS	21	SCC-SJC	UP	Flag Cp Alameda MT 2 to Depot track 5 at SJC Control Point, Cp alameda
729	SJC	12	DSR	10	DSR	10	HAY-FMT	UP	Per bulletin Milepost, 22.3, 22.38, 15, m, Milepost, 23.09, 23.90, 15, m, Milepost, 23.90, 224.0, 15, m
732	SAC	17	TEN	30	TEN	30	OKJ-OKJ	UP	Set out defective locomotive 2104 swapped for 2009. Late flagging for commissary load, clean and cab car daily., CDTX 2104
733	SJC	34	PTI	25	PTI	19	GAC-SCC	UP	Meet Shuffle at Expressway, 734, Control Point, CO044
734	SAC	33	DCS	24	DCS	15	SJC-SJC	UP	Flag Cp Alameda, depot track 5 to MT 2. Disp gave authority to pass signal displaying stop indication. But did not send authority to PTC. And gave new flagging instructions. Ran PTC cut out from SJC to SCC Control Point, Cp Alameda
736	SAC	22	PTI	22	PTI	22	DAV-SAC	UP	Meet 5, Milepost, 88, 88
738	SAC	Trn Cancelled	DSR	11	DSR	11	FMT-HAY	UP	Per bulletin Milepost, 24.0, 23.09, 15, Main
743	OKJ	33	SYS	43	SYS	43	SAC-SAC	UP	Other late crew Engineer, Control Point, SAC
747	SJC	55	POL	31	POL	31	EMY-EMY	UP	Removal of passenger by police
751	OKJ	Trn Cancelled	TEN	61	TEN	61	DAV-DAV	UP	Set out defective locomotive Couple to failed train 738(08) at Davis -, C2123
503	EUG	28	DSR	14	FTI	8	ORC-SLM	UP	Meet UP 5878, Siding, Labbish, Z
505	VAN	16	DCS	13	DCS	13	TAC-XNI	ST	Restrictive signal(s) from unknown cause Restricting , Milepost, 18.8, 21

Amtrak Endpoint OTP Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
508	PDX	24	PTI	15	PTI	13	EUG-ALY	UP	Meet Amtrak 11, Siding, Alford
516	VAC	47	FTI	33	FTI	33	EVR-STW	BN	Meet Bridge, 37, BNSF 3976
517	VAN	50	DCS	27	DCS	21	TAC-XNI	ST	Signal 20.7 was dark Control Point, 20.7
518	VAC	45	OTH	27	OTH	27	VAN-VAN	BN	Waited for busses to arrive at VAN station to load passengers on.
59	NOL	43	DSR	67	FTI	24	NBN-MEM	CC	Follow un, Control Point, North Dyersburg, Siding, Curve
7	SEA	123	FTI	247	FTI	98	LWA-XEN	BN	Meet BNSF Officers Special, Siding, BERNE
8	CHI	44	FTI	154	FTI	84	GGW-WPT	BN	Meet BNSF 5952, BNSF 7995, BNSF 7351, BNSF 7401, Siding, WHATLEY, Siding, kintyre, Siding, Oswego
822	OKC	18	DSR	24	DSR	20	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, 1, Milepost, 350.7, 351.1, 50, 1, Milepost, 353.7, 354.1, 60, 1, Milepost, 354, 354.5, 70, 1, Milepost, 355.5, 355.9, 50, 1, Milepost, 361.5, 362.9, 60, 2, Milepost, 364.4, 364.8, 60, 2, Milepost, 371.4, 371.5, 50, m, Milepost, 374, 374.1, 60, m, Milepost, 379.
350	PNT	26	DSR	38	DSR	21	ROY-TRM	CC	Per bulletin Milepost, 13.9, 17.1, 10, 1
351	CHI	17	DSR	33	DSR	19	TRM-ROY	CC	Per bulletin Milepost, 17.1, 14.63, 10, 1
355	CHI	20	DSR	44	DSR	21	TRM-ROY	CC	Per bulletin Milepost, 17.1, 14.63, 10, MAIN ONE, Milepost, 16.3, 13.9, 10, MAIN ONE, Milepost, 12.9, 12.7, 25, MAIN ONE, Milepost, 11.5, 11, 25, MAIN ONE & TWO
566	SAN	17	DSR	10	CTI	10	OSD-SOL	SN	Meet COASTER, UNK, Control Point, PONTO
572	SAN	21	CTI	23	CTI	10	SNA-IRV	SC	Follow metrolink, 1662, Milepost, 176, 184
581	LAX	72	CTI	60	CTI	30	OSD-X98	SC	Meet Stop signal at Songs, Metrolink, 1664, Control Point, Songs
584	SAN	44	PTI	26	PTI	13	OSD-SOL	SN	Meet 591, Control Point, ponto
588	SAN	30	PTI	27	PTI	20	SNC-SNP	SC	Meet 591, Control Point, Serra
591	LAX	28	PTI	35	PTI	25	OSD-X98	SC	Meet 786, Control Point, songs
757	SLO	27	OTH	28	OTH	28	X3G-LPS	UP	Rocket Launch
761	GTA	28	DCS	48	DCS	45	OSD-X98	SN	PTC init. problems on Metrolink Control Point, Songs
770	SAN	39	CTI	25	CTI	16	SNC-SNP	SC	Meet Metrolink, 803, Control Point, Serra

Amtrak Endpoint OTP Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
782	SAN	37	PTI	56	PTI	30	SNC-SNP	SC	Meet SCRRA 1667, Control Point, CP SERRA
786	SAN	58	PTI	78	PTI	34	GUA-LPS	UP	Meet 765 / 14, Siding, tangair
794	SAN	17	CON	27	CON	27	LAX-LAX	SC	Hold for bus with passengers from train
703	SAC	61	ITI	62	ITI	62	BFD-BFD	BN	Service, turn, or wye train AMT 712
711	OKJ	82	POL	69	POL	67	FNO-FNO	BN	RR blocked by trespasser or vehicle strike by another train BNSF Bakersfield DS held AMTK 711 at FNO due to disabled freight train at MP 1007.
712	BFD	112	TCC	100	TCC	100	OKJ-OKJ	UP	Toilet C8312
713	OKJ	36	INJ	43	INJ	40	MOD-MOD	BN	Injured or sick passenger Passenger fell in restroom at TRK requested medical assistance
714	BFD	55	TCC	32	TCC	32	OKJ-OKJ	UP	Toilet C8312, CAB CAR RESTROOM REPAIR.
718	BFD	90	PTI	82	PTI	40	OKJ-OKJ	UP	Meet 542, 715, 716, 545, Control Point, north jack london
719	OKJ	83	TEN	77	TEN	77	BFD-BFD	BN	Ditch lights were not working on loco 2002. Drumac changed light bulbs. Still not working. Fortunately, loco 2107 was the trail unit, so we swapped out locos put the 2002 on the trail. C2107, C2002
3	LAX	226	ENG	225	ENG	225	TOP-NEW	BN	Air / Brake 167
21	SAS	No OS Rpt	CAR	262	CAR	259	CHI-CHI	AM	Toilet 31023
22	CHI	No OS Rpt	ENG	393	CON	214	SAS-SAS	UP	Hold for connecting train 2
307	STL	43	SYS	34	FTI	17	PON-BNL	UP	Meet UP8115, Other, BALLARD
382	CHI	35	FTI	21	DCS	18	QCY-MAC	BN	Power switch failure Control Point, east camp point
383	QCY	17	CTI	11	CTI	11	XUA-LAG	BN	Follow Metra on MT 2, followed one on MT 1, Metra, Control Point, Berwyn
393	CDL	18	FTI	19	PTI	10	CHM-MAT	CC	Meet 3 WAY MEET, 392, Siding, TUSCOLA
311	KCY	16	PTI	26	PTI	26	JEF-SED	UP	Meet Daily delay of on time 311 waiting for late 318, Amtk 318, Siding, Shell
316	STL	232	FTI	231	FTI	209	SED-JEF	UP	Disabled freight train between Sedalia and Jefferson City. Waited in siding at Dow for lite power move. Then at Shell for disabled train to pass. Siding, Dow, UP 7214

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/8/2026

26-FOI-00671 00000008701 "UNCLASSIFIED" 9/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
319	KCY	291	FTI	297	FTI	268	JEF-JEF	UP	Disabled coal train at Centertown. Took a lite engine out of Dresden to come pull the train out of the way. Coal train, Control Point, Centertown

Amtrak Initial Terminal Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/8/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	1	08/08	142	142	Late release from mechanical 1
NOL	58	08/08	5	5	Hold for train 1 to clear clara st. Amtk 199 defective train 1 shoved carrollton jct to sta 4, amtrak 1, Control Point, clara st
BON	691	08/08	49	49	Service, turn, or wye train 690, Late arrival, job briefing. Boarded and left
BON	697	08/08	36	30	Service, turn, or wye train 696
BON	697	08/08	36	6	Wheelchair Group of 20 with 2 wheelchairs and about 12 service dogs.
BON	1689	08/08	1		
BOS	87	08/08	8	8	Water, commissary, toilet/trash dumping, LATE COMMISSARY
BOS	195	08/08	4	4	HEP, 656 EX ES, 195 will be delayed departing Boston South Station on account of no HEP and low air
BOS	2293	08/08	14	14	Other electrical failure, 2129 NG NP, AM2293 e/2129 rpts trying to reconfigure pantographs, requesting HSR a/c pantographs will not stay up, RFE Mingione rpts HSR took no exceptions for AM2293
BRK	696	08/08	44	44	Service, turn, or wye train 691
BRK	698	08/08	21	21	IFD SCREEN KEEPS REBOOTING 108
HAR	674	08/08	1	1	Passenger and/or baggage
MTR	68	08/08	3	3	High passenger count High passenger count. Working alone. Short time due to setting out private cars and additional brake test prior to loading passengers
NFL	280	08/08	6	6	Push Pull set engineer had to check rear unit prior to departure 99
NHV	143	08/08	9	9	Waited for departure time as train was leaving off platform. Also had to wait for shuttle busses.
NHV	147	08/08	26	26	Hold for bus with passengers from train
NYP	43	08/08	14	14	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	69	08/08	10	10	Escalator malfunction, Other, NYP-NYP, BROKEN ESCALATOR
NYP	89	08/08	14	14	Passenger and/or baggage, HELD A/C PASSENGER LOST BAGGAGE
NYP	97	08/08	59	59	Set out defective car, 20815, LATE F/SSYD A/C CAR 20815 FULL REFRIGERATION FAILURE IN ENTIRE CAR
NYP	101	08/08	3	3	Door, 0000, DOOR LIGHT INDICATIONS
NYP	103	08/08	107	107	Service, turn, or wye train, 144, LATE TURN OFF AM144
NYP	107	08/08	36	36	Service, turn, or wye train, 106, LATE TURN OFF AM106
NYP	109	08/08	2	2	Passenger and/or baggage, TRAVEL
NYP	127	08/08	19	19	Undesired emergency application, 9640, LATE F/SSYD A/C LOSING POWER TWICE IN THE SUBS

Amtrak Initial Terminal Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/8/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	153	08/08	34	34	Commercial power outage, Other, NYP-NYP, HELD A/C FIBER OPTIC CABLE LAYING ACROSS CATENARY AT MP13.1
NYP	155	08/08	7	7	Passenger and/or baggage, LOADING
NYP	235	08/08	11	11	Service, turn, or wye train, 238, LATE TURN OFF AM238
NYP	283	08/08	2	2	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
PHL	144	08/08	131	109	CETC/PSCC system failure, Control Point, ., failed AMTEC cold start
PHL	144	08/08	131	22	CETC/PSCC system failure, Control Point, ., failed AMTEC cold start
PHL	150	08/08	15	15	Planned set out / pick out of locomotives, cars or section of train, LATE DEPARTURE OUT OF THE YARD
PHL	151	08/08	10	10	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	611	08/08	3	3	PTC - Stop Bypass Permission Required, Control Point, ., CC/9646
WAS	82	08/08	11	11	High passenger count, HIGH PAX COUNT (404 PAX)
WAS	106	08/08	65	65	Service, turn, or wye train, 103, TRAIN 103 ARRIVED AFTER DEP TIME (2:05PM)
WAS	142	08/08	2	2	Delay in Block, CNDR ALLOWED LATE PAX ON AT DEP TIME
WAS	162	08/08	3	3	Wheelchair
WAS	194	08/08	7	7	Routine inspections, CREW ALLOCATED TO OTHER ASSIGNMENTS AND MULTIPLE TRAINS IN STATION REQUIRING WORK.
CHI	48	08/08	10	10	Service, turn, or wye train 49
QCY	382	08/08	1	1	Passenger was slow to board
ARN	729	08/08	1		
BFD	703	08/08	62	62	Service, turn, or wye train AMT 712
BFD	719	08/08	77	77	Ditch lights were not working on loco 2002. Drumac changed light bulbs. Still not working. Fortunately, loco 2107 was the trail unit, so we swapped out locos put the 2002 on the trail. C2107, C2002
EMY	6	08/08	1		
EUG	508	08/08	6	6	Air / Brake Engineer was on phone with Mechanical troubleshooting brake issue on AMTK 72 appears there was sticking breaks due to bottled air, 72
GTA	782	08/08	9	9	Meet 14, Control Point, CO 358
OKJ	712	08/08	100	100	Toilet C8312
OKJ	714	08/08	32	32	Toilet C8312, CAB CAR RESTROOM REPAIR.

Amtrak Initial Terminal Details

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/8/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	716	08/08	12	12	PTC issues not showing AMTK 90218 on our consist had to log out then log in causing delay Contacted power desk to inform them that AMTK 90218 was not showing on our consist as well as calling CMS Operations regarding delay. AMTK90218
OKJ	718	08/08	9	9	Water, commissary, toilet/trash dumping
OKJ	732	08/08	30	30	Set out defective locomotive 2104 swapped for 2009. Late flagging for commissary load, clean and cab car daily., CDTX 2104
PDX	11	08/08	10		
PDX	503	08/08	22		
PDX	507	08/08	8		
SAC	743	08/08	43	43	Other late crew Engineer, Control Point, SAC
SAN	593	08/08	6	6	Meet Control Point, ash, bnsf 9029, auto
SAN	595	08/08	1	1	Service, turn, or wye train 584
SEA	8	08/08	6	6	Service, turn, or wye train 7
SJC	728	08/08	6	6	Restrictive signal(s) from unknown cause Signal was not cooperating. Track indication unknown., Red, Milepost, 46.85, 46.34
SJC	734	08/08	15	15	Flag Cp Alameda, depot track 5 to MT 2. Disp gave authority to pass signal displaying stop indication. But did not send authority to PTC. And gave new flagging instructions. Ran PTC cut out from SJC to SCC Control Point, Cp Alameda
SLO	794	08/08	3	1	Wait for station track Dispatcher held train in service spur to allow AMTK 11 to enter station first, AMTK 11, Control Point, CPCO249
SLO	794	08/08	3	1	Mobility Impaired PNR B39234 accidentally boarded coach and needed to use platform to enter business class
SLO	794	08/08	3	1	Unticketed or fare evading passenger Fare evader attempted to board train with luggage tag claiming it as a ticket., Milepost, 248.6, 248.6
VAN	506	08/08	2	2	High passenger count
VAN	518	08/08	27	27	Waited for busses to arrive at VAN station to load passengers on.

Eastern Region

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.8	99.0	94.8	166	2
CDOT	95.0	87.5	90.5	92.4	16	2
MARC	95.0	83.3	81.7	90.2	18	3
SEPTA	95.0	88.3	93.8	91.5	103	12
NJT-NED	95.0	66.3	91.8	88.6	178	60
NJT-SED	95.0	100.0	98.9	97.2	22	0

Operating Highlights

Train 126(08) - Baltimore, MD - Engine Failure

09AUG26: Train 126(08) was delayed at Baltimore Station/MP 95.5 on the Amtrak PW Line due to intermittent HEP losses. When the train stopped, HEP would drop out. The crew attempted to rectify without any available mechanical help at Baltimore, to no avail. The decision was made to release the train to continue northbound, as HEP came back up when the train was in motion.

Train	Delay	Comment
126(08)	1'10"	

Train 89(08) - North of Fayetteville, NC - Freight Train Interference

09AUG26: Train 89(08) was delayed on the CSX South End Subdivision at MP 207.3 due to meeting CSX Train M429-07.

Train	Delay	Comment
89(08)	36"	

Train 19(08) - Washington, DC - Engine Failure

09AUG26: Train 19(08) was delayed at Washington Union Terminal due to a brake issue which caused a dynamic brake fault. Mechanical personnel responded to the scene and assisted in clearing the fault.

Train	Delay	Comment
19(08)	1'16"	

Train 2267(08) - East of New York Penn Station - Miscellaneous Amtrak Responsible

08AUG26: 4:40pm Train 2267(08) with Power Car 2027 trailing, plus 5 coaches with Power Car 2027 trailing, carrying 492 passengers, stopped on the Amtrak Hellgate near Manor Interlocking/MP 18.2 due to the train losing power as it traversed the phase break between Metro North and Amtrak territories. The train lost all traction power and HEP. The outside temperature at the time was 87°.

An initial plan to transfer all passengers to Train 57(08) was scrapped due to the location of the train. The gap between the two trains was too wide to facilitate a safe transfer of the passengers from the disabled equipment onto Train 57(08).

Rescue Engine 573 was dispatched from Sunnyside Yard for rescue. Once on the scene of the disabled Acela 2267(08), E/573 coupled to the disabled set and towed it into New York Penn Station, where HSR personnel were able to liven the set back up.

After discovering a paperwork issue and experiencing a mechanical issue with the brakes on the original 2267(08) equipment; passengers were transferred to the 2293(08) equipment across the platform on station track 13. The 2293(08) equipment represented 2267(08) NYP-WAS.

Train	Delay	Comment
2267(08)	4'21"	
2267(08)	1'09"	Livening EQ/Removing Rescue Motor/Swapping Set
2267(08)	13"	Recrew at PHL

Train 448(07) - West of Springfield, MA - Tree Obstructing Right of Way

08AUG26: Train 448(07) was delayed on the CSX Berkshire Subdivision at MP 105.2 due to a large tree obstructing the route. The crew attempted to removed the tree to no avail. CSX dispatched MW personnel to the scene for removal.

Due to the lateness of Train 448(07)'s operation, it was necessary to conduct the daily inspections on the equipment at Springfield.

Train	Delay	Comment
448(07)	2'22"	
448(07)	1'19"	Daily Inspections at SPG

Train 98(08) North of Kissimmee, FL - Signal

08AUG26: Train 98(08) operating with locomotives 10-339, 12 cars and 239 customers was delayed operating on the CFRC Orlando subdivision due to CFRC PTC systemwide failure with multiple red fences present while operating on clear signals. CFRC acknowledged system failure but would not authorize train 98(08) to proceed with PTC cut-out. Once off CFRC property train 98(08) was able to operate with functional PTC.

Train	Delay	Comment
98(08)	1'10"	

Train 68(08) South of St-Lambert, QC - Weather

08AUG26: Train 68(08) was delayed south of St. Lambert Station due to CN heat orders on the Rouses Point subdivision between MP42 and MP2.

Train	Delay	Comment
69(08)	50"	
68(08)	48"	

Train 97(07) North of Orlando, FL - Passenger Train Interference

08AUG26: Train 97(07) ~~26-FBI-00671~~ ~~00000008701~~ files "UNCLASSIFIED" ~~8/2/2026~~ at MP 790 on the CFRC Orlando subdivision meeting Amtrak 98(08). After train 98(08) passed train 97(07) was able to proceed and occupy Orlando Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(07)	30"	

Train 693(08) Portland, ME - Freight Train Interference

08AUG26: Train 693(08) operating with locomotive 108, 5 cars and 80 customers was delayed holding at Portland station due to freight train interference resulting from CSX L070 becoming disabled on the CSX Portland subdivision single track main line between CPF196 and CPF194. Once the train was able to restore their and begin movement again train 693(08) departed Portland Station and met the freight at CPF196.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
693(08)	60"	

Train 90(08) South of Wilson, NC - Freight Train Interference

08AUG26: Train 90(08) operating with locomotive 15, 7 cars and 192 customers was delayed south of Wilson at MP 147 on the CSX South End subdivision due to CSX freight L225-08 striking a vehicle at MP143.9. Once the freight incident was released and the train was moved to clear an open route train 90(08) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
90(08)	54"	

Train 97(08) New York, NY - Initial Terminal Delay - Car Failure

08AUG26: train 97(08) operating with locomotive 635, 11 cars and 199 customers was delayed at the initial terminal of New York as a result of the shopping of lounge car 28001 requiring replacement with car 28011. After the train was made up and all inspections and documentation were completed the equipment was moved to the station for customer boarding.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(08)	59"	

Train 40(07) Rocky Mount, NC - Fueling

08AUG26: Train 40(07) operating with locomotives 381-330, 10 cars and 201 customers was delayed 1 mile south of Rock Mount Station due to needing CSX to provide fueling services as a result of the Savannah fuel vendor being unavailable to provide fueling service as scheduled and contracted. After fueling was completed train 40(07) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(07)	48"	

NYP Line - West of Newark Liberty Airport, NJ - Utility Company Failure

08AUG26: Multiple trains were delayed on the NYP line west of Newark Liberty Airport after a reported utility company fiber optic cable was laying across the catenary system. An AC power plate was in place with a hold on all 4 tracks between Lane and Union interlockings. Train 101(08) was held at Newark, 106(08) at Metropark and 153(08) at New York. ET personnel responded and were able to remove the cable allowing service to resume.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
160(08)	23"	
101(08)	33"	
153(08)	34"	

Train 80(08) South of Petersburg, VA - Trespasser Incident

08AUG26: Train 80(08) operating with locomotive 346, 7 cars and 269 customers onboard was delayed 30 miles south of Petersburg at MP 51.6 on the CSX North End subdivision after striking an occupied ATV at private road crossing DOTX 623737T in Jarratt, VA in Greensville county. This trespasser strike did not result in a fatality. There were no reported injuries to crew or customers onboard and no damage to equipment or infrastructure. The crew did not request relief at the scene. Local authorities responded and took 1 injured occupant to an area hospital. After local authorities completed their investigation train 80(08) was released and able to proceed.

National Response Center Number: 1470152

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
80(08)	57"	

Train 2211(08) Newark, NJ - Engine Failure

08AUG26: Next Gen Acela train 2211(08) was delayed 8 miles west of Newark at MP 17 on the Amtrak NYP Line with a parking brake alarm on lead PC 2137. The crew received track protection to allow inspection of the equipment with the onboard high-speed tech. Upon inspection the crew identified a separated hose and were able to reattach. The crew further identified an electronic fault that would not clear requiring the trainset to de-prepare and re-prepare. After completing the reset all faults were cleared, and the crew was able to complete a good Class II brake test and resume operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2211(08)	1'02"	

Train 690(08) Haverhill, MA - M of W Work

08AUG26: Train 690(08) operating with locomotive 96, 4 cars, NPCU 90214 and 88 customers onboard was delayed 10 miles South of Haverhill Station at MP 103 on the CSX Middlesex subdivision due to a track defect resulting from a pull apart. CSX personnel responded and were able to walk over train 690(08) at the location allowing it to proceed.

As a result of the late operation of train 690(08) the subsequent turns to trains 691(08) and 696(08) resulted in initial terminal delays.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
696(08)	44"	Initial terminal delay
690(08)	1'19"	
691(08)	49"	Initial terminal delay
697(08)	36"	

Train 144(08) Philadelphia, PA - Initial Terminal Delay - CETC System

08AUG26: Train 144(08) operating with locomotive 660-644, 8 cars and 198 customers was delayed at the initial terminal of Philadelphia due to the late arrival of equipment off train 179(07) resulting from the CTEC Amtec outage affecting operations on the PW and the PH Lines. The equipment was inspected and tested in the station awaiting movement to the yard to have the facilities dumped and watered prior to release. Once released, the yard crew positioned the equipment in the station for passenger boarding.

As a result of the late operation of train 144(08) the subsequent equipment turns to trains 103(08) at New York and 106(08) at Washington and 107(08) at New York resulted in initial terminal delays.

Train	Delay	Comment
144(08)	2'11"	Initial terminal delay
103(08)	1'47"	Initial terminal delay
106(08)	1'05"	Initial terminal delay
107(08)	36"	Initial terminal delay

Train 43(08) New York, NY - Initial Terminal Delay - Servicing

08AUG26: train 43(08) operating with locomotive 650-109, 7 cars and 256 customers was delayed departing the initial terminal of New York as a result of a late release of equipment from the yard.

Train	Delay	Comment
43(08)	14"	Initial terminal delay

CSX Heat Orders - Weather

08AUG26: CSX has imposed heat orders effective between 1pm and 7pm for the following subdivisions: Baltimore Terminal, Capital, Cumberland, Metropolitan, Old Main Line, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Lakeland, North End, Sanford, and Tampa Terminal.

Train	Delay	Comment
53(08)	30"	
128(08)	08"	
40(08)	60"	
90(08)	15"	
79(08)	53"	
99(08)	12"	
124(08)	23"	
52(08)	11"	
89(08)	49"	
158(08)	31"	
80(08)	28"	
155(08)	21"	
41(07)	27"	
40(07)	37"	
97(07)	23"	

Multiple Trains - PW Line Sinkhole

08AUG26: 12:47am-et: Maintenance crew identified a sinkhole on the PW Line north of Baltimore at MP 89.3 on the No. 1 track. A hold was placed on the No.1 track Point Interlocking to River Interlocking to allow IMCS personnel access to make repairs. Initial efforts were unsuccessful in completing repairs with additional resources needed. Additional personnel from Track and B&B reported at 7am-et and the track was taken out-of-service for additional work to be performed.

11:42am-et: Track No.1 was returned to service after repairs were completed with a speed restriction of 30 MPH.

As a result of the No.1 track being out of service, Amtrak trains operated over a single-track between Gunpow Interlocking and River Interlocking for a 10-mile stretch. The single-track operation resulted in routing delays due to passenger train meets at the location.

Train	Delay	Comment
101 (08)	04"	
2208 (08)	01"	
79 (08)	09"	
2252 (08)	02"	
160 (08)	05"	

Train 66(07) Philadelphia, PA - Signal

08AUG26: Following an unsuccessful update of the CETC system, a system-wide outage occurred on the PH and PW lines, as well as on portions of the NYP Line between Girard and Holmes. To restore operations, the system was reverted to its previous configuration. As a result of the outage, Trains 66(07) and 65(07) were held in Philadelphia until the system issue was resolved. To support continued operations and ensure reliable control of the affected territory, maintainers were assigned to provide round-the-clock coverage at FRAZER and GLEN interlockings, where they operated the interlockings under local control.

Train	Delay	Comment
66 (07)	1'02"	
65 (07)	08"	

Maintenance of Way Highlights

Train 147(08) New Haven, CT - Initial terminal Delay - Scheduled M/W Work

08AUG26: Train 147(08) operating with locomotive 612, 8 cars and 253 customers was delayed at the initial terminal of New Haven as a result of holding for connecting bus customers due to the scheduled trackwork.

Train	Delay	Comment
147(08)	26"	

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00671a 00000008701 UNCLASSIFIED 19/2/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Train 4(08) West of Needles, CA - Freight Train Interference

09AUG26: Train 4(08) was delayed west of Needles, CA, on the BNSF Needles Subdivision due to freight traffic congestion. The train followed various BNSF freight movements between Fenner (MP 622.6) and Goffs (MP 609.2), resulting in reduced operating speeds through the territory.

Train	Delay	Comment
4(08)	33"	

Train 58(08) South of Newbern-Dyersburg, TN - Freight Train Interference

08AUG26: Train 58(08), with 103 customers onboard, was delayed at Rialto siding/MP347.6, 42 miles south of Newbern-Dyersburg, TN/MP305.6, on the CN Fulton subdivision meeting grain train CN2896. The CN2896 went into emergency while passing 58(08), adding to the delay. Once the freight recovered their air pressure and cleared the route, train 58(08) continued north.

Train	Delay	Comment
58(08)	43"	

Train 747(08) Emeryville, CA - Police Related

08AUG26: Train 747(08), carrying 62 customers onboard, was delayed at Emeryville, CA, Station (MP 4.3) on the Union Pacific Martinez Subdivision while awaiting a police response to remove an unruly customer. Once law enforcement addressed the situation and the customer was removed from the train, Train 747(08) resumed its scheduled operation.

Train	Delay	Comment
747(08)	31"	

Train 4(07) East of Trinidad, CO - Thermal Misalignment

08AUG26: Train 4(07), carrying 211 customers onboard, was delayed holding at Raton, NM, after BNSF reported a thermal misalignment east of Trinidad, CO, at MP 619.4 on the BNSF Raton Subdivision at approximately 4:40 PM MT. Initial reports indicated Maintenance of Way personnel would require 3 to 4 hours to arrive on scene, followed by approximately 2 hours of repair work. Service recovery measures were implemented onboard, with coach passengers provided pizza, water, juice, and soda, while sleeping car customers were served dinner in the dining car. An initial recrew plan was also developed utilizing a crew from Albuquerque, NM. BNSF subsequently provided an estimated track reopening time of 9:00 PM MT. After the pizza delivery was completed, Train 4(07) departed Raton and proceeded eastward. The train was briefly delayed east of Trinidad near MP 627.9 before receiving track warrants to La Junta, CO, and continuing its trip.

WBS#: B.TR.100150.7013

Train	Delay	Comment
4(07)	3'08"	

Train 782(08) East of San Juan Capistrano, CA - Commuter Train Interference

08AUG26: Train 782(08), carrying 1000 customers onboard, was delayed approximately 2 miles east of San Juan Capistrano, CA, while holding at CP Serra (MP 199.5) on the Metrolink Orange Subdivision to meet Metrolink Train 1667.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
782(08)	30"	

Train 738(08) Davis, CA - Third Party Contractor Engine Failure

08AUG26: Train 738(08), carrying 69 customers onboard and operating with CC/C6961, five cars, and locomotive C2123, was delayed at Davis, CA, due to a locomotive failure caused by low hydrostatic oil. The locomotive shut down, resulting in the loss of head-end power. Weather conditions at the time were reported as approximately 89°F and sunny. Local management and mechanical personnel responded to the scene to assess the equipment and develop a recovery plan. To minimize customer impact, all customers were accommodated onto Train 742(08) upon its arrival at Davis. Train 742(08) subsequently continued to Sacramento and was utilized for turn into Train 751(08).

During troubleshooting efforts, mechanical personnel discovered a broken oil line, preventing the equipment from operating under its own power. As a result, Train 751(08) was assigned to couple to the disabled equipment at Davis and double draft the consist west to the Oakland Mechanical Facility for repair, with train terminating in Emeryville, CA. Customers traveling between Emeryville and Oakland Jack London Square were accommodated by bus route 6653(08).

Once the 751(08) equipment was disconnected from 738(08) in the yard, it operated deadhead back to Sacramento to be in place for morning service train 727(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
738(08)	Term DAV	49" for customers
751(08)	1'01"	Term EMY

Train 790(08) North of Ventura, CA - Passenger Train Interference

08AUG26: Train 790(08), carrying 366 customers onboard, was delayed approximately 8 miles north of Ventura, CA, while holding at South Seacliff Siding (MP 386.2) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Train 777(08).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
790(08)	44"	

Train 719(08) Bakersfield, CA - Third Party Contractor Engine Failure

08AUG26: Train 719(08), operating with locomotives E/C2002 and E/C2001 and six cars, was delayed departing Bakersfield, CA, after the lead locomotive, E/C2002, was reported with inoperative ditch lights. Technicians responded and replaced the bulbs; however, the issue could not be resolved. A decision was made to flat-switch the locomotives and place E/C2107 in the lead position. Once the equipment movements were completed, Train 719(08) departed with 95 customers onboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(08)	1'17"	

Train 25(08) North of New Orleans, LA - Freight Train Interference

08AUG26: Train 25(08), with 116 customers onboard, was delayed at Paris Road/MP796.0, 15.5 miles north of New Orleans, LA/MP0.0 on the CSX N.O.&M. subdivision meeting freight Y101. Once the freight was clear of the route, train 25(08) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(08)	31"	

Train 786(08) South of Camarillo, CA - Passenger Train Interference

08AUG26: Train 786(08), carrying 255 customers onboard, was delayed approximately 1 mile south of Camarillo, CA, while holding at Camarillo Siding (MP 414.2) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Train 777(08).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(08)	43"	

Train 6(08) West of Winnemucca, NV - Heat Orders

08AUG26: Train 6(08), carrying 132 customers onboard, was delayed west of Winnemucca, NV, while operating on the Union Pacific Nevada Subdivision under heat-order restrictions. The train operated at reduced speeds between Vista (MP 249.4) and Winnemucca (MP 417.2) in accordance with temporary operating restrictions implemented due to high rail temperatures.

Train was also delayed east of Winnemucca, NV for additional heat orders in effect on the Elko Subdivision from the depot to Whirlwind (MP 612.1).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(08)	46"	XMS-WNN
6(08)	35"	WNN-XW6

Train 319(08) West of Jefferson City, MO - Freight Train Interference

08AUG26: Train 319(08), with 88 customers onboard, held at Jefferson City, MO/MP125.5 on the UP Jefferson City subdivision meeting UP8161 that was disabled due to engine failure at around mile post 152.0. UP brought a freight engine from Dresden/MP195.7 to move the equipment into the clear. Once the route was open, train 319(08) departed Jefferson City, MO, met Amtrak train 316(08) at Centertown/MP141.9, and continued west.

Train 316(08) was also delayed at Shell siding/MP151.6 holding for an open route.

Out of an abundance of caution, two buses were secured for train 319(08) operating between Jefferson City, MO and Kansas City, MO. For train 316(08), one bus was secured operating between Shell siding and St Louis, MO. The UP freight cleared the route before the buses arrived and the buses shadowed their trains to the end points.

WBS#: B.TR.100150.7014

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(08)	3'29"	
319(08)	4'28"	

Train 581(08) East of San Clemente Pier, CA - Commuter Train Interference

08AUG26: Train 581(08) was delayed operating west on the NCTD San Diego Subdivision due to Metrolink train traffic. After following Metrolink 1858, the train was held at Oceanside Station when both trains encountered a stop signal ahead at Shell (MP 225.98). Train 581(08) subsequently continued following Metrolink 1858 to CP SONGS (MP 209.6), where it was held while Metrolink 1858 proceeded and an eastbound meet was conducted with Metrolink 1664. Once the meet was completed, Train 581(08) continued westward.

Train	Delay	Comment
581(08)	17"	hold OSD
581(08)	30"	meet ML 1664
581(08)	13"	follow 1858 to Songs

Train 713(08) Turlock-Denair, CA - Injured or Sick Passenger or Employee

08AUG26: Train 713(08) was delayed starting at Turlock-Denair, CA on the BNSF Stockton Subdivision due to an elderly customer on board falling in the restroom. The crew advanced to Modesto, CA where EMS met the train to evaluate the customer. Once EMS arrived and evaluated the customer, they remained on board and Train 713(08) departed.

Train	Delay	Comment
713(08)	03"	TRK
713(08)	40"	MOD

Train 11(07) San Jose, CA - Signal Issues

08AUG26: Train 11(07) was delayed departing San Jose, CA due to signal issues with Caltrain. The crew held while signal maintainers responded and flagged through affected area from San Jose/ MP 47.6 to Bird/ MP 47.8.

Train 734(07) was also delayed departing San Jose due to signal issues. Once through crew received permission from the dispatcher, they flagged from San Jose to Alameda/MP 47.4.

Train	Delay	Comment
11(07)	17"	
734(08)	27"	

Train 732(08) Oakland, CA - Third Party Contractor Engine Failure

08AUG26: Train 732(08), CC/C8311-4 cars-E/C2009, was delayed departing Oakland, CA due to a late release from mechanical. Locomotive E/C2104 was having mechanical issues and needed to be swapped for E/C2009. Due to the late change in equipment, mechanical was delayed in doing the daily servicing. Once mechanical finished servicing the equipment, it was released to the crew to their tests and departed the maintenance facility. Once the equipment was brought to the station and boarded, Train 732(08) departed Oakland.

Train	Delay	Comment
732(08)	30"	

Train 786(08) North of Lompoc-Surf, CA - Passenger Train Interference

08AUG26: Train 786(08), carrying 73 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station while holding at Tangair Siding (MP 294.6) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(08) and 14(08).

Train	Delay	Comment
-------	-------	---------

Train 743(08) Sacramento, CA - Crew Issue

08AUG26: Train 743(08) was delayed in its departure from Sacramento, CA, while awaiting the arrival of an engineer. Once the engineer arrived and boarded the train, Train 743(08) departed with 51 customers onboard and continued its scheduled operation.

Train	Delay	Comment
743(08)	43"	

Train 8/28(07) East of West Glacier, MT - Freight Train Interference

08AUG26: Train 8/28(07) was held 23 miles east of West Glacier, MT (MP1196.2) on the BNSF Hi Line Subdivision to meet BNSF 7048, BNSF 7266, and BNSF 5045 at Pinnacle (MP1173.2). Additional delay was incurred at Java West (MP1166.2) while meeting BNSF 7700.

Train	Delay	Comment
8/28(07)	39"	Pinnacle
8/28(07)	11"	Java West

Train 19(07) North of Meridian, MS - Freight Train Interference

08AUG26: Train 19(07), with 62 customers, onboard, was delayed between Breyer/MP292.7 and Meridian, MS/MP295.0 on the NS AGS South subdivision following an CPKC freight. Once the route was clear, train 19(07) continued south.

Train	Delay	Comment
19(07)	33"	

Train 4(07) East of Lamy, NM - Temporary Speed Restrictions

08AUG26: Train 4(07), carrying 177 customers onboard, was delayed east of Lamy, NM, on the BNSF Glorieta Subdivision due to multiple speed restrictions in effect between MP 830.8 and MP 796.7. The train was required to operate through several temporary slow-order locations with authorized speeds ranging from 15 MPH to 50 MPH, resulting in reduced operating speeds through the territory. After departing the Lamy area, Train 4(07) encountered additional speed restrictions east of Las Vegas, NM, between MP 750.0 and MP 711.6 on the BNSF Raton Subdivision. The train continued through the affected territory at the prescribed speeds outlined in the bulletin orders, resulting in further delays as it proceeded eastbound.

Train	Delay	Comment
4(07)	29"	LMY-LSV
4(07)	06"	LSV-RAT

Train 5(06) Elko, NV - Freight Train Interference

08AUG26: Train 5(06) was delayed starting at Elko, NV/ MP 557 on the UPRR Elko Subdivision due to freight interference. The crew followed UPRR freight MGRRV starting in Elko to Whirlwind/MP 502.2 where they were able to operate around. The freight was experiencing mechanical issues which limited them to 30MPH until their EOT came back.

Train	Delay	Comment
5(06)	41"	

Train 7/27(06) West of Leavenworth, WA - Freight Train Interference

08AUG26: Train 7/27(06) was delayed at MP 16.0, 27 miles west of Leavenworth, WA, on the BNSF Scenic Subdivision due to freight interference. The crew held for two eastbound freight to clear route. Once freights were clear, Train 7/27(06) proceeded west.

Train	Delay	Comment
7(06)	1'38"	

Train 516(08) South of Mount Vernon, WA - Freight Train Interference/ Passenger Train Interference

08AUG26: Train 516(08) was delayed at MP 32.1, 23 miles south of Mount Vernon, WA, on the BNSF Bellingham Subdivision due to freight interference. The crew held at MP 32.1 until BN3976 cleared route. Once the BNSF freight cleared, the crew advanced to MP 46.1 where they met Train 517(08). Once all rail traffic was clear, Train 516(08) proceeded north.

Train	Delay	Comment
516(08)	33"	BN3976
516(08)	16"	Train 517(09)
517(08)	18"	Train 516(08) meet

Train 21(07) South of Texarkana, AR - Freight Train Interference

08AUG26: Train 21(07) was delayed beginning at Sulphur (MP8.7), 8.7 miles south of Texarkana, AR (MP0.0), on the UPRR Little Rock Subdivision due to signal issues and freight interference. The signal department was working to correct a track indication problem at MP12, resulting in slow freight train movements through the area. Consequently, Train 21(07) was required to complete multiple freight meets while operating southbound, including UP 7160 at Sulphur (MP8.7), UP 8222 and UP 8061 at Queen City (MP21.2), BNSF 8549 and UP 8143 at Bivins (MP31.9), and UP 3000 at Kildare (MP38.0).

Train	Delay	Comment
21(07)	1'00"	Sulphur
21(07)	20"	Bivins
21(07)	28"	Queen City
21(07)	14"	Kildare
21(07)	13"	Signals

Train 3(06) East of Victorville, CA - Debris Strike

08AUG26: At approximately 8:44A-PT, Train 3(06), E/167-E/53-9 cars, went into emergency at MP 24.6, 12 miles east of Victorville, CA, on the BNSF Cajon Subdivision after striking debris on the tracks. There were no injuries reported to the crew or the 172 customers on board. Head end power (HEP) remained up and active. A hose separation was reported but no other damage to the equipment. Once crew finished inspecting equipment and performed a brake test, Train 3(06) proceeded west.

Train	Delay	Comment
3(06)	15"	

Train 2/422(07) East of Maricopa, AZ - Freight Train Interference

08AUG26: Train 2/422(07) was delayed starting 61 miles east of Maricopa, AZ (MP897.7), on the UPRR Gila Subdivision, following UP 7930 from Naviska (MP958.7) to MP976.0.

Train	Delay	Comment
-------	-------	---------

Train 21/421(07) South of Texarkana, AR - Signal

08AUG26: Train 21/421(07) with 46 cars, 100000008701, UNCLASSIFIED, 9/2/2026 delayed at Sulphur/MP8.7 8.7 miles from Texarkana, AR/MP0.0 on the UP Little Rock subdivision due to a signal malfunction. Once the route was clear, train 21/421(07) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(07)	1'00"	

Train 711(08) Fresno, CA - Freight Train Interference

08AUG26: Train 711(08) was delayed departing Fresno, CA / MP 997.9 on the BNSF Stockton Subdivision due to disabled BN3798 ahead in undesired emergency (UDE) from vandals cutting air hoses at Figarden/ MP 1004.1 . After arriving into Fresno at 6:54A-PT, the crew held while the disabled freight inspected consist and BNSF personnel responded to scene. A BNSF trainmaster and special agent arrived on scene by 7:30A-PT to assist with mechanical forces arriving at 7:45A-PT. Once air hoses were repaired and replaced, the disabled freight was able to clear route then Train 711(08) proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
711(08)	1'09"	

Train 761(08) West of Oceanside, CA - PTC Issues

08AUG26: Train 761(08), CC/C6901-4 cars-E/C2121, was delayed at Song/MP 209.16, 17 miles west of Oceanside, CA, on the NCTD San Diego Subdivision due to PTC issues. The crew was unable to initiate PTC going from NCTD territory to Metrolink. Train 761(08) held while the crew contacted the PTC help desk to troubleshoot. Once PTC issues were resolved with a reset, Train 761(08) proceed west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
761(08)	45"	

Train 4(07) East of Winslow, AZ - Signal

08AUG26: Train 4(07) was delayed 50.5 miles east of Winslow, AZ (MP285.5), on the BNSF Gallup Subdivision, due to a power switch failure at Adamana (MP235.0). Operating speeds were restricted through the affected area, resulting in a delay to train operations. Once clear of the restriction, the train resumed track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(07)	30"	

Train 19(07) South of Atlanta, GA - Freight Train Interference

08AUG26: Train 19(07) was holding at Birmont (MP 634.8) on the NSRR Norcross Subdivision, approximately 1.5 miles south of Atlanta, GA (MP 633.3), awaiting a CSX freight train to clear ahead. Once the route was established and authority was received, Train 19(07) was released to continue southward.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(07)	1'01"	

Train 5(06) West of Provo, UT - Signal Issues

08AUG26: Train 5(06) was delayed at MP 745 west of Provo, UT station, on the UPRR Provo Subdivision due to signal issues. Due to the CTC system failure, the crew hand lined and flagged through the crossing after shoving out of the station. Once through affected area, Train 5(06) proceeded west.

Train	Delay	Comment
5(06)	36"	

Train 6(07) West of Provo, UT - Freight Train Interference

08AUG26: Train 6(07) was delayed starting at Riverton/MP 726.7, 25 miles west of Provo, UT, on the UPRR Provo Subdivision due to freight interference. The crew followed UP5722 from Riverton to American Fork/715.9 stopping at Mesa/MP 719 for the freight crew to address mechanical issues on the UP5722. Once at the American Fork siding, Train 6(07) was able to operate around.

Train	Delay	Comment
6(07)	48"	

Train 22(07) North of Marshall, TX - Freight Train Interference

08AUG26: Train 22(07) was delayed beginning 57.8 miles north of Marshall, TX (MP66.5) on the UPRR Little Rock Subdivision while following UP 2654 from Sulphur (MP8.7) to MP1.0. During this movement, both trains were also delayed while holding for cross traffic to clear at KCS Crossing (MP2.4).

Train	Delay	Comment
22(07)	40"	Follow UP 2654
22(07)	15"	KCS Crossing

Train 21(07) South of St. Louis, MO - Signal

08AUG26: Train 21(07) was delayed starting 1.5 miles south of St. Louis, MO (MP1.5), on the UPRR Desoto Subdivision, due to signal issues at Iron Mountain Jct (MP0.0). Operating speeds were restricted until a clear signal was reached at Barracks (MP9.8).

Train	Delay	Comment
21(07)	30"	

Train 22(07)/422(05) Austin, TX - Engine Failure

07AUG26: Train 22(07)/422(05) 00000008701 delayed at Austin, TX station/MP179.4 on the UPRR Austin subdivision due to engine 315 shutting down. Crew attempted to get engine 315 restarted at Austin but were unsuccessful. Crew proceeded to Fort Worth TX station/mp346.2 operating with a single engine. Crew was met by mechanical and spoke with CNOC mechanical to troubleshoot but could not get engine 315 restarted. Train 22(07)/422(05) operated single engine to Marith/MP198.6 where they added UPRR freight engine 6761. Train 22(07) was back on the move at 134M CT after adding the freight engine.

08AUG26: Train 22(07)/422(05) experienced an additional delay at Little Rock, AR (MP345.7) on the UPRR Little Rock Subdivision due to brake pressure issues involving freight engine 6761. After the mechanical issue was resolved, Train 22(07) advanced to One Lead (MP340.5), where it held while UP5906 completed switching operations in North End Yard (MP339.2). Once a route was established, Train 22(07) was released and continued northward.

Train 22(07)/422(05) was further delayed at St Louis, MO performing a calendar day inspection of the engines.

WBS#: B.TR.100150.7009

Train	Delay	Comment
22(07)	07"	AUS
22(07)	54"	FTW
22(07)	2'37"	Add Freight
22(07)	55"	Lrk
22(07)	22"	Operating with freight loco DAL-LRK
22(07)	47"	N/LRK - One Lead
22(07)/422(05)	1'08"	Calendar Day @STL

Gold Runner Service - Equipment Servicing/ Repair Issues

07AUG26: Train 712(07), CC/C8306-5 cars- E/C2102, was delayed departing Oakland, CA due to a late release from mechanical. Equipment arrived into the maintenance facility at 7:28P-PT on August 6th from Train 715(06). With the equipment still not fully serviced, at 10:00A-PT, mechanical estimated another twenty minutes were needed for servicing the equipment. Once equipment was serviced, it departed the maintenance facility at 11:14A-PT en route to Oakland Station for boarding. Once all customers were boarded, Train 712(07) was able to depart at 11:29A-PT.

Train 714(07), E/C2013-8 cars-E/C2014, was delayed departing Oakland, CA due to the late turn of equipment arriving on Train 711(07). The equipment, E/C2012-6 cars-CC/C6962, arrived to the maintenance facility from Train 719(06) at 11:05P-PT on August 6th and was not ready for departure. To avoid a lengthy delay, the inbound Train 711(07) equipment was turned for Train 714(07). Once Train 711(07) arrived into the maintenance facility at 11:30A-PT the equipment was serviced and fueled and it departed at 12:47P-PT for Oakland station for boarding. Once all customers were on board, Train 714(07) departed at 12:59P-PT.

Train 532(07) was delayed departing Oakland, CA due to the congestion in the yard from the Gold Runner service being serviced. Once Train 714(07) cleared yard and worked the Oakland station, the crew on Train 532(07) was able to head to station for boarding.

Train 716(07), CC/C8309-8 cars-E/C2012, was delayed departing Oakland, CA due to a late release from mechanical. At 2:00P-PT, mechanical estimated another thirty minutes were needed for servicing the equipment. The train was released and departed the yard at 500P-PT. After arriving at the station, crew was unable to log into PTC causing further delay. Due to the extended delay, and closing in on the departure time for Train 718, the decision was made to cancel Train 716(07) and deadhead the equipment to Bakersfield. The Union Pacific dispatcher did not receive the information in time and allowed 716(07) to depart Oakland as soon as they were able to initialize PTC. Train 716(07) was then terminated at Emeryville, where all passengers detrained and were accommodated on train 718(07).

to a late release from mechanical. The original equipment, CC/C8312-7 cars-E/C2005, arrived into the maintenance facility from Train 719(07) at 10:27P-PT on August 7th. At 9:55A-PT, mechanical was still working on restroom issues on CC/C8212, as well as addressing door issues on the CC/C8312-7 cars-E/C2005. Due to the anticipated delay for repairs, the equipment for Train 714(08), CC/C8314-7 cars-E/C2004, was decided to be moved up at 10:48A-PT with an anticipated additional thirty minute delay to finish the daily inspections. At 11:27A-PT, mechanical released the equipment to the crew where they performed their necessary inspections and departed the yard at 11:44A-PT to take equipment to station for boarding. Once all customers where boarded, Train 712(08) departed at 11:56A-PT.

Train 714(08), CC/C8312-7 cars-E/C2005, was delayed departing Oakland, CA due to mechanical resolving restroom issues on CC/C8312. The equipment was moved to Train 714(08) from Train 712(08) to give more time for repairs to be made. Once mechanical released the equipment at 12:17P-PT, the crew performed their necessary tests and departed the yard for the station. Once all customers were boarded, Train 714(08) departed at 12:50P-PT.

WBS#: B.TR.100150.7012

Train	Delay	Comment
712(07)	1'11"	
714(07)	41"	
532(07)	18"	yard congestion
716(07)	3'07"	Terminated EMY
716(07)	37"	OKJ- PTC
718(07)	40"	
714(08)	32"	ITD OKJ
712(08)	1'39"	ITD OKJ
703(08)	1'02"	late turn 712(08)

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG:

Pere Marquette:

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(07) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13) cancelled entirely - sourcing alternate.
- Train 371(14) cancelled entirely - sourcing alternate.
- Train 370(16) cancelled entirely - sourcing alternate.
- Train 371(17) cancelled entirely - sourcing alternate.
- Train 370(20) cancelled entirely - sourcing alternate.
- Train 371(21) cancelled entirely - sourcing alternate.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.

and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely - with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(15) cancelled entirely - sourcing alternate.
- Train 355(15) cancelled entirely - sourcing alternate.
- Train 350(18) cancelled entirely - sourcing alternate.
- Train 355(18) cancelled entirely - sourcing alternate.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL and Quincy, IL.
- Train 382(10) cancelled entirely, with 2 alternate buses secured between Quincy, IL and Chicago IL.
- Train 381(14) cancelled entirely, - sourcing alternate.
- Train 382(14) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(17) cancelled entirely - with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21) cancelled entirely - with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21) cancelled entirely, with 1 alternate bus secured between Quincy, IL and Chicago IL.

Saluki/Illini Service

- Train 391(12) cancelled entirely - with 2 alternate buses secured between Chicago, IL and Carbondale, IL.
- Train 392(12) cancelled entirely, with 2 alternate buses secured between Carbondale, IL and Chicago, IL.
- Train 391(19) cancelled entirely - sourcing alternate.
- Train 392(19) cancelled entirely, with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04-10) Cancelled entirely, No alternate Transportation.
- Train 502 (04-10) Cancelled entirely. With alternate transportation.
- Train 504 (04-10) Will terminate in Portland, OR. With alternate transportation.
- Train 518 (04-07) Originates at Seattle, WA. 518 (08-10) Originates Vancouver, WA All with alternate transportation.
- Train 517 (04-10) Will terminate in Vancouver, WA. No alternate Transportation.
- Train 506 (04-10) Originates in Vancouver, WA. No alternate Transportation.
- Train 508 (04-10) Will terminate Portland, OR. With alternate transportation.
- Train 503 (04-10) Originates Portland, OR. With alternate transportation.
- Train 505 (04-07) Cancelled entirely. With alternate transportation. 505 (08-10) Will Terminate in Vancouver, WA, no alternate transportation.
- Train 507 (04-10) Originates Portland, OR. With alternate transportation.
- Train 509 (04-10) Cancelled entirely, with alternate transportation.
- Train 511 (04-10) Cancelled entirely. No alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Train 27 (02-08) Will Terminate at Spokane, WA. Alternate Transportation provided.
- Train 28 (04-10) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

- Train 14 (04-09) Will Terminate at Portland, OR, no alternate transportation provided.
- Train 11 (05-10) Will Originate at Portland, OR, no alternate transportation provided.

WBS#: B.TR.100150.6981

Train	Delay	Comment
-------	-------	---------

507(02)	1'41"	bus VAN-PDX	
506(02)	Canceled		
508(02)	45"	bus PDX-VAN	
509(02)	77"	couple 509-511(02)	
509(02)	75"	detour through UP yard	26-59400671 00000008701 "UNCLASSIFIED" 9/2/2026
511(02)	76"	Detour through UP yard	
500(03)	Canceled		
502(03)	Canceled		
511(03)	Canceled		
505(03)	Canceled		
518(03)	Canceled	between SEA-PDX	
507(03)	Canceled	between SEA-PDX	
508(03)	Term PDX		
504(03)	Term PDX		
509(03)	Canceled		
517(03)	Term VAN		
506(03)	Orig VAN		
503(03)	24"	canceled SEA-PDX	
507(03)	1'10"	waiting for bus at PDX	
14(02)	58"	detour	
11(03)	51"	detour	
14(04)	term PDX		
506(04)	1'03"	wait for inbound bus	
518(04)	1'27"	wait for inbound bus	
507(05)	1'09"	PDX- wait for inbound bus	
507(06)	1'06"	PDX- inbound bus	
503(07)	33"	PDX- inbound bus	
507(07)	1'21"	PDX- inbound bus	
503(08)	22"	PDX- inbound buses	

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple trackwork projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		Mu issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
22 (7)	XMH	UPRR6761	E/315 multiple faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00671

00000008701

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
234 (08)	ALB	car 82548 shopped for wheels, train will go out short a car. no impact to ridership	No impact	0	48170
7 (08)	CHI	0732 car using sleeper in lieu of dorm. schedule change performed. check war report. please block all DS & FS rooms on the 0732 car.	no impact	0	32115
782 (08)	GTA	one coach short, U capacity reduced per division's instructions. no further action required.	NO IMPACT	0	64XX
584 (08)	LAX	no bv	N/A	0	90225
566 (09)	LAX	NO BIKE SPACE OR WIFI	email sent to start passenger notifications.	0	90225
584 (09)	LAX	NO BIKE SPACE OR WIFI	email sent to start passenger notifications.	0	90225
281 (08)	NFL	car 82548 shopped for wheels, train will go out short a car. overcapacity, customer service notified.	Passengers notified	65	48170
280 (09)	NFL	car 82548 shopped for wheels, train will go out short a car. overcapacity, customer service notified. **280(09)**	Passengers notified	71	48170
241 (09)	NYP	car 82548 shopped for wheels, train will go out short a car. no impact to ridership. **241(09)**	No impact	0	48170
761 (08)	SAN	one coach short, U capacity reduced per division's instructions. no further action required.	NO IMPACT	0	64XX
593 (08)	SAN	one coach short, U capacity reduced per division's instructions. no further action required.	NO IMPACT	0	64XX
579 (08)	SAN	no bv	N/A	0	90225
595 (08)	SAN	no bv	N/A	0	90225
579 (09)	SAN	NO BIKE SPACE OR WIFI	email sent to start passenger notifications.	5	90225
595 (09)	SAN	NO BIKE SPACE OR WIFI	email sent to start passenger	0	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00671 00000008701 "UNCLASSIFIED"	notifications.		
8 (10)	SEA	0832(*10*) car using sleeper in lieu of dorm. schedule change performed. check war report. please block all DS & FS rooms on the 0832 car.	no impact	0	32115

Reverse Consists

Train Number	Station	Reason
87 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
127 (08)	NYP	Consist reversed Business class seat orientation may have changed At Rear
109 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
150 (08)	PHL	Consist reversed Business class seat orientation may have changed At Front
144 (08)	PHL	Consist reversed Business class seat orientation may have changed At Rear
103 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
106 (08)	WAS	Consist reversed Business class seat orientation may have changed At Rear
107 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
128 (09)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **128(09)**
158 (09)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **158(09)**
142 (08)	WAS	Consist reversed Business class seat orientation may have changed At Front
126 (08)	WAS	Consist reversed Business class seat orientation may have changed At Front
147 (08)	NHV	Consist reversed Business class seat orientation may have changed At Front