



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, October 02, 2025

Rules: 0-59



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-0001Initial Terminal Performance By Division

Scheduled Departure Date: 10/01/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/01/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	293	58	80.2%	293	58	80.2%	293	58	80.2%
Central Division	85.5%	65	9	86.2%	65	9	86.2%	65	9	86.2%
Northeast Division	80.0%	93	24	74.2%	93	24	74.2%	93	24	74.2%
Southeast Division	72.5%	70	9	87.1%	70	9	87.1%	70	9	87.1%
Southwest Division	77.0%	65	16	75.4%	65	16	75.4%	65	16	75.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00008

Endpoint Arrival Dates through 10/1/25

UNCLASSIFIED

10/6/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	82,210	13,647	83%	82,210	13,647	83%	82,210	13,647	83%
Northeast Corridor	81%	38,433	4,364	89%	38,433	4,364	89%	38,433	4,364	89%
Acela	83%	8,006	708	91%	8,006	708	91%	8,006	708	91%
Northeast Regional	79%	30,427	3,656	88%	30,427	3,656	88%	30,427	3,656	88%
Richmond / Newport News / Norfolk	77%	9,618	1,347	86%	9,618	1,347	86%	9,618	1,347	86%
Springfield Shuttles	89%	634	162	74%	634	162	74%	634	162	74%
Roanoke	79%	2,355	608	74%	2,355	608	74%	2,355	608	74%
On Spine Northeast Regional	80%	17,820	1,539	91%	17,820	1,539	91%	17,820	1,539	91%
State Supported	80%	34,049	5,614	84%	34,049	5,614	84%	34,049	5,614	84%
Borealis	60%	427	129	70%	427	129	70%	427	129	70%
Capitol Corridor	90%	3,693	550	85%	3,693	550	85%	3,693	550	85%
Carolinian	60%	771	257	67%	771	257	67%	771	257	67%
Cascades	63%	1,612	382	76%	1,612	382	76%	1,612	382	76%
Downeaster	82%	1,120	59	95%	1,120	59	95%	1,120	59	95%
Empire	78%	4,205	1,357	68%	4,205	1,357	68%	4,205	1,357	68%
Adirondack	72%	240	135	44%	240	135	44%	240	135	44%
Ethan Allen Express	70%	461	430	7%	461	430	7%	461	430	7%
Maple Leaf	70%	516	152	71%	516	152	71%	516	152	71%
New York - Albany	85%	1,943	377	81%	1,943	377	81%	1,943	377	81%
New York - Niagara Falls	75%	1,045	263	75%	1,045	263	75%	1,045	263	75%
Heartland Flyer	65%	118	83	30%	118	83	30%	118	83	30%
Hiawatha	90%	1,446	510	65%	1,446	510	65%	1,446	510	65%
Illinois	78%	1,707	487	71%	1,707	487	71%	1,707	487	71%
Carl Sandburg / Illinois Zephyr	85%	234	179	24%	234	179	24%	234	179	24%
Illini / Saluki	85%	565	6	99%	565	6	99%	565	6	99%
Lincoln Service	70%	908	302	67%	908	302	67%	908	302	67%
Keystone	92%	8,657	398	95%	8,657	398	95%	8,657	398	95%
Lincoln / Missouri	60%	553	205	63%	553	205	63%	553	205	63%
Mardi Gras Service	80%	320	140	56%	320	140	56%	320	140	56%
Michigan	69%	1,191	0	100%	1,191	0	100%	1,191	0	100%
Blue Water	70%	310	0	100%	310	0	100%	310	0	100%
Pere Marquette	85%	239	0	100%	239	0	100%	239	0	100%
Wolverine	65%	642	0	100%	642	0	100%	642	0	100%
Missouri	80%	126	14	89%	126	14	89%	126	14	89%
Pacific Surfliner	85%	4,185	217	95%	4,185	217	95%	4,185	217	95%
Pennsylvanian	72%	739	0	100%	739	0	100%	739	0	100%
Piedmont	73%	552	85	85%	552	85	85%	552	85	85%
San Joaquins	73%	1,445	739	49%	1,445	739	49%	1,445	739	49%
Vermont	75%	1,182	2	100%	1,182	2	100%	1,182	2	100%
Long Distance	56%	9,728	3,669	62%	9,728	3,669	62%	9,728	3,669	62%
Auto Train	57%	539	0	100%	539	0	100%	539	0	100%
California Zephyr	50%	902	62	93%	902	62	93%	902	62	93%
Cardinal	55%	199	113	43%	199	113	43%	199	113	43%
City Of New Orleans	75%	464	83	82%	464	83	82%	464	83	82%
Coast Starlight	60%	445	102	77%	445	102	77%	445	102	77%
Crescent	70%	581	181	69%	581	181	69%	581	181	69%
Empire Builder	55%	1,029	459	55%	1,029	459	55%	1,029	459	55%
Floridian	40%	1,791	1,382	23%	1,791	1,382	23%	1,791	1,382	23%
Lake Shore Ltd	73%	757	180	76%	757	180	76%	757	180	76%
Palmetto	65%	671	19	97%	671	19	97%	671	19	97%
Silver Meteor	45%	615	0	100%	615	0	100%	615	0	100%
Southwest Chief	40%	750	747	0%	750	747	0%	750	747	0%
Sunset Ltd	70%	258	2	99%	258	2	99%	258	2	99%
Texas Eagle	50%	727	339	53%	727	339	53%	727	339	53%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FD-000000 00000004007 "UNCLASSIFIED" 10/0/2025

Train Index Dates Through October 01, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	3,748	106,768	351	3,748	106,768	351

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	115	30,820	37	115	30,820	37
INFRASTRUCTURE PLANNED	130	105	30,820	34	105	30,820	34
FLEET RELIABILITY	90	387	106,768	36	387	106,768	36
TRAIN OPERATIONS	427	3,141	106,768	294	3,141	106,768	294

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/01/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/01/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	293	58	80.2%	293	58	80.2%	293	58	80.2%
Central Division	85.5%	65	9	86.2%	65	9	86.2%	65	9	86.2%
Northeast Division	80.0%	93	24	74.2%	93	24	74.2%	93	24	74.2%
Southeast Division	72.5%	70	9	87.1%	70	9	87.1%	70	9	87.1%
Southwest Division	77.0%	65	16	75.4%	65	16	75.4%	65	16	75.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak or Commuter: **Amtrak**

2.1 of 2.2

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/01/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/01/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	293	58	80.2%	293	58	80.2%	293	58	80.2%
Southeast Division	72.5%	70	9	87.1%	70	9	87.1%	70	9	87.1%
RNK	85.5%	2	0	100.0%	2	0	100.0%	2	0	100.0%
RVM	86.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
SAV	91.5%	1	0	100.0%	1	0	100.0%	1	0	100.0%
SFA	70.5%	1	0	100.0%	1	0	100.0%	1	0	100.0%
WAS	70.0%	22	1	95.5%	22	1	95.5%	22	1	95.5%
Southwest Division	77.0%	65	16	75.4%	65	16	75.4%	65	16	75.4%
ARN	60.5%	1	1	0.0%	1	1	0.0%	1	1	0.0%
BFD	75.5%	5	3	40.0%	5	3	40.0%	5	3	40.0%
EMY	50.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
FTW	89.5%	1	0	100.0%	1	0	100.0%	1	0	100.0%
GTA	72.5%	3	1	66.7%	3	1	66.7%	3	1	66.7%
LAX	77.5%	10	3	70.0%	10	3	70.0%	10	3	70.0%
OKC	96.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
OKJ	79.0%	9	1	88.9%	9	1	88.9%	9	1	88.9%
SAC	73.5%	12	1	91.7%	12	1	91.7%	12	1	91.7%
SAN	77.0%	12	1	91.7%	12	1	91.7%	12	1	91.7%
SAS	85.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
SJC	87.5%	7	3	57.1%	7	3	57.1%	7	3	57.1%
SLO	62.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
3	47	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
4	57	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
5		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
6		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
7		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
8	62	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
11	No OS	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
14		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
19		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
20		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
21	35	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
22		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
23		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
24		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
25	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
26	150	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
27		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
28	53	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
40		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
41	77	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
42		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
43		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
48		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
49		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
50		0.0%			0.0%			1	0	100.0%	1	0	100.0%
52		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
53		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
55		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
56		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
58		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
59		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
63		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
64		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
66		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
67		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
68	22	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
69		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
71		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
72		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
73		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
74	14	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75	12	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
76	29	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
77	14	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
78		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
79		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
80		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
84		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
85		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
86		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
89		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
90		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
93	36	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
94	74	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
95		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
97		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
98		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
110		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
111		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
112		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
114		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
119		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
125		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
129		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
130		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
131		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
133	27	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
134	30	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
136		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
138		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
141		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
148		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
151	27	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
171		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
172		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
173		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
174		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
175		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
176		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
177		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
178		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
179		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
181		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
183		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
184		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
185		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
186		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
190		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
192		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
193		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
196		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
197		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
232		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
233	27	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
234		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
236		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
237		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
239		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
240	30	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
241		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
243		1	1	0.0%	1	1	0.0%	2	1	50.0%	2	1	50.0%
243	16	1	1	0.0%	1	1	0.0%	2	1	50.0%	2	1	50.0%
244		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
280		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
281		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
283		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
284	17	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
290	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
291	21	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
300		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
301		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
302	64	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
305		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
306		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
307		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
311		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
316		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
318		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
319	24	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
329		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
330		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
331		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
332	16	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
334		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
336		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
337		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
338	17	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
339		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
341	14	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
342		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
351		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
352		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
354		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
355		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
364		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
365		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
370		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
371		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
380	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
381		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
382	35	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
383	59	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
390		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
391		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
392		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
393		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
417		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
425		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
470		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
471		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
473		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
474		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
475		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
478		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
479		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
486		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
494	59	2	2	0.0%	2	2	0.0%	1	1	0.0%	1	1	0.0%
495		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
500		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
502		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
503		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
504		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
505		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
506		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
507		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
508		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
509		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
511		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
516	52	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
517		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
518	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
519		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
521		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
522		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
523		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
524		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
525	14	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
526		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
527		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
528		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
529		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
531		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
532	45	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
536		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
537		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
538		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
540		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
541	42	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
542	12	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
543		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
544		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
545	31	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
546		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
547		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
548		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
551		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
562		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
564		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
566		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
572		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
573		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
577		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
580		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
581	24	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
582		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
586		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
587		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
591		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
593		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
595		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
600		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
601		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
605		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
607		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
609		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
620		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
624		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
639		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
640		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
641		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
642		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
643		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
644		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
645		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
646		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
647	17	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
648		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
649		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
650		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
651		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
652	18	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
653		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
654		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
655		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
656		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
657		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
658		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
680		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
681		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
682		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
685		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
686		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
687		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
688	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
702	23	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
703		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
710	38	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
711	29	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
712		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/1/2025

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
713		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
715	34	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
716	20	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
718		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
719		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
761		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
765		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
769		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
770		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
774		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
779	Cncld	1	0	100.0%	1	0	100.0%	0.0%			0.0%		
784		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
785		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
790		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
794		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
821	17	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
822		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1333	44	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1340		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1689		0.0%			0.0%			1	0	100.0%	1	0	100.0%
2103		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2107		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2108		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2121		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2122		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2150		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2151		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2153		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2154		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2155	Cncld	1	0	100.0%	1	0	100.0%	0.0%			0.0%		
2159		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2162		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2163		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2166		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2167		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2168	40	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2170	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2172		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2173		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2190		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2193		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak Endpoint OTP Details

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/1/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2155	XHM	Trn Cancelled	ENG	69	ENG	55	XSH-NYP	AM	Air / Brake, 2006, AIR COMPRESSOR PROBLEM ON REAR PC2006
2168	BOS	40	ENG	25	ENG	25	XSH-STM	MN	Power car 2010 smoke comes out another train report power car get some smoke dispatcher order to stop and inspect train Called road formen mark William order us to lower pangraph, 2010
2170	BOS	21	OTH	19	TRS	12	PHL-XHM	AM	Vandalism, Control Point, Clearfield, Received 241 a/c TOL across all track,
93	NFK	36	DCS	32	DCS	12	RVR-PTB	CS	Restrictive signal(s) from known wayside signal failure Talked passed Stop signal, stop, Control Point, Petersburg
94	BOS	74	SYS	42	SYS	42	NFK-NFK	NS	Late bulletins due to Amtrak cause No CSX orders, Other, norfolk
133	WAS	27	ADA	8	ADA	5	PHL-PHL	AM	Wheelchair, per cndr; 3:32pm
134	NYP	30	FTI	13	FTI	13	ALX-XVG	CS	Follow n/a, Milepost, 106.5, 110.5
151	RNK	27	ENG	16	ENG	16	WAS-WAS	AM	Other electrical failure, 355, LATE DIESEL FROM PIT, DIESEL ARRIVED TO STATION AT 810A
494	GFD	59	CON	61	CON	35	NHV-NHV	AM	Hold for connecting train, late dp of AM494 due to late connection of AM94
647	HAR	17	PTI	8	PTI	8	XHM-PHL	AM	Follow, 93, Milepost, 88.0, 77.2
652	NYP	18	CTI	18	CTI	18	NWK-NYP	AM	Blocked from station track, NJ, 6360 X318, Other, NWK-NYP, STATION CONGESTION DUE TO MULTIPLE NJT EXTRA TRAINS IN STATION
688	BON	19	PTI	16	PTI	14	FRE-POR	CS	Meet 685, Control Point, mountain
68	NYP	22	CTI	22	CTI	22	POU-CRT	MN	Follow mn, Control Point, 56
233	ALB	27	CTI	16	ENG	14	NYP-NYP	AM	HEP, 99, UNSPECIFIED MECHANICAL PROBLEM ON ENG.99
240	NYP	30	ENG	16	ENG	16	ALB-HUD	AM	PTC- IETMS hard cutout Acses failure, 716
243	ALB	16	ITI	17	ITI	17	NYP-NYP	AM	Service, turn, or wye train, 244, LATE TURN OFF OF AM244
284	NYP	17	RTE	11	RTE	11	BFX-BUF	CS	Had to pull into belt sub and back up do to switch failure at 437 Control Point, 437
290	NYP	21	CTI	21	CTI	19	POU-CRT	MN	Follow mn, Control Point, 72
291	BTN	21	ITI	20	ITI	20	NYP-NYP	AM	Service, turn, or wye train, 240, LATE TURN OFF AM240

Amtrak Endpoint OTP Details

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/1/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
74	RGH	14	PTI	9	PTI	9	BNC-DNC	NS	Meet #Amt77, Siding, Haw River
75	CLT	12	PTI	12	PTI	12	HPT-SAL	NS	Meet #Amt74, Control Point, Duke
76	RGH	29	PTI	15	PTI	15	GRO-DNC	NS	Meet #Amt79, Control Point, Isom
77	CLT	14	TEN	18	TEN	18	RGH-CYN	NS	Failure of diesel engine Diesel Engine shut down on us leaving RGH., NC1871
41	MIA	77	FTI	175	FTI	112	DNK-SAV	CS	Follow While following 693 went into emergency @ the 494.4 , would not recover, found air hose separation., M-693-30, Milepost, 467.0, 497.2
25	NOL	26	FTI	62	FTI	43	BAS-XNO	CS	Meet 4 way at Claiborne, csx 5215, csx 4758, Siding, claiborne
26	MOE	150	FTI	165	FTI	145	XNO-BAS	CS	Follow 602, Milepost, 775.4, 752.5
525	OKJ	14	PTI	9	PTI	9	SUI-MTZ	UP	Meet 522, Control Point, Cordelia
532	SAC	45	MBO	49	MBO	49	MTZ-SUI	UP	For maritime traffic Control Point, vista
541	SJC	42	PTI	20	PTI	20	FMT-GAC	UP	Meet Amt 538, Control Point, CO 035
542	SAC	12	TEN	12	SYS	4	SJC-SJC	UP	Other late crew Crew late DHT arrival to SJC off aMT 541. Subsequent equipment set over depot 8 > 1., Other, SJC depot
545	OKJ	31	INJ	26	INJ	26	MTZ-MTZ	UP	Injured or sick passenger Passenger fell down stairs after train had come to a complete stop. Daniel Vincent Kincheloe PNR#AB9522.
516	VAC	52	DBS	35	DBS	18	SEA-SEA	BN	Debris blocking track (no debris strike) Control Point, 23rd
518	VAC	26	CTI	23	CTI	12	TAC-XTW	ST	Meet Sounder, SDRX 902, Control Point, Portland Ave
11	LAX	No OS Rpt	FTI	206	FTI	78	EUG-XFS	UP	Hold for disabled freight MPDRV stalled on the main MP 543. Decision made to split their train in two and drag each half up the mountain. Hold at Fields in the meantime., Control Point, Fields, UP 7643, Manifest
8	CHI	62	FTI	94	FTI	40	MSP-XH8	CP	Cross Traffic CP 8869 West making multiple direction moves between Hoffman and Division Street. Very long train with extra power in the middle., CP 4450101 C, Control Point, Division Street
28	SPK	53	FTI	83	FTI	25	WIH-PSC	BN	Meet Control Point, West Towal, BN3797

Amtrak Endpoint OTP Details

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/1/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
821	FTW	17	DSR	43	DSR	28	GLE-FTW	BN	Per bulletin Milepost, 409.1, 409.0, 30, main, Milepost, 392.1, 392.0, 10, main, Milepost, 389.7, 389.5, 40, main, Milepost, 383.3, 383.2, 30, main, Milepost, 372.3, 372.2, 25, main, Milepost, 379.8, 374.3, 60, main, Milepost, 360.0, 359.2, 30, main	
332	CHI	16	OTH	25	OTH	24	MKE-MKE	CP	No 1173 paperwork in either unit; had CNOC fax a copy to MKE ticket office.	
335	MKE	21	SYS	15	DCS	13	XRO-SVT	CP	Efficiency test (host railroad officers only) Hand line west crossover switch on MT1, Control Point, Truesdell 2-1	
338	CHI	17	ITI	15	ITI	15	MKE-MKE	CP	Service, turn, or wye train 335	
341	MKE	14	DCS	10	DCS	10	XWA-GLN	ME	Restrictive signal(s) from unknown cause Stop, Control Point, A-6	
581	LAX	24	CTI	22	CTI	10	SOL-OSD	SN	Meet coaster, Control Point, swami	
779	SLO	Trn Cancelled	ADA	6	PTI	4	OLT-SOL	SN	Meet Amtk 572, Control Point, Torrey	
702	BFD	23	FTI	29	DSR	10	XEC-LOD	UP	Per bulletin Milepost, 49.9, 50, 70, main, Milepost, 52.58, 52.75, 60, main 1, Milepost, 58.10, 58.20, 60, main, Milepost, 64.35, 64.65, 40, main, Milepost, 68.06, 68.15, 40, main	
710	BFD	38	FTI	24	DSR	16	COC-WAC	BN	Per bulletin Milepost, 945.5, 943.4, 25, main	
711	OKJ	29	FTI	26	FTI	11	HNF-FNO	BN	Meet bnsf 6616, Milepost, 995, 995	
715	OKJ	34	PTI	23	PTI	20	ACA-XPR	BN	Meet Shuffle with 718, AMTK 718, Siding, Pittsburg	
716	BFD	20	FTI	34	FTI	28	WAC-BFD	BN	Meet bnsf7161w, Control Point, jastro/gomez	
3	LAX	47	FTI	93	PTI	39	LSV-LMY	BN	Meet AMTK 4, Control Point, W Canoncito	
4	CHI	57	CAR	81	CAR	61	RIV-SNB	BN	Air / Brake / Wheel 61034, 39012, Brake Pipe between 61034 and 39012 came apart. BNSF responders adjusted brake pipe hoses.	
21	SAS	35	FTI	86	PTI	46	FTW-FTW	UP	Meet AMTK 22, Control Point, 951	
302	CHI	64	FTI	75	FTI	55	XUD-SMT	CC	Cross Traffic Freight, Control Point, Canal	
380	CHI	21	DSR	11	FTI	8	QCY-MAC	BN	Meet 5187, Siding, Eubanks	
382	CHI	35	ENG	29	ENG	9	QCY-QCY	BN	Operate with freight locomotive 313, XBN8284	
383	QCY	59	POL	64	POL	64	KEE-GBB	BN	RR blocked by trespasser or vehicle strike by another train Trespasser on tracks near GBB station. Held at B Plant for clearance	

Amtrak Endpoint OTP Details

26-FOI-0000800000004607"UNCLASSIFIED"10/6/2025

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/1/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
319	KCY	24	DSR	23	FTI	15	JEF-SED	UP	Meet 9770, Siding, smithton
1333	MSP	44	FTI	46	FTI	46	WIN-RDW	CP	Follow 375, Milepost w/Letters, LAKEVIEW, FRONTENAC

Amtrak Initial Terminal Details

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/1/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	620	10/01	1		
HAR	624	10/01	1		
HAR	650	10/01	1		
HAR	652	10/01	1		
HAR	658	10/01	1		
NFK	94	10/01	42	42	Late bulletins due to Amtrak cause No CSX orders, Other, norfolk
NPN	186	10/01	1		
RVM	86	10/01	4	4	Line manual or spring switch Waiting for switch to time out, Milepost, 4.4, 4.4
WAS	2172	10/01	1		
BON	689	10/01	1		
BOS	67	10/01	3	3	Door, 48158, Door issues with the 2nd door B' Door
BOS	173	10/01	1		
BOS	177	10/01	1		
BOS	2173	10/01	2	2	Door, 3696-3469, rpts door issues on PV 3696 & PV 3469 dp BOS 2" late
NHV	470	10/01	1		
NHV	474	10/01	17	17	Fuel, Servicing
NHV	478	10/01	6	10	Water, commissary, toilet/trash dumping, SERVICING EQUIPMENT
NHV	486	10/01	1		
NHV	494	10/01	61	35	Hold for connecting train, late dp of AM494 due to late connection of AM94
NHV	494	10/01	61	26	Hold for connecting train, late dp of AM494 due to late connection of AM94
NHV	494	10/01	61	35	Hold for connecting train, late dp of AM494 due to late connection of AM94
NHV	494	10/01	61	26	Hold for connecting train, late dp of AM494 due to late connection of AM94
NYP	51	10/01	3	3	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	79	10/01	6	6	Enforcement of carry-on baggage policy, PSGR ISSUE WITH OVERSIZED LUGGAGE
NYP	111	10/01	5	5	Passenger and/or baggage, HELD BY DSPR FOR LATE BOARDING PSGRS.
NYP	133	10/01	3	3	Passenger and/or baggage, LOADING
NYP	233	10/01	14	14	HEP, 99, UNSPECIFIED MECHANICAL PROBLEM ON ENG.99
NYP	237	10/01	2	2	High passenger count, LOADING
NYP	241	10/01	2	2	High passenger count, LOADING

Amtrak Initial Terminal Details

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/1/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	243	10/01	17	17	Service, turn, or wye train, 244, LATE TURN OFF OF AM244
NYP	291	10/01	19	20	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	607	10/01	2	2	Copy authority / restriction, LATE PAPERWORK
SPG	141	10/01	1		
SPG	417	10/01	1		
SPG	495	10/01	13	13	Planned Switch, Equipment swap at SPG
TWO	64	10/01	4		
WEM	686	10/01	2	2	Hold for thruway bus
CHI	339	10/01	7	2	Passenger and/or baggage Same pax from 338, a9bd33, was completely in way of boarding with her bags
CHI	339	10/01	7	5	Service, turn, or wye train 338
MKE	332	10/01	24	24	No 1173 paperwork in either unit; had CNOC fax a copy to MKE ticket office.
MKE	338	10/01	15	15	Service, turn, or wye train 335
PDX	28	10/01	8	8	PTC problem or failure (cause unknown) D17 PTC failure code. Had to reset the I-etms breaker and wait.
PDX	502	10/01	1		
PTH	365	10/01	9	9	Door ID4001, Showing door open on engine. All doors were secure prior to attempted departure. Appeared to be issue with bad ordered car 4001. Open and closed door and steps repeatedly until finally all doors were shown as closed.
QCY	382	10/01	9	9	Operate with freight locomotive 313, XBN8284
SEA	516	10/01	18	18	Debris blocking track (no debris strike) Control Point, 23rd
ARN	529	10/01	1		
BFD	703	10/01	5	5	Door C8807, Couldn't get a door light from door 5&6. Had to troubleshoot, but was able to fix the problem.
BFD	711	10/01	3	3	Door issue
BFD	715	10/01	5	5	High passenger count
EMY	6	10/01	1	1	Meet 527, Control Point, East Emeryville
GTA	790	10/01	1		
LAX	4	10/01	2	2	Meet Did not get clear signal until Amtrak train cleared track 14 switch, 781, Control Point, track 11
LAX	566	10/01	4	4	Cross Traffic Per DS: held for inbound Metrolink on track 8, scax, mtk, Other, LAX
LAX	586	10/01	1		
OKJ	716	10/01	6	6	Excessive play (condemnable) on brake cylinders C2002

Amtrak Initial Terminal Details

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/1/2025

Terminal	Train	Date	Late	Delay	Cause
SAC	545	10/01	1		
SAN	573	10/01	10	10	Loading problem C2115, C2109
SJC	542	10/01	4	4	Other late crew Crew late DHT arrival to SJC off aMT 541. Subsequent equipment set over depot 8 > 1., Other, SJC depot
SJC	544	10/01	1		
SJC	546	10/01	1		
SLO	794	10/01	(Trn Cxld)		VEHICLE STRIKE

Eastern Region

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	99.4	94.8	309	2
CDOT	95.0	100	100	92.4	20	0
MARC	95.0	No Data	No Data	83.5	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	92.8	92.8	93.8	363	26
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 494(01) New Haven, CT - Hold for Connection

01OCT25: Train 494(01) was delayed departing New Haven, CT waiting for late inbound connections off train 94(01).

Train	Delay	Comment
494 (01)	1'01"	

Train 26/25(01) East of New Orleans, LA - Freight Train Interference

01OCT25: Train 26(01) operating with engine 14, 3 cars, and engine 82 was delayed east of New Orleans on the CSX NO&M subdivision meeting freight at milepost 769.0 and then stopping behind the same freight after a hot box detector was set off and the freight crew had to inspect. Due to the length of the freight train, train 26(01) followed the freight into Mobile.

Train 25(01) operating with engine 206, 3 cars, and engine 187 was delayed east of train 26(01) at milepost 766.3 meeting the same CSX freight and train 26(01). Once both trains cleared, train 25(01) proceeded east to New Orleans.

Train	Delay	Comment
25 (01)	43"	FTI
26 (01)	32"	Recrew
26 (01)	2'25"	FTI

Train 98(01) Savannah, GA - Police Related

01OCT25: Train 98(01) was delayed departing Savannah, GA due to an older passenger refusing help detraining at the station and ended up falling. EMS arrived on scene promptly and requested a second group of EMS to help get passenger onto gurney. The passenger was stated to be lying on the yellow line and train 98(01) was unable to move until the passenger was taken by EMS.

Train	Delay	Comment
98 (01)	34"	

Track Light Outage - East of North Philadelphia, PA - Signal

01OCT25: Track Oc 26-FCI-00006 y 0000004607 s a "UNCLASSIFIED" on 10/6/2025 on all tracks at the Clearfield Interlocking/MP84.5 on Amtrak's New York (West) subdivision. Trains operating Eastbound received delays receiving a 241, Westbound trains did a stop and approach. The trouble desk and Amtrak Police were notified. The maintainer was dispatched and arrived on the scene at approximately 537P - ET.

Train	Delay	Comment
85 (01)	08"	
651 (01)	11"	
173 (01)	15"	
129 (01)	13"	
2170 (01)	12"	
2167 (01)	08"	
148 (01)	06"	
652 (01)	06"	
20 (30)	12"	
2172 (01)	07"	
178 (01)	08"	

Train 52(01) North of DeLand, FL - Vehicle Strike /Trespasser Incident

01OCT25: At 437P-ET, Train 52(01) with E/357,E/364 and E/516 and 40 cars reported that they struck a vehicle towing a trailer that ran around the gates at MP 726.7 on the CSX Sanford A subdivision. The conductor reported they struck the trailer not the vehicle and there were no injuries to the 238 passengers, crew or vehicle occupants. The train did lose HEP initially due to E/357 shutting down and crew was able to restore HEP but it went back down. Amtrak Road Foreman was onboard and working with crew and Sanford mechanical to restore HEP on the train unit. The Road Foreman and Crew after speaking with CNOC were able to get the HEP back up and running on E/364 and E/357 restarted. This occurred at an industry business crossing with a stop sign no gates or warning lights.

Sanford mechanical was dispatched to the train to make temporary repairs to engineer side plow. It was deemed by mechanical that lose cables needed to be secured and all damages could be repaired at end point in Lorton. CSX maintenance of way cleared the tracks at 7:00 p.m. and train 52(01) was released at 7:28 p.m.

National Response Center Number: 1444360

Train	Delay	Comment
52 (01)	2'51"	

Train 2155(01) West of Providence, RI - Engine Failure

01OCT25: Acela 2155(01) experienced low main reservoir penalties with PC/2006 at MP86.51 on Amtrak/New Haven Boston Main Line. Crew was in contact with the Road Foreman and was able to correct the problem and proceed west.

Acela 2155(01) stopped again at MP31.7/Harold with compressor issues on rear PC/2006. Crew was in contact with the Road Foreman and proceeded west into New York, NY. Upon arrival in New York, NY High Speed Mechanical meet the train and determined that it was necessary to cancel the train at New York, NY/ Passengers were reaccommodated on Train 171(01) from New York, NY to Washington, DC. This also cancelled Acela 2124(01) Washington, DC to New York, NY.

Train	Delay	Comment
2155(01)	04"	MP 88.51
2155(01)	55"	MP 3.7
2155(01)	TERM NYP	
2124(01)	XCLD	

Train 94(01) Norfolk, VA - CSX Orders/System

01OCT25: Train 94(01) was delayed departing Norfolk, VA, to CSX having computer issues which caused the train not being able to receive their orders.

Train	Delay	Comment
94(01)	42"	

Train 41(29) - South of Denmark, SC - Freight Train Interference

01OCT25: Train 41(29) was delayed on the CSX Columbia Subdivision at MP 490.0 due to CSX Train M693-30 being disabled ahead. The conductor reported CSX Train M693-30, 10,00 feet long, experienced UDE and was unable to rebuild air.

Train	Delay	Comment
41(29)	1'15"	

Maintenance of Way Highlights

Downeaster Trackwork CSX Portland Sub-M of W Work

22SEP25: Downeaster Service Adjustments due to CSX Portland Subdivision trackwork between Brunswick, ME and Boston North, MA station. They are welding , switch timbers and tie pickup between Wells, MA and Brunswick on the following Tuesday thru Thursday from 8A-ET to 530P-ET. On September 30,2025 to October 02,2025, October 7-9, 2025, October 14-16, 2025, October 21-23, 2025, October 28-30, 2025 and November 4-6, 2025. The following service adjustments will be made:

Northbound:

- Train 681(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BON and BRK, will terminate at WEM.
- Train 683(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BON and BRK is cancelled in its entirety with no alternate transportation.

Southbound:

- Train 684(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BRK and BON, is cancelled in its entirety with no alternate transportation.
- Train 686(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BRK and BON, will originate at WEM.

WBS#: B.TR.100151.0776

Train	Delay	Comment
681	TERM WEM	WITH ALT TRANS
684	CANCELLED	NO ALT TRANS
686	ORIG WEM	WITH ALT TRANS
683	CANCELLED	NO ALT TRANS

Metro North NHV Line - Weekend Outages

25SEP25: Metro North Railroad has trackwork scheduled this weekend on their NHV Line. First, the No.1 and No.2 tracks between CP223/MP23.5 and CP229/MP29.6 will be out of service starting Friday 9/26 at 11:00PM through Sunday 9/28 at 4:00PM. This is located between the New Rochelle, NY station/MP16.6 and the Stamford, CT station/MP33.1 with Rule 22 on No.3 track.

Starting Friday 9/26 at 11:00PM through Monday 9/29 at 5:00AM, the No. 1 and No.2 tracks from CP266/MP66.3 to CP272/MP71.9 will be out of service to replace the 21B switch at CP271/MP71.3. Rule 22A will be placed on the No.3 and No.4 tracks. There is also an all-track outage from CP261/MP60.7 to CP266/MP66.3 on both Friday and Saturday overnights between 11:59PM and 6:00AM, AC power will be removed. No.4 track will be the running track. This trackwork is located between the Bridgeport, CT/MP55.4 and New Haven, CT/MP72.3 stations.

Metro North Hudson Line - Weekend Outage

25SEP25: Metro North Railroad has a weekend outage on the Hudson Line starting Friday, September 26th at 11:00PM through Monday, September 29th at 5:00AM. The trackwork is scheduled between the Croton Harmon, NY station/MP33.3 and the Yonkers, NY station/MP15.2. The No.1 and No.2 tracks between CP25/MP26.4 and CP33/MP32.9 will be out of service with a Rule 22A placed on No.3 and No.4 tracks.

VIA Oakville Subdivision Oakville, ON - Scheduled M/W Work

13SEP25: To accommodate 25-FOI-00008-00000004607 UNCLASSIFIED 11/06/2025 VIA Oakville subdivision at Oakville/MP 21.4. As a result, train 63/7098(13SEP-14SEP, 27SEP-28SEP, 04OCT-05OCT, 25OCT-26OCT, 29NOV-30NOV, 06DEC-07DEC, and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay. Train 64/7097(13SEP-14SEP, 27SEP-28SEP, 04OCT-05OCT, 25OCT-26OCT, 29NOV-30NOV, 06DEC-07DEC, and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay.

WBS#: B.TR.100150.5989

Train	Delay	Comment
64(13)	1'39"	

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12, 2025 to Friday October 10, 2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS 26-FOI-00008 No 00000004607 UNCLASSIFIED 10/6/2025
between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

· Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

· Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

· Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

· Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

· Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

· Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

· Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

· Bus 3470 will provide alternate transportation between HFD and SPG

· Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

· Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

· Deadhead Train 426 will turn for Train 471 at HFD

· Train 470 will turn for Train 473 at HFD

Eastern Region

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 80(01) Passenger Removal at Richmond (Staples Mill Rd), Virginia – Improper Conduct***

01OCT25, Passenger on PNR 8C04AF, traveling from Charlotte, NC to New York, NY, was removed at Richmond, VA for aggressive behavior and disrespectful language towards onboard crew. Amtrak Police notified.

Delay: 80 (01) NONE

Train 98(01) Passenger Removal at Savannah, Georgia – Medical

01OCT25, Passenger on PNR A77092, traveling from Hollywood, FL to Savannah, GA, was removed from the train by EMS. The passenger refused the offered help detraining and fell down the vestibule steps. The passenger landed on the platform and rolled under the train. Amtrak Police notified.

Delay: 98 (01) 38"

Train 53(28) Passenger Removal at Lorton, Virginia – Improper Conduct

01OCT25, Passenger on PNR 90DC5F, traveling from Lorton, VA to Sandford, FL, was removed from the train by Jesus Sherrif department. The passenger was reported to be physically and verbally abusive to traveling companion. Amtrak Police notified.

Delay: 53 (28) 36"

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Western Region

Operating Highlights

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Train 7(30) West of Whitefish, MT - Broken Rail

02OCT25: Train 7(30) was delayed 69 miles west of Whitefish, MT, at MP 1288, on BNSF Koontenai River subdivision, due to an impassable broken rail at MP 1288.1. BNSF personnel arrived to the scene to repair. Once the rail was repaired and inspected, train 7(30) was able to proceed.

Train	Delay	Comment
7(30)	1'08"	

Train 383(01) East of Galesburg, IL - Trespasser Incident

01OCT25: Train 383(01) was delayed 1 mile east of Galesburg, IL, at milepost 161.5, on BNSF Mendota subdivision, due police placing a hold on all tracks because of a trespasser on the tracks. Once the police finished their investigation, they released the tracks and train 383(01) was able to proceed.

Train	Delay	Comment
383(01)	1'04"	

Train 11(30) Signal Problems South of Salinas, CA

01OCT25: Train 11(30) was delayed 87 miles south of Salinas at South McKay, MP 201.80, Coast Subdivision of the Union Pacific Railroad. This was after the local dispatcher was unable to remotely control the signals. The Engineer was required to gain verbal authority to pass the red signal, operating at a reduced speed until the next verified aspect at Paso Robles (MP 212.9). The train was further delayed slowing to ensure all road crossings were clear. Once through the affected area, train 11(30) was able to continue to Paso Robles at track speed.

Train	Delay	Comment
11(30)	34"	

Train 545(01) Martinez, CA - Injured Passenger Removal

01OCT25: Train 545(01) was delayed departing Martinez Station when paramedics were requested to assist a passenger. Passenger Daniel Kincheloe (PNR# AB9522) traveling from Sacramento to Martinez fell down stairs while attempting to exit the train. The attending paramedics evaluated the passenger on board before transporting them to a nearby medical facility for treatment. Amtrak Police Notified.

Train	Delay	Comment
545(01)	26"	

Train 14(01) North of Santa Barbara, CA - Occupied Vehicle Strike- Fuel Truck

01OCT25: At approximately 26-FOI-00008 tra00000004607 operatUNCLASSIFIED"era eq10/6/2025 Locomotive AMTK/347, struck an occupied fuel truck. The incident occurred 93 miles north of Santa Barbara in Guadalupe, at Private crossing (DOT # 745393 U) MP 274.97; Santa Barbara Subdivision of the Union Pacific Railroad. The track speed is 60MPH. There were 218 passengers on board with three (03) passengers reporting minor injuries being treated at a nearby medical facility. The driver of the vehicle was treated by paramedics at the scene for serious injuries before being transported to a local hospital for further treatment. Officers from California Highway Patrol Santa Maria Fire Dept and Santa Barbara Co sheriff, responded to investigate, assisted by San Luis Obispo Road Foreman of Engines, and trainmaster. Amtrak Police officer attended the scene along with members of Los Angeles Mechanical Dept. and Drummac contracted services. Locomotive AMTK/347 was unable to provide Head End Power, the ambient temperature at the time of incident was 70° Fahrenheit. The reported (unspecified) damage to the train preventing the train from continuing it's trip to Seattle. There was approx. 3,500 Gallons of Diesel Fuel spilled from the damaged tanker onto the Right of Way requiring specialist cleaning HAZ-MAT crews. Amtrak Police Notified and EAP Notified.

The following alterations to train service applied:

Train 14(01) Terminated at Guadalupe (MP 274.7). All passengers (except San Luis Obispo who were provided Uber Transport) were provided bus transportation back to Origin.

UPDATE: Train 14(01) advanced north to Callender siding Once police released the train.

UPDATE: California Highway Patrol shut down all activity regarding clearing the scene until 8:00AM-PT. As a result the following service modifications have been made. 11(30) was terminated at San Luis Obispo, CA with alternate bus transportation. 3 buses were sourced and arrived on the scene around 3:30AM. 2 buses operated express from San Luis Obispo - Los Angeles, and one bus made all stops San Luis Obispo - LAX.

Once the passengers were boarded onto the buses 11(30) proceeded to Callender siding where is coupled to the south end of 14(01) equipment and the combo sets proceeded to Los Angeles, CA.

Train 774(02) originated Los Angeles, CA and train 761(02) terminated Los Angeles, CA.

Service Recovery: 14(01): As the train was unable to provide Head End Power for hot meals, the catering crews provided sandwiches, potato chips and canned drinks to passengers. Snack Packs and soft drinks were also readily available.

11(30): Regular dinner service was held and snack packs and water was provided to passengers. hotels were provided in Los Angeles, CA for passengers who missed connections.

Train 11(03) Cancelled entirely - with no specific alternate transport offered.

Train 794(01) was replaced by a bus service between San Luis Obispo thru Santa Barbara (not stopping at Lompoc Surf). Train 794(01) resumed from Santa Barbara thru Los Angeles using train equipment turned from 779(01). Passengers travelling beyond Los Angeles were directed to board thruway 5818(01). An 'on-time' section of train 794(01) was operated using equipment turned from train 587(01). Service Recovery: Snack Packs and Bottled water and hot beverages offered to affected passengers.

Train 779(01) Terminated in Santa Barbara - A replacement bus service operated to all missed stops (except Lompoc Surf) to San Luis Obispo.

National Response Centre Number: 1444371

1444377

California Office of Emergency Services: 25-5010

WBS#: B.TR.100150.6148

National Response Center Number: 1444371 - 1444377

Train	Delay	Comment
11(03)	Cancelled	No Specific Alternate Transport
794(01)	On Time Section	Los Angeles - San Diego
779(01)	Terminates Santa Barbara	Passengers to Replacement Buses
794N(01)	Terminates Los Angeles	Passengers to 5818(01)
11(30)	Term	San Luis Obispo
14(01)		Terminates Guadalupe - Passengers Return to Origin on Buses
794(01)	2'58"	Originates Santa Barbara
794(02)	Orig LAX	
761(02)	Term LAX	

Train 7(30) West of Havre, MT - Routing

01OCT25: Train 7(30) was delayed 11 miles west of Havre, MT, on BNSF Hi Line subdivision, due to a damaged crossing at MP 973.6. BNSF reported that a vehicle damaged the concrete at the crossing causing the rail to come unseated from the tie plates. BNSF personnel was dispatched to the area and arrived at 7:32PM. BNSF made temporary repairs to allow train 7(30) to pass. BNSF engineering walked train 7(30) passed the affected area.

Train	Delay	Comment
7(30)	1'37"	

Train 1333(01) East of Red Wing, MN - Freight Train Interference

01OCT25: Train 1333(01) was delayed 21 miles east of Red Wing, MN, at MP349.3, on CPKC River subdivision, due to meeting and following unknown freight train. Once the freight cleared and a route was made available, train 1333(01) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(01)	46"	

Train 532(01) East of Martinez, CA - Marine Traffic

01OCT25: Train 532(01) was delayed 1 mile east of Martinez at Vista MP 33.0 Martinez subdivision of the Union Pacific Railroad. The structure was raised to allow for the passage of marine traffic. Delays were extended for signal problems at MP 35.00 preventing the bridge being lowered between the passage of two ships. Once the vessels had cleared, the bridge was lowered and train 532(01) was able to continue to Suisun.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
532(01)	49"	

Train 21/421(30) Fort Worth, TX - Equipment Move & Passenger Train Interference

01OCT25: Train 21/421(30), E/56-E/139 & 8 cars, was delayed at Fort Worth, TX/MP346.2, on the BNSF Fort Worth Subdivision, adding E/139 in trail, in a planned engine move, then further delayed troubleshooting HVAC issues on E/56 and meeting Train 22(01).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(30)	46"	

Train 14(01) North of Santa Barbara - Passenger Removal – Injury

01OCT25: Train 14(01) made an unscheduled stop 24 miles north of San Luis Obispo at Capitan - MP 343.1, Santa Barbara Subdivision of Union Pacific Railroad. This was to allow local paramedics to assist a pregnant passenger (using a wheelchair) who fell in the ADA bathroom in car C/34515. Passenger Demetria York (PNR# 9D96B2) travelling from Los Angeles to Portland was treated by paramedics on the train before being removed for further evaluation at a nearby hospital. Ms. York was taken to hospital allowing the train to continue to San Luis Obispo.

Delays were extended as the passenger was not an English speaker. Paramedics took longer than expected to locate the train which was stopped in a remote location. Amtrak Police Notified.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(01)	1'55"	

Train 302(01) South of Summit, IL - Freight Train Interference

01OCT25: Train 302(01) was delayed at CP-Canal/MP13.1, 2 miles south of Summit, IL, on the CN Joliet Subdivision, holding for freight cross-traffic to clear ahead.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
302(01)	55"	

Train 22(01) North of Temple, TX - Near Miss with Semi

01OCT25: Train 22(01), E/68 & 7 cars, with 88 passengers, stopped in emergency at MP234.6, 15 miles north of Temple, TX, on the BNSF Fort Worth Subdivision, due to a near miss with a semi. There were reported injuries to passengers or crew and no reported damages. The truck was briefly stuck on track then able to clear. Train 22(01) was further delayed holding for BNSF track inspector to arrive and ok track for movement.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(01)	48"	

Train 381(01) West of Galesburg, IL - Bird Strike

01OCT25: Train 381(01), E/313 & 4 cars, struck a large bird at MP177.4X, 15 miles west of Galesburg, IL, on the BNSF Brookfield Subdivision. There were no reported injuries to passengers (13) or crew. E/313 fireman's windshield was shattered. There were no other exceptions to equipment taken. Train 381(01) continued to Quincy, IL, where a BNSF freight engine, BN E/BN8284, was sourced to be added ahead for the turn of Train 382(01).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
381(01)	None	
382(01)	09"	Departing QCY
382(02)	20"	Operating at reduced Speeds due to Freight.

Train 4(30) East of Flagstaff, AZ - Freight Train Interference

01OCT25: Train 4(30) was delayed east of Flagstaff, AZ/MP344.2, on the BNSF Seligman Subdivision, following eastbound freight traffic between MP320.1 and MP316.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(30)	46"	

Train 8/28(29) East of St. Paul-Minneapolis, MN - Freight Train Interference

01OCT25: Train 8/28(29) was delayed at MP408.9, just east of St. Paul-Minneapolis, MN, on the CPKC Merriam Park Subdivision, waiting on cross-traffic, CPKC 8869, to clear ahead.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(29)	40"	

Train 3(30) West of La Junta, CO - Trespasser Incident

01OCT25: Train 3(30), E/179-E/61 & 11 cars, reported by BNSF, to have had a near miss at MP583.1, 28 miles west of La Junta, CO, on the BNSF Raton Subdivision, with a contractor working on a radio tower fouling the track. There were no reported injuries, damages or delay.

Train 3(30) East of Dodge City, KS - Near Miss with Vehicle

01OCT25: Train 3(30), E/179-E/61 & 11 cars, with 159 passengers, stopped in emergency at MP336.5, 17 miles east of Dodge City, KS, on the BNSF La Junta Subdivision, due to a near miss with a vehicle. There were no reported injuries to passengers or crew. Crew inspected consist and took no exceptions. Train 3(30) was on the move west after crew restored air and performed brake test.

Train 8/28(30) Spokane, WA - Hold for Connection

01OCT25: Train 8/28(30) was delayed departing Spokane, WA/MP71.6 on the BNSF Spokane subdivision meeting the connecting Amtrak 28(30) portion.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(30)	44"	

Train 511(30) East of Portland, OR - Trespasser Incident

01OCT25: Train 511(30) was delayed entering Portland Union Station, OR/MP0.0 on the BNSF Fallbridge subdivision due to a suicidal trespasser. Train 511(30) operated around the wye prior to entering Portland because the two private cars on the rear of the train needed to change direction for the morning service. The crew expired on Hours of Service while holding outside of Portland, OR. and a yard crew was taken by van to meet the train and recrew.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
511(30)	2'45"	

Train 11(30) North of Chemult, OR - Freight Train Interference

01OCT25: Train 11(30) held at Fields siding/MP554.3 50 miles north of Chemult, OR/MP503.1 on the UP Cascade subdivision due to UP freight UP/7643 disabled ahead around mile post 542.0 with no route around. Once the route was open, train 11(30) continued into Chemult, OR.

Train 11(30) was further delayed south of Chemult, OR meeting UP/7162, stopped inspecting a hot wheel, at Yamsay and UP/5335 and Lenz. Train 11(30) operated to Chiloquin for recrew.

Due to the late operation of 11(30) a crew signed up at Portland, OR at 2:00AM PT and took a van to Klamath Falls, OR. for train 14(30).

Train 11(30) was further delayed operating thru Oakland Maintenance Facility (MP 5.6, Niles Subdivision, Union Pacific Railroad). This was to facilitate fueling and daily inspection of locomotives AMTK/339 and AMTK/331. Once completed, train 11(30) rejoined the mainline to resume to Oakland Jack London Square.

Work Element WBS # B.TR.100150.6145

WBS#: B.TR.100150.6145

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(30)	1'18"	
11(30)	44"	Follow UP/7643 to Abernethy
11(30)	27"	Oakland Facility - Locomotives Daily Inspection
11(30)	30"	Oakland Facility Fuel Locomotives

Oakland, CA - Capitol Corridor/San Joaquin Services - Third Party Contractor Engine Failure

23AUG25: Account on-going high shop counts for locomotives of state-support trains in Oakland, the following modifications to service have occurred:

23AUG25:

-Train 714(23) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

24AUG25:

-Train 711(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 716(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive

effort.

- Train 534(25) cancelled - passengers accommodated on later departure of train 534(27).
- Train 549(25) cancelled - passengers accommodated on later departure of train 549(27).
- Train 716(25) locomotive 26-F01-00008 has 00000004607 OMF /"UNCLASSIFIED" CDTX/10/8/2025 add CDTX/2123 (pulled from train 534(25))

26AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 535(26) Operating with CDTX/2007 Providing Head End Power , BNSF/4357 Providing tractive effort;

Delayed west of Sacramento when BNSF/4357 shut down after overspeed warning - PCS and Speedometer not synced.

- Train 535(26) Terminated in Emeryville for locomotives to be added to train 716(26).
- Train 716(26) received CDTX/2007 to provide HEP and BNSF/4357 to provide tractive effort from train 535(16).
- Train 716(26) Originated in Emeryville - Passengers boarding on Oakland provided bus transport to Emeryville.
- Train 534(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 549(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

27AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 715(27) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.
- Train 714 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 717 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 716(27) Originates Emeryville - Extended Servicing from train 711(27).

28AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 534(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 549(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 547(28) 27 Mins late departing Sacramento - Equipment Turn from 536(28) after cancellation of 534(28).
- Train 711(28) was terminated at Emeryville, CA. to turn for an on time 714(28) out of Jack London Square, Oakland, CA.
- Train 712(28) Cancelled after dynamic brake failure on locomotive CDTX/2103.
- Train 717(28) Cancelled - equipment turn from 712(28) (after manipulations)
- Train 714(28) 1 Hour 59 Mins delay while techs resolve compressed air issues with cab car AMTK/90278
- Train 716(30) 30 mins late departing Oakland Jack London - Extended servicing in Oakland Maintenance Facility
- Train 718(30) Originates Emeryville - Techs after replacing door seal on Cab Car CDTX/8305 unable to get 'trainline complete' indication or interior lights - swapped equipment with original 712(30)

29AUG25: Normal Service Operates with No Cancellations

01SEP25:

- Train 714(01) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 711(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

02SEP25:

- Train 714(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 718(02) Delayed Departing Oakland Jack London - Locomotive Wouldn't Start

03SEP25: Following discussions with Amtrak Transportation, Transit America (TASI) and our California State Department of Transportation, it has been determined that a temporary reduction in Capitol Corridor and San Joaquins service is essential to perform necessary inspections, maintenance and repairs on the California state owned locomotives.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 20SEP.

-714 (03-19SEP) CANCELLED

-717 (03-19SEP) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 20SEP.

-520 (04-19SEP) CANCELLED

-534 (04-19SEP) CANCELLED

-535 (04-19SEP) CANCELLED

-549 (04-19SEP) CANCELLED

03SEP25:

- Train 712(03) Cancelled - failure of locomotive CDTX 2101 (oil leak).

- Train 711(04) Cancelled - failure of locomotive CDTX 2101 (oil leak).

04SEP25:

- Train 718(04) Originate EMY - CDTX 2101 & CDTX Failure. -Late operation.

- Train 715(04) Terminate EMY to turn for 718(04).

05SEP25:

-Train 712(05) Cancelled - failure of locomotive CDTX/2106, passengers to 716(05).

-Train 703(05) Cancelled - passengers to earlier train 719(05).

-Train 540(05) Cancelled - passengers to train 542(02).

06SEP25:

-Train 738(06) Cancelled

-Train 745(06) Cancelled

08SEP25: The temporary reduction in Capitol Corridor and San Joaquins service has now been extended though October 4.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 04OCT.

-714 (03SEP-03OCT) CANCELLED

-717 (03SEP-03OCT) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 04OCT.

-520 (04SEP-03OCT) CANCELLED

-534 (04SEP-03OCT) CANCELLED

-535 (04SEP-03OCT) CANCELLED

-549 (04SEP-03OCT) CANCELLED.

15SEP25

To streamline departures and provide a stable service for passengers: Effective 15th September 2025.

Train #547 retimed to depart Sacramento 52 minutes later than advertised at 5:55PM-PT operating 52 mins later throughout to San Jose,.

Train #715 retimed to depart Bakersfield 01 hour later than advertised at 1:12PM-PT operating 52 mins later throughout to Oakland.

These changes will remain thru Saturday 4th October 2025

15SEP25: Train 716(15) Locomotive failed at OKJ. Train returned to OMF and new equipment was sourced. Train originate EMY, pax to train 536(15) OKJ-EMY

Cause: Pending

WBS#: B.TR.100150.6069

Train	Delay	Comment
-------	-------	---------

714 (23)	32"	OKJ - delay departing OMF
714 (23)	21"	Operating at reduced speeds account freight locomotive
716 (23)	25"	Follow 714 (23)
711 (24)	26"	26-FCI-00008-00000004607 UNCLASSIFIED Pax to BUS 711 EMY-19/09/25 SFC
716 (24)	26"	Operating at reduced speeds account freight locomotive.
711 (24)	32"	Reduced operating speeds account freight locomotive
715 (25)	27"	W. FNO - PTC Issue on freight loco
534 (25)	CANCELLED	Pax to 536 (25)
549 (25)	CANCELLED	Pax to 551 (25)
716 (25)	1'03"	Loco change at OMF
715 (25)	23"	Operate with freight locomotive
715 (25)	17"	SKN - Freight loco air compressor issue
535 (26)	41"	West Sac - Recovery from BNSF/4357 Penalty Brake
534 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
716 (26)	1'57"	Originates Emeryville - Receiving CDTX/2007 and BNSF/4357 from 535 (26)
535 (26)	Terminates Emeryville	Oakland Passengers to 537 (26)
549 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
545 (26)	11"	SAC - Short turn of 536 (26) after 534 (26) cancelled
716 (26)	43"	Restricted not to exceed 65 mph with BNSF/4357
714 (27)	Cancelled	
717 (27)	Cancelled	
716 (27)	Originates Emeryville	Passengers to 534 (27)
715 (27)	524"	Restricted not to exceed 65 mph with BNSF/4357
715 (27)	28"	Oakley - BNSF/4357 - Penalty Brake Application Overspeed
534 (28)	Cancelled	
549 (28)	Cancelled	
711 (28)	Term EMY	
712 (28)	Cancelled	Dynamic Brake Failure
717 (28)	Cancelled	Cancellation of 712 (28))
714 (28)	1'59"	OKJ - Techs Resolve Compressed Air Issues
716 (28)	30"	OKJ - Extended Servicing Oakland Maintenance Facility
718 (28)	1'48"	EMY - Swapped Equipment after failed door seal replacement -Originates EMY
547 (28)	27"	SAC - Equipment Turn From 536 (28) after 534 (28) cancelled
714 (02SEP)	Cancelled	
717 (02SEP)	Cancelled	
714 (01SEP)	Cancelled	
711 (02SEP)	Cancelled	
718 (02SEP)	31"	OKJ - Locomotive CDTX/2103 would not start
534 (02SEP)	40"	OKJ - Locomotive Compressed air Issues
712 (03SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
711 (04SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
718 (04SEP)	2'09"	originate EMY
715 (04SEP)		Terminate EMY
712 (05SEP)	CANCELLED	Passengers to 716 (05SEP)
703 (05SEP)	CANCELLED	Passengers to earlier 719 (05SEP)
540 (05SEP)	CANCELLED	Passengers to 542 (05SEP)
716 (05SEP)	1'15"	OKJ - late departure
738 (06SEP)	CANCELLED	
745 (06SEP)	CANCELLED	
549 (04SEP-03OCT)	Cancelled	
535 (04SEP-03OCT)	Cancelled	
534 (04SEP-03OCT)	Cancelled	
520 (04SEP-03OCT)	Cancelled	
717 (03SEP-03OCT)	Cancelled	
714 (03SEP-03OCT)	Cancelled	
547 (08SEP)	36"	SAC - ITD - Equipment from 536 (08)
715 (09SEP)	1'21"	BFD - ITD - Equipt from 702 (09)
547 (09SEP)	13"	SAC - ITD - Equipt from 536 (09)
715 (10SEP)	47"	BFD - ITD - Equipt from 702 (10)
547 (10SEP)	25"	SAC - ITD - Equipment from 536 (10)
715 (11SEP)	1'15"	BFD - Equipment Turn From 702 (11)
547 (11SEP)	21"	SAC - ITD - Equipment from 536 (11)

Train	Delay	Comment
716 (15SEP)	1'49"	Loco Failed
715 (16SEP)	16"	BFD- ITD - Equipment Turn from 702 (16)

26-FOI-00008 00000004607 "UNCLASSIFIED" 10/6/2025

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work - City of New Orleans

26-FBI-09089 7000004607 "UNCLASSIFIED" 10/6/2025

05OCT25: CN will have multiple work gangs on the CN Yazoo Subdivision, between Memphis, TN and Jackson, MS, working 5-hour work windows beginning Monday October 6th through Thursday October 9th. To accommodate this work, City of New Orleans Service adjusted as follows:

- Train 1059(05) will operate in lieu of Train 59(05), departing Chicago, IL, 2 hours earlier at 605PM-CT and will operate on an adjusted schedule to New Orleans.
- Train 59(06-08) will depart Chicago 2 hours earlier at 605PM-CT and operate on an adjusted schedule to New Orleans.
- Train 1058(06) will depart New Orleans, LA, 2 hours earlier at 1145AM-CT and operate on an adjusted schedule to Chicago.
- Train 58(07-09) will depart New Orleans 2 hours earlier at 1145AM-CT and operate on an adjusted schedule to Chicago.

WBS#: B.TR.100150.6117

Canadian National Holly Subdivision - Pontiac Station Track Project

02SEP25: September 2nd thru September 30th, Canadian National will be performing a track project at the Pontiac, MI station. Updated 24SEP25 to extend through October 15th. The follow trains will originate and terminate at Troy, MI:

Train 350 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep -28Sep, 03Oct- 05Oct, 10Oct - 12Oct) will terminate Troy, MI.

Train 352 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 354 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 351 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

Train 353 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep - 28Sep, 03Oct - 05Oct, 10Oct - 12Oct) will originate Troy, MI

Train 355 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

There will be NO alternate transportation provided.

WBS#: B.TR.100150.6045

Michigan Department of Transportation Michigan Line affecting Wolverine Service - Scheduled M/W Work

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

05MAY25: Amtrak will be performing a track rehabilitation by modifying a curve between Chelsea, MI / MP 56.0 and Ypsilanti, MI / MP 28.2, which encompasses the Ann Arbor, MI station at MP 37.5, on the Michigan Department of Transportation Michigan Line. The follow operating plan will be placed in to effect:

May 5th through June 26th (except for May 26th and June 19th):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

August 4th through October 30th (except for September 1st):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

WBS#: B.TR.100150.5512

Train	Delay	Comment
350 & 353(27MAY - 29MAY)	Cancel	
350 & 353(16JUN - 18JUN)	Cancel	
350 & 353(23JUN - 26JUN)	Cancel	
350 & 353(04AUG - 07AUG)	Cancel	
350 & 353(11AUG - 14AUG)	Cancel	
350 & 353(18AUG - 21AUG)	Cancel	
350 & 353(25AUG - 28AUG)	Cancel	
350 & 353(02SEP - 04SEP)	Cancel	
350 & 353(08SEP - 11SEP)	Cancel	
350 & 353(15SEP - 18SEP)	Cancel	
350 & 353(22SEP - 25SEP)	Cancel	
350 & 353(29SEP - 02OCT)	Cancel	
350 & 353(06OCT - 09OCT)	Cancel	
350 & 353(13OCT - 16OCT)	Cancel	
350 & 353(20OCT - 23OCT)	Cancel	
350 & 353(27OCT - 30OCT)	Cancel	

Western Region

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
				None

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
382 (1)	QCY	BN8284	E/313 strike damage F/S windshield	CHI	10/02/25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 381(01) Passenger Meet by EMS at Mendota, IL - Medical

01OCT25, Passenger on PNR A9F6E7, traveling from Chicago, IL to Galesburg, IL appeared to have a seizure and was unresponsive. EMS meet train at Mendota, IL and was cleared to travel. Amtrak Police notified.

Delay: 381(01) 05"

Train 25(01) Passenger Removal at Bay Saint Louis, Mississippi -Intoxication

01OCT25, Passenger on PNR AADAA4, traveling from Mobile, AL to New Orleans, LA was removed from the train by Police. The passengers were indoctrinated and being belligerent. The passengers were using profanity towards one another and speaking inappropriately to the conductor. Amtrak Police notified.

Delay: 25(01) 11"

Train 27(01) Passenger Removal at Portage, Wisconsin -Improper Conduct

01OCT25, Passenger on PNR A6C9BE, traveling from Chicago, IL to Portland, OR was removed from the train by Portage PD. The passenger was asked to use headphones while using their cellular device. The passenger yelled inappropriate verbiage at the conductor after the third attempt by conductor. Amtrak Police notified.

Delay: 27(01)

None
26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Train 14(01) Passenger Removal at Santa Barbara, California -Medical

01OCT25, Train 14(01) made an unscheduled stop 24 miles north of San Luis Obispo at Capitan - MP 343.1, Santa Barbara Subdivision of Union Pacific Railroad. This was to allow local paramedics to assist a pregnant passenger (using a wheelchair) who fell in the ADA bathroom in car C/34515. Passenger Demetria York (PNR# 9D96B2) travelling from Los Angeles to Portland was treated by paramedics on the train before being removed for further evaluation at a nearby hospital. Ms. York was taken to hospital allowing the train to continue to San Luis Obispo. Delays were extended as the passenger was not an English speaker. Paramedics took longer than expected to locate the train which was stopped in a remote location. Amtrak Police Notified.

Delay: 14(01) 1' 55"

Train 545(01) Passenger Removal at Martinez, California -Medical

01OCT25, Train 545(01) was delayed departing from Martinez Station when paramedics were requested to assist a passenger. Passenger Daniel Kincheloe (PNR# AB9522) traveling from Sacramento to Martinez fell downstairs while attempting to exit the train. The paramedics evaluated the passenger on board before transporting them to a nearby medical facility for treatment. Amtrak Police Notified.

Delay: 545(01) 36"

Consist Deviations

26-FOI-00008

00000004607

"UNCLASSIFIED"

10/6/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
572 (01)	LAX	No bags or bikes due to broken doors.	N/A	1	90215
98 (01)	MIA	DUE TO INOPERABLE HVAC SYSTEM IN DINING CAR 68011, SERVICE RECOVERY HAS BEEN ENACTED AT JACKSONVILLE, FL AND CONSISTS OF FIRST CLASS PASSENGERS RECEIVING POPEYES CHICKEN, RED BEANS AND RICE, COLESLAW, AND DINNER ROLLS. BEVERAGES WERE PROVIDED AS WELL.			68011
97 (01)	NYP	Rom B on 97(01) line 9710-car 62025 has a broken chair off the rails. HIA must repair or replace upon arrival	N/A	0	62025
3 (30)	RAT	No working toilets in sleepers. Sleeper sales closed.			32090,32117
785 (01)	SAN	No bags or bikes due to broken doors.	NO BIKE	1	90215

Reverse Consists

Train Number	Station	Reason	Customer Impact	Affected Psgr
173 (01)	BOS	Consist reversed Business class oriented normal At Front	N/A	0
183 (01)	NYP	Consist reversed Business class oriented normal At Front	N/A	0
190 (01)	PHL	Consist reversed Business class oriented normal At Front	N/A	0
2107 (01)	NYP	Acela consist reversed First class at Rear	N/A	0
2107 (01)	NYP	Acela consist reversed First class at Front	N/A	0
175 (01)	BOS	Consist reversed Business class oriented backward At Front	N/A	0