



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, October 03, 2025

Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/02/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	45	84.6%	585	97	83.4%	585	97	83.4%
Central Division	85.5%	66	13	80.3%	131	22	83.2%	131	22	83.2%
Northeast Division	80.0%	92	16	82.6%	185	40	78.4%	185	40	78.4%
Southeast Division	72.5%	70	4	94.3%	140	8	94.3%	140	8	94.3%
Southwest Division	77.0%	64	12	81.3%	129	27	79.1%	129	27	79.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00008 00000004606 UNCLASSIFIED 10/6/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	80,757	11,704	86%	168,495	26,444	84%	168,495	26,444	84%
Northeast Corridor	81%	35,959	3,411	91%	77,727	8,386	89%	77,727	8,386	89%
Acela	83%	7,456	1,060	86%	16,146	1,876	88%	16,146	1,876	88%
Northeast Regional	79%	28,503	2,351	92%	61,581	6,510	89%	61,581	6,510	89%
Richmond / Newport News / Norfolk	77%	9,810	1,845	81%	20,296	3,420	83%	20,296	3,420	83%
Springfield Shuttles	89%	509	10	98%	1,171	181	85%	1,171	181	85%
Roanoke	79%	2,515	274	89%	5,031	975	81%	5,031	975	81%
On Spine Northeast Regional	80%	15,669	222	99%	35,083	1,934	94%	35,083	1,934	94%
State Supported	80%	34,939	5,800	83%	71,028	11,824	83%	71,028	11,824	83%
Borealis	60%	563	397	29%	1,043	541	48%	1,043	541	48%
Capitol Corridor	90%	3,144	41	99%	6,843	595	91%	6,843	595	91%
Carolinian	60%	994	343	65%	1,790	617	66%	1,790	617	66%
Cascades	63%	1,810	420	77%	3,591	818	77%	3,591	818	77%
Downeaster	82%	1,163	0	100%	2,367	71	97%	2,367	71	97%
Empire	78%	4,483	1,077	76%	9,024	2,583	71%	9,024	2,583	71%
Adirondack	72%	287	142	51%	544	293	46%	544	293	46%
Ethan Allen Express	70%	453	16	96%	995	526	47%	995	526	47%
Maple Leaf	70%	598	242	60%	1,151	416	64%	1,151	416	64%
New York - Albany	85%	2,108	258	88%	4,185	638	85%	4,185	638	85%
New York - Niagara Falls	75%	1,037	419	60%	2,149	710	67%	2,149	710	67%
Heartland Flyer	65%	139	66	53%	268	151	44%	268	151	44%
Hiawatha	90%	1,448	635	56%	3,017	1,182	61%	3,017	1,182	61%
Illinois	78%	2,176	339	84%	4,000	850	79%	4,000	850	79%
Carl Sandburg / Illinois Zephyr	85%	306	154	50%	563	351	38%	563	351	38%
Illini / Saluki	85%	733	1	100%	1,337	7	99%	1,337	7	99%
Lincoln Service	70%	1,137	184	84%	2,100	492	77%	2,100	492	77%
Keystone	92%	7,784	117	98%	16,980	559	97%	16,980	559	97%
Lincoln / Missouri	60%	644	489	24%	1,247	709	43%	1,247	709	43%
Mardi Gras Service	80%	351	161	54%	684	313	54%	684	313	54%
Michigan	69%	1,428	106	93%	2,722	106	96%	2,722	106	96%
Blue Water	70%	411	33	92%	740	33	96%	740	33	96%
Pere Marquette	85%	224	0	100%	484	0	100%	484	0	100%
Wolverine	65%	793	73	91%	1,498	73	95%	1,498	73	95%
Missouri	80%	140	84	40%	274	98	64%	274	98	64%
Pacific Surfliner	85%	4,441	170	96%	8,632	388	96%	8,632	388	96%
Pennsylvanian	72%	705	349	50%	1,502	349	77%	1,502	349	77%
Piedmont	73%	746	123	84%	1,366	221	84%	1,366	221	84%
San Joaquins	73%	1,645	705	57%	3,249	1,493	54%	3,249	1,493	54%
Vermont	75%	1,135	178	84%	2,429	180	93%	2,429	180	93%
Long Distance	56%	9,859	2,493	75%	19,740	6,234	68%	19,740	6,234	68%
Auto Train	57%	578	226	61%	1,117	226	80%	1,117	226	80%
California Zephyr	50%	813	28	97%	1,718	90	95%	1,718	90	95%
Cardinal	55%	324	24	93%	529	143	73%	529	143	73%
City Of New Orleans	75%	625	76	88%	1,093	159	85%	1,093	159	85%
Coast Starlight	60%	860	415	52%	1,317	519	61%	1,317	519	61%
Crescent	70%	683	60	91%	1,275	248	81%	1,275	248	81%
Empire Builder	55%	951	426	55%	1,988	892	55%	1,988	892	55%
Floridian	40%	1,196	36	97%	3,007	1,438	52%	3,007	1,438	52%
Lake Shore Ltd	73%	753	0	100%	1,512	180	88%	1,512	180	88%
Palmetto	65%	782	143	82%	1,495	163	89%	1,495	163	89%
Silver Meteor	45%	724	250	65%	1,350	250	81%	1,350	250	81%
Southwest Chief	40%	769	601	22%	1,524	1,353	11%	1,524	1,353	11%
Sunset Ltd	70%	0	0	-	258	2	99%	258	2	99%
Texas Eagle	50%	801	208	74%	1,557	571	63%	1,557	571	63%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FD-000000 000000000000 "UNCLASSIFIED" 10/0/2025

Train Index Dates Through October 02, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	8,520	210,937	404	8,520	210,937	404

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	269	61,962	43	269	61,962	43
INFRASTRUCTURE PLANNED	130	182	61,962	29	182	61,962	29
FLEET RELIABILITY	90	1,196	210,937	57	1,196	210,937	57
TRAIN OPERATIONS	427	6,873	210,937	326	6,873	210,937	326

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/02/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	45	84.6%	585	97	83.4%	585	97	83.4%
Central Division	85.5%	66	13	80.3%	131	22	83.2%	131	22	83.2%
Northeast Division	80.0%	92	16	82.6%	185	40	78.4%	185	40	78.4%
Southeast Division	72.5%	70	4	94.3%	140	8	94.3%	140	8	94.3%
Southwest Division	77.0%	64	12	81.3%	129	27	79.1%	129	27	79.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak or Commuter: **Amtrak**

2.1 of 2.2

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/02/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	45	84.6%	585	97	83.4%	585	97	83.4%
Southeast Division	72.5%	70	4	94.3%	140	8	94.3%	140	8	94.3%
RNK	85.5%	2	1	50.0%	4	1	75.0%	4	1	75.0%
RVM	86.0%	1	0	100.0%	2	1	50.0%	2	1	50.0%
SAV	91.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
SFA	70.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
WAS	70.0%	23	2	91.3%	45	3	93.3%	45	3	93.3%
Southwest Division	77.0%	64	12	81.3%	129	27	79.1%	129	27	79.1%
ARN	60.5%	1	0	100.0%	2	1	50.0%	2	1	50.0%
BFD	75.5%	5	1	80.0%	10	4	60.0%	10	4	60.0%
EMY	50.0%	1	0	100.0%	2	1	50.0%	2	1	50.0%
FTW	89.5%	1	0	100.0%	2	0	100.0%	2	0	100.0%
GTA	72.5%	3	1	66.7%	6	2	66.7%	6	2	66.7%
LAX	77.5%	10	4	60.0%	20	6	70.0%	20	6	70.0%
OKC	96.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
OKJ	79.0%	9	3	66.7%	18	4	77.8%	18	4	77.8%
SAC	73.5%	12	2	83.3%	24	3	87.5%	24	3	87.5%
SAN	77.0%	12	0	100.0%	24	1	95.8%	24	1	95.8%
SAS	85.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
SJC	87.5%	7	1	85.7%	14	4	71.4%	14	4	71.4%
SLO	62.0%	1	0	100.0%	3	1	66.7%	3	1	66.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	130	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
4		2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
5		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
6		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
7		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
8		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
11		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
14	Cncld	2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
19		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
20		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
21		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
22		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
23	26	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
24	28	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
25		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
26		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
27	84	2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
28		2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
40		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
41		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
42	22	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
43		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
48		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
49		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
51		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
52	173	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
53		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
55		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
56		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
58		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
59		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
63	32	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
64	88	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
66		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
67		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
68	26	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
69		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
71		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
72		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
73	30	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
74		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
75		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
77		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
78		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
79		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
80		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
84		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
85	60	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
86	28	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
89		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
90		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
93		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
94		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
95		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
97		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
98		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
110		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
111		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
112		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
114		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
119		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
125		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
129		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
130		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
131		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
133		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
134		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
136		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
138		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
141		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
148		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
151		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
171		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
172		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
173		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
174		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
175		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
176		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
177	31	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
178		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
179		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
181		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
182		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
184		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
185		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
186		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
190		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
192		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
193		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
196		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
197		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
232		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
233		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
234		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
236		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
237		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
239		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
240		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
241		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
243		2	2	0.0%	2	2	0.0%	3	1	66.7%	3	1	66.7%
244		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
280	21	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
281	26	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
283	19	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
284		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
290		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
291		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
300		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
301		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
302		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
305		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
306		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
307		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
311	22	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
316		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
318		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
319	54	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
329		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
330		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
331	11	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
332		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
334		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
335	25	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
336	13	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
337		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
338	47	2	2	0.0%	2	2	0.0%	2	2	0.0%	2	2	0.0%
339	39	2	2	0.0%	2	2	0.0%	2	1	50.0%	2	1	50.0%
341	63	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
342	18	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
351		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
352	32	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
354		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
355		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
364	17	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
365		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
370		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
371		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
380		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
381	159	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
382		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
383	32	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
390		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
391		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
392		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
393		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
417	Cncld	2	2	0.0%	2	2	0.0%	1	0	100.0%	1	0	100.0%
425	33	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
470		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
471		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
473		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
474	Cncld	2	2	0.0%	2	2	0.0%	1	0	100.0%	1	0	100.0%
475		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
478		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
479		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
486		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
494		3	3	0.0%	3	3	0.0%	2	1	50.0%	2	1	50.0%
495		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
500		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
502		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
503	56	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
504		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
505		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
506	20	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
507	16	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
508		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
509		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
511		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
516		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
517	34	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
518		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
519		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
521		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
522		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
523		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
524		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
525		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
526		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
527		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
528		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
529		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
531		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
532		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
536		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
537		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
538		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
540		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
541		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
542		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
543		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
544		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
545		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
546		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
547		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
548		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
551		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
562		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
564		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
566		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
572		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
573		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
577		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
580		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
581		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
582		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
586		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
587		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
591		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
593	No OS	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
595	No OS	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
600	12	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
601		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
605		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
607		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
609		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
620		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
624		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
639		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
640		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
641		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
642		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
643		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
644		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
645		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
646		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
647		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
648		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
649		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
650		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
651		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
652		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
653		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
654		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
655		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
656		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
657		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
658		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
680		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
681		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
682	12	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
685		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
686		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
687		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
688		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
689		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
702	20	2	1	50.0%	2	1	50.0%	2	2	0.0%	2	2	0.0%
703	No OS	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
710	28	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
711		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
712	88	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
713		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/2/2025

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
715	34	2	2	0.0%	2	2	0.0%	2	2	0.0%	2	2	0.0%
716		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
718	32	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
719		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
761		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
765		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
769		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
770		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
774		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
779		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
784		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
785		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
790		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
794		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
821		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
822	36	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
1333	31	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
1340	61	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2103		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2107		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
2108		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2121		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2122		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2124		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2150		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2151		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2153		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2154		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2155	36	2	0	100.0%	2	0	100.0%	1	1	0.0%	1	1	0.0%
2159		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2162		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2163		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2166		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2167		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2168	38	2	0	100.0%	2	0	100.0%	2	2	0.0%	2	2	0.0%
2170		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2172	21	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
2173		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
2190		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2193		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%

Amtrak Endpoint OTP Details

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/2/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2155	WAS	36	UTL	15	UTL	15	PVD-XGX	AM	Commercial power outage, Other, CRANSTON AREA
2168	BOS	38	ENG	44	ENG	44	BAL-BAL	AM	Unrecoverable penalty (PCS), 2168, HIGH SPEED TECH REQUESTED FOR AN UNRECOVERABLE PENALTY ANFTER ATTEMPTS TO RECYCLE ENGINE WERE UNSUCCESSFUL
2172	BOS	21	ENG	51	ENG	21	PHL-XHM	AM	Other electrical failure, PC/2038, Aces issues, Necessary to WYE
85	RVM	60	DBB	38	DBB	38	PVD-OSB	AM	Stuck open bridges, Bridge, Thames River
86	BOS	28	CTI	21	CTI	17	PVD-RTE	AM	Follow, MBTA, 856, Milepost w/Letters, pvd, rte, AM86 followed signals of MT856 Junction - Cove
177	PHL	31	CON	35	CON	35	NHV-NHV	MN	Hold for thruway bus
417	NHV	Trn Cancelled							
425	SPG	33	ENG	47	ENG	40	GFD-GFD	MA	Traction motor 97
474	SPG	Trn Cancelled							
52	LOR	173	TRS	177	TRS	177	XDD-XPX	CS	Vehicle strike Other, A726.7
600	NYP	12	CCR	20	CCR	20	NWK-NYP	AM	Unrecoverable penalty (PCS), 9633, ACSES PENALTY ON CC9633
682	BON	12	DCS	5	DCS	3	FRE-POR	CS	Restrictive signal(s) from unknown cause Approach, Other, allen ave
63	TWO	32	OTH	17	OTH	13	AMS-AMS	CS	Passenger removed by emts do to medical emergency
64	ALB	88	FTI	41	FTI	21	SYR-ROM	CS	Meet csxt, Control Point, 283
68	NYP	26	CTI	23	CTI	19	POU-CRT	MN	Follow Metro North, Milepost, 65, 33.3
280	NYP	21	DSR	24	DMW	20	POU-CRT	MN	Held for or routed around MW work or equipment Held at CP 53 account MN Track Car ahead. Single track, held for one NB MN train then run around Track Car., Control Point, 53
281	NFL	26	FTI	50	FTI	50	ROM-SYR	CS	Meet csx i002, Control Point, 278
283	NFL	19	FTI	45	FTI	22	XSV-ROC	CS	Cross over or go around - Flow freight from CP 300 to CP 323 - Crossover 1 to 2 @ CP 323 - Crossover 2 to 1 @ CP 334, CSX, Milepost w/Letters, CP 300, CP 334

Amtrak Endpoint OTP Details

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/2/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
42	NYP	22	FTI	32	FTI	32	XNN-HAR	NS	Follow NS 28X, Milepost, 114, 105
73	CLT	30	INJ	30	INJ	30	DNC-BNC	NS	Injured or sick passenger
23	NOL	26	FTI	43	FTI	31	XNO-XEJ	NS	Meet Control Point, NOT Junction, AMTK 20
24	MOE	28	FTI	34	FTI	34	PAG-MOE	CS	Meet csx L80102, Milepost, 687.4, 685.6
503	EUG	56	FTI	42	FTI	16	PDX-PDX	UP	UP engine/train ID unknown in the control point at CPS001. Train clearing to the Graham line at CPS001., UP engine unknown, Control Point, CPS000
506	SEA	20	SVS	15	SVS	15	PDX-VAN	BN	Wyed the train at T6 due to 7910 having a cracked windshield
507	EUG	16	FTI	13	PTI	13	PDX-ORC	UP	Meet 508, Control Point, clackamas
517	PDX	34	FTI	27	FTI	27	KEL-VAN	BN	Meet Single tracking FELIDA to FRUIT VALLEY, UP 5994, Control Point, FELIDA
14	KFS	Trn Cancelled	PTI	5	PTI	5	VNC-SIM	SC	Meet 774, Control Point, Santa Suzanna
27	PDX	18	DMW	66	DMW	66	SPK-XPW	BN	Hold for defect repair Milepost, 21.5, 31.4
822	OKC	36	FTI	33	DSR	19	FTW-GLE	BN	Per bulletin Milepost, 347.7, 350.6, 30, m1, Milepost, 354, 354.5, 40, m1, Milepost, 354.8, 354.9, 30, m1, Milepost, 355.6, 355.8, 40, m2, Milepost, 356.5, 356.8, 60, m2, Milepost, 357.5, 357.9, 60, m2, Milepost, 359.2, 360, 30, m2, Milepost, 364.7, 364.8, 30, m1, Milepost, 372.2, 372.3, 25, m, Mile
331	MKE	11	DCS	16	DCS	9	GLN-XRO	ME	Issue with automatic road crossing protection #8153, 8152, 8161 - Item #1's, Milepost, 23.92, 24.36
335	MKE	25	CTI	30	CTI	15	GLN-XRO	ME	Follow Metra, 2117, Milepost, 17.4, 29.1
336	CHI	13	CTI	18	CTI	10	XWA-X9L	ME	Follow Metra, Control Point, X9L
338	CHI	47	ITI	25	ITI	25	MKE-MKE	CP	Service, turn, or wye train 335
339	MKE	39	ITI	41	ITI	41	CHI-CHI	AM	Service, turn, or wye train 338
341	MKE	63	ITI	34	ITI	34	CHI-CHI	AM	Service, turn, or wye train 1340
342	CHI	18	ITI	15	ITI	15	MKE-MKE	CP	Service, turn, or wye train 339
352	TRM	32	CAR	23	CAR	23	DER-DER	MI	Air / Brake / Wheel ID4006, Inspect for flat spots 4006/4317
364	PTH	17	FTI	22	FTI	22	LPE-PTH	CC	Follow CN3412, Control Point, E. Emmett
593	LAX	No OS Rpt	TRS	64	TRS	64	FUL-FUL	BN	Trespasser strike Holding due to Metrolink strike, Control Point, Valley View

Amtrak Endpoint OTP Details

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/2/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
595	LAX	No OS Rpt	HLD	1	HLD	1	OLT-OLT	SN	Passenger and/or baggage	
702	BFD	20	FTI	25	FTI	25	MDR-FNO	BN	Meet BN 7164, Siding, Gregg	
703	SAC	No OS Rpt	FTI	99	FTI	68	SKT-SKT	UP	Freight crew re crew Other, skt, 6934N, UPRR	
710	BFD	28	FTI	25	FTI	25	WAC-BFD	BN	Follow Followed BNSF E from Una to Gomez, Control Point, Una X/O, BNSF 7011 E, ZNBYWSP9	
712	BFD	88	SYS	50	TEN	50	OKJ-OKJ	UP	Failure of diesel engine C2001	
715	OKJ	34	PTI	23	FTI	19	BFD-WAC	BN	Follow westbound bnsf, Control Point, bakersfield	
718	BFD	32	DCS	12	ADA	5	EMY-EMY	UP	Wheelchair Unannounced wheel chair	
4	CHI	130	FTI	108	CAR	67	LAX-LAX	SC	Set out defective car 34014, Car had smoke coming out of it. Switched out in yard for good car 34109,	
381	QCY	159	ENG	154	ENG	154	CHI-XUA	AM	PTC - On Board Cab Signal or PTC Failure ID4618	
383	QCY	32	CTI	20	CTI	11	LAG-NPV	BN	Follow Metra, Control Point, E NPV	
311	KCY	22	OTH	15	OTH	15	STL-STL	TR	Station agents said they were shorthanded. Received first passengers on the platform at 0808. Had to hold for multiple meet and assist.	
319	KCY	54	FTI	62	FTI	29	XW1-XWR	UP	Meet UP 6925, Control Point, WR Tower	
1333	MSP	31	DSR	23	DSR	10	XH8-MSP	CP	Per bulletin GTB No.18981, Milepost, 393.6, 393.9, 30, main 1, Milepost, 397.5, 397.8, 30, main 1, Milepost, 401.0, 401.3, 30, main 1, Milepost, 410.5, 410.6, 10, hastings lead	
1340	CHI	61	DBS	52	DBS	52	CBS-MKE	CP	Debris strike Multiple cars hoses apart, Large tree, Other, MP 119	

Amtrak Initial Terminal Details

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/2/2025

Terminal	Train	Date	Late	Delay	Cause
LOR	53	10/02	2	2	Routine inspections Let turn of equipment (52), Milepost, 92.1, 92.1
RNK	66	10/02	5	5	Cross Traffic NS 7680, Other, RNK
WAS	178	10/02	4	4	Set out defective car, 82665, SHOPPED B/O #5 WHEEL
WAS	182	10/02	1		
BON	1689	10/02	2	2	Door 82662, B end door on handbrake side has bent metal that prevents the door from fully closing. Bent metal is affecting the door sensors. I walked to the door and gave it a push after keying doors to close for departure, and it fully shut. On the move 2 min late.
GFD	425	10/02	40	40	Traction motor 97
NHV	470	10/02	1		
NHV	474	10/02	(Trn Cxld)		Locomotive Failure
NHV	478	10/02	3	3	Mobility Impaired, last min special service request for mobility impaired psngrs
NHV	486	10/02	1		
NHV	494	10/02	7	7	Wheelchair, AM494 delayed due to wheelchair psngr from AM2170 transferring over
NYP	97	10/02	13	13	Power switch failure, Other, NYP-NYP, OUT LATE HELD AT "F" A/C DC SWITCHING AT "JO"
NYP	243	10/02	2	2	Passenger and/or baggage, LATE BOARDING PSGR
NYP	281	10/02	12	12	Loading problem, 104, UNSPECIFIED PROBLEM WITH ENG.104 SWITCHING TO DIESEL
NYP	643	10/02	3	3	Passenger and/or baggage, LOADING
NYP	645	10/02	3	3	Door, 00000, DOOR LIGHTS THROUGHOUT TRAIN OPERATING IN BYPASS
NYP	649	10/02	13	13	Conductor working alone/crew shortage., LATE FROM SSYD A/C CREW SHORTAGE
NYP	2107	10/02	2	2	Door, N/A, AS PER CNDR, DOOR ISSUE, UNSPECIFIED DOOR/CAR
SPG	417	10/02	(Trn Cxld)		Locomotive Failure
WEM	686	10/02	6		
CHI	5	10/02	42	42	Diner had missing stock that was reported at 127pm
CHI	7	10/02	4		
CHI	48	10/02	2	2	Unticketed or fare evading passenger PNR 5C27AF. Cynthia Ralls 4811/H sleeping car res NOT PAID FOR, pax was aware res was not paid for due to a credit card issue and came out last minute to evade fare and utilized wheelchair LIFT causing delay to train., Other, CUS
CHI	307	10/02	2	2	Door ID4129, Door wouldn't close with key. Had to close door from the outside

Amtrak Initial Terminal Details

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/2/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	339	10/02	41	41	Service, turn, or wye train 338
CHI	341	10/02	34	34	Service, turn, or wye train 1340
CHI	352	10/02	1		
MKE	338	10/02	25	25	Service, turn, or wye train 335
MKE	342	10/02	15	15	Service, turn, or wye train 339
PDX	28	10/02	3	3	Water, commissary, toilet/trash dumping Other, Portland Union Station
SEA	503	10/02	5	5	HEP HEP was not coming on. Then car 82552 was not powering on. Mechanic was able to fix both issues at 6:50 a.m, 193
STL	311	10/02	15	15	Station agents said they were shorthanded. Received first passengers on the platform at 0808. Had to hold for multiple meet and assist.
TRM	355	10/02	9		
BFD	715	10/02	2	2	Service, turn, or wye train 702
GTA	770	10/02	1	1	Passenger and/or baggage
LAX	562	10/02	3	3	Door 6800, Bad micro switch in door 1.
LAX	572	10/02	3		
LAX	580	10/02	1		
LAX	582	10/02	1		
OKJ	526	10/02	3	3	Meet 527, Control Point, North Jack London
OKJ	548	10/02	1		
OKJ	712	10/02	100	50	Failure of diesel engine C2001
OKJ	712	10/02	100	50	PTC problem or failure (cause unknown) After equipment swap Unable to initialize PTC. Timed out 5+ times + breaker reset., Other, OMF
SAC	541	10/02	2	2	Door C6961, Unable to obtain closed door circuit for departure. Traced to doors 7 and 8 in cab car 6961, which were found stuck in the open position despite showing a door closed light locally.
SAC	702	10/02	1	1	Wheelchair
SJC	544	10/02	1	1	Erroneous delay due to rounding error. Departed on-time at 5:05p.

Eastern Region

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.0	99.2	94.8	309	3
CDOT	95.0	95.0	97.5	92.4	20	1
MARC	95.0	96.5	95.6	83.5	57	2
SEPTA	95.0	98.2	97.9	91.5	218	4
NJT-NED	95.0	95.03	93.9	93.8	362	18
NJT-SED	95.0	100	97.9	97.2	24	0

Operating Highlights

Train 40(02) North of Savannah, GA - Freight Train Interference

03OCT25: Train 40(02) operating with engines 351, 314, and 10 cars was delayed 16 miles north of Savannah, GA on the CSX Columbia subdivision meeting CSX freight M692-02 at Stillwell milepost 474.5. Train 40(02) then met train 41(01) at South Gifford milepost 443.3.

Train	Delay	Comment
40 (02)	1'00"	

Train 41(01) South of Camden, SC - Freight Train Interference

03OCT25: Train 41(01) operating with engines 315, 169, and 10 cars was delayed 50 miles south of Camden, SC on the CSX Hamlet subdivision meeting cross freight traffic at milepost 359.3.

Train	Delay	Comment
41 (01)	45"	

Train 98(02) North of Savannah, GA - Freight Train Interference

02OCT25: Train 98(02) operating with engines 365, 168, and 10 cars was delayed 8 miles north of Savannah, GA on the CSX Charleston subdivision holding at Chatham siding milepost 481.0 meeting CSX 491.

Train	Delay	Comment
98 (02)	30"	

Train 177(02) New Haven, CT - Hold for Connection

02OCT25: Train 177(02) was delayed departing New Haven, CT due to delayed arrival of thruway bus.

Train	Delay	Comment
177 (02)	35"	

Train 97(02) Ashland, VA - Engine Failure

02OCT25: Train 97(02) operating with engine 373, 10/6/2025 and 11 cars was delayed at Ashland, VA station on the CSX RFP subdivision due to ground fault codes on lead engine 373. The crew reported that HEP was lost at 9:23 p.m. and the train coasted into the Ashland station. There were 204 passengers onboard and the ambient temperature was 57 degrees. HEP was able restored at 9:50 p.m. from the trail unit 135. The crew continued to work with CNOC mechanical to attempt to restart the lead unit 373. Amtrak field management met the train at Ashland station at 10:20 p.m. and then followed and met the train at Richmond station to further troubleshooting efforts with the crew after using the lead engine as a control stand and providing HEP and tractive effort from the rear unit 135.

Upon arrival into Richmond station, it was determined the ground fault on engine 373 was detrimental and engine 373 was ultimately set out at Richmond. Train 97(02) operated single unit Richmond, VA to Miami, FL and was on the move from Richmond at 1:56 a.m. operating over 4 hours late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(02)	4'13"	

Train 90(02) South of Alexandria, VA - Freight Train Interference

02OCT25: Train 90(02) operating with engine 146 and 7 cars was delayed south of Alexandria, VA on the CSX RFP subdivision following CSX 410 from milepost 75.9 to milepost 105.1.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
90(02)	34"	

Train 474(02) New Haven, CT - Engine Failure

02OCT25: Train 474(02) with E/86 and E/114 was cancelled due to issues with E/114. Train 417(02) was cancelled with passengers utilizing local CT Rail service. Due to this, Train 417(02) was cancelled in its entirety with alternate transportation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
474(02)		CANCELLED
417(02)		CANCELLED W/ALT

Train 281(02) West of Rome, NY - Freight Train Interference

02OCT25: Train 281(02) with E/104 was delayed at CP278 on the CSX Albany, Syracuse Terminal West subdivision waiting on freight train CSX/I002 to clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
281(02)	50"	

Acela 2168(02) Baltimore, MD - Engine Failure

02OCT25: Acela 2168(02), TS - 12, PC/2006, 6 cars, PC/2037 was delayed at Baltimore, MD Station on Amtrak's PW subdivision with a unrecoverable penalty on PC/2006. A highspeed technician was contacted to troubleshoot problem. They were able to rectify the issue and the train proceeded east at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 20(02) North of New Orleans, LA - Signal

02OCT25: Train 20(02) delayed after departing New Orleans, LA at CP Carrollton/MP 2.3 on Amtrak's NO UP Subdivision due to a track occupancy light, operating at a restricted speed. IMCS was on scene troubleshooting the TOL upon 20(02) arrival. Train 23(02) was held at MP193.4 waiting for Train 20(02) to clear. Once Train 20(02) was cleared, 23(02) proceeded to MP 2.5 where they were also delayed for the TOL. Train 24(02) was then delayed meeting Train 23(02) at MP 768.1.

Train	Delay	Comment
23(02)	19"	
23(02)	31"	Meeting 20(02)
24(02)	25"	
20(02)	25"	

Train 24(02) - West of Pascagoula, MS - Freight Train Interference

02OCT25: Train 24(02) was delayed 21 miles west of Pascagoula, MS at MP 685.6 on the CSX NO & M South Subdivision due to meeting freight train CSX L80102.

Train	Delay	Comment
24(02)	34"	

Train 425(02) Greenfield, MA - Engine Failure

02OCT25: Train 425(02) operating with CC9649, 1 car and E/97 departed Greenfield, MA Station late due to traction motor issues on E/97. Train 425(02) took additional delays on it's run to Springfield, MA due to the traction motor not being able to run at track speed.

Train	Delay	Comment
425(02)	05"	GFD - NHT
425(02)	40"	ITD
425(02)	02"	NHT - HLK

Maintenance of Way Highlights

25FC00009

00000004606

UNCLASSIFIED

10/6/2025

Downeaster Trackwork CSX Portland Sub-M of W Work

22SEP25: Downeaster Service Adjustments due to CSX Portland Subdivision trackwork between Brunswick, ME and Boston North, MA station. They are welding , switch timbers and tie pickup between Wells, MA and Brunswick on the following Tuesday thru Thursday from 8A-ET to 530P-ET. On September 30,2025 to October 02,2025, October 7-9, 2025, October 14-16, 2025, October 21-23, 2025, October 28-30, 2025 and November 4-6, 2025. The following service adjustments will be made:

Northbound:

- Train 681(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BON and BRK, will terminate at WEM.
- Train 683(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BON and BRK is cancelled in its entirety with no alternate transportation.

Southbound:

- Train 684(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BRK and BON, is cancelled in its entirety with no alternate transportation.
- Train 686(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BRK and BON, will originate at WEM.

WBS#: B.TR.100151.0776

Train	Delay	Comment
681	TERM WEM	WITH ALT TRANS
684	CANCELLED	NO ALT TRANS
686	ORIG WEM	WITH ALT TRANS
683	CANCELLED	NO ALT TRANS

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(02JUN-26JUL) terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02JUN-28JUL) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02JUN-26JUL) and 449(02JUN-28JUL) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12, 2025 to Friday October 10, 2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS 26-FOI-00008 No 00000004606 UNCLASSIFIED 10/6/2025
Deadhead Train 426 will turn for Train 471 at HFD
Train 470 will turn for Train 473 at HFD
between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

· Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

· Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

· Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

· Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

· Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

· Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

· Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

· Bus 3470 will provide alternate transportation between HFD and SPG

· Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

· Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

· Deadhead Train 426 will turn for Train 471 at HFD

· Train 470 will turn for Train 473 at HFD

Eastern Region

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
97 (2)	RVR	373		Ground faults//no HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 98(01) Passenger Removal at Richmond, Virginia - Medical***

02OCT25, Passenger on PNR A8C473, traveling from Fort Lauderdale, FL to Philadelphia, PA was removed from the train by EMS after experiencing severe back pain. Amtrak Police notified.

Delay: 98 (01) None

Train 73(02) Passenger Removal at Burlington, North Carolina - Medical

02OCT25, Passenger on PNR AB6D50, traveling from Fort Raliegh, NC to Greensboro, NC was removed from the train by EMS after experiencing a medical emergency. Passenger removed at MP 41.2NC. Amtrak Police notified.

Delay: 73 (02) 30"

Train 2155(02) Passenger Removal at Newark, New Jersey - Medical

02OCT25, Passenger on PNR C5B35B, traveling from New York, NY to Baltimore, MD was removed from the train by EMS after falling and hitting his head on the buckle of the ADA space. Amtrak Police notified.

Delay: 2155 (02) 04"

Train 74(02) Passenger Removal at Durham, North Carolina – Improper Conduct

26-FOI-00008 00000004606 "UNCLASSIFIED" 10/6/2025
02OCT25, Passenger on PNR AD0E0C, traveling from Greensboro, NC to Raleigh, NC was removed from the train by the conductor. The passenger was caught smoking on the train. Amtrak Police notified.

Delay: 74 (02) None

Western Region

Operating Highlights

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Train 353(03) Pontiac, MI - Engine Failure

03OCT25: Train 353(03) was cancelled due to TBU fault on E/4616. As a result the cars were coupled to 351(03) and taken to Chicago where they provided a motor so that equipment could turn for 352(03).

WBS#: B.TR.100150.6151

Train 5(01) West of Salt Lake City, UT - Police Related

03OCT25: Train 5(01) was delayed 37 miles west of Salt Lake City, UT, on UP Lynndyl subdivision, due to an accident near the right of way. Local police placed a hold on all tracks while they removed vehicles from near the right of way. Once police removed the vehicles and released the scene, train 5(01) was able to continue.

Train	Delay	Comment
5(01)	45"	Wi-Tronix estimate

Train 703(02) Stockton, CA - Freight Train Interference

03OCT25: Train 703(02) was delayed departing Stockton, CA station/mp83.8, on UP Fresno subdivision, due to a UP freight train that ran out of hours of service, waiting for a recrew. Once the recrew arrived the freight train was able to proceed, clearing a route for train 703(02). Train 703(03) then followed the freight to Akers siding.

Train	Delay	Comment
703(02)	27"	Following Frt
703(02)	1'08"	Holding at STK

Train 41(02) East of Waterloo, IN - Vehicle Strike

02OCT25: At 10:50PM-ET, train 41(02) with E/366/377, 10 coaches, and 178 passengers, went into emergency .8 miles east of Waterloo, IN, at MP366.1, on NS Toledo-Elkhart subdivision, after striking an unoccupied vehicle. The weather was 60 degrees and cloudy. This incident occurred at Best Street Crossing. NS reports that this crossing was ripped up for track work and barricaded. There were no injuries of crew or passengers reported. There was damage reported to the fireman side ladder. HEP remained active the entire time. Local police were dispatched to the scene as well as NS management. Amtrak Train Master was notified. The vehicle that was struck was fouling the tracks so 41(02) waited for a tow truck to arrive to remove the vehicle. Once the vehicle was removed and the tracks were inspected, train 41(02) was able to proceed.

DOT Crossing # 509587C

NRC # 144-4462

National Response Center Number: 144-4462

Train	Delay	Comment
41(02)	1'10"	Wi-Tronix estimate

Train 22(02) South of Texarkana, AR - Freight Train Interference

02OCT25: Train 22(02) was delayed 20 minutes south of Texarkana, AR, on UP Little Rock subdivision, due to a freight train in emergency ahead blocking the route. The Freight crew inspected their equipment and found a broken knuckle. After the crew replaced the knuckle, the freight was able to continue. Train 22(02) then followed the freight to Texarkana.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(02)	2'00"	

Train 790(02) Moorpark, CA - Passenger Removal - Hygiene

02OCT25: Train 790(02) was delayed departing Moorpark station when police were requested to assist with the removal of a passenger with a hygiene issue. Passenger Arthur Wilson (PNR#AD6BDA) travelling from Santa Barbara to San Diego emitted a pungent odor, on closer inspection the passenger was infested with fleas. The passenger decided to exit the train of their own volition before law enforcement arrived. Amtrak Police Notified.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
790(02)	20"	

Train 1340(02) West of Milwaukee, WI - Tree Strike

02OCT25: Train 1340(02) with E78/188, 3 coaches and 185 passengers, struck a tree at milepost 118.7, 33 miles west of Milwaukee, WI, on CPKC Watertown subdivision. HEP initially went down after impact but was recovered right away. The crew inspected the equipment and found damage to the fireman side ditch lights and leaking fluid from E/78. Also 3 air hoses separated during impact. After the conductor was able to reconnect the air hoses the train proceeded to milepost 102.1 to a crossing where an Amtrak Road Foreman met the train to further inspect the equipment. It was determined that the leaking fluid was a rain pan that caught water. The Road Foreman cleared the train to continue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1340(02)	52"	

Train 4(01) East of Albuquerque, NM - Commuter / Passenger Train Interference

02OCT25: Train 4(01) held 26.8 miles east of Albuquerque, NM/MP902.4, on the NMRX Albuquerque Subdivision, at East Herzog/MP875.6 meeting multiple NMRX commuter trains. Train 4(01) then advanced 10.6 miles to East Domingo/MP865.0 to meet Train 3(01).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(01)	42"	East Herzog
4(01)	14"	East Domingo

Train 5(02) Chicago, IL - Commissary

02OCT25: Train 5(02) was delayed departing Chicago, IL, on the Amtrak Chicago Line, waiting on commissary to arrive after the diner car was reported missing stock at 1:27PM.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(02)	42"	

Train 4(01) Albuquerque, NM - Biohazard Cleanup

02OCT25: Train 4(01), E/ID4618-4 Cars, "UNCLASSIFIED" delayed at Albuquerque, NM/MP902.4, on the NMRX Albuquerque Subdivision, due to C/34134 requiring biohazard removal. This was the result of a passenger physical altercation onboard overnight that led to a passenger removal by police at Victorville, CA/MP36.7, on the BNSF Cajon Subdivision. Only the upper level of C/34134 was able to be serviced however the bottom level had to be locked off due to delay it would have taken cleaners to complete.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(01)	1'15"	

Train 712(02) Inital Terminal Oakland, CA - Third Party Contractor Engine Failure

02OCT25: Train 712(02) was delayed departing Oakland, MP 7.0/UPRR Niles Subdivision, following a late yard release as a result of mechanical failure of assigned locomotive E/2001. This resulted in an equipment swap with Train 716(02). The train then incurred additional delay in the yard due to PTC initialization problems on locomotive E/2010. Train 712(02) departed Oakland at 11:16AM-PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
712(02)	1'40"	

Train 22(02) North of San Marcos, TX - Sick Passenger

02OCT25: Train 22(02) held 15.4 miles north of San Marcos, TX/MP209.8, on the UPRR Austin Subdivision, at MP194.4 for emergency services to respond for a passenger medical emergency. The passenger was removed from the train for observation. Shortly after, Train 22(02) was back on the move north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(02)	38"	

Train 27(30) West of Spokane, WA - Broken Rail

02OCT25: Train 27(30) was delayed at MP 14.7/BNSF Lakeside Subdivision, 14.5 miles west of Spokane, waiting on a broken rail to be repaired ahead at Babb, MP 21.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
27(30)	1'06"	

Train 381(02) Chicago, IL - Engine Failure

02OCT25: Train 381(02), E/ID4618-4 Cars, departed Chicago, IL on-time and then stopped on the Amtrak Chicago Line at CP Roosevelt/MP0.91 from PTC issues. The crew reported "unable to initialize PTC to select a track". The Amtrak and BNSF PTC desks worked with the crew to try and remedy the issue. Chicago Mechanical responded to the train to troubleshoot and found a speed sensor issue. As a result, Train 381(01) shoved back to the station for mechanical to fix. One precautionary bus was secured in Chicago but was later called off once the issue was resolved. At 10:12AM, Train 381(02) departed Chicago operating 2 hours and 32 minutes late.

WBS#: B.TR.100150.6149

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
381(02)	2'34"	

Train 3(01) West of Hutchinson, KS - Passenger Train Interference

02OCT25: Train 3(01) ~~28-FCI-00008~~ ~~100000084608~~ ~~UNCLASSIFIED~~ ~~10/6/2025~~ west of Hutchinson, KS MP218.1, on the BNSF La Junta Subdivision, at CH Jct/MP218.4 meeting Train 4(30).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(01)	30"	

Oakland, CA - Capitol Corridor/San Joaquin Services - Third Party Contractor Engine Failure

23AUG25: Account on-going high shop counts for locomotives of state-support trains in Oakland, the following modifications to service have occurred:

23AUG25:

-Train 714(23) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

24AUG25:

-Train 711(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 716(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

25AUG25:

-Train 715(25) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 534(25) cancelled - passengers accommodated on later departure of train 534(27).

-Train 549(25) cancelled - passengers accommodated on later departure of train 549(27).

-Train 716(25) locomotive change at OMF, remove CDTX/2101 add CDTX/2123 (pulled from train 534(25))

26AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 535(26) Operating with CDTX/2007 Providing Head End Power , BNSF/4357 Providing tractive effort;

Delayed west of Sacramento when BNSF/4357 shut down after overspeed warning - PCS and Speedometer not synced.

- Train 535(26) Terminated in Emeryville for locomotives to be added to train 716(26).

- Train 716(26) received CDTX/2007 to provide HEP and BNSF/4357 to provide tractive effort from train 535(16).

- Train 716(26) Originated in Emeryville - Passengers boarding on Oakland provided bus transport to Emeryville.

- Train 534(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 549(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

27AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

-Train 715(27) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 714 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

-Train 717 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 716(27) Originates Emeryville - Extended Servicing from train 711(27).

28AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 534(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance

- Train 547(28) 27 Mins late departing Sacramento - Equipment Turn from 536(28) after cancellation of 534(28).
- Train 711(28) was terminated at Emeryville, CA. to turn for an on time 714(28) out of Jack London Square, Oakland, CA. 26-FOI-00008 CA 00000004606 "UNCLASSIFIED" 10/6/2025
- Train 712(28) Cancelled after dynamic brake failure on locomotive CDTX/2103.
- Train 717(28) Cancelled - equipment turn from 712(28) (after manipulations)
- Train 714(28) 1 Hour 59 Mins delay while techs resolve compressed air issues with cab car AMTK/90278
- Train 716(30) 30 mins late departing Oakland Jack London - Extended servicing in Oakland Maintenance Facility
- Train 718(30) Originates Emeryville - Techs after replacing door seal on Cab Car CDTX/8305 unable to get 'trainline complete' indication or interior lights - swapped equipment with original 712(30)

29AUG25: Normal Service Operates with No Cancellations

01SEP25:

- Train 714(01) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 711(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

02SEP25:

- Train 714(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 717(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.
- Train 534(02) Delayed Departing Oakland Jack London - Locomotive Compressed Air
- Train 718(02) Delayed Departing Oakland Jack London - Locomotive Wouldn't Start

03SEP25: Following discussions with Amtrak Transportation, Transit America (TASI) and our California State Partners; it has been determined that a temporary reduction in Capitol Corridor and San Joaquins service is essential to perform necessary inspections, maintenance and repairs on the California state owned locomotives.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 20SEP.

- 714 (03-19SEP) CANCELLED
- 717 (03-19SEP) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 20SEP.

- 520 (04-19SEP) CANCELLED
- 534 (04-19SEP) CANCELLED
- 535 (04-19SEP) CANCELLED
- 549 (04-19SEP) CANCELLED

03SEP25:

- Train 712(03) Cancelled - failure of locomotive CDTX 2101 (oil leak).
- Train 711(04) Cancelled - failure of locomotive CDTX 2101 (oil leak).

04SEP25:

- Train 718(04) Originate EMY - CDTX 2101 & CDTX Failure. -Late operation.
- Train 715(04) Terminate EMY to turn for 718(04).

05SEP25:

- Train 712(05) Cancelled - failure of locomotive CDTX/2106, passengers to 716(05).
- Train 703(05) Cancelled - passengers to earlier train 719(05).
- Train 540(05) Cancelled - passengers to train 542(02).

06SEP25:

- Train 738(06) Cancelled
- Train 745(06) Cancelled

08SEP25: The temporary reduction in Capitol Corridor and San Joaquins service has now been extended though October 4.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 04OCT.

- 714 (03SEP-03OCT) CANCELLED

-520 (04SEP-03OCT) CANCELLED
-534 (04SEP-03OCT) CANCELLED
-535 (04SEP-03OCT) CANCELLED
-549 (04SEP-03OCT) CANCELLED

26-FBI-00008 00000004606 "UNCLASSIFIED" 10/6/2025

15SEP25

To streamline departures and provide a stable service for passengers: Effective 15th September 2025.

Train #547 retimed to depart Sacramento 52 minutes later than advertised at 5:55PM-PT operating 52 mins later throughout to San Jose,.

Train #715 retimed to depart Bakersfield 01 hour later than advertised at 1:12PM-PT operating 52 mins later throughout to Oakland.

These changes will remain thru Saturday 4th October 2025

15SEP25: Train 716(15) Locomotive failed at OKJ. Train returned to OMF and new equipment was sourced. Train originate EMY, pax to train 536(15) OKJ-EMY

Cause: Pending

WBS#: B.TR.100150.6069

Train	Delay	Comment
-------	-------	---------

714 (23)	32"	OKJ - delay departing OMF
714 (23)	21"	Operating at reduced speeds account freight locomotive
716 (23)	25"	Follow 714 (23)
711 (24)	26"	25-FCI-00008-00000004606 Pax to BUS 711 EMY-19/6/3025 SFC UNCLASSIFIED
716 (24)	26"	Operating at reduced speeds account freight locomotive.
711 (24)	32"	Reduced operating speeds account freight locomotive
715 (25)	27"	W. FNO - PTC Issue on freight loco
534 (25)	CANCELLED	Pax to 536 (25)
549 (25)	CANCELLED	Pax to 551 (25)
716 (25)	1'03"	Loco change at OMF
715 (25)	23"	Operate with freight locomotive
715 (25)	17"	SKN - Freight loco air compressor issue
535 (26)	41"	West Sac - Recovery from BNSF/4357 Penalty Brake
534 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
716 (26)	1'57"	Originates Emeryville - Receiving CDTX/2007 and BNSF/4357 from 535 (26)
535 (26)	Terminates Emeryville	Oakland Passengers to 537 (26)
549 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
545 (26)	11"	SAC - Short turn of 536 (26) after 534 (26) cancelled
716 (26)	43"	Restricted not to exceed 65 mph with BNSF/4357
714 (27)	Cancelled	
717 (27)	Cancelled	
716 (27)	Originates Emeryville	Passengers to 534 (27)
715 (27)	524"	Restricted not to exceed 65 mph with BNSF/4357
715 (27)	28"	Oakley - BNSF/4357 - Penalty Brake Application Overspeed
534 (28)	Cancelled	
549 (28)	Cancelled	
711 (28)	Term EMY	
712 (28)	Cancelled	Dynamic Brake Failure
717 (28)	Cancelled	Cancellation of 712 (28))
714 (28)	1'59"	OKJ - Techs Resolve Compressed Air Issues
716 (28)	30"	OKJ - Extended Servicing Oakland Maintenance Facility
718 (28)	1'48"	EMY - Swapped Equipment after failed door seal replacement -Originates EMY
547 (28)	27"	SAC - Equipment Turn From 536 (28) after 534 (28) cancelled
714 (02SEP)	Cancelled	
717 (02SEP)	Cancelled	
714 (01SEP)	Cancelled	
711 (02SEP)	Cancelled	
718 (02SEP)	31"	OKJ - Locomotive CDTX/2103 would not start
534 (02SEP)	40"	OKJ - Locomotive Compressed air Issues
712 (03SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
711 (04SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
718 (04SEP)	2'09"	originate EMY
715 (04SEP)		Terminate EMY
712 (05SEP)	CANCELLED	Passengers to 716 (05SEP)
703 (05SEP)	CANCELLED	Passengers to earlier 719 (05SEP)
540 (05SEP)	CANCELLED	Passengers to 542 (05SEP)
716 (05SEP)	1'15"	OKJ - late departure
738 (06SEP)	CANCELLED	
745 (06SEP)	CANCELLED	
549 (04SEP-03OCT)	Cancelled	
535 (04SEP-03OCT)	Cancelled	
534 (04SEP-03OCT)	Cancelled	
520 (04SEP-03OCT)	Cancelled	
717 (03SEP-03OCT)	Cancelled	
714 (03SEP-03OCT)	Cancelled	
547 (08SEP)	36"	SAC - ITD - Equipment from 536 (08)
715 (09SEP)	1'21"	BFD - ITD - Equipt from 702 (09)
547 (09SEP)	13"	SAC - ITD - Equipt from 536 (09)
715 (10SEP)	47"	BFD - ITD - Equipt from 702 (10)
547 (10SEP)	25"	SAC - ITD - Equipment from 536 (10)
715 (11SEP)	1'15"	BFD - Equipment Turn From 702 (11)
547 (11SEP)	21"	SAC - ITD - Equipment from 536 (11)

Train	Delay	Comment
716 (15SEP)	1'49"	Loco Failed
715 (16SEP)	16"	BFD- ITD - Equipment Turn from 702 (16)

26-FOI-00008 00000004606 "UNCLASSIFIED" 10/6/2025

Maintenance of Way Highlights

Union Pacific Track Work on the Moffat Tunnel Subdivision - California Zephyr Schedule Change

11SEP25: To accommodate a Union Pacific scheduled track work on the Moffat Tunnel Subdivision between Denver, CO and Glenwood Springs, CO, Train 5(19SEP and 03OCT) will be renumbered as Train 1005(19SEP AND 03OCT). The train departed Chicago, IL Union station at 5:00 p.m. (CDT), 3 hours after the normally scheduled departure time. It then continued to operate 3 hours later than the scheduled departure time through Emeryville, CA.

WBS#: B.TR.100150.6084

Canadian National Holly Subdivision - Pontiac Station Track Project

02SEP25: September 2nd thru September 30th, Canadian National will be performing a track project at the Pontiac, MI station. Updated 24SEP25 to extend through October 15th. The follow trains will originate and terminate at Troy, MI:

Train 350 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep -28Sep, 03Oct- 05Oct, 10Oct - 12Oct) will terminate Troy, MI.

Train 352 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 354 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 351 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

Train 353 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep - 28Sep, 03Oct - 05Oct, 10Oct - 12Oct) will originate Troy, MI

Train 355 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

There will be NO alternate transportation provided.

WBS#: B.TR.100150.6045

Michigan Department of Transportation Michigan Line affecting Wolverine Service - Scheduled M/W Work

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

05MAY25: Amtrak will be performing a track rehabilitation by modifying a curve between Chelsea, MI / MP 56.0 and Ypsilanti, MI / MP 28.2, which encompasses the Ann Arbor, MI station at MP 37.5, on the Michigan Department of Transportation Michigan Line. The follow operating plan will be placed in to effect:

May 5th through June 26th (except for May 26th and June 19th):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

August 4th through October 30th (except for September 1st):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

WBS#: B.TR.100150.5512

Train	Delay	Comment
350 & 353 (27MAY - 29MAY)	Cancel	
350 & 353 (16JUN - 18JUN)	Cancel	
350 & 353 (23JUN - 26JUN)	Cancel	
350 & 353 (04AUG - 07AUG)	Cancel	
350 & 353 (11AUG - 14AUG)	Cancel	
350 & 353 (18AUG - 21AUG)	Cancel	
350 & 353 (25AUG - 28AUG)	Cancel	
350 & 353 (02SEP - 04SEP)	Cancel	
350 & 353 (08SEP - 11SEP)	Cancel	
350 & 353 (15SEP - 18SEP)	Cancel	
350 & 353 (22SEP - 25SEP)	Cancel	
350 & 353 (29SEP - 02OCT)	Cancel	
350 & 353 (06OCT - 09OCT)	Cancel	
350 & 353 (13OCT - 16OCT)	Cancel	
350 & 353 (20OCT - 23OCT)	Cancel	
350 & 353 (27OCT - 30OCT)	Cancel	

Western Region

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
353 (3)	PNT	ID4616		B/O Tread brake unit

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
22 (3)	SAS	UP7253	E/62 loading issues		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 22(02) Passenger Removal at San Marcos, Texas - Medical

02OCT25, Passenger on PNR A98F3A, traveling from San Antonio, TX to Austin, TX was removed from the train by EMS after experiencing complications from gall bladder surgery. Amtrak Police notified.

Delay: 22 (02) 38"

Train 11(02) Passenger Removal at Tacoma, Washington – Improper Behavior

02OCT25, Passenger on PNR AB6594, traveling from Seattle, Washinton to Los Angeles, CA was removed from the train Tacoma Station Security. Passenger is unfit for travel as they appear mentally unstable. Amtrak Police notified.

Delay: 11 (02) None

Train 517(02) Passenger Removal at Tukwila, Washington – Injury

02OCT25, Passenger on PNR AB0BBD, traveling from Stanwood, WA to Tukwila, WA fell as the train came to a stop at Tukwila. Pax hurt her back but stated she did not want medical attention. Amtrak Police notified.

Delay: 517 (02) 4"

Train 1(01) Passenger Removal at El Paso, Texas – Medical

26-FOI-00008 00000004606 "UNCLASSIFIED" 10/6/2025

02OCT25, Passenger on PNR A88395, traveling from Houston, TX to Los Angeles, CA was having difficulty breathing and chest pains. They were removed from the train by EMS and taken to the hospital. Amtrak Police notified.

Delay: 1 (01) None

Train 3(01) Passenger Removal at Lamy, New Mexico – Improper Behavior

02OCT25, Passenger on PNR ABFC56, traveling from Houston, TX to Kansas City, MO to Los Angeles, CA was removed by local Police after causing a disruption in the lounge, cursing and talking to himself. Amtrak Police notified.

Delay: 3 (01) 19"

Train 14(02) Passenger Removal at San Luis Obispo, California – Improper Conduct

02OCT25, Passenger on PNR A6115A, traveling from Los Angeles, LA to Klamath Falls, OR was removed by the conductor. The passenger was disrespecting other passengers using profanity and threatening to stab them. Amtrak Police notified.

Delay: 14 (02) None

Train 1(01) Passenger Removal at El Paso, Texas – Medical

02OCT25, Passenger on PNR A98395, traveling from Houston, TX to Los Angeles, CA was removed from the train by El Paso EMS. The passenger complained of chest pain and requested EMS. Amtrak Police notified.

Delay: 1 (01) None

Train 21(01) Passenger Removal at McGregor, Texas – Intoxication

02OCT25, Passenger on PNR A98395, traveling from Fort Worth, TX to San Antonio, TX was removed from the train by McGregor PD. The passenger threatened the other passengers and kept laying across the aisle. Amtrak Police notified.

Delay: 21 (01) 28"

Train 5(30SEP) Passenger Removal at Sacramento, California – Intoxication

02OCT25, Passenger on PNR AC93F0, traveling from Reno, NV to Martinez, CA was removed from the train by APD. The passenger speaking of suicide and a weapon was taken from the passenger. Amtrak Police notified.

Delay: 5 (30SEP) 10"

Train 11(02) Passenger Removal at Albany, Oregon – Improper Conduct

02OCT25, Passenger on PNR AD10B9, traveling from Portland, OR to Sacramento, CA, was removed from the train by the conductor. The passenger was sitting in the wrong seat with a large hiking bag. The passenger was shown where their correct seat was and asked several times to sit in the correct seat in which the passenger argued with the conductor and continued to not follow instructions. Amtrak Police notified.

Delay: 11(02) 04"

Train 790(02) Passenger Removal at Moorpark, California – Improper Conduct

02OCT25, Passenger on PNR AD6BDA, traveling from Santa Barbara, CA to San Diego, CA, was removed from the train by the conductor. The passenger was wandering coach with a business class ticket. The passenger smelled of human waste and was covered in fleas. The passenger was asked to detrain after a discussion about issue. The passenger refused and insisted on having police remove them. Amtrak Police notified.

Delay: 790(02) 20"

Train 6(02) Passenger Removal at Elko, Nevada – Improper Conduct

02OCT25, Passenger on PNR ABF409, traveling from Emeryville, CA to Green River, UT, was removed from the train by Elko PD. The passenger was intoxicated and speaking of X-rated scenarios making other passengers uncomfortable. Amtrak Police notified.

Delay: 6(02) 22"

Consist Deviations

26-FOI-00008

00000004606

"UNCLASSIFIED"

10/6/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
770 (02)	GTA	No bike or bag space.	Passengers advised no bike space.	2	90215
586 (02)	LAX	No bag or bike space.	No bike PNRs	0	90215
97 (02)	NYP	Due to a shortage of available Diners in NYP and to protect on time performance, we will operate Train 97(2) with a Lounge car instead of a Diner. (Lounge car #28022)	Passengers will be offered alternative service	0	28022
365 (03)	PTH	356(03) will be overcapacity due to ID4001 D/Hing inline. CHI mech unable to complete repairs.	Supplimental bus will be provided.	23	ID4001
581 (02)	SAN	No bike or bag space.	No bike PNRs	0	90215
178 (02)	WAS	TRAIN 178 SHORT 1 COACH (UNDER CAP) DUE SHOP CAR 82665 #5 WHEEL THIN FLANG	Passengers not affected	0	82665

Reverse Consists

Train Number	Station	Reason	Customer Impact	Affected Psgr
94 (02)	NFK	Consist reversed Business class oriented normal At Front	NONE	0
173 (02)	BOS	Consist reversed Business class oriented normal At Front	NONE	0
181 (02)	NYP	Consist reversed Business class oriented normal At Front	NONE	0
183 (02)	NYP	Consist reversed Business class oriented normal At Front	NONE	0
111 (02)	NYP	Consist reversed Business class oriented normal At Front	N/A	0
190 (02)	PHL	Consist reversed Business class oriented normal At Front	N/A	0
110 (02)	PHL	Consist reversed Business class oriented normal At Rear	N/A	0
2159 (02)	BOS	Consist reversed Business class oriented normal At Rear	N/A	29
185 (02)	NYP	Consist reversed Business class oriented backward At Front		
114 (02)	WAS	Consist reversed Business class oriented backward At Rear		

Train Number	Station	Reason	Customer Impact	Affected Psgr
		26-FOI-00008 00000004606 "UNCLASSIFIED" 10/6/2025		
182 (02)	WAS	Consist reversed Business class oriented backward At Rear		
176 (02)	WAS	Consist reversed Business class oriented backward At Rear		
193 (02)	NYP	Consist reversed Business class oriented backward At Front	Passengers notified	61
129 (02)	NYP	Consist reversed Business class oriented backward At Front	Passengers notified	52
175 (02)	BOS	Consist reversed Business class oriented backward At Front	Passengers notified	56
193 (02)	NYP	Consist NORMAL, NOT reversed Business class oriented normal At Rear	Customers will be advised	54
2172 (02)	WAS	Consist reversed Business class oriented normal At Front	0	0