



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, October 04, 2025

Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/03/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	298	52	82.6%	883	145	83.6%	883	145	83.6%
Central Division	85.5%	66	9	86.4%	197	31	84.3%	197	31	84.3%
Northeast Division	80.0%	97	26	73.2%	282	66	76.6%	282	66	76.6%
Southeast Division	72.5%	70	4	94.3%	210	12	94.3%	210	12	94.3%
Southwest Division	77.0%	65	13	80.0%	194	36	81.4%	194	36	81.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00028 00000004750 UNCLASSIFIED 10/13/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	106,610	22,348	79%	284,605	50,298	82%	284,605	50,298	82%
Northeast Corridor	81%	42,874	7,634	82%	125,828	16,599	87%	125,828	16,599	87%
Acela	83%	7,697	755	90%	25,000	2,852	89%	25,000	2,852	89%
Northeast Regional	79%	35,177	6,879	80%	100,828	13,747	86%	100,828	13,747	86%
Richmond / Newport News / Norfolk	77%	12,012	3,283	73%	33,786	7,043	79%	33,786	7,043	79%
Springfield Shuttles	89%	962	64	93%	2,182	244	89%	2,182	244	89%
Roanoke	79%	3,020	0	100%	8,296	975	88%	8,296	975	88%
On Spine Northeast Regional	80%	19,183	3,532	82%	56,564	5,485	90%	56,564	5,485	90%
State Supported	80%	51,261	10,151	80%	126,203	22,857	82%	126,203	22,857	82%
Borealis	60%	695	204	71%	1,847	830	55%	1,847	830	55%
Capitol Corridor	90%	4,534	585	87%	11,387	1,179	90%	11,387	1,179	90%
Carolinian	60%	1,380	228	83%	3,285	882	73%	3,285	882	73%
Cascades	63%	2,912	463	84%	6,824	1,369	80%	6,824	1,369	80%
Downeaster	82%	1,786	0	100%	4,262	71	98%	4,262	71	98%
Empire	78%	6,019	1,285	79%	15,713	3,968	75%	15,713	3,968	75%
Adirondack	72%	436	255	42%	1,014	578	43%	1,014	578	43%
Ethan Allen Express	70%	662	12	98%	1,789	540	70%	1,789	540	70%
Maple Leaf	70%	933	393	58%	2,132	847	60%	2,132	847	60%
New York - Albany	85%	2,459	595	76%	6,983	1,233	82%	6,983	1,233	82%
New York - Niagara Falls	75%	1,529	30	98%	3,795	770	80%	3,795	770	80%
Heartland Flyer	65%	249	113	55%	542	289	47%	542	289	47%
Hiawatha	90%	2,032	15	99%	5,304	1,361	74%	5,304	1,361	74%
Illinois	78%	2,938	1,208	59%	7,276	2,124	71%	7,276	2,124	71%
Carl Sandburg / Illinois Zephyr	85%	401	299	25%	1,001	682	32%	1,001	682	32%
Illini / Saluki	85%	1,242	339	73%	2,707	349	87%	2,707	349	87%
Lincoln Service	70%	1,295	570	56%	3,568	1,093	69%	3,568	1,093	69%
Keystone	92%	9,426	724	92%	27,330	1,318	95%	27,330	1,318	95%
Lincoln / Missouri	60%	1,004	596	41%	2,331	1,353	42%	2,331	1,353	42%
Mardi Gras Service	80%	404	0	100%	1,108	313	72%	1,108	313	72%
Michigan	69%	2,061	559	73%	4,985	693	86%	4,985	693	86%
Blue Water	70%	649	323	50%	1,446	361	75%	1,446	361	75%
Pere Marquette	85%	271	0	100%	795	0	100%	795	0	100%
Wolverine	65%	1,141	236	79%	2,744	332	88%	2,744	332	88%
Missouri	80%	363	176	52%	660	281	57%	660	281	57%
Pacific Surfliner	85%	8,052	2,131	74%	16,694	2,519	85%	16,694	2,519	85%
Pennsylvanian	72%	1,027	13	99%	2,612	407	84%	2,612	407	84%
Piedmont	73%	1,446	222	85%	2,956	443	85%	2,956	443	85%
San Joaquins	73%	3,532	1,002	72%	7,076	2,649	63%	7,076	2,649	63%
Vermont	75%	1,401	627	55%	4,011	808	80%	4,011	808	80%
Long Distance	56%	12,475	4,563	63%	32,574	10,842	67%	32,574	10,842	67%
Auto Train	57%	574	0	100%	1,691	226	87%	1,691	226	87%
California Zephyr	50%	845	300	64%	2,576	390	85%	2,576	390	85%
Cardinal	55%	262	98	63%	791	241	70%	791	241	70%
City Of New Orleans	75%	768	189	75%	1,873	348	81%	1,873	348	81%
Coast Starlight	60%	1,282	850	34%	2,621	1,373	48%	2,621	1,373	48%
Crescent	70%	1,008	54	95%	2,309	304	87%	2,309	304	87%
Empire Builder	55%	1,086	538	50%	3,118	1,433	54%	3,118	1,433	54%
Floridian	40%	1,547	704	54%	4,592	2,142	53%	4,592	2,142	53%
Lake Shore Ltd	73%	954	33	97%	2,493	213	91%	2,493	213	91%
Palmetto	65%	985	128	87%	2,577	306	88%	2,577	306	88%
Silver Meteor	45%	807	363	55%	2,175	613	72%	2,175	613	72%
Southwest Chief	40%	900	567	37%	2,437	1,933	21%	2,437	1,933	21%
Sunset Ltd	70%	573	88	85%	831	90	89%	831	90	89%
Texas Eagle	50%	884	651	26%	2,490	1,230	51%	2,490	1,230	51%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00020 00000004750 "UNCLASSIFIED" 10/10/2025

Train Index Dates Through October 03, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	13,928	317,109	439	13,928	317,109	439

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	335	93,305	36	335	93,305	36
INFRASTRUCTURE PLANNED	130	335	93,305	36	335	93,305	36
FLEET RELIABILITY	90	2,039	317,109	64	2,039	317,109	64
TRAIN OPERATIONS	427	11,219	317,109	354	11,219	317,109	354

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/03/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	298	52	82.6%	883	145	83.6%	883	145	83.6%
Central Division	85.5%	66	9	86.4%	197	31	84.3%	197	31	84.3%
Northeast Division	80.0%	97	26	73.2%	282	66	76.6%	282	66	76.6%
Southeast Division	72.5%	70	4	94.3%	210	12	94.3%	210	12	94.3%
Southwest Division	77.0%	65	13	80.0%	194	36	81.4%	194	36	81.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0001 Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/03/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	298	52	82.6%	883	145	83.6%	883	145	83.6%
Central Division	85.5%	66	9	86.4%	197	31	84.3%	197	31	84.3%
CDL	90.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
CHI	85.0%	28	2	92.9%	81	10	87.7%	81	10	87.7%
EUG	86.5%	2	0	100.0%	6	0	100.0%	6	0	100.0%
GRR	98.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
KCY	84.5%	2	0	100.0%	6	0	100.0%	6	0	100.0%
MKE	86.5%	6	1	83.3%	18	5	72.2%	18	5	72.2%
MSP	94.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
PDX	78.0%	5	2	60.0%	15	5	66.7%	15	5	66.7%
PTH	93.0%	1	0	100.0%	3	1	66.7%	3	1	66.7%
QCY	87.5%	2	1	50.0%	6	2	66.7%	6	2	66.7%
SEA	80.0%	7	1	85.7%	23	3	87.0%	23	3	87.0%
SPK	92.0%	1	0	100.0%	3	1	66.7%	3	1	66.7%
STL	88.0%	4	1	75.0%	12	2	83.3%	12	2	83.3%
TRM	-	2	1	50.0%	6	2	66.7%	6	2	66.7%
VAC	95.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
Northeast Division	80.0%	97	26	73.2%	282	66	76.6%	282	66	76.6%
ALB	91.5%	6	0	100.0%	18	0	100.0%	18	0	100.0%
BON	43.5%	5	3	40.0%	13	5	61.5%	13	5	61.5%
BOS	86.5%	17	1	94.1%	51	5	90.2%	51	5	90.2%
BRK	88.0%	5	1	80.0%	11	1	90.9%	11	1	90.9%
BTN	48.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
GFD	86.0%	2	0	100.0%	6	1	83.3%	6	1	83.3%
HFD	-	2	1	50.0%	6	1	83.3%	6	1	83.3%
MTR	79.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
NFL	96.5%	2	1	50.0%	6	1	83.3%	6	1	83.3%
NHV	75.5%	5	3	40.0%	15	12	20.0%	15	12	20.0%
NYP	77.5%	44	13	70.5%	127	30	76.4%	127	30	76.4%
SAB	98.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
SPG	88.0%	5	2	60.0%	15	6	60.0%	15	6	60.0%
TWO	84.0%	1	1	0.0%	3	2	33.3%	3	2	33.3%
WEM	-	-	-	-	2	2	0.0%	2	2	0.0%
Southeast Division	72.5%	70	4	94.3%	210	12	94.3%	210	12	94.3%
CLT	92.0%	5	0	100.0%	15	0	100.0%	15	0	100.0%
HAR	62.0%	13	0	100.0%	39	0	100.0%	39	0	100.0%
LOR	69.5%	1	0	100.0%	3	1	66.7%	3	1	66.7%
MIA	87.5%	2	0	100.0%	6	0	100.0%	6	0	100.0%
MOE	94.0%	2	0	100.0%	6	0	100.0%	6	0	100.0%
NFK	86.0%	3	0	100.0%	9	1	88.9%	9	1	88.9%
NOL	92.0%	4	0	100.0%	13	0	100.0%	13	0	100.0%
NPN	96.0%	2	0	100.0%	6	1	83.3%	6	1	83.3%
PGH	92.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
PHL	45.0%	5	0	100.0%	15	0	100.0%	15	0	100.0%
RGH	97.0%	4	0	100.0%	12	0	100.0%	12	0	100.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/03/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	298	52	82.6%	883	145	83.6%	883	145	83.6%
Southeast Division	72.5%	70	4	94.3%	210	12	94.3%	210	12	94.3%
RNK	85.5%	2	0	100.0%	6	1	83.3%	6	1	83.3%
RVM	86.0%	1	0	100.0%	3	1	66.7%	3	1	66.7%
SAV	91.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
SFA	70.5%	1	0	100.0%	3	0	100.0%	3	0	100.0%
WAS	70.0%	23	4	82.6%	68	7	89.7%	68	7	89.7%
Southwest Division	77.0%	65	13	80.0%	194	36	81.4%	194	36	81.4%
ARN	60.5%	1	0	100.0%	3	1	66.7%	3	1	66.7%
BFD	75.5%	5	3	40.0%	15	7	53.3%	15	7	53.3%
EMY	50.0%	1	1	0.0%	3	2	33.3%	3	2	33.3%
FTW	89.5%	1	1	0.0%	3	1	66.7%	3	1	66.7%
GTA	72.5%	3	0	100.0%	9	1	88.9%	9	1	88.9%
LAX	77.5%	10	2	80.0%	30	5	83.3%	30	5	83.3%
OKC	96.0%	1	0	100.0%	3	0	100.0%	3	0	100.0%
OKJ	79.0%	9	1	88.9%	27	5	81.5%	27	5	81.5%
SAC	73.5%	12	1	91.7%	36	4	88.9%	36	4	88.9%
SAN	77.0%	12	1	91.7%	36	2	94.4%	36	2	94.4%
SAS	85.0%	1	1	0.0%	3	1	66.7%	3	1	66.7%
SJC	87.5%	7	1	85.7%	21	5	76.2%	21	5	76.2%
SLO	62.0%	2	1	50.0%	5	2	60.0%	5	2	60.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		1	0	100.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
2		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
3		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
4	103	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
5	31	2	1	50.0%	2	1	50.0%	3	1	66.7%	3	1	66.7%
6		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
7		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
8	96	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
11		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
14	116	3	1	66.7%	3	1	66.7%	2	1	50.0%	2	1	50.0%
19		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
20		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
21		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
22		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
23		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
24		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
25		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
26		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
27		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
28		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
40		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
41	75	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
42		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
43		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
48		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
49		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
50		1	0	100.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
52		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
53		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
55		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
56	31	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
58		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
59		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
63		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
64	23	3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
66		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
67		2	1	50.0%	2	1	50.0%	3	0	100.0%	3	0	100.0%
68	28	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
69		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
71		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
72		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
73		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74	20	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
75		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
76		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
77		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
78		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
79		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
80		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
84		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
85		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
86	26	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
89		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
90		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
93		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
94		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
95	25	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
97	277	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
98		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
110		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
111		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
112		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
114		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
119		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
125	32	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
129		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
130		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
131		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
133	18	3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
134		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
136		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
137		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
138		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
141	20	3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
148	31	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
151		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
171		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
172	51	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
173		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
174		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
175		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
176		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
177	31	3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
178		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
181		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
182		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
183	31	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
184		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
185		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
186	21	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
190		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
192		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
193	20	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
196		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
197		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
232		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
233	40	3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
234		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
236		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
237		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
239		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
240		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
241	21	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
243		3	2	33.3%	3	2	33.3%	4	1	75.0%	4	1	75.0%
244		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
280		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
281		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
283		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
284		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
290		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
291		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
300	34	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
301		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
302		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
305	27	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
306		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
307		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
311		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
316	48	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
318	18	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
319		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
329		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
330		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
331		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
332		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
335		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
336		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
337		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
338		3	2	33.3%	3	2	33.3%	3	2	33.3%	3	2	33.3%
339		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
341		3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
342		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
350		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
351	80	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
352		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
354	18	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
355		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
364		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
365	49	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
370		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
371		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
380	21	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
381		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
382	27	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
383	115	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
390	34	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
391		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
392		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
393		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
417		3	3	0.0%	3	3	0.0%	2	0	100.0%	2	0	100.0%
425		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
470		3	3	0.0%	3	3	0.0%	3	0	100.0%	3	0	100.0%
471		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
473	20	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
474		3	2	33.3%	3	2	33.3%	2	0	100.0%	2	0	100.0%
475		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
478		3	3	0.0%	3	3	0.0%	3	0	100.0%	3	0	100.0%
479		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
486		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
494		4	4	0.0%	4	4	0.0%	3	1	66.7%	3	1	66.7%
495		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
500		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
502		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
503		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
504		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
505		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506	16	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
507	17	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
508		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
509		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
511		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
516	19	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
517		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
518		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
519		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
521		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
522		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
523		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
524		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
525		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
526		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
527		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
528		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
529	39	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
531		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
532		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
536		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
537		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
538	17	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
540		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
541		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
542	18	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
543		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
544		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
545		3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
546		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
547		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
548		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
551		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
562		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
564		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
566		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
572		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
573		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
577		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
580		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
581		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
582		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
586		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
587	65	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
591	21	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
593		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
595		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
600		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
601		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
605		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
607		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
609		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
620		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
624		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
639		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
640		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
641	13	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
642	66	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
643		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
644		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
645		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
646		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
647		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
648		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
649		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
650		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
651		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
652		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
653		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
654		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
655	23	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
656		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
657		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
658		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
680		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
681	11	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
682		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
683	12	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
684		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
685		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
686		3	2	33.3%	3	2	33.3%	3	0	100.0%	3	0	100.0%
687		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
688		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
702		3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%

Amtrak On Time Performance

Trains Arriving Through: 10/3/2025

25-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
703		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
710	30	3	1	66.7%	3	1	66.7%	3	3	0.0%	3	3	0.0%
711		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
712	30	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
713		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
715		3	3	0.0%	3	3	0.0%	3	2	33.3%	3	2	33.3%
716		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
718		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
719		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
761		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
765	18	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
769	17	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
770		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
774		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
779		3	0	100.0%	3	0	100.0%	2	0	100.0%	2	0	100.0%
784		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
785		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
790		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
794	328	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
821		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
822	29	3	1	66.7%	3	1	66.7%	3	2	33.3%	3	2	33.3%
1333	24	3	0	100.0%	3	0	100.0%	3	3	0.0%	3	3	0.0%
1340		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
1689		1	1	0.0%	1	1	0.0%	2	0	100.0%	2	0	100.0%
2103		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2107	Cncld	3	1	66.7%	3	1	66.7%	2	0	100.0%	2	0	100.0%
2108		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2121		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2122		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2130		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2150	22	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2151		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2153	27	3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2154		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2155	Cncld	3	0	100.0%	3	0	100.0%	1	1	0.0%	1	1	0.0%
2159		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2162		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2163		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2166		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2167		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2168		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
2170	44	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%

Amtrak On Time Performance Trains Arriving Through: 10/3/2025 26-FOI-0002800000004750"UNCLASSIFIED"10/13/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2172		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
2173		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2190		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2193		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%

Amtrak Endpoint OTP Details

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/3/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2107	XHM	Trn Cancelled	HLD	2	HLD	2	MET-MET	AM	Passenger and/or baggage, TRAVEL
2150	BOS	22	OTH	19	DSR	10	STM-XNH	MN	Per bulletin Milepost, 40.6, 41.7, 30, 4, Control Point, 241, 15, 4, Control Point, 248, 30, 1, Control Point, 257, 30, 1
2153	WAS	27	DSR	13	DSR	7	NHV-STM	MN	Per bulletin Milepost, 40.6, 41.7, 30, 2, Milepost, 41.7, 42.0, 15, 2
2155	XHM	Trn Cancelled	ENG	24	DMW	20	NHV-STM	MN	Hold for defect repair Also, No Access, Control Point, East Norwalk
2170	BOS	44	ENG	30	ENG	30	STM-STM	MN	Traction motor 2117
86	BOS	26	CTI	19	DCS	10	ALX-XVG	CS	Restrictive signal(s) from unknown cause Stop , Control Point, Virginia
95	NFK	25	FTI	25	PTI	18	FBG-RVR	CS	Meet Amt-138, Milepost, 37.7, 37.7
125	NPN	32	PTI	34	PTI	29	FBG-ASD	CS	Meet 90, Control Point, milford
133	WAS	18	POL	12	POL	12	PHL-PHL	AM	Removal of passenger by police
141	NFK	20	ADA	23	DCS	12	WAS-WAS	AM	Power switch failure, Control Point, K INTERLOCKING, 336 SWITCH FAILURE BLOCKING CREW FROM GETTING DIESELS FROM PIT
148	SPG	31	SMW	27	SMW	27	NHV-NHV	AM	Scheduled in track usage program, Milepost w/Letters, NHV, NHV, Metro North loop trk o/s tonight, AM148 had to loop at Devon instead
172	BOS	51	ENG	41	ENG	32	NCR-BWI	AM	Other electrical failure, 658/659, STOPPED ON 1TRK AT MP 121.8 WITH LOOSE MAIN RESEVOIR HOSES BETWEEN TWO ENGINES. FOLLOWED MK410 GROVE TO BWI A/C OUT OF SLOT.
177	PHL	31	PTI	25	PTI	25	NRO-NRO	MN	Meet amt 2174, Control Point, cp216
183	WAS	31	MTI	35	MTI	35	MET-PJC	AM	Disabled train ahead, Other, LINCOLN-XCY, PICKING UP DISABLED AM2107'S PSGRS
186	PHL	21	FTI	31	FTI	26	RVR-ASD	CS	Meet 407, Control Point, Elmont
193	WAS	20	POL	22	POL	22	MET-MET	AM	Removal of passenger by police, UNACCOMPANIED MINOR
473	NHV		POL	24	POL	24	HFD-HFD	AM	Suspicious bag or bomb threat
641	HAR	13	ENG	8	PTI	4	XHM-PHL	AM	Meet, 600, Control Point, PHL
642	NYP	66	ENG	64	ENG	59	PHL-PHL	AM	HEP, 637, HEP ISSUES, REMOVED E/637 ADDED E/650

Amtrak Endpoint OTP Details

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/3/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
655	HAR	23	SYS	18	SYS	18	NYP-NYP	AM	Other late crew, LATE CREW OFF AM42
681	BRK	11	PTI	9	PTI	9	POR-FRE	CS	Meet 684, Control Point, Congress
683	BRK	12	PTI	9	PTI	9	EXR-DHM	CS	Meet 684, Control Point, Rockingham
64	ALB	23	HLD	16	HLD	16	NFS-NFS	XC	High passenger count 40 via passengers off, 150 Amtrak passengers on, low level platform
68	NYP	28	CUI	31	CUI	31	RSP-RSP	DH	United States
233	ALB	40	ENG	20	CON	12	NYP-NYP	AM	Hold for connecting train, HELD F/PSGRS OFF AM172
241	ALB	21	CTI	26	CTI	18	CRT-POU	MN	Follow metro, 869, Milepost, 34, 72
75	CLT	20	PTI	19	PTI	19	CYN-DNC	NS	Meet #amtk72, Control Point, Nelson
97	MIA	277	ENG	253	ENG	171	RVR-RVR	CS	Set out defective locomotive 373
56	SAB	31	PTI	24	TRS	18	NHT-GFD	MA	Held the CPR 35 for trespasses on track Control Point, CPR 35
41	MIA	75	FTI	176	FTI	45	CAM-CLB	CS	Cross Traffic STOP SIGNAL, L 644/03, Other, 359.3
5	EMY	31	FTI	99	ENG	20	DEN-DEN	RT	Air / Brake Engine wouldn't hold brake pipe pressure., 164
529	SJC	39	MBO	33	MBO	33	SUI-MTZ	UP	For maritime traffic Bridge, Suisun
538	ARN	17	PTI	14	RTE	8	RLN-ARN	UP	Run via siding or slower track due to N.A.R. Milepost, 110.0, 120.0
542	SAC	18	PTI	17	PTI	8	GAC-FMT	UP	Meet 543, Siding, Albrae
506	SEA	16	PTI	14	PTI	9	XNI-TAC	ST	Meet amtrak 511, Control Point, manitou
507	EUG	17	SYS	16	POL	11	PDX-ORC	UP	Right of Way police hold Police hold at naito crossing for trespasser
516	VAC	19	DMW	14	DMW	14	XF2-X1J	BN	Waiting for MW clearance Bridge, Fraser
14	SEA	116	HLD	85	HLD	38	KFS-CMO	UP	. Passenger barely responsive and needing medical assistance. Passenger removed by Fire & Rescue. Saldivar, Denise (PNR 9C9DCB) Please see report.
8	CHI	96	FTI	150	FTI	55	WPT-WTN	BN	Meet BNSF 3821, Siding, Blair

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Region: ALL

Service: ALL

Arriving On: 10/3/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
822	OKC	29	DSR	37	DSR	20	FTW-GLE	BN	Per bulletin Milepost, 370.5, 371.0, 30, Main Track, Milepost, 372.2, 372.3, 25, Main Track, Milepost, 374.3, 374.5, 60, Main Track, Milepost, 378.1, 378.4, 60, Main Track, Milepost, 379.1, 379.2, 60, Main Track, Milepost, 379.7, 379.8, 60, Main Track, Milepost, 382.2, 382.6, 60, Main Track, Milepos	
351	CHI	1	DSR	13	DSR	6	DER-ARB	MI	Per bulletin Milepost, 34.8, 35.2, 30, main	
354	TRM	18	RTE	21	RTE	21	DET-DET	CC	Inability to contact dispatcher Branch Line Dispatcher unable to get ahold of Desk 10 for route. We toned up twice with no answer. Conductor called at 12:05am and they answered phone at 12:19am. Dispatcher said phones and radios were down and we would be waiting for 1 freight to clear., Control Poin	
365	CHI	49	SYS	31	FTI	23	FLN-DRD	CC	Cross over or go around Q122 CN 8003, Milepost, 264, 264	
587	LAX	65	TRS	59	TRS	54	SNA-SNA	SC	Vehicle on track ahead Stop signal at Lincoln. Dispatch hold until tracks clear of car on tracks, Milepost, 172.21, 172.21	
591	LAX	21	CTI	21	CTI	9	FUL-XRJ	BN	Follow Metrolink, Milepost, 165, 144	
765	GTA	18	PTI	15	PTI	15	MPK-XMR	UP	Meet 774, Control Point, las posas	
769	GTA	17	RTE	13	FTI	10	FUL-XRJ	BN	Meet BNSF 7346, Control Point, Valley View	
794	SAN	328	TRS	338	TRS	338	XRJ-FUL	BN	Trespasser strike Metrolink 634 vs trespasser, Milepost, 159.0, 159.0	
710	BFD	30	FTI	27	PTI	11	COC-WAC	BN	Meet amt 715, Control Point, elmo	
712	BFD	30	PTI	38	PTI	12	MOD-TRK	BN	Cross over or go around shuffle move, amtk 713, Control Point, west empire	
4	CHI	103	SVS	77	SVS	55	ABQ-ABQ	NM	Hazmat cleaning of blood in 411 car due to violent exchange between passenger and LAX Conductors G. Lawton and E. Gonzales prior to VRV.	
300	CHI	34	FTI	40	FTI	15	ALN-CRV	UP	Meet UP 5572, Control Point, Shipman	
305	STL	27	PTI	27	PTI	27	JOL-DWT	UP	Meet Shuffle, Amtk 318, Control Point, Hitt	
380	CHI	21	FTI	9	FTI	9	QCY-MAC	BN	Meet BNSF 6939 W, Siding, Ewbanks	
382	CHI	27	FTI	19	FTI	12	PCT-MDT	BN	Meet bnsf 5167, Control Point, Zearing	
383	QCY	115	FTI	88	FTI	72	KEE-GBB	BN	Ft engine down at B plant bnsf, Control Point, B plant	
390	CHI	34	DCS	22	DCS	17	HMW-XCS	CC	TALK BY SIGNAL Control Point, 67th street	

Amtrak Endpoint OTP Details

26-FOI-0002800000004750"UNCLASSIFIED"10/13/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/3/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
316	STL	48	FTI	64	FTI	53	SED-JEF	UP	Meet Held at west end of centertown for train the was inspecting a defect from a defect detector. Got lined into the siding to await their departure., UP Unknown, Siding, Centertown	
318	CHI	18	FTI	27	FTI	15	KCY-XRC	KC	Cross Traffic unk, Control Point, up kcs	
1333	MSP	24	PTI	15	PTI	15	WDL-TOH	CP	Meet amtk 1340, Siding, camp douglas	

Amtrak Initial Terminal Details

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/3/2025

Terminal	Train	Date	Late	Delay	Cause
WAS	148	10/03	4	4	Other electrical failure, ., MOTOR WAS RELEASED LATE FROM THE PIT
WAS	176	10/03	3	3	HEP, 642, DOORS STILL SHOWING OPEN
WAS	178	10/03	9	9	Onboard HBD alarm, 625, HOT JOURNAL BEARING ALARM
WAS	182	10/03	7	7	HEP, 636, TRAIN LINE ISSUES AND NO HEP
BON	683	10/03	1		
BON	687	10/03	1		
BON	689	10/03	1		
BOS	177	10/03	1		
BRK	684	10/03	1		
HFD	473	10/03	24	24	Suspicious bag or bomb threat
NFL	284	10/03	1		
NHV	470	10/03	2	2	Inability to contact dispatcher, Other, NHV
NHV	478	10/03	1		
NHV	494	10/03	1		
NYP	19	10/03	6	6	Passenger and/or baggage, LOADING
NYP	111	10/03	10	10	HEP, 635, LOS OF HEP WHILE DEPARTING SSYD
NYP	133	10/03	3	3	Door, 00000, UNSPECIFIED DOOR PROBLEM
NYP	183	10/03	3	3	Door, 00000, UNSPECIFIED DOOR PROBLEM
NYP	197	10/03	2	2	Undesired emergency application, 634, HOT JOURNAL ALARM
NYP	233	10/03	12	12	Hold for connecting train, HELD F/PSGRS OFF AM172
NYP	239	10/03	2	2	Cross Traffic, NJT, NJ3510, Other, XBH-NYP, NJ3510 XING AHEAD AT "A" INT
NYP	281	10/03	3	3	Passenger and/or baggage, LOADING
NYP	641	10/03	3	3	Meet, AM190, Other, NYP, AM190 XING AHD
NYP	655	10/03	18	18	Other late crew, LATE CREW OFF AM42
NYP	2103	10/03	3	3	Passenger and/or baggage, LATE BOARDING PSGRS
NYP	2121	10/03	3	3	Passenger and/or baggage, LOADING
NYP	2190	10/03	2	2	Passenger and/or baggage, LATE BOARDING PSGRS
SPG	141	10/03	1		
SPG	417	10/03	1		
TWO	64	10/03	1		

Amtrak Initial Terminal Details

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/3/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	41	10/03	7	7	Sink not working 62507
CHI	307	10/03	10	10	Door ID4129
MKE	332	10/03	1		
PDX	502	10/03	5	5	Fuel
PDX	506	10/03	1	1	Meet amtrak 507, Control Point, .5
QCY	380	10/03	2	2	Door 48184, Door on the B End, firemen side opened on its own while at the station stop
SEA	8	10/03	6	6	Water, commissary, toilet/trash dumping Late train wye due inbound train bathrooms not working. Mechanical meet at station stop to fix bathrooms in 831 sleeper. Oakland op reallocated rooms for crew due dh crew car.
STL	311	10/03	4		
TRM	351	10/03	79		
BFD	713	10/03	5	5	Door C8314, No door light at departure time. Doors recycled on both sides and no door light. After inspecting the cab car doors had to be recycled.
BFD	715	10/03	5	5	High passenger count Train was blue flagged past departure time due to cleaning. Loaded close to 200 passengers after flags dropped.
BFD	719	10/03	3	3	Door C9001, Door light issues
EMY	6	10/03	73	73	Air / Brake Parking Brake would not release so we had mechanical help us out in the yard... then we departed the yard and the disk brakes would not release. We opened our iPad to troubleshoot and got the brakes released and continued on our tour of duty, 377
FTW	822	10/03	2	2	Water, commissary, toilet/trash dumping Had to load new commissary onto train., Other, FTW station
LAX	14	10/03	1		
LAX	566	10/03	1		
OKJ	710	10/03	1		
SAC	545	10/03	2	2	Mobility Impaired Last minute ADA walking up tunnel.
SAN	595	10/03	1		
SAS	22	10/03	62	62	UP 7253 breaker issues DP1 DP2 breakers left up XUP7253
SJC	538	10/03	1		
SLO	774	10/03	10	5	Air / Brake / Wheel C6952, After going into PTC emergency twice, brakes failed to set up
SLO	774	10/03	10	5	PTC-caused slow-down or penalty stop Milepost, 248, 249

Eastern Region

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	93.0	94.7	83.5	57	4
SEPTA	95.0	96.3	97.4	91.5	189	7
NJT-NED	95.0	No Data	No Data	93.8	No Data	No Data
NJT-SED	95.0	100	98.6	97.2	24	0

Operating Highlights

Train 2170(03) Stamford, CT - Engine Failure

03OCT25: Next Gen Acela 2170(03) was delayed departing Stamford, CT on the Metro North New Haven Line after arriving at 6:55 p.m. due to loss of power on power car 2117. Headend power remained operational and a Siemens tech rider was on the lead unit to help perform a reset. 2170(03) departed Stamford, CT at 7:27 p.m.

Train	Delay	Comment
2170(03)	30"	

CSX RF&P Single Tracking - Freight Train Interference

03OCT25: Multiple trains were delayed on the CSX RF&P Subdivision south of Fredericksburg, VA, due to freight unit X419-02 stopped with a DED alarm, and setting off a car at Doswell/MP34.1. Train 138(03) was the first train affected. Trains 53/95/90(03) and 41(02) were all delayed due to congestion, single-tracking by the freight between MP37.6 and MP21.7.

Train	Delay	Comment
138(03)	51"	
95(03)	15"	
90(03)	35"	
53(03)	30"	
40(02)	10"	
125(03)	29"	
93(03)	30"	

Train 68(03) Rouses Point, NY - Customs and Immigration

03OCT25: Train 68(03) was delayed on the CPKC Canadian subdivision at Rouses Point, NY for customs and immigration.

Train	Delay	Comment
68(03)	31"	

Acela 2155(03) East of Kingston, RI - Engine Failure

03OCT25: Acela 2155(03) with E/659 and E/658, 6 cars, reported ACSES issues east of Kingston, RI, the train stopped at the Kingston, RI station to attempt to troubleshoot the issue. The crew worked with an Amtrak Road Foreman and was still unable to rectify the issues with PC/2029. The train declared ACSES failure and proceeded west at reduced speeds to New York, NY losing additional time. The train was met at New York by mechanical. They were still unable to resolve the issue, it was determined to terminate Acela 2155(03) and passengers were transferred to Train 131(03) to continue their travel west to Washington, DC.

Acela 2155(03) equipment was wye'd at New York, then deadheaded to Washington where it became 2174(03). Acela 2159(03) short turned for 2122(03) at Washington.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2155(03)	17"	KIN
2155(03)	27"	KIN - NYP
2155(03)		TERM NYP

Train 172(03) North of New Carrollton, MD - Engine Failure

03OCT25: Train 172(03) with E/659 and E/658 stopped on track 1 at MP121.8 on Amtrak's PW South Subdivision, 6 mile north of New Carrollton, MD due to a loose hose between E/659 and E/658. The train was delayed as the crew inspected the train. They were able to re-secure the main reservoir hoses, and the train resumed travel north. Train 172(03) took additional delays at Baltimore and BWI stations as the crew inspected the hoses. Philadelphia mechanical was contacted and met the train upon its arrival at the Philadelphia Station. They were inspected and continued travel north.

Train 233(03) was delayed departing New York, NY Station holding for 20 connections off the late 172(03).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
172(03)	32"	MP 121.8
172(03)	09"	BWI - PHL
233(03)	12"	HLN CONEX 172

Train 642(03) Philadelphia, PA - Shopped Engine

03OCT25: Train 642(03) E/637, 5 cars, was delayed departing Philadelphia due to reported HEP issues on engine E/637. Mechanical met the train upon arrival into the station. After multiple attempts to reset, and still unable to resolve the issue, engine E/637 was replaced with E/650. Some passengers were accommodated to Train 600(03) that departed Philadelphia first. Once the engine was changed out, and brake test performed, Train 642(03) was able to depart Philadelphia.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
642(03)	59"	

Train 2107(03) West of Metropark, NJ - Engine Failure

03OCT25: at approximately 10:26 PM, Train 2107(03) operating with TS17, PC/2022, 6 cars, PC/2011 was reported stopped in emergency brake application, 5 miles west of Metropark, NJ at MP28 on the Amtrak NYP Line Subdivision. There were approximately 213 passengers onboard and the weather was a reported 60 degrees and clear. A high speed rail technician and an Amtrak Road Foreman was in contact with the crew troubleshooting the issue. After troubleshooting with the technician, and multiple attempts to reset, the crew was unable to resolve the issue and the decision was made to terminate the train. All 213 passengers onboard were transferred via a train-to-train transfer to Train 183(03). Downline passengers given option to re-book or take 183(03). A rescue engine was dispatched from SSYD to bring 2107's equipment back to New York. Due to no available replacement equipment, Train 2168(03) utilizing TS-15, was originated at New York, cancelled WAS-NYP. Passengers were able to re-book to next available services.

Train	Delay	Comment
2107(03)	Terminated - W/MET	
183(03)	35"	Rescued 2107 passengers
2168(03)	Originated NYP	Cancelled WAS-NYP

Maintenance of Way Highlights

Metro North NHV Line - Weekend Outages

25-EO-140733 20000000750 "UNCLASSIFIED" 10/13/2025

25SEP25: Metro North Railroad has trackwork scheduled this weekend on their NHV Line. No.3trk CP217 to CP223 Saturday(04) 12:50A to 4P. No.1trk CP217 to CP223 Sunday 10A to 2P Catenary inspection. No.1 & 2trks Cp266 to Cp272 Replace ties and Rail. Friday(03) 11P to 6P Sunday(05). Rule 22 on 3 & 4trks

Sunday(05) on Overnight 12A to 5A Monday(06) in New Haven CP272 to CP273(including Cp272) 3,5 & R tracks for Church St. Bridge inspectors. No Access to Motor Storage.

Northeast Regional Service Track Work - M of W Work

08SEP25: Amtrak Northeast Regional Corridor/Southeast Division. Washington Terminal 'K' Interlocking will be installing a 238 Turnout from 7:45pm Friday October 3rd, 2025 - 5:00am Monday October 6th, 2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Northeast Regional Service will be adjusted as follows:

Southbound

- Train 65 (30Oct, 40Oct), which normally operates between BOS and NPN, will terminate at WAS with no alternate transportation.

Northbound

- Train 124 (40Oct, 50Oct), which normally operates between NPN and PHL, will originate at WAS with no alternate transportation.

WBS#: B.TR.100151.0773

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(02JUN-26JUL) terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02JUN-28JUL) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02JUN-26JUL) and 449(02JUN-28JUL) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division / Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12, 2025 to Friday October 10, 2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Eastern Region

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
97 (2)	RVR	373		Ground faults// trail 164 (4) to WAS

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 53(02) Passenger Removal at Lorton, Virginia – Medical

03OCT25, Passenger on PNR AA2B81, traveling from Lorton, VA to Sanford, FL was removed from the by EMS after possibly having a food related allergy attack. Amtrak Police notified.

Delay: 53 (02) 10"

Western Region

Operating Highlights

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Train 587(03) Santa Ana, CA - Police Related

03OCT25: Train 587(03) was delayed at Santa Ana, CA (SNA) on the Southern California Regional Rail Authority Orange Subdivision. Local authorities observed a vehicle to be fouling the tracks ahead and requested all train traffic halted. A tow truck and track inspector were called; once the vehicle was removed and tracks inspected train traffic was resumed.

Train	Delay	Comment
587(03)	54"	

Train 2(03) West of Ontario, CA - Police Related

04OCT25: Train 2(03) was delayed 5 miles west of Ontario, CA, on UP Alhambra subdivision, due to police meeting the train to remove an unruly passenger who was threatening the crew. The crew called for the police to meet the train at Pomona station. Once police arrived and removed the passenger, train 2(03) was able to proceed.

Train	Delay	Comment
2(03)	32"	

Train 383(03) North of Galesburg, IL - Freight Train Interference

03OCT25: Train 383(03) was delayed 1 mile North of Galesburg, IL at milepost 176.7, on BNSF Chillicothe subdivision, due to a stalled freight engine obstructing the route. Once the BNSF crew resolved the issues with the loco, they were able to proceed, clearing a route for train 383(03).

Train	Delay	Comment
383(03)	1'12"	

Train 316(03) West of Jefferson City, MO - Freight Train Interference

03OCT25: Train 316(03) was delayed 25 miles west of Jefferson City, MO, at Centertown siding/MP142, on UP Sedalia subdivision, due to UP freight train, UP6586, setting off a drag detector. The UP crew inspected their 14800+ ft train and found a dragging air hose. Once the crew secured the hose they were able to get on the move, creating a route for 316(03).

Train	Delay	Comment
316(03)	53"	

Train 2(01) Schriever, LA - Drawbridge Opening

03OCT25: Train 2(01) was delayed 26 miles west of Schriever, LA at milepost 80.9, on BNSF Lafayette subdivision, due to Berwick bridge being open for maritime traffic. Once the maritime traffic cleared and the bridge was properly seated, train 2(01) was able to proceed.

Train	Delay	Comment
2(01)	30"	

Train 3(02) East of Lamy, NM - Passenger Train Interference

03OCT25: Train 3(02) was delayed starting 26.4 miles east of Lamy, NM/MP835.2, on the BNSF Glorieta Subdivision, at Canyoncito/MP830.5 meeting Train 4(02).

Train	Delay	Comment
3(02)	43"	

Train 21(02) Fort Worth, TX - Late Fuel Truck

03OCT25: Train 21(02) was delayed at Fort Worth, TX/MP346.2, on the BNSF Fort Worth Subdivision, due to a late arriving fuel truck.

Train	Delay	Comment
21(02)	36"	

Train 4(02) East of Gallup, NM - Freight Train Interference

03OCT25: Train 4(02) was delayed starting 17.3 miles east of Gallup, NM/MP157.5, on the BNSF Gallup Subdivision, between MP140.3 and MP27.5 following BNSF QSDCHI602X. This was a result of an earlier track indication that caused congestion and multiple BNSF freight trains to be tied down for hours of service.

Train	Delay	Comment
4(02)	40"	

Train 6(01) East of Burlington, IA - Sick Passenger

03OCT25: Train 6(01) held 27.8 miles east of Burlington, IA/MP205.6, on the BNSF Ottumwa Subdivision, at MP177.8 for emergency services to respond for a passenger onboard having a seizure. Responders arrived and cleared the passenger to continue on the train east. At the Galesburg, IL station/MP/MP162.6, the Conductor reported the passenger decided to detrain and go to the hospital themselves.

Train	Delay	Comment
6(01)	34"	

Train 21(02) South of Texarkana, AR - Freight Train Interference

03OCT25: Train 21(02) was delayed starting 8.7 miles south of Texarkana, AR/MP0.0, on the UPRR Little Rock Subdivision, at Sulphur/MP8.7 meeting UP 7198. Additional delay at Queen City/MP21.2 meeting an unspecified UPRR freight train.

Train	Delay	Comment
21(02)	38"	Queen City
21(02)	13"	Sulphur

Train 14(02) North of Klamath Falls, OR - Sick Passenger

03OCT25: Train 14(02) was delayed in Chiloquin, OR at MP 458.0/UPRR Cascade Subdivision, 28.4 miles north of Klamath Falls, as a result of an onboard passenger medical emergency. Local EMS (Klamath County Fire & Rescue) responded, removed the passenger and transported to an area hospital. Amtrak Police notified.

Train	Delay	Comment
14(02)	38"	

Train 11(02) Emeryville, CA - Police Related

03OCT25: Train 11(02) was delayed at Emeryville, MP 4.5/UPRR Martinez Subdivision, following assault of a crew member by a person (allegedly a passenger waiting to board), as the crew member stepped off the train. Local police were called and took the suspect into custody. The crew member did not requested medical attention and remained onobard the train. Amtrak Police notified.

Train	Delay	Comment
11(02)	42"	

Train 529(03) West of Suisun-Fairfield, CA - Drawbridge Opening

03OCT25: Train 529(03) was delayed at Benicia, MP 35/UPRR Martinez Subdivision, 13.9 miles west of Suisun as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass.

Train	Delay	Comment
529(03)	33"	

Train 6(03) Initial Terminal Emeryville, CA - Late Release/Locomotive Issue

03OCT25: Train 6(03) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard departure (and subsequently further delay on the mainline before the Emeryville depot) as a result of handbrake issues on trailing locomotive E/377 (third locomotive, new Charger unit delivery deadhead move to Chicago). Train 6(03) departed Emeryville at 9:38AM-PT.

Train	Delay	Comment
6(03)	1'13"	

Train 22(03) San Antonio, TX - Engine Failure

03OCT25: Train 22(03) was delayed departing San Antonio, TX/MP209.5, on the UPRR Del Rio Subdivision, from engine issues with E/UP7253. The freight unit was sourced after E/62 encountered loading issues coming into San Antonio on Train 21(01). San Antonio Mechanical experienced setup issues with E/UP7253 but was able to resolve to get the unit working as intended. The DP1 and DP2 breakers were left up which is what caused the issue. Once complete, Train 22(03) departed the station.

Train 22(03) operated for 18.8 miles before stopping at MP244.3 after E/UP7253 encountered issues with the wheel slip alarm and speedometer. The train completed a roll by and took no exceptions. E/62 was also isolated. Once on the move, the wheel slip alarm issue continued which caused Train 22(03) to not exceed 40MPH to Austin. The crew change Engineer at Austin boarded, completed a ground inspection on the wheels and completed a roll by taking no exceptions. The wheel slip alarm continued so Train 22(03) stopped at McNeil/MP166.1 to take an M/U cable from a tied down RWAKD-27. This also did not work so the train continued to the Taylor, TX station at MP144.5 to pull the M/U cable to try and resolve the issue. Efforts were unsuccessful and Train 22(03) continued not exceeding 40MPH to Fort Worth.

Train 22(03) was delayed South of Cleburne, TX, on BNSF FT. Worth subdivision due to holding for a re-crew. The Re-crew was stuck in traffic and took longer than expected to arrive.

22(03) arrived at Fort Worth, TX, at 7:54PM-CT, 6'03" late. Mechanical was unable to repair UP7253 and 22(03) continued on to Mesquite where the freight unit was originally going to be swapped for UP8504 but UP8504 was bad ordered due to a traction motor fire. 22(03) departed Fort Worth, TX at 8:36PM-CT, 6'18" late and arrived at Dallas, TX, at 9:58PM-CT, 6'40" late. 22(03) held in Dallas for a replacement freight loco UP7655 out of Fort Worth, TX. The replacement loco arrived in Dallas at 12:20AM-CT. Once the freight locos were swapped, train 22(03) departed Dallas, TX at 12:56AM-CT, operating 9'18" late.

WBS#: B.TR.100150.6153

Train	Delay	Comment
22(03)	1'02"	ITD SAS
22(03)	26"	MP244.3
22(03)	14"	SMC-AUS 40MPH
22(03)	22"	AUS
22(03)	30"	AUS-TAY
22(03)	06"	TAY
22(03)	1'04"	TAY-FTW
22(03)	1'30"	Re-Crew Rio Vista siding

Train 6(02) East of Elko, NV - Freight Train Interference

03OCT25: Train 6(02) was delayed starting 114.7 miles east of Elko, NV/MP557.0, on the UPRR Shafter Subdivision, from freight interference. First, Train 6(02) met UP 9833 at Cliffside/MP781.6 followed by meeting UP 5248 at Pilot/MP789.6.

Train	Delay	Comment
6(02)	51"	

Train 7/27(02) East of Fargo, ND - Passenger Train Interference

03OCT25: Train 7/27(02) held 1.8 miles east of Fargo, ND/MP23.4X, on the BNSF Prosper Subdivision, at the Moorhead Jct/MP21.6 for Train 8/28(01) to clear the station track.

Train	Delay	Comment
7/27(02)	46"	

Train 21(02) South of Arkadelphia, AR - Freight Train Interference

03OCT25: Train 21(02) was delayed 41.6 minutes south of Arkadelphia, AR/MP410.9, on the UPRR Little Rock Subdivision, at Gurdon/MP426.5 meeting UP 7791.

Train	Delay	Comment
21(02)	41"	

Train 353(03) Pontiac, MI - Engine Failure

03OCT25: Train 353(03) was cancelled in its entirety at Pontiac, MI with partial bus alternate due to a TBU fault on E/ID4616. The equipment was coupled to 351(03) to double draft to Chicago. Four alternate buses were secured picking up Chicago bound passengers only at Troy, Detroit, Dearborn, Ann Arbor, Jackson, Battle Creek, and Kalamazoo. Passengers boarding at any of those stations who were not alighting in Chicago were not provided any alternate transportation. There was no alternate for any passengers at Royal Oak, Niles, New Buffalo, or Hammond.

Train 351(03) was delayed departing Troy, MI/MP17.4, on the CNRR Holly Subdivision, as a result of coupling the equipment prior to departure.

WBS#: B.TR.100150.6151

Train	Delay	Comment
353(03)	Cancelled	
351(03)	1'19"	ITD TRM

Metrolink Trespasser Strike - West of Fullerton, CA

02OCT25: At 10:15PM-PT, Metrolink 634 was involved in a fatal trespasser strike on Main Track No. 3 at MP159.0. Located 6.2 miles west of Fullerton, CA/MP1165.2 on the BNSF San Bernardino Subdivision. All tracks were closed with no route around. As a result, Pacific Surfliner trains, 794(02), 593(02) and 595(02) were all delayed multiple hours holding for open track. Los Angeles sheriff responded to the scene as well as local Santa Fe Springs and Metrolink police. The Homicide division and the coroner also responded. Once the tracks were released, Trains 794(02), 593(02), and 595(02) took additional delay holding for their re crews from Los Angeles. Once the re crews boarded and completed their job briefing, all trains were on the move.

Train	Delay	Comment
593(02)	4'45"	
794(02)	5'38"	
595(02)	4'31"	Witronix

Oakland, CA - Capitol Corridor/San Joaquin Services - Third Party Contractor Engine Failure

23AUG25: Account on-going high shop counts for locomotives of state-support trains in Oakland, the following modifications to service have occurred:

23AUG25:

-Train 714(23) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

24AUG25:

-Train 711(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 716(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

25AUG25:

-Train 715(25) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive

-Train 716(25) locomotive change at OMF, remove CDTX/2101 add CDTX/2123 (pulled from train 534(25))

26AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 535(26) Operating with CDTX/2007 Providing Head End Power , BNSF/4357 Providing tractive effort;

Delayed west of Sacramento when BNSF/4357 shut down after overspeed warning - PCS and Speedometer not synced.

- Train 535(26) Terminated in Emeryville for locomotives to be added to train 716(26).

- Train 716(26) received CDTX/2007 to provide HEP and BNSF/4357 to provide tractive effort from train 535(16).

- Train 716(26) Originated in Emeryville - Passengers boarding on Oakland provided bus transport to Emeryville.

- Train 534(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 549(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

27AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

-Train 715(27) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 714 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

-Train 717 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 716(27) Originates Emeryville - Extended Servicing from train 711(27).

28AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 534(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 549(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 547(28) 27 Mins late departing Sacramento - Equipment Turn from 536(28) after cancellation of 534(28).

- Train 711(28) was terminated at Emeryville, CA. to turn for an on time 714(28) out of Jack London Square, Oakland, CA.

- Train 712(28) Cancelled after dynamic brake failure on locomotive CDTX/2103.

- Train 717(28) Cancelled - equipment turn from 712(28) (after manipulations)

- Train 714(28) 1 Hour 59 Mins delay while techs resolve compressed air issues with cab car AMTK/90278

- Train 716(30) 30 mins late departing Oakland Jack London - Extended servicing in Oakland Maintenance Facility

- Train 718(30) Originates Emeryville - Techs after replacing door seal on Cab Car CDTX/8305 unable to get 'trainline complete' indication or interior lights - swapped equipment with original 712(30)

29AUG25: Normal Service Operates with No Cancellations

01SEP25:

- Train 714(01) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 711(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

02SEP25:

- Train 714(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 717(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 534(02) Delayed Departing Oakland Jack London - Locomotive Compressed Air

our California State Partners; it has been determined that a temporary reduction in Capitol Corridor and San Joaquins service is essential to perform necessary inspections, maintenance and repairs on the California state owned locomotives.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 20SEP.

-714 (03-19SEP) CANCELLED

-717 (03-19SEP) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 20SEP.

-520 (04-19SEP) CANCELLED

-534 (04-19SEP) CANCELLED

-535 (04-19SEP) CANCELLED

-549 (04-19SEP) CANCELLED

03SEP25:

- Train 712(03) Cancelled - failure of locomotive CDTX 2101 (oil leak).

- Train 711(04) Cancelled - failure of locomotive CDTX 2101 (oil leak).

04SEP25:

- Train 718(04) Originate EMY - CDTX 2101 & CDTX Failure. -Late operation.

- Train 715(04) Terminate EMY to turn for 718(04).

05SEP25:

-Train 712(05) Cancelled - failure of locomotive CDTX/2106, passengers to 716(05).

-Train 703(05) Cancelled - passengers to earlier train 719(05).

-Train 540(05) Cancelled - passengers to train 542(02).

06SEP25:

-Train 738(06) Cancelled

-Train 745(06) Cancelled

08SEP25: The temporary reduction in Capitol Corridor and San Joaquins service has now been extended through October 4.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 04OCT.

-714 (03SEP-03OCT) CANCELLED

-717 (03SEP-03OCT) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 04OCT.

-520 (04SEP-03OCT) CANCELLED

-534 (04SEP-03OCT) CANCELLED

-535 (04SEP-03OCT) CANCELLED

-549 (04SEP-03OCT) CANCELLED.

15SEP25:

To streamline departures and provide a stable service for passengers: Effective 15th September 2025.

Train #547 retimed to depart Sacramento 52 minutes later than advertised at 5:55PM-PT operating 52 mins later throughout to San Jose,.

Train #715 retimed to depart Bakersfield 01 hour later than advertised at 1:12PM-PT operating 52 mins later throughout to Oakland.

These changes will remain thru Saturday 4th October 2025

15SEP25: Train 716(15) Locomotive failed at OKJ. Train returned to OMF and new equipment was sourced. Train originate EMY, pax to train 536(15) OKJ-EMY.

03OCT25: Restoration of service planned to be phased in over the weekend of October 3rd as follows:

-714(04OCT) will operate as planned.

-717(04OCT) will remain cancelled with resumption scheduled for 717(05OCT) to allow for equipment to be positioned to BFD.

-715(04OCT) will remain operating on the modified schedule with resumption of normal schedule with train 715(05OCT).

-520/534/535/549 (06OCT) will be resumed on Monday, October 6th, 2025.

Cause: Pending

714 (23)	32"	OKJ - delay departing OMF
714 (23)	21"	Operating at reduced speeds account freight locomotive
716 (23)	25"	Follow 714 (23)
711 (24)	Terminate EMI	Pax to Bus 5011 "UNCLASSIFIED" EMI OKJ SFC
716 (24)	26"	Operating at reduced speeds account freight locomotive.
711 (24)	32"	Reduced operating speeds account freight locomotive
715 (25)	27"	W. FNO - PTC Issue on freight loco
534 (25)	CANCELLED	Pax to 536 (25)
549 (25)	CANCELLED	Pax to 551 (25)
716 (25)	1'03"	Loco change at OMF
715 (25)	23"	Operate with freight locomotive
715 (25)	17"	SKN - Freight loco air compressor issue
535 (26)	41"	West Sac - Recovery from BNSF/4357 Penalty Brake
534 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
716 (26)	1'57"	Originates Emeryville - Receiving CDTX/2007 and BNSF/4357 from 535 (26)
535 (26)	Terminates Emeryville	Oakland Passengers to 537 (26)
549 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
545 (26)	11"	SAC - Short turn of 536 (26) after 534 (26) cancelled
716 (26)	43"	Restricted not to exceed 65 mph with BNSF/4357
714 (27)	Cancelled	
717 (27)	Cancelled	
716 (27)	Originates Emeryville	Passengers to 534 (27)
715 (27)	524"	Restricted not to exceed 65 mph with BNSF/4357
715 (27)	28"	Oakley - BNSF/4357 - Penalty Brake Application Overspeed
534 (28)	Cancelled	
549 (28)	Cancelled	
711 (28)	Term EMI	
712 (28)	Cancelled	Dynamic Brake Failure
717 (28)	Cancelled	Cancellation of 712 (28))
714 (28)	1'59"	OKJ - Techs Resolve Compressed Air Issues
716 (28)	30"	OKJ - Extended Servicing Oakland Maintenance Facility
718 (28)	1'48"	EMY - Swapped Equipment after failed door seal replacement -Originates EMI
547 (28)	27"	SAC - Equipment Turn From 536 (28) after 534 (28) cancelled
714 (02SEP)	Cancelled	
717 (02SEP)	Cancelled	
714 (01SEP)	Cancelled	
711 (02SEP)	Cancelled	
718 (02SEP)	31"	OKJ - Locomotive CDTX/2103 would not start
534 (02SEP)	40"	OKJ - Locomotive Compressed air Issues
712 (03SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
711 (04SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
718 (04SEP)	2'09"	originate EMI
715 (04SEP)		Terminate EMI
712 (05SEP)	CANCELLED	Passengers to 716 (05SEP)
703 (05SEP)	CANCELLED	Passengers to earlier 719 (05SEP)
540 (05SEP)	CANCELLED	Passengers to 542 (05SEP)
716 (05SEP)	1'15"	OKJ - late departure
738 (06SEP)	CANCELLED	
745 (06SEP)	CANCELLED	
549 (04SEP-03OCT)	Cancelled	
535 (04SEP-03OCT)	Cancelled	
534 (04SEP-03OCT)	Cancelled	
520 (04SEP-03OCT)	Cancelled	
717 (03SEP-03OCT)	Cancelled	
714 (03SEP-03OCT)	Cancelled	
547 (08SEP)	36"	SAC - ITD - Equipment from 536 (08)
715 (09SEP)	1'21"	BFD - ITD - Equipt from 702 (09)
547 (09SEP)	13"	SAC - ITD - Equipt from 536 (09)
715 (10SEP)	47"	BFD - ITD - Equipt from 702 (10)
547 (10SEP)	25"	SAC - ITD - Equipment from 536 (10)
715 (11SEP)	1'15"	BFD - Equipment Turn From 702 (11)
547 (11SEP)	21"	SAC - ITD - Equipment from 536 (11)

Train	Delay	Comment
716 (15SEP)	1'49"	Loco Failed
715 (16SEP)	16"	BFD- ITD - Equipment Turn from 702 (16)
717 (04OCT)	CANCELLED	Allow for equipment to rotate to BFD with resumption
	26-FOI-00028 00000004750	of train 714 (03OCT)

"UNCLASSIFIED"

10/13/2025

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work - City of New Orleans

26-FOI-99028 10000014750 "UNCLASSIFIED" 10/13/2025

05OCT25: CN will have multiple work gangs on the CN Yazoo Subdivision, between Memphis, TN and Jackson, MS, working 5-hour work windows beginning Monday October 6th through Thursday October 9th. To accommodate this work, City of New Orleans Service adjusted as follows:

- Train 1059(05) will operate in lieu of Train 59(05), departing Chicago, IL, 2 hours earlier at 605PM-CT and will operate on an adjusted schedule to New Orleans.
- Train 59(06-08) will depart Chicago 2 hours earlier at 605PM-CT and operate on an adjusted schedule to New Orleans.
- Train 1058(06) will depart New Orleans, LA, 2 hours earlier at 1145AM-CT and operate on an adjusted schedule to Chicago.
- Train 58(07-09) will depart New Orleans 2 hours earlier at 1145AM-CT and operate on an adjusted schedule to Chicago.

WBS#: B.TR.100150.6117

Portland Marathon East of Portland, OR - Cascades Service Adjustments

05OCT25: On Sunday October 5th the Portland Marathon at SE Stark Street/MP769.78, 1 mile east of Portland, OR, on the UPRR Brooklyn Subdivision, will take place between 800AM-PT and 1200PM-PT. As a result, Cascades service adjustments as follows:

- Train 503(05) terminates at Portland, OR, with Bus 3503(05) as alternate transportation between Portland and Eugene, OR.
- Train 504(05) originates at Portland, OR and operate 1-hour later, departing Portland at 1140AM-PT. Bus 3504(05) will provide alternate transportation between Eugene and Portland, with adjusted departure times.

WBS#: B.TR.100150.6100

Union Pacific Track Work on the Moffat Tunnel Subdivision - California Zephyr Schedule Change

11SEP25: To accommodate a Union Pacific scheduled track work on the Moffat Tunnel Subdivision between Denver, CO and Glenwood Springs, CO, Train 5(19SEP and 03OCT) will be renumbered as Train 1005(19SEP AND 03OCT). The train departed Chicago, IL Union station at 5:00 p.m. (CDT), 3 hours after the normally scheduled departure time. It then continued to operate 3 hours later than the scheduled departure time through Emeryville, CA.

WBS#: B.TR.100150.6084

San Joaquins Wasco, CA - BNSF M of W Work

05OCT25: To accommodate track work in Bakersfield Subdivision, Amtrak's San Joaquins Service will be adjusted as follows:

-718(14SEP-18SEP / 21SEP-25SEP / 05OCT) - Replacement bus Fresno - Hanford - Bakersfield, CA.

-711(15SEP-19SEP / 22SEP-26SEP / 06OCT) - Replacement bus Bakersfield - Hanford - Fresno, CA.

NOTE: Replacement buses will not stop at Corcoran, CA (COC) or Wasco, CA (WAC).

Work Element WBS # B.TR.100150.6075

WBS#: B.TR.100150.6075

Train	Delay	Comment
718(14SEP-18SEP))	Terminate FNO	Replacement Bu FNO-HNF-BFD
718(28SEP-02OCT)	Terminate FNO	Replacement Bu FNO-HNF-BFD
718(21SEP-25SEP)	Terminate FNO	Replacement Bu FNO-HNF-BFD
7(5OCT-09OCT)	Terminate FNO	Replacement Bu FNO-HNF-BFD
711(22SEP-26SEP)	Originate FNO	Replacement Bus BFD-HNF-FNO
711(15SEP-19SEP)	Originate FNO	Replacement Bus BFD-HNF-FNO
71(29SEP-03OCT)	Originate FNO	Replacement Bus BFD-HNF-FNO
711(06OCT-10OCT)	Originate FNO	Replacement Bus BFD-HNF-FNO
7141(16)	1'11"	FNO, crew transportation issue at BFD

Canadian National Holly Subdivision - Pontiac Station Track Project

02SEP25: September 2nd thru September 30th, Canadian National will be performing a track project at the Pontiac, MI station. Updated 24SEP25 to extend through October 15th. The follow trains will originate and terminate at Troy, MI:

Train 350 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep -28Sep, 03Oct- 05Oct, 10Oct - 12Oct) will terminate Troy, MI.

Train 352 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 354 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 351 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

Train 353 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep - 28Sep, 03Oct - 05Oct, 10Oct - 12Oct) will originate Troy, MI

Train 355 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

There will be NO alternate transportation provided.

WBS#: B.TR.100150.6045

Michigan Department of Transportation Michigan Line affecting Wolverine Service - Scheduled M/W Work

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

05MAY25: Amtrak will be performing a track rehabilitation by modifying a curve between Chelsea, MI / MP 56.0 and Ypsilanti, MI / MP 28.2, which encompasses the Ann Arbor, MI station at MP 37.5, on the Michigan Department of Transportation Michigan Line. The follow operating plan will be placed in to effect:

May 5th through June 26th (except for May 26th and June 19th):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

August 4th through October 30th (except for September 1st):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

WBS#: B.TR.100150.5512

Train	Delay	Comment
350 & 353(27MAY - 29MAY)	Cancel	
350 & 353(16JUN - 18JUN)	Cancel	
350 & 353(23JUN - 26JUN)	Cancel	
350 & 353(04AUG - 07AUG)	Cancel	
350 & 353(11AUG - 14AUG)	Cancel	
350 & 353(18AUG - 21AUG)	Cancel	
350 & 353(25AUG - 28AUG)	Cancel	
350 & 353(02SEP - 04SEP)	Cancel	
350 & 353(08SEP - 11SEP)	Cancel	
350 & 353(15SEP - 18SEP)	Cancel	
350 & 353(22SEP - 25SEP)	Cancel	
350 & 353(29SEP - 02OCT)	Cancel	
350 & 353(06OCT - 09OCT)	Cancel	
350 & 353(13OCT - 16OCT)	Cancel	
350 & 353(20OCT - 23OCT)	Cancel	
350 & 353(27OCT - 30OCT)	Cancel	

NCTD San Diego Subdivision East of Solana Beach, CA - M of W Work

19MAY24, Commencing 12th FEB 2028, 00000004750 Court UNCLASSIFIED 10/13/2025
on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:

from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

Sunday August 4 - Tuesday August 6
Sunday August 11 - no extended window account Padres game
Sunday August 18th - Tuesday 20th
Sunday August 25 - Tuesday August 27
Sunday September 8 - Tuesday September 10.
Sunday September 15 - Monday September 16
Sunday September 22 - Tuesday September 24.
Sunday October 27 - Tuesday October 29.
Sunday November 3 - Tuesday November 5.
Sunday December 8-Tuesday December 10.
Sunday December 15-Tuesday December 17.
2025
Sunday February 9 - Tuesday February 11.
Sunday April 06th - Tuesday April 08th (CANCELLED)
Sunday May 20 - Tuesday May 22
Sunday July 20th - Tuesday July 22nd
Sunday August 3rd - Tuesday August 5th
Sunday August 10th - Tuesday August 12th
Sunday August 24th - Tuesday August 26th
Sunday October 5th - Tuesday October 7th.

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN

Western Region

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
22 (3)	SAS	UP7253	E/62 loading issues	DAL	10/4/25
22 (3)	DAL	UP2655	E/UP7253//faults speed reduced		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
519	EDM	1	SEA A3F4E6	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 48(02) Passenger Removal at Toledo, Ohio - Intoxication

03OCT25, Passenger on PNR AB69E4, traveling from Chicago, IL to New York, NY was removed from the train by the conductor. The passenger was heavily intoxicated shouting obscenities and vomiting while traveling with own alcohol. Amtrak Police notified.

Delay: 48 (02) None

Train 7(02) Passenger Removal at Fargo, North Dakota – Medical

03OCT25, Passenger on PNR 7BEDBF, traveling from Lacrosse, WI to Grand Forks, ND was removed from the by EMS after passing out in the restroom. Amtrak Police notified.

Delay: 7 (02) 10"

Train 4(01) Passenger Removal at Lawrence, Kansas – Medical

03OCT25, Passenger on PNR 649570, traveling from Los Angeles, CA to Chicago, IL was removed from the by EMS after experiencing shortness of breath and sweating profusely. Amtrak Police notified.

Delay: 4 (01) None

Train 6(01) Passenger Removal at Galesburg, Illinois – Medical

26-FOI-00028 00000004750 UNCLASSIFIED 10/13/2025

03OCT25, Passenger on PNR 900A44, traveling from Emeryville, CA to Chicago, IL was looked over by EMS at MP177, was looked over but refused to detain. Pax got off on his own at next stop. Amtrak Police notified.

Delay: 6(01) 26"

Train 14(02) Passenger Removal at Klamath Falls, Oregon – Medical

03OCT25, Passenger on PNR 9C9DCB, traveling from Sacramento, CA to Redding, CA was removed from the train by EMS after being found dazed and confused and missing her stop at Redding, CA. Amtrak Police notified.

Delay: 14(02) 38"

Train 3(02) Passenger Removal at Albuquerque, New Mexico – Improper Conduct

03OCT25, Passenger on PNR A3C7B6, traveling from Chicago, IL to Los Angeles, CA was removed from the train by the conductor after being aggressive with other passengers and using profanity. Amtrak Police notified.

Delay: 3(02) None

Consist Deviations

26-FOI-00028

00000004750

"UNCLASSIFIED"

10/13/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
177 (03)	BOS	Train 177(3) will operate with an extra Business Class car in Lieu of a coach. The extra Business class car has been positioned behind the engine.	No action required	0	81534
50 (04)	CHI	50(04) Operating with an All Table Lounge in lieu of AMII lounge due to equipment availability out of NY.			43397
51 (03)	NYP	43397 all table cafe in lieu of lounge	Passengers will be accommodated	0	43397
761 (03)	SAN	No BV space.			90215
794 (03)	SLO	No BV space			90215
172 (03)	WAS	81534 business class car in lieu of coach car	Passengers notified	0	81534

Reverse Consists

Train Number	Station	Reason	Customer Impact	Affected Psgr
93 (03)	BOS	Consist reversed Business class oriented normal At Front	0	0
111 (03)	NYP	Consist reversed Business class oriented normal At Front	0	0
181 (03)	NYP	Consist reversed Business class oriented normal At Front	0	0
183 (03)	NYP	Consist reversed Business class oriented normal At Front	0	0
2107 (03)	NYP	Acela consist reversed First class at Rear	0	0
129 (03)	NYP	Consist reversed Business class oriented backward At Front	Passengers notified	0
182 (03)	NYP	Consist reversed Business class oriented normal At Rear	Passengers notified	0
114 (03)	WAS	Consist reversed Business class oriented normal At Rear	Passengers notified	0
193 (03)	NYP	Consist reversed Business class oriented normal At Front	Passengers notified	0
88 (04)	NFK	Consist reversed Business class oriented normal At Front	Passengers notified	0
2167 (03)	BOS	Acela consist reversed First class at Rear	0	0