

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, August 18, 2026

Rules: 1-46



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/17/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/17/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	315	53	83.2%	5,124	827	83.9%	95,996	13,371	86.1%
Central Division	86.0%	53	5	90.6%	917	100	89.1%	18,273	1,666	90.9%
East Division	82.0%	176	33	81.3%	2,793	446	84.0%	50,463	7,864	84.4%
West Division	86.0%	86	15	82.6%	1,414	281	80.1%	27,260	3,841	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

 26-FOI-00671 00000008592 "UNCLASSIFIED" 9/2/2026

Endpoint Arrival Dates through 8/17/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	99,015	30,573	69%	1,827,706	577,688	68%	32,160,704	8,219,038	74%
Northeast Corridor	81%	44,320	13,993	68%	793,847	222,386	72%	14,095,360	3,478,414	75%
Acela	83%	9,843	2,312	77%	163,693	41,076	75%	2,824,117	742,627	74%
Northeast Regional	79%	34,477	11,681	66%	630,154	181,310	71%	11,271,243	2,735,787	76%
Richmond / Newport News / Norfolk	77%	11,714	6,438	45%	197,231	75,633	62%	3,497,207	1,037,094	70%
Springfield Shuttles	89%	662	113	83%	10,490	1,705	84%	198,217	31,573	84%
Roanoke	79%	2,720	1,398	49%	61,548	18,731	70%	1,066,832	237,387	78%
On Spine Northeast Regional	80%	19,381	3,732	81%	360,885	85,241	76%	6,508,987	1,429,733	78%
State Supported	80%	43,683	11,104	75%	825,634	231,574	72%	14,135,253	3,037,499	79%
Borealis	80%	565	229	59%	10,311	2,476	76%	179,937	38,108	79%
Capitol Corridor	90%	3,619	254	93%	62,384	10,720	83%	1,178,103	156,469	87%
Carolinian	70%	1,045	401	62%	19,293	9,062	53%	364,175	144,061	60%
Cascades	75%	1,334	486	64%	29,623	15,090	49%	812,873	230,126	72%
Downeaster	82%	1,581	266	83%	35,276	3,999	89%	495,589	59,954	88%
Empire	78%	6,337	2,494	61%	109,034	38,228	65%	1,752,747	421,687	76%
Adirondack	72%	520	501	4%	7,887	4,406	44%	107,850	35,251	67%
Ethan Allen Express	70%	597	571	4%	10,164	6,576	35%	179,072	66,925	63%
Maple Leaf	70%	861	474	45%	15,589	7,067	55%	215,938	83,910	61%
New York - Albany	85%	2,918	551	81%	48,590	12,898	73%	810,938	138,825	83%
New York - Niagara Falls	75%	1,441	397	72%	24,484	5,495	78%	428,516	91,176	79%
Berkshire Flyer	60%	0	0	-	2,320	1,786	23%	10,433	5,600	46%
Gold Runner	73%	1,751	1,398	20%	42,916	22,022	49%	798,482	292,475	63%
Heartland Flyer	70%	154	92	40%	4,331	3,087	29%	69,014	28,509	59%
Hiawatha	90%	1,718	0	100%	35,358	3,016	91%	556,277	60,713	89%
Illinois	78%	2,132	648	70%	46,235	19,000	59%	792,459	223,555	72%
Carl Sandburg / Illinois Zephyr	85%	242	10	96%	7,720	3,460	55%	132,520	37,618	72%
Illini / Saluki	85%	506	352	30%	13,781	6,831	50%	273,668	68,731	75%
Lincoln Service	70%	1,384	286	79%	24,734	8,709	65%	386,271	117,206	70%
Keystone	92%	8,440	709	92%	133,331	8,147	94%	2,415,450	247,693	90%
Lincoln / Missouri	70%	1,111	876	21%	15,099	10,656	29%	247,590	128,964	48%
Mardi Gras Service	80%	240	0	100%	5,425	1,127	79%	129,146	28,742	78%
Michigan	70%	2,189	1,274	42%	42,051	20,286	52%	639,476	212,707	67%
Blue Water	70%	314	304	3%	10,444	5,601	46%	150,102	61,429	59%
Pere Marquette	85%	172	0	100%	4,118	593	86%	82,552	15,717	81%
Wolverine	70%	1,703	970	43%	27,489	14,092	49%	406,822	135,561	67%
Missouri	80%	199	194	3%	4,774	2,614	45%	70,610	19,050	73%
Pacific Surfliner	85%	8,317	816	90%	176,002	47,148	73%	2,588,174	476,855	82%
Pennsylvanian	80%	900	0	100%	14,931	2,561	83%	280,733	53,638	81%
Piedmont	80%	832	73	91%	17,296	3,199	82%	357,570	91,851	74%
Vermont	75%	1,219	894	27%	21,964	9,136	58%	406,848	122,342	70%
Long Distance	70%	11,012	5,476	50%	208,225	123,728	41%	3,890,824	1,700,662	56%
Auto Train	70%	835	0	100%	14,711	3,143	79%	249,120	83,932	66%
California Zephyr	70%	912	490	46%	17,170	12,823	25%	308,764	119,480	61%
Cardinal	70%	315	192	39%	2,449	1,499	39%	73,930	37,042	50%
City Of New Orleans	75%	631	523	17%	10,275	7,964	22%	201,499	66,143	67%
Coast Starlight	70%	930	88	91%	16,821	8,727	48%	361,498	129,189	64%
Crescent	70%	897	479	47%	15,020	4,630	69%	294,673	90,613	69%
Empire Builder	70%	1,076	666	38%	17,329	10,960	37%	305,696	153,165	50%
Floridian	60%	0	0	-	23,937	19,826	17%	501,703	346,868	31%
Lake Shore Ltd	73%	1,218	244	80%	19,702	8,089	59%	306,939	93,195	70%
Palmetto	70%	506	177	65%	15,355	8,248	46%	291,458	90,857	69%
Silver Meteor	70%	1,158	1,096	5%	17,285	11,705	32%	322,485	149,056	54%
Southwest Chief	60%	907	772	15%	15,747	12,684	19%	266,213	175,277	34%
Sunset Ltd	70%	357	290	19%	4,189	3,222	23%	92,555	35,990	61%
Texas Eagle	70%	1,270	459	64%	18,235	10,208	44%	314,291	129,855	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 00000000002 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 17, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	114,805	1,792,033	641	1,904,884	33,739,971	565

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	6,399	548,758	117	92,311	9,745,760	95
INFRASTRUCTURE PLANNED	135	11,266	548,758	205	107,321	9,745,760	110
FLEET RELIABILITY	90	17,185	1,792,033	96	303,325	33,739,971	90
TRAIN OPERATIONS	424	79,955	1,792,033	446	1,401,927	33,739,971	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/17/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/17/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	315	53	83.2%	5,124	827	83.9%	95,996	13,371	86.1%
Central Division	86.0%	53	5	90.6%	917	100	89.1%	18,273	1,666	90.9%
East Division	82.0%	176	33	81.3%	2,793	446	84.0%	50,463	7,864	84.4%
West Division	86.0%	86	15	82.6%	1,414	281	80.1%	27,260	3,841	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/17/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/17/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	315	53	83.2%	5,124	827	83.9%	95,996	13,371	86.1%
Central Division	86.0%	53	5	90.6%	917	100	89.1%	18,273	1,666	90.9%
CDL	95.0%	2	1	50.0%	32	4	87.5%	608	29	95.2%
CHI	86.0%	24	4	83.3%	423	68	83.9%	8,437	1,032	87.8%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	17	0	100.0%	344	36	89.5%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	-	-	-	11	0	100.0%	299	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	1	0	100.0%	17	3	82.4%	574	45	92.2%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	98	6	93.9%	1,878	120	93.6%
MOE	97.5%	2	0	100.0%	34	0	100.0%	639	9	98.6%
MSP	96.5%	1	0	100.0%	17	1	94.1%	314	7	97.8%
NOL	94.5%	5	0	100.0%	75	2	97.3%	1,348	62	95.4%
OKC	97.0%	1	0	100.0%	17	0	100.0%	315	6	98.1%
PNT	88.0%	3	0	100.0%	48	5	89.6%	835	69	91.7%
PTH	93.0%	1	0	100.0%	17	2	88.2%	309	13	95.8%
QCY	91.0%	1	0	100.0%	28	2	92.9%	605	45	92.6%
SAS	90.5%	1	0	100.0%	17	3	82.4%	318	36	88.7%
STL	89.0%	4	0	100.0%	65	3	95.4%	1,234	100	91.9%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	33	81.3%	2,793	446	84.0%	50,463	7,864	84.4%
ALB	88.5%	8	0	100.0%	126	6	95.2%	2,376	181	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	85	11	87.1%	1,551	169	89.1%
BOS	85.5%	18	7	61.1%	293	26	91.1%	5,456	630	88.5%
BRK	92.5%	2	1	50.0%	82	8	90.2%	1,534	110	92.8%
BTN	82.0%	1	0	100.0%	16	1	93.8%	306	42	86.3%
CLT	91.5%	5	0	100.0%	85	8	90.6%	1,562	158	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	27	2	92.6%	620	59	90.5%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	1	92.3%	185	29	84.3%	3,549	577	83.7%
HFD	-	2	0	100.0%	21	3	85.7%	212	18	91.5%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	17	0	100.0%	317	38	88.0%
MIA	89.5%	2	0	100.0%	31	4	87.1%	631	72	88.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/17/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/17/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	315	53	83.2%	5,124	827	83.9%	95,996	13,371	86.1%
East Division	82.0%	176	33	81.3%	2,793	446	84.0%	50,463	7,864	84.4%
MTR	79.0%	1	0	100.0%	17	5	70.6%	304	57	81.3%
NFK	84.5%	2	0	100.0%	34	6	82.4%	717	129	82.0%
NFL	93.5%	2	0	100.0%	34	1	97.1%	646	30	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	3	40.0%	82	24	70.7%	1,636	277	83.1%
NPN	93.0%	2	0	100.0%	34	5	85.3%	606	46	92.4%
NYP	75.5%	50	10	80.0%	784	177	77.4%	13,268	2,955	77.7%
PGH	93.0%	1	0	100.0%	17	1	94.1%	318	23	92.8%
PHL	48.0%	5	2	60.0%	79	33	58.2%	1,629	773	52.5%
PIT	76.0%	-	-	-	5	5	0.0%	20	17	15.0%
POR	-	3	2	33.3%	3	2	33.3%	14	10	28.6%
RGH	95.0%	4	0	100.0%	60	2	96.7%	1,218	51	95.8%
RNK	83.5%	2	0	100.0%	34	2	94.1%	630	89	85.9%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	14	0	100.0%	301	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	17	1	94.1%	314	11	96.5%
SFA	88.0%	1	0	100.0%	17	1	94.1%	317	42	86.8%
SPG	92.5%	5	0	100.0%	82	5	93.9%	1,889	110	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	17	3	82.4%	306	63	79.4%
WAS	84.0%	31	6	80.6%	487	75	84.6%	7,959	1,042	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	86	15	82.6%	1,414	281	80.1%	27,260	3,841	85.9%
ARN	92.0%	1	1	0.0%	17	2	88.2%	319	28	91.2%
BFD	79.0%	7	5	28.6%	118	30	74.6%	2,015	423	79.0%
EMY	72.0%	1	0	100.0%	17	3	82.4%	335	97	71.0%
EUG	86.5%	2	0	100.0%	34	2	94.1%	632	58	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	51	15	70.6%	960	158	83.5%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	174	19	89.1%	3,173	345	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	2	84.6%	195	71	63.6%	3,456	899	74.0%
PDX	86.0%	3	3	0.0%	44	30	31.8%	1,532	211	86.2%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/17/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/17/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	315	53	83.2%	5,124	827	83.9%	95,996	13,371	86.1%
West Division	86.0%	86	15	82.6%	1,414	281	80.1%	27,260	3,841	85.9%
SAC	88.5%	16	1	93.8%	245	25	89.8%	4,511	487	89.2%
SAN	90.5%	13	0	100.0%	216	19	91.2%	3,857	363	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	0	100.0%	69	30	56.5%	2,454	377	84.6%
SJC	89.0%	7	1	85.7%	118	11	90.7%	2,242	220	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	51	6	88.2%	723	71	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	34	0	100.0%	625	14	97.8%
VAN	-	2	1	50.0%	25	15	40.0%	25	15	40.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	73	8	1	87.5%	136	10	92.6%	6	6	0.0%	135	37	72.6%
3		17	3	82.4%	319	62	80.6%	16	11	31.3%	316	147	53.5%
4	102	17	1	94.1%	318	47	85.2%	17	13	23.5%	318	212	33.3%
5		17	3	82.4%	317	53	83.3%	17	14	17.6%	313	102	67.4%
6	217	17	3	82.4%	316	88	72.2%	17	16	5.9%	316	119	62.3%
7		17	4	76.5%	308	46	85.1%	16	7	56.3%	299	81	72.9%
8	66	17	10	41.2%	308	139	54.9%	17	13	23.5%	307	188	38.8%
11		17	14	17.6%	319	71	77.7%	17	5	70.6%	313	65	79.2%
14		17	2	88.2%	320	51	84.1%	16	10	37.5%	317	102	67.8%
19	60	17	3	82.4%	318	80	74.8%	17	5	70.6%	315	76	75.9%
20		17	0	100.0%	318	23	92.8%	17	4	76.5%	318	62	80.5%
21		17	6	64.7%	315	31	90.2%	17	5	70.6%	314	87	72.3%
22		17	3	82.4%	316	34	89.2%	17	9	47.1%	314	90	71.3%
23		17	0	100.0%	320	6	98.1%	17	3	82.4%	318	88	72.3%
24		17	0	100.0%	320	16	95.0%	17	5	70.6%	319	61	80.9%
25		17	0	100.0%	319	3	99.1%	16	6	62.5%	316	89	71.8%
26		17	0	100.0%	319	5	98.4%	16	1	93.8%	316	61	80.7%
42		17	1	94.1%	320	25	92.2%	17	3	82.4%	318	55	82.7%
43		17	2	88.2%	319	44	86.2%	17	2	88.2%	318	72	77.4%
48		17	4	76.5%	318	61	80.8%	17	5	70.6%	317	47	85.2%
49		17	5	70.6%	318	80	74.8%	17	5	70.6%	318	67	78.9%
51	356	4	2	50.0%	130	57	56.2%	5	4	20.0%	126	48	61.9%
52		17	1	94.1%	317	42	86.8%	17	0	100.0%	316	72	77.2%
53		17	0	100.0%	317	38	88.0%	17	5	70.6%	316	100	68.4%
55	67	11	1	90.9%	201	8	96.0%	11	4	63.6%	198	42	78.8%
56		11	2	81.8%	202	25	87.6%	11	5	54.5%	198	39	80.3%
58	615	16	1	93.8%	293	17	94.2%	15	13	13.3%	291	86	70.4%
59	171	17	11	35.3%	292	44	84.9%	16	13	18.8%	287	70	75.6%
63	75	17	8	52.9%	321	140	56.4%	17	17	0.0%	315	183	41.9%
64	20	17	3	82.4%	319	71	77.7%	17	13	23.5%	318	122	61.6%
66	32	17	1	94.1%	318	62	80.5%	17	5	70.6%	314	59	81.2%
67		12	1	91.7%	220	14	93.6%	11	3	72.7%	219	39	82.2%
68	78	17	5	70.6%	321	66	79.4%	17	11	35.3%	320	129	59.7%
69	70	17	8	52.9%	308	76	75.3%	17	9	47.1%	303	52	82.8%
71		17	0	100.0%	316	3	99.1%	16	4	75.0%	314	85	72.9%
72		17	3	82.4%	312	34	89.1%	16	6	62.5%	310	67	78.4%
73		17	2	88.2%	315	21	93.3%	17	4	76.5%	313	146	53.4%
74		17	0	100.0%	313	33	89.5%	17	4	76.5%	311	112	64.0%
75		17	0	100.0%	309	16	94.8%	17	7	58.8%	303	144	52.5%
76		17	1	94.1%	309	30	90.3%	17	7	58.8%	300	124	58.7%
77	14	17	0	100.0%	311	20	93.6%	17	5	70.6%	309	128	58.6%
78		17	1	94.1%	315	26	91.7%	17	8	52.9%	314	71	77.4%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79		17	2	88.2%	318	58	81.8%	17	6	64.7%	317	107	66.2%
80		17	3	82.4%	318	36	88.7%	17	8	52.9%	315	71	77.5%
84		11	4	63.6%	192	18	90.6%	9	4	55.6%	188	47	75.0%
85	20	11	2	81.8%	203	18	91.1%	11	4	63.6%	203	74	63.5%
86		11	1	90.9%	203	16	92.1%	11	4	63.6%	202	119	41.1%
89	34	17	8	52.9%	316	73	76.9%	17	10	41.2%	314	95	69.7%
90	104	17	1	94.1%	316	11	96.5%	17	7	58.8%	315	58	81.6%
93	60	11	2	81.8%	202	21	89.6%	11	7	36.4%	201	54	73.1%
94	16	11	3	72.7%	233	58	75.1%	11	4	63.6%	231	87	62.3%
95	75	11	2	81.8%	202	6	97.0%	11	9	18.2%	202	78	61.4%
97	52	17	11	35.3%	318	209	34.3%	17	12	29.4%	316	112	64.6%
98	38	17	0	100.0%	318	26	91.8%	17	10	41.2%	316	118	62.7%
110	44	11	1	90.9%	199	103	48.2%	11	1	90.9%	196	20	89.8%
111		11	1	90.9%	193	36	81.3%	11	1	90.9%	191	22	88.5%
112		11	1	90.9%	193	19	90.2%	11	0	100.0%	192	19	90.1%
113		11	4	63.6%	124	29	76.6%	11	1	90.9%	123	15	87.8%
119	88	11	2	81.8%	190	47	75.3%	11	4	63.6%	188	26	86.2%
125	30	11	1	90.9%	203	12	94.1%	11	7	36.4%	203	81	60.1%
128	36	6	0	100.0%	118	19	83.9%	6	2	66.7%	118	24	79.7%
129		11	2	81.8%	202	49	75.7%	11	1	90.9%	202	29	85.6%
130		11	2	81.8%	193	20	89.6%	11	0	100.0%	191	16	91.6%
131	30	11	3	72.7%	195	56	71.3%	11	1	90.9%	195	36	81.5%
134		11	3	72.7%	203	30	85.2%	11	4	63.6%	202	40	80.2%
137		11	1	90.9%	200	36	82.0%	11	3	72.7%	200	61	69.5%
138	77	11	1	90.9%	203	40	80.3%	11	4	63.6%	202	38	81.2%
139	52	3	0	100.0%	41	5	87.8%	3	2	33.3%	41	15	63.4%
141		11	1	90.9%	202	4	98.0%	11	2	81.8%	201	35	82.6%
148	17	11	2	81.8%	202	22	89.1%	11	3	72.7%	200	39	80.5%
151		17	6	64.7%	317	101	68.1%	17	2	88.2%	316	97	69.3%
166	46	3	1	66.7%	41	6	85.4%	3	1	66.7%	40	14	65.0%
169	18	6	0	100.0%	116	12	89.7%	6	2	66.7%	116	26	77.6%
170		11	0	100.0%	198	12	93.9%	11	0	100.0%	197	29	85.3%
171	67	11	0	100.0%	203	11	94.6%	11	9	18.2%	203	84	58.6%
172		11	3	72.7%	202	18	91.1%	11	7	36.4%	200	69	65.5%
173		11	1	90.9%	195	25	87.2%	11	5	54.5%	194	83	57.2%
174		11	2	81.8%	203	22	89.2%	11	4	63.6%	203	52	74.4%
175	44	11	1	90.9%	203	23	88.7%	11	4	63.6%	203	66	67.5%
176		11	2	81.8%	195	17	91.3%	11	2	81.8%	193	26	86.5%
177		11	0	100.0%	203	27	86.7%	11	0	100.0%	203	46	77.3%
181		11	3	72.7%	199	62	68.8%	10	1	90.0%	196	16	91.8%
182		11	1	90.9%	193	31	83.9%	11	0	100.0%	191	21	89.0%
183		11	6	45.5%	202	62	69.3%	11	5	54.5%	199	43	78.4%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		11	2	81.8%	203	35	82.8%	11	1	90.9%	202	28	86.1%
185		11	2	81.8%	203	39	80.8%	11	1	90.9%	203	15	92.6%
186		11	4	63.6%	202	25	87.6%	11	7	36.4%	201	60	70.1%
190		11	2	81.8%	202	71	64.9%	11	1	90.9%	201	44	78.1%
192		11	0	100.0%	200	24	88.0%	11	1	90.9%	200	18	91.0%
193		10	4	60.0%	198	82	58.6%	10	1	90.0%	197	89	54.8%
196		11	2	81.8%	199	22	88.9%	10	1	90.0%	197	16	91.9%
197		11	1	90.9%	203	76	62.6%	11	2	81.8%	203	69	66.0%
230		17	0	100.0%	154	4	97.4%	17	0	100.0%	154	7	95.5%
232		17	0	100.0%	320	11	96.6%	17	2	88.2%	320	23	92.8%
233	28	12	2	83.3%	285	63	77.9%	12	6	50.0%	284	94	66.9%
234	30	17	0	100.0%	321	22	93.1%	17	1	94.1%	320	26	91.9%
235		17	7	58.8%	245	41	83.3%	17	5	70.6%	244	57	76.6%
236		17	0	100.0%	305	10	96.7%	17	3	82.4%	304	42	86.2%
237		17	0	100.0%	318	56	82.4%	17	3	82.4%	316	54	82.9%
238		17	3	82.4%	245	23	90.6%	17	3	82.4%	243	21	91.4%
239		17	2	88.2%	319	81	74.6%	17	2	88.2%	318	40	87.4%
240		17	1	94.1%	320	22	93.1%	17	5	70.6%	317	65	79.5%
241		17	6	64.7%	320	80	75.0%	17	7	58.8%	320	78	75.6%
243		17	4	76.5%	256	69	73.0%	17	3	82.4%	255	36	85.9%
244		12	0	100.0%	284	12	95.8%	12	9	25.0%	284	58	79.6%
245		17	5	70.6%	201	38	81.1%	17	5	70.6%	200	27	86.5%
280	45	17	1	94.1%	321	16	95.0%	17	7	58.8%	320	68	78.8%
281		17	2	88.2%	321	39	87.9%	17	2	88.2%	321	59	81.6%
283		17	8	52.9%	321	82	74.5%	17	3	82.4%	321	64	80.1%
284		17	0	100.0%	321	13	96.0%	17	1	94.1%	318	55	82.7%
290	28	17	1	94.1%	321	51	84.1%	17	12	29.4%	318	126	60.4%
291	23	17	11	35.3%	320	104	67.5%	16	8	50.0%	317	84	73.5%
300		15	1	93.3%	303	21	93.1%	15	5	66.7%	301	73	75.7%
301		17	0	100.0%	318	10	96.9%	17	5	70.6%	314	60	80.9%
302		16	0	100.0%	299	33	89.0%	16	7	56.3%	295	85	71.2%
305		15	1	93.3%	301	29	90.4%	15	4	73.3%	297	119	59.9%
306	47	17	1	94.1%	316	17	94.6%	16	5	68.8%	314	87	72.3%
307	61	17	2	88.2%	309	40	87.1%	16	6	62.5%	305	88	71.1%
311	39	17	1	94.1%	314	27	91.4%	17	10	41.2%	308	73	76.3%
316	57	17	3	82.4%	310	21	93.2%	17	12	29.4%	305	90	70.5%
318	99	17	2	88.2%	319	33	89.7%	17	12	29.4%	316	156	50.6%
319	59	17	0	100.0%	320	20	93.8%	17	16	5.9%	315	181	42.5%
329		11	0	100.0%	226	9	96.0%	11	1	90.9%	226	16	92.9%
330		14	0	100.0%	272	6	97.8%	14	0	100.0%	272	15	94.5%
331		17	0	100.0%	321	33	89.7%	16	0	100.0%	320	44	86.3%
332		16	1	93.8%	320	18	94.4%	16	2	87.5%	320	45	85.9%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		17	1	94.1%	321	11	96.6%	16	1	93.8%	319	41	87.1%
335		17	0	100.0%	321	34	89.4%	17	3	82.4%	319	54	83.1%
336		17	0	100.0%	321	10	96.9%	17	0	100.0%	319	28	91.2%
337		17	1	94.1%	321	19	94.1%	17	5	70.6%	317	41	87.1%
338		17	3	82.4%	321	50	84.4%	17	6	64.7%	319	100	68.7%
339		17	3	82.4%	321	53	83.5%	17	3	82.4%	321	56	82.6%
341		16	4	75.0%	308	48	84.4%	16	8	50.0%	302	49	83.8%
342		17	1	94.1%	321	25	92.2%	17	0	100.0%	319	60	81.2%
350	27	15	0	100.0%	296	18	93.9%	15	12	20.0%	289	163	43.6%
351		16	2	87.5%	303	29	90.4%	16	7	56.3%	301	85	71.8%
352	51	16	3	81.3%	287	24	91.6%	16	8	50.0%	281	89	68.3%
353	32	17	0	100.0%	259	13	95.0%	17	7	58.8%	253	45	82.2%
354		17	1	94.1%	302	36	88.1%	17	12	29.4%	295	113	61.7%
355	75	15	3	80.0%	309	34	89.0%	14	12	14.3%	301	111	63.1%
364	21	17	5	70.6%	310	70	77.4%	17	9	47.1%	304	116	61.8%
365	48	17	2	88.2%	309	13	95.8%	16	8	50.0%	306	117	61.8%
370		12	1	91.7%	307	36	88.3%	11	3	72.7%	296	72	75.7%
380		14	1	92.9%	303	28	90.8%	13	4	69.2%	302	67	77.8%
383		15	1	93.3%	308	27	91.2%	15	8	46.7%	305	131	57.0%
390	270	16	4	75.0%	302	23	92.4%	15	10	33.3%	300	83	72.3%
391	34	16	2	87.5%	303	13	95.7%	16	11	31.3%	299	87	70.9%
392		16	0	100.0%	316	10	96.8%	15	6	60.0%	312	96	69.2%
417		11	2	81.8%	213	46	78.4%	11	2	81.8%	204	24	88.2%
425		10	1	90.0%	214	7	96.7%	9	0	100.0%	213	7	96.7%
448		11	2	81.8%	245	45	81.6%	10	4	60.0%	241	84	65.1%
449		11	1	90.9%	242	33	86.4%	11	2	81.8%	242	44	81.8%
470		11	2	81.8%	226	39	82.7%	11	2	81.8%	220	26	88.2%
471		10	2	80.0%	215	13	94.0%	10	0	100.0%	215	5	97.7%
473		11	0	100.0%	222	15	93.2%	11	0	100.0%	219	10	95.4%
474		11	2	81.8%	220	65	70.5%	11	4	63.6%	205	67	67.3%
475		11	1	90.9%	220	7	96.8%	11	0	100.0%	220	15	93.2%
478		11	3	72.7%	214	35	83.6%	11	1	90.9%	212	28	86.8%
479	23	11	2	81.8%	221	36	83.7%	11	3	72.7%	219	34	84.5%
486		11	3	72.7%	225	34	84.9%	11	2	81.8%	219	60	72.6%
494	60	12	5	58.3%	228	46	79.8%	11	4	63.6%	220	61	72.3%
495		11	0	100.0%	210	4	98.1%	11	0	100.0%	208	3	98.6%
503		17	13	23.5%	317	40	87.4%	17	12	29.4%	310	99	68.1%
504	22	17	1	94.1%	321	20	93.8%	17	5	70.6%	319	95	70.2%
505		11	1	90.9%	313	42	86.6%	11	4	63.6%	308	88	71.4%
506		17	12	29.4%	316	54	82.9%	15	3	80.0%	308	49	84.1%
507	19	17	11	35.3%	321	47	85.4%	17	11	35.3%	321	111	65.4%
508		17	1	94.1%	316	42	86.7%	17	10	41.2%	312	78	75.0%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
516		17	6	64.7%	312	35	88.8%	17	8	52.9%	311	142	54.3%
517	18	17	0	100.0%	321	8	97.5%	17	14	17.6%	317	141	55.5%
518	68	17	8	52.9%	321	45	86.0%	17	17	0.0%	319	224	29.8%
519		17	0	100.0%	312	9	97.1%	17	4	76.5%	310	70	77.4%
520		11	3	72.7%	184	28	84.8%	9	1	88.9%	179	10	94.4%
521		11	0	100.0%	222	7	96.8%	11	3	72.7%	222	30	86.5%
522		11	2	81.8%	222	41	81.5%	11	1	90.9%	219	21	90.4%
523	17	11	2	81.8%	222	9	95.9%	11	3	72.7%	221	25	88.7%
524		10	1	90.0%	221	17	92.3%	10	2	80.0%	218	25	88.5%
525		10	0	100.0%	219	16	92.7%	10	1	90.0%	215	15	93.0%
526		11	6	45.5%	196	40	79.6%	11	3	72.7%	193	18	90.7%
527		11	0	100.0%	222	10	95.5%	11	2	81.8%	221	39	82.4%
528		11	0	100.0%	222	17	92.3%	11	1	90.9%	221	31	86.0%
529		11	1	90.9%	222	13	94.1%	11	4	63.6%	221	62	71.9%
530		11	1	90.9%	176	17	90.3%	11	3	72.7%	176	35	80.1%
531		11	0	100.0%	196	13	93.4%	11	0	100.0%	196	13	93.4%
532	16	11	4	63.6%	222	55	75.2%	10	3	70.0%	220	34	84.5%
534		11	2	81.8%	181	27	85.1%	11	0	100.0%	179	16	91.1%
535		10	1	90.0%	208	26	87.5%	10	2	80.0%	203	25	87.7%
536		11	4	63.6%	222	59	73.4%	11	2	81.8%	218	40	81.7%
537		10	0	100.0%	191	22	88.5%	10	2	80.0%	185	22	88.1%
538		11	1	90.9%	222	25	88.7%	11	2	81.8%	221	45	79.6%
539		11	1	90.9%	176	25	85.8%	11	5	54.5%	176	76	56.8%
540		11	1	90.9%	221	39	82.4%	10	1	90.0%	212	19	91.0%
541		11	1	90.9%	221	23	89.6%	11	2	81.8%	215	38	82.3%
542		11	0	100.0%	221	24	89.1%	11	3	72.7%	218	40	81.7%
543		11	1	90.9%	222	25	88.7%	11	4	63.6%	222	67	69.8%
544		11	1	90.9%	220	21	90.5%	10	2	80.0%	216	22	89.8%
545		11	1	90.9%	222	18	91.9%	11	3	72.7%	219	27	87.7%
547		11	5	54.5%	222	46	79.3%	11	5	54.5%	222	52	76.6%
548		10	1	90.0%	216	22	89.8%	9	1	88.9%	213	16	92.5%
549		11	1	90.9%	217	27	87.6%	10	3	70.0%	208	20	90.4%
550		11	1	90.9%	176	19	89.2%	11	5	54.5%	176	41	76.7%
551		11	1	90.9%	218	23	89.4%	11	2	81.8%	208	22	89.4%
562		17	2	88.2%	312	25	92.0%	17	0	100.0%	308	35	88.6%
564		17	0	100.0%	313	19	93.9%	17	3	82.4%	305	41	86.6%
566		17	3	82.4%	311	28	91.0%	17	6	64.7%	308	51	83.4%
567		17	0	100.0%	198	10	94.9%	17	2	88.2%	196	11	94.4%
572	16	17	2	88.2%	308	26	91.6%	17	8	52.9%	301	91	69.8%
573		17	2	88.2%	310	42	86.5%	17	3	82.4%	303	54	82.2%
579		17	1	94.1%	198	12	93.9%	16	3	81.3%	192	40	79.2%
580		17	1	94.1%	313	17	94.6%	17	4	76.5%	306	32	89.5%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
581		17	3	82.4%	313	53	83.1%	17	7	58.8%	311	71	77.2%
584		17	3	82.4%	197	28	85.8%	17	16	5.9%	192	124	35.4%
587		17	2	88.2%	306	18	94.1%	17	4	76.5%	297	57	80.8%
588		15	1	93.3%	196	19	90.3%	15	5	66.7%	195	38	80.5%
591		17	1	94.1%	310	22	92.9%	16	4	75.0%	303	43	85.8%
593		14	2	85.7%	304	49	83.9%	14	1	92.9%	283	38	86.6%
595		15	3	80.0%	306	56	81.7%	15	4	73.3%	303	64	78.9%
600		11	0	100.0%	230	9	96.1%	11	1	90.9%	228	20	91.2%
601		11	5	54.5%	213	88	58.7%	11	2	81.8%	210	27	87.1%
605		11	6	45.5%	220	136	38.2%	11	0	100.0%	216	22	89.8%
607		11	0	100.0%	229	30	86.9%	11	0	100.0%	226	25	88.9%
609	15	11	0	100.0%	220	23	89.5%	11	2	81.8%	219	21	90.4%
622		9	1	88.9%	129	33	74.4%	9	0	100.0%	127	5	96.1%
626		11	3	72.7%	134	19	85.8%	11	0	100.0%	132	18	86.4%
637		6	0	100.0%	69	7	89.9%	6	1	83.3%	69	6	91.3%
639		11	1	90.9%	200	39	80.5%	11	0	100.0%	199	19	90.5%
640		11	0	100.0%	220	7	96.8%	11	4	63.6%	218	84	61.5%
641		11	3	72.7%	202	41	79.7%	11	1	90.9%	202	27	86.6%
642		11	2	81.8%	218	11	95.0%	11	0	100.0%	217	26	88.0%
643		11	0	100.0%	232	44	81.0%	11	2	81.8%	229	38	83.4%
644		11	0	100.0%	224	28	87.5%	11	2	81.8%	222	54	75.7%
645	14	11	0	100.0%	232	41	82.3%	11	7	36.4%	229	53	76.9%
646		11	1	90.9%	221	52	76.5%	11	5	54.5%	219	106	51.6%
647		11	0	100.0%	232	32	86.2%	11	0	100.0%	231	49	78.8%
648		11	2	81.8%	228	58	74.6%	11	1	90.9%	228	35	84.6%
649		11	1	90.9%	233	43	81.5%	11	0	100.0%	230	34	85.2%
650		11	3	72.7%	232	44	81.0%	11	1	90.9%	229	37	83.8%
651		11	1	90.9%	232	17	92.7%	11	1	90.9%	230	43	81.3%
652		11	2	81.8%	233	31	86.7%	11	2	81.8%	229	39	83.0%
653		11	3	72.7%	221	36	83.7%	11	1	90.9%	218	40	81.7%
654		11	2	81.8%	222	42	81.1%	11	1	90.9%	218	19	91.3%
655		11	2	81.8%	230	74	67.8%	11	2	81.8%	228	75	67.1%
656	28	11	5	54.5%	232	52	77.6%	11	2	81.8%	231	32	86.1%
657		11	2	81.8%	221	29	86.9%	11	0	100.0%	220	29	86.8%
658		11	1	90.9%	232	36	84.5%	11	0	100.0%	230	33	85.7%
680		11	0	100.0%	227	12	94.7%	11	0	100.0%	226	27	88.1%
681		11	0	100.0%	227	17	92.5%	11	5	54.5%	221	91	58.8%
682		11	1	90.9%	226	7	96.9%	11	1	90.9%	226	39	82.7%
683	38	11	1	90.9%	209	18	91.4%	11	3	72.7%	208	70	66.3%
684		11	2	81.8%	208	34	83.7%	11	0	100.0%	208	45	78.4%
685		11	0	100.0%	223	31	86.1%	11	1	90.9%	220	54	75.5%
686	38	11	1	90.9%	228	38	83.3%	11	4	63.6%	227	51	77.5%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
687		11	3	72.7%	227	37	83.7%	11	2	81.8%	226	38	83.2%
688		11	1	90.9%	226	14	93.8%	11	3	72.7%	225	39	82.7%
699		2	0	100.0%	64	8	87.5%	2	0	100.0%	64	3	95.3%
701	206	17	3	82.4%	253	28	88.9%	17	4	76.5%	250	29	88.4%
702	34	17	0	100.0%	320	32	90.0%	17	7	58.8%	317	77	75.7%
703	60	17	12	29.4%	321	105	67.3%	17	10	41.2%	319	95	70.2%
704	37	17	5	70.6%	252	42	83.3%	16	6	62.5%	244	52	78.7%
710	109	17	1	94.1%	321	78	75.7%	17	5	70.6%	317	86	72.9%
711	Cncl'd	17	1	94.1%	312	35	88.8%	15	8	46.7%	289	60	79.2%
712	112	17	8	52.9%	318	88	72.3%	17	9	47.1%	309	107	65.4%
713	Cncl'd	16	1	93.8%	188	17	91.0%	12	8	33.3%	168	75	55.4%
714	94	17	10	41.2%	202	85	57.9%	15	11	26.7%	186	87	53.2%
715	125	17	1	94.1%	320	62	80.6%	14	8	42.9%	294	149	49.3%
716	109	17	12	29.4%	321	132	58.9%	16	13	18.8%	314	131	58.3%
717	51	17	4	76.5%	306	72	76.5%	14	5	64.3%	284	91	68.0%
718		17	12	29.4%	321	165	48.6%	16	11	31.3%	318	120	62.3%
719	128	17	8	52.9%	321	111	65.4%	16	8	50.0%	304	92	69.7%
757		17	1	94.1%	106	6	94.3%	17	2	88.2%	105	10	90.5%
761		17	1	94.1%	317	13	95.9%	17	2	88.2%	314	43	86.3%
765		17	0	100.0%	317	25	92.1%	17	3	82.4%	317	45	85.8%
769		17	0	100.0%	317	27	91.5%	17	4	76.5%	311	61	80.4%
770		17	2	88.2%	317	24	92.4%	17	10	41.2%	315	99	68.6%
774		17	0	100.0%	317	16	95.0%	17	5	70.6%	316	74	76.6%
777		17	0	100.0%	202	12	94.1%	17	8	52.9%	201	50	75.1%
782		17	12	29.4%	202	94	53.5%	17	5	70.6%	197	30	84.8%
785		17	4	76.5%	317	26	91.8%	17	5	70.6%	317	58	81.7%
786	18	17	2	88.2%	106	21	80.2%	16	10	37.5%	102	57	44.1%
790		17	1	94.1%	317	29	90.9%	17	3	82.4%	314	49	84.4%
794		17	4	76.5%	317	37	88.3%	17	6	64.7%	313	72	77.0%
821		17	0	100.0%	315	6	98.1%	17	11	35.3%	315	132	58.1%
822	26	17	0	100.0%	317	16	95.0%	17	15	11.8%	315	157	50.2%
1333	118	17	4	76.5%	317	36	88.6%	17	5	70.6%	314	104	66.9%
1340		17	1	94.1%	316	7	97.8%	17	4	76.5%	316	55	82.6%
2102		11	1	90.9%	79	14	82.3%	11	1	90.9%	78	7	91.0%
2103		11	1	90.9%	143	13	90.9%	11	1	90.9%	142	10	93.0%
2104		11	0	100.0%	169	10	94.1%	11	1	90.9%	167	13	92.2%
2107		11	1	90.9%	200	35	82.5%	11	1	90.9%	197	21	89.3%
2108		11	2	81.8%	200	28	86.0%	11	6	45.5%	194	26	86.6%
2109		11	1	90.9%	93	12	87.1%	11	1	90.9%	91	5	94.5%
2112		11	1	90.9%	40	5	87.5%	11	0	100.0%	38	2	94.7%
2113		11	1	90.9%	79	9	88.6%	11	0	100.0%	79	10	87.3%
2115		11	1	90.9%	79	12	84.8%	11	1	90.9%	78	11	85.9%

Amtrak On Time Performance

Trains Arriving Through: 8/17/2026

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2116		11	0	100.0%	40	1	97.5%	11	1	90.9%	40	8	80.0%
2118		11	2	81.8%	40	4	90.0%	11	2	81.8%	40	11	72.5%
2119		11	2	81.8%	40	6	85.0%	10	2	80.0%	39	12	69.2%
2120	54	11	8	27.3%	40	17	57.5%	10	8	20.0%	38	21	44.7%
2123		11	1	90.9%	78	9	88.5%	11	0	100.0%	77	15	80.5%
2124		10	4	60.0%	171	38	77.8%	10	2	80.0%	169	24	85.8%
2127		11	2	81.8%	40	9	77.5%	11	1	90.9%	39	8	79.5%
2128		11	1	90.9%	40	4	90.0%	11	1	90.9%	40	3	92.5%
2131		11	3	72.7%	40	9	77.5%	11	1	90.9%	40	4	90.0%
2150		11	0	100.0%	193	22	88.6%	11	1	90.9%	190	74	61.1%
2151	37	11	1	90.9%	142	7	95.1%	11	3	72.7%	140	40	71.4%
2152		11	1	90.9%	98	7	92.9%	11	1	90.9%	97	31	68.0%
2154		11	0	100.0%	101	23	77.2%	11	3	72.7%	97	45	53.6%
2155	69	11	1	90.9%	202	17	91.6%	11	4	63.6%	198	100	49.5%
2158		11	1	90.9%	39	5	87.2%	11	3	72.7%	39	15	61.5%
2159	63	11	2	81.8%	195	16	91.8%	11	7	36.4%	193	66	65.8%
2160		11	0	100.0%	40	2	95.0%	11	7	36.4%	39	25	35.9%
2162		11	4	63.6%	201	22	89.1%	11	5	54.5%	195	90	53.8%
2165	27	11	1	90.9%	37	3	91.9%	11	8	27.3%	37	21	43.2%
2167		11	0	100.0%	188	20	89.4%	11	1	90.9%	188	40	78.7%
2171		11	0	100.0%	129	10	92.2%	11	0	100.0%	125	23	81.6%
2190		11	2	81.8%	198	29	85.4%	11	1	90.9%	196	24	87.8%
2193		11	0	100.0%	193	25	87.0%	11	1	90.9%	191	50	73.8%
2233		3	1	66.7%	25	5	80.0%	2	0	100.0%	24	4	83.3%
2264	28	3	0	100.0%	7	0	100.0%	3	2	33.3%	7	6	14.3%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/17/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2120	NYP	54	ITI	54	ITI	54	WAS-WAS	AM	Service, turn, or wye train, 2159, 2159 arrived was 507p 1'04" late	
2151	WAS	37	DET	16	DET	16	RTE-RTE	AM	Catenary failure, Milepost, rte, rte, waiting at RTE no power / wires down	
2155	WAS	69	SVS	57	SVS	57	BOS-BOS	AM	Water, commissary, toilet/trash dumping, Late commissary loading	
2159	WAS	63	PTI	34	PTI	26	BAL-XNY	AM	Follow, 171, Control Point, .	
2165	WAS	27	OTH	23	DMW	12	NHV-STM	MN	Waiting for MW clearance Milepost, 51.7, 50.3	
2264	BOS	28	SMW	16	SMW	9	NWK-NYP	AM	Scheduled in track usage program, Other, HUDSON-LACK SINGLE TRACKING	
66	BOS	32	DET	30	DET	30	RTE-BBY	AM	Catenary failure, Control Point, Forest-Tower 1, SINGLE TRK Wires down / out of services tracks 1 AND TRK 2	
85	WAS	20	DSR	19	DSR	19	BRP-STM	MN	Per bulletin Milepost, 51.7, 50.3, 30, 3, Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 2, Milepost, 33.6, 33.1, 30, 2	
93	NFK	60	CTI	34	SVS	32	BOS-BOS	AM	Water, commissary, toilet/trash dumping, Late commissary loading / a/c wires down between tower 1 - Forest	
94	BOS	16	CTI	21	PTI	10	NLC-KIN	AM	Follow, 2160, Milepost w/Letters, NLC, KIN, AM94 crossed over trk 2 - 1 at Groton, waited for AM2160 to clear High St, cross over trk 1 - 2 High St, then followed signals of AM2160 High St - KIN	
95	NFK	75	SVS	40	SVS	27	BOS-BOS	AM	Water, commissary, toilet/trash dumping, Late loading food from commissary	
110	NYP	44	DCS	42	DCS	42	PHL-XHM	AM	PTC system failure (wayside), Control Point, SHORE, Train reversed backwards onto 1 trk a/c 32 sw failure at Shore affecting 2 and 3 trks.	
119	WAS	88	ENG	94	ENG	92	NYP-NYP	AM	HEP, 000, SHOPPED MULTIPLE ENGINES FOR MULTIPLE REASONS SUBBED ENG.646	
125	NPN	30	DSR	30	DSR	21	BRP-STM	MN	Per bulletin Milepost w/Letters, not, STM, 30, 3	
128	NYP	36	DBS	27	DBS	27	TRE-NWK	AM	Debris blocking track (no debris strike), Other, Hunter Int , DUE TO 12SW FAILURE AT HUNTER CAUSED BY METAL DEBRIS IN SWITCH POINT, AM128 WAS REVERSED FOR A SHIFT MOVE TO NO.2 TRACK TO NEWARK.	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/17/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
131	WAS	30	SYS	21	SYS	21	NYP-NYP	AM	Delay in Block, NECESSARY TO RUN AROUND TRAIN A/C OPERATING W/ONLY 1 ENGINE	
138	NYP	77	DCS	97	DCS	72	NFK-X3V	NS	Power switch failure Dispatcher lost communication with the switch. Had us try putting them in hand, then back in motor to restore comms which didn't work. Then we waited for the switch maintainer to get it working again., Control Point, crater	
139	WAS	52	CTI	18	CAR	13	PHL-PHL	AM	Set out defective car, 43361 AX MF, 82652 AX AS, 82652 AX AS, MECHANICAL MET RAIN IN 30TH ST FOR A HOT BUFFER PLATE BETWEEN THE 7TH AND 8TH CAR	
148	SPG	17	SMW	27	SMW	9	BER-BER	AM	Diversion around M/W work, Control Point, BER, AM148 waited for CT4467 to run around O/s trk	
166	BOS	46	SMW	39	SMW	23	NYP-XSH	AM	Scheduled in track usage program, Other, NYP XSH	
169	PHL	18	DMW	13	DMW	13	MET-TRE	AM	Held for or routed around MW work or equipment, Other, MET-XH1, CONGESTION AHEAD DUE TO 4 TRK O/O/S AND NJT TRAINS LOW LEVELING 3/4 TRACK BTWN MENLO AND MIDWAY.	
171	RNK	67	CTI	27	FTI	23	CLP-CVS	NS	Cross over or go around 27A, Control Point, Weyburn	
175	WAS	44	RTE	43	RTE	43	NHV-STM	MN	Line manual or spring switch Control Point, cp 243	
479	NHV	23	TRS	12	TRS	12	SPG-WNL	AM	Near-miss, Milepost w/Letters, SPG, WNL, reports of trespasser on single trk, S/r 20 MPH MP 50 - 49, AM479 rpts the trespassers still on scene at MP 49.6	
494	GFD	60	ENG	34	ENG	34	NHV-NHV	AM	Other electrical failure, 85 DX BD, E/85 that is stuck in a penalty, AM494 dp NHV 32" late due to mechanical issues on E/85	
609	HAR	15	SVS	20	SVS	20	PHL-PAO	AM	Unplanned Wye, a/c no cab car	
645	HAR	14	DBS	11	DBS	11	PAO-EXT	AM	Animal strike, Control Point, FRAZER, DEER STRIKE. TRAIN ON THE MOVE.	
656	NYP	28	SVS	21	SVS	21	PHL-XHM	AM	Unplanned Wye	
19	NOL	60	WTR	118	WTR	55	TCL-MEI	NS	Heat order Milepost w/Letters, TCL station, 292.7 mp	
683	POR	38	PTI	40	PTI	24	SAO-ORB	CS	Meet 686, Control Point, Ocean Park	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
686	BON	38	CON	32	CON	32	POR-POR	CS	Hold for bus with passengers from train Miscommunication with bus driver delayed northbound 3681 bus, resulting in missed Freeport stop. Management sent bus back to Freeport, then back to Brunswick for a delayed 3686 bus departure. Resulting in delayed departure for train 686 out of Portland.
63	TWO	75	CTI	20	CTI	14	CRT-POU	MN	Follow MNRR, 807, Milepost, 39, 72
64	NYP	20	CTI	31	CTI	18	POU-CRT	MN	Follow man, 890, Milepost, 72, 39
68	NYP	78	CUI	53	CUI	53	RSP-RSP	DH	United States
69	MTR	70	CUI	39	CUI	39	XLQ-XLQ	CN	Canada
233	ALB	28	ENG	11	ENG	11	POU-XCP	MN	HEP 708
234	NYP	30	CTI	25	CTI	18	POU-CRT	MN	Follow metro north, 842, Control Point, 61
280	NYP	45	FTI	51	FTI	51	BUF-ROC	CS	Meet Control Point, 406, 157
290	NYP	28	DCS	18	DCS	13	SAR-XSY	DH	Restrictive signal(s) from known wayside signal failure STOP SIGNAL, Control Point, CPC 35
291	BTN	23	DCS	16	ITI	15	NYP-NYP	AM	Service, turn, or wye train, 240, LATE TURN OFF AM240
77	CLT	14	FTI	14	FTI	14	DNC-BNC	NS	Meet Had to hold back at the siding at Mebane to meet Amtrak 74 from Burlington. Due to NS P07 being in the siding at Merrill and Haw River., Control Point, Mebane, NS P07, Local
89	SAV	34	FTI	33	DMW	22	FAY-DIL	CS	Waiting for MW clearance All stop CSX track inspector, Control Point, Hamill
90	NYP	104	FTI	55	PTI	28	RMT-PTB	CS	Meet P089;P079, Control Point, Jarratt
97	MIA	52	WTR	57	SVS	34	NYP-NYP	AM	Water, commissary, toilet/trash dumping, SSYD DELAYED
98	NYP	38	WTR	59	CAR	32	MIA-HOL	FL	Electrical failure 28021, Water pump shorted out in cafe car. Maintenance replaced
55	WAS	67	DSR	22	DSR	6	ESX-WAB	NE	Per bulletin Milepost, 103.51, 103.51, 10, Track, Milepost, 102.01, 102.10, 25, Track, Milepost, 99.68, 99.70, 15, Track
6	CHI	217	SVS	170	SVS	130	HER-GRI	UP	Planned set out / pick out of locomotives, cars or section of train
523	SJC	17	MBO	14	MBO	14	SUI-MTZ	UP	For maritime traffic Control Point, rv035
532	SAC	16	MBO	21	MBO	21	MTZ-SUI	UP	For maritime traffic Control Point, vista

Amtrak Endpoint OTP Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
51	CHI	356	FTI	53	FTI	21	IND-CRF	CS	Follow unknown local, Control Point, clermont
504	PDX	22	DSR	14	FTI	13	EUG-ALY	UP	Follow UP 8163, Siding, Swain, Siding, Shedd, z train
507	EUG	19	DSR	17	PTI	10	PDX-ORC	UP	Meet 508, Siding, Clackamas
517	VAN	18	RTE	10	SVS	9	SEA-SEA	BN	Water, commissary, toilet/trash dumping
518	VAC	68	PTI	37	FTI	27	XF2-X1J	BN	Cross Traffic CN, Bridge, Fraser River Br
58	CHI	615	ENG	391	ENG	391	FTN-CDL	CC	Air / Brake 342
59	NOL	171	FTI	118	PTI	36	MCB-HMD	CC	Meet AMTK58, Control Point, Greenwood Jct.
8	CHI	66	FTI	150	FTI	52	SBY-HAV	BN	Meet bn 7387, bn 8342, Control Point, havre west
822	OKC	26	DSR	28	FTI	22	FTW-GLE	BN	Meet BN Freight, Siding, Ponder, Siding, Metro
350	PNT	27	PTI	40	PTI	24	KAL-XGO	MI	Meet 365, Other, 140
352	PNT	51	DSR	55	DSR	33	XH6-XPI	NS	Per bulletin Milepost, 509.62, 509.62, 25, 1, Milepost, 506.34, 506.34, 25, 1, Milepost, 505.1, 505.0, 25, 3, Milepost, 501.41, 501.41, 50, 2, Milepost, 488, 487, 10, 2
353	CHI	32	FTI	25	FTI	19	XMC-XPI	AM	Meet 30Q, Other, 239
355	CHI	75	FTI	99	FTI	99	XPI-HMI	NS	Follow 23G, Milepost, 482, 501
364	PTH	21	DMW	38	DMW	38	XH6-XPI	NS	Waiting for MW clearance FORM Y., Milepost, 488.0, 484.0
365	CHI	48	DSR	52	DSR	20	LNS-BTL	CC	Per bulletin Milepost, 221.42, 221.42, 30, main, Milepost, 219, 218.5, 30, main, Milepost, 218.64, 215.95, 25, main, Milepost, 215.17, 214.84, 25, 2 and mill w xover and main, Milepost, 214.96, 214.96, 25, 2 and mill w x over, Milepost, 210.40, 210.40, 30, 2, Milepost, 205.99, 205.99, 60, main, Mile
572	SAN	16	DCS	8	DCS	8	X98-OSD	SN	Restrictive signal(s) from unknown cause Red/stop, Control Point, Don
786	SAN	18	PTI	50	PTI	17	SIM-CWT	SC	Meet 127, Siding, Davis
701	SAC	206	TCC	131	TCC	131	BFD-BFD	BN	Air / Brake / Wheel C8309
702	BFD	34	DCS	22	DCS	22	XSK-MOD	BN	Restrictive signal(s) from known wayside signal failure Receive verbal APSS at East Duffy account signal outage related to two-main track cutover. Flag East Duffy to signal 2104-8., Stop, Control Point, East Duffy
703	SAC	60	ITI	60	ITI	60	BFD-BFD	BN	Service, turn, or wye train AMT 712

Amtrak Endpoint OTP Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
704	BFD	37	OTH	42	OTH	39	XSK-MOD	BN	Lost time - N.A.R. Stopped at WE DUFFY
710	BFD	109	FTI	90	FTI	72	SKN-MOD	BN	Meet BNSF 3862, BNSF 3272, Control Point, W. Duffy
711	OKJ	Trn Cancelled	DCS	67	DCS	61	MOD-SKN	BN	Restrictive signal(s) from unknown cause Restricting, Control Point, Escalon, Control Point, mariposa
712	BFD	112	FTI	91	FTI	40	SKN-MOD	BN	Meet 1095, Control Point, E Duffy
713	OKJ	Trn Cancelled	DCS	75	DCS	75	MOD-SKN	BN	Restrictive signal(s) from known wayside signal failure Held at riverbank for several trains to clear though affected area including AMT 712/701 and BNSF 3852 then flagged Escalon to West Duffy, Dark, Control Point, escalon
714	BFD	94	FTI	57	PTI	15	SKN-MOD	BN	Meet AMTK 701, Control Point, Hanshaw
715	OKJ	125	DCS	37	RTE	34	MCD-MCD	BN	Dispatcher hold Hold for 712, Other, Merced station
716	BFD	109	DCS	68	DCS	58	SKN-MOD	BN	Couldn't get a signal was stopped at w. Duffy Siding, w. duffy
717	OKJ	51	DCS	43	DCS	31	MOD-SKN	BN	Flagging block Control Point, escalon, Control Point, east duffy
719	OKJ	128	ITI	78	ITI	78	BFD-BFD	BN	Service, turn, or wye train 710, Late inbound equipment did not arrive u til 428 the equipment was serviced before 719 able to depart
4	CHI	102	FTI	126	WTR	45	LMR-GCK	BN	High winds Winds estimated at 55mph, reduce speed through area to 40mph, Milepost, 483, 417
1	LAX	73	FTI	207	FTI	80	XZS-YUM	UP	Follow 6558 WEST SET OUT BAD ORDER MOTOR AT STOVAL, AND FOLLOWED THEM AFTERWORD TO WELLTON MILEPOST 771, UP 6558 WEST, Milepost, 807.0, 771.0
306	CHI	47	FTI	45	FTI	34	XUD-SMT	CC	Cross Traffic NA, Other, CANAL
307	STL	61	FTI	66	FTI	66	CRV-ALN	UP	Meet UP6497, Milepost, 243, 243
390	CHI	270	ENG	254	ENG	212	CDL-CDL	CC	Pick up rescue locomotive due to mechanical failure AMTK 342, ID4605
391	CDL	34	SYS	16	SYS	16	CHI-CHI	AM	Crew rest
311	KCY	39	DCS	32	DCS	30	KWD-WAH	UP	Restrictive signal(s) from unknown cause Received authorization to pass stop signal @ Keefer Creek., Stop, Milepost w/Letters, Keefer Creek, Dozier

Amtrak Endpoint OTP Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
316	STL	57	FTI	68	FTI	44	SED-JEF	UP	Meet UP 8296, Siding, Centertown
318	CHI	99	SYS	57	SYS	48	KCY-KCY	KC	Other late crew Not called by CMS until past 830AM.
319	KCY	59	DCS	43	DCS	43	KWD-WAH	UP	Restrictive signal(s) from unknown cause Talked by signal, ran on restricted proceeds until dozier, Stop, Control Point, keefer creek- dozier
1333	MSP	118	ENG	129	ENG	65	LSE-WIN	CP	Other electrical failure First we got a alertor penalty. Then we got a hot bearing alarm Then Eng 44 would not set its brakes., 517

Amtrak Initial Terminal Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/17/2026

Terminal	Train	Date	Late	Delay	Cause
BON	687	08/17	5	5	Service, turn, or wye train 686, Late arrival. Aquire bulletins, job Briefing, board, depart.
BOS	85	08/17	13	5	Water, commissary, toilet/trash dumping, Late from the yard /
BOS	85	08/17	13	8	Blocked from station track, mbta, 1522, Milepost, BOS, BOS, Keolis double draft/ blocking terminal
BOS	93	08/17	32	32	Water, commissary, toilet/trash dumping, Late commissary loading / a/c wires down between tower 1 - Forest
BOS	95	08/17	27	27	Water, commissary, toilet/trash dumping, Late loading food from commissary
BOS	2151	08/17	9	9	Water, commissary, toilet/trash dumping, Commissary late loading
BOS	2155	08/17	57	57	Water, commissary, toilet/trash dumping, Late commissary loading
BOS	2159	08/17	19	19	Water, commissary, toilet/trash dumping, Late commissary loading
BOS	2165	08/17	7	7	Water, commissary, toilet/trash dumping, commissary loading and missing menu for first class per cndr
BRK	682	08/17	1		
HAR	648	08/17	1	1	Passenger and/or baggage
NHV	474	08/17	8	4	Follow, CDOT, 1634, Milepost w/Letters, NHV, STS, AM474 followed signals of CD1634
NHV	474	08/17	8	4	Planned set out / pick out of locomotives, cars or section of train, late release from the yard NHV
NHV	478	08/17	4	4	Service, turn, or wye train, 479
NHV	494	08/17	34	34	Other electrical failure, 85 DX BD, E/85 that is stuck in a penalty, AM494 dp NHV 32" late due to mechanical issues on E/85
NYP	19	08/17	7	7	Meet, TEST TRAIN, Other, NYP, HELD AT "F" A/C TEST TRAIN IN LINE 2
NYP	63	08/17	13	13	Restrictive signal(s) from unknown cause, N/A, Other, NYP, LATE ARRIVAL A/C PROBLEM WITH 708 SIGNAL AT "F"
NYP	97	08/17	3	3	Passenger and/or baggage, LOADING
NYP	119	08/17	92	92	HEP, 000, SHOPPED MULTIPLE ENGINES FOR MULTIPLE REASONS SUBBED ENG.646
NYP	131	08/17	21	21	Delay in Block, NECESSARY TO RUN AROUND TRAIN A/C OPERATING W/ONLY 1 ENGINE
NYP	183	08/17	12	12	Restrictive signal(s) from unknown cause, N/A, Other, NYP, LATE ARRIVAL A/C PROBLEM WITH 708 SIGNAL AT "F"
NYP	185	08/17	5	5	Service, turn, or wye train, 110, LATE TURN OFF AM110
NYP	245	08/17	34	34	Service, turn, or wye train, 68
NYP	281	08/17	5	5	Service, turn, or wye train, 234, LATE TURN OFF AM234

Amtrak Initial Terminal Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/17/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	291	08/17	15	15	Service, turn, or wye train, 240, LATE TURN OFF AM240
PHL	110	08/17	2	2	High passenger count
PHL	605	08/17	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
POR	684	08/17	11	11	Waiting for bus from Brunswick and Freeport due to track work
POR	686	08/17	32	32	Hold for bus with passengers from train Miscommunication with bus driver delayed northbound 3681 bus, resulting in missed Freeport stop. Management sent bus back to Freeport, then back to Brunswick for a delayed 3686 bus departure. Resulting in delayed departure for train 686 out of Portland.
WAS	130	08/17	25	25	Other electrical failure, 609 EX ES, LATE DUE TO LATE MTR'S FROM THE PIT
WAS	172	08/17	2	2	Delay in Block, D HANDLE PULLED DOWN AT DP TIME ON 82604 A END
WAS	196	08/17	4	4	Delay in Block, STUDENT ENGR LEFT HAND BRAKE ON
WAS	2118	08/17	16	16	Service, turn, or wye train, 2155, 2155 WAS 1'15" LATE SO WE HADE SWITCH CONSIST WITH 2115 FOR 2118
WAS	2120	08/17	54	54	Service, turn, or wye train, 2159, 2159 arrived was 507p 1'04" late
WAS	2124	08/17	5	5	Service, turn, or wye train, 2119, LATE TURN TRAIN 2119
CDL	390	08/17	212	212	Pick up rescue locomotive due to mechanical failure AMTK 342, ID4605
CHI	41	08/17	15	15	Routine inspections Servicing by mechanical in the yard per glass house.. late release of equipment @ 545 P .. train stopped on platform @ 614 P .., Other, Chi union station
CHI	59	08/17	172	172	Service, turn, or wye train 22, Late turn/ Wye of late inbound train 22 caused to swap out car for delay.
CHI	352	08/17	17	17	Door ID4314, A end door wheelchair side problem
CHI	391	08/17	16	16	Crew rest
KCY	318	08/17	48	48	Other late crew Not called by CMS until past 830AM.
ARN	529	08/17	5	5	Follow Red signal , caused departure delay. Waited on freight to clear OS, Control Point, rv124, union pacific
BFD	701	08/17	131	131	Air / Brake / Wheel C8309
BFD	703	08/17	60	60	Service, turn, or wye train AMT 712
BFD	713	08/17	23	23	Wait for station track 701, Other, Bakersfield
BFD	717	08/17	1	1	Service, turn, or wye train 702
BFD	719	08/17	78	78	Service, turn, or wye train 710, Late inbound equipment did not arrive u til 428 the equipment was serviced before 719 able to depart
LAX	572	08/17	1		
OKJ	526	08/17	4	4	Meet 11, Control Point, North Jack London

Amtrak Initial Terminal Details

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/17/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	716	08/17	24	24	Door C8312, Had door & throttle issues in the yard and also tasie mechanical had to replace a window
PDX	11	08/17	64	20	Hold for thruway bus Bus SEA to PDX due to service disruption
PDX	11	08/17	64	30	Fuel Other, PDX station
PDX	11	08/17	64	14	Cross over or go around AMTK 14, Control Point, CP0001
PDX	503	08/17	10		
PDX	507	08/17	5	5	Hold for thruway bus
SAC	547	08/17	1		
SJC	524	08/17	3	3	PTC - On Board Cab Signal or PTC Failure C6961, Clear in the field Red fence on PTC
VAN	506	08/17	9	7	Hold for bus with passengers from train

Eastern Region

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.2	94.8	342	1
CDOT	95.0	75.0	87.7	92.4	20	5
MARC	95.0	84.5	83.8	90.2	58	9
SEPTA	95.0	98.6	95.0	91.5	208	3
NJT-NED	95.0	95.5	91.7	88.6	364	16
NJT-SED	95.0	95.8	99.1	97.2	24	1

Operating Highlights

Train 175(17) - East of Stamford, CT - Routing

17AUG26: Train 175(16) was delayed on the Metro North New Haven Line at CP 243/MP 43.4 due to having to manually line a switch for the route.

Train	Delay	Comment
175 (17)	43"	

Train 66(17) - Washington, DC - Hold for Connection

17AUG26: Train 66(17) was delayed at Washington Union Terminal due to being held for 71 connections on late operating Train 40(16).

Train	Delay	Comment
66 (17)	1'03"	

Train 178(17) - East of New Haven, CT - Commuter Train Interference

17AUG26: Train 178(17) was delayed on the New Haven to Boston Line at MP 82.4 due to accepting a passenger transfer from CDOT train 1652, which became disabled after its compressor failed.

Train	Delay	Comment
178 (17)	48"	

Train 494(17) - New Haven, CT - Engine Failure

17AUG26: Train 494(17) was delayed at its initial terminal at New Haven due to a mechanical issue, creating an unresolvable penalty. After some troubleshooting, a loose alerter was discovered on the E/85. Once corrected, the train was able to depart.

Train	Delay	Comment
494 (17)	34"	

New York to Philadelphia main line - Bridge Strike

17AUG26: At 304P-ET A 26-FO-0067E 50000008692 UNCLASSIFIED Hazlewood Rd., MP 19.72, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At approximately 430P, the bridge was inspected and released for normal service.

Train	Delay	Comment
93(17)	12"	

Train 98(17) North of Jacksonville, FL - Freight Train Interference

17AUG26: Train 98(17) with E/39, E/46 and 9 cars was delayed on the CSX Jacksonville Terminal due to holding for cross traffic of CSX Q711.

Train	Delay	Comment
98(17)	35"	

Train 178(17) Washington, DC - Servicing

17AUG26: Train 178(17) was delayed departing Washington due to holding for engine.

Train	Delay	Comment
178(17)	32"	

Train 68(17) Rouses Point, NY - Customs and Immigration

17AUG26: Train 68(17) was delayed on the CN Rouse Point subdivision at US Customs.

Train	Delay	Comment
68(17)	53"	
69(17)	39"	

Train 280(17) North of Buffalo, NY - Freight Train Interference

17AUG26: Train 280(17) with E/117 and 5 cars was delayed on the CSX Buffalo Terminal at MP 406.8 due to meeting CSX 157.

Train	Delay	Comment
280(17)	51"	

Train 138(17) North of Norfolk, VA -Switch Failure /Signal

17AUG26: Train 138(17) with E/130 and 8 cars was delayed on the NS Norfolk subdivision at MP 3.1 due to switch failure NS maintainer was on scene making repairs.

Train	Delay	Comment
138(17)	1'06"	

Train 119(17) New York, NY - Engine Failure

17AUG26: Train 119(17) with E/609 and 8 cars was delayed departing New York due to paperwork issues. It was necessary to swap the engine out with E/646.

Train	Delay	Comment
119(17)	1'32"	

CSX Heat Orders - Weather

17AUG26: Multiple trains were affected by CSX heat orders that were in place from 1300-1900 on the following subdivisions Peninsula, Richmond Terminal, North End, Auburndale, Carters, Lakeland, Nahunta, Sanford, Savannah, South End, Tampa Terminal and NO&M.

Train	Delay	Comment
53(17)	06"	
98(17)	46"	
52(17)	17"	
89(17)	34"	
79(17)	37"	
40(17)	46"	
95(17)	02"	
90(17)	34"	
186(17)	18"	
138(17)	05"	
80(17)	03"	
40(16)	15"	
41(16)	23"	
97(16)	31"	

Train 110(17) North of Philadelphia, PA - Switch Failure/Signal

17AUG26: Train 110(17) with E/657, E/660 and 8 cars was delayed on the New York to Philadelphia main line due to the 32SW failure on track 1. It was necessary for the train to make a reverse move from MP 82.1/Shore to MP 84.5/Clearfield for a route around.

Train	Delay	Comment
110(17)	42"	

Boston, MA - Commissary /Servicing

17AUG26: Due to a Commissary accident where a skid load tipped over making it necessary to return to the yard to get new supplies. Making commissary run late on servicing the trains which caused delay to several trains.

Next Gen Train 2159(17) was late arriving Washington at 507P-ET 1 hour and 3 minutes late which caused train 2120(17) to be delayed departing Washington.

Train	Delay	Comment
2151(17)	09"	
95(17)	27"	
2155(17)	57"	
2159(17)	19"	
93(17)	32"	
2165(17)	07"	
2120(17)	54"	Turn off 2159(17)

Train 40(16) North of Camden, SC - Struck Trees/Debris

17AUG26: At 819A-ET, Train 40(16) with 13 cars reported that they struck a tree at MP S284.3 on the CSX Hamlet S subdivision. They said there was plow damage and need assistance trimming the plow. Amtrak Assistant Superintendent of Operation was notified and Amtrak Road Foreman was enroute. CSX was able to provide a work truck from Hamlet to assist. There was no injuries to customers or crew. As of 921A-ET CSX mechanical arrived to assist and another CSX Mechanical was enroute with a torch. As of 1100A-ET, Amtrak Road Foreman arrived on scene with the recrew. As of 1115A-ET CSX Mechanical arrived with the torch to finish making repairs. There was still damage to the main res hose and temporary repairs were made. It was necessary to swap engines in Washington.

Service Recovery was initiated for coach passengers with beef stew over rice and bottled water and First class passengers will be served dinner as usual in the dining car.

Train 40(16) was further delayed on the NS Piedmont at Raleigh station due to having PTC issues. Amtrak Road Foreman was on scene assisting the crew with CNOC Mechanical once they corrected the issue they were able to proceed north.

WBS#: B.TR.100150.7046

Train	Delay	Comment
40(16)	3'50"	
40(16)	36"	RGH
40(16)	30"	WAS

New Haven to Boston Main Line- Back Bay Boston, MA - Catenary or Wayside Failure

17AUG26: At 530A-ET, Keolis 802 reported wire down at MP 227.6/Back Bay on the equipment and smoke coming from the train. Power director and Amtrak Police were notified. ET was enroute to Back Bay. Keolis 602 was inspecting overhead catenary at 30MPH on track 3 between Plains and Cove. Train 2151(17) was delayed at Route 128 and operated via the Dorchester branch. At 610A-ET, ET Foreman arrived on scene and was working on grounding power to safely deenergize the wires. ET reported wire down on the Fireman's side of the 2nd coach from the lead on Keolis 802. At 632A-ET, ET reported that wire is down across track 1 and 2 and grounded, deenergized and safe. Fire department is assisting on deboarding 802. As of 635A-ET Track 3 was ok for normal service. At 747A-ET, The bucket truck arrived on scene at Back Bay on track 1 to repair overhead catenary. As of 1015A-ET, ET equipment was clear of the Back Bay station area. Track 2 was good for Diesel only and track 1 was okayed for Electric and Diesel. Repairs would be finished later this evening.

Train	Delay	Comment
2190(17)	19"	
171(17)	02"	
2159(17)	04"	
2155(17)	04"	
2151(17)	16"	
95(17)	04"	
66(16)	30"	

Metro North Track Outage - Croton, NY - M of W Work

15AUG26: Due to Metro North track outage, Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

26-FOI-00671

00000008692

UNCLASSIFIED

9/2/2026

Train	Delay	Comment
235 (15)	43"	
236 (15)	10"	
280 (15)	16"	
230 (15)	02"	
233 (15)	50"	
290 (15)	24"	
238 (15)	12"	
239 (15)	29"	
49 (15)	43"	
48 (14)	1'00"	
1233 (16)	1'08"	
240 (16)	31"	
291 (16)	25"	late turn off 240 (16)
1246 (16)	1'11"	LATE TURN OFF 1233 (16)

Downeaster Service - CSX Trackwork - M of W Work - 8/17 - 8/20

28JUL26: CSX Portland subdivision has a system tie gang working between Boston North station and Brunswick, ME MP BRU 5.0 to MP BRU 0.5 from Monday, August 17, 2026 to Thursday, August 20, 2026 from 7A-3P. The following service adjustments have been made:

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound:

- Train 681 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.
- Train 683 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 684 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 686 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 688 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3683 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, and 3688 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100151.0835

Train	Delay	Comment
686 (17)	32"	holding for buses por

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No Data

Eastern Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Western Region

Operating Highlights

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train 11(17) Klamath Falls, OR - Police Related

18AUG26: Train 11(17), carrying 177 customers onboard, was delayed at Klamath Falls, OR, while awaiting a response from the Klamath County Sheriff's Office to remove an unruly individual from the train. Once law enforcement personnel arrived and addressed the situation, Train 11(17) resumed its scheduled operation.

Train	Delay	Comment
11(17)	1'13"	

Train 719(17) Richmond, CA - Fire Department Activity

18AUG26: Train 719(17), carrying 28 customers onboard, was delayed at Richmond, CA, Station while local fire department personnel maintained a hold on train movements due to fire hoses being placed across the tracks. Once the scene was cleared and the restriction was removed, Train 719(17) resumed its scheduled operation.

Train	Delay	Comment
719(17)	32"	

Train 5(17) West of Lincoln, NE - Weather

18AUG26: Train 5(17) with 172 customers was delayed on the BNSF Hastings subdivision due to 80mph high wind warnings in effect between MP 60.4 and MP 153.0.

Train	Delay	Comment
5(17)	43"	

Train 4(17) West of Needles, CA - Freight Train Interference

18AUG26: Train 4(17), transporting 159 customers, was delayed west of Needles, CA, on the BNSF Needles Subdivision due to freight traffic interference. The train followed freight traffic between MP 649 and MP 581, resulting in reduced operating speeds and delays through the affected territory.

Train	Delay	Comment
4(17)	39"	

Train 306(17) South of Summit, IL - Freight Train Interference

17AUG26: Train 306(17) with 107 customers was delayed on the CN Joliet subdivision one mile south of Summit at Canal/MP 13.1 due to meeting unknown freight.

Train	Delay	Comment
306(17)	34"	

Train 7/27(17) West of Red Wing, MN - Freight Train Interference

18AUG26: Train 7/27(17) was delayed on the CPKC River subdivision starting 10 miles west of Red Wing due to meeting and following CP 149 between MP 380.0 and MP 391.0.

Train	Delay	Comment
-------	-------	---------

Train 355(17) West of Michigan City, IN - Freight Train Interference

17AUG26: Train 355(17) with 208 customers was delayed on the NS Chicago district 16 miles west of Michigan City holding behind 23G-16 and single tracking due to 257-16 with the crew on hours of service at CP 501. Train 355(17) followed 23G-16 to CP 501 before operating in the clear.

Train	Delay	Comment
355(17)	1'39"	

Train 3(16) Winslow, AZ - Freight Train Interference

17AUG26: Train 3(16), carrying 150 customers onboard, was delayed operating between Winslow, AZ (MP 285.5) and Flagstaff, AZ (MP 344.3) on the BNSF Seligman Subdivision due to freight traffic interference. The train followed freight traffic throughout the territory, resulting in reduced operating speeds and delays as it proceeded between the two locations.

Train	Delay	Comment
3(16)	58"	

Train 1(17) Houston, TX - Freight Train Interference

17AUG26: Train 1(17) with 66 customers was delayed on the UPRR Glidden subdivision 49 miles west of Houston at Bernard/MP 49.3 due to meeting MSAEW-17.

Train	Delay	Comment
1(17)	33"	

Train 58(17) Marks, MS - System

17AUG26: Train 58(17) with 146 customers arrived at Marks at 748PM-CT on the CN Yazoo subdivision and was delayed due to holding for a CN pilot to arrive and work with the outbound Amtrak relief engineer to continue to Memphis. The inbound Amtrak engineer's hours of service expired at 825PM-CT. The pilot was on duty in Memphis at 630PM-CT. CN stated that train 58(17) was held at Marks for the relief engineer and pilot as opposed to advancing them closer to Memphis due to downed trees reported 32 miles north of Marks at MP 35.0. The trees were removed from the tracks and once the pilot arrived to Marks at 910PM-CT, 58(17) was able to depart at 919PM-CT, 2 hours, and 44 minutes late.

Train	Delay	Comment
58(17)	1'29"	

Train 316(17) West of Jefferson City, MO - Freight Train Interference

17AUG26: Train 316(17) with 44 customers was delayed 15 miles west of Jefferson City on the UPRR Sedalia subdivision at Centertown/MP 140.2 due to meeting MASNP-17.

Train	Delay	Comment
316(17)	44"	

Train 354(17) East of Hammond-Whiting, IN - Freight Train Interference

17AUG26: Train 354(17) with 253 customers was delayed on the NS Chicago district starting six miles east of Hammond-Whiting due to following 10R-17 between CP 501 and CP 482.

Train 8/28(16) East of Wolf Point, MT - Freight Train Interference

17AUG26: Train 8/28 (26-FOI-00671 00000008592 UNCLASSIFIED 9/2/2026) is delayed east of Wolf Point, MT, on the BNSF Glasgow Subdivision due to freight traffic interference. The train met BNSF 7633 at Macon (MP 221.0), BNSF 8217 at Blair (MP 180.1), and BNSF 7735 at Snowden (MP 148.0), resulting in delays as it progressed through the territory. Once the freight movements were cleared, the train continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(16)	32"	

Train 59(17) Chicago, IL - Initial Terminal Delay

17AUG26: Train 59(17) with E/319, seven cars, and 195 customers was delayed departing Chicago due to a late release account C/32082 had ordered for battery issues and replaced with C/32069. Additionally, it was necessary to repair the knuckle between C/33038-C/31047. Once the train was released and set in the station, the customers were welcomed aboard, and 59(17) departed Chicago at 857PM-CT, 2 hours, and 52 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(17)	2'52"	

Train 364(17) East of Hammond-Whiting, IN - M of W Work

17AUG26: Train 364(17) with 272 customers was delayed on the NS Chicago district 17 miles east of Hammond-Whiting at CP 490 due to holding for MOW clearance between MP 488.0 and MP 484.0 with a form Y.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(17)	38"	

Train 1333(17) La Crosse, WI - Engine Failure

17AUG26: Train 1333(17) with E/517, three cars, E/44, and 188 customers was delayed departing La Crosse on the CPKC Tomah subdivision due to E/517 with a sparking 480 cable that started to flame and was ousted with a fire extinguisher. The crew short looped, set up E/517 as a cab car, set the HEP to trail E/44, and departed La Crosse at 505PM-CT, 54 minutes late. The crew stopped again on the CPKC River subdivision three miles east of Winona at MP 305.1 due to E/517 with an alerter penalty, hot bearing alarm, and the brakes unable to set on trail E/44. The crew worked with CNOC mechanical and a technician to reset the PTC breaker, clear the penalty, and establish air. The crew pulled the MU cable between E/517 and C/34078 and continued to Winona.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(17)	1'05"	E/WIN
1333(17)	15"	LSE

Train 4(15) East of Naperville, IL - Commuter Train Interference

17AUG26: Train 4(15) with 193 customers was delayed on the BNSF Chicago subdivision starting eight miles east of Naperville between Fairview Ave/MP 20.6 and Chicago due to following Metra.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(15)	37"	

Train 319(17) West of Kirkwood, MO - Signal

17AUG26: Train 319(17) with 220 customers was delayed on the UPRR Jefferson City subdivision starting seven miles west of Kirkwood between Keefer Creek/MP 20.5 and Dozier/MP 32.4 due to signal issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(17)	43"	

Train 318(17) East of Washington, MO - Freight Train Interference

17AUG26: Train 318(17) was delayed east of Washington, MO/MP51.75, on the UPRR Jefferson City Subdivision, following UP 8112 between MP32 and MP21.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
318(17)	30"	

Train 59(16) South of McComb, MS - Passenger Train Interference

17AUG26: Train 59(16) was delayed at MP811, 5 miles south of McComb, MS, on the CN McComb Subdivision, meeting Train 58(17).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(16)	36"	

Train 352(17) West of Hammond-Whiting, IN - Temporary Speed Restrictions

17AUG26: Train 352(17) with 273 customers was delayed on the NS Chicago district starting three miles west of Hammond-Whiting due to designated speed restrictions between MP 509.62 and MP 487.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(17)	33"	

Train 4(15) West of Galesburg, IL - M of W Work

17AUG26: Train 4(15) was delayed beginning 7 miles west of Galesburg, IL, on the BNSF Ottumwa Subdivision, due to MW working on the Cameron connection at MP170 and necessary to detour around work location between CP1705 to MP173 and then to Galesburg.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(15)	32"	

Train 711(17) West of Modesto, CA - M of W Work, Signal Issues

17AUG26: Train 711(17) was delayed approximately 8 miles west of Modesto, CA, on the BNSF Stockton Subdivision due to signal system issues associated with an overstayed maintenance window between West End Duffy (MP 1110.6) and Escalon (MP 1101.1). The maintenance window, which began at 12:01 AM CT, was scheduled to conclude at 7:00 AM CT; however, issues with a signal bungalow prevented the planned release and delayed train movements through the affected territory. Signal testing and troubleshooting efforts continued throughout the day as BNSF personnel worked to restore normal operations. Multiple projected release times were provided, but the signal issues persisted, resulting in continued delays to rail operations through the corridor. BNSF ultimately completed testing on Main Track 1 at approximately 9:00 PM CT, after which the track was released following Maintenance of Way inspections. Testing efforts then shifted to Main Track 2. The extended outage affected all Gold Runner services operating through the territory, resulting in delays to multiple trains until signal testing was completed and track capacity was restored.

Train	Delay	Comment
711(17)	1'01"	
711(17)	Term EMY	Late operation
710(17)	1'12"	Meet Frt
710(17)	25"	
713(17)	1'15"	Term EMY
701(17)	1'17"	
714(17)	1'15"	Signals & Meets
712(17)	1'49"	Signals & Meets
715(17)	54"	congestion meets
719(17)	1'18"	BFD - late turn from 710(17)
716(17)	1'09"	
717(17)	1'01"	
703(17)	1'00"	BFD - late turn from 712(17)
704(17)	39"	
718(17)	24"	
703(17)	26"	
702(17)	37"	

Train 8/28(16) East of Shelby, MT - Freight Train Interference

17AUG26: Train 8/28(16) was delayed east of Shelby, MT, while operating on the BNSF Hi Line and Milk River Subdivisions due to freight traffic interference. The train met BNSF 5051 at Devon (MP 1048) on the Hi Line Subdivision before continuing eastward. On the Milk River Subdivision, the train was required to follow BNSF 5532 between Havre West (MP 431.8) and Havre Station (MP 430.3). Additional delays were incurred east of Havre while meeting BNSF 6596 at Havre Center (MP 429.3), after which the train continued following BNSF 5532 to Lohman (MP 418.7). Following these freight train movements, Train 8/28(16) continued its trip to Malta, MT.

Train	Delay	Comment
8/28(16)	20"	SBY-HAV
8/28(16)	35"	HAV-MAL

Train 8/28(16) East Glacier Park, MT - Freight Train Interference

17AUG26: Train 8/28(16) was delayed east of East Glacier Park, MT, while holding at Browning Siding (MP 1122.1) on the BNSF Hi Line Subdivision to meet BNSF 6788.

Train	Delay	Comment
8/28(16)	40"	

Train 318(17) Late Departure Kansas City, MO - Crew Issue

17AUG26: Train 318(17) was delayed departing Kansas City, MO, due to CMS miscommunication resulting in the conductor job not filled and it was necessary for CMS to call an ASAP conductor to work the vacancy.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
318(17)	48"	

Train 311(17) West of Kirkwood, MO - Signal Issues

17AUG26: Train 311(17) was delayed at Keefer Creek/MP20.7, 7 miles west of Kirkwood, MO, on the UPRR Jefferson City Subdivision, due to signal issues. Train 311(17) received permission by signal at MP20.7 and operated on restrictive signals to Dozier/MP32.4.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
311(17)	30"	

Train 701(17) Bakersfield, CA - Third Party Contractor Engine Failure

17AUG26: Train 701(17), operating with locomotive C2108, was delayed departing Bakersfield, CA, on the BNSF Mojave Subdivision due to mechanical issues. Mechanical forces reported air brake problems on C8309 at departure time. Drummac and TASI mechanical personnel troubleshot the issue but were unable to resolve it. As a result, Train 701(17) was returned to its original equipment and ultimately departed operating with locomotives C2001/C2009.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
701(17)	2'11"	

Train 5(16) East of McCook, NE - Passenger Train Interference

17AUG26: Train 5(16) was delayed at Indianola/MP276.6, 11 miles east of McCook, NE, on the BNSF Hastings Subdivision, meeting Train 6(15).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(16)	39"	

Train 59(16) Memphis, TN - Freight Train Interference

17AUG26: Train 59(16) was delayed at Memphis, TN/MP391.8, on the CN Memphis Subdivision, holding for freight cross-traffic to clear CN Junction ahead at MP392.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(16)	30"	

Train 58(16) South of Carbondale, IL - Engine Failure

17AUG26: Train 58(16) E/342 & 7 cars, with 137 customers, was delayed at MP345.6, 37 miles south of Carbondale, IL, on the CN Centralia Subdivision, due to E/342 air compressor overheating alarms and leaking oil in the back engine room. Train 58(16) was able to maintain HEP. The crew contacted mechanical to troubleshoot however was unable to resolve the issue. Mechanical from St. Louis, MO, responded to assist. CN estimated first available freight engine would not arrive on scene until after 900AM-CT. Due to the ongoing engine issues and no readily available freight engine, an extra crew was called at Carbondale, IL/MP308.3 to utilize equipment scheduled for Train 390(17) to rescue Train 58(16). 710AM-CT, Rescue equipment, E/IDTX4605 & 7 cars, departed Carbondale, and shoved south to MP345.6 where it was coupled ahead of Train 58(16). The equipment remained combined to Chicago, IL, operating as a Train 390(17)/58(16) combo between Carbondale and Chicago. Two shadow busses were secured and followed the combo train out of Carbondale. As service recovery on Train 58(16), snack packs, bottled water, coffee and tea were available to all coach passengers. Breakfast was extended in the dining car for all first-class passengers. Train 390(17) passengers were notified of the delay departing Carbondale due to equipment utilized to rescue Train 58(16).

Due to the late operation of Train 390(17) and anticipated late equipment turn at Chicago, IL, for Train 393(17), Illini Service was adjusted as follows:

- Train 393(17) was cancelled, with on time alternate transportation. Four busses were secured as alternate transportation between Chicago and Carbondale. Once serviced equipment operated deadhead Chicago to Carbondale to be in position for AM service on 18AUG.

WBS#: B.TR.100150.7045

Train	Delay	Comment
393(17)	Cancelled	
58(16)	6'31"	
390(17)	3'32"	CDL

Train 4(16) West of Winslow, AZ - Freight Train Interference

17AUG26: Train 4(16), carrying 144 customers, was delayed approximately 6 miles west of Winslow, AZ, on the Seligman Subdivision. The delay occurred after BNSF 7616 went into emergency at MP 288.0, just east of Winslow, AZ, and became disabled on Main Track 1. The disabled freight train caused congestion in the area, resulting in Train 4(16) being delayed while moving through the freight traffic backup.

Train	Delay	Comment
4(16)	46"	

Train 2/422(16) West of Yuma, AZ - Freight Train Interference

17AUG26: Train 2/422(16), carrying 193 customers, was delayed on the UPRR Yuma Subdivision. The train was held west of Yuma, AZ, at MP 723.1 for a westbound freight train. Afterward, it continued to hold at Yuma awaiting a route due to heavy westbound freight traffic.

Train	Delay	Comment
2/422(16)	18"	XIC-YUM
2/422(16)	25"	Holding at YUM

Train 1(15)/421(14) East of Yuma, AZ - Freight Train Interference

17AUG26: Train 1(15)/421(14) was delayed east of Yuma, AZ, near Stoval (MP 802) at MP 804.0 on the Union Pacific Gila Subdivision due to freight traffic interference. The train was held while UP freight train ZG2LC-14 set out locomotive UP 7697 in Stoval Siding due to a locked axle condition. While the setout was being completed, Train 1(15)/421(14) was also delayed behind UP freight train ZAILA-15 with UP 6063. An operating plan was implemented to move ZAILA-15 into Stoval Siding after the first train cleared, allowing Train 1(15)/421(14) to proceed around the train. Train 1(15)/421(14) resumed its trip, although it continued to follow ZG2LC-14 eastward toward Wellton (MP 770.9) where it was able to pass.

Train	Delay	Comment
1(15)/421(14)	1'20"	

Amtrak Crescent Service - Norfolk Southern Heat Orders

15AUG26: Norfolk Southern issued heat orders on the NO&NE Subdivision beginning 45 miles north of Picayune, MS (MP149.0), from MP104 to MP0.5. . The heat orders were in place from 1:00PM-CT to 6:00PM-CT and required operating speeds to be reduced to 40MPH through the affected areas, causing delays to Trains 19(14) and 20(15). Additional heat orders were in effect on the NSRR AGS South Subdivision beginning 2.3 miles north of Meridian, MS (MP295.0), from MP292.7 to MP143.5.

16AUG26: NS heat orders remained in effect between 1:00PM-CT and 6:00PM-CT on the AGS South Subdivision between Birmingham, AL/MP143.5 and Meridian, MS/MP295. Trains 19(15) and 20(16) were delayed operating through the affected areas.

17AUG26: NS heat orders remained in effect on the AGS South Subdivision between Birmingham, AL and Meridian, MS. Trains 19(16) and 20(17) were delayed operating through the affected areas.

Train	Delay	Comment
19(14)	2'30"	
20(15)	1'25"	
19(15)	2'02"	
20(16)	1'35"	
20(17)	1'47"	
19(16)	1'55"	

CN Blanket Heat Orders - City of New Orleans / Illini / Saluki Service

12AUG26: Canadian National issued blanket heat orders for the entire route from Chicago, IL and New Orleans, LA starting at 9:00AM-CT on 12AUG to remain in effect until temperatures decline. Expected to remain through the weekend. During this time, the maximum authorized speed was reduced to 15 MPH below timetable speed throughout most of the territory, with additional 40 MPH speed restrictions in designated areas. On the McComb Subdivision, 40 MPH restrictions were in effect between MP731-MP735 and MP823-MP849. On the Yazoo Subdivision, 40 MPH restrictions were in effect between MP15-MP21, MP70-MP71, MP136-MP137, MP172-MP189, and MP210-MP216. The heat orders caused delays to Amtrak's City of New Orleans, Illini, and Saluki Service.

-Train 58(12) had service recovery enacted, with snack packs, bottled water, coffee, hot tea, and juice provided to all coach customers, while all First Class customers were provided breakfast in the dining car.

-Train 59(12) had service recovery enacted, with snack packs and bottled water provided to all coach customers, while First Class customers received their scheduled meal service in the dining car.

16AUG16: Heat orders remained in effect with ongoing delays to City of New Orleans, Illini and Saluki services through the affected areas.

17AUG16: Heat orders remained in effect on the CN Memphis, Shelby, Yazoo and McComb Subdivisions resulting in continued delays to City of New Orleans service through the affected area.

Train	Delay	Comment
58(12)	2'35"	NOL-CHI
390(13)	37"	
391(13)	46"	
392(13)	53"	CDL-CHI
393(13)	49"	CHI-CDL
59(12)	310"	CHI-NOL
391(14)	1'04"	
390(14)	51"	
58(14)	57"	Crew Rest JAN
392(14)	42"	
393(14)	42"	
59(13)	3'32"	CHI-NOL
390(15)	43"	
391(15)	32"	
58(14)	2'44"	NOL-CHI
392(15)	48"	
58(15)	1'54"	NOL-CHI
59(14)	2'24"	CHI-NOL
58(14)	2'49"	NOL-CHI
390(16)	51"	
391(16)	40"	
59(15)	41"	MEM, hold for CN engineer pilot
59(15)	2'16"	CHI-NOL
392(16)	1'10"	
393(16)	35"	
58(16)	1'06"	NOL-FTN
59(16)	1'27"	CHI-NOL
58(17)	57"	NOL-MEM

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG:

Pere Marquette:

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.

- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids

- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI. 26-FOI-00671 00000008692 "UNCLASSIFIED" 9/2/2026
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13), with 143 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(14), with 162 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(16), with 151 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(17), with 149 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(20), with 90 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(21)m with 155 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(15), with 163 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(15), with 108 impacted customers, is cancelled entirely with 3 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(18), with 31 impacted customers, is cancelled entirely with no alternate transportation provided.
- Train 355(18), with 11 impacted customers, is cancelled entirely with no alternate transportation provided.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL and Quincy, IL.
- Train 382(10) cancelled entirely, with 2 alternate buses secured between Quincy, IL and Chicago IL.
- Train 381(14), with 22 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL
- Train 382(14), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(17), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21), with 15 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21), with 11 impacted customers, is cancelled entirely with 1 alternate bus

secured between Chicago, IL and Carbondale, IL.

- Train 392(12), with 45 impacted customers, is cancelled entirely with 1 alternate buses secured between Carbondale, IL and Chicago, IL.

- Train 391(19), with 55 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Carbondale, IL.

- Train 392(19), with 18 impacted customers, is cancelled entirely with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

BNSF Fallbridge Subdivision - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.

- Train 502(03) canceled, with alternate bus transportation provided.

- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.

- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.

- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.

- Train 506(03) originated Vancouver, WA using the 517(03) equipment.

- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.

- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.

- Train 505(03) canceled, with alternate transportation provided.

- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.

- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.

- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

13AUG26: Due to the structural integrity of the building and the need for demolition, the service adjustments on the Cascades, Coast Starlight, and the Empire Builder were adjusted through Sunday, August 16th. Multiple trains were delayed holding for bus connections.

15AUG26: Initial plan is to start detonation of the water tower on Monday, August 17th with the demolition of the remaining structure on Tuesday, August 18th. As a result, the

-Train 502 (04-19) Cancelled entirely, with alternate transportation via Bus 3502.
 -Train 504 (04-19) Terminated in Portland, OR, with alternate transportation via Bus 3504.
 -Train 518 (04-07) Originated in Seattle, WA with alternate bus transportation.
 -Train 518 (08-19) Originated in Vancouver, WA with alternate bus transportation via Bus 3518.
 -Train 517 (04-19) Terminated in Vancouver, WA, no alternate transportation (04-10); alternate bus transportation via Bus 3517(11-19)
 -Train 506 (04-19) Originated in Vancouver, WA, no alternate Transportation (04-10); alternate bus transportation via Bus 3506(11-19)
 -Train 508 (04-19) Terminated in Portland, OR with alternate transportation via Bus 3508.
 -Train 503 (04-19) Originated in Portland, OR, with alternate transportation via Bus 3503.
 -Train 505 (04-07) Cancelled entirely with alternate bus transportation.
 -Train 505 (08-19) Terminated in Vancouver, WA, no alternate transportation(04-10); alternate bus transportation via Bus 3505(11-19)
 -Train 507 (04-19) Originated in Portland, OR, with alternate transportation via Bus 3507, operating 1 hour earlier at 1:20P-PT.
 -Train 509 (04-19) Cancelled entirely, with alternate transportation via Bus 3509.
 -Train 511 (04-19) Cancelled entirely, no alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

-Train 27 (02-17) Will Terminate at Spokane, WA. Alternate Transportation provided.
 -Train 28 (04-19) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

-Train 14 (04-11) Terminated in Portland, OR, no alternate transportation provided.
 -Train 14 (12-18) Terminated in Portland, OR with alternate transportation secured via Bus 3014.
 -Train 11 (05-12) Originated in Portland, OR, no alternate transportation provided.
 -Train 11 (13-19) Terminated in Portland, OR with alternate transportation secured via Bus 3011.

Bus to operate earlier 8/11-8/16 - Arrow
 Bus 3507 to depart 1 hour earlier at 1:20pm
 Train 505 bus VAN-PDX depart VAN at 12pm
 Train 518 bus PDX-VAN depart PDX at 1:30pm
 Train 517 bus VAN-PDX depart VAN at 330pm
 Train 506 bus PDX-VAN depart PDX at 5:20pm

Due to inability to secure other fueling options, Train 517(11-14) was delayed departing Seattle, WA for fueling the equipment.

WBS#: B.TR.100150.6981

Train	Delay	Comment
-------	-------	---------

507(02)	1'41"	bus VAN-PDX	
506(02)	Canceled		
508(02)	45"	bus PDX-VAN	
509(02)	77"	couple 509-511(02)	
509(02)	75"	detour through UP yard	26-59400671 00000008692 "UNCLASSIFIED" 9/2/2026
511(02)	76"	Detour through UP yard	
500(03)	Canceled		
502(03)	Canceled		
511(03)	Canceled		
505(03)	Canceled		
518(03)	Canceled	between SEA-PDX	
507(03)	Canceled	between SEA-PDX	
508(03)	Term PDX		
504(03)	Term PDX		
509(03)	Canceled		
517(03)	Term VAN		
506(03)	Orig VAN		
503(03)	24"	canceled SEA-PDX	
507(03)	1'10"	waiting for bus at PDX	
14(02)	58"	detour	
11(03)	51"	detour	
14(04)	term PDX		
506(04)	1'03"	wait for inbound bus	
518(04)	1'27"	wait for inbound bus	
507(05)	1'09"	PDX- wait for inbound bus	
507(06)	1'06"	PDX- inbound bus	
503(07)	33"	PDX- inbound bus	
507(07)	1'21"	PDX- inbound bus	
503(08)	22"	PDX- inbound buses	
503(09)	28"	bus connections	
518(09)	27"	bus connections	
518(10)	34"	bus connections	
503(10)	45"	bus connections	
503(12)	28"	PDX- inbound bus connections	
517(12)	47"	Fuel in SEA yard due to no Fueling in VAN	
507(12)	1'15"	Connecting Bus	
517(13)	44"	Fuel in SEA Yard	
517(14)	59"	Fuel in SEA Yard	
503(15)	26"	PDX- inbound bus connections	
11(15)	25"	PDX - inbound bus connections	
11(17)	1'04"	PDX - Bus connect, fueling, meet 14	

UPRR Joliet Sub - Chenoa Diamond Air Hose Separations

11JUL25: The following information is in emergency when crossing over the Chenoa Diamond/MP102 on the UPRR Joliet Subdivision:

-Train 22(10JUL), E/56-7 Cars, experienced an air hose separation between C/31006 and C/34024. Delay - 45"

09AUG25: Train 22(08AUG), E/58, E/514 and 9 cars, experienced an air hose separation at Car 34049. The crew was able to secure and continue. Delay - 45"

14AUG25: Train 305(14) E/4628 and 5 cars, experienced air hose separation and broken glad hand on car 4008. The crew was able to replace the hose and continue. Delay - 25"

02SEP25: Train 300(02) E/4619 and 5 cars, experienced air hose separation between cars 4116 & 4002. The crew was able to replace the hose and continue. Delay - 4"

03SEP25: Train 300(03) E/4619 and 5 cars, experienced air hose separation between cars 4116 & 4002. The crew was able to replace the hose and continue. Delay - 11"

15OCT25: Train 302(15) E/IDTX4617 and 5 cars, experienced air hose separation between the 3rd and 4th cars, C/ID4121 and C/ID4128. The crew was able to replace the hose and continue.
Delay - 10"

12NOV25: Train 302(15), E/IDTX4617 - 5 cars-EIDTX4626, experienced an air hose separation between 3rd and 4th cars, C/ID4008 and C/ID4130. The was able to secure hose and Train 302(15) was able to proceed north.
Delay - 10"

15NOV25: Train 307(15), E/IDTX4617 and 5 cars, experienced an air hose separation between the 2nd and 3rd cars, C/ID4130 and ID4008. The crew was able to replace the hose and continue.
Delay - 10"

12DEC25: At 7:45AM-CT, Train 300(12), E/63-6 Cars, went into emergency after striking unknown debris after crossing over the Chenoa diamond at MP102.3 and coming to a stop at MP94.4. The Chenoa Diamond is located 21.7 miles north of the Bloomington-Normal, IL station on the UPRR Joliet Subdivision. The strike caused the main reservoir hose on the B-End of C/ID4128 to rip off and go missing. There were no injuries reported to the crew or 277 passengers onboard and no damage to the equipment. The main reservoir was cutoff to the car and then the crew completed a brake test. At 8:00AM-CT, Train 300(12) was back on the move north. Delay ~ 20"

06FEB26: Train 306(06) operating with engine 4603, 5 coaches, and 250 passengers, went into emergency 9.6 miles south of Pontiac, IL, on UPRR Joliet subdivision, after an air hose on car 4116 snapped, causing the train to come to a stop. The crew found the broken air hose and replaced it. Once the hose was replaced and the crew performed their brake test, train 306(06) was able to proceed. Delay 43".

15JUN26: Train 302(15), E/IDTX4625 and 6 cars, with 200 customers, was delayed at MP101.9, 23 miles north of Bloomington-Normal, IL, on the UPRR Joliet Subdivision, due to an air hose separation while operating over the Chenoa diamond at MP102. The crew resecured air hose between the first and second cars, C/ID4001 and C/ID4301. There were no other exceptions to equipment reported. Train 302(15) was on the move north after crew secured hose and performed brake test.

16AUG26: Train 319(16), E/IDTX4624 & 7 cars, with 281 customers, went into emergency over the Chenoa diamond/MP102.3, 10 miles south of Pontiac, IL, on the UPRR Joliet Subdivision. Crew inspected consist and found parted air hose between the 6th and 7th cars, C/ID4310 and C/ID4121. There were no other exceptions to equipment reported. Train 319(16) was on the move south after crew secured hose and performed brake test.

Train	Delay	Comment
319(16)	10"	

Maintenance of Way Highlights

BNSF Track Work West of Galesburg, IL - Illinois Zephyr/Carl Sandburg Service

19AUG26: BNSF tie gang will perform work at Saluda/MP168, 6 miles west of Galesburg, IL, on the Brookfield Subdivision, on Wednesday August 19th. To accommodate this infrastructure work, Illinois Zephyr/Carl Sandburg service adjusted as follows:

- Train 383(18) terminates at Galesburg, IL, with Bus 3383 as alternate transportation between Galesburg, IL and Quincy, IL.
- Train 380(19) originates at Galesburg, IL, with Bus 5380 as alternate transportation between Quincy, IL and Galesburg. Bus 5380 will operate 1-hour earlier than train schedule.
- Train 382(19) originates at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy and Galesburg. Bus 3382 will operate 1-hour earlier than train schedule.
- Train 381(19) terminates at Galesburg, IL, with Bus 5381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.7043

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
- Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
- Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
- Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.

*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task 26-FOI-00671 00000008692 UNCLASSIFIED 5/2/2026 C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No Data

Western Region

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00671

00000008692

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
656 (17)	HAR	656(17) will operate with 5 coaches and no cab car. No Wi-Fi services will be available.	passengers notified.	0	623
562 (17)	LAX	No bikes due to cab 9700. Notify passengers.	NONE	0	9700
580 (17)	LAX	No bikes due to cab 9700. Notify passengers.	NONE	0	9700
584 (17)	LAX	Consist short a coach. Unreserved train- no confirmed passenger impact.	NONE	0	
566 (17)	LAX	Consist short a coach. Unreserved train- no confirmed passenger impact.	NONE	0	
562 (18)	LAX	no bikes or wifi	Passnegers notified no bike space no wifi.	1	9700
580 (18)	LAX	no bikes or wifi	Passnegers notified no bike space no wifi.	1	9700
609 (17)	NYP	no wifi	emails ent to have passengers notified.	0	623
573 (17)	SAN	No bikes due to cab 9700. Notify passengers.	NONE	0	9700
591 (17)	SAN	No bikes due to cab 9700. Notify passengers.	NONE	0	9700
579 (17)	SAN	Consist short a coach. Unreserved train- no confirmed passenger impact.	NONE	0	
595 (17)	SAN	Consist short a coach. Unreserved train- no confirmed passenger impact.	NONE	0	
573 (18)	SAN	no bikes or wifi	Passnegers notified no bike space no wifi.	0	9700
591 (18)	SAN	no bikes or wifi	Passnegers notified no bike space no wifi.	1	9700

Reverse Consists

Train Number	Station	Reason
113 (17)	NYP	Consist reversed Business class seat orientation may have changed At Rear
190 (17)	PHL	Consist reversed Business class seat orientation may have changed At Front
2151 (17)	BOS	Acela consist reversed First class at Rear
170 (17)	WAS	Business class change only Business class seating orientation may have changed At Rear
175 (17)	BOS	Business class change only Business class seating orientation may have changed At Rear
113 (17)	NYP	Consist reversed Business class seat orientation may have changed At Rear
84 (17)	WAS	Consist reversed Business class seat orientation may have changed At Front
193 (17)	NYP	Consist reversed Business class seat orientation may have changed At Rear
86 (17)	NPN	Consist reversed Business class seat orientation may have changed At Front
129 (17)	NYP	Consist reversed Business class seat orientation may have changed At Front
136 (17)	WAS	Consist reversed Business class seat orientation may have changed At Front
85 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front
137 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front
184 (17)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (18)	SPG	Consist reversed Business class seat orientation may have changed At Front
94 (18)	NFK	Consist reversed Business class seat orientation may have changed At Front
178 (18)	RNK	Consist reversed Business class seat orientation may have changed At Front
125 (17)	SPG	Consist reversed Business class seat orientation may have changed At Front
86 (18)	NPN	Consist reversed Business class seat orientation may have changed At Front
129 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front
171 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
95 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	26-FOI-00671 00000008692 "UNCLASSIFIED"	Reason 9/2/2026
94 (18)	NFK	Consist reversed	Business class seat orientation may have changed At Front