

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, August 19, 2026

Rules: 1-46



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/18/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	60	81.3%	5,478	887	83.8%	96,422	13,439	86.1%
Central Division	86.0%	57	15	73.7%	1,008	117	88.4%	18,436	1,691	90.8%
East Division	82.0%	176	27	84.7%	2,969	473	84.1%	50,639	7,891	84.4%
West Division	86.0%	87	18	79.3%	1,501	297	80.2%	27,347	3,857	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00671 00000008591 "UNCLASSIFIED" 9/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	90,747	23,271	74%	1,921,828	601,806	69%	32,254,826	8,243,156	74%
Northeast Corridor	81%	39,910	6,184	85%	835,366	228,950	73%	14,136,879	3,484,978	75%
Acela	83%	8,727	548	94%	172,603	41,665	76%	2,833,027	743,216	74%
Northeast Regional	79%	31,183	5,636	82%	662,763	187,285	72%	11,303,852	2,741,762	76%
Richmond / Newport News / Norfolk	77%	9,050	1,470	84%	206,714	77,328	63%	3,506,690	1,038,789	70%
Springfield Shuttles	89%	636	30	95%	11,140	1,737	84%	198,867	31,605	84%
Roanoke	79%	3,319	1,607	52%	64,994	20,398	69%	1,070,278	239,054	78%
On Spine Northeast Regional	80%	18,178	2,529	86%	379,915	87,822	77%	6,528,017	1,432,314	78%
State Supported	80%	39,823	12,087	70%	867,044	244,076	72%	14,176,663	3,050,001	78%
Borealis	80%	545	266	51%	10,874	2,748	75%	180,500	38,380	79%
Capitol Corridor	90%	3,670	866	76%	66,165	11,587	82%	1,181,884	157,336	87%
Carolinian	70%	881	67	92%	20,209	9,144	55%	365,091	144,143	61%
Cascades	75%	1,229	666	46%	30,933	15,786	49%	814,183	230,822	72%
Downeaster	82%	1,245	372	70%	36,599	4,388	88%	496,912	60,343	88%
Empire	78%	5,625	2,362	58%	114,822	40,658	65%	1,758,535	424,117	76%
Adirondack	72%	435	370	15%	8,334	4,787	43%	108,297	35,632	67%
Ethan Allen Express	70%	547	263	52%	10,726	6,854	36%	179,634	67,203	63%
Maple Leaf	70%	849	409	52%	16,473	7,498	54%	216,822	84,341	61%
New York - Albany	85%	2,530	653	74%	51,185	13,562	74%	813,533	139,489	83%
New York - Niagara Falls	75%	1,264	667	47%	25,784	6,171	76%	429,816	91,852	79%
Berkshire Flyer	60%	0	0	-	2,320	1,786	23%	10,433	5,600	46%
Gold Runner	73%	1,985	1,516	24%	44,994	23,619	48%	800,560	294,072	63%
Heartland Flyer	70%	90	47	48%	4,431	3,138	29%	69,114	28,560	59%
Hiawatha	90%	1,691	136	92%	37,101	3,152	92%	558,020	60,849	89%
Illinois	78%	1,891	796	58%	48,233	19,833	59%	794,457	224,388	72%
Carl Sandburg / Illinois Zephyr	85%	372	143	62%	8,103	3,603	56%	132,903	37,761	72%
Illini / Saluki	85%	692	301	57%	14,510	7,154	51%	274,397	69,054	75%
Lincoln Service	70%	827	352	57%	25,620	9,076	65%	387,157	117,573	70%
Keystone	92%	8,256	1,108	87%	141,865	9,281	93%	2,423,984	248,827	90%
Lincoln / Missouri	70%	723	518	28%	15,850	11,193	29%	248,341	129,501	48%
Mardi Gras Service	80%	290	62	79%	5,728	1,189	79%	129,449	28,804	78%
Michigan	70%	1,798	1,346	25%	43,901	21,663	51%	641,326	214,084	67%
Blue Water	70%	558	555	1%	11,008	6,162	44%	150,666	61,990	59%
Pere Marquette	85%	198	198	0%	4,330	791	82%	82,764	15,915	81%
Wolverine	70%	1,042	593	43%	28,563	14,710	48%	407,896	136,179	67%
Missouri	80%	225	162	28%	5,008	2,785	44%	70,844	19,221	73%
Pacific Surfliner	85%	6,998	552	92%	183,327	47,707	74%	2,595,499	477,414	82%
Pennsylvanian	80%	719	554	23%	15,671	3,115	80%	281,473	54,192	81%
Piedmont	80%	711	464	35%	18,046	3,668	80%	358,320	92,320	74%
Vermont	75%	1,251	227	82%	23,287	9,422	60%	408,171	122,628	70%
Long Distance	70%	11,014	5,000	55%	219,418	128,780	41%	3,902,017	1,705,714	56%
Auto Train	70%	848	451	47%	15,559	3,594	77%	249,968	84,383	66%
California Zephyr	70%	967	357	63%	18,144	13,180	27%	309,738	119,837	61%
Cardinal	70%	0	0	-	2,460	1,510	39%	73,941	37,053	50%
City Of New Orleans	75%	555	551	1%	10,841	8,526	21%	202,065	66,705	67%
Coast Starlight	70%	480	104	78%	17,360	8,832	49%	362,037	129,294	64%
Crescent	70%	767	127	83%	15,794	4,758	70%	295,447	90,741	69%
Empire Builder	70%	1,101	83	92%	18,444	11,051	40%	306,811	153,256	50%
Floridian	60%	1,551	1,192	23%	25,488	21,018	18%	503,254	348,060	31%
Lake Shore Ltd	73%	1,159	134	88%	20,887	8,223	61%	308,124	93,329	70%
Palmetto	70%	1,133	867	23%	16,488	9,115	45%	292,591	91,724	69%
Silver Meteor	70%	880	423	52%	18,177	12,140	33%	323,377	149,491	54%
Southwest Chief	60%	839	402	52%	16,595	13,094	21%	267,061	175,687	34%
Sunset Ltd	70%	287	237	17%	4,476	3,459	23%	92,842	36,227	61%
Texas Eagle	70%	447	72	84%	18,705	10,280	45%	314,761	129,927	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 00000000001 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 18, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	122,844	1,900,621	646	1,912,923	33,848,559	565

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	6,711	583,248	115	92,623	9,780,251	95
INFRASTRUCTURE PLANNED	135	11,740	583,248	201	107,795	9,780,251	110
FLEET RELIABILITY	90	19,090	1,900,621	100	305,230	33,848,559	90
TRAIN OPERATIONS	424	85,303	1,900,621	449	1,407,275	33,848,559	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/18/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	60	81.3%	5,478	887	83.8%	96,422	13,439	86.1%
Central Division	86.0%	57	15	73.7%	1,008	117	88.4%	18,436	1,691	90.8%
East Division	82.0%	176	27	84.7%	2,969	473	84.1%	50,639	7,891	84.4%
West Division	86.0%	87	18	79.3%	1,501	297	80.2%	27,347	3,857	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/18/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	60	81.3%	5,478	887	83.8%	96,422	13,439	86.1%
Central Division	86.0%	57	15	73.7%	1,008	117	88.4%	18,436	1,691	90.8%
CDL	95.0%	2	1	50.0%	34	5	85.3%	610	30	95.1%
CHI	86.0%	27	14	48.1%	467	82	82.4%	8,517	1,049	87.7%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	18	0	100.0%	345	36	89.6%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	12	0	100.0%	300	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	36	5	86.1%	623	49	92.1%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	104	6	94.2%	1,884	120	93.6%
MOE	97.5%	2	0	100.0%	36	0	100.0%	641	9	98.6%
MSP	96.5%	1	0	100.0%	18	1	94.4%	315	7	97.8%
NOL	94.5%	4	0	100.0%	79	2	97.5%	1,352	62	95.4%
OKC	97.0%	1	0	100.0%	18	0	100.0%	316	6	98.1%
PNT	88.0%	2	0	100.0%	50	5	90.0%	837	69	91.8%
PTH	93.0%	1	0	100.0%	18	2	88.9%	310	13	95.8%
QCY	91.0%	2	0	100.0%	30	2	93.3%	607	45	92.6%
SAS	90.5%	1	0	100.0%	18	3	83.3%	319	36	88.7%
STL	89.0%	4	0	100.0%	69	3	95.7%	1,244	103	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	27	84.7%	2,969	473	84.1%	50,639	7,891	84.4%
ALB	88.5%	8	0	100.0%	134	6	95.5%	2,384	181	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	90	12	86.7%	1,556	170	89.1%
BOS	85.5%	18	2	88.9%	311	28	91.0%	5,474	632	88.5%
BRK	92.5%	2	1	50.0%	84	9	89.3%	1,536	111	92.8%
BTN	82.0%	1	0	100.0%	17	1	94.1%	307	42	86.3%
CLT	91.5%	5	2	60.0%	90	10	88.9%	1,567	160	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	29	2	93.1%	622	59	90.5%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	1	92.3%	198	30	84.8%	3,562	578	83.8%
HFD	-	2	0	100.0%	23	3	87.0%	214	18	91.6%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	1	0.0%	18	1	94.4%	318	39	87.7%
MIA	89.5%	2	1	50.0%	33	5	84.8%	633	73	88.5%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/18/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	60	81.3%	5,478	887	83.8%	96,422	13,439	86.1%
East Division	82.0%	176	27	84.7%	2,969	473	84.1%	50,639	7,891	84.4%
MTR	79.0%	1	0	100.0%	18	5	72.2%	305	57	81.3%
NFK	84.5%	2	0	100.0%	36	6	83.3%	719	129	82.1%
NFL	93.5%	2	0	100.0%	36	1	97.2%	648	30	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	87	24	72.4%	1,641	277	83.1%
NPN	93.0%	2	1	50.0%	36	6	83.3%	608	47	92.3%
NYP	75.5%	50	9	82.0%	834	186	77.7%	13,318	2,964	77.7%
PGH	93.0%	1	0	100.0%	18	1	94.4%	319	23	92.8%
PHL	48.0%	5	2	60.0%	84	35	58.3%	1,634	775	52.6%
PIT	76.0%	-	-	-	5	5	0.0%	20	17	15.0%
POR	-	3	1	66.7%	6	3	50.0%	17	11	35.3%
RGH	95.0%	4	1	75.0%	64	3	95.3%	1,222	52	95.7%
RNK	83.5%	2	0	100.0%	36	2	94.4%	632	89	85.9%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	15	0	100.0%	302	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	18	1	94.4%	315	11	96.5%
SFA	88.0%	1	1	0.0%	18	2	88.9%	318	43	86.5%
SPG	92.5%	5	0	100.0%	87	5	94.3%	1,894	110	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	18	3	83.3%	307	63	79.5%
WAS	84.0%	31	3	90.3%	518	78	84.9%	7,990	1,045	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	87	18	79.3%	1,501	297	80.2%	27,347	3,857	85.9%
ARN	92.0%	1	0	100.0%	18	2	88.9%	320	28	91.3%
BFD	79.0%	7	2	71.4%	125	31	75.2%	2,022	424	79.0%
EMY	72.0%	1	0	100.0%	18	3	83.3%	336	97	71.1%
EUG	86.5%	2	0	100.0%	36	2	94.4%	634	58	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	54	16	70.4%	963	159	83.5%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	0	100.0%	184	19	89.7%	3,183	345	89.2%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	6	53.8%	208	77	63.0%	3,469	905	73.9%
PDX	86.0%	3	1	66.7%	47	31	34.0%	1,535	212	86.2%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/18/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	60	81.3%	5,478	887	83.8%	96,422	13,439	86.1%
West Division	86.0%	87	18	79.3%	1,501	297	80.2%	27,347	3,857	85.9%
SAC	88.5%	16	1	93.8%	261	25	90.4%	4,527	487	89.2%
SAN	90.5%	13	2	84.6%	229	21	90.8%	3,870	365	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	4	1	75.0%	73	31	57.5%	2,458	378	84.6%
SJC	89.0%	7	3	57.1%	125	14	88.8%	2,249	223	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	54	6	88.9%	726	71	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	36	0	100.0%	627	14	97.8%
VAN	-	2	1	50.0%	27	16	40.7%	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	57	7	4	42.9%	136	35	74.3%	8	3	62.5%	132	27	79.5%
3		18	4	77.8%	320	63	80.3%	17	11	35.3%	317	147	53.6%
4		18	1	94.4%	319	47	85.3%	18	13	27.8%	319	212	33.5%
5	38	18	4	77.8%	318	54	83.0%	18	15	16.7%	314	103	67.2%
6		18	3	83.3%	317	88	72.2%	18	16	11.1%	317	119	62.5%
7		18	5	72.2%	309	47	84.8%	17	7	58.8%	300	81	73.0%
8		18	10	44.4%	309	139	55.0%	18	13	27.8%	308	188	39.0%
11	No OS	18	15	16.7%	320	72	77.5%	18	6	66.7%	314	66	79.0%
14		18	2	88.9%	321	51	84.1%	17	10	41.2%	318	102	67.9%
19		18	4	77.8%	319	81	74.6%	18	5	72.2%	316	76	75.9%
20		18	0	100.0%	319	23	92.8%	18	4	77.8%	319	62	80.6%
21	No OS	18	7	61.1%	316	32	89.9%	18	6	66.7%	315	88	72.1%
22		18	3	83.3%	317	34	89.3%	18	9	50.0%	315	90	71.4%
23		18	0	100.0%	321	6	98.1%	18	3	83.3%	319	88	72.4%
24	80	18	0	100.0%	321	16	95.0%	18	6	66.7%	320	62	80.6%
25		18	0	100.0%	320	3	99.1%	17	6	64.7%	317	89	71.9%
26		18	0	100.0%	320	5	98.4%	17	1	94.1%	317	61	80.8%
40	474	15	5	66.7%	311	46	85.2%	14	10	28.6%	307	165	46.3%
41	283	16	7	56.3%	311	121	61.1%	15	13	13.3%	308	237	23.1%
42	23	18	1	94.4%	321	25	92.2%	18	4	77.8%	319	56	82.4%
43	23	18	3	83.3%	320	45	85.9%	18	3	83.3%	319	73	77.1%
48		18	5	72.2%	319	62	80.6%	18	5	72.2%	318	47	85.2%
49		18	5	72.2%	319	80	74.9%	18	5	72.2%	319	67	79.0%
52		18	2	88.9%	318	43	86.5%	18	0	100.0%	317	72	77.3%
53	91	18	1	94.4%	318	39	87.7%	18	6	66.7%	317	101	68.1%
55		12	1	91.7%	202	8	96.0%	12	4	66.7%	199	42	78.9%
56		12	2	83.3%	203	25	87.7%	12	5	58.3%	199	39	80.4%
58	223	17	1	94.1%	294	17	94.2%	16	14	12.5%	292	87	70.2%
59	223	18	12	33.3%	293	45	84.6%	17	14	17.6%	288	71	75.3%
63	40	18	8	55.6%	322	140	56.5%	18	18	0.0%	316	184	41.8%
64	20	18	3	83.3%	320	71	77.8%	18	14	22.2%	319	123	61.4%
66		18	1	94.4%	319	62	80.6%	18	5	72.2%	315	59	81.3%
67	47	13	1	92.3%	221	14	93.7%	12	4	66.7%	220	40	81.8%
68	76	18	5	72.2%	322	66	79.5%	18	12	33.3%	321	130	59.5%
69	40	18	9	50.0%	309	77	75.1%	18	10	44.4%	304	53	82.6%
71		18	0	100.0%	317	3	99.1%	17	4	76.5%	315	85	73.0%
72	22	18	4	77.8%	313	35	88.8%	17	7	58.8%	311	68	78.1%
73	62	18	3	83.3%	316	22	93.0%	18	5	72.2%	314	147	53.2%
74	30	18	1	94.4%	314	34	89.2%	18	5	72.2%	312	113	63.8%
75	32	18	0	100.0%	310	16	94.8%	18	8	55.6%	304	145	52.3%
76	16	18	1	94.4%	310	30	90.3%	18	8	55.6%	301	125	58.5%
77		18	0	100.0%	312	20	93.6%	18	5	72.2%	310	128	58.7%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		18	1	94.4%	316	26	91.8%	18	8	55.6%	315	71	77.5%
79		18	2	88.9%	319	58	81.8%	18	6	66.7%	318	107	66.4%
80		18	3	83.3%	319	36	88.7%	18	8	55.6%	316	71	77.5%
84		12	4	66.7%	193	18	90.7%	10	4	60.0%	189	47	75.1%
85		12	2	83.3%	204	18	91.2%	12	4	66.7%	204	74	63.7%
86		12	1	91.7%	204	16	92.2%	12	4	66.7%	203	119	41.4%
89		18	9	50.0%	317	74	76.7%	18	10	44.4%	315	95	69.8%
90	36	18	1	94.4%	317	11	96.5%	18	8	55.6%	316	59	81.3%
93		12	2	83.3%	203	21	89.7%	12	7	41.7%	202	54	73.3%
94		12	3	75.0%	234	58	75.2%	12	4	66.7%	232	87	62.5%
95	128	12	2	83.3%	203	6	97.0%	12	10	16.7%	203	79	61.1%
97	49	18	12	33.3%	319	210	34.2%	18	13	27.8%	317	113	64.4%
98		18	0	100.0%	319	26	91.8%	18	10	44.4%	317	118	62.8%
110		12	1	91.7%	200	103	48.5%	12	1	91.7%	197	20	89.8%
111		12	1	91.7%	194	36	81.4%	12	1	91.7%	192	22	88.5%
112		12	1	91.7%	194	19	90.2%	12	0	100.0%	193	19	90.2%
113		12	5	58.3%	125	30	76.0%	12	1	91.7%	124	15	87.9%
119		12	2	83.3%	191	47	75.4%	12	4	66.7%	189	26	86.2%
125	18	12	1	91.7%	204	12	94.1%	12	8	33.3%	204	82	59.8%
129		12	2	83.3%	203	49	75.9%	12	1	91.7%	203	29	85.7%
130		12	2	83.3%	194	20	89.7%	12	0	100.0%	192	16	91.7%
131	31	12	3	75.0%	196	56	71.4%	12	2	83.3%	196	37	81.1%
134		12	3	75.0%	204	30	85.3%	12	4	66.7%	203	40	80.3%
136		12	0	100.0%	204	24	88.2%	12	2	83.3%	202	27	86.6%
137		12	1	91.7%	201	36	82.1%	12	3	75.0%	201	61	69.7%
138		12	1	91.7%	204	40	80.4%	12	4	66.7%	203	38	81.3%
141		12	1	91.7%	203	4	98.0%	12	2	83.3%	202	35	82.7%
148	32	12	2	83.3%	203	22	89.2%	12	4	66.7%	201	40	80.1%
151	16	18	7	61.1%	318	102	67.9%	18	3	83.3%	317	98	69.1%
170		12	0	100.0%	199	12	94.0%	12	0	100.0%	198	29	85.4%
171	54	12	0	100.0%	204	11	94.6%	12	10	16.7%	204	85	58.3%
172		12	3	75.0%	203	18	91.1%	12	7	41.7%	201	69	65.7%
173		12	1	91.7%	196	25	87.2%	12	5	58.3%	195	83	57.4%
174		12	2	83.3%	204	22	89.2%	12	4	66.7%	204	52	74.5%
175	88	12	1	91.7%	204	23	88.7%	12	5	58.3%	204	67	67.2%
176		12	2	83.3%	196	17	91.3%	12	2	83.3%	194	26	86.6%
177	31	12	1	91.7%	204	28	86.3%	12	1	91.7%	204	47	77.0%
178	44	12	0	100.0%	204	26	87.3%	12	3	75.0%	202	34	83.2%
179	27	12	1	91.7%	204	24	88.2%	12	3	75.0%	203	73	64.0%
181		12	3	75.0%	200	62	69.0%	11	1	90.9%	197	16	91.9%
182		12	1	91.7%	194	31	84.0%	12	0	100.0%	192	21	89.1%
183		12	6	50.0%	203	62	69.5%	12	5	58.3%	200	43	78.5%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		12	3	75.0%	204	36	82.4%	12	1	91.7%	203	28	86.2%
185		12	2	83.3%	204	39	80.9%	12	1	91.7%	204	15	92.6%
186		12	5	58.3%	203	26	87.2%	12	7	41.7%	202	60	70.3%
190		12	3	75.0%	203	72	64.5%	12	1	91.7%	202	44	78.2%
192	60	12	0	100.0%	201	24	88.1%	12	2	83.3%	201	19	90.5%
193		11	5	54.5%	199	83	58.3%	11	1	90.9%	198	89	55.1%
196		12	2	83.3%	200	22	89.0%	11	1	90.9%	198	16	91.9%
197	21	12	1	91.7%	204	76	62.7%	12	3	75.0%	204	70	65.7%
198		12	0	100.0%	136	17	87.5%	12	1	91.7%	135	22	83.7%
230	51	18	0	100.0%	155	4	97.4%	18	1	94.4%	155	8	94.8%
232		18	0	100.0%	321	11	96.6%	18	2	88.9%	321	23	92.8%
233	36	13	2	84.6%	286	63	78.0%	13	7	46.2%	285	95	66.7%
234		18	0	100.0%	322	22	93.2%	18	1	94.4%	321	26	91.9%
235		18	7	61.1%	246	41	83.3%	18	5	72.2%	245	57	76.7%
236		18	0	100.0%	306	10	96.7%	18	3	83.3%	305	42	86.2%
237	68	18	1	94.4%	319	57	82.1%	18	4	77.8%	317	55	82.6%
238		18	3	83.3%	246	23	90.7%	18	3	83.3%	244	21	91.4%
239		18	2	88.9%	320	81	74.7%	18	2	88.9%	319	40	87.5%
240		18	1	94.4%	321	22	93.1%	18	5	72.2%	318	65	79.6%
241		18	6	66.7%	321	80	75.1%	18	7	61.1%	321	78	75.7%
243		18	4	77.8%	257	69	73.2%	18	3	83.3%	256	36	85.9%
244		13	0	100.0%	285	12	95.8%	13	9	30.8%	285	58	79.6%
245	22	18	6	66.7%	202	39	80.7%	18	6	66.7%	201	28	86.1%
280	60	18	1	94.4%	322	16	95.0%	18	8	55.6%	321	69	78.5%
281		18	2	88.9%	322	39	87.9%	18	2	88.9%	322	59	81.7%
283		18	8	55.6%	322	82	74.5%	18	3	83.3%	322	64	80.1%
284	49	18	0	100.0%	322	13	96.0%	18	2	88.9%	319	56	82.4%
290	24	18	1	94.4%	322	51	84.2%	18	13	27.8%	319	127	60.2%
291		18	11	38.9%	321	104	67.6%	17	8	52.9%	318	84	73.6%
300		16	1	93.8%	304	21	93.1%	16	5	68.8%	302	73	75.8%
301		18	0	100.0%	319	10	96.9%	18	5	72.2%	315	60	81.0%
302	17	17	0	100.0%	300	33	89.0%	17	8	52.9%	296	86	70.9%
305	125	16	2	87.5%	302	30	90.1%	16	5	68.8%	298	120	59.7%
306		18	1	94.4%	317	17	94.6%	17	5	70.6%	315	87	72.4%
307	36	18	3	83.3%	310	41	86.8%	17	7	58.8%	306	89	70.9%
311	23	18	1	94.4%	315	27	91.4%	18	11	38.9%	309	74	76.1%
316	24	18	3	83.3%	311	21	93.2%	18	13	27.8%	306	91	70.3%
318		18	2	88.9%	320	33	89.7%	18	12	33.3%	317	156	50.8%
319	18	18	0	100.0%	321	20	93.8%	18	17	5.6%	316	182	42.4%
329		12	0	100.0%	227	9	96.0%	12	1	91.7%	227	16	93.0%
330		15	0	100.0%	273	6	97.8%	15	0	100.0%	273	15	94.5%
331		18	0	100.0%	322	33	89.8%	17	0	100.0%	321	44	86.3%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		17	1	94.1%	321	18	94.4%	17	2	88.2%	321	45	86.0%
334		18	1	94.4%	322	11	96.6%	17	1	94.1%	320	41	87.2%
335		18	0	100.0%	322	34	89.4%	18	3	83.3%	320	54	83.1%
336		18	0	100.0%	322	10	96.9%	18	0	100.0%	320	28	91.3%
337		18	1	94.4%	322	19	94.1%	18	5	72.2%	318	41	87.1%
338		18	3	83.3%	322	50	84.5%	18	6	66.7%	320	100	68.8%
339		18	3	83.3%	322	53	83.5%	18	3	83.3%	322	56	82.6%
341	51	17	5	70.6%	309	49	84.1%	17	9	47.1%	303	50	83.5%
342		18	1	94.4%	322	25	92.2%	18	0	100.0%	320	60	81.3%
351	23	17	2	88.2%	304	29	90.5%	17	8	52.9%	302	86	71.5%
352		17	3	82.4%	288	24	91.7%	17	8	52.9%	282	89	68.4%
353	36	18	0	100.0%	260	13	95.0%	18	8	55.6%	254	46	81.9%
354		18	1	94.4%	303	36	88.1%	18	12	33.3%	296	113	61.8%
364	47	18	6	66.7%	311	71	77.2%	18	10	44.4%	305	117	61.6%
365	40	18	2	88.9%	310	13	95.8%	17	9	47.1%	307	118	61.6%
370	55	13	2	84.6%	308	37	88.0%	12	4	66.7%	297	73	75.4%
371	199	12	0	100.0%	300	8	97.3%	12	1	91.7%	299	30	90.0%
380	17	15	1	93.3%	304	28	90.8%	14	5	64.3%	303	68	77.6%
381		15	1	93.3%	317	13	95.9%	15	8	46.7%	316	68	78.5%
382		15	1	93.3%	316	28	91.1%	15	11	26.7%	316	111	64.9%
383		16	1	93.8%	309	27	91.3%	16	8	50.0%	306	131	57.2%
390	26	17	5	70.6%	303	24	92.1%	16	11	31.3%	301	84	72.1%
391		17	2	88.2%	304	13	95.7%	17	11	35.3%	300	87	71.0%
392	62	17	0	100.0%	317	10	96.8%	16	7	56.3%	313	97	69.0%
393		17	1	94.1%	321	19	94.1%	16	10	37.5%	317	101	68.1%
417		12	2	83.3%	214	46	78.5%	12	2	83.3%	205	24	88.3%
425		11	1	90.9%	215	7	96.7%	10	0	100.0%	214	7	96.7%
448		12	2	83.3%	246	45	81.7%	11	4	63.6%	242	84	65.3%
449		12	1	91.7%	243	33	86.4%	12	2	83.3%	243	44	81.9%
470		12	2	83.3%	227	39	82.8%	12	2	83.3%	221	26	88.2%
471		11	2	81.8%	216	13	94.0%	11	0	100.0%	216	5	97.7%
473		12	0	100.0%	223	15	93.3%	12	0	100.0%	220	10	95.5%
474		12	2	83.3%	221	65	70.6%	12	4	66.7%	206	67	67.5%
475		12	1	91.7%	221	7	96.8%	12	0	100.0%	221	15	93.2%
478		12	3	75.0%	215	35	83.7%	12	1	91.7%	213	28	86.9%
479		12	2	83.3%	222	36	83.8%	12	3	75.0%	220	34	84.5%
486	18	12	3	75.0%	226	34	85.0%	12	3	75.0%	220	61	72.3%
494		13	5	61.5%	229	46	79.9%	12	4	66.7%	221	61	72.4%
495		12	0	100.0%	211	4	98.1%	12	0	100.0%	209	3	98.6%
503	54	18	13	27.8%	318	40	87.4%	18	13	27.8%	311	100	67.8%
504		18	1	94.4%	322	20	93.8%	18	5	72.2%	320	95	70.3%
505		12	1	91.7%	314	42	86.6%	12	4	66.7%	309	88	71.5%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506		18	13	27.8%	317	55	82.6%	16	3	81.3%	309	49	84.1%
507		18	11	38.9%	322	47	85.4%	18	11	38.9%	322	111	65.5%
508	16	18	1	94.4%	317	42	86.8%	18	11	38.9%	313	79	74.8%
516		18	6	66.7%	313	35	88.8%	18	8	55.6%	312	142	54.5%
517	77	18	0	100.0%	322	8	97.5%	18	15	16.7%	318	142	55.3%
518	69	18	8	55.6%	322	45	86.0%	18	18	0.0%	320	225	29.7%
519	20	18	0	100.0%	313	9	97.1%	18	5	72.2%	311	71	77.2%
520		12	3	75.0%	185	28	84.9%	10	1	90.0%	180	10	94.4%
521	Cncl'd	12	0	100.0%	223	7	96.9%	11	3	72.7%	222	30	86.5%
522		12	2	83.3%	223	41	81.6%	12	1	91.7%	220	21	90.5%
523	19	12	2	83.3%	223	9	96.0%	12	4	66.7%	222	26	88.3%
524	39	11	1	90.9%	222	17	92.3%	11	3	72.7%	219	26	88.1%
525		11	0	100.0%	220	16	92.7%	11	1	90.9%	216	15	93.1%
526		12	6	50.0%	197	40	79.7%	12	3	75.0%	194	18	90.7%
527		12	0	100.0%	223	10	95.5%	12	2	83.3%	222	39	82.4%
528	18	12	1	91.7%	223	18	91.9%	12	2	83.3%	222	32	85.6%
529	17	12	1	91.7%	223	13	94.2%	12	5	58.3%	222	63	71.6%
530		12	1	91.7%	177	17	90.4%	12	3	75.0%	177	35	80.2%
531		12	0	100.0%	197	13	93.4%	12	0	100.0%	197	13	93.4%
532		12	5	58.3%	223	56	74.9%	11	3	72.7%	221	34	84.6%
534		12	2	83.3%	182	27	85.2%	12	0	100.0%	180	16	91.1%
535	20	11	1	90.9%	209	26	87.6%	11	3	72.7%	204	26	87.3%
536		12	5	58.3%	223	60	73.1%	12	2	83.3%	219	40	81.7%
537		11	0	100.0%	192	22	88.5%	11	2	81.8%	186	22	88.2%
538		12	2	83.3%	223	26	88.3%	12	2	83.3%	222	45	79.7%
539		12	2	83.3%	177	26	85.3%	12	5	58.3%	177	76	57.1%
540		12	2	83.3%	222	40	82.0%	11	1	90.9%	213	19	91.1%
541	15	12	1	91.7%	222	23	89.6%	12	3	75.0%	216	39	81.9%
542		12	1	91.7%	222	25	88.7%	12	3	75.0%	219	40	81.7%
543	26	12	1	91.7%	223	25	88.8%	12	5	58.3%	223	68	69.5%
544		12	1	91.7%	221	21	90.5%	11	2	81.8%	217	22	89.9%
545		12	1	91.7%	223	18	91.9%	12	3	75.0%	220	27	87.7%
547		12	4	66.7%	223	45	79.8%	12	5	58.3%	223	52	76.7%
548	21	11	1	90.9%	217	22	89.9%	10	2	80.0%	214	17	92.1%
549		12	1	91.7%	218	27	87.6%	11	3	72.7%	209	20	90.4%
550	23	12	1	91.7%	177	19	89.3%	12	6	50.0%	177	42	76.3%
551	12	12	1	91.7%	219	23	89.5%	12	3	75.0%	209	23	89.0%
562		18	2	88.9%	313	25	92.0%	18	0	100.0%	309	35	88.7%
564		18	0	100.0%	314	19	93.9%	18	3	83.3%	306	41	86.6%
566		18	3	83.3%	312	28	91.0%	18	6	66.7%	309	51	83.5%
567		18	0	100.0%	199	10	95.0%	18	2	88.9%	197	11	94.4%
572		18	2	88.9%	309	26	91.6%	18	8	55.6%	302	91	69.9%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		18	3	83.3%	311	43	86.2%	18	3	83.3%	304	54	82.2%
579		18	1	94.4%	199	12	94.0%	17	3	82.4%	193	40	79.3%
580		18	1	94.4%	314	17	94.6%	18	4	77.8%	307	32	89.6%
581	20	18	3	83.3%	314	53	83.1%	18	8	55.6%	312	72	76.9%
584	36	18	3	83.3%	198	28	85.9%	18	17	5.6%	193	125	35.2%
587		18	2	88.9%	307	18	94.1%	18	4	77.8%	298	57	80.9%
588		16	1	93.8%	197	19	90.4%	16	5	68.8%	196	38	80.6%
591		18	1	94.4%	311	22	92.9%	17	4	76.5%	304	43	85.9%
593		15	2	86.7%	305	49	83.9%	15	1	93.3%	284	38	86.6%
595	33	16	4	75.0%	307	57	81.4%	16	5	68.8%	304	65	78.6%
600	46	12	0	100.0%	231	9	96.1%	12	2	83.3%	229	21	90.8%
601		12	5	58.3%	214	88	58.9%	12	2	83.3%	211	27	87.2%
605		12	6	50.0%	221	136	38.5%	12	0	100.0%	217	22	89.9%
607		12	0	100.0%	230	30	87.0%	12	0	100.0%	227	25	89.0%
609		12	0	100.0%	221	23	89.6%	12	2	83.3%	220	21	90.5%
622		10	1	90.0%	130	33	74.6%	10	0	100.0%	128	5	96.1%
626		12	3	75.0%	135	19	85.9%	12	0	100.0%	133	18	86.5%
639		12	1	91.7%	201	39	80.6%	12	0	100.0%	200	19	90.5%
640		12	0	100.0%	221	7	96.8%	12	4	66.7%	219	84	61.6%
641		12	3	75.0%	203	41	79.8%	12	1	91.7%	203	27	86.7%
642	20	12	2	83.3%	219	11	95.0%	12	1	91.7%	218	27	87.6%
643		12	0	100.0%	233	44	81.1%	12	2	83.3%	230	38	83.5%
644		12	0	100.0%	225	28	87.6%	12	2	83.3%	223	54	75.8%
645		12	0	100.0%	233	41	82.4%	12	7	41.7%	230	53	77.0%
646	24	12	2	83.3%	222	53	76.1%	12	6	50.0%	220	107	51.4%
647		12	0	100.0%	233	32	86.3%	12	0	100.0%	232	49	78.9%
648		12	2	83.3%	229	58	74.7%	12	1	91.7%	229	35	84.7%
649		12	1	91.7%	234	43	81.6%	12	0	100.0%	231	34	85.3%
650		12	3	75.0%	233	44	81.1%	12	1	91.7%	230	37	83.9%
651		12	1	91.7%	233	17	92.7%	12	1	91.7%	231	43	81.4%
652		12	2	83.3%	234	31	86.8%	12	2	83.3%	230	39	83.0%
653		12	3	75.0%	222	36	83.8%	12	1	91.7%	219	40	81.7%
654		12	2	83.3%	223	42	81.2%	12	1	91.7%	219	19	91.3%
655		12	2	83.3%	231	74	68.0%	12	2	83.3%	229	75	67.2%
656		12	5	58.3%	233	52	77.7%	12	2	83.3%	232	32	86.2%
657	27	12	2	83.3%	222	29	86.9%	12	1	91.7%	221	30	86.4%
658		12	1	91.7%	233	36	84.5%	12	0	100.0%	231	33	85.7%
680	Cncld	12	0	100.0%	228	12	94.7%	11	0	100.0%	226	27	88.1%
681	Cncld	12	1	91.7%	228	18	92.1%	11	5	54.5%	221	91	58.8%
682	85	12	2	83.3%	227	8	96.5%	12	2	83.3%	227	40	82.4%
683	18	12	1	91.7%	210	18	91.4%	12	4	66.7%	209	71	66.0%
684		12	3	75.0%	209	35	83.3%	12	0	100.0%	209	45	78.5%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685		12	0	100.0%	224	31	86.2%	12	1	91.7%	221	54	75.6%
686		12	1	91.7%	229	38	83.4%	12	4	66.7%	228	51	77.6%
687		12	3	75.0%	228	37	83.8%	12	2	83.3%	227	38	83.3%
688	12	12	1	91.7%	227	14	93.8%	12	4	66.7%	226	40	82.3%
701		18	3	83.3%	254	28	89.0%	18	4	77.8%	251	29	88.4%
702	20	18	0	100.0%	321	32	90.0%	18	8	55.6%	318	78	75.5%
703		18	13	27.8%	322	106	67.1%	18	10	44.4%	320	95	70.3%
704		18	5	72.2%	253	42	83.4%	17	6	64.7%	245	52	78.8%
710	47	18	1	94.4%	322	78	75.8%	18	6	66.7%	318	87	72.6%
711	28	18	1	94.4%	313	35	88.8%	16	9	43.8%	290	61	79.0%
712		18	8	55.6%	319	88	72.4%	18	9	50.0%	310	107	65.5%
713	45	17	1	94.1%	189	17	91.0%	13	9	30.8%	169	76	55.0%
714		18	11	38.9%	203	86	57.6%	16	11	31.3%	187	87	53.5%
715	54	18	1	94.4%	321	62	80.7%	15	9	40.0%	295	150	49.2%
716	41	18	13	27.8%	322	133	58.7%	17	14	17.6%	315	132	58.1%
717	16	18	3	83.3%	307	71	76.9%	15	6	60.0%	285	92	67.7%
718		18	13	27.8%	322	166	48.4%	17	11	35.3%	319	120	62.4%
719	25	18	9	50.0%	322	112	65.2%	17	9	47.1%	305	93	69.5%
757		18	1	94.4%	107	6	94.4%	18	2	88.9%	106	10	90.6%
761		18	1	94.4%	318	13	95.9%	18	2	88.9%	315	43	86.3%
765		18	0	100.0%	318	25	92.1%	18	3	83.3%	318	45	85.8%
769		18	0	100.0%	318	27	91.5%	18	4	77.8%	312	61	80.4%
770		18	2	88.9%	318	24	92.5%	18	10	44.4%	316	99	68.7%
774		18	0	100.0%	318	16	95.0%	18	5	72.2%	317	74	76.7%
777		18	0	100.0%	203	12	94.1%	18	8	55.6%	202	50	75.2%
782		18	13	27.8%	203	95	53.2%	18	5	72.2%	198	30	84.8%
785		18	4	77.8%	318	26	91.8%	18	5	72.2%	318	58	81.8%
786		18	2	88.9%	107	21	80.4%	17	10	41.2%	103	57	44.7%
790		18	1	94.4%	318	29	90.9%	18	3	83.3%	315	49	84.4%
794		18	4	77.8%	318	37	88.4%	18	6	66.7%	314	72	77.1%
821		18	0	100.0%	316	6	98.1%	18	11	38.9%	316	132	58.2%
822	59	18	0	100.0%	318	16	95.0%	18	16	11.1%	316	158	50.0%
1333	62	18	5	72.2%	318	37	88.4%	18	6	66.7%	315	105	66.7%
1340		18	1	94.4%	317	7	97.8%	18	4	77.8%	317	55	82.6%
1689		12	1	91.7%	107	6	94.4%	12	2	83.3%	106	13	87.7%
2102		12	1	91.7%	80	14	82.5%	12	1	91.7%	79	7	91.1%
2103		12	1	91.7%	144	13	91.0%	12	1	91.7%	143	10	93.0%
2104		12	0	100.0%	170	10	94.1%	12	1	91.7%	168	13	92.3%
2107		12	1	91.7%	201	35	82.6%	12	1	91.7%	198	21	89.4%
2108		12	2	83.3%	201	28	86.1%	12	6	50.0%	195	26	86.7%
2109		12	1	91.7%	94	12	87.2%	12	1	91.7%	92	5	94.6%
2112		12	2	83.3%	41	6	85.4%	12	0	100.0%	39	2	94.9%

Amtrak On Time Performance

Trains Arriving Through: 8/18/2026

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2113		12	1	91.7%	80	9	88.8%	12	0	100.0%	80	10	87.5%
2115		12	1	91.7%	80	12	85.0%	12	1	91.7%	79	11	86.1%
2116		12	0	100.0%	41	1	97.6%	12	1	91.7%	41	8	80.5%
2118		12	2	83.3%	41	4	90.2%	12	2	83.3%	41	11	73.2%
2119		12	2	83.3%	41	6	85.4%	11	2	81.8%	40	12	70.0%
2120		12	9	25.0%	41	18	56.1%	11	8	27.3%	39	21	46.2%
2123		12	1	91.7%	79	9	88.6%	12	0	100.0%	78	15	80.8%
2124		11	4	63.6%	172	38	77.9%	11	2	81.8%	170	24	85.9%
2127		12	2	83.3%	41	9	78.0%	12	1	91.7%	40	8	80.0%
2128		12	1	91.7%	41	4	90.2%	12	1	91.7%	41	3	92.7%
2131		12	3	75.0%	41	9	78.0%	12	1	91.7%	41	4	90.2%
2150		12	0	100.0%	194	22	88.7%	12	1	91.7%	191	74	61.3%
2151		12	1	91.7%	143	7	95.1%	12	3	75.0%	141	40	71.6%
2152		12	1	91.7%	99	7	92.9%	12	1	91.7%	98	31	68.4%
2154		12	0	100.0%	102	23	77.5%	12	3	75.0%	98	45	54.1%
2155		12	1	91.7%	203	17	91.6%	12	4	66.7%	199	100	49.7%
2158		12	1	91.7%	40	5	87.5%	12	3	75.0%	40	15	62.5%
2159	23	12	2	83.3%	196	16	91.8%	12	8	33.3%	194	67	65.5%
2160	23	12	0	100.0%	41	2	95.1%	12	8	33.3%	40	26	35.0%
2162		12	4	66.7%	202	22	89.1%	12	5	58.3%	196	90	54.1%
2165		12	2	83.3%	38	4	89.5%	12	8	33.3%	38	21	44.7%
2167		12	0	100.0%	189	20	89.4%	12	1	91.7%	189	40	78.8%
2171		12	0	100.0%	130	10	92.3%	12	0	100.0%	126	23	81.7%
2190		12	2	83.3%	199	29	85.4%	12	1	91.7%	197	24	87.8%
2193		12	0	100.0%	194	25	87.1%	12	1	91.7%	192	50	74.0%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2159	WAS	23	DMW	19	DMW	19	NHV-STM	MN	Waiting for MW clearance Also waited outside of STM station waiting for track, Milepost, 50.8, 52.2
2160	BOS	23	RTE	19	RTE	12	STM-NHV	MN	Dispatcher hold Possible Trespasser Strike at Darien, Control Point, 234
67	NPN	47	DCS	30	CTI	13	BWI-NCR	AM	Follow, Marc, 9511, Milepost, 106.3, 134.6
95	NFK	128	PTI	86	PTI	37	WDB-FBG	CS	Follow Amt 41, Other, Featherstone
125	NPN	18	CTI	43	CTI	32	ALX-WDB	CS	Follow vre, Other, alx-wdb
131	WAS	31	OTH	20	SYS	13	BAL-BAL	AM	PTC- IETMS Software Download, 435 stopped ahead, MARC having system wide IETMS issues
148	SPG	32	DSR	10	CTI	8	XPB-XSH	AM	Cross Traffic, MN, MN, Other, XSH
151	RNK	16	PTI	31	PTI	10	XVG-ALX	CS	Follow 67, Milepost, 112.2, 105.2
171	RNK	54	CTI	46	SMW	13	XSH-NYP	AM	Scheduled in track usage program, Other, XM9, HELD F/AM2154 A/C 1 TRK OOS MANOR TO LEGGETT
175	WAS	88	CTI	56	CTI	48	NHV-STM	MN	Follow metro, Other, enroute
177	PHL	31	CTI	26	ENG	23	BOS-BOS	AM	PTC - On Board Cab Signal or PTC Failure, 670 EX ES, Late release from the yard, issues with ACSES on unit 670, able to resolve before being released
178	BOS	44	CTP	51	CTP	51	NHV-NLC	AM	Delay due to mechanical problems on a Commuter train, CDOT No. 1652 has been terminated at Branford. No. 178 will perform a train to train transfer and carry the passengers east
179	PHL	27	CTI	16	CTI	11	XSH-NYP	AM	Follow, LG, LI1589, Other, XHR-NYP
192	NYP	60	CTP	57	CTP	57	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, NJ3984 DISABLED AHEAD IN THE SOUTH TUBE
197	WAS	21	OTH	15	SMW	12	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 3 track o/s between Davis & Bacon
486	GFD	18	PTI	17	PTI	17	BER-HFD	AM	Meet, 55, Milepost, X0W, XOW, Meet AM 55 at Willow a/c track work
53	SFA	91	SYS	99	SYS	99	XPX-XDD	CS	PTC problem or failure (cause unknown) CSX PTC outage, Other, Deland
600	NYP	46	ENG	31	ENG	31	MID-MID	AM	Undesired emergency application, 604 EX ES, ALERTER FAILURE

Amtrak Endpoint OTP Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
642	NYP	20	ENG	12	ENG	12	PHL-PHL	AM	PTC - On Board Cab Signal or PTC Failure, 9645 CB CC
646	NYP	24	ENG	23	ENG	23	HAR-HAR	AM	Undesired emergency application, 662 EX ES, PANTOGRAPH DROPPED TWICE SWAPPED EQUIPMENT WITH 648
657	HAR	27	CON	24	CON	24	PHL-PHL	AM	Hold for connecting train, HELD FOR PASSENGER OFF 175.
680	BON	Trn Cancelled							
681	POR	Trn Cancelled							
682	BON	85	FTI	41	FTI	41	POR-POR	CS	Freight train broken down holding a Portland Station csx, Control Point, Scarborough
683	POR	18	PTI	17	PTI	17	EXR-DHM	CS	Meet 684, Control Point, rockingham
688	BON	12	INJ	20	INJ	20	EXR-EXR	CS	Passenger having seizures
63	TWO	40	DCS	11	DCS	11	YNY-CRT	MN	Restrictive signal(s) from known wayside signal failure Stop, Control Point, 25
64	NYP	20	FTI	93	FTI	45	BUF-ROC	CS	Following multiple freight trains ahead of us and held at 425 then held at 406 csx, Milepost, 425, 406
68	NYP	76	FTI	40	FTI	40	SLQ-RSP	CN	Meet 323, Siding, Lacadie
69	MTR	40	PTI	39	PTI	31	WSP-PLB	DH	Meet 68, Siding, bluffs point
230	NYP	51	CTI	21	CTI	17	XCP-CRT	MN	Follow man, local, Milepost, 61, 39
233	ALB	36	CTI	25	CTI	19	CRT-POU	MN	Meet mn, 858, Control Point, 39
237	ALB	68	CTI	31	ITI	31	NYP-NYP	AM	Service, turn, or wye train, 284, LATE TURN OFF AM234
245	ALB	22	ITI	34	ITI	34	NYP-NYP	AM	Service, turn, or wye train, 68
280	NYP	60	DSR	29	DSR	27	BUF-ROC	CS	Per MW foreman Milepost, 402.5, 397.0, 25, trk 1, Milepost, 397.0, 391.5, 25, trk 1
284	NYP	49	ENG	54	ENG	30	BUF-ROC	CS	PTC - On Board Cab Signal or PTC Failure 123
290	NYP	24	PTI	21	PTI	17	ALB-HUD	AM	Follow 234, Control Point, 124
42	NYP	23	ENG	17	ENG	17	XHM-TRE	AM	Air / Brake, 632, BRAKE PIPE PROBLEM WITH ENG.632
43	PGH	23	ENG	39	ENG	39	NYP-NYP	AM	Other electrical failure, 607, LATE F/SSYD SHOPPED ENG.607 A/C CHIPPED CARBON STRIP SUBBED ENG.632

Amtrak Endpoint OTP Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/18/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
72	RGH	22	DCS	25	DCS	25	CLT-CLT	NS	PTC- Unplanned PTC system /server outage Other, CLT	
73	CLT	62	DCS	60	DCS	60	RGH-RGH	NS	PTC- Unplanned PTC system /server outage CSX had unplanned PTC outage; unable to proceed from initial terminal., Milepost w/Letters, S156.0, S156.0	
74	RGH	30	ITI	17	ITI	17	CLT-CLT	NS	Service, turn, or wye train 73	
75	CLT	32	PTI	32	PTI	18	CYN-DNC	NS	Meet #Amt72, Control Point, D&S Jct	
76	RGH	16	FTI	19	FTI	19	KAN-GRO	NS	Follow #NS12R, Control Point, Lee	
90	NYP	36	SYS	48	PTI	21	XDJ-ALX	CS	Follow 186, Milepost w/Letters, cfp61.1, cfp105.1	
97	MIA	49	DCS	46	SYS	28	JSP-JAX	CS	PTC problem or failure (cause unknown) PTC disengage at mp A 560.5 had to run 59 mph, Other, A 560.5	
40	CHI	474	WTR	296	WTR	228	CAM-HAM	CS	Trees down Hit a tree mp287 we had a mechanical inspection at mp 284. Mechanical had to get the correct tools to cut the plow. Did another inspection at mp 283.5 and had to do some more modifications, Milepost, 287, 283.5	
41	MIA	283	SYS	185	SYS	75	TPA-TPA	CS	PTC problem or failure (cause unknown) Other, A 882.0	
24	MOE	80	SYS	88	SYS	88	XNO-BAS	CS	PTC problem or failure (cause unknown)	
5	EMY	38	FTI	120	PTI	39	HLD-MCK	BN	Meet Amtk 6, Siding, Indianola	
521	SJC	Trn Cancelled								
523	SJC	19	SYS	21	SYS	21	OKJ-OAC	UP	Blocked by or assisting another, disabled Amtrak train Train to train transfer of passengers from 521. 521 had struck a vehicle which was a confirmed fatality., Milepost, 10.1, 10.1	
524	SAC	39	POL	57	POL	25	HAY-OAC	UP	RR blocked by trespasser or vehicle strike by another train	
528	SAC	18	ITI	27	ITI	27	SJC-SJC	UP	Due to vehicle strike involving 521 equipment, Inbound equipment for 528 arrived as 523. 523, Due to vehicle strike involving 521 equipment, Inbound equipment for 528 arrived as 523	
529	SJC	17	PTI	29	PTI	17	FMT-GAC	UP	Meet 530, Control Point, Albee	
535	OKJ	20	PTI	24	PTI	18	EMY-OKJ	UP	Wait for station track Amt 711/Amt 11/Amt 530, Control Point, King St	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
541	OKJ	15	DCS	12	DCS	10	EMY-OKJ	UP	Issue with automatic road crossing protection Milepost, 6.20, 6.20
543	SJC	26	PTI	23	PTI	12	EMY-OKJ	UP	Meet 538, Control Point, king
548	SAC	21	MBO	17	MBO	17	MTZ-MTZ	UP	For maritime traffic Dispatcher had us hold at MTZ Station., Other, Martinez Station
550	SAC	23	SYS	14	SYS	14	MTZ-SUI	UP	Efficiency test involving Amtrak officer(s) Milepost, 39.0, 39.0
551	OKJ	12	PTI	12	PTI	12	FFV-SUI	UP	Meet 550, Milepost, 53, 53
503	EUG	54	DMW	57	DMW	57	ORC-SLM	UP	Waiting for MW clearance Dispatcher unable to contact MOW Grossehelweg, Siding, labish
508	PDX	16	DSR	12	PTI	7	EUG-ALY	UP	Meet 11, Siding, hallawell
517	VAN	77	SVS	43	SVS	43	SEA-TUK	BN	Fuel Fueled on wash track after departing Seattle
518	VAC	69	DSR	42	FTI	15	BEL-X8B	BN	Meet bnsf 5978, Siding, swift
519	SEA	20	FTI	22	FTI	22	X8B-BEL	BN	Meet BNSF 2721, Control Point, Custer
58	CHI	223	SYS	92	SYS	89	MKS-MKS	CC	Re-crew / job briefing Waiting on engineer recrew and CN pilot, Control Point, mks
59	NOL	223	ITI	172	ITI	172	CHI-CHI	AM	Service, turn, or wye train 22, Late turn/ Wye of late inbound train 22 caused to swap out car for delay.
11	LAX	No OS Rpt	SVS	117	SVS	74	SLO-SLO	UP	Calendar day inspections on locomotives
822	OKC	59	DSR	41	FTI	25	FTW-GLE	BN	Meet bnsf 3775, Siding, metro
341	MKE	51	ENG	48	ENG	48	CHI-CHI	AM	Set out defective locomotive 517
351	CHI	23	DSR	30	DMW	12	XMC-XPI	NS	Waiting for MW clearance FORM Y. CD 482.4-486.0, Control Point, 482
353	CHI	36	DSR	28	SYS	18	HMI-XTF	NS	PTC problem or failure (cause unknown)
364	PTH	47	SVS	53	SVS	33	CHI-CHI	AM	
365	CHI	40	DMW	46	DMW	24	LNS-BTL	CC	Amtrak encountered a yellow red board mp 213.5 w/o corresponding GBO going restricted speed. Foreman J. Smith, Milepost, 213.5, 206
370	GRR	55	SYS	53	SYS	53	CHI-CHI	AM	Crew rest Other, CHI
371	CHI	199	TRS	126	TRS	126	SJM-XPI	CS	Vehicle strike Milepost, 109.1, 109.1
581	LAX	20	CTI	18	CTI	11	OLT-SOL	SN	Meet coaster, Control Point, miramar

Amtrak Endpoint OTP Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
584	SAN	36	CTI	26	PTI	18	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
595	LAX	33	FTI	18	FTI	13	OSD-X98	SN	Meet Control Point, song, bnsf 5894
702	BFD	20	DSR	28	DSR	18	XSK-MOD	BN	Per bulletin Milepost, 1107.0, 1102.5, 15, MT
710	BFD	47	PTI	36	PTI	20	ACA-SKN	BN	Meet 711, Control Point, Holt
711	OKJ	28	DCS	27	DCS	21	MOD-SKN	BN	Issue with automatic road crossing protection Box 1, Other, 1120.37, Other, 1120.45, Other, 1120.83, Other, 1120.98, Other, 1121.12, Other, 1121.12
713	EMY	45	PTI	22	PTI	15	HNF-FNO	BN	Meet AMTK 702, Control Point, Sunmaid
715	OKJ	54	PTI	44	PTI	22	HNF-FNO	BN	Meet Waited to enter station, amtrak 710, Control Point, calwa crossing
716	BFD	41	SVS	38	SVS	38	OKJ-OKJ	UP	Routine inspections Lost time on initial departure. Late departure leaving the yard., Other, oak maintenance facility
717	OKJ	16	PTI	24	DCS	13	MOD-SKN	BN	Restrictive signal(s) from known wayside signal failure Stop, Control Point, keddie junction, Control Point, up crossing
719	OKJ	25	FTI	32	FTI	17	SKN-ACA	BN	Freight doing Switch moves at Pittsburgh. 763, Control Point, W Sando
2	NOL	57	FTI	209	FTI	128	XKY-XKG	UP	Follow Disabled freight we stopped at mp 176. Freight Went into emergency started moving and stopped again at mp 172 for over an hour due to brake issues. Then Followed into kingsbury., up 7731, Siding, noltes, Control Point, kingsbury
21	SAS	No OS Rpt	FTI	296	FTI	182	LRK-MVN	UP	Broken fright up 8836, up 6286, Siding, traskwood
302	CHI	17	FTI	23	CTI	12	JOL-JOL	UP	Cross Traffic metra, Control Point, 37
305	STL	125	ENG	130	ENG	130	CHI-CHI	AM	Set out defective locomotive Engine issues, ID4608
307	STL	36	PTI	29	PTI	29	JOL-DWT	UP	Meet 318, Control Point, 45
380	CHI	17	DMW	11	DMW	11	KEE-PCT	BN	Waiting for MW clearance Other, MP 125.0
390	CHI	26	SYS	22	SYS	22	CDL-CDL	CC	Other late crew Late call for crew on duty at 07:22 am
392	CHI	62	CAR	46	CAR	46	DQN-CEN	CC	HI/LOW 35004, 35002, Stopped to inspect
311	KCY	23	PTI	23	PTI	23	JEF-SED	UP	Meet Daily delay waiting on late 318, Amtk 318, Siding, Shell

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 8/18/2026

26-FOI-00671 00000008691 "UNCLASSIFIED" 9/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
316	STL	24	DSR	27	FTI	9	KCY-XRC	UP	Cross Traffic UP 1234, Control Point, UPRR Interlocker
319	KCY	18	DSR	23	DTR	12	XWR-STL	TR	Traveled via Highline Highline from WR Tower to St. Louis, Control Point, WR Tower, XWR, STL
1333	MSP	62	CAR	29	CAR	29	CHI-CHI	AM	MU CABLE issues, pulled cable and AC riding rear engine. 34134

Amtrak Initial Terminal Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/18/2026

Terminal	Train	Date	Late	Delay	Cause
BON	681	08/18	(Trn Cxld)		Disabled Freight Train
BOS	177	08/18	23	23	PTC - On Board Cab Signal or PTC Failure, 670 EX ES, Late release from the yard, issues with ACSES on unit 670, able to resolve before being released
BOS	2165	08/18	12	12	Water, commissary, toilet/trash dumping, Sent to the yard for water
BRK	682	08/18	7	4	Restrictive signal(s) from unknown cause Could not get the signal to come in, Stop, Control Point, Brunswick
BRK	682	08/18	7	3	Inability to contact dispatcher Other, Brunswick
CLT	72	08/18	25	25	PTC- Unplanned PTC system /server outage Other, CLT
CLT	74	08/18	17	17	Service, turn, or wye train 73
HAR	646	08/18	23	23	Undesired emergency application, 662 EX ES, PANTOGRAPH DROPPED TWICE SWAPPED EQUIPMENT WITH 648
LOR	53	08/18	40	25	Failure of diesel engine Had to add yard Diesel #511 as trail engine due to engine 364 fuel leak issue., 364
LOR	53	08/18	40	15	DRUMMAC late loading automobiles
MIA	40	08/18	37	37	Insect found in sleeper 62007, The 10 car
NPN	186	08/18	1		
NYP	19	08/18	74	74	Other electrical failure, 630, LATE F/SSYD SHOPPED ENG.630 A/C CHIPPED CARBON STRIP SUBBED ENG.623
NYP	43	08/18	39	39	Other electrical failure, 607, LATE F/SSYD SHOPPED ENG.607 A/C CHIPPED CARBON STRIP SUBBED ENG.632
NYP	69	08/18	23	23	Service, turn, or wye train, 230, LATE TURN OFF AM230
NYP	89	08/18	10	10	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD BY CATERING.
NYP	97	08/18	24	24	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	113	08/18	9	9	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	193	08/18	5	5	Unrecoverable penalty (PCS), 629 EX ES, LATE F/SSYD A/C PENALTY ON ENG.629
NYP	237	08/18	31	31	Service, turn, or wye train, 284, LATE TURN OFF AM234
NYP	245	08/18	23	23	Service, turn, or wye train, 68
PHL	151	08/18	1	1	Wait for scheduled departure time
PHL	190	08/18	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM THE YARD
POR	684	08/18	14	14	Waiting for Bus from Brunswick and Freeport due to track work

Amtrak Initial Terminal Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/18/2026

Terminal	Train	Date	Late	Delay	Cause
RGH	73	08/18	60	60	PTC- Unplanned PTC system /server outage CSX had unplanned PTC outage; unable to proceed from initial terminal., Milepost w/Letters, S156.0, S156.0
SFA	52	08/18	25	25	Late loading of vehicles by drummac Control Point, sanford
WAS	184	08/18	10	10	Injured or sick passenger, PAX FELL WHILE BOARDING THE TRAIN REQUIRED MEDICAL ASSISTANCE
WAS	2112	08/18	9	5	Set out defective locomotive, 2017 LH LP, 50% traction loss
WAS	2112	08/18	9	4	Door, 3530 LH LC
WAS	2120	08/18	3	3	Door, N/A, BLUE FLAG LEFT
CDL	390	08/18	22	22	Other late crew Late call for crew on duty at 07:22 am
CHI	3	08/18	53	53	Mechanical clearance
CHI	5	08/18	2	2	Non working PA. Switched out box. Still not working. Repeat issue 32094
CHI	7	08/18	185	185	Adding an engine 176
CHI	21	08/18	252	252	Set out defective car 37009, HVAC
CHI	41	08/18	104	104	Service, turn, or wye train 40
CHI	48	08/18	91	91	Equipment Adjustments Other, Chicago
CHI	50	08/18	48	48	Water, commissary, toilet/trash dumping
CHI	59	08/18	82	82	Unknown defect 34090
CHI	305	08/18	130	130	Set out defective locomotive Engine issues, ID4608
CHI	307	08/18	24	24	Mechanical working on engine in the station ID4629
CHI	341	08/18	48	48	Set out defective locomotive 517
CHI	364	08/18	33	33	
CHI	370	08/18	53	53	Crew rest Other, CHI
CHI	1333	08/18	29	29	MU CABLE issues, pulled cable and AC riding rear engine. 34134
BFD	703	08/18	18	18	Hold for thruway bus
BFD	719	08/18	2	2	Passenger frantically waving next the train.
GTA	782	08/18	5	5	Meet Waited for 14 to clear MT and we waited in the ellwood siding., 14, Control Point, 358
OKJ	532	08/18	7	7	Chiller in caffe needed to be replaced C8802
OKJ	536	08/18	8	8	Meet Left yard behind 716 waited for 716 to leave station before 541 could enter, 716, 541, Other, oakland jack london
OKJ	540	08/18	6	6	Meet 543, Control Point, ni007
OKJ	714	08/18	11	11	Routine inspections

Amtrak Initial Terminal Details

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/18/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	716	08/18	38	38	Routine inspections Lost time on initial departure. Late departure leaving the yard., Other, oak maintenance facility
OKJ	718	08/18	13	13	Oil spill in engine room C2005
PDX	11	08/18	60	55	Bus from Seattle
SAC	539	08/18	3	3	No working wch lifts in cars 8015, 8022, and 6961. Got the ramp out of the diner to use car 4. Car 2 is a bike car. Could not accommodate both pax needing the lift. C8015, 13 minutes total to get 2 pax on board the train. Also making them walk multiple car lengths to accommodate them.
SAN	573	08/18	2	2	Loading problem C2116
SAN	595	08/18	3	3	Service, turn, or wye train 584
SJC	528	08/18	27	27	Due to vehicle strike involving 521 equipment, Inbound equipment for 528 arrived as 523. 523, Due to vehicle strike involving 521 equipment, Inbound equipment for 528 arrived as 523
SJC	538	08/18	14	14	PTC- IETMS recycle breaker to clear fault C8302
SJC	542	08/18	1	1	Door No door light, C6963
VAN	506	08/18	2	2	Hold for thruway bus

Eastern Region

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.2	94.8	342	1
CDOT	95.0	100.0	88.4	92.4	20	0
MARC	95.0	84.5	83.8	90.2	58	9
SEPTA	95.0	96.7	95.1	91.5	214	7
NJT-NED	95.0	90.1	91.6	88.6	353	35
NJT-SED	95.0	100.0	99.1	97.2	12	0

Operating Highlights

Train 68(18) and 69(18) - South of Montreal Station, Longueuil, QC - Weather

19AUG26: Due to excessive heat, speed restrictions were imposed on the CN Rouses Point Subdivision, impacting Adirondack Service. Trains 68(18) and 69(18) incurred delay.

Train	Delay	Comment
68(18)	30"	
69(18)	30"	

Train 175(18) - East of Stamford, CT - Commuter Train Interference

19AUG26: Train 175(18) was delayed on the Metro North New Haven Line between MP 56.5 and MP 32.9 due to following Metro North train travel west.

Train	Delay	Comment
175(18)	48"	

Train 40(17) - South of Connellsville, PA - Freight Train Interference

19AUG26: Train 40(17) was delayed on the CSX Keystone Subdivision at MP 251.8 due to meeting CSX Train I018-18.

Train	Delay	Comment
40(17)	44"	

Train 192(18) - West of New York Penn Station - Commuter Train Problems

18AUG26: Train 192(18) was delayed in the South Tube at MP 1.6 due to New Jersey Transit Train 3984 becoming disabled at the mouth of the tunnel. A code 500 was declared. PSCC dispatched Engine 611 to rescue the disabled set. Once the rescue engine coupled to the disabled set and pulled it into station track 12, Train 192(18) was cleared to proceed into the station.

Train	Delay	Comment
192(18)	50"	

Train 41(16) Tampa, FL - PTC Issues/Engine Failure

18AUG26: Train 41(16) with E/330, E/352 and 15 cars was delayed on CSX Tampa Terminal A at MP 881.9 due to being unable to initialize PTC. The crew was trouble shooting with CNOC mechanical and able to initialize.

Train	Delay	Comment
41(16)	1'25"	

Train 52(18) Sanford, FL - Servicing

18AUG26: Train 52(18) with E/380, E/354 was delayed departing Sanford due to Drummac late loading cars.

Train	Delay	Comment
52(18)	25"	

Train 53(18) Lorton, VA - Servicing

18AUG26: Train 53(18) was delayed departing Lorton due to adding E/511.

Train	Delay	Comment
53(18)	40"	

Train 68(18) North of St-Lambert, QC -CN Heat Orders/ Weather

18AUG26: Train 68(18) was delayed on the CN Rouses Point subdivision due to Heat Orders from MP 40 to MP 15.0.

Train	Delay	Comment
68(18)	30"	

Train 68(18) South of St-Lambert, QC - Freight Train Interference

18AUG26: Train 68(18) with E/118 and 5 cars was delayed on the CN Rouses Point subdivision due to meeting 323 at MP 27.8/Lacadie siding.

Train	Delay	Comment
68(18)	40"	

Train 64(18) North of Buffalo, NY - Freight Train Interference

18AUG26: Train 64(18) with E/131 and 5 cars was delayed on the CSX Buffalo Terminal subdivision due to following multiple CSX freights and held at MP 425 and MP 406. Train 64(18) was further delayed on the CSX North of Rochester due to meeting CSX 169 at CP 313 and another freight at CP 293.

Train	Delay	Comment
64(18)	48"	CP 313/293
64(18)	45"	MP 425/406

Train 95(18) Newark, NJ - Engine Failure

18AUG26: Train 95(18) with E/611 reported that they had cut out cab signals, PTC and Acces on the New York to Philadelphia main line at MP 8.8/Newark. The were able to continue at restricted speed. The train was met at Philadelphia and capped with E/665.

Train	Delay	Comment
95(18)	25"	adding ENG PHL
95(18)	59"	NWK-PHL

Train 43(18) New York, NY - Engine Failure

18AUG26: Train 43(18) was delayed departing New York due to E/607 being shopped for a chipped carbon strip and replaced with E/632.

Train	Delay	Comment
43(18)	39"	

Train 40(18) Miami, FL - Shopped Sleeper /Servicing

18AUG26: Train 40(18) with E/339, E/356 and 10 cars was delayed departing Miami due to shopping sleeper C/62040 and was replaced with C/62039.

Train	Delay	Comment
40(18)	37"	

CSX Heat Orders - Weather

18AUG26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Peninsula, Richmond Terminal, North End, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, Tampa Terminal and NO&M.

Train	Delay	Comment
52(18)	13"	
53(18)	03"	
98(18)	24"	
40(18)	45"	
90(18)	20"	
79(18)	25"	
186(18)	13"	
138(18)	04"	
89(18)	24"	
80(18)	12"	
97(17)	39"	

Train 600(18) Middletown, PA - Engine Failure

18AUG26: Train 600(18) with E/604, CC/9638 and 4 cars was delayed at MP 95.3/Middletown on the Harrisburg to Philadelphia main line due to alertor failure that put the train into penalty. The engineer cut out the alertor and moved the brakeman up to the headend and proceeded east.

Train	Delay	Comment
600(18)	31"	

Train 680(17) - Biddleford, ME - Freight Train Interference

18AUG26: Train 680(18) was delayed at Portland Station/MP 1.8 on the CSX Portland Subdivision due to a disabled freight train. CSX Train M426-17 broke a knuckle at MP 26 on the single main.

UPDATE As of 722A-ET, Train 680(18) was terminated at Portland and customers were re-accommodated to train 682(18). Train 681(18) was cancelled in its entirety and customers were re-accommodated to 683(18).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
680(17)		TERM POR
681(18)		CANCELLED
682(18)	1'01"	POR

Metro North Track Outage - Croton, NY - M of W Work

15AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
235(15)	43"	
236(15)	10"	
280(15)	16"	
230(15)	02"	
233(15)	50"	
290(15)	24"	
238(15)	12"	
239(15)	29"	
49(15)	43"	
48(14)	1'00"	
1233(16)	1'08"	
240(16)	31"	
291(16)	25"	late turn off 240(16)
1246(16)	1'11"	LATE TURN OFF 1233(16)

Downeaster Service - CSX Trackwork - M of W Work - 8/17 - 8/20

28JUL26: CSX Portland, ME is working between Boston North station and Brunswick, ME MP BRU 5.0 to MP BRU 0.5 from Monday, August 17, 2026 to Thursday, August 20, 2026 from 7A-3P. The following service adjustments have been made:

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound:

- Train 681 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.
- Train 683 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 684 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 686 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 688 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3683 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, and 3688 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100151.0835

Train	Delay	Comment
686(17)	32"	holding for buses por

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No Data

Eastern Region

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Train 307(18) North of St. Louis, MO - Freight Train Interference

19AUG26: Train 307(18) was delayed on the UPRR Springfield subdivision four miles north of St. Louis at Q Tower/MP 281.0 due to being held account of a work train stalled on the TRRA MacArthur Bridge/MP 1.0.

Train	Delay	Comment
307(18)	55"	

Train 41(18) West of South Bend, IN - Car Failure

18AUG26: Train 41(18) with E/140-113, nine cars, and 182 customers was delayed on the NS Chicago district 23 miles west of South Bend due to air hose separation between C/62013 and C/62501. The crew re-attached, performed the necessary tests, and continued to South Bend.

19AUG26: Train 41(18) with E/140-113, nine cars, and 159 customers was delayed on the NS Cleveland Terminal district one mile west of Elyria at MP 207.6 due to air hose separation between the aforementioned cars. The crew re-attached, performed the necessary tests, and continued to Elyria.

Train	Delay	Comment
41(18)	34"	W/SOB
41(18)	45"	W/ELY

Train 5(18) West of Creston, IA - Freight Train Interference

18AUG26: Train 5(18) with 164 customers was delayed 36 miles west of Creston on the BNSF Creston subdivision at MP 428.7 due to C-ATMCNM0-22 with a right end drawbar and setting out a car between CP4367/MP 436.7 and CP4289/MP 428.9.

Train	Delay	Comment
5(18)	1'17"	

Train 11(17) San Luis Obispo, CA - Late Operation & Calendar Day Inspections

18AUG26: Train 11(17), operating with locomotives UP4292, E/301, and E/313 and nine cars, experienced delays throughout its trip due to a series of operational and mechanical events. The train originated late while awaiting inbound bus connections and servicing activities. Additionally, locomotive UP4292 was added to the consist after locomotive E/313 was removed from service in Portland, OR, due to an unrepairable oil leak. Further delays were incurred at Klamath Falls, OR, while law enforcement responded to remove an unruly customer from the train. These delays, combined with those accumulated earlier in the trip, resulted in Train 11(17) arriving at San Luis Obispo, CA, behind schedule. Upon arrival, required calendar day inspections were performed on the equipment before the train was released to continue its trip.

Train	Delay	Comment
11(17)	1'14"	SLO Inspections
11(17)	1'08"	SAC-SLO engine related
11(17)	42"	PDX-KFS engine related
11(17)	05"	SLO-LAX op with eng

Train 6(18) East of Winnemucca, NV - Heat Orders

18AUG26: Train 6(18), 26-FDI-00971 00000008651 UNCLASSIFIED, 9/2/2026 delayed west of Winnemucca, NV, on the Union Pacific Elko Subdivision due to heat-order restrictions. The train operated at reduced speeds between MP 535.70 and Whirlwind (MP 612.0) and then continued under heat-order restrictions between Whirlwind and Carlin (MP 646.02) in accordance with temporary operating restrictions implemented due to high rail temperatures.

Train	Delay	Comment
6(18)	30"	

Train 48/448(18) Chicago, IL - Initial Terminal Delay

18AUG26: Train 48/448(18) with 249 customers was delayed departing Chicago due to the late turn of equipment from 40(16) that arrived Chicago at 439PM-CT, 7 hours, and 54 minutes late, which resulted in a late release of equipment for train 48/448(18). Once the equipment was made up, released, and set in the station, the customers were welcomed aboard, and 48/448(18) departed Chicago at 1101PM-CT, 1 hour, and 31 minutes late.

Train	Delay	Comment
48/448(18)	1'31"	

Train 4(18) East of Riverside-Downtown, CA - Debris Strike

18AUG26: Train 4(18), operating with locomotives E/79 and E/30, nine cars, and 126 customers onboard, was delayed east of Riverside, CA, at MP 5.1 on the BNSF San Bernardino Subdivision after striking a blue plastic trash can on the right-of-way. The impact parted several air hoses, requiring the crew to stop and inspect the train. The crew resecured the affected air hoses and subsequently rebooted the Positive Train Control (PTC) system. Once the necessary repairs and system recovery procedures were completed, Train 4(18) resumed its trip.

Train	Delay	Comment
4(18)	50"	

Train 3(18) East of La Plata, MO - Freight Train Interference

18AUG26: Train 3(18) with 187 customers was delayed on the BNSF Marcelline subdivision due to V-FTMPEA1-18 stopped at Baring/MP 292.4 with a locked axle that caused single tracking through the area. As a result, train 3(18) followed H-MTWKCK1-17 and G-HAGJOE9-17 between MP 268.1 and La Plata/MP 312.7.

Train	Delay	Comment
3(18)	32"	

Train 341(18) Chicago, IL - Initial Terminal Delay

18AUG26: Train 341(18) with E/44, three cars, E/517, and 144 customers was delayed departing Chicago due to replacing E/517 with E/381. Once the engine swap was complete, and the necessary tests were performed, 341(18) departed Chicago at 853PM-CT, 48 minutes late.

Train	Delay	Comment
341(18)	48"	

Train 58(18) South of Greenwood, MS - System

18AUG26: Train 58(18) with E/108, five cars, and 115 customers was delayed departing the CN Yazoo subdivision five miles south of Greenwood at MP 127.5 due to holding for an Amtrak relief engineer. Once the engineer arrived, boarded, and briefed, 58(18) continued to Greenwood. The train was further delayed with 115 customers eight miles south of Marks at MP 75.5 due to holding for an Amtrak relief conductor. Once the conductor arrived, boarded, and briefed, 58(18) continued to Marks.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(18)	58"	S/GWD - relief engineer
58(18)	1'44"	S/MKS - relief conductor

Train 41(18) Chicago, IL - Initial Terminal Delay

18AUG26: Train 41(18) with E/140-113, nine cars, and 182 customers was delayed departing Chicago due to a late release account E/140 being added from train 40(16), which arrived Chicago at 439PM-CT, 7 hours, and 54 minutes late. Once the equipment was released and set in the station, 41(18) departed Chicago at 824PM-CT, 1 hour, and 44 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(18)	1'44"	

Train 59(18) Chicago, IL - Initial Terminal Delay

18AUG26: Train 59(18) with 172 customers was delayed departing Chicago due to sleeper C/32106 held out for preventative maintenance as of 444PM-CT and replaced with C/32067. Once the train was made up, released, and set in the station, the customers were welcomed aboard, and 59(18) departed Chicago at 727PM-CT, 1 hour, and 22 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(18)	1'22"	

Train 50(18) Chicago, IL - Initial Terminal Delay

18AUG26: Train 50(18) with E/751-518, five cars, E/127, six cars, and 126 customers was delayed departing Chicago due to a late shove to the station. The equipment was released at 500PM-CT and shoved to the station at 550PM-CT. Once the equipment was set in the station and the customers were welcomed aboard, 50(18) departed Chicago at 643PM-CT, 48 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(18)	48"	

Train 392(18) North of Du Quoin, IL - Car Failure

18AUG26: Train 392(18) with E/ID4601, seven cars, and 24 customers was delayed on the CN Centralia subdivision 15 miles north of Du Quoin at Bois/MP 273.8 due to the crew reporting hi-low issues between C/35002-34004 and stopping to inspect. After consulting with mechanical, the crew was cleared to continue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
392(18)	46"	

Train 716(18) Oakland, CA - Late Yard Release

18AUG26: Train 716(18) with E/ID4629, five cars, and locomotive C2001, was delayed departing Oakland Jack London Square, CA, due to a late yard release. The delay occurred after CC/90278 was added to the consist in place of locomotive C2009. Once the equipment change was completed and the train was released from the yard, Train 716(18) departed and continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(18)	38"	

Train 305(18) Chicago, IL - Engine Failure

18AUG26: Train 305(18) with E/ID4629, five cars, and 119 customers was delayed departing Chicago due to E/ID4629 with a coolant leak and being assessed by mechanical in the yard. The decision was made to swap 307(18) equipment with 305(18) equipment to prevent further delay. After swapping equipment, train 307(18) equipment arrived at Union Station at 640PM-CT and was to be worked up at the station. Train 305(18) equipment arrived at Union Station at 703PM-CT. Train 305(18) departed Chicago at 730PM-CT, 2 hours, and 10 minutes late. Train 307(18) departed Chicago with 231 customers at 734PM-CT, 24 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
305(18)	2'10"	
307(18)	24"	

Train 7/27(17) East of Malta, MT - Passenger Train Interference

18AUG26: Train 7/27(17), carrying 231 customers onboard, was delayed east of Malta, MT, while holding at Saco Siding (MP 318.2) on the BNSF Milk River Subdivision to meet Train 8/28(17).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(18)	34"	

Train 19(17) North of Anniston, AL - Freight Train Interference

18AUG26: Train 19(17) was delayed at Heflin/MP716.3, 19 miles north of Anniston, AL, on the NS East End District, meeting NS156.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(17)	32"	

Train 517(18) Seattle, WA - Fueling

18AUG26: Train 517(18), carrying 96 customers onboard, was delayed after departing Seattle, WA, on the BNSF Seattle subdivision. The train operated to Seattle Yard to fuel E/186. Once fueling was completed, the train departed and continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
517(18)	43"	

Train 371(18) West of St. Joseph-Benton Harbor, MI - Injured or Sick Passenger or Employee

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

18AUG26: Train 371(18) was delayed at MP105.7, 17 miles west of St. Joseph, MI, on the CSX Grand Rapids Subdivision, due to EMS responding for a passenger medical emergency. EMS transported the passenger to an area medical facility.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
371(18)	30"	

Train 7/27(18) Late Departure Chicago, IL - System

18AUG26: Train 7/27(18) with E/164-E/176, 10 cars, and 262 customers was delayed departing Chicago due to the late release of locomotives. E/164 came off train 58(17), which arrived Chicago at 1058AM-CT, 3 hours, and 43 minutes late. The trail locomotive E/176 came from the shop and was released at 139PM-CT. Once the equipment was made up, released, and set in the station, the customers were welcomed aboard, and 7/27(18) departed Chicago at 610PM-CT, 3 hours, and 5 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(18)	3'05"	

Train 503(18) North of Salem, OR - M of W Work

18AUG26: Train 503(18), carrying 61 customers, was delayed approximately two miles north of Salem, OR, on the BNSF Brooklyn Subdivision. At MP 720.5, the crew stopped due to a Maintenance-of-Way out-of-service restriction.

The UPRR dispatcher was unable to establish contact with the contractor responsible for the protected work area, resulting in additional delay. After the contractor cleared the limits and authority was released, Train 503(18) resumed normal operations and continued its route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
503(18)	57"	

Train 27(17) Spokane, WA - Engine Failure

18AUG26: Train 27(17), led by Engine 196, was terminated at Spokane, WA, on the BNSF Spokane Subdivision due to an air compressor fault on the locomotive. As a result, the train was unable to continue operating under its own power to Portland, OR.

Alternate transportation was secured for the 62 customers onboard to complete their journey. The equipment from Train 27(17) subsequently deadheaded in line with Train 7(17) to Seattle, WA, where it was scheduled for repair, servicing, and inspection.

WBS#: B.TR.100150.7050

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
27(17)	TERM SPK	
28(19)	ORIG SPK	

Train 21(17) Dallas, TX - Police Related

18AUG26: TRE placed a hold on 26-FBI-006711 0000008631 "UNCLASSIFIED" 9/2/2026 at Dallas/MP634, 26 miles west of Dallas, TX, on the TRE Mainline, at approximately 330PM-CT due to a right of way fire. The brush fire was reported 95% contained, with no estimate on the duration of the hold. Train 21(17), with 59 customers, held at Dallas, TX, for open route ahead. Once the hold was released and the route was cleared, 21(17) departed Dallas at 608PM-CT, 5 hours, and 30 minutes late. Train 22(18)/422(16) was also delayed at Fort Worth holding for an available route for this reason.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(17)	2'07"	
22(18)/422(16)	20"	

Train 364(18) Chicago, IL - Initial Terminal Delay

18AUG26: Train 364(18) with 227 customers was delayed departing Chicago due to a late release and terminal congestion. Once the equipment was released and set in the station, the customers were welcomed aboard and 364(18) departed Chicago at 433PM-CT, 33 minutes late. After departing, the crew stopped at CP Lumber/MP 1.4 to perform a departure test.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(18)	33"	CHI
364(18)	20"	CP Lumber

Train 22(18)/422(16) North of McGregor, TX - Engine Failure

18AUG26: Train 22(18)/422(16), E/315-E/198 & 8 cars, with 139 customers, was delayed at MP270.1, 27 miles north of McGregor, TX, on the BNSF Fort Worth Subdivision, due to lead E/315 lost HEP and had IO 47 faults. The crew contacted mechanical to troubleshoot. After recycling E/315 issues were still unresolved. The crew was able to restore HEP off the trail unit, E/198. HEP was down approximately fifteen minutes. The crew continued to work with mechanical in an attempt to restore tractive power on E/315 however was unable to do so. Due to the faults on E/315 the unit was unable to be set up as a control stand. BNSF freight in the siding at MP270.1, cut off E/BN7399 to assist in setting out E/315 in track 2017 at Clifton/MP270.8. Train 22(18)/422(16) then proceeded north with E/198 only. Train 22(18)/422(16) operated single unit E/198 north to Mesquite/MP203, 11 miles east of Dallas, TX, on the UPRR Mineola Subdivision, and was further delayed adding UPRR E/UP9804 ahead. Amtrak mechanical and a road foreman were on scene to assist in adding the freight locomotive.

WBS#: B.TR.100150.7049

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(18)/422(16)	2'34"	N/MCG, s/o E/315
22(18)/422(16)	1'25"	E/DAL, add UP E/UP9804
22(18)/422(16)	13"	DAL-MHL, operating with freight

Train 3(18) Late Departure Chicago, IL - Engine Failure

18AUG26: Train 3(18), E/167-E/53 & 9 cars, with 178 customers, was delayed departing Chicago, IL, due to engine issues reported just prior to scheduled departure. Mechanical responded to CUS and corrected an engine setup issue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(18)	53"	

Train 21/421(18) Late Departure Chicago, IL - Car Failure

18AUG26: Train 21/421(18) was delayed at Chicago, IL, due to diner C/37009 shopped at 1213PM-CT for HVAC issues and replaced with C/37014. Once the train was made up, released, and set in the station, the customers were welcomed aboard, and 21/421(18) departed Chicago at 622PM-CT, 4 hours, and 12 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(18)	4'12"	

Train 22(17) North of St. Louis, MO - Freight Train Interference

18AUG26: Train 22(17) was delayed at Q Tower/MP281, 2 miles north of St. Louis, MO, on the UPRR Springfield Subdivision, meeting UP 2599.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(17)	30"	

Train 371(18) West of St. Joseph-Benton Harbor, MI - Struck Occupied Vehicle

18AUG26: 955AM-ET, Train 371(18), E/IDTX4631 & 4 cars, with 203 customers, struck an occupied vehicle at East Road crossing/MP109.1, (DOT 234865C) 21 miles west of St. Joseph, MI, Berrien County, on the CSX Grand Rapids Subdivision. There were no reported injuries to passengers or crew. There was one fatality reported in the vehicle. Train 371(18) maintained HEP and there were no exceptions to equipment reported. Local authorities, Amtrak road foreman and Amtrak PD responded to the scene. The crew worked the remainder of trip to Chicago once train was released. Train 371(18) was delayed holding for completion of investigation by local authorities and for the recrew to arrive. A recrew deadheaded from Grand Rapids, MI to Chicago to work the crew turn of Train 370(18) and was placed on a respite until 645PM-CT. Once the crew signed up, briefed, and boarded the train, 370(18) departed Chicago at 723PM-CT, 53 minutes late.

WBS#: B.TR.100150.7047

National Response Center Number: 1471119

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
371(18)	2'06"	
370(18)	53"	CHI - crew rest

Train 521(18) South Oakland, CA - Trespasser Incident

18AUG26: At approximately 6:20 PM, Train 521(18), led by JPBX920 with five cars and 60 passengers onboard, struck an occupied vehicle south of Oakland, CA at Oak St crossing/MP 10.1(DOT749591D) on the UPRR Niles Subdivision. The incident resulted in a confirmed fatality. No injuries were reported among passengers or crew.

The crew requested relief following the incident. UPRR responders and Amtrak Road Foremen and Amtrak Police responded to the scene. Weather conditions at the time were reported as 59°F and cloudy. Local authorities investigated the incident as a traffic accident.

Damage was reported to the fireman's side ladder on JPBX920. A relief crew was scheduled to arrive at approximately 8:00 a.m. PT. ACE offered mutual aid transportation for passengers traveling between Fremont (FMT) and San Jose (SJC).

All passengers from Train 521(18) were transferred to Train 523(18) to continue their travel south. Upon completion of the coroner's investigation, the scene was released. Train 521(18)'s equipment subsequently deadheaded to San Jose, CA, for its adjusted turn.

Service recovery was offered to passengers on Trains 521(18), 523(18), and 524(18).

B.TR.100150.7048

NRC# 1471118

CA# 26-4176

WBS#: B.TR.100150.7048

Train	Delay	Comment
528(18)	27"	turn off 521(18)
523(18)	21"	PSGR transfer
521(18)	Term OKJ	
527(18)	8"	
524(18)	57"	

CSX/NS Systemwide PTC Outage - Delays

18AUG26: 807AM-ET CSX reported an unplanned systemwide PTC outage. At 930A-ET, NS reported an unplanned systemwide PTC outage. Both the CSX and NS were able to identify the issues and both were back at 1046A-ET. Several Trains were delayed due to operating restricted speed due to PTC being cut out and other trains were delayed at initial terminals.

CSX reported that the cause was found to be a back office server issue and they were able to restore their system as of 1035A-ET.

Train	Delay	Comment
98(18)	42"	
371(18)	48"	
73(18)	1'00"	
72(18)	25"	
23(18)	16"	
24(18)	1'24"	
280(18)	37"	
90(18)	28"	
40(17)	31"	
53(17)	1'39"	
41(16)	1'16"	
284(18)	30"	
48(17)	25"	

Train 2(16) East San Antonio, TX - Freight Train Interference

18AUG26: Train 2(16) was delayed at MP171, 37 miles east of San Antonio, TX, on the UPRR Glidden Subdivision, due to MSALI-17 (UP 7731) stopped in emergency ahead at MP174. UPRR carman responded to assist. After UP 7731 replaced a bad order air hose the crew reported issues with the DPU unit. Train 2(16) was delayed holding for UP 7731 to resolve issues and then further delayed following UP 7731 to Kingsbury/MP163.

Train	Delay	Comment
2(16)	2'08"	

Train 5(16) East of Elko, NV - Freight Train Interference

18AUG26: Train 5(16), carrying 138 customers, was delayed east of Elko, NV, on the UPRR Lakeside Subdivision. To mitigate the delay, the train was routed through Elko Yard with the intent of avoiding UP7988. The strategy was unsuccessful, as Train 5(16) subsequently followed UP7988 after departing the yard, resulting in additional delay to the train's operation.

Train	Delay	Comment
5(16)	27"	Elko yard
5(16)	27"	UP7988

Train 21(17) South of Little Rock, AR - Freight Train Interference

18AUG26: Train 21(17), with 72 customers, was delayed at Traskwood/MP378.2, 31 miles south of Little Rock, AR, on the UPRR Little Rock Subdivision, due to MLDNL-16 (UP 8836) in emergency ahead on the Main at Gifford/MP383.4, with MBZCN-16 (UP 6286) in behind. UPRR crew on UP 8836 expired on hours of service prior to operating in the clear. A UPRR manager who was on site assisting freight responded to North Little Rock and transported recrew back to MP383.4. transported a recrew to location. UPRR reported the crew on UP 6286 was on short time and it was also necessary to recrew UP 6286. Train 21(17) was delayed holding for open route ahead.

Train	Delay	Comment
21(17)	3'02"	

Amtrak Crescent Service - Norfolk Southern Heat Orders

15AUG26: Norfolk Southern issued heat orders on the NO&NE Subdivision beginning 45 miles north of Picayune, MS (MP149.0), from MP104 to MP0.5. . The heat orders were in place from 1:00PM-CT to 6:00PM-CT and required operating speeds to be reduced to 40MPH through the affected areas, causing delays to Trains 19(14) and 20(15). Additional heat orders were in effect on the NSRR AGS South Subdivision beginning 2.3 miles north of Meridian, MS (MP295.0), from MP292.7 to MP143.5.

16AUG26: NS heat orders remained in effect between 1:00PM-CT and 6:00PM-CT on the AGS South Subdivision between Birmingham, AL/MP143.5 and Meridian, MS/MP295. Trains 19(15) and 20(16) were delayed operating through the affected areas.

17AUG26: NS heat orders remained in effect on the AGS South Subdivision between Birmingham, AL and Meridian, MS. Trains 19(16) and 20(17) were delayed operating through the affected areas.

Train	Delay	Comment
19(14)	2'30"	
20(15)	1'25"	
19(15)	2'02"	
20(16)	1'35"	
20(17)	1'47"	
19(16)	1'55"	

CN Blanket Heat Orders - City of New Orleans / Illini / Saluki Service

12AUG26: Canadian National issued blanket heat orders for the entire route from Chicago, IL and New Orleans, LA starting at 9:00AM-CT on 12AUG to remain in effect until temperatures decline. Expected to remain through the weekend. During this time, the maximum authorized speed was reduced to 15 MPH below timetable speed throughout most of the territory, with additional 40 MPH speed restrictions in designated areas. On the McComb Subdivision, 40 MPH restrictions were in effect between MP731-MP735 and MP823-MP849. On the Yazoo Subdivision, 40 MPH restrictions were in effect between MP15-MP21, MP70-MP71, MP136-MP137, MP172-MP189, and MP210-MP216. The heat orders caused delays to Amtrak's City of New Orleans, Illini, and Saluki Service.

-Train 58(12) had service recovery enacted, with snack packs, bottled water, coffee, hot tea, and juice provided to all coach customers, while all First Class customers were provided breakfast in the dining car.

-Train 59(12) had service recovery enacted, with snack packs and bottled water provided to all coach customers, while First Class customers received their scheduled meal service in the dining car.

16AUG16: Heat orders remained in effect with ongoing delays to City of New Orleans, Illini and Saluki services through the affected areas.

17AUG16: Heat orders remained in effect on the CN Memphis, Shelby, Yazoo and McComb Subdivisions resulting in continued delays to City of New Orleans service through the affected area.

Train	Delay	Comment
58(12)	2'35"	NOL-CHI
390(13)	37"	
391(13)	46"	
392(13)	53"	CDL-CHI
393(13)	49"	CHI-CDL
59(12)	310"	CHI-NOL
391(14)	1'04"	
390(14)	51"	
58(14)	57"	Crew Rest JAN
392(14)	42"	
393(14)	42"	
59(13)	3'32"	CHI-NOL
390(15)	43"	
391(15)	32"	
58(14)	2'44"	NOL-CHI
392(15)	48"	
58(15)	1'54"	NOL-CHI
59(14)	2'24"	CHI-NOL
58(14)	2'49"	NOL-CHI
390(16)	51"	
391(16)	40"	
59(15)	41"	MEM, hold for CN engineer pilot
59(15)	2'16"	CHI-NOL
392(16)	1'10"	
393(16)	35"	
58(16)	1'06"	NOL-FTN
59(16)	1'27"	CHI-NOL
58(17)	57"	NOL-MEM
59(17)	1'11"	MEM-NOL
58(18)	37"	NOL-YAZ

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

UPDATE 07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG.

UPDATE 18AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 28AUG.

and Chicago.

- Train 370(07) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13), with 143 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(14), with 162 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(16), with 151 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(17), with 149 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(20), with 90 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(21), with 155 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(22) cancelled entirely with two alternate buses.
- Train 370(24) cancelled entirely with two alternate buses.
- Train 370(26) cancelled entirely with customer service still sourcing alternate busing.
- Train 371(23) cancelled entirely with two alternate buses.
- Train 371(25) cancelled entirely with two alternate buses.
- Train 371(27) cancelled entirely with three alternate buses.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.
- Train 305(25) cancelled entirely with one alternate bus.
- Train 300(26) cancelled entirely with customer service still sourcing alternate busing.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(15), with 163 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(15), with 108 impacted customers, is cancelled entirely with 3 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(18), with 31 impacted customers, is cancelled entirely with no alternate transportation provided.
- Train 355(18), with 11 impacted customers, is cancelled entirely with no alternate transportation provided.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL and Quincy, IL.

secured between Chicago, IL and Quincy, IL

- Train 382(14), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(17), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21), with 15 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 383(23) cancelled entirely with two alternate buses.
- Train 383(27) cancelled entirely with customer service still sourcing alternate busing.
- Train 380(24) cancelled entirely with customer service still sourcing alternate busing.
- Train 380(28) cancelled entirely with customer service still sourcing alternate busing.

Saluki/Illini Service

- Train 391(12), with 54 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Carbondale, IL.
- Train 392(12), with 45 impacted customers, is cancelled entirely with 1 alternate buses secured between Carbondale, IL and Chicago, IL.
- Train 391(19), with 55 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Carbondale, IL.
- Train 392(19), with 18 impacted customers, is cancelled entirely with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

BNSF Fallbridge Subdivision - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland

- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

13AUG26: Due to the structural integrity of the building and the need for demolition, the service adjustments on the Cascades, Coast Starlight, and the Empire Builder were adjusted through Sunday, August 16th. Multiple trains were delayed holding for bus connections.

15AUG26: Initial plan is to start detonation of the water tower on Monday, August 17th with the demolition of the remaining structure on Tuesday, August 18th. As a result, the following adjustments have been extended through Wednesday, August 19th.

- Train 500 (04-19) Cancelled entirely, no alternate Transportation.
- Train 502 (04-19) Cancelled entirely, with alternate transportation via Bus 3502.
- Train 504 (04-19) Terminated in Portland, OR, with alternate transportation via Bus 3504.
- Train 518 (04-07) Originated in Seattle, WA with alternate bus transportation.
- Train 518 (08-19) Originated in Vancouver, WA with alternate bus transportation via Bus 3518.
- Train 517 (04-19) Terminated in Vancouver, WA, no alternate transportation (04-10); alternate bus transportation via Bus 3517(11-19)
- Train 506 (04-19) Originated in Vancouver, WA, no alternate Transportation (04-10); alternate bus transportation via Bus 3506(11-19)
- Train 508 (04-19) Terminated in Portland, OR with alternate transportation via Bus 3508.
- Train 503 (04-19) Originated in Portland, OR, with alternate transportation via Bus 3503.
- Train 505 (04-07) Cancelled entirely with alternate bus transportation.
- Train 505 (08-19) Terminated in Vancouver, WA, no alternate transportation(04-10); alternate bus transportation via Bus 3505(11-19)
- Train 507 (04-19) Originated in Portland, OR, with alternate transportation via Bus 3507, operating 1 hour earlier at 1:20P-PT.
- Train 509 (04-19) Cancelled entirely, with alternate transportation via Bus 3509.
- Train 511 (04-19) Cancelled entirely, no alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Train 27 (02-17) Will Terminate at Spokane, WA. Alternate Transportation provided.
- Train 28 (04-19) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

- Train 14 (04-11) Terminated in Portland, OR, no alternate transportation provided.
- Train 14 (12-18) Terminated in Portland, OR with alternate transportation secured via Bus 3014.
- Train 11 (05-12) Originated in Portland, OR, no alternate transportation provided.
- Train 11 (13-19) Terminated in Portland, OR with alternate transportation secured via Bus 3011.

Bus to operate earlier 8/11-8/16 - Arrow

Bus 3507 to depart 1 hour earlier at 1:20pm

Train 505 Bus VAN-PDX depart VAN at 12pm

Train 518 bus PDX-VAN depart PDX at 1:30pm

Train 517 bus VAN-PDX depart VAN at 330pm

Train 506 bus PDX-VAN depart PDX at 5:20pm

Train	Delay	26-FC-00000008691 Observation	"UNCLASSIFIED"	9/2/2026
507(02)	1'41"	bus VAN-PDX		
506(02)	Canceled			
508(02)	45"	bus PDX-VAN		
509(02)	77"	couple 509-511(02)		
509(02)	75"	Detour through UP yard		
511(02)	76"	Detour through UP yard		
500(03)	Canceled			
502(03)	Canceled			
511(03)	Canceled			
505(03)	Canceled			
518(03)	Canceled	between SEA-PDX		
507(03)	Canceled	between SEA-PDX		
508(03)	Term PDX			
504(03)	Term PDX			
509(03)	Canceled			
517(03)	Term VAN			
506(03)	Orig VAN			
503(03)	24"	canceled SEA-PDX		
507(03)	1'10"	waiting for bus at PDX		
14(02)	58"	detour		
11(03)	51"	detour		
14(04)	term PDX			
506(04)	1'03"	wait for inbound bus		
518(04)	1'27"	wait for inbound bus		
507(05)	1'09"	PDX- wait for inbound bus		
507(06)	1'06"	PDX- inbound bus		
503(07)	33"	PDX- inbound bus		
507(07)	1'21"	PDX- inbound bus		
503(08)	22"	PDX- inbound buses		
503(09)	28"	bus connections		
518(09)	27"	bus connections		
518(10)	34"	bus connections		
503(10)	45"	bus connections		
503(12)	28"	PDX- inbound bus connections		
517(12)	47"	Fuel in SEA yard due to no Fueling in VAN		
507(12)	1'15"	Connecting Bus		
517(13)	44"	Fuel in SEA Yard		
517(14)	59"	Fuel in SEA Yard		
503(15)	26"	PDX- inbound bus connections		
11(15)	25"	PDX - inbound bus connections		
11(17)	1'04"	PDX - Bus connect, fueling, meet 14		
11(18)	1'00"	PDX - inbound bus connections		
517(18)	43"	Fuel in SEA Yard		
517(16)	31"	Fuel in SEA Yard		

Maintenance of Way Highlights

BNSF Track Work West of Galesburg, IL - Illinois Zephyr/Carl Sandburg Service

19AUG26: BNSF tie gang will perform work at Saluda/MP168, 6 miles west of Galesburg, IL, on the Brookfield Subdivision, on Wednesday August 19th. To accommodate this infrastructure work, Illinois Zephyr/Carl Sandburg service adjusted as follows:

- Train 383(18) terminates at Galesburg, IL, with Bus 3383 as alternate transportation between Galesburg, IL and Quincy, IL.
- Train 380(19) originates at Galesburg, IL, with Bus 5380 as alternate transportation between Quincy, IL and Galesburg. Bus 5380 will operate 1-hour earlier than train schedule.
- Train 382(19) originates at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy and Galesburg. Bus 3382 will operate 1-hour earlier than train schedule.
- Train 381(19) terminates at Galesburg, IL, with Bus 5381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.7043

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
- Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
- Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
- Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.

*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task 26-055 scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No Data

Western Region

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00671

00000008691

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
392 (18)	CDL	391/392(18) b/o 34206 and replaced with 35004, impact -10LY seats, 391 -10LY seats and 392 -7LY seats	passengers are being notified and downgraded	7	35004
391 (18)	CHI	391/392(18) b/o 34206 and replaced with 35004, impact -10LY seats, 391 -10LY seats and 392 -7LY seats	passengers are being notified and downgraded	10	35004
564 (19)	LAX	no bike space or wifi	Passengers notified no bike space no wifi	0	90225
777 (19)	SAN	no bike space or wifi	Passengers notified no bike space no wifi	3	90225

Reverse Consists

Train Number	Station	Reason
113 (18)	NYP	Consist reversed Business class seat orientation may have changed At Rear
190 (18)	PHL	Consist reversed Business class seat orientation may have changed At Front
171 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
125 (18)	SPG	Consist reversed Business class seat orientation may have changed At Front
86 (18)	NPN	Consist reversed Business class seat orientation may have changed At Front
129 (18)	NPN	Consist reversed Business class seat orientation may have changed At Front
84 (18)	WAS	Consist reversed Business class seat orientation may have changed At Front
193 (18)	NYP	Consist reversed Business class seat orientation may have changed At Rear
94 (18)	NFK	Consist reversed Business class seat orientation may have changed At Front
178 (18)	RNK	Consist reversed Business class seat orientation may have changed At Front
95 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
137 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00671	00000008691 "UNCLASSIFIED" 9/2/2026
174 (18)	WAS	Consist reversed Business class seat orientation may have changed At Front	
173 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front	
136 (18)	WAS	Consist reversed Business class seat orientation may have changed At Front	
85 (18)	BOS	Business class change only Business class seating orientation may have changed At Rear	
198 (18)	WAS	Business class change only Business class seating orientation may have changed At Rear	
178 (19)	RNK	Consist reversed Business class seat orientation may have changed At Front	
86 (19)	NPN	Consist reversed Business class seat orientation may have changed At Front	
179 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front	
125 (19)	SPG	Consist reversed Business class seat orientation may have changed At Front	
94 (19)	NFK	Consist reversed Business class seat orientation may have changed At Front	