

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, August 21, 2026

Rules: 3-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/20/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/20/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	51	84.3%	6,139	998	83.7%	97,083	13,550	86.0%
Central Division	86.0%	57	8	86.0%	1,136	146	87.1%	18,564	1,720	90.7%
East Division	82.0%	175	27	84.6%	3,321	526	84.2%	50,991	7,944	84.4%
West Division	86.0%	92	16	82.6%	1,682	326	80.6%	27,528	3,886	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00703 00000008738 "UNCLASSIFIED" 9/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	96,131	24,197	75%	2,120,623	650,729	69%	32,453,621	8,292,079	74%
Northeast Corridor	81%	42,799	5,465	87%	924,519	242,683	74%	14,226,032	3,498,711	75%
Acela	83%	11,025	482	96%	193,375	43,176	78%	2,853,799	744,727	74%
Northeast Regional	79%	31,774	4,983	84%	731,144	199,507	73%	11,372,233	2,753,984	76%
Richmond / Newport News / Norfolk	77%	9,801	1,116	89%	226,591	81,641	64%	3,526,567	1,043,102	70%
Springfield Shuttles	89%	646	147	77%	12,434	1,955	84%	200,161	31,823	84%
Roanoke	79%	3,634	487	87%	72,323	21,452	70%	1,077,607	240,108	78%
On Spine Northeast Regional	80%	17,693	3,233	82%	419,796	94,459	77%	6,567,898	1,438,951	78%
State Supported	80%	42,005	10,651	75%	955,153	265,138	72%	14,264,772	3,071,063	78%
Borealis	80%	616	213	65%	11,845	2,968	75%	181,471	38,600	79%
Capitol Corridor	90%	3,947	195	95%	74,280	11,866	84%	1,189,999	157,615	87%
Carolinian	70%	1,034	393	62%	22,208	9,819	56%	367,090	144,818	61%
Cascades	75%	2,286	966	58%	35,513	17,799	50%	818,763	232,835	72%
Downeaster	82%	1,681	868	48%	40,326	5,282	87%	500,639	61,237	88%
Empire	78%	6,382	1,482	77%	127,667	43,437	66%	1,771,380	426,896	76%
Adirondack	72%	476	15	97%	9,249	4,815	48%	109,212	35,660	67%
Ethan Allen Express	70%	611	263	57%	11,877	7,347	38%	180,785	67,696	63%
Maple Leaf	70%	898	418	53%	18,328	8,293	55%	218,677	85,136	61%
New York - Albany	85%	2,941	295	90%	57,254	13,963	76%	819,602	139,890	83%
New York - Niagara Falls	75%	1,456	491	66%	28,639	7,233	75%	432,671	92,914	79%
Berkshire Flyer	60%	0	0	-	2,320	1,786	23%	10,433	5,600	46%
Gold Runner	73%	1,380	767	44%	48,344	25,685	47%	803,910	296,138	63%
Heartland Flyer	70%	109	47	57%	4,666	3,299	29%	69,349	28,721	59%
Hiawatha	90%	2,171	431	80%	41,032	3,592	91%	561,951	61,289	89%
Illinois	78%	2,774	582	79%	53,166	21,215	60%	799,390	225,770	72%
Carl Sandburg / Illinois Zephyr	85%	534	186	65%	8,838	3,924	56%	133,638	38,082	72%
Illini / Saluki	85%	860	182	79%	15,883	7,369	54%	275,770	69,269	75%
Lincoln Service	70%	1,380	214	84%	28,445	9,922	65%	389,982	118,419	70%
Keystone	92%	5,594	444	92%	157,016	10,740	93%	2,439,135	250,286	90%
Lincoln / Missouri	70%	340	140	59%	16,903	11,865	30%	249,394	130,173	48%
Mardi Gras Service	80%	191	60	69%	6,241	1,359	78%	129,962	28,974	78%
Michigan	70%	2,703	1,821	33%	49,242	24,573	50%	646,667	216,994	66%
Blue Water	70%	877	524	40%	12,449	7,249	42%	152,107	63,077	59%
Pere Marquette	85%	159	0	100%	4,976	951	81%	83,410	16,075	81%
Wolverine	70%	1,667	1,297	22%	31,817	16,373	49%	411,150	137,842	66%
Missouri	80%	237	219	8%	5,474	3,213	41%	71,310	19,649	72%
Pacific Surfliner	85%	7,966	1,066	87%	198,642	50,377	75%	2,610,814	480,084	82%
Pennsylvanian	80%	865	210	76%	17,393	3,347	81%	283,195	54,424	81%
Piedmont	80%	848	339	60%	19,722	4,247	78%	359,996	92,899	74%
Vermont	75%	881	408	54%	25,473	10,455	59%	410,357	123,661	70%
Long Distance	70%	11,327	8,081	29%	240,951	142,908	41%	3,923,550	1,719,842	56%
Auto Train	70%	852	852	0%	17,276	4,936	71%	251,685	85,725	66%
California Zephyr	70%	836	387	54%	19,862	13,911	30%	311,456	120,568	61%
Cardinal	70%	622	601	3%	3,082	2,111	32%	74,563	37,654	50%
City Of New Orleans	75%	471	469	0%	11,779	9,461	20%	203,003	67,640	67%
Coast Starlight	70%	1,021	77	92%	19,661	9,584	51%	364,338	130,046	64%
Crescent	70%	754	230	69%	17,149	5,231	69%	296,802	91,214	69%
Empire Builder	70%	1,098	1,020	7%	20,476	12,327	40%	308,843	154,532	50%
Floridian	60%	1,365	1,365	0%	27,623	23,117	16%	505,389	350,159	31%
Lake Shore Ltd	73%	1,143	777	32%	23,076	9,510	59%	310,313	94,616	70%
Palmetto	70%	819	248	70%	18,092	9,602	47%	294,195	92,211	69%
Silver Meteor	70%	826	680	18%	19,795	13,488	32%	324,995	150,839	54%
Southwest Chief	60%	817	785	4%	18,189	14,581	20%	268,655	177,174	34%
Sunset Ltd	70%	0	0	-	4,738	3,650	23%	93,104	36,418	61%
Texas Eagle	70%	703	590	16%	20,153	11,399	43%	316,209	131,046	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00700 00000000700 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 20, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	137,020	2,122,760	645	1,927,099	34,070,698	566

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,515	651,159	115	93,427	9,848,161	95
INFRASTRUCTURE PLANNED	135	12,950	651,159	199	109,005	9,848,161	111
FLEET RELIABILITY	90	20,679	2,122,760	97	306,819	34,070,698	90
TRAIN OPERATIONS	424	95,876	2,122,760	452	1,417,848	34,070,698	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/20/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/20/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	51	84.3%	6,139	998	83.7%	97,083	13,550	86.0%
Central Division	86.0%	57	8	86.0%	1,136	146	87.1%	18,564	1,720	90.7%
East Division	82.0%	175	27	84.6%	3,321	526	84.2%	50,991	7,944	84.4%
West Division	86.0%	92	16	82.6%	1,682	326	80.6%	27,528	3,886	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/20/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/20/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	51	84.3%	6,139	998	83.7%	97,083	13,550	86.0%
Central Division	86.0%	57	8	86.0%	1,136	146	87.1%	18,564	1,720	90.7%
CDL	95.0%	2	0	100.0%	38	6	84.2%	614	31	95.0%
CHI	86.0%	27	5	81.5%	526	97	81.6%	8,576	1,064	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	1	0.0%	20	1	95.0%	347	37	89.3%
GBB	-	-	-	-	2	1	50.0%	15	12	20.0%
GRR	95.5%	1	0	100.0%	17	3	82.4%	305	11	96.4%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	40	6	85.0%	627	50	92.0%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	1	80.0%	115	8	93.0%	1,895	122	93.6%
MOE	97.5%	2	0	100.0%	40	0	100.0%	645	9	98.6%
MSP	96.5%	1	0	100.0%	20	1	95.0%	317	7	97.8%
NOL	94.5%	4	0	100.0%	88	2	97.7%	1,361	62	95.4%
OKC	97.0%	1	0	100.0%	20	0	100.0%	318	6	98.1%
PNT	88.0%	3	1	66.7%	57	7	87.7%	844	71	91.6%
PTH	93.0%	1	0	100.0%	20	2	90.0%	312	13	95.8%
QCY	91.0%	2	0	100.0%	34	4	88.2%	611	47	92.3%
SAS	90.5%	1	0	100.0%	20	3	85.0%	321	36	88.8%
STL	89.0%	4	0	100.0%	78	4	94.9%	1,253	104	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	27	84.6%	3,321	526	84.2%	50,991	7,944	84.4%
ALB	88.5%	8	0	100.0%	150	6	96.0%	2,400	181	92.5%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	2	60.0%	100	14	86.0%	1,566	172	89.0%
BOS	85.5%	18	0	100.0%	347	29	91.6%	5,510	633	88.5%
BRK	92.5%	2	0	100.0%	88	10	88.6%	1,540	112	92.7%
BTN	82.0%	1	0	100.0%	19	1	94.7%	309	42	86.4%
CLT	91.5%	5	0	100.0%	100	10	90.0%	1,577	160	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	33	2	93.9%	626	59	90.6%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	6	53.8%	224	38	83.0%	3,588	586	83.7%
HFD	-	2	0	100.0%	27	3	88.9%	218	18	91.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	20	1	95.0%	320	39	87.8%
MIA	89.5%	2	1	50.0%	37	6	83.8%	637	74	88.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/20/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/20/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	51	84.3%	6,139	998	83.7%	97,083	13,550	86.0%
East Division	82.0%	175	27	84.6%	3,321	526	84.2%	50,991	7,944	84.4%
MTR	79.0%	1	0	100.0%	20	6	70.0%	307	58	81.1%
NFK	84.5%	2	2	0.0%	40	8	80.0%	723	131	81.9%
NFL	93.5%	2	0	100.0%	40	1	97.5%	652	30	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	97	25	74.2%	1,651	278	83.2%
NPN	93.0%	2	0	100.0%	40	6	85.0%	612	47	92.3%
NYP	75.5%	50	6	88.0%	935	204	78.2%	13,419	2,982	77.8%
PGH	93.0%	1	0	100.0%	20	1	95.0%	321	23	92.8%
PHL	48.0%	5	3	40.0%	94	40	57.4%	1,644	780	52.6%
PIT	76.0%	-	-	-	5	5	0.0%	20	17	15.0%
POR	-	3	2	33.3%	12	7	41.7%	23	15	34.8%
RGH	95.0%	4	0	100.0%	72	3	95.8%	1,230	52	95.8%
RNK	83.5%	2	0	100.0%	40	3	92.5%	636	90	85.8%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	-	-	-	16	0	100.0%	303	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	20	1	95.0%	317	11	96.5%
SFA	88.0%	1	0	100.0%	20	3	85.0%	320	44	86.3%
SPG	92.5%	5	1	80.0%	97	6	93.8%	1,904	111	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	20	3	85.0%	309	63	79.6%
WAS	84.0%	31	3	90.3%	580	84	85.5%	8,052	1,051	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	92	16	82.6%	1,682	326	80.6%	27,528	3,886	85.9%
ARN	92.0%	1	0	100.0%	20	2	90.0%	322	28	91.3%
BFD	79.0%	7	2	71.4%	139	36	74.1%	2,036	429	78.9%
EMY	72.0%	1	0	100.0%	20	3	85.0%	338	97	71.3%
EUG	86.5%	2	0	100.0%	40	2	95.0%	638	58	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	60	18	70.0%	969	161	83.4%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	2	80.0%	205	22	89.3%	3,204	348	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	4	69.2%	234	84	64.1%	3,495	912	73.9%
PDX	86.0%	5	1	80.0%	55	32	41.8%	1,543	213	86.2%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/20/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/20/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	51	84.3%	6,139	998	83.7%	97,083	13,550	86.0%
West Division	86.0%	92	16	82.6%	1,682	326	80.6%	27,528	3,886	85.9%
SAC	88.5%	16	2	87.5%	293	29	90.1%	4,559	491	89.2%
SAN	90.5%	13	0	100.0%	255	23	91.0%	3,896	367	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	88	34	61.4%	2,473	381	84.6%
SJC	89.0%	7	2	71.4%	139	16	88.5%	2,263	225	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	60	6	90.0%	732	71	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	6	3	50.0%	304	29	90.5%
VAC	97.0%	2	0	100.0%	40	0	100.0%	631	14	97.8%
VAN	-	-	-	-	27	16	40.7%	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	84	20	4	80.0%	322	63	80.4%	19	13	31.6%	319	149	53.3%
4	59	20	2	90.0%	321	48	85.0%	20	15	25.0%	321	214	33.3%
5	58	20	4	80.0%	320	54	83.1%	20	16	20.0%	316	104	67.1%
6		20	3	85.0%	319	88	72.4%	20	16	20.0%	319	119	62.7%
7	245	20	7	65.0%	311	49	84.2%	19	8	57.9%	302	82	72.8%
8	206	20	11	45.0%	311	140	55.0%	20	14	30.0%	310	189	39.0%
11		20	15	25.0%	322	72	77.6%	20	6	70.0%	316	66	79.1%
14		20	2	90.0%	323	51	84.2%	19	10	47.4%	320	102	68.1%
19		20	4	80.0%	321	81	74.8%	20	6	70.0%	318	77	75.8%
20		20	0	100.0%	321	23	92.8%	20	4	80.0%	321	62	80.7%
21	102	20	8	60.0%	318	33	89.6%	20	8	60.0%	317	90	71.6%
22	408	20	3	85.0%	319	34	89.3%	20	11	45.0%	317	92	71.0%
23		20	0	100.0%	323	6	98.1%	20	3	85.0%	321	88	72.6%
24		20	0	100.0%	323	16	95.0%	20	6	70.0%	322	62	80.7%
25	41	20	0	100.0%	322	3	99.1%	19	8	57.9%	319	91	71.5%
26		20	0	100.0%	322	5	98.4%	19	2	89.5%	319	62	80.6%
27	221	6	5	16.7%	291	21	92.8%	3	3	0.0%	284	96	66.2%
40	62	17	6	64.7%	313	47	85.0%	16	12	25.0%	309	167	46.0%
41	392	18	7	61.1%	313	121	61.3%	17	15	11.8%	310	239	22.9%
42		20	1	95.0%	323	25	92.3%	20	4	80.0%	321	56	82.6%
43		20	3	85.0%	322	45	86.0%	20	3	85.0%	321	73	77.3%
48		20	5	75.0%	321	62	80.7%	20	6	70.0%	320	48	85.0%
49	81	20	5	75.0%	321	80	75.1%	20	6	70.0%	321	68	78.8%
51	170	5	3	40.0%	131	58	55.7%	6	5	16.7%	127	49	61.4%
52	41	20	3	85.0%	320	44	86.3%	20	1	95.0%	319	73	77.1%
53	84	20	1	95.0%	320	39	87.8%	20	8	60.0%	319	103	67.7%
55	96	14	2	85.7%	204	9	95.6%	14	5	64.3%	201	43	78.6%
56		14	2	85.7%	205	25	87.8%	14	5	64.3%	201	39	80.6%
58	397	19	1	94.7%	296	17	94.3%	18	16	11.1%	294	89	69.7%
59	418	20	14	30.0%	295	47	84.1%	19	16	15.8%	290	73	74.8%
63	63	20	8	60.0%	324	140	56.8%	20	20	0.0%	318	186	41.5%
64	35	20	3	85.0%	322	71	78.0%	20	16	20.0%	321	125	61.1%
66		20	2	90.0%	321	63	80.4%	20	5	75.0%	317	59	81.4%
67		15	1	93.3%	223	14	93.7%	14	4	71.4%	222	40	82.0%
68		20	6	70.0%	324	67	79.3%	20	12	40.0%	323	130	59.8%
69		20	9	55.0%	311	77	75.2%	20	10	50.0%	306	53	82.7%
71		20	0	100.0%	319	3	99.1%	19	4	78.9%	317	85	73.2%
72		20	4	80.0%	315	35	88.9%	19	7	63.2%	313	68	78.3%
73		20	3	85.0%	318	22	93.1%	20	5	75.0%	316	147	53.5%
74	44	20	1	95.0%	316	34	89.2%	20	6	70.0%	314	114	63.7%
75	20	20	0	100.0%	312	16	94.9%	20	9	55.0%	306	146	52.3%
76	27	20	1	95.0%	312	30	90.4%	20	10	50.0%	303	127	58.1%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		20	0	100.0%	314	20	93.6%	20	6	70.0%	312	129	58.7%
78		20	1	95.0%	318	26	91.8%	20	9	55.0%	317	72	77.3%
79	59	20	2	90.0%	321	58	81.9%	20	7	65.0%	320	108	66.3%
80		20	3	85.0%	321	36	88.8%	20	8	60.0%	318	71	77.7%
84		14	4	71.4%	195	18	90.8%	12	4	66.7%	191	47	75.4%
85		14	2	85.7%	206	18	91.3%	14	4	71.4%	206	74	64.1%
86		14	1	92.9%	206	16	92.2%	14	4	71.4%	205	119	42.0%
89		20	10	50.0%	319	75	76.5%	20	10	50.0%	317	95	70.0%
90		20	1	95.0%	319	11	96.6%	20	8	60.0%	318	59	81.4%
93		14	2	85.7%	205	21	89.8%	14	7	50.0%	204	54	73.5%
94		14	4	71.4%	236	59	75.0%	14	4	71.4%	234	87	62.8%
95		14	2	85.7%	205	6	97.1%	14	11	21.4%	205	80	61.0%
97	178	20	14	30.0%	321	212	34.0%	20	15	25.0%	319	115	63.9%
98	33	20	0	100.0%	321	26	91.9%	20	12	40.0%	319	120	62.4%
110		14	3	78.6%	202	105	48.0%	14	1	92.9%	199	20	89.9%
111		14	1	92.9%	196	36	81.6%	14	1	92.9%	194	22	88.7%
112		14	1	92.9%	196	19	90.3%	14	0	100.0%	195	19	90.3%
113		14	6	57.1%	127	31	75.6%	14	1	92.9%	126	15	88.1%
119		14	2	85.7%	193	47	75.6%	14	4	71.4%	191	26	86.4%
125		14	1	92.9%	206	12	94.2%	14	8	42.9%	206	82	60.2%
129		14	3	78.6%	205	50	75.6%	14	2	85.7%	205	30	85.4%
130		14	2	85.7%	196	20	89.8%	14	0	100.0%	194	16	91.8%
131		14	3	78.6%	198	56	71.7%	14	3	78.6%	198	38	80.8%
134	17	14	4	71.4%	206	31	85.0%	14	6	57.1%	205	42	79.5%
136		14	1	92.9%	206	25	87.9%	14	2	85.7%	204	27	86.8%
137	19	14	1	92.9%	203	36	82.3%	14	4	71.4%	203	62	69.5%
138		14	2	85.7%	206	41	80.1%	14	4	71.4%	205	38	81.5%
141	25	14	1	92.9%	205	4	98.0%	14	3	78.6%	204	36	82.4%
148		14	2	85.7%	205	22	89.3%	14	4	71.4%	203	40	80.3%
151		20	7	65.0%	320	102	68.1%	20	3	85.0%	319	98	69.3%
170	34	14	0	100.0%	201	12	94.0%	14	1	92.9%	200	30	85.0%
171		14	0	100.0%	206	11	94.7%	14	10	28.6%	206	85	58.7%
172		14	4	71.4%	205	19	90.7%	14	7	50.0%	203	69	66.0%
173		14	1	92.9%	198	25	87.4%	14	5	64.3%	197	83	57.9%
174		14	2	85.7%	206	22	89.3%	14	4	71.4%	206	52	74.8%
175	61	14	1	92.9%	206	23	88.8%	14	6	57.1%	206	68	67.0%
176		14	2	85.7%	198	17	91.4%	14	2	85.7%	196	26	86.7%
177		14	1	92.9%	206	28	86.4%	14	1	92.9%	206	47	77.2%
178		14	0	100.0%	206	26	87.4%	14	3	78.6%	204	34	83.3%
179	37	14	2	85.7%	206	25	87.9%	14	4	71.4%	205	74	63.9%
181		14	4	71.4%	202	63	68.8%	13	1	92.3%	199	16	92.0%
182		14	1	92.9%	196	31	84.2%	14	0	100.0%	194	21	89.2%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		14	6	57.1%	205	62	69.8%	14	5	64.3%	202	43	78.7%
184		14	3	78.6%	206	36	82.5%	14	1	92.9%	205	28	86.3%
185	18	14	3	78.6%	206	40	80.6%	14	2	85.7%	206	16	92.2%
186		14	5	64.3%	205	26	87.3%	14	7	50.0%	204	60	70.6%
190		14	4	71.4%	205	73	64.4%	14	1	92.9%	204	44	78.4%
192		14	0	100.0%	203	24	88.2%	14	2	85.7%	203	19	90.6%
193	69	13	5	61.5%	201	83	58.7%	13	2	84.6%	200	90	55.0%
196		14	3	78.6%	202	23	88.6%	13	2	84.6%	200	17	91.5%
197		14	1	92.9%	206	76	63.1%	14	3	78.6%	206	70	66.0%
198		14	0	100.0%	138	17	87.7%	14	1	92.9%	137	22	83.9%
230		20	0	100.0%	157	4	97.5%	20	1	95.0%	157	8	94.9%
232		20	0	100.0%	323	11	96.6%	20	2	90.0%	323	23	92.9%
233		15	2	86.7%	288	63	78.1%	15	7	53.3%	287	95	66.9%
234		20	0	100.0%	324	22	93.2%	20	1	95.0%	323	26	92.0%
235		20	7	65.0%	248	41	83.5%	20	5	75.0%	247	57	76.9%
236		20	0	100.0%	308	10	96.8%	20	3	85.0%	307	42	86.3%
237		20	1	95.0%	321	57	82.2%	20	4	80.0%	319	55	82.8%
238		20	3	85.0%	248	23	90.7%	20	3	85.0%	246	21	91.5%
239		20	2	90.0%	322	81	74.8%	20	2	90.0%	321	40	87.5%
240		20	1	95.0%	323	22	93.2%	20	5	75.0%	320	65	79.7%
241		20	7	65.0%	323	81	74.9%	20	7	65.0%	323	78	75.9%
243	18	20	4	80.0%	259	69	73.4%	20	4	80.0%	258	37	85.7%
244	29	15	0	100.0%	287	12	95.8%	15	10	33.3%	287	59	79.4%
245		20	6	70.0%	204	39	80.9%	20	7	65.0%	203	29	85.7%
280	50	20	1	95.0%	324	16	95.1%	20	10	50.0%	323	71	78.0%
281		20	3	85.0%	324	40	87.7%	20	2	90.0%	324	59	81.8%
283		20	9	55.0%	324	83	74.4%	20	3	85.0%	324	64	80.2%
284		20	0	100.0%	324	13	96.0%	20	2	90.0%	321	56	82.6%
290	27	20	1	95.0%	324	51	84.3%	20	14	30.0%	321	128	60.1%
291		20	13	35.0%	323	106	67.2%	19	8	57.9%	320	84	73.8%
300		19	2	89.5%	307	22	92.8%	18	5	72.2%	304	73	76.0%
301		20	0	100.0%	321	10	96.9%	20	5	75.0%	317	60	81.1%
302		19	0	100.0%	302	33	89.1%	19	9	52.6%	298	87	70.8%
305		19	3	84.2%	305	31	89.8%	18	5	72.2%	300	120	60.0%
306		20	1	95.0%	319	17	94.7%	19	5	73.7%	317	87	72.6%
307	77	20	4	80.0%	312	42	86.5%	19	9	52.6%	308	91	70.5%
311	65	20	1	95.0%	317	27	91.5%	20	13	35.0%	311	76	75.6%
316	27	20	3	85.0%	313	21	93.3%	20	15	25.0%	308	93	69.8%
318	332	20	3	85.0%	322	34	89.4%	20	14	30.0%	319	158	50.5%
319	132	20	0	100.0%	323	20	93.8%	20	19	5.0%	318	184	42.1%
329		14	0	100.0%	229	9	96.1%	14	1	92.9%	229	16	93.0%
330		17	0	100.0%	275	6	97.8%	17	0	100.0%	275	15	94.5%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		20	0	100.0%	324	33	89.8%	19	0	100.0%	323	44	86.4%
332		19	1	94.7%	323	18	94.4%	19	2	89.5%	323	45	86.1%
334	18	20	1	95.0%	324	11	96.6%	19	2	89.5%	322	42	87.0%
335	19	20	0	100.0%	324	34	89.5%	20	4	80.0%	322	55	82.9%
337		20	1	95.0%	324	19	94.1%	20	5	75.0%	320	41	87.2%
338	14	20	4	80.0%	324	51	84.3%	20	7	65.0%	322	101	68.6%
339		20	3	85.0%	324	53	83.6%	20	3	85.0%	324	56	82.7%
341		18	5	72.2%	310	49	84.2%	18	9	50.0%	304	50	83.6%
342		20	2	90.0%	324	26	92.0%	20	0	100.0%	322	60	81.4%
350	21	18	1	94.4%	299	19	93.6%	17	14	17.6%	291	165	43.3%
351	24	19	2	89.5%	306	29	90.5%	19	9	52.6%	304	87	71.4%
352	88	19	3	84.2%	290	24	91.7%	19	9	52.6%	284	90	68.3%
353	44	20	0	100.0%	262	13	95.0%	20	9	55.0%	256	47	81.6%
354		20	1	95.0%	305	36	88.2%	20	12	40.0%	298	113	62.1%
355	25	18	5	72.2%	312	36	88.5%	16	14	12.5%	303	113	62.7%
364		20	7	65.0%	313	72	77.0%	20	11	45.0%	307	118	61.6%
365	39	20	2	90.0%	312	13	95.8%	19	11	42.1%	309	120	61.2%
371		17	3	82.4%	305	11	96.4%	14	1	92.9%	301	30	90.0%
380		17	2	88.2%	306	29	90.5%	16	6	62.5%	305	69	77.4%
381		19	3	84.2%	321	15	95.3%	17	8	52.9%	318	68	78.6%
382	19	19	3	84.2%	320	30	90.6%	17	13	23.5%	318	113	64.5%
383		18	1	94.4%	311	27	91.3%	18	9	50.0%	308	132	57.1%
390		19	5	73.7%	305	24	92.1%	18	11	38.9%	303	84	72.3%
391		19	3	84.2%	306	14	95.4%	18	11	38.9%	301	87	71.1%
392	22	19	1	94.7%	319	11	96.6%	17	8	52.9%	314	98	68.8%
393		19	1	94.7%	323	19	94.1%	18	10	44.4%	319	101	68.3%
417		14	2	85.7%	216	46	78.7%	14	2	85.7%	207	24	88.4%
425		13	1	92.3%	217	7	96.8%	12	0	100.0%	216	7	96.8%
448		14	2	85.7%	248	45	81.9%	13	5	61.5%	244	85	65.2%
449		14	1	92.9%	245	33	86.5%	14	2	85.7%	245	44	82.0%
470	42	14	2	85.7%	229	39	83.0%	14	3	78.6%	223	27	87.9%
471		13	2	84.6%	218	13	94.0%	13	0	100.0%	218	5	97.7%
473		14	0	100.0%	225	15	93.3%	14	0	100.0%	222	10	95.5%
474		14	2	85.7%	223	65	70.9%	14	5	64.3%	208	68	67.3%
478		14	3	78.6%	217	35	83.9%	14	1	92.9%	215	28	87.0%
479	16	14	2	85.7%	224	36	83.9%	14	4	71.4%	222	35	84.2%
486		14	3	78.6%	228	34	85.1%	14	3	78.6%	222	61	72.5%
494	58	15	6	60.0%	231	47	79.7%	14	5	64.3%	223	62	72.2%
495		14	0	100.0%	213	4	98.1%	14	0	100.0%	211	3	98.6%
500		3	0	100.0%	298	16	94.6%	3	0	100.0%	295	35	88.1%
502		4	0	100.0%	306	18	94.1%	4	1	75.0%	302	59	80.5%
503		20	13	35.0%	320	40	87.5%	20	13	35.0%	313	100	68.1%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504	64	20	1	95.0%	324	20	93.8%	20	6	70.0%	322	96	70.2%
505		14	1	92.9%	316	42	86.7%	14	4	71.4%	311	88	71.7%
506		20	13	35.0%	319	55	82.8%	18	3	83.3%	311	49	84.2%
507		20	12	40.0%	324	48	85.2%	20	11	45.0%	324	111	65.7%
508		20	1	95.0%	319	42	86.8%	20	11	45.0%	315	79	74.9%
509	22	4	1	75.0%	305	15	95.1%	4	3	25.0%	305	69	77.4%
511		4	1	75.0%	300	25	91.7%	4	2	50.0%	299	52	82.6%
516		20	6	70.0%	315	35	88.9%	20	8	60.0%	314	142	54.8%
517	30	20	0	100.0%	324	8	97.5%	20	17	15.0%	320	144	55.0%
518	49	20	8	60.0%	324	45	86.1%	20	20	0.0%	322	227	29.5%
519		20	0	100.0%	315	9	97.1%	20	6	70.0%	313	72	77.0%
520		14	4	71.4%	187	29	84.5%	12	1	91.7%	182	10	94.5%
521		14	0	100.0%	225	7	96.9%	13	3	76.9%	224	30	86.6%
522		14	2	85.7%	225	41	81.8%	14	1	92.9%	222	21	90.5%
523		14	2	85.7%	225	9	96.0%	14	4	71.4%	224	26	88.4%
524		13	1	92.3%	224	17	92.4%	13	3	76.9%	221	26	88.2%
525		13	0	100.0%	222	16	92.8%	13	1	92.3%	218	15	93.1%
526		14	7	50.0%	199	41	79.4%	14	3	78.6%	196	18	90.8%
527		14	0	100.0%	225	10	95.6%	14	2	85.7%	224	39	82.6%
528		14	2	85.7%	225	19	91.6%	14	2	85.7%	224	32	85.7%
529		14	1	92.9%	225	13	94.2%	14	5	64.3%	224	63	71.9%
530	17	14	2	85.7%	179	18	89.9%	14	4	71.4%	179	36	79.9%
531		14	0	100.0%	199	13	93.5%	14	0	100.0%	199	13	93.5%
532		14	5	64.3%	225	56	75.1%	13	3	76.9%	223	34	84.8%
534		14	2	85.7%	184	27	85.3%	14	0	100.0%	182	16	91.2%
535		13	1	92.3%	211	26	87.7%	13	3	76.9%	206	26	87.4%
536		14	6	57.1%	225	61	72.9%	14	2	85.7%	221	40	81.9%
537		13	0	100.0%	194	22	88.7%	13	2	84.6%	188	22	88.3%
538		14	2	85.7%	225	26	88.4%	14	2	85.7%	224	45	79.9%
539	31	14	3	78.6%	179	27	84.9%	14	6	57.1%	179	77	57.0%
540	Cncld	14	3	78.6%	224	41	81.7%	12	1	91.7%	214	19	91.1%
541	Cncld	14	2	85.7%	224	24	89.3%	13	3	76.9%	217	39	82.0%
542		14	1	92.9%	224	25	88.8%	14	3	78.6%	221	40	81.9%
543		14	2	85.7%	225	26	88.4%	14	5	64.3%	225	68	69.8%
544		14	1	92.9%	223	21	90.6%	13	2	84.6%	219	22	90.0%
545		14	1	92.9%	225	18	92.0%	14	3	78.6%	222	27	87.8%
547		14	4	71.4%	225	45	80.0%	14	5	64.3%	225	52	76.9%
548		13	1	92.3%	219	22	90.0%	12	2	83.3%	216	17	92.1%
549	Cncld	14	1	92.9%	220	27	87.7%	12	3	75.0%	210	20	90.5%
550	12	14	1	92.9%	179	19	89.4%	14	7	50.0%	179	43	76.0%
551		14	1	92.9%	221	23	89.6%	14	3	78.6%	211	23	89.1%
562		20	3	85.0%	315	26	91.7%	20	0	100.0%	311	35	88.7%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564		20	0	100.0%	316	19	94.0%	20	3	85.0%	308	41	86.7%
566		20	4	80.0%	314	29	90.8%	20	6	70.0%	311	51	83.6%
567		20	1	95.0%	201	11	94.5%	20	2	90.0%	199	11	94.5%
572		20	2	90.0%	311	26	91.6%	20	8	60.0%	304	91	70.1%
573		20	3	85.0%	313	43	86.3%	20	3	85.0%	306	54	82.4%
579		20	1	95.0%	201	12	94.0%	19	3	84.2%	195	40	79.5%
580		20	1	95.0%	316	17	94.6%	20	4	80.0%	309	32	89.6%
581		20	4	80.0%	316	54	82.9%	20	8	60.0%	314	72	77.1%
584		20	3	85.0%	200	28	86.0%	20	18	10.0%	195	126	35.4%
587	40	20	2	90.0%	309	18	94.2%	20	6	70.0%	300	59	80.3%
588	69	18	1	94.4%	199	19	90.5%	18	6	66.7%	198	39	80.3%
591		20	1	95.0%	313	22	93.0%	19	4	78.9%	306	43	85.9%
593		17	2	88.2%	307	49	84.0%	17	1	94.1%	286	38	86.7%
595	37	18	4	77.8%	309	57	81.6%	18	6	66.7%	306	66	78.4%
600		14	0	100.0%	233	9	96.1%	14	2	85.7%	231	21	90.9%
601		14	6	57.1%	216	89	58.8%	14	2	85.7%	213	27	87.3%
605		14	7	50.0%	223	137	38.6%	14	0	100.0%	219	22	90.0%
607		14	0	100.0%	232	30	87.1%	14	0	100.0%	229	25	89.1%
609		14	0	100.0%	223	23	89.7%	14	3	78.6%	222	22	90.1%
622	Cncld	12	2	83.3%	132	34	74.2%	11	0	100.0%	129	5	96.1%
626		14	4	71.4%	137	20	85.4%	14	0	100.0%	135	18	86.7%
639	Cncld	14	2	85.7%	203	40	80.3%	13	0	100.0%	201	19	90.5%
640		14	0	100.0%	223	7	96.9%	14	4	71.4%	221	84	62.0%
641		14	4	71.4%	205	42	79.5%	14	1	92.9%	205	27	86.8%
642		14	2	85.7%	221	11	95.0%	14	1	92.9%	220	27	87.7%
643		14	0	100.0%	235	44	81.3%	14	2	85.7%	232	38	83.6%
644		14	0	100.0%	227	28	87.7%	14	3	78.6%	225	55	75.6%
645		14	0	100.0%	235	41	82.6%	14	7	50.0%	232	53	77.2%
646	58	14	3	78.6%	224	54	75.9%	14	8	42.9%	222	109	50.9%
647	Cncld	14	0	100.0%	235	32	86.4%	13	0	100.0%	233	49	79.0%
648		14	2	85.7%	231	58	74.9%	14	1	92.9%	231	35	84.8%
649	Cncld	14	2	85.7%	236	44	81.4%	13	0	100.0%	232	34	85.3%
650		14	4	71.4%	235	45	80.9%	14	2	85.7%	232	38	83.6%
651	Cncld	14	1	92.9%	235	17	92.8%	13	1	92.3%	232	43	81.5%
652		14	2	85.7%	236	31	86.9%	14	3	78.6%	232	40	82.8%
653	Cncld	14	3	78.6%	224	36	83.9%	13	1	92.3%	220	40	81.8%
654	25	14	4	71.4%	225	44	80.4%	14	2	85.7%	221	20	91.0%
655	Cncld	14	2	85.7%	233	74	68.2%	13	2	84.6%	230	75	67.4%
656	Cncld	14	6	57.1%	235	53	77.4%	13	3	76.9%	233	33	85.8%
657	Cncld	14	2	85.7%	224	29	87.1%	13	1	92.3%	222	30	86.5%
658		14	2	85.7%	235	37	84.3%	14	0	100.0%	233	33	85.8%
680		14	0	100.0%	230	12	94.8%	13	0	100.0%	228	27	88.2%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681		14	1	92.9%	230	18	92.2%	13	5	61.5%	223	91	59.2%
682	18	14	3	78.6%	229	9	96.1%	14	3	78.6%	229	41	82.1%
683		14	1	92.9%	212	18	91.5%	14	5	64.3%	211	72	65.9%
684	191	14	5	64.3%	211	37	82.5%	14	1	92.9%	211	46	78.2%
685	137	14	1	92.9%	226	32	85.8%	14	2	85.7%	223	55	75.3%
686	108	14	2	85.7%	231	39	83.1%	14	5	64.3%	230	52	77.4%
687	72	14	4	71.4%	230	38	83.5%	14	3	78.6%	229	39	83.0%
688		14	2	85.7%	229	15	93.4%	14	4	71.4%	228	40	82.5%
689		6	1	83.3%	151	21	86.1%	5	2	60.0%	149	23	84.6%
701		20	3	85.0%	256	28	89.1%	20	4	80.0%	253	29	88.5%
702	101	20	0	100.0%	323	32	90.1%	20	10	50.0%	320	80	75.0%
703	No OS	20	15	25.0%	324	108	66.7%	20	11	45.0%	322	96	70.2%
704		20	6	70.0%	255	43	83.1%	19	7	63.2%	247	53	78.5%
710		20	1	95.0%	324	78	75.9%	20	6	70.0%	320	87	72.8%
711		20	2	90.0%	315	36	88.6%	18	9	50.0%	292	61	79.1%
712	Cncld	20	8	60.0%	321	88	72.6%	19	10	47.4%	311	108	65.3%
713	Cncld	19	1	94.7%	191	17	91.1%	14	9	35.7%	170	76	55.3%
714	108	20	12	40.0%	205	87	57.6%	18	13	27.8%	189	89	52.9%
715	Cncld	20	1	95.0%	323	62	80.8%	16	10	37.5%	296	151	49.0%
716		20	13	35.0%	324	133	59.0%	19	15	21.1%	317	133	58.0%
717	Cncld	20	5	75.0%	309	73	76.4%	16	7	56.3%	286	93	67.5%
718		20	15	25.0%	324	168	48.1%	19	12	36.8%	321	121	62.3%
719		20	9	55.0%	324	112	65.4%	19	10	47.4%	307	94	69.4%
757		20	1	95.0%	109	6	94.5%	20	2	90.0%	108	10	90.7%
761		20	1	95.0%	320	13	95.9%	20	2	90.0%	317	43	86.4%
765		20	0	100.0%	320	25	92.2%	20	3	85.0%	320	45	85.9%
769		20	0	100.0%	320	27	91.6%	20	4	80.0%	314	61	80.6%
770		20	2	90.0%	320	24	92.5%	20	11	45.0%	318	100	68.6%
774		20	0	100.0%	320	16	95.0%	20	5	75.0%	319	74	76.8%
777		20	0	100.0%	205	12	94.1%	20	8	60.0%	204	50	75.5%
782		20	15	25.0%	205	97	52.7%	20	5	75.0%	200	30	85.0%
785		20	4	80.0%	320	26	91.9%	20	5	75.0%	320	58	81.9%
786	25	20	2	90.0%	109	21	80.7%	19	12	36.8%	105	59	43.8%
790	17	20	1	95.0%	320	29	90.9%	20	4	80.0%	317	50	84.2%
794		20	4	80.0%	320	37	88.4%	20	6	70.0%	316	72	77.2%
821	15	20	0	100.0%	318	6	98.1%	20	13	35.0%	318	134	57.9%
822	22	20	1	95.0%	320	17	94.7%	20	18	10.0%	318	160	49.7%
1333	28	20	5	75.0%	320	37	88.4%	20	7	65.0%	317	106	66.6%
1340		20	1	95.0%	319	7	97.8%	19	4	78.9%	318	55	82.7%
2102		14	2	85.7%	82	15	81.7%	14	1	92.9%	81	7	91.4%
2103		14	2	85.7%	146	14	90.4%	14	1	92.9%	145	10	93.1%
2104		14	0	100.0%	172	10	94.2%	14	1	92.9%	170	13	92.4%

Amtrak On Time Performance

Trains Arriving Through: 8/20/2026

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2107		14	1	92.9%	203	35	82.8%	14	1	92.9%	200	21	89.5%
2108		14	2	85.7%	203	28	86.2%	14	7	50.0%	197	27	86.3%
2109		14	1	92.9%	96	12	87.5%	14	1	92.9%	94	5	94.7%
2112		14	2	85.7%	43	6	86.0%	14	0	100.0%	41	2	95.1%
2113		14	1	92.9%	82	9	89.0%	14	0	100.0%	82	10	87.8%
2115		14	1	92.9%	82	12	85.4%	14	1	92.9%	81	11	86.4%
2116		14	0	100.0%	43	1	97.7%	14	1	92.9%	43	8	81.4%
2118		14	2	85.7%	43	4	90.7%	14	2	85.7%	43	11	74.4%
2119		14	3	78.6%	43	7	83.7%	13	2	84.6%	42	12	71.4%
2120		14	10	28.6%	43	19	55.8%	13	9	30.8%	41	22	46.3%
2123		14	1	92.9%	81	9	88.9%	14	0	100.0%	80	15	81.3%
2124		13	4	69.2%	174	38	78.2%	13	2	84.6%	172	24	86.0%
2127		14	2	85.7%	43	9	79.1%	14	1	92.9%	42	8	81.0%
2128		14	1	92.9%	43	4	90.7%	14	1	92.9%	43	3	93.0%
2131		14	3	78.6%	43	9	79.1%	14	1	92.9%	43	4	90.7%
2150		14	0	100.0%	196	22	88.8%	14	1	92.9%	193	74	61.7%
2151		14	1	92.9%	145	7	95.2%	14	3	78.6%	143	40	72.0%
2152		14	1	92.9%	101	7	93.1%	14	1	92.9%	100	31	69.0%
2154		14	0	100.0%	104	23	77.9%	14	3	78.6%	100	45	55.0%
2155		14	1	92.9%	205	17	91.7%	14	4	71.4%	201	100	50.2%
2158		14	1	92.9%	42	5	88.1%	14	3	78.6%	42	15	64.3%
2159		14	2	85.7%	198	16	91.9%	14	9	35.7%	196	68	65.3%
2160		14	0	100.0%	43	2	95.3%	14	8	42.9%	42	26	38.1%
2162		14	4	71.4%	204	22	89.2%	14	5	64.3%	198	90	54.5%
2165		14	2	85.7%	40	4	90.0%	14	8	42.9%	40	21	47.5%
2167		14	0	100.0%	191	20	89.5%	14	1	92.9%	191	40	79.1%
2171		14	0	100.0%	132	10	92.4%	14	0	100.0%	128	23	82.0%
2190		14	2	85.7%	201	29	85.6%	14	1	92.9%	199	24	87.9%
2193		14	0	100.0%	196	25	87.2%	14	1	92.9%	194	50	74.2%

Amtrak Endpoint OTP Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/20/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
134	NYP	17	SYS	16	SYS	16	WAS-WAS	AM	Other late crew, CREW ARRIVED LATE TO PLATFORM.
137	WAS	19	SMW	37	SMW	23	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT-PELHAMBAY 2 TRK DUE TO SCHEDULED MAINTENANCE
141	WAS	25	OTH	18	BSP	11	MET-TRE	AM	Bridge strike, Other, NOTTINGHAM WAY
170	BOS	34	OTH	46	OTH	43	NRO-BRP	MN	Hot Journal alarm set off on engine 602, checked at Stamford Station and rechecked at Cat pole 431, with Temperstik on both sides. No exceptions.
175	WAS	61	CTI	61	CTI	47	NHV-STM	MN	Follow metto, Other, entoute
179	PHL	37	ENG	36	ENG	21	XHM-PHL	AM	Other electrical failure, 642 EX ES, stopped to reset fault
185	WAS	18	OTH	15	DMW	10	MET-TRE	AM	Held for or routed around MW work or equipment, Other, DELCO-TRE, OPR 4 TRK A/C MW FOULING 3 TRK AT HAM
193	WAS	69	SYS	56	SYS	47	BWI-NCR	AM	Re-crew / job briefing, CREW TIME EXPIRED. HELD AT BOWIE FOR 8910 TO COUPLE AND BRING TRAIN SOUTH
470	HFD	42	CON	34	CON	34	NHV-NHV	AM	Hold for connecting train
479	NHV	16	PSR	6	PSR	6	SPG-WNL	AM	Post MW Work, Milepost w/Letters, SPG, WNL, 30 MPH S/R MP 47.2 - MP 49.2
494	GFD	58	ITI	35	ITI	34	NHV-NHV	AM	Service, turn, or wye train, 417
52	LOR	41	ITI	52	ITI	52	SFA-SFA	FR	Service, turn, or wye train 53
53	SFA	84	FTI	131	FTI	25	XSE-XFL	CS	Meet I032, Milepost, 216.1, 218.7
79	CLT	59	PTI	49	WTR	18	PTB-RMT	CS	Heat order Other, ptb
622	PHL	Trn Cancelled							
639	PHL	Trn Cancelled							
646	NYP	58	ENG	45	ENG	22	PHL-PHL	AM	PTC- Cutout due to unrecoverable penalty, 9634 CB CC, Engine swap a/c bad pantograph. Train unable to take power.
647	HAR	Trn Cancelled	WTR	119	WTR	97	LNC-LNC	AM	Trees down, Control Point, MT JOY, HELD A/C TREES DOWN AND ON FIRE ACROSS BOTH TRACKS AT MT JOY; NO SIGNAL POWER

Amtrak Endpoint OTP Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/20/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
649	HAR	Trn Cancelled	SVS	29	SVS	29	PHL-ARD	AM	Unplanned Wye, WYE ON THE OUTBOUND
651	HAR	Trn Cancelled	OTH	179	OTH	177	NWK-TRE	AM	Lost time - N.A.R.
653	HAR	Trn Cancelled	CTI	5	CTI	5	NYP-NWK	AM	Follow, NJT, NJ3725, Other, NYP-NWK
654	NYP	25	WTR	24	WTR	24	MID-ELT	AM	Trees down, Control Point, MT JOY, SPUN AND SENT BACK TO HARRISBURG A/C TREES IN CATENARY AT MT JOY
655	HAR	Trn Cancelled	PTI	5	PTI	5	NYP-NWK	AM	Follow, AM137, Other, NYP-NWK
656	NYP	Trn Cancelled							
657	HAR	Trn Cancelled							
682	BON	18	DCS	16	DCS	5	DOV-DHM	CS	Restrictive signal(s) from unknown cause Restricting and proceed, Other, dover
684	BON	191	TRS	183	TRS	183	EXR-XP0	CS	Trespasser strike Control Point, SL
685	BRK	137	ITI	128	ITI	128	BON-BON	MT	Service, turn, or wye train 684, Late arrival, brake test, job briefing, board, depart
686	BON	108	TRS	90	TRS	90	EXR-EXR	CS	Trespasser strike for trainn684. Held in Exeter station until 684 released Other, exeter
687	BRK	72	ITI	71	ITI	71	BON-BON	MT	Service, turn, or wye train 686
63	TWO	63	DSR	14	HLD	8	BUF-BUF	CS	Passenger and/or baggage
64	NYP	35	FTI	31	FTI	31	BUF-ROC	CS	Follow Follow and ran on approaches from 423-378 Then crossed over, Control Point, 393, Control Point, 380, csx unknown
243	ALB	18	PTI	9	PTI	9	NYP-XSD	AM	Meet, AM64, Other, XIW
244	NYP	29	CTI	17	CTI	8	POU-CRT	MN	Follow metro, 880, Control Point, 61
280	NYP	50	FTI	22	DSR	13	BUF-ROC	CS	Per MW foreman Milepost, 408.4, 405.0, 25, 1
290	NYP	27	CTI	26	CTI	17	POU-CRT	MN	Follow metro north, Milepost, 68, 33.8
49	CHI	81	FTI	105	FTI	49	SYR-ROC	CS	Follow Train in Emergency ahead, N/A, Other, SYR-ROC
74	RGH	44	PTI	20	PTI	20	GRO-BNC	NS	Meet Amtk 77, Control Point, Superior

Amtrak Endpoint OTP Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/20/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
75	CLT	20	TEN	12	TCC	6	DNC-BNC	NS	CCU NC102
76	RGH	27	DSR	21	DSR	14	KAN-GRO	NS	Per bulletin Milepost, 328.0, 327.7, 10, 1, Milepost, 320.1, 320.0, 25, 1
97	MIA	178	DCS	175	DCS	93	ORL-KIS	FR	PTC- I-ETMS Red Fence/Signal Status Unknown Hand throwing switches, Milepost w/Letters, 791.4, 808.0
98	NYP	33	FTI	68	FTI	25	XDY-SBG	CS	Meet csx, Control Point, Mildred
55	WAS		ITI	75	ITI	75	SPG-SPG	AM	Service, turn, or wye train, 56, AM55 had to wye the train over CSX and BNE, hit multiple stops and had to do multiple break test
40	CHI	62	WTR	65	CAR	37	MIA-MIA	FL	Insect found in sleeper 62007, The 10 car
41	MIA	392	DCS	210	DCS	119	RKV-XQN	AM	Restrictive signal(s) from unknown cause Stop, Control Point, QN 2.1
25	NOL	41	FTI	45	FTI	38	BAS-XNO	NS	Meet CSX 205, CSX/ 67, Control Point, NOT Jct
5	EMY	58	FTI	148	FTI	77	CRN-OMA	BN	Meet They had a broken draw bar, bnsf 9260E, Control Point, 4289
530	SAC	17	MBO	21	MBO	21	MTZ-SUI	UP	For maritime traffic Control Point, vista
539	SJC	31	TEN	21	TEN	21	SAC-SAC	UP	Control Stan failed. Jpbx 921 921
540	SAC	Trn Cancelled							
541	OKJ	Trn Cancelled							
549	OKJ	Trn Cancelled	OTH	24	OTH	24	EMY-OKJ	UP	Went in at kirkham (coach yard) car on tracks ahead
550	SAC	12	MBO	13	MBO	13	MTZ-SUI	UP	For maritime traffic Control Point, Vista
51	CHI	170	FTI	68	PTI	35	CVS-STA	BB	Meet Po5018, Control Point, Afton
504	SEA	64	POL	37	POL	37	PDX-VAN	BN	Right of Way police hold Held at Willbridge for police, possible shooting.
509	PDX	22	CTI	15	PTI	11	TAC-TAC	ST	Meet 14, Control Point, Tacoma Dome
517	PDX	30	FTI	28	FTI	16	BEL-MVW	BN	Meet BNSF 2761, Control Point, South Bow
518	VAC	49	RTE	28	PTI	16	EVR-STW	BN	Meet amtk 519, Siding, English
58	CHI	397	WTR	356	WTR	282	FTN-CDL	CC	Trees down Tornados, flash flood warnings, high wind warnings., Milepost, 380, 320

Amtrak Endpoint OTP Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/20/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
59	NOL	418	DBS	177	DBS	177	CDL-FTN	CC	Debris blocking track (no debris strike) At least 13 trees reported down due to storms and requiring crew to cut through and remove the debris, Milepost, 365, 386
7	SEA	245	ENG	225	ENG	185	CHI-CHI	AM	Adding an engine 176
8	CHI	206	FTI	255	FTI	42	MAL-GGW	BN	Meet Duck and Tuck, BN 8052, BN 5537, Siding, Saco
27	PDX	19	FTI	51	FTI	41	VAN-PDX	BN	Pull into A-Line to meet 518 then back out to crossover 1-2 at Willamette bridge due to BNSF 3856 blocking main 1 at Willbridge BNSF 3856, Bridge, Willamette
821	FTW	15	DSR	32	DSR	25	GLE-FTW	BN	Per bulletin Milepost, 401, 400.2, 25, M, Milepost, 400.0, 399.6, 15, M, Milepost, 396.3, 396.2, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 386.9, 386.8, 25, M, Milepost, 385.5, 385.3, 30, M, Milepost, 383.7, 383.3, 25, M, Milepost, 361.5, 360.9, 15, 1, Milepost, 357.6, 357.3, 29, 2, Milepost, 35
822	OKC	22	DSR	44	DSR	30	FTW-GLE	BN	Per bulletin Milepost, 350.0, 350.4, 30, mt1, Milepost, 350.7, 351.1, 50, mt1, Milepost, 353.7, 354.1, 60, mt1, Milepost, 355.5, 355.9, 50, mt1, Milepost, 360.9, 361.5, 15, mt1, Milepost, 371.4, 371.5, 50, mt, Milepost, 374.0, 374.1, 60, mt, Milepost, 375.4, 376.6, 60, mt, Milepost, 378.7, 378.9, 60
334	CHI	18	RTE	13	RTE	11	SVT-XRO	CP	Put in the siding at Abbott park. 1333 was on MT1, Frights on MT2. Control Point, Abbott Park
335	MKE	19	CTI	11	CTI	10	XWA-GLN	ME	Meet Metra 2134 on MT1 crossing to MT2 at A-6. CPKC 247 on MT2. Had to wait for Metra to get around the freight before we could move., Metra, 2134, Control Point, A-6
338	CHI	14	CTI	6	CTI	5	GLN-XWA	ME	Cross Traffic METRA, Control Point, A5, Control Point, A3
350	PNT	21	PTI	41	PTI	19	KAL-XGO	MI	Meet 365, Control Point, 122
351	CHI	24	DSR	18	FTI	16	XMC-XPI	NS	Cross Traffic 34J, Control Point, 482
352	PNT	88	SYS	99	SYS	97	CHI-XTF	AM	PTC problem or failure (cause unknown)
353	CHI	44	DSR	75	DSR	58	XMC-XPI	AM	Per dispatcher (radio/phone) Control Point, 239, 25, MAIN
355	CHI	25	FTI	45	FTI	20	XPI-HMI	NS	Follow 265, Milepost, 482, 506

Amtrak Endpoint OTP Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/20/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	39	DSR	70	DSR	33	LNS-BTL	CC	Per bulletin Milepost, 221.42, 221.42, 30, MAIN, Milepost, 220.54, 219.86, 25, MAIN, Milepost, 219.86, 217.54, 25, MAIN, Milepost, 215.17, 214.84, 30, MAIN, Milepost, 210.40, 210.40, 30, MAIN TWO, Milepost, 202.45, 202.25, 25, MAIN, Milepost, 196.82, 196.82, 25, MAIN TWO, Milepost, 185.66, 184.79, 3
587	LAX	40	CTI	45	CTI	17	OSD-X98	SC	Meet metrolink, Control Point, songs
588	SAN	69	PTI	40	PTI	26	SOL-OLT	SN	Meet 595, Control Point, Scripps
595	LAX	37	DCS	52	DCS	52	OLT-SOL	SN	Power switch failure Control Point, cudahy
786	SAN	25	DCS	29	PTI	26	GUA-LPS	UP	Meet 765 / 14, Siding, tangair
790	SAN	17	CTI	36	CTI	14	SOL-OLT	SN	Follow AMTK, Control Point, scripps
702	BFD	101	FTI	105	FTI	96	LOD-SKT	UP	Freight train ahead: UDE. UP 7265, Control Point, SPO80
703	SAC	No OS Rpt	ITI	189	ITI	189	BFD-BFD	BN	Service, turn, or wye train 714
712	BFD	Trn Cancelled	TEN	149	TEN	114	MOD-MOD	BN	Loading problem C2014
713	OKJ	Trn Cancelled	FTI	8	FTI	5	HNF-FNO	BN	Blocked from station track Stop signal at CP Fresno due to meet. Held short of station track., Control Point, Fresno, BNSF 7826, Manifest
714	BFD	108	POL	49	POL	49	MCD-MDR	BN	Fire department hold
715	OKJ	Trn Cancelled	PTI	20	SYS	19	MCD-TRK	BN	Blocked by or assisting another, disabled Amtrak train
717	OKJ	Trn Cancelled	ITI	30	ITI	30	BFD-BFD	BN	702 came in late, 702
3	LAX	84	DSR	89	SYS	53	CHI-CHI	AM	Mechanical clearance
4	CHI	59	FTI	90	DBS	50	RIV-SNB	BN	Debris strike Hit debris which had been left between the rails. Debris rolled up under train disconnecting eight hoses in six places. Inspected, re-connected, after securing 3-pt. Protection. PTC went out, re-set breaker. Did Class II air test., Trash can loaded with debris, Milepost, 5.1, 5.1
21	SAS	102	FTI	133	WTR	55	ACD-PBF	UP	Flash flood warning Per dispatcher, Milepost, 112.0, 132.0
22	CHI	408	FTI	263	FTI	156	MHL-TXA	UP	Held at mp36.9 due to up 8470 with3 broken knuckles. Wait for repairs to be completed. Then follow to mp 19.7 Disabled frt, up 8470, Milepost, 36.9, 19.7

Amtrak Endpoint OTP Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/20/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
307	STL	77	SYS	100	SYS	75	XTF-SMT	CC	PTC problem or failure (cause unknown)
382	CHI	19	FTI	14	FTI	14	MAC-GBB	BN	Follow BNSF 4384, Milepost, 174.0, 167.0
392	CHI	22	PTI	22	PTI	22	GLM-KKI	CC	Meet amtrak 59, Siding, ashkum
311	KCY	65	PTI	30	PTI	30	JEF-SED	UP	Meet Daily delay waiting on 318, Amtk 318, Siding, Centertown
316	STL	27	DSR	23	FTI	10	LEE-WAR	UP	Meet UP 8325, Siding, Pleasant Hill
318	CHI	332	RTE	217	RTE	217	HEM-HEM	UP	Dispatcher hold Broken down freight train at Washington, Other, HEM station
319	KCY	132	FTI	82	FTI	78	STL-STL	TR	Freight broken down unk, Milepost w/Letters, stl, st louis
1333	MSP	28	DSR	26	INJ	25	LSE-WIN	CP	Injured or sick passenger Ce4448

Amtrak Initial Terminal Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/20/2026

Terminal	Train	Date	Late	Delay	Cause
BON	685	08/20	128	128	Service, turn, or wye train 684, Late arrival, brake test, job briefing, board, depart
BON	687	08/20	71	71	Service, turn, or wye train 686
HAR	622	08/20	(Trn Cxld)		Downed Trees
HAR	626	08/20	(Trn Cxld)		Downed Trees
HAR	646	08/20	13	13	PTC- Cutout due to unrecoverable penalty, 9634 CB CC, Roll away penalty on cc 9634. ACSES cut out.
HAR	654	08/20	(Trn Cxld)		Downed Trees
HAR	656	08/20	(Trn Cxld)		Downed Trees
HAR	658	08/20	(Trn Cxld)		Downed Trees
MIA	40	08/20	73	73	Service, turn, or wye train 04117, Late release from the yard due to late inbound.
NFK	94	08/20	1		
NFK	138	08/20	11	11	For maritime traffic Bridge still completely up at 12:54 departure time., Milepost, 1.23, 1.23
NHV	494	08/20	35	1	Service, turn, or wye train, 417
NHV	494	08/20	35	34	Service, turn, or wye train, 417
NYP	97	08/20	12	12	Water, commissary, toilet/trash dumping, LATE RELEASE F/SSYD A/C LATE SERVICING
NYP	185	08/20	2	2	Passenger and/or baggage, LOADING
NYP	291	08/20	4	4	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	639	08/20	(Trn Cxld)		Downed Trees
NYP	649	08/20	8	8	PTC - On Board Cab Signal or PTC Failure, 9634 CB CC, LATE DEPARTURE A/C CAB CAR FAILURE IN STATION
NYP	2103	08/20	2	2	Passenger and/or baggage, LOADING
PHL	110	08/20	4	2	Passenger and/or baggage
PHL	110	08/20	4	2	High passenger count
PHL	151	08/20	1	1	Passenger and/or baggage
PHL	190	08/20	1	1	Passenger and/or baggage
POR	684	08/20	2	2	Hold for bus with passengers from train
POR	688	08/20	1		
SPG	55	08/20	75	75	Service, turn, or wye train, 56, AM55 had to wye the train over CSX and BNE, hit multiple stops and had to do multiple break test
WAS	134	08/20	16	16	Other late crew, CREW ARRIVED LATE TO PLATFORM.

Amtrak Initial Terminal Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/20/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	172	08/20	3	3	Other electrical failure, 658 EX ES, DOOR LIGHT SHOWING, NECESSARY TO PUT IN BYPASS.
WAS	2102	08/20	3	3	Delay in Block, DELAY IN BLOCK. CREW REQUESTED PERMISSION TO THE SIGNAL
CHI	7	08/20	10	4	Service, turn, or wye train 8
CHI	7	08/20	10	6	Inability to contact dispatcher Start calling sign up time cp c and m dispatcher would not answer phone to markup order for 50 minutes and would not answer tone on channel 44 for engineer, Milepost, 0.0, 0.0
CHI	21	08/20	133	133	Late Release Late release of Both engines, 69
CHI	50	08/20	103	103	Service, turn, or wye train 51
CHI	59	08/20	11	11	Service, turn, or wye train 59
CHI	307	08/20	2	2	Late equipment into the station 307
FTW	822	08/20	6	6	Re-crew / job briefing Late job briefing due to receiving late GTB's
MKE	338	08/20	5	5	Service, turn, or wye train 335
PNT	355	08/20	3	1	FRA on property inspecting locomotive. Electrical cover over door needed to be secured before departure. ID4601
PNT	355	08/20	3	2	FRA on property inspecting cars. High low vestibule needed to be adjusted before departure between cars ID4305 and ID4009. ID4305, ID4009
BFD	703	08/20	189	189	Service, turn, or wye train 714
BFD	717	08/20	39	30	702 came in late, 702
BFD	717	08/20	39	9	Meet 710, Other, bfd depot
GTA	782	08/20	11	3	Meet 14, Control Point, CO 358
GTA	782	08/20	11	8	Investigating reports of fare evaders entering crew room at GTA per Train Master.
LAX	4	08/20	88	88	Service, turn, or wye train 4, Late arrival from 8th Street Yard
LAX	562	08/20	12	12	Last minute equipment swap with 564's equipment- spot time at lax at 0610 562
OKJ	520	08/20	22	22	Door C6961
OKJ	526	08/20	1	1	Reverser issue Consulting with TASI mechanical over reverser issue., JPBX921
OKJ	540	08/20	(Trn Cxld)		Third Party Engine Failure
OKJ	718	08/20	(Trn Cxld)	108	Third Party Engine Failure
PDX	28	08/20	101	101	Late arrival of 28 into PDX 27
SAC	539	08/20	21	21	Control Stan failed. Jpbx 921 921
SAC	541	08/20	(Trn Cxld)		Third Party Engine Failure
SEA	8	08/20	175	175	Service, turn, or wye train 007

Amtrak Initial Terminal Details

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/20/2026

Terminal	Train	Date	Late	Delay	Cause
SEA	511	08/20	18	18	Wait for train from yard 511, Waited for train to come from the yard after AMTK 8 and AMTK 14 arrived into SEA
SJC	528	08/20	9	9	PTC problem or failure (cause unknown) Other, SJC depot
SJC	530	08/20	1		

Eastern Region

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	84.5	83.1	90.2	58	9
SEPTA	95.0	95.3	95.1	91.5	190	9
NJT-NED	95.0	No Data	No Data	88.6	No Data	No Data
NJT-SED	95.0	100	99.2	97.2	24	0

Operating Highlights

Train 97(20) South of Fayetteville, NC - Vehicle Strike

21AUG26: Train 97(20) operating with engines 134, 326, 12 cars, and 231 customers onboard struck an occupied vehicle 18 miles south of Fayetteville, NC on the CSX South End subdivision at Crenshaw RD Crossing ID 629581S in Robeson County. The crossing was equipped with two advanced warnings, two roadway signs, two quad gate configuration, and two mast mounted flashing lights. The train did not lose headend power and the equipment was in tact and on the rails. No injuries were reported by the crew or customers onboard. The occupant of the vehicle was intoxicated and fled the scene. Train 52(20) held at Pembroke Interlocking milepost 243.6 until CSX dispatch gave clearance to proceed at restricted speed passed the incident site. A wrecker and track inspector were not needed on the scene. There was no reported damage to the equipment. Train 52(20) was released at 2:45 a.m. and train 97(20) was on the move at 3:37 a.m.

National Response Center Number: 1471403 Williams

Train	Delay	Comment
97(20)	1'46"	
53(20)	1'01"	

Train 53(20) North of Yemassee, SC - Signal

21AUG26: Train 53(20) operating with engines 360, 352, and 483 customers onboard was delayed 3 miles north of Yemassee, NC on the CSX Charleston subdivision holding at milepost 439.5 after going into a PTC penalty brake application. The crew inspected the equipment and took no exceptions.

Train	Delay	Comment
53(20)	40"	

Train 136(20) New Haven, CT - Engine Failure

21AUG26: Train 136(20) operating with engine 114, 8 cars, and 65 customers onboard was delayed departing New Haven, CT due to engine 114 arriving with water in the electrical closet causing mechanical issues. Engine 100 was worked up in New Haven Motor Storage and brought to the consist to replace engine 114.

Train	Delay	Comment
-------	-------	---------

Train 193(20) South of BWI, MD - Recrew

21AUG26: Train 193(20) was inbound with engine 658, 9 cars, and 305 customers onboard was delayed south of BWI Station holding at Carroll Interlocking for an 8910 crew to couple up to the train to proceed south due to the original crew on 193(20) expiring on hours of service.

Train	Delay	Comment
193 (20)	47"	

Train 245(20) South of Yonkers, NY - Tree Strike

21AUG26: Train 245(20) operating with engine 711, 5 cars, engine 93, and 97 customers onboard struck a tree at Inwood interlocking milepost 9.6 south of Yonker, NY on the Metro North Hudson Line. The crew reported no damage to equipment, injuries onboard, and took no exceptions.

Train	Delay	Comment
245 (20)	09"	

Train 494(20) New Haven, CT - Initial Terminal Delay

20AUG26: Train 494(20) was delayed departing New Haven, CT due to late turn of equipment from inbound 417(20).

Train	Delay	Comment
494 (20)	34"	

Train 175(20) New Haven, CT - Commuter Train Interference

20AUG26: Train 175(20) operating with engine 633, 10 cars, and 614 customers onboard was delayed after departing New Haven, CT following Metro North commuter traffic to Stamford, CT.

Train	Delay	Comment
175 (20)	47"	

Keystone Service - Amtrak PH Line - Tree in Catenary

20AUG26: At 4:50 p.m. 26-FOI-00703 was reported by Mount Joy Interlocking milepost 80.1 located 25 miles east of Harrisburg, PA. ET was on scene at 5:20 p.m. and investigate the scene. No catenary power was reported at 5:47 p.m. and trains 647, 654, and 649(20) were reported to have no headend power but were all in stations. 100hz power was off from State Interlocking milepost 104.6 to Thorn Interlocking milepost 35.0 causing Keystone service to be suspended pending an operational adjustment to service. Equipment was balanced for service the following day to ensure customers were not further inconvenienced. ET reported all catenary power was back, except for at Mount Joy where the tree was located, at approximately 7:00 p.m.

Service Adjustments:

- Train 639(20) was cancelled in its entirety with no alternate transportation.
- Train 622(20) was cancelled in its entirety with no alternate transportation.
- Train 656(20) was cancelled in its entirety with no alternate transportation.
- Trains 626, 658, 626(20) originated Philadelphia and was cancelled Harrisburg to Philadelphia.
- Trains 651, 653, 655, 657(20) terminated Philadelphia and were cancelled Philadelphia to Harrisburg.
- Train 654(20) originated Paoli and was cancelled Harrisburg to Paoli.

Alternate busing was provided from Harrisburg to Philadelphia and making rounds trips consisting of 3 buses. 1 bus was able to service from Philadelphia to Harrisburg. Customers on 649(20) and 654(20) were bused to final locations and buses performed full service due to the location of these two trains being unable to move within the loss of catenary.

At 4:20 a.m. Wilmington CETC approved PH Line is able to operate normal service with no further truncations or service adjustments for 08/21.

WBS#: B.TR.100150.7063

CSX Heat Orders - Weather

20AUG26: CSX has imposed heat orders in affect between 1pm - 7pm for the following subdivisions: Richmond Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah, South End, Tampa Terminal, and NO&M.

Train	Delay	Comment
40(19)	03"	
40(20)	33"	
41(18)	24"	
41(19)	22"	
52(20)	09"	
53(20)	10"	
79(20)	35"	
80(20)	13"	
89(20)	37"	
90(20)	28"	
97(19)	29"	
138(20)	05"	

Train 64(20) East of Buffalo, NY - Freight Train Interference

20AUG26: Train 64(20) was delayed 8 miles east of Buffalo between MP 420 and MP 378 due to freight train interference following CSX train. Once CSX cleared at ROC train 64(20) was able to proceed without further delay.

Train	Delay	Comment
64(20)	31"	

CFRC Signal System Outage - Signal

20AUG26: Multiple trains delayed on the northern end of the CFRC property between MP 787 and MP 813 due to damage to the signal system resulting from a work crew cutting the main signal wires. Trains operating over the affected territory were required to operate at restricted speed and confirm and hand line switches when necessary to establish routing for their trains. Once the trains exited the impacted area the trains were able to resume normal operating conditions.

Train	Delay	Comment
98(20)	2'32"	
97(19)	1'11"	
41(18)	47"	

Train 684(20) Exeter, NH - Trespasser Incident

20AUG26: Train 684(20) operating with locomotive 96, 4 cars, NPCU 90406, and 156 customers onboard was delayed 13 miles south of Exeter, NH at MP 88 on the CSX Portland subdivision after fatally striking a trespasser. This incident occurred in the city of Plaistow in the county of Rockingham and did not occur at a grade crossing. There were no reported injuries to crew or customers and there was no damage to equipment or infrastructure. An Amtrak Road Foreman responded to the scene and the onboard crew requested relief at the scene. A recrew reported to Portland and was transported to the location by an Amtrak Trainmaster. Once the crew was onboard and the scene was released by the local authorities the equipment was released and train 684(20) was able to proceed toward Haverhill.

The late operation of train 684(20) resulted in a late equipment turn and initial terminal delay to train 685(20).

Train 686(20) was held at Exeter Station for an open route past the location of the trespasser strike. The late operation of train 686(20) resulted in a late equipment turn and initial terminal delay to train 687(20).

National Response Center Number: 1471370

Train	Delay	Comment
686(20)	1'30"	
684(20)	3'03"	trespasser strike
687(20)	1'11"	initial terminal delay
685(20)	2'08"	initial terminal delay

Train 470(02) New Haven, CT - Passenger Related

20AUG26: Train 470(20) was delayed at the initial terminal of New Haven after holding for connecting customers from 170(20). Upon arrival of 170(20) the customers transferred and train 470(20) was able to depart.

Train	Delay	Comment
470(02)	34"	

Train 40(05) Miami, FL - Initial Terminal Delay

20AUG26: Train 40(20) operating with locomotives 305-136, 10 cars and 62 customers onboard was delayed at the initial terminal of Miami due to late arrival of inbound train 41(17) arriving at 2:55 am-et 8'46" late. After the equipment arrived the train was serviced and inspected and upon release from mechanical the equipment was positioned in the station for customer boarding.

Train	Delay	Comment
40(05)	1'13"	

Train 170(20) Stamford, CT - Engine Failure

20AUG26: Train 170(20) operating with locomotive 602, 4 cars and 507 customers onboard was delayed at MP33 Stamford Station on the MNRR New Haven Line due to an onboard hot journal alarm activation on E/602. The crew stopped at Stamford Station to inspect the equipment by utilizing a temple stick and took no exceptions with the condition of the axle allowing the train to proceed. Train 170(02) stopped a second time after the onboard system alarmed and the crew performed a second inspection and again took no exceptions. CNOC Mechanical and Siemens confirmed the cause of the system activation to be a failed sensor. NHV Mechanical responded and confirmed the sensor to be triggering the alarm. The equipment was able to proceed to the final destination of Boston without restrictions or further delays. Upon arrival into Boston, locomotive 602 was removed and shopped and replaced with locomotive 633 for the operation of train 175(20).

Train	Delay	Comment
170(20)	43"	

Train 646(20) Harrisburg, PA - Engine Failure

20AUG26: Train 646(20) operating with locomotive 669, 4 cars, cab car 9634 and 27 customers onboard was delayed at the initial terminal of Harrisburg due to ACSES failure on cab car 9634 requiring the crew to cut out the system to allow the train to proceed. As a result of th esystem being cut out the operating condition of the train required maximum authorized speeds of 79 MPH causing lost run time. Upon arrival into Philadelphia the locomotives were replaced due to previously reported pantograph dame to locomotive 669.

Upon arrival into New York the equipment was looped for the operation of train 649(20) to allow the motor to operate in the lead and the equipment was wye'd in Philadelphia again for operation to Harrisburg. The equipment turns were adjusted to allow the set to terminate in Philadelphia for correction.

Train	Delay	Comment
646(20)	13"	HAR initial terminal delay
646(20)	22"	PHL motor change
646(20)	10"	HAR-PHL
649(20)	33"	

Downeaster Service - CSX Trackwork - M of W Work - 8/17 - 8/20

28JUL26: CSX Portland, ME is scheduled to perform trackwork between Boston North station and Brunswick, ME MP BRU 5.0 to MP BRU 0.5 from Monday, August 17, 2026 to Thursday, August 20, 2026 from 7A-3P. The following service adjustments have been made:

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound:

- Train 681 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.
- Train 683 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 684 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 686 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 688 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3683 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, and 3688 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100151.0835

Train	Delay	Comment
686 (17)	32"	holding for buses por

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Train 8/28(19) East of Malta, MT - Freight Train Interference

21AUG26: Train 8/28(19) was delayed at Saco /MP316.3 on the BNSF Milk River Subdivision, 26.9 miles east of Malta, MT station due to meeting BN5188 and BN7904.

Train	Delay	Comment
8/28(19)	1'06"	

Train 3(19) West of Gallup, NM - Freight Train Interference

21AUG26: Train 3(19) was delayed at Coronado /MP214.9 on the BNSF Gallup Subdivision, 57.4 miles west of Gallup, NM station, due to meeting BN3891.

Train	Delay	Comment
3(19)	32"	

Train 28(20) East OF Wishram, WA - Freight Train Interference

21AUG26: Train 28(20) was delayed east of Wishram, WA on the BNSF Fallbridge Subdivision due to following BN4755 between MP151.6 and MP171.1.

Train	Delay	Comment
28(20)	31"	

Train 3(19) West of Winslow, AZ - System

21AUG26: Train 3(19) was delayed at Winslow/ MP286 on the BNSF Seligman Subdivision, 0.5 miles west of Winslow, AZ, due to waiting for BNSF pilots to arrive. The delay was prolonged due to the pilots getting stuck in traffic enroute due to a highway accident.

Train	Delay	Comment
3(19)	1'00"	

Train 14(19) North of Tacoma, WA - Near Miss

21AUG26: Train 14(19), E/318-E/350 & 9 cars, with 163 passengers, stopped in emergency north of Tacoma, WA at MP16.2, on the BNSF Seattle Subdivision, due to a near miss with a vehicle. There were no reported injuries to passengers or crew. Crew inspected consist and took no exceptions. Train 14(19) was on the move after crew performed a Class II brake test. APD notified.

Train	Delay	Comment
14(09)	10"	

Train 717(20) Terminated at Emeryville, CA - Vehicle on Tracks

21AUG26: Train 717(20) initially delayed at Emeryville, CA/ MP4.4 on the UPRR Martinez Subdivision due to a reported vehicle on the tracks at King St/ MP6.4. The vehicle was removed, but the estimated arrival time for the track inspector was an hour. In order to minimize passenger delay, the decision was made to terminate 717(20) at Emeryville, with one bus arranged for 13 passengers at Emeryville to accommodate them into Oakland. Due to this, Train 549(20) was also terminated at Emeryville, and all 13 affected passengers were also accommodated to Oakland on the same acquired bus. Train 14(20) was also delayed due to this.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
717(20)	Terminated	EMY
549(20)	Terminated	EMY
14(20)	16"	

Train 703(20) Fresno, CA - Vehicle on Tracks

21AUG26: Train 703(20) was delayed at Fresno, CA/ MP997.9 on the BNSF Stockton Subdivision, due to an initial hold on the track account of a vehicle reported on the tracks at MP999.06. The train was later given permission to operate restricted speeds by the area, and was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(20)	28"	

Train 595(20) West of San Diego, CA (OLT) - Signal

21AUG26: Train 595(20) was delayed at Cudahy/MP 262.25 on the SCRRA-NCTD San Diego Subdivision, 2 miles west of San Diego, CA (OLT) station due to a power switch failure. Train 588(20) and 790(20) were also delayed holding for repairs and train congestion due to this.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
595(20)	52"	
588(20)	49"	
790(20)	25"	

Train 58(20) South of Memphis, TN - Freight Train Interference

21AUG26: Train 58(20), operating with engines 48/320, 6 coaches was delayed 5 miles south of Memphis, TN, on CN Shelby subdivision, due to a BSNF freight being delayed entering the yard. There was a miscommunication between the Yard Master and the freight train that needed to be cleared up before the freight could proceed into the yard. Once the freight cleared train 58(20) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(20)	1'00"	

Train 6(19) Grand Junction, CO - Car Failure

20AUG26: Train 6(19), 26-EP-00703, 00000008738 engine UNCLASSIFIED 45/193, 3 coaches, and 157 customers, experienced HVAC-related issues shortly after departing Grand Junction (GJT), on UP Glenwood Springs subdivision. Coach 34065 was reported as a hot car, and sales to that car were closed while plans were made to have the equipment inspected in Denver (DEN). Shortly thereafter, the crew also reported that Lounge 33025 had become a hot car. At that time, the train was operating approximately 1 hour and 20 minutes late east of Glenwood Springs (GSC).

To help alleviate onboard conditions, one supplemental bus was arranged to be on site at Granby (GRA) at 4:30 PM MT to operate express to Denver. Union Pacific Railroad (UPRR) was advised of the planned hold at Granby for the bus connection. Contingency planning was also discussed should Denver mechanical forces be unable to correct the HVAC problems, with consideration given to handling the situation farther downline if necessary.

Upon arrival in Denver mechanical personnel met the train and worked to address the HVAC issues affecting Coach 34065 and Lounge 33025. Mechanical forces were able to restore HVAC service on the lower level of Coach 34065. In addition, available rooms in the crew dormitory car were identified and utilized to accommodate affected customers.

Following the mechanical inspection and repairs, Train 6(19) departed Denver at 9:07 PM MT. The train left Denver operating with an approximate delay of 1 hour and 10 minutes.

WBS#: B.TR.100150.7064

Train	Delay	Comment
6(19)	51"	

Train 25(20) - Freight Train Interference

21AUG26: Train 25(20), operating with engines 365/14, 3 coaches and 30 customers, was delayed east of New Orleans, LA, on NS NO&NE subdivision, due to meeting CSX205 and CSX67 at Control Point NOT JCT. Once the freight cleared and a route was made available, train 25(20) was able to proceed.

Train	Delay	Comment
25(20)	38"	

Train 6(20) East of Colfax, CA - Freight Train Interference

20AUG26: Train 6(20) was delayed at Gold Run/MP152.4 on the UPRR Roseville Subdivision, 10.5 miles east of Colfax, CA station, due to meeting freight unit UP 5876.

Train	Delay	Comment
6(20)	2'02"	

Train 27(18) - Freight Train Interference

20AUG26: Train 27(18) was delayed at Willbridge /MP4.1 on the BNSF Fallbridge Subdivision due to meeting BN 3856 that was blocking the main. Once a route was clear, Train 27(18) was able to proceed.

Train 11(20) was delayed at Portland, OR station/MP0.0 on the BNSF Fallbridge Subdivision due to holding for connecting Train 27(18) with 15 passengers connections, that arrived at 258PM-PT, 3 hours and 41 minutes late. Once connecting customers were onboard, train 11(20) was further delayed waiting for Train 14(19) to clear then was able to depart the station.

Train	Delay	Comment
-------	-------	---------

Train 41(20) East of Chicago, IL - Drawbridge Opening

21AUG26: Train 41(20), 26-FP-00703, 00000008758, UNCLASSIFIED, 310/4356, 9/2/2026, operating with engines 310/4356, 3 coaches, and 179 customers was delayed 11 miles east of Chicago, IL, on NS Chicago_76CD subdivision, due to drawbridge opening for maritime traffic. Once the maritime traffic cleared and the drawbridge was closed and locked, train 41(20) was able to proceed. Due to the congestion built up by the drawbridge opening train 41(20) was further delayed following NS freight between milepost 474 and milepost 438.

Train	Delay	Comment
41(20)	42"	Following Freight
41(20)	28"	Drawbridge Open

Train 4(20) Los Angeles, CA - Engine Failure

20AUG26: Train 4(20) E/194, E/53, E142, 9 cars, was delayed departing Los Angeles, CA due to a late release from the yard. The Mechanical team was working to resolve ATS issues on engine E/194. Unable to resolve, the decision was made to replace engine E/194 with E/23. Once the engine was replaced and consist made complete, the train proceeded to the station to load 93 customers prior to departure.

Train	Delay	Comment
4(20)	1'28"	

Train 26(20) East of New Orleans, LA - Freight Train Interference

21AUG26: Train 26(20), operating with engines 361/38, 3 coaches, and 48 customers, was delayed 17.5 miles east of New Orleans, LA, on CSX NO&M subdivision, due to meeting CSX 601 at Control Point Michoud.

Train	Delay	Comment
26(20)	32"	

Train 50(20) Chicago, IL - Initial Terminal Delay

21AUG26: Train 50(20) was delayed 1 hour and 43 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 51(19). Train 51(19) arrived in Chicago at 115pm; 2 hours and 50 minutes late due to a 20-minute initial terminal delay in New York, New York for routine inspections, 1 hour and 8 minutes for freight interference, 1 hour and 5 minutes for passenger train interference, 44 minutes for speed restrictions, and 27 minutes between Connerville, Indiana and Indianapolis, Indiana for restrictive signals on the CSX Indianapolis_BD Subdivision. Equipment set to the yard for servicing and inspection at 243pm. Scheduled program move(s) to hold the Beech Grove shippers, no replacements, and Washington section locomotive AMTK 130 for Train 48(20), replacing with trail locomotive AMTK 33 off inbound 6(18). The Beech Grove shippers and Washington locomotive AMTK 130 were removed at 325pm. At 341pm, amfleet coach 25079 was bad ordered for a tread brake unit to be replaced with C/25052 off inbound 40(18). Train 50(20) was made-up complete at 553pm. Train 50(20) was released by mechanical at 644pm, shoved from yard at 704pm, and set in the station at 711pm with 121 passengers to board. Train 50(20) departed Chicago at 738pm; 1 hour and 43 minutes late.

Train	Delay	Comment
50(20)	1'43"	

Train 822(20) North of Fort Worth, TX - Temporary Speed Restrictions

21AUG26: Train 822(20) at 00000008738 UNCLASSIFIED 55, 9/2/2026
26-FOI-00703 at 00000008738 UNCLASSIFIED 55, 9/2/2026
was delayed 8 miles north of Fort Worth, TX, on BNSF Ft. Worth subdivision, due to operating through BNSF slow orders from milepost 350 and milepost 358.9.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
822(20)	30"	

Train 59(20) Chicago, IL - Initial Terminal Delay

21AUG26: Train 59(20) was delayed 11 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 58(19). Train 58(19) arrived in Chicago at 152pm; 6 hours and 37 minutes late due to a 4 hour and 42-minute delay between Fulton, Kentucky and Carbondale, Illinois for tornado warnings, flash flood warnings and high wind warnings between milepost 380 and 320 on the Canadian National Centralia Subdivision, 40 minutes for a re-crew in Carbondale, Illinois, and 1 hour and 24 minutes for speed restrictions. Equipment was brought straight back to the yard for servicing and inspection at 250pm. Scheduled program move to hold locomotive AMTK 319 to Train 41(20), no replacement. Train 59(20) was released at 521pm and set in the station at 616pm with 161 passengers to board. Train 59(20) departed Chicago at 616pm; 11 minutes late. An additional 34-minute delay was incurred wyeing on departure due to a vehicle on the tracks on the BNSF Chicago Subdivision.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(20)	11"	ITI
59(20)	34"	Wye on Departure/ Vehicle on Tracks

Trains 541(20)/ 540(20) Cancelled - Third Party Contractor Engine Failure

20AUG26: Trains 541(20) and 540(20) were both cancelled in their entirety due to a control stand issue on engine JPBX921. Multiple troubleshooting attempts were made to fix the equipment prior to the cancellation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
540(20)	Cancelled	
541(20)	Cancelled	

Train 2(19) West of El Paso, TX - Freight Train Interference

21AUG26: At 1:47 PM CT, Union Pacific Railroad (UPRR) reported that train MHNPX-18 had derailed at El Paso. At the time of the report, details regarding the extent of the derailment were not available; however, it was confirmed that Main Track 1 (MT1) and Main Track 2 (MT2) were impacted by the incident. A route remained available through Main Track 6 (MT6), and the crew was qualified to operate over that territory, allowing for continued movement around the affected area while response and assessment efforts proceeded.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(19)	1'03"	

Train 7/27(18) Late Departure Chicago, IL - System

18AUG26: Train 7/27(18) with E/164-E/176 3 cars, 262 customers was delayed departing Chicago due to the late release of locomotives. E/164 came off train 58(17), which arrived Chicago at 1058AM-CT, 3 hours, and 43 minutes late. The trail locomotive E/176 came from the shop and was released at 139PM-CT. Once the equipment was made up, released, and set in the station, the customers were welcomed aboard, and 7/27(18) departed Chicago at 610PM-CT, 3 hours, and 5 minutes late.

Trains 8(20) and 28(20) were both late departing initial terminal, turning from late inbound 7(18) that arrived Seattle at 334P-PT and Train 27(18) that arrived Portland at 258P-PT.

Train	Delay	Comment
7/27(18)	3'05"	
28(20)	1'41"	
8(20)	2'55"	

Train 352(20) Chicago, IL - PTC Issues

20AUG26: Train 352(20), E/ID4633-5 Cars, was delayed at CP Lumber (MP1.34), on the Amtrak Chicago Line, due to PTC issues. Chicago Mechanical boarded the train and found it to be a software issue. Once PTC was successfully initialized, Train 352(20) was released to continue east.

Train	Delay	Comment
352(20)	1'37"	

Train 22(19) South of Alton, IL - M of W Work

21AUG26: Train 22(19), operating with engines 311/147, and 7 coaches was delayed 7 miles south of Alton, IL, on UP Springfield subdivision, due to MOW working at milepost 258.29.

Train	Delay	Comment
22(19)	33"	

Train 712(20) Modesto, CA - Engine Failure

20AUG26: Train 712(20) operating with CDTX 8303, 7 cars, CDTX 2014, and 125 customers onboard was stopped at Modesto, CA on the BNSF Stockton subdivision due to a loss of load on CDTX 2014. Crew attempted to troubleshoot the issue with TASI. Traction motor three was cut out. This was unsuccessful. The train then received a ground fault. The decision was made to terminate the train and couple to 714(20). Crew was able to load the engine and proceed to Merced/ MP1055.9 where the train was then terminated and coupled to Train 714(20). Once all safety checks were complete, the combined set proceeded towards Bakersfield.

This train was then further delayed east of Merced at MP1040.8 for police activity at MP1030.2. Once released, the train proceeded east operating 1 hour and 30 minutes late.

The turn of equipment, Train 703(20) was also delayed departing initial terminal Bakersfield, CA due to this.

WBS#: B.TR.100150.7060

Train	Delay	Comment
712(20)	1'54"	MOD
712/714(20)	39"	Police Hold
714(20)	35"	MCD - Coupling
703(20)	3'09"	ITD- Equip turn off 714

Train 353(20) West of New Buffalo, MI - M of W Work

20AUG26: Train 353(20) held 20.8 miles west of New Buffalo, MI (MP218.9), on the Amtrak Michigan Line due to NS Maintenance of Way personnel working within the limits of MP481 to MP486. The train remained stopped at Chesterton (MP239.7) until a route was established and was then released to continue to Chicago Union Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
353(20)	58"	

Train 713(20) Merced, CA - Engine Failure

20AUG26: Train 713(20) operating with CDTX 2102, 6 cars, and 104 customers onboard was stopped at Merced, CA on the BNSF Stockton subdivision due to losing main res air from an overheating air compressor. The crew worked with TASI to troubleshoot. The crew was instructed to hold for an hour to allow the engine to cool down. The attempt to allow the engine to cool down was unsuccessful and air was not able to be built or maintained. The train was coupled with Train 715(20) and towed to Oakland maintenance facility, terminating at Emeryville. All affected Emeryville passengers accommodated on to train 545(20) into Oakland. The turn of equipment, train 718(20) was originated late at Emeryville, all affected Oakland passengers to train 544(20) into Emeryville.

WBS#: B.TR.100150.7062

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
713(20)	Term MCD	
718(20)	1'49"	Originated EMY
715(20)	25"	

Train 504(20) East of Portland, OR - Police Related

20AUG26: Train 504(20) operating with WDTX 1401, 4 cars, and 134 customers onboard was delayed at milepost 3.8, 3 miles east of Portland, OR on the BNSF Fallbridge subdivision due to police hold on all of the tracks around Willbridge to look for a suspect. Once the police hold was lifted, Train 504(20) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
504(20)	37"	

Train 7(18) Wenatchee, WA - Engine Failure

20AUG26: Train 7(18) operating with engines BNSF 6783, 164, 6 cars, and 131 customers onboard was delayed at Wenatchee, WA on the BNSF Columbia River subdivision due to adding BNSF freight engine 7550 to the consist for fuel. Once the engine was added to the consist and all necessary tests were completed, Train 7(18) advanced into the station to complete the station work at Wenatchee.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7(18)	30"	

Train 14(19) Portland, OR - En Route Car Failure

20AUG26: Train 14(19) operating with engines 318, 350, 9 cars, and 205 customers onboard had to bad order car 34510 while enroute. The car was closed due to a report of biting ants infesting the car. The closure of the car created over capacity conditions between Portland, OR and Seattle, WA. A supplemental bus was secured to transport the passengers between Portland and Seattle. The car was treated in Seattle for the insects.

Train 58(20) South of Hammond, LA - Trespasser Incident

20AUG26: Train 58(20) held 16.1 miles south of Hammond, LA (MP859.1), on the CNRR McComb Subdivision, at Manchac (MP875.2) due to a reported semi truck broken down across both the main track and siding ahead. A wrecker responded to remove the semi, allowing operations to resume.

Train	Delay	Comment
58(20)	1'29"	

Train 21(20) Chicago, IL - Servicing

20AUG26: Train 21(20) was delayed 2 hours 13 minutes departing Chicago, Illinois account late road power. Leader E/69 was identified from the shop and trail E/68 identified from inbound Train 49(19). Leader E/69 was released from PM at approximately 10am and after repairing a sander defect, was dailied and released at 205pm. Train 49(19) arrived at 1133am, 1 hour 21 minutes late. The train was wyed and E/68 was set out and added to Train 21(20) at 142pm. The train was made up at 238pm and released at 328pm. The train was set in CUS at 341pm and began boarding 193 passengers. Train 21(20) departed CUS at 423pm, 2 hours 13 minutes late.

Train	Delay	Comment
21(20)	2'13"	

Train 318(20) Hermann, MO - Freight Train Interference

20AUG26: Train 318(20) was extensively delayed at Hermann, MO (MP81.1), on the UPRR Jefferson City Subdivision due to freight interference after MASNP-20 (UP8689) experienced a wrong-end drawbar failure ahead on Main Track 2, requiring the car to be set out and resulting in a lengthy delay. CBTWL9-18 (UP5435) was subsequently tied down on Main Track 1, with the recrew not expected onsite until after 4:00PM-CT. MASNP-20 ultimately recovered and cleared prior to the arrival of CBTWL9-18's recrew. Once a route was established, Train 318(20) was released to continue east. Once released train 318(20) first shoved west though the interlocking to transfer from track 1 to track 2 and then they proceeded east. Two buses were secured to Hermann with an estimated arrival of 6:30PM-CT; however, they were not utilized as the track was reopened prior to their arrival. Train 22(19) assisted Train 318(20) customers boarding between St. Louis and Chicago. Two supplemental downline buses were also secured, with Bus #1 operating express from Bloomington-Normal to Chicago and Bus #2 operating express from Springfield to Chicago. Train 319(20) was also delayed during this incident while holding at St. Louis, MO (MP1.5), on the TRRA Merchants Subdivision, awaiting confirmation of open track. 319(20)

WBS#: B.TR.100150.7061

Train	Delay	Comment
318(20)	3'37"	Holding at HEM
318(20)	55"	Holding East of HEM
319(20)	1'00"	Meeting 318(20)
319(20)	1'18"	Holding STL

Train 311(20) West of Jefferson City, MO - Passenger Train Interference

20AUG26: Train 311(20) held 16.4 miles west of Jefferson City, MO (MP125.5), on the UPRR Sedalia Subdivision, at Centertown (MP141.9) in order to meet Train 318(20).

Train	Delay	Comment
311(20)	30"	

Train 702(20) North of Stockton, CA - Freight Train Interference

20AUG26: Train 702(20) operating with engines BNSF 6862, 10000008738, CDTX 6862, 5 cars, CDTX 2002, and 88 customers onboard was delayed at milepost 79.8, 5 miles north of Stockton, CA on the UPRR Fresno subdivision due to BNSF freight train 7265 disabled ahead with an undesired emergency brake application. The freight crew inspected the equipment and found angle cocks turned incorrectly. The crew was able to troubleshoot the issue. Once the freight train was cleared, Train 702(20) advanced to the next station.

WBS#: B.TR.100150.7058

Train	Delay	Comment
702(20)	1'36"	
717(20)	39"	ITD -Equip turn

Train 7(18) West of Spokane, WA - Freight Train Interference

20AUG26: Train 7(18) operating with engines BNSF 6783, 164, 6 cars, and 130 customers onboard was delayed at milepost 1500.1, 20 miles west of Spokane, WA on the BNSF Columbia River subdivision due to meeting BNSF freight train 1785. The train was further delayed at milepost 1541.7 due to meeting BNSF freight train 5629. Once the freight trains cleared, Train 7(18) advanced to the next station.

Train	Delay	Comment
7(18)	10"	BNSF 1785
7(18)	35"	BNSF 5629

Train 4(18) East of Kansas City, MO - Freight Train Interference

20AUG26: Train 4(18) was delayed starting 6.9 miles east of Kansas City, MO (MP6.9), on the BNSF Marceline Subdivision, following BNSF 9115 from Congo (MP444.3) to Ethel (MP329.3).

Train	Delay	Comment
4(18)	30"	

Train 365(20) West of Flint, MI - Temporary Speed Restrictions

20AUG26: Train 365(20) was delayed between East Lansing, MI (MP223.8) and Battle Creek, MI (MP175.7) on the CNRR Flint Subdivision due to multiple temporary speed restrictions, requiring operation at reduced speeds between MP221.42 and MP184.79.

Train	Delay	Comment
365(20)	33"	

Train 2/422(19) West of Maricopa, AZ - Signal

20AUG26: Train 2/422(19) operating with engines 19, 310, 9 cars, and 211 customers onboard was delayed beginning at milepost 831.2, 66 miles west of Maricopa, AZ on the UPRR Gila subdivision due to signals dropping from Control Point Sentinel to Control Point West Piedra.

Train	Delay	Comment
2/422(19)	45"	

Train 58(19) and 59(19) North of Fulton, KY - Downed Trees

20AUG26: Train 58(19), with 133 customers, was delayed 24 miles north of Fulton, KY (MP404.6) on the CNRR Cairo Subdivision at MP380.6 due to 13 trees down across the tracks between MP380 and MP365. CN reported a tornado touched down in the area, resulting in the downed trees. CN Maintenance of Way crews were dispatched from both ends of the affected territory to clear the debris. Train 59(19), with 89 customers onboard, was also delayed while holding at MP375.4. Once the route was returned to service, Train 58(19) was the first train authorized through the area at restricted speed. After completing the meet with Train 58(19), Train 59(19) advanced to MP358.8 to meet northbound CN U763 and subsequently followed CN A432 until it was able to operate around the train at Wickliffe (MP369.9).

Due to the extensive delay, service recovery was enacted for both trains. Snack boxes, bottled water, muffins, and coffee cakes were distributed to all coach customers. Complimentary coffee and hot tea were made available in the café car, and breakfast service was extended in the dining car for all first-class customers.

Train 58(19) was further delayed at Carbondale, IL (MP 308.3) on the CNRR Centralia Subdivision while awaiting a fresh crew. The replacement crew came on duty at 7:50AM-CT, allowing the train to resume its movement.

Train 59(19) was further delayed at Memphis, TN (MP 391.8), on the CNRR Memphis Subdivision while awaiting a recrew Engineer to arrive at 11:00AM-CT.

WBS#: B.TR.100150.7056

Train	Delay	Comment
58(19)	40"	CDL - Fresh Crew
58(19)	4'51"	Trees Down
59(19)	2'57"	Trees Down / U763 / A432
59(19)	15"	MEM - Engineer Recrew

Coast Starlight UPRR Sacramento Sub Curfew- Detour TWA 26-090

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

B.TR.100151.0836

WBS#: B.TR.100151.0836

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

UPDATE 07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG.

UPDATE 18AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 28AUG.

Pere Marquette:

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.

and Chicago.

- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13), with 143 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(14), with 162 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(16), with 151 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(17), with 149 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(20), with 90 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(21), with 155 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(22), with 104 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(23), with 97 impacted customers, is cancelled entirely with 2 alternate buses secured between Grand Rapids and Chicago.
- Train 370(24), with 72 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(25), with 60 impacted customers, is cancelled entirely with 2 alternate buses secured between Grand Rapids and Chicago.
- Train 370(26), with 63 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(27), with 119 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.
- Train 305(25), with 61 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and St. Louis, MO.
- Train 300(26), with 95 impacted customers, is cancelled entirely with customer service still sourcing alternate busing.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(15), with 163 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(15), with 108 impacted customers, is cancelled entirely with 3 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(18), with 31 impacted customers, is cancelled entirely with no alternate transportation provided.
- Train 355(18), with 11 impacted customers, is cancelled entirely with no alternate transportation provided.

Quincy Service:

and Chicago IL.

- Train 381(14), with 22 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL

- Train 382(14), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.

- Train 381(17), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.

- Train 382(17), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.

- Train 381(21), with 15 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.

- Train 382(21), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.

- Train 383(23), with 95 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Quincy, IL.

- Train 380(24), with 47 impacted customers, is cancelled entirely with customer service still sourcing alternate busing.

- Train 383(27), with 41 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.

- Train 380(28), with 119 impacted customers, is cancelled entirely with customer service still sourcing alternate busing.

Saluki/Illini Service

- Train 391(12), with 54 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Carbondale, IL.

- Train 392(12), with 45 impacted customers, is cancelled entirely with 1 alternate buses secured between Carbondale, IL and Chicago, IL.

- Train 391(19), with 55 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Carbondale, IL.

- Train 392(19), with 18 impacted customers, is cancelled entirely with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task scheduled on C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		MU issues
22 (18)	XNT	315		I/O 47 faults
1340 (19)	XH8	150		Stuck brakes

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (20)	SEA	BNSF7550	E/164 B/O air compressor		
8 (19)	SEA	BNSF8205	E/196 bad air compressor		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00703

00000008738

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
41 (20)	CHI	41(20) WILL DEPART 1 COACH SHORT, DUE TO 25079 IN 50(20) BEING SHOPPED FOR BRAKES. INVENTORY HAS BEEN REDUCED WITH NO IMPACT TO PAX	n/a	0	
564 (20)	LAX	DUE TO EQUIPMENT CHANGE WILL BE OPERATING WITH 90225 IN CONSIST UNABLE TO ACCOMMODATE PASSENGER WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE PASSENGERS IMPACTED BY THIS.	no bv	3	90225
58 (20)	NOL	OPERATING W/O LOUNGE DUE TO 33004 SHOPPED FOR BRAKE ACTUATORY AND NO REPLACEMENT.	n/a	0	33004
197 (20)	NYP	biz class car being used in lieu of coach. no impact to ridership	no impact	0	81534
777 (20)	SAN	DUE TO EQUIPMENT CHANGE WILL BE OPERATING WITH 90225 IN CONSIST UNABLE TO ACCOMMODATE PASSENGER WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE PASSENGERS IMPACTED BY THIS.	no bv	3	90225
785 (21)	SAN	NO BIKE SPACE AVAILABLE DUE TO CONSIST HAVING CAR 90225.	n/a	0	90225
774 (21)	SLO	NO BIKE SPACE AVAILABLE DUE TO CONSIST HAVING CAR 90225.	n/a	0	90225
134 (20)	WAS	biz class car being used in lieu of coach. no impact to ridership	no impact	0	81534

Reverse Consists

Train Number	Station	Reason
2151 (20)	BOS	Acela consist reversed First class at Rear
131 (20)	NYP	Consist reversed Business class seat orientation may have changed At Rear
190 (20)	PHL	Consist reversed Business class seat orientation may have changed At Front
95 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00703	00000008738 "UNCLASSIFIED" 9/2/2026
85 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front	
136 (20)	WAS	Consist reversed Business class seat orientation may have changed At Front	
86 (21)	NPN	Consist reversed Business class seat orientation may have changed At Front.. **Train 86(21)**	
86 (21)	NPN	Consist reversed Business class seat orientation may have changed At Front.. **train 86(21)**	
84 (20)	WAS	Consist reversed Business class seat orientation may have changed At Front	
193 (20)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
137 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front	
138 (21)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 138(21)**	
174 (20)	WAS	Consist reversed Business class seat orientation may have changed At Front	
113 (20)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
148 (20)	SPG	Consist reversed Business class seat orientation may have changed At Front	
141 (21)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 141(21)**	
175 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front	
175 (20)	BOS	Consist reversed Business class seat orientation may have changed At Rear	