

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, January 02, 2026

Rules: 0-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/01/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	269	47	82.5%	269	47	82.5%	27,575	3,725	86.5%
Central Division	85.5%	66	10	84.8%	66	10	84.8%	6,148	677	89.0%
Northeast Division	80.0%	83	14	83.1%	83	14	83.1%	8,699	1,295	85.1%
Southeast Division	72.5%	56	9	83.9%	56	9	83.9%	6,403	890	86.1%
Southwest Division	77.0%	64	14	78.1%	64	14	78.1%	6,325	863	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00217 00000005557 "UNCLASSIFIED" 1/5/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	75,926	19,989	74%	75,926	19,989	74%	9,400,860	2,059,575	78%
Northeast Corridor	81%	31,734	8,558	73%	31,734	8,558	73%	4,199,666	888,174	79%
Acela	83%	4,845	1,112	77%	4,845	1,112	77%	888,634	212,159	76%
Northeast Regional	79%	26,889	7,446	72%	26,889	7,446	72%	3,311,032	676,015	80%
Richmond / Newport News / Norfolk	77%	9,898	1,976	80%	9,898	1,976	80%	1,012,151	235,064	77%
Springfield Shuttles	89%	430	69	84%	430	69	84%	60,149	6,757	89%
Roanoke	79%	2,461	894	64%	2,461	894	64%	255,812	43,739	83%
On Spine Northeast Regional	80%	14,100	4,507	68%	14,100	4,507	68%	1,982,920	390,455	80%
State Supported	80%	32,610	6,732	79%	32,610	6,732	79%	4,017,101	772,180	81%
Borealis	60%	536	0	100%	536	0	100%	54,493	13,893	75%
Capitol Corridor	90%	1,959	186	91%	1,959	186	91%	323,056	34,101	89%
Carolinian	60%	958	0	100%	958	0	100%	108,188	30,349	72%
Cascades	63%	2,304	445	81%	2,304	445	81%	222,977	52,813	76%
Downeaster	82%	1,140	0	100%	1,140	0	100%	136,012	17,582	87%
Empire	78%	5,129	1,874	63%	5,129	1,874	63%	500,609	105,938	79%
Adirondack	72%	412	252	39%	412	252	39%	31,512	11,779	63%
Ethan Allen Express	70%	611	128	79%	611	128	79%	55,149	16,334	70%
Maple Leaf	70%	716	447	38%	716	447	38%	59,101	25,722	56%
New York - Albany	85%	2,104	508	76%	2,104	508	76%	227,236	30,714	86%
New York - Niagara Falls	75%	1,286	539	58%	1,286	539	58%	127,611	21,389	83%
Gold Runner	73%	1,832	672	63%	1,832	672	63%	235,214	85,805	64%
Heartland Flyer	65%	185	0	100%	185	0	100%	19,686	8,293	58%
Hiawatha	90%	1,072	43	96%	1,072	43	96%	160,700	19,645	88%
Illinois	78%	1,785	269	85%	1,785	269	85%	226,024	65,382	71%
Carl Sandburg / Illinois Zephyr	85%	412	0	100%	412	0	100%	39,423	10,265	74%
Illini / Saluki	85%	701	0	100%	701	0	100%	78,696	21,222	73%
Lincoln Service	70%	672	269	60%	672	269	60%	107,905	33,895	69%
Keystone	92%	4,653	246	95%	4,653	246	95%	755,098	74,814	90%
Lincoln / Missouri	60%	790	60	92%	790	60	92%	73,365	35,328	52%
Mardi Gras Service	80%	407	0	100%	407	0	100%	40,049	4,679	88%
Michigan	69%	1,658	1,005	39%	1,658	1,005	39%	183,077	56,385	69%
Blue Water	70%	332	170	49%	332	170	49%	44,848	13,814	69%
Pere Marquette	85%	235	143	39%	235	143	39%	24,716	4,462	82%
Wolverine	65%	1,091	692	37%	1,091	692	37%	113,513	38,109	66%
Missouri	80%	205	0	100%	205	0	100%	22,533	5,035	78%
Pacific Surfliner	85%	4,944	1,619	67%	4,944	1,619	67%	624,459	90,699	85%
Pennsylvanian	72%	856	0	100%	856	0	100%	86,662	9,220	89%
Piedmont	73%	957	90	91%	957	90	91%	119,660	27,778	77%
Vermont	75%	1,240	223	82%	1,240	223	82%	125,239	34,441	72%
Long Distance	56%	11,582	4,699	59%	11,582	4,699	59%	1,180,653	398,954	66%
Auto Train	57%	918	0	100%	918	0	100%	64,785	10,771	83%
California Zephyr	50%	1,122	186	83%	1,122	186	83%	87,771	24,928	72%
Cardinal	55%	289	105	64%	289	105	64%	25,860	11,431	56%
City Of New Orleans	75%	506	45	91%	506	45	91%	66,225	14,454	78%
Coast Starlight	60%	1,111	914	18%	1,111	914	18%	110,630	35,704	68%
Crescent	70%	723	51	93%	723	51	93%	90,828	21,036	77%
Empire Builder	55%	1,166	1,166	0%	1,166	1,166	0%	96,005	37,611	61%
Floridian	40%	1,580	861	46%	1,580	861	46%	161,032	88,317	45%
Lake Shore Ltd	73%	755	578	23%	755	578	23%	91,403	20,005	78%
Palmetto	65%	788	2	100%	788	2	100%	90,302	15,219	83%
Silver Meteor	45%	858	396	54%	858	396	54%	97,478	31,337	68%
Southwest Chief	40%	846	39	95%	846	39	95%	77,690	46,340	40%
Sunset Ltd	70%	0	0	-	0	0	-	26,771	6,164	77%
Texas Eagle	50%	920	356	61%	920	356	61%	93,873	35,637	62%
Seasonal Trains	%	0	0	-	0	0	-	3,440	267	92%
Winter Park Express	75%	0	0	-	0	0	-	3,440	267	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00217 00000005557 "UNCLASSIFIED" 1/5/2020

Train Index Dates Through January 01, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	4,025	99,323	405	532,257	9,959,714	534

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	138	25,142	55	20,910	2,907,118	72
INFRASTRUCTURE PLANNED	135	64	25,142	25	15,439	2,907,118	53
FLEET RELIABILITY	90	1,079	99,323	109	83,937	9,959,714	84
TRAIN OPERATIONS	424	2,744	99,323	276	411,971	9,959,714	414

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/01/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	269	47	82.5%	269	47	82.5%	27,575	3,725	86.5%
Central Division	85.5%	66	10	84.8%	66	10	84.8%	6,148	677	89.0%
Northeast Division	80.0%	83	14	83.1%	83	14	83.1%	8,699	1,295	85.1%
Southeast Division	72.5%	56	9	83.9%	56	9	83.9%	6,403	890	86.1%
Southwest Division	77.0%	64	14	78.1%	64	14	78.1%	6,325	863	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/01/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	269	47	82.5%	269	47	82.5%	27,575	3,725	86.5%
Central Division	85.5%	66	10	84.8%	66	10	84.8%	6,148	677	89.0%
CDL	90.0%	2	0	100.0%	2	0	100.0%	157	8	94.9%
CHI	85.0%	27	3	88.9%	27	3	88.9%	2,493	282	88.7%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	-	-	-	6	2	66.7%
EUG	86.5%	2	0	100.0%	2	0	100.0%	180	26	85.6%
GRR	98.0%	1	0	100.0%	1	0	100.0%	92	3	96.7%
KCY	84.5%	2	1	50.0%	2	1	50.0%	183	16	91.3%
MKE	86.5%	5	0	100.0%	5	0	100.0%	542	46	91.5%
MSP	94.0%	1	0	100.0%	1	0	100.0%	93	3	96.8%
PDX	78.0%	5	1	80.0%	5	1	80.0%	466	62	86.7%
PNT	91.5%	3	1	66.7%	3	1	66.7%	221	23	89.6%
PTH	93.0%	1	1	0.0%	1	1	0.0%	92	8	91.3%
QCY	87.5%	2	0	100.0%	2	0	100.0%	186	17	90.9%
SEA	80.0%	8	3	62.5%	8	3	62.5%	739	122	83.5%
SPK	92.0%	1	-	100.0%	1	-	100.0%	96	5	94.8%
STL	88.0%	4	0	100.0%	4	0	100.0%	367	38	89.6%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	2	0	100.0%	181	6	96.7%
WIP	-	-	-	-	-	-	-	6	0	100.0%
Northeast Division	80.0%	83	14	83.1%	83	14	83.1%	8,699	1,295	85.1%
ALB	91.5%	8	1	87.5%	8	1	87.5%	623	47	92.5%
BON	43.5%	5	0	100.0%	5	0	100.0%	446	44	90.1%
BOS	86.5%	15	4	73.3%	15	4	73.3%	1,695	213	87.4%
BRK	88.0%	5	1	80.0%	5	1	80.0%	426	21	95.1%
BTN	48.0%	1	0	100.0%	1	0	100.0%	92	18	80.4%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	2	1	50.0%	178	16	91.0%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	1	0	100.0%	93	17	81.7%
NFL	96.5%	2	0	100.0%	2	0	100.0%	187	8	95.7%
NHV	75.5%	4	1	75.0%	4	1	75.0%	483	82	83.0%
NYP	77.5%	32	5	84.4%	32	5	84.4%	3,660	768	79.0%
SAB	98.0%	1	0	100.0%	1	0	100.0%	91	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	0	100.0%	6	0	100.0%	567	24	95.8%
TWO	84.0%	1	1	0.0%	1	1	0.0%	91	20	78.0%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	56	9	83.9%	56	9	83.9%	6,403	890	86.1%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	5	0	100.0%	465	37	92.0%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	7	5	28.6%	7	5	28.6%	1,036	195	81.2%
LOR	69.5%	1	0	100.0%	1	0	100.0%	93	9	90.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/01/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	269	47	82.5%	269	47	82.5%	27,575	3,725	86.5%
Southeast Division	72.5%	56	9	83.9%	56	9	83.9%	6,403	890	86.1%
MIA	87.5%	2	0	100.0%	2	0	100.0%	186	19	89.8%
MOE	94.0%	2	0	100.0%	2	0	100.0%	186	3	98.4%
NFK	86.0%	3	0	100.0%	3	0	100.0%	261	28	89.3%
NOL	92.0%	4	0	100.0%	4	0	100.0%	411	20	95.1%
NPN	96.0%	2	0	100.0%	2	0	100.0%	161	10	93.8%
PGH	92.0%	1	0	100.0%	1	0	100.0%	93	3	96.8%
PHL	45.0%	4	2	50.0%	4	2	50.0%	427	219	48.7%
RGH	97.0%	4	0	100.0%	4	0	100.0%	368	9	97.6%
RNK	85.5%	2	1	50.0%	2	1	50.0%	185	22	88.1%
RVM	86.0%	1	0	100.0%	1	0	100.0%	103	13	87.4%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	1	0	100.0%	93	2	97.8%
SFA	70.5%	1	0	100.0%	1	0	100.0%	93	3	96.8%
WAS	70.0%	16	1	93.8%	16	1	93.8%	2,234	293	86.9%
Southwest Division	77.0%	64	14	78.1%	64	14	78.1%	6,325	863	86.4%
ARN	60.5%	1	0	100.0%	1	0	100.0%	93	7	92.5%
BFD	75.5%	7	1	85.7%	7	1	85.7%	559	136	75.7%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	1	0	100.0%	100	36	64.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	1	0	100.0%	92	3	96.7%
GTA	72.5%	3	0	100.0%	3	0	100.0%	272	25	90.8%
LAX	77.5%	9	1	88.9%	9	1	88.9%	861	93	89.2%
OKC	96.0%	1	0	100.0%	1	0	100.0%	93	3	96.8%
OKJ	79.0%	8	3	62.5%	8	3	62.5%	1,007	246	75.6%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	11	2	81.8%	11	2	81.8%	1,228	132	89.3%
SAN	77.0%	12	5	58.3%	12	5	58.3%	1,069	96	91.0%
SAS	85.0%	1	0	100.0%	1	0	100.0%	93	4	95.7%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	7	1	85.7%	649	60	90.8%
SLO	62.0%	2	1	50.0%	2	1	50.0%	180	16	91.1%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		1	0	100.0%	93	12	87.1%	1	0	100.0%	92	36	60.9%
4		1	0	100.0%	92	14	84.8%	1	0	100.0%	92	59	35.9%
5		1	0	100.0%	92	15	83.7%	1	0	100.0%	90	13	85.6%
6		1	0	100.0%	91	29	68.1%	1	0	100.0%	91	27	70.3%
7		1	0	100.0%	93	10	89.2%	1	0	100.0%	89	15	83.1%
8	91	1	1	0.0%	93	40	57.0%	1	1	0.0%	93	46	50.5%
11		1	1	0.0%	92	19	79.3%	1	0	100.0%	90	15	83.3%
14	111	1	0	100.0%	93	10	89.2%	1	1	0.0%	92	22	76.1%
19		1	0	100.0%	93	18	80.6%	1	0	100.0%	93	13	86.0%
20		1	0	100.0%	93	6	93.5%	1	0	100.0%	93	8	91.4%
21		1	0	100.0%	92	13	85.9%	1	0	100.0%	92	18	80.4%
22	41	1	0	100.0%	93	4	95.7%	1	1	0.0%	92	20	78.3%
23		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	13	86.0%
24		1	0	100.0%	93	7	92.5%	1	0	100.0%	93	9	90.3%
25		1	0	100.0%	93	0	100.0%	1	0	100.0%	93	10	89.2%
26		1	0	100.0%	93	2	97.8%	1	0	100.0%	93	14	84.9%
27		1	1	0.0%	93	4	95.7%	1	0	100.0%	92	20	78.3%
28		1	0	100.0%	92	20	78.3%	1	0	100.0%	92	12	87.0%
40	38	1	0	100.0%	93	14	84.9%	1	1	0.0%	93	35	62.4%
41	193	1	0	100.0%	93	33	64.5%	1	1	0.0%	93	59	36.6%
42		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	12	87.1%
43		1	0	100.0%	93	8	91.4%	1	0	100.0%	93	4	95.7%
48		1	0	100.0%	93	13	86.0%	1	0	100.0%	93	10	89.2%
49	155	1	0	100.0%	93	14	84.9%	1	1	0.0%	93	14	84.9%
51		0	0	0.0%	40	18	55.0%	1	0	100.0%	39	12	69.2%
52		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	14	84.9%
53		1	0	100.0%	93	9	90.3%	1	0	100.0%	93	13	86.0%
54		1	0	100.0%	29	0	100.0%	1	0	100.0%	29	4	86.2%
57		1	0	100.0%	29	1	96.6%	1	0	100.0%	29	1	96.6%
58		1	0	100.0%	92	3	96.7%	1	0	100.0%	91	14	84.6%
59		1	0	100.0%	91	7	92.3%	1	0	100.0%	91	9	90.1%
63		1	0	100.0%	93	39	58.1%	1	0	100.0%	92	48	47.8%
64		1	1	0.0%	92	21	77.2%	1	0	100.0%	92	21	77.2%
65		0	0	0.0%	29	5	82.8%	1	0	100.0%	29	7	75.9%
66	47	1	1	0.0%	93	14	84.9%	1	1	0.0%	93	20	78.5%
68	29	1	0	100.0%	93	17	81.7%	1	1	0.0%	93	47	49.5%
69		1	0	100.0%	93	11	88.2%	1	0	100.0%	93	13	86.0%
71		1	0	100.0%	93	1	98.9%	1	0	100.0%	93	24	74.2%
72		1	0	100.0%	93	10	89.2%	1	0	100.0%	93	23	75.3%
73		1	0	100.0%	93	3	96.8%	1	0	100.0%	92	44	52.2%
74		1	0	100.0%	93	7	92.5%	1	0	100.0%	93	25	73.1%
75		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	39	58.1%

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	20	1	0	100.0%	93	4	95.7%	1	1	0.0%	93	36	61.3%
77		1	0	100.0%	93	4	95.7%	1	0	100.0%	93	31	66.7%
78		1	0	100.0%	93	5	94.6%	1	0	100.0%	93	12	87.1%
79		1	0	100.0%	93	21	77.4%	1	0	100.0%	92	15	83.7%
80		1	0	100.0%	93	11	88.2%	1	0	100.0%	92	10	89.1%
82		1	0	100.0%	15	0	100.0%	1	0	100.0%	15	1	93.3%
87		1	0	100.0%	29	6	79.3%	1	0	100.0%	29	5	82.8%
88		1	0	100.0%	29	1	96.6%	1	0	100.0%	29	4	86.2%
89		1	0	100.0%	93	18	80.6%	1	0	100.0%	93	15	83.9%
90		1	0	100.0%	93	2	97.8%	1	0	100.0%	93	9	90.3%
97	76	1	0	100.0%	93	41	55.9%	1	1	0.0%	93	20	78.5%
98		1	0	100.0%	93	5	94.6%	1	0	100.0%	93	24	74.2%
99		1	0	100.0%	29	2	93.1%	1	0	100.0%	28	12	57.1%
101		1	0	100.0%	15	1	93.3%	1	0	100.0%	15	0	100.0%
103	47	1	1	0.0%	29	4	86.2%	1	1	0.0%	29	2	93.1%
106		1	0	100.0%	29	2	93.1%	1	0	100.0%	29	3	89.7%
107		1	0	100.0%	29	6	79.3%	1	0	100.0%	29	2	93.1%
118		1	0	100.0%	29	2	93.1%	1	0	100.0%	29	2	93.1%
123		1	0	100.0%	15	0	100.0%	1	0	100.0%	15	0	100.0%
124		1	0	100.0%	29	2	93.1%	1	0	100.0%	29	4	86.2%
135	163	1	1	0.0%	29	6	79.3%	1	1	0.0%	29	15	48.3%
136		0	0	0.0%	64	7	89.1%	1	0	100.0%	65	5	92.3%
140		1	0	100.0%	29	2	93.1%	1	0	100.0%	29	6	79.3%
142		1	0	100.0%	15	0	100.0%	1	0	100.0%	15	0	100.0%
143		1	0	100.0%	29	2	93.1%	1	0	100.0%	29	3	89.7%
144	94	1	1	0.0%	16	9	43.8%	1	1	0.0%	16	1	93.8%
146	52	1	0	100.0%	29	5	82.8%	1	1	0.0%	29	10	65.5%
147		1	0	100.0%	15	3	80.0%	1	0	100.0%	15	2	86.7%
150	43	1	0	100.0%	29	22	24.1%	1	1	0.0%	29	20	31.0%
151		1	0	100.0%	93	30	67.7%	1	0	100.0%	92	25	72.8%
152		1	0	100.0%	15	0	100.0%	1	0	100.0%	15	4	73.3%
153		1	0	100.0%	29	2	93.1%	1	0	100.0%	29	3	89.7%
155		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	4	86.2%
156		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	5	82.8%
158		1	0	100.0%	29	0	100.0%	1	0	100.0%	29	1	96.6%
159		1	0	100.0%	15	1	93.3%	1	0	100.0%	15	0	100.0%
160	41	1	0	100.0%	29	0	100.0%	1	1	0.0%	27	5	81.5%
161	59	1	0	100.0%	29	1	96.6%	1	1	0.0%	29	16	44.8%
162	22	1	0	100.0%	29	2	93.1%	1	1	0.0%	29	12	58.6%
163	82	1	0	100.0%	15	2	86.7%	1	1	0.0%	15	9	40.0%
164		1	0	100.0%	29	4	86.2%	1	0	100.0%	29	9	69.0%
165	71	1	1	0.0%	29	9	69.0%	1	1	0.0%	29	9	69.0%

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
168	105	1	0	100.0%	15	2	86.7%	1	1	0.0%	15	5	66.7%
178		0	0	0.0%	64	10	84.4%	1	0	100.0%	65	9	86.2%
179		0	0	0.0%	64	6	90.6%	1	0	100.0%	65	14	78.5%
194		1	0	100.0%	15	3	80.0%	1	0	100.0%	15	2	86.7%
195	64	1	0	100.0%	29	0	100.0%	1	1	0.0%	29	20	31.0%
232		1	0	100.0%	93	2	97.8%	1	0	100.0%	93	6	93.5%
233	139	1	0	100.0%	93	24	74.2%	1	1	0.0%	93	21	77.4%
234		1	0	100.0%	93	4	95.7%	1	0	100.0%	93	3	96.8%
235		1	0	100.0%	32	5	84.4%	1	0	100.0%	32	6	81.3%
236		1	0	100.0%	93	1	98.9%	1	0	100.0%	93	16	82.8%
237	50	1	0	100.0%	92	15	83.7%	1	1	0.0%	91	8	91.2%
238		1	0	100.0%	32	6	81.3%	1	0	100.0%	32	3	90.6%
239		1	0	100.0%	92	24	73.9%	1	0	100.0%	92	4	95.7%
240		1	0	100.0%	93	9	90.3%	1	0	100.0%	93	12	87.1%
241		1	0	100.0%	93	24	74.2%	1	0	100.0%	93	14	84.9%
244		1	0	100.0%	93	5	94.6%	1	0	100.0%	93	18	80.6%
280		1	0	100.0%	93	4	95.7%	1	0	100.0%	93	17	81.7%
281	61	1	0	100.0%	93	9	90.3%	1	1	0.0%	93	11	88.2%
283		1	0	100.0%	93	20	78.5%	1	0	100.0%	93	15	83.9%
284		1	0	100.0%	93	3	96.8%	1	0	100.0%	92	7	92.4%
290		1	0	100.0%	93	19	79.6%	1	0	100.0%	92	31	66.3%
291		1	0	100.0%	93	18	80.6%	1	0	100.0%	93	15	83.9%
300		1	0	100.0%	93	10	89.2%	1	0	100.0%	92	25	72.8%
301		1	0	100.0%	91	2	97.8%	1	0	100.0%	90	16	82.2%
302		1	0	100.0%	90	11	87.8%	1	0	100.0%	88	27	69.3%
305	35	1	1	0.0%	93	13	86.0%	1	1	0.0%	91	36	60.4%
306	No OS	1	0	100.0%	91	6	93.4%	1	1	0.0%	90	21	76.7%
307		1	1	0.0%	92	12	87.0%	1	0	100.0%	91	20	78.0%
311		1	0	100.0%	92	10	89.1%	1	0	100.0%	91	20	78.0%
316		1	0	100.0%	91	5	94.5%	1	0	100.0%	91	18	80.2%
318		1	1	0.0%	93	12	87.1%	1	0	100.0%	92	37	59.8%
319		1	0	100.0%	93	4	95.7%	1	0	100.0%	93	48	48.4%
331		1	0	100.0%	93	11	88.2%	1	0	100.0%	93	14	84.9%
332		1	0	100.0%	93	9	90.3%	1	0	100.0%	93	16	82.8%
334		1	0	100.0%	93	2	97.8%	1	0	100.0%	92	12	87.0%
335		1	0	100.0%	93	14	84.9%	1	0	100.0%	91	17	81.3%
336		1	0	100.0%	93	4	95.7%	1	0	100.0%	93	5	94.6%
337		1	0	100.0%	93	5	94.6%	1	0	100.0%	93	12	87.1%
338		1	0	100.0%	93	21	77.4%	1	0	100.0%	91	22	75.8%
339		1	0	100.0%	93	20	78.5%	1	0	100.0%	93	19	79.6%
341	Cncld	1	0	100.0%	90	16	82.2%	0	0	0.0%	88	14	84.1%
342	Cncld	1	0	100.0%	93	8	91.4%	0	0	0.0%	91	16	82.4%

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
350	41	1	1	0.0%	75	4	94.7%	1	1	0.0%	75	42	44.0%
351		1	1	0.0%	93	14	84.9%	1	0	100.0%	93	38	59.1%
352	35	1	0	100.0%	93	7	92.5%	1	1	0.0%	90	27	70.0%
353		1	0	100.0%	72	5	93.1%	1	0	100.0%	72	16	77.8%
354	20	1	0	100.0%	93	8	91.4%	1	1	0.0%	91	29	68.1%
355	48	1	0	100.0%	92	9	90.2%	1	1	0.0%	91	26	71.4%
364		1	0	100.0%	92	17	81.5%	1	0	100.0%	91	20	78.0%
365	69	1	1	0.0%	92	8	91.3%	1	1	0.0%	91	29	68.1%
370	19	1	0	100.0%	93	5	94.6%	1	1	0.0%	93	17	81.7%
371		1	0	100.0%	92	3	96.7%	1	0	100.0%	92	11	88.0%
380		1	0	100.0%	93	15	83.9%	1	0	100.0%	93	21	77.4%
381		1	0	100.0%	93	2	97.8%	1	0	100.0%	93	11	88.2%
382		1	0	100.0%	93	2	97.8%	1	0	100.0%	93	23	75.3%
383		1	0	100.0%	93	9	90.3%	1	0	100.0%	91	36	60.4%
390		1	0	100.0%	77	9	88.3%	1	0	100.0%	76	25	67.1%
391		1	0	100.0%	78	2	97.4%	1	0	100.0%	76	15	80.3%
392		1	0	100.0%	93	4	95.7%	1	0	100.0%	92	28	69.6%
393		1	0	100.0%	93	7	92.5%	1	0	100.0%	92	25	72.8%
400		1	0	100.0%	27	2	92.6%	1	0	100.0%	26	1	96.2%
405		1	0	100.0%	25	0	100.0%	1	0	100.0%	25	2	92.0%
448	140	1	1	0.0%	34	14	58.8%	1	1	0.0%	32	13	59.4%
449		1	0	100.0%	31	1	96.8%	1	0	100.0%	31	5	83.9%
450		1	0	100.0%	26	8	69.2%	1	0	100.0%	26	8	69.2%
460	26	2	2	0.0%	28	14	50.0%	1	1	0.0%	25	8	68.0%
461		1	0	100.0%	28	3	89.3%	1	0	100.0%	28	1	96.4%
463		1	0	100.0%	14	1	92.9%	1	0	100.0%	14	0	100.0%
464		1	0	100.0%	26	4	84.6%	1	0	100.0%	26	8	69.2%
467		1	0	100.0%	14	1	92.9%	1	0	100.0%	13	0	100.0%
488	Cncld	1	1	0.0%	29	8	72.4%	0	0	0.0%	25	4	84.0%
499	Cncld	1	1	0.0%	26	4	84.6%	0	0	0.0%	25	2	92.0%
500		1	0	100.0%	93	6	93.5%	1	0	100.0%	92	10	89.1%
502	Cncld	1	1	0.0%	93	8	91.4%	0	0	0.0%	91	21	76.9%
503		1	0	100.0%	90	11	87.8%	1	0	100.0%	89	22	75.3%
504	28	1	0	100.0%	93	8	91.4%	1	1	0.0%	92	26	71.7%
505		1	0	100.0%	93	16	82.8%	1	0	100.0%	91	17	81.3%
506		1	0	100.0%	92	14	84.8%	1	0	100.0%	91	13	85.7%
507		1	1	0.0%	93	12	87.1%	1	0	100.0%	93	32	65.6%
508		1	0	100.0%	91	20	78.0%	1	0	100.0%	91	22	75.8%
509		1	0	100.0%	93	7	92.5%	1	0	100.0%	93	25	73.1%
511		1	0	100.0%	93	10	89.2%	1	0	100.0%	93	17	81.7%
516		1	0	100.0%	91	9	90.1%	1	0	100.0%	91	38	58.2%
517		1	0	100.0%	93	2	97.8%	1	0	100.0%	92	31	66.3%

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
518	118	1	0	100.0%	93	13	86.0%	1	1	0.0%	93	55	40.9%
519	41	1	0	100.0%	91	4	95.6%	1	1	0.0%	91	15	83.5%
562	Cncld	1	0	100.0%	91	11	87.9%	0	0	0.0%	89	9	89.9%
564	Cncld	1	0	100.0%	91	9	90.1%	0	0	0.0%	86	12	86.0%
566	79	1	0	100.0%	91	6	93.4%	1	1	0.0%	88	9	89.8%
572	Cncld	1	1	0.0%	90	8	91.1%	0	0	0.0%	87	18	79.3%
573	20	1	1	0.0%	91	13	85.7%	1	1	0.0%	89	11	87.6%
577	Cncld	1	1	0.0%	89	8	91.0%	0	0	0.0%	84	8	90.5%
580		1	0	100.0%	91	2	97.8%	1	0	100.0%	91	9	90.1%
581	34	1	1	0.0%	91	11	87.9%	1	1	0.0%	91	17	81.3%
582		1	0	100.0%	91	6	93.4%	1	0	100.0%	89	7	92.1%
586		1	0	100.0%	91	19	79.1%	1	0	100.0%	86	11	87.2%
587	26	1	0	100.0%	91	5	94.5%	1	1	0.0%	87	12	86.2%
591		1	0	100.0%	91	2	97.8%	1	0	100.0%	90	8	91.1%
593		1	0	100.0%	91	14	84.6%	1	0	100.0%	83	9	89.2%
595		1	0	100.0%	90	19	78.9%	1	0	100.0%	89	14	84.3%
611	17	1	1	0.0%	15	12	20.0%	1	1	0.0%	15	2	86.7%
624		0	0	0.0%	64	19	70.3%	1	0	100.0%	65	14	78.5%
660	18	1	1	0.0%	29	3	89.7%	1	1	0.0%	29	12	58.6%
661		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	6	79.3%
662		1	0	100.0%	17	0	100.0%	1	0	100.0%	17	0	100.0%
663		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	1	96.6%
664		1	1	0.0%	29	6	79.3%	1	0	100.0%	29	1	96.6%
665		1	0	100.0%	29	6	79.3%	1	0	100.0%	29	11	62.1%
666		1	1	0.0%	29	11	62.1%	1	0	100.0%	29	3	89.7%
667		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	6	79.3%
669		1	1	0.0%	29	3	89.7%	1	0	100.0%	29	10	65.5%
670		1	1	0.0%	29	5	82.8%	1	0	100.0%	29	2	93.1%
671		1	1	0.0%	29	2	93.1%	1	0	100.0%	29	4	86.2%
672		1	1	0.0%	29	4	86.2%	1	0	100.0%	29	2	93.1%
674		1	0	100.0%	29	8	72.4%	1	0	100.0%	29	0	100.0%
680		1	1	0.0%	67	3	95.5%	1	0	100.0%	67	7	89.6%
681		1	0	100.0%	67	3	95.5%	1	0	100.0%	67	19	71.6%
682		1	0	100.0%	67	0	100.0%	1	0	100.0%	67	14	79.1%
683		1	0	100.0%	50	4	92.0%	1	0	100.0%	50	16	68.0%
684		1	0	100.0%	48	9	81.3%	1	0	100.0%	48	14	70.8%
685		1	0	100.0%	65	9	86.2%	1	0	100.0%	65	17	73.8%
686		1	0	100.0%	67	15	77.6%	1	0	100.0%	67	15	77.6%
687		1	0	100.0%	67	9	86.6%	1	0	100.0%	67	11	83.6%
688		1	0	100.0%	67	1	98.5%	1	0	100.0%	67	14	79.1%
701		1	0	100.0%	25	6	76.0%	1	0	100.0%	25	2	92.0%
702		1	0	100.0%	93	17	81.7%	1	0	100.0%	92	24	73.9%

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
703	20	1	1	0.0%	93	25	73.1%	1	1	0.0%	93	25	73.1%
704		1	0	100.0%	25	3	88.0%	1	0	100.0%	24	5	79.2%
710		1	1	0.0%	93	36	61.3%	1	0	100.0%	93	34	63.4%
711	Cncld	1	0	100.0%	87	8	90.8%	0	0	0.0%	79	12	84.8%
712		1	0	100.0%	93	22	76.3%	1	0	100.0%	91	33	63.7%
713		1	0	100.0%	90	12	86.7%	1	0	100.0%	79	33	58.2%
714	30	1	1	0.0%	87	31	64.4%	1	1	0.0%	80	26	67.5%
715	22	1	0	100.0%	93	30	67.7%	1	1	0.0%	86	44	48.8%
716	51	1	1	0.0%	93	42	54.8%	1	1	0.0%	91	42	53.8%
717		1	0	100.0%	84	23	72.6%	1	0	100.0%	77	28	63.6%
718		1	0	100.0%	93	39	58.1%	1	0	100.0%	92	29	68.5%
719		1	0	100.0%	93	35	62.4%	1	0	100.0%	91	32	64.8%
720		1	0	100.0%	31	2	93.5%	1	0	100.0%	31	1	96.8%
723		1	0	100.0%	31	3	90.3%	1	0	100.0%	31	3	90.3%
724	16	1	0	100.0%	31	0	100.0%	1	1	0.0%	31	3	90.3%
727		1	0	100.0%	31	3	90.3%	1	0	100.0%	31	6	80.6%
728		1	0	100.0%	31	2	93.5%	1	0	100.0%	31	5	83.9%
729		1	0	100.0%	31	3	90.3%	1	0	100.0%	31	7	77.4%
732		1	0	100.0%	31	5	83.9%	1	0	100.0%	31	4	87.1%
733		1	0	100.0%	31	3	90.3%	1	0	100.0%	27	7	74.1%
734		1	0	100.0%	31	9	71.0%	1	0	100.0%	31	6	80.6%
738		1	1	0.0%	31	6	80.6%	1	0	100.0%	29	2	93.1%
741		1	0	100.0%	31	7	77.4%	1	0	100.0%	31	4	87.1%
742		1	0	100.0%	31	4	87.1%	1	0	100.0%	30	3	90.0%
743		1	1	0.0%	31	5	83.9%	1	0	100.0%	31	2	93.5%
744		1	0	100.0%	31	3	90.3%	1	0	100.0%	31	11	64.5%
745		1	0	100.0%	31	3	90.3%	1	0	100.0%	31	7	77.4%
746		1	0	100.0%	31	0	100.0%	1	0	100.0%	31	2	93.5%
747		1	0	100.0%	31	7	77.4%	1	0	100.0%	31	6	80.6%
748		1	0	100.0%	30	6	80.0%	1	0	100.0%	30	3	90.0%
749		1	0	100.0%	30	5	83.3%	1	0	100.0%	26	2	92.3%
751		1	1	0.0%	31	8	74.2%	1	0	100.0%	30	5	83.3%
761		1	0	100.0%	91	4	95.6%	1	0	100.0%	91	14	84.6%
765		1	0	100.0%	91	8	91.2%	1	0	100.0%	91	17	81.3%
769		1	1	0.0%	91	8	91.2%	1	0	100.0%	89	18	79.8%
770	52	1	0	100.0%	91	10	89.0%	1	1	0.0%	91	15	83.5%
774	22	1	0	100.0%	91	7	92.3%	1	1	0.0%	90	20	77.8%
779		1	1	0.0%	91	5	94.5%	1	0	100.0%	90	18	80.0%
784		1	0	100.0%	91	10	89.0%	1	0	100.0%	90	47	47.8%
785		1	0	100.0%	91	0	100.0%	1	0	100.0%	91	14	84.6%
790		1	0	100.0%	91	6	93.4%	1	0	100.0%	91	11	87.9%
794		1	1	0.0%	91	9	90.1%	1	0	100.0%	90	16	82.2%

Amtrak On Time Performance

Trains Arriving Through: 1/1/2026

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
821		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	46	50.5%
822		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	47	49.5%
1333		1	0	100.0%	93	10	89.2%	1	0	100.0%	92	36	60.9%
1340		1	0	100.0%	93	3	96.8%	1	0	100.0%	93	22	76.3%
1689	14	0	0	0.0%	17	1	94.1%	1	1	0.0%	18	1	94.4%
2174	59	0	0	0.0%	15	3	80.0%	1	1	0.0%	15	4	73.3%
2203		1	0	100.0%	15	0	100.0%	1	0	100.0%	15	0	100.0%
2205		1	1	0.0%	29	4	86.2%	1	0	100.0%	29	2	93.1%
2216		1	0	100.0%	15	1	93.3%	1	0	100.0%	15	0	100.0%
2218	30	1	1	0.0%	15	3	80.0%	1	1	0.0%	15	2	86.7%
2249	26	1	0	100.0%	15	0	100.0%	1	1	0.0%	15	5	66.7%
2250		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	11	62.1%
2251	18	1	1	0.0%	15	1	93.3%	1	1	0.0%	15	6	60.0%
2252		1	0	100.0%	28	3	89.3%	1	0	100.0%	28	4	85.7%
2253		1	0	100.0%	27	3	88.9%	1	0	100.0%	26	14	46.2%
2254		1	0	100.0%	29	0	100.0%	1	0	100.0%	29	7	75.9%
2255		1	0	100.0%	29	4	86.2%	1	0	100.0%	29	10	65.5%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2174	BOS	59	SVS	52	SVS	52	NWK-NYP	AM	Planned Switch, NO TIME LOST. ARRIVED IN NYP AT 919PM. CHANGED EQUIPMENT WITH AM2193 ACROSS THE PLATFORM IN NY PENN STATION.
2218	NYP	30	ENG	13	ENG	13	XPV-WIL	AM	Traction motor, PC/2117, stopped just north of Perry Int. with unknown fault, Engr reset traction motor
2249	WAS	26	WTR	18	DCS	10	XGX-NHV	AM	Power switch failure, Milepost, xgx, nhv, Switch failure @ Guilford
2251	WAS	18	CTI	15	CTI	15	NHV-STM	MN	Follow MNRR, Control Point, 261
66	BOS	47	CAR	24	CAR	21	KIN-PVD	AM	Door, 86622, 66 is stopped at MP 172 to inspect the consist after getting a hot journal alarm on the 8th axle
103	WAS	47	ITI	66	ITI	66	NYP-NYP	AM	Service, turn, or wye train, 144
135	WAS	163	WTR	113	WTR	96	BOS-BOS	AM	Ice / snow on or under equipment, Other, BOS, AM135 departed late due to excessive snow/ice build on AM150, tested break fault on train and train was given the okay to travel
144	NYP	94	SVS	102	SVS	102	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, Late Yard Release
146	SPG	52	OTH	57	OTH	55	NRO-STM	MN	Train 168 gapped itself at cos cob, we had to attach and pull back so 168 could grab power to continue on. This took a bit as 168 was totally dead.
150	BOS	43	HLD	21	HLD	7	EWR-EWR	AM	Passenger and/or baggage, TRAVEL
160	BOS	41	WTR	25	INJ	17	WLY-WLY	AM	Injured or sick passenger, 160 is awaiting EMS at Westerly Station for a diabetic woman having a seizure
161	WAS	59	PTI	26	DSR	10	BRP-STM	MN	Per bulletin Milepost, 41.7, 40.4, 30, 2
162	BOS	22	WTR	19	DSR	8	NRO-STM	MN	Per bulletin Milepost, 32.3, 33.6, 30, 2, Control Point, 217, 30, 4, Milepost, 24.6, 24.8, 30, 4
163	WAS	82	CAR	26	ENG	18	XSH-NYP	AM	Other electrical failure, 663, STOPPED AT LEGGETT A/C ONBOARD ACESES ISSUES
165	WAS	71	ITI	32	ITI	32	BOS-BOS	AM	Service, turn, or wye train, 160, late turn
168	BOS	105	SYS	99	SYS	99	NRO-STM	MN	Blocked by or assisting another, disabled Amtrak train Disabled at cos cob, Control Point, CP 230

Amtrak Endpoint OTP Details

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/1/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
195	RVM	64	CAR	46	CAR	34	WAS-WAS	AM	Electrical failure, 81516, BUSINESS CLASS BATTERY BOS WAS SMOKING, MECH SAID IT WAS SOPPED AND HAD TO COME OFF. MECH CUT THE AND DSL AT ONE TIME	
460	SPG	26	CON	25	CON	23	NHV-NHV	AM	Hold for connecting train	
488	GFD	Trn Cancelled								
499	SPG	Trn Cancelled								
611	HAR	17	WTR	13	WTR	5	DOW-PAR	AM	Wet / slippery rail, Milepost, 32.4, 44.2	
660	NYP	18	WTR	14	WTR	7	NWK-NYP	AM	Ice / snow on or under equipment, Other, XBH-NYP, CONGESTION A/C SINGLE TRKING IN NORTH TUBE DUE TO ICE PATROL IN SOUTH TUBE	
1689	BRK	14	FTI	26	FTI	26	SAO-POR	CS	Meet m427, Control Point, ocean	
68	NYP	29	CON	23	CON	23	ALB-ALB	AM	Hold for connecting train 237	
233	ALB	139	ENG	115	ENG	110	NYP-XSD	AM	HEP, N/A, REVERSED BACK INTO NYP A/C NO HEP NECY TO SWAP EQUIPMENT	
237	ALB	50	ENG	38	ENG	38	NYP-XSD	AM	Other electrical failure, 132, Stopped with locked axle alarm just south of Empire	
281	NFL	61	CAR	51	ENG	20	ALB-ALB	AM	Other electrical failure 117	
49	CHI	155	FTI	187	FTI	87	SKY-TOL	NS	Follow 256, Control Point, 285	
448	BOS	70	FTI	95	FTI	95	XRD-PIT	CS	Meet 42501, Control Point, 171	
76	RGH	20	DCS	18	DCS	18	KAN-GRO	NS	Restrictive signal(s) from known wayside signal failure Wait on Amtrak 77 crossover behind them, Stop, Control Point, Summner	
97	MIA	76	FTI	178	FTI	178	PTB-RMT	CS	M415 in emergency m415, Control Point, fox	
40	CHI	38	RTE	73	RTE	30	X86-CLE	NS	Per dispatcher shoved back into Cleveland Station. Due to frozen switches. Control Point, drawbridge	
41	MIA	193	FTI	315	FTI	281	COV-CUM	CS	Hold due to freight derailment R13331, Control Point, Viaduct Jct	
724	SAC	16	TCC	27	TCC	19	FFV-DAV	UP	PTC - cut itself out, put us into penalty, we recovered, logged back in, made us do departure test, then locked at restricted speed until the next signal C8302	
502	SEA	Trn Cancelled								

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
504	SEA	28	FTI	47	FTI	29	PDX-VAN	BN	Blocked from station track bnsf 6429, Milepost, 7.4, 9.9
518	VAC	118	ENG	131	ENG	85	EVR-STW	BN	Air / Brake Car cut out, 7910
519	SEA	41	OTH	58	OTH	56	STW-EVR	BN	Train 518 was stopped at bridge 38 due to mechanical problems. They caused a 56 minute delay to us.
14	SEA	111	ENG	103	ENG	103	VNC-SIM	SC	Undesired emergency application Engine went completely off line, mechanical talk is thorough restoration., 371
8	CHI	91	FTI	154	ITI	119	SEA-SEA	BN	Service, turn, or wye train 7, Late 8 arrival, wye, engine swap, late release by mechanical
341	MKE	Trn Cancelled	SVS	2	SVS	2	X9L-XWA	ME	PTC - Initializing PTC (no failure)
342	CHI	Trn Cancelled	POL	142	POL	134	GLN-XWA	ME	Right of Way police hold Crime scene fatality ahead.
350	PNT	41	DCS	66	DCS	56	DOA-KAL	MI	Issue with automatic road crossing protection 13 CROSSINGS TO PROTECT., Milepost w/Letters, 145.55 HOWARD ST., 143.45 N. ROSE ST.
352	PNT	35	CAR	48	CAR	46	X90-KAL	AM	Door ID4018, Door not closed
354	PNT	20	CAR	19	CAR	19	XPI-XMC	AM	Air / Brake / Wheel ID4019, Back up hose came apart around mp 234
355	CHI	48	CAR	74	CAR	59	ARB-JXN	MI	Brake Pipe between cars 4003 & 4123 kept putting train into emergency 4003, 4123
365	CHI	69	RTE	55	RTE	55	XGO-KAL	AM	Dispatcher hold Held at CP 143 by AML due to issues with crossings between cp 143 and cp 147, broken rail on M2, and meet with eastbound 350., Control Point, 143
370	GRR	19	FTI	25	FTI	14	XH6-XPI	NS	Meet 29P, Control Point, 485
562	SAN	Trn Cancelled	DBS	9	DBS	9	XRJ-FUL	BN	Debris blocking track (no debris strike) Vehicle on tracks, Control Point, Los Nietos
564	SAN	Trn Cancelled	SYS	6	SYS	4	LAX-XRJ	SC	Copy authority / restriction
566	SAN	79	WTR	47	WTR	40	OSD-OSD	SN	Landslide / rockslide Milepost, 252, 252
572	SAN	Trn Cancelled							
573	LAX	20	WTR	32	WTR	32	SOL-SOL	SN	Landslide / rockslide Milepost, 2629, 2629

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/1/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
577	LAX	Trn Cancelled							
581	LAX	34	CTI	24	ITI	16	SAN-SAN	SN	Service, turn, or wye train 770
587	LAX	26	DCS	29	DCS	29	FUL-XRJ	BN	Restrictive signal(s) from unknown cause Stop, Control Point, Bandini
770	SAN	52	WTR	27	WTR	19	SOL-OLT	SN	Flash flood warning Milepost, 244.1, 245.7, Milepost, 246.1, 248.7, Milepost, 251.0, 253.0
774	SAN	22	PTI	26	CTI	16	SOL-OLT	SN	Meet nctc, 679, Control Point, scripps
703	SAC	20	PTI	33	PTI	30	BFD-WAC	BN	Meet amtrak 714, Control Point, una
711	OKJ	Trn Cancelled	PTI	5	DCS	4	XPR-MTZ	UP	Restrictive signal(s) from unknown cause Stop, Control Point, Ferry
714	BFD	30	RTE	32	RTE	24	WAC-BFD	BN	Line manual or spring switch Control Point, wasco
715	OKJ	22	PTI	24	PTI	9	HNF-FNO	BN	Meet 710, Siding, Shirley
716	BFD	51	TCC	45	TCC	45	OKJ-OKJ	UP	Tazzy was cleaning train servicing toilets and issue with grounding wire on locomotive as well as issues with door lights not communicating with locomotive causing issue with door lights being illuminated indicating doors are closed but they were open. C9006, C9008, C9015, C9304, C9026, C9809, C9805
22	CHI	41	FTI	61	FTI	35	XUD-XTF	CC	Cross Traffic unk, Control Point, Brighton
305	STL	35	CAR	32	CAR	23	CHI-CHI	AM	Air / Brake / Wheel ID4125
306	CHI	No OS Rpt	OTH	5	ADA	3	ALN-ALN	UP	Wheelchair

Amtrak Initial Terminal Details

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/1/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	660	01/01	2	2	Other electrical failure, E/639, MU power fault HEP issue rear engine
HAR	664	01/01	4	4	Meet, 611, Control Point, .
HAR	666	01/01	1		
HAR	670	01/01	1		
HAR	672	01/01	1		
PHL	144	01/01	105	102	Planned set out / pick out of locomotives, cars or section of train, Late Yard Release
PHL	144	01/01	105	3	Ice / snow on or under equipment, Control Point, .. Frozen doors
PHL	611	01/01	2	2	High passenger count
RNK	66	01/01	3	3	Routine inspections Blue Flag down at 4:05; then permission to line out.
WAS	2218	01/01	3	3	Door, .. DOOR ISSUES AT DP TIME.
ALB	448	12/31	59	59	Fuel Control Point, 142
BOS	135	01/01	96	96	Ice / snow on or under equipment, Other, BOS, AM135 departed late due to excessive snow/ice build on AM150, tested break fault on train and train was given the okay to travel
BOS	165	01/01	32	32	Service, turn, or wye train, 160, late turn
BOS	167	01/01	77	77	Ice / snow on or under equipment, Other, BOS, AM167 delayed due to frozen pipe bursting in c/82601, entire car had to be removed from train set
BOS	2251	01/01	11	11	Water, commissary, toilet/trash dumping, waiting for commissary. They rptd there was old food on the consist
BRK	680	01/01	1		
GFD	499	01/01	(Trn Cxld)		Engine Issue
NHV	460	01/01	25	23	Hold for connecting train
NHV	460	01/01	25	2	Hold for connecting train
NHV	460	01/01	25	23	Hold for connecting train
NHV	460	01/01	25	2	Hold for connecting train
NHV	488	01/01	(Trn Cxld)		Engine Issue
NYP	103	01/01	66	66	Service, turn, or wye train, 144
NYP	245	01/01	64	64	Other electrical failure, 115, LOSS OF POWER BEFORE DEPARTING SSYD
NYP	669	01/01	2	2	Passenger and/or baggage, BOARDING
NYP	671	01/01	1		
NYP	2205	01/01	3	3	Passenger and/or baggage, LOADING

Amtrak Initial Terminal Details

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/1/2026

Terminal	Train	Date	Late	Delay	Cause
TWO	64	01/01	6		
CHI	305	01/01	23	23	Air / Brake / Wheel ID4125
CHI	307	01/01	94	94	Door 25110
CHI	350	01/01	5	5	Door ID4003, CLASS 2 AND CONSIST DOOR CHECK DONE PRIOR TO DEPT. NO ISSUES. HEADEND DOOR OPEN SHOWING AT DEPT.
KCY	318	01/01	1		
PDX	502	01/01	(Trn Cxld)		Car Issue
PNT	351	01/01	13	13	Air / Brake / Wheel ID4109, Had 4 bathrooms out also frozen brakes on last car. Along with one car with ppl no power
PTH	365	01/01	2	2	Ice / snow on or under equipment Late departure due to frozen equipment. Engineer had to throttle down so train could start moving., Milepost, 334, 334
SEA	8	01/01	18	18	Routine inspections Added DEF..., Other, Seattle Coach Yard
SEA	11	01/01	10	10	Late yard release due to truing wheels
SEA	507	01/01	2	2	PTC problem or failure (cause unknown) king st 6 disappeared from PTC on departure before signal. Had to troubleshoot to get track 6 back for PTC, Other, King St 6
BFD	703	01/01	1		
LAX	572	01/01	(Trn Cxld)		Winter Storm
OKJ	710	01/01	4	4	Meet AMTK 723, Control Point, N. Jack London
OKJ	714	01/01	1		
OKJ	716	01/01	60	15	PTC - On Board Cab Signal or PTC Failure Engineer stated PTU communication failure causing delay, 90218
OKJ	716	01/01	60	45	Tazzy was cleaning train servicing toilets and issue with grounding wire on locomotive as well as issues with door lights not communicating with locomotive causing issue with door lights being illuminated indicating doors are closed but they were open. C9006, C9008, C9015, C9304, C9026, C9809, C9805
SAC	743	01/01	2	2	For maritime traffic Control Point, RV989
SAC	751	01/01	1	1	Meet 746 pulled into 3 track and we had to wait for a signal to depart off of track 4, 746, Control Point, RV989
SAN	573	01/01	(Trn Cxld)		Winter Storm
SAN	577	01/01	(Trn Cxld)		PTC System Issues
SAN	581	01/01	16	16	Service, turn, or wye train 770
SAN	769	01/01	1	1	Copy authority / restriction Dispatcher transmitted Flash Flood warning at departure time.

Amtrak Initial Terminal Details

26-FOI-00217 00000005557 "UNCLASSIFIED" 1/5/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 1/1/2026

Terminal	Train	Date	Late	Delay	Cause
SAN	779	01/01	11	11	Service, turn, or wye train 566, Also waiting for passengers off cxld 577 to board
SJC	738	01/01	3	3	Door C8204
SLO	794	01/01	1	1	We left at 4:20 Geolocation is incorrect.

Eastern Region

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	100	94.8	165	0
CDOT	95.0	100	100	92.4	16	0
MARC	95.0	0	0	90.2	0	0
SEPTA	95.0	94.5	94.5	91.5	109	6
NJT-NED	95.0	97.1	97.1	93.8	206	6
NJT-SED	95.0	100	100	97.2	1	0

Operating Highlights

Train 245(01) New York, NY - Engine Failure

01JAN26: Train 245(01) operating with engine 115, 5 cars, and engine 711 was delayed departing New York, NY due to loss of power on engine 115 in Sunnyside Yard.

Train	Delay	Comment
245(01)	1'09"	

Train 168(01) East of New Rochelle, NY - System

01JAN26: At 7:52 p.m. train 168(01) operating with engine 659, 10 cars, and 528 passengers onboard missed the phase break at CP 230 on track 1 which is approximately 13 miles east of New Rochelle, NY located on the MNRR New Haven Line. Train 146(01) was used to rescue the equipment by coupling up from the rear and shoving the equipment west. Once shoved west, train 146(01) uncoupled which allowed 168(01) to get a head start east. Once the shove move was executed, both trains 168(01) and 146(01) were able to proceed east.

Service recovery was initiated and consisted of snack packs and water bottles for all passengers.

Train	Delay	Comment
168(01)	1'39"	
146(01)	55"	

Train 488/499(01) New Haven, CT - Car Failure

01JAN26: Trains 488/499(01) were cancelled due to air leak involving cab car 9640 and coach car 82765 due to damage from a prior deer strike and the contracted cleaning company arriving late to tidy the equipment outside from the strike. Customers boarded train 140(01) from New Haven to Springfield. Alternate transportation was provided for train 488(01) from Springfield to Greenfield in the form of a Datco bus.

Train	Delay	Comment
499(01)	CANCELLED	
488(01)	CANCELLED	

Train 448(31) West of Pittsfield, MA - Freight Train Interference

02JAN26: Train 448(31) 26-FQ1-002471 00000005557 eng UNCLASSIFIED, 46 1/5/2026 4 cars was delayed 21 miles west of Pittsfield, MA on the CSX Berkshire subdivision holding at milepost 171.9 meeting CSX M425-01.

Train	Delay	Comment
448(31)	1'35"	

Train 87(01) South of Aberdeen, MD - Deer Strike

01JAN26: Train 87(01) operating with engine 614, 8 cars, and 433 passengers onboard struck a deer 20.5 miles south of Aberdeen, MD on the Amtrak PW line at milepost 85.8. No damage occurred and no injuries were reported by crew or onboard passengers. Once the crew inspected the equipment and performed necessary tests, train 87(01) continued to Baltimore.

Train	Delay	Comment
87(01)	09"	

Train 167(01) Boston, MA - Shopped Car

01JAN26: Train 167(01) was delayed departing Boston, MA due to need to shop car C/82601 due to water leaking into the electrical closet. Once car was removed, Train 167(01) was able to depart.

Train	Delay	Comment
167(01)	1'17"	

Train 165(01) Boston, MA - Initial Terminal Delay

01JAN26: Train 165(01) was delayed departing Boston, MA due to a late turn and servicing of equipment from Train 160(01), that arrived Boston 2:16PM-ET, 41 minutes late.

Train	Delay	Comment
165(01)	32"	

Train 135(01) Boston, MA - Car Failure

01JAN26: Train 135(01) E/615, 9 cars, 288 passengers, was delayed departing Boston, MA due to brake release issues. An Amtrak Road Foreman and mechanical worked to remove ice from the brakes and once removed, as the train was ready to depart, received another brake fault. Mechanical was on scene and continued to work to resolve the issue. Once issue was resolved, Train 135(01) departed Boston.

Train	Delay	Comment
135(01)	1'36"	

Train 233(01) New York, NY - Engine Failure

01JAN26: Train 233(01) 26-FOI-002178, 00000005557 was UNCLASSIFIED" shown 1/5/2026 after departing New York, NY when the train lost power between A/MP0.2 and Empire/MP1.0. Head end power (HEP) was not active and the reported temperature was 28 degrees, with 258 passengers onboard. A rescue engine was quickly readied to retrieve the train back to the station. Once the rescue engine arrived and coupled to Train 233(01) HEP was restored to the train and was pulled back into the station. To minimize passenger delay, equipment for 283 was moved up to represent 233(01) and passengers were cross-platformed to the new equipment upon its arrival. Once passenger transfer was complete, Train 233(01) departed New York a second time, operating 1 hour and 48 minutes late.

Train	Delay	Comment
233(01)	1'50"	

Train 144(01) Philadelphia, PA - Initial Terminal/ Weather

01JAN26: Train 144(01) was delayed departing Philadelphia, PA due to a late yard release account of frozen cars, unable to release brakes on cars C/82609 and C/43392. Once resolved and released from the yard, Train 144(1) was able to depart.

Train	Delay	Comment
144(01)	1'45"	
103(01)	1'06"	ITD -Equip Turn off 144

Eastern Region

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 68(01) Passenger Removal at Rouses Point, New York – Customs***

01JAN26, Passenger on PNR 41B340, traveling from Montreal, QC to New York, NY, was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 68 (01) None

Train 64(30) Passenger Removal at Niagara Falls, New York – Customs

01JAN26, Passengers on PNR 1F9E9B, traveling from Canadian Border, NY to New York, NY were removed by Customs Border Patrol at Niagara Falls, NY. Amtrak Police notified.

Delay: 64 (30) None

Train 69(30) Passenger Removal at Rouses Point, New York – Customs

01JAN26, Passenger on PNR 370846, traveling from Yonkers, NY to Montreal, QC was removed by Customs Border Patrol at Rouses Point, NY. Amtrak Police notified.

Delay: 69 (30) None

Operating Highlights

Train 1(31) West of Tucson, AZ - Freight Train Interference

02JAN26: Train 1(31) was delayed 4 miles west of Tucson, AZ, at milepost 979.2, on UP Gila subdivision, due to UP2581 obstructing the route. The UP freight had to be tied down due to the crew running out of Hours of Service, causing train 1(31) to have to reverse 6 miles to be routed down a different track.

Train	Delay	Comment
1(31)	45"	

Train 714(01) Wasco, CA - Signal

01JAN26: Train 714(01) was delayed east of Wasco, CA (WAC) at CP East Wasco on the Burlington Northern Santa Fe Railway Stockton Subdivision. There was a problem with the dual control main track switch at CP E. Wasco which required the train crew to manually line the switch for the correct routing. Once the switch was lined, train 714(01) was able to proceed.

Train	Delay	Comment
714(01)	24"	

Train 14(01) South of Salinas, CA - Trespasser Incident

01JAN26: At approximately 6:13 PM-PT train 14(01) - operating with camera equipped locomotive AMTK/349, AMTK/159 and nine cars - fatally struck a trespasser at MP 117.74 on the Union Pacific Railway Coast Subdivision in the city of Salinas, Monterey County, California. This incident did NOT occur on a public highway crossing at grade. Train 14(01) was operating north on the main track at an estimated 38 MPH with a posted track speed of 40 MPH. There were no reports of injuries to the 266 passengers or crew and no reports of damage to Amtrak equipment. The weather was 58 degrees and cloudy. Local police and fire responded to the scene and conducted an investigation. Once the investigation was complete, train 14(01) advanced to San Jose, CA (SJC) where the train was held for a relief crew. Train 14(01) departed SJC once the relief crew arrived.

Google Maps Location of Incident:

<https://maps.app.goo.gl/a4LRAYTkDRBfBzqW6>

36.650756, -121.619846

1799-1301 Abbott St, Salinas, CA 93901

National Response Center: 1451796

California Office of Emergency Services: 26-0016

National Response Center Number: 1451796

Train	Delay	Comment
14(01)	3'11"	

Train 28(01) Vancouver, WA - M of W Work

01JAN26: Train 28(01) was delayed east of Vancouver, WA (VAN) at MP 32.1 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. There was a report of broken rail between MP 32.1 and MP 41.5. Train 28(01) was held for a track inspector to arrive and access the break. Once a track inspector was on-scene, train 28(01) was able to operate across the break at reduced speeds.

Train	Delay	Comment
28(01)	22"	

Train 518(01) North of Everett, WA - Cab Car Failure

02JAN26: Train 518(01) 26-FOI-00217 00000005557 mil "UNCLASSIFIED" of 1/5/2026 ett, WA, at milepost 38.1, on BNSF Bellingham subdivision, due to the brake pipe coming out of its fitting on cabcar 7910. This caused the train to go into emergency. The crew inspected the train and found the issue. There was no repair that could be made at location. As a result the crew had to cut out the trucks on the cabcar. Once the trucks were cut out, the crew waited for confirmation from the host railroad on what there speed would be moving forward. 518(01) was required to operate at freight speeds after cutting out the trucks. The train went into emergency again after the air hose on cabcar 7910, which were now hanging lower, came apart. the crew, using zip ties, was able to hang the cables higher and resolve the issue. 518(01) equipment had to wye once it arrived at vancouver, BC Canada.

Train 517(02) had to operate freight speeds due to the cut out trucks on cabcar 7910.

Train	Delay	Comment
518(01)	1'25"	Brake Pipe Failure
518(01)	46"	Operating Freight speeds

Train 341/342(01) West of Chicago, IL - Trespasser Incident

01JAN26: Trains 342(01) and 341(01) were delayed west of Chicago, Illinois, on the CPKC C&M Subdivision due to a fatal vehicle accident obstructing the tracks at MP 11.6. All train traffic was halted, and a lengthy delay was expected. Buses were sourced as alternate transportation. Train 342(01) held at Metra Morton Grove Station (MP 14.3), while Train 341(01) held at Metra Mayfair Station (MP 8.8). One bus was secured for Train 342(01) to operate Morton Grove-Chicago, and two buses were secured for Train 341(01), with one bus operating express Mayfair-Milwaukee and the other making all stops to Milwaukee. Train 341(01) transferred all passengers to buses at Mayfair Station and was subsequently terminated, with its equipment deadheading to Milwaukee. Train 342(01) also transferred all passengers to a bus and was terminated, with its equipment scheduled to deadhead to Chicago once the route reopened. The alternate buses for Train 341(01) departed Mayfair Station with 68 passengers onboard and 7 additional pickups en route. The alternate bus for Train 342(01) departed Morton Grove Station with 6 passengers onboard, while eight passengers arranged their own alternate transportation prior to the bus arriving.

Train	Delay	Comment
341(01)	Terminated	E/GLN
342(01)	Terminated	E/GLN

Train 307(01) Chicago, IL - Car Failure

01JAN26: Train 307(01) was delayed departing Chicago, Illinois account replacing bad order cars. Train 351(01) turned for Train 307(01). Train 351(01) set to the yard at 1142AM. At 245PM, Married pair ID4127/4317 were bad ordered for 11V power and toilets in both cars. Flags were dropped at 439PM to set out the 2 bad orders and add cars 48164 and 25110. Train 307(01) was made up at 542PM. Mechanical release Train 307(01) at 632PM and Commissary cleared at 701PM. Train 307(01) shoved to CUS at 703PM. At 711PM, the engineer reported a hot journal alarm on E/ID4620. Mechanical arrived at 740PM and cleared the fault. Boarding began at 720PM. Upon attempting to depart at 755PM, the engineer reported a door bypass light showing an open door. Cycling the door did not clear the door light and mechanical arrived from the yard at 830PM. They were able to reset the door on C/48164 and resolve the door light and cleared at 840PM. Train 307(01) departed Chicago at 844PM.

Train	Delay	Comment
307(01)	1'34"	

Train 716(01) Oakland, CA - Third Party Contractor Cab Car Failure

01JAN26: Train 716(01) departed Oakland, CA (OKJ) on the Union Pacific Railway Niles Subdivision. There was an issue with the door safety interlock system discovered on cab car CC/90218 prior to departing Oakland Maintenance Facility (OMF). Once technicians were able to resolve the issue, train 716(01) departed OKJ at 3:18 PM-PT.

Train	Delay	Comment
716(01)	1'00"	

Train 355(01) West of Ann Arbor, MI - Car Failure

02JAN26: Train 355(01) was delayed 3.6 miles west of Ann Arbor, MI, at milepost 41, on Amtrak Michigan Line, due to the brake pipe between C/4003 & C/4123 repeatedly putting the train into emergency. After 2 undesired emergencies the crew was able to shore up the brake pipe, preventing the train from going into emergency.

Train 354(01) was delayed meeting train 355(01) west of Battle Creek, MI, at Control Point Gord.

Train	Delay	Comment
355(01)	59"	
354(01)	44"	

Train 352(01) East of Niles, MI - Car Failure

01JAN26: Train 352(01) was delayed 11.5 miles east of Niles, MI, at milepost 180.5, on Amtrak Michigan Line, due to door issues with C/4018. The door was not shutting fully due to built up snow and ice preventing the door to shut securely. The crew work to remove the ice and snow and was eventually able to get the door to latch securely and proceed.

Train	Delay	Comment
352(01)	46"	

Train 1(31)/421(30) East of El Paso, TX - Freight Train Interference

01JAN26: Train 1(31)/421(30) was delayed 58.4 miles east of El Paso, TX/MP1296.0, on the UPRR Valentine Subdivision, at McNary/MP771.0 from freight interference. UP7933 was stopped ahead at Iser/MP782.6 after suffering from an undesired emergency with issues recovering. A carman responded to the freight train to work with the crew and resolve the problem. Once UP7933 recovered, the freight train advanced in between the switches at Iser to allow Train 1(31)/421(30) to pass by through the siding.

Train	Delay	Comment
1(31)/421(30)	1'11"	

Train 8(01) Seattle, WA - Car Failure

01JAN26: Train 8(01) departed Seattle, WA short a sleeper car after car 32090 was shopped prior to departure. This was due to car 32090 alarming on Train 7(30)'s inbound for a Level 3 hot bearing which required repair or replacing prior to coming back onto BNSF territory. The car was unable to be repaired in Seattle prior to 8(01)'s departure which required it to be setout. 26 sleeper car occupants were downgraded to coach and 25 coach passengers were bussed from Seattle to Spokane. The alternate bus made station stops at Seattle, Leavenworth, Wenatchee, and Spokane.

WBS#: B.TR.100150.6365

Train	Delay	Comment
-------	-------	---------

Train 22(31) South of Chicago, IL - Freight Train Interference

01JAN26: Train 22(31) FOI-00217 50000005557les "UNCLASSIFIED" f Ch1/5/2026 Jo, IL, on the CNRR Joliet Subdivision, at MP5.2 waiting on a BNSF freight train to finish crossing over at CP Brighton/MP5.1.

Train	Delay	Comment
22(31)	35"	

Train 11(01) Seattle, WA - Car Failure

01JAN26: Train 11(01) coach car 34515 was shopped in Seattle, WA for wheels with no available replacement. This led to overcapacity conditions from Tacoma (-27) to Eugene. Overflow passengers between Seattle and Portland were accommodated to the next available Cascade. Overcapacity passengers from Portland (-22) boarded a supplemental bus making station stops to Salem, Albany, and Eugene. There was also overcapacity downline starting at Oakland, CA to San Luis Obispo to which passengers will board an extra bus #4794(02). Highest overcapacity was at Salinas, CA with -61 passengers.

WBS#: B.TR.100150.6364

Train	Delay	Comment
11(01)	No Delay	

Train 769(01) San Diego, CA - Weather - Mudslide

01JAN26: At approximately 8:20 AM-PT the North County Transit District Reported a Mudslide between Old Town San Diego, CA (OLT) and Solana Beach, CA (SOL). Tracks were closed pending clean-up and inspection. The following modifications were made to Pacific Surfliner Service:

- 562(01) Terminate SOL - NCTD Bus Bridge SOL-SAN
- 564(01) Terminate SOL - NCTD Bus Bridge SOL-SAN
- 769(01) Cancelled between OLT and SOL - NCTD Bus Bridge OLT-SOL
- 573(01) Originate SOL - NCTD Bus Bridge SAN-SOL
- 577(01) Cancelled - Passengers to 779(01)
- 572(01) Cancelled - Passengers to 774(01)

WBS#: B.TR.100150.6366

Train	Delay	Comment
562(01)	Terminate SOL	NCTD Bus Bridge SOL-SAN
564(01)	Terminate SOL	NCTD Bus Bridge SOL-SAN
573(01)	Originate SOL	NCTD Bus Bridge SAN-SOL
769(01)	Cancelled btwn OLT-SOL	NCTD Bus Bridge OLT-SOL
577(01)	Cancelled	Pax to 779(01)
572(01)	Cancelled	Pax to 774(01)
769(01)	Supplemental Bus	LAX-GTA
566(01)	40"	Hold for route
573(01)	32"	Hold for route
770(01)	19"	Flash Flood Warning in Area

Train 22(01) South of Cleburne, TX - Broken Rail

01JAN26: Train 22(01) 26-FOI-00217-00000005557 UNCLASSIFIED 1/5/2026h of Cleburne, TX/MP317.5, on the BNSF Fort Worth Subdivision, due to reported broken rail at MP305.4 and MP306.1. Maintenance of Way was onsite and walked Train 22(01) over the broken rail in order to proceed into the station.

Train 21(31) was also delayed as a result holding 7.8 miles south of Cleburne at Rio Vista/MP309.7 for Maintenance of Way to finish repairing the defects. Once complete, Train 21(31) was released to continue south.

Train	Delay	Comment
22(01)	33"	
21(31)	51"	

Train 350(01) Kalamazoo, MI - Broken Rail

01JAN26: Amtrak's Michigan Line Dispatcher reported a broken rail on Main Track 2 at the Kalamazoo Depot around MP143.4 affecting multiple crossings in the area. C&S and the Track Department were onsite working to resolve the issue. Train 350(01) was delayed through the area having to stop and protect all crossings on Main Track 1 that the broken rail affected from CP147/MP147.1 into the station. Train 365(01) was also delayed holding at CP143/MP143.1 in order to meet Train 350(01). Once the meeting was complete, Train 365(01) was able to be routed through the area with no restrictions. No other trains were impacted and the defect was repaired.

Train	Delay	Comment
350(01)	56"	
365(01)	55"	

Train 502(01) Portland, OR - Cancelled

01JAN26: Train 502(01) was cancelled in its entirety at Portland, OR/MP0.0, on the BNSF Fallbridge Subdivision, after coach car 82666 was shopped for wheels with no available replacement. Two alternate buses were secured for the 45 affected passengers. One bus operated express Portland to Seattle and the other bus made all station stops.

WBS#: B.TR.100150.6363

Train	Delay	Comment
502(01)	Cancelled	

Train 49(31) East of Toledo, OH - B&B Work Due to Defect

01JAN26: Train 49(31) held 3.7 miles east of Toledo, OH/MP288.3, on the NSRR Chicago Line, at MP284.6 due to the Maumee Bridge/MP287.6 malfunction ahead. Building and Bridges (B&B) responded to the location and was able to resolve the issue to get the bridge seated and locked. Once this was complete, Train 49(31) was back on the move west.

Train	Delay	Comment
49(31)	1'27"	

Train 49(31) West of Cleveland, OH - Freight Train Interference

01JAN26: Train 49(31) was delayed on the NSRR Chicago Line following NS 27G from the Cleveland, OH station/MP181.6 to CP216/MP216.8.

Train	Delay	Comment
49(31)	42"	

Train 11(31) South of Redding, CA - Freight Train Interference

01JAN26: Train 11(31) 26-FOI-00247 00000005557 UNCLASSIFIED 1/5/2026 h of Redding, CA/MP258.3, on the UPRR Valley Subdivision, at MP249.6 from freight interference. UP2549 was stopped ahead on the single main track at Culp/MP243.2 with a locked axle indication. Once the axle was cutout, UP2549 experienced an undesired emergency and was struggling to recover. Once their issue was resolved, Train 11(31) had to follow UP2549 until they were able to get by at Gerber/MP214.9. Train 14(31) was also delayed holding in the Rawson siding/MP219.9 to meet UP2549 and Train 11(31).

Train	Delay	Comment
11(31)	1'55"	
14(31)	41"	

Train 8/28(30) Minot, ND - Servicing

01JAN26: Train 8/28(30), E/319-E/325-E/363-10 Cars, was delayed at Minot, ND/MP203.3X, on the BNSF KO Subdivision, for mechanical to complete routine inspections on the equipment.

Train	Delay	Comment
8/28(30)	34"	

Train 59(31) South of Carbondale, IL - Passenger Train Interference

01JAN26: Train 59(31) was delayed 19.5 miles south of Carbondale, IL/MP308.3, on the CNRR Centralia Subdivision, at South Anna/MP327.8 meeting Train 58(31).

Train	Delay	Comment
59(31)	35"	

Train 48/448(31) East of Sandusky, OH - Switch Failure

01JAN26: Train 48/448(31) was delayed 21.8 miles east of Sandusky, OH/MP241.5, on the NSRR Chicago Line, at MP219.7 due to power switch failure at CP-219. The Conductor reported having to manually line the switch by hand. Once this was complete, Train 48/448(31) had to meet Train 40(30) before the train could proceed east.

Train	Delay	Comment
48/448(31)	1'22"	Switch
48/448(31)	15"	40(30)

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

-715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.

-718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

-714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.

-718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.

-716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

24DEC25

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

- Train 520(29-30) Cancelled - No alternate transportation.
- Train 534(29-30) Cancelled - No alternate transportation.
- Train 535(29) Cancelled - No alternate transportation.
- Train 537(30) Cancelled - No alternate transportation.
- Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

- Train 520(31) Cancelled - No alternate transportation.
- Train 534(31) Cancelled - No alternate transportation.
- Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

- Train 736(01-04) Cancelled - No alternate transportation.
- Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-05MAR) Cancelled - No alternate transportation.
- TRAIN 713(05JAN-06MAR) Cancelled - No alternate transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718(21)	Originate EMY	Passengers to 744(21) OKJ-EMY
718(22)	Originate EMY	Passengers to 544(22) OKJ-EMY
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
714(23)	.	CANCELLED
713(24)	.	CANCELLED
535(24)	Cancelled	
520(24)	Cancelled	
534(24)	Cancelled	
736(25-28)	Cancelled	
737(25-28)	Cancelled	
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
551(29-30)	Cancelled	Replacement Bus SAC-OKJ
520(29-31)	Cancelled	No alternate transportation.
534(29-31)	Cancelled	No alternate transportation.
736(01JAN-04JAN))	Cancelled	No alternate transportation
737(01JAN-04JAN)	Cancelled	No alternate transportation
535(29)	Cancelled	No alternate transportation.
537(30-31)	Cancelled	No Alternate Transportation
713(05JAN-06MAR)	CANCELLED	No Alternate Transport Offered
714(05JAN-06MAR)	CANCELLED	No Alternate Transport Offered

Western Region

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standeers

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 2(31) Passenger Incident at Tucson, Missouri – Medical***

01JAN26, Passenger on PNR 628DCE, traveling from Tucson, MO to Lake Charles, LA, was removed from the train by EMS. Passenger fell on the train. Amtrak Police notified.

Delay: 2 (31) 07"

Train 4(31) Passenger Removal at Flagstaff, Arizona – Improper Conduct

01JAN26, Passenger on PNR 41484A, traveling from Los Angeles, CA to Chicago, IL, was removed from the train by Flagstaff PD. Passenger was intoxicated and caught smoking at their seat. Amtrak Police notified.

Delay: 4 (31) 15"

Train 319(01) Passenger Removal at Bloomington-Normal, Illinois –Fare Evader

01JAN26, Passenger on PNR 41D442, traveling from Joliet, IL to Springfield, IL, was removed from the train by the Conductor. Passenger refused to get off the train to purchase a ticket. Amtrak Police notified.

Delay: 319 (01) 02"

Train 3(29) Passenger Removal at Trinidad, Colorado – Improper Conduct

26-FOI-00217 00000005557 "UNCLASSIFIED" 1/5/2026

01JAN26, Passenger PNR 3D5318, traveling from Chicago, IL to Los Angeles, CA was removed by the local police at Trinidad, CO due to being extremely hostile and confrontational toward a family in the lower level. Passenger told them they were not supposed to be sitting in the lower level as it was for handicapped only. The family felt unsafe. Amtrak Police notified.

Delay: 3 (29) 06"

Train 352(30) On Board Passenger Issue at Jackson, Michigan – Medical

01JAN26, Passenger on PNR, 3F3C2F, traveling from Chicago, IL to Dearborn, MI was feeling faint and had numbness in her hands. EMS checked her vitals and they were good. Passenger refused to go to the hospital. She remained on the train until her destination. Amtrak Police notified.

Delay: 352 (30) 05"

Train 11(30) Passenger Removal at Albany, Oregon – Refusal to Pay

01JAN26, Passenger on PNR 3F120B, traveling from Seattle, WA to Albany, OR was removed by the Conductor at Albany, OR due to locking himself in the restroom. The Conductor could not locate him upon arrival. The Conductor explained to him that he could either step off at his destination or be removed by the police. Passenger reluctantly stepped off the train with his belongings. Amtrak Police notified.

Delay: 11 (30) 10"

Consist Deviations

26-FOI-00217

00000005557

"UNCLASSIFIED"

1/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
685 (01)	BON	NO BAGGAGE CAR; running with engine in lieu	No impact	0	130
683 (01)	BON	NO BAGGAGE CAR; running with engine in lieu	No impact	0	90
689 (01)	BON	NO BAGGAGE CAR; running with engine in lieu	No impact	0	90
684 (01)	BRK	NO BAGGAGE CAR; running with engine in lieu	No impact	0	130
682 (01)	BRK	NO BAGGAGE CAR; running with engine in lieu	No impact	0	90
688 (01)	BRK	NO BAGGAGE CAR; running with engine in lieu	No impact	0	90
59 (31)	CHI	34032 is BYD for toilets and running deadhead inline; no replacement. Please accomodate affected passengers	No impact	0	34032
6 (01)	EMY	32005 (0632) Room 4 bunk bed is unrepairable- repeater.	Passenger moved to another room	2	32005
86 (02)	RVM	BUSINESS CLASS SHOPPED WAS 195(01) AND REMOVED. JY SALES CLOSED RVM-WAS, WAS WILL CORRECT CONSIST ON ARRIVAL	0	0	81516
22 (01)	SAS	Diner in lieu of Lounge.	0	0	38065
11 (01)	SEA	34515 shopped BYD wheels; no replacement for consist. Please accomodate all passengers affected	Passengers will re-book, be bused, or use the lounge car	69	NOCAR
8 (01)	SEA	SEA does not have material to fix 32090. 8(01) will be operating without the 0830 sleeper. Please reaccomodate all 0830 pax.	0	0	32090
195 (01)	WAS	BUSINESS CLASS CAR IS SHOPPED IN WAS AND WAS REMOVED. JY SALES CLOSED WAS-RVM	0	0	81516

Reverse Consists

Train Number	Station	Reason	
		26-FOI-00217	00000005557 "UNCLASSIFIED" 1/5/2026
161 (01)	BOS	Consist reversed	Business class seat orientation may have changed At Front
155 (01)	NYP	Consist reversed	Business class seat orientation may have changed At Front
101 (01)	NYP	Consist reversed	Business class seat orientation may have changed At Front
153 (01)	NYP	Consist reversed	Business class seat orientation may have changed At Front
150 (01)	PHL	Consist reversed	Business class seat orientation may have changed At Front
144 (01)	PHL	Consist reversed	Business class seat orientation may have changed At Rear
103 (01)	NYP	Consist reversed	Business class seat orientation may have changed At Front
106 (01)	WAS	Consist reversed	Business class seat orientation may have changed At Rear
107 (01)	NY	Consist reversed	Business class seat orientation may have changed At Front
135 (01)	BOS	Consist reversed	Business class seat orientation may have changed At Front
142 (01)	WAS	Consist reversed	Business class seat orientation may have changed At Front
94 (02)	NFK	Consist reversed	Business class seat orientation may have changed At Front
128 (01)	WAS	Consist reversed	Business class seat orientation may have changed At Front
135 (01)	BOS	Consist reversed	Business class seat orientation may have changed At Front