



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, January 03, 2026

Rules: 0-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/02/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	312	50	84.0%	581	95	83.6%	27,887	3,770	86.5%
Central Division	85.5%	70	3	95.7%	136	13	90.4%	6,218	680	89.1%
Northeast Division	80.0%	103	17	83.5%	186	31	83.3%	8,802	1,312	85.1%
Southeast Division	72.5%	74	18	75.7%	130	27	79.2%	6,477	907	86.0%
Southwest Division	77.0%	65	12	81.5%	129	24	81.4%	6,390	871	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00217 00000005556 "UNCLASSIFIED" 1/5/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	102,969	23,219	77%	181,235	43,823	76%	9,506,156	2,083,409	78%
Northeast Corridor	81%	45,465	12,374	73%	78,425	21,324	73%	4,246,351	900,940	79%
Acela	83%	8,915	3,239	64%	13,920	4,371	69%	897,709	215,418	76%
Northeast Regional	79%	36,550	9,135	75%	64,505	16,953	74%	3,348,642	685,522	80%
Richmond / Newport News / Norfolk	77%	10,545	2,528	76%	20,806	4,607	78%	1,023,059	237,695	77%
Springfield Shuttles	89%	855	144	83%	1,296	214	83%	61,009	6,902	89%
Roanoke	79%	2,576	0	100%	5,124	942	82%	258,475	43,787	83%
On Spine Northeast Regional	80%	22,574	6,463	71%	37,279	11,190	70%	2,006,099	397,138	80%
State Supported	80%	43,381	8,024	82%	76,977	14,922	81%	4,061,464	780,369	81%
Borealis	60%	212	18	92%	765	18	98%	54,722	13,911	75%
Capitol Corridor	90%	2,827	706	75%	4,787	892	81%	325,883	34,807	89%
Carolinian	60%	1,022	89	91%	2,003	89	96%	109,233	30,438	72%
Cascades	63%	2,720	279	90%	5,154	747	86%	225,827	53,115	76%
Downeaster	82%	1,202	124	90%	2,369	124	95%	137,241	17,706	87%
Empire	78%	6,154	1,663	73%	11,424	3,605	68%	506,904	107,669	79%
Adirondack	72%	548	283	48%	972	545	44%	32,072	12,072	62%
Ethan Allen Express	70%	512	289	44%	1,144	428	63%	55,682	16,634	70%
Maple Leaf	70%	804	698	13%	1,532	1,155	25%	59,917	26,430	56%
New York - Albany	85%	2,867	325	89%	5,031	843	83%	230,163	31,049	87%
New York - Niagara Falls	75%	1,423	68	95%	2,746	634	77%	129,070	21,484	83%
Gold Runner	73%	2,276	951	58%	4,177	1,650	60%	237,558	86,783	63%
Heartland Flyer	65%	260	0	100%	452	0	100%	19,953	8,293	58%
Hiawatha	90%	1,476	99	93%	2,575	142	94%	162,203	19,744	88%
Illinois	78%	2,313	427	82%	4,297	706	84%	228,536	65,819	71%
Carl Sandburg / Illinois Zephyr	85%	504	0	100%	925	0	100%	39,936	10,265	74%
Illini / Saluki	85%	677	214	68%	1,394	214	85%	79,389	21,436	73%
Lincoln Service	70%	1,132	213	81%	1,978	492	75%	109,211	34,118	69%
Keystone	92%	7,229	292	96%	12,063	538	96%	762,508	75,106	90%
Lincoln / Missouri	60%	920	43	95%	1,725	103	94%	74,300	35,371	52%
Mardi Gras Service	80%	503	0	100%	923	0	100%	40,565	4,679	88%
Michigan	69%	1,969	595	70%	3,656	1,625	56%	185,075	57,005	69%
Blue Water	70%	484	298	38%	819	469	43%	45,335	14,113	69%
Pere Marquette	85%	262	0	100%	506	152	70%	24,987	4,471	82%
Wolverine	65%	1,223	297	76%	2,331	1,004	57%	114,753	38,421	67%
Missouri	80%	330	151	54%	545	151	72%	22,872	5,186	77%
Pacific Surfliner	85%	8,535	2,025	76%	13,487	3,645	73%	633,002	92,725	85%
Pennsylvanian	72%	968	0	100%	1,846	0	100%	87,652	9,220	89%
Piedmont	73%	1,276	0	100%	2,270	93	96%	120,973	27,781	77%
Vermont	75%	1,189	562	53%	2,459	794	68%	126,457	35,011	72%
Long Distance	56%	13,509	2,821	79%	25,219	7,577	70%	1,194,287	401,833	66%
Auto Train	57%	1,060	0	100%	1,978	0	100%	65,845	10,771	84%
California Zephyr	50%	1,163	105	91%	2,293	291	87%	88,938	25,033	72%
Cardinal	55%	262	162	38%	551	267	52%	26,122	11,593	56%
City Of New Orleans	75%	762	28	96%	1,273	73	94%	66,992	14,482	78%
Coast Starlight	60%	1,102	531	52%	2,219	1,451	35%	111,738	36,241	68%
Crescent	70%	943	7	99%	1,690	58	97%	91,795	21,043	77%
Empire Builder	55%	1,143	108	91%	2,310	1,275	45%	97,149	37,720	61%
Floridian	40%	1,690	1,019	40%	3,293	1,903	42%	162,745	89,359	45%
Lake Shore Ltd	73%	1,039	38	96%	1,809	626	65%	92,457	20,053	78%
Palmetto	65%	848	14	98%	1,658	16	99%	91,172	15,233	83%
Silver Meteor	45%	1,049	7	99%	1,917	413	78%	98,537	31,354	68%
Southwest Chief	40%	705	498	29%	1,551	537	65%	78,396	46,839	40%
Sunset Ltd	70%	761	118	84%	761	118	84%	27,532	6,282	77%
Texas Eagle	50%	982	186	81%	1,916	549	71%	94,869	35,830	62%
Seasonal Trains	%	614	0	100%	614	0	100%	4,054	267	93%
Winter Park Express	75%	614	0	100%	614	0	100%	4,054	267	93%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00217 00000005550 "UNCLASSIFIED" 1/5/2020

Train Index Dates Through January 02, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	10,277	211,305	486	538,847	10,071,696	535

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	446	59,400	75	21,179	2,941,377	72
INFRASTRUCTURE PLANNED	135	191	59,400	32	15,566	2,941,377	53
FLEET RELIABILITY	90	2,477	211,305	117	85,527	10,071,696	85
TRAIN OPERATIONS	424	7,163	211,305	339	416,575	10,071,696	414

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/02/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	312	50	84.0%	581	95	83.6%	27,887	3,770	86.5%
Central Division	85.5%	70	3	95.7%	136	13	90.4%	6,218	680	89.1%
Northeast Division	80.0%	103	17	83.5%	186	31	83.3%	8,802	1,312	85.1%
Southeast Division	72.5%	74	18	75.7%	130	27	79.2%	6,477	907	86.0%
Southwest Division	77.0%	65	12	81.5%	129	24	81.4%	6,390	871	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/02/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	312	50	84.0%	581	95	83.6%	27,887	3,770	86.5%
Central Division	85.5%	70	3	95.7%	136	13	90.4%	6,218	680	89.1%
CDL	90.0%	2	0	100.0%	4	0	100.0%	159	8	95.0%
CHI	85.0%	28	1	96.4%	55	4	92.7%	2,521	283	88.8%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	1	0	100.0%	7	2	71.4%
EUG	86.5%	2	0	100.0%	4	0	100.0%	182	26	85.7%
GRR	98.0%	1	0	100.0%	2	0	100.0%	93	3	96.8%
KCY	84.5%	2	0	100.0%	4	1	75.0%	185	16	91.4%
MKE	86.5%	6	0	100.0%	11	0	100.0%	548	46	91.6%
MSP	94.0%	1	0	100.0%	2	0	100.0%	94	3	96.8%
PDX	78.0%	5	1	80.0%	10	2	80.0%	471	63	86.6%
PNT	91.5%	3	0	100.0%	6	1	83.3%	224	23	89.7%
PTH	93.0%	1	0	100.0%	2	1	50.0%	93	8	91.4%
QCY	87.5%	2	0	100.0%	4	0	100.0%	188	17	91.0%
SEA	80.0%	8	1	87.5%	16	4	75.0%	747	123	83.5%
SPK	92.0%	1	0	100.0%	2	0	100.0%	97	5	94.8%
STL	88.0%	4	0	100.0%	8	0	100.0%	371	38	89.8%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	4	0	100.0%	183	6	96.7%
WIP	-	1	0	100.0%	1	0	100.0%	7	0	100.0%
Northeast Division	80.0%	103	17	83.5%	186	31	83.3%	8,802	1,312	85.1%
ALB	91.5%	8	1	87.5%	16	2	87.5%	631	48	92.4%
BON	43.5%	5	0	100.0%	10	0	100.0%	451	44	90.2%
BOS	86.5%	20	5	75.0%	35	9	74.3%	1,715	218	87.3%
BRK	88.0%	5	1	80.0%	10	2	80.0%	431	22	94.9%
BTN	48.0%	1	0	100.0%	2	0	100.0%	93	18	80.6%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	4	1	75.0%	180	16	91.1%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	2	0	100.0%	94	17	81.9%
NFL	96.5%	2	0	100.0%	4	0	100.0%	189	8	95.8%
NHV	75.5%	6	1	83.3%	10	2	80.0%	489	83	83.0%
NYP	77.5%	44	9	79.5%	76	14	81.6%	3,704	777	79.0%
SAB	98.0%	1	0	100.0%	2	0	100.0%	92	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	13	0	100.0%	574	24	95.8%
TWO	84.0%	1	0	100.0%	2	1	50.0%	92	20	78.3%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	74	18	75.7%	130	27	79.2%	6,477	907	86.0%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	10	0	100.0%	470	37	92.1%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	5	61.5%	20	10	50.0%	1,049	200	80.9%
LOR	69.5%	1	0	100.0%	2	0	100.0%	94	9	90.4%

Information Management

26-FOI-00100000 Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/02/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	312	50	84.0%	581	95	83.6%	27,887	3,770	86.5%
Southeast Division	72.5%	74	18	75.7%	130	27	79.2%	6,477	907	86.0%
MIA	87.5%	2	0	100.0%	4	0	100.0%	188	19	89.9%
MOE	94.0%	2	0	100.0%	4	0	100.0%	188	3	98.4%
NFK	86.0%	2	0	100.0%	5	0	100.0%	263	28	89.4%
NOL	92.0%	4	0	100.0%	8	0	100.0%	415	20	95.2%
NPN	96.0%	2	0	100.0%	4	0	100.0%	163	10	93.9%
PGH	92.0%	1	0	100.0%	2	0	100.0%	94	3	96.8%
PHL	45.0%	5	4	20.0%	9	6	33.3%	432	223	48.4%
RGH	97.0%	4	0	100.0%	8	0	100.0%	372	9	97.6%
RNK	85.5%	2	1	50.0%	4	2	50.0%	187	23	87.7%
RVM	86.0%	1	0	100.0%	2	0	100.0%	104	13	87.5%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	2	0	100.0%	94	2	97.9%
SFA	70.5%	1	1	0.0%	2	1	50.0%	94	4	95.7%
WAS	70.0%	28	7	75.0%	44	8	81.8%	2,262	299	86.8%
Southwest Division	77.0%	65	12	81.5%	129	24	81.4%	6,390	871	86.4%
ARN	60.5%	1	0	100.0%	2	0	100.0%	94	7	92.6%
BFD	75.5%	7	2	71.4%	14	2	85.7%	566	137	75.8%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	2	0	100.0%	101	36	64.4%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	2	0	100.0%	93	3	96.8%
GTA	72.5%	3	0	100.0%	6	0	100.0%	275	25	90.9%
LAX	77.5%	10	1	90.0%	19	2	89.5%	871	94	89.2%
OKC	96.0%	1	0	100.0%	2	0	100.0%	94	3	96.8%
OKJ	79.0%	8	3	62.5%	16	6	62.5%	1,015	248	75.6%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	11	0	100.0%	22	2	90.9%	1,239	131	89.4%
SAN	77.0%	12	2	83.3%	24	7	70.8%	1,081	98	90.9%
SAS	85.0%	1	0	100.0%	2	0	100.0%	94	4	95.7%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	4	42.9%	14	5	64.3%	656	64	90.2%
SLO	62.0%	2	0	100.0%	4	0	100.0%	182	15	91.8%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		0	0	0.0%	40	1	97.5%	1	0	100.0%	41	1	97.6%
2		1	0	100.0%	41	8	80.5%	1	0	100.0%	40	6	85.0%
3		2	0	100.0%	94	12	87.2%	2	0	100.0%	93	36	61.3%
4	84	2	0	100.0%	93	14	84.9%	2	1	50.0%	93	60	35.5%
5		2	0	100.0%	93	15	83.9%	2	0	100.0%	91	13	85.7%
6		2	0	100.0%	92	29	68.5%	2	0	100.0%	92	27	70.7%
7		2	0	100.0%	94	10	89.4%	2	0	100.0%	90	15	83.3%
8		2	1	50.0%	94	40	57.4%	2	1	50.0%	94	46	51.1%
11		2	1	50.0%	93	19	79.6%	2	0	100.0%	91	15	83.5%
14	114	2	0	100.0%	94	10	89.4%	2	2	0.0%	93	23	75.3%
19		2	1	50.0%	94	19	79.8%	2	0	100.0%	94	13	86.2%
20		2	0	100.0%	94	6	93.6%	2	0	100.0%	94	8	91.5%
21		2	0	100.0%	93	13	86.0%	2	0	100.0%	93	18	80.6%
22		2	0	100.0%	94	4	95.7%	2	1	50.0%	93	20	78.5%
23		2	0	100.0%	94	3	96.8%	2	0	100.0%	94	13	86.2%
24		2	0	100.0%	94	7	92.6%	2	0	100.0%	94	9	90.4%
25		2	0	100.0%	94	0	100.0%	2	0	100.0%	94	10	89.4%
26		2	0	100.0%	94	2	97.9%	2	0	100.0%	94	14	85.1%
27		2	2	0.0%	94	4	95.7%	2	0	100.0%	93	20	78.5%
28		2	1	50.0%	93	21	77.4%	2	0	100.0%	93	12	87.1%
40		2	0	100.0%	94	14	85.1%	2	1	50.0%	94	35	62.8%
41	75	2	0	100.0%	94	33	64.9%	2	2	0.0%	94	60	36.2%
42		2	0	100.0%	94	3	96.8%	2	0	100.0%	94	12	87.2%
43		2	0	100.0%	94	8	91.5%	2	0	100.0%	94	4	95.7%
48		2	0	100.0%	94	13	86.2%	2	0	100.0%	94	10	89.4%
49		2	0	100.0%	94	14	85.1%	2	1	50.0%	94	14	85.1%
50		1	0	100.0%	40	7	82.5%	1	0	100.0%	41	19	53.7%
52		2	1	50.0%	94	4	95.7%	2	0	100.0%	94	14	85.1%
53		2	0	100.0%	94	9	90.4%	2	0	100.0%	94	13	86.2%
55		1	0	100.0%	65	0	100.0%	1	0	100.0%	65	13	80.0%
56		1	1	0.0%	65	14	78.5%	1	0	100.0%	65	11	83.1%
58		2	0	100.0%	93	3	96.8%	2	0	100.0%	92	14	84.8%
59		2	0	100.0%	92	7	92.4%	2	0	100.0%	92	9	90.2%
63	39	2	1	50.0%	94	40	57.4%	2	1	50.0%	93	49	47.3%
64		2	1	50.0%	93	21	77.4%	2	0	100.0%	93	21	77.4%
66		2	2	0.0%	94	15	84.0%	2	1	50.0%	94	20	78.7%
67		1	0	100.0%	64	4	93.8%	1	0	100.0%	65	11	83.1%
68	21	2	0	100.0%	94	17	81.9%	2	2	0.0%	94	48	48.9%
69		2	0	100.0%	94	11	88.3%	2	0	100.0%	94	13	86.2%
71		2	0	100.0%	94	1	98.9%	2	0	100.0%	94	24	74.5%
72		2	0	100.0%	94	10	89.4%	2	0	100.0%	94	23	75.5%
73	12	2	0	100.0%	94	3	96.8%	2	1	50.0%	93	45	51.6%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74	11	2	0	100.0%	94	7	92.6%	2	1	50.0%	94	26	72.3%
75		2	0	100.0%	94	3	96.8%	2	0	100.0%	94	39	58.5%
76		2	0	100.0%	94	4	95.7%	2	1	50.0%	94	36	61.7%
77		2	0	100.0%	94	4	95.7%	2	0	100.0%	94	31	67.0%
78		2	0	100.0%	94	5	94.7%	2	0	100.0%	94	12	87.2%
79		2	0	100.0%	94	21	77.7%	2	0	100.0%	93	15	83.9%
80		2	0	100.0%	94	11	88.3%	2	0	100.0%	93	10	89.2%
84		1	1	0.0%	65	4	93.8%	1	0	100.0%	65	12	81.5%
85		1	0	100.0%	65	3	95.4%	1	0	100.0%	65	24	63.1%
86	42	1	0	100.0%	65	5	92.3%	1	1	0.0%	64	34	46.9%
89		2	0	100.0%	94	18	80.9%	2	0	100.0%	94	15	84.0%
90		2	0	100.0%	94	2	97.9%	2	0	100.0%	94	9	90.4%
93		1	0	100.0%	65	10	84.6%	1	0	100.0%	64	13	79.7%
94	38	1	0	100.0%	65	16	75.4%	1	1	0.0%	64	19	70.3%
95		1	0	100.0%	65	2	96.9%	1	0	100.0%	65	19	70.8%
97		2	1	50.0%	94	42	55.3%	2	1	50.0%	94	20	78.7%
98		2	0	100.0%	94	5	94.7%	2	0	100.0%	94	24	74.5%
110		1	1	0.0%	65	32	50.8%	1	0	100.0%	65	7	89.2%
111		1	0	100.0%	65	12	81.5%	1	0	100.0%	65	9	86.2%
112	25	1	0	100.0%	65	7	89.2%	1	1	0.0%	65	10	84.6%
114	68	1	1	0.0%	65	14	78.5%	1	1	0.0%	64	3	95.3%
119		1	1	0.0%	65	16	75.4%	1	0	100.0%	65	8	87.7%
125		1	0	100.0%	65	2	96.9%	1	0	100.0%	65	15	76.9%
128		1	0	100.0%	29	6	79.3%	1	0	100.0%	29	2	93.1%
129		1	1	0.0%	65	25	61.5%	1	0	100.0%	65	9	86.2%
130		1	1	0.0%	65	6	90.8%	1	0	100.0%	65	6	90.8%
131	20	1	1	0.0%	65	11	83.1%	1	1	0.0%	65	6	90.8%
133		1	0	100.0%	65	28	56.9%	1	0	100.0%	65	26	60.0%
134		1	0	100.0%	65	6	90.8%	1	0	100.0%	65	12	81.5%
137	16	1	0	100.0%	63	14	77.8%	1	1	0.0%	63	19	69.8%
138		1	0	100.0%	65	9	86.2%	1	0	100.0%	65	5	92.3%
141		1	0	100.0%	65	3	95.4%	1	0	100.0%	65	15	76.9%
148		1	0	100.0%	65	6	90.8%	1	0	100.0%	64	10	84.4%
151		2	0	100.0%	94	30	68.1%	2	0	100.0%	93	25	73.1%
167	67	1	1	0.0%	15	3	80.0%	1	1	0.0%	15	2	86.7%
169		1	0	100.0%	29	3	89.7%	1	0	100.0%	29	7	75.9%
170		1	0	100.0%	62	6	90.3%	1	0	100.0%	62	21	66.1%
171		1	0	100.0%	65	5	92.3%	1	0	100.0%	65	12	81.5%
172		1	0	100.0%	65	9	86.2%	1	0	100.0%	63	24	61.9%
173		1	0	100.0%	65	8	87.7%	1	0	100.0%	65	27	58.5%
174		1	0	100.0%	65	3	95.4%	1	0	100.0%	65	13	80.0%
175		1	0	100.0%	65	10	84.6%	1	0	100.0%	65	19	70.8%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
176		1	0	100.0%	65	5	92.3%	1	0	100.0%	65	4	93.8%
177	42	1	1	0.0%	65	15	76.9%	1	1	0.0%	65	28	56.9%
181	103	1	1	0.0%	65	16	75.4%	1	1	0.0%	64	4	93.8%
182		1	0	100.0%	65	12	81.5%	1	0	100.0%	65	5	92.3%
183		1	0	100.0%	65	19	70.8%	1	0	100.0%	65	10	84.6%
184		1	0	100.0%	65	12	81.5%	1	0	100.0%	65	11	83.1%
185		1	0	100.0%	65	13	80.0%	1	0	100.0%	65	4	93.8%
186		1	0	100.0%	65	9	86.2%	1	0	100.0%	65	15	76.9%
190		1	1	0.0%	65	28	56.9%	1	0	100.0%	65	15	76.9%
192		1	1	0.0%	63	9	85.7%	1	0	100.0%	63	2	96.8%
193		1	0	100.0%	65	21	67.7%	1	0	100.0%	65	23	64.6%
196		1	0	100.0%	65	1	98.5%	1	0	100.0%	65	3	95.4%
197		1	0	100.0%	65	24	63.1%	1	0	100.0%	65	14	78.5%
232		2	0	100.0%	94	2	97.9%	2	0	100.0%	94	6	93.6%
233	19	2	1	50.0%	94	25	73.4%	2	2	0.0%	94	22	76.6%
234		2	0	100.0%	94	4	95.7%	2	0	100.0%	94	3	96.8%
235		2	0	100.0%	33	5	84.8%	2	0	100.0%	33	6	81.8%
236		2	0	100.0%	94	1	98.9%	2	0	100.0%	94	16	83.0%
237		2	0	100.0%	93	15	83.9%	2	1	50.0%	92	8	91.3%
238		2	1	50.0%	33	7	78.8%	2	0	100.0%	33	3	90.9%
239		2	0	100.0%	93	24	74.2%	2	0	100.0%	93	4	95.7%
240		2	0	100.0%	94	9	90.4%	2	0	100.0%	94	12	87.2%
241		2	0	100.0%	94	24	74.5%	2	0	100.0%	94	14	85.1%
243		1	0	100.0%	65	22	66.2%	1	0	100.0%	66	12	81.8%
244		2	0	100.0%	94	5	94.7%	2	0	100.0%	94	18	80.9%
245	78	1	1	0.0%	29	8	72.4%	1	1	0.0%	29	2	93.1%
280		2	0	100.0%	94	4	95.7%	2	0	100.0%	94	17	81.9%
281		2	0	100.0%	94	9	90.4%	2	1	50.0%	94	11	88.3%
283		2	0	100.0%	94	20	78.7%	2	0	100.0%	94	15	84.0%
284		2	0	100.0%	94	3	96.8%	2	0	100.0%	93	7	92.5%
290	23	2	0	100.0%	94	19	79.8%	2	1	50.0%	93	32	65.6%
291		2	0	100.0%	94	18	80.9%	2	0	100.0%	94	15	84.0%
300		2	0	100.0%	94	10	89.4%	2	0	100.0%	93	25	73.1%
301		2	0	100.0%	92	2	97.8%	2	0	100.0%	91	16	82.4%
302		2	0	100.0%	91	11	87.9%	2	0	100.0%	89	27	69.7%
305		2	1	50.0%	94	13	86.2%	2	1	50.0%	92	36	60.9%
306	No OS	2	0	100.0%	92	6	93.5%	2	1	50.0%	91	21	76.9%
307	71	2	1	50.0%	93	12	87.1%	2	1	50.0%	92	21	77.2%
311	21	2	0	100.0%	93	10	89.2%	2	1	50.0%	92	21	77.2%
316		2	0	100.0%	92	5	94.6%	2	0	100.0%	92	18	80.4%
318		2	1	50.0%	94	12	87.2%	2	0	100.0%	93	37	60.2%
319		2	0	100.0%	94	4	95.7%	2	0	100.0%	94	48	48.9%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
329		1	0	100.0%	65	3	95.4%	1	0	100.0%	65	5	92.3%
330		1	0	100.0%	78	2	97.4%	1	0	100.0%	78	5	93.6%
331		2	0	100.0%	94	11	88.3%	2	0	100.0%	94	14	85.1%
332		2	0	100.0%	94	9	90.4%	2	0	100.0%	94	16	83.0%
334		2	0	100.0%	94	2	97.9%	2	0	100.0%	93	12	87.1%
335		2	0	100.0%	94	14	85.1%	2	0	100.0%	92	17	81.5%
336		2	0	100.0%	94	4	95.7%	2	0	100.0%	94	5	94.7%
337		2	0	100.0%	94	5	94.7%	2	0	100.0%	94	12	87.2%
338		2	0	100.0%	94	21	77.7%	2	0	100.0%	92	22	76.1%
339	13	2	0	100.0%	94	20	78.7%	2	1	50.0%	94	20	78.7%
341		2	0	100.0%	91	16	82.4%	1	0	100.0%	89	14	84.3%
342		2	0	100.0%	94	8	91.5%	1	0	100.0%	92	16	82.6%
350	40	2	1	50.0%	76	4	94.7%	2	2	0.0%	76	43	43.4%
351		2	1	50.0%	94	14	85.1%	2	0	100.0%	94	38	59.6%
352		2	0	100.0%	94	7	92.6%	2	1	50.0%	91	27	70.3%
353		2	0	100.0%	73	5	93.2%	2	0	100.0%	73	16	78.1%
354	47	2	0	100.0%	94	8	91.5%	2	2	0.0%	92	30	67.4%
355	No OS	2	0	100.0%	93	9	90.3%	2	2	0.0%	92	27	70.7%
364		2	0	100.0%	93	17	81.7%	2	0	100.0%	92	20	78.3%
365	49	2	1	50.0%	93	8	91.4%	2	2	0.0%	92	30	67.4%
370		2	0	100.0%	94	5	94.7%	2	1	50.0%	94	17	81.9%
371		2	0	100.0%	93	3	96.8%	2	0	100.0%	93	11	88.2%
380		2	0	100.0%	94	15	84.0%	2	0	100.0%	94	21	77.7%
381		2	0	100.0%	94	2	97.9%	2	0	100.0%	94	11	88.3%
382		2	0	100.0%	94	2	97.9%	2	0	100.0%	94	23	75.5%
383		2	0	100.0%	94	9	90.4%	2	0	100.0%	92	36	60.9%
390	25	2	0	100.0%	78	9	88.5%	2	1	50.0%	77	26	66.2%
391		2	0	100.0%	79	2	97.5%	2	0	100.0%	77	15	80.5%
392	No OS	2	0	100.0%	94	4	95.7%	2	1	50.0%	93	29	68.8%
393		2	0	100.0%	94	7	92.6%	2	0	100.0%	93	25	73.1%
417		1	0	100.0%	62	10	83.9%	1	0	100.0%	59	2	96.6%
425		1	0	100.0%	62	2	96.8%	1	0	100.0%	62	2	96.8%
448		2	1	50.0%	35	14	60.0%	2	1	50.0%	33	13	60.6%
449		2	0	100.0%	32	1	96.9%	2	0	100.0%	32	5	84.4%
470		1	0	100.0%	67	13	80.6%	1	0	100.0%	65	12	81.5%
471		1	0	100.0%	62	1	98.4%	1	0	100.0%	62	0	100.0%
473		1	0	100.0%	65	3	95.4%	1	0	100.0%	65	1	98.5%
474		1	1	0.0%	63	19	69.8%	1	0	100.0%	59	18	69.5%
475		1	0	100.0%	65	0	100.0%	1	0	100.0%	65	1	98.5%
478		1	1	0.0%	63	14	77.8%	1	0	100.0%	63	7	88.9%
479		1	0	100.0%	65	8	87.7%	1	0	100.0%	65	3	95.4%
486	21	1	0	100.0%	66	8	87.9%	1	1	0.0%	65	12	81.5%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
490		1	0	100.0%	42	8	81.0%	1	0	100.0%	42	2	95.2%
494	20	1	0	100.0%	67	9	86.6%	1	1	0.0%	64	12	81.3%
495		1	0	100.0%	65	2	96.9%	1	0	100.0%	65	1	98.5%
500		2	0	100.0%	94	6	93.6%	2	0	100.0%	93	10	89.2%
502		2	1	50.0%	94	8	91.5%	1	0	100.0%	92	21	77.2%
503		2	0	100.0%	91	11	87.9%	2	0	100.0%	90	22	75.6%
504		2	0	100.0%	94	8	91.5%	2	1	50.0%	93	26	72.0%
505	35	2	1	50.0%	94	17	81.9%	2	1	50.0%	92	18	80.4%
506		2	0	100.0%	93	14	84.9%	2	0	100.0%	92	13	85.9%
507		2	1	50.0%	94	12	87.2%	2	0	100.0%	94	32	66.0%
508		2	0	100.0%	92	20	78.3%	2	0	100.0%	92	22	76.1%
509		2	0	100.0%	94	7	92.6%	2	0	100.0%	94	25	73.4%
511		2	0	100.0%	94	10	89.4%	2	0	100.0%	94	17	81.9%
516		2	0	100.0%	92	9	90.2%	2	0	100.0%	92	38	58.7%
517		2	0	100.0%	94	2	97.9%	2	0	100.0%	93	31	66.7%
518	44	2	0	100.0%	94	13	86.2%	2	2	0.0%	94	56	40.4%
519		2	0	100.0%	92	4	95.7%	2	1	50.0%	92	15	83.7%
562		2	0	100.0%	92	11	88.0%	1	0	100.0%	90	9	90.0%
564		2	0	100.0%	92	9	90.2%	1	0	100.0%	87	12	86.2%
566		2	0	100.0%	92	6	93.5%	2	1	50.0%	89	9	89.9%
572		2	1	50.0%	91	8	91.2%	1	0	100.0%	88	18	79.5%
573		2	2	0.0%	92	14	84.8%	2	1	50.0%	90	11	87.8%
577		2	1	50.0%	90	8	91.1%	1	0	100.0%	85	8	90.6%
580		2	1	50.0%	92	3	96.7%	2	0	100.0%	92	9	90.2%
581		2	1	50.0%	92	11	88.0%	2	1	50.0%	92	17	81.5%
582		2	0	100.0%	92	6	93.5%	2	0	100.0%	90	7	92.2%
586		2	0	100.0%	92	19	79.3%	2	0	100.0%	87	11	87.4%
587		2	0	100.0%	92	5	94.6%	2	1	50.0%	88	12	86.4%
591		2	0	100.0%	92	2	97.8%	2	0	100.0%	91	8	91.2%
593		2	1	50.0%	92	15	83.7%	2	0	100.0%	84	9	89.3%
595		2	0	100.0%	91	19	79.1%	2	0	100.0%	90	14	84.4%
600		1	0	100.0%	65	2	96.9%	1	0	100.0%	65	5	92.3%
601		1	1	0.0%	65	37	43.1%	1	0	100.0%	65	15	76.9%
605		1	1	0.0%	65	42	35.4%	1	0	100.0%	64	6	90.6%
607		1	0	100.0%	65	4	93.8%	1	0	100.0%	64	4	93.8%
609		1	0	100.0%	64	5	92.2%	1	0	100.0%	64	4	93.8%
620		1	0	100.0%	64	19	70.3%	1	0	100.0%	62	3	95.2%
637		1	0	100.0%	17	2	88.2%	1	0	100.0%	17	2	88.2%
639		1	0	100.0%	65	18	72.3%	1	0	100.0%	65	7	89.2%
640		1	0	100.0%	65	5	92.3%	1	0	100.0%	64	32	50.0%
641		1	0	100.0%	65	14	78.5%	1	0	100.0%	65	12	81.5%
642		1	0	100.0%	64	4	93.8%	1	0	100.0%	64	8	87.5%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
643		1	0	100.0%	65	14	78.5%	1	0	100.0%	64	10	84.4%
644	28	1	0	100.0%	65	10	84.6%	1	1	0.0%	65	15	76.9%
645		1	0	100.0%	65	8	87.7%	1	0	100.0%	65	11	83.1%
646	13	1	0	100.0%	65	16	75.4%	1	1	0.0%	64	38	40.6%
647		1	0	100.0%	65	7	89.2%	1	0	100.0%	65	16	75.4%
648		1	1	0.0%	65	15	76.9%	1	0	100.0%	65	10	84.6%
649		1	0	100.0%	65	11	83.1%	1	0	100.0%	64	9	85.9%
650		1	1	0.0%	65	15	76.9%	1	0	100.0%	65	15	76.9%
651		1	0	100.0%	65	5	92.3%	1	0	100.0%	65	18	72.3%
652		1	0	100.0%	65	12	81.5%	1	0	100.0%	64	12	81.3%
653		1	0	100.0%	65	12	81.5%	1	0	100.0%	65	17	73.8%
654		1	1	0.0%	65	16	75.4%	1	0	100.0%	65	5	92.3%
655		1	0	100.0%	63	18	71.4%	1	0	100.0%	62	19	69.4%
656		1	0	100.0%	65	17	73.8%	1	0	100.0%	65	5	92.3%
657		1	0	100.0%	65	3	95.4%	1	0	100.0%	65	12	81.5%
658		1	1	0.0%	65	10	84.6%	1	0	100.0%	65	11	83.1%
680	29	2	1	50.0%	68	3	95.6%	2	1	50.0%	68	8	88.2%
681	Cncld	2	0	100.0%	68	3	95.6%	1	0	100.0%	67	19	71.6%
682	13	2	0	100.0%	68	0	100.0%	2	1	50.0%	68	15	77.9%
683		2	0	100.0%	51	4	92.2%	2	0	100.0%	51	16	68.6%
684		2	0	100.0%	49	9	81.6%	2	0	100.0%	49	14	71.4%
685		2	0	100.0%	66	9	86.4%	2	0	100.0%	66	17	74.2%
686		2	1	50.0%	68	16	76.5%	2	0	100.0%	68	15	77.9%
687		2	0	100.0%	68	9	86.8%	2	0	100.0%	68	11	83.8%
688	63	2	0	100.0%	68	1	98.5%	2	1	50.0%	68	15	77.9%
689		1	0	100.0%	55	5	90.9%	1	0	100.0%	54	4	92.6%
701		2	0	100.0%	26	6	76.9%	2	0	100.0%	26	2	92.3%
702		2	0	100.0%	94	17	81.9%	2	0	100.0%	93	24	74.2%
703	No OS	2	0	100.0%	94	24	74.5%	2	2	0.0%	94	26	72.3%
704		2	0	100.0%	26	3	88.5%	2	0	100.0%	25	5	80.0%
710	58	2	2	0.0%	94	37	60.6%	2	1	50.0%	94	35	62.8%
711		2	0	100.0%	88	8	90.9%	1	0	100.0%	80	12	85.0%
712	49	2	1	50.0%	94	23	75.5%	2	1	50.0%	92	34	63.0%
713	Cncld	2	0	100.0%	91	12	86.8%	1	0	100.0%	79	33	58.2%
714		2	1	50.0%	88	31	64.8%	2	1	50.0%	81	26	67.9%
715	25	2	0	100.0%	94	30	68.1%	2	2	0.0%	87	45	48.3%
716		2	1	50.0%	94	41	56.4%	2	1	50.0%	92	42	54.3%
717	Cncld	2	1	50.0%	85	24	71.8%	1	0	100.0%	77	28	63.6%
718		2	1	50.0%	94	40	57.4%	2	0	100.0%	93	29	68.8%
719		2	1	50.0%	94	36	61.7%	2	0	100.0%	92	32	65.2%
720		2	0	100.0%	32	2	93.8%	2	0	100.0%	32	1	96.9%
723		2	0	100.0%	32	3	90.6%	2	0	100.0%	32	3	90.6%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
724	21	2	1	50.0%	32	1	96.9%	2	2	0.0%	32	4	87.5%
727	15	2	0	100.0%	32	3	90.6%	2	1	50.0%	32	7	78.1%
728		2	1	50.0%	32	3	90.6%	2	0	100.0%	32	5	84.4%
729		2	0	100.0%	32	3	90.6%	2	0	100.0%	32	7	78.1%
732		2	0	100.0%	32	5	84.4%	2	0	100.0%	32	4	87.5%
733	15	2	0	100.0%	32	3	90.6%	2	1	50.0%	28	8	71.4%
734		2	0	100.0%	32	9	71.9%	2	0	100.0%	32	6	81.3%
738		2	2	0.0%	32	7	78.1%	2	0	100.0%	30	2	93.3%
741		2	0	100.0%	32	7	78.1%	2	0	100.0%	32	4	87.5%
742		2	0	100.0%	32	4	87.5%	2	0	100.0%	31	3	90.3%
743		2	1	50.0%	32	5	84.4%	2	0	100.0%	32	2	93.8%
744		2	0	100.0%	32	3	90.6%	2	0	100.0%	32	11	65.6%
745		2	0	100.0%	32	3	90.6%	2	0	100.0%	32	7	78.1%
746	120	2	1	50.0%	32	1	96.9%	2	1	50.0%	32	3	90.6%
747	90	2	0	100.0%	32	7	78.1%	2	1	50.0%	32	7	78.1%
748		2	0	100.0%	31	6	80.6%	2	0	100.0%	31	3	90.3%
749		2	0	100.0%	31	5	83.9%	2	0	100.0%	27	2	92.6%
751		2	1	50.0%	32	8	75.0%	2	0	100.0%	31	5	83.9%
761	35	2	0	100.0%	92	4	95.7%	2	1	50.0%	92	15	83.7%
765		2	0	100.0%	92	8	91.3%	2	0	100.0%	92	17	81.5%
769		2	1	50.0%	92	8	91.3%	2	0	100.0%	90	18	80.0%
770	16	2	0	100.0%	92	10	89.1%	2	2	0.0%	92	16	82.6%
774	32	2	0	100.0%	92	7	92.4%	2	2	0.0%	91	21	76.9%
779	31	2	1	50.0%	92	5	94.6%	2	1	50.0%	91	19	79.1%
784		2	0	100.0%	92	10	89.1%	2	0	100.0%	91	47	48.4%
785		2	0	100.0%	92	0	100.0%	2	0	100.0%	92	14	84.8%
790		2	0	100.0%	92	6	93.5%	2	0	100.0%	92	11	88.0%
794		2	0	100.0%	92	8	91.3%	2	0	100.0%	91	16	82.4%
821		2	0	100.0%	94	3	96.8%	2	0	100.0%	94	46	51.1%
822		2	0	100.0%	94	3	96.8%	2	0	100.0%	94	47	50.0%
1105		1	0	100.0%	7	2	71.4%	1	0	100.0%	7	1	85.7%
1106	15	1	0	100.0%	7	0	100.0%	1	1	0.0%	7	1	85.7%
1333	Cncld	2	0	100.0%	94	10	89.4%	1	0	100.0%	92	36	60.9%
1340		2	0	100.0%	94	3	96.8%	2	0	100.0%	94	22	76.6%
2103		1	0	100.0%	64	5	92.2%	1	0	100.0%	64	5	92.2%
2104		1	0	100.0%	35	7	80.0%	1	0	100.0%	34	5	85.3%
2107		1	0	100.0%	65	13	80.0%	1	0	100.0%	63	6	90.5%
2108		1	0	100.0%	64	6	90.6%	1	0	100.0%	62	2	96.8%
2117		1	1	0.0%	34	11	67.6%	1	0	100.0%	34	6	82.4%
2121		1	0	100.0%	62	8	87.1%	1	0	100.0%	62	6	90.3%
2122		1	0	100.0%	65	11	83.1%	1	0	100.0%	65	4	93.8%
2130		1	0	100.0%	17	2	88.2%	1	0	100.0%	17	3	82.4%

Amtrak On Time Performance

Trains Arriving Through: 1/2/2026

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2150	55	1	0	100.0%	65	15	76.9%	1	1	0.0%	63	18	71.4%
2151	45	1	0	100.0%	63	0	100.0%	1	1	0.0%	62	14	77.4%
2152		1	0	100.0%	61	3	95.1%	1	0	100.0%	60	26	56.7%
2153		1	0	100.0%	65	9	86.2%	1	0	100.0%	65	15	76.9%
2154		1	1	0.0%	65	20	69.2%	1	0	100.0%	62	34	45.2%
2155	22	1	0	100.0%	65	5	92.3%	1	1	0.0%	63	23	63.5%
2159		1	0	100.0%	64	3	95.3%	1	0	100.0%	63	16	74.6%
2162	17	1	0	100.0%	65	2	96.9%	1	1	0.0%	63	18	71.4%
2163	34	1	1	0.0%	65	8	87.7%	1	1	0.0%	64	19	70.3%
2166	17	1	1	0.0%	65	8	87.7%	1	1	0.0%	63	13	79.4%
2167	17	1	1	0.0%	63	12	81.0%	1	1	0.0%	63	18	71.4%
2168		1	0	100.0%	63	4	93.7%	1	0	100.0%	63	9	85.7%
2169	25	1	1	0.0%	61	27	55.7%	1	1	0.0%	61	33	45.9%
2170		1	0	100.0%	65	12	81.5%	1	0	100.0%	63	14	77.8%
2172	17	1	0	100.0%	65	8	87.7%	1	1	0.0%	65	14	78.5%
2173	152	1	1	0.0%	64	13	79.7%	1	1	0.0%	64	25	60.9%
2190		1	0	100.0%	64	10	84.4%	1	0	100.0%	62	10	83.9%
2193		1	0	100.0%	64	3	95.3%	1	0	100.0%	64	21	67.2%

Amtrak Endpoint OTP Details

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2150	BOS	55	CAR	28	CAR	28	NYP-NYP	AM	Door, 3550, DOOR PROBLEM CAR 3550
2151	WAS	45	DBB	32	DBB	32	XGX-NHV	AM	Stuck open bridges, Bridge, Shaw;s Cove
2155	WAS	22	WTR	9	WTR	4	PVD-XGX	AM	Wet / slippery rail, Milepost w/Letters, PVD, XGX, wheel slip
2162	BOS	17	WTR	12	PTI	8	XPV-WIL	AM	Follow, 86, Control Point, xpv-xrg, following 86 who had a newark station stop.
2163	WAS	34	CAR	21	CAR	12	NWK-NWK	AM	Door, 3261 3910 3650 3651 3652 3360 3653 , DOOR ISSUES DUE TO GAP FILLER MALFUNCTION
2166	BOS	17	CAR	9	CAR	7	WAS-WAS	AM	Heat / AC, ALL, CAR - RESETTING HVAC
2167	WAS	17	ITI	16	ITI	16	BOS-BOS	AM	Service, turn, or wye train, 2150, Late turn
2169	WAS	25	ENG	17	ENG	17	BOS-BOS	AM	Other electrical failure, 2129, has multiple alarms sounding off
2172	BOS	17	OTH	16	DCS	10	STM-NHV	MN	Restrictive signal(s) from unknown cause Stop, Control Point, 271
2173	WAS	152	SVS	126	SVS	126	BOS-BOS	AM	Water, commissary, toilet/trash dumping, AM2173 will dp BOS late a/c in SHSY waiting to get water
86	BOS	42	PTI	15	SMW	9	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD F/AM93 A/C 1 TRK OOS PELHAM BAY TO LEGGETT
94	BOS	38	ENG	35	ENG	26	NWK-NWK	AM	Other electrical failure, 637, HELD A/C ET INSPECTING PANELGRAPH AT NEWARK
112	NYP	25	DCS	30	DCS	30	XHM-PJC	AM	T.O.L, Other, XHM-XGY, TOL ON 2 TRK
114	NYP	68	MTI	77	MTI	77	WAS-WAS	AM	Disabled train ahead, Control Point, NYP, CAR - 181 TURNED FOR 114 DELAYED DUE 1' 43" LATE SHOPPED CAR OUT OF NYP 82575 WHICH DELAYED THE TRAIN HERE IN WAS
131	WAS	20	SVS	26	SVS	26	NYP-NYP	AM	Planned Switch, ADDING ENG.645 TO WEST END A/C AM112 W/ONLY 1 ENGINE IN CONSIST
137	WAS	16	CTI	21	PTI	10	OSB-NHV	AM	Cross over or go around, 2169, Milepost w/Letters, OSB, NHV, AM137 was held for late AM2169 to clear
167	WAS	67	WTR	82	WTR	77	BOS-BOS	AM	Ice / snow on or under equipment, Other, BOS, AM167 delayed due to frozen pipe bursting in c/82601, entire car had to be removed from train set

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
177	PHL	42	WTR	23	WTR	23	BOS-BOS	AM	Ice / snow on or under equipment, Other, BOS, AM177 rpts leak in cafe/43376, they cut off the water to the car
181	WAS	103	CAR	117	CAR	117	NYP-NYP	AM	Air / Brake / Wheel, 82575, LATE F/SSYD SHOPPED CAR 82575 FOR UNSPECIFIED REASON SUBBED CAR 81541
486	GFD	21	CON	22	CON	22	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM86
494	GFD	20	CON	36	CON	36	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM94
644	NYP	28	DCS	25	DCS	25	XHM-TRE	AM	T.O.L, Other, XHM-XGY, TOL ON 2 TRK
646	NYP	13	WTR	12	WTR	12	NWK-NYP	AM	Ice / snow on or under equipment, Other, XBH, HELD A/C ICE PATROL IN SOUTH TUBE
680	BON	29	ENG	26	ENG	26	DHM-EXR	CS	Loading problem 87
681	BRK	Trn Cancelled	ENG	56	ENG	45	EXR-EXR	CS	Loading problem 87
682	BON		SYS	9	FTI	5	DHM-EXR	CS	Meet M426, Control Point, New Fields
688	BON		DCS	59	DCS	56	WOB-BON	MT	Restrictive signal(s) from known wayside signal failure Waited at front ladders of Tower A until Terminal dispatcher could take us, then received 3 rule 241 permissions to pass stop signals to get into station., Stop Signal, Control Point, Tower A
63	TWO	39	HLD	17	CTI	13	CRT-POU	MN	Follow man, Milepost, 43, 56
68	NYP	21	CTI	21	CTI	19	POU-CRT	MN	Follow metro north, local, Control Point, 72
233	ALB	19	CTI	8	CTI	8	YNY-CRT	MN	Follow MTA radar showed 5725 as only train in area ahead of us, mnrr, 5725?, Milepost, 25, 33
245	ALB	78	WTR	71	WTR	64	NYP-NYP	AM	Ice / snow on or under equipment, Other, NYP-NYP, LOSS OF POWER DUE TO ICE BUILD-UP
290	NYP	23	CTI	17	CTI	14	POU-CRT	MN	Follow metro, 874, Milepost, 62, 39
73	CLT	12	OTH	7	ADA	3	CYN-CYN	NS	Vision / hearing-impaired
74	RGH	11	OTH	9	FTI	4	CLT-KAN	NS	Cross over or go around NS P49, Control Point, AT&O Junction
41	MIA	75	FTI	119	FTI	31	ELY-CLE	NS	Meet 269, 29G, Control Point, 194.0
724	SAC	21	POL	16	POL	16	SUI-SUI	UP	Removal of passenger by police

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
727	SJC	15	MBO	36	MBO	36	SUI-MTZ	UP	For maritime traffic Control Point, RV036
733	SJC	15	MBO	15	MBO	15	SUI-MTZ	UP	For maritime traffic Control Point, Rv036
746	SAC	120	ENG	126	ENG	126	SJC-SJC	UP	Air / Brake C8314
747	SJC	90	TRS	79	TRS	79	EMY-OKJ	UP	Vehicle strike Webster Street. Collision with vehicle, occupants fled scene, no injuries to passengers onboard., Milepost, 6.95, 6.95
505	PDX	35	SVS	33	SVS	33	SEA-SEA	BN	Planned set out / pick out of locomotives, cars or section of train Locomotive swap in Seattle; late departure from yard.
518	VAC	44	FTI	24	FTI	24	XF2-X1J	BN	Cross Traffic CN, Bridge, Fraser
14	SEA	114	TRS	191	TRS	191	PRB-SNS	UP	Trespasser strike Milepost, 118, 118
339	MKE	13	CTI	11	RTE	10	GLN-XRO	ME	Dispatcher hold Held at Deerfield on #1 behind 2135. Was originally going to wait for an inbound 2150 to pass on #2; after waiting dispatcher decided to send us and hold 2150 at Lake Forest. Multiple Metras stopped due to pedestrian strike on Fox Lake sub., Control Point, Deerfield
350	PNT	40	DCS	28	DCS	20	JXN-ARB	MI	Wayside detector failure including false actuation Leoni detector said dragging equipment axel 23. Lots of low hanging ice. Chopped off. No hanging hoses, Milepost, 67, 67
354	PNT	47	PTI	44	PTI	44	KAL-XGO	MI	Meet Held out at Gord for meet with late westbound 355, 355, Control Point, Gord
355	CHI	No OS Rpt	TRS	208	TRS	208	XGO-KAL	MI	Trespasser strike Other, 124.1
365	CHI	49	FTI	16	PTI	16	XGO-KAL	MI	Meet Amtrak 350, Control Point, 124
761	SLO	35	DCS	27	PTI	15	MPK-XMR	UP	Meet amtk, Control Point, los possas
770	SAN	16	DBS	19	DBS	19	CML-XMR	UP	Debris strike Struck crossing gate, debris hit the hoses between cars 4/5 and caused a air leak and also MU cable, all got resolved and fixed., Crossing gate, Milepost, 414.5, 414.5
774	SAN	32	DCS	53	DCS	39	LPS-X3G	UP	Restrictive signal(s) from known wayside signal failure Track side signal issue at intermediate MP CO 311, Red, Milepost, 305, 313
779	SLO	31	CTI	40	CTI	12	NRG-CWT	SC	Blocked from station track Two step, metrolink, 124, Control Point, Bernson
703	SAC	No OS Rpt	OTH	6	OTH	6	HNF-HNF	BN	Person pulling emergency cord
710	BFD	58	SYS	63	PTI	10	COC-WAC	BN	Meet 717, Control Point, E Elmo

Amtrak Endpoint OTP Details

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
712	BFD	49	FTI	40	FTI	31	TRK-MCD	BN	Meet BNSF 8395, Siding, balico
713	OKJ	Trn Cancelled	ADA	19	TEN	15	MTZ-MTZ	UP	Loading problem C2104
715	OKJ	25	PTI	27	PTI	15	WAC-COC	BN	Meet 702, Control Point, Allensworth
717	OKJ	Trn Cancelled	PTI	16	TEN	8	BFD-BFD	BN	Dead loco battery C2010
4	CHI	84	SYS	83	PTI	32	HUT-NEW	BN	Meet Per dispatch we had to wait for train 3, train 3, Control Point, first street
306	CHI	No OS Rpt	PTI	17	PTI	9	BNL-PON	UP	Meet Amtk307, Milepost, 92, 92
307	STL	71	CAR	94	CAR	94	CHI-CHI	AM	Door 25110
390	CHI	25	FTI	28	DBS	19	RTL-GLM	CC	Debris strike Struck some scrap hard plastic between rails.knocked out main res and brake pipe on two cars, Control Point, 85
392	CHI	No OS Rpt	DSR	6	DSR	4	CEN-EFG	CC	Per bulletin Milepost, 243.3, 243.1, 60, main, Milepost, 232.52, 232.52, 60, main, Milepost, 229.43, 229.43, 25, main
311	KCY	21	PTI	19	PTI	19	JEF-SED	UP	Meet AMT 318, Siding, Shell
1106	DEN	15	FTI	24	FTI	24	XXP-XFJ	BN	Blocked from station track BNSF, Unknown, Control Point, 23rd street
1333	MSP	Trn Cancelled	ENG	197	ENG	196	LSE-LSE	CP	HEP 4

Amtrak Initial Terminal Details

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/2/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	624	01/02	2	2	Ice / snow on or under equipment, Control Point, .. Frozen doors
HAR	648	01/02	1		
HAR	650	01/02	1		
HAR	654	01/02	1		
HAR	658	01/02	1		
PHL	110	01/02	1		
PHL	190	01/02	2	2	Door, .. FROZEN DOORS
PHL	601	01/02	3	3	Planned set out / pick out of locomotives, cars or section of train, EQUIPMENT BLOCKING DEPARTURE FROM YARD
PHL	605	01/02	1		
RNK	66	01/02	2	2	Water, commissary, toilet/trash dumping
SFA	52	01/02	18	18	EOT device Engine 352, 3520
WAS	56	01/02	2	2	Delay in Block, CREW STARTED CLOSING DOORS AND TRAPS AT DP TIME.
WAS	84	01/02	14	14	Air / Brake / Wheel, 43392 , SHOPPED FOR BRAKES.
WAS	114	01/02	77	77	Disabled train ahead, Control Point, NYP, CAR - 181 TURNED FOR 114 DELAYED DUE 1' 43" LATE SHOPPED CAR OUT OF NYP 82575 WHICH DELAYED THE TRAIN HERE IN WAS
WAS	130	01/02	2	2	Delay in Block, THE AC DIDN'T PUSH THE D HANDLE COMPLETELY IN WHICH CAUSED THE DOOR LIGHT TO COME ON AT DP TIME.
WAS	192	01/02	5	5	Pick up equipment, awaiting new motor for train; after originally assigned motor not coupled in S&I before departing for the station
WAS	2154	01/02	11	11	Door, ALL, NG 12, WHEN THE CREW ARRIVED TO THE TRAIN THEY COULD NOT GAIN ENTRY. MECH WAS CALLED. MECH FRM SAID THEY HAD TO RESET THE TRAIN
WAS	2166	01/02	7	7	Heat / AC, ALL, CAR - RESETTING HVAC
ALB	238	01/02	8	8	Pick up equipment
BOS	177	01/02	23	23	Ice / snow on or under equipment, Other, BOS, AM177 rpts leak in cafe/43376, they cut off the water to the car
BOS	2163	01/02	6	6	Toilet, 3360, 2163 and rpts the bathroom in car 7 is locked out due to a clogged pipe/The pipes in cafe car 3360 are clogged as well.
BOS	2167	01/02	16	16	Service, turn, or wye train, 2150, Late turn
BOS	2169	01/02	17	17	Other electrical failure, 2129, has multiple alarms sounding off
BOS	2173	01/02	126	126	Water, commissary, toilet/trash dumping, AM2173 will dp BOS late a/c in SHSY waiting to get water
BRK	686	01/02	(Trn Cxld)		Engine Issue

Amtrak Initial Terminal Details

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/2/2026

Terminal	Train	Date	Late	Delay	Cause
NHV	474	01/02	8	5	Hold for connecting train, departed late due to late connection of AM174
NHV	474	01/02	8	3	Routine inspections, went back into yard to inspect engine
NHV	478	01/02	7	7	Dispatcher hold, Other, NHV, delayed signal on the MNRR side
NYP	19	01/02	4	4	Passenger and/or baggage, LOADING
NYP	63	01/02	11	11	Passenger and/or baggage, LOADING
NYP	97	01/02	4	4	Passenger and/or baggage, LOADING
NYP	119	01/02	4	4	Passenger and/or baggage, LOADING
NYP	129	01/02	14	14	Service, turn, or wye train, 114, LATE TURN OFF AM114
NYP	131	01/02	26	26	Planned Switch, ADDING ENG.645 TO WEST END A/C AM112 W/ONLY 1 ENGINE IN CONSIST
NYP	181	01/02	117	117	Air / Brake / Wheel, 82575, LATE F/SSYD SHOPPED CAR 82575 FOR UNSPECIFIED REASON SUBBED CAR 81541
NYP	233	01/02	6	6	Passenger and/or baggage, LOADING
NYP	2117	01/02	2	2	Passenger and/or baggage, LOADING
CHI	343	01/02	73	73	Set out defective car 4103
PDX	28	01/02	125	125	Air / Brake Compressed air leak, 164
SEA	505	01/02	33	33	Planned set out / pick out of locomotives, cars or section of train Locomotive swap in Seattle; late departure from yard.
BFD	717	01/02	8	8	Dead loco battery C2010
BFD	719	01/02	10	10	Waited for equipment (710). Late arrival of 710 710, Other, Bakersfield
LAX	580	01/02	4	4	Water, commissary, toilet/trash dumping Await commissary to load train., Control Point, terminal
OKJ	710	01/02	11	2	Meet Held for arrival of 723, 723, Control Point, N Jack london
OKJ	710	01/02	11	9	Restrictive signal(s) from unknown cause Waiting for down line signal to time out unknown cause, Stop, Control Point, N Jack London
OKJ	712	01/02	3	3	Follow 724, Control Point, OKJ
OKJ	718	01/02	22	5	Meet 715, 745, 744, Control Point, north jack london
OKJ	718	01/02	22	4	PTC not logging in 90218
OKJ	718	01/02	22	13	Service, turn, or wye train 713, Engine 2104 massive oil leak. Tasi forces to rectify situation before leaving yard
SAN	573	01/02	1		
SAN	593	01/02	1		
SJC	724	01/02	2	2	Restrictive signal(s) from unknown cause Red, Other, SJC

Amtrak Initial Terminal Details

26-FOI-00217 00000005556 "UNCLASSIFIED" 1/5/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 1/2/2026

Terminal	Train	Date	Late	Delay	Cause
SJC	728	01/02	1	1	Door C8310, Persistent door light issue.
SJC	738	01/02	21	21	Air / Brake Unable to get a good class 2., C2002
SJC	746	01/02	126	126	Air / Brake C8314

Eastern Region

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	86.2	86.2	90.2	58	8
SEPTA	95.0	98.1	96.9	91.5	215	4
NJT-NED	95.0	No Data	No Data	93.8	No Data	No Data
NJT-SED	95.0	100	100	97.2	20	0

Operating Highlights

Train 40(02) North of Savannah, GA - Freight Train Interference

03JAN26: Train 40(02) operating with engines 15, 154, and 10 cars was delayed starting 25 miles north of Savannah, GA on the CSX Columbia subdivision following CSX M692-02 from Scotia milepost 466.1 to Gifford Yard milepost 434.9.

Train	Delay	Comment
40(02)	30"	

Train 2173(02) Boston, MA - Late Watering

02JAN26: Train 2173(02) operating with NG-12, PC/2133, PC/2124, was delayed departing Boston, MA due to a late yard release, account of needing to be watered.

Train	Delay	Comment
2173(02)	2'06"	

Train 2151(02) New London, CT - B&B Work Due to Defect

02JAN26: At 627A-ET, The Boston Chief reported that Train 2151(02) was delayed on the New Haven to Boston Main Line at MP 122.5 due to the Shaw's Cove Bridge not locking. As of 652A-ET, B&B was on scene. As of 703A-ET, The bridge was closed and signals were displayed and the train proceeded west.

Train	Delay	Comment
2151(02)	32"	

Train 681(02) Exeter, NH - Engine Failure

02JAN26: Train 681(02) 26-FOI-00217 500000005556 95 "UNCLASSIFIED"rs, 1/5/2026 delayed at Exeter, NH due to engine E/87 stopped with loading issues. Earlier, Train 680(02) displayed the same issue with E/87 and was also delayed east of Exeter. Head end power remained active during this incident. Out of precaution, the protect engine was readied with a crew from Portland yard in case a rescue became necessary. The crew was able to troubleshoot and recycled the engine in order to resolve the loading issues. The train proceeded to Portland operating reduced speeds to reduce the load on the engine.

Train 681(02) was terminated at Portland, ME where engine E/87 was capped with the protect engine E/107, then turned for an on-time 686(02). A total of 60 passengers from 681(02) and 686(02) were provided alternate bus transportation between Portland and Brunswick, ME.

WBS#: B.TR.100150.6367

Train	Delay	Comment
681(02)	Term POR w/ALT	56"
686(02)	Originated POR	Bus BRK-POR
680(02)	26"	EXR

Train 41(01) Pittsburgh, PA - Late Fuel

02JAN26: Train 41(01) was delayed at Pittsburgh, PA/MP353.1, on the NSRR Pittsburgh Line, due to waiting for a late fuel truck. Once truck arrived and fueling was complete, Train 41(01) departed the station operating 1 hour and 4 minutes late.

Train	Delay	Comment
41(01)	1'04"	

Train 181(02) New York, NY - Car Failure

02JAN26: Train 181(02) operating with engine 655, 10 cars, and engine 605 was delayed departing New York, NY due to car 82575 being shopped for car 81541. Once the swap and inspections were complete, the train was released by Sunnyside Yard and operated to Penn station to board 225 passengers.

Train	Delay	Comment
181(02)	1'57"	
114(02)	1'17"	ITD -Equip Turn off 181

Eastern Region

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standeers

Train	Projected Need		Number Operated		Standeers	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 2167(02) Passenger Removal at Providence, Rhode Island –Intoxication***

02JAN26, Passenger on PNR 430735, traveling from Boston, MA to Baltimore, MD, was removed from the train by APD. The passenger was found slumped over the chair in the aisle. Amtrak Police notified.

Delay: 2167(02) None

Train 290(02) Passenger Removal at Yonkers, New York – Medical

02JAN26, Passenger on PNR 0C867E, traveling from Burlington, VT to New York, NY was removed from the train by MTA Police after having a medical emergency concerning his heart. Amtrak Police notified.

Delay: 290(02) 7"

Operating Highlights

Train 2/422(02) Palm Springs, CA Station Closed due to Flooding

02JAN26: Local Palm Springs security detail in association with Palm Springs PD advised the roads surrounding Palm Springs Station are closed following flooding occurring through the area. Trains 1(31DCEC), 421(30DEC), 2(02JAN) and 422(02JAN) will be unable to make the stop. Affected passengers advised to use Ontario station, or thruway bus services to/from downtown Palm Springs which are unaffected.

Train	Delay	Comment
2/422(02)	PSN - Does Not Stop	

Train 41(02) West of Elyria, OH - Signal

03JAN26: Train 41(02) came to a stop at milepost 219.6, 13 miles west of Elyria, OH, on NS Cleveland-Toledo subdivision, due to NS switch failure ahead requiring train 41(02) to hand line their route. The crew had to manually operate 5 switches in order to line their route. There was no switch maintainer available to assist. Once the switches were lined, train 41(02) received permission from the dispatcher to proceed.

Train	Delay	Comment
41(02)	1'11"	

Train 343(02) Chicago, IL - Initial Terminal Delay

03JAN26: Train 343(02) was delayed departing Chicago, Illinois account switching out a Venture married pair, Cars ID4210/4103 for wheel shelling. Train 342(02) arrived Chicago at 911PM, 07" late. The train was flagged in for cuts at 931PM, but the cuts were delayed due to YC13 sitting south of the blue flagged equipment on Track 28, not tied onto it. Mechanical would not cut the cars with the engine and crew sitting on the same track. Once YC13 pulled South, mechanical made the cuts on the bad order cars, clearing at 1011PM. Crew YC13 began the switch move at 1028PM, and Train 343(02) was made up complete in CUS at 1122PM. Mechanical flagged the train in at 1127PM and cleared at 1230AM. Boarding began at 1230AM, gates cleared at 1235AM, and Train 343(02) departed Chicago at 1238PM.

Train	Delay	Comment
343(02)	1'12"	

Train 747(02) South of Emeryville CA - Occupied Vehicle Strike

02JAN26: At approximately 5:55 PM, Train 747(02) operating with camera equipped locomotive CDTX/2012, struck an occupied vehicle. The incident occurred at Webster Street rail crossing (DOT 7495876-N) at MP 6.83 Jack London Square, on the UPRR Niles Subdivision, 5 miles South of Emeryville, in Alameda County. The crossing is equipped with cross bucks, advance warning signs, quad gates, flashing lights and two bells. Authorized track speed at the location is 25MPH. There were no reported injuries to 55 passengers or crew. The occupants of the vehicle fled the scene shortly after impact and before the arrival of emergency services. There was no reported damage to the train. The weather was reported to be dark, raining 57°F. Oakland Police and EMS responded to the scene along with Oakland Road Foreman. Once investigations were completed, tracks inspected and vehicle removed, train 747(02) continued to Oakland Jack London Square. The Engineer and conductor did not request trauma relief at the scene. As a result of the extended delay, train 717(02) terminated in Emeryville, passengers for Oakland transferred to train 749(02). Amtrak Police and EAP were notified. National Response Center # 14-51850 California Department of Emergency Response # 26-0030

Train	Delay	Comment
747(02)	1'19"	
717(02)	Terminates Emeryville	Oakland Passengers to 749(02)

Train 355(02) Battle Creek, MI - Trespasser Incident

02JAN26: Train 355(02), operating with locomotive E/4627, five coaches, and 131 passengers, went into emergency at milepost 124.1, approximately four miles west of Battle Creek, MI, after striking a trespasser on the Amtrak Michigan Line. The incident did not occur at a crossing. No injuries were reported among passengers or crew, and no equipment damage was noted. Head-End Power remained active. Weather conditions were 14 degrees and cloudy. The crew requested relief, and the train held west of Battle Creek, resulting in an initial delay of one hour. Due to challenges in securing a relief crew, buses were sourced for alternate transportation, and an Amtrak Train Master responded with an ETA of two hours and thirty minutes. The delay extended to two hours and twenty-five minutes while arrangements were finalized. A recrew was scheduled to go on duty in Battle Creek at 11:55 PM to operate the train to Chicago. Three buses were arranged: two to run express to Chicago and one to make all intermediate stops, with an ETA of 12:30 AM to the train. Ultimately, train 355(02) was released with the recrew onboard and the buses shadowed the train to Chicago.

Train 354(02) was also delayed holding at Kalamazoo, MI, for an open route.

National Response Center Number: 1451858

Train	Delay	Comment
355(02)	3'28"	
354(02)	2'44"	

Train 746(02) Initial Terminal Delay San Jose, CA – Cab Car Compressed Air Problems

02JAN26: Train 746(02) operating with Cab Car CDTX/8314, 4 cars being pushed by CDTX/2107 on rear was delayed departing San Jose. After resolving issues with P.T.C signaling in San Jose station, the crew reported unable to maintain compressed air pressure in cab car CDTX/8314. After extensive troubleshooting, the crew were unable to make repairs. This led to plans to couple trains 746(02) and 748(02). As the crew were preparing to couple the trains, 746(02) was repaired, holding compressed air pressure. This restored tractive effort allowing the train to depart.

Train	Delay	Comment
746(02)	2'05"	SJC - ITD

Train 794(02) Delay South of Guadalupe, CA - Rocket Launch

02JAN26: The US Space Force launched the Falcon-9 rocket, from Vandenberg Space Base in Southern California AT 6:09PM-PT. The safe exclusion zone for this launch encompassed the railroad tracks South of Lompoc Station. This required train 794(02) be held at Lompoc Surf station, MP 299.3 Santa Barbara Subdivision of the Union Pacific Railroad- until the rocket was safely underway. Once the rocket had been launched, Union Pacific Maintenance-of-way personnel searched the tracks for potential fallen debris. Once given the 'all-clear' train 794(02) resumed.

Train	Delay	Comment
794(02)	1'07"	

Train 6(01) West of Denver, CO - Freight Train Derailment

02JAN26: Train 6(01) was delayed 1 miles east of Denver, CO, on UP Moffat Tunnel subdivision, due to a BNSF derailment and train separation in their yard. the derailment happened in their yard, leaving their equipment obstructing the main line. Once the freight was able to clear the portion of their train that was not derailed, a route was opened for 6(01) to proceed.

Train	Delay	Comment
6(01)	58"	

Train 28(31) at Portland, OR, - Initial Terminal Delay - Locomotive Compressed Air Leak.

02JAN26: Train 28(31) was delayed departing Portland after locomotive AMTK/164 developed multiple issues with compressed air leaks. This led to BNSF Freight Locomotive BNSF/8783 being leased to lead train 28(31) from Portland to Spokane (where train 8(31) portion was coupled).

Train	Delay	Comment
28(02)	2'05"	PDX - ITD

Train 5(31) West of Davis, CA - Delayed by Police Action

02JAN26: Train 5(31) was delayed 21 miles west of Davis, at Fairfield/Vacaville station. This was after reports of trespasser wandering the tracks ahead. Tracks were closed at Suisun, MP 48.9, Martinez Subdivision of the Union Pacific Railroad. As a result of the police action, tracks were closed in both directions until the tracks were clear of searching personnel. Amtrak Police Advised.

Train	Delay	Comment
5(31)	22"	

Train 1333(02) - Car Failure

02JAN26: At approximately 26-FOI-00247.00000005556, train 1333(02), 1/5/2026, operating with a consist of E/4, E/375, three coaches, and 186 passengers, reported losing Head-End Power (HEP) while en route. Despite the loss of power, the train continued dark to La Crosse, WI station. The crew began troubleshooting the issue with assistance from their RFE in an effort to restore HEP. At the time of the incident the outside temperatures were around 16 degrees and mostly sunny. During troubleshooting, car C/34137 was found to be smoking when attempting a short loop; the car was immediately isolated, and passengers were removed and efforts were made to short loop power to the remaining two cars in the consist. These efforts proved to be unsuccessful and the train continued to have HEP issues. Due to overcapacity conditions, resulting from C/34137 being taken out of service for no HEP, between LSE and MSP-LSE (-59), WIN (-57), and RDW (-71)-alternate bus transportation was arranged. Due to the car with no HEP 2 buses were sourced to accommodate overcapacity conditions.

The train continued to experience HEP issues, resulting in two additional buses being secured, bringing the total to four: two operating express to Saint Paul, MN, and two making all intermediate stops. Additional buses were also sourced for train 1340(03) operating between Saint Paul MN and Milwaukee, WI.

Ultimately, train 1333(02) was terminated at La Crosse, WI. All buses arrived and departed La Crosse, WI between 730pm-ct and 745pm-ct.

Service recovery efforts began, including providing snack packs, water, and coffee to customers.

Train	Delay	Comment
1333(02)	Terminated LSE	

Train 712(02) East of Turlock/Denair, CA - Freight Train Interference

02JAN26:

Train 712(02) was diverted into the siding 8 miles east of Turlock/Denair station at Balco MP1071.1, Stockton Subdivision, BNSF Railroad. This was to allow for BNSF freight train BNSF/8395 to pass on the single mainline. Once the track ahead was clear train 712(02) was able to resume to Merced.

Train	Delay	Comment
712(02)	31"	

Train 4(31) East of Fort Madison, IA - PTC Failure

02JAN26: Train 4(31), E/147-E/190-9 Cars, reported losing PTC 47.9 miles east of Fort Madison, IA/MP232.9, on the BNSF Chillicothe Subdivision, at MP185.2. The crew contacted the BNSF PTC desk and permission was granted to cutout I-ETMS. Once complete, Train 4(31) continued to Chicago not exceeding 59MPH.

Train	Delay	Comment
4(31)	59"	

Train 724(02) Suisun-Fairfield, CA - Police Related

02JAN26: Train 724(02) was delayed at the Suisun-Fairfield depot, MP 48.9/UPRR Martinez Subdivision, while local police responded as a result of 2 passengers in a physical fight aboard the train. One passenger fled the station before arrival of local police. Amtrak Police Notified.

Train	Delay	Comment
724(02)	17"	

02JAN26: At 11:20AM-CT, Train 390(02), EUNCLASSIFIED Cars, reported striking hard plastic debris between the rails that caused the main reservoir and brake pipe between cars 34107 and 34028 to separate. The strike occurred 3 miles south of the Gilman, IL station/MP82.0, on the CNRR Chicago Subdivision, at MP85.0. There were no injuries reported to the crew or 198 passengers onboard and no damage to the equipment. Once the hoses were secured and air restored, Train 390(02) was back on the move at 11:36AM-CT.

Train 391(02) South of Gilman, IL - Debris

Train 11(01) South of San Jose, CA - Close Call With Trespasser

Train 505(02) Initial Terminal Seattle, WA - Late Release

Train 770(02) South of Camarillo, CA - Debris

Train	Delay	Comment
770 (02)	19"	

Train 774(02) South of Lompoc-Surf, CA - Signal

02JAN26: Train 774(02) was delayed at Lompoc-Surf, CA (MP 305) as a result of the signal being and operating at reduced speeds through a signal outage on the UPRR Santa Barbara Subdivision between Honda, MP 305 (5.7 miles south of Lompoc-Surf) and MP 311.

Train	Delay	Comment
774(02)	39"	

Train 727(02) West of Suisun-Fairfield, CA - Drawbridge Opening

02JAN26: Train 727(02) was delayed at Benicia, MP 35/UPRR Martinez Subdivision, 13.9 miles west of Suisun as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass.

Train	Delay	Comment
720(02)	15"	
727(02)	36"	

Train 4(31) West of Newton, KS - Passenger Train Interference

02JAN26: Train 4(31) held 0.3 miles west of Newton, KS/MP185.1, on the BNSF La Junta Subdivision, at First St/MP185.4 meeting Train 3(01).

Train	Delay	Comment
4(31)	32"	

Train 713(02) Terminates Emeryville, CA – Low Coolant Warning

02JAN26: Train 713(02) departed Richmond, CA (RIC) with locomotive CDTX/2104 leading. The crew reported excessive 'slack' movement and low coolant fault. To ensure timely repair, the train terminated in Emeryville to enter Oakland Maintenance Facility via Kirkham entrance to turn for 718(30). Twenty - Seven (27) passengers travelling to Oakland transferred to train 743(31) after a 14 minute wait.

Train	Delay	Comment
713(02)	Terminates EMY	Oakland Passengers to 743(02)
718(02)	21"	OKJ - ITD - CDTX/2104

Train 7/27(31) West of Sandpoint, ID - Switch Failure

02JAN26: Train 7/27(31) was delayed 31.8 miles west of Sandpoint, ID/MP3.1, on the BNSF Kootenai River Subdivision, due to switch failure at Silver/MP34.9. The Conductor reported having to manually line the switch. Once this was complete, Train 7/27(31) continued to Spokane.

Train	Delay	Comment
7/27(31)	42"	

Train 3(31) West of Flagstaff, AZ - Freight Train Interference

02JAN26: Train 3(31) was delayed starting 14.9 miles west of Flagstaff, AZ/MP344.2, on the BNSF Seligman Subdivision, between MP359.1 and Kingman, AZ/MP516.3 following BNSF 8395.

Train	Delay	Comment
3(31)	40"	

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

- Train 520(29-30) Cancelled - No alternate transportation.
- Train 534(29-30) Cancelled - No alternate transportation.
- Train 535(29) Cancelled - No alternate transportation.
- Train 537(30) Cancelled - No alternate transportation.
- Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

- Train 520(31) Cancelled - No alternate transportation.
- Train 534(31) Cancelled - No alternate transportation.
- Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

- Train 736(01-04) Cancelled - No alternate transportation.
- Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-05MAR) Cancelled - No alternate transportation.
- TRAIN 713(05JAN-06MAR) Cancelled - No alternate transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
-------	-------	---------

718 (21)	Originate	Passengers to 744 (21) OKJ-EMY
	EMY	
718 (22)	Originate	Passengers to 744 (22) OKJ-EMY
	EMY	
714 (22)	1'07"	ITD - OKJ - Late change of equipment
718 (21)	37"	ITD - EMY
716 (22)	20"	
718 (22)	3'10"	ITD - EMY
714 (23)	.	CANCELLED
713 (24)	.	CANCELLED
535 (24)	Cancelled	
520 (24)	Cancelled	
534 (24)	Cancelled	
736 (25-28)	Cancelled	
737 (25-28)	Cancelled	
749 (28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751 (28)
551 (29-30)	Cancelled	Replacement Bus SAC-OKJ
520 (29-31)	Cancelled	No alternate transportation.
534 (29-31)	Cancelled	No alternate transportation.
736 (01JAN-04JAN)	Cancelled	No alternate transportation
737 (01JAN-04JAN)	Cancelled	No alternate transportation
535 (29)	Cancelled	No alternate transportation.
537 (30-31)	Cancelled	No Alternate Transportation
713 (05JAN-06MAR)	CANCELLED	No Alternate Transport Offered
714 (05JAN-05MAR)	CANCELLED	No Alternate Transport Offered

Western Region

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
28 (2)	PDX	BNSF8783	E/164 Brake controller faults	SPK	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
381	QCY	1	QCY	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 21(01) Passenger Removal at Texarkana, Arkansas –Improper Conduct***

02JAN26, Passenger on PNR 41DB70, traveling from Chicago, IL to San Antonio, TX was removed by conductor due to improper conduct. The passenger was yelling and screaming saying she was possessed by a demon. Amtrak Police notified.

Delay: 21(01) None

Train 1333(02) Passenger Removal at Sturtevant, Wisconsin –Improper Conduct

02JAN26, Passenger on PNR 3CBFBE, traveling from Chicago, IL to St. Paul-Minneapolis, MN was removed by local law enforcement. The passenger was involved in an incident with using profanity towards the conductor. Amtrak Police notified.

Delay: 1333(02) None

Train 6(01) Passenger Removal at Glenwood Springs, Colorado – Improper Conduct

02JAN26, Passenger on PNR D8DCEF, traveling from Sacramento, CA to Chicago, IL was removed by local Police after exposing himself in front of other passengers. Amtrak Police notified.

Delay: 6(01) 18"

Train 518(02) Passenger Removal at Everett, Washington – Improper Conduct

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

02JAN26, Passenger on PNR EDC17B, traveling from Portland, OR to Vancouver, BC was removed from the train by Everett Security assaulting a female passenger. Amtrak Police notified.

Delay: 518(02) 10"

Consist Deviations

26-FOI-00217

00000005556

"UNCLASSIFIED"

1/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2155 (02)	BOS	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
179 (02)	BOS	BUSSINESS CLASS ON THE HEAD END BACKWARDS (A LEADING), REST ON THE CONSIST HAS THE CORRECT ORIENTATION	0	0	81522
2163 (02)	BOS	WILL OPERATE WITH NEXT GEN EQUIPMENT, SCHEDULE CHANGE IS COMPLETED	0	0	
167 (03)	BOS	TURN FROM SHORT 162(03), 1 CAR SHORT	0	0	
2249 (03)	BOS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED	0	0	
48 (01)	CHI	deadhead 62031 (4812) in line due to frozen toilets. please accomodate passengers.	Pax downgraded to coach	26	62031
301 (02)	CHI	NO CAFE- short on cafe equipment.	No food available.	159	
306 (02)	CHI	NO CAFE- short on cafe equipment.	No food available	80	
307 (01)	CHI	using a amfleet 2 coach in lieu of venture coach. no impact to ridership	0	0	25110
6 (02)	CHI	61006 shopped with no replacement. all checked bags to go on bag coach.	No impact	0	61006
4 (03)	LAX	Please block the H-room on the 0432 car on 4(03). dorm not equipped w/ h-room.	0	0	39009
1333 (02)	LSE	Byd inline, causing HEP to trip. Customer service noitfied. will effect 1340(03) as well	Passenger bussed	184	34137
98 (02)	MIA	62503 (9811) Viewliner II sleeper in lieu of Viewliner I sleeper.	Pax had to be downgraded	4	62503
1340 (03)	MSP	Byd inline, causing HEP to trip. Customer service noitfied.	Alternate transporation being provided	120	34137
186 (02)	NPN	COACH SHOPPED NPN DEADHEAD INLINE NO PASSENGERS, COACH WILL BE REMOVED IN WAS NO REPLACEMENT	0	0	82622

Train Number	Station	Reason 26-FOI-00217 00000005556 "UNCLASSIFIED"	Customer Impact	Affected Psgr	Unit Number(s)
2117 (02)	NYP	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
2107 (02)	NYP	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
181 (02)	NYP	Business Class car in lieu of coach car	No impact	0	81518
129 (02)	NYP	BUSINESS CLASS OPERATING IN LIEU OF COACH	0	0	81541
2190 (02)	NYP	WILL OPERATE WITH NEXT GEN EQUIPMENT, SCHEDULE CHANGE IS COMPLETED	0	0	
151 (03)	PHL	SHORT FROM TURN 186(02), SHORT 1 CAR	0	0	
66 (03)	RNK	SHORT FROM TURN 151(03), 1 CAR SHORT	0	0	
302 (02)	STL	using a amfleet 2 coach in lieu of venture coach. no impact to ridership	0	0	25110
2104 (02)	WAS	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
2172 (02)	WAS	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
2122 (02)	WAS	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
2166 (02)	WAS	NEXT GEN ACELA IN LIEU OF LEGACY ACELA	No impact	0	
114 (02)	WAS	BUSINESS CLASS CAR OPERATING IN LIEU OF COACH	0	0	81541
86 (02)	WAS	BUSSINESS CLASS ADD ON AT WAS WILL BE PLACED ON THE HEAD END, BUSINESS CAR WILL BE BACKWARDS ON THE HEAD END (A LEADING)	0	0	81522
162 (03)	WAS	SHORT EQUIP WAS, SHORT 1 CAR	0	0	
2218 (03)	WAS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED	0	0	
192 (02)	WAS	EQUIPMENT SWAPPED OVER FROM 196(02) TO MIN DELAYS. OPERATING ONE CAR SHORT	No impact	0	

Reverse Consists

Train Number	Station	Reason	
		26-FOI-00217	00000005556 "UNCLASSIFIED" 1/5/2026
85 (02)	BOS	Consist reversed	Business class seat orientation may have changed At Front
183 (02)	NYP	Consist reversed	Business class seat orientation may have changed At Front
190 (02)	PHL	Consist reversed	Business class seat orientation may have changed At Front
2155 (02)	BOS	Acela consist reversed First class at Rear	
2159 (02)	BOS	Acela consist reversed First class at Rear	
137 (02)	BOS	Consist reversed	Business class seat orientation may have changed At Front
164 (03)	RVM	Consist reversed	Business class seat orientation may have changed At Front
125 (02)	SPG	Consist reversed	Business class seat orientation may have changed At Front
192 (02)	WAS	Consist reversed	Business class seat orientation may have changed At Rear
196 (02)	WAS	Consist reversed	Business class seat orientation may have changed At Front
194 (03)	NPN	Consist reversed	Business class seat orientation may have changed At Front