



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, November 06, 2025

Rules: 0-2



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 11/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/05/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	304	35	88.5%	1,456	172	88.2%	10,529	1,222	88.4%
Central Division	85.5%	67	2	97.0%	334	17	94.9%	2,370	220	90.7%
Northeast Division	80.0%	94	11	88.3%	449	60	86.6%	3,293	428	87.0%
Southeast Division	72.5%	73	12	83.6%	337	46	86.4%	2,472	253	89.8%
Southwest Division	77.0%	70	10	85.7%	336	49	85.4%	2,394	321	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00103 00000005199 UNCLASSIFIED Endpoint Arrival Dates through 11/5/25 11/14/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	86,026	12,572	85%	489,737	72,450	85%	3,587,234	656,450	82%
Northeast Corridor	81%	41,402	4,041	90%	219,528	29,880	86%	1,622,473	248,509	85%
Acela	83%	10,674	1,061	90%	47,710	6,383	87%	342,859	54,566	84%
Northeast Regional	79%	30,728	2,980	90%	171,818	23,497	86%	1,279,614	193,943	85%
Richmond / Newport News / Norfolk	77%	9,309	1,396	85%	50,926	9,422	81%	388,613	70,312	82%
Springfield Shuttles	89%	650	124	81%	3,516	412	88%	19,970	1,765	91%
Roanoke	79%	2,506	356	86%	13,608	1,840	86%	96,800	14,917	85%
On Spine Northeast Regional	80%	18,263	1,104	94%	103,768	11,823	89%	774,231	106,949	86%
State Supported	80%	33,994	4,022	88%	210,821	28,064	87%	1,526,129	265,463	83%
Borealis	60%	425	0	100%	2,804	40	99%	21,766	5,662	74%
Capitol Corridor	90%	3,928	742	81%	19,273	1,105	94%	118,668	9,239	92%
Carolinian	60%	875	299	66%	5,713	1,080	81%	44,582	13,629	69%
Cascades	63%	1,405	432	69%	10,483	1,950	81%	82,731	21,480	74%
Downeaster	82%	1,021	56	95%	7,022	199	97%	51,955	9,333	82%
Empire	78%	3,903	2	100%	23,908	4,415	82%	187,936	36,656	80%
Adirondack	72%	232	0	100%	1,396	243	83%	12,731	4,051	68%
Ethan Allen Express	70%	476	0	100%	2,527	540	79%	21,862	5,736	74%
Maple Leaf	70%	454	2	100%	3,311	1,281	61%	21,684	7,658	65%
New York - Albany	85%	1,730	0	100%	10,255	1,406	86%	82,375	11,816	86%
New York - Niagara Falls	75%	1,011	0	100%	6,419	945	85%	49,284	7,395	85%
Gold Runner	73%	1,421	356	75%	10,529	3,657	65%	83,693	27,036	68%
Heartland Flyer	65%	106	21	80%	891	248	72%	7,271	4,975	32%
Hiawatha	90%	1,412	187	87%	8,372	602	93%	62,180	7,585	88%
Illinois	78%	1,509	87	94%	11,540	1,713	85%	90,608	19,174	79%
Carl Sandburg / Illinois Zephyr	85%	206	0	100%	1,763	71	96%	14,175	3,149	78%
Illini / Saluki	85%	543	0	100%	4,421	595	87%	34,235	5,480	84%
Lincoln Service	70%	760	87	89%	5,356	1,047	80%	42,198	10,545	75%
Keystone	92%	8,451	604	93%	40,137	3,386	92%	292,380	21,681	93%
Lincoln / Missouri	60%	534	85	84%	3,611	1,555	57%	28,656	14,804	48%
Mardi Gras Service	80%	378	45	88%	2,025	128	94%	16,952	2,605	85%
Michigan	69%	1,186	3	100%	9,099	1,822	80%	67,850	14,171	79%
Blue Water	70%	263	0	100%	2,236	277	88%	18,365	4,446	76%
Pere Marquette	85%	188	0	100%	1,168	0	100%	9,344	1,064	89%
Wolverine	65%	735	3	100%	5,695	1,545	73%	40,141	8,661	78%
Missouri	80%	111	0	100%	1,074	157	85%	8,358	1,970	76%
Pacific Surfliner	85%	5,089	894	82%	38,106	4,811	87%	227,691	25,503	89%
Pennsylvanian	72%	738	9	99%	4,350	34	99%	33,672	3,975	88%
Piedmont	73%	579	198	66%	5,442	1,019	81%	49,203	15,648	68%
Vermont	75%	923	2	100%	6,442	143	98%	49,977	10,337	79%
Long Distance	56%	10,630	4,509	58%	59,388	14,506	76%	438,632	142,478	68%
Auto Train	57%	651	651	0%	3,531	1,354	62%	22,720	4,216	81%
California Zephyr	50%	760	169	78%	4,061	634	84%	33,662	10,818	68%
Cardinal	55%	247	247	0%	1,274	499	61%	10,534	5,486	48%
City Of New Orleans	75%	603	88	85%	3,335	631	81%	25,609	5,708	78%
Coast Starlight	60%	884	584	34%	5,601	2,082	63%	39,624	12,403	69%
Crescent	70%	655	114	83%	4,693	1,567	67%	34,106	10,991	68%
Empire Builder	55%	914	448	51%	4,403	1,574	64%	35,138	11,127	68%
Floridian	40%	1,480	801	46%	8,489	2,476	71%	60,461	29,297	52%
Lake Shore Ltd	73%	752	100	87%	4,294	426	90%	32,476	3,852	88%
Palmetto	65%	760	28	96%	4,623	33	99%	34,411	5,007	85%
Silver Meteor	45%	740	214	71%	5,081	782	85%	34,821	8,080	77%
Southwest Chief	40%	788	322	59%	3,878	1,056	73%	30,560	18,181	41%
Sunset Ltd	70%	274	85	69%	1,162	188	84%	9,725	2,502	74%
Texas Eagle	50%	1,122	658	41%	4,963	1,204	76%	34,785	14,810	57%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00100 00000005100 "UNCLASSIFIED" 11/14/2025

Train Index Dates Through November 05, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	22,309	530,147	421	186,106	3,834,534	485

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	1,114	153,396	73	7,281	1,117,497	65
INFRASTRUCTURE PLANNED	130	818	153,396	53	6,475	1,117,497	58
FLEET RELIABILITY	90	2,633	530,147	50	26,263	3,834,534	68
TRAIN OPERATIONS	427	17,744	530,147	335	146,087	3,834,534	381

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

26-FOI-00103Initial Terminal Performance By Division

Scheduled Departure Date: 11/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/05/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	304	35	88.5%	1,456	172	88.2%	10,529	1,222	88.4%
Central Division	85.5%	67	2	97.0%	334	17	94.9%	2,370	220	90.7%
Northeast Division	80.0%	94	11	88.3%	449	60	86.6%	3,293	428	87.0%
Southeast Division	72.5%	73	12	83.6%	337	46	86.4%	2,472	253	89.8%
Southwest Division	77.0%	70	10	85.7%	336	49	85.4%	2,394	321	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 11/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/05/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	304	35	88.5%	1,456	172	88.2%	10,529	1,222	88.4%
Central Division	85.5%	67	2	97.0%	334	17	94.9%	2,370	220	90.7%
CDL	90.0%	2	0	100.0%	10	0	100.0%	72	5	93.1%
CHI	85.0%	27	0	100.0%	135	5	96.3%	963	76	92.1%
EUG	86.5%	2	0	100.0%	10	1	90.0%	67	6	91.0%
GRR	98.0%	1	0	100.0%	5	0	100.0%	36	0	100.0%
KCY	84.5%	2	0	100.0%	10	0	100.0%	70	6	91.4%
MKE	86.5%	6	1	83.3%	29	2	93.1%	211	23	89.1%
MSP	94.0%	1	0	100.0%	5	0	100.0%	36	0	100.0%
PDX	78.0%	5	0	100.0%	25	4	84.0%	181	28	84.5%
PNT	91.5%	3	0	100.0%	15	1	93.3%	54	3	94.4%
PTH	93.0%	1	0	100.0%	5	0	100.0%	36	2	94.4%
QCY	87.5%	2	0	100.0%	10	1	90.0%	72	9	87.5%
SEA	80.0%	8	1	87.5%	40	2	95.0%	285	44	84.6%
SPK	92.0%	1	0	100.0%	5	0	100.0%	36	1	97.2%
STL	88.0%	4	0	100.0%	20	1	95.0%	144	9	93.8%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	10	0	100.0%	72	3	95.8%
Northeast Division	80.0%	94	11	88.3%	449	60	86.6%	3,293	428	87.0%
ALB	91.5%	6	0	100.0%	30	2	93.3%	216	7	96.8%
BON	43.5%	4	1	75.0%	23	1	95.7%	164	22	86.6%
BOS	86.5%	19	0	100.0%	90	5	94.4%	645	54	91.6%
BRK	88.0%	3	0	100.0%	21	2	90.5%	148	8	94.6%
BTN	48.0%	1	0	100.0%	5	2	60.0%	36	12	66.7%
DOV	-	1	0	100.0%	2	1	50.0%	2	1	50.0%
GFD	86.0%	2	1	50.0%	8	3	62.5%	70	6	91.4%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	1	0.0%	5	1	80.0%	36	6	83.3%
NFL	96.5%	2	0	100.0%	10	0	100.0%	72	4	94.4%
NHV	75.5%	5	3	40.0%	26	10	61.5%	178	35	80.3%
NYP	77.5%	42	4	90.5%	187	28	85.0%	1,397	244	82.5%
SAB	98.0%	1	0	100.0%	5	0	100.0%	36	0	100.0%
SPG	88.0%	6	0	100.0%	32	3	90.6%	198	10	94.9%
TWO	84.0%	1	1	0.0%	5	2	60.0%	35	6	82.9%
WEM	-	-	-	-	-	-	-	14	10	28.6%
Southeast Division	72.5%	73	12	83.6%	337	46	86.4%	2,472	253	89.8%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	25	0	100.0%	180	16	91.1%
GRO	-	1	0	100.0%	3	1	66.7%	3	1	66.7%
HAR	62.0%	13	2	84.6%	53	9	83.0%	407	36	91.2%
LOR	69.5%	1	0	100.0%	5	3	40.0%	36	5	86.1%
MIA	87.5%	2	0	100.0%	10	1	90.0%	72	7	90.3%
MOE	94.0%	2	0	100.0%	10	0	100.0%	72	3	95.8%
NFK	86.0%	3	0	100.0%	12	1	91.7%	101	10	90.1%
NOL	92.0%	5	1	80.0%	23	4	82.6%	159	10	93.7%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 11/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/05/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	304	35	88.5%	1,456	172	88.2%	10,529	1,222	88.4%
Southeast Division	72.5%	73	12	83.6%	337	46	86.4%	2,472	253	89.8%
NPN	96.0%	-	-	-	1	1	0.0%	51	5	90.2%
PGH	92.0%	1	0	100.0%	5	0	100.0%	36	1	97.2%
PHL	45.0%	5	2	60.0%	22	11	50.0%	165	44	73.3%
RGH	97.0%	3	0	100.0%	17	0	100.0%	141	3	97.9%
RNK	85.5%	2	1	50.0%	9	1	88.9%	71	10	85.9%
RVM	86.0%	2	1	50.0%	9	1	88.9%	44	7	84.1%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	5	0	100.0%	36	0	100.0%
SFA	70.5%	1	1	0.0%	5	1	80.0%	36	2	94.4%
WAS	70.0%	26	4	84.6%	123	12	90.2%	858	90	89.5%
Southwest Division	77.0%	70	10	85.7%	336	49	85.4%	2,394	321	86.6%
ARN	60.5%	1	0	100.0%	5	1	80.0%	36	4	88.9%
BFD	75.5%	5	0	100.0%	22	6	72.7%	199	48	75.9%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	1	0.0%	5	2	60.0%	38	12	68.4%
FNO	-	-	-	-	5	3	40.0%	6	3	50.0%
FTW	89.5%	1	0	100.0%	5	0	100.0%	35	3	91.4%
GTA	72.5%	3	1	66.7%	15	2	86.7%	102	9	91.2%
LAX	77.5%	10	0	100.0%	47	4	91.5%	324	33	89.8%
OKC	96.0%	1	0	100.0%	5	0	100.0%	36	2	94.4%
OKJ	79.0%	12	4	66.7%	53	14	73.6%	390	85	78.2%
SAC	73.5%	14	3	78.6%	64	8	87.5%	468	58	87.6%
SAN	77.0%	12	1	91.7%	60	4	93.3%	395	31	92.2%
SAS	85.0%	1	0	100.0%	5	0	100.0%	36	3	91.7%
SJC	87.5%	7	0	100.0%	35	2	94.3%	251	19	92.4%
SLO	62.0%	2	0	100.0%	10	3	70.0%	67	10	85.1%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	8	1	87.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

25-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		3	0	100.0%	16	1	93.8%	2	0	100.0%	16	0	100.0%
3		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	12	66.7%
4		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	23	36.1%
5		5	0	100.0%	35	4	88.6%	5	0	100.0%	34	5	85.3%
6		5	2	60.0%	36	12	66.7%	5	1	80.0%	36	12	66.7%
7	346	5	0	100.0%	36	3	91.7%	5	1	80.0%	36	4	88.9%
8	43	5	1	80.0%	36	14	61.1%	5	3	40.0%	36	15	58.3%
11	104	5	1	80.0%	35	7	80.0%	5	1	80.0%	33	5	84.8%
14	33	5	1	80.0%	36	6	83.3%	5	2	60.0%	35	8	77.1%
19	89	5	2	60.0%	36	6	83.3%	5	2	60.0%	36	11	69.4%
20		5	1	80.0%	36	4	88.9%	5	2	60.0%	36	3	91.7%
21		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	7	80.6%
22		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	6	83.3%
23		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	8	77.8%
24		5	1	80.0%	36	1	97.2%	5	0	100.0%	36	5	86.1%
25	35	5	0	100.0%	36	0	100.0%	5	1	80.0%	36	5	86.1%
26		5	1	80.0%	36	1	97.2%	5	1	80.0%	36	5	86.1%
27		5	2	60.0%	36	3	91.7%	5	0	100.0%	36	6	83.3%
28		5	0	100.0%	36	7	80.6%	5	0	100.0%	36	4	88.9%
40		5	1	80.0%	36	5	86.1%	5	0	100.0%	36	9	75.0%
41		5	0	100.0%	36	11	69.4%	5	1	80.0%	36	22	38.9%
42		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	5	86.1%
43		5	1	80.0%	36	2	94.4%	5	0	100.0%	36	2	94.4%
48		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	2	94.4%
49		5	1	80.0%	36	5	86.1%	5	0	100.0%	36	1	97.2%
50	67	2	1	50.0%	15	3	80.0%	2	1	50.0%	16	8	50.0%
52	42	5	1	80.0%	36	2	94.4%	5	2	60.0%	36	5	86.1%
53	77	5	3	40.0%	36	5	86.1%	5	2	60.0%	36	5	86.1%
55		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	4	84.6%
56		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	5	80.8%
58		5	1	80.0%	35	2	94.3%	5	0	100.0%	34	5	85.3%
59		5	0	100.0%	34	3	91.2%	5	0	100.0%	34	3	91.2%
63		5	1	80.0%	36	15	58.3%	5	4	20.0%	36	21	41.7%
64		5	2	60.0%	35	6	82.9%	5	1	80.0%	35	9	74.3%
66		5	2	60.0%	36	9	75.0%	5	0	100.0%	36	7	80.6%
67		4	0	100.0%	26	1	96.2%	3	1	66.7%	26	2	92.3%
68		5	1	80.0%	36	6	83.3%	5	1	80.0%	36	16	55.6%
69		5	2	60.0%	36	4	88.9%	5	0	100.0%	36	5	86.1%
71		5	0	100.0%	36	0	100.0%	5	1	80.0%	36	12	66.7%
72		5	0	100.0%	36	3	91.7%	5	1	80.0%	36	7	80.6%
73		5	0	100.0%	36	1	97.2%	5	2	60.0%	35	21	40.0%
74	20	5	0	100.0%	36	3	91.7%	5	3	40.0%	36	13	63.9%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75	32	5	1	80.0%	36	1	97.2%	5	2	60.0%	36	21	41.7%
76		5	0	100.0%	36	3	91.7%	5	2	60.0%	36	23	36.1%
77		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	17	52.8%
78		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	7	80.6%
79		5	0	100.0%	36	7	80.6%	5	1	80.0%	36	8	77.8%
80		5	0	100.0%	36	4	88.9%	5	0	100.0%	36	3	91.7%
84		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	3	88.5%
85		3	0	100.0%	26	1	96.2%	3	1	66.7%	26	11	57.7%
86		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	10	61.5%
89		5	0	100.0%	36	6	83.3%	5	0	100.0%	36	5	86.1%
90		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	4	88.9%
93		3	0	100.0%	26	3	88.5%	3	0	100.0%	25	7	72.0%
94		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	7	73.1%
95		3	1	66.7%	26	1	96.2%	3	1	66.7%	26	7	73.1%
97		5	4	20.0%	36	12	66.7%	5	0	100.0%	36	9	75.0%
98	41	5	0	100.0%	36	2	94.4%	5	1	80.0%	36	3	91.7%
110		3	1	66.7%	26	8	69.2%	3	0	100.0%	26	2	92.3%
111		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	1	96.2%
112		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	4	84.6%
114		3	1	66.7%	26	6	76.9%	3	0	100.0%	26	0	100.0%
119		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	2	92.3%
125		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	2	92.3%
129		3	0	100.0%	26	6	76.9%	3	0	100.0%	26	3	88.5%
130		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	3	88.5%
131		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	0	100.0%
133		3	1	66.7%	26	10	61.5%	3	2	33.3%	26	10	61.5%
134		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	5	80.8%
136		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	1	96.2%
137		3	0	100.0%	24	6	75.0%	3	0	100.0%	24	4	83.3%
138		3	1	66.7%	26	4	84.6%	3	1	66.7%	26	1	96.2%
141	84	3	0	100.0%	26	2	92.3%	3	1	66.7%	26	5	80.8%
148		3	0	100.0%	26	3	88.5%	3	0	100.0%	25	6	76.0%
151		5	2	60.0%	36	9	75.0%	4	1	75.0%	35	11	68.6%
170		3	0	100.0%	23	2	91.3%	3	1	66.7%	23	5	78.3%
171		3	1	66.7%	26	2	92.3%	3	0	100.0%	26	3	88.5%
172		3	0	100.0%	26	2	92.3%	3	1	66.7%	26	11	57.7%
173	21	3	0	100.0%	26	2	92.3%	3	1	66.7%	26	9	65.4%
174		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	2	92.3%
175		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	2	92.3%
176		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	0	100.0%
177	No OS	3	0	100.0%	26	5	80.8%	3	2	33.3%	26	11	57.7%
178		3	1	66.7%	26	3	88.5%	3	0	100.0%	26	3	88.5%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	7	73.1%
181		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	0	100.0%
182		3	0	100.0%	26	6	76.9%	3	0	100.0%	26	0	100.0%
183		3	0	100.0%	26	7	73.1%	3	0	100.0%	26	5	80.8%
184		3	1	66.7%	26	3	88.5%	3	0	100.0%	26	3	88.5%
185		3	0	100.0%	26	6	76.9%	3	0	100.0%	26	0	100.0%
186		3	1	66.7%	26	5	80.8%	3	1	66.7%	26	8	69.2%
190		3	1	66.7%	26	8	69.2%	3	0	100.0%	26	5	80.8%
192		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	1	96.2%
193		3	0	100.0%	26	7	73.1%	3	1	66.7%	26	8	69.2%
196		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	2	92.3%
197		3	0	100.0%	26	8	69.2%	3	1	66.7%	26	4	84.6%
232		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	4	88.9%
233		5	2	60.0%	36	8	77.8%	5	3	40.0%	36	9	75.0%
234		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	0	100.0%
236		5	0	100.0%	36	0	100.0%	5	2	60.0%	36	7	80.6%
237		5	0	100.0%	36	6	83.3%	5	0	100.0%	36	3	91.7%
239		4	1	75.0%	35	10	71.4%	4	0	100.0%	35	1	97.1%
240		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	1	97.2%
241		5	1	80.0%	36	8	77.8%	5	0	100.0%	36	8	77.8%
243		3	2	33.3%	26	10	61.5%	3	0	100.0%	27	5	81.5%
244		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	13	63.9%
280		5	0	100.0%	36	3	91.7%	5	1	80.0%	36	5	86.1%
281		5	1	80.0%	36	6	83.3%	5	1	80.0%	36	3	91.7%
283		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	5	86.1%
284		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	4	88.9%
290		5	2	60.0%	36	12	66.7%	4	1	75.0%	35	11	68.6%
291		5	0	100.0%	36	5	86.1%	5	2	60.0%	36	8	77.8%
300		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	6	83.3%
301		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	5	86.1%
302		5	1	80.0%	36	4	88.9%	4	1	75.0%	35	11	68.6%
305		5	0	100.0%	36	1	97.2%	5	0	100.0%	35	9	74.3%
306		5	0	100.0%	36	1	97.2%	5	1	80.0%	35	6	82.9%
307	36	5	0	100.0%	36	2	94.4%	5	2	60.0%	36	4	88.9%
311		5	0	100.0%	35	2	94.3%	5	1	80.0%	35	9	74.3%
316		5	0	100.0%	35	1	97.1%	5	0	100.0%	35	6	82.9%
318		5	0	100.0%	36	6	83.3%	5	2	60.0%	35	16	54.3%
319		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	21	41.7%
329	29	3	0	100.0%	26	0	100.0%	3	1	66.7%	26	1	96.2%
330		4	0	100.0%	31	2	93.5%	4	0	100.0%	31	1	96.8%
331		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	3	91.7%
332	25	5	1	80.0%	36	4	88.9%	5	1	80.0%	36	3	91.7%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

25-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		5	0	100.0%	36	1	97.2%	5	0	100.0%	35	3	91.4%
335		5	0	100.0%	36	6	83.3%	5	0	100.0%	35	7	80.0%
336		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	4	88.9%
337		5	0	100.0%	36	4	88.9%	5	0	100.0%	36	4	88.9%
338		5	0	100.0%	36	11	69.4%	5	1	80.0%	35	10	71.4%
339		5	1	80.0%	36	10	72.2%	5	1	80.0%	36	8	77.8%
341		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	4	88.9%
342	11	5	1	80.0%	36	4	88.9%	5	1	80.0%	35	4	88.6%
350		5	1	80.0%	18	2	88.9%	5	2	60.0%	18	5	72.2%
351		5	0	100.0%	36	1	97.2%	5	3	40.0%	36	12	66.7%
352		5	1	80.0%	36	3	91.7%	5	1	80.0%	35	5	85.7%
353		5	0	100.0%	17	2	88.2%	5	1	80.0%	17	3	82.4%
354		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	7	80.6%
355	No OS	5	1	80.0%	36	5	86.1%	5	2	60.0%	36	6	83.3%
364		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	6	83.3%
365		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	10	72.2%
370		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	5	86.1%
371		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	2	94.4%
380		5	1	80.0%	36	8	77.8%	5	0	100.0%	36	7	80.6%
381		5	1	80.0%	36	1	97.2%	5	0	100.0%	36	5	86.1%
382		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	5	86.1%
383		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	12	66.7%
390		5	0	100.0%	36	3	91.7%	5	2	60.0%	36	7	80.6%
391		5	0	100.0%	36	0	100.0%	5	1	80.0%	35	6	82.9%
392		5	0	100.0%	36	2	94.4%	5	0	100.0%	35	4	88.6%
393		5	0	100.0%	36	3	91.7%	5	0	100.0%	35	7	80.0%
425		2	0	100.0%	25	1	96.0%	2	0	100.0%	25	1	96.0%
470		3	2	33.3%	26	5	80.8%	3	1	66.7%	26	6	76.9%
471		2	0	100.0%	25	0	100.0%	2	0	100.0%	25	0	100.0%
473		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	1	96.2%
475		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	1	96.2%
478		3	1	66.7%	26	8	69.2%	3	0	100.0%	26	3	88.5%
479		3	1	66.7%	26	3	88.5%	3	0	100.0%	26	0	100.0%
486	25	3	1	66.7%	27	6	77.8%	3	1	66.7%	26	3	88.5%
490	44	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
494		3	0	100.0%	27	6	77.8%	3	0	100.0%	25	3	88.0%
495		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	0	100.0%
500		5	1	80.0%	36	3	91.7%	5	0	100.0%	36	4	88.9%
502	31	5	0	100.0%	36	5	86.1%	5	2	60.0%	36	11	69.4%
503		5	0	100.0%	33	6	81.8%	5	2	60.0%	32	10	68.8%
504	39	5	0	100.0%	36	1	97.2%	5	2	60.0%	36	13	63.9%
505		5	0	100.0%	36	6	83.3%	5	0	100.0%	35	7	80.0%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

25-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506		5	2	60.0%	35	6	82.9%	5	0	100.0%	34	5	85.3%
507		5	0	100.0%	36	3	91.7%	5	1	80.0%	36	16	55.6%
508		5	1	80.0%	34	6	82.4%	5	0	100.0%	34	5	85.3%
509		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	8	77.8%
511		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	6	83.3%
516		5	0	100.0%	36	4	88.9%	5	1	80.0%	36	17	52.8%
517	50	5	0	100.0%	36	1	97.2%	5	2	60.0%	35	14	60.0%
518	37	5	1	80.0%	36	7	80.6%	5	3	40.0%	36	25	30.6%
519		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	7	80.6%
520		3	0	100.0%	23	2	91.3%	3	0	100.0%	23	0	100.0%
521		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	0	100.0%
522	27	3	0	100.0%	26	3	88.5%	3	1	66.7%	26	3	88.5%
523	24	3	0	100.0%	26	0	100.0%	3	1	66.7%	26	1	96.2%
524		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	0	100.0%
525	25	3	0	100.0%	26	1	96.2%	3	1	66.7%	26	5	80.8%
526	98	3	1	66.7%	26	4	84.6%	3	1	66.7%	26	4	84.6%
527		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	2	92.3%
528	21	3	0	100.0%	26	1	96.2%	3	1	66.7%	26	4	84.6%
529		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	2	92.3%
531	70	3	0	100.0%	26	1	96.2%	3	1	66.7%	26	2	92.3%
532		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	4	84.6%
534		3	0	100.0%	23	2	91.3%	3	0	100.0%	23	1	95.7%
535	20	3	1	66.7%	23	1	95.7%	3	1	66.7%	23	1	95.7%
536		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	1	96.2%
537		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	1	96.2%
538		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	2	92.3%
540		3	0	100.0%	26	2	92.3%	3	0	100.0%	25	0	100.0%
541	16	3	1	66.7%	26	3	88.5%	3	2	33.3%	26	5	80.8%
542		3	0	100.0%	26	2	92.3%	3	0	100.0%	25	5	80.0%
543		3	0	100.0%	26	4	84.6%	3	1	66.7%	26	7	73.1%
544		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	2	92.3%
545		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	3	88.5%
546		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	2	92.3%
547		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	4	84.6%
548		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	2	92.3%
549		3	1	66.7%	23	8	65.2%	3	0	100.0%	22	3	86.4%
551		3	1	66.7%	26	5	80.8%	3	0	100.0%	24	3	87.5%
562		5	1	80.0%	34	4	88.2%	5	0	100.0%	33	3	90.9%
564		5	0	100.0%	34	2	94.1%	5	0	100.0%	33	5	84.8%
566		5	0	100.0%	34	2	94.1%	5	0	100.0%	34	2	94.1%
572	20	5	1	80.0%	33	4	87.9%	5	3	40.0%	33	8	75.8%
573		5	0	100.0%	34	6	82.4%	5	0	100.0%	33	4	87.9%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

25-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
577		5	0	100.0%	32	0	100.0%	5	0	100.0%	32	1	96.9%
580		5	0	100.0%	34	2	94.1%	5	0	100.0%	34	3	91.2%
581	23	5	0	100.0%	34	0	100.0%	5	1	80.0%	34	7	79.4%
582		5	0	100.0%	34	3	91.2%	5	1	80.0%	34	3	91.2%
586		5	1	80.0%	34	6	82.4%	5	1	80.0%	32	3	90.6%
587		5	0	100.0%	34	2	94.1%	5	0	100.0%	32	3	90.6%
591		5	0	100.0%	34	1	97.1%	5	0	100.0%	34	2	94.1%
593		5	1	80.0%	34	5	85.3%	5	0	100.0%	31	3	90.3%
595		5	2	60.0%	33	6	81.8%	5	0	100.0%	32	6	81.3%
600		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	3	88.5%
601	11	3	2	33.3%	26	3	88.5%	3	3	0.0%	26	8	69.2%
605		3	2	33.3%	26	5	80.8%	3	0	100.0%	26	0	100.0%
607		3	0	100.0%	26	1	96.2%	3	0	100.0%	25	0	100.0%
609		3	0	100.0%	25	1	96.0%	3	0	100.0%	25	3	88.0%
620		3	0	100.0%	26	6	76.9%	3	0	100.0%	25	2	92.0%
624	14	3	1	66.7%	26	4	84.6%	3	2	33.3%	26	7	73.1%
639		3	2	33.3%	26	9	65.4%	3	1	66.7%	26	4	84.6%
640	19	3	0	100.0%	26	1	96.2%	3	2	33.3%	26	14	46.2%
641		3	0	100.0%	26	3	88.5%	3	1	66.7%	26	4	84.6%
642		3	1	66.7%	25	1	96.0%	3	0	100.0%	25	2	92.0%
643		3	1	66.7%	26	3	88.5%	3	0	100.0%	25	1	96.0%
644	19	3	0	100.0%	26	1	96.2%	3	1	66.7%	26	4	84.6%
645		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	2	92.3%
646	13	3	1	66.7%	26	3	88.5%	3	3	0.0%	25	10	60.0%
647		3	0	100.0%	26	1	96.2%	3	0	100.0%	26	7	73.1%
648		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	1	96.2%
649		3	1	66.7%	26	4	84.6%	3	0	100.0%	25	3	88.0%
650		3	2	33.3%	26	4	84.6%	3	0	100.0%	26	3	88.5%
651		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	7	73.1%
652		3	0	100.0%	26	2	92.3%	3	0	100.0%	25	4	84.0%
653		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	8	69.2%
654		3	1	66.7%	26	1	96.2%	3	0	100.0%	26	2	92.3%
655	Cncld	3	0	100.0%	24	6	75.0%	2	1	50.0%	23	4	82.6%
656		3	2	33.3%	26	2	92.3%	3	0	100.0%	26	4	84.6%
657	150	3	0	100.0%	26	1	96.2%	3	1	66.7%	26	6	76.9%
658		3	1	66.7%	26	2	92.3%	3	1	66.7%	26	3	88.5%
680		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	3	88.5%
681		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	7	73.1%
682	13	3	0	100.0%	26	0	100.0%	3	1	66.7%	26	7	73.1%
685	15	3	1	66.7%	26	2	92.3%	3	2	33.3%	26	11	57.7%
686		3	2	33.3%	26	12	53.8%	3	0	100.0%	26	8	69.2%
687		3	0	100.0%	26	5	80.8%	3	1	66.7%	26	5	80.8%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

25-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
688	36	3	0	100.0%	26	1	96.2%	3	2	33.3%	26	10	61.5%
702		5	1	80.0%	36	8	77.8%	5	2	60.0%	35	11	68.6%
703		5	1	80.0%	36	8	77.8%	5	1	80.0%	36	8	77.8%
710		5	1	80.0%	36	13	63.9%	5	2	60.0%	36	15	58.3%
711		5	0	100.0%	34	2	94.1%	4	2	50.0%	32	4	87.5%
712		5	3	40.0%	36	10	72.2%	5	1	80.0%	36	13	63.9%
713	18	5	2	60.0%	36	7	80.6%	4	2	50.0%	33	15	54.5%
714	Cncld	4	3	25.0%	30	9	70.0%	2	1	50.0%	26	8	69.2%
715		5	2	60.0%	36	14	61.1%	5	2	60.0%	34	17	50.0%
716	33	5	4	20.0%	36	15	58.3%	5	3	40.0%	35	10	71.4%
718		5	1	80.0%	36	12	66.7%	5	0	100.0%	36	10	72.2%
719	117	5	3	40.0%	36	16	55.6%	5	1	80.0%	35	11	68.6%
761		5	0	100.0%	34	2	94.1%	5	1	80.0%	34	5	85.3%
765	26	5	1	80.0%	34	6	82.4%	5	2	60.0%	34	8	76.5%
769		5	0	100.0%	34	2	94.1%	5	0	100.0%	34	5	85.3%
770		5	0	100.0%	34	3	91.2%	5	1	80.0%	34	3	91.2%
774		5	2	60.0%	34	6	82.4%	5	1	80.0%	33	4	87.9%
779		5	0	100.0%	34	2	94.1%	5	0	100.0%	33	1	97.0%
784	39	5	2	60.0%	34	5	85.3%	5	3	40.0%	33	14	57.6%
785		5	0	100.0%	34	0	100.0%	5	0	100.0%	34	4	88.2%
790		5	0	100.0%	34	1	97.1%	5	1	80.0%	34	3	91.2%
794	16	5	1	80.0%	34	4	88.2%	5	1	80.0%	34	8	76.5%
821		5	0	100.0%	36	2	94.4%	5	2	60.0%	36	24	33.3%
822	14	5	0	100.0%	36	3	91.7%	5	2	60.0%	36	28	22.2%
1333		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	16	55.6%
1340		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	8	77.8%
1689		2	0	100.0%	7	1	85.7%	2	0	100.0%	8	0	100.0%
2103		3	0	100.0%	26	3	88.5%	3	0	100.0%	26	0	100.0%
2107		3	1	66.7%	26	4	84.6%	3	0	100.0%	24	0	100.0%
2108		3	0	100.0%	26	1	96.2%	3	0	100.0%	25	0	100.0%
2121		3	0	100.0%	25	2	92.0%	3	0	100.0%	25	2	92.0%
2122		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	2	92.3%
2124		3	0	100.0%	20	3	85.0%	3	0	100.0%	20	1	95.0%
2150		3	1	66.7%	26	6	76.9%	3	0	100.0%	26	5	80.8%
2151		3	0	100.0%	26	0	100.0%	3	1	66.7%	25	3	88.0%
2152		3	1	66.7%	22	1	95.5%	3	0	100.0%	22	1	95.5%
2153	20	3	0	100.0%	26	3	88.5%	3	1	66.7%	26	5	80.8%
2154		3	1	66.7%	26	8	69.2%	3	2	33.3%	24	12	50.0%
2155		3	1	66.7%	26	2	92.3%	3	1	66.7%	24	6	75.0%
2159		3	0	100.0%	26	0	100.0%	3	0	100.0%	26	3	88.5%
2162		3	0	100.0%	26	2	92.3%	3	0	100.0%	25	4	84.0%
2163		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	7	73.1%

Amtrak On Time Performance

Trains Arriving Through: 11/5/2025

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2166		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	4	84.6%
2167		3	0	100.0%	26	2	92.3%	3	0	100.0%	26	3	88.5%
2168		3	1	66.7%	26	2	92.3%	3	0	100.0%	26	6	76.9%
2169		3	0	100.0%	22	2	90.9%	3	0	100.0%	22	3	86.4%
2170		3	2	33.3%	26	5	80.8%	3	0	100.0%	26	7	73.1%
2172		3	0	100.0%	26	3	88.5%	3	1	66.7%	26	4	84.6%
2173		3	0	100.0%	25	4	84.0%	3	1	66.7%	25	9	64.0%
2190		3	0	100.0%	26	4	84.6%	3	0	100.0%	26	3	88.5%
2193		3	0	100.0%	25	1	96.0%	3	0	100.0%	25	5	80.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Region: ALL

Service: ALL

Arriving On: 11/5/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2153	WAS	20	CTI	12	CTI	9	RTE-PVD	AM	Meet, MBTA, MT810, Milepost w/Letters, RTE, PVD, HELD AT HEBRONVILLE FOR MBTA MT810 RTE - PVD
141	NFK	84	ENG	49	ENG	26	NYP-NYP	AM	Air / Brake, 652, AIR HOSE LEAVE BETWEEN ENG.652 & CAR 81514
173	WAS	21	CTI	33	DCS	10	PVD-KIN	AM	Power switch failure, Milepost, x7t, xdr, SW FAILURE ON THE 31SW AT POST
177	PHL	No OS Rpt	CON	17	CON	17	NHV-NHV	MN	Hold for bus with passengers from train
486	GFD	25	SVS	21	SVS	21	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD MECHANICAL PROBLEM
490	SPG	44	ITI	45	ITI	45	NHV-NHV	AM	Service, turn, or wye train, 471, late turn
52	LOR	42	DSR	86	DSR	55	XV7-XRV	CS	Stopped at walthall per dispatcher had to wait for track equipment to clear up on to the Bellwood Control Point, walthall, 0, 1
53	SFA	77	PTI	75	CTI	29	XDD-XSF	FR	Meet fr, p310, Control Point, blue springs
601	HAR	11	SMW	10	SMW	5	PHL-ARD	AM	Diversions around M/W work, Control Point, Zoo, Opr 1 trk.
624	NYP	14	DCS	13	DCS	13	ELT-MJY	AM	T.O.L, Control Point, Rheems - Cork 1 trk, opr 1 trk to 2 trk around TOL
640	NYP	19	CTI	22	CTI	11	TRE-NWK	AM	Follow, NJT, NJ3926, Other, ADAMS-NWK
644	NYP	19	DMW	13	DMW	13	NWK-NYP	AM	Held for or routed around MW work or equipment, Other, XPT, SINGLE TRACKING A/C TRACK DEFECT ON 2 TRK PORTAL INT
646	NYP	13	WTR	9	PTI	6	PHL-XHM	AM	Follow, 2162, Control Point, .
655	HAR	Trn Cancelled	PTI	7	CTI	6	NYP-NWK	AM	Follow, NJ, 3515 3275, Other, NYP-NWK, FLWD NJ3515 AND NJ3275
657	HAR	150	WTR	147	WTR	62	LNC-LNC	AM	Trees down, Control Point, ., signal power loss Rheems - Roy due to downed tree
19	NOL	89	DCS	124	DCS	118	SDL-XEJ	NS	Restrictive signal(s) from unknown cause Stopped at NO172.1 waiting for NS employee to walk and inspect the bridge to make sure it was down, lined and locked before our train continued its movement to New Orleans..., Approach, Restricted , Stop, Milepost, 169.7, 172.1
682	BON	13	ENG	8	ENG	8	HHL-HHL	MT	Loading problem 116
685	BRK	15	DSR	14	DSR	9	DHM-DOV	CS	Per bulletin Milepost, 61.4, 62.5, 25, single

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Region: ALL

Service: ALL

Arriving On: 11/5/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
688	BON	36	PTI	11	PTI	11	FRE-POR	CS	Meet 685, Control Point, mountain
74	RGH	20	DMW	13	DMW	13	GRO-BNC	NS	Waiting for MW clearance Control Point, Fields
76	RGH	32	FTI	22	FTI	22	GRO-DNC	NS	Pull in behind NS 95Z. Wait until Amt 79 clears. Shove out of siding at Mebane #NS 95Z, Control Point, Mebane
98	NYP	41	FTI	98	FTI	51	RMT-PTB	CS	Blocked from station track io32, Control Point, Appomattox
25	NOL	35	FTI	48	FTI	33	BAS-XNO	CS	Meet Stop for freight trains in gentilly yard, csx freight, Milepost, 793.2, 793.2
522	SAC	27	TRS	40	TRS	38	BKY-BKY	UP	Vehicle on track ahead Milepost, 10.85, 10.85
523	SJC	24	TRS	17	TRS	17	RIC-RIC	UP	Vehicle on track ahead Milepost, 10.86, 10.86
525	OKJ	25	FTI	30	FTI	15	RIC-BKY	UP	Follow Train went into emergency ahead of us., Milepost, 7.1, 6.2, UP 6224, intermodal
526	SAC	98	DCS	102	DCS	102	MTZ-SUI	UP	Drawbridge stuck open Unable to lock bridge into position., Control Point, Vista
528	SAC	21	MBO	26	MBO	14	MTZ-SUI	UP	Bridge issues. Manually getting locked Milepost, 31.7, 48.9
531	OKJ	70	MBO	73	MBO	73	SUI-MTZ	UP	Bridge refused to lock in place Bridge, Suisun
535	OKJ	20	DCS	16	DCS	13	SAC-DAV	UP	Restrictive signal(s) from known wayside signal failure Restricted speed , Control Point, Mixon
541	SJC	16	ITI	19	ITI	19	SAC-SAC	UP	526 delayed. 523
50	NYP	67	SYS	90	SYS	72	CHI-CHI	AM	Revenue engine 329 added engine wrong direction.
502	SEA	31	FTI	26	FTI	24	CTL-OLW	BN	Follow Follow the UP 7522 from Tenino to Centennial., UP 7522, Control Point, Tenino
504	SEA	39	FTI	31	FTI	31	XTW-XA4	BN	Disabled Freight Freight across M1 and M2 at Pacific, Control Point, Sumner, BN 8150, vehicle
517	PDX	50	DCS	46	DCS	46	VAN-PDX	BN	Drawbridge stuck open Had to walk bridge to make sure down and locked, Bridge, OREGON SLOUGH
518	VAC	37	FTI	26	FTI	18	XF2-X1J	BN	Follow CN, Control Point, CN
11	LAX	104	TRS	160	TRS	91	BUR-LAX	SC	Vehicle on track ahead Milepost, 461.46, 461.46

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Region: ALL

Service: ALL

Arriving On: 11/5/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
14	SEA	33	PTI	54	DCS	30	PDX-VAN	BN	Restrictive signal(s) from known wayside signal failure Stop, Bridge, Oregon Slough	
7	SEA	346	ENG	374	ENG	374	LWA-XEN	BN	Pick up rescue locomotive due to mechanical failure Failure to make traction at grade past Merritt due to inoperative sanders and inadequate horsepower output. Wait for arrival of BNSF 4053 E to add rescue unit BNSF 7961 to head end., 361	
8	CHI	43	FTI	150	FTI	32	SBY-HAV	BN	Meet Siding, Burnham, BNSF 7747W	
822	OKC	14	DSR	32	DSR	25	FTW-GLE	BN	Per bulletin Milepost, 354.0, 354.1, 35, mt2, Milepost, 355.6, 355.8, 40, mt2, Milepost, 356.5, 356.8, 60, mt2, Milepost, 357.5, 357.9, 60, mt2, Milepost, 358.0, 358.2, 30, mt1, Milepost, 361.6, 361.8, 60, mt1, Milepost, 365.0, 367.8, 25, mt1, Milepost, 385.3, 385.5, 60, mt, Siding, metro, 10, sidin	
329	MKE	29	ENG	41	ENG	25	GLN-GLN	ME	Onboard HBD alarm Fault came up on, hot journal on two axles on 4610. Stopped, inspected, and heat gun revealed nothing was above 20 degrees Celsius. Proceeded at 50mph for the next ten miles and re-inspected., ID4610	
332	CHI	25	SYS	26	SYS	26	MKE-MKE	CP	Re-crew / job briefing Late inbound 329 - Short notice call from Crew Management (less than 2hr call), Other, MKE	
342	CHI	11	CTI	15	CTI	13	GLN-XWA	ME	Follow metra, Control Point, edge brook	
355	CHI	No OS Rpt	DCS	221	DCS	221	XGO-KAL	AM	T.O.L Broken rail @139.01 waiting for track dept to repair, Other, 124.4	
572	SAN	20	OTH	21	PTI	9	SOL-SOL	SN	Meet 779, Control Point, valley	
581	LAX	23	CTI	25	CTI	12	OSD-X98	SC	Meet metrolink, Control Point, songs	
765	GTA	26	CTI	33	PTI	13	OSD-X98	SC	Meet 562, Control Point, san onofre	
784	SAN	39	CTI	34	PTI	17	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano	
794	SAN	16	DSR	21	TRS	20	GDL-GDL	SC	Unticketed or fare evading passenger Crazy fare evader removed by Glendale PD, Other, Glendale station	
713	OKJ	18	RTE	21	RTE	14	MCD-TRK	BN	Dispatcher hold Held on main to let BNSF 7989 east pass us using the siding NAR, Control Point, west ballicko	
714	BFD	Trn Cancelled								
716	BFD	33	ITI	56	ITI	56	EMY-EMY	UP	Change out locos 711	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-0010300000005199"UNCLASSIFIED"11/14/2025

Region: ALL

Service: ALL

Arriving On: 11/5/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
719	OKJ	117	POL	128	POL	128	SKN-ACA	BN	RR blocked by trespasser or vehicle strike by another train
307	STL	36	FTI	42	ADA	25	BNL-LCN	UP	Vision / hearing-impaired Ada pax missed station stop of bnl. Shoved train back to platform to get pax off at correct station. Dispatcher was changing shifts had to wait for new dispatcher to come on duty. Also walked passenger to front of station due to station being closed.

Amtrak Initial Terminal Details

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 11/5/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	624	11/05	1		
HAR	656	11/05	2	2	Vision / hearing-impaired, per cndr; 5:42pm
NOL	20	11/05	8	8	Door 62035, Trap door latch was broken. The trap would not shut.
PHL	601	11/05	1		
PHL	605	11/05	1		
RNK	66	11/05	3	3	Dispatcher held us at the storage track Control Point, JK, unknown
RVM	186	11/05	16	16	Meet CSX 3396, Control Point, AY
SFA	52	11/05	13	13	Loading problem 358
WAS	2150	11/05	2	2	Door, N/A
WAS	2152	11/05	3	3	Fire department hold, FIRE DRILL IN REA BULIDING PREVENTED K TOWER FROM GIVING DEPARTURE SIGNAL
WAS	2168	11/05	1		
WAS	2170	11/05	5	5	Door, UNKNOWN, THERE WAS A FAULT ON THE TRAIN, THE ALSTON TECT ON BOARD WAS ABLE TO RESET IT. THE FAULT WAS ON T OPEN DOOR HANDEL
BON	685	11/05	2	2	Mobility Impaired
GFD	479	11/05	4	4	IETMS issue
MTR	68	11/05	47	19	Service, turn, or wye train 694
MTR	68	11/05	47	17	Incomplete and missing map 100 101
MTR	68	11/05	47	11	Late / wrong track bulletins from host railroad CPKC, Other, MTR
NHV	470	11/05	8	8	Planned set out / pick out of locomotives, cars or section of train, late release from the yard
NHV	486	11/05	21	21	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD MECHANICAL PROBLEM
NHV	490	11/05	45	45	Service, turn, or wye train, 471, late turn
NYP	241	11/05	2	2	Cross Traffic, NJ, 3961, Other, NYP-NYP, NJ3961 XING AHD
NYP	243	11/05	2	2	High passenger count, LATE LOADING
NYP	639	11/05	2	2	Other electrical failure, 640, DOOR LIGHTS
NYP	643	11/05	4	4	Service, turn, or wye train, 640, LATE TURN OFF AM640
TWO	64	11/05	4		
MKE	332	11/05	26	26	Re-crew / job briefing Late inbound 329 - Short notice call from Crew Management (less than 2hr call), Other, MKE
SEA	8	11/05	319	319	Service, turn, or wye train 007

Amtrak Initial Terminal Details

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 11/5/2025

Terminal	Train	Date	Late	Delay	Cause
EMY	6	11/05	3	3	Meet Train went into emergency, caused backup of PTI. We met 525 and 527 as a result., Control Point, Shellmound, UP 6224 West, INPOA-02
GTA	784	11/05	1		
OKJ	526	11/05	6	6	Service, turn, or wye train 525, Late arrival of 525 at OKJ.
OKJ	712	11/05	9	9	Replacing marker light CDTX2006. C2006
OKJ	714	11/05	(Trn Cxld)		engine failure
OKJ	716	11/05	(No OS)		
SAC	535	11/05	3	3	Restrictive signal(s) from known wayside signal failure Restricted speed , Control Point, Mixon
SAC	541	11/05	19	19	526 delayed. 523
SAC	551	11/05	1		
SAN	595	11/05	4	4	Service, turn, or wye train 784

Eastern Region

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.1	96.1	94.8	309	6
CDOT	95.0	95.0	93.5	92.4	20	1
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	93.0	95.1	93.8	371	26
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 52(05) North of Charleston, SC - Freight Train Interference

05NOV25: Train 52(05) operating with engines 354, 358 and 522, 48 cars and 199 passengers onboard, on CSX Charleston South subdivision was delayed due to freight interference from Elta / MP A348.30 to Coward / MP A310.0.

Train	Delay	Comment
52(05)	32"	Meet 31, 37

Train 98(05) South of Charleston, SC - Freight Train Interference

05NOV25: Train 98(05) operating with engine 39 and 302, 11 cars and 177 passengers onboard, on CSX Charleston South subdivision was delayed due to freight train interference caused by a commercial power outage that affected Ashley River Bridge / MP 393.7 approximately 1 mile south of Charleston, SC Station. The power outage caused single tracking across the bridge. Train 98(05) had to cross at walking speeds. Due to the single tracking, Train 98(05) had to wait for freight train M492 to clear before proceeding.

Train	Delay	Comment
98(05)	06"	Following M492
98(05)	53"	M492 Blocked Station

05NOV25: Keystone Service 26-FOI-00103 00000005199 UNCLASSIFIED and 11/14/2025 Harrisburg, PA and Philadelphia, PA was affected due to signal power loss at Roy Interlocking. An emergency plate was put into effect on track 2 between Rheems / MP 83.4 and Roy / MP 94.3. Train 624(05) operated on track 1 at 30mph to inspect the catenary between MP 95.0 and Rheems. Train 624(05) reported tree and catenary down on track 2 at MP 89, and tree branches fouling track 1. Train 624(05) was unable to continue east on track 1 and reversed back to Harrisburg, PA. Train 655(05) held on track 2 at Mount Joy, PA for disposition, while 657(05) departed Philadelphia, PA. Train 655(05) discharged passengers at Mount Joy, PA giving them the option to find their own transportation. Some passengers, who required additional assistance, remained onboard as the train reversed back to Lancaster, PA then to Philadelphia representing a late Train 624(05) making all stops. Train 639(05) equipment was utilized as an on-time Train 624(05) from Philadelphia, PA to New York, NY. Train 657(05) held at Lancaster, PA for open track before proceeding west to Harrisburg, PA. Passengers on the original Train 624(05), after returning to Harrisburg, PA took alternate transportation to Philadelphia, PA. All passengers on the late sections of Train 624(05) or alternate transportation who were continuing east of Philadelphia, PA were protected on Train 66(05).

Train	Delay	Comment
624(05)	1'33"	MP 89
657(05)	1'43"	LNC
655(05)	TERM MJY	
657(05)	44"	MJY - ELT - MID

Train 19(04) South of Slidell, LA - Signal

05NOV25: Train 19(04) operating with engine 309 and 346, 8 cars and 66 passengers onboard, was delayed at North Draw (drawbridge) / MP 171.9 on NS N.O. & N.E. District subdivision due to erratic signals on the NS. The conductor reported that the signal dropped, and they had to wait for NS personnel to walk and inspect the bridge. After confirming that the bridge was down, lined and locked, Train 19(04) was able to continue to its' destination, New Orleans.

Train	Delay	Comment
19(04)	1'58"	

Train 85(05) Philadelphia, PA - Servicing

05NOV25: Train 85(05) was delayed departing Philadelphia, PA due to a power swap consisting of a diesel engine being added to avoid causing strain on equipment availability at Washington D.C.

Train	Delay	Comment
85(05)	31"	

Train 68(05) Montreal, Quebec, Canada - Initial Terminal Delay

05NOV25: Train 68(05) operating with engine 101 and 5 cars was delayed departing Montreal, CN due to the crew performing a job briefing regarding wyeing the train on territory that had not been utilized in a long time by the crew, obtaining correct paperwork for engine 101, and obtaining paperwork from CP rail.

Train	Delay	Comment
68(05)	47"	

Train 490(05) New Haven, CT - Engine Failure

05NOV25: Train 490(05) 26-FOI-00103 00000005199 Original UNCLASSIFIED cab 01/14/2025 41, car 82765, and engine 93 was delayed departing New Haven, CT due to engine 93 being swapped out for engine 86 after a high KIPS reading was reported. Once engine 86 was swapped into place, train 490(05) departed New Haven, CT.

Train	Delay	Comment
490(05)	41"	

MNRR Code Green Stamford, CT - Signal

05NOV25: At 8:08 a.m. it was reported that multiple trains would be affected on the MNRR New Haven Line between Stamford milepost 33.1 and South Norwalk milepost 41.0 due to code green and trains operating absolute block.

Train	Delay	Comment
190(05)	03"	
141(05)	06"	
2150(04)	05"	

CSX Switch Replacement - North of Petersburg, VA - Freight Train Interference

05NOV25: Due to CSX replacing a switch located on the North End subdivision located 7 miles north of Petersburg, VA at Walthall milepost 15.0 and the crew working passed the designated work window, multiple trains including 98(04), 52(04), and 84(05) were affected by residual freight traffic congestion in the area.

Train	Delay	Comment
52(04)	55"	
98(04)	1'35"	
84(05)	07"	

CSX Freight Derailment - East of Richmond Main Street, VA

25OCT25: At 3:15PM-ET, CSX reported that C135-23 derailed 20 miles east of the Richmond Main Street, VA station/MP85.0, on the CSX Peninsula Subdivision, at MP65.0. C135-23 was an 11,402 foot long, 220 car coal train with a reported 53 cars piled up on a single main track with no route around. CSX personnel responded to the scene to assess the derailment.

As a result, the following service adjustments were put in place:

-Train 124(25) originated at Richmond Staples Mill, VA with 1 bus operating Newport News, VA, Williamsburg, VA, Richmond Main Street, VA, and Staples Mill, VA. The bus departed at 6:00 p.m. out of Newport News, VA and all passengers were accommodated.

-Train 99(25) was terminated at Richmond Staples Mill, VA with one bus operating from Raleigh, NC to Staples Mill, VA and another bus operating Staples Mill, VA to Newport News, VA. 99(25)'s equipment was wye'd at Richmond Staples Mill to operate back north as a late 124(25).

-Train 65(25) was terminated Richmond Staples Mill, VA with two buses departing Richmond Staples Mill, VA making all stops at Richmond Main Street, Williamsburg, and Newport News.

-Train 96(26) originated Richmond Staples Mill, VA with three buses departing Newport News making all stops at Williamsburg, Richmond Main Street, and Richmond Staples Mill.

-Train 99(26) was terminated Richmond Staples Mill, VA - 4 Buses were secured from AT&T bus company out of Raleigh, NC

-Train 124(26) originated Richmond Staples Mill, VA.- 4 Buses were secured from AT&T bus company out of Raleigh, NC

-Train 86(27-31) originate Washington with passengers going to train 174(27-28) for travel between Richmond Main ST.-Washington, DC and 174(27-28) making additional stops Ashland, Quantico, Woodbridge, VA.

-Train 174(27-31) originate Richmond Main St with alternate bus transportation Newport News, VA, Richmond Staples Mill, VA

Train 100(27-31) originate Richmond Main St. with alternate bus transportation Newport News, VA-Richmond Staples Mills, VA.
 -Train 125(27-31) terminate Washington with alternate transportation
 -Train 65(31) terminate Richmond Staples Mills with alternate Bus transportation Richmond Staples Mills to Newport News.
 -Train 186(27) originated at Richmond Staples Mill due to the train not being serviced and the bus picked up the passengers at Richmond Main St.
 -Train 174(28) was delayed departing Richmond Main St due to receiving orders late from CSX and problems initializing PTC.

31OCT25: Service adjustments have now been extended through and including Friday, November 07th:

Saturday and Sunday Operating Plan November 1st and 2nd

-Train 65(31,01) will terminate at Richmond-Staples Mill with alternate transportation between Richmond-Staples Mill and Newport News
 -Train 164(01,02) will originate in Washington (utilizing TRN 125(31)'s equipment from Friday and 195(01)' equipment from Saturday) - No alternate transportation
 -Trains 194(01) and 96(02) will originate at Richmond-Main-Street with alternate transportation between Newport News and Richmond-Main-Street, - both trains will make Train 164 WBD station stop.
 -Train 195(01,02) will terminate in Washington - No alternate transportation.
 -Train 99(01,02) will terminate at Richmond-Staples Mill with alternate transportation between Richmond-Staples Mill and Newport News (Equipment will represent Train 96(02),174(03) bus bridge Richmond Main St, Williamsburg, and Newport news
 -Train 124 (01,02) will originate at Richmond-Main-Street with alternate transportation between Newport News and Richmond Main Street

Monday through Friday Operating Plan November 3rd -7th:

-Train 86(03-07) will originate at Washington with no alternate transportation. Customers will go to Train 174 (03-07), making ALL train 86 stops Richmond Main and Washington.
 -Train 174(03-07) will originate at Richmond-Main Street with alternate transportation between Newport News Williamsburg and Richmond Main St - will make all scheduled stops for Train 86(3) (ASD, FBG, QAN, WBD)
 -Train 67(02-06) will terminate at Richmond-Staples-Mill with alternate transportation between Richmond-Staples Mill and Newport News
 -Train 186(03-07) will originate at Richmond-Main Street with alternate transportation between Newport News Williamsburg and Richmond Main Street
 -Train 125(03-07) will terminate at Washington with no alternate transportation. Customers to rebook on Train 95 and Train 93 for thruway busing between Norfolk and Newport News. Equipment will represent Train 86 at Washington.

WBS#: B.TR.100150.6204

Train	Delay	Comment
96(26)	13"	ORIG RVR
124(25)	ORIG RVR	ALT BUS
124(26)	2'39"	ORIG RVR OFF 99(26)
124(26)	1'27"	WAS COMM TRANSF STOCK
125(27-31)	TERM WAS	NO ALT
186(27-31)	ORIG RVM	ALT BUS
99(25)	TERM RVR	ALT BUS
65(25,31)	TERM RVR	ALT BUS
67(26-30)	TERM RVR	ALT BUS
174(27-31)	ORIG RVM	ALT BUS
86(27-31)	ORIG WAS	NO ALT
186(27)	34"	SERVICING TRAIN RVR
174(28)	39"	DP RVM
186(28)	38"	ORIG RVM/HLD BUSES
174(31)	15"	DP RVM

16 OCT 2025 11:01 AM 0000005188 UNCLAS//FOUO 11/14/2025
NSRR Blue Ridge Subdivision - Scheduled M/W Work

16OCT25: Norfolk Southern has trackwork scheduled on their Blue Ridge Division starting Monday, November 3rd through November 6th between 10:00AM and 4:00PM from Isom/MP34NC to King/MP48NC. In order to accommodate the outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Nov-6Nov) will depart CLT 15-minutes LATER and operate 20-minutes LATER between KAN and BNC, operate as Bus 3172 between BNC and DNC, and as Train 1072 between DNC and RGH departing DNC 61-minutes LATER and operating 60-minutes LATER between CYN and RGH.
- Train 74 (3Nov-6Nov) will operate 25-minutes LATER between CLT and RGH.
- Train 78 (3Nov-6Nov) will operate 15-minutes LATER between CLT and RGH.

WESTBOUND

- Train 73 (3Nov-6Nov) will operate 85-minutes EARLIER between RGH and DNC and 80-minutes EARLIER between BNC and CLT.
- Train 75 (3Nov-6Nov) will operate as Train 1075 45-minutes EARLIER between RGH and DNC, as Bus 3175 between DNC and BNC, and as Train 75 on their normal schedule between BNC and CLT.
- Train 77 (3Nov-6Nov) will operate 45-minutes LATER between RGH and CLT.
- Train 79 (3Nov-6Nov) will operate 10-minutes LATER between CYN and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between BNC and DNC.
- Bus 3175 will provide alternate transportation between DNC and BNC.

EQUIPMENT:

- Train 72 will make a same day turn at BNC for Train 75
- Train 1075 will make a same day turn at DNC to Train 1072

WBS#: B.TR.100150.6180

22SEP25: Downeaster 26-FOI-001036 000000051991 UNCLASSIFIED CSX 11/14/2025 land Subdivision trackwork between Brunswick, ME and Boston North, MA station. They are welding , switch timbers and tie pickup between Wells, MA and Brunswick on the following Tuesday thru Thursday from 8A-ET to 530P-ET. On September 30,2025 to October 02,2025, October 7-9, 2025, October 14-16, 2025, October 21-23, 2025, October 28-30, 2025 and November 4-6, 2025. The following service adjustments will be made:

Northbound:

-Train 681(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct), which normally operates between BON and BRK, will terminate at WEM.

-Train 681(4Nov-6Nov), which normally operates between BON and BRK, will terminate at DOV. Bus 3681(4Nov-6Nov) will provide alternate transportation between EXR and BRK for all stops except DHM, DOV, and SAO. Passengers on 681 who are traveling north of DOV must use bus bridge at EXR.

-Train 683(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BON and BRK is cancelled in its entirety with no alternate transportation.

Southbound:

-Train 684(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct, 4Nov-6Nov), which normally operates between BRK and BON, is cancelled in its entirety with no alternate transportation.

-Train 686(30Sep-20Oct, 7Oct-9Oct, 14Oct-16Oct, 21Oct-23Oct, 28Oct-30Oct), which normally operates between BRK and BON, will originate at WEM.

-Train 686(4Nov-6Nov), which normally operates between BRK and BON, will originate at DOV. Bus 3686(4Nov-6Nov) will provide alternate transportation between BRK and EXR for all stops except SAO, DOV, and DMH. Passengers traveling south of DOV will connect to train 686 at EXR.

WBS#: B.TR.100151.0776

Amtrak Post Road Branch North of Albany-Kensselaer, NY - Track Repairs

02JUN25: Train 448(02JUN-26JUL) terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02JUN-28JUL) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-28Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

23OCT25: Train 448(29NOV) and Train 449(01DEC) will be the first trains operating normal when service resumes on 30NOV.

WBS#: B.TR.100150.5746

Eastern Region

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

None

Operating Highlights***Train 7(04) West of Browning, MT - Freight Train Interference***

06NOV25: Train 7(04) was delayed 7 mile west of Browning, MT, at milepost 1131.7, on BNSF Hi Line subdivision, due to meeting BNFS8321 and BNSF7226 at control point Spotted Robe.

Train	Delay	Comment
7(04)	1'27"	

Train 719(05) East of Antioch-Pittsburg, CA - Police Related

06NOV25: Train 719(05) was delayed 2 miles east of Antioch-Pittsburg, CA, at milepost 1150.6, on BNSF Stockton subdivision due to a freight train trespasser strike obstructing the route. 719(05) held for the coroner to arrive and remove the body. Once the body was removed and the tracks were re-opened, train 719(05) was able to proceed.

Train	Delay	Comment
719(05)	2'08"	

Train 11(04) North of Burbank, CA - Trespasser Incident

06NOV25: Train 11(04) was delayed 1 mile north of Burbank, CA, at milepost 461.4, on SCRRA Ventura subdivision, due to a vehicle on the tracks. 11(04) held for a track inspector to arrive. Once the track inspector cleared the tracks for movement, train 11(04) was able to proceed.

Train 794(05) was also delayed north of Burbank due the vehicle on the tracks.

WBS#: B.TR.100150.6228

Train	Delay	Comment
11(04)	1'31"	
794(05)	1'04"	

Train 355(05) Battle Creek, MI - B&B Work Due to Defect

06NOV25: Train 355(05) was delayed 4 miles west of Battle Creek, MI, on Amtrak Michigan Line subdivision due to a broken rail between milepost 137-140. Train 355(05) held for the track department to arrive on the scene at which point they were walked by the affected area.

Train 355(05) was further delayed after the crew ran out of hours of service after striking a deer. After the crew inspected the equipment and found no exceptions they held at milepost 178 until the recrew out of Chicago arrived to take over the train. Once the train was recrewed, train 355(05) was able to proceed.

Train	Delay	Comment
355(05)	3'41"	Hold for Broken Rail
355(05)	1'58"	Waiting for Re-crew/Deer Strike.

Train 8(04) West of Wolf Point, MT - Freight Train Interference

06NOV25: Train 8(04) was delayed 11 miles west of Wolf Point, MT, at milepost 238, on BNSF Glasgow subdivision, due to meeting BNSF3877 and BNSF6268 at Oswego siding.

Train	Delay	Comment
-------	-------	---------

Train 355(02) Ann Arbor, MI - Passenger Train Interference

05NOV25: Train 355(02) was delayed 32 minutes at milepost 27.6, on Amtrak Michigan Line subdivision, due to meeting train 352(05).

Train	Delay	Comment
355(02)	32"	

Train 14(04) East of Portland , OR Signal Failure

05NOV25: Train 14(04) was delayed 8 miles east of Portland OR, at Oregon Slough Drawbridge MP8.8, Fallbridge Subdivision, BNSF Railway. The dispatcher was unable to gain remote control of the signals. This required the Engineer to gain verbal authority to pass the signal ahead, while proceeding at reduced speed. Once clear of the affected area train 14(04) resumed to Vancouver, WA.

Train	Delay	Comment
14(04)	30"	
517(05)	43"	

Train 58(05) Jackson, MS - Police Related

05NOV25: Train 58(05), with E/77, 7 coaches and 101 passengers, was delayed holding at Jackson, MS, milepost 728.9, on CN McComb subdivision due to a fertilizer plant explosion near Yazoo City. The police placed a hold on 10 miles of tracks between mileposts 175-165 and as a result train 58(05) held at Jackson, MS station. Fema arrived on location as well as CN supervision approximately 6:30pm-et to evaluate the situation. An Air Quality Control officer was dispatched to the scene and arrived approximately 8:30PM-CT. The initial report was that the air quality was unsafe with high levels of Ammonia gas still in the area. After about an hour the gas levels had dropped significantly and were within safe levels.

58(05) was released approximately 9:40PM-CT, but then held for recrews and pilots. A CN pilot came on duty at 11:30PM-CT and an Amtrak relief engineer was transported to Jackson, MS, from Greenwood, MS. There was an additional Amtrak relief conductor that was transported from Greenwood, MS to meet the train enroute. Train 58(05) departed Jackson, MS at 11:46PM-CT and made it approximately 11 miles north and stopped again due to the onboard conductor running out of hours of service. Train 58(05) held again for the relief conductor out of Greenwood, MS to arrive. The Relief Conductor arrived approximately, 12:35AM-CT and train 58(05) was back on the move at 12:45AM-CT.

Once train 58(05) was back on the move the crew was instructed to shut off their blowers throughout the affected area due to the lingering smell of ammonia in the air.

Service recovery for train 58(05) was as follows; snack packs and water were made available for all passengers as well as complimentary coffee and tea. Sleeper passengers were served menu items from the diner car.

WBS#: B.TR.100150.6227

Train	Delay	Comment
58(05)	5'51"	Holding at JAN
58(05)	50"	Holding North of JAN for recrew.

Train 6(05) at Colfax, CA - Passenger Removal - Behavior

05NOV25: Train 6(05) ~~24-FOI-00103~~ ~~00000005199~~ ~~UNCLASSIFIED~~ at Colfax station when police investigated an alleged assault on a passenger by another passenger. Police responded, questioned, and removed alleged perpetrator (PNR#E1F95C) in conjunction with the incident. The alleged victim (PNR#E04CE8) remained on board to complete travel. Once police had completed their investigation train 6(05) was released - by attending Placer County Sheriffs- to resume to Truckee.

Amtrak Police Notified.

Update: Train 6(05) was delayed 21 miles east of Truckee - at Verdi, MP 227.4, Roseville Subdivision Union Pacific Railroad- waiting for relief crew to take operation of the train. The original crew were requested to briefly violate their Hours of Service to position the train to a safe location for the relief crew to access and board.

Train	Delay	Comment
6(05)	1'29"	Colfax
6(05)	25"	Verdi

Train 504(05) North of Tacoma WA - Freight Train Interference

Train 504(05) experienced a delay approximately six miles north of Tacoma, near Sumner (MP 29.9X) on the Seattle Subdivision of the BNSF Railroad. The delay was caused by BNSF freight train VAUBPTS4-05 (BNSF/8150), which had stopped and obstructed both main tracks at the Pacific crossover (MP 24.0X). Following an inspection, the freight crew identified a broken coupler lifter pin as the source of the issue. After repairs were completed, the freight train cleared the tracks, allowing train 504(05) to resume its journey to Tukwila without further disruption.

Train	Delay	Comment
504(05)	31"	

Train 716(05) Oakland Maintenance Facility – Originates Emeryville – Switching Locomotives

05NOV25: The preparation time for Train 716(05) was shortened at the Oakland Maintenance Facility when inbound locomotive CDTX/2108 was found to have a damaged windshield, a broken engineer's seat, and a faulty exit door. To avoid delays, CDTX/2108 was removed and replaced with CDTX/2010, requiring Train 716(05) to originate in Emeryville. All passengers at Oakland Jack London Square were advised to take Train 534(05) and transfer at Emeryville.

Cause: Pending

Train	Delay	Comment
716(05)	53"	EMY - Passengers to 534(05)

Train 6(05) East of Colfax, CA - Freight Train Interference

05NOV25: Union Pacific train MRVNP-05 (UPRR/ 8014) stalled blocking track #2, 8 miles East of Colfax - at Cape Horn , MP 149.00, Roseville Subdivision, Union Pacific Railroad. While waiting for the stricken train to be re-started, train 6(05) was delayed waiting for train 5(03) to clear main track #1 at Bowman (MP 129.00).

Train	Delay	Comment
6(05)	43"	

Train 4(03) East of Lamy, NM - Passenger Train Interference

05NOV25: Train 4(03) was delayed at Lamy / MP 199.0 on the Burlington Northern Santa Fe Glorieta Subdivision, 15 miles east of the Lamy, NM, meeting Train 3(04).

Train	Delay	Comment
4(03)	19"	

Train 21/421(04) Fort Worth, TX - System

05NOV25: Train 21 / 421(04) was delayed departing the Fort Worth, TX Central Station account of a program move to set out Locomotive 135 and add Locomotive 38. Locomotive 38 was due preventive maintenance in Chicago, IL.

Train	Delay	Comment
21/421(04)	58"	

Train 3(04) West of Raton, NM - Signal

05NOV25: Train 3(04) was delayed between Springer / MP 698.1 and Colmor / MP 710.4 on the Burlington Northern Santa Fe Raton Subdivision, starting 39 miles west of the Raton, NM station, due to signal issues. The train crew was flagged through the area.

Train	Delay	Comment
3(04)	40"	

Train 22(04)/422(02) Pontiac, IL - Injured or Sick Passenger or Employee

05NOV25: Train 22(04) / 422(02) was delayed departing the Pontiac, IL station waiting on EMS to respond and assist with an unresponsive passenger.

Train	Delay	Comment
22(04) / 422(02)	18"	

Train 4(03) East of Fort Madison, IA - Injured or Sick Passenger or Employee

05NOV25: Train 4(03) had requested EMS assistance for a passenger medical emergency. The train was stopped at MP 212.9 on the Burlington Northern Santa Fe Chillicothe Subdivision, 10 miles east of the Fort Madison, IA station.

Train	Delay	Comment
4(03)	35"	

Train 6(03) West of Galesburg, IL - Freight Train Interference

05NOV25: Train 6(03) was delayed at Academy / MP 163.3 on the Burlington Northern Santa Fe Ottumwa Subdivision, 1 miles west of the Galesburg, IL station, due to HBARGAL1-03 (BNSF 7507) experienced an undesired emergency brake application. The freight crew had to inspect their equipment before advancing into the rail yard.

Train 4(03) East of Fort Madison, IA - Injured or Sick Passenger or Employee

05NOV25: Train 4(03) was delayed at MP 212.9 on the Burlington Northern Santa Fe Chillicothe Subdivision, 20 miles east of the Fort Madison, IA station, waiting on EMS to respond and assist with a passenger medical emergency.

Train	Delay	Comment
-------	-------	---------

05NOV25: Train 6(05) was delayed at Capitol Corridor for 11/14/2025 were delayed as a result of the Suisun Drawbridge, MP 32.9/UPRR Martinez Subdivision (1.4 miles east of Martinez) not locking down after being raised for maritime traffic to pass. This resulted in the bridge operator having to manually lower and lock-down the structure. Once that was completed, all train traffic was able to resume movement, flagging across.

Train	Delay	Comment
531(05)	1'13"	
526(05)	1'42"	
6(05)	1'32"	
541(05)	19"	SAC - IDT; late eqpt turn off 526(05)
528(05)	26"	
535(05)	07"	

Train 712(04) Oakland, CA - Third Party Contractor Engine Failure - Ongoing Cancellations

04NOV25: Train 712(04) was delayed departing Oakland, MP 7.0/UPRR Niles Subdivision, following a late yard release after swapping equipment with Train 714(04). This was a result of PCS failure on locomotive E/2010 which could not be repaired in a timely manner. Train 712(04) departed Oakland at 10:33AM-PT.

As a result of prolonged delays repairing locomotive E/2010, Train 714(04) originated at Emeryville. Passengers boarding at Oakland were reaccommodated onto Train 532(04) to Emeryville to make the connection.

UPDATE: As a result of continued delays repairing locomotive E/2010:

- Train 714(04) was cancelled. Passengers were reaccommodated onto Train 716(04).
- Train 717(04) was cancelled. Passengers were reaccommodated onto Train 719(04).

05NOV25: Continuing challenges making repairs to locomotive CDTX/2010 in Oakland cause the following alterations:

Train 714(05) cancelled. Passengers advised to board next available departure to destination.

-Train 717(05) cancelled. Passengers advised to board next available departure to destination.

Cause: Pending

Train	Delay	Comment
712(04)	57"	
717(04)	Cancelled	Psgrs to 719(04)
714(04)	Cancelled	Psgrs to 716(04)
714(05)	Cancelled	Passengers to Next Available Departure
717(05)	Cancelled	Passengers to Next Available Departure

Train 7(03) West of Leavenworth, WA - Engine Failure

05NOV25: Train 7(03) ~~26-FOI-00103~~ ~~00000005199~~ ~~UNCLASSIFIED~~ ~~11/14/2025~~ stalled on the grade at MP 1693.2/BNSF Scenic Subdivision, 22 miles west of Leavenworth and unable to proceed as a result of the unit having insufficient traction power and bad-ordered sanders. The train then made a reverse move to the siding at Merritt, MP 1693.2 where freight locomotive BNSF 7961 was given off an eastbound BNSF freight train. There were 108 passengers onboard and head-end power remained up and running.

Train 7(03) arrived Seattle 5 hours 46 mins late at 5:15PM-PT.

Train 8(05) was delayed departing the Seattle, WA King Street Station account of servicing late inbound Train 7(03).

Train 8(05) Departs Seattle 10:14PM-PT

Service Recovery: Train 8(05)

Service Recovery- Due to the expected late departure of train 8(05) from SEA this evening food has been sourced for distribution at the Seattle Station beginning at 6:00pm. Various Burritos, rice and beans will be available. Dessert and drink service will still be provided for sleeper passengers on board. Pizza has been ordered for Edmonds (EDM) and Everett (EVR) as well.

WBS#: B.TR.100150.6226

Train	Delay	Comment
7(03)	6'14"	
8(05)	5'19"	

Train 525(05) West of Richmond, CA - Freight Train Interference

05NOV25: Train 525(05) was delayed following UPRR freight train INPOA02 between Richmond, MP 11.9/UPRR Martinez Subdivision and Shellmound, MP 7.1. The freight stopped multiple times as a result of having air problems.

Train	Delay	Comment
525(05)	30"	
526(05)	06"	OKJ - ITD late turn off 525(05)

Train 522(05) Berkeley, CA - Vehicle on Tracks

05NOV25: Train 522(05) was delayed at Berkeley, MP 6.2/UPRR Martinez Subdivision, waiting on an auto to be removed off the tracks ahead at MP 10.86 followed by track inspection. Additionally, Train 523(05) was delayed at Richmond, MP 11.9.

Train	Delay	Comment
523(05)	17"	
522(05)	40"	

Train 329(05) West of Chicago, IL - Engine Failure

05NOV25: Train 329(05), operating push-pull with Locomotive ID4601, 4 cars, Locomotive ID4610 and Locomotive ID4622, was stopped at MP 8.7 on the Canadian Pacific Kansas City C & M Subdivision, 9 miles west of the Chicago, IL Union Station, after experiencing an onboard hot axle alarm for Axle #2 on Locomotive ID4610. The crew inspected and took no exceptions. The train operated per AMT-3 limiting the train to not exceed 50 mph for 10 miles before re-inspecting. The crew took no exceptions to the second inspection.

Train	Delay	Comment
329(05)	41"	

Train 8/28(04) West of Sandpoint, ID - Freight Train Interference

05NOV25: Train 8/28 (28-FC-00103S 0000005199) at MP 66.3, 63.14 miles west of Sandpoint, ID station on the BNSF Spokane subdivision due to BMSF Freight 7572 stopped in UDE ahead. Conductor from freight walked train.....

Train	Delay	Comment
8/28 (04)	57"	
7/27 (03)	21"	

Western Region

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
1333 (5)	MSP	152		Shelling

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
7 (3)	XWW	BNSF7961	E/361 having wheel slips and minimal traction effort.	SEA	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
27	SPK	1	LIB-SPT - SPK	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 4(4) Passenger Removal at Albuquerque, New Mexico – Improper Conduct

05NOV25, Passenger traveling on PNR DE126D, from Los Angeles, CA to Chicago, IL was removed at Albuquerque, NM for disrupting other passengers. Amtrak Police notified.

Delay: 4 (4) NONE

Train 4(3) Passenger Removal at Galesburg, Illinois – Medical

05NOV25, Passenger traveling on PNR E08705, from Lamar, CO to Chicago, IL was removed by Burlington / Stronghurst Fire Department at Galesburg, IL. Passenger was unresponsive and appeared to have had a seizure. Once responsive, unaware of surroundings. Amtrak Police notified.

Delay: 4 (3) 35"

Train 4(3) Passenger Removal at Galesburg, Illinois – Medical

05NOV25, Passenger traveling on PNR DF545A, from Kingman, AZ to Princeton, IL was voluntarily removed by Burlington / Stronghurst Fire Department at Galesburg, IL. Passenger was hallucinating and paranoid and called for Police for assistance. Amtrak Police notified.

Delay: 4 (3) 35"

Train 22(4) Passenger Removal at Pontiac, Illinois – Medical

05NOV25, Passenger traveling on PNR 70CCD1, from Longview, TX to Chicago, IL was removed by EMS at Pontiac, IL. Passenger was unresponsive, and the door to room was locked. Amtrak Police notified.

Delay: 22 (4) 18"

Train 14(3) Passenger Removal at Portland, Oregon – Improper Conduct

05NOV25, Passenger traveling on PNR E0B8C1, from Eugene, OR to Vancouver, WA was removed from the train by station security after being aggressive and out of control because the train was stopped. Amtrak Police notified.

Delay: 14 (3) None

Train 14(4) Passenger Removal at Eugene, Oregon – Denied Travel

05NOV25, Passenger traveling on PNR E252F6, from Eugene, OR to Portland, OR was severely intoxicated and was denied travel. Amtrak Police notified.

Delay: 14 (4) 7"

Train 6(5) Passenger Removal at Colfax, California – Improper Conduct

05NOV25, Passenger traveling on PNR E1F95C, from Roseville, CA to Reno, NV was removed from the train by Placer County Sheriff Department for allegedly sexually assaulting another passenger. Amtrak Police notified.

Delay: 6 (5) 90"

Train 11(5) Passenger Removal at Klamath Falls, Oregon – Improper Conduct

05NOV25, Passenger traveling on PNR E2ADD9, from Albany, OR to Sacramento, CA was removed from the train by the Klamath Falls Police Department for inappropriate behavior towards the Assistant Conductor. Amtrak Police notified.

Delay: 11 (5) 21"

Consist Deviations

26-FOI-00103

00000005199

"UNCLASSIFIED"

11/14/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
383 (05)	CHI	Due to shopped car id4007, we will make changes to the equipment causing to deviate from consist plan. no ridership issues.	equipment causing to deviate from consist plan. no ridership issues.	0	ID4206
508 (05)	EUG	No NPCU/Cab Car in consist. No BV sales.	NO BV	1	NOCAR
508 (06)	EUG	No NPCU/Cab Car in consist. No BV sales.	NO BV	0	NOCAR
564 (05)	LAX	Set is operating 1-coach short. XY/WY/U caps adjusted.	IS OPERATING 1-COACH SHORT. XY/WY/U CAPS ADJUSTED	0	NOCAR
582 (05)	LAX	Set is operating 1-coach short. XY/WY/U caps adjusted.	SET IS OPERATING 1-COACH SHORT. XY/WY/U CAPS ADJUSTED	0	NOCAR
562 (05)	LAX	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	0	6904
580 (05)	LAX	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	0	6904
58 (05)	NOL	SET OPERATING WITH 1-LESS STANDARD COACH. LY/XY/WY ADJUSTED. LY OVERCAPACITY. REPLACEMENT AXLE CAR TBD.	4 PAX LY	4	NOCAR
577 (05)	SAN	Set is operating 1-coach short. XY/WY/U caps adjusted.	: SET IS OPERATING 1-COACH SHORT. XY/WY/U CAPS ADJUSTED.	0	NOCAR
593 (05)	SAN	Set is operating 1-coach short. XY/WY/U caps adjusted.	OPERATING 1-COACH SHORT. XY/WY/U CAPS ADJUSTED	0	NOCAR
765 (05)	SAN	765 OPERATING TO LAX WITH COMET SET. NO	pax notified	111	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		JY/BV. CROSS-PLATFORM EQUIPMENT SWAP AT LAX.			
573 (05)	SAN	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	0	6904
591 (05)	SAN	SECOND CAB CAR USED IN LIEU OF A COACH. U CAPPED AT 310.	U CAPPED AT 310	0	6904
8 (05)	SEA	37016 CROSS-OUNTRY CAFE USED IN LIEU OF 38XXX DINER.	NO CUST IMPACT	0	37016
503 (05)	SEA	No NPCU/Cab Car in consist. No BV sales.	NO BV	0	NOCAR
503 (06)	SEA	No NPCU/Cab Car in consist. No BV sales.	NO BV	0	NOCAR
774 (06)	SLO	No BV space on the 90215.	NO BV	4	90215

Reverse Consists

Train Number	Station	Reason
84 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front
2151 (05)	BOS	Acela consist reversed First class at Rear
171 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
141 (05)	SPG	Consist reversed Business class seat orientation may have changed At Front
84 (06)	NFK	Consist reversed Business class seat orientation may have changed At Front