



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, June 06, 2026

Rules: 0-32



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

26-FOI-00510000

Scheduled Departure Date: 06/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/05/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	49	84.9%	1,610	192	88.1%	73,575	10,030	86.4%
Central Division	88.0%	68	5	92.6%	340	27	92.1%	16,312	1,625	90.0%
Northeast Division	82.0%	105	10	90.5%	521	72	86.2%	23,200	3,652	84.3%
Southeast Division	83.0%	73	17	76.7%	363	48	86.8%	16,832	2,455	85.4%
Southwest Division	86.0%	78	17	78.2%	386	45	88.3%	17,231	2,298	86.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00526 00000007705 "UNCLASSIFIED" 6/10/2026

Endpoint Arrival Dates through 6/5/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	108,342	40,028	63%	517,297	134,085	74%	24,160,658	5,623,277	77%
Northeast Corridor	81%	45,658	17,937	61%	234,184	57,258	76%	10,658,467	2,462,996	77%
Acela	83%	10,301	3,865	62%	51,749	9,012	83%	2,100,601	546,589	74%
Northeast Regional	79%	35,357	14,072	60%	182,435	48,246	74%	8,557,866	1,916,407	78%
Richmond / Newport News / Norfolk	77%	11,385	6,435	43%	53,401	20,673	61%	2,654,406	698,323	74%
Springfield Shuttles	89%	795	354	55%	3,660	988	73%	151,450	20,375	87%
Roanoke	79%	4,293	764	82%	18,208	3,467	81%	813,853	155,347	81%
On Spine Northeast Regional	80%	18,884	6,519	65%	107,166	23,118	78%	4,938,157	1,042,362	79%
State Supported	80%	50,591	14,172	72%	223,985	47,552	79%	10,518,392	2,032,671	81%
Borealis	80%	542	0	100%	2,749	336	88%	135,839	27,858	79%
Capitol Corridor	90%	3,487	248	93%	19,581	1,138	94%	903,841	113,551	87%
Carolinian	70%	936	780	17%	4,207	2,050	51%	281,025	97,859	65%
Cascades	75%	2,890	1,063	63%	13,206	6,153	53%	604,450	160,334	73%
Downeaster	82%	1,662	7	100%	7,243	389	95%	353,283	40,647	88%
Empire	78%	6,839	1,915	72%	28,745	6,392	78%	1,302,358	258,930	80%
Adirondack	72%	409	218	47%	1,729	334	81%	76,577	22,642	70%
Ethan Allen Express	70%	663	340	49%	2,768	1,269	54%	135,776	36,909	73%
Maple Leaf	70%	861	323	62%	3,912	1,675	57%	153,552	56,356	63%
New York - Albany	85%	3,485	855	75%	14,202	2,373	83%	608,596	86,073	86%
New York - Niagara Falls	75%	1,421	179	87%	6,134	741	88%	327,857	56,950	83%
Gold Runner	73%	3,177	2,067	35%	12,348	5,956	52%	605,917	202,515	67%
Heartland Flyer	70%	304	220	28%	1,124	434	61%	48,870	18,374	62%
Hiawatha	90%	2,167	0	100%	8,927	377	96%	406,248	44,087	89%
Illinois	78%	3,070	1,059	66%	12,482	4,191	66%	593,625	152,995	74%
Carl Sandburg / Illinois Zephyr	85%	608	97	84%	2,351	712	70%	97,163	23,915	75%
Illini / Saluki	85%	929	590	36%	4,063	913	78%	211,576	45,908	78%
Lincoln Service	70%	1,533	372	76%	6,068	2,566	58%	284,886	83,172	71%
Keystone	92%	8,776	883	90%	46,928	2,562	95%	1,856,407	195,583	89%
Lincoln / Missouri	70%	961	779	19%	3,834	2,130	44%	184,759	88,175	52%
Mardi Gras Service	80%	425	282	34%	1,820	1,049	42%	99,496	17,580	82%
Michigan	70%	2,723	1,200	56%	10,151	3,572	65%	460,155	138,467	70%
Blue Water	70%	626	245	61%	2,145	955	55%	107,272	35,364	67%
Pere Marquette	85%	498	407	18%	1,532	797	48%	59,727	11,587	81%
Wolverine	70%	1,599	548	66%	6,474	1,820	72%	293,156	91,516	69%
Missouri	80%	353	234	34%	925	397	57%	52,829	11,486	78%
Pacific Surfliner	85%	9,068	1,647	82%	36,381	5,361	85%	1,811,886	274,030	85%
Pennsylvanian	80%	809	249	69%	4,182	860	79%	216,168	35,994	83%
Piedmont	80%	1,180	398	66%	3,976	775	81%	287,932	69,276	76%
Vermont	75%	1,222	1,141	7%	5,176	3,430	34%	313,304	84,930	73%
Long Distance	70%	12,093	7,919	35%	59,128	29,275	50%	2,944,532	1,125,147	62%
Auto Train	70%	719	719	0%	3,691	1,288	65%	187,712	61,431	67%
California Zephyr	70%	896	132	85%	4,528	1,294	71%	234,356	68,955	71%
Cardinal	70%	265	149	44%	1,186	323	73%	57,520	25,572	56%
City Of New Orleans	75%	865	795	8%	1,831	1,195	35%	161,828	38,786	76%
Coast Starlight	70%	1,158	612	47%	5,405	2,826	48%	271,495	89,893	67%
Crescent	70%	848	637	25%	4,590	1,881	59%	224,551	60,513	73%
Empire Builder	70%	648	574	11%	4,884	2,889	41%	224,766	98,660	56%
Floridian	60%	1,629	1,444	11%	8,141	5,751	29%	390,232	245,698	37%
Lake Shore Ltd	73%	1,164	353	70%	5,173	1,174	77%	225,633	61,095	73%
Palmetto	70%	892	751	16%	3,995	1,716	57%	223,747	53,637	76%
Silver Meteor	70%	1,073	827	23%	4,968	2,208	56%	245,978	93,074	62%
Southwest Chief	60%	480	480	0%	4,405	2,992	32%	193,681	117,600	39%
Sunset Ltd	70%	428	329	23%	1,461	994	32%	69,653	22,335	68%
Texas Eagle	70%	1,028	117	89%	4,870	2,744	44%	233,380	87,898	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

26-FOI-00526 00000007705 "UNCLASSIFIED" 6/10/2026

Train Index Dates Through June 05, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	30,190	551,812	547	1,399,361	25,925,198	540

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,919	166,071	116	66,056	7,420,922	89
INFRASTRUCTURE PLANNED	135	1,944	166,071	117	64,212	7,420,922	87
FLEET RELIABILITY	90	4,017	551,812	73	230,977	25,925,198	89
TRAIN OPERATIONS	424	22,310	551,812	404	1,038,069	25,925,198	400

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

26-FOI-00510000

Scheduled Departure Date: 06/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/05/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	49	84.9%	1,610	192	88.1%	73,575	10,030	86.4%
Central Division	88.0%	68	5	92.6%	340	27	92.1%	16,312	1,625	90.0%
Northeast Division	82.0%	105	10	90.5%	521	72	86.2%	23,200	3,652	84.3%
Southeast Division	83.0%	73	17	76.7%	363	48	86.8%	16,832	2,455	85.4%
Southwest Division	86.0%	78	17	78.2%	386	45	88.3%	17,231	2,298	86.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0054 Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/05/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	49	84.9%	1,610	192	88.1%	73,575	10,030	86.4%
Central Division	88.0%	68	5	92.6%	340	27	92.1%	16,312	1,625	90.0%
CDL	95.0%	2	1	50.0%	13	2	84.6%	467	16	96.6%
CHI	86.0%	28	0	100.0%	138	9	93.5%	6,565	762	88.4%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	-	-	-	57	2	96.5%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	10	0	100.0%	486	50	89.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GRR	95.5%	1	0	100.0%	5	0	100.0%	236	8	96.6%
KCY	92.0%	2	1	50.0%	9	1	88.9%	488	37	92.4%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	30	2	93.3%	1,452	88	93.9%
MSP	96.5%	1	0	100.0%	5	0	100.0%	241	4	98.3%
PDX	86.0%	5	1	80.0%	25	5	80.0%	1,214	145	88.1%
PNT	88.0%	3	0	100.0%	15	0	100.0%	630	54	91.4%
PTH	93.0%	1	0	100.0%	5	0	100.0%	236	10	95.8%
QCY	91.0%	2	0	100.0%	10	1	90.0%	483	35	92.8%
SEA	85.0%	8	2	75.0%	40	6	85.0%	1,941	268	86.2%
SPK	90.0%	1	-	100.0%	5	1	80.0%	241	18	92.5%
STL	89.0%	4	0	100.0%	20	0	100.0%	957	84	91.2%
TOL	-	-	-	-	-	-	-	2	2	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	10	0	100.0%	480	12	97.5%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	105	10	90.5%	521	72	86.2%	23,200	3,652	84.3%
ALB	88.5%	8	0	100.0%	40	1	97.5%	1,820	153	91.6%
BON	87.5%	5	0	100.0%	25	1	96.0%	1,188	129	89.1%
BOS	85.5%	18	2	88.9%	90	8	91.1%	4,203	529	87.4%
BRK	92.5%	5	1	80.0%	25	4	84.0%	1,179	70	94.1%
BTN	82.0%	1	0	100.0%	5	1	80.0%	234	38	83.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	10	1	90.0%	482	46	90.5%
HFD	-	2	0	100.0%	10	0	100.0%	113	7	93.8%
MTR	79.0%	1	0	100.0%	5	0	100.0%	231	41	82.3%
NFL	93.5%	2	0	100.0%	10	0	100.0%	500	22	95.6%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	1	80.0%	27	1	96.3%	1,284	217	83.1%
NYP	75.5%	49	4	91.8%	242	51	78.9%	9,921	2,214	77.7%
POR	-	-	-	-	-	-	-	5	3	40.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
SAB	98.0%	1	0	100.0%	4	1	75.0%	235	3	98.7%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%

Information Management

26-FOI-0054 Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/05/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	49	84.9%	1,610	192	88.1%	73,575	10,030	86.4%
Northeast Division	82.0%	105	10	90.5%	521	72	86.2%	23,200	3,652	84.3%
SPG	92.5%	5	1	80.0%	23	2	91.3%	1,516	82	94.6%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	5	1	80.0%	234	53	77.4%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
Southeast Division	83.0%	73	17	76.7%	363	48	86.8%	16,832	2,455	85.4%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CLT	91.5%	5	1	80.0%	24	1	95.8%	1,218	110	91.0%
GRO	-	-	-	-	-	-	-	17	5	70.6%
HAR	79.5%	13	1	92.3%	65	6	90.8%	2,746	483	82.4%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	5	0	100.0%	244	31	87.3%
MIA	89.5%	2	1	50.0%	10	3	70.0%	489	49	90.0%
MOE	97.5%	2	0	100.0%	10	0	100.0%	495	7	98.6%
NFK	84.5%	2	1	50.0%	10	4	60.0%	571	96	83.2%
NOL	94.5%	4	0	100.0%	19	0	100.0%	1,042	45	95.7%
NPN	93.0%	2	0	100.0%	10	0	100.0%	463	29	93.7%
PGH	93.0%	1	0	100.0%	5	0	100.0%	246	17	93.1%
PHL	48.0%	5	3	40.0%	25	13	48.0%	1,283	631	50.8%
RGH	95.0%	4	1	75.0%	20	2	90.0%	971	39	96.0%
RNK	83.5%	2	1	50.0%	10	1	90.0%	484	72	85.1%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	5	0	100.0%	243	8	96.7%
SFA	88.0%	1	0	100.0%	5	0	100.0%	244	30	87.7%
WAS	84.0%	28	8	71.4%	140	18	87.1%	5,919	781	86.8%
Southwest Division	86.0%	78	17	78.2%	386	45	88.3%	17,231	2,298	86.7%
ARN	92.0%	1	0	100.0%	5	0	100.0%	247	17	93.1%
BFD	79.0%	7	0	100.0%	34	7	79.4%	1,520	295	80.6%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	1	1	0.0%	5	3	40.0%	262	77	70.6%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	1	0	100.0%	5	1	80.0%	271	33	87.8%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GTA	90.0%	3	1	66.7%	15	5	66.7%	741	88	88.1%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	2	81.8%	52	3	94.2%	2,410	242	90.0%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKC	97.0%	1	0	100.0%	5	0	100.0%	242	4	98.3%
OKJ	74.5%	13	4	69.2%	65	10	84.6%	2,612	645	75.3%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	88.5%	16	4	75.0%	80	9	88.8%	3,438	352	89.8%
SAN	90.5%	13	2	84.6%	65	4	93.8%	2,920	268	90.8%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/05/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	49	84.9%	1,610	192	88.1%	73,575	10,030	86.4%
Southwest Division	86.0%	78	17	78.2%	386	45	88.3%	17,231	2,298	86.7%
SAS	90.5%	1	1	0.0%	5	1	80.0%	244	24	90.2%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SJC	89.0%	7	0	100.0%	35	0	100.0%	1,732	166	90.4%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	2	33.3%	15	2	86.7%	506	49	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	48	2	0	100.0%	104	7	93.3%	3	3	0.0%	105	19	81.9%
2	156	2	0	100.0%	105	23	78.1%	2	1	50.0%	101	17	83.2%
3	89	5	3	40.0%	246	45	81.7%	5	2	60.0%	245	103	58.0%
4	No OS	5	1	80.0%	246	34	86.2%	5	3	40.0%	246	160	35.0%
5		5	0	100.0%	245	38	84.5%	5	2	60.0%	241	50	79.3%
6		5	3	40.0%	244	70	71.3%	5	0	100.0%	244	65	73.4%
7	143	5	0	100.0%	235	28	88.1%	5	2	60.0%	228	50	78.1%
8	498	5	2	60.0%	235	95	59.6%	5	4	20.0%	234	126	46.2%
11		5	2	60.0%	246	44	82.1%	5	2	60.0%	240	47	80.4%
14	40	5	1	80.0%	247	39	84.2%	5	3	40.0%	245	67	72.7%
19	93	5	0	100.0%	245	56	77.1%	5	1	80.0%	244	49	79.9%
20	168	5	0	100.0%	245	16	93.5%	5	2	60.0%	245	39	84.1%
21		5	0	100.0%	242	22	90.9%	5	0	100.0%	241	57	76.3%
22		5	1	80.0%	243	22	90.9%	5	4	20.0%	241	55	77.2%
23	38	5	0	100.0%	248	5	98.0%	5	2	60.0%	247	56	77.3%
24		5	0	100.0%	248	14	94.4%	5	1	80.0%	247	31	87.4%
25	156	5	0	100.0%	247	2	99.2%	5	5	0.0%	246	59	76.0%
26	17	5	0	100.0%	247	3	98.8%	5	4	20.0%	246	42	82.9%
27	193	5	2	60.0%	233	14	94.0%	5	3	40.0%	229	68	70.3%
28		5	3	40.0%	229	49	78.6%	5	2	60.0%	229	38	83.4%
40	90	5	2	60.0%	241	30	87.6%	5	3	40.0%	240	107	55.4%
41	183	5	0	100.0%	241	91	62.2%	5	3	40.0%	239	171	28.5%
42		5	0	100.0%	247	18	92.7%	5	0	100.0%	245	39	84.1%
43		5	0	100.0%	246	37	85.0%	5	1	80.0%	246	43	82.5%
48		5	0	100.0%	245	49	80.0%	5	0	100.0%	245	35	85.7%
49		5	0	100.0%	245	61	75.1%	5	0	100.0%	245	46	81.2%
50	54	2	0	100.0%	100	24	76.0%	2	1	50.0%	100	53	47.0%
52		5	0	100.0%	244	30	87.7%	5	0	100.0%	243	52	78.6%
53	37	5	0	100.0%	244	31	87.3%	5	2	60.0%	243	73	70.0%
55	40	4	1	75.0%	151	5	96.7%	4	3	25.0%	148	30	79.7%
56	42	5	1	80.0%	152	21	86.2%	5	3	40.0%	150	24	84.0%
58	260	5	1	80.0%	237	13	94.5%	5	2	60.0%	236	48	79.7%
59	104	5	1	80.0%	236	21	91.1%	5	2	60.0%	234	34	85.5%
63	66	5	2	60.0%	248	109	56.0%	5	4	20.0%	244	119	51.2%
64	53	5	1	80.0%	246	60	75.6%	5	4	20.0%	246	72	70.7%
66		5	1	80.0%	245	52	78.8%	5	0	100.0%	243	43	82.3%
67		4	0	100.0%	169	11	93.5%	5	0	100.0%	170	27	84.1%
68	28	5	0	100.0%	248	50	79.8%	5	1	80.0%	248	96	61.3%
69		5	2	60.0%	235	48	79.6%	5	1	80.0%	231	24	89.6%
71	11	5	0	100.0%	243	3	98.8%	5	1	80.0%	242	57	76.4%
72		5	0	100.0%	243	22	90.9%	5	1	80.0%	242	43	82.2%
73	20	5	2	60.0%	247	13	94.7%	4	2	50.0%	245	117	52.2%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74	16	4	0	100.0%	246	27	89.0%	4	2	50.0%	244	81	66.8%
75		5	0	100.0%	246	10	95.9%	5	3	40.0%	242	113	53.3%
76	22	5	0	100.0%	246	25	89.8%	5	1	80.0%	239	99	58.6%
77		5	0	100.0%	245	17	93.1%	5	1	80.0%	243	93	61.7%
78		5	0	100.0%	243	14	94.2%	5	0	100.0%	242	40	83.5%
79	78	5	2	60.0%	245	49	80.0%	5	3	40.0%	244	69	71.7%
80	78	5	1	80.0%	245	23	90.6%	5	2	60.0%	244	38	84.4%
84		5	0	100.0%	145	11	92.4%	5	0	100.0%	143	26	81.8%
85	89	5	1	80.0%	153	16	89.5%	5	3	40.0%	153	53	65.4%
86	179	5	0	100.0%	153	11	92.8%	5	5	0.0%	152	88	42.1%
89	74	5	2	60.0%	243	54	77.8%	5	1	80.0%	241	60	75.1%
90	45	5	0	100.0%	243	8	96.7%	5	2	60.0%	242	28	88.4%
93		5	0	100.0%	152	18	88.2%	5	2	60.0%	151	32	78.8%
94		5	1	80.0%	183	43	76.5%	5	1	80.0%	181	62	65.7%
95	70	5	0	100.0%	152	3	98.0%	5	2	60.0%	152	50	67.1%
97		5	4	20.0%	245	154	37.1%	5	0	100.0%	243	60	75.3%
98	52	5	1	80.0%	245	18	92.7%	5	3	40.0%	243	68	72.0%
110		5	5	0.0%	150	88	41.3%	5	1	80.0%	147	16	89.1%
111		5	0	100.0%	143	28	80.4%	5	0	100.0%	141	18	87.2%
112		5	0	100.0%	143	15	89.5%	5	0	100.0%	142	16	88.7%
113		5	2	60.0%	74	17	77.0%	5	0	100.0%	73	8	89.0%
119	30	5	2	60.0%	143	38	73.4%	5	1	80.0%	141	19	86.5%
125	35	5	0	100.0%	153	8	94.8%	5	4	20.0%	153	58	62.1%
129	62	5	1	80.0%	152	41	73.0%	5	2	60.0%	152	21	86.2%
130		5	1	80.0%	143	15	89.5%	5	0	100.0%	141	12	91.5%
131		5	1	80.0%	145	41	71.7%	5	1	80.0%	145	28	80.7%
134		5	1	80.0%	153	19	87.6%	5	0	100.0%	152	23	84.9%
136		5	0	100.0%	153	18	88.2%	4	0	100.0%	151	15	90.1%
137		5	0	100.0%	150	28	81.3%	5	1	80.0%	150	44	70.7%
138	25	5	3	40.0%	153	32	79.1%	5	1	80.0%	152	19	87.5%
141		5	0	100.0%	152	3	98.0%	5	1	80.0%	151	27	82.1%
148		5	1	80.0%	152	16	89.5%	5	1	80.0%	150	28	81.3%
151		5	4	20.0%	244	79	67.6%	5	2	60.0%	243	76	68.7%
170		5	0	100.0%	148	11	92.6%	5	0	100.0%	147	28	81.0%
171	94	5	0	100.0%	153	10	93.5%	5	3	40.0%	153	51	66.7%
172	67	5	0	100.0%	152	14	90.8%	5	2	60.0%	150	47	68.7%
173	236	5	0	100.0%	148	21	85.8%	5	3	40.0%	147	64	56.5%
174		5	1	80.0%	153	18	88.2%	5	1	80.0%	153	28	81.7%
175	23	5	1	80.0%	153	20	86.9%	5	2	60.0%	153	49	68.0%
176	22	5	2	60.0%	148	13	91.2%	5	1	80.0%	146	15	89.7%
177	25	5	1	80.0%	153	23	85.0%	5	1	80.0%	153	43	71.9%
178		5	0	100.0%	153	22	85.6%	4	1	75.0%	151	23	84.8%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179	30	5	2	60.0%	153	16	89.5%	4	2	50.0%	152	50	67.1%
181		5	4	20.0%	149	48	67.8%	5	1	80.0%	147	10	93.2%
182		5	1	80.0%	143	26	81.8%	5	0	100.0%	141	14	90.1%
183		5	2	60.0%	152	46	69.7%	5	0	100.0%	150	32	78.7%
184		5	0	100.0%	153	26	83.0%	5	0	100.0%	152	21	86.2%
185		5	0	100.0%	153	34	77.8%	5	0	100.0%	153	10	93.5%
186	20	5	0	100.0%	152	14	90.8%	5	3	40.0%	151	33	78.1%
190		5	1	80.0%	152	55	63.8%	5	1	80.0%	151	35	76.8%
192		5	0	100.0%	150	19	87.3%	5	1	80.0%	150	14	90.7%
193	73	5	2	60.0%	152	62	59.2%	5	3	40.0%	151	68	55.0%
196		5	1	80.0%	152	14	90.8%	5	0	100.0%	151	13	91.4%
197	21	5	2	60.0%	153	65	57.5%	5	3	40.0%	153	46	69.9%
198	66	5	2	60.0%	85	13	84.7%	4	1	75.0%	84	13	84.5%
230		5	0	100.0%	82	4	95.1%	5	0	100.0%	82	5	93.9%
232		5	0	100.0%	248	10	96.0%	5	0	100.0%	248	16	93.5%
233		5	0	100.0%	232	49	78.9%	5	3	40.0%	232	56	75.9%
234		5	0	100.0%	248	19	92.3%	5	0	100.0%	248	21	91.5%
235	30	5	0	100.0%	172	21	87.8%	5	1	80.0%	172	31	82.0%
236		5	0	100.0%	232	7	97.0%	5	0	100.0%	232	28	87.9%
237	25	5	1	80.0%	247	50	79.8%	5	2	60.0%	245	41	83.3%
238		5	1	80.0%	172	18	89.5%	5	0	100.0%	171	10	94.2%
239		5	1	80.0%	247	68	72.5%	5	1	80.0%	246	25	89.8%
240		5	0	100.0%	247	18	92.7%	5	0	100.0%	246	28	88.6%
241	18	5	2	60.0%	248	65	73.8%	5	3	40.0%	248	59	76.2%
243		5	0	100.0%	184	51	72.3%	5	0	100.0%	184	24	87.0%
244	29	5	0	100.0%	232	9	96.1%	5	1	80.0%	232	35	84.9%
245		5	1	80.0%	129	22	82.9%	5	0	100.0%	128	13	89.8%
280		5	0	100.0%	248	11	95.6%	5	0	100.0%	248	40	83.9%
281	38	5	0	100.0%	248	25	89.9%	5	2	60.0%	248	38	84.7%
283		5	2	60.0%	248	54	78.2%	5	1	80.0%	248	44	82.3%
284		5	0	100.0%	248	10	96.0%	5	0	100.0%	246	34	86.2%
290	17	5	1	80.0%	248	47	81.0%	5	4	20.0%	246	75	69.5%
291		5	0	100.0%	247	56	77.3%	5	1	80.0%	245	39	84.1%
300		5	0	100.0%	232	18	92.2%	5	1	80.0%	230	50	78.3%
301		5	0	100.0%	246	8	96.7%	5	1	80.0%	243	44	81.9%
302		5	0	100.0%	233	28	88.0%	5	3	40.0%	230	66	71.3%
305		5	1	80.0%	236	27	88.6%	5	1	80.0%	232	90	61.2%
306	35	5	0	100.0%	244	13	94.7%	5	3	40.0%	243	61	74.9%
307		5	0	100.0%	236	30	87.3%	5	1	80.0%	233	62	73.4%
311		5	0	100.0%	246	23	90.7%	4	0	100.0%	241	45	81.3%
316	58	4	0	100.0%	243	16	93.4%	4	3	25.0%	240	55	77.1%
318	33	5	1	80.0%	247	23	90.7%	5	3	40.0%	244	105	57.0%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
319	35	5	1	80.0%	248	15	94.0%	5	3	40.0%	246	125	49.2%
329		5	0	100.0%	175	7	96.0%	5	0	100.0%	175	12	93.1%
330		5	0	100.0%	210	4	98.1%	5	0	100.0%	210	13	93.8%
331		5	1	80.0%	248	27	89.1%	5	1	80.0%	248	37	85.1%
332		5	1	80.0%	248	13	94.8%	5	2	60.0%	248	36	85.5%
334	11	5	1	80.0%	248	7	97.2%	5	2	60.0%	247	31	87.4%
335		5	0	100.0%	248	27	89.1%	5	0	100.0%	246	39	84.1%
336		5	0	100.0%	248	8	96.8%	5	0	100.0%	246	19	92.3%
337		5	0	100.0%	248	17	93.1%	5	0	100.0%	244	29	88.1%
338	13	5	0	100.0%	248	37	85.1%	5	1	80.0%	246	71	71.1%
339		5	0	100.0%	248	42	83.1%	5	0	100.0%	248	42	83.1%
341	12	5	0	100.0%	238	31	87.0%	5	1	80.0%	235	32	86.4%
342		5	0	100.0%	248	19	92.3%	5	0	100.0%	246	44	82.1%
350	39	5	0	100.0%	229	15	93.4%	5	4	20.0%	224	119	46.9%
351		5	0	100.0%	231	22	90.5%	5	0	100.0%	230	62	73.0%
352		5	0	100.0%	216	17	92.1%	5	1	80.0%	211	64	69.7%
353		5	0	100.0%	191	12	93.7%	5	0	100.0%	185	30	83.8%
354		5	1	80.0%	229	20	91.3%	5	1	80.0%	225	77	65.8%
355	24	5	0	100.0%	243	26	89.3%	5	2	60.0%	237	78	67.1%
364	78	5	0	100.0%	237	50	78.9%	5	3	40.0%	231	73	68.4%
365		5	0	100.0%	236	10	95.8%	5	2	60.0%	234	74	68.4%
370		5	0	100.0%	239	29	87.9%	5	2	60.0%	235	56	76.2%
371	18	5	0	100.0%	236	8	96.6%	5	2	60.0%	235	26	88.9%
380		5	0	100.0%	235	23	90.2%	5	1	80.0%	235	43	81.7%
381		5	1	80.0%	248	10	96.0%	5	2	60.0%	248	40	83.9%
382	32	5	1	80.0%	248	12	95.2%	5	5	0.0%	248	76	69.4%
383		5	0	100.0%	237	23	90.3%	5	2	60.0%	235	89	62.1%
390	20	5	0	100.0%	230	15	93.5%	5	1	80.0%	229	53	76.9%
391	102	5	0	100.0%	233	6	97.4%	5	1	80.0%	230	47	79.6%
392	53	5	1	80.0%	247	5	98.0%	5	2	60.0%	245	68	72.2%
393		5	0	100.0%	248	15	94.0%	5	1	80.0%	246	65	73.6%
417		5	1	80.0%	163	33	79.8%	5	0	100.0%	154	14	90.9%
425		5	0	100.0%	166	6	96.4%	5	0	100.0%	166	7	95.8%
448	75	5	1	80.0%	178	35	80.3%	5	2	60.0%	176	60	65.9%
449	41	5	1	80.0%	176	28	84.1%	5	2	60.0%	176	31	82.4%
470	23	5	1	80.0%	175	32	81.7%	5	1	80.0%	170	22	87.1%
471		5	0	100.0%	166	5	97.0%	5	0	100.0%	166	2	98.8%
473		5	0	100.0%	172	13	92.4%	5	0	100.0%	169	8	95.3%
474	34	5	1	80.0%	166	45	72.9%	5	4	20.0%	155	38	75.5%
475	24	5	1	80.0%	171	4	97.7%	5	2	60.0%	171	8	95.3%
478	32	5	0	100.0%	164	26	84.1%	5	2	60.0%	162	18	88.9%
479	104	5	1	80.0%	171	26	84.8%	5	1	80.0%	169	17	89.9%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
486	154	5	2	60.0%	175	27	84.6%	5	2	60.0%	169	44	74.0%
494		5	1	80.0%	176	32	81.8%	5	0	100.0%	170	41	75.9%
495		5	0	100.0%	161	3	98.1%	5	0	100.0%	159	3	98.1%
500		5	0	100.0%	240	15	93.8%	5	1	80.0%	238	29	87.8%
502		5	1	80.0%	246	14	94.3%	5	0	100.0%	243	53	78.2%
503		5	0	100.0%	244	20	91.8%	5	1	80.0%	238	60	74.8%
504		5	0	100.0%	248	16	93.5%	5	3	40.0%	246	73	70.3%
505		5	1	80.0%	246	31	87.4%	5	4	20.0%	243	66	72.8%
506		5	0	100.0%	243	33	86.4%	5	2	60.0%	239	37	84.5%
507	40	5	0	100.0%	248	28	88.7%	5	3	40.0%	248	76	69.4%
508	85	5	0	100.0%	243	38	84.4%	5	3	40.0%	240	55	77.1%
509	60	5	1	80.0%	245	12	95.1%	5	4	20.0%	245	58	76.3%
511	19	5	0	100.0%	240	20	91.7%	5	2	60.0%	239	43	82.0%
516	30	5	0	100.0%	240	24	90.0%	5	2	60.0%	239	105	56.1%
517	17	5	0	100.0%	248	7	97.2%	5	5	0.0%	245	94	61.6%
518	29	5	1	80.0%	248	30	87.9%	5	4	20.0%	246	162	34.1%
519		5	0	100.0%	240	8	96.7%	5	1	80.0%	238	58	75.6%
520		5	1	80.0%	133	19	85.7%	5	0	100.0%	130	8	93.8%
521		5	1	80.0%	171	7	95.9%	5	0	100.0%	171	20	88.3%
522		5	1	80.0%	171	29	83.0%	5	1	80.0%	168	17	89.9%
523	78	5	0	100.0%	171	6	96.5%	5	1	80.0%	170	21	87.6%
524	Cncld	5	0	100.0%	171	11	93.6%	4	1	75.0%	169	19	88.8%
525		5	0	100.0%	169	10	94.1%	5	1	80.0%	167	13	92.2%
526		5	1	80.0%	145	24	83.4%	5	0	100.0%	143	11	92.3%
527	11	5	0	100.0%	171	6	96.5%	5	1	80.0%	171	30	82.5%
528		5	0	100.0%	171	13	92.4%	5	0	100.0%	170	29	82.9%
529		5	0	100.0%	171	10	94.2%	5	0	100.0%	170	42	75.3%
530		5	0	100.0%	125	12	90.4%	5	1	80.0%	125	23	81.6%
531		5	0	100.0%	145	10	93.1%	5	0	100.0%	145	10	93.1%
532		5	1	80.0%	171	36	78.9%	5	1	80.0%	171	24	86.0%
534		5	0	100.0%	130	19	85.4%	5	0	100.0%	129	11	91.5%
535		5	1	80.0%	158	22	86.1%	5	0	100.0%	153	20	86.9%
536		5	0	100.0%	171	43	74.9%	5	0	100.0%	168	35	79.2%
537	15	5	1	80.0%	142	14	90.1%	5	1	80.0%	137	12	91.2%
538	No OS	5	0	100.0%	171	21	87.7%	5	1	80.0%	171	33	80.7%
539	34	5	2	60.0%	125	14	88.8%	5	4	20.0%	125	56	55.2%
540		5	2	60.0%	171	34	80.1%	5	0	100.0%	164	16	90.2%
541		5	1	80.0%	170	18	89.4%	5	1	80.0%	167	32	80.8%
542		5	0	100.0%	170	20	88.2%	5	1	80.0%	168	30	82.1%
543		5	0	100.0%	171	15	91.2%	5	0	100.0%	171	45	73.7%
544		5	0	100.0%	169	19	88.8%	5	0	100.0%	166	14	91.6%
545		5	0	100.0%	171	12	93.0%	5	0	100.0%	169	18	89.3%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
547		5	0	100.0%	171	33	80.7%	5	1	80.0%	171	41	76.0%
548		5	0	100.0%	171	20	88.3%	5	1	80.0%	170	14	91.8%
549		5	0	100.0%	166	21	87.3%	5	1	80.0%	162	15	90.7%
550		5	0	100.0%	125	13	89.6%	5	1	80.0%	125	24	80.8%
551	No OS	5	1	80.0%	167	16	90.4%	5	2	60.0%	159	16	89.9%
562		5	0	100.0%	240	18	92.5%	5	0	100.0%	237	27	88.6%
564		5	0	100.0%	240	13	94.6%	5	0	100.0%	232	26	88.8%
566		5	0	100.0%	238	16	93.3%	5	0	100.0%	235	30	87.2%
567		5	1	80.0%	125	7	94.4%	5	0	100.0%	123	5	95.9%
572	23	5	1	80.0%	235	22	90.6%	5	2	60.0%	230	54	76.5%
573		5	0	100.0%	238	35	85.3%	5	1	80.0%	231	38	83.5%
579		5	0	100.0%	125	8	93.6%	5	0	100.0%	120	21	82.5%
580		5	0	100.0%	240	11	95.4%	5	1	80.0%	236	20	91.5%
581		5	0	100.0%	240	38	84.2%	5	0	100.0%	238	45	81.1%
584	40	5	0	100.0%	124	13	89.5%	5	4	20.0%	121	67	44.6%
587		5	0	100.0%	235	14	94.0%	5	0	100.0%	226	30	86.7%
588		5	0	100.0%	125	9	92.8%	5	1	80.0%	125	18	85.6%
591		5	0	100.0%	239	15	93.7%	5	0	100.0%	234	23	90.2%
593		5	0	100.0%	234	33	85.9%	5	0	100.0%	218	24	89.0%
595		5	0	100.0%	236	38	83.9%	5	0	100.0%	234	40	82.9%
600		5	0	100.0%	180	9	95.0%	5	0	100.0%	178	14	92.1%
601		5	0	100.0%	163	70	57.1%	5	0	100.0%	160	23	85.6%
605		5	3	40.0%	170	108	36.5%	5	0	100.0%	166	19	88.6%
607		5	0	100.0%	179	19	89.4%	5	0	100.0%	176	21	88.1%
609		5	0	100.0%	170	22	87.1%	5	0	100.0%	169	14	91.7%
626		5	0	100.0%	84	11	86.9%	5	1	80.0%	82	15	81.7%
639		5	2	60.0%	151	35	76.8%	5	0	100.0%	150	18	88.0%
640		5	0	100.0%	170	6	96.5%	5	2	60.0%	168	72	57.1%
641		5	2	60.0%	152	30	80.3%	5	1	80.0%	152	23	84.9%
642		5	1	80.0%	168	7	95.8%	5	0	100.0%	167	22	86.8%
643		5	0	100.0%	182	39	78.6%	5	0	100.0%	180	31	82.8%
644	43	5	0	100.0%	174	26	85.1%	5	1	80.0%	172	45	73.8%
645	28	5	1	80.0%	182	36	80.2%	5	1	80.0%	180	34	81.1%
646		5	0	100.0%	171	45	73.7%	5	0	100.0%	169	83	50.9%
647		5	0	100.0%	182	31	83.0%	5	1	80.0%	181	40	77.9%
648		5	1	80.0%	178	48	73.0%	5	0	100.0%	178	31	82.6%
649		5	1	80.0%	183	32	82.5%	5	0	100.0%	180	31	82.8%
650		5	0	100.0%	182	38	79.1%	5	0	100.0%	179	26	85.5%
651		5	0	100.0%	182	15	91.8%	5	0	100.0%	180	36	80.0%
652		5	0	100.0%	183	25	86.3%	5	0	100.0%	179	31	82.7%
653		5	1	80.0%	171	29	83.0%	5	2	60.0%	169	33	80.5%
654		5	0	100.0%	172	36	79.1%	5	0	100.0%	169	16	90.5%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
655	22	5	1	80.0%	180	64	64.4%	5	2	60.0%	178	62	65.2%
656		5	3	40.0%	182	43	76.4%	5	0	100.0%	181	21	88.4%
657		5	0	100.0%	171	25	85.4%	5	2	60.0%	170	25	85.3%
658		5	1	80.0%	182	31	83.0%	5	1	80.0%	180	30	83.3%
680		5	0	100.0%	176	7	96.0%	5	0	100.0%	175	22	87.4%
681		5	0	100.0%	176	12	93.2%	5	2	60.0%	171	64	62.6%
682		5	0	100.0%	175	3	98.3%	5	0	100.0%	175	31	82.3%
683		5	0	100.0%	158	15	90.5%	5	1	80.0%	157	43	72.6%
684		5	1	80.0%	157	20	87.3%	5	0	100.0%	157	33	79.0%
685		5	1	80.0%	172	26	84.9%	5	0	100.0%	170	40	76.5%
686		5	1	80.0%	177	31	82.5%	5	0	100.0%	177	34	80.8%
687		5	0	100.0%	177	29	83.6%	5	1	80.0%	176	28	84.1%
688	14	5	2	60.0%	175	7	96.0%	5	2	60.0%	175	29	83.4%
689		2	0	100.0%	132	17	87.1%	2	1	50.0%	131	18	86.3%
701		5	0	100.0%	180	15	91.7%	5	1	80.0%	177	14	92.1%
702		5	0	100.0%	247	26	89.5%	5	1	80.0%	246	52	78.9%
703	45	5	3	40.0%	248	65	73.8%	5	2	60.0%	247	60	75.7%
704		5	2	60.0%	179	29	83.8%	5	1	80.0%	175	35	80.0%
710	20	5	1	80.0%	248	65	73.8%	5	3	40.0%	244	63	74.2%
711	22	5	1	80.0%	239	23	90.4%	5	1	80.0%	223	37	83.4%
712	35	5	1	80.0%	245	61	75.1%	5	2	60.0%	237	74	68.8%
713	69	4	0	100.0%	130	13	90.0%	4	2	50.0%	117	52	55.6%
714	47	5	1	80.0%	131	45	65.6%	4	3	25.0%	122	45	63.1%
715	43	5	1	80.0%	247	53	78.5%	4	2	50.0%	231	111	51.9%
716		5	0	100.0%	248	98	60.5%	5	3	40.0%	243	93	61.7%
717		5	1	80.0%	234	53	77.4%	4	2	50.0%	219	60	72.6%
718		5	1	80.0%	248	120	51.6%	5	2	60.0%	246	80	67.5%
719		5	1	80.0%	248	80	67.7%	5	1	80.0%	236	65	72.5%
757		5	0	100.0%	33	1	97.0%	5	0	100.0%	33	1	97.0%
761		5	1	80.0%	244	10	95.9%	5	1	80.0%	241	33	86.3%
765		5	0	100.0%	244	24	90.2%	5	0	100.0%	244	35	85.7%
769		5	0	100.0%	244	23	90.6%	5	1	80.0%	238	44	81.5%
770		5	0	100.0%	244	20	91.8%	5	0	100.0%	242	62	74.4%
774	40	5	0	100.0%	244	16	93.4%	5	1	80.0%	243	50	79.4%
777		5	1	80.0%	129	10	92.2%	5	0	100.0%	129	30	76.7%
782		5	5	0.0%	129	33	74.4%	5	0	100.0%	124	10	91.9%
785		5	1	80.0%	244	14	94.3%	5	1	80.0%	244	40	83.6%
786	18	5	1	80.0%	33	6	81.8%	5	3	40.0%	32	15	53.1%
790		5	0	100.0%	244	24	90.2%	5	0	100.0%	242	26	89.3%
794	90	5	1	80.0%	244	30	87.7%	5	2	60.0%	242	53	78.1%
821	29	5	0	100.0%	242	4	98.3%	5	2	60.0%	242	95	60.7%
822		5	1	80.0%	244	13	94.7%	5	2	60.0%	242	106	56.2%

Amtrak On Time Performance

Trains Arriving Through: 6/5/2026

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1333		5	0	100.0%	244	26	89.3%	5	2	60.0%	241	81	66.4%
1340		5	0	100.0%	243	4	98.4%	5	0	100.0%	243	39	84.0%
2102		5	2	60.0%	29	10	65.5%	5	1	80.0%	28	3	89.3%
2103		5	1	80.0%	93	10	89.2%	5	1	80.0%	92	7	92.4%
2104		5	0	100.0%	119	9	92.4%	5	0	100.0%	117	9	92.3%
2107		5	3	40.0%	150	29	80.7%	5	0	100.0%	147	18	87.8%
2108		5	1	80.0%	150	24	84.0%	5	0	100.0%	144	16	88.9%
2110	23	5	1	80.0%	29	2	93.1%	5	1	80.0%	29	5	82.8%
2113		5	0	100.0%	29	2	93.1%	5	0	100.0%	29	4	86.2%
2115	19	5	1	80.0%	29	3	89.7%	5	1	80.0%	29	4	86.2%
2121	29	5	1	80.0%	146	27	81.5%	5	2	60.0%	144	25	82.6%
2122	63	5	0	100.0%	148	16	89.2%	5	1	80.0%	148	13	91.2%
2123		5	0	100.0%	29	3	89.7%	5	1	80.0%	29	8	72.4%
2124	55	5	1	80.0%	122	20	83.6%	5	1	80.0%	121	11	90.9%
2126		5	2	60.0%	87	21	75.9%	5	0	100.0%	86	18	79.1%
2150		5	0	100.0%	143	22	84.6%	5	0	100.0%	140	64	54.3%
2151		5	0	100.0%	92	4	95.7%	5	0	100.0%	90	23	74.4%
2155	54	5	0	100.0%	152	13	91.4%	5	3	40.0%	149	85	43.0%
2159	72	5	0	100.0%	145	9	93.8%	5	2	60.0%	144	42	70.8%
2162	23	5	0	100.0%	152	11	92.8%	5	1	80.0%	148	72	51.4%
2163	94	5	0	100.0%	152	17	88.8%	5	2	60.0%	146	62	57.5%
2166	98	5	0	100.0%	148	13	91.2%	5	2	60.0%	146	34	76.7%
2167		5	0	100.0%	142	18	87.3%	5	1	80.0%	142	33	76.8%
2170	26	5	0	100.0%	122	38	68.9%	5	3	40.0%	118	49	58.5%
2171		5	1	80.0%	79	8	89.9%	5	0	100.0%	76	17	77.6%
2172		5	0	100.0%	124	10	91.9%	5	0	100.0%	123	28	77.2%
2190		5	0	100.0%	151	23	84.8%	5	0	100.0%	149	21	85.9%
2192		5	1	80.0%	77	15	80.5%	5	0	100.0%	77	3	96.1%
2193	20	5	1	80.0%	150	22	85.3%	5	1	80.0%	148	45	69.6%

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2110	NYP	23	POL	17	POL	17	XPV-WIL	AM	Fire department hold, ahead all tracks between Hook & Baldwin
2115	WAS	19	WTR	17	WTR	10	NWK-XCY	AM	Heat order, Other, X94-XCY
2121	WAS	29	BSP	15	BSP	11	PHL-XPV	AM	Bridge strike, Control Point, BALDWIN TO HOOK, RST. SPEED A/C BRIDGE STRIKE MP 12.28
2122	NYP	63	MBO	76	MBO	76	BAL-XPV	AM	For maritime traffic, Milepost, 72.14, ., Bush River Bridge opening
2124	NYP	55	POL	27	POL	27	WAS-WAS	AM	Fire department hold, FD HOLD ON ALL TRACKS BETWEEN PHL AND WIL (INBOUND 2121)
2155	WAS	54	ENG	23	ENG	23	XCY-XHM	AM	Air / Brake, 2133, BRAKE APPLICATION FAULT ON PC2133
2159	WAS	72	POL	55	POL	55	PHL-PHL	AM	Fire department hold, FD HOLD ON ALL TRACKS BALDWIN TO HOOK A/C LARGE BRUSH FIRE
2162	BOS	23	DMW	20	DMW	20	STM-NHV	MN	Hold for defect repair Control Point, East Norwalk
2163	WAS	94	MBO	52	MBO	52	XPV-BAL	AM	For maritime traffic, Milepost, 72.14, ., Bush River Bridge opening
2166	BOS	98	POL	69	POL	69	WIL-WIL	AM	Fire department hold, FD HOLD ON ALL TRACKS BALDWIN TO HOOK A/C LARGE BRUSH FIRE
2170	BOS	26	DSR	23	DSR	21	STM-NHV	MN	Per bulletin Milepost, 38.2, 41.7, 30, 4, Milepost, 40.4, 41.7, 30, 2, Milepost, 41.7, 42.0, 15, 2, Milepost, 48.4, 48.6, 30, 2
2193	NYP	20	CTI	38	CTI	24	XNH-STM	MN	Follow metro north, Control Point, 252
85	WAS	89	MBO	67	MBO	67	ABE-BAL	AM	For maritime traffic, Milepost, 72.14, ., Bush River Bridge opening
86	BOS	179	FTI	37	TRS	18	PVD-RTE	AM	Near-miss, Milepost w/Letters, PVD, RTE, AM86 had to copy Form D, traveling restricted speed, report of trespasser on tracks
95	NFK	70	CTI	45	CTI	22	WDB-FBG	CS	Follow vre, 303, Milepost w/Letters, cfp 88.9, cfp 59.3
119	WAS	30	BSP	17	BSP	17	EWR-TRE	AM	Bridge strike, Other, PARSONAGE RD
125	NPN	35	ADA	22	PTI	11	ABE-BAL	AM	Follow, 2115, Milepost, 71.6, 95.7
129	WAS	62	MTI	45	MTI	45	NBK-PJC	AM	Disabled train ahead, Other, NBK-PJC, PSGR TRANSFER WITH DISABLED AM173 AT MP37.5

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
138	NYP	25	PTI	32	PTI	17	ALX-XVG	AM	Follow p080, Control Point, lefant
171	RNK	94	POL	67	POL	67	PHL-PHL	AM	Fire department hold, FD HOLD ON ALL TRACKS BALDWIN TO HOOK A/C LARGE BRUSH FIRE
172	BOS	67	CTI	45	CTI	20	PVD-RTE	AM	Follow, MBTA, 852, Milepost w/Letters, PVD, RTE, AM172 followed signals of MT852
173	WAS	236	ENG	167	ENG	167	MET-TRE	AM	Undesired emergency application, 608, AIR COMPRESSOR OVERHEAT ALARM, NO OIL IN COMPRESSOR
175	WAS	23	CTI	47	CTI	31	NHV-STM	MN	Follow metro, Other, enroute
176	BOS	22	DSR	26	DSR	19	STM-BRP	MN	Per bulletin Milepost w/Letters, STM, BRP, 30, 4
177	PHL	25	ITI	22	ITI	22	BOS-BOS	AM	Service, turn, or wye train, 172, late turn of AM172
179	PHL	30	DET	21	DET	21	NWK-MET	AM	Catenary failure, Other, XCY-XUN, LOSS OF CATENARY POWER ALL TRACKS BETWEEN COUNTY AND UNION.
186	PHL	20	FTI	33	FTI	25	WBG-RVM	CS	Follow G629-02, Milepost, 76.2, 84.7
193	WAS	73	MTI	62	MTI	57	MET-XHM	AM	Disabled train ahead, Other, XCY-XMW, PSGR TRANSFER FROM DISABLED AM173 AT MP37.5
197	WAS	21	CTP	11	CTP	11	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, LATE F/SSYD A/C LACK OF TRACK SPACE DUE TO CANCELLED NJ3947 AND NJ3511
198	NYP	66	DET	64	DET	23	XNY-BWI	AM	Catenary failure, Milepost, 119.5, .. single tracking a/c catenary damage on 3 track
470	HFD	23	DCS	13	DCS	13	STS-WFD	AM	Issue with automatic road crossing protection, Other, MP 12.7 HALL AVE, Copy Form D/ STOP & PROTECT XING HALL AVE MP 12.7
474	SPG	34	CON	28	CON	28	NHV-NHV	AM	Hold for connecting train, late connection of AM174
475	NHV	24	WTR	12	WTR	8	SPG-WNL	AM	Heat order, Milepost w/Letters, SPG, WNL, AM475 held at FIELD due to heat patrol, heat patrol needed additions to Form D and a Form 241 for the different tracks
478	SPG	32	DCS	31	DCS	27	WNL-SPG	AM	PTC- Planned PTC system maintenance, Control Point, Sweeney, RTU replacement at Sweeney delayed 32" on account of planned outage at Sweeney

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
479	NHV	104	ITI	126	ITI	126	GFD-GFD	MA	486 late in 486
486	GFD	154	CON	146	CON	146	NHV-NHV	AM	Hold for connecting train, late connection of AM86
53	SFA	37	FTI	87	FTI	56	XSE-XFL	CS	Follow Milepost w/Letters, a 181.1, a 194.6, io3104
79	CLT	78	FTI	75	FTI	65	FBG-RVR	CS	Follow CSX I031, Control Point, Dahlgren
80	NYP	78	WTR	66	FTI	30	CLT-CLT	NS	Blocked from station track 12R went into emergency, Milepost, 376, 376, 12R
644	NYP	43	ENG	28	ENG	28	PHL-PHL	AM	Air / Brake, 659, BRAKE TEST TROUBLE
645	HAR	28	SYS	11	SYS	11	NYP-NYP	AM	Delay in Block, LATE F/SSYD NO REASON GIVEN
655	HAR	22	CTI	16	MTI	11	NWK-TRE	AM	Disabled train ahead, Other, XIS-XMW , OPERATED NO.4 TRK A/C AM173 DISABLED AT MP37.5
19	NOL	93	FTI	163	FTI	97	SDL-XEJ	NS	Cross Traffic WX went emergency and ran out of time to work..., UPWX, Milepost, 193.5, 5.5
20	NYP	168	FTI	190	FTI	117	ATN-ATL	NS	Blocked from station track Held at Phoenix and then Brookwood until 27A cleared the station, 27A, Control Point, Phoenix
688	BON	14	FTI	11	FTI	7	FRE-POR	CS	Follow L070, Milepost w/Letters, POR 8.7, POR 12.0
63	TWO	66	WTR	20	WTR	15	XSV-ROC	CS	Heat order Milepost, 296.0, 370.0
64	NYP	53	WTR	47	FTI	37	SYR-ROM	CS	Meet csxt, Control Point, 285, 002
68	NYP	28	WTR	41	WTR	41	SLQ-RSP	CN	Heat order Milepost, 43, 0
235	ALB	30	CTI	25	CTI	20	CRT-POU	MN	Follow mn, Control Point, 39
237	ALB	25	PTI	21	PTI	21	HUD-ALB	AM	Wait for station track 49/449/64/68, Control Point, 141
241	ALB	18							
244	NYP	29	CTI	36	CTI	20	POU-CRT	MN	Follow MNRR, 880, Milepost w/Letters, POU, CRT
281	NFL	38	WTR	31	WTR	12	AMS-UCA	CS	Heat order Milepost w/Letters, cp 169, UCA
290	NYP	17	CTI	25	CTI	13	POU-CRT	MN	Follow metro, Milepost, 72, 38
448	BOS	38	DCS	39	DCS	39	WOR-FRA	MT	Power switch failure Control Point, 28
449	ALB	41	FTI	52	FTI	52	PIT-XRD	CS	Cross Traffic csx, M438, Control Point, 150

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
71	CLT	11	DSR	5	TEN	3	CYN-DNC	NS	Engine shutdown Restart engine, NC1755
73	CLT	20	TEN	11	PTI	5	RGH-RGH	NS	Meet Amtk 40, Other, RGH Station
74	RGH	16	ADA	11	DSR	5	HPT-GRO	NS	Per bulletin Milepost, 289.1, 288.6, 25, 1
76	RGH	22	FTI	28	FTI	28	KAN-GRO	NS	Dispatcher had both Main one and Main two blocked by Freight trains. Waited for ns 65w to go up k line off main 2. Ns 165 working main one Control Point, Pomona, #Ns165, #NS65W
89	SAV	74	FTI	81	FTI	21	FLO-KTR	CS	Follow M 407, Milepost, 317.5, 327.6
90	NYP	45	WTR	39	DCS	34	RMT-PTB	CS	Stop signal Control Point, weldon
98	NYP	52	FTI	139	FTI	57	XDI-FAY	CS	Meet CSX 409, Control Point, N. Hamill
55	WAS	40	DSR	50	CTI	15	BRP-STM	MN	Follow mnrr, Milepost, 55.0, 48.0
56	SAB	42	DSR	48	ENG	48	WAS-WAS	AM	Other electrical failure, 639, SHOPPED MTR 639 REPLACED WITH MTR 605
40	CHI	90	ENG	74	CAR	48	MIA-MIA	FL	Air / Brake / Wheel 25106
41	MIA	183	FTI	117	WTR	21	PTB-RMT	CS	Heat order Other, A22.0
23	NOL	38	FTI	74	FTI	35	BAS-XNO	CS	Meet up6058, Control Point, industrial canal
25	NOL	156	FTI	119	FTI	61	XNO-XEJ	NS	Up train dead on law unknown UP, Control Point, Frenchman
26	MOE	17	FTI	18	FTI	18	BIX-PAG	CS	Meet 601, Siding, guatier
523	SJC	78	SYS	68	SYS	58	HAY-HAY	UP	Blocked by or assisting another, disabled Amtrak train
524	SAC	Trn Cancelled	CTI	2	CTI	2	SJC-SCC	UP	Meet Caltrain, Control Point, Stockton
527	SJC	11	PTI	16	CTI	10	SCC-SJC	UP	Meet Caltrain, 121, Control Point, Shark
537	OKJ	15	ITI	15	ITI	15	SAC-SAC	UP	Service, turn, or wye train 524, 524 hours late due to HEP. Took 526 equipment.
538	ARN	No OS Rpt	TEN	36	TEN	22	RSV-RLN	UP	Loading problem Can not regain load trouble shooting, C2107
539	SJC	34	ITI	14	ITI	14	SAC-SAC	UP	Service, turn, or wye train 528, Told to take 528.
551	OKJ	No OS Rpt							
50	NYP	54	DSR	39	WTR	23	XJD-STA	BB	Heat order Milepost, 276.0, 220.8

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
507	EUG	40	FTI	41	FTI	30	ALY-EUG	UP	Pick up / drop off freight crew Stop in the siding Hallawell, met UP8842. Wait for train to clear and assist freight crew back to the head end of their train., UP 8842, Siding, Hallawell
508	SEA	85	FTI	76	FTI	76	PDX-VAN	BN	Meet bnsf 3987, Control Point, wilbridge
509	PDX	60	FTI	56	FTI	50	VAN-PDX	BN	Meet BNSF 8174, Control Point, North Portland Jct.
511	PDX	19	FTI	17	DCS	14	KEL-VAN	BN	Restrictive signal(s) from unknown cause Dark, Milepost, 115.9, 115.9
516	VAC	30	PTI	20	PTI	20	STW-MVW	BN	Meet Amtrak 517, Control Point, North Stanwood
517	PDX	17	DSR	24	DSR	7	XTW-TAC	ST	Per bulletin Milepost w/Letters, 14.4X, 14.6X, 50, 2, Milepost w/Letters, 17.5X, 17.7X, 50, 2, Milepost w/Letters, 19.6X, 20.2X, 60, 3
518	VAC	29	DCS	19	DCS	19	XNI-TAC	ST	Restrictive signal(s) from unknown cause Stop, Control Point, cp188
58	CHI	260	DCS	95	DCS	95	MKS-MEM	CC	Restrictive signal(s) from unknown cause Stopped at CN jct. per dispatcher and signal. Told to work CN jct box then headed to box to have a train run through jct. unknown train. Then signal was gonna clear up but did not. Had to go back to the box and work it., Stop, Control Point, cn jct
59	NOL	104	DSR	86	ENG	60	CDL-FTN	CC	Fire alarm code 0530. Mechanical told us to shut down while engine 369
14	SEA	40	PTI	96	PTI	38	SLO-PRB	UP	Meet Siding, SMG, AMTK 313 S.
7	SEA	143	FTI	140	CAR	71	MKE-CBS	CP	Air / Brake / Wheel 39012, Transition end, replace MR hose that broke & loaded with pipe dope
8	CHI	498	FTI	447	FTI	74	ESM-GPK	BN	Meet bn 8270, bn 6539, bn 7218, Siding, java west
27	PDX	24	FTI	50	FTI	40	BNG-VAN	BN	Follow BN 6042, Other, Bingen Station, Siding, Melonas
821	FTW	29	FTI	32	FTI	18	PVL-ADM	BN	Meet bnsf 7621 & 4415, Siding, gene autry
334	CHI	11	CTI	5	CTI	5	X9L-CHI	AM	Cross Traffic Stopped at Lake, two Metra exiting, including a late- departing 2117., Metra, 2117, Control Point, Lake
338	CHI	13	CTI	8	SYS	4	XRO-GLN	ME	Copy authority / restriction Control Point, Deerfield

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
341	MKE	12	DCS	6	DCS	6	XWA-GLN	ME	Restrictive signal(s) from unknown cause Stop, Control Point, Mayfair
350	PNT	39	PTI	34	PTI	21	XB0-XA5	MI	Meet 353, Siding, albion
355	CHI	24	FTI	40	FTI	34	XPI-HMI	NS	Follow NS270, Milepost, 492, 503
364	PTH	78	DBS	73	DBS	73	BTL-LNS	CC	Debris blocking track (no debris strike) Dispatcher held us at Hope for vehicle on the tracks, had to wait for tow truck and track inspector., Milepost, 219, 219
371	CHI	18	DSR	14	DSR	9	BAM-SJM	CS	Per bulletin Milepost, 70.8, 71.2, 10, main, Milepost, 84.5, 84.8, 25, 2
572	SAN	23	CTI	8	CTI	8	OSD-SOL	SN	Meet NCTD, 633, Control Point, ponto
584	SAN	40	CTI	27	PTI	15	SNC-SNP	SC	Meet 587, Control Point, serra
774	SAN	40	CTI	26	CTI	13	OSD-SOL	SN	Meet coaster, 635, Control Point, Ponto
786	SAN	18	PTI	53	PTI	24	GUA-LPS	UP	Meet 14, Siding, tangair
794	SAN	90	TRS	94	TRS	94	MPK-MPK	SC	Trespasser strike 790 train hit trespasser, Other, MP 435
703	SAC	45	TRS	41	TRS	41	MDR-MCD	BN	Vehicle on track ahead STOPPED AT LE GRANDE, Milepost, 1044.5, 1044.5
710	BFD	20	PTI	25	PTI	10	FNO-HNF	BN	Meet AMTK 715, Control Point, Anderson
711	OKJ	22	FTI	20	FTI	13	HNF-FNO	BN	Meet BNSF 3860 E, Control Point, W. Shirley, Stacks
712	BFD	35	PTI	37	PTI	15	MOD-TRK	BN	Meet Shuffle, amt 713, Control Point, denair
713	OKJ	69	TEN	38	TEN	36	FNO-MDR	BN	Failure of diesel engine ERROR MESSAGE FUEL PUMP NOT WORKER. BREAKER SWITCH TRIPPED TWICE., C2014
714	BFD	47	DCS	31	SYS	24	XPR-ACA	BN	PTC problem or failure (cause unknown) Proceed indication (diverging clear) UP main to UP connection track in field, but PTC showed red. BNSF controlled signal for eastward movement. BNSF PTC desk unable to resolve. Instructed to request authorization to pass signal from BNSF SKN Sub DS., Control Po
715	OKJ	43	PTI	25	FTI	11	BFD-WAC	BN	Meet SF3816, Control Point, East Bakersfield
3	LAX	89	FTI	85	CAR	60	CHI-CHI	AM	Set out defective car 33030
4	CHI	No OS Rpt	ENG	427	ENG	90	KNG-FLG	BN	Traction motor Stopped at 375.2 to reset faults on 142 due to bad traction motors., 142

Amtrak Endpoint OTP Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/5/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
1	LAX	48	FTI	180	FTI	37	XVL-XTS	UP	Follow Follow UP8515 W to MT XTS, Meet UP 7376e shove back., up8515, Control Point, XTS	
2	NOL	156	FTI	169	DMW	55	XWJ-HOS	UP	Hold for defect repair Milepost, 364.57, 364.57	
306	CHI	35	FTI	38	PTI	24	ALN-CRV	UP	Meet Amt 21, Control Point, Miles	
382	CHI	32	FTI	24	FTI	20	KEE-PCT	BN	Hold due to freight congestion bnsf4140 east stopped on main1 at searing and a local working off main 2 st Mendota. Ran single track from buda to zearing bnsf4140, Control Point, buda	
390	CHI	20	PTI	16	PTI	16	CHM-RTL	CC	Meet 391, Control Point, lev jct	
391	CDL	102	TRS	86	TRS	86	CEN-DQN	CC	Vehicle strike Private crossing, Other, crossing at grade mp 260.8 ish	
392	CHI	53	FTI	52	FTI	29	CEN-EFG	CC	Meet up4991, Control Point, edgewood	
316	STL	58	RTE	63	RTE	41	LEE-WAR	UP	Dispatcher hold Held for track defect reported ahead in Warrensburg...45 minute wait for track inspector...was told we could pull into and do our station at Warrensburg, Siding, Centerview	
318	CHI	33	FTI	37	FTI	15	WAR-SED	UP	Meet up7308, Siding, dresden	
319	KCY	35	DSR	24	PTI	18	JEF-SED	UP	Meet Shuffle, 316, Siding, smithton	

Amtrak Initial Terminal Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/5/2026

Terminal	Train	Date	Late	Delay	Cause
CLT	80	06/05	30	30	Blocked from station track 12R went into emergency, Milepost, 376, 376, 12R
HAR	648	06/05	1		
MIA	98	06/05	2	2	Waiting on SFRTA GTB Called at 0611, 0618 & 0630
NFK	138	06/05	1		
PHL	110	06/05	3	3	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	151	06/05	1		
PHL	190	06/05	2	2	Passenger and/or baggage, LQTE TRAVEL
RGH	73	06/05	5	5	Meet Amtk 40, Other, RGH Station
RNK	66	06/05	1		
WAS	56	06/05	48	48	Other electrical failure, 639, SHOPPED MTR 639 REPLACED WITH MTR 605
WAS	130	06/05	3	3	Delay in Block, CREW IDENTIFIED AND RESOLVED DOOR ISSUE (82772)
WAS	176	06/05	2	2	Passenger and/or baggage, LATE PAX AT DEPARTURE TIME
WAS	196	06/05	7		
WAS	198	06/05	69	69	Re-crew / job briefing, TRN HELD FOR CREW OFF OF LATE IB TRN 193
WAS	2102	06/05	3	3	Electrical failure, 3359, FIRST CLASS COFFEE MAKER WASN'T GETTING PWR AND COOLER TEMP DROPPING
WAS	2124	06/05	27	27	Fire department hold, FD HOLD ON ALL TRACKS BETWEEN PHL AND WIL (INBOUND 2121)
WAS	2126	06/05	8	8	Water, commissary, toilet/trash dumping, COMMISSARY DID NOT LEAVE BASE TO LOAD TRN UNTIL DP TIME
BOS	177	06/05	22	22	Service, turn, or wye train, 172, late turn of AM172
BOS	179	06/05	123	123	Service, turn, or wye train, 86, late turn of AM86
BRK	686	06/05	2	2	Restrictive signal(s) from unknown cause Stop, Control Point, Brunswick West
GFD	479	06/05	126	126	486 late in 486
NHV	470	06/05	9	9	Other electrical failure, 46 DX BD, Issues with CAB car / ENG.
NHV	486	06/05	147	146	Hold for connecting train, late connection of AM86
NYP	97	06/05	4	4	Passenger and/or baggage, LOADING
NYP	183	06/05	2	2	Cross Traffic, NJT, NJ6406, Other, NYP
NYP	197	06/05	11	11	Delay due to mechanical problems on a Commuter train, LATE F/SSYD A/C LACK OF TRACK SPACE DUE TO CANCELLED NJ3947 AND NJ3511
NYP	645	06/05	11	11	Delay in Block, LATE F/SSYD NO REASON GIVEN

Amtrak Initial Terminal Details

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/5/2026

Terminal	Train	Date	Late	Delay	Cause
SPG	475	06/05	8	4	Meet, 56, Other, SPG, waited for AM56 to clear single track
SPG	475	06/05	8	4	Heat order, Other, SPG, delayed do to heat patrol
CDL	392	06/05	9	9	PTC - Initializing PTC (no failure) Late train arrival led to late ptc initialization.
KCY	318	06/05	4	4	Wheelchair
PDX	28	06/05	75	75	Routine inspections Late arrival inbound equipment
SEA	8	06/05	108	108	Service, turn, or wye train 7, Due to late departure. 1755. Waited Train 518 departure from station.
SEA	11	06/05	55	55	Broken spring 32016
EMY	6	06/05	2	2	Train 524 broke down we picked up their passengers Other, emy, 524
GTA	782	06/05	10	10	Meet 14, Control Point, CP CO 358
LAX	14	06/05	3	3	Wheelchair
LAX	572	06/05	1		
OKJ	526	06/05	5	5	Meet 11, Control Point, North Jack London
OKJ	540	06/05	2	2	Meet 713, Control Point, ni007
OKJ	712	06/05	1	1	Meet Had to wait for them to depart first., amt 524, Other, okj
OKJ	718	06/05	2	2	Meet 545, Control Point, north jack london
SAC	537	06/05	15	15	Service, turn, or wye train 524, 524 hours late due to HEP. Took 526 equipment.
SAC	539	06/05	14	14	Service, turn, or wye train 528, Told to take 528.
SAC	551	06/05	(No OS)		
SAC	704	06/05	2	2	Group Group of 70 showed up last minute
SAN	777	06/05	1		
SAN	785	06/05	5	5	Service, turn, or wye train 774
SAS	22	06/05	49	49	Hold for connecting train 2
SLO	786	06/05	1		
SLO	794	06/05	1	1	RFE J Torgesen stopped train asked to open doors.

Eastern Region

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	99.5	94.8	340	0
CDOT	95.0	95.2	97.0	92.4	21	1
MARC	95.0	81.4	79.6	90.2	59	11
SEPTA	95.0	96.7	94.5	91.5	214	7
NJT-NED	95.0	93.5	89.2	88.6	354	23
NJT-SED	95.0	86.4	97.1	97.2	22	3

Operating Highlights

Train 97(05) South of Fayetteville, NC - Fatal Trespasser Strike

06JUN26: Train 97(05) with engines 40, 330, 10 cars, and 201 fatally struck a trespasser at milepost 213.4, 5 miles south of Fayetteville, NC on the CSX South End subdivision. The train maintained head end power and remained intact and on the rails. There were no reported injuries to the crew or the customers. Local authorities and local management responded to the scene. The weather at the time of the strike was 69 degrees and clear. The strike did not occur at a crossing. The crew did not request relief. The scene was cleared by the local authorities and the train advanced to the next station at 4:15 AM-ET.

Train	Delay	Comment
97(05)	1'30"	

Train 40(04) East of Connellsville, PA - Freight Train Interference

06JUN26: Train 40(04) with engines 192, 309, 10 cars, and 137 customers onboard was delayed at milepost 251.9, 19 miles east of Connellsville, PA on the CSX Keystone subdivision due to meeting CSX freight train M276. Once the freight train cleared, train 40(04) advanced to the next station.

Train	Delay	Comment
40(04)	30"	

Train 179(05) New London, CT - Car Failure

06JUN26: Train 179(05) with engines 605, 604, 8 cars, and 283 customers onboard was delayed at New London, CT on the Amtrak NHB Line due to mechanical issues with the doors of the train. The crew reported that all of the doors on the fireman's side would open at all stops. The crew worked with mechanical to troubleshoot the issue and was successful. Train 179(05) was on the move at 12:21 AM-ET.

Train	Delay	Comment
179(05)	30"	

Train 136(05) East of Stamford, CT - Power Switch Failure

05JUN26: Train 136(05) with engines 264, 00526, 000000077053, 8 "UNCLASSIFIED" 6/10/2026 customers onboard was delayed at milepost 41.3, 8 miles east of Stamford, CT on the Metro North New Haven Line due to power switch failure at control point 241.

Train	Delay	Comment
136(05)	1'23"	

Train 53(05) North of Florence, SC - Police Related

05JUN26: Train 53(05) with engines 357, 354, 45 cars and 349 customers onboard was delayed at milepost 282.6, 16 miles North of Florence, SC on the CSX South End subdivision due to a police hold being placed on the tracks to search for a suspect. Once the police hold was lifted, train 53(05) was on the move at 12:15 AM-ET.

Train 98(05) with engine 63, 10 cars, and 223 customers onboard was delayed at milepost 292.8 due to the police hold. Train 98(05) was on the move at 12:07 AM-ET.

Train	Delay	Comment
53(05)	1'24"	
98(05)	51"	

Train 448(04) West of Framingham, MA - Power Switch Failure

05JUN26: Train 448(05) with engines 87, 86, 113, 99, 3 cars, and 76 customers onboard was delayed at milepost 28.2, 7 miles west of Framingham, MA on the Keolis Worcester Main Line subdivision due to power switch failure at control point 28.

Train	Delay	Comment
448(04)	39"	

Train 49/449(05) Albany-Rensselaer, NY - Servicing

05JUN26: Train 49/449(05) with engines 117, 374, 11 cars, and 204 customers onboard was delayed departing Albany, NY on the Amtrak HUD line due to scheduled change to the consist. Once the changes were made and the necessary tests performed, train 49/449(05) departed Albany to advance to the next station.

Train	Delay	Comment
49/449(05)	41"	

PW Line Bush River Bridge Opening

05JUN26: At 5:16 PM-ET, it was reported that the Bush River Bridge was open. The opening caused all traffic to stop in the area. It was reported at 6:54 PM-ET that the tracks were returned to service and that normal operations were to resume.

Train	Delay	Comment
2163(05)	52"	
2122(05)	1'16"	
20(04)	1'03"	
136(05)	54"	
97(05)	1'31"	
2124(05)	26"	
85(05)	1'07"	

Train 449(05) West of Pittsfield, MA - Freight Train Interference

05JUN26: Train 449(05) with engine 117, 3 cars, and 86 customers onboard was delayed at milepost 150.6, south of Pittsfield, MA on the CSX Berkshire subdivision due to cross traffic with CSX freight train M438. Once the freight train cleared, train 449(05) advanced to the next station.

Train	Delay	Comment
449(05)	52"	

Train 175(05) West of New Haven, CT - Commuter Train Interference

05JUN26: Train 175(05) with engine 602, 9 cars, and 464 customers onboard was delayed between New Haven, CT and Stamford, CT on the Metro North New Haven Line due to following a Metro North commuter train. Once the commuter train cleared, train 175(05) advanced to the next station.

Train	Delay	Comment
175(05)	31"	

Train 173(05) West of New Brunswick, NJ - Engine Failure

05JUN26: Train 173(05) with engine 606, 10 cars, and 509 customers onboard was delayed at milepost 37.5, 6 miles west of New Brunswick, NJ on the Amtrak NYP Line due to engine failure on engine 606. The engine had a no oil compressor fault that caused the engine to shut down, Rescue engine 608 was sent from New York. All passengers were transferred to trains 129(05) and 193(05).

The rescue engine arrived at the equipment and coupled up. Once the equipment was together and the necessary tests done, train 173(05) was on the move at 8:05 PM-ET.

Train	Delay	Comment
173(05)	2'47"	
129(05)	45"	
193(05)	57"	
198(05)	1'08"	Waiting on crew
173(05)	42"	Held for recrew and then ordered into WAS

Train 79(05) South of Fredericksburg, VA - Freight Train Interference

05JUN26: Train 79(05) with engine 346, 7 cars, and 244 customers onboard was delayed between Fredericksburg, VA and Richmond, VA on the CSX RF&P subdivision due to following CSX freight train IO31. Once the freight train was cleared, train 79(05) advanced to the next station.

Train	Delay	Comment
79(05)	1'05"	

Train 86(05) Bridgeport, CT - Engine Failure

05JUN26: Train 86(05) 26-FOR-00526 in 00000007705 loc UNCLASSIFIED 604, 8/10/2026, and 487 customers onboard was delayed at Bridgeport station due to locomotive failure on engine 604. Locomotive 604 was stopped with an open MCB and I/O station faults. The crew was in contact with an Amtrak Road Foreman and CNOC Mechanical and Siemens technicians and were unable to restore the locomotive after recycling the engine. HEP was initially reported to be down, however, further updates reported HEP was operational throughout the episode with the exception of the attempts to recycle the locomotive. It was identified that the locomotive would not be able to continue providing power for the train. Rescue motor E/605 and mechanical personnel were dispatched out of New Haven to the location of the disabled train. Once the motor arrived it was added to the train and train 86(04) was able to proceed.

Due to the late operation of train 86(04) it caused a late initial terminal delay to train 179(04) at Boston due the equipment turn.

Train	Delay	Comment
86(05)	1'50"	
486(05)	2'26"	Held for connections from 86(05)
479(05)	2'06"	Late turn from 486(05)
179(05)	2'03"	Late turn from 86(05)

Train 20(04) South of Manassas, VA - Commuter Train Interference

05JUN26: Train 20(04) operating with locomotives 40-330, 8 cars and 194 customers onboard was delayed south of Manassas at MP 35 on the NS Alexandria-Montview subdivision meeting VRE 325. Once VRE 325 passed an open route was established and train 20(04) was able to proceed.

Train	Delay	Comment
20(04)	36"	

Train 98(04) North of West Palm Beach, FL - Freight Train Interference

05JUN26: Train 98(04) operating with locomotives 163-63, 10 cars and 157 customers onboard was delayed at MP 650 on the CSXS Auburndale subdivision meeting CSX I453-05 at Palm Center. Once the freight passed an open route was established and train 98(04) was able to proceed.

Train	Delay	Comment
98(04)	34"	

Train 48(04) East of Syracuse - Freight Train Interference

05JUN26: Train 48(04) operating with locomotives 113-99, 10 cars, and 134 customers onboard was delayed east of Syracuse at MP 258 on the CSX Mohawk subdivision following a track inspector from Syracuse to Amsterdam. Once the train arrived in Amsterdam the track inspector was no longer obstructing their operation.

Train	Delay	Comment
48(04)	1'10"	

05JUN26:

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

2:27 pm-et - Amtrak police requested a hold on all tracks on the PW Line at MP 12.8 between Hook and Baldwin interlockings for a brush fire adjacent to the tracks. APD National Operations liaison responded to the scene and provided updates that multiple agencies had responded, hoses were over the tracks, additional resources were enroute and the responders were making progress in fighting the fire. Train 2166(05) was held after departing Wilmington at Landith interlocking and trains began to hold at Philadelphia with 171(05), and 2159(05) and Wilmington with 184(05). Train 2166(05) reversed back to Wilmington awaiting the opening of the tracks.

3:24 pm-et - APD reported the fire was contained off the right of way and released their hold allowing train traffic to resume.

Train	Delay	Comment
2110(05)	17"	
2166(05)	1'09"	
171(05)	1'07"	
184(05)	16"	
2159(05)	55"	

Train 64(05) East of Syracuse, NY - Freight Train Interference

05JUN26: Train 64(05) with engine 119, 5 cars, and 180 customers onboard was delayed at milepost 285.9, 7 miles east of Syracuse, NY on the CSX Syracuse Terminal subdivision due to meeting a CSX freight train. Once the freight train passed, train 64(05) advanced to the next station.

Train	Delay	Comment
64(05)	37"	

Train 90(05) North of Rocky Mount, NC - Stop Signal

05JUN26: Train 90(05) with engine 333, 8 cars, and 222 customers onboard was delayed at milepost 84.7, 32 miles north of Rocky Mount, NC on the CSX North End subdivision due to receiving a stop signal at control point Weldon. Once the train received a move favorable signal, it advanced to the next station.

Train	Delay	Comment
90(05)	34"	

Multiple Trains - NYP Line - Bridge Strike

05JUN26: 11:16am-et Bridges and Building Supervisor reported a bridge strike on marked bridge at Parsonage Road MP 24.38 and confirmed a strike after reviewing video at the location that a truck did make contact with the bridge structure. Per operating rule, special instruction 132-S2 to operate over the bridge at restricted speed was placed into affect.

12:01pm-et Bridges and Building inspector reported bridge was free of damages and returned it to normal service.

Train	Delay	Comment
125(05)	04"	
119(05)	17"	
646(05)	05"	
2162(05)	05"	
95(05)	06"	
2155(05)	13"	
56(05)	04"	
43(05)	08"	

Train 80(05) Initial Terminal Delay - Freight Train Interference

05JUN26: Train 80(05) 26-FOI-00526-00000007705 UNCLASSIFIED 239, 7/6/2026 and 91 customers onboard was delayed at the initial terminal of Charlotte due to a disabled NS 12r-04 with a broken knuckle blocking one of the station tracks. NS was holding train 80(05) in the yard for train 20(04) to occupy Charlotte station. NS was informed it was not necessary to hold train 80(05) and advanced them into the station to allow boarding of their customers and allow the train to depart.

Train	Delay	Comment
80(05)	30"	

CSX heat Orders

05JUN26: CSX has imposed heat orders in effect 1:00 pm-et to 7:00 pm-et for the following subdivisions: Baltimore Terminal, Capital, Cumberland, Keystone, Metropolitan, Old Main Line, Peninsula, RF&P, Richmond Terminal and North End.

Train	Delay	Comment
186(05)	13"	
53(05)	24"	
79(05)	12"	
52(05)	02"	
281(05)	31"	
98(05)	19"	
283(05)	21"	
90(05)	39"	
40(04)	1'04"	
40(05)	47"	
125(05)	21"	
89(05)	50"	
64(05)	47"	
95(05)	13"	
138(05)	23"	
80(05)	1'06"	
79(05)	03"	
41(04)	16"	
97(04)	23"	
20(04)	02"	
63(05)	20"	
178(05)	01"	
94(05)	04"	

CN Heat Orders

05JUN26: CN imposed heat orders on the Rouses Point subdivision causing delays to trains 68 and 69.

Train	Delay	Comment
68(05)	41"	
69(05)	53"	

Train 56(05) Washington - Initial Terminal Delay - Engine Failure

05JUN26: Train 56(05) operating with locomotive 639, and 5 cars was delayed at the initial terminal of Washington due to locomotive 639 shopping out for unrecoverable faults at departure time. Locomotive 605 was used as a replacement motor and once the train was assembled, tested and documented the equipment was positioned in the terminal for boarding of the 235 customers and departed.

Train	Delay	Comment
56(05)	48"	

Train 97(04) South of Savannah, GA - Freight Train Interference

05JUN26: Train 97(04) 26-FOI-00526 00000007705 UNCLASSIFIED 320-376-236 6/10/2026, 10 cars and 222 customers onboard was delayed at MP 539 on the CSX Nahunta subdivision due to freight train interference waiting for CSX I098-04 at Backswamp. Once the freight passed an openroute was established and train 97(04) was able to proceed.

Train	Delay	Comment
97(04)	35"	

26 MAY 2026 09:00:00 17705 "UNCLASSIFIED" 41078826
CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

NECR Trackwork - Affecting Vermonter Service - 5/16 - 6/20 - Scheduled M/W Work

15MAY26:

NECR New England Central and Roxbury Subdivision, White River Junction to St. Albans, VT, Friday May 15th - Saturday June 20th

To accommodate the above outlined infrastructure work, Amtrak's Vermonter Service will be adjusted as follows:

- Train 55(15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun) will depart SAB 20-minutes Earlier, at 8:55am, and resume normal schedule departing WRJ at 11:37am.
- Train 56(15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun) will depart MPR 20-minutes Later, at 7:54pm, and operate 20-minutes Later to SAB.
- Train 54(16May-17May, 23May-25May, 6Jun-7Jun, 13Jun-14Jun, 20Jun) will depart MPR 20-minutes Later, at 7:54pm, and operate 20-minutes Later to SAB.
- Train 57(16May-17May, 23May-25May, 6Jun-7Jun, 13Jun-14Jun, 20Jun) will depart SAB 20-minutes Earlier, at 8:55am, and resume normal schedule departing WRJ at 11:37am.

WBS#: B.TR.100150.6668

Train	Delay	Comment
57(17)	37"	

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday

Work will occur Monday 26-Fri 00526, 00000007705 - 2:00 PM at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

Eastern Region

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
20 (26)	XN2	174		Brake pads missing

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 6(04) West of McCook, NE - M of W Work

06JUN26: Train 6(04) was delayed at MP456.2, 169.9 miles west of McCook, NE on the BNSF Brush subdivision due to a red flag at MP456.6. Maintainers arrived and removed the red flag. Train 6(04) was back on the move at 1017PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	52"	

Train 5(05) East of Omaha, NE - High Wind Warnings

06JUN26: Train 5(05) was delayed beginning at MP463, 42.60 miles east of Omaha, NE station on the BNSF Creston subdivision operating at a reduced speed of 40 miles per hour due to high wind warnings until MP17.0. Train 5(05) was delayed by flash flood warnings from MP96 to MP128 on the BNSF Hastings subdivision.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(05)	32"	LNK-HAS
5(05)	28"	CRN-OMA

Train 8/28(03) West of Glenview, IL - M of W Work

06JUN26: Train 8/28(03) was delayed holding at MP24.7, 7.32 miles west of Glenview IL station on the CPKC C & M subdivision meeting train 343(05) and a commuter train due to maintenance work creating single tracking through the area. Train 8/28(03) was back on the move at 1223AM CT after the trains cleared to the west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(03)	40"	

Train 8/28(03) West of Tomah, WI - Passenger Train Interference

06JUN26: Train 8/28(03) was delayed holding at MP264.9, 23.13 miles west of Tomah, WI station on the CPKC Tomah subdivision for a meet with 7/27(05). Train 8/28(03) was back on the move at 756PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(03)	31"	

Train 48/448(05) West of South Bend, IN - Freight Train Interference

06JUN26: Train 48/448(05) was delayed beginning at MP490, 52.5 miles west of South Bend IN station on the Norfolk Southern Chicago 76 subdivision following NS freight 276 until MP463.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448(05)	35"	

Train 4(04) West of Raton, NM - High Wind Warnings

06JUN26: Train 4(04) was delayed at MP526.0, 2.2 miles west of Raton, NM, station on the BNSF Raton subdivision due to operating at a reduced speed of 40 miles per hour due to high wind warnings. Train 4(04) operated through the high wind warnings until MP565.

Train	Delay	Comment
4(04)	13"	LSV-RAT
4(04)	41"	TRI-LAJ

Train 19(04) North of New Orleans, LA - Freight Train Interference

06JUN26: Train 19(04) was delayed at MP6.0, 6 miles north of New Orleans LA station on the Norfolk Southern New Orleans Terminal subdivision due to UPRR freight train AV-24(05) stopped blocking the route with a crew expired on hours of service. The freight re-crew arrived on scene at 939PM CT. The freight train pulled and cleared the route for train 19(04). Train 19(04) was back on the move at 1013PM CT. Train 25(05) was also delayed holding at MP7.0, 7 miles north of New Orleans LA station and was back on the move at 1023PM CT.

Train	Delay	Comment
20(05)	1'01"	
19(04)	1'37"	

Train 20(05) South of Atlanta, GA - Freight Train Interference

06JUN26: Train 20(05) was delayed beginning at MP143.1 south of Atlanta, GA station on the Norfolk Southern Atlanta North subdivision following Norfolk Southern freight train 50G. Train 20(05) followed the freight train into Atlanta GA station and was able to resume track speed after departing the station.

Train	Delay	Comment
20(05)	31"	

Train 2(03) West of Beaumont, TX - System

06JUN26: Train 2(03) was delayed at MP400, 57.6 miles west of Beaumont, TX station on the UPRR Beaumont subdivision due to PTC enforced breaking. Crew worked with the PTC desk and was able to resolve the issues. Train 2(03) was back on the move at 319PM CT.

Train 2(03) was delayed again at MP680.4, east of Lafayette LA station due to PTC system failure. Crew was able to reset and re-initialize PTC after speaking with the PTC desk. Train 2(03) was back on the move for the second time at 740PM CT.

Train	Delay	Comment
2(03)	42"	E/BMT
2(03)	25"	E/LFT

Train 718(05) Merced, CA - Vehicle on Tracks

06JUN26: Train 718(05) was delayed departing Merced, CA, on BNSF Stockton subdivision due to a vehicle on the tracks west of Merced at milepost 1044.5. Local authorities responded to the scene and discovered the vehicle was gone before a tow truck could be arranged. Once the vehicle was reported gone, the tracks were released and 718(05) was able to proceed at restricted speed through the affected area.

Train 703(05) was stopped east of Stockton, CA waiting for open route.

Train	Delay	Comment
718(05)	27"	
703(05)	41"	

Train 509(05) South of Vancouver, WA - Freight Train Interference

06JUN26: Train 509(05) was delayed 50 seconds at 100000007705 miles south of Vancouver, WA, on BNSF Fallbridge subdivision, due to meeting BNSF 8174 at Portland Junction. Once the freight was clear and a route was made available, train 509(05) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
509(05)	50"	

Train 507(05) South of Albany, OR - Freight Train Interference

06JUN26: Train 507(05) was delayed 2 miles south of Albany, OR, on UP Brooklyn subdivision, due to meeting UP8842 at Hallawell siding. The freight was just recovering from being disabled and train 507(05) waited and gave the freight conductor a ride to the head end of their equipment.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
507(05)	30"	

Train 508(05) North of Portland, OR - Freight Train Interference

05JUN26: Train 508(05) operating with engine 1408/164, 4 coaches, and 75 customers, was delayed 4 miles north of Portland, OR, on BNSF Fallbridge subdivision, due to a freight train occupying the main while being put away in the yard. Once BNSF3987 cleared the main, train 508(05) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
508(05)	1'16"	

Train 355(04) East of Hammond-Whiting, IN - Freight Train Interference

05JUN26: Train 355(04) was delayed at MP492, 16.80 miles east of Hammond-Whiting, IN station on the Norfolk Southern Chicago 76 subdivision following Norfolk Southern freight train 270. Train 355(04) followed the freight train until MP503.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(04)	34"	

Train 6(05) West of Elko, NV - Freight Train Interference

06JUN26: Train 6(05) was delayed 57 miles west of Elko, NV, on UPRR Elko subdivision, due to following UP7975 from milepost 612 to milepost 642. Once the freight cleared and a route was made available, train 6(05) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(05)	43"	

Train 25(05) North of Pascagoula, MS - Debris

05JUN26: Train 25(05) was delayed at MP687.2, 20.86 miles north of Pascagoula, MS station on the CSX N O and M subdivision due to power lines down on the tracks ahead. The local power company responded to the scene and removed the lines from the tracks. Train 25(05) was back on the move at 556PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(05)	51"	

Train 364(05) West of East Lansing, MI - Trespasser Incident

05JUN26: Train 364(05) was delayed at MP017.8, 6.63 miles west of East Lansing, MI station on the CN Flint subdivision due to a vehicle on the tracks ahead. A tow truck responded to the scene and removed the vehicle from the tracks. Once the vehicle removed the track inspector completed their inspection and released the tracks. Train 364(05) was back on the move at 1007PM ET.

Train	Delay	Comment
364(05)	1'13"	

Train 538(05) East of Rocklin, CA - Engine Failure

05JUN26: Train 538(05), operating with engine 2107, 5 coaches, and 17 customers, came to a stop 1 miles east of Rocklin, CA, on UP Roseville subdivision due to loading issues. This train was terminated at Rocklin, CA with supplemental bus out of Sacramento, CA to accommodate customers to Auburn, CA. The bus arrived approximately 8:20pm-pt. Road foreman Brubaker and ASO Wrought responded to the scene to trouble shoot the equipment. They were unsuccessful and as result train 551(05) was used to rescue this equipment and take it to oakland for repairs. There were no buses available to assist 551(05). 551(05) arrived at Rocklin at 10:10pm-pt and coupled up to the west end of the equipment. Once coupled they proceeded to Sacramento where they continues their normal route. As a result of the bad ordered equipment train 729(06) was cancelled with buses being sourced as alternate transportation Auburn, CA to Sacramento, CA and customers will be accommodated on 733(06).

WBS#: B.TR.100150.6741

Train	Delay	Comment
538(05)	Cancelled	RLN
551(05)	3'53"	Rescued 538(05) equipment.
729(06)	Cancelled	

Train 25(05) North of Pascagoula, MS - Freight Train Interference

05JUN26: Train 25(05) was delayed at MP701.1, 7.20 miles north of Pascagoula station on the CSX N O and M subdivision holding in the Orange Grove siding for a meet with Freight train 602(05). Train 25(05) was back on the move at 657PM CT.

Train	Delay	Comment
25(05)	58"	

Train 58(05) South of Yazoo City, MS - Freight Train Interference

05JUN26: Train 58(05) was delayed beginning at MP216, 46.1 miles south of Yazoo City MS station on the CN Yazoo subdivision meeting freight trains 2268, 3072 and 2319. Train 58(05) was clear of the freight trains at MP182.5 and resumed operating at track speeds.

Train	Delay	Comment
58(05)	58"	

Train 316(05) West of Warrensburg, MO - Routing

05JUN26: Train 316(05) was delayed beginning at MP223.8, 5.32 miles west of Warrensburg, MO station on the UPRR Sedalia sub due to a reported track defect at MP216.78. Track inspector arrived on scene and determined the track could be accessed without hi-railing so train 316(05) was allowed to advance to Warrensburg station at 600PM CT. The track inspector found no damage and the tracks were released at 630PM CT. Train 316(05) departed Warrensburg MO station at 631PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(05)	41"	

Train 777(05) West of Goleta, CA - Passenger Train Interference

06JUN26: Train 777(05) was delayed 2 miles west of Goleta, CA, on UP Santa Barbara subdivision, due to meeting train 794(05) at control point Ellwood.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
777(05)	34"	

Train 8/28(04) East of Malta, MT - Signal

06JUN26: Train 8/28(05) was delayed 27 miles east of Malta, MT, on BNSF Milk River subdivision, due to signal issues at Saco siding. Train 8/28(04) had to be talked by the signals at the siding and then operate at restricted speed afterwards.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(04)	1'10"	

Train 3(04) West of Las Vegas, NM - Temporary Speed Restrictions

05JUN26: Train 3(04) was delayed 2 miles west of Las Vegas, NM, on BNSF Glorieta subdivision due to operating through temporary speed restrictions from milepost 772 to milepost 828.9. Train 3(04) was able to resume normal speed once cleared of the affected area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(04)	36"	

Train 27(03) Bingen-White Salmon, WA - Freight Train Interference

05JUN26: Train 27(03) was delayed beginning at Bingen-White Salmon WA station/MP76.1 on the BNSF Fallbridge subdivision following BNSF Freight 6042. Train 27(03) was able to get around the freight at Melonas siding/MP49.3 and resumed operating at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
27(03)	40"	

Train 4(04) West of Kingman, AZ - Passenger Train Interference

05JUN26: Train 4(04) was delayed 11 miles east of Kingman, AZ, on BNSF Seligman subdivision due to meeting train 3(03) at control point Griffith. Once train 3(03) cleared and a route was made available, train 4(04) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(04)	40"	

Train 713(05) Fresno, CA - Third Party Contractor Engine Failure

05JUN26: Train 713(05), E/62-E/14-9 cars, was delayed at MP 1005.7, 7 miles west of Fresno, CA, on the BNSF Stockton Subdivision due to C/C2014 having a fuel pump fault. The crew contacted mechanical to troubleshoot. Head end power (HEP) remained active. Once crew reset breaker, the fault cleared and Train 713(05) proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
713(05)	36"	

Train 4(04) Albuquerque, NM - Servicing

05JUN26: Train 4(04), E/62-E/14-9 cars, was delayed departing Albuquerque, NM after during the routine inspections the dynamic brakes issues were found on the trail E/14. Once mechanical was able to resolve issues, Train 4(04) departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(04)	30"	

Train 20(05) North of Laurel, MS - Freight Train Interference

05JUN26: Train 20(05) was held approximately 5.6 miles north of Laurel, MS (MP 56.4) on the NSRR NO&NE Subdivision at Hawkes (MP 50.8) while meeting NS 131. Once the meet was completed, Train 20(05) advanced to 27th Avenue (MP 0.4) where it met NS 29K.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(05)	34"	NS 29K
20(05)	20"	NS 131

Train 8/28(04) West of Shelby, MT - Freight Train Interference

06JUN26: Train 8/28(04) was delayed 33 miles west of Shelby, MT, on BNSF Hi Line subdivision, due to meeting and following an unknown BNSF freight. Once the freight cleared and a route was made available, train 8/28(04) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(04)	39"	

Train 391(05) South of Centralia, IL - Vehicle Strike

05JUN26: At 1:19PM-CT, Train 391(05), E/ID4609-7 Cars, struck an occupied vehicle at a private road crossing (DOT#295005Y) located at MP 260.71 on the CNRR Centralia Subdivision, approximately 8.4 miles south of Centralia, IL (MP 252.3), in Irvington, Washington County. The crossing was equipped with an ENS sign. Both occupants of the vehicle were reported as uninjured. At the time of the incident, the train was operating at 79MPH, the maximum authorized timetable speed for the location. Weather conditions were approximately 80.6 degrees and partly sunny, and head-end power was maintained throughout the duration of the incident. No injuries were reported to the crew or the 56 customers onboard, and no damage was reported to the train equipment. Local police and EMS responded to the scene along with the Carbondale Road Foreman. The crew did not request trauma relief. Once released by local authorities, Train 391(05) resumed movement south at 2:33PM-CT.

National Response Center Number: 1464444

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
391(05)	1'26"	

Train 11(05) Seattle, WA - Car Failure

05JUN26: Train 11(05) was held approximately 2.6 miles west of Seattle, WA (MP 362.3) on the UPRR Houston Subdivision at MP 364.9 due to an RMCC hold on all tracks. A concerned citizen had reported potential track damage at MP 364.57. A Union Pacific track inspector was dispatched to the location. Once the area was inspected and deemed safe for travel, Train 2(03) was released to continue east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(05)	55"	

Train 2(03) West of Houston, TX - Police Hold

05JUN26: Train 2(03) was held approximately 2.6 miles west of Houston, TX (MP 362.3) on the UPRR Houston Subdivision at MP 364.9 due to an RMCC hold on all tracks. A concerned citizen had reported potential track damage at MP 364.57. A Union Pacific track inspector was dispatched to the location. Once the area was inspected and deemed safe for travel, Train 2(03) was released to continue east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(03)	55"	

Train 8/28(04) East of Whitefish, MT - Freight Train Interference

05JUN26: At 5:49A, the BNSF reported one of their freights, X WHINGT2 04G, was disabled at Nyack/MP 1187.9, 32 miles east of Whitefish, MT, on the BNSF Hi Line Subdivision with main reservoir issues. Multiple freights were stopped in area with a few freight crews with hours of service issues. Train 8/28(04) held at MP 1215.9 until the disabled freight was able clear. Once on the move, Train 8/28(04) followed BN6929 until Browning, MT where they were able to operate around. Train 8/28(04) was further delayed at MP 1098.4 holding a freight at Cut Bank with a crew that expired on hours of service. Once freight was recrewed, Train 8/28(04) proceeded east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(04)	2'17"	WFH-BRO
8/28(04)	39"	Cut Bank

Train 19(04) South of Atlanta, GA - Freight Train Interference

05JUN26: Train 19(04) was held approximately 4.2 miles south of Atlanta, GA (MP 633.3), on the NSRR Atlanta North Subdivision at Bolton (MP 145.5) due to NS 152 being broken down ahead on the single main track. NS 152 was able to recover and clear the main line, allowing Train 19(04) to continue south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(04)	36"	

Train 23(05) North of New Orleans, LA - Freight Train Interference

05JUN26: Train 23(05) was held approximately 9.2 miles north of New Orleans, LA, on the CSX NO&M Subdivision at Industrial Canal (MP 801.5) while meeting UP 6058. Once the meet was completed, Train 23(05) advanced to Frenchmen Street (MP 6.8) on the NSRR New Orleans Terminal Subdivision in order to meet multiple additional freight trains.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
23(05)	35"	Industrial Canal
23(05)	24"	Frenchmen

Train 8/28(03) West of Detroit Lakes, MN - Freight Train Interference

05JUN26: Train 8/28(03) held 24.0 miles west of Detroit Lakes, MN (MP210.0), on the BNSF Staples Subdivision, at Hawley (MP234.4) in order to meet BNSF 7398.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(03)	31"	

Train 2(03) East of San Antonio, TX - Freight Train Interference

05JUN26: Train 2(03) was delayed starting 56 miles east of San Antonio, TX (MP209.5), on the UPRR Glidden Subdivision, from Luling (MP153.5) to MP124.3 following UP 7889.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(03)	30"	

Train 58(04) South of Kankakee, IL - Passenger Train Interference

05JUN26: Train 58(04) held 14.7 miles south of Kankakee, IL (MP55.9), on the CNRR Chicago Subdivision, at Ashkum (MP70.6) in order to meet Train 391(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(04)	39"	

Train 7/27(04) Shelby, MT - Freight Train Interference

05JUN26: Train 7/27(05), operating with engines 327/79, 10 coaches and 224 customers, was delayed 22 miles west of Shelby, MT, on BNSF Hi Line subdivision, due to a disabled grain train ahead of them. The disabled freight train had a locked axel. Once the freight resolved its locked axel and cleared, train 7/27(04) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(04)	1'29"	

Train 4(03) West of Dodge City, KS - Vehicle Strike

05JUN26: At 9:48AM-CT, Train 4(03), consisting of BN5427-E/142-E/78 with 9 cars, struck an occupied vehicle approximately 4.3 miles west of Dodge City, KS (MP 352.5) on the BNSF La Junta Subdivision. The collision occurred at a private road crossing located at MP 356.828 in Dodge City, Ford County (DOT #012883L), which was equipped with an ENS sign. Upon impact, the vehicle was forced off the tracks and came to rest in a ditch. The sole occupant was ejected from the vehicle and sustained injuries. Emergency medical services, local and state law enforcement, BNSF mechanical and a BNSF Track Inspector responded to the scene. No injuries were reported to the train crew or the 176 passengers onboard. The train maintained head-end power for the duration of the incident. Minor damage was reported to the plow on lead locomotive, BN5427. The crew agreed to proceed once released and planned to take trauma relief upon return to their home terminal. BNSF personnel responded and arrived on scene at approximately 11:00AM-CT. An Amtrak Road Foreman was en route with an estimated arrival of 1:30PM-CT; however, the train was released prior to their arrival. At 11:02AM-CT, Train 4(03) was released to continue east.

National Response Center Number: 1464411

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(03)	1'15"	

05JUN26: AT 7:15A-PT, 26-FOI-00526-00000007705 CC/C800231 UNCLASSIFIED 6/10/2026, with 34 customers on board stopped at MP 19, a mile north of Hayward, CA on the UPRR Niles Subdivision after HEP dropped. The crew contacted mechanical to troubleshoot. The outside temperature was 55 degrees and sunny. Amtrak Road foreman arrived on scene at 8:00A-PT and mechanical was on site at 8:30A-PT. Train 523(05) coupled to Train 524(05) to tow into Hayward for customers to detrain, arriving back into Hayward at 8:38A. BART provided mutual aid as well as UBER vouchers issued to customers at Hayward station. Train 523(05) uncoupled disabled equipment and departed Hayward at 8:50A-PT. Mechanical was able to resolve issue and the equipment deadheaded to Sacramento to be in place for Train 528(05), arriving at 12:04P-PT.

Train 537(05) was delayed departing Sacramento, CA due to the equipment swaps needed from the disabled Train 524(05). Train 526(05)'s equipment turned for Train 537(05) arriving at 10:56A-PT. Train 539(05) was, also, delayed departing Sacramento due to necessary equipment swaps. Once Train 528(05) arrived into Sacramento at 11:56A-PT, and the customers for Train 539(05) were boarded, Train 539(05) was able to depart Sacramento.

WBS#: B.TR.100150.6739

Train	Delay	Comment
524(05)	Term HAY	
523(05)	58"	Assist Disabled 524(05)
537(05)	15"	SAC
539(05)	14"	SAC

Train 821(05) South of Pauls Valley, OK - Freight Train Interference

05JUN26: Train 821(05) was delayed beginning 26.9 miles south of Pauls Valley, Oklahoma (MP 495.5) on the BNSF Red Rock Subdivision. The train held the main track at Dougherty (MP 468.6) to meet BNSF 6890. After completing that meet, Train 821(05) proceeded south to Gene Autry (MP 459.4) for a second meet with BNSF 7621 and BNSF 4415. These multiple meets were necessary due to an earlier disruption experienced by BNSF 6890, which impacted traffic flow on the single main line.

Train	Delay	Comment
821(05)	18"	Gene Autry
821(05)	14"	Dougherty

Train 22(05)/422(03) San Antonio, TX - Hold for Connection

05JUN26: Train 22(05)/422(03) was delayed departing San Antonio, TX (MP209.5), on the UPRR Del Rio Subdivision, as a result of a late 422(03) section arriving at 6:15AM-CT, 1 hour and 15 minutes late.

Train	Delay	Comment
22(05)/422(03)	49"	

Train 8/28(04) West of Libby, MT - Freight Train Interference

05JUN26: Train 8/28(04) held 35.9 miles west of Libby, MT (MP1319.6), on the BNSF Kootenai River Subdivision, at Katka (MP1355.5) in order to meet BNSF 6778, BNSF 6539, and Train 7/27(03).

Train	Delay	Comment
8/28(04)	05"	7/27(03)
8/28(04)	35"	Freight

Train 59(04) Memphis, TN - Freight Train Interference

05JUN26: Train 59(04) was delayed starting at MP 391.8, 42 miles west of Memphis, TN (MP 391.8) on the CNRR Memphis Subdivision while operating with a conductor only and performing numerous customer load and unload activities. After completing the work and becoming ready to depart, the train experienced additional delay due to signal issues at CN Jct (MP 392.5).

Train	Delay	Comment
59(04)	15"	Conductor only
59(04)	48"	Cn Jct

Train 4(03) West of La Junta, CO - Temporary Speed Restrictions

05JUN26: Train 4(03) was delayed starting at MP 596.5, 42 miles west of La Junta, CO, on the BNSF Raton Subdivision due to operating at reduced speed. The BNSF placed a temporary speed restriction starting at MP 596.5. The crew operating at restricted speed MP 596.5 to MP 595.5 and MP 582.7 to MP 581.9. Once through affected area, the crew was able to proceed at track speed.

Train	Delay	Comment
4(03)	32"	

Train 4(04) West of Kingman, AZ - Passenger Train Interference

05JUN26: Train 4(04) was delayed at MP 527.4, 11 miles west of Kingman, AZ, on the BNSF Seligman Subdivision due to meet with Train 3(03). Once route was clear, Train 4(04) proceeded east.

Train	Delay	Comment
4(03)	40"	

Train 4(04) Barstow, CA - Engine Failure

05JUN26: Train 4(04), E/62-E/14-9 Cars, reported losing time between Barstow, CA (MP 0.4) and Needles, CA (MP 578.0) on the BNSF Needles Subdivision. The Conductor stated that the lead locomotive, 62, was running hot and was unable to maintain track speed through the territory. After departing Needles, no further issues were reported.

Train	Delay	Comment
4(04)	30"	

Train 701(04) South of Lodi, CA - Signal

05JUN26: Train 701(04) was delayed approximately 3.7 miles south of Lodi, CA (MP 71.8) on the UPRR Fresno Subdivision while flagging through a track indication at Acampo (MP 68.1). Once the train cleared the affected area, track speed resumed.

Train	Delay	Comment
701(04)	31"	

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

26APR26: Canadian National has completed work on the Yazoo Subdivision between MP94 and MP126 starting on April 27th through May 29th. To accommodate this infrastructure work, Amtrak's City of New Orleans Service has been adjusted as follows:
24MAY26: Track work extended through June 19th, 2026.

-Train 1059 (26Apr) will operate in lieu of Train 59(26Apr), departing Chicago 2-hours Earlier, at 6:05pm, and will operate on an adjusted schedule between Chicago and New Orleans.

-Train 59(27Apr-18JUN) will depart Chicago 2-hours Earlier, at 6:05pm, and operate on an adjusted schedule between Chicago and New Orleans.

-Train 1058(27Apr) will operate in lieu of Train 58(27Apr), departing New Orleans 2-hours Earlier, at 11:45am, and will operate on an adjusted schedule between New Orleans and Chicago.

-Train 58(28Apr-19JUN) will depart New Orleans 2-hours Earlier, at 11:45am, and will operate on an adjusted schedule between New Orleans and Chicago.

WBS#: B.TR.100150.6608

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

09APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

WBS#: B.TR.100150.6620

Western Region

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
4 (3)	WLO	BNSF 5427	Alternator blower on E/142	Enroute	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00526

00000007705

"UNCLASSIFIED"

6/10/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
449 (05)	BOS	(4920) Viewliner I sleeper in lieu of Viewliner II sleeper.	0	0	62034
175 (05)	BOS	ADA special coach running live for 15 revenue seats due to the set operating 1-coach-short.	ADA special coach running live for 15 revenue seats	15	82651
449 (06)	BOS	**449(06)** WILL OPERATE WITHOUT A SLEEPER BETWEEN BOS-ALB. 62524 WILL BE ADDED IN ALB.	All passengers downgraded BOS-ALB	10	
5 (05)	CHI	Operating with snack coach in lieu of baggage coach a/c no good car on the yard.	No impact	0	35009
19 (04)	CVS	BYD electricity issues. Conductor states no one can ride in car as car is now deadhead. Over capacity	-55 high count passengers notified count dropping	-55	25058
562 (05)	LAX	Operating with 9700 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	Passenger notified	1	9700
580 (05)	LAX	Operating with 9700 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	Passengers notified	3	9700
562 (06)	LAX	NO BIKE SPACE	0	0	9700
580 (06)	LAX	NO BIKE SPACE- over capacity	-1	-1	9700
127 (06)	NYP	No Business Class due to no business class cars available. Replacement will be coach 82564	-26 high count	-26	NOCAR
573 (05)	SAN	Operating with 9700 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	Passenger notified	1	9700
591 (05)	SAN	Operating with 9700 in consist will not be able to accommodate	No impact	0	9700

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00526 00000007705 "UNCLASSIFIED"			
		passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.			
573 (06)	SAN	NO BIKE SPACE	0	0	9700
591 (06)	SAN	NO BIKE SERVICE- over capacity	-2	-2	9700
125 (05)	SPG	Please block 7D and 7F. These seats are missing.	Passengers moved to other seats	2	81546
170 (05)	WAS	Short one coach- over capacity. 82651 (nonrevenue) running deadhead rearmost	Resolved	0	82651

Reverse Consists

Train Number	Station	Reason
198 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front
93 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
183 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
113 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
130 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front
170 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front
136 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front
196 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front
119 (05)	NYP	Consist reversed Business class seat orientation may have changed At Rear
148 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front
193 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00526 00000007705 "UNCLASSIFIED"	6/10/2026
192 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
175 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front	
182 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
129 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front	
147 (06)	SPG	Consist reversed Business class seat orientation may have changed At Front.. ***train 147(06)	
143 (06)	SPG	Consist reversed Business class seat orientation may have changed At Front	