CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, November 06, 2026 Rules: 0-4



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00137 [illegible]

Initial Terminal Performance By Division

Scheduled Departure Date: **11/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/05/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	58	81.2%	1,519	219	85.6%	10,993	1,571	85.7%
Central Division	86.0%	59	6	89.8%	290	16	94.5%	2,060	141	93.2%
East Division	82.0%	159	28	82.4%	779	110	85.9%	5,778	848	85.3%
West Division	86.0%	91	24	73.6%	450	93	79.3%	3,155	582	81.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 11/5/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**76%**	**88,200**	**31,052**	**65%**	**460,211**	**145,487**	**68%**	**3,609,287**	**1,045,617**	**71%**
Northeast Corridor	***78%***	***40,689***	***12,157***	***70%***	***199,970***	***60,138***	***70%***	***1,554,973***	***384,778***	***75%***
Acela	80%	6,917	1,429	79%	30,176	9,192	70%	267,500	55,674	79%
Northeast Regional	78%	33,772	10,728	68%	169,794	50,946	70%	1,287,473	329,104	74%
Richmond / Newport News / Norfolk	75%	6,819	1,939	72%	40,040	12,266	69%	310,897	86,490	72%
Springfield Shuttles	89%	750	93	88%	3,584	360	90%	26,585	5,200	80%
Roanoke	75%	2,394	1,101	54%	14,070	5,191	63%	111,719	33,579	70%
On Spine Northeast Regional	80%	23,809	7,595	68%	112,100	33,129	70%	838,272	203,835	76%
State Supported	***80%***	***37,757***	***13,303***	***65%***	***204,867***	***57,970***	***72%***	***1,628,992***	***466,253***	***71%***
Borealis	80%	533	237	56%	2,966	729	75%	25,235	5,028	80%
Capitol Corridor	90%	3,903	466	88%	20,013	2,862	86%	148,696	27,626	81%
Carolinian	70%	1,110	775	30%	6,747	2,980	56%	47,365	16,627	65%
Cascades	75%	2,404	724	70%	12,780	4,108	68%	100,947	30,228	70%
Downeaster	82%	1,317	271	79%	6,508	1,630	75%	63,974	15,312	76%
Empire	78%	5,265	2,117	60%	27,697	6,019	78%	225,593	53,146	76%
Adirondack	72%	298	0	100%	1,521	10	99%	14,468	2,081	86%
Ethan Allen Express	70%	476	233	51%	2,480	1,117	55%	20,957	8,142	61%
Maple Leaf	70%	704	451	36%	3,711	1,519	59%	30,817	10,017	67%
New York - Albany	85%	2,653	743	72%	13,825	2,032	85%	109,438	19,716	82%
New York - Niagara Falls	75%	1,134	690	39%	6,160	1,341	78%	49,913	13,190	74%
Gold Runner	73%	1,773	511	71%	11,950	4,331	64%	92,499	35,043	62%
Heartland Flyer	70%	135	60	56%	731	585	20%	6,974	5,806	17%
Hiawatha	90%	1,261	518	59%	7,608	1,225	84%	65,978	6,985	89%
Illinois	78%	2,370	496	79%	12,369	1,678	86%	97,882	29,055	70%
Carl Sandburg / Illinois Zephyr	85%	286	42	85%	1,524	165	89%	15,049	3,676	76%
Illini / Saluki	85%	888	237	73%	4,689	479	90%	33,690	12,392	63%
Lincoln Service	70%	1,196	217	82%	6,156	1,034	83%	49,143	12,987	74%
Keystone	92%	6,021	1,749	71%	30,088	3,220	89%	243,019	24,906	90%
Lincoln / Missouri	70%	790	21	97%	3,971	2,090	47%	30,929	15,079	51%
Mardi Gras Service	80%	373	86	77%	1,518	203	87%	10,870	2,808	74%
Michigan	70%	1,713	278	84%	9,040	2,319	74%	75,123	19,184	74%
Blue Water	70%	175	13	93%	1,923	369	81%	19,050	5,200	73%
Pere Marquette	85%	272	112	59%	1,292	112	91%	10,591	735	93%
Wolverine	70%	1,266	153	88%	5,825	1,838	68%	45,482	13,249	71%
Missouri	80%	192	0	100%	1,044	316	70%	9,998	2,048	80%
Pacific Surfliner	85%	5,666	3,753	34%	32,916	19,861	40%	250,093	138,654	45%
Pennsylvanian	80%	915	1	100%	4,645	574	88%	33,848	9,824	71%
Piedmont	80%	617	236	62%	4,724	2,033	57%	44,130	14,080	68%
Vermonter	75%	1,399	1,004	28%	7,552	1,207	84%	55,839	14,814	73%
Long Distance	***58%***	***9,754***	***5,592***	***43%***	***55,374***	***27,379***	***51%***	***425,322***	***194,586***	***54%***
Auto Train	70%	678	678	0%	3,674	3,120	15%	24,632	18,559	25%
California Zephyr	70%	715	421	41%	4,040	2,054	49%	33,280	10,541	68%
Cardinal	70%	315	97	69%	1,145	340	70%	7,941	3,493	56%
City Of New Orleans	75%	610	317	48%	3,272	741	77%	26,620	17,039	36%
Coast Starlight	70%	483	473	2%	4,335	2,678	38%	38,398	21,385	44%
Crescent	70%	851	142	83%	4,594	854	81%	34,652	5,654	84%
Empire Builder	70%	828	291	65%	4,287	1,086	75%	36,518	13,097	64%
Floridian	60%	1,312	1,118	15%	7,973	6,101	23%	50,964	30,301	41%
Lake Shore Ltd	73%	825	40	95%	4,620	825	82%	37,461	11,135	70%
Palmetto	70%	432	105	76%	3,929	1,655	58%	27,682	7,758	72%
Silver Meteor	70%	910	628	31%	4,837	3,269	32%	37,577	13,644	64%
Southwest Chief	60%	694	666	4%	3,559	2,995	16%	27,431	21,420	22%
Sunset Ltd	70%	0	0	-	1,124	338	70%	10,010	4,595	54%
Texas Eagle	70%	1,101	616	44%	3,985	1,323	67%	32,156	15,965	50%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00187 00000000188 "UNCLASSIFIED" 11/18/2026~~

Train Index Dates Through November 05, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	29,547	508,052	582	217,457	3,597,635	604

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	957	133,628	72	10,507	1,005,345	105
INFRASTRUCTURE PLANNED	135	3,057	133,628	229	23,024	1,005,345	229
FLEET RELIABILITY	90	4,287	508,052	84	30,890	3,597,635	86
TRAIN OPERATIONS	424	21,246	508,052	418	153,036	3,597,635	425

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00137 [illegible]

Initial Terminal Performance By Division

Scheduled Departure Date: **11/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/05/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	58	81.2%	1,519	219	85.6%	10,993	1,571	85.7%
Central Division	86.0%	59	6	89.8%	290	16	94.5%	2,060	141	93.2%
East Division	82.0%	159	28	82.4%	779	110	85.9%	5,778	848	85.3%
West Division	86.0%	91	24	73.6%	450	93	79.3%	3,155	582	81.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

27-FOI-001

Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/05/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	58	81.2%	1,519	219	85.6%	10,993	1,571	85.7%
Central Division	86.0%	59	6	89.8%	290	16	94.5%	2,060	141	93.2%
CDL	95.0%	2	1	50.0%	10	1	90.0%	51	4	92.2%
CHI	86.0%	28	3	89.3%	135	9	93.3%	965	77	92.0%
CHM	-	-	-	-	-	-	-	20	3	85.0%
DAL	-	-	-	-	-	-	-	2	0	100.0%
DET	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	5	0	100.0%	33	2	93.9%
GRR	95.5%	1	0	100.0%	5	0	100.0%	36	0	100.0%
IND	-	-	-	-	-	-	-	4	0	100.0%
KCY	92.0%	2	0	100.0%	10	0	100.0%	73	1	98.6%
MKE	92.0%	6	2	66.7%	29	3	89.7%	210	15	92.9%
MOE	97.5%	2	0	100.0%	10	0	100.0%	65	0	100.0%
MSP	96.5%	1	0	100.0%	5	0	100.0%	36	0	100.0%
NOL	94.5%	4	0	100.0%	22	0	100.0%	148	6	95.9%
OKC	97.0%	1	0	100.0%	5	0	100.0%	35	2	94.3%
PNT	88.0%	3	0	100.0%	15	1	93.3%	95	13	86.3%
PTH	93.0%	1	0	100.0%	5	1	80.0%	36	2	94.4%
QCY	91.0%	2	0	100.0%	9	0	100.0%	71	4	94.4%
SAS	90.5%	1	0	100.0%	5	1	80.0%	35	7	80.0%
STL	89.0%	4	0	100.0%	20	0	100.0%	143	3	97.9%
TAY	-	-	-	-	-	-	-	1	1	0.0%
East Division	82.0%	159	28	82.4%	779	110	85.9%	5,778	848	85.3%
ALB	88.5%	8	1	87.5%	40	3	92.5%	285	23	91.9%
ALX	-	-	-	-	-	-	-	27	14	48.1%
ATL	-	-	-	-	-	-	-	14	4	71.4%
BON	87.5%	5	1	80.0%	25	4	84.0%	180	16	91.1%
BOS	85.5%	12	0	100.0%	55	6	89.1%	448	28	93.8%
BRK	92.5%	5	1	80.0%	25	2	92.0%	180	15	91.7%
BTN	82.0%	1	0	100.0%	5	0	100.0%	36	5	86.1%
CLT	91.5%	5	1	80.0%	25	2	92.0%	174	22	87.4%
GFD	88.0%	2	0	100.0%	10	1	90.0%	72	7	90.3%
GRO	-	1	0	100.0%	6	1	83.3%	17	1	94.1%
HAR	79.5%	13	4	69.2%	60	9	85.0%	415	48	88.4%
HFD	-	-	-	-	-	-	-	44	9	79.5%
JAX	-	-	-	-	-	-	-	18	2	88.9%
LOR	84.0%	1	1	0.0%	5	4	20.0%	34	16	52.9%
MET	-	-	-	-	-	-	-	1	1	0.0%
MIA	89.5%	2	0	100.0%	10	3	70.0%	71	11	84.5%
MTR	79.0%	1	0	100.0%	5	0	100.0%	36	9	75.0%
NFK	84.5%	2	0	100.0%	10	0	100.0%	61	10	83.6%
NFL	93.5%	2	0	100.0%	10	1	90.0%	72	6	91.7%
NFS	-	-	-	-	-	-	-	3	3	0.0%
NHV	78.0%	6	0	100.0%	30	3	90.0%	187	36	80.7%
NPN	93.0%	2	0	100.0%	10	1	90.0%	50	5	90.0%

Information Management

Initial Terminal Performance By Terminal

27-FOI-0013 [illegible]

Scheduled Departure Date: **11/05/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/05/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	58	81.2%	1,519	219	85.6%	10,993	1,571	85.7%
East Division	82.0%	159	28	82.4%	779	110	85.9%	5,778	848	85.3%
NYP	75.5%	39	6	84.6%	198	26	86.9%	1,496	244	83.7%
PGH	93.0%	1	0	100.0%	5	0	100.0%	44	10	77.3%
PHL	48.0%	11	7	36.4%	50	27	46.0%	298	143	52.0%
RGH	95.0%	3	1	66.7%	14	2	85.7%	140	23	83.6%
RNK	83.5%	2	1	50.0%	10	2	80.0%	61	8	86.9%
SAB	98.0%	1	0	100.0%	5	0	100.0%	36	0	100.0%
SAV	96.0%	1	0	100.0%	5	0	100.0%	25	0	100.0%
SFA	88.0%	1	1	0.0%	5	4	20.0%	34	9	73.5%
SPG	92.5%	7	0	100.0%	35	0	100.0%	203	10	95.1%
TWO	73.0%	1	1	0.0%	5	1	80.0%	33	9	72.7%
WAS	84.0%	24	2	91.7%	116	8	93.1%	983	101	89.7%
West Division	86.0%	91	24	73.6%	450	93	79.3%	3,155	582	81.6%
ARN	92.0%	1	0	100.0%	5	0	100.0%	36	3	91.7%
BFD	79.0%	7	1	85.7%	35	11	68.6%	244	63	74.2%
EMY	72.0%	1	0	100.0%	5	1	80.0%	40	16	60.0%
EUG	86.5%	2	0	100.0%	10	0	100.0%	69	3	95.7%
FNO	-	-	-	-	-	-	-	5	4	20.0%
GAC	-	-	-	-	-	-	-	3	2	33.3%
GTA	90.0%	6	3	50.0%	30	10	66.7%	161	65	59.6%
IRV	-	-	-	-	-	-	-	1	0	100.0%
LAX	89.5%	10	2	80.0%	51	12	76.5%	351	46	86.9%
OKJ	74.5%	13	6	53.8%	61	18	70.5%	424	133	68.6%
PDX	86.0%	5	1	80.0%	24	3	87.5%	179	16	91.1%
SAC	88.5%	16	3	81.3%	76	7	90.8%	532	51	90.4%
SAN	90.5%	12	6	50.0%	63	22	65.1%	422	97	77.0%
SEA	85.0%	8	1	87.5%	40	4	90.0%	287	33	88.5%
SJC	89.0%	7	1	85.7%	35	5	85.7%	251	40	84.1%
SLO	90.0%	-	-	-	-	-	-	42	8	81.0%
SPK	90.0%	1	0	100.0%	5	0	100.0%	35	0	100.0%
VAC	97.0%	2	0	100.0%	10	0	100.0%	68	1	98.5%
VNC	-	-	-	-	-	-	-	5	1	80.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	249	4	1	75.0%	33	7	78.8%	5	5	0.0%	32	24	25.0%
4	280	4	2	50.0%	32	5	84.4%	5	5	0.0%	32	28	12.5%
5		5	0	100.0%	35	2	94.3%	5	2	60.0%	35	10	71.4%
6	108	5	1	80.0%	35	14	60.0%	5	4	20.0%	35	13	62.9%
7		5	1	80.0%	35	3	91.4%	5	0	100.0%	35	2	94.3%
8	76	5	0	100.0%	35	7	80.0%	5	2	60.0%	35	18	48.6%
11	No OS	5	1	80.0%	36	5	86.1%	4	4	0.0%	35	24	31.4%
14	44	5	1	80.0%	36	10	72.2%	5	4	20.0%	36	23	36.1%
19		5	2	60.0%	36	8	77.8%	5	2	60.0%	35	8	77.1%
20		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	4	88.9%
21		5	0	100.0%	36	2	94.4%	5	1	80.0%	35	14	60.0%
22	19	5	1	80.0%	36	8	77.8%	5	2	60.0%	36	20	44.4%
23		5	0	100.0%	33	0	100.0%	5	0	100.0%	33	6	81.8%
24	40	5	0	100.0%	32	0	100.0%	5	1	80.0%	32	7	78.1%
25		5	0	100.0%	32	0	100.0%	5	0	100.0%	32	7	78.1%
26		5	0	100.0%	33	0	100.0%	5	1	80.0%	33	9	72.7%
27	37	5	2	60.0%	35	2	94.3%	4	1	75.0%	34	7	79.4%
40	81	5	2	60.0%	36	12	66.7%	5	5	0.0%	36	19	47.2%
41	253	5	2	60.0%	36	5	86.1%	5	5	0.0%	36	20	44.4%
42		5	0	100.0%	36	3	91.7%	5	1	80.0%	36	12	66.7%
43		5	1	80.0%	36	9	75.0%	5	1	80.0%	35	13	62.9%
48		5	0	100.0%	36	4	88.9%	5	1	80.0%	36	13	63.9%
49		5	0	100.0%	36	5	86.1%	5	1	80.0%	36	7	80.6%
51		2	1	50.0%	15	4	73.3%	2	0	100.0%	16	5	68.8%
52	72	5	4	20.0%	34	9	73.5%	5	3	40.0%	34	19	44.1%
53	354	5	4	20.0%	34	16	52.9%	5	5	0.0%	34	30	11.8%
55	22	4	0	100.0%	26	0	100.0%	4	1	75.0%	26	6	76.9%
56	20	4	0	100.0%	26	3	88.5%	4	2	50.0%	26	6	76.9%
58		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	27	25.0%
59	100	5	0	100.0%	36	2	94.4%	5	1	80.0%	36	23	36.1%
63	36	5	1	80.0%	36	13	63.9%	5	5	0.0%	36	33	8.3%
64	23	5	1	80.0%	36	12	66.7%	5	4	20.0%	36	20	44.4%
66	18	5	1	80.0%	35	5	85.7%	5	2	60.0%	35	7	80.0%
67		5	1	80.0%	25	5	80.0%	4	0	100.0%	25	5	80.0%
68		5	0	100.0%	36	9	75.0%	5	0	100.0%	36	7	80.6%
69		5	0	100.0%	36	10	72.2%	5	0	100.0%	36	2	94.4%
71	No OS	5	0	100.0%	36	2	94.4%	5	4	20.0%	36	10	72.2%
72	65	5	2	60.0%	36	7	80.6%	5	3	40.0%	36	6	83.3%
73	71	5	1	80.0%	31	5	83.9%	5	3	40.0%	31	16	48.4%
74		5	0	100.0%	31	6	80.6%	5	2	60.0%	31	15	51.6%
75		5	1	80.0%	36	3	91.7%	5	1	80.0%	34	8	76.5%
76	65	5	0	100.0%	35	5	85.7%	5	3	40.0%	34	15	55.9%

Amtrak On Time Performance

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		5	1	80.0%	36	5	86.1%	5	2	60.0%	36	14	61.1%
78		5	0	100.0%	36	4	88.9%	5	2	60.0%	37	9	75.7%
79	43	5	0	100.0%	36	6	83.3%	5	4	20.0%	36	16	55.6%
80	196	5	0	100.0%	36	0	100.0%	5	3	40.0%	36	11	69.4%
89		5	0	100.0%	25	1	96.0%	5	4	20.0%	25	14	44.0%
90	No OS	5	0	100.0%	25	0	100.0%	5	4	20.0%	25	11	56.0%
94		5	0	100.0%	25	4	84.0%	5	2	60.0%	25	5	80.0%
97	19	5	2	60.0%	36	12	66.7%	5	5	0.0%	36	10	72.2%
98		5	1	80.0%	36	4	88.9%	5	2	60.0%	36	14	61.1%
230		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	1	97.2%
232	48	5	0	100.0%	36	1	97.2%	5	1	80.0%	36	3	91.7%
233	18	5	0	100.0%	36	12	66.7%	5	2	60.0%	36	14	61.1%
234		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	1	97.2%
235		5	1	80.0%	36	5	86.1%	5	2	60.0%	36	11	69.4%
236		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	6	83.3%
237		5	1	80.0%	36	5	86.1%	5	0	100.0%	36	10	72.2%
238		5	2	60.0%	36	6	83.3%	5	1	80.0%	36	4	88.9%
239		5	1	80.0%	35	6	82.9%	5	1	80.0%	35	3	91.4%
240		5	0	100.0%	36	4	88.9%	4	0	100.0%	35	2	94.3%
241	30	5	0	100.0%	36	6	83.3%	5	1	80.0%	36	9	75.0%
243		5	0	100.0%	36	5	86.1%	5	0	100.0%	36	1	97.2%
244	72	5	0	100.0%	36	0	100.0%	5	1	80.0%	36	11	69.4%
245		5	0	100.0%	36	5	86.1%	5	0	100.0%	36	5	86.1%
280	52	5	0	100.0%	36	3	91.7%	5	1	80.0%	36	13	63.9%
281	54	5	0	100.0%	36	5	86.1%	5	3	40.0%	36	6	83.3%
283	18	5	1	80.0%	36	2	94.4%	5	2	60.0%	36	6	83.3%
284	21	5	1	80.0%	36	3	91.7%	5	1	80.0%	36	4	88.9%
290	27	5	0	100.0%	36	5	86.1%	5	4	20.0%	35	16	54.3%
291		5	0	100.0%	36	17	52.8%	5	1	80.0%	36	8	77.8%
300		5	0	100.0%	35	1	97.1%	5	0	100.0%	35	7	80.0%
301		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	4	88.9%
302		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	9	75.0%
305	16	5	0	100.0%	36	1	97.2%	5	2	60.0%	36	14	61.1%
306		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	10	72.2%
307		5	0	100.0%	36	1	97.2%	5	2	60.0%	36	12	66.7%
311		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	4	88.9%
316		5	0	100.0%	36	0	100.0%	5	2	60.0%	36	11	69.4%
318		5	0	100.0%	36	1	97.2%	5	4	20.0%	36	16	55.6%
319		5	0	100.0%	36	0	100.0%	5	3	40.0%	35	26	25.7%
329		4	0	100.0%	26	1	96.2%	4	0	100.0%	26	1	96.2%
330		4	0	100.0%	31	0	100.0%	4	0	100.0%	30	1	96.7%
331		5	0	100.0%	36	2	94.4%	5	0	100.0%	34	1	97.1%

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		5	0	100.0%	36	3	91.7%	5	1	80.0%	36	2	94.4%
334		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	1	97.2%
335	Cncld	5	0	100.0%	36	6	83.3%	4	0	100.0%	35	3	91.4%
336	172	5	0	100.0%	35	0	100.0%	5	3	40.0%	35	4	88.6%
337	180	5	2	60.0%	35	3	91.4%	5	2	60.0%	35	3	91.4%
338	47	5	2	60.0%	36	6	83.3%	5	2	60.0%	36	11	69.4%
339	54	5	1	80.0%	36	9	75.0%	5	1	80.0%	35	7	80.0%
341		5	0	100.0%	35	5	85.7%	5	0	100.0%	35	2	94.3%
342	22	5	1	80.0%	36	5	86.1%	5	1	80.0%	35	4	88.6%
350		5	0	100.0%	33	2	93.9%	5	1	80.0%	31	13	58.1%
351		5	0	100.0%	31	4	87.1%	5	2	60.0%	29	7	75.9%
352	19	5	1	80.0%	32	5	84.4%	5	3	40.0%	31	13	58.1%
353		5	0	100.0%	33	4	87.9%	5	1	80.0%	32	5	84.4%
354		5	0	100.0%	33	6	81.8%	5	0	100.0%	32	11	65.6%
355		5	1	80.0%	32	6	81.3%	5	1	80.0%	31	9	71.0%
364	22	5	0	100.0%	36	1	97.2%	5	1	80.0%	36	9	75.0%
365	No OS	5	1	80.0%	36	2	94.4%	5	3	40.0%	36	14	61.1%
370		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	4	88.9%
371	43	5	0	100.0%	36	0	100.0%	5	1	80.0%	36	1	97.2%
380		4	0	100.0%	35	2	94.3%	4	0	100.0%	35	10	71.4%
381	26	5	0	100.0%	36	0	100.0%	5	1	80.0%	36	8	77.8%
382		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	7	80.6%
383		5	0	100.0%	36	0	100.0%	4	2	50.0%	35	14	60.0%
390	40	5	1	80.0%	35	6	82.9%	5	1	80.0%	35	10	71.4%
391		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	6	83.3%
392		5	0	100.0%	36	1	97.2%	5	1	80.0%	36	24	33.3%
393		5	0	100.0%	35	4	88.6%	5	0	100.0%	35	18	48.6%
417		4	0	100.0%	26	5	80.8%	4	0	100.0%	25	6	76.0%
425		4	0	100.0%	26	0	100.0%	4	0	100.0%	26	3	88.5%
448		4	1	75.0%	32	11	65.6%	5	1	80.0%	33	10	69.7%
449		5	0	100.0%	33	1	97.0%	5	2	60.0%	33	6	81.8%
470	38	4	0	100.0%	26	3	88.5%	4	1	75.0%	26	9	65.4%
471		4	0	100.0%	26	7	73.1%	4	0	100.0%	26	7	73.1%
473		4	0	100.0%	26	2	92.3%	4	0	100.0%	26	0	100.0%
474		4	0	100.0%	26	7	73.1%	4	0	100.0%	25	8	68.0%
475		4	0	100.0%	26	0	100.0%	4	0	100.0%	26	2	92.3%
478		4	1	75.0%	26	3	88.5%	4	1	75.0%	26	2	92.3%
479		4	1	75.0%	26	4	84.6%	4	1	75.0%	25	9	64.0%
486		4	0	100.0%	26	3	88.5%	4	1	75.0%	25	4	84.0%
490	34	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
494		4	0	100.0%	27	3	88.9%	4	1	75.0%	26	6	76.9%
495		4	0	100.0%	26	0	100.0%	4	0	100.0%	26	1	96.2%

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
500		5	0	100.0%	36	2	94.4%	5	3	40.0%	36	8	77.8%
502	39	5	0	100.0%	36	1	97.2%	5	2	60.0%	36	8	77.8%
503		5	0	100.0%	36	7	80.6%	5	1	80.0%	36	15	58.3%
504		5	0	100.0%	34	1	97.1%	5	2	60.0%	34	15	55.9%
505		5	1	80.0%	36	2	94.4%	5	3	40.0%	36	9	75.0%
506		5	1	80.0%	36	3	91.7%	5	1	80.0%	35	7	80.0%
507		5	2	60.0%	36	5	86.1%	5	2	60.0%	34	13	61.8%
508		5	0	100.0%	36	3	91.7%	5	0	100.0%	36	12	66.7%
509		5	0	100.0%	36	1	97.2%	5	4	20.0%	36	18	50.0%
511		5	0	100.0%	36	1	97.2%	5	0	100.0%	36	4	88.9%
516	77	5	0	100.0%	34	4	88.2%	5	2	60.0%	33	18	45.5%
517	16	5	0	100.0%	36	2	94.4%	5	2	60.0%	36	15	58.3%
518	18	5	2	60.0%	36	5	86.1%	5	4	20.0%	35	18	48.6%
519		5	0	100.0%	34	0	100.0%	5	1	80.0%	34	6	82.4%
520	18	4	0	100.0%	26	0	100.0%	4	1	75.0%	26	1	96.2%
521		4	0	100.0%	26	1	96.2%	4	1	75.0%	24	5	79.2%
522	Cncld	4	2	50.0%	26	9	65.4%	3	1	66.7%	25	4	84.0%
523	32	4	0	100.0%	26	4	84.6%	4	2	50.0%	25	8	68.0%
524		4	0	100.0%	26	3	88.5%	4	1	75.0%	25	5	80.0%
525		4	0	100.0%	26	3	88.5%	4	0	100.0%	24	2	91.7%
526		4	2	50.0%	26	9	65.4%	4	0	100.0%	24	2	91.7%
527		4	0	100.0%	26	1	96.2%	4	1	75.0%	26	7	73.1%
528		4	0	100.0%	26	3	88.5%	4	0	100.0%	26	8	69.2%
529		4	0	100.0%	26	2	92.3%	4	0	100.0%	26	10	61.5%
530		4	1	75.0%	26	5	80.8%	4	1	75.0%	26	6	76.9%
531		4	0	100.0%	26	1	96.2%	4	0	100.0%	25	2	92.0%
532		4	0	100.0%	26	9	65.4%	4	0	100.0%	25	1	96.0%
534		4	1	75.0%	26	5	80.8%	4	0	100.0%	26	0	100.0%
535		4	0	100.0%	26	0	100.0%	4	0	100.0%	25	2	92.0%
536		4	0	100.0%	26	9	65.4%	4	0	100.0%	26	1	96.2%
537	Cncld	4	1	75.0%	25	2	92.0%	3	0	100.0%	23	1	95.7%
538		4	0	100.0%	26	2	92.3%	4	1	75.0%	26	2	92.3%
539	36	4	1	75.0%	26	6	76.9%	4	1	75.0%	26	9	65.4%
540		4	0	100.0%	25	3	88.0%	4	1	75.0%	24	1	95.8%
541		4	1	75.0%	26	4	84.6%	4	0	100.0%	26	4	84.6%
542		4	2	50.0%	26	6	76.9%	4	0	100.0%	25	2	92.0%
543		4	1	75.0%	26	5	80.8%	4	3	25.0%	26	13	50.0%
544		4	0	100.0%	26	6	76.9%	4	0	100.0%	26	6	76.9%
545		4	0	100.0%	25	0	100.0%	4	0	100.0%	24	0	100.0%
547		4	0	100.0%	26	2	92.3%	4	1	75.0%	26	6	76.9%
548		4	0	100.0%	26	1	96.2%	4	0	100.0%	26	1	96.2%
549		4	1	75.0%	26	4	84.6%	4	2	50.0%	25	5	80.0%

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
550		4	2	50.0%	26	5	80.8%	4	1	75.0%	26	5	80.8%
551		4	0	100.0%	26	2	92.3%	4	0	100.0%	26	4	84.6%
562	38	5	1	80.0%	34	3	91.2%	5	5	0.0%	34	21	38.2%
564		5	0	100.0%	34	0	100.0%	5	4	20.0%	34	21	38.2%
566	74	5	2	60.0%	34	3	91.2%	4	4	0.0%	31	18	41.9%
572	63	5	2	60.0%	31	9	71.0%	4	4	0.0%	28	20	28.6%
573	32	5	2	60.0%	34	5	85.3%	5	4	20.0%	33	16	51.5%
579	52	5	3	40.0%	31	5	83.9%	3	3	0.0%	28	18	35.7%
580		5	1	80.0%	34	3	91.2%	5	3	40.0%	33	15	54.5%
581	24	5	3	40.0%	34	15	55.9%	5	3	40.0%	32	23	28.1%
584	60	5	1	80.0%	34	4	88.2%	5	5	0.0%	32	26	18.8%
587	43	5	1	80.0%	33	7	78.8%	5	4	20.0%	31	20	35.5%
588		5	1	80.0%	31	5	83.9%	4	2	50.0%	28	16	42.9%
591		5	0	100.0%	34	5	85.3%	5	1	80.0%	34	20	41.2%
593		4	3	25.0%	27	12	55.6%	4	2	50.0%	24	10	58.3%
595	43	5	5	0.0%	30	18	40.0%	5	5	0.0%	30	23	23.3%
600	68	5	0	100.0%	34	1	97.1%	5	1	80.0%	34	5	85.3%
601		4	3	25.0%	26	12	53.8%	4	0	100.0%	26	4	84.6%
605		4	2	50.0%	26	12	53.8%	4	0	100.0%	25	1	96.0%
607		5	0	100.0%	34	2	94.1%	5	0	100.0%	34	1	97.1%
609		4	1	75.0%	26	3	88.5%	4	0	100.0%	25	0	100.0%
622		4	1	75.0%	24	3	87.5%	4	1	75.0%	24	2	91.7%
626		5	2	60.0%	34	7	79.4%	5	0	100.0%	34	5	85.3%
640		4	0	100.0%	26	1	96.2%	4	0	100.0%	26	4	84.6%
641	91	4	1	75.0%	26	5	80.8%	4	1	75.0%	26	3	88.5%
642		4	0	100.0%	26	1	96.2%	4	0	100.0%	26	2	92.3%
643		5	2	60.0%	34	10	70.6%	5	0	100.0%	34	3	91.2%
644		4	1	75.0%	26	3	88.5%	4	0	100.0%	26	7	73.1%
645		5	3	40.0%	34	12	64.7%	5	0	100.0%	33	4	87.9%
646		4	0	100.0%	26	6	76.9%	4	1	75.0%	26	3	88.5%
647		5	0	100.0%	33	4	87.9%	5	0	100.0%	32	1	96.9%
648		4	1	75.0%	26	1	96.2%	4	0	100.0%	26	1	96.2%
649		5	0	100.0%	34	2	94.1%	5	1	80.0%	34	5	85.3%
650		5	1	80.0%	34	5	85.3%	5	1	80.0%	34	3	91.2%
651	27	4	1	75.0%	26	1	96.2%	4	2	50.0%	26	6	76.9%
652		5	0	100.0%	34	3	91.2%	5	0	100.0%	34	2	94.1%
653	22	4	4	0.0%	25	11	56.0%	4	1	75.0%	25	4	84.0%
654		4	0	100.0%	25	5	80.0%	4	0	100.0%	25	3	88.0%
655		5	1	80.0%	34	4	88.2%	5	0	100.0%	34	2	94.1%
656		5	2	60.0%	34	7	79.4%	5	0	100.0%	34	5	85.3%
657	73	4	2	50.0%	26	10	61.5%	4	1	75.0%	26	2	92.3%
658		5	1	80.0%	33	2	93.9%	5	0	100.0%	33	1	97.0%

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680		4	0	100.0%	26	4	84.6%	4	0	100.0%	26	2	92.3%
681		4	0	100.0%	26	0	100.0%	4	2	50.0%	25	12	52.0%
682		4	1	75.0%	26	4	84.6%	4	0	100.0%	26	4	84.6%
683		4	0	100.0%	26	0	100.0%	4	2	50.0%	26	18	30.8%
684		4	0	100.0%	26	2	92.3%	4	0	100.0%	26	9	65.4%
685		4	1	75.0%	26	4	84.6%	4	2	50.0%	26	9	65.4%
686	76	4	0	100.0%	26	1	96.2%	4	2	50.0%	26	11	57.7%
687	71	4	2	50.0%	26	7	73.1%	4	3	25.0%	26	11	57.7%
688		4	0	100.0%	26	1	96.2%	4	1	75.0%	26	7	73.1%
701		5	2	60.0%	36	6	83.3%	5	2	60.0%	36	9	75.0%
702		5	0	100.0%	36	2	94.4%	5	1	80.0%	36	15	58.3%
703	84	5	2	60.0%	36	12	66.7%	5	3	40.0%	36	9	75.0%
704		5	2	60.0%	36	8	77.8%	5	1	80.0%	36	5	86.1%
710		5	2	60.0%	36	8	77.8%	5	1	80.0%	36	8	77.8%
711		5	0	100.0%	36	6	83.3%	5	1	80.0%	31	5	83.9%
712	59	5	2	60.0%	36	12	66.7%	5	4	20.0%	36	17	52.8%
713		5	2	60.0%	33	12	63.6%	5	1	80.0%	28	7	75.0%
714	34	5	4	20.0%	36	21	41.7%	5	4	20.0%	35	20	42.9%
715		5	0	100.0%	36	6	83.3%	4	2	50.0%	34	17	50.0%
716	75	5	1	80.0%	35	16	54.3%	5	2	60.0%	34	9	73.5%
717		5	2	60.0%	36	16	55.6%	5	3	40.0%	33	15	54.5%
718		5	4	20.0%	36	24	33.3%	5	2	60.0%	36	14	61.1%
719		5	3	40.0%	36	9	75.0%	5	1	80.0%	36	8	77.8%
757		5	0	100.0%	33	2	93.9%	5	0	100.0%	33	14	57.6%
761		5	0	100.0%	34	0	100.0%	5	0	100.0%	34	11	67.6%
765	140	5	0	100.0%	34	0	100.0%	5	3	40.0%	34	22	35.3%
769	95	5	0	100.0%	34	2	94.1%	5	5	0.0%	34	26	23.5%
770	39	5	0	100.0%	34	3	91.2%	5	5	0.0%	33	24	27.3%
774	61	5	3	40.0%	34	16	52.9%	5	4	20.0%	33	28	15.2%
777	62	5	2	60.0%	34	4	88.2%	5	4	20.0%	33	24	27.3%
782		5	2	60.0%	34	23	32.4%	5	4	20.0%	33	24	27.3%
785	40	5	3	40.0%	34	20	41.2%	5	2	60.0%	34	20	41.2%
786	16	5	1	80.0%	34	10	70.6%	5	3	40.0%	29	17	41.4%
790	23	5	0	100.0%	34	2	94.1%	5	4	20.0%	34	22	35.3%
794	102	5	4	20.0%	34	18	47.1%	5	4	20.0%	34	19	44.1%
821		5	0	100.0%	35	2	94.3%	5	4	20.0%	35	28	20.0%
822	21	5	0	100.0%	35	2	94.3%	5	4	20.0%	35	29	17.1%
1082		4	0	100.0%	19	2	89.5%	4	2	50.0%	19	5	73.7%
1087		4	0	100.0%	19	1	94.7%	4	1	75.0%	18	2	88.9%
1088	24	4	0	100.0%	19	2	89.5%	4	3	25.0%	19	6	68.4%
1099		4	0	100.0%	19	0	100.0%	4	2	50.0%	19	7	63.2%
1103		4	2	50.0%	19	10	47.4%	4	1	75.0%	19	4	78.9%

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1107		4	3	25.0%	19	8	57.9%	3	0	100.0%	18	3	83.3%
1109		4	0	100.0%	19	1	94.7%	4	0	100.0%	19	1	94.7%
1111		4	0	100.0%	19	2	89.5%	4	1	75.0%	19	1	94.7%
1116		4	1	75.0%	19	3	84.2%	3	1	66.7%	18	2	88.9%
1118		4	0	100.0%	19	2	89.5%	4	1	75.0%	19	1	94.7%
1124		4	0	100.0%	17	2	88.2%	4	0	100.0%	17	5	70.6%
1126		4	1	75.0%	19	1	94.7%	4	0	100.0%	19	4	78.9%
1127		4	1	75.0%	19	4	78.9%	4	0	100.0%	19	1	94.7%
1128		4	0	100.0%	19	2	89.5%	3	1	66.7%	18	2	88.9%
1129		4	0	100.0%	19	1	94.7%	4	0	100.0%	19	3	84.2%
1135	78	4	1	75.0%	19	3	84.2%	4	2	50.0%	19	14	26.3%
1138		4	0	100.0%	18	2	88.9%	4	0	100.0%	18	3	83.3%
1140		4	1	75.0%	19	5	73.7%	4	2	50.0%	19	3	84.2%
1142		4	1	75.0%	19	5	73.7%	4	0	100.0%	19	4	78.9%
1143		4	0	100.0%	19	0	100.0%	4	2	50.0%	19	7	63.2%
1144		4	4	0.0%	19	16	15.8%	4	1	75.0%	19	5	73.7%
1146	22	4	1	75.0%	19	4	78.9%	4	2	50.0%	19	3	84.2%
1147		4	0	100.0%	19	0	100.0%	4	2	50.0%	19	6	68.4%
1150	21	4	3	25.0%	19	13	31.6%	4	3	25.0%	19	5	73.7%
1151		4	2	50.0%	19	7	63.2%	4	2	50.0%	19	10	47.4%
1152		4	0	100.0%	19	2	89.5%	4	1	75.0%	19	4	78.9%
1153		4	0	100.0%	19	0	100.0%	4	1	75.0%	19	1	94.7%
1155		4	0	100.0%	18	2	88.9%	4	0	100.0%	18	5	72.2%
1156	27	4	1	75.0%	16	3	81.3%	4	3	25.0%	16	12	25.0%
1160	31	4	1	75.0%	19	1	94.7%	4	3	25.0%	19	10	47.4%
1161		4	0	100.0%	19	0	100.0%	4	3	25.0%	19	14	26.3%
1162	33	4	0	100.0%	19	0	100.0%	4	4	0.0%	19	12	36.8%
1163	174	4	0	100.0%	19	1	94.7%	4	3	25.0%	19	14	26.3%
1164	26	4	1	75.0%	18	2	88.9%	4	3	25.0%	18	8	55.6%
1165	46	4	1	75.0%	19	1	94.7%	4	2	50.0%	19	9	52.6%
1167	74	4	2	50.0%	19	6	68.4%	4	3	25.0%	19	8	57.9%
1168		4	0	100.0%	19	4	78.9%	4	0	100.0%	19	4	78.9%
1169	21	4	1	75.0%	18	4	77.8%	3	2	33.3%	17	4	76.5%
1194	58	4	1	75.0%	19	3	84.2%	4	2	50.0%	19	4	78.9%
1195		4	0	100.0%	18	0	100.0%	4	0	100.0%	17	1	94.1%
1333	167	5	1	80.0%	36	4	88.9%	5	3	40.0%	36	13	63.9%
1340		5	0	100.0%	36	0	100.0%	5	0	100.0%	36	4	88.9%
1697		2	0	100.0%	7	0	100.0%	2	0	100.0%	7	2	71.4%
2101		4	0	100.0%	19	1	94.7%	4	0	100.0%	19	1	94.7%
2103		4	0	100.0%	26	1	96.2%	4	0	100.0%	26	2	92.3%
2105		4	1	75.0%	26	2	92.3%	4	2	50.0%	26	3	88.5%
2106		4	0	100.0%	19	0	100.0%	4	1	75.0%	19	3	84.2%

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2114		4	0	100.0%	19	3	84.2%	4	1	75.0%	19	4	78.9%
2115		4	0	100.0%	26	0	100.0%	4	1	75.0%	25	4	84.0%
2116		4	0	100.0%	26	2	92.3%	4	2	50.0%	26	2	92.3%
2118		4	0	100.0%	26	3	88.5%	4	2	50.0%	25	6	76.0%
2120		4	0	100.0%	26	3	88.5%	4	0	100.0%	26	3	88.5%
2122		4	1	75.0%	19	3	84.2%	4	1	75.0%	19	3	84.2%
2123		4	1	75.0%	26	3	88.5%	4	2	50.0%	26	4	84.6%
2133		4	0	100.0%	19	0	100.0%	4	1	75.0%	19	3	84.2%
2148	31	4	0	100.0%	19	1	94.7%	4	1	75.0%	18	3	83.3%
2149	45	4	0	100.0%	19	2	89.5%	4	4	0.0%	19	18	5.3%
2150	36	4	0	100.0%	26	0	100.0%	4	4	0.0%	25	15	40.0%
2151	22	4	0	100.0%	26	0	100.0%	4	3	25.0%	26	16	38.5%
2152		4	0	100.0%	26	1	96.2%	4	1	75.0%	26	3	88.5%
2155		4	1	75.0%	26	2	92.3%	4	1	75.0%	25	3	88.0%

Amtrak Endpoint OTP Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2148	BOS	31	DCS	25	ADA	14	NYP-NYP	AM	Mobility Impaired, HELD IN STATION A/C ADA PSNGR BEING MOVED TO ANOTHER CAR
2149	WAS	45	SMW	20	DMW	13	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2150	BOS	36	DCS	36	DCS	16	WIL-PHL	AM	T.O.L, Control Point, HOLLY, 2 TRK
2151	WAS	22	OTH	17	CTI	12	NHV-STM	MN	Follow MN, Milepost, 39, 34
66	BOS	18	CTI	21	DET	13	NWK-NWK	AM	Catenary maintenance , Other, E.DOCK-HUDSON, POWER LOSS E.DOCK-HUDSON
470	SPG	38	CON	28	CON	28	NHV-NHV	AM	Hold for connecting train
490	SPG	34	SYS	21	SYS	18	WND-WNL	AM	Copy authority / restriction, Copy form D for Dexter & Bridge St.
1088	BOS	24	DMW	24	DMW	24	NLC-XGX	AM	Held for or routed around MW work or equipment, Milepost w/Letters, NLC, XGX, AM1088 held to allow AM1167 to cross over trk 2 - 1 to run around OOS trk 1
1135	WAS	78	CTI	31	DMW	21	KIN-XGX	AM	Held for or routed around MW work or equipment, Control Point, XHI, AM1135 held at High St, waited for AM2150 to clear trk 1 OOS Mystic River - High St
1146	SPG	22	WTR	25	WTR	9	STM-NHV	MN	Wet / slippery rail Other, enroute
1150	BOS	21	DSR	14	PSR	14	KIN-PVD	AM	Post MW Work, Milepost, kin, x7t, 10 MPH S/R at Davisville
1156	NYP	27	DCS	47	DCS	36	RNK-LYH	NS	PTC- I-ETMS Red Fence/Signal Status Unknown Milepost, 215.5, 215.5
1160	BOS	31	WTR	14	DMW	10	WLY-PVD	AM	Hold for defect repair, Other, DAVISVILLE , 10 MPH /S/R
1162	BOS	33	SMW	13	SMW	13	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING ON NO.2 TRK LEGGETT TO PELHAM BAY A/C 1 TRK OOS MANOR TO LEGGETT
1163	WAS	174	POL	78	POL	41	WIL-XPV	AM	Right of Way police hold, hold on all tracks MP 60
1164	BOS	26	CTI	36	DCS	17	NBK-NWK	AM	Power switch failure, Other, UNION, HELD AT ROADS A/C 12SW AT UNION 2TRK, FAILING TO NORMAL
1165	WAS	46	CTI	24	CTI	15	NHV-BRP	MN	Cross over or go around mnrr, Control Point, 266

Amtrak Endpoint OTP Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1167	PHL	74	ENG	25	ENG	17	KIN-WLY	AM	Onboard HBD alarm, 621|EX|ES, stopped to inspect train due to "integrity failure" @ Kenyons HBD
1169	PHL								
1194	BOS	58	WTR	18	WTR	16	NHV-NLC	AM	Wet / slippery rail, Milepost w/Letters, NHV, XVW, wheel slip due to weather, rpts under 50 MPH at some points
52	LOR	72	FTI	57	SYS	33	XSA-XOU	CS	PTC-caused slow-down or penalty stop Other, A402.0
53	SFA	354	ITI	255	ITI	255	LOR-LOR	CS	Late departure at initial terminal due to late arrival of inbound equipment 52
79	CLT	43	PTI	76	PTI	49	PTB-RMT	CS	Follow 89, Other, collier
80	NYP	196	PTI	140	PTI	121	GRO-GRO	NS	Meet NC 71, Control Point, Fields
600	PHL	68	DET	75	DET	75	PAO-PHL	AM	Catenary failure, Control Point, PENN COACH YARD, STOPPED ON N7 TRACK AT PENN INT. REPORTS OF WIRES DOWN IN PENN COACH YARD
641	HAR	91	DET	88	DET	88	PHL-PHL	AM	Catenary failure, Control Point, ., Held a/c 600; wires down entering PHL
651	HAR	27	ITI	28	ITI	28	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 650, LATE TURN OFF AM650
653	HAR	22	CTI	12	CTI	8	PHL-ARD	AM	Per Schedule
657	HAR	73	SVS	54	SVS	54	PHL-PHL	AM	Routine inspections, WAITED FOR MAP 100 PAPERWORK
686	BON	76	DCS	40	ENG	21	WOB-BON	MT	Traction motor 99
687	BRK	71	ITI	54	ITI	54	BON-BON	MT	Late departure at initial terminal due to late arrival of inbound equipment 686
63	TWO	36	WTR	32	WTR	25	ALB-SDY	AM	Wet / slippery rail Control Point, 145
64	NYP	23	FTI	33	FTI	16	SYR-ROM	CS	Follow csx unknown, Milepost, 286, 254
232	NYP	48	CTI	24	WTR	19	HUD-RHI	AM	Wet / slippery rail Unable to obtain track speed due to excessive wheel slip, Other, HUD SD
233	ALB	18	WTR	17	WTR	6	YNY-CRT	MN	Wet / slippery rail Reduced wheel-rail adhesion 1 in effect, Control Point, 6, Control Point, 33
241	ALB	30	CTI	2	CTI	2	NYP-XSD	AM	Cross Traffic, MNRR, MN, Other, XSD

Amtrak Endpoint OTP Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
244	NYP	72	CTI	81	CTI	60	CRT-YNY	MN	Mechanical issues Train hit a deer And had a flat spot MNR, 880, Other, Dobbs Ferry
280	NYP	52	WTR	53	WTR	44	SDY-ALB	AM	Wet / slippery rail 280 down to 1 mph from mp 158-cp 156., Milepost w/Letters, sdy, alb
281	NFL	54	FTI	69	FTI	54	ROC-BUF	CS	Had approach signal from CP388 to CP423 CSX freight train M27505 went into emergency stopped at MP425. M27505, Control Point, 388, csx
283	NFL	18	FTI	52	FTI	38	ROC-BUF	CS	Follow m561, Milepost, 374, 423
284	NYP	21	WTR	24	WTR	13	SDY-ALB	AM	Wet / slippery rail Milepost, 159, 145
290	NYP	27	RTE	42	RTE	24	SAR-XSY	DH	Dispatcher hold DISP Talked by stop signal AND instructed to had line route through out interlocking, Control Point, CPC 36
71	CLT	No OS Rpt	POL	142	POL	142	DNC-GRO	NS	Right of Way police hold We had a trespasser strike at .89 NC
72	GRO	65							
73	CLT	71	PTI	52	PTI	49	DNC-BNC	NS	Meet Amtk 80, Control Point, Merrill
76	RGH	65	FTI	62	FTI	62	GRO-DNC	NS	Meet Engine problems, #NS94Z, Control Point, Isom
90	NYP	No OS Rpt	FTI	34	ENG	29	RMT-PTB	CS	Undesired emergency application 50
97	MIA	19	PTI	61	MTI	31	BAL-XNY	AM	Disabled train ahead, Milepost, 121, ., single tracking a/c 1116 disabled on 1 track
55	WAS	22	CTI	37	CTI	20	BRP-STM	MN	Follow metro, Other, enroute
56	SAB	20	WTR	33	DCS	10	X1X-HLK	MA	Issue with automatic road crossing protection Milepost, 2, 2.4
40	CHI	81	PTI	88	TRS	62	RGH-XSE	NS	Vehicle on track ahead Other, MP 96.2 NC
41	MIA	253	FTI	143	FTI	101	CLB-CLB	CS	Cross Traffic Control Point, Cayce Yard, #CSL57-04
24	MOE	40	FTI	59	FTI	32	XEJ-XNO	NS	Follow Approach diverging restricting sgl @ East City Jct. Following UP MLIGN to NOT Jct #1Tk., Control Point, East City Jct., UP MLIGN, Manifest
6	CHI	108	FTI	146	FTI	37	ELK-XAZ	UP	Meet Take 40 rail to meet west bound Z train at Elko, Other, Elko Yard, UP, Z train
520	SAC	18	MBO	21	MBO	21	MTZ-SUI	UP	For maritime traffic Control Point, vista
522	SAC	Trn Cancelled	ENG	75	ENG	55	OKJ-OKJ	UP	Traction motor Run 3 door lights and traction light comes on. Losing load, C2108

Amtrak Endpoint OTP Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
523	SJC	32	MBO	22	MBO	22	SUI-MTZ	UP	For maritime traffic Control Point, benecia
537	OKJ	Trn Cancelled							
539	SJC	36	SYS	28	SYS	28	SAC-SAC	UP	Other late crew Substitute Engineer came in on short call, Other, SAC Station
502	SEA	39	FTI	37	FTI	23	PDX-VAN	BN	Cross Traffic BN unknown, Bridge, Columbia Draw
516	VAC	77	DSR	26	DSR	8	XF2-X1J	BN	Per bulletin Milepost, 146.6, 147.8, 25, West, Milepost, 151.6, 151.9, 25, All, Other, Need updated CN run times, 30, All CN tracks
517	PDX	16	OTH	60	OTH	60	XF2-X8B	BN	Time change. Default times are not accurate.
518	VAC	18	DSR	16	RTE	8	XF2-X1J	BN	Insufficient run time Control Point, spruce
59	NOL	100	DSR	78	TRS	57	GWD-YAZ	CC	Vehicle on track ahead All stop South Gwen on main , semi stuck on track ahead at MP 163.75, Siding, Gwen
11	LAX	No OS Rpt	DCS	152	DCS	80	SLO-SBA	UP	Signal suspension Control Point, 295, Control Point, 356
14	SEA	44	RTE	67	RTE	60	SBA-SLO	UP	Track & Time between the limits of: cp 356 and cp 335 on the main track, switch no; cp 336 and cp 321 on the main track, switch no; and cp322 and cp 295 on the main track, switch no. Proceeded at restricted speed, Control Point, cp 356, Control Point, cp 295
8	CHI	76	FTI	167	FTI	33	GGW-WPT	BN	Meet BNSF 6426, Siding, Oswego
27	PDX	37	FTI	64	FTI	60	PSC-WIH	BN	Meet BNSF 6795, BNSF 4008, BNSF 3816, Siding, Berrian
822	OKC	21	DSR	34	DSR	24	FTW-GLE	BN	Per bulletin Milepost, 346.3, 346.5, 25, m, Milepost, 349.6, 350.1, 25, m1, Milepost, 351, 351.6, 25, m1, Milepost, 358.3, 358.4, 50, m2, Milepost, 361, 361.2, 40, m2, Milepost, 361.4, 361.6, 25, m2, Milepost, 371, 372.5, 60, m, Milepost, 374, 374.1, 60, m, Milepost, 374.6, 373.8, 60, m, Milepost, 3
335	MKE	Trn Cancelled	DMW	5	DMW	5	GLN-XRO	ME	Waiting for MW clearance #8181 foreman Gavina, stopped at red flag of work limits, Milepost, 21.1, 24.0
336	CHI	172	DCS	152	DCS	151	MKE-MKA	CP	Drawbridge stuck open Bridge, Menomonee
337	MKE	180	ITI	139	ITI	139	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 336
338	CHI	47	CTI	18	CTI	14	GLN-XWA	ME	Follow metra, Milepost, 17.4, 2.9

Amtrak Endpoint OTP Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
339	MKE	54	ITI	24	ITI	24	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 338
342	CHI	22	ITI	15	ITI	15	MKE-MKE	CP	Late departure at initial terminal due to late arrival of inbound equipment 339
352	PNT	19	PTI	24	PTI	24	JXN-ARB	MI	Meet amtrak 355, Control Point, CP53
364	PTH	22	FTI	21	FTI	21	LPE-PTH	CC	Cross Traffic cn 8021, Control Point, 318
365	CHI	No OS Rpt	DSR	20	DSR	7	LPE-FLN	CC	Per bulletin Milepost, 274.1, 273.7, 30, m1&2
371	CHI	43	FTI	20	FTI	20	SJM-XPI	CS	Meet BNSF 9190, Control Point, EE New Buffalo
562	SAN	38	PTI	36	PTI	33	SNC-X98	SC	Meet Amtk 765, Control Point, Serra
566	SAN	74	CTI	19	FTI	19	XRJ-FUL	BN	Follow 6679, Milepost, 155, 164
572	SAN	63	ITI	26	ITI	26	LAX-LAX	SC	Late Equipment from the yard due to emergency equipment 572 was taken by AMTRAK 770 572
573	LAX	32	DCS	23	DCS	18	OSD-X98	SN	Restrictive signal(s) from known wayside signal failure Flagging CP Songs to X98, Stop, Control Point, Songs
579	LAX	52	PTI	29	PTI	29	OSD-X98	SN	Meet Stopped at cp songs waiting for Amtrak 774., 774, Control Point, songs
581	LAX	24	WTR	17	WTR	13	OSD-X98	SN	Flood / washout Control Point, songs
584	SAN	60	PTI	47	PTI	36	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	43	DCS	55	DCS	52	OSD-X98	SC	CTC system failure High tides causing a lot of backups. Had to Flag cp songs, Control Point, songs
595	LAX	43	HLD	15	HLD	15	SAN-SAN	SN	Enforcement of supposedly animal services who barked aggressively and constantly at passengers and passersby and leashes had to be held tight to keep it close to the owner the other one had to be held by her daughter pnr 5d5856
765	GTA	140	CTI	91	CTI	65	VNC-VNC	SC	Blocked from station track Stopped disabled Metrolink at VNC per DS, metrolink, Other, vnc
769	GTA	95	CTI	36	PTI	22	CML-OXN	UP	Meet 782, Control Point, South Oxnard
770	SAN	39	PTI	41	CTI	26	CWT-CWT	SC	Meet Broken down M107 at NRG, SCAX, M107, Other, CWT
774	SAN	61	CTI	35	CTI	32	CWT-VNC	SC	Blocked from station track Waited for traffic to clear due to disabled Metrolink at Northridge, Metrolink, 107, Control Point, Bernson

Amtrak Endpoint OTP Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
777	GTA	62	DCS	42	DCS	26	OSD-X98	SC	Restrictive signal(s) from unknown cause Red, Control Point, songs
785	GTA	40	WTR	33	WTR	29	OSD-X98	SN	High tide Control Point, songs
786	SAN	16	PTI	32	PTI	11	SBA-CPN	UP	Meet amtk, Control Point, south sba
790	SAN	23	ITI	26	ITI	26	LAX-LAX	SC	Late departure at initial terminal due to late arrival of inbound equipment 785
794	SAN	102	PTI	76	PTI	42	SIM-CWT	SC	Follow 786, Control Point, Davis, Control Point, Topanga
703	SAC	No OS Rpt	DCS	47	DCS	43	WAC-COC	BN	Power switch failure Flag east angiola, line switch and flag west and guild, Control Point, east angiola, Control Point, eest angiola
712	BFD	59	ENG	68	ENG	68	OKJ-OKJ	UP	Other electrical failure CAB car SPEEDOMETER and PTC not working, mechanical worked on it at OKJ STATION, C8307
714	BFD	34	DCS	42	DCS	24	COC-WAC	BN	Restrictive signal(s) from unknown cause Flagging @ E. Corcoran, Stop, Control Point, E. Corcoran
716	BFD	75	DCS	88	DCS	81	COC-WAC	BN	Restrictive signal(s) from known wayside signal failure Stop at E Corcoran waiting for AMT 703 due to signal being dark at W Angiola. Once AMT 703 passed, AMT 716 was flagged past red signal at E Corcoran until MP 944 where we received a clear signal due to signal at W Angiola being fixed., Stop, Co
3	LAX	249	FTI	310	FTI	109	XIA-GLP	BN	Follow BNSF unknown, Milepost, 75.7, 157.7
4	CHI	280	FTI	170	ENG	128	LAX-LAX	SC	Had to wait for turn of inbound engines off of Train 3 of 11/1/2026 19 and 205, 19
22	CHI	19	POL	172	POL	172	FTW-FTW	TE	RR blocked by trespasser or vehicle strike by another train AMTK 21 had a vehicle strike and we waited at FTW station until the track was released
305	STL	16	PTI	24	PTI	19	BNL-LCN	UP	Meet Amtrak 306, Siding, Mclean
381	QCY	26	DSR	18	FTI	13	PLO-MDT	BN	Blocked from station track BNSF, Other, MDT DEPOT
390	CHI	40	ENG	41	ENG	39	CDL-CDL	CC	Mechanical issues with daily inspection of added locomotive; Amtk335 335
1333	MSP	167	MBO	165	MBO	165	MKA-MKE	CP	Menomonee bridge was stuck open Bridge, Menomonee

Amtrak Initial Terminal Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/5/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	11/04	10	10	Planned set out / pick out of locomotives, cars or section of train Control Point, 142
BON	687	11/05	54	54	Late departure at initial terminal due to late arrival of inbound equipment 686
BRK	682	11/05	2	2	Mobility Impaired
CLT	72	11/05	(No OS)		
HAR	626	11/05	1	1	Passenger and/or baggage
HAR	650	11/05	11	11	Late departure at initial terminal due to late arrival of inbound equipment, 641
HAR	656	11/05	3	3	Meet, 647, Control Point, ., HELD FOR LATE 647 COMING IN
HAR	658	11/05	2	2	PTC - Stop Bypass Permission Required, Control Point, HARRISBURG, NEEDED TO PUSH THE BUTTON ON THE 9644
LOR	53	11/05	15	15	Station began boarding passengers before the engines were attached had to wait until boarding was completed Milepost, 92.1, 92.1
NYP	19	11/05	6	6	HEP, 608|EX|ES, MECHANICAL ISSUES IN STATION, HEP DROPPED
NYP	239	11/05	2	2	Passenger and/or baggage, TRAVEL
NYP	651	11/05	28	28	Late departure at initial terminal due to late arrival of inbound equipment, 650, LATE TURN OFF AM650
NYP	655	11/05	45	45	Other electrical failure, 662|EX|ES, LATE RELEASE DUE TO MECHANICAL ISSUES
NYP	1103	11/05	3	3	Passenger and/or baggage, BOARDING
NYP	1107	11/05	4	4	Door, 82592|AX|AS, DOOR ISSUES
PHL	605	11/05	1	1	Passenger and/or baggage
PHL	609	11/05	1	1	Passenger and/or baggage
PHL	645	11/05	4	4	PTC - Stop Bypass Permission Required, Control Point, ., Stop bypass on e/607.
PHL	653	11/05	2	2	High passenger count, PER DSPR; 729P
PHL	657	11/05	54	54	Routine inspections, WAITED FOR MAP 100 PAPERWORK
PHL	1144	11/05	1	1	Passenger and/or baggage
PHL	1151	11/05	1	1	Passenger and/or baggage
RGH	73	11/05	5	5	Restrictive signal(s) from unknown cause Stop Signal, Control Point, Capitol
RNK	1156	11/05	3	3	Meet Q272, Control Point, Campbell Ave
SFA	52	11/05	249	249	Late departure at initial terminal due to late arrival of inbound equipment 53
TWO	64	11/05	1		
WAS	1142	11/05	6	6	Dispatcher hold, Other, X, BLOCKED INTERLOCKING WITH MULTIPLE MARC TRN 855,536,879 AND THEN REMINDED TO RUN TRN

Amtrak Initial Terminal Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/5/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	1160	11/05	5	5	Door, 82709, PER CNDR UNABLE TO CLOSE DOOR ON A-END
CDL	390	11/05	39	39	Mechanical issues with daily inspection of added locomotive; Amtk335 335
CHI	3	11/05	2	2	Passenger and/or baggage Red cap brought down passenger, late for sleeper,
CHI	337	11/05	139	139	Late departure at initial terminal due to late arrival of inbound equipment 336
CHI	339	11/05	24	24	Late departure at initial terminal due to late arrival of inbound equipment 338
MKE	338	11/05	(Trn Cxld)		Bridge Failure
MKE	342	11/05	15	15	Late departure at initial terminal due to late arrival of inbound equipment 339
BFD	719	11/05	1	1	Door C9019, At departure time door stuck in loop and would not close had to get off train to force it closed.
GTA	774	11/05	4	0	Late departure at initial terminal due to late arrival of inbound equipment 757, Late Initial terminal departure due to late inbound 757 and insufficient schedule time for turning as outbound 774
GTA	782	11/05	2	2	Traction motor Giving fault code 0274 “no traction effort “ On the ride up on 761 it was randomly dropping the load but not enough to cause issues. Wasn’t giving door lights and engineer cut out the doors from the cab and it seemed to work after that but we had doors., 345
GTA	794	11/05	48	46	Late departure at initial terminal due to late arrival of inbound equipment 777
LAX	566	11/05	5	5	Air / Brake / Wheel 90215, Crew performed a second air brake test
LAX	572	11/05	26	26	Late Equipment from the yard due to emergency equipment 572 was taken by AMTRAK 770 572
OKJ	522	11/05	55	55	Traction motor Run 3 door lights and traction light comes on. Losing load, C2108
OKJ	534	11/05	15	15	HEP Engine shut down for unknown reason, C2123
OKJ	710	11/05	14	14	PTC - Initializing PTC (no failure) Per engineer no consist, trailing tonnage or length information in PTC, Other, OKJ
OKJ	712	11/05	68	68	Other electrical failure CAB car SPEEDOMETER and PTC not working, mechanical worked on it at OKJ STATION, C8307
OKJ	714	11/05	4	4	Wait for station track Late arrival at OKJ due to 530 & 535 working station first, 530 / 535, Other, Oakland Jack London station
OKJ	718	11/05	5	5	Meet 545, Other, jack london square
PDX	518	11/05	5	5	Meet Held for arrival of 11, 11, Control Point, CP05
SAC	537	11/05	(Trn Cxld)		Third Party Engine Failure
SAC	539	11/05	28	28	Other late crew Substitute Engineer came in on short call, Other, SAC Station
SAC	541	11/05	9	9	Other late crew

Amtrak Initial Terminal Details

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/5/2026

Terminal	Train	Date	Late	Delay	Cause
SAN	573	11/05	2	2	Late departure at initial terminal due to late arrival of inbound equipment 562, Inbound 562 late to SAN - spot at 09:42 - load 138 pax, etc.
SAN	579	11/05	4	4	Door 6408, Doors 7 & 8 not closing properly leaving a gap between the weathering strips. Recycled doors to get door lights
SAN	581	11/05	1		
SAN	595	11/05	32	10	Late departure at initial terminal due to late arrival of inbound equipment 584
SAN	595	11/05	32	7	Loading problem 40
SAN	595	11/05	32	15	Enforcement of supposedly animal services who barked aggressively and constantly at passengers and passersby and leashes had to be held tight to keep it close to the owner the other one had to be held by her daughter pnr 5d5856
SAN	777	11/05	9	9	PTC-caused slow-down or penalty stop Crossing acknowledged but put in emergency, Control Point, ash
SAN	785	11/05	1		
SEA	507	11/05	1	1	Meet AMTK 507 turned the wheel towards the red signal at 220 pm but delay report is saying 221 pm. Waiting for sounder 908 engine., SNDR 908, Control Point, King St.
SJC	542	11/05	4	4	Restrictive signal(s) from unknown cause Stop, Control Point, ALAMEDA

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.8	98.8	99.14	342	4
CDOT	95.0	66.7	66.7	92.4	24	8
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	93.7	No Data	No Data
NJT-NED	95.0	84.5	84.5	88.6	219	34
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 53(05) South of Charleston, SC - Signal

06NOV26: rain 53(05) operating with engines 354, 377, and 485 customers onboard was delayed 6 miles south of Charleston, SC on the CSX Charleston subdivision at milepost 393.6 on the Ashley River Bridge inspecting the stop signal and gaining permission to operate through the area upon a clear inspection.

Train	Delay	Comment
53(05)	45"	

Train 53(05) North of Charleston, SC - Vehicle on Tracks

06NOV26: Train 53(05) operating with engines 354, 377, and 485 customers onboard was delayed holding 13 miles north of Charleston, SC on the CSX Charleston subdivision at milepost 375.5 for a vehicle on the tracks ahead. Upon removal, train 53(05) operated at restricted speed through the affected area.

Train	Delay	Comment
53(05)	32"	

Train 657(05) Philadelphia, PA - Engine Failure

05NOV26: Train 657(05) operating with engine 607, 9641, and 45 customers onboard was delayed departing Philadelphia, PA due to a new MAP100 being issued for the engine.

Train	Delay	Comment
657(05)	54"	

Train 53(05) South of Petersburg, VA - Passenger Related

05NOV26: Train 53(05) operating with engines 354, 377, and 492 customers onboard was delayed south of Petersburg, VA on the CSX North End subdivision following CSX I031-05 from milepost 34.9 to milepost 161.2.

Train	Delay	Comment
53(05)	32"	

27-FOI-00137 0000000913 "UNCLASSIFIED" 11/10/2026

Train 1163(05) North of Aberdeen, MD - Police Related

05NOV26: Train 1163(05) operating with engines 630 and 432 customers onboard was delayed 7 miles north of Aberdeen, MD on the Amtrak PW Line holding at Perry Interlocking milepost 58.9 due to local police on scene at Oak Interlocking milepost 60.0 for a suicidal person laying in the gauge on 4 track. The police were able to help the distressed individual and release the scene safely with no injuries.

Train	Delay	Comment
1163(05)	41"	

Train 655(05) New York, NY - Engine Failure

05NOV26: Train 655(05) operating with engines 662, 665, and 325 customers was delayed departing New York Penn Station due to a late mechanical release from Sunnyside Yard. Train 644(05) arrived into New York with 2 inch flat spots and spalding on cab car 9632 which was replaced with engine 665 and a business class was added to provide wifi for outbound train 655(05).

Train	Delay	Comment
655(05)	45"	

Train 76(05) East of Burlington, NC - Freight Train Interference

05NOV26: Train 76(05) operating with engines 514, NC105, and 101 customers onboard was delayed 12 miles east of Burlington, NC on the Norfolk Southern H Line holding at Isom milepost 33.8 for disabled NS94Z-05 ahead. The freight was able to utilize a helper engine to shove into the siding at Isom and allow 76(05) to proceed.

Train	Delay	Comment
76(05)	1'02"	

Train 281(05) East of Buffalo, NY - Freight Train Interference

05NOV26: Train 281(05) operating with engines 9707, 714, and 68 customers onboard was delayed east of Buffalo, NY on the CSX Buffalo Terminal subdivision operating through approach signals from milepost 388 to milepost 425 where CSX 275-05 was disabled. Train 281(05) held at milepost 425 until the CSX freight was repaired and able to proceed.

Train	Delay	Comment
281(05)	54"	

Train 244(05) South of Croton, NY - Commuter Train Interference

05NOV26: Train 244(05) operating with engine 707, 9704, and 189 customers onboard was delayed 11 miles south of Croton-Harmon, NY on the MNRR Hudson Line holding at milepost 22.0 for MNRR 880-05 dealing with a deer strike ahead. The commuter train was able to build air and proceed south, but caused congestion in the area.

Train	Delay	Comment
244(05)	1'00"	

Train 79(05) South of Petersburg, VA - Freight Train Interference

05NOV26: Train 79(05) operating with engine 307 and 237 customers onboard was delayed 17 miles north of Rocky Mount, NC on the CSX North End subdivision following train 89(05) from milepost 102.3 until milepost 119.7.

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Train 686(05) East of Dover, NH - Signal

05NOV26: Train 686(05) operating with engines 90 and 64 customers onboard was delayed multiple times on the CSX Portland subdivision due to restrictive signals between Wells, ME and Boston, MA North Station. The areas of delay were milepost 58.4, milepost 103.9, and the MBTA Main Line subdivision at milepost 4.0. Due to the late operation of train 686(05), train 687(05) was delayed departing initial terminal.

Train	Delay	Comment
686(05)	40"	
687(04)	54"	

Train 41(03) North of Lakeland, FL - M of W Work

05NOV26: Train 41(03) was delayed holding at MP862.3, 13.2 miles north of Lakeland FL station on the CSX Lakeland subdivision due to M/W working on the track ahead. M/W released the track and train 41(03) was back on the move at 523PM ET.

Train	Delay	Comment
41(03)	59"	

Train 1156(05) South of Lynchburg, VA - Signal

05NOV26: Train 1156(05) was delayed at MP215.5, south of Lynchburg, VA station on the Norfolk Southern Blue Ridge subdivision due to signal issues.

Train	Delay	Comment
1156(05)	36"	

Train 280(05) North of Albany-Rensselaer, NY - Weather

05NOV26: Train 280(05) was delayed beginning at MP158, 16.2 miles north of Albany Rensselaer NY station on the Amtrak Hudson line operating over wet rails until MP156.

Train	Delay	Comment
280(05)	44"	

Downed Wire Philadelphia Yard Keystone Service

05NOV26: At 834AM ET Wilmington CETC reported an emergency plate in effect on the Amtrak PH Line in the Philadelphia yard affecting power to tracks 9 and 10. Train 600(05) was affected and stopped at mp1.2 and train 641(05) was delayed departing Philadelphia PA station while the power to the tracks was out. At approximately 855AM ET a wire was discovered down in the yard. ET and maintainers attempted to sectionalize and bring back power to tracks 9 and 10. At 935AM ET maintainers were and ET were able to restore power to track 9 and 10. Train 600(05) was back on the move at 938AM ET and arrived to Philadelphia PA station at 941AM ET 1 hour and 8 minutes late.

Train	Delay	Comment
641(05)	1'28"	
600(05)	1'08"	

27-FOI-00137 0000009133 "UNCLASSIFIED" 1/10/2026

Train 71(05) North of Greensboro, NC - Trespasser Strike

05NOV26: 759AM ET Train 71(05) with E/514, E/105 plus 5 cars carrying 51 passengers, struck a trespasser on the Norfolk Southern Goldsboro Greensboro subdivision at MP 0.7 north of Greensboro NC station in an area of single track. There were no reported injuries among the passengers or crew. The trespasser was a confirmed fatality. There was no reported damage to the equipment. This did not occur at a DOT grade crossing. The weather at the time of incident was 67° and partly sunny. Local police, EMS and Norfolk Southern police responded to the scene. Train 80(05) held at Greensboro NC station for open tracks. A recrew was summoned and took over the train's operation after it was cleared to depart by local police. Train 71(05) was released at 1003AM ET and terminated upon arrival to Greensboro NC station. Train 71(05) remaining passengers were transferred to train 73(05). Train 72(05) was cancelled Charlotte, NC to Greensboro as a result of the trespasser strike. Two on time buses were secured to accommodate passengers from 72(05) Charlotte, NC to Greensboro, NC. NRC # 1477886

National Response Center Number: 1477886

Train	Delay	Comment
71(05)	2'22"	
80(05)	2'01"	Hold GRO
73(05)	49"	

Train 53(04) North of Savannah, GA - Passenger Train Interference

05NOV26: Train 53(04) was delayed holding at MP477.3, North of Savannah GA station on the CSX Charleston subdivision meeting Amtrak train 90(05).

Train	Delay	Comment
53(04)	30"	

Train 53(04) Lorton, VA - Initial Terminal Delay

04NOV26: Train 53(04) operating with engines 360, 384, and 497 customers onboard was delayed departing Lorton, VA due to turn from late inbound 52(03).

05NOV26: Train 52(05) operating with engines 380, 352, and 166 customers onboard was delayed departing Sanford, FL due to turn from late inbound 53(04).

Train	Delay	Comment
53(04)	4'15"	
52(05)	4'09"	

Northeast Regional Crescent and Cardinal NS Track Work - 11/21-11/22 TWA 27-

27-FOJ-00137 0000000091130 "UNCLASSIFIED" 11/10/2026

04NOV26: On November 22, 2026, Norfolk Southern will perform signal system upgrade and testing work on the Washington District between MP 9 and MP 19. As a result, Northeast Regional, Crescent, and Cardinal service will be modified.

Northeast Regional
Train 147(21NOV) will terminate at Washington, DC Union Station. Bus 5147 will provide alternate transportation between Washington, DC Union Station and the Roanoke, VA station.
Train 156(22NOV) will originate at Washington, DC Union Station. Bus 5156 will provide alternate transportation between the Roanoke, VA station and Washington, DC Union Station.

Crescent
Train 220(21NOV) will operate in lieu of Train 20(21NOV), departing New Orleans, LA Union Passenger Terminal at 12:40P-CT. The train will operate 3 hours and 30 minutes later between New Orleans and Baltimore, MD Penn Station and 3 hours and 40 minutes later between Baltimore and New York, NY Penn Station.

Cardinal
Train 51(22NOV) will depart New York, NY Penn Station at 10:40A-ET and operate 4 hours later between New York and Chicago, IL Union Station.

WBS#: B.TR.100150.7326

Maintenance of Way Highlights

27-FOI-00137 0000009737 "UNCLASSIFIED" 1/19/2026

Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work

26OCT26: Due to the Veltri continuous outage on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Train 8/28(04) West of Glasgow, MT - Freight Train Interference

06NOV26: Train 8/28(04) was delayed at Tampico / MP 288.0, on the Burlington Northern Santa Fe Milk River Subdivision, 11 miles west of the Glasgow, MT station, meeting BNSF 7557 and BNSF 7874.

Train	Delay	Comment
8/28(04)	1'07"	

Train 714(05) East of Corcoran, CA - Signal

06NOV26: Train 714(05) was delayed at E. Corcoran/ MP949.9 on the BNSF Bakersfield Subdivision, 0.9 miles east of Corcoran, CA station, due to a power switch failure at Angiola/ MP942.8. The train was delayed flagging and taking the switch in hand. Trains 703(05) and 716(05) were also delayed due to this.

Train	Delay	Comment
714(05)	42"	
716(05)	1'21"	
703(05)	1'23"	

Train 6(05) Elko, NV - Freight Train Interference

06NOV26: Train 6(05) was delayed departing Elko, NV/MP557 on the UPRR Elko Subdivision, due to the route being blocked by UP 5693 that was fueling. The route around was through the Elko yard, and 6(05) also needed to wait for Z-train UP 8230 to finish fueling in the yard. Once the fueling of UP 8230 was complete, Train 6(05) departed Elko, and was routed through the yard.

Train	Delay	Comment
6(05)	1'02"	

Train 4(05) East of Victorville, CA - Freight Train Interference

06NOV26: Train 4(05) was delayed beginning at Hodge/ MP13.6 on the BNSF Cajon Subdivision, 23.1 miles east of Victorville, CA station, due to following BNSF 6536 to East D yard/MP1.0.

Train	Delay	Comment
4(05)	45"	

Train 5(05) Lincoln, NE - Freight Train Interference

06NOV26: 5(05), operating with locomotives 6345, 6 coaches, and 144 customers, was stopped east of Lincoln, Nebraska, at MP 40.4, on BNSF Creston subdivision, due to a disabled freight train ahead in an undesired emergency. The freight crew inspected the approximately three-mile-long train and determined that a distributed power unit (DPU) had stopped loading. After isolating the failed unit and addressing an issue with a replacement DPU, the freight train was able to resume recovery efforts.

While waiting, 5(05) incurred a delay of approximately 1 hour and 36 minutes. To expedite movement, BNSF arranged for 5(05) to reverse to CP411 and operate on Main Track 1 behind a tied-down freight train that had been recrewed. Once the shove movement was completed and the recrewed freight train departed, 5(05) resumed westward movement and followed the freight train toward Lincoln.

Train	Delay	Comment
5(05)	2'00"	wi-tronix est

Train 11(04) South of San Luis Obispo, CA - Engine Failure

05NOV26: Train 11(04) operating with E/327, E/338, 12 cars, and 189 customers, was delayed 40.1 miles south of San Luis Obispo, CA station at MP288.6 on the UPRR Santa Barbara Subdivision due to the trail engine E/338 shutting down. Crew reported the train did not have head-end power (HEP) and received fault codes "HEP rotation phase is down". The weather was a reported as 51 degrees and partly cloudy. The crew worked with CNOC mechanical and was able to restore HEP through the lead engine E/327. After further consultation with a Siemens technician, the train was advanced to the next safe siding in order to continue troubleshooting. Train 11(04) proceeded to Tangair siding/ MP293.6 where they cut out dynamic braking in order to proceed. The train was further delayed holding for a Gemco ballast train, in order to proceed.

Due to the delay, it was necessary for the crew on 11(04) to complete a calendar day inspection at Camarillo, CA, further delaying the train.

Train	Delay	Comment
11(04)	28"	FTI
11(04)	58"	
11(04)	1'30"	CML- Calendar Day

Train 7/27(04) East of Shelby, MT - Freight Train Interference

05NOV26: Train 7/27(04) was delayed at Chester/ MP1024 on the BNSF Hi Line Subdivision, 41.7 miles east of Shelby, MT station due to a disabled freight ahead at Lothair/ MP1034.7 and no route around. Once the freight was able to clear, Train 7/27(04) was able to proceed west.

Train	Delay	Comment
7/27(04)	45"	Witronix estimate

Train 7/27(05) West of Milwaukee, WI - Car Failure

05NOV26: Train 7/27(05), operating with locomotives 353 and 339, 10 coaches, and 157 customers, went into emergency at MP 102.4 on the CPKC Watertown Subdivision. Following an inspection of the train, the crew identified a damaged brake pipe hose on sleeper car 32021 as the cause of the emergency brake application. The crew replaced the defective brake pipe hose, performed the necessary inspections and tests, and restored the train to service. Upon completion of the repairs, Train 7/27(05) resumed normal operations.

Train	Delay	Comment
7/27(05)	42"	

27-FOI-00137 000000091333 "UNCLASSIFIED" 11/10/2026

Train 59(04) North of Hammond, LA - Freight Train Interference

06NOV26: Train 59(04) operating with [illegible]23, 7 [illegible]ches and 184 customers, was delayed .5 miles north of Hammond, LA, on CN McComb subdivision, due to meeting CN8006 at Control Point Hammond junction. Once the freight cleared and a route was made available, train 59(04) was able to proceed.

Train	Delay	Comment
59(04)	34"	

Train 11(04) South of Oakland, CA - Debris Strike

05NOV26: Train 11(04), E/327-E/338-12 cars, went into emergency at MP 25.0, 18 miles south of Oakland, CA, on the UPRR Coast Subdivision after striking unknown debris. There were no reported injuries to the crew or 202 customers on board. The was no damage reported to the equipment but 3 sets of air hoses were separated and needed resecuring. Once all hoses were resecured, the crew performed a brake test and proceeded south.

Train	Delay	Comment
11(04)	30"	

Trains 5(05) and 6(03) Naperville, IL - Police Related

05NOV26: Train 5(05) was held at Naperville, IL (MP28.5), on the BNSF Chicago Subdivision due to reported police activity ahead at Eola (MP34.6). Train 6(03) was also delayed while holding at West Eola (MP35.4) for the same incident. Once the hold was lifted, both trains resumed movement and continued operation.

Train	Delay	Comment
6(03)	36"	
5(05)	58"	

Train 539(05) Sacramento, CA - Crew Issues

05NOV26: Train 539(05), with 92 customers on board, was delayed departing Sacramento. CA due to crew issues. At sign up time, there was no engineer present. Crew management worked to call in a new engineer and to swap crews around to alleviate delay time. The engineer from Train 541(05) was moved up to operate Train 539(05). The engineer given a two hour call to report to the vacancy on Train 539(05) was moved to operate Train 541(05) upon arrival. Train 541(05) was also delayed departing holding for the engineer to arrive.

Train	Delay	Comment
541(05)	09"	
539(05)	28"	

Train 7/27(04) East of Glasgow, MT - Freight Train Interference

05NOV26: Train 7/27(04) was delayed at MP 270.6, 7 miles east of Glasgow, MT, on the BNSF Glasgow Subdivision due to BNSF freight H GALPAS1 03 ahead with mechanical issues. The crew held while BNSF personnel responded to assist. Upon inspecting the equipment, the freight crew found a broken knuckle. Once the mechanical issues were identified and resolved, and the freight was clear, Train 7/27(04) proceeded west. Train 8/28(04) was also delayed due to this, holding at Tampico/ MP289 until 2 westbound freights (BNSF 7557, BNSF 7874) and train 7/27(04) passed by.

Train	Delay	Comment
7/27(04)	2'57"	
8/28(04)	1'30"	

27-FOI-00137 000000091133 "UNCLASSIFIED" 1/10/2026

Train 6(03) East of Galesburg, IL - Freight Train Interference

05NOV26: Train 6(03) held 22.0 miles east of Galesburg, IL (MP162.6), on the BNSF Mendota Subdivision, at Galva (MP139.7) meeting BNSF 5067. Additional delay was incurred following BNSF 7776 from Galva to Buda (MP116.7).

Train	Delay	Comment
6(03)	30"	Meet BNSF 5067
6(03)	19"	Follow BNSF 7776

Train 11(05) South of Tacoma, WA - M of W Work

05NOV26: Train 11(05) was delayed at MP 10.3, 8 miles south of Tacoma, WA, on the SDRX Lakewood Subdivision due to maintenance of way work ahead. The crew held at MP 10.3 for Train 502(05) to clear route due to single tracking conditions due to maintenance of way crew. Once Train 502(05) cleared route, Train 11(05) proceeded south routed around affected area.

Train	Delay	Comment
11(05)	40"	

Train 712(05) Oakland, CA - Third Party Contractor Cab Car Failure

05NOV26: Train 712(05), CC/C8307-5 cars-E/C2012, was delayed departing Oakland, CA due to speedometer issues on CC/C8307. The crew held at the station for mechanical to respond. An Amtrak Road Foreman and an Amtrak Trainmaster responded to assist. Once on site, mechanical identified issues with the wiring and worked to resolve. Once the wiring issues were resolved, Train 712(05) was able to board the 4 customers and depart.

Train	Delay	Comment
712(05)	1'08"	

27-FOI-00137 0000009130 UNCLASSIFIED 11/10/2026

Hiawatha and Borealis Service East of Milwaukee, WI - B&B Work Due to Defect

05NOV26: At 12:45PM-CT, CPKC reported that Menomonee Bridge (MP85.1), located 0.3 miles east of the Milwaukee, WI station (MP85.4) on the C&M Subdivision, had malfunctioned. Bridges & Buildings (B&B) personnel responded to resolve the failure. During this time, multiple trains were delayed. At 330PM-CT, the bridge was reported closed and locked, and all train movements resumed.
-Train 336(05), with 42 customers onboard, was held at the Milwaukee station for a route to be established.
-Train 1333(05), with 167 customers onboard, was held 0.7 miles east of Milwaukee at MP84.7 for an open route.
-Train 335(05) was terminated at Milwaukee Airport (MP78.4), and the 105 customers destined for Milwaukee were provided three buses to their final destination.
-Train 338(05) originated at Milwaukee Airport, and the 125 customers were provided four buses from Milwaukee to bus bridge the train.
-Train 337(05), with 165 affected customers, was delayed departing Chicago Union Station due to the late turn of Train 336(05)'s inbound equipment, and customers were given the option to board Train 7/27(05) or wait for the delayed train.
-Train 8/28(03), with 209 customers onboard, was held at the Milwaukee station for a route to be established.

WBS#: B.TR.100150.7331

Train	Delay	Comment
335(05)	TERM MKA	
338(05)	27"	ORIG MKA
336(05)	2'31"	Hold MKE
337(05)	2'19"	ITD CHI - Turn of 336(05)
8/28(03)	25"	Hold MKE
8/28(03)	36"	FTI after route was open
1333(05)	2'45"	Hold MP84.7
7/27(05)	41"	

Train 3(03) East of Barstow, CA - Freight Train Interference

05NOV26: Train 3(03) was held at East Pisgah (MP705.2), approximately 41 miles east of Barstow, CA (MP0.4), on the BNSF Needles Subdivision due to BNSF 4862 experiencing an air brake failure and becoming disabled on Main Track 1. Due to single-tracking around the disabled freight train, Train 3(03) was required to meet BNSF 6075, BNSF 8051, and three other eastbound freight trains before receiving authority to proceed westward.

Train	Delay	Comment
3(03)	1'20"	

27-FOI-00137 :00000009133 "UNCLASSIFIED" 11/10/2026

Metrolink Ventura Subdivision South of Chatsworth, CA- Commuter Train Interference

05NOV26: At approximately 9:20a PT, Metrolink reported Metrolink 107 disabled at Northridge, between Chatsworth/MP 445.46 and Van Nuys/MP 455.05, on the Ventura Subdivision. They dispatched equipment from Simi Valley to rescue the disabled equipment. Train 770(05) held at Chatsworth/MP 446.3 for the rescue crew and equipment to respond. Train 14(05) held at Van Nuys station with Train 765(05) stopping behind it. Once the rescue equipment was onsite and coupled to the disabled equipment and cleared the route, train movement through the area commenced. Train 769(05) was also delayed at Burbank due to the Metrolink double set becoming disabled.

Due to the late operation of Train 770(05), a make-up section was made up to operate on time from Los Angeles to San Diego. Because of this swap of equipment, Train 572(05) was delayed departing Los Angeles due to a late release from the yard. Once the equipment was released from mechanical, the equipment was deadheaded to the station for boarding. After all customer were boarded, Train 572(05) departed.

Train	Delay	Comment
14(05)	55"	
765(05)	1'16"	
572(05)	26"	ITD LAX
770(05)	2'00"	GTA-LAX Section
774(05)	32"	
769(05)	28"	

Train 523(05) East of Martinez, CA - Drawbridge Opening

05NOV26: Train 523(05) was delayed at MP 35.4, 4 miles east of Martinez, CA, on the UPRR Martinez Subdivision as a result of the Suisun Drawbridge/ MP 32.9 being raised for maritime traffic to pass. Train 520(05) held at MP 32.7 for maritime traffic to clear.

Train	Delay	Comment
523(05)	22"	
520(05)	21"	

Train 59(04) North of Yazoo City, MS - Trespasser Incident

05NOV26: Train 59(04) was delayed 25 miles north of Yazoo City, MS (MP174.9), on the CNRR Yazoo Subdivision, at Gwin (MP149.9) due to a reported 18 wheeler stuck on the tracks at MP163.75. After the truck was removed and the track was inspected and determined safe for movement, Train 59(04) was released and continued southward on its route.

Train	Delay	Comment
59(04)	57"	

27,FOI-00137 000000009133 "UNCLASSIFIED" 11/10/2026

Train 522(05) Oakland, CA - Third Party Contractor Engine Failure

05NOV26: Train 522(05), CC/C8306, 3 cars-E/C2108, was delayed departing Oakland, CA due to a late release from mechanical. Mechanical worked to resolve loading issues on E/C2108 releasing the equipment at 544A-PT. At 5:56A-PT mechanical began working to address headlight issues on CC/C8306. Once cab car headlights issues were resolved, the crew deadheaded the equipment to the station from the Oakland Maintenance facility arriving at 6:32A-PT. At the Oakland station, addition locomotive issues with E/C2108 with door and loading issues. An Amtrak Roadforeman and mechanical responded to assist. Mechanical identified a cable issues and held for additional mechanical forced to bring a cable from the Maintenance Facility. Once the new cable was installed and the issues were resolved, Train 522(05), with 9 customers on board, departed Oakland Station.

After departure, loading issues on E/C2108 persisted with the crew stopping at MP 6.7, a quarter mile north of Oakland Station, to troubleshoot. Due to the uncertainty of the locomotives reliability, Train 522(05) was advanced to Emeryville, CA where it was terminated and the 30 affected customers were reaccommodated on Train 524(05). Train 537(05) was cancelled in its entirety, with customers to next available service, due to the equipment shortage.

Train	Delay	Comment
522(05)	Term EMY	
537(05)	Cancelled	

Train 24(05) North of New Orleans, LA - Freight Train Interference

05NOV26: Train 24(05) was delayed 7 miles north of New Orleans, LA (MP0.0), on the CSX NO&M Subdivision at NOT Junction (MP803.7) while waiting for a Union Pacific freight train to clear the route. Train 23(05) was also delayed 11.8 miles south of Bay Saint Louis, MS (MP754.5), on the CSX NO&M Subdivision at Claiborne (MP766.3) while meeting Train 24(05).

Train	Delay	Comment
24(05)	32"	
23(05)	32"	

Train 390(05) Carbondale, IL - Engine Failure

05NOV26: Train 390(05), with 47 customers onboard, was delayed departing Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision after engine ID4626 would not start. To recover the failure, Train 58(04) cut engine 335 at Carbondale and added it ahead of Train 390(05). Once the engine was added, Train 390(05) departed 39 minutes late. Due to the extended period without head-end power in the yard, onboard food spoiled, resulting in service recovery of snack packs, bottled water, and non-perishable food items.

WBS#: B.TR.100150.7329

Train	Delay	Comment
390(05)	39"	
58(04)	24"	CDL - Cut E/335

Train 3(03) West of Flagstaff, AZ - Freight Train Interference

05NOV26: Train 3(03) was delayed starting at MP 387.8, 43 miles west of Flagstaff, AZ, on the BNSF Seligman Subdivision due to freight interference. The crew followed an BNSF freight beginning at MP 387.8 until MP 473.6 where they were able to operate around. Once the route was clear, Train 3(03) proceeded west at track speed.

Train	Delay	Comment
3(03)	32"	

27-FOI-00137, 000000009133 "UNCLASSIFIED" 11/10/2026

Train 2/422(04) Ontario, CA - Car Failure

05NOV26: Train 2/422(04), P476, P413, 10 cars, with 214 customers onboard, was delayed at Ontario, CA due to reported air issues. Crew worked with CNOC mechanical and was unable to resolve. The issue was reported to be a bad air valve. A mechanical team was dispatched from Los Angeles, after securing the needed replacement part. Once mechanical arrived and assisted in repairing the air valve, Train 2/422(04) was able to proceed.

Train 2/422(04) was further delayed at Palm Springs due to a disabled freight and police activity blocking normal access to station. The UPRR attempted to shove Train 2/422(04) from the east to allow access to the station, however the switch at Garnet/MP 589.0 would not align properly. The crew held at MP 589.5 for the maintainer to respond. Once the maintainer was on site and able to lock and secure the switch, the crew shoved into the Palm Springs Station to perform station work.

Service recovery measures were enacted, including the distribution of snack packs and water to all coach customers and complimentary coffee service. A 10% discount was offered on items purchased in the lounge. Early dinner service was provided to coach customers on the current day and the following day. Sleeper car customers continued to receive their standard amenities without interruption.

WBS#: B.TR.100150.7330

Train	Delay	Comment
2/422(04)	5'26"	ONA
2/422(04)	40"	PSN

BNSF Fallbridge Subdivision West of Pasco, WA- Freight Derailment

04NOV26: At 7:30A-PT, The BNSF reported BNSF freight H-VAWPAS1-03 derailed while entering the Plymouth Siding/ MP 192.8 on the BNSF Fallbridge Subdivision, 40 miles west of Pasco, WA. Initial reports were 9 cars and 2 locomotives on the ground blocking the main line. At 7:16A, Train 27(02), with 82 customers on board, stopped at MP 202.7 and held for disposition. Due to the length of delay anticipated, Train 27(02) shoved back the 29.1 miles to Pasco where 2 buses were sourced to accommodate the 82 affected customers between Pasco and Portland, OR. Train 27(02) arrived back to Pasco at 9:06A-PT and was terminated. The buses were on site at 9:00A-PT for customers to transfer to their final destinations. With the assistance of BNSF pilots, the equipment was wyed at Pasco then deadheaded to Spokane, WA for servicing. Train 28(04) originated in Spokane with 2 buses sourced for the 72 affected customers traveling between Portland and Spokane.

Due to the alternate bus transportation for Train 28(04), service recovery was initiated with all coach customers provided with Popeyes chicken. All sleeper car customers were provided regular scheduled meals. Emergency water was placed on the buses for customers as needed.

At 11:00PM-PT, BNSF reported the main line was returned to service.

05NOV26: Train 27(03) was delayed holding at MP 202.7, 57 miles west of Pasco, WA, on the BNSF Fallbridge Subdivision due to freight interference from freight derailment. The crew held for BN6795, BN4008 and BN3816 to clear then proceeded west.

Train	Delay	Comment
27(02)	Term PSC	
28(04)	Orig SPK	
27(03)	1'00"	

UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority

16OCT26: The UPRR placed general orders in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected

17OCT26: In order to minimize customer delays due to this, the following Service Adjustments were implemented:

Train 761(17) and 765(17) were originated at Los Angeles, CA, no alternate transportation provided.

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Trains 757/ 765/ 777(17-01NOV) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-01NOV) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

23OCT26: The operating plan was extended through at least Sunday November 1.

30OCT26: The operating plan was extended to Friday November 6th.

04NOV26: The operating plan was extended to Friday November 15th.

WBS#: B.TR.100150.7278

Train	Delay	Comment
774(16)	1'39"	
757(16)	1'34"	
786(16)	1'35"	ITD SLO- Turn of 757(16)
786(16)	1'35"	ITD SLO- Equip off 757
765(16)	1'22"	
794(16)	38"	ITD SLO- Equip off 765
794(16)	2'08"	
14(16)	2'21"	
786(16)	2'57"	
11(15)	1'23"	
14(17)	1'13"	
11(16)	1'51"	
11(17)	1'15"	
14(18)	1'19"	
14(19)	1'01"	
11(18)	1'08"	
11(19)	1'10"	
14(20)	1'40"	
11(19)	51"	waiting for & meeting 14(20) at Tangair
14(21)	40"	
11(20)	1'05"	meet 14(21)
11(20)	1'14"	
11(21)	1'02"	
14(22)	59"	
11(22)	1'51"	
14(23)	1'03"	
782(23)	48"	
14(24)	1'03"	
11(25)	1'52"	
14(27)	1'31"	
11(26)	1'29"	
11(28)	1'11"	
14(28)	1'07"	
14(29)	45"	
11(29)	1'00"	
14(31)	1'02"	
11(30)	1'21"	
14(01)	1'24"	
11(31)	1'05"	
14(02)	1'00"	
11(01)	1'15"	
14(03)	51"	
14(04)	1'00"	
11(03)	1'00"	
14(05)	1'00"	
11(04)	1'20"	

NCTD San Diego Subdivision East of San Clemente Pier, CA - Signal Issues

31OCT26: Ongoing signal issues on the NCTD San Diego Subdivision due to high tides requires trains to flag between San Clemente Pier, CA and Oceanside, CA. The single-

inbound Train 567(03) which was operating 2 hours late from the train interference caused by the signal outage between San Clemete Pier and Oceanside.

The 79 customers scheduled for Train 572(03) were accommodated on Train 774(03).
The 89 customers scheduled for Train 579(03) were accommodated on Train 581(03).

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Train	Delay	Comment

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

```
562(31)  32"
765(31)  17"
564(31)  52"
566(31)  45"
769(31)  54"
573(31)  28"
770(31)  47"
774(31)  58"
572(31)  14"
777(31)  15"
579(31)  46"
785(31)  14"
581(31)  1'02"
587(31)  49"
591(31)  50"
580(31)  11"
782(31)  46"
584(31)  1'14"
786(31)  24"
588(31)  21"
593(31)  1'06"
595(31)  1'02"
790(31)  11"
794(31)  24"
562(01)  22"
567(01)  32"
769(01)  47"
564(01)  59"
566(01)  1'13"
573(01)  27"
777(01)  22"
572(01)  21"
579(01)  47"
774(01)  41"
581(01)  1'02"
785(01)  26"
587(01)  48"
580(01)  22"
782(01)  52"
591(01)  51"
584(01)  1'15"
593(01)  1'03"
786(01)  13"
588(01)  1'04"
790(01)  12"
595(01)  1'01"
794(01)  17"
761(02)  17"
765(02)  12"
567(02)  13"
769(02)  22"
562(02)  12"
564(02)  33"
573(02)  19"
777(02)  21"
566(02)  43"
770(02)  15"
572(02)  16"
581(02)  16"
774(02)  11"
785(02)  22"
587(02)  16"
580(02)  11"
782(02)  12"
591(02)  22"
584(02)  21"
786(02)  11"
588(02)  38"
794(02)  17"
790(02)  12"
595(02)  1'38"  SAN Turn of Late Inbound 584(02) and Delay between SOL and SNC
593(02)  2'09"  SAN Turn Late Inbound 782(02) and Delay between SOL and SNC
761(03)  22"
567(03)  1'56"
765(03)  1'14"
562(03)  1'34"
```

Train	Delay	Comment
770(03)	50"	
573(03)	1'51"	SAN Late Inbound 562 and SOL to SNC Delays
777(03)	31"	
774(03)	36"	
581(03)	14"	
785(03)	16"	
587(03)	37"	
580(03)	13"	
782(03)	29"	
591(03)	18"	
584(03)	20"	
593(03)	13"	
595(03)	48"	
786(03)	16"	
588(03)	21"	
790(03)	16"	
794(03)	20"	
566(04)	11"	
562(04)	32"	
564(04)	24"	
770(04)	23"	
572(04)	33"	
761(04)	19"	
765(04)	19"	
567(04)	16"	
573(04)	15"	
769(04)	20"	
579(04)	18"	
587(04)	30"	
777(04)	1'03"	
581(04)	12"	
785(04)	17"	
774(04)	29"	
580(04)	10"	
584(04)	56"	
786(04)	11"	
794(04)	41"	ITD GTA - Equip off 777
761(05)	13"	
765(05)	36"	
769(05)	26"	
573(05)	33"	
562(05)	49"	
564(05)	13"	
566(05)	11"	
584(05)	1'03"	
777(05)	29"	
794(05)	28"	ITD GTA - Turn off 777
587(05)	55"	
595(05)	06"	
593(05)	14"	
591(05)	21"	
785(05)	45"	
581(05)	17"	
774(05)	14"	
579(05)	42"	
572(05)	06"	
770(05)	31"	

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

BNSF Gallup Subdivision East of Winslow, AZ- Southwest Chief Service Disruption

23OCT26: A severe storm with isolated showers and thunderstorms impacted the area between Gallup, NM and Albuquerque, NM bringing flash floods and reduced operating conditions. At 9:50A-PT, the BNSF reported flash floods on the Gallup Subdivision with confirmed water over the rails at MP 77.9, 80 miles east of Gallup, NM . Multiple freights were tied down with crews expired on hours of service between Laguna/MP 71.1 and Grants/MP 98.3 causing single tracking conditions over 100 miles. BNSF maintenance of way personnel responded to areas of potential water of the rails to inspect. Substantial delays were incurred operating through the affected area.

Train 4(22), with 159 customers on board, arrived into Winslow, AZ at 9:42A-PT and held for open track. While holding in Winslow, and in anticipation of further delay, the crew performed a calendar day inspection. Once a route was open, Train 4(22) proceeded east

floods, and freight meets.

24OCT26: Due to the late operation of Train 3(22), the crew expired on hours of service holding in Flagstaff, AZ. Train 3(22) held at Flagstaff with pilots on board beginning at 1:55A-PT for the recrew to arrive from Train 4(23), arriving at approximately 4:30A-PT. Once the recrew arrived and conducted their job briefing, Train 3(22) proceeded west.

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

To support customers and provide service recovery on Train 4(22), complimentary food and beverage offerings were provided. All coach customers received complimentary snack packs, bottled water, and hot beverages. During lunch service, sleeping car customers received the regular lunch service in the Dining Car, while coach customers were provided complimentary beef stew, mashed potatoes, and beverages. During dinner service, sleeping car customers received the regular dinner service in the Dining Car, while coach customers were provided complimentary Salisbury steak, vegetables, and mashed potatoes.

Train 4(22) had five misconnections at Kansas City, MO to Train 318(24) that were provided an alternate bus to their final destination. Train 6(22) also provided aid to local customers on Train 4(22) that were boarding between Galesburg and Chicago.

24OCT26: Train 3(23), operating with engines 79/29, 9 coaches, and 153 customers, was stopped east of the Gallup, NM station due to severe weather resulting in water above the rail in multiple locations. Burlington Northern Santa Fe subsequently reported that there was no route available beyond Laguna (MP 71) due to flooding of the tracks and the adjacent highway. Reported flood damage included both main tracks under water with debris between MP 72.7 and MP 72.3, including approximately 800 feet of side scour on the Main Track 1 side; side scour and undercutting at a culvert near MP 72.4; water over a high-water detector bridge and both rails between MP 70.1 and MP 69.8; and water over both rails between MP 69.8 and MP 69.7, where inspection was not possible. As a result, Train 3(23) shoved back to Albuquerque, NM and arrived at 11:57P-MT. The train wye'd en route into the station and will return to its origin.

As a result of the service disruption, the following service adjustments were implemented:
- Train 3(23) arrived at Albuquerque, NM at 11:57P-MT, wyed enroute into the station, and operated back to Chicago, IL, returning customers to points of origination.
- Train 4(24), with 135 customers, wyed at Barstow, CA and operated back to Los Angeles, CA Union Station.
- Train 3(24), with 136 customers, reversed back to Kansas City, MO, wyed, and planned to return to its origin.
Due to crew availability in Kansas City, Train 3(24) held in Kansas City for the arrival of Train 4(23) and was coupled to operate as a combo set to Chicago, returning Train 3(24) customers to points of origination.
- Train 4(25) was canceled. No alternate transportation was provided.

25OCT26: Train 3(23) departed Albuquerque, NM, at 125AM-MT operating eastward back to Chicago. Train 3(23) was delayed at Fox/MP820.0, 15 miles east of Lamy, NM, on the BNSF Glorieta Subdivision, after operating through code line failure at E. Fox, the crew reported while operating through the switch, with it on hand, the switch handle popped up as train started into the switch. Train 3(23) was delayed due to possible switch damage and due to holding for a required recrew to arrive.

As of 700AM-CT on Sunday October 25th, BNSF reported still no estimate for open track. Due to the ongoing issues on the BNSF Gallup Subdivision, additional Southwest Chief service adjustments were necessary:
- Train 3(25) terminated in Kansas City, MO. No alternate transportation between Kansas City and Los Angeles.
- Train 4(25) was reinstated between Kansas City and Chicago only. Train 4(25) originated in Kansas City with no alternate transportation between Los Angeles and Kansas City.
- Train 4(27) cancelled entirely. No alternate transportation between Los Angeles and Chicago.

26OCT26: BNSF reported current weather conditions and further soil and ground

subdivision the following additional service adjustments were necessary:
- Train 3(26) cancelled entirely, no alternate transportation between Chicago and Los Angeles.
- Train 4(26) cancelled entirely, no alternate transportation between Los Angeles and Chicago.

27-FOI-00137 0000009133 "UNCLASSIFIED" 11/10/2026

BNSF advised an extremely large volume of freight traffic has been holding for open route and expect it to be heavily congested across the subdivision upon track opening.

27OCT26: A revised Main Track 1 estimate has been changed to "pending" due to a new washout that was identified at Milepost 50.2, with approximately 500 feet of side scour (erosion of the soil, rock, or ballast along the side of the railroad embankment (roadbed) caused by flowing water). Repair efforts are underway, with a ballast train placing material. Main Track Two between Laguna and Marmon is expected to reopen at 12:01 AM CT on the 27th under a 10 MPH speed restriction. BNSF has advised there are still a significant amount of Freight Trains tied down which will cause significant congestion through the area. Restoration efforts remain fluid due to changing water levels along the right-of-way.

- Train 3 (27) canceled in its entirety between Chicago and Los Angeles. No alternate transportation will be provided.
- Train 4(28) cancelled entirely, no alternate transportation between Los Angeles and Chicago.

29OCT26: Trains 3 and 4 continued to see heavy delays in the area due to ongoing repairs and congestion. BNSF advised to expect delays between 2 to 4 hours to continue over the next several days.

01NOV26: Trains 3(30) and 4(31) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.

02NOV26: Trains 3(31) and 4(01) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.
Moderate rainfall continues through the day. The Gallup Subdivision remains open, with one main closed for stabilization work. There were 43 trains on the subdivision.

03NOV26: Trains 3(01) and 4(02) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.
Weather conditions were favorable. The Gallup Subdivision remains open, with one main closed for stabilization work. There were 31 trains on the subdivision. Due to continued late operations and staffing issues, trains 3(04) and 4(04) were cancelled entirely with no alternate transportation.

WBS#: B.TR.100150.7301

Train	Delay	Comment

4(22)	1'32"	Hold WLO
4(22)	5'09"	Meeting multiple freights due to weather
3(22)	1'30"	High winds and flash floods
3(22)	2'43"	meeting multiple freights due to weather
3(22)	2'59"	FLG, recrew
4(25)	Originated KCY	
3(23)	Terminated ABQ	Returned to origin
3(24)	Terminated KCY	Returned to origin
4(24)	Terminated BAR	Returned to origin
3(25)	Terminated KCY	
4(27)	Cancelled	
3(23)	5'18"	E/LMY, switch issue/recrew
3(26)	Cancelled	
4(26)	Cancelled	
3(27)	Cancelled	
4(28)	Cancelled	
4(29)	47"	BAR-NDL Congestion
3(28)	1'07"	ABQ-KNG Congestion
4(29)	1'20"	GLP-XIA
3(29)	4'44"	ABQ-GLP
3(29)	44"	WLO-FLG Congestion
4(30)	32"	KNG-FLG Congestion
4(30)	51"	FLG-WLO Congestion
4(31)	2'44"	NDL to ABQ
3(30)	8'45"	ABQ to BAR
3(31)	8'08"	ABQ-BAR
4(01)	3'30"	BAR to ABQ
3(01)	7'23"	ABQ to BAR
4(02)	4'52"	BAR to GLP
3(02)	20"	ABQ-KNG
3(04)	Canceled	
4(04)	Canceled	
3(03)	1'49"	
4(03)	2'29"	VRV-GLP

27-FOI-00137 90000009133 "UNCLASSIFIED" 11/10/2026

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

Train	Delay	Comment

822(29)	32"				
821(29)	27"				
821(30)	34"				
822(30)	30"				
822(01)	30"	27-FOI-00137	00000009133	"UNCLASSIFIED"	11/10/2026
821(02)	34"				
822(02)	29"				
822(03)	33"				
821(03)	25"				
821(04)	35"				
822(04)	32"				
821(05)	35"				
822(05)	26"				
821(06)	26"				
822(06)	37"				
821(07)	35"				
822(08)	32"				
821(09)	32"				
822(09)	36"				
822(10)	23"				
822(11)	41"				
822(12)	48"				
821(12)	21"				
821(13)	22"				
822(13)	36"				
821(14)	35"				
822(14)	17"				
821(15)	26"				
821(16)	41"				
822(15)	34"				
822(16)	19"				
821(17)	24"				
821(19)	39"				
822(19)	22"				
821(20)	29"				
822(20)	32"				
821(21)	46"				
821(22)	32"				
822(21)	19"				
822(22)	30"				
821(23)	42"				
822(23)	23"				
821(24)	21"				
822(24)	22"				
821(25)	34"				
822(25)	43"				
821(26)	52"				
822(27)	34"				
822(26)	21"				
821(28)	30"				
822(28)	31"				
821(29)	23"				
822(29)	33"				
821(30)	33"				
822(30)	22"				
821(31)	20"				
822(31)	25"				
822(01)	30"				
821(02)	35"				
822(03)	27"				
821(04)	37"				
822(04)	15"				

Maintenance of Way Highlights

27-FOI-00187 0000000091136 "UNCLASSIFIED" 11/7/2025

Pacific Surfliner and Coast Starlight Service San Luis Obispo, CA to San Diego, CA - Scheduled M/W TW 27-021

07NOV26: A multi-agency track maintenance project involving North County Transit District (NCTD), Southern California Regional Rail Authority (SCRRA/Metrolink), and Union Pacific Railroad (UP) was conducted between San Luis Obispo, CA, and San Diego, CA. To accommodate the work, the following operating plan was implemented:

Coast Starlight
Train 11 (November 5-7): Terminated at Emeryville, CA with alternate transportation provided between Sacramento and Los Angeles via Gold Runner Services.
Train 14 (November 7-9): Originated at Emeryville, CA with alternate transportation provided between Los Angeles and Martinez via Gold Runner Services.

Pacific Surfliner
Friday, November 6
Train 794(06) Originated in Goleta, CA account of ongoing signal issues and Terminated at Los Angeles, CA account of the scheduled track work. Bus 3594 provided alternate transportation between Los Angeles and San Diego making all stops except San Juan Capistrano
Train 595(06) Canceled in its entirety. Customers were accommodated on Bus 5811.

Saturday, November 7, and Sunday, November 8
All Pacific Surfliner trains were canceled. No alternate transportation was provided.

UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Scheduled M/W Work TWA 27-020

26OCT26:To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 1(31Oct, 7Nov, 14Nov) and Train 42(30Oct, 6Nov, 13Nov) will detour over the BNSF San Bernardino Subdivision between West Colton(UPRR Alhambra subdivision) and Soto(BNSF San Bernardino subdivision), bypassing Ontario, CA (ONA) and Pomona, CA (POS). Train 801(2Nov, 9Nov, 16Nov) was created for the detour between Riverside, CA (RIV) and Los Angeles, CA (LAX).

Train 2/422(1Nov, 8Nov, 15Nov) will detour over the BNSF San Bernardino Subdivision between Soto(BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(1Nov, 8Nov, 15Nov) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV). An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision. No alternate transportation will be provided to POS and ONA.

WBS#: B.TR.100150.7307

Train	Delay	Comment
2/422(01)	39"	
1(31)/421(30)	44"	

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
11(2)	SLO	164		Main Resevoir

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

27-FOI-00137 00000009133 "UNCLASSIFIED" 11/10/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
504 (06)	EUG	no NPCU - no firearms, bikes, or checked baggage.	n/a	0	72
566 (05)	LAX	no bikes	n/a	0	90215
584 (05)	LAX	no bikes	n/a	0	90215
572 (05)	LAX	NO JY, NO BIKE SPACE, NO CAFE.	n/a	0	COMET SET
785 (05)	LAX	785(05) *SAN-LAX only* will operate Comet set - no BV, no JY, no cafe. 785 lax-gta WILL HAVE NORMAL EQUIPMENT. 587(05) will have the JY/BV/cafe reinstated.	jy - 91 / bv - 6	97	COMET
502 (05)	PDX	no NPCU - no firearms, bikes, or checked baggage.	n/a	0	72
579 (05)	SAN	no bikes	n/a	0	90215
595 (05)	SAN	no bikes	n/a	0	90215
507 (05)	SEA	no NPCU - no firearms, bikes, or checked baggage.	n/a	0	72

Reverse Consists

Train Number	Station	Reason
1163 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1087 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1143 (05)	SPG	Consist reversed | Business class seat orientation may have changed | At Front
1155 (05)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1153 (05)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
2133 (05)	NYP	Business class change only | Business class seating orientation may have changed | At Rear
1147 (05)	SPG	Consist reversed | Business class seat orientation may have changed | At Front
1135 (05)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
94 (06)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
1138 (06)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
1156 (06)	RNK	Consist reversed | Business class seat orientation may have changed | At Front