CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, November 07, 2026 Rules: 0-4



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00137 [illegible]

Initial Terminal Performance By Division

[illegible]

Scheduled Departure Date: **11/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/06/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	37	88.1%	1,829	254	86.1%	11,303	1,606	85.8%
Central Division	86.0%	59	1	98.3%	349	17	95.1%	2,119	142	93.3%
East Division	82.0%	159	25	84.3%	938	135	85.6%	5,937	873	85.3%
West Division	86.0%	92	11	88.0%	542	102	81.2%	3,247	591	81.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 11/6/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**76%**	**103,726**	**39,108**	**62%**	**569,928**	**186,794**	**67%**	**3,750,683**	**1,093,680**	**71%**
Northeast Corridor	***78%***	***43,377***	***18,963***	***56%***	***246,056***	***80,152***	***67%***	***1,619,155***	***405,919***	***75%***
Acela	80%	7,820	2,293	71%	38,273	11,529	70%	275,332	58,092	79%
Northeast Regional	78%	35,557	16,670	53%	207,783	68,623	67%	1,343,823	347,827	74%
Richmond / Newport News / Norfolk	75%	4,765	2,185	54%	45,223	14,539	68%	317,181	90,256	72%
Springfield Shuttles	89%	851	283	67%	4,466	647	86%	25,022	5,008	80%
Roanoke	75%	3,284	598	82%	17,592	5,988	66%	135,787	34,260	75%
On Spine Northeast Regional	80%	26,657	13,604	49%	140,502	47,449	66%	865,833	218,303	75%
State Supported	***80%***	***48,139***	***14,452***	***70%***	***256,163***	***73,448***	***71%***	***1,695,079***	***487,762***	***71%***
Borealis	80%	840	427	49%	3,824	1,167	69%	26,063	5,463	79%
Capitol Corridor	90%	4,562	731	84%	24,912	3,593	86%	150,650	27,823	82%
Carolinian	70%	1,447	1,160	20%	8,291	4,223	49%	47,498	17,825	62%
Cascades	75%	3,185	1,086	66%	16,367	5,244	68%	104,348	31,453	70%
Downeaster	82%	1,660	525	68%	8,198	2,164	74%	66,675	16,162	76%
Empire	78%	6,384	3,016	53%	34,196	9,086	73%	231,905	56,189	76%
Adirondack	72%	326	0	100%	1,855	10	99%	14,825	2,118	86%
Ethan Allen Express	70%	622	284	54%	3,118	1,411	55%	21,548	8,413	61%
Maple Leaf	70%	908	709	22%	4,634	2,243	52%	31,721	10,716	66%
New York - Albany	85%	3,007	1,008	66%	16,883	3,057	82%	112,325	20,707	82%
New York - Niagara Falls	75%	1,521	1,015	33%	7,706	2,365	69%	51,486	14,235	72%
Gold Runner	73%	3,114	592	81%	15,239	4,954	67%	95,392	35,516	63%
Heartland Flyer	70%	199	0	100%	932	586	37%	7,310	5,947	19%
Hiawatha	90%	1,898	111	94%	9,655	1,466	85%	67,833	7,209	89%
Illinois	78%	3,151	156	95%	15,607	1,849	88%	101,013	29,161	71%
Carl Sandburg / Illinois Zephyr	85%	499	6	99%	2,032	171	92%	15,516	3,685	76%
Illini / Saluki	85%	1,109	0	100%	5,828	485	92%	34,784	12,370	64%
Lincoln Service	70%	1,543	150	90%	7,747	1,193	85%	50,713	13,106	74%
Keystone	92%	5,848	310	95%	36,417	3,666	90%	247,564	25,346	90%
Lincoln / Missouri	70%	1,033	156	85%	5,048	2,247	55%	32,099	15,212	53%
Mardi Gras Service	80%	420	0	100%	1,955	205	90%	12,763	3,355	74%
Michigan	70%	2,499	174	93%	11,811	2,499	79%	79,463	19,425	76%
Blue Water	70%	547	0	100%	2,707	370	86%	21,381	5,234	76%
Pere Marquette	85%	305	0	100%	1,604	112	93%	10,915	735	93%
Wolverine	70%	1,647	174	89%	7,500	2,017	73%	47,167	13,456	71%
Missouri	80%	298	0	100%	1,353	316	77%	10,390	2,038	80%
Pacific Surfliner	85%	7,589	4,714	38%	41,254	24,993	39%	274,562	149,065	46%
Pennsylvanian	80%	1,001	0	100%	5,676	574	90%	35,647	10,256	71%
Piedmont	80%	1,566	1,294	17%	6,348	3,347	47%	46,116	15,483	66%
Vermonter	75%	1,445	0	100%	9,080	1,269	86%	57,788	14,834	74%
Long Distance	***58%***	***12,210***	***5,693***	***53%***	***67,709***	***33,194***	***51%***	***436,449***	***199,999***	***54%***
Auto Train	70%	657	657	0%	4,329	3,777	13%	25,195	19,147	24%
California Zephyr	70%	834	38	95%	4,895	2,092	57%	34,492	10,638	69%
Cardinal	70%	273	122	55%	1,414	462	67%	8,366	3,689	56%
City Of New Orleans	75%	780	65	92%	4,087	806	80%	28,042	17,551	37%
Coast Starlight	70%	1,388	1,127	19%	5,767	3,856	33%	40,003	22,536	44%
Crescent	70%	1,088	214	80%	5,720	1,068	81%	36,224	6,113	83%
Empire Builder	70%	956	605	37%	5,161	1,693	67%	35,881	12,875	64%
Floridian	60%	1,557	1,336	14%	9,557	7,451	22%	52,523	31,672	40%
Lake Shore Ltd	73%	1,076	125	88%	5,682	951	83%	37,545	11,122	70%
Palmetto	70%	1,462	720	51%	5,391	2,375	56%	29,181	8,460	71%
Silver Meteor	70%	1,073	501	53%	5,913	3,778	36%	38,639	14,200	63%
Southwest Chief	60%	0	0	-	3,538	2,975	16%	27,201	21,257	22%
Sunset Ltd	70%	248	51	79%	1,426	433	70%	10,261	4,661	55%
Texas Eagle	70%	818	132	84%	4,829	1,477	69%	32,896	16,078	51%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00187 00000000182 "UNCLASSIFIED" 11/18/2026~~

Train Index Dates Through November 06, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	36,171	612,264	591	224,081	3,701,847	605

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	1,003	161,447	62	10,553	1,033,163	102
INFRASTRUCTURE PLANNED	135	3,803	161,447	236	23,770	1,033,163	230
FLEET RELIABILITY	90	5,046	612,264	82	31,649	3,701,847	85
TRAIN OPERATIONS	424	26,319	612,264	430	158,109	3,701,847	427

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00137 [illegible]

Initial Terminal Performance By Division

[illegible]

Scheduled Departure Date: **11/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/06/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	37	88.1%	1,829	254	86.1%	11,303	1,606	85.8%
Central Division	86.0%	59	1	98.3%	349	17	95.1%	2,119	142	93.3%
East Division	82.0%	159	25	84.3%	938	135	85.6%	5,937	873	85.3%
West Division	86.0%	92	11	88.0%	542	102	81.2%	3,247	591	81.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/06/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	37	88.1%	1,829	254	86.1%	11,303	1,606	85.8%
Central Division	86.0%	59	1	98.3%	349	17	95.1%	2,119	142	93.3%
CDL	95.0%	2	0	100.0%	12	1	91.7%	53	4	92.5%
CHI	86.0%	28	0	100.0%	163	9	94.5%	993	77	92.2%
CHM	-	-	-	-	-	-	-	20	3	85.0%
DAL	-	-	-	-	-	-	-	2	0	100.0%
DET	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	6	0	100.0%	34	2	94.1%
GRR	95.5%	1	0	100.0%	6	0	100.0%	37	0	100.0%
IND	-	-	-	-	-	-	-	4	0	100.0%
KCY	92.0%	2	0	100.0%	12	0	100.0%	75	1	98.7%
MKE	92.0%	6	0	100.0%	35	3	91.4%	216	15	93.1%
MOE	97.5%	2	0	100.0%	12	0	100.0%	67	0	100.0%
MSP	96.5%	1	0	100.0%	6	0	100.0%	37	0	100.0%
NOL	94.5%	4	0	100.0%	26	0	100.0%	152	6	96.1%
OKC	97.0%	1	0	100.0%	6	0	100.0%	36	2	94.4%
PNT	88.0%	3	0	100.0%	18	1	94.4%	98	13	86.7%
PTH	93.0%	1	0	100.0%	6	1	83.3%	37	2	94.6%
QCY	91.0%	2	0	100.0%	11	0	100.0%	73	4	94.5%
SAS	90.5%	1	1	0.0%	6	2	66.7%	36	8	77.8%
STL	89.0%	4	0	100.0%	24	0	100.0%	147	3	98.0%
TAY	-	-	-	-	-	-	-	1	1	0.0%
East Division	82.0%	159	25	84.3%	938	135	85.6%	5,937	873	85.3%
ALB	88.5%	7	1	85.7%	47	4	91.5%	292	24	91.8%
ALX	-	-	-	-	-	-	-	27	14	48.1%
ATL	-	-	-	-	-	-	-	14	4	71.4%
BON	87.5%	5	0	100.0%	30	4	86.7%	185	16	91.4%
BOS	85.5%	12	9	25.0%	67	15	77.6%	460	37	92.0%
BRK	92.5%	5	0	100.0%	30	2	93.3%	185	15	91.9%
BTN	82.0%	1	0	100.0%	6	0	100.0%	37	5	86.5%
CLT	91.5%	5	0	100.0%	30	2	93.3%	179	22	87.7%
GFD	88.0%	2	0	100.0%	12	1	91.7%	74	7	90.5%
GRO	-	-	-	-	6	1	83.3%	17	1	94.1%
HAR	79.5%	13	0	100.0%	73	9	87.7%	428	48	88.8%
HFD	-	-	-	-	-	-	-	44	9	79.5%
JAX	-	-	-	-	-	-	-	18	2	88.9%
LOR	84.0%	1	1	0.0%	6	5	16.7%	35	17	51.4%
MET	-	-	-	-	-	-	-	1	1	0.0%
MIA	89.5%	2	0	100.0%	12	3	75.0%	73	11	84.9%
MTR	79.0%	1	0	100.0%	6	0	100.0%	37	9	75.7%
NFK	84.5%	2	0	100.0%	12	0	100.0%	63	10	84.1%
NFL	93.5%	2	0	100.0%	12	1	91.7%	74	6	91.9%
NFS	-	-	-	-	-	-	-	3	3	0.0%
NHV	78.0%	6	1	83.3%	36	4	88.9%	193	37	80.8%
NPN	93.0%	2	1	50.0%	12	2	83.3%	52	6	88.5%

Information Management

27-FOI-0013

Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/06/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	37	88.1%	1,829	254	86.1%	11,303	1,606	85.8%
East Division	82.0%	159	25	84.3%	938	135	85.6%	5,937	873	85.3%
NYP	75.5%	40	5	87.5%	238	31	87.0%	1,536	249	83.8%
PGH	93.0%	1	0	100.0%	6	0	100.0%	45	10	77.8%
PHL	48.0%	11	3	72.7%	61	30	50.8%	309	146	52.8%
RGH	95.0%	4	0	100.0%	18	2	88.9%	144	23	84.0%
RNK	83.5%	2	0	100.0%	12	2	83.3%	63	8	87.3%
SAB	98.0%	1	0	100.0%	6	0	100.0%	37	0	100.0%
SAV	96.0%	1	0	100.0%	6	0	100.0%	26	0	100.0%
SFA	88.0%	1	1	0.0%	6	5	16.7%	35	10	71.4%
SPG	92.5%	7	1	85.7%	42	1	97.6%	210	11	94.8%
TWO	73.0%	1	1	0.0%	6	2	66.7%	34	10	70.6%
WAS	84.0%	24	1	95.8%	140	9	93.6%	1,007	102	89.9%
West Division	86.0%	92	11	88.0%	542	102	81.2%	3,247	591	81.8%
ARN	92.0%	1	0	100.0%	6	0	100.0%	37	3	91.9%
BFD	79.0%	7	0	100.0%	42	11	73.8%	251	63	74.9%
EMY	72.0%	1	0	100.0%	6	1	83.3%	41	16	61.0%
EUG	86.5%	2	1	50.0%	12	1	91.7%	71	4	94.4%
FNO	-	-	-	-	-	-	-	5	4	20.0%
GAC	-	-	-	-	-	-	-	3	2	33.3%
GTA	90.0%	6	2	66.7%	36	12	66.7%	167	67	59.9%
IRV	-	-	-	-	-	-	-	1	0	100.0%
LAX	89.5%	11	2	81.8%	62	14	77.4%	362	48	86.7%
OKJ	74.5%	13	2	84.6%	74	20	73.0%	437	135	69.1%
PDX	86.0%	5	0	100.0%	29	3	89.7%	184	16	91.3%
SAC	88.5%	16	1	93.8%	92	8	91.3%	548	52	90.5%
SAN	90.5%	12	1	91.7%	75	21	72.0%	434	96	77.9%
SEA	85.0%	8	2	75.0%	48	6	87.5%	295	35	88.1%
SJC	89.0%	7	0	100.0%	42	5	88.1%	258	40	84.5%
SLO	90.0%	-	-	-	-	-	-	42	8	81.0%
SPK	90.0%	1	-	100.0%	6	0	100.0%	36	0	100.0%
VAC	97.0%	2	0	100.0%	12	0	100.0%	70	1	98.6%
VNC	-	-	-	-	-	-	-	5	1	80.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		2	0	100.0%	15	3	80.0%	3	0	100.0%	16	6	62.5%
2	230	3	1	66.7%	16	2	87.5%	3	1	66.7%	16	6	62.5%
5		6	0	100.0%	36	2	94.4%	6	2	66.7%	36	10	72.2%
6		6	1	83.3%	36	14	61.1%	6	4	33.3%	36	13	63.9%
7	85	6	1	83.3%	36	3	91.7%	6	1	83.3%	36	3	91.7%
8	50	6	1	83.3%	36	8	77.8%	6	3	50.0%	36	19	47.2%
11	34	6	1	83.3%	37	5	86.5%	5	5	0.0%	36	25	30.6%
14	120	6	2	66.7%	37	11	70.3%	6	5	16.7%	37	24	35.1%
19		6	2	66.7%	37	8	78.4%	6	2	66.7%	36	8	77.8%
20		6	0	100.0%	37	3	91.9%	6	0	100.0%	37	4	89.2%
21		6	0	100.0%	37	2	94.6%	6	1	83.3%	36	14	61.1%
22		6	2	66.7%	37	9	75.7%	6	2	66.7%	37	20	45.9%
23		6	0	100.0%	34	0	100.0%	6	0	100.0%	34	6	82.4%
24		6	0	100.0%	33	0	100.0%	6	1	83.3%	33	7	78.8%
25		6	0	100.0%	33	0	100.0%	6	0	100.0%	33	7	78.8%
26		6	0	100.0%	34	0	100.0%	6	1	83.3%	34	9	73.5%
27	101	6	3	50.0%	36	3	91.7%	5	2	60.0%	35	8	77.1%
28		5	0	100.0%	35	4	88.6%	5	0	100.0%	35	6	82.9%
40	164	6	2	66.7%	37	12	67.6%	6	6	0.0%	37	20	45.9%
41	81	6	2	66.7%	37	5	86.5%	6	6	0.0%	37	21	43.2%
42		6	0	100.0%	37	3	91.9%	6	1	83.3%	37	12	67.6%
43		6	1	83.3%	37	9	75.7%	6	1	83.3%	36	13	63.9%
48		6	0	100.0%	37	4	89.2%	6	1	83.3%	37	13	64.9%
49		6	0	100.0%	37	5	86.5%	6	1	83.3%	37	7	81.1%
50		2	0	100.0%	16	0	100.0%	3	1	66.7%	16	7	56.3%
52	301	6	5	16.7%	35	10	71.4%	6	4	33.3%	35	20	42.9%
53	217	6	5	16.7%	35	17	51.4%	6	6	0.0%	35	31	11.4%
55		5	0	100.0%	27	0	100.0%	5	1	80.0%	27	6	77.8%
56		5	0	100.0%	27	3	88.9%	5	2	60.0%	27	6	77.8%
58		6	0	100.0%	37	1	97.3%	6	1	83.3%	37	27	27.0%
59		6	0	100.0%	37	2	94.6%	6	1	83.3%	37	23	37.8%
63	43	6	1	83.3%	37	13	64.9%	6	6	0.0%	37	34	8.1%
64	39	6	2	66.7%	37	13	64.9%	6	5	16.7%	37	21	43.2%
66	191	6	1	83.3%	36	5	86.1%	6	3	50.0%	36	8	77.8%
67	19	5	1	80.0%	25	5	80.0%	5	1	80.0%	26	6	76.9%
68		6	0	100.0%	37	9	75.7%	6	0	100.0%	37	7	81.1%
69		6	1	83.3%	37	11	70.3%	6	0	100.0%	37	2	94.6%
71	16	6	0	100.0%	37	2	94.6%	5	4	20.0%	36	10	72.2%
72	68	6	2	66.7%	37	7	81.1%	5	3	40.0%	36	6	83.3%
73	28	6	1	83.3%	32	5	84.4%	6	4	33.3%	32	17	46.9%
74	24	6	0	100.0%	32	6	81.3%	6	3	50.0%	32	16	50.0%
75	49	6	1	83.3%	37	3	91.9%	6	2	66.7%	35	9	74.3%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	32	6	0	100.0%	36	5	86.1%	6	4	33.3%	35	16	54.3%
77	23	6	1	83.3%	37	5	86.5%	6	3	50.0%	37	15	59.5%
78		6	0	100.0%	37	4	89.2%	6	2	66.7%	38	9	76.3%
79	25	6	0	100.0%	37	6	83.8%	6	5	16.7%	37	17	54.1%
80	55	6	0	100.0%	37	0	100.0%	6	4	33.3%	37	12	67.6%
89	37	6	0	100.0%	26	1	96.2%	6	5	16.7%	26	15	42.3%
90		6	0	100.0%	26	0	100.0%	6	4	33.3%	26	11	57.7%
94		6	0	100.0%	26	4	84.6%	6	2	66.7%	26	5	80.8%
97	53	6	2	66.7%	37	12	67.6%	6	6	0.0%	37	11	70.3%
98		6	1	83.3%	37	4	89.2%	6	2	66.7%	37	14	62.2%
230		6	0	100.0%	37	1	97.3%	6	0	100.0%	37	1	97.3%
232		6	0	100.0%	37	1	97.3%	6	1	83.3%	37	3	91.9%
233		6	1	83.3%	37	13	64.9%	6	2	66.7%	37	14	62.2%
234		6	0	100.0%	37	0	100.0%	6	0	100.0%	37	1	97.3%
235		6	2	66.7%	37	6	83.8%	6	2	66.7%	37	11	70.3%
236	18	6	0	100.0%	37	0	100.0%	6	1	83.3%	37	7	81.1%
237	90	6	2	66.7%	37	6	83.8%	6	1	83.3%	37	11	70.3%
238		6	3	50.0%	37	7	81.1%	6	1	83.3%	37	4	89.2%
239	21	6	1	83.3%	36	6	83.3%	6	2	66.7%	36	4	88.9%
240		6	0	100.0%	37	4	89.2%	5	0	100.0%	36	2	94.4%
241	20	6	1	83.3%	37	7	81.1%	6	2	66.7%	37	10	73.0%
243		6	0	100.0%	37	5	86.5%	6	0	100.0%	37	1	97.3%
244		6	0	100.0%	37	0	100.0%	6	1	83.3%	37	11	70.3%
245		6	0	100.0%	37	5	86.5%	6	0	100.0%	37	5	86.5%
280	46	6	0	100.0%	37	3	91.9%	6	2	66.7%	37	14	62.2%
281		6	0	100.0%	37	5	86.5%	6	3	50.0%	37	6	83.8%
283	91	6	1	83.3%	37	2	94.6%	6	3	50.0%	37	7	81.1%
284	70	6	1	83.3%	37	3	91.9%	6	2	66.7%	37	5	86.5%
290	21	6	0	100.0%	37	5	86.5%	6	5	16.7%	36	17	52.8%
291		6	0	100.0%	37	17	54.1%	6	1	83.3%	37	8	78.4%
300		6	0	100.0%	36	1	97.2%	6	0	100.0%	36	7	80.6%
301		6	0	100.0%	37	0	100.0%	6	0	100.0%	37	4	89.2%
302		6	0	100.0%	37	1	97.3%	6	1	83.3%	37	9	75.7%
305		6	0	100.0%	37	1	97.3%	6	2	66.7%	37	14	62.2%
306		6	0	100.0%	37	0	100.0%	6	0	100.0%	37	10	73.0%
307		6	0	100.0%	37	1	97.3%	6	2	66.7%	37	12	67.6%
311		6	0	100.0%	37	1	97.3%	6	0	100.0%	37	4	89.2%
316		6	0	100.0%	37	0	100.0%	6	2	66.7%	37	11	70.3%
318		6	0	100.0%	37	1	97.3%	6	4	33.3%	37	16	56.8%
319		6	0	100.0%	37	0	100.0%	6	3	50.0%	36	26	27.8%
329		5	0	100.0%	27	1	96.3%	5	0	100.0%	27	1	96.3%
330		5	0	100.0%	32	0	100.0%	5	0	100.0%	31	1	96.8%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		6	0	100.0%	37	2	94.6%	6	0	100.0%	35	1	97.1%
332	18	6	0	100.0%	37	3	91.9%	6	2	66.7%	37	3	91.9%
334		6	0	100.0%	37	1	97.3%	6	0	100.0%	37	1	97.3%
335		6	0	100.0%	37	6	83.8%	5	0	100.0%	36	3	91.7%
336		6	0	100.0%	36	0	100.0%	6	3	50.0%	36	4	88.9%
337		6	2	66.7%	36	3	91.7%	6	2	66.7%	36	3	91.7%
338		6	2	66.7%	37	6	83.8%	6	2	66.7%	37	11	70.3%
339		6	1	83.3%	37	9	75.7%	6	1	83.3%	36	7	80.6%
341		6	0	100.0%	36	5	86.1%	6	0	100.0%	36	2	94.4%
342		6	1	83.3%	37	5	86.5%	6	1	83.3%	36	4	88.9%
350		6	0	100.0%	34	2	94.1%	6	1	83.3%	32	13	59.4%
351		6	0	100.0%	32	4	87.5%	6	2	66.7%	30	7	76.7%
352		6	1	83.3%	33	5	84.8%	6	3	50.0%	32	13	59.4%
353		6	0	100.0%	34	4	88.2%	6	1	83.3%	33	5	84.8%
354		6	0	100.0%	34	6	82.4%	6	0	100.0%	33	11	66.7%
355		6	1	83.3%	33	6	81.8%	6	1	83.3%	32	9	71.9%
364		6	0	100.0%	37	1	97.3%	6	1	83.3%	37	9	75.7%
365		6	1	83.3%	37	2	94.6%	6	2	66.7%	37	13	64.9%
370		6	0	100.0%	37	0	100.0%	6	0	100.0%	37	4	89.2%
371		6	0	100.0%	37	0	100.0%	6	1	83.3%	37	1	97.3%
380		5	0	100.0%	36	2	94.4%	5	0	100.0%	36	10	72.2%
381		6	0	100.0%	37	0	100.0%	6	1	83.3%	37	8	78.4%
382		6	0	100.0%	37	2	94.6%	6	0	100.0%	37	7	81.1%
383		6	0	100.0%	37	0	100.0%	5	2	60.0%	36	14	61.1%
390		6	1	83.3%	36	6	83.3%	6	1	83.3%	36	10	72.2%
391		6	0	100.0%	37	2	94.6%	6	0	100.0%	37	6	83.8%
392		6	0	100.0%	37	1	97.3%	6	1	83.3%	37	24	35.1%
393		6	0	100.0%	36	4	88.9%	6	0	100.0%	36	18	50.0%
417		5	0	100.0%	27	5	81.5%	5	0	100.0%	26	6	76.9%
425	22	5	0	100.0%	27	0	100.0%	5	1	80.0%	27	4	85.2%
449	23	6	1	83.3%	34	2	94.1%	6	3	50.0%	34	7	79.4%
470	40	5	0	100.0%	27	3	88.9%	5	2	60.0%	27	10	63.0%
471		5	0	100.0%	27	7	74.1%	5	0	100.0%	27	7	74.1%
473		5	1	80.0%	27	3	88.9%	5	0	100.0%	27	0	100.0%
474	22	5	1	80.0%	27	8	70.4%	5	1	80.0%	26	9	65.4%
475		5	0	100.0%	27	0	100.0%	5	0	100.0%	27	2	92.6%
478		5	1	80.0%	27	3	88.9%	5	1	80.0%	27	2	92.6%
479		5	1	80.0%	27	4	85.2%	5	1	80.0%	26	9	65.4%
486	25	5	0	100.0%	27	3	88.9%	5	2	60.0%	26	5	80.8%
490		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
494		5	0	100.0%	28	3	89.3%	5	1	80.0%	27	6	77.8%
495		5	0	100.0%	27	0	100.0%	5	0	100.0%	27	1	96.3%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
500		6	0	100.0%	37	2	94.6%	6	3	50.0%	37	8	78.4%
502		6	0	100.0%	37	1	97.3%	6	2	66.7%	37	8	78.4%
503	52	6	0	100.0%	37	7	81.1%	6	2	66.7%	37	16	56.8%
504		6	0	100.0%	35	1	97.1%	6	2	66.7%	35	15	57.1%
505		6	1	83.3%	37	2	94.6%	6	3	50.0%	37	9	75.7%
506		6	1	83.3%	37	3	91.9%	6	1	83.3%	36	7	80.6%
507		6	2	66.7%	37	5	86.5%	6	2	66.7%	35	13	62.9%
508		6	1	83.3%	37	4	89.2%	6	0	100.0%	37	12	67.6%
509	65	6	1	83.3%	37	2	94.6%	6	5	16.7%	37	19	48.6%
511	No OS	6	0	100.0%	37	1	97.3%	6	1	83.3%	37	5	86.5%
516	43	6	0	100.0%	35	4	88.6%	6	3	50.0%	34	19	44.1%
517	20	6	0	100.0%	37	2	94.6%	6	3	50.0%	37	16	56.8%
518	20	6	2	66.7%	37	5	86.5%	6	5	16.7%	36	19	47.2%
519		6	0	100.0%	35	0	100.0%	6	1	83.3%	35	6	82.9%
520		5	0	100.0%	27	0	100.0%	5	1	80.0%	27	1	96.3%
521		5	0	100.0%	27	1	96.3%	5	1	80.0%	25	5	80.0%
522		5	2	60.0%	27	9	66.7%	4	1	75.0%	26	4	84.6%
523		5	0	100.0%	27	4	85.2%	5	2	60.0%	26	8	69.2%
524		5	0	100.0%	27	3	88.9%	5	1	80.0%	26	5	80.8%
525		5	0	100.0%	27	3	88.9%	5	0	100.0%	25	2	92.0%
526		5	2	60.0%	27	9	66.7%	5	0	100.0%	25	2	92.0%
527	25	5	0	100.0%	27	1	96.3%	5	2	60.0%	27	8	70.4%
528		5	0	100.0%	27	3	88.9%	5	0	100.0%	27	8	70.4%
529		5	0	100.0%	27	2	92.6%	5	0	100.0%	27	10	63.0%
530		5	1	80.0%	27	5	81.5%	5	1	80.0%	27	6	77.8%
531		5	0	100.0%	27	1	96.3%	5	0	100.0%	26	2	92.3%
532		5	0	100.0%	27	9	66.7%	5	0	100.0%	26	1	96.2%
534		5	1	80.0%	27	5	81.5%	5	0	100.0%	27	0	100.0%
535		5	0	100.0%	27	0	100.0%	5	0	100.0%	26	2	92.3%
536	18	5	0	100.0%	27	9	66.7%	5	1	80.0%	27	2	92.6%
537		5	1	80.0%	26	2	92.3%	4	0	100.0%	24	1	95.8%
538		5	0	100.0%	27	2	92.6%	5	1	80.0%	27	2	92.6%
539		5	1	80.0%	27	6	77.8%	5	1	80.0%	27	9	66.7%
540		5	0	100.0%	26	3	88.5%	5	1	80.0%	25	1	96.0%
541	17	5	1	80.0%	27	4	85.2%	5	1	80.0%	27	5	81.5%
542		5	2	60.0%	27	6	77.8%	5	0	100.0%	26	2	92.3%
543		5	1	80.0%	27	5	81.5%	5	3	40.0%	27	13	51.9%
544		5	0	100.0%	27	6	77.8%	5	0	100.0%	27	6	77.8%
545		5	0	100.0%	26	0	100.0%	5	0	100.0%	25	0	100.0%
547		5	1	80.0%	27	3	88.9%	5	1	80.0%	27	6	77.8%
548		5	0	100.0%	27	1	96.3%	5	0	100.0%	27	1	96.3%
549		5	1	80.0%	27	4	85.2%	5	2	60.0%	26	5	80.8%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
550		5	2	60.0%	27	5	81.5%	5	1	80.0%	27	5	81.5%
551		5	0	100.0%	27	2	92.6%	5	0	100.0%	27	4	85.2%
562	37	6	1	83.3%	35	3	91.4%	6	6	0.0%	35	22	37.1%
564	33	6	0	100.0%	35	0	100.0%	6	5	16.7%	35	22	37.1%
566	36	6	2	66.7%	35	3	91.4%	5	5	0.0%	32	19	40.6%
567	41	5	0	100.0%	33	4	87.9%	5	3	40.0%	32	10	68.8%
572	60	6	2	66.7%	32	9	71.9%	5	5	0.0%	29	21	27.6%
573	18	6	2	66.7%	35	5	85.7%	6	5	16.7%	34	17	50.0%
579	20	6	3	50.0%	32	5	84.4%	4	4	0.0%	29	19	34.5%
580		6	1	83.3%	35	3	91.4%	6	3	50.0%	34	15	55.9%
581	40	6	2	66.7%	35	14	60.0%	6	4	33.3%	33	24	27.3%
584	65	6	1	83.3%	35	4	88.6%	6	6	0.0%	33	27	18.2%
587	42	6	1	83.3%	34	7	79.4%	6	5	16.7%	32	21	34.4%
588	39	6	2	66.7%	32	6	81.3%	5	3	40.0%	29	17	41.4%
591	18	6	0	100.0%	35	5	85.7%	6	2	66.7%	35	21	40.0%
593	33	5	3	40.0%	28	12	57.1%	5	3	40.0%	25	11	56.0%
600		6	0	100.0%	35	1	97.1%	6	1	83.3%	35	5	85.7%
601	25	5	3	40.0%	27	12	55.6%	5	1	80.0%	27	5	81.5%
605		5	2	60.0%	27	12	55.6%	5	0	100.0%	26	1	96.2%
607		6	0	100.0%	35	2	94.3%	6	0	100.0%	35	1	97.1%
609		5	1	80.0%	27	3	88.9%	5	0	100.0%	26	0	100.0%
622		5	1	80.0%	25	3	88.0%	5	1	80.0%	25	2	92.0%
626		6	2	66.7%	35	7	80.0%	6	0	100.0%	35	5	85.7%
640		5	0	100.0%	27	1	96.3%	5	0	100.0%	27	4	85.2%
641		5	1	80.0%	27	5	81.5%	5	1	80.0%	27	3	88.9%
642		5	0	100.0%	27	1	96.3%	5	0	100.0%	27	2	92.6%
643		6	3	50.0%	35	11	68.6%	6	0	100.0%	35	3	91.4%
644		5	1	80.0%	27	3	88.9%	5	0	100.0%	27	7	74.1%
645		6	3	50.0%	35	12	65.7%	6	0	100.0%	34	4	88.2%
646		5	0	100.0%	27	6	77.8%	5	1	80.0%	27	3	88.9%
647		6	0	100.0%	34	4	88.2%	6	0	100.0%	33	1	97.0%
648		5	1	80.0%	27	1	96.3%	5	0	100.0%	27	1	96.3%
649		6	0	100.0%	35	2	94.3%	6	1	83.3%	35	5	85.7%
650		6	1	83.3%	35	5	85.7%	6	1	83.3%	35	3	91.4%
651	16	5	1	80.0%	27	1	96.3%	5	3	40.0%	27	7	74.1%
652		6	0	100.0%	35	3	91.4%	6	0	100.0%	35	2	94.3%
653		5	4	20.0%	26	11	57.7%	5	1	80.0%	26	4	84.6%
654		5	0	100.0%	26	5	80.8%	5	0	100.0%	26	3	88.5%
655		6	1	83.3%	35	4	88.6%	6	0	100.0%	35	2	94.3%
656		6	2	66.7%	35	7	80.0%	6	0	100.0%	35	5	85.7%
657		5	2	60.0%	27	10	63.0%	5	1	80.0%	27	2	92.6%
658		6	1	83.3%	34	2	94.1%	6	0	100.0%	34	1	97.1%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680		5	0	100.0%	27	4	85.2%	5	0	100.0%	27	2	92.6%
681		5	0	100.0%	27	0	100.0%	5	2	60.0%	26	12	53.8%
682	21	5	1	80.0%	27	4	85.2%	5	1	80.0%	27	5	81.5%
683	47	5	0	100.0%	27	0	100.0%	5	3	40.0%	27	19	29.6%
684		5	0	100.0%	27	2	92.6%	5	0	100.0%	27	9	66.7%
685		5	1	80.0%	27	4	85.2%	5	2	60.0%	27	9	66.7%
686		5	0	100.0%	27	1	96.3%	5	2	60.0%	27	11	59.3%
687		5	2	60.0%	27	7	74.1%	5	3	40.0%	27	11	59.3%
688	20	5	0	100.0%	27	1	96.3%	5	2	60.0%	27	8	70.4%
689		1	0	100.0%	9	0	100.0%	1	0	100.0%	10	2	80.0%
701		6	2	66.7%	37	6	83.8%	6	2	66.7%	37	9	75.7%
702		6	0	100.0%	37	2	94.6%	6	1	83.3%	37	15	59.5%
703		6	2	66.7%	37	12	67.6%	6	3	50.0%	37	9	75.7%
704		6	2	66.7%	37	8	78.4%	6	1	83.3%	37	5	86.5%
710		6	3	50.0%	37	9	75.7%	6	1	83.3%	37	8	78.4%
711		6	0	100.0%	37	6	83.8%	6	1	83.3%	32	5	84.4%
712		6	2	66.7%	37	12	67.6%	6	4	33.3%	37	17	54.1%
713		6	2	66.7%	34	12	64.7%	6	1	83.3%	29	7	75.9%
714		6	4	33.3%	37	21	43.2%	6	4	33.3%	36	20	44.4%
715	16	6	0	100.0%	37	6	83.8%	5	3	40.0%	35	18	48.6%
716		6	1	83.3%	36	16	55.6%	6	2	66.7%	35	9	74.3%
717		6	2	66.7%	37	16	56.8%	6	3	50.0%	34	15	55.9%
718		6	5	16.7%	37	25	32.4%	6	2	66.7%	37	14	62.2%
719		6	3	50.0%	37	9	75.7%	6	1	83.3%	37	8	78.4%
757		6	0	100.0%	34	2	94.1%	6	0	100.0%	34	14	58.8%
761		6	0	100.0%	35	0	100.0%	6	0	100.0%	35	11	68.6%
765	60	6	0	100.0%	35	0	100.0%	6	4	33.3%	35	23	34.3%
769	36	6	0	100.0%	35	2	94.3%	6	6	0.0%	35	27	22.9%
770	20	6	0	100.0%	35	3	91.4%	6	6	0.0%	34	25	26.5%
774	50	6	3	50.0%	35	16	54.3%	6	5	16.7%	34	29	14.7%
777	18	6	1	83.3%	35	3	91.4%	6	5	16.7%	34	25	26.5%
782		6	2	66.7%	35	23	34.3%	6	4	33.3%	34	24	29.4%
785	37	6	4	33.3%	35	21	40.0%	6	3	50.0%	35	21	40.0%
786	26	6	1	83.3%	35	10	71.4%	6	4	33.3%	30	18	40.0%
790	39	6	1	83.3%	35	3	91.4%	6	5	16.7%	35	23	34.3%
794	76	6	5	16.7%	35	19	45.7%	7	5	28.6%	36	20	44.4%
794		6	5	16.7%	35	19	45.7%	7	5	28.6%	36	20	44.4%
821		6	0	100.0%	36	2	94.4%	6	4	33.3%	36	28	22.2%
822		6	0	100.0%	36	2	94.4%	6	4	33.3%	36	29	19.4%
1082	92	5	0	100.0%	20	2	90.0%	5	3	40.0%	20	6	70.0%
1087	67	5	0	100.0%	20	1	95.0%	5	2	60.0%	19	3	84.2%
1088	47	5	0	100.0%	20	2	90.0%	5	4	20.0%	20	7	65.0%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1099	185	5	1	80.0%	20	1	95.0%	5	3	40.0%	20	8	60.0%
1103		5	2	60.0%	20	10	50.0%	5	1	80.0%	20	4	80.0%
1107		5	3	40.0%	20	8	60.0%	4	0	100.0%	19	3	84.2%
1109	94	5	0	100.0%	20	1	95.0%	5	1	80.0%	20	2	90.0%
1111		5	0	100.0%	20	2	90.0%	5	1	80.0%	20	1	95.0%
1116		5	1	80.0%	20	3	85.0%	4	1	75.0%	19	2	89.5%
1118		5	0	100.0%	20	2	90.0%	5	1	80.0%	20	1	95.0%
1124	95	5	1	80.0%	18	3	83.3%	5	1	80.0%	18	6	66.7%
1126		5	1	80.0%	20	1	95.0%	5	0	100.0%	20	4	80.0%
1127		5	1	80.0%	20	4	80.0%	5	0	100.0%	20	1	95.0%
1128		5	0	100.0%	20	2	90.0%	4	1	75.0%	19	2	89.5%
1129		5	0	100.0%	20	1	95.0%	5	0	100.0%	20	3	85.0%
1135	82	5	2	60.0%	20	4	80.0%	5	3	40.0%	20	15	25.0%
1138		5	0	100.0%	19	2	89.5%	5	0	100.0%	19	3	84.2%
1140		5	1	80.0%	20	5	75.0%	5	2	60.0%	20	3	85.0%
1142	91	5	2	60.0%	20	6	70.0%	5	1	80.0%	20	5	75.0%
1143		5	0	100.0%	20	0	100.0%	5	2	60.0%	20	7	65.0%
1144		5	5	0.0%	20	17	15.0%	5	1	80.0%	20	5	75.0%
1146		5	1	80.0%	20	4	80.0%	5	2	60.0%	20	3	85.0%
1147		5	0	100.0%	20	0	100.0%	5	2	60.0%	20	6	70.0%
1150	79	5	4	20.0%	20	14	30.0%	5	4	20.0%	20	6	70.0%
1151		5	2	60.0%	20	7	65.0%	5	2	60.0%	20	10	50.0%
1152	20	5	0	100.0%	20	2	90.0%	5	2	60.0%	20	5	75.0%
1153		5	0	100.0%	20	0	100.0%	5	1	80.0%	20	1	95.0%
1155	17	5	0	100.0%	19	2	89.5%	5	1	80.0%	19	6	68.4%
1156		5	1	80.0%	17	3	82.4%	5	3	40.0%	17	12	29.4%
1160	70	5	1	80.0%	20	1	95.0%	5	4	20.0%	20	11	45.0%
1161	128	5	1	80.0%	20	1	95.0%	5	4	20.0%	20	15	25.0%
1162	57	5	0	100.0%	20	0	100.0%	5	5	0.0%	20	13	35.0%
1163	152	5	1	80.0%	20	2	90.0%	5	4	20.0%	20	15	25.0%
1164	61	5	1	80.0%	19	2	89.5%	5	4	20.0%	19	9	52.6%
1165	53	5	2	60.0%	20	2	90.0%	5	3	40.0%	20	10	50.0%
1167	20	5	3	40.0%	20	7	65.0%	5	4	20.0%	20	9	55.0%
1168	33	5	0	100.0%	20	4	80.0%	5	1	80.0%	20	5	75.0%
1169	30	5	1	80.0%	19	4	78.9%	4	3	25.0%	18	5	72.2%
1194		5	1	80.0%	20	3	85.0%	5	2	60.0%	20	4	80.0%
1195	159	5	0	100.0%	19	0	100.0%	5	1	80.0%	18	2	88.9%
1333	21	6	1	83.3%	37	4	89.2%	6	4	33.3%	37	14	62.2%
1340		6	0	100.0%	37	0	100.0%	6	0	100.0%	37	4	89.2%
2101		5	0	100.0%	20	1	95.0%	5	0	100.0%	20	1	95.0%
2103		5	0	100.0%	27	1	96.3%	5	0	100.0%	27	2	92.6%
2105		5	1	80.0%	27	2	92.6%	5	2	60.0%	27	3	88.9%

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2106		5	0	100.0%	20	0	100.0%	5	1	80.0%	20	3	85.0%
2114		5	0	100.0%	20	3	85.0%	5	1	80.0%	20	4	80.0%
2115	17	5	0	100.0%	27	0	100.0%	5	2	60.0%	26	5	80.8%
2116		5	0	100.0%	27	2	92.6%	5	2	60.0%	27	2	92.6%
2118		5	0	100.0%	27	3	88.9%	5	2	60.0%	26	6	76.9%
2120		5	0	100.0%	27	3	88.9%	5	0	100.0%	27	3	88.9%
2122		5	1	80.0%	20	3	85.0%	5	1	80.0%	20	3	85.0%
2123		5	1	80.0%	27	3	88.9%	5	2	60.0%	27	4	85.2%
2133		5	0	100.0%	20	0	100.0%	5	1	80.0%	20	3	85.0%
2148		5	0	100.0%	20	1	95.0%	5	1	80.0%	19	3	84.2%
2149	170	5	0	100.0%	20	2	90.0%	5	5	0.0%	20	19	5.0%
2150	24	5	0	100.0%	27	0	100.0%	5	5	0.0%	26	16	38.5%
2151	147	5	1	80.0%	27	1	96.3%	5	4	20.0%	27	17	37.0%
2152		5	0	100.0%	27	1	96.3%	5	1	80.0%	27	3	88.9%
2155	18	5	1	80.0%	27	2	92.6%	5	2	60.0%	26	4	84.6%

Amtrak Endpoint OTP Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2115	WAS	17	SMW	15	SMW	7	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 2 track a/c 3 track o/s between Ragan & Davis
2149	WAS	170	TRS	93	TRS	77	PVD-PVD	AM	Trespasser strike, Milepost, PVD, PVD, HELD IN PVD UNTIL TRESPASSER STRIKE WAS CLEARED, TRK 1 IS CLEAR.
2150	BOS	24	DSR	21	HLD	8	NYP-NYP	AM	Passenger and/or baggage, BOARDING
2151	WAS	147	TRS	94	TRS	80	BOS-BOS	AM	Trespasser strike, Milepost, BOS, BOS, DP BOS 80" LATE DUE TO THE TRESPASSER STRIKE, MP 170
2155	WAS	5							
66	BOS	191	WTR	68	DMW	45	NLC-MYS	AM	Held for or routed around MW work or equipment, Control Point, XGX, AM66 held for AM1195 and AM2151 to clear run around OOS trk 1
67	NPN	19	SMW	35	CTI	14	BRP-STM	MN	Follow MN, Control Point, 254
425	SPG	22							
470	SPG	40	CON	35	CON	35	NHV-NHV	AM	Hold for connecting train, DP NHV 35" LATE A/C OF LATE AM1160.
474	SPG	22	SVS	22	SVS	22	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, late release from the yard, train master Malcolm Green decided to not hold AM474 to connection with AM1082
486	GFD	25	CON	24	CON	24	NHV-NHV	AM	Hold for connecting train, late connection of AM1164
1082	BOS	92	WTR	27	WTR	10	KIN-PVD	AM	Wet / slippery rail, Milepost w/Letters, KIN, PVD, wheel slip
1087	NFK	67	PTI	94	PTI	36	PVD-WLY	AM	Follow, 1163/1099, Control Point, CRANSTON, STOPPED BEHIND TRAINS 1099 AND 1163
1088	BOS	47	PTI	38	DSR	16	STM-BRP	MN	Per bulletin Milepost, 40.4, 41.7, 30, 2, Milepost, 41.7, 42.0, 15, 2
1099	NPN	185	WTR	124	WTR	69	PVD-KIN	AM	Wet / slippery rail, Other, MP 166 AND MP 163, SLIPPERY RAIL, MULTIPLE ATTEMPTS TO CLIMB GRADE WEST OF STONY. NO SAND IN ENGINE PER ENGR
1109	WAS	94	ENG	76	ENG	43	XHM-PHL	AM	Other electrical failure, 670|EX|ES, Train experienced MCB issues between Lehigh and Clearfield.
1124	PHL	95	PTI	40	PTI	40	WDB-ALX	CS	Follow P092, Milepost, 99.5, 104.3

Amtrak Endpoint OTP Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1135	WAS	82	DSR	37	ITI	22	BOS-BOS	AM	Late departure at initial terminal due to late arrival of inbound equipment, 1150, DP BOS 11" LATE A/C OF LATE TURN OF AM1150
1142	NYP	91	POL	76	POL	76	WAS-WAS	AM	Removal of passenger by police, PAX MEDICAL EMERGENCY
1150	BOS	79	PTI	47	PTI	23	NLC-NLC	AM	Follow, 66, Milepost, XSS, XM6, SIGNALS OF AM66 AHEAD
1152	NYP	20	SMW	24	SMW	9	XPV-NRK	AM	Diversions around M/W work, Control Point, ., OPERATED "A" TRACK FOR 2150 AHEAD ON 1TRK A/C 3TRK O/S BACON TO DAVIS.
1155	NFK	17	FTI	21	WTR	9	X3V-NFK	NS	Flash flood warning Milepost, 14.6, 1.5
1160	BOS	70	SMW	28	SMW	23	NHV-XGX	AM	Diversions around M/W work, Other, XGX, HELD AT GROTON FOR AM1099, AM1161 & AM1087 TO CLEAR
1161	WAS	128	WTR	54	WTR	45	PVD-KIN	AM	Wet / slippery rail, Other, DAVISVILLE, STOPPED AT DAVISVILLE BEHIND TRAIN 1099 A/C SLIPPERY RAIL
1162	BOS	57	WTR	27	ENG	10	PHL-XHM	AM	Other electrical failure, 649|EX|ES, Train went into emergency at Girard a/c hose leaking air. Had to reattach.
1163	WAS	152	WTR	47	CAR	17	BOS-BOS	AM	Door, 1163, DP BOS 17" LATE DUE TO DOOR ISSUES.
1164	BOS	61	FTI	45	FTI	26	WBG-RVM	CS	Meet Train running short on time, Control Point, East Providence Forge, L21605
1165	WAS	53	WTR	27	ITI	11	BOS-BOS	AM	Late departure at initial terminal due to late arrival of inbound equipment, 1160, late turn of AM1160 and delayed due to Tower 1 project BOS
1167	PHL	20	DSR	25	ITI	9	BOS-BOS	AM	Late departure at initial terminal due to late arrival of inbound equipment, 1162, late turn of AM1162
1168	BOS	33	CTI	15	SYS	14	NYP-NYP	AM	Other late crew, HELD FOR INBOUND CREW OFF AM1135
1169	PHL	11							
1195	WAS	159	TRS	70	TRS	50	PVD-PVD	AM	Trespasser strike, Milepost, PVD, PVD, HELD IN PVD UNTIL TRESPASSER STRIKE WAS CLEARED, TRK 1 IS CLEAR.
52	LOR	301	ITI	249	ITI	249	SFA-SFA	FR	Late departure at initial terminal due to late arrival of inbound equipment 53
53	SFA	217	FTI	122	MBO	35	XOU-XSA	CS	Stop and Check Bridge, Ashley River

Amtrak Endpoint OTP Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
79	CLT	25	FTI	21	FTI	17	WLN-SSM	CS	Meet CSX L607, Control Point, S. Contentnea
80	NYP	55	RTE	35	RTE	33	FBG-QAN	CS	Dispatcher hold Had to do reverse move to track 2 Po 92 broke down, Other, CFP77.1
601	HAR	25	WTR	22	WTR	8	ELT-MID	AM	Wet / slippery rail, Control Point, .
651	HAR	16	CTI	16	CTI	6	PHL-ARD	AM	Per Schedule
682	BON	21	DMW	12	DMW	9	SAO-WEM	CS	Unable to contact dispatcher / MW foreman Other, PLD 41.7
683	BRK	47	PTI	34	PTI	19	WEM-SAO	CS	Meet 686, Control Point, Wells
688	BON	20	DSR	6	PTI	5	WEM-DOV	CS	Meet Amt 685, Control Point, varney
63	TWO	43	WTR	27	WTR	27	ALB-SDY	AM	Wet / slippery rail Engine stalled climbing up hill had to shove back to get a better start up hill due to no sand in engine, Milepost, 144.0, 146.0
64	NYP	39	FTI	24	SVS	19	SDY-ALB	AM	Scheduled wyeing of the train Control Point, lab
236	NYP	18	CTI	16	CTI	13	POU-CRT	MN	Follow man, 846, Control Point, 61 35
237	ALB	90	CTI	31	ITI	30	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 290, LATE TURN OFF AM290
239	ALB	21	PTI	24	PTI	11	RHI-HUD	AM	Wait for station track Following 237, 237, Control Point, 114
241	ALB	20	MBO	6	MBO	6	NYP-XSD	AM	For maritime traffic, Other, SPUYTENDUYVIL BRIDGE
280	NYP	46	ENG	39	ENG	31	ALB-ALB	AM	Set out defective locomotive 9707
283	NFL	91	FTI	118	FTI	43	ROC-BUF	CS	Follow Crossed over behind another freight that we followed all the way to Depew, csx unknown, Control Point, 382
284	NYP	70	RTE	64	RTE	60	CRT-YNY	MN	Dispatcher hold Shuffle at 25 so to issue at dobbs ferry station, Control Point, 25
290	NYP	21	CTI	29	CTI	29	CRT-YNY	MN	Follow metro north, Milepost, 33.3, 15.4
449	ALB	23	FTI	31	FTI	31	WOR-WOR	CS	Meet ?, Control Point, 45
71	CLT	16	DSR	10	DSR	6	KAN-CLT	NS	Per bulletin Milepost, 362.8, 362.9, 10, main one
72	RGH	68	PTI	37	PTI	37	BNC-DNC	NS	Meet #AM75, Siding, Funston
73	CLT	28	FTI	10	DMW	7	KAN-CLT	NS	Held for or routed around MW work or equipment Control Point, Junker

Amtrak Endpoint OTP Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
74	RGH	24	PTI	16	PTI	14	SAL-HPT	NS	Meet Amtk 75, Control Point, Lake
75	CLT	49	WTR	16	WTR	9	CYN-DNC	NS	Flash flood warning Milepost, 71.0, 64.0
76	RGH	32	PTI	12	PTI	12	DNC-CYN	NS	Meet #Am79, Control Point, Clegg
77	CLT	23	PTI	20	PTI	20	DNC-BNC	NS	Meet #Amt74, Control Point, Merrill
89	SAV	37	FTI	52	FTI	24	PTB-RMT	CS	Follow CSX???, Control Point, Enfield
97	MIA	53	CTI	40	CTI	22	XDY-WPB	FL	Follow Stop signal Gator MT2, held to follow P641, Trirail, 641, Control Point, Gator
40	CHI	164	FTI	123	FTI	21	RMT-PTB	CS	Meet CSX G627, CSX I111, Control Point, Jarratt, Control Point, N. Collier
41	MIA	81	FTI	142	FTI	33	SAV-XJG	CS	Meet STOP SIGNAL, M 492/05, Other, A 494.8
527	SJC	25	MBO	31	MBO	31	SUI-MTZ	UP	For maritime traffic 1 oil tanker and pilot tug, Control Point, CPRV 035 Benecia
536	SAC	18	PTI	26	PTI	26	DAV-SAC	UP	Meet Regular delay for Friday . Meeting amt 547 at w sac waiting for station track 3 per parking plan., amt547, Control Point, w sacramento
541	OKJ	17	MBO	20	MBO	20	SUI-MTZ	UP	For maritime traffic Control Point, rv035
503	EUG	52	ENG	55	ENG	30	ORC-ORC	UP	Loading problem MU Cable disconnected once again, zip tied them both together, WS1404
509	PDX	65	TRS	46	TRS	46	TAC-XNI	ST	Vehicle on track ahead Other, MP 10.39
511	PDX	No OS Rpt	PTI	18	PTI	11	OLW-CTL	BN	Meet 511, Control Point, tenino
516	VAC	43	DSR	22	PTI	15	STW-MVW	BN	Meet Amtk 517, Siding, Logen
517	PDX	20	OTH	60	OTH	60	VAC-XVB	BN	No lost time. Updated delay report still incorrect.
518	VAC	20	FTI	27	FTI	20	X8B-XF2	BN	Cross Traffic CN, Control Point, Townsend
11	EMY	34	DMW	46	DMW	40	TAC-XNI	ST	Held for or routed around MW work or equipment Maintenance window. Waited on AMTK 502, Control Point, Rill
14	SEA	120	PTI	100	SYS	60	SBA-SLO	UP	Track and time from mp 356 and mp 295
7	SEA	85	FTI	273	FTI	177	WPT-GGW	BN	Blocked from station track Train broke a knuckle at Glasgow. Held at Whatley., BNSF 7557, Control Point, East Whatley
8	CHI	50	FTI	118	FTI	67	MAL-GGW	BN	Meet BNSF 7557, BNSF 7874, Siding, Tampico

Amtrak Endpoint OTP Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
27	PDX	-28	CON	105	CON	105	SPK-SPK	BN	Late train 7 into SPK
332	CHI	18	CTI	9	CTI	7	X9L-CHI	AM	Blocked from station track Metra, 2111, Control Point, CP Lake
562	SAN	37	DCS	24	PTI	13	SNC-X98	SC	Meet Amtk 765, Control Point, Serra
564	SAN	33	PTI	19	PTI	19	SNC-SNP	SC	Meet 567, Control Point, serra
566	SAN	36	DCS	13	FTI	12	XRJ-FUL	BN	Follow unk, Other, xrj-ful, BNSF
567	LAX	41	DCS	33	DCS	22	OSD-X98	SC	Restrictive signal(s) from known wayside signal failure Red Stop, Control Point, Songs
572	SAN	60	CTI	34	CTI	12	OSD-OSD	SN	Meet Coaster, 633, Control Point, Escondido Jct
573	LAX	18	DCS	20	DCS	12	OSD-X98	SN	Restrictive signal(s) from known wayside signal failure Flagging to X98, Stop, Control Point, Songs
579	LAX	20	PTI	14	PTI	14	OSD-X98	SN	Meet 774, Control Point, songs
581	LAX	40	WTR	19	WTR	16	OSD-X98	SN	Flood / washout Control Point, songs
584	SAN	65	PTI	73	PTI	37	SNC-SNP	SC	Meet Amtk 587, Control Point, Serra
587	LAX	42	CTI	58	CTI	54	OSD-X98	SN	Meet Metrolink, 624, Control Point, Songs
588	SAN	39	PTI	18	PTI	18	SNC-SNP	SC	Meet 591, Control Point, Serra
591	LAX	18	PTI	9	SYS	8	OSD-X98	SN	Copy authority / restriction Control Point, Songs
593	LAX	33	FTI	40	FTI	29	OSD-X98	SN	Meet bnsf8217, Control Point, songs
765	GTA	60	CTI	40	DCS	12	OSD-X98	SC	T.O.L Control Point, SONGS, Other, Signal 206
769	GTA	36	PTI	31	PTI	19	OXN-VEC	UP	Meet 782, Control Point, North Ventura
770	SAN	20	DCS	28	PTI	11	SNC-SNP	SC	Meet 573, Control Point, serra
774	SAN	50	PTI	27	CTI	14	OSD-SOL	SN	Follow Coaster, 640, Control Point, Escondido jct, Control Point, Farr
777	GTA	18	DCS	19	PTI	13	OSD-X98	SN	Meet 572, Control Point, songs
785	GTA	37	DCS	34	DCS	24	OSD-X98	SC	CTC system failure Flagging cp songs, Control Point, songs
786	SAN	26	PTI	20	PTI	10	IRV-SNC	SC	Meet 587, Control Point, trabuco
790	SAN	39	PTI	9	PTI	5	OLT-OLT	SN	Wait for station track Deadhead equipment occupying station in SAN, amtk, Control Point, 264

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
794	LAX	76	SYS	46	SYS	46	GTA-GTA	UP	Blocked by or assisting another, disabled Amtrak train Double up to 790, Control Point, Elwood
715	OKJ	16	PTI	16	FTI	10	FNO-MDR	BN	Meet BNSF 6056, Control Point, WEST FIGARDEN
2	NOL	230	ENG	382	ENG	200	ONA-PSN	UP	Air / Brake 76
1333	MSP	21	DSR	21	DCS	14	GLN-XRO	CP	Restrictive signal(s) from unknown cause Signal dropping at Tower A20. Authority past signal displaying stop indication. Signal kept dropping from clear to stop, back and forth., Stop, Control Point, Tower A20

Amtrak Initial Terminal Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/6/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	238	11/06	10	10	Engine change Other, ALB
BOS	65	11/06	4	4	Wheelchair, special service request, bridge plate BOS
BOS	449	11/06	4	4	Crews working around failed tower switches. Yard brought train first into track 9 then to track 3 Milepost w/Letters, tower 9, tower3
BOS	1099	11/06	29	29	Trespasser strike, Milepost, BOS, BOS, DP BOS 29" LATE DUE TO THE TRESPASSER STRIKE , MP 170.
BOS	1135	11/06	33	22	Late departure at initial terminal due to late arrival of inbound equipment, 1150, DP BOS 11" LATE A/C OF LATE TURN OF AM1150
BOS	1135	11/06	33	11	Water, commissary, toilet/trash dumping, WENT BACK TO YARD DUE TO CLEANING THE TRAIN
BOS	1161	11/06	11	11	Trespasser strike, Milepost, BOS, BOS, DP BOS 11" LATE DUE TO THE TRESPASSER STRIKE AT MP 170.
BOS	1163	11/06	17	17	Door, 1163, DP BOS 17" LATE DUE TO DOOR ISSUES.
BOS	1165	11/06	11	11	Late departure at initial terminal due to late arrival of inbound equipment, 1160, late turn of AM1160 and delayed due to Tower 1 project BOS
BOS	1167	11/06	9	9	Late departure at initial terminal due to late arrival of inbound equipment, 1162, late turn of AM1162
BOS	2151	11/06	80	80	Trespasser strike, Milepost, BOS, BOS, DP BOS 80" LATE DUE TO THE TRESPASSER STRIKE, MP 170
LOR	53	11/06	198	198	Late departure at initial terminal due to late arrival of inbound equipment 52
NHV	474	11/06	22	22	Planned set out / pick out of locomotives, cars or section of train, late release from the yard, train master Malcolm Green decided to not hold AM474 to connection with AM1082
NPN	1124	11/06	6	6	Hold for thruway bus
NYP	69	11/06	5	5	Late departure at initial terminal due to late arrival of inbound equipment, 230, LATE TURN OFF AM230
NYP	233	11/06	8	9	Late departure at initial terminal due to late arrival of inbound equipment, 236, LATE TURN OFF AM236
NYP	235	11/06	3	3	Late departure at initial terminal due to late arrival of inbound equipment, 238, LATE TURN OFF AM238
NYP	237	11/06	30	30	Late departure at initial terminal due to late arrival of inbound equipment, 290, LATE TURN OFF AM290
NYP	241	11/06	3	3	Hold for connecting train, HELD FOR PSNGRS OFF AM1156
PHL	643	11/06	1	1	Passenger and/or baggage
PHL	1144	11/06	1	1	Passenger and/or baggage
PHL	1150	11/06	6	6	Catenary failure, Control Point, PCY, POWER INTERUPTION IN YARD

Amtrak Initial Terminal Details

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/6/2026

Terminal	Train	Date	Late	Delay	Cause
SFA	52	11/06	134	134	Late departure at initial terminal due to late arrival of inbound equipment 53
SPG	473	11/06	5	5	Electrical failure, 473, NEEDED TO FIX LOOSE CABLE ON REAR OF TRAIN
TWO	64	11/06	9		
WAS	1142	11/06	76	76	Removal of passenger by police, PAX MEDICAL EMERGENCY
SAS	22	11/06	306	306	Hold for connecting train 2
EUG	508	11/06	1	1	Cross over or go around Engine Reporting Marks Unknown, Other, Eugene Station
GTA	790	11/06	(Trn Cxld)		Engine Issue
GTA	794	11/06	46	46	Blocked by or assisting another, disabled Amtrak train Double up to 790, Control Point, Elwood
LAX	14	11/06	2	2	Multiple passengers and groups boarding from late Amtrak 765
LAX	588	11/06	3	3	Inability to contact dispatcher Unable to contact river sub. Stop at terminal, Control Point, Terminal
OKJ	710	11/06	1	1	Loading problem Engine shut itself off wouldn't give a load upon departure, C2003
OKJ	718	11/06	(Trn Cxld)		Third Party Cab Car Failure
SAC	547	11/06	8	8	Hold for thruway bus
SAN	785	11/06	17	17	Late departure at initial terminal due to late arrival of inbound equipment 774
SEA	8	11/06	17	17	Mechanical issues car 32063 (no bathroom) released from yard @1650 7
SEA	509	11/06	7	7	Routine inspections Complete daily inspection on NPCU 90222., Other, King Street
SPK	27	11/04	105	105	Late train 7 into SPK

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	99.14	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	77.6	89.9	90.2	58	13
SEPTA	95.0	90.1	89.8	93.7	223	22
NJT-NED	95.0	93.5	93.5	88.6	200	13
NJT-SED	95.0	100.0	95.8	97.2	24	0

Operating Highlights

Train 52(06) North of Charleston, SC - Freight Train Interference

07NOV26: Train 52(06) operating with engines 377, 354, and 297 customers onboard was delayed 15 miles north of Charleston, SC on the CSX Charleston subdivision holding at milepost 362.4 meeting I031-06 and I137-06.

Train	Delay	Comment
52(06)	51"	

Train 98(06) North of Dillon, SC - Freight Train Interference

07NOV26: Train 98(06) operating with engines 44, 359, and 217 customers onboard was delayed North of Dillon, SC on the CSX South End subdivision meeting I031-06 at Hamill siding milepost 256.9.

Train	Delay	Comment
98(06)	35"	

Train 41(05) Columbia, SC - Freight Train Interference

07NOV26: Train 41(05) operating with engines 372, 356, and 175 customers onboard was delayed departing Columbia, SC due to CSX L657-06 putting their 10,000 foot train away at Cayce Yard.

Train	Delay	Comment
41(05)	40"	

CSX RFP Subdivision - North of Quantico, VA - Passenger Train Interference

06NOV26: Multiple Amtrak trains were delayed on the CSX RFP subdivision near North Possum Point Interlocking located at milepost 81.3 approximately 5 miles north of Quantico, VA on the CSX RFP subdivision operating through residual traffic congestion due to earlier track occupancy light located at AF interlocking.

Train	Delay	Comment
1087(06)	32"	
1099(06)	51"	

27-FOI-00137 000000091321 "UNCLASSIFIED" 1/10/2026

Train 49/449(06) Albany, NY - Engine Failure

06NOV26: Train 49/449(06) operating with engines 275, 180, and 218 customers onboard was delayed departing Albany, NY due to late servicing of engines and congestion in the yard.

Train	Delay	Comment
49/449(06)	46"	

Train 283(06) East of Syracuse, NY - Freight Train Interference

06NOV26: Train 283(06) operating with engine 700 and 148 customers onboard was delayed east of Syracuse, NY on the CSX Syracuse Terminal subdivision starting at CP 283 following freight traffic until Rochester, NY. Upon departure at ROchester, NY, train 283(06) followed more CSX freight to Buffalo Depew, NY.

Train	Delay	Comment
283(06)	43"	ROC-BUF
283(06)	1'02"	SYR-ROC

Train 40(05) Quantico, VA - Engine Failure

06NOV26: Train 40(05) operating with engines 171, 11, and 211 customers onboard was delayed at Quantico, VA station on the CSX RFP subdivision due to engine 11 having low lube oil pressure faults and leaking oil. Train 40(05) was unable to proceed due to the engine oil leak and was met by mechanical from Lorton VA. Upon inspection, mechanical found the issue to be a blown crankcase that caused the leaking oil. The spill in the engine was able to be contained and train 40(05) was able to proceed.

When 40(05) arrived at AF interlocking milepost 104.3, a track occupancy light was on track 2 to track 1 after train 50(05) operated through the area. Train 40(05) was further delayed waiting for permission to proceed from CSX dispatch. Train 19(06) was also delayed holding at Alexandria station for authority to proceed once 40(05) was clear. Upon arrival of train 40(05) into Alexandria station, a recrew was set up to take over the train causing further delay. Upon arrival of train 40(05) into Washington D.C., engine 11 was taken off due to environmental concerns from the residual oil. Engine 147 was added as the leader to engine 171. Once the engine moves were complete and all inspections were finished, train 40(05) was able to depart.

Train	Delay	Comment
40(05)	3'28"	QAN - Oil Leak
19(06)	37"	ALX TOL
40(05)	1'10"	TOL - AF
40(05)	1'12"	ALX - Recrew
40(05)	30"	WAS - PTC/Engines

Train 449(06) Worcester, MA - Freight Train Interference

06NOV26: Train 449(06) held at Worchester, MA (MP44.2), on the CSX Boston Subdivision, in order to meet a CSX freight train.

Train	Delay	Comment
449(06)	31"	

Train 284(06) North of Yonkers, NY - Routing

06NOV26: Train 284(06) was delayed beginning at MP21.5, 7.4 miles north of Yonkers, NY station on the Amtrak Hudson line being routed around due to an issues at Dobbs Ferry station.

27-FOI-00137 0000009132 UNCLASSIFIED 11/10/2026

Train 66(05) East of New London, CT - Weather

06NOV26: Train 66(05) was delayed 0.5 miles east of New London, CT (MP122.9), on the Amtrak NHB Line at MP123.4 due to excessive wheel slip caused by heavy rain in the area, which prevented the train from ascending the grade approaching Groton Interlocking (MP124.1). Train 66(05) subsequently made a reverse move, successfully cleared the grade, and continued to Boston. Train 1150(06) was also delayed through the area while following Train 66(05) due to excessive wheel slip. As a result, Train 1135(06) was delayed departing Boston, MA (MP228.7), on the Amtrak NHB Line due to the late turn of Train 1150(06), which arrived at 12:56PM, 1 hour and 19 minutes late.

Train	Delay	Comment
1135(06)	33"	ITD BOS
1150(06)	47"	Following 66(05)
1150(06)	22"	Excessive Wheel Slip
66(05)	42"	

Train 72(06) West of Durham, NC - Passenger Train Interference

06NOV26: Train 72(06) held 5.4 miles west of Durham, NC (MP55.2), on the NSRR Danville District, at Funston (MP49.8) meeting Train 75(06).

Train	Delay	Comment
72(06)	37"	

Train 40(06) Okeechobee, FL - Engine Failure

06NOV26: Train 40(06) was delayed at Okeechobee, FL station/MP908.7 on the CSX Auburndale subdivision due to PTC faults on engine 341. Crew attempted to cut out PTC with CNOC mechanical assisting but was unsuccessful. Train 40(06) departed Okeechobee, FL station at 224PM ET operating 50 late and continued to Sebring FL station with no further issues.

Train	Delay	Comment
40(06)	40"	

Train 50(05) West of Clifton Forge, VA - Freight Train Interference

06NOV26: Train 50(05) was delayed at MP283, 6.3 miles west of Clifton Forge VA station on the CSX Alleghany subdivision meeting CSX Freight train 5430. Train 50(05) was back on the move at 116PM ET after the freight cleared.

Train	Delay	Comment
50(05)	32"	

Train 280(06) Albany-Rensselaer, NY - Engine Failure

06NOV26: Train 280(06) was delayed at Albany Rensselaer NY station/MP142.1 on the Amtrak Hudson line setting out engine 9707 due to flat spots. Train 280(06) departed Albany Rensselaer station at 1056AM ET operating 51 minutes later.

Train	Delay	Comment
280(06)	51"	

Train 470(06) New Haven, CT - Hold for Connection

27-FOI-00137 0000000091832 UNCLASSIFIED 11/10/2026

06NOV26: Train 470(06) was delayed holding at New Haven, CT station/MP72.3 on the MNRR New Haven Line for connections off late arriving train 1160(06). Train 1160(06) arrived to New Haven CT station at 1121AM ET 34 minutes late.

Train	Delay	Comment
470(06)	35"	

Train 1099(06) East of Kingston, RI - Weather

06NOV26: Train 1099(06) was delayed at MP168.5 east of Kingston RI station on the Amtrak NHB line due to failing to make a grade caused by excessive wheel slip. Train 1099(06) reversed to attempt to make the grade but was unable to do so. A second reverse move was successful and train 1099(06) made the grade. Trains 1161(06) and 1087(06) were delayed holding east of 1099(06) while the attempts were made.

WBS#: B.TR.100151.0865

Train	Delay	Comment
1087(06)	36"	
1099(06)	1'09"	
1161(06)	45"	

Keolis 6008 Fatal Trespasser Strike - West of Providence, RI

06NOV26: At 6:10AM-ET, Keolis 6008 fatally struck a trespasser 14.1 miles west of Providence, RI (MP185.1), on the Amtrak NHB Line at MP171 on Track 2. Both main tracks were taken out of service to facilitate the investigation. Keolis and Amtrak transportation management personnel, local police, EMS, and the medical examiner responded to the scene. During the incident, Train 2149(06), with 283 customers onboard, and Train 1195(06), with 504 customers onboard, held at Providence Station. Train 2151(06), with 132 customers onboard, and Train 1099(06), with 251 customers onboard, held at their initial terminal in Boston. At 8:08AM-ET, Main Track 1 was released for service with a restriction in place between MP172 and MP171. Trains 2149(06) and 1195(06) were the first trains authorized to proceed through the area, followed by Trains 2151(06) and 1099(06), which were released from Boston.

Train 1142(06) was delayed departing Washington, DC due to a late turn of Train 1195(06) that arrived at 5:17PM, 2 hours and 39 minutes late.

WBS#: B.TR.100151.0864

Train	Delay	Comment
2149(06)	1'27"	
2151(06)	1'34"	
1161(06)	15"	
1099(06)	13"	
1195(06)	20"	
1142(06)	1'16"	ITD WAS

Train 41(04) South of Savannah, GA - Freight Train Interference

06NOV26: Train 41(04) held 3.8 miles south of Savannah, GA (MP491.0), on the CSX Savannah Subdivision, at North Tower (MP494.8) meeting CSX M492-05.

Train	Delay	Comment
41(04)	33"	

27-FOI-00137 . 00000009132 UNCLASSIFIED 11/10/2026

Train 98(05) North of Petersburg, VA - Freight Train Interference

06NOV26: Train 98(05) held 16.4 miles north of Petersburg, VA (MP22.0), on the CSX North End Subdivision, at FA (MP5.6) meeting multiple CSX freight trains.

Train	Delay	Comment
98(05)	33"	

Train 1109(06) North of Philadelphia, PA - Engine Failure

06NOV26: Train 1109(06) was delayed at MP85, North of Philadelphia PA station on the Amtrak NYP line due to MCB opening on engine 670. Crew preformed a hard reset on the engine and was not able to proceed without the MCB opening again. The crew called in to troubleshoot with Sieman's and CNOC mechanical. Mechanical walked the crew through troubleshooting and cutout TCU 2 effecting traction motors 3 and 4. Cutting out TCU limited train 1109(06) to 50 percent tractive effort. Once cutout MCB was closed and train 1109(06) was back on the move south at 739AM ET. Engine 618 was added at Philadelphia station. Train 1109(06) departed Philadelphia station at 824AM ET operating 1 hour and 18" minutes late.

Train	Delay	Comment
1109(06)	33"	Add 618
1109(06)	43"	

Train 53(05) South of Charleston, SC - Drawbridge Opening

06NOV26: Train 53(05) was delayed 6.3 miles north of Charleston, SC (MP387.4), on the CSX Charleston Subdivision due to the Ashley River Bridge at MP393.7 being open for marine traffic. After the bridge was seated and locked, Train 53(05) resumed southward movement and continued its route.

Train	Delay	Comment
53(05)	35"	

Train 1164(06) South of Richmond, VA - Freight Train Interference

06NOV26: Train 1164(06) was delayed holding at MP60.6, 24.9 miles south of Richmond VA station on the CSX Peninsula subdivision meeting CSX freight trains C119 and L216(05).

Train	Delay	Comment
1164(06)	35"	

Train 53(04) Lorton, VA - Initial Terminal Delay

04NOV26: Train 53(04) operating with engines 360, 384, and 497 customers onboard was delayed departing Lorton, VA due to turn from late inbound 52(03).

05NOV26: Train 52(05) operating with engines 380, 352, and 166 customers onboard was delayed departing Sanford, FL due to turn from late inbound 53(04).

06NOV26: Train 53(06) operating with engines 352, 380, and 483 customers onboard was delayed departing Lorton VA due to turn from late inbound 52(05). Train 52(06) operating with engines 377, 354, and 303 customers onboard was delayed departing Sanford, FL due to late inbound 53(05).

Train	Delay	Comment
53(04)	4'15"	
52(05)	4'09"	
52(06)	2'14"	
53(06)	3'18"	

Northeast Regional Crescent and Cardinal NS Track Work - 11/21-11/22 TWA 27-

27-FOJ-00137 0000000091132 "UNCLASSIFIED" 11/10/2026

04NOV26: On November 22, 2026, Norfolk Southern will perform signal system upgrade and testing work on the Washington District between MP 9 and MP 19. As a result, Northeast Regional, Crescent, and Cardinal service will be modified.

Northeast Regional
Train 147(21NOV) will terminate at Washington, DC Union Station. Bus 5147 will provide alternate transportation between Washington, DC Union Station and the Roanoke, VA station.
Train 156(22NOV) will originate at Washington, DC Union Station. Bus 5156 will provide alternate transportation between the Roanoke, VA station and Washington, DC Union Station.

Crescent
Train 220(21NOV) will operate in lieu of Train 20(21NOV), departing New Orleans, LA Union Passenger Terminal at 12:40P-CT. The train will operate 3 hours and 30 minutes later between New Orleans and Baltimore, MD Penn Station and 3 hours and 40 minutes later between Baltimore and New York, NY Penn Station.

Cardinal
Train 51(22NOV) will depart New York, NY Penn Station at 10:40A-ET and operate 4 hours later between New York and Chicago, IL Union Station.

WBS#: B.TR.100150.7326

Maintenance of Way Highlights

27-FOI-00137 0000009737 "UNCLASSIFIED" 1/19/2026

Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work

26OCT26: Due to the Veltri continuous outage on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Train 5(06) East of Lincoln, NE - Police Related

07NOV26: Train 5(06) operating with engines 163/146/193/15, 8 coaches, and 115 customers, was delayed 5 miles east of Lincoln, NE, on BNSF Creston subdivision, due to BNSF5287 striking a vehicle earlier. 5(05) held east of the station until the scene was released by local police. 5(06) then operated through the affected area at restricted speed and flagged a crossing.

Train	Delay	Comment
5(06)	1'25"	

Train 704(06) South of Hanford, CA - Debris

07NOV26: Train 704(06), operating with engine 2002, 8 coaches and 71 customers, was delayed 1 mile south of Hanford, CA, on BNSF Bakersfield, subdivision, due to striking a crossing gate that was previously knocked down by a vehicle. The crew brought the train to a stop to remove the gate from under the train.

Train	Delay	Comment
704(06)	10"	

Train 509(06) South of Tacoma, WA - Vehicle on Tracks

06NOV26: Train 509(06) was delayed 7.3 miles south of Tacoma WA at MP9.2 on the Sound Transit Lakewood Subdivision, due to a reported vehicle on the tracks ahead at MP10.39. Once the vehicle was removed and tracks inspected, Train 509(06) was able to proceed.

Train	Delay	Comment
509(06)	46"	

Train 718(06) Originated at Emeryville, CA - Third Party Contractor Cab Car Failure

06NOV26: Train 718(6) was originated at Emeryville, CA due to a late mechanical release from the yard. Train 718(06) was initially late due to changing out a faulty wiper motor on cab car CC/C8303. Due to a prolonged delay, the decision was made to swap equipment, using the 715 inbound consist. Delays persisted in the yard, with the equipment requiring service and fueling, and to help minimize the delay, the train was originated at Emeryville, CA. All 26 affected customers were accommodated on Train 544(06) between OKJ-EMY. Additional delays ensued after the train departed from the yard, losing Head-end power (HEP). A plan was developed to take the equipment from inbound 717 instead, and the train was readied while technicians continued to work on the disabled 715 set. Mechanical was able to repair the issue, and 718(06) was released to Emeryville, departing 4 hours and 19 minutes late with the 715 equipment set, CC/C8310, 7 cars, E/C2124.

Train	Delay	Comment
718(06)	4'19"	

27-FOI-00137 00000009132 UNCLASSIFIED 11/10/2026

Train 790(06) Goleta, CA - PTC Failure

06NOV26: Train 790(06), GC/6952 cars, E/C2114 was initially delayed departing Goleta, CA due to reported ongoing Positive Train Control (PTC) issues. Due to the unresolved PTC problems, Train 790 was cancelled between Goleta and Los Angeles, and all affected passengers were accommodated on Train 794(06). A make-up section using inbound Train 587's equipment operated between Los Angeles and San Diego. The equipment originally assigned to Train 790 was coupled and operated in a double-draft consist with Train 794(06) between GTA and LAX. Additionally, arrangements were made to secure two busses to provide alternate transportation for 111 customers originally booked on Train 790 boarding between GTA-LAX who were traveling beyond LAX. Prior to departure, the combined Train 794/790 consist experienced an additional delay at GTA while a hose was being changed out. Following completion of the repair, the combined train departed GTA at 7:24 p.m. Pacific Time, operating 46 minutes behind schedule.

The combined Train 794/790 was further delayed at Camarillo for mechanical troubleshooting in coordination with CNOC Mechanical and Siemens personnel. Investigation determined that the trailing locomotive E/C2114 was drawing amperage from the lead locomotive. Mechanical forces and the train crew worked together to isolate and cut out the trailing unit so it could remain in tow. Following the corrective action, full Head End Power (HEP) was maintained throughout the consist, and all required safety checks were successfully completed. The combined train departed Camarillo at 9:20 p.m. Pacific Time, operating 1 hour and 6 minutes late after incurring an additional 22-minute delay for troubleshooting and repairs.

WBS#: B.TR.100150.7334

Train	Delay	Comment
790(06)	47"	Originated LAX
794/790(06)	46"	ITD GTA
794/790(06)	23"	CML
794/790(06)	14"	Operating single loco

Train 22(06) Fort Worth, TX - Police Related

06NOV26: Train 22(06), operating with engine 313, 9 cars, and 70 customers, was delayed departing Fort Worth, TX, on BNSF Ft. Worth subdivision, due to a TRE trespasser strike which caused the police to place a hold on all tracks pending investigation. Once the police completed their investigation and released the tracks, train 22(06) was able to depart the station.

Train	Delay	Comment
22(06)	1'02"	

Train 3(05) West of Albuquerque, NM - Weather

07NOV26: Train 3(05), operating with engines 194/142, 10 coaches, and 169 customers, was delayed 46 miles West of Albuquerque, NM, on BNSF Gallup subdivision, due to severe weather resulting in flash flood speed restrictions. BNSF freight trains were also delayed due to the flash flood restrictions and 3(05) was delayed following some of these freights.

Train	Delay	Comment
3(05)	1'14"	Following freights
3(05)	56"	flash flood restrictions

27-FOI-00137 000000009132 "UNCLASSIFIED" 11/10/2026

Train 58(06) Jackson, MS - Crew Rest

06NOV26: Train 58(06) operating with engines 3827 and 7 cars and 99 customers, was delayed departing Jackson, MSm on CN McComb subdivision, was delayed departing Jackson, MS, on CN McComb subdivision, due to an issue with crew rest for the outbound engineer. As a result a recrew engineer was called in and cabbed to Jackson, MS to meet the train. Once the engineer arrived and a job briefing was completed, train 58(06) was able to proceed.

Train	Delay	Comment
58(06)	45"	

Train 7/27(05) West of Williston, ND - Freight Train Interference

06NOV26: Train 7/27(05) was delayed 26.8 miles west of Williston, ND (MP147.9) on the BNSF Glasgow Subdivision at Snowden (MP147.9) due to BNSF 8398 being disabled ahead at Bainville (MP160.7). Once BNSF 8398 was recovered, Train 7/27(05) was required to follow the freight train until it was able to pass at Brockton (MP191.8).

Train	Delay	Comment
7/27(05)	48"	

Train 503(06) South of Portland, OR - Engine Failure

06NOV26: Train 503(06), CC/90252-Airo set 4- E/WS1404-E/WS1401, was delayed starting at MP 762.9, 8 miles south of Portland, OR, on the UPRR Brooklyn Subdivision due to the main res separation. The crew stopped at MP 762.9 to secure hose then proceeded south. The separation occurred again at Oregon City, OR where the crew was able to resecure the hose. Once the hose was secured, Train 503(06) was able to depart.

Train	Delay	Comment
503(06)	25"	
503(06)	30"	ORC

Train 2(04) East of San Antonio, TX - Freight Train Interference

06NOV26: Train 2(04) was delayed 1.5 miles east of San Antonio, TX (MP209.5) on the UPRR Del Rio Subdivision due to UP 9013 being disabled ahead at Kirby (MP201.4). As a result, Train 2(04) was held at Tower 121 (MP208.0) and was required to wait for westbound UP 5606 to pass before being routed through Track 61 to bypass the disabled freight train.

Train	Delay	Comment
2(04)	40"	

Train 527(06) East of Martinez, CA - Drawbridge Opening

06NOV26: Train 527(06) was delayed at MP 34.8, 3 miles east of Martinez, CA, on the UPRR Martinez Subdivision as a result of the Suisun Drawbridge at MP 32.9 being raised for maritime traffic to pass. Train 11(05) held at MP 35.0 for a clear route. Once the bridge was lowered and secured, rail traffic was able to resume.

Train	Delay	Comment
527(06)	31"	
11(05)	32"	

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Train 4(05) East of Kingman, AZ - Freight Train Interference

06NOV26: Train 4(05) was delayed beginning at MP 500.0 16 miles east of Kingman, AZ, on the BNSF Seligman Subdivision due to freight interference. BN5267 had a broken knuckle causing freight traffic to build while it was repaired. The crew on Train 4(05) followed BNSF freight starting at MP 500 to Flagstaff/ MP 344.8 where they were able to operate around. At East Valentine/MP 484.0 the crew held for westbound freight traffic to clear.

Train	Delay	Comment
4(05)	1'02"	Follow Freight
4(05)	1'44"	Hold E. Valentine

Train 5(05) Lincoln, NE - Freight Train Interference

06NOV26: 5(05), operating with engines 63/145, 8 coaches, and 144 customers, was stopped east of Lincoln, Nebraska, at MP 40.4, on BNSF Creston subdivision, due to a disabled freight train ahead in an undesired emergency. The freight crew inspected the approximately three-mile-long train and determined that a distributed power unit (DPU) had stopped loading. After isolating the failed unit and addressing an issue with a replacement DPU, the freight train was able to resume recovery efforts.

While waiting, 5(05) incurred a delay of approximately 1 hour and 36 minutes. To expedite movement, BNSF arranged for 5(05) to reverse to CP411 and operate on Main Track 1 behind a tied-down freight train that had been recrewed. Once the shove movement was completed and the recrewed freight train departed, 5(05) resumed westward movement and followed the freight train toward Lincoln.

Train	Delay	Comment
5(05)	2'17"	wi-tronix est

Train 511(06) South of Vancouver, WA - Engine Failure

07NOV26: Train 511(06) CC/90340, 3 cars, E/72, with 79 customers, was delayed 1.28 miles south of Vancouver, WA at MP9.02 on the BNSF Fallbridge Subdivision due to a bad air compressor on engine E/72. Head-end power remained active during this event. The crew worked with CNOC mechanical and was unable to resolve, requiring additional power in order to proceed. There were no freights available to be sourced in the area. The Engineer and Conductor were picked up via a northbound passing UP freight train to Vancouver, WA, where they were met by an Amtrak Road Foreman to bring them to Portland and retrieve 509's equipment to rescue the train. The Assistant Conductor remained onboard with 511(06). Once the 509 rescue equipment arrived, it coupled and operated as a double-draft into Portland.

As a result, Train 502(07) is cancelled in entirety, no alternate transportation will be provided due to no available busses. Customers were accommodated on next available services. Train 500(07) will operate as a double-draft with the 511's equipment, in order to bring it to Seattle for needed repairs.

Train	Delay	Comment
511(06)	2'35"	Wi-tronix estimate
502(07)	Cancelled	

UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority

16OCT26: The UPRR placed general orders in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected area due to signal issues where crews operated at restricted speed and stopped to flag crossings.

transportation provided.
Trains 757/ 765/ 777(17-01NOV) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-01NOV) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

27-FOI-00137 0000000S132 UNCLASSIFIED 1/10/2026

23OCT26: The operating plan was extended through at least Sunday November 1.

30OCT26: The operating plan was extended to Friday November 6th.

04NOV26: The operating plan was extended to Friday November 15th.

WBS#: B.TR.100150.7278

Train	Delay	Comment
774(16)	1'39"	
757(16)	1'34"	
786(16)	1'35"	ITD SLO- Turn of 757(16)
786(16)	1'35"	ITD SLO- Equip off 757
765(16)	1'22"	
794(16)	38"	ITD SLO- Equip off 765
794(16)	2'08"	
14(16)	2'21"	
786(16)	2'57"	
11(15)	1'23"	
14(17)	1'13"	
11(16)	1'51"	
11(17)	1'15"	
14(18)	1'19"	
14(19)	1'01"	
11(18)	1'08"	
11(19)	1'10"	
14(20)	1'40"	
11(19)	51"	waiting for & meeting 14(20) at Tangair
14(21)	40"	
11(20)	1'05"	meet 14(21)
11(20)	1'14"	
11(21)	1'02"	
14(22)	59"	
11(22)	1'51"	
14(23)	1'03"	
782(23)	48"	
14(24)	1'03"	
11(25)	1'52"	
14(27)	1'31"	
11(26)	1'29"	
11(28)	1'11"	
14(28)	1'07"	
14(29)	45"	
11(29)	1'00"	
14(31)	1'02"	
11(30)	1'21"	
14(01)	1'24"	
11(31)	1'05"	
14(02)	1'00"	
11(01)	1'15"	
14(03)	51"	
14(04)	1'00"	
11(03)	1'00"	
14(05)	1'00"	
11(04)	1'20"	
14(06)	1'20"	

NCTD San Diego Subdivision East of San Clemente Pier, CA - Signal Issues

31OCT26: Ongoing signal issues on the NCTD San Diego Subdivision due to high tides requires trains to flag between San Clemente Pier, CA and Oceanside, CA. The single-track conditions that exist also creates congestion through the area causing further delay to trains that operate through the area.

03NOV26: Train 572(03) and Train 579(03) were canceled due to the late arrival of

The 79 customers scheduled for Train 572(03) were accommodated on Train 774(03).
The 89 customers scheduled for Train 579(03) were accommodated on Train 581(03).

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Train	Delay	Comment

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

```
562(31)  32"
765(31)  17"
564(31)  52"
566(31)  45"
769(31)  54"
573(31)  28"
770(31)  47"
774(31)  58"
572(31)  14"
777(31)  15"
579(31)  46"
785(31)  14"
581(31)  1'02"
587(31)  49"
591(31)  50"
580(31)  11"
782(31)  46"
584(31)  1'14"
786(31)  24"
588(31)  21"
593(31)  1'06"
595(31)  1'02"
790(31)  11"
794(31)  24"
562(01)  22"
567(01)  32"
769(01)  47"
564(01)  59"
566(01)  1'13"
573(01)  27"
777(01)  22"
572(01)  21"
579(01)  47"
774(01)  41"
581(01)  1'02"
785(01)  26"
587(01)  48"
580(01)  22"
782(01)  52"
591(01)  51"
584(01)  1'15"
593(01)  1'03"
786(01)  13"
588(01)  1'04"
790(01)  12"
595(01)  1'01"
794(01)  17"
761(02)  17"
765(02)  12"
567(02)  13"
769(02)  22"
562(02)  12"
564(02)  33"
573(02)  19"
777(02)  21"
566(02)  43"
770(02)  15"
572(02)  16"
581(02)  16"
774(02)  11"
785(02)  22"
587(02)  16"
580(02)  11"
782(02)  12"
591(02)  22"
584(02)  21"
786(02)  11"
588(02)  38"
794(02)  17"
790(02)  12"
595(02)  1'38"  SAN Turn of Late Inbound 584(02) and Delay between SOL and SNC
593(02)  2'09"  SAN Turn Late Inbound 782(02) and Delay between SOL and SNC
761(03)  22"
567(03)  1'56"
765(03)  1'14"
562(03)  1'34"
```

Train	Delay	Comment
770(03)	50"	
573(03)	1'51"	SAN Late Inbound 562 and SOL to SNC Delays
777(03)	31"	
774(03)	36"	
581(03)	14"	
785(03)	16"	
587(03)	37"	
580(03)	13"	
782(03)	29"	
591(03)	18"	
584(03)	20"	
593(03)	13"	
595(03)	48"	
786(03)	16"	
588(03)	21"	
790(03)	16"	
794(03)	20"	
566(04)	11"	
562(04)	32"	
564(04)	24"	
770(04)	23"	
572(04)	33"	
761(04)	19"	
765(04)	19"	
567(04)	16"	
573(04)	15"	
769(04)	20"	
579(04)	18"	
587(04)	30"	
777(04)	1'03"	
581(04)	12"	
785(04)	17"	
774(04)	29"	
580(04)	10"	
584(04)	56"	
786(04)	11"	
794(04)	41"	ITD GTA - Equip off 777
761(05)	13"	
765(05)	36"	
769(05)	26"	
573(05)	33"	
562(05)	49"	
564(05)	13"	
566(05)	11"	
584(05)	1'03"	
777(05)	29"	
794(05)	28"	ITD GTA - Turn off 777
587(05)	55"	
595(05)	06"	
593(05)	14"	
591(05)	21"	
785(05)	45"	
581(05)	17"	
774(05)	14"	
579(05)	42"	
572(05)	06"	
770(05)	31"	
761(06)	12"	
567(06)	29"	
765(06)	26"	
573(06)	15"	
769(06)	25"	
777(06)	15"	
562(06)	32"	
564(06)	14"	
566(06)	13"	
770(06)	11"	
572(06)	13"	
579(06)	18"	
581(06)	37"	
785(06)	48"	
587(06)	1'01"	
774(06)	54"	
580(06)	25"	
782(06)	22"	

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

27-FOI-00137, 00000009132 "UNCLASSIFIED" 11/10/2026

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	
821(07)	35"	
822(08)	32"	
821(09)	32"	
822(09)	36"	
822(10)	23"	
822(11)	41"	
822(12)	48"	
821(12)	21"	
821(13)	22"	
822(13)	36"	
821(14)	35"	
822(14)	17"	
821(15)	26"	
821(16)	41"	
822(15)	34"	
822(16)	19"	
821(17)	24"	
821(19)	39"	
822(19)	22"	
821(20)	29"	
822(20)	32"	
821(21)	46"	
821(22)	32"	
822(21)	19"	
822(22)	30"	
821(23)	42"	
822(23)	23"	
821(24)	21"	
822(24)	22"	
821(25)	34"	
822(25)	43"	
821(26)	52"	
822(27)	34"	
822(26)	21"	
821(28)	30"	
822(28)	31"	
821(29)	23"	
822(29)	33"	
821(30)	33"	
822(30)	22"	
821(31)	20"	
822(31)	25"	
822(01)	30"	
821(02)	35"	

Maintenance of Way Highlights

27-FOI-00187 0000000091132 "UNCLASSIFIED" 11/7/2025

Pacific Surfliner and Coast Starlight Service San Luis Obispo, CA to San Diego, CA - Scheduled M/W TW 27-021

07NOV26: A multi-agency track maintenance project involving North County Transit District (NCTD), Southern California Regional Rail Authority (SCRRA/Metrolink), and Union Pacific Railroad (UP) was conducted between San Luis Obispo, CA, and San Diego, CA. To accommodate the work, the following operating plan was implemented:

Coast Starlight
Train 11 (November 5-7): Terminated at Emeryville, CA with alternate transportation provided between Sacramento and Los Angeles via Gold Runner Services.
Train 14 (November 7-9): Originated at Emeryville, CA with alternate transportation provided between Los Angeles and Martinez via Gold Runner Services.

Pacific Surfliner
Friday, November 6
Train 794(06) Originated in Goleta, CA account of ongoing signal issues and Terminated at Los Angeles, CA account of the scheduled track work. Bus 3594 provided alternate transportation between Los Angeles and San Diego making all stops except San Juan Capistrano
Train 595(06) Canceled in its entirety. Customers were accommodated on Bus 5811.

Saturday, November 7, and Sunday, November 8
All Pacific Surfliner trains were canceled. No alternate transportation was provided.

UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Scheduled M/W Work TWA 27-020

26OCT26:To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 1(31Oct, 7Nov, 14Nov) and Train 42(30Oct, 6Nov, 13Nov) will detour over the BNSF San Bernardino Subdivision between West Colton(UPRR Alhambra subdivision) and Soto(BNSF San Bernardino subdivision), bypassing Ontario, CA (ONA) and Pomona, CA (POS). Train 801(2Nov, 9Nov, 16Nov) was created for the detour between Riverside, CA (RIV) and Los Angeles, CA (LAX).

Train 2/422(1Nov, 8Nov, 15Nov) will detour over the BNSF San Bernardino Subdivision between Soto(BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(1Nov, 8Nov, 15Nov) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV). An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision. No alternate transportation will be provided to POS and ONA.

WBS#: B.TR.100150.7307

Train	Delay	Comment
2/422(01)	39"	
1(31)/421(30)	44"	

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
11(2)	SLO	164		Main Resevoir

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

27-FOI-00137 00000009132 "UNCLASSIFIED" 11/10/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
236 (06)	ALB	TRAIN WILL OPERATE WITH AN ALL TABLE CAR IN LIEU OF A COACH CAR. INVENTORY HAS BEEN ADJUSTED. PLEASE NOTIFY ALL EFFECTED PAX AND REACCOMMODATE WHERE POSSIBLE.	Passengers notified	19	43344
244 (06)	ALB	TRAIN WILL OPERATE WITH AN ALL TABLE CAR IN LIEU OF A COACH CAR. INVENTORY HAS BEEN ADJUSTED. PLEASE NOTIFY ALL EFFECTED PAX AND REACCOMMODATE WHERE POSSIBLE.	Passengers notified	21	43344
48 (06)	CHI	view 1 in lieu of view 2 sleeper in 448 section.	SVWR48/6NOV NO WAR DATA THIS TRAIN/DATE	0	62049
80 (07)	CLT	consist should be 2 amfleet 1 coaches and 2 amfleet 2 coaches. no impact to ridership	n/a	0	25082
642 (06)	HAR	TRAIN WILL OPERATE WITH A BUSINESS CLASS CAR IN LIEU OF A CAB CAR. THERE WILL BE NO WIFI. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	na	0	81511
770 (06)	LAX	770 lax-san ONLY, will use comet set. no JY/IY/ZY/BY, no cafe. Turn tbd.	JY -106 BV -2	108	COMET SET
14 (06)	LAX	no H-room on the 1432(06) car. please block room.	Room blocked	0	39002
233 (06)	NYP	TRAIN WILL OPERATE WITH AN ALL TABLE CAR IN LIEU OF A COACH CAR. INVENTORY HAS BEEN ADJUSTED. PLEASE NOTIFY ALL EFFECTED PAX AND REACCOMMODATE WHERE POSSIBLE.	No impact	0	43344
243 (06)	NYP	TRAIN WILL OPERATE WITH AN ALL TABLE CAR IN LIEU OF A COACH CAR. INVENTORY HAS BEEN ADJUSTED. PLEASE NOTIFY ALL EFFECTED PAX AND REACCOMMODATE WHERE POSSIBLE.	Passengers notified	18	43344

27-FOI-00137 00000009132 "UNCLASSIFIED"

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
97 (06)	NYP	Due to shopped lounge, a all table cafe is being used.	NA	0	43349
19 (06)	NYP	Due to shopped equipment a view 2 sleeper is being used in lieu of a view 1 sleeper. schedule change performed. 20(08) is the return	SVWR19/6NOV NO WAR DATA THIS TRAIN/DATE	0	62508
79 (06)	NYP	Consist should consist of 2 amfleet 1 coaches and 2 amfleet 2 coaches. no impact to ridership	na	0	25082
581 (06)	SAN	no JY/IY/ZY, cafe, or wifi	Passengers notified	0	COMET SET
11 (08)	SEA	no H-room on the 1132(*08*) car. please block room.	NO H RM	2	39002

Reverse Consists

Train Number	Station	Reason
1144 (06)	PHL	Consist reversed | Business class seat orientation may have changed | At Rear
1153 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1111 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1109 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1155 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
2103 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Rear
2101 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Rear
1103 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
2114 (06)	WAS	Acela consist reversed | First class at Front
2155 (06)	NYP	Acela consist reversed | First class at Rear
1169 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1129 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1116 (06)	WAS	Consist reversed | Business class seat orientation may have changed | At Rear
1107 (06)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1142 (06)	WAS	Consist reversed | Business class seat orientation may have changed | At Front