# CNOC

## (CONSOLIDATED NATIONAL OPERATIONS CENTER)

# Amtrak Status Report

Sunday, November 08, 2026 Rules: 0-4




*This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.*

## Information Management

27-FOI-00134

# Initial Terminal Performance By Division

Scheduled Departure Date: **11/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/07/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 252 | 25 | 90.1% | 2,081 | 279 | 86.6% | 11,555 | 1,631 | 85.9% |
| Central Division | 86.0% | 59 | 5 | 91.5% | 408 | 22 | 94.6% | 2,178 | 147 | 93.3% |
| East Division | 82.0% | 138 | 11 | 92.0% | 1,076 | 146 | 86.4% | 6,075 | 884 | 85.4% |
| West Division | 86.0% | 55 | 9 | 83.6% | 597 | 111 | 81.4% | 3,302 | 600 | 81.8% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

## Information Management

# Customer On Time Performance

Endpoint Arrival Dates through 11/7/26

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

| Service | Target | Day | | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score |
| **Amtrak System** | **76%** | **92,576** | **33,987** | **63%** | **668,626** | **223,418** | **67%** | **3,849,381** | **1,130,304** | **71%** |
| ***Northeast Corridor*** | ***78%*** | ***48,720*** | ***18,528*** | ***62%*** | ***297,022*** | ***99,663*** | ***66%*** | ***1,670,121*** | ***425,430*** | ***75%*** |
| Acela | 80% | 4,667 | 502 | 89% | 43,136 | 12,084 | 72% | 280,195 | 58,647 | 79% |
| Northeast Regional | 78% | 44,053 | 18,026 | 59% | 253,886 | 87,579 | 66% | 1,389,926 | 366,783 | 74% |
| Richmond / Newport News / Norfolk | 75% | 16,850 | 9,702 | 42% | 62,376 | 24,344 | 61% | 334,334 | 100,061 | 70% |
| Springfield Shuttles | 89% | 681 | 147 | 78% | 5,231 | 827 | 84% | 25,787 | 5,188 | 80% |
| Roanoke | 75% | 3,172 | 615 | 81% | 20,950 | 6,605 | 68% | 139,145 | 34,877 | 75% |
| On Spine Northeast Regional | 80% | 23,350 | 7,562 | 68% | 165,329 | 55,803 | 66% | 890,660 | 226,657 | 75% |
| ***State Supported*** | ***80%*** | ***31,217*** | ***8,042*** | ***74%*** | ***291,079*** | ***83,081*** | ***71%*** | ***1,729,995*** | ***497,395*** | ***71%*** |
| Borealis | 80% | 712 | 174 | 76% | 4,573 | 1,363 | 70% | 26,812 | 5,659 | 79% |
| Capitol Corridor | 90% | 2,378 | 625 | 74% | 27,675 | 4,234 | 85% | 153,413 | 28,464 | 81% |
| Carolinian | 70% | 1,073 | 729 | 32% | 9,457 | 5,020 | 47% | 48,664 | 18,622 | 62% |
| Cascades | 75% | 2,347 | 406 | 83% | 19,122 | 5,753 | 70% | 107,103 | 31,962 | 70% |
| Downeaster | 82% | 1,687 | 318 | 81% | 9,953 | 2,506 | 75% | 68,430 | 16,504 | 76% |
| Empire | 78% | 4,744 | 1,639 | 65% | 39,160 | 10,825 | 72% | 236,869 | 57,928 | 76% |
| Adirondack | 72% | 271 | 156 | 42% | 2,140 | 166 | 92% | 15,110 | 2,274 | 85% |
| Ethan Allen Express | 70% | 450 | 5 | 99% | 3,589 | 1,425 | 60% | 22,019 | 8,427 | 62% |
| Maple Leaf | 70% | 731 | 264 | 64% | 5,386 | 2,522 | 53% | 32,473 | 10,995 | 66% |
| New York - Albany | 85% | 2,452 | 551 | 78% | 19,445 | 3,642 | 81% | 114,887 | 21,292 | 81% |
| New York - Niagara Falls | 75% | 840 | 663 | 21% | 8,600 | 3,070 | 64% | 52,380 | 14,940 | 71% |
| Gold Runner | 73% | 2,296 | 913 | 60% | 17,910 | 5,884 | 67% | 98,063 | 36,446 | 63% |
| Heartland Flyer | 70% | 265 | 265 | 0% | 1,222 | 851 | 30% | 7,600 | 6,212 | 18% |
| Hiawatha | 90% | 1,982 | 0 | 100% | 11,705 | 1,470 | 87% | 69,883 | 7,213 | 90% |
| Illinois | 78% | 2,420 | 977 | 60% | 18,155 | 2,827 | 84% | 103,561 | 30,139 | 71% |
| Carl Sandburg / Illinois Zephyr | 85% | 459 | 290 | 37% | 2,507 | 461 | 82% | 15,991 | 3,975 | 75% |
| Illini / Saluki | 85% | 803 | 277 | 66% | 6,683 | 762 | 89% | 35,639 | 12,647 | 65% |
| Lincoln Service | 70% | 1,158 | 410 | 65% | 8,965 | 1,604 | 82% | 51,931 | 13,517 | 74% |
| Keystone | 92% | 4,410 | 4 | 100% | 41,114 | 3,671 | 91% | 252,261 | 25,351 | 90% |
| Lincoln / Missouri | 70% | 447 | 447 | 0% | 5,529 | 2,702 | 51% | 32,580 | 15,667 | 52% |
| Mardi Gras Service | 80% | 442 | 0 | 100% | 2,406 | 205 | 91% | 13,214 | 3,355 | 75% |
| Michigan | 70% | 2,048 | 127 | 94% | 13,904 | 2,627 | 81% | 81,556 | 19,553 | 76% |
| Blue Water | 70% | 411 | 0 | 100% | 3,131 | 370 | 88% | 21,805 | 5,234 | 76% |
| Pere Marquette | 85% | 199 | 0 | 100% | 1,806 | 112 | 94% | 11,117 | 735 | 93% |
| Wolverine | 70% | 1,438 | 127 | 91% | 8,967 | 2,145 | 76% | 48,634 | 13,584 | 72% |
| Missouri | 80% | 376 | 152 | 60% | 1,742 | 468 | 73% | 10,779 | 2,190 | 80% |
| Pacific Surfliner | 85% | 0 | 0 | - | 42,575 | 26,173 | 39% | 275,883 | 150,245 | 46% |
| Pennsylvanian | 80% | 978 | 239 | 76% | 6,689 | 812 | 88% | 36,660 | 10,494 | 71% |
| Piedmont | 80% | 1,402 | 827 | 41% | 7,812 | 4,221 | 46% | 47,580 | 16,357 | 66% |
| Vermonter | 75% | 1,210 | 200 | 83% | 10,376 | 1,469 | 86% | 59,084 | 15,034 | 75% |
| ***Long Distance*** | ***58%*** | ***12,639*** | ***7,417*** | ***41%*** | ***80,525*** | ***40,674*** | ***49%*** | ***449,265*** | ***207,479*** | ***54%*** |
| Auto Train | 70% | 778 | 778 | 0% | 5,107 | 4,555 | 11% | 25,973 | 19,925 | 23% |
| California Zephyr | 70% | 888 | 797 | 10% | 5,790 | 2,889 | 50% | 35,387 | 11,435 | 68% |
| Cardinal | 70% | 353 | 135 | 62% | 1,773 | 600 | 66% | 8,725 | 3,827 | 56% |
| City Of New Orleans | 75% | 732 | 386 | 47% | 4,831 | 1,192 | 75% | 28,786 | 17,937 | 38% |
| Coast Starlight | 70% | 1,139 | 387 | 66% | 6,922 | 4,259 | 38% | 41,158 | 22,939 | 44% |
| Crescent | 70% | 965 | 376 | 61% | 6,707 | 1,447 | 78% | 37,211 | 6,492 | 83% |
| Empire Builder | 70% | 976 | 298 | 69% | 6,146 | 2,000 | 67% | 36,866 | 13,182 | 64% |
| Floridian | 60% | 1,630 | 824 | 49% | 11,210 | 8,298 | 26% | 54,176 | 32,519 | 40% |
| Lake Shore Ltd | 73% | 982 | 803 | 18% | 6,676 | 1,755 | 74% | 38,539 | 11,926 | 69% |
| Palmetto | 70% | 951 | 394 | 59% | 6,380 | 2,769 | 57% | 30,170 | 8,854 | 71% |
| Silver Meteor | 70% | 1,133 | 743 | 34% | 7,053 | 4,528 | 36% | 39,779 | 14,950 | 62% |
| Southwest Chief | 60% | 871 | 657 | 25% | 4,409 | 3,632 | 18% | 28,072 | 21,914 | 22% |
| Sunset Ltd | 70% | 358 | 358 | 0% | 1,784 | 791 | 56% | 10,619 | 5,019 | 53% |
| Texas Eagle | 70% | 883 | 481 | 46% | 5,737 | 1,959 | 66% | 33,804 | 16,560 | 51% |

**Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"**

# Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00187 000000000181 "UNCLASSIFIED" 11/10/2026~~

## Train Index Dates Through November 07, 2026

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Service** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| Amtrak System | 585 | 42,776 | 707,497 | 605 | 230,686 | 3,797,080 | 608 |

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Department** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| INFRASTRUCTURE UNPLANNED | 107 | 1,261 | 186,595 | 68 | 10,811 | 1,058,312 | 102 |
| INFRASTRUCTURE PLANNED | 135 | 4,503 | 186,595 | 241 | 24,470 | 1,058,312 | 231 |
| FLEET RELIABILITY | 90 | 5,975 | 707,497 | 84 | 32,578 | 3,797,080 | 86 |
| TRAIN OPERATIONS | 424 | 31,037 | 707,497 | 439 | 162,827 | 3,797,080 | 429 |

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

## Information Management

27-FOI-00134

# Initial Terminal Performance By Division

Scheduled Departure Date: **11/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/07/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 252 | 25 | 90.1% | 2,081 | 279 | 86.6% | 11,555 | 1,631 | 85.9% |
| Central Division | 86.0% | 59 | 5 | 91.5% | 408 | 22 | 94.6% | 2,178 | 147 | 93.3% |
| East Division | 82.0% | 138 | 11 | 92.0% | 1,076 | 146 | 86.4% | 6,075 | 884 | 85.4% |
| West Division | 86.0% | 55 | 9 | 83.6% | 597 | 111 | 81.4% | 3,302 | 600 | 81.8% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

27-FOI-001

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/07/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 252 | 25 | 90.1% | 2,081 | 279 | 86.6% | 11,555 | 1,631 | 85.9% |
| Central Division | 86.0% | 59 | 5 | 91.5% | 408 | 22 | 94.6% | 2,178 | 147 | 93.3% |
| CDL | 95.0% | 2 | 1 | 50.0% | 14 | 2 | 85.7% | 55 | 5 | 90.9% |
| CHI | 86.0% | 27 | 3 | 88.9% | 190 | 12 | 93.7% | 1,020 | 80 | 92.2% |
| CHM | - | - | - | - | - | - | - | 20 | 3 | 85.0% |
| DAL | - | - | - | - | - | - | - | 2 | 0 | 100.0% |
| DET | - | - | - | - | - | - | - | 1 | 1 | 0.0% |
| FTW | 92.5% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 35 | 2 | 94.3% |
| GRR | 95.5% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 0 | 100.0% |
| IND | - | - | - | - | - | - | - | 4 | 0 | 100.0% |
| KCY | 92.0% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 77 | 1 | 98.7% |
| MKE | 92.0% | 6 | 0 | 100.0% | 41 | 3 | 92.7% | 222 | 15 | 93.2% |
| MOE | 97.5% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 69 | 0 | 100.0% |
| MSP | 96.5% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 0 | 100.0% |
| NOL | 94.5% | 5 | 1 | 80.0% | 31 | 1 | 96.8% | 157 | 7 | 95.5% |
| OKC | 97.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 37 | 2 | 94.6% |
| PNT | 88.0% | 3 | 0 | 100.0% | 21 | 1 | 95.2% | 101 | 13 | 87.1% |
| PTH | 93.0% | 1 | 0 | 100.0% | 7 | 1 | 85.7% | 38 | 2 | 94.7% |
| QCY | 91.0% | 2 | 0 | 100.0% | 13 | 0 | 100.0% | 75 | 4 | 94.7% |
| SAS | 90.5% | 1 | 0 | 100.0% | 7 | 2 | 71.4% | 37 | 8 | 78.4% |
| STL | 89.0% | 4 | 0 | 100.0% | 28 | 0 | 100.0% | 151 | 3 | 98.0% |
| TAY | - | - | - | - | - | - | - | 1 | 1 | 0.0% |
| East Division | 82.0% | 138 | 11 | 92.0% | 1,076 | 146 | 86.4% | 6,075 | 884 | 85.4% |
| ALB | 88.5% | 7 | 1 | 85.7% | 54 | 5 | 90.7% | 299 | 25 | 91.6% |
| ALX | - | - | - | - | - | - | - | 27 | 14 | 48.1% |
| ATL | - | - | - | - | - | - | - | 14 | 4 | 71.4% |
| BON | 87.5% | 5 | 0 | 100.0% | 35 | 4 | 88.6% | 190 | 16 | 91.6% |
| BOS | 85.5% | 11 | 0 | 100.0% | 78 | 15 | 80.8% | 471 | 37 | 92.1% |
| BRK | 92.5% | 5 | 0 | 100.0% | 35 | 2 | 94.3% | 190 | 15 | 92.1% |
| BTN | 82.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 5 | 86.8% |
| CLT | 91.5% | 5 | 1 | 80.0% | 35 | 3 | 91.4% | 184 | 23 | 87.5% |
| GFD | 88.0% | 2 | 1 | 50.0% | 14 | 2 | 85.7% | 76 | 8 | 89.5% |
| GRO | - | - | - | - | 6 | 1 | 83.3% | 17 | 1 | 94.1% |
| HAR | 79.5% | 8 | 0 | 100.0% | 81 | 9 | 88.9% | 436 | 48 | 89.0% |
| HFD | - | - | - | - | - | - | - | 44 | 9 | 79.5% |
| JAX | - | - | - | - | - | - | - | 18 | 2 | 88.9% |
| LOR | 84.0% | 1 | 1 | 0.0% | 7 | 6 | 14.3% | 36 | 18 | 50.0% |
| MET | - | - | - | - | - | - | - | 1 | 1 | 0.0% |
| MIA | 89.5% | 2 | 1 | 50.0% | 14 | 4 | 71.4% | 75 | 12 | 84.0% |
| MTR | 79.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 9 | 76.3% |
| NFK | 84.5% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 65 | 10 | 84.6% |
| NFL | 93.5% | 2 | 0 | 100.0% | 14 | 1 | 92.9% | 76 | 6 | 92.1% |
| NFS | - | - | - | - | - | - | - | 3 | 3 | 0.0% |
| NHV | 78.0% | 4 | 0 | 100.0% | 40 | 4 | 90.0% | 197 | 37 | 81.2% |
| NPN | 93.0% | 2 | 0 | 100.0% | 14 | 2 | 85.7% | 54 | 6 | 88.9% |

**Information Management**

# Initial Terminal Performance By Terminal

27-FOI-001

Scheduled Departure Date: **11/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/07/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 252 | 25 | 90.1% | 2,081 | 279 | 86.6% | 11,555 | 1,631 | 85.9% |
| East Division | 82.0% | 138 | 11 | 92.0% | 1,076 | 146 | 86.4% | 6,075 | 884 | 85.4% |
| NYP | 75.5% | 36 | 1 | 97.2% | 274 | 32 | 88.3% | 1,572 | 250 | 84.1% |
| PGH | 93.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 46 | 10 | 78.3% |
| PHL | 48.0% | 6 | 3 | 50.0% | 67 | 33 | 50.7% | 315 | 149 | 52.7% |
| RGH | 95.0% | 4 | 0 | 100.0% | 22 | 2 | 90.9% | 148 | 23 | 84.5% |
| RNK | 83.5% | 2 | 0 | 100.0% | 14 | 2 | 85.7% | 65 | 8 | 87.7% |
| SAB | 98.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 0 | 100.0% |
| SAV | 96.0% | 1 | 1 | 0.0% | 7 | 1 | 85.7% | 27 | 1 | 96.3% |
| SFA | 88.0% | 1 | 1 | 0.0% | 7 | 6 | 14.3% | 36 | 11 | 69.4% |
| SPG | 92.5% | 6 | 0 | 100.0% | 48 | 1 | 97.9% | 216 | 11 | 94.9% |
| TWO | 73.0% | 1 | 0 | 100.0% | 7 | 2 | 71.4% | 35 | 10 | 71.4% |
| WAS | 84.0% | 21 | 0 | 100.0% | 161 | 9 | 94.4% | 1,028 | 102 | 90.1% |
| West Division | 86.0% | 55 | 9 | 83.6% | 597 | 111 | 81.4% | 3,302 | 600 | 81.8% |
| ARN | 92.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 3 | 92.1% |
| BFD | 79.0% | 7 | 0 | 100.0% | 49 | 11 | 77.6% | 258 | 63 | 75.6% |
| EMY | 72.0% | 2 | 1 | 50.0% | 8 | 2 | 75.0% | 43 | 17 | 60.5% |
| EUG | 86.5% | 2 | 0 | 100.0% | 14 | 1 | 92.9% | 73 | 4 | 94.5% |
| FNO | - | - | - | - | - | - | - | 5 | 4 | 20.0% |
| GAC | - | - | - | - | - | - | - | 3 | 2 | 33.3% |
| GTA | 90.0% | - | - | - | 36 | 12 | 66.7% | 167 | 67 | 59.9% |
| IRV | - | - | - | - | - | - | - | 1 | 0 | 100.0% |
| LAX | 89.5% | 1 | 0 | 100.0% | 63 | 14 | 77.8% | 363 | 48 | 86.8% |
| OKJ | 74.5% | 9 | 5 | 44.4% | 83 | 25 | 69.9% | 446 | 140 | 68.6% |
| PDX | 86.0% | 4 | 1 | 75.0% | 33 | 4 | 87.9% | 188 | 17 | 91.0% |
| SAC | 88.5% | 11 | 1 | 90.9% | 103 | 9 | 91.3% | 559 | 53 | 90.5% |
| SAN | 90.5% | - | - | - | 75 | 21 | 72.0% | 434 | 96 | 77.9% |
| SEA | 85.0% | 8 | 0 | 100.0% | 56 | 6 | 89.3% | 303 | 35 | 88.4% |
| SJC | 89.0% | 7 | 1 | 85.7% | 49 | 6 | 87.8% | 265 | 41 | 84.5% |
| SLO | 90.0% | - | - | - | - | - | - | 42 | 8 | 81.0% |
| SPK | 90.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 37 | 0 | 100.0% |
| VAC | 97.0% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 72 | 1 | 98.6% |
| VNC | - | - | - | - | - | - | - | 5 | 1 | 80.0% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 3 | 103 | 6 | 1 | 83.3% | 35 | 7 | 80.0% | 6 | 6 | 0.0% | 33 | 25 | 24.2% |
| 4 | 294 | 6 | 2 | 66.7% | 34 | 5 | 85.3% | 6 | 6 | 0.0% | 33 | 29 | 12.1% |
| 5 | 48 | 7 | 0 | 100.0% | 37 | 2 | 94.6% | 7 | 3 | 57.1% | 37 | 11 | 70.3% |
| 6 | 140 | 7 | 2 | 71.4% | 37 | 15 | 59.5% | 7 | 5 | 28.6% | 37 | 14 | 62.2% |
| 7 | | 7 | 1 | 85.7% | 37 | 3 | 91.9% | 7 | 1 | 85.7% | 37 | 3 | 91.9% |
| 8 | | 7 | 1 | 85.7% | 37 | 8 | 78.4% | 7 | 3 | 57.1% | 37 | 19 | 48.6% |
| 11 | | 7 | 1 | 85.7% | 38 | 5 | 86.8% | 6 | 5 | 16.7% | 37 | 25 | 32.4% |
| 14 | | 7 | 2 | 71.4% | 38 | 11 | 71.1% | 7 | 5 | 28.6% | 38 | 24 | 36.8% |
| 19 | | 7 | 2 | 71.4% | 38 | 8 | 78.9% | 7 | 2 | 71.4% | 37 | 8 | 78.4% |
| 20 | 81 | 7 | 0 | 100.0% | 38 | 3 | 92.1% | 7 | 1 | 85.7% | 38 | 5 | 86.8% |
| 21 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 1 | 85.7% | 37 | 14 | 62.2% |
| 22 | 270 | 7 | 2 | 71.4% | 38 | 9 | 76.3% | 7 | 3 | 57.1% | 38 | 21 | 44.7% |
| 23 | | 7 | 0 | 100.0% | 35 | 0 | 100.0% | 7 | 0 | 100.0% | 35 | 6 | 82.9% |
| 24 | | 7 | 0 | 100.0% | 34 | 0 | 100.0% | 7 | 1 | 85.7% | 34 | 7 | 79.4% |
| 25 | | 7 | 0 | 100.0% | 34 | 0 | 100.0% | 7 | 0 | 100.0% | 34 | 7 | 79.4% |
| 26 | | 7 | 0 | 100.0% | 35 | 0 | 100.0% | 7 | 1 | 85.7% | 35 | 9 | 74.3% |
| 27 | | 7 | 3 | 57.1% | 37 | 3 | 91.9% | 6 | 2 | 66.7% | 36 | 8 | 77.8% |
| 28 | | 6 | 0 | 100.0% | 36 | 4 | 88.9% | 6 | 0 | 100.0% | 36 | 6 | 83.3% |
| 40 | 463 | 7 | 2 | 71.4% | 38 | 12 | 68.4% | 7 | 7 | 0.0% | 38 | 21 | 44.7% |
| 41 | 16 | 7 | 3 | 57.1% | 38 | 6 | 84.2% | 7 | 7 | 0.0% | 38 | 22 | 42.1% |
| 42 | | 7 | 0 | 100.0% | 38 | 3 | 92.1% | 7 | 1 | 85.7% | 38 | 12 | 68.4% |
| 43 | | 7 | 1 | 85.7% | 38 | 9 | 76.3% | 7 | 1 | 85.7% | 37 | 13 | 64.9% |
| 48 | 17 | 7 | 1 | 85.7% | 38 | 5 | 86.8% | 7 | 2 | 71.4% | 38 | 14 | 63.2% |
| 49 | 62 | 7 | 0 | 100.0% | 38 | 5 | 86.8% | 7 | 2 | 71.4% | 38 | 8 | 78.9% |
| 51 | 23 | 3 | 1 | 66.7% | 16 | 4 | 75.0% | 3 | 1 | 66.7% | 17 | 6 | 64.7% |
| 52 | 125 | 7 | 6 | 14.3% | 36 | 11 | 69.4% | 7 | 5 | 28.6% | 36 | 21 | 41.7% |
| 53 | 190 | 7 | 6 | 14.3% | 36 | 18 | 50.0% | 7 | 7 | 0.0% | 36 | 32 | 11.1% |
| 54 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 0 | 100.0% |
| 57 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 58 | 27 | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 2 | 71.4% | 38 | 28 | 26.3% |
| 59 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 1 | 85.7% | 38 | 23 | 39.5% |
| 63 | 62 | 7 | 1 | 85.7% | 38 | 13 | 65.8% | 7 | 7 | 0.0% | 38 | 35 | 7.9% |
| 64 | | 7 | 2 | 71.4% | 38 | 13 | 65.8% | 7 | 5 | 28.6% | 38 | 21 | 44.7% |
| 65 | 76 | 2 | 1 | 50.0% | 12 | 2 | 83.3% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 66 | | 7 | 1 | 85.7% | 37 | 5 | 86.5% | 7 | 3 | 57.1% | 37 | 8 | 78.4% |
| 68 | 23 | 7 | 0 | 100.0% | 38 | 9 | 76.3% | 7 | 1 | 85.7% | 38 | 8 | 78.9% |
| 69 | | 7 | 1 | 85.7% | 38 | 11 | 71.1% | 7 | 0 | 100.0% | 38 | 2 | 94.7% |
| 71 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 6 | 4 | 33.3% | 37 | 10 | 73.0% |
| 72 | | 7 | 2 | 71.4% | 38 | 7 | 81.6% | 6 | 3 | 50.0% | 37 | 6 | 83.8% |
| 73 | 27 | 7 | 1 | 85.7% | 33 | 5 | 84.8% | 7 | 5 | 28.6% | 33 | 18 | 45.5% |
| 74 | 57 | 7 | 1 | 85.7% | 33 | 7 | 78.8% | 7 | 4 | 42.9% | 33 | 17 | 48.5% |
| 75 | 22 | 7 | 1 | 85.7% | 38 | 3 | 92.1% | 7 | 3 | 57.1% | 36 | 10 | 72.2% |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 76 | 20 | 7 | 0 | 100.0% | 37 | 5 | 86.5% | 7 | 5 | 28.6% | 36 | 17 | 52.8% |
| 77 | 50 | 7 | 1 | 85.7% | 38 | 5 | 86.8% | 7 | 4 | 42.9% | 38 | 16 | 57.9% |
| 78 | | 7 | 0 | 100.0% | 38 | 4 | 89.5% | 7 | 2 | 71.4% | 39 | 9 | 76.9% |
| 79 | 18 | 7 | 0 | 100.0% | 38 | 6 | 84.2% | 7 | 6 | 14.3% | 38 | 18 | 52.6% |
| 80 | | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 4 | 42.9% | 38 | 12 | 68.4% |
| 82 | 37 | 2 | 0 | 100.0% | 10 | 1 | 90.0% | 2 | 1 | 50.0% | 10 | 1 | 90.0% |
| 87 | | 2 | 0 | 100.0% | 11 | 5 | 54.5% | 2 | 0 | 100.0% | 11 | 3 | 72.7% |
| 88 | 48 | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 89 | 33 | 7 | 0 | 100.0% | 27 | 1 | 96.3% | 7 | 6 | 14.3% | 27 | 16 | 40.7% |
| 90 | | 7 | 1 | 85.7% | 27 | 1 | 96.3% | 7 | 4 | 42.9% | 27 | 11 | 59.3% |
| 94 | | 7 | 0 | 100.0% | 27 | 4 | 85.2% | 7 | 2 | 71.4% | 27 | 5 | 81.5% |
| 97 | | 7 | 2 | 71.4% | 38 | 12 | 68.4% | 7 | 6 | 14.3% | 38 | 11 | 71.1% |
| 98 | 18 | 7 | 2 | 71.4% | 38 | 5 | 86.8% | 7 | 3 | 57.1% | 38 | 15 | 60.5% |
| 99 | 25 | 2 | 1 | 50.0% | 11 | 2 | 81.8% | 2 | 1 | 50.0% | 11 | 4 | 63.6% |
| 101 | | 2 | 0 | 100.0% | 10 | 1 | 90.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 103 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 106 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 0 | 100.0% |
| 107 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 0 | 100.0% |
| 109 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 118 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 0 | 100.0% |
| 124 | 16 | 2 | 0 | 100.0% | 11 | 3 | 72.7% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 126 | | 2 | 0 | 100.0% | 10 | 1 | 90.0% | 2 | 0 | 100.0% | 10 | 3 | 70.0% |
| 127 | | 2 | 0 | 100.0% | 10 | 2 | 80.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 135 | 39 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 140 | 21 | 2 | 0 | 100.0% | 11 | 2 | 81.8% | 2 | 2 | 0.0% | 11 | 6 | 45.5% |
| 142 | | 2 | 0 | 100.0% | 10 | 2 | 80.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 143 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 4 | 63.6% |
| 144 | | 2 | 0 | 100.0% | 10 | 7 | 30.0% | 2 | 0 | 100.0% | 10 | 0 | 100.0% |
| 146 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 3 | 72.7% |
| 147 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 5 | 50.0% |
| 150 | 52 | 2 | 1 | 50.0% | 11 | 7 | 36.4% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 151 | | 2 | 1 | 50.0% | 18 | 14 | 22.2% | 2 | 0 | 100.0% | 18 | 3 | 83.3% |
| 152 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 0 | 100.0% |
| 153 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 155 | | 2 | 0 | 100.0% | 12 | 1 | 91.7% | 2 | 0 | 100.0% | 12 | 1 | 91.7% |
| 156 | 68 | 2 | 0 | 100.0% | 12 | 0 | 100.0% | 2 | 1 | 50.0% | 12 | 6 | 50.0% |
| 158 | | 2 | 0 | 100.0% | 11 | 3 | 72.7% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 159 | | 2 | 0 | 100.0% | 10 | 5 | 50.0% | 2 | 0 | 100.0% | 10 | 2 | 80.0% |
| 160 | | 2 | 1 | 50.0% | 11 | 5 | 54.5% | 2 | 0 | 100.0% | 11 | 3 | 72.7% |
| 161 | 76 | 2 | 1 | 50.0% | 11 | 3 | 72.7% | 2 | 2 | 0.0% | 11 | 5 | 54.5% |
| 162 | 41 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 4 | 63.6% |
| 163 | 61 | 2 | 0 | 100.0% | 10 | 1 | 90.0% | 2 | 2 | 0.0% | 10 | 5 | 50.0% |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 164 | 99 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 2 | 0.0% | 11 | 5 | 54.5% |
| 165 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 167 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 3 | 70.0% |
| 168 | | 2 | 0 | 100.0% | 10 | 1 | 90.0% | 2 | 0 | 100.0% | 10 | 3 | 70.0% |
| 194 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 195 | 33 | 2 | 1 | 50.0% | 11 | 1 | 90.9% | 2 | 2 | 0.0% | 11 | 5 | 54.5% |
| 230 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 0 | 100.0% | 38 | 1 | 97.4% |
| 232 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 1 | 85.7% | 38 | 3 | 92.1% |
| 233 | | 7 | 1 | 85.7% | 38 | 13 | 65.8% | 7 | 2 | 71.4% | 38 | 14 | 63.2% |
| 234 | | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 1 | 97.4% |
| 235 | | 7 | 3 | 57.1% | 38 | 7 | 81.6% | 7 | 2 | 71.4% | 38 | 11 | 71.1% |
| 236 | | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 1 | 85.7% | 38 | 7 | 81.6% |
| 237 | | 7 | 2 | 71.4% | 38 | 6 | 84.2% | 7 | 1 | 85.7% | 38 | 11 | 71.1% |
| 238 | 18 | 7 | 4 | 42.9% | 38 | 8 | 78.9% | 7 | 2 | 71.4% | 38 | 5 | 86.8% |
| 239 | | 7 | 1 | 85.7% | 37 | 6 | 83.8% | 7 | 2 | 71.4% | 37 | 4 | 89.2% |
| 240 | | 7 | 0 | 100.0% | 38 | 4 | 89.5% | 6 | 0 | 100.0% | 37 | 2 | 94.6% |
| 241 | 17 | 7 | 1 | 85.7% | 38 | 7 | 81.6% | 7 | 3 | 57.1% | 38 | 11 | 71.1% |
| 243 | | 7 | 0 | 100.0% | 38 | 5 | 86.8% | 7 | 0 | 100.0% | 38 | 1 | 97.4% |
| 244 | 33 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 2 | 71.4% | 38 | 12 | 68.4% |
| 245 | | 7 | 0 | 100.0% | 38 | 5 | 86.8% | 7 | 0 | 100.0% | 38 | 5 | 86.8% |
| 280 | 50 | 7 | 0 | 100.0% | 38 | 3 | 92.1% | 7 | 3 | 57.1% | 38 | 15 | 60.5% |
| 281 | No OS | 7 | 0 | 100.0% | 38 | 5 | 86.8% | 7 | 4 | 42.9% | 38 | 7 | 81.6% |
| 283 | 91 | 7 | 1 | 85.7% | 38 | 2 | 94.7% | 7 | 4 | 42.9% | 38 | 8 | 78.9% |
| 284 | 23 | 7 | 1 | 85.7% | 38 | 3 | 92.1% | 7 | 3 | 57.1% | 38 | 6 | 84.2% |
| 290 | | 7 | 0 | 100.0% | 38 | 5 | 86.8% | 7 | 5 | 28.6% | 37 | 17 | 54.1% |
| 291 | | 7 | 0 | 100.0% | 38 | 17 | 55.3% | 7 | 1 | 85.7% | 38 | 8 | 78.9% |
| 300 | | 7 | 0 | 100.0% | 37 | 1 | 97.3% | 7 | 0 | 100.0% | 37 | 7 | 81.1% |
| 301 | | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 0 | 100.0% | 38 | 4 | 89.5% |
| 302 | 116 | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 2 | 71.4% | 38 | 10 | 73.7% |
| 305 | 67 | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 3 | 57.1% | 38 | 15 | 60.5% |
| 306 | 88 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 1 | 85.7% | 38 | 11 | 71.1% |
| 307 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 2 | 71.4% | 38 | 12 | 68.4% |
| 311 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 0 | 100.0% | 38 | 4 | 89.5% |
| 316 | 17 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 3 | 57.1% | 38 | 12 | 68.4% |
| 318 | Cncld | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 6 | 4 | 33.3% | 37 | 16 | 56.8% |
| 319 | 49 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 4 | 42.9% | 37 | 27 | 27.0% |
| 330 | | 6 | 0 | 100.0% | 33 | 0 | 100.0% | 6 | 0 | 100.0% | 32 | 1 | 96.9% |
| 331 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 0 | 100.0% | 36 | 1 | 97.2% |
| 332 | | 7 | 0 | 100.0% | 38 | 3 | 92.1% | 7 | 2 | 71.4% | 38 | 3 | 92.1% |
| 334 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 0 | 100.0% | 38 | 1 | 97.4% |
| 335 | | 7 | 0 | 100.0% | 38 | 6 | 84.2% | 6 | 0 | 100.0% | 37 | 3 | 91.9% |
| 336 | | 7 | 0 | 100.0% | 37 | 0 | 100.0% | 7 | 3 | 57.1% | 37 | 4 | 89.2% |

# Amtrak On Time Performance

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 337 | | 7 | 2 | 71.4% | 37 | 3 | 91.9% | 7 | 2 | 71.4% | 37 | 3 | 91.9% |
| 338 | | 7 | 2 | 71.4% | 38 | 6 | 84.2% | 7 | 2 | 71.4% | 38 | 11 | 71.1% |
| 339 | | 7 | 1 | 85.7% | 38 | 9 | 76.3% | 7 | 1 | 85.7% | 37 | 7 | 81.1% |
| 341 | | 7 | 0 | 100.0% | 37 | 5 | 86.5% | 7 | 0 | 100.0% | 37 | 2 | 94.6% |
| 342 | | 7 | 1 | 85.7% | 38 | 5 | 86.8% | 7 | 1 | 85.7% | 37 | 4 | 89.2% |
| 343 | | 1 | 0 | 100.0% | 6 | 0 | 100.0% | 1 | 0 | 100.0% | 6 | 0 | 100.0% |
| 350 | | 7 | 0 | 100.0% | 35 | 2 | 94.3% | 7 | 1 | 85.7% | 33 | 13 | 60.6% |
| 351 | | 7 | 0 | 100.0% | 33 | 4 | 87.9% | 7 | 2 | 71.4% | 31 | 7 | 77.4% |
| 352 | | 7 | 1 | 85.7% | 34 | 5 | 85.3% | 7 | 3 | 57.1% | 33 | 13 | 60.6% |
| 353 | | 7 | 0 | 100.0% | 35 | 4 | 88.6% | 7 | 1 | 85.7% | 34 | 5 | 85.3% |
| 354 | | 7 | 0 | 100.0% | 35 | 6 | 82.9% | 7 | 0 | 100.0% | 34 | 11 | 67.6% |
| 355 | | 7 | 1 | 85.7% | 34 | 6 | 82.4% | 7 | 1 | 85.7% | 33 | 9 | 72.7% |
| 364 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 1 | 85.7% | 38 | 9 | 76.3% |
| 365 | | 7 | 1 | 85.7% | 38 | 2 | 94.7% | 7 | 2 | 71.4% | 38 | 13 | 65.8% |
| 370 | 49 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 1 | 85.7% | 38 | 5 | 86.8% |
| 371 | | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 1 | 85.7% | 38 | 1 | 97.4% |
| 380 | 160 | 6 | 0 | 100.0% | 37 | 2 | 94.6% | 6 | 1 | 83.3% | 37 | 11 | 70.3% |
| 381 | | 7 | 1 | 85.7% | 38 | 1 | 97.4% | 7 | 1 | 85.7% | 38 | 8 | 78.9% |
| 382 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 0 | 100.0% | 38 | 7 | 81.6% |
| 383 | 54 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 6 | 3 | 50.0% | 37 | 15 | 59.5% |
| 390 | 41 | 7 | 2 | 71.4% | 37 | 7 | 81.1% | 7 | 2 | 71.4% | 37 | 11 | 70.3% |
| 391 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 0 | 100.0% | 38 | 6 | 84.2% |
| 392 | | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 1 | 85.7% | 38 | 24 | 36.8% |
| 393 | | 7 | 0 | 100.0% | 37 | 4 | 89.2% | 7 | 0 | 100.0% | 37 | 18 | 51.4% |
| 400 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 405 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 450 | | 2 | 0 | 100.0% | 11 | 3 | 72.7% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 460 | | 2 | 1 | 50.0% | 11 | 5 | 54.5% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 461 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 463 | | 1 | 0 | 100.0% | 6 | 1 | 83.3% | 1 | 0 | 100.0% | 6 | 1 | 83.3% |
| 464 | 42 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 467 | | 1 | 0 | 100.0% | 6 | 0 | 100.0% | 1 | 0 | 100.0% | 6 | 0 | 100.0% |
| 488 | 55 | 2 | 0 | 100.0% | 11 | 4 | 63.6% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 499 | 49 | 2 | 1 | 50.0% | 11 | 3 | 72.7% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 500 | | 7 | 1 | 85.7% | 38 | 3 | 92.1% | 7 | 3 | 57.1% | 38 | 8 | 78.9% |
| 503 | | 7 | 0 | 100.0% | 38 | 7 | 81.6% | 7 | 2 | 71.4% | 38 | 16 | 57.9% |
| 504 | | 7 | 0 | 100.0% | 36 | 1 | 97.2% | 7 | 2 | 71.4% | 36 | 15 | 58.3% |
| 505 | | 7 | 1 | 85.7% | 38 | 2 | 94.7% | 7 | 3 | 57.1% | 38 | 9 | 76.3% |
| 506 | | 7 | 1 | 85.7% | 38 | 3 | 92.1% | 7 | 1 | 85.7% | 37 | 7 | 81.1% |
| 507 | | 7 | 2 | 71.4% | 38 | 5 | 86.8% | 7 | 2 | 71.4% | 36 | 13 | 63.9% |
| 508 | 19 | 7 | 1 | 85.7% | 38 | 4 | 89.5% | 7 | 1 | 85.7% | 38 | 13 | 65.8% |
| 509 | 75 | 7 | 1 | 85.7% | 38 | 2 | 94.7% | 7 | 6 | 14.3% | 38 | 20 | 47.4% |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 511 | 91 | 7 | 0 | 100.0% | 38 | 1 | 97.4% | 7 | 2 | 71.4% | 38 | 6 | 84.2% |
| 516 | | 7 | 0 | 100.0% | 36 | 4 | 88.9% | 7 | 3 | 57.1% | 35 | 19 | 45.7% |
| 517 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 3 | 57.1% | 38 | 16 | 57.9% |
| 518 | 72 | 7 | 2 | 71.4% | 38 | 5 | 86.8% | 7 | 6 | 14.3% | 37 | 20 | 45.9% |
| 519 | | 7 | 0 | 100.0% | 36 | 0 | 100.0% | 7 | 1 | 85.7% | 36 | 6 | 83.3% |
| 600 | | 7 | 0 | 100.0% | 36 | 1 | 97.2% | 7 | 1 | 85.7% | 36 | 5 | 86.1% |
| 607 | | 7 | 0 | 100.0% | 36 | 2 | 94.4% | 7 | 0 | 100.0% | 36 | 1 | 97.2% |
| 626 | | 7 | 2 | 71.4% | 36 | 7 | 80.6% | 7 | 0 | 100.0% | 36 | 5 | 86.1% |
| 643 | | 7 | 4 | 42.9% | 36 | 12 | 66.7% | 7 | 0 | 100.0% | 36 | 3 | 91.7% |
| 645 | | 7 | 4 | 42.9% | 36 | 13 | 63.9% | 7 | 0 | 100.0% | 35 | 4 | 88.6% |
| 647 | | 7 | 0 | 100.0% | 35 | 4 | 88.6% | 7 | 0 | 100.0% | 34 | 1 | 97.1% |
| 649 | | 7 | 0 | 100.0% | 36 | 2 | 94.4% | 7 | 1 | 85.7% | 36 | 5 | 86.1% |
| 650 | | 7 | 1 | 85.7% | 36 | 5 | 86.1% | 7 | 1 | 85.7% | 36 | 3 | 91.7% |
| 652 | | 7 | 0 | 100.0% | 36 | 3 | 91.7% | 7 | 0 | 100.0% | 36 | 2 | 94.4% |
| 655 | | 7 | 1 | 85.7% | 36 | 4 | 88.9% | 7 | 0 | 100.0% | 36 | 2 | 94.4% |
| 656 | | 7 | 2 | 71.4% | 36 | 7 | 80.6% | 7 | 0 | 100.0% | 36 | 5 | 86.1% |
| 658 | | 7 | 1 | 85.7% | 35 | 2 | 94.3% | 7 | 0 | 100.0% | 35 | 1 | 97.1% |
| 661 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 662 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 664 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 667 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 0 | 100.0% |
| 690 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 1 | 50.0% | 11 | 1 | 90.9% |
| 691 | | 2 | 1 | 50.0% | 11 | 1 | 90.9% | 1 | 0 | 100.0% | 10 | 1 | 90.0% |
| 692 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 693 | | 2 | 0 | 100.0% | 11 | 2 | 81.8% | 2 | 1 | 50.0% | 11 | 4 | 63.6% |
| 694 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 695 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 1 | 90.9% |
| 696 | 36 | 2 | 1 | 50.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 697 | 34 | 2 | 0 | 100.0% | 11 | 2 | 81.8% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 698 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 0 | 100.0% |
| 701 | 17 | 7 | 2 | 71.4% | 38 | 6 | 84.2% | 7 | 3 | 57.1% | 38 | 10 | 73.7% |
| 702 | | 7 | 0 | 100.0% | 38 | 2 | 94.7% | 7 | 1 | 85.7% | 38 | 15 | 60.5% |
| 703 | | 7 | 2 | 71.4% | 38 | 12 | 68.4% | 7 | 3 | 57.1% | 38 | 9 | 76.3% |
| 704 | | 7 | 3 | 57.1% | 38 | 9 | 76.3% | 7 | 1 | 85.7% | 38 | 5 | 86.8% |
| 710 | | 7 | 3 | 57.1% | 38 | 9 | 76.3% | 7 | 1 | 85.7% | 38 | 8 | 78.9% |
| 711 | | 7 | 0 | 100.0% | 38 | 6 | 84.2% | 7 | 1 | 85.7% | 33 | 5 | 84.8% |
| 712 | | 7 | 2 | 71.4% | 38 | 12 | 68.4% | 7 | 4 | 42.9% | 38 | 17 | 55.3% |
| 713 | 28 | 7 | 2 | 71.4% | 35 | 12 | 65.7% | 7 | 2 | 71.4% | 30 | 8 | 73.3% |
| 714 | | 7 | 4 | 42.9% | 38 | 21 | 44.7% | 7 | 4 | 42.9% | 37 | 20 | 45.9% |
| 715 | | 7 | 0 | 100.0% | 38 | 6 | 84.2% | 6 | 3 | 50.0% | 36 | 18 | 50.0% |
| 716 | 74 | 7 | 2 | 71.4% | 37 | 17 | 54.1% | 7 | 3 | 57.1% | 36 | 10 | 72.2% |
| 717 | | 7 | 2 | 71.4% | 38 | 16 | 57.9% | 7 | 3 | 57.1% | 35 | 15 | 57.1% |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 718 | 260 | 7 | 6 | 14.3% | 38 | 26 | 31.6% | 7 | 3 | 57.1% | 38 | 15 | 60.5% |
| 719 | | 7 | 3 | 57.1% | 38 | 9 | 76.3% | 7 | 1 | 85.7% | 38 | 8 | 78.9% |
| 720 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 10 | 0 | 100.0% |
| 723 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 1 | 50.0% | 11 | 2 | 81.8% |
| 724 | | 2 | 0 | 100.0% | 11 | 2 | 81.8% | 2 | 0 | 100.0% | 11 | 3 | 72.7% |
| 727 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 728 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 4 | 63.6% |
| 729 | 28 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 732 | 17 | 2 | 1 | 50.0% | 11 | 4 | 63.6% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |
| 733 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 4 | 63.6% |
| 734 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 3 | 72.7% |
| 736 | Cncld | 2 | 1 | 50.0% | 11 | 3 | 72.7% | 1 | 0 | 100.0% | 9 | 1 | 88.9% |
| 737 | Cncld | 2 | 0 | 100.0% | 10 | 1 | 90.0% | 1 | 0 | 100.0% | 8 | 0 | 100.0% |
| 738 | 66 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 4 | 63.6% |
| 741 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 2 | 80.0% |
| 742 | 28 | 2 | 1 | 50.0% | 9 | 2 | 77.8% | 2 | 1 | 50.0% | 9 | 2 | 77.8% |
| 743 | 87 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 10 | 1 | 90.0% |
| 744 | | 2 | 0 | 100.0% | 11 | 3 | 72.7% | 2 | 1 | 50.0% | 11 | 5 | 54.5% |
| 745 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 3 | 72.7% |
| 746 | | 2 | 1 | 50.0% | 10 | 2 | 80.0% | 2 | 0 | 100.0% | 9 | 3 | 66.7% |
| 747 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 4 | 63.6% |
| 748 | | 2 | 0 | 100.0% | 11 | 2 | 81.8% | 2 | 0 | 100.0% | 11 | 2 | 81.8% |
| 751 | Cncld | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 1 | 0 | 100.0% | 10 | 0 | 100.0% |
| 821 | 21 | 7 | 0 | 100.0% | 37 | 2 | 94.6% | 7 | 5 | 28.6% | 37 | 29 | 21.6% |
| 822 | 29 | 7 | 0 | 100.0% | 37 | 2 | 94.6% | 7 | 5 | 28.6% | 37 | 30 | 18.9% |
| 1128 | | 5 | 0 | 100.0% | 20 | 2 | 90.0% | 5 | 1 | 80.0% | 20 | 2 | 90.0% |
| 1169 | | 5 | 1 | 80.0% | 19 | 4 | 78.9% | 5 | 3 | 40.0% | 19 | 5 | 73.7% |
| 1333 | | 7 | 1 | 85.7% | 38 | 4 | 89.5% | 7 | 4 | 42.9% | 38 | 14 | 63.2% |
| 1340 | 24 | 7 | 0 | 100.0% | 38 | 0 | 100.0% | 7 | 1 | 85.7% | 38 | 5 | 86.8% |
| 1689 | | 3 | 0 | 100.0% | 17 | 0 | 100.0% | 2 | 0 | 100.0% | 16 | 3 | 81.3% |
| 2201 | | 2 | 0 | 100.0% | 9 | 0 | 100.0% | 2 | 0 | 100.0% | 9 | 0 | 100.0% |
| 2203 | | 2 | 0 | 100.0% | 11 | 0 | 100.0% | 2 | 0 | 100.0% | 11 | 0 | 100.0% |
| 2205 | | 2 | 0 | 100.0% | 9 | 0 | 100.0% | 2 | 0 | 100.0% | 9 | 0 | 100.0% |
| 2216 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 2218 | | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 0 | 100.0% | 10 | 1 | 90.0% |
| 2220 | | 2 | 0 | 100.0% | 9 | 0 | 100.0% | 2 | 0 | 100.0% | 9 | 2 | 77.8% |
| 2248 | | 2 | 0 | 100.0% | 9 | 0 | 100.0% | 2 | 0 | 100.0% | 9 | 1 | 88.9% |
| 2249 | | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 2 | 0 | 100.0% | 8 | 1 | 87.5% |
| 2250 | 28 | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 2 | 1 | 50.0% | 10 | 2 | 80.0% |
| 2251 | | 2 | 0 | 100.0% | 9 | 1 | 88.9% | 2 | 1 | 50.0% | 9 | 4 | 55.6% |
| 2252 | | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 0 | 100.0% | 11 | 0 | 100.0% |
| 2255 | 84 | 2 | 0 | 100.0% | 11 | 1 | 90.9% | 2 | 1 | 50.0% | 11 | 3 | 72.7% |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 2250 | BOS | 28 | OTH | 29 | OTH | 22 | STM-STM | MN | Car 3628 and car 3905 door issues in both sides coming into Stamford |
| 2255 | WAS | 71 | | | | | | | |
| 65 | NPN | 76 | DBS | 91 | DBS | 91 | RVM-WBG | CS | Debris blocking track (no debris strike) Tree on tracks, Other, east Providence forge |
| 82 | BOS | 37 | SMW | 22 | SMW | 19 | NYP-XSH | AM | Scheduled in track usage program, Other, HELD FOR AM87 DELAYED AM161 |
| 88 | BOS | 48 | PTI | 37 | PTI | 37 | NYP-XSH | AM | Meet, AM163, Other, HELD FOR AM163 A/C DSPR UNABLE TO DISPLAY 2W SIG AT PELHAM BY |
| 99 | NPN | 25 | DSR | 32 | DSR | 20 | NHV-BRP | MN | Per bulletin Waiting for track 4 for BRP station stop., Milepost, 57.0, 56.8, 30, 2,4 |
| 124 | PHL | 16 | OTH | 21 | RTE | 19 | ALX-XVG | AM | Dispatcher hold Single tracking/Hold for route into station., Control Point, CP Virginia |
| 135 | WAS | 39 | SMW | 22 | DMW | 13 | KIN-XGX | AM | Held for or routed around MW work or equipment, Milepost w/Letters, KIN, XGX, AM135 held to allow AM2250 to clear before crossing over to run around OOS trk 1 |
| 140 | SPG | 21 | DSR | 24 | DSR | 19 | BRP-NHV | MN | Per bulletin Aces failure CP 261., Milepost, 58.6, 57.0, 10, 4 |
| 150 | BOS | 52 | POL | 31 | POL | 31 | KIN-PVD | AM | Fire department hold, Fire dept reports sinkhole on London st street underpass mph 171-172 |
| 156 | NYP | 68 | PTI | 49 | PTI | 36 | ALX-XVG | AM | Meet p151, Milepost, 109.0, 109.0 |
| 161 | WAS | 76 | POL | 27 | POL | 27 | PVD-KIN | AM | Fire department hold, Fire dept reports sinkhole on London st street underpass |
| 162 | BOS | 41 | CTI | 23 | CTI | 13 | NYP-XSH | AM | Cross Traffic, MN, MN, Other, XSH-XSH, MNRR TRAIN ROUTED AHEAD |
| 163 | WAS | 61 | DCS | 26 | DCS | 26 | XSH-NYP | AM | Restrictive signal(s) from unknown cause, DSPR UNABLE TO DISPLAY SIGNALS GIVEN 241 TROUGH INTERLOCKING , Other, NO.2 TRACK PELHAM BAY |
| 164 | BOS | 99 | DMW | 35 | DMW | 35 | NLC-MYS | AM | Held for or routed around MW work or equipment, Milepost w/Letters, NLC, MYS, AM164 held to allow AM165 to clear run around OOS trk 1 |
| 195 | WAS | 33 | CTI | 18 | CTI | 16 | NHV-BRP | MN | Cross over or go around Put behind a local to avoid the bridge plates on track 3 @ Bridgeport, mnrr, Control Point, cp261 |
| 464 | SPG | 42 | CON | 35 | CON | 35 | NHV-NHV | AM | Hold for connecting train |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 488 | GFD | 55 | CON | 56 | CON | 56 | NHV-NHV | AM | Hold for connecting train |
| 499 | SPG | 49 | ITI | 47 | ITI | 47 | GFD-GFD | MA | Late departure at initial terminal due to late arrival of inbound equipment, 488, Held for equipment off late 488. |
| 52 | LOR | 125 | ITI | 134 | ITI | 134 | SFA-SFA | FR | Late departure at initial terminal due to late arrival of inbound equipment 53 |
| 53 | SFA | 190 | ITI | 198 | ITI | 198 | LOR-LOR | CS | Late departure at initial terminal due to late arrival of inbound equipment 52 |
| 79 | CLT | 18 | PTI | 38 | PTI | 13 | PTB-RMT | CS | Follow 89, Other, collier |
| 20 | NYP | 81 | PTI | 86 | PTI | 49 | ALX-XVG | AM | Meet 89, 79, 155, Control Point, Virginia Ave |
| 696 | BON | 36 | SYS | 27 | SYS | 23 | WOB-BON | MT | Re-crew / job briefing Engineer, ill job briefing conducted, Milepost, 8, 8 |
| 697 | BRK | 34 | SYS | 35 | SYS | 20 | HHL-XP0 | MT | Engineer restroom break Engineer, restroom, brake, and job briefing, Control Point, HA |
| 63 | TWO | 62 | FTI | 32 | FTI | 29 | ROC-BUF | CS | Blocked from station track 2 freights, csx, Control Point, 423 |
| 68 | NYP | 23 | SVS | 25 | SVS | 25 | ALB-ALB | AM | Planned set out / pick out of locomotives, cars or section of train |
| 238 | NYP | 18 | SVS | 33 | SVS | 33 | ALB-ALB | AM | Cut out coach due to flat spots |
| 241 | ALB | 17 | ENG | 12 | ENG | 12 | NYP-XSD | AM | Traction motor, 715\|DX\|DM, REAR END POWER HEP FROM ENG.708 |
| 244 | NYP | 33 | CTI | 37 | CTI | 22 | POU-CRT | MN | Follow metro 4856, Milepost, 72, 34 |
| 280 | NYP | 50 | ENG | 40 | ENG | 40 | ALB-ALB | AM | Flat spots 9709 |
| 281 | NFL | No OS Rpt | ENG | 59 | ENG | 56 | SDY-SDY | AM | Unrecoverable penalty (PCS) 9703 |
| 283 | NFL | 91 | FTI | 68 | FTI | 58 | ROC-BUF | CS | Follow CSX, Milepost w/Letters, CP 373, BUF |
| 284 | NYP | 23 | WTR | 18 | ENG | 8 | ALB-ALB | AM | Flat spots. Set out in ALB for flat spots., 700, 9705 |
| 48 | NYP | 17 | FTI | 27 | DCS | 22 | BUF-BUF | CS | Power switch failure Waiting on I150. Single track CP429-CP423 due to switch failure at CP423. Decided to wait at station rather than at CP429. Using DCS instead of FTI as DCS is root cause., Control Point, 423 |
| 49 | CHI | 62 | FTI | 80 | ENG | 46 | ALB-ALB | AM | Engine problem. Unknown reason. 375, 199 |
| 73 | CLT | 27 | HLD | 15 | HLD | 11 | RGH-CYN | NS | Passenger and/or baggage |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 74 | RGH | 57 | TRS | 45 | TRS | 45 | GRO-BNC | NS | Trespasser strike Trespasser strike at 21.2 nc; was taken by ambulance for medical treatment., Milepost w/Letters, 21.2nc, 21.0nc |
| 75 | CLT | 22 | ADA | 10 | PTI | 10 | CYN-DNC | NS | Meet Amtk 72, Control Point, Nelson |
| 76 | RGH | 20 | PTI | 18 | PTI | 14 | DNC-CYN | NS | Meet Amtk 79, Control Point, Clegg |
| 77 | CLT | 50 | POL | 55 | POL | 55 | DNC-BNC | NS | RR blocked by trespasser or vehicle strike by another train 74 struck trespasser. Waiting for that to clear. |
| 89 | SAV | 33 | FTI | 78 | FTI | 16 | WLN-SSM | CS | Meet L607, Other, a150.9 |
| 98 | NYP | 18 | FTI | 60 | ENG | 40 | FAY-XSE | CS | Undesired emergency application 44 |
| 40 | CHI | 463 | ENG | 271 | ENG | 218 | XDJ-ALX | CS | Oil leak detected after trail loco hep went out 11 |
| 41 | MIA | 16 | FTI | 116 | FTI | 29 | CLB-CLB | CS | Cross Traffic L657-06, Other, CLB STATION |
| 5 | EMY | 48 | FTI | 149 | FTI | 137 | OMA-LNK | BN | BNSF 8465 disabled on M2 @ CP 535. Brought us up to mp 48 then after about an hour shoved back to CP 411 crossed over to m1 the back west. At the time this started there was a tied down train on m2 completely blocking traffic., bnsf 8465, Control Point, 535 |
| 6 | CHI | 140 | FTI | 200 | FTI | 62 | ELK-ELK | UP | Blocked from station track Blocked from departing station. UP 5693 was parked on MT 2 fueling. Our route to go around UP 5693 was thru Elko yard. Held @ ELK depot, waiting for UP 8230 to fuel inside Elko yard, so we could follow UP 8230 thru Elko yard (around UP5693) and to Alazon, UP 8230, UP 5693, |
| 729 | SJC | 28 | TCR | 19 | TCR | 19 | OKJ-OKJ | UP | Set out defective car C8009, C8026, C8205, C8311, C8804, Set out full set due to bad order bathrooms on all cars. Equipment swap at OKJ |
| 732 | SAC | 17 | TCC | 30 | TCC | 30 | OKJ-OKJ | UP | Toilet 8311, Bathroom out of service repairing PA car 5 out of service Car 1 8009 lift out of service Car 2 8205 lift out of service Car 4 both bathrooms out of service per Tazzy Ecoly?Car 5 8311 bathroom out of service until Sac per Chris Tazzy informed Operations. |
| 736 | SAC | Trn Cancelled | | | | | | | |
| 737 | OKJ | Trn Cancelled | TEN | 85 | TEN | 43 | DAV-DAV | UP | Loading problem C2108 |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 738 | SAC | 66 | SVS | 70 | SVS | 70 | SJC-SCC | UP | Unplanned Wye Had to wait for local to clear before using the wye |
| 742 | SAC | 28 | ITI | 31 | ITI | 31 | OKJ-OKJ | UP | Late departure at initial terminal due to late arrival of inbound equipment 743 |
| 743 | OKJ | 87 | TEN | 39 | TEN | 39 | DAV-FFV | UP | Pick up rescue locomotive due to mechanical failure C2108 |
| 751 | OKJ | Trn Cancelled | DCS | 31 | DCS | 18 | SUI-MTZ | UP | Flagging to Cordelia Control Point, cordelia |
| 51 | CHI | 23 | FTI | 79 | FTI | 21 | COI-IND | CS | Cross Traffic Eastbound, unknown, Control Point, CP IU |
| 508 | SEA | 19 | PTI | 27 | PTI | 11 | SLM-ORC | UP | Meet 507, Control Point, Coalca |
| 509 | PDX | 75 | CCR | 26 | CCR | 26 | SEA-TUK | BN | Cab car tagged trail only due to faulty windshield wipers, had to wye train leaving SEA 90253 |
| 511 | PDX | No OS Rpt | DCS | 68 | DCS | 50 | KEL-VAN | BN | Power switch failure Talked by red. B1 and BF1 switches had to be lined by hand. Proceed at restricted speed mp 109.8-112, Control Point, toteff |
| 518 | VAC | 72 | DCS | 31 | WTR | 18 | BEL-X8B | BN | High winds Winds in excess of 55 mph. Passenger trains restricted to 40 mph, Milepost, 102.1, 119.6 |
| 58 | CHI | 27 | FTI | 49 | SYS | 45 | JAN-JAN | CC | Re-crew / job briefing |
| 821 | FTW | 21 | DSR | 19 | DSR | 14 | GLE-FTW | BN | Per bulletin Milepost, 409.5, 409.0, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 407.9, 407.1, 30, m, Milepost, 405.9, 405.0, 60, m, Milepost, 404.2, 403.8, 60, m, Milepost, 403.2, 402.7, 60, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.5, 399.8, 60, m, Milepost, 399.9, 399.5, 60, m, Milepost |
| 822 | OKC | 29 | DSR | 34 | DSR | 17 | FTW-GLE | BN | Per bulletin Milepost, 352.8, 353.3, 60, main 2, Milepost, 353.5, 354.1, 60, main 2, Milepost, 354.0, 354.5, 70, main 1, Milepost, 355.5, 355.7, 70, main 1, Milepost, 357.3, 357.6, 50, main 2, Milepost, 357.3, 358.2, 50, main 2, Milepost, 358.3, 358.4, 50, main 2, Milepost, 361.0, 361.2, 40, main 2, |
| 370 | GRR | 49 | FTI | 60 | FTI | 60 | BAM-HOM | CS | Follow R598, Control Point, EE Wells |
| 701 | SAC | 17 | FTI | 31 | FTI | 24 | BFD-WAC | BN | Meet bnsf 7020, Siding, wasco |
| 713 | OKJ | 28 | FTI | 24 | PTI | 10 | MDR-MCD | BN | Meet amtk 710, Siding, sharon |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 716 | BFD | 74 | TEN | 76 | TEN | 76 | OKJ-OKJ | UP | Equipment swap at OMF CDTX 2002 to CDTX 2004 Locomotive swap at OMF, C2002, C2004 |
| 718 | BFD | 260 | TEN | 194 | TEN | 194 | EMY-EMY | UP | Fuel cut out failure. Mechanical forces met on train on main line C2124 |
| 3 | LAX | 103 | FTI | 178 | FTI | 74 | XIA-GLP | BN | Follow Following freight backed up due to flash flood warnings., BNSF Unknown, Milepost, 31.5, 75, Milepost, 113.3, 128.8 |
| 4 | CHI | 294 | FTI | 325 | FTI | 104 | KNG-FLG | BN | Meet bnsf unknown, Control Point, E Valentine |
| 22 | CHI | 270 | CON | 306 | CON | 306 | SAS-SAS | UP | Hold for connecting train 2 |
| 302 | CHI | 116 | CAR | 128 | CAR | 80 | BNL-PON | UP | Air / Brake / Wheel ID4016, Brake pipe hose damaged. Needed replacement. |
| 305 | STL | 67 | PTI | 77 | PTI | 77 | BNL-BNL | UP | Meet Amtrak 318, Milepost, 124, 124 |
| 306 | CHI | 88 | PTI | 70 | PTI | 63 | LCN-BNL | UP | Amt318 had engine failure and we were behind them stopped at McLean. We had to wait for them to get a freight engine to attach. amt318, Siding, mclean |
| 380 | CHI | 160 | TRS | 146 | TRS | 146 | NPV-LAG | BN | Trespasser strike Waited to be released after passenger strike, Milepost, 28.3, 28.1 |
| 383 | QCY | 54 | CAR | 30 | CAR | 30 | GBB-GBB | BN | Air / Brake / Wheel ID4119, Sticking brakes |
| 390 | CHI | 41 | ENG | 40 | ENG | 40 | CDL-CDL | CC | PTC - On Board Cab Signal or PTC Failure ID4610 |
| 316 | STL | 17 | FTI | 29 | FTI | 10 | LEE-WAR | UP | Meet UP 5525, Siding, Strasburg |
| 318 | CHI | Trn Cancelled | ENG | 231 | ENG | 167 | LCN-BNL | UP | Pick up rescue locomotive due to mechanical failure ID4607 |
| 319 | KCY | 49 | FTI | 29 | FTI | 15 | XTF-SMT | CC | Cross Traffic unknown, Control Point, corwith |
| 1340 | CHI | 24 | DCS | 18 | DCS | 15 | MKA-SVT | CP | Restrictive signal(s) from unknown cause Dark signal at intermediate 73.4 on MT1. Went restricted speed until Oakwood., Dark, Milepost, 73.4, 73.4 |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/7/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| NOL | 1 | 11/07 | 110 | 110 | Late departure at initial terminal due to late arrival of inbound equipment 2, Late turn of equipment |
| ALB | 238 | 11/07 | 33 | 33 | Cut out coach due to flat spots |
| CLT | 74 | 11/07 | 1 | | |
| GFD | 499 | 11/07 | 47 | 47 | Late departure at initial terminal due to late arrival of inbound equipment, 488, Held for equipment off late 488. |
| LOR | 53 | 11/07 | 62 | 62 | Late departure at initial terminal due to late arrival of inbound equipment 52 |
| MIA | 98 | 11/07 | 15 | 15 | PTC problem or failure (cause unknown) Issues with PTC initialization, Other, Mia Amtrak |
| NYP | 235 | 11/07 | 11 | 11 | Late departure at initial terminal due to late arrival of inbound equipment, 238 |
| PHL | 150 | 11/07 | 2 | 2 | PTC - Stop Bypass Permission Required, Control Point, N PENN |
| PHL | 643 | 11/07 | 1 | 1 | Passenger and/or baggage |
| PHL | 645 | 11/07 | 1 | 1 | Passenger and/or baggage |
| SAV | 90 | 11/07 | 3 | 3 | Meet 97, Milepost, 490.2, 490.2 |
| SFA | 52 | 11/07 | 65 | 65 | Late departure at initial terminal due to late arrival of inbound equipment 53 |
| CDL | 390 | 11/07 | 40 | 40 | PTC - On Board Cab Signal or PTC Failure ID4610 |
| CHI | 41 | 11/07 | 164 | 164 | Late departure at initial terminal due to late arrival of inbound equipment 40, Was told to leave with ADA restroom inoperative. Ordered out by General Rodeforeman Maurice Jones. He told glasshouse that we didn't need that coach car and to leave. |
| CHI | 48 | 11/07 | 179 | 179 | Late departure at initial terminal due to late arrival of inbound equipment 8, Instructed by CD-7 Yardmaster to place delay under ITI due to engine failure of AMTK 375 and having to replace with AMTK 305 off of inbound Train 8. |
| CHI | 381 | 11/07 | 1 | 1 | Door ID4314, Door light |
| EMY | 6 | 11/07 | 2 | 2 | Passenger and/or baggage 3 Passengers showed up at last minute and had to walk up to Sleeping Cars. |
| OKJ | 716 | 11/07 | 76 | 76 | Equipment swap at OMF CDTX 2002 to CDTX 2004 Locomotive swap at OMF, C2002, C2004 |
| OKJ | 718 | 11/07 | 3 | 3 | Meet Wait for 715 to come into the yard before we depart, 715, Control Point, magnolia |
| OKJ | 732 | 11/07 | 30 | 30 | Toilet 8311, Bathroom out of service repairing PA car 5 out of service Car 1 8009 lift out of service Car 2 8205 lift out of service Car 4 both bathrooms out of service per Tazzy Ecoly?Car 5 8311 bathroom out of service until Sac per Chris Tazzy informed Operations. |
| OKJ | 736 | 11/07 | (Trn Cxld) | | Third Party Engine Failure |
| OKJ | 742 | 11/07 | 31 | 31 | Late departure at initial terminal due to late arrival of inbound equipment 743 |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/7/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| PDX | 500 | 11/07 | 2 | 2 | Taking a double set due to cancelled train 502. Had some HEP issues to fix. |
| SAC | 704 | 11/07 | 1 | 1 | Door C9304, Door would not close via trainline. Had to walk length of train to close it. |
| SJC | 746 | 11/07 | 1 | | |

# Eastern Region



## Commuter Services

| Service Type | OTP Goal | OTP Day | OTP MTD | OTP Prior Month | Trains Operated | Trains Late |
|---|---|---|---|---|---|---|
| MBTA | 95.0 | 98.0 | 98.0 | 99.14 | 146 | 3 |
| CDOT | 95.0 | 87.5 | 87.5 | 92.4 | 16 | 2 |
| MARC | 95.0 | 77.8 | 89.1 | 90.2 | 18 | 4 |
| SEPTA | 95.0 | 89.2 | 89.7 | 93.7 | 111 | 12 |
| NJT-NED | 95.0 | 92.7 | 92.7 | 88.6 | 137 | 127 |
| NJT-SED | 95.0 | 100.0 | 96.5 | 97.2 | 24 | 0 |

## Operating Highlights

### *Train 98(07) South of Petersburg, VA - Freight Train Interference*

08NOV26: TRain 98(07) operating with engines 342, 387, and 239 customers onboard was delayed 23 miles south of Petersburg, VA on the CSX North End subdivision meeting CSX I032-07 at milepost 45.1.

| Train | Delay | Comment |
|---|---|---|
| 98(07) | 35" | |

### *Train 283(07) West of Rochester, NY - Freight Train Interference*

08NOV26: Train 283(07) operating with engines 107, 708, and 46 customers onboard was delayed 2 miles west of Rochester, NY on the CSX Rochester subdivision holding at CP 373 following CSX freight.

| Train | Delay | Comment |
|---|---|---|
| 283(07) | 58" | |

### *Train 89(07) North of Florence, SC - Freight Train Interference*

07NOV26: Train 89(07) operating with engine 650 and 67 customers onboard was delayed 6 miles north of Florence, SC holding at Mars Bluff milepost 286.3 meeting CSX I032-06.

| Train | Delay | Comment |
|---|---|---|
| 89(07) | 47" | |

### *Train 49/449(07) Albany, NY - Servicing*

07NOV26: TRain 49/449(07) operating with engines 111, 92, and 169 customers onboard was delayed departing Albany, NY due to the equipment arriving backwards and needing to be wyed. In addition to needing to be wyed, a deadhead car was on the consist and caused the train to be too long to fit around the wye causing it to be pulled off before the wye move could start.

| Train | Delay | Comment |
|---|---|---|
| 49/449(07) | 1'14" | |

27-FOI-00137 0000009134 UNCLASSIFIED 11/10/2026

## Train 88(07) East of New York, NY - Passenger Train Interference

07NOV26: Train 88(07) was delayed at MP0.2 east of New York NY Penn Station on the Amtrak NYS Line due to 2W signal at Pelham Bay unable to display. Train held for 163(07) to proceed through and was back on the move east once clear.

| Train | Delay | Comment |
|---|---|---|
| 88(07) | 37" | |
| 488(07) | 56" | HOLD CONNECTIONS |
| 499(07) | 47" | Late Turn 488(07) |

## Train 74(07) North of Greensboro, NC - Trespasser Incident

07NOV26: 425PM ET Train 74(07) with E/514, E/105 plus 4 cars carrying 132 passengers, struck a trespasser on the Norfolk Southern Goldsboro Greensboro subdivision at MP 25.7 north of Greensboro NC station in an area of single track. There were no reported injuries among the passengers or crew. The trespasser was not a fatality. There was no reported damage to the equipment. This did not occur at a DOT grade crossing. The weather at the time of incident was 60° and sunny. Local police, EMS and Norfolk Southern police responded to the scene. Train 77(07) held north of Burlington NC station for open tracks. . Train 74(07) was released at 505PM ET.

| Train | Delay | Comment |
|---|---|---|
| 77(07) | 55" | |
| 74(07) | 45" | |

## Train 281(07) South of Schenectady, NY - Engine Failure

07NOV26: Train 281(07) was delayed beginning at MP159.6, .3 miles south of Schenectady, NY station on the Amtrak Hudson line due to an unrecoverable penalty on cab car 9703. Cab Car 9703 was causing excessive wheel slip send the train into an air brake penalty. Crew attempted to troubleshoot with Albany mechanical but were able to resolve issues. Rescue engine 98 came out of Albany and coupled to train 281(07). At Albany train 281(07) transferred all passengers to 283(07) and terminated. Train 283(07) departed Albany NY station at 445PM ET operating 35 minutes late. As a result train 280(08) was cancelled between Niagara Falls and Albany. Customers were accommodated on the next available service.

| Train | Delay | Comment |
|---|---|---|
| 281(07) | | TERM ALB |
| 283(07) | 20" | |

## Train 238(07) Albany-Rensselaer, NY - Car Failure

07NOV26: Train 238(07) was delayed departing Albany-Rensselaer, NY station/MP142.1 on the Amtrak Hudson line setting out car 82725 for flat spots. Train 238(07) departed Albany-Rensselaer at 1243PM ET operating 33 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 238(07) | 33" | |

## Train 280(07) Albany-Rensselaer, NY - Car Failure

07NOV26: Train 28(07) was delayed departing Albany-Rensselaer, NY station/MP142.1 on the Amtrak Hudson line setting out car 82516 for flat spots. Train 280(07) departed Albany-Rensselaer at 1109AM ET operating 1 hour and 4 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 280(07) | 30" | |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

## NHB Line Sinkhole Under London St. Bridge MP171.84

07NOV26: Sinkhole was reported under the London St. Bridge west of Providence RI station on the Amtrak NHB line at MP171.84. A speed restriction was placed on the tracks from MP171 to MP172 until the track inspector could arrive and inspect the tracks. The track inspector arrived on scene at 1202PM ET inspected the tracks, found no exceptions and released the tracks for normal speed.

| Train | Delay | Comment |
|---|---|---|
| 87(06) | 22" | |
| 150(07) | 31" | |
| 160(07) | 16" | |
| 161(07) | 27" | |
| 163(07) | 03" | |

## Train 65(06) north of Williamsburg, VA - Debris

07NOV26: Train 65(06) was delayed holding at MP58.8, 23.8 miles north of Williamsburg VA. station on the CSX Peninsula subdivision due to a tree on the tracks ahead. Mow responded to the scene and remove the tree from the tracks to clear the route for 65(06). Train 65(06) was back on the move at 1139AM ET.

| Train | Delay | Comment |
|---|---|---|
| 65(06) | 1'31" | |

## Train 40(05) East of Cumberland, MD - Freight Train Interference

07NOV26: Train 40(05) was delayed beginning at MP155.8, east of Cumberland MD. station on the CSX Cumberland subdivision following CSX freight train 674 until MP173.5.

| Train | Delay | Comment |
|---|---|---|
| 40(05) | 31" | |

## Washington Terminal A Interlocking Number 19 Switch Replacement

07NOV26: Due to the Washington Terminal A-Interlocking number 19 switch replacement that was operating behind schedule approximately five to six hours. The AK427, the northward main and number 25 track remained out of service until 5AM ET Sunday. Due to this, the only routes available through Washington Terminal from Virginia were via the number 23 and 24 tracks through the southward main. As a result, trains operating through the area saw delays.

The following engines moves were made in Philadelphia to reduce delays in Washington:

Saturday
--Southbound: Tr 65(06), Tr 151(07), Tr 79(07), Tr 89(07)
--Northbound: Tr 156(07), 158(07), Tr 164(07), Tr 124(07), Tr 66(07)
Sunday
--Southbound: Tr 65(07), Tr 151(08), Tr 79(08), Tr 89(08), Tr 51(08)

| Train | Delay | Comment |
|---|---|---|
| 89(07) | 30" | Engine Add PHL |
| 20(06) | 49" | |
| 164(07) | 35" | Eng Swap PHL |
| 464(07) | 35" | 164(07) connections |
| 156(07) | 36" | PTI |
| 156(07) | 27" | ALX |
| 158(07) | 34" | |

# *Northeast Regional Crescent and Cardinal NS Track Work - 11/21-11/22 TWA 27-*

27-FOJ-00137 0000000131 "UNCLASSIFIED" 11/10/2026

04NOV26: On November 22, 2026, Norfolk Southern will perform signal system upgrade and testing work on the Washington District between MP 9 and MP 19. As a result, Northeast Regional, Crescent, and Cardinal service will be modified.

Northeast Regional
Train 147(21NOV) will terminate at Washington, DC Union Station. Bus 5147 will provide alternate transportation between Washington, DC Union Station and the Roanoke, VA station.
Train 156(22NOV) will originate at Washington, DC Union Station. Bus 5156 will provide alternate transportation between the Roanoke, VA station and Washington, DC Union Station.

Crescent
Train 220(21NOV) will operate in lieu of Train 20(21NOV), departing New Orleans, LA Union Passenger Terminal at 12:40P-CT. The train will operate 3 hours and 30 minutes later between New Orleans and Baltimore, MD Penn Station and 3 hours and 40 minutes later between Baltimore and New York, NY Penn Station.

Cardinal
Train 51(22NOV) will depart New York, NY Penn Station at 10:40A-ET and operate 4 hours later between New York and Chicago, IL Union Station.

**WBS#: B.TR.100150.7326**

# Maintenance of Way Highlights

## *Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work*

27-FOI-00137 0000008701 "UNCLASSIFIED" 1/19/2026

26OCT26: Due to the Veltri continuous outage on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

# Western Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| None | | | | |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| None | | | | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Eastern Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| Train | Projected Need Cars | Projected Need Seats | Number Operated Cars | Number Operated Seats | Standees | Location |
|---|---|---|---|---|---|---|
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

# Western Region
# Operating Highlights



## *Train 511(07) South of Kelso-Longview, WA - Signal*

08NOV26: Train 511(07) was delayed at Toteff/ MP109.8 on the BNSF Seattle Subdivision, 12 miles south of Kelso, WA station, due to a power switch failure. The train received authority by red signal indication, and the B1 and BF1 switches were hand-lined. As a result of the switch failure, Train 511(07) operated at restricted speed between MP 109.8 and MP 112 through Control Point Toteff.

| Train | Delay | Comment |
|---|---|---|
| 511(07) | 50" | |

## *Train 738(07) San Jose, CA - Servicing*

08NOV26: Train 738(07) E/JPBX920, 4 cars, CC/C8312 was initially delayed departing San Jose, CA Diridon Station waiting for freight traffic to clear. Due to a positive train control (PTC) D09 failure that prevented equipment CC/C8312 from leading, the train departed San Jose, CA Diridon Station at 3:35P-PT, operating 45 minutes late, and then performed a wye movement. The train performed an additional wye movement after arrival at Sacramento, CA station to be in position for Train 751(07). Due to the PTC issues on CC/C8312, Train 751(07) was terminated at Emeryville, CA station. Customers traveling to Oakland, CA Jack London Square Station were accommodated on Bus 6653, which made a special stop at Oakland, CA Jack London Square Station.

| Train | Delay | Comment |
|---|---|---|
| 738(07) | 1'10" | FTI/WYE Equipment |
| 751(07) | Terminated EMY | |

## *Train 6(07) West of Winnemucca, NV - Freight Train Interference*

08NOV26: Train 6(07) was delayed at Colado /MP351.4 on the UPRR Nevada Subdivision, 65.8 miles west of Winnemucca, NV station, meeting UP Z-train UP6999.

| Train | Delay | Comment |
|---|---|---|
| 6(07) | 1'11" | |

## *Train 4(06) West of Garden City, KS - Freight Train Interference*

08NOV26: Train 4(06), operating with engines 79/192, 9 coaches, and 105 customers, was delayed, 36 miles west of Garden City, KS, on BNSF La Junta subdivision, due to meeting BNSF 8390 at Sutton Siding. Once the freight cleared and a route was made available, train 4(06) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 4(06) | 43" | |

## *Train 7/27(06) Browning, MT - Freight Train Interference*

08NOV26: Train 7/27(06) was delayed beginning at Browning, MT station/MP1123.9 on the BNSF Hi Line due to following BNSF 4265 to Java West/ MP1166.2.

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

## Train 20(07) West of Atlanta, GA - Signal

08NOV26: Train 20(07), operating with engine 214/386, 8 coaches, and 94 customers, was delayed, 5 miles west of Atlanta, GA, on NS Atlanta North Subdivision, due to an NS signal issue at Control Point Howell, which required all trains operating through the area to hand line switches.

| Train | Delay | Comment |
|---|---|---|
| 20(07) | 53" | |

## Train 370(07) Bangor, MI - Freight Train Interference

08NOV26: Train 370(07), operating with engine 4610, 4 coaches, and 78 customers, was delayed 19 miles North of Bangor, MI, on CSX Grand Rapids subdivision, due to meeting CSX R598 at Control Point Wells. Once the freight cleared and a route was made available, train 370(07) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 370(07) | 1'00" | |

## Train 383(07) Galesburg, IL - Car Failure

08NOV26: Train 383(07), operating with engine 4602, 4 coaches and 51 customers, reported a brake issue on C/4203, prompting an inspection, multiple brake applications and releases, and a roll-by inspection that confirmed no sticking brake. After resuming movement, the crew continued to express concern and, as a precaution, conducted an additional inspection at Macomb, IL station. The inspection determined that a main reservoir pipe had been cut out. The crew cut the pipe back in, correcting the issue, and Train 383(07) resumed operation. As additional information, train 383(07) was inspected by mechanical forces at its end point and no other issues were found.

| Train | Delay | Comment |
|---|---|---|
| 383(07) | 30" | |

## Train 48/448 Chicago, IL - Initial Terminal Delay

08NOV26: Train 48(07) was delayed departing Chicago, Illinois due to a late turn of equipment and a bad order locomotive. As background, inbound 49(06) arrived in Chicago at 1114am; 1 hour and 2 minutes late due to 1 hour and 20 minutes of freight train interference, 46 minutes for locomotive problems in Albany, New York (no explanation given), and 10 minutes of commuter train interference. Equipment set to the yard for servicing and inspection at 148pm. At 330pm, lead locomotive AMTK 375 was bad ordered for continuous wheel shelling. Blue flags were dropped at 438pm and locomotive AMTK 375 was delivered to the wheelhouse for wheel truing at 520pm. At 824pm, the diesel pit bad ordered locomotive AMTK 375 account it would not restart with a hard computer fault. Replacement locomotive AMTK 305 off inbound 8(05) was serviced as the replacement. Locomotive AMTK 305 was released at 936pm, wyed, and tied onto Train 48(07)'s consist at 1016pm. Train 48(07) was released by mechanical at 1137pm, shoved from the yard at 1149pm, and set in the station at 1155pm with 147 passengers to board. Train 48(07) departed Chicago at 1229am.

| Train | Delay | Comment |
|---|---|---|
| 48/448 | 2'59" | |

27-FOI-00137 00000009131 UNCLASSIFIED 11/10/2026

## Train 8/28(06) East of Malta, MT - Signal

07NOV26:Train 8/28(06) was delayed beginning at Saco/MP318 on the BNSF Milk River Subdivision, 28 miles east of Malta, MT to Hinsdale/ MP302 due to track indication and was talked by the signal at restricted speed.

| Train | Delay | Comment |
|---|---|---|
| 8/28(06) | 38" | |

## Train 318(07) Bloomington-Normal, IL - Engine Failure

07NOV26: At approximately 6:50P-CT, Train 318(07), operating with Engine 4607, 7 coaches, and 166 customers, experienced a loss of head-end power (HEP) 23 miles north of the Lincoln, IL station on the Union Pacific Springfield Subdivision after Engine 4607 shut down with numerous faults and was reported to be leaking coolant and oil. A Union Pacific freight locomotive, UP 4580, was dispatched to assist the train, and a Road Foreman of Engines responded to the scene. After UP 4580 was added to the train, Train 318(07) proceeded to the Bloomington-Normal, IL station, where it terminated. All customers onboard detrained and boarded Train 306(07) as well as customers boarding at Bloomington-Normal, IL and downline. Train 318(07) arrived at the Bloomington-Normal, IL station at 8:43P-CT and departed at 8:56P-CT deadheading to Chicago, IL. Train 305(07) departed the Bloomington-Normal, IL station at 8:44P-CT and was operating 1 hour and 10 minutes late. Train 306(07) arrived at the Bloomington-Normal, IL station at 9:13P-CT and was operating 59 minutes late.

**WBS#: B.TR.100150.7336**

| Train | Delay | Comment |
|---|---|---|
| 306(07) | 1'12" | |
| 318(07) | Term BNL | |
| 305(07) | 47" | |

## Train 41(07) Chicago, IL - Initial Terminal Delay

08NOV26: Train 41(07) was delayed departing Chicago, Illinois due to a late turn of equipment off inbound 40(05). Train 40(05) arrived in Chicago at 428pm; 7 hours and 43 minutes late due to a 3 hour and 38-minute delay in Quantico, Virginia for a locomotive failure caused by an oil leak on Amtrak locomotive AMTK 11, 1 hour and 8 minutes in Alexandria, Virginia for a re-crew, 44 minutes in Washington, D.C. setting out defective Amtrak locomotive AMTK 11 and replacing with Amtrak locomotive AMTK 147, 2 hours and 57 minutes of freight train interference, 57 minutes for weather restrictions, and 37 minutes of speed restrictions. Equipment set to the yard for servicing and inspection at 531pm. Train 41(07) was released by mechanical at 743pm, shoved from the yard at 752pm, wyed, and set in station at 829pm. Boarding of the 201 passengers began at 839pm. Train 41(07) departed Chicago at 924pm.

| Train | Delay | Comment |
|---|---|---|
| 41(07) | 2'44" | |

## Train 716(07) Oakland, CA - Third Party Contractor Engine Failure

07NOV26: Train 716(07), operating with equipment CC/C8305 and 8 cars, was delayed departing Oakland, CA Jack London Square Station due to an exhaust leak on equipment E/C2002. Equipment E/C2002 was replaced with E/C2004, and locomotive switching and equipment servicing were performed. Train 716(07) departed Oakland, CA Jack London Square Station at 3:34P-PT, operating 1 hour and 16 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 716(07) | 1'16" | |

27-FOI-00137 0000009130 "UNCLASSIFIED" 11/10/2026

## *Train 729(07) Sacramento, CA - Third Party Contractor Car Failure*

07NOV26: At 9:15A-PT, the conductor on Train 729(07), E/JPBX922-4 cars-CC/C8311, reported multiple cars without operating toilets in consist with only one working restroom in C/C8009. Due to the equipment turns slated for this set of equipment, and the high capacity of customers expected, alternate equipment was sourced at Oakland, CA. The equipment set slated for Train 732(07), E/C2006-4 cars-CC/C8309, was readied and brought from the yard to Oakland Station. Train 729(07) was delayed at Oakland, CA for the 71 customers to transfer to the new set of equipment. Once all customers were transferred, Train 729(07) proceeded south. The equipment was then deadheaded to the Oakland Maintenance Facility to be repaired, arriving at 11:03A-PT.

Train 732(07), CC/C8311-4 cars- E/JPBX922 with 10 customers, was delayed departing Oakland, CA due to a late release from mechanical. Mechanical worked to resolve earlier toilet issues and repair ADA lifts. Once mechanical released the equipment, the equipment departed the Maintenance Facility at 1:07P-PT. The equipment departed with lifts on C/C8009 and C/C8205 still out of service. The restrooms in C/C8026 remained out of service and the restrooms is C/C8311 were not able to be placed in service until further en route. Once all customers were on board, Train 732(07) was able to depart.

| Train | Delay | Comment |
|---|---|---|
| 729(07) | 19" | Transfer Customers OKJ |
| 732(07) | 30" | ITD OKJ |

## *Train 737(07) West of Sacramento, CA - Third Party Contractor Engine Failure*

07NOV26: Train 737(07), E/C2108-3 cars-CC/C8306 with 96 customers onboard, was delayed at Webster/MP 80.9, 9 miles west of Sacramento, CA, on the UPRR Martinez Subdivision due to loading issues on E/C2108. The crew contacted mechanical to troubleshoot. The crew was able to advance the equipment to Davis/ MP 75.5 to continuing troubleshooting efforts and allow for easier customer transfer, if necessary. An Amtrak Road Foreman responded to the scene and the crew continued to troubleshoot with mechanical. Unable to resolve the issue, Train 737(07) was terminated at Davis, CA and all customers were reaccommodated on Train 741(07). Once Train 741(07) arrived into Davis at 1:08P, all customers were transferred and Train 741(07) departed. The continued to troubleshoot to begin deadheading the equipment to the Oakland Maintenance Facility under its own power. Due to equipment availability, Train 736(07) and Train 749(07) were cancelled in their entirety, with customers reaccommodated on the next available service. Troubleshooting efforts were unsuccessful and the equipment was coupled to Train 743(07) at Davis, arriving at 2:07P-PT. Once the equipment was coupled and a brake test was completed the double set operated to Oakland where both sets were deadheaded to the Maintenance Facility for the disabled equipment to be detached and repaired.

| Train | Delay | Comment |
|---|---|---|
| 737(07) | Term DAV | |
| 741(07) | 05" | Transfer customers |
| 736(07) | Cancelled | |
| 749(07) | Cancelled | |
| 743(07) | 39" | |
| 743(07) | 37" | c/o 737 at OMF |
| 742(07) | 31" | ITD OKJ - Equip off 743 |

## *Train 40(05) West of Sandusky, OH - Freight Train Interference*

07NOV26: Train 40(05) was delayed starting 39.4 miles west of Sandusky, OH (MP241.5), on the NSRR Chicago Line, following NS 13N from MP280.9 to MP329. Further delay was incurred downline starting 15.9 miles west of Elkhart, IN, on the NSRR Chicago Line, following NS 31M from MP437 to MP497.

| Train | Delay | Comment |
|---|---|---|
| 40(05) | 37" | Follow NS 13N |
| 40(05) | 56" | Follow NS 31M |

27-FOI-00137 0000009131 "UNCLASSIFIED" 11/10/2026

## *Train 380(07) Naperville, IL - Trespasser Incident*

07NOV26: At 10:13AM-CT, Train 380(07), E/ID4625 with four cars, struck a trespasser 0.3 miles east of Naperville, IL (MP28.5), on the BNSF Chicago Subdivision at MP28.2 on Main Track 3 in DuPage County. The incident did not occur at a grade crossing, and the train was operating at 38 MPH at the time of the strike. Weather conditions were 41 degrees and mostly cloudy. The trespasser was pronounced deceased. There were no injuries to the crew or the 158 customers onboard. Local police, EMS, and the medical examiner responded to the scene. An Amtrak Road Foreman of Engines arrived at 11:00AM-CT. The engineer requested relief, and a recrew engineer arrived onsite at 11:10AM-CT. A recrew conductor was already onboard, did not request relief, and was scheduled to operate the train into Chicago Union Station. Head end power was intermittent until the remains were removed from beneath the locomotive, although onboard conditions were reported as comfortable. At 12:26PM-CT, Train 380(07) was released by responding officials and resumed movement to Chicago Union Station.

**National Response Center Number: 1478049**

| Train | Delay | Comment |
|---|---|---|
| 380(07) | 2'26" | |

## *Train 302(07) South of Pontiac, IL - Debris*

07NOV26: At 10:00AM-CT, Train 302(07) E/ID4630 and five cars experienced an undesired emergency 10.2 miles south of Pontiac, IL (MP92.1) on the UPRR Joliet Subdivision after crossing the Chenoa Diamond (MP102.3). The train stopped at MP101.8 due to a brake pipe separation between cafe ID4312 and coach ID4016. The crew encountered difficulties replacing the hose, resulting in additional delay, while head end power was intermittent during the incident. There were no injuries to the crew or the 272 customers onboard, and no damage was reported to the equipment. At 10:15AM-CT, the hose was successfully replaced, air was restored, and Train 302(07) resumed its movement northward.

At 11:33AM-CT, Train 302(07) experienced a second undesired emergency at MP60.3, 13.5 miles north of Dwight, IL (MP73.8). The emergency was caused by the same brake pipe separating due to excessive length. Head end power was intermittent during this time. Once the repairs were completed, Train 302(07) continued toward Chicago at 12:16PM-CT.

| Train | Delay | Comment |
|---|---|---|
| 302(07) | 1'20" | First UDE |
| 302(07) | 48" | Second UDE |

## *Train 6(05) East of Omaha, NE - Freight Train Interference / Broken Rail*

07NOV26: Train 6(05) was delayed beginning 1.8 miles east of Omaha, NE (MP16.7) on the BNSF Omaha and Creston Subdivision while following BNSF 3687 from Gibson (MP14.9) to Plattsmouth (MP5.0). Additional delay was incurred 73.7 miles west of Creston, IA (MP393.1) on the BNSF Creston Subdivision after the train was held at MP466.8 due to a reported broken rail at MP466.4. Maintenance of way forces responded and repaired the defect, and once repairs were completed, Train 6(05) continued operating toward Chicago Union Station.

| Train | Delay | Comment |
|---|---|---|
| 6(05) | 36" | Follow BNSF 3687 |
| 6(05) | 56" | Broken Rail |

27-FOI-00137 00000009131 UNCLASSIFIED 11/10/2026

## Train 390(07) Carbondale, IL - PTC Issues

07NOV26: Train 390(07), E/[illegible]7 cars, was delayed at Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision due to PTC issues. The crew contacted the PTC desk for troubleshooting, and once the system was successfully initialized, Train 390(07) departed Carbondale.

| Train | Delay | Comment |
|---|---|---|
| 390(07) | 40" | |

## Train 5(05) East of Elko, NV - Routing

07NOV26: Train 5(05), E/63-E/145-8 cars, was delayed starting at MP 561.0, 5 miles east of Elko, NV, on the UPRR Lakeside Subdivision due to being routed through Elko yard to on the account of freight traffic on the main line. No yard crews were available to assist with lining switches, additional delay was incurred for UPRR personnel to debrief Train 5(05) crew in operating through 17 rail.

| Train | Delay | Comment |
|---|---|---|
| 5(05) | 58" | |

## Train 3(06) West of Hutchinson, KS - Broken Rail

07NOV26: Train 3(06) was delayed starting 48.5 miles west of Hutchinson, KS (MP218.1), on the BNSF La Junta Subdivision while waiting for Maintenance of Way forces to repair a broken rail at MP283.1. Once released, Train 3(06) was authorized to flag through the affected area from St. John (MP266.6) to Belpre (MP284.1).

Train 4(05) was delayed holding 17.3 miles east of Dodge City, KS (MP352.5) at Spearville (MP335.2) to meet Train 3(06). Additional delay was incurred as Train 4(05) was required to flag through the broken rail territory from Belpre (MP284.1) to St. John (MP266.6).

| Train | Delay | Comment |
|---|---|---|
| 3(06) | 1'22" | |
| 4(05) | 1'03" | Broken Rail |
| 4(05) | 20" | Spearville |

## Train 5(06) West of Lincoln, NE - Signal

07NOV26: Train 5(06) was delayed 71.9 miles west of Lincoln, NE (MP0.8), on the BNSF Hastings Subdivision due to signal issues at Saronville (MP132.9). Operating speeds were restricted through the affected area until the train reached a clear signal at Harvard (MP139.2). Train 6(05) was also delayed operating eastward through the area.

| Train | Delay | Comment |
|---|---|---|
| 5(06) | 36" | |
| 6(05) | 23" | |

## Train 21(06) North of Malvern, AR - Passenger Train Interference

07NOV26: Train 21(06) held 4.2 miles north of Malvern, AR (MP389), on the UPRR Little Rock Subdivision, at Gifford (MP384.8) meting Train 22(06).

| Train | Delay | Comment |
|---|---|---|
| 21(06) | 30" | |

27-FOI-00187 00000009131 "UNCLASSIFIED" 11/10/2026

## *Train 511(06) South of Vancouver, WA - Engine Failure*

07NOV26: Train 511(06) with 340 riders, E/72 with 79 customers, was delayed 1.28 miles south of Vancouver, WA at MP9.02 on the BNSF Fallbridge Subdivision due to a bad air compressor on engine E/72. Head-end power remained active during this event. The crew worked with CNOC mechanical and was unable to resolve, requiring additional power in order to proceed. There were no freights available to be sourced in the area. The Engineer and Conductor were picked up via a northbound passing UP freight train to Vancouver, WA, where they were met by an Amtrak Road Foreman to bring them to Portland and retrieve 509's equipment to rescue the train. The Assistant Conductor remained onboard with 511(06). Once the 509 rescue equipment arrived, it coupled and operated as a double-draft into Portland.

As a result, Train 502(07) is cancelled in entirety, no alternate transportation will be provided due to no available busses. Customers were accommodated on next available services. Train 500(07) will operate as a double-draft with the 511's equipment, in order to bring it to Seattle for needed repairs.

| Train | Delay | Comment |
|---|---|---|
| 502(07) | Cancelled | |
| 511(06) | 2'47" | |
| 500(07) | 02" | PDX- Double-set |

## *Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions*

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

| Train | Delay | Comment |
|---|---|---|

822(29) 32"
821(29) 27"
821(30) 34"
822(30) 30"
822(01) 30"
821(02) 34"
822(02) 29"
822(03) 33"
821(03) 25"
821(04) 35"
822(04) 32"
821(05) 35"
822(05) 26"
821(06) 26"
822(06) 37"
821(07) 35"
822(08) 32"
821(09) 32"
822(09) 36"
822(10) 23"
822(11) 41"
822(12) 48"
821(12) 21"
821(13) 22"
822(13) 36"
821(14) 35"
822(14) 17"
821(15) 26"
821(16) 41"
822(15) 34"
822(16) 19"
821(17) 24"
821(19) 39"
822(19) 22"
821(20) 29"
822(20) 32"
821(21) 46"
821(22) 32"
822(21) 19"
822(22) 30"
821(23) 42"
822(23) 23"
821(24) 21"
822(24) 22"
821(25) 34"
822(25) 43"
821(26) 52"
822(27) 34"
822(26) 21"
821(28) 30"
822(28) 31"
821(29) 23"
822(29) 33"
821(30) 33"
822(30) 22"
821(31) 20"
822(31) 25"
822(01) 30"
821(02) 35"
822(03) 27"
821(04) 37"
822(04) 15"
821(05) 16"
822(05) 24"
822(06) 10"
821(06) 22"

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

# Maintenance of Way Highlights

27-FOI-00187 0000000091134 "UNCLASSIFIED" 11/7/2025

## *Pacific Surfliner and Coast Starlight Service San Luis Obispo, CA to San Diego, CA - Scheduled M/W TW 27-021*

07NOV26: A multi-agency track maintenance project involving North County Transit District (NCTD), Southern California Regional Rail Authority (SCRRA/Metrolink), and Union Pacific Railroad (UP) was conducted between San Luis Obispo, CA, and San Diego, CA. To accommodate the work, the following operating plan was implemented:

Coast Starlight
Train 11 (November 5-7): Terminated at Emeryville, CA with alternate transportation provided between Sacramento and Los Angeles via Gold Runner Services.
Train 14 (November 7-9): Originated at Emeryville, CA with alternate transportation provided between Los Angeles and Martinez via Gold Runner Services.

Pacific Surfliner
Friday, November 6
Train 794(06) Originated in Goleta, CA account of ongoing signal issues and Terminated at Los Angeles, CA account of the scheduled track work. Bus 3594 provided alternate transportation between Los Angeles and San Diego making all stops except San Juan Capistrano
Train 595(06) Canceled in its entirety. Customers were accommodated on Bus 5811.

Saturday, November 7, and Sunday, November 8
All Pacific Surfliner trains were canceled. No alternate transportation was provided.

## *UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Scheduled M/W Work TWA 27-020*

26OCT26:To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 1(31Oct, 7Nov, 14Nov) and Train 42(30Oct, 6Nov, 13Nov) will detour over the BNSF San Bernardino Subdivision between West Colton(UPRR Alhambra subdivision) and Soto( BNSF San Bernardino subdivision), bypassing Ontario, CA (ONA) and Pomona, CA (POS). Train 801(2Nov, 9Nov, 16Nov) was created for the detour between Riverside, CA (RIV) and Los Angeles, CA (LAX).

Train 2/422(1Nov, 8Nov, 15Nov) will detour over the BNSF San Bernardino Subdivision between Soto( BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(1Nov, 8Nov, 15Nov) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV). An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision. No alternate transportation will be provided to POS and ONA.

**WBS#: B.TR.100150.7307**

| Train | Delay | Comment |
|---|---|---|
| 2/422(01) | 39" | |
| 1(31)/421(30) | 44" | |

# Western Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| 11(2) | SLO | 164 | | Main Resevoir |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| 318(7) | BNL | UP4580 | E/4607 shutdown/coolant/oil leaks | CHI | 11/8/26 |
| 7(6) | SPK | BNSF3873 | E/381 master controller faults | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Western Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| Train | Projected Need Cars | Projected Need Seats | Number Operated Cars | Number Operated Seats | Standees | Location |
|---|---|---|---|---|---|---|
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

## Consist Deviations

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 238 (07) | ALB | TRAIN WILL OPERATE WITH AN ALL TABLE CAR IN LIEU OF A COACH CAR. INVENTORY HAS BEEN REDUCED. PLEASE NOTIFY AND REACCOMODATE ALL EFFECTED PAX. | no impact | 0 | 43344 |
| 280 (07) | ALB | 280(07) WILL BE OPERATING 1 COACH SHORT DUE TO FLAT SPOTS, OVERCAPACITY CONDITIONS EXIST. PLEASE SEE WAR REPORT. | -68 fare protect pax | 68 | 82516 |
| 284 (07) | ALB | 284(07) WILL BE OPERATING WITHOUT FOOD SERVICE, OR BUSINESS CLASS DUE TO FLAT SPOTS. OVERCAPACITY CONDITIONS EXIST, PLEASE SEE WAR REPORT. | no jy | 21 | 48195 |
| 236 (08) | ALB | DUE TO SHOPPED EQUIPMENT, 236(08) WILL OPERATE WITHOUT A BUSINESS CLASS. PLEASE SEE WAR REPORT. | NO JY | 16 | |
| 244 (08) | ALB | DUE TO SHOPPED EQUIPMENT, 244(08) WILL OPERATE WITHOUT A BUSINESS CLASS. PLEASE SEE WAR REPORT. | NO JY | 16 | |
| 230 (08) | ALB | 230(08) WILL OPERATE SHORT 1 COACH. INVENTORY HAS BEEN ADJUSTED, WITH NO PAX IMPACT | | | |
| 600 (07) | HAR | TRAIN WILL OPERATE WITHOUT A CAB CAR AND WILL HAVE A EXTRA COACH CAR AND TAIL ENGINE. TRAIN WILL NOT HAVE WIFI. PLEASE NOTIFY ALL EFFECTED PAX. | No impact | 0 | 81511, 665 |
| 235 (07) | NYP | TRAIN WILL OPERATE WITH AN ALL TABLE CAR IN LIEU OF A COACH CAR. INVENTORY HAS BEEN REDUCED. PLEASE NOTIFY AND REACCOMODATE ALL EFFECTED PAX. | no impact | 0 | 43344 |
| 237 (07) | NYP | 237(07) WILL BE OPERATING WITHOUT FOOD SERVICE, OR A BUSINESS CLASS. PLEASE SEE WAR REPORT. | no jy | 6 | |
| 233 (08) | NYP | DUE TO SHOPPED EQUIPMENT, 233(08) WILL OPERATE WITHOUT A BUSINESS CLASS. PLEASE SEE WAR REPORT. | NO JY | 16 | |

27-FOI-00137 00000009131 "UNCLASSIFIED" 11/10/2026

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 243 (08) | NYP | DUE TO SHOPPED EQUIPMENT, 243(08) WILL OPERATE WITHOUT A BUSINESS CLASS. PLEASE SEE WAR REPORT. | NO JY | 5 | |
| 69 (08) | NYP | 69(08) WILL OPERATE SHORT 1 COACH, INVENTORY HAS BEEN ADJUSTED. MINOR OVERCAPACITY CONDITIONS EXIST, PLEASE SEE WAR REPORT. | | | |

**Reverse Consists**

| Train Number | Station | Reason |
|---|---|---|
| 151 (07) | PHL | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 150 (07) | PHL | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 155 (07) | NYP | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 94 (07) | NFK | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 135 (07) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 124 (07) | NPN | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 66 (07) | RNK | Consist reversed \| Business class seat orientation may have changed \| At Front. |
| 94 (08) | NFK | Consist reversed \| Business class seat orientation may have changed \| At Front |