



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, January 20, 2026

Rules: 2-12



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/19/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/19/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	58	80.1%	5,623	680	87.9%	32,928	4,352	86.8%
Central Division	85.5%	66	21	68.2%	1,287	128	90.1%	7,369	795	89.2%
Northeast Division	80.0%	91	10	89.0%	1,803	225	87.5%	10,419	1,506	85.5%
Southeast Division	72.5%	63	10	84.1%	1,253	156	87.5%	7,599	1,033	86.4%
Southwest Division	77.0%	72	17	76.4%	1,280	171	86.6%	7,541	1,018	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00257 00000005638 UNCLASSIFIED 1/22/2026

Endpoint Arrival Dates through 1/19/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	100,798	37,113	63%	1,659,270	323,308	81%	10,954,646	2,359,873	78%
Northeast Corridor	81%	44,197	18,677	58%	726,267	152,899	79%	4,883,108	1,033,863	79%
Acela	83%	7,794	4,201	46%	133,813	43,201	68%	1,017,233	254,229	75%
Northeast Regional	79%	36,403	14,476	60%	592,454	109,698	81%	3,865,875	779,634	80%
Richmond / Newport News / Norfolk	77%	10,872	5,760	47%	183,006	41,584	77%	1,184,307	274,625	77%
Springfield Shuttles	89%	690	67	90%	12,796	1,352	89%	64,469	7,276	89%
Roanoke	79%	2,761	0	100%	46,456	4,313	91%	299,326	47,935	84%
On Spine Northeast Regional	80%	22,080	8,649	61%	350,196	62,449	82%	2,317,773	449,798	81%
State Supported	80%	45,496	14,010	69%	719,407	114,591	84%	4,688,150	876,832	81%
Borealis	60%	511	353	31%	9,149	2,136	77%	63,057	16,014	75%
Capitol Corridor	90%	3,206	1,263	61%	61,664	6,603	89%	381,281	40,363	89%
Carolinian	60%	1,237	342	72%	18,676	4,073	78%	125,906	34,404	73%
Cascades	63%	3,114	465	85%	43,982	7,053	84%	264,501	59,489	78%
Downeaster	82%	1,374	0	100%	24,635	936	96%	159,706	18,641	88%
Empire	78%	5,980	1,296	78%	94,700	14,245	85%	584,374	114,677	80%
Adirondack	72%	384	282	27%	5,874	1,694	71%	36,960	13,230	64%
Ethan Allen Express	70%	662	312	53%	9,516	1,559	84%	64,044	17,757	72%
Maple Leaf	70%	894	493	45%	12,178	5,889	52%	65,074	27,558	58%
New York - Albany	85%	2,633	8	100%	43,619	2,492	94%	268,556	32,675	88%
New York - Niagara Falls	75%	1,407	201	86%	23,513	2,611	89%	149,740	23,457	84%
Gold Runner	73%	3,176	2,316	27%	42,803	14,625	66%	275,642	99,582	64%
Heartland Flyer	65%	170	165	3%	3,118	588	81%	22,757	8,937	61%
Hiawatha	90%	1,259	482	62%	24,453	2,143	91%	183,884	21,712	88%
Illinois	78%	2,544	452	82%	38,547	6,784	82%	262,855	71,951	73%
Carl Sandburg / Illinois Zephyr	85%	483	194	60%	6,715	1,063	84%	45,842	11,366	75%
Illini / Saluki	85%	857	258	70%	12,998	2,065	84%	91,009	23,283	74%
Lincoln Service	70%	1,204	0	100%	18,834	3,656	81%	126,004	37,302	70%
Keystone	92%	5,508	1,296	76%	130,453	10,877	92%	875,173	85,291	90%
Lincoln / Missouri	60%	839	167	80%	11,725	2,635	78%	84,201	37,853	55%
Mardi Gras Service	80%	475	226	52%	7,232	623	91%	47,354	5,349	89%
Michigan	69%	2,267	1,396	38%	31,246	9,197	71%	212,688	64,782	70%
Blue Water	70%	641	614	4%	6,718	2,719	60%	51,315	16,588	68%
Pere Marquette	85%	258	138	47%	3,596	932	74%	28,052	5,240	81%
Wolverine	65%	1,368	644	53%	20,932	5,546	74%	133,321	42,954	68%
Missouri	80%	223	45	80%	3,385	272	92%	25,750	5,370	79%
Pacific Surfliner	85%	9,823	2,955	70%	117,042	24,278	79%	735,010	113,141	85%
Pennsylvanian	72%	965	103	89%	16,138	633	96%	101,794	10,376	90%
Piedmont	73%	1,517	263	83%	18,806	2,721	86%	136,672	30,414	78%
Vermont	75%	1,308	425	68%	21,653	4,169	81%	145,545	38,486	74%
Long Distance	56%	11,105	4,426	60%	206,277	55,818	73%	1,373,001	448,911	67%
Auto Train	57%	672	446	34%	15,711	3,266	79%	79,506	14,026	82%
California Zephyr	50%	1,064	699	34%	18,875	3,856	80%	105,530	28,696	73%
Cardinal	55%	242	94	61%	4,069	1,233	70%	29,574	12,521	58%
City Of New Orleans	75%	638	46	93%	11,119	1,340	88%	76,853	15,771	79%
Coast Starlight	60%	1,009	336	67%	14,427	4,831	67%	124,028	39,559	68%
Crescent	70%	927	18	98%	13,399	1,815	86%	103,561	22,794	78%
Empire Builder	55%	803	433	46%	16,565	7,216	56%	110,441	43,070	61%
Floridian	40%	1,457	871	40%	29,524	13,362	55%	188,872	100,745	47%
Lake Shore Ltd	73%	970	741	24%	16,496	4,188	75%	106,017	23,180	78%
Palmetto	65%	408	0	100%	14,606	1,326	91%	104,283	16,565	84%
Silver Meteor	45%	932	177	81%	16,644	2,876	83%	113,225	33,847	70%
Southwest Chief	40%	626	248	60%	12,950	5,327	59%	89,625	51,509	43%
Sunset Ltd	70%	311	0	100%	4,794	1,071	78%	31,501	7,238	77%
Texas Eagle	50%	1,046	317	70%	17,098	4,111	76%	109,985	39,390	64%
Seasonal Trains	%	0	0	-	7,319	0	100%	10,387	267	97%
Winter Park Express	75%	0	0	-	7,319	0	100%	10,387	267	97%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00257 00000005000 "UNCLASSIFIED" 1/22/2020

Train Index Dates Through January 19, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	94,607	1,987,467	476	622,883	11,847,404	526

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	3,763	565,770	67	24,502	3,447,293	71
INFRASTRUCTURE PLANNED	135	3,433	565,770	61	18,808	3,447,293	55
FLEET RELIABILITY	90	17,341	1,987,467	87	100,621	11,847,404	85
TRAIN OPERATIONS	424	70,070	1,987,467	353	478,952	11,847,404	404

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/19/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/19/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	58	80.1%	5,623	680	87.9%	32,928	4,352	86.8%
Central Division	85.5%	66	21	68.2%	1,287	128	90.1%	7,369	795	89.2%
Northeast Division	80.0%	91	10	89.0%	1,803	225	87.5%	10,419	1,506	85.5%
Southeast Division	72.5%	63	10	84.1%	1,253	156	87.5%	7,599	1,033	86.4%
Southwest Division	77.0%	72	17	76.4%	1,280	171	86.6%	7,541	1,018	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-002 Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/19/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 01/19/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	58	80.1%	5,623	680	87.9%	32,928	4,352	86.8%
Central Division	85.5%	66	21	68.2%	1,287	128	90.1%	7,369	795	89.2%
CDL	90.0%	2	0	100.0%	37	0	100.0%	192	8	95.8%
CHI	85.0%	26	12	53.8%	515	65	87.4%	2,981	344	88.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	11	0	100.0%	17	2	88.2%
EUG	86.5%	2	1	50.0%	38	5	86.8%	216	31	85.6%
GRR	98.0%	1	0	100.0%	18	0	100.0%	109	3	97.2%
KCY	84.5%	2	1	50.0%	37	2	94.6%	218	17	92.2%
MKE	86.5%	6	3	50.0%	111	6	94.6%	648	52	92.0%
MSP	94.0%	1	0	100.0%	18	0	100.0%	110	3	97.3%
PDX	78.0%	5	0	100.0%	93	10	89.2%	554	71	87.2%
PNT	91.5%	3	2	33.3%	57	6	89.5%	275	28	89.8%
PTH	93.0%	1	0	100.0%	19	2	89.5%	110	9	91.8%
QCY	87.5%	2	1	50.0%	38	3	92.1%	222	20	91.0%
SEA	80.0%	8	0	100.0%	150	17	88.7%	881	136	84.6%
SPK	92.0%	1	0	100.0%	20	5	75.0%	115	10	91.3%
STL	88.0%	4	1	75.0%	76	6	92.1%	439	44	90.0%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	38	0	100.0%	217	6	97.2%
WIP	-	-	-	-	11	1	90.9%	17	1	94.1%
Northeast Division	80.0%	91	10	89.0%	1,803	225	87.5%	10,419	1,506	85.5%
ALB	91.5%	8	0	100.0%	152	9	94.1%	767	55	92.8%
BON	43.5%	5	1	80.0%	95	7	92.6%	536	51	90.5%
BOS	86.5%	18	4	77.8%	329	44	86.6%	2,009	253	87.4%
BRK	88.0%	5	0	100.0%	95	5	94.7%	516	25	95.2%
BTN	48.0%	1	0	100.0%	19	3	84.2%	110	21	80.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	37	4	89.2%	213	19	91.1%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	19	4	78.9%	111	21	81.1%
NFL	96.5%	2	0	100.0%	38	0	100.0%	223	8	96.4%
NHV	75.5%	5	0	100.0%	101	17	83.2%	580	98	83.1%
NYP	77.5%	35	4	88.6%	753	125	83.4%	4,381	888	79.7%
SAB	98.0%	1	0	100.0%	19	0	100.0%	109	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	127	3	97.6%	688	27	96.1%
TWO	84.0%	1	0	100.0%	19	4	78.9%	109	23	78.9%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	63	10	84.1%	1,253	156	87.5%	7,599	1,033	86.4%
ATL	-	1	0	100.0%	8	0	100.0%	9	0	100.0%
CLT	92.0%	5	0	100.0%	95	6	93.7%	555	43	92.3%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	7	0	100.0%	194	39	79.9%	1,223	229	81.3%
LOR	69.5%	1	0	100.0%	19	1	94.7%	111	10	91.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/19/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/19/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	292	58	80.1%	5,623	680	87.9%	32,928	4,352	86.8%
Southeast Division	72.5%	63	10	84.1%	1,253	156	87.5%	7,599	1,033	86.4%
MIA	87.5%	2	1	50.0%	38	3	92.1%	222	22	90.1%
MOE	94.0%	2	0	100.0%	38	0	100.0%	222	3	98.6%
NFK	86.0%	2	0	100.0%	46	6	87.0%	304	34	88.8%
NOL	92.0%	4	0	100.0%	75	1	98.7%	482	21	95.6%
NPN	96.0%	2	0	100.0%	38	2	94.7%	197	12	93.9%
PGH	92.0%	1	0	100.0%	19	0	100.0%	111	3	97.3%
PHL	45.0%	4	2	50.0%	85	35	58.8%	508	249	51.0%
RGH	97.0%	4	0	100.0%	76	4	94.7%	440	13	97.0%
RNK	85.5%	2	0	100.0%	38	5	86.8%	221	26	88.2%
RVM	86.0%	-	-	-	11	0	100.0%	113	13	88.5%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	19	0	100.0%	111	2	98.2%
SFA	70.5%	1	0	100.0%	19	3	84.2%	111	6	94.6%
WAS	70.0%	24	7	70.8%	435	51	88.3%	2,652	342	87.1%
Southwest Division	77.0%	72	17	76.4%	1,280	171	86.6%	7,541	1,018	86.5%
ARN	60.5%	1	0	100.0%	18	0	100.0%	110	7	93.6%
BFD	75.5%	6	1	83.3%	118	18	84.7%	670	153	77.2%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	25	4	84.0%	124	40	67.7%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	19	0	100.0%	110	3	97.3%
GTA	72.5%	3	0	100.0%	69	8	88.4%	338	33	90.2%
IRV	-	-	-	-	2	2	0.0%	2	2	0.0%
LAX	77.5%	9	0	100.0%	171	19	88.9%	1,023	111	89.1%
OKC	96.0%	1	0	100.0%	19	0	100.0%	111	3	97.3%
OKJ	79.0%	12	5	58.3%	182	44	75.8%	1,181	286	75.8%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	16	5	68.8%	260	30	88.5%	1,477	159	89.2%
SAN	77.0%	12	3	75.0%	203	21	89.7%	1,260	112	91.1%
SAS	85.0%	1	0	100.0%	20	2	90.0%	112	6	94.6%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	3	57.1%	133	14	89.5%	775	73	90.6%
SLO	62.0%	2	0	100.0%	26	4	84.6%	204	19	90.7%
SNC	-	-	-	-	15	5	66.7%	17	5	70.6%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		8	1	87.5%	48	2	95.8%	8	0	100.0%	48	1	97.9%
3		19	3	84.2%	111	15	86.5%	19	3	84.2%	110	39	64.5%
4		19	3	84.2%	110	17	84.5%	19	8	57.9%	110	67	39.1%
5	138	19	3	84.2%	110	18	83.6%	19	3	84.2%	108	16	85.2%
6	129	19	3	84.2%	109	32	70.6%	19	4	78.9%	109	31	71.6%
7		19	3	84.2%	111	13	88.3%	18	4	77.8%	106	19	82.1%
8	93	19	8	57.9%	111	47	57.7%	18	10	44.4%	110	55	50.0%
11		19	2	89.5%	110	20	81.8%	16	2	87.5%	105	17	83.8%
14		19	4	78.9%	111	14	87.4%	19	6	68.4%	110	27	75.5%
19		19	4	78.9%	111	22	80.2%	19	0	100.0%	111	13	88.3%
20		19	0	100.0%	111	6	94.6%	19	2	89.5%	111	10	91.0%
21		19	0	100.0%	110	13	88.2%	19	1	94.7%	110	19	82.7%
22		19	1	94.7%	111	5	95.5%	19	4	78.9%	110	23	79.1%
23	51	19	0	100.0%	111	3	97.3%	19	3	84.2%	111	16	85.6%
24		19	1	94.7%	111	8	92.8%	19	0	100.0%	111	9	91.9%
25	38	19	0	100.0%	111	0	100.0%	19	4	78.9%	111	14	87.4%
26		19	0	100.0%	111	2	98.2%	19	0	100.0%	111	14	87.4%
27		18	5	72.2%	110	7	93.6%	17	5	70.6%	108	25	76.9%
28	102	17	3	82.4%	108	23	78.7%	17	4	76.5%	108	16	85.2%
40		19	3	84.2%	111	17	84.7%	19	4	78.9%	111	38	65.8%
41	37	19	6	68.4%	111	39	64.9%	19	12	36.8%	111	70	36.9%
42		19	0	100.0%	111	3	97.3%	19	2	89.5%	111	14	87.4%
43		19	3	84.2%	111	11	90.1%	19	0	100.0%	111	4	96.4%
48		19	6	68.4%	111	19	82.9%	19	2	89.5%	111	12	89.2%
49		19	4	78.9%	111	18	83.8%	19	2	89.5%	111	15	86.5%
51	57	8	4	50.0%	48	22	54.2%	9	1	88.9%	47	13	72.3%
52		19	3	84.2%	111	6	94.6%	19	1	94.7%	111	15	86.5%
53		19	1	94.7%	111	10	91.0%	19	3	84.2%	111	16	85.6%
54	67	8	0	100.0%	36	0	100.0%	8	1	87.5%	36	5	86.1%
57		8	0	100.0%	36	1	97.2%	8	0	100.0%	36	1	97.2%
58		19	0	100.0%	110	3	97.3%	19	2	89.5%	109	16	85.3%
59		19	4	78.9%	109	11	89.9%	19	1	94.7%	109	10	90.8%
63		19	11	42.1%	111	50	55.0%	19	8	57.9%	110	56	49.1%
64		19	4	78.9%	110	24	78.2%	19	2	89.5%	110	23	79.1%
65		7	1	85.7%	36	6	83.3%	8	0	100.0%	36	7	80.6%
66		19	3	84.2%	111	16	85.6%	19	1	94.7%	111	20	82.0%
68	42	19	4	78.9%	111	21	81.1%	19	7	63.2%	111	53	52.3%
69		19	1	94.7%	111	12	89.2%	19	1	94.7%	111	14	87.4%
71		19	0	100.0%	111	1	99.1%	19	1	94.7%	111	25	77.5%
72		19	0	100.0%	111	10	91.0%	19	1	94.7%	111	24	78.4%
73		19	2	89.5%	111	5	95.5%	19	8	57.9%	110	52	52.7%
74		19	2	89.5%	111	9	91.9%	19	5	73.7%	111	30	73.0%

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		19	1	94.7%	111	4	96.4%	18	8	55.6%	110	47	57.3%
76	18	19	3	84.2%	111	7	93.7%	16	6	62.5%	108	41	62.0%
77	18	19	1	94.7%	111	5	95.5%	18	4	77.8%	110	35	68.2%
78		19	0	100.0%	111	5	95.5%	19	2	89.5%	111	14	87.4%
79	107	19	0	100.0%	111	21	81.1%	19	2	89.5%	110	17	84.5%
80		19	1	94.7%	111	12	89.2%	19	1	94.7%	110	11	90.0%
87		8	2	75.0%	36	8	77.8%	8	1	87.5%	36	6	83.3%
88	20	8	2	75.0%	36	3	91.7%	8	2	75.0%	36	6	83.3%
89	109	19	3	84.2%	111	21	81.1%	19	3	84.2%	111	18	83.8%
90		19	0	100.0%	111	2	98.2%	19	0	100.0%	111	9	91.9%
96		3	0	100.0%	17	1	94.1%	3	0	100.0%	17	5	70.6%
97		19	10	47.4%	111	51	54.1%	19	1	94.7%	111	20	82.0%
98		18	0	100.0%	110	5	95.5%	18	4	77.8%	110	28	74.5%
99	87	8	2	75.0%	36	4	88.9%	8	5	37.5%	35	17	51.4%
100		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
103		8	2	75.0%	36	5	86.1%	8	1	87.5%	36	2	94.4%
104		3	0	100.0%	15	1	93.3%	3	0	100.0%	15	0	100.0%
105		3	1	66.7%	17	7	58.8%	3	0	100.0%	17	1	94.1%
117	61	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
118		8	0	100.0%	36	2	94.4%	8	1	87.5%	36	3	91.7%
120		3	0	100.0%	17	2	88.2%	3	0	100.0%	17	1	94.1%
121		3	0	100.0%	17	5	70.6%	3	0	100.0%	17	4	76.5%
122		3	2	33.3%	17	6	64.7%	3	0	100.0%	17	2	88.2%
123		4	0	100.0%	18	0	100.0%	4	0	100.0%	18	0	100.0%
124	16	8	0	100.0%	36	2	94.4%	8	1	87.5%	36	5	86.1%
128		8	0	100.0%	36	6	83.3%	7	0	100.0%	35	2	94.3%
132		3	0	100.0%	17	1	94.1%	3	0	100.0%	17	1	94.1%
135	43	8	1	87.5%	36	6	83.3%	8	6	25.0%	36	20	44.4%
140		8	0	100.0%	36	2	94.4%	8	0	100.0%	36	6	83.3%
143		8	0	100.0%	36	2	94.4%	8	0	100.0%	36	3	91.7%
145		3	0	100.0%	17	3	82.4%	3	0	100.0%	17	5	70.6%
146		8	1	87.5%	36	6	83.3%	8	5	37.5%	36	14	61.1%
149	27	3	0	100.0%	17	0	100.0%	3	1	66.7%	17	6	64.7%
150	88	8	3	62.5%	36	25	30.6%	8	5	37.5%	36	24	33.3%
151		19	3	84.2%	111	30	73.0%	19	2	89.5%	110	27	75.5%
153		8	0	100.0%	36	2	94.4%	8	1	87.5%	36	4	88.9%
154		3	0	100.0%	17	2	88.2%	3	1	66.7%	17	10	41.2%
155		8	1	87.5%	36	4	88.9%	8	1	87.5%	36	5	86.1%
156		8	0	100.0%	36	3	91.7%	8	0	100.0%	36	5	86.1%
157	20	3	0	100.0%	17	1	94.1%	3	2	33.3%	17	9	47.1%
158		8	0	100.0%	36	0	100.0%	8	1	87.5%	36	2	94.4%
160		8	0	100.0%	36	0	100.0%	8	3	62.5%	34	7	79.4%

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
161	114	8	2	75.0%	36	3	91.7%	8	7	12.5%	36	22	38.9%
162	23	8	0	100.0%	36	2	94.4%	8	4	50.0%	36	15	58.3%
164		8	0	100.0%	36	4	88.9%	8	2	75.0%	36	11	69.4%
165	54	8	2	75.0%	36	10	72.2%	8	4	50.0%	36	12	66.7%
169	46	8	1	87.5%	36	4	88.9%	7	2	71.4%	35	9	74.3%
189	18	3	1	66.7%	17	6	64.7%	3	2	33.3%	17	8	52.9%
195	98	8	0	100.0%	36	0	100.0%	8	7	12.5%	36	26	27.8%
232		19	0	100.0%	111	2	98.2%	19	0	100.0%	111	6	94.6%
233		19	6	68.4%	111	30	73.0%	19	3	84.2%	111	23	79.3%
234		19	1	94.7%	111	5	95.5%	19	1	94.7%	111	4	96.4%
235		18	2	88.9%	49	7	85.7%	18	2	88.9%	49	8	83.7%
236		19	1	94.7%	111	2	98.2%	19	1	94.7%	111	17	84.7%
237		19	0	100.0%	110	15	86.4%	19	2	89.5%	109	9	91.7%
238		19	3	84.2%	50	9	82.0%	18	1	94.4%	49	4	91.8%
239		19	3	84.2%	110	27	75.5%	19	1	94.7%	110	5	95.5%
240		19	0	100.0%	111	9	91.9%	19	0	100.0%	111	12	89.2%
241		19	1	94.7%	111	25	77.5%	19	0	100.0%	111	14	87.4%
244		19	0	100.0%	111	5	95.5%	19	0	100.0%	111	18	83.8%
245		8	2	75.0%	36	9	75.0%	7	1	85.7%	35	2	94.3%
280		19	0	100.0%	111	4	96.4%	19	2	89.5%	111	19	82.9%
281		19	0	100.0%	111	9	91.9%	19	3	84.2%	111	13	88.3%
283	57	19	3	84.2%	111	23	79.3%	19	3	84.2%	111	18	83.8%
284		19	0	100.0%	111	3	97.3%	19	1	94.7%	110	8	92.7%
290	18	19	3	84.2%	111	22	80.2%	19	2	89.5%	110	33	70.0%
291		19	2	89.5%	111	20	82.0%	19	2	89.5%	111	17	84.7%
300		19	1	94.7%	111	11	90.1%	19	2	89.5%	110	27	75.5%
301		19	0	100.0%	109	2	98.2%	19	1	94.7%	108	17	84.3%
302		19	3	84.2%	108	14	87.0%	19	4	78.9%	106	31	70.8%
305		19	3	84.2%	111	15	86.5%	19	5	73.7%	109	40	63.3%
306		19	0	100.0%	109	6	94.5%	19	2	89.5%	108	22	79.6%
307		19	1	94.7%	110	12	89.1%	19	3	84.2%	109	23	78.9%
311		19	2	89.5%	110	12	89.1%	19	1	94.7%	109	21	80.7%
316		19	2	89.5%	109	7	93.6%	19	0	100.0%	109	18	83.5%
318		18	0	100.0%	110	11	90.0%	18	6	66.7%	109	43	60.6%
319		19	0	100.0%	111	4	96.4%	18	2	88.9%	110	50	54.5%
329	47	12	0	100.0%	76	3	96.1%	12	2	83.3%	76	7	90.8%
330	54	15	0	100.0%	92	2	97.8%	15	1	93.3%	92	6	93.5%
331	60	19	2	89.5%	111	13	88.3%	19	2	89.5%	111	16	85.6%
332	31	19	1	94.7%	111	10	91.0%	19	3	84.2%	111	19	82.9%
334		19	1	94.7%	111	3	97.3%	19	3	84.2%	110	15	86.4%
335	12	19	1	94.7%	111	15	86.5%	19	4	78.9%	109	21	80.7%
336		19	0	100.0%	111	4	96.4%	19	0	100.0%	111	5	95.5%

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
337		19	0	100.0%	111	5	95.5%	19	2	89.5%	111	14	87.4%
338	21	19	4	78.9%	111	25	77.5%	19	5	73.7%	109	27	75.2%
339		19	3	84.2%	111	23	79.3%	19	4	78.9%	111	23	79.3%
342		19	0	100.0%	111	8	92.8%	18	1	94.4%	109	17	84.4%
350	75	19	4	78.9%	93	7	92.5%	19	13	31.6%	93	54	41.9%
351	103	19	2	89.5%	111	15	86.5%	19	2	89.5%	111	40	64.0%
352	69	19	1	94.7%	111	8	92.8%	18	6	66.7%	107	32	70.1%
353		19	0	100.0%	90	5	94.4%	18	1	94.4%	89	17	80.9%
354		19	3	84.2%	111	11	90.1%	18	8	55.6%	108	36	66.7%
355	132	19	4	78.9%	110	13	88.2%	16	5	68.8%	106	30	71.7%
364	16	19	7	63.2%	110	24	78.2%	18	7	61.1%	108	27	75.0%
365	17	19	2	89.5%	110	9	91.8%	19	6	68.4%	109	34	68.8%
370	101	19	4	78.9%	111	9	91.9%	18	5	72.2%	110	21	80.9%
371		18	0	100.0%	109	3	97.2%	18	4	77.8%	109	15	86.2%
380		19	2	89.5%	111	17	84.7%	19	4	78.9%	111	25	77.5%
381		19	1	94.7%	111	3	97.3%	19	0	100.0%	111	11	90.1%
382		19	1	94.7%	111	3	97.3%	19	0	100.0%	111	23	79.3%
383	75	19	2	89.5%	111	11	90.1%	19	4	78.9%	109	40	63.3%
390		19	0	100.0%	95	9	90.5%	19	6	68.4%	94	31	67.0%
391	71	19	0	100.0%	96	2	97.9%	18	4	77.8%	93	19	79.6%
392		18	0	100.0%	110	4	96.4%	18	1	94.4%	109	29	73.4%
393		19	2	89.5%	111	9	91.9%	19	2	89.5%	110	27	75.5%
400		8	0	100.0%	34	2	94.1%	8	0	100.0%	33	1	97.0%
405		8	0	100.0%	32	0	100.0%	8	0	100.0%	32	2	93.8%
409		3	0	100.0%	15	1	93.3%	3	0	100.0%	15	1	93.3%
416		3	1	66.7%	15	2	86.7%	3	0	100.0%	15	1	93.3%
448	123	19	7	63.2%	52	20	61.5%	19	5	73.7%	50	17	66.0%
449		19	1	94.7%	49	2	95.9%	19	0	100.0%	49	5	89.8%
450	34	8	3	62.5%	33	11	66.7%	8	3	62.5%	33	11	66.7%
460		9	5	44.4%	35	17	51.4%	8	4	50.0%	32	11	65.6%
461		8	0	100.0%	35	3	91.4%	8	0	100.0%	35	1	97.1%
464		9	4	55.6%	34	8	76.5%	8	1	87.5%	33	9	72.7%
465		3	0	100.0%	16	0	100.0%	3	0	100.0%	16	0	100.0%
488	18	8	4	50.0%	36	11	69.4%	7	2	71.4%	32	6	81.3%
497		3	0	100.0%	15	0	100.0%	3	0	100.0%	15	0	100.0%
499		8	3	62.5%	33	6	81.8%	7	1	85.7%	32	3	90.6%
500		19	2	89.5%	111	8	92.8%	19	1	94.7%	110	11	90.0%
502		19	2	89.5%	111	9	91.9%	18	2	88.9%	109	23	78.9%
503		19	2	89.5%	108	13	88.0%	19	6	68.4%	107	28	73.8%
504		19	2	89.5%	111	10	91.0%	19	4	78.9%	110	29	73.6%
505		19	4	78.9%	111	20	82.0%	19	3	84.2%	109	20	81.7%
506		19	2	89.5%	110	16	85.5%	19	1	94.7%	109	14	87.2%

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507		19	1	94.7%	111	12	89.2%	19	6	68.4%	111	38	65.8%
508		19	3	84.2%	109	23	78.9%	19	1	94.7%	109	23	78.9%
509		19	1	94.7%	111	8	92.8%	19	2	89.5%	111	27	75.7%
511		19	1	94.7%	111	11	90.1%	19	2	89.5%	111	19	82.9%
516		19	0	100.0%	109	9	91.7%	19	5	73.7%	109	43	60.6%
517		19	0	100.0%	111	2	98.2%	19	3	84.2%	110	34	69.1%
518	102	19	1	94.7%	111	14	87.4%	19	14	26.3%	111	68	38.7%
519	32	19	0	100.0%	109	4	96.3%	19	3	84.2%	109	17	84.4%
520		6	1	83.3%	61	9	85.2%	6	1	83.3%	59	4	93.2%
521		11	2	81.8%	73	2	97.3%	11	2	81.8%	73	6	91.8%
522		11	3	72.7%	73	12	83.6%	11	0	100.0%	72	6	91.7%
523		11	0	100.0%	73	0	100.0%	11	1	90.9%	73	9	87.7%
524		11	0	100.0%	73	2	97.3%	11	1	90.9%	73	5	93.2%
525		11	1	90.9%	72	4	94.4%	10	0	100.0%	70	6	91.4%
526		11	2	81.8%	73	12	83.6%	10	1	90.0%	71	7	90.1%
527	22	11	1	90.9%	73	2	97.3%	11	1	90.9%	73	4	94.5%
528		11	0	100.0%	73	6	91.8%	11	2	81.8%	73	15	79.5%
529		11	1	90.9%	73	5	93.2%	11	1	90.9%	73	14	80.8%
530	172	11	0	100.0%	27	2	92.6%	11	3	72.7%	27	4	85.2%
531		10	2	80.0%	72	3	95.8%	10	0	100.0%	72	6	91.7%
532	102	11	2	81.8%	73	7	90.4%	11	2	81.8%	73	10	86.3%
534	Cncld	4	4	0.0%	59	10	83.1%	3	1	66.7%	58	6	89.7%
535		8	2	75.0%	63	8	87.3%	6	1	83.3%	60	5	91.7%
536	13	11	2	81.8%	73	12	83.6%	11	2	81.8%	71	5	93.0%
537	Cncld	9	0	100.0%	69	5	92.8%	7	1	85.7%	65	3	95.4%
538		11	3	72.7%	73	13	82.2%	11	1	90.9%	73	10	86.3%
539	69	11	2	81.8%	27	4	85.2%	11	7	36.4%	27	16	40.7%
540	17	11	0	100.0%	73	7	90.4%	11	1	90.9%	70	3	95.7%
541		11	2	81.8%	73	10	86.3%	11	0	100.0%	73	15	79.5%
542	34	11	1	90.9%	73	6	91.8%	11	2	81.8%	72	13	81.9%
543	148	11	2	81.8%	73	8	89.0%	11	4	63.6%	73	19	74.0%
544		11	1	90.9%	72	7	90.3%	11	0	100.0%	71	7	90.1%
545	Cncld	11	1	90.9%	73	7	90.4%	10	0	100.0%	71	5	93.0%
547		11	4	63.6%	73	10	86.3%	11	3	72.7%	73	17	76.7%
548		11	2	81.8%	73	12	83.6%	11	0	100.0%	73	6	91.8%
549		11	1	90.9%	70	14	80.0%	11	1	90.9%	67	8	88.1%
550	86	11	2	81.8%	27	5	81.5%	11	3	72.7%	27	5	81.5%
551		11	0	100.0%	70	7	90.0%	11	0	100.0%	68	7	89.7%
562		19	2	89.5%	109	13	88.1%	18	4	77.8%	107	13	87.9%
564		19	0	100.0%	109	9	91.7%	18	1	94.4%	104	13	87.5%
566		19	1	94.7%	109	7	93.6%	19	5	73.7%	106	13	87.7%
572	28	17	1	94.1%	106	8	92.5%	16	5	68.8%	103	23	77.7%

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		19	4	78.9%	109	16	85.3%	18	4	77.8%	106	14	86.8%
577		17	3	82.4%	105	10	90.5%	15	4	73.3%	99	12	87.9%
580		19	2	89.5%	109	4	96.3%	18	1	94.4%	108	10	90.7%
581	27	19	2	89.5%	109	12	89.0%	19	7	63.2%	109	23	78.9%
582		17	4	76.5%	107	10	90.7%	16	1	93.8%	104	8	92.3%
586		19	1	94.7%	109	20	81.7%	18	3	83.3%	103	14	86.4%
587	28	17	0	100.0%	107	5	95.3%	17	5	70.6%	103	16	84.5%
591		19	1	94.7%	109	3	97.2%	19	1	94.7%	108	9	91.7%
593		17	2	88.2%	107	16	85.0%	16	2	87.5%	98	11	88.8%
595		19	3	84.2%	108	22	79.6%	19	4	78.9%	107	18	83.2%
612		3	0	100.0%	17	2	88.2%	3	0	100.0%	17	0	100.0%
615		3	2	33.3%	17	8	52.9%	3	0	100.0%	17	3	82.4%
637		5	0	100.0%	21	2	90.5%	4	0	100.0%	20	2	90.0%
660		8	1	87.5%	36	3	91.7%	8	3	62.5%	36	14	61.1%
661	16	8	0	100.0%	36	3	91.7%	8	4	50.0%	36	10	72.2%
663		8	0	100.0%	36	3	91.7%	8	0	100.0%	36	1	97.2%
664		8	1	87.5%	36	6	83.3%	8	2	75.0%	36	3	91.7%
665	44	8	0	100.0%	36	6	83.3%	8	2	75.0%	36	13	63.9%
666		8	3	62.5%	36	13	63.9%	8	0	100.0%	36	3	91.7%
667	28	8	0	100.0%	36	3	91.7%	8	1	87.5%	36	7	80.6%
669	101	8	1	87.5%	36	3	91.7%	8	4	50.0%	36	14	61.1%
670		8	2	75.0%	36	6	83.3%	8	1	87.5%	36	3	91.7%
671		8	2	75.0%	36	3	91.7%	8	1	87.5%	36	5	86.1%
672		8	1	87.5%	36	4	88.9%	8	2	75.0%	36	4	88.9%
674		8	5	37.5%	36	13	63.9%	8	1	87.5%	36	1	97.2%
680		13	1	92.3%	79	3	96.2%	13	1	92.3%	79	8	89.9%
681		13	0	100.0%	79	3	96.2%	12	3	75.0%	78	22	71.8%
682		13	1	92.3%	79	1	98.7%	13	1	92.3%	79	15	81.0%
683		13	0	100.0%	62	4	93.5%	13	0	100.0%	62	16	74.2%
684		13	1	92.3%	60	10	83.3%	13	1	92.3%	60	15	75.0%
685		13	2	84.6%	77	11	85.7%	13	0	100.0%	77	17	77.9%
686		13	2	84.6%	79	17	78.5%	13	0	100.0%	79	15	81.0%
687		13	2	84.6%	79	11	86.1%	13	1	92.3%	79	12	84.8%
688		13	0	100.0%	79	1	98.7%	13	2	84.6%	79	16	79.7%
699		4	0	100.0%	25	2	92.0%	4	0	100.0%	25	0	100.0%
701		19	0	100.0%	43	6	86.0%	19	1	94.7%	43	3	93.0%
702	23	18	2	88.9%	110	19	82.7%	18	5	72.2%	109	29	73.4%
703		19	5	73.7%	111	29	73.9%	18	5	72.2%	110	29	73.6%
704	52	19	0	100.0%	43	3	93.0%	19	2	89.5%	42	7	83.3%
710	17	19	6	68.4%	111	41	63.1%	19	4	78.9%	111	38	65.8%
711		19	1	94.7%	105	9	91.4%	18	5	72.2%	97	17	82.5%
712	55	19	5	73.7%	111	27	75.7%	18	7	61.1%	108	40	63.0%

Amtrak On Time Performance

Trains Arriving Through: 1/19/2026

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
715	17	19	2	89.5%	111	32	71.2%	19	12	36.8%	104	55	47.1%
716	52	19	7	63.2%	111	47	57.7%	19	7	63.2%	109	48	56.0%
717	18	18	4	77.8%	101	27	73.3%	16	4	75.0%	92	32	65.2%
718		19	7	63.2%	111	46	58.6%	19	4	78.9%	110	33	70.0%
719		19	6	68.4%	111	41	63.1%	17	2	88.2%	107	34	68.2%
761		19	2	89.5%	109	6	94.5%	17	5	70.6%	107	19	82.2%
765		19	5	73.7%	109	13	88.1%	19	2	89.5%	109	19	82.6%
769	51	19	5	73.7%	109	12	89.0%	19	4	78.9%	107	22	79.4%
770		19	2	89.5%	109	12	89.0%	19	7	63.2%	109	21	80.7%
774		19	4	78.9%	109	11	89.9%	19	5	73.7%	108	24	77.8%
779	62	19	1	94.7%	109	5	95.4%	19	7	63.2%	108	25	76.9%
784		19	2	89.5%	109	12	89.0%	19	7	63.2%	108	54	50.0%
785		19	0	100.0%	109	0	100.0%	19	4	78.9%	109	18	83.5%
790		19	1	94.7%	109	7	93.6%	17	1	94.1%	107	12	88.8%
794		19	3	84.2%	109	11	89.9%	19	7	63.2%	108	23	78.7%
821	21	19	0	100.0%	111	3	97.3%	19	4	78.9%	111	50	55.0%
822	22	19	0	100.0%	111	3	97.3%	19	5	73.7%	111	52	53.2%
1333	106	19	3	84.2%	111	13	88.3%	18	6	66.7%	109	42	61.5%
1340		19	0	100.0%	111	3	97.3%	19	3	84.2%	111	25	77.5%
2205		8	1	87.5%	36	4	88.9%	8	1	87.5%	36	3	91.7%
2207		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
2222		3	0	100.0%	17	1	94.1%	3	0	100.0%	17	1	94.1%
2226		3	1	66.7%	16	4	75.0%	3	1	66.7%	16	3	81.3%
2248	71	7	0	100.0%	34	4	88.2%	7	1	85.7%	34	8	76.5%
2250	26	8	1	87.5%	36	4	88.9%	8	3	62.5%	36	14	61.1%
2252		8	1	87.5%	35	4	88.6%	8	1	87.5%	35	5	85.7%
2255	58	7	2	71.4%	35	6	82.9%	7	3	57.1%	35	13	62.9%
2256		2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2257	37	3	0	100.0%	16	0	100.0%	3	2	33.3%	16	6	62.5%
2258	Cncld	3	1	66.7%	17	8	52.9%	2	0	100.0%	16	6	62.5%
2259	17	6	2	66.7%	20	9	55.0%	6	4	33.3%	19	12	36.8%
2265	64	3	0	100.0%	17	0	100.0%	3	2	33.3%	17	8	52.9%
2271	40	6	0	100.0%	20	1	95.0%	6	4	33.3%	20	10	50.0%
2290		3	0	100.0%	16	2	87.5%	3	0	100.0%	16	5	68.8%
2292	25	3	0	100.0%	16	2	87.5%	3	1	66.7%	15	1	93.3%
2295		2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Region: ALL

Service: ALL

Arriving On: 1/19/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2248	BOS	71	CAR	69	CAR	30	PHL-PHL	AM	Door, multiple doors , met by mechanical a/c multiple frozen doors.
2250	BOS	26	PTI	22	DMW	14	STM-XNH	MN	Hold for defect repair Control Point, EAST NORWALK
2255	WAS	58	WTR	43	WTR	24	XPV-BAL	AM	Ice / snow on or under equipment, Control Point, .., activated dragger at mp 83.7 a/c snow and ice build up.
2257	WAS	37	CTI	24	WTR	12	XGX-NHV	AM	Ice / snow on or under equipment, Control Point, XBC, Held at Branford a/c ET ahead clearing ice
2258	XHM	Trn Cancelled							
2259	WAS	17	CAR	25	CAR	15	PVD-PVD	AM	Door, 3361, AM2259 has dp PVD due to the door issue in car 3 and 7. CNDR rpts the gap filler in car 3 had to be pulled in manually. Car 7 will be cut out until NYP
2265	WAS	64	WTR	15	OTH	6	XSH-NYP	AM	Lost time - N.A.R.
2271	WAS	40	WTR	46	WTR	20	RTE-PVD	AM	Ice / snow on or under equipment, Control Point, XHE, CATENARY ISSUES AT XHE
2292	BOS	25	DSR	27	DSR	15	STM-NHV	MN	Per bulletin Control Point, cp241, 15, 4
88	BOS	20	HLD	12	ITI	9	WAS-WAS	AM	Service, turn, or wye train, 117, DELAYED SHORT TURN 117 ARRIVED AT 9:44AM & CONSIST NEEDING WYE.
99	NPN	87	SVS	38	SVS	30	BOS-BOS	AM	Pick up equipment, HELD FOR SWAPPING EQUIPMENT WITH 161
117	WAS	61	SYS	50	SYS	50	PHL-PHL	AM	Conductor working alone/crew shortage., No crew scheduled. Had to find crew.
124	PHL	16	DCS	23	ADA	11	RVM-RVM	CS	Wheelchair 1 lift off and 2 lifts on. One of the scooters went dead on the lift
135	WAS	43	CTI	17	OTH	8	NLC-NHV	AM	Lost time - N.A.R., no additional time lost
149	WAS	27	WTR	33	WTR	19	XPV-BAL	AM	Ice / snow on or under equipment, Control Point, .., following 2255 who activated dragger at mp 83.7 a/c snow and ice build up.
150	BOS	88	PTI	33	SVS	27	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, LATE EQUIPMENT OUT OF THE YARD
157	WAS	20	CTI	32	CTI	9	BRP-STM	MN	Follow MNRR, Control Point, 248-240
161	WAS	114	SVS	86	SVS	56	BOS-BOS	AM	Routine inspections, WENT INTO EMERGENCY AFTER DEPARTING. CREW IS INSPECTING THE CONSIST

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Region: ALL

Service: ALL

Arriving On: 1/19/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
162	BOS	23	OTH	11	DSR	10	STM-BRP	MN	Per bulletin Milepost, 32.3, 33.6, 30, 2, Milepost, 24.6, 24.8, 30, 4, Milepost, 40.4, 41.7, 30, 4, Milepost, 41.7, 42, 15, 4, Control Point, 248, 30, 2
165	WAS	54	CAR	28	CAR	14	WLY-WLY	AM	Onboard HBD alarm, 82623, cndr inspects possible hot bearing c/82623 a/c unable to disable onboard HBD alarm
169	PHL	46	ENG	54	ENG	24	XGX-NLC	AM	HEP, 615, AM169 stopped east of NLC due to E/615 losing main res, train was able to get main res back on E/615
189	WAS	18	CTI	15	CTI	9	BWI-NCR	AM	Follow, MARC, 449, Control Point, ., .
195	WAS	98	DBS	34	DBS	34	PVD-PVD	AM	Debris blocking track (no debris strike), Milepost w/Letters, PACKARD, DAVISVILLE, WIRE DOWN BETWEEN PACKARD AND DAVISVILLE. AM195 OPERATING WITH A FORM D BETWEEN MP 174 - 175
450	SPG	34	CON	32	CON	32	NHV-NHV	AM	Hold for connecting train, HELD FOR CONNECTION WITH AM450
488	GFD	18	FTI	12	FTI	12	SPG-X1X	MA	Meet M427, Control Point, CP98
79	CLT	107	DMW	86	DMW	86	PTB-RMT	CS	Hold for defect repair Other, weldon
661	HAR	16	OTH	8	ENG	4	ARD-ARD	AM	Other electrical failure, 9643, experience penalties at Overbrook.
665	HAR	44	DDA	33	DDA	33	TRE-XHM	AM	HBD - no exceptions, Other, XMO-XGY
667	HAR	28	CAR	17	CAR	17	PHL-PHL	AM	Air / Brake / Wheel, 82988
669	HAR	101	POL	78	POL	78	TRE-TRE	AM	On-train police or DEA activity, HELD A/C CNDR REQUESTED EMS UPON ARRIVAL
68	NYP	42	WTR	54	WTR	54	ALB-ALB	AM	Frozen knuckle Other, alb
283	NFL	57	FTI	65	FTI	42	ROC-BUF	CS	Follow - Follow freight from ROC to CP 429 - Crossover 1 to 2 @ CP 429, M363, Milepost w/Letters, ROC, CP 429
290	NYP	18	CTI	27	CTI	14	POU-CRT	MN	Follow metro, Milepost, 72, 33
448	BOS	71	CTI	57	CTI	38	SPG-WOR	MT	Blocked from station track Keolis, 584, Control Point, 45
76	RGH	18	PTI	11	PTI	7	KAN-GRO	NS	Meet #Am77, Control Point, Sharp
77	CLT	18	FTI	14	FTI	14	HPT-SAL	NS	Cross Traffic 119 was on track 2 south also. I don't believe they were responsible for any of the delay, ns 742, Milepost, 316.5, 324.5
89	SAV	109	DMW	79	DMW	74	PTB-RMT	CS	Held for or routed around MW work or equipment Other, a78.5

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Region: ALL

Service: ALL

Arriving On: 1/19/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
54	SAB	67	CAR	83	CAR	46	BRP-NHV	MN	Air / Brake / Wheel 82751, BOTH TRUKS WERE SMOKING
41	MIA	37	FTI	103	FTI	29	EKH-WTI	NS	Follow ns 12 Q, Milepost, 412, 367
23	NOL	51	FTI	100	FTI	39	BAS-XNO	CS	Follow y105, Milepost w/Letters, paris rd, not junction
25	NOL	38	FTI	70	FTI	39	MOE-PAG	CS	Follow I80120, Siding, orange grove
5	EMY	138	ENG	125	ENG	72	XFJ-XXP	UP	Pick up rescue locomotive due to mechanical failure Add up 7426 at northyard siding Issues initializing PTC, 163
6	CHI	129	FTI	109	WTR	79	GJT-XAC	UP	Broken rail due to cold temps" Hold for defect repair Broken rail MP 434.8, Control Point, Palisade
527	SJC	22	TEN	23	TEN	19	OKJ-OAC	UP	Spalling waiting for advice to proceed or wait for a QMP to confirm movement or not management called and stated for us to highball C2123
530	SAC	172	FTI	172	FTI	160	EMY-EMY	UP	FRT trespasser strike at MP6.5 MTZ sub HLD at EMY for FRT strike at BKY, UP1081, Other, EMY station
532	SAC	102	TRS	104	TRS	99	EMY-EMY	UP	Trespasser strike Milepost, 4.26, 4.50
534	SAC	Trn Cancelled							
536	SAC	13	MBO	19	MBO	19	MTZ-SUI	UP	For maritime traffic Control Point, vista
537	OKJ	Trn Cancelled	PTI	4	PTI	4	SUI-MTZ	UP	Wait for station track 712, Control Point, MTZ M1
539	SJC	69	TRS	69	TRS	58	RIC-RIC	UP	Trespasser strike Held at RIC for TRS at BKY., Other, BKY
540	SAC	17	MBO	27	MBO	27	MTZ-SUI	UP	For maritime traffic Control Point, rv032
542	SAC	34	TCR	29	TCR	29	FMT-HAY	UP	Electrical failure C8810, Exterior cable behind HEP housing on Cafe Car CDTX 8810 came loose south of Hayward, dragged on the tracks and frayed out causing an MU failure and loss of HEP and traction. Car was short looped around the damaged area.
543	SJC	148	ITI	142	ITI	142	SAC-SAC	UP	Service, turn, or wye train 530, Delayed due to fatality at BKY
545	OKJ	Trn Cancelled							
550	SAC	86	ITI	85	ITI	85	SJC-SJC	UP	Service, turn, or wye train 543, Late turn from 543 due to late 530.

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Region: ALL

Service: ALL

Arriving On: 1/19/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
51	CHI	57	FTI	85	FTI	66	IND-CRF	CS	Follow 640, Control Point, Hunt, Control Point, Clermont	
518	VAC	102	FTI	104	FTI	65	BEL-X8B	BN	Meet BNSF 5401, Control Point, North Swift	
519	SEA	32	PTI	17	PTI	17	MVW-STW	BN	Cross over or go around Pulled in behind a freight in the siding and backed out, 518, Siding, S MVW	
8	CHI	55	FTI	139	FTI	79	WPT-WTN	BN	Meet bn 7075, bn 9311, Siding, baineville	
28	SPK	102	ENG	131	ENG	131	PDX-PDX	BN	Set out defective locomotive Amtk 350 bad order. Add Amtk 343 from train 14., 343	
821	FTW	21	DSR	44	DSR	27	GLE-FTW	BN	Per bulletin Milepost, 407.7, 407.3, 50, MT, Milepost, 405.6, 405.0, 50, MT, Milepost, 404.4, 403.9, 50, MT, Milepost, 403.4, 403.0, 50, MT, Milepost, 401.6, 401.5, 10, MT, Milepost, 399.6, 399.2, 50, MT, Milepost, 397.8, 397.4, 50, MT, Milepost, 396.3, 396.2, 60, MT, Milepost, 395.6, 395.5, 50, MT,	
822	OKC	22	DSR	28	DSR	19	FTW-GLE	BN	Per bulletin Milepost, 346.8, 347.4, 29, main 1, Milepost, 350.0, 350.5, 50, main 1, Milepost, 353.4, 353.8, 50, main 1, Milepost, 354.0, 354.5, 70, main 1, Milepost, 355.2, 355.9, 50, main 1, Milepost, 355.6, 355.8, 40, main 2, Milepost, 362.3, 362.7, 30, main 2, Milepost, 364.4, 364.8, 50, main 2,	
329	MKE	47	DCS	45	DCS	31	MKA-MKE	CP	Power switch failure Had to hand-line both switches at KK, locks were frozen on both., Control Point, KK	
330	CHI	54	CTI	34	DCS	21	MKE-MKA	CP	Power switch failure CPKC Dispatcher gave permission past stop signal MT1-MT1, hand lining our route, R/S, Control Point, Kinnickinnic bridge 83.4	
331	MKE	60	CAR	27	CAR	27	CHI-CHI	AM	Door ID4007, 9:01 passengers all boarded, waiting on Mech. Dept. No door light 9:06 mech. dept. blue flagged 9:17 blue flags down	
332	CHI	31	SYS	27	SYS	27	MKE-MKE	CP	Re-crew / job briefing ASAP call sign up was 8:05	
335	MKE	12	PTI	10	PTI	8	GLN-XRO	ME	Follow All Westbound trains being routed around broken rail on MT1, A1333, Milepost, 17.4, 32.3	
338	CHI	21	CAR	15	CAR	15	MKE-MKE	CP	Door ID4131, Stairs not working in multiple doors limiting detaining. Doors/stairs need repairing.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Region: ALL

Service: ALL

Arriving On: 1/19/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
350	PNT	75	WTR	57	WTR	49	CHI-CHI	AM	Frozen plungers and frozen steps Other, CUS	
351	CHI	103	SYS	61	SYS	38	DER-ARB	MI	PTC problem or failure (cause unknown) Received a C260054 code. ITcs went dead. Rebooted . Still said target yard zero. Instructions to cut out ITcs.....run 595 (59 mph)	
352	PNT	69	DMW	75	DMW	75	ARB-DER	MI	Waiting for MW clearance Control Point, 25	
355	CHI	132	DCS	67	DCS	67	DER-ARB	MI	Power switch failure Wait for maintainers to arrive and repair switch., Control Point, 25	
364	PTH	16	WTR	39	WTR	30	CHI-CHI	AM	Ice / snow on or under equipment IDTX 4607 WINDSHIELD AND MIRRORS ICED OVER., Other, CHICAGO UNION STATION	
365	CHI	17	PTI	16	PTI	12	LNS-BTL	CC	Wait for station track Stop at Rose waiting on 351 to depart BTL, 351, Control Point, Rose	
370	GRR	101	DCS	82	DCS	80	XTF-XH6	NS	Power switch failure Control Point, 518	
572	SAN	28	CTI	12	PTI	9	X98-OSD	SN	Meet amtk 577, Control Point, eastbrook	
581	LAX	27	CTI	14	CTI	11	SOL-OSD	SN	Meet coaster, Control Point, swami	
587	LAX	28	PTI	23	PTI	14	OSD-X98	SC	Meet Stop signal at Songs, amtk 784, Control Point, songs	
769	GTA	51	CTI	34	CAR	17	SAN-SAN	SN	Air / Brake / Wheel 6407, 6406, Troubleshooting main reservoir leakage.	
779	SLO	62	CTI	46	CTI	20	SOL-OSD	SN	Meet coaster, 638, Control Point, swami	
702	BFD	23	FTI	36	FTI	21	MDR-FNO	BN	Follow Followed BNSF 6402 Eastbound into Fresno after mainline crew change, BNSF 6402, Control Point, E. Gregg, Other, Fresno Station	
704	BFD	52	DBS	34	DBS	34	XEC-LOD	UP	Debris strike Struck a big pile of rocks at mp 51.33. The area was extremely foggy thought that it could have been a person. Conductor went back to investigate., Pile of rocks, Milepost, 51.33, 51.33	
710	BFD	17	FTI	18	FTI	10	MCD-MDR	BN	Meet BNSF 7964, Siding, Sharon	
712	BFD	55	TEN	53	TEN	53	OKJ-EMY	UP	HEP C2104	
715	OKJ	17	RTE	20	RTE	20	WAC-COC	BN	Dispatcher hold Held at Angiola 702 was running late, but I cannot justify a 20 minute delay on PTI, Siding, Angiola	
716	BFD	52	POL	35	POL	15	OKJ-EMY	UP	RR blocked by trespasser or vehicle strike by another train	

Amtrak Endpoint OTP Details

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/19/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
717	OKJ	18	DSR	14	FTI	10	WAC-COC	BN	Meet bnsf 4730, Control Point, west allensworth
383	QCY	75	FTI	35	FTI	32	GBB-MAC	BN	Meet There was nothing on New Long 1 or 2, could've routed us around freight train that was on MT 2 (Quincy Main) Knox-Waterman, CN 5627, Control Point, Knox
391	CDL	71	DCS	59	DCS	59	X9R-XCS	CT	Power switch failure Control Point, 21st street
1333	MSP	106	CAR	48	CAR	48	CHI-CHI	AM	Toilet 34094, Mechanical flushing toilets. Ending up taking car out of service

Amtrak Initial Terminal Details

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/19/2026

Terminal	Train	Date	Late	Delay	Cause
MIA	40	01/19	34	34	PTC system failure PTC not configuring w/ SFRTA. Contacted PTC support. SFRTA PTC system failure, authorized to proceed without PTC., Other, MIA
PHL	117	01/19	50	50	Conductor working alone/crew shortage., No crew scheduled. Had to find crew.
PHL	150	01/19	27	27	Planned set out / pick out of locomotives, cars or section of train, LATE EQUIPMENT OUT OF THE YARD
WAS	88	01/19	9	9	Service, turn, or wye train, 117, DELAYED SHORT TURN 117 ARRIVED AT 9:44AM & CONSIST NEEDING WYE.
WAS	122	01/19	1		
WAS	146	01/19	4	4	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE
WAS	166	01/19	23	23	Service, turn, or wye train, 195, DELAYED SHORT TURN 195 ARRIVED AT 4:03PM & MOTOR NEEDING WYE.
WAS	2228	01/19	31	31	Service, turn, or wye train, 2255
WAS	2252	01/19	1		
WAS	2258	01/19	(Trn Cxld)		Equipment Issues
BON	689	01/19	2	2	Cross Traffic keolisKeolis, inbound, Other, Boston
BOS	87	01/19	18	18	Delay in Block, DELAYED DUE TO TERMINAL CONGESTION
BOS	99	01/19	48	12	HEP, 670, HELD DUE TO DEAD ENG
BOS	99	01/19	48	8	Planned Switch, Departed BOS and stopped AT XT1 with a trailing unit fault. Backing into the station and will swap equipment with 161
BOS	99	01/19	48	30	Pick up equipment, HELD FOR SWAPPING EQUIPMENT WITH 161
BOS	161	01/19	86	56	Routine inspections, WENT INTO EMERGENCY AFTER DEPARTING. CREW IS INSPECTING THE CONSIST
BOS	161	01/19	86	30	Routine inspections, Crew is inspecting the consist
BOS	2259	01/19	4	4	Other late crew, Held waiting on mech personnel to board and ride
GFD	499	01/19	5	5	Late 488 arrival causing late departure 488
NYP	43	01/19	9	9	Snow removal equipment working ahead, Other, NYP, HELD SINGLETRACKING A/C ICE PATROL IN SOUTH TUBE
NYP	49	01/19	10	10	Hold for connecting train, HELD FOR PSNGRS OFF AM161
NYP	63	01/19	9	9	Hold for connecting train, HELD F/PSGRS OFF LATE AM150
NYP	105	01/19	5	5	Door, 00000, UNSPECIFIED DOOR ISSUE
CHI	3	01/19	125	125	Toilet 31040
CHI	5	01/19	216	90	Waited for train 51's road power to use for train 5 175, 78
CHI	5	01/19	216	126	Ice / snow on or under equipment Control Point, CUS

Amtrak Initial Terminal Details

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/19/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	41	01/19	82	35	Planned set out / pick out of locomotives, cars or section of train Late pulled down from the yard., Other, CUS
CHI	41	01/19	82	47	Door 62511, Door panel would not shut, mechanical came to train side and fixed it.
CHI	59	01/19	2	2	Excessive carry-on luggage by college students
CHI	331	01/19	53	27	Door ID4007, 9:01 passengers all boarded, waiting on Mech. Dept. No door light 9:06 mech. dept. blue flagged 9:17 blue flags down
CHI	331	01/19	53	26	Service, turn, or wye train 330, Arrival 8:51
CHI	339	01/19	5	5	Service, turn, or wye train 338
CHI	350	01/19	49	49	Frozen plungers and frozen steps Other, CUS
CHI	354	01/19	31	31	Issue with the sander, waiting on a mechanical assessment ID4623
CHI	364	01/19	30	30	Ice / snow on or under equipment IDTX 4607 WINDSHIELD AND MIRRORS ICED OVER., Other, CHICAGO UNION STATION
CHI	383	01/19	31	31	Freezer started spewing water, mechanical was unable to fix it at this time. Waited for OBS to bring us towels to soak up the water and hopefully keep the rest of the water from coming out into the rest of the cafe. ID 4311. Coded WTR per Control Center Other, CUS
CHI	393	01/19	4	4	Planned Switch
CHI	1333	01/19	99	48	Toilet 34094, Mechanical flushing toilets. Ending up taking car out of service
CHI	1333	01/19	99	20	Set out defective locomotive Set out the AMTK 168 and replaced it with the AMTK 194, 194
CHI	1333	01/19	99	31	Service, turn, or wye train 332
EUG	508	01/19	1	1	Platform construction. Passenger brought to train 1 minute.
KCY	316	01/19	1	1	Dispatcher hold Wait for light to exit station, Control Point, Grand
MKE	332	01/19	27	27	Re-crew / job briefing ASAP call sign up was 8:05
MKE	334	01/19	2	2	Fuel Fueled up to departure time, face to face with fuel vendor, pulled hose and in the clear, Milepost, 85.4, 85.4
MKE	338	01/19	15	15	Door ID4131, Stairs not working in multiple doors limiting detaining. Doors/stairs need repairing.
PNT	351	01/19	5	5	Low temperatures had all bathroom sinks froze. Mechanical working on unthawing sinks Other, pontiac station/mechanical
PNT	355	01/19	50	50	Service, turn, or wye train 350, Late inbound AMT 350. Engine needed wye upon arrival into PNT.
QCY	382	01/19	2	2	Door ID4113, ID4205, Door operator showed door open but yellow light was off. Stopped to verify all doors and stairs closed.
STL	311	01/19	22	22	Loading problem ID4626

Amtrak Initial Terminal Details

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/19/2026

Terminal	Train	Date	Late	Delay	Cause
BFD	703	01/19	2	2	Passenger and/or baggage
OKJ	526	01/19	3	3	Restrictive signal(s) from unknown cause Possibly related to the arrival of Train 11 several minutes earlier., Stop, Control Point, North Jack London
OKJ	534	01/19	(Trn Cxld)		Trespasser Strike
OKJ	536	01/19	2	2	Met amt 537 at north jack London due to trespasser strike and trains arriving into jack London late. Control Point, north jacklondon
OKJ	548	01/19	6	6	Service, turn, or wye train 545, Train 545 was annulled. Deadheaded to Oakland Yard on 543. Pulled new set out of yard to OKJ.
OKJ	716	01/19	4	4	RR blocked by trespasser or vehicle strike by another train
SAC	525	01/19	6	6	Signal in time Switch was lined for Train 11 to spot for fuel., Control Point, Sacramento
SAC	543	01/19	142	142	Service, turn, or wye train 530, Delayed due to fatality at BKY
SAC	545	01/19	(Trn Cxld)		Trespasser Strike
SAC	547	01/19	1	1	Loading problem Locomotive would not load upon departure of SAC., C2102
SAC	549	01/19	6	6	Hold for thruway bus
SAN	573	01/19	1		
SAN	761	01/19	1	1	Wait for scheduled departure time Departed ON TIME (wheels turning!!!) at 4:01 AM (Apparently GPS was "asleep at the switch...?")
SAN	769	01/19	17	17	Air / Brake / Wheel 6407, 6406, Troubleshooting main reservoir leakage.
SJC	538	01/19	1		
SJC	542	01/19	12	12	Late Deadhead 539, Crew deadheaded in on late Amtrak 539 due to residual congestion from a freight trespasser strike at BKY Depot.
SJC	550	01/19	85	85	Service, turn, or wye train 543, Late turn from 543 due to late 530.

Eastern Region

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	96.2	99.2	94.8	340	13
CDOT	95.0	100.0	92.5	92.4	13	0
MARC	95.0	87.9	92.5	90.2	33	4
SEPTA	95.0	97.3	96.8	91.5	110	3
NJT-NED	95.0	94.9	92.1	93.8	217	11
NJT-SED	95.0	100.0	99.8	97.2	24	0

Operating Highlights

Train 2192(20) New York, NY - Car Failure

20JAN26: Train 2192(20) with PC/2007-2028 was cancelled between New York and Boston due to TS 15 with wheel defects related to a high KIPS reading. Passengers were accommodated on the next available services.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2192(20)	Cancelled	NYP-BOS

Train 52(19) South of Florence, SC - Freight Train Interference

20JAN26: Train 52(19) was delayed on the CSX Charleston subdivision 13 miles south of Florence at New Hope/MP 306.0 due to meeting I137-19.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(19)	40"	

Train 283(19) West of Rochester, NY - Freight Train Interference

19JAN26: Train 283(19) was delayed on the CSX Rochester and Buffalo Terminal subdivisions following M363 between Rochester/MP 371.1 and CP 429.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
283(19)	42"	

Train 448(18) West of Worcester, MA - Commuter Train Interference

19JAN26: Train 448(18) was delayed one mile west of Worcester on the CSX Boston subdivision due to meeting Y210-19 at CP 45/MP 44.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
448(18)	38"	

Amtrak Philadelphia to Washington Main Line North of Baltimore, MD - Defect Detector Actuation

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

19JAN26: Train 2255(19) was delayed on the Amtrak Philadelphia to Washington Main Line 13 miles north of Baltimore due to actuating the DED on 3 track at MP 83.4. The crew inspected, found snow and ice build up, and continued to Baltimore. Soon after, it was reported that the DED on 3 track at MP 83.4 was stuck down and preventing the home signal at River/MP 89.3 from being displayed. Trains received Rule 241 permission to operate through River during this time. The DED livened with signal display. Maintainers responded and inspected the DED with no exceptions reported. Train 2255(19) was further delayed for actuating an additional DED on 3 track at MP 116.4. The crew inspected, found snow and ice build up, and continued to Washington. As a result, train 2228(19) was delayed departing Washington due to the late turn of equipment from 2255(19). Train 2228(19) departed Washington at 936PM-ET, 31 minutes late.

Train	Delay	Comment
2255(19)	24"	MP 83.4
2255(19)	11"	MP 116.4
149(19)	19"	MP 83.4
149(19)	09"	MP 116.4
2228(19)	31"	WAS - ITD

Train 49/449(19) Albany-Rensselaer, NY - Servicing

19JAN26: Train 49/449(19) was delayed departing Albany on the Amtrak Hudson Line due to late outbound engines from the shop. Once the train was made up and the passengers were onboard, 49/449(19) departed Albany at 738PM-ET, 33 minutes late.

Train	Delay	Comment
49/449(19)	33"	

Train 669(19) Trenton, NJ - Injured or Sick Passenger or Employee

19JAN26: Train 669(19) was delayed on the Amtrak New York to Philadelphia Main Line at Trenton/MP 56.7 due to the engineer requesting EMS for a medical emergency. The engineer was taken by EMS to Capital Health Hospital in Trenton to be assessed. An Amtrak road foreman responded to the scene and a replacement engineer arrived on scene, taking control of the train at Trenton. Train 669(19) departed Trenton at 741PM-ET, 1 hour, and 33 minutes late.

Train	Delay	Comment
669(19)	1'20"	

Train 25(19) East of Pascagoula, MS - Freight Train Interference

19JAN26: Train 25(19) was delayed on the CSX NO&M subdivision seven miles east of Pascagoula at Orange Grove/MP 701.1 due to meeting I80120.

Train	Delay	Comment
25(19)	39"	

Train 64/68(19) Albany-Rensselaer, NY - Servicing

19JAN26: Train 64/68(19) was delayed departing Albany on the Amtrak Hudson Line due to frozen knuckles and unable to make the hook. Mechanical utilized a torch to melt the knuckles and put the train together. Once the train was together and the passengers were onboard, 64/68(19) departed Albany at 831PM-ET, 51 minutes late.

Train	Delay	Comment
64/68(19)	51"	

Train 52(19) North of Palatka, FL - Engine Failure

19JAN26: Train 52(19) with E/357 and 834 "UNCLASSIFIED" cars was delayed on the CSX Sanford subdivision three miles north of Palatka due to E/357 going into an undesired emergency with a loss of air. The air quickly restored on its own. The conductor walked the train, reported no exceptions, and 52(19) continued north.

Train	Delay	Comment
52(19)	39"	

CSX North End Subdivision North of Rocky Mount, NC - M of W Work

19JAN26: Trains were delayed on the CSX North End subdivision 36 miles north of Rocky Mount due to a broken rail reported by a track inspector at MP 82.9. Due to the significance of the break, trains were unable to be walked over the affected area. CSX MOW responded to the scene, made repairs, and train movement continued. Train 79(19) was delayed holding at MP 81.5 and train 89(19) was delayed holding at MP 81.8 until repairs were complete.

Train	Delay	Comment
79(19)	1'26"	
89(19)	1'14"	

Train 165(19) Westerly, RI - Car Failure

19JAN26: Train 165(19) with E/645 and 9 cars was stopped at Westerly station/MP 141.1 on the Amtrak New Haven to Boston Main Line due to a consistent hot journal alarm in C/82623. The crew worked with CNOC Mechanical and the Amtrak Road Foreman. The crew inspected the equipment, took no exceptions, and were capped at 80 mph to New Haven. At New Haven, mechanical met the train and identified an electrical short with a potential circuit breaker issue that was tripping the hot journal alarm. New Haven mechanical confirmed no exceptions to the hot journal alarm. Train 165(19) departed New Haven at 620PM-ET, 45 minutes late. There was no HVAC in C/82623 due to the electrical issues. The conductor reported the passengers were comfortable and on board ambient temperature slowly dropped into New York. Inventory was reduced and the train was over capacity by two passengers at Newark Liberty Airport, where both passengers were accommodated in business class.

Train	Delay	Comment
165(19)	14"	WLY
165(19)	12"	NHV

Train 2258(19) Cancelled - Washington, DC - Wheels/Car Failure

19JAN26: Next Gen 2258(19) with PC/2117 and PC/2116 was cancelled in its entirety due to wheel kip readings on set 11.

Train	Delay	Comment
2258(19)	CANCELLED	

Train 665(19) West of Trenton, NJ - Defect Detector Actuation

19JAN26: Train 665(19) was stopped on track 3 east of MP 65.3/Grundy to inspect the train account actuating a dragging detector at MP 62.5. They stopped again on track 3 just east of MP 77.2/Holmes to inspect the train again due to actuating a dragging detector. They took no exceptions and proceeded west.

Train	Delay	Comment
665(19)	33"	

Train 54(19) East of Bridgeport, CT - Car Failure

19JAN26: Train 54(19) 28-FOI-00257/600900056380 was UNCLASSIFIED on 1/22/2026 New Haven Line at MP 61.3 on track 4 due to reports of smoke coming from C/82751. The crew was inspecting and found a stuck parking brake on C/82751. They released the brake and performed a roll by. The passengers were moved out of the car due to lingering smoke conditions. Once the train arrived in New Haven they removed the C/82751.

Train	Delay	Comment
54(19)	20"	
54(19)	37"	NHV

Train 23(19) South of Mobile, AL - Freight Train Interference

19JAN26: Train 23(19) was delayed on the CSX NO and M subdivision due to following CSX I801 from Mobile to Biloxi. Then they were further delayed due to following CSX Y105 on the CSX NO and M subdivision from MP 801.1 to the New Orleans Terminal.

Train	Delay	Comment
23(19)	49"	CSX I801
23(19)	39"	CSX Y105

Train 40(19) Miami, FL - SFTRA PTC Issues/System

19JAN26: Train 40(19) was delayed departing Miami due to having issues initializing PTC on the SFRTA. The train was further delayed due to the PTC map not displaying for CSX Territory at SE Dyer. CSX instructed to engage at restricted mode onto the territory to display the map.

Train	Delay	Comment
40(19)	34"	
40(19)	28"	CSX

Train 2248(19) Philadelphia, PA - Car Failure

19JAN26: Next Gen 2248(19) with PC/2122, PC/2129 was delayed in Philadelphia due to having door issues between the 7th C/3703 and 8th C/3704 where the door will not open. Philadelphia mechanical was not able to fix the issue. Passengers were moved to the rear of the trains set. There was mechanical rider that boarded the train and was attempting to fix the problem enroute. New York High Speed mechanical will meet the train upon arrival. There was also two bathrooms that were locked out on the set.

UPDATE: High Speed tech was able to get the door open between C/3703 and C/3704.

Train	Delay	Comment
2248(19)	12"	BWI DOOR C/O 3702
2248(19)	30"	PHL DOOR 3704,3703
2248(19)	21"	NYP DOORS/TOILETS

Train 53(18) South of DeLand, FL - Commuter Train Interference

19JAN26: Train 53(18) was delayed on the CFRC Orlando subdivision at MP 765.0 due to meeting CFRC P306 and P310.

Train	Delay	Comment
53(18)	44"	

Train 450(19) New Haven, CT - Hold for Connection

19JAN26: Train 450(19) was delayed departing New Haven due to holding for connections off late train 150(19) that arrived at 919A-ET 37 minutes late.

Train	Delay	Comment
450(19)	32"	

Train 99(19) Boston, MA - Engine Failure

19JAN26: Train 99(19) was delayed departing Boston due to E/670 having issues getting power set up between E/670 and E/620. Due to this it was decided to swap sets of equipment with train 161(19). After swapping sets they were able to depart.

Train 161(19) was also delayed due to same set up issues between E/670 and E/620. The train was able to depart at 1036A-ET, 56 minutes late but went into emergency at Tower 1 due to a set up issue between the engines. They did reverse back into the Boston station where mechanical met the train and was able to correct the problem. The train departed Boston for a second time at 1106A-ET 1 hour 26 minutes late. Train 87(19) was also delayed due to station congestion.

There were a total of eight missed passenger connections at Washington from train 161(19); two missed connections to 19(19), three missed connections to 87(19), and three missed connections to 97(19), who were all housed in Washington overnight.

WBS#: B.TR.100151.0800

Train	Delay	Comment
99(19)	48"	
87(19)	18"	
161(19)	1'26"	

19JAN26: At 230A-ET, 26-FOI-00257n 00000005638 report of communication loss at MP 198.1/Holden Interlocking. As of 317A-ET C&S arrived on scene at MP 213.9/Junction, MP 198.1/Holden and MP 204.0/Mansfield. As of 353A-ET, C&S reported that the 21SW at MP 198.1/Mansfield was OK for use in the normal position only. The CSX L005 was tied down on the Framingham secondary at Mansfield due to the switch issue. As of 401A-ET, C&S reported they cleared snow from the switch points at MP 213.9/Junction and all switches were OK for normal service. As of 353A-ET, The trees were cleared between MP 198.1/Holden and MP 213.9/Junction with Overhead Catenary power holding on track 1. The 31SW was stuck in reverse at MP 198.1/Holden with communication loss. C&S was still on scene at MP 198.1/Holden. As of 436A-ET, Track Foreman returned track 3 to service between MP 218.5/Transfer and MP 219.6/Read. Corridor dispatcher reported a TOL on track 3 and C&S was on scene. As of 511A-ET, C&S reported that the switches at MP 198.1/Holden were going to need to be spiked and clamped in the position of use and inspected after each move.

At 811A-ET, Power Director restored Overhead Catenary power but also reported Warwick RI Fire Department was on scene between MP 175.0/Packard and MP 168.0/Davisville for the report of city wire down. Train 195(19) operated with a Form D between MP 174.0-175.0. As of 823A-ET, ET was on scene at MP 174.8 on track 2 and reported no wire down just snow and tree on top of wire and crews were working to remove it.

At 905A-ET, South County dispatcher reported that the 21SW at MP 168.0/Davisville would not reverse. As of 951A-ET, South County Dispatcher reported that crew were waiting on a bucket truck to remove the tree at MP 174.8 and a plate order was in effect on track 2 between MP 168.0/Davisville and MP 181.2/Cranston.

As of 930A-ET, Holden is OK and back to normal.

As of 405P-ET, Shoreline dispatcher reported that 135(19) lost overhead power at MP 88.8/Guilford on track 1 momentarily. Zone 10 reported between MP 75.2/Shoreline Junction and MP 81.5/Branford was having multiple tripping's. As 408P-ET, ET arrived on scene and needed foul time on both tracks between MP 75.2/Shoreline Junction and MP 81.5/Branford to knock down ice build up.

Train	Delay	Comment
3 MBTA	37"-1'11"	
2271(19)	26"	
195(19)	57"	
2257(19)	06"	
166(19)	23"	WAS - ITD, late turn equip 195(19)

Train 117(19) Philadelphia, PA - No Crew/Miscellaneous Amtrak Responsible

19JAN26: Train 117(19) was delayed departing Philadelphia due to no crew for train at departure time. The protect crew that signed up at 7A-ET took the train from Philadelphia to Washington.

Train	Delay	Comment
117(19)	50"	

15JAN26: Weekend Outages on the New Haven Line:

- Continuous outage- No.3trk CP 217 to CP 223 Started 1/9 OOS for 3 weeks.
- Continuous outage- No. 3trk CP 217 interlocking replace timbers 13B sw. Started 1/9
- No.1trk CP 217 to CP 223 Repair Fenimore Bridge Deck Start 11:30P Friday 1/16 to 5A Sunday 1/18.
- No.4trk CP 233 to CP 234 Atlantic St. contractor 820AM Saturday 1/17 to 6P Saturday 1/17. No Access to 4trk in Stamford during outage.
- Continuous outage No.2trk CP 255 to CP 257 to replace rail. Started on 1/9 will be return to service on Friday 1/16.
- No.1trk CP 257 to CP 261 to Replace Rail. Will go OOS when 2trk CP 255 to CP 257 returns. Rule 22 will be on track 3.
- No. 3trk CP 266 to CP 271 Rebuild track 5 West Haven Lumber. Begins 12AM Saturday 1/17 to 5P Sunday 1/18. Rule 22 will be on No.1trk.
- No. 1trk CP 255 to CP 261 for Potweld. Both Saturday and Sunday 8A to 4P.

Crescent NS Gulf Division TW - Scheduled M/W Work

10OCT25: To accommodate the above outlined infrastructure work, Amtrak's Crescent Service will be adjusted as follows:

- Train 19 (5Jan-7Jan, 11Jan-14Jan, 18Jan-21Jan, 25Jan-28Jan, 1Feb-4Feb, 8Feb-11Feb, 16Feb-18Feb, 22Feb-25Feb, 1Mar-4Mar), which normally operates between NYP and NOL, will terminate at ATL.
- Train 20 (6Jan-8Jan, 12Jan-15Jan, 19Jan-22Jan, 26Jan-29Jan, 2Feb-5Feb, 9Feb-12Feb, 17Feb-19Feb, 23Feb-26Feb, 2Mar-5Mar), which normally operates between NOL and NYP, will originate at ATL.

ALTERNATE TRANSPORTATION:

- Local Bus 3119 will provide alternate transportation between ATL and NOL, making all scheduled station stops.
- Express Bus 3019 will provide alternate transportation from ATL to NOL only.
- Local Bus 3120 will provide alternate transportation between NOL and ATL, making all scheduled station stops.
- Express Bus 3020 will provide alternate transportation from NOL to ATL only.

Weekly Friday through Sunday (This INCLUDES Monday February 16th) - No Track Work Scheduled:

- Trains 19 & 20 will operate normal schedule and route between Atlanta and New Orleans.
- Trains may incur delays of 20-30 minutes operating through the track work area, due to residual slow orders and congestion.

WBS#: B.TR.100150.6165

Long Bridge Replacement Outage - Scheduled M/W Work

18DEC25: Starting January 11th, 2026, the Long Bridge replacement trackwork will commence causing reduced service and schedule changes through March 08, 2026 as follows:

January 11th will commence transition plan with 195 terminating New York and 153 terminating Washington D.C.

Monday through Friday: 114 cancelled, 133 cancelled, 141 terminates Washington D.C., 85 terminates Washington D.C., 176 originates Washington D.C., 174 originates Washington D.C., 84 originates Washington D.C., 134 originates Washington D.C., 86 originates Newport News, VA, 178 originates Roanoke, VA.

New trains operating Monday through Friday : 113 originating New York, NY and 198 originating Washington D.C.

Saturday: 167 terminates Philadelphia, PA, 153 terminates Washington D.C., 195 terminates Washington D.C., 155 operates through to Norfolk, VA, 164 originates Newport News, VA, 194 originates Washington D.C., 128 originates Norfolk, VA, 88 originates Washington D.C., 82 originates Washington D.C.

New train operating Saturday: 109 originates New York, NY

Sunday: 106 cancelled, 107 cancelled, 157 terminates Washington D.C., 155 operates through to Norfolk, VA, 195 terminates Washington D.C., 128 originates Norfolk, VA, 96 originates Washington D.C., 88 originates Washington D.C.

New trains operating Sunday: 117 originates Philadelphia, PA, 100 originates Washington D.C.

WBS#: B.TR.100150.6327

Eastern Region

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 383(19) West of Galesburg, IL - Freight Train Interference

20JAN26: Train 383(19) was delayed at Knox St/MP162.9 0.5 miles west of Galesburg, IL/MP162.4 on the BNSF Brookfield subdivision meeting freight CN/5627. The freight was stopped for an unplanned fueling event. Once the route was clear, train 383(19) continued west.

Train	Delay	Comment
383(19)	32"	

Train 11(19) South of Eugene , OR – Positive Train Control - Signals

19JAN26: Train 11(19) delayed 61 miles South of Eugene at Lookout, OR MP 586.1 on the Union Pacific Brooklyn Subdivision. The Positive Train Control system stopped the train after it was displaying a different aspect to the signal post at trackside. The signal post showed green while P.T.C showed a red signal. The Engineer was required contact dispatcher for authority to continue at reduced speed until the system synchronized with the trackside signals.

Train	Delay	Comment
11(19)	33"	

Train 518(19) North of Bellingham, WA - Freight Train Interference

19JAN26: Train 518(19) was delayed at North Swift/MP116.7 23 miles north of Bellingham, WA/MP93.4 on the BNSF Bellingham subdivision meeting BNSF freight 5401. Once the route was clear, train 518(19) continued north.

Train	Delay	Comment
518(19)	1'05"	

Train 704 (19) – South of Sacramento, CA – Debris Strike

19JAN26: Train 704 (19) was delayed after striking large rocks on the tracks approximately 14 miles south of the Sacramento station in Elk Grove - MP 51.6- on the Fresno Subdivision of the Union Pacific Railroad. No damage to the train and no injuries to the 50 passengers or crew were reported. After reconnecting the separated air hoses and completing a required compressed air safety test, the train resumed service and continued to Lodi. Amtrak Police were notified.

Train	Delay	Comment
704(19)	34"	

Train 540(19) East of Martinez, CA - Marine Traffic

19JAN26: Train 540(19) was delayed 1 mile east of Martinez at Vista MP 33.0 Martinez subdivision of the Union Pacific Railroad. The structure was raised to allow for the passage of marine traffic. Once the vessels had cleared, the bridge was lowered and train 540(19) was able to continue to Suisun.

Train	Delay	Comment
540(19)	27"	
536(19)	19"	
530(19)	05"	
543(19)	03"	

Train 542(19) - Northern Fremont, CA - Locomotive Shut Down - No Head End Power

19JAN26: Train 542(19) delayed 29 minutes at south Hayward MP 21.4, Niles Subdivision of the Union Pacific Railroad. Locomotive CDTX 2002 shut down not providing head end or tractive power. There were 61 passengers on board. Outside weather conditions 59°F, clear. After extensive diagnosing the crew identified a damaged 480V cable on café car C/8810 as the cause. The crew were able to perform a short-loop procedure between cars C/8202 and C/8810. This restored power, allowing train 542(19) to resume to Hayward.

Cause: Pending

Train	Delay	Comment
542(19)	29"	

Train 355(19) East of Ann Arbor, MI - Signal

20JAN26: Train 355(19) held at CP25/MP25.8 12 miles east of Ann Arbor, MI/MP37.5 on the Michigan Department of Transportation Michigan Line subdivision due to a switch failure. Switch maintainers responded and repaired the switch. Once clear of the affected area, train 355(19) continued west.

Train 352(19) was also delayed awaiting open track due to the switch failure at CP25.

Train	Delay	Comment
355(19)	1'07"	
352(19)	1'15"	

Train 354(19) Chicago, IL - Clogged Sander

19JAN26: Train 354(19), with engine IDTX4623, 5 cars, and 272 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to a clogged sander reported on the fireman side of engine IDTX4623. Diesel Technicians from the yard responded and cleared the clog. Once Mechanical was clear of the equipment, train 354(19) departed Chicago, IL.

Train	Delay	Comment
354(19)	31"	

Train 370(19) East of Chicago, IL - Signal

19JAN26: Train 370(19) stopped due to the number 3 switch failure at CP518/MP518.5 4 miles east of Chicago, IL/MP0.0 on the NS Chicago Terminal subdivision. Maintainers responded made repairs. Once clear of the affected area, train 370(19) continued east.

Train 354(19) was also delayed awaiting repair of the number 3 switch at CP518. Train 41(19) held at Chicago Union Station, IL and followed train 370(19) through the area.

Train	Delay	Comment
370(19)	1'20"	
354(19)	1'21"	
41(19)	22"	PTI - Follow 370(19)

Train 2/422(18) East of El Paso, TX - Trespasser Incident

19JAN26: Train 2/422(18) with engines 14 and 133 and 133 passengers, fatally struck a trespasser 5 miles east of El Paso, TX/MP1296.0 on the UP Valentine subdivision. There were no injuries reported by the passengers or crew. There was no damage reported to the equipment. HEP remained on throughout the incident. The strike did not occur at a grade crossing. The crew requested and was granted relief. An Amtrak Road Foreman and an UP supervisor responded to the scene. The relief crew signed up at 6:30PM MT out of EL Paso, TX. and arrived at 7:00PM MT. The medical examiner arrived at around 6:51PM MT. After local police and the RMCC released the train, train 2/422(18) was back on the move east.

National Response Center Number: 1453063

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(18)	3'41"	

Train 383(19) Chicago, IL - Water Leak

19JAN26: Train 383(19), with engine 154, 4 cars, and 142 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to a water leak discovered in the cafe car IDTX4311. Mechanical forces responded to repair the leak. OBS forces responded to clean up the spill. Once Mechanical and OBS were clear of the equipment, train 383(19) departed Chicago, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
383(19)	31"	

Train 41(19) Chicago, IL - Car Failure

19JAN26: Train 41(19), with engines 365 and 193, 10 cars, and 212 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late release of the engine 193 off of inbound train 4(17). Once the equipment was made up complete, train 41(19) shoved into the depot. Mechanical assistance was then requested for a hanging door panel on car 62511. Once repairs were made and Mechanical was clear of the equipment, train 41(19) departed Chicago, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(19)	40"	Late release of E/193
41(19)	42"	Repair door panel on C/62511

Train 364(19) Chicago, IL - Iced Windshields

19JAN26: Train 364(19), with engines IDTX4607 and IDTX4628, 7 cars, and 309 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to ice on the windshields of engine IDTX4607 obscuring clear vision. Train 364(19) held at the depot while the defrosters cleared the ice on the windshields. Once the windshields on IDTX4607 provided a clear view, train 364(19) departed Chicago, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(19)	30"	

Train 1340(19) Red Wing, MN - Engine Failure

19JAN26: Train 1340(19) FPI-00257 7600000005838S-E/"UNCLASSIFIED" delay at Red Wing, MN/MP370.68, on the CPKC River Subdivision, due to E/176 air compressor leaking air. The crew contacted mechanical and road foreman for assistance. The crew was able to make temporary repairs and Train 1340(19) was able to proceed east. Due to concerns over E/176 reliability, busses were secured to shadow Train 1340(19) between La Crosse, WI and Chicago, IL.

Due to necessary engine swap in Chicago and the anticipated late turn of equipment off Train 1340(19) for Train 341(19), the following service adjustment was in effect:

- Train 341(19) was cancelled, with on time alternate transportation between Chicago and Milwaukee, WI. One bus operated Chicago to Milwaukee making all stops and one bus operated Chicago to Milwaukee express. After an engine swap, equipment deadhead to Milwaukee to be in position for AM service 20JAN26.

WBS#: B.TR.100150.6408

Train	Delay	Comment
1340(19)	24"	RDW
341(19)	Cancelled, with alt CHI-MKE	

Train 5(19) Late Departure Chicago, IL - Late Turn of Power and Equipment Issues

19JAN26: Train 5(19), E/175-E/78 & 8 cars, was delayed departing Chicago, IL, due to late turn of power and equipment issues. E/175 turned off Train 51(18) which arrived at 1122AM-CT, then delays on the wye and releasing E/175. Train 5(19) was then further delayed due to C/34206 reported with frozen brakes in yard. Once the equipment shoved into the depot, train 5(19) boarded passengers, and departed.

Train	Delay	Comment
5(19)	2'06"	Frozen brakes on C/34206
5(19)	1'30"	Late release of E/175

Train 8/28(17) West of St. Paul-Minneapolis, MN - Broken Rail

19JAN26: Train 8/28(17) was delayed at Coon Creek/MP21.1, 25 miles west of St. Paul-Minneapolis, MN, on the BNSF Staples Subdivision, due to a broken rail ahead. Train 8/28(17) was delayed holding for MW to complete repairs and clear the location.

Train	Delay	Comment
8/28(17)	39"	

Train 530(19), East of Berkeley, CA - Freight Trespasser Incident

19JAN26 At approximately 2:45 PM PT, freight train LOA11 19 (UPRR 1081) struck a trespasser approximately 0.2 miles east of Berkeley on Main Track #1 at MP 6.5 on the Union Pacific Martinez Subdivision. The individual sustained fatal injuries. All tracks were temporarily closed to allow local authorities to conduct their investigation. Amtrak Train 530 (19) was held at Emeryville. Following the completion of the on scene investigation, Track #2 was reopened for restricted-speed operations at 2:00 PM PT.

Berkeley station remained closed while HAZMAT crews conducted platform cleanup, and trains were not permitted to stop at the station during this period. Amtrak Trains 534 (19) and 545 (19) were canceled due to the prolonged closure of Track #1 and resulting congestion.

Train 537(19) terminated in Richmond after all passengers transferred to Bay Area Rapid Transit (BART) departures.

Main Track #1 was reopened at 4:01 PM PT after the freight train was re-crewed and cleared the area.

Berkeley station re-opened to passengers and rail traffic at 5:45PM-PT.

A shuttle bus service operated for one trip between Emeryville and Berkeley station.

Mutual Aid- Bay Area Rapid Transit (BART) accepted Capitol Corridor tickets between Richmond and San Francisco and Richmond and San Jose Berryessa for the duration of the incident.

Service Recovery- Passengers on affected trains were offered 20% discount on café purchases.

Amtrak Police were notified.

WBS#: B.TR.100150.6409

Train	Delay	Comment
530(19)	2'40"	
530(19)		No Stop at Berkeley
532(19)	1'44"	
532(19)		No Stop at Berkeley
534(19)	Cancelled	No Alternate Transport Offered
536(19)		No Stop at Berkeley
538(19)		No Stop at Berkeley
539(19)	1'09"	
539(19)		No Stop at Berkeley
541(19)		No Stop at Berkeley
543(19)		No Stop at Berkeley
545(19)	Cancelled	NO Alternate Transport Offered
543(19)	2'22"	SAC - Equipment Turn From 530(19)
537(19)	1'01"	Terminates RIC - Passengers to BART
540(19)		No Stop at Berkeley
716(19)	35"	
542(19)	12"	SJC- Crew turn from 539(19)
550(19)	1'25"	SJC - Equipment Turn from 543(19)

Train 1333(19) Late Departure Chicago, IL - Turn of Equipment and Mechanical Issues

19JAN26: Train 1333(19) was delayed departing Chicago, IL, due to late turn of Train 332(19) which arrived at 1005AM-CT, 31 minutes late and planned engine swap due to loading issues on inbound E/168. The engine swap was extended due to E/168 stopped loading and necessary to tow off and set on track 30 before adding replacement E/194. Train 1333(19) was made up complete at 1124AM-CT and passenger boarding (186) began at 1157AM-CT. Train 1333(19) was then further delayed departing due to mechanical working on a frozen main line clog on the rear car, C/34094. Mechanical was unable to resolve issue and C/34094 was bad ordered inline. Due to C/34094 deadhead only, Train 1333(19) was over capacity by 65 seats between Chicago, IL and St. Paul-Minneapolis, MN. At Chicago, passengers destined for Sturtevant, WI, Milwaukee-Airport, WI and Milwaukee, WI, detrained and were reaccommodated on Train 335(19). A Supplemental bus was secured at Milwaukee, WI and operated express to St. Paul-Minneapolis.

WBS#: B.TR.100150.6406

Train	Delay	Comment
1333(19)	1'39"	
1333(19)		Supplemental Bus MKE-MSP

Train 6(17) West of Creston, IA - Freight Train Interference

19JAN26: Train 6(17) was delayed beginning 18 miles west of Creston, IA, on the BNSF Creston Subdivision, following BNSF 3944 and BNSF 9109 between MP412.0 and MP395.2.

Train	Delay	Comment
6(17)	49"	

Train 350(19) Late Departure Chicago, IL - Weather

19JAN26: Train 350(19), E/IDTX4608 & 5 cars, with 235 passengers, was delayed departing Chicago, IL, due to frozen brakes on cars. At approximately 620AM-CT, Train 350(19) reported air brake plungers on cars not working as intended. Mechanical forces responded from the yard and flagged train in at 716AM-CT to troubleshoot. Air brake issues were resolved and Train 350(19) departed Chicago at 734AM-CT, 49 minutes late.

Train 355(19) was delayed departing Pontiac, MI due to the late turn of equipment off train 350(19).

Train	Delay	Comment
350(19)	49"	
355(19)	50"	Late turn off 350(19)

Train 51(18) West of Indianapolis, IN - Freight Train Interference

19JAN26: Train 51(18) was delayed at MP9.4, 9 miles west of Indianapolis, IN, on the CSX Indianapolis Terminal Subdivision, due to CSX M640 ahead with DPU issues. Train 51(18) was delayed holding for freight to resolve mechanical issues and then following CSX M640 to Clermont/MP12.4.

Train	Delay	Comment
51(18)	1'06"	

Train 712(19) Oakland, CA - Lost Head-End Power

19JAN26: Train 712(19) with consist of 10 cars, including + 5 cars and locomotive E/C2104 at the rear, lost head-end power after departing the Oakland depot (MP 7.1/UPRR Niles Subdivision) and came to a stop at MP 6.8. There were 38 passengers onboard and the outside temperature was 55F and sunny. The crew began to troubleshoot the issue and TASI mechanical forces were notified. Due to the close proximity of the depot and the need to clear the mainline, the train made a reverse move back into the depot where it was met by the mechanical forces. The head-end power was restored after short-looping between locomotive E/C2104 and car C/5003.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
712(19)	53"	

Train 3(19) Chicago, IL - Car Failure

19JAN26: Train 3(19), with engines 189 and 140, 7 cars, and 149 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late bad order of car 31014 for high flange wheels. The replacement car, 31040, required additional time to warm up enough to hold water. Once the car was watered, the equipment shoved into the depot. Train 3(19) boarded passengers and departed Chicago, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(19)	2'05"	

Train 3(18) West of Lamar, CO - Car Failure

19JAN26: Train 3(18), E/147-E/207 & 6 cars, with 88 passengers on board, was delayed at MP508.4, 6 miles west of Lamar, CO, on the BNSF La Junta Subdivision, due to HEP dropped and E/147 with "passenger car load too high" alerts. Crew inspected consist and reported the third car, diner C/38016 with sparking under car. The crew was in contact with road foreman and mechanical for assistance. Weather was reported as 27 degrees with snow showers. Train 3(18) proceeded west, without HEP, to the La Junta depot/MP555.1 to further troubleshoot while passengers had access to the station. Passengers detrained and accommodated in station while crew and road foreman worked to resolve issues. After numerous attempts, electrical issues were still unresolved on the diner C/38016. Train 3(18) advanced just west of La Junta to the wye and switched the diner to the rear of consist to deadhead to Los Angeles. The road foreman secured an EOT and added it to the rear of C/38016. Train 3(18) began shove move back to depot and reported the passenger car overload faults returned. Once back in the station, crew performed a hard reset on E/207 and cleared faults. HEP was restored to train and held and passengers were able to reboard. Train 3(18) departed La Junta at 1028AM-MT, 2 hours and 58 minutes late.

As service recovery at La Junta, the station provide passengers with coffee, snacks and water. Albuquerque station also provided snacks, drinks and lunches to passengers waiting in the station to board. Stations also made personalized calls to passengers scheduled to board downline to update them on the train status. As service recovery onboard, coach passengers were provided complimentary snack packs and water. Sleepers were provided lunch at Raton, NM and dinner at Albuquerque, NM, supplied by outside vendors. Additional service recovery planned downline due to no diner in service.

WBS#: B.TR.100150.6405

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(18)	16"	W/LMR
3(18)	2'39"	

Train 391(19) South of Chicago, IL - Switch Failure

19JAN26: Train 391(19) was delayed at MP2.7, 2 miles south of Chicago, IL, due to the 854 switch at 21st Street failing reverse. Maintainer responded to the scene. After maintainer okayed switch, Train 391(19) was held for Train 58(18) to operate north first through the area.

Train	Delay	Comment
391(19)	59"	

Train 7/27(18) Minot, ND - Servicing

20JAN26: Train 7/27(18) was delayed departing Minot, ND/MP0.5 on the BNSF Glasgow subdivision due to additional time required to complete the calendar day inspection. Once the inspection was complete, train 7/27(19) departed Minot, ND.

Train	Delay	Comment
7/27(18)	39"	

Train 8/28(17) West of St. Paul-Minneapolis, MN - M of W Work

20JAN26: Train 8/28(17) was delayed at Coon Creek/MP21.1 24 miles west of St Paul - Minneapolis, MN/MP410.3 on the BNSF Staples subdivision due to broken rail. Once clear of the affected area, train 8/28(17) continued east.

Train	Delay	Comment
8/28(17)	39"	

Train 5(17) Elko, NV - Routing

19JAN26: Train 5(17) was delayed at Elko, NV, MP 556.7/UPRR Elko Subdivision, being routed through the Elko Yard, switching from main Track #1 to Main Track #2, in order to bypass a broken rail ahead at MP 542.7.

Train	Delay	Comment
5(17)	32"	

Train 5(18) East of Holdrege, NE - Air Hose Separation

19JAN26: Train 5(18), with engines 18 and 79, 10 cars, and 121 passengers, stopped in emergency at Minden/MP188.0 23 miles east of Holdrege, NE/MP210.9 on the BNSF Hastings subdivision due to an air hose separation between the baggage car 61055 and the crew dorm car 39044. The crew was delayed seating the air hose due to a broken glad hand. Once air pressure was restored, train 5(18) continued west. Train 5(18) stopped in emergency again at MP266.7, 56 miles west of Holdrege, NE, due to the same hose separated again. Crew reported no other exceptions to the equipment. Train 5(18) was on the move west again after crew secured hose and restored air.

Train	Delay	Comment
5(18)	37"	MP188
5(18)	19"	MP266.7

Train 6(17) West of Hastings, NE - Freight Train Interference

19JAN26: Train 6(17) was delayed west of Hastings, NE/MP156.1 on the BNSF Hastings subdivision from entering the station due to BNSF freight BN/6610 blocking the station track. Once the route was clear, train 6(17) entered Hastings, NE.

Train	Delay	Comment
6(17)	22"	

Train 5(17) East of Elko, NV - M or W Work

20JAN26: Train 5(17) ~~26-FOI-00257~~ ~~00000005638~~ ~~UNCLASSIFIED~~ 8.0 1/22/2026 Pilot/MP792.0 beginning 131.0 miles east Elko, NV/MP557.0 on the UP Shafter subdivision flagging across broken rail. Once clear of the affected area, train 5(17) continued west.

Train	Delay	Comment
5(17)	33"	

Train 3(19) Fort Madison, IA - Engine Failure

19JAN26: Train 3(19), with engines 189 and 140, 6 cars, and 158 passengers, was delayed west of Fort Madison, IA/MP232.9 on the BNSF Chillicothe subdivision adding BNSF freight BN/7466 due to loading problems on engine 189. Crew reported air issues after adding the freight and they resolved the issue by working with CNOC Mechanical Desk and a Los Angeles engine technician over the phone. Once the equipment was made up complete, train 3(19) continued west.

Train	Delay	Comment
3(19)	1'55"	

Train 330(19) East of Milwaukee, WI - B&B Work Due to Defect

19JAN26: Train 330(19) departed Milwaukee, WI/MP85.4, on the CPKC C&M Subdivision, on time and was then delayed just east of Milwaukee due to power switch issues ahead at the Menomonee/MP84.9 and KK/MP83.3 bridges. Train 330(19) was delayed through the affected area. Train 331(19) was delayed departing Chicago, IL, due to late turn of equipment off Train 330(19) which arrived at 851AM-CT, 54 minutes late. Train 329(19) was also delayed through the area, hand lining both switches at KK bridge/MP83.3. Train 332(19) was delayed departing Milwaukee due to crew turn off Train 329(19) which arrived at 1005AM-CT, 31 minutes late.

Train	Delay	Comment
330(19)	32"	
331(19)	53"	CHI, late turn of equip off 330(19)
329(19)	31"	
332(19)	27"	MKE, crew turn off 329(19)

Train 351(19) West of Dearborn, MI - Engine

19JAN26: Train 351(19), E/IDTX4601 & 5 cars, reported ITCS issues, unable to remove a zero target, and necessary to cut out ITCS on E/IDTX4601 at MP15, 3 miles west of Dearborn, MI, on the Amtrak Michigan Line. Train 351(19) was delayed enroute operating reduced speed, 59MPH MAX.

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

-715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.

-718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

716(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
-716(22) Modified Equipment for OMF from UNCLASSIFIED 1) as of 12/22/2026 repairs completed.

23DEC25

-714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
-713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

-520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
-535(24) Cancelled. Turn of equipment from cancelled train 520(24).
-534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

-Train 736(25-28) Cancelled - No alternate transportation.
-Train 737(25-28) Cancelled - No alternate transportation.
-Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

-Train 520(29-30) Cancelled - No alternate transportation.
-Train 534(29-30) Cancelled - No alternate transportation.
-Train 535(29) Cancelled - No alternate transportation.
-Train 537(30) Cancelled - No alternate transportation.
-Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

-Train 520(31) Cancelled - No alternate transportation.
-Train 534(31) Cancelled - No alternate transportation.
-Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

-Train 736(01-04) Cancelled - No alternate transportation.
-Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-06MAR) Cancelled - No alternate transportation.
- TRAIN 713(06JAN-07MAR) Cancelled - No alternate transportation.

10JAN26 - 11JAN26

-Train 736(10-11) Cancelled - No alternate transportation.
-Train 737(10-11) Cancelled - No alternate transportation.

12JAN26 - 13JAN26

-Train 520(12-13) Cancelled - No alternate transportation.
-Train 534(12-13) Cancelled - No alternate transportation.
-Train 535(12-13) Cancelled - No alternate transportation.

14JAN26:

-Train 520(14) Cancelled - No alternate transportation.
-Train 537(14) Cancelled - No alternate transportation.
-Train 534(14) Cancelled - No alternate transportation.

15JAN26:

-Train 520(15-16) Cancelled - No Alternate Transport offered
-Train 534(15-16) Cancelled - No Alternate Transport offered
-Train 535(16) Cancelled - No Alternate Transport offered
-Train 537(15) Cancelled - No Alternate Transport offered

17JAN26:

-Train 718(17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744(17) OKJ-EMY.

Cause: Pending

EMY

718 (21) 37" ITD - EMY

716 (22) 20"

718 (22) 3'10" ITD - EMY

713 (22)	3-10	713-22
714 (23)	.	CANCELLED

711 (23)	.	CANCELLED
713 (24)	.	CANCELLED

535 (24) Cancelled

520 (24)	Cancelled
----------	-----------

534 (24) Canceled

736 (25-28)	Cancelled
-------------	-----------

737 (25-28) Canceled

749 (28) Canceled

551 (29-30)	Cancelled	Replacement Bus SAC-OKJ
-------------	-----------	-------------------------

520 (29-31)	Cancelled	No alternate transportation.
-------------	-----------	------------------------------

534 (29-31)	Cancelled	No alternate transportation.
-------------	-----------	------------------------------

736 (01JAN-04JAN)) Cancelled No alternate transportation

737 (01JAN-04JAN)	Cancelled	No alternate transportation
-------------------	-----------	-----------------------------

535 (29)	Cancelled	No alternate transportation.
----------	-----------	------------------------------

537 (30-31)	Cancelled	No Alternate Transportation
-------------	-----------	-----------------------------

713 (06JAN-07MAR)	CANCELLED	No Alternate Transport Offered
-------------------	-----------	--------------------------------

714 (05JAN-06MAR)	CANCELLED	No Alternate Transport Offered
-------------------	-----------	--------------------------------

736 (10-11JAN)	Cancelled	No Alternate Transport Offered
----------------	-----------	--------------------------------

737 (10-11JAN)	Cancelled	No Alternate Transport Offered
----------------	-----------	--------------------------------

520 (12-13-14- 15-	Cancelled	No alternate transportation
--------------------	-----------	-----------------------------

16 JAN)

534 (12-13-14-15-16	Cancelled	No alternate transportation
---------------------	-----------	-----------------------------

JAN)

535 (12-13-16JAN) Cancelled No alternate transportation

537 (14-15JAN)	Cancelled	No Alternate Transport offered
----------------	-----------	--------------------------------

718 (17)	Originate	Pax to 744 OKJ-EMY
----------	-----------	--------------------

EMY

718 (17) 35"

Western Region

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
8 (15)	SCD	369		Shelled wheels

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (17)	DEN	UP7426	E/163 blower fault	OKJ	1/19/26
3 (19)	FMD	UP7466	E/189 low water pressure faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
307(12)	12	No	Business Class removed, passengers were downgraded and removed.

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
14	PDX	1	OLW	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 14(18) Passenger Removal at Portland, Oregon – Improper Conduct***

19JAN26, Passenger on PNR 56B36D, traveling from Sacramento, CA to Seattle, WA was removed from the train due to smoking in the ADA bathroom. Amtrak Police notified.

Delay: 14 (18) **None**

Train 593(19) Passenger Removal at Oceanside, California – Fare Evader

19JAN26, Passenger on PNR Unknown, traveling from Oceanside, CA to Los Angeles, CA was removed from the train due to fare evading. The trespasser snuck on the train and attacked the crew member. Amtrak Police notified.

Delay: 593 (19) **02"**

Consist Deviations

26-FOI-00257

00000005638

"UNCLASSIFIED"

1/22/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
57 (19)	NHV	Operating with 4 coaches, local coach not added due 82751 set out in NHV off 54(19).	OVER CAPACITY PASSENGERS NOTIFIED	21	
97 (20)	NYP	Due to an equipment change it was necessary to perform a schedule change on train 97(20) line 9711. Please re-accommodate all affected passengers utilizing the WAR report shown below	PASSENGERS REACCOMODATED	0	62515

Reverse Consists

Train Number	Station	Reason
153 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front
103 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front
135 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front
150 (19)	PHL	Consist reversed Business class seat orientation may have changed At Front
2259 (19)	BOS	Acela consist reversed First class at Rear
149 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front
166 (19)	WAS	Consist reversed Business class seat orientation may have changed At Front