



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, July 16, 2026

Rules: 0-37



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/15/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/15/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	50	84.1%	4,561	686	85.0%	85,908	11,808	86.3%
Central Division	86.0%	57	10	82.5%	817	85	89.6%	16,545	1,482	91.0%
East Division	82.0%	164	27	83.5%	2,396	418	82.6%	44,947	7,025	84.4%
West Division	86.0%	93	13	86.0%	1,348	183	86.4%	24,416	3,301	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00603 00000008329 UNCLASSIFIED 7/21/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	97,179	38,216	61%	1,577,262	583,366	63%	28,524,586	7,057,652	75%
Northeast Corridor	81%	40,456	17,456	57%	677,602	265,605	61%	12,521,383	3,048,798	76%
Acela	83%	9,652	5,622	42%	149,604	58,028	61%	2,486,369	660,705	73%
Northeast Regional	79%	30,804	11,834	62%	527,998	207,577	61%	10,035,014	2,388,093	76%
Richmond / Newport News / Norfolk	77%	10,086	6,387	37%	165,251	80,366	51%	3,115,979	893,987	71%
Springfield Shuttles	89%	588	112	81%	9,533	2,970	69%	177,567	27,184	85%
Roanoke	79%	2,580	757	71%	49,133	22,538	54%	942,193	197,823	79%
On Spine Northeast Regional	80%	17,550	4,578	74%	304,081	101,703	67%	5,799,275	1,269,099	78%
State Supported	80%	44,941	13,345	70%	707,000	193,143	73%	12,493,048	2,555,507	80%
Borealis	80%	601	221	63%	8,949	2,080	77%	159,919	32,526	80%
Capitol Corridor	90%	3,718	494	87%	56,214	9,465	83%	1,057,433	138,661	87%
Carolinian	70%	1,404	940	33%	16,462	10,546	36%	326,436	126,452	61%
Cascades	75%	2,547	519	80%	46,928	11,576	75%	734,572	200,136	73%
Downeaster	82%	1,965	415	79%	28,501	7,433	74%	425,999	52,903	88%
Empire	78%	5,417	2,762	49%	90,495	32,934	64%	1,544,500	347,351	78%
Adirondack	72%	305	166	46%	6,404	2,882	55%	92,837	28,366	69%
Ethan Allen Express	70%	504	487	3%	8,643	5,672	34%	159,608	53,279	67%
Maple Leaf	70%	428	326	24%	12,893	5,221	60%	187,712	72,008	62%
New York - Albany	85%	2,873	581	80%	40,059	9,471	76%	717,224	113,371	84%
New York - Niagara Falls	75%	1,307	1,202	8%	20,418	8,282	59%	381,877	78,061	80%
Berkshire Flyer	60%	0	0	-	2,078	1,406	32%	5,242	2,266	57%
Gold Runner	73%	2,165	1,333	38%	39,269	15,926	59%	712,889	248,024	65%
Heartland Flyer	70%	179	171	4%	4,128	2,121	49%	59,833	22,614	62%
Hiawatha	90%	2,029	559	72%	29,291	2,047	93%	486,985	52,595	89%
Illinois	78%	2,042	939	54%	38,226	13,231	65%	700,381	189,275	73%
Carl Sandburg / Illinois Zephyr	85%	410	117	71%	7,062	2,315	67%	116,616	30,121	74%
Illini / Saluki	85%	483	337	30%	13,451	4,213	69%	247,113	58,240	76%
Lincoln Service	70%	1,149	485	58%	17,713	6,703	62%	336,652	100,914	70%
Keystone	92%	9,639	888	91%	104,251	17,983	83%	2,161,328	227,918	89%
Lincoln / Missouri	70%	773	375	51%	10,182	5,758	43%	218,701	109,574	50%
Mardi Gras Service	80%	455	239	47%	6,102	2,419	60%	117,050	24,880	79%
Michigan	70%	2,653	1,141	57%	34,993	14,505	59%	554,740	179,460	68%
Blue Water	70%	947	831	12%	8,713	6,078	30%	128,939	51,412	60%
Pere Marquette	85%	189	0	100%	4,774	983	79%	72,346	14,313	80%
Wolverine	70%	1,517	310	80%	21,506	7,444	65%	353,455	113,735	68%
Missouri	80%	201	65	68%	2,443	977	60%	61,679	14,217	77%
Pacific Surfliner	85%	6,644	1,506	77%	148,992	26,241	82%	2,231,516	353,403	84%
Pennsylvanian	80%	860	211	75%	13,408	5,820	57%	252,118	47,979	81%
Piedmont	80%	446	137	69%	9,914	3,648	63%	323,299	82,202	75%
Vermont	75%	1,203	430	64%	18,252	8,433	54%	363,670	105,337	71%
Long Distance	70%	11,782	7,415	37%	192,660	124,618	35%	3,470,888	1,450,884	58%
Auto Train	70%	744	369	50%	12,460	4,995	60%	221,304	75,823	66%
California Zephyr	70%	932	459	51%	15,319	9,927	35%	275,382	95,224	65%
Cardinal	70%	0	0	-	3,468	2,439	30%	67,142	32,681	51%
City Of New Orleans	75%	362	266	27%	2,250	1,828	19%	179,614	51,445	71%
Coast Starlight	70%	1,180	205	83%	18,938	6,028	68%	323,702	110,480	66%
Crescent	70%	815	404	50%	14,233	8,633	39%	264,726	80,725	70%
Empire Builder	70%	1,661	1,571	5%	18,736	12,107	35%	271,797	130,859	52%
Floridian	60%	1,356	1,248	8%	23,568	22,380	5%	453,733	306,023	33%
Lake Shore Ltd	73%	1,107	298	73%	17,825	7,831	56%	269,462	79,441	71%
Palmetto	70%	428	297	31%	13,016	9,556	27%	260,789	75,654	71%
Silver Meteor	70%	912	658	28%	16,011	13,378	16%	288,392	123,530	57%
Southwest Chief	60%	929	470	49%	15,277	11,204	27%	233,927	149,616	36%
Sunset Ltd	70%	356	353	1%	5,251	3,213	39%	83,636	29,894	64%
Texas Eagle	70%	1,000	817	18%	16,308	11,099	32%	277,282	109,489	61%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FOI-00000 00000000020 "UNCLASSIFIED" 7/21/2026

Train Index Dates Through July 15, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	104,632	1,576,959	664	1,671,565	30,214,001	553

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	5,693	464,293	123	79,033	8,679,052	91
INFRASTRUCTURE PLANNED	135	7,539	464,293	162	86,411	8,679,052	100
FLEET RELIABILITY	90	16,476	1,576,959	104	269,465	30,214,001	89
TRAIN OPERATIONS	424	74,924	1,576,959	475	1,236,656	30,214,001	409

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/15/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/15/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	50	84.1%	4,561	686	85.0%	85,908	11,808	86.3%
Central Division	86.0%	57	10	82.5%	817	85	89.6%	16,545	1,482	91.0%
East Division	82.0%	164	27	83.5%	2,396	418	82.6%	44,947	7,025	84.4%
West Division	86.0%	93	13	86.0%	1,348	183	86.4%	24,416	3,301	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-00633 Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/15/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	50	84.1%	4,561	686	85.0%	85,908	11,808	86.3%
Central Division	86.0%	57	10	82.5%	817	85	89.6%	16,545	1,482	91.0%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	1	0	100.0%	28	3	89.3%	545	21	96.1%
CHI	86.0%	26	7	73.1%	383	44	88.5%	7,622	908	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	15	1	93.3%	311	35	88.7%
GBB	-	1	1	0.0%	6	5	16.7%	6	5	16.7%
GRR	95.5%	1	0	100.0%	14	0	100.0%	273	8	97.1%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	21	2	90.5%	559	42	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	2	66.7%	88	6	93.2%	1,686	103	93.9%
MOE	97.5%	2	0	100.0%	30	1	96.7%	575	9	98.4%
MSP	96.5%	1	0	100.0%	15	0	100.0%	281	5	98.2%
NOL	94.5%	5	0	100.0%	57	6	89.5%	1,207	59	95.1%
OKC	97.0%	1	0	100.0%	15	0	100.0%	282	6	97.9%
PNT	88.0%	3	0	100.0%	38	4	89.5%	741	62	91.6%
PTH	93.0%	1	0	100.0%	15	1	93.3%	276	11	96.0%
QCY	91.0%	1	0	100.0%	21	3	85.7%	552	43	92.2%
SAS	90.5%	1	0	100.0%	15	1	93.3%	284	28	90.1%
STL	89.0%	4	0	100.0%	55	7	87.3%	1,112	97	91.3%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	164	27	83.5%	2,396	418	82.6%	44,947	7,025	84.4%
ALB	88.5%	8	1	87.5%	116	6	94.8%	2,130	167	92.2%
BON	87.5%	5	0	100.0%	74	10	86.5%	1,386	150	89.2%
BOS	85.5%	15	1	93.3%	250	16	93.6%	4,886	577	88.2%
BRK	92.5%	2	0	100.0%	71	13	81.7%	1,372	97	92.9%
BTN	82.0%	1	0	100.0%	15	1	93.3%	274	40	85.4%
CLT	91.5%	4	1	75.0%	58	11	81.0%	1,399	143	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	30	4	86.7%	561	54	90.4%
GRO	-	1	0	100.0%	3	0	100.0%	32	10	68.8%
HAR	79.5%	13	2	84.6%	156	24	84.6%	3,179	530	83.3%
HFD	-	2	0	100.0%	20	4	80.0%	167	12	92.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	15	1	93.3%	284	35	87.7%
MIA	89.5%	2	0	100.0%	29	3	89.7%	568	63	88.9%
MTR	79.0%	1	0	100.0%	15	4	73.3%	271	50	81.5%

Information Management

26-FOI-0060 Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/15/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	50	84.1%	4,561	686	85.0%	85,908	11,808	86.3%
East Division	82.0%	164	27	83.5%	2,396	418	82.6%	44,947	7,025	84.4%
NFK	84.5%	2	0	100.0%	30	9	70.0%	651	118	81.9%
NFL	93.5%	2	0	100.0%	30	3	90.0%	580	25	95.7%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	6	1	83.3%	72	11	84.7%	1,478	234	84.2%
NPN	93.0%	2	0	100.0%	28	3	89.3%	541	38	93.0%
NYP	75.5%	48	9	81.3%	677	171	74.7%	11,728	2,632	77.6%
PGH	93.0%	1	0	100.0%	15	3	80.0%	286	22	92.3%
PHL	48.0%	5	2	60.0%	74	34	54.1%	1,474	711	51.8%
PIT	76.0%	-	-	-	4	4	0.0%	10	9	10.0%
POR	-	3	3	0.0%	3	3	0.0%	11	8	27.3%
RGH	95.0%	2	0	100.0%	40	5	87.5%	1,097	46	95.8%
RNK	83.5%	2	0	100.0%	30	4	86.7%	564	81	85.6%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	-	-	-	12	0	100.0%	271	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	13	0	100.0%	281	10	96.4%
SFA	88.0%	1	1	0.0%	15	1	93.3%	284	38	86.6%
SPG	92.5%	5	0	100.0%	71	5	93.0%	1,723	97	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	15	1	93.3%	274	57	79.2%
WAS	84.0%	26	6	76.9%	414	63	84.8%	7,007	904	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	93	13	86.0%	1,348	183	86.4%	24,416	3,301	86.5%
ARN	92.0%	1	0	100.0%	15	4	73.3%	286	23	92.0%
BFD	79.0%	7	1	85.7%	100	23	77.0%	1,786	364	79.6%
EMY	72.0%	1	0	100.0%	15	6	60.0%	302	92	69.5%
EUG	86.5%	2	0	100.0%	30	0	100.0%	566	52	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	1	50.0%	3	2	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	45	12	73.3%	861	126	85.4%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	1	90.9%	157	15	90.4%	2,833	291	89.7%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	3	76.9%	176	52	70.5%	3,075	788	74.4%
PDX	86.0%	5	1	80.0%	75	5	93.3%	1,412	171	87.9%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	1	93.8%	224	21	90.6%	4,029	431	89.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/15/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/15/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	50	84.1%	4,561	686	85.0%	85,908	11,808	86.3%
West Division	86.0%	93	13	86.0%	1,348	183	86.4%	24,416	3,301	86.5%
SAN	90.5%	13	1	92.3%	194	14	92.8%	3,438	308	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	120	15	87.5%	2,262	325	85.6%
SJC	89.0%	7	2	71.4%	105	12	88.6%	2,012	194	90.4%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	45	2	95.6%	624	62	90.1%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	15	1	93.3%	281	21	92.5%
VAC	97.0%	2	0	100.0%	30	0	100.0%	560	14	97.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	125	7	0	100.0%	122	8	93.4%	7	4	42.9%	122	27	77.9%
3		15	2	86.7%	286	56	80.4%	15	6	60.0%	284	123	56.7%
4		15	1	93.3%	285	43	84.9%	15	9	40.0%	285	188	34.0%
5	160	15	2	86.7%	284	45	84.2%	14	11	21.4%	280	74	73.6%
6		15	6	60.0%	283	83	70.7%	15	10	33.3%	283	92	67.5%
7	110	15	2	86.7%	275	37	86.5%	15	6	60.0%	268	67	75.0%
8	269	15	8	46.7%	275	119	56.7%	15	12	20.0%	274	161	41.2%
11		15	3	80.0%	286	53	81.5%	15	2	86.7%	280	56	80.0%
14		15	2	86.7%	287	43	85.0%	15	2	86.7%	285	85	70.2%
19	113	15	7	53.3%	285	72	74.7%	15	10	33.3%	283	69	75.6%
20	32	15	4	73.3%	285	22	92.3%	15	9	40.0%	285	56	80.4%
21	No OS	15	0	100.0%	282	22	92.2%	15	11	26.7%	281	73	74.0%
22	58	15	1	93.3%	283	26	90.8%	15	11	26.7%	281	73	74.0%
23	46	15	1	93.3%	288	6	97.9%	15	8	46.7%	286	77	73.1%
24		15	2	86.7%	288	16	94.4%	15	6	60.0%	287	49	82.9%
25		15	0	100.0%	287	3	99.0%	15	6	60.0%	285	75	73.7%
26	118	15	0	100.0%	287	5	98.3%	15	5	66.7%	285	57	80.0%
27	121	15	3	80.0%	273	17	93.8%	15	6	60.0%	269	87	67.7%
28		15	2	86.7%	269	61	77.3%	15	1	93.3%	269	52	80.7%
40	454	14	2	85.7%	280	40	85.7%	14	12	14.3%	279	144	48.4%
41	140	14	8	42.9%	280	110	60.7%	14	14	0.0%	278	210	24.5%
42		15	3	80.0%	287	23	92.0%	15	6	60.0%	285	48	83.2%
43	72	15	1	93.3%	286	42	85.3%	15	9	40.0%	286	65	77.3%
48		15	3	80.0%	285	56	80.4%	15	3	80.0%	285	41	85.6%
49		15	4	73.3%	285	71	75.1%	15	6	60.0%	285	58	79.6%
50	180	6	1	83.3%	117	27	76.9%	7	6	14.3%	117	69	41.0%
52		15	1	93.3%	284	38	86.6%	15	4	73.3%	283	65	77.0%
53	177	15	1	93.3%	284	35	87.7%	15	5	66.7%	283	90	68.2%
55		10	0	100.0%	178	6	96.6%	10	3	70.0%	175	37	78.9%
56		10	0	100.0%	179	22	87.7%	9	5	44.4%	175	31	82.3%
59	121	4	1	75.0%	262	29	88.9%	3	3	0.0%	258	49	81.0%
63	Cncld	15	8	46.7%	288	125	56.6%	14	12	14.3%	283	152	46.3%
64	26	15	1	93.3%	286	64	77.6%	15	8	46.7%	286	99	65.4%
66		15	3	80.0%	285	57	80.0%	13	2	84.6%	281	51	81.9%
67		10	1	90.0%	197	12	93.9%	10	3	70.0%	197	34	82.7%
68	75	15	4	73.3%	288	59	79.5%	15	8	46.7%	288	111	61.5%
69		15	3	80.0%	275	62	77.5%	15	6	60.0%	271	38	86.0%
71		15	0	100.0%	283	3	98.9%	15	8	46.7%	282	74	73.8%
72		11	1	90.9%	279	30	89.2%	11	3	72.7%	278	58	79.1%
73		10	2	80.0%	282	18	93.6%	10	5	50.0%	280	131	53.2%
74	11	10	1	90.0%	280	31	88.9%	10	6	40.0%	278	100	64.0%
77	56	10	3	70.0%	279	20	92.8%	10	7	30.0%	277	115	58.5%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78	26	15	4	73.3%	283	24	91.5%	15	9	40.0%	282	59	79.1%
79	46	15	0	100.0%	285	55	80.7%	15	11	26.7%	284	95	66.5%
80	32	15	4	73.3%	285	32	88.8%	14	7	50.0%	282	56	80.1%
85	32	10	0	100.0%	180	16	91.1%	10	4	60.0%	180	65	63.9%
86	24	10	1	90.0%	180	15	91.7%	10	8	20.0%	179	108	39.7%
89	51	15	5	66.7%	283	63	77.7%	15	10	33.3%	281	80	71.5%
90	96	15	0	100.0%	283	10	96.5%	15	11	26.7%	282	48	83.0%
93	29	10	0	100.0%	179	18	89.9%	10	5	50.0%	178	42	76.4%
94	43	10	3	70.0%	210	53	74.8%	10	7	30.0%	208	76	63.5%
95	102	10	1	90.0%	179	4	97.8%	10	5	50.0%	179	64	64.2%
97	70	15	14	6.7%	285	187	34.4%	15	12	20.0%	283	88	68.9%
98	39	15	1	93.3%	285	22	92.3%	15	14	6.7%	283	94	66.8%
110		10	4	60.0%	176	100	43.2%	10	2	80.0%	173	18	89.6%
111		10	0	100.0%	170	32	81.2%	10	1	90.0%	168	21	87.5%
112		10	0	100.0%	170	16	90.6%	10	2	80.0%	169	19	88.8%
113	31	10	1	90.0%	101	23	77.2%	10	1	90.0%	100	12	88.0%
125	70	10	1	90.0%	180	9	95.0%	10	5	50.0%	180	71	60.6%
129		10	2	80.0%	179	46	74.3%	10	2	80.0%	179	25	86.0%
130		10	1	90.0%	170	17	90.0%	10	1	90.0%	168	16	90.5%
131	23	10	4	60.0%	172	51	70.3%	10	6	40.0%	172	35	79.7%
134	39	10	3	70.0%	180	24	86.7%	10	4	60.0%	179	30	83.2%
136		10	2	80.0%	180	22	87.8%	10	4	60.0%	178	21	88.2%
137		10	2	80.0%	177	32	81.9%	10	3	70.0%	177	55	68.9%
138	91	10	3	70.0%	180	38	78.9%	10	5	50.0%	179	32	82.1%
141		10	0	100.0%	179	3	98.3%	10	2	80.0%	178	30	83.1%
148	57	10	1	90.0%	179	18	89.9%	10	3	70.0%	177	33	81.4%
151		15	4	73.3%	284	90	68.3%	15	8	46.7%	283	92	67.5%
170		10	0	100.0%	175	12	93.1%	10	0	100.0%	174	29	83.3%
171	134	10	0	100.0%	180	10	94.4%	10	8	20.0%	180	69	61.7%
172		10	0	100.0%	179	14	92.2%	10	4	60.0%	177	59	66.7%
174		10	0	100.0%	180	20	88.9%	10	5	50.0%	180	43	76.1%
175		10	0	100.0%	180	21	88.3%	10	2	80.0%	180	57	68.3%
177		10	1	90.0%	180	25	86.1%	10	0	100.0%	180	44	75.6%
178		10	0	100.0%	180	24	86.7%	10	3	70.0%	178	26	85.4%
179		10	2	80.0%	180	21	88.3%	10	5	50.0%	179	63	64.8%
181		10	1	90.0%	176	55	68.8%	10	2	80.0%	174	14	92.0%
182	18	10	1	90.0%	170	29	82.9%	10	2	80.0%	168	18	89.3%
183		10	3	70.0%	179	51	71.5%	10	2	80.0%	177	35	80.2%
184	39	10	3	70.0%	180	32	82.2%	10	4	60.0%	179	27	84.9%
185	33	10	1	90.0%	180	37	79.4%	10	1	90.0%	180	12	93.3%
186	38	10	1	90.0%	179	18	89.9%	10	4	60.0%	178	44	75.3%
190		10	2	80.0%	179	64	64.2%	10	2	80.0%	178	39	78.1%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
192		10	3	70.0%	177	22	87.6%	10	1	90.0%	177	15	91.5%
197	25	10	4	60.0%	180	72	60.0%	10	7	30.0%	180	60	66.7%
198		10	3	70.0%	112	17	84.8%	10	3	70.0%	111	19	82.9%
230		15	0	100.0%	122	4	96.7%	15	0	100.0%	122	6	95.1%
232		15	0	100.0%	288	11	96.2%	15	0	100.0%	288	17	94.1%
233	42	11	2	81.8%	262	58	77.9%	11	8	27.3%	262	81	69.1%
234		15	1	93.3%	288	20	93.1%	15	0	100.0%	288	24	91.7%
235		15	2	86.7%	212	29	86.3%	15	5	66.7%	212	46	78.3%
236		15	1	93.3%	272	8	97.1%	15	2	86.7%	272	38	86.0%
237	18	15	1	93.3%	286	53	81.5%	15	5	66.7%	284	48	83.1%
238		15	0	100.0%	212	19	91.0%	15	1	93.3%	211	15	92.9%
239		15	4	73.3%	287	76	73.5%	15	4	73.3%	286	34	88.1%
240	32	15	0	100.0%	287	20	93.0%	15	7	53.3%	285	51	82.1%
241		15	3	80.0%	288	71	75.3%	15	3	80.0%	288	69	76.0%
243	56	15	6	60.0%	224	61	72.8%	15	4	73.3%	223	30	86.5%
244		11	2	81.8%	262	12	95.4%	11	5	54.5%	262	43	83.6%
245		15	4	73.3%	169	31	81.7%	15	2	86.7%	168	19	88.7%
280	36	15	2	86.7%	288	13	95.5%	15	2	86.7%	288	52	81.9%
281	22	15	3	80.0%	288	32	88.9%	15	7	53.3%	288	54	81.3%
283	24	15	4	73.3%	288	68	76.4%	15	7	53.3%	288	59	79.5%
284	20	15	1	93.3%	288	11	96.2%	15	8	46.7%	286	50	82.5%
290	49	15	1	93.3%	288	49	83.0%	15	11	26.7%	286	102	64.3%
291	86	15	8	46.7%	287	83	71.1%	15	8	46.7%	285	66	76.8%
300		15	1	93.3%	272	20	92.6%	15	8	46.7%	270	64	76.3%
301		15	0	100.0%	286	9	96.9%	15	3	80.0%	283	53	81.3%
302	28	9	1	88.9%	267	32	88.0%	9	3	66.7%	263	75	71.5%
305		9	0	100.0%	270	28	89.6%	9	6	33.3%	266	108	59.4%
306		15	0	100.0%	284	15	94.7%	15	5	66.7%	283	76	73.1%
307	17	15	3	80.0%	276	38	86.2%	15	6	60.0%	273	76	72.2%
311		12	2	83.3%	283	25	91.2%	11	5	54.5%	277	55	80.1%
316	73	11	1	90.9%	279	17	93.9%	10	5	50.0%	275	69	74.9%
318		14	4	71.4%	286	30	89.5%	14	10	28.6%	283	134	52.7%
319	131	14	1	92.9%	287	18	93.7%	11	7	36.4%	282	152	46.1%
329		11	0	100.0%	203	8	96.1%	11	0	100.0%	203	13	93.6%
330		13	0	100.0%	244	4	98.4%	13	1	92.3%	244	14	94.3%
331	21	15	1	93.3%	288	30	89.6%	15	1	93.3%	288	41	85.8%
332	59	15	2	86.7%	288	16	94.4%	15	3	80.0%	288	42	85.4%
334		15	0	100.0%	288	9	96.9%	15	1	93.3%	287	37	87.1%
335		15	0	100.0%	288	30	89.6%	15	3	80.0%	286	46	83.9%
336		15	1	93.3%	288	9	96.9%	15	2	86.7%	286	27	90.6%
337		15	1	93.3%	288	18	93.8%	15	2	86.7%	284	35	87.7%
338		15	3	80.0%	288	44	84.7%	15	5	66.7%	286	86	69.9%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
339	18	15	2	86.7%	288	48	83.3%	15	2	86.7%	288	50	82.6%
341		15	3	80.0%	277	38	86.3%	15	2	86.7%	272	37	86.4%
342		15	0	100.0%	288	21	92.7%	15	2	86.7%	286	55	80.8%
350	35	12	1	91.7%	266	18	93.2%	10	5	50.0%	259	141	45.6%
351		15	2	86.7%	271	27	90.0%	15	4	73.3%	269	72	73.2%
352		15	0	100.0%	255	20	92.2%	15	4	73.3%	249	75	69.9%
353		12	1	91.7%	227	13	94.3%	12	2	83.3%	221	37	83.3%
354		15	6	60.0%	269	34	87.4%	13	7	46.2%	263	96	63.5%
355	34	12	2	83.3%	279	29	89.6%	12	8	33.3%	272	93	65.8%
364		15	2	86.7%	277	62	77.6%	15	10	33.3%	271	100	63.1%
365	30	15	1	93.3%	276	11	96.0%	15	10	33.3%	274	102	62.8%
370	45	15	1	93.3%	279	34	87.8%	14	3	78.6%	271	68	74.9%
371		14	0	100.0%	273	8	97.1%	14	2	85.7%	272	29	89.3%
380		14	3	78.6%	273	27	90.1%	14	6	57.1%	273	55	79.9%
381	17	13	0	100.0%	286	11	96.2%	13	4	69.2%	285	52	81.8%
382	22	13	5	61.5%	285	21	92.6%	13	7	46.2%	285	91	68.1%
383	21	15	1	93.3%	277	26	90.6%	14	7	50.0%	274	112	59.1%
390	20	15	1	93.3%	270	18	93.3%	15	5	66.7%	269	68	74.7%
393	19	15	0	100.0%	288	16	94.4%	15	9	40.0%	285	86	69.8%
417		10	3	70.0%	190	41	78.4%	10	2	80.0%	181	19	89.5%
425		10	0	100.0%	192	6	96.9%	10	0	100.0%	192	7	96.4%
448		15	3	80.0%	218	41	81.2%	15	6	60.0%	216	74	65.7%
449		15	1	93.3%	216	31	85.6%	15	4	73.3%	216	40	81.5%
470		10	1	90.0%	203	35	82.8%	10	1	90.0%	197	24	87.8%
471		10	3	70.0%	193	9	95.3%	10	2	80.0%	193	4	97.9%
473		10	1	90.0%	199	14	93.0%	10	0	100.0%	196	8	95.9%
474	22	13	7	46.2%	197	58	70.6%	10	8	20.0%	182	55	69.8%
475		10	0	100.0%	197	5	97.5%	10	3	70.0%	197	13	93.4%
478	18	10	2	80.0%	191	29	84.8%	10	2	80.0%	189	22	88.4%
479		10	2	80.0%	198	31	84.3%	10	5	50.0%	196	27	86.2%
486		10	1	90.0%	202	29	85.6%	10	4	60.0%	196	54	72.4%
494	115	10	2	80.0%	203	37	81.8%	10	8	20.0%	197	52	73.6%
495		10	0	100.0%	188	3	98.4%	10	0	100.0%	186	3	98.4%
500		15	1	93.3%	279	16	94.3%	14	1	92.9%	276	33	88.0%
502		15	1	93.3%	286	16	94.4%	14	1	92.9%	282	57	79.8%
503		15	1	93.3%	284	26	90.8%	15	8	46.7%	278	82	70.5%
504		15	0	100.0%	288	17	94.1%	15	3	80.0%	286	85	70.3%
505		15	1	93.3%	286	37	87.1%	14	6	57.1%	281	79	71.9%
506		15	1	93.3%	283	39	86.2%	15	3	80.0%	278	44	84.2%
507	26	15	1	93.3%	288	35	87.8%	15	4	73.3%	288	92	68.1%
508		15	0	100.0%	283	39	86.2%	15	2	86.7%	280	64	77.1%
509	26	15	0	100.0%	285	12	95.8%	15	2	86.7%	285	65	77.2%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
511		15	0	100.0%	280	21	92.5%	15	0	100.0%	279	45	83.9%
516		15	1	93.3%	280	28	90.0%	15	2	86.7%	279	125	55.2%
517		15	0	100.0%	288	8	97.2%	15	10	33.3%	284	118	58.5%
518	46	15	0	100.0%	288	35	87.8%	15	10	33.3%	286	193	32.5%
519		15	0	100.0%	280	9	96.8%	15	1	93.3%	278	64	77.0%
520		11	0	100.0%	161	24	85.1%	11	0	100.0%	158	9	94.3%
521	20	11	0	100.0%	199	7	96.5%	11	3	72.7%	199	26	86.9%
522		11	0	100.0%	199	36	81.9%	11	0	100.0%	196	18	90.8%
523		11	0	100.0%	199	6	97.0%	11	0	100.0%	198	22	88.9%
524		11	2	81.8%	199	13	93.5%	11	2	81.8%	197	22	88.8%
525		11	2	81.8%	197	14	92.9%	10	0	100.0%	193	13	93.3%
526		11	4	63.6%	173	33	80.9%	11	2	81.8%	170	14	91.8%
527		11	1	90.9%	199	10	95.0%	11	4	63.6%	198	36	81.8%
528		11	2	81.8%	199	17	91.5%	11	1	90.9%	198	30	84.8%
529	17	11	0	100.0%	199	11	94.5%	11	3	72.7%	198	53	73.2%
530		11	2	81.8%	153	16	89.5%	11	4	63.6%	153	30	80.4%
531		11	0	100.0%	173	12	93.1%	11	2	81.8%	173	13	92.5%
532	114	11	6	45.5%	199	49	75.4%	11	3	72.7%	198	30	84.8%
534	65	11	0	100.0%	158	24	84.8%	11	1	90.9%	156	16	89.7%
535		11	1	90.9%	186	24	87.1%	11	1	90.9%	181	21	88.4%
536		11	3	72.7%	199	52	73.9%	10	0	100.0%	195	37	81.0%
537		11	2	81.8%	170	20	88.2%	11	2	81.8%	165	18	89.1%
538		11	0	100.0%	199	23	88.4%	11	3	72.7%	198	40	79.8%
539		11	1	90.9%	153	21	86.3%	11	2	81.8%	153	66	56.9%
540	Cncld	10	3	70.0%	198	38	80.8%	9	0	100.0%	190	18	90.5%
541	Cncld	11	0	100.0%	198	21	89.4%	10	1	90.0%	192	34	82.3%
542		11	0	100.0%	198	21	89.4%	11	3	72.7%	196	35	82.1%
543	106	11	2	81.8%	199	21	89.4%	11	8	27.3%	199	58	70.9%
544		11	0	100.0%	197	20	89.8%	11	2	81.8%	194	17	91.2%
545	Cncld	11	2	81.8%	199	17	91.5%	10	1	90.0%	196	23	88.3%
547		11	1	90.9%	199	38	80.9%	11	1	90.9%	199	45	77.4%
548	Cncld	10	1	90.0%	194	21	89.2%	9	0	100.0%	192	14	92.7%
549	19	11	1	90.9%	194	26	86.6%	10	1	90.0%	186	17	90.9%
550	63	11	2	81.8%	153	16	89.5%	11	2	81.8%	153	33	78.4%
551		11	0	100.0%	195	19	90.3%	11	0	100.0%	187	17	90.9%
562		15	1	93.3%	280	22	92.1%	15	0	100.0%	277	29	89.5%
564		15	1	93.3%	280	18	93.6%	15	2	86.7%	272	32	88.2%
566		15	1	93.3%	278	18	93.5%	15	2	86.7%	275	34	87.6%
567		15	1	93.3%	165	9	94.5%	15	0	100.0%	163	6	96.3%
572	16	15	0	100.0%	275	22	92.0%	14	6	57.1%	269	71	73.6%
573		15	0	100.0%	278	40	85.6%	15	1	93.3%	271	45	83.4%
579		15	0	100.0%	165	8	95.2%	15	3	80.0%	160	29	81.9%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
580		15	0	100.0%	280	14	95.0%	15	2	86.7%	275	23	91.6%
581		15	2	86.7%	280	45	83.9%	15	3	80.0%	278	57	79.5%
584	Cncld	15	4	73.3%	164	21	87.2%	14	11	21.4%	159	93	41.5%
587	42	14	0	100.0%	274	15	94.5%	14	5	64.3%	265	43	83.8%
588	67	15	2	86.7%	165	14	91.5%	15	2	86.7%	164	24	85.4%
591	83	15	0	100.0%	279	18	93.5%	15	1	93.3%	273	30	89.0%
593	Cncld	15	4	73.3%	274	41	85.0%	14	1	92.9%	255	28	89.0%
595	26	15	3	80.0%	275	44	84.0%	15	3	80.0%	272	49	82.0%
600		10	0	100.0%	207	9	95.7%	10	2	80.0%	205	17	91.7%
601		10	5	50.0%	190	77	59.5%	10	1	90.0%	187	24	87.2%
605		10	7	30.0%	197	125	36.5%	10	2	80.0%	193	21	89.1%
607		10	4	60.0%	206	28	86.4%	10	3	70.0%	203	25	87.7%
609		10	1	90.0%	197	23	88.3%	10	3	70.0%	196	18	90.8%
622		8	1	87.5%	111	31	72.1%	8	0	100.0%	109	5	95.4%
626		10	2	80.0%	111	14	87.4%	10	1	90.0%	109	16	85.3%
639		9	1	88.9%	177	38	78.5%	9	0	100.0%	176	19	89.2%
640		10	0	100.0%	197	7	96.4%	10	2	80.0%	195	78	60.0%
641		10	4	60.0%	179	38	78.8%	10	1	90.0%	179	26	85.5%
642		10	0	100.0%	195	9	95.4%	10	3	70.0%	194	26	86.6%
643		10	1	90.0%	209	40	80.9%	10	1	90.0%	206	33	84.0%
644		10	0	100.0%	201	27	86.6%	10	3	70.0%	199	51	74.4%
645	20	10	2	80.0%	209	40	80.9%	9	5	44.4%	206	44	78.6%
646	28	10	4	60.0%	198	50	74.7%	10	6	40.0%	196	95	51.5%
647		10	1	90.0%	209	32	84.7%	10	3	70.0%	208	46	77.9%
648		10	2	80.0%	205	52	74.6%	10	2	80.0%	205	33	83.9%
649		10	4	60.0%	210	41	80.5%	10	1	90.0%	207	32	84.5%
650		10	0	100.0%	209	39	81.3%	10	2	80.0%	206	32	84.5%
651		10	0	100.0%	209	16	92.3%	10	3	70.0%	207	42	79.7%
652	15	10	1	90.0%	210	28	86.7%	10	3	70.0%	206	35	83.0%
653	15	10	2	80.0%	198	32	83.8%	10	3	70.0%	195	37	81.0%
654		10	3	70.0%	199	39	80.4%	9	0	100.0%	195	16	91.8%
655		10	2	80.0%	207	71	65.7%	10	3	70.0%	205	71	65.4%
656		10	0	100.0%	209	45	78.5%	10	4	60.0%	208	25	88.0%
657		10	1	90.0%	198	27	86.4%	10	1	90.0%	197	29	85.3%
658		10	0	100.0%	209	34	83.7%	10	1	90.0%	207	31	85.0%
680		11	2	81.8%	204	11	94.6%	11	1	90.9%	203	25	87.7%
681		11	1	90.9%	204	15	92.6%	11	6	45.5%	199	78	60.8%
682		11	0	100.0%	203	5	97.5%	11	3	72.7%	203	36	82.3%
683	59	11	0	100.0%	186	15	91.9%	11	9	18.2%	185	60	67.6%
684	11	11	4	63.6%	185	31	83.2%	11	4	63.6%	185	42	77.3%
685	17	11	3	72.7%	200	31	84.5%	11	7	36.4%	197	51	74.1%
686	17	11	3	72.7%	205	36	82.4%	11	6	45.5%	204	42	79.4%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
687		11	2	81.8%	204	32	84.3%	11	3	72.7%	203	34	83.3%
688		11	4	63.6%	203	13	93.6%	11	5	54.5%	202	35	82.7%
701		15	3	80.0%	220	24	89.1%	15	2	86.7%	217	22	89.9%
702	36	15	1	93.3%	287	32	88.9%	14	4	71.4%	284	64	77.5%
703		15	8	46.7%	288	85	70.5%	14	8	42.9%	286	78	72.7%
704	28	15	1	93.3%	219	33	84.9%	14	2	85.7%	213	40	81.2%
710		15	5	66.7%	288	74	74.3%	15	4	73.3%	284	77	72.9%
711		15	2	86.7%	279	30	89.2%	11	1	90.9%	258	46	82.2%
712	18	15	5	66.7%	285	76	73.3%	14	4	71.4%	276	91	67.0%
713	21	11	1	90.9%	157	15	90.4%	10	4	60.0%	143	60	58.0%
714	56	14	9	35.7%	169	67	60.4%	14	8	42.9%	157	66	58.0%
715	57	15	2	86.7%	287	60	79.1%	12	6	50.0%	265	131	50.6%
716		15	6	60.0%	288	113	60.8%	14	5	64.3%	282	107	62.1%
717	23	14	2	85.7%	273	64	76.6%	13	6	53.8%	254	76	70.1%
718		15	7	53.3%	288	143	50.3%	15	9	40.0%	286	100	65.0%
719	26	15	5	66.7%	288	93	67.7%	14	5	64.3%	273	77	71.8%
757	36	15	1	93.3%	73	4	94.5%	15	2	86.7%	72	6	91.7%
761		15	1	93.3%	284	12	95.8%	15	1	93.3%	281	35	87.5%
765		15	0	100.0%	284	24	91.5%	15	0	100.0%	284	36	87.3%
769		15	1	93.3%	284	26	90.8%	15	1	93.3%	278	50	82.0%
770		15	0	100.0%	284	21	92.6%	15	6	60.0%	282	80	71.6%
774		15	0	100.0%	284	16	94.4%	15	4	73.3%	283	60	78.8%
777		15	1	93.3%	169	10	94.1%	15	2	86.7%	168	36	78.6%
782	32	15	12	20.0%	169	68	59.8%	15	2	86.7%	164	17	89.6%
785	117	15	1	93.3%	284	18	93.7%	15	2	86.7%	284	48	83.1%
786	57	15	1	93.3%	73	17	76.7%	15	6	60.0%	72	33	54.2%
790	96	15	0	100.0%	284	26	90.8%	15	3	80.0%	281	35	87.5%
794	23	15	1	93.3%	284	32	88.7%	15	3	80.0%	281	58	79.4%
821	29	15	0	100.0%	282	6	97.9%	15	8	46.7%	282	111	60.6%
822	16	15	1	93.3%	284	15	94.7%	15	10	33.3%	282	128	54.6%
1333	29	15	2	86.7%	284	30	89.4%	15	5	66.7%	281	93	66.9%
1340		15	0	100.0%	283	5	98.2%	15	3	80.0%	283	45	84.1%
1689		8	0	100.0%	82	5	93.9%	8	1	87.5%	81	9	88.9%
2102		10	0	100.0%	56	12	78.6%	10	1	90.0%	55	5	90.9%
2103		10	2	80.0%	120	12	90.0%	10	0	100.0%	119	9	92.4%
2104	21	10	0	100.0%	146	9	93.8%	10	2	80.0%	144	12	91.7%
2107		10	3	70.0%	177	33	81.4%	10	0	100.0%	174	20	88.5%
2108	19	10	0	100.0%	177	25	85.9%	10	2	80.0%	171	19	88.9%
2109		10	0	100.0%	70	9	87.1%	10	0	100.0%	69	4	94.2%
2112	22	10	1	90.0%	17	3	82.4%	9	2	77.8%	15	2	86.7%
2113	16	10	2	80.0%	56	5	91.1%	10	1	90.0%	56	8	85.7%
2115	32	10	2	80.0%	56	7	87.5%	10	4	60.0%	55	8	85.5%

Amtrak On Time Performance

Trains Arriving Through: 7/15/2026

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2116	31	10	0	100.0%	17	0	100.0%	10	3	70.0%	17	5	70.6%
2118	34	10	2	80.0%	17	2	88.2%	10	5	50.0%	17	7	58.8%
2119	86	10	1	90.0%	17	3	82.4%	10	6	40.0%	17	7	58.8%
2120	67	10	5	50.0%	17	8	52.9%	9	5	44.4%	16	8	50.0%
2123	29	10	1	90.0%	55	7	87.3%	9	2	77.8%	54	15	72.2%
2124	69	10	7	30.0%	149	30	79.9%	10	7	30.0%	147	20	86.4%
2127	17	10	3	70.0%	17	4	76.5%	10	4	60.0%	16	4	75.0%
2128		10	2	80.0%	17	2	88.2%	10	1	90.0%	17	1	94.1%
2131		10	4	60.0%	17	4	76.5%	10	1	90.0%	17	1	94.1%
2150		10	0	100.0%	170	22	87.1%	10	3	70.0%	167	70	58.1%
2151		10	0	100.0%	119	6	95.0%	10	3	70.0%	117	32	72.6%
2155	33	10	2	80.0%	179	16	91.1%	10	4	60.0%	175	94	46.3%
2158	32	10	0	100.0%	17	2	88.2%	10	4	60.0%	17	4	76.5%
2159	64	10	1	90.0%	172	12	93.0%	10	7	30.0%	170	55	67.6%
2160	32	10	0	100.0%	17	0	100.0%	9	7	22.2%	16	11	31.3%
2162	27	10	2	80.0%	178	15	91.6%	10	4	60.0%	172	81	52.9%
2165	No OS	9	2	77.8%	16	2	87.5%	9	6	33.3%	16	8	50.0%
2171		10	0	100.0%	106	8	92.5%	10	3	70.0%	103	21	79.6%

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2104	NYP	21	SMW	15	DMW	8	PHL-XHM	AM	Held for or routed around MW work or equipment, Control Point, HOLMES, S/R 10/2 A/C BROKEN FROG
2108	NYP	19	WTR	13	WTR	13	XHM-XCY	AM	Heat order, Other, XHM-XCY
2112	NYP	22	WTR	30	WTR	11	XHM-XCY	AM	Heat order, Other, XHM-XCY
2113	WAS	16	POL	12	POL	12	XPV-BAL	AM	Removal of passenger by police, held a/c 185 stopped at Baltimore station for unruly passenger
2115	WAS	32	WTR	20	PTI	8	XCY-XHM	AM	Follow, AM125, Other, XCY-XH1
2116	NYP	31	WTR	20	CTI	9	NWK-NYP	AM	Follow, NJT, NJ6246, Other, SWIFT-NYP
2118	NYP	34	WTR	23	WTR	9	XHM-XCY	AM	Heat order, Other, XHM-XCY
2119	WAS	86	WTR	37	ENG	28	NYP-NYP	AM	Other electrical failure, 2153 NG NP, LATE F/SSYD A/C INSPECTING HOT CAR
2120	NYP	67	WTR	42	WTR	38	WAS-WAS	AM	Heat order, Other, X
2123	WAS	29	OTH	17	OTH	9	BAL-XNY	AM	Lost time - N.A.R., no train ahead
2124	NYP	69	WTR	61	WTR	61	WAS-WAS	AM	Heat order, Other, X
2127	WAS	17	WTR	16	WTR	13	XCY-XHM	AM	Heat order, Other, XCY-XHM
2155	WAS	33	OTH	21	CAR	9	WIL-WIL	AM	Door, 3661 NG NB, 3663 NG NB, 3663 NG NB
2158	BOS	32	WTR	25	WTR	11	XHM-XCY	AM	Heat order, Other, XHM-XCY
2159	WAS	64	WTR	45	DMW	15	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2160	BOS	32	WTR	18	DCS	14	NHV-XGX	AM	Issue with automatic road crossing protection, Milepost, NHV, XGX, Stop & protect MP 122.8 State ST.
2162	BOS	27	WTR	29	WTR	11	XHM-XCY	AM	Heat order, Other, XHM-XCY
2165	WAS	No OS Rpt							
85	WAS	32	WTR	28	OTH	6	PHL-WIL	AM	Lost time - N.A.R., PRT
86	BOS	24	CTI	40	CTI	11	WDB-ALX	CS	Follow VRE, 31015, Other, ALL
93	NFK	29	CTI	28	DCS	16	BRP-STM	MN	Signal issues at cp 241 stopped as per dispatcher request and waited for permission beyond the signal Control Point, 241
94	BOS	43	WTR	24	DSR	17	QAN-ALX	CS	Per bulletin Other, beltway, 10, 3-2
95	NFK	102	WTR	68	WTR	30	X3V-NFK	NS	Heat order Milepost, 22.2, 3.5

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
113	WAS	31	ENG	42	ENG	39	PHL-WIL	AM	Air / Brake, 651 EX ES
125	NPN	70	WTR	55	CTI	16	XVG-ALX	CS	Follow vre, 307, Milepost, 112.2, 105.1
131	WAS	23	WTR	38	WTR	11	NWK-NBK	AM	Heat order, Other, X94-NBK
134	NYP	39	WTR	16	OTH	7	WIL-PHL	AM	Lost time - N.A.R., PRT
138	NYP	91	SYS	84	SYS	81	NFK-X3V	NS	PTC-caused slow-down or penalty stop PTC enforce head before the time time started, Milepost, 70.0, 70.0
148	SPG	57	CAR	27	CAR	17	PHL-PHL	AM	Heat / AC, 82730 AX AS, MET WITH MECHANICAL A/C HOT CAR; COULD NOT BE FIXED
171	RNK	134	WTR	57	FTI	50	CLP-CVS	NS	Cross over or go around Milepost, 99.1, 102., 288, 274
182	NYP	18	WTR	15	WTR	15	XHM-EWR	AM	Heat order, Other, XHM-EWR
184	BOS	39	DCS	23	DCS	23	NHV-XGX	AM	Issue with automatic road crossing protection, Control Point, 122.8, Stop & protect /stop bypass track 2 /
185	WAS	33	POL	14	POL	14	BAL-BAL	AM	Removal of passenger by police
186	PHL	38	FTI	30	FTI	30	RVM-RVR	CS	Meet IO31, Other, cfp 3.3
197	WAS	25	ITI	11	ITI	11	NYP-NYP	AM	Service, turn, or wye train, 134, LATE TURN OFF AM134
474	SPG	22	CON	22	CON	17	NHV-NHV	AM	Hold for connecting train
478	SPG	18	PTI	23	PTI	10	WNL-SPG	AM	Follow, 148, Milepost w/Letters, WNL, SPG
494	GFD	115	ITI	99	ITI	99	NHV-NHV	AM	Service, turn, or wye train, 417, Late turn
53	SFA	177	ENG	110	ENG	54	XSE-XFL	CS	Undesired emergency application Main res struck diamond at a&r crossing mp a210.5, 317, 322
79	CLT	46	WTR	33	FTI	25	FBG-RVR	CS	Follow CSX I111, Control Point, Hamilton
80	NYP	32	WTR	29	WTR	13	RVR-FBG	CS	Heat order Other, RF&P Subdivision
645	HAR	20	WTR	15	WTR	11	NWK-TRE	AM	Heat order, Other, X94-TRE
646	NYP	28	SMW	7	WTR	6	PJC-NWK	AM	Heat order, Other, PJC-X94
652	NYP	15	DCS	12	DCS	6	LNC-PAR	AM	T.O.L, Control Point, PARK TO LEAMAN, TOL NO 2 TRK
653	HAR	15	WTR	11	DCS	6	NYP-NWK	AM	Signal suspension, Other, XLT-SWIFT, CONGESTION AHD AT NEWARK A/C SIGNAL FAILURE LANE TO SWIFT

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
19	NOL	113	FTI	154	FTI	138	HBG-PIC	NS	Meet Stopped at South Derby, waiting on UP8137/130 to clear the main...., UP8137/130, Milepost, 127.7, 131.7
20	NYP	32	WTR	87	WTR	28	CLP-MSS	NS	Heat order Milepost, 67.4, 32.6
683	POR	59	PTI	48	PTI	19	WEM-SAO	CS	Meet 686, Control Point, wells
684	BON	11	CON	10	CON	10	POR-POR	CS	Hold for bus with passengers from train Signal cutover
685	BRK	17	WTR	15	DCS	5	POR-FRE	CS	DTMF not working at Bo Street Control Point, bow st
686	BON	17	CON	9	CON	9	POR-POR	CS	Hold for thruway bus Waiting for bus bridge from Brunswick and Freeport due to signal cut over.
63	TWO	Trn Cancelled	FTI	15	FTI	10	AMS-UCA	CS	Follow csx, Milepost w/Letters, 215, uca
64	NYP	26	FTI	29	FTI	29	ROC-XSV	CS	Follow csx, Milepost, 346, 306
68	NYP	75	FTI	69	WTR	38	SLQ-RSP	CN	Heat order Milepost, 43, 0
233	ALB	42	CTI	18	PTI	15	CRT-POU	MN	Meet 280, Control Point, 39
237	ALB	18	PTI	12	PTI	12	HUD-ALB	AM	Meet ?, Control Point, 124
240	NYP	32	CTI	27	CTI	25	POU-CRT	MN	Meet mn, Control Point, 46
243	ALB	56	ENG	57	ENG	57	POU-POU	MN	Air / Brake 706
280	NYP	36	CTI	33	CTI	33	POU-CRT	MN	Meet Waited for 821 at cp46, before continuing through working limits, metro north, 821, Control Point, 46
281	NFL	22	CTI	32	CTI	22	CRT-POU	MN	Cross over or go around man, local, Control Point, 39
283	NFL	24	FTI	20	FTI	20	XSV-ROC	CS	Cross over or go around - Stop Signal @ CP 349 - Waiting for I168 to pass eastbound on track 2 - Crossover 1 to 2 @ CP 349 - Crossover 2 to 1 @ CP 362 around M626, CSX (multiple), Milepost w/Letters, CP 349, CP 362
284	NYP	20	FTI	46	FTI	24	BUF-ROC	CS	Follow csx, Milepost, 417, 373
290	NYP	49	CTI	46	CTI	43	POU-CRT	MN	Single tracking waited for 2 northbound trains 291 and mine train 837 Control Point, 46, mn, 837
291	BTN	86	CTI	40	FTI	40	SAR-FED	DH	Cross Traffic Control Point, CPC37, 228

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
43	PGH	72	WTR	55	WTR	27	LEW-HGD	NS	Heat order Milepost, 171.2, 191.2
74	RGH	11	FTI	22	FTI	17	CLT-KAN	NS	Follow #NS28R, Control Point, Junker, Control Point, Adams
77	CLT	56	DMW	73	DMW	73	CYN-DNC	NS	Waiting for MW clearance Control Point, Sullivan
78	RGH	26	ITI	32	ITI	32	CLT-CLT	NS	Service, turn, or wye train 77
89	SAV	51	WTR	43	DMW	20	ALX-XDJ	CS	Held for or routed around MW work or equipment Control Point, Beltway
90	NYP	96	DMW	44	DMW	37	RMT-PTB	CS	Held for or routed around MW work or equipment Control Point, Gary
97	MIA	70	CTI	57	CTI	21	DLD-WPK	FR	Meet Stopped T2 holding, Sunrail, 316, Control Point, Blue Springs
98	NYP	39	PTI	90	PTI	28	XDJ-ALX	CS	Follow Followed VRE into DC, E345, Milepost, 59, 105
40	CHI	454	SVS	234	SVS	195	SAV-SAV	CS	Due to a speed sensor being damaged on lead engine 336 from the vehicle strike earlier near Lakeland, FL., Sav mech was not able to complete the routine inspection so we had to flat switch the engines. But first this all had to be ok'ed by upper management
41	MIA	140	FTI	88	FTI	47	XFI-COV	CS	Blocked from station track I135, Milepost, 272.5, 272.5
23	NOL	46	PTI	40	PTI	40	BAS-XNO	CS	Meet 24, Siding, Nicholson
26	MOE	118	FTI	132	FTI	78	XNO-BAS	CS	Follow 606, Milepost w/Letters, north gintilly, bas
5	EMY	160	WTR	123	POL	34	ELK-ELK	UP	Removal of passenger by EMS
521	SJC	20	FTI	30	FTI	22	HAY-FMT	UP	Meet UP 8714 South, Control Point, F030
529	SJC	17	FTI	12	FTI	10	HAY-FMT	UP	Cross Traffic UP7455north, Control Point, NI021
532	SAC	114	POL	122	POL	122	MTZ-MTZ	UP	Fire department hold Fire ahead RMCC Hold
534	SAC	65	POL	61	POL	58	MTZ-MTZ	UP	Fire department hold Fire near tracks at MP 35.7
540	SAC	Trn Cancelled							
541	OKJ	Trn Cancelled	TRS	2	TRS	2	DAV-DAV	UP	Unticketed or fare evading passenger Milepost, 75.4, 75.4
543	SJC	106	POL	101	POL	43	MTZ-RIC	UP	Fire department hold 14.9 MTZ sub

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
545	OKJ	Trn Cancelled							
548	SAC	Trn Cancelled							
549	OKJ	19	TEN	22	TEN	22	SUI-MTZ	UP	Loading problem Ground relay faults/lost load, 2005
550	SAC	63	ITI	44	ITI	44	SJC-SJC	UP	Service, turn, or wye train 543
50	NYP	180	WTR	73	PTI	33	STA-CVS	BB	Meet amtk 51, Control Point, Ivy
507	EUG	26	PTI	19	PTI	19	PDX-ORC	UP	Meet AMT508, Siding, Clackamas
509	PDX	26	INJ	25	INJ	25	CTL-CTL	BN	Injured or sick passenger PAX unwell and was transported to hospital
518	VAC	46	MBO	27	MBO	27	X8B-XF2	BN	For maritime traffic Bridge, Fraser River
59	NOL	121	DSR	91	RTE	37	MEM-MKS	CC	Routed through MEM A yard lined multiple switches 5 switches. Other, MEM A yard
7	SEA	110	FTI	161	FTI	50	WTN-WPT	BN	Meet bn 7741, 6244, Siding, blair
8	CHI	269	FTI	161	ITI	77	SEA-SEA	BN	Service, turn, or wye train 7
27	PDX	-11	CON	132	CON	132	SPK-SPK	BN	Late arrival of 7 into SPK
821	FTW	29	DSR	36	DSR	26	GLE-FTW	BN	Per bulletin Milepost, 408.5, 408.1, 60, main, Milepost, 408, 407.7, 30, main, Milepost, 407.4, 407, 30, main, Milepost, 405.8, 405.6, 30, main, Milepost, 405.3, 404.9, 50, main, Milepost, 403.2, 402.7, 75, main, Milepost, 401, 400.2, 25, main, Milepost, 397.5, 397.3, 50, main, Milepost, 397.5, 397.
822	OKC	16	DSR	32	DSR	26	FTW-GLE	BN	Per bulletin Milepost, 350.3, 350.4, 30, X OVER, Milepost, 355.5, 355.9, 29, 1, Milepost, 360.6, 361.3, 30, M, Milepost, 364.7, 365.1, 30, 1, Milepost, 383.4, 383.6, 30, M, Milepost, 385.3, 385.5, 30, M, Milepost, 389, 389.7, 25, M, Milepost, 396.2, 396.3, 30, M, Milepost, 400.2, 401, 25, M, Milepos
331	MKE	21	CAR	16	CAR	16	XRO-SVT	CP	Air / Brake / Wheel ID4010, ID4123, Broke brake hoses between cars going through Rondout tower crossovers 1-2, lost power on two cars 4204 & 4010, did a quick check to restore power
332	CHI	59	ENG	47	ENG	47	MKE-MKE	CP	Loading problem Couldn't get a load, had to troubleshoot with CNOC, 14
339	MKE	18	CTI	18	CTI	8	GLN-XRO	CP	Follow Following Metra 2139 to Rondout, Metra, 2139, Control Point, Tower A20

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
350	PNT	35	DSR	39	PTI	16	DOA-KAL	AM	Meet AMTK 351, Siding, GLENWOOD
355	CHI	34	PTI	55	PTI	55	DER-ARB	MI	Meet Scheduled meet is at CP 52. NS B25 in the Chelsea siding. Unable to make meet there., AMT 352, Control Point, 28
365	CHI	30	DSR	31	DSR	18	LNS-BTL	CC	Per bulletin Milepost, 223.53, 223.53, 25, main two, Milepost, 219.15, 219.15, 25, main, Milepost, 219, 218.5, 30, main, Milepost, 215.61, 214.97, 25, main two, Milepost, 210.40, 210.40, 30, main, Milepost, 202.45, 199.85, 28, main, Milepost, 221.42, 221.42, 30, main
370	GRR	45	DCS	24	SVS	19	CHI-XTF	AM	Unplanned Wye Other, CUS
572	SAN	16	CTI	9	CTI	9	OSD-SOL	SN	Meet NCTD, 633, Control Point, ponto
584	SAN	Trn Cancelled							
587	LAX	42	CTI	35	CTI	29	OSD-X98	SC	Meet metrolink, Control Point, songs
588	SAN	67	PTI	50	PTI	49	SNC-SNP	SC	Meet 591, Siding, Capistrano
591	LAX	83	PTI	51	PTI	51	OSD-X98	SN	Meet 786, Control Point, songs
593	LAX	Trn Cancelled							
595	LAX	26	PTI	26	PTI	24	OSD-X98	SN	Meet 790, Control Point, song
757	SLO	36	ENG	24	ENG	24	LPS-LPS	UP	Failure of diesel engine Computer message Major Engine Fault. Engineer was able to reset and restart., C2121
782	SAN	32	PTI	30	PTI	17	SNC-SNP	SC	Meet 785, Control Point, serra
785	GTA	117	POL	123	POL	112	CML-CML	UP	Right of Way police hold Held at Camarillo due to a person threatening to jump off a bridge at mile post 404.
786	SAN	57	DCS	58	DCS	29	SNP-X98	SC	Restrictive signal(s) from known wayside signal failure Flagging two blocks. Restricted speed from Pier to SONGS., STOP, Control Point, Pier
790	SAN	96	POL	61	POL	61	OSD-SOL	SN	Right of Way police hold
794	SAN	23	POL	44	POL	44	VEC-VEC	UP	Removal of passenger by police Sydney Traub Res# 91CC5C VEC to VNC. Run away 15 year old, parent track her at the VEC station. Parents were at the scene and Didn't want the child to travel. Hid in the Cafe car till APD arrived . APD Connor assisted at VEC station.

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
702	BFD	36	FTI	22	FTI	14	FNO-HNF	BN	Meet BNSF 6680, Siding, E. Conejo
704	BFD	28	PTI	31	FTI	23	WAC-BFD	BN	Blocked from station track bnsf 8178, Control Point, gomez
712	BFD	18	PTI	18	PTI	9	MCD-MDR	BN	Meet AMT715, Siding, LEGRAND
713	OKJ	21	PTI	24	PTI	17	TRK-MOD	BN	Meet Shuffled with 712 at E Empire Flagged into track 2 behind BNSF 7414, 712, Control Point, E Modesto Empire
714	BFD	56	PTI	33	DCS	17	FNO-HNF	BN	Restrictive signal(s) from known wayside signal failure Flagging instructions per Bakersfield DS, STOP, Control Point, Anderson
715	OKJ	57	PTI	44	PTI	17	TRK-MOD	BN	Meet 714, Control Point, Denair
717	OKJ	23	PTI	26	PTI	18	FNO-MDR	BN	Meet 714, Control Point, madera
719	OKJ	26	DCS	28	DCS	21	HNF-FNO	BN	Restrictive signal(s) from unknown cause DS Flag pass Stop at West Conejo; intermediate did no favors; issue appears to be at Anderson., Stop, Control Point, West Conejo
1	LAX	125	FTI	156	DBS	100	XEA-XFA	UP	Debris blocking track (no debris strike) Control Point, SA101
21	SAS	No OS Rpt	ENG	267	ENG	267	ARK-HOP	UP	PTC - On Board Cab Signal or PTC Failure PTC screen blank on Engr side. Also brakes in penalty on Eng 311. Swap out lead unit 311 with63. Issue with HEP cables(too short) for 311, used a jumper cable and short looped on Engr side. Also dealing with frt train traffic as disp needed to run trains, 311
22	CHI	58	FTI	72	DSR	46	PBF-ACD	UP	Per bulletin Milepost, 122.39, 121.85, 15, MT, Milepost, 110, 105.25, 10, MT, Milepost, 105.25, 95, 15, MT
302	CHI	28	CAR	36	CAR	36	BNL-PON	UP	Air / Brake / Wheel ID4128
307	STL	17	ENG	20	ENG	18	CHI-XTF	AM	Retest XITCS ID4608
381	GBB	17	DCS	8	DCS	8	NPV-PLO	BN	Restrictive signal(s) from unknown cause Talked by signal. Restricted speed, Stop, Control Point, Aurora
382	CHI	22	SYS	19	SYS	19	GBB-GBB	BN	Late bulletins due to Amtrak cause Train make up not entered with BNSF. Unable to obtain orders in wst QCY. Per RFE Fertig-pick up orders in GBB
383	QCY	21	RTE	13	RTE	10	GBB-MAC	BN	Dispatcher hold Control Point, Saluda
390	CHI	20	DSR	22	FTI	10	CEN-EFG	CC	Cross Traffic up 4601 w, Control Point, kinmundy

Amtrak Endpoint OTP Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
393	CDL	19	DSR	25	WTR	6	HMW-KKI	CC	Heat order High temp restriction 64mph, Milepost, 23.5, 55.5	
316	STL	73	POL	36	POL	36	WAH-KWD	UP	Right of Way police hold Water rescue ahead	
319	KCY	131	PTI	71	ENG	40	CHI-CHI	AM	IDTX 4611 B/O which caused a set swap with Amtk 319 in which 2 extra cars were added for axle count .Waited for Chi mechanical to complete their inspections in union station. IDTX 4611	
1333	MSP	29	ENG	26	ENG	23	WDL-TOH	CP	Traction motor Warning light for Traction Motor Suspension Bearing. inspected axels and found no defects 2nd Engineer riding in rear unit.Proceeded for 10 miles @ 50 mph per CNOC/Mechanical with no further defects, 14	

Amtrak Initial Terminal Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/15/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	07/14	8	8	Mix up with passenger that had tickets exchanged and no room on #4920. Boarded train a day early
BOS	2165	07/15	(No OS)		
CLT	78	07/15	32	32	Service, turn, or wye train 77
HAR	646	07/15	3	3	Door, 43379 AX MF
HAR	652	07/15	1		
NHV	474	07/15	22	17	Hold for connecting train
NHV	474	07/15	22	5	Hold for connecting train
NHV	474	07/15	22	5	Hold for connecting train
NHV	474	07/15	22	17	Hold for connecting train
NHV	494	07/15	115	2	Late bulletins due to Amtrak cause, Reissuing paperwork
NHV	494	07/15	115	14	Routine inspections, Inspecting train and reissuing paperwork
NHV	494	07/15	115	99	Service, turn, or wye train, 417, Late turn
NYP	63	07/15	5	5	Air / Brake, 715 DX DM, LATE F/SSYD A/C BRAKE ISSUE ON ENG.715
NYP	129	07/15	2	2	Passenger and/or baggage, BOARDING
NYP	185	07/15	3	3	Passenger and/or baggage, BOARDING
NYP	197	07/15	11	11	Service, turn, or wye train, 134, LATE TURN OFF AM134
NYP	245	07/15	65	20	Service, turn, or wye train, 68, LATE TURN OF AM68
NYP	245	07/15	65	45	Unrecoverable penalty (PCS), 704 DX DM
NYP	291	07/15	15	15	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	641	07/15	5	5	Passenger and/or baggage, BOARDING
NYP	2107	07/15	3	3	Passenger and/or baggage, BOARDING
NYP	2119	07/15	28	28	Other electrical failure, 2153 NG NP, LATE F/SSYD A/C INSPECTING HOT CAR
PHL	601	07/15	2	2	PTC - Stop Bypass Permission Required, Control Point, .
PHL	605	07/15	3	3	PTC - Stop Bypass Permission Required, Control Point, .
POR	684	07/15	10	10	Hold for bus with passengers from train Signal cutover
POR	686	07/15	9	9	Hold for thruway bus Waiting for bus bridge from Brunswick and Freeport due to signal cut over.
POR	688	07/15	12	12	Service, turn, or wye train 688, Bus stuck in traffic
SFA	52	07/15	53	53	Service, turn, or wye train 53, Inbound Train 53 incurred Delays Arriving. Also Crew was Set Back an Hour

Amtrak Initial Terminal Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/15/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	148	07/15	6	6	Delay in Block, CNDR HELD OFF ON BOARDING DUE TO HOT CAR. MECHANICAL AND TM OK'D OUT.
WAS	184	07/15	7	7	Passenger and/or baggage, LATE PASSENGER CAME DOWN AFTER GATES CLOSED NEEDING LIFT ASSISTANCE
WAS	2120	07/15	38	38	Heat order, Other, X
WAS	2124	07/15	61	61	Heat order, Other, X
WAS	2128	07/15	16	16	Heat order, Other, x
WAS	2162	07/15	2	2	Removal of passenger by police, ASSISTANCE NEEDED TO TURN AWAY 178 PASSENGERS AFTER GATES CLOSED
CHI	3	07/15	65	65	Heat / AC 39014, B/O dorm for HVAC + late makeup of engines
CHI	5	07/15	15	15	Planned set out / pick out of locomotives, cars or section of train Control Point, CUS
CHI	7	07/15	41	41	Heat / AC 38068, Plus back the train into track 30 for water the diner on a cold car hmmm
CHI	41	07/15	459		
CHI	319	07/15	40	40	IDTX 4611 B/O which caused a set swap with Amtk 319 in which 2 extra cars were added for axle count .Waited for Chi mechanical to complete their inspections in union station. IDTX 4611
CHI	339	07/15	7	7	Electrical failure ID4010, Car 4010 had no power, AC, HEP. Mechanical came out to track 17 to reset the car. No luck until the second try.
CHI	354	07/15	18	18	HEP ID4608
GBB	382	07/15	19	19	Late bulletins due to Amtrak cause Train make up not entered with BNSF. Unable to obtain orders in wst QCY. Per RFE Fertig- pick up orders in GBB
MKE	332	07/15	47	47	Loading problem Couldn't get a load, had to troubleshoot with CNOC, 14
MKE	338	07/15	4	4	Electrical failure ID4010, Car 4010 lost all power while loading in MKE, reset breakers underneath car with no result. Manual closed all side doors and locked doors out. No power, HEP, A/C in car 4010
BFD	703	07/15	4	4	Service, turn, or wye train 712
GTA	782	07/15	6	4	Meet 14, Control Point, S. Ellwood
GTA	782	07/15	6	2	Group Summer camp group of 100 students.
LAX	584	07/15 (Trn Cxld)			Engine Issue
OKJ	540	07/15 (Trn Cxld)			Right of Way Encroachment
OKJ	548	07/15 (Trn Cxld)			Right of Way Encroachment
OKJ	714	07/15	16	8	Loading problem Door trainline circuit, C2013
OKJ	714	07/15	16	8	Door C8312, End door vestibule door would not close.

Amtrak Initial Terminal Details

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/15/2026

Terminal	Train	Date	Late	Delay	Cause
PDX	28	07/15	7	7	Heat / AC 34029, 31021, Both cars hot, no air conditioning.
SAC	545	07/15	(Trn Cxld)		Right of Way Encroachment
SAN	593	07/15	(Trn Cxld)		Engine Issue
SEA	8	07/15	54	54	Service, turn, or wye train 007
SJC	528	07/15	7	7	Meet Caltrain, North & South, Other, SJC Station
SJC	550	07/15	44	44	Service, turn, or wye train 543
SPK	27	07/13	139	7	Person pulling emergency cord Pax's Mike and Esther Staley pulled the emergency brake in car 2715 because he decided he was too claustrophobic to take his trip and was mad that the upstairs coach area was not bigger. Not sure why he waited until the doors closed and we departed.
SPK	27	07/13	139	132	Late arrival of 7 into SPK

Eastern Region

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	98.4	94.8	342	1
CDOT	95.0	85.0	83.8	92.4	20	3
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	86.4	90.5	88.6	352	48
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 49(15) West of Syracuse, NY - Freight Train Interference

16JUL26: Train 49(15) operating with engines 374, 108, 129, 10 cars, and 152 customers onboard was delayed 6 miles west of Syracuse, NY on the CSX Rochester subdivision following CSX freight traffic to Rochester, NY which is approximately 71 miles.

Train	Delay	Comment
49 (15)	41"	

Train 245(15) New York, NY - Engine Failure

16JUL26: Train 245(15) operating with engine 704, 5 cars, engine 101, and 141 customers was delayed departing New York, NY due to 480v train line issues. Mechanical was on scene to resolve the issue. The crew performed a brake test and loaded the customers to depart the station.

Train	Delay	Comment
245 (15)	1'05"	

Train 243(15) Poughkeepsie, NY - Engine Failure

15JUL26: Train 243(15) operating with engine 131, 5 cars, engine 706, and 175 customers onboard was delayed departing Poughkeepsie, NY due to a damaged valve on rear engine 706. Metro North mechanical was able to repair the valve on scene. Headend power was dropped at 11:10 p.m. during the repair time and the temperature was 73 degrees and slightly raining. Headend power was brought back up at 11:40 p.m. and once a brake test was performed, train 243(15) departed Poughkeepsie.

Train	Delay	Comment
243 (15)	57"	

Train 171(15) North of Charlottesville, VA - Freight Train Interference

16JUL26: Train 171(15) operating with engine 37, 9 cars, and 230 customers onboard was delayed 11 miles north of Charlottesville, VA on the Norfolk Southern Washington District holding at milepost 101.8 to go around NS-102, NS-288, and NS-274.

Train 494(15) New Haven, CT - Hold for Connection

15JUL26: Train 494(15) operating with engine 115, 2 engine 95, and 63 customers onboard was delayed departing New Haven, CT due to late inbound 94(15) with 43 connections onboard. Additionally, mechanical had to reinspect both engines to ensure the paperwork did not expire at midnight and en route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
494(15)	1'55"	

Train 63(15) Niagara Falls, ON - Engine Failure

15JUL26: Train 63(15) operating with engine 99, 5 cars, and 39 customers onboard was terminated at Niagara Fall, ON due to a bad order air compressor on engine 99. All customers were accommodated to buses from Niagara Falls, ON to Toronto, ON. Train 64(16) originates in Niagara Fall, ON with buses provided from Toronto, ON by VIA rail. Rescue engine 132 was sent from Niagara Falls, NY to cap the equipment to ensure service from Niagara Fall, ON to New York, NY.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
63(15)		TERM NFS
64(16)		ORIG NFS

Train 186(15) North of Richmond Main Street, VA - Freight Train Interference

15JUL26: Train 186(15) operating with engine 182, 5 cars, and 138 customers onboard was delayed starting 1.4 miles north of Richmond Main Street, VA on the CSX RFP subdivision meeting IO31-15 at Dumbarton milepost 3.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
186(15)	30"	

Train 68(15) Fort Edward, NY - Freight Train Interference

15JUL26: Train 68(15) operating with engine 101, 5 cars, engine 704, and 80 customers onboard was delayed departing Fort Edward, NY on the CPKC Canadian subdivision due to CN 228 in emergency ahead on the station. Train 68(15) lost additional time following the freight from milepost 55.5 to milepost 37.1. Train 291(15) was delayed departing Saratoga Springs, NY meeting cross traffic involving CN 228 and 68(15).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(15)	30"	Follow Freight
68(15)	37"	Hold FED
291(15)	40"	Hold SAR

Train 90(15) South of Petersburg, VA - M of W Work

15JUL26: Train 90(15) operating with engine 330, 7 cars, and 186 customers onboard was delayed 50 miles south of Petersburg, VA on the CSX North End subdivision holding for maintenance of way work at Gary milepost 78.7.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
90(15)	37"	

Train 50(14) West of Charlottesville, VA - Passenger Train Interference

15JUL26: Train 50(14) 26-FOT-00803 00000008329 engine UNCLASSIFIED 1345 cat 7/21/2028 and 131 customers onboard was delayed 7 miles west of Charlottesville, VA on the Buckingham Branch North Mountain subdivision meeting train 51(15) at Ivy milepost 189.1.

Train	Delay	Comment
50 (14)	33"	

Train 138(15) South of Petersburg, VA - System

15JUL26: Train 138(15) operating with engine 83, 9 cars, and 94 customers onboard was delayed 13 miles south of Petersburg, VA on the Norfolk Southern Norfolk District holding at milepost 70.2 due to a penalty stop from PTC enforcement.

Train	Delay	Comment
138 (15)	1 '21"	

Train 77(15) East of Durham, NC - M of W Work

15JUL26: Train 77(15) operating with locomotives NC1810-NC1984, 4 cars and 73 customers onboard was delayed 5 miles east of Durham Station at MP 59.2 on the NS Goldsboro-Greensboro division due to NS maintenance of way clearance.

Train	Delay	Comment
77 (15)	1 '13"	

Train 68(15) St-Lambert, QC - Weather

15JUL26: Train 68(15) operating with locomotive 101, 5 cars, and 67 customers was delayed on the CN Rouses Point subdivision for heat orders between St. Lambert and Rouses Point.

Train	Delay	Comment
68 (15)	38"	

CSX RF&P Subdivision - Heat Kink

15JUL26: CSX reported a heat kink track defect 7 miles south of Washington between Slaters Interlocking and the South End of AF Interlocking. Tracks No.2 and No.3 were taken out of service for repair leaving only a single-track open route. Trains operating through the affected area took significant delays holding for an open route meeting freight trains, commuter trains and Amtrak passenger trains.

Train	Delay	Comment
41 (14)	35"	
95 (14)	15"	
178 (15)	45"	
171 (15)	30"	
125 (14)	16"	

Train 2119(15) New York, NY - Engine Failure

15JUL26: Next Gen Acc 28-FCI-00603 00000008329 UNCLASSIFIED 7/21/2026
Train 2119(15) operating with TS 25 was delayed at the initial terminal of NYP due to HSR Mechanical needing to respond to a reported hot PC 2153 and ditch light failure. HSR Mechanical was required to de-prepare and re-prepare the trainset twice to get the HVAC to return to functioning status. After the second recycle train 2119(15) was able to depart.

As a result of the late operation of train 2119(15), train 2124(15) had an initial terminal delay off the turn of the equipment.

Train	Delay	Comment
2119(15)	28"	Initial Terminal Delay
2124(15)	1'01"	Initial Terminal Delay

NYP Line - Broken Frog- M of W Work

15JUL26: Multiple trains were delayed at Holmes Interlocking on the NYP Line due to a broken frog on the No.2 tracks requiring a 10mph restriction until repaired.

Train	Delay	Comment
86(15)	08"	
182(15)	05"	
643(15)	03"	
644(15)	03"	
646(15)	03"	
2104(15)	14"	
2108(15)	04"	
174(15)	04"	
56(15)	05"	

Train 53(14) Jacksonville, FL - Engine Failure

15JUL26: train 53(14) operating with locomotives 322-317, 16 passenger cars, 22 auto carriers and 366 customers was delayed at Jacksonville due to making an unscheduled stop to fuel locomotive 322 resulting from locomotive 317 operating isolated for HEP failure and a higher than average fuel consumption rate operating with a single diesel supplying both tractive effort and HEP.

Due to the late operation of 53(14) train 52(15) had an initial terminal delay at Sanford off the equipment turn from 53(14).

Train	Delay	Comment
53(14)	40"	
52(15)	53"	Initial Terminal Delay

Train 113(15) South of Philadelphia, PA - Engine Failure

15JUL26: Train 113(15) operating with locomotives 651-622, 9 cars and 396 customers onboard was delayed 6 miles south of Philadelphia at MP 6 on the PW Line due to a main res air leak on between car 82791 and locomotive 620. The crew was able to identify and isolate the air leak with the assistance of CNOC Mechanical and an Amtrak Trainmaster. After the air leak was isolated, the train was able to rebuild the appropriate amount of air and proceed.

Train	Delay	Comment
113(15)	35"	
51(15)	02"	

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008329 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00893 a 00000008329 in "UNCLASSIFIED" open 7/21/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train 790(15) West of Solana Beach, CA - Police Related

16JUL26: Train 790(15) was delayed at Encinitas /MP 237.8 on the SCRRA- NCTD San Diego Subdivision, 4 miles west of Solana Beach, CA due to a police hold on all tracks due to a reported trespasser near or on the tracks ahead. Once hold was released, Train 790(15) was able to proceed.

Train	Delay	Comment
790 (15)	1'01"	

Train 26(15) Pascagoula, MS - Freight Train Interference

16JUL26: Train 26(15) was delayed upon departing Pascagoula, MS station on the CSX NO and M subdivision following freight train 606. Train 26(15) was able to get around the freight at MP674.5 and resumed operating at track speed.

Train	Delay	Comment
26 (15)	54"	

Train 316(15) West of Kirkwood, MO - Police Related

16JUL26: Train 316(15) was delayed holding at MP32.7, 19.03 miles west of Kirkwood, MO station on the UPRR Jefferson City subdivision due to hold on the tracks for water rescue. The tracks were released and train 316(15) was back on the move at 1009PM CT.

Train	Delay	Comment
316 (15)	36"	

Train 8/28(14) West of Glasgow, MT - Freight Train Interference

16JUL26: Train 8/28(14) was delayed at Tampico / MP 288.0 on the Burlington Northern Santa Fe Milk River Subdivision, 10 miles west of the Glasgow, MT station, meeting two BNSF freight trains (BNSF 5320 and BNSF 7739). Train was further delayed at Oswego / MP239.9 on the BNSF Glasgow Subdivision meeting BNSF 7360 and BNSF 8759.

Train	Delay	Comment
8/28 (14)	33"	Tampico
8/28 (14)	32"	Oswego

Train 20(15) South of Atlanta, GA - Freight Train Interference

16JUL26: Train 20(15) was delayed holding at MP684.6, 51.3 miles south of Atlanta, GA station on the Norfolk Southern East End subdivision meeting Norfolk Southern freight trains 346 and 153. Train 20(15) was back on the move at 851PM CT after reversing out of the siding once Norfolk Southern Freight 153 cleared to the south.

Train	Delay	Comment
20 (15)	39"	

Train 785(15) Camarillo, CA - Police Related

16JUL26: Train 785(15) was delayed departing Camarillo, CA/ MP413.1 on the UPRR Santa Barbara Subdivision due to a police hold on the tracks account of a reported trespasser on the bridge at MP404. Once the trespasser was clear and the hold released, Train 785(15) departed the station.

Train	Delay	Comment
785 (15)	1'48"	

Train 8(15) Seattle, WA - Initial Terminal Delay

16JUL26: Train 8(15) was delayed departing Seattle on the BNSF Scenic subdivision due to servicing the late turn of equipment from train 7(13) that arrived Seattle at 119PM-PT, 1 hour, and 50 minutes late. Once the equipment was turned, serviced, and set in the station, the customers were welcomed aboard and 8(15) departed Seattle at 549PM-PT, 54 minutes late.

Train	Delay	Comment
8 (15)	54"	

Train 354(15) Albion, MI - Engine Failure

16JUL26: Train 354(15) with engine ID4608, 5 cars and 220 customers lost HEP due to a gas pressure fault coming into Albion MI station/MP95.8 on the Amtrak Michigan Line. Crew worked with CNOC mechanical and were able to get the engine restarted with HEP restored. Due to the nature of the fault train 354(15) was terminated at Albion MI station with five alternate buses secured to accommodate passengers Albion MI to Pontiac MI. Road Foreman arrived on scene at 109AM ET. Bus one operated from Albion MI to Ann Arbor MI, bus two operated from Albion MI to Jackson MI and Ann Arbor MI, bus three operated from Albion MI to Dearborn and Pontiac MI, bus four operated from Albion MI to Detroit MI, bus five operated from Albion MI making all stops. All buses departed Albion MI station at 246AM ET.

Train 353(16) was cancelled in it's entirety with six supplement buses secured to accommodate passengers. Bus one operated from Detroit MI to Chicago IL, bus two operated from Ann Arbor MI to Chicago IL, bus three operated from Dearborn MI to Chicago IL, bus four operated from Royal Oak MI. to Detroit, MI, Ann Arbor, MI Jackson MI, Battle Creek, MI, Niles MI, New Buffalo MI and Chicago IL, bus five operated from Troy MI to Kalamazoo, MI and Chicago IL, bus six operated from Pontiac MI and made all stops.

Train	Delay	Comment
354 (15)	Term ALI	
353 (16)	Cancelled	

Metrolink Orange Subdivision Signal Issues - San Clemente Pier, CA

16JUL26: Multiple trains were delayed by ~~26-FOT-00603~~ ~~00000008329~~ ~~UNCLASSIFIED~~ San Clemente Pier, CA/ MP204.8 on the Metrolink Orange Subdivision and Songs/ MP 209.16, due to signal issues. The crews were delayed flagging, hand-throwing switches, and operating at reduced speeds as a result of the signal problems, and further delayed throughout the area account of congestion related delays caused by this.

Train	Delay	Comment
587(15)	15"	
587(15)	50"	Congestion delays
588(15)	49"	Congestion delays
588(15)	32"	
591(15)	26"	
591(15)	51"	Congestion delays
790(15)	46"	
595(15)	32"	
786(15)	44"	
785(15)	23"	
782(11)	35"	
580(15)	25"	

Train 1(15) East of Houston, TX - Freight Train Interference

15JUL26: Train 1(15) was delayed holding at MP319.4, 45.2 miles east of Houston TX on the UPRR Houston subdivision due to UPRR Freight 6955 stopped ahead after losing it's lead power unit. CP 8773W arrived and assist UPRR Freight 6955 into the siding. The CP freight ran a red signal while shoving UP 6955 to clear a route and needed to be relieved. A UPRR Freight crew arrived on scene to relieve the crew and finished shoving the train to clear a route for 1(15). Train 1(15) was back on the move at 739PM CT. Train 1(15) continued to be delayed following CP8773 until MP327.

Train	Delay	Comment
1(15)	2'00"	
1(15)	1'07"	Follow CP8773

Train 19(14) North of Picayune, MS - Freight Train Interference

15JUL26: Train 19(14) was delayed holding at MP131.9, 17.1 miles north of Picayune MS station on the Norfolk Southern NO and NE subdivision due to UP8137 stopped ahead with mechanical issues. Freight crew determined the car needed to be set out and advanced to the siding. UP8137 crew arrived to the siding to set out the car but the siding was locked out by maintenance. Maintenance arrived on scene and unlocked the siding for UP8137. Train 19(14) was back on the move at 915PM CT once UPRR freight 8137 cleared into the siding.

Train	Delay	Comment
19(14)	2'18"	

Train 26(25) South of Gulfport, MS - Signal

15JUL26: Train 26(25) was delayed holding at MP753, 13.31 miles south of Gulfport MS station on the CSX NO and M subdivision due to the Bay St. Louis Drawbridge being stuck open. Train 26(25) was back on the move at 829PM CT after the bridge was seated and they received the signal.

Train	Delay	Comment
26(25)	38"	

Train 26(15) South of Bay Saint Louis, MS - Freight Train Interference

15JUL26: Train 26(15) was delayed holding at MP799.7, 15.05 miles south of Bay Saint Louis, MO station on the CSX NO and M subdivision following freight train 606.

Train	Delay	Comment
26(15)	1'18"	

Train 584(15) Cancelled at Los Angeles, CA - Engine Failure

15JUL26: Train 584(15) was cancelled in entirety out of Los Angeles, CA/ MP0.0 on the SCRRA-Metrolink River Subdivision due to AC failure on engine E/C2118. As a result, the turn of equipment Train 593(15) was also cancelled in entirety. All affected passengers were re-accommodated on the next available trains, 786(15) and 595(15).

Train	Delay	Comment
584(15)	Cancelled	
593(15)	Cancelled	

Train 355(15) East of Ann Arbor, MI - Passenger Train Interference

15JUL26: Train 355(15) was delayed holding at MP27.9, 11.4 miles east of Ann Arbor MI station on the Amtrak Michigan line meeting Amtrak train 352(15). Train 355(15) was back on the move at 755PM ET after train 352(15) cleared to the east.

Train	Delay	Comment
355(15)	55"	

Train 532(15) Martinez, CA - Fire Near Tracks

15JUL26: Train 532(15) with engine CDTX 6963, 3 cars, CDTX 2005, and 52 customers onboard was delayed at Martinez, CA on the BNSF Martinez subdivision due to a fire reported near the tracks at milepost 35.7, affecting No.1 track. RMCC placed a hold on all tracks. Train 541(15) with 46 customers onboard was stopped in the area at milepost 38.3 waiting for a clear route. Train 534(15) was also delayed holding at Martinez. Due to the prolonged delay, Train 541(15) was reversed back to Suisun and terminated, all passengers onboard were transferred to Train 543(15). Trains 540(15), 545(15) and 548(15) were all cancelled in entirety. Once the hold was released on No.2 track, all trains resumed single-track operations with residual congestion delays in the area.

Train 543(15) was further delayed due to another reported fire near the tracks on the Martinez Subdivision at MP14.9. Once the hold was released, Train 543(15) was able to proceed.

Train	Delay	Comment
540(15)	Cancelled	
545(15)	Cancelled	
548(15)	Cancelled	
541(15)	Terminated	SUI
543(15)	59"	SUI-MTZ
543(15)	43"	MP14.9
534(15)	58"	
532(15)	2'01"	
550(15)	44"	ITD SJC - Equip from 543

Train 7/27(15) Chicago, IL - Car Failure

15JUL26: Train 7/27(15) operating with engines 382/370, 10 coaches, and 238 customers, was delayed departing Chicago, IL, on Amtrak Chicago Terminal subdivision, due to HVAC issues in diner car C/34063. Mechanical worked and was able to resolve the issue. That diner car also had no water and needed to have that serviced as well. Once those 2 issues were resolved, train 7/27(15) was able to board their customers and depart Chicago, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(15)	41"	

Train 8/28(14) Libby, MT - Freight Train Interference

15JUL26: Train 8/28(14) with engines 306, 376, 10 cars, and 208 customers onboard was delayed beginning at milepost 1272.2, 47 miles east of Libby, MT on the BNSF Kootenai River subdivision due to meeting BNSF freight train 7544. The train then met BNSF 3897, 7949, 8262 at Brimstone siding. The train advanced to East Whitefish siding and met BNSF freight train 7742. Train 8/28(14) was then stopped at milepost 1149.8 due to BNSF freight 6704 stalled ahead. Once the freight congestion cleared, train 8/28(14) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(14)	11"	BNSF 7949
8/28(14)	20"	BNSF 3897
8/28(14)	46"	BNSF 7544
8/28(14)	18"	BNSF 8262
8/28(14)	26"	BNSF 7742
8/28(14)	41"	BNSF 6704

Train 3(15) Chicago, IL - Initial Terminal Delay

15JUL26: Train 3(15), operating with engines 53/140, 9 coaches, and 213 customers, was delayed departing Chicago, IL, on Amtrak Chicago Terminal subdivision, due to HVAC issues in C/39014 and late make up of the engines. Once 3(15) was finished being serviced they were able to board their customers and depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(15)	1'05"	

Train 22(15) Fort Worth, TX - Servicing

15JUL26: Train 22(15), operating with engines 315/13, 6 coaches, and 101 customers, was delayed departing Fort Worth, TX, on BNSF Ft. Worth subdivision, due to swapping engine 55 for engine 13. Once the train finished the engine change and performed the necessary tests, it was able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(15)	43"	

Train 24(15) West of New Orleans, LA - Freight Train Interference

15JUL26: Train 24(15) 26-FOT-00603 000000083291 engine UNCLASSIFIED 384365, 7/21/2026, 6 coaches and 123 customers, was delayed 13 miles west of New Orleans, LA, on CSX NO&M subdivision, due to meeting freight trains being set into the yard at North Gentilly Yard. Once the freights cleared into the yard and a route was made available, train 24(15) was able to proceed.

Train 23(15) was also delayed meeting train 24(15) and then 2 freights at North Gentilly Yard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(15)	36"	
23(15)	1'03"	

Train 22(15) North of Austin, TX - Trespasser Incident

15JUL26: Train 22(15) operating with engines 55/315, 6 coaches and 115 customers went into emergency 17 miles north of Austin, TX, on UPRR Austin subdivision, to avoid striking a vehicle on the tracks. There was no strike and after recovering their air and performing their brake test, train 22(15) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(15)	11"	

Train 302(15) South of Pontiac, IL - Car Failure

15JUL26: Train 302(15), operating with engine 4608, 5 coaches, 258 customers, went into emergency, 9.5 miles south of Pontiac, IL, at milepost 101.7 on UP Joliet subdivision due to an air hose separation between coaches 4004 and 4128. The crew stopped to put the hoses back together and discovered that the hoses where damaged. They then worked to replace the hoses. Once completed the crew performed their required brake tests and were able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
302(15)	36"	

Train 59(14) South of Memphis, TN - Routing

15JUL26: Train 59(14), operating with engine 23, 8 coaches, and 203 customers, was delayed 2 miles south of Memphis, TN, on CN Memphis subdivision, due to being routed through A Yard. Taking this route required the crew to hand line their route by hand operating switches. Once train 59(14) cleared the yard limits they were able to resume normal speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(14)	37"	

Train 319(15) Chicago, IL - Engine Failure

15JUL26: Train 319(15), operating with engine 68, 7 coaches, and 190 customers was delayed, departing Chicago, IL due to a bad ordered engine, 4611, that caused the equipment to be swapped out. The new equipment also required additional coaches to be added to be in compliant with the axel count.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(15)	40"	

Train 5(14) West of Fort Morgan, CO - Police Related

15JUL26: Train 5(14), 26-FO-00603, in 00000008329 engine UNCLASSIFIED 196436, 7/21/2026 coaches and 217 customers, was delayed 37 miles east of Denver, CO, on BNSF Brush subdivision, due to police meeting the train to remove a trespasser.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(14)	31"	

Train 5(13) Elko, NV - Injured or Sick Passenger or Employee

15JUL26: Train 5(13) with engines 188, 146, 9 cars, and 153 customers onboard was delayed departing Elko, NV on the UPRR Elko subdivision due to requesting medical assistance for a customer. Emergency services responded to the train. Once the customer and EMS cleared the train, train 5(13) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(13)	34"	

Train 21(14) South of Arkadelphia, AR - PTC Issue

15JUL26:

Train 21(14) was stopped approximately one mile south of Arkadelphia, AR, on UP Little Rock subdivision, due to PTC issues. The crew worked with mechanical personnel in an attempt to resolve the problem. When troubleshooting efforts were unsuccessful, Union Pacific required the train to perform a flat switch of the locomotives. During preparations for this move, the crew encountered an unrecoverable penalty condition that prevented the train from moving. The crew continued troubleshooting with CNOC and UP mechanical personnel while UP identified a freight locomotive at Texarkana, AR that could be utilized if necessary.

The crew subsequently worked with the Road Foreman of Engines (RFE) and mechanical personnel to resolve the penalty condition and proceeded with the locomotive flat switch. At that time, the train had accumulated a two-hour delay. A UP freight locomotive was dispatched from TXA as a contingency measure with an estimated arrival time of 8:45 a.m. CT if needed. After completing the flat switch, encountered an additional issue with the electrical cables. They were too short to be connected from the engine to the coaches. The crew found a jumper on one of the engines and used that to bridge the gap.

Upon completion of the brake test, Train 21(14) resumed movement after an overall delay of approximately four hours and thirty minutes. Shortly thereafter, the train stopped again so EMS personnel could meet the train and assist a customer experiencing a medical emergency. After EMS responded and took the customer to the hospital, the train resumed operation. All PTC-related issues had been fully resolved, and Train 21(14) continued its trip operating approximately six hours and eighteen minutes late.

Due operating 6 hours and 21 minutes at Forth Worth TX station it was necessary to daily the engines on train 21(14) before departing.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(14)	4'27"	
21(14)	35"	EMS meet.
21(14)	32"	Daily Engines

Severe Weather Central and Southwestern Texas - Flash Flood Warnings

14JUL26: A nearly stationary front will continue to play from the Southern Plains across the Deep South into the Southeast through the next several days. Upper-level disturbances moving along the front will support repeated rounds of showers and thunderstorms across this corridor, producing periods of locally heavy rainfall. The greatest concern is across Texas Hill Country and Big Bend, where a significant multi day heavy rainfall event is expected to continue for the next three days. A widespread 2-4 inches of rainfall will bring localized flash flooding to much of the region. The greatest accumulations of 8-12 inches with widespread flash flooding will occur around Del Rio, TX and areas south of I-10.

UPRR flash flood warnings were in effect on the Del Rio Subdivision, beginning 31 miles west of San Antonio, TX, between MP241 and MP292. Trains 2/422(12) and 1(13)/421(12) were delayed operating through the affected area. Train 1(13)/421(12) was further delayed west of Del Rio, TX/MP378.6, on the UPRR Sanderson Subdivision, operating through flash flood warnings between MP392 and MP406 and flagging through a track indication between MP468 and MP478.

Train 22(14)/422(12) was delayed beginning 4 miles north of San Antonio, TX, on the UPRR Austin Subdivision, operating through flash flood warnings between MP259 and MP236. Train 22(14)/422(12) was further delayed north of Temple, TX/MP218 due to flash flood warnings in effect on the BNSF Fort Worth Subdivision between MNP218 and MP243.

Train 2(12) was delayed east of San Antonio, TX/MP209, on the UPRR Glidden Subdivision, due to flash flood warnings in effect between MP126 and MP85. Train 2(12) was further delayed east of Houston, TX, on the UPRR Beaumont Subdivision, due to a large tree down ahead at MP419.3 and also due to flash flood warnings in effect on the UPRR Beaumont and Lafayette Subdivisions.

Train	Delay	Comment
2(12)	20"	E/DRT, flash flood warnings MP277-MP244
1(13)/421(12)	1'11"	W/SAS, flash flood warnings
2(12)	11"	E/SAS, flash flood warnings
22(14)/422(12)	16"	N/SAS
22(14)/422(12)	27"	N/TPL, flash flood warnings
1(13)/421(12)	38"	W/DRT
2(12)	1'20"	E/HOS, downed tree ahead
2(12)	04"	E/HOS, flash flood warnings

UPRR Desoto Subdivision Washout - North of Poplar Bluff, MO

10JUL26: At 3:30AM-CT 26-FBI-00603 60000008329 reported an "UNCLASSIFIED" washout on 7/21/2026 the UPRR DeSoto Subdivision at Annapolis (MP108), located 57.6 miles north of Poplar Bluff, MO (MP165.6). As a result, Train 22(09) arrived at the Poplar Bluff station at 4:04AM-CT with 144 customers onboard and held for disposition.

A Union Pacific Manager of Track Maintenance responded to the washout location at 4:20AM-CT and provided a preliminary estimated track restoration time of 2:00PM-CT. A detour route was available via the Chester Subdivision between Poplar Bluff and St. Louis, bypassing Arcadia. No customer impact occurred at Arcadia, as no customers were scheduled to board or detrain at that location. Union Pacific pilot crews went on duty at 6:10AM-CT and responded to the train, arriving at 7:00AM-CT. Upon the pilots' arrival, Train 22(09) departed Poplar Bluff at 7:21AM-CT and proceeded over the detour route via the Chester Subdivision.

At 12:00PM-CT, Union Pacific reported that floodwaters were not expected to begin receding until Saturday, July 11. Following the water's recession, a track inspection would be required before rail operations could resume through the area. As a result:

-Train 21/421(10) detoured via the Chester Subdivision with 6 on / 0 off at Arcadia. The affected six customers were notified and advised to rebook on the next available departure.

-Train 22(10)/422(08) detoured via the Chester Subdivision with 0 on / 5 off at Arcadia. A sprinter van transported passengers from Saint Louis, MO back to Arcadia, MO.

11JUL26: Union Pacific reported that the floodwaters were not expected to recede until Sunday, July 12th. As a result, Trains 22(11) and 21(11) were also routed via the Chester Subdivision detour with no alternate provided to/from Arcadia.

12JUL26: UPRR revised eto was updated to 930AM-CT 12JUL. Due to no available UPRR pilots to support the detour, Train 22(11), with 109 customers, was delayed at Poplar Bluff, MO, holding for dispo of the route ahead and then further delayed through the area. Train 22(11) was delayed due to the 10MPH speed restriction through the washout area and also signal issues between MP107 and MP92. Train 21/421(12) was also delayed operating at 10MPH through the washout site.

13JUL26: UPRR 10MPH slow orders remained in effect between MP95 and MP110. Trains 22(12)/422(10) and 21(13) were delayed operating through the affected area.

Train	Delay	Comment
22(09)	3'14"	Hold PBF
22(09)	1'09"	Detour
21(11)	1'08"	Detour
22(10)/422(08)	3'21"	
21/421(10)	2'13"	
22(11)	1'09"	PBF
22(11)	2'42"	N/PBF
21/421(12)	1'47"	
22(12)/422(10)	1'13"	
21(13)	50"	
21/421(14)	49"	

Heat Dome affect Entire Network - Weather

08JUL26: A heat dome ~~28-FOI-006031 00000008329~~ ~~UNCLASSIFIED~~ ~~7/21/2025~~ bringing scorching high temps in excess of 100° throughout the country. It will begin to expand as the week goes along and shift to the east affecting the entire nation. The first few days will be focused from the southwest through the Rockies to the Great Plains. It will then shift east affecting the Upper Midwest through the Northeast. Trains will be restricted to high temperature restriction. The high temperatures, there will be increase of severe thunderstorms and high winds.

The heat dome is expected to persist until the remainder of July.

14JUL26: Vermonter Service Train 56(14) terminated in Springfield, MA. The equipment was deadhead to New Haven, CT where Train 55(15) originated.

Three buses were secured for the 119 customers for Train 56(14) between Springfield to St. Albans.

Buses were secured for the 221 customers for Train 55(14) between St. Albans and New Haven.

14JUL26: Additional Cancellations on the Northeast Corridor impacting Regional and Acela services were put into place to protect overall service:

Northeast Regional Trains 84, 119, 173, 176, 193, 196, (15-16)

Acela Trains 2152, 2154, 2165, 2167, 2193 (15-16)

On Corridor WBS # B.TR.100151.0830

WBS#: B.TR.100151.0830

Train	Delay	Comment
6(08)	32"	Heat Orders WNN-ELK
5(06)	31"	Heat orders - ELK to WNN
6(08)	49"	Heat orders- GRI to GJT
5(08)	28"	Heat Orders GRA-GJT
5(08)	43"	Heat Orders GJT-HER
6(08)	17"	Heat Orders MTZ-RSV
3(08)	45"	High Winds RAT - GLP
6(10)	1'25"	Heat Orders RNO - ELK
6(11)	1'20"	Heat Orders RNO-ELK
5(10)	46"	Heat Orders GRA-GRI
8(10)	1'59"	Heat Orders
7(10)	2'40"	Heat Orders
7/27(11)	2'22"	GGW-SBY
8/28(11)	2'03"	SBY-WPT
5(11)	1'12"	DEN-PRO
6(11)	49"	GRI-GRA
68(13)	48"	
5(12)	54"	GRA-HER
6(12)	47"	WNN-DEN
7/27(12)	2'00"	WTN-HAV
8/28(12)	50"	HAV-GGW
56(14)	Term SPG	New England storms
55(15)	Orig NHV	New England storms
68(14)	40"	
64(14)	24"	
8/28(13)	1'00"	HAV-GGW
7/27(13)	1'28"	WTN-HAV
6(14)	43"	WNN-ELK
5(12)	29"	RSV-MTZ
5(13)	1'13"	GRA-HER
5(14)	58"	Heat Orders GSC-HER
5(13)	51"	ELK-MTZ
6(15)	38"	Heat Orders WNN-ELK
3(14)	40"	Flash Flood Warnings E/WLO
3(14)	1'18"	Winds GLP-WLO
28(15)	16"	High Winds WIH-PSC

Midwest State Supported Service Adjustments - Equipment

08JUL26: The following Midwest State Supported Service Adjustments are in effect due to equipment availability issues in Chicago, IL:

10JUL26: Additional adjustments have been added to the schedule through 12JUL.

12JUL26: Lincoln and Wolverine service adjustments extended through 13JUL.

13JUL26: Lincoln and Illini/Saluki service adjustments in effect on Tuesday July 14th.

14JUL26: Illini/Saluki service adjustments extended to Wednesday July 15th.

Carl Sandburg Service:

- Trains 381(09-10) cancelled entirely, with alternate transportation for customers between Chicago and Quincy, IL.

- Trains 382(09-10) cancelled entirely, with alternate transportation for customers between Quincy and Chicago.

Lincoln Service:

- Trains 305(08-13) cancelled entirely, with alternate transportation for customers between Chicago, IL and St. Louis, MO.

- Trains 302(09-14) cancelled entirely, with alternate transportation for customers between St. Louis and Chicago.

Wolverine Service:

- Trains 350(11-13) cancelled entirely, with alternate transportation for customers between Chicago, IL and Pontiac, MI.

- Trains 355(11-13) cancelled entirely, with alternate transportation for customers between Pontiac, MI and Chicago, IL.

- Trains 350(16) cancelled entirely, with alternate transportation for customers between Chicago, IL and Pontiac, MI.

- Trains 355(16) cancelled entirely, with alternate transportation for customers between Pontiac, MI and Chicago, IL.

Illini/Saluki Service:

- Train 391(14-15) cancelled entirely, with alternate transportation for customers between Chicago, IL and Carbondale, IL.

- Train 392(14-15) cancelled entirely, with alternate transportation for customers between Carbondale and Chicago.

12JUL26: One of the busses providing alternate transportation for Train 302(12), Bus 3, was involved in an auto accident at the Bloomington-Normal, IL station. There were four passengers onboard at the time. No injuries were reported. The station secured transportation for the affected passengers.

WBS#: B.TR.100150.6872

Train	Delay	Comment
381(09-10)	Cancelled	
382(09-10)	Cancelled	
302(09-14)	Cancelled	
305(08-13)	Cancelled	
355(11-13)	Cancelled	
350(11-13)	Cancelled	
391(14-15)	Cancelled	
392(14-15)	Cancelled	

Wolverine Track Work- Scheduled M/W Work

15JUL26:

Westbound

Eastbound

WBS#: B.TR.100150.6897

WBS#: B.TR.100150.6896

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

09JUL26: This outage was originally scheduled to conclude on Friday July 31st, but will now conclude 2-weeks Earlier on Friday July 17th. The following adjustments are now in place.

- Train 59(21Jun-15Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (16Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-16Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(17Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track construction projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,

Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,

Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,

Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,

Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,

Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,

Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,

Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,

Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00603

00000008329

"UNCLASSIFIED"

7/21/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
448 (15)	ALB	View 1 sleeper in lieu of view 2. Schedule change completed	SVWR448/15JUL NO WAR DATA THIS TRAIN/DATE	0	62015
5 (16)	CHI	Operating with standard coach in lieu of bag coach. Inventory for Lower level increased to reflect the change.			34014
646 (15)	HAR	CAFE IN PLACE OF CAB CAR, 288Y SEATS	n/a	0	43379
562 (15)	LAX	NO BIKE SPACE OR WIFI	passenger notifications sent no bike space no wifi.	0	90215
580 (15)	LAX	NO BIKE SPACE OR WIFI	passenger notifications sent no bike space no wifi.	1	90215
653 (15)	NYP	CAFE IN PLACE OF CAB CAR, 288Y SEATS, -65Y SEATS, CUSTOMER SERVICE WILL DIVERT TO OTHER TRAINS	email sent for overcapacity stanging conditions for passenger notifications	64	43379
185 (15)	NYP	Due to shopped equipment, there is no Biz class. extra coach was added for ridership.			82511
97 (15)	NYP	View 1 sleeper in lieu of view 2. Schedule change completed			62044
28 (15)	PDX	Coach (2814) abd Bag coach (2815) are BYD HVAC. WY, LY, XY and Y sales have been closed. Please accomodate all passengers who are effected.			34029, 31021
605 (15)	PHL	CAFE IN PLACE OF CAB CAR, 288Y SEATS	n/a	0	43379
110 (15)	PHL	Due to shopped equipment, there is no Biz class. extra coach was added for ridership.			82511
573 (15)	SAN	NO BIKE SPACE OR WIFI	passenger notifications sent no bike space no wifi.	0	90215
591 (15)	SAN	NO BIKE SPACE OR WIFI	passenger notifications sent no bike space no	0	90215

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00603 00000008329	"UNCLASSIFIED" 7/21/2026		
			wifi.		

Reverse Consists

Train Number	Station	Reason
93 (15)	BOS	Consist reversed Business class seat orientation may have changed At Front
94 (15)	NFK	Consist reversed Business class seat orientation may have changed At Front
138 (15)	NFK	Consist reversed Business class seat orientation may have changed At Front
183 (15)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (15)	PHL	Consist reversed Business class seat orientation may have changed At Front
137 (15)	BOS	Consist reversed Business class seat orientation may have changed At Front
86 (16)	NPN	Consist reversed Business class seat orientation may have changed At Front **Train 86(16)**
179 (15)	BOS	Consist reversed Business class seat orientation may have changed At Front
86 (15)	NPN	Consist reversed Business class seat orientation may have changed At Front
174 (15)	WAS	Consist reversed Business class seat orientation may have changed At Front
41 (15)	CHI	Consist reversed, sleeper cars are located at the front.