



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, June 29, 2026

Rules: 2-35



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/28/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	294	42	85.7%	8,746	1,202	86.3%	80,711	11,040	86.3%
Central Division	88.0%	64	5	92.2%	1,874	220	88.3%	17,846	1,818	89.8%
Northeast Division	82.0%	97	13	86.6%	2,818	388	86.2%	25,497	3,968	84.4%
Southeast Division	83.0%	64	10	84.4%	1,963	245	87.5%	18,432	2,652	85.6%
Southwest Division	86.0%	69	14	79.7%	2,091	349	83.3%	18,936	2,602	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00562 00000008119 "UNCLASSIFIED" 6/30/2026

	Day				Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	17,800	4,733	73%	2,997,387	906,960	70%	26,639,040	6,395,331	76%
Northeast Corridor	81%	7,134	1,350	81%	1,309,004	350,284	73%	11,718,130	2,754,033	76%
Acela	83%	507	0	100%	261,895	61,122	77%	2,310,644	598,609	74%
Northeast Regional	79%	6,627	1,350	80%	1,047,109	289,162	72%	9,407,486	2,155,424	77%
Richmond / Newport News / Norfolk	77%	2,337	602	74%	318,656	125,532	61%	2,918,674	803,391	72%
Springfield Shuttles	89%	256	0	100%	20,424	4,884	76%	166,993	24,099	86%
Roanoke	79%	640	282	56%	102,387	23,904	77%	885,140	173,927	80%
On Spine Northeast Regional	80%	3,394	466	86%	605,642	134,842	78%	5,436,679	1,154,007	79%
State Supported	80%	6,136	745	88%	1,330,399	342,915	74%	11,639,427	2,330,033	80%
Borealis	80%	0	0	-	15,955	2,817	82%	148,948	30,337	80%
Capitol Corridor	90%	45	40	11%	109,668	14,303	87%	992,147	126,535	87%
Carolinian	70%	0	0	-	30,441	18,976	38%	307,213	114,753	63%
Cascades	75%	0	0	-	86,692	32,870	62%	678,144	187,145	72%
Downeaster	82%	519	0	100%	44,334	4,533	90%	391,762	44,873	89%
Empire	78%	1,136	7	99%	163,461	54,924	66%	1,436,509	307,345	79%
Adirondack	72%	0	0	-	10,278	2,595	75%	85,086	24,926	71%
Ethan Allen Express	70%	0	0	-	16,211	10,765	34%	149,202	46,408	69%
Maple Leaf	70%	0	0	-	23,253	10,810	54%	172,574	65,376	62%
New York - Albany	85%	798	7	99%	75,424	17,686	77%	669,670	101,364	85%
New York - Niagara Falls	75%	338	0	100%	35,671	12,211	66%	357,353	68,414	81%
Berkshire Flyer	60%	0	0	-	2,624	857	67%	2,624	857	67%
Gold Runner	73%	0	0	-	72,341	31,893	56%	666,191	228,849	66%
Heartland Flyer	70%	0	0	-	7,030	2,345	67%	54,834	20,292	63%
Hiawatha	90%	451	0	100%	55,379	6,369	88%	452,368	50,064	89%
Illinois	78%	871	209	76%	73,259	25,296	65%	654,327	174,004	73%
Carl Sandburg / Illinois Zephyr	85%	147	0	100%	13,350	4,004	70%	108,141	27,187	75%
Illini / Saluki	85%	0	0	-	23,427	8,184	65%	230,853	53,148	77%
Lincoln Service	70%	724	209	71%	36,482	13,108	64%	315,333	93,669	70%
Keystone	92%	1,069	173	84%	229,639	16,090	93%	2,037,199	208,955	90%
Lincoln / Missouri	70%	0	0	-	24,854	16,081	35%	205,720	102,105	50%
Mardi Gras Service	80%	229	0	100%	10,543	5,167	51%	109,172	22,077	80%
Michigan	70%	870	237	73%	64,438	27,778	57%	513,461	162,518	68%
Blue Water	70%	237	237	0%	14,649	9,639	34%	118,894	43,982	63%
Pere Marquette	85%	163	0	100%	8,678	2,552	71%	66,952	13,337	80%
Wolverine	70%	470	0	100%	41,111	15,587	62%	327,615	105,199	68%
Missouri	80%	0	0	-	6,697	2,020	70%	58,531	13,094	78%
Pacific Surfliner	85%	866	0	100%	250,639	50,501	80%	2,043,818	320,955	84%
Pennsylvanian	80%	0	0	-	24,304	6,621	73%	236,165	41,762	82%
Piedmont	80%	80	79	1%	26,588	9,708	63%	310,582	78,229	75%
Vermont	75%	0	0	-	34,137	14,623	57%	342,336	96,141	72%
Long Distance	70%	4,530	2,638	42%	357,984	213,761	40%	3,242,216	1,308,802	60%
Auto Train	70%	505	0	100%	22,647	8,903	61%	206,542	68,979	67%
California Zephyr	70%	0	0	-	26,755	15,653	41%	256,788	83,463	67%
Cardinal	70%	0	0	-	6,574	4,525	31%	63,074	29,864	53%
City Of New Orleans	75%	0	0	-	16,833	11,620	31%	177,085	49,375	72%
Coast Starlight	70%	0	0	-	33,981	16,261	52%	300,405	103,330	66%
Crescent	70%	451	290	36%	26,266	11,664	56%	246,471	70,465	71%
Empire Builder	70%	39	17	56%	31,864	22,644	29%	250,640	117,588	53%
Floridian	60%	890	890	0%	43,706	40,420	8%	425,517	280,136	34%
Lake Shore Ltd	73%	529	72	86%	30,371	11,065	64%	249,934	70,705	72%
Palmetto	70%	469	241	49%	25,899	13,683	47%	245,758	65,593	73%
Silver Meteor	70%	486	227	53%	28,741	17,759	38%	269,695	108,633	60%
Southwest Chief	60%	535	535	0%	26,657	22,034	17%	215,805	136,525	37%
Sunset Ltd	70%	0	0	-	8,723	4,792	45%	76,988	26,271	66%
Texas Eagle	70%	626	366	42%	28,967	12,738	56%	257,514	97,875	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~20-FOI-00502~~ ~~00000000110~~ ~~"UNCLASSIFIED"~~ ~~0/00/2020~~

Train Index Dates Through June 28, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	186,113	3,050,088	610	1,555,241	28,423,474	547

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	8,655	892,686	97	72,792	8,147,537	89
INFRASTRUCTURE PLANNED	135	15,500	892,686	174	77,768	8,147,537	95
FLEET RELIABILITY	90	21,279	3,050,088	70	248,239	28,423,474	87
TRAIN OPERATIONS	424	140,679	3,050,088	461	1,156,442	28,423,474	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/28/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	294	42	85.7%	8,746	1,202	86.3%	80,711	11,040	86.3%
Central Division	88.0%	64	5	92.2%	1,874	220	88.3%	17,846	1,818	89.8%
Northeast Division	82.0%	97	13	86.6%	2,818	388	86.2%	25,497	3,968	84.4%
Southeast Division	83.0%	64	10	84.4%	1,963	245	87.5%	18,432	2,652	85.6%
Southwest Division	86.0%	69	14	79.7%	2,091	349	83.3%	18,936	2,602	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0054 Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/28/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	294	42	85.7%	8,746	1,202	86.3%	80,711	11,040	86.3%
Central Division	88.0%	64	5	92.2%	1,874	220	88.3%	17,846	1,818	89.8%
CDL	95.0%	2	0	100.0%	59	4	93.2%	513	18	96.5%
CHI	86.0%	25	2	92.0%	759	105	86.2%	7,186	858	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	1	1	0.0%	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	56	2	96.4%	532	52	90.2%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	1	1	0.0%	1	1	0.0%
GRR	95.5%	1	0	100.0%	27	0	100.0%	258	8	96.9%
IND	-	-	-	-	1	0	100.0%	1	0	100.0%
KCY	92.0%	2	0	100.0%	55	4	92.7%	534	40	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	1	80.0%	164	11	93.3%	1,586	97	93.9%
MSP	96.5%	1	0	100.0%	28	1	96.4%	264	5	98.1%
PDX	86.0%	5	1	80.0%	139	26	81.3%	1,328	166	87.5%
PNT	88.0%	3	0	100.0%	82	4	95.1%	697	58	91.7%
PTH	93.0%	1	0	100.0%	28	0	100.0%	259	10	96.1%
QCY	91.0%	2	0	100.0%	53	4	92.5%	526	38	92.8%
SEA	85.0%	8	0	100.0%	224	45	79.9%	2,125	307	85.6%
SPK	90.0%	1	0	100.0%	28	3	89.3%	264	20	92.4%
STL	89.0%	4	1	75.0%	112	6	94.6%	1,049	90	91.4%
TOL	-	-	-	-	1	1	0.0%	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	56	2	96.4%	526	14	97.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	97	13	86.6%	2,818	388	86.2%	25,497	3,968	84.4%
ALB	88.5%	7	1	85.7%	218	9	95.9%	1,998	161	91.9%
BON	87.5%	5	0	100.0%	139	10	92.8%	1,302	138	89.4%
BOS	85.5%	17	4	76.5%	491	38	92.3%	4,604	559	87.9%
BRK	92.5%	5	0	100.0%	137	17	87.6%	1,291	83	93.6%
BTN	82.0%	1	0	100.0%	28	2	92.9%	257	39	84.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	55	4	92.7%	527	49	90.7%
HFD	-	-	-	-	40	0	100.0%	143	7	95.1%
MTR	79.0%	1	0	100.0%	28	4	85.7%	254	45	82.3%
NFL	93.5%	2	0	100.0%	56	0	100.0%	546	22	96.0%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	138	5	96.4%	1,395	221	84.2%
NYP	75.5%	42	6	85.7%	1,275	275	78.4%	10,954	2,438	77.7%
PIT	76.0%	1	1	0.0%	6	5	16.7%	6	5	16.7%
POR	-	-	-	-	3	2	33.3%	8	5	37.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%

Information Management

26-FOI-0054 Initial Terminal Performance By Terminal

Scheduled Departure Date:	06/28/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 06/28/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	294	42	85.7%	8,746	1,202	86.3%	80,711	11,040	86.3%
Northeast Division	82.0%	97	13	86.6%	2,818	388	86.2%	25,497	3,968	84.4%
SAB	98.0%	1	0	100.0%	27	2	92.6%	258	4	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SPG	92.5%	7	1	85.7%	149	12	91.9%	1,642	92	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	28	3	89.3%	257	55	78.6%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
Southeast Division	83.0%	64	10	84.4%	1,963	245	87.5%	18,432	2,652	85.6%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CLT	91.5%	5	0	100.0%	137	22	83.9%	1,331	131	90.2%
GRO	-	-	-	-	8	3	62.5%	25	8	68.0%
HAR	79.5%	7	2	71.4%	316	28	91.1%	2,997	505	83.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	28	2	92.9%	267	33	87.6%
MIA	89.5%	2	0	100.0%	56	13	76.8%	535	59	89.0%
MOE	97.5%	2	0	100.0%	56	1	98.2%	541	8	98.5%
NFK	84.5%	2	2	0.0%	56	17	69.6%	617	109	82.3%
NOL	94.5%	3	0	100.0%	120	8	93.3%	1,143	53	95.4%
NPN	93.0%	2	0	100.0%	56	5	91.1%	509	34	93.3%
PGH	93.0%	1	1	0.0%	28	2	92.9%	269	19	92.9%
PHL	48.0%	4	3	25.0%	132	53	59.8%	1,390	671	51.7%
RGH	95.0%	4	0	100.0%	102	4	96.1%	1,053	41	96.1%
RNK	83.5%	2	0	100.0%	56	6	89.3%	530	77	85.5%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	28	2	92.9%	266	10	96.2%
SFA	88.0%	1	1	0.0%	28	7	75.0%	267	37	86.1%
WAS	84.0%	27	1	96.3%	756	72	90.5%	6,535	835	87.2%
Southwest Division	86.0%	69	14	79.7%	2,091	349	83.3%	18,936	2,602	86.3%
ARN	92.0%	1	0	100.0%	27	2	92.6%	269	19	92.9%
BFD	79.0%	7	1	85.7%	186	52	72.0%	1,672	340	79.7%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	1	1	0.0%	28	11	60.7%	285	85	70.2%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	1	0	100.0%	28	2	92.9%	294	34	88.4%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	1	0	100.0%	1	0	100.0%
GTA	90.0%	3	1	66.7%	84	30	64.3%	810	113	86.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	1	90.9%	297	34	88.6%	2,655	273	89.7%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKC	97.0%	1	0	100.0%	28	2	92.9%	265	6	97.7%

Information Management

Initial Terminal Performance By Terminal

26-FOI-0054

06/29/2026 04:45 AM

Scheduled Departure Date:	06/28/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 06/28/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	294	42	85.7%	8,746	1,202	86.3%	80,711	11,040	86.3%
Southwest Division	86.0%	69	14	79.7%	2,091	349	83.3%	18,936	2,602	86.3%
OKJ	74.5%	9	4	55.6%	326	95	70.9%	2,873	730	74.6%
RNO	-	-	-	-	1	0	100.0%	2	1	50.0%
SAC	88.5%	11	4	63.6%	415	64	84.6%	3,773	407	89.2%
SAN	90.5%	13	1	92.3%	363	26	92.8%	3,218	290	91.0%
SAS	90.5%	1	0	100.0%	28	4	85.7%	267	27	89.9%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SJC	89.0%	7	1	85.7%	196	14	92.9%	1,893	180	90.5%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	83	13	84.3%	574	60	89.5%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 6/28/2026

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	No OS	11	2	81.8%	114	25	78.1%	12	5	58.3%	111	21	81.1%
3	76	27	12	55.6%	268	54	79.9%	27	15	44.4%	267	116	56.6%
4	No OS	26	7	73.1%	267	40	85.0%	27	21	22.2%	268	178	33.6%
5	No OS	27	4	85.2%	267	42	84.3%	28	15	46.4%	264	63	76.1%
6	No OS	28	10	64.3%	267	77	71.2%	28	17	39.3%	267	82	69.3%
7	No OS	27	6	77.8%	257	34	86.8%	28	12	57.1%	251	60	76.1%
8	No OS	27	17	37.0%	257	110	57.2%	28	25	10.7%	257	147	42.8%
11	No OS	27	7	74.1%	268	49	81.7%	28	10	64.3%	263	55	79.1%
14	No OS	27	3	88.9%	269	41	84.8%	28	19	32.1%	268	83	69.0%
19	No OS	27	7	74.1%	267	63	76.4%	27	11	59.3%	266	59	77.8%
20	No OS	28	2	92.9%	268	18	93.3%	28	11	60.7%	268	48	82.1%
21	No OS	27	0	100.0%	264	22	91.7%	28	6	78.6%	264	63	76.1%
22	No OS	28	4	85.7%	266	25	90.6%	28	12	57.1%	264	63	76.1%
23		28	0	100.0%	271	5	98.2%	27	15	44.4%	269	69	74.3%
24		28	0	100.0%	271	14	94.8%	28	13	53.6%	270	43	84.1%
27	No OS	27	6	77.8%	255	18	92.9%	28	16	42.9%	252	81	67.9%
28		27	12	55.6%	251	58	76.9%	28	15	46.4%	252	51	79.8%
40	117	28	10	64.3%	264	38	85.6%	28	26	7.1%	263	130	50.6%
41	No OS	27	10	63.0%	263	101	61.6%	28	26	7.1%	262	194	26.0%
42	No OS	28	2	92.9%	270	20	92.6%	28	4	85.7%	268	43	84.0%
43	No OS	28	4	85.7%	269	41	84.8%	28	14	50.0%	269	56	79.2%
48	No OS	27	3	88.9%	267	52	80.5%	28	4	85.7%	268	39	85.4%
49		27	5	81.5%	267	66	75.3%	28	5	82.1%	268	51	81.0%
50	No OS	12	2	83.3%	110	26	76.4%	12	11	8.3%	110	63	42.7%
52		27	6	77.8%	266	36	86.5%	28	7	75.0%	266	59	77.8%
53	No OS	27	2	92.6%	266	33	87.6%	28	13	53.6%	266	84	68.4%
54	No OS	8	1	87.5%	100	6	94.0%	8	5	37.5%	100	14	86.0%
57	No OS	8	1	87.5%	99	4	96.0%	8	2	75.0%	99	7	92.9%
59	Cncld	27	8	70.4%	258	28	89.1%	26	14	46.2%	255	46	82.0%
63	No OS	28	10	64.3%	271	117	56.8%	28	24	14.3%	267	139	47.9%
64	No OS	28	3	89.3%	269	62	77.0%	28	21	25.0%	269	89	66.9%
65		8	1	87.5%	83	12	85.5%	8	0	100.0%	83	11	86.7%
66	103	27	3	88.9%	267	54	79.8%	28	6	78.6%	266	49	81.6%
68	No OS	28	4	85.7%	271	54	80.1%	28	8	71.4%	271	103	62.0%
69	No OS	28	11	60.7%	258	57	77.9%	28	8	71.4%	254	31	87.8%
71	31	28	0	100.0%	266	3	98.9%	28	10	64.3%	265	66	75.1%
72	No OS	28	7	75.0%	266	29	89.1%	28	12	57.1%	265	54	79.6%
73	No OS	28	5	82.1%	270	16	94.1%	27	12	55.6%	268	127	52.6%
79	No OS	28	7	75.0%	268	54	79.9%	28	18	35.7%	267	84	68.5%
80	No OS	28	5	82.1%	268	27	89.9%	27	14	48.1%	266	50	81.2%
87	No OS	8	0	100.0%	103	24	76.7%	8	5	37.5%	103	33	68.0%
88	No OS	8	1	87.5%	102	14	86.3%	8	4	50.0%	102	23	77.5%

Amtrak On Time Performance

Trains Arriving Through: 6/28/2026

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
89		28	4	85.7%	266	56	78.9%	28	10	64.3%	264	69	73.9%
90	No OS	28	2	92.9%	266	10	96.2%	28	11	60.7%	265	37	86.0%
97	No OS	27	20	25.9%	267	170	36.3%	28	16	42.9%	266	76	71.4%
98		28	3	89.3%	268	20	92.5%	28	14	50.0%	266	79	70.3%
99	No OS	8	0	100.0%	102	12	88.2%	8	5	37.5%	101	57	43.6%
103		8	2	75.0%	101	21	79.2%	8	0	100.0%	101	8	92.1%
105	No OS	4	1	75.0%	34	15	55.9%	4	1	75.0%	34	6	82.4%
117		4	2	50.0%	18	11	38.9%	4	0	100.0%	18	3	83.3%
118	No OS	8	0	100.0%	101	6	94.1%	8	2	75.0%	101	6	94.1%
120		4	0	100.0%	34	5	85.3%	4	0	100.0%	34	3	91.2%
121	No OS	4	0	100.0%	34	9	73.5%	4	2	50.0%	34	14	58.8%
128	20	7	0	100.0%	102	18	82.4%	8	4	50.0%	102	15	85.3%
140	No OS	8	1	87.5%	101	12	88.1%	8	2	75.0%	100	20	80.0%
143	No OS	8	2	75.0%	100	9	91.0%	8	3	62.5%	100	23	77.0%
150	23	8	4	50.0%	99	54	45.5%	8	3	62.5%	97	48	50.5%
151	No OS	28	10	64.3%	267	85	68.2%	28	9	67.9%	266	83	68.8%
153		8	1	87.5%	101	8	92.1%	8	2	75.0%	101	14	86.1%
154	No OS	4	0	100.0%	34	4	88.2%	4	3	25.0%	34	19	44.1%
155	No OS	8	1	87.5%	103	15	85.4%	8	6	25.0%	103	34	67.0%
156	No OS	8	1	87.5%	103	10	90.3%	8	4	50.0%	103	31	69.9%
157	No OS	4	0	100.0%	34	2	94.1%	4	1	75.0%	34	12	64.7%
160	No OS	8	0	100.0%	100	5	95.0%	8	3	62.5%	98	23	76.5%
161	No OS	8	1	87.5%	101	9	91.1%	8	6	25.0%	100	63	37.0%
162	No OS	8	0	100.0%	101	5	95.0%	8	4	50.0%	101	49	51.5%
164	No OS	8	0	100.0%	103	8	92.2%	8	4	50.0%	103	44	57.3%
169		7	1	85.7%	100	12	88.0%	8	1	87.5%	100	21	79.0%
195	No OS	8	0	100.0%	101	4	96.0%	8	5	37.5%	101	53	47.5%
230		28	0	100.0%	105	4	96.2%	28	0	100.0%	105	5	95.2%
232		28	1	96.4%	271	11	95.9%	28	1	96.4%	271	17	93.7%
234		28	0	100.0%	271	19	93.0%	28	2	92.9%	271	23	91.5%
236		28	0	100.0%	255	7	97.3%	28	7	75.0%	255	35	86.3%
238	No OS	28	2	92.9%	195	19	90.3%	28	5	82.1%	194	15	92.3%
240	No OS	28	2	92.9%	270	20	92.6%	27	15	44.4%	268	43	84.0%
245		27	6	77.8%	151	27	82.1%	28	4	85.7%	151	17	88.7%
280		28	0	100.0%	271	11	95.9%	28	9	67.9%	271	49	81.9%
281	No OS	28	3	89.3%	271	28	89.7%	28	10	64.3%	271	46	83.0%
284	No OS	28	0	100.0%	271	10	96.3%	28	8	71.4%	269	42	84.4%
290	No OS	28	2	92.9%	271	48	82.3%	28	19	32.1%	269	90	66.5%
300		28	1	96.4%	255	19	92.5%	28	7	75.0%	253	56	77.9%
301	No OS	28	1	96.4%	269	9	96.7%	28	8	71.4%	266	51	80.8%
302		28	3	89.3%	256	31	87.9%	27	9	66.7%	252	72	71.4%
307	47	27	5	81.5%	258	35	86.4%	28	9	67.9%	256	70	72.7%

Amtrak On Time Performance

Trains Arriving Through: 6/28/2026

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
311	No OS	28	0	100.0%	269	23	91.4%	27	6	77.8%	264	51	80.7%
318	No OS	28	4	85.7%	270	26	90.4%	28	20	28.6%	267	122	54.3%
319	No OS	28	3	89.3%	271	17	93.7%	28	21	25.0%	269	143	46.8%
331		28	3	89.3%	271	29	89.3%	28	4	85.7%	271	40	85.2%
332		28	2	92.9%	271	14	94.8%	28	5	82.1%	271	39	85.6%
334	No OS	28	3	89.3%	271	9	96.7%	28	8	71.4%	270	37	86.3%
350	No OS	28	2	92.9%	252	17	93.3%	28	21	25.0%	247	136	44.9%
351		28	3	89.3%	254	25	90.2%	27	6	77.8%	252	68	73.0%
353	No OS	27	0	100.0%	213	12	94.4%	27	6	77.8%	207	36	82.6%
354		27	8	70.4%	251	27	89.2%	28	11	60.7%	248	87	64.9%
365	No OS	28	0	100.0%	259	10	96.1%	28	18	35.7%	257	90	65.0%
371		27	0	100.0%	258	8	96.9%	27	3	88.9%	257	27	89.5%
380		27	0	100.0%	257	23	91.1%	27	6	77.8%	257	48	81.3%
381	No OS	28	2	92.9%	271	11	95.9%	27	10	63.0%	270	48	82.2%
390	No OS	28	2	92.9%	253	17	93.3%	28	11	60.7%	252	63	75.0%
391	No OS	28	2	92.9%	256	8	96.9%	28	18	35.7%	253	64	74.7%
400		8	2	75.0%	82	6	92.7%	8	0	100.0%	80	2	97.5%
405		8	0	100.0%	77	0	100.0%	8	0	100.0%	77	4	94.8%
448	No OS	27	4	85.2%	200	38	81.0%	28	9	67.9%	199	67	66.3%
450		9	3	66.7%	81	27	66.7%	8	2	75.0%	79	24	69.6%
460	No OS	8	1	87.5%	80	27	66.3%	8	6	25.0%	77	25	67.5%
461		8	0	100.0%	83	5	94.0%	8	0	100.0%	82	2	97.6%
500	No OS	27	0	100.0%	262	15	94.3%	27	4	85.2%	260	32	87.7%
502	No OS	28	2	92.9%	269	15	94.4%	28	4	85.7%	266	57	78.6%
503	No OS	28	5	82.1%	267	25	90.6%	28	16	42.9%	261	75	71.3%
504	No OS	28	1	96.4%	271	17	93.7%	28	13	53.6%	269	83	69.1%
505	No OS	28	5	82.1%	269	35	87.0%	28	12	57.1%	266	74	72.2%
516	No OS	28	3	89.3%	263	27	89.7%	28	20	28.6%	262	123	53.1%
517	No OS	28	1	96.4%	271	8	97.0%	27	19	29.6%	267	108	59.6%
562		28	3	89.3%	263	21	92.0%	28	2	92.9%	260	29	88.8%
564	No OS	28	4	85.7%	263	17	93.5%	28	5	82.1%	255	31	87.8%
566	No OS	28	1	96.4%	261	17	93.5%	28	3	89.3%	258	33	87.2%
567	No OS	28	2	92.9%	148	8	94.6%	28	2	92.9%	146	7	95.2%
637		7	0	100.0%	53	6	88.7%	8	0	100.0%	53	4	92.5%
660	11	8	3	62.5%	73	11	84.9%	8	4	50.0%	73	25	65.8%
661	29	8	0	100.0%	101	11	89.1%	8	2	75.0%	100	37	63.0%
663	No OS	8	3	62.5%	73	10	86.3%	8	3	62.5%	73	7	90.4%
664	No OS	8	0	100.0%	72	6	91.7%	8	1	87.5%	72	7	90.3%
666	No OS	8	0	100.0%	73	20	72.6%	8	1	87.5%	73	7	90.4%
690		8	1	87.5%	78	2	97.4%	8	0	100.0%	77	4	94.8%
691		8	0	100.0%	78	7	91.0%	8	0	100.0%	76	21	72.4%
692		8	0	100.0%	78	3	96.2%	8	0	100.0%	77	13	83.1%

Amtrak On Time Performance

Trains Arriving Through: 6/28/2026

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
693	No OS	8	0	100.0%	78	12	84.6%	8	3	62.5%	77	22	71.4%
694	No OS	8	0	100.0%	78	6	92.3%	8	2	75.0%	78	15	80.8%
699		5	0	100.0%	58	8	86.2%	6	0	100.0%	58	2	96.6%
701	No OS	28	6	78.6%	203	21	89.7%	28	7	75.0%	200	20	90.0%
702	No OS	28	5	82.1%	270	31	88.5%	27	9	66.7%	268	60	77.6%
710	No OS	28	5	82.1%	271	69	74.5%	28	12	57.1%	267	72	73.0%
711	No OS	28	6	78.6%	262	28	89.3%	27	8	70.4%	245	44	82.0%
713	No OS	18	1	94.4%	144	14	90.3%	18	7	61.1%	131	57	56.5%
718		27	17	37.0%	270	136	49.6%	28	12	57.1%	269	90	66.5%
720	No OS	8	1	87.5%	85	9	89.4%	8	1	87.5%	85	5	94.1%
723	20	8	1	87.5%	85	5	94.1%	8	1	87.5%	85	9	89.4%
724	No OS	8	0	100.0%	85	3	96.5%	8	2	75.0%	85	15	82.4%
727	No OS	8	0	100.0%	85	6	92.9%	8	2	75.0%	85	14	83.5%
729	No OS	7	1	85.7%	84	9	89.3%	7	3	57.1%	84	20	76.2%
757	No OS	28	1	96.4%	56	2	96.4%	28	3	89.3%	56	4	92.9%
761	No OS	28	2	92.9%	267	11	95.9%	28	2	92.9%	264	34	87.1%
765	No OS	28	0	100.0%	267	24	91.0%	28	2	92.9%	267	37	86.1%
769	No OS	28	1	96.4%	267	24	91.0%	28	6	78.6%	261	49	81.2%
770	No OS	28	1	96.4%	267	21	92.1%	28	12	57.1%	265	74	72.1%
774	No OS	28	0	100.0%	267	16	94.0%	28	7	75.0%	266	56	78.9%
794		27	2	92.6%	266	31	88.3%	27	4	85.2%	264	55	79.2%
821	No OS	28	2	92.9%	265	6	97.7%	28	11	60.7%	265	104	60.8%
1233	No OS	6	2	66.7%	6	2	66.7%	6	4	33.3%	6	4	33.3%
1333	No OS	28	2	92.9%	267	28	89.5%	28	10	64.3%	264	89	66.3%
1340	No OS	28	1	96.4%	266	5	98.1%	28	4	85.7%	266	43	83.8%
2208	No OS	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
2209		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2212	No OS	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2213	No OS	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2252	No OS	8	0	100.0%	98	8	91.8%	8	4	50.0%	96	28	70.8%
2254	No OS	2	0	100.0%	33	0	100.0%	2	2	0.0%	33	9	72.7%
2255	No OS	8	0	100.0%	99	11	88.9%	8	5	37.5%	98	47	52.0%
2259	No OS	8	4	50.0%	55	23	58.2%	8	3	62.5%	54	26	51.9%
2265	No OS	5	0	100.0%	36	3	91.7%	5	3	40.0%	35	21	40.0%
2290		4	1	75.0%	33	7	78.8%	4	0	100.0%	32	7	78.1%

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2208	NYP	No OS Rpt	OTH	23	OTH	15	PHL-NYP	AM	Lost time - N.A.R., PRT
2212	NYP	No OS Rpt	OTH	15	OTH	11	WAS-PHL	AM	Lost time - N.A.R.
2213	WAS	No OS Rpt	OTH	6	OTH	6	PHL-WIL	AM	Lost time - N.A.R., PRT
2252	BOS	No OS Rpt	DET	38	DET	24	RTE-BBY	AM	Catenary failure, Control Point, Cove, Catenary down on track 1 at Cove-Transfer
2254	BOS	No OS Rpt	CTI	19	CTI	11	STM-NHV	MN	Follow metro north, 6522, Milepost, 40, 55
2255	WAS	No OS Rpt	DSR	29	DSR	29	NHV-STM	MN	Per bulletin Restricted speed cat 533- cat 535, cp 241 - East Norwalk, WLSS Fairfield-Green's farm., Milepost, 48.6, 33.6, 30, 2
2259	WAS	No OS Rpt	OTH	12	SMW	6	PHL-PHL	AM	Scheduled in track usage program, Control Point, PENN, MW HOLD A/C 1-4 TRKS OOS
2265	WAS	No OS Rpt	DSR	24	DSR	24	NHV-STM	MN	Per bulletin Control Point, 273/234, 20, 1/2
66	BOS	103	SVS	86	SVS	86	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Engine swap
87	NFK	No OS Rpt	PTI	23	WTR	15	RVR-PTB	CS	Flash flood warning Milepost, 1.0, 12.9
88	BOS	No OS Rpt	SMW	14	DSR	13	STM-BRP	MN	Per bulletin Milepost, 38.2, 41.7, 30, 4, Milepost, 41.7, 42.0, 15, 4
99	NPN	No OS Rpt	DCS	16	SYS	16	RVR-RVR	CS	Had to get a new set of CSX bulletins Other, rvr
105	WAS	No OS Rpt	ITI	9	ITI	9	NYP-NYP	AM	Service, turn, or wye train, 120, LATE TURN OFF AM120
118	NYP	No OS Rpt	OTH	12	OTH	5	BAL-XPV	AM	Lost time - N.A.R., pure run time
121	WAS	No OS Rpt	CCR	23	CCR	23	XPV-BAL	AM	Electrical failure, CC 9645, reported an alarm on trailing E/657 & lost all power - stopped at MP 91.5
128	NYP	20	SMW	17	SMW	13	NWK-NYP	AM	Scheduled in track usage program, Other, XBH-NYP, SINGLE TRACKING IN THE NORTH TUBE A/C THE SOUTH TUBE O/O/S.
140	SPG	No OS Rpt	OTH	15	DSR	9	STM-BRP	MN	Per bulletin Control Point, 248, 30, 1,2
143	WAS	No OS Rpt	CTI	11	CTI	7	BWI-NCR	AM	Follow, Marc, 9485, Milepost, 106.3, 127.0
150	BOS	23	OTH	10	OTH	6	KIN-PVD	AM	Lost time - N.A.R.
151	RNK	No OS Rpt	OTH	9	OTH	7	PHL-WIL	AM	Lost time - N.A.R.
154	BOS	No OS Rpt	ENG	23	ENG	23	WIL-PHL	AM	Other electrical failure, 661 EX ES, Hit dragger at MP 13.2 on e/661.
155	NFK	No OS Rpt	OTH	15	PTI	11	XVG-ALX	CS	Follow p079, Milepost, 109.9, 105.1

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
156	NYP	No OS Rpt	OTH	13	WTR	7	BCV-XA1	NS	Flash flood warning Milepost w/Letters, BCV, CR Tower
157	WAS	No OS Rpt	DSR	24	DSR	16	BRP-STM	MN	Per bulletin Working limits stop sign, Milepost, 49.1, 48, 30, 2
160	BOS	No OS Rpt	DET	38	DET	22	RTE-BBY	AM	Catenary failure, Control Point, Cove, Crossover 3-1 at Transfer
161	WAS	No OS Rpt	CTI	17	CTI	11	BRP-STM	MN	Follow Following to cp 240, metro north, Control Point, 248
162	BOS	No OS Rpt	HLD	14	HLD	9	NYP-NYP	AM	Passenger and/or baggage, CREW REPORTED HEAVY BOARDING
164	BOS	No OS Rpt	CTI	19	CTI	9	STM-BRP	MN	Follow metro north, Control Point, 244
195	WAS	No OS Rpt	DSR	15	DSR	8	BRP-STM	MN	Per bulletin Milepost, 49.1, 48.0, 30, 2
460	SPG	No OS Rpt	CON	17	CON	17	NHV-NHV	AM	Hold for connecting train
53	SFA	No OS Rpt	TRS	220	TRS	220	XFL-XOU	CS	Trespasser strike Milepost, 381.7, 381.7
79	CLT	No OS Rpt	WTR	36	WTR	16	ALX-QAN	CS	Flash flood warning Milepost, 101.9, 92.0
80	NYP	No OS Rpt	SYS	18	WTR	10	QAN-ALX	CS	Flash flood warning Milepost w/Letters, CFP92.0, CFP101.9
660	NYP	11	SMW	8	PTI	7	XHM-TRE	AM	Follow, AM54, Other, XHM-TRE, FOLLOWED AM54
661	HAR	29	ENG	28	ENG	28	PHL-ARD	AM	HEP, 9638 CB CC, Wye'd on the outbound a/c HEP issues cc9638.
663	HAR	No OS Rpt	OTH	4	HLD	4	ARD-ARD	AM	High passenger count, per cndr 1145a
664	NYP	No OS Rpt	CTI	6	CTI	6	XHM-TRE	AM	Blocked from station track, NJT, NJ7832, Other, XMO-TRE, HELD A T E. FAIR A/C NJ7832 AHEAD NO.1 TRK TRENTON
666	NYP	No OS Rpt	SVS	63	SVS	38	PHL-PHL	AM	Unplanned Wye, UNPLANNED WYE A/C BAD CCR. ENGR WAS NOT QUALIFIED ON THE WYE SO HAD TO WAIT FOR QUALIFIED PERSONNEL
19	NOL	No OS Rpt	FTI	100	FTI	59	HBG-PIC	NS	Meet Cleared the main... Waiting on 2 Northbound to pass.. Shoved back onto the main and continued south, NS8128, NS4716, Milepost, 77.7, 93.3
20	NYP	No OS Rpt	FTI	101	FTI	48	LAU-MEI	NS	Follow Following NS346, NS346, Milepost, 44.0, 3.2
693	BRK	No OS Rpt	PTI	6	PTI	4	EXR-DHM	CS	Cross over or go around 694, Control Point, Newfields
694	BON	No OS Rpt	HLD	6	HLD	3	POR-POR	CS	High passenger count 100

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
63	TWO	No OS Rpt	FTI	33	FTI	26	ROC-BUF	CS	Follow csx 00928, Milepost, 380, 406
64	NYP	No OS Rpt	CTI	47	CTI	29	RHI-XCP	MN	Blocked from station track metro north, Control Point, 75
68	NYP	No OS Rpt	WTR	43	WTR	43	SLQ-RSP	CN	Heat order 25c weather restriction, Milepost, 42.5, 2
69	MTR	No OS Rpt	WTR	47	WTR	47	XLQ-SLQ	CN	Heat order 25 mph heat restriction, Milepost, 2, 42
238	NYP	No OS Rpt	DSR	5	DSR	3	ALB-HUD	AM	Per bulletin Milepost, 127, 125, 30, 2
240	NYP	No OS Rpt	DSR	6	DSR	6	ALB-HUD	AM	Per bulletin Milepost, 127.0, 125.0, 30, 2
281	NFL	No OS Rpt	PTI	4	PTI	4	NYP-XSD	AM	Meet, AM236, Other, XIW-XIW, AM236 XING AHEAD
284	NYP	No OS Rpt	FTI	11	SMW	10	XSD-NYP	AM	Scheduled in track usage program, Other, NO TIME LOST
290	NYP	No OS Rpt	CTI	23	CTI	23	POU-CRT	MN	Follow metro north, 8844, Milepost w/Letters, pou, crt
1233	PIT	No OS Rpt	DSR	10	ENG	9	ALB-ALB	AM	Unrecognizable fault, mechanical had to assist to clear and had to relog in 709
48	NYP	No OS Rpt	DCS	32	DCS	30	BYN-TOL	NS	Restrictive signal Planned system outage .. wait for system to come back up .. STOP signal at CP 340, Control Point, 340
448	BOS	No OS Rpt	ENG	20	ENG	20	ALB-ALB	AM	Air / Brake Removed 104 for stuck brakes, 104
42	NYP	No OS Rpt	OTH	13	CAR	12	PGH-PGH	NS	Set out defective car 61059
43	PGH	No OS Rpt	FTI	20	FTI	11	GNB-PGH	NS	Follow 11V, Milepost, 222.1, 235.4
71	CLT	31	TEN	30	TEN	30	DNC-GRO	NS	HEP HEP shut down. Issues restating., NC1810
72	RGH	No OS Rpt	TEN	52	TEN	42	KAN-SAL	NS	Failure of diesel engine 1797 engine shut down unable to restart. 1810 issues with HEP., NC1797
73	CLT	No OS Rpt	PTI	5	PTI	5	RGH-CYN	NS	Wait for station track #AMTK80, Control Point, Fentner
90	NYP	No OS Rpt	FTI	49	FTI	35	XDJ-ALX	CS	Meet 419, Other, cfp87.3
97	MIA	No OS Rpt	PTI	52	PTI	29	ALX-XDJ	CS	Follow PO87, Milepost w/Letters, CFP 101.3, CFP 63.3
54	SAB	No OS Rpt	OTH	19	OTH	9	WNL-SPG	AM	Lost time - N.A.R.

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
57	WAS	No OS Rpt	OTH	35	OTH	23	HLK-X1X	MA	Prior police issue into dispatch line up Prior police issue and dispatch allowing already late CT rail train out ahead of Amtrak trains making them late, instead of holding CT RAIL and lining trains to track 6 which was open
40	CHI	117	DSR	67	DCS	41	PGH-PGH	NS	PTC- Unplanned PTC system /server outage Norfolk Southern system outage, Other, Pittsburgh Station
41	MIA	No OS Rpt	FTI	58	FTI	25	DNK-SAV	CS	Meet #CSM59228, Siding, Estill SDG
5	EMY	No OS Rpt	FTI	86	FTI	28	XSN-XAZ	UP	Meet Stopped in siding, up 7195, Siding, sage
6	CHI	No OS Rpt	FTI	175	FTI	45	XAZ-XSN	UP	Follow Waited for UP 8951 to inspect train for dragging equipment detector prior to following., UP 8591, Control Point, Shafter, Control Point, Silverzone
720	SAC	No OS Rpt	PTI	12	PTI	6	RIC-MTZ	UP	Meet Held at CP RV027 Costa on MT2 to wait for Amtrak 727 to crossover in front of us, MT2 to MT1., Amtrak 727, Control Point, CP RV027 Costa
723	SJC	20	TEN	16	TEN	16	SAC-SAC	UP	The daily air brake inspection wasn't performed on Engine 920. (Second unit) Swapped equipment in SAC., JPBX920
724	SAC	No OS Rpt	DCS	104	DCS	88	HAY-OAC	UP	CTC system failure Vandalism; theft of cables - Waiting for Train 727 taking switches into hand throw; then we copied authority and did the same., Control Point, Coliseum
727	SJC	No OS Rpt	RTE	52	RTE	29	OKJ-OAC	UP	Line manual or spring switch Had us test switch and returned it to motor to try to get signal. After it didn't work we took switch back to hand and proceeded over switch then restored switch back to motor, Control Point, NI011
729	SJC	No OS Rpt	TRS	55	TRS	39	OKJ-OAC	UP	Vandalism Vandalism to control point . waiting for northbound traffic to hand throw switches and clear the area before we could do the same westbound, Control Point, NI011
50	NYP	No OS Rpt	FTI	259	FTI	167	CRF-IND	CS	Follow unknown, Control Point, Switzer
500	SEA	No OS Rpt	FTI	4	FTI	4	PDX-VAN	BN	Meet UP 1962, Control Point, CP 05
502	SEA	No OS Rpt	MBO	15	MBO	15	PDX-VAN	BN	For maritime traffic Bridge, columbia river
503	EUG	No OS Rpt	PTI	16	PTI	16	ALY-EUG	UP	Cross over or go around Routed around 14 on the main and shove back., amt14, Control Point, 647

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
504	SEA	No OS Rpt	PTI	11	PTI	8	XNI-TAC	ST	Meet amtk 517, Control Point, manitou
505	PDX	No OS Rpt	HLD	8	HLD	7	VAN-VAN	BN	Passenger and/or baggage Bear spray can went off in pax bag as she was exiting. No passengers affected, conductor and AC little choked up walking through the area, aired out vestibule before departing. PNR 71B6FC
516	VAC	No OS Rpt	DSR	11	DSR	7	XF2-X1J	BN	Per bulletin Milepost, 146.6, 147.8, 25, West, Milepost, 151.6, 151.9, 25, All, Other, CN, 30, All tracks
517	PDX	No OS Rpt	MBO	9	MBO	9	VAN-PDX	BN	For maritime traffic Bridge, Willamette River Bridge
59	JAN	Trn Cancelled							
11	LAX	No OS Rpt	TRS	100	TRS	100	EUG-XFS	UP	Vehicle on track ahead Control Point, 365.2
14	SEA	No OS Rpt	DCS	63	SYS	32	KFS-KFS	UP	Crew rest Other, KFS Depot
7	SEA	No OS Rpt	FTI	95	FTI	56	SPK-XOD	BN	Follow bnsf 3256, Milepost, 1481.6, 1532.0
8	CHI	No OS Rpt	WTR	215	WTR	113	WPT-WTN	BN	High winds Control Point, east macon, Control Point, east willston
27	PDX	No OS Rpt	FTI	50	FTI	19	PSC-WIH	BN	Meet BNSF 7026, Siding, Roosevelt
821	FTW	No OS Rpt	DSR	13	DSR	13	GLE-FTW	BN	Per bulletin Milepost, 410.8, 410.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.4, 25, m, Milepost, 400.9, 400.6, 60, m, Milepost, 396.3, 396.2, 30, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 385.5, 385.3, 30, m, Milepost, 383.6, 383.4, 60, m, Milepost, 38
334	CHI	No OS Rpt	RTE	4	RTE	4	GLN-XWA	ME	Dispatcher hold Control Point, Mayfair
350	PNT	No OS Rpt	DSR	11	DSR	6	TRM-PNT	CC	Per bulletin Milepost, 17.9, 18.0, 30, 1, Milepost, 18.4, 19.0, 30, 1, Milepost, 20.0, 21.2, 30, 1
353	CHI	No OS Rpt	DSR	19	DSR	5	PNT-TRM	CC	Per bulletin Milepost, 21.2, 17, 30, 1
365	CHI	No OS Rpt	DSR	30	DSR	16	LNS-BTL	CC	Per bulletin Milepost, 223.53, 223.53, 25, 2, Milepost, 221.42, 221.42, 30, main, Milepost, 219.15, 218.5, 25, main, Control Point, Mill, 25, main-1, Milepost, 214.93, 214.93, 25, 1, Milepost, 202.45, 201.75, 25, main, Milepost, 196.82, 196.82, 25, 2, Milepost, 194.78, 194.78, 25, 2, Milepost, 192.6
564	SAN	No OS Rpt	PTI	11	PTI	5	SNC-SNP	SC	Meet Amtk 567, Control Point, Serra

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
566	SAN	No OS Rpt	PTI	12	PTI	12	SNC-SNP	SC	Meet Waited in siding at CP Serra for Amtrak 769 to pass., 769, Control Point, Serra	
567	LAX	No OS Rpt	CTI	4	CTI	4	SOL-OSD	SN	Meet coaster, 672Q, Control Point, escondido jct	
757	SLO	No OS Rpt	PTI	41	PTI	39	GTA-X3G	UP	Meet 774, Siding, ellwood	
761	GTA	No OS Rpt	CTI	23	CTI	23	VNC-NRG	SC	Meet Metrolink, FIFA train, Control Point, Raymer	
765	SLO	No OS Rpt	PTI	12	PTI	12	MPK-XMR	SC	Meet 774, Control Point, Las Posas	
769	GTA	No OS Rpt	PTI	22	PTI	22	VEC-CPN	UP	Meet Waiting on 782 due to 782 waiting for 765 and 14, 782, Control Point, North Seacliff	
770	SAN	No OS Rpt	CTI	38	CTI	20	SNC-SNP	SC	Meet metrolink, Siding, serra	
774	SAN	No OS Rpt	PTI	17	PTI	16	CPN-VEC	UP	Meet 761, Siding, Seacliff	
701	SAC	No OS Rpt	ADA	10	ADA	4	SKT-SKT	UP	Wheelchair Retrieve and use manual lift to board pax traveling in a power wheelchair.	
702	BFD	No OS Rpt	FTI	17	FTI	9	MDR-FNO	BN	Meet bnsf 6556, Siding, medera	
710	BFD	No OS Rpt	TCC	60	TCC	60	OKJ-OKJ	UP	Air / Brake / Wheel 90218, Per TASI, per Amtrak Mechanical, a valve associated w/ATS causing brk issues when attempting to cut in cabbage car	
711	OKJ	No OS Rpt	PTI	26	PTI	13	ACA-XPR	BN	Meet AMTK 710, Control Point, W. Pittsburg	
713	OKJ	No OS Rpt	RTE	22	RTE	22	TRK-MOD	BN	Run via siding or slower track due to N.A.R. FREIGHT IN MAIN 2. HAD TO SHOVE., Control Point, EAST MODESTO EMPIRE	
3	LAX	76	CAR	168	CAR	168	CHI-CHI	AM	Set out defective car 32068	
4	CHI	No OS Rpt	FTI	120	INJ	41	RAT-RAT	BN	Injured or sick passenger Pax Mark Spencer Jr. faked a fall on the train after refusing to use the step box and arguing about being forced to use it. He is planning on suing Amtrak, Raton PD, Raton FD, and the doctors that he hasn't seen yet. This is all a huge scam.	
2	NOL	No OS Rpt	FTI	134	FTI	40	XIJ-LFT	BN	Meet Held in siding, bnsf7395, Siding, crowley	
21	SAS	No OS Rpt	FTI	57	SVS	31	FTW-FTW	UP	Routine inspections	
22	CHI	No OS Rpt	FTI	37	FTI	27	MHL-TXA	UP	Follow 6425, Milepost, 30.4, 2.9	
301	STL	No OS Rpt	FTI	33	FTI	17	XTF-XUD	CC	Cross Traffic bnsf, Control Point, Corwith	
307	STL	47	FTI	29	ENG	20	CHI-CHI	AM	HEP Fixing HEP Engine 4609 not 4631, ID4631	

Amtrak Endpoint OTP Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
381	QCY	No OS Rpt	ADA	3	ADA	3	MDT-MDT	BN	Wheelchair
390	CHI	No OS Rpt	PTI	12	PTI	12	HMW-XCS	CC	Meet UNKNOWN, Control Point, 16th
391	CDL	No OS Rpt	FTI	13	PTI	9	RTL-CHM	CC	Meet AM 390, Control Point, S Rantoul
311	KCY	No OS Rpt	ADA	5	ADA	5	HEM-HEM	UP	Mobility Impaired Conductor assisted sick mobility impaired pax off train with assistance from family members. Pax became violently sick and was able to detrain at ticketed destination. 5 minute delay incurred due to assisting with removal from train.
318	CHI	No OS Rpt	ENG	63	ENG	63	STL-STL	TR	Download- 314 files ID4613
319	KCY	No OS Rpt	FTI	47	FTI	43	WAR-LEE	UP	Cross over or go around up 7923, Siding, lees summit
1333	MSP	No OS Rpt	OTH	18	DCS	10	WIN-RDW	CP	Issue with automatic road crossing protection Other, WINONA AVE
1340	CHI	No OS Rpt	DSR	16	DSR	9	MSP-XH8	CP	Per bulletin GTB 12522 #6293, Milepost, 406.5, 406.2, 25, main 2

Amtrak Initial Terminal Details

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/28/2026

Terminal	Train	Date	Late	Delay	Cause
PGH	42	06/28	12	12	Set out defective car 61059
PHL	117	06/28	1		
PHL	150	06/28	1		
ALB	448	06/27	(No OS)	20	Air / Brake Removed 104 for stuck brakes, 104
BOS	161	06/28	9	9	Door, 82623 AX AS, Late a/c of a jammed door
NHV	450	06/28	1		
NYP	69	06/28	3	3	
NYP	105	06/28	9	9	Meet, AM232, Other, NYP-NYP, HELD A/C AM232 XING AHEAD
SPG	400	06/28	2	2	Service, turn, or wye train, 120, LATE TURN OFF AM120
CHI	1333	06/28	2	2	Passenger and/or baggage
STL	300	06/28	1		Hot Weather Air filters on all 3 cars needed to be changed due to extreme heat wave coming, Other, CUS
EMY	6	06/28	9	9	
OKJ	710	06/28	60	60	710 had mechanical issues 710 had mechanical issues we had to wait for Tracks to clear, 710, Control Point, kirkham
SAC	702	06/28	6	6	Air / Brake / Wheel 90218, Per TASI, per Amtrak Mechanical, a valve associated w/ATS causing brk issues when attempting to cut in cabbage car
SAC	723	06/28	16	16	Follow up 7898, Control Point, rv 990
					The daily air brake inspection wasn't performed on Engine 920. (Second unit) Swapped equipment in SAC., JPBX920

Eastern Region

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	98.7	94.8	166	0
CDOT	95.0	87.5	91.8	92.4	16	2
MARC	95.0	100.0	84.3	90.2	12	0
SEPTA	95.0	94.6	94.3	91.5	93	5
NJT-NED	95.0	94.3	92.3	88.6	194	11
NJT-SED	95.0	100.0	98.6	97.2	24	0

Operating Highlights

Train 40(27) - Confluence, PA - Injured or Sick Passenger or Employee

29JUN26: Train 40(27) was delayed on the CSX Keystone Subdivision at MP 243.5 due to an ill passenger required an EMS response to the train at Fairview Crossing.

Train	Delay	Comment
40(27)	47"	

Train 66(28) - Washington, DC - Delayed Engine Swap

29JUN26: Train 66(28) was delayed at Washington Union Terminal due to a delay in crews swapping diesels for electrics.

Train	Delay	Comment
66(28)	30"	

Train 283(28) - West Of Rochester, NY - Freight Train Interference

29JUN26: Train 283(28) was delayed on the CSX Rochester Subdivision between MP 371 and MP 406 due to following CSX Train M363-28.

Train	Delay	Comment
283(28)	32"	

Train 239(28) - South of Poughkeepsie, NY - Commuter Train Interference

28JUN26: Train 239(28) was delayed on the Metro North Hudson Line at MP 71.6 due to being held out of Poughkeepsie Station/MP 73.6. A disabled commuter train occupied the station track.

Train	Delay	Comment
239(28)	0'43"	

Train 128(28) Norfolk, VA - Engine Failure

28JUN26: Train 128(28) with E/333, E/366 and 10 cars with 170 customers was delayed departing Norfolk due to having brake issues in the yard.

Train	Delay	Comment
128(28)	38"	

Train 666(28) Philadelphia, PA - Servicing

28JUN26: Train 666(28) was delayed in Philadelphia due to it being necessary to wye the train upon departure due to problems with CC/9638. The engineer on the train was not qualified around the Wye making it necessary to find a qualified engineer.

Train	Delay	Comment
666(28)	1'03"	

Train 68(28) South of Rouses Point, NY - Weather

28JUN26: Train 68(28) was delayed on the CN Rouses Point subdivision due to heat orders from MP 42.5 to MP 2.0.

Train	Delay	Comment
68(28)	43"	

Train 2267(28) Boston, MA - Catenary or Wayside Failure

28JUN26: Train 2267(28) was delayed departing Boston due to down catenary on track 2 on top of Keolis 5838. It was necessary that train 2267(28) was able to depart on track 3.

This also delayed train 135(28) from departing Boston. As of 205P-ET Boston chief reported that ET returned the foul time on track 1 within Cove Interlocking limits. Track 1 was ok for eastbound trains and track 3 was ok for westbound trains. Track 2 was still unpassable.

Train	Delay	Comment
2267(28)	35"	
149(28)	25"	
2252(28)	38"	
160(28)	38"	
135(28)	14"	
2254(28)	06"	

Train 40(28) North of Miami, FL - Passenger Train Interference

28JUN26: Train 40(28) with E/333, E/98 and 10 cars with 102 customers onboard was delayed on the SFRTA South at MP 1022.5 due to Tri Rail 672 ahead with mechanical issues. They were able to crossover from track 2 to track 1 at CP Hardy.

Train	Delay	Comment
40(28)	56"	

28JUN26: Multiple trains affected by CSX heat orders that were in place from 1300-1900 on the following subdivisions Kanawha, Keystone, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(28)	20"	
98(28)	26"	
25(28)	10"	
128(28)	11"	
89(28)	27"	
53(28)	05"	
79(28)	18"	
155(28)	03"	
90(28)	21"	
97(27)	21"	
41(27)	04"	
40(27)	14"	

Train 71(28) Durham, NC - Engine Failure

28JUN26: Train 71(28) with E/NC1810 and E/NC1797 and 5 cars with 69 customers onboard was delayed on the NS Danville District due to E/NC1810 shutting down and needing to be recycled.

Train 72(28) was also delayed due to E/NC1797 shutting down and E/NC1810 having HEP issues. They were able to E/NC1797 restarted and operated with one engine.

Train	Delay	Comment
71(28)	30"	
72(28)	50"	

Train 66(27) New Haven, CT - Adding/Removing Engine Failure

28JUN26: Train 66(27) with E/613 and 5 cars was delayed at New Haven due to adding E/115 for PM Move. After having HEP issues with E/115 it was determined to remove E/115 and allow train 66(27) to proceed towards Boston.

This also caused delay to train 149(28) due to the crew arriving on late 66(27).

Train	Delay	Comment
66(27)	1'22"	
149(28)	36"	DUE TO CREW OFF LATE 66(27)

Train 53(27) - North of Charleston, SC - Trespasser Incident

28JUN26: 1:09am Train 53(27) 00000008119 E/352, E/388, E/364 plus 14 passenger cars and 28 auto carriers, transporting 502 passengers struck a trespasser near MP 381.8 on the CSX Charleston Subdivision, in the City of Goose Creek, Berkely County, SC. There were no reported injuries to the 22 crew or 502 passengers. There was no reported damage to the equipment. The struck trespasser was a confirmed fatality. HEP was maintained throughout the incident. The weather at the time of the incident was 80° and clear. This did not occur at a DOT Grade Crossing.

Amtrak Management and The Hanahan Police Department responded to the scene. After the police reviewed the footage of the incident recorded on the lead engine's forward facing camera, it was determined that two individuals were fighting on/near the right of way just prior to the strike. This escalated the matter into a homicide investigation.

Train 97(27) was held at MP 374.9 behind train 53(27) until the route was cleared.

Due to damage to the ladder on E/352 it was necessary to have Savannah mechanical remove the ladder from the engineer side. Then further delayed do to waiting for recrew/ job briefing.

National Response Center Number: 1466378

Train	Delay	Comment
53(27)	3'45"	
97(27)	0'30"	
53(27)	45"	SAV REMOVING LADDER
53(27)	31"	recrew
52(28)	3'45"	Turn off 53(27)

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46

21MAY26: CSX Albany Division, 26-FOI-00562, 00000008119, 00000008119, UNCLASSIFIED, 6/30/2026
 Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

17Oct, 20Oct-21Oct, 27Oct-31Oct, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) in Train "UNCLASSIFIED" operated Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 354(28) West of Dearborn, MI - Vehicle on the Tracks

28JUN26: Train 354(28), with 148 customers onboard, was delayed at mile post 11.0 1.3 miles west of Dearborn, MI/MP9.7 on the Michigan Department of Transportation Michigan Line operating around a vehicle on the tracks. Once clear of the affected area, train 354(28) continued into Dearborn, MI.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(28)	35"	

Train 19(27) South of Hattiesburg, MS - Freight Train Interference

28JUN26: Train 19(27), with 140 customers onboard, was delayed in Richburg/MP93.3 8 miles south of Hattiesburg, MS/MP85.3 on the NS N.O.&N.E. subdivision meeting multiple NS freights. Train 19(27) was ordered to clear the main track for northbound freights NS8128 and NS4716. Once the route was clear, train 19(27) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(27)	59"	

Train 319(28) East of Lee's Summit, MO - Freight Train Interference

28JUN26: Train 319(28), with 262 customers onboard, was delayed at Lee's Summit siding/MP258.0 2 miles east of Lee's Summit, MO/MP259.9 on the UP Sedalia subdivision crossing over onto the siding to operate around UP freight UP7923. Train 319(28) advanced into the Lee's Summit once clear of the UP freight.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(28)	32"	

Train 3(27) East of Gallup, NM - High Wind Warnings

28JUN26: Train 3(27), carrying 237 customers onboard, was delayed east of Gallup, NM, on the BNSF Gallup Subdivision due to high wind warnings in the area. The train was required to operate at a maximum speed of 20 MPH between approximately MP 145 and MP 168, resulting in reduced speeds and additional delay through the territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(27)	48"	

Train 7/27(27) East & West of Havre, MT - High Wind Warnings

28JUN26: Train 7/27(27), carrying 207 customers onboard, was delayed east of Havre, MT, on the BNSF Milk River Subdivision due to high wind warnings, requiring reduced speeds of 40 MPH between West Zurich (MP 400) and West Lohman (MP 418.7). The train experienced additional delay west of Havre on the BNSF Hi Line Subdivision, operating through alternating 40 MPH restriction zones from Pacific Junction (MP 964.8) to Shelby East (MP 1065.5). Once clear of the wind-restricted territory, Train 7/27(27) resumed normal operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(27)	24"	MAL-HAV
7/27(27)	44"	HAV-SBY

Train 19(27) South of Birmingham, AL - Switch Failure

28JUN26: Train 19(27) 28-FOI-00562 00000008119 MP163.9 25 miles south of Birmingham, AL, on the NS AGS South District, due to power switch failure. Train 19(27) was delayed hand throwing switches and operating through the affected area.

Train	Delay	Comment
19(27)	35"	

Train 2(26) West of Lafayette, LA - Freight Train Interference

28JUN26: Train 2(26), with 119 customers onboard, was delayed at Crowley siding/MP163.9 20 miles west of Lafayette, LA/MP144.5 on the BNSF Lafayette subdivision meeting BNSF freight. Train 2(26) was held on Crowley siding for BNSF freight BN/7395 to clear the route, and then continued east.

Train	Delay	Comment
2(26)	40"	

Train 8/28(27) East of Shelby, MT - High Wind Warnings

28JUN26: Train 8/28(27), carrying 207 customers onboard, was delayed while operating between Shelby, MT, and Havre, MT, across the BNSF Hi Line and Milk River Subdivisions due to high wind warnings in the area. The train was required to operate at reduced speeds not exceeding 40 MPH from approximately MP 1021 on the Hi Line Subdivision through Havre (MP 430.4) on the Milk River Subdivision.

Train 8/28(27) was delayed east of Havre for additional warnings operating at 40 MPH to MP 402.00 on the Milk River sub as well.

Train	Delay	Comment
8/28(27)	37"	SBY-HAV
8/28(27)	15"	HAV-MAL

Train 728(28) West of Martinez, CA - Drawbridge Opening

28JUN26: At approximately 4:55 PM PT, Train 728(28), carrying 143 customers onboard, was delayed while holding at Martinez, CA Station and then just west at Vista (MP 32.7) on the Union Pacific Martinez Subdivision, awaiting the Suisun Bay Bridge to close following maritime traffic. At the same time, Train 741(28), carrying 146 customers, was delayed on the opposite side of the bridge while holding at Park (MP 35.3).

At approximately 6:10 PM PT, the bridge was again opened to maritime traffic, causing additional delays. Train 743(28), carrying 81 customers, was held at Park (MP 35.0), while Train 734(28), carrying 143 customers, was held at Vista (MP 32.8). Once vessel movements concluded and the bridge was lowered and secured, rail traffic resumed, and all affected trains continued their trips without further incident.

Train	Delay	Comment
728(28)	52"	
741(28)	46"	
743(28)	40"	
734(28)	10"	

Train 318(28) St. Louis, MO - PTC

28JUN26: Train 318(28), E/IDTX4613 & 7 cars, with 285 customers, was delayed at St. Louis, MO/MP1.5, on the TRRA Merchants Subdivision, due to PTC issues on E/IDTX4613. Crew attempted to resolve issue and then contacted mechanical desk for additional assistance. Issues were resolved and Train 318(28) proceeded north with PTC operational on E/IDTX4613.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
318(28)	1'03"	

Train 732(28) North of Oakland, CA - Third Party Contractor Engine Failure

28JUN26: Train 732(28), operating with locomotive C2001 and carrying 9 customers onboard, was stopped shortly after departing Oakland, CA, at MP 5.7 on the Union Pacific Niles Subdivision, due to a loss of head-end power (HEP). While stopped adjacent to the Oakland Maintenance Facility, TASI Mechanical responded and determined the issue was caused by a low oil fault.

Due to the inability to complete timely repairs, the train was shoved back to Oakland Jack London Station to detrain passengers. As a result, the following service adjustments were implemented:

- Train 732(28) was canceled, with customers accommodated on the next available service, Train 734(28).
- Train 751(28) was canceled, with alternate bus transportation provided.
- Train 734(28) equipment was turned for Train 747(28) at Sacramento.
- Train 738(28) equipment was turned for Train 749(28).

Service recovery initiated on 734(28) for 732 customers with 20% cafe discount offered.

The affected equipment was removed from service for further inspection and repair at the maintenance facility.

WBS#: B.TR.100150.6825

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
732(28)	Cancel	
751(28)	Cancel	

Train 22(28)/422(26) Fort Worth, TX - Planned Equipment Move

28JUN26: Train 22(28)/422(26), E/315-E/192 & 8 cars, was delayed just south of Fort Worth, TX/MP345.3, on the UPRR Choctaw Subdivision, cutting off E/192 in a planned equipment move.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(28)/422(26)	34"	

Train 786(28) Lompoc-Surf, CA - Passenger Train Interference

28JUN26: Train 786(28), carrying 210 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.7) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(28) and 14(28).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(28)	53"	

Train 20(28) South of Meridian, MS - Freight Train Interference

28JUN26: Train 20(28) 28-FCI-00562 delay 00000008119MP7.2 UNCLASSIFIED 6/30/2026 was delayed south of Meridian, MS, on the NS NO & NE District, due to NS 344 stopped ahead and then further delayed following NS 344 to Meridian.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(28)	43"	

Train 14(27) Klamath Falls, OR - System

28JUN26: Train 14(27), with 285 customers, was delayed at Klamath Falls, OR/MP429.5, on the UPRR Cascade Subdivision, due to crew rest. The crew signed up on 10 hours rest at 0800-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(27)	32"	

Train 757(28) North of Goleta, CA - Passenger Train Interference

28JUN26: Train 757(28) was delayed 2 miles north of Goleta, CA on the UPRR Santa Barbara subdivision due to meeting train 774(28) at Ellwood siding at MP 355.7.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
757(28)	39"	

Train 21(27) Fort Worth, TX - Servicing

28JUN26: Train 21(27), with 160 customers onboard, was delayed departing Fort Worth, TX/MP346.2 on the BNSF Fort Worth subdivision completing a routine equipment inspection. Once the inspection was complete, train 21(27) departed Fort Worth, TX.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(27)	31"	

Train 727(28) North of Oakland, CA - Routing

28JUN26: Train 727(28) was delayed north of Oakland Coliseum Station, Oakland, CA on the UPRR Niles Subdivision due to signal and switch issues. Track indicator lights were observed at the end of the depot, requiring movement through the area under flag protection.

At the first switch near 66th Ave, the switch encountered was a hand-operated/manual (spring) switch. The crew tested the switch and restored it to power in an attempt to obtain a signal indication. When a signal was not achieved, the switch was returned to hand operation, the movement was made through the switch, and it was then restored back to power.

The crew manually lined two additional switches to access the depot and hand-lined one final switch upon departure.

Service Recovery was initiated on all affected train with 20% cafe discounts offered.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
727(28)	57"	
724(28)	1' 37"	
729(28)	55"	
733(28)	56"	
734(28)	42"	
728(28)	43"	

Train 8/28(27) West Glacier, MT - M O R W WORK

28JUN26: Train 8/28(27) with 100000008119 held in the station until repairs were made and rail traffic was cleared to resume. UNCLASSIFIED 6/30/2026

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(27)	41"	

Train 710(28) Oakland, CA - Third Party Contractor Cab Car Failure

28JUN26: Train 710(28) with cab car 90218 leading and locomotive C2013 trailing was delayed departing Oakland Jack London Square (OKJ), Oakland, CA on the UPRR Niles Subdivision. After departing Oakland Maintenance Facility with the locomotive leading, the crew was unable to cut in the cab car upon arrival at the station. TASI Mechanical responded and determined a valve associated with the ATS system was causing a brake issue during the cut-in process.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
710(28)	1'00"	

Train 7(26) West of Spokane, WA - Freight Train Interference

28JUN26: Train 7(26) experienced delays approximately 2 miles west of Spokane, WA, on the BNSF Columbia River Subdivision due to freight interference. The train was held behind BNSF freight locomotive 3256 from Milepost (MP) 1481.6 to MP 1532.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7(26)	56"	

Train 50(27) East of Connersville, IN - Freight Train Interference

28JUN26: Train 50(27), with 91 customers, was delayed east of Connersville, IN/MP67.2, on the CSX Indianapolis Subdivision, following CSX 361 between MP46.3 and MP25.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(27)	45"	

Train 7/27(27) Minot, ND - Crew Rest

28JUN26: Train 7/27(27), with 215 customers, was delayed at Minot, ND/MP203.3, on the BNSF KO Subdivision, due to crew rest. The crew signed up on 10 hours rest at 1118AM-CT off Train 8/28(26) which arrived at 118AM-CT, 3 hours and 10 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(27)	1'42"	

28JUN26: Train 8/28(26) with 00000008119 UNCLASSIFIED as of 6/30/2026 beginning 8 miles west of Rugby, ND, on the BNSF Devils Lake Subdivision, due to tornado warning just expired ahead between MP150.0 and MP127. Train 8/28(26) was the first train to operate through the area post tornado warning and was delayed operating restricted speed through. Train 8/28(26) was further delayed at MP143 due to a downed tree and it was necessary to shove back and operate through the siding around the tree.

Train	Delay	Comment
8/28(26)	1'06"	MP150-MP127
8/28(26)	31"	MP143

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27) was cancelled in its entirety with no alternate transportation.
- Train 58(28) was cancelled in its entirety with no alternate transportation.
- Train 59(27) was cancelled in its entirety with no alternate transportation.
- Train 59(28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

WBS#: B.TR.100150.6822

Train	Delay	Comment
58(27-29)	Cancelled	
59(27-29)	Cancelled	
59(26)	Terminated	JAN

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1(15NOV)/421(14NOV)	Bypass PSN	
1(18-21FEB)/421(17-20FEB)	BYPASS - Palm Springs	Flooding
2/422(18, 20, 22FEB)	Bypass Palm Springs	Flooding
1(30)/421(29)(MAR)	Bypass PSN	
1(01APR)/421(31MAR)	Bypass PSN	
1(04APR)/421(03APR)	Bypass PSN	
1(23, 31DEC)421(23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422(24DEC)	Bypass PSN - Flooding	
1(03, 05JAN)/421(02, 04JAN)	BYPASS PSN - flooding	
2/422(04, 07JAN)	BYPASS PSN - flooding	
2/422(01, 03, 05APR)	Bypass PSN	
1(06, 13, 18, 20, 23MAY) 421(05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422(13, 15, 20, 24MAY)	Bypass PSN	
2/422(17, 21, 26JUN)	Bypass PSN	
1(08, 15, 17, 20, 22, 24JUN) 421(07, 14, 16, 19, 21, 23JUN)	Bypass PSN	
2/422(28)	BYPASS PSN	
1(27)/421(26)	BYPASS PSN	

26JUN26: BNSF has bridge deck replacement trackwork scheduled on the Ottumwa Subdivision Monday, June 29th from 8:00AM to 10:00PM between Osceola, IA and Creston, IA. To accommodate the infrastructure work, Amtrak's California Zephyr Service has been adjusted as follows:

- Train 6(27JUN) will operate as Train 1006(27JUN) and will operate 1-hour earlier between Emeryville and Chicago.
- Train 5(29JUN) will operate as Train 1005(29JUN) and will operate 1-hour later between Chicago and Emeryville.

WBS#: B.TR.100150.6816

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform maintenance and track construction projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 20-044

20APR26: Amtrak/MDOT will perform track reconstruction on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 24(28) Passenger Removal at Bay Saint Louis, Mississippi – Improper Conduct***

28Jun26, Passengers traveling together on PNRs 3D4643, 482FC3, 48FC56, and 719BFC, traveling from New Orleans, LA to Mobile, AL were removed by local police due to playing music loud, consuming personal alcohol, and being a disturbance to others. Amtrak Police notified.

Delay: **24 (28)** **13"**

Consist Deviations

26-FOI-00562

00000008119

"UNCLASSIFIED"

6/30/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
232 (28)	ALB	biz class as coach	NONE	0	81527
149 (28)	BOS	BIZ USED AS COACH	none	0	81502
149 (28)	BOS	81502 operating as a coach due to lack of equipment in BOS.	NONE	0	81502
672 (28)	HAR	CAFE REPLACED CAB CAR -66Y SEATS	NONE	0	43379
562 (28)	LAX	no bike space or wifi	NONE	0	90225
580 (28)	LAX	no bike space or wifi	YES	1	90225
562 (29)	LAX	NO BIKE SPACE OR WIFI	YES	1	90225
580 (29)	LAX	NO BIKE SPACE OR WIFI	YES	1	90225
566 (29)	LAX	NO BIKE SPACE OR WIFI	YES	1	9700
584 (29)	LAX	NO BIKE SPACE OR WIFI	NONE	0	9700
40 (28)	MIA	SLEEPER FOR OVERFLOW COACH PAX	NONE	0	62XXX
40 (28)	MIA	28015 CAFE/LOUNGE IN PLACE OF A DINER	NONE	0	28015
1233 (28)	NYP	biz class as coach	NONE	0	81527
243 (28)	NYP	biz class as coach	NONE	0	81527
121 (28)	NYP	coach in place of biz class, no biz class	NONE	0	82663
637 (28)	NYP	CAFE REPLACED CAB CAR -66Y SEATS	NONE	0	43379
42 (28)	PGH	b/o baggage car cut @ pgh	none	0	61059
615 (28)	PHL	CAFE REPLACED CAB CAR -66Y SEATS	NONE	0	43379
1246 (28)	PIT	biz class as coach	NONE	0	81527
573 (28)	SAN	no bike space or wifi	YES	6	90225
591 (28)	SAN	no bike space or wifi	YES	2	90225
573 (29)	SAN	NO BIKE SPACE OR WIFI	YES	2	90225
591 (29)	SAN	NO BIKE SPACE OR WIFI	NONE	0	90225
579 (29)	SAN	NO BIKE SPACE OR WIFI	NONE	0	9700
595 (29)	SAN	NO BIKE SPACE OR WIFI	NONE	0	9700
122 (28)	WAS	coach in place of biz class, no biz class	NONE	0	82663
154 (28)	WAS	biz class used as coach	none	0	81530

Reverse Consists

Train Number	Station	Reason	
		26-FOI-00562 00000008119	"UNCLASSIFIED" 6/30/2026
161 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
149 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
158 (28)	NFK	Consist reversed Business class seat orientation may have changed At Front	
155 (28)	NYP	Consist reversed Business class seat orientation may have changed At Front	
153 (28)	NYP	Consist reversed Business class seat orientation may have changed At Front	
150 (28)	PHL	Consist reversed Business class seat orientation may have changed At Front	
100 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	
135 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
146 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	
125 (29)	SPG	Consist reversed Business class seat orientation may have changed At Front	
94 (29)	NFK	Consist reversed Business class seat orientation may have changed At Front	
88 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	