



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, June 12, 2026

Rules: 0-33



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/11/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	52	83.8%	3,465	462	86.7%	75,430	10,300	86.3%
Central Division	88.0%	68	14	79.4%	740	79	89.3%	16,712	1,677	90.0%
Northeast Division	82.0%	102	19	81.4%	1,115	169	84.8%	23,794	3,749	84.2%
Southeast Division	83.0%	73	9	87.7%	778	103	86.8%	17,247	2,510	85.4%
Southwest Division	86.0%	77	10	87.0%	832	111	86.7%	17,677	2,364	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00532 00000007812 UNCLASSIFIED 6/17/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	103,195	37,879	63%	1,148,049	353,970	69%	24,789,702	5,842,341	76%
Northeast Corridor	81%	47,272	15,529	67%	509,509	160,077	69%	10,918,635	2,563,826	77%
Acela	83%	10,507	2,966	72%	106,519	30,436	71%	2,155,268	567,923	74%
Northeast Regional	79%	36,765	12,563	66%	402,990	129,641	68%	8,763,367	1,995,903	77%
Richmond / Newport News / Norfolk	77%	10,499	5,518	47%	120,690	53,193	56%	2,720,708	731,052	73%
Springfield Shuttles	89%	575	117	80%	7,869	2,077	74%	154,438	21,292	86%
Roanoke	79%	3,822	1,065	72%	38,922	9,040	77%	821,675	159,063	81%
On Spine Northeast Regional	80%	21,869	5,863	73%	235,509	65,331	72%	5,066,546	1,084,496	79%
State Supported	80%	44,600	15,049	66%	502,272	117,897	77%	10,811,300	2,105,015	81%
Borealis	80%	507	266	48%	6,117	1,588	74%	139,110	29,108	79%
Capitol Corridor	90%	4,286	671	84%	42,285	3,601	91%	924,764	115,833	87%
Carolinian	70%	517	502	3%	10,440	6,131	41%	287,212	101,908	65%
Cascades	75%	2,980	680	77%	30,357	13,020	57%	621,809	167,295	73%
Downeaster	82%	1,369	0	100%	16,671	1,067	94%	364,099	41,407	89%
Empire	78%	5,994	3,694	38%	62,928	19,554	69%	1,335,976	271,975	80%
Adirondack	72%	331	165	50%	3,786	820	78%	78,594	23,151	71%
Ethan Allen Express	70%	567	552	3%	6,268	3,805	39%	139,259	39,448	72%
Maple Leaf	70%	833	361	57%	8,822	3,746	58%	158,143	58,312	63%
New York - Albany	85%	3,003	1,769	41%	30,423	7,568	75%	624,669	91,246	85%
New York - Niagara Falls	75%	1,260	847	33%	13,629	3,615	73%	335,311	59,818	82%
Gold Runner	73%	2,197	765	65%	27,870	11,440	59%	621,720	208,396	66%
Hearland Flyer	70%	236	101	57%	2,635	961	64%	50,439	18,908	63%
Hiawatha	90%	1,905	950	50%	20,444	2,012	90%	417,433	45,707	89%
Illinois	78%	1,708	869	49%	27,368	7,955	71%	608,436	156,663	74%
Carl Sandburg / Illinois Zephyr	85%	459	223	51%	5,171	982	81%	99,962	24,165	76%
Illini / Saluki	85%	620	327	47%	8,543	2,212	74%	215,969	47,176	78%
Lincoln Service	70%	629	319	49%	13,654	4,761	65%	292,505	85,322	71%
Keystone	92%	9,462	566	94%	96,982	5,779	94%	1,904,542	198,644	90%
Lincoln / Missouri	70%	392	284	28%	8,314	5,044	39%	189,180	91,068	52%
Mardi Gras Service	80%	402	259	36%	4,362	1,932	56%	102,991	18,842	82%
Michigan	70%	2,235	1,579	29%	23,391	9,361	60%	472,414	144,101	69%
Blue Water	70%	538	531	1%	5,372	2,521	53%	109,617	36,864	66%
Pere Marquette	85%	143	0	100%	3,236	965	70%	61,510	11,750	81%
Wolverine	70%	1,554	1,048	33%	14,783	5,875	60%	301,287	95,487	68%
Missouri	80%	253	208	18%	2,458	971	60%	54,292	12,045	78%
Pacific Surfliner	85%	7,470	1,941	74%	87,665	13,340	85%	1,880,844	283,794	85%
Pennsylvanian	80%	842	539	36%	9,635	2,648	73%	221,496	37,789	83%
Piedmont	80%	766	714	7%	9,309	3,334	64%	293,303	71,855	76%
Vermont	75%	1,079	461	57%	13,041	8,159	37%	321,240	89,677	72%
Long Distance	70%	11,323	7,301	36%	136,268	75,996	44%	3,020,500	1,171,037	61%
Auto Train	70%	739	0	100%	8,238	2,843	65%	192,133	62,919	67%
California Zephyr	70%	470	69	85%	10,088	3,417	66%	240,121	71,227	70%
Cardinal	70%	569	500	12%	2,690	1,254	53%	59,190	26,593	55%
City Of New Orleans	75%	631	572	9%	5,676	4,079	28%	165,928	41,834	75%
Coast Starlight	70%	1,106	153	86%	12,581	5,594	56%	279,005	92,663	67%
Crescent	70%	878	379	57%	10,315	3,740	64%	230,520	62,541	73%
Empire Builder	70%	1,189	1,082	9%	12,063	8,253	32%	230,839	103,197	55%
Floridian	60%	1,543	1,527	1%	17,629	14,953	15%	399,440	254,669	36%
Lake Shore Ltd	73%	976	838	14%	11,473	3,737	67%	231,036	63,377	73%
Palmetto	70%	382	264	31%	9,538	5,204	45%	229,397	57,114	75%
Silver Meteor	70%	931	756	19%	10,832	6,330	42%	251,786	97,204	61%
Southwest Chief	80%	947	870	8%	10,481	7,827	25%	199,629	122,318	39%
Sunset Ltd	70%	0	0	-	3,431	2,098	39%	71,696	23,577	67%
Texas Eagle	70%	962	291	70%	11,233	6,667	41%	239,780	91,804	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~26 FOI 00502~~ ~~00000007012~~ ~~"UNCLASSIFIED"~~ ~~0/17/2026~~

Train Index Dates Through June 11, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	72,926	1,200,993	607	1,442,101	26,574,378	543

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,111	353,981	116	68,248	7,608,968	90
INFRASTRUCTURE PLANNED	135	6,317	353,981	178	68,585	7,608,968	90
FLEET RELIABILITY	90	8,553	1,200,993	71	235,513	26,574,378	89
TRAIN OPERATIONS	424	53,918	1,200,993	449	1,069,681	26,574,378	403

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/11/2026
Amtrak or Commuter: Amtrak

Location	Target	ITP 06/11/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	52	83.8%	3,465	462	86.7%	75,430	10,300	86.3%
Central Division	88.0%	68	14	79.4%	740	79	89.3%	16,712	1,677	90.0%
Northeast Division	82.0%	102	19	81.4%	1,115	169	84.8%	23,794	3,749	84.2%
Southeast Division	83.0%	73	9	87.7%	778	103	86.8%	17,247	2,510	85.4%
Southwest Division	86.0%	77	10	87.0%	832	111	86.7%	17,677	2,364	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0054 Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/11/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	52	83.8%	3,465	462	86.7%	75,430	10,300	86.3%
Central Division	88.0%	68	14	79.4%	740	79	89.3%	16,712	1,677	90.0%
CDL	95.0%	2	0	100.0%	25	2	92.0%	479	16	96.7%
CHI	86.0%	28	8	71.4%	301	34	88.7%	6,728	787	88.3%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	-	-	-	57	2	96.5%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	22	1	95.5%	498	51	89.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GRR	95.5%	1	0	100.0%	11	0	100.0%	242	8	96.7%
KCY	92.0%	2	0	100.0%	21	1	95.2%	500	37	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	2	66.7%	65	5	92.3%	1,487	91	93.9%
MSP	96.5%	1	0	100.0%	11	0	100.0%	247	4	98.4%
PDX	86.0%	5	1	80.0%	54	13	75.9%	1,243	153	87.7%
PNT	88.0%	3	1	66.7%	32	1	96.9%	647	55	91.5%
PTH	93.0%	1	0	100.0%	11	0	100.0%	242	10	95.9%
QCY	91.0%	2	0	100.0%	22	2	90.9%	495	36	92.7%
SEA	85.0%	8	1	87.5%	88	15	83.0%	1,989	277	86.1%
SPK	90.0%	1	-	100.0%	11	1	90.9%	247	18	92.7%
STL	89.0%	4	1	75.0%	44	2	95.5%	981	86	91.2%
TOL	-	-	-	-	-	-	-	2	2	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	22	2	90.9%	492	14	97.2%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	102	19	81.4%	1,115	169	84.8%	23,794	3,749	84.2%
ALB	88.5%	8	1	87.5%	88	4	95.5%	1,868	156	91.6%
BON	87.5%	5	0	100.0%	55	5	90.9%	1,218	133	89.1%
BOS	85.5%	18	2	88.9%	195	17	91.3%	4,308	538	87.5%
BRK	92.5%	5	0	100.0%	55	8	85.5%	1,209	74	93.9%
BTN	82.0%	1	0	100.0%	11	1	90.9%	240	38	84.2%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	1	1	0.0%	21	3	85.7%	493	48	90.3%
HFD	-	2	0	100.0%	18	0	100.0%	121	7	94.2%
MTR	79.0%	1	1	0.0%	11	2	81.8%	237	43	81.9%
NFL	93.5%	2	0	100.0%	22	0	100.0%	512	22	95.7%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	56	2	96.4%	1,313	218	83.4%
NYP	75.5%	48	13	72.9%	507	119	76.5%	10,186	2,282	77.6%
POR	-	-	-	-	-	-	-	5	3	40.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
SAB	98.0%	1	0	100.0%	10	2	80.0%	241	4	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/11/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	52	83.8%	3,465	462	86.7%	75,430	10,300	86.3%
Northeast Division	82.0%	102	19	81.4%	1,115	169	84.8%	23,794	3,749	84.2%
SPG	92.5%	4	1	75.0%	55	4	92.7%	1,548	84	94.6%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	11	2	81.8%	240	54	77.5%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
Southeast Division	83.0%	73	9	87.7%	778	103	86.8%	17,247	2,510	85.4%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CLT	91.5%	5	2	60.0%	54	10	81.5%	1,248	119	90.5%
GRO	-	2	1	50.0%	8	3	62.5%	25	8	68.0%
HAR	79.5%	13	0	100.0%	131	9	93.1%	2,812	486	82.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	11	1	90.9%	250	32	87.2%
MIA	89.5%	2	0	100.0%	22	5	77.3%	501	51	89.8%
MOE	97.5%	2	0	100.0%	22	0	100.0%	507	7	98.6%
NFK	84.5%	2	2	0.0%	22	9	59.1%	583	101	82.7%
NOL	94.5%	4	0	100.0%	46	2	95.7%	1,069	47	95.6%
NPN	93.0%	2	0	100.0%	22	0	100.0%	475	29	93.9%
PGH	93.0%	1	0	100.0%	11	0	100.0%	252	17	93.3%
PHL	48.0%	5	3	40.0%	53	27	49.1%	1,311	645	50.8%
RGH	95.0%	2	0	100.0%	36	2	94.4%	987	39	96.0%
RNK	83.5%	2	1	50.0%	22	2	90.9%	496	73	85.3%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	11	1	90.9%	249	9	96.4%
SFA	88.0%	1	0	100.0%	11	0	100.0%	250	30	88.0%
WAS	84.0%	28	0	100.0%	296	32	89.2%	6,075	795	86.9%
Southwest Division	86.0%	77	10	87.0%	832	111	86.7%	17,677	2,364	86.6%
ARN	92.0%	1	0	100.0%	10	0	100.0%	252	17	93.3%
BFD	79.0%	7	1	85.7%	75	15	80.0%	1,561	303	80.6%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	1	0	100.0%	11	4	63.6%	268	78	70.9%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	1	0	100.0%	11	2	81.8%	277	34	87.7%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GTA	90.0%	3	1	66.7%	33	13	60.6%	759	96	87.4%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	114	8	93.0%	2,472	247	90.0%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKC	97.0%	1	0	100.0%	11	0	100.0%	248	4	98.4%
OKJ	74.5%	13	4	69.2%	135	28	79.3%	2,682	663	75.3%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	88.5%	16	0	100.0%	168	24	85.7%	3,526	367	89.6%
SAN	90.5%	13	2	84.6%	143	9	93.7%	2,998	273	90.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/11/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/11/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	52	83.8%	3,465	462	86.7%	75,430	10,300	86.3%
Southwest Division	86.0%	77	10	87.0%	832	111	86.7%	17,677	2,364	86.6%
SAS	90.5%	1	0	100.0%	11	2	81.8%	250	25	90.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SJC	89.0%	7	1	85.7%	77	3	96.1%	1,774	169	90.5%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	33	3	90.9%	524	50	90.5%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	48	11	5	54.5%	252	47	81.3%	11	5	54.5%	251	106	57.8%
4	113	11	3	72.7%	252	36	85.7%	11	8	27.3%	252	165	34.5%
5		11	1	90.9%	251	39	84.5%	11	2	81.8%	247	50	79.8%
6	698	11	4	63.6%	250	71	71.6%	11	3	72.7%	250	68	72.8%
7	204	11	0	100.0%	241	28	88.4%	11	5	54.5%	234	53	77.4%
8	87	11	5	54.5%	241	98	59.3%	11	10	9.1%	240	132	45.0%
11		11	3	72.7%	252	45	82.1%	11	4	63.6%	246	49	80.1%
14		11	1	90.9%	253	39	84.6%	11	6	45.5%	251	70	72.1%
19		11	3	72.7%	251	59	76.5%	11	2	81.8%	250	50	80.0%
20		11	1	90.9%	251	17	93.2%	11	3	72.7%	251	40	84.1%
21		11	0	100.0%	248	22	91.1%	11	1	90.9%	247	58	76.5%
22		11	2	81.8%	249	23	90.8%	11	8	27.3%	247	59	76.1%
23	32	11	0	100.0%	254	5	98.0%	11	5	54.5%	253	59	76.7%
24	36	11	0	100.0%	254	14	94.5%	11	3	72.7%	253	33	87.0%
25	45	11	0	100.0%	253	2	99.2%	11	7	36.4%	252	61	75.8%
26		11	0	100.0%	253	3	98.8%	11	6	45.5%	252	44	82.5%
27	290	11	3	72.7%	239	15	93.7%	11	6	45.5%	235	71	69.8%
28		11	7	36.4%	235	53	77.4%	11	6	45.5%	235	42	82.1%
40	160	11	3	72.7%	247	31	87.4%	11	9	18.2%	246	113	54.1%
41	68	11	4	63.6%	247	95	61.5%	11	9	18.2%	245	177	27.8%
42	86	11	0	100.0%	253	18	92.9%	11	1	90.9%	251	40	84.1%
43	137	11	1	90.9%	252	38	84.9%	11	4	63.6%	252	46	81.7%
48	180	11	2	81.8%	251	51	79.7%	11	1	90.9%	251	36	85.7%
49	120	11	3	72.7%	251	64	74.5%	11	1	90.9%	251	47	81.3%
51	93	4	1	75.0%	104	49	52.9%	5	1	80.0%	101	33	67.3%
52		11	0	100.0%	250	30	88.0%	11	2	81.8%	249	54	78.3%
53		11	1	90.9%	250	32	87.2%	11	4	63.6%	249	75	69.9%
55	67	8	1	87.5%	155	5	96.8%	8	4	50.0%	152	31	79.6%
56		9	1	88.9%	156	21	86.5%	9	4	55.6%	154	25	83.8%
58	50	11	2	81.8%	243	14	94.2%	11	8	27.3%	242	54	77.7%
59	38	11	2	81.8%	242	22	90.9%	11	6	45.5%	240	38	84.2%
63	42	11	4	63.6%	254	111	56.3%	11	10	9.1%	250	125	50.0%
64	63	11	2	81.8%	252	61	75.8%	11	8	27.3%	252	76	69.8%
66		11	2	81.8%	251	53	78.9%	11	1	90.9%	249	44	82.3%
67		9	0	100.0%	174	11	93.7%	9	1	88.9%	174	28	83.9%
68	25	11	2	81.8%	254	52	79.5%	11	3	72.7%	254	98	61.4%
69		11	4	63.6%	241	50	79.3%	11	2	81.8%	237	25	89.5%
71	36	11	0	100.0%	249	3	98.8%	11	3	72.7%	248	59	76.2%
72	49	11	2	81.8%	249	24	90.4%	11	4	63.6%	248	46	81.5%
73	26	11	4	63.6%	253	15	94.1%	10	6	40.0%	251	121	51.8%
74	45	10	3	70.0%	252	30	88.1%	10	7	30.0%	250	86	65.6%
75	19	11	1	90.9%	252	11	95.6%	11	6	45.5%	248	116	53.2%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	18	11	0	100.0%	252	25	90.1%	11	3	72.7%	245	101	58.8%
77	22	11	0	100.0%	251	17	93.2%	11	6	45.5%	249	98	60.6%
78	14	11	3	72.7%	249	17	93.2%	11	3	72.7%	248	43	82.7%
79	75	11	3	72.7%	251	50	80.1%	11	7	36.4%	250	73	70.8%
80	100	11	2	81.8%	251	24	90.4%	11	4	63.6%	250	40	84.0%
84	23	9	0	100.0%	149	11	92.6%	9	2	77.8%	147	28	81.0%
85	32	9	1	88.9%	157	16	89.8%	9	5	44.4%	157	55	65.0%
86	34	9	0	100.0%	157	11	93.0%	9	9	0.0%	156	92	41.0%
89	37	11	3	72.7%	249	55	77.9%	11	3	72.7%	247	62	74.9%
90	132	11	1	90.9%	249	9	96.4%	11	6	45.5%	248	32	87.1%
93	29	9	0	100.0%	156	18	88.5%	9	3	66.7%	155	33	78.7%
94		9	3	66.7%	187	45	75.9%	9	3	66.7%	185	64	65.4%
95	31	9	0	100.0%	156	3	98.1%	9	4	55.6%	156	52	66.7%
97	52	11	7	36.4%	251	157	37.5%	11	6	45.5%	249	66	73.5%
98	62	11	2	81.8%	251	19	92.4%	11	5	54.5%	249	70	71.9%
110		8	7	12.5%	153	90	41.2%	8	1	87.5%	150	16	89.3%
111		9	1	88.9%	147	29	80.3%	9	0	100.0%	145	18	87.6%
112		9	0	100.0%	147	15	89.8%	9	0	100.0%	146	16	89.0%
113		9	3	66.7%	78	18	76.9%	9	0	100.0%	77	8	89.6%
119		9	3	66.7%	147	39	73.5%	9	1	88.9%	145	19	86.9%
125	44	9	0	100.0%	157	8	94.9%	9	5	44.4%	157	59	62.4%
129		9	3	66.7%	156	43	72.4%	9	4	55.6%	156	23	85.3%
130		9	1	88.9%	147	15	89.8%	9	0	100.0%	145	12	91.7%
131	30	9	2	77.8%	149	42	71.8%	9	2	77.8%	149	29	80.5%
134		9	1	88.9%	157	19	87.9%	9	0	100.0%	156	23	85.3%
136		9	0	100.0%	157	18	88.5%	8	1	87.5%	155	16	89.7%
137	33	9	1	88.9%	154	29	81.2%	9	3	66.7%	154	46	70.1%
138	31	9	5	44.4%	157	34	78.3%	9	3	66.7%	156	21	86.5%
141		9	0	100.0%	156	3	98.1%	9	1	88.9%	155	27	82.6%
148		9	1	88.9%	156	16	89.7%	9	1	88.9%	154	28	81.8%
151	55	11	6	45.5%	250	81	67.6%	11	3	72.7%	249	77	69.1%
170		9	0	100.0%	152	11	92.8%	9	0	100.0%	151	28	81.5%
171	63	9	0	100.0%	157	10	93.6%	9	5	44.4%	157	53	66.2%
172	25	9	0	100.0%	156	14	91.0%	9	5	44.4%	154	50	67.5%
173	42	9	0	100.0%	152	21	86.2%	9	5	44.4%	151	66	56.3%
174		9	2	77.8%	157	19	87.9%	9	2	77.8%	157	29	81.5%
175	30	9	1	88.9%	157	20	87.3%	9	3	66.7%	157	50	68.2%
176		9	2	77.8%	152	13	91.4%	9	1	88.9%	150	15	90.0%
177		9	1	88.9%	157	23	85.4%	9	1	88.9%	157	43	72.6%
178		9	0	100.0%	157	22	86.0%	8	1	87.5%	155	23	85.2%
179	18	9	2	77.8%	157	16	89.8%	8	6	25.0%	156	54	65.4%
181		9	7	22.2%	153	51	66.7%	9	1	88.9%	151	10	93.4%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		9	2	77.8%	147	27	81.6%	9	0	100.0%	145	14	90.3%
183		9	2	77.8%	156	46	70.5%	9	0	100.0%	154	32	79.2%
184		9	0	100.0%	157	26	83.4%	9	0	100.0%	156	21	86.5%
185		9	1	88.9%	157	35	77.7%	9	0	100.0%	157	10	93.6%
186	73	9	0	100.0%	156	14	91.0%	9	4	55.6%	155	34	78.1%
190		9	1	88.9%	156	55	64.7%	9	2	77.8%	155	36	76.8%
192		9	0	100.0%	154	19	87.7%	9	1	88.9%	154	14	90.9%
193	31	9	6	33.3%	156	66	57.7%	9	7	22.2%	155	72	53.5%
196		9	3	66.7%	156	16	89.7%	9	0	100.0%	155	13	91.6%
197	53	9	4	55.6%	157	67	57.3%	9	6	33.3%	157	49	68.8%
198		9	2	77.8%	89	13	85.4%	8	2	75.0%	88	14	84.1%
230		11	0	100.0%	88	4	95.5%	11	0	100.0%	88	5	94.3%
232	17	11	1	90.9%	254	11	95.7%	11	1	90.9%	254	17	93.3%
233	33	11	2	81.8%	238	51	78.6%	11	9	18.2%	238	62	73.9%
234		11	0	100.0%	254	19	92.5%	11	0	100.0%	254	21	91.7%
235	45	11	4	63.6%	178	25	86.0%	11	4	63.6%	178	34	80.9%
236	21	11	0	100.0%	238	7	97.1%	11	2	81.8%	238	30	87.4%
237	22	10	2	80.0%	252	51	79.8%	10	3	70.0%	250	42	83.2%
238	28	11	2	81.8%	178	19	89.3%	11	4	63.6%	177	14	92.1%
239		11	3	72.7%	253	70	72.3%	11	2	81.8%	252	26	89.7%
240	21	11	0	100.0%	253	18	92.9%	10	4	60.0%	251	32	87.3%
241	39	11	3	72.7%	254	66	74.0%	11	5	54.5%	254	61	76.0%
243		11	1	90.9%	190	52	72.6%	11	0	100.0%	190	24	87.4%
244		11	0	100.0%	238	9	96.2%	11	2	81.8%	238	36	84.9%
245		11	1	90.9%	135	22	83.7%	11	0	100.0%	134	13	90.3%
280	31	11	0	100.0%	254	11	95.7%	11	3	72.7%	254	43	83.1%
281		11	1	90.9%	254	26	89.8%	11	4	63.6%	254	40	84.3%
283		11	4	63.6%	254	56	78.0%	11	1	90.9%	254	44	82.7%
284	28	11	0	100.0%	254	10	96.1%	11	2	81.8%	252	36	85.7%
290	61	11	1	90.9%	254	47	81.5%	11	8	27.3%	252	79	68.7%
291	42	11	5	54.5%	253	61	75.9%	11	7	36.4%	251	45	82.1%
300		11	0	100.0%	238	18	92.4%	11	1	90.9%	236	50	78.8%
301	21	11	0	100.0%	252	8	96.8%	11	2	81.8%	249	45	81.9%
302	Cncld	11	1	90.9%	239	29	87.9%	10	4	60.0%	235	67	71.5%
305	148	11	2	81.8%	242	28	88.4%	11	6	45.5%	238	95	60.1%
306	115	11	1	90.9%	250	14	94.4%	11	6	45.5%	249	64	74.3%
307	563	11	2	81.8%	242	32	86.8%	11	4	63.6%	239	65	72.8%
311	32	11	0	100.0%	252	23	90.9%	10	2	80.0%	247	47	81.0%
316	26	10	0	100.0%	249	16	93.6%	10	5	50.0%	246	57	76.8%
318	278	11	1	90.9%	253	23	90.9%	11	9	18.2%	250	111	55.6%
319	51	11	1	90.9%	254	15	94.1%	11	7	36.4%	252	129	48.8%
329		9	1	88.9%	179	8	95.5%	9	0	100.0%	179	12	93.3%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
330		10	0	100.0%	215	4	98.1%	10	0	100.0%	215	13	94.0%
331		11	1	90.9%	254	27	89.4%	11	1	90.9%	254	37	85.4%
332		11	1	90.9%	254	13	94.9%	11	2	81.8%	254	36	85.8%
334		11	1	90.9%	254	7	97.2%	11	3	72.7%	253	32	87.4%
335	49	11	0	100.0%	254	27	89.4%	11	1	90.9%	252	40	84.1%
336	16	11	0	100.0%	254	8	96.9%	11	2	81.8%	252	21	91.7%
337		11	0	100.0%	254	17	93.3%	11	1	90.9%	250	30	88.0%
338	57	11	1	90.9%	254	38	85.0%	11	4	63.6%	252	74	70.6%
339	56	11	2	81.8%	254	44	82.7%	11	2	81.8%	254	44	82.7%
341	115	11	2	81.8%	244	33	86.5%	10	2	80.0%	240	33	86.3%
342	28	11	2	81.8%	254	21	91.7%	11	2	81.8%	252	46	81.7%
350	72	11	0	100.0%	235	15	93.6%	11	9	18.2%	230	124	46.1%
351		11	1	90.9%	237	23	90.3%	11	1	90.9%	236	63	73.3%
352		11	0	100.0%	222	17	92.3%	11	3	72.7%	217	66	69.6%
353	26	11	0	100.0%	197	12	93.9%	11	3	72.7%	191	33	82.7%
354	230	11	3	72.7%	235	22	90.6%	11	3	72.7%	231	79	65.8%
355	No OS	10	0	100.0%	248	26	89.5%	10	5	50.0%	242	81	66.5%
364	48	11	2	81.8%	243	52	78.6%	11	6	45.5%	237	76	67.9%
365	31	11	0	100.0%	242	10	95.9%	11	5	54.5%	240	77	67.9%
370	No OS	11	1	90.9%	245	30	87.8%	10	4	60.0%	240	58	75.8%
371		11	0	100.0%	242	8	96.7%	11	2	81.8%	241	26	89.2%
380		11	0	100.0%	241	23	90.5%	11	1	90.9%	241	43	82.2%
381		11	1	90.9%	254	10	96.1%	11	3	72.7%	254	41	83.9%
382	147	11	2	81.8%	254	13	94.9%	11	7	36.4%	254	78	69.3%
383	114	11	0	100.0%	243	23	90.5%	11	4	63.6%	241	91	62.2%
390	27	11	0	100.0%	236	15	93.6%	11	3	72.7%	235	55	76.6%
391	18	11	0	100.0%	239	6	97.5%	11	4	63.6%	236	50	78.8%
392	207	11	1	90.9%	253	5	98.0%	11	5	54.5%	251	71	71.7%
393		11	0	100.0%	254	15	94.1%	11	4	63.6%	252	68	73.0%
417	54	9	2	77.8%	167	34	79.6%	9	1	88.9%	158	15	90.5%
448	218	11	2	81.8%	184	36	80.4%	11	5	54.5%	182	63	65.4%
449	139	11	1	90.9%	182	28	84.6%	11	3	72.7%	182	32	82.4%
470		10	3	70.0%	180	34	81.1%	9	2	77.8%	174	23	86.8%
471		9	0	100.0%	170	5	97.1%	9	0	100.0%	170	2	98.8%
473		9	0	100.0%	176	13	92.6%	9	0	100.0%	173	8	95.4%
474		9	2	77.8%	170	46	72.9%	9	6	33.3%	159	40	74.8%
478		9	0	100.0%	168	26	84.5%	9	2	77.8%	166	18	89.2%
479	30	9	2	77.8%	175	27	84.6%	9	2	77.8%	173	18	89.6%
486	52	9	2	77.8%	179	27	84.9%	9	3	66.7%	173	45	74.0%
494		9	2	77.8%	180	33	81.7%	9	0	100.0%	174	41	76.4%
495		9	0	100.0%	165	3	98.2%	9	0	100.0%	163	3	98.2%
500		10	0	100.0%	245	15	93.9%	10	1	90.0%	243	29	88.1%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
502		11	1	90.9%	252	14	94.4%	11	1	90.9%	249	54	78.3%
503		11	0	100.0%	250	20	92.0%	11	2	81.8%	244	61	75.0%
504		11	0	100.0%	254	16	93.7%	11	5	54.5%	252	75	70.2%
505		11	2	81.8%	252	32	87.3%	11	6	45.5%	249	68	72.7%
506		11	1	90.9%	249	34	86.3%	10	3	70.0%	244	38	84.4%
507	22	11	2	81.8%	254	30	88.2%	11	4	63.6%	254	77	69.7%
508		11	1	90.9%	249	39	84.3%	11	5	54.5%	246	57	76.8%
509		11	1	90.9%	251	12	95.2%	11	6	45.5%	251	60	76.1%
511		11	1	90.9%	246	21	91.5%	11	4	63.6%	245	45	81.6%
516	39	11	1	90.9%	246	25	89.8%	11	8	27.3%	245	111	54.7%
517		11	1	90.9%	254	8	96.9%	10	8	20.0%	250	97	61.2%
518	37	11	4	63.6%	254	33	87.0%	11	10	9.1%	252	168	33.3%
519		11	1	90.9%	246	9	96.3%	11	3	72.7%	244	60	75.4%
520		9	3	66.7%	137	21	84.7%	9	0	100.0%	134	8	94.0%
521		9	1	88.9%	175	7	96.0%	9	1	88.9%	175	21	88.0%
522		9	3	66.7%	175	31	82.3%	9	1	88.9%	172	17	90.1%
523		9	0	100.0%	175	6	96.6%	9	2	77.8%	174	22	87.4%
524		9	0	100.0%	175	11	93.7%	8	2	75.0%	173	20	88.4%
525		9	0	100.0%	173	10	94.2%	9	1	88.9%	171	13	92.4%
526		9	3	66.7%	149	26	82.6%	9	1	88.9%	147	12	91.8%
527		9	1	88.9%	175	7	96.0%	9	1	88.9%	175	30	82.9%
528		9	1	88.9%	175	14	92.0%	9	0	100.0%	174	29	83.3%
529	20	9	0	100.0%	175	10	94.3%	9	2	77.8%	174	44	74.7%
530		9	0	100.0%	129	12	90.7%	9	1	88.9%	129	23	82.2%
531		9	1	88.9%	149	11	92.6%	9	1	88.9%	149	11	92.6%
532	40	9	2	77.8%	175	37	78.9%	9	3	66.7%	175	26	85.1%
534	88	9	0	100.0%	134	19	85.8%	9	1	88.9%	133	12	91.0%
535		9	2	77.8%	162	23	85.8%	9	0	100.0%	157	20	87.3%
536		9	0	100.0%	175	43	75.4%	9	0	100.0%	172	35	79.7%
537		9	2	77.8%	146	15	89.7%	9	1	88.9%	141	12	91.5%
538		9	0	100.0%	175	21	88.0%	8	1	87.5%	174	33	81.0%
539		9	4	55.6%	129	16	87.6%	9	5	44.4%	129	57	55.8%
540		9	3	66.7%	175	35	80.0%	9	1	88.9%	168	17	89.9%
541		9	2	77.8%	174	19	89.1%	8	2	75.0%	170	33	80.6%
542		9	0	100.0%	174	20	88.5%	9	2	77.8%	172	31	82.0%
543	29	9	0	100.0%	175	15	91.4%	9	1	88.9%	175	46	73.7%
544		9	1	88.9%	173	20	88.4%	9	0	100.0%	170	14	91.8%
545		9	0	100.0%	175	12	93.1%	9	1	88.9%	173	19	89.0%
547		9	2	77.8%	175	35	80.0%	9	2	77.8%	175	42	76.0%
548		9	0	100.0%	175	20	88.6%	9	1	88.9%	174	14	92.0%
549	No OS	9	1	88.9%	170	22	87.1%	8	2	75.0%	165	16	90.3%
550		9	0	100.0%	129	13	89.9%	9	3	66.7%	129	26	79.8%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
551		9	3	66.7%	171	18	89.5%	9	2	77.8%	163	16	90.2%
562		11	0	100.0%	246	18	92.7%	11	0	100.0%	243	27	88.9%
564	40	11	2	81.8%	246	15	93.9%	11	2	81.8%	238	28	88.2%
566		11	0	100.0%	244	16	93.4%	11	0	100.0%	241	30	87.6%
567		11	1	90.9%	131	7	94.7%	11	0	100.0%	129	5	96.1%
572		11	0	100.0%	241	21	91.3%	11	4	63.6%	236	56	76.3%
573	22	11	1	90.9%	244	36	85.2%	11	3	72.7%	237	40	83.1%
579		11	0	100.0%	131	8	93.9%	11	1	90.9%	126	22	82.5%
580		11	0	100.0%	246	11	95.5%	11	1	90.9%	242	20	91.7%
581		11	2	81.8%	246	40	83.7%	11	1	90.9%	244	46	81.1%
584		11	0	100.0%	130	13	90.0%	11	7	36.4%	127	70	44.9%
587		11	0	100.0%	241	14	94.2%	11	1	90.9%	232	31	86.6%
588		11	0	100.0%	131	9	93.1%	11	1	90.9%	131	18	86.3%
591	39	11	1	90.9%	245	16	93.5%	11	1	90.9%	240	24	90.0%
593		11	0	100.0%	240	33	86.3%	11	0	100.0%	224	24	89.3%
595		11	1	90.9%	242	39	83.9%	11	0	100.0%	240	40	83.3%
600		9	0	100.0%	184	9	95.1%	9	0	100.0%	182	14	92.3%
601		9	0	100.0%	167	70	58.1%	9	0	100.0%	164	23	86.0%
605		9	7	22.2%	174	112	35.6%	9	0	100.0%	170	19	88.8%
607		9	2	77.8%	183	21	88.5%	9	0	100.0%	180	21	88.3%
609		9	0	100.0%	174	22	87.4%	9	0	100.0%	173	14	91.9%
622		8	0	100.0%	93	29	68.8%	8	0	100.0%	92	5	94.6%
626		9	0	100.0%	88	11	87.5%	9	1	88.9%	86	15	82.6%
639		9	3	66.7%	155	36	76.8%	9	0	100.0%	154	18	88.3%
640		9	0	100.0%	174	6	96.6%	9	3	66.7%	172	73	57.6%
641		9	2	77.8%	156	30	80.8%	9	1	88.9%	156	23	85.3%
642		9	1	88.9%	172	7	95.9%	9	0	100.0%	171	22	87.1%
643		9	0	100.0%	186	39	79.0%	9	0	100.0%	184	31	83.2%
644		9	0	100.0%	178	26	85.4%	9	1	88.9%	176	45	74.4%
645	22	9	2	77.8%	186	37	80.1%	9	3	66.7%	184	36	80.4%
646		9	0	100.0%	175	45	74.3%	9	0	100.0%	173	83	52.0%
647		9	0	100.0%	186	31	83.3%	9	1	88.9%	185	40	78.4%
648		9	1	88.9%	182	48	73.6%	9	0	100.0%	182	31	83.0%
649		9	1	88.9%	187	32	82.9%	9	0	100.0%	184	31	83.2%
650	13	9	1	88.9%	186	39	79.0%	9	2	77.8%	183	28	84.7%
651		9	1	88.9%	186	16	91.4%	9	2	77.8%	184	38	79.3%
652		9	1	88.9%	187	26	86.1%	9	1	88.9%	183	32	82.5%
653		9	1	88.9%	175	29	83.4%	9	2	77.8%	173	33	80.9%
654		9	0	100.0%	176	36	79.5%	9	0	100.0%	173	16	90.8%
655	12	9	3	66.7%	184	66	64.1%	9	4	55.6%	182	64	64.8%
656		9	3	66.7%	186	43	76.9%	9	0	100.0%	185	21	88.6%
657		9	0	100.0%	175	25	85.7%	9	2	77.8%	174	25	85.6%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
658		9	1	88.9%	186	31	83.3%	9	1	88.9%	184	30	83.7%
680		9	1	88.9%	180	8	95.6%	9	0	100.0%	179	22	87.7%
681		9	0	100.0%	180	12	93.3%	9	4	55.6%	175	66	62.3%
682		9	0	100.0%	179	3	98.3%	9	0	100.0%	179	31	82.7%
683		9	0	100.0%	162	15	90.7%	9	3	66.7%	161	45	72.0%
684		9	3	66.7%	161	22	86.3%	9	2	77.8%	161	35	78.3%
685		9	2	77.8%	176	27	84.7%	9	1	88.9%	174	41	76.4%
686		9	1	88.9%	181	31	82.9%	9	1	88.9%	181	35	80.7%
687		9	0	100.0%	181	29	84.0%	9	2	77.8%	180	29	83.9%
688		9	3	66.7%	179	8	95.5%	9	2	77.8%	179	29	83.8%
689		5	0	100.0%	135	17	87.4%	5	1	80.0%	134	18	86.6%
701		11	1	90.9%	186	16	91.4%	11	2	81.8%	183	15	91.8%
702		11	1	90.9%	253	27	89.3%	10	1	90.0%	251	52	79.3%
703	19	11	7	36.4%	254	69	72.8%	11	5	54.5%	253	63	75.1%
704		11	2	81.8%	185	29	84.3%	11	1	90.9%	181	35	80.7%
710		11	1	90.9%	254	65	74.4%	11	5	54.5%	250	65	74.0%
711		11	2	81.8%	245	24	90.2%	11	2	81.8%	229	38	83.4%
712	22	11	3	72.7%	251	63	74.9%	11	5	54.5%	243	77	68.3%
713	39	9	0	100.0%	135	13	90.4%	9	4	55.6%	122	54	55.7%
714	123	11	4	63.6%	137	48	65.0%	10	7	30.0%	128	49	61.7%
715		11	1	90.9%	253	53	79.1%	9	5	44.4%	236	114	51.7%
716	No OS	11	2	81.8%	254	100	60.6%	11	5	54.5%	249	95	61.8%
717		11	3	72.7%	240	55	77.1%	8	3	62.5%	223	61	72.6%
718		11	4	63.6%	254	123	51.6%	11	3	72.7%	252	81	67.9%
719		11	1	90.9%	254	80	68.5%	11	2	81.8%	242	66	72.7%
757	48	11	1	90.9%	39	2	94.9%	11	1	90.9%	39	2	94.9%
761		11	1	90.9%	250	10	96.0%	11	1	90.9%	247	33	86.6%
765		11	1	90.9%	250	25	90.0%	11	0	100.0%	250	35	86.0%
769		11	0	100.0%	250	23	90.8%	11	2	81.8%	244	45	81.6%
770	17	11	1	90.9%	250	21	91.6%	11	3	72.7%	248	65	73.8%
774	83	11	0	100.0%	250	16	93.6%	11	2	81.8%	249	51	79.5%
777		11	0	100.0%	135	9	93.3%	11	1	90.9%	135	31	77.0%
782		11	11	0.0%	135	39	71.1%	11	1	90.9%	130	11	91.5%
785		11	1	90.9%	250	14	94.4%	11	1	90.9%	250	40	84.0%
786		11	2	81.8%	39	7	82.1%	11	4	63.6%	38	16	57.9%
790		11	1	90.9%	250	25	90.0%	11	0	100.0%	248	26	89.5%
794		11	1	90.9%	250	30	88.0%	11	3	72.7%	248	54	78.2%
821		11	0	100.0%	248	4	98.4%	11	5	54.5%	248	98	60.5%
822	31	11	2	81.8%	250	14	94.4%	11	5	54.5%	248	109	56.0%
1333		11	0	100.0%	250	26	89.6%	11	5	54.5%	247	84	66.0%
1340	61	11	0	100.0%	249	4	98.4%	11	2	81.8%	249	41	83.5%
2102		9	3	66.7%	33	11	66.7%	9	1	88.9%	32	3	90.6%

Amtrak On Time Performance

Trains Arriving Through: 6/11/2026

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2103		9	1	88.9%	97	10	89.7%	9	2	77.8%	96	8	91.7%
2104		9	0	100.0%	123	9	92.7%	9	0	100.0%	121	9	92.6%
2107	33	9	3	66.7%	154	29	81.2%	9	1	88.9%	151	19	87.4%
2108		9	1	88.9%	154	24	84.4%	9	0	100.0%	148	16	89.2%
2110		9	1	88.9%	33	2	93.9%	9	1	88.9%	33	5	84.8%
2113		9	0	100.0%	33	2	93.9%	9	0	100.0%	33	4	87.9%
2115		9	1	88.9%	33	3	90.9%	9	1	88.9%	33	4	87.9%
2121		9	1	88.9%	150	27	82.0%	9	2	77.8%	148	25	83.1%
2122		9	0	100.0%	152	16	89.5%	9	2	77.8%	152	14	90.8%
2123		9	1	88.9%	33	4	87.9%	9	3	66.7%	33	10	69.7%
2124		9	1	88.9%	126	20	84.1%	9	1	88.9%	125	11	91.2%
2126		9	3	66.7%	91	22	75.8%	9	0	100.0%	90	18	80.0%
2150		9	0	100.0%	147	22	85.0%	9	1	88.9%	144	65	54.9%
2151		9	2	77.8%	96	6	93.8%	9	3	66.7%	94	26	72.3%
2155	64	9	1	88.9%	156	14	91.0%	9	5	44.4%	153	87	43.1%
2159		9	0	100.0%	149	9	94.0%	9	3	66.7%	148	43	70.9%
2162	26	9	1	88.9%	156	12	92.3%	9	4	55.6%	152	75	50.7%
2163	30	9	0	100.0%	156	17	89.1%	9	4	55.6%	150	64	57.3%
2166	47	9	0	100.0%	152	13	91.4%	9	4	55.6%	150	36	76.0%
2167		9	0	100.0%	146	18	87.7%	9	2	77.8%	146	34	76.7%
2170	28	9	0	100.0%	126	38	69.8%	9	7	22.2%	122	53	56.6%
2171		9	1	88.9%	83	8	90.4%	9	0	100.0%	80	17	78.8%
2172		9	0	100.0%	128	10	92.2%	9	0	100.0%	127	28	78.0%
2190		9	0	100.0%	155	23	85.2%	9	0	100.0%	153	21	86.3%
2192	46	9	3	66.7%	81	17	79.0%	9	1	88.9%	81	4	95.1%
2193		9	2	77.8%	154	23	85.1%	9	1	88.9%	152	45	70.4%

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2107	WAS	33	ENG	32	ENG	32	XPV-BAL	AM	Other electrical failure, 2123 NG NP, REPORTED MULTIPLE FAULTS AND CODES, REPORTED TECH ON BOARD. STOPPED ON NO. 3 TRACK MP 88.	
2155	WAS	64	ENG	34	ENG	34	BOS-BOS	AM	Other electrical failure, 2116 NG NP, Engine Issues	
2162	BOS	26	CTI	17	DMW	11	STM-NHV	MN	Hold for defect repair Control Point, East Norwalk	
2163	WAS	30	DSR	14	MTI	8	NYP-NWK	AM	Disabled train ahead, Other, NEWARK, HELD A/C AM5 AHD WITH DOOR ISSUES	
2166	BOS	47	CAR	12	CAR	12	WIL-WIL	AM	Heat / AC, ENTIRE CONSIST, NO AIR CONDITIONING IN THE TRAIN. RECYCLED IN THE STATION AND SOLVED THE PROBLEM	
2170	BOS	28	ENG	14	ENG	12	NYP-NYP	AM	Other electrical failure, 2115, MECHANICAL ISSUES IN STATION A/C TRUNK HUNTING FAULT ISSUES AND AC ISSUES	
2192	BOS	46	ENG	47	ENG	47	NYP-NYP	AM	Other electrical failure, 2036, MCB ISSUES ON PC2036	
84	NYP	23	OTH	15	SMW	5	BAL-ABE	AM	Diversions around M/W work, Control Point, Gunpow, Opr No.1 trk a/c No.2 trk O/O/S	
85	WAS	32	CTI	23	CTI	15	NHV-BRP	MN	Follow mnrr, Control Point, 271, Control Point, 261, Control Point, 257	
86	BOS	34	CTI	41	CTI	18	WDB-ALX	CS	Follow vre310, Other, cfp90.0-105.0	
93	NFK	29	CTI	38	CTI	14	ALX-QAN	CS	Follow vre, 313, Milepost, 101.1, 79.0	
95	NFK	31	DSR	40	DSR	34	X3V-NFK	NS	Per bulletin Milepost w/Letters, N. 52.0, N22.2, 25, both	
125	NPN	44	WTR	30	WTR	10	FBG-ASD	CS	Heat order Other, FBG to ASD	
131	WAS	30	CTP	20	CTP	9	NYP-NWK	AM	Delay due to mechanical problems on a Commuter train, XPT-NWK NJ3841 W/CAB SIGNAL PROBLEM AHD	
137	WAS	33	MTI	33	CTI	16	BRP-STM	MN	Follow mn, Milepost w/Letters, bro, stm	
138	NYP	31	WTR	64	WTR	36	NFK-X3V	NS	Heat order Milepost, 32.0, 52.0	
151	RNK	55	CTI	38	CTI	33	ALX-MSS	NS	Meet VRE, Control Point, James	
171	RNK	63	FTI	69	FTI	69	CVS-LYH	NS	Meet Had to drop off engineers for 66 and waited on 2 freights before we could proceed., 28R, Control Point, mclvor	
172	BOS	25	OTH	13	PTI	6	PHL-PHL	AM	Follow, 2104, Control Point, PHL	

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
173	WAS	42	DSR	20	DSR	10	NHV-BRP	MN	Per bulletin Milepost w/Letters, NHV, BRP, 30, 1
175	WAS	30	CTI	36	CTI	28	NHV-STM	MN	Follow metro, Other, entoute
179	PHL	18	SMW	12	SMW	10	NYP-NWK	AM	Scheduled in track usage program, Other, XBH-XHU, SINGLE TRACKING ON NO.2 TRK A/C 3 TRK O/O/S LACK TO HUDSON
186	PHL	73	FTI	73	FTI	30	ASD-FBG	CS	Follow M408, Milepost, 29.6, 59.3
193	WAS	31	OTH	11	ITI	8	NYP-NYP	AM	Service, turn, or wye train, 184, LATE TURN OFF AM184
197	WAS	53	ENG	58	ENG	35	BWI-XNY	AM	Traction motor, 665 EX ES, 603 EX ES, MCB OPENED AGAIN AT MP 108.3
417	NHV	54	ENG	30	ENG	30	SPG-WNL	AM	Radio failure, 46 DX BD, no radio, dispatcher couldn't give Form D until AM417 called fo the Stop & Protect for MP 48.5
479	NHV	30	ITI	23	ITI	23	GFD-GFD	MA	Late coming in 486
486	GFD	52	FTI	14	FTI	14	SPG-HLK	MA	Cross Traffic Control Point, 98, csx
79	CLT	75	WTR	81	WTR	22	PTB-RMT	CS	Heat order Other, rmt
80	NYP	100	WTR	62	DSR	20	BNC-DNC	NS	Per bulletin Milepost, 24.5, 24.6, 50, 1, Milepost, 25.7, 25.8, 10, 1, Milepost, 30.1, 30.3, 25, 1, Milepost, 32.8, 33.0, 25, 1, Milepost, 34.0, 34.2, 10, 1, Milepost, 41.0, 41.2, 10, 1
645	HAR	22	DET	10	CTP	10	NYP-NWK	AM	Delay due to mechanical problems on a Commuter train, XPT-NWK NJ3841 W/CAB SIGNAL PROBLEM AHD
650	NYP	13	DMW	11	DMW	11	PHL-XHM	AM	Hold for defect repair, Control Point, HOLMES, T.O.L. NO 3 TRK AT HOLMES. DEFECTIVE INSULATED JOINT
655	HAR	12	PTI	17	PTI	10	NWK-TRE	AM	Follow, AM137, Other, AM137
63	TWO	42	RTE	14	RTE	8	CRT-POU	MN	Dispatcher hold Control Point, 39
64	NYP	63	CTI	39	SVS	24	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train
68	NYP	25	PTI	44	WTR	39	SLQ-RSP	CN	Heat order Milepost, 29, 0
232	NYP	17	CTI	18	CTI	18	CRT-XSD	MN	Meet mnrr, 728, mnrr, 834, Control Point, 12
233	ALB	33	HLD	14	HLD	12	NYP-XSD	AM	Passenger and/or baggage, STOPPED NORTH OF EMPIRE ACCOUNT PASSENGER LEFT CHILD ON PLATFORM

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
235	ALB	45	CTI	17	ITI	17	NYP-NYP	AM	Service, turn, or wye train, 238, LATE TURN OFF AM238
236	NYP	21	RTE	28	RTE	28	POU-CRT	MN	Dispatcher hold Wait on 2 trains 69 and 856, Other, garrison
237	ALB	22	PTI	14	PTI	11	HUD-ALB	AM	Meet 64, Control Point, 124
238	NYP	28	DMW	29	DMW	29	POU-CRT	MN	Held for or routed around MW work or equipment Milepost, 41.4, 40
240	NYP	21	DMW	9	DMW	9	POU-CRT	MN	Waiting for MW clearance Milepost, 41.4, 40.0
241	ALB	39	RTE	24	RTE	20	CRT-POU	MN	Reverse mp41 to to cp 39 1-2 track per dispatcher Control Point, 39
280	NYP	31	DBS	23	DBS	23	XSV-SYR	CS	Debris blocking track (no debris strike) Tree fouling Tk 2. Locomotive engineer stopped short after being warned by Westbound freight. Assessed situation - tree would've been difficult/unsafe to pass. Spoke w/CSX NF Dispr and rec'd permission to backup to CP 300 and safely pass tree on Tk 1., Milepo
284	NYP	28	FTI	41	CTI	34	POU-CRT	MN	Cross Traffic Single track, mn, Control Point, 46
290	NYP	61	CTI	60	CTI	60	POU-CRT	MN	Meet man, Milepost, 46, 46
291	BTN	42	DMW	24	DMW	24	CRT-POU	MN	Waiting for MW clearance Milepost, 40.0, 41.4
48	NYP	180	ENG	101	ENG	101	ALB-ALB	AM	Failure of diesel engine 715
49	CHI	120	ENG	102	ENG	97	ALB-ALB	AM	Set out defective locomotive 118
448	BOS	184	OTH	1	OTH	1	BBY-BOS	AM	Lost time - N.A.R., No delay.
449	ALB	139	PTI	76	PTI	76	PIT-XRD	CS	Meet While we waited at CP 176 a westbound freight passed us, then waited for Amtrak 448 passed going Eastbound, Amtrak 448, Control Point, 176
42	NYP	86	ENG	82	ENG	82	PHL-PHL	AM	HEP, 656 EX ES, NO HEP ON THE 656; SWAPPED TO THE 633
43	PGH	137	DSR	72	WTR	57	LEW-HGD	NS	High winds Dispatcher stop order for 5:05 pm due to high winds. All stopped at PT 193.5, Milepost, 193.5, 193.5

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
71	CLT	36	DSR	38	DSR	25	DNC-BNC	NS	Per bulletin Milepost w/Letters, 41.2NC, 41.0NC, 10, Main 1, Milepost w/Letters, 34.2NC, 34.0NC, 10, Main 1, Milepost w/Letters, 33.0NC, 32.8NC, 25, Main 1, Milepost w/Letters, 30.3NC, 30.1NC, 25, Main 1, Milepost w/Letters, 25.8NC, 25.7NC, 10, Main 1, Milepost w/Letters, 24.6NC, 24.5NC, 50, Main 1
72	GRO	49	ITI	32	ITI	32	CLT-CLT	NS	Service, turn, or wye train 71, Late arrival of 71 that becomes 72
73	CLT	26	ITI	30	ITI	30	GRO-GRO	NS	Service, turn, or wye train 72
74	RGH	45	DSR	28	DSR	22	BNC-DNC	NS	Per bulletin Milepost w/Letters, 25.7NC, 26.8NC, 25, 1, Milepost w/Letters, 30.1NC, 30.3NC, 25, 1, Milepost w/Letters, 32.8NC, 33.0NC, 25, 1, Milepost w/Letters, 34.0NC, 34.2NC, 10, 1, Milepost w/Letters, 36.1NC, 36.2NC, 10, 1, Milepost w/Letters, 36.7NC, 36.8NC, 10, 1, Milepost w/Letters, 41.0NC, 4
75	CLT	19	TEN	12	TEN	12	GRO-HPT	NS	Air / Brake NC1893
76	RGH	18	DSR	30	DSR	30	GRO-DNC	NS	Per bulletin Milepost, 5.8, 5.9, 10, m, Milepost, 7.7, 7.8, 25, m, Milepost, 25.7, 25.8, 22, m, Milepost, 30.1, 30.3, 25, m, Milepost, 32.8, 33.0, 25, m, Milepost, 34.0, 34.2, 10, m, Milepost, 36.1, 36.2, 10, m, Milepost, 36.7, 36.8, 10, m, Milepost, 41.0, 41.2, 25, m
77	CLT	22	DSR	27	PTI	24	BNC-GRO	NS	Meet #Amt74, Control Point, Mccleansville
78	RGH	14	DSR	22	DSR	17	BNC-DNC	NS	Per bulletin Milepost w/Letters, 25.7 NC, 25.8 NC, 25, 1, Milepost w/Letters, 30.1 NC, 30.3 NC, 25, 1, Milepost w/Letters, 32.8 NC, 33.0 NC, 25, 1, Milepost w/Letters, 34.0 NC, 34.2 NC, 10, 1, Milepost w/Letters, 36.1 NC, 36.2 NC, 25, 1, Milepost w/Letters, 36.7 NC, 36.8 NC, 10, 1, Milepost w/Letter
89	SAV	37	WTR	49	WTR	14	XDJ-RVR	CS	Heat order Other, RF&P Sub
90	NYP	132	WTR	83	PTI	35	XDJ-ALX	CS	Follow 186, Milepost w/Letters, cfp61.1, cfp105.1
97	MIA	52	DSR	41	WTR	16	SBG-XDY	CS	Heat order Milepost w/Letters, SX867.3, SX963.3
98	NYP	62	FTI	62	FTI	31	RVR-FBG	CS	Follow IO32, Milepost w/Letters, CFP 14.8, CFP 58.9
55	WAS	67	CTI	37	WTR	21	SPG-WNL	AM	Heat order, Milepost w/Letters, SPG, WNL, followed heat patrol

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
40	CHI	160	FTI	102	FTI	59	TOL-WTI	NS	Follow 13Q, Milepost, 304.0, 350.0
41	MIA	68	WTR	77	FTI	28	SOB-EKH	NS	Meet 277, Control Point, 435.0
23	NOL	32	DMW	46	DMW	46	BAS-XNO	CS	Hold for defect repair Problems with the bridge, Bridge, Industrial Canal
24	MOE	36	FTI	74	FTI	48	PAG-MOE	CS	Follow m606, Control Point, 678
25	NOL	45	FTI	57	FTI	35	BAS-XNO	CS	Follow x60511, Milepost, 801.5, 803.6
6	CHI	698	WTR	661	WTR	578	OMA-CRN	BN	Storm Wind restrictions, flash floods and tornado warnings, Milepost, 16.9, 393.0
529	SJC	20	TSV	20	TSV	20	SAC-SAC	UP	Water, commissary, toilet/trash dumping
532	SAC	40	PTI	32	PTI	32	RIC-MTZ	UP	714 broke down, was waiting for instructions to shove back. Was instructed to shove back and was about to shove back until plans changed and was instructed to carry with normal movement 714, Control Point, costa
534	SAC	88	TEN	31	TEN	24	SUI-FFV	UP	Loading problem Engine lost load and we were stuck at MP 53.5 letting engine to cool down before proceeding to FFV, C2102
543	SJC	29	CTI	30	CTI	30	GAC-SCC	UP	Meet ACE, Ace 8, Control Point, CO044
549	OKJ	No OS Rpt	MBO	8	MBO	8	SUI-MTZ	UP	For maritime traffic Control Point, park
51	CHI	93	DSR	43	PTI	40	MSS-CLP	NS	Meet 178, Control Point, Remington
507	EUG	22	DCS	31	DCS	23	XNI-OLW	BN	Power switch failure Hand line power switch and two frogs for mvmt. M2 - M1, Control Point, Nisqually
516	VAC	39	DMW	28	DMW	14	X8B-XF2	BN	Held for or routed around MW work or equipment Maintenance window until noon., Bridge, Fraser River Bridge
518	VAC	37	FTI	20	FTI	20	EDM-EVR	BN	Meet Train was at Snohomish Jct when stopped. Dispatcher said it was "high priority" and was instructed from above her, Control Point, Howarth Park, BNSF 3783, Z
58	CHI	50	FTI	103	FTI	37	FTN-CDL	CC	Meet Siding, anna, AMTK 59
59	NOL	38	DSR	80	FTI	46	KKI-CHM	CC	Follow cn 3878, Milepost, 87.9, 103.6
7	SEA	204	FTI	235	FTI	63	WTN-WPT	BN	Meet BNSF 1442E, BNSF 6049E, Siding, Snowden
8	CHI	87	FTI	159	POL	45	SPK-SPK	BN	Removal of passenger by police
27	PDX	58	DMW	66	DMW	32	BNG-VAN	BN	Follow MOW Meloans to Skamaina Siding, Meloans, Siding, Skamaina

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	31	FTI	38	FTI	19	GLE-ADM	BN	Meet bn 8093, Milepost, 423, 425
335	MKE	49	FTI	32	FTI	32	GLN-XRO	CP	640 in emergency at A-20. Blocking tracks as they are unable to move. Tracks blocked while 640's crew inspects and does their break tests., 640, Control Point, A-20
336	CHI	16	FTI	19	FTI	14	XRO-GLN	ME	Follow Other, GLN, CPKC 640
338	CHI	57	ITI	35	ITI	35	MKE-MKE	CP	Service, turn, or wye train 335
339	MKE	56	ITI	33	ITI	33	CHI-CHI	AM	Service, turn, or wye train 338
341	MKE	115	ENG	62	ITI	45	CHI-CHI	AM	Service, turn, or wye train 1340
342	CHI	28	ITI	23	ITI	23	MKE-MKE	CP	Service, turn, or wye train 339
350	PNT	72	PTI	60	ENG	32	DOA-DOA	AM	Onboard HBD alarm ID4609
353	CHI	26	DMW	17	DMW	17	XPI-HMI	NS	Hold for defect repair Control Point, 503
354	PNT	230	ITI	125	ITI	125	CHI-CHI	AM	Service, turn, or wye train 353
355	CHI	No OS Rpt	DSR	20	DSR	13	ARB-JXN	MI	Per bulletin Milepost, 40.5, 41.8, 30, m, Milepost, 58.9, 61.0, 30, m, Milepost, 65.2, 66, 30, m
364	PTH	48	DSR	44	DSR	28	BTL-LNS	CC	Per bulletin Milepost, 175.3, 175.45, 25, MAIN ONE, Milepost, 176.86, 176.86, 25, MAIN TWO, Milepost, 177.1, 177.1, 25, MAIN ONE, Milepost, 180.91, 181.34, 30, MAIN TWO, Milepost, 181.99, 182.85, 30, MAIN TWO, Milepost, 182.7, 183.47, 60, MAIN ONE, Milepost, 183.52, 184, 60, MAIN ONE, Milepost, 184.
365	CHI	31	DSR	41	DSR	20	LNS-BTL	CC	Per bulletin Milepost, 221.42, 221.42, 30, MAIN, Milepost, 219, 218.5, 30, MAIN, Milepost, 216.1, 215.79, 60, MAIN, Milepost, 214.96, 214.96, 25, MAIN TWO, Milepost, 210.40, 210.40, 30, MAIN TWO, Milepost, 208.91, 208.91, 40, MAIN TWO, Milepost, 208.91, 208.91, 40, MAIN TWO, Milepost, 205.99, 205.99
370	GRR	No OS Rpt							
564	SAN	40	CTI	31	ITI	23	LAX-LAX	SC	Train late arriving from yard 564
573	LAX	22	CTI	7	PTI	7	OLT-SOL	SN	Meet Amtk 566, Control Point, Torrey
591	LAX	39	SYS	19	SYS	19	SAN-SAN	SN	PTC- IETMS incorrect consist PTC issue, contacted CNOC Mechanical for support. Metrolink River corrected incorrect consist., Other, San Diego Santa Fe Depot
757	SLO	48	RTE	42	RTE	42	GTA-X3G	UP	Dispatcher hold Control Point, no Ellwood

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
770	SAN	17	PTI	47	PTI	20	CPN-VEC	UP	Meet 757, Siding, seaciff
774	SAN	83	POL	71	POL	71	GUA-LPS	UP	SpaceX launch at Vandenberg.
703	SAC	19	PTI	17	TEN	8	BFD-BFD	BN	Headlights did not work/ Bakersfield mechanical replaced front headlights. C2014
712	BFD	22	PTI	19	PTI	13	HNF-COC	BN	Meet 717, Control Point, Wagner
713	OKJ	39	DCS	29	DCS	26	MTZ-RIC	UP	Restrictive signal(s) from unknown cause Restricted Proceed, Milepost, 27.5, 20.8
714	BFD	123	TEN	92	TEN	92	RIC-MTZ	UP	HEP C2005
716	BFD	No OS Rpt	TEN	54	TEN	54	MTZ-MTZ	UP	HEP Lost Hep troubleshooted issue got hep back., 90278
3	LAX	48	ENG	79	ENG	79	ABQ-ABQ	NM	Flat-switched engines due to the A/C not working on Amtk 167. 167
4	CHI	113	WTR	106	DCS	72	TRI-LAJ	BN	Restrictive signal(s) from unknown cause Stop, Restricting , Restricting , Restricting , Restricting , Control Point, E. Timpas, Milepost, 569.8, 555.3
301	STL	21	PTI	27	PTI	21	BNL-SPI	UP	Meet amt 22, Control Point, x182
302	CHI	Trn Cancelled							
305	STL	148	WTR	59	DMW	35	LCN-SPI	UP	Waiting for MW clearance Track inspector, Milepost, 170, 170
306	CHI	115	SYS	38	SYS	38	BNL-PON	UP	Blocked by or assisting another, disabled Amtrak train Rescue amtk318, Control Point, x121
307	STL	563	SYS	355	SYS	347	CHI-XTF	AM	Re-crew / job briefing
382	CHI	147	WTR	82	FTI	60	KEE-PCT	BN	Follow Milepost, 123, 104, bnsf7409
383	QCY	114	WTR	57	DBS	40	MDT-MDT	BN	Debris blocking track (no debris strike) Fallen trees on main 2 and freight tied down on main 1. Held at Mendota until route available., Other, West of Zearing
390	CHI	27	DSR	25	DSR	10	CEN-EFG	CC	Per bulletin Milepost, 244.3, 243.6, 30, Main, Milepost, 241.2, 240.7, 30, Main, Milepost, 229.43, 229.43, 25, Main, Milepost, 199.3, 199.3, 10, Main
391	CDL	18	DSR	19	DSR	12	EFG-CEN	CC	Per bulletin Milepost, 229.43, 229.43, 25, main, Milepost, 240.7, 241.2, 30, main, Milepost, 243.6, 244.3, 30, main
392	CHI	207	WTR	151	WTR	99	RTL-GLM	CC	Trees down Milepost, 101.2, 101.2

Amtrak Endpoint OTP Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/11/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
311	KCY	32	DCS	24	DCS	15	HEM-JEF	UP	Slide fence restriction due to false actuation or out of service Restricted speed no debris on tracks, Milepost, 104.3, 106.7	
316	STL	26	FTI	19	PTI	14	SED-JEF	UP	Meet AMT 319, Siding, Dow	
318	CHI	278	SYS	79	SYS	69	BNL-PON	UP	2 headlights and 1 ditch light was out. Had 306 shove on top of us and tow us back to Chicago. Siding, Normal	
319	KCY	51	FTI	55	FTI	26	WAR-LEE	UP	Follow Milepost w/Letters, war, lee, up 5939	
1340	CHI	61	DCS	41	DCS	35	CBS-MKE	CP	Track light both mains stopped at Tamarak for maintainer Other, Tamarak	

Amtrak Initial Terminal Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/11/2026

Terminal	Train	Date	Late	Delay	Cause
CLT	72	06/11	32	32	Service, turn, or wye train 71, Late arrival of 71 that becomes 72
CLT	74	06/11	19	19	Service, turn, or wye train 73, Late train 73 arriving in CLT
GRO	73	06/11	30	30	Service, turn, or wye train 72
NFK	94	06/11	1		
NFK	138	06/11	1		
PHL	110	06/11	16	16	Service, turn, or wye train, 110, LATE OUT OF THE YARD
PHL	151	06/11	14	14	Other electrical failure, 669, Mechanical requested a/c dropped pantograph E/669.
PHL	605	06/11	1		
RNK	66	06/11	59	59	Planned set out / pick out of locomotives, cars or section of train
ALB	448	06/10	220		
BOS	2155	06/11	34	34	Other electrical failure, 2116 NG NP, Engine Issues
BOS	2193	06/11	6	6	Traction motor, 2012 LH LP, AM2193 dp BOS 6" late a/c traction motor issues on e/2012
GFD	479	06/11	23	23	Late coming in 486
MTR	68	06/11	9	9	Service, turn, or wye train 69, Late release from shop
NYP	19	06/11	7	7	Air / Brake / Wheel, 00000, UNSPECIFIED PROBLEM WITH CAFE CAR
NYP	49	06/11	71	71	Other electrical failure, 705, NECESSARY TO SWING IN SSYD A/C OPR WITH DIESEL ENGINE AND MECHANICAL ISSUES IN YARD
NYP	63	06/11	2	2	Meet, AM230, Other, NYP, HELD F/INBOUND AM230
NYP	89	06/11	5	5	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	111	06/11	5	5	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	181	06/11	20	20	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	193	06/11	8	8	Service, turn, or wye train, 184, LATE TURN OFF AM184
NYP	233	06/11	8	8	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	235	06/11	17	17	Service, turn, or wye train, 238, LATE TURN OFF AM238
NYP	241	06/11	11	11	Service, turn, or wye train, 290, LATE TURN OFF AM290
NYP	243	06/11	11	11	T.O.L, Other, XEE-XIW, HELD FOR AM48 A/C SINGLE TRACKING ON 2 TRK FOR TOL ON 1 TRK
NYP	291	06/11	13	13	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	2192	06/11	47	47	Other electrical failure, 2036, MCB ISSUES ON PC2036
SPG	417	06/11	29	29	Routine inspections, AM417 will dp SPG late a/c equip being looped

Amtrak Initial Terminal Details

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/11/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	48	06/11	(No OS)		
CHI	50	06/11	32	32	Air / Brake / Wheel 82654
CHI	305	06/11	8	8	Door ID4017, Pax trapped in restroom, mechanical department used crowbar to unlock door
CHI	329	06/11	2	2	Service, turn, or wye train 4617, Late turn of equipment
CHI	339	06/11	33	33	Service, turn, or wye train 338
CHI	341	06/11	80	45	Service, turn, or wye train 1340
CHI	341	06/11	80	35	Pick up rescue locomotive due to mechanical failure 519 no speedo, 518
CHI	354	06/11	16	16	Service, turn, or wye train 353
CHI	364	06/11	9	9	Received train late from yard. ID4607
MKE	338	06/11	35	35	Service, turn, or wye train 335
MKE	342	06/11	23	23	Service, turn, or wye train 339
PDX	28	06/11	120	120	Late arrival of 27 into PDX. Train had to be wyed cleaned and maintenance. Other, pdx station
PNT	351	06/11	10	10	Service, turn, or wye train 352, Waiting for re crew to wye equipment
SEA	8	06/11	132	132	Service, turn, or wye train 007
STL	302	06/11	(Trn Cxld)		Engine Issue
BFD	703	06/11	8	8	Headlights did not work/ Bakersfield mechanical replaced front headlights. C2014
GTA	782	06/11	18	18	Meet 14, Control Point, CP CO 358
LAX	564	06/11	23	23	Train late arriving from yard 564
OKJ	526	06/11	4	4	Meet 11, Control Point, North Jack London
OKJ	540	06/11	1	1	Last minute notification to load 716s PAX and bring them to EMY.
OKJ	716	06/11	(Trn Cxld)		Late Inbound
OKJ	718	06/11	3		
SAN	591	06/11	19	19	PTC- IETMS incorrect consist PTC issue, contacted CNOC Mechanical for support. Metrolink River corrected incorrect consist., Other, San Diego Santa Fe Depot
SAN	765	06/11	7	7	Meet NCTD, 620, Control Point, ash
SJC	528	06/11	1		

Eastern Region

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	99.0	94.8	342	3
CDOT	95.0	90.0	94.3	92.4	20	2
MARC	95.0	81.0	82.0	90.2	58	11
SEPTA	95.0	95.1	94.7	91.5	204	10
NJT-NED	95.0	89.9	88.9	88.6	359	36
NJT-SED	95.0	100.0	97.0	97.2	24	0

Operating Highlights

Train 52(11) Savannah, GA - Servicing

11JUN26: Train 52(11) with engines 360, 354, 358, 511, 44 cars, and 434 customers onboard was delayed at Savannah, GA on the CSX Savannah subdivision due to stopping at Savannah station to water and dump car 32114. Once the servicing was completed, train 52(11) was able to advance.

Train	Delay	Comment
52(11)	34"	

Train 171(11) North of Lynchburg, VA - Freight Train Interference

11JUN26: Train 171(11) with engine 148, 8 cars, and 150 customers onboard was delayed at milepost 164.2, 8 miles north of Lynchburg, VA on the NS Washington District due to meeting two freight trains. Once the freight trains were cleared and relief engineers for train 66(11) dropped off, train 171(11) advanced to the next station.

Train	Delay	Comment
171(11)	1'09"	

Train 97(11) South of Alexandria, VA - High Wind Warnings

11JUN26: Train 97(11) with engines 350, 330, 10 cars, and 263 customers onboard was delayed beginning at milepost 79.7, 26 miles south of Alexandria, VA on the CSX RF&P subdivision due to high wind warnings from milepost 79.7 to milepost 59.3. The train was required to operate at a reduced speed. Once the high wind warnings were lifted, train 97(11) advanced to the next station at normal authorized speed.

Train 41(10) was operating through the area during the high wind warnings and was delayed due to the reduced speeds.

Train	Delay	Comment
97(11)	43"	
41(10)	46"	

Train 449(11) West of Worcester, MA - Freight Train Interference

11JUN26: Train 449(11) with engines 99, 117, 4 cars, and 99 customers onboard was delayed at milepost 60.3, 16 miles west of Worcester, MA on the CSX Boston subdivision due to meeting CSX freight train N426-11. Once the freight train cleared, train 449(11) advanced to the next station.

Train	Delay	Comment
449(11)	32"	

Train 449(11) West of Pittsfield, MA - Freight Train Interference

11JUN26: Train 449(11) with engines 99, 117, 4 cars, and 79 customers onboard was delayed at milepost 176.7, 26 miles west of Pittsfield, MA on the CSX Berkshire subdivision due to meeting westbound freight. The train then also had to wait for eastbound train 448(10). Once all traffic was cleared, train 449(11) advanced to the next station.

Train	Delay	Comment
449(11)	1'16"	

Train 90(11) North of Fredericksburg, VA - Passenger Train Interference

11JUN26: Train 90(11) with engine 333, 8 cars, and 218 customers onboard was delayed beginning at milepost 61.1, 2 miles north of Fredericksburg, VA on the CSX RF&P subdivision due to following train 186(11) from milepost 61.1 to milepost 105.1. Once train 186(11) cleared, train 90(11) was able to advance to the next station at normal authorized speed.

Train	Delay	Comment
90(11)	35"	

NS Heat Orders

11JUN26: NS implemented multiple heat orders that caused delays to trains operating through those areas due to the reduced speeds.

Train	Delay	Comment
76(11)	30"	
95(11)	34"	
138(11)	36"	

Train 417(11) North of Windsor Locks, CT - Engine Failure

11JUN26: Train 417(11) with engine 46, 1 car, cab car 9636, and 12 customers onboard was delayed at milepost 48.5, 1 mile north of Windsor Locks, CT on the Amtrak MRS Line due to radio failure on engine 46. The train was not able to be reached by the dispatcher for a Form D until it was stopped and able to call. Once the Form D was given, train 417(11) was able to advance to the next station.

Train	Delay	Comment
417(11)	30"	

Train 53(11) South of Fayetteville, NC - Freight Train Interference

11JUN26: Train 53(11) with engines 329, 179, 8 cars, and 381 customers onboard was delayed beginning at milepost 256.5, 47 miles south of Fayetteville, NC on the CSX South End subdivision due to crossing over and going around CSX freight train I031.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(11)	35"	

Train 19(11) North of Culpeper, VA - Trees Down

11JUN26: Train 19(11) with engines 355, 179, 8 cars, and 189 customers onboard was delayed at milepost 52.0, 15 miles north of Culpeper, VA on the NS Washington District due to a large tree across both main tracks. The train went into emergency to avoid striking the tree. NS Maintenance of Way personnel responded to the scene to clear the debris. Once the debris was cleared, train 19(11) was on the move at 10:15 PM-ET and advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(11)	2'25"	

Train 186(11) North of Ashland, VA - Freight Train Interference

11JUN26: Train 186(11) with engine 329, 4 cars, and 168 customers onboard was delayed beginning at milepost 29.6, 15 miles north of Ashland, VA on the CSX RF&P subdivision due to follow CSX freight train M408 from milepost 29.6 to milepost 59.3. Once the freight train cleared, train 186(11) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
186(11)	30"	

Train 43(11) East of Huntingdon, PA - High Winds

11JUN26: Train 43(11) with engine 127, 7 cars, and 226 customers onboard was delayed at milepost 193.5, 9 miles east of Huntingdon, PA on the NS Pittsburgh Line due to high wind warnings. The dispatcher stopped the train at 5:05 PM-ET. Once the high wind warning expired, train 43(11) was on the move at 6:02 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
43(11)	57"	

Train 66(11) Roanoke, VA - Servicing

11JUN26: Train 66(11) with engine 139, 6 cars, and 44 customers was delayed departing Roanoke, VA on the NS Blue Ridge District due to a planned change to the consist. Car 82773 was shopped due to a shock issue. The car was moved from being fourth in the consist to behind the engine so that it could be taken off and replaced upon arrival in Washington.

Train 66(11) was stopped in Lynchburg. It was reported that the FRA stated that car 82773 had to be set out and could not continue to travel. The car was set out in Lynchburg and the train advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
66(11)	59"	RNK
66(11)	2'24"	LYH

Train 197(11) South of BWI Marshall Airport, MD - Engine Failure

11JUN26: Train 197(11) with engine 703, 10 cars, and 300 customers onboard was delayed departing BWI Marshall Airport, MD on the Amtrak Philadelphia to Washington Line due to the MCB opening when the train attempted to depart the station. The crew attempted to switch pantographs, and this did not work. The crew then soft reset the engine. This allowed the MCB to be closed until an attempt was made to advance. The crew worked with the Road Foreman to troubleshoot. The decision was made that the train would operate without head end power into Washington. The train was able to advance and was on the move at 9:49 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
197(11)	58"	

Train 49(11) New York, NY - Engine Failure

11JUN26: Train 49(11) with engine 705, 9701, 7 cars, and 185 customers onboard was delayed departing New York, NY on the Amtrak New York Terminal Line due to the necessity to add an additional engine to the consist. Engine 132 was added to the consist. Once the engine was added and the necessary inspections completed, train 49(11) arrived into the station to board and departed at 4:51 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
49(11)	1'11"	

Train 290(11) South of Croton-Harmon, NY - Commuter Train Interference

11JUN26: Train 290(11) with engine 9703, 5 cars, engine 716, and 244 customers onboard was delayed at milepost 46.0, 13 miles south of Croton-Harmon, NY on the Metro North Hudson Line due to meeting a Metro North commuter train. Once the commuter train cleared, train 290(11) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
290(11)	1'00"	

CN Heat Orders

11JUN26: CN imposed heat orders on the Rouses Point subdivision causing delays to trains 68 and 69.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
69(11)	43"	
68(11)	39"	

Train 48(10) North of Poughkeepsie, NY - Commuter Train Interference

11JUN26: Train 48(10) with engines 711, 715, 9707, 8 cars, and 124 customers onboard was delayed at milepost 75.5, 2 miles north of Poughkeepsie, NY on the Metro North Hudson Line due to a Metro North commuter train occupying the station. Once the commuter train departed the station, train 48(10) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48(10)	30"	

Train 151(11) South of Alexandria, VA - Commuter Train Interference

11JUN26: Train 151(11) with engine 715, 8 coaches, and 125 customers, was delayed approximately 3 miles South of Alexandria, VA, on NS Alexandria-Montview subdivision, due to meeting VRE commuter train at Control Point James.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
151(11)	33"	

Train 48(10) Albany-Rensselaer, NY - Engine Failure

12JUN26: Train 48(10) with engine 715, 9707, 8 cars, and 126 customers onboard was delayed at Albany-Rensselaer, NY on the Amtrak HUD Line due to engine failure upon departing the station. It was reported that right after departing the station engine 715 had air compressor failure. The train was capped with engine 711. Once the engine was added to the consist and all necessary tests were completed, train 48(10) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48(10)	1'41"	

Train 98(10) Richmond, VA - Freight Train Interference

11JUN26: Train 98(10), operating with engines 355/179, 10 coaches and 244 customers, was delayed 10 miles north of Richmond, VA, Staple Mill Road station, on CSX Richmond Fredericksburg subdivision, due to following IO32 from milepost 14.8 to milepost 58.9. Once the freight cleared and a route was made available, train 98(10) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(10)	31"	

Train 448(10) Albany-Rensselaer, NY - Engine Failure

11JUN26: Train 448(10), operating with engines 109/108/105, 4 coaches, and 71 customers, was delayed departing Albany, NY, on Amtrak Hudson Line, due to swapping engine 109 for engine 108. After the engines were swapped and 448(11) was preparing to depart, engine 108 experienced ACSES failure and was bad ordered. That engine was removed. Engine 105 was worked up and added to the consist. Once the engine was added to the consist and all necessary tests completed, train 448(10) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
448(10)	3'06"	

Train 42(11) Philadelphia, PA - Engine Failure

11JUN26: Train 42(11), operating with engine 633, 8 coaches and 225 customers, was delayed departing Philadelphia, PA, on Amtrak PW Line, due to engine failure of engine 372/656. After the routine engine change from diesel to electric engines it was discovered that engines 372/656 would not supply Head End Power to the train. While Head End Power was down, customers were able go inside the station. The decision was made to remove these two engines were removed and engine 633 was their replacement. Once engine 633 was added and the equipment was tested and inspected, train 42(11) was able to depart Philadelphia.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
42(11)	1'22"	

11JUN26: Multiple train orders of delayed CSX heat orders that were in place from 1300-1900 on the following subdivisions:

Baltimore Terminal, Berkshire, Boston, Capital, Cumberland, Kanawha, Keystone, Metropolitan, North End, Old Main Line, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, South End, Tampa Terminal.

Train	Delay	Comment
138(11)	28"	
80(11)	1'02"	
53(11)	29"	
41(10)	44"	
186(11)	16"	
90(11)	49"	
79(11)	1'21"	
98(11)	33"	
40(11)	45"	
95(11)	27"	
40(10)	51"	
89(11)	45"	
97(10)	20"	
94(11)	13"	
20(10)	02"	
449(11)	36"	
52(11)	13"	
125(11)	26"	
178(11)	04"	

Train 72(11) Charlotte, NC - Initial Terminal Delay

11JUN26: Train 72(11), operating with engines 1794/1810, 10 coaches, and 48 customers, was delayed departing Charlotte, NC, on NS Salisbury-Greenville_04 subdivision, due to turning from the late 71(11). Train 71(11) was delayed due to slow orders between Durham, NC and Burlington, NC.

Train	Delay	Comment
72(11)	32"	
73(11)	30"	Turn of late 72(11)
74(11)	19"	Turn of late 73(11)

Train 2107(11) North of Baltimore, MD - Engine Failure

11JUN26: 2107(11), operating with power cars 2123/2121, 9 coaches and, 223 customers, was delayed 7.5 miles north of Baltimore, MD, Penn station, on Amtrak PW line, due to engine issues on lead power car 2123. The power car was showing multiple faults that could not be cleared initially. After the engineer attempted to clear the faults unsuccessfully, there was a tech onboard who stepped in to assist as well as CNOC mechanical remotely. After recycling the power car the faults were able to be cleared and train 2107(11) was able to proceed.

Train	Delay	Comment
2107(11)	32"	

Train 48/448(10) West of Rochester, NY - Freight Train Interference

11JUN26: Train 48/448(11), operating with engines 5/122, 12 coaches, and 196 customers, was delayed 10 miles west of Rochester, NY, on CSX Rochester_QC subdivision, due to meeting M42911 at Control Point 380. Once the freight cleared and a route was made available, train 48/448(10) was able to proceed.

Train	Delay	Comment
48/448(10)	32"	

Train 69(11) North of Croton-Harmon, NY - Commuter Train Interference

11JUN26: Train 69(11), 26-PP-00532, engine 103/706, 5 coaches, and 259 customers, was delayed 6.2 miles north of Croton-Harmon, NY, on MNCW Hudson Line, due to meeting Metro North 844/846 at Control Point 39. This congestion was due to MOW work that caused track 2 to be out of service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
69(11)	35"	

Train 284(11) East of Rochester, NY - Freight Train Interference

11JUN26: Train 284(11), operating with engine 103/706, 5 coaches, and 132 customers, was delayed 19 miles east of Rochester, NY, on CSX Rochester_QC subdivision, due to following unknown CSX freight train from milepost 350 to milepost 320. Once the freight cleared and a route was made available, train 284(11) was able to resume normal speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
284(11)	30"	

Train 2155(11) Boston, MA - Engine Failure

11JUN26: Next Gen Acela 2155(11), operating with power cars 2116/2117, 9 coaches, and 107 customers, was delayed departing Boston, MA, South Station, on Amtrak NHB line, due to being met by mechanical to for an electrical issue on power car 2116. Mechanical was able to resolve the issue and 2155(11) was able to depart Boston at 7:34am-et.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2155(11)	34"	

Train 2192(11) New York, NY - Engine Failure

11JUN26: Train 2192(11) operating with powercars 2036/2017, 6 coaches and 174 customers, was delayed departing New York, NY, Penn Station, on Amtrak NYP Line, due to Main Circuit Breaker issues on lead powercar 2036. Mechanical responded to the train and was able to resolve the issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2192(11)	47"	

Train 56(10) North of White River Junction, VT - Debris Strike

11JUN26: Train 56(10) with engine 95 6 cars, and 40 customers onboard struck a tree around milepost 27.0, 13 miles north of White River Junction, VT on the New England Central Railroad Roxbury subdivision. It was reported that the windshield of engine 95 was broken from striking the tree. The crew was willing to take the train to the final destination. The equipment was scheduled to turn for train 55(11). An attempt was made to source a freight engine. The attempts were unsuccessful. A shuttle set made up of engine 90, car 82584, and cab car 9647 was sent from Springfield, MA to Saint Albans, VT to couple to the equipment and operate to New Haven.

Trains 425/475(11) were cancelled in their entirety due to a shortage in shuttle sets. Buses were sourced as alternate transportation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
425/475(11)	Cancelled	

NS Trackwork affecting Piedmont and Carolinian Services - 6/8 - 6/11- TW 26-054

11MAY26:

Beginning Monday May18th - Thursday May 21st and again Monday June 8th - Thursday June 11th between the hours of 9:30 AM-ET and 3:30 PM-ET NS will be performing scheduled trackwork on their NC Lines between Charlotte and Raleigh, NC., between MP 0.0 and 34.0 at Elm to Isom.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (18May-21May; 8Jun-11Jun), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (18May-21May; 8Jun-11Jun) will operate 40-minutes Later between CLT and GRO, arrive 45-minutes later at BNC, and operate 50-minutes Later between DNC and RGH.
- Train 76 (18May-21May; 8Jun-11Jun) will operate 12-minutes Later between DNC and RGH.
- Train 78 (18May-21May; 8Jun-11Jun) will depart BNC 10-minutes Later and operate 20-minutes Later between DNC and RGH.
- Train 80 (18May-21May; 8Jun-11Jun) will operate 10-minutes Later between DNC and RGH.

WESTBOUND

- Train 71 (18May-21May; 8Jun-11Jun) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (18May-21May; 8Jun-11Jun), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (18May-21May; 8Jun-11Jun), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (18May-21May; 8Jun-11Jun) will depart BNC 1-minute Later and operate 21-minutes Later between GRO and CLT.
- Train 79 (18May-21May; 8Jun-11Jun) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

EQUIPMENT:

May 18th - 21st and June 8th - 11th:

- Train 71 will operate RGH to CLT with a double trainset. This train set will then operate on Train 72 between CLT and GRO where it will be split up to represent Trains 73 and 75.

WBS#: B.TR.100150.6656

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
77(09)	1'09"	

21MAY26: CSX Albany Division, 26-FOI-00532, 00000007812, UNCLASSIFIED, 6/17/2026
 Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

17Jul, 20Oct-21Oct, 21Oct-27Oct, 31Oct, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) in "UNCLASSIFIED" operation. Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
20 (26)	XN2	174		Brake pads missing
80 (12)	CLT	101		Brake Caliper broken
291 (4)	CRT	9705		Trail link broken bolt

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 392(11) South of Chicago, IL - Signal

12JUN26: Train 392(11) was delayed beginning at 15.0, 15 miles south of Chicago IL station on the CN Chicago subdivision due to restrictive signals from an unknown cause. Train 392(11) proceeded through the signals at reduced speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
392(11)	45"	

Train 14(11) West of Sacramento, CA - Air Hose Separation

12JUN26: Train 14(11), E/378-377 and 9 cars, went into emergency at MP 144.5 on the UPRR Sacramento Subdivision due to an air hose separation between C/32044 and C/39037. No reported injuries to 284 passengers or crew. The crew needed to replace the hose due to the gald-hand was reported broken. Once the hose was replaced, Train 14(11) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(11)	56"	Wi-Tronix Estimate

Train 8(11) West of Leavenworth, WA - Freight Train Interference

12JUN26: Train 8(11) was delayed west of Leavenworth, WA due to meeting an unknown BNSF freight unit at Winton/MP1687 on the BNSF Scenic Subdivision.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8(11)	31"	

Train 58(11) Greenwood, MS - M of W Work

12JUN26: Train 58(11) was delayed holding at MP122.5 Greenwood MS station on the CN Yazoo subdivision due to maintainers working ahead. Maintainers released the tracks and train 58(11) departed Greenwood MS station at 727PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(11)	1'18"	

Train 7/27(10) West of East Glacier Park, MT - Freight Train Interference

12JUN26: Train 7/27(10) was delayed at W. Bison/MP1138.1 BNSF Hi Line Subdivision, west of East Glacier Park, MT due to a disabled BNSF 7731W freight unit at Summit/MP1149.8. The freight needed to replace two knuckles then wait on re-crew to arrive after expiring on hours of service. Once the freight was clear, Train 7/27(10) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(10)	2'36"	

Train 716(11) Emeryville, CA - Third Party Contractor Engine Failure

12JUN26: Train 716(11) CC/90278, 7 cars, E/C2004, with 69 passengers onboard, was further delayed at Martinez, CA with a loss of tractive effort and headend power (HEP). Crew worked with Amtrak Trainmaster and TASI mechanical in order to troubleshoot the issue. Train 718 (was also held at Martinez upon arrival, in case a rescue transfer of passengers was necessary. Once HEP was restored, crew continued to work with mechanical account of door issues, making it necessary to override them in order to proceed. The train departed Martinez operating 3 hours and 50 minutes late.

Train 716(11) was stopped again 10 miles west of Bakersfield at MP897 on the UPRR Bakersfield Subdivision. Crew reported no HEP and total loss of tractive effort. The weather was a reported 76 degrees and there was 47 passengers onboard. The decision was made to couple to Train 718(11) that was behind them, in order for the train to proceed into Bakersfield.

Due to this service disruption, Train 713(12) was cancelled in entirety, passengers to re-book next available services.

Train	Delay	Comment
716(11)	2'52"	Originated EMY
716(11)	54"	MTZ - Wi-Tronix Estimate
716(11)	1'30"	W/BFD -Wi-Tronix Estimate
718(11)	1'22"	Wi-Tronix estimate
713(12)	Cancelled	

Train 534(11) Suisun-Fairfield, CA - Third Party Contractor Engine Failure

12JUN26: Train 534(11) CC/8302, 4 cars, E/C2102 was delayed at Suisun-Fairfield, CA due to engine loading issues, train coasted into the station without a load. Crew troubleshooted with an Amtrak Road Foreman and TASI mechanical to rectify and depart. Shortly after departing, the train came to a stop again at MP53.4 on the UPRR Martinez Subdivision and the crew continued to troubleshoot. It was determined that the engine would need to cool upon arrival into Fairfield-Vacaville, CA station, and to limit passenger delay, the train was terminated and all passengers were transferred to Train 536(11).

Train	Delay	Comment
534(11)	31"	
534(11)	Terminated	FFV

Train 3(11) La Plata, MO - Freight Train Interference

12JUN26: Train 3(11) was delayed departing La Plata MO station/MP312.7 on the BNSF Marceline subdivision following BNSF Freight.

Train	Delay	Comment
3(11)	37"	

Train 14(11) West of Martinez, CA - Near Miss

12JUN26: Train 14(11) was delayed 5 miles west of Martinez, CA at MP 26 on the UPRR Martinez Subdivision. The delay was incurred after a "near-miss" of a semi-truck. Once the crew performed the mandatory brake tests 14(11) continued east at track speed. Amtrak Police Notified.

Train	Delay	Comment
14(11)	12"	

Train 4(10) Raton, NM - Passenger Train Interference

12JUN26: Train 4(10) was delayed beginning at MP0.7 west of Raton, NM station on the BNSF Raton subdivision meeting Amtrak train 3(10).

Train	Delay	Comment
4(10)	38"	

Train 341(11) Chicago, IL - Initial Terminal Delay

12JUN26: Train 341(11) was delayed departing Chicago IL station/MP0.0 on the Amtrak Chicago terminal due to a late turn of equipment off train 1340(11) . Engine 519 off train 1340(11) had PTC issues so it was capped with engine 518. Train 341(11) began boarding at 903PM CT and the train departed at 925PM CT.

Train	Delay	Comment
341(11)	1'20"	

Train 6(09) West of Ottumwa, IA - Freight Train Interference

12JUN26: Train 6(09) was delayed beginning at MP318.5 west of Ottumwa IA station on the BNSF Ottumwa subdivision following BNSF Freight train 8264.

Train	Delay	Comment
6(09)	1'08"	

Train 7/27(11) Chicago, IL - Engine Failure

12JUN26: Train 7/27(11) was delayed beginning MP0.6 west of Chicago IL station on the Amtrak Chicago Terminal due to the speedometer not working on engine 353. Train 7/27(11) reversed to Chicago IL station and was met by mechanical to troubleshoot the speedometer. Mechanical was able to resolve the issues with the speedometer and train 7/27(11) departed Chicago IL station for a second time at 435PM CT.

Train	Delay	Comment
7/27(11)	1'30"	

Train 25(11) North of New Orleans, LA - Freight Train Interference

12JUN26: Train 25(11) was delayed beginning at MP801.5, north of New Orleans LA station following freight train X60511 until MP803.6.

Train	Delay	Comment
25(11)	35"	

Train 307(11) South of Pontiac, IL - Engine Failure

11JUN26: Train 307(11) with engine 57, 5 cars, and 194 customers onboard was delayed at milepost 94.2; just outside of Pontiac, IL on the UPRR Joliet subdivision due to PCS not loading. The crew worked to troubleshoot the issue and was able to rectify the problem. Train 307(11) was able to advance to the next station.

Train	Delay	Comment
307(11)	33"	

Train 382(11) East of Kewanee, IL - Freight Train Interference

12JUN26: Train 382(11) with engines 150, 160, 9 cars, and 167 customers onboard was delayed beginning at milepost 123, 8 miles east of Kewanee, IL on the BNSF Mendota subdivision due to following BNSF freight train 7409 from milepost 123 to milepost 104.

Train	Delay	Comment
382(11)	1'00"	

Train 5(11) West of Ottumwa, IA - Freight Train Interference

11JUN26: Train 5(11) with engines 150, 160, 9 cars, and 167 customers onboard was delayed beginning at milepost 288.9, 9 miles west of Ottumwa, IA on the BNSF Ottumwa subdivision due to crossing over and going around two freight trains between milepost 288.9 and milepost 300.8. Once the train was around the congestion, train 5(11) advance to the next station.

Train	Delay	Comment
5(11)	54"	

Train 50(11) Chicago, IL - Car Failure

11JUN26: Train 50(11) was delayed departing Chicago IL station/MP0.0 due to stuck brakes on deadhead car 82654. Mechanical responded to the train to troubleshoot the issue and found the brakes to be working after performing the electrical cuts to remove the car. Car was re-added to train 50(11) and four set and releases were performed to test the brakes. Brakes on car 82654 were found to be functioning correctly and the train was release at 546PM CT. Train 50(11) departed Chicago IL Station at 627PM CT.

Train	Delay	Comment
50(11)	32"	

Train 318(11) South of Springfield, IL - Passenger Train Interference

11JUN26: Train 318(11) with engine 59, 7 cars, and 232 customers onboard was delayed at milepost 197.9, 13 miles south of Springfield, IL on the UPRR Springfield subdivision due to meeting train 21(11). Train 318(11) was able to advance to the next station after the passenger train passed.

Train	Delay	Comment
318(11)	41"	

Train 22(11) Fort Worth, TX - Fueling

11JUN26: Train 22(11) was delayed at Fort Worth, TX Station/MP611.29 on the BNSF Fort Worth subdivision adding fuel to engine 69.

Train	Delay	Comment
22(11)	33"	

Train 19(10) North of Meridian, MS - Freight Train Interference

11JUN26: Train 19(10) was delayed beginning at MP280.7, 14.3 miles north of Meridian MS station on the Norfolk Southern AGS South subdivision following Norfolk Southern Freight train until MP295.

Train	Delay	Comment
19(10)	31"	

Train 714(11) East of Richmond, CA - Third Party Contractor Engine Failure

11JUN26: AT 12:56P-PT 26-F000532 70000007812, CC(001107 cars 5/17/2026 C2005, stopped at MP 20.1, 8 miles east of Richmond, CA, on the UPRR Martinez Subdivision due to loading and head end power(HEP) issues on E/C2005. There were 62 customers on board with the ambient outside temperature 80 degrees and sunny. Amtrak road foreman and mechanical responded to scene. Amtrak road foreman arrived at 1:45P-PT and was able to get HEP restore at 2:00P-PT. Once passenger trains cleared route, Train 714(11) proceeded east. Train 532(11) was delayed assisting Train 714(11) in case customers needed to transfer.

Train	Delay	Comment
714(11)	1'32"	
532(11)	32"	

Train 24(11) North of Pascagoula, MS - Freight Train Interference

11JUN26: Train 24(11) was delayed starting 28.6 miles north of Pascagoula, MS (MP706.6), on the CSX NO&M Subdivision, from MP678 to Mobile, AL (MP666.7) following CSX M606.

Train	Delay	Comment
24(11)	48"	

Train 335(11) West of Glenview, IL - Freight Train Interference

11JUN26: Train 335(11) was delayed 3.5 miles west of Glenview, IL (MP17.0), on the Metra C&M Subdivision, at Tower A20 due to CP 640 in emergency ahead. Once recovered and cleared, Train 335(11) was able to proceed west.

Train 338(11) was delayed departing Milwaukee, WI (MP85.4), on the CPRR C&M Subdivision, due to a late turn of Train 335(11)'s equipment.

Train	Delay	Comment
335(11)	32"	
338(11)	35"	
339(11)	33"	Turn off 338(11)

Train 516(11) South of Vancouver, BC - M of W Work

11JUN26: Train 516(11) was delayed starting at MP 137.3, 20 miles south of Vancouver, BC, on the BNSF New Westminster Subdivision due to maintenance of way work at Fraser River Bridge/ MP 143.4.

Train	Delay	Comment
516(11)	28"	

Train 20(11) South of Meridian, MS - Freight Train Interference

11JUN26: Train 20(11) was held approximately 1.9 miles south of Meridian, MS (MP 295.0) on the NSRR NO&NE Subdivision, at MP 1.9, due to NS 346 blocking the station track. NS 346 was stopped at the station for fueling; however, the initial fuel truck did not have sufficient fuel, requiring a second truck to be dispatched. Once fueling was completed and NS 346 cleared the station track, Train 20(11) proceeded north.

Train	Delay	Comment
20(11)	1'08"	

Train 7/27(10) Minot, ND - Servicing

11JUN26: Train 7/27(10) was delayed at MP 312.5, 5 miles north of Minot, ND on the BNSF Glasgow Subdivision due to bell issues on E/312. During routine inspections in Minot, mechanical found the bell on E/312 was not working properly and a temporary fix was put in place. Once routine inspections and temporary fix was complete, Train 7/27(10) departed Minot.

Train	Delay	Comment
7/27(10)	38"	

Train 774(11) North of Lompoc-Surf, CA - Police Related

11JUN26: Train 774(11) was delayed at MP 294.6, 5 miles north of Lompoc-Surf, CA, on the UPRR Santa Barbara Subdivision due to the SpaceX rocket launch at Vandenburg. The crew held until local officials released track due to launch. Train 774(11) was further delayed at the station Lompoc-Surf due to a concerned citizen reporting a defect ahead. The track inspector was prevented from accessing the location due to the SpaceX launch. Once launch was concluded and the track inspector was able to access the location it was determined that the defect was on abandoned tracks nearby, not on the main line. Once tracks were released, Train 774(11) was able to depart. Train 757(11) was delayed south of Lompoc-Surf holding for open track.

Train	Delay	Comment
774(11)	1'11"	N/ LPS
757(11)	42"	
774(11)	29"	Hold LPS

Train 19(10) North of Anniston, AL - Tree Strike

11JUN26: At 9:14AM-CT, Train 19(10), E/63-E/302-8 Cars, struck a tree on the tracks 56.5 miles north of Anniston, AL (MP735.0), on the NSRR East End Subdivision, at MP678.5. There were no injuries reported to the crew or 97 customers onboard. There was no damage reported to the equipment. At 9:17AM-CT, the tree was removed and Train 19(10) continued south.

Train	Delay	Comment
19(10)	03"	

Train 23(11) North of New Orleans, LA - B&B Work Due to Defect

11JUN26: Train 23(11) was held approximately 2.5 miles north of New Orleans, LA (MP 0.0) on the CSX NO&M Subdivision, at NOPB (MP 801.2), due to a malfunction of the Industrial Canal Bridge (MP 801.4). B&B personnel were dispatched to the location to address the issue. Once the bridge was properly seated and secured, Train 23(11) was released and continued on to New Orleans.

Train	Delay	Comment
23(11)	46"	

Train 51(10) North of Lafayette, IN - Freight Train Interference

11JUN26: Train 51(10) was held 25 miles north of Lafayette, IN (MP120.1), on the CSX Monon Subdivision, at Reynolds (MP95.1) in order to meet CSX M641-11.

Train	Delay	Comment
51(10)	39"	

Train 350(11) Dowagiac, MI - Engine Failure / Passenger Train Interference

11JUN26: Train 350(11), E/55-D4620-7 Cars, UNCLASSIFIED ID 4609, 6/17/2026 223 customers onboard, was stopped at Dowagiac, MI (MP 179.5) due to a reported M/U fault and an onboard hot journal alarm on rear engine (ID4609). The crew inspected axle 3 for the reported hot journal; however, no defects were identified. The M/U cable was pulled, allowing Train 350(11) to continue for 8.1 miles until stopping again at Glenwood (MP171.4) in order to meet Trains 351(11) and 365(11).

Train	Delay	Comment
350(11)	30"	
350(11)	30"	Meet 365(11)
350(11)	25"	Meet 351(11)

Train 40(09) and 49(10) Toledo, OH - Freight Train Interference

11JUN26: Train 40(09) was delayed starting 15.7 miles west of Toledo, OH (MP288.3), on the NSRR Chicago Line, following NS 13Q from MP304 to MP350. Train 49(10) was also delayed through the area following Train 40(09) starting at Cleveland, OH (MP181.6).

Train	Delay	Comment
40(09)	59"	Follow 13Q
49(10)	1'37"	Follow 40(09)

Train 14(10) South of Redding, CA - Freight Train Interference

11JUN26: Train 14(10) was delayed at MP 244.0, 14 miles south of Redding, CA, on the UPRR Valley Subdivision meeting UP1037. Once UPRR freight cleared, Train 14(10) proceeded north.

Train	Delay	Comment
14(10)	38"	

Train 4(09) East of Lawrence, KS - Tree Strike

11JUN26: Train 4(09), E/11-E/62-9 Cars, reported that it had struck a tree branch on the tracks approximately 11.7 miles east of Lawrence, KS (MP 26.0), on the BNSF Topeka Subdivision, at MP 14.3. There were no injuries to the crew or the 174 customers onboard. Damage was reported to the engineer-side mirror on engine 11. No delay was attributed to the incident.

Train	Delay	Comment
4(09)	No Delay	

Train 1(10)/421(09) El Paso, TX - Engine Failure

11JUN26: Train 1(10)/421(09), E/140-E/19-10 Cars, was delayed at El Paso, TX (MP1296.0), on the UPRR Lordsburg Subdivision, adding freight locomotive UP4243 to the head end. This was a result of lead engine 140 experiencing loading issues enroute. Once the freight was added, Train 1(10)/421(09) was able to proceed west.

Train	Delay	Comment
1(10)/421(09)	1'59"	
2/422(10)	46"	HELD OUT ELP

Train 7/27(09) East of Libby, MT - Freight Train Interference

11JUN26: Train 7/27(09) was delayed at MP 1251.8, 68 miles east of Libby, MT, on the BNSF Kootenai River Subdivision due to freight interference. The crew followed BN5814 from MP 1251.8 to Twin Meadows/ MP 1264.5. They were then held at Tamarack/MP 1291.1 for BN3910 to clear, once freight cleared Train 7/27(09) proceeded west where they were held again at Fish River/MP 1299.0 for BN6699. Once all freights were clear, Train 7/27(09) proceeded west at track speed.

Train	Delay	Comment
7/27(09)	13"	BN3910
7/27(09)	10"	Follow BN5814
7/27(09)	16"	BN6699

Train 2/422(10) West of Yuma, AZ - Freight Train Interference

11JUN26: Train 2/422(10) was delayed at MP 723.0, 10 miles west of Yuma, AZ, on the UPRR Yuma Subdivision due to meet with UP8048. Once freight cleared, Train 2/422(10) proceeded east.

Train	Delay	Comment
2/422(10)	44"	

Train 41(10) West of Alliance, OH - Tree on Tracks

11JUN26: Train 41(10) was held 2.8 miles west of Alliance, OH (MP 83.1) on the NSRR Cleveland Line due to a reported tree obstructing the track at MP 79.8. The train was stopped at MP 85.9 until Maintenance of Way personnel responded and cleared the obstruction. Once the tree was removed and a route was established, Train 41(10) was released to proceed east. Service recovery enacted for lateness consisting of all coach customers offered complimentary coffee and tea followed by bottled water and snack packs. All first-class customers received breakfast as normal from the diner.

Train	Delay	Comment
41(10)	1'05"	

Train 4(10) West of Kingman, AZ - Passenger Train Interference

11JUN26: Train 4(10) was delayed at Griffith/MP 528.8, 12 miles west of Kingman, AZ, on the BNSF Seligman Subdivision due to meet with Train 3(09). Once Train 3(09) cleared route, Train 4(10) proceeded east.

Train	Delay	Comment
4(10)	31"	

Severe Weather Central U.S - Weather

09JUN26: A seasonably strong storm system brought scattered storms to much of the Northern Plains and Midwest. Storms forecasted to congeal as they move east and are expected to produce wind gusts to 80MPH, large hail, localized flash flooding and isolated tornadoes. Storms will diminish into the early hours of Wednesday morning. Another round of scattered storms will develop Wednesday afternoon along a corridor through central Minnesota, central Iowa and northwestern Missouri. Disruptions are expected from these storms, including flash floods, downed trees and power lines and possible power outages in affected areas.

Southwest Chief

09JUN26: Train 4(07), E/50-E/181 & 9 cars, with 181 customers, was delayed at MP125.2, 72 miles west of Topeka, KS, on the BNSF Emporia Subdivision, due to a reported washout ahead at MP56.8, on the BNSF Topeka Subdivision and no estimate for open track. As a result, Train 4(07) was rerouted to detour over the BNSF Emporia Subdivision to Kansas

scheduled to board at Topeka and Lawrence were notified train was bypassing and advised to rebook travel. The ten customers scheduled to detrain at the bypassed stops were provided alternate travel from Kansas City to Lawrence and Topeka. BNSF estimated track would be open at approximately 600PM-CT.

Empire Builder and Borealis

10JUN26, Train 7/27(09), with 254 customers, was delayed west of Staples, MN/MP148.3, on the BNSF Staples Subdivision, due to high wind warnings in effect between MP148 and MP165. Train 7/27(09) was delayed operating reduced speed through the affected area.

10JUN26, Train 8/28(08), E/353-E/301 & 11 cars, with 213 customers, was delayed at MP413, 3 miles west of St. Paul-Minneapolis, MN, on the CPKC Merriam Park Subdivision, due to large tree down ahead at Erie St. Train 8/28(08) held for MW to respond, clear tree and open the route. Train 8/28(08) was further delayed at MP361.1, 9 miles east of Red Wing, MN, due to PTC issues after striking a tree. There were no injuries and no reported damages to equipment. The crew contacted PTC desk however was unable to resolve issues. Train 8/28(08) proceeded east with PTC cut out on E/353.

10JUN26, Train 1340(10), E/29-3 cars-E/14, with 162 customers, struck a tree at MP343.2, 27 miles east of Red Wing, MN, on the CPKC Merriam Park Subdivision. There were no reported injuries to passengers or crew. Lead E/29 engineer's side ditch light was knocked out. There were no other exceptions to equipment reported.

10JUN26, Train 1333(10), E/519-3 cars-E/198, was delayed at MP172.3, 6 miles east of Portage, WI, on the CPKC Watertown Subdivision, due to striking a tree and PTC disengaging on E/519. There were no injuries reported and no other exceptions to equipment reported. Crew was unable to resolve PTC issue and Train 1333(10) was authorized to proceed with PTC cut out. Train 1333(10) was delayed enroute operating 59MPH Max.

Lake Shore Limited & Floridian

10JUN26, Trains 49/449(09) with 256 customers, and Train 40(08) with 126 customers, were delayed west of Elyria, OH/MP206.6, on the NS Toledo East Subdivision, operating through flash flood warnings between MP232 and MP240. Trains 48/448(09), with 272 customers, and Train 41(09), with 182 customers, were delayed east of Toledo, OH/MP288.3, on the NS Toledo East Subdivision, operating through flash flood warnings between MP271 and MP233.

Cardinal: 10JUN26, Train 50(09), with 85 customers, was delayed at MP110, 17 miles east of Indianapolis, IN, on the CSX Indianapolis Subdivision, waiting on track inspector to clear ahead after high winds expired.

California Zephyr & Southwest Chief

10JUN26, BNSF issues numerous high wind warnings across the BNSF Mendota and Ottumwa Subdivisions. Trains 3(10) and 5(10) were delayed operating through the affected areas. 5(10) was delayed from MP155 to MP196 east of Burlington IL due to high wind and flash flood warnings. Train 5(10) held at Ottumwa IA station on the BNSF Ottumwa sub due to a washout reported at MP322. Train 5(10) departed the station at 116AM CT to approach the washout and wait for open tracks. Train 3(10) was delayed holding for a re-crew at La Plata MO station on the BNSF Marceline subdivision. Re-crew arrived and after the briefing train 3(10) departed La Plata MO station at 212AM CT.

Texas Eagle: UPRR issued high wind warnings, in excess of 80MPH gusts, on the Joliet Subdivision, between Joliet, IL/MP37 and MP81. Additionally a tornado warning was in effect between MP39 and MP46. Trains 21(10) and 22(09)/422(07) were delayed through the area.

Borealis: Train 1340(10) was delayed holding at MP187.2, 10.10 miles west of Portage WI station on the CPKC Tomah subdivision due to signal issues caused by lightning strikes in the area.

Michigan Line: Train 352(10) was stopped at MP266, west of New Buffalo, MI station on the Amtrak Michigan line due to debris on the track. Train 352(10) was back on the move at 609PM ET. Train 370(10) was delayed beginning at MP136.4 west of St. Joseph MI station on the CSX Grand Rapids subdivision due to high wind warnings until MP5.9.

Illini Service: Train 393(10) was delayed departing Chicago IL station/MP0.0 due to Norfolk Southern holding trains on while tracks ahead were inspected for debris. Train

Lincoln Service: Train 318(10) was delayed beginning at MP51.6, south of Joliet IL Station on the CN Joliet subdivision operating at restricted speed due to a track light from severe weather. 26-FOI-00532 00000007812 "UNCLASSIFIED" 6/17/2026

Carl Sandberg: Train 383(10) was delayed beginning at MP61, west of Mendota, IL station on the BNSF Mendota subdivision due to high wind warnings until MP52.3. 382(10) was delayed beginning at MP191.4 east of Galesburg, IL station due to high wind warnings until MP162.4

11JUN26 Updates:

Southwest Chief Service:

-Train 3(10) was further delayed after departing La Plata, MO (MP312.7), on the BNSF Marceline Subdivision, due to flash flood warnings ending at MP327.0. Operating speeds were restricted through the area. At West Marceline (MP347.3), Train 3(10) stopped to pick-up their recrew before being able to proceed west.

-Train 4(09) was delayed starting 133.2 miles east of Kansas City, MO (MP6.9), on the BNSF Marceline Subdivision, from high wind warnings starting at MP318.0 to MP273.3. Additional delay incurred due to flash flood warnings from MP264.0 to MP250.0.

California Zephyr Service:

-Train 5(10), once released from Ottumwa, IA (MP279.8), operated through flash flood warnings starting at M281.0 to MP347.0. Operating speeds were restricted from Halpin (MP309.8) to MP347.0. Severe weather continued west of Creston, IA (MP393.1) resulting extensive delays due to multiple downed trees ahead of 5(10) at MP404.8, MP405, MP418 and also downed power lines at MP421. The crew was able to remove the tree at MP404.8 themselves but required Maintenance of Way and a Hi-rail excavator response for the others and the power lines. Train 5(10) held at MP404.7 with 235 customers onboard for a route to be established. The tracks were reopened at 3:00PM-CT. Re-crew arrived on site for train 5(10) at MP442.6 W/CRN at approximately 520PM CT. Train 5(10) was back on the move west at 538PM CT and was operating approximately 19'37" late. Service recovery was enacted due to the delay and car lounge 33039 with no refrigeration. Sleeper customers meal service was not affected. Snack packs, coffee, tea, juice, and water were offered for all customers. Coach customers received beef stew for lunch and Pizza at Omaha for dinner. Customers waiting at the Omaha station were given Jersey Mikes meal boxes. Train 5(10) was delayed at MP263.9 east of McCook NE station on the BNSF Hastings subdivision holding for a re-crew. Re-crew arrived on site and train 5(10) was back on the move at 150AM CT.

-Train 6(09) was delayed starting 0.8 miles east of Lincoln, NE (MP0.8X), on the BNSF Creston and Omaha Subdivisions, due to high wind warnings starting at Baird (MP58.8) to MP29.0. 60MPH warnings in effect MP58.8 to MP41.1, 70MPH warnings in effect MP41.1 to Ashland (MP35.1), then 80MPH warnings on the Omaha Subdivision from East Wye Ashland (MP46.1) to MP29.0. Train 6(09) was also heavily delayed west of Creston holding at MP429.1 for the power lines and trees to be removed ahead. Train 6(09) held at MP426.5 west of Creston IA station waiting for a re-crew to arrive. Re-crew arrived on site and train 6(09) was back on the move at 503PM CT operating approximately 10'57" late. Service recovery was enacted starting with snack packs, bottled water, coffee, tea, and juice for all customers. Coach customers also received beef stew or vegetarian chili. Sleeper customers meals were not affected for breakfast or lunch but did receive a modified menu for dinner consisting of chicken, salmon, and pasta.

-Due to the extensive delay to Train 5(10) and the upcoming UPRR Moffat Subdivision trackwork starting at 5PM-MDT on 11JUN, Train 5(10) and 6(10) bus bridged between Denver and Grand Junction. Train 6(10) had four buses secured to arrive to Grand Junction at 1:30PM-MDT to bus bridge Grand Junction to Denver. One bus operated Grand Junction, Glenwood Springs, Denver and the other three operated express. Two ADA customers at Glenwood Springs were also provided vans. Train 5(10) had five buses secured between Denver and Grand Junction to be onsite upon train arrival. Bus#1 made stops to Denver, Glenwood Springs, and Grand Junction and the other four buses operated express. Local transportation was provided for customers destined to Winter Park and Granby for both trains. Customers for trains 5(10) and 6(10) set to board at Winter Park and Granby were notified of no alternate and to rebook to the next available.

-Additional service adjustments were made due to the late operations of Train 5(10). Train 5(10) was terminated at Reno, NV with alternate bus transportation provided

at Reno, NV from train 5(10) equipment. Passengers between LHM and Reno were accommodated on Train 720(13) to SAC then boarded a bus from SAC to RNO; 3 express busses and 1 local bus making all intermediate stops. Train 5(10) arrived at Sacramento 13JUN at 9:30AM-PT.

Cardinal

Train 50(11) was delayed due to tornado warnings at MP25.1 north of Dyer, IN station on the CSX Monon subdivision. 50(11) was delayed again between Dyer and Rensselaer due to trees down.

Carl Sandberg:

Train 383(11) was delayed at holding at Mendota IL station/MP82.8 on the BNSF Mendota subdivision due to down tress reported on the tracks ahead. Train 383(11) was back on the move at 824PM CT. Train 382(11) was delayed beginning at MP263.4 north of Quincy IL station on the BNSF Brookfield subdivision due to high wind warnings until MP240.

Lincoln

Train 318(11) was delayed holding at Springfield IL station/MP185.1 due to high wind warnings.

Train 318(11) struck a debris knocking out both headlights and one ditch light. Train 318(11) advanced to the Normal siding to meet train 306(11) so that they could couple up and double draft. After coupling up both trains were back on the move at 945PM CT.

Train 305(11) was delayed holding at MP170 north of Springfield IL station for a track inspector to release the tracks due to debris from the severe weather.

Illini Service:

Train 392(11) was delayed holding at MP101.2 due to downed trees south of Gilman IL station.

City Of New Orleans

Train 59(11) was delayed holding at MP83.2 due to downed trees south of Gilman IL station.

NS Chicago subdivision down power lines :

Trains 41(11), 370(11) and 355(11) were delayed due to downed power lines on the Norfolk Southern Chicago subdivision. Trains 41(10) and 370(11) reversed to Chicago IL station. 370(11) terminated Chicago IL station with alternate bus transportation secure Chicago IL to Grand Rapids MI. Train 41(11) coupled with train 48/448(11) and double drafted to Toledo OH station. 355(11) reversed to Michigan City to meet alternate bus transportation for Hammond IN and Chicago IL station. 371(12) was cancelled in it's entirety with no alternate transportation due to train 370(11) being cancelled. Train 350(12) delayed departing Chicago IL station. Train 48/448(11) and 41(11) double draft departed Chicago IL Station at 321AM CT. Train 355(11) deadhead equipment on the move to Chicago IL station at 241AM CT.

WBS#: B.TR.100150.6762

Train	Delay	Comment
-------	-------	---------

49/449 (09)	15"	W/ELY, flash flood warnings
40 (08)	04"	W/ELY, flash flood warnings
48/448 (09)	28"	E/TUN, flash flood warnings
41 (09)	15"	E/TOL, flash flood warnings
50 (09)	29"	E/IND, high winds/track insp
8/28 (08)	52"	W/MSP, downed tree
8/28 (08)	44"	E/RDW, PTC c/o after tree strike
8/28 (08)	20"	E/RDW, tree strike
22 (09) /422 (07)		
1333 (10)	28"	E/POG, tree strike
3 (10)	33"	W/NPV, high wind warnings
21 (10)	1'07"	S/JOL, high wind/tornado warning
5 (10)	1'28"	W/NPV, high wind warnings
1340 (10)	50"	
352 (10)	1'29"	W/NBU, downed tree
393 (10)	51"	
318 (10)	32"	
383 (10)	41"	PLO-MDT
382 (10)	1'14"	MAC-GBB
5 (10)	1'45"	GBB-BRL
5 (10)	1'36"	HOLD OTM
3 (10)	1'16"	HOLD LAP RE-CREW
3 (10)	4'51"	FMD-LAP FLOOD WIND
370 (10)	48"	
1333 (10)	49"	W/POG, PTC c/o
3 (10)	35"	W/LAP FF
3 (10)	10"	West Marceline - Recrew
5 (10)	3'13"	OTM - OSC Flash Floods MP281-MP347
6 (09)	55"	LNK-OMA High Winds
4 (09)	1'00"	High Winds/Flash Floods KCY-FMD
6 (09)	9'08"	W/CRN POWERLINES
5 (10)	1'31"	RECREW W/CRN
5 (10)	9'12"	W/CRN POWERLINES
382 (11)	40"	
50 (11)	58"	TORNADO W N/DYE
6 (13)	Originated RNO	
5 (10)	Terminated RNO	
383 (11)	40"	
50 (11)	59"	DYE-REN TREES DOWN
306 (11)	38"	COUPLE 318 (11)
318 (11)	1'20"	COUPLE 306 (11)
318 (11)	32"	High Winds SPI
59 (11)	1'20"	TREES S/GLM
392 (11)	1'39"	TREES S/GLM
305 (11)	35"	HOLD MP170 TI
5 (10)	1'28"	RECREW E/MCK
370 (11)	Term CHI	
355 (11)	Term NBU	
371 (12)	Cancelled No ALT	

UPRR Moffat Tunnel Subdivision - Scheduled M/W Work 26-060

11JUN26: Union Pacific has tunnel rehabilitation scheduled on the Moffat Tunnel Subdivision starting June 11th at 5:00PM through June 12th at 1:00PM. To accommodate the above outlined infrastructure work, Amtrak's California Zephyr Service will be adjusted as follows:

-Train 5(11Jun), which normally operates between CHI and EMY, will operate as Train 5(11Jun) CHI to DEN, as Bus 3005(12Jun) DEN to GJT, and as Train 1005(12Jun) GJT-EMY. Bus 3005(12Jun) will provide alternate transportation at DEN, GSC, and GJT. The bus will not be stopping at WIP or GRA.

-Train 6(11Jun), which normally operates between EMY and CHI, will operate as Train 6(11Jun) EMY to GJT, as Bus 3006(12Jun) GJT to DEN, and as Train 1006(12Jun) DEN-CHI. Bus 3006(12Jun) will provide alternate transportation at GJT, GSC and DEN. The bus will not be stopping at GRA or WIP.

EQUIPMENT

-After arriving at DEN, Train 5(11Jun) will wye and the equipment will represent Train 1006(12Jun) from DEN to CHI.

-Train 6(11Jun) will operate with diesel engines back-to-back and will wye upon arrival in GJT. Should the wye be unavailable, the engines will run around the train. The equipment will represent Train 1005(12Jun) from GJT to EMY.

Update: Due to the continued late operation of Train 5(10) from weather and the previously scheduled UPRR trackwork, the following California Zephyr service adjustments were implemented;

Train 5(10) and Train 6(10) were cancelled between Grand Junction, CO and Denver, CO, with alternate transportation provided via bus-bridge between Grand Junction and Denver.

Train 5(10) equipment, upon arrival at Denver, will turn and represent Train 6(10) Denver to Chicago. Train 6(10) equipment, upon arrival at Grand Junction, will turn and represent Train 5(10) Grand Junction to Emeryville, holding for arrival of customers from delayed Train 5(10) at Denver.

WBS#: B.TR.100150.6655

13APR26: BNSF will perform multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

26APR26: Canadian National has scheduled trackwork on the Yazoo Subdivision between MP94 and MP126 starting on April 27th through May 29th. To accommodate this infrastructure work, Amtrak's City of New Orleans Service has been adjusted as follows:
24MAY26: Track work extended through June 19th, 2026.

-Train 1059 (26Apr) will operate in lieu of Train 59(26Apr), departing Chicago 2-hours Earlier, at 6:05pm, and will operate on an adjusted schedule between Chicago and New Orleans.

-Train 59(27Apr-18JUN) will depart Chicago 2-hours Earlier, at 6:05pm, and operate on an adjusted schedule between Chicago and New Orleans.

-Train 1058(27Apr) will operate in lieu of Train 58(27Apr), departing New Orleans 2-hours Earlier, at 11:45am, and will operate on an adjusted schedule between New Orleans and Chicago.

-Train 58(28Apr-19JUN) will depart New Orleans 2-hours Earlier, at 11:45am, and will operate on an adjusted schedule between New Orleans and Chicago.

WBS#: B.TR.100150.6608

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

09APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

WBS#: B.TR.100150.6620

Western Region

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
1(10)	ELP	140	Lost all traction motors	Enroute	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
774	IRV	1	OLT	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00532

00000007812

"UNCLASSIFIED"

6/17/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
179 (11)	BOS	Please lock Business class seats 7D and 7F as these seats are missing	no impact	0	81546
59 (11)	CHI	Utilizing bag coach in lieu of standard coach. No passengers impacted by this change.	No impact	0	31043
5 (12)	CHI	Operating with T-Dorm w/o H room. Schedule change has been performed. Customer Svc will need to accommodate passengers impacted by this.	Passenger moved to Bedroom	2	39006
6 (15)	EMY	Operating with T-Dorm w/o H room. Schedule change has been made. Customer Svc will need to accommodate passengers impacted by this.	Passenger re-booked to next day with same accommodation	2	39006
566 (11)	LAX	NO BIKE SERVICE- BV over capacity	Passenger notified	1	90225
584 (11)	LAX	NO BIKE SERVICE	No impact	0	90225
580 (11)	LAX	NO BIKE SERVICE- over capacity	Passengers notified	2	9700
562 (11)	LAX	NO BIKE SERVICE- over capacity	Passengers notified	3	9700
4 (11)	LAX	Snack Coach in lieu of coach. Over capacity in LY sales. Please accomodate all passengers who are affected.	Passenger moved to upper level	2	35010
186 (11)	NPN	Operating a car short, no impact to customers.	0	0	48140
97 (11)	NYP	(9711) Viewliner II in lieu of Viewliner I sleeper-sleeper/crew. Please run war report as passengers were changed.	Passengers re-booked	3	62517
66 (11)	RNK	Due to broken shock, car will be moved to headend and be cut off in washington. this will cause overcapacity starting at NYP. Please notify those pax	No impact-resolved	0	82773
579 (11)	SAN	NO BIKE SERVICE- BV sales over capacity	Passenger notified	2	90225
595 (11)	SAN	NO BIKE SERVICE	No impact	0	90225
591 (11)	SAN	NO BIKE SERVICE	No impact	0	9700

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
573 (11)	SAN	NO BIKE SERVICE- over capacity	Passengers notified	3	9700
90 (12)	SAV	90(12) WILL OPERATE SHORT 1 COACH DUE TO HVAC. INV ADJUSTED, OVERCAPACITY CONDITONS EXIST. PLEASE NOTIFY AFFECTED PAX	No impact-Resolved	0	25001
311 (11)	STL	NO WIFI-AWAITING PARTS	0	0	48181
184 (11)	WAS	Per conductor cars 82807 & 82667 are running hot. sales have been closed.	Sales have been closed	0	81540

Reverse Consists

Train Number	Station	Reason
95 (11)	BOS	Consist reversed Business class seat orientation may have changed At Front
113 (11)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (11)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (11)	NYP	Consist reversed Business class seat orientation may have changed At Front
136 (11)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (12)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 125(12)**
174 (11)	WAS	Consist reversed Business class seat orientation may have changed At Front
193 (11)	NYP	Consist reversed Business class seat orientation may have changed At Front
182 (11)	WAS	Consist reversed Business class seat orientation may have changed At Rear
94 (12)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 94(12)**