

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, August 22, 2026

Rules: 3-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/21/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/21/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	44	86.4%	6,463	1,042	83.9%	97,407	13,594	86.0%
Central Division	86.0%	56	10	82.1%	1,192	156	86.9%	18,620	1,730	90.7%
East Division	82.0%	175	18	89.7%	3,496	544	84.4%	51,166	7,962	84.4%
West Division	86.0%	93	16	82.8%	1,775	342	80.7%	27,621	3,902	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

 26-FOI-00703 00000008737 "UNCLASSIFIED" 9/2/2026

Endpoint Arrival Dates through 8/21/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	110,119	31,009	72%	2,234,274	682,688	69%	32,567,272	8,324,038	74%
Northeast Corridor	81%	48,196	9,785	80%	974,800	252,819	74%	14,276,313	3,508,847	75%
Acela	83%	11,250	1,043	91%	204,916	44,227	78%	2,865,340	745,778	74%
Northeast Regional	79%	36,946	8,742	76%	769,884	208,592	73%	11,410,973	2,763,069	76%
Richmond / Newport News / Norfolk	77%	11,008	3,583	67%	238,089	85,311	64%	3,538,065	1,046,772	70%
Springfield Shuttles	89%	625	147	76%	13,062	2,107	84%	200,789	31,975	84%
Roanoke	79%	4,149	1,072	74%	76,618	22,585	71%	1,081,902	241,241	78%
On Spine Northeast Regional	80%	21,164	3,940	81%	442,115	98,589	78%	6,590,217	1,443,081	78%
State Supported	80%	50,588	14,434	71%	1,007,414	280,116	72%	14,317,033	3,086,041	78%
Borealis	80%	596	266	55%	12,457	3,241	74%	182,083	38,873	79%
Capitol Corridor	90%	4,200	329	92%	78,567	12,205	84%	1,194,286	157,954	87%
Carolinian	70%	1,096	746	32%	23,331	10,578	55%	368,213	145,577	60%
Cascades	75%	2,939	697	76%	38,666	18,561	52%	821,916	233,597	72%
Downeaster	82%	1,971	53	97%	42,346	5,375	87%	502,659	61,330	88%
Empire	78%	6,737	1,959	71%	134,569	45,443	66%	1,778,282	428,902	76%
Adirondack	72%	408	0	100%	9,666	4,815	50%	109,629	35,660	67%
Ethan Allen Express	70%	659	625	5%	12,556	7,979	36%	181,464	68,328	62%
Maple Leaf	70%	917	443	52%	19,278	8,755	55%	219,627	85,598	61%
New York - Albany	85%	2,684	196	93%	60,004	14,170	76%	822,352	140,097	83%
New York - Niagara Falls	75%	1,506	207	86%	30,182	7,450	75%	434,214	93,131	79%
Berkshire Flyer	60%	563	488	13%	2,883	2,274	21%	10,996	6,088	45%
Gold Runner	73%	2,276	1,362	40%	50,769	27,135	47%	806,335	297,588	63%
Heartland Flyer	70%	231	231	0%	4,907	3,538	28%	69,590	28,960	58%
Hiawatha	90%	1,805	1,065	41%	42,899	4,667	89%	563,818	62,364	89%
Illinois	78%	2,927	749	74%	56,212	21,971	61%	802,436	226,526	72%
Carl Sandburg / Illinois Zephyr	85%	292	119	59%	9,146	4,044	56%	133,946	38,202	71%
Illini / Saluki	85%	1,096	34	97%	17,033	7,409	57%	276,920	69,309	75%
Lincoln Service	70%	1,539	596	61%	30,033	10,518	65%	391,570	119,015	70%
Keystone	92%	8,924	1,868	79%	166,141	12,646	92%	2,448,260	252,192	90%
Lincoln / Missouri	70%	1,281	1,016	21%	18,204	12,895	29%	250,695	131,203	48%
Mardi Gras Service	80%	277	159	43%	6,521	1,518	77%	130,242	29,133	78%
Michigan	70%	2,404	1,280	47%	51,676	25,870	50%	649,101	218,291	66%
Blue Water	70%	664	422	36%	13,127	7,677	42%	152,785	63,505	58%
Pere Marquette	85%	0	0	-	4,977	951	81%	83,411	16,075	81%
Wolverine	70%	1,740	858	51%	33,572	17,242	49%	412,905	138,711	66%
Missouri	80%	294	294	0%	5,778	3,517	39%	71,614	19,953	72%
Pacific Surfliner	85%	9,599	2,326	76%	208,585	52,781	75%	2,620,757	482,488	82%
Pennsylvanian	80%	997	0	100%	18,426	3,352	82%	284,228	54,429	81%
Piedmont	80%	1,304	0	100%	21,051	4,259	80%	361,325	92,911	74%
Vermont	75%	730	34	95%	26,309	10,564	60%	411,193	123,770	70%
Long Distance	70%	11,335	6,790	40%	252,060	149,753	41%	3,934,659	1,726,687	56%
Auto Train	70%	885	400	55%	18,161	5,336	71%	252,570	86,125	66%
California Zephyr	70%	865	719	17%	20,737	14,638	29%	312,331	121,295	61%
Cardinal	70%	0	0	-	3,082	2,111	32%	74,563	37,654	50%
City Of New Orleans	75%	658	658	0%	12,454	10,136	19%	203,678	68,315	66%
Coast Starlight	70%	1,228	381	69%	20,925	9,968	52%	365,602	130,430	64%
Crescent	70%	0	0	-	16,797	5,233	69%	296,450	91,216	69%
Empire Builder	70%	1,105	575	48%	21,583	12,904	40%	309,950	155,109	50%
Floridian	60%	1,886	1,725	9%	29,509	24,842	16%	507,275	351,884	31%
Lake Shore Ltd	73%	1,279	58	95%	24,377	9,580	61%	311,614	94,686	70%
Palmetto	70%	854	134	84%	18,977	9,740	49%	295,080	92,349	69%
Silver Meteor	70%	919	797	13%	20,717	14,287	31%	325,917	151,638	53%
Southwest Chief	60%	937	625	33%	19,128	15,208	20%	269,594	177,801	34%
Sunset Ltd	70%	280	279	0%	5,018	3,929	22%	93,384	36,697	61%
Texas Eagle	70%	439	439	0%	20,595	11,841	43%	316,651	131,488	58%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00700 00000000707 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 21, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	145,161	2,235,089	649	1,935,240	34,183,027	566

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,877	685,849	115	93,789	9,882,851	95
INFRASTRUCTURE PLANNED	135	13,519	685,849	197	109,574	9,882,851	111
FLEET RELIABILITY	90	22,793	2,235,089	102	308,933	34,183,027	90
TRAIN OPERATIONS	424	100,972	2,235,089	452	1,422,944	34,183,027	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/21/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/21/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	44	86.4%	6,463	1,042	83.9%	97,407	13,594	86.0%
Central Division	86.0%	56	10	82.1%	1,192	156	86.9%	18,620	1,730	90.7%
East Division	82.0%	175	18	89.7%	3,496	544	84.4%	51,166	7,962	84.4%
West Division	86.0%	93	16	82.8%	1,775	342	80.7%	27,621	3,902	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/21/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/21/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	44	86.4%	6,463	1,042	83.9%	97,407	13,594	86.0%
Central Division	86.0%	56	10	82.1%	1,192	156	86.9%	18,620	1,730	90.7%
CDL	95.0%	2	0	100.0%	40	6	85.0%	616	31	95.0%
CHI	86.0%	27	6	77.8%	553	103	81.4%	8,603	1,070	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	21	1	95.2%	348	37	89.4%
GBB	-	-	-	-	2	1	50.0%	15	12	20.0%
GRR	95.5%	-	-	-	17	3	82.4%	305	11	96.4%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	42	7	83.3%	629	51	91.9%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	121	9	92.6%	1,901	123	93.5%
MOE	97.5%	2	0	100.0%	42	0	100.0%	647	9	98.6%
MSP	96.5%	1	0	100.0%	21	1	95.2%	318	7	97.8%
NOL	94.5%	4	0	100.0%	92	2	97.8%	1,365	62	95.5%
OKC	97.0%	1	0	100.0%	21	0	100.0%	319	6	98.1%
PNT	88.0%	3	0	100.0%	60	7	88.3%	847	71	91.6%
PTH	93.0%	1	0	100.0%	21	2	90.5%	313	13	95.8%
QCY	91.0%	1	0	100.0%	35	4	88.6%	612	47	92.3%
SAS	90.5%	1	1	0.0%	21	4	81.0%	322	37	88.5%
STL	89.0%	4	1	75.0%	82	5	93.9%	1,257	105	91.6%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	18	89.7%	3,496	544	84.4%	51,166	7,962	84.4%
ALB	88.5%	7	0	100.0%	157	6	96.2%	2,407	181	92.5%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	105	14	86.7%	1,571	172	89.1%
BOS	85.5%	18	0	100.0%	365	29	92.1%	5,528	633	88.5%
BRK	92.5%	5	0	100.0%	93	10	89.2%	1,545	112	92.8%
BTN	82.0%	1	0	100.0%	20	1	95.0%	310	42	86.5%
CLT	91.5%	5	0	100.0%	105	10	90.5%	1,582	160	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	35	2	94.3%	628	59	90.6%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	13	0	100.0%	237	38	84.0%	3,601	586	83.7%
HFD	-	2	1	50.0%	29	4	86.2%	220	19	91.4%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	21	1	95.2%	321	39	87.9%
MIA	89.5%	2	1	50.0%	39	7	82.1%	639	75	88.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/21/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/21/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	44	86.4%	6,463	1,042	83.9%	97,407	13,594	86.0%
East Division	82.0%	175	18	89.7%	3,496	544	84.4%	51,166	7,962	84.4%
MTR	79.0%	1	0	100.0%	21	6	71.4%	308	58	81.2%
NFK	84.5%	2	0	100.0%	42	8	81.0%	725	131	81.9%
NFL	93.5%	2	0	100.0%	42	1	97.6%	654	30	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	4	0	100.0%	101	25	75.2%	1,655	278	83.2%
NPN	93.0%	2	1	50.0%	42	7	83.3%	614	48	92.2%
NYP	75.5%	51	10	80.4%	986	214	78.3%	13,470	2,992	77.8%
PGH	93.0%	1	0	100.0%	21	1	95.2%	322	23	92.9%
PHL	48.0%	5	2	60.0%	99	42	57.6%	1,649	782	52.6%
PIT	76.0%	1	1	0.0%	6	6	0.0%	21	18	14.3%
POR	-	-	-	-	12	7	41.7%	23	15	34.8%
RGH	95.0%	4	0	100.0%	76	3	96.1%	1,234	52	95.8%
RNK	83.5%	2	1	50.0%	42	4	90.5%	638	91	85.7%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	17	0	100.0%	304	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	21	1	95.2%	318	11	96.5%
SFA	88.0%	1	0	100.0%	21	3	85.7%	321	44	86.3%
SPG	92.5%	4	0	100.0%	101	6	94.1%	1,908	111	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	21	3	85.7%	310	63	79.7%
WAS	84.0%	31	1	96.8%	611	85	86.1%	8,083	1,052	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	93	16	82.8%	1,775	342	80.7%	27,621	3,902	85.9%
ARN	92.0%	1	0	100.0%	21	2	90.5%	323	28	91.3%
BFD	79.0%	7	6	14.3%	146	42	71.2%	2,043	435	78.7%
EMY	72.0%	1	0	100.0%	21	3	85.7%	339	97	71.4%
EUG	86.5%	2	0	100.0%	42	2	95.2%	640	58	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	1	0	100.0%	2	0	100.0%	6	3	50.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	63	18	71.4%	972	161	83.4%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	4	63.6%	216	26	88.0%	3,215	352	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	12	3	75.0%	246	87	64.6%	3,507	915	73.9%
PDX	86.0%	5	0	100.0%	60	32	46.7%	1,548	213	86.2%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/21/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/21/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	324	44	86.4%	6,463	1,042	83.9%	97,407	13,594	86.0%
West Division	86.0%	93	16	82.8%	1,775	342	80.7%	27,621	3,902	85.9%
SAC	88.5%	16	1	93.8%	309	30	90.3%	4,575	492	89.2%
SAN	90.5%	13	0	100.0%	268	23	91.4%	3,909	367	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	0	100.0%	96	34	64.6%	2,481	381	84.6%
SJC	89.0%	7	1	85.7%	146	17	88.4%	2,270	226	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	63	6	90.5%	735	71	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	7	4	42.9%	305	30	90.2%
VAC	97.0%	2	0	100.0%	42	0	100.0%	633	14	97.8%
VAN	-	-	-	-	27	16	40.7%	27	16	40.7%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	243	9	1	88.9%	137	10	92.7%	8	7	12.5%	137	38	72.3%
2	167	9	4	55.6%	138	35	74.6%	9	4	55.6%	133	28	78.9%
3	100	21	5	76.2%	323	64	80.2%	20	14	30.0%	320	150	53.1%
4		21	3	85.7%	322	49	84.8%	21	15	28.6%	322	214	33.5%
5	38	21	4	81.0%	321	54	83.2%	21	17	19.0%	317	105	66.9%
6	109	21	3	85.7%	320	88	72.5%	21	17	19.0%	320	120	62.5%
7		21	8	61.9%	312	50	84.0%	20	8	60.0%	303	82	72.9%
8	145	21	11	47.6%	312	140	55.1%	21	15	28.6%	311	190	38.9%
11		21	15	28.6%	323	72	77.7%	21	6	71.4%	317	66	79.2%
14		21	3	85.7%	324	52	84.0%	20	10	50.0%	321	102	68.2%
19	238	21	4	81.0%	322	81	74.8%	21	7	66.7%	319	78	75.5%
20	No OS	21	0	100.0%	322	23	92.9%	21	6	71.4%	322	64	80.1%
21	No OS	21	8	61.9%	319	33	89.7%	21	9	57.1%	318	91	71.4%
22	709	21	4	81.0%	320	35	89.1%	21	12	42.9%	318	93	70.8%
23	46	21	0	100.0%	324	6	98.1%	21	4	81.0%	322	89	72.4%
24		21	0	100.0%	324	16	95.1%	21	6	71.4%	323	62	80.8%
25	74	21	0	100.0%	323	3	99.1%	20	9	55.0%	320	92	71.3%
26		21	0	100.0%	323	5	98.5%	20	2	90.0%	320	62	80.6%
27	78	7	6	14.3%	292	22	92.5%	4	4	0.0%	285	97	66.0%
28	99	3	2	33.3%	284	66	76.8%	3	2	33.3%	284	58	79.6%
40	75	18	6	66.7%	314	47	85.0%	17	13	23.5%	310	168	45.8%
41	160	19	8	57.9%	314	122	61.1%	18	16	11.1%	311	240	22.8%
42		21	1	95.2%	324	25	92.3%	21	4	81.0%	322	56	82.6%
43		21	3	85.7%	323	45	86.1%	21	3	85.7%	322	73	77.3%
48		21	5	76.2%	322	62	80.7%	21	6	71.4%	321	48	85.0%
49		21	6	71.4%	322	81	74.8%	21	6	71.4%	322	68	78.9%
50	203	7	3	57.1%	131	33	74.8%	6	5	16.7%	130	81	37.7%
52	43	21	3	85.7%	321	44	86.3%	21	2	90.5%	320	74	76.9%
53		21	1	95.2%	321	39	87.9%	21	8	61.9%	320	103	67.8%
55	140	15	2	86.7%	205	9	95.6%	15	6	60.0%	202	44	78.2%
56		15	2	86.7%	206	25	87.9%	15	5	66.7%	202	39	80.7%
58	250	20	1	95.0%	297	17	94.3%	19	17	10.5%	295	90	69.5%
59	127	21	14	33.3%	296	47	84.1%	20	17	15.0%	291	74	74.6%
63	36	21	8	61.9%	325	140	56.9%	21	21	0.0%	319	187	41.4%
64	25	21	3	85.7%	323	71	78.0%	21	17	19.0%	322	126	60.9%
66		21	2	90.5%	322	63	80.4%	21	5	76.2%	318	59	81.4%
67		15	1	93.3%	223	14	93.7%	15	4	73.3%	223	40	82.1%
68		21	6	71.4%	325	67	79.4%	21	12	42.9%	324	130	59.9%
69		21	10	52.4%	312	78	75.0%	21	10	52.4%	307	53	82.7%
71		21	0	100.0%	320	3	99.1%	20	4	80.0%	318	85	73.3%
72		21	4	81.0%	316	35	88.9%	20	7	65.0%	314	68	78.3%
73		21	3	85.7%	319	22	93.1%	21	5	76.2%	317	147	53.6%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74		21	1	95.2%	317	34	89.3%	21	6	71.4%	315	114	63.8%
75		21	0	100.0%	313	16	94.9%	21	9	57.1%	307	146	52.4%
76		21	1	95.2%	313	30	90.4%	21	10	52.4%	304	127	58.2%
77		21	0	100.0%	315	20	93.7%	21	6	71.4%	313	129	58.8%
78	13	21	1	95.2%	319	26	91.8%	21	10	52.4%	318	73	77.0%
79	60	21	2	90.5%	322	58	82.0%	21	8	61.9%	321	109	66.0%
80		21	3	85.7%	322	36	88.8%	21	8	61.9%	319	71	77.7%
84	17	15	4	73.3%	196	18	90.8%	13	5	61.5%	192	48	75.0%
85		15	2	86.7%	207	18	91.3%	15	4	73.3%	207	74	64.3%
86		15	1	93.3%	207	16	92.3%	15	4	73.3%	206	119	42.2%
89		21	11	47.6%	320	76	76.3%	21	10	52.4%	318	95	70.1%
90		21	1	95.2%	320	11	96.6%	21	8	61.9%	319	59	81.5%
93		15	2	86.7%	206	21	89.8%	15	7	53.3%	205	54	73.7%
94	104	15	4	73.3%	237	59	75.1%	15	5	66.7%	235	88	62.6%
95		15	2	86.7%	206	6	97.1%	15	11	26.7%	206	80	61.2%
97	150	21	15	28.6%	322	213	33.9%	21	16	23.8%	320	116	63.8%
98	335	21	1	95.2%	322	27	91.6%	21	13	38.1%	320	121	62.2%
110	22	15	4	73.3%	203	106	47.8%	15	2	86.7%	200	21	89.5%
111		15	1	93.3%	197	36	81.7%	15	1	93.3%	195	22	88.7%
112		15	1	93.3%	197	19	90.4%	15	0	100.0%	196	19	90.3%
113		15	6	60.0%	128	31	75.8%	15	1	93.3%	127	15	88.2%
119		15	3	80.0%	194	48	75.3%	15	4	73.3%	192	26	86.5%
125		15	1	93.3%	207	12	94.2%	15	8	46.7%	207	82	60.4%
129		15	3	80.0%	206	50	75.7%	15	2	86.7%	206	30	85.4%
130		15	2	86.7%	197	20	89.8%	15	0	100.0%	195	16	91.8%
131		15	3	80.0%	199	56	71.9%	15	3	80.0%	199	38	80.9%
134		15	4	73.3%	207	31	85.0%	15	6	60.0%	206	42	79.6%
136	87	15	2	86.7%	207	26	87.4%	15	3	80.0%	205	28	86.3%
137		15	1	93.3%	204	36	82.4%	15	4	73.3%	204	62	69.6%
138		15	2	86.7%	207	41	80.2%	15	4	73.3%	206	38	81.6%
141		15	1	93.3%	206	4	98.1%	15	3	80.0%	205	36	82.4%
148		15	2	86.7%	206	22	89.3%	15	4	73.3%	204	40	80.4%
151		21	7	66.7%	321	102	68.2%	21	3	85.7%	320	98	69.4%
170		15	0	100.0%	202	12	94.1%	15	1	93.3%	201	30	85.1%
171		15	0	100.0%	207	11	94.7%	15	10	33.3%	207	85	58.9%
172		15	4	73.3%	206	19	90.8%	15	7	53.3%	204	69	66.2%
173		15	1	93.3%	199	25	87.4%	15	5	66.7%	198	83	58.1%
174		15	2	86.7%	207	22	89.4%	15	4	73.3%	207	52	74.9%
175		15	1	93.3%	207	23	88.9%	15	6	60.0%	207	68	67.1%
176		15	2	86.7%	199	17	91.5%	15	2	86.7%	197	26	86.8%
177		15	1	93.3%	207	28	86.5%	15	1	93.3%	207	47	77.3%
178	30	15	1	93.3%	207	27	87.0%	15	4	73.3%	205	35	82.9%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179	105	15	2	86.7%	207	25	87.9%	15	5	66.7%	206	75	63.6%
181		15	4	73.3%	203	63	69.0%	14	1	92.9%	200	16	92.0%
182		15	1	93.3%	197	31	84.3%	15	0	100.0%	195	21	89.2%
183		15	6	60.0%	206	62	69.9%	15	5	66.7%	203	43	78.8%
184		15	3	80.0%	207	36	82.6%	15	1	93.3%	206	28	86.4%
185	34	15	3	80.0%	207	40	80.7%	15	3	80.0%	207	17	91.8%
186		15	6	60.0%	206	27	86.9%	15	7	53.3%	205	60	70.7%
190		15	4	73.3%	206	73	64.6%	15	1	93.3%	205	44	78.5%
192		15	0	100.0%	204	24	88.2%	15	2	86.7%	204	19	90.7%
193		14	5	64.3%	202	83	58.9%	14	2	85.7%	201	90	55.2%
196		15	3	80.0%	203	23	88.7%	14	2	85.7%	201	17	91.5%
197		15	1	93.3%	207	76	63.3%	15	3	80.0%	207	70	66.2%
198		15	0	100.0%	139	17	87.8%	15	1	93.3%	138	22	84.1%
230		21	0	100.0%	158	4	97.5%	21	1	95.2%	158	8	94.9%
232		21	0	100.0%	324	11	96.6%	21	2	90.5%	324	23	92.9%
234		21	0	100.0%	325	22	93.2%	21	1	95.2%	324	26	92.0%
235		21	7	66.7%	249	41	83.5%	21	5	76.2%	248	57	77.0%
236		21	0	100.0%	309	10	96.8%	21	3	85.7%	308	42	86.4%
237		21	1	95.2%	322	57	82.3%	21	4	81.0%	320	55	82.8%
238		21	3	85.7%	249	23	90.8%	21	3	85.7%	247	21	91.5%
239		21	2	90.5%	323	81	74.9%	21	2	90.5%	322	40	87.6%
240		21	1	95.2%	324	22	93.2%	21	5	76.2%	321	65	79.8%
241		21	7	66.7%	324	81	75.0%	21	7	66.7%	324	78	75.9%
243	23	21	4	81.0%	260	69	73.5%	21	5	76.2%	259	38	85.3%
245		21	6	71.4%	205	39	81.0%	21	7	66.7%	204	29	85.8%
280		21	1	95.2%	325	16	95.1%	21	10	52.4%	324	71	78.1%
281		21	3	85.7%	325	40	87.7%	21	2	90.5%	325	59	81.8%
283		21	9	57.1%	325	83	74.5%	21	3	85.7%	325	64	80.3%
284		21	0	100.0%	325	13	96.0%	21	2	90.5%	322	56	82.6%
290	27	21	1	95.2%	325	51	84.3%	21	15	28.6%	322	129	59.9%
291	25	21	14	33.3%	324	107	67.0%	20	9	55.0%	321	85	73.5%
300		20	2	90.0%	308	22	92.9%	19	5	73.7%	305	73	76.1%
301	17	21	0	100.0%	322	10	96.9%	21	6	71.4%	318	61	80.8%
302	17	20	0	100.0%	303	33	89.1%	20	10	50.0%	299	88	70.6%
305		20	3	85.0%	306	31	89.9%	19	5	73.7%	301	120	60.1%
306		21	1	95.2%	320	17	94.7%	20	5	75.0%	318	87	72.6%
307		21	4	81.0%	313	42	86.6%	20	9	55.0%	309	91	70.6%
311	132	21	2	90.5%	318	28	91.2%	21	14	33.3%	312	77	75.3%
316	57	21	4	81.0%	314	22	93.0%	21	16	23.8%	309	94	69.6%
318		21	3	85.7%	323	34	89.5%	21	14	33.3%	320	158	50.6%
319	81	21	0	100.0%	324	20	93.8%	21	20	4.8%	319	185	42.0%
329		15	0	100.0%	230	9	96.1%	15	1	93.3%	230	16	93.0%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
330		18	0	100.0%	276	6	97.8%	18	0	100.0%	276	15	94.6%
331		21	0	100.0%	325	33	89.8%	20	0	100.0%	324	44	86.4%
332		20	1	95.0%	324	18	94.4%	20	2	90.0%	324	45	86.1%
334	118	21	1	95.2%	325	11	96.6%	20	3	85.0%	323	43	86.7%
335	Cncld	21	1	95.2%	325	35	89.2%	20	4	80.0%	322	55	82.9%
336	30	20	0	100.0%	324	10	96.9%	20	1	95.0%	322	29	91.0%
337	19	21	2	90.5%	325	20	93.8%	21	6	71.4%	321	42	86.9%
338	Cncld	21	5	76.2%	325	52	84.0%	20	7	65.0%	322	101	68.6%
339		21	3	85.7%	325	53	83.7%	21	3	85.7%	325	56	82.8%
341	27	19	5	73.7%	311	49	84.2%	19	10	47.4%	305	51	83.3%
342	19	21	2	90.5%	325	26	92.0%	21	1	95.2%	323	61	81.1%
350	23	19	1	94.7%	300	19	93.7%	18	15	16.7%	292	166	43.2%
351	26	20	2	90.0%	307	29	90.6%	20	10	50.0%	305	88	71.1%
352		20	3	85.0%	291	24	91.8%	20	9	55.0%	285	90	68.4%
353		21	0	100.0%	263	13	95.1%	21	9	57.1%	257	47	81.7%
354	30	21	1	95.2%	306	36	88.2%	21	13	38.1%	299	114	61.9%
355	53	19	5	73.7%	313	36	88.5%	17	15	11.8%	304	114	62.5%
364		21	7	66.7%	314	72	77.1%	21	11	47.6%	308	118	61.7%
365	42	21	2	90.5%	313	13	95.8%	20	12	40.0%	310	121	61.0%
370	131	17	4	76.5%	312	39	87.5%	14	5	64.3%	299	74	75.3%
380		18	2	88.9%	307	29	90.6%	17	6	64.7%	306	69	77.5%
383	24	19	1	94.7%	312	27	91.3%	19	10	47.4%	309	133	57.0%
390		20	5	75.0%	306	24	92.2%	19	11	42.1%	304	84	72.4%
391		20	3	85.0%	307	14	95.4%	19	11	42.1%	302	87	71.2%
392		20	1	95.0%	320	11	96.6%	18	8	55.6%	315	98	68.9%
393		20	1	95.0%	324	19	94.1%	19	10	47.4%	320	101	68.4%
425		14	1	92.9%	218	7	96.8%	13	0	100.0%	217	7	96.8%
448		15	2	86.7%	249	45	81.9%	14	5	64.3%	245	85	65.3%
449		15	1	93.3%	246	33	86.6%	15	2	86.7%	246	44	82.1%
470		15	2	86.7%	230	39	83.0%	15	3	80.0%	224	27	87.9%
471	22	14	3	78.6%	219	14	93.6%	14	1	92.9%	219	6	97.3%
473		15	0	100.0%	226	15	93.4%	15	0	100.0%	223	10	95.5%
475		14	1	92.9%	223	7	96.9%	14	0	100.0%	223	15	93.3%
478		15	3	80.0%	218	35	83.9%	15	1	93.3%	216	28	87.0%
479		15	2	86.7%	225	36	84.0%	15	4	73.3%	223	35	84.3%
486		15	3	80.0%	229	34	85.2%	15	3	80.0%	223	61	72.6%
494	30	16	6	62.5%	232	47	79.7%	15	6	60.0%	224	63	71.9%
495		15	0	100.0%	214	4	98.1%	15	0	100.0%	212	3	98.6%
500		4	0	100.0%	299	16	94.6%	4	0	100.0%	296	35	88.2%
502		5	0	100.0%	307	18	94.1%	5	1	80.0%	303	59	80.5%
503	16	21	13	38.1%	321	40	87.5%	21	14	33.3%	314	101	67.8%
504		21	1	95.2%	325	20	93.8%	21	6	71.4%	323	96	70.3%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		15	1	93.3%	317	42	86.8%	15	4	73.3%	312	88	71.8%
506		21	13	38.1%	320	55	82.8%	19	3	84.2%	312	49	84.3%
507	139	21	12	42.9%	325	48	85.2%	21	12	42.9%	325	112	65.5%
508		21	1	95.2%	320	42	86.9%	21	11	47.6%	316	79	75.0%
509		5	1	80.0%	306	15	95.1%	5	3	40.0%	306	69	77.5%
511		5	1	80.0%	301	25	91.7%	5	2	60.0%	300	52	82.7%
516	90	21	6	71.4%	316	35	88.9%	21	9	57.1%	315	143	54.6%
517		21	0	100.0%	325	8	97.5%	21	17	19.0%	321	144	55.1%
518	40	21	8	61.9%	325	45	86.2%	21	21	0.0%	323	228	29.4%
519		21	0	100.0%	316	9	97.2%	21	6	71.4%	314	72	77.1%
520		15	4	73.3%	188	29	84.6%	13	1	92.3%	183	10	94.5%
521		15	0	100.0%	226	7	96.9%	14	3	78.6%	225	30	86.7%
522	15	15	2	86.7%	226	41	81.9%	15	2	86.7%	223	22	90.1%
523		15	2	86.7%	226	9	96.0%	15	4	73.3%	225	26	88.4%
524		14	1	92.9%	225	17	92.4%	14	3	78.6%	222	26	88.3%
525		14	0	100.0%	223	16	92.8%	14	1	92.9%	219	15	93.2%
526		15	7	53.3%	200	41	79.5%	15	3	80.0%	197	18	90.9%
527		15	0	100.0%	226	10	95.6%	15	2	86.7%	225	39	82.7%
528		15	2	86.7%	226	19	91.6%	15	2	86.7%	225	32	85.8%
529		15	1	93.3%	226	13	94.2%	15	5	66.7%	225	63	72.0%
530		15	2	86.7%	180	18	90.0%	15	4	73.3%	180	36	80.0%
531		15	0	100.0%	200	13	93.5%	15	0	100.0%	200	13	93.5%
532		15	5	66.7%	226	56	75.2%	14	3	78.6%	224	34	84.8%
534		15	2	86.7%	185	27	85.4%	15	0	100.0%	183	16	91.3%
535		14	1	92.9%	212	26	87.7%	14	3	78.6%	207	26	87.4%
536		15	6	60.0%	226	61	73.0%	15	2	86.7%	222	40	82.0%
537		14	0	100.0%	195	22	88.7%	14	2	85.7%	189	22	88.4%
538	17	15	2	86.7%	226	26	88.5%	15	3	80.0%	225	46	79.6%
539		15	3	80.0%	180	27	85.0%	15	6	60.0%	180	77	57.2%
540		15	3	80.0%	225	41	81.8%	13	1	92.3%	215	19	91.2%
541		15	2	86.7%	225	24	89.3%	14	3	78.6%	218	39	82.1%
542		15	1	93.3%	225	25	88.9%	15	3	80.0%	222	40	82.0%
543	26	15	2	86.7%	226	26	88.5%	15	6	60.0%	226	69	69.5%
544		15	1	93.3%	224	21	90.6%	14	2	85.7%	220	22	90.0%
545		15	1	93.3%	226	18	92.0%	15	3	80.0%	223	27	87.9%
547		15	4	73.3%	226	45	80.1%	15	5	66.7%	226	52	77.0%
549		15	1	93.3%	221	27	87.8%	13	3	76.9%	211	20	90.5%
550		15	2	86.7%	180	20	88.9%	15	7	53.3%	180	43	76.1%
551		15	1	93.3%	222	23	89.6%	15	3	80.0%	212	23	89.2%
562	31	21	3	85.7%	316	26	91.8%	21	1	95.2%	312	36	88.5%
564		21	0	100.0%	317	19	94.0%	21	3	85.7%	309	41	86.7%
566		21	4	81.0%	315	29	90.8%	21	6	71.4%	312	51	83.7%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
567		21	1	95.2%	202	11	94.6%	21	2	90.5%	200	11	94.5%
572	37	21	2	90.5%	312	26	91.7%	21	9	57.1%	305	92	69.8%
573		21	3	85.7%	314	43	86.3%	21	3	85.7%	307	54	82.4%
579		21	1	95.2%	202	12	94.1%	20	3	85.0%	196	40	79.6%
580		21	1	95.2%	317	17	94.6%	21	4	81.0%	310	32	89.7%
581		21	4	81.0%	317	54	83.0%	21	8	61.9%	315	72	77.1%
584	35	21	3	85.7%	201	28	86.1%	21	19	9.5%	196	127	35.2%
587	27	21	2	90.5%	310	18	94.2%	21	7	66.7%	301	60	80.1%
588	41	19	2	89.5%	200	20	90.0%	19	7	63.2%	199	40	79.9%
591	71	21	1	95.2%	314	22	93.0%	20	5	75.0%	307	44	85.7%
593	19	18	2	88.9%	308	49	84.1%	18	2	88.9%	287	39	86.4%
595	24	19	4	78.9%	310	57	81.6%	19	7	63.2%	307	67	78.2%
600		15	0	100.0%	234	9	96.2%	15	2	86.7%	232	21	90.9%
601		15	7	53.3%	217	90	58.5%	15	2	86.7%	214	27	87.4%
605	13	15	7	53.3%	224	137	38.8%	15	1	93.3%	220	23	89.5%
607		15	0	100.0%	233	30	87.1%	15	0	100.0%	230	25	89.1%
609		15	0	100.0%	224	23	89.7%	15	3	80.0%	223	22	90.1%
626		15	4	73.3%	138	20	85.5%	15	0	100.0%	136	18	86.8%
639		15	2	86.7%	204	40	80.4%	14	0	100.0%	202	19	90.6%
640		15	0	100.0%	224	7	96.9%	15	4	73.3%	222	84	62.2%
641		15	4	73.3%	206	42	79.6%	15	1	93.3%	206	27	86.9%
642		15	2	86.7%	222	11	95.0%	15	1	93.3%	221	27	87.8%
643	21	15	0	100.0%	236	44	81.4%	15	3	80.0%	233	39	83.3%
644		15	0	100.0%	228	28	87.7%	15	3	80.0%	226	55	75.7%
645	26	15	1	93.3%	236	42	82.2%	15	8	46.7%	233	54	76.8%
646	22	15	3	80.0%	225	54	76.0%	15	9	40.0%	223	110	50.7%
647	20	15	1	93.3%	236	33	86.0%	14	1	92.9%	234	50	78.6%
648		15	2	86.7%	232	58	75.0%	15	1	93.3%	232	35	84.9%
649		15	2	86.7%	237	44	81.4%	14	0	100.0%	233	34	85.4%
650		15	4	73.3%	236	45	80.9%	15	2	86.7%	233	38	83.7%
651		15	1	93.3%	236	17	92.8%	14	1	92.9%	233	43	81.5%
652	27	15	2	86.7%	237	31	86.9%	15	4	73.3%	233	41	82.4%
653	23	15	3	80.0%	225	36	84.0%	14	2	85.7%	221	41	81.4%
654		15	4	73.3%	226	44	80.5%	15	2	86.7%	222	20	91.0%
655		15	2	86.7%	234	74	68.4%	14	2	85.7%	231	75	67.5%
656		15	6	60.0%	236	53	77.5%	14	3	78.6%	234	33	85.9%
657		15	2	86.7%	225	29	87.1%	14	1	92.9%	223	30	86.5%
658		15	2	86.7%	236	37	84.3%	15	0	100.0%	234	33	85.9%
680		15	0	100.0%	231	12	94.8%	14	0	100.0%	229	27	88.2%
681	17	15	1	93.3%	231	18	92.2%	14	6	57.1%	224	92	58.9%
682		15	3	80.0%	230	9	96.1%	15	3	80.0%	230	41	82.2%
683	16	15	1	93.3%	213	18	91.5%	15	6	60.0%	212	73	65.6%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
684		15	5	66.7%	212	37	82.5%	15	1	93.3%	212	46	78.3%
685		15	1	93.3%	227	32	85.9%	15	2	86.7%	224	55	75.4%
686		15	2	86.7%	232	39	83.2%	15	5	66.7%	231	52	77.5%
687		15	4	73.3%	231	38	83.5%	15	3	80.0%	230	39	83.0%
688		15	2	86.7%	230	15	93.5%	15	4	73.3%	229	40	82.5%
689		6	1	83.3%	151	21	86.1%	6	2	66.7%	150	23	84.7%
701		21	3	85.7%	257	28	89.1%	21	4	81.0%	254	29	88.6%
702	40	21	0	100.0%	324	32	90.1%	21	11	47.6%	321	81	74.8%
703		21	16	23.8%	325	109	66.5%	21	11	47.6%	323	96	70.3%
704	17	21	7	66.7%	256	44	82.8%	20	8	60.0%	248	54	78.2%
710		21	1	95.2%	325	78	76.0%	21	6	71.4%	321	87	72.9%
711		21	3	85.7%	316	37	88.3%	19	9	52.6%	293	61	79.2%
712		21	9	57.1%	322	89	72.4%	20	10	50.0%	312	108	65.4%
713	Cncld	20	2	90.0%	192	18	90.6%	14	9	35.7%	170	76	55.3%
714	21	21	12	42.9%	206	87	57.8%	19	14	26.3%	190	90	52.6%
715	48	21	2	90.5%	324	63	80.6%	17	11	35.3%	297	152	48.8%
716	Cncld	21	14	33.3%	325	134	58.8%	19	15	21.1%	317	133	58.0%
717	Cncld	21	6	71.4%	310	74	76.1%	16	7	56.3%	286	93	67.5%
718	138	21	16	23.8%	325	169	48.0%	20	13	35.0%	322	122	62.1%
719		21	10	52.4%	325	113	65.2%	20	10	50.0%	308	94	69.5%
757		21	2	90.5%	110	7	93.6%	21	2	90.5%	109	10	90.8%
761		21	1	95.2%	321	13	96.0%	21	2	90.5%	318	43	86.5%
765		21	0	100.0%	321	25	92.2%	21	3	85.7%	321	45	86.0%
769		21	0	100.0%	321	27	91.6%	21	4	81.0%	315	61	80.6%
770		21	2	90.5%	321	24	92.5%	21	11	47.6%	319	100	68.7%
774	91	21	0	100.0%	321	16	95.0%	21	6	71.4%	320	75	76.6%
777		21	0	100.0%	206	12	94.2%	21	8	61.9%	205	50	75.6%
782		21	15	28.6%	206	97	52.9%	21	5	76.2%	201	30	85.1%
785		21	4	81.0%	321	26	91.9%	21	5	76.2%	321	58	81.9%
786		21	2	90.5%	110	21	80.9%	20	12	40.0%	106	59	44.3%
790	44	21	1	95.2%	321	29	91.0%	21	5	76.2%	318	51	84.0%
794		21	4	81.0%	321	37	88.5%	21	6	71.4%	317	72	77.3%
821	158	21	0	100.0%	319	6	98.1%	21	14	33.3%	319	135	57.7%
822	49	21	1	95.2%	321	17	94.7%	21	19	9.5%	319	161	49.5%
1233	38	6	1	83.3%	21	5	76.2%	4	4	0.0%	19	12	36.8%
1246	30	6	6	0.0%	21	18	14.3%	6	4	33.3%	21	11	47.6%
1333	113	21	6	71.4%	321	38	88.2%	21	8	61.9%	318	107	66.4%
1340		21	1	95.2%	320	7	97.8%	20	4	80.0%	319	55	82.8%
2102		15	2	86.7%	83	15	81.9%	15	1	93.3%	82	7	91.5%
2103		15	2	86.7%	147	14	90.5%	15	1	93.3%	146	10	93.2%
2104		15	0	100.0%	173	10	94.2%	15	1	93.3%	171	13	92.4%
2107		15	1	93.3%	204	35	82.8%	15	1	93.3%	201	21	89.6%

Amtrak On Time Performance

Trains Arriving Through: 8/21/2026

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2108		15	2	86.7%	204	28	86.3%	15	7	53.3%	198	27	86.4%
2109		15	1	93.3%	97	12	87.6%	15	1	93.3%	95	5	94.7%
2112		15	2	86.7%	44	6	86.4%	15	0	100.0%	42	2	95.2%
2113		15	1	93.3%	83	9	89.2%	15	0	100.0%	83	10	88.0%
2115		15	2	86.7%	83	13	84.3%	15	1	93.3%	82	11	86.6%
2116		15	0	100.0%	44	1	97.7%	15	1	93.3%	44	8	81.8%
2118		15	2	86.7%	44	4	90.9%	15	2	86.7%	44	11	75.0%
2119		15	4	73.3%	44	8	81.8%	14	2	85.7%	43	12	72.1%
2120		15	10	33.3%	44	19	56.8%	14	9	35.7%	42	22	47.6%
2123		15	1	93.3%	82	9	89.0%	15	0	100.0%	81	15	81.5%
2124		14	4	71.4%	175	38	78.3%	14	2	85.7%	173	24	86.1%
2127		15	2	86.7%	44	9	79.5%	15	1	93.3%	43	8	81.4%
2128		15	1	93.3%	44	4	90.9%	15	1	93.3%	44	3	93.2%
2131		15	3	80.0%	44	9	79.5%	15	1	93.3%	44	4	90.9%
2150		15	0	100.0%	197	22	88.8%	15	1	93.3%	194	74	61.9%
2151	48	15	1	93.3%	146	7	95.2%	15	4	73.3%	144	41	71.5%
2152		15	1	93.3%	102	7	93.1%	15	1	93.3%	101	31	69.3%
2154		15	0	100.0%	105	23	78.1%	15	3	80.0%	101	45	55.4%
2155		15	1	93.3%	206	17	91.7%	15	4	73.3%	202	100	50.5%
2158		15	1	93.3%	43	5	88.4%	15	3	80.0%	43	15	65.1%
2159		15	2	86.7%	199	16	92.0%	15	9	40.0%	197	68	65.5%
2160		15	0	100.0%	44	2	95.5%	15	8	46.7%	43	26	39.5%
2162		15	4	73.3%	205	22	89.3%	15	5	66.7%	199	90	54.8%
2165		15	2	86.7%	41	4	90.2%	15	8	46.7%	41	21	48.8%
2167		15	0	100.0%	192	20	89.6%	15	1	93.3%	192	40	79.2%
2171		15	0	100.0%	133	10	92.5%	15	0	100.0%	129	23	82.2%
2190		15	2	86.7%	202	29	85.6%	15	1	93.3%	200	24	88.0%
2193		15	0	100.0%	197	25	87.3%	15	1	93.3%	195	50	74.4%

Amtrak Endpoint OTP Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/21/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2151	WAS	48	DCS	21	ENG	21	STM-STM	MN	Level 7 023 code had to de prepare/reboot 2149	
84	NYP	17	DCS	14	DCS	14	BAL-ABE	AM	T.O.L, Control Point, ., TOL ON ALL TRACKS BETWEEN GUNPOW AND RIVER	
94	BOS	104	FTI	45	FTI	42	ASD-FBG	CS	Cross Traffic M415, Control Point, S. Milford	
110	NYP	22	ITI	19	ITI	19	PHL-PHL	AM	Service, turn, or wye train, 179	
136	SPG	87	ENG	53	ENG	53	NHV-NHV	AM	Failure of diesel engine, 114 DX BD, 136 arrived at NHV 30 minutes late, will experience a significant additional delay on account of mechanical issues with diesel Eng 114. Eng 100 has been mechanically released at NHV and will be placed onto No. 136.136=53	
178	BOS	30	DSR	23	CTI	9	NRO-STM	MN	Follow metro north, Milepost, 23, 34	
179	PHL	105	ENG	72	ENG	54	PVD-KIN	AM	Other electrical failure, 613 EX ES, AM179 rpts fault on rear e/613 stopped on trk 1 at MP 182.0 , e/613 is now dead in tow and fault still not clear	
185	WAS	34	ENG	31	ENG	31	NYP-NWK	AM	Traction motor, 637, DISABLED IN NORTH TUBE	
471	NHV	22	ITI	21	ITI	21	HFD-HFD	AM	Service, turn, or wye train, 426, Late turn	
494	GFD	30	CON	49	CON	49	NHV-NHV	AM	Hold for connecting train, late connection of AM94	
52	LOR	43	TRS	61	TRS	61	XFL-XSE	CS	Vehicle strike 97 hit a vehicle all traffic stopped, Milepost, 228.2, 228.2	
79	CLT	60	TRS	46	TRS	46	WLN-SSM	CS	Unticketed or fare evading passenger 2 pax got on @ RMT w/o tickets asked to detrain @ WLN re-boarded train at another door and got hostile and disrespectful towards conductor which resulted in immediate removal @ MP 148.87, Milepost, 148.8, 148.8	
605	HAR	13	ENG	17	ENG	17	PAO-PAO	AM	Undesired emergency application, 640 EX ES, ISSUES WITH SPEEDOMETER	
643	HAR	21	MTI	23	MTI	23	NYP-NWK	AM	Disabled train ahead, Other, NYP-XBH, NECESSARY TO MAKE REVERSE MOVE A/C AM185 DISABLED IN NORTH TUBE	
645	HAR	26	DMW	15	DMW	15	NYP-NYP	AM	Waiting for MW clearance, Other, NYP, HELD TO OPERATE SOUTH TUBE A/C BROKEN I-JOINT ON `10 TRK "A" INT	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/21/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
646	NYP	22	DMW	24	DMW	24	NWK-NYP	AM	Waiting for MW clearance, Other, XBH, HELD TO OPERATE SOUTH TUBE A/C BROKEN I-JOINT ON 10 TRK "A" INT	
647	HAR	20	DCS	11	DCS	11	PHL-PAO	AM	T.O.L, Control Point, BRYN MAWR, T.O.L. WEST OF BRYN MAWR; STOP AND PROCEED ON THE AUTOMATIC SIGNAL	
652	NYP	27	ENG	31	ENG	31	PHL-PHL	AM	Other electrical failure, 645 EX ES, ENGINE CHANGE A/C BAD ENGINE; UNSPECIFIED ISSUE	
653	HAR	23	SVS	27	SVS	27	PHL-ARD	AM	Unplanned Wye, WYE ON THE OUTBOUND	
19	NOL	238	MBO	270	MBO	270	SDL-XEJ	NS	Power Outage at Seabrook, bridge stuck in the upward position.. waiting for permission to cross Power Outage at Seabrook, bridge stuck in the upward position.. waiting for permission to cross, Bridge, Seabrook Draw	
20	NYP	No OS Rpt	PTI	45	INJ	27	CVS-CVS	NS	Injured or sick passenger Report in Enablon. Passenger struck in head with ladder in room.	
681	BRK	17	PTI	17	PTI	13	POR-FRE	CS	Meet 684, Control Point, Congress	
683	BRK	16	PTI	9	PTI	5	SAO-ORB	CS	Meet 686, Control Point, Ocean Park	
63	TWO	36	FTI	21	FTI	20	SDY-XHF	CS	Meet Sit at stop signal at CP 169 for 20 minutes for a mixed freight train., Control Point, 169, CSXT 773, Manifest	
64	NYP	25	CUI	27	CUI	27	NFL-NFL	CS	United States	
243	ALB	23	ENG	18	ENG	15	NYP-XSD	AM	Cab signal failure, 9701 CB DC, ENGR REPORTED CABS DROPPED AT MP5,PICKED BACK UP AND MP6.2, DROPPED AGAIN AT MP6.6	
290	NYP	27	CTI	27	CTI	20	POU-CRT	MN	Follow metro, 870, Milepost, 68, 39	
291	BTN	25	CTI	19	CTI	17	CRT-POU	MN	Follow mn, 4835, Control Point, 39 72	
1233	PIT	38	DCS	32	DCS	32	RHI-HUD	AM	Power switch failure Control Point, 103	
1246	NYP	30	ITI	23	ITI	23	PIT-PIT	CS	Late train 1233	
78	RGH	13	WTR	13	WTR	13	BNC-DNC	NS	Flash flood warning Milepost w/Letters, 33.5 NC, 54.3 NC	
97	MIA	150	TRS	106	TRS	106	FAY-XDI	CS	Vehicle strike Milepost w/Letters, A228.3, A228.3	
98	NYP	335	DCS	232	DCS	152	KIS-ORL	FR	CTC system failure Permission by N KIS, Tupperware, S Stanton, N Stanton, N Taft, TOFC, Sandlake, S ORL, and Stop Signal Mid KIS., Other, Kis Amtrak-Mid Orl	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/21/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
55	WAS	140	TRS	95	TRS	95	SAB-ESX	NE	Trespasser strike Confirmed Fatality, Milepost, 132, 132	
40	CHI	75	WTR	61	DMW	34	XDJ-ALX	CS	Unable to contact dispatcher / MW foreman Locomotive 330's radio wasn't able to contact none of the EIC's which BD dispatch had to relay info, Milepost, 95.3, 95.3	
41	MIA	160	FTI	87	FTI	22	DNK-SAV	CS	Follow MIXTURE OF APPR, STOP AND CLEAR SIGNALS, M 585/19, Milepost, 436.0, 458.3	
23	NOL	46	FTI	88	FTI	32	BAS-XNO	CS	Follow m521, Milepost w/Letters, bas, claborn	
25	NOL	74	WTR	81	WTR	74	BAS-XNO	CS	High winds CSX Foreign Line Employee Operating Manual Rule Number 301.10 High Winds greater than 60 MPH Passengers Trains operate at 20MPH., Milepost, 789.0, 803.2	
5	EMY	38	FTI	147	FTI	46	XW6-WNN	UP	Follow UPRR 2768, Milepost, 502, 422	
6	CHI	109	FTI	135	FTI	66	COX-XSO	UP	Follow UP 5917 East, Milepost, 148, 178.3	
522	SAC	15	TEN	21	TEN	21	BKY-BKY	UP	Failure of diesel engine CDTX 2103 completely and spontaneously shut down when attempting to depart BKY Depot. Engineer dropped back to locomotive to do entire start-up sequence., C2103	
538	ARN	17	INJ	8	INJ	8	DAV-DAV	UP	Injured or sick passenger	
543	SJC	26	CTI	22	CTI	15	GAC-SCC	UP	Meet ACE, ACE8, Control Point, CO044	
50	NYP	203	ITI	103	ITI	103	CHI-CHI	AM	Service, turn, or wye train 51	
503	EUG	16	DSR	18	PTI	14	ALY-EUG	UP	Meet 14, Siding, Shedd	
507	EUG	139	CCR	118	CCR	50	TAC-XNI	ST	BOTH speedometers failed enroute to Nisqually. PTC dropped to zero as did analog. Stopped and trouble shot with CNOC and PTC desk. 90340	
516	VAC	90	POL	53	POL	53	X8B-XF2	BN	Right of Way police hold	
518	VAC	40	DSR	21	MBO	15	X8B-XF2	BN	For maritime traffic Bridge, Fraser	
58	CHI	250	FTI	123	TRS	89	XSU-HMD	CC	Vehicle on track ahead 18 wheeler hung up on crossing north end of Manchac siding, Siding, manchac	
59	NOL	127	DSR	83	TRS	34	X9R-XCS	CT	Car accident. BNSF was not allowing traffic to go through until accident was clear Other, entrance into the wye	
8	CHI	145	FTI	187	FTI	66	MAL-GGW	BN	Meet BNSF 5188, BNSF 7904, Siding, Saco	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/21/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
27	PDX	78	CAR	86	CAR	66	WIH-BNG	BN	Legitimate wayside HBD or DED actuation 33011, Hot bearing desk called and said we had to set out 33011 due to the bearings being 50 degrees warmer then the rest. Set the car out at BNG
28	SPK	99	ITI	101	ITI	101	PDX-PDX	BN	Late arrival of 28 into PDX 27
821	FTW	158	FTI	147	FTI	96	NOR-PUR	BN	Blocked from station track bnsf5743, Control Point, north purcell
822	OKC	49	FTI	34	FTI	34	FTW-GLE	BN	Meet BN Freight, Siding, Valleyview
334	CHI	118	POL	101	POL	101	SVT-XRO	CP	RR blocked by trespasser or vehicle strike by another train Dispatcher held us at Rondout, CPKC 246 hit a car at Old Mill Road (MP 27.27)
335	MKE	Trn Cancelled							
336	CHI	30	TRS	15	TRS	15	XRO-GLN	ME	Vehicle strike Control Point, Lake Forrest
337	MKE	19	ITI	14	ITI	14	CHI-CHI	AM	Service, turn, or wye train 336
338	CHI	Trn Cancelled							
341	MKE	27	POL	11	POL	11	XWA-GLN	ME	Police activity at Oakton Ave
342	CHI	19	CTI	13	CTI	10	GLN-XWA	ME	Follow Metra, 2156, Milepost, 11, 3
350	PNT	23	PTI	34	PTI	22	XB0-XA5	MI	Meet 353, Siding, Albion
351	CHI	26	DCS	33	DCS	33	XH6-XTF	NS	Drawbridge stuck open Bridge, 509
354	PNT	30	SVS	24	SVS	24	CHI-XTF	AM	Fuel Control Point, Lumber
355	CHI	53	MBO	52	MBO	52	HMI-XTF	NS	Bridge strike at 515 Bridge, 515
365	CHI	42	FTI	36	FTI	20	XH6-XTF	NS	Follow Q369, Milepost, 507, 509
370	GRR	131	CAR	112	CAR	112	XPI-SJM	CS	Air / Brake / Wheel ID4128, Hole in brake pipe Needed two wrenches to break seal Replacement brake pipe glad hand broke Used brake pipe of locomotive
562	SAN	31	CTI	30	PTI	17	SNC-X98	SC	Meet Amtk 765, Control Point, Serra
572	SAN	37	CTI	20	CTI	14	SOL-OLT	SN	Meet nctd, Control Point, skripps
584	SAN	35	FTI	24	FTI	24	XRJ-FUL	BN	Follow 7511, Control Point, valley view, Control Point, Buena Park, Control Point, basta
587	LAX	27	CTI	31	CTI	13	OSD-X98	SC	Meet Metrolink, Control Point, Songs

Amtrak Endpoint OTP Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/21/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
588	SAN	41	SYS	27	RTE	10	OSD-SOL	SN	Dispatcher hold Control Point, Ponto
591	LAX	71	SYS	53	SYS	39	OLT-OLT	SN	PTC problem or failure (cause unknown) Stopped at OLT troubleshooting PTC problem., Milepost, 264, 264
593	LAX	19	PTI	25	PTI	11	OLT-SOL	SN	Follow Yellow signals, 591, Milepost, 257, 241.8
595	LAX	24	DCS	40	DCS	15	OSD-OSD	SN	PTC system failure Cycled PTC power breaker per NCTD dispatcher and PTC desk and were once again unable to initialize with NCTC. Proceeded disengaged after initializing without NCTC per dispatcher instructions., Other, Oceanside station
774	SAN	91	PTI	90	PTI	26	SBA-SBA	UP	Meet amtk, Other, sba station
790	SAN	44	PTI	48	PTI	25	SNC-SNP	SC	Meet 591, 593, Control Point, serra
702	BFD	40	FTI	46	FTI	35	XEC-LOD	UP	Meet Control Point, CP Polk, UP 7295 west
704	BFD	17	DBS	15	DBS	15	XEC-LOD	UP	Debris blocking track (no debris strike) Control Point, Polk
713	OKJ	Trn Cancelled							
714	BFD	21	FTI	19	FTI	15	ACA-SKN	BN	Meet bnsf 5941, Siding, Orwood, Z
715	OKJ	48	CON	18	CON	18	BFD-BFD	BN	Hold for thruway bus Per CNOC BUS Hold per Assistant Superintendent Tommy
716	BFD	Trn Cancelled							
717	OKJ	Trn Cancelled	TSV	55	TSV	55	BFD-BFD	BN	Water, commissary, toilet/trash dumping
718	BFD	138	TSV	108	TSV	108	OKJ-OKJ	UP	Water, commissary, toilet/trash dumping
3	LAX	100	FTI	88	SYS	60	WLO-FLG	BN	Re-crew / job briefing Stopped @ BNSF crew depot to wait for pilots., Control Point, W. Winslow
1	LAX	243	FTI	262	DMW	67	XZS-YUM	UP	Hold for defect repair Control Point, E. Kinter
2	NOL	167	FTI	117	PTI	63	X5S-ELP	UP	Meet CP Lizard, AMK 170, Milepost, 1285, 1285
21	SAS	No OS Rpt	FTI	383	FTI	169	LRK-LRK	UP	Hold at Little Rock station due to freight train break down UP southbound, Control Point, Little Rock
22	CHI	709	FTI	415	FTI	352	HOP-ARK	UP	Broken fright Milepost w/Letters, Curtis, ark, up. 8648

Amtrak Endpoint OTP Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/21/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
301	STL	17	ENG	13	ENG	9	JOL-BNL	UP	Xitcs not working. Held to 79 mph ID4620
302	CHI	17	FTI	21	DCS	14	DWT-JOL	UP	Issue with automatic road crossing protection XG second crossing north of station. Crept up to it after departing station., Milepost, 73.51, 73.51
383	QCY	24	WTR	25	WTR	25	PLO-MDT	BN	Tornado warnings Milepost, 74, 86
311	KCY	132	CAR	110	CAR	85	HEM-JEF	UP	HEP ID4020, Dead car/ no power
316	STL	57	ITI	47	ITI	47	KCY-KCY	KC	Service, turn, or wye train 311
319	KCY	81	DMW	38	DMW	38	XQT-STL	TR	Hold for defect repair Control Point, Gratiot
1333	MSP	113	FTI	89	FTI	58	GLN-XRO	ME	Follow Police activity ahead, CP149, Control Point, A20

Amtrak Initial Terminal Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/21/2026

Terminal	Train	Date	Late	Delay	Cause
HFD	471	08/21	21	21	Service, turn, or wye train, 426, Late turn
MIA	98	08/21	18	18	Crew rest
NPN	186	08/21	5	5	Hold for thruway bus
NYP	49	08/21	20	20	PTC - On Board Cab Signal or PTC Failure, 713 DX DM, LATE RELEASE F/SSYD A/C REPORTED ISSUES WITH ACSES ON ENGINE 713
NYP	69	08/21	3	3	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	89	08/21	3	3	Passenger and/or baggage, LOADING
NYP	97	08/21	30	30	Water, commissary, toilet/trash dumping, LATE RELEASE F/SSYD A/C LATE SERVICING OF EQUIPMENT
NYP	119	08/21	3	3	Passenger and/or baggage, LOADING
NYP	291	08/21	10	10	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	645	08/21	15	15	Waiting for MW clearance, Other, NYP, HELD TO OPERATE SOUTH TUBE A/C BROKEN I-JOINT ON `10 TRK "A" INT
NYP	647	08/21	3	3	Passenger and/or baggage, LOADING
NYP	2115	08/21	2	2	Passenger and/or baggage, LOADING
NYP	2119	08/21	3	3	Passenger and/or baggage, LOADING
PHL	110	08/21	19	19	Service, turn, or wye train, 179
PHL	601	08/21	3	3	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD
PIT	1246	08/21	23	23	Late train 1233
RNK	178	08/21	4	4	Traction motor Issue with traction. Had to resolve before leaving storage facility., 336
WAS	136	08/21	11	11	Power switch failure, Control Point, K INTERLOCKING, 134 SWITCH FAILURE
CHI	3	08/21	113	113	Failure of diesel engine Trail Unit would not start, 30
CHI	7	08/21	61	61	Late release from yard 377, 368, 126
CHI	41	08/21	139	60	Planned set out / pick out of locomotives, cars or section of train Per glasshouse CHI SVS ENG 342 was incorrectly added in lead at 345 pm. Error was noticed at 525pm and switched into trail at 607 pm, Other, CUS
CHI	41	08/21	139	79	Set out defective locomotive 330
CHI	335	08/21	(Trn Cxld)		Trespasser Strike
CHI	337	08/21	14	14	Service, turn, or wye train 336
CHI	1333	08/21	18	18	Air / Brake Brakes, 44
KCY	316	08/21	47	47	Service, turn, or wye train 311

Amtrak Initial Terminal Details

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/21/2026

Terminal	Train	Date	Late	Delay	Cause
MKE	338	08/21	(Trn Cxld)		Trespasser Strike
SAS	22	08/21	102	102	Hold for connecting train 2
STL	311	08/21	9	9	Crew rest 316, 316 yard work- switch cars upon arrival into STL. Set out 2 cars, pick up 2 cars.
BFD	703	08/21	3	3	Hold for thruway bus
BFD	711	08/21	12	12	Hold for thruway bus
BFD	713	08/21	(Trn Cxld)		Third Party Engine Failure
BFD	715	08/21	18	18	Hold for thruway bus Per CNOC BUS Hold per Assistant Superintendent Tommy
BFD	717	08/21	55	55	Water, commissary, toilet/trash dumping
BFD	719	08/21	35	35	Hold for thruway bus Held for late buses
LAX	4	08/21	1	1	PTC- IETMS incorrect consist PTC timed out. Contacted DS. Dispatcher had to wait to get correct train sheet for consist., Control Point, Terminal
LAX	14	08/21	15	15	Hold for connecting train Hold for connecting passengers. Train 1 arrival 9:38a, train 3 arrival 9:52a, 1, 3
LAX	588	08/21	5	5	PTC problem or failure (cause unknown) Failure to initialize on NCTD territory. Contacted CNOC PTC Desk and verified no known system issue. Will attempt initialization again en route., Other, LAX
LAX	757	08/21	2	2	Late from yard
OKJ	712	08/21	7	3	PTC - Initializing PTC (no failure) Other, jack london depot
OKJ	712	08/21	7	4	Air / Brake Had problem building up main res leaving the yard, C2002
OKJ	716	08/21	(Trn Cxld)		Third Party Engine Failure
OKJ	718	08/21	3	3	Service, turn, or wye train 716
SAC	704	08/21	7	7	Wait for scheduled departure time Had door issues at initial terminal
SJC	550	08/21	1		
SPK	27	08/19	2	2	Wait for station track Train 7 left 11 mins late, working conductor only had to do switching and the shove and hook and load all the passengers., AMTK7, Control Point, Spokane Station

Eastern Region

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	99.3	94.8	342	0
CDOT	95.0	100	89.7	92.4	20	0
MARC	95.0	91.4	83.6	90.2	58	5
SEPTA	95.0	93.2	95.0	91.5	219	15
NJT-NED	95.0	88.5	91.6	88.6	355	41
NJT-SED	95.0	100	99.2	97.2	11	0

Operating Highlights

Trenton, NJ - Police Related

22AUG26: At 12:06 a.m. in Trenton, NJ on the Amtrak NYP Line a suspicious package was reported by NJTPD to be on track 1 causing a hold to be placed. At 12:17 a.m. the hold was released on the high tracks allowing rail traffic to resume. Train 50(22) was routed from a low track to a high track due to the police hold. Train 624(21) and train 65(21) were delayed due to congestion in the station.

Train	Delay	Comment
624(21)	06"	
50(20)	36"	
65(21)	08"	

NHB Line - East of Providence, RI - Trespasser Incident

21AUG26: At 10:13 p.m. an individual reportedly fell from the Charles St Bridge into the overhead catenary system east of Providence, RI on the Amtrak NHB Line located at milepost 186.44. An emergency plate went into effect from Davisville to Mansfield and train 94(21) with 227 customers onboard was at the Providence Station with no head end power due to OCS being cut out. The temperature outside was 66 degrees and clear and the doors were kept open in the station. Amtrak ET and local authorities were on site. At 10:53 p.m. the individual was removed from the tracks and taken to the local hospital, OCS was restored, and train 94(21) regained head end power. MTBA 886 completed a visual inspection of the catenary first before 94(21) was released from Providence station at 10:55 p.m.

Train	Delay	Comment
2162(21)	03"	
176(21)	03"	
94(21)	44"	
MBTA 886	36"	

Train 69(21) North of Lacolle, QC - Weather

21AUG26: Train 69(21) operating with engine 112, 5 cars, and 86 customers onboard was delayed 23 miles north of Lacolle, QC on the CN Rouses Point subdivision operating through heat orders until milepost 42.3.

Train	Delay	Comment
-------	-------	---------

Train 79(21) South of Wilson, NC - Police Related

21AUG26: Train 79(21) 26-FOF00703 00000008737 engine UNCLASSIFIED cars 5 and 234 customers onboard was delayed 13 miles south of Wilson, NC on the CSX South End subdivision meeting police at NC Highway 581 N crossing ID 629929F to remove unruly customers onboard.

Train	Delay	Comment
79(21)	46"	

Train 48(20) West of Amsterdam, NY - Freight Train Interference

21AUG26: Train 48(20) was delayed 11 miles west of Amsterdam due to freight train interference meeting CSX freight at MP 188 on the CSX Mohawk subdivision.

Train	Delay	Comment
48(20)	31"	

Multiple Trains - CSX RF&P Subdivision Single Track - Freight Train Interference

21AUG26: Multiple trains were delayed by freight train interference resulting from blocking on the No.1 track on the CSX RF&P subdivision at CP38 Milford resulting in single track operations at that location.

Train 94(21) was delayed meeting CSX M145-21 at CP 38.

Train 80(21) was delayed meeting CSX I031-21 at CP 38.

Train 40(20) was delayed meeting CSX I031-21 at CP38.

Train	Delay	Comment
94(21)	42"	
80(21)	45"	
40(20)	38"	
41(20)	38"	
125(21)	33"	
90(21)	23"	
186(21)	12"	

Train 1233(21) South of Hudson, NY - Power Switch Failure

21AUG26: Train 1233(21) operating with locomotive 714, 5 cars, NPCU 9701, and 239 customers was delayed 11 miles south of Hudson Station on the Amtrak Hudson Line due to power switch failure at CP103. Amtrak signal maintainers responded to the location and were able to restore the switch function allowing train 1233(21) to proceed.

The late operation of train 1233(21) caused a late turn of equipment and an initial terminal delay to train 1246(21).

Train	Delay	Comment
1233(21)	32"	
1246(21)	33"	initial terminal delay

Train 97(21) New York, NY - Initial Terminal Delay - Servicing

21AUG26: Train 97(21) was delayed at the initial terminal of New York due to a late release from the yard from servicing. A baggage car was needed from the shop to fulfill the consist and a motor was needed from the engine house. Once the trail was released it was positioned in the station, 195 customers were boarded and train 97(21) departed New York.

Multiple Trains - Northeast Corridor Motor Availability

21AUG26: Multiple trains delayed on the Northeast Corridor due to lack of motor availability resulting from a low percentage of completed CM tasks requiring service adjustments to be made to prevent motors from expiring at 11:59pm-et while in service.

Train 651(21) departed New York with a single motor and no cab car after E/640 was removed, requiring the need to wye the train at Philadelphia.

Train 624(21) departed Harrisburg with a single motor and no cab car requiring the need to wye the train at Philadelphia.

Train 653(21) departed New York with a single motor capping the cab car due to the inbound motor needing to be shopped for CM and the replacement motor capping the cab car.

Train 652(21) took a delay at Philadelphia due to motor E/645 needing to be removed to shop for CM and being replaced with E/613 off the yard.

Train	Delay	Comment
652 (21)	31"	
624 (21)	40"	

CSX Heat Orders - Weather

21AUG26: CSX has imposed heat orders in affect between 1pm - 7pm for the following subdivisions: Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, Tampa Terminal, and NO&M.

Train	Delay	Comment
40 (21)	35"	
41 (19)	38"	
52 (21)	04"	
97 (20)	33"	
89 (21)	02"	
98 (21)	38"	

Train 185(21) West of New York, NY - Engine Failure

21AUG26: Train 185(21) operating with locomotives 637-634, 8 cars and 302 customers was delayed 1 mile west of New York in the North Tube after becoming disabled due to a stuck parking brake on locomotive 637. The train did have functioning HEP while the crew worked to troubleshoot the motor with assistance from an Amtrak Road Foreman. The crew was able to isolate the locomotive and get the parking brake to release allowing the train to proceed.

Train	Delay	Comment
185 (21)	31"	

Train 55(20) St. Albans, VT - Trespasser Incident

21AUG26: Train 55(21) 26:FOI00703 00000008737 UNCLASSIFIED 05-95-952/2026 cars and 6 customers onboard was delayed south of Saint Albans, VT after striking a trespasser at MP 131.9 on the NECR Roxbury subdivision. Vermont State Police contacted NECR and reported train 55(21) struck a trespasser at Lake Street, DOTX id# 247411R and requested the train stop and hold for investigation. The train was stopped at MP 115 and were unaware of the trespasser strike. This incident occurred in the town of Saint Albans, VT in Franklin County. There were no reported injuries to crew or customers onboard and no damage to equipment or infrastructure was noted. Vermont State Police indicated the trespasser made contact with the middle of the train consist after the operating cab passed the trespasser. Saint Albans Police performed the investigation at the scene of the trespasser strike and Vermont State Police responded to the train to take statements from the crew. An Amtrak Road Foreman assisted APD with the investigation to support the expeditious release of the equipment. Once the statements were given the train was released and the crew was able to proceed.

National Response Center Number: 1471424

Train	Delay	Comment
55(20)	1'35"	

Train 98(20) South of Selma-Smithfield, NC - Trespasser Incident

21AUG26: Train 98(20) operating with locomotives 160-383, 10 cars, and 244 customers was delayed 4 miles south of Selma at MP 165 on the CSX South End subdivision after fatally striking a trespasser. This incident did occur at a grade crossing, Brogden Rd. DOTX id# 629965B in the town of Smithfield, Johnson County. There were no reported injuries to crew or customers onboard and no damage to equipment or infrastructure. An Amtrak Road Foreman, APD Detective and local authorities responded to the scene. The Engineer did not request relief at the scene, the Conductor did request relief, and the Assistant Conductor was moved up to operate once the train was released. Local authorities conducted their investigation and once the scene was released train 98(20) was able to proceed towards the next stop of Rocky Mount.

National Response Center Number: 1471408

Train	Delay	Comment
98(20)	1'59"	

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Train 3(20) East of Gallup, NM - Freight Train Interference

22AUG26: Train 3(20) was delayed East of Gallup, NM beginning at E. Baca/MP113.4 on the BNSF Gallup Subdivision following an unknown BNSF freight unit to E. Gallup/ MP156.5.

Train	Delay	Comment
3 (20)	32"	

Train 8/28(20) East of Wolf Point, MT - Freight Train Interference

22AUG26: Train 8/28(20) was delayed at Poplar(East)/MP205.3 on the BNSF Glasgow Subdivision, 22 miles east of Wolf Point, MT and again at Bainville/MP158.9 due to meeting multiple BNSF freights (BN7410 BN7336, BN4361).

Train	Delay	Comment
8/28(20)	37"	

Train 6(21) West of Winnemucca, NV - Freight Train Interference

22AUG26: Train 6(21) was delayed at Colado /MP351.4 on the UPRR Nevada Subdivision, 65.8 miles west of Winnemucca, NV station, due to pick-up/ drop-off of freight crew for UP5947.

Train	Delay	Comment
6 (21)	30"	

Train 591(21) San Diego (Old Town), CA - PTC Issues

22AUG26: Train 591(21) was delayed at San Diego (Old Town), CA/ MP 264.2 on the SCRRA - North County Transit District San Diego Subdivision, unable to initialize PTC due to an unknown cause. Crew worked with CNOC mechanical and the NCTD's PTC desk to troubleshoot the issue. Unable to resolve, they received permission from the NCTD to operate with PTC disengaged. Multiple Amtrak trains were also delayed on the NCTD San Diego Subdivision, unable to initialize PTC. Trains 595(21), 588(21), 790(21) were all delayed operating between San Diego and San Clemente Pier, operating with PTC disengaged.

Train	Delay	Comment
591 (21)	53"	
588 (21)	27"	
595 (21)	40"	
790 (21)	31"	

Train 14(21) North of Oakland Colliseum, CA - Trespasser Incident

22AUG26: At approximately 12:40 PM, train 14(21) operating with E/194, E/329, 9 cars struck an unoccupied vehicle on 66th AVE rail crossing (DOT 749720R) in Oakland, CA. Location is MP 11.62 on the UPRR Niles Subdivision, 0.4 miles north of the Oakland Coliseum station, in Alameda County. The crossing was protected with gates, flashers and bells. There were no reported injuries to the (227) passengers or crew and no reported damage to the train. The vehicle was initially stuck to the front of the lead engine, however the train was able to reverse and dislodge the vehicle in order for it to be removed from the tracks. The weather was reported as a clear 64° degrees. Locomotive E/329 provided head end power for the duration of the incident. The T&E crew requested and was granted relief, there was a deadhead crew already onboard the train that was utilized. Local authorities arrived on scene to investigate the incident. An Amtrak Road Foreman along with Amtrak Police Officers responded to the scene, Amtrak Police and EAP advised.

National Response Center Number: 1471535

Train	Delay	Comment
14(21)	2'40"	Wi-Tronix estimate

Train 6(20) West of McCook, NE - Weather

22AUG26: Train 6(20), operating with engines 206/81, 9 coaches, and 185 customers, was delayed on west of McCook, NE on BNSF Akron subdivision, due to operating through high wind speed restrictions from milepost 359 to milepost 305.

Train	Delay	Comment
6(20)	33"	

Train 355(21) East of Chicago, IL - Bridge Strike

22AUG26: Train 355(21), operating with engine 4607, 5 coaches and 231 customers, was delayed 8 miles east of Chicago, IL, on NS Chicago_76CD subdivision, due to a bridge strike. Train 355(21) held until the bridge could be inspected.

Train	Delay	Comment
355(21)	52"	

Train 370(21) West of St. Joseph-Benton Harbor, MI - Car Failure

21AUG26: Train 370(21), operating with engine 4631, 4 coaches, and 196 customers went into emergency east of New Buffalo at Milepost 108.8 on the CSX Grand Rapids Subdivision. After conducting a train inspection, the crew determined that the cause of the emergency application was a burst air hose. The crew initially attempted to replace the damaged hose; however, the replacement hose available at the location was found to be too short for the application, preventing the repair from being completed. Due to the difficulties encountered, a Road Foreman of Engines (RFE) was dispatched to assist, with an estimated arrival time of approximately 30 minutes.

Upon further troubleshooting, the crew obtained an alternate air hose from the lead locomotive and successfully completed the repair. After the damaged hose was replaced and the train's air system was tested and confirmed operational, Train 370(21) resumed movement and continued its trip without further reported issues.

Train	Delay	Comment
370(21)	1'52"	

Train 19(21) East of New Orleans, LA - Drawbridge Opening

21AUG26: Train 19(20) 26-FQ1-00706 00000008737 engine UNCLASSIFIED 323/77, 9/2/2026, 3 coaches and 155 customers, was stopped east of New Orleans on NS NO&NE due to a drawbridge power failure after the bridge was struck by lightning and lost commercial power causing the bridge to be stuck open. The local power company was dispatched to the scene with an initial estimated arrival time of 9:00 PM CT. The power company and Norfolk Southern (NS) Bridge & Building personnel arrived on site and began efforts to restore power; however, no estimated time of restoration was available at that point.

NS personnel reported that power had not yet been restored to the bridge and implemented contingency measures by utilizing an auxiliary motor and generator to lower the bridge. The process was expected to take approximately 30 minutes, with an estimated time of operation (ETO) of 12:15 AM CT. Following the successful completion of these efforts, the bridge was lowered and Train 19(20) resumed movement with an overall delay of approximately 3 hours and 10 minutes.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(21)	4'30"	

Train 719(21) Bakersfield, CA - Hold for Connection

21AUG26: Train 719(21) was delayed departing Bakersfield, CA, while awaiting the arrival of multiple late inbound bus connections. Once all connecting customers arrived and boarded, Train 719(21) departed with 121 customers onboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(21)	35"	

Train 25(21) West of Bay Saint Louis, MS - Weather

22AUG26: Train 25(21), operating with engines 365/14, 3 coaches, and 100 customers was delayed 44 miles west of Bay Saint Louis, MS, on CSX NO&M subdivision, due to operating through high wind speed restrictions from milepost 789-803 that required the train to operate at 20mph.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(21)	1'14"	

Train 822(21) South of Gainesville, TX - Freight Train Interference

22AUG26: Train 822(21), operating with engines 50/55, 3 coaches and 89 customers, was delayed 9.5 miles south of Gainesville, TX, on BNSF Ft. Worth Subdivision due to meeting an unknown BNSF freight train at Valleyview siding.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
822(21)	34"	

Train 507(21) Tacoma, WA - PTC Failure

21AUG26: Train 507(21) CC/90340, 3 cars, E/WS1401, was delayed south of Tacoma, WA at MP21.2 on the Sounder Lakewood Subdivision due to PTC issues and both speedometers failing. The crew worked with CNOC mechanical and PTC desk to troubleshoot the issue. Unable to resolve the issue, the train received permission to operate with PTC cut-out and Assistant Conductor riding on the rear in order to proceed at reduced speeds. At Centralia, WA the train was wye'd in order to operate with E/WS1401 in the lead, resolving the PTC and speedometer issue allowing the train to resume track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 41(21) Chicago, IL - Engine Failure

21AUG26: Train 41(21) delayed 2 hours and 19 minutes departing Chicago, Illinois due to a late release of road power, correcting a locomotive switching error, a door bypass issue, and restarting locomotive AMTK 330 after it shut down while shoving to the station. As background, engine AMTK 342 was released at 400pm and was incorrectly added in the lead position at 445pm. The Diesel Pit Power Sheet had a note stating "Add 342 Trail" due to the unit being an RCA-unit for previous air compressor issues. The error was noticed at 525pm. Blue flags were dropped at 541pm and made-up at 607pm with locomotive AMTK 342 in the correct trail position. Train 41(21) was released by mechanical at 646pm. At 701pm, the yard crew requested mechanical assistance due to the door bypass issue preventing the locomotive from loading even though all the doors were verified to be closed. The issue was with deadhead baggage car 61009 so the door bypass was cut-out locally on only the 61009. Train 41(21) shoved from yard at 741pm. While shoving to the station at 751pm, lead locomotive AMTK 330 shutdown in the interlocking at CP Harrison. The fuel foreman responded and was able to restart the locomotive. The diesel pit general foreman reported that trail locomotive AMTK 342 went into fuel conservation mode causing the lead unit to shut down as it sensed low fuel pressure on the trail unit. After restarting the locomotive and completing required air tests, Train 41(21) set in the station at 823pm with 240 passengers to board. Train 41(21) departed Chicago at 859pm; 2 hours and 19 minutes late.

After departing Chicago Union Station and advancing to main #5 at Lumber Street, milepost 1.4, in the Amtrak Chicago Terminal, lead locomotive AMTK 330 shutdown again for a second time at 905pm. A technician responded and initially reported a loose CPU circuit breaker on locomotive AMTK 330. It was also reported that the fuel pressure system faults had returned. Rather than risking any further issues en route, the diesel pit general foreman made the decision at 941pm to remove locomotive AMTK 330 and replace with

locomotive AMTK 171. Locomotive AMTK 330 was cut on the mainline and the diesel pit reported clear at 944pm. Note: There was approximately a 40-minute delay on the mainline prior to commencing the back up movement for PTC issues. After the train director applied blocks for the reverse movement, Train 41's engineer reported a red fence, and a countdown was set to begin which would place him into emergency in 300 feet. The backup movement finally began at 1031pm and Train 41(21) spotted back on Chicago Union Station track 28 at 1037pm. Bad order locomotive AMTK 330 was removed at 1054pm. Replacement locomotive AMTK 171 was released at 955pm, wyed, and tied onto the train at 1117pm. Train 41(21) was released by mechanical at 1144pm and was back on the move again from Chicago at 1149pm

As service recovery, snack packs and water were distributed to customers.

WBS#: B.TR.100150.7070

Train	Delay	Comment
41(21)	2'19"	ITI- flat switch engines
41(21)	2'50"	Engine Failure after departure

Train 7/27(21) Glenview, IL - Debris

21AUG26: Train 7/27(21) operating with locomotives 375/268, and 126, sixteen coaches, and approximately 255 customers, was stopped north of Glenview at Milepost 35.7 after experiencing a loss of Head End Power (HEP). Following an inspection, the crew determined that the outage was caused by a damaged 480-volt cable on baggage car 61028. The damage was likely caused by the cable being caught on something and because the damage suggested the cable was yanked out of the receptacle. The crew coordinated troubleshooting efforts with CNOC Mechanical, and Assistant Superintendent (ASO) was notified of the situation. After evaluating repair options, it was determined that the damaged cable could not be immediately repaired en route. As a result, the decision was made to operate the train without HEP, or "dark," from the location of the failure to Milwaukee.

While en route to Milwaukee, the train continued to operate without HEP, and plans were made to reposition baggage car 61028 to the rear of the consist upon arrival in order to isolate the affected car and restore power to the remainder of the train. The Assistant Superintendent was stationed in Milwaukee to meet the train, and Chicago Mechanical personnel were dispatched to assist with the required switching and recovery efforts. Train 7/27(21) arrived in Milwaukee at 6:25 PM CT, where the baggage car was moved to the rear of the consist. Following completion of the switching moves and mechanical work, HEP was successfully restored to all revenue cars. The train departed Milwaukee at 7:41 PM CT with Head End Power fully operational.

Train	Delay	Comment
7/27(21)	1'09"	shifting equipment
7/27(21)	25"	initial loss of HEP

Train 6(19) Naperville, IL - Commuter Train Interference

22AUG26: Train 6(19), operating with engines 46/193, 9 coaches and 130 customers, was delayed operating between Naperville, IL, and Chicago, IL on BNSF Chicago subdivision due to following metra train 1264.

Train	Delay	Comment
6(19)	31"	

Train 516(21) North of Bellingham, WA - Police Related

21AUG26: Train 516(21) operating with WDTX 1406, 3 cars, cab car 90252, and 159 customers onboard was stopped at milepost 119.9, 26 miles north of Bellingham, WA on the BNSF New Westminster subdivision due to a police hold on all tracks. Once the police hold was lifted, Train 516(21) advanced to the next station.

Train	Delay	Comment
516(21)	53"	

Train 319(21) North of St. Louis, MO - M of W Work

22AUG26: Train 319(21), operating with engine 4627, 7 coaches and 178 customers, was delayed 1 miles north of Saint Louis, MO, on TRRA Merchants subdivision due to MOW repairing a defect at control point Gratiot.

Train	Delay	Comment
319(21)	38"	

Train 311(21) Jefferson City, MO - Debris Strike

21AUG26: Train 311(21) F/ID46007 Car "UNCLASSIFIED" a 9/2/2026 at 10:54AM-CT on the UPRR Jefferson City Subdivision at MP121.8, approximately 3.7 miles east of Jefferson City, MO (MP125.5). As a result of the strike, the train experienced an undesired emergency, and the conductor worked to restore air before the train could proceed. Head End Power was also lost during the incident and was restored at 11:17AM-CT to all cars except coach ID4020. The crew worked with CNOC Mechanical to restore power to the coach; however, all troubleshooting efforts were unsuccessful. Train 311(21) resumed westward movement at 11:49AM-CT. Additional delay was incurred while holding at MP125.1 for Train 318(21) to clear the station track. The crew attempted further troubleshooting of coach ID4020 at the Jefferson City station, but power could not be restored.

Train 316(21) was delayed departing Kansas City, MO, on the KCT Kansas City Terminal Subdivision, due to a late turn of Train 311(21)'s equipment that arrived at 4:02PM - 2 hour and 12 minutes late.

Train	Delay	Comment
311(21)	1'25"	Debris Strike MP121.8
311(21)	25"	JEF
316(21)	47"	Turn of Late 311(21)

Train 7/27(21) Chicago, IL - Engine Failure

21AUG26: Train 7(21) was delayed 1 hour 1 minute departing Chicago, Illinois account flat-switching locomotives. Train 7(21) power was added to the train, made up at 1223pm. It was determined the engines needed to be flip flopped due to an air leak on the front of trail E/377. The flags were dropped at 151pm and the train was made up again at 227pm. The engines were laced up and the train was released at 250pm. With the additional Airo Train Equipment on the train, it was necessary to respot the train multiple times in CUS to get to the correct spot, set at 326pm. After loading 249 passengers, Train 7(21) departed CUS at 315pm, 1 hour 1 minute late.

Train	Delay	Comment
7/27(21)	1'01"	

Train 3(21) Chicago, IL - Engine Failure

21AUG26: Train 3(21), with 190 customers onboard, was delayed departing Chicago, IL due to locomotive failure. Lead engine 30 was late bad ordered after shutting down, and Chicago Mechanical was unable to restart the locomotive. As a result, engine 48 was worked up as the replacement power. At 3:23PM-CT, Train 3(21) departed Chicago operating 1 hours and 53 minutes late.

Train	Delay	Comment
3(21)	1'53"	

Gold Runner Service Adjustments - Third Party Contractor Engine Failure

21AUG26: Mechanical issues and equipment shortages affected multiple Gold Runner trains. The following adjustments were made:

Train 713(21) was cancelled in its entirety.

Train 717(21) was terminated in Emeryville.

Train 716(21) was cancelled in entirety.

Train 968(21) with E/C2108 was deadheaded from Oakland Maintenance Facility to Bakersfield in order to balance.

Train	Delay	Comment
-------	-------	---------

Train 516(21) Everett, WA - Freight Train Interference

21AUG26: Train 516(21) operating with engine 1406, 2 cars, cab car 90252, and 162 customers onboard was held at Everett, WA on the BNSF Scenic subdivision due to cross traffic with BNSF freight train 5045. Once the freight train cleared, Train 516(21) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
516(21)	48"	

Train 27(19) Bingen-White Salmon, WA - Car Failure

21AUG26: Train 27(19) operating with engine 139, 4 cars, and 86 customers onboard was delayed at Bingen, WA on the BNSF Fallbridge subdivision due to car failure on car 33011. It was reported that the car set off the hot box detector and was 50 degrees higher than the rest. The car was required to be set out. The crew set out the car in Bingen and advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
27(19)	1'26"	

Train 702(21) South of Sacramento, CA - Freight Train Interference

21AUG26: Train 702(21) operating with cab car 8309, 7 cars, CDTX 2108, and 61 customers onboard was stopped at milepost 43.0, 45 miles south of Sacramento, CA on the UPRR Fresno subdivision due to meeting UP freight train 7295. Once the freight train cleared, Train 702(21) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
702(21)	35"	

Train 20(21) North of Hattiesburg, MS - Signal

21AUG26: Train 20(21) was delayed on the NSRR NO&NE Subdivision due to signal issues beginning 13 miles north of Hattiesburg, MS (MP85.3). The train operated restricted speed through the affected territory from MP72.3 until reaching a clear signal at MP64.1.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(21)	30"	

Trains 1333(21) and 334(21) West of Glenview, IL - Commuter Vehicle Strike

21AUG26: CP 246 reported striking which "UNCLASSIFIED" 8/2/2028 at MP26.5, approximately 9.5 miles west of Glenview, IL (MP17.0), on the Metra C&M Subdivision. As a result, both main tracks were taken out of service, with Train 1333(21) holding at MP23.7 and Train 334(21) holding at Rondout (MP32.3). Main Track 1 was subsequently released, first for westbound traffic and then for eastbound traffic. Train 1333(21) was released first and followed CP 149 through the area until it was able to get around at Truesdale (MP53.8). After the westbound trains had cleared the affected area, Train 334(21) resumed movement toward Chicago.

Due to the extensive delays incurred, Train 335(21), affecting 191 customers, was cancelled in its entirety and four alternate buses were secured, with all buses departing Chicago Union Station by 3:10PM-CT. Train 338(21), affecting 155 customers, was also cancelled in its entirety and four alternate buses were secured, with all buses departing Milwaukee by 3:17PM-CT.

WBS#: B.TR.100150.7068

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(21)	1'12"	
335(21)	Cancelled	
334(21)	1'51"	
338(21)	Cancelled	

Train 5(20) East of Fraser-Winter Park, CO - Trespasser Incident

21AUG26: At 10:51AM-MT, Train 5(20), operating with E/13-E/198 and 9 cars, fatally struck a trespasser at MP58.9 on the UPRR Moffat Tunnel Subdivision. Located approximately 3.4 miles east of Winter Park, CO (MP62.3) on a single main track located in Grand County. There were no injuries to the crew or the 219 customers onboard. Police, EMS, and the coroner responded quickly to the scene. The incident did not occur at a crossing. HEP was taken down while officials removed the remains from under the train and was restored at 12:07PM-MT. The crew requested trauma relief but agreed to advance the train to the Winter Park Station once released, where it would hold for a recrew. At 1:45PM-MT, Train 5(20) was released to proceed to Winter Park. The recrew was transported by the Denver Trainmaster and arrived at the location at 2:00PM-MT. Following a crew briefing, Train 5(20) departed Winter Park at 3:08PM-MT, operating 4 hours and 15 minutes late.

National Response Center Number: 1471496

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(20)	2'50"	Strike
5(20)	1'08"	WIP - Hold For Recrew

Train 23(21) West of Gulfport, MS - Freight Train Interference

21AUG26: Train 23(21) was delayed on the CSX NO&M Subdivision due to freight interference while following CSX M521 from Gulfport, MS (MP739.4) to Claiborne (MP768.1). Additional delay was incurred at Industrial Canal (MP801.5) while meeting CSX 305 before continuing its movement to New Orleans.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
23(21)	51"	CSX M521
23(21)	28"	CSX 305

Train 351(21) West of Hammond-Whiting, IN - Bridge Malfunction

21AUG26: Train 351(21) was held 1.8 miles west of Hammond-Whiting, IN (MP506.9), on the NSRR Chicago Line due to a drawbridge failure at CP509. Buildings and Bridges personnel responded to the location and resolved the issue. Once the bridge was properly seated and locked, Train 351(21) resumed westward movement.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
351(21)	33"	

Train 5(19) East of Winnemucca, NV - Freight Train Interference

21AUG26: Train 5(19) operating with engines 148, 179, 9 cars, and 148 customers onboard were delayed beginning at milepost 520.0, 12 miles east of Winnemucca, NV due to following UP freight train 2768 from milepost 520.0 to milepost 422.0. Once the freight train cleared, Train 5(19) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(19)	46"	

Train 5(19) East of Elko, NV - Freight Train Interference

21AUG26: Train 5(19) operating with engines 148, 179, 9 cars, and 144 customers onboard was stopped at milepost 564.2, 8 miles east of Elko, NV on the UPRR Lakeside subdivision due to meeting UP freight train 2768. Once the freight train cleared, Train 5(19) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(19)	33"	

Train 821(21) Purcell, OK - Freight Train Interference

21AUG26: Train 821(21) was held 1.7 miles north of Purcell, OK (MP516.6) on the BNSF Red Rock Subdivision in the North Purcell Siding (MP416.6) due to BNSF 5743 being disabled on the single main track at Wayne (MP511.3). BNSF 5743 was required to add power before it could continue north and clear the route. Once the route was established, Train 821(21) followed BNSF 8199 until it could operate around the freight train at Wynnewood (MP486.2).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
821(21)	1'36"	Meet BN 5743
821(21)	39"	Follow BN 8199

Train 7/27(20) East of Minot, ND - Trespasser Incident

21AUG26: At 8:45AM-CT, E/26-FOI-00700 7/27(20), E/26-FOI-00700 7/27(20), struck the RV portion of a pickup truck carrying an RV at the 27th St SE crossing (MP200.976, DOT#093079G) in Minot, ND, Ward County. The crossing was located 2.32 miles east of Minot (MP203.3) on the BNSF KO Subdivision and was equipped with two crossbucks, two advance warning signs, stop lines, an ENS sign, two quad gate arms, two mast-mounted flashing lights, and two bells. No injuries were reported to the crew, 265 customers onboard, or the driver of the pickup truck. The RV became wrapped around the front end of engine 332; however, the train retained HEP. Emergency responders, two BNSF officers, and Maintenance of Way personnel responded to the scene. The RV was removed from the front of engine 332, and the crew confirmed they would continue west to Minot upon release by local authorities. Minor cosmetic damage was reported to engine 332, with a further inspection planned upon arrival in Minot. At 9:21AM-CT, Train 7/27(20) was released by officials and continued west to Minot.

National Response Center Number: 1471429

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(20)	36"	

Train 1(19)/421(18) East of Yuma, AZ - M of W Work

21AUG26: Train 1(19)/421(18) operating with engines 170, 192, 9 cars, and 189 customers onboard was stopped at milepost 751.2, 20 miles east of Yuma, AZ on the UPRR Gila subdivision due to waiting for a rail repair to be made. Once the repair was completed, Train 1(19)/421(18) advanced to the next station.

WBS#: B.TR.100150.7069

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(19)/421(18)	1'07"	

Train 4(20) East of Barstow, CA - Engine Failure

21AUG26: Train 4(20) operating with engines 23, 53, 142, 9 cars, and 172 customers onboard was stopped at milepost 744.1, 6 miles east of Barstow, CA on the BNSF Needles subdivision due to engine failure on engine 53. The engine experienced a loss of water pressure that result in overheating and a loss of head end power. The crew attempted to troubleshoot and was unsuccessful. The train advanced with only engine 23 working. A freight diesel was sourced to be added in Needles.

Train 4(20) arrived in Needles at 3:00 AM-PT. The train completed the station work and a crew change. Once that was completed, the train added BNSF 5510. While adding the freight engine, the crew and BNSF responder had issues with connecting the MU cables. The crew was able to connect the cables. Train 4(20) was able to advance at 4:50 AM-PT.

Due to the late operation of Train 4(20), the following service recovery efforts were implemented to support our customers:

Complimentary snack packs and bottled water were offered to all passengers.

Sleeping Car Passengers- Regular meal service is being provided for both lunch and dinner.

Coach Passengers -LUNCH: Complimentary beef stew, rice, and beverages are being provided to all coach passengers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(20)	1'30"	BAR-NDL
4(20)	12"	Recrew
4(20)	13"	Waiting freight engine to be dropped off
4(20)	2'10"	Freight engine addition

Train 2/422(19) East of Del Rio, TX - Ditch Light Failure

21AUG26: Train 2/422(19) was delayed departing San Antonio, TX (MP209.5), on the UPRR Del Rio Subdivision due to a ditch light failure on engine 19 at Spafford (MP341.8). As a result, the train proceeded east operating at 20 MPH over public crossings. The San Antonio Road Foreman and Mechanical personnel met the train at Macdona (MP223.6), where the ditch lights were temporarily repaired, allowing the train to resume track speed to San Antonio. Upon arrival, the engines were flat switched to place engine 310 in the lead and engine 19 in the trail prior to continuing east to New Orleans.

Train 22(21)/422(19) was delayed departing San Antonio, TX (MP209.5), on the UPRR Del Rio Subdivision while awaiting the late inbound Train 422(19). The equipment arrived at 7:45AM-CT, 2 hours and 45 minutes late, resulting in the delayed departure of Train 22(21)/422(19).

Train	Delay	Comment
2/422(19)	1'12"	Ditch Light Failure
22(21)/422(19)	1'42"	DP SAS
2(19)	21"	SAS

Trains 22(20) and 21(20) South of Arkadelphia, AR - Downed Trees / Disabled Freight

20AUG26: Train 22(20), with 82 customers onboard, stopped at 10:47PM-CT 12.1 miles south of Arkadelphia, AR (MP410.9), on the UPRR Little Rock Subdivision at MP423.0 due to reports of multiple downed trees ahead. Extensive delay was incurred waiting on a track inspector to get onsite due to multiple other trees down on roadways, making access to the location difficult. Once a route was established, Train 22(20) was on the move at 1:58AM-CT before stopping again at 2:05AM-CT at MP420.4 due to MHONL-20 being in emergency on the single main track with no route around.

Union Pacific field personnel and a carman were onsite to assist in recovery efforts of the disabled freight train. At 5:00AM-CT, MHONL-20 was believed to have recovered and started pulling north; however, it went into another undesired emergency. It was determined the train had an additional three separations in the consist that the freight crew was required to repair. The ongoing recovery was further impacted by debris and downed trees still lingering on the track, prompting a Maintenance of Way response at 7:15AM-CT to clear the remaining obstructions. The crew of Train 22(20) expired on their hours of service at 6:44AM-CT. MHONL-20 recovered and was back on the move north at 7:15AM-CT. The crew of Train 22(20) was authorized to exceed hours of service to move the train into the Arkadelphia station, arriving at 7:56AM-CT, where it awaited a recrew and pilots estimated to arrive between 8:15AM-CT and 8:30AM-CT. This also allowed the 82 customers onboard an opportunity to detrain, if necessary, and stretch their legs while awaiting relief personnel. Upon arrival of the recrew and pilots, Train 22(20) departed Arkadelphia operating 10 hours and 50 minutes late.

During the same period, Train 21(20) was held at the Little Rock Station (MP345.7) while a route was established through the affected territory. The train was released to continue south after MHONL-20 was confirmed on the move. Significant freight interference delays were incurred en route to Hope, AR due to the main line being shut down for an extended period. Train 21(20) first met UP 5853, UP 5442, and UP 5010 at Arkadelphia, followed by UP 5980 and UP 6745 at Boughton (MP438.2). Train 21(20) held again 21.2 miles south of Texarkana, AR (MP21.2) in order to meet UP 2588 which was delayed due to a police hold on all tracks. Once the hold was released and the meeting complete, Train 21(20) was able to proceed south.

WBS#: B.TR.100150.7067

Train	Delay	Comment
22(20)	3'00"	Downed Trees
22(20)	5'52"	Broken Down Freight
22(20)	55"	ARK - Hold Fore Recrew
21(20)	2'49"	LRL - Hold for Open Route
21(20)	1'04"	ARK

Train 1(19)/421(18) Tucson, AZ - HVAC Issue

21AUG26: Train 1(19)/421(18) 00000008737 "UNCLASSIFIED" 9/2/2026 originating in engine 170/192, 9 coaches and 155 customers, was delayed departing Tucson, AZ, on UP Gila subdivision, due to moving ADA customers out of a hot coach (C/34085). Train 1(19)/421(18) reported a hot coach before arriving and the decision was made to move the ADA customers on the platform at Tucson. As background information the conductor was working alone, which added to the delay.

Due to the now bad ordered coach and the moving around of customers, 2 ADA customers due to board in Palm Springs had to be rebooked due to lack of accommodations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(19)/421(18)	23"	

Coast Starlight UPRR Sacramento Sub Curfew- Detour TWA 26-090

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

B.TR.100151.0836

WBS#: B.TR.100151.0836

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

UPDATE 07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG.

UPDATE 18AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 28AUG.

UPDATE 21AUG26: SC-44 fleet reliability has improved and the number of available units to support full service has been maintained for several cycles; as a result, full restoration of Midwest Corridor state-supported frequencies will now occur on Monday August 24th;

Pere Marquette:

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(07) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13), with 143 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(14), with 162 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(16), with 151 impacted customers, is cancelled entirely with 3 alternate

- Train 370(20), with 90 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(21), with 155 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 370(22), with 104 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(23), with 97 impacted customers, is cancelled entirely with 2 alternate buses secured between Grand Rapids and Chicago.
- Train 370(24) has been restored and will now operate as scheduled.
- Train 371(25) has been restored and will now operate as scheduled.
- Train 370(26) has been restored and will now operate as scheduled.
- Train 371(27) has been restored and will now operate as scheduled.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.
- Train 305(25) has been restored and will now operate as scheduled.
- Train 300(26) has been restored and will now operate as scheduled.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(15), with 163 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(15), with 108 impacted customers, is cancelled entirely with 3 alternate buses secured between Pontiac, MI and Chicago, IL
- Train 350(18), with 31 impacted customers, is cancelled entirely with no alternate transportation provided.
- Train 355(18), with 11 impacted customers, is cancelled entirely with no alternate transportation provided.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL and Quincy, IL.
- Train 382(10) cancelled entirely, with 2 alternate buses secured between Quincy, IL and Chicago IL.
- Train 381(14), with 22 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL
- Train 382(14), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(17), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21), with 15 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 383(23), with 95 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Quincy, IL.
- Train 380(24), with 47 impacted customers, is cancelled entirely with customer

Saluki/Illini Service

- Train 391(12), with 54 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Carbondale, IL.
- Train 392(12), with 45 impacted customers, is cancelled entirely with 1 alternate buses secured between Carbondale, IL and Chicago, IL.
- Train 391(19), with 55 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Carbondale, IL.
- Train 392(19), with 18 impacted customers, is cancelled entirely with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task scheduled on C&M Subdivision at Western Avenue -
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In
order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be
adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		MU issues
22 (18)	XNT	315		I/O 47 faults
1340 (19)	XH8	150		Stuck Brake

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (20)	SEA	BNSF7550	E/164 B/O air compressor		
8 (19)	SEA	BNSF5205	E/96 No HEP/ HVAC	CHI	8/21/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00703

00000008737

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
137 (21)	BOS	TRAIN WILL OPERATE WITH ONE LESS COACH. PLEASE NOTIFY PAX TO REBOOK.	-23	-23	
50 (22)	CHI	VI in lieu of VII for 5000(*22*) car. schedule change performed. check war report.	see war rpt	0	62005
59 (21)	CHI	OPERATING W/O LOUNGE DUE TO 33004 SHOPPED IN NOL FOR BRAKE ACTUATORY AND NO REPLACEMENT AVAILABLE IN CHI.	na	0	NOCAR
7 (21)	CHI	Operating with sleeper 32072 inlieu of T-Dorm a/c 39019 shipped for bolster spring. Customer Svc will need to block out all DS and FS rooms. Schedule change has been performed.	N/A	0	39019
646 (21)	HAR	no cab car or cafe car to provide wifi.	N/A	0	82799
40 (21)	MIA	40(21) WILL BE OPERATING WITHOUT A LOUNGE CAR. PLEASE NOTIFY PASSENGERS.	n/a	0	
51 (21)	NYP	VI in lieu of VII for 5100 car. schedule change performed. check war report.	see war rpt	0	62005
49 (21)	NYP	49(21) WILL BE OPERATING WITH A BAGDORM IN LIEU OF A BAGGAGE CAR.	na	0	69004
651 (21)	NYP	No cab car or cafe car to provide wifi.	N/A	0	82799
27 (19)	PDX	Operating without Lounge a/c 33011 s/o BNG for hot bearing alarm.	N/A	0	33011
28 (21)	PDX	Operating w/o lounge a/c 33011 s/o BNG for hot bearing.	N/A	0	NOCAR
190 (21)	PHL	190(21) will go 1 car short. PHL unable to replace very late shipped coach without massive delay. NYP unable to produce on time section w/out additonal delay.	-61 pax	-61	NOCAR
190 (21)	PHL	TRAIN WILL OPERATE WITH ONE LESS COACH. PLEASE NOTIFY PAX TO REBOOK.	-61 pax	-61	
605 (21)	PHL	no cab car, loco added instead so no wifi and less seating capacity.	n/a	0	96XX
516 (21)	SEA	TRAIN WILL OPERATE WITH ONE LESS COACH CAR. INVENTORY	fare protect pax to alt	10	82507

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		HAS BEEN ADJUSTED. PLEASE NOTIFY AFFECTED PAX.	svc		
519 (21)	VAC	TRAIN WILL OPERATE WITH ONE LESS COACH CAR. INVENTORY HAS BEEN ADJUSTED. PLEASE NOTIFY AFFECTED PAX.	fare protected pax to alt svc	7	82507
172 (21)	WAS	EXTRA BUSINESS CLASS CAR IN LIEU OF A COACH. INVENTORY REDUCED.	n/a	0	81534

Reverse Consists

Train Number	Station	Reason
95 (21)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (21)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (21)	BOS	Consist reversed Business class seat orientation may have changed At Front
94 (21)	NFK	Consist reversed Business class seat orientation may have changed At Front
113 (21)	NYP	Consist reversed Business class seat orientation may have changed At Rear
143 (21)	SPG	Consist reversed Business class seat orientation may have changed At Front
84 (21)	WAS	Consist reversed Business class seat orientation may have changed At Front
193 (21)	NYP	Consist reversed Business class seat orientation may have changed At Rear
174 (21)	WAS	Consist reversed Business class seat orientation may have changed At Front
128 (22)	NFK	Consist reversed Business class seat orientation may have changed At Front
136 (21)	WAS	Consist reversed Business class seat orientation may have changed At Front
147 (22)	SPG	Consist reversed Business class seat orientation may have changed At Front
193 (21)	NYP	Consist reversed Business class seat orientation may have changed At Front