CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, November 09, 2026 Rules: 0-4



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00134 [illegible]

Initial Terminal Performance By Division

Scheduled Departure Date: **11/08/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/08/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	255	27	89.4%	2,336	306	86.9%	11,810	1,658	86.0%
Central Division	86.0%	56	2	96.4%	464	24	94.8%	2,234	149	93.3%
East Division	82.0%	141	17	87.9%	1,217	163	86.6%	6,216	901	85.5%
West Division	86.0%	58	8	86.2%	655	119	81.8%	3,360	608	81.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 11/8/26

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**76%**	**95,081**	**27,145**	**71%**	**768,896**	**252,155**	**67%**	**3,949,651**	**1,159,041**	**71%**
Northeast Corridor	***78%***	***42,004***	***12,578***	***70%***	***341,916***	***113,198***	***67%***	***1,715,015***	***438,965***	***74%***
Acela	80%	5,001	1,488	70%	48,242	13,584	72%	285,301	60,147	79%
Northeast Regional	78%	37,003	11,090	70%	293,674	99,614	66%	1,429,714	378,818	74%
Richmond / Newport News / Norfolk	75%	12,574	5,626	55%	75,916	30,374	60%	347,874	106,091	70%
Springfield Shuttles	89%	853	60	93%	6,106	897	85%	26,662	5,258	80%
Roanoke	75%	3,299	487	85%	24,346	7,127	71%	142,541	35,399	75%
On Spine Northeast Regional	80%	20,277	4,917	76%	187,306	61,216	67%	912,637	232,070	75%
State Supported	***80%***	***41,075***	***9,101***	***78%***	***334,244***	***92,732***	***72%***	***1,773,160***	***507,046***	***71%***
Borealis	80%	855	0	100%	5,457	1,365	75%	27,696	5,661	80%
Capitol Corridor	90%	4,022	1,114	72%	31,909	5,357	83%	157,647	29,587	81%
Carolinian	70%	1,357	766	44%	10,913	5,865	46%	50,120	19,467	61%
Cascades	75%	3,739	1,473	61%	23,162	7,391	68%	111,143	33,600	70%
Downeaster	82%	1,939	932	52%	11,983	3,452	71%	70,460	17,450	75%
Empire	78%	6,634	450	93%	45,963	11,362	75%	243,672	58,465	76%
Adirondack	72%	405	0	100%	2,560	179	93%	15,530	2,287	85%
Ethan Allen Express	70%	662	45	93%	4,262	1,470	66%	22,692	8,472	63%
Maple Leaf	70%	916	30	97%	6,335	2,565	60%	33,422	11,038	67%
New York - Albany	85%	3,235	0	100%	22,764	3,678	84%	118,206	21,328	82%
New York - Niagara Falls	75%	1,416	375	74%	10,042	3,470	65%	53,822	15,340	71%
Gold Runner	73%	2,767	258	91%	20,907	6,205	70%	101,060	36,767	64%
Heartland Flyer	70%	208	28	87%	1,439	888	38%	7,817	6,249	20%
Hiawatha	90%	1,840	0	100%	13,612	1,470	89%	71,790	7,213	90%
Illinois	78%	3,596	973	73%	21,859	3,846	82%	107,265	31,158	71%
Carl Sandburg / Illinois Zephyr	85%	539	174	68%	3,064	648	79%	16,548	4,162	75%
Illini / Saluki	85%	1,095	0	100%	7,827	769	90%	36,783	12,654	66%
Lincoln Service	70%	1,962	799	59%	10,968	2,429	78%	53,934	14,342	73%
Keystone	92%	4,995	240	95%	46,534	3,911	92%	257,681	25,591	90%
Lincoln / Missouri	70%	1,441	637	56%	6,977	3,346	52%	34,028	16,311	52%
Mardi Gras Service	80%	646	0	100%	3,107	205	93%	13,915	3,355	76%
Michigan	70%	2,296	371	84%	16,282	3,004	82%	83,934	19,930	76%
Blue Water	70%	262	0	100%	3,410	370	89%	22,084	5,234	76%
Pere Marquette	85%	427	79	81%	2,235	191	91%	11,546	814	93%
Wolverine	70%	1,607	292	82%	10,637	2,443	77%	50,304	13,882	72%
Missouri	80%	334	12	96%	2,100	493	77%	11,137	2,215	80%
Pacific Surfliner	85%	0	0	-	42,575	26,173	39%	275,883	150,245	46%
Pennsylvanian	80%	972	497	49%	7,689	1,314	83%	37,660	10,996	71%
Piedmont	80%	1,848	1,331	28%	9,732	5,588	43%	49,500	17,724	64%
Vermonter	75%	1,586	19	99%	12,044	1,497	88%	60,752	15,062	75%
Long Distance	***58%***	***12,002***	***5,466***	***54%***	***92,736***	***46,225***	***50%***	***461,476***	***213,030***	***54%***
Auto Train	70%	884	884	0%	5,991	5,439	9%	26,857	20,809	23%
California Zephyr	70%	911	207	77%	6,708	3,103	54%	36,305	11,649	68%
Cardinal	70%	242	117	52%	2,016	718	64%	8,968	3,945	56%
City Of New Orleans	75%	660	85	87%	5,493	1,278	77%	29,448	18,023	39%
Coast Starlight	70%	809	49	94%	7,737	4,310	44%	41,973	22,990	45%
Crescent	70%	1,120	357	68%	7,854	1,819	77%	38,358	6,864	82%
Empire Builder	70%	948	221	77%	7,108	2,224	69%	37,828	13,406	65%
Floridian	60%	1,803	1,418	21%	13,038	9,727	25%	56,004	33,948	39%
Lake Shore Ltd	73%	835	496	41%	7,522	2,261	70%	39,385	12,432	68%
Palmetto	70%	391	377	4%	6,841	3,149	54%	30,631	9,234	70%
Silver Meteor	70%	993	469	53%	8,062	5,008	38%	40,788	15,430	62%
Southwest Chief	60%	769	344	55%	5,183	3,981	23%	28,846	22,263	23%
Sunset Ltd	70%	335	15	96%	2,119	806	62%	10,954	5,034	54%
Texas Eagle	70%	1,302	427	67%	7,064	2,402	66%	35,131	17,003	52%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00187 00000000188 "UNCLASSIFIED" 11/18/2026~~

Train Index Dates Through November 08, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	47,939	801,597	598	235,849	3,891,179	606

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	1,482	211,826	70	11,032	1,083,543	102
INFRASTRUCTURE PLANNED	135	5,172	211,826	244	25,139	1,083,543	232
FLEET RELIABILITY	90	6,712	801,597	84	33,315	3,891,179	86
TRAIN OPERATIONS	424	34,573	801,597	431	166,363	3,891,179	428

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00134 [illegible]

Initial Terminal Performance By Division

Scheduled Departure Date: **11/08/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/08/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	255	27	89.4%	2,336	306	86.9%	11,810	1,658	86.0%
Central Division	86.0%	56	2	96.4%	464	24	94.8%	2,234	149	93.3%
East Division	82.0%	141	17	87.9%	1,217	163	86.6%	6,216	901	85.5%
West Division	86.0%	58	8	86.2%	655	119	81.8%	3,360	608	81.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

27-FOI-001[illegible]

Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/08/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/08/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	255	27	89.4%	2,336	306	86.9%	11,810	1,658	86.0%
Central Division	86.0%	56	2	96.4%	464	24	94.8%	2,234	149	93.3%
CDL	95.0%	2	0	100.0%	16	2	87.5%	57	5	91.2%
CHI	86.0%	26	2	92.3%	216	14	93.5%	1,046	82	92.2%
CHM	-	-	-	-	-	-	-	20	3	85.0%
DAL	-	-	-	-	-	-	-	2	0	100.0%
DET	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	8	0	100.0%	36	2	94.4%
GRR	95.5%	1	0	100.0%	8	0	100.0%	39	0	100.0%
IND	-	-	-	-	-	-	-	4	0	100.0%
KCY	92.0%	2	0	100.0%	16	0	100.0%	79	1	98.7%
MKE	92.0%	5	0	100.0%	46	3	93.5%	227	15	93.4%
MOE	97.5%	2	0	100.0%	16	0	100.0%	71	0	100.0%
MSP	96.5%	1	0	100.0%	8	0	100.0%	39	0	100.0%
NOL	94.5%	4	0	100.0%	35	1	97.1%	161	7	95.7%
OKC	97.0%	1	0	100.0%	8	0	100.0%	38	2	94.7%
PNT	88.0%	3	0	100.0%	24	1	95.8%	104	13	87.5%
PTH	93.0%	1	0	100.0%	8	1	87.5%	39	2	94.9%
QCY	91.0%	2	0	100.0%	15	0	100.0%	77	4	94.8%
SAS	90.5%	1	0	100.0%	8	2	75.0%	38	8	78.9%
STL	89.0%	4	0	100.0%	32	0	100.0%	155	3	98.1%
TAY	-	-	-	-	-	-	-	1	1	0.0%
East Division	82.0%	141	17	87.9%	1,217	163	86.6%	6,216	901	85.5%
ALB	88.5%	8	1	87.5%	62	6	90.3%	307	26	91.5%
ALX	-	-	-	-	-	-	-	27	14	48.1%
ATL	-	-	-	-	-	-	-	14	4	71.4%
BON	87.5%	5	0	100.0%	40	4	90.0%	195	16	91.8%
BOS	85.5%	11	3	72.7%	89	18	79.8%	482	40	91.7%
BRK	92.5%	5	0	100.0%	40	2	95.0%	195	15	92.3%
BTN	82.0%	1	0	100.0%	8	0	100.0%	39	5	87.2%
CLT	91.5%	5	1	80.0%	40	4	90.0%	189	24	87.3%
GFD	88.0%	2	0	100.0%	16	2	87.5%	78	8	89.7%
GRO	-	-	-	-	6	1	83.3%	17	1	94.1%
HAR	79.5%	8	0	100.0%	89	9	89.9%	444	48	89.2%
HFD	-	-	-	-	-	-	-	44	9	79.5%
JAX	-	-	-	-	-	-	-	18	2	88.9%
LOR	84.0%	1	0	100.0%	8	6	25.0%	37	18	51.4%
MET	-	-	-	-	-	-	-	1	1	0.0%
MIA	89.5%	2	0	100.0%	16	4	75.0%	77	12	84.4%
MTR	79.0%	1	0	100.0%	8	0	100.0%	39	9	76.9%
NFK	84.5%	2	0	100.0%	16	0	100.0%	67	10	85.1%
NFL	93.5%	1	0	100.0%	15	1	93.3%	77	6	92.2%
NFS	-	-	-	-	-	-	-	3	3	0.0%
NHV	78.0%	5	1	80.0%	45	5	88.9%	202	38	81.2%
NPN	93.0%	2	0	100.0%	16	2	87.5%	56	6	89.3%

Information Management

Initial Terminal Performance By Terminal

27-FOI-001

Scheduled Departure Date: **11/08/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/08/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	255	27	89.4%	2,336	306	86.9%	11,810	1,658	86.0%
East Division	82.0%	141	17	87.9%	1,217	163	86.6%	6,216	901	85.5%
NYP	75.5%	37	3	91.9%	311	35	88.7%	1,609	253	84.3%
PGH	93.0%	1	1	0.0%	8	1	87.5%	47	11	76.6%
PHL	48.0%	6	4	33.3%	73	37	49.3%	321	153	52.3%
RGH	95.0%	4	1	75.0%	26	3	88.5%	152	24	84.2%
RNK	83.5%	2	0	100.0%	16	2	87.5%	67	8	88.1%
SAB	98.0%	1	0	100.0%	8	0	100.0%	39	0	100.0%
SAV	96.0%	1	0	100.0%	8	1	87.5%	28	1	96.4%
SFA	88.0%	1	0	100.0%	8	6	25.0%	37	11	70.3%
SPG	92.5%	7	0	100.0%	55	1	98.2%	223	11	95.1%
TWO	73.0%	1	0	100.0%	8	2	75.0%	36	10	72.2%
WAS	84.0%	21	2	90.5%	182	11	94.0%	1,049	104	90.1%
West Division	86.0%	58	8	86.2%	655	119	81.8%	3,360	608	81.9%
ARN	92.0%	1	1	0.0%	8	1	87.5%	39	4	89.7%
BFD	79.0%	7	0	100.0%	56	11	80.4%	265	63	76.2%
EMY	72.0%	2	0	100.0%	10	2	80.0%	45	17	62.2%
EUG	86.5%	2	0	100.0%	16	1	93.8%	75	4	94.7%
FNO	-	-	-	-	-	-	-	5	4	20.0%
GAC	-	-	-	-	-	-	-	3	2	33.3%
GTA	90.0%	-	-	-	36	12	66.7%	167	67	59.9%
IRV	-	-	-	-	-	-	-	1	0	100.0%
LAX	89.5%	2	0	100.0%	65	14	78.5%	365	48	86.8%
OKJ	74.5%	9	5	44.4%	92	30	67.4%	455	145	68.1%
PDX	86.0%	5	0	100.0%	38	4	89.5%	193	17	91.2%
SAC	88.5%	12	0	100.0%	115	9	92.2%	571	53	90.7%
SAN	90.5%	-	-	-	75	21	72.0%	434	96	77.9%
SEA	85.0%	8	2	75.0%	64	8	87.5%	311	37	88.1%
SJC	89.0%	7	0	100.0%	56	6	89.3%	272	41	84.9%
SLO	90.0%	-	-	-	-	-	-	42	8	81.0%
SPK	90.0%	1	0	100.0%	8	0	100.0%	38	0	100.0%
VAC	97.0%	2	0	100.0%	16	0	100.0%	74	1	98.6%
VNC	-	-	-	-	-	-	-	5	1	80.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		4	1	75.0%	17	2	88.2%	4	1	75.0%	17	6	64.7%
3	53	7	1	85.7%	36	7	80.6%	7	7	0.0%	34	26	23.5%
4		7	2	71.4%	35	5	85.7%	7	6	14.3%	34	29	14.7%
5		8	0	100.0%	38	2	94.7%	8	3	62.5%	38	11	71.1%
6		8	2	75.0%	38	15	60.5%	8	5	37.5%	38	14	63.2%
7		8	1	87.5%	38	3	92.1%	8	1	87.5%	38	3	92.1%
8		8	2	75.0%	38	9	76.3%	8	3	62.5%	38	19	50.0%
11		8	1	87.5%	39	5	87.2%	7	5	28.6%	38	25	34.2%
14		8	2	75.0%	39	11	71.8%	8	5	37.5%	39	24	38.5%
19	43	8	3	62.5%	39	9	76.9%	8	3	62.5%	38	9	76.3%
20		8	0	100.0%	39	3	92.3%	8	1	87.5%	39	5	87.2%
21		8	0	100.0%	39	2	94.9%	9	1	88.9%	39	14	64.1%
21		8	0	100.0%	39	2	94.9%	9	1	88.9%	39	14	64.1%
22	63	8	3	62.5%	39	10	74.4%	8	4	50.0%	39	22	43.6%
23		8	0	100.0%	36	0	100.0%	8	0	100.0%	36	6	83.3%
24		8	0	100.0%	35	0	100.0%	8	1	87.5%	35	7	80.0%
25		8	0	100.0%	35	0	100.0%	8	0	100.0%	35	7	80.0%
26		8	0	100.0%	36	0	100.0%	8	1	87.5%	36	9	75.0%
27		8	3	62.5%	38	3	92.1%	7	2	71.4%	37	8	78.4%
28		7	0	100.0%	37	4	89.2%	7	0	100.0%	37	6	83.8%
40	40	8	2	75.0%	39	12	69.2%	8	8	0.0%	39	22	43.6%
41	25	8	3	62.5%	39	6	84.6%	8	8	0.0%	39	23	41.0%
42	27	8	1	87.5%	39	4	89.7%	8	2	75.0%	39	13	66.7%
43		8	1	87.5%	39	9	76.9%	8	1	87.5%	38	13	65.8%
48	182	8	1	87.5%	39	5	87.2%	8	3	62.5%	39	15	61.5%
49		8	0	100.0%	39	5	87.2%	8	2	75.0%	39	8	79.5%
50	43	3	0	100.0%	17	0	100.0%	4	2	50.0%	17	8	52.9%
52	47	8	6	25.0%	37	11	70.3%	8	6	25.0%	37	22	40.5%
53	60	8	6	25.0%	37	18	51.4%	8	8	0.0%	37	33	10.8%
54		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	0	100.0%
57		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	1	91.7%
58		8	0	100.0%	39	1	97.4%	8	2	75.0%	39	28	28.2%
59		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	23	41.0%
63	31	8	1	87.5%	39	13	66.7%	8	8	0.0%	39	36	7.7%
64		8	2	75.0%	39	13	66.7%	8	5	37.5%	39	21	46.2%
65		2	1	50.0%	12	2	83.3%	3	1	66.7%	12	2	83.3%
66		8	1	87.5%	38	5	86.8%	8	3	62.5%	38	8	78.9%
68		8	0	100.0%	39	9	76.9%	8	1	87.5%	39	8	79.5%
69		8	1	87.5%	39	11	71.8%	8	0	100.0%	39	2	94.9%
71	60	8	0	100.0%	39	2	94.9%	7	5	28.6%	38	11	71.1%
72	96	8	3	62.5%	39	8	79.5%	7	4	42.9%	38	7	81.6%
73		8	1	87.5%	34	5	85.3%	8	5	37.5%	34	18	47.1%

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74	20	8	1	87.5%	34	7	79.4%	8	5	37.5%	34	18	47.1%
75	31	8	1	87.5%	39	3	92.3%	8	4	50.0%	37	11	70.3%
76	35	8	0	100.0%	38	5	86.8%	8	6	25.0%	37	18	51.4%
77	28	8	2	75.0%	39	6	84.6%	8	5	37.5%	39	17	56.4%
78		8	0	100.0%	39	4	89.7%	8	2	75.0%	40	9	77.5%
79		8	0	100.0%	39	6	84.6%	8	6	25.0%	39	18	53.8%
80	131	8	0	100.0%	39	0	100.0%	8	5	37.5%	39	13	66.7%
82	39	3	0	100.0%	11	1	90.9%	3	2	33.3%	11	2	81.8%
87	52	3	0	100.0%	12	5	58.3%	3	1	66.7%	12	4	66.7%
88		3	0	100.0%	12	0	100.0%	3	1	66.7%	12	2	83.3%
89	62	8	0	100.0%	28	1	96.4%	8	7	12.5%	28	17	39.3%
90	120	8	1	87.5%	28	1	96.4%	8	5	37.5%	28	12	57.1%
94		8	0	100.0%	28	4	85.7%	8	2	75.0%	28	5	82.1%
97		8	3	62.5%	39	13	66.7%	8	6	25.0%	39	11	71.8%
98		8	2	75.0%	39	5	87.2%	8	3	62.5%	39	15	61.5%
99	41	3	1	66.7%	12	2	83.3%	3	2	33.3%	12	5	58.3%
101		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	1	90.9%
103	16	3	0	100.0%	12	1	91.7%	3	1	66.7%	12	2	83.3%
106		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
107		3	1	66.7%	11	1	90.9%	3	0	100.0%	11	0	100.0%
109		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
118		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	0	100.0%
124	31	3	0	100.0%	12	3	75.0%	3	2	33.3%	12	4	66.7%
126		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	3	72.7%
127		3	0	100.0%	11	2	81.8%	3	0	100.0%	11	1	90.9%
128		3	0	100.0%	12	4	66.7%	3	0	100.0%	11	2	81.8%
135	22	3	0	100.0%	12	1	91.7%	3	2	33.3%	12	3	75.0%
140		3	0	100.0%	12	2	83.3%	3	2	33.3%	12	6	50.0%
142		3	1	66.7%	11	3	72.7%	3	0	100.0%	11	1	90.9%
143		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	4	66.7%
144		3	1	66.7%	11	8	27.3%	3	0	100.0%	11	0	100.0%
146		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	3	75.0%
147		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	5	54.5%
150	54	3	2	33.3%	12	8	33.3%	3	2	33.3%	12	4	66.7%
151		3	2	33.3%	19	15	21.1%	3	0	100.0%	19	3	84.2%
152		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
153		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	1	91.7%
155	24	3	0	100.0%	13	1	92.3%	3	1	66.7%	13	2	84.6%
156		3	0	100.0%	13	0	100.0%	3	1	66.7%	13	6	53.8%
158		3	0	100.0%	12	3	75.0%	3	0	100.0%	12	2	83.3%
159		3	0	100.0%	11	5	54.5%	3	0	100.0%	11	2	81.8%
160	24	3	1	66.7%	12	5	58.3%	3	1	66.7%	12	4	66.7%

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
161	37	3	1	66.7%	12	3	75.0%	3	3	0.0%	12	6	50.0%
162	41	3	0	100.0%	12	1	91.7%	3	2	33.3%	12	5	58.3%
163	17	3	0	100.0%	11	1	90.9%	3	3	0.0%	11	6	45.5%
164	153	3	0	100.0%	12	1	91.7%	3	3	0.0%	12	6	50.0%
165		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	2	83.3%
167		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	3	72.7%
168		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	3	72.7%
169		3	0	100.0%	12	0	100.0%	3	0	100.0%	11	1	90.9%
194		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
195	151	3	2	33.3%	12	2	83.3%	3	3	0.0%	12	6	50.0%
230		8	0	100.0%	39	1	97.4%	8	0	100.0%	39	1	97.4%
232		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	3	92.3%
233		8	1	87.5%	39	13	66.7%	8	2	75.0%	39	14	64.1%
234		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	1	97.4%
235		8	3	62.5%	39	7	82.1%	8	2	75.0%	39	11	71.8%
236		8	0	100.0%	39	0	100.0%	8	1	87.5%	39	7	82.1%
237		8	2	75.0%	39	6	84.6%	8	1	87.5%	39	11	71.8%
238		8	4	50.0%	39	8	79.5%	8	2	75.0%	39	5	87.2%
239		8	1	87.5%	38	6	84.2%	8	2	75.0%	38	4	89.5%
240		8	0	100.0%	39	4	89.7%	7	0	100.0%	38	2	94.7%
241		8	1	87.5%	39	7	82.1%	8	3	62.5%	39	11	71.8%
243		8	0	100.0%	39	5	87.2%	8	0	100.0%	39	1	97.4%
244		8	0	100.0%	39	0	100.0%	8	2	75.0%	39	12	69.2%
245		8	0	100.0%	39	5	87.2%	8	0	100.0%	39	5	87.2%
280		8	1	87.5%	39	4	89.7%	8	3	62.5%	39	15	61.5%
281	18	8	0	100.0%	39	5	87.2%	7	4	42.9%	38	7	81.6%
283	30	8	1	87.5%	39	2	94.9%	8	5	37.5%	39	9	76.9%
284		8	1	87.5%	39	3	92.3%	8	3	62.5%	39	6	84.6%
290		8	0	100.0%	39	5	87.2%	8	5	37.5%	38	17	55.3%
291		8	0	100.0%	39	17	56.4%	8	1	87.5%	39	8	79.5%
300		8	0	100.0%	38	1	97.4%	8	0	100.0%	38	7	81.6%
301		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	4	89.7%
302	18	8	0	100.0%	39	1	97.4%	8	3	62.5%	39	11	71.8%
305		8	0	100.0%	39	1	97.4%	8	3	62.5%	39	15	61.5%
306		8	0	100.0%	39	0	100.0%	8	1	87.5%	39	11	71.8%
307	32	8	0	100.0%	39	1	97.4%	8	3	62.5%	39	13	66.7%
311		8	0	100.0%	39	1	97.4%	8	0	100.0%	39	4	89.7%
316		8	0	100.0%	39	0	100.0%	8	3	62.5%	39	12	69.2%
318		8	0	100.0%	39	1	97.4%	7	4	42.9%	38	16	57.9%
319		8	0	100.0%	39	0	100.0%	8	4	50.0%	38	27	28.9%
331		8	0	100.0%	39	2	94.9%	8	0	100.0%	37	1	97.3%
332		8	0	100.0%	39	3	92.3%	8	2	75.0%	39	3	92.3%

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		8	0	100.0%	39	1	97.4%	8	0	100.0%	39	1	97.4%
335		8	0	100.0%	39	6	84.6%	7	0	100.0%	38	3	92.1%
336		8	0	100.0%	38	0	100.0%	8	3	62.5%	38	4	89.5%
337		8	2	75.0%	38	3	92.1%	8	2	75.0%	38	3	92.1%
338		8	2	75.0%	39	6	84.6%	8	2	75.0%	39	11	71.8%
339		8	1	87.5%	39	9	76.9%	8	1	87.5%	38	7	81.6%
341		8	0	100.0%	38	5	86.8%	8	0	100.0%	38	2	94.7%
342		8	1	87.5%	39	5	87.2%	8	1	87.5%	38	4	89.5%
350		8	0	100.0%	36	2	94.4%	8	1	87.5%	34	13	61.8%
351		8	0	100.0%	34	4	88.2%	8	2	75.0%	32	7	78.1%
352	22	8	1	87.5%	35	5	85.7%	8	4	50.0%	34	14	58.8%
353		8	0	100.0%	36	4	88.9%	8	1	87.5%	35	5	85.7%
354		8	0	100.0%	36	6	83.3%	8	0	100.0%	35	11	68.6%
355		8	1	87.5%	35	6	82.9%	8	1	87.5%	34	9	73.5%
364	121	8	0	100.0%	39	1	97.4%	8	2	75.0%	39	10	74.4%
365		8	1	87.5%	39	2	94.9%	8	2	75.0%	39	13	66.7%
370		8	0	100.0%	39	0	100.0%	8	1	87.5%	39	5	87.2%
371		8	0	100.0%	39	0	100.0%	8	1	87.5%	39	1	97.4%
380		7	0	100.0%	38	2	94.7%	7	1	85.7%	38	11	71.1%
381		8	1	87.5%	39	1	97.4%	8	1	87.5%	39	8	79.5%
382		8	0	100.0%	39	2	94.9%	8	0	100.0%	39	7	82.1%
383	35	8	1	87.5%	39	1	97.4%	7	4	42.9%	38	16	57.9%
390		8	2	75.0%	38	7	81.6%	8	2	75.0%	38	11	71.1%
391		8	0	100.0%	39	2	94.9%	8	0	100.0%	39	6	84.6%
392		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	24	38.5%
393		8	0	100.0%	38	4	89.5%	8	0	100.0%	38	18	52.6%
400		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	1	91.7%
405		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	1	91.7%
409		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	1	83.3%
416	29	2	1	50.0%	6	2	66.7%	2	1	50.0%	6	1	83.3%
450		3	0	100.0%	12	3	75.0%	3	0	100.0%	12	2	83.3%
460		3	1	66.7%	12	5	58.3%	3	1	66.7%	12	2	83.3%
461		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	2	83.3%
464		3	0	100.0%	12	1	91.7%	3	1	66.7%	12	2	83.3%
465		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	1	83.3%
488		3	0	100.0%	12	4	66.7%	3	1	66.7%	12	3	75.0%
497		2	0	100.0%	6	1	83.3%	2	0	100.0%	6	2	66.7%
499		3	1	66.7%	12	3	75.0%	3	1	66.7%	12	3	75.0%
500		8	1	87.5%	39	3	92.3%	8	3	62.5%	39	8	79.5%
502	31	7	0	100.0%	38	1	97.4%	7	3	57.1%	38	9	76.3%
503	18	8	1	87.5%	39	8	79.5%	8	3	62.5%	39	17	56.4%
504		8	0	100.0%	37	1	97.3%	8	2	75.0%	37	15	59.5%

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		8	1	87.5%	39	2	94.9%	8	3	62.5%	39	9	76.9%
506		8	1	87.5%	39	3	92.3%	8	1	87.5%	38	7	81.6%
507	22	8	2	75.0%	39	5	87.2%	8	3	62.5%	37	14	62.2%
508		8	1	87.5%	39	4	89.7%	8	1	87.5%	39	13	66.7%
509	16	8	1	87.5%	39	2	94.9%	8	7	12.5%	39	21	46.2%
511	19	8	0	100.0%	39	1	97.4%	8	3	62.5%	39	7	82.1%
516	31	8	0	100.0%	37	4	89.2%	8	4	50.0%	36	20	44.4%
517	40	8	0	100.0%	39	2	94.9%	8	4	50.0%	39	17	56.4%
518		8	2	75.0%	39	5	87.2%	8	6	25.0%	38	20	47.4%
519		8	0	100.0%	37	0	100.0%	8	1	87.5%	37	6	83.8%
600		8	0	100.0%	37	1	97.3%	8	1	87.5%	37	5	86.5%
607		8	0	100.0%	37	2	94.6%	8	0	100.0%	37	1	97.3%
626		8	2	75.0%	37	7	81.1%	8	0	100.0%	37	5	86.5%
643		8	4	50.0%	37	12	67.6%	8	0	100.0%	37	3	91.9%
645		8	5	37.5%	37	14	62.2%	8	0	100.0%	36	4	88.9%
647		8	0	100.0%	36	4	88.9%	8	0	100.0%	35	1	97.1%
649		8	0	100.0%	37	2	94.6%	8	1	87.5%	37	5	86.5%
650		8	1	87.5%	37	5	86.5%	8	1	87.5%	37	3	91.9%
652		8	0	100.0%	37	3	91.9%	8	0	100.0%	37	2	94.6%
655		8	1	87.5%	37	4	89.2%	8	0	100.0%	37	2	94.6%
656		8	2	75.0%	37	7	81.1%	8	0	100.0%	37	5	86.5%
658		8	1	87.5%	36	2	94.4%	8	0	100.0%	36	1	97.2%
661	29	3	0	100.0%	12	1	91.7%	3	1	66.7%	12	3	75.0%
662		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
664		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	1	91.7%
667		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	0	100.0%
690	29	3	0	100.0%	12	0	100.0%	3	2	33.3%	12	2	83.3%
691	23	3	1	66.7%	12	1	91.7%	2	1	50.0%	11	2	81.8%
692	20	3	0	100.0%	12	1	91.7%	3	2	33.3%	12	4	66.7%
693		3	0	100.0%	12	2	83.3%	3	1	66.7%	12	4	66.7%
694	40	3	0	100.0%	12	0	100.0%	3	1	66.7%	12	3	75.0%
695	24	3	0	100.0%	12	0	100.0%	3	1	66.7%	12	2	83.3%
696		3	1	66.7%	12	1	91.7%	3	1	66.7%	12	2	83.3%
697		3	0	100.0%	12	2	83.3%	3	1	66.7%	12	2	83.3%
698		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	0	100.0%
701		8	2	75.0%	39	6	84.6%	8	3	62.5%	39	10	74.4%
702		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	15	61.5%
703		8	2	75.0%	39	12	69.2%	8	3	62.5%	39	9	76.9%
704		8	3	62.5%	39	9	76.9%	8	1	87.5%	39	5	87.2%
710		8	4	50.0%	39	10	74.4%	8	1	87.5%	39	8	79.5%
711		8	0	100.0%	39	6	84.6%	8	1	87.5%	34	5	85.3%
712		8	2	75.0%	39	12	69.2%	8	4	50.0%	39	17	56.4%

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
713		8	2	75.0%	36	12	66.7%	8	2	75.0%	31	8	74.2%
714	17	8	5	37.5%	39	22	43.6%	8	5	37.5%	38	21	44.7%
715		8	0	100.0%	39	6	84.6%	7	3	57.1%	37	18	51.4%
716		8	2	75.0%	38	17	55.3%	8	3	62.5%	37	10	73.0%
717		8	2	75.0%	39	16	59.0%	8	3	62.5%	36	15	58.3%
718		8	7	12.5%	39	27	30.8%	8	3	62.5%	39	15	61.5%
719		8	3	62.5%	39	9	76.9%	8	1	87.5%	39	8	79.5%
720	78	3	1	66.7%	12	2	83.3%	3	1	66.7%	11	1	90.9%
723		3	0	100.0%	12	0	100.0%	3	1	66.7%	12	2	83.3%
724		3	0	100.0%	12	2	83.3%	3	0	100.0%	12	3	75.0%
727		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	2	83.3%
728	18	3	0	100.0%	12	1	91.7%	3	1	66.7%	12	5	58.3%
729		3	1	66.7%	12	2	83.3%	3	1	66.7%	12	3	75.0%
732		3	1	66.7%	12	4	66.7%	3	1	66.7%	12	3	75.0%
733		3	0	100.0%	12	1	91.7%	3	1	66.7%	12	4	66.7%
734		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	3	75.0%
736		3	2	33.3%	12	4	66.7%	2	0	100.0%	10	1	90.0%
737		3	0	100.0%	11	1	90.9%	2	0	100.0%	9	0	100.0%
738		3	0	100.0%	12	1	91.7%	3	1	66.7%	12	4	66.7%
741		3	0	100.0%	12	0	100.0%	3	0	100.0%	11	2	81.8%
742		3	1	66.7%	10	2	80.0%	3	1	66.7%	10	2	80.0%
743		3	0	100.0%	12	1	91.7%	3	1	66.7%	11	1	90.9%
744	51	3	0	100.0%	12	3	75.0%	3	2	33.3%	12	6	50.0%
745		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	3	75.0%
746		3	1	66.7%	11	2	81.8%	3	0	100.0%	10	3	70.0%
747		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	4	66.7%
748		3	0	100.0%	12	2	83.3%	3	0	100.0%	12	2	83.3%
749		2	0	100.0%	10	2	80.0%	2	0	100.0%	10	1	90.0%
751		3	0	100.0%	12	0	100.0%	2	0	100.0%	11	0	100.0%
821		8	0	100.0%	38	2	94.7%	8	5	37.5%	38	29	23.7%
822		8	0	100.0%	38	2	94.7%	8	5	37.5%	38	30	21.1%
1022		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1333		8	2	75.0%	39	5	87.2%	8	4	50.0%	39	14	64.1%
1340		8	0	100.0%	39	0	100.0%	8	1	87.5%	39	5	87.2%
1689		3	0	100.0%	17	0	100.0%	3	0	100.0%	17	3	82.4%
2201		3	0	100.0%	10	0	100.0%	3	0	100.0%	10	0	100.0%
2203		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	0	100.0%
2205		3	0	100.0%	10	0	100.0%	3	0	100.0%	10	0	100.0%
2216		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
2218		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
2220		3	1	66.7%	10	1	90.0%	3	0	100.0%	10	2	80.0%
2248		3	0	100.0%	10	0	100.0%	3	0	100.0%	10	1	90.0%

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/8/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2249	151	3	1	66.7%	9	1	88.9%	3	1	66.7%	9	2	77.8%
2250		3	0	100.0%	11	0	100.0%	3	1	66.7%	11	2	81.8%
2251	94	3	1	66.7%	10	2	80.0%	3	2	33.3%	10	5	50.0%
2252	26	3	0	100.0%	12	1	91.7%	3	1	66.7%	12	1	91.7%
2255		3	0	100.0%	12	1	91.7%	3	1	66.7%	12	3	75.0%

Amtrak Endpoint OTP Details

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2249	WAS	151	WTR	124	WTR	117	BOS-BOS	AM	Flood / washout, Other, bby, Held at BOS a/c no OCS due to wire down at BBY. Heavy rains broke the fiber board that diverts the rain water from the OCS.
2251	WAS	94	WTR	55	WTR	55	BOS-BOS	AM	Flood / washout, Other, bby, Held at BOS a/c no OCS due to wire down at BBY. Heavy rains broke the fiber board that diverts the rain water from the OCS.
2252	NYP	26	CAR	21	CAR	21	BAL-BAL	AM	Door, 3651|NG|NB, Door malfunction, cut out door bypass
82	BOS	39	CTI	31	CTI	21	PVD-RTE	AM	Follow, MBTA, 6514, Milepost w/Letters, PVD, RTE, AM82 followed signal of CT6514
87	NFK	52	DMW	56	DMW	30	WAS-WAS	AM	Held for or routed around MW work or equipment, Control Point, A-INTERLOCKING, SINGLE TRACKING DUE TO TRACK WORK ON THE 19 SWITCH
99	NPN	41	DSR	37	SMW	17	KIN-WLY	AM	Diversions around M/W work, Control Point, High st, Held at high st.for 150 a/c run around
103	WAS	16	PTI	14	OTH	8	WIL-XPV	AM	Lost time - N.A.R., pure run time
124	PHL	31	PTI	26	PTI	26	ALX-XVG	CS	Follow P090, Milepost, 105.2, 112.2
135	WAS	22	DSR	14	POL	9	ABE-ABE	AM	Removal of passenger by police, PASSENGER PULLED EMERGENCY CORD.
150	BOS	54	WTR	24	WTR	22	RTE-BBY	AM	Flood / washout, Other, FOREST, HELD AT FOREST A/C WESTBOUND TRAFFIC ON TRACK 3. OCS OUTAGE AT BBY
155	NFK	24	PTI	24	PTI	8	BAL-BWI	AM	Follow, 103, Milepost, 95.7, 106.3
160	BOS	24	INJ	23	INJ	23	WLY-WLY	AM	Injured or sick passenger, AM160 request EMS at Westerly Station a/c a sick passenger
161	WAS	37	SMW	14	DMW	8	NCR-XNY	AM	Held for or routed around MW work or equipment, Control Point, ., HELD AT CP AVE A/C TRACK WORK AT "A" INTERLOCKING.
162	BOS	41	SMW	29	SMW	24	NLC-XGX	AM	Diversions around M/W work, Milepost, xgx, xgx, Stopped at Groton for 163 a/c run around
163	WAS	17	SMW	9	PBB	5	BWI-BWI	AM	Scheduled in track usage program, Control Point, ., DOUBLE SPOTS A/C STATION PLATFORM CONSTRUCTION

Amtrak Endpoint OTP Details

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
164	BOS	153	ENG	74	ENG	58	NHV-NHV	AM	Other electrical failure, 637|EX|ES, AM164 capped with E/631in NHV, due to E/637 experiencing multiple faults on MNRR
195	WAS	151	WTR	108	WTR	104	BOS-BOS	AM	Flood / washout, Other, bby, Held at BOS a/c no OCS due to wire down at BBY. Heavy rains broke the fiber board that diverts the rain water from the OCS.
416	SPG	29	TRS	16	TRS	16	NHV-NHV	AM	Vehicle on track ahead, Control Point, NHV, AM416 held in NHV a/c of report of car on trk at MP 72.93, confirmed vehicle on the Belldock trk not affecting Amtrak property
52	LOR	47	ITI	65	ITI	65	SFA-SFA	FR	Late departure at initial terminal due to late arrival of inbound equipment 53
53	SFA	60	ITI	62	ITI	62	LOR-LOR	CS	Late departure at initial terminal due to late arrival of inbound equipment 52
80	NYP	131	PTI	62	PTI	40	BNC-DNC	NS	Meet NC 73, Siding, Isom
661	HAR	29	SVS	26	SVS	26	PHL-ARD	AM	Unplanned Wye
19	NOL	43	FTI	92	FTI	57	GNS-ATL	NS	Blocked from station track 241, Control Point, Armour
690	BON	29	DCS	29	DCS	20	WEM-DOV	CS	PTC- I-ETMS Red Fence/Signal Status Unknown After stopping, instructed by PTC to place IETMS in restricted mode to pass red fence. Then place back in normal. Operate at restricted speed to automatic 45.9, Control Point, Willie
691	BRK	23	DCS	18	DCS	15	DOV-WEM	CS	PTC- I-ETMS Red Fence/Signal Status Unknown Control Point, Willie
692	BON	20	SYS	18	SYS	18	WEM-DOV	CS	PTC problem or failure (cause unknown) Cp willie showed a clear, IETMS displayed it as a stop, dspr gave instructions to put in restricted mode, clear the interlocking and stop, restore back to normal, and proceed stop in block, Control Point, willie
694	BON	40	SYS	33	SYS	33	WEM-DOV	CS	PTC problem or failure (cause unknown) Other, Willie to Bragdons
695	BRK	24	RTE	15	RTE	15	BON-WOB	MT	Routed to the Fitchburg Rt had to shove back to front ladder to be lined for the NH rt Control Point, front ladder
63	TWO	31	CTI	10	CTI	10	CRT-POU	MN	Follow mn, Control Point, 46
281	NFL	18	FTI	40	FTI	32	ROC-BUF	CS	Follow csxt, Control Point, 402
283	NFL	30	PTI	29	PTI	23	SDY-SDY	AM	Meet Hold at SDY for 48., 48, Other, SDY

Amtrak Endpoint OTP Details

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
48	NYP	182	ITI	179	ITI	179	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 8, Instructed by CD-7 Yardmaster to place delay under ITI due to engine failure of AMTK 375 and having to replace with AMTK 305 off of inbound Train 8.
42	NYP	27	CON	35	CON	35	PGH-PGH	NS	Hold for connecting train 41
71	CLT	60	RTE	25	RTE	23	DNC-GRO	NS	Dispatcher hold Stop and inspect train per dispatcher. Account two block lights., Other, Back Creek
72	RGH	96	ITI	39	ITI	39	CLT-CLT	NS	Late departure at initial terminal due to late arrival of inbound equipment 71
74	RGH	20	DSR	12	PTI	10	BNC-DNC	NS	Meet Stop signal at 34.1, 77, Milepost, 31.6, 34.1
75	CLT	31	DSR	18	DSR	10	DNC-BNC	NS	Per dispatcher (radio/phone) Broken Rail. Contacted RWIC Mawer before entering work area., Milepost, 38.4, 38.2, 10, Main
76	RGH	35	TEN	17	PTI	10	GRO-DNC	NS	Meet Amtk 79, Control Point, Funston
77	CLT	28	ITI	16	ITI	16	RGH-RGH	NS	Late departure at initial terminal due to late arrival of inbound equipment 72
89	SAV	62	FTI	108	FTI	47	DIL-FLO	CS	Meet CSX032, Control Point, Mars Bluff
90	NYP	120	PTI	96	PTI	87	ALX-XVG	CS	Wait for station track Amtk, Other, Cfp112.2
40	CHI	40	FTI	113	ENG	40	OKE-SBG	CS	Problems with the over speed talk to CNOC Mechanical they were trying to get it to cut out with no luck 341
41	MIA	25	FTI	67	FTI	16	SAV-XJG	CS	Follow #CSI03107, Milepost w/Letters, A512.7, A543.6
720	SAC	78	CCR	91	CCR	91	OKJ-OKJ	UP	Door C8306, No door light door 2. Wrong paperwork for loco in loco and cab car.
728	SAC	18	POL	14	POL	14	OKJ-EMY	UP	Individual who assaulted ticket agent in EMY, trespassed onto tracks
744	ARN	51	TRS	27	TRS	27	SAC-RSV	UP	Vehicle on track ahead Dispatch brought train to a stop at mp 91.2 due to a possible car on tracks at mp 99.3, Milepost, 91.2, 91.2
50	NYP	43	PTI	66	PTI	64	ALX-XVG	AM	Wait for station track 97, Control Point, Virginia
502	SEA	31	MBO	21	MBO	21	PDX-VAN	BN	For maritime traffic Bridge, columbia
503	EUG	18	PTI	17	PTI	17	ALY-EUG	UP	Meet amtrak 14, Milepost, 677.7, 677.7

Amtrak Endpoint OTP Details

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
507	EUG	22	PTI	30	PTI	30	PDX-ORC	UP	Meet Stop in the Clackamas siding met AMTK 508, AMTK 508, Siding, Clackamas
509	PDX	16	DBS	17	DBS	17	KEL-VAN	BN	Legitimate slide fence activation Slide fence activation, restricted speed through block, Control Point, woodland, Control Point, ridgefield south
511	PDX	19	DCS	13	DCS	13	KEL-VAN	BN	Slide fence restriction due to false actuation or out of service Restricted speed, Milepost, 118, 122
516	VAC	31	DSR	19	FTI	16	XF2-X1J	BN	Follow Control Point, Still Creek, Job 103
517	PDX	40	SVS	27	SVS	27	SEA-SEA	BN	Water, commissary, toilet/trash dumping
352	PNT	22	PTI	24	PTI	24	JXN-ARB	MI	Meet am355, Control Point, 53
364	PTH	121	FTI	130	FTI	111	LNS-LNS	CC	CN M302 had two ruptured hoses on the single main track Milepost, 232, 233, CN M302
714	BFD	17	PTI	44	PTI	17	OKJ-EMY	UP	Follow amtk 728, Control Point, n jack, Control Point, e emeryville
3	LAX	53	FTI	140	DMW	52	HUT-DDG	BN	Hold for defect repair Broken rail, Milepost, 283.1, 283.2
22	CHI	63	ENG	41	SYS	21	STL-STL	TR	Crew rest Other, StL station
302	CHI	18	FTI	25	INJ	16	CRV-CRV	UP	Injured or sick passenger Passenger fainted while trying to get up and walk . EMS was called at CRV. Medical passenger on board helped assist until EMS arrived
307	STL	32	FTI	53	FTI	28	PON-BNL	UP	Follow unk, Milepost, 121, 124
383	QCY	35	SVS	27	SVS	27	CHI-CHI	AM	Routine inspections Paperwork wasn't complete,mechanical had to do an inspection on consist and have proper paperwork., Control Point, CUS

Amtrak Initial Terminal Details

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/8/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	280	11/08	6		
BOS	195	11/08	104	104	Flood / washout, Other, bby, Held at BOS a/c no OCS due to wire down at BBY. Heavy rains broke the fiber board that diverts the rain water from the OCS.
BOS	2249	11/08	117	117	Flood / washout, Other, bby, Held at BOS a/c no OCS due to wire down at BBY. Heavy rains broke the fiber board that diverts the rain water from the OCS.
BOS	2251	11/08	55	55	Flood / washout, Other, bby, Held at BOS a/c no OCS due to wire down at BBY. Heavy rains broke the fiber board that diverts the rain water from the OCS.
CLT	72	11/08	39	39	Late departure at initial terminal due to late arrival of inbound equipment 71
NHV	416	11/08	16	16	Vehicle on track ahead, Control Point, NHV, AM416 held in NHV a/c of report of car on trk at MP 72.93, confirmed vehicle on the Belldock trk not affecting Amtrak property
NYP	19	11/08	3	3	Passenger and/or baggage, HELD FOR TRAVEL OFF AM99
NYP	97	11/08	11	11	Water, commissary, toilet/trash dumping, LATE RELEASE OUT OF SSYD
NYP	107	11/08	6	6	Door, 82791|AX|AS
PGH	42	11/08	35	35	Hold for connecting train 41
PHL	144	11/08	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	150	11/08	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	151	11/08	1	1	Passenger and/or baggage
PHL	645	11/08	1	1	Passenger and/or baggage
RGH	77	11/08	16	16	Late departure at initial terminal due to late arrival of inbound equipment 72
WAS	142	11/08	36	36	Flood / washout, Other, BOS-BOS, LATE INBOUND 195 DUE TO HEAVY RAINS BREAKING THE FIBER BOARD THAT DIVERTS THE RAINWATER FROM THE OCS.
WAS	2220	11/08	22	22	Flood / washout, Other, BOS-BOS, LATE INBOUND 2249 DUE TO HEAVY RAINS BREAKING THE FIBER BOARD THAT DIVERTS THE RAINWATER FROM THE OCS.
CHI	383	11/08	27	27	Routine inspections Paperwork wasn't complete,mechanical had to do an inspection on consist and have proper paperwork., Control Point, CUS
CHI	1333	11/08	3	3	Wheelchair
ARN	729	11/08	16	16	Meet 3082, Other, ARN STA
OKJ	710	11/08	2	2	Dispatcher hold No line up/no signal to depart, Control Point, N. Jack London
OKJ	714	11/08	3	3	Follow amtk 728, Control Point, n jack
OKJ	718	11/08	1	1	Mobility Impaired

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/8/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	720	11/08	91	91	Door C8306, No door light door 2. Wrong paperwork for loco in loco and cab car.
OKJ	736	11/08	1		
SEA	8	11/08	7	7	Fuel Late fueling of engine in yard left after 435 to station late boarding at Seattle
SEA	503	11/08	1	1	Undesired emergency application 7904, Reverser left in cab car train dumped, also train not set up correctly angle cock closed behind cab car

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	100.0	99.14	146	0
CDOT	95.0	75.0	75.0	92.4	16	4
MARC	95.0	100.0	89.6	90.2	12	0
SEPTA	95.0	85.8	90.3	93.7	106	15
NJT-NED	95.0	92.7	92.7	88.6	177	13
NJT-SED	95.0	100.0	98.2	97.2	22	0

Operating Highlights

Train 281(08) - East of Buffalo - Depew Station, NY - Freight Train Interference

09NOV26: Train 281(08) was delayed on the CSX Buffalo Terminal Subdivision at MP 402 due to meeting and following unidentified CSX Freight Train.

Train	Delay	Comment
281(08)	32"	

Train 49(08) - Albany-Rensselaer Station, NY - Equipment Manipulation/Servicing

09NOV26: train 49(08) was delayed departing Albany-Rensselaer Station, NY/MP 142.2 due to limited crews and yard congestion per the Yardmaster. Additional time was required to make the set up.

Train	Delay	Comment
49(08)	54"	

Train 90(08) - Philadelphia, PA - Engine Removed/Servicing

09NOV26: Train 90(08) was delayed at 30th Street Station in Philadelphia/MP 1.1 on the PW Line due to having E/116 removed and sent to Penn Coach Yard.

Train	Delay	Comment
90(08)	34"	

Train 97(08) - Washington, DC - Engine Failure

09NOV26: Train 97(08) experienced main reservoir issues during its first attempt to depart Washington Union Terminal. Mechanical personnel responded and rectified the issue. Train 97(08)'s delay cascaded into multiple delays for northbound and southbound trains at Washington Union Terminal. The delays were exacerbated by scheduled trackwork at A-Interlocking, which necessitated single track operations just south of the terminal.

Train	Delay	Comment
97(08)	15"	
90(08)	1'27"	Held south at L'Enfant/MP 111.5

27-FOI-00137 09000009130 "UNCLASSIFIED" 11/10/2026

Train 40(08) - North of Deland, FL - Freight Train Interference

08NOV26: Train 40(08) was delayed on the CSX Sanford Subdivision initially at MP 707.6 due to a report of a roll away railcar ahead near CP Bostwick/MP 690.8. After 40" Train 40(08) advanced to MP 695.6, where it held for an additional 1'06".
CSX confirmed there was a roll away railcar from an industry track near MP 690.8. CSX Management responded and conducted an investigation. The car was cleared and Train 40(08) was allowed to advance north.

Train	Delay	Comment
40(08)	40"	MP 707.6
40(08)	1'06"	MP 695.6

Train 48/448(07) South of Amsterdam, NY -Adding Engine/ Engine Failure

08NOV26: Train 48/448(07) with E/305, E/199 and 11 cars was delayed on the CSX Mohawk subdivision at MP 169.6 due to adding E/709, 9701 due to ACSES issues. This also caused train 283(08) to be delayed in Schenectady station.

Train	Delay	Comment
283(08)	24"	
48/448(07)	1'28"	

Train 164(08) New Haven, CT - Engine Failure

08NOV26: Train 164(08) with E/637 was delayed with multiple penalties, due to this upon arrival into New Haven E/631 was added ahead.

Train	Delay	Comment
164(08)	15"	
164(08)	58"	ADDING ENG NHV

Downeaster Service - Wells, ME - PTC/System

08NOV26: Several trains were delayed due to a PTC-I-ETMS outage on the CSX Portland PLD subdivision at MP 43.2 for an unknown reason. This resulted in trains being talked by MP 43.2/Willie then held at restricted speed to MP 45.9.

Train	Delay	Comment
694(08)	33"	
690(08)	29"	
692(08)	18"	
691(08)	18"	
694(08)	33"	

Train 113(08) South of Aberdeen, MD - Engine Failure

08NOV26: Train 113(08) with E/113 and 7 cars was delayed on the Philadelphia to Washington main line at MP 95.3 due to E/113 with double dashes and restricted to 79MPH.

Train	Delay	Comment
113(08)	48"	

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Train 164(08) North of Wilmington, DE -Debris/ Weather

08NOV26: Train 164(08) with E/6377 and 10 cars was delayed due to leaves under C/43369 which caused a leaf fire. Mechanical inspected at Philadelphia and okayed them for normal speed.

Train	Delay	Comment
164(08)	38"	

Train 80(08) South of Burlington, NC - Passenger Train Interference

08NOV26: Train 80(08) with E/88 and 7 cars was delayed on the NS Goldsboro-Greensboro subdivision at MP 33.8 due to meeting train 73(08).

Train	Delay	Comment
80(08)	40"	

Train 72(08) Charlotte, NC - Servicing

08NOV26: Train 72(08) with NC102, E/NC1810 and 5 cars was delayed departing Charlotte due to turning off the late 71(08). Train 77(08) was also delayed due to turning off the late 72(08).

Train	Delay	Comment
72(08)	39"	
77(08)	16"	

Train 19(07) South of Gainesville, GA - Freight Train Interference

08NOV26: Train 19(07) with E/359, E/369 and 8 cars was delayed on the NS Norcross subdivision at MP 632.5 due to being blocked from the station track by NS 241.

Train	Delay	Comment
19(07)	57"	

Train 42(08) Pittsburgh, PA - Hold for Connection

08NOV26: Train 42(08) with E/118 and 7 cars was delayed departing Pittsburgh due to holding for 26 connections off the late 41(07).

Train	Delay	Comment
42(08)	35"	

27-FOI-00137 000000091130 "UNCLASSIFIED" 1/10/2026

Boston South Station - Catenary or Wayside Failure

08NOV26: At 5:10 a.m. Boston 10 power dispatcher reported inability to hold overhead catenary power on any tracks between Mansfield and Boston South Station including South Bay and Tower 1. At 5:30 a.m. Keolis PX6891 stopped on 2 track at Back Bay Station reporting a catenary wire down and on top of the train. Amtrak police, Hi-Speed Rail, Trouble Desk, ET, Keolis, MBTA, and mechanical were all notified and dispatched to the scene. As of 553A-ET, ET arrived on scene at Back Bay station. At 735A-ET, Boston reported that the overhead catenary was back on track 1. Train 2249(08) was further delayed due to boarding the passengers and were also having gap filler issues. As of 1110A-ET, The Keolis equipment at Back Bay on track 2 was on the move and clear of the down wire. As of 1119A-ET, The Cat Car was clear of track 1 and going onto track 2 out of service. At 220P-ET, All repairs were made to the catenary at Back Bay and okayed for electric moves on track 2.

WBS#: B.TR.100151.0867

Train	Delay	Comment
2249(08)	1'57"	
2251(08)	55"	
195(08)	1'44"	
2220(08)	22"	late turn off 2249(08)
142(08)	36"	late turn off 195(08)

Train 281(07) South of Schenectady, NY - Engine Failure

07NOV26: Train 281(07) was delayed beginning at MP159.6, .3 miles south of Schenectady, NY station on the Amtrak Hudson line due to an unrecoverable penalty on cab car 9703. Cab Car 9703 was causing excessive wheel slip send the train into an air brake penalty. Crew attempted to troubleshoot with Albany mechanical but were able to resolve issues. Rescue engine 98 came out of Albany and coupled to train 281(07). At Albany train 281(07) transferred all passengers to 283(07) and terminated. Train 283(07) departed Albany NY station at 445PM ET operating 35 minutes late. As a result train 280(08) was cancelled between Niagara Falls and Albany. Customers were accommodated on the next available service.

Train	Delay	Comment
281(07)		TERM ALB
283(07)	20"	
280(08)	ORIG ALB	

Maintenance of Way Highlights

27-FOI-00137 0000009730 "UNCLASSIFIED" 1/19/2026

Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work

26OCT26: Due to the Veltri continuous outage on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None				RNK	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 118(08) Passenger Removal at Wilmington, Delaware – Medical

08NOV26, Passenger on PNR 5DA851, traveling from Washington D.C. to Metropark, NJ was reportedly removed due to flu like symptoms. Amtrak Police notified.

Delay: 118(08) 16"

Western Region
Operating Highlights

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Train 3(07) East of Flagstaff, AZ - Freight Train Interference

08NOV26: Train 3(07) with 121 customers was delayed on the BNSF Seligman subdivision starting 30 miles east of Flagstaff between MP 314.2 and MP 340.6 due to following unknown westbound freight. The delay was extended at East Flagstaff/MP 340.8 due to meeting an unknown eastbound freight.

Train	Delay	Comment
3(07)	29"	Follow
3(07)	20"	Meet

Train 4(07) East of Trinidad, CO - Signal

08NOV26: Train 4(07) with 93 customers was delayed on the BNSF Raton subdivision starting 32 miles east of Trinidad due to signal issues between MP 607.9 through MP 594.4.

Train	Delay	Comment
4(07)	52"	

Train 507(08) North of Oregon City, OR - Passenger Train Interference

08NOV26: Train 507(08) with 139 customers was delayed on the UPRR Brooklyn subdivision 5 miles north of Oregon City at Clackamas/MP 759.3 due to meeting train 508(08).

Train	Delay	Comment
507(08)	30"	

Train 364(08) East Lansing, MI - Freight Train Interference

08NOV26: Train 364(08), with 136 customers onboard, held at East Lansing, MI/MP223.8 on the CN Flint subdivision due to a disabled freight ahead at mile post 232.0. CN freight M302 was 9700 feet long and stopped on single main track with air issues. In anticipation of a lengthy delay, three buses were secured to take customers east from East Lansing, staging at 11:30PM ET. At 10:56PM ET, train 364(08) departed East Lansing after M302 starting to clear the route. The buses shadowed, train 364(08) until Flint, MI. and were released. Train 364(08) continued east.

WBS#: B.TR.100150.7337

Train	Delay	Comment
364(08)	1'51"	

Train 3(08) West of La Plata, MO - Freight Train Interference

08NOV26: Train 3(08), with 198 customers on board, was delayed at mile post 347.4 near Marceline siding/MP347.3, 34.60 miles west of La Plata, MO/MP312.7 on the BNSF Marceline subdivision meeting local police to assist with an disruptive customer, PNR# 64AB53. Once the police were clear of the equipment, train 3(08) continued west.

Train	Delay	Comment
3(08)	32"	

27-POI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Train 4(07) West of Raton, NM - Signal

08NOV26: Train 4(07) with 95 customers was delayed on the BNSF Raton subdivision starting 53 miles west of Raton between MP 712.6 and MP 701.8 due to signal issues.

Train	Delay	Comment
4(07)	30"	

Train 19(07) South of Meridian, MS - Animal Strike

08NOV26: Train 19(07), with engines 359 and 369, 8 cars, and 116 customers onboard, struck a deer at mile post 4.7, 4.7 miles south of Meridian, MS/MP295.0, on the NS N.O. & N.E. subdivision. The conductor walked the train and reconnected an air hose. Once air was recovered and a brake test was completed successfully, train 19(07) continued south.

Train	Delay	Comment
19(07)	15"	

Train 8/28(07) East of Malta, MT - Freight Train Interference

08NOV26: Train 8/28(07) with 86 customers was delayed on the BNSF Milk River subdivision starting one mile east of Malta at East Malta/MP 341.7 due to meeting BN 8086 and then eleven miles west of Glasgow at Tampico/MP 288.0, meeting BN 7742 and 7711.

Train	Delay	Comment
8/28(07)	09"	E/MAL
8/28(07)	27"	W/GGW

Train 8/28(07) West of Cut Bank, MT - Weather

08NOV26: Train 8/28(07), operating on the BNSF Hi Line Subdivision, was delayed west of Cut Bank, MT due to severe high wind conditions. The train initially encountered high winds between Piegan (MP 1106.5) and Cut Bank West (MP 1091.0), and subsequently between Shelby East (MP 1065.0) and Inverness (MP 1007.0). Wind gusts exceeding 60 mph were reported throughout the affected territory. As a safety precaution, train speed was reduced to 50 MPH through the impacted limits. Once the train cleared the high wind areas and conditions permitted, normal operations resumed. No injuries or equipment damage were reported.

Train	Delay	Comment
8/28(07)	31"	BRO-CUT
8/28(07)	41"	SBY-HAV

Train 21(07) South of Fort Worth, TX - Freight Train Interference

08NOV26: Train 21(07), with 163 customers, was delayed just south of Fort Worth, TX/MP346.2, on the BNSF Fort Worth Subdivision, waiting on freight traffic to clear route through Tower 55.

Train	Delay	Comment
21(07)	1'01"	

Train 24(08) North of Gulfport, MS - Freight Train Interference

08NOV26: Train 24(08) was delayed beginning 5 miles north of Gulfport, MS, on the CSX NO&M Subdivision, following CSX 602 between MP734 and Mobile, AL/MP666.7.

Train	Delay	Comment

27-FOI-00137 000000009130 UNCLASSIFIED 11/10/2026

Train 22(07) North of St. Louis, MO - Engine

08NOV26: Train 22(07) E/310 & 6 cars, was delayed north of St. Louis, MO, on the UPRR Springfield and Joliet Subdivisions and CN Joliet Subdivision, operating 79MPH MAX due to E/310 XITCS cut-out. Train 22(07) was delayed enroute due to operating the reduced speed.

Train	Delay	Comment
22(07)	37"	

Train 720(08) Oakland, CA - Servicing

08NOV26: Train 720(08), with 67 total downline customers, was delayed departing Oakland, Ca Jack London Square Station on the UPRR Niles Subdivision due to the commissary loading the wrong train and paperwork discrepancies. After resolving the commissary-related issues, Train 720(08) experienced additional delays due to door light malfunctions, requiring troubleshooting before continuing service. The delay impacted the train's departure from Oakland and subsequent operations.

Train	Delay	Comment
720(08)	1'31"	

Train 21(07) South of Texarkana, AR - Freight Train Interference

08NOV26: Train 21(07) was delayed at Bivins/MP30.4, 30 miles south of Texarkana, AR, on the UPRR Little Rock Subdivision, meeting UP 8779 and at Payne/MP42.7, meeting UP 6352. Train 21(07) was delayed at Keokuk/MP76, 10 miles south of Marshall, TX, on the UPRR Little Rock Subdivision, meeting UP 5617. Train 21(07) was further delayed at Greggton/MP93, 4 miles west of Longview, TX, on the UPRR Mineola Subdivision, meeting UP 7765.

Train	Delay	Comment
21(07)	30"	S/TXA
21(07)	30"	S/MHL
21(07)	31"	W//LVW

Train 4(07) Flagstaff, AZ - Engine Failure

08NOV26: Train 4(07), operating with Locomotives E/196 and E/142, was delayed at Flagstaff (FLG) on the BNSF Seligman Subdivision due to main reservoir issues on Locomotive E/142. The crew coordinated with CNOC Mechanical and successfully reset the locomotive. Following troubleshooting and recovery efforts, the locomotive returned to normal operation and Train 4(07) resumed its trip without further delay.

Train	Delay	Comment
4(07)	40"	

Train 14(07) Redding, CA - Police Search

08NOV26: Train 14(07), with 126 customers, was delayed departing Redding, CA, on the UPRR Valley Subdivision due to police activity. Local law enforcement responded after receiving reports that a missing teenager was possibly onboard the train. Following a search of the train, the reported missing teenager was not located. However, police identified and removed two runaway teenagers from the train. Once the investigation and removal process were completed, the train was released to continue service.

Train	Delay	Comment
14(07)	40"	

27-FOI-00137 0000000913O "UNCLASSIFIED" 1/10/2026

Train 7(06) Spokane, WA - Adding BNSF Locomotive

08NOV26: Train 7(06) departing Spokane with Locomotive 381 and 6 cars, experienced multiple master controller faults on Locomotive 381. This was not affecting the train currently, however the Siemens technician was concerned that when we split the train at Spokane, Engine E/381 may not be able to provide tractive effort. In order to protect the train into Seattle, WA King Street Station, BNSF 3873 was scheduled to be added at Spokane, WA station.

09NOV26: BNSF 3873 remained on the point of train 8(08) out of Seattle and continued to Chicago due to E/381 as a do not lead.

Train	Delay	Comment
7(06)	8"	WEN-EVR

UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority

16OCT26: The UPRR placed general orders in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected area due to signal issues where crews operated at restricted speed and stopped to flag crossings.

17OCT26: In order to minimize customer delays due to this, the following Service Adjustments were implemented:

Train 761(17) and 765(17) were originated at Los Angeles, CA, no alternate transportation provided.
Trains 757/ 765/ 777(17-01NOV) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-01NOV) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

23OCT26: The operating plan was extended through at least Sunday November 1.

30OCT26: The operating plan was extended to Friday November 6th.

04NOV26: The operating plan was extended to Friday November 15th.

WBS#: B.TR.100150.7278

Train	Delay	Comment

774(16)	1'39"	
757(16)	1'34"	
786(16)	1'35"	ITD SLO- Turn of 757(16)
786(16)	1'35"	ITD SLO- Equip off 757
765(16)	1'22"	
794(16)	38"	ITD SLO- Equip off 765
794(16)	2'08"	
14(16)	2'21"	
786(16)	2'57"	
11(15)	1'23"	
14(17)	1'13"	
11(16)	1'51"	
11(17)	1'15"	
14(18)	1'19"	
14(19)	1'01"	
11(18)	1'08"	
11(19)	1'10"	
14(20)	1'40"	
11(19)	51"	waiting for & meeting 14(20) at Tangair
14(21)	40"	
11(20)	1'05"	meet 14(21)
11(20)	1'14"	
11(21)	1'02"	
14(22)	59"	
11(22)	1'51"	
14(23)	1'03"	
782(23)	48"	
14(24)	1'03"	
11(25)	1'52"	
14(27)	1'31"	
11(26)	1'29"	
11(28)	1'11"	
14(28)	1'07"	
14(29)	45"	
11(29)	1'00"	
14(31)	1'02"	
11(30)	1'21"	
14(01)	1'24"	
11(31)	1'05"	
14(02)	1'00"	
11(01)	1'15"	
14(03)	51"	
14(04)	1'00"	
11(03)	1'00"	
14(05)	1'00"	
11(04)	1'20"	
14(06)	1'20"	

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

Train	Delay	Comment

822(29)	32"				
821(29)	27"				
821(30)	34"				
822(30)	30"				
822(01)	30"	27-FOI-00137	00000009130	"UNCLASSIFIED"	11/10/2026
821(02)	34"				
822(02)	29"				
822(03)	33"				
821(03)	25"				
821(04)	35"				
822(04)	32"				
821(05)	35"				
822(05)	26"				
821(06)	26"				
822(06)	37"				
821(07)	35"				
822(08)	32"				
821(09)	32"				
822(09)	36"				
822(10)	23"				
822(11)	41"				
822(12)	48"				
821(12)	21"				
821(13)	22"				
822(13)	36"				
821(14)	35"				
822(14)	17"				
821(15)	26"				
821(16)	41"				
822(15)	34"				
822(16)	19"				
821(17)	24"				
821(19)	39"				
822(19)	22"				
821(20)	29"				
822(20)	32"				
821(21)	46"				
821(22)	32"				
822(21)	19"				
822(22)	30"				
821(23)	42"				
822(23)	23"				
821(24)	21"				
822(24)	22"				
821(25)	34"				
822(25)	43"				
821(26)	52"				
822(27)	34"				
822(26)	21"				
821(28)	30"				
822(28)	31"				
821(29)	23"				
822(29)	33"				
821(30)	33"				
822(30)	22"				
821(31)	20"				
822(31)	25"				
822(01)	30"				
821(02)	35"				
822(03)	27"				
821(04)	37"				
822(04)	15"				
821(05)	16"				
822(05)	24"				
822(06)	10"				
821(06)	22"				
821(08)	17"				
822(08)	20"				

Maintenance of Way Highlights

27-FOI-00187 0000009130 "UNCLASSIFIED" 11/10/2026

Pacific Surfliner and Coast Starlight Service San Luis Obispo, CA to San Diego, CA - Scheduled M/W TW 27-021

07NOV26: A multi-agency track maintenance project involving North County Transit District (NCTD), Southern California Regional Rail Authority (SCRRA/Metrolink), and Union Pacific Railroad (UP) was conducted between San Luis Obispo, CA, and San Diego, CA. To accommodate the work, the following operating plan was implemented:

Coast Starlight
Train 11 (November 5-7): Terminated at Emeryville, CA with alternate transportation provided between Sacramento and Los Angeles via Gold Runner Services.
Train 14 (November 7-9): Originated at Emeryville, CA with alternate transportation provided between Los Angeles and Martinez via Gold Runner Services.

Pacific Surfliner
Friday, November 6
Train 794(06) Originated in Goleta, CA account of ongoing signal issues and Terminated at Los Angeles, CA account of the scheduled track work. Bus 3594 provided alternate transportation between Los Angeles and San Diego making all stops except San Juan Capistrano
Train 595(06) Canceled in its entirety. Customers were accommodated on Bus 5811.

Saturday, November 7, and Sunday, November 8
All Pacific Surfliner trains were canceled. No alternate transportation was provided.

09NOV26: Due to a delay in the track work and testing on the NCTD. As a result, trains 761(09) and 765(09) originated at Solana Beach with alternate bus transportation provided by the NCTD. Two buses were staged at San Diego and one bus was staged at Old Town for each train.

Train	Delay	Comment
761(09)	Orig SOL	
765(09)	Orig SOL	

UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Scheduled M/W Work TWA 27-020

26OCT26:To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 1(31Oct, 7Nov, 14Nov) and Train 42(30Oct, 6Nov, 13Nov) will detour over the BNSF San Bernardino Subdivision between West Colton(UPRR Alhambra subdivision) and Soto(BNSF San Bernardino subdivision), bypassing Ontario, CA (ONA) and Pomona, CA (POS). Train 801(2Nov, 9Nov, 16Nov) was created for the detour between Riverside, CA (RIV) and Los Angeles, CA (LAX).

Train 2/422(1Nov, 8Nov, 15Nov) will detour over the BNSF San Bernardino Subdivision between Soto(BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(1Nov, 8Nov, 15Nov) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV). An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision. No alternate transportation will be provided to POS and ONA.

WBS#: B.TR.100150.7307

Train	Delay	Comment
2/422(01)	39"	
1(31)/421(30)	44"	

UPRR Little Rock Subdivision Track Work - Texas Eagle Service TWA 27-019

27-FOI-00137 00000009130 UNCLASSIFIED 11/10/2026

08NOV26: Union Pacific has arranged a scheduled outage on the Little Rock Subdivision starting at 9:00PM on Sunday November 8th through 11:00AM on Monday, November 9th. Work gangs will be conducting a double diamond replacement project at Hope, AR/MP457.8 and bridge work at Saline Jct/MP370. To accommodate the above outlined infrastructure work, Amtrak's Texas Eagle Service will be adjusted as follows:

-Train 21(08Nov) will operate as Train 21 (08Nov) between Chicago and St. Louis and as Train 1021 (09Nov) between Fort Worth and San Antonio. Bus 3021(09Nov) will provide alternate transportation between Dallas and Fort Worth with no alternate transportation between St. Louis and Dallas.

-Train 421(08Nov) will operate between Chicago and St. Louis and between Fort Worth and Los Angeles. Bus 3021(09Nov) will provide alternate transportation between Dallas and Fort Worth with no alternate transportation between St. Louis and Dallas.

-Train 22(08Nov) will operate as Train 1022 (08Nov) between San Antonio and Fort Worth and as Train 22 (08Nov) between St. Louis and Chicago. Bus 3022(08Nov) will provide alternate transportation between Fort Worth and Dallas with no alternate transportation between Dallas and St. Louis.

-Train 422(06Nov) will operate between LAX and FTW and between STL and CHI. Bus 3022(08Nov) will provide alternate transportation between Fort Worth and Dallas with no alternate transportation between Dallas and St. Louis.

WBS#: B.TR.100150.7294

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
11(2)	GUA	E/164		Debris strike

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8(8)	SEA	BN3873	Speedo issues-E/301		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 511(08) Passenger Removal at Olympia, Washington – Improper Conduct

08NOV26, Passenger on PNR 41BD0F, traveling from Seattle, Washington to Portland, Oregon was reportedly intoxicated when he boarded. Then he became irate when he was denied more alcohol and began threatening the crew. The passenger was eventually removed by Olympia, Washington police for continued threats. Amtrak Police notified.

Delay: 511(08) 08"

Consist Deviations

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
67 (08)	BOS	Due to a shopped coach and no viable coach replacement, Boston is using a business class in lieu of a coach and is now oversold. Notify passengers.	over capacity email sent for paxs notification	9	81540
392 (08)	CDL	TRAIN WILL OPERATE WITHOUT BIKE SPACE ON THE LOWER LEVEL DUE TO HAVING CAR 34038 IN CONSIST. PLEAES NOTIFY ALL EFFECTED PAX.	No impact	0	34038
391 (08)	CHI	TRAIN WILL OPERATE WITHOUT BIKE SPACE ON THE LOWER LEVEL DUE TO HAVING CAR 34038 IN CONSIST. PLEAES NOTIFY ALL EFFECTED PAX.	No impact	0	34038
600 (08)	HAR	TRAIN WILL OPERATE WITH ONE LESS COACH CAR. INVENTORY HAS BEEN REDUCED. NO EFFECTED PAX.	No impact	0	
658 (08)	HAR	TRAIN WILL OPERATE WITH ONE LESS COACH CAR. INVENTORY HAS BEEN REDUCED. NO EFFECTED PAX.	No impact	0	
20 (08)	NOL	Team as an FYI train 20(08) is using a VW 11 in lieu of a VW I / line 2010 car 62508. The schedule change was done earlier.	N/A	0	62508
607 (08)	NYP	Train will operate with an extra coach and engine in lieu of cab car.	none	0	81511, 665
647 (08)	PHL	TRAIN WILL OPERATE WITH ONE LESS COACH CAR. INVENTORY HAS BEEN REDUCED. NO EFFECTED PAX.	No impact	0	
365 (08)	PTH	Train 365(08) is operating without cafe service due to (BYD-ID4302 -water and flooding)	n/ano cafe service	0	ID4302
2250 (08)	WAS	Due to high shop counts of NextGen equipment in Washington, TRN 2250(08) will operate with Legacy equipment (in lieu of NextGen equipment).	N/A	0	3214

Reverse Consists

27-FOI-00137 00000009130 "UNCLASSIFIED" 11/10/2026

Train Number	Station	Reason
151 (08)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
150 (08)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
144 (08)	PHL	Consist reversed | Business class seat orientation may have changed | At Rear
2203 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Rear
109 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
155 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
101 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
153 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
135 (08)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
66 (08)	RNK	Consist reversed | Business class seat orientation may have changed | At Front
106 (08)	WAS	Consist reversed | Business class seat orientation may have changed | At Rear
103 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
107 (08)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1138 (09)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
142 (08)	WAS	Consist reversed | Business class seat orientation may have changed | At Front