

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, December 28, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-002Initial Terminal Performance By Division

Scheduled Departure Date: 12/27/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/27/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	271	54	80.1%	8,179	1,269	84.5%	26,088	3,459	86.7%
Central Division	85.5%	69	2	97.1%	1,791	267	85.1%	5,813	636	89.1%
Northeast Division	80.0%	80	28	65.0%	2,626	432	83.5%	8,222	1,184	85.6%
Southeast Division	72.5%	58	14	75.9%	1,868	305	83.7%	6,067	822	86.5%
Southwest Division	77.0%	64	10	84.4%	1,894	265	86.0%	5,986	817	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00217 Endpoint Arrival Dates through 12/27/25 "UNCLASSIFIED" 1/5/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	100,890	33,755	67%	2,697,675	664,747	75%	8,892,409	1,912,952	78%
Northeast Corridor	81%	38,087	19,612	49%	1,195,520	296,306	75%	3,986,921	814,190	80%
Acela	83%	5,666	3,711	35%	256,747	75,728	71%	848,947	193,407	77%
Northeast Regional	79%	32,421	15,901	51%	938,773	220,578	77%	3,137,974	620,783	80%
Richmond / Newport News / Norfolk	77%	11,244	4,877	57%	290,271	72,866	75%	956,277	216,371	77%
Springfield Shuttles	89%	631	78	88%	22,386	2,478	89%	55,908	6,173	89%
Roanoke	79%	2,951	1,411	52%	73,713	13,505	82%	242,466	40,254	83%
On Spine Northeast Regional	80%	17,595	9,535	46%	552,403	131,729	76%	1,883,323	357,985	81%
State Supported	80%	46,426	11,715	75%	1,151,416	242,509	79%	3,798,090	725,564	81%
Borealis	60%	602	193	68%	15,132	3,780	75%	51,422	13,351	74%
Capitol Corridor	90%	3,200	731	77%	89,867	9,300	90%	308,460	32,696	89%
Carolinian	60%	1,134	339	70%	29,823	8,597	71%	102,969	29,499	71%
Cascades	63%	2,994	535	82%	63,344	14,530	77%	209,633	49,867	76%
Downeaster	82%	1,396	0	100%	37,938	4,616	88%	129,196	16,392	87%
Empire	78%	5,921	3,533	40%	153,767	33,926	78%	469,951	95,471	80%
Adirondack	72%	218	192	12%	8,236	3,814	54%	29,135	10,365	64%
Ethan Allen Express	70%	570	463	19%	15,011	4,021	73%	52,004	15,542	70%
Maple Leaf	70%	884	881	0%	19,525	10,915	44%	54,907	22,703	59%
New York - Albany	85%	2,701	1,214	55%	74,735	8,861	88%	213,342	27,983	87%
New York - Niagara Falls	75%	1,548	783	49%	36,260	6,315	83%	120,563	18,878	84%
Gold Runner	73%	3,351	1,747	48%	67,326	26,479	61%	221,374	82,124	63%
Heartland Flyer	65%	387	2	99%	5,878	720	88%	18,387	8,290	55%
Hiawatha	90%	1,845	0	100%	46,124	7,950	83%	152,577	18,865	88%
Illinois	78%	2,476	39	98%	63,752	22,025	65%	213,589	61,343	71%
Carl Sandburg / Illinois Zephyr	85%	485	0	100%	11,980	3,262	73%	37,138	9,820	74%
Illini / Saluki	85%	800	39	95%	19,775	6,880	65%	74,599	20,339	73%
Lincoln Service	70%	1,191	0	100%	31,997	11,883	63%	101,852	31,184	69%
Keystone	92%	6,385	1,508	76%	225,686	31,033	86%	721,264	71,844	90%
Lincoln / Missouri	60%	923	275	70%	20,469	8,996	56%	68,769	33,652	51%
Mardi Gras Service	80%	516	132	74%	10,048	863	91%	37,721	4,622	88%
Michigan	69%	2,234	86	96%	53,627	22,498	58%	172,962	52,386	70%
Blue Water	70%	534	0	100%	11,849	5,588	53%	42,634	12,883	70%
Pere Marquette	85%	312	0	100%	7,376	2,147	71%	23,272	4,076	82%
Wolverine	65%	1,388	86	94%	34,402	14,763	57%	107,056	35,427	67%
Missouri	80%	341	168	51%	6,394	1,395	78%	20,964	4,931	76%
Pacific Surfliner	85%	8,471	749	91%	172,251	24,922	86%	585,239	83,069	86%
Pennsylvanian	72%	1,099	0	100%	24,759	3,018	88%	81,783	9,216	89%
Piedmont	73%	1,646	686	58%	29,011	5,062	83%	113,340	26,893	76%
Vermont	75%	1,505	992	34%	36,220	12,799	65%	118,490	31,053	74%
Long Distance	56%	15,707	2,428	85%	347,849	125,665	64%	1,104,508	372,931	66%
Auto Train	57%	895	0	100%	20,041	2,995	85%	59,866	10,206	83%
California Zephyr	50%	1,219	446	63%	24,536	7,276	70%	81,344	22,947	72%
Cardinal	55%	357	38	89%	7,275	2,845	61%	24,631	11,150	55%
City Of New Orleans	75%	869	340	61%	18,985	3,734	80%	62,311	13,456	78%
Coast Starlight	60%	1,614	363	78%	33,032	10,939	67%	103,570	33,314	68%
Crescent	70%	1,262	135	89%	26,324	4,911	81%	85,439	20,693	76%
Empire Builder	55%	1,388	368	73%	28,223	12,247	57%	88,640	32,508	63%
Floridian	40%	1,915	327	83%	46,902	30,396	35%	150,803	84,768	44%
Lake Shore Ltd	73%	1,386	47	97%	29,475	8,819	70%	85,403	17,080	80%
Palmetto	65%	1,157	0	100%	25,713	6,483	75%	85,522	14,914	83%
Silver Meteor	45%	1,299	212	84%	28,893	11,379	61%	91,642	29,713	68%
Southwest Chief	40%	840	142	83%	21,239	13,199	38%	72,813	43,553	40%
Sunset Ltd	70%	0	0	-	8,364	1,590	81%	24,746	5,814	77%
Texas Eagle	50%	1,506	10	99%	28,847	8,852	69%	87,778	32,815	63%
Seasonal Trains	%	670	0	100%	2,890	267	91%	2,890	267	91%
Winter Park Express	75%	670	0	100%	2,890	267	91%	2,890	267	91%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00217 00000005502 "UNCLASSIFIED" 1/5/2020

Train Index Dates Through December 27, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	168,687	2,914,453	579	498,569	9,423,246	529

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,056	852,634	83	19,411	2,754,871	70
INFRASTRUCTURE PLANNED	135	4,259	852,634	50	14,840	2,754,871	54
FLEET RELIABILITY	90	29,884	2,914,453	103	77,768	9,423,246	83
TRAIN OPERATIONS	424	127,488	2,914,453	437	386,550	9,423,246	410

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/27/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/27/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	271	54	80.1%	8,179	1,269	84.5%	26,088	3,459	86.7%
Central Division	85.5%	69	2	97.1%	1,791	267	85.1%	5,813	636	89.1%
Northeast Division	80.0%	80	28	65.0%	2,626	432	83.5%	8,222	1,184	85.6%
Southeast Division	72.5%	58	14	75.9%	1,868	305	83.7%	6,067	822	86.5%
Southwest Division	77.0%	64	10	84.4%	1,894	265	86.0%	5,986	817	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/27/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/27/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	271	54	80.1%	8,179	1,269	84.5%	26,088	3,459	86.7%
Central Division	85.5%	69	2	97.1%	1,791	267	85.1%	5,813	636	89.1%
CDL	90.0%	2	0	100.0%	33	2	93.9%	147	8	94.6%
CHI	85.0%	27	0	100.0%	725	130	82.1%	2,358	267	88.7%
CHM	-	-	-	-	13	5	61.5%	13	5	61.5%
DEN	-	1	0	100.0%	5	2	60.0%	5	2	60.0%
EUG	86.5%	2	0	100.0%	53	8	84.9%	170	23	86.5%
GRR	98.0%	1	0	100.0%	26	2	92.3%	87	2	97.7%
KCY	84.5%	2	1	50.0%	53	4	92.5%	173	15	91.3%
MKE	86.5%	6	0	100.0%	158	16	89.9%	514	46	91.1%
MSP	94.0%	1	0	100.0%	27	0	100.0%	88	3	96.6%
PDX	78.0%	5	0	100.0%	135	13	90.4%	441	59	86.6%
PNT	91.5%	3	0	100.0%	80	14	82.5%	206	19	90.8%
PTH	93.0%	1	0	100.0%	26	4	84.6%	87	6	93.1%
QCY	87.5%	2	0	100.0%	54	4	92.6%	176	16	90.9%
SEA	80.0%	8	1	87.5%	214	38	82.2%	699	112	84.0%
SPK	92.0%	1	0	100.0%	30	4	86.7%	91	5	94.5%
STL	88.0%	4	0	100.0%	105	19	81.9%	347	37	89.3%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	49	2	95.9%	171	6	96.5%
WIP	-	1	0	100.0%	5	0	100.0%	5	0	100.0%
Northeast Division	80.0%	80	28	65.0%	2,626	432	83.5%	8,222	1,184	85.6%
ALB	91.5%	8	2	75.0%	216	14	93.5%	583	35	94.0%
BON	43.5%	5	0	100.0%	134	9	93.3%	421	41	90.3%
BOS	86.5%	15	11	26.7%	507	82	83.8%	1,605	185	88.5%
BRK	88.0%	5	0	100.0%	134	6	95.5%	401	19	95.3%
BTN	48.0%	1	0	100.0%	27	0	100.0%	87	17	80.5%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	1	0	100.0%	53	5	90.6%	169	14	91.7%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	1	0.0%	27	6	77.8%	88	17	80.7%
NFL	96.5%	3	1	66.7%	55	3	94.5%	177	7	96.0%
NHV	75.5%	4	2	50.0%	149	17	88.6%	456	80	82.5%
NYP	77.5%	30	11	63.3%	1,087	281	74.1%	3,463	711	79.5%
SAB	98.0%	1	0	100.0%	27	0	100.0%	86	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	0	100.0%	184	6	96.7%	533	22	95.9%
TWO	84.0%	-	-	-	26	3	88.5%	86	19	77.9%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	58	14	75.9%	1,868	305	83.7%	6,067	822	86.5%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	3	40.0%	135	10	92.6%	440	35	92.0%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	7	2	71.4%	303	80	73.6%	983	178	81.9%
LOR	69.5%	1	1	0.0%	27	2	92.6%	88	7	92.0%

Information Management

26-FOI-001000 Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/27/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/27/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	271	54	80.1%	8,179	1,269	84.5%	26,088	3,459	86.7%
Southeast Division	72.5%	58	14	75.9%	1,868	305	83.7%	6,067	822	86.5%
MIA	87.5%	2	0	100.0%	54	6	88.9%	176	19	89.2%
MOE	94.0%	2	0	100.0%	54	0	100.0%	176	3	98.3%
NFK	86.0%	3	0	100.0%	77	10	87.0%	247	25	89.9%
NOL	92.0%	5	0	100.0%	120	6	95.0%	389	20	94.9%
NPN	96.0%	2	0	100.0%	54	3	94.4%	151	10	93.4%
PGH	92.0%	1	0	100.0%	27	2	92.6%	88	3	96.6%
PHL	45.0%	4	4	0.0%	124	79	36.3%	405	202	50.1%
RGH	97.0%	4	1	75.0%	108	6	94.4%	348	9	97.4%
RNK	85.5%	2	1	50.0%	54	7	87.0%	175	21	88.0%
RVM	86.0%	1	0	100.0%	27	2	92.6%	98	13	86.7%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	27	2	92.6%	88	2	97.7%
SFA	70.5%	1	0	100.0%	27	0	100.0%	88	3	96.6%
WAS	70.0%	17	2	88.2%	650	90	86.2%	2,119	267	87.4%
Southwest Division	77.0%	64	10	84.4%	1,894	265	86.0%	5,986	817	86.4%
ARN	60.5%	1	0	100.0%	27	1	96.3%	88	6	93.2%
BFD	75.5%	7	2	71.4%	177	42	76.3%	524	126	76.0%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	32	18	43.8%	95	35	63.2%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	27	0	100.0%	87	3	96.6%
GTA	72.5%	3	1	66.7%	81	8	90.1%	257	25	90.3%
LAX	77.5%	9	0	100.0%	253	31	87.7%	813	92	88.7%
OKC	96.0%	1	0	100.0%	27	0	100.0%	88	3	96.6%
OKJ	79.0%	8	2	75.0%	298	84	71.8%	958	236	75.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	11	3	72.7%	377	38	89.9%	1,165	124	89.4%
SAN	77.0%	12	2	83.3%	316	27	91.5%	1,009	92	90.9%
SAS	85.0%	1	0	100.0%	27	1	96.3%	88	4	95.5%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	189	11	94.2%	614	51	91.7%
SLO	62.0%	2	0	100.0%	54	3	94.4%	171	14	91.8%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		27	6	77.8%	88	10	88.6%	26	11	57.7%	87	34	60.9%
4		26	7	73.1%	87	13	85.1%	26	19	26.9%	87	57	34.5%
5		27	8	70.4%	87	15	82.8%	26	6	76.9%	85	12	85.9%
6		25	11	56.0%	86	28	67.4%	25	5	80.0%	86	26	69.8%
7		27	5	81.5%	88	9	89.8%	23	6	73.9%	84	13	84.5%
8		27	16	40.7%	88	36	59.1%	27	14	48.1%	88	41	53.4%
11		27	5	81.5%	87	16	81.6%	27	7	74.1%	85	14	83.5%
14		27	2	92.6%	88	11	87.5%	27	3	88.9%	87	21	75.9%
19		27	9	66.7%	88	17	80.7%	27	2	92.6%	88	13	85.2%
20		27	0	100.0%	88	6	93.2%	27	2	92.6%	88	8	90.9%
21		27	5	81.5%	87	13	85.1%	27	6	77.8%	87	17	80.5%
22		27	1	96.3%	88	4	95.5%	27	4	85.2%	87	17	80.5%
23	17	27	0	100.0%	88	3	96.6%	27	3	88.9%	88	13	85.2%
24		27	5	81.5%	88	7	92.0%	27	3	88.9%	88	9	89.8%
25		27	0	100.0%	88	0	100.0%	27	1	96.3%	88	10	88.6%
26		27	0	100.0%	88	2	97.7%	27	2	92.6%	88	13	85.2%
27		27	3	88.9%	88	4	95.5%	26	8	69.2%	87	18	79.3%
28		26	5	80.8%	87	18	79.3%	26	3	88.5%	87	11	87.4%
40		27	5	81.5%	88	14	84.1%	27	12	55.6%	88	34	61.4%
41		27	13	51.9%	88	31	64.8%	27	18	33.3%	88	57	35.2%
42		27	2	92.6%	88	3	96.6%	27	3	88.9%	88	12	86.4%
43		27	3	88.9%	88	8	90.9%	27	1	96.3%	88	4	95.5%
48		27	8	70.4%	88	13	85.2%	27	6	77.8%	88	9	89.8%
49		27	3	88.9%	88	13	85.2%	27	7	74.1%	88	12	86.4%
51		11	4	63.6%	38	18	52.6%	11	2	81.8%	37	11	70.3%
52		27	0	100.0%	88	3	96.6%	27	2	92.6%	88	14	84.1%
53		27	2	92.6%	88	7	92.0%	27	4	85.2%	88	12	86.4%
54		8	0	100.0%	27	0	100.0%	8	2	75.0%	27	3	88.9%
57		8	0	100.0%	27	1	96.3%	8	1	87.5%	27	1	96.3%
58		27	1	96.3%	87	3	96.6%	27	6	77.8%	86	13	84.9%
59	118	27	4	85.2%	86	7	91.9%	27	5	81.5%	86	8	90.7%
63	77	27	15	44.4%	88	36	59.1%	26	15	42.3%	87	44	49.4%
64	86	27	4	85.2%	87	20	77.0%	27	9	66.7%	87	19	78.2%
65		9	2	77.8%	28	5	82.1%	8	2	75.0%	27	7	74.1%
66	27	27	3	88.9%	88	13	85.2%	27	2	92.6%	88	15	83.0%
68	No OS	27	6	77.8%	88	17	80.7%	27	18	33.3%	88	43	51.1%
69	68	27	3	88.9%	88	10	88.6%	27	4	85.2%	88	11	87.5%
71		27	1	96.3%	88	1	98.9%	27	7	74.1%	88	23	73.9%
72	47	27	4	85.2%	88	9	89.8%	27	11	59.3%	88	21	76.1%
73	21	27	2	92.6%	88	3	96.6%	27	10	63.0%	87	43	50.6%
74		27	2	92.6%	88	7	92.0%	27	5	81.5%	88	25	71.6%
75		27	1	96.3%	88	3	96.6%	27	10	63.0%	88	38	56.8%

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		27	0	100.0%	88	4	95.5%	27	5	81.5%	88	35	60.2%
77	64	27	2	92.6%	88	4	95.5%	27	8	70.4%	88	30	65.9%
78		27	1	96.3%	88	4	95.5%	27	2	92.6%	88	11	87.5%
79		27	9	66.7%	88	20	77.3%	27	3	88.9%	87	14	83.9%
80		27	3	88.9%	88	11	87.5%	27	5	81.5%	87	10	88.5%
82	189	5	0	100.0%	14	0	100.0%	5	1	80.0%	14	1	92.9%
87		8	2	75.0%	27	6	77.8%	8	1	87.5%	27	5	81.5%
88	171	8	0	100.0%	27	1	96.3%	8	2	75.0%	27	4	85.2%
89		27	5	81.5%	88	17	80.7%	27	8	70.4%	88	14	84.1%
90		27	2	92.6%	88	2	97.7%	27	3	88.9%	88	9	89.8%
97		27	20	25.9%	88	38	56.8%	27	3	88.9%	88	19	78.4%
98		27	1	96.3%	88	5	94.3%	27	12	55.6%	88	23	73.9%
99	82	8	1	87.5%	27	2	92.6%	8	3	62.5%	26	11	57.7%
101		5	1	80.0%	14	1	92.9%	5	0	100.0%	14	0	100.0%
103		8	0	100.0%	27	3	88.9%	8	1	87.5%	27	1	96.3%
106		8	1	87.5%	27	2	92.6%	8	1	87.5%	27	3	88.9%
107		8	3	62.5%	27	5	81.5%	8	1	87.5%	27	2	92.6%
118	21	8	1	87.5%	27	2	92.6%	8	2	75.0%	27	2	92.6%
124		8	0	100.0%	27	2	92.6%	8	0	100.0%	27	4	85.2%
135	335	8	2	75.0%	27	4	85.2%	8	4	50.0%	27	13	51.9%
136	41	19	2	89.5%	61	5	91.8%	19	2	89.5%	62	5	91.9%
140	124	8	0	100.0%	27	2	92.6%	8	2	75.0%	27	6	77.8%
142		5	0	100.0%	14	0	100.0%	5	0	100.0%	14	0	100.0%
143	96	8	0	100.0%	27	2	92.6%	8	2	75.0%	27	3	88.9%
144		5	3	40.0%	15	8	46.7%	5	0	100.0%	15	0	100.0%
146	36	8	3	62.5%	27	5	81.5%	8	3	62.5%	27	8	70.4%
147	45	5	1	80.0%	14	3	78.6%	5	1	80.0%	14	2	85.7%
150	258	8	8	0.0%	27	21	22.2%	8	6	25.0%	27	18	33.3%
151	175	27	13	51.9%	88	27	69.3%	27	9	66.7%	87	25	71.3%
152	72	5	0	100.0%	14	0	100.0%	5	2	60.0%	14	4	71.4%
153		8	1	87.5%	27	2	92.6%	8	3	62.5%	27	3	88.9%
155	63	8	1	87.5%	27	2	92.6%	8	2	75.0%	27	3	88.9%
156		8	2	75.0%	27	3	88.9%	8	3	62.5%	27	5	81.5%
158		8	0	100.0%	27	0	100.0%	8	1	87.5%	27	1	96.3%
159		5	1	80.0%	14	1	92.9%	5	0	100.0%	14	0	100.0%
160	126	8	0	100.0%	27	0	100.0%	7	3	57.1%	25	4	84.0%
161	57	8	1	87.5%	27	1	96.3%	8	6	25.0%	27	14	48.1%
162	95	8	1	87.5%	27	2	92.6%	8	4	50.0%	27	10	63.0%
163	147	5	1	80.0%	14	2	85.7%	5	3	40.0%	14	8	42.9%
164	94	8	1	87.5%	27	4	85.2%	8	4	50.0%	27	8	70.4%
165	No OS	8	4	50.0%	27	7	74.1%	8	3	62.5%	27	7	74.1%
168	47	5	0	100.0%	14	2	85.7%	5	2	60.0%	14	4	71.4%

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178	125	19	2	89.5%	61	9	85.2%	19	3	84.2%	62	8	87.1%
179	64	19	2	89.5%	61	6	90.2%	19	4	78.9%	62	14	77.4%
194	67	5	1	80.0%	14	3	78.6%	5	1	80.0%	14	2	85.7%
195	16	8	0	100.0%	27	0	100.0%	8	5	37.5%	27	18	33.3%
232		27	0	100.0%	88	1	98.9%	27	0	100.0%	88	6	93.2%
233	27	27	8	70.4%	88	21	76.1%	27	7	74.1%	88	19	78.4%
234		27	0	100.0%	88	3	96.6%	27	0	100.0%	88	2	97.7%
235	78	27	3	88.9%	27	3	88.9%	27	5	81.5%	27	5	81.5%
236		27	0	100.0%	88	1	98.9%	27	4	85.2%	88	15	83.0%
237		27	4	85.2%	88	14	84.1%	26	2	92.3%	87	6	93.1%
238	66	27	3	88.9%	27	3	88.9%	27	2	92.6%	27	2	92.6%
239		27	9	66.7%	87	24	72.4%	27	2	92.6%	87	4	95.4%
240	28	27	2	92.6%	88	8	90.9%	27	5	81.5%	88	12	86.4%
241		27	8	70.4%	88	24	72.7%	27	4	85.2%	88	14	84.1%
244		27	1	96.3%	88	3	96.6%	27	2	92.6%	88	17	80.7%
280		27	1	96.3%	88	4	95.5%	27	5	81.5%	88	15	83.0%
281	168	27	0	100.0%	88	8	90.9%	27	3	88.9%	88	8	90.9%
283	90	27	10	63.0%	88	18	79.5%	27	5	81.5%	88	14	84.1%
284		27	1	96.3%	88	2	97.7%	27	2	92.6%	88	7	92.0%
290	34	27	0	100.0%	88	18	79.5%	27	8	70.4%	87	29	66.7%
291		27	5	81.5%	88	18	79.5%	27	3	88.9%	88	15	83.0%
300		27	6	77.8%	88	8	90.9%	27	9	66.7%	87	23	73.6%
301		26	1	96.2%	86	2	97.7%	26	5	80.8%	85	14	83.5%
302		25	5	80.0%	85	11	87.1%	25	7	72.0%	83	24	71.1%
305		27	7	74.1%	88	12	86.4%	26	14	46.2%	86	34	60.5%
306		26	3	88.5%	86	5	94.2%	26	8	69.2%	85	19	77.6%
307		27	5	81.5%	87	10	88.5%	26	9	65.4%	86	20	76.7%
311	56	27	5	81.5%	87	12	86.2%	26	6	76.9%	86	20	76.7%
316		26	2	92.3%	86	5	94.2%	26	6	76.9%	86	18	79.1%
318		27	2	92.6%	88	11	87.5%	27	10	63.0%	87	35	59.8%
319		27	2	92.6%	88	4	95.5%	27	9	66.7%	88	45	48.9%
330		23	0	100.0%	74	2	97.3%	23	4	82.6%	74	5	93.2%
331		27	7	74.1%	88	11	87.5%	27	7	74.1%	88	13	85.2%
332	12	27	4	85.2%	88	9	89.8%	27	10	63.0%	88	15	83.0%
334		27	1	96.3%	88	2	97.7%	27	8	70.4%	87	12	86.2%
335		27	7	74.1%	88	14	84.1%	26	7	73.1%	86	16	81.4%
336		27	3	88.9%	88	4	95.5%	27	1	96.3%	88	5	94.3%
337		27	1	96.3%	88	5	94.3%	27	6	77.8%	88	11	87.5%
338	11	27	6	77.8%	88	21	76.1%	26	10	61.5%	86	22	74.4%
339		27	5	81.5%	88	19	78.4%	27	7	74.1%	88	18	79.5%
341		25	4	84.0%	85	13	84.7%	24	4	83.3%	84	12	85.7%
342		27	2	92.6%	88	8	90.9%	27	7	74.1%	87	15	82.8%

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
343		4	0	100.0%	13	1	92.3%	4	1	75.0%	13	4	69.2%
350		27	1	96.3%	70	3	95.7%	27	17	37.0%	70	39	44.3%
351		27	8	70.4%	88	11	87.5%	27	10	63.0%	88	36	59.1%
352		27	2	92.6%	88	6	93.2%	26	9	65.4%	85	23	72.9%
353		27	3	88.9%	67	5	92.5%	27	11	59.3%	67	16	76.1%
354		27	5	81.5%	88	8	90.9%	26	12	53.8%	87	26	70.1%
355		26	3	88.5%	87	8	90.8%	25	10	60.0%	86	23	73.3%
364		26	11	57.7%	87	16	81.6%	25	11	56.0%	86	19	77.9%
365		26	4	84.6%	87	6	93.1%	25	10	60.0%	86	26	69.8%
370		27	3	88.9%	88	5	94.3%	27	7	74.1%	88	16	81.8%
371		26	2	92.3%	87	2	97.7%	26	6	76.9%	87	10	88.5%
380		27	4	85.2%	88	14	84.1%	27	7	74.1%	88	20	77.3%
381		27	1	96.3%	88	2	97.7%	27	4	85.2%	88	11	87.5%
382		27	0	100.0%	88	2	97.7%	27	7	74.1%	88	22	75.0%
383		27	4	85.2%	88	9	89.8%	26	12	53.8%	86	34	60.5%
390		19	5	73.7%	72	9	87.5%	18	6	66.7%	71	22	69.0%
391		19	2	89.5%	73	2	97.3%	18	2	88.9%	71	14	80.3%
392		27	2	92.6%	88	4	95.5%	27	13	51.9%	87	28	67.8%
393		27	2	92.6%	88	7	92.0%	27	10	63.0%	87	25	71.3%
400		8	1	87.5%	26	2	92.3%	8	1	87.5%	25	1	96.0%
405		8	0	100.0%	23	0	100.0%	8	0	100.0%	23	1	95.7%
448		27	9	66.7%	29	10	65.5%	26	10	61.5%	27	10	63.0%
449		26	1	96.2%	26	1	96.2%	26	4	84.6%	26	4	84.6%
450	67	8	4	50.0%	24	8	66.7%	8	2	75.0%	24	8	66.7%
460	28	8	3	62.5%	24	10	58.3%	8	2	75.0%	23	6	73.9%
461		8	1	87.5%	26	2	92.3%	8	0	100.0%	26	1	96.2%
463		5	1	80.0%	13	1	92.3%	5	0	100.0%	13	0	100.0%
464		8	2	75.0%	24	4	83.3%	8	3	62.5%	24	7	70.8%
467		5	0	100.0%	13	1	92.3%	5	0	100.0%	12	0	100.0%
488	Cncl'd	8	1	87.5%	27	7	74.1%	7	0	100.0%	24	4	83.3%
500		27	1	96.3%	88	6	93.2%	27	4	85.2%	87	9	89.7%
502	16	27	1	96.3%	88	7	92.0%	27	4	85.2%	87	20	77.0%
503		27	3	88.9%	85	11	87.1%	27	7	74.1%	84	22	73.8%
504		27	2	92.6%	88	7	92.0%	27	6	77.8%	88	25	71.6%
505		27	6	77.8%	88	16	81.8%	27	4	85.2%	86	17	80.2%
506		27	5	81.5%	87	14	83.9%	27	4	85.2%	86	13	84.9%
507		27	3	88.9%	88	10	88.6%	27	9	66.7%	88	31	64.8%
508		27	7	74.1%	86	18	79.1%	27	8	70.4%	86	21	75.6%
509		27	3	88.9%	88	7	92.0%	27	11	59.3%	88	24	72.7%
511		27	5	81.5%	88	9	89.8%	27	4	85.2%	88	16	81.8%
516		25	0	100.0%	86	9	89.5%	25	7	72.0%	86	35	59.3%
517	26	27	1	96.3%	88	2	97.7%	27	9	66.7%	87	31	64.4%

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
518		27	0	100.0%	88	13	85.2%	27	15	44.4%	88	51	42.0%
519		25	1	96.0%	86	4	95.3%	25	4	84.0%	86	13	84.9%
562		27	3	88.9%	86	11	87.2%	27	3	88.9%	85	9	89.4%
564		27	3	88.9%	86	9	89.5%	26	2	92.3%	82	12	85.4%
566		27	1	96.3%	86	6	93.0%	27	2	92.6%	83	8	90.4%
572		27	1	96.3%	85	7	91.8%	26	3	88.5%	83	17	79.5%
573	22	27	3	88.9%	86	12	86.0%	26	2	92.3%	84	10	88.1%
577		27	2	92.6%	84	7	91.7%	27	6	77.8%	80	8	90.0%
580		27	0	100.0%	86	2	97.7%	27	2	92.6%	86	9	89.5%
581		27	3	88.9%	86	10	88.4%	27	3	88.9%	86	15	82.6%
582		27	2	92.6%	86	6	93.0%	27	3	88.9%	84	7	91.7%
586		27	8	70.4%	86	19	77.9%	25	2	92.0%	81	11	86.4%
587		27	2	92.6%	86	5	94.2%	25	1	96.0%	82	10	87.8%
591		27	1	96.3%	86	2	97.7%	26	2	92.3%	85	8	90.6%
593		27	5	81.5%	86	14	83.7%	25	4	84.0%	78	9	88.5%
595	17	27	5	81.5%	85	19	77.6%	27	3	88.9%	84	13	84.5%
611		5	5	0.0%	14	11	21.4%	5	0	100.0%	14	1	92.9%
624		19	8	57.9%	61	18	70.5%	19	4	78.9%	62	13	79.0%
660	45	8	1	87.5%	27	2	92.6%	8	2	75.0%	27	10	63.0%
661		8	0	100.0%	27	3	88.9%	8	1	87.5%	27	6	77.8%
662		5	0	100.0%	16	0	100.0%	5	0	100.0%	16	0	100.0%
663		8	1	87.5%	27	3	88.9%	8	0	100.0%	27	1	96.3%
664		8	1	87.5%	27	5	81.5%	8	0	100.0%	27	1	96.3%
665	60	8	4	50.0%	27	6	77.8%	8	3	62.5%	27	11	59.3%
666	47	8	4	50.0%	27	10	63.0%	8	2	75.0%	27	3	88.9%
667	11	8	1	87.5%	27	3	88.9%	8	3	62.5%	27	6	77.8%
669		8	1	87.5%	27	1	96.3%	8	2	75.0%	27	9	66.7%
670		8	2	75.0%	27	4	85.2%	8	1	87.5%	27	2	92.6%
671		8	0	100.0%	27	1	96.3%	8	3	62.5%	27	4	85.2%
672		8	1	87.5%	27	3	88.9%	8	1	87.5%	27	2	92.6%
674		8	3	62.5%	27	7	74.1%	8	0	100.0%	27	0	100.0%
689		16	1	93.8%	52	5	90.4%	16	1	93.8%	52	4	92.3%
690		7	0	100.0%	25	0	100.0%	7	0	100.0%	25	1	96.0%
691		7	0	100.0%	25	2	92.0%	7	0	100.0%	25	6	76.0%
692		7	0	100.0%	25	1	96.0%	7	1	85.7%	25	6	76.0%
693		7	0	100.0%	25	3	88.0%	7	1	85.7%	25	6	76.0%
694		7	0	100.0%	25	4	84.0%	7	1	85.7%	25	2	92.0%
695		7	0	100.0%	25	2	92.0%	7	0	100.0%	25	5	80.0%
696		7	0	100.0%	25	1	96.0%	7	1	85.7%	25	4	84.0%
697		7	0	100.0%	25	3	88.0%	7	1	85.7%	25	5	80.0%
698		7	0	100.0%	25	0	100.0%	7	1	85.7%	25	3	88.0%
701		20	6	70.0%	20	6	70.0%	20	2	90.0%	20	2	90.0%

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
702		27	2	92.6%	88	17	80.7%	27	5	81.5%	87	24	72.4%
703		27	8	70.4%	88	23	73.9%	27	7	74.1%	88	23	73.9%
704		20	3	85.0%	20	3	85.0%	19	4	78.9%	19	4	78.9%
710	65	27	10	63.0%	88	34	61.4%	27	6	77.8%	88	34	61.4%
711		25	2	92.0%	82	6	92.7%	22	5	77.3%	75	12	84.0%
712	16	27	5	81.5%	88	22	75.0%	26	9	65.4%	86	32	62.8%
713		24	3	87.5%	85	12	85.9%	20	6	70.0%	75	33	56.0%
714		27	10	63.0%	82	29	64.6%	25	8	68.0%	75	24	68.0%
715	19	27	6	77.8%	88	28	68.2%	23	13	43.5%	81	42	48.1%
716		27	16	40.7%	88	39	55.7%	26	16	38.5%	86	39	54.7%
717		27	7	74.1%	79	20	74.7%	25	13	48.0%	72	26	63.9%
718		27	17	37.0%	88	39	55.7%	26	13	50.0%	87	29	66.7%
719	17	27	10	63.0%	88	34	61.4%	27	13	51.9%	86	29	66.3%
720		9	0	100.0%	29	2	93.1%	9	0	100.0%	29	1	96.6%
723		9	0	100.0%	29	3	89.7%	9	1	88.9%	29	3	89.7%
724	28	9	0	100.0%	29	0	100.0%	9	2	77.8%	29	2	93.1%
727		9	0	100.0%	29	3	89.7%	9	0	100.0%	29	6	79.3%
728		9	0	100.0%	29	2	93.1%	9	0	100.0%	29	4	86.2%
729		9	1	88.9%	29	3	89.7%	9	2	77.8%	29	7	75.9%
732		9	1	88.9%	29	4	86.2%	9	0	100.0%	29	4	86.2%
733	16	9	0	100.0%	29	3	89.7%	8	3	62.5%	25	6	76.0%
734		9	1	88.9%	29	9	69.0%	9	0	100.0%	29	6	79.3%
738		9	2	77.8%	29	5	82.8%	9	0	100.0%	27	1	96.3%
741		9	3	66.7%	29	6	79.3%	9	0	100.0%	29	4	86.2%
742		9	1	88.9%	29	4	86.2%	9	0	100.0%	28	3	89.3%
743		9	2	77.8%	29	4	86.2%	9	1	88.9%	29	2	93.1%
744	71	9	2	77.8%	29	3	89.7%	9	5	44.4%	29	10	65.5%
745		9	1	88.9%	29	3	89.7%	9	4	55.6%	29	6	79.3%
746		9	0	100.0%	29	0	100.0%	9	1	88.9%	29	2	93.1%
747	34	9	3	66.7%	29	6	79.3%	9	4	55.6%	29	6	79.3%
748		9	0	100.0%	28	5	82.1%	9	1	88.9%	28	2	92.9%
749		9	1	88.9%	29	5	82.8%	9	0	100.0%	25	2	92.0%
751	25	9	3	66.7%	29	7	75.9%	8	1	87.5%	28	5	82.1%
761	22	27	1	96.3%	86	4	95.3%	27	5	81.5%	86	14	83.7%
765		27	1	96.3%	86	8	90.7%	27	3	88.9%	86	16	81.4%
769		27	3	88.9%	86	7	91.9%	27	5	81.5%	84	16	81.0%
770		27	3	88.9%	86	10	88.4%	27	4	85.2%	86	13	84.9%
774		27	1	96.3%	86	7	91.9%	27	7	74.1%	85	18	78.8%
779	No OS	27	0	100.0%	86	4	95.3%	27	8	70.4%	85	17	80.0%
784		27	4	85.2%	86	10	88.4%	27	15	44.4%	85	44	48.2%
785		27	1	96.3%	86	1	98.8%	27	6	77.8%	86	13	84.9%
790		27	1	96.3%	86	6	93.0%	27	4	85.2%	86	11	87.2%

Amtrak On Time Performance

Trains Arriving Through: 12/27/2025

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
794		27	2	92.6%	86	7	91.9%	27	6	77.8%	85	16	81.2%
821		27	0	100.0%	88	3	96.6%	27	6	77.8%	88	46	47.7%
822		27	0	100.0%	88	3	96.6%	27	3	88.9%	88	47	46.6%
1105		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
1106		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
1333	44	27	6	77.8%	88	10	88.6%	27	10	63.0%	87	36	58.6%
1340		27	0	100.0%	88	3	96.6%	27	7	74.1%	88	20	77.3%
2174	20	4	0	100.0%	14	2	85.7%	4	1	75.0%	14	3	78.6%
2203		5	0	100.0%	14	0	100.0%	5	0	100.0%	14	0	100.0%
2205		8	0	100.0%	27	3	88.9%	8	1	87.5%	27	2	92.6%
2216		5	0	100.0%	14	1	92.9%	5	0	100.0%	14	0	100.0%
2218	39	5	1	80.0%	14	2	85.7%	5	1	80.0%	14	1	92.9%
2248	35	7	2	71.4%	26	4	84.6%	7	3	57.1%	26	6	76.9%
2249	44	5	0	100.0%	14	0	100.0%	5	1	80.0%	14	4	71.4%
2250	31	8	0	100.0%	27	3	88.9%	8	3	62.5%	27	11	59.3%
2251	106	5	0	100.0%	14	0	100.0%	5	2	60.0%	14	5	64.3%
2252	121	7	1	85.7%	26	2	92.3%	7	1	85.7%	26	3	88.5%
2253	Cncld	6	1	83.3%	25	3	88.0%	5	3	40.0%	24	13	45.8%
2254	81	8	0	100.0%	27	0	100.0%	8	2	75.0%	27	6	77.8%
2255	330	8	1	87.5%	27	3	88.9%	8	3	62.5%	27	9	66.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/27/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2174	BOS	20	OTH	7	PTI	5	XHM-XCY	AM	Follow, AM196, Other, XHM-XCY
2218	NYP	39	DET	22	DET	22	NWK-NYP	AM	Catenary maintenance , Other, SINGLE TRACKING NORTH TUBE A/C SOUTH TUBE HAS NO POWER
2248	BOS	35	WTR	30	POL	15	XHM-XCY	AM	Right of Way police hold, RESTRICTED SPEED THROUGH MP38 TO MP39 A/C POLICE HOLD ON NO.1 TRK
2249	WAS	44	CTI	24	CTI	24	NHV-STM	MN	Follow mn, Milepost, 71, 33
2250	BOS	31	OTH	14	WTR	13	RTE-BBY	AM	Ice / snow on or under equipment, Milepost w/Letters, RTE, BBY, 30 MPH S/r
2251	WAS	106	TRS	69	TRS	57	NWK-NWK	AM	Trespasser strike, Other, NWK-NWK, HELD A/C TRESPASSER STRIKE MP67.2158
2252	BOS	121	POL	66	POL	66	PHL-PHL	AM	Right of Way police hold, hold on all trks at PHL a/c SEPTA trespasser strike at MP 68.3
2253	XHM	Trn Cancelled	ITI	53	ITI	53	BOS-BOS	AM	Service, turn, or wye train, 2255, Late turn
2254	BOS	81	WTR	21	WTR	13	RTE-BBY	AM	Wet / slippery rail, Milepost w/Letters, RTE, BBY, 30 mph S/r
2255	WAS	330	ITI	256	ITI	256	BOS-BOS	AM	Service, turn, or wye train, 2248, late turn of AM2248
66	BOS	27	DCS	45	POL	35	XHM-NWK	AM	Right of Way police hold, HELD IN TRENTON A/C POLICE HOLD ON ALL TRACKS COUNTY TO MIDWAY
82	BOS	189	POL	102	POL	90	PHL-PHL	AM	Right of Way police hold, hold on all trks at PHL a/c SEPTA trespasser strike at MP 68.3
88	BOS	171	POL	49	POL	35	PHL-PHL	AM	Right of Way police hold, hold on all trks at PHL a/c SEPTA trespasser strike at MP 68.3
99	NPN	82	WTR	52	WTR	17	BRP-STM	MN	Ice / snow on or under equipment Control Point, 247
118	NYP	21	POL	13	POL	13	TRE-MET	AM	Right of Way police hold, RESTRICTED SPEED MP38 TO MP39 A/C POLICE HOLD ON NO.1 TRK
135	WAS	335	ITI	242	ITI	242	BOS-BOS	AM	Service, turn, or wye train, 150, late turn of AM150
136	SPG	41	PTI	26	DCS	15	NRO-STM	MN	Power switch failure Switch failure at cp232 cause delays into Stamford station (westbound)), Control Point, cp232
140	SPG	124	ENG	62	ENG	51	WND-WND	AM	Air / Brake, 145, AM140 e/145 rpts loosing main res a/c air leak

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/27/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
143	WAS	96	ENG	43	ENG	25	PHL-PHL	AM	PTC - On Board Cab Signal or PTC Failure, E/668, was opr 79 MPH a/c no valid TSR, ACSES failed on reset then cut out and on the move	
146	SPG	36	OTH	15	OTH	5	XNY-BWI	AM	Lost time - N.A.R., no train ahead	
147	RNK	45	TRS	49	TRS	39	NYP-NYP	AM	Trespasser strike, Other, NYP-NYP, HELD A/C TRESPASSER STRIKE AT MP67.2158	
150	BOS	258	SYS	157	SYS	157	RTE-BBY	AM	Unscheduled passenger stop, AM150 arrived on trk 2 at AM2253 for psngr transfer	
151	RNK	175	ENG	134	ENG	134	ALX-MSS	CS	Other electrical failure PTC ISSUE AS WELL AS COM CABLE ISSUE, 150	
152	BOS	72	WTR	41	SYS	24	NHV-NLC	AM	Copy authority / restriction, Stopped at Branford to Copy From D speed restriction XBU - XGU	
155	WAS	63	POL	31	POL	31	NBK-PJC	AM	Right of Way police hold, RESTRICTED SPEED THROUGH MP38 TO MP39 A/C POLICE HOLD ON NO.1 TRK	
160	BOS	126	WTR	10	WTR	7	TRE-MET	AM	Wet / slippery rail, Other, XMW-MET, ICY RAILS CAN ONLY GO 90 MPH	
161	WAS	57	HLD	19	DET	14	NYP-NYP	AM	Catenary maintenance , Other, NYP-NYP, SINGLE TRACKING IN THE NORTH TUBE A/C POWER LOSS IN THE SOUTH TUBE	
162	BOS	95	WTR	36	WTR	29	PVD-PVD	AM	Ice / snow on or under equipment, Other, PVD, Held at PVD due to downed wire	
163	WAS	147	HLD	27	DCS	17	BBY-RTE	AM	T.O.L, Control Point, Plains- Forest, Cabs dropped	
164	BOS	94	PTI	57	PTI	57	RTE-BBY	AM	Meet, 2255, 135, 165, Milepost w/Letters, RTE, BBY, AM164 was held for late Westbound trains	
165	WAS	No OS Rpt	ITI	157	ITI	157	BOS-BOS	AM	Service, turn, or wye train, 160, late turn of AM160	
168	BOS	47	WTR	19	WTR	10	RTE-RTE	AM	Ice / snow on or under equipment, Milepost, RTE, RTE, reporting burn marks on the pantograph on the lead unit Eng 664, reconfiguring. Excessive arcing B/C ICE ON WIRE	
178	BOS	125	ENG	64	ENG	25	NLC-XGX	AM	Traction motor, 633, AM178 reports cut out traction motors No. 1 and 2	
179	PHL	64	CTI	80	CTI	44	NHV-BRP	MN	Reverse move Due to switch failures AM179 reversed back into Bridgeport to be rerouted, MNR, Other, BRP	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/27/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
194	BOS	67	HLD	29	HLD	11	RTE-RTE	AM	Passenger and/or baggage, drunk psngr, needed use of station wheelchair to assist psngr off the train	
195	RVM	16	ADA	20	DSR	7	BRP-STM	MN	Per bulletin Milepost, 48.4, 48.6, 30, 1, Milepost, 41.7, 42.0, 15, 2, Milepost, 41.7, 40.4, 30, 1	
450	SPG	67	PTI	61	PTI	50	NHV-NHV	AM	Follow, 150, Milepost, nhv, nhv, Late train AM150	
460	SPG	28	CTI	21	CTI	11	NHV-NHV	AM	Meet, ctrail, 6403, Milepost, x1h, x1h	
488	GFD	Trn Cancelled	CON	130	CON	130	NHV-NHV	AM	Hold for connecting train, late due to late connection of AM88	
660	NYP	45	POL	44	POL	22	PJC-EWR	AM	Right of Way police hold, RESTRICTED SPEED MP38 TO MP39 A/C POLICE HOLD ON NO.1 TRK	
665	HAR	60	TRS	44	TRS	44	NYP-NYP	AM	Trespasser strike, Other, NYP-NYP, HELD A/C TRESPASSER STRIKE AT MP67.2158	
666	NYP	47	POL	28	TRS	16	PHL-XHM	AM	Trespasser strike, Control Point, ., opr restricted speeds a/c service disruption MP 68.3	
667	HAR	11	OTH	13	OTH	8	NWK-TRE	AM	Lost time - N.A.R., NO TIME LOST	
63	TWO	77	ADA	32	CAR	18	NYP-XSD	AM	Door, 82543, B END. BAD DOOR SEAL	
64	ALB	86	SVS	62	SVS	49	NFL-NFL	CS	Routine inspections All initial terminal inspections at Niagara maintenance facilities, shoved into station and loaded pax., Siding, Amtrak Siding	
68	NYP	No OS Rpt	ENG	161	ENG	99	MTR-MTR	CN	Slip axle alarm, 115	
69	MTR	9	PTI	40	PTI	40	WSP-PLB	DH	Meet amtrak 68, Milepost, 163, 165	
233	ALB	27	DCS	12	DCS	12	CRT-POU	MN	Issue with automatic road crossing protection Stop and warn at pirate canoe crossing per form m d-8, Milepost, 69.0, 70.1	
235	ALB	78	ITI	58	ITI	58	NYP-NYP	AM	Service, turn, or wye train, 238	
238	NYP	66	CTI	40	CTI	40	POU-CRT	MN	Follow mta, 8840, Milepost, 72, 35	
240	NYP	28	SVS	25	SVS	25	ALB-ALB	AM	Late release from shop	
281	NFL	168	ENG	157	ENG	157	NYP-XSD	AM	Air / Brake, 101, MADE REVERSE MOVE INTO NYP A/C AIR BRAKE ISSUE ON ENG.101	
283	NFL	90	MTI	55	MTI	55	NYP-NYP	AM	Disabled train ahead, Other, NYP-NYP, LATE TURN OFF DISABLED AM281 FROM SSYD	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/27/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
290	NYP	34	DCS	58	DCS	46	XWH-FED	DH	Power switch failure 3 frozen switches. Talked by CP 56 . Hand throw . Frozen lock and switch points . Cleaned out and used fusees to unfreeze. Returned switches to power, Control Point, 56
72	RGH	47	TCR	36	TCR	36	KAN-SAL	NS	Air / Brake / Wheel 400014, Stopped MP 337 issues with main res.
73	CLT	21	HLD	19	HLD	6	CYN-CYN	NS	High passenger count 97 pax on at CYN.
77	CLT	64	ITI	48	ITI	48	RGH-RGH	NS	Took over Late arrival train #Amtk72 equipment. 72, Late arrival train #Amtk72.
23	NOL	17	FTI	44	FTI	33	BAS-XNO	CS	Cross over or go around 606, Control Point, claiborne
724	SAC	28	PTI	39	PTI	20	FMT-HAY	UP	Meet Red Signal, amtk 727, Control Point, Shinn - NI030
733	SJC	16	CTI	13	CTI	9	GAC-SCC	UP	Meet caltrain, Control Point, coast
744	ARN	71	TRS	27	TRS	17	FMT-FMT	UP	Vehicle on track ahead Milepost, 32.0, 32.1
747	SJC	34	PTI	15	TRS	14	OAC-HAY	UP	Vehicle on track ahead Milepost, 24, 24.1
751	OKJ	25	CON	31	CON	31	SAC-SAC	UP	Hold for thruway bus Hold for S.Tahoe bus #3647 per RFE Herndobler
502	SEA	16	FTI	12	FTI	12	VAN-KEL	BN	Meet bnsf 7248, Control Point, kelso
517	PDX	26	PTI	19	PTI	11	EDM-SEA	BN	Wait for station track 7, Control Point, North Portal
59	NOL	118	FTI	163	FTI	157	GWD-YAZ	CC	CN5724 CN5724, Siding, GWIN
332	CHI	12	ENG	7	ENG	7	MKE-MKA	CP	PTC - On Board Cab Signal or PTC Failure 518
338	CHI	11	PTI	9	PTI	5	GLN-XWA	ME	Follow AMTK8, Control Point, Mayfair
573	LAX	22	PTI	26	PTI	19	OSD-X98	SN	Meet 770, Control Point, songs
595	LAX	17	DCS	13	CTI	10	OLT-SOL	SN	Blocked from station track Elevator out of service Solana Beach Single track in use, Coaster, Control Point, Crosby
761	SLO	22	PTI	36	PTI	23	CML-OXN	UP	Meet 770, Control Point, co 313
779	SLO	No OS Rpt	CTI	19	CTI	10	NRG-CWT	SC	Meet Ran through the siding up to Topanga then shoved back into the chatsworth station, scrra, Other, cwt
710	BFD	65	TCC	67	TCC	67	OKJ-OKJ	UP	HEP C6962
712	BFD	16	PTI	33	PTI	12	RIC-MTZ	UP	Meet amtrak733, Control Point, costa

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/27/2025

26-FOI-00217 00000005562 "UNCLASSIFIED" 1/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
715	OKJ	19	POL	16	POL	16	WAC-WAC	BN	Removal of passenger by police
719	OKJ	17	ITI	18	ITI	18	BFD-BFD	BN	Service, turn, or wye train 710
311	KCY	56	FTI	67	FTI	67	WAR-LEE	UP	Follow UP 6549, Siding, pleasant hill, Siding, lees summit
1333	MSP	44	DCS	48	DCS	48	WIN-RDW	CP	Power switch failure Other, Red Wing

Amtrak Initial Terminal Details

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/27/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	72	12/27	4	4	Mobility Impaired Two pax with power wheel chairs and four other pax needing assistance with lift
CLT	78	12/27	3	3	Service, turn, or wye train 77, Late inbound train #Amtk77
CLT	80	12/27	28	28	Air / Brake There was no air flow through the train line. Mechanicals determination was the cab signal box needed to be cut out in order for complete air flow throughout the train line, 306
HAR	666	12/27	1		
HAR	670	12/27	2	2	PTC - Stop Bypass Permission Required, Control Point, ., E/648
LOR	53	12/27	5	5	Broke bridge plate on carrier delayed vehicle loading 9225
PHL	144	12/27	6	6	High passenger count, per dspr 621a
PHL	150	12/27	18	18	Lost time - N.A.R., Late release from yard.
PHL	151	12/27	1		
PHL	611	12/27	1		
RGH	77	12/27	48	48	Took over Late arrival train #Amtk72 equipment. 72, Late arrival train #Amtk72.
RNK	66	12/27	119		
WAS	146	12/27	21	21	Wait for scheduled departure time
WAS	2218	12/27	6	6	Other electrical failure, 2021, TRAIN NEEDED TO WYE DUE TO POWER 2021 COULD NOT GET POWER, TO USE 2024.
ALB	238	12/27	32	32	Late from shop Late from shop.
ALB	240	12/27	25	25	Late release from shop
BOS	65	12/27	16	16	Ice / snow on or under equipment, Other, BOS, departed late due to wire down track 1 MP 222.11 - 225.37
BOS	87	12/27	6	6	Mobility Impaired, late psgr boarding
BOS	99	12/27	3	3	Door, 82669, door issues on car no. 82669
BOS	135	12/27	238	242	Service, turn, or wye train, 150, late turn of AM150
BOS	161	12/27	10	10	Planned set out / pick out of locomotives, cars or section of train, Shopped 3 coaches / late release from yard
BOS	163	12/27	15	15	Door, All, Late release from the Yard/released late from mechanical due to weather related issues. All doors were frozen shut.
BOS	165	12/27	157	157	Service, turn, or wye train, 160, late turn of AM160
BOS	167	12/27	132	132	Service, turn, or wye train, 162, late turn of AM162
BOS	169	12/27	19	19	Ice / snow on or under equipment, Other, BOS, departed late due to wire down track 1 MP 222.11 - 225.37
BOS	2253	12/27	53	53	Service, turn, or wye train, 2255, Late turn

Amtrak Initial Terminal Details

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/27/2025

Terminal	Train	Date	Late	Delay	Cause
BOS	2255	12/27	256	256	Service, turn, or wye train, 2248, late turn of AM2248
MTR	68	12/27	99	99	Slip axle alarm, 115
NFL	64	12/27	49	49	Routine inspections All initial terminal inspections at Niagara maintenance facilities, shoved into station and loaded pax., Siding, Amtrak Siding
NHV	450	12/27	50	50	Follow, 150, Milepost, nhv, nhv, Late train AM150
NHV	460	12/27	11	11	Meet, ctrail, 6403, Milepost, x1h, x1h
NHV	464	12/27	13	12	Hold for connecting train
NYP	19	12/27	8	9	Trespasser strike, Other, NYP-NYP, HELD A/C TRESPASSER STRIKE AT MP67.2158
NYP	63	12/27	12	12	Hold for connecting train, HELD FOR PSGRS OFF LATE AM150
NYP	97	12/27	27	27	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	101	12/27	2	2	Passenger and/or baggage, STILL BOARDING AT DEPARTURE TIME
NYP	107	12/27	2	2	Passenger and/or baggage
NYP	155	12/27	2	2	Passenger and/or baggage, STILL BOARDING AT DEPARTURE TIME
NYP	235	12/27	58	58	Service, turn, or wye train, 238
NYP	241	12/27	3	3	Passenger and/or baggage
NYP	283	12/27	55	55	Disabled train ahead, Other, NYP-NYP, LATE TURN OFF DISABLED AM281 FROM SSYD
NYP	291	12/27	15	15	Service, turn, or wye train, 240
NYP	665	12/27	44	44	Trespasser strike, Other, NYP-NYP, HELD A/C TRESPASSER STRIKE AT MP67.2158
KCY	318	12/27	2	2	Mobility Impaired 12 meet and assist 3 passengers requested the lift
SEA	505	12/27	33	33	Equipment swap from Talgo to Amfleet. Oversold consist
BFD	703	12/27	1		
BFD	719	12/27	18	18	Service, turn, or wye train 710
GTA	770	12/27	59	59	Air / Brake / Wheel 6402, 6907, Issues with main res hose on both cars
OKJ	710	12/27	68	67	HEP C6962
OKJ	710	12/27	68	1	Door C6962, C8813, C8016, C8008, C8004, Unable to get door light
OKJ	716	12/27	2	2	Ticket agent from OKJ walked out passengers during our departure causing a delay informed Oakland operations Nick
SAC	704	12/27	2	2	Restrictive signal(s) from unknown cause Red/stop, Control Point, sacramento

Amtrak Initial Terminal Details

26-FOI-00217 00000005562 "UNCLASSIFIED" 1/5/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 12/27/2025

Terminal	Train	Date	Late	Delay	Cause
SAC	741	12/27	10	10	Hold for thruway bus Bus from RNO 10 minute hold per Oakland Ops
SAC	751	12/27	31	31	Hold for thruway bus Hold for S.Tahoe bus #3647 per RFE Herndobler
SAN	581	12/27	1		
SAN	785	12/27	1		

Eastern Region

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	87.1	92.8	93.8	194	25
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 165(27) - Philadelphia, PA - Daily Inspection/Servicing

28DEC25: Train 165(27) was delayed at 30th Street Station/MP 1.4 in Philadelphia on the PW Line due to holding for mechanical personnel to conduct the daily inspection of the engine.

All passengers were transferred to Train 167(27) for southbound travel to Washington, DC.

Train	Delay	Comment
167(27)	09"	
165(27)	1'45"	

Train 140(27) - Blue Hills, CT/Windsor Station - Engine Failure

27DEC25: Train 140(27) was delayed at Windsor Station/MP 43.3 on the Amtrak MRS Line due to E/145 losing main reservoir pressure. The crew consulted with CNOC Mechanical and the Road Foreman, to resolve the issue.

Train	Delay	Comment
140(27)	1'02"	

Train 488(27) - Blue Hills, CT/Windsor Station - Engine Failure

27DEC25: Train 488(27) lost traction power when it arrived at Windsor Station/MP 43.3 on the Amtrak MRS Line. The crew consulted with CNOC Mechanical and Mechanical personnel arriving from Springfield. The issue was not resolved. All passengers were transferred to CDOT 6410.

Train 488(27) was terminated at Windsor Station (WND). Springfield dispatched E/111 to rescue the 488(27) equipment and tow it into SPG.

Due to the failure of E/123, Train 400(28) was cancelled in its entirety, with no alternate transportation and Train 461(28) was cancelled Greenfield to Springfield, with alternate transportation for passengers traveling between GFD and SPG.

Train	Delay	Comment
488(27)	Term WND	
499(27)	Cancelled	
400(28)	Cancelled	
461(28)	Orig SPG	

27DEC25: At approximately 12:30 PM ET, a catenary wire was reported down on Track No. 1 at Catenary Pole 225.37 on the Amtrak New Haven-Boston Line. Train 2253 (27) operating with train set 14, PC2015, PC2010, was stopped on Track No. 1 at MP 222.11 with reports of the catenary wire on top of the equipment and no Head End Power (HEP). There were 168 customers onboard, and the outside temperature was 23°F. Northeast Division Transportation Management and Mechanical teams responded, while IMCS personnel were near the scene preparing for ICE Patrol. The wire was also reported fouling Tracks No. 2 and No. 3. Engine 119 was being readied in Boston, MA for dispatch to rescue Train 2253 (27). At approximately 2:20 PM ET, Track No. 2 between Forest and Cove Interlockings was returned to service with a 30 MPH speed restriction after the overhead catenary was cleared. At approximately 2:50 PM ET, a train-to-train transfer began, moving customers from Train 2253 (27) to Train 150 (27), with Transportation Management on-site to assist. The transfer was completed at 3:20 PM ET. Due to this, Train 2253 (27) Terminated West of Cove Interlocking. Cancelled Boston, MA to Washington, DC. Train 160 (27) all customers boarded MBTA Trains at Providence, RI. Equipment continued to Boston, MA

Train	Delay	Comment
2253(27)	Term MP 225	Pax transferred to 150(27)
163(27)	15"	
150(27)	2"37"	
162(27)	59"	
160(27)	Term at PVD	
2248(27)	09"	
135(27)	4'18"	
165(17)	3'04"	
2255(27)	29"	
164(27)	57"	
167(27)	2'51"	
2252(27)	29"	
65(27)	19"	
169(27)	1'03"	
82(27)	34"	
2254(27)	28"	
MT5839	28"	
MT5739	42"	
MT5846	19"	

NYP Line West of Trenton, NJ - SE1716 Trespasser Strike

27DEC25: at approximately 12:30PM ET, CETC reported a possible trespasser strike of SE1716 at MP68.3. This was later confirmed as a fatal trespasser strike, and police placed a hold on all tracks between Grundy and Holmes. All train traffic were held at Philadelphia, and New York stations for further disposition. At At 1:44PM-ET tracks No.1 and No.2 were released for train traffic, and service resumed. At 2:45PM-ET, all emergency personnel were clear of the tracks, and tracks were returned to normal speed and service.

Train	Delay	Comment
2251(27)	1'03"	
2252(27)	22"	
666(27)	27"	
147(27)	43"	
140(27)	12"	
99(27)	10"	
88(27)	34"	
82(27)	32"	
19(27)	09"	
665(27)	44"	

Train 68(27) Montreal, QC - Engine Failure

27DEC25: Train 68(27) 26-FOI-00217 00000005562 MP73."UNCLASSIFIED" 1 QG/5/2026 terminated on the CN St. Hyacinthe subdivision due to a slip axle alarm on E/115. Mechanical responded adjusting the setting of the pressure and cleared the alarm. Train 68(27) departed Montreal QC station at 1247PM ET.

Train	Delay	Comment
68(27)	1'39"	

Train 290(27) Fort Edward-Glens Falls, NY - Signal

27DEC25: Train 290(27) was delayed beginning at MP56.1, 2.4 miles east of Fort Edward-Glens Falls NY station on the CPKC Canadian subdivision due to frozen switched. Crew on train 290(27) had to handline switched into Fort Edward Glens Falls NY station.

Train	Delay	Comment
290(27)	46"	

Train 19(26) South of Atlanta, GA - Freight Train Interference

27DEC25: Train 19(26) was delayed 1.5 miles south of Atlanta, GA at MP6335 on the NSRR Norcross Subdivision, due to freight congestion and a M583-26 blocking the interchange.

Train	Delay	Comment
19(26)	37"	

Train 151(27) South of Alexandria, VA - Engine Failure

27DEC25: Train 151(27) E/39, E/150 5 cars, with 154 passengers onboard, was delayed just south of Alexandria, VA at MP11.8 on the NSRR Alexandria-Montview Subdivision due to a PTC fault on trail engine E/150. Train maintained head-end power (HEP) the entire stop. Crew worked with CNOC mechanical and a General Foreman to troubleshoot. After attempts to recycle and reset fault failed, crew received permission from the host railroad to operate with PTC cut out, and were able to proceed south.

Train	Delay	Comment
151(27)	2'14"	
66(27)	1'59"	ITD -Equip Turn off 151

Train 63(26)/64(27) Niagara Falls, CN - Servicing

27DEC25: Train 63(26) operating with engine 105, 110, and 5 cars was terminated at Niagara Fall, CN due to ongoing issues from prior in the day involving the CN Seaway St. Lawrence Bridge which was unresolved coupled with VIA Rail manpower issues to operate Amtrak equipment to Toronto on hours of service. Train 64(27) originated Niagara Falls, NY late after the equipment was wye'd on the Canadian side and brought over for Niagara Falls, NY mechanical to perform daily inspection and servicing of equipment.

Train	Delay	Comment
63(26)	TERM NFS	
64(27)	ORIG NFL	
64(27)	49"	Late DP NFL

Eastern Region

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 794(27) South of Lompoc-Surf, CA - Engine Failure

27DEC25: Train 794(27) was delayed south of Lompoc-Surf, CA (LPS) at MP 332.0 on the Union Pacific Railway Santa Barbara Subdivision. Locomotive CDTX/2110 stopped providing tractive effort; Head End Power was NOT affected. The train crew was unable to make or receive phone calls account poor phone reception in the area and worked to troubleshoot the issue. The crew was able to partially resolve the problem and advanced train to CP Gaviota where they were able to make a phone call to Amtrak Mechanical Forces and further troubleshoot the issue.....

TRAIN 779(27) coupled-up with disabled 794(27) and towed back to Santa Barbara, CA where passengers on the disable 794(27) were provided alternate transportation to their destinations. Train 779/794(27) operated as a double set to Los Angeles were that equipment died. Train 587(27) equipment was utilized as on-time section from Los Angeles, CA to San Diego, CA.

Due to the equipment manipulation, Train 774(28) is cancelled from San Luis Obispo , CA to Los Angeles, CA, there will be an on-time section from Los Angeles, CA to San Diego, CA. Passengers San Luis Obispo, CA to Santa Barbara, CA will be protected by 3 buses where they connected with Train 784(28). Passengers Santa Barbara, CA to Los Angeles protected on Train 784(28) .

WBS#: B.TR.100150.6348

Train	Delay	Comment
794(27)		TERM LPS

Train 11(26) San Luis Obispo, CA - Signal

27DEC25: Train 11(26) was delayed south of San Luis Obispo, CA (SLO) at CP Honda on the Union Pacific Railway Santa Barbara Subdivision. There was a problem with the signal system between CP Honda and CP Sudden and dual control main track switch at CP Sudden. The train crew was required to operate at reduced speeds on verbal authority from the train dispatcher and manually operate the dual control switch at CP Sudden. Once clear of the affected area, the crew was able to resume operation at maximum authorised track speeds.

Train	Delay	Comment
11(26)	36"	

Train 1(27) Houston, TX - Police Related

27DEC25: Train 1(27) was delayed at Richmond, TX, MP 33 on UPRR Coast Subdivision due to the removal of a disruptive passengers. Local Richmond Texas Police reported to the scene, but did not want to physically remove the passenger from the train. The conductor reached out to Amtrak Police so they could talk with them to request their assistance. Eventually the passenger was removed and Train 1(27) continued west.

Train	Delay	Comment
1(27)	1'10"	

Train 319(26) East of Kansas City, MO - Freight Train Interference

27DEC25: Train 319(26) was delayed approximately 36 miles east of Kansas City, MO, at milepost 1.4, on KCT' KCT Terminal subdivision, due to KCS4831 crossing in front. Once the freight cleared and a route was made available, train 319(26) was able to proceed.

Train	Delay	Comment
319(26)	36"	

Train 1333(27) East of Red Wing, MN - Signal

27DEC25: Train 1333(27) operating with E/4, 3 cars, E/518 and 199 passengers onboard was delayed approximately 3 miles east of Red Wing, MN Station on CPKC River Subdivision due to park track needing to be clamped.

Train	Delay	Comment
1333(27)	48"	

Train 27(25) West of Vancouver, WA - Freight Train Interference

27DEC25: Train 27(25) was delayed west of Vancouver, WA at MP 8.7 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. Train 27(25) was held at MP 8.7 for a freight train, UP/5272, followed by train 504(27) to clear the track ahead. Once the track ahead was clear, train 27(25) was able to proceed west.

Train	Delay	Comment
504(25)	23"	Follow UP/5272
27(25)	40"	

Train 4(25) Kansas City, MO - System

27DEC25: Train 4(25) was delayed at MP6.85 Kansas City MO station due to a crew signing up on rest at 700am CT. Crew signed up and completed briefing. Train 4(25) departed Kansas City MO station at 717AM CT.

Train	Delay	Comment
4(25)	33"	

Train 3(26) East of Lamy, NM - Passenger Train Interference

27DEC25: Train 3(26) was delayed at MP794.0, 42.10 miles east of Lamy, NM station on the BNSF Glorieta subdivision holding in the Blanchard siding for a meet with train 4(26). Once train 4(26) was east of 3(26), they were able to proceed west towards Lamy NM station.

Train 5(27) Chicago, IL - Car Failure

27DEC25: Train 5(27) was delayed at MP0.5 Chicago IL station on the CN Chicago subdivision due to toilets inoperable on car 32067. Mechanical responded and were able to fix the bathrooms on car 32067. Train 5(27) was on the move at 244PM CT.

Train	Delay	Comment
5(27)	42"	

Train 8/28(26) East of Havre, MT - Freight Train Interference

27DEC25: Train 8/28(26) was delayed at MP74.48, 10.6 miles west of Havre, MT station on the BNSF HI Line subdivision due to BNSF 7360 stopped ahead with air issues. BNSF 7360 crew was met by mechanical and master or trains to troubleshoot. Mechanical cycled the circuit breakers and were able to bring the engine back online. BNSF freight 7360 proceeded west at a restricted speed of 20 MPH. Train 8/28(26) was on the move east after the freight cleared west.

Train	Delay	Comment
8/28(26)	1'59"	SBY - HAV

Train 311(27) East of Lees Summit, MO - Freight Train Interference

27DEC25: Train 311(27) was delayed at MP249.8, 10.6 miles east of Lees Summit, MO station on the UPRR Sedalia subdivision due to UPRR freight 6549 stopped ahead with air issues. Freight crews walked the train and were able to resolve the issue. Once UPRR freight 6549 cleared a route, 311(27) was able to proceed west into Lee's Summit MO station.

Train	Delay	Comment
311(27)	1'07"	

Train 505/518(27) Seattle, WA - Miscellaneous Amtrak Responsible

27DEC25: Train 505(27) was delayed departing the initial terminal of Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. There was an equipment change which resulted in train 505(27) being over capacity. Train 505(27) was delayed while supplemental buses were secured and overflow passengers accommodated; departing SEA at 9:28 AM-PT. Supplemental buses were also secured to accommodate overflow passengers on the equipment turn of train 518(27).

WBS#: B.TR.100150.6347

Train	Delay	Comment
505(27)	33"	

Train 710(27) Oakland, CA - Third Party Contractor Cab Car Failure

27DEC25: Train 710(27) was delayed departing the initial terminal of Oakland, CA (OKJ) on the Union Pacific Railway Niles Subdivision. There was an issue with the Head End Power System (HEP) on cab car CC/6962; HEP is required for the cab car control stand to function. This only affected the bi-level cab car - which was not being used in revenue service as it is not compatible with the single level venture equipment - HEP was working on the rest of the train. Technicians from the Mechanical Contractor, TASI, responded and were able to resolve the HEP Issue. Once the issue was resolved, train 710(27) was able to depart OKJ at 9:02 AM-PT.

Train	Delay	Comment
710(27)	1'07"	
719(27)	18"	ITD - BFD - Late turn inbound 710

Train 59(26) North of Yazoo City, MS - Freight Train Interference

27DEC25: Train 59(26) 28-FOI-00247a 00000005562 MP140.7 UNCLASSIFIED 1/5/2026 9 miles north of Yazoo City MS station on the CN Yazoo subdivision due to CN freight 5724 ahead setting off a hot bearing detector. Crew from CN 5724 walked train to inspect consist and found the car. Freight CN 5724 proceeded south to the siding to set out the car at reduced speed. Once in the siding to set out the car, 59(26) was able to continue south towards Yazoo City station.

Train	Delay	Comment
59(26)	2'37"	

Train 5(25) East of Reno, NV - Freight Train Interference

27DEC25: Train 5(25) was delayed beginning at MP276.8, 40.49 miles east of Reno, NV. on the UPRR Nevada subdivision meeting multiple freight trains. UPRR freight 6704 stopped ahead with a breaker issue. Crew worked to resolve the issue, and was able to clear a route for train 5(25). Train 5(25) proceeded west towards Reno and was further delayed following UPRR freight 7363. UPRR freight 7363 pulled into a siding and 5(25) was able to get around them. Train 5(25) held in the Clark Siding at MP262.4 meeting BNSF 6162. Train 5(25) proceeded west out of the siding when BNSF 6162 cleared to the east.

Train	Delay	Comment
5(25)	52"	

Train 770(27) Goleta, CA - Car Failure

27DEC25: Train 770(27) was delayed departing the initial terminal of Goleta, CA (GTA) on the Union Pacific Railway Santa Barbara Subdivision. There was a problem with the compressed air system on cars C/6402 and C/6907. The train crew was able to resolve the issue and train 770(27) departed GTA at 7:38 AM-PT. To maintain on-time performance, an "on-time" section of train 770(27) was operated from LAX to SAN with 572(27) equipment. Inbound 770(27) GTA-LAX equipment was used to represent train 572(27) LAX to SAN.

Train	Delay	Comment
770(27)	59"	ITD - GTA
770(27)	no delay	"on-time" section LAX-SAN

Train 8/28(25) West of Red Wing, MN - Freight Train Interference

27DEC25: Train 8/28(25) was delayed at MP409.6, 23.10 miles east of Red Wing, MN Station on the CPKC Merriam Park subdivision due to UPRR yard train stopped with air issues. Yard train was able to resolve the air issues and move to create a route for 8/28(25).

Train	Delay	Comment
8/28(25)	28"	

Train 518(26) West of Vancouver, BC - Freight Train Interference

27DEC25: Train 518(26) was delayed 5 miles east of Vancouver, BC, at milepost 151.4, on CN New Westminster subdivision, due to a freight train obstructing the route. The conductor reported a shortage of manpower that caused the freight train to occupy the main track. Once a crew arrived, they were able to move the freight, which cleared a route for train 518(26).

Train	Delay	Comment
518(26)	2'02"	

Train 716(26) East of Madera, CA - Debris

26DEC25 Train 716(26) 26-FOI-00247 00000005582 yed "UNCLASSIFIED" Made 15/2026 CA (MDR) at MP 1007.5 on the Burlington Northern Santa Fe Railway Stockton Subdivision. Train 716(26) struck debris on the track which resulted in the separation of air hoses between cars. There were no reports of injuries to passengers or crew. Once the crew connected the air hoses, train 716(26) was able to resume operation at 6:55 PM-PT.

Train	Delay	Comment
716(26)	24"	
719(26)	27"	Hold for 716(26) to connect air hose and clear track ahead.

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

-715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.

-718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

-714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.

-718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.

-716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

-714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).

-713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

-520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).

-535(24) Cancelled. Turn of equipment from cancelled train 520(24).

-534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

-Train 736(25-28) Cancelled - No alternate transportation.

-Train 737(25-28) Cancelled - No alternate transportation.

29DEC25

-Train 520(29) Cancelled - No alternate transportation.

-Train 534(29) Cancelled - No alternate transportation.

-Train 535(29) Cancelled - No alternate transportation.

-Train 551(29) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718(21)	Originate EMY	Passengers to 744(21) OKJ-EMY
718(22)	Originate EMY	Passengers to 544(22) OKJ-EMY
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
714(23)	.	CANCELLED
713(24)	.	CANCELLED
535(24)	Cancelled	
520(24)	Cancelled	
534(24)	Cancelled	
736(25-28)	Cancelled	
737(25-28)	Cancelled	
551(29)	Cancelled	Replacement Bus SAC-OKJ
520(29)	Cancelled	No alternate transportation.
534(29)	Cancelled	No alternate transportation.
535(29)	Cancelled	No alternate transportation.

Western Region

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Bus 5415(27) Passenger Removal at La Crescenta, California – Medical

27DEC25, Passenger on PNR 39CB53, traveling from Riverside, CA to Bakersfield, CA was removed from the train by local Paramedics for exhibiting a medical emergency. Bus driver administered CPR until the medics arrived. Amtrak Police notified.

Delay: 5415 (27) None

Train 4(26) Passenger Removal at Albuquerque, New Mexico –Fare Evader

27DEC25, Passenger on PNR Unknown, traveling from Albuquerque, NM to Lamy, NM was removed from the train by station security for fare evading. Amtrak Police notified.

Delay: 4 (26) 02"

Train 5(27) Passenger Removal at Princeton, Illinois – Medical

27DEC25, Passenger on PNR C7AAA5, traveling from Chicago, IL to Emeryville, CA was removed by EMS at Princeton, IL due to having an allergic reaction to something he ate. Amtrak Police notified.

Delay: 5 (27) 10"

Train 713(27) Passenger Removal at Martinez, California – Medical

26-FOI-00217 00000005562 "UNCLASSIFIED" 1/5/2026

27DEC25, Passenger on PNR 257203, traveling from Hanford, CA to Martinez, CA fell while detraining at Martinez, CA onto the platform. He had abrasions to his hands and elbows, and they couldn't move him due to severe pain in his legs, knees and hips. The station agent called 911 and he was taken to a local hospital. Amtrak Police notified.

Delay: 713(27) 06"

Train 49(26) Passenger Removal at Toledo, Ohio – Improper Conduct

27DEC25, Passengers on PNR 3064CD, traveling from Buffalo-Depew, NY to Chicago, IL were removed from the train by the conductor for causing a disturbance. The passenger began using profanity when asked to sit up and not take up more than one seat. Amtrak Police notified.

Delay: 49(26) None

Train 49(26) Passenger Incident at Elkhart, Indiana – Baggage

27DEC25, Passengers on PNR B00826, traveling from Elkhart, IN to Chicago, IL were forced to repack luggage due to carryon being over the weight limit per baggage policy. Amtrak Police notified.

Delay: 49(26) 02"

Train 49(26) Passenger Incident at Elkhart, Indiana – Baggage

27DEC25, Passengers on PNR 540DA5, traveling from Elkhart, IN to Chicago, IL were forced to repack luggage due to carryon being over the weight limit per baggage policy. Amtrak Police notified.

Delay: 49(26) 02"

Consist Deviations

26-FOI-00217

00000005562

"UNCLASSIFIED"

1/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2251 (26)	BOS	NEXT GEN Acela in lieu of Legacy Acela equipment	Pax advised	0	2116
161 (27)	BOS	DUE SHOPPED EQUIPMENT IN BOS 161 IS OPERATING 2 CARS SHORT AND IS OVER CAPACITY BY 1 CAR			
161 (27)	BOS	WILL OPERATE 3 CARS SHORT DUE SHOPPED EQUIPMENT IN BOS / CAPS SET TO 360	WILL OPERATE 3 CARS SHORT DUE SHOPPED EQUIPMENT IN BOS / CAPS SET TO 360	42	
2255 (28)	BOS	TRAIN WILL NOW OPERATE NEXT GEN EQUIPMENT / SCHEDULE CHANGE, DCA UPDATE COMPLETED	N/A	0	
2275 (27)	BOS	TRAIN WILL NOW OPERATE NEXT GEN EQUIPMENT / SCHEDULE CHANGE COMPLETED	N/A	0	
48 (28)	CHI	4812 car on 48(*28*) is using a VII in lieu of a VI. Schedule change performed. Please work war report.	4812 car on 48(*28*) is using a VII in lieu of a VI.	1	625234
6 (28)	EMY	Utilizing T-Dorm w/o H room, schedule change has been performed.	N/A	0	39005
4 (26)	LAX	coach in lieu of bag coach	No impact	0	34050
14 (27)	LAX	Operating with Standard coach in lieu of baggage coach. Bags to H/E to baggage car.	N/A	0	34027
3 (27)	LAX	Operating with T-Dorm w/o H room.	N/A	0	39009
4 (29)	LAX	Operating with T-Dorm w/o H room.	N/A	0	39009
194 (27)	NPN	All 6 coaches operating revenue service NPN-BOS per TM Richardson			
49 (27)	NYP	Viewliner II in lieu of Viewliner I sleeper (4912)	Pax downgraded	3	62523
97 (27)	NYP	Viewliner II in lieu of	Pax downgraded	6	62519

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		Viewliner I (9710)			
97 (27)	NYP	Viewliner II in lieu of Viewliner I sleeper. (9711)	Pax downgraded	6	62501
2290 (28)	NYP	TRAIN WILL NOW OPERATE NEXT GEN EQUIPMENT / SCHEDULE CHANGE, DCA UPDATE COMPLETED	N/A	0	
518 (27)	PDX	Will not be operating with talgo set. Equipment change in SEA outbound 505(27) currently capacity in coach and business class will need to reaccommodate passengers.			186 8255 82615 48193 90252
156 (27)	RNK	All 6 coaches operating revenue service RNK-BOS per TM Richardson			
505 (27)	SEA	Will not be operating with talgo set. Equipment change currently capacity in coach will need to reaccommodate passengers.			90252 48193 82615 82555 186
516 (27)	SEA	Due to equipment swap coach is currently over capacity between stw-bel by 2.			WS1401 82507 82666 48169 61032 WS1403
2248 (26)	WAS	NEXT GEN Acela in lieu of Legacy Acela equipment	Px advised	0	2121
2250 (26)	WAS	NEXT GEN Acela in lieu of Legacy Acela equipment	Pax advised	0	2122
2226 (28)	WAS	TRAIN WILL NOW OPERATE NEXT GEN EQUIPMENT / SCHEDULE CHANGE, DCA UPDATE COMPLETED	N/A	0	

Reverse Consists

Train Number	Station	Reason
87 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
99 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
161 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00217	00000005562 "UNCLASSIFIED" 1/5/2026
101 (27)	NYP	Consist reversed Business class seat orientation may have changed At Front	
150 (27)	PHL	Consist reversed Business class seat orientation may have changed At Front	
96 (28)	NPN	Consist reversed Business class seat orientation may have changed At Front	
88 (28)	NFK	Consist reversed Business class seat orientation may have changed At Front	
135 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front	
142 (27)	WAS	Consist reversed Business class seat orientation may have changed At Front	
2218 (27)	WAS	Acela consist reversed First class at Front	