



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, September 04, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-007Initial Terminal Performance By Division

Scheduled Departure Date:	09/03/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/03/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	31	90.5%	982	152	84.5%	101,504	14,120	86.1%
Central Division	86.0%	59	4	93.2%	176	19	89.2%	19,371	1,794	90.7%
East Division	82.0%	178	15	91.6%	531	66	87.6%	53,351	8,200	84.6%
West Division	86.0%	90	12	86.7%	275	67	75.6%	28,782	4,126	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008774 UNCLASSIFIED 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	100,101	27,899	72%	272,883	71,125	74%	33,870,017	8,658,395	74%
Northeast Corridor	81%	46,408	10,051	78%	123,971	23,179	81%	14,842,386	3,610,967	76%
Acela	83%	11,609	1,253	89%	31,228	3,694	88%	2,994,138	762,915	75%
Northeast Regional	79%	34,799	8,798	75%	92,743	19,485	79%	11,848,248	2,848,052	76%
Richmond / Newport News / Norfolk	77%	9,401	5,574	41%	24,313	9,840	60%	3,547,939	1,057,245	70%
Springfield Shuttles	89%	866	182	79%	2,090	328	84%	209,320	33,564	84%
Roanoke	79%	3,098	997	68%	9,381	2,291	76%	1,123,538	252,111	78%
On Spine Northeast Regional	80%	21,434	2,045	90%	56,959	7,026	88%	6,967,451	1,505,132	78%
State Supported	80%	43,458	10,158	77%	119,652	31,911	73%	14,908,589	3,243,004	78%
Borealis	80%	613	0	100%	1,709	158	91%	189,728	40,635	79%
Capitol Corridor	90%	3,880	569	85%	12,241	1,576	87%	1,244,366	165,964	87%
Carolinian	70%	472	321	32%	2,093	1,031	51%	379,478	149,150	61%
Cascades	75%	2,450	1,082	56%	6,642	2,642	60%	859,242	243,667	72%
Downeaster	82%	1,474	0	100%	4,285	0	100%	524,437	61,834	88%
Empire	78%	6,129	1,753	71%	16,915	5,044	70%	1,859,419	460,325	75%
Adirondack	72%	429	112	74%	1,049	491	53%	115,069	37,444	67%
Ethan Allen Express	70%	548	389	29%	1,598	449	72%	188,549	72,673	61%
Maple Leaf	70%	874	534	39%	2,411	1,174	51%	231,299	91,397	60%
New York - Albany	85%	2,725	363	87%	7,703	1,531	80%	857,136	150,087	82%
New York - Niagara Falls	75%	1,553	355	77%	4,154	1,399	66%	454,516	101,866	78%
Berkshire Flyer	60%	0	0	-	0	0	-	12,850	6,858	47%
Gold Runner	73%	2,336	1,240	47%	5,359	3,681	31%	835,540	312,585	63%
Heartland Flyer	70%	169	83	51%	267	126	53%	71,804	30,294	58%
Hiawatha	90%	1,844	245	87%	4,922	291	94%	588,989	64,167	89%
Illinois	78%	1,977	1,083	45%	4,941	3,061	38%	833,618	235,806	72%
Carl Sandburg / Illinois Zephyr	85%	360	10	97%	814	197	76%	138,627	39,557	71%
Illini / Saluki	85%	887	682	23%	1,700	1,135	33%	287,825	72,654	75%
Lincoln Service	70%	730	391	46%	2,427	1,729	29%	407,166	123,595	70%
Keystone	92%	9,599	510	95%	25,682	4,399	83%	2,552,290	262,160	90%
Lincoln / Missouri	70%	567	564	1%	1,306	1,301	0%	258,943	136,753	47%
Mardi Gras Service	80%	179	45	75%	576	74	87%	133,675	29,791	78%
Michigan	70%	2,029	620	69%	5,106	2,046	60%	678,411	227,586	66%
Blue Water	70%	450	448	0%	974	470	52%	159,645	65,637	59%
Pere Marquette	85%	323	0	100%	782	129	84%	87,301	16,487	81%
Wolverine	70%	1,256	172	86%	3,350	1,447	57%	431,465	145,462	66%
Missouri	80%	147	138	6%	381	351	8%	73,770	21,600	71%
Pacific Surfliner	85%	7,262	1,069	85%	20,261	4,081	80%	2,728,706	519,880	81%
Pennsylvanian	80%	456	40	91%	1,853	235	87%	294,609	56,106	81%
Piedmont	80%	583	207	64%	1,370	208	85%	372,155	94,828	75%
Vermont	75%	1,292	589	54%	3,743	1,606	57%	429,409	129,873	70%
Long Distance	70%	10,235	7,690	25%	29,260	16,035	45%	4,079,775	1,801,961	56%
Auto Train	70%	632	632	0%	1,917	632	67%	262,080	89,388	66%
California Zephyr	70%	771	742	4%	2,433	1,473	39%	323,565	127,467	61%
Cardinal	70%	495	397	20%	495	397	20%	77,577	39,697	49%
City Of New Orleans	75%	626	327	48%	1,572	1,251	20%	210,973	73,491	65%
Coast Starlight	70%	1,051	199	81%	3,016	784	74%	380,189	135,482	64%
Crescent	70%	780	516	34%	2,002	779	61%	307,070	95,133	69%
Empire Builder	70%	575	216	62%	2,625	389	85%	323,776	161,974	50%
Floridian	60%	1,173	896	24%	3,775	2,549	32%	523,841	362,698	31%
Lake Shore Ltd	73%	897	746	17%	2,675	1,017	62%	325,363	99,147	70%
Palmetto	70%	306	219	28%	1,554	959	38%	304,724	95,737	69%
Silver Meteor	70%	1,008	931	8%	2,005	1,702	15%	336,507	157,162	53%
Southwest Chief	60%	811	793	2%	2,366	1,720	27%	279,750	185,425	34%
Sunset Ltd	70%	0	0	-	203	43	79%	95,981	38,561	60%
Texas Eagle	70%	1,110	1,076	3%	2,622	2,340	11%	328,379	140,599	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000774 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 03, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	20,112	337,067	597	2,019,587	35,611,234	567

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	939	106,802	88	97,384	10,314,237	94
INFRASTRUCTURE PLANNED	135	1,786	106,802	167	117,322	10,314,237	114
FLEET RELIABILITY	90	3,232	337,067	96	322,973	35,611,234	91
TRAIN OPERATIONS	424	14,155	337,067	420	1,481,908	35,611,234	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

26-FOI-007Initial Terminal Performance By Division

Scheduled Departure Date:	09/03/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/03/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	31	90.5%	982	152	84.5%	101,504	14,120	86.1%
Central Division	86.0%	59	4	93.2%	176	19	89.2%	19,371	1,794	90.7%
East Division	82.0%	178	15	91.6%	531	66	87.6%	53,351	8,200	84.6%
West Division	86.0%	90	12	86.7%	275	67	75.6%	28,782	4,126	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-007100-000000

Scheduled Departure Date:	09/03/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/03/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	31	90.5%	982	152	84.5%	101,504	14,120	86.1%
Central Division	86.0%	59	4	93.2%	176	19	89.2%	19,371	1,794	90.7%
CDL	95.0%	2	0	100.0%	6	1	83.3%	642	32	95.0%
CHI	86.0%	28	3	89.3%	83	10	88.0%	8,953	1,110	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	3	1	66.7%	361	39	89.2%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	3	0	100.0%	317	11	96.5%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	6	0	100.0%	654	54	91.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	18	1	94.4%	1,977	127	93.6%
MOE	97.5%	2	0	100.0%	6	1	83.3%	673	10	98.5%
MSP	96.5%	1	0	100.0%	3	0	100.0%	331	7	97.9%
NOL	94.5%	4	0	100.0%	12	0	100.0%	1,422	64	95.5%
OKC	97.0%	1	0	100.0%	2	0	100.0%	331	6	98.2%
PNT	88.0%	3	0	100.0%	9	0	100.0%	885	73	91.8%
PTH	93.0%	1	0	100.0%	3	0	100.0%	326	13	96.0%
QCY	91.0%	2	0	100.0%	6	1	83.3%	637	49	92.3%
SAS	90.5%	1	0	100.0%	3	1	66.7%	335	40	88.1%
STL	89.0%	4	0	100.0%	12	2	83.3%	1,308	108	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	178	15	91.6%	531	66	87.6%	53,351	8,200	84.6%
ALB	88.5%	8	0	100.0%	24	1	95.8%	2,508	189	92.5%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	15	0	100.0%	1,636	175	89.3%
BOS	85.5%	19	0	100.0%	56	1	98.2%	5,761	641	88.9%
BRK	92.5%	5	1	80.0%	15	1	93.3%	1,610	113	93.0%
BTN	82.0%	1	0	100.0%	3	1	66.7%	322	43	86.6%
CLT	91.5%	4	1	75.0%	12	1	91.7%	1,643	168	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	5	0	100.0%	653	60	90.8%
GRO	-	1	0	100.0%	3	1	66.7%	53	12	77.4%
HAR	79.5%	13	1	92.3%	39	7	82.1%	3,746	601	84.0%
HFD	-	2	0	100.0%	6	0	100.0%	238	19	92.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	1	0.0%	3	1	66.7%	334	41	87.7%

Information Management

Initial Terminal Performance By Terminal

26-FOI-007

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

09/03/2026

Scheduled Departure Date:	09/03/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/03/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	31	90.5%	982	152	84.5%	101,504	14,120	86.1%
East Division	82.0%	178	15	91.6%	531	66	87.6%	53,351	8,200	84.6%
MIA	89.5%	2	1	50.0%	6	2	66.7%	664	78	88.3%
MTR	79.0%	1	0	100.0%	3	0	100.0%	321	58	81.9%
NFK	84.5%	2	0	100.0%	6	1	83.3%	751	137	81.8%
NFL	93.5%	2	0	100.0%	6	1	83.3%	680	32	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	15	2	86.7%	1,717	289	83.2%
NPN	93.0%	2	0	100.0%	6	1	83.3%	640	52	91.9%
NYP	75.5%	51	3	94.1%	153	29	81.0%	14,082	3,086	78.1%
PGH	93.0%	1	0	100.0%	3	0	100.0%	335	23	93.1%
PHL	48.0%	5	2	60.0%	15	6	60.0%	1,710	805	52.9%
PIT	76.0%	-	-	-	-	-	-	24	19	20.8%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	1	50.0%	6	1	83.3%	1,270	55	95.7%
RNK	83.5%	2	0	100.0%	6	0	100.0%	664	93	86.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	3	0	100.0%	317	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	3	0	100.0%	331	12	96.4%
SFA	88.0%	1	0	100.0%	3	0	100.0%	334	47	85.9%
SPG	92.5%	5	0	100.0%	14	1	92.9%	1,976	116	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	3	0	100.0%	323	63	80.5%
WAS	84.0%	33	4	87.9%	99	8	91.9%	8,468	1,082	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	90	12	86.7%	275	67	75.6%	28,782	4,126	85.7%
ARN	92.0%	1	0	100.0%	3	0	100.0%	336	28	91.7%
BFD	79.0%	6	0	100.0%	20	7	65.0%	2,133	455	78.7%
EMY	72.0%	1	0	100.0%	3	1	66.7%	352	101	71.3%
EUG	86.5%	1	0	100.0%	5	0	100.0%	665	59	91.1%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	9	1	88.9%	1,010	173	82.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	31	5	83.9%	3,351	374	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	4	69.2%	38	20	47.4%	3,657	973	73.4%
PDX	86.0%	5	0	100.0%	15	4	73.3%	1,620	229	85.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/03/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/03/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	31	90.5%	982	152	84.5%	101,504	14,120	86.1%
West Division	86.0%	90	12	86.7%	275	67	75.6%	28,782	4,126	85.7%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	3	81.3%	48	10	79.2%	4,767	530	88.9%
SAN	90.5%	13	0	100.0%	39	4	89.7%	4,076	396	90.3%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	3	62.5%	24	8	66.7%	2,577	388	84.9%
SJC	89.0%	7	0	100.0%	21	4	81.0%	2,361	233	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	9	0	100.0%	774	77	90.1%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	3	1	66.7%	315	30	90.5%
VAC	97.0%	2	0	100.0%	6	1	83.3%	659	15	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	530	3	1	66.7%	336	67	80.1%	3	1	66.7%	333	158	52.6%
4	110	3	0	100.0%	335	53	84.2%	3	2	33.3%	335	223	33.4%
5	210	3	1	66.7%	334	58	82.6%	3	1	66.7%	330	112	66.1%
6	375	3	1	66.7%	333	92	72.4%	3	3	0.0%	333	128	61.6%
7		3	0	100.0%	325	51	84.3%	3	0	100.0%	316	86	72.8%
8	473	3	1	66.7%	325	146	55.1%	3	1	66.7%	324	199	38.6%
11		3	2	33.3%	336	74	78.0%	3	0	100.0%	330	67	79.7%
14		3	2	33.3%	337	56	83.4%	3	0	100.0%	334	105	68.6%
19		3	1	66.7%	335	84	74.9%	3	0	100.0%	332	82	75.3%
20	49	3	0	100.0%	335	23	93.1%	3	1	66.7%	335	66	80.3%
21	59	3	0	100.0%	332	36	89.2%	3	3	0.0%	331	102	69.2%
22	139	3	1	66.7%	333	38	88.6%	3	3	0.0%	331	102	69.2%
23		3	1	66.7%	337	7	97.9%	3	1	66.7%	335	91	72.8%
24	34	3	0	100.0%	337	16	95.3%	3	1	66.7%	336	66	80.4%
25		3	0	100.0%	336	3	99.1%	3	0	100.0%	333	94	71.8%
26		3	0	100.0%	336	5	98.5%	3	0	100.0%	333	66	80.2%
27		3	2	33.3%	302	21	93.0%	3	0	100.0%	296	97	67.2%
28		3	0	100.0%	296	67	77.4%	3	0	100.0%	296	60	79.7%
40	115	3	1	66.7%	326	48	85.3%	3	2	33.3%	322	174	46.0%
41	173	3	2	33.3%	326	126	61.3%	3	3	0.0%	323	250	22.6%
42		3	0	100.0%	337	25	92.6%	3	0	100.0%	335	58	82.7%
43	320	3	0	100.0%	336	45	86.6%	3	2	33.3%	335	78	76.7%
48	52	3	0	100.0%	335	62	81.5%	3	1	66.7%	334	52	84.4%
49	384	3	0	100.0%	335	84	74.9%	3	1	66.7%	335	71	78.8%
51	60	1	0	100.0%	137	58	57.7%	1	1	0.0%	133	53	60.2%
52	159	3	0	100.0%	334	47	85.9%	3	1	66.7%	333	78	76.6%
53	113	3	1	66.7%	334	41	87.7%	3	1	66.7%	333	107	67.9%
55		3	0	100.0%	214	9	95.8%	3	0	100.0%	211	46	78.2%
56	33	3	0	100.0%	215	25	88.4%	3	2	33.3%	211	42	80.1%
58	76	3	0	100.0%	310	17	94.5%	3	3	0.0%	308	100	67.5%
59		3	1	66.7%	309	52	83.2%	3	2	33.3%	304	83	72.7%
63	39	3	1	66.7%	338	145	57.1%	3	3	0.0%	332	200	39.8%
64	74	3	0	100.0%	336	71	78.9%	3	2	33.3%	335	135	59.7%
66		3	0	100.0%	335	64	80.9%	3	1	66.7%	330	61	81.5%
67		3	0	100.0%	233	14	94.0%	3	0	100.0%	232	40	82.8%
68		3	0	100.0%	338	67	80.2%	3	2	33.3%	337	136	59.6%
69	27	3	1	66.7%	325	80	75.4%	3	1	66.7%	320	57	82.2%
71		3	0	100.0%	333	3	99.1%	3	0	100.0%	331	86	74.0%
72		3	0	100.0%	329	36	89.1%	3	0	100.0%	327	69	78.9%
75		3	1	66.7%	326	18	94.5%	3	1	66.7%	320	152	52.5%
76		3	0	100.0%	326	31	90.5%	3	0	100.0%	316	130	58.9%
77	67	3	1	66.7%	328	22	93.3%	3	1	66.7%	325	134	58.8%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		3	1	66.7%	332	30	91.0%	3	0	100.0%	329	75	77.2%
79	75	3	0	100.0%	335	59	82.4%	3	3	0.0%	333	115	65.5%
80	124	3	0	100.0%	335	37	89.0%	3	1	66.7%	332	72	78.3%
84		3	0	100.0%	205	19	90.7%	3	1	66.7%	201	49	75.6%
85	18	3	0	100.0%	216	18	91.7%	3	2	33.3%	216	76	64.8%
86	37	3	0	100.0%	216	16	92.6%	3	1	66.7%	215	122	43.3%
89		3	0	100.0%	333	78	76.6%	3	2	33.3%	331	99	70.1%
90	88	3	0	100.0%	333	12	96.4%	3	1	66.7%	332	61	81.6%
93	21	3	0	100.0%	215	21	90.2%	3	2	33.3%	214	57	73.4%
94		3	0	100.0%	246	61	75.2%	3	0	100.0%	244	89	63.5%
95	178	3	0	100.0%	215	6	97.2%	3	2	33.3%	215	84	60.9%
97	113	3	2	33.3%	335	219	34.6%	3	2	33.3%	333	122	63.4%
98	60	3	1	66.7%	335	29	91.3%	3	2	33.3%	333	125	62.5%
110		3	0	100.0%	212	110	48.1%	3	0	100.0%	209	22	89.5%
111		3	0	100.0%	206	37	82.0%	3	0	100.0%	204	22	89.2%
112		3	1	66.7%	206	21	89.8%	3	0	100.0%	205	20	90.2%
113		3	0	100.0%	137	33	75.9%	3	0	100.0%	136	16	88.2%
119		3	0	100.0%	203	49	75.9%	3	0	100.0%	201	26	87.1%
125	46	3	0	100.0%	216	12	94.4%	3	1	66.7%	216	85	60.6%
129		3	1	66.7%	215	51	76.3%	3	1	66.7%	215	31	85.6%
130		3	0	100.0%	206	20	90.3%	3	0	100.0%	204	16	92.2%
131	23	3	0	100.0%	208	57	72.6%	3	1	66.7%	208	40	80.8%
134		3	0	100.0%	216	32	85.2%	3	0	100.0%	215	42	80.5%
136		3	1	66.7%	216	28	87.0%	3	2	33.3%	214	30	86.0%
137		3	0	100.0%	213	36	83.1%	3	1	66.7%	213	63	70.4%
138	131	3	1	66.7%	216	44	79.6%	3	1	66.7%	215	39	81.9%
141		3	1	66.7%	215	5	97.7%	3	1	66.7%	214	38	82.2%
148		3	1	66.7%	215	23	89.3%	3	0	100.0%	213	40	81.2%
151		3	1	66.7%	334	106	68.3%	3	0	100.0%	333	99	70.3%
170		3	0	100.0%	211	12	94.3%	3	0	100.0%	210	30	85.7%
171	93	3	0	100.0%	216	11	94.9%	3	2	33.3%	216	90	58.3%
172		3	0	100.0%	215	19	91.2%	3	1	66.7%	213	70	67.1%
173		3	0	100.0%	208	25	88.0%	3	0	100.0%	207	84	59.4%
174	21	3	0	100.0%	216	23	89.4%	3	1	66.7%	216	53	75.5%
175		3	0	100.0%	216	23	89.4%	3	1	66.7%	216	71	67.1%
176		3	0	100.0%	208	17	91.8%	3	0	100.0%	205	26	87.3%
177		3	0	100.0%	216	28	87.0%	3	0	100.0%	216	48	77.8%
178		3	0	100.0%	216	28	87.0%	3	0	100.0%	214	36	83.2%
179		3	0	100.0%	216	25	88.4%	3	1	66.7%	215	77	64.2%
181		3	1	66.7%	212	65	69.3%	3	0	100.0%	209	17	91.9%
182		3	0	100.0%	206	31	85.0%	3	1	66.7%	204	24	88.2%
183		3	1	66.7%	215	63	70.7%	3	0	100.0%	212	44	79.2%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		3	0	100.0%	216	36	83.3%	3	0	100.0%	215	28	87.0%
185		3	0	100.0%	216	41	81.0%	3	0	100.0%	216	18	91.7%
186	33	3	1	66.7%	215	30	86.0%	3	2	33.3%	214	63	70.6%
190		3	1	66.7%	215	76	64.7%	3	0	100.0%	214	44	79.4%
192		3	0	100.0%	213	24	88.7%	3	0	100.0%	213	19	91.1%
193		3	2	33.3%	211	85	59.7%	3	1	66.7%	210	91	56.7%
196		3	0	100.0%	212	23	89.2%	3	0	100.0%	210	17	91.9%
197		3	1	66.7%	216	78	63.9%	3	2	33.3%	216	73	66.2%
198		3	2	33.3%	148	19	87.2%	3	1	66.7%	147	23	84.4%
230		3	0	100.0%	171	4	97.7%	3	0	100.0%	171	9	94.7%
232		3	0	100.0%	337	12	96.4%	3	1	66.7%	337	24	92.9%
233		3	1	66.7%	298	67	77.5%	3	0	100.0%	297	101	66.0%
234		3	0	100.0%	338	23	93.2%	3	0	100.0%	337	29	91.4%
235		3	0	100.0%	262	42	84.0%	3	0	100.0%	261	60	77.0%
236		3	0	100.0%	322	10	96.9%	3	0	100.0%	321	43	86.6%
237		3	1	66.7%	335	62	81.5%	3	1	66.7%	333	60	82.0%
238		3	0	100.0%	262	23	91.2%	3	0	100.0%	260	22	91.5%
239		3	2	33.3%	336	85	74.7%	3	0	100.0%	335	42	87.5%
240		3	0	100.0%	337	23	93.2%	3	0	100.0%	334	69	79.3%
241		3	2	33.3%	337	84	75.1%	3	2	33.3%	337	83	75.4%
243		3	1	66.7%	273	72	73.6%	3	0	100.0%	272	39	85.7%
244	23	3	1	66.7%	297	13	95.6%	3	2	33.3%	297	67	77.4%
245		3	0	100.0%	218	41	81.2%	3	0	100.0%	217	30	86.2%
280		3	0	100.0%	338	17	95.0%	3	1	66.7%	337	79	76.6%
281		3	0	100.0%	338	40	88.2%	3	0	100.0%	338	60	82.2%
283	39	3	0	100.0%	338	85	74.9%	3	3	0.0%	338	69	79.6%
284	18	3	1	66.7%	338	14	95.9%	3	2	33.3%	335	63	81.2%
290	35	3	1	66.7%	338	53	84.3%	3	1	66.7%	335	138	58.8%
291	23	3	0	100.0%	337	112	66.8%	3	1	66.7%	333	91	72.7%
300		3	0	100.0%	321	22	93.1%	3	0	100.0%	318	73	77.0%
301	84	3	0	100.0%	335	10	97.0%	3	3	0.0%	331	66	80.1%
302	68	3	1	66.7%	316	35	88.9%	3	3	0.0%	312	93	70.2%
305	108	3	1	66.7%	319	32	90.0%	3	3	0.0%	314	125	60.2%
306	87	3	0	100.0%	333	17	94.9%	3	3	0.0%	331	92	72.2%
307		3	0	100.0%	326	44	86.5%	3	2	33.3%	322	100	68.9%
311	61	3	1	66.7%	330	29	91.2%	3	3	0.0%	324	87	73.1%
316	90	3	0	100.0%	326	24	92.6%	3	3	0.0%	320	104	67.5%
318	179	3	0	100.0%	336	35	89.6%	3	3	0.0%	333	169	49.2%
319	267	3	0	100.0%	337	20	94.1%	3	3	0.0%	332	196	41.0%
329		3	0	100.0%	239	12	95.0%	3	0	100.0%	239	19	92.1%
330	39	3	1	66.7%	287	7	97.6%	3	1	66.7%	287	16	94.4%
331	40	3	1	66.7%	338	34	89.9%	3	1	66.7%	337	45	86.6%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		3	0	100.0%	337	19	94.4%	3	1	66.7%	337	47	86.1%
334		3	0	100.0%	338	11	96.7%	3	0	100.0%	336	43	87.2%
335		3	0	100.0%	338	35	89.6%	3	0	100.0%	335	55	83.6%
336		3	0	100.0%	337	10	97.0%	3	0	100.0%	335	29	91.3%
337		3	0	100.0%	338	21	93.8%	3	0	100.0%	334	47	85.9%
338		3	0	100.0%	338	54	84.0%	3	0	100.0%	335	104	69.0%
339		3	0	100.0%	338	54	84.0%	3	0	100.0%	338	58	82.8%
341		3	0	100.0%	323	51	84.2%	3	0	100.0%	317	53	83.3%
342		3	0	100.0%	338	26	92.3%	3	2	33.3%	336	63	81.3%
350		3	1	66.7%	313	21	93.3%	3	2	33.3%	305	176	42.3%
351		3	0	100.0%	320	29	90.9%	3	2	33.3%	318	94	70.4%
352	56	3	0	100.0%	304	24	92.1%	3	3	0.0%	298	96	67.8%
353		3	0	100.0%	275	14	94.9%	3	1	66.7%	269	50	81.4%
354		3	0	100.0%	319	37	88.4%	3	1	66.7%	311	117	62.4%
355	129	3	0	100.0%	326	37	88.7%	3	1	66.7%	317	120	62.1%
364	37	3	0	100.0%	327	73	77.7%	3	2	33.3%	321	122	62.0%
365	58	3	0	100.0%	326	13	96.0%	3	1	66.7%	323	125	61.3%
370		3	0	100.0%	324	39	88.0%	3	0	100.0%	311	75	75.9%
371		3	0	100.0%	317	11	96.5%	3	1	66.7%	313	31	90.1%
380		3	0	100.0%	319	30	90.6%	3	0	100.0%	318	72	77.4%
381		3	0	100.0%	334	15	95.5%	3	0	100.0%	331	71	78.5%
382		3	1	66.7%	333	31	90.7%	3	2	33.3%	331	118	64.4%
383		3	1	66.7%	324	28	91.4%	2	0	100.0%	320	138	56.9%
390	30	3	0	100.0%	319	24	92.5%	3	2	33.3%	317	88	72.2%
391	31	3	0	100.0%	320	14	95.6%	3	3	0.0%	315	91	71.1%
392	52	3	1	66.7%	333	12	96.4%	2	2	0.0%	327	105	67.9%
393	33	3	1	66.7%	337	20	94.1%	2	2	0.0%	332	106	68.1%
417		3	0	100.0%	224	47	79.0%	3	0	100.0%	215	25	88.4%
425		2	0	100.0%	226	7	96.9%	2	0	100.0%	225	7	96.9%
448	45	3	2	33.3%	262	51	80.5%	3	1	66.7%	258	90	65.1%
449		3	0	100.0%	259	34	86.9%	3	0	100.0%	259	45	82.6%
470		3	0	100.0%	239	40	83.3%	3	1	66.7%	233	28	88.0%
471		3	0	100.0%	228	14	93.9%	3	0	100.0%	228	6	97.4%
473		3	0	100.0%	235	15	93.6%	3	0	100.0%	232	10	95.7%
474	26	3	0	100.0%	231	66	71.4%	3	1	66.7%	216	72	66.7%
475		2	0	100.0%	231	8	96.5%	2	0	100.0%	231	16	93.1%
478		3	1	66.7%	227	37	83.7%	3	1	66.7%	225	29	87.1%
479		3	0	100.0%	234	36	84.6%	3	0	100.0%	232	36	84.5%
486		3	0	100.0%	238	35	85.3%	3	0	100.0%	232	61	73.7%
494	32	3	1	66.7%	241	48	80.1%	3	2	33.3%	233	66	71.7%
495		3	0	100.0%	222	4	98.2%	3	0	100.0%	220	3	98.6%
500		3	1	66.7%	312	17	94.6%	3	1	66.7%	309	37	88.0%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
502		3	0	100.0%	320	19	94.1%	3	1	66.7%	316	62	80.4%
503	Cncld	3	2	33.3%	334	42	87.4%	2	0	100.0%	326	102	68.7%
504	18	3	0	100.0%	338	20	94.1%	3	1	66.7%	336	100	70.2%
505	18	3	0	100.0%	330	43	87.0%	3	3	0.0%	325	94	71.1%
506		3	1	66.7%	333	57	82.9%	2	1	50.0%	324	52	84.0%
507		3	0	100.0%	338	49	85.5%	3	1	66.7%	338	116	65.7%
509		3	1	66.7%	319	16	95.0%	3	1	66.7%	319	72	77.4%
511		3	1	66.7%	314	26	91.7%	3	0	100.0%	313	53	83.1%
516	88	3	1	66.7%	329	36	89.1%	3	2	33.3%	328	148	54.9%
517	19	3	0	100.0%	338	8	97.6%	3	1	66.7%	334	151	54.8%
518	32	3	2	33.3%	338	48	85.8%	3	3	0.0%	336	235	30.1%
519	37	3	1	66.7%	329	10	97.0%	3	2	33.3%	327	74	77.4%
520	23	3	1	66.7%	197	30	84.8%	3	1	66.7%	192	12	93.8%
521		3	1	66.7%	235	8	96.6%	3	0	100.0%	234	31	86.8%
522		3	1	66.7%	235	44	81.3%	3	0	100.0%	232	24	89.7%
523	37	3	0	100.0%	235	9	96.2%	3	1	66.7%	234	27	88.5%
524		3	1	66.7%	234	18	92.3%	3	0	100.0%	231	27	88.3%
525		3	1	66.7%	232	17	92.7%	2	0	100.0%	227	15	93.4%
526		3	1	66.7%	209	42	79.9%	2	0	100.0%	205	18	91.2%
527		3	0	100.0%	235	10	95.7%	3	0	100.0%	233	40	82.8%
528		3	0	100.0%	235	19	91.9%	3	1	66.7%	234	33	85.9%
529		3	0	100.0%	235	13	94.5%	3	0	100.0%	234	65	72.2%
530		3	1	66.7%	189	19	89.9%	3	0	100.0%	189	38	79.9%
531	15	3	1	66.7%	209	15	92.8%	3	1	66.7%	209	14	93.3%
532		3	2	33.3%	235	59	74.9%	3	1	66.7%	233	36	84.5%
534		3	1	66.7%	194	29	85.1%	3	0	100.0%	191	17	91.1%
535		3	1	66.7%	221	27	87.8%	3	0	100.0%	216	28	87.0%
536		3	2	33.3%	235	66	71.9%	3	1	66.7%	231	42	81.8%
537		3	1	66.7%	204	25	87.7%	3	0	100.0%	198	25	87.4%
538		3	0	100.0%	235	26	88.9%	3	0	100.0%	234	46	80.3%
539		3	0	100.0%	189	28	85.2%	3	1	66.7%	189	83	56.1%
540	21	3	2	33.3%	234	46	80.3%	3	1	66.7%	224	22	90.2%
541		3	1	66.7%	234	26	88.9%	3	1	66.7%	227	42	81.5%
542		3	0	100.0%	234	25	89.3%	3	1	66.7%	231	42	81.8%
543	43	3	1	66.7%	235	29	87.7%	3	2	33.3%	235	75	68.1%
544		3	0	100.0%	233	22	90.6%	3	0	100.0%	229	22	90.4%
545		3	1	66.7%	235	21	91.1%	3	0	100.0%	232	29	87.5%
547		3	1	66.7%	235	48	79.6%	3	0	100.0%	235	54	77.0%
548		2	0	100.0%	226	22	90.3%	2	0	100.0%	223	17	92.4%
549		3	0	100.0%	230	27	88.3%	3	0	100.0%	220	20	90.9%
550		3	2	33.3%	189	22	88.4%	3	1	66.7%	189	45	76.2%
551		3	0	100.0%	231	23	90.0%	3	0	100.0%	221	23	89.6%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562		3	0	100.0%	329	27	91.8%	3	0	100.0%	324	37	88.6%
564		3	0	100.0%	330	19	94.2%	3	1	66.7%	322	44	86.3%
566	21	3	1	66.7%	328	30	90.9%	3	1	66.7%	325	55	83.1%
567		3	0	100.0%	215	11	94.9%	3	0	100.0%	213	14	93.4%
572	18	3	0	100.0%	325	27	91.7%	3	1	66.7%	317	96	69.7%
573		3	0	100.0%	327	44	86.5%	3	0	100.0%	319	58	81.8%
579		3	0	100.0%	215	14	93.5%	3	1	66.7%	208	46	77.9%
580		3	1	66.7%	330	19	94.2%	3	1	66.7%	323	38	88.2%
581		3	0	100.0%	330	58	82.4%	3	2	33.3%	327	77	76.5%
584		3	0	100.0%	214	32	85.0%	3	2	33.3%	207	134	35.3%
587		3	0	100.0%	322	21	93.5%	3	0	100.0%	313	65	79.2%
588		3	0	100.0%	213	23	89.2%	3	0	100.0%	211	43	79.6%
591		3	1	66.7%	327	27	91.7%	3	1	66.7%	320	50	84.4%
593	19	3	1	66.7%	320	54	83.1%	3	2	33.3%	297	43	85.5%
595		3	2	33.3%	323	62	80.8%	3	0	100.0%	320	73	77.2%
600		3	0	100.0%	243	9	96.3%	3	1	66.7%	241	23	90.5%
601		3	1	66.7%	226	91	59.7%	3	1	66.7%	223	28	87.4%
605		3	3	0.0%	233	142	39.1%	2	0	100.0%	228	23	89.9%
607		3	1	66.7%	242	31	87.2%	3	1	66.7%	239	26	89.1%
609		3	0	100.0%	233	23	90.1%	3	0	100.0%	232	23	90.1%
622		3	0	100.0%	140	35	75.0%	3	1	66.7%	137	6	95.6%
626		3	0	100.0%	147	20	86.4%	3	0	100.0%	145	18	87.6%
639		3	0	100.0%	213	40	81.2%	3	0	100.0%	211	20	90.5%
640		3	1	66.7%	233	8	96.6%	3	1	66.7%	231	85	63.2%
641		3	0	100.0%	215	43	80.0%	3	2	33.3%	215	29	86.5%
642		3	1	66.7%	231	12	94.8%	3	0	100.0%	230	27	88.3%
643		3	1	66.7%	245	45	81.6%	3	1	66.7%	242	40	83.5%
644		3	0	100.0%	237	28	88.2%	3	1	66.7%	235	57	75.7%
645		3	0	100.0%	245	42	82.9%	3	0	100.0%	242	55	77.3%
646	45	3	3	0.0%	234	59	74.8%	3	2	33.3%	232	115	50.4%
647		3	2	33.3%	245	37	84.9%	3	1	66.7%	243	52	78.6%
648		3	1	66.7%	241	60	75.1%	3	1	66.7%	241	36	85.1%
649		3	1	66.7%	246	45	81.7%	3	0	100.0%	242	34	86.0%
650		3	0	100.0%	245	45	81.6%	3	1	66.7%	242	40	83.5%
651		3	0	100.0%	245	17	93.1%	3	0	100.0%	242	43	82.2%
652		3	0	100.0%	246	31	87.4%	3	1	66.7%	242	42	82.6%
653		3	2	33.3%	234	38	83.8%	3	1	66.7%	230	42	81.7%
654		3	0	100.0%	235	44	81.3%	3	0	100.0%	231	20	91.3%
655	18	3	2	33.3%	243	76	68.7%	3	2	33.3%	240	78	67.5%
656		3	1	66.7%	245	55	77.6%	3	0	100.0%	243	33	86.4%
657		3	0	100.0%	234	29	87.6%	3	1	66.7%	232	31	86.6%
658		3	0	100.0%	245	37	84.9%	3	0	100.0%	243	35	85.6%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680		3	0	100.0%	240	12	95.0%	3	0	100.0%	238	27	88.7%
681		3	0	100.0%	240	18	92.5%	3	0	100.0%	233	93	60.1%
682		3	1	66.7%	239	10	95.8%	3	0	100.0%	239	42	82.4%
683		3	0	100.0%	222	18	91.9%	3	0	100.0%	221	75	66.1%
684		3	0	100.0%	221	37	83.3%	3	0	100.0%	221	47	78.7%
685		3	0	100.0%	236	33	86.0%	3	0	100.0%	233	55	76.4%
686		3	0	100.0%	241	39	83.8%	3	0	100.0%	240	52	78.3%
687		3	0	100.0%	240	38	84.2%	3	0	100.0%	239	40	83.3%
688		3	0	100.0%	239	15	93.7%	3	0	100.0%	238	41	82.8%
689		2	0	100.0%	157	21	86.6%	1	0	100.0%	155	23	85.2%
701		3	0	100.0%	270	30	88.9%	3	1	66.7%	267	33	87.6%
702	35	3	1	66.7%	337	37	89.0%	3	3	0.0%	334	86	74.3%
703		3	2	33.3%	338	114	66.3%	3	2	33.3%	336	102	69.6%
704		3	0	100.0%	269	49	81.8%	3	2	33.3%	261	61	76.6%
710		3	1	66.7%	338	80	76.3%	2	1	50.0%	333	89	73.3%
711		3	1	66.7%	329	39	88.1%	3	1	66.7%	306	66	78.4%
712	16	3	2	33.3%	335	93	72.2%	3	2	33.3%	325	116	64.3%
714	18	3	2	33.3%	219	94	57.1%	3	3	0.0%	203	98	51.7%
715	48	3	0	100.0%	337	63	81.3%	2	2	0.0%	307	157	48.9%
716	16	3	2	33.3%	338	145	57.1%	3	3	0.0%	329	144	56.2%
717		3	2	33.3%	323	81	74.9%	3	2	33.3%	298	100	66.4%
718	131	3	3	0.0%	338	181	46.4%	3	3	0.0%	335	132	60.6%
719		3	1	66.7%	338	114	66.3%	3	1	66.7%	321	99	69.2%
757		3	0	100.0%	123	7	94.3%	3	1	66.7%	122	15	87.7%
761		3	0	100.0%	334	13	96.1%	3	0	100.0%	331	44	86.7%
765		3	0	100.0%	334	25	92.5%	3	1	66.7%	334	47	85.9%
769		3	0	100.0%	334	27	91.9%	3	1	66.7%	327	66	79.8%
770		3	0	100.0%	334	25	92.5%	3	0	100.0%	331	104	68.6%
774		3	0	100.0%	334	17	94.9%	3	0	100.0%	332	80	75.9%
777	No OS	3	0	100.0%	219	13	94.1%	3	3	0.0%	218	61	72.0%
782		3	1	66.7%	219	106	51.6%	3	1	66.7%	214	37	82.7%
785	87	3	0	100.0%	334	29	91.3%	3	1	66.7%	334	62	81.4%
786	21	3	0	100.0%	123	23	81.3%	3	1	66.7%	119	67	43.7%
790		3	0	100.0%	334	31	90.7%	3	0	100.0%	331	54	83.7%
794		3	0	100.0%	334	40	88.0%	3	0	100.0%	330	76	77.0%
821	11	2	0	100.0%	331	6	98.2%	2	1	50.0%	331	141	57.4%
822	94	3	1	66.7%	334	19	94.3%	2	2	0.0%	331	172	48.0%
1333		3	0	100.0%	334	40	88.0%	3	1	66.7%	331	113	65.9%
1340		3	0	100.0%	333	7	97.9%	3	0	100.0%	332	56	83.1%
2102		3	0	100.0%	92	16	82.6%	3	0	100.0%	91	7	92.3%
2103		3	0	100.0%	156	14	91.0%	3	0	100.0%	155	10	93.5%
2104		3	0	100.0%	182	10	94.5%	3	0	100.0%	180	13	92.8%

Amtrak On Time Performance

Trains Arriving Through: 9/3/2026

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2105		3	0	100.0%	4	1	75.0%	3	0	100.0%	4	0	100.0%
2107		2	0	100.0%	212	35	83.5%	2	0	100.0%	209	21	90.0%
2108		3	0	100.0%	213	28	86.9%	3	0	100.0%	207	27	87.0%
2109		3	0	100.0%	106	13	87.7%	3	0	100.0%	104	6	94.2%
2112		3	0	100.0%	53	6	88.7%	3	0	100.0%	51	2	96.1%
2113		3	0	100.0%	92	9	90.2%	3	0	100.0%	92	10	89.1%
2115		3	1	66.7%	92	14	84.8%	3	0	100.0%	91	12	86.8%
2116		3	0	100.0%	53	1	98.1%	3	0	100.0%	53	8	84.9%
2118		3	0	100.0%	53	4	92.5%	3	0	100.0%	53	12	77.4%
2119	20	3	0	100.0%	53	8	84.9%	3	1	66.7%	52	13	75.0%
2120		3	1	66.7%	53	20	62.3%	3	0	100.0%	51	23	54.9%
2123		3	1	66.7%	91	11	87.9%	3	0	100.0%	90	15	83.3%
2124		3	0	100.0%	184	38	79.3%	3	0	100.0%	182	24	86.8%
2126		3	0	100.0%	101	26	74.3%	3	0	100.0%	100	22	78.0%
2127		3	0	100.0%	53	10	81.1%	3	0	100.0%	52	9	82.7%
2128		3	0	100.0%	53	4	92.5%	3	0	100.0%	53	3	94.3%
2131		3	0	100.0%	53	10	81.1%	3	0	100.0%	53	6	88.7%
2150		3	0	100.0%	206	22	89.3%	3	0	100.0%	203	75	63.1%
2151	42	3	0	100.0%	155	7	95.5%	3	2	33.3%	153	43	71.9%
2152		3	0	100.0%	111	7	93.7%	3	0	100.0%	110	31	71.8%
2154		3	1	66.7%	114	24	78.9%	2	0	100.0%	109	45	58.7%
2155		3	0	100.0%	215	17	92.1%	3	1	66.7%	211	103	51.2%
2156		3	0	100.0%	4	0	100.0%	3	0	100.0%	4	0	100.0%
2158		3	0	100.0%	52	6	88.5%	3	0	100.0%	52	16	69.2%
2159		3	0	100.0%	208	16	92.3%	3	0	100.0%	206	69	66.5%
2160		3	1	66.7%	53	3	94.3%	3	0	100.0%	52	28	46.2%
2162		3	0	100.0%	214	23	89.3%	3	0	100.0%	208	91	56.3%
2163	22	3	0	100.0%	166	17	89.8%	3	1	66.7%	160	70	56.3%
2165	18	3	0	100.0%	50	4	92.0%	3	1	66.7%	50	22	56.0%
2167		3	1	66.7%	201	21	89.6%	3	1	66.7%	201	42	79.1%
2171		3	0	100.0%	142	10	93.0%	3	1	66.7%	138	24	82.6%
2190		3	0	100.0%	211	29	86.3%	3	0	100.0%	209	24	88.5%
2193		2	0	100.0%	205	26	87.3%	2	0	100.0%	203	50	75.4%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/3/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2119	WAS	20	CAR	23	CAR	23	BWI-BWI	AM	Door, 3922 NG NM, door problems 2nd car
2151	WAS	42	OTH	16	OTH	7	PHL-XPV	AM	Lost time - N.A.R., PRT
2163	WAS	22	OTH	14	DMW	10	NHV-STM	MN	Waiting for MW clearance Milepost, 53.9, 52.5
2165	WAS	18	DSR	28	DSR	28	NHV-STM	MN	Per bulletin Cp 241-East Norwalk PSGR speed 15, Restricted speed cat pole 533-535. Held at the Working limits stop sign., Milepost, 48.6, 33.6, 30, 2,4
85	WAS	18	OTH	15	DSR	13	BRP-STM	MN	Per bulletin Control Point, 248, 30, 2, Milepost, 42, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 2
86	NYP	37	CTI	43	CTI	23	WDB-ALX	CS	Follow vre310, Other, cfp94.5-105.0
93	NFK	21	ENG	30	ENG	30	WAS-WAS	AM	HEP, 369 DX AG, ENGR PUT HEP SELECTOR SWITCH IN INCORRECT POSITION CAUSING FAULT. DSL HAD TO BE SHUT DOWN AND RESTARTED.
95	NFK	178	ENG	70	ENG	70	X3V-NFK	NS	Air / Brake Brake holes came off couldn't locate, cut out angle cock secured other dangling equipment., 121
125	NPN	46	WTR	26	DCS	16	WAS-WAS	AM	Power switch failure, Control Point, A INT, LOSS OF POWER IN A INTERLOCKING
131	WAS	23	OTH	11	OTH	8	BWI-XNY	AM	Lost time - N.A.R., PRT
138	NYP	131	FTI	91	FTI	91	ASD-FBG	CS	Broken knuckle I031, Milepost, 53.2, 53.2
171	RNK	93	ENG	38	ENG	38	WAS-WAS	AM	HEP, 174 DX BD, LATE DSL FROM THE PIT, NO WORKINNG BELL AND ISSUES WITH POWER.
174	BOS	21	SMW	24	SMW	12	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING ON NO.2 TRK LEGGETT TO PELHAM BAY DUE TO SCHEDULED MAINTANENCE WORK
186	PHL	33	WTR	24	FTI	20	RVM-RVR	CS	Meet Stop signal, I031, Control Point, NA
474	SPG	26	CON	22	CON	22	NHV-NHV	AM	Hold for connecting train, late connection of AM174
494	GFD	32	POL	39	POL	39	WNL-WNL	AM	Right of Way police hold, APD has a hold on both trks btwn Field and Sweeney
52	LOR	159	FTI	61	DCS	45	XSE-XV7	CS	Restrictive signal(s) from known wayside signal failure Stop, Control Point, pleasant hill
53	SFA	113	FTI	66	FTI	23	XSE-XFL	CS	Meet E315, Milepost, 231.7, 233.7

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
79	CLT	75	WTR	71	ENG	39	WAS-WAS	AM	HEP, 305 DX AG, SHOPPED DSL 305 DUE TO I045 FAULT. DSL 132 REPLACED SHOPPED DSL 305.
80	NYP	124	FTI	175	FTI	119	RVR-FBG	CS	Train had a broken knuckle m418, Other, cfp 47.5
646	NYP	45	SYS	18	SYS	18	PHL-XHM	AM	Re-crew / job briefing, WYE OUTBOUND A/C NO CAB CAR
655	HAR	18	CTI	9	SVS	8	PHL-PHL	AM	Pick up equipment, CAPPED WITH ENG 669
20	NYP	49	FTI	89	FTI	72	CVS-CLP	NS	Follow Control Point, Weyburn, K99
63	TWO	39	OTH	3	OTH	3	NYP-XSD	AM	Lost time - N.A.R.
64	NYP	74	CUI	36	CUI	36	NFL-NFL	CS	United States High passenger count
69	MTR	27	WTR	39	WTR	39	XLQ-SLQ	CN	Heat order Milepost, 0, 42.5
244	NYP	23	CTI	34	CTI	15	POU-CRT	MN	Follow metro north, 880, Milepost, 73, 50
283	NFL	39	FTI	62	FTI	62	ROC-BUF	CS	Follow Multiple stops due to westbound ahead of us. 380 on 2 xed over to 1 at 382. Followed then stopped wt 417 for ten minutes. Stopped at 323 for 10 minutes then xed over 1 to 2 at 423 to head into Buffalo Depew., Milepost, 382, 423, M27503
284	NYP	18	PTI	18	PTI	18	ALB-HUD	AM	Meet 233, Control Point, 124
290	NYP	35	ENG	47	ENG	38	BTN-VRN	VR	290 stopped at mp 108 due to multiple locked axle #4 faults on engine #708. 708
291	BTN	23	ENG	22	ENG	22	ALB-ALB	AM	Set out defective locomotive 703
48	NYP	52	FTI	48	PTI	35	X81-ERI	CS	Meet amtk49, Control Point, 113
49	CHI	384	FTI	345	FTI	195	BUF-ERI	CS	Follow Stopped behind freight giant tree over both mains at 84.8 waiting on logging company to come out and clear main 2, UKCSX, Control Point, 81
448	BOS	-16	CON	52	CON	52	ALB-ALB	AM	Hold for connecting train 48
43	PGH	320	WTR	322	WTR	175	LAB-GNB	NS	Trees down Trees down every where.. had to stop multiple times to clear brush from the train, Milepost, 312.3, 322.1
77	CLT	67	DMW	50	DMW	50	DNC-BNC	NS	Held for or routed around MW work or equipment Control Point, king
90	NYP	88	WTR	55	FTI	23	PTB-RVR	CS	Meet 111, Other, a10.7

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/3/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
97	MIA	113	DCS	107	SVS	50	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR INBOUND TRAIN AM98 AND ADD FOUR COACHES AND SERVICE THE EQUIPMENT	
98	NYP	60	DSR	45	RTE	30	XDJ-ALX	CS	Dispatcher hold Following VRE waiting for permission to pass stop signal, Other, AF	
56	SAB	33	DSR	29	MTI	13	TRE-NWK	AM	Disabled train ahead, Other, XH1, HELD A/C AM2154 DISABLED ON 2 TRK AHD	
40	CHI	115	WTR	78	ENG	48	PGH-ALC	NS	Cab signal failure Cab signals cut out at CP Bell, 327	
41	MIA	173	WTR	117	WTR	69	PTB-RMT	CS	High winds Winds up to 60mph, Milepost, 22.0, 79.0, Milepost, 109.9, 120.0	
24	MOE	34	POL	36	POL	36	BIX-PAG	CS	Right of Way police hold	
5	EMY	210	DSR	118	RTE	79	GRI-HER	UP	Dispatcher hold Dispatcher told us to stop at 622 due to co2 leak at 626, Milepost, 622.0, 622.0	
6	CHI	375	ENG	220	SVS	81	SAC-RSV	UP	Planned set out / pick out of locomotives, cars or section of train Other, rsv yard	
520	SAC	23	MBO	27	MBO	27	MTZ-SUI	UP	For maritime traffic Control Point, Vista	
523	SJC	37	MBO	30	MBO	30	SUI-MTZ	UP	For maritime traffic Control Point, Benicia	
531	OKJ	15	POL	25	POL	25	SAC-DAV	UP	Right of Way police hold Per dispatcher 62, police presence on main tracks at milepost 86.39. Hold until released	
540	SAC	21	TEN	20	TEN	20	OKJ-OKJ	UP	Other electrical failure Locomotive shut down Fault code 0959 "Diesel engine fuel level indicator faulty", C2103	
543	SJC	43	PTI	28	CTI	17	FMT-GAC	UP	Meet ACE, ACE8, Siding, Albrae	
51	CHI	60	DSR	51	WTR	21	STA-XJD	BB	Heat order Heat restrictions Staunton to Clifton Forge, Other, Staunton	
503	EUG	Trn Cancelled								
504	SEA	18	PTI	15	PTI	15	XNI-TAC	ST	Meet Lakewood sub, AMTK 517, Control Point, Manitou	
505	PDX	18	SVS	21	SVS	21	VAN-PDX	BN	Unplanned Wye Wye train due to inoperative cab car for train set that turns in PDX as #518, Other, T-6	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
516	VAC	88	ENG	81	ENG	69	SEA-SEA	BN	No working windshield wipers on AMTK 186, which will have to wye in VAC due to B/O cab car 90252. AMTK 186
517	PDX	19	FTI	17	FTI	17	XA4-XTW	BN	Meet BNSF 7328, Control Point, CLEAR CREEK
518	VAC	32	CTI	11	CTI	11	XNI-TAC	ST	Meet Sound Transit, Control Point, Manitou
519	SEA	37	FTI	25	FTI	17	STW-EVR	BN	Cross Traffic Control Point, Bridge 37, Control Point, PA Jct, BN unknown
58	CHI	76	SYS	51	SYS	49	JAN-JAN	CC	Other late crew
8	CHI	473	FTI	189	DCS	154	SEA-SEA	BN	PTC- Unplanned PTC system /server outage Other, seattle
821	FTW	11	DSR	24	DSR	18	GLE-FTW	BN	Per bulletin Milepost, 396.3, 396.2, 30, M, Milepost, 392.5, 391.6, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 388.2, 387.6, 15, M, Milepost, 385.5, 385.3, 30, M, Milepost, 384, 383.4, 25, M, Milepost, 382.7, 382.5, 40, M, Milepost, 355.9, 355.5, 50, 1, Milepost, 351.1, 350.7, 50, M, Milepost, 34
822	OKC	94	RTE	50	RTE	50	FTW-GLE	BN	Line manual or spring switch #2 switch wouldn't lock up - I couldn't hand line it so we had to back up to 350.5 to cross over to main 2, Siding, saginaw
330	CHI	39	CTI	27	ENG	20	MKE-MKE	CP	Failure of diesel engine ACS shut down engine, restarted 30 minutes before departure, engine shut just before departure, working with C'noc mechanical for an emergency restart in order to get traction effort from locomotive, ID4601
331	MKE	40	ITI	24	ITI	24	CHI-CHI	AM	Service, turn, or wye train 330, 8:36 arrived 8:41 boarding 8:48 cleared by Yard Master
352	PNT	56	DBS	36	DBS	32	ARB-DER	MI	Debris blocking track (no debris strike) Holding due to large tree blocking track. Waiting on MOW to arrive and cut it up., Milepost, 11.8, 11.8
355	CHI	129	DBS	59	PTI	53	DER-ARB	MI	Meet AMT 352, Control Point, 28
364	PTH	37	DSR	46	DCS	21	DOA-KAL	AM	Issue with automatic road crossing protection Other, 144.08, Other, 143.38, Other, 143.30, Other, 143.60, Other, 143.75, Other, 143.78, Other, 143.65

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	58	DSR	42	DSR	16	LPE-FLN	CC	Per bulletin Milepost, 289.2, 289.2, 30, ALL, Milepost, 286.16, 285.71, 40, MAIN, Milepost, 285.1, 285.1, 25, MAIN, Milepost, 281.3, 281.2, 40, MAIN, Milepost, 279.52, 279.52, 25, MAIN, Milepost, 273.91, 273.91, 40, MAIN
566	SAN	21	SYS	12	SYS	12	XRJ-FUL	BN	PTC problem or failure (cause unknown) Control Point, w. hobart
572	SAN	18	CTI	11	RTE	7	LAX-XRJ	SC	Single tracking at SD jct Control Point, san Diego jct
593	LAX	19	FTI	22	FTI	22	XFT-FUL	BN	Cross Traffic Waiting for BNSF 3775 East to pass at Fullerton Jct., BNSF 3775 East, Control Point, Fullerton Jct
777	SLO	No OS Rpt	ENG	314	ENG	314	GTA-GTA	UP	Failure of diesel engine CDTX 2116 multiple faults. Took equipment back to GTA. Loaded PAX on 785 equipment and departed GTA 11:51 Pacific Time., C2116
785	GTA	87	POL	93	POL	63	CPN-CPN	UP	RR blocked by trespasser or vehicle strike by another train
786	SAN	21	PTI	49	PTI	33	GUA-LPS	UP	Meet 765 / 14, Siding, tangair
702	BFD	35	FTI	41	FTI	28	FNO-HNF	BN	Meet BNSF 3794 WE, Control Point, EE CONEJO
712	BFD	16	PTI	28	DCS	11	SKN-SKN	BN	Signal suspension Had to wait to signal Time out .. dispatcher talked us through signal, Control Point, up crossing
714	BFD	18	PTI	25	PTI	16	TRK-MCD	BN	Meet Control Point, e denair, 715
715	OKJ	48	PTI	25	FTI	16	WAC-COC	BN	Meet bnsf, Siding, angiola
716	BFD	16	PTI	19	PTI	13	HNF-COC	BN	Meet 703, Control Point, Calabrese
718	BFD	131	ITI	70	ITI	70	EMY-EMY	UP	Service, turn, or wye train 713, 713 running late.
3	LAX	530	FTI	253	DCS	169	FMD-LAP	BN	PTC system failure Control Point, Argyle
4	CHI	110	FTI	162	FTI	42	FLG-WLO	BN	Meet BNSF 8140 W, Milepost, 342.9, 338.3
21	SAS	59	WTR	117	WTR	30	SPI-CRV	UP	Heat order Milepost, 36, 173
22	CHI	139	WTR	154	SYS	33	STL-STL	TR	Crew rest
301	STL	84	DSR	97	DSR	39	SPI-ALN	UP	Per bulletin Level 2 heat restriction, Milepost, 185.1, 255.6, 50, All
302	CHI	68	WTR	70	WTR	21	DWT-JOL	UP	Heat order Milepost, 173, 36
305	STL	108	WTR	76	ENG	29	BNL-LCN	UP	Failure of diesel engine ID4604

Amtrak Endpoint OTP Details

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
306	CHI	87	WTR	68	WTR	27	CRV-SPI	UP	Heat order Milepost w/Letters, crv, spi
390	CHI	30	WTR	21	SYS	11	CHM-RTL	CC	Re-crew / job briefing
391	CDL	31	WTR	23	WTR	6	CHM-MAT	CC	Heat order Milepost w/Letters, Champaign, Mattoon
392	CHI	52	WTR	54	WTR	13	MAT-CHM	CC	Heat order Milepost, 172.4, 127.9
393	CDL	33	WTR	41	WTR	6	EFG-CEN	CC	Heat order Other, CEN SUB
311	KCY	61	WTR	52	PTI	16	JEF-SED	UP	Meet Amtk 318, Siding, Shell
316	STL	90	FTI	50	FTI	19	KCY-XRC	UP	Cross Traffic UP 7323, Control Point, UP Interlocker
318	CHI	179	WTR	191	WTR	27	BNL-PON	UP	Heat order Milepost, 275.45, 36.88
319	KCY	267	WTR	165	FTI	106	WAR-LEE	UP	Follow up 6797, Milepost w/Letters, war, lee

Amtrak Initial Terminal Details

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/3/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	09/02	52	52	Hold for connecting train 48
BRK	682	09/03	3	3	Issue with automatic road crossing protection Other, .09
CLT	78	09/03	50	50	Late inbound train 77
HAR	646	09/03	12	12	Storm, Milepost, 99, 104, HELD FOR DISPOSITION A/C 607 OPERATE 1 TRACK AHEAD, TREE IN CATENARY ON 2 TRACK
LOR	53	09/03	26	26	Drum Mac
MIA	40	09/03	140	140	Lead locomotive 134 failure during mechanical inspection at Miami mechanical facility. Locomotive needs to be removed and no replacement.
NYP	239	09/03	7	7	Delay due to mechanical problems on a Commuter train, NJ6651 STOPPED AHD AT "A" INT WITH DOOR ISSUES
NYP	653	09/03	3	3	Cross Traffic, NJT, NJ6656, Other, "A" INT, DELAYED NJ6656 RTD AHD IN "A" INT
NYP	2115	09/03	3	3	Passenger and/or baggage, BOARDING
PHL	151	09/03	3	3	Lost time - N.A.R., given Form D cancelling speed restriction
PHL	605	09/03	2	2	PTC - Stop Bypass Permission Required, Control Point, .
RGH	77	09/03	5	5	Re-crew / job briefing Waiting for engineer to look up something in his tablet about fetner
WAS	148	09/03	4	4	Disabled train ahead, Control Point, K INT, AM2160 DOOR ISSUES DELAYED DEPARTURE
WAS	198	09/03	3	3	Follow, MARC, 548, Bridge, H&J BRIDGE, FOLLOWING MARC 548
WAS	2120	09/03	2	2	Wheelchair, LATE ADA PAX AT DEP TIME
WAS	2160	09/03	5	5	Electrical failure, ., DOOR ISSUE
CHI	41	09/03	80	80	Late road power, adding Eng/10 off inbound 22(02) the same day 10
CHI	331	09/03	24	24	Service, turn, or wye train 330, 8:36 arrived 8:41 boarding 8:48 cleared by Yard Master
CHI	350	09/03	4	4	HEP HEP SHUT DOWN PRIOR TO DEPARTURE. BREAKERS RESET BY MECHANICAL. WORKING AS INTENDED. 4 MIN DELAY., ID4619
MKE	330	09/03	20	20	Failure of diesel engine ACS shut down engine, restarted 30 minutes before departure, engine shut just before departure, working with C'noc mechanical for an emergency restart in order to get traction effort from locomotive, ID4601
GTA	782	09/03	5	5	Meet 14, Control Point, CO 358
LAX	566	09/03	6	6	Engine 2121 shut down. Mechanical had to restart the engine. C2121
OKJ	536	09/03	1		

Amtrak Initial Terminal Details

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/3/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	540	09/03	20	20	Other electrical failure Locomotive shut down Fault code 0959 "Diesel engine fuel level indicator faulty", C2103
OKJ	712	09/03	1		
OKJ	718	09/03	(Trn Cxld)		Third Party Car Failure
SAC	521	09/03	4	4	Other late crew Desk 12 had our Engineer on the job but he was scheduled for the simulation test. Had to wait for another Engineer, Other, Sac depot
SAC	543	09/03	4	4	Service, turn, or wye train 530, Waiting for DRUMMAC to drop flags
SAC	547	09/03	1		
SEA	11	09/03	1	1	Passenger and/or baggage Waiting on checked bags. Late train 516 held up baggage crew. Bags not brought to train until 950.
SEA	503	09/03	(Trn Cxld)		Cab Car Issue
SEA	516	09/03	69	69	No working windshield wipers on AMTK 186, which will have to wye in VAC due to B/O cab car 90252. AMTK 186

Eastern Region

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	96.5	98.3	94.8	342	12
CDOT	95.0	90	93.3	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	91.9	92.7	88.6	358	29
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 41(02) Washington, DC - Signal

04SEP26: Due to a power switch failure at A interlocking multiple trains were delayed operating through Washington, DC Union station.

Train	Delay	Comment
41 (02)	36"	
171 (03)	6"	
125 (03)	18"	

Train 52(03) Yemassee, SC - Debris

04SEP26: Train 52(03), operating with engines 380/360, 37 coaches, and 331 customers, was delayed 23 miles north of Yemassee, SC, on CSX Charleston A, subdivision, due to an animal strike. The crew reported stiking a pack of dogs which caused an air hose to separate. After inspecting the equipment to locate the separated hoses, the crew coupled the hoses, performed their brake tests and were able to proceed.

Train	Delay	Comment
52 (03)	34"	

Train 494(03) Windsor Locks, CT - Police Related

03SEP26: Train 494(03), operating with engine 120, 2 coaches, and 37 customers, was delayed holding at Windsor Locks, CT, on Amtrak MRS subdivision, due to a police hold all tracks due to a trespasser reported in the area. There was also a reported fire on the Right of Way. Once these issues were resolved, the police released their hold on the tracks and train 494(02) was able to proceed.

Train	Delay	Comment
494 (03)	39"	

Train 283(03) - Freight Train Interference

03SEP26: Train 283(03), operating with engines 117/713, 5 coaches and 93 customers, was delayed 9 miles west of Rochester, NY, on CSX Buffalo Terminal subvision, following and meeting multiple freights between milepost 380 and milepost 423.

Train 95(03) East of Petersburg, VA - Engine Failure

04SEP26: Train 95(03) operating with engines 661/626, 5 coaches, and 212 customers, was delayed 11 miles east of Petersburg, VA, on NS Norfolk_62N subdivision, due to going into emergency. After inspecting the equipment the crew discovered their back-up hose was missing. The crew was unable to recover the hose and had to close the angle cock to the brake pipe on the last car to stop the air leak. The crew also secured other low hanging hoses and cables. After the appropriate brake tests the train was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
95(03)	1'10"	

Train 67(03) West of Kingston, RI - Engine Failure

03SEP26: Train 67(03), operating with engines 661/626, 5 coaches, and 266 customers, was delayed 4.5 miles west of Kingston, RI, on Amtrak NHB line, due to their trailing loco, E/626, showing a fault code that brought the train to a stop. Once stopped the crew inspected and with the aid of a Road Foreman and Cnoc Mechanical, they were able to diagnose the issue as a faulty MU cable. They swapped out the cable and was able to continue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
67(03)	41"	

Train 43(03) Johnstown, PA - Weather

03SEP26: Train 43(03), operating with engine 127, 7 coaches and 141 customers, encountered significant weather-related delays while operating westbound between Johnstown and Pittsburgh. The train was stopped at MP 288.7, west of Johnstown, on NS Pittsburgh subdivision, at approximately 6:45 PM due to high winds and remained on hold until being released around 7:45 PM. Upon resuming service, Train 43(03) operated at a restricted speed of 20 MPH between Johnstown and Pittsburgh because of continued high wind conditions and flash flood warnings. As the train proceeded west, the conductor reported multiple trees down on the tracks. The crew was able to remove several of the obstructions themselves, while an NS Maintenance-of-Way (MOW) crew worked ahead of the train to clear additional hazards.

The train continued to experience delays and was operating 2 hours and 7 minutes late departing Latrobe, PA. Just east of Greensburg, PA, Train 43(03) was again stopped when a large tree was discovered blocking the track ahead. The responding NS MOW crew encountered additional delays while clearing other fallen trees in the area before reaching the train's location. Due to the extended delay, a recrew was arranged for 1:15 AM to protect Train 43(03) into Pittsburgh and subsequently operate Train 42(04). A protect crew was also made available in Harrisburg to assist with Train 42(04) if necessary.

After the large tree was removed, Train 43(03) resumed operation and arrived at Greensburg 5 hours and 2 minutes behind schedule. The train later departed Greensburg operating 5 hours and 25 minutes late. NS subsequently lifted the high wind restrictions, allowing the train to resume normal authorized speeds and improving its ability to reach Pittsburgh within Hours of Service limitations. Train 43(03) ultimately arrived in Pittsburgh at 1:25 AM, operating 5 hours and 20 minutes late due to severe weather conditions and multiple fallen trees along the route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
43(03)	1'51"	E/JST
43(03)	3'18"	E/GNB
43(03)	8"	Remove Trees at LAB
43(03)	13"	Flash Floods W/GNB

Train 40(03) North of Okeechobee, FL - Weather

03SEP26: Train 40(03), operating with engine 384, 134 coaches and 161 customers, was delayed 25 miles north of Okeechobee, FL, on CSX Auburndale subdivision due to a signal issue beginning at milepost 865. This signal issue was caused by earlier storms through the area. As a result there is single tracking and flagging in the affected area.

Train	Delay	Comment
40(03)	1'25"	
97(02)	1'01"	
41(01)	40"	

Train 93(03) Washington, DC - Engine Failure

04SEP26: Train 93(03), operating with engine 369, 9 coaches and 262 customers, was delayed departing Washington, DC union station due to the engineer putting the HEP selector switch in the the incorrect position causing an engine fault. As a result the engine had to be restarted to clear the fault.

Train	Delay	Comment
93(03)	30"	

Train 80(03) South of Fredericksburg, VA - Freight Train Interference

03SEP26: Train 80(03) operating with engine 382, 7 cars, and 269 customers onboard was stopped at milepost 47.5, 12 miles south of Fredericksburg, VA on the CSX RF&P subdivision due to disabled CSX freight M418-03 at milepost 53.2. The freight train had a broken knuckled that needed to be fixed. The freight was able to replace the knuckle and resume travel. Train 80(03) was able to advance to the next station once there was a clear route.

Trains 40(02) and 138(03) were stopped behind Train 80(03) waiting on a clear route. Once train traffic resumed, the trains were able to advance to the next station.

Train	Delay	Comment
138(03)	1'31"	
40(02)	1'12"	
80(03)	1'59"	
80(03)	56"	Frt congestion
40(02)	42"	Train congestion
89(03)	34"	

Train 68(03) North of St-Lambert, QC -CN Heat Orders/ Weather - Weather

03SEP26: Train 68(27) was delayed on the CN Rouses Point subdivision due to Heat Orders from MP 40 to MP 15.0.

Train	Delay	Comment
68(03)	34"	

Train 89(03) Alexandria, VA - Freight Train Interference

03SEP26: Train 89(03) operating with engine 88, 7 cars, and 271 customers onboard was delayed beginning at Alexandria, VA on the CSX RF&P subdivision due to following CSX freight trains 135 and 407. Once the freight trains cleared, Train 89(03) advanced to the next station.

Train	Delay	Comment
89(03)	34"	

Train 64(03) Niagara Falls, NY - Customs and Immigration

03SEP26: Train 64(03) operating with engine 890 and 231 customers onboard was delayed at Niagara Falls, NY due to customs. UNCLASSIFIED 9/18/2026

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
64(03)	36"	

Train 290(03) North of Ferrisburgh, VT - Engine Failure

03SEP26: Train 290(03) operating with cab car 9702, 5 cars, engine 708, and 45 customers was delayed at milepost 108.1, 8 miles north of Ferrisburgh, VT on the Vermont Railway Northern subdivision due to multiple locked axels on engine 708. There were faults on the engine. The crew was able to successfully troubleshoot the issue. Train 290(03) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
290(03)	38"	

Train 79(03) Washington, DC - Engine Failure

03SEP26: Train 79(03) operating with engine 305, 7 cars, and 255 was delayed departing Washington, DC on the Amtrak WT line due to engine 305 being shopped during the scheduled power change. The engine 305 was shopped for I/O 45 faults. Engine 305 was replaced with engine 132. Once the new engine was added to the consist, Train 79(03) departed Washington at 1:44 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
79(03)	39"	

Train 97(02) South of Jacksonville, FL - Signal

03SEP26: Train 97(02) operating with engines 115, 307, 10 cars, and 202 customers onboard was delayed beginning at milepost 640.0, 1 mile south of Jacksonville, FL on the CSX Jacksonville Terminal subdivision due to restrictive signals from unknown causes between milepost 640. to milepost 642. 2. Once the train received more favorable signals, Train 97(02) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(02)	31"	

Train 20(02) North of Charlottesville, VA - Freight Train Interference

03SEP26: Train 20(02) operating with engines 343, 376, 8 cars, and 196 customers was delayed at milepost 92.4, 20 miles north of Charlottesville, VA on the NS Washington District due to freight K99 activating a detector. Once the freight train was recovered and, on the move, Train 20(02) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(02)	1'12"	

03SEP26: Train 40(03) ~~26-FCI-00731~~ ~~00000003774~~ engine UNCLASSIFIED, 324, 364, and 64 cars, and 64 customers was delayed departing Miami, FL on the SFRTA SFRTA subdivision due to engine failure on engine 134. The engine was not able to be turned on. The engines were flat switched in order for engine 324 to operate in the lead. The train departed Miami and made a stop in Sanford. In Sanford, engine 364 was added to the consist. Once the engine was added to the consist, Train 40(03) advanced to the next station.

Train	Delay	Comment
40(03)	2'20"	MIA
40(03)	45"	Adding Loco SFA

03SEP26: Trains were delayed on the following CSX subdivisions due to heat orders in effect between 100PM-ET through 700PM-ET: Alleghany, Baltimore Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, New River, North End, Old Main Line, Peninsula, RF&P, Richmond Terminal, Charleston, Nahunta, Savannah, and South End.

Train	Delay	Comment
53 (03)	12"	
79 (03)	1' 11"	
80 (03)	9"	
90 (03)	55"	
89 (03)	43"	
95 (03)	9"	
125 (03)	24"	
138 (03)	5"	
171 (03)	3"	
186 (03)	24"	

03SEP26: Train 52(02) operating with engines 317, 352, 40 cars, and 286 customers onboard was delayed at milepost 74.7, 46 miles north of Rocky Mont, NC on the CSX North End subdivision due to receiving restrictive signals from a known wayside signal failure. Once the train received more favorable signals, Train 52(02) advanced to the next station.

Train	Delay	Comment
52 (02)	45"	

03SEP26: Train 98(03) operating with engines 171, 319, 11 cars, and 47 customers onboard was delayed at milepost 1031.8, 3 miles north of Miami, FL on the SFTRA SFRTA subdivision due to a police hold on the tracks. The train was seventh in line to enter the main line. Once the police hold was lifted and the congestion cleared, Train 98(03) was able to advance to the next station.

Train	Delay	Comment
98(03)	2'53"	

Train 98(02) South of Alexandria, VA - Routing

03SEP26: Train 98(02) operating with engines 174, 360, 10 cars, and 232 customers onboard was delayed at milepost 102.5, 3 miles south of Alexandria, VA on the CSX RF&P subdivision due to being held by the dispatcher. The train was held due to following VRE. Once there was a clear route and the train received permission by the stop signal, Train 98(02) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(02)	30"	

Train 41(01) North of Savannah, GA - Freight Train Interference

03SEP26: Train 41(01) operating with engines 182, 136, 10 cars, and 143 customers onboard was delayed at milepost 490.1, 7 miles north of Savannah, GA on the CSX Columbia subdivision due to meeting CSX freight train M592-03. Once the freight train cleared, Train 41(01) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(01)	30"	

Train 52(02) North of Rocky Mount, NC - Engine Failure

03SEP26: Train 52(02) operating with engines 317, 352, 40 cars, and 286 customers onboard was delayed at milepost 94.9, 25 miles north of Rocky Mount, NC on the CSX North End subdivision due to an active fire alarm on engine 317. The crew got in contact with CNOC mechanical and Siemens to troubleshoot. The crew recycled the engine successfully. The train was on the move at 6:52 AM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(02)	43"	

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
240(29)	29"	
280(29)	18"	
233(29)	54"	
283(29)	64"	
284(29)	39"	
291(29)	36"	
290(29)	47"	
49(29)	49"	
235(29)	49"	
48(28)	31"	
237(29)	36"	
239(29)	1'10"	
69(30)	51"	
240(30)	35"	
1233(30)	18"	
291(30)	45"	LATE TURN OFF 240(30)

Maintenance of Way Highlights

26-XXX Adirondack CN Rouses Point Subdivision UCI Road World Championships Advisory - Scheduled M/W Work

03SEP26: To accommodate the UCI Road World Championships on the CN Rouses Point Subdivision, Amtrak's Adirondack Service will be adjusted as follows:

Train 69(25-27SEP), which normally operates between New York and Montreal, CA, will terminate at Saratoga Springs, NY.

Train 68(26-28SEP), which normally operated between Montreal and New York, will originate in Saratoga Springs.

Alternate transportation will be provided as follows:

Bus 3069 will provide alternate transportation between Saratoga Springs and Montreal.

Bus 3068 will provide alternate transportation between Montreal and Saratoga Springs.

Train 69(25SEP) equipment will deadhead Saratoga Springs to Albany for mechanical servicing and will deadhead Albany to Saratoga Springs on Monday September 28th to turn for Train 68(28SEP).

Train 69(26-27SEP) will make a same day turn for Train 68(26-27SEP) in Saratoga Springs.

WBS#: B.TR.100150.7134

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008774 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008774 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Train 300(04) St. Louis, MO - Engine Failure

04SEP26: Train 300(04) cancelled due to oil leak on engine ID4633. Train 302(04) will operate as a double draft to Chicago IL station. Customers advised to re-book on 302(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
300(04)	Cancelled	

Train 786(03) South of Lompoc-Surf, CA - Passenger Train Interference

04SEP26: Train 786(03) was delayed at Tangair siding/MP293.6 5.5 miles south of Lompoc-Surf, CA/MP299.2 on the UP Santa Barbara subdivision due to meeting Train 14(03).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(03)	33"	

Train 7/27(02) Havre, MT - Freight Train Interference

04SEP26: Train 7/27(02) was delayed beginning at Havre, MT/MP430.3 on the BNSF Milk River Subdivision, due to following BNSF freight unit BN5123 to Gildford/MP988.9 on the BNSF Hi Line Subdivision.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(02)	38"	

Train 58(03) South of Fulton, KY - CN PTC Outage

04SEP26: Train 58(03) was delayed holding at MP297.5, 31.1 miles south of Fulton KY station on the CN Fulton subdivision due to a CN PTC outage. CN PTC was resolved at 218AM CT and train 58(03) was back on the move proceeding at reduced speed until they reached the next signal. Train 59(03) was delayed holding at MP402.5 north of Fulton KY station while CN worked to restore the PTC outage.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(03)	49"	
59(03)	1'18"	

Train 22(03) South of Texarkana, AR - Freight Train Interference

04SEP26: Train 22(03) was delayed beginning at MP49.4, 49.71 miles south of Texarkana AR station on the UPRR Little Rock subdivision following a KCS freight train.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(03)	32"	

Train 319(03) Warrensburg, MO - Freight Train Interference

04SEP26: Train 319(03) was delayed departing Warrensburg MO station/MP218.5 on the UPRR Sedalia subdivision following UP freight train 6797. Train 319(03) followed the freight until Lee's Summit MO. station/MP259.9.

Train 7(03) East of St. Paul-Minneapolis, MN - Freight Train Interference

04SEP26: Train 7(03) was delayed beginning at MP406.59, 18.26 miles east of St. Paul-Minneapolis MN station on the BNSF St. Paul subdivision following CPKC freight train 149.

Train	Delay	Comment
7(03)	35"	

Train 355(03) East Hammond-Whiting, IN - Freight Train Interference

04SEP26: Train 355(03) was delayed beginning at MP487, 21.20 miles east of Hammond-Whiting IN station on the Norfolk Southern Chicago 76 subdivision following Norfolk Southern freight train 267(03). Train 355(03) followed the freight until MP506.

Train	Delay	Comment
355(03)	34"	

Train 354(03) West of Battle Creek, MI - Passenger Train Interference

03SEP26: Train 354(03) was delayed holding at MP121.4, .3 miles west of Battle Creek MI station on the Michigan line for a meet with Amtrak train 355(03). Train 354(03) was back on the move at 1034PM ET after train 355(03) cleared to the west.

Train	Delay	Comment
354(03)	34"	

Train 777(03) South of Goleta, CA - Engine Failure

03SEP26: Train 777(03) E/C2116, 6 cars, "UNCLASSIFIED" passengers onboard, was delayed 6.2 miles south of Goleta, CA at MP351.7 on the UPRR Santa Barbara Subdivision due to engine E/C2116 shut down, showing faults and Head-end power (H.E.P.) was active during this time. The crew worked with mechanical to recycle the engine in order to resolve the faults and was able to proceed. The train came to a stop just 8 miles later at MP343.6, reporting the engine shutdown with multiple faults showing, and no H.E.P. The weather was a reported 65 degrees and clear. The crew continued to work with Lester mechanical in order to help troubleshoot the issue. The crew was able to restore H.E.P. after approximately 20 minutes, however the issue was determined to be a high voltage ground fault and the train was unable to proceed. Due to this, Train 777(03) reversed back to Goleta where they waited for Train 785(03) to arrive and continue as Train 777(03) into San Luis Obispo.

While the train waited for 785(03) to arrive, initially estimated 10:08PM-PT, all doors remained open at the platform to allow passengers to step off the train. Complimentary snacks, coffee and bottled water were distributed as service recovery.

Train 785(03) was operating on-time when they were stopped at MP385 for a police hold on the tracks south of Carpinteria, CA at MP372.01 account of a reported trespasser in the area. The train was later advanced to Carpinteria and held there. This hold considerably lengthened the delay to 777(03) that were waiting at Goleta for 785(03)'s arrival. Once the tracks were released, 785(03) was able to proceed.

Train 777(03) discharged passengers to the platform, and then parked the equipment into the Goleta spur, just prior to 785(03) arrival. Once all of 785(03) passengers detrained, and all 777(03) boarded, Train 777(03) departed Goleta for a second time, operating 5 hours and 49 minutes late.

Due to this, the following adjustments were necessary: Train 785 equipment continued as 777(03) to SOL, then represented train 774(04). The original 777 equipment will be added to inbound 761(04) at GTA then will operate as a double-set train 782(04) GTA to LAX, where the 777 set will be set-out. Train 770(04) to originate at LAX off inbound 567, cancelled between GTA-LAX. Affected passengers accommodated on Train 774(04). Comet sets will be utilized for trains 572(04) and 587(04) offering no business class seating.

Train	Delay	Comment
777(03)	5'14"	
785(03)	1'33"	Police Hold
770(04)	Originates LAX	

Train 41(03) Chicago, IL - Engine Failure

03SEP26: Train 41(03) was delayed departing initial terminal of Chicago IL station/MP0.0 due to needing an engine off late arriving train 22(02). Engine 10 was cut off train 22(02) upon arrival to Chicago IL station at 408PM CT. Engine 10 was added to the trail position of train 41(03) at 552PM CT and was released by mechanical at 708PM CT. Train 41(03) arrived to the station at 724PM CT and departed after boarding all 200 passengers at 800PM CT.

Train	Delay	Comment
41(03)	1'20"	

Train 352(03) West of Dearborn, MI - Debris

03SEP26: Train 352(03) was delayed hold at MP11.8, 2.4 miles west of Dearborn MI station on the Amtrak Michigan line due to a tree on down on the tracks. Mow responded to the scene and removed the tree that was blocking the route. Train 352(03) was back on the move at 916PM ET.

Train	Delay	Comment
-------	-------	---------

Train 822(03) South of Gainesville, TX - Freight Train Interference

03SEP26: Train 822(03) was delayed holding at the Pottsville siding/MP378.3, 32.5 miles south of Gainesville, TX station on the BNSF Ft. Worth subdivision meeting BNSF freight train 7156. Train 822(03) was back on the move at 724PM CT after the freight cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
822 (03)	30"	

Train 822(03) South of Gainesville, TX - Routing

03SEP26: Train 822(03) was delayed beginning at MP353.3, 57.3 miles south of Gainesville, TX station on the BNSF Ft. Worth subdivision due to a switch that wouldn't hand line. Train 822(03) had to reverse to MP350.5 to cross over because the switch wouldn't hand line.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
822 (03)	50"	

Train 355(03) East of Ann Arbor, MI - Debris

03SEP26: Train 355(03) was delayed holding MP24.5, 14 miles east of Ann Arbor MI station on the Amtrak Michigan line due to trees down on the tracks at MP27. Maintainers were on site when 355(03) came to a stop working to remove the trees. Train 355(03) was back on the move at 738PM ET after the trees were removed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355 (03)	41"	

Train 5(01) East of Martinez, CA - Drawbridge Opening

03SEP26: Train 5(01) was delayed at Benicia, MP 35/UPRR Martinez Subdivision, 3 miles east of Martinez, CA station, as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5 (01)	30"	

Train 355(03) East of Ann Arbor, MI - Passenger Train Interference

03SEP26: Train 355(03) was delayed holding at MP28.2, 9.2 miles east of Ann Arbor MI station on the Amtrak Michigan Line meeting Amtrak train 352(03). Train 355(03) was back on the move at 825PM ET after train 352(03) cleared to the east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355 (03)	53"	

Train 1333(03) east of St. Paul-Minneapolis, MN - Freight Train Interference

03SEP26: Train 1333(03) was delayed beginning at MP390, east of St Paul-Minneapolis, MN station on the CPKC River subdivision following BNSF freight train 964.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333 (03)	30"	

Train 3(03) East of Galesburg, IL - Debris

03SEP26: Train 3(03) was delayed at MP176.6 of Galesburg, IL station on the BNSF Chillicothe subdivision after striking a rail tie. The ATS Bar was damaged in the strike and was condemnable. Train 3(03) was met by BNSF mechanical responders upon arrival to Galesburg IL station and the ATS Bar was cut off. Train 3(03) was back on the move at 518PM CT with the ATS bar removed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(03)	33"	

Train 718(03) Originated at Emeryville, CA - Third Party Contractor Engine Failure

03SEP26: Train 718(03) operating with E/C2013, 7 cars, CC/C8309, was initially delayed departing Oakland, CA due to a late release from Oakland Mechanical facility due to servicing of the equipment. The train was then reported to have door light issues on CC/C8309. TASI mechanical continued to work to troubleshoot the issue. Unable to resolve, inbound 715's equipment with CC/C6963, 7 cars and E/C2004, was utilized to represent Train 718(03). The plan was to service and fuel the equipment, then originate Train 718(03) at Emeryville to help minimize passenger delay. All affected passengers were accommodated onto Train 544(03) between Oakland and Emeryville. After fueling the equipment, the train was further delayed due to a radio issue on CC/C6963. Technicians were able to resolve this issue due to the radio being in an incorrect mode. The equipment was then released to the crew, and during the class II air test, the equipment had main reservoir pressure issues, which further delayed the mechanical release from Oakland Maintenance facility. The crew continued to work with TASI mechanical in order to resolve the issue. Once resolved, the train was released and proceeded to Emeryville station to load 63 customers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(03)	3'45"	Originated EMY

Train 25(03) North of Pascagoula, MS - Freight Train Interference

03SEP26: Train 25(03) was delayed holding at MP701.1, north of Pascagoula, MS station/MP706.6 on the CSX NO and M subdivision meeting CSX freight train L800. Train 25(03) was back on the move at 538PM CT after the freight cleared to the north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(03)	40"	

Train 20(03) South of Meridian, MS - Freight Train Interference

03SEP26: Train 20(03) was delayed beginning at MP0.4, south of Meridian MS station/MP295 on the Norfolk Southern NO and NE subdivision following Norfolk Southern freight train 344. Train 20(03) followed the freight train until MP257 and resumed operating track speed after getting around the freight.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(03)	32"	

Train 8/28(02) West of Glasgow, MT - Freight Train Interference

03SEP26: Train 8/28(02) was delayed at Tampico / MP 288.0, on the Burlington Northern Santa Fe Milk River Subdivision, 11 miles west of the Glasgow, MT station, due to meeting freight units BN7091 and BN5534.

Train 22(03) East of Dallas, TX - Heat Orders

03SEP26: Train 22(03) was delayed departing 22 miles east of Dallas, TX (MP214.4), on the UPRR Mineola Subdivision, due to level 2 heat restrictions in effect from 12:00PM to 9:00PM. The heat order limits extended from Terrell (MP182.4) to Greggton (MP95.7), resulting in reduced operating speeds through the affected territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(03)	26"	

Train 3(01) Riverside-Downtown, CA - Injured or Sick Passenger or Employee

03SEP26: Train 3(01) was delayed departing Riverside-Downtown, CA on the BNSF San Bernardino Subdivision holding for EMS for a customer on board. The crew held for EMS to arrive and assist the customer that reportedly suffered a heart attack. The train was further delayed waiting for police to remove a disorderly passenger then for the train to be re-crewed at Riverside before departing.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(01)	30"	Police Removal
3(01)	42"	EMS
3(01)	34"	Re-crew

Train 22(03) Fort Worth, TX - Servicing

03SEP26: Train 22(03) was delayed departing Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision after waiting for the fuel vendor to complete locomotive fueling.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(03)	45"	

Train 21(02) Fort Worth, TX - Servicing / Freight Interference

03SEP26: Train 21(02) was delayed at Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision, while mechanical forces completed routine inspections and fueled the locomotives. After servicing was completed, additional delay was incurred while waiting for UP 4804 to clear at Tower 55 before the train proceeded south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(02)	29"	Servicing
21(02)	13"	Cross Traffic

Train 8/28(01) East of Fargo, ND - M of W Work

03SEP26: Train 8/28(01) was delayed 60.4 miles east of Fargo, ND (MP23.4), on the BNSF Staples Subdivision at MP214.1 while waiting for Maintenance of Way forces to clear multiple trains through the working limits between MP214.1 and MP203.1. Once authorized to proceed, Train 8/28(01) followed an eastbound BNSF freight train until able to pass it at MP196.0, resulting in additional freight interference.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(01)	35"	MOW
8/28(01)	08"	Follow

Train 8/28(02) West of Havre, MT - Freight Train Interference

03SEP26: Train 8/28(02) was delayed 30" at MP 989.7, 28 miles west of Havre, MT, on the BNSF Hi Line Subdivision due to meet with BN4251. Once BN4251 cleared, the crew advanced to Burnham/MP 971 where it was further delayed holding for BN6937/

Train	Delay	Comment
8/28(02)	30"	

Train 22(03) South of Fort Worth, TX - Freight Train Interference

03SEP26: Train 22(03) was delayed 0.9 miles south of Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision, at MP345.3 waiting on UP 8021 to clear at Tower 55.

Train	Delay	Comment
22(03)	32"	

Train 3(01) West of Barstow, CA - Freight Train Interference

03SEP26: Train 3(01) was delayed starting at MP 6.79, 6 miles east of Barstow, CA, on the BNSF Cajon Subdivision due to freight interference. The crew followed freight from MP 6.79 to MP 21 where they were able to operate around. The crew was further delayed starting at MP 32 where they followed an unknown BNSF freight until MP 34 where they were held for another BNSF to clear ahead. Once all freight was clear, Train 3(01) proceeded into Victorville. CA/ MP 36.7. Train 3(01) was further delays west of Victorville starting at MP 36.7 until MP 62.8 following a BNSF freight.

Train	Delay	Comment
3(01)	49"	VRV-SNB
3(01)	38"	BAR-VRV

Train 49/449(02) West of Elkhart, IN - Police Related

03SEP26: Train 49/449(02) stopped 4.5 miles west of Elkhart, IN (MP421.6), on the NSRR Chicago Line at MP426.1 due to a police hold for a reported trespasser on the tracks ahead. Once the police hold was released, Train 49/449(02) was authorized to proceed and continued its trip to Chicago.

Train	Delay	Comment
49/449(02)	38"	

Train 365(03) Battle Creek, MI - ITCS Failure

03SEP26: Train 365(03), E/ID4621-6 Cars-E/ID4630, reported an L55 code on the ITCS at Battle Creek, MI (MP175.7) on the CNRR South Bend Subdivision prior to entering Amtrak Michigan Line territory. As a result, Train 365(03) was reduced to a maximum speed of 59MPH on the Amtrak Michigan Line from Gord (MP121.4) to Porter (MP240.57).

Train	Delay	Comment
365(03)	40"	

Train 58(03) South of Hammond, LA - Passenger Train Interference

03SEP26: Train 58(03) held 16.1 miles south of Hammond, LA (MP859.1), on the CNRR McComb Subdivision, at Manchac (MP875.2) in order to meet Train 59(02).

Train	Delay	Comment
58(03)	22"	

Train 24(03) South of Biloxi, MS - Police Related

03SEP26: Train 24(03) held 6.1 miles south of Biloxi, MS (MP726.95), on the CSX NO&M Subdivision due to a police hold at MP722. Once the hold was released, Train 24(03) was authorized to continue north toward Mobile.

Train	Delay	Comment
24(03)	36"	

Train 516(03) Seattle, WA - Engine Failure

03SEP26: Train 516(03), E/186-3 cars-CC/90252, was delayed departing Seattle, WA due to wiper blade issues on E/186. The consist was unable to be wyed due to CC/90252 being bad ordered and cannot lead. The crew held while mechanical addressed the wiper blade issue. Once issue was resolved, and equipment was released from mechanical, Train 516(03) departed Seattle.

Train	Delay	Comment
516(03)	1'09"	

Train 523(03) East of Martinez, CA - Drawbridge Opening

03SEP26: Train 523(03) was delayed at MP 35.4, 4 miles east of Martinez, CA, on the UPRR Martinez Subdivision as a result of the Suisun Drawbridge being raised for maritime traffic to pass. Train 520(03) was held at MP 32.7. Once all maritime traffic cleared, and the bridge was lowered, all rail traffic resumed.

Train	Delay	Comment
523(03)	30"	
520(03)	27"	

Train 2/422(02) East of Yuma, AZ - Freight Train Interference

03SEP26: Train 2/422(02) was delayed starting at MP 732.7/ Yuma, AZ on the UPRR Gila Subdivision due to freight interference. The crew followed UP8746 from MP 732.7 to Colfred/ MP 783.1. Once around the freight, Train 2/422(02) was further delayed operating at restricted speed from MP 798.1 to MP 814.25. Once through the affected area, the crew proceeded at track speed.

Train	Delay	Comment
2/422(02)	1'26"	UP8746
2/422(02)	47"	Speed restrictions

Train 7/27(02) West of Rugby, ND - Flash Flood

03SEP26: Train 7/27(02) was delayed starting 12.8 miles west of Rugby, ND (MP142.2), on the BNSF Devils Lake Subdivision, due to flash flood warnings in effect from MP155 to MP196.3.

Train	Delay	Comment
7/27(02)	1'15"	

Train 2/422(02) West of Yuma, AZ - Freight Train Interference

03SEP26: Train 2/422(02) was delayed starting at Glamis/MP 698.7, 34 miles west of Yuma, AZ, on the UPRR Yuma Subdivision due to freight interference. The crew was delayed holding at MP 698.7 for meet with UP5665. Once UP5665 cleared, the crew was further delayed at Araz/MP 723.7 after following UP5609.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422 (02)	26"	UP5609
2/422 (02)	23"	UP5665

Train 3(01) East of Flagstaff, AZ - Freight Train Interference

03SEP26: Train 3(01) was delayed starting at East Canyon Diablo/MP 311.9, 33 miles east of Flagstaff, AZ, on the BNSF Seligman Subdivision due to freight interference. The crew followed a BNSF freight from MP 311.9 to Mc Phetridge/ MP 338.4 where it was able to operate around.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3 (01)	50"	

Train 6(02) East of Elko, NV - Freight Train Interference

03SEP26: Train 6(02) was delayed at Cliffside/MP781.4, 114 miles east of Elko, NV, on the UPRR Shafter Subdivision due to freight interference. The crew held for UP7038 to clear then was further delayed holding for Train 5(01). Once route was clear, Train 6(02) proceeded east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(02)	15"	Hold for 5(01)
6(02)	17"	Hold for UP7038

Train 49/449(02) East of Erie, PA - Tree on Tracks

03SEP26: Train 49/449(02) with 236 customers was delayed on the CSX Erie West subdivision six miles east of Erie at CD 81.0 due to a large tree across both tracks at MP 84.8 that required a logging company for removal. Once a route was established, Train 49/449(20) was released to continue west following a CSX freight train until they were able to get around at MP111. Additional delay was incurred at Toledo, OH (MP288.3) on the NSRR Chicago Line while awaiting the crew to come on duty at 11:48AM-ET and also police to respond and remove an unruly customers onboard.

Train 48/448(02) held 26.2 miles west of Erie, PA (MP86.9), on the CSX Erie Subdivision, at CP113 (MP113.1) in order to meet Train 49/449(02).

WBS#: B.TR.100150.7137

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
49/449(02)	1'03"	Follow
48/448(02)	35"	
49/449(02)	3'32"	Tree Down
49/449(02)	26"	TOL - Crew
49/449(02)	25"	TOL - Police Removal

Train 40(01) West of Pittsburgh, PA - Cab Signal Failure

03SEP26: Train 40(01) 28-ED1-00731-00000008774 ten UNCLASSIFIED and 157 customers was delayed on the NS Pittsburgh East district starting five miles west of Pittsburgh due to the crew cutting out cab signals and operating on C lights between Bell/MP 4.8 and Cleveland/MP 181.6. The crew was restricted to 20mph between MP 74.0 through MP 86.0 as well as MP 94.0 through MP 102.0 due to PTC showing as interlocking.

Train	Delay	Comment
40(01)	1'49"	PGH-CLE

Union Pacific Sedalia, Jefferson City, Springfield and Joliet Subdivision Kansas City, MO to St. Louis, MO to Joliet, IL - Heat Restrictions

31AUG26: Union Pacific placed Level 2 heat restrictions on the entire Sedalia and Jefferson City Sub division from Kansas City, MO and St. Louis, MO. Trains were limited to 40mph. Train 311(31), 316(31), 318(31), and Train 319(31) were delayed account of the restrictions.

01SEP26: Union Pacific also added Level 2 heat restrictions on the Joliet and Springfield Subdivision from St. Louis, MO and Joliet, IL. Trains were limited to 50mph through 02SEP.

03SEP26: Continued Union Pacific Level 2 heat restrictions on the Joliet, Springfield, Sedalia and Jefferson City Subdivision.

WBS#: B.TR.100150.7132

Train	Delay	Comment
316(31)	31"	
319(31)	32"	
318(31)	14"	
311(31)	12"	
301(01)	1'30"	JOL to STL
302(01)	1'04"	LCN to JOL
311(01)	51"	HEM to KCY
305(01)	1'05"	JOL-LCN
22(31)	1'02"	ALN-JOL
307(01)	20"	JOL-DWT
21(01)	1'58"	JOL-ALN
306(01)	1'04"	
301(02)	1'05"	
22(01)/422(30)	1'58"	
302(02)	1'02"	
21(02)	1'57"	
319(02)	1'53"	
307(02)	24"	
305(02)	1'09"	
306(02)	1'01"	
311(02)	44"	
316(02)	36"	
318(02)	2'16"	
316(01)	28"	
318(01)	2'41"	
319(01)	2'28"	
302(03)	1'10"	
301(03)	1'35"	
311(03)	52"	
22(02)	1'52"	
319(03)	2'45"	
318(03)	3'11"	
305(03)	1'16"	
306(03)	1'08"	
307(03)	26"	
316(03)	44"	
21(03)	1'40"	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 009000087741"UNCLASSIFIED" 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (1)	RSV	UP5197	Dynamic brake	CHI	9/3/26
6 (2)	RNO	UP8997	E/139 No HEP		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00731

00000008774

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
646 (03)	HAR	Due to no cab car or cafe car, no wifi	n/a	0	630
622 (03)	HAR	Due to no cab car or cafe car, no wifi	n/a	0	630
562 (03)	LAX	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATION. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	2	90225
580 (03)	LAX	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	4	90225
98 (03)	MIA	OPERATING WITH 3 COACH DUE TO 25095 SHOPPED IN WAS BYD ELECTRICAL NO REPLACEMENT ON THE YARD. OVER CAPACITY FLO-WAS CNOC CSV WILL NEED TO REACCOMMODATE PASSENGERS.			
651 (03)	NYP	Due to no cab car or cafe car, no wifi	n/a	0	630
518 (03)	PDX	3 Amfleet coaches in lieu of talgo set. JY reduced. please downgrade overcapacity passengers.	-13 pax	13	AMFLEET SET
605 (03)	PHL	Due to no cab car or cafe car, no wifi	n/a	0	630
573 (03)	SAN	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	No impact	0	90225
591 (03)	SAN	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	1	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
505 (03)	SEA	26-FOI-00731 00000008774 "UNCLASSIFIED" 9/18/2017 3 Amfleet coaches in lieu of talgo set. JY reduced. please downgrade overcapacity passengers.	JU OVER CAP AT OLW -1	1	AMFLEET SET

Reverse Consists

Train Number	Station	Reason
95 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
136 (03)	WAS	Consist reversed Business class seat orientation may have changed At Front
85 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
113 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
125 (04)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 125(04)**
190 (03)	PHL	Consist reversed Business class seat orientation may have changed At Front
141 (04)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 141(04)**
86 (04)	NPN	Consist reversed Business class seat orientation may have changed At Front.. **Train 86(04)**
84 (03)	WAS	Consist reversed Business class seat orientation may have changed At Rear
178 (04)	RNK	Consist reversed Business class seat orientation may have changed At Front.. **Train 178(04)**
184 (03)	WAS	Consist reversed Business class seat orientation may have changed At Front.
197 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
134 (03)	WAS	Consist reversed Business class seat orientation may have changed At Front
174 (03)	WAS	Consist reversed Business class seat orientation may have changed At Front
94 (04)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 94(04)**
175 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
193 (03)	NYP	Consist reversed Business class seat orientation may have changed At Rear