



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, September 05, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/04/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/04/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	333	59	82.3%	1,315	209	84.1%	101,837	14,177	86.1%
Central Division	86.0%	59	17	71.2%	235	36	84.7%	19,430	1,811	90.7%
East Division	82.0%	181	24	86.7%	712	90	87.4%	53,532	8,224	84.6%
West Division	86.0%	93	18	80.6%	368	83	77.4%	28,875	4,142	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008775 UNCLASSIFIED Endpoint Arrival Dates through 9/4/26 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	120,567	44,912	63%	396,995	116,875	71%	33,994,129	8,704,145	74%
Northeast Corridor	81%	52,042	15,535	70%	177,829	39,115	78%	14,896,244	3,626,903	76%
Acela	83%	12,344	2,355	81%	43,811	6,093	86%	3,006,721	765,314	75%
Northeast Regional	79%	39,698	13,180	67%	134,018	33,022	75%	11,889,523	2,861,589	76%
Richmond / Newport News / Norfolk	77%	12,411	5,776	53%	37,148	15,878	57%	3,560,774	1,063,283	70%
Springfield Shuttles	89%	999	237	76%	3,092	565	82%	210,322	33,801	84%
Roanoke	79%	4,151	1,753	58%	13,672	4,098	70%	1,127,829	253,918	77%
On Spine Northeast Regional	80%	22,137	5,414	76%	80,106	12,481	84%	6,990,598	1,510,587	78%
State Supported	80%	55,066	20,330	63%	176,275	52,527	70%	14,965,212	3,263,620	78%
Borealis	80%	616	0	100%	2,343	158	93%	190,362	40,635	79%
Capitol Corridor	90%	4,288	958	78%	16,632	2,534	85%	1,248,757	166,922	87%
Carolinian	70%	1,241	1,049	15%	3,357	2,099	37%	380,742	150,218	61%
Cascades	75%	3,153	1,090	65%	9,953	3,774	62%	862,553	244,799	72%
Downeaster	82%	1,724	12	99%	6,058	12	100%	526,210	61,846	88%
Empire	78%	6,978	1,023	85%	24,046	6,120	75%	1,866,550	461,401	75%
Adirondack	72%	426	28	93%	1,490	523	65%	115,510	37,476	68%
Ethan Allen Express	70%	636	49	92%	2,251	511	77%	189,202	72,735	62%
Maple Leaf	70%	1,003	135	87%	3,434	1,320	62%	232,322	91,543	61%
New York - Albany	85%	2,930	104	96%	10,690	1,646	85%	860,123	150,202	83%
New York - Niagara Falls	75%	1,389	707	49%	5,587	2,120	62%	455,949	102,587	78%
Berkshire Flyer	60%	594	0	100%	594	0	100%	13,444	6,858	49%
Gold Runner	73%	3,920	2,817	28%	9,362	6,449	31%	839,543	315,353	62%
Heartland Flyer	70%	304	116	62%	580	250	57%	72,117	30,418	58%
Hiawatha	90%	2,122	236	89%	7,104	536	92%	591,171	64,412	89%
Illinois	78%	2,499	2,302	8%	7,535	5,417	28%	836,212	238,162	72%
Carl Sandburg / Illinois Zephyr	85%	382	245	36%	1,217	443	64%	139,030	39,803	71%
Illini / Saluki	85%	437	437	0%	2,183	1,599	27%	288,308	73,118	75%
Lincoln Service	70%	1,680	1,620	4%	4,135	3,375	18%	408,874	125,241	69%
Keystone	92%	9,549	1,024	89%	35,483	5,432	85%	2,562,091	263,193	90%
Lincoln / Missouri	70%	717	717	0%	2,026	2,021	0%	259,663	137,473	47%
Mardi Gras Service	80%	300	101	66%	882	176	80%	133,981	29,893	78%
Michigan	70%	2,458	2,096	15%	7,611	4,155	45%	680,916	229,695	66%
Blue Water	70%	563	510	9%	1,543	986	36%	160,214	66,153	59%
Pere Marquette	85%	203	0	100%	1,000	129	87%	87,519	16,487	81%
Wolverine	70%	1,692	1,586	6%	5,068	3,040	40%	433,183	147,055	66%
Missouri	80%	377	365	3%	761	719	6%	74,150	21,968	70%
Pacific Surfliner	85%	10,230	3,420	67%	30,855	7,586	75%	2,739,300	523,385	81%
Pennsylvanian	80%	1,494	852	43%	3,355	1,087	68%	296,111	56,958	81%
Piedmont	80%	1,636	829	49%	3,041	1,051	65%	373,826	95,671	74%
Vermont	75%	1,460	1,323	9%	5,291	2,951	44%	430,957	131,218	70%
Long Distance	70%	13,459	9,047	33%	42,891	25,233	41%	4,093,406	1,811,159	56%
Auto Train	70%	693	693	0%	2,610	1,325	49%	262,773	90,081	66%
California Zephyr	70%	827	463	44%	3,265	1,941	41%	324,397	127,935	61%
Cardinal	70%	0	0	-	496	398	20%	77,578	39,698	49%
City Of New Orleans	75%	785	719	8%	2,363	1,976	16%	211,764	74,216	65%
Coast Starlight	70%	1,292	136	89%	4,315	920	79%	381,488	135,618	64%
Crescent	70%	1,108	173	84%	3,127	962	69%	308,195	95,316	69%
Empire Builder	70%	1,521	1,151	24%	4,152	1,540	63%	325,303	163,125	50%
Floridian	60%	1,527	1,527	0%	5,370	4,144	23%	525,436	364,293	31%
Lake Shore Ltd	73%	1,189	850	29%	3,893	1,895	51%	326,581	100,025	69%
Palmetto	70%	858	780	9%	2,412	1,739	28%	305,582	96,517	68%
Silver Meteor	70%	997	977	2%	3,008	2,685	11%	337,510	158,145	53%
Southwest Chief	60%	926	452	51%	3,295	2,175	34%	280,679	185,880	34%
Sunset Ltd	70%	666	305	54%	869	348	60%	96,647	38,866	60%
Texas Eagle	70%	1,070	821	23%	3,716	3,185	14%	329,473	141,444	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000775 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 04, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	28,655	451,815	634	2,027,813	35,725,981	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,427	142,879	100	97,866	10,350,313	95
INFRASTRUCTURE PLANNED	135	2,478	142,879	173	118,014	10,350,313	114
FLEET RELIABILITY	90	4,554	451,815	101	324,099	35,725,981	91
TRAIN OPERATIONS	424	20,196	451,815	447	1,487,834	35,725,981	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/04/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/04/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	333	59	82.3%	1,315	209	84.1%	101,837	14,177	86.1%
Central Division	86.0%	59	17	71.2%	235	36	84.7%	19,430	1,811	90.7%
East Division	82.0%	181	24	86.7%	712	90	87.4%	53,532	8,224	84.6%
West Division	86.0%	93	18	80.6%	368	83	77.4%	28,875	4,142	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/04/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/04/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	333	59	82.3%	1,315	209	84.1%	101,837	14,177	86.1%
Central Division	86.0%	59	17	71.2%	235	36	84.7%	19,430	1,811	90.7%
CDL	95.0%	2	2	0.0%	8	3	62.5%	644	34	94.7%
CHI	86.0%	28	10	64.3%	111	20	82.0%	8,981	1,120	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	4	1	75.0%	362	39	89.2%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	4	0	100.0%	318	11	96.5%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	8	0	100.0%	656	54	91.8%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	24	2	91.7%	1,983	128	93.5%
MOE	97.5%	2	0	100.0%	8	1	87.5%	675	10	98.5%
MSP	96.5%	1	0	100.0%	4	0	100.0%	332	7	97.9%
NOL	94.5%	4	0	100.0%	16	0	100.0%	1,426	64	95.5%
OKC	97.0%	1	0	100.0%	3	0	100.0%	332	6	98.2%
PNT	88.0%	3	1	66.7%	12	1	91.7%	888	74	91.7%
PTH	93.0%	1	0	100.0%	4	0	100.0%	327	13	96.0%
QCY	91.0%	2	0	100.0%	8	1	87.5%	639	49	92.3%
SAS	90.5%	1	0	100.0%	4	1	75.0%	336	40	88.1%
STL	89.0%	4	3	25.0%	16	5	68.8%	1,312	111	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	181	24	86.7%	712	90	87.4%	53,532	8,224	84.6%
ALB	88.5%	7	0	100.0%	31	1	96.8%	2,515	189	92.5%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	20	0	100.0%	1,641	175	89.3%
BOS	85.5%	19	1	94.7%	75	2	97.3%	5,780	642	88.9%
BRK	92.5%	5	0	100.0%	20	1	95.0%	1,615	113	93.0%
BTN	82.0%	1	0	100.0%	4	1	75.0%	323	43	86.7%
CLT	91.5%	5	1	80.0%	17	2	88.2%	1,648	169	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	7	0	100.0%	655	60	90.8%
GRO	-	-	-	-	3	1	66.7%	53	12	77.4%
HAR	79.5%	13	0	100.0%	52	7	86.5%	3,759	601	84.0%
HFD	-	2	0	100.0%	8	0	100.0%	240	19	92.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	4	1	75.0%	335	41	87.8%

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/04/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	333	59	82.3%	1,315	209	84.1%	101,837	14,177	86.1%
East Division	82.0%	181	24	86.7%	712	90	87.4%	53,532	8,224	84.6%
MIA	89.5%	2	2	0.0%	8	4	50.0%	666	80	88.0%
MTR	79.0%	1	0	100.0%	4	0	100.0%	322	58	82.0%
NFK	84.5%	2	1	50.0%	8	2	75.0%	753	138	81.7%
NFL	93.5%	2	0	100.0%	8	1	87.5%	682	32	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	20	3	85.0%	1,722	290	83.2%
NPN	93.0%	2	0	100.0%	8	1	87.5%	642	52	91.9%
NYP	75.5%	52	10	80.8%	205	39	81.0%	14,134	3,096	78.1%
PGH	93.0%	1	1	0.0%	4	1	75.0%	336	24	92.9%
PHL	48.0%	5	2	60.0%	20	8	60.0%	1,715	807	52.9%
PIT	76.0%	1	1	0.0%	1	1	0.0%	25	20	20.0%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	4	1	75.0%	10	2	80.0%	1,274	56	95.6%
RNK	83.5%	2	1	50.0%	8	1	87.5%	666	94	85.9%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	4	0	100.0%	318	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	4	0	100.0%	332	12	96.4%
SFA	88.0%	1	0	100.0%	4	0	100.0%	335	47	86.0%
SPG	92.5%	5	0	100.0%	19	1	94.7%	1,981	116	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	4	0	100.0%	324	63	80.6%
WAS	84.0%	33	2	93.9%	132	10	92.4%	8,501	1,084	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	93	18	80.6%	368	83	77.4%	28,875	4,142	85.7%
ARN	92.0%	1	0	100.0%	4	0	100.0%	337	28	91.7%
BFD	79.0%	7	3	57.1%	27	10	63.0%	2,140	458	78.6%
EMY	72.0%	1	1	0.0%	4	2	50.0%	353	102	71.1%
EUG	86.5%	2	0	100.0%	7	0	100.0%	667	59	91.2%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	2	1	50.0%	11	2	81.8%	1,012	174	82.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	12	1	91.7%	43	6	86.0%	3,363	375	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	3	76.9%	51	22	56.9%	3,670	975	73.4%
PDX	86.0%	5	0	100.0%	20	4	80.0%	1,625	229	85.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/04/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/04/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	333	59	82.3%	1,315	209	84.1%	101,837	14,177	86.1%
West Division	86.0%	93	18	80.6%	368	83	77.4%	28,875	4,142	85.7%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	5	68.8%	64	14	78.1%	4,783	534	88.8%
SAN	90.5%	13	1	92.3%	52	5	90.4%	4,089	397	90.3%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	32	9	71.9%	2,585	389	85.0%
SJC	89.0%	7	1	85.7%	28	5	82.1%	2,368	234	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	12	1	91.7%	777	78	90.0%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	4	1	75.0%	316	30	90.5%
VAC	97.0%	2	0	100.0%	8	1	87.5%	661	15	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		1	1	0.0%	143	13	90.9%	2	0	100.0%	143	41	71.3%
2		2	1	50.0%	144	37	74.3%	1	0	100.0%	138	29	79.0%
3		4	1	75.0%	337	67	80.1%	4	1	75.0%	334	158	52.7%
4		4	0	100.0%	336	53	84.2%	4	2	50.0%	336	223	33.6%
5		4	1	75.0%	335	58	82.7%	4	1	75.0%	331	112	66.2%
6	421	4	2	50.0%	334	93	72.2%	4	4	0.0%	334	129	61.4%
7		4	0	100.0%	326	51	84.4%	4	0	100.0%	317	86	72.9%
8	132	4	1	75.0%	326	146	55.2%	4	2	50.0%	325	200	38.5%
11		4	2	50.0%	337	74	78.0%	4	0	100.0%	331	67	79.8%
14		4	3	25.0%	338	57	83.1%	4	0	100.0%	335	105	68.7%
19		4	1	75.0%	336	84	75.0%	4	0	100.0%	333	82	75.4%
20		4	0	100.0%	336	23	93.2%	4	1	75.0%	336	66	80.4%
21		4	0	100.0%	333	36	89.2%	4	3	25.0%	332	102	69.3%
22	188	4	1	75.0%	334	38	88.6%	4	4	0.0%	332	103	69.0%
23	181	4	1	75.0%	338	7	97.9%	4	2	50.0%	336	92	72.6%
24		4	0	100.0%	338	16	95.3%	4	1	75.0%	337	66	80.4%
25		4	0	100.0%	337	3	99.1%	4	0	100.0%	334	94	71.9%
26	39	4	0	100.0%	337	5	98.5%	4	1	75.0%	334	67	79.9%
27		4	2	50.0%	303	21	93.1%	4	0	100.0%	297	97	67.3%
28		4	0	100.0%	297	67	77.4%	4	0	100.0%	297	60	79.8%
40	355	4	2	50.0%	327	49	85.0%	4	3	25.0%	323	175	45.8%
41	237	4	3	25.0%	327	127	61.2%	4	4	0.0%	324	251	22.5%
42		4	1	75.0%	338	26	92.3%	4	0	100.0%	336	58	82.7%
43	23	4	0	100.0%	337	45	86.6%	4	3	25.0%	336	79	76.5%
48	57	4	0	100.0%	336	62	81.5%	4	2	50.0%	335	53	84.2%
49		4	0	100.0%	336	84	75.0%	4	1	75.0%	336	71	78.9%
50	111	2	0	100.0%	137	34	75.2%	2	2	0.0%	135	85	37.0%
52	50	4	0	100.0%	335	47	86.0%	4	2	50.0%	334	79	76.3%
53	99	4	1	75.0%	335	41	87.8%	4	2	50.0%	334	108	67.7%
55		4	0	100.0%	215	9	95.8%	4	0	100.0%	212	46	78.3%
56	57	4	0	100.0%	216	25	88.4%	4	3	25.0%	212	43	79.7%
58	396	4	0	100.0%	311	17	94.5%	4	4	0.0%	309	101	67.3%
59	443	4	1	75.0%	310	52	83.2%	4	3	25.0%	305	84	72.5%
63	46	4	2	50.0%	339	146	56.9%	4	4	0.0%	333	201	39.6%
64		4	0	100.0%	337	71	78.9%	4	2	50.0%	336	135	59.8%
66	31	4	1	75.0%	336	65	80.7%	4	2	50.0%	331	62	81.3%
67		3	0	100.0%	233	14	94.0%	4	0	100.0%	233	40	82.8%
68		4	0	100.0%	339	67	80.2%	4	2	50.0%	338	136	59.8%
69		4	2	50.0%	326	81	75.2%	4	1	75.0%	321	57	82.2%
71	23	4	0	100.0%	334	3	99.1%	4	1	75.0%	332	87	73.8%
72	16	4	1	75.0%	330	37	88.8%	4	1	75.0%	328	70	78.7%
73		1	0	100.0%	329	23	93.0%	1	0	100.0%	327	148	54.7%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74	30	1	0	100.0%	327	35	89.3%	1	1	0.0%	325	119	63.4%
75	38	4	2	50.0%	327	19	94.2%	4	2	50.0%	321	153	52.3%
76	14	4	0	100.0%	327	31	90.5%	4	1	75.0%	317	131	58.7%
77		4	1	75.0%	329	22	93.3%	4	1	75.0%	326	134	58.9%
78	40	4	1	75.0%	333	30	91.0%	5	2	60.0%	331	77	76.7%
78	26	4	1	75.0%	333	30	91.0%	5	2	60.0%	331	77	76.7%
79	86	4	0	100.0%	336	59	82.4%	4	4	0.0%	334	116	65.3%
80	81	4	0	100.0%	336	37	89.0%	4	2	50.0%	333	73	78.1%
84		4	0	100.0%	206	19	90.8%	4	1	75.0%	202	49	75.7%
85		4	0	100.0%	217	18	91.7%	4	2	50.0%	217	76	65.0%
86		4	0	100.0%	217	16	92.6%	4	1	75.0%	216	122	43.5%
89	85	4	0	100.0%	334	78	76.6%	4	3	25.0%	332	100	69.9%
90	213	4	0	100.0%	334	12	96.4%	4	2	50.0%	333	62	81.4%
93	52	4	0	100.0%	216	21	90.3%	4	3	25.0%	215	58	73.0%
94	32	4	1	75.0%	247	62	74.9%	4	1	75.0%	245	90	63.3%
95	147	4	1	75.0%	216	7	96.8%	4	3	25.0%	216	85	60.6%
97	96	4	3	25.0%	336	220	34.5%	4	3	25.0%	334	123	63.2%
98	220	4	2	50.0%	336	30	91.1%	4	3	25.0%	334	126	62.3%
110		4	0	100.0%	213	110	48.4%	4	0	100.0%	210	22	89.5%
111		4	0	100.0%	207	37	82.1%	4	0	100.0%	205	22	89.3%
112		4	1	75.0%	207	21	89.9%	4	0	100.0%	206	20	90.3%
113		4	0	100.0%	138	33	76.1%	4	0	100.0%	137	16	88.3%
119		4	0	100.0%	204	49	76.0%	4	0	100.0%	202	26	87.1%
125	40	4	0	100.0%	217	12	94.5%	4	2	50.0%	217	86	60.4%
129		4	1	75.0%	216	51	76.4%	4	1	75.0%	216	31	85.6%
130		4	0	100.0%	207	20	90.3%	4	0	100.0%	205	16	92.2%
131		4	0	100.0%	209	57	72.7%	4	1	75.0%	209	40	80.9%
134		4	0	100.0%	217	32	85.3%	4	0	100.0%	216	42	80.6%
136		4	1	75.0%	217	28	87.1%	4	2	50.0%	215	30	86.0%
137	42	4	0	100.0%	214	36	83.2%	4	2	50.0%	214	64	70.1%
138		4	1	75.0%	217	44	79.7%	4	1	75.0%	216	39	81.9%
141		4	1	75.0%	216	5	97.7%	4	1	75.0%	215	38	82.3%
148		4	2	50.0%	216	24	88.9%	4	0	100.0%	214	40	81.3%
151	33	4	2	50.0%	335	107	68.1%	4	1	75.0%	334	100	70.1%
170		4	0	100.0%	212	12	94.3%	4	0	100.0%	211	30	85.8%
171		4	0	100.0%	217	11	94.9%	4	2	50.0%	217	90	58.5%
172	44	4	0	100.0%	216	19	91.2%	4	2	50.0%	214	71	66.8%
173		4	0	100.0%	209	25	88.0%	4	0	100.0%	208	84	59.6%
174		4	0	100.0%	217	23	89.4%	4	1	75.0%	217	53	75.6%
175	30	4	0	100.0%	217	23	89.4%	4	2	50.0%	217	72	66.8%
176		4	0	100.0%	209	17	91.9%	4	0	100.0%	206	26	87.4%
177	93	4	0	100.0%	217	28	87.1%	4	1	75.0%	217	49	77.4%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178	25	4	0	100.0%	217	28	87.1%	4	1	75.0%	215	37	82.8%
179	18	4	0	100.0%	217	25	88.5%	4	2	50.0%	216	78	63.9%
181	17	4	1	75.0%	213	65	69.5%	4	1	75.0%	210	18	91.4%
182	64	4	0	100.0%	207	31	85.0%	4	2	50.0%	205	25	87.8%
183		4	1	75.0%	216	63	70.8%	4	0	100.0%	213	44	79.3%
184		4	0	100.0%	217	36	83.4%	4	0	100.0%	216	28	87.0%
185		4	1	75.0%	217	42	80.6%	4	0	100.0%	217	18	91.7%
186		4	1	75.0%	216	30	86.1%	4	2	50.0%	215	63	70.7%
190		4	1	75.0%	216	76	64.8%	4	0	100.0%	215	44	79.5%
192		4	0	100.0%	214	24	88.8%	4	0	100.0%	214	19	91.1%
193	33	4	2	50.0%	212	85	59.9%	4	2	50.0%	211	92	56.4%
196		4	0	100.0%	213	23	89.2%	4	0	100.0%	211	17	91.9%
197	22	4	1	75.0%	217	78	64.1%	4	3	25.0%	217	74	65.9%
198		4	2	50.0%	149	19	87.2%	4	1	75.0%	148	23	84.5%
230	18	4	0	100.0%	172	4	97.7%	4	1	75.0%	172	10	94.2%
232		4	0	100.0%	338	12	96.4%	4	1	75.0%	338	24	92.9%
234		4	0	100.0%	339	23	93.2%	4	0	100.0%	338	29	91.4%
235		4	0	100.0%	263	42	84.0%	4	0	100.0%	262	60	77.1%
236		4	0	100.0%	323	10	96.9%	4	0	100.0%	322	43	86.6%
237		4	1	75.0%	336	62	81.5%	4	1	75.0%	334	60	82.0%
238		4	0	100.0%	263	23	91.3%	4	0	100.0%	261	22	91.6%
239		4	2	50.0%	337	85	74.8%	4	0	100.0%	336	42	87.5%
240		4	0	100.0%	338	23	93.2%	4	0	100.0%	335	69	79.4%
241		4	2	50.0%	338	84	75.1%	4	2	50.0%	338	83	75.4%
243		4	1	75.0%	274	72	73.7%	4	0	100.0%	273	39	85.7%
245		4	0	100.0%	219	41	81.3%	4	0	100.0%	218	30	86.2%
280	35	4	0	100.0%	339	17	95.0%	4	2	50.0%	338	80	76.3%
281	24	4	0	100.0%	339	40	88.2%	4	1	75.0%	339	61	82.0%
283	76	4	1	75.0%	339	86	74.6%	4	4	0.0%	339	70	79.4%
284		4	1	75.0%	339	14	95.9%	4	2	50.0%	336	63	81.3%
290		4	1	75.0%	339	53	84.4%	4	1	75.0%	336	138	58.9%
291		4	0	100.0%	338	112	66.9%	4	1	75.0%	334	91	72.8%
300	Cncld	4	1	75.0%	322	23	92.9%	3	0	100.0%	318	73	77.0%
301	206	4	1	75.0%	336	11	96.7%	4	4	0.0%	332	67	79.8%
302	106	4	2	50.0%	317	36	88.6%	4	4	0.0%	313	94	70.0%
305	38	4	2	50.0%	320	33	89.7%	4	4	0.0%	315	126	60.0%
306	74	4	1	75.0%	334	18	94.6%	4	4	0.0%	332	93	72.0%
307		4	1	75.0%	327	45	86.2%	4	2	50.0%	323	100	69.0%
311	50	4	1	75.0%	331	29	91.2%	4	4	0.0%	325	88	72.9%
316	47	4	0	100.0%	327	24	92.7%	4	4	0.0%	321	105	67.3%
318	129	4	0	100.0%	337	35	89.6%	4	4	0.0%	334	170	49.1%
319	No OS	4	1	75.0%	338	21	93.8%	4	4	0.0%	333	197	40.8%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
329	19	4	0	100.0%	240	12	95.0%	4	1	75.0%	240	20	91.7%
330		4	1	75.0%	288	7	97.6%	4	1	75.0%	288	16	94.4%
331		4	1	75.0%	339	34	90.0%	4	1	75.0%	338	45	86.7%
332	22	4	1	75.0%	338	20	94.1%	4	2	50.0%	338	48	85.8%
334		4	0	100.0%	339	11	96.8%	4	0	100.0%	337	43	87.2%
335		4	0	100.0%	339	35	89.7%	4	0	100.0%	336	55	83.6%
336	12	4	0	100.0%	338	10	97.0%	4	1	75.0%	336	30	91.1%
337		4	0	100.0%	339	21	93.8%	4	0	100.0%	335	47	86.0%
338		4	0	100.0%	339	54	84.1%	4	0	100.0%	336	104	69.0%
339		4	0	100.0%	339	54	84.1%	4	0	100.0%	339	58	82.9%
341		4	0	100.0%	324	51	84.3%	4	0	100.0%	318	53	83.3%
342		4	0	100.0%	339	26	92.3%	4	2	50.0%	337	63	81.3%
350	117	4	1	75.0%	314	21	93.3%	4	3	25.0%	306	177	42.2%
351	16	4	0	100.0%	321	29	91.0%	4	3	25.0%	319	95	70.2%
352	34	4	0	100.0%	305	24	92.1%	4	4	0.0%	299	97	67.6%
353	118	4	1	75.0%	276	15	94.6%	4	2	50.0%	270	51	81.1%
354	77	4	1	75.0%	320	38	88.1%	4	2	50.0%	312	118	62.2%
355	129	4	0	100.0%	327	37	88.7%	4	2	50.0%	318	121	61.9%
364	156	4	1	75.0%	328	74	77.4%	4	3	25.0%	322	123	61.8%
365	232	4	0	100.0%	327	13	96.0%	4	2	50.0%	324	126	61.1%
370	192	4	1	75.0%	325	40	87.7%	4	1	75.0%	312	76	75.6%
371		4	0	100.0%	318	11	96.5%	4	1	75.0%	314	31	90.1%
380	54	4	0	100.0%	320	30	90.6%	4	1	75.0%	319	73	77.1%
381		4	0	100.0%	335	15	95.5%	4	0	100.0%	332	71	78.6%
382	31	4	1	75.0%	334	31	90.7%	4	3	25.0%	332	119	64.2%
383	208	4	2	50.0%	325	29	91.1%	3	1	66.7%	321	139	56.7%
390	263	4	1	75.0%	320	25	92.2%	4	3	25.0%	318	89	72.0%
391	208	4	0	100.0%	321	14	95.6%	4	4	0.0%	316	92	70.9%
392	175	4	2	50.0%	334	13	96.1%	3	3	0.0%	328	106	67.7%
393	193	4	2	50.0%	338	21	93.8%	3	3	0.0%	333	107	67.9%
417		4	0	100.0%	225	47	79.1%	4	0	100.0%	216	25	88.4%
425		3	0	100.0%	227	7	96.9%	3	0	100.0%	226	7	96.9%
448	88	4	2	50.0%	263	51	80.6%	4	2	50.0%	259	91	64.9%
449		4	0	100.0%	260	34	86.9%	4	0	100.0%	260	45	82.7%
470	31	4	1	75.0%	240	41	82.9%	4	2	50.0%	234	29	87.6%
471		4	0	100.0%	229	14	93.9%	4	0	100.0%	229	6	97.4%
473		4	0	100.0%	236	15	93.6%	4	0	100.0%	233	10	95.7%
474		4	0	100.0%	232	66	71.6%	4	1	75.0%	217	72	66.8%
475		3	0	100.0%	232	8	96.6%	3	0	100.0%	232	16	93.1%
478		4	1	75.0%	228	37	83.8%	4	1	75.0%	226	29	87.2%
479		4	0	100.0%	235	36	84.7%	4	0	100.0%	233	36	84.5%
486		4	0	100.0%	239	35	85.4%	4	0	100.0%	233	61	73.8%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
494	23	4	1	75.0%	242	48	80.2%	4	3	25.0%	234	67	71.4%
495		4	0	100.0%	223	4	98.2%	4	0	100.0%	221	3	98.6%
500		4	1	75.0%	313	17	94.6%	4	1	75.0%	310	37	88.1%
502		4	0	100.0%	321	19	94.1%	4	1	75.0%	317	62	80.4%
503		4	2	50.0%	335	42	87.5%	3	0	100.0%	327	102	68.8%
504		4	0	100.0%	339	20	94.1%	4	1	75.0%	337	100	70.3%
505	32	4	1	75.0%	331	44	86.7%	4	4	0.0%	326	95	70.9%
506		4	1	75.0%	334	57	82.9%	3	1	66.7%	325	52	84.0%
507	63	4	0	100.0%	339	49	85.5%	4	2	50.0%	339	117	65.5%
508		3	0	100.0%	333	43	87.1%	3	1	66.7%	329	82	75.1%
509		4	1	75.0%	320	16	95.0%	4	1	75.0%	320	72	77.5%
511	18	4	1	75.0%	315	26	91.7%	4	1	75.0%	314	54	82.8%
516		4	1	75.0%	330	36	89.1%	4	2	50.0%	329	148	55.0%
517	24	4	0	100.0%	339	8	97.6%	4	2	50.0%	335	152	54.6%
518	60	4	2	50.0%	339	48	85.8%	4	4	0.0%	337	236	30.0%
519	25	4	1	75.0%	330	10	97.0%	4	3	25.0%	328	75	77.1%
520		4	1	75.0%	198	30	84.8%	4	1	75.0%	193	12	93.8%
521	11	4	1	75.0%	236	8	96.6%	4	1	75.0%	235	32	86.4%
522		4	1	75.0%	236	44	81.4%	4	0	100.0%	233	24	89.7%
523	34	4	0	100.0%	236	9	96.2%	4	2	50.0%	235	28	88.1%
524	17	4	1	75.0%	235	18	92.3%	4	1	75.0%	232	28	87.9%
525		4	1	75.0%	233	17	92.7%	3	0	100.0%	228	15	93.4%
526		4	1	75.0%	210	42	80.0%	3	0	100.0%	206	18	91.3%
527		4	0	100.0%	236	10	95.8%	4	0	100.0%	234	40	82.9%
528		4	0	100.0%	236	19	91.9%	4	1	75.0%	235	33	86.0%
529		4	0	100.0%	236	13	94.5%	4	0	100.0%	235	65	72.3%
530	Cncld	4	1	75.0%	190	19	90.0%	3	0	100.0%	189	38	79.9%
531		4	1	75.0%	210	15	92.9%	4	1	75.0%	210	14	93.3%
532		4	2	50.0%	236	59	75.0%	4	1	75.0%	234	36	84.6%
534		4	2	50.0%	195	30	84.6%	4	0	100.0%	192	17	91.1%
535		4	1	75.0%	222	27	87.8%	4	0	100.0%	217	28	87.1%
536		4	2	50.0%	236	66	72.0%	4	1	75.0%	232	42	81.9%
537		4	2	50.0%	205	26	87.3%	4	0	100.0%	199	25	87.4%
538		4	1	75.0%	236	27	88.6%	4	0	100.0%	235	46	80.4%
539	14	4	0	100.0%	190	28	85.3%	4	2	50.0%	190	84	55.8%
540		4	1	75.0%	235	45	80.9%	4	1	75.0%	225	22	90.2%
541		4	1	75.0%	235	26	88.9%	4	1	75.0%	228	42	81.6%
542		4	0	100.0%	235	25	89.4%	4	1	75.0%	232	42	81.9%
543	60	4	2	50.0%	236	30	87.3%	4	3	25.0%	236	76	67.8%
544		4	0	100.0%	234	22	90.6%	4	0	100.0%	230	22	90.4%
545	55	4	2	50.0%	236	22	90.7%	4	1	75.0%	233	30	87.1%
547	157	4	2	50.0%	236	49	79.2%	4	1	75.0%	236	55	76.7%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
548		3	0	100.0%	227	22	90.3%	3	0	100.0%	224	17	92.4%
549		4	0	100.0%	231	27	88.3%	4	0	100.0%	221	20	91.0%
550		4	2	50.0%	190	22	88.4%	4	1	75.0%	190	45	76.3%
551		4	0	100.0%	232	23	90.1%	4	0	100.0%	222	23	89.6%
562		4	0	100.0%	330	27	91.8%	4	0	100.0%	325	37	88.6%
564		4	0	100.0%	331	19	94.3%	4	1	75.0%	323	44	86.4%
566		4	1	75.0%	329	30	90.9%	4	1	75.0%	326	55	83.1%
567		4	0	100.0%	216	11	94.9%	4	0	100.0%	214	14	93.5%
572	83	4	0	100.0%	326	27	91.7%	4	2	50.0%	318	97	69.5%
573		4	0	100.0%	328	44	86.6%	4	0	100.0%	320	58	81.9%
579		4	0	100.0%	216	14	93.5%	4	1	75.0%	209	46	78.0%
580		4	1	75.0%	331	19	94.3%	4	1	75.0%	324	38	88.3%
581		4	0	100.0%	331	58	82.5%	4	2	50.0%	328	77	76.5%
584	36	4	0	100.0%	215	32	85.1%	4	3	25.0%	208	135	35.1%
587	25	4	0	100.0%	323	21	93.5%	4	1	75.0%	314	66	79.0%
588		4	0	100.0%	214	23	89.3%	4	0	100.0%	212	43	79.7%
591		4	1	75.0%	328	27	91.8%	4	1	75.0%	321	50	84.4%
593		4	1	75.0%	321	54	83.2%	4	2	50.0%	298	43	85.6%
595		4	2	50.0%	324	62	80.9%	4	0	100.0%	321	73	77.3%
600		4	0	100.0%	244	9	96.3%	4	1	75.0%	242	23	90.5%
601		4	1	75.0%	227	91	59.9%	4	1	75.0%	224	28	87.5%
605	23	4	4	0.0%	234	143	38.9%	3	1	66.7%	229	24	89.5%
607		4	1	75.0%	243	31	87.2%	4	1	75.0%	240	26	89.2%
609		4	0	100.0%	234	23	90.2%	4	0	100.0%	233	23	90.1%
626		4	0	100.0%	148	20	86.5%	4	0	100.0%	146	18	87.7%
639		4	0	100.0%	214	40	81.3%	4	0	100.0%	212	20	90.6%
640		4	1	75.0%	234	8	96.6%	4	1	75.0%	232	85	63.4%
641	23	4	1	75.0%	216	44	79.6%	4	3	25.0%	216	30	86.1%
642		4	1	75.0%	232	12	94.8%	4	0	100.0%	231	27	88.3%
643		4	1	75.0%	246	45	81.7%	4	1	75.0%	243	40	83.5%
644	14	4	0	100.0%	238	28	88.2%	4	2	50.0%	236	58	75.4%
645		4	0	100.0%	246	42	82.9%	4	0	100.0%	243	55	77.4%
646		4	3	25.0%	235	59	74.9%	4	2	50.0%	233	115	50.6%
647		4	2	50.0%	246	37	85.0%	4	1	75.0%	244	52	78.7%
648		4	1	75.0%	242	60	75.2%	4	1	75.0%	242	36	85.1%
649	19	4	2	50.0%	247	46	81.4%	4	1	75.0%	243	35	85.6%
650		4	0	100.0%	246	45	81.7%	4	1	75.0%	243	40	83.5%
651		4	0	100.0%	246	17	93.1%	4	0	100.0%	243	43	82.3%
652	11	4	0	100.0%	247	31	87.4%	4	2	50.0%	243	43	82.3%
653	21	4	2	50.0%	235	38	83.8%	4	2	50.0%	231	43	81.4%
654		4	0	100.0%	236	44	81.4%	4	0	100.0%	232	20	91.4%
655		4	2	50.0%	244	76	68.9%	4	2	50.0%	241	78	67.6%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
656		4	1	75.0%	246	55	77.6%	4	0	100.0%	244	33	86.5%
657		4	0	100.0%	235	29	87.7%	4	1	75.0%	233	31	86.7%
658		4	0	100.0%	246	37	85.0%	4	0	100.0%	244	35	85.7%
680		4	0	100.0%	241	12	95.0%	4	0	100.0%	239	27	88.7%
681	11	4	0	100.0%	241	18	92.5%	4	1	75.0%	234	94	59.8%
682		4	1	75.0%	240	10	95.8%	4	0	100.0%	240	42	82.5%
683	14	4	0	100.0%	223	18	91.9%	4	1	75.0%	222	76	65.8%
684	12	4	0	100.0%	222	37	83.3%	4	1	75.0%	222	48	78.4%
685		4	0	100.0%	237	33	86.1%	4	0	100.0%	234	55	76.5%
686	13	4	0	100.0%	242	39	83.9%	4	1	75.0%	241	53	78.0%
687		4	0	100.0%	241	38	84.2%	4	0	100.0%	240	40	83.3%
688		4	0	100.0%	240	15	93.8%	4	0	100.0%	239	41	82.8%
689		3	0	100.0%	158	21	86.7%	2	0	100.0%	156	23	85.3%
701		4	0	100.0%	271	30	88.9%	4	1	75.0%	268	33	87.7%
702		4	0	100.0%	338	36	89.3%	4	3	25.0%	335	86	74.3%
703	No OS	4	3	25.0%	339	115	66.1%	4	3	25.0%	337	103	69.4%
704	16	4	1	75.0%	270	50	81.5%	4	3	25.0%	262	62	76.3%
710	45	4	1	75.0%	339	80	76.4%	3	2	33.3%	334	90	73.1%
711		4	1	75.0%	330	39	88.2%	4	1	75.0%	307	66	78.5%
712	48	4	2	50.0%	336	93	72.3%	4	3	25.0%	326	117	64.1%
713	83	3	2	33.3%	205	22	89.3%	2	2	0.0%	179	82	54.2%
714	106	4	3	25.0%	220	95	56.8%	4	4	0.0%	204	99	51.5%
715	47	4	1	75.0%	338	64	81.1%	3	3	0.0%	308	158	48.7%
716	58	4	2	50.0%	339	145	57.2%	4	4	0.0%	330	145	56.1%
717		4	2	50.0%	324	81	75.0%	4	2	50.0%	299	100	66.6%
718	224	4	4	0.0%	339	182	46.3%	4	4	0.0%	336	133	60.4%
719		4	1	75.0%	339	114	66.4%	4	1	75.0%	322	99	69.3%
757		4	0	100.0%	124	7	94.4%	4	1	75.0%	123	15	87.8%
761		4	0	100.0%	335	13	96.1%	4	0	100.0%	332	44	86.7%
765		4	0	100.0%	335	25	92.5%	4	1	75.0%	335	47	86.0%
769		4	0	100.0%	335	27	91.9%	4	1	75.0%	328	66	79.9%
770		4	0	100.0%	335	25	92.5%	4	0	100.0%	332	104	68.7%
774	56	4	0	100.0%	335	17	94.9%	4	1	75.0%	333	81	75.7%
777	22	4	0	100.0%	220	13	94.1%	4	4	0.0%	219	62	71.7%
782		4	2	50.0%	220	107	51.4%	4	1	75.0%	215	37	82.8%
785	43	4	1	75.0%	335	30	91.0%	4	2	50.0%	335	63	81.2%
786	18	4	1	75.0%	124	24	80.6%	4	2	50.0%	120	68	43.3%
790		4	0	100.0%	335	31	90.7%	4	0	100.0%	332	54	83.7%
794		4	0	100.0%	335	40	88.1%	4	0	100.0%	331	76	77.0%
821	14	3	0	100.0%	332	6	98.2%	3	2	33.3%	332	142	57.2%
822	29	4	1	75.0%	335	19	94.3%	3	3	0.0%	332	173	47.9%
1233		1	0	100.0%	25	5	80.0%	1	0	100.0%	23	13	43.5%

Amtrak On Time Performance

Trains Arriving Through: 9/4/2026

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1246		1	1	0.0%	25	20	20.0%	1	0	100.0%	25	13	48.0%
1333		4	0	100.0%	335	40	88.1%	4	1	75.0%	332	113	66.0%
1340		4	0	100.0%	334	7	97.9%	4	0	100.0%	333	56	83.2%
2102		4	0	100.0%	93	16	82.8%	4	0	100.0%	92	7	92.4%
2103	21	4	0	100.0%	157	14	91.1%	4	1	75.0%	156	11	92.9%
2104		4	0	100.0%	183	10	94.5%	4	0	100.0%	181	13	92.8%
2105		4	0	100.0%	5	1	80.0%	4	0	100.0%	5	0	100.0%
2107		3	0	100.0%	213	35	83.6%	3	0	100.0%	210	21	90.0%
2108		4	0	100.0%	214	28	86.9%	4	0	100.0%	208	27	87.0%
2109		4	0	100.0%	107	13	87.9%	4	0	100.0%	105	6	94.3%
2112		4	0	100.0%	54	6	88.9%	4	0	100.0%	52	2	96.2%
2113		4	0	100.0%	93	9	90.3%	4	0	100.0%	93	10	89.2%
2115		4	1	75.0%	93	14	84.9%	4	0	100.0%	92	12	87.0%
2116		4	0	100.0%	54	1	98.1%	4	0	100.0%	54	8	85.2%
2118		4	0	100.0%	54	4	92.6%	4	0	100.0%	54	12	77.8%
2119		4	1	75.0%	54	9	83.3%	4	1	75.0%	53	13	75.5%
2120		4	1	75.0%	54	20	63.0%	4	0	100.0%	52	23	55.8%
2123		4	2	50.0%	92	12	87.0%	4	0	100.0%	91	15	83.5%
2124		4	0	100.0%	185	38	79.5%	4	0	100.0%	183	24	86.9%
2126		4	0	100.0%	102	26	74.5%	4	0	100.0%	101	22	78.2%
2127		4	0	100.0%	54	10	81.5%	4	0	100.0%	53	9	83.0%
2128		4	1	75.0%	54	5	90.7%	4	0	100.0%	54	3	94.4%
2131		4	0	100.0%	54	10	81.5%	4	0	100.0%	54	6	88.9%
2150		4	0	100.0%	207	22	89.4%	4	0	100.0%	204	75	63.2%
2151	29	4	0	100.0%	156	7	95.5%	4	3	25.0%	154	44	71.4%
2152		4	0	100.0%	112	7	93.8%	4	0	100.0%	111	31	72.1%
2154		4	1	75.0%	115	24	79.1%	3	0	100.0%	110	45	59.1%
2155		4	0	100.0%	216	17	92.1%	4	1	75.0%	212	103	51.4%
2156	20	4	0	100.0%	5	0	100.0%	4	1	75.0%	5	1	80.0%
2158		4	0	100.0%	53	6	88.7%	4	0	100.0%	53	16	69.8%
2159	18	4	0	100.0%	209	16	92.3%	4	1	75.0%	207	70	66.2%
2160		4	1	75.0%	54	3	94.4%	4	0	100.0%	53	28	47.2%
2162		4	0	100.0%	215	23	89.3%	4	0	100.0%	209	91	56.5%
2163	20	4	0	100.0%	167	17	89.8%	4	2	50.0%	161	71	55.9%
2165		4	0	100.0%	51	4	92.2%	4	1	75.0%	51	22	56.9%
2167		4	1	75.0%	202	21	89.6%	4	1	75.0%	202	42	79.2%
2171		4	0	100.0%	143	10	93.0%	4	1	75.0%	139	24	82.7%
2190		4	0	100.0%	212	29	86.3%	4	0	100.0%	210	24	88.6%
2193		3	0	100.0%	206	26	87.4%	3	0	100.0%	204	50	75.5%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2103	WAS	21	DCS	14	DCS	14	BAL-XNY	AM	T.O.L, Control Point, ., TOL ON 3TRK SOUTH OF CP AVE.
2151	WAS	29	CTI	17	DSR	13	NHV-STM	MN	Per bulletin Speed restrictions and train congestion, Control Point, 248, 30, 2/1, Control Point, 241, 15, 2/4
2156	BOS	20	CTI	26	CTI	10	NHV-XGX	AM	Follow, CDOT, 1632, Milepost w/Letters, NHV, XGX, AM2156 followed signals of CD1632
2159	WAS	18	DSR	24	DSR	24	STM-XSH	MN	Per bulletin Milepost, 33.1, 16.6, 30, 1
2163	WAS	20	OTH	15	SMW	11	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 trk a/c 3 trk o/s between Davis & Bacon
66	BOS	31	SVS	38	SVS	38	NHV-NHV	AM	Pick up equipment, ADDED 2 ENGS
93	NFK	52	CTI	27	CTI	15	QAN-FBG	CS	Follow vre, Milepost, 78.9, 59.3
94	BOS	32	ADA	25	FTI	14	QAN-ALX	CS	Follow M416, Control Point, QAN
95	NFK	147	WTR	96	ENG	75	BOS-BOS	AM	Other electrical failure, 629 EX ES, CAB SIGNAL/ ELECTRICAL
125	NPN	40	WTR	35	ADA	18	ABE-ABE	AM	Wheelchair, needed lift for an ADA psgr
137	WAS	42	CTI	51	DBB	32	NLC-OSB	AM	Stuck open bridges, Bridge, Conn River, conn river bridge stuck open
151	RNK	33	DCS	24	RTE	16	WAS-XVG	CS	Inability to contact dispatcher, Control Point, A INTERLOCKING
172	BOS	44	DSR	24	DSR	12	STM-BRP	MN	Per bulletin Speed restrictions and train congestion, Milepost, 40.4, 41.7, 30, 1/2/4
175	WAS	30	CTI	37	CTI	19	NHV-STM	MN	Follow metro, Other, enroute
177	PHL	93	POL	76	POL	66	XHM-PHL	AM	Right of Way police hold, HELD FOR POLICE ACTIVITY. POSSIBLE SUICIDAL PASSENGER W/ KNIFE AT N. PHILA
178	BOS	25	PTI	58	PTI	33	ALX-XVG	CS	Follow po20, Milepost, 105.0, 110.0
179	PHL	18	CTI	22	SMW	11	NYP-NWK	AM	Scheduled in track usage program, Other, XBH-XHU, SINGLE TRACKING ON NO.2 TRACK A/C 3 TRK O/O/S LACK TO HUDSON.
181	WAS	17	OTH	12	DCS	11	BAL-XNY	AM	T.O.L, Control Point, ., TOL ON 3TRK SOUTH OF CP AVE.
182	BOS	64	DBB	48	DBB	48	NHV-NLC	AM	Stuck open bridges, Bridge, Conn River, conn river bridge stuck open
193	WAS	33	SMW	15	SYS	10	BWI-BWI	AM	Re-crew / job briefing

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
197	WAS	22	SMW	23	SMW	23	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 trk a/c 3 trk o/s between Davis & Bacon	
470	HFD	31	CCR	25	CCR	25	NHV-NHV	AM	Cab signal failure, 82681 AX AS, SWAP OUT EQUIPMENT IN NHV A/C CAB SIG PROBLEMS	
494	GFD	23	CON	21	CON	21	NHV-NHV	AM	Hold for connecting train, late connection of AM94	
52	LOR	50	FTI	66	DBS	34	XSA-XOU	CS	Animal strike Milepost, 410.3, 410.6	
53	SFA	99	FTI	63	FTI	28	XV7-XSE	CS	Follow IO31, Milepost, 53.3, 97.4	
79	CLT	86	PTI	54	DCS	39	BNC-GRO	NS	Dispatcher talked us past the signals doing restricted speed. Milepost, 7.8, 0.7	
80	NYP	81	WTR	65	CTI	23	ALX-XVG	CS	Blocked from station track VRE, 335, Other, CFP112.0	
605	HAR	23	SVS	24	SVS	24	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD	
641	HAR	23	ENG	34	ENG	31	PHL-PAO	AM	Undesired emergency application, 9634 CB CC, WYE OUTBOUND	
644	NYP	14	ENG	11	ENG	11	PHL-XHM	AM	Undesired emergency application, 9632 CB CC, WYE OUTBOUND	
649	HAR	19	MTI	23	MTI	23	NYP-NYP	AM	Disabled train ahead, Other, F-INT, CONGESTION AHD IN LINE 1 A/C AM97 DISABLED	
652	NYP	11	PTI	14	CTC	9	ARD-PHL	AM	PTC - Stop Bypass Permission Required, Control Point, PENN, STOP BYPASS PERMISSION MULTIPLE TIMES	
653	HAR	21	CTI	14	CTP	10	ARD-ARD	AM	Delay due to mechanical problems on a Commuter train, SEPTA 9593 STOPPED AT ARDMORE A/C FAULT THAT DOESNT ALLOW PSGR TRANSPORT; ALL PSGRS DISCHARGED. AMTRAK 653 ROUTED AROUND THEM	
681	BRK	11	PTI	16	PTI	13	POR-FRE	CS	Meet 684, Control Point, Congress	
683	BRK	14	PTI	14	PTI	14	EXR-DHM	CS	Meet 684, Control Point, Rockingham	
684	BON	12	ENG	6	ENG	4	SAO-WEM	CS	Capped at 64 mph 737	
686	BON	13	RTE	8	RTE	8	FRE-POR	CS	Dispatcher hold NAR, Control Point, Royal	
63	TWO	46	SYS	10	FTI	7	SYR-SYR	CS	Meet CSX, Control Point, 291, CSX	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
230	NYP	18	FTI	17	FTI	17	ALB-HUD	AM	Cross over or go around csx, Control Point, 124
280	NYP	35	RTE	39	RTE	21	ALB-HUD	AM	Dispatcher hold Control Point, 124
281	NFL	24	FTI	54	FTI	43	ROC-BUF	CS	Follow csx, Milepost w/Letters, 388, cp 423
283	NFL	76	POL	45	POL	45	XSV-ROC	CS	Removal of passenger by police Drunk passenger Removed at 313.8 by police
48	NYP	57	FTI	111	DCS	37	ERI-BUF	CS	Power switch failure Control Point, 434
448	BOS	7	DSR	15	POL	8	PIT-SPG	CS	Right of Way police hold Stop at CP 97
43	PGH	23	DSR	14	ENG	10	PAO-LNC	AM	HEP, 109 DX BD, LOST POWER, RECYCLED AND ON THE MOVE
71	CLT	23	FTI	26	FTI	14	SAL-KAN	NS	Follow Other, Duke to Sumner, #NS50D
72	RGH	16	FTI	14	ITI	9	CLT-CLT	NS	Service, turn, or wye train 71
74	RGH	30	PTI	32	PTI	32	BNC-DNC	NS	Meet #AMTK77, Control Point, Haw River
75	CLT	38	TEN	41	TEN	41	HPT-SAL	NS	Onboard HBD alarm Stopped to inspect no exceptions found 50 mph for 10 miles then reinspect, NC1869
76	RGH	14	DCS	20	DCS	20	GRO-DNC	NS	Restrictive signal(s) from unknown cause Clear signal at FIELDS restricting signal at 2.5 PTC put train in emergency., Restricting , Milepost, 2.5, 2.5
78	RGH	40	DCS	38	DCS	27	GRO-BNC	NS	T.O.L Talked by signal, then restricted speed to Mccleansville, Control Point, Fields
78	RGH	26	ITI	50	ITI	50	CLT-CLT	NS	Late inbound train 77
89	SAV	85	FTI	66	WTR	43	PTB-RMT	CS	Heat order Other, north end sub
90	NYP	213	WTR	84	ENG	82	WAS-WAS	AM	Set out defective locomotive, 46 DX BD, DSL ON MTR/DSL COMBO WOULD NOT ALLOW POWER TO CARS. ISSUE COULD NOT BE RESOLVED. DSL SET OFF AND MTR PUT BACK ON. 1ST H/E CHANGE 804P-815P
97	MIA	96	FTI	52	FTI	22	CHS-YEM	CS	Meet #CSM49203, Control Point, YEM
98	NYP	220	TRS	173	TRS	173	MIA-HOL	FL	Trespasser strike Held at Tompkins for Trespasser strike with P603 at MP-1006. Currently behind 6 trains, Control Point, Tompkins
56	SAB	57	PTI	31	PTI	18	NYP-XSH	AM	Follow, AM835, Other, XGG, HELD AT GATE A/C AM835 REVERSING AT LEGGETT

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
40	CHI	355	WTR	139	FTI	72	RVR-XDJ	CS	Broken Knuckle Control Point, Jones, CSX M418	
41	MIA	237	FTI	102	DCS	36	WAS-WAS	AM	Power switch failure, Control Point, A INT, SWITCH FAILURE	
23	NOL	181	TRS	192	TRS	192	MOE-PAG	CS	Trespasser strike Freight train strikes trespasser., Milepost, 684.1, 686.9	
26	MOE	39	FTI	48	FTI	48	PAG-MOE	CS	Meet 60702, Siding, st elmo	
6	CHI	421	ENG	335	ENG	172	COX-XSO	UP	Traction motor The traction motor in the loco failed, running on one locomotive going over Donner pass, had to stop and go the whole to make it over, from milepost 158.4 to 181, going 10 mph while in motion, 139	
521	SJC	11	DCS	13	DCS	10	OAC-HAY	UP	Restrictive signal(s) from unknown cause Restricted proceed, Milepost, 15.0, 16.6	
523	SJC	34	DCS	23	DCS	23	OAC-HAY	UP	CTC system failure Control Point, NI014	
524	SAC	17	DCS	17	DCS	17	HAY-OAC	UP	CTC system failure Flag, Milepost w/Letters, NI019, Signal 14.9	
530	SAC	Trn Cancelled	PTI	5	PTI	3	SCC-SCC	UP	Meet 529, Control Point, Coast	
539	SJC	14	PTI	15	PTI	10	GAC-SCC	UP	Meet Amt538, Control Point, CO044	
543	SJC	60	ITI	57	ITI	57	SAC-SAC	UP	Service, turn, or wye train 532	
545	OKJ	55	RTE	30	RTE	30	SAC-SAC	UP	Late / wrong track bulletins from host railroad UP, Other, SAC Station	
547	SJC	157	TEN	142	TEN	142	HAY-HAY	UP	HEP CDTX 2123 loss of HEP and no oil in the motor, JPBX922	
50	NYP	111	WTR	47	DBS	42	CVS-XOR	BB	Debris blocking track (no debris strike) Milepost, 161.5, 9.1	
505	PDX	32	ENG	32	ENG	32	SEA-SEA	BN	Broken windshield wiper motor. WS1400	
507	EUG	63	FTI	82	FTI	52	PDX-ORC	UP	Follow Red at Reed. Running on signals following UP 7770, UP 7770, Control Point, Reed	
511	PDX	18	MBO	15	MBO	15	VAN-PDX	BN	For maritime traffic Control Point, VAN	
517	PDX	24	SVS	20	SVS	20	VAN-PDX	BN	Unplanned Wye Control Point, north portland	
518	VAC	60	CAR	38	CAR	34	STW-STW	BN	Door 7561, Door would not close. After resetting multiple times it closed.	
519	SEA	25	FTI	19	FTI	11	X1J-XF2	BN	Meet cn 7581, Control Point, spruce	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
58	CHI	396	DCS	198	DCS	104	MAT-MAT	CC	PTC system failure Held At Mattoon Station Due To CN System Outage, Other, Mattoon Station	
59	NOL	443	DCS	271	DCS	267	MEM-MKS	CC	PTC- Unplanned PTC system /server outage Control Point, s. lambert	
8	CHI	132	FTI	173	FTI	55	MAL-GGW	BN	Meet Talked by west Tampico into siding behind the 5534. Met the 7091, then backed out into the main and continued east, BNSF 7091, BNSF 5534, Siding, Tampico	
821	FTW	14	DSR	30	DSR	22	GLE-FTW	BN	Per bulletin Milepost, 409.5, 409.3, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 397.5, 397.1, 60, m, Milepost, 396.3, 396.2, 30, m, Milepost, 395.5, 395, 60, m, Milepost, 394.3, 394.1, 60, m, Milepost, 393.4, 392.8, 60, m, Milepost, 392.4, 392.2, 60, m, Milepost,	
822	OKC	29	DSR	30	DSR	20	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, 1, Milepost, 350.3, 350.4, 30, X over, Milepost, 350.7, 351.1, 50, 1, Milepost, 354.4, 354.5, 10, X over, Milepost, 357.3, 357.6, 29, 2, Milepost, 361, 361.2, 40, 2, Milepost, 361.4, 361.6, 25, 2, Milepost, 382.5, 382.7, 30, M, Milepost, 383.4, 384, 25, M, Mi	
329	MKE	19	CTI	20	CTI	20	XWA-GLN	ME	Follow METRA, Control Point, Morton Grove	
332	CHI	22	ITI	17	ITI	17	MKE-MKE	CP	Service, turn, or wye train 329	
336	CHI	12	DCS	16	DCS	12	GLN-XWA	ME	Issue with automatic road crossing protection Given at GLN cancelled as we stopped wait for PTC, Milepost, 13.75, 13.75	
350	PNT	117	DCS	67	DCS	60	KAL-XGO	CC	CTC system failure Control Point, gord	
351	CHI	16	DSR	26	FTI	14	XMC-XPI	NS	Cross Traffic ns, Control Point, 239	
352	PNT	34	DSR	33	PTI	13	CHI-XTF	AM	Blocking us from departing track 16 YC11, Control Point, HARRISON	
353	CHI	118	DCS	103	DCS	66	ROY-DET	CC	CTC system failure Control Point, Milwaukee Jct	
354	PNT	77	PTI	34	PTI	34	KAL-XGO	MI	Meet 355, Milepost w/Letters, ford, gord	
355	CHI	129	DCS	78	DCS	60	DER-DER	MI	Restrictive signal(s) from known wayside signal failure Stop at CP 9. No power to signal system due to power outage. Back up generators ran out of gas. Wait for maintainer to arrive and resolve., Stop, Control Point, 9	
364	PTH	156	ITI	120	ITI	120	CHI-CHI	AM	Service, turn, or wye train 365	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	232	DCS	172	DCS	80	FLN-DRD	CC	PTC system failure (wayside) Control Point, Flint
370	GRR	192	ENG	171	ENG	171	CHI-CHI	AM	HVAC ID4621
572	SAN	83	ENG	46	ENG	46	XRJ-FUL	BN	PTC mag valve issue 509
584	SAN	36	PTI	28	PTI	23	SNC-SNP	SC	Meet 587, Control Point, serra
587	LAX	25	CTI	22	CTI	9	SOL-OSD	SN	Meet Coaster, Control Point, Swami
774	SAN	56	PTI	70	PTI	18	OSD-SOL	SN	Follow 572, Control Point, Pacific, Control Point, Cardiff
777	SLO	22	PTI	24	CTI	12	SOL-OSD	SN	Meet coaster, Other, sol-osd
785	GTA	43	CTI	30	ITI	27	SAN-SAN	SN	Service, turn, or wye train 774
786	SAN	18	CTI	32	PTI	25	GUA-LPS	UP	Meet 14, Siding, tangaire
703	SAC	No OS Rpt	PTI	37	PTI	32	HNF-FNO	BN	Meet AMT 704, Control Point, Calwa
704	BFD	16	POL	17	POL	17	MDR-FNO	BN	Police hold due to removal of trespasser ahead, hot stopped at CP E.Madera
710	BFD	45	PTI	37	FTI	27	MCD-MDR	BN	Meet BNSF WB, Control Point, East Sharon, Z Train
712	BFD	48	PTI	22	DCS	16	HNF-COC	BN	Restrictive signal(s) from known wayside signal failure Authority to pass stop signal per BFD dispatcher, Calabrese to E. Guernsey., Stop, Control Point, Calabrese
713	OKJ	83	FTI	55	FTI	25	HNF-FNO	BN	Meet bnsf 6845, Control Point, Fresno
714	BFD	106	PTI	42	RTE	33	ACA-SKN	BN	Dispatcher hold Held 21 minutes for Z train BNSF 5066 Held additional 12 minutes for Amtrak 713, Control Point, Holt
715	OKJ	47	DSR	27	DSR	11	WAC-COC	BN	Per bulletin Milepost, 951.1, 951.2, 10, MT
716	BFD	58	PTI	50	PTI	14	HNF-COC	BN	Meet AMTK 703, Control Point, Wagner
718	BFD	224	TSV	216	TSV	216	OKJ-OKJ	UP	Equipment swap
22	CHI	188	WTR	132	SVS	45	FTW-FTW	TE	Fuel
300	CHI	Trn Cancelled							
301	STL	206	DSR	85	DCS	54	CHI-CHI	AM	PTC- Unplanned PTC system /server outage Chicago union station, Milepost, 0.0, 0.0
302	CHI	106	WTR	85	WTR	21	DWT-JOL	UP	Heat order Milepost, 126.4, 36.88
305	STL	38	DCS	21	WTR	17	JOL-DWT	UP	Heat order Milepost, 36.88, 126.4

Amtrak Endpoint OTP Details

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
306	CHI	74	WTR	44	ENG	29	STL-STL	TR	Code IO41 trouble with oil compressor ID4627	
380	CHI	54	DMW	33	DMW	22	PCT-MDT	BN	Held for or routed around MW work or equipment Single tracking ahead for Form B 6076, MP 82.0-80.0; held for AMTK 381, Control Point, Zearing	
382	CHI	31	CTI	27	CTI	27	NPV-LAG	BN	Follow metra, Control Point, lisle/congress park	
383	QCY	208	ENG	100	ENG	100	CHI-CHI	AM	Engine off inbound train 390 arrived @ 523pm ID4605	
390	CHI	263	SYS	173	SYS	153	CDL-CDL	CC	PTC problem or failure (cause unknown)	
391	CDL	208	SYS	159	SYS	156	CHI-X9R	AM	PTC problem or failure (cause unknown) Control Point, 16th st	
392	CHI	175	ITI	117	ITI	64	CDL-CDL	CC	Service, turn, or wye train 391	
393	CDL	193	ITI	153	ITI	153	CHI-CHI	AM	Service, turn, or wye train 390	
311	KCY	50	WTR	35	WTR	12	JEF-SED	UP	Heat order Milepost w/Letters, JEF, SED	
316	STL	47	WTR	42	WTR	20	SED-JEF	UP	Heat order Milepost, 276.00, 128.00	
318	CHI	129	WTR	121	WTR	21	CRV-SPI	UP	Heat order Level 2 heat restriction in effect. Max speed 50mph., Other, -	
319	KCY	No OS Rpt	WTR	227	ENG	85	CHI-CHI	AM	Coolant Leak ID4629	

Amtrak Initial Terminal Details

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/4/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	95	09/04	75	75	Other electrical failure, 629 EX ES, CAB SIGNAL/ ELECTRICAL
CLT	72	09/04	9	9	Service, turn, or wye train 71
MIA	40	09/04	1	1	Late passenger boarded per road foreman Sahara Reece
MIA	98	09/04	107	107	Held for Car 68024 mechanical issues. 68024
NFK	94	09/04	6	2	Air / Brake Independent break issues, 121
NFK	94	09/04	6	2	Wheelchair
NFK	94	09/04	6	2	High passenger count
NHV	470	09/04	25	25	Cab signal failure, 82681 AX AS, SWAP OUT EQUIPMENT IN NHV A/C CAB SIG PROBLEMS
NYP	51	09/04	6	6	Air / Brake, 637, UNSPECIFIED MECHANICAL ISSUE
NYP	63	09/04	2	2	Passenger and/or baggage, LOADING
NYP	69	09/04	5	5	Passenger and/or baggage, HEAVY HOLIDAY LOADING
NYP	97	09/04	116	89	Other electrical failure, 602 EX ES, DISABLED IN LINE 2 A/C MECHANICAL ISSUES
NYP	97	09/04	116	27	Planned set out / pick out of locomotives, cars or section of train, DELAYED DEPARTING NYS DUE TO CATERING AND OBS RELEASING THE EQUIPMENT AT 1:20 PM
NYP	185	09/04	5	5	Door, 00000, UNABLE TO GET DOOR LIGHTS
NYP	283	09/04	41	41	Air / Brake, 123 DX BD, LATE F/SSYD TRAINLINE ISSUES
NYP	641	09/04	2	2	Passenger and/or baggage, LOADING
NYP	649	09/04	23	23	Disabled train ahead, Other, F-INT, CONGESTION AHD IN LINE 1 A/C AM97 DISABLED
NYP	2119	09/04	2	2	Passenger and/or baggage, LOADING
NYP	2123	09/04	2	2	Passenger and/or baggage, BOARDING
PGH	42	09/04	1	1	Waiting on baggage services
PHL	151	09/04	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	605	09/04	24	24	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD
PIT	1246	09/04	2	2	Passenger and/or baggage
RGH	75	09/04	1		
RNK	66	09/04	7	7	Routine inspections
WAS	148	09/04	3	3	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE

Amtrak Initial Terminal Details

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/4/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2128	09/04	2	2	Toilet, 3270 NG NS, 6 OUT OF 9 BATHROOMS ON TRN WERE INOPERABLE
CDL	390	09/04	153	153	PTC problem or failure (cause unknown)
CDL	392	09/04	64	64	Service, turn, or wye train 391
CHI	41	09/04	71	71	Service, turn, or wye train 40, Late inbound train, 240pm 5hrs 55 mins late.
CHI	301	09/04	54	54	PTC- Unplanned PTC system /server outage Chicago union station, Milepost, 0.0, 0.0
CHI	305	09/04	10	10	Service, turn, or wye train 302
CHI	307	09/04	45	45	ENGINE PROBLEMS NEED TO BE FIXED . Late arrival of train, ID4633
CHI	319	09/04	85	85	Coolant Leak ID4629
CHI	354	09/04	8	8	Service, turn, or wye train 353
CHI	364	09/04	120	120	Service, turn, or wye train 365
CHI	370	09/04	171	171	HVAC ID4621
CHI	383	09/04	100	100	Engine off inbound train 390 arrived @ 523pm ID4605
CHI	393	09/04	153	153	Service, turn, or wye train 390
MKE	332	09/04	17	17	Service, turn, or wye train 329
PNT	353	09/04	23	23	CTC system failure System wide issue with dispatch system on the CN railroad., Control Point, MAL
STL	300	09/04	(Trn Cxld)		Engine Issue
STL	302	09/04	7	7	Failure of diesel engine Double draft equipment due to engine failure, ID4633
STL	306	09/04	29	29	Code IO41 trouble with oil compressor ID4627
BFD	703	09/04	4	4	Track was still blue flagged until multiple attempts to get in contact with mechanical in BFD came out and removed blue flag
BFD	713	09/04	4	4	Door C8312, No door light had to open and close b end doors
BFD	715	09/04	10	10	Door C8006, C8007, C8014, C8205, C8814, Door light issues could not get door light per Road foreman Brandon Cooper cut out door light feature (engineer) and instructed to walk every station stop to ensure all doors are closed. Also contacted Tazzy and CNOC operations (Danielle).
EMY	6	09/04	1		
GTA	782	09/04	2	2	Meet 14, Control Point, CO 358
LAX	14	09/04	16	16	Switch of BO dorm car Late release after switching of dorm car, release approx 9:20am
OKJ	534	09/04	1	1	Meet Amt 716, Control Point, N. Jack London
OKJ	714	09/04	12	12	Water, commissary, toilet/trash dumping Departed yard 12:13

Amtrak Initial Terminal Details

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/4/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	718	09/04	(Trn Cxld)		Third Party Cab Car Failure
SAC	537	09/04	6	6	PTC problem or failure (cause unknown) PTC stalled out multiple times on attempted log-ins at the "waiting for system configuration" screen. PTC breaker was cycled after multiple failed log-ins and UP PTC Desk was contacted. Was able to log-in after breaker re-set and departure test., Other, SAC Dep
SAC	543	09/04	57	57	Service, turn, or wye train 532
SAC	545	09/04	50	30	Late / wrong track bulletins from host railroad UP, Other, SAC Station
SAC	545	09/04	50	20	Service, turn, or wye train 530
SAC	547	09/04	18	3	Wheelchair
SAC	547	09/04	18	15	Service, turn, or wye train 530, Waiting for AMT 530's equipment
SAC	704	09/04	1		
SAN	785	09/04	27	27	Service, turn, or wye train 774
SEA	505	09/04	32	32	Broken windshield wiper motor. WS1400
SJC	538	09/04	3	3	Held for or routed around MW work or equipment Control Point, alameda
SLO	786	09/04	1	1	Door C6951, After a good door test, closing doors for final departure caused door to be closed but showing open. Put train into override and departed.

Eastern Region

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	NO DATA	NO DATA	94.8	NO DATA	NO DATA
CDOT	95.0	NO DATA	NO DATA	92.4	NO DATA	NO DATA
MARC	95.0	No Data	No Data	90.2	NO DATA	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	NO DATA	NO DATA	88.6	NO DATA	NO DATA
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 19(04) North of Greensboro, NC - Signal

05SEP26: Train 19(04), operating with engines 333/77, 9 coaches, and 157 customers, was delayed 19 miles North of Greensboro, NC, on NS Montview-Salisbury subdivision due to signal issues between milepost 265.5 and milepost 272.9. This required the train to operate at a restricted speed until they cleared the affected area.

Train	Delay	Comment
19(04)	32"	

Train 20(04) East of Atlanta, GA - Engine Failure

05SEP26: Train 20(04), operating with engines 328/122, 8 coaches, and 139 customers, was delayed 3 miles east of Atlanta, GA, on NS Greenville-Inman_04 subdivision, due to radio failure on lead loco 328. The crew was able to restore function and get back on the move. Charlotte mechanical inspected upon arrival.

Train	Delay	Comment
20(04)	31"	

North Philadelphia, PA - Police Hold - Trespasser

05SEP26: Due to a trespasser being reported in the area of North Philadelphia, PA, the Amtrak Police Department (APD) placed a hold on all tracks through the area. As a result, Train 198(04) and Train 624(04) were held at Philadelphia (PHL), while Train 177(04) was held at Cornwells Heights. The incident caused delays to multiple trains, including Train 198(04), 624(04), .Additional impacts included Train 90(04) at Philadelphia, train 177(04) holding at Tacony, Train 65(04) set to hold at Cornwells Heights

During the incident, APD, local police, and SEPTA Police responded to the scene and worked to resolve the situation. Law enforcement personnel negotiated with the trespasser in an effort to safely remove them from the tracks. The trespasser was reported to have had a knife and was suicidal. Once the trespasser was apprehended, APD lifted the hold on all tracks through PHN. Following the release of the tracks, train movements resumed, and all affected trains were returned to service and continued on their routes.

Train 90(04) was short on Hours of Service and was ordered to violate Hours of Service in order to advance the train to Metropark, NJ where a recrew out of New York would meet the train.

Train	Delay	Comment
198(04)	1'52"	
65(04)	40"	
177(04)	1'06"	
90(04)	1'07"	
624(04)	1'51"	

Train 79(04) West of Greensboro, NC - Signal

05SEP26: Train 79(04), operating with engine 33, 7 coaches, and 314 customers, was delayed 8 miles west of Greensboro, NC, on NS Goldsboro-Greensboro-62NC, due to signal issues requiring the dispatcher to talk the train through the affected area.

Train	Delay	Comment
79(04)	39"	

Train 66(03) Washington, DC - Hold for Connection

05SEP26: Train 66(04), operating with engine 656, 5 coaches, and 249 customers, was delayed departing Washington, DC, due to holding for connections off of late inbound train 40(03). train 40(03) arrived at Washington at 11:12pm-et, 8'00" late. The trains were brought in across the platform from each other and station services was on scene to expedite the boarding process.

Train	Delay	Comment
66(03)	1'25"	

Train 98(04) North of Jesup, GA - Freight Train Interference

05SEP26: Train 98(04), operating with engines 115/307, 10 coaches and 259 customers, was delayed 26 miles north of Jesup, GA, on CSX Nahunta_A subdivision, due to following freight from milepost 522 to milepost 503.

52(04) was also delayed following the freight.

Train	Delay	Comment
98(04)	53"	
52(04)	50"	

Train 283(04) West of Syracuse, NY - Police Related

05SEP26: Train 283(04) 26-FCI-00731-00000008775 UNCLASSIFIED 1026/707, 9/18/2026, operating with engines 1026/707, 5 coaches, and 124 customers, was delayed 22 miles west of Syracuse, NY, on CSX Rochester_QC subdivision, due to police meeting the train to remove an intoxicated and unruly customers.

Train	Delay	Comment
283 (04)	45"	

Train 53(04) Petersburg, VA - Weather

04SEP26: Train 53(04), operating with engines 360/380, 39 coaches, and 333 customers,, was delayed south of Petersburg, VA, on CSX North End_A subdivision, due to operating through high wind speed restrictions. The speed restrictions were between mileposts 64 and 177.

Train	Delay	Comment
53 (04)	2'42"	

Train 53(04) South of Petersburg, VA - Debris Strike

04SEP26: Train 53(04), operating with engines 360/380, 39 coaches, and 333 customers, was delayed south of Petersburg, VA, on CSX North End_A subdivision, due to striking a tree at milepost 60.8. The tree strike caused a speed sensor to be damaged which disabled PTC. As a result train 53(04) operated the rest of the route with PTC cut out and at a restricted speed of 59MPH.

Train	Delay	Comment
53 (04)	51"	

Train 90(04) Washington, DC - Engine Failure

04SEP26: Train 90(04), operating with Engine 617, seven coaches, and carrying 229 customers, experienced a delayed departure from Washington, DC, due to the removal of deadhead diesel locomotive E/46. The removal was required because of communication issues between the electric motor on Engine 617 and the diesel unit.

Train	Delay	Comment
90 (04)	1'22"	

Train 50(03) North of Charlottesville, VA - Debris

05SEP26: Train 50(03), operating with engines 346/388, 5 coaches, and 133 customers, was delayed 22 miles North of Charlottesville, NC, on BB North Mountain subdivision, due to debris on the tracks. BB Maintenance of Way team was dispatched to remove the debris. Once the debris was removed and the tracks were inspected, train 50(03) was able to proceed.

Train	Delay	Comment
50 (03)	42"	

Train 182(04) East of Old Saybrook, CT - Drawbridge Opening

04SEP26: Train 182(04) operating with engine UNCLASSIFIED 8 cars, engine 643, and 477 customers onboard was stopped at milepost 105.6, half a mile east of Old Saybrook, CT on the Amtrak NHB Line due to the Conn Bridge being stuck in the open position. It was reported that the bridge could not be closed and locked due to a breaker trip. B&B and a mechanic reported to the scene and was able to rectify the issue. The train was back on the move at 4:10 PM-ET.

Train 137(04) operating with 454 customers onboard was stopped at milepost 107.1 due to the bridge being open and waiting for a clear route. Once the bridge was reported closed and locked, Train 137(04) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
137(04)	32"	
182(04)	48"	
1632(04)	1'25"	

Train 75(04) North of Salisbury, NC - Third Party Contractor Engine Failure

04SEP26: Train 75(04) operating with engine RNCX1869, 4 cars, RNCX102, and 178 customers onboard was delayed beginning at milepost 317.5, 16 miles north of Salisbury, NC on the NS Charlotte District due to the on-board hot box detector activating. The crew inspected the train and took no exceptions. The train was then required to operate not exceeding 50 miles per hour for ten miles and then reinspect. The crew found no exceptions on the reinspection. Train 75(04) advanced to the next station without any further restrictions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
75(04)	41"	

Train 74(04) East of Burlington, NC - Passenger Train Interference

05SEP26: Train 74(04), operating with engines 1755/103, 4 coaches, and 188 customers was delayed 4 miles east of Burlington, NC, on NS Goldsboro-Greensboro-62NC subdivision, due to meeting train 77(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
74(04)	32"	

Train 97(04) New York, NY - Engine Failure

04SEP26: Train 97(04) operating with engines 602, 630, 11 cars, and 190 customers was delayed departing New York, NY on the Amtrak NYT line due to a stuck parking brake on engine 630 while on the way to the station from Sunny Side Yard. The crew attempted unsuccessfully to troubleshoot the issue with the road foreman and mechanical. A rescue engine 636 was dispatched to rescue to the trainset. Mechanical forces were on the rescue motor. Mechanical was able to rectify the issue. The train was able to pull into New York station and board the train. Train 97(04) departed New York at 4:26 PM-ET.

Train 649(04) operating with 277 customers was delayed departing New York due to 97(04) blocking line 2 between the station and Sunny Side Yard. Train 649(04) had to reverse and go around. Train 649(04) departed New York at 3:07 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
649(04)	23"	
97(04)	1'56"	

Train 48/448(03) East of Rochester, NY - Freight Train Interference

04SEP26: Train 48/448(03) operating with engine 126, 11 cars, and 262 customers onboard was delayed beginning at milepost 370.0, 1 mile east of Rochester, NY on the CSX Rochester subdivision due to following CSX freight train from milepost 370.0 to milepost 293.0. Once the freight cleared, Train 48/448(03) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448(03)	32"	

Train 283(04) New York, NY - Engine Failure

04SEP26: Train 283(04) operating with engine 123, 5 cars, and 295 customers was delayed departing New York, NY on the Amtrak NYT Line due to a late release from the yard. There were trainline issues with the brakes. Once the train was staged and boarded in New York, Train 283(04) departed at 2:01 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
283(04)	41"	

Train 284(04) West of Syracuse, NY - Routing

04SEP26: Train 284(04) operating with engine 117, 5 cars, and 167 customers onboard was delayed at milepost 296.8, 5 miles west of Syracuse, NY on the CSX Rochester subdivision due to being lined for the incorrect route. Once the correct and clear route was established, Train 284(04) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
284(04)	35"	

Train 641(04) Philadelphia, PA - Engine Failure

04SEP26: Train 641(04) operating with engine 650, 4 cars, cab car 9634, and 152 customers onboard was delayed departing Philadelphia, PA on the Amtrak PH Line due to being necessary to wye the equipment for bad cab car 9634. The cab car was shopped for bad cab signals. Once the train completed the move around the wye, Train 641(04) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
641(04)	31"	

CSX Heat Orders - Weather

04SEP26: Trains were delayed on the following CSX subdivisions due to heat orders in effect between 100PM-ET through 700PM-ET: Alleghany, Kanawha, Keystone, New River, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, North End, Sanford, South End, and Tampa Terminal.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(04)	5"	
40(04)	35"	
51(04)	5"	
52(04)	7"	
53(04)	15"	
79(04)	45"	
80(04)	1'02"	
89(04)	56"	
90(04)	1'24"	
95(04)	27"	
98(04)	44"	

Train 41(03) West of Connellsville, PA - Freight Train Interference

04SEP26: Train 41(03) operating with engine 230, 10 cars, and 164 customers onboard was delayed at milepost 16.9, 41 miles west of Connellsville, PA on the CSX Pittsburgh subdivision due to meeting CSX freight train 135.

Train 41(03) was further delayed at milepost 266.8, 4 miles east of Connellsville, due to meeting CSX freight train M225-04. Once the freight train cleared, Train 41(03) advanced to the next station.

Train	Delay	Comment
41(03)	37"	MP 16.9
41(03)	42"	MP 266.8

Train 66(03) New Haven, CT - Servicing

04SEP26: Train 66(03) operating with engine 605, 5 cars, and 293 customers was delayed departing New Haven, CT on the Metro North New Haven Line due to adding engines 85 and 86 to the consist. Once the engines were added to the consist, Train 66(03) departed New Haven at 8:04 AM-ET.

Train	Delay	Comment
66(03)	38"	

Train 98(04) Miami, FL - Initial Terminal Delay

04SEP26: Train 98(04) operating with engines 115, 307, 10 cars, and 64 customers were delayed departing Miami, FL on the SFTRA SFTRA subdivision due to mechanical issues with car 68024. Mechanical reported a leaking valve that had to be replaced, and the train had to be re-watered. The train was released by mechanical and arrived into the station at 8:28 AM-ET. Once the train was boarded, Train 98(04) departed the Miami at 8:52 AM-ET.

Train	Delay	Comment
98(04)	1'47"	

Train 95(04) East of Boston, MA - Engine Failure

04SEP26: Train 95(04) operating with engine 629, 9 cars, and 323 customers onboard was stopped at milepost 226.7, one mile east of Boston, MA on the Amtrak NHB Line due to engine failure on engine 629. The engine had a penalty that the crew was unable to recover from. The crew was in contact with the road foreman. The train shoved back into Boston and swapped equipment. The equipment was stocked by commissary. Once the customers were transferred and the equipment prepared, Train 95(04) departed Boston for a second time at 7:27 AM-ET.

Train	Delay	Comment
95(04)	1'25"	

Train 40(02) Pittsburgh, PA - Servicing

04SEP26: Train 40(02), with E/145-E/199-11 cars, was delayed at Pittsburgh, PA (MP353.1), on the NSRR Pittsburgh Line while awaiting the fuel vendor to complete fueling the locomotives.

Train	Delay	Comment
40(02)	43"	

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outage on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

26-FOI-00731 00000008775 UNCLASSIFIED

9/18/2026

Train	Delay	Comment
240 (29)	29"	
280 (29)	18"	
233 (29)	54"	
283 (29)	64"	
284 (29)	39"	
291 (29)	36"	
290 (29)	47"	
49 (29)	49"	
235 (29)	49"	
48 (28)	31"	
237 (29)	36"	
239 (29)	1' 10"	
69 (30)	51"	
240 (30)	35"	
1233 (30)	18"	
291 (30)	45"	LATE TURN OFF 240 (30)

Maintenance of Way Highlights

26-XXX Adirondack CN Rouses Point Subdivision UCI Road World Championships Advisory - Scheduled M/W Work

03SEP26: To accommodate the UCI Road World Championships on the CN Rouses Point Subdivision, Amtrak's Adirondack Service will be adjusted as follows:

Train 69(25-27SEP), which normally operates between New York and Montreal, CA, will terminate at Saratoga Springs, NY.

Train 68(26-28SEP), which normally operated between Montreal and New York, will originate in Saratoga Springs.

Alternate transportation will be provided as follows:

Bus 3069 will provide alternate transportation between Saratoga Springs and Montreal.

Bus 3068 will provide alternate transportation between Montreal and Saratoga Springs.

Train 69(25SEP) equipment will deadhead Saratoga Springs to Albany for mechanical servicing and will deadhead Albany to Saratoga Springs on Monday September 28th to turn for Train 68(28SEP).

Train 69(26-27SEP) will make a same day turn for Train 68(26-27SEP) in Saratoga Springs.

WBS#: B.TR.100150.7134

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008775 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008775 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train 383(04) Macomb, IL - Freight Train Interference

05SEP26: Train 383(04) was delayed upon departing Macomb IL station/MP202.3 on the BNSF Brookfield subdivision following BNSF Freight train 5144. Train 383(04) followed the freight all the way into Quincy IL station/MP258.6.

Train	Delay	Comment
383(04)	40"	

Train 518(04) Stanwood, WA - Car Failure

05SEP26: Train 518(04) was delayed at Stanwood, WA/ MP55.5 on the BNSF Bellingham Subdivision, due to a door on the business class car C/7561 would not close. After multiple attempts at resetting, the crew was able to resolve and proceed north.

Train	Delay	Comment
518(04)	34"	

Train 703(04) West of Corcoran, CA - Signal Failure

05SEP26: Train 703(04) was delayed west of Corcoran, CA due to a BNSF signal failure, flagging between East Guernsey/MP959.4 and Calabrese/MP962.8 on the BNSF Bakersfield Subdivision. And was further delayed meeting BN5429 and Amtrak 704(04) due to the resulting congestion delays. Trains 716(04) and 714(04) were also delayed due to this signal failure, flagging and meeting multiple trains account of congestion. As a result, Train 794(04) was also delayed at Los Angeles, CA waiting for connecting bus 5714(04) with 17 passenger connections off delayed train 714(04).

Train	Delay	Comment
703(04)	1'03"	Congestion
703(04)	26"	
714(04)	21"	
716(04)	35"	Congestion
794(04)	30"	LAX- Bus 5714 Connection

Train 319(04) east of Warrensburg, MO - Weather

05SEP26: Train 319(04) was delayed at MP 206.3, east of Warrensburg MO station on the UPRR Sedalia subdivision due to a sun kinked rail. Train 319(04) was delayed a second time at MP229, 11.52 miles west of Warrensburg MO station on the UPRR Sedalia subdivision due to a sunk kinked rail. Train 319(04) went into emergency when they operated over the sun kinks. After the being put into emergency by the sunk kinks train 319(04) operated at reduced speed until Independence MO station/MP273.3.

Train	Delay	Comment
319(04)	1'24"	

Train 507(04) South of Portland, OR - Freight Train Interference

05SEP26: Train 507(04) was delayed departing from Portland OR/MP0.0 on the UPRR Portland Subdivision, then delayed from Portland to Hito/MP742.6 on the UPRR Brooklyn Subdivision due to a meet and follow with UP7770.

Train 11(04) Portland, OR - Freight Train Interference

05SEP26: Train 11(04) ~~26-FOI-00731 00000008775~~ at "UNCLASSIFIED", 09/18/2026 0.0 on the BNSF Fallbridge Subdivision, meeting freight unit cross traffic UP6021.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(04)	31"	

Train 319(04) Warrensburg, MO - Freight Train Interference

05SEP26: Train 319(04) was delayed holding at Warrensburg MO station/MP218.5 on the UPRR Sedalia subdivision due to UPRR Freight 7358 stopped ahead due to a sun kinked rail. Train 319(04) departed Warrensburg MO station at 1250AM CT after the freight was clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(04)	35"	

Train 22(04) South of Little Rock, AR - Freight Train Interference

05SEP26: Train 22(04) was delayed beginning at MP389, 43.4 miles south of Little Rock AR station on the UPRR Little Rock subdivision following UP freight train 7940 until MP360.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(04)	30"	

Train 718(04) Originated at Emeryville, CA - Third Party Contractor Cab Car Failure

05SEP26: Train 718(04), CC/C8312, 7 cars, E/C2108, was initially delayed departing Oakland, CA due to a late expected mechanical release from Oakland Mechanical facility as TASI worked to replace a faulty E7 box on CC/C8312. To help minimize delay, the decision was made to originate 718(04) at Emeryville, with all affected passengers accommodated onto train 548(04) between OKJ-EMY. Once the replacement was complete, the mechanical issue remained unresolved. It was then necessary to swap out cab car CC/C8312 with CC/90218 further prolonging the delay. Once the cab cars were swapped out, and the train made complete with all testing complete, Train 718(04) was released from Oakland Mechanical facility to load 75 customers at Emeryville, departing 4 hours and 30 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(04)	4'30"	

Train 5(04) East of Omaha, NE - Vehicle Strike

05SEP26: At 1214AM CT, train 5(04), with engines 179 and 206 9 cars, and 184 customers onboard struck an unoccupied vehicle at mile post 7.5 10.6 miles east of Omaha NE station on the BNSF Brookfield subdivision No injuries were reported by the customers or crew. Minor damage was reported to the plow on engine 179. Head end power remained up during the duration of the incident. Local police were already on scene when the strike occurred and an Amtrak Road Foreman, was on train 5(04). Weather was 79 degrees and clear at the time of the strike. The crew did not request relief. Police released the scene and train 5(04) was back on the move at 103AM CT. NRC # 1472810.

National Response Center Number: 1472810

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(04)	50"	

Train 392(04) South of Champaign-Urbana, IL - Passenger Train Interference

05SEP26: Train 392(04) was delayed holding at MP137.3, 19.30 miles south of Champaign-Urbana IL station on the CN Champaign subdivision meeting Amtrak train 393(04). Train 392(04) was back on the move at 956PM CT after 393(04) cleared to the south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
392(04)	55"	

Train 383(04) East of Plano, IL - Passenger Train Interference

04SEP26: Train 383(04) was delayed holding at MP373.3, 8.99 miles east of Plano IL station on the BNSF Chicago subdivision due to a meet with 382(04). Train 383(04) was back on the move at 911PM CT after train 382(04) cleared to the east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
383(04)	47"	

Train 354(04) Kalamazoo, MI - Passenger Train Interference

04SEP26: Train 354(04) was delayed holding at Kalamazoo MI station/MP143.4 on the Amtrak Michigan line due to a meet with train 355(04). Train 354(04) was back on the move at 1013PM CT after 355(04) cleared to the west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(04)	43"	

Train 370(04) Chicago, IL - Initial Terminal Delay

04SEP26: Train 370(04) was delayed departing initial terminal of Chicago IL stationMP0.0 due to failed HVAC on charger locomotive ID4621. Engine ID4621 was removed from the consist and taken to the locomotive shop for repairs at 550PM CT. The HVAC unit was replaced and the engine was released from the yard at 747PM CT and tied back onto the consist at 758PM. Train 370(04)'s consist was released at 843PM CT and set in the station at 854PM CT. Train 370(04) departed Chicago Union station at 921PM CT 2 hours and 51 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
370(04)	2'51"	

Train 26(04) South of Mobile, AL - Freight Train Interference

04SEP26: Train 26(04) was delayed holding at MP686.1, 19.17 miles south of Mobile AL station on the CSX NO and M subdivision meeting CSX freight train, Train 26(04) was back on the move at 927PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
26(04)	48"	

Train 355(04) Dearborn, MI - Signal

04SEP26: Train 355(04) was delayed holding at Dearborn MI station/MP9.7 on the Michigan Line due to signal issues at CP9 caused by power outage and the backup generator running out of fuel. Maintainer arrived on scene to fuel the generator. Train 350(04) was back on the move at 816PM ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 5(04) Galesburg, IL - Signal

04SEP26: Train 5(04) was delayed starting at MP 161.5, 13.20 miles east of Galesburg IL station on the BNSF Mendota subdivision due to a switch failure at Knox Street preventing BNSF freight 9106 train from entering the yard. Maintainer arrived on scene and were able to repair the switch. Train 5(04) was back on the move at 546PM CT after BNSF freight 9106 cleared into the yard.

Train	Delay	Comment
5(04)	53"	

Train 714(04) West of Stockton, CA - Freight/ Passenger Train Interference

04SEP26: Train 714(04) was delayed at Holt/MP1129 on the BNSF Stockton Subdivision, 8 miles west of Stockton, CA station due to meeting BNSF Z-train BN5066. Then was additionally held to meet Amtrak Train 713(04).

Train	Delay	Comment
714(04)	21"	FTI -BN5066
714(04)	12"	Meeting 713

Train 4(03) East of Albuquerque, NM - Commuter Train Interference

04SEP26: Train 4(03) was delayed starting at MP 885.5, 16 miles east of Albuquerque, NM, on the NMRX Glorieta Subdivision due to commuter rail interference. The crew held at MP 885.5 for a meet with NMRX102 then was further delayed for a meet with NMRX103. Once all commuter rail was clear, Train 4(03) proceeded east.

Train	Delay	Comment
4(03)	39"	

Train 530(04) Berkeley, CA - Third Party Contractor Engine Failure

04SEP26: At 12:04P-PT, Train 530(04), CC/C8314, 4 cars, C2123 was delayed departing Berkeley, CA on the UPRR Martinez Subdivision due oil leaking from E/C2123. The crew contacted mechanical to troubleshoot. Due to the length of delay, Train 530(04) was terminated at Berkeley and the 90 customers on board were reaccommodated on Train 532(04) from Berkeley to Sacramento departing Berkeley at 1:21P-PT. An Amtrak road foreman arrived on scene at 1:00P-PT to assist. Mechanical responded to scene with oil and a cap. Mechanical brought additional oil to the scene arriving at 2:45P-PT. With the delays increasing, equipment turn manipulations were made to avoid further delays. The equipment from inbound Train 532(04) was turned for Train 543(04), Train 534(04) was turned for Train 545(04) and 530 Equipment was deadheaded to Sacramento for Train 547(04).

At approximately 7:40PM-PT, Train 547(04), operating with the same equipment set from 530(04), E/C2123, 4 cars, CC/C8314, with 70 passengers including one mobility impaired customer with a wheelchair onboard, came to a stop shortly after departing Hayward station. The crew reported the engine shut-down with a loss of head-end power (H.E.P) and began to work with mechanical to troubleshoot the issue. The outside temperature was reported as 63 degrees and clear. The issue was determined to be the same low oil fault as experienced earlier with Train 530(04). An Amtrak Road Foreman and TASI mechanical were dispatched to the scene with oil to help get the locomotive running again, with plans to shove the train back into Hayward station. Expecting a lengthy delay, busses were sourced for passengers onboard. The train was currently 1 car length beyond the station, and unable to detrain passengers onto the platform. The area was safe for passengers to detrain using the step stool and Uber vouchers were initiated for passengers onboard to utilize if they chose to detrain prior to securing alternate bussing.

Once TASI mechanical arrived and added oil to the locomotive, the crew was able to re-start the engine and restore H.E.P. AT 9:05PM-PT. Train 549(04) had just arrived into Oakland, and the equipment was advanced to Hayward to represent Train 547(04) from Hayward to San Jose. The original Train 547(04) reversed back to Hayward station to allow passengers to detrain as necessary. Two busses were secured for passengers onboard the train. One from Avalon departed HAY with 29 passengers at 9:39PM-PT and made all local stops, drop-off only. The second was an ADA bus from Royal Coach that departed HAY at 10:02PM-PT with the one mobility impaired passenger and operated express to San Jose. Once all passengers were loaded onto the busses, Train 547(04) (operating with 549 equipment) departed HAY at 10:00PM-PT, 2 hours and 48 minutes late, and operated live to San Jose. The original 547 equipment was deadheaded back to Oakland Mechanical facility.

WBS#: B.TR.100150.7143

Train	Delay	Comment
530(04)	Terminated BKY	
543(04)	57"	ITD SAC - turn of 532
532(04)	08"	
545(04)	50"	ITD SAC - turn of 534
547(04)	18"	ITD SAC - off 530 Equip
547(04)	2'22"	HAY

Train 572(04) West of Fullerton, CA - Engine Failure

04SEP26: Train 572(04) was delayed at MP 163.8, 2 miles west of Fullerton, CA, on the BNSF San Bernardino Subdivision due to valve issues on E/509. The crew contacted mechanical to troubleshoot. Mechanical was able to identify the issue as a wire issue on the mag valve causing a PTC penalty. Once the issue was resolved, Train 572(04) proceeded east.

Train	Delay	Comment
572(04)	46"	

Train 4(03) - Engine Failure

04SEP26: Train 4(03), E/40-5/104 Cars, UNCLASSIFIED, 9/18/2026, 26-FOI-00731 00000008775, delayed departing Albuquerque, NM due to locomotive issues on E/40. The crew held while mechanical repaired the bell and replaced the wiper blades on lead locomotive E/40. Once repairs were made, the crew performed their tests and were able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4 (04)	33"	

Train 350(04) East of Jackson, MI - Passenger Train Interference

04SEP26: Train 350(04) held 2.8 miles east of Jackson, MI (MP75.5), on the Michigan DOT Michigan Line, at CP72 (MP72.7) in order to meet Train 353(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
350 (04)	36"	

Train 365(04) East Lansing, MI - Debris

04SEP26: Train 365(04), E/ID4621-6 Cars-E/ID4630, reported striking a tree on the tracks 2 miles east of East Lansing, MI (MP223.8), on the CNRR Flint Subdivision at MP225.8. There were no injuries reported to the crew or 152 customers onboard. The strike caused damage to the hotbox journal wiring on engine ID4621. No delay was incurred from the strike.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
365 (04)	No Delay	

Train 301(04) South of Pontiac, IL - Passenger Train Interference

04SEP26: Train 301(04) held 16.7 miles south of Pontiac, IL (MP92.1), on the CNRR Joliet Subdivision, at Ballard (MP108.8) in order to meet Train 302(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
301 (04)	42"	

Train 27(19) Bingen-White Salmon, WA - Car Failure

21AUG26: Train 27(19) operating with engine 139, 4 cars, and 86 customers onboard was delayed at Bingen, WA on the BNSF Fallbridge subdivision due to car failure on car 33011. It was reported that the car set off the hot box detector and was 50 degrees higher than the rest. The car was required to be set out. The crew set out the car in Bingen and advanced to the next station.

04SEP26: UPDATE -Train 28(04) was delayed at Bingen-White Salmon, WA picking up repaired car C/33011. An Amtrak Road Foreman and mechanical personnel were on scene to help facilitate this event. A mechanical rider remained onboard 28(04) into Spokane, WA after the addition of the car.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
27 (19)	1'26"	
28 (SEP04)	35"	

Train 319(04) Chicago, IL - Engine Failure

04SEP26: Train 319(04) delayed at Chicago, Illinois, due to repairs for a coolant leak on engine ID4629. Mechanical forces were unable to fully service the train until repairs were completed due to an inoperative power stand. Following release from mechanical, additional yard movements were required due to switching activity involving Trains 7(04) and 1333(04). After being placed in Chicago Union Station, it was discovered that X-ITCS had not been tested following the locomotive swap. After boarding 199 customers, Train 319(04) departed Chicago Union Station 1 hour 25 minutes late. The train subsequently stopped at CP Lumber to complete the required X-ITCS test before continuing south, operating 1 hour 47 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(04)	1'25"	ITD CHI
319(04)	10"	XITCS

Train 14(03) North of Dunsmuir, CA - Animal Strike

04SEP26: Train 14(03), E/349-E/19-9 cars, was delayed at MP 337.9, 16 miles north of Dunsmuir, CA, on the UPRR Black Butte Subdivision due to striking an animal. No injuries were reported to the crew or the 259 customers on board. The crew stopped at MP 337.9 to inspect the consist after the strike and no damage was reported. After the consist was inspected and a brake test was complete, Train 14(03) proceeded north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(03)	20"	

Train 505(04) Seattle, WA - Engine Failure

04SEP26: Train 505(04), CC/7910-12 cars-E/WS1400, was delayed departing Seattle, WA on the BNSF Seattle Subdivision due to locomotive issues on E/WS1400. The crew held while mechanical repaired the windshield wiper motor on E/WS1400. Once the repairs and all other servicing was completed, the equipment was released to the crew. The equipment was then taken to the station for boarding. After all customers boarded the equipment and a brake test was complete, Train 505(04) was able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
505(04)	32"	

Train 7/27(03) Minot, ND - Engine Failure

04SEP26: Train 7/27(03), E/353-E/335-10 cars, was delayed departing Minot, ND on the BNSF KO Subdivision due to an oil leak on E/353. Once the equipment arrived into Minot, mechanical identified an oil leak on E/353. The crew held while mechanical repaired the oil leak. After the oil leak was repaired, Train 7/27(03) was further delayed for mechanical to bring oil train side in order to fill up the oil to ensure it would not run out en route. Once mechanical was finished, the crew performed their brake test and departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(03)	1'12"	

Train 48/448(03) West of Buffalo, NY - Power Switch Failure

04SEP26: Train 48/448(03) operating with engines 126, 124, 11 cars, and 272 customers onboard was delayed at milepost 434.4, 3 miles west of Buffalo, NY on the CSX Buffalo Terminal subdivision due to a power switch failure. Once there was a clear route, Train 48/448(03) advanced to the next station.

Train 23(04) Mobile, AL - Freight Train Interference

04SEP26: Train 23(04), 26-F01-007349 00000008775 UNCLASSIFIED was held 0.1 miles south of Mobile, AL (MP666.7), on the CSX NO&M Subdivision, at Choctaw (MP666.8) for open track. The delay resulted from CSX M602-04 fatally striking a trespasser 17.4 miles west of the station at MP684.1. Local police, EMS, the coroner, and Amtrak's Mobile Road Foreman responded to the scene. The freight crew requested relief, and a replacement crew was transported to the location. After authorities released the scene and the recrew boarded, CSX M602-04 proceeded north. Once a route was established, Train 23(04) was released to continue south. Service recovery was enacted, with snack packs and bottled water distributed to all customers onboard.

WBS#: B.TR.100150.7141

Train	Delay	Comment
23(04)	3'12"	Hold
23(04)	08"	Meet CSX 602-04

Train 765(03)/ 14(03) South of Lompoc-Surf, CA- Loss of Shunt

04SEP26: Union Pacific Railroad advised that Train 765(03), E/C2111-C/34120-C/6803-C/C6352-C/6407-C/C6451-CC/6905 and 14(03), E/349-E/19-C/61064-C/39035-C/32031-C/32055-C/38040-C/33040-C/34515-C/34205-C/31044 experienced a loss of shunt on September 3rd, 2026, between 1:25P and 1:43P PST. This occurred south of Lompoc-Surf station at MP 303.49 on the Union Pacific Santa Barbara subdivision. UPRR signal department was notified, and shunt testing will be performed.

Train 49/449(03) West of Elyria, OH - Customer Medical

04SEP26: Train 49/449(03) was held 11.3 miles west of Elyria, OH (MP206.6), on the NSRR Chicago Line at MP217.9 to meet emergency services and local police for an onboard customer medical emergency. After the customer was removed from the train, Train 49/449(03) incurred additional delay while meeting NS 22M before authorization was received to proceed west.

Train	Delay	Comment
49/449(03)	46"	EMS
49/449(03)	22"	NS 22M

CNRR System Wide Outage

04SEP26: Train 58(03) was delayed holding at MP297.5, 31.1 miles south of Fulton KY station on the CN Fulton subdivision due to a CN systemwide outage. The outage was resolved at 218AM-CT and train 58(03) was back on the move proceeding at reduced speed until they reached the next signal. Train 59(03) was delayed holding at MP402.5 north of Fulton KY station while CN worked to restore the PTC outage.

04SEP26: At 8:00AM-ET, Canadian National reported a systemwide PDS outage resulting in a loss of control of dispatch systems and causing delays to multiple Amtrak trains. At 8:50AM-ET, the systems were reported as slowly restoring, with some trains beginning to move; however, a second systemwide outage occurred at 9:50AM-ET. The system continued to operate intermittently while troubleshooting efforts were underway. At 12:30PM-ET, CN reported the system was restored and stable, with no further delays anticipated.

-Train 365(04), with 45 customers onboard, was the first train delayed, originally holding 32.1 miles west of Port Huron, MI (MP334.3), on the CNRR Flint Subdivision, at Imlay City (MP302.2), to meet CN M394. After the meet was completed, the system went down and Train 365(04) held awaiting restoration. At 8:51AM-ET, the system was restored and the train resumed westbound movement until stopping again at CP Flint (MP270.4) when the PDS screens went down a second time. Once restored, Train 365(04) resumed movement

while awaiting system recovery. After departing, the train stopped again 8.7 miles south of Royal Oak, MI (MP13.2), on the CNRR Holly Subdivision at MP4.5 due to another intermittent system failure. Once a route was established, Train 353(04) continued onto Amtrak Michigan Line to Detroit. ~~28-FOI-00731 00000008775~~ any "UNCLASSIFIED" system-related delays. 9/18/2028

-Train 350(04), with 225 customers onboard, held 0.2 miles west of Battle Creek, MI (MP175.7), on the CNRR South Bend Subdivision at Gord (MP175.5), while awaiting a route to be established.

-Train 390(04), with 95 customers onboard, held at Carbondale, IL (MP308.3), awaiting restoration of the system. At 10:03AM-CT, Train 390(04) departed and traveled 22.6 miles before stopping again at MP285.7 due to another intermittent system failure. Once the system was restored, Train 390(04) proceeded north.

-Train 391(04), with 209 customers onboard, departed Chicago on time but held just south of the station at MP1.5. Due to the extensive delay incurred while awaiting restoration, the train shoved back into the station, arriving at 10:28AM-CT. At 10:51AM-CT, a route was established, allowing Train 391(04) to depart for a second time. Four buses were secured that shadowed the train downline and later called off once CN established that their system stabilized.

-Train 301(04), with 142 customers onboard, held at Chicago, IL, pending restoration of the PDS screens. Once on the move, Train 301(04) passed through the area without further delay.

-Train 58(03), with 196 customers onboard, held at Mattoon, IL (MP172.3), on the CNRR Champaign Subdivision, awaiting system restoration. After resuming movement, the train experienced several additional brief delays at the Champaign, IL station and near MP124.4 due to intermittent system issues. Service recovery included snack packs, bottled water, hot tea, and coffee. First Class customers received an extended breakfast service from the dining car.

-Train 59(03), with 256 customers onboard, held 5.1 miles south of Memphis, TN (MP391.8), on the CNRR Shelby Subdivision at West Jct (MP5.1), while awaiting system restoration. After resuming movement, Train 59(03) traveled 57.3 miles before stopping again at Darling (MP62.4) due to another intermittent system outage and to await a recrew and pilots after the conductors expired under Hours of Service regulations at 11:09AM-CT. Service recovery included snack packs, bottled water, hot tea, and coffee. First Class customers received an extended breakfast service from the dining car. Once the recrew boarded and the job briefing was completed, Train 59(03) proceeded south for 32.1 miles before stopping again at Swan Lake/MP94.3. This was necessary to replace the CN pilot as the original expired on their hours of service at 1:30PM-CT. Once the new pilot boarded, Train 59(03) was able to continue to New Orleans.

Equipment Turn Delays:

-Train 364(04) was delayed departing Chicago, IL as a result of a late turn of Train 365(04) that arrived at 3:47PM-CT, 3 hours and 52 minutes late.

-Train 392(04) was delayed departing Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision, as a result of a late turn of Train 391(04). Two buses were secured as a precaution and later cancelled once CN established stability of their systems. Both buses were able to be cancelled in time with no cost incurred.

-Train 393(04) was delayed departing Chicago, IL as a result of a late turn of Train 390(04).

WBS#: B.TR.100150.7140

Train	Delay	Comment
-------	-------	---------

59(03)	1'18"	S/FTN - MP297.5		
58(03)	49"	N/FTN - MP402.5		
365(04)	41"	Imlay - Meet M394		
365(04)	1'19"	Imlay - System Outage		
365(04)	1'25"	CP Print	00000008775	"UNCLASSIFIED" 9/18/2026
353(04)	23"	PNT		
353(04)	1'13"	MP4.5		
350(04)	1'00"	Gord		
390(04)	2'33"	CDL		
391(04)	2'39"	CHI		
301(04)	54"	CHI		
58(03)	2'30"	MAT-CHI Delays		
59(03)	58"	Swan Lake		
59(03)	4'27"	S/MEM - Outage		
390(04)	31"	MP285.7 - Witronix		
392(04)	1'04"	ITD CDL		
364(04)	2'00"	ITD CHI		
393(04)	2'33"	ITD CHI		
383(04)	1'40"	ITD		

Coast Starlight UPRR Sacramento Sub Curfew- Detour TWA 26-090

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

B.TR.100151.0836

WBS#: B.TR.100151.0836

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(22)	23"	
11(22)	32"	

Train 355(04) Pontiac, MI - Wye OOS

04SEP26: Canadian National reported that the Pontiac, MI wye on the CNRR Holly Subdivision was removed from service due to wide gauge and was expected to remain out of service until Tuesday, September 7. As a result, Train 355(04) departed Pontiac on time but incurred delay en route to Detroit, MI while completing a shove move to Milwaukee Jct (MP4.1) to wye the equipment. After the wye move was completed, Train 355(04) continued toward Chicago operating at track speed.

05SEP26: Due to the Pontiac MI wye being out of service train 350(05) will terminate at Detroit MI station with alternate bus transportation Detroit MI to Pontiac MI. Train 355(05) will originate at Dearborn MI station with alternate bus transportation Pontiac MI to Dearborn MI station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(04)	31"	
350(05)	TERM DET	
355(05)	ORIGINATE DER	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 00900008775 UNCLASSIFIED 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (1)	RSV	UP5197	Dynamic brake	CHI	9/3/26
6 (2)	RNO	UP8997	E/139 No HEP	CHI	9/5/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 518(04) Passenger Removal at Centralia, Washington. – Improper Behavior

05SEP26, Passenger on PNR EAE5F3, traveling from Centralia, WA to Seattle WA was removed from the train by the Conductor for having their service animal on the seat in the café car. The conductor explained the policy to the passenger, but he became irate. The passenger then threatened the Conductor. Amtrak Police notified.

Delay: 518 (04) None

Consist Deviations

26-FOI-00731

00000008775

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
319 (04)	CHI	Due to turn changes will be operating with 48181 for business class car which only accommodates 17 paxs. CNOC CSV will need to downgrade and reaccommodate passengers.	Passengers downgraded	18	48181
27 (04)	CHI	diner/lounge in lieu of 33xxx lounge. no sight-seer dome car.	no impact	0	37011
7 (04)	CHI	0732 car has no H-room, please block.	0 impact	0	39003
600 (04)	HAR	No cab car or cafe car to provide wifi. extra coach added for ridership	n/a	0	615
626 (04)	HAR	No cab car or cafe car to provide wifi. extra coach added for ridership	n/a	0	615
562 (04)	LAX	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	4	90225
580 (04)	LAX	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	1	90225
572 (04)	LAX	Due to equipment swap operating with comet set and will not be able to accommodate passengers with BV or JY reservation. Over capacity CNOC CSV will need to reaccommodate passengers impacted by this.	Passengers notified	122	C5004 C5010 C5001 C5002 C5005 9700
649 (04)	NYP	No cab car or cafe car to provide wifi. extra coach added for ridership	n/a	0	615
28 (06)	PDX	diner/lounge in lieu of 33xxx lounge. no sight-seer dome car.	no impact	0	37011
573 (04)	SAN	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO	Passengers notified	3	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00731 00000008775 "UNCLASSIFIED"			
		ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.			
591 (04)	SAN	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	4	90225
587 (04)	SAN	Due to equipment swap operating with comet set and will not be able to accommodate passengers with BV or JY reservation. Over capacity will need to reaccommodate passengers impacted by this.	Passengers notified and downgraded	70	9700 C5005 C5002 C5001C 5010 C5004
8 (06)	SEA	0832(*06*) CAR HAS NO H-ROOM, PLEASE BLOCK	0 Impact	0	39003

Reverse Consists

Train Number	Station	Reason
95 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
190 (04)	PHL	Consist reversed Business class seat orientation may have changed At Front
137 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
164 (05)	NPN	Consist reversed Business class seat orientation may have changed At Front
147 (05)	SPG	Consist reversed Business class seat orientation may have changed At Front
129 (04)	NYP	Consist reversed Business class seat orientation may have changed At Front
156 (05)	RNK	Consist reversed Business class seat orientation may have changed At Front
158 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00731	00000008775 "UNCLASSIFIED" 9/18/2026
174 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front	
128 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front	
85 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front	
198 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front	