



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, September 06, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/05/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	48	83.4%	1,604	257	84.0%	102,126	14,225	86.1%
Central Division	86.0%	59	11	81.4%	294	47	84.0%	19,489	1,822	90.7%
East Division	82.0%	147	18	87.8%	859	108	87.4%	53,679	8,242	84.6%
West Division	86.0%	83	19	77.1%	451	102	77.4%	28,958	4,161	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008776 UNCLASSIFIED 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	113,307	38,168	66%	516,533	156,930	70%	34,113,666	8,744,200	74%
Northeast Corridor	81%	49,042	9,100	81%	230,095	49,057	79%	14,948,509	3,636,845	76%
Acela	83%	8,105	854	89%	52,174	6,997	87%	3,015,084	766,218	75%
Northeast Regional	79%	40,937	8,246	80%	177,921	42,060	76%	11,933,425	2,870,627	76%
Richmond / Newport News / Norfolk	77%	12,198	1,638	87%	49,994	17,776	64%	3,573,620	1,065,181	70%
Springfield Shuttles	89%	625	201	68%	3,744	775	79%	210,973	34,011	84%
Roanoke	79%	5,133	832	84%	19,272	4,953	74%	1,133,429	254,773	78%
On Spine Northeast Regional	80%	22,981	5,575	76%	104,911	18,556	82%	7,015,403	1,516,662	78%
State Supported	80%	50,659	20,613	59%	229,765	74,090	68%	15,018,702	3,285,183	78%
Borealis	80%	582	0	100%	2,942	158	95%	190,961	40,635	79%
Capitol Corridor	90%	3,037	640	79%	19,845	3,177	84%	1,251,970	167,565	87%
Carolinian	70%	1,875	1,398	25%	5,254	3,518	33%	382,639	151,637	60%
Cascades	75%	2,731	788	71%	12,944	4,634	64%	865,544	245,659	72%
Downeaster	82%	1,929	0	100%	8,074	12	100%	528,226	61,846	88%
Empire	78%	6,598	2,443	63%	30,848	8,596	72%	1,873,352	463,877	75%
Adirondack	72%	343	27	92%	1,848	550	70%	115,868	37,503	68%
Ethan Allen Express	70%	243	238	2%	2,520	749	70%	189,471	72,973	61%
Maple Leaf	70%	988	116	88%	4,466	1,450	68%	233,354	91,673	61%
New York - Albany	85%	2,678	1,065	60%	13,437	2,711	80%	862,870	151,267	82%
New York - Niagara Falls	75%	2,346	997	58%	7,970	3,136	61%	458,332	103,603	77%
Berkshire Flyer	60%	0	0	-	607	0	100%	13,457	6,858	49%
Gold Runner	73%	2,956	1,598	46%	12,673	8,310	34%	842,854	317,214	62%
Heartland Flyer	70%	311	14	95%	901	270	70%	72,438	30,438	58%
Hiawatha	90%	2,116	54	97%	9,295	593	94%	593,362	64,469	89%
Illinois	78%	3,775	3,410	10%	11,440	8,945	22%	840,117	241,690	71%
Carl Sandburg / Illinois Zephyr	85%	739	530	28%	1,975	980	50%	139,788	40,340	71%
Illini / Saluki	85%	1,734	1,674	3%	3,957	3,313	16%	290,082	74,832	74%
Lincoln Service	70%	1,302	1,206	7%	5,508	4,652	16%	410,247	126,518	69%
Keystone	92%	5,982	246	96%	41,839	5,702	86%	2,568,447	263,463	90%
Lincoln / Missouri	70%	795	795	0%	2,842	2,837	0%	260,479	138,289	47%
Mardi Gras Service	80%	405	113	72%	1,299	294	77%	134,398	30,011	78%
Michigan	70%	3,203	1,751	45%	10,862	5,952	45%	684,167	231,492	66%
Blue Water	70%	718	327	54%	2,288	1,340	41%	160,959	66,507	59%
Pere Marquette	85%	544	166	69%	1,545	295	81%	88,064	16,653	81%
Wolverine	70%	1,941	1,258	35%	7,029	4,317	39%	435,144	148,332	66%
Missouri	80%	339	267	21%	1,113	998	10%	74,502	22,247	70%
Pacific Surfliner	85%	10,047	6,199	38%	41,754	13,985	67%	2,750,199	529,784	81%
Pennsylvanian	80%	925	334	64%	4,310	1,440	67%	297,066	57,311	81%
Piedmont	80%	1,768	534	70%	4,859	1,606	67%	375,644	96,226	74%
Vermont	75%	1,285	29	98%	6,671	3,063	54%	432,337	131,330	70%
Long Distance	70%	13,606	8,455	38%	56,673	33,783	40%	4,107,188	1,819,709	56%
Auto Train	70%	643	643	0%	3,253	1,968	40%	263,416	90,724	66%
California Zephyr	70%	1,083	161	85%	4,358	2,103	52%	325,490	128,097	61%
Cardinal	70%	565	401	29%	1,061	799	25%	78,143	40,099	49%
City Of New Orleans	75%	824	824	0%	3,195	2,808	12%	212,596	75,048	65%
Coast Starlight	70%	1,447	474	67%	5,793	1,398	76%	382,966	136,096	64%
Crescent	70%	1,108	350	68%	4,259	1,312	69%	309,327	95,666	69%
Empire Builder	70%	1,245	655	47%	5,401	2,198	59%	326,552	163,783	50%
Floridian	60%	633	633	0%	6,019	4,793	20%	526,085	364,942	31%
Lake Shore Ltd	73%	1,194	273	77%	5,131	2,208	57%	327,819	100,338	69%
Palmetto	70%	1,389	893	36%	3,801	2,632	31%	306,971	97,410	68%
Silver Meteor	70%	1,142	1,142	0%	4,153	3,830	8%	338,655	159,290	53%
Southwest Chief	60%	967	949	2%	4,272	3,126	27%	281,656	186,831	34%
Sunset Ltd	70%	0	0	-	871	349	60%	96,649	38,867	60%
Texas Eagle	70%	1,366	1,057	23%	5,106	4,259	17%	330,863	142,518	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000770 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 05, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	35,375	557,781	634	2,035,193	35,831,948	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,701	172,088	99	98,140	10,379,522	95
INFRASTRUCTURE PLANNED	135	2,838	172,088	165	118,384	10,379,522	114
FLEET RELIABILITY	90	5,646	557,781	101	325,191	35,831,948	91
TRAIN OPERATIONS	424	25,190	557,781	452	1,493,478	35,831,948	417

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/05/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	48	83.4%	1,604	257	84.0%	102,126	14,225	86.1%
Central Division	86.0%	59	11	81.4%	294	47	84.0%	19,489	1,822	90.7%
East Division	82.0%	147	18	87.8%	859	108	87.4%	53,679	8,242	84.6%
West Division	86.0%	83	19	77.1%	451	102	77.4%	28,958	4,161	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/05/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/05/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	48	83.4%	1,604	257	84.0%	102,126	14,225	86.1%
Central Division	86.0%	59	11	81.4%	294	47	84.0%	19,489	1,822	90.7%
CDL	95.0%	2	0	100.0%	10	3	70.0%	646	34	94.7%
CHI	86.0%	27	7	74.1%	138	27	80.4%	9,008	1,127	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	1	1	0.0%	1	1	0.0%	3	3	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	5	1	80.0%	363	39	89.3%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	5	0	100.0%	319	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	10	1	90.0%	658	55	91.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	30	2	93.3%	1,989	128	93.6%
MOE	97.5%	2	0	100.0%	10	1	90.0%	677	10	98.5%
MSP	96.5%	1	0	100.0%	5	0	100.0%	333	7	97.9%
NOL	94.5%	5	0	100.0%	21	0	100.0%	1,431	64	95.5%
OKC	97.0%	1	0	100.0%	4	0	100.0%	333	6	98.2%
PNT	88.0%	2	1	50.0%	14	2	85.7%	890	75	91.6%
PTH	93.0%	1	0	100.0%	5	0	100.0%	328	13	96.0%
QCY	91.0%	2	0	100.0%	10	1	90.0%	641	49	92.4%
SAS	90.5%	1	0	100.0%	5	1	80.0%	337	40	88.1%
STL	89.0%	4	1	75.0%	20	6	70.0%	1,316	112	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	147	18	87.8%	859	108	87.4%	53,679	8,242	84.6%
ALB	88.5%	8	2	75.0%	39	3	92.3%	2,523	191	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	25	0	100.0%	1,646	175	89.4%
BOS	85.5%	18	0	100.0%	93	2	97.8%	5,798	642	88.9%
BRK	92.5%	5	0	100.0%	25	1	96.0%	1,620	113	93.0%
BTN	82.0%	1	0	100.0%	5	1	80.0%	324	43	86.7%
CLT	91.5%	5	1	80.0%	22	3	86.4%	1,653	170	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	9	1	88.9%	657	61	90.7%
GRO	-	-	-	-	3	1	66.7%	53	12	77.4%
HAR	79.5%	7	0	100.0%	59	7	88.1%	3,766	601	84.0%
HFD	-	-	-	-	8	0	100.0%	240	19	92.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	5	1	80.0%	336	41	87.8%

Information Management

Initial Terminal Performance By Terminal

26-FOI-007100-00000000

Scheduled Departure Date:	09/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/05/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	48	83.4%	1,604	257	84.0%	102,126	14,225	86.1%
East Division	82.0%	147	18	87.8%	859	108	87.4%	53,679	8,242	84.6%
MIA	89.5%	2	0	100.0%	10	4	60.0%	668	80	88.0%
MTR	79.0%	1	1	0.0%	5	1	80.0%	323	59	81.7%
NFK	84.5%	2	0	100.0%	10	2	80.0%	755	138	81.7%
NFL	93.5%	2	0	100.0%	10	1	90.0%	684	32	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	4	0	100.0%	24	3	87.5%	1,726	290	83.2%
NPN	93.0%	2	0	100.0%	10	1	90.0%	644	52	91.9%
NYP	75.5%	37	6	83.8%	242	45	81.4%	14,171	3,102	78.1%
PGH	93.0%	1	0	100.0%	5	1	80.0%	337	24	92.9%
PHL	48.0%	4	2	50.0%	24	10	58.3%	1,719	809	52.9%
PIT	76.0%	-	-	-	1	1	0.0%	25	20	20.0%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	4	1	75.0%	14	3	78.6%	1,278	57	95.5%
RNK	83.5%	2	0	100.0%	10	1	90.0%	668	94	85.9%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	5	0	100.0%	319	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	5	0	100.0%	333	12	96.4%
SFA	88.0%	1	1	0.0%	5	1	80.0%	336	48	85.7%
SPG	92.5%	6	0	100.0%	25	1	96.0%	1,987	116	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	5	0	100.0%	325	63	80.6%
WAS	84.0%	24	3	87.5%	156	13	91.7%	8,525	1,087	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	83	19	77.1%	451	102	77.4%	28,958	4,161	85.6%
ARN	92.0%	1	0	100.0%	5	0	100.0%	338	28	91.7%
BFD	79.0%	6	1	83.3%	33	11	66.7%	2,146	459	78.6%
EMY	72.0%	1	0	100.0%	5	2	60.0%	354	102	71.2%
EUG	86.5%	2	2	0.0%	9	2	77.8%	669	61	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	14	2	85.7%	1,015	174	82.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	0	100.0%	53	6	88.7%	3,373	375	88.9%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	9	6	33.3%	60	28	53.3%	3,679	981	73.3%
PDX	86.0%	5	1	80.0%	25	5	80.0%	1,630	230	85.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/05/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/05/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	48	83.4%	1,604	257	84.0%	102,126	14,225	86.1%
West Division	86.0%	83	19	77.1%	451	102	77.4%	28,958	4,161	85.6%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	2	83.3%	76	16	78.9%	4,795	536	88.8%
SAN	90.5%	13	3	76.9%	65	8	87.7%	4,102	400	90.2%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	3	62.5%	40	12	70.0%	2,593	392	84.9%
SJC	89.0%	7	1	85.7%	35	6	82.9%	2,375	235	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	15	1	93.3%	780	78	90.0%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	5	1	80.0%	317	30	90.5%
VAC	97.0%	2	0	100.0%	10	1	90.0%	663	15	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		5	1	80.0%	338	67	80.2%	5	1	80.0%	335	158	52.8%
4		5	0	100.0%	337	53	84.3%	5	2	60.0%	337	223	33.8%
5		5	1	80.0%	336	58	82.7%	5	1	80.0%	332	112	66.3%
6		5	2	60.0%	335	93	72.2%	5	4	20.0%	335	129	61.5%
7		5	0	100.0%	327	51	84.4%	5	0	100.0%	318	86	73.0%
8		5	1	80.0%	327	146	55.4%	5	2	60.0%	326	200	38.7%
11	61	5	3	40.0%	338	75	77.8%	5	1	80.0%	332	68	79.5%
14		5	3	40.0%	339	57	83.2%	5	0	100.0%	336	105	68.8%
19		5	1	80.0%	337	84	75.1%	5	0	100.0%	334	82	75.4%
20		5	0	100.0%	337	23	93.2%	5	1	80.0%	337	66	80.4%
21		5	0	100.0%	334	36	89.2%	5	3	40.0%	333	102	69.4%
22	46	5	1	80.0%	335	38	88.7%	5	5	0.0%	333	104	68.8%
23	16	5	1	80.0%	339	7	97.9%	5	3	40.0%	337	93	72.4%
24		5	0	100.0%	339	16	95.3%	5	1	80.0%	338	66	80.5%
25		5	0	100.0%	338	3	99.1%	5	0	100.0%	335	94	71.9%
26		5	0	100.0%	338	5	98.5%	5	1	80.0%	335	67	80.0%
27	36	5	3	40.0%	304	22	92.8%	5	1	80.0%	298	98	67.1%
28	37	5	0	100.0%	298	67	77.5%	5	1	80.0%	298	61	79.5%
40	451	5	2	60.0%	328	49	85.1%	5	4	20.0%	324	176	45.7%
41	353	5	4	20.0%	328	128	61.0%	5	5	0.0%	325	252	22.5%
42		5	1	80.0%	339	26	92.3%	5	0	100.0%	337	58	82.8%
43	37	5	0	100.0%	338	45	86.7%	5	4	20.0%	337	80	76.3%
48	67	5	0	100.0%	337	62	81.6%	5	3	40.0%	336	54	83.9%
49		5	0	100.0%	337	84	75.1%	5	1	80.0%	337	71	78.9%
51	215	2	1	50.0%	138	59	57.2%	2	2	0.0%	134	54	59.7%
52	83	5	1	80.0%	336	48	85.7%	5	3	40.0%	335	80	76.1%
53	254	5	1	80.0%	336	41	87.8%	5	3	40.0%	335	109	67.5%
54		1	0	100.0%	120	8	93.3%	1	0	100.0%	120	17	85.8%
57		1	0	100.0%	119	5	95.8%	1	0	100.0%	119	10	91.6%
58	139	5	0	100.0%	312	17	94.6%	5	5	0.0%	310	102	67.1%
59	88	5	2	60.0%	311	53	83.0%	5	4	20.0%	306	85	72.2%
63	146	5	2	60.0%	340	146	57.1%	5	5	0.0%	334	202	39.5%
64		5	0	100.0%	338	71	79.0%	5	2	60.0%	337	135	59.9%
65		2	0	100.0%	104	13	87.5%	1	0	100.0%	102	14	86.3%
66		5	1	80.0%	337	65	80.7%	5	2	60.0%	332	62	81.3%
68		5	1	80.0%	340	68	80.0%	5	2	60.0%	339	136	59.9%
69		5	2	60.0%	327	81	75.2%	5	1	80.0%	322	57	82.3%
71		5	0	100.0%	335	3	99.1%	5	1	80.0%	333	87	73.9%
72		5	1	80.0%	331	37	88.8%	5	1	80.0%	329	70	78.7%
73		2	1	50.0%	330	24	92.7%	2	0	100.0%	328	148	54.9%
74	16	2	0	100.0%	328	35	89.3%	2	2	0.0%	326	120	63.2%
75	16	5	2	60.0%	328	19	94.2%	5	3	40.0%	322	154	52.2%

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	32	5	0	100.0%	328	31	90.5%	5	2	60.0%	318	132	58.5%
77		5	1	80.0%	330	22	93.3%	5	1	80.0%	327	134	59.0%
78		5	1	80.0%	334	30	91.0%	6	2	66.7%	332	77	76.8%
79		5	0	100.0%	337	59	82.5%	5	4	20.0%	335	116	65.4%
80		5	1	80.0%	337	38	88.7%	5	2	60.0%	334	73	78.1%
82		1	0	100.0%	78	10	87.2%	1	0	100.0%	78	24	69.2%
87		1	0	100.0%	123	26	78.9%	1	0	100.0%	123	45	63.4%
88	45	1	1	0.0%	119	17	85.7%	1	1	0.0%	119	26	78.2%
89	32	5	0	100.0%	335	78	76.7%	5	4	20.0%	333	101	69.7%
90		5	0	100.0%	335	12	96.4%	5	2	60.0%	334	62	81.4%
97	92	5	3	40.0%	337	220	34.7%	5	4	20.0%	335	124	63.0%
98	180	5	2	60.0%	337	30	91.1%	5	4	20.0%	335	127	62.1%
99		1	0	100.0%	122	12	90.2%	1	0	100.0%	119	67	43.7%
101		1	0	100.0%	77	8	89.6%	1	0	100.0%	77	12	84.4%
103		1	0	100.0%	121	24	80.2%	1	0	100.0%	121	11	90.9%
106		1	0	100.0%	93	11	88.2%	1	0	100.0%	92	14	84.8%
107	69	1	0	100.0%	93	30	67.7%	1	1	0.0%	92	16	82.6%
109		1	0	100.0%	60	9	85.0%	1	0	100.0%	60	6	90.0%
118		1	0	100.0%	121	8	93.4%	1	0	100.0%	121	8	93.4%
124	18	1	0	100.0%	120	9	92.5%	1	1	0.0%	119	35	70.6%
126	42	1	1	0.0%	56	10	82.1%	1	1	0.0%	56	14	75.0%
127	89	1	1	0.0%	56	18	67.9%	1	1	0.0%	56	7	87.5%
135	66	1	0	100.0%	122	18	85.2%	1	1	0.0%	122	58	52.5%
136		4	1	75.0%	217	28	87.1%	5	2	60.0%	216	30	86.1%
140		1	0	100.0%	121	15	87.6%	1	0	100.0%	120	29	75.8%
142		1	0	100.0%	76	8	89.5%	1	0	100.0%	75	9	88.0%
143		1	0	100.0%	120	13	89.2%	1	0	100.0%	120	29	75.8%
144		1	1	0.0%	78	53	32.1%	1	0	100.0%	77	11	85.7%
146		1	1	0.0%	120	19	84.2%	1	0	100.0%	120	42	65.0%
147		1	0	100.0%	79	10	87.3%	1	0	100.0%	79	27	65.8%
150	23	1	1	0.0%	119	63	47.1%	1	1	0.0%	117	56	52.1%
151		5	2	60.0%	336	107	68.2%	5	1	80.0%	335	100	70.1%
152		1	0	100.0%	78	6	92.3%	1	0	100.0%	78	27	65.4%
153		1	0	100.0%	121	11	90.9%	1	0	100.0%	121	19	84.3%
155		1	0	100.0%	123	20	83.7%	1	0	100.0%	123	43	65.0%
156		1	0	100.0%	123	12	90.2%	1	0	100.0%	123	43	65.0%
158		1	0	100.0%	122	22	82.0%	1	0	100.0%	122	27	77.9%
159	Cncld	1	0	100.0%	76	8	89.5%	0	0	0.0%	75	11	85.3%
160		1	0	100.0%	120	8	93.3%	1	0	100.0%	117	27	76.9%
161		1	0	100.0%	121	10	91.7%	1	0	100.0%	120	81	32.5%
162		1	0	100.0%	121	10	91.7%	1	0	100.0%	121	58	52.1%
163	24	1	0	100.0%	76	15	80.3%	1	1	0.0%	76	63	17.1%

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
164		1	0	100.0%	123	9	92.7%	1	0	100.0%	123	51	58.5%
165		1	0	100.0%	121	27	77.7%	1	0	100.0%	121	47	61.2%
167		1	0	100.0%	79	16	79.7%	1	0	100.0%	78	22	71.8%
168		1	0	100.0%	77	14	81.8%	1	0	100.0%	77	28	63.6%
178		4	0	100.0%	217	28	87.1%	5	1	80.0%	216	37	82.9%
179		4	0	100.0%	217	25	88.5%	5	2	60.0%	217	78	64.1%
194		1	0	100.0%	78	18	76.9%	1	0	100.0%	77	23	70.1%
195		1	0	100.0%	121	5	95.9%	1	0	100.0%	121	66	45.5%
198	108	4	2	50.0%	149	19	87.2%	5	2	60.0%	149	24	83.9%
230		5	0	100.0%	173	4	97.7%	5	1	80.0%	173	10	94.2%
232		5	0	100.0%	339	12	96.5%	5	1	80.0%	339	24	92.9%
233		4	1	75.0%	299	67	77.6%	4	0	100.0%	298	101	66.1%
234		5	0	100.0%	340	23	93.2%	5	0	100.0%	339	29	91.4%
235	75	5	1	80.0%	264	43	83.7%	5	1	80.0%	263	61	76.8%
236		5	0	100.0%	324	10	96.9%	5	0	100.0%	323	43	86.7%
237	40	5	1	80.0%	337	62	81.6%	5	2	60.0%	335	61	81.8%
238	27	5	1	80.0%	264	24	90.9%	5	1	80.0%	262	23	91.2%
239		5	2	60.0%	338	85	74.9%	5	0	100.0%	337	42	87.5%
240	72	5	1	80.0%	339	24	92.9%	5	1	80.0%	336	70	79.2%
241		5	2	60.0%	339	84	75.2%	5	2	60.0%	339	83	75.5%
243		5	1	80.0%	275	72	73.8%	5	0	100.0%	274	39	85.8%
244	51	4	1	75.0%	298	13	95.6%	4	3	25.0%	298	68	77.2%
245		5	1	80.0%	220	42	80.9%	5	0	100.0%	219	30	86.3%
280		5	0	100.0%	340	17	95.0%	5	2	60.0%	339	80	76.4%
281		5	0	100.0%	340	40	88.2%	5	1	80.0%	340	61	82.1%
283	20	5	2	60.0%	340	87	74.4%	5	5	0.0%	340	71	79.1%
284		5	1	80.0%	340	14	95.9%	5	2	60.0%	337	63	81.3%
290	35	5	1	80.0%	340	53	84.4%	5	2	60.0%	337	139	58.8%
291	164	5	1	80.0%	339	113	66.7%	5	2	60.0%	335	92	72.5%
300	205	5	2	60.0%	323	24	92.6%	4	1	75.0%	319	74	76.8%
301	44	5	1	80.0%	337	11	96.7%	5	5	0.0%	333	68	79.6%
302	77	5	2	60.0%	318	36	88.7%	5	5	0.0%	314	95	69.7%
305	Cncld	5	2	60.0%	321	33	89.7%	4	4	0.0%	315	126	60.0%
306	46	5	1	80.0%	335	18	94.6%	5	5	0.0%	333	94	71.8%
307	38	5	2	60.0%	328	46	86.0%	5	3	40.0%	324	101	68.8%
311	130	5	1	80.0%	332	29	91.3%	5	5	0.0%	326	89	72.7%
316	83	5	1	80.0%	328	25	92.4%	5	5	0.0%	322	106	67.1%
318	299	5	0	100.0%	338	35	89.6%	5	5	0.0%	335	171	49.0%
319	156	5	1	80.0%	339	21	93.8%	5	5	0.0%	334	198	40.7%
330		5	1	80.0%	289	7	97.6%	5	1	80.0%	289	16	94.5%
331		5	1	80.0%	340	34	90.0%	5	1	80.0%	339	45	86.7%
332		5	1	80.0%	339	20	94.1%	5	2	60.0%	339	48	85.8%

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		5	0	100.0%	340	11	96.8%	5	0	100.0%	338	43	87.3%
335		5	0	100.0%	340	35	89.7%	5	0	100.0%	337	55	83.7%
336		5	0	100.0%	339	10	97.1%	5	1	80.0%	337	30	91.1%
337	13	5	0	100.0%	340	21	93.8%	5	1	80.0%	336	48	85.7%
338	12	5	0	100.0%	340	54	84.1%	5	1	80.0%	337	105	68.8%
339		5	0	100.0%	340	54	84.1%	5	0	100.0%	340	58	82.9%
341		5	0	100.0%	325	51	84.3%	5	0	100.0%	319	53	83.4%
342		5	0	100.0%	340	26	92.4%	5	2	60.0%	338	63	81.4%
343		1	0	100.0%	48	3	93.8%	1	0	100.0%	48	10	79.2%
350	65	5	1	80.0%	315	21	93.3%	5	4	20.0%	307	178	42.0%
351	146	5	1	80.0%	322	30	90.7%	5	4	20.0%	320	96	70.0%
352		5	0	100.0%	306	24	92.2%	5	4	20.0%	300	97	67.7%
353		5	1	80.0%	277	15	94.6%	5	2	60.0%	271	51	81.2%
354	125	5	1	80.0%	321	38	88.2%	5	3	40.0%	313	119	62.0%
355	90	5	1	80.0%	328	38	88.4%	5	3	40.0%	319	122	61.8%
364	39	5	1	80.0%	329	74	77.5%	5	4	20.0%	323	124	61.6%
365		5	0	100.0%	328	13	96.0%	5	2	60.0%	325	126	61.2%
370		5	1	80.0%	326	40	87.7%	5	1	80.0%	313	76	75.7%
371		5	0	100.0%	319	11	96.6%	5	1	80.0%	315	31	90.2%
380		5	0	100.0%	321	30	90.7%	5	1	80.0%	320	73	77.2%
381	56	5	1	80.0%	336	16	95.2%	5	1	80.0%	333	72	78.4%
382	34	5	1	80.0%	335	31	90.7%	5	4	20.0%	333	120	64.0%
383	56	5	3	40.0%	326	30	90.8%	4	2	50.0%	322	140	56.5%
390	111	5	1	80.0%	321	25	92.2%	5	4	20.0%	319	90	71.8%
391	58	5	0	100.0%	322	14	95.7%	5	5	0.0%	317	93	70.7%
392	65	5	2	60.0%	335	13	96.1%	4	4	0.0%	329	107	67.5%
393	50	5	3	40.0%	339	22	93.5%	4	4	0.0%	334	108	67.7%
400		1	0	100.0%	100	6	94.0%	1	0	100.0%	98	2	98.0%
405		1	0	100.0%	93	0	100.0%	1	0	100.0%	93	4	95.7%
448		5	2	60.0%	264	51	80.7%	5	2	60.0%	260	91	65.0%
449		5	0	100.0%	261	34	87.0%	5	0	100.0%	261	45	82.8%
450		1	0	100.0%	96	29	69.8%	1	0	100.0%	94	30	68.1%
460	30	1	0	100.0%	96	30	68.8%	1	1	0.0%	93	32	65.6%
461	38	1	0	100.0%	101	5	95.0%	1	1	0.0%	100	4	96.0%
463		1	0	100.0%	51	4	92.2%	1	0	100.0%	51	0	100.0%
464		1	0	100.0%	97	21	78.4%	1	0	100.0%	94	29	69.1%
467		1	0	100.0%	51	1	98.0%	1	0	100.0%	50	3	94.0%
488	24	1	0	100.0%	106	29	72.6%	1	1	0.0%	96	15	84.4%
499		1	1	0.0%	97	15	84.5%	1	0	100.0%	94	6	93.6%
500		5	1	80.0%	314	17	94.6%	5	1	80.0%	311	37	88.1%
502		5	0	100.0%	322	19	94.1%	5	1	80.0%	318	62	80.5%
503		5	2	60.0%	336	42	87.5%	4	0	100.0%	328	102	68.9%

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504	51	5	1	80.0%	340	21	93.8%	5	2	60.0%	338	101	70.1%
505	109	5	2	60.0%	332	45	86.4%	5	5	0.0%	327	96	70.6%
506		5	1	80.0%	335	57	83.0%	4	1	75.0%	326	52	84.0%
507		5	0	100.0%	340	49	85.6%	5	2	60.0%	340	117	65.6%
508		4	1	75.0%	334	44	86.8%	4	1	75.0%	330	82	75.2%
509		5	2	60.0%	321	17	94.7%	5	1	80.0%	321	72	77.6%
511		5	1	80.0%	316	26	91.8%	5	1	80.0%	315	54	82.9%
516		5	1	80.0%	331	36	89.1%	5	2	60.0%	330	148	55.2%
517		5	0	100.0%	340	8	97.6%	5	2	60.0%	336	152	54.8%
518	71	5	3	40.0%	340	49	85.6%	5	5	0.0%	338	237	29.9%
519		5	1	80.0%	331	10	97.0%	5	3	40.0%	329	75	77.2%
562		5	0	100.0%	331	27	91.8%	5	0	100.0%	326	37	88.7%
564	32	5	0	100.0%	332	19	94.3%	5	2	60.0%	324	45	86.1%
566		5	1	80.0%	330	30	90.9%	5	1	80.0%	327	55	83.2%
567		5	0	100.0%	217	11	94.9%	5	0	100.0%	215	14	93.5%
572	17	5	0	100.0%	327	27	91.7%	5	3	40.0%	319	98	69.3%
573		5	0	100.0%	329	44	86.6%	5	0	100.0%	321	58	81.9%
579		5	0	100.0%	217	14	93.5%	5	1	80.0%	210	46	78.1%
580	54	5	1	80.0%	332	19	94.3%	5	2	60.0%	325	39	88.0%
581	76	5	0	100.0%	332	58	82.5%	5	3	40.0%	329	78	76.3%
584	Cncld	5	0	100.0%	216	32	85.2%	4	3	25.0%	208	135	35.1%
587	124	5	0	100.0%	324	21	93.5%	5	2	60.0%	315	67	78.7%
588	No OS	5	0	100.0%	215	23	89.3%	5	1	80.0%	213	44	79.3%
591	148	5	2	60.0%	329	28	91.5%	5	2	60.0%	322	51	84.2%
593	Cncld	5	2	60.0%	322	55	82.9%	4	2	50.0%	298	43	85.6%
595	No OS	5	3	40.0%	325	63	80.6%	5	1	80.0%	322	74	77.0%
611		1	0	100.0%	49	35	28.6%	1	0	100.0%	49	5	89.8%
624	104	1	0	100.0%	124	38	69.4%	1	1	0.0%	125	34	72.8%
660		1	0	100.0%	92	13	85.9%	1	0	100.0%	91	26	71.4%
661		1	0	100.0%	120	12	90.0%	1	0	100.0%	119	45	62.2%
662		1	0	100.0%	51	0	100.0%	1	0	100.0%	51	1	98.0%
663		1	0	100.0%	93	15	83.9%	1	0	100.0%	92	9	90.2%
664		1	0	100.0%	92	8	91.3%	1	0	100.0%	92	16	82.6%
665		1	0	100.0%	93	10	89.2%	1	0	100.0%	93	25	73.1%
666		1	0	100.0%	91	22	75.8%	1	0	100.0%	91	7	92.3%
667		1	0	100.0%	91	7	92.3%	1	0	100.0%	89	16	82.0%
669		1	0	100.0%	91	7	92.3%	1	0	100.0%	89	22	75.3%
670		1	0	100.0%	93	13	86.0%	1	0	100.0%	91	17	81.3%
671		1	0	100.0%	91	8	91.2%	1	0	100.0%	89	11	87.6%
672		1	0	100.0%	93	10	89.2%	1	0	100.0%	93	18	80.6%
674		1	0	100.0%	91	30	67.0%	1	0	100.0%	91	7	92.3%
689		3	0	100.0%	158	21	86.7%	3	0	100.0%	157	23	85.4%

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
690		1	0	100.0%	97	2	97.9%	1	0	100.0%	96	5	94.8%
691		1	0	100.0%	97	8	91.8%	1	0	100.0%	95	28	70.5%
692		1	0	100.0%	97	4	95.9%	1	0	100.0%	96	15	84.4%
693		1	0	100.0%	97	14	85.6%	1	0	100.0%	95	31	67.4%
694		1	0	100.0%	96	10	89.6%	1	0	100.0%	96	15	84.4%
695		1	0	100.0%	95	10	89.5%	1	0	100.0%	95	16	83.2%
696		1	0	100.0%	97	11	88.7%	1	0	100.0%	97	27	72.2%
697		1	0	100.0%	97	23	76.3%	1	0	100.0%	97	19	80.4%
698		1	0	100.0%	95	3	96.8%	1	0	100.0%	95	8	91.6%
701		5	0	100.0%	272	30	89.0%	5	1	80.0%	269	33	87.7%
702	Cncld	5	1	80.0%	339	37	89.1%	4	3	25.0%	335	86	74.3%
703		5	3	40.0%	340	115	66.2%	5	3	40.0%	338	103	69.5%
704		5	2	60.0%	271	51	81.2%	5	3	40.0%	263	62	76.4%
710	55	5	1	80.0%	340	80	76.5%	4	3	25.0%	335	91	72.8%
711		5	1	80.0%	331	39	88.2%	5	1	80.0%	308	66	78.6%
712		5	3	40.0%	337	94	72.1%	5	3	40.0%	327	117	64.2%
713	17	4	2	50.0%	206	22	89.3%	3	3	0.0%	180	83	53.9%
714		5	4	20.0%	221	96	56.6%	5	4	20.0%	205	99	51.7%
715		5	1	80.0%	339	64	81.1%	4	3	25.0%	309	158	48.9%
716		5	3	40.0%	340	146	57.1%	5	4	20.0%	331	145	56.2%
718	270	5	5	0.0%	340	183	46.2%	5	5	0.0%	337	134	60.2%
719	52	5	2	60.0%	340	115	66.2%	5	2	60.0%	323	100	69.0%
720		1	1	0.0%	104	10	90.4%	1	0	100.0%	104	6	94.2%
723	24	1	0	100.0%	104	5	95.2%	1	1	0.0%	104	12	88.5%
724	11	1	0	100.0%	104	5	95.2%	1	1	0.0%	102	23	77.5%
727		1	0	100.0%	104	9	91.3%	1	0	100.0%	104	15	85.6%
728		1	0	100.0%	104	7	93.3%	1	0	100.0%	104	18	82.7%
729		1	0	100.0%	103	16	84.5%	1	0	100.0%	102	25	75.5%
732	Cncld	1	1	0.0%	102	20	80.4%	0	0	0.0%	99	21	78.8%
733	17	1	0	100.0%	104	14	86.5%	1	1	0.0%	99	33	66.7%
734	21	1	0	100.0%	104	16	84.6%	1	1	0.0%	103	25	75.7%
736		1	0	100.0%	80	8	90.0%	1	0	100.0%	78	12	84.6%
737	25	1	0	100.0%	80	7	91.3%	1	1	0.0%	79	15	81.0%
738	39	1	0	100.0%	104	15	85.6%	1	1	0.0%	98	15	84.7%
741		1	0	100.0%	104	15	85.6%	1	0	100.0%	104	20	80.8%
742		1	0	100.0%	101	13	87.1%	1	0	100.0%	98	7	92.9%
743		1	0	100.0%	104	21	79.8%	1	0	100.0%	100	12	88.0%
744		1	1	0.0%	104	17	83.7%	1	0	100.0%	104	34	67.3%
745	No OS	1	0	100.0%	104	13	87.5%	1	1	0.0%	103	17	83.5%
746		1	0	100.0%	104	9	91.3%	1	0	100.0%	103	15	85.4%
747		1	0	100.0%	104	16	84.6%	1	0	100.0%	104	25	76.0%
748		1	0	100.0%	103	14	86.4%	1	0	100.0%	103	14	86.4%

Amtrak On Time Performance

Trains Arriving Through: 9/5/2026

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
749		1	0	100.0%	101	15	85.1%	1	0	100.0%	92	12	87.0%
751		1	0	100.0%	103	17	83.5%	1	0	100.0%	99	11	88.9%
757		5	0	100.0%	125	7	94.4%	5	1	80.0%	124	15	87.9%
761		5	0	100.0%	336	13	96.1%	5	0	100.0%	333	44	86.8%
765		5	0	100.0%	336	25	92.6%	5	1	80.0%	336	47	86.0%
769	35	5	0	100.0%	336	27	92.0%	5	2	60.0%	329	67	79.6%
770	31	5	0	100.0%	336	25	92.6%	5	1	80.0%	333	105	68.5%
774	20	5	0	100.0%	336	17	94.9%	5	2	60.0%	334	82	75.4%
777	67	5	0	100.0%	221	13	94.1%	5	5	0.0%	220	63	71.4%
782	256	5	2	60.0%	221	107	51.6%	5	2	60.0%	216	38	82.4%
785	25	5	1	80.0%	336	30	91.1%	5	3	40.0%	336	64	81.0%
786	Cncld	5	1	80.0%	125	24	80.8%	4	2	50.0%	120	68	43.3%
790	No OS	5	0	100.0%	336	31	90.8%	5	1	80.0%	333	55	83.5%
794	36	5	0	100.0%	336	40	88.1%	5	1	80.0%	332	77	76.8%
821		4	0	100.0%	333	6	98.2%	4	2	50.0%	333	142	57.4%
822		5	1	80.0%	336	19	94.3%	4	3	25.0%	333	173	48.0%
1333		5	0	100.0%	336	40	88.1%	5	1	80.0%	333	113	66.1%
1340		5	0	100.0%	335	7	97.9%	5	0	100.0%	334	56	83.2%
2203		1	0	100.0%	66	9	86.4%	1	0	100.0%	66	17	74.2%
2207		1	0	100.0%	29	5	82.8%	1	0	100.0%	29	6	79.3%
2208		1	0	100.0%	22	5	77.3%	1	0	100.0%	22	5	77.3%
2211	35	1	1	0.0%	12	2	83.3%	1	1	0.0%	12	3	75.0%
2219		1	0	100.0%	22	4	81.8%	1	0	100.0%	22	6	72.7%
2224		1	0	100.0%	37	6	83.8%	1	0	100.0%	36	4	88.9%
2226		1	0	100.0%	42	8	81.0%	1	0	100.0%	40	10	75.0%
2250		1	0	100.0%	110	12	89.1%	1	0	100.0%	109	35	67.9%
2252		1	0	100.0%	117	10	91.5%	1	0	100.0%	115	32	72.2%
2254		1	0	100.0%	52	3	94.2%	1	0	100.0%	52	13	75.0%
2255		1	0	100.0%	119	12	89.9%	1	0	100.0%	118	55	53.4%
2256		1	0	100.0%	19	3	84.2%	1	0	100.0%	18	7	61.1%
2258		1	0	100.0%	55	9	83.6%	1	0	100.0%	54	24	55.6%
2259		1	0	100.0%	75	26	65.3%	1	0	100.0%	74	35	52.7%
2260		1	0	100.0%	21	2	90.5%	1	0	100.0%	21	12	42.9%
2262		1	0	100.0%	27	5	81.5%	1	0	100.0%	27	9	66.7%
2263	46	1	0	100.0%	16	0	100.0%	1	1	0.0%	15	3	80.0%
2265		1	0	100.0%	56	6	89.3%	1	0	100.0%	55	29	47.3%
2267		1	0	100.0%	19	3	84.2%	1	0	100.0%	18	10	44.4%
2271		1	0	100.0%	102	11	89.2%	1	0	100.0%	101	47	53.5%
2293		1	0	100.0%	20	3	85.0%	1	0	100.0%	20	3	85.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2211	WAS	35	SVS	27	SVS	27	NYP-NYP	AM	Water, commissary, toilet/trash dumping, DELAYED A/C COMMISSARY LOADING BISTRO CAR	
2263	WAS	46	ENG	31	ENG	31	XSH-NYP	AM	Other electrical failure, 2119 NG NP, MCB OPEN ON NO. 1 TRK BETWEEN GATE AND HAROLD INTS	
88	BOS	45	ENG	35	ENG	35	WAS-WAS	AM	HEP, 600 EX ES, TROUBLESHOOTING TRAILING UNIT FAULT	
107	WAS	69	MTI	73	MTI	52	XPV-BAL	AM	Disabled train ahead, Milepost, 59.4, 95.7, shadowed 159, 159 opr 30 MPH a/c brake issues	
124	PHL	18	DMW	10	DMW	10	BAL-ABE	AM	Held for or routed around MW work or equipment, Milepost, 62.9, ., opr 3 track and platformed off 3 track at Aberdeen a/c report of rough track at No. 2 track at Oak	
126	NYP	42	MTI	30	MTI	30	WAS-WAS	AM	Disabled train ahead, Control Point, NYP, acses fault on cab car delayed arrival A127 for A126	
127	WAS	89	ENG	39	ENG	39	PHL-PHL	AM	PTC - On Board Cab Signal or PTC Failure, 653 EX ES, INOPERATABLE CAB SIGNALS ON E/653	
135	WAS	66	MTI	59	MTI	42	ABE-BAL	AM	Disabled train ahead, Milepost, 51, 95.7, shadowed 159 to Baltimore a/c 159 had brake issues, will receive transfer from 159 in Baltimore	
150	BOS	23	ENG	14	ENG	14	RTE-BBY	AM	HEP, 640 EX ES, AM150 stopped at MP 222.74 due to main res issues on E/640	
159	WAS	Trn Cancelled	ENG	123	ENG	63	WIL-XPV	AM	Air / Brake, 665 EX ES, Stopped at MP 44.8 and again at Bacon with multiple faults and brake issues	
163	WAS	24	HLD	15	CTI	9	NHV-BRP	MN	Cross over or go around MNR, Control Point, 266	
198	NYP	108	POL	112	POL	112	PHL-PHL	AM	Right of Way police hold, HELD FOR POLICE ACTIVITY. POSSIBLE SUICIDAL PASSENGER W/ KNIFE AT N. PHILA	
460	SPG	30	CTI	15	CTI	15	WND-WNL	AM	Meet, ctrail, 6403, Milepost, xha, xha	
461	NHV	38	ENG	20	ENG	20	WND-WND	AM	HEP, 9636 CB CC, AM461 stopped at Windsor due to an ACSES fault on E/9636	
488	GFD	24	CON	50	CON	50	NHV-NHV	AM	Hold for connecting train, late connection of AM88	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/5/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
52	LOR	83	PTI	72	PTI	50	XJG-XSA	CS	Follow PO98, Milepost w/Letters, A525.0, A491.0	
53	SFA	254	WTR	177	WTR	88	XV7-XSE	CS	High winds Milepost w/Letters, a25.9, a127.0	
624	NYP	104	POL	111	POL	111	PHL-PHL	AM	Right of Way police hold, HELD FOR POLICE ACTIVITY. POSSIBLE SUICIDAL PASSENGER W/ KNIFE AT N. PHILA	
63	TWO	146	CUI	51	CUI	51	NFL-NFL	XC	United States	
235	ALB	75	RTE	54	RTE	54	CRT-POU	MN	Dispatcher hold Control Point, 58	
237	ALB	40	PTI	28	PTI	28	CRT-POU	MN	Meet amtrak 48, amtrak 244, Control Point, 58	
238	NYP	27	ENG	21	ENG	21	ALB-ALB	AM	Set out defective locomotive Equipment swap with train 240 due to multiple faults on Eng 708, 708	
240	NYP	72	ENG	57	ENG	57	ALB-ALB	AM	Traction motor Engine fail, had to swap equipment for 238, 708	
244	NYP	51	RTE	35	RTE	35	RHI-XCP	MN	Dispatcher hold Held at 75. Single tracking POU to cp58, Control Point, cp75	
283	NFL	20	DMW	41	DMW	41	CRT-POU	MN	Held for or routed around MW work or equipment Held for MN 8844, Control Point, 58	
290	NYP	35	ENG	40	ENG	34	CNV-XWH	VR	HEP Issue with HEP and main reservoir on the move now, 702	
291	BTN	164	ITI	63	ITI	63	NYP-NYP	AM	Service, turn, or wye train, 240	
48	NYP	67	FTI	46	DCS	18	ERI-BUF	CS	Restrictive signal(s) from unknown cause Restricted Proceed. No traffic and no radio communication from IG Dispatcher, QD 71, Other, QD 71	
43	PGH	37	SVS	39	SVS	39	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, WAITED FOR MECHANICAL TO FINISH WORK ON TRAIN 127.	
74	RGH	16	DSR	13	DSR	6	BNC-DNC	NS	Per bulletin Milepost w/Letters, 26.6NC, 28.6NC, 25, track 1	
75	CLT	16	DSR	12	DSR	8	DNC-BNC	NS	Per bulletin Milepost w/Letters, 28.6NC, 26.6NC, 25, 1	
76	RGH	32	PTI	27	PTI	27	GRO-DNC	NS	Meet Amtk 79, Control Point, Funston	
89	SAV	32	WTR	56	WTR	16	PTB-RMT	CS	Heat order Other, NE Sub	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/5/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
97	MIA	92	ENG	89	ENG	89	NYP-NYP	AM	Other electrical failure, 602 EX ES, DISABLED IN LINE 2 A/C MECHANICAL ISSUES	
98	NYP	180	CAR	107	CAR	107	MIA-MIA	FL	Held for Car 68024 mechanical issues. 68024	
40	CHI	451	SVS	203	SVS	140	MIA-MIA	FL	Lead locomotive 134 failure during mechanical inspection at Miami mechanical facility. Locomotive needs to be removed and no replacement.	
41	MIA	353	FTI	128	ENG	80	CHI-CHI	AM	Late road power, adding Eng/10 off inbound 22(02) the same day 10	
23	NOL	16	FTI	23	FTI	23	BAS-XNO	CS	Meet CSX 602, Siding, Claiborne	
723	SJC	24	PTI	22	PTI	20	FMT-GAC	UP	Meet Amtk 724 North, Control Point, S. Albrae	
724	SAC	11	ADA	10	PTI	5	GAC-FMT	UP	Cross over or go around AMT 723, Siding, Albrae	
732	SAC	Tm Cancelled								
733	SJC	17	PTI	13	PTI	11	GAC-SCC	UP	Meet AMT 734, Control Point, Expressway	
734	SAC	21	MBO	22	MBO	22	MTZ-SUI	UP	For maritime traffic Control Point, RV033	
737	OKJ	25	PTI	13	PTI	13	EMY-OKJ	UP	Wait for station track Per UP DS62, stopped at CP NI006 King Street, on MT2, to allow Amtrak 734 to work OKJ Depot and then depart before we pulled in., Amtrak 734, Control Point, CP NI006 King Street	
738	SAC	39	MBO	40	MBO	40	MTZ-SUI	UP	For maritime traffic Control Point, Suisun Bridge	
745	SJC	No OS Rpt	PTI	17	PTI	6	EMY-OKJ	UP	Meet AMT 715, Control Point, Magnolia	
51	CHI	215	TRS	177	TRS	177	IND-CRF	CS	Trespasser strike Milepost w/Letters, qsc2.4, qsc2.6	
504	SEA	51	POL	36	POL	36	EUG-EUG	UP	RR blocked by trespasser or vehicle strike by another train Red at CPVP 648, UP 6881 had a trespasser strike. Wait for police to clear tracks.	
505	PDX	109	CCR	103	CCR	103	SEA-SEA	BN	Onboard HBD alarm 7911, Train swap due to hot bearing alarm	
518	VAC	71	ITI	47	ITI	47	PDX-PDX	BN	Late arrival of train 505. Also needed to pump bathrooms 505	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/5/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
58	CHI	139	DSR	108	DSR	22	JAN-YAZ	CC	Per bulletin Milepost, 216, 210, 40, main, Milepost, 200.2, 199.9, 10, main, Milepost, 190.3, 189.0, 25, main, Milepost, 189, 172, 40, main
59	NOL	88	DSR	128	DSR	25	MCB-HMD	CC	Per dispatcher (radio/phone) Milepost, 823, 849, 40, main
11	LAX	61	FTI	66	SVS	38	SAC-SAC	UP	Fuel
27	PDX	-8	CON	30	CON	30	SPK-SPK	BN	Late arrival of 7 into SPK
28	SPK	37	SVS	35	SVS	35	BNG-WIH	BN	Pick up equipment Pick up car 33011 @ BNG
337	MKE	13	FTI	16	FTI	16	GLN-XRO	ME	Follow 249, Control Point, XRO
338	CHI	12	PTI	17	PTI	17	SVT-XRO	CP	Meet AMTK7, AMTK337, Control Point, XRO
350	DET	65	PTI	47	PTI	36	KAL-XGO	MI	Meet amtk351, Control Point, gord
351	CHI	146	SVS	151	SVS	151	PNT-PNT	CC	Unplanned Wye Due to wide guage in CN yard Pontiac, Equipment had to be wyed in Detroit at sugar house wye
354	PNT	125	PTI	77	PTI	43	KAL-KAL	MI	Holding out. Talked to train director and CNOC central. Held at Kalamazoo for pax comfort. Waiting for 355 to go past ALI, Amtrak 355, Other, Kalamazoo Station
355	CHI	88	OTH	63	OTH	56	DER-DER	MI	Delayed departure due to BP air issues.
364	PTH	39	FTI	49	FTI	29	LPE-PTH	CC	Meet Follow Eastbound CN 3172 stopping at MP317. Wait on Westbound CN3038, CN3038, Siding, Emmett
564	SAN	32	CTI	23	CTI	15	SNC-SNP	SC	Meet Scax, ML 1661, Control Point, Serra
572	SAN	17	RTE	18	RTE	11	SNA-IRV	SC	Routed to abnormal station track due to N.A.R. 1, Control Point, tinkham
580	SAN	54	DMW	20	DMW	20	SNP-SNP	SC	Waiting for MW clearance ML5181, Control Point, pier
581	LAX	76	DCS	80	DCS	73	OSD-X98	SC	Red/stop signal songs. Trains flagging because of high tides and wet rail Control Point, songs
584	SAN	Trn Cancelled	CTI	39	CTI	39	IRV-SNC	SC	Meet mtlk, Control Point, trabuco
587	LAX	124	CTI	130	CTI	130	OSD-X98	SC	Meet Metrolink, 6088, Control Point, Songs
588	SAN	No OS Rpt	WTR	114	WTR	74	IRV-SNC	SC	Stopped due to high surf near tracks at MP 206.5 Control Point, Trabuco

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/5/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
591	LAX	148	WTR	114	WTR	54	OSD-OSD	SN	High tide at SNP. Trains being flagged. Stopped at OSD station., Control Point, pacific	
593	LAX	Trn Cancelled								
595	LAX	No OS Rpt	ITI	156	ITI	156	SAN-SAN	SN	Service, turn, or wye train 782, Late arriving inbound equipment from train 782.	
769	GTA	35	DCS	16	PTI	10	OSD-X98	SN	Meet 564, Control Point, songs	
770	SAN	31	CTI	28	CTI	14	SOL-SOL	SN	Meet coaster, 677, Control Point, Valley	
774	SAN	20	DCS	35	DCS	25	CPN-VEC	UP	Restrictive signal(s) from known wayside signal failure Restricted speed due to red signal from unknown track issue. Flagging block per Dispatcher instructions., Red/ Stop, Control Point, S Seacliff, Other, Ventura Sta	
777	SLO	67	PTI	56	PTI	32	OXN-VEC	UP	Meet 790, Control Point, N. Ventura	
782	SAN	256	CTI	206	CTI	198	SNC-SNP	SC	Meet Waited in the siding for Amtrak 785 and Metrolink 1667. Metrolink 1668 then went east ahead of us. Dispatcher told us we would follow them, then changed the plan to us waiting for 2 more Westbound trains with no explanation available as to why., Amtrak, 785, Metrolink, 1667, Amtrak, 587, Metr	
785	GTA	25	PTI	44	PTI	44	OSD-X98	SC	Meet 580, Control Point, songs	
786	SAN	Trn Cancelled	POL	67	POL	67	LPS-X3G	UP	Right of Way police hold	
790	SAN	No OS Rpt	RTE	68	RTE	58	SNA-SNA	SC	Dispatcher hold Waiting for tracks to clear ahead, Milepost, 175, 175	
794	SAN	36	CON	30	CON	30	LAX-LAX	SC	Hold for thruway bus	
702	BFD	Trn Cancelled								
710	BFD	55	TEN	34	TEN	34	MCD-MCD	BN	Onboard HBD alarm Hot journal alarm. Axle 3 says 662F• temp stick showed nothing. Instructed by Tasi to run it., C2106	
713	OKJ	17	PTI	19	PTI	8	TRK-MOD	BN	Meet 712, Control Point, W Empire	
718	BFD	270	TCC	270	TCC	270	EMY-EMY	UP	Air / Brake / Wheel 8312, Decellostat replacement unsuccessful. Replaced with amtk 90218	
719	OKJ	52	ITI	38	ITI	38	BFD-BFD	BN	Service, turn, or wye train 710	
22	CHI	46	DSR	79	FTI	30	MVN-LRK	UP	Follow UP 7940, Milepost, 389, 360	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/5/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
300	CHI	205	TRS	178	TRS	178	ALN-CRV	UP	Trespasser strike Other, 252.3
301	STL	44	WTR	44	WTR	33	SPI-ALN	UP	Heat order Level 2 heat restriction in effect. Max speed 50mph., Other, -
302	CHI	77	POL	34	POL	34	STL-XQT	TR	RR blocked by trespasser or vehicle strike by another train
305	STL	Tm Cancelled							
306	CHI	46	WTR	37	WTR	21	CRV-SPI	UP	Heat order Milepost, 281.45, 173.00
307	STL	38	ENG	45	ENG	45	CHI-CHI	AM	ENGINE PROBLEMS NEED TO BE FIXED . Late arrival of train, ID4633
381	QCY	56	SYS	48	SYS	39	CHI-XUA	AM	PTC not allowing ENGR to log in. CNOC mechanical instructed to cycle PTC breaker 3 times. Wouldn't get passed departure test Chicago mechanical logged in and addressed communication issue.
382	CHI	34	CTI	32	CTI	32	NPV-LAG	BN	Follow METRA, Milepost, 27.0, 12.9
383	QCY	56	FTI	42	FTI	24	MAC-QCY	BN	Meet BNSF 7369, Siding, Colchester
390	CHI	111	SYS	52	SYS	46	CHM-RTL	CC	Re-crew / job briefing Train waiting for 391 to change out crew
391	CDL	58	FTI	20	FTI	20	HMW-KKI	CC	Meet CN 195, Control Point, peotone
392	CHI	65	WTR	51	DMW	17	CEN-EFG	CC	Held for or routed around MW work or equipment Rough track reported at Effingham Diamond, Control Point, Effingham
393	CDL	50	WTR	29	FTI	9	X9R-XCS	CT	Cross Traffic UNKNOWN, Control Point, 16th
311	KCY	130	WTR	76	WTR	28	JEF-SED	UP	Heat order Other, Sedalia Sub
316	STL	83	FTI	30	ITI	27	KCY-KCY	KC	Service, turn, or wye train 311
318	CHI	299	FTI	162	FTI	48	JEF-HEM	UP	Follow Milepost, 128, 120, up 8234
319	KCY	156	DSR	109	FTI	45	JEF-SED	UP	Cross over or go around Pull behind train at shell on main TRK then shove out and go through the siding after the train shoved back to clear the west end, up 7015, Siding, shell

Amtrak Initial Terminal Details

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/5/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	238	09/05	21	21	Set out defective locomotive Equipment swap with train 240 due to multiple faults on Eng 708, 708
ALB	240	09/05	57	57	Traction motor Engine fail, had to swap equipment for 238, 708
CLT	80	09/05	11	11	Service, turn, or wye train 79, Wye train.
GFD	499	09/05	11	11	Unknown
MTR	68	09/05	1		
NYP	127	09/05	4	4	Door, 82745 AX AS
NYP	235	09/05	20	20	Service, turn, or wye train, 238
NYP	245	09/05	8	8	Waiting for MW clearance, Other, NYP-NYP, HELD IN STATION FOR TRACKCAR TO CLEAR EMPIRE INT.
NYP	283	09/05	13	14	Electrical failure, 8208, MECHANICAL ISSUES SSYD CAR 82808 SHOPPED BRAKER BAD ORDER, REPLACEMENT 82767
NYP	291	09/05	63	63	Service, turn, or wye train, 240
NYP	2211	09/05	27	27	Water, commissary, toilet/trash dumping, DELAYED A/C COMMISSARY LOADING BISTRO CAR
PHL	144	09/05	4	4	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	150	09/05	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
RGH	73	09/05	4	4	Loading problem NC1755
SFA	52	09/05	108	108	Service, turn, or wye train 53
WAS	88	09/05	63	35	HEP, 600 EX ES, TROUBLESHOOTING TRAILING UNIT FAULT
WAS	88	09/05	63	28	Hold for defect repair, Control Point, WYE BRIDGE , TRACK FROM HOLDING WEST LEG WYE OOS DELAYING WYE OPERATION OF POWER EQUIPMENT
WAS	126	09/05	30	30	Disabled train ahead, Control Point, NYP, acses fault on cab car delayed arrival A127 for A126
WAS	146	09/05	1	1	Wait for scheduled departure time
CHI	41	09/05	119	119	Late arriving train 40
CHI	50	09/05	85	85	Service, turn, or wye train 51
CHI	59	09/05	32	32	Late release from the yard due to engine problems 193
CHI	307	09/05	32	32	Accommodating passenger from cancelled 305 IDTX 4631 engine trouble, ID4633
CHI	381	09/05	6	6	PTC software issue not allowing ENGR to log in. CNOC mech instructed to cycle PTC breaker 3 times. Wouldn't get passed departure test. CHI mechanical came to log in and address communication issue.
CHI	383	09/05	19	19	No water going to the galley ID4316

Amtrak Initial Terminal Details

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/5/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	393	09/05	5	5	Service, turn, or wye train 390
DER	355	09/05	58	56	Delayed departure due to BP air issues.
KCY	316	09/05	27	27	Service, turn, or wye train 311
PNT	351	09/05	151	151	Unplanned Wye Due to wide guage in CN yard Pontiac, Equipment had to be wyeed in Detroit at sugar house wye
STL	300	09/05	6	6	Wheelchair 5 Wchr lifts 10 mobility impaired. Broken escalator, passengers sent to the wrong track for boarding.
BFD	719	09/05	38	38	Service, turn, or wye train 710
EUG	504	09/05	36	36	RR blocked by trespasser or vehicle strike by another train Red at CPVP 648, UP 6881 had a trespasser strike. Wait for police to clear tracks.
EUG	508	09/05	7	7	Blocked from station track Held for train entering EUG yard. Late loading of PASSENGERS arrived 4:28, Siding, PNW, UP 7697
OKJ	712	09/05	8	8	Follow amtk 724, Control Point, north jack London
OKJ	714	09/05	22	22	Cab car was unclean had to wait for tasi cleaners to clean car C8312
OKJ	716	09/05	12	12	Power needed fuel causing delay C2004
OKJ	718	09/05	1		
OKJ	720	09/05	6	6	Follow Amtrak 710 had late blue flag drop from TASI mechanical. Normal lineup from UP DS62 has us follow 710 from the yard to OKJ Depot., Amtrak 710, Other, Oakland Mechanical Yard
OKJ	732	09/05	(Trn Cxld)		Third Party Engine Failure
PDX	518	09/05	47	47	Late arrival of train 505. Also needed to pump bathrooms 505
SAC	702	09/05	(Trn Cxld)		Third Party Engine Failure
SAC	704	09/05	1	1	Restrictive signal(s) from unknown cause Red/stop, Control Point, rv990
SAN	591	09/05	24	24	Service, turn, or wye train 580
SAN	593	09/05	(Trn Cxld)		Track Washout
SAN	595	09/05	156	156	Service, turn, or wye train 782, Late arriving inbound equipment from train 782.
SEA	11	09/05	2	2	Late due to taking on 40 passengers from the mechanically troubled AMTK 505
SEA	505	09/05	103	103	Onboard HBD alarm 7911, Train swap due to hot bearing alarm
SEA	509	09/05	1	1	Crew rest Control Point, sea
SJC	744	09/05	1		
SPK	27	09/03	30	30	Late arrival of 7 into SPK

Eastern Region

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	99.6	94.8	166	1
CDOT	95.0	87.5	89.6	92.4	16	2
MARC	95.0	94.4	92.3	90.2	18	1
SEPTA	95.0	89.2	92.9	91.5	111	12
NJT-NED	95.0	97.4	93.5	88.6	194	5
NJT-SED	95.0	100.0	98.3	97.2	111	12

Operating Highlights

Train 40(04) - South of Connellsville, PA - Routing

05SEP26: Train 40(04) was delayed on the CSX Keystone Subdivision at MP 252.2 due to the dispatcher holding the train while CSX trains worked into the yard at Connellsville.

Train	Delay	Comment
40 (04)	40"	

Train 291(05) - Albany-Rensselaer Station, NY - System

05SEP26: Train 291(05) was delayed at Albany-Rensselaer Station/MP 142.6 due to swapping sets with the 235(05) equipment. This move was necessary because the paperwork for the inbound 291(05) set was due to expire at midnight.

Train	Delay	Comment
291 (05)	45"	

Train 159(05) - North of Baltimore, MD - Engine Failure

05SEP26: Train 159(05) stopped at MP 51.6 on the Amtrak PW Line due to a recurring speed sensor fault. The engineer also requested protection to inspect the consist due to braking inconsistencies. There were no exceptions taken upon inspection. The train continued south into Baltimore with an average speed of 30MPH, as to not trigger the overspeed alert. The equipment was inspected again at Baltimore. The issue could not be rectified.

Trains 135(05) and 107(05) shadowed Train 159(05) into Baltimore.

All 411 passengers were transferred to Train 135(05) and Train 107(05) for all stops south of Baltimore into Washington Union Terminal.

HEP was maintained throughout.

The 159(05) equipment was deadheaded to WAS by a relief crew.

Train	Delay	Comment
159 (05)	2'03" MP 51.6 - BAL	Term BAL
107 (05)	1'13"	Shadow and Receive at BAL
135 (05)	59"	Shadow and Receive at BAL

North of Croton Harmon Station, NY - M of W Work

05SEP26: Multiple Amtrak trains were delayed between Croton Harmon/MP 33.3 and Poughkeepsie/MP 73.7, NY on the Metro North Hudson Line due to being held for MW work.

Train	Delay	Comment
283 (05)	41"	
49 (05)	49"	
235 (05)	51"	
291 (05)	55"	
237 (05)	35"	

Train 2263(05) East of New York, NY - Engine Failure

05SEP26: Train 2263(05) operating with power car 2125 and 257 customers onboard was stopped between Gate and Harold interlockings on the Amtrak NYS Line due to the MCB opening on the power car. The crew was able to troubleshoot with the road foreman and get the MCB closed. The crew was able to raise the pantograph and perform a brake test. Train 2263(05) was able to advance to the next station.

Train	Delay	Comment
2263 (05)	31"	

Train 127(05) Philadelphia, PA - Engine Failure

05SEP26: Train 127(05) operating with cab car 9632, 10 cars, engine 649, and 574 customers onboard was delayed departing Philadelphia, PA on the Amtrak PW Line due to adding engine 653 to the head end of the consist. Train 127(05) cut out cab signals while departing New York in the North Tube. The train operated at a reduced speed to Philadelphia where engine 653 could be added. Once the engine was added to the consist, Train 127(05) departed Philadelphia at 1:07 PM-ET.

Train 43(05) operating with 268 customers was scheduled for an engine change in Philadelphia shortly after Train 127(05) arrived. Train 43(05) had to wait for their engine change to be completed until mechanical was finished adding the engine to Train 127. Once the scheduled engine change was completed, Train 43(05) departed Philadelphia at 1:24 PM-ET.

Train	Delay	Comment
127 (05)	39"	
43 (05)	39"	
126 (05)	30"	Late turn 127(05)

Train 290(05) North of Fort Edward-Glens Falls, NY - Engine Failure

05SEP26: Train 290(05) operating with engine 702, 5 cars, cab car 9703, and 75 customers onboard was stopped at milepost 77.5, 21 miles north of Fort Edward-Glens Falls, NY on the Canadian Pacific Canadian subdivision due to engine failure on engine 702. The train lost head end power and was having issues with the main res as well. The crew worked with Albany mechanical and CNOC mechanical to troubleshoot the issue. The issue was able to be rectified by resetting two IMC cards. The train was back on the move at 12:34 PM-ET.

Train	Delay	Comment
290 (05)	34"	

Train 240(05) Albany-Rensselaer, NY - Initial Terminal delay - Engine Failure

05SEP26: Train 240(05) operating with engine 708, 5 cars, and 171 customers was delayed departing Albany-Rensselaer, NY on the Amtrak HUD Line due to multiple faults on the original engine 708. Multiple attempts were made by mechanical to troubleshoot the originally planned equipment with no success. The train swapped equipment with Train 238(05). Once the equipment swap was completed, Train 240(05) departed Albany-Rensselaer.

Train 238(05) operating with 147 customers was delayed departing Albany-Rensselaer due to swapping engines off of the failed equipment. Engine 708 was replaced with engine 701. Once the engine swap was completed, Train 238(05) departed the station at 12:31 PM-ET.

Train 291(05) was delayed departing New York, NY due to turn of late equipment from Train 240(05).

Train	Delay	Comment
240(05)	57"	
238(05)	21"	
291(05)	1'03"	Late turn 240(05)
235(05)	20"	Late turn 238(05)

Train 88(05) Washington, DC - Initial Terminal Delay - Engine Failure

05SEP26: Train 88(05) operating with engine 661, 8 cars, and 183 customers onboard was delayed departing Washington, DC on the Amtrak WT Line due to a worn pantograph on engine 661 requiring the engine to be wye'd. Once the engine was wye'd and added to the consist, the engine displayed a trailing unit fault. Mechanical responded to the train and replaced cables. The train was able to recover and departed Washington at 12:28 PM-ET.

Train	Delay	Comment
88(05)	1'03"	

Train 41(04) West of Connellsville, PA - Freight Train Interference

05SEP26: Train 41(04) operating with engines 145, 199, 10 cars, and 159 customers onboard was delayed beginning at milepost 11.3, 46 miles west of Connellsville, PA on the CSX Pittsburgh subdivision due to following CSX freight train M332-03 from milepost 11.3 to milepost 272.5. Once the freight train cleared, Train 41(04) was able to advance to the next station.

Train	Delay	Comment
41(04)	30"	

CSX Heat Orders - Weather

05SEP26: Trains were delayed on the following CSX subdivisions due to heat orders in effect between 100PM-ET through 700PM-ET: Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, and Tampa Terminal.

Train	Delay	Comment
98(05)	42"	
40(05)	42"	
52(05)	08"	
97(04)	33"	

Train 53(04) North of Fayetteville, NC - Freight Train Interference

05SEP26: Train 53(04) operating with engines 360, 380, 37 cars, and 330 customers onboard was delayed at milepost 197.2, 12 miles north of Fayetteville, NC on the CSX South End subdivision due to meeting CSX freight train I036. Once the freight cleared, Train 53(04) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(04)	36"	

Train 53(04) North of Charleston, SC - Freight Train Interference

05SEP26: Train 53(04) operating with engines 360, 380, 37 cars, and 330 customers onboard was delayed at milepost 376.8, 11 miles north of Charleston, SC on the CSX Charleston subdivision due to meeting CSX freight train 410. Once the freight cleared, Train 53(04) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(04)	46"	

Train 40(03) East of Cumberland, MD - Freight Train Interference

05SEP26: Train 40(03) operating with engines 132, 305, 10 cars, and 112 customers onboard was delayed at milepost 177.0, 1 mile east of Cumberland, MD on the CSX Cumberland Terminal subdivision due to meeting CSX freight train I018. Once the freight train passed, Train 40(03) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(03)	35"	

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
240(29)	29"	
280(29)	18"	
233(29)	54"	
283(29)	64"	
284(29)	39"	
291(29)	36"	
290(29)	47"	
49(29)	49"	
235(29)	49"	
48(28)	31"	
237(29)	36"	
239(29)	1'10"	
69(30)	51"	
240(30)	35"	
1233(30)	18"	
291(30)	45"	LATE TURN OFF 240(30)

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

- Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.
- Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.
- Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.
- Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.
- Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.
- Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.
- Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.
- Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.
- Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.
- Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.
- Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.
- Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77 (03)	50"	
78 (03)	50"	Turn of Late 77 (03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008778 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008776 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Train 2/422(04) West of Del Rio, TX - Injured or Sick Passenger or Employee

06SEP26: Train 2/422(04), with 123 customers onboard, was delayed at Langtry/MP443.4, 65 miles west of Del Rio, TX/MP378.6, on the UP Sanderson subdivision holding for local EMS to assess a customer, PNR# E95599, who was sometimes unresponsive. The customer refused to be taken to a hospital and remained on the train. Once EMS was clear of the equipment, train 2/422(04) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(04)	1'16"	

Train 7/27(05) East of St. Cloud, MN - Trespasser Incident

06SEP26: Train 7/27(05), with 178 customers onboard, was delayed at Big Lake/MP48.0, 56 miles east of St. Cloud, MN/MP78.88, on the BNSF Staples subdivision due to a possible trespasser strike. The trespasser was seen close to the tracks at train 7/27(05) passed. The conductor and local police walked the train and found the trespasser injured but conscious. Amtrak Police and the local authorities investigated and determined that the incident was a near miss. Train 7/27(05) was released and continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(05)	57"	

Train 382(05) East of Naperville, IL - Commuter Train Interference

05SEP26: Train 382(05), with 50 customers onboard, was delayed between mile post 27.0 and mile post 12.9, beginning 1.5 miles east of Naperville, IL/MP28.5, on the BNSF Chicago subdivision following a Metra Commuter train. Once the route was clear, train 382(05) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
382(05)	32"	

Train 354(05) Kalamazoo, MI - Passenger Train Interference

05SEP26: Train 354(05), with 189 customers onboard, was delayed at Kalamazoo, MI/MP143.4 on the Amtrak Michigan Line meeting Amtrak train 355(05). Once the route was clear, train 354(05) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(05)	43"	

Train 5(05) East of Creston, IA - Freight Train Interference

05SEP26: Train 5(05), with 141 customers onboard, was delayed at control point 3818/MP381.8, 11 miles east of Creston, IA/MP393.1, on the BNSF Ottumwa subdivision meeting BNSF freight BN/5794. Once the route was clear, train 5(05) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(05)	30"	

Train 777(05) South of Ventura, CA - Passenger Train Interference

05SEP26: Train 777(05), with 100 customers onboard, was delayed south of Ventura, CA, at North Ventura (MP 395.1) on the Union Pacific Santa Barbara Subdivision while meeting Train 790(05).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
777(05)	32"	

Train 22(05) South of Marshall, TX - Freight Train Interference

05SEP26: Train 22(05), with 77 customers onboard, was delayed at west Keokuk siding/MP76.2, 10 miles south of Marshall, TX/MP66.5, on the UP Little Rock subdivision meeting UP freight UP/2746. UP reported that the freight needed to be split so the available power could pull the equipment into the clear. Once the route was open, train 22(05) continued north into Marshall.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(05)	2'16"	

Train 738(05) East of Martinez, CA - Drawbridge Opening

05SEP26: Train 738(05) was delayed east of Martinez, CA, while holding at Vista (MP 32.7) on the Union Pacific Martinez Subdivision due to the Suisun Bay Bridge being opened for maritime traffic.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
738(05)	40"	

Train 319(05) East of Sedalia, MO - Freight Train Interference

05SEP26: Train 319(05), with 57 customers onboard, was delayed at Shell siding/MP153.5, 35 miles east of Sedalia, MO/MP188.9, on the UP Sedalia subdivision meeting UP freight UP/7015. Train 319(05) operating through Shell siding in order to have a route around the freight. Once clear of the area, train 319(05) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(05)	45"	

Train 14(05) North of San Luis Obispo, CA - Passenger Train Interference

05SEP26: Train 14(05), carrying 222 customers onboard, was delayed north of San Luis Obispo, CA, while holding at Serrano (MP 239.0) on the Union Pacific Coast Subdivision to meet Amtrak Train 11(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(05)	39"	
11(04)	05"	

Train 355(05) East of Ann Arbor, MI - Passenger Train Interference

05SEP26: Train 355(05), with 80 customers onboard, was delayed at control point 28/MP28.2, 9 miles east of Ann Arbor, MI/MP37.5, on the Michigan Department of Transportation Michigan Line meeting Amtrak train 352(05). Once the route was clear, train 355(05) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(05)	50"	

Train 59(05) Chicago, IL - Engine Failure

05SEP26: Train 59(05), with engine 193 and 207 cars, 261 customers to board, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late release of the equipment by Chicago Mechanical. Delays to the servicing and inspection of engine 193 caused the late release of train 59(05). Once the equipment was release, train 59(05) shoved into the depot, boarded customers, and departed Chicago.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(05)	32"	

Train 50(05) Chicago, IL - Late Shopping of Engine

05SEP26: Train 50(05), with engines 104 and IDTX4601, 5 cars, and 129 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late shopping of engine IDTX4601. An issue with the 480v feedthrough was discovered leading to engine IDTX 4601 being shopped and cut out of the consist of train 50(05). Once the set out was complete, train 50(05) departed Chicago.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(05)	1'25"	

Train 22(05) West of Mineola, TX - Freight Train Interference

05SEP26: Train 22(05), with 87 customers onboard, was delayed between mile post 171.0 and 169.0, beginning 35 miles west of Mineola, TX/MP136.1, on the UP Mineola subdivision following UP freight UP/2546. The freight crew stopped to inspect their equipment before train 22(05) arrived at the scene. Once the route was clear, train 22(05) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(05)	45"	

Train 786(05) North of Goleta, CA - Hold for Emergency Medical in Area

05SEP26: Train 786(05), carrying 83 customers onboard, was delayed north of Goleta, CA, at MP 334.5 on the Union Pacific Santa Barbara Subdivision due to emergency personnel responding to an injured individual near the tracks. Train movements through the area were temporarily halted while first responders conducted rescue operations, including the use of a helicopter to remove the individual from the scene. Once emergency response activities were completed and the affected territory was released, train traffic resumed through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(05)	1'07"	

Train 21(04) Fort Worth, TX - Servicing

05SEP26: Train 21(04), E/62-E/69-8 Cars, was delayed at Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision, while completing routine locomotive fueling.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(04)	38"	

Train 782(05) South of Carpinteria, CA - Passenger Train Interference

05SEP26: Train 782 (26-ECI-00734) 128 cars-E/JPBX921, was delayed south of Carpinteria, CA, while holding at Seacliff (MP 386.2) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Train 769(05).

Train	Delay	Comment
782(05)	40"	

Train 732(05) Oakland, CA - Third Party Contractor Engine Failure

05SEP26: Train 732(05), CC/C8307-3 cars-E/JPBX921, was delayed departing Oakland, CA due to locomotive issues with E/JPBX921. The crew held while mechanical worked to resolve issues and ready locomotive to add to consist. Unable to make timely locomotive swap, 732(05) was canceled with customers accommodated on next services. E/C2013 was then switched into the consist and equipment operated deadhead from Oakland Maintenance Facility to Sacramento to be in place for next day service.

Train	Delay	Comment
732(05)	Canceled	

Train 318(05) East of Lee's Summit, MO - Freight Train Interference

05SEP26: Train 318(05) was delayed between Lee's Summit, MO/MP259.9 and Hermann, MO/MP81.1, beginning 10 miles east of Lee's Summit, MO., on the UP Sedalia subdivision meeting multiple UP freights. UP freights were met at Pleasant Hill, Strasburg, Smithton, and River Junction. Train 318(05) followed UP freight UP/8234 between Jefferson City, MO/MP125.5 and Hermann, MO/MP81.1. Once clear of the congestion, train 318(05) continued east.

Train	Delay	Comment
318(05)	17"	Smithton, UP/5519
318(05)	22"	Strasburg
318(05)	12"	Pleasant Hill, UP/6932
318(05)	31"	River Junction
318(05)	48"	Follow UP/8234 JEF-HEM

Train 710(05) Merced, CA - Third Party Contractor Engine Failure

05SEP26: Train 710(05), CC/C8303-7 cars-E/C2106, was delayed departing Merced, CA on the BNSF Stockton Subdivision due to a hot journal alarm on E/C2106. The crew stopped to inspect and contacted mechanical. Once mechanical verified temperatures they approved the equipment to continue to Bakersfield, CA and would inspect the equipment upon return to the Oakland Maintenance Facility off Train 719(05). After a brake test was performed, Train 710(05) continued west.

Train	Delay	Comment
710(05)	34"	
719(05)	38"	late turn from 710(05)

Train 6(05) East of Colfax, CA - Freight Train Interference

05SEP26: Train 6(05), carrying 211 customers onboard, was delayed east of Colfax, CA, near Switch 9 (MP 169.3) on the Union Pacific Roseville Subdivision due to freight traffic interference. The train was required to follow UP 6678 through the area.

Train	Delay	Comment
6(05)	33"	

Train 51(04) North of Dyer, IN - Freight Train Interference

05SEP26: Train 51(04) held 3.6 miles north of Dyer, IN (MP187.9), on the UPRR Villa Grove Subdivision, at 159th St (MP19.4) in order to meet an unspecified Union Pacific freight train.

Train	Delay	Comment
51(04)	35"	

Train 504(05) Eugene, OR - Police Related

05SEP26: Train 504(05) was delayed departing Eugene, OR on the UPRR Brooklyn Subdivision due to a police hold on the tracks for a freight (UP6881) trespasser strike. The crew held while police responded to scene and cleared tracks. Once police released the scene, Train 504(05) departed Eugene.

Train	Delay	Comment
504(05)	36"	

Train 8/28(04) East of Essex, MT - Freight Train Interference

05SEP26: Train 8/28(04) experienced significant delay beginning 19.1 miles east of Essex, MT (MP1168.9) due to freight interference on the BNSF Hi Line Subdivision. At Summit (MP1149.8), the train was required to meet westbound BNSF 3893 and BNSF 3872. Operations were further impacted by BNSF 6526 being disabled with locomotive issues at Spotted Robe (MP1132.0), as well as multiple freight trains tied down in sidings that limited available meet and pass locations. Westbound BNSF 3893 also incurred a prolonged delay while clearing Summit after stalling. Following the meet, Train 8/28(04) was required to follow BNSF 8003 until overtaking the freight at Bison (MP1142.7).

Train	Delay	Comment
8/28(04)	1'53"	

Train 19(04) South of Anniston, AL - Freight Train Interference

05SEP26: Train 19(04) held 46.9 miles south of Anniston, AL (MP735.0), on the NSRR East End Subdivision, at Leeds (MP781.9) in order to meet NS 154 and NS 28A.

Train	Delay	Comment
19(04)	31"	

Train 390(05) North of Champaign-Urbana, IL - Passenger Train Interference

05SEP26: Train 390(05) held 3.7 miles north of Champaign-Urbana, IL (MP127.9), on the CNRR Champaign Subdivision, at Leverett Jct (MP124.2) meeting Train 391(05).

Train	Delay	Comment
390(05)	46"	

Train 505(05) Seattle, WA - Engine Failure

05SEP26: Train 505(05), CC/C8309-7 cars- E/C2013 with 157 customers, was delayed departing Seattle, WA on the BNSF Seattle Subdivision due to hot journal alarm on E/WS1406. The crew held while mechanical responded and began troubleshooting. Due to mechanical being unable to resolve the issue, equipment from inbound Train 500(05), E/WS1405-3 cars-CC/90222, was turned at the station for Train 505(05). The equipment swapped was unable to accommodate all 157 customers causing oversold conditions. Customer service was able to reaccommodate 15 coach customers with 2 business class downgraded customers on Train 11(05) from Seattle, WA to Portland, OR. Once Train 500(05) arrived into Seattle at 10:06A, the on board customers detrained. Once the customers from 505(05) were boarded and the crew performed a brake test, Train 505(04) was able to depart.

Due to the change of equipment, the equipment turn for Train 505(05), Train 518(05), also had oversold conditions from Portland, OR to Seattle, WA. One supplemental bus was secured to operate express from Portland to Seattle to accommodate the 26 affected customers.

WBS#: B.TR.100150.7149

Train	Delay	Comment
505(05)	1'43"	
518(05)	47"	late turn from 505(05)

Train 702(05) Sacramento, CA - Third Party Contractor Engine Failure

05SEP26: Train 702(05), CC/C8309-7 cars- E/C2013 with 97 customers, was delayed departing Sacramento, CA on the UPRR Martinez Subdivision due to restroom issues in multiple cars and door issues. The crew contacted mechanical to troubleshoot. Mechanical was unable to resolve issues. Train 702(05) was cancelled with customers reaccommodated on regular local buses 3710 and 3810 with an additional bus on standby for any customer not able to be accommodated on regular scheduled buses from Sacramento, CA to Stockton, CA. In Stockton, customers traveling between Stockton and Bakersfield, CA were reaccommodated on other Gold Runner Service to their final destinations. As a result of the cancellation of Train 702(05), Train 717(05) was cancelled in its entirety from Bakersfield, CA to Oakland, CA with customers reaccommodated on the next available service. The equipment from Train 702(05) was deadheaded from Sacramento to the Oakland Maintenance facility for repairs.

WBS#: B.TR.100150.7147

Train	Delay	Comment
702(05)	Cancelled	
717(05)	Cancelled	

Train 350(05) Niles, MI - Passenger Train Interference

05SEP26: Train 350(05) was delayed at Niles, MI (MP191.9), where it was originally scheduled to meet Train 351(05) on the Amtrak Michigan Line. To avoid the additional delay that would have resulted from completing the meet at Niles, Train 350(05) advanced to Gord (MP121.4), where the meet with Train 351(05) was subsequently completed.

Train	Delay	Comment
350(05)	33"	NLS
350(05)	36"	Gord

Train 5(04) West of Denver, CO - Engine Failure

05SEP26: Train 5(04), 26-F/1173-E/60679 Cars and 232 customers onboard, was delayed 3 miles west of Denver, CO (MP0.0), on the BNSF Front Range Subdivision. The delay occurred at North Yard (MP3.0) while freight locomotive UP5727 was added to the head end after both train locomotives experienced dynamic braking issues en route to Denver. Once UP5727 was added, Train 5(04) proceeded west.

Train	Delay	Comment
5(04)	1'24"	

Train 381(05) Chicago, IL - PTC Issues

05SEP26: Train 381(05), E/ID4611-4 Cars and 93 customers onboard, was delayed departing Chicago, IL account PTC (I-ETMS) issues. The crew contacted the PTC Help Desk and was instructed to cycle the PTC breaker. A check of the PTC Client verified the train information was in the system for train 381(05). A review of the PTC Usage logs did not show any attempted connection to initialize the train. The crew recycled the braker and had no luck correcting the issue. The crew pulled out from under the overbuild to attempt better communications. Chicago Mechanical responded to assist the crew. At 8:30AM-CT, Train 381(05) was initialized and on the move west.

Train	Delay	Comment
381(05)	45"	

Train 8/28(03) St. Cloud, MN - Freight Train Interference

05SEP26: Train 8/28(03) was delayed at St. Cloud, MN (MP73.8) on the BNSF Staples Subdivision due to BNSF 4076 being involved in an earlier occupied vehicle strike at MP68.1. Both main tracks were taken out of service while the incident was addressed. Once a route was established and track access was restored, Train 8/28(03) was released to proceed east.

Train	Delay	Comment
8/28(03)	31"	

Train 2/422(04) East of Yuma, AZ - Police Related

05SEP26: Train 2/422(04) was delayed at MP 735.9, 3 miles east of Yuma, AZ, on the UPRR Gila Subdivision due to a police hold on the tracks for a fire ahead. The crew held while the local fire department responded and extinguished the fire. Once tracks were cleared, Train 2/422(04) proceeded east.

Train	Delay	Comment
2/422(04)	34"	

Train 8/28(04) East of Sandpoint, ID - Debris

05SEP26: Train 8/28(04), E/355-E/11-11 cars, was delayed at MP 1400.7, 4 miles east of Sandpoint, ID, on the BNSF Kootenai River Subdivision due to striking debris causing an air hose separation. Once the air hoses were resecured, the crew performed a brake test and proceeded east.

Train	Delay	Comment
8/28(04)	10"	

Train 51(04) West of Indianapolis, IN - Trespasser Incident

05SEP26: At 6:55AM-ET, ~~26-FOI-00731~~ ~~100000008776~~ ~~51(04)~~ ~~E/1045~~ UNCLASSIFIED struck trespasser on the tracks 2.6 miles west of Indianapolis, IN Station (MP0.0) on the CSX Indianapolis Terminal Subdivision at MP2.6 in Marion County. The incident did not occur at a crossing. There were no reported injuries to the crew or 139 customers onboard, and there was no damage to the equipment. Head end power remained on throughout the incident. Weather conditions were clear with a temperature of 78.8 degrees. Local police and EMS responded to the scene, and the Indianapolis Road Foreman arrived at 8:00AM-ET. Police were unable to locate the individual believed to be struck by the train. The engineer requested relief, and the recrew engineer arrived at 9:45AM-ET. After local authorities released the scene and the recrew boarded, Train 51(04) resumed movement at 9:48AM-ET en route to Chicago Union Station.

WBS#: B.TR.100150.7145

National Response Center Number: 1472819

Train	Delay	Comment
51(04)	2'57"	

Train 300(05) North of Alton, IL - Trespasser Incident

05SEP26: At 5:26AM-CT, Train 300(05), E/ID4620 with five cars, struck a trespasser on a single main track 2.8 miles north of the Alton, IL station (MP255.1) on the UPRR Springfield Subdivision at MP252.3 in Madison County. The strike did not occur at a crossing and was determined to be fatal. No injuries were reported to the crew or the 147 customers onboard, and no damage was reported to the equipment. Head end power remained on for the duration of the incident. Weather conditions were reported as clear with a temperature of 78.8 degrees. The crew requested relief. Madison County Police and EMS responded quickly to the location, and the Coroner arrived at 6:45AM-CT. A recrew went on duty in St. Louis at 6:30AM-CT and was transported to the train by the Carbondale Road Foreman, arriving at 7:24AM-CT. During this time, Train 302(05) was held 0.6 miles north of the St. Louis, MO station (MP1.5) on the TRRA Merchants Subdivision at Gratiot (MP2.1) and was released at 7:14AM-CT to advance north. At 8:11AM-CT, Train 300(05) was released by officials to proceed to Chicago.

National Response Center Number: 1472820

Train	Delay	Comment
302(05)	57"	
300(05)	2'58"	

Train 3(04) West of La Plata, MO - Freight Train Interference

05SEP26: Train 3(04) was delayed starting 18.2 miles west of La Plata, MO (MP312.7), on the BNSF Marceline Subdivision, following a BNSF freight train from West Ethel (MP330.9) to West Marceline (MP347.3).

Train	Delay	Comment
3(04)	44"	

Train 3(04) East of Fort Madison, IA - Drawbridge Opening

05SEP26: Train 3(04) held 1.1 miles east of Fort Madison, IA (MP232.9), on the BNSF Chillicothe Subdivision, due to the Mississippi River Bridge (MP231.8) opening for marine traffic. Once the bridge was seated and locked, Train 3(04) proceeded west.

Train	Delay	Comment
3(04)	40"	

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

05SEP26: High tides along the Southern California coast caused track indication issues between San Clemente Pier (MP 204.8) and CP SONGS (MP 209.5) on the Metrolink Orange Subdivision, requiring trains to operate at restricted speed and flag through the affected territory. Metrolink personnel conducted track inspections following each train movement through the area, resulting in significant congestion and delays to Pacific Surfliner service.

The incident resulted in the following service impacts and recovery actions:

- Train 581(05), carrying 244 customers onboard, was delayed at CP SONGS (MP 209.5) while awaiting authorization to proceed through the affected territory under restricted-speed conditions.
- Train 580(05), carrying 373 customers onboard, was delayed at San Clemente Pier Station (MP 204.9) before proceeding through the area under flag protection.
- Train 785(05), carrying 374 customers onboard, was delayed at CP SONGS while awaiting the passage of Train 580(05) before proceeding toward San Clemente Pier.
- Train 587(05), carrying 410 customers onboard, was delayed at CP SONGS while awaiting track inspections and clearance through the affected territory.
- Train 782(05), carrying 411 customers onboard, was delayed at CP Serra (MP 199.7) pending clearance through the affected territory.
- Train 584(05), carrying 167 customers onboard, was delayed at CP Serra after initially holding near Trabuco (MP 195.5).
- Train 588(05), carrying 106 customers onboard, experienced delays approaching the affected territory.
- Train 591(05) experienced delays approaching and departing Oceanside, CA, due to congestion created by the restricted operations.
- Train 786(05) encountered downstream delays while operating south toward the affected territory.

To mitigate customer impacts, the following service adjustments were implemented:

- Train 584(05) was terminated at San Juan Capistrano, CA, with customers accommodated on Train 588(05).
- Train 786(05) was terminated at Irvine, CA, after customers detrained at Laguna Niguel/Mission Viejo Station and were accommodated on Train 790(05).
- Train 593(05) was canceled, with customers accommodated on Train 595(05).
- Train 595(05) operated late after turning from the delayed Train 782(05).
- Equipment from Trains 584(05) and 786(05) was returned to Los Angeles, CA.

WBS#: B.TR.100150.7150

Train	Delay	Comment
584(05)	Term SNC	
786(05)	Term IRV	
593(05)	Canceled	
785(05)	50"	
587(05)	2'19"	
584(05)	52"	
591(05)	24"	late turn of 580
591(05)	2'17"	
782(05)	3'35"	
588(05)	2'52"	
790(05)	2'11"	
595(05)	2'36"	late turn of 782

Train 305(05) South of Chicago, IL - Engine Failure

05SEP26: Train 305(05) ended at DTX4601, 9/18/2026 11:41 customers, stopped at mile post 3.1 south of Chicago Union Station, IL/MP0.0 on the CN Freeport subdivision due to loading problems. Chicago Mechanical responded and inspected. Train 305(05) shoved back to Chicago Union Station where train 305(05) was terminated. One bus was secured to operate express to Burlington-Normal, and the remaining customers boarded train 307(05), which made additional stops at Dwight and Carlinville.

Train 300(06) was cancelled in its entirety with four buses secured.

WBS#: B.TR.100150.7148

Train	Delay	Comment
305(05)	Terminated	
300(06)	Cancelled	

Wolverine Service - Pontiac, MI Wye OOS

04SEP26: Canadian National reported that the Pontiac, MI wye on the CNRR Holly Subdivision was removed from service due to wide gauge and was expected to remain out of service until Tuesday, September 7. As a result, Train 355(04) departed Pontiac on time but incurred delay en route to Detroit, MI while completing a shove move to Milwaukee Jct (MP4.1) to wye the equipment. After the wye move was completed, Train 355(04) continued toward Chicago operating at track speed.

05SEP26: Train 351(05), with 14 customers onboard, departed Pontiac, MI 2 hours and 31 minutes late due to the late wyeing of the engines at Milwaukee Jct prior to departure. The wye move was delayed by the late arrival of inbound Train 354(04), which arrived at 3:16AM-ET.

Due to the Pontiac, MI wye being out of service and Chicago unable to support a push-pull trainset, Train 350(05-06) was terminated at Detroit, MI, with two alternate buses secured for 05SEP and one alternate bus secured for 06SEP. Train 355(05-06) originated at Dearborn, MI, with two alternate buses secured each day between Pontiac, MI, and Dearborn, MI, to accommodate customers.

WBS#: B.TR.100150.7144

Train	Delay	Comment
355(04)	31"	
351(05)	2'31"	ITD PNT
355(05-06)	ORIG DER	
350(05-06)	TERM DET	
355(05)	56"	Air Issues @DER

Union Pacific Sedalia, Jefferson City, Springfield and Joliet Subdivision Kansas City, MO to St. Louis, MO to Joliet, IL - Heat Restrictions

31AUG26: Union Pacific placed Level 2 heat restrictions on the entire Sedalia and Jefferson City Sub division from Kansas City, MO and St. Louis, MO. Trains were limited to 40mph. Train 311(31), 316(31), 318(31), and Train 319(31) were delayed account of the restrictions.

01SEP26: Union Pacific also added Level 2 heat restrictions on the Joliet and Springfield Subdivision from St. Louis, MO and Joliet, IL. Trains were limited to 50mph through 04SEP.

05SEP26: Continued Union Pacific Level 2 heat restrictions on the Springfield, Sedalia and Jefferson City Subdivisions. The Joliet Subdivision was reduced to a Level 1 heat restriction.

WBS#: B.TR.100150.7132

316 (31)	31"		
319 (31)	32"		
318 (31)	14"		
311 (31)	12"		
301 (01)	12' 50"	JOL to STL	"UNCLASSIFIED" 9/18/2026
302 (01)	1' 04"	LCN to JOL	
311 (01)	51"	HEM to KCY	
305 (01)	1' 05"	JOL-LCN	
22 (31)	1' 02"	ALN-JOL	
307 (01)	20"	JOL-DWT	
21 (01)	1' 58"	JOL-ALN	
306 (01)	1' 04"		
301 (02)	1' 05"		
22 (01) / 422 (30)	1' 58"		
302 (02)	1' 02"		
21 (02)	1' 57"		
319 (02)	1' 53"		
307 (02)	24"		
305 (02)	1' 09"		
306 (02)	1' 01"		
311 (02)	44"		
316 (02)	36"		
318 (02)	2' 16"		
316 (01)	28"		
318 (01)	2' 41"		
319 (01)	2' 28"		
302 (03)	1' 10"		
301 (03)	1' 35"		
311 (03)	52"		
22 (02)	1' 52"		
319 (03)	2' 45"		
318 (03)	3' 11"		
305 (03)	1' 16"		
306 (03)	1' 08"		
307 (03)	26"		
316 (03)	44"		
21 (03)	1' 40"		
311 (04)	33"		
302 (04)	1' 25"		
301 (04)	1' 25"		
307 (04)	45"	Turn 302 (04)	
22 (03)	1' 46"		
305 (04)	20"		
306 (04)	44"		
318 (04)	2' 01"		
316 (04)	42"		
319 (04)	2' 23"		
21 (04)	1' 59"		
300 (05)	09"		
302 (05)	23"		
301 (05)	44"		
22 (04)	45"		
311 (05)	1' 16"		
316 (05)	27"	ITD KCY - Turn of 311 (05)	
316 (05)	23"	Heat Orders	
21 (05)	03"		
319 (05)	1' 37"		
318 (05)	2' 22"		
306 (05)	37"		

Maintenance of Way Highlights

Coast Starlight - Scheduled M/W Work 26-090

26-010273

90000076

UNCLASSIFIED

9/18/2026

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
14 (22)	23"	
11 (22)	32"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 00900008776 UNCLASSIFIED 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues
	West Amboy (MP 661.6)		32039	waiting for wheel set to be shipped and Amtrak personnel to assist with removal- Tentatively scheduled for 08SEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (4)	DEN	UP5727	Dynamic brakes on E/179+E/206		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 509(05) Passenger Removal at Tacoma, Washington– Fare Evader

05SEP26, Non-ticketed Passenger, traveling from Seattle, WA to Tacoma, WA was reportedly dodging buying a ticket he was asked several times to produce his ticket and given the opportunity to call to buy one. Local authorities called and removed him from the train at Tacoma, WA. Amtrak Police notified.

Delay: 509(05) 09"

Consist Deviations

26-FOI-00731

00000008776

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
240 (05)	ALB	due to equipment swap, will NO longer offer Biz Class	16 pax downgraded	16	43348
290 (06)	BTN	due to equipment swap, will NO longer offer Biz Class	16 pax downgraded	16	43348
670 (05)	HAR	No cab car or cafe car to provide wifi. Please notify pax.	N/A	0	615
562 (05)	LAX	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Paseengers notified	2	90225
580 (05)	LAX	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Paseengers notified	3	90225
562 (06)	LAX	no bikes or wifi	email sent for passenger notificationsno bike space no wifi	1	90225
580 (06)	LAX	no bikes or wifi	email sent for passenger notificationsno bike space no wifi	0	90225
58 (05)	NOL	third coach shopped. loco 507 added for axle count. Y-reduced with overages. reaccomodate impact pax. please manually block room A in the 5832 car for safe checked bag storage.	no impact	0	34113
661 (05)	NYP	No cab car or cafe car to provide wifi. Please notify pax.	N/A	0	615
671 (05)	NYP	No cab car or cafe car to provide wifi. Please notify pax.	N/A	0	615
291 (05)	NYP	due to equipment swap, will NO longer offer Biz Class	16 pax downgraded	16	43348

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
239 (06)	NYP	due to equipment swap, will NO longer offer Biz Class	2 pax downgraded	2	43348
518 (05)	PDX	JY AND Y REDUCED WITH OVERCAPACITIES.	1 bus sourced for 26 pax	26	AMFLEET SET
573 (05)	SAN	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Paseengers notified	1	90225
591 (05)	SAN	OPERATING WITH 90225 IN CONSIST WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO REACCOMMODATE ANY PASSENGERS IMPACTED BY THIS.	Passengers notified	2	90225
573 (06)	SAN	no bikes or wifi	email sent for passenger notificationsno bike space no wifi	0	90225
591 (06)	SAN	no bikes or wifi	email sent for passenger notificationsno bike space no wifi	2	90225
505 (05)	SEA	JY AND Y REDUCED WITH OVERCAPACITIES.	no impact pax moved to train 11(05)	0	AMFLEET SET

Reverse Consists

Train Number	Station	Reason
195 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
161 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
99 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
87 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00731	00000008776 "UNCLASSIFIED" 9/18/2026
150 (05)	PHL	Consist reversed Business class seat orientation may have changed At Front	
127 (05)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
164 (06)	NPN	Consist reversed Business class seat orientation may have changed At Front	
88 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front	
135 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front	
128 (06)	NFK	Consist reversed Business class seat orientation may have changed At Front	
168 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front	
194 (05)	WAS	Consist reversed Business class seat orientation may have changed At Front	
168 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear	