CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, November 04, 2026 Rules: 0-4



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00137-Request-Records-11-07-2026

Initial Terminal Performance By Division

Scheduled Departure Date: **11/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/03/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	43	86.1%	902	116	87.1%	10,376	1,468	85.9%
Central Division	86.0%	58	5	91.4%	173	9	94.8%	1,943	134	93.1%
East Division	82.0%	159	19	88.1%	460	51	88.9%	5,459	789	85.5%
West Division	86.0%	92	19	79.3%	269	56	79.2%	2,974	545	81.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Refresh Date & Time: **11/04/2026 05:50 AM**

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 11/3/26

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**76%**	**78,737**	**26,233**	**67%**	**282,419**	**74,462**	**74%**	**3,431,502**	**974,593**	**72%**
Northeast Corridor	***78%***	***34,362***	***8,941***	***74%***	***117,207***	***24,330***	***79%***	***1,472,217***	***348,971***	***76%***
Acela	80%	5,883	1,523	74%	16,189	3,372	79%	253,513	49,854	80%
Northeast Regional	78%	28,479	7,418	74%	101,018	20,958	79%	1,218,704	299,117	75%
Richmond / Newport News / Norfolk	75%	5,177	1,401	73%	25,532	6,428	75%	296,389	80,652	73%
Springfield Shuttles	89%	665	0	100%	2,176	57	97%	25,183	4,897	81%
Roanoke	75%	2,432	1,353	44%	8,958	2,450	73%	106,607	30,838	71%
On Spine Northeast Regional	80%	20,205	4,664	77%	64,352	12,023	81%	790,525	182,730	77%
State Supported	***80%***	***33,469***	***10,201***	***70%***	***129,562***	***34,727***	***73%***	***1,553,687***	***443,010***	***71%***
Borealis	80%	448	238	47%	1,958	238	88%	24,227	4,537	81%
Capitol Corridor	90%	3,663	1,049	71%	11,606	2,224	81%	140,289	26,988	81%
Carolinian	70%	1,133	869	23%	4,421	1,307	70%	45,039	14,954	67%
Cascades	75%	1,631	340	79%	8,339	2,436	71%	96,506	28,556	70%
Downeaster	82%	1,213	87	93%	4,083	1,057	74%	61,549	14,739	76%
Empire	78%	4,327	747	83%	17,258	3,360	81%	215,154	50,487	77%
Adirondack	72%	188	0	100%	980	4	100%	13,927	2,075	85%
Ethan Allen Express	70%	401	210	48%	1,582	879	44%	20,059	7,904	61%
Maple Leaf	70%	585	400	32%	2,357	811	66%	29,463	9,309	68%
New York - Albany	85%	2,183	2	100%	8,391	1,259	85%	104,004	18,943	82%
New York - Niagara Falls	75%	970	135	86%	3,948	407	90%	47,701	12,256	74%
Gold Runner	73%	1,703	776	54%	8,380	2,557	69%	88,929	33,269	63%
Heartland Flyer	70%	89	87	2%	471	458	3%	6,714	5,679	15%
Hiawatha	90%	1,285	82	94%	4,827	310	94%	63,197	6,070	90%
Illinois	78%	1,851	439	76%	8,128	863	89%	93,641	28,240	70%
Carl Sandburg / Illinois Zephyr	85%	170	51	70%	947	51	95%	14,472	3,562	75%
Illini / Saluki	85%	691	203	71%	3,075	207	93%	32,076	12,120	62%
Lincoln Service	70%	990	185	81%	4,106	605	85%	47,093	12,558	73%
Keystone	92%	5,907	1,353	77%	17,431	1,440	92%	230,362	23,126	90%
Lincoln / Missouri	70%	625	619	1%	2,492	1,613	35%	29,450	14,602	50%
Mardi Gras Service	80%	338	22	93%	913	109	88%	10,265	2,714	74%
Michigan	70%	1,560	524	66%	5,813	1,445	75%	71,896	18,310	75%
Blue Water	70%	297	121	59%	1,446	195	87%	18,573	5,026	73%
Pere Marquette	85%	191	0	100%	805	0	100%	10,104	623	94%
Wolverine	70%	1,072	403	62%	3,562	1,250	65%	43,219	12,661	71%
Missouri	80%	167	21	87%	720	267	63%	9,674	1,999	79%
Pacific Surfliner	85%	4,839	2,536	48%	21,864	13,117	40%	239,041	131,910	45%
Pennsylvanian	80%	824	324	61%	2,813	324	88%	32,016	9,574	70%
Piedmont	80%	540	58	89%	3,464	1,399	60%	42,870	13,446	69%
Vermonter	75%	1,326	30	98%	4,581	203	96%	52,868	13,810	74%
Long Distance	***58%***	***10,906***	***7,091***	***35%***	***35,650***	***15,405***	***57%***	***405,598***	***182,612***	***55%***
Auto Train	70%	732	484	34%	2,293	1,739	24%	23,251	17,178	26%
California Zephyr	70%	838	661	21%	2,615	1,053	60%	31,855	9,540	70%
Cardinal	70%	0	0	-	593	69	88%	7,389	3,222	56%
City Of New Orleans	75%	670	135	80%	2,139	198	91%	25,487	16,496	35%
Coast Starlight	70%	481	467	3%	2,923	1,715	41%	36,986	20,422	45%
Crescent	70%	824	153	81%	2,976	400	87%	33,034	5,200	84%
Empire Builder	70%	974	567	42%	2,719	758	72%	34,950	12,769	63%
Floridian	60%	1,748	1,748	0%	5,225	3,668	30%	48,216	27,868	42%
Lake Shore Ltd	73%	923	380	59%	2,971	446	85%	35,812	10,756	70%
Palmetto	70%	987	710	28%	2,475	848	66%	26,228	6,951	73%
Silver Meteor	70%	978	913	7%	3,059	1,785	42%	35,799	12,160	66%
Southwest Chief	60%	766	591	23%	2,184	1,738	20%	26,056	20,163	23%
Sunset Ltd	70%	268	206	23%	827	306	63%	9,713	4,563	53%
Texas Eagle	70%	717	76	89%	2,651	682	74%	30,822	15,324	50%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00187 00000000185 "UNCLASSIFIED" 11/10/2026~~

Train Index Dates Through November 03, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	15,717	304,617	516	203,643	3,394,199	600

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	358	78,427	46	9,937	950,143	105
INFRASTRUCTURE PLANNED	135	1,712	78,427	218	21,679	950,143	228
FLEET RELIABILITY	90	2,019	304,617	66	28,517	3,394,199	84
TRAIN OPERATIONS	424	11,628	304,617	382	143,510	3,394,199	423

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00137-Request-Records-11-07-2026

Initial Terminal Performance By Division

Scheduled Departure Date: **11/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/03/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	43	86.1%	902	116	87.1%	10,376	1,468	85.9%
Central Division	86.0%	58	5	91.4%	173	9	94.8%	1,943	134	93.1%
East Division	82.0%	159	19	88.1%	460	51	88.9%	5,459	789	85.5%
West Division	86.0%	92	19	79.3%	269	56	79.2%	2,974	545	81.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

27-FOI-001

Scheduled Departure Date: **11/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/03/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	43	86.1%	902	116	87.1%	10,376	1,468	85.9%
Central Division	86.0%	58	5	91.4%	173	9	94.8%	1,943	134	93.1%
CDL	95.0%	2	0	100.0%	6	0	100.0%	47	3	93.6%
CHI	86.0%	28	3	89.3%	81	5	93.8%	911	73	92.0%
CHM	-	-	-	-	-	-	-	20	3	85.0%
DAL	-	-	-	-	-	-	-	2	0	100.0%
DET	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	3	0	100.0%	31	2	93.5%
GRR	95.5%	1	0	100.0%	3	0	100.0%	34	0	100.0%
IND	-	-	-	-	-	-	-	4	0	100.0%
KCY	92.0%	2	0	100.0%	6	0	100.0%	69	1	98.6%
MKE	92.0%	6	0	100.0%	17	1	94.1%	198	13	93.4%
MOE	97.5%	2	0	100.0%	6	0	100.0%	61	0	100.0%
MSP	96.5%	1	0	100.0%	3	0	100.0%	34	0	100.0%
NOL	94.5%	4	0	100.0%	13	0	100.0%	139	6	95.7%
OKC	97.0%	1	0	100.0%	3	0	100.0%	33	2	93.9%
PNT	88.0%	3	0	100.0%	9	1	88.9%	89	13	85.4%
PTH	93.0%	1	1	0.0%	3	1	66.7%	34	2	94.1%
QCY	91.0%	1	0	100.0%	5	0	100.0%	67	4	94.0%
SAS	90.5%	1	1	0.0%	3	1	66.7%	33	7	78.8%
STL	89.0%	4	0	100.0%	12	0	100.0%	135	3	97.8%
TAY	-	-	-	-	-	-	-	1	1	0.0%
East Division	82.0%	159	19	88.1%	460	51	88.9%	5,459	789	85.5%
ALB	88.5%	8	0	100.0%	24	2	91.7%	269	22	91.8%
ALX	-	-	-	-	-	-	-	27	14	48.1%
ATL	-	-	-	-	-	-	-	14	4	71.4%
BON	87.5%	5	0	100.0%	15	1	93.3%	170	13	92.4%
BOS	85.5%	12	2	83.3%	31	3	90.3%	424	25	94.1%
BRK	92.5%	5	0	100.0%	15	1	93.3%	170	14	91.8%
BTN	82.0%	1	0	100.0%	3	0	100.0%	34	5	85.3%
CLT	91.5%	5	0	100.0%	15	0	100.0%	164	20	87.8%
GFD	88.0%	2	0	100.0%	6	0	100.0%	68	6	91.2%
GRO	-	2	1	50.0%	4	1	75.0%	15	1	93.3%
HAR	79.5%	13	1	92.3%	34	4	88.2%	389	43	88.9%
HFD	-	-	-	-	-	-	-	44	9	79.5%
JAX	-	-	-	-	-	-	-	18	2	88.9%
LOR	84.0%	1	0	100.0%	3	2	33.3%	32	14	56.3%
MET	-	-	-	-	-	-	-	1	1	0.0%
MIA	89.5%	2	0	100.0%	6	2	66.7%	67	10	85.1%
MTR	79.0%	1	0	100.0%	3	0	100.0%	34	9	73.5%
NFK	84.5%	2	0	100.0%	6	0	100.0%	57	10	82.5%
NFL	93.5%	2	0	100.0%	6	0	100.0%	68	5	92.6%
NFS	-	-	-	-	-	-	-	3	3	0.0%
NHV	78.0%	6	0	100.0%	18	2	88.9%	175	35	80.0%
NPN	93.0%	2	0	100.0%	6	1	83.3%	46	5	89.1%

Information Management

27-FOI-0013 [illegible] 11/17/2026

Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/03/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 11/03/2026			ITP November 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	309	43	86.1%	902	116	87.1%	10,376	1,468	85.9%
East Division	82.0%	159	19	88.1%	460	51	88.9%	5,459	789	85.5%
NYP	75.5%	39	4	89.7%	119	10	91.6%	1,417	228	83.9%
PGH	93.0%	1	0	100.0%	3	0	100.0%	42	10	76.2%
PHL	48.0%	11	7	36.4%	28	15	46.4%	276	131	52.5%
RGH	95.0%	2	0	100.0%	8	1	87.5%	134	22	83.6%
RNK	83.5%	2	0	100.0%	6	1	83.3%	57	7	87.7%
SAB	98.0%	1	0	100.0%	3	0	100.0%	34	0	100.0%
SAV	96.0%	1	0	100.0%	3	0	100.0%	23	0	100.0%
SFA	88.0%	1	1	0.0%	3	2	33.3%	32	7	78.1%
SPG	92.5%	7	0	100.0%	21	0	100.0%	189	10	94.7%
TWO	73.0%	1	0	100.0%	3	0	100.0%	31	8	74.2%
WAS	84.0%	24	3	87.5%	68	3	95.6%	935	96	89.7%
West Division	86.0%	92	19	79.3%	269	56	79.2%	2,974	545	81.7%
ARN	92.0%	1	0	100.0%	3	0	100.0%	34	3	91.2%
BFD	79.0%	7	1	85.7%	21	6	71.4%	230	58	74.8%
EMY	72.0%	1	0	100.0%	3	1	66.7%	38	16	57.9%
EUG	86.5%	2	0	100.0%	6	0	100.0%	65	3	95.4%
FNO	-	-	-	-	-	-	-	5	4	20.0%
GAC	-	-	-	-	-	-	-	3	2	33.3%
GTA	90.0%	6	0	100.0%	18	6	66.7%	149	61	59.1%
IRV	-	-	-	-	-	-	-	1	0	100.0%
LAX	89.5%	10	3	70.0%	31	8	74.2%	331	42	87.3%
OKJ	74.5%	13	5	61.5%	35	10	71.4%	398	125	68.6%
PDX	86.0%	5	0	100.0%	15	2	86.7%	170	15	91.2%
SAC	88.5%	16	3	81.3%	44	5	88.6%	500	49	90.2%
SAN	90.5%	13	4	69.2%	39	13	66.7%	398	88	77.9%
SEA	85.0%	8	1	87.5%	24	2	91.7%	271	31	88.6%
SJC	89.0%	7	2	71.4%	21	3	85.7%	237	38	84.0%
SLO	90.0%	-	-	-	-	-	-	42	8	81.0%
SPK	90.0%	1	0	100.0%	3	0	100.0%	33	0	100.0%
VAC	97.0%	2	0	100.0%	6	0	100.0%	64	1	98.4%
VNC	-	-	-	-	-	-	-	5	1	80.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		1	1	0.0%	14	2	85.7%	2	0	100.0%	15	5	66.7%
3	508	3	0	100.0%	32	6	81.3%	3	3	0.0%	30	22	26.7%
4	283	3	2	33.3%	31	5	83.9%	3	3	0.0%	30	26	13.3%
5	260	3	0	100.0%	33	2	93.9%	3	1	66.7%	33	9	72.7%
6	47	3	1	66.7%	33	14	57.6%	3	2	33.3%	33	11	66.7%
7		3	1	66.7%	33	3	90.9%	3	0	100.0%	33	2	93.9%
8	221	3	0	100.0%	33	7	78.8%	3	1	66.7%	33	17	48.5%
11	Cncld	3	1	66.7%	34	5	85.3%	2	2	0.0%	33	22	33.3%
14	67	3	1	66.7%	34	10	70.6%	3	2	33.3%	34	21	38.2%
19		3	0	100.0%	34	6	82.4%	3	1	66.7%	33	7	78.8%
20		3	0	100.0%	34	3	91.2%	3	0	100.0%	34	4	88.2%
21		3	0	100.0%	34	2	94.1%	3	0	100.0%	33	13	60.6%
22		3	1	66.7%	34	8	76.5%	3	1	66.7%	34	19	44.1%
23		3	0	100.0%	31	0	100.0%	3	0	100.0%	31	6	80.6%
24		3	0	100.0%	30	0	100.0%	3	0	100.0%	30	6	80.0%
25		3	0	100.0%	30	0	100.0%	3	0	100.0%	30	7	76.7%
26		3	0	100.0%	31	0	100.0%	3	1	66.7%	31	9	71.0%
27		3	2	33.3%	33	2	93.9%	3	0	100.0%	33	6	81.8%
28		3	0	100.0%	33	4	87.9%	3	0	100.0%	33	6	81.8%
40	44	3	1	66.7%	34	11	67.6%	3	3	0.0%	34	17	50.0%
41	118	3	2	33.3%	34	5	85.3%	3	3	0.0%	34	18	47.1%
42	22	3	0	100.0%	34	3	91.2%	3	1	66.7%	34	12	64.7%
43		3	0	100.0%	34	8	76.5%	3	0	100.0%	33	12	63.6%
48	22	3	0	100.0%	34	4	88.2%	3	1	66.7%	34	13	61.8%
49		3	0	100.0%	34	5	85.3%	3	0	100.0%	34	6	82.4%
52		3	2	33.3%	32	7	78.1%	3	1	66.7%	32	17	46.9%
53	387	3	2	33.3%	32	14	56.3%	3	3	0.0%	32	28	12.5%
55		2	0	100.0%	24	0	100.0%	2	0	100.0%	24	5	79.2%
56		2	0	100.0%	24	3	87.5%	2	1	50.0%	24	5	79.2%
58		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	26	23.5%
59		3	0	100.0%	34	2	94.1%	3	0	100.0%	34	22	35.3%
63	32	3	0	100.0%	34	12	64.7%	3	3	0.0%	34	31	8.8%
64	24	3	0	100.0%	34	11	67.6%	3	2	33.3%	34	18	47.1%
66	37	3	1	66.7%	33	5	84.8%	3	1	66.7%	33	6	81.8%
67		3	1	66.7%	23	5	78.3%	2	0	100.0%	23	5	78.3%
68		3	0	100.0%	34	9	73.5%	3	0	100.0%	34	7	79.4%
69		3	0	100.0%	34	10	70.6%	3	0	100.0%	34	2	94.1%
71	18	3	0	100.0%	34	2	94.1%	3	2	33.3%	34	8	76.5%
72		3	0	100.0%	34	5	85.3%	3	1	66.7%	34	4	88.2%
73		3	0	100.0%	29	4	86.2%	3	1	66.7%	29	14	51.7%
74		3	0	100.0%	29	6	79.3%	3	1	66.7%	29	14	51.7%
75		3	1	66.7%	34	3	91.2%	3	1	66.7%	32	8	75.0%

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		3	0	100.0%	33	5	84.8%	3	1	66.7%	32	13	59.4%
77		3	1	66.7%	34	5	85.3%	3	1	66.7%	34	13	61.8%
78		3	0	100.0%	34	4	88.2%	3	1	66.7%	35	8	77.1%
79	30	3	0	100.0%	34	6	82.4%	3	2	33.3%	34	14	58.8%
80	46	3	0	100.0%	34	0	100.0%	3	1	66.7%	34	9	73.5%
89	60	3	0	100.0%	23	1	95.7%	3	3	0.0%	23	13	43.5%
90	190	3	0	100.0%	23	0	100.0%	3	2	33.3%	23	9	60.9%
94		3	0	100.0%	23	4	82.6%	3	1	66.7%	23	4	82.6%
97	39	3	2	33.3%	34	12	64.7%	3	3	0.0%	34	8	76.5%
98	427	3	1	66.7%	34	4	88.2%	3	1	66.7%	34	13	61.8%
230		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	1	97.1%
232		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	2	94.1%
233		3	0	100.0%	34	12	64.7%	3	1	66.7%	34	13	61.8%
234		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	1	97.1%
235		3	1	66.7%	34	5	85.3%	3	2	33.3%	34	11	67.6%
236		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	6	82.4%
237		3	1	66.7%	34	5	85.3%	3	0	100.0%	34	10	70.6%
238		3	2	33.3%	34	6	82.4%	3	1	66.7%	34	4	88.2%
239		3	0	100.0%	33	5	84.8%	3	1	66.7%	33	3	90.9%
240		3	0	100.0%	34	4	88.2%	2	0	100.0%	33	2	93.9%
241		3	0	100.0%	34	6	82.4%	3	0	100.0%	34	8	76.5%
243		3	0	100.0%	34	5	85.3%	3	0	100.0%	34	1	97.1%
244		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	10	70.6%
245		3	0	100.0%	34	5	85.3%	3	0	100.0%	34	5	85.3%
280		3	0	100.0%	34	3	91.2%	3	0	100.0%	34	12	64.7%
281		3	0	100.0%	34	5	85.3%	3	1	66.7%	34	4	88.2%
283		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	4	88.2%
284		3	0	100.0%	34	2	94.1%	3	0	100.0%	34	3	91.2%
290	18	3	0	100.0%	34	5	85.3%	3	3	0.0%	33	15	54.5%
291		3	0	100.0%	34	17	50.0%	3	1	66.7%	34	8	76.5%
300		3	0	100.0%	33	1	97.0%	3	0	100.0%	33	7	78.8%
301		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	4	88.2%
302		3	0	100.0%	34	1	97.1%	3	1	66.7%	34	9	73.5%
305	71	3	0	100.0%	34	1	97.1%	3	1	66.7%	34	13	61.8%
306		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	10	70.6%
307		3	0	100.0%	34	1	97.1%	3	1	66.7%	34	11	67.6%
311		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	4	88.2%
316		3	0	100.0%	34	0	100.0%	3	2	33.3%	34	11	67.6%
318	68	3	0	100.0%	34	1	97.1%	3	3	0.0%	34	15	55.9%
319	38	3	0	100.0%	34	0	100.0%	3	2	33.3%	33	25	24.2%
329		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	1	95.8%
330		2	0	100.0%	29	0	100.0%	2	0	100.0%	28	1	96.4%

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		3	0	100.0%	34	2	94.1%	3	0	100.0%	32	1	96.9%
332		3	0	100.0%	34	3	91.2%	3	1	66.7%	34	2	94.1%
334		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	1	97.1%
335		3	0	100.0%	34	6	82.4%	3	0	100.0%	34	3	91.2%
336	27	3	0	100.0%	33	0	100.0%	3	1	66.7%	33	2	93.9%
337		3	0	100.0%	33	1	97.0%	3	0	100.0%	33	1	97.0%
338		3	1	66.7%	34	5	85.3%	3	0	100.0%	34	9	73.5%
339		3	0	100.0%	34	8	76.5%	3	0	100.0%	33	6	81.8%
341		3	0	100.0%	33	5	84.8%	3	0	100.0%	33	2	93.9%
342		3	0	100.0%	34	4	88.2%	3	0	100.0%	33	3	90.9%
350		3	0	100.0%	31	2	93.5%	3	1	66.7%	29	13	55.2%
351		3	0	100.0%	29	4	86.2%	3	1	66.7%	27	6	77.8%
352	40	3	1	66.7%	30	5	83.3%	3	1	66.7%	29	11	62.1%
353	48	3	0	100.0%	31	4	87.1%	3	1	66.7%	30	5	83.3%
354		3	0	100.0%	31	6	80.6%	3	0	100.0%	30	11	63.3%
355		3	1	66.7%	30	6	80.0%	3	1	66.7%	29	9	69.0%
364		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	8	76.5%
365	19	3	1	66.7%	34	2	94.1%	3	1	66.7%	34	12	64.7%
370		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	4	88.2%
371		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	0	100.0%
381		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	7	79.4%
382		3	0	100.0%	34	2	94.1%	3	0	100.0%	34	7	79.4%
383	69	3	0	100.0%	34	0	100.0%	2	1	50.0%	33	13	60.6%
390		3	0	100.0%	33	5	84.8%	3	0	100.0%	33	9	72.7%
391		3	0	100.0%	34	2	94.1%	3	0	100.0%	34	6	82.4%
392	84	3	0	100.0%	34	1	97.1%	3	1	66.7%	34	24	29.4%
393		3	0	100.0%	33	4	87.9%	3	0	100.0%	33	18	45.5%
417		2	0	100.0%	24	5	79.2%	2	0	100.0%	23	6	73.9%
425		2	0	100.0%	24	0	100.0%	2	0	100.0%	24	3	87.5%
448	113	3	1	66.7%	31	11	64.5%	3	1	66.7%	31	10	67.7%
449	235	3	0	100.0%	31	1	96.8%	3	2	33.3%	31	6	80.6%
470		2	0	100.0%	24	3	87.5%	2	0	100.0%	24	8	66.7%
471		2	0	100.0%	24	7	70.8%	2	0	100.0%	24	7	70.8%
473		2	0	100.0%	24	2	91.7%	2	0	100.0%	24	0	100.0%
474		2	0	100.0%	24	7	70.8%	2	0	100.0%	23	8	65.2%
475		2	0	100.0%	24	0	100.0%	2	0	100.0%	24	2	91.7%
478		2	0	100.0%	24	2	91.7%	2	0	100.0%	24	1	95.8%
479		2	0	100.0%	24	3	87.5%	2	0	100.0%	23	8	65.2%
486		2	0	100.0%	24	3	87.5%	2	0	100.0%	23	3	87.0%
490		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
494		2	0	100.0%	25	3	88.0%	2	0	100.0%	24	5	79.2%
495		2	0	100.0%	24	0	100.0%	2	0	100.0%	24	1	95.8%

Amtrak On Time Performance

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
500	23	3	0	100.0%	34	2	94.1%	3	2	33.3%	34	7	79.4%
502		3	0	100.0%	34	1	97.1%	3	1	66.7%	34	7	79.4%
503		3	0	100.0%	34	7	79.4%	3	0	100.0%	34	14	58.8%
504		3	0	100.0%	32	1	96.9%	3	1	66.7%	32	14	56.3%
505	22	3	0	100.0%	34	1	97.1%	3	2	33.3%	34	8	76.5%
506		3	1	66.7%	34	3	91.2%	3	1	66.7%	33	7	78.8%
507		3	1	66.7%	34	4	88.2%	3	2	33.3%	32	13	59.4%
508		3	0	100.0%	34	3	91.2%	3	0	100.0%	34	12	64.7%
509	89	3	0	100.0%	34	1	97.1%	3	3	0.0%	34	17	50.0%
511		3	0	100.0%	34	1	97.1%	3	0	100.0%	34	4	88.2%
516		3	0	100.0%	32	4	87.5%	3	0	100.0%	31	16	48.4%
517		3	0	100.0%	34	2	94.1%	3	1	66.7%	34	14	58.8%
518	170	3	1	66.7%	34	4	88.2%	3	2	33.3%	33	16	51.5%
519		3	0	100.0%	32	0	100.0%	3	0	100.0%	32	5	84.4%
520		2	1	50.0%	24	1	95.8%	2	0	100.0%	24	0	100.0%
521	30	2	0	100.0%	24	1	95.8%	2	1	50.0%	22	5	77.3%
522	61	2	1	50.0%	24	8	66.7%	2	1	50.0%	24	4	83.3%
523	20	2	0	100.0%	24	4	83.3%	2	1	50.0%	23	7	69.6%
524	22	2	0	100.0%	24	3	87.5%	2	1	50.0%	23	5	78.3%
525		2	0	100.0%	24	3	87.5%	2	0	100.0%	22	2	90.9%
526		2	1	50.0%	24	8	66.7%	2	0	100.0%	22	2	90.9%
527	71	2	0	100.0%	24	1	95.8%	2	1	50.0%	24	7	70.8%
528		2	0	100.0%	24	3	87.5%	2	0	100.0%	24	8	66.7%
529		2	0	100.0%	24	2	91.7%	2	0	100.0%	24	10	58.3%
530	46	2	1	50.0%	24	5	79.2%	2	1	50.0%	24	6	75.0%
531		2	0	100.0%	24	1	95.8%	2	0	100.0%	23	2	91.3%
532		2	0	100.0%	24	9	62.5%	2	0	100.0%	23	1	95.7%
534		2	0	100.0%	24	4	83.3%	2	0	100.0%	24	0	100.0%
535		2	0	100.0%	24	0	100.0%	2	0	100.0%	23	2	91.3%
536		2	0	100.0%	24	9	62.5%	2	0	100.0%	24	1	95.8%
537		2	0	100.0%	23	1	95.7%	2	0	100.0%	22	1	95.5%
538		2	0	100.0%	24	2	91.7%	2	1	50.0%	24	2	91.7%
539		2	0	100.0%	24	5	79.2%	2	0	100.0%	24	8	66.7%
540		2	0	100.0%	23	3	87.0%	2	1	50.0%	22	1	95.5%
541		2	0	100.0%	24	3	87.5%	2	0	100.0%	24	4	83.3%
542		2	0	100.0%	24	4	83.3%	2	0	100.0%	23	2	91.3%
543	54	2	1	50.0%	24	5	79.2%	2	2	0.0%	24	12	50.0%
544		2	0	100.0%	24	6	75.0%	2	0	100.0%	24	6	75.0%
545		2	0	100.0%	23	0	100.0%	2	0	100.0%	22	0	100.0%
547		2	0	100.0%	24	2	91.7%	2	1	50.0%	24	6	75.0%
548		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	1	95.8%
549	31	2	2	0.0%	24	5	79.2%	2	2	0.0%	23	5	78.3%

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
550		2	2	0.0%	24	5	79.2%	2	1	50.0%	24	5	79.2%
551		2	0	100.0%	24	2	91.7%	2	0	100.0%	24	4	83.3%
562	87	3	1	66.7%	32	3	90.6%	3	3	0.0%	32	19	40.6%
564	51	3	0	100.0%	32	0	100.0%	3	3	0.0%	32	20	37.5%
566	91	3	0	100.0%	32	1	96.9%	2	2	0.0%	29	16	44.8%
567	112	3	0	100.0%	31	4	87.1%	3	2	33.3%	30	9	70.0%
572	Cncld	3	1	66.7%	29	8	72.4%	2	2	0.0%	26	18	30.8%
573	89	3	1	66.7%	32	4	87.5%	3	3	0.0%	31	15	51.6%
579	Cncld	3	2	33.3%	29	4	86.2%	1	1	0.0%	26	16	38.5%
580	18	3	1	66.7%	32	3	90.6%	3	3	0.0%	31	15	51.6%
581		3	2	33.3%	32	14	56.3%	3	2	33.3%	30	22	26.7%
584	56	3	1	66.7%	32	4	87.5%	3	3	0.0%	30	24	20.0%
587	39	3	0	100.0%	31	6	80.6%	3	2	33.3%	29	18	37.9%
588		3	0	100.0%	29	4	86.2%	3	2	33.3%	27	16	40.7%
591		3	0	100.0%	32	5	84.4%	3	1	66.7%	32	20	37.5%
593		3	3	0.0%	26	12	53.8%	3	2	33.3%	23	10	56.5%
595	56	3	3	0.0%	28	16	42.9%	3	3	0.0%	28	21	25.0%
600		3	0	100.0%	32	1	96.9%	3	0	100.0%	32	4	87.5%
601		2	2	0.0%	24	11	54.2%	2	0	100.0%	24	4	83.3%
605		2	1	50.0%	24	11	54.2%	2	0	100.0%	23	1	95.7%
607		3	0	100.0%	32	2	93.8%	3	0	100.0%	32	1	96.9%
609		2	0	100.0%	24	2	91.7%	2	0	100.0%	23	0	100.0%
622		2	1	50.0%	22	3	86.4%	2	1	50.0%	22	2	90.9%
626		3	0	100.0%	32	5	84.4%	3	0	100.0%	32	5	84.4%
640		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	4	83.3%
641		2	0	100.0%	24	4	83.3%	2	0	100.0%	24	2	91.7%
642		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	2	91.7%
643		3	2	33.3%	32	10	68.8%	3	0	100.0%	32	3	90.6%
644		2	1	50.0%	24	3	87.5%	2	0	100.0%	24	7	70.8%
645		3	2	33.3%	32	11	65.6%	3	0	100.0%	31	4	87.1%
646		2	0	100.0%	24	6	75.0%	2	1	50.0%	24	3	87.5%
647		3	0	100.0%	31	4	87.1%	3	0	100.0%	30	1	96.7%
648		2	1	50.0%	24	1	95.8%	2	0	100.0%	24	1	95.8%
649	24	3	0	100.0%	32	2	93.8%	3	1	66.7%	32	5	84.4%
650	61	3	0	100.0%	32	4	87.5%	3	1	66.7%	32	3	90.6%
651	24	2	0	100.0%	24	0	100.0%	2	1	50.0%	24	5	79.2%
652		3	0	100.0%	32	3	90.6%	3	0	100.0%	32	2	93.8%
653		2	2	0.0%	23	9	60.9%	2	0	100.0%	23	3	87.0%
654		2	0	100.0%	23	5	78.3%	2	0	100.0%	23	3	87.0%
655		3	0	100.0%	32	3	90.6%	3	0	100.0%	32	2	93.8%
656		3	1	66.7%	32	6	81.3%	3	0	100.0%	32	5	84.4%
657		2	0	100.0%	24	8	66.7%	2	0	100.0%	24	1	95.8%

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
658		3	0	100.0%	31	1	96.8%	3	0	100.0%	31	1	96.8%
680		2	0	100.0%	24	4	83.3%	2	0	100.0%	24	2	91.7%
681		2	0	100.0%	24	0	100.0%	2	1	50.0%	23	11	52.2%
682		2	0	100.0%	24	3	87.5%	2	0	100.0%	24	4	83.3%
683	39	2	0	100.0%	24	0	100.0%	2	2	0.0%	24	18	25.0%
684		2	0	100.0%	24	2	91.7%	2	0	100.0%	24	9	62.5%
685		2	0	100.0%	24	3	87.5%	2	1	50.0%	24	8	66.7%
686		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	9	62.5%
687		2	0	100.0%	24	5	79.2%	2	1	50.0%	24	9	62.5%
688		2	0	100.0%	24	1	95.8%	2	1	50.0%	24	7	70.8%
701	27	3	1	66.7%	34	5	85.3%	3	2	33.3%	34	9	73.5%
702		3	0	100.0%	34	2	94.1%	3	0	100.0%	34	14	58.8%
703		3	1	66.7%	34	11	67.6%	3	1	66.7%	34	7	79.4%
704		3	2	33.3%	34	8	76.5%	3	1	66.7%	34	5	85.3%
710		3	0	100.0%	34	6	82.4%	3	0	100.0%	34	7	79.4%
711		3	0	100.0%	34	6	82.4%	3	0	100.0%	29	4	86.2%
712	19	3	1	66.7%	34	11	67.6%	3	2	33.3%	34	15	55.9%
713		3	2	33.3%	31	12	61.3%	3	1	66.7%	26	7	73.1%
714	19	3	3	0.0%	34	20	41.2%	3	2	33.3%	33	18	45.5%
715	Cncld	3	0	100.0%	34	6	82.4%	2	1	50.0%	32	16	50.0%
716		3	0	100.0%	33	15	54.5%	3	0	100.0%	32	7	78.1%
717	34	3	1	66.7%	34	15	55.9%	3	2	33.3%	31	14	54.8%
718	39	3	3	0.0%	34	23	32.4%	3	1	66.7%	34	13	61.8%
719		3	1	66.7%	34	7	79.4%	3	0	100.0%	34	7	79.4%
757		3	0	100.0%	31	2	93.5%	3	0	100.0%	31	14	54.8%
761		3	0	100.0%	32	0	100.0%	3	0	100.0%	32	11	65.6%
765	60	3	0	100.0%	32	0	100.0%	3	1	66.7%	32	20	37.5%
769	77	3	0	100.0%	32	2	93.8%	3	3	0.0%	32	24	25.0%
770	45	3	0	100.0%	32	3	90.6%	3	3	0.0%	31	22	29.0%
774	50	3	2	33.3%	32	15	53.1%	3	2	33.3%	31	26	16.1%
777		3	1	66.7%	32	3	90.6%	3	2	33.3%	31	22	29.0%
782	20	3	1	66.7%	32	22	31.3%	3	3	0.0%	31	23	25.8%
785		3	1	66.7%	32	18	43.8%	3	0	100.0%	32	18	43.8%
786		3	1	66.7%	32	10	68.8%	3	2	33.3%	27	16	40.7%
790		3	0	100.0%	32	2	93.8%	3	2	33.3%	32	20	37.5%
794	59	3	2	33.3%	32	16	50.0%	3	2	33.3%	32	17	46.9%
821	38	3	0	100.0%	33	2	93.9%	3	3	0.0%	33	27	18.2%
822	43	3	0	100.0%	33	2	93.9%	3	3	0.0%	33	28	15.2%
1082	69	2	0	100.0%	17	2	88.2%	2	1	50.0%	17	4	76.5%
1087	53	2	0	100.0%	17	1	94.1%	2	1	50.0%	16	2	87.5%
1088	35	2	0	100.0%	17	2	88.2%	2	1	50.0%	17	4	76.5%
1099		2	0	100.0%	17	0	100.0%	2	1	50.0%	17	6	64.7%

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1103		2	0	100.0%	17	8	52.9%	2	0	100.0%	17	3	82.4%
1107		2	1	50.0%	17	6	64.7%	2	0	100.0%	17	3	82.4%
1109		2	0	100.0%	17	1	94.1%	2	0	100.0%	17	1	94.1%
1111		2	0	100.0%	17	2	88.2%	2	0	100.0%	17	0	100.0%
1116	35	2	0	100.0%	17	2	88.2%	2	1	50.0%	17	2	88.2%
1118		2	0	100.0%	17	2	88.2%	2	0	100.0%	17	0	100.0%
1124		2	0	100.0%	15	2	86.7%	2	0	100.0%	15	5	66.7%
1126		2	1	50.0%	17	1	94.1%	2	0	100.0%	17	4	76.5%
1127		2	0	100.0%	17	3	82.4%	2	0	100.0%	17	1	94.1%
1128		2	0	100.0%	17	2	88.2%	1	0	100.0%	16	1	93.8%
1129		2	0	100.0%	17	1	94.1%	2	0	100.0%	17	3	82.4%
1135		2	0	100.0%	17	2	88.2%	2	0	100.0%	17	12	29.4%
1138		2	0	100.0%	16	2	87.5%	2	0	100.0%	16	3	81.3%
1140	32	2	1	50.0%	17	5	70.6%	2	1	50.0%	17	2	88.2%
1142		2	0	100.0%	17	4	76.5%	2	0	100.0%	17	4	76.5%
1143		2	0	100.0%	17	0	100.0%	2	1	50.0%	17	6	64.7%
1144		2	2	0.0%	17	14	17.6%	2	0	100.0%	17	4	76.5%
1146	17	2	1	50.0%	17	4	76.5%	2	1	50.0%	17	2	88.2%
1147		2	0	100.0%	17	0	100.0%	2	1	50.0%	17	5	70.6%
1150		2	2	0.0%	17	12	29.4%	2	1	50.0%	17	3	82.4%
1151	31	2	1	50.0%	17	6	64.7%	2	1	50.0%	17	9	47.1%
1152		2	0	100.0%	17	2	88.2%	2	0	100.0%	17	3	82.4%
1153		2	0	100.0%	17	0	100.0%	2	0	100.0%	17	0	100.0%
1155		2	0	100.0%	16	2	87.5%	2	0	100.0%	16	5	68.8%
1156	27	2	0	100.0%	14	2	85.7%	2	1	50.0%	14	10	28.6%
1160		2	0	100.0%	17	0	100.0%	2	1	50.0%	17	8	52.9%
1161	42	2	0	100.0%	17	0	100.0%	2	2	0.0%	17	13	23.5%
1162	50	2	0	100.0%	17	0	100.0%	2	2	0.0%	17	10	41.2%
1163	22	2	0	100.0%	17	1	94.1%	2	2	0.0%	17	13	23.5%
1164	132	2	1	50.0%	16	2	87.5%	2	1	50.0%	16	6	62.5%
1165		2	0	100.0%	17	0	100.0%	2	0	100.0%	17	7	58.8%
1167	117	2	1	50.0%	17	5	70.6%	2	1	50.0%	17	6	64.7%
1168		2	0	100.0%	17	4	76.5%	2	0	100.0%	17	4	76.5%
1169	27	2	1	50.0%	16	4	75.0%	1	1	0.0%	15	3	80.0%
1194		2	0	100.0%	17	2	88.2%	2	0	100.0%	17	2	88.2%
1195		2	0	100.0%	16	0	100.0%	2	0	100.0%	15	1	93.3%
1333	73	3	1	66.7%	34	4	88.2%	3	1	66.7%	34	11	67.6%
1340		3	0	100.0%	34	0	100.0%	3	0	100.0%	34	4	88.2%
1697		1	0	100.0%	6	0	100.0%	1	0	100.0%	6	2	66.7%
2101		2	0	100.0%	17	1	94.1%	2	0	100.0%	17	1	94.1%
2103		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	2	91.7%
2105		2	1	50.0%	24	2	91.7%	2	1	50.0%	24	2	91.7%

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak On Time Performance

Trains Arriving Through: 11/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2106		2	0	100.0%	17	0	100.0%	2	0	100.0%	17	2	88.2%
2114		2	0	100.0%	17	3	82.4%	2	0	100.0%	17	3	82.4%
2115	20	2	0	100.0%	24	0	100.0%	2	1	50.0%	23	4	82.6%
2116	17	2	0	100.0%	24	2	91.7%	2	1	50.0%	24	1	95.8%
2118	30	2	0	100.0%	24	3	87.5%	2	1	50.0%	23	5	78.3%
2120		2	0	100.0%	24	3	87.5%	2	0	100.0%	24	3	87.5%
2122		2	0	100.0%	17	2	88.2%	2	0	100.0%	17	2	88.2%
2123	60	2	0	100.0%	24	2	91.7%	2	1	50.0%	24	3	87.5%
2133		2	0	100.0%	17	0	100.0%	2	0	100.0%	17	2	88.2%
2148		2	0	100.0%	17	1	94.1%	2	0	100.0%	16	2	87.5%
2149	31	2	0	100.0%	17	2	88.2%	2	2	0.0%	17	16	5.9%
2150	205	2	0	100.0%	24	0	100.0%	2	2	0.0%	23	13	43.5%
2151		2	0	100.0%	24	0	100.0%	2	1	50.0%	24	14	41.7%
2152		2	0	100.0%	24	1	95.8%	2	0	100.0%	24	2	91.7%
2155		2	0	100.0%	24	1	95.8%	2	0	100.0%	23	2	91.3%

Amtrak Endpoint OTP Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2115	WAS	20	TRS	14	TRS	10	MET-XCY	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
2116	NYP	17	TRS	17	TRS	12	XCY-NWK	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
2118	NYP	30	TRS	25	TRS	14	XCY-MET	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
2123	WAS	60	TRS	56	TRS	56	NWK-XCY	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
2149	WAS	31	DMW	16	DMW	16	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2150	BOS	205	TRS	135	TRS	135	PVD-PVD	AM	Trespasser strike, Milepost, 219.14, 219.14, HELD AT PVD DUE TO TRESPASSER STRIKE AT MP 219.14, TRK 1 (TRANSFER & READ)
66	BOS	37	DET	58	DET	58	NWK-NYP	AM	Catenary failure, Other, NWK-XHU, (ENG 608) STOPPED EAST OF DOCK ON NO. 2 TRACK AFTER MULTIPLE FAULTS INCLUDING NO VALID VOLTAGE DETECTED
1082	BOS	69	TRS	76	TRS	46	PVD-PVD	AM	Trespasser strike, Milepost, 219.14, 219.14, HELD AT PVD DUE TO TRESPASSER STRIKE AT MP 219.14, TRK 1 (TRANSFER & READ)
1087	NFK	53	PTI	53	PTI	31	ASD-RVR	CS	Wait for station track 97, Control Point, Greendale
1088	BOS	35	TRS	36	TRS	20	PVD-RTE	AM	Trespasser strike, Milepost, XJC, BBY, REQUESTED TO BE DETOURED TO TRK 1 AT RTE 128, WAITED FOR LATE WESTBOUND TRAFFIC TO CLEAR JCT (LATE FROM TRESPASSER STRIKE)
1116	NYP	35	TRS	25	TRS	25	XHM-EWR	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
1140	SPG	32	TRS	38	TRS	25	TRE-MET	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE

Amtrak Endpoint OTP Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1146	SPG	17	SYS	51	SYS	49	WAS-WAS	AM	Delay in Block, TRAIN WYED LATE, LEFT AT 3:50PM BACKED DOWN AT 4:20PM NEC'Y TO SWAP MTRS TO LESSEN DELAY ORG MTR NEEDING FULL WORKUP
1151	RNK	31	PTI	24	PTI	24	CVS-LYH	NS	Cross over or go around 20, 156, Milepost, 117.5, 120..5
1156	NYP	27	PTI	27	PTI	17	ALX-XVG	CS	Meet 155, Control Point, Virginia
1161	WAS	42	TRS	46	TRS	41	MET-TRE	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
1162	BOS	50	DSR	24	DSR	18	STM-BRP	MN	Per bulletin Milepost, 40.4, 41.7, 30, 2, Milepost, 41.7, 42.0, 15, 2, Milepost, 46.3, 46.5, 30, 2
1163	WAS	22	TRS	24	TRS	24	MET-TRE	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
1164	BOS	132	TRS	129	TRS	82	PVD-PVD	AM	Trespasser strike, Milepost, 219.14, 219.14, HELD AT PVD DUE TO TRESPASSER STRIKE AT MP 219.14, TRK 1 (TRANSFER & READ)
1167	PHL	117	TRS	120	TRS	108	BOS-BOS	AM	Trespasser strike, Milepost, 219.14, 219.14, HELD AT BOS DUE TO TRESPASSER STRIKE AT MP 219.14, TRK 1 (TRANSFER & READ)
1169	PHL								
53	SFA	387	ITI	179	ITI	179	LOR-LOR	CS	Late departure at initial terminal due to late arrival of inbound equipment 52, Also late so to DRUMMAC they didn't have enough chalkers
79	CLT	30	PTI	48	PTI	29	CYN-DNC	NS	Meet NC 76, Siding, Nelson
80	NYP	46	PTI	25	PTI	17	BNC-DNC	NS	Meet NC 73, Siding, Funston
649	HAR	24	TRS	25	TRS	25	EWR-TRE	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
650	NYP	61	TRS	54	TRS	28	PJC-NWK	AM	Trespasser strike, Other, PJC-NWK, CONGESTION AHD DUE TO TRESPASSER STRIKE AT NEW BRUNSWHICK
651	HAR	24	TRS	30	TRS	30	NWK-TRE	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE

Amtrak Endpoint OTP Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
683	BRK	39	PTI	27	PTI	27	XP0-EXR	CS	Meet 684, Control Point, plastow
63	TWO	32	FTI	62	FTI	29	AMS-UCA	CS	Follow csxt, Control Point, 210
64	NYP	24	ENG	39	ENG	34	NFL-NFL	CS	PTC outage nationwide 122
290	NYP	18	CTI	15	PTI	12	SDY-ALB	AM	Meet 281, Control Point, 149
48	NYP	22	FTI	81	SVS	58	SYR-SYR	CS	PTC - Initializing PTC (no failure) New engineer was unable to initialize PTC due to national outage. Called PTC help desk and CNOC for assistance. Was advised by CSX NF to run with IETMS for cut out and to try to initialize at UCA station., Other, syracuse starion
448	BOS	64	FTI	46	FTI	31	PIT-SPG	CS	Meet 424, Control Point, 109
449	ALB	235	TRS	215	TRS	215	SPG-PIT	CS	Trespasser strike Milepost, 102.2, 102.2
42	NYP	22	TRS	15	TRS	15	TRE-NWK	AM	Trespasser strike, Other, NBK, Held A/C AM98 AHD AT NEW BRUNSWHICK WITH TRESPASSER STRIKE
71	CLT	18	TRS	13	TRS	13	GRO-SAL	NS	Near-miss Milepost, 316.2, 316.2
89	SAV	60	FTI	72	FTI	26	KTR-CHS	CS	Meet M 492, Control Point, A 352.9
90	NYP	190	DMW	72	DMW	68	FAY-SSM	CS	Hold for defect repair Other, a172.0
97	MIA	39	FTI	69	DCS	50	WPB-DLB	FL	Power switch failure Control Point, Seaboard
98	NYP	427	TRS	189	TRS	189	TRE-NWK	AM	Trespasser strike, Other, NBK, STOPPED AT NBK A/C TRESPASSER STRIKE ON NO.1 TRK
40	CHI	44	FTI	81	FTI	61	CUM-COV	CS	Meet IO18, Milepost, 266.8, 268.5
41	MIA	118	CAR	89	CAR	89	CHI-CHI	AM	Set out defective car, 68009, Dinner car was bad ordered and set out with no replacement.
5	EMY	260	DMW	146	DMW	140	XSZ-XNV	UP	Hold for defect repair Hold at Timpie for broken rail, Siding, Timpie
6	CHI	47	FTI	223	FTI	143	COX-XSO	UP	Had to shove back from M.P 146 to 133 to get onto another track due to freight train breaking down frieght, Milepost, 140, 133, frieght
521	SJC	30	DCS	13	MBO	13	SUI-MTZ	UP	For maritime traffic Control Point, Benicia
522	SAC	61	DSR	1	DSR	1	RIC-MTZ	UP	Per bulletin Milepost, 26.00, 26.40, 25, m2
523	SJC	20	DCS	23	DCS	15	OKJ-OKJ	UP	Signal suspension Control Point, Ni009

Amtrak Endpoint OTP Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
524	SAC	22	DCS	25	DCS	13	OAC-OAC	UP	Signal suspension Other, OAC
527	SJC	71	TCC	66	TCC	66	OKJ-OAC	UP	PTC - On Board Cab Signal or PTC Failure C2010, PTC Failure system wide outage
530	SAC	46	ITI	47	ITI	47	SJC-SJC	UP	Late departure at initial terminal due to late arrival of inbound equipment 527
543	SJC	54	CTI	24	ITI	20	SAC-SAC	UP	Late departure at initial terminal due to late arrival of inbound equipment 530
549	OKJ	31	PTI	37	PTI	18	SUI-MTZ	UP	Follow AMT5, Milepost, 47, 34
500	SEA	23	MBO	20	MBO	20	PDX-VAN	BN	Issues with bridge. Waited for authority past stop signal after inspection of bridge Bridge, Columbia River
505	PDX	22	FTI	15	FTI	15	XA4-XTW	BN	Meet BNSF 7075, Control Point, Stewart
509	PDX	89	POL	92	POL	92	SEA-TUK	BN	RR blocked by trespasser or vehicle strike by another train
518	VAC	170	POL	98	POL	98	TUK-SEA	BN	RR blocked by trespasser or vehicle strike by another train
11	LAX	Trn Cancelled	DMW	141	DMW	120	CIC-XB7	UP	Hold for defect repair Broken rail, Milepost, 163.0, 161.0
14	SEA	67	DCS	129	DCS	60	SBA-SLO	UP	PTC- Planned PTC system maintenance Track and Time 59-41 CO356-CO295, Milepost, 356.00, 295.00
8	CHI	221	ENG	142	ENG	95	MSP-MSP	CP	Swap out locomotives 206 to the 306 because Engineer wiper blade broke and couldn't see going forward, per Amtrak 206
821	FTW	38	FTI	39	FTI	39	PUR-PVL	BN	Meet BN7152, Bn7165, Siding, Purcell, Siding, Paoli
822	OKC	43	DSR	36	FTI	29	GLE-ADM	BN	Meet bnsf 4275, Siding, thackerville
336	CHI	27	DSR	14	DSR	14	MKA-SVT	CP	Per bulletin Routed down Main 2 at Lake for 1333, I61, and 247, Milepost, 76.6, 69.6, 25, Main 2
352	PNT	40	PTI	30	PTI	30	ALI-JXN	MI	Meet am355, Control Point, 75
353	CHI	48	DMW	35	DMW	32	HMI-XTF	NS	Bridge strike Other, cd518
365	CHI	19	CTI	12	CTI	12	XH6-XTF	AM	Meet Metra, Unknown, Control Point, 21st St
562	SAN	87	PTI	83	PTI	83	SNC-X98	SC	Meet 765, Control Point, Serra
564	SAN	51	DCS	51	DCS	19	SNC-SNP	SC	Issue with automatic road crossing protection Milepost, 20371, 20371, Milepost, 20395, 20395, Milepost, 20404, 20404

Amtrak Endpoint OTP Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
566	SAN	91	PTI	75	PTI	67	SNC-SNP	SC	Meet 567, 769, Control Point, Serra
567	LAX	112	PTI	104	PTI	104	OSD-X98	SC	Meet 562, 564, Control Point, songs
572	SAN	Trn Cancelled							
573	LAX	89	ITI	47	ITI	47	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 562, Arrived in SAN late.
579	LAX	Trn Cancelled							
580	SAN	18	CTI	13	CTI	10	OSD-SOL	SN	Meet coaster, 641, Control Point, longboard
584	SAN	56	PTI	46	PTI	46	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	39	CTI	49	CTI	32	OSD-X98	SN	Meet Metrolink, Control Point, Songs
595	LAX	No OS Rpt	ITI	26	ITI	26	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 584
765	GTA	60	DCS	74	DCS	34	SNP-SNP	SC	Issue with automatic road crossing protection Dije CT, El Portal, SNP pedestrian Xing, Milepost, 204.04, 203.71
769	GTA	77	DCS	37	DCS	19	OSD-X98	SC	CTC system failure Control Point, Songs
770	SAN	45	DCS	56	DCS	31	SNC-SNP	SC	Issue with automatic road crossing protection Issued 2 procedure 1's and 1 procedure 2 x-ings, Control Point, Lantern
774	SAN	50	PTI	45	CON	27	SBA-SBA	UP	Hold for thruway bus 36 pax connecting
782	SAN	20	PTI	36	PTI	15	SBA-CPN	UP	Meet 14, Control Point, CO 369
794	SAN	59	ITI	57	ITI	57	GTA-GTA	UP	Late departure at initial terminal due to late arrival of inbound equipment 777, Late Arrival to GTA A 777 Switch ends at platform and shove back to ellwood to clear for A 11 at the siding.
701	SAC	27	POL	26	PTI	23	MCD-TRK	BN	Meet Amtrak 710, Siding, Fluhr
712	BFD	19	RTE	21	RTE	21	HNF-COC	BN	Dispatcher hold Held for AMTK 717 NAR, Control Point, east guernsey
714	BFD	19	PTI	28	DCS	10	ACA-SKN	BN	Restrictive signal(s) from known wayside signal failure Restricting , Control Point, holt
715	OKJ	Trn Cancelled	DCS	31	DCS	24	SKN-ACA	BN	Restrictive signal(s) from unknown cause Restricting , Control Point, west skn
717	OKJ	34	DCS	33	DCS	33	SKN-ACA	BN	Flagging West Stockton to Holt 15 mph causing delay Control Point, West Stockton

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
718	BFD	39	TEN	41	TEN	41	OKJ-OKJ	UP	Set out defective locomotive CDTX2003 was set out due to damage from previous train 714. CDTX 2002 was added to our consist causing delay. Informed Operations West and Train Master Naterman., C2003
3	LAX	508	FTI	535	FTI	147	XIA-GLP	BN	Follow BNSF, bnsf 9003 west, Milepost, 31.5, 144.2
4	CHI	283	FTI	323	FTI	54	XC7-LAP	BN	Follow BN 6964, Control Point, Congo
305	STL	71	DTR	22	DTR	22	XWR-STL	TR	UNKNOWN XWR, STL
383	QCY	69	RTE	47	RTE	26	GBB-GBB	BN	Dispatcher hold Galesburg yard control had freight occupying several tracks, Control Point, Gbb
392	CHI	84	DMW	49	DMW	45	RTL-GLM	CC	Waiting on track inspector for rough track reported ahead @ MP 92 Control Point, north paxton
318	CHI	68	TRS	41	TRS	41	SED-JEF	UP	Pax walking in bridge. Either jumped or was clipped by train and fell 20 feet to ground below Milepost, 186.3, 186.6
319	KCY	38	FTI	27	PTI	14	DWT-PON	UP	Meet Amtrak Train 22, Siding, O'dell
1333	MSP	73	SYS	36	SYS	36	CHI-CHI	AM	PTC problem or failure (cause unknown)

Amtrak Initial Terminal Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/3/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	67	11/03	48	48	Trespasser strike, Milepost, 219.14, 219.14, HELD AT BOS DUE TO TRESPASSER STRIKE AT MP 219.14, TRK 1 (TRANSFER & READ)
BOS	1167	11/03	108	108	Trespasser strike, Milepost, 219.14, 219.14, HELD AT BOS DUE TO TRESPASSER STRIKE AT MP 219.14, TRK 1 (TRANSFER & READ)
GRO	75	11/03	1		
HAR	648	11/03	1	1	Passenger and/or baggage, TRAVEL AND BAGGAGE ASSISTANCE
NYP	97	11/03	39	39	Trespasser strike, Other, NBK, HELD DUE TO TRESPASSER STRIKE AT NEW BRUNSWHICK
NYP	237	11/03	6	6	Loading problem, 700|DX|DM, HELD A/C ENGINE FAILING TO LOAD
NYP	1107	11/03	4	4	Door, 82682|AX|AS, DOOR ISSUES
NYP	1169	11/02	3		
PHL	601	11/03	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	605	11/03	1	1	PTC - Stop Bypass Permission Required, Control Point, PENN
PHL	645	11/03	4	4	Hold for connecting train, HELD FOR PSGRS FROM 98 W/ BAGGAGE
PHL	653	11/03	1	1	Passenger and/or baggage
PHL	1144	11/03	1	1	Passenger and/or baggage, TRAVEL AND BAGGAGE ASSISTANCE
PHL	1150	11/03	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	1151	11/03	3	3	PTC - Stop Bypass Permission Required, Control Point, PENN
SFA	52	11/03	260	260	Late departure at initial terminal due to late arrival of inbound equipment 53
WAS	1126	11/03	5	3	Delay in Block, crew identified and rectified door issue
WAS	1126	11/03	5	2	Delay in Block, CREW IDENTIFIED AND RECTIFIED DOOR ISSUE
WAS	1140	11/03	3	3	Delay in Block, CNDR DIDNT SECURE THE DOOR PROPERLY ON CAR 82987
WAS	1146	11/03	49	49	Delay in Block, TRAIN WYED LATE, LEFT AT 3:50PM BACKED DOWN AT 4:20PM NEC'Y TO SWAP MTRS TO LESSEN DELAY ORG MTR NEEDING FULL WORKUP
CHI	41	11/03	7	7	Wheelchair Had an extra large power wheelchair could not turn it into the coaches was removed after several attempts of trying different things to fit it in. Chicago station manager there to witness! Train was shoved down at 6:11pm Sleepers @ 6:15 General @ 6:20
CHI	352	11/03	27	17	Bridge strike by a vehicle or boat Held us and cus to make sure we could proceed through the bridge, Bridge, 518

Amtrak Initial Terminal Details

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/3/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	352	11/03	27	10	Door ID4002, Door was open reading open and mechanical come inspect and fix the door
CHI	1333	11/03	36	36	PTC problem or failure (cause unknown)
PTH	365	11/03	8	8	Door ID4201, Door bypass on engine 4617 cut out per CNOC
SAS	22	11/03	45	45	Hold for connecting train 2
BFD	701	11/03	3	3	Door C8305, Door circuit showing doors open, despite all doors being closed, and would not respond to train-line close commands. Walked back to key closed locally and clear circuit.
LAX	4	11/03	128	128	Had to wait for turn of inbound engines off of Train 3 of 11/1/2026 19 and 205, 19
LAX	14	11/03	31	31	Late departure at initial terminal due to late arrival of inbound equipment 14
LAX	572	11/03	(Trn Cxld)		Signal Outage
OKJ	520	11/03	1		
OKJ	522	11/03	(Trn Cxld)		Third Party Engine Failure
OKJ	526	11/03	1	1	Restrictive signal(s) from unknown cause Stop, Control Point, North Jack London
OKJ	714	11/03	4	4	Delayed delivery of equipment from Mechanical (not due to mechanical failure) C6962, In yard at 12:00.
OKJ	718	11/03	12	12	Vehicle on track ahead Vehicle on 1 at king street. All traffic shut down., Other, 6.38
SAC	543	11/03	20	20	Late departure at initial terminal due to late arrival of inbound equipment 530
SAC	549	11/03	1		
SAC	704	11/03	2	2	Door C8305, Door light has to be closed locally; wouldn't trainline.
SAN	573	11/03	47	47	Late departure at initial terminal due to late arrival of inbound equipment 562, Arrived in SAN late.
SAN	579	11/03	(Trn Cxld)		Signal Outage
SAN	593	11/03	2	1	CTC system failure Track selection, Control Point, ash
SAN	593	11/03	2	1	Door 6408, Door not closing
SAN	595	11/03	26	26	Late departure at initial terminal due to late arrival of inbound equipment 584
SEA	11	11/03	23	23	PTC- Unplanned PTC system /server outage System wide outage, multiple trains affected, Control Point, SEA yard
SJC	530	11/03	47	47	Late departure at initial terminal due to late arrival of inbound equipment 527
SJC	550	11/03	1		

Eastern Region

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.1	99.4	99.14	342	3
CDOT	95.0	91.7	87.5	92.4	24	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	93.7	No Data	No Data
NJT-NED	95.0	85.4	90.9	88.6	206	30
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 89(03) - South of Charleston, SC - Freight Train Interference

04NOV26: Train 89(03) was delayed on the CSX Charleston Subdivision at MP 394.6 due to meeting CSX Train M410-03.

Train	Delay	Comment
89(03)	49"	

Train 66(03) - Alexandria, VA - Power Switch Failure/Signal

03NOV26: Train 66(03) was delayed on the CSX RF&P Subdivision at MP 105.8 due to a power switch failure ahead at CP Slaters Lane/MP 106.4.

Train	Delay	Comment
66(03)	33"	

Train 97(02) - South of West Palm Beach, FL - Power Switch Failure/Signal

03NOV26: Train 97(02) was delayed on the CSX Miami Subdivision at MP 972.5 due to a power switch failure at CP Seaboard/MP 972.8. Maintainers responded to correct the issue.

Train	Delay	Comment
97(02)	50"	

Train 1146(03) Washington, DC - Engine Failure

03NOV26: Train 1146(03) was delayed at its initial terminal at Washington Union Terminal due to a late engine swap. The original engine-642 needed a full work up/inspection. In order to decrease the delay, E/642 was swapped out for E/654.

Train	Delay	Comment
1146(03)	49"	

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Train 449(03) West of Springfield, MA - Trespasser Incident

03NOV26: At approximately 3:49pm ET, Train 449(03), operating with Locomotives E/375 and E/98, four cars, and 65 customers onboard, struck a trespasser at Milepost 102, approximately four miles west of SPG. The incident resulted in a confirmed fatality.

There were no reported injuries to customers or crew members as a result of the incident. Following the strike, the train was brought to a stop and local law enforcement and appropriate railroad personnel responded to the scene to conduct the investigation. Rail operations in the area were impacted while authorities completed their on-scene activities and evidence collection.

A relief crew was readied to assist with the continuation of service once the investigation and all required operating procedures were completed.

National Response Center Number: 1477764

Train	Delay	Comment
449(03)	3'38"	
49(03)	3'45"	Held at ALB for 449 section

MBTA MT6021- Boston, MA- MBTA Keolis Trespasser Strike

03NOV26: 3:56pm MBTA Train MT6021 fatally struck a trespasser who intentionally placed himself in the path of the train at MP 219.14 on the Amtrak New Haven to Boston Line. The trespasser was a confirmed fatality. There were no other injuries reported.
Amtrak ASO Gilbert and RFE Romikitis responded to the scene.
All train traffic at the scene was temporarily suspended. Multiple Amtrak and MBTA Trains incurred substantial delay.
At 7:49pm the hold on all tracks was released.

National Response Center Number: 1477766

Train	Delay	Comment
1088(03)	31"	
1082(03)	1'18"	
67(03)	1'08"	
1164(13)	1'52"	
1167(03)	2'00"	
2150(03)	2'15"	
38 MBTA Trains	06" - 2'40"	3 Cancelled

27-FOI-00137 : 00000009135 : UNCLASSIFIED : 1/10/2026

Train 98(02) West of New Brunswick, NJ - Trespasser Incident

03NOV26: At approximately 2:10PM ET, Train 98(02), operating with Locomotive 665, 10 cars, and 136 customers, struck a trespasser on Track 1 at the New Brunswick, NJ station (MP 30.7), approximately 14 miles north of Trenton, NJ. The incident resulted in a confirmed fatality.

No injuries were reported among customers or crew members. A Trainmaster responded to the scene with a relief crew, and Amtrak Police initiated an investigation. As a result, all rail traffic through the area was temporarily halted while emergency responders and investigators conducted their work.

During the investigation, operational impacts extended to multiple trains in the territory as rail traffic was held pending authorization to resume movement. Once conditions permitted, Tracks 3 and 4 were returned to service, allowing trains to operate through the area at restricted speed while investigative activities continued on Track 1.

Following completion of the investigation and release of the scene by the appropriate authorities, rail operations were fully restored. Train 98(02) subsequently resumed its trip and continued to its final destination.

Weather conditions at the time of the incident were reported as 71°F with clear, sunny skies.

National Response Center Number: 1477735

Train	Delay	Comment
1161(03)	41"	Hold Edison, NJ
2123(03)	56"	Hold MET
650(03)	26"	Hold PJC
97(03)	39"	Hold NYP
1140(03)	38"	Hold TRE
649(03)	22"	hold NWK
19(03)	57"	Hold MET
98(02)	3'07"	
1116(03)	25"	
1163(03)	24"	
2118(03)	27"	
1156(03)	13"	

Train 41(01) North of Kissimmee, FL - Commuter Train Interference

03NOV26: Train 41(01), with 126 customers, was delayed 1 mile north of the Kissimmee, FL station on Central Florida Rail Commission territory after disabled commuter train P317 blocked access to the station track at Middle Kissimmee MP 807.7.

Train	Delay	Comment
41(01)	57"	

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

National Amtrak Positive Train Control Outage

03NOV26: At approximately 11:26A-ET, a undisclosed Amtrak Positive Train Control outage caused trains to experience issues initializing PTC. Amtrak Digital Technology team was able to work with Wabtec to restore the PTC. PTC service was restored at 12:41P-ET.

Train 48(02) was delayed at the Syracuse, NY station.
Train 64(03) was delayed at the Niagara Falls, NY station.
Train 90(03) was delayed at the Florence, SC station.
Train 353(03) was delayed at the Battle Creek, MI station.
Train 1333(03) was delayed at Chicago, IL Union Station.
Train 8/28(01) was delayed at the St. Paul/Minneapolis, MN station.
Train 5(02) was delayed west of the Denver, CO station.
Train 14(03) was delayed at Los Angeles, CA Union Station.
Train 527(03) was delayed south of Oakland, CA Jack London Square Station.
Train 11(03) was delayed at Seattle, WA King Street Station.

Train 530(03) was delayed departing the San Jose, CA station account of turning late inbound Train 527(03).

Train	Delay	Comment
527(03)	1'11"	
1333(03)	36"	
353(03)	18"	
48(02)	58"	
90(03)	34"	
14(03)	31"	
11(03)	23"	
8/28(01)	41"	
64(03)	34"	
530(03)	47"	SJC - Turn Late Inbound 527(03)
543(03)	20"	SAC - late turn of equip 530(03)

Train 90(03) North of Charleston, SC - Debris Strike

03NOV26: Train 90(03), operating with Locomotive 82, 7 cars, and 58 customers, was stopped north of the Charleston, SC station at MP 377.2 on the CSX Charleston subdivision after striking a bicycle and an unoccupied stroller that were fouling the track. The individual pushing the items was not struck and cleared the track area before the incident. Local law enforcement responded and located the individual unharmed. The scene was released, and the crew completed a Class II air test before resuming operation.

Train	Delay	Comment
90(03)	52"	

Train 49(02) West of Erie, PA - Air Hose Separation

03NOV26: Train 49(02), with 288 customers, was stopped 60 miles west of the Erie, PA station on the CSX Erie West Subdivision after the train experienced an undesired emergency brake application due to a hose separation between Sleepers 62044 and 62047.

Train	Delay	Comment
49(02)	34"	

Train 66(02) East of Newark, NJ - Catenary or Wayside Failure

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

03NOV26: Train 66(02) operating with Locomotive 608 and 148 customers, was stopped east of Dock (MP 7.8) on Track 2 on the New York Penn Line after experiencing multiple faults, including a no-valid-voltage-detected fault. The crew attempted to recycle the locomotive without success. Multiple trains crossing from Track 1 to Track 3 at Dock reported main circuit breaker openings and loss of power, with power restored on Track 3. Trains operated around Track 2 east of Newark, NJ Penn Station. Electric Traction personnel were dispatched. Infrastructure Maintenance and Construction Services advised a catenary switch did not fully close after power was restored following overnight protection for the Dock Bridge project, resulting in low power east of the break. Power was restored after the switch was opened and reclosed. Once the issue was identified and resolved, train 66(02) resumed operations without further delay.

Train	Delay	Comment
66(02)	58"	

Maintenance of Way Highlights

Piedmont and Carolinian NS Track Work - 10/26-10/29 - 11/2-11/5 TWA 24-016

37EQI-00137 "0000009138" "UNCLASSIFIED" 01/10/2026

26AUG26: The NS / NC Line trackwork between MP NC 0.6 and MP NC 31.6 for Rail Pick up and Switch Replacement occurring between 900A-ET and 600P-ET on Monday, October 26 to Thursday, October 29 and Monday, November 2 to Thursday, November 6. To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

· Train 72 (26Oct-29Oct, 2Nov-5Nov), which normally operates between CLT and RGH, will terminate at GRO.

· Train 74 (26Oct-27Oct, 2Nov-3Nov), which normally operates between CLT and RGH, will terminate at GRO.

· Train 74 (28Oct-29Oct, 4Nov-5Nov) will operate 10-minutes Earlier between CLT and BNC, and 8-minutes Earlier between DNC and RGH.

· Train 76 (26Oct-27Oct, 2Nov-3Nov) will operate 30-minutes Later between CLT and GRO, add a BNC stop at 7:21pm, and operate 34-minutes Later between DNC and RGH.

· Train 76 (28Oct-29Oct, 4Nov-5Nov) will operate 30-minutes Later between CLT and RGH, departing CLT at 5:35pm.

WESTBOUND

· Train 71 (26Oct-29Oct, 2Nov-5Nov) will operate 15-minutes Earlier, departing RGH at 6:15am.

· Train 73 (26Oct-29Oct, 2Nov-5Nov) will depart RGH 55-minutes Earlier, at 9:05am, and operate on an earlier schedule between RGH and CLT. See schedule grid below.

· Train 75 (26Oct-27Oct, 2Nov-3Nov), which normally operates between RGH and CLT, will originate at GRO, departing 14-minutes Later at 2:34pm.

· Train 75 (28Oct-29Oct, 4Nov-5Nov), which normally operates between RGH and CLT, will originate at GRO.

· Train 77 (26Oct-27Oct, 2Nov-3Nov), which normally operates between RGH and CLT, will originate at GRO, departing 44-minutes Later at 5:35pm.

· Train 77 (28Oct-29Oct, 4Nov-5Nov) will operate 30-minutes Later between RGH and CLT, departing RGH at 3:45pm.

ALTERNATE TRANSPORTATION:

· Bus 3172 (26Oct-29Oct, 2Nov-5Nov) will provide alternate transportation between GRO and RGH making all stops except BNC.

· Bus 3174 (26Oct-27Oct, 2Nov-3Nov) will provide alternate transportation between GRO and RGH making all stops except BNC.

· Bus 3175 (26Oct-29Oct, 2Nov-5Nov) will provide alternate transportation between RGH and GRO making all stops except BNC.

· Bus 3177 (26Oct-27Oct, 2Nov-3Nov) will provide alternate transportation between RGH and GRO making all stops except BNC.

WBS#: B.TR.100150.7292

27-FOI-00137 000000009135 "UNCLASSIFIED" 11/10/2026

Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work

26OCT26: Due to the Veltri conditions outages on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

27-FOI-00137 000000009135 "UNCLASSIFIED" 11/10/2026

09MAR26: Beginning April 21, 2026 and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 80(03) Passenger Removal at Burlington, North Carolina – Passenger Removal

03NOV26, Passenger on PNR 5D2AAD, traveling from Charlotte, NC to Rocky Mount, NC was removed from the train by local Police for not following instructions from the crew then becoming belligerent using foul language. Amtrak Police notified.

Delay: 80(03) 13"

Western Region
Operating Highlights

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Train 21/421(03) North of Poplar Bluff, MO - Air Hose Separation

03NOV26: Train 21/421(03), with engine 312, 8 cars, and 146 customers onboard, stopped after hitting a crossing at mile post 150.3, 15 miles north of Poplar Bluff, MO/MP165.6, on the UP Desoto subdivision. The equipment went into emergency. The conductor walked the train and reconnected a detached air hose. After restoring air pressure and completing a successful brake test, train 21/421(03) continued south.

Train	Delay	Comment
21/421(03)	20"	

Train 6(03) East of Elko, NV - Freight Train Interference

03NOV26: Train 6(03) with 127 customers was delayed on the UPRR Lakeside subdivision five miles east of Elko at RV 561 Hold Signal/MP 561.3 due to meeting ZG2LT-02.

Train	Delay	Comment
6(03)	37"	

Train 717(03) West of Stockton, CA - Signal

03NOV26: Train 717(03) with 68 customers was delayed on the BNSF Stockton subdivision starting one mile west of Stockton between West Stockton/MP 1122.2 and Holt/MP 1129.0 due to signal issues.

Train	Delay	Comment
717(03)	33"	
713(03)	25"	
715(03)	24"	
718(03)	23"	
719(03)	24"	

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Train 11(02) South of San Luis Obispo, CA - Debris

03NOV26: Train 11(02) with E164-30, nine cars and 139 customers was delayed 26 miles south of San Luis Obispo on the UPRR Santa Barbara subdivision due to striking debris that caused four broken pipes on the main reservoir tank of E/164, causing air issues, and unable to continue. E/164-30 were set up back to back. The train maintained head end power throughout the disruption. Due to the locomotives being back to back with no available wye within 130 miles the decision was made to shove back two miles to Guadalupe station where customer service sourced three alternate buses and train 11(02) was terminated at Guadalupe. A track inspector responded to the scene to inspect the tracks behind train 11(02) due to a track light appearing after they operated through the area. Once the tracks were released, the crew shoved back to Guadalupe station and held until the buses arrived at 1110PM-PT. The crew performed a calendar inspection on E/30 during their time at Guadalupe. Drummac, an Amtrak Road Foreman, an Amtrak Trainmaster, and a relief crew responded to Guadalupe.

Once the customers alighted to the buses, the crew set out E/164 on spur track #406 at Guadalupe/MP 273.5 where it was to be assessed and repaired by Amtrak mechanical. After the set out was complete, the crew continued to shove towards Los Angeles with E/30 leading at reduced speed. The UPRR loaned portable ditch lights for E/30 due to the atypical setup. At Los Angeles, the comet set with E/510 was worked up and dispatched to meet and rescue the deadhead equipment from 11(02) at Ellwood/MP 355.7 and return to Los Angeles.

WBS#: B.TR.100150.7323

Train	Delay	Comment
11(02)	Term GUA	

Train 392(03) South of Gilman, IL - Rough Track

03NOV26: Train 392(03), with 182 customers onboard, was delayed at North Paxton siding/MP100.7, 18.58 miles south of Gilman, IL/MP82.12, on the CN Chicago subdivision due to reports of rough track ahead at mile post 92.0. A CN track inspector responded. Once the tracks were clear for operation, train 392(03) continued north.

Train	Delay	Comment
Train 392(03)	45"	

BNSF Seattle Subdivision South of Seattle, WA - Commuter Train Interference

03NOV26: Trains were delayed on the BNSF Seattle subdivision just south of Seattle due to Sounder train 1522(03) striking a trespasser at MP 1.5. The trespasser strike was not a fatality. Local authorities responded to the scene for an investigation. Train 509(03) was held at Seattle station and train 518(03) was held two miles south of Seattle at Spokane Street/MP 2.1 for disposition. Once the scene was released, train movement continued.

Train	Delay	Comment
509(03)	1'32"	
518(03)	1'38"	

27-FOI-00137 00000009135 "UNCLASSIFIED" 1/10/2026

UPRR Niles Subdivision North of Oakland, CA - Police Related

03NOV26: Trains were delayed on the UPRR Niles subdivision due to a vehicle on the tracks one mile north of Oakland at King Street/MP 6.38. Train 718(03) was delayed between the maintenance facility and Oakland. Train 542(03) was held at Oakland station. Train 715(03) was terminated at Emeryville with customers accommodated on train 545(03). Once the vehicle was removed and the tracks were inspected, train movement continued.

Train	Delay	Comment
718(03)	12"	
542(03)	19"	
545(03)	03"	
715(03)	Term EMY	

Train 352(03) West of Jackson, MI - Passenger Train Interference

04NOV26: Train 352(03), with 165 customers onboard, was delayed at control point 75/MP75.7, 0.2 miles west of Jackson, MI/MP75.5, on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(03). Once the route was clear, train 355(03) continued east.

Train	Delay	Comment
352(03)	30"	

Train 3(02) Gallup, NM - Police Related

03NOV26: Train 3(02) with 150 customers was delayed on the BNSF Gallup subdivision at Gallup station due to meeting the police to remove an unruly customer.

Train	Delay	Comment
3(02)	40"	

Train 4(02) East of Albuquerque, NM - Commuter Train Interference

03NOV26: Train 4(02) with 128 customers was delayed on the NMRX Albuquerque subdivision starting one mile east of Albuquerque due to meeting NMRX 105 at Marquette/MP 902.06, NMRX 103 at East Alameda/MP 894.4, and NMRX 101 at East Bernalillo/MP 885.25.

Train	Delay	Comment
4(02)	43"	

Train 4(03) Los Angeles, CA - Initial Terminal Delay

03NOV26: Train 4(03) with E/48-205, nine cars, and 89 customers was delayed departing Los Angeles due to E/48 bad ordered for crank fault and replaced with E/19. Once the equipment was made up and released, the customers were welcomed aboard, and 4(03) departed Los Angeles at 703PM-PT, 2 hours, and 8 minutes late.

Train	Delay	Comment
4(03)	2'08"	

Train 3(03) East of Fort Madison, IA - Drawbridge Opening

03NOV26: Train 3(03), with 170 customers onboard, was delayed at the Mississippi River Bridge/MP231.8, 1 mile east of Fort Madison, IA/MP232.9, on the BNSF Chillicothe subdivision due to the bridge opening. Once the route was open, train 3(03) continued operation west.

27-FOI-00137 000000009135 UNCLASSIFIED 1/10/2026

Train 8/28(01) East of Tomah, WI - Passenger Train Interference

03NOV26: Train 8/28(01) with 115 customers delayed at Camp Douglas/MP224.1, 16 miles east of Tomah, WI, on the CPKC Tomah Subdivision, meeting Train 1333(03).

Train	Delay	Comment
8/28(01)	44"	

Train 353(03) East of Chicago, IL - M of W Work

03NOV26: Train 353(03), with 167 customers onboard, was delayed at control point 518/MP518.5, 1.6 miles east of Chicago Union Station, IL/MP0.0 on the NS Chicago Terminal subdivision due to a bridge strike at South Branch Bridge/MP1.54. Once the tracks were inspected and the bridge opened, train 353(03) continued into Chicago.

Train	Delay	Comment
353(03)	32"	

Train 4(01) East of Kansas City, MO - Freight Train Interference

03NOV26: Train 4(01) was delayed beginning 6 miles east of Kansas City, MO, on the BNSF Marceline Subdivision, following eastbound BNSF 6964 between Congo/MP444.3 and Mendon/MP349.3, and following another eastbound freight between MP263.4 Fort Madison, IA/MP234.2. BNSF reported multiple MW curfews on the Marceline Subdivision and limited meet/pass opportunities. Customers scheduled to connect with Train 50(03) detrained at Galesburg, IL and were bussed to Indianapolis, IN, to connect with Train 50(03). Customers scheduled to connect with Bus 8890(03) at Galesburg remained onboard to Chicago and were reaccommodated on Train 59(03) to Champaign, IL.

Train	Delay	Comment
4(01)	1'34"	E/KCY, follow BNSF 6964
4(01)	32"	DMW on Marceline sub

Train 318(03) East of Sedalia, MO - Trespasser Incident

03NOV26: 1043AM-CT Train 318(03), E/319 & 7 cars, with 98 customers, stopped in emergency at MP186.44, 2 miles east of Sedalia, MO, on the UPRR Sedalia Subdivision, due to a near miss with a trespasser. The trespasser was waking in the gauge on the bridge and jumped in the clear to the ground below as Train 318(03) was approaching. Local authorities responded to the scene. Once local authorities and Amtrak managers confirmed it was a near miss, UPRR RMCC and locals released the scene and Train 318(03) was back on the move east.

Train	Delay	Comment
318(03)	41"	

27-FOI-00137 000000009135 UNCLASSIFIED 11/10/2026

Train 383(02) West of Plano, IL - Alleged Wheel Defect

03NOV26: Train 383(02) with engines JDTX4605, 4 cars, and 19 customers onboard, stopped at mile post 53.1, 1.5 miles west of Plano, IL/MP51.7, on the BNSF Mendota subdivision due to the crew identifying possibly condemnable wheel defects on the second car, C/IDTX4314. The crew received permission from BNSF to shove back to Plano, IL. Train 383(02) was terminated at Plano, IL. Two buses were sourced for the customers. Chicago Mechanical forces arrived on the scene and declared the defects to be non-condemnable. The 383(02) equipment operated deadhead back to Chicago.

Train 380(03) was canceled in its entirety. There was no alternate transportation for customers at Quincy, IL or Macomb, IL. One bus was secured and operated between Galesburg, IL and Chicago, IL, making all scheduled stops.

WBS#: B.TR.100150.7322

Train	Delay	Comment
383(02)	Terminated PLO	
380(03)	Cancelled	

Train 821(03) South of Purcell, OK - Freight Train Interference

03NOV26: Train 821(03) was delayed south of Purcell, OK/MP517.1, on the BNSF Red Rock Subdivision, meeting BNSF 7152 at MP516.4 and BNSF 7165 at MP502.9.

Train	Delay	Comment
821(03)	39"	

Train 8/28(02) East of Essex, MT - Freight Train Interference

03NOV26: Train 8/28(02) was delayed at Summit (MP 1149.8) on the Burlington Northern Santa Fe Hi Line Subdivision, 19 miles east of the Essex, MT station, while meeting freight U-TIOTAO0-57 (BNSF 7209) and freight S-CHCTAC1-27 (BNSF 7340).

Train	Delay	Comment
8/28(02)	48"	

Train 8/28(01) St. Paul-Minneapolis, MN - Engine Failure

03NOV26: Train 8/28(01), E/206-E/306 & 10 cars, with 112 customers, was delayed at St. Paul-Minneapolis, MN/MP410.3, on the CPKC Merriam Park Subdivision, due to lead E/206 engineer side windshield wiper not operational. As a result, Train 8/28(01) was delayed flat switching engines to position E/306 lead and E/206 trail.

Train	Delay	Comment
8/28(01)	1'35"	

Train 522(03) Originated Emeryville, CA - Third Party Contractor Engine Failure

03NOV26: Train 522(03), operating with Cab Car C8312, 4 cars, and Locomotive JPBX920, originated at the Emeryville, CA station due to ground fault and ditch light issues on Locomotive JPBX920. The 3 customers scheduled to board at Oakland, CA Jack London Square Station were accommodated on Train 524(03).

Train	Delay	Comment
522(03)	1'10"	Orig EMY

27-FOI-00137 000000009135 "UNCLASSIFIED" 1/10/2026

Train 24(03) North of New Orleans, LA - Freight Train Interference

03NOV26: Train 24(03) with 97 customers, was delayed at MP799.5, 12 miles north of New Orleans, LA, on the CSX NO&M Subdivision, waiting on CSX M605-01 to clear into Gentilly yard ahead.

Train	Delay	Comment
24(03)	34"	

Train 8/28(01) West of Fargo, ND - Passenger Train Interference

03NOV26: Train 8/28(01), with 47 customers, was delayed at Bison/MP27.4, 4 miles west of Fargo, ND, on the BNSF Hillsboro Subdivision, meeting Train 7/27(02).

Train	Delay	Comment
8/28(01)	41"	

Train 11(02) South of Chico, CA - Broken Rail

03NOV26: Train 11(02) was held at Richvale (MP 167.2) on the Union Pacific Valley Subdivision, 17 miles south of the Chico, CA station, due to a broken rail at MP 161.1. A track crew responded and made temporary repairs to allow Train 11(02) to continue south.

Train	Delay	Comment
11(02)	2'00"	

Train 14(02) North of Chico, CA - Passenger Train Interference

03NOV26: Train 14(02) was delayed at Anita (MP 193.9) on the Union Pacific Valley Subdivision, 10 miles north of the Chico, CA station, while meeting Train 11(02).

Train	Delay	Comment
14(02)	30"	

UPRR Shafter Subdivision West of Salt Lake City, UT - M of W Work

03NOV26: Trains 6(02) and 5(01) were delayed on the UPRR Shafter subdivision due to an impassable broken rail 47 miles west of Salt Lake City at Delle/MP 822.49. MOW was unable to bar. The tracks were released at 4:30A-MST.

Train	Delay	Comment
6(02)	3'15"	
5(01)	2'20"	

Train 5(02) West of Denver, CO - Engine Failure

03NOV26: Train 5(02), E/188-E/69 & 8 cars, with 157 customers, was delayed at North yard/MP3, 3 miles west of Denver, CO, on the UPRR Moffat Tunnel Subdivision, adding UPRR E/UP7656 ahead due to enroute loading issues on lead E/188. After adding UP E/7656 ahead the crew reported issues logging into PTC. The PTC issue was attributed to a systemwide PTC outage that began at approximately 1136AM-ET/936AM-MT and was resolved at 1241PM-ET/1041AM-MT. Train 5(02), E/UP7656-E/188-E/69 & 8 cars was delayed enroute to Emeryville, CA, due to operating with the UPRR freight engine.

Train	Delay	Comment
5(02)	2'10"	W/DEN, MP3 add UPRR unit
5(02)	13"	W/DEN-CBI, op with freight eng

27-FOI-00137 000000009135 "UNCLASSIFIED" 11/10/2026

Train 5(01) West of Denver, CO - Engine Failure

02NOV26: Train 5(01) E/169-E/100 & 8 [illegible] with 170 customers, was delayed North Yard/MP3.0, 3 miles west of Denver, CO, on the UPRR Moffat Tunnel Subdivision, adding UPRR E/UP6851 ahead due to inbound loading issues on lead E/169. Train 5(01) was delayed enroute to Emeryville, CA, due to operating with the UPRR E/UP6851.

Train	Delay	Comment
5(01)	1'19"	W/DEN, add UP 6851 a/h
5(01)	1'28"	W/DEN-SLC, op with freight unit

NCTD San Diego Subdivision East of San Clemente Pier, CA - Signal Issues

31OCT26: Ongoing signal issues on the NCTD San Diego Subdivision due to high tides requires trains to flag between San Clemente Pier, CA and Oceanside, CA. The single-track conditions that exist also creates congestion through the area causing further delay to trains that operate through the area.

03NOV26: Train 572(03) and Train 579(03) were canceled due to the late arrival of inbound Train 567(03) which was operating 2 hours late from the train interference caused by the signal outage between San Clemete Pier and Oceanside.

The 79 customers scheduled for Train 572(03) were accommodated on Train 774(03).
The 89 customers scheduled for Train 579(03) were accommodated on Train 581(03).

Train	Delay	Comment

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

```
562(31)  32"
765(31)  17"
564(31)  52"
566(31)  45"
769(31)  54"
573(31)  28"
770(31)  47"
774(31)  58"
572(31)  14"
777(31)  15"
579(31)  46"
785(31)  14"
581(31)  1'02"
587(31)  49"
591(31)  50"
580(31)  11"
782(31)  46"
584(31)  1'14"
786(31)  24"
588(31)  21"
593(31)  1'06"
595(31)  1'02"
790(31)  11"
794(31)  24"
562(01)  22"
567(01)  32"
769(01)  47"
564(01)  59"
566(01)  1'13"
573(01)  27"
777(01)  22"
572(01)  21"
579(01)  47"
774(01)  41"
581(01)  1'02"
785(01)  26"
587(01)  48"
580(01)  22"
782(01)  52"
591(01)  51"
584(01)  1'15"
593(01)  1'03"
786(01)  13"
588(01)  1'04"
790(01)  12"
595(01)  1'01"
794(01)  17"
761(02)  17"
765(02)  12"
567(02)  13"
769(02)  22"
562(02)  12"
564(02)  33"
573(02)  19"
777(02)  21"
566(02)  43"
770(02)  15"
572(02)  16"
581(02)  16"
774(02)  11"
785(02)  22"
587(02)  16"
580(02)  11"
782(02)  12"
591(02)  22"
584(02)  21"
786(02)  11"
588(02)  38"
794(02)  17"
790(02)  12"
595(02)  1'38"  SAN Turn of Late Inbound 584(02) and Delay between SOL and SNC
593(02)  2'09"  SAN Turn Late Inbound 782(02) and Delay between SOL and SNC
761(03)  22"
567(03)  1'56"
765(03)  1'14"
562(03)  1'34"
```

Train	Delay	Comment
770(03)	50"	
573(03)	1'51"	SAN Late Inbound 562 and SOL to SNC Delays
777(03)	31"	
774(03)	36"	
581(03)	14"	
785(03)	16"	
587(03)	37"	
580(03)	13"	
782(03)	29"	
591(03)	18"	
584(03)	20"	
593(03)	13"	
595(03)	48"	
786(03)	16"	
588(03)	21"	
790(03)	16"	
794(03)	20"	

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

BNSF Gallup Subdivision East of Winslow, AZ- Southwest Chief Service Disruption

23OCT26: A severe storm with isolated showers and thunderstorms impacted the area between Gallup, NM and Albuquerque, NM bringing flash floods and reduced operating conditions. At 9:50A-PT, the BNSF reported flash floods on the Gallup Subdivision with confirmed water over the rails at MP 77.9, 80 miles east of Gallup, NM . Multiple freights were tied down with crews expired on hours of service between Laguna/MP 71.1 and Grants/MP 98.3 causing single tracking conditions over 100 miles. BNSF maintenance of way personnel responded to areas of potential water of the rails to inspect. Substantial delays were incurred operating through the affected area.

Train 4(22), with 159 customers on board, arrived into Winslow, AZ at 9:42A-PT and held for open track. While holding in Winslow, and in anticipation of further delay, the crew performed a calendar day inspection. Once a route was open, Train 4(22) proceeded east incurring further delay at MP 253.4, holding for the recrew to arrive and conduct a job briefing. Upon completion of their job briefing, Train 4(22) proceeded east.

Train 3(22) was also delayed operating through the affected area by high winds, flash floods, and freight meets.

24OCT26: Due to the late operation of Train 3(22), the crew expired on hours of service holding in Flagstaff, AZ. Train 3(22) held at Flagstaff with pilots on board beginning at 1:55A-PT for the recrew to arrive from Train 4(23), arriving at approximately 4:30A-PT. Once the recrew arrived and conducted their job briefing, Train 3(22) proceeded west.

To support customers and provide service recovery on Train 4(22), complimentary food and beverage offerings were provided. All coach customers received complimentary snack packs, bottled water, and hot beverages. During lunch service, sleeping car customers received the regular lunch service in the Dining Car, while coach customers were provided complimentary beef stew, mashed potatoes, and beverages. During dinner service, sleeping car customers received the regular dinner service in the Dining Car, while coach customers were provided complimentary Salisbury steak, vegetables, and mashed potatoes.

Train 4(22) had five misconnections at Kansas City, MO to Train 318(24) that were provided an alternate bus to their final destination. Train 6(22) also provided aid to local customers on Train 4(22) that were boarding between Galesburg and Chicago.

24OCT26: Train 3(23), operating with engines 79/29, 9 coaches, and 153 customers, was stopped east of the Gallup, NM station due to severe weather resulting in water above the rail in multiple locations. Burlington Northern Santa Fe subsequently reported that there was no route available beyond Laguna (MP 71) due to flooding of the tracks and the adjacent highway. Reported flood damage included both main tracks under water with debris between MP 72.7 and MP 72.3, including approximately 800 feet of side scour on the Main Track 1 side; side scour and undercutting at a culvert near MP 72.4; water over a high-water detector bridge and both rails between MP 70.1 and MP 69.8; and water over both rails between MP 69.8 and MP 69.7, where inspection was not possible. As a result, Train 3(23) shoved back to Albuquerque, NM and arrived at 11:57P-MT. The train wye'd en

- Train 3(23) arrived at Albuquerque, NM at 11:57P-MT, wyed enroute into the station, and operated back to Chicago, IL, returning customers to points of origination.
- Train 4(24), with 135 customers, wyed at Barstow, CA and operated back to Los Angeles, CA Union Sta27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026
- Train 3(24), with 136 customers, reversed back to Kansas City, MO, wyed, and planned to return to its origin.
Due to crew availability in Kansas City, Train 3(24) held in Kansas City for the arrival of Train 4(23) and was coupled to operate as a combo set to Chicago, returning Train 3(24) customers to points of origination.
- Train 4(25) was canceled. No alternate transportation was provided.

25OCT26: Train 3(23) departed Albuquerque, NM, at 125AM-MT operating eastward back to Chicago. Train 3(23) was delayed at Fox/MP820.0, 15 miles east of Lamy, NM, on the BNSF Glorieta Subdivision, after operating through code line failure at E. Fox, the crew reported while operating through the switch, with it on hand, the switch handle popped up as train started into the switch. Train 3(23) was delayed due to possible switch damage and due to holding for a required recrew to arrive.

As of 700AM-CT on Sunday October 25th, BNSF reported still no estimate for open track. Due to the ongoing issues on the BNSF Gallup Subdivision, additional Southwest Chief service adjustments were necessary:
- Train 3(25) terminated in Kansas City, MO. No alternate transportation between Kansas City and Los Angeles.
- Train 4(25) was reinstated between Kansas City and Chicago only. Train 4(25) originated in Kansas City with no alternate transportation between Los Angeles and Kansas City.
- Train 4(27) cancelled entirely. No alternate transportation between Los Angeles and Chicago.

26OCT26: BNSF reported current weather conditions and further soil and ground degradation and scouring have delayed necessary repairs and pushed back track opening. Main Track 1 estimated back 300PM-MT Monday October 26th and No 2 estimated back at 1201AM-MT Tuesday October 27th. Due to the ongoing issues on the BNSF Gallup subdivision the following additional service adjustments were necessary:
- Train 3(26) cancelled entirely, no alternate transportation between Chicago and Los Angeles.
- Train 4(26) cancelled entirely, no alternate transportation between Los Angeles and Chicago.
BNSF advised an extremely large volume of freight traffic has been holding for open route and expect it to be heavily congested across the subdivision upon track opening.

27OCT26: A revised Main Track 1 estimate has been changed to "pending" due to a new washout that was identified at Milepost 50.2, with approximately 500 feet of side scour (erosion of the soil, rock, or ballast along the side of the railroad embankment (roadbed) caused by flowing water). Repair efforts are underway, with a ballast train placing material. Main Track Two between Laguna and Marmon is expected to reopen at 12:01 AM CT on the 27th under a 10 MPH speed restriction. BNSF has advised there are still a significant amount of Freight Trains tied down which will cause significant congestion through the area. Restoration efforts remain fluid due to changing water levels along the right-of-way.

- Train 3 (27) canceled in its entirety between Chicago and Los Angeles. No alternate transportation will be provided.
- Train 4(28) cancelled entirely, no alternate transportation between Los Angeles and Chicago.

29OCT26: Trains 3 and 4 continued to see heavy delays in the area due to ongoing repairs and congestion. BNSF advised to expect delays between 2 to 4 hours to continue over the next several days.

01NOV26: Trains 3(30) and 4(31) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.

02NOV26: Trains 3(31) and 4(01) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.

03NOV26: Trains 3(01) and 4(02) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.
Weather conditions were favorable. The Gallup Subdivision remains open, with one main closed for stabilization work. There were 31 trains on the subdivision. Due to continued late operations and staffing issues, trains 3(04) and 4(04) were cancelled entirely with no alternate transportation.

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

WBS#: B.TR.100150.7301

Train	Delay	Comment
4(22)	1'32"	Hold WLO
4(22)	5'09"	Meeting multiple freights due to weather
3(22)	1'30"	High winds and flash floods
3(22)	2'43"	meeting multiple freights due to weather
3(22)	2'59"	FLG, recrew
4(25)	Originated KCY	
3(23)	Terminated ABQ	Returned to origin
3(24)	Terminated KCY	Returned to origin
4(24)	Terminated BAR	Returned to origin
3(25)	Terminated KCY	
4(27)	Cancelled	
3(23)	5'18"	E/LMY, switch issue/recrew
3(26)	Cancelled	
4(26)	Cancelled	
3(27)	Cancelled	
4(28)	Cancelled	
4(29)	47"	BAR-NDL Congestion
3(28)	1'07"	ABQ-KNG Congestion
4(29)	1'20"	GLP-XIA
3(29)	4'44"	ABQ-GLP
3(29)	44"	WLO-FLG Congestion
4(30)	32"	KNG-FLG Congestion
4(30)	51"	FLG-WLO Congestion
4(31)	2'44"	NDL to ABQ
3(30)	8'45"	ABQ to BAR
3(31)	8'08"	ABQ-BAR
4(01)	3'30"	BAR to ABQ
3(01)	7'23"	ABQ to BAR
4(02)	4'52"	BAR to GLP
3(02)	20"	ABQ-KNG
3(04)	Canceled	
4(04)	Canceled	
4(03)	1'06"	VRV-BAR

UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

16OCT26: The UPRR placed engineering orders in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected area due to signal issues where crews operated at restricted speed and stopped to flag crossings.

17OCT26: In order to minimize customer delays due to this, the following Service Adjustments were implemented:

Train 761(17) and 765(17) were originated at Los Angeles, CA, no alternate transportation provided.
Trains 757/ 765/ 777(17-01NOV) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-01NOV) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

23OCT26: The operating plan was extended through at least Sunday November 1.

30OCT26: The operating plan was extended to Friday November 6th.

WBS#: B.TR.100150.7278

Train	Delay	Comment
774(16)	1'39"	
757(16)	1'34"	
786(16)	1'35"	ITD SLO- Turn of 757(16)
786(16)	1'35"	ITD SLO- Equip off 757
765(16)	1'22"	
794(16)	38"	ITD SLO- Equip off 765
794(16)	2'08"	
14(16)	2'21"	
786(16)	2'57"	
11(15)	1'23"	
14(17)	1'13"	
11(16)	1'51"	
11(17)	1'15"	
14(18)	1'19"	
14(19)	1'01"	
11(18)	1'08"	
11(19)	1'10"	
14(20)	1'40"	
11(19)	51"	waiting for & meeting 14(20) at Tangair
14(21)	40"	
11(20)	1'05"	meet 14(21)
11(20)	1'14"	
11(21)	1'02"	
14(22)	59"	
11(22)	1'51"	
14(23)	1'03"	
782(23)	48"	
14(24)	1'03"	
11(25)	1'52"	
14(27)	1'31"	
11(26)	1'29"	
11(28)	1'11"	
14(28)	1'07"	
14(29)	45"	
11(29)	1'00"	
14(31)	1'02"	
11(30)	1'21"	
14(01)	1'24"	
11(31)	1'05"	
14(02)	1'00"	
11(01)	1'15"	
14(03)	51"	

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

27-FOI-00137 00000008135 "UNCLASSIFIED" 11/10/2026

29SEP26: Train 821(29) was delayed beginning the 2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	
821(07)	35"	
822(08)	32"	
821(09)	32"	
822(09)	36"	
822(10)	23"	
822(11)	41"	
822(12)	48"	
821(12)	21"	
821(13)	22"	
822(13)	36"	
821(14)	35"	
822(14)	17"	
821(15)	26"	
821(16)	41"	
822(15)	34"	
822(16)	19"	
821(17)	24"	
821(19)	39"	
822(19)	22"	
821(20)	29"	
822(20)	32"	
821(21)	46"	
821(22)	32"	
822(21)	19"	
822(22)	30"	
821(23)	42"	
822(23)	23"	
821(24)	21"	
822(24)	22"	
821(25)	34"	
822(25)	43"	
821(26)	52"	
822(27)	34"	
822(26)	21"	
821(28)	30"	
822(28)	31"	
821(29)	23"	
822(29)	33"	
821(30)	33"	
822(30)	22"	
821(31)	20"	
822(31)	25"	
822(01)	30"	

Maintenance of Way Highlights

27FOI00127 00000009135 "UNCLASSIFIED" 11102026

UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Scheduled M/W Work TWA 27-020

26OCT26:To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 1(31Oct, 7Nov, 14Nov) and Train 42(30Oct, 6Nov, 13Nov) will detour over the BNSF San Bernardino Subdivision between West Colton(UPRR Alhambra subdivision) and Soto(BNSF San Bernardino subdivision), bypassing Ontario, CA (ONA) and Pomona, CA (POS). Train 801(2Nov, 9Nov, 16Nov) was created for the detour between Riverside, CA (RIV) and Los Angeles, CA (LAX).

Train 2/422(1Nov, 8Nov, 15Nov) will detour over the BNSF San Bernardino Subdivision between Soto(BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(1Nov, 8Nov, 15Nov) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV). An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision. No alternate transportation will be provided to POS and ONA.

WBS#: B.TR.100150.7307

Train	Delay	Comment
2/422(01)	39"	
1(31)/421(30)	44"	

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
11(2)	GUA	164		Main res

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5(1)	DEN	UP6851	E/169 loading issues	OKJ	11/4/26
5(2)	DEN	UP7656	E/188 loading issues		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 22(02) Passenger Removal at Summit, Illinois – Service Animal

03NOV26, Passenger on PNR 5B472F, traveling from San Antonio, TX to Chicago, IL was removed by local police due to the service animal not being under control. Passenger left dog unattended multiple times and dog was running around in sleeper car. Passenger was warned, but same behavior continued resulting in removal. Amtrak Police notified.

Delay: 22(02) 11″

Consist Deviations

27-FOI-00137 00000009135 "UNCLASSIFIED" 11/10/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)

Reverse Consists

Train Number	Station	Reason
1164 (03)	NPN	Consist reversed | Business class seat orientation may have changed | At Front
1195 (03)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1135 (03)	BOS	Consist reversed | Business class seat orientation may have changed | At Front