# CNOC

## (CONSOLIDATED NATIONAL OPERATIONS CENTER)

# Amtrak Status Report

Thursday, November 05, 2026 Rules: 0-4




*This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.*

## Information Management

27-FOI-00137 [illegible]

# Initial Terminal Performance By Division

Scheduled Departure Date: **11/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/04/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 308 | 49 | 84.1% | 1,210 | 162 | 86.6% | 10,684 | 1,514 | 85.8% |
| Central Division | 86.0% | 58 | 1 | 98.3% | 231 | 10 | 95.7% | 2,001 | 135 | 93.3% |
| East Division | 82.0% | 160 | 31 | 80.6% | 620 | 82 | 86.8% | 5,619 | 820 | 85.4% |
| West Division | 86.0% | 90 | 17 | 81.1% | 359 | 70 | 80.5% | 3,064 | 559 | 81.8% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

## Information Management

# Customer On Time Performance

Endpoint Arrival Dates through 11/4/26

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

| Service | Target | Day | | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score |
| **Amtrak System** | **76%** | **80,250** | **35,983** | **55%** | **366,564** | **111,446** | **70%** | **3,515,642** | **1,011,576** | **71%** |
| ***Northeast Corridor*** | ***78%*** | ***37,111*** | ***20,879*** | ***44%*** | ***156,228*** | ***45,741*** | ***71%*** | ***1,511,233*** | ***370,381*** | ***75%*** |
| Acela | 80% | 6,378 | 3,930 | 38% | 22,827 | 7,399 | 68% | 260,151 | 53,881 | 79% |
| Northeast Regional | 78% | 30,733 | 16,949 | 45% | 133,401 | 38,342 | 71% | 1,251,082 | 316,500 | 75% |
| Richmond / Newport News / Norfolk | 75% | 7,092 | 3,667 | 48% | 32,907 | 10,197 | 69% | 303,764 | 84,421 | 72% |
| Springfield Shuttles | 89% | 631 | 194 | 69% | 2,828 | 251 | 91% | 25,831 | 5,091 | 80% |
| Roanoke | 75% | 2,492 | 1,455 | 42% | 11,518 | 3,950 | 66% | 109,167 | 32,338 | 70% |
| On Spine Northeast Regional | 80% | 20,518 | 11,633 | 43% | 86,148 | 23,944 | 72% | 812,320 | 194,650 | 76% |
| ***State Supported*** | ***80%*** | ***33,387*** | ***8,864*** | ***73%*** | ***164,850*** | ***44,013*** | ***73%*** | ***1,588,975*** | ***452,296*** | ***72%*** |
| Borealis | 80% | 431 | 227 | 47% | 2,411 | 477 | 80% | 24,680 | 4,776 | 81% |
| Capitol Corridor | 90% | 3,998 | 113 | 97% | 15,845 | 2,391 | 85% | 144,528 | 27,155 | 81% |
| Carolinian | 70% | 1,088 | 805 | 26% | 5,578 | 2,155 | 61% | 46,196 | 15,802 | 66% |
| Cascades | 75% | 1,609 | 864 | 46% | 10,164 | 3,344 | 67% | 98,331 | 29,464 | 70% |
| Downeaster | 82% | 875 | 135 | 85% | 4,979 | 1,195 | 76% | 62,445 | 14,877 | 76% |
| Empire | 78% | 4,883 | 487 | 90% | 22,268 | 3,882 | 83% | 220,164 | 51,009 | 77% |
| Adirondack | 72% | 229 | 6 | 97% | 1,215 | 10 | 99% | 14,162 | 2,081 | 85% |
| Ethan Allen Express | 70% | 399 | 0 | 100% | 1,990 | 884 | 56% | 20,467 | 7,909 | 61% |
| Maple Leaf | 70% | 600 | 223 | 63% | 2,990 | 1,060 | 65% | 30,096 | 9,558 | 68% |
| New York - Albany | 85% | 2,652 | 29 | 99% | 11,096 | 1,288 | 88% | 106,709 | 18,972 | 82% |
| New York - Niagara Falls | 75% | 1,003 | 229 | 77% | 4,977 | 640 | 87% | 48,730 | 12,489 | 74% |
| Gold Runner | 73% | 1,401 | 1,095 | 22% | 9,940 | 3,682 | 63% | 90,489 | 34,394 | 62% |
| Heartland Flyer | 70% | 102 | 52 | 49% | 584 | 521 | 11% | 6,827 | 5,742 | 16% |
| Hiawatha | 90% | 1,449 | 383 | 74% | 6,313 | 694 | 89% | 64,683 | 6,454 | 90% |
| Illinois | 78% | 1,701 | 271 | 84% | 9,917 | 1,167 | 88% | 95,430 | 28,544 | 70% |
| Carl Sandburg / Illinois Zephyr | 85% | 267 | 57 | 79% | 1,221 | 111 | 91% | 14,746 | 3,622 | 75% |
| Illini / Saluki | 85% | 649 | 23 | 96% | 3,768 | 242 | 94% | 32,769 | 12,155 | 63% |
| Lincoln Service | 70% | 785 | 191 | 76% | 4,928 | 814 | 83% | 47,915 | 12,767 | 73% |
| Keystone | 92% | 5,931 | 0 | 100% | 23,581 | 1,471 | 94% | 236,512 | 23,157 | 90% |
| Lincoln / Missouri | 70% | 620 | 403 | 35% | 3,154 | 2,056 | 35% | 30,112 | 15,045 | 50% |
| Mardi Gras Service | 80% | 213 | 8 | 96% | 1,134 | 117 | 90% | 10,486 | 2,722 | 74% |
| Michigan | 70% | 1,434 | 582 | 59% | 7,295 | 2,034 | 72% | 73,378 | 18,899 | 74% |
| Blue Water | 70% | 288 | 157 | 45% | 1,741 | 354 | 80% | 18,868 | 5,185 | 73% |
| Pere Marquette | 85% | 199 | 0 | 100% | 1,015 | 0 | 100% | 10,314 | 623 | 94% |
| Wolverine | 70% | 947 | 425 | 55% | 4,539 | 1,680 | 63% | 44,196 | 13,091 | 70% |
| Missouri | 80% | 121 | 49 | 60% | 846 | 316 | 63% | 9,800 | 2,048 | 79% |
| Pacific Surfliner | 85% | 4,682 | 2,779 | 41% | 27,007 | 15,963 | 41% | 244,184 | 134,756 | 45% |
| Pennsylvanian | 80% | 844 | 228 | 73% | 3,691 | 563 | 85% | 32,894 | 9,813 | 70% |
| Piedmont | 80% | 593 | 383 | 35% | 4,081 | 1,782 | 56% | 43,487 | 13,829 | 68% |
| Vermonter | 75% | 1,412 | 0 | 100% | 6,062 | 203 | 97% | 54,349 | 13,810 | 75% |
| ***Long Distance*** | ***58%*** | ***9,752*** | ***6,240*** | ***36%*** | ***45,486*** | ***21,692*** | ***52%*** | ***415,434*** | ***188,899*** | ***55%*** |
| Auto Train | 70% | 703 | 703 | 0% | 2,996 | 2,442 | 18% | 23,954 | 17,881 | 25% |
| California Zephyr | 70% | 693 | 563 | 19% | 3,317 | 1,625 | 51% | 32,557 | 10,112 | 69% |
| Cardinal | 70% | 237 | 174 | 27% | 830 | 243 | 71% | 7,626 | 3,396 | 55% |
| City Of New Orleans | 75% | 517 | 224 | 57% | 2,659 | 422 | 84% | 26,007 | 16,720 | 36% |
| Coast Starlight | 70% | 895 | 470 | 47% | 3,824 | 2,191 | 43% | 37,887 | 20,898 | 45% |
| Crescent | 70% | 748 | 310 | 59% | 3,734 | 710 | 81% | 33,792 | 5,510 | 84% |
| Empire Builder | 70% | 726 | 32 | 96% | 3,454 | 795 | 77% | 35,685 | 12,806 | 64% |
| Floridian | 60% | 1,413 | 1,292 | 9% | 6,647 | 4,969 | 25% | 49,638 | 29,169 | 41% |
| Lake Shore Ltd | 73% | 810 | 331 | 59% | 3,787 | 782 | 79% | 36,628 | 11,092 | 70% |
| Palmetto | 70% | 979 | 660 | 33% | 3,454 | 1,508 | 56% | 27,207 | 7,611 | 72% |
| Silver Meteor | 70% | 856 | 845 | 1% | 3,926 | 2,640 | 33% | 36,666 | 13,015 | 65% |
| Southwest Chief | 60% | 669 | 579 | 13% | 2,856 | 2,320 | 19% | 26,728 | 20,745 | 22% |
| Sunset Ltd | 70% | 294 | 32 | 89% | 1,124 | 338 | 70% | 10,010 | 4,595 | 54% |
| Texas Eagle | 70% | 212 | 25 | 88% | 2,878 | 707 | 75% | 31,049 | 15,349 | 51% |

**Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"**

# Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00187 000000000184 "UNCLASSIFIED" 11/10/2026~~

## Train Index Dates Through November 04, 2026

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Service** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| Amtrak System | 585 | 22,829 | 405,846 | 563 | 210,519 | 3,495,429 | 602 |

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Department** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| INFRASTRUCTURE UNPLANNED | 107 | 505 | 105,815 | 48 | 10,080 | 977,531 | 103 |
| INFRASTRUCTURE PLANNED | 135 | 2,408 | 105,815 | 228 | 22,375 | 977,531 | 229 |
| FLEET RELIABILITY | 90 | 3,294 | 405,846 | 81 | 29,792 | 3,495,429 | 85 |
| TRAIN OPERATIONS | 424 | 16,622 | 405,846 | 410 | 148,272 | 3,495,429 | 424 |

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

## Information Management

27-FOI-00137 [illegible]

# Initial Terminal Performance By Division

Scheduled Departure Date: **11/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/04/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 308 | 49 | 84.1% | 1,210 | 162 | 86.6% | 10,684 | 1,514 | 85.8% |
| Central Division | 86.0% | 58 | 1 | 98.3% | 231 | 10 | 95.7% | 2,001 | 135 | 93.3% |
| East Division | 82.0% | 160 | 31 | 80.6% | 620 | 82 | 86.8% | 5,619 | 820 | 85.4% |
| West Division | 86.0% | 90 | 17 | 81.1% | 359 | 70 | 80.5% | 3,064 | 559 | 81.8% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/04/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 308 | 49 | 84.1% | 1,210 | 162 | 86.6% | 10,684 | 1,514 | 85.8% |
| Central Division | 86.0% | 58 | 1 | 98.3% | 231 | 10 | 95.7% | 2,001 | 135 | 93.3% |
| CDL | 95.0% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 49 | 3 | 93.9% |
| CHI | 86.0% | 26 | 1 | 96.2% | 107 | 6 | 94.4% | 937 | 74 | 92.1% |
| CHM | - | - | - | - | - | - | - | 20 | 3 | 85.0% |
| DAL | - | - | - | - | - | - | - | 2 | 0 | 100.0% |
| DET | - | - | - | - | - | - | - | 1 | 1 | 0.0% |
| FTW | 92.5% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 32 | 2 | 93.8% |
| GRR | 95.5% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 0 | 100.0% |
| IND | - | - | - | - | - | - | - | 4 | 0 | 100.0% |
| KCY | 92.0% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 71 | 1 | 98.6% |
| MKE | 92.0% | 6 | 0 | 100.0% | 23 | 1 | 95.7% | 204 | 13 | 93.6% |
| MOE | 97.5% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 63 | 0 | 100.0% |
| MSP | 96.5% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 0 | 100.0% |
| NOL | 94.5% | 5 | 0 | 100.0% | 18 | 0 | 100.0% | 144 | 6 | 95.8% |
| OKC | 97.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 34 | 2 | 94.1% |
| PNT | 88.0% | 3 | 0 | 100.0% | 12 | 1 | 91.7% | 92 | 13 | 85.9% |
| PTH | 93.0% | 1 | 0 | 100.0% | 4 | 1 | 75.0% | 35 | 2 | 94.3% |
| QCY | 91.0% | 2 | 0 | 100.0% | 7 | 0 | 100.0% | 69 | 4 | 94.2% |
| SAS | 90.5% | 1 | 0 | 100.0% | 4 | 1 | 75.0% | 34 | 7 | 79.4% |
| STL | 89.0% | 4 | 0 | 100.0% | 16 | 0 | 100.0% | 139 | 3 | 97.8% |
| TAY | - | - | - | - | - | - | - | 1 | 1 | 0.0% |
| East Division | 82.0% | 160 | 31 | 80.6% | 620 | 82 | 86.8% | 5,619 | 820 | 85.4% |
| ALB | 88.5% | 8 | 0 | 100.0% | 32 | 2 | 93.8% | 277 | 22 | 92.1% |
| ALX | - | - | - | - | - | - | - | 27 | 14 | 48.1% |
| ATL | - | - | - | - | - | - | - | 14 | 4 | 71.4% |
| BON | 87.5% | 5 | 2 | 60.0% | 20 | 3 | 85.0% | 175 | 15 | 91.4% |
| BOS | 85.5% | 12 | 3 | 75.0% | 43 | 6 | 86.0% | 436 | 28 | 93.6% |
| BRK | 92.5% | 5 | 0 | 100.0% | 20 | 1 | 95.0% | 175 | 14 | 92.0% |
| BTN | 82.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 5 | 85.7% |
| CLT | 91.5% | 5 | 1 | 80.0% | 20 | 1 | 95.0% | 169 | 21 | 87.6% |
| GFD | 88.0% | 2 | 1 | 50.0% | 8 | 1 | 87.5% | 70 | 7 | 90.0% |
| GRO | - | 1 | 0 | 100.0% | 5 | 1 | 80.0% | 16 | 1 | 93.8% |
| HAR | 79.5% | 13 | 1 | 92.3% | 47 | 5 | 89.4% | 402 | 44 | 89.1% |
| HFD | - | - | - | - | - | - | - | 44 | 9 | 79.5% |
| JAX | - | - | - | - | - | - | - | 18 | 2 | 88.9% |
| LOR | 84.0% | 1 | 1 | 0.0% | 4 | 3 | 25.0% | 33 | 15 | 54.5% |
| MET | - | - | - | - | - | - | - | 1 | 1 | 0.0% |
| MIA | 89.5% | 2 | 1 | 50.0% | 8 | 3 | 62.5% | 69 | 11 | 84.1% |
| MTR | 79.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 9 | 74.3% |
| NFK | 84.5% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 59 | 10 | 83.1% |
| NFL | 93.5% | 2 | 1 | 50.0% | 8 | 1 | 87.5% | 70 | 6 | 91.4% |
| NFS | - | - | - | - | - | - | - | 3 | 3 | 0.0% |
| NHV | 78.0% | 6 | 1 | 83.3% | 24 | 3 | 87.5% | 181 | 36 | 80.1% |
| NPN | 93.0% | 2 | 0 | 100.0% | 8 | 1 | 87.5% | 48 | 5 | 89.6% |

## Information Management

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **11/04/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 11/04/2026 | | | ITP November 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 308 | 49 | 84.1% | 1,210 | 162 | 86.6% | 10,684 | 1,514 | 85.8% |
| East Division | 82.0% | 160 | 31 | 80.6% | 620 | 82 | 86.8% | 5,619 | 820 | 85.4% |
| NYP | 75.5% | 40 | 10 | 75.0% | 159 | 20 | 87.4% | 1,457 | 238 | 83.7% |
| PGH | 93.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 43 | 10 | 76.7% |
| PHL | 48.0% | 11 | 5 | 54.5% | 39 | 20 | 48.7% | 287 | 136 | 52.6% |
| RGH | 95.0% | 3 | 0 | 100.0% | 11 | 1 | 90.9% | 137 | 22 | 83.9% |
| RNK | 83.5% | 2 | 0 | 100.0% | 8 | 1 | 87.5% | 59 | 7 | 88.1% |
| SAB | 98.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 0 | 100.0% |
| SAV | 96.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 24 | 0 | 100.0% |
| SFA | 88.0% | 1 | 1 | 0.0% | 4 | 3 | 25.0% | 33 | 8 | 75.8% |
| SPG | 92.5% | 7 | 0 | 100.0% | 28 | 0 | 100.0% | 196 | 10 | 94.9% |
| TWO | 73.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 32 | 8 | 75.0% |
| WAS | 84.0% | 24 | 3 | 87.5% | 92 | 6 | 93.5% | 959 | 99 | 89.7% |
| West Division | 86.0% | 90 | 17 | 81.1% | 359 | 70 | 80.5% | 3,064 | 559 | 81.8% |
| ARN | 92.0% | 1 | 1 | 0.0% | 4 | 1 | 75.0% | 35 | 4 | 88.6% |
| BFD | 79.0% | 7 | 4 | 42.9% | 28 | 10 | 64.3% | 237 | 62 | 73.8% |
| EMY | 72.0% | 1 | 0 | 100.0% | 4 | 1 | 75.0% | 39 | 16 | 59.0% |
| EUG | 86.5% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 67 | 3 | 95.5% |
| FNO | - | - | - | - | - | - | - | 5 | 4 | 20.0% |
| GAC | - | - | - | - | - | - | - | 3 | 2 | 33.3% |
| GTA | 90.0% | 6 | 1 | 83.3% | 24 | 7 | 70.8% | 155 | 62 | 60.0% |
| IRV | - | - | - | - | - | - | - | 1 | 0 | 100.0% |
| LAX | 89.5% | 10 | 2 | 80.0% | 41 | 10 | 75.6% | 341 | 44 | 87.1% |
| OKJ | 74.5% | 13 | 3 | 76.9% | 48 | 12 | 75.0% | 411 | 127 | 69.1% |
| PDX | 86.0% | 4 | 0 | 100.0% | 19 | 2 | 89.5% | 174 | 15 | 91.4% |
| SAC | 88.5% | 16 | 0 | 100.0% | 60 | 4 | 93.3% | 516 | 48 | 90.7% |
| SAN | 90.5% | 12 | 3 | 75.0% | 51 | 16 | 68.6% | 410 | 91 | 77.8% |
| SEA | 85.0% | 8 | 1 | 87.5% | 32 | 3 | 90.6% | 279 | 32 | 88.5% |
| SJC | 89.0% | 7 | 2 | 71.4% | 28 | 4 | 85.7% | 244 | 39 | 84.0% |
| SLO | 90.0% | - | - | - | - | - | - | 42 | 8 | 81.0% |
| SPK | 90.0% | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 34 | 0 | 100.0% |
| VAC | 97.0% | 2 | 0 | 100.0% | 8 | 0 | 100.0% | 66 | 1 | 98.5% |
| VNC | - | - | - | - | - | - | - | 5 | 1 | 80.0% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

# Amtrak On Time Performance

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 1 | | 2 | 0 | 100.0% | 15 | 3 | 80.0% | 2 | 0 | 100.0% | 15 | 6 | 60.0% |
| 3 | 54 | 3 | 0 | 100.0% | 32 | 6 | 81.3% | 4 | 4 | 0.0% | 31 | 23 | 25.8% |
| 4 | 356 | 3 | 2 | 33.3% | 31 | 5 | 83.9% | 4 | 4 | 0.0% | 31 | 27 | 12.9% |
| 5 | 213 | 4 | 0 | 100.0% | 34 | 2 | 94.1% | 4 | 2 | 50.0% | 34 | 10 | 70.6% |
| 6 | 107 | 4 | 1 | 75.0% | 34 | 14 | 58.8% | 4 | 3 | 25.0% | 34 | 12 | 64.7% |
| 7 | | 4 | 1 | 75.0% | 34 | 3 | 91.2% | 4 | 0 | 100.0% | 34 | 2 | 94.1% |
| 8 | | 4 | 0 | 100.0% | 34 | 7 | 79.4% | 4 | 1 | 75.0% | 34 | 17 | 50.0% |
| 11 | 48 | 4 | 1 | 75.0% | 35 | 5 | 85.7% | 3 | 3 | 0.0% | 34 | 23 | 32.4% |
| 14 | 22 | 4 | 1 | 75.0% | 35 | 10 | 71.4% | 4 | 3 | 25.0% | 35 | 22 | 37.1% |
| 19 | 26 | 4 | 1 | 75.0% | 35 | 7 | 80.0% | 4 | 2 | 50.0% | 34 | 8 | 76.5% |
| 20 | | 4 | 0 | 100.0% | 35 | 3 | 91.4% | 4 | 0 | 100.0% | 35 | 4 | 88.6% |
| 21 | 94 | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 1 | 75.0% | 34 | 14 | 58.8% |
| 22 | | 4 | 1 | 75.0% | 35 | 8 | 77.1% | 4 | 1 | 75.0% | 35 | 19 | 45.7% |
| 23 | | 4 | 0 | 100.0% | 32 | 0 | 100.0% | 4 | 0 | 100.0% | 32 | 6 | 81.3% |
| 24 | | 4 | 0 | 100.0% | 31 | 0 | 100.0% | 4 | 0 | 100.0% | 31 | 6 | 80.6% |
| 25 | | 4 | 0 | 100.0% | 31 | 0 | 100.0% | 4 | 0 | 100.0% | 31 | 7 | 77.4% |
| 26 | | 4 | 0 | 100.0% | 32 | 0 | 100.0% | 4 | 1 | 75.0% | 32 | 9 | 71.9% |
| 27 | Cncld | 4 | 2 | 50.0% | 34 | 2 | 94.1% | 3 | 0 | 100.0% | 33 | 6 | 81.8% |
| 28 | | 3 | 0 | 100.0% | 33 | 4 | 87.9% | 4 | 0 | 100.0% | 34 | 6 | 82.4% |
| 40 | 50 | 4 | 2 | 50.0% | 35 | 12 | 65.7% | 4 | 4 | 0.0% | 35 | 18 | 48.6% |
| 41 | 60 | 4 | 2 | 50.0% | 35 | 5 | 85.7% | 4 | 4 | 0.0% | 35 | 19 | 45.7% |
| 42 | | 4 | 0 | 100.0% | 35 | 3 | 91.4% | 4 | 1 | 75.0% | 35 | 12 | 65.7% |
| 43 | 26 | 4 | 1 | 75.0% | 35 | 9 | 74.3% | 4 | 1 | 75.0% | 34 | 13 | 61.8% |
| 48 | | 4 | 0 | 100.0% | 35 | 4 | 88.6% | 4 | 1 | 75.0% | 35 | 13 | 62.9% |
| 49 | 183 | 4 | 0 | 100.0% | 35 | 5 | 85.7% | 4 | 1 | 75.0% | 35 | 7 | 80.0% |
| 50 | 28 | 1 | 0 | 100.0% | 15 | 0 | 100.0% | 2 | 1 | 50.0% | 15 | 7 | 53.3% |
| 52 | 278 | 4 | 3 | 25.0% | 33 | 8 | 75.8% | 4 | 2 | 50.0% | 33 | 18 | 45.5% |
| 53 | 150 | 4 | 3 | 25.0% | 33 | 15 | 54.5% | 4 | 4 | 0.0% | 33 | 29 | 12.1% |
| 55 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 0 | 100.0% | 25 | 5 | 80.0% |
| 56 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 1 | 66.7% | 25 | 5 | 80.0% |
| 58 | 17 | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 1 | 75.0% | 35 | 27 | 22.9% |
| 59 | | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 0 | 100.0% | 35 | 22 | 37.1% |
| 63 | 32 | 4 | 1 | 75.0% | 35 | 13 | 62.9% | 4 | 4 | 0.0% | 35 | 32 | 8.6% |
| 64 | 26 | 4 | 0 | 100.0% | 35 | 11 | 68.6% | 4 | 3 | 25.0% | 35 | 19 | 45.7% |
| 66 | | 4 | 1 | 75.0% | 34 | 5 | 85.3% | 4 | 1 | 75.0% | 34 | 6 | 82.4% |
| 67 | | 4 | 1 | 75.0% | 24 | 5 | 79.2% | 3 | 0 | 100.0% | 24 | 5 | 79.2% |
| 68 | | 4 | 0 | 100.0% | 35 | 9 | 74.3% | 4 | 0 | 100.0% | 35 | 7 | 80.0% |
| 69 | | 4 | 0 | 100.0% | 35 | 10 | 71.4% | 4 | 0 | 100.0% | 35 | 2 | 94.3% |
| 71 | 124 | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 3 | 25.0% | 35 | 9 | 74.3% |
| 72 | 72 | 4 | 1 | 75.0% | 35 | 6 | 82.9% | 4 | 2 | 50.0% | 35 | 5 | 85.7% |
| 73 | 25 | 4 | 0 | 100.0% | 30 | 4 | 86.7% | 4 | 2 | 50.0% | 30 | 15 | 50.0% |
| 74 | 16 | 4 | 0 | 100.0% | 30 | 6 | 80.0% | 4 | 2 | 50.0% | 30 | 15 | 50.0% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 75 | | 4 | 1 | 75.0% | 35 | 3 | 91.4% | 4 | 1 | 75.0% | 33 | 8 | 75.8% |
| 76 | 56 | 4 | 0 | 100.0% | 34 | 5 | 85.3% | 4 | 2 | 50.0% | 33 | 14 | 57.6% |
| 77 | 39 | 4 | 1 | 75.0% | 35 | 5 | 85.7% | 4 | 2 | 50.0% | 35 | 14 | 60.0% |
| 78 | 19 | 4 | 0 | 100.0% | 35 | 4 | 88.6% | 4 | 2 | 50.0% | 36 | 9 | 75.0% |
| 79 | 41 | 4 | 0 | 100.0% | 35 | 6 | 82.9% | 4 | 3 | 25.0% | 35 | 15 | 57.1% |
| 80 | 53 | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 2 | 50.0% | 35 | 10 | 71.4% |
| 89 | 38 | 4 | 0 | 100.0% | 24 | 1 | 95.8% | 4 | 4 | 0.0% | 24 | 14 | 41.7% |
| 90 | 22 | 4 | 0 | 100.0% | 24 | 0 | 100.0% | 4 | 3 | 25.0% | 24 | 10 | 58.3% |
| 94 | 21 | 4 | 0 | 100.0% | 24 | 4 | 83.3% | 4 | 2 | 50.0% | 24 | 5 | 79.2% |
| 97 | 55 | 4 | 2 | 50.0% | 35 | 12 | 65.7% | 4 | 4 | 0.0% | 35 | 9 | 74.3% |
| 98 | 26 | 4 | 1 | 75.0% | 35 | 4 | 88.6% | 4 | 2 | 50.0% | 35 | 14 | 60.0% |
| 230 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 0 | 100.0% | 35 | 1 | 97.1% |
| 232 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 0 | 100.0% | 35 | 2 | 94.3% |
| 233 | | 4 | 0 | 100.0% | 35 | 12 | 65.7% | 4 | 1 | 75.0% | 35 | 13 | 62.9% |
| 234 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 1 | 97.1% |
| 235 | | 4 | 1 | 75.0% | 35 | 5 | 85.7% | 4 | 2 | 50.0% | 35 | 11 | 68.6% |
| 236 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 6 | 82.9% |
| 237 | | 4 | 1 | 75.0% | 35 | 5 | 85.7% | 4 | 0 | 100.0% | 35 | 10 | 71.4% |
| 238 | | 4 | 2 | 50.0% | 35 | 6 | 82.9% | 4 | 1 | 75.0% | 35 | 4 | 88.6% |
| 239 | | 4 | 0 | 100.0% | 34 | 5 | 85.3% | 4 | 1 | 75.0% | 34 | 3 | 91.2% |
| 240 | | 4 | 0 | 100.0% | 35 | 4 | 88.6% | 3 | 0 | 100.0% | 34 | 2 | 94.1% |
| 241 | | 4 | 0 | 100.0% | 35 | 6 | 82.9% | 4 | 0 | 100.0% | 35 | 8 | 77.1% |
| 243 | | 4 | 0 | 100.0% | 35 | 5 | 85.7% | 4 | 0 | 100.0% | 35 | 1 | 97.1% |
| 244 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 10 | 71.4% |
| 245 | | 4 | 0 | 100.0% | 35 | 5 | 85.7% | 4 | 0 | 100.0% | 35 | 5 | 85.7% |
| 280 | | 4 | 0 | 100.0% | 35 | 3 | 91.4% | 4 | 0 | 100.0% | 35 | 12 | 65.7% |
| 281 | 57 | 4 | 0 | 100.0% | 35 | 5 | 85.7% | 4 | 2 | 50.0% | 35 | 5 | 85.7% |
| 283 | 25 | 4 | 1 | 75.0% | 35 | 2 | 94.3% | 4 | 1 | 75.0% | 35 | 5 | 85.7% |
| 284 | | 4 | 1 | 75.0% | 35 | 3 | 91.4% | 4 | 0 | 100.0% | 35 | 3 | 91.4% |
| 290 | | 4 | 0 | 100.0% | 35 | 5 | 85.7% | 4 | 3 | 25.0% | 34 | 15 | 55.9% |
| 291 | | 4 | 0 | 100.0% | 35 | 17 | 51.4% | 4 | 1 | 75.0% | 35 | 8 | 77.1% |
| 300 | | 4 | 0 | 100.0% | 34 | 1 | 97.1% | 4 | 0 | 100.0% | 34 | 7 | 79.4% |
| 301 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 4 | 88.6% |
| 302 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 1 | 75.0% | 35 | 9 | 74.3% |
| 305 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 1 | 75.0% | 35 | 13 | 62.9% |
| 306 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 10 | 71.4% |
| 307 | 34 | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 2 | 50.0% | 35 | 12 | 65.7% |
| 311 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 0 | 100.0% | 35 | 4 | 88.6% |
| 316 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 2 | 50.0% | 35 | 11 | 68.6% |
| 318 | 33 | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 4 | 0.0% | 35 | 16 | 54.3% |
| 319 | 70 | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 3 | 25.0% | 34 | 26 | 23.5% |
| 329 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 25 | 1 | 96.0% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 330 | | 3 | 0 | 100.0% | 30 | 0 | 100.0% | 3 | 0 | 100.0% | 29 | 1 | 96.6% |
| 331 | | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 0 | 100.0% | 33 | 1 | 97.0% |
| 332 | | 4 | 0 | 100.0% | 35 | 3 | 91.4% | 4 | 1 | 75.0% | 35 | 2 | 94.3% |
| 334 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 0 | 100.0% | 35 | 1 | 97.1% |
| 335 | | 4 | 0 | 100.0% | 35 | 6 | 82.9% | 4 | 0 | 100.0% | 35 | 3 | 91.4% |
| 336 | 84 | 4 | 0 | 100.0% | 34 | 0 | 100.0% | 4 | 2 | 50.0% | 34 | 3 | 91.2% |
| 337 | 90 | 4 | 1 | 75.0% | 34 | 2 | 94.1% | 4 | 1 | 75.0% | 34 | 2 | 94.1% |
| 338 | 16 | 4 | 1 | 75.0% | 35 | 5 | 85.7% | 4 | 1 | 75.0% | 35 | 10 | 71.4% |
| 339 | | 4 | 0 | 100.0% | 35 | 8 | 77.1% | 4 | 0 | 100.0% | 34 | 6 | 82.4% |
| 341 | | 4 | 0 | 100.0% | 34 | 5 | 85.3% | 4 | 0 | 100.0% | 34 | 2 | 94.1% |
| 342 | | 4 | 0 | 100.0% | 35 | 4 | 88.6% | 4 | 0 | 100.0% | 34 | 3 | 91.2% |
| 350 | | 4 | 0 | 100.0% | 32 | 2 | 93.8% | 4 | 1 | 75.0% | 30 | 13 | 56.7% |
| 351 | 42 | 4 | 0 | 100.0% | 30 | 4 | 86.7% | 4 | 2 | 50.0% | 28 | 7 | 75.0% |
| 352 | 50 | 4 | 1 | 75.0% | 31 | 5 | 83.9% | 4 | 2 | 50.0% | 30 | 12 | 60.0% |
| 353 | | 4 | 0 | 100.0% | 32 | 4 | 87.5% | 4 | 1 | 75.0% | 31 | 5 | 83.9% |
| 354 | | 4 | 0 | 100.0% | 32 | 6 | 81.3% | 4 | 0 | 100.0% | 31 | 11 | 64.5% |
| 355 | | 4 | 1 | 75.0% | 31 | 6 | 80.6% | 4 | 1 | 75.0% | 30 | 9 | 70.0% |
| 364 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 0 | 100.0% | 35 | 8 | 77.1% |
| 365 | 67 | 4 | 1 | 75.0% | 35 | 2 | 94.3% | 4 | 2 | 50.0% | 35 | 13 | 62.9% |
| 370 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 4 | 88.6% |
| 371 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 0 | 100.0% |
| 380 | | 3 | 0 | 100.0% | 34 | 2 | 94.1% | 3 | 0 | 100.0% | 34 | 10 | 70.6% |
| 381 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 7 | 80.0% |
| 382 | | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 0 | 100.0% | 35 | 7 | 80.0% |
| 383 | 38 | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 3 | 2 | 33.3% | 34 | 14 | 58.8% |
| 390 | | 4 | 0 | 100.0% | 34 | 5 | 85.3% | 4 | 0 | 100.0% | 34 | 9 | 73.5% |
| 391 | | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 0 | 100.0% | 35 | 6 | 82.9% |
| 392 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 1 | 75.0% | 35 | 24 | 31.4% |
| 393 | | 4 | 0 | 100.0% | 34 | 4 | 88.2% | 4 | 0 | 100.0% | 34 | 18 | 47.1% |
| 417 | | 3 | 0 | 100.0% | 25 | 5 | 80.0% | 3 | 0 | 100.0% | 24 | 6 | 75.0% |
| 425 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 0 | 100.0% | 25 | 3 | 88.0% |
| 448 | | 4 | 1 | 75.0% | 32 | 11 | 65.6% | 4 | 1 | 75.0% | 32 | 10 | 68.8% |
| 449 | | 4 | 0 | 100.0% | 32 | 1 | 96.9% | 4 | 2 | 50.0% | 32 | 6 | 81.3% |
| 470 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 8 | 68.0% |
| 471 | | 3 | 0 | 100.0% | 25 | 7 | 72.0% | 3 | 0 | 100.0% | 25 | 7 | 72.0% |
| 473 | | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 0 | 100.0% | 25 | 0 | 100.0% |
| 474 | | 3 | 0 | 100.0% | 25 | 7 | 72.0% | 3 | 0 | 100.0% | 24 | 8 | 66.7% |
| 475 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 0 | 100.0% | 25 | 2 | 92.0% |
| 478 | 36 | 3 | 1 | 66.7% | 25 | 3 | 88.0% | 3 | 1 | 66.7% | 25 | 2 | 92.0% |
| 479 | 40 | 3 | 1 | 66.7% | 25 | 4 | 84.0% | 3 | 1 | 66.7% | 24 | 9 | 62.5% |
| 486 | 74 | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 1 | 66.7% | 24 | 4 | 83.3% |
| 490 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |

# Amtrak On Time Performance

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 494 | 34 | 3 | 0 | 100.0% | 26 | 3 | 88.5% | 3 | 1 | 66.7% | 25 | 6 | 76.0% |
| 495 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 0 | 100.0% | 25 | 1 | 96.0% |
| 500 | 21 | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 3 | 25.0% | 35 | 8 | 77.1% |
| 502 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 1 | 75.0% | 35 | 7 | 80.0% |
| 503 | 46 | 4 | 0 | 100.0% | 35 | 7 | 80.0% | 4 | 1 | 75.0% | 35 | 15 | 57.1% |
| 504 | 40 | 4 | 0 | 100.0% | 33 | 1 | 97.0% | 4 | 2 | 50.0% | 33 | 15 | 54.5% |
| 505 | 49 | 4 | 1 | 75.0% | 35 | 2 | 94.3% | 4 | 3 | 25.0% | 35 | 9 | 74.3% |
| 506 | | 4 | 1 | 75.0% | 35 | 3 | 91.4% | 4 | 1 | 75.0% | 34 | 7 | 79.4% |
| 507 | | 4 | 1 | 75.0% | 35 | 4 | 88.6% | 4 | 2 | 50.0% | 33 | 13 | 60.6% |
| 508 | | 4 | 0 | 100.0% | 35 | 3 | 91.4% | 4 | 0 | 100.0% | 35 | 12 | 65.7% |
| 509 | 31 | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 4 | 0.0% | 35 | 18 | 48.6% |
| 511 | | 4 | 0 | 100.0% | 35 | 1 | 97.1% | 4 | 0 | 100.0% | 35 | 4 | 88.6% |
| 516 | 28 | 4 | 0 | 100.0% | 33 | 4 | 87.9% | 4 | 1 | 75.0% | 32 | 17 | 46.9% |
| 517 | | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 1 | 75.0% | 35 | 14 | 60.0% |
| 518 | 126 | 4 | 1 | 75.0% | 35 | 4 | 88.6% | 4 | 3 | 25.0% | 34 | 17 | 50.0% |
| 519 | No OS | 4 | 0 | 100.0% | 33 | 0 | 100.0% | 4 | 1 | 75.0% | 33 | 6 | 81.8% |
| 520 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 0 | 100.0% | 25 | 0 | 100.0% |
| 521 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 1 | 66.7% | 23 | 5 | 78.3% |
| 522 | | 3 | 1 | 66.7% | 25 | 8 | 68.0% | 3 | 1 | 66.7% | 25 | 4 | 84.0% |
| 523 | | 3 | 0 | 100.0% | 25 | 4 | 84.0% | 3 | 1 | 66.7% | 24 | 7 | 70.8% |
| 524 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 1 | 66.7% | 24 | 5 | 79.2% |
| 525 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 23 | 2 | 91.3% |
| 526 | | 3 | 2 | 33.3% | 25 | 9 | 64.0% | 3 | 0 | 100.0% | 23 | 2 | 91.3% |
| 527 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 1 | 66.7% | 25 | 7 | 72.0% |
| 528 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 8 | 68.0% |
| 529 | | 3 | 1 | 66.7% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 10 | 60.0% |
| 530 | | 3 | 1 | 66.7% | 25 | 5 | 80.0% | 3 | 1 | 66.7% | 25 | 6 | 76.0% |
| 531 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 24 | 2 | 91.7% |
| 532 | | 3 | 0 | 100.0% | 25 | 9 | 64.0% | 3 | 0 | 100.0% | 24 | 1 | 95.8% |
| 534 | | 3 | 0 | 100.0% | 25 | 4 | 84.0% | 3 | 0 | 100.0% | 25 | 0 | 100.0% |
| 535 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 0 | 100.0% | 24 | 2 | 91.7% |
| 536 | | 3 | 0 | 100.0% | 25 | 9 | 64.0% | 3 | 0 | 100.0% | 25 | 1 | 96.0% |
| 537 | | 3 | 0 | 100.0% | 24 | 1 | 95.8% | 3 | 0 | 100.0% | 23 | 1 | 95.7% |
| 538 | | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 1 | 66.7% | 25 | 2 | 92.0% |
| 539 | | 3 | 0 | 100.0% | 25 | 5 | 80.0% | 3 | 0 | 100.0% | 25 | 8 | 68.0% |
| 540 | | 3 | 0 | 100.0% | 24 | 3 | 87.5% | 3 | 1 | 66.7% | 23 | 1 | 95.7% |
| 541 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 4 | 84.0% |
| 542 | | 3 | 1 | 66.7% | 25 | 5 | 80.0% | 3 | 0 | 100.0% | 24 | 2 | 91.7% |
| 543 | 57 | 3 | 1 | 66.7% | 25 | 5 | 80.0% | 3 | 3 | 0.0% | 25 | 13 | 48.0% |
| 544 | | 3 | 0 | 100.0% | 25 | 6 | 76.0% | 3 | 0 | 100.0% | 25 | 6 | 76.0% |
| 545 | | 3 | 0 | 100.0% | 24 | 0 | 100.0% | 3 | 0 | 100.0% | 23 | 0 | 100.0% |
| 547 | | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 1 | 66.7% | 25 | 6 | 76.0% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 548 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 25 | 1 | 96.0% |
| 549 | | 3 | 1 | 66.7% | 25 | 4 | 84.0% | 3 | 2 | 33.3% | 24 | 5 | 79.2% |
| 550 | | 3 | 2 | 33.3% | 25 | 5 | 80.0% | 3 | 1 | 66.7% | 25 | 5 | 80.0% |
| 551 | | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 0 | 100.0% | 25 | 4 | 84.0% |
| 562 | 29 | 4 | 1 | 75.0% | 33 | 3 | 90.9% | 4 | 4 | 0.0% | 33 | 20 | 39.4% |
| 564 | 24 | 4 | 0 | 100.0% | 33 | 0 | 100.0% | 4 | 4 | 0.0% | 33 | 21 | 36.4% |
| 566 | 68 | 4 | 1 | 75.0% | 33 | 2 | 93.9% | 3 | 3 | 0.0% | 30 | 17 | 43.3% |
| 567 | | 4 | 0 | 100.0% | 32 | 4 | 87.5% | 4 | 2 | 50.0% | 31 | 9 | 71.0% |
| 572 | 63 | 4 | 1 | 75.0% | 30 | 8 | 73.3% | 3 | 3 | 0.0% | 27 | 19 | 29.6% |
| 573 | | 4 | 1 | 75.0% | 33 | 4 | 87.9% | 4 | 3 | 25.0% | 32 | 15 | 53.1% |
| 579 | 31 | 4 | 2 | 50.0% | 30 | 4 | 86.7% | 2 | 2 | 0.0% | 27 | 17 | 37.0% |
| 580 | | 4 | 1 | 75.0% | 33 | 3 | 90.9% | 4 | 3 | 25.0% | 32 | 15 | 53.1% |
| 581 | | 4 | 2 | 50.0% | 33 | 14 | 57.6% | 4 | 2 | 50.0% | 31 | 22 | 29.0% |
| 584 | 61 | 4 | 1 | 75.0% | 33 | 4 | 87.9% | 4 | 4 | 0.0% | 31 | 25 | 19.4% |
| 587 | 30 | 4 | 1 | 75.0% | 32 | 7 | 78.1% | 4 | 3 | 25.0% | 30 | 19 | 36.7% |
| 588 | Cncld | 4 | 1 | 75.0% | 30 | 5 | 83.3% | 3 | 2 | 33.3% | 27 | 16 | 40.7% |
| 591 | | 4 | 0 | 100.0% | 33 | 5 | 84.8% | 4 | 1 | 75.0% | 33 | 20 | 39.4% |
| 595 | No OS | 4 | 4 | 0.0% | 29 | 17 | 41.4% | 4 | 4 | 0.0% | 29 | 22 | 24.1% |
| 600 | | 4 | 0 | 100.0% | 33 | 1 | 97.0% | 4 | 0 | 100.0% | 33 | 4 | 87.9% |
| 601 | | 3 | 3 | 0.0% | 25 | 12 | 52.0% | 3 | 0 | 100.0% | 25 | 4 | 84.0% |
| 605 | | 3 | 1 | 66.7% | 25 | 11 | 56.0% | 3 | 0 | 100.0% | 24 | 1 | 95.8% |
| 607 | | 4 | 0 | 100.0% | 33 | 2 | 93.9% | 4 | 0 | 100.0% | 33 | 1 | 97.0% |
| 609 | | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 0 | 100.0% | 24 | 0 | 100.0% |
| 622 | | 3 | 1 | 66.7% | 23 | 3 | 87.0% | 3 | 1 | 66.7% | 23 | 2 | 91.3% |
| 626 | | 4 | 1 | 75.0% | 33 | 6 | 81.8% | 4 | 0 | 100.0% | 33 | 5 | 84.8% |
| 640 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 25 | 4 | 84.0% |
| 641 | | 3 | 1 | 66.7% | 25 | 5 | 80.0% | 3 | 0 | 100.0% | 25 | 2 | 92.0% |
| 642 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 25 | 2 | 92.0% |
| 643 | | 4 | 2 | 50.0% | 33 | 10 | 69.7% | 4 | 0 | 100.0% | 33 | 3 | 90.9% |
| 644 | | 3 | 1 | 66.7% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 7 | 72.0% |
| 645 | | 4 | 2 | 50.0% | 33 | 11 | 66.7% | 4 | 0 | 100.0% | 32 | 4 | 87.5% |
| 646 | | 3 | 0 | 100.0% | 25 | 6 | 76.0% | 3 | 1 | 66.7% | 25 | 3 | 88.0% |
| 647 | | 4 | 0 | 100.0% | 32 | 4 | 87.5% | 4 | 0 | 100.0% | 31 | 1 | 96.8% |
| 648 | | 3 | 1 | 66.7% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 25 | 1 | 96.0% |
| 649 | | 4 | 0 | 100.0% | 33 | 2 | 93.9% | 4 | 1 | 75.0% | 33 | 5 | 84.8% |
| 650 | | 4 | 0 | 100.0% | 33 | 4 | 87.9% | 4 | 1 | 75.0% | 33 | 3 | 90.9% |
| 651 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 1 | 66.7% | 25 | 5 | 80.0% |
| 652 | | 4 | 0 | 100.0% | 33 | 3 | 90.9% | 4 | 0 | 100.0% | 33 | 2 | 93.9% |
| 653 | | 3 | 3 | 0.0% | 24 | 10 | 58.3% | 3 | 0 | 100.0% | 24 | 3 | 87.5% |
| 654 | | 3 | 0 | 100.0% | 24 | 5 | 79.2% | 3 | 0 | 100.0% | 24 | 3 | 87.5% |
| 655 | | 4 | 0 | 100.0% | 33 | 3 | 90.9% | 4 | 0 | 100.0% | 33 | 2 | 93.9% |
| 656 | | 4 | 1 | 75.0% | 33 | 6 | 81.8% | 4 | 0 | 100.0% | 33 | 5 | 84.8% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 657 | | 3 | 1 | 66.7% | 25 | 9 | 64.0% | 3 | 0 | 100.0% | 25 | 1 | 96.0% |
| 658 | | 4 | 0 | 100.0% | 32 | 1 | 96.9% | 4 | 0 | 100.0% | 32 | 1 | 96.9% |
| 680 | | 3 | 0 | 100.0% | 25 | 4 | 84.0% | 3 | 0 | 100.0% | 25 | 2 | 92.0% |
| 681 | 23 | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 2 | 33.3% | 24 | 12 | 50.0% |
| 682 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 4 | 84.0% |
| 683 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 2 | 33.3% | 25 | 18 | 28.0% |
| 684 | | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 0 | 100.0% | 25 | 9 | 64.0% |
| 685 | 81 | 3 | 1 | 66.7% | 25 | 4 | 84.0% | 3 | 2 | 33.3% | 25 | 9 | 64.0% |
| 686 | 132 | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 1 | 66.7% | 25 | 10 | 60.0% |
| 687 | | 3 | 1 | 66.7% | 25 | 6 | 76.0% | 3 | 1 | 66.7% | 25 | 9 | 64.0% |
| 688 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 1 | 66.7% | 25 | 7 | 72.0% |
| 701 | | 4 | 2 | 50.0% | 35 | 6 | 82.9% | 4 | 2 | 50.0% | 35 | 9 | 74.3% |
| 702 | 123 | 4 | 0 | 100.0% | 35 | 2 | 94.3% | 4 | 1 | 75.0% | 35 | 15 | 57.1% |
| 703 | No OS | 4 | 2 | 50.0% | 35 | 12 | 65.7% | 4 | 2 | 50.0% | 35 | 8 | 77.1% |
| 704 | | 4 | 2 | 50.0% | 35 | 8 | 77.1% | 4 | 1 | 75.0% | 35 | 5 | 85.7% |
| 710 | 258 | 4 | 1 | 75.0% | 35 | 7 | 80.0% | 4 | 1 | 75.0% | 35 | 8 | 77.1% |
| 711 | 134 | 4 | 0 | 100.0% | 35 | 6 | 82.9% | 4 | 1 | 75.0% | 30 | 5 | 83.3% |
| 712 | 40 | 4 | 1 | 75.0% | 35 | 11 | 68.6% | 4 | 3 | 25.0% | 35 | 16 | 54.3% |
| 713 | | 4 | 2 | 50.0% | 32 | 12 | 62.5% | 4 | 1 | 75.0% | 27 | 7 | 74.1% |
| 714 | 36 | 4 | 3 | 25.0% | 35 | 20 | 42.9% | 4 | 3 | 25.0% | 34 | 19 | 44.1% |
| 715 | 47 | 4 | 0 | 100.0% | 35 | 6 | 82.9% | 3 | 2 | 33.3% | 33 | 17 | 48.5% |
| 716 | 45 | 4 | 1 | 75.0% | 34 | 16 | 52.9% | 4 | 1 | 75.0% | 33 | 8 | 75.8% |
| 717 | 134 | 4 | 2 | 50.0% | 35 | 16 | 54.3% | 4 | 3 | 25.0% | 32 | 15 | 53.1% |
| 718 | 20 | 4 | 3 | 25.0% | 35 | 23 | 34.3% | 4 | 2 | 50.0% | 35 | 14 | 60.0% |
| 719 | 117 | 4 | 2 | 50.0% | 35 | 8 | 77.1% | 4 | 1 | 75.0% | 35 | 8 | 77.1% |
| 757 | | 4 | 0 | 100.0% | 32 | 2 | 93.8% | 4 | 0 | 100.0% | 32 | 14 | 56.3% |
| 761 | | 4 | 0 | 100.0% | 33 | 0 | 100.0% | 4 | 0 | 100.0% | 33 | 11 | 66.7% |
| 765 | 71 | 4 | 0 | 100.0% | 33 | 0 | 100.0% | 4 | 2 | 50.0% | 33 | 21 | 36.4% |
| 769 | 21 | 4 | 0 | 100.0% | 33 | 2 | 93.9% | 4 | 4 | 0.0% | 33 | 25 | 24.2% |
| 770 | 30 | 4 | 0 | 100.0% | 33 | 3 | 90.9% | 4 | 4 | 0.0% | 32 | 23 | 28.1% |
| 774 | 65 | 4 | 2 | 50.0% | 33 | 15 | 54.5% | 4 | 3 | 25.0% | 32 | 27 | 15.6% |
| 777 | 72 | 4 | 1 | 75.0% | 33 | 3 | 90.9% | 4 | 3 | 25.0% | 32 | 23 | 28.1% |
| 782 | 40 | 4 | 1 | 75.0% | 33 | 22 | 33.3% | 4 | 4 | 0.0% | 32 | 24 | 25.0% |
| 785 | 25 | 4 | 2 | 50.0% | 33 | 19 | 42.4% | 4 | 1 | 75.0% | 33 | 19 | 42.4% |
| 786 | | 4 | 1 | 75.0% | 33 | 10 | 69.7% | 4 | 2 | 50.0% | 28 | 16 | 42.9% |
| 790 | 69 | 4 | 0 | 100.0% | 33 | 2 | 93.9% | 4 | 3 | 25.0% | 33 | 21 | 36.4% |
| 794 | 20 | 4 | 3 | 25.0% | 33 | 17 | 48.5% | 4 | 3 | 25.0% | 33 | 18 | 45.5% |
| 821 | 32 | 4 | 0 | 100.0% | 34 | 2 | 94.1% | 4 | 4 | 0.0% | 34 | 28 | 17.6% |
| 822 | | 4 | 0 | 100.0% | 34 | 2 | 94.1% | 4 | 3 | 25.0% | 34 | 28 | 17.6% |
| 1082 | 82 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 3 | 2 | 33.3% | 18 | 5 | 72.2% |
| 1087 | | 3 | 0 | 100.0% | 18 | 1 | 94.4% | 3 | 1 | 66.7% | 17 | 2 | 88.2% |
| 1088 | 180 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 3 | 2 | 33.3% | 18 | 5 | 72.2% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 1099 | 50 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 2 | 33.3% | 18 | 7 | 61.1% |
| 1103 | 115 | 3 | 1 | 66.7% | 18 | 9 | 50.0% | 3 | 1 | 66.7% | 18 | 4 | 77.8% |
| 1107 | Cncld | 3 | 2 | 33.3% | 18 | 7 | 61.1% | 2 | 0 | 100.0% | 17 | 3 | 82.4% |
| 1109 | | 3 | 0 | 100.0% | 18 | 1 | 94.4% | 3 | 0 | 100.0% | 18 | 1 | 94.4% |
| 1111 | 84 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 3 | 1 | 66.7% | 18 | 1 | 94.4% |
| 1116 | Cncld | 3 | 1 | 66.7% | 18 | 3 | 83.3% | 2 | 1 | 50.0% | 17 | 2 | 88.2% |
| 1118 | 73 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 3 | 1 | 66.7% | 18 | 1 | 94.4% |
| 1124 | | 3 | 0 | 100.0% | 16 | 2 | 87.5% | 3 | 0 | 100.0% | 16 | 5 | 68.8% |
| 1126 | | 3 | 1 | 66.7% | 18 | 1 | 94.4% | 3 | 0 | 100.0% | 18 | 4 | 77.8% |
| 1127 | | 3 | 1 | 66.7% | 18 | 4 | 77.8% | 3 | 0 | 100.0% | 18 | 1 | 94.4% |
| 1128 | 21 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 2 | 1 | 50.0% | 17 | 2 | 88.2% |
| 1129 | | 3 | 0 | 100.0% | 18 | 1 | 94.4% | 3 | 0 | 100.0% | 18 | 3 | 83.3% |
| 1135 | 84 | 3 | 1 | 66.7% | 18 | 3 | 83.3% | 3 | 1 | 66.7% | 18 | 13 | 27.8% |
| 1138 | | 3 | 0 | 100.0% | 17 | 2 | 88.2% | 3 | 0 | 100.0% | 17 | 3 | 82.4% |
| 1140 | 158 | 3 | 1 | 66.7% | 18 | 5 | 72.2% | 3 | 2 | 33.3% | 18 | 3 | 83.3% |
| 1142 | | 3 | 0 | 100.0% | 18 | 4 | 77.8% | 3 | 0 | 100.0% | 18 | 4 | 77.8% |
| 1143 | 26 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 2 | 33.3% | 18 | 7 | 61.1% |
| 1144 | 69 | 3 | 3 | 0.0% | 18 | 15 | 16.7% | 3 | 1 | 66.7% | 18 | 5 | 72.2% |
| 1146 | | 3 | 1 | 66.7% | 18 | 4 | 77.8% | 3 | 1 | 66.7% | 18 | 2 | 88.9% |
| 1147 | 85 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 2 | 33.3% | 18 | 6 | 66.7% |
| 1150 | 46 | 3 | 3 | 0.0% | 18 | 13 | 27.8% | 3 | 2 | 33.3% | 18 | 4 | 77.8% |
| 1151 | 27 | 3 | 1 | 66.7% | 18 | 6 | 66.7% | 3 | 2 | 33.3% | 18 | 10 | 44.4% |
| 1152 | 17 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 3 | 1 | 66.7% | 18 | 4 | 77.8% |
| 1153 | 83 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 1 | 66.7% | 18 | 1 | 94.4% |
| 1155 | | 3 | 0 | 100.0% | 17 | 2 | 88.2% | 3 | 0 | 100.0% | 17 | 5 | 70.6% |
| 1156 | 24 | 3 | 0 | 100.0% | 15 | 2 | 86.7% | 3 | 2 | 33.3% | 15 | 11 | 26.7% |
| 1160 | 105 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 2 | 33.3% | 18 | 9 | 50.0% |
| 1161 | 65 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 3 | 0.0% | 18 | 14 | 22.2% |
| 1162 | 65 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 3 | 0.0% | 18 | 11 | 38.9% |
| 1163 | | 3 | 0 | 100.0% | 18 | 1 | 94.4% | 3 | 2 | 33.3% | 18 | 13 | 27.8% |
| 1164 | 114 | 3 | 1 | 66.7% | 17 | 2 | 88.2% | 3 | 2 | 33.3% | 17 | 7 | 58.8% |
| 1165 | No OS | 3 | 1 | 66.7% | 18 | 1 | 94.4% | 3 | 1 | 66.7% | 18 | 8 | 55.6% |
| 1167 | 40 | 3 | 2 | 33.3% | 18 | 6 | 66.7% | 3 | 2 | 33.3% | 18 | 7 | 61.1% |
| 1168 | | 3 | 0 | 100.0% | 18 | 4 | 77.8% | 3 | 0 | 100.0% | 18 | 4 | 77.8% |
| 1169 | | 3 | 1 | 66.7% | 17 | 4 | 76.5% | 2 | 1 | 50.0% | 16 | 3 | 81.3% |
| 1194 | 96 | 3 | 1 | 66.7% | 18 | 3 | 83.3% | 3 | 1 | 66.7% | 18 | 3 | 83.3% |
| 1195 | | 3 | 0 | 100.0% | 17 | 0 | 100.0% | 3 | 0 | 100.0% | 16 | 1 | 93.8% |
| 1333 | 116 | 4 | 1 | 75.0% | 35 | 4 | 88.6% | 4 | 2 | 50.0% | 35 | 12 | 65.7% |
| 1340 | | 4 | 0 | 100.0% | 35 | 0 | 100.0% | 4 | 0 | 100.0% | 35 | 4 | 88.6% |
| 1689 | | 1 | 0 | 100.0% | 15 | 0 | 100.0% | 1 | 0 | 100.0% | 15 | 3 | 80.0% |
| 2101 | | 3 | 0 | 100.0% | 18 | 1 | 94.4% | 3 | 0 | 100.0% | 18 | 1 | 94.4% |
| 2103 | | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 0 | 100.0% | 25 | 2 | 92.0% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak On Time Performance

Trains Arriving Through: 11/4/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 2105 | 40 | 3 | 1 | 66.7% | 25 | 2 | 92.0% | 3 | 2 | 33.3% | 25 | 3 | 88.0% |
| 2106 | 77 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 1 | 66.7% | 18 | 3 | 83.3% |
| 2114 | 163 | 3 | 0 | 100.0% | 18 | 3 | 83.3% | 3 | 1 | 66.7% | 18 | 4 | 77.8% |
| 2115 | | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 1 | 66.7% | 24 | 4 | 83.3% |
| 2116 | 55 | 3 | 0 | 100.0% | 25 | 2 | 92.0% | 3 | 2 | 33.3% | 25 | 2 | 92.0% |
| 2118 | 23 | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 2 | 33.3% | 24 | 6 | 75.0% |
| 2120 | | 3 | 0 | 100.0% | 25 | 3 | 88.0% | 3 | 0 | 100.0% | 25 | 3 | 88.0% |
| 2122 | 73 | 3 | 1 | 66.7% | 18 | 3 | 83.3% | 3 | 1 | 66.7% | 18 | 3 | 83.3% |
| 2123 | 73 | 3 | 1 | 66.7% | 25 | 3 | 88.0% | 3 | 2 | 33.3% | 25 | 4 | 84.0% |
| 2133 | 105 | 3 | 0 | 100.0% | 18 | 0 | 100.0% | 3 | 1 | 66.7% | 18 | 3 | 83.3% |
| 2148 | | 3 | 0 | 100.0% | 18 | 1 | 94.4% | 3 | 0 | 100.0% | 17 | 2 | 88.2% |
| 2149 | 250 | 3 | 0 | 100.0% | 18 | 2 | 88.9% | 3 | 3 | 0.0% | 18 | 17 | 5.6% |
| 2150 | 61 | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 3 | 0.0% | 24 | 14 | 41.7% |
| 2151 | 26 | 3 | 0 | 100.0% | 25 | 0 | 100.0% | 3 | 2 | 33.3% | 25 | 15 | 40.0% |
| 2152 | 42 | 3 | 0 | 100.0% | 25 | 1 | 96.0% | 3 | 1 | 66.7% | 25 | 3 | 88.0% |
| 2155 | 120 | 3 | 1 | 66.7% | 25 | 2 | 92.0% | 3 | 1 | 66.7% | 24 | 3 | 87.5% |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

# Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 2105 | WAS | 40 | MBO | 47 | MBO | 47 | WIL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bidge, Held a/c bridge opening |
| 2106 | NYP | 77 | MBO | 84 | MBO | 84 | BAL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |
| 2114 | NYP | 163 | TRS | 137 | TRS | 137 | WIL-PHL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, HELD A/C TRESPASSER STRIKE MP 8.4 |
| 2116 | NYP | 55 | TRS | 34 | TRS | 31 | WIL-PHL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, CONGESTION A/C TRESPASSER STRIKE MP 8.4 |
| 2118 | NYP | 23 | SMW | 16 | SMW | 10 | XPV-WIL | AM | Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 1099 on 2 track, 1099 opr 2 track a/c 3 track o/s between Ragan & Davis |
| 2122 | NYP | 73 | MTI | 52 | MTI | 52 | XNY-BWI | AM | Disabled train ahead, Milepost, 121, ., received transfer from disabled 1116 |
| 2123 | WAS | 73 | ITI | 33 | ITI | 33 | NYP-NYP | AM | Late departure at initial terminal due to late arrival of inbound equipment, 2106, LATE TURN FOR AM2106 |
| 2133 | WAS | 105 | TRS | 108 | TRS | 108 | PHL-WIL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, HELD A/C TRESPASSER STRIKE MP 8.4; REST SPEED NO 4 TRK |
| 2149 | WAS | 250 | ENG | 133 | ENG | 96 | XGX-NHV | AM | Onboard HBD alarm, 2144\|NG\|NP, 2149 stopped at MP 93.67 for multiple faults on E/2144/ then stopped just east of Orchard with a locked axle alarm. |
| 2150 | BOS | 61 | DCS | 24 | DCS | 24 | XNH-XGX | AM | T.O.L, Control Point, PALMER COVE-MYSTIC RIVER , 2E SIGNAL @ PALMERS COVE DROPPED A/C OF T.O.L. TRK 2, PALMERS COVE-MYSTIC RIVER |
| 2151 | WAS | 26 | ENG | 18 | ENG | 18 | NYP-NYP | AM | Undesired emergency application, 2125\|NG\|NP, UNSPECIFIED MECHANICAL PROBLEMS |
| 2152 | NYP | 42 | MBO | 40 | MBO | 40 | BAL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |
| 2155 | WAS | 8 | | | | | | | |
| 94 | WAS | 21 | DCS | 20 | DCS | 14 | ALX-XVG | AM | Restrictive signal(s) from unknown cause Stop , Control Point, Virginia |
| 478 | SPG | 36 | ITI | 20 | ITI | 20 | NHV-NHV | AM | Late departure at initial terminal due to late arrival of inbound equipment, 479, DP NHV 20" LATE A/C OF LATE TURN OF AM479 |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 479 | NHV | 40 | ITI | 45 | ITI | 45 | GFD-GFD | MA | Late departure at initial terminal due to late arrival of inbound equipment 486, 486 late due to holding for connection in NHV |
| 486 | GFD | 74 | CON | 85 | CON | 85 | NHV-NHV | AM | Hold for connecting train, DP NHV 85" LATE A/C OF LATE AM1164. |
| 494 | GFD | 34 | CON | 50 | CON | 50 | NHV-NHV | AM | Hold for connecting train, DP NHV 50" LATE A/C OF LATE AM1194 |
| 1082 | BOS | 82 | MBO | 41 | MBO | 31 | ABE-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |
| 1088 | BOS | 180 | TRS | 138 | TRS | 138 | WIL-PHL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, HELD A/C TRESPASSER STRIKE MP 8.4 |
| 1099 | NPN | 50 | TRS | 55 | TRS | 29 | PHL-PHL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, HELD A/C TRESPASSER STRIKE MP 8.4 |
| 1103 | WAS | 115 | ENG | 111 | ENG | 111 | NYP-NYP | AM | Undesired emergency application, 622\|EX\|ES, SHOPPED ENG.622 FOR ENG.614 |
| 1107 | WAS | Trn Cancelled | | | | | | | |
| 1111 | WAS | 84 | MBO | 91 | MBO | 91 | WIL-XPV | AM | For maritime traffic, Control Point, Susquehanna Bridge, Held a/c Bridge opening |
| 1116 | NYP | Trn Cancelled | MBO | 60 | MBO | 60 | WAS-WAS | AM | For maritime traffic, Control Point, SASQUEHANNA RIVER BRIDGE, LATE TURN OFF 1103 DUE TO SUSQUEHANNA RIVER BRIDGE BEING OPEN |
| 1118 | NYP | 73 | MBO | 65 | MBO | 65 | BAL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |
| 1128 | NYP | 21 | SMW | 34 | SMW | 14 | XHM-TRE | AM | Scheduled in track usage program, Other, XHM-XMO, OPR ON NO.3 TRACK A/C 2 TRACK O/O/S BTWN HOLMES AND MORRIS. |
| 1135 | WAS | 84 | ITI | 67 | ITI | 67 | BOS-BOS | AM | Late departure at initial terminal due to late arrival of inbound equipment, 1150, DP BOS 67" A/C OF LATE TURN OF AM1150 |
| 1140 | SPG | 158 | TRS | 103 | TRS | 67 | WIL-WIL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, HELD A/C TRESPASSER STRIKE MP 8.4 |
| 1143 | WAS | 26 | MBO | 24 | MBO | 24 | WIL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 1144 | NYP | 69 | ENG | 50 | ENG | 21 | PHL-XHM | AM | Undesired emergency application, 622\|EX\| ES, FAULT ON REAR CAR |
| 1147 | RNK | 85 | TRS | 75 | TRS | 52 | PHL-PHL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, HELD A/C TRESPASSER STRIKE MP 8.4 |
| 1150 | BOS | 46 | SVS | 29 | SVS | 29 | PHL-PHL | AM | Planned set out / pick out of locomotives, cars or section of train, Late out from the yd. |
| 1151 | RNK | 27 | RTE | 24 | RTE | 24 | WAS-WAS | AM | Dispatcher hold, Other, X, MTRS ROUTED IN TRK WITH 7 MTR UNABLE TO CLEARED SIGNAL BLOCKING DSL IN NEC'Y FOR CREW TO RESPOT MTRS |
| 1152 | NYP | 17 | SMW | 20 | SMW | 9 | XPV-NRK | AM | Diversions around M/W work, Control Point, Bacon - Davis, OPR No.1 TRK A/C No.3 TRK O/O/S |
| 1153 | WAS | 83 | MBO | 92 | MBO | 92 | WIL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |
| 1156 | NYP | 24 | DSR | 21 | DCS | 18 | CLP-MSS | NS | Issue with automatic road crossing protection Stop and Flag at School house Rd crossing., Milepost, 52.8, 52.8 |
| 1160 | BOS | 105 | ENG | 76 | ENG | 76 | STM-BRP | MN | Unrecoverable penalty (PCS) 656 |
| 1161 | WAS | 65 | TRS | 34 | TRS | 28 | PHL-WIL | AM | Trespasser strike, Control Point, PHIL TO BALDWIN, CONGESTION A/C TRESPASSER STRIKE MP 8.4 |
| 1162 | BOS | 65 | PTI | 27 | DSR | 22 | STM-BRP | MN | Per bulletin Milepost, 40.4, 41.7, 30, 2, Milepost, 41.7, 42.0, 15, 2, Milepost, 46.3, 46.5, 30, 2, Milepost, 48.4, 48.6, 30, 2 |
| 1164 | BOS | 114 | MBO | 85 | MBO | 85 | BAL-XPV | AM | For maritime traffic, Bridge, Susquehanna Bridge, Held a/c Bridge opening |
| 1165 | WAS | No OS Rpt | ITI | 52 | ITI | 52 | BOS-BOS | AM | Late departure at initial terminal due to late arrival of inbound equipment, 1160, DP BOS 52" LATE A/C OF LATE TURN OF AM1160 |
| 1167 | PHL | 40 | ITI | 34 | ITI | 34 | BOS-BOS | AM | Late departure at initial terminal due to late arrival of inbound equipment, 1162, DP BOS 34" LATE A/C OF LATE TURN OF AM1162 |
| 1194 | BOS | 96 | MBO | 35 | MBO | 35 | WAS-WAS | AM | For maritime traffic, Control Point, SUSQUEHANNA RIVER BRIDGE, LATE TURN OFF 1111 DUE TO SUSQUEHANNA RIVER BRIDGE BEING OPEN |
| 52 | LOR | 278 | ITI | 260 | ITI | 260 | SFA-SFA | FR | Late departure at initial terminal due to late arrival of inbound equipment 53 |
| 53 | SFA | 150 | FTI | 189 | FTI | 40 | XV7-XSE | CS | Follow 111, Milepost, 38.0, 82.0 |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 79 | CLT | 41 | CON | 32 | CON | 32 | WAS-WAS | AM | Hold for connecting train, DUE TO SUSQUEHANNA RIVER BRIDGE BEING OPEN HELD INBOUND TRN |
| 80 | NYP | 53 | PTI | 40 | MTI | 39 | XNY-BAL | AM | Disabled train ahead, Milepost, 121, ., 1116 disabled on 1 track |
| 19 | NOL | 26 | FTI | 99 | FTI | 84 | TCL-MEI | NS | Follow 355, Milepost w/Letters, 234, Meridian Station |
| 681 | BRK | 23 | DMW | 24 | DMW | 13 | ORB-POR | CS | Waiting for MW clearance Other, MP PLD 12 |
| 685 | BRK | 81 | | | | | | | |
| 686 | BON | 132 | TRS | 116 | TRS | 116 | WEM-DOV | CS | Trespasser strike Other, church rd |
| 63 | TWO | 32 | FTI | 21 | HLD | 8 | NYP-NYP | AM | Passenger and/or baggage, HELD FOR PSGRS OFF LATE AM1150 |
| 64 | NYP | 26 | CTI | 38 | DTR | 29 | NFL-BUF | CS | MW Project NFL, BUF |
| 281 | NFL | 57 | FTI | 79 | FTI | 49 | XSV-ROC | CS | Follow Ran on approaches and restricted proceeds<br>Trains stacked up<br>Got around at 359, csx unknown, csx unknown, Milepost, 302, 359 |
| 283 | NFL | 25 | FTI | 51 | FTI | 26 | ROC-BUF | CS | Follow - Follow freight from CP 393 to CP 429<br>- Crossover 1 to 2 @ CP 429, CSX, Milepost w/Letters, CP 393, CP 429 |
| 49 | CHI | 183 | OTH | 228 | OTH | 225 | ALB-ALB | AM | Wait for late 449. |
| 43 | PGH | 26 | ENG | 22 | FTI | 18 | TYR-ALT | NS | Follow NS 29G, Milepost, 228, 236 |
| 71 | CLT | 124 | TEN | 116 | TEN | 116 | RGH-CYN | NS | Mechanical replaced sanding solenoid on engine 1984 Unable to proceed uphill without operational sanding system, NC1984 |
| 72 | GRO | 72 | ITI | 63 | ITI | 63 | CLT-CLT | NS | Late departure at initial terminal due to late arrival of inbound equipment 71 |
| 73 | CLT | 25 | TCC | 13 | PTI | 9 | SAL-KAN | NS | Meet #Amt72, Control Point, N. Kannapolis |
| 74 | RGH | 16 | TCC | 10 | HLD | 5 | CYN-CYN | NS | Passenger and/or baggage |
| 76 | RGH | 56 | PTI | 41 | PTI | 30 | KAN-GRO | NS | Meet AMTK77, Control Point, Salisbury |
| 77 | CLT | 39 | DCS | 32 | DCS | 32 | HPT-SAL | NS | PTC dropped to disengaged Dropped out four times between those points. Had to run restricted speed to next signal each time., Milepost, 313, 333 |
| 78 | RGH | 19 | PTI | 23 | PTI | 23 | GRO-GRO | NS | Meet #Amt79, Control Point, Fields |
| 89 | SAV | 38 | FTI | 84 | FTI | 49 | CHS-YEM | CS | Meet 410, Milepost, 394.7, 394.7 |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 90 | NYP | 22 | FTI | 46 | FTI | 20 | FAY-SSM | CS | Follow CSX410, Other, S. Godwin |
| 97 | MIA | 55 | FTI | 93 | TRS | 39 | NYP-NYP | AM | Trespasser strike, Other, NBK, HELD DUE TO TRESPASSER STRIKE AT NEW BRUNSWHICK |
| 98 | NYP | 26 | FTI | 98 | FTI | 42 | JSP-SAV | CS | Cross Traffic GC, 19802, Control Point, NE Savannah Yard |
| 40 | CHI | 50 | DSR | 73 | POL | 26 | JAX-JAX | CS | Removal of passenger by police Removing passenger for assaulting another passenger |
| 41 | MIA | 60 | FTI | 115 | PTI | 35 | SAV-XJG | CS | Follow P053, Milepost, 503, 543 |
| 5 | EMY | 213 | ENG | 271 | ENG | 130 | XFJ-XXP | UP | Pick up rescue locomotive due to mechanical failure PTC login issue due to Amtrak system PTC outage, 7656 |
| 6 | CHI | 107 | WTR | 195 | WTR | 195 | XNV-XSZ | UP | Rail broke due to cold temps, Hold for defect repair Broken rail between delle and timpie, Siding, elle |
| 543 | SJC | 57 | PTI | 31 | CTI | 23 | FMT-GAC | UP | Meet ACE8, Siding, Albrae |
| 50 | NYP | 28 | FTI | 41 | FTI | 25 | CIN-MAY | CS | Follow m54103, Control Point, CT Jct |
| 500 | SEA | 21 | DMW | 11 | DMW | 11 | CTL-OLW | BN | Waiting for MW clearance Milepost, 36.6, 32.0 |
| 503 | EUG | 46 | DMW | 40 | DMW | 33 | PDX-ORC | UP | Broken Rail Other, MP 761.84 |
| 504 | SEA | 40 | DMW | 40 | DMW | 39 | ORC-PDX | UP | Hold for defect repair Stop and wait for permission through MP 761.84, broken rail. Proceed at restricted speed after stopping to speak to track inspector. Continue at restricted speed to Willsburg Jct, Milepost, 761.84, 761.84 |
| 505 | PDX | 49 | CAR | 34 | CAR | 34 | SEA-SEA | BN | Door 7310, Exterior door on west side not working correctly causing brakes to apply. Blue flags were dropped in the SEA yard at 9:05. |
| 509 | PDX | 31 | TRS | 31 | TRS | 20 | TAC-TAC | ST | Vehicle on track ahead Vehicle stuck on grade crossing at MP 4.29 on the Lakewood Subdivision., Milepost, 4.29, 4.29 |
| 516 | VAC | 28 | MBO | 25 | MBO | 25 | XF2-X1J | BN | For maritime traffic Bridge, Fraser |
| 518 | VAC | 126 | POL | 109 | POL | 109 | BEL-X8B | BN | Right of Way police hold Body on beach |
| 519 | SEA | No OS Rpt | POL | 241 | POL | 241 | XF2-X8B | BN | Right of Way police hold Held at Cole brook due to police activity at white rock mp 125 |
| 58 | CHI | 17 | FTI | 82 | FTI | 22 | JAN-YAZ | CC | Meet CN2298, Siding, Ferryman |
| 11 | LAX | 48 | DCS | 77 | SYS | 60 | SLO-SBA | UP | Track and time from 295-356 |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 14 | SEA | 22 | PTI | 57 | OTH | 51 | SBA-SLO | UP | Track and time |
| 27 | PDX | Trn Cancelled | DSR | 7 | DSR | 5 | XPW-PSC | BN | Per bulletin Milepost, 83.2, 83.3, 30, 1, Milepost, 113.1, 113.3, 30, 1, Milepost, 119.7, 119.8, 60, main, Milepost, 130.5, 130.6, 60, main, Milepost, 131.0, 131.2, 45, main, Milepost, 132.6, 132.7, 10, main |
| 821 | FTW | 32 | DSR | 57 | DSR | 37 | GLE-FTW | BN | Per bulletin Milepost, 409.5, 409, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 407.9, 407.1, 30, m, Milepost, 405.9, 405, 60, m, Milepost, 404.2, 403.8, 60, m, Milepost, 403.2, 402.7, 60, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.5, 399.8, 60, m, Milepost, 399.9, 399.5, 60, m, Milepost, 39 |
| 336 | CHI | 84 | MBO | 66 | MBO | 66 | MKE-MKA | CP | Bridge OOS Bridge tender can't get it to lock up. Crews working on it, bridge tender reporting an estimated 30 mins before it's fixed, Bridge, Menomonee |
| 337 | MKE | 90 | ITI | 61 | ITI | 61 | CHI-CHI | AM | Late departure at initial terminal due to late arrival of inbound equipment 336 |
| 338 | CHI | 16 | CTI | 10 | CTI | 10 | GLN-XWA | ME | Cross Traffic metra, Milepost, 9, 9, Milepost, 4, 2 |
| 351 | CHI | 42 | WTR | 36 | FTI | 14 | ARB-JXN | MI | Cross over or go around ns 5433, Siding, chelsea |
| 352 | PNT | 50 | CAR | 43 | CAR | 41 | X90-KAL | AM | Legitimate wayside HBD or DED actuation id4214, Had to stop and inspect for hot journal detected on axel 1<br>CNOC gave us permission to travel 10miles at 5ph until we got to the next detector and we had no defects to travel at track speed |
| 365 | CHI | 67 | DCS | 58 | DCS | 41 | XH6-XTF | AM | Restrictive signal(s) from unknown cause Red fence, Other, 21st street |
| 562 | SAN | 29 | PTI | 20 | DCS | 15 | SNC-X98 | SC | Restrictive signal(s) from known wayside signal failure Flagging through high tide area, Red, Milepost, 204, 210 |
| 564 | SAN | 24 | DCS | 16 | FTI | 9 | XRJ-FUL | BN | Follow bnsf, Control Point, santafe springs |
| 566 | SAN | 68 | ITI | 47 | ITI | 47 | LAX-LAX | SC | Late departure at initial terminal due to late arrival of inbound equipment 566, Late release from 8th street yard @ 08:21. Spot at LAX 08:46 |
| 572 | SAN | 63 | CTI | 40 | CTI | 18 | X98-OSD | SN | Follow Lined behind coaster deadhead equipment. We had plenty of time to get into Oceanside and depart without getting in their way., NCTD, DH equipment, Control Point, cp mesa |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 579 | LAX | 31 | DCS | 18 | DCS | 15 | OSD-X98 | SN | Restrictive signal(s) from known wayside signal failure Flagging CP Songs to X98, Stop, Control Point, Songs |
| 584 | SAN | 61 | PTI | 46 | PTI | 37 | SNC-SNP | SC | Meet Amtk 587, Siding, Capistrano |
| 587 | LAX | 30 | WTR | 27 | WTR | 27 | OSD-X98 | SN | High tides along the San Clemente beach Control Point, songs |
| 588 | SAN | Trn Cancelled | | | | | | | |
| 595 | LAX | No OS Rpt | PTI | 31 | ITI | 27 | SAN-SAN | SN | Late departure at initial terminal due to late arrival of inbound equipment 584 |
| 765 | GTA | 71 | PTI | 48 | PTI | 21 | SBA-SBA | UP | Meet 782 is stopped ahead with a locomotive issue., 782, Other, SBA |
| 769 | GTA | 21 | DCS | 20 | DCS | 16 | OSD-X98 | SC | CTC system failure Control Point, Songs |
| 770 | SAN | 30 | DCS | 22 | DSR | 10 | OSD-SOL | SN | Per bulletin Milepost, 237, 238, 10, 2 |
| 774 | SAN | 65 | PTI | 49 | PTI | 14 | X98-OSD | SN | Meet 579, Control Point, eastbrook |
| 777 | GTA | 72 | PTI | 51 | PTI | 38 | OSD-X98 | SC | Meet 774, Control Point, songs |
| 782 | SIM | 40 | ENG | 46 | ENG | 24 | GTA-SBA | UP | Failure of diesel engine C2118 |
| 785 | GTA | 25 | CTI | 19 | CON | 16 | SAN-SAN | SN | Hold for connecting train 774 |
| 790 | SAN | 69 | PTI | 78 | PTI | 54 | SIM-CWT | SC | Meet Wait for double set to clear the main line, 782/786, Siding, Davis |
| 794 | SAN | 20 | DCS | 23 | DCS | 12 | SNC-X98 | SC | T.O.L Milepost, 205.14, 207.4 |
| 702 | BFD | 123 | FTI | 113 | FTI | 96 | XEC-LOD | UP | Follow Held at SP055 for disabled freight train ahead that lost its air., UP South, Control Point, SP055 |
| 703 | SAC | No OS Rpt | ITI | 79 | ITI | 79 | BFD-BFD | BN | Late departure at initial terminal due to late arrival of inbound equipment 710 |
| 710 | BFD | 258 | TRS | 123 | TRS | 123 | XPR-ACA | BN | Trespasser strike Milepost, 1157.3, 1157.3 |
| 711 | OKJ | 134 | DMW | 70 | POL | 65 | SKN-ACA | BN | RR blocked by trespasser or vehicle strike by another train Held @ W. Sando a/c aAMTK 710 trespasser fatality strike @ MP 1157.3 |
| 712 | BFD | 40 | POL | 37 | POL | 37 | XPR-ACA | BN | RR blocked by trespasser or vehicle strike by another train Trespasser strike at mp1157.4 by train 710. Stopped at W PITTSBURG waiting for clearance. |
| 714 | BFD | 36 | PTI | 41 | FTI | 17 | TRK-MCD | BN | Follow SF8076, Milepost, 1079, 1056, SF8076 |

# Amtrak Endpoint OTP Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 11/4/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 715 | OKJ | 47 | PTI | 33 | PTI | 12 | MCD-TRK | BN | Wait for station track Shuffle out of siding into TRK station, AMT 714, Siding, Denair |
| 716 | BFD | 45 | ITI | 62 | ITI | 62 | OKJ-OKJ | UP | Late departure at initial terminal due to late arrival of inbound equipment 711 |
| 717 | OKJ | 134 | ITI | 65 | ITI | 65 | BFD-BFD | BN | Late departure at initial terminal due to late arrival of inbound equipment 702 |
| 718 | BFD | 20 | DCS | 23 | DCS | 23 | ACA-SKN | BN | Restrictive signal(s) from known wayside signal failure Flagging, Stop, Control Point, holt |
| 719 | OKJ | 117 | ITI | 107 | ITI | 107 | BFD-BFD | BN | Late departure at initial terminal due to late arrival of inbound equipment 712 |
| 3 | LAX | 54 | FTI | 100 | POL | 40 | GLP-GLP | BN | Removal of passenger by police |
| 4 | CHI | 356 | FTI | 400 | FTI | 101 | KNG-FLG | BN | Follow BNSF 7003 E, Milepost, 389.5, 344.8 |
| 21 | SAS | 94 | TRS | 175 | TRS | 175 | DAL-FTW | TE | Trespasser strike Control Point, EC JCT |
| 307 | STL | 34 | DCS | 20 | DCS | 13 | BNL-BNL | UP | Restrictive signal(s) from known wayside signal failure Stop, Control Point, X124 |
| 383 | QCY | 38 | WTR | 22 | WTR | 12 | MDT-PCT | BN | Wet / slippery rail Other, Princeton |
| 318 | CHI | 33 | FTI | 50 | FTI | 20 | LCN-BNL | UP | Meet up1498, Control Point, x124 |
| 319 | KCY | 70 | DMW | 57 | DMW | 57 | JEF-SED | UP | Hold for defect repair Held for broken rail, Control Point, 182.9 |
| 1333 | MSP | 116 | DCS | 47 | DCS | 47 | MKA-MKE | CP | Drawbridge stuck open CPKC could not get the bridge closed. faulty wire in the lift motor, had to wait for the part., Bridge, Menominee |

# Amtrak Initial Terminal Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/4/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| BON | 685 | 11/04 | 71 | | |
| BON | 687 | 11/04 | 126 | 6 | Late departure at initial terminal due to late arrival of inbound equipment 686 |
| BOS | 1135 | 11/04 | 67 | 67 | Late departure at initial terminal due to late arrival of inbound equipment, 1150, DP BOS 67" A/C OF LATE TURN OF AM1150 |
| BOS | 1165 | 11/04 | 52 | 52 | Late departure at initial terminal due to late arrival of inbound equipment, 1160, DP BOS 52" LATE A/C OF LATE TURN OF AM1160 |
| BOS | 1167 | 11/04 | 34 | 34 | Late departure at initial terminal due to late arrival of inbound equipment, 1162, DP BOS 34" LATE A/C OF LATE TURN OF AM1162 |
| CLT | 72 | 11/04 | 63 | 63 | Late departure at initial terminal due to late arrival of inbound equipment 71 |
| GFD | 479 | 11/04 | 45 | 45 | Late departure at initial terminal due to late arrival of inbound equipment 486, 486 late due to holding for connection in NHV |
| HAR | 626 | 11/04 | 2 | 2 | Passenger and/or baggage |
| LOR | 53 | 11/04 | 255 | 255 | Late departure at initial terminal due to late arrival of inbound equipment 52 |
| MIA | 40 | 11/04 | 9 | 9 | Set out defective car Swap Baggage cars last minute, 61014 |
| NFL | 284 | 11/04 | 16 | 16 | Restrictive signal(s) from unknown cause Stop, Control Point, 28 |
| NHV | 478 | 11/04 | 20 | 20 | Late departure at initial terminal due to late arrival of inbound equipment, 479, DP NHV 20" LATE A/C OF LATE TURN OF AM479 |
| NYP | 19 | 11/04 | 3 | 3 | Passenger and/or baggage, LOADING |
| NYP | 43 | 11/04 | 2 | 2 | Follow, AM1103, Other, NYP-NYP, HELD A/C AM1103 XING AHEAD |
| NYP | 63 | 11/04 | 8 | 8 | Passenger and/or baggage, HELD FOR PSGRS OFF LATE AM1150 |
| NYP | 283 | 11/04 | 8 | 8 | Electrical failure, 9705, COULDN'T DRAW POWER |
| NYP | 641 | 11/04 | 2 | 2 | Cross Traffic, NJT, NJ3221, Other, NYP-NYP, HELD A/C NJ3221 XING AHEAD |
| NYP | 1103 | 11/04 | 111 | 111 | Undesired emergency application, 622\|EX\|ES, SHOPPED ENG.622 FOR ENG.614 |
| NYP | 1107 | 11/04 | (Trn Cxld) | | Engine Issue |
| NYP | 1127 | 11/04 | 4 | 4 | Other late crew, CREW MEMBER LEFT ON PLATFORM |
| NYP | 2123 | 11/04 | 33 | 33 | Late departure at initial terminal due to late arrival of inbound equipment, 2106, LATE TURN FOR AM2106 |
| NYP | 2155 | 11/04 | 98 | | |
| PHL | 601 | 11/04 | 1 | 1 | Passenger and/or baggage |
| PHL | 653 | 11/04 | 1 | 1 | Wheelchair, WAITED FOR A WHEELCHAIR PER CNDR; 642P |
| PHL | 657 | 11/04 | 4 | 4 | Door, 82602\|AX\|AS |
| PHL | 1144 | 11/04 | 20 | 20 | Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF YARD |

# Amtrak Initial Terminal Details

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 11/4/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| PHL | 1150 | 11/04 | 29 | 29 | Planned set out / pick out of locomotives, cars or section of train, Late out from the yd. |
| SFA | 52 | 11/04 | 7 | 7 | Late departure at initial terminal due to late arrival of inbound equipment 53 |
| WAS | 1116 | 11/04 | 111 | 60 | For maritime traffic, Control Point, SASQUEHANNA RIVER BRIDGE, LATE TURN OFF 1103 DUE TO SUSQUEHANNA RIVER BRIDGE BEING OPEN |
| WAS | 1116 | 11/04 | 111 | 51 | Set out defective locomotive, 622\|EX\|ES, SHOPPED AND SET OFF IN NY REPLACED MTR 604 IN WASH. |
| WAS | 1194 | 11/04 | 35 | 35 | For maritime traffic, Control Point, SUSQUEHANNA RIVER BRIDGE, LATE TURN OFF 1111 DUE TO SUSQUEHANNA RIVER BRIDGE BEING OPEN |
| WAS | 2122 | 11/04 | 16 | 16 | Other late crew, CREW OFF LATE 2133 |
| CHI | 337 | 11/04 | 61 | 61 | Late departure at initial terminal due to late arrival of inbound equipment 336 |
| ARN | 529 | 11/04 | 1 | | |
| BFD | 701 | 11/04 | 4 | 4 | Hold for thruway bus |
| BFD | 703 | 11/04 | 79 | 79 | Late departure at initial terminal due to late arrival of inbound equipment 710 |
| BFD | 717 | 11/04 | 65 | 65 | Late departure at initial terminal due to late arrival of inbound equipment 702 |
| BFD | 719 | 11/04 | 107 | 107 | Late departure at initial terminal due to late arrival of inbound equipment 712 |
| GTA | 794 | 11/04 | 41 | 41 | Late departure at initial terminal due to late arrival of inbound equipment 777 |
| LAX | 566 | 11/04 | 47 | 47 | Late departure at initial terminal due to late arrival of inbound equipment 566, Late release from 8th street yard @ 08:21. Spot at LAX 08:46 |
| LAX | 588 | 11/04 | (Trn Cxld) | | Engine Issue |
| OKJ | 526 | 11/04 | 1 | 1 | Meet 11, Control Point, North Jack London |
| OKJ | 710 | 11/04 | 1 | 1 | Meet 525, Control Point, N Jack London |
| OKJ | 716 | 11/04 | 62 | 62 | Late departure at initial terminal due to late arrival of inbound equipment 711 |
| SAN | 587 | 11/04 | 1 | | |
| SAN | 595 | 11/04 | 27 | 27 | Late departure at initial terminal due to late arrival of inbound equipment 584 |
| SAN | 785 | 11/04 | 16 | 16 | Hold for connecting train 774 |
| SEA | 505 | 11/04 | 34 | 34 | Door 7310, Exterior door on west side not working correctly causing brakes to apply. Blue flags were dropped in the SEA yard at 9:05. |
| SJC | 542 | 11/04 | 1 | | |
| SJC | 550 | 11/04 | 1 | | |

# Eastern Region



## Commuter Services

| Service Type | OTP Goal | OTP Day | OTP MTD | OTP Prior Month | Trains Operated | Trains Late |
|---|---|---|---|---|---|---|
| MBTA | 95.0 | 99.1 | 99.3 | 99.14 | 342 | 3 |
| CDOT | 95.0 | 95.8 | 89.8 | 92.4 | 24 | 1 |
| MARC | 95.0 | No Data | No Data | 90.2 | No Data | No Data |
| SEPTA | 95.0 | No Data | No Data | 93.7 | No Data | No Data |
| NJT-NED | 95.0 | 89.6 | 90.5 | 88.6 | 211 | 22 |
| NJT-SED | 95.0 | No Data | No Data | 97.2 | No Data | No Data |

## Operating Highlights

### *Train 41(03) Columbia, SC - Freight Train Interference*

05NOV26: Train 41(03) operating with engines 341, 22, and 209 customers onboard was delayed departing Columbia, SC on the CSX Columbia subdivision holding for CSX freight U657-04 to finish working Cayce Yard. Once the freight cleared, train 41(03) proceeded south.

| Train | Delay | Comment |
|---|---|---|
| 41(03) | 1'50" | |

### *Train 52(04) South of Charleston, SC - System*

05NOV26: Train 52(04) operating with engines 348, 354, and 190 customers onboard was delayed 15 miles south of Charleston, SC on the CSX Charleston subdivision inspecting their equipment at milepost 402.0 after the engineer failed to hit the alerter in time causing the train to go into emergency. Upon inspection the crew took no exceptions and proceeded north.

| Train | Delay | Comment |
|---|---|---|
| 52(04) | 33" | |

### *Train 53(04) Lorton, VA - Initial Terminal Delay*

05NOV26: Train 53(04) operating with engines 360, 384, and 497 customers onboard was delayed departing Lorton, VA due to turn from late inbound 52(03).

| Train | Delay | Comment |
|---|---|---|
| 53(04) | 4'15" | |

### *Train 494(04) New Haven, CT - Hold for Connection*

04NOV26: Train 494(04) operating with engine 93 and 22 customers onboard was delayed departing New Haven, CT waiting on 12 connections from inbound 1194(04) which was operating late.

| Train | Delay | Comment |
|---|---|---|
| 494(04) | 50" | |

27-FOI-00137 0000000913A "UNCLASSIFIED" 11/10/2026

## *Train 41(03) South of Richmond, VA - Signal*

04NOV26: Train 41(03) operating with engines 241, 220 and 187 customers onboard was delayed 3.3 miles south of Richmond, VA on the CSX North End subdivision stopped at milepost 1.3 due to PTC system failure causing the PTC to become disengaged. The crew worked with the CSX dispatcher to reboot the system which resolved the issue.

| Train | Delay | Comment |
|---|---|---|
| 41(03) | 36" | |

## *Train 77(04) East of Salisbury, NC - Weather*

04NOV26: Train 77(04) operating with engines NC1810, NC102, and 84 customers onboard was delayed on the Norfolk Southern Danville District east of Salisbury, NC starting a milepost 313.0 due to PTC disengaging due to wheel slip caused by wet rail. Train 77(04) had to operate restricted speed to the next signal until milepost 333.0. Train 76(04) was delayed holding at Sumner milepost 336.0 to cross over once 77(04) passed.

| Train | Delay | Comment |
|---|---|---|
| 77(04) | 38" | |
| 76(04) | 30" | |

## *Train 686(04) North of Dover, NH - Trespasser Incident*

04NOV26: 123PM ET Train 686(04) with E/99 plus 6 cars carrying 71 passengers, struck a trespasser on the CSX Portland subdivision at MP 55.4. There were no reported injuries among the passengers or crew. The trespasser was a confirmed fatality. There was no reported damage to the equipment. This did not occur at a DOT grade crossing. The Weather at the time of incident was 69° and sunny. Amtrak Management and Amtrak Police responded to the incident scene. A recrew was summoned and took over the train's operation after it was cleared to depart by local police. Train 686(04) was released at 432PM ET. Two buses secured to accommodate customers for 687(04) and train 685(04) held at Boston, MA and operated on 687(04) schedule.

NRC # 1477837

**National Response Center Number: 1477837**

| Train | Delay | Comment |
|---|---|---|
| 687(04) | 2'06" | |
| 685(04) | 1'11" | |
| 686(04) | 1'54" | |

27-FOI-00137 00600009134 "UNCLASSIFIED" 11/10/2026

## *Train 1088(04) South of Philadelphia, PA - Trespasser Strike*

04NOV26: 123PM ET Train 1088(04) with E/62 locomotive carrying 333 passengers, struck a trespasser on the Amtrak Philadelphia to Washington Line at MP 14.3 on No 3 track. There were no reported injuries among the passengers or crew. The trespasser was a confirmed fatality. There was no reported damage to the equipment. This did not occur at a DOT grade crossing. The Weather at the time of incident was 72° and partly sunny. Amtrak Management and Amtrak Police responded to the incident scene. A recrew was summoned and took over the train's operation after it was cleared to depart by local police.

240pm The coroner arrived.

256pm APD released the hold on number 4 track at the scene and train movement via single tracking resumed.

336PM ET Train 1088(04) released and all tracks resumed to normal service and operating speed.

Multiple Amtrak trains incurred delay related to this incident.

NRC # 1477836

**National Response Center Number: 1477836**

| Train | Delay | Comment |
|---|---|---|
| 1099(04) | 55" | |
| 1147(04) | 1'15" | |
| 2149(04) | 1'24" | |
| 2133(04) | 1'48" | |
| 1161(04) | 34" | |
| 2116(04) | 34" | |
| 1194(04) | 27" | |
| 1140(04) | 1'43" | |
| 2114(04) | 1'57" | |
| 1088(04) | 2'18" | |

## *Train 40(03) South of Petersburg, VA - Freight Train Interference*

04NOV26: Train 40(03) was delayed beginning at MP102.5, south of Petersburg, VA station on the CSX North End subdivision meeting CSX freight trains 419 and 415.

| Train | Delay | Comment |
|---|---|---|
| 40(03) | 50" | |

## *Train 1160(04) East of Bridgeport, CT - Engine Failure*

04NOV26: Train 1160(04) was delayed at MP50.7, 5.1 miles east of Bridgeport CT station on the Amtrak New Haven Line due to BCU faults on engine 656. Crew spoke with mechanical and performed a hard recycle. After the recycle the brake pipe circuit was set and the faults were cleared. Train 1160(04) was back on the move at 1141AM ET.

| Train | Delay | Comment |
|---|---|---|
| 1160(04) | 1'16" | |
| 1165(04) | 52" | ITI |

27-FOI-00137 000000091134 "UNCLASSIFIED" 11/10/2026

## *Train 1144(04) East of Philadelphia, PA - Engine Failure*

04NOV26: Train 1144(04) P/614-10 Cmas-E/622 stopped 4.5 miles east of Philadelphia, PA (MP1.5), on the Amtrak NYP Line at North Philadelphia (MP85.0) due to a fault with rear engine 622. The engine was subsequently isolated, and the train continued to New York operating with a single locomotive, resulting in delays. Upon arrival in New York, engine 622 was shopped, which caused an initial terminal delay to Train 1103(04). At 10:52AM-ET, Train 1103(04) departed New York operating 1 hour and 51 minutes late operating single locomotive to Washington.

Train 1116(04) was delayed departing Washington, DC as a result late inbound Train 1103(04) and the necessity of adding engine 604 to fill out the consist.

Train 1116(04) was stopped at MP122.8 north of New Carrolton MD station with engine faults. Crew attempted to troubleshoot and clear faults but were unsuccessful. Train 1116(04) was cancelled and passengers were transferred to train 2122(04). As a result train 1107(04) was cancelled in it's entirety with no alternate transportation. Engine 642 was dispatched from Washington D.C. to rescue 1116(04) equipment to tow back to Washington.

| Train | Delay | Comment |
|---|---|---|
| 1144(04) | 21" | North Philadephia |
| 1144(04) | 29" | Enroute delays |
| 1103(04) | 1'51" | ITD NYP |
| 1107(04) | Cancelled | |
| 2122(04) | 52" | |
| 1116(04) | 1'51" | TERM NCR |
| 97(04) | 31" | |
| 80(04) | 39" | |

## *Amtrak PW Line North of Aberdeen, MD - Drawbridge Opening*

04NOV26: At 10:00AM-ET, the Susquehanna River Bridge opened for marine traffic 5.3 miles north of Aberdeen, MD (MP65.5) on the Amtrak PW Line. The bridge remained open until 11:19AM-ET, after which it was inspected and cleared for rail traffic to resume at 11:45AM-ET. As a result, Amtrak trains 1111(04), 1153(04), 2105(04), 1164(04), 2106(04), 1118(04), and 1082(04) incurred delays of up to two hours. Once the tracks were returned to service, southbound traffic was released through the area, followed by northbound traffic. The delays were exacerbated because all train movements were operating over a single track on Main Track 2 while Main Track 3 remained out of service for scheduled track work.

Train 1194(04) was delayed departing Washington, DC due to a late turn of Train 1111(04)'s equipment that arrived at 12:50PM, 1 hour and 24 minutes late.

Train 2123(04) was delayed departing New York, NY due to a late turn of Train 2106(04)'s equipment that arrived at 2:11pm, 1 hour and 17 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 1111(04) | 1'31" | |
| 1153(04) | 1'32" | |
| 2105(04) | 47" | |
| 1164(04) | 1'25" | |
| 2106(04) | 1'24" | |
| 1118(04) | 1'25" | |
| 1082(04) | 41" | |
| 1143(04) | 24" | |
| 2152(04) | 40" | |
| 1155(04) | 37" | |
| 1194(04) | 35" | ITD WAS - Turn of 1111(04) |
| 79(04) | 32" | Connections |
| 41(03) | 45" | Connections |
| 2123(04) | 33" | ITD NYP - Turn of 2106(04) |
| 486(04) | 1'25" | Connection 1164(04) |
| 1116(04) | 1'00" | |

27-FOI-00137 000000091134 UNCLASSIFIED 11/10/2026.

## Train 40(03) East of Raleigh, NC - Vehicle on the Tracks

04NOV26: Train 40(03) was delayed holding at MP93.6/12.8 miles east of Raleigh NC station on the Norfolk Southern Goldsboro Greensboro subdivision due to a semi truck on the tracks at MP96. A tow truck arrived on scene and removed the semi from the tracks. Maintainers arrived on scene and released the tracks. Train 40(03) was back on the move at 1036AM ET.

| Train | Delay | Comment |
|---|---|---|
| 40(03) | 1'02" | |

## Train 98(04) South of Sebring, FL - Freight Train Interference

04NOV26: Train 98(04) was held 57.1 miles south of Sebring, FL (MP867.2) on the CSX Auburndale Subdivision while meeting CSX M453-03 at Zana (MP924.3). The delay was extensive due to all sidings ahead occupied, limiting available meet locations and resulting in extended holding time.

| Train | Delay | Comment |
|---|---|---|
| 98(04) | 1'01" | |

## Train 2149(04) East of New Haven, CT - Engine Failure

04NOV26: Train 2149(04) was delayed at MP93.67, 25.3 miles east of New Haven, CT station on the Amtrak NHB line due to multiple faults on engine 2144. Crew spoke with Alstom mechanical and cut out the front axle on the front bogie on engine 2144. Train 2149(04) was back on the move operating at reduced max speed of 40 miles per hour. 2149(04) was stopped again at MP92.15 inspection for flat spots in the consist. Crew found a flat spot less than 2.5 inches on the fireman's side front axle.

| Train | Delay | Comment |
|---|---|---|
| 2149(04) | 1'36" | |

## Train 71(04) Raleigh, NC - Engine Failure

04NOV26: Train 71(04) was delayed at MP79.3, 1/6 miles west of Raleigh NC station on the Norfolk Southern Goldsboro Greensboro subdivision due to sander on engine 1984 not working. Train 71(04) reversed to Raleigh NC station and was met by mechanical to troubleshoot. Mechanical found a bad sanding solenoid on engine 1984. Once the solenoid was replace the sander was operational. Train 71(04) departed Raleigh, NC for the second time at 805AM ET operating 1 hour and 50 minutes late. Train 72(04) was delayed departing Charlotte NC station due to late turn of train 71(04).

| Train | Delay | Comment |
|---|---|---|
| 71(04) | 1'56" | |
| 72(04) | 1'03" | ITI |

## Train 1164(04) South of Richmond, VA - Tie Fire

04NOV26: Train 1164(04) was delayed holding at MP60.6, 24.5 miles south of Richmond, VA station on the CSX Peninsula subdivision due to a tie fire on the tracks ahead. The fire was extinguished and the tracks were released. Train 1164(04) was back on the move at 532AM ET.

| Train | Delay | Comment |
|---|---|---|
| 1164(04) | 43" | |
| 486(04) | 1'25" | Connections 1164(04) |

27-FOI-00137 09000009164 UNCLASSIFIED 11/10/2026

## Train 41(02) South of Savannah, GA - Passenger Train Interference

04NOV26: Train 41(02) was delayed beginning at MP503, south of Savannah, GA station on the CSX Savannah subdivision following Amtrak train 53(03) until MP543.

| Train | Delay | Comment |
|---|---|---|
| 41(02) | 35" | |

## Train 53(03) Savannah, GA - Freight Train Interference

04NOV26: Train 53(04) was delayed beginning at MP477.6, north of Savannah, GA station/MP491.0 on the CSX Charleston subdivision following CSX freight train 31.

| Train | Delay | Comment |
|---|---|---|
| 53(03) | 30" | |

## Northeast Regional Crescent and Cardinal NS Track Work - 11/21-11/22 TWA 27-

04NOV26: On November 22, 2026, Norfolk Southern will perform signal system upgrade and testing work on the Washington District between MP 9 and MP 19. As a result, Northeast Regional, Crescent, and Cardinal service will be modified.

Northeast Regional
Train 147(21NOV) will terminate at Washington, DC Union Station. Bus 5147 will provide alternate transportation between Washington, DC Union Station and the Roanoke, VA station.
Train 156(22NOV) will originate at Washington, DC Union Station. Bus 5156 will provide alternate transportation between the Roanoke, VA station and Washington, DC Union Station.

Crescent
Train 220(21NOV) will operate in lieu of Train 20(21NOV), departing New Orleans, LA Union Passenger Terminal at 12:40P-CT. The train will operate 3 hours and 30 minutes later between New Orleans and Baltimore, MD Penn Station and 3 hours and 40 minutes later between Baltimore and New York, NY Penn Station.

Cardinal
Train 51(22NOV) will depart New York, NY Penn Station at 10:40A-ET and operate 4 hours later between New York and Chicago, IL Union Station.

**WBS#: B.TR.100150.7326**

# Maintenance of Way Highlights

## *Piedmont and Carolinian NS Track Work - 10/26-10/29 - 11/2-11/5 TWA 24-016*

37EQI-00137 0000009134 "UNCLASSIFIED" 01/10/2026

26AUG26: The NS / NC Line trackwork between MP NC 0.6 and MP NC 31.6 for Rail Pick up and Switch Replacement occurring between 900A-ET and 600P-ET on Monday, October 26 to Thursday, October 29 and Monday, November 2 to Thursday, November 6. To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

· Train 72 (26Oct-29Oct, 2Nov-5Nov), which normally operates between CLT and RGH, will terminate at GRO.

· Train 74 (26Oct-27Oct, 2Nov-3Nov), which normally operates between CLT and RGH, will terminate at GRO.

· Train 74 (28Oct-29Oct, 4Nov-5Nov) will operate 10-minutes Earlier between CLT and BNC, and 8-minutes Earlier between DNC and RGH.

· Train 76 (26Oct-27Oct, 2Nov-3Nov) will operate 30-minutes Later between CLT and GRO, add a BNC stop at 7:21pm, and operate 34-minutes Later between DNC and RGH.

· Train 76 (28Oct-29Oct, 4Nov-5Nov) will operate 30-minutes Later between CLT and RGH, departing CLT at 5:35pm.

WESTBOUND

· Train 71 (26Oct-29Oct, 2Nov-5Nov) will operate 15-minutes Earlier, departing RGH at 6:15am.

· Train 73 (26Oct-29Oct, 2Nov-5Nov) will depart RGH 55-minutes Earlier, at 9:05am, and operate on an earlier schedule between RGH and CLT. See schedule grid below.

· Train 75 (26Oct-27Oct, 2Nov-3Nov), which normally operates between RGH and CLT, will originate at GRO, departing 14-minutes Later at 2:34pm.

· Train 75 (28Oct-29Oct, 4Nov-5Nov), which normally operates between RGH and CLT, will originate at GRO.

· Train 77 (26Oct-27Oct, 2Nov-3Nov), which normally operates between RGH and CLT, will originate at GRO, departing 44-minutes Later at 5:35pm.

· Train 77 (28Oct-29Oct, 4Nov-5Nov) will operate 30-minutes Later between RGH and CLT, departing RGH at 3:45pm.

ALTERNATE TRANSPORTATION:

· Bus 3172 (26Oct-29Oct, 2Nov-5Nov) will provide alternate transportation between GRO and RGH making all stops except BNC.

· Bus 3174 (26Oct-27Oct, 2Nov-3Nov) will provide alternate transportation between GRO and RGH making all stops except BNC.

· Bus 3175 (26Oct-29Oct, 2Nov-5Nov) will provide alternate transportation between RGH and GRO making all stops except BNC.

· Bus 3177 (26Oct-27Oct, 2Nov-3Nov) will provide alternate transportation between RGH and GRO making all stops except BNC.

**WBS#: B.TR.100150.7292**

27-FOI-00137 000000009134 UNCLASSIFIED 11/10/2026

## *Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work*

26OCT26: Due to the Veltri conditions outages on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

# Eastern Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| None | | | | |
| | | | | |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| None | | | | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Eastern Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| Train | Projected Need Cars | Projected Need Seats | Number Operated Cars | Number Operated Seats | Standees | Location |
|---|---|---|---|---|---|---|
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

# Western Region
# Operating Highlights

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

## *Train 59(04) Carbondale, IL - Debris*

05NOV26: At approximately 3:45 a.m. ET, Train 59(04), operating with Engine 23, seven coaches, and 114 customers, struck an animal at Milepost 327.6 on the CN Centralia Subdivision south of Carbondale. Following the incident, the train was brought to a stop to allow the crew to inspect the train's hoses and cables for any damage. After completing the inspection and confirming that it was safe to proceed, the train resumed movement.

| Train | Delay | Comment |
|---|---|---|
| 59(04) | 15" | |

## *Train 519(04) South of Vancouver, BC - Police Related*

05NOV26: Train 519(04) was delayed at Mud Bay West/ MP131.8 on the BNSF New Westminster Subdivision, 24.8 miles south of Vancouver, B.C. due to a police hold on the tracks account of an active investigation of a body found near MP124.9. Train 518(04) was also delayed, holding at Aldergrove/ MP108. Once the police hold was lifted, Train 519(04) was able to proceed, followed by Train 518(4).

| Train | Delay | Comment |
|---|---|---|
| 519(04) | 4'01" | |
| 518(04) | 1'49" | |

27-FOI-00137 00000009134 "UNCLASSIFIED" 1/10/2026

## *Train 782(04) Terminated East of Simi Valley, CA - Engine Failure*

05NOV26: Train 782(04) with C6003-5 cars E/C2118, was delayed upon departing Simi Valley, CA, coming to a stop three cars off the platform. Crew reported the engine E/C2118 had shut down with no Head-end power (HEP), and a fuel filter fault. Crew worked with Mechanical to troubleshoot, rebooted and were able to restore HEP and load the engine. After departing, the train came to a stop at MP440.3 on the SCRRA-Metrolink Ventura Subdivision, approximately 3 miles east of the station, with the same issue. This was the third time this engine had shut-down since departing with a recurring fuel filter fault; the first incident was 4 miles south of Goleta at MP362.4. The crew was able to reboot again, restoring H.E.P. but was deemed unreliable to proceed and was terminated at location.

Train 782(04) shoved into Davis siding to wait for 786(04) to rescue. Upon arrival, Train 786(04) was coupled to the rear of Train 782(04) disabled consist. With approximately 177 customers remaining aboard both equipment sets with Head-End Power (HEP) supplied by locomotive E/C2114. After multiple attempts to proceed, both sets of equipment continued to receive power issues. Train 790(04) was delayed at Davis waiting for the double set to clear the main. The onboard crew reached hours-of-service limits at 8:13PM PT, and a relief crew arrived at 8:23PM PT with mechanical to take equipment east. The combined train was then advanced to Van Nuys station, transferred all customers from the combined Train 782/ 786(04) equipment to Train 794(04) that was directly behind them. The combined equipment was then deadheaded to Los Angeles.

Due to this, Train 786(04) had an on-time make-up section between Los Angeles and San Diego. Trains 593(04), 588(04) and 567(05) were cancelled in entirety. Service recovery was implemented on both Trains 786 and 782, with onboard personnel distributing available revenue items and worked to keep customers comfortable. Two unaccompanied minors traveling on Train 782(04) to Anaheim required an onboard welfare check by the relief crew. Parents arrived at location to retrieve both unaccompanied minors with police assistance.

**WBS#: B.TR.100150.7327**

| Train | Delay | Comment |
|---|---|---|
| 782(04) | 24" | S/GTA |
| 782(04) | 22" | Terminated E/SIM |
| 786(04) | 5'28" | Rescue 782 |
| 794(04) | 1'11" | |
| 790(04) | 54" | |

## *Train 3(03) West of Winslow, AZ - Freight Train Interference*

05NOV26: Train 3(03), operating with engines 79/192, 9 coaches, and 164 customers, was delayed 11 miles west of Winslow, AZ, on BNSF Seligman subdivision due to following unknown BNSF freight train from milepost 297.6 to milepost 329.5. Once the freight cleared and a route was made available, train 3(03) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 3(03) | 56" | |

## *Train 717(04) East of Antioch-Pittsburg, CA - Freight Train Interference*

05NOV26: Train 717(04), operating with engine 2013, 8 coaches, and 65 customers, was delayed 1.5 miles east of Antioch-Pittsburg station, on BNSF Stockton subdivision, due to meeting multiple freights at control point west sando. Once the freights cleared and a route was made available, train 717(04) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 717(04) | 38" | |

27-FOI-00137 0000009134 UNCLASSIFIED 11/10/2026

## Train 509(04) Tacoma, WA - Trespasser Incident

05NOV26: Train 509(04), operating with engine 1886, 4 coaches, and 101 customers, was delayed departing Tacoma, WA, on SDRX Lakewood subdivision, due to a vehicle stuck on the tracks ahead at milepost 4.3. local police responded with a tow truck to remove the vehicle. Once the tracks were inspected, train 509(04) was able to depart. Train 509(04) subsequently operated at restricted speed through the affected area.

Train 14(03), operating with 123 customers, was also delayed holding south of Tacoma, WA, at milepost 7.2, holding for an open route.

| Train | Delay | Comment |
|---|---|---|
| 509(04) | 31" | |
| 14(03) | 41" | |

## Train 319(04) East of Sedalia, MO - M of W Work

04NOV26: Train 319(04), operating with engine 4607, 7 coaches, and 88 customers, was delayed 6 miles east of Sedalia, MO, on UPRR Sedalia subdivision, at milepost 182.8, due to a broken rail reported by UPRR. They dispatched Maintenance of Way to address the broken rail and train 319(04) held while the repairs were completed.

Train 316(04), with 56 customers, was delayed meeting train 319(04) and a UP freight in the area.

| Train | Delay | Comment |
|---|---|---|
| 319(04) | 57" | |
| 316(04) | 21" | |

## Train 8/28(03) West of Glasgow, MT - Freight Train Interference

05NOV26: Train 8/28(03), operating with engines 301/381, 10 coaches, and 119 customers, was delayed 1 mile west of Glasgow, MT, on BNSF Glasgow subdivision, due to following and then meeting BNSF6426 at Oswego Siding. Once the freight was clear and a route was made available, train 8/28(03) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 8/28(03) | 33" | |

## Train 352(04) West of Kalamazoo, MI - Defect Detector Actuation

04NOV26: Train 352(04), operating with engine 4610, 5 coaches, and 170 customers, was delayed 17 miles west of Kalamazoo, MI, on Amtrak Michigan Line, due to activating a hot box detector, which required an inspection of the equipment. The crew inspected the affected car (ID4214) and found no exceptions. They then operated the next 10 miles at a reduced speed of 50mph.

| Train | Delay | Comment |
|---|---|---|
| 352(04) | 41" | |

## Trains 20(04) and 19(03) North of Meridian, MS - Freight Train Interference

04NOV26: Train 20(04) was delayed 40.3 miles north of Meridian, MS (MP295.0), on the NSRR AGS South Subdivision at Parker (MP254.7) due to freight interference. NS 131-04 had experienced earlier locomotive issues that blocked the main line before clearing into the siding at Miller (MP244.28). Once traffic resumed movement, Train 20(04) was required to meet southbound NS 29S-04, NS 355-04, and Train 19(03) before continuing north, resulting in additional delay.

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

## Trains 1333(04) and 336(04) Milwaukee, WI - B&B Work Due to Defect

04NOV26: Trains 1333(04) and 336(04) were delayed on the CPRR C&M Subdivision while awaiting a B&B response to a defect on the Menomonee Bridge (MP85.1), located 0.3 miles east of the Milwaukee, WI station (MP85.4). Train 1333(04) was held at MP84.7, while Train 336(04) was held at the Milwaukee station. Once B&B personnel seated and locked the bridge, both trains resumed movement.

Train 337(04) was delayed departing Chicago, IL due to a late turn of Train 336(04)'s equipment.

| Train | Delay | Comment |
|---|---|---|
| 1333(04) | 47" | |
| 336(04) | 1'06" | |
| 337(04) | 1'01" | ITD CHI - Turn of 336(04) |

## Train 24(04) South of Bay Saint Louis, MS - Passenger Train Interference

04NOV26: Train 24(04) held 13.6 miles south of Bay Saint Louis, MS (MP754.5), on the CSX NO&M Subdivision, at Claiborne (MP768.1) in order to meet Train 23(04).

| Train | Delay | Comment |
|---|---|---|
| 24(04) | 30" | |

## Train 5(03) West of Denver, CO - Signal

04NOV26: Train 5(03) was delayed beginning at East Portal (MP48.9), located 48.9 miles west of Denver, CO (MP0.0), on the UPRR Moffat Tunnel Subdivision due to a track occupancy light ahead between West East Portal (MP50.1) and East Winter Park (MP56.6). As a result, Train 5(03) was required to flag through the affected territory, resulting in delay. Once the train cleared the affected area, normal track speed resumed.

| Train | Delay | Comment |
|---|---|---|
| 5(03) | 30" | |

## Train 504(04) North of Oregon City, OR - M of W Work

04NOV26: Train 504(04), operating with 69 customers on board, was delayed starting at MP 760.6, 6 miles north of Oregon City, OR, on the UPRR Brooklyn Subdivision due to a broken rail ahead. The crew held at Clackmas/MP 760.6 for the track inspector to respond. Once the track inspector was on site, they were able to operate at restricted speed over the affected area.

Train 503(04) was also delayed being walked over the affected area.

| Train | Delay | Comment |
|---|---|---|
| 504(04) | 39" | |
| 503(04) | 33" | |

27-FOI-00137 : 00000009134 UNCLASSIFIED 11/10/2026

## *Train 21/421(03) East of Fort Worth, TX - Trespasser Incident*

04NOV26: At approximately 12:51PM-CT, Train 21/421(03), operating with engine 312 and 8 cars, struck a trespasser at MP 635.7 on the Trinity Railway Express Main Line Subdivision in Irving, TX, Dallas County, 24.3 miles east of the Fort Worth, TX station (MP611.4). Weather conditions were reported as 75°F and sunny, and head-end power remained operational. The crew inspected the train and determined the trespasser was deceased. The train was operating at 75MPH on Main Track 1 at the time of the incident, which did not occur at a crossing. There were no injuries to the crew or 138 customers onboard. There was no damage damage to the equipment. Local police, fire, emergency medical services, and the medical examiner responded to the scene. The crew requested trauma relief, and the relief crew was transported to the location by the Fort Worth Road Foreman of Engines, arriving at 2:15PM-CT. Both main tracks were shut down while authorities conducted their investigation. At 3:47PM-CT both main tracks were reopened with Train 21/421(03) resuming movement westward.

During this time, Train 22(04) with 68 customers onboard, was held at the Fort Worth station for open track to be established.

**National Response Center Number: 1477832**

| Train | Delay | Comment |
|---|---|---|
| 21/421(03) | 2'55" | |
| 22(04) | 2'52" | |

## *Train 566(04) Los Angeles, CA - Cab Car Failure*

04NOV26: Train 566(04), E/C2120-5 cars-CC/9700, was delayed departing Los Angeles, CA due to CC/9700 being bad ordered and needing to be replaced with CC/C6951. Once the bad ordered cab car was removed and replaced with CC/C6951, mechanical was able to continue servicing the equipment. After mechanical released the equipment at 8:21A-PT, the equipment was brought to the station for boarding. At the station, the crew boarded all customers and performed a brake test then departed Los Angeles.

| Train | Delay | Comment |
|---|---|---|
| 566(04) | 47" | |

## *Train 505(04) Seattle, WA - Car Failure*

04NOV26: Train 505(04), CC/7911-12 cars- E/WS1403, was delayed departing Seattle, WA due to issues with the door on C/7310 causing brake issues. Mechanical worked to resolve air issues and released the equipment at 9:05A-PT. Once equipment was released, the crew had to take the equipment to the station for boarding. After all customers were boarded and brake test was complete, Train 505(05) departed Seattle.

| Train | Delay | Comment |
|---|---|---|
| 505(04) | 34" | |

# *Train 710(04) West of Antioch-Pittsburg, CA - Trespasser Incident*

27-FOI-00137 00000009184 "UNCLASSIFIED" 11/10/2026

04NOV26: At 9:15 AM-PT, Train 710(04), consisting of E/C2009- 7 cars- CC/C2101, with 59 customers onboard, went into emergency approximately 5 miles west of Antioch-Pittsburg, CA at MP 1157.3 on the BNSF Stockton Subdivision after fatally striking a trespasser. No injuries were reported to the crew or customers, and no damage was reported to the equipment. The crew requested relief. An Amtrak Road Foreman responded to scene arriving at 10:10 AM-PT. EMS and local law enforcement also responded. The coroner arrived on scene at 10:45 AM-PT to begin investigation. The Amtrak Road Foreman on scene worked to clear the siding for movement around the affected area. Train 711(04) was held at MP 1150.3, arriving at 11:13A-PT and Train 712(04) was held at MP 1158.3 arriving at 11:33A-PT. The relief conductor arrived on scene at 11:44A-PT with the relief engineer still en route. All rail traffic was reopened at 11:53A-PT where trains were moved around affected area through a siding. Due to the location, a train to train transfer was not feasible, so the customers on Train 710(04) remained on board until the relief engineer arrived. Train 712(04) was first through the area, followed by Train 711(04). Once the recrew engineer arrived at 12:40P-PT and performed a crew briefing, Train 710(04) was able to proceed east.

Train 719(04) was delayed departing Bakersfield, CA due to the late operation of Train 710(04). The turn of equipment was swapped around due to Train 712(04) being released prior to Train 710(04). Once the equipment from Train 712(04) arrived into Bakersfield and was serviced, the crew performed a job briefing then was able to depart Bakersfield.

NRC # 1477820

CA # 26-5711

**National Response Center Number: 1477820**

| Train | Delay | Comment |
|---|---|---|
| 712(04) | 37" | |
| 711(04) | 1'05" | |
| 710(04) | 2'02" | Re-crew |
| 710(04) | 2'03" | |
| 703(04) | 1'19" | ITD BFD - Equip off 710 |
| 716(04) | 1'00" | ITD OKJ - Equip off 711 |
| 719(04) | 1'47" | ITD BFD- Equip off 712 |

27,FOI-00137 0000D009134 "UNCLASSIFIED" 11/10/2026

## *Amtrak PTC Outage*

04NOV26: At 12:28P-CST, trains operating on Amtrak property experienced Positive Train Control "Red Fence" conditions on I-ETMS territory, resulting in emergency brake applications. The system was restored at 12:40P-CST after WabTec rested AS0 (Application Subsystem) on their side. The following trains were delayed:

Amtrak
-Train 365(04), E/ID4617-6 Cars-E/ID4606 with 151 customers onboard, was delayed on Chicago South at 21st Street (MP1.64).
-Train 300(04), E/ID4627-5 Cars and 135 customers onboard, was delayed south of Chicago at CP Lumber (MP1.46).
-Train 351(04)'s inbound equipment was delayed wyeing for turn of Train 305(04). There was no delay to Train 305(04).
-An Amtrak yard job in New Orleans.

Commuter
-Metra 816 on Chicago South.

Norfolk Southern Freight
-NS880 on Chicago South.
-NSB17 on Michigan East.
-NSB33 on Michigan East.
-NSB02 on Michigan West.

| Train | Delay | Comment |
|---|---|---|
| 365(04) | 43" | 21st Street |
| 300(04) | 06" | CP Lumber |

## *Train 702(02) North of Lodi, CA - Freight Train Interference*

04NOV26: Train 702(04) was delayed at Elk Grove/MP 54.7, 17 miles north of Lodi, CA, on the UPRR Fresno Subdivision due to UPRR freight MFRRV-04 (UP2647) ahead with air issues. The crew held while the freight crew inspected equipment. The freight crew found a bad air gasket and a car with the brakes set up. Once the freight crew resolved those issues, they pulled up to clear the route. After the route was clear, Train 702(04) proceeded south.

| Train | Delay | Comment |
|---|---|---|
| 702(02) | 1'36" | |

27-FOI-00137 00000009134 "UNCLASSIFIED" 1/10/2026

## BNSF Fallbridge Subdivision West of Pasco, WA- Freight Derailment

04NOV26: At 7:30A-PT, the BNSF reported BNSF freight train H-VAWPAS1-03 derailed while entering the Plymouth Siding/ MP 192.8 on the BNSF Fallbridge Subdivision, 40 miles west of Pasco, WA. Initial reports were 9 cars and 2 locomotives on the ground blocking the main line. At 7:16A, Train 27(02), with 82 customers on board, stopped at MP 202.7 and held for disposition. Due to the length of delay anticipated, Train 27(02) shoved back the 29.1 miles to Pasco where 2 buses were sourced to accommodate the 82 affected customers between Pasco and Portland, OR. Train 27(02) arrived back to Pasco at 9:06A-PT and was terminated. The buses were on site at 9:00A-PT for customers to transfer to their final destinations. With the assistance of BNSF pilots, the equipment was wyed at Pasco then deadheaded to Spokane, WA for servicing. Train 28(04) originated in Spokane with 2 buses sourced for the 72 affected customers traveling between Portland and Spokane.

Due to the alternate bus transportation for Train 28(04), service recovery was initiated with all coach customers provided with Popeyes chicken. All sleeper car customers were provided regular scheduled meals. Emergency water was placed on the buses for customers as needed.

At 11:00PM-PT, BNSF reported the main line was returned to service.

| Train | Delay | Comment |
|---|---|---|
| 27(02) | Term PSC | |
| 28(04) | Orig SPK | |

## Train 301(04) South of Joliet, IL - Engine Failure

05NOV26: Train 301(04), operating with engine 4613, 5 coaches and 114 customers was delayed operating between Joliet, IL, and Saint Louis, MO, on UPRR Joliet subdivision due to operating with XITCS cut out. This required the train to operate at a maximum speed of 79MPH. 301(04) equipment was then used for train 306(04) which also operated with XITCS cut out while operating between Saint Louis, MO, and Joliet, IL.

| Train | Delay | Comment |
|---|---|---|
| 301(04) | 29" | |
| 306(04) | 27" | |

## Train 711(04) Wasco, CA - M of W Work

04NOV26: Train 711(04), with 51 customers on board, was delayed departing Wasco, CA/ MP 913.0 on the BNSF Bakersfield Subdivision due to a maintenance of way crew ahead at MP 942.02, 8 miles east of Corcoran, CA, overstaying their work window. The crew held at the station in Wasco for the maintenance of way crew to complete work. Once the maintenance of way crew completed their work, Train 711(04) advanced to MP 942.02 to hold for the crews to clear the tracks. After the tracks were clear, Train 711(04) proceeded west.

| Train | Delay | Comment |
|---|---|---|
| 711(04) | 33" | Hold WAC |
| 711(04) | 37" | Hold E/ COC |

## Train 6(03) West of Salt Lake City, UT - Passenger Train Interference

04NOV26: Train 6(03) was delayed at MP 744.8, just west of Salt Lake City, UT, on the UPRR Provo Subdivision due to the meet with Train 5(02). The crew on Train 6(03) held just west of Salt Lake City for the crew on Train 5(02) to perform station work and clear route. Once route was cleared, Train 6(03) was able to proceed into the station to begin their station work.

# *UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority*

27-FOI-00137 000000009134 "UNCLASSIFIED" 11/10/2026

16OCT26: The UPRR placed engineering orders in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected area due to signal issues where crews operated at restricted speed and stopped to flag crossings.

17OCT26: In order to minimize customer delays due to this, the following Service Adjustments were implemented:

Train 761(17) and 765(17) were originated at Los Angeles, CA, no alternate transportation provided.
Trains 757/ 765/ 777(17-01NOV) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-01NOV) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

23OCT26: The operating plan was extended through at least Sunday November 1.

30OCT26: The operating plan was extended to Friday November 6th.

04NOV26: The operating plan was extended to Friday November 15th.

**WBS#: B.TR.100150.7278**

| Train | Delay | Comment |
|---|---|---|
| 774(16) | 1'39" | |
| 757(16) | 1'34" | |
| 786(16) | 1'35" | ITD SLO- Turn of 757(16) |
| 786(16) | 1'35" | ITD SLO- Equip off 757 |
| 765(16) | 1'22" | |
| 794(16) | 38" | ITD SLO- Equip off 765 |
| 794(16) | 2'08" | |
| 14(16) | 2'21" | |
| 786(16) | 2'57" | |
| 11(15) | 1'23" | |
| 14(17) | 1'13" | |
| 11(16) | 1'51" | |
| 11(17) | 1'15" | |
| 14(18) | 1'19" | |
| 14(19) | 1'01" | |
| 11(18) | 1'08" | |
| 11(19) | 1'10" | |
| 14(20) | 1'40" | |
| 11(19) | 51" | waiting for & meeting 14(20) at Tangair |
| 14(21) | 40" | |
| 11(20) | 1'05" | meet 14(21) |
| 11(20) | 1'14" | |
| 11(21) | 1'02" | |
| 14(22) | 59" | |
| 11(22) | 1'51" | |
| 14(23) | 1'03" | |
| 782(23) | 48" | |
| 14(24) | 1'03" | |
| 11(25) | 1'52" | |
| 14(27) | 1'31" | |
| 11(26) | 1'29" | |
| 11(28) | 1'11" | |
| 14(28) | 1'07" | |
| 14(29) | 45" | |
| 11(29) | 1'00" | |
| 14(31) | 1'02" | |
| 11(30) | 1'21" | |
| 14(01) | 1'24" | |
| 11(31) | 1'05" | |
| 14(02) | 1'00" | |
| 11(01) | 1'15" | |
| 14(03) | 51" | |

## *NCTD San Diego Subdivision East of San Clemente Pier, CA - Signal Issues*

31OCT26: Ongoing signal issues on the NCTD San Diego Subdivision due to high tides requires trains to flag between San Clemente Pier, CA and Oceanside, CA. The single-track conditions that exist also creates congestion through the area causing further delay to trains that operate through the area.

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

03NOV26: Train 572(03) and Train 579(03) were canceled due to the late arrival of inbound Train 567(03) which was operating 2 hours late from the train interference caused by the signal outage between San Clemete Pier and Oceanside.

The 79 customers scheduled for Train 572(03) were accommodated on Train 774(03).
The 89 customers scheduled for Train 579(03) were accommodated on Train 581(03).

| Train | Delay | Comment |
|---|---|---|

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

```
562(31)  32"
765(31)  17"
564(31)  52"
566(31)  45"
769(31)  54"
573(31)  28"
770(31)  47"
774(31)  58"
572(31)  14"
777(31)  15"
579(31)  46"
785(31)  14"
581(31)  1'02"
587(31)  49"
591(31)  50"
580(31)  11"
782(31)  46"
584(31)  1'14"
786(31)  24"
588(31)  21"
593(31)  1'06"
595(31)  1'02"
790(31)  11"
794(31)  24"
562(01)  22"
567(01)  32"
769(01)  47"
564(01)  59"
566(01)  1'13"
573(01)  27"
777(01)  22"
572(01)  21"
579(01)  47"
774(01)  41"
581(01)  1'02"
785(01)  26"
587(01)  48"
580(01)  22"
782(01)  52"
591(01)  51"
584(01)  1'15"
593(01)  1'03"
786(01)  13"
588(01)  1'04"
790(01)  12"
595(01)  1'01"
794(01)  17"
761(02)  17"
765(02)  12"
567(02)  13"
769(02)  22"
562(02)  12"
564(02)  33"
573(02)  19"
777(02)  21"
566(02)  43"
770(02)  15"
572(02)  16"
581(02)  16"
774(02)  11"
785(02)  22"
587(02)  16"
580(02)  11"
782(02)  12"
591(02)  22"
584(02)  21"
786(02)  11"
588(02)  38"
794(02)  17"
790(02)  12"
595(02)  1'38"  SAN Turn of Late Inbound 584(02) and Delay between SOL and SNC
593(02)  2'09"  SAN Turn Late Inbound 782(02) and Delay between SOL and SNC
761(03)  22"
567(03)  1'56"
765(03)  1'14"
562(03)  1'34"
```

| Train | Delay | Comment |
|---|---|---|
| 770(03) | 50" | |
| 573(03) | 1'51" | SAN Late Inbound 562 and SOL to SNC Delays |
| 777(03) | 31" | |
| 774(03) | 36" | |
| 581(03) | 14" | |
| 785(03) | 16" | |
| 587(03) | 37" | |
| 580(03) | 13" | |
| 782(03) | 29" | |
| 591(03) | 18" | |
| 584(03) | 20" | |
| 593(03) | 13" | |
| 595(03) | 48" | |
| 786(03) | 16" | |
| 588(03) | 21" | |
| 790(03) | 16" | |
| 794(03) | 20" | |
| 566(04) | 11" | |
| 562(04) | 32" | |
| 564(04) | 24" | |
| 770(04) | 23" | |
| 572(04) | 33" | |
| 761(04) | 19" | |
| 765(04) | 19" | |
| 567(04) | 16" | |
| 573(04) | 15" | |
| 769(04) | 20" | |
| 579(04) | 18" | |
| 587(04) | 30" | |
| 777(04) | 1'03" | |
| 581(04) | 12" | |
| 785(04) | 17" | |
| 774(04) | 29" | |
| 580(04) | 10" | |
| 584(04) | 56" | |
| 786(04) | 11" | |
| 794(04) | 41" | ITD GTA - Equip off 777 |

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

## *BNSF Gallup Subdivision East of Winslow, AZ- Southwest Chief Service Disruption*

23OCT26: A severe storm with isolated showers and thunderstorms impacted the area between Gallup, NM and Albuquerque, NM bringing flash floods and reduced operating conditions. At 9:50A-PT, the BNSF reported flash floods on the Gallup Subdivision with confirmed water over the rails at MP 77.9, 80 miles east of Gallup, NM . Multiple freights were tied down with crews expired on hours of service between Laguna/MP 71.1 and Grants/MP 98.3 causing single tracking conditions over 100 miles. BNSF maintenance of way personnel responded to areas of potential water of the rails to inspect. Substantial delays were incurred operating through the affected area.

Train 4(22), with 159 customers on board, arrived into Winslow, AZ at 9:42A-PT and held for open track. While holding in Winslow, and in anticipation of further delay, the crew performed a calendar day inspection. Once a route was open, Train 4(22) proceeded east incurring further delay at MP 253.4, holding for the recrew to arrive and conduct a job briefing. Upon completion of their job briefing, Train 4(22) proceeded east.

Train 3(22) was also delayed operating through the affected area by high winds, flash floods, and freight meets.

24OCT26: Due to the late operation of Train 3(22), the crew expired on hours of service holding in Flagstaff, AZ. Train 3(22) held at Flagstaff with pilots on board beginning at 1:55A-PT for the recrew to arrive from Train 4(23), arriving at approximately 4:30A-PT. Once the recrew arrived and conducted their job briefing, Train 3(22) proceeded west.

To support customers and provide service recovery on Train 4(22), complimentary food and beverage offerings were provided. All coach customers received complimentary snack packs, bottled water, and hot beverages. During lunch service, sleeping car customers received the regular lunch service in the Dining Car, while coach customers were provided complimentary beef stew, mashed potatoes, and beverages. During dinner service, sleeping car customers received the regular dinner service in the Dining Car, while

provided an alternate bus to their final destination. Train 6(22) also provided aid to local customers on Train 4(22) that were boarding between Galesburg and Chicago.

24OCT26: Train 3(23), operating with engines 79/29, 9 coaches, and 153 customers, was stopped east of the Gallup, NM station due to severe weather resulting in water above the rail in multiple locations. Burlington Northern Santa Fe subsequently reported that there was no route available beyond Laguna (MP 71) due to flooding of the tracks and the adjacent highway. Reported flood damage included both main tracks under water with debris between MP 72.7 and MP 72.3, including approximately 800 feet of side scour on the Main Track 1 side; side scour and undercutting at a culvert near MP 72.4; water over a high-water detector bridge and both rails between MP 70.1 and MP 69.8; and water over both rails between MP 69.8 and MP 69.7, where inspection was not possible. As a result, Train 3(23) shoved back to Albuquerque, NM and arrived at 11:57P-MT. The train wye'd en route into the station and will return to its origin.

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

As a result of the service disruption, the following service adjustments were implemented:
- Train 3(23) arrived at Albuquerque, NM at 11:57P-MT, wyed enroute into the station, and operated back to Chicago, IL, returning customers to points of origination.
- Train 4(24), with 135 customers, wyed at Barstow, CA and operated back to Los Angeles, CA Union Station.
- Train 3(24), with 136 customers, reversed back to Kansas City, MO, wyed, and planned to return to its origin.

Due to crew availability in Kansas City, Train 3(24) held in Kansas City for the arrival of Train 4(23) and was coupled to operate as a combo set to Chicago, returning Train 3(24) customers to points of origination.
- Train 4(25) was canceled. No alternate transportation was provided.

25OCT26: Train 3(23) departed Albuquerque, NM, at 125AM-MT operating eastward back to Chicago. Train 3(23) was delayed at Fox/MP820.0, 15 miles east of Lamy, NM, on the BNSF Glorieta Subdivision, after operating through code line failure at E. Fox, the crew reported while operating through the switch, with it on hand, the switch handle popped up as train started into the switch. Train 3(23) was delayed due to possible switch damage and due to holding for a required recrew to arrive.

As of 700AM-CT on Sunday October 25th, BNSF reported still no estimate for open track. Due to the ongoing issues on the BNSF Gallup Subdivision, additional Southwest Chief service adjustments were necessary:
- Train 3(25) terminated in Kansas City, MO. No alternate transportation between Kansas City and Los Angeles.
- Train 4(25) was reinstated between Kansas City and Chicago only. Train 4(25) originated in Kansas City with no alternate transportation between Los Angeles and Kansas City.
- Train 4(27) cancelled entirely. No alternate transportation between Los Angeles and Chicago.

26OCT26: BNSF reported current weather conditions and further soil and ground degradation and scouring have delayed necessary repairs and pushed back track opening. Main Track 1 estimated back 300PM-MT Monday October 26th and No 2 estimated back at 1201AM-MT Tuesday October 27th. Due to the ongoing issues on the BNSF Gallup subdivision the following additional service adjustments were necessary:
- Train 3(26) cancelled entirely, no alternate transportation between Chicago and Los Angeles.
- Train 4(26) cancelled entirely, no alternate transportation between Los Angeles and Chicago.

BNSF advised an extremely large volume of freight traffic has been holding for open route and expect it to be heavily congested across the subdivision upon track opening.

27OCT26: A revised Main Track 1 estimate has been changed to "pending" due to a new washout that was identified at Milepost 50.2, with approximately 500 feet of side scour (erosion of the soil, rock, or ballast along the side of the railroad embankment (roadbed) caused by flowing water). Repair efforts are underway, with a ballast train placing material. Main Track Two between Laguna and Marmon is expected to reopen at 12:01 AM CT on the 27th under a 10 MPH speed restriction. BNSF has advised there are

- Train 3 (27) canceled in its entirety between Chicago and Los Angeles. No alternate transportation will be provided.
- Train 4(28) cancelled entirely, no alternate transportation between Los Angeles and Chicago.

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

29OCT26: Trains 3 and 4 continued to see heavy delays in the area due to ongoing repairs and congestion. BNSF advised to expect delays between 2 to 4 hours to continue over the next several days.

01NOV26: Trains 3(30) and 4(31) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.

02NOV26: Trains 3(31) and 4(01) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.
Moderate rainfall continues through the day. The Gallup Subdivision remains open, with one main closed for stabilization work. There were 43 trains on the subdivision.

03NOV26: Trains 3(01) and 4(02) continue to receive delays account fleeting westbound trains on Main Track #2 and eastbound trains on main track #1 on the Gallup, Seligman and Needles Subdivisions.
Weather conditions were favorable. The Gallup Subdivision remains open, with one main closed for stabilization work. There were 31 trains on the subdivision. Due to continued late operations and staffing issues, trains 3(04) and 4(04) were cancelled entirely with no alternate transportation.

**WBS#: B.TR.100150.7301**

| Train | Delay | Comment |
|---|---|---|
| 4(22) | 1'32" | Hold WLO |
| 4(22) | 5'09" | Meeting multiple freights due to weather |
| 3(22) | 1'30" | High winds and flash floods |
| 3(22) | 2'43" | meeting multiple freights due to weather |
| 3(22) | 2'59" | FLG, recrew |
| 4(25) | Originated KCY | |
| 3(23) | Terminated ABQ | Returned to origin |
| 3(24) | Terminated KCY | Returned to origin |
| 4(24) | Terminated BAR | Returned to origin |
| 3(25) | Terminated KCY | |
| 4(27) | Cancelled | |
| 3(23) | 5'18" | E/LMY, switch issue/recrew |
| 3(26) | Cancelled | |
| 4(26) | Cancelled | |
| 3(27) | Cancelled | |
| 4(28) | Cancelled | |
| 4(29) | 47" | BAR-NDL Congestion |
| 3(28) | 1'07" | ABQ-KNG Congestion |
| 4(29) | 1'20" | GLP-XIA |
| 3(29) | 4'44" | ABQ-GLP |
| 3(29) | 44" | WLO-FLG Congestion |
| 4(30) | 32" | KNG-FLG Congestion |
| 4(30) | 51" | FLG-WLO Congestion |
| 4(31) | 2'44" | NDL to ABQ |
| 3(30) | 8'45" | ABQ to BAR |
| 3(31) | 8'08" | ABQ-BAR |
| 4(01) | 3'30" | BAR to ABQ |
| 3(01) | 7'23" | ABQ to BAR |
| 4(02) | 4'52" | BAR to GLP |
| 3(02) | 20" | ABQ-KNG |
| 3(04) | Canceled | |
| 4(04) | Canceled | |
| 3(03) | 1'49" | |
| 4(03) | 2'29" | VRV-GLP |

# *Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions*

27-FOI-00137 0000000134 "UNCLASSIFIED" 11/10/2026

29SEP26: Train 821(29) was delayed beginning the 2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

| Train | Delay | Comment |
|---|---|---|
| 822(29) | 32" | |
| 821(29) | 27" | |
| 821(30) | 34" | |
| 822(30) | 30" | |
| 822(01) | 30" | |
| 821(02) | 34" | |
| 822(02) | 29" | |
| 822(03) | 33" | |
| 821(03) | 25" | |
| 821(04) | 35" | |
| 822(04) | 32" | |
| 821(05) | 35" | |
| 822(05) | 26" | |
| 821(06) | 26" | |
| 822(06) | 37" | |
| 821(07) | 35" | |
| 822(08) | 32" | |
| 821(09) | 32" | |
| 822(09) | 36" | |
| 822(10) | 23" | |
| 822(11) | 41" | |
| 822(12) | 48" | |
| 821(12) | 21" | |
| 821(13) | 22" | |
| 822(13) | 36" | |
| 821(14) | 35" | |
| 822(14) | 17" | |
| 821(15) | 26" | |
| 821(16) | 41" | |
| 822(15) | 34" | |
| 822(16) | 19" | |
| 821(17) | 24" | |
| 821(19) | 39" | |
| 822(19) | 22" | |
| 821(20) | 29" | |
| 822(20) | 32" | |
| 821(21) | 46" | |
| 821(22) | 32" | |
| 822(21) | 19" | |
| 822(22) | 30" | |
| 821(23) | 42" | |
| 822(23) | 23" | |
| 821(24) | 21" | |
| 822(24) | 22" | |
| 821(25) | 34" | |
| 822(25) | 43" | |
| 821(26) | 52" | |
| 822(27) | 34" | |
| 822(26) | 21" | |
| 821(28) | 30" | |
| 822(28) | 31" | |
| 821(29) | 23" | |
| 822(29) | 33" | |
| 821(30) | 33" | |
| 822(30) | 22" | |
| 821(31) | 20" | |
| 822(31) | 25" | |
| 822(01) | 30" | |

# Maintenance of Way Highlights

27-FOI-00187 0000000091134 "UNCLASSIFIED" 11/7/2026

## *Pacific Surfliner and Coast Starlight Service San Luis Obispo, CA to San Diego, CA - Scheduled M/W TW 27-021*

07NOV26: A multi-agency track maintenance project involving North County Transit District (NCTD), Southern California Regional Rail Authority (SCRRA/Metrolink), and Union Pacific Railroad (UP) was conducted between San Luis Obispo, CA, and San Diego, CA. To accommodate the work, the following operating plan was implemented:

Coast Starlight
Train 11 (November 5-7): Terminated at Emeryville, CA with alternate transportation provided between Sacramento and Los Angeles via Gold Runner Services.
Train 14 (November 7-9): Originated at Emeryville, CA with alternate transportation provided between Los Angeles and Martinez via Gold Runner Services.

Pacific Surfliner
Friday, November 6
Train 794(06) Originated in Goleta, CA account of ongoing signal issues and Terminated at Los Angeles, CA account of the scheduled track work. Bus 3594 provided alternate transportation between Los Angeles and San Diego making all stops except San Juan Capistrano
Train 595(06) Canceled in its entirety. Customers were accommodated on Bus 5811.

Saturday, November 7, and Sunday, November 8
All Pacific Surfliner trains were canceled. No alternate transportation was provided.

## *UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Scheduled M/W Work TWA 27-020*

26OCT26:To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 1(31Oct, 7Nov, 14Nov) and Train 42(30Oct, 6Nov, 13Nov) will detour over the BNSF San Bernardino Subdivision between West Colton(UPRR Alhambra subdivision) and Soto( BNSF San Bernardino subdivision), bypassing Ontario, CA (ONA) and Pomona, CA (POS). Train 801(2Nov, 9Nov, 16Nov) was created for the detour between Riverside, CA (RIV) and Los Angeles, CA (LAX).

Train 2/422(1Nov, 8Nov, 15Nov) will detour over the BNSF San Bernardino Subdivision between Soto( BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(1Nov, 8Nov, 15Nov) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV). An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision. No alternate transportation will be provided to POS and ONA.

**WBS#: B.TR.100150.7307**

| Train | Delay | Comment |
|---|---|---|
| 2/422(01) | 39" | |
| 1(31)/421(30) | 44" | |

# Western Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| 11(2) | SLO | 164 | | Main Resevoir |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| 5(2) | DEN | UP7656 | E/188 speedo/loading | OAK | 11/5/26 |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Western Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| | Projected Need | | Number Operated | | | |
|---|---|---|---|---|---|---|
| Train | Cars | Seats | Cars | Seats | Standees | Location |
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

## Consist Deviations

27-FOI-00137 00000009134 "UNCLASSIFIED" 11/10/2026

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 370 (04) | CHI | Using superliner equipment in lieu of venture cars. | n/a | 0 | 35001 |
| 383 (04) | CHI | Using superliner equipment in lieu of venture cars. | n/a | 0 | 35007 |
| 20 (04) | NOL | using a view 2 sleeper in lieu of view 1 sleeper. | SVWR20/4NOV NO WAR DATA THIS TRAIN/DATE | 0 | 62523 |
| 49 (04) | NYP | lounge being used in lieu of diner. will correct set once returned. | none | 0 | 28005 |
| 1107 (04) | NYP | 82972 HAS REPORTED FLOODING, INVENTORY AS BE ADJUSTED. OVERCAPCITY CONDITIONS EXIST, PLEASE SEE WAR REPORT. | no impact | 0 | 82972 |
| 1116 (04) | WAS | 82972 HAS REPORTED FLOODING, INVENTORY AS BE ADJUSTED WITH NO IMPACT TO PAX. | none | 0 | 82972 |

## Reverse Consists

| Train Number | Station | Reason |
|---|---|---|
| 1195 (04) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 2133 (04) | NYP | Acela consist reversed \| First class at Rear |
| 1088 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 1128 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 1146 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 1168 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 1135 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 1194 (04) | WAS | Consist reversed \| Business class seat orientation may have changed \| At Front |