



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, December 30, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/29/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/29/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	67	78.4%	8,773	1,385	84.2%	26,682	3,575	86.6%
Central Division	85.5%	67	9	86.6%	1,925	284	85.2%	5,947	653	89.0%
Northeast Division	80.0%	100	30	70.0%	2,818	490	82.6%	8,414	1,242	85.2%
Southeast Division	72.5%	73	19	74.0%	2,002	332	83.4%	6,201	849	86.3%
Southwest Division	77.0%	70	9	87.1%	2,028	279	86.2%	6,120	831	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00217 Endpoint Arrival Dates through 12/29/25 "UNCLASSIFIED" 1/5/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	106,290	37,423	65%	2,917,036	740,823	75%	9,111,770	1,989,028	78%
Northeast Corridor	81%	45,253	21,110	53%	1,287,914	341,994	73%	4,079,315	859,878	79%
Acela	83%	9,785	5,762	41%	275,128	86,163	69%	867,328	203,842	76%
Northeast Regional	79%	35,468	15,348	57%	1,012,786	255,831	75%	3,211,987	656,036	80%
Richmond / Newport News / Norfolk	77%	11,055	7,180	35%	313,231	86,100	73%	979,237	229,605	77%
Springfield Shuttles	89%	835	35	96%	24,169	2,984	88%	57,691	6,679	88%
Roanoke	79%	2,738	1,215	56%	79,002	15,548	80%	247,755	42,297	83%
On Spine Northeast Regional	80%	20,840	6,918	67%	596,384	151,199	75%	1,927,304	377,455	80%
State Supported	80%	45,989	10,440	77%	1,246,080	263,977	79%	3,892,754	747,032	81%
Borealis	60%	624	303	51%	16,417	4,097	75%	52,707	13,668	74%
Capitol Corridor	90%	3,514	167	95%	96,517	10,037	90%	315,110	33,433	89%
Carolinian	60%	975	523	46%	32,000	9,367	71%	105,146	30,269	71%
Cascades	63%	2,665	433	84%	68,991	15,405	78%	215,280	50,742	76%
Downeaster	82%	1,276	0	100%	40,742	5,085	88%	132,000	16,861	87%
Empire	78%	5,818	1,937	67%	166,443	39,664	76%	482,627	101,209	79%
Adirondack	72%	518	280	46%	9,281	4,582	51%	30,180	11,133	63%
Ethan Allen Express	70%	603	320	47%	16,235	4,367	73%	53,228	15,888	70%
Maple Leaf	70%	781	588	25%	21,229	12,326	42%	56,611	24,114	57%
New York - Albany	85%	2,795	597	79%	80,743	10,898	87%	219,350	30,020	86%
New York - Niagara Falls	75%	1,121	152	86%	38,955	7,491	81%	123,258	20,054	84%
Gold Runner	73%	2,506	563	78%	73,785	27,736	62%	227,833	83,381	63%
Heartland Flyer	65%	261	0	100%	6,510	721	89%	19,019	8,291	56%
Hiawatha	90%	1,649	148	91%	49,780	8,098	84%	156,233	19,013	88%
Illinois	78%	2,712	1,503	45%	68,966	24,432	65%	218,803	63,750	71%
Carl Sandburg / Illinois Zephyr	85%	439	0	100%	12,976	3,500	73%	38,134	10,058	74%
Illini / Saluki	85%	830	444	47%	21,474	7,325	66%	76,298	20,784	73%
Lincoln Service	70%	1,443	1,059	27%	34,516	13,607	61%	104,371	32,908	68%
Keystone	92%	8,145	1,095	87%	239,541	32,525	86%	735,119	73,336	90%
Lincoln / Missouri	60%	951	443	53%	22,386	10,123	55%	70,686	34,779	51%
Mardi Gras Service	80%	469	0	100%	11,059	863	92%	38,732	4,622	88%
Michigan	69%	1,907	1,074	44%	57,836	24,515	58%	177,171	54,403	69%
Blue Water	70%	288	277	4%	12,677	5,865	54%	43,462	13,160	70%
Pere Marquette	85%	316	194	39%	8,018	2,390	70%	23,914	4,319	82%
Wolverine	65%	1,303	603	54%	37,141	16,260	56%	109,795	36,924	66%
Missouri	80%	262	0	100%	7,051	1,499	79%	21,621	5,035	77%
Pacific Surfliner	85%	8,820	1,348	85%	190,168	27,384	86%	603,156	85,531	86%
Pennsylvanian	72%	1,018	0	100%	26,771	3,018	89%	83,795	9,216	89%
Piedmont	73%	1,072	261	76%	32,011	5,331	83%	116,340	27,162	77%
Vermont	75%	1,345	642	52%	39,106	14,077	64%	121,376	32,331	73%
Long Distance	56%	15,048	5,873	61%	379,602	134,585	65%	1,136,261	381,851	66%
Auto Train	57%	1,006	0	100%	22,099	2,995	86%	61,924	10,206	84%
California Zephyr	50%	1,294	1,151	11%	27,243	8,695	68%	84,051	24,366	71%
Cardinal	55%	369	142	62%	7,944	2,987	62%	25,300	11,292	55%
City Of New Orleans	75%	876	354	60%	20,676	4,368	79%	64,002	14,090	78%
Coast Starlight	60%	771	6	99%	35,478	11,061	69%	106,016	33,436	68%
Crescent	70%	1,198	66	94%	28,834	5,126	82%	87,949	20,908	76%
Empire Builder	55%	1,486	1,311	12%	30,702	13,603	56%	91,119	33,864	63%
Floridian	40%	2,156	471	78%	51,352	31,533	39%	155,253	85,905	45%
Lake Shore Ltd	73%	1,331	1,145	14%	32,097	10,407	68%	88,025	18,668	79%
Palmetto	65%	1,011	274	73%	27,967	6,757	76%	87,776	15,188	83%
Silver Meteor	45%	1,249	483	61%	31,567	12,017	62%	94,316	30,351	68%
Southwest Chief	40%	1,032	336	67%	23,353	14,392	38%	74,927	44,746	40%
Sunset Ltd	70%	530	83	84%	9,438	1,734	82%	25,820	5,958	77%
Texas Eagle	50%	739	51	93%	30,852	8,910	71%	89,783	32,873	63%
Seasonal Trains	%	0	0	-	3,440	267	92%	3,440	267	92%
Winter Park Express	75%	0	0	-	3,440	267	92%	3,440	267	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00217 00000005500 "UNCLASSIFIED" 1/5/2020

Train Index Dates Through December 29, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	185,215	3,129,264	592	515,097	9,638,057	534

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,819	913,915	86	20,174	2,816,151	72
INFRASTRUCTURE PLANNED	135	4,629	913,915	51	15,210	2,816,151	54
FLEET RELIABILITY	90	32,207	3,129,264	103	80,091	9,638,057	83
TRAIN OPERATIONS	424	140,560	3,129,264	449	399,622	9,638,057	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/29/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/29/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	67	78.4%	8,773	1,385	84.2%	26,682	3,575	86.6%
Central Division	85.5%	67	9	86.6%	1,925	284	85.2%	5,947	653	89.0%
Northeast Division	80.0%	100	30	70.0%	2,818	490	82.6%	8,414	1,242	85.2%
Southeast Division	72.5%	73	19	74.0%	2,002	332	83.4%	6,201	849	86.3%
Southwest Division	77.0%	70	9	87.1%	2,028	279	86.2%	6,120	831	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/29/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/29/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	67	78.4%	8,773	1,385	84.2%	26,682	3,575	86.6%
Central Division	85.5%	67	9	86.6%	1,925	284	85.2%	5,947	653	89.0%
CDL	90.0%	2	0	100.0%	37	2	94.6%	151	8	94.7%
CHI	85.0%	27	4	85.2%	778	136	82.5%	2,411	273	88.7%
CHM	-	-	-	-	13	5	61.5%	13	5	61.5%
DEN	-	-	-	-	6	2	66.7%	6	2	66.7%
EUG	86.5%	2	1	50.0%	57	10	82.5%	174	25	85.6%
GRR	98.0%	1	0	100.0%	28	2	92.9%	89	2	97.8%
KCY	84.5%	2	0	100.0%	57	4	93.0%	177	15	91.5%
MKE	86.5%	6	0	100.0%	169	16	90.5%	525	46	91.2%
MSP	94.0%	1	0	100.0%	29	0	100.0%	90	3	96.7%
PDX	78.0%	5	1	80.0%	145	14	90.3%	451	60	86.7%
PNT	91.5%	3	1	66.7%	86	16	81.4%	212	21	90.1%
PTH	93.0%	1	0	100.0%	28	4	85.7%	89	6	93.3%
QCY	87.5%	2	0	100.0%	58	4	93.1%	180	16	91.1%
SEA	80.0%	8	1	87.5%	230	42	81.7%	715	116	83.8%
SPK	92.0%	1	-	100.0%	32	4	87.5%	93	5	94.6%
STL	88.0%	4	1	75.0%	113	21	81.4%	355	39	89.0%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	53	2	96.2%	175	6	96.6%
WIP	-	-	-	-	6	0	100.0%	6	0	100.0%
Northeast Division	80.0%	100	30	70.0%	2,818	490	82.6%	8,414	1,242	85.2%
ALB	91.5%	8	3	62.5%	232	23	90.1%	599	44	92.7%
BON	43.5%	5	0	100.0%	144	10	93.1%	431	42	90.3%
BOS	86.5%	18	10	44.4%	544	97	82.2%	1,642	200	87.8%
BRK	88.0%	5	0	100.0%	144	6	95.8%	411	19	95.4%
BTN	48.0%	1	0	100.0%	29	1	96.6%	89	18	79.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	56	5	91.1%	172	14	91.9%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	29	6	79.3%	90	17	81.1%
NFL	96.5%	2	1	50.0%	59	4	93.2%	181	8	95.6%
NHV	75.5%	6	0	100.0%	160	17	89.4%	467	80	82.9%
NYP	77.5%	43	16	62.8%	1,166	310	73.4%	3,542	740	79.1%
SAB	98.0%	1	0	100.0%	29	0	100.0%	88	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	198	8	96.0%	547	24	95.6%
TWO	84.0%	1	0	100.0%	28	3	89.3%	88	19	78.4%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	73	19	74.0%	2,002	332	83.4%	6,201	849	86.3%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	145	10	93.1%	450	35	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	5	61.5%	323	86	73.4%	1,003	184	81.7%
LOR	69.5%	1	0	100.0%	29	3	89.7%	90	8	91.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/29/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/29/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	67	78.4%	8,773	1,385	84.2%	26,682	3,575	86.6%
Southeast Division	72.5%	73	19	74.0%	2,002	332	83.4%	6,201	849	86.3%
MIA	87.5%	2	0	100.0%	58	6	89.7%	180	19	89.4%
MOE	94.0%	2	0	100.0%	58	0	100.0%	180	3	98.3%
NFK	86.0%	3	2	33.3%	82	12	85.4%	252	27	89.3%
NOL	92.0%	5	0	100.0%	129	6	95.3%	398	20	95.0%
NPN	96.0%	2	0	100.0%	58	3	94.8%	155	10	93.5%
PGH	92.0%	1	0	100.0%	29	2	93.1%	90	3	96.7%
PHL	45.0%	5	4	20.0%	132	86	34.8%	413	209	49.4%
RGH	97.0%	4	0	100.0%	116	6	94.8%	356	9	97.5%
RNK	85.5%	2	0	100.0%	58	7	87.9%	179	21	88.3%
RVM	86.0%	1	0	100.0%	29	2	93.1%	100	13	87.0%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	29	2	93.1%	90	2	97.8%
SFA	70.5%	1	0	100.0%	29	0	100.0%	90	3	96.7%
WAS	70.0%	25	8	68.0%	698	101	85.5%	2,167	278	87.2%
Southwest Division	77.0%	70	9	87.1%	2,028	279	86.2%	6,120	831	86.4%
ARN	60.5%	1	0	100.0%	29	1	96.6%	90	6	93.3%
BFD	75.5%	7	4	42.9%	191	48	74.9%	538	132	75.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	34	19	44.1%	97	36	62.9%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	29	0	100.0%	89	3	96.6%
GTA	72.5%	3	0	100.0%	87	8	90.8%	263	25	90.5%
LAX	77.5%	9	0	100.0%	273	31	88.6%	833	92	89.0%
OKC	96.0%	1	0	100.0%	29	0	100.0%	90	3	96.7%
OKJ	79.0%	11	2	81.8%	317	89	71.9%	977	241	75.3%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	14	1	92.9%	401	41	89.8%	1,189	127	89.3%
SAN	77.0%	12	0	100.0%	340	23	93.2%	1,033	88	91.5%
SAS	85.0%	1	0	100.0%	29	1	96.6%	90	4	95.6%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	2	71.4%	203	14	93.1%	628	54	91.4%
SLO	62.0%	2	0	100.0%	57	3	94.7%	174	14	92.0%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		13	0	100.0%	39	1	97.4%	13	0	100.0%	39	1	97.4%
3		29	7	75.9%	90	11	87.8%	28	12	57.1%	89	35	60.7%
4		28	8	71.4%	89	14	84.3%	28	19	32.1%	89	57	36.0%
5	58	29	8	72.4%	89	15	83.1%	28	7	75.0%	87	13	85.1%
6	234	27	12	55.6%	88	29	67.0%	27	6	77.8%	88	27	69.3%
7	339	29	5	82.8%	90	9	90.0%	25	7	72.0%	86	14	83.7%
8	504	29	18	37.9%	90	38	57.8%	29	16	44.8%	90	43	52.2%
11	193	29	6	79.3%	89	17	80.9%	29	8	72.4%	87	15	82.8%
14		29	1	96.6%	90	10	88.9%	29	3	89.7%	89	21	76.4%
19		29	10	65.5%	90	18	80.0%	29	2	93.1%	90	13	85.6%
20		29	0	100.0%	90	6	93.3%	29	2	93.1%	90	8	91.1%
21	133	29	5	82.8%	89	13	85.4%	29	7	75.9%	89	18	79.8%
22		29	1	96.6%	90	4	95.6%	29	4	86.2%	89	17	80.9%
23		29	0	100.0%	90	3	96.7%	29	3	89.7%	90	13	85.6%
24		29	5	82.8%	90	7	92.2%	29	3	89.7%	90	9	90.0%
25		29	0	100.0%	90	0	100.0%	29	1	96.6%	90	10	88.9%
26		29	0	100.0%	90	2	97.8%	29	2	93.1%	90	13	85.6%
27	325	29	3	89.7%	90	4	95.6%	28	9	67.9%	89	19	78.7%
28		28	6	78.6%	89	19	78.7%	28	3	89.3%	89	11	87.6%
40		29	5	82.8%	90	14	84.4%	29	12	58.6%	90	34	62.2%
41		29	14	51.7%	90	32	64.4%	29	18	37.9%	90	57	36.7%
42		29	2	93.1%	90	3	96.7%	29	3	89.7%	90	12	86.7%
43		29	3	89.7%	90	8	91.1%	29	1	96.6%	90	4	95.6%
48	114	29	8	72.4%	90	13	85.6%	29	7	75.9%	90	10	88.9%
49		29	3	89.7%	90	13	85.6%	29	7	75.9%	90	12	86.7%
51	134	12	4	66.7%	39	18	53.8%	12	3	75.0%	38	12	68.4%
52		29	0	100.0%	90	3	96.7%	29	2	93.1%	90	14	84.4%
53		29	3	89.7%	90	8	91.1%	29	4	86.2%	90	12	86.7%
55		20	0	100.0%	62	0	100.0%	20	6	70.0%	62	12	80.6%
56		20	5	75.0%	62	12	80.6%	20	4	80.0%	62	10	83.9%
58	55	29	1	96.6%	89	3	96.6%	29	7	75.9%	88	14	84.1%
59		29	4	86.2%	88	7	92.0%	29	6	79.3%	88	9	89.8%
63	100	29	16	44.8%	90	37	58.9%	28	17	39.3%	89	46	48.3%
64	186	29	4	86.2%	89	20	77.5%	29	10	65.5%	89	20	77.5%
66	32	29	3	89.7%	90	13	85.6%	29	4	86.2%	90	17	81.1%
67		20	2	90.0%	62	4	93.5%	20	3	85.0%	62	10	83.9%
68	104	29	6	79.3%	90	17	81.1%	29	20	31.0%	90	45	50.0%
69		29	4	86.2%	90	11	87.8%	29	5	82.8%	90	12	86.7%
71		29	1	96.6%	90	1	98.9%	29	7	75.9%	90	23	74.4%
72	16	29	4	86.2%	90	9	90.0%	29	12	58.6%	90	22	75.6%
73		29	2	93.1%	90	3	96.7%	29	10	65.5%	89	43	51.7%
74		29	2	93.1%	90	7	92.2%	29	5	82.8%	90	25	72.2%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75	39	29	1	96.6%	90	3	96.7%	29	11	62.1%	90	39	56.7%
76		29	0	100.0%	90	4	95.6%	29	5	82.8%	90	35	61.1%
77		29	2	93.1%	90	4	95.6%	29	8	72.4%	90	30	66.7%
78		29	1	96.6%	90	4	95.6%	29	2	93.1%	90	11	87.8%
79	55	29	9	69.0%	90	20	77.8%	29	4	86.2%	89	15	83.1%
80		29	3	89.7%	90	11	87.8%	29	5	82.8%	89	10	88.8%
84	35	20	0	100.0%	62	3	95.2%	20	7	65.0%	62	12	80.6%
85	30	20	2	90.0%	62	3	95.2%	20	9	55.0%	62	24	61.3%
86	36	20	1	95.0%	62	5	91.9%	19	14	26.3%	61	33	45.9%
89	66	29	5	82.8%	90	17	81.1%	29	9	69.0%	90	15	83.3%
90		29	2	93.1%	90	2	97.8%	29	3	89.7%	90	9	90.0%
93	17	20	3	85.0%	62	9	85.5%	20	3	85.0%	61	13	78.7%
94		20	9	55.0%	62	15	75.8%	19	6	68.4%	61	18	70.5%
95	99	20	1	95.0%	62	2	96.8%	20	8	60.0%	62	19	69.4%
97		29	22	24.1%	90	40	55.6%	29	3	89.7%	90	19	78.9%
98		29	1	96.6%	90	5	94.4%	29	12	58.6%	90	23	74.4%
110		20	10	50.0%	62	29	53.2%	20	4	80.0%	62	7	88.7%
111		20	6	70.0%	62	10	83.9%	20	4	80.0%	62	7	88.7%
112	28	20	2	90.0%	62	6	90.3%	20	3	85.0%	62	8	87.1%
114		20	4	80.0%	62	12	80.6%	19	2	89.5%	61	2	96.7%
119	67	20	5	75.0%	62	14	77.4%	20	5	75.0%	62	8	87.1%
125		20	0	100.0%	62	2	96.8%	20	9	55.0%	62	15	75.8%
128		9	3	66.7%	28	6	78.6%	10	1	90.0%	28	2	92.9%
129		20	11	45.0%	62	24	61.3%	20	2	90.0%	62	8	87.1%
130		20	1	95.0%	62	5	91.9%	20	1	95.0%	62	5	91.9%
131		20	5	75.0%	62	9	85.5%	20	4	80.0%	62	4	93.5%
133		20	8	60.0%	62	27	56.5%	20	5	75.0%	62	25	59.7%
134		20	2	90.0%	62	6	90.3%	20	4	80.0%	62	12	80.6%
137	18	20	6	70.0%	60	14	76.7%	20	8	60.0%	60	18	70.0%
138	26	20	3	85.0%	62	9	85.5%	20	2	90.0%	62	4	93.5%
139		4	3	25.0%	14	3	78.6%	5	2	60.0%	14	4	71.4%
141		20	0	100.0%	62	3	95.2%	20	6	70.0%	62	14	77.4%
148		20	2	90.0%	62	6	90.3%	20	1	95.0%	61	10	83.6%
151		29	15	48.3%	90	29	67.8%	29	9	69.0%	89	25	71.9%
166	Cncld	4	1	75.0%	14	1	92.9%	4	1	75.0%	13	3	76.9%
169		9	1	88.9%	28	3	89.3%	10	4	60.0%	28	7	75.0%
170	27	20	3	85.0%	59	6	89.8%	20	11	45.0%	59	20	66.1%
171	89	20	2	90.0%	62	5	91.9%	20	7	65.0%	62	12	80.6%
172	Cncld	20	4	80.0%	62	8	87.1%	18	8	55.6%	60	23	61.7%
173	98	20	5	75.0%	62	7	88.7%	20	11	45.0%	62	26	58.1%
174	24	20	0	100.0%	62	3	95.2%	20	5	75.0%	62	13	79.0%
175	17	20	8	60.0%	62	10	83.9%	20	11	45.0%	62	19	69.4%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
176		20	2	90.0%	62	5	91.9%	20	1	95.0%	62	4	93.5%
177		20	6	70.0%	62	14	77.4%	20	7	65.0%	62	27	56.5%
181		20	9	55.0%	62	15	75.8%	19	2	89.5%	61	3	95.1%
182		20	3	85.0%	62	12	80.6%	20	2	90.0%	62	5	91.9%
183		20	7	65.0%	62	18	71.0%	20	4	80.0%	62	10	83.9%
184		20	4	80.0%	62	12	80.6%	20	5	75.0%	62	10	83.9%
185		20	4	80.0%	62	12	80.6%	20	3	85.0%	62	4	93.5%
186		20	2	90.0%	62	9	85.5%	20	3	85.0%	62	15	75.8%
190		20	10	50.0%	62	26	58.1%	20	5	75.0%	62	15	75.8%
192		20	2	90.0%	60	8	86.7%	20	1	95.0%	60	2	96.7%
193	31	20	7	65.0%	62	20	67.7%	20	8	60.0%	62	22	64.5%
196		20	1	95.0%	62	1	98.4%	20	1	95.0%	62	3	95.2%
197		20	9	55.0%	62	24	61.3%	20	7	65.0%	62	13	79.0%
232		29	1	96.6%	90	2	97.8%	29	0	100.0%	90	6	93.3%
233		29	10	65.5%	90	23	74.4%	29	8	72.4%	90	20	77.8%
234		29	1	96.6%	90	4	95.6%	29	1	96.6%	90	3	96.7%
235		29	4	86.2%	29	4	86.2%	29	6	79.3%	29	6	79.3%
236	18	29	0	100.0%	90	1	98.9%	29	5	82.8%	90	16	82.2%
238		29	5	82.8%	29	5	82.8%	29	3	89.7%	29	3	89.7%
239		29	9	69.0%	89	24	73.0%	29	2	93.1%	89	4	95.5%
240		29	3	89.7%	90	9	90.0%	29	5	82.8%	90	12	86.7%
241		29	8	72.4%	90	24	73.3%	29	4	86.2%	90	14	84.4%
243	38	20	6	70.0%	62	22	64.5%	20	4	80.0%	63	12	81.0%
244	43	29	3	89.7%	90	5	94.4%	29	3	89.7%	90	18	80.0%
245		9	2	77.8%	28	7	75.0%	10	0	100.0%	28	1	96.4%
280		29	1	96.6%	90	4	95.6%	29	6	79.3%	90	16	82.2%
281	87	29	1	96.6%	90	9	90.0%	29	5	82.8%	90	10	88.9%
283		29	11	62.1%	90	19	78.9%	29	6	79.3%	90	15	83.3%
284	Cncld	29	2	93.1%	90	3	96.7%	28	2	92.9%	89	7	92.1%
290	19	29	1	96.6%	90	19	78.9%	29	9	69.0%	89	30	66.3%
291		29	5	82.8%	90	18	80.0%	29	3	89.7%	90	15	83.3%
300	30	29	7	75.9%	90	9	90.0%	29	10	65.5%	89	24	73.0%
301	24	28	1	96.4%	88	2	97.7%	28	7	75.0%	87	16	81.6%
302	36	27	5	81.5%	87	11	87.4%	27	9	66.7%	85	26	69.4%
305		29	7	75.9%	90	12	86.7%	28	15	46.4%	88	35	60.2%
306		28	4	85.7%	88	6	93.2%	28	9	67.9%	87	20	77.0%
307		29	5	82.8%	89	10	88.8%	28	9	67.9%	88	20	77.3%
311		29	5	82.8%	89	12	86.5%	28	6	78.6%	88	20	77.3%
316		28	2	92.9%	88	5	94.3%	28	6	78.6%	88	18	79.5%
318		29	2	93.1%	90	11	87.8%	29	11	62.1%	89	36	59.6%
319	36	29	2	93.1%	90	4	95.6%	29	11	62.1%	90	47	47.8%
329		20	2	90.0%	62	3	95.2%	20	3	85.0%	62	5	91.9%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
330		24	0	100.0%	75	2	97.3%	24	4	83.3%	75	5	93.3%
331	13	29	7	75.9%	90	11	87.8%	29	8	72.4%	90	14	84.4%
332	14	29	4	86.2%	90	9	90.0%	29	11	62.1%	90	16	82.2%
334		29	1	96.6%	90	2	97.8%	29	8	72.4%	89	12	86.5%
335		29	7	75.9%	90	14	84.4%	28	7	75.0%	88	16	81.8%
336		29	3	89.7%	90	4	95.6%	29	1	96.6%	90	5	94.4%
337		29	1	96.6%	90	5	94.4%	29	6	79.3%	90	11	87.8%
338		29	6	79.3%	90	21	76.7%	28	10	64.3%	88	22	75.0%
339		29	5	82.8%	90	19	78.9%	29	7	75.9%	90	18	80.0%
341	48	27	6	77.8%	87	15	82.8%	26	5	80.8%	86	13	84.9%
342		29	2	93.1%	90	8	91.1%	29	7	75.9%	89	15	83.1%
350	81	29	1	96.6%	72	3	95.8%	29	19	34.5%	72	41	43.1%
351	17	29	9	69.0%	90	12	86.7%	29	12	58.6%	90	38	57.8%
352		29	3	89.7%	90	7	92.2%	28	10	64.3%	87	24	72.4%
353		29	3	89.7%	69	5	92.8%	29	11	62.1%	69	16	76.8%
354	16	29	5	82.8%	90	8	91.1%	27	13	51.9%	88	27	69.3%
355	70	28	4	85.7%	89	9	89.9%	27	12	55.6%	88	25	71.6%
364	40	28	12	57.1%	89	17	80.9%	27	12	55.6%	88	20	77.3%
365	34	28	4	85.7%	89	6	93.3%	27	11	59.3%	88	27	69.3%
370		29	3	89.7%	90	5	94.4%	29	7	75.9%	90	16	82.2%
371	22	28	2	92.9%	89	2	97.8%	28	7	75.0%	89	11	87.6%
380		29	4	86.2%	90	14	84.4%	29	7	75.9%	90	20	77.8%
381		29	1	96.6%	90	2	97.8%	29	4	86.2%	90	11	87.8%
382		29	0	100.0%	90	2	97.8%	29	8	72.4%	90	23	74.4%
383		29	4	86.2%	90	9	90.0%	28	13	53.6%	88	35	60.2%
390	45	21	5	76.2%	74	9	87.8%	20	7	65.0%	73	23	68.5%
391	31	21	2	90.5%	75	2	97.3%	20	3	85.0%	73	15	79.5%
392		29	2	93.1%	90	4	95.6%	29	13	55.2%	89	28	68.5%
393		29	2	93.1%	90	7	92.2%	29	10	65.5%	89	25	71.9%
417		20	2	90.0%	59	10	83.1%	19	1	94.7%	56	2	96.4%
425		20	1	95.0%	59	2	96.6%	20	1	95.0%	59	2	96.6%
448	125	29	11	62.1%	31	12	61.3%	28	12	57.1%	29	12	58.6%
449		28	1	96.4%	28	1	96.4%	28	5	82.1%	28	5	82.1%
470		22	8	63.6%	64	13	79.7%	20	5	75.0%	62	12	80.6%
471		20	1	95.0%	59	1	98.3%	20	0	100.0%	59	0	100.0%
473		20	0	100.0%	62	3	95.2%	20	0	100.0%	62	1	98.4%
474		20	5	75.0%	60	18	70.0%	19	7	63.2%	56	18	67.9%
475		20	0	100.0%	62	0	100.0%	20	0	100.0%	62	1	98.4%
478		20	3	85.0%	60	13	78.3%	20	1	95.0%	60	7	88.3%
479		20	3	85.0%	62	7	88.7%	20	2	90.0%	62	3	95.2%
486		20	1	95.0%	63	8	87.3%	20	5	75.0%	62	11	82.3%
490		20	2	90.0%	39	7	82.1%	20	0	100.0%	39	2	94.9%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
494		20	0	100.0%	64	9	85.9%	20	4	80.0%	61	11	82.0%
495		20	0	100.0%	62	2	96.8%	20	0	100.0%	62	1	98.4%
500		29	1	96.6%	90	6	93.3%	29	4	86.2%	89	9	89.9%
502		29	1	96.6%	90	7	92.2%	29	4	86.2%	89	20	77.5%
503		29	3	89.7%	87	11	87.4%	29	7	75.9%	86	22	74.4%
504		29	3	89.7%	90	8	91.1%	28	6	78.6%	89	25	71.9%
505		29	6	79.3%	90	16	82.2%	29	4	86.2%	88	17	80.7%
506		29	5	82.8%	89	14	84.3%	29	4	86.2%	88	13	85.2%
507		29	3	89.7%	90	10	88.9%	29	9	69.0%	90	31	65.6%
508		29	8	72.4%	88	19	78.4%	29	8	72.4%	88	21	76.1%
509	20	29	3	89.7%	90	7	92.2%	29	12	58.6%	90	25	72.2%
511		29	6	79.3%	90	10	88.9%	29	4	86.2%	90	16	82.2%
516		27	0	100.0%	88	9	89.8%	27	8	70.4%	88	36	59.1%
517		29	1	96.6%	90	2	97.8%	29	9	69.0%	89	31	65.2%
518	18	29	0	100.0%	90	13	85.6%	29	17	41.4%	90	53	41.1%
519		27	1	96.3%	88	4	95.5%	27	4	85.2%	88	13	85.2%
521		19	0	100.0%	60	0	100.0%	19	1	94.7%	60	4	93.3%
522		19	5	73.7%	60	9	85.0%	18	1	94.4%	59	5	91.5%
523		19	0	100.0%	60	0	100.0%	19	4	78.9%	60	8	86.7%
524		19	0	100.0%	60	2	96.7%	19	1	94.7%	60	4	93.3%
525		19	2	89.5%	60	3	95.0%	18	1	94.4%	59	6	89.8%
526		19	4	78.9%	60	10	83.3%	18	2	88.9%	59	6	89.8%
527		19	1	94.7%	60	2	96.7%	19	1	94.7%	60	3	95.0%
528		19	1	94.7%	60	6	90.0%	19	3	84.2%	60	13	78.3%
529	22	19	0	100.0%	60	3	95.0%	19	5	73.7%	60	12	80.0%
530		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
531		19	0	100.0%	60	1	98.3%	19	3	84.2%	60	6	90.0%
532		19	4	78.9%	60	5	91.7%	19	1	94.7%	60	8	86.7%
536		19	5	73.7%	60	9	85.0%	17	2	88.2%	58	3	94.8%
537		19	2	89.5%	60	5	91.7%	17	1	94.1%	58	2	96.6%
538		19	4	78.9%	60	10	83.3%	19	4	78.9%	60	9	85.0%
539		14	1	92.9%	14	1	92.9%	14	8	42.9%	14	8	42.9%
540		19	3	84.2%	60	7	88.3%	18	1	94.4%	57	2	96.5%
541		19	3	84.2%	60	8	86.7%	19	4	78.9%	60	15	75.0%
542		19	2	89.5%	60	5	91.7%	19	1	94.7%	59	11	81.4%
543	15	19	0	100.0%	60	6	90.0%	19	3	84.2%	60	15	75.0%
544		19	2	89.5%	59	4	93.2%	19	3	84.2%	59	7	88.1%
545		19	2	89.5%	60	6	90.0%	19	1	94.7%	59	5	91.5%
547		19	1	94.7%	60	5	91.7%	19	5	73.7%	60	12	80.0%
548		19	2	89.5%	60	10	83.3%	19	1	94.7%	60	6	90.0%
549		19	3	84.2%	57	13	77.2%	17	1	94.1%	54	7	87.0%
550		14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562		29	3	89.7%	88	11	87.5%	29	3	89.7%	87	9	89.7%
564		29	3	89.7%	88	9	89.8%	28	2	92.9%	84	12	85.7%
566		29	1	96.6%	88	6	93.2%	29	2	93.1%	85	8	90.6%
572		29	1	96.6%	87	7	92.0%	28	3	89.3%	85	17	80.0%
573		29	3	89.7%	88	12	86.4%	28	2	92.9%	86	10	88.4%
577		29	2	93.1%	86	7	91.9%	29	6	79.3%	82	8	90.2%
580		29	0	100.0%	88	2	97.7%	29	2	93.1%	88	9	89.8%
581		29	2	93.1%	88	9	89.8%	29	3	89.7%	88	15	83.0%
582		29	2	93.1%	88	6	93.2%	29	3	89.7%	86	7	91.9%
586		29	8	72.4%	88	19	78.4%	27	2	92.6%	83	11	86.7%
587		29	1	96.6%	88	4	95.5%	27	1	96.3%	84	10	88.1%
591		29	1	96.6%	88	2	97.7%	28	2	92.9%	87	8	90.8%
593		29	5	82.8%	88	14	84.1%	27	4	85.2%	80	9	88.8%
595		29	5	82.8%	87	19	78.2%	29	4	86.2%	86	14	83.7%
600		20	1	95.0%	62	2	96.8%	20	1	95.0%	62	5	91.9%
601		20	15	25.0%	62	34	45.2%	20	2	90.0%	62	15	75.8%
605		20	18	10.0%	62	39	37.1%	20	4	80.0%	61	6	90.2%
607		20	1	95.0%	62	4	93.5%	20	3	85.0%	61	4	93.4%
609		20	4	80.0%	61	5	91.8%	20	1	95.0%	61	4	93.4%
620		20	9	55.0%	61	18	70.5%	20	1	95.0%	59	3	94.9%
637		5	2	60.0%	16	2	87.5%	6	2	66.7%	16	2	87.5%
639		20	8	60.0%	62	18	71.0%	20	3	85.0%	62	7	88.7%
640	14	20	3	85.0%	62	5	91.9%	19	13	31.6%	61	31	49.2%
641		20	9	55.0%	62	14	77.4%	20	5	75.0%	62	12	80.6%
642		20	2	90.0%	61	4	93.4%	20	4	80.0%	61	8	86.9%
643		20	7	65.0%	62	14	77.4%	20	7	65.0%	61	10	83.6%
644	31	20	5	75.0%	62	10	83.9%	20	8	60.0%	62	13	79.0%
645		20	4	80.0%	62	7	88.7%	20	5	75.0%	62	11	82.3%
646	17	20	7	65.0%	62	14	77.4%	20	15	25.0%	61	35	42.6%
647	22	20	5	75.0%	62	7	88.7%	20	4	80.0%	62	16	74.2%
648	13	20	7	65.0%	62	13	79.0%	20	6	70.0%	62	10	83.9%
649		20	4	80.0%	62	10	83.9%	20	2	90.0%	61	9	85.2%
650		20	5	75.0%	62	14	77.4%	20	7	65.0%	62	14	77.4%
651		20	0	100.0%	62	5	91.9%	20	5	75.0%	62	18	71.0%
652		20	4	80.0%	62	12	80.6%	20	4	80.0%	61	12	80.3%
653		20	4	80.0%	62	12	80.6%	20	3	85.0%	62	17	72.6%
654		20	9	55.0%	62	14	77.4%	20	3	85.0%	62	5	91.9%
655	21	20	6	70.0%	60	18	70.0%	20	11	45.0%	59	19	67.8%
656		20	9	55.0%	62	16	74.2%	20	0	100.0%	62	5	91.9%
657		20	0	100.0%	62	3	95.2%	20	3	85.0%	62	12	80.6%
658		20	2	90.0%	62	9	85.5%	20	4	80.0%	62	10	83.9%
680		21	0	100.0%	64	2	96.9%	21	4	81.0%	64	7	89.1%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681	11	21	1	95.2%	64	3	95.3%	21	6	71.4%	64	19	70.3%
682		21	0	100.0%	64	0	100.0%	21	4	81.0%	64	14	78.1%
683		21	1	95.2%	47	4	91.5%	21	5	76.2%	47	14	70.2%
684		20	4	80.0%	45	8	82.2%	20	5	75.0%	45	13	71.1%
685		20	3	85.0%	62	7	88.7%	20	4	80.0%	62	17	72.6%
686		21	2	90.5%	64	15	76.6%	21	4	81.0%	64	14	78.1%
687		21	3	85.7%	64	9	85.9%	21	5	76.2%	64	11	82.8%
688		21	0	100.0%	64	1	98.4%	21	2	90.5%	64	14	78.1%
699		7	0	100.0%	21	2	90.5%	8	0	100.0%	21	0	100.0%
701		22	6	72.7%	22	6	72.7%	22	2	90.9%	22	2	90.9%
702		29	2	93.1%	90	17	81.1%	29	5	82.8%	89	24	73.0%
703	24	29	7	75.9%	90	22	75.6%	29	8	72.4%	90	24	73.3%
704		22	3	86.4%	22	3	86.4%	21	4	81.0%	21	4	81.0%
710		29	11	62.1%	90	35	61.1%	29	6	79.3%	90	34	62.2%
711		27	4	85.2%	84	8	90.5%	24	5	79.2%	77	12	84.4%
712		29	5	82.8%	90	22	75.6%	28	9	67.9%	88	32	63.6%
713		26	3	88.5%	87	12	86.2%	22	6	72.7%	77	33	57.1%
714		29	11	62.1%	84	30	64.3%	27	8	70.4%	77	24	68.8%
715		29	8	72.4%	90	30	66.7%	25	13	48.0%	83	42	49.4%
716	160	29	17	41.4%	90	40	55.6%	28	17	39.3%	88	40	54.5%
717		29	9	69.0%	81	22	72.8%	27	13	51.9%	74	26	64.9%
718		29	17	41.4%	90	39	56.7%	28	13	53.6%	89	29	67.4%
719	No OS	29	11	62.1%	90	35	61.1%	29	15	48.3%	88	31	64.8%
748		10	1	90.0%	29	6	79.3%	10	2	80.0%	29	3	89.7%
761		29	0	100.0%	88	3	96.6%	29	5	82.8%	88	14	84.1%
765		29	1	96.6%	88	8	90.9%	29	3	89.7%	88	16	81.8%
769		29	3	89.7%	88	7	92.0%	29	5	82.8%	86	16	81.4%
770		29	3	89.7%	88	10	88.6%	29	5	82.8%	88	14	84.1%
774		29	1	96.6%	88	7	92.0%	29	7	75.9%	87	18	79.3%
779	69	29	0	100.0%	88	4	95.5%	29	9	69.0%	87	18	79.3%
784	34	29	4	86.2%	88	10	88.6%	29	17	41.4%	87	46	47.1%
785		29	0	100.0%	88	0	100.0%	29	7	75.9%	88	14	84.1%
790		29	1	96.6%	88	6	93.2%	29	4	86.2%	88	11	87.5%
794		29	2	93.1%	88	7	92.0%	29	6	79.3%	87	16	81.6%
821		29	0	100.0%	90	3	96.7%	29	6	79.3%	90	46	48.9%
822		29	0	100.0%	90	3	96.7%	29	3	89.7%	90	47	47.8%
1333		29	6	79.3%	90	10	88.9%	29	10	65.5%	89	36	59.6%
1340	48	29	0	100.0%	90	3	96.7%	29	8	72.4%	90	21	76.7%
2103		20	2	90.0%	61	5	91.8%	20	3	85.0%	61	4	93.4%
2104		20	4	80.0%	32	6	81.3%	20	3	85.0%	32	5	84.4%
2107	60	20	5	75.0%	62	12	80.6%	20	5	75.0%	60	5	91.7%
2108		20	3	85.0%	62	5	91.9%	20	2	90.0%	60	2	96.7%

Amtrak On Time Performance

Trains Arriving Through: 12/29/2025

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2117		20	6	70.0%	32	9	71.9%	20	5	75.0%	32	6	81.3%
2121		20	5	75.0%	60	8	86.7%	20	3	85.0%	60	6	90.0%
2122		20	4	80.0%	62	10	83.9%	20	1	95.0%	62	4	93.5%
2124	57	15	3	80.0%	45	7	84.4%	15	2	86.7%	45	3	93.3%
2150	24	20	6	70.0%	62	15	75.8%	18	6	66.7%	60	15	75.0%
2152	23	20	1	95.0%	58	3	94.8%	20	15	25.0%	57	24	57.9%
2153	201	20	2	90.0%	62	8	87.1%	20	5	75.0%	62	14	77.4%
2154	19	20	4	80.0%	62	18	71.0%	19	11	42.1%	59	32	45.8%
2155	179	20	2	90.0%	62	4	93.5%	20	11	45.0%	60	20	66.7%
2159	115	20	2	90.0%	61	3	95.1%	19	8	57.9%	60	15	75.0%
2162	55	20	0	100.0%	62	2	96.8%	19	7	63.2%	60	16	73.3%
2163	32	20	1	95.0%	62	5	91.9%	20	8	60.0%	62	18	71.0%
2166	49	20	1	95.0%	62	6	90.3%	20	6	70.0%	60	12	80.0%
2167	40	18	4	77.8%	60	9	85.0%	18	7	61.1%	60	15	75.0%
2169	41	20	14	30.0%	58	24	58.6%	20	16	20.0%	58	31	46.6%
2170	Cncld	20	5	75.0%	62	12	80.6%	18	4	77.8%	60	13	78.3%
2172		20	1	95.0%	62	7	88.7%	20	5	75.0%	62	12	80.6%
2173		20	5	75.0%	61	12	80.3%	20	6	70.0%	61	24	60.7%
2190	30	19	4	78.9%	61	9	85.2%	18	5	72.2%	60	9	85.0%
2193	26	20	2	90.0%	61	3	95.1%	20	11	45.0%	61	20	67.2%
2275	35	4	1	75.0%	14	3	78.6%	5	4	20.0%	14	8	42.9%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/29/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2107	WAS	60	SVS	48	SVS	48	NYP-NYP	AM	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL	
2124	NYP	57	DET	60	DET	60	WAS-WAS	AM	Catenary failure, Control Point, TOWER 1 INTERLOCKING, DET - CATENARY DOWN IN TOWER 1 INTERLOCKING DELAYED TRAIN 2159	
2150	BOS	24	CTI	16	PTI	9	XNH-XGX	AM	Follow, 190, Milepost w/Letters, XNH, XGX, FOLLOWING AM190	
2152	BOS	23	DSR	12	DCS	11	NHV-XGX	AM	Power switch failure, Control Point, XGU, SWITCH FAILURE AT XGU	
2153	WAS	201	SVS	145	SVS	145	BOS-BOS	AM	Routine inspections, HELD A/C DAMAGE TO 2151'S PANTOGRAPH AT TOWER 1	
2154	BOS	19	DSR	14	CTI	12	RTE-BBY	AM	Follow, MBTA, 942 & 642, Control Point, XRF, Control Point, XT1, Sigs of 942 and late 642(10") ahead Plains to Cove	
2155	WAS	179	SVS	122	SVS	122	BOS-BOS	AM	Routine inspections, HELD A/C PANTOGRAPH DAMAGE ON 2151'S EQ.TOWER 1	
2159	WAS	115	SVS	87	SVS	87	BOS-BOS	AM	Routine inspections, HELD DUE TO PANTO DAMAGE ON AM2151	
2162	BOS	55	HLD	18	HLD	12	NYP-NYP	AM	Passenger and/or baggage, LOADING	
2163	WAS	32	PTI	13	DSR	5	NHV-STM	MN	Per bulletin Milepost, 41.7, 40.6, 30, 2	
2166	BOS	49	CAR	19	SYS	10	PVD-PVD	AM	Re-crew / job briefing, WAITED FOR PROTECT CREW IN PVD	
2167	WAS	40	ENG	21	ENG	21	XSH-NYP	AM	Other electrical failure, 2123, HELD AT HAROLD A/C CIRCUIT BREAKER OPEN	
2169	WAS	41	PTI	27	PTI	12	PVD-XGX	AM	Follow, 137, Milepost w/Letters, PVD, XGX, AM2169 FOLLOWED SIGNALS OF AM137	
2170	BOS	Trn Cancelled	DET	145	DET	145	WAS-WAS	AM	Catenary failure, Control Point, TOWER 1 INTERLOCKING, DET - CATENARY DOWN IN TOWER 1 INTERLOCKING DELAYED TRAIN 2153	
2190	BOS	30	PSR	17	PSR	17	XGX-PVD	AM	Slow bys, Milepost, XGX, PVD, CLASS 8 SPEED RESTRICTION MP 154 TO CRANSTON	
2193	NYP	26	DSR	16	WTR	8	XGX-XNH	AM	Wet / slippery rail, Milepost w/Letters, XGX, NHV, WHEEL SLIP	
2275	WAS	35	PTI	16	SMW	16	XSH-NYP	AM	Scheduled in track usage program, Other, XSH NYP	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
66	BOS	32	OTH	27	CTI	11	PVD-RTE	AM	Blocked from station track, MBTA, 828, Control Point, XJC, HELD AT XJC FOR MT828 TO CLEAR
84	NYP	35	ADA	26	ADA	13	ABE-ABE	AM	Wheelchair
85	RVM	30	SVS	48	SVS	48	BOS-BOS	AM	Routine inspections, HELD DUE TO PANTO DAMAGE ON AM2151
86	BOS	36	CTI	26	CTI	11	NWK-NYP	AM	Follow, NJT, NJ8842, Other, NWK-XPT
93	NFK	17	SVS	34	SVS	34	BOS-BOS	AM	Routine inspections, HELD A/C PANTOGRAPH DAMAGE TO 2151'S EQ. TOWER 1
95	NFK	99	SVS	106	SVS	106	BOS-BOS	AM	Routine inspections, HELD IN YARD A/C PANTOGRAPH DAMAGE TO 2151'S EQ
112	NYP	28	MTI	31	MTI	31	NBK-NWK	AM	Disabled train ahead, Other, EWR, PICKING UP DISABLED AM172'S PSGRS
119	WAS	67	ENG	59	ENG	59	NYP-NYP	AM	HEP, 662, SHOPPED ENG.662 A/C PANTOGRAPH ISSUES SUBBED ENG.653
137	WAS	18	HLD	13	HLD	11	BOS-BOS	AM	High passenger count, SLOW BOARDING PER CREW 204/ON
138	NYP	26	PTI	77	PTI	56	ALX-XVG	AM	Wait for station track multiple trains, Control Point, CP VA
166	BOS	Trn Cancelled	DET	12	DET	12	PVD-RTE	AM	Catenary failure, Other, TOWER 1 BOSTON, CATENARY FAILURE TOWER 1 BOSTON
170	BOS	27	DCS	29	DCS	29	NHV-NLC	AM	Restrictive signal(s) from unknown cause, 104.7, Milepost w/Letters, NHV, NLC, SIGNAL STACKED
171	RNK	89	DCS	50	DCS	50	NLC-NHV	AM	Power switch failure, Control Point, XGU, SWITCH FAILURE AT XGU
172	BOS	Trn Cancelled	DET	8	DET	8	BAL-XPV	AM	Catenary failure, Control Point, RIVER TO GUNPOW, CARBON STRIP DAMAGE A/C BROKEN HANGER
173	WAS	98	SVS	40	SVS	40	BOS-BOS	AM	Routine inspections, HELD DUE TO PANTO DAMAGE ON AM2151
174	BOS	24	CTI	24	HLD	12	NYP-NYP	AM	Passenger and/or baggage, BOARDING
175	WAS	17	SMW	21	SMW	21	XSH-NYP	AM	Scheduled in track usage program, Other, XPB, HELD FOR AM176 AND AM2172 DUE TO SINGLE TRACKING PELHAM BAY TO LEGGETT DUE TO SCHEDULED MAINTENANCE WORK ON NO.1 TRK
193	WAS	31	PTI	15	ITI	14	NYP-NYP	AM	Service, turn, or wye train, 84, LATE TURN OFF AM84

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
79	CLT	55	PTI	37	PTI	12	PTB-RMT	CS	Meet 138, Other, Appomattox
640	NYP	14	CTI	19	CTI	10	CWH-TRE	AM	Follow, SE, SE703, Other, CWH-XMO
644	NYP	31	MTI	25	MTI	25	TRE-NWK	AM	Disabled train ahead, Other, EWR, PICKING UP DISABLED AM172'S PSGRS
646	NYP	17	PTI	17	PTI	8	NWK-NYP	AM	Follow, AM86, Other, NWK-NYP
647	HAR	22	PTI	18	MTI	10	EWR-TRE	AM	Disabled train ahead, Other, MET, AM171 AHEAD AT STATION WITH DOOR ISSUES.
648	NYP	13	OTH	17	OTH	10	NWK-NYP	AM	Lost time - N.A.R., LOST ON RUN NO REPORTED PROBLEM
655	HAR	21	CTI	13	SYS	10	PHL-PHL	AM	Delay in Block, blue flag protection
681	BRK	11	PTI	10	PTI	8	POR-FRE	CS	Meet 684, Control Point, Congress
63	TWO	100	WTR	158	WTR	76	ROC-BUF	CS	High winds Control Point, 371
64	ALB	186	WTR	101	WTR	62	BUF-ROC	CS	High winds Milepost, 427, 372
68	NYP	104	OTH	118	OTH	114	ALB-ALB	AM	Waited in ALB for train 64
236	NYP	18	CTI	20	CTI	18	POU-CRT	MN	Follow Metro north, 846, Control Point, 72, Control Point, 33
243	ALB	38	ITI	37	ITI	37	NYP-NYP	AM	Service, turn, or wye train, 244, LATE TURN OFF AM244
244	NYP	43	CON	40	CON	40	ALB-ALB	AM	Hold for connecting train 48
281	NFL	87	WTR	112	WTR	56	ROC-BUF	CS	High winds Other, rochester subdivision, Other, buffalo subdivision
284	NYP	Trn Cancelled	CAR	72	CAR	72	NFL-NFL	CS	HEP 48186, 82502, 82671, 82701, 82733
290	NYP	19	CTI	17	RTE	15	RHI-XCP	MN	Dispatcher hold Control Point, 75
48	NYP	114	WTR	111	WTR	64	ERI-BUF	CS	High winds Milepost w/Letters, QD87.00, QD19.00, Milepost w/Letters, QD8.00, QC403.00
448	BOS	4	CON	112	CON	112	ALB-ALB	AM	Hold for connecting train 48
72	RGH	16	FTI	19	FTI	19	BNC-DNC	NS	Meet #ns51x, Control Point, Isom
75	CLT	39	DBS	26	DBS	26	HPT-SAL	NS	Debris blocking track (no debris strike) Tree down. Shove back to Maybelle, Milepost, 320.0, 320.0
89	SAV	66	FTI	64	FTI	31	KTR-CHS	CS	Meet csx M410, Control Point, west branch
5	EMY	58	FTI	97	FTI	65	CRN-OMA	BN	Meet bnsf 5157, Siding, bellevue, Z

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
6	CHI	234	FTI	177	WTR	128	HER-GRI	UP	CTC system failure Hand line all switches and flagging for 20 miles., Milepost, 593.7, 573.7, Other, .. CTC repeater struck by lightning
529	SJC	22	PTI	34	PTI	22	FMT-GAC	UP	Meet 530, Siding, ALBRAE
543	SJC	15	PTI	21	PTI	17	GAC-SCC	UP	Meet 544, Control Point, expressway
51	CHI	134	DCS	113	DCS	103	XMY-XTJ	CS	Power switch failure Control Point, XTJ
509	PDX	20	FTI	26	FTI	15	KEL-VAN	BN	Follow BNSF 8085, Control Point, 39th Street
518	VAC	18	PTI	10	PTI	10	STW-MVW	BN	Meet Amtrak 519, Control Point, North Stanwood
58	CHI	55	FTI	67	CTI	20	HMD-MCB	CC	Meet amtrak, 59, Milepost, 828.5, 823.3
11	LAX	193	ENG	254	ENG	82	SAC-SAC	UP	Set out defective locomotive 338
7	SEA	339	SYS	314	SYS	292	MOT-MOT	BN	Crew rest
8	CHI	504	DCS	291	DCS	257	DVL-GFK	BN	Power switch failure DL switch wouldn't normal or reverse. Sig MTR worked for several minutes on it. Ended up point clamping switch., Control Point, DL Switch
27	PDX	-39	FTI	33	FTI	33	XPW-PSC	BN	Meet BNSF 8222, Control Point, Beatrice
331	MKE	13	CTI	12	CTI	8	XWA-GLN	ME	Meet Equipment move with Engine #516 going into western coach yard on the West lead, Metra, equipment, Control Point, A-4, 4.1
332	CHI	14	CTI	6	SYS	6	MKE-MKA	CP	PTC problem or failure (cause unknown) PTC dropped right at Menominee and almost. Immediately came back- had to go restricted speed to KK., Milepost, 85.1, 83.4
341	MKE	48	ITI	28	ITI	28	CHI-CHI	AM	Late inbound 1340
350	PNT	81	DCS	77	DCS	77	XB0-XA5	MI	Power switch failure After 353 went through. Could not get the switch. Maintainer had to spike the switch., Control Point, 96
351	CHI	17	PTI	20	CAR	9	KAL-X90	AM	Legitimate wayside HBD or DED actuation ID4109, No defects found. DED 176.2
354	PNT	16	PTI	49	PTI	49	KAL-XGO	MI	Meet amt355, Other, 124
355	CHI	70	SYS	57	SYS	57	PNT-PNT	CC	Re-crew / job briefing Had to recrew 350 because they died for time while doing their Y move., Other, CN yard
364	PTH	40	WTR	52	WTR	48	CHI-CHI	AM	SEVERAL DOORS FROZEN. Other, CUS

Amtrak Endpoint OTP Details

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	34	CAR	21	CAR	16	FLN-DRD	CC	Air / Brake / Wheel ID4019, Main res hose became detached from rear locomotive p57
371	CHI	22	WTR	34	WTR	15	SJM-XPI	CS	High winds Milepost, 87.9, 109.0
779	SLO	69	PTI	43	PTI	32	X3G-LPS	UP	Meet 11, Siding, gaviota
784	SAN	34	CTI	32	PTI	14	SBA-CPN	UP	Meet 769, Other, s sba
703	SAC	24	PTI	20	PTI	20	FNO-MDR	BN	Meet 704, 716, Siding, Gregg, Siding, medera
716	BFD	160	TCC	133	TCC	133	EMY-EMY	UP	Cab signal failure C8307
719	OKJ	No OS Rpt	TRS	56	TRS	56	MCD-TRK	BN	Vehicle on track ahead Milepost, 1062.05, 1062.46
21	SAS	133	FTI	106	WTR	67	ALN-ALN	UP	High winds Power lines down across tracks. Waited for tracks to open at ALN station, Control Point, X272
300	CHI	30	WTR	46	WTR	41	STL-STL	TR	High winds Control Point, Gratiot
301	STL	24	PTI	34	PTI	15	JOL-BNL	UP	Meet Amtrak 300, Control Point, Mazonia
302	CHI	36	FTI	31	FTI	22	XUD-SMT	CC	Cross Traffic Unknown, Control Point, CP Canal
390	CHI	45	FTI	24	PTI	23	CHM-RTL	CC	Meet 391, Control Point, lev jct
391	CDL	31	FTI	42	FTI	22	KKI-GLM	CC	Follow a408, Milepost w/Letters, Otto, delray
319	KCY	36	SYS	30	DCS	26	XW1-XWR	UP	Restrictive signal(s) from known wayside signal failure Signal dropped at 267.7, had stop at Lenox. Authority past signal displaying stop., Stop, Control Point, Lenox
1340	CHI	48	RTE	62	RTE	62	MSP-XH8	CP	Line manual or spring switch Inoperable due to snow ice required maintainer assistance, Control Point, division

Amtrak Initial Terminal Details

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/29/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	620	12/29	1		
HAR	624	12/29	1		
HAR	648	12/29	1		
HAR	650	12/29	1		
HAR	656	12/29	1		
NFK	94	12/29	5	5	Mobility Impaired
NFK	138	12/29	22	22	Meet 822, Other, NFK STATION
PHL	151	12/29	(No OS)		
PHL	190	12/29	1		
PHL	601	12/29	1		
PHL	605	12/29	2	2	PTC - Stop Bypass Permission Required, Control Point, ., had to press stop bypass twice.
WAS	114	12/29	3	3	Door, 43362, ISSUES WITH A DOOR AT DEPARTURE TIME, CONDUCTOR TOLD THE ENGR TO PUT THE TRAIN IN BYPASS. MTR 610
WAS	136	12/29	17	17	Other late crew, CREW TURNED OFF 95 ARRIVED WAS 419 PM 2'14" LATE
WAS	178	12/29	153		
WAS	184	12/29	2	2	Other late crew, SYS - CONDUCTOR STILL WALKING ON THE PLATFORM AT 1 MINUTE TO THEIR DP TIME. CLOSING TRAPS AND DOORS
WAS	2122	12/29	8	8	Catenary failure, Control Point, TOWER 1 INTERLOCKING, DET - CATENARY DOWN IN TOWER 1 INTERLOCKING DELAYED THE TRAIN 2117
WAS	2124	12/29	60	60	Catenary failure, Control Point, TOWER 1 INTERLOCKING, DET - CATENARY DOWN IN TOWER 1 INTERLOCKING DELAYED TRAIN 2159
WAS	2154	12/29	4	4	Delay in Block, LSA ON BOARD WAS HAVING ISSUES WITH THE POS CONNECTING TO WIFI IS WHAT IT TURNED OUT TO BE.
WAS	2170	12/29	145	145	Catenary failure, Control Point, TOWER 1 INTERLOCKING, DET - CATENARY DOWN IN TOWER 1 INTERLOCKING DELAYED TRAIN 2153
WAS	2172	12/29	2	2	Catenary failure, Control Point, TOWER 1 INTERLOCKING, DET - LATE EQUIPMENT TURNED OFF 2155 4:52 PM DUE TO CATAENARY DOWN
ALB	238	12/29	24	24	Pick up equipment Other, alb
ALB	240	12/29	9	9	Service, turn, or wye train 240
ALB	244	12/29	40	40	Hold for connecting train 48
ALB	448	12/28	112	112	Hold for connecting train 48
BOS	85	12/29	48	48	Routine inspections, HELD DUE TO PANTO DAMAGE ON AM2151

Amtrak Initial Terminal Details

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/29/2025

Terminal	Train	Date	Late	Delay	Cause
BOS	93	12/29	34	34	Routine inspections, HELD A/C PANTOGRAPH DAMAGE TO 2151'S EQ. TOWER 1
BOS	95	12/29	106	106	Routine inspections, HELD IN YARD A/C PANTOGRAPH DAMAGE TO 2151'S EQ
BOS	137	12/29	9	11	High passenger count, SLOW BOARDING PER CREW 204/ON
BOS	171	12/29	34	34	Routine inspections, HELD A/C PANTOGRAPH DAMAGE TO NO.2151'S EQ. TOWER 1
BOS	173	12/29	40	40	Routine inspections, HELD DUE TO PANTO DAMAGE ON AM2151
BOS	175	12/29	9	9	T.O.L. Other, BOS, Terminal Dspr Rpts TOL in Tower 1 Int, Locking up the 98sw, 109sw , 911sw and 29sw. There will be a delay on the departure of AM175
BOS	2153	12/29	145	145	Routine inspections, HELD A/C DAMAGE TO 2151'S PANTOGRAPH AT TOWER 1
BOS	2155	12/29	122	122	Routine inspections, HELD A/C PANTOGRAPH DAMAGE ON 2151'S EQ. TOWER 1
BOS	2159	12/29	87	87	Routine inspections, HELD DUE TO PANTO DAMAGE ON AM2151
NFL	284	12/29	(Trn Cxld)	72	Car Issue
NYP	97	12/29	20	10	Other electrical failure, 656, LATE RELEASE F/SSYD A/C MECHANICAL ISSUES
NYP	97	12/29	20	10	Water, commissary, toilet/trash dumping, DELAYED F/SSYD DUE TO LATE CATERING
NYP	111	12/29	21	21	Routine inspections, LATE RELEASE BY MECHANICAL FROM SSYD
NYP	119	12/29	59	59	HEP, 662, SHOPPED ENG.662 A/C PANTOGRAPH ISSUES SUBBED ENG.653
NYP	129	12/29	2	2	Passenger and/or baggage, LOADING
NYP	131	12/29	20	20	Service, turn, or wye train, 112, LATE TURN OFF AM112
NYP	133	12/29	4	4	Passenger and/or baggage, LOADING
NYP	177	12/29	(No OS)		
NYP	193	12/29	14	14	Service, turn, or wye train, 84, LATE TURN OFF AM84
NYP	233	12/29	7	7	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	243	12/29	37	37	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	283	12/29	9	9	Passenger and/or baggage, LOADING
NYP	641	12/29	3	3	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	647	12/29	3	3	Passenger and/or baggage, LOADING
NYP	2107	12/29	48	48	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	2121	12/29	4	4	Passenger and/or baggage, LOADING

Amtrak Initial Terminal Details

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/29/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	2190	12/29	4	4	Routine inspections, LATE RELEASE BY MECHANICAL FROM SSYD
CHI	3	12/29	31	31	Air / Brake Parking break not releasing, 14
CHI	41	12/29	22	22	Hold for connecting train 6
CHI	341	12/29	32	4	PTC problem or failure (cause unknown) PTC would not communicate with back office, Other, CUS South
CHI	341	12/29	32	28	Late inbound 1340
CHI	364	12/29	48	48	SEVERAL DOORS FROZEN. Other, CUS
EUG	508	12/29	3	3	Mobility Impaired Had to walk to the train from the station. Train boards north of the station because of platform construction.
PDX	28	12/29	169	171	Service, turn, or wye train 27
PNT	355	12/29	57	57	Re-crew / job briefing Had to recrew 350 because they died for time while doing their Y move., Other, CN yard
SEA	8	12/29	201	202	Service, turn, or wye train 7, Late Train 7
STL	300	12/29	41	41	High winds Control Point, Gratiot
BFD	711	12/29	1		
BFD	715	12/29	2	2	HEP C2123
BFD	717	12/29	19	19	Hold for thruway bus 3 buses with all pax for train
BFD	719	12/29	39	39	Hold for thruway bus Late arrival of bus connections waited for four buses to arrive in Bakersfield per Oakland Ops
OKJ	532	12/29	3	3	Engine not serviced C2012
OKJ	716	12/29	(Trn Cxld)		Third Party Cab Car Failure
SAC	527	12/29	1		
SJC	538	12/29	6	6	PTC-caused slow-down or penalty stop Required to shuffle from south 9 to depot track one. Upon starting shuffle we had a diverging approach in the field, once past the signal PTC put us into a penalty stop. Once recovered restricted speed for the shuffle., Control Point, Bird
SJC	542	12/29	3	3	Meet Red/Stop signal at CP Alameda on SJC Depot Track 9 waiting for Caltrain 814 to arrive at SJC Depot., Caltrain, Caltrain 814, Control Point, Alameda

Eastern Region

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	87.7	97.6	94.8	309	38
CDOT	95.0	90.0	92.1	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	94.3	92.8	93.8	365	21
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 689(29) - Portland, ME - Route Obstructed by Roll Away Car

30DEC25: Train 689(29) was terminated officially at Portland Station after stopping at MP 11.7 on the CSX Portland Subdivision - short of the Portland Station, due to a car rolling out of the Portland Layover Facility - running through a switch in the process, blocking the main.

Trainmaster Menair transported the 7 remaining passengers from the equipment to the Portland Station.

ASO Luke Irvine reported a switcher crew took the E/107 from the rear of the 689(29) set to use later, in coordination with CSX, to push the roll away car back into the yard. The original crew deadheaded the equipment to Brunswick with the E/86 in the lead.

Train	Delay	Comment
689(29)	Term PVD	

Train NG 2170(29) - Providence, RI - Calendar Day Inspection Expiring

30DEC25: Train 2170(29) was terminated at Providence Station/MP 185.1 due to the rapidly approaching expiration of the equipment's calendar day inspection.

All passengers were transferred to Keolis train 892 at Providence Station for continues travel east into Boston South Station.

Train	Delay	Comment
NG 2170(29)	Term at PVD	Passengers Transferred to Keolis 892

Train 244(29) - Albany, NY - Hold for Connection

29DEC25: Train 244(29) was delayed at its initial terminal at Albany-Rensselaer Station due to holding for connections on late arriving train 48(28).

Train	Delay	Comment
244(29)	40"	
243(29)	37"	Turn off 244(29)

Train 178(29) Washington, DC - Engine Failure

29DEC25: Train 178(29) had a hot journal issue on the right side of the engine. The train had hot journal issues and reversed back into Washington. Mechanical met the train and was able to correct the problem on the original engine. They were able to depart again.

2nd UPDATE: Train 178(29) had the same hot journal issue and reversed back into Washington for the second time where they will shop E/654 and replace it with E/640.

Train	Delay	Comment
178(29)	2'33"	

Train 2166(29) New Rochelle, NY - Car Failure

29DEC25: Train 2166(29) with set 10 PC/2038 and PC/2016 with 298 passengers onboard was stopped at New Rochelle station due to having comm issues on C/3534. The crew was trouble shooting with the Road Foreman and they were able to cut the power to the C/3534 and operate 'C' speeds into Boston.

Train	Delay	Comment
2166(29)	27"	

CSX High Wind Warnings - Weather

29DEC25: CSX Issued High Warnings on the following subdivisions Niagara, Rochester, Buffalo Terminal of upwards of 40-60MPH which restrict train movement to 40MPH and over 60MPH which will restrict train movement to 20MPH.

Train	Delay	Comment
64(29)	1'25"	
63(29)	2'36"	
49(29)	30"	
281(29)	1'50"	
48(28)	1'51"	
68(29)	1'54"	Hold for 64(29) Portion

Train 171(29) West of Old Saybrook, CT Switch Failure/ Routing

29DEC25: At 1102A-ET, Boston Chief reported that they had 21SW at Fitter Interlocking that would not reverse. C&S was enroute to Guilford. Train 171(29) and Train 2155(29) were stopped until repairs were made. Once repairs were complete the trains were able to proceed.

Train	Delay	Comment
171(29)	43"	
2155(29)	36"	

Train 119(29) New York, NY - Engine Failure

29DEC25: Train 119(29) was delayed departing New York due to E/662 being shopped and replaced with E/653.

Train	Delay	Comment
119(29)	59"	

Train 172(29) Newark Liberty Airport, NJ - Engine Failure

29DEC25: Train 172(29) 26-FOI-00217E/60000005560 10 "UNCLASSIFIED" 485/5/2026 passengers onboard was disabled at Newark Airport with reports of Pantograph damage. This train did operate on track 2 at Gunpow on the Philadelphia to Washington Line where they did find broken hangers. Trains 130(29) with E/658 and E/662, 172(29) with E/609 and 2154(29) with PC/2104, PC/2141 all operated track 2 at Gunpow and did have to reconfigure their pantographs. Passengers off train 172(29) were transferred to trains 644(29) and 112(29). After the passengers were transferred the train was okayed to advance to Newark station on A track where ET would do the repairs. Train 172(29) was terminated at Newark Airport and train 177(29) originate in New York.

Train	Delay	Comment
172(29)	TERM EWR	
177(29)	ORIG NYP	
644(29)	25"	PAX TRANSFER EWR
112(29)	31"	PAX TRANSFER EWR

Train 2107(29) New York, NY - Servicing

29DEC25: Train 2107(29) was delayed departing New York due to the late release of the equipment from the yard.

Train	Delay	Comment
2107(29)	48"	

Train 284(29) Niagara Falls, NY - Car Failure

29DEC25: Train 284(29) with E/92 and 5 cars was delayed in the Niagara Falls yard due to not having HEP. The crew was able to get HEP restored thru 4 coaches by short looping. They were not able to restore power to the club dinette C/48186, business class passengers were downgraded and no food service was available. They arrived the station and were having the same issue. the crew worked on attempting to fix the issue again but were unable to get the 480V to provide HEP to the consist so the train was cancelled in its entirety. This also cancelled train 237(29) due to the lack of replacement equipment.

Train 244(29) was held in Albany for the excess passengers caused by the cancellation of train 284(29).

Train	Delay	Comment
284(29)	CANCELLED	
237(29)	CANCELLED	
244(29)	40"	held for connection

West of Boston South - Catenary or Wayside Failure

29DEC25: Approximately 26-FOI-00217PM 00000005560 gacy UNCLASSIFIED et 14/5/2026 at its west end pantograph on power car 2015, while traversing Tower 1 Interlocking/MP 228.5. The pantograph became tangled in the catenary. This caused a loss of power throughout the entirety of Tower 1 Interlocking. Emergency plates immediately went into effect. All inbound traffic from the west and South Hampton Yard was halted. ET and C&S Personnel responded. Passengers that were on Train 132(28) were transferred to the diesel Keolis set 5892. Passengers on Train 166(28) were transferred to the 132(28) equipment at Route 128 because the 132(28) equipment was within dimensional tolerances for the only available route into Boston South Station. 4:50AM A diesel engine was tied onto the 2151(29) equipment and towed it back to the yard. Tower 1 interlocking cleared of the disabled equipment. Due to this several trains were delayed departing Boston. The track car was still making repairs and the station tracks were full of trains until the track car cleared. As of 622A-ET, The track equipment cleared tower 1 and they were able to energize the power. Trains were able to start movement in and out of the yard. As of 646A-ET, All power was restored in the Terminal at South Station.

WBS#: B.TR.100151.0795

Train	Delay	Comment
132(28)	Term Route 128	Pax to Diesel Keolis Set
166(29)	Term Route 128	Pax to 132(28) EQ for travel into BOS
2151(29)	Cancelled	
95(29)	1'46"	
171(29)	34"	
2153(29)	2'25"	
2155(29)	2'02"	
2168(29)	CANCELLED	
93(29)	34"	
2159(29)	1'27"	
85(29)	48"	
173(29)	40"	
2170(29)	2'25"	LATE TURN OFF 2153(29)
2124(29)	60"	LATE TURN OFF 2124(29)

Eastern Region

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 2117(29) Passenger Removal at Philadelphia, Pennsylvania - Fare Evader***

29DEC25, Unknown Male Passenger traveling without a PNR was discovered hiding in the restroom and refused to provide a ticket or identification. Amtrak Police were contacted for assist. Amtrak Police notified.

Delay: 2117(29) None

Operating Highlights

Train 22(29) South of Texarkana, AR - Freight Train Interference

30DEC25: Train 22(29) operating with E/56, 6 cars and 115 passengers onboard, stopped at MP 6.9 approximately 6 miles south of Texarkana, TX Station on UPRR Little Rock Subdivision due to a disabled freight ahead. UP 3073 was stopped inspecting their train due to dragging equipment. Nothing was found, and the train on the move. Once the UP freight cleared, Train 22(29) was on the move north.

Train	Delay	Comment
22(29)	1'02"	

Train 719(29) Merced, CA - Trespasser Incident

29DEC25: Train 719(29) operating with E/CDTX 2010, 8 cars and 139 passengers onboard, was delayed at MP 1062 on BNSF Stockton Subdivision due to a car on the tracks ahead. Once the car was removed Train 719(29) was able to proceed.

Train 719(29) was held at the Antioch Station waiting for a BNSF freight to clear. Due to the delay removing the car from the tracks, the dispatcher proceed with move.

Train	Delay	Comment
719(29)	56"	
719(29)	26"	ACA/FTI

Train 8/28(29) - Initial Terminal Delay

29DEC25: Train 8(29) operating with E/353, E373 was delayed depart Seattle, WA due to the late inbound Train 7(27). Train 7(27) arrived Seattle 508P-PT, 5'39" late. The equipment needed to be turned and cleaned, causing Train 8(29) to depart late. Train 7(29) departed Seattle, WAS 734P-PT.

Service recover for Late 8(29)

Passengers departing Seattle, WA were provided sandwiches at the station from Subway, and the OBS Staff continued service recovery for the train.

for 12/30/2025:

1. Sleeping car passengers will be feed breakfast, lunch and dinner in the dining car
2. Snack packs and water will be distributed
3. Lounge car is offering complimentary coffee, tea and juice. Discounted and complimentary meals as needed.

29DEC25: Train 28(29) operating with E/372 was delayed departing Portland, OR due to the late inbound Train 27(27). Train 27(27) arrived Portland 442P-PT, 5'25" late. The equipment needed to be turned and cleaned, causing Train 28(29) to depart late. Train 28(29) departed Portland, OR 734P-PT.

Train	Delay	Comment
8(29)	3'22"	SEA
28(29)	2'51"	PDX

Train 719(29) Fresno, CA - Debris

29DEC25: Train 719(29) was delayed north of Fresno, CA (FNO) at MP 1007.8 on the Burlington Northern Santa Fe Railway Stockton Subdivision. Train 719(29) struck debris on the track which resulted in the separation of multiple air hoses between cars. There were no reports of injuries to passengers or crew; Head End Power (HEP) remained operational for the duration of the delay. Once the crew finished connecting all the hoses, train 719(29) was able to proceed.

Train	Delay	Comment
719(29)	30"	

Train 14(29) Paso Robles, CA - Passenger Train Interference

29DEC25: Train 14(29) was delayed north of Paso Robles, CA (PRB) at CP Bradley on the Union Pacific Railway Coast Subdivision. Train 14(29) was held in the siding track at CP Bradley for train 11(28). Once train 11(28) was clear of the track ahead, train 14(29) was able to proceed north.

Train	Delay	Comment
14(29)	35"	

Train 719(29) Bakersfield, CA - Hold for Connection

29DEC25: Train 719(29) was delayed departing the initial terminal of Bakersfield, CA (BFD) on the Burlington Northern Santa Fe Railway Mojave Subdivision. There were several late connecting buses, 5619, 5719, 5919 and 5419 with over one-hundred connecting passengers (20 for the SF Bay Area). Once all connecting buses were in, train 719(29) departed Bakersfield, CA at 4:41 PM-PT.

Train	Delay	Comment
719(29)	39"	

Train 716(29) Oakland, CA - Third Party Contractor Cab Car Failure

29DEC25: Train 716(29) was delayed departing the initial terminal of Oakland, CA (OKJ) on the Union Pacific Railway Niles Subdivision. There was a problem discovered at Oakland Maintenance Facility (OMF) with cab car CC/8307; which required the train operate locomotive first. The train crew was instructed to uncouple and wye locomotive CDTX/2104, then couple the locomotive to the north end of the train. Once the locomotive was turned to face the opposite direction and attached to the equipment, train 716(29) was able to depart OMF. To minimize delays, train 716(29) originated from Emeryville, CA (EMY) with passengers accommodated on train 536 OKJ to EMY. Train 716(29) departed EMY at 4:41 PM-PT.

Train	Delay	Comment
716(29)	2'13"	

Train 11(29) South of Portland, OR - Debris

29DEC25: Train 11(29) was delayed south of Portland, OR (PDX) on the Union Pacific Railway Brooklyn Subdivision. Train 11(29) struck debris at MP 752.2 on the Brooklyn Subdivision which resulted in the separation of air hoses between cars. There were no reports of injuries to passengers or crew and Head End Power remained operational. Once the train crew connected the air hoses, train 11(29) was able to proceed.

Train	Delay	Comment
11(29)	33"	

Train 27(27) West of Spokane, WA - Freight Train Interference

29DEC25: Train 27(27) 26-FOI-00217ay00000005560 of "UNCLASSIFIED" WA 11/5/2025 at MP 90.5 on the Burlington Northern Santa Fe Railway Lakeside Subdivision. Train 27(27) was held for an opposing freight train, BNSF/8222. Once the track ahead was clear, train 27(27) was able to proceed.

Train	Delay	Comment
27(27)	33"	

Train 21/421(28) Fort Worth, TX - Struck Pedestrian

29DEC25: At approximately 3:25PM-CT, Train 21/421(28), E/58 & 8 cars, with 185 passengers, struck a pedestrian on the platform at Fort Worth, TX/MP345.9, on the TRE Mainline, in Tarrant County, as train was arriving into the Fort Worth station. There were no reported injuries to passengers or crew. The pedestrian was not a fatality. Local emergency services responded to the scene. Amtrak road foreman and ASRO were also on the scene. Train 21/421(28) maintained HEP. Weather was reported as 45 degrees and sunny. Train 21/421(28) was delayed holding for completion of the investigation by local authorities. APD notified.

NRC 1451613

National Response Center Number: 1451613

Train	Delay	Comment
21/421(28)	27"	
21/421(28)	15"	HLD FTW FTI

Train 3(29) Late Departure Chicago, IL - Engine

29DEC25: Train 3(29), E/181-E/14 & 10 cars, was delayed departing Chicago, IL, due to parking brake issues at departure time. Mechanical responded from the yard and assisted in resolving issues.

Train	Delay	Comment
3(29)	31"	

Train 8/28(28) Shelby, MT - Disabled Freight Ahead

29DEC25: Train 8/28(28), with 191 passengers, delayed at Shelby, MT/MP1065.6, on the BNSF Hi Line Subdivision, due to BNSF 9875 ahead with a locked axle. BNSF crew set off the bad engine and then returned to remainder of consist at Dunkirk/MP1058, once train back together BNSF 9875 proceeded west to clear Shelby. Train 8/28(28) was delayed holding for open route ahead.

WBS#: B.TR.100151.0796

Train	Delay	Comment
8/28(28)	2'27"	
8/28(28)	24"	FTI/SBY -HAVE

Train 21/421(28) Dallas, TX - Police Related

29DEC25: Train 21/421(28) was delayed at Dallas, TX/MP214.4, on the TRE Mainline, due to a tractor trailer on track ahead. Train 21/421(28) was delayed holding for truck removal and track inspection.

Train	Delay	Comment
21/421(28)	55"	

Train 1340(29) East of St. Paul-Minneapolis, MN - Switch Failure

29DEC25: Train 1340(29) was delayed at 1 mile east of St. Paul-Minneapolis, MN/MP410.3, on the CPKC Merriam Park Subdivision, due to switch failure. Switch would not reverse and crew was unable to hand line. Maintainer responded and assisted crew in lining switch for movement.

Train	Delay	Comment
1340(29)	1'02"	
341(29)	28"	CHI, turn off 1340(29)

Train 350(29) East of Battle Creek, MI - Switch Failure

29DEC25: Train 350(29) was delayed at Albion/MP96, 24 miles east of Battle Creek, MI, on the MDOT Michigan Line, due to power switch failure. No 1 SW failing in both directions. Signal maintainer responded to scene and established local control at 1208PM-ET.

29DEC25: Train 355(29) departed Pontiac, MI late due to the late turn of equipment of inbound Train 350(29).

Train	Delay	Comment
350(29)	1'17"	
355(29)	57"	

Train 7/27(27) West of Browning, MT - Freight Train Interference

29DEC25: Train 7/27(27) was delayed at Spotted Robe/MP1129.6, 6 miles west of Browning, MT, on the BNSF Hi Line Subdivision, meeting BNSF 8347.

Train	Delay	Comment
7/27(27)	37"	

Train 371(29) West of Holland, MI - High Wind Warnings

29DEC25: Train 371(29) was delayed west of Holland, MI/MP25.4, on the CSX Grand Rapids Subdivision, due to high wind warnings in effect between MP43.2 and MP109.

Train	Delay	Comment
371(29)	34"	

Train 59(28) South of Memphis, TN - Signal

29DEC25: Train 59(28) was delayed at CN Jct/MP392.5, 1 mile south of Memphis, TN, on the CN Memphis Subdivision, due to signal issues. Train 59(28) was talked by the signal, operated the lock box and hand lined switches.

Train	Delay	Comment
59(28)	39"	

Train 51(28) West of Indianapolis, IN - Weather

29DEC25: Train 51(28) was delayed at Indianapolis, IN/MP284, on the CSX Indianapolis Terminal, Crawfordsville Branch and Monon Subdivisions, due to high wind warnings in effect between Indianapolis and Rensselaer, IN/MP72.3. Train 51(28) was further delayed at MP25.5, just north of Dyer, IN, on the CSX Elsdon Subdivision, due to frozen switches. Crew was unable to hand throw and it was necessary to hold for CSX maintainer to arrive.

Train	Delay	Comment
51(28)	32"	W/IND, high wind warnings
51(18)	1'43"	N/DYE, frozen switches

Train 300(29) St. Louis, MO - Weather

29DEC25: Train 300(29) was delayed at St. Louis, MO, holding for high wind warnings to expire at 515AM-CT. Once warnings expired, Train 300(29) was able to depart.

Train	Delay	Comment
300(29)	41"	

Train 7/27(27) Libby, MT - Deceased Passenger

29DEC25: Train 7/27(27), E/372-E/353-E/373 & 10 cars, was delayed at Libby, MT/MP1340.6, on the BNSF Kootenai River Subdivision, in Lincoln County, due to a passenger found deceased onboard. The passenger (E77EC1 CHI-PDX) was found deceased in the 2730 sleeper, C/32048 Room 9. Local emergency services and Libby Mortuary responded to the scene. Passenger remains were removed and in the custody of Libby Mortuary. APD notified.

NRC # 1451551

National Response Center Number: 1451551

Train	Delay	Comment
7/27(27)	1'00"	

Train 11(28) South of Chico, CA - Engine Failure

29DEC25: Train 11(29), operating with locomotives E/301-E/338 and 9 cars, was delayed at Berg, MP 145.9/UPRR Valley Subdivision, 38.2 miles south of Chico, while the crew inspected locomotive wheels following activation of a wheel impact detector at MP 150.5. Shelling and flat spots were found on trailing unit E/338 (4th axle - side wheels) which resulted in UPRR requiring the unit to be set-out. The train was authorized to continue at a maximum speed of 30mph to Sacramento, where the unit was set-out. The train incurred further delay downline as a result of stopping at the Oakland Yard to add replacement locomotive E/313 to the point.

A special move occurred (Train 961(29)) for locomotive E/338 to operate light from Sacramento to Oakland Yard.

WBS#: B.TR.100150.6355

Train	Delay	Comment
11(28)	1'22"	SAC - set-out E/338
11(28)	50"	Berg
11(28)	49"	Berg-SAC - operated at restricted speed
11(28)	1'10"	Oakland Yard - added E/313

29DEC25: Train 8/28 (28-FOI-002175 00000005560 at UNCLASSIFIED mil 1/5/2028 east of Rugby, ND, on the BNSF Devils Lake Subdivision, due to signal issues. Train 8/28(27) was delayed operating on restricting signals between MP131 and MP121.9.

Train 8/28(27), with 193 passengers, was further delayed at MP 0.6, 1/2 mile west of Grand Forks, ND, on BNSF Devils Lake Subdivision, due to the DL Switch would not line. The conductor, working alone, was unable to throw the switch all the way. The conductor continued attempts to line switch while waiting on BNSF maintainer to respond to scene. The maintainer was also unable to line switch and responded to the nearby yard for clamps. Once maintainer returned and clamped switch, traffic was able to resume through the area.

Train 7/27(28), with 247 passengers, was delayed at Spirit/MP86.9, 11 miles east of Grand Forks, on the BNSF Hillsboro Subdivision, waiting on DL switch issues ahead to be resolved. Once switch issue at DL was resolved, Train 7/27(28) was further delayed due to west spirit switch and lock frozen. BNSF maintainer responded and was able to assist in hand lining west Spirit. Train 8/28(27) was delayed at Spirit meeting Train 7/27(28) and then shoving out of west spirit due to east spirit now locking up. Train 7/27(28) was delayed at Rugby, ND/MP142.4, on the BNSF Devils Lake Subdivision, waiting on road foreman with recrew enroute from ST. Cloud, MN, due to crew on hours of service at 1209PM-CT.

As service recovery on Train 8/28(27), snack packs and water were available, lounge offered coffee, tea, juice and discounted/comp meals as necessary. Beef stew dinners planned for coaches and snack boxed dropped off in Milwaukee for passengers into Chicago. Upon arrival in Chicago, misconnecting passengers were provided hotel accommodations, shuttle bus, complimentary hotel breakfast vouchers and tickets for next day travel.

WBS#: B.TR.100150.6353

Train	Delay	Comment
8/28(27)	34"	E/RUG, signal issues
8/28(27)	4'17"	W/GFK, DL switch failure
8/28(27)	1'04"	E/GFK, meet 7/27(28)
7/27(28)	2'35"	E/GFK, DL switch failure
7/27(28)	40"	E/GFK, Spirit switch failiure
7/27(28)	27"	RUG, recrew

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

-715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.

-718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

-714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.

-718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.

-716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

-714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).

-713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

535(21) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

26-FOI-00217 00000005560 "UNCLASSIFIED" 1/5/2026

25DEC25 - 28DEC25

-Train 736(25-28) Cancelled - No alternate transportation.
-Train 737(25-28) Cancelled - No alternate transportation.
-Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

-Train 520(29-30) Cancelled - No alternate transportation.
-Train 534(29-30) Cancelled - No alternate transportation.
-Train 537(29-30) Cancelled - No alternate transportation.
-Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

-Train 520(31) Cancelled - No alternate transportation.
-Train 534(31) Cancelled - No alternate transportation.
-Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

-Train 736(01-04) Cancelled - No alternate transportation.
-Train 737(01-04) Cancelled - No alternate transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718(21)	Originate EMY	Passengers to 744(21) OKJ-EMY
718(22)	Originate EMY	Passengers to 544(22) OKJ-EMY
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
714(23)	.	CANCELLED
713(24)	.	CANCELLED
535(24)	Cancelled	
520(24)	Cancelled	
534(24)	Cancelled	
736(25-28)	Cancelled	
737(25-28)	Cancelled	
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
551(29-30)	Cancelled	Replacement Bus SAC-OKJ
520(29-31)	Cancelled	No alternate transportation.
534(29-31)	Cancelled	No alternate transportation.
736(01JAN-04JAN))	Cancelled	No alternate transportation
737(01JAN-04JAN)	Cancelled	No alternate transportation
535(29)	Cancelled	No alternate transportation.
537(30-31)	Cancelled	No Alternate Transportation

Western Region

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
6 (27)	DEN		33040	Wheel defects

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 27(27) Passenger Removal at Libby, Montana – Medical

29DEC25, Passenger on PNR E77EC1, traveling from Chicago, IL to Portland, OR was reportedly found unresponsive in the sleeper compartment. Libby Paramedics attempted to assist the passenger. However, it was determined that the passenger had expired, and the Libby Coroner was contacted for removal of the remains. Amtrak Police notified.

Delay: 27 (27) 1'

Train 21(28) Passenger Removal at Texarkana, Arkansas – Improper Conduct

29DEC25, Passenger on PNR 3BD9F2, traveling from St. Louis, MO to Longview, TX reportedly refused to move personal baggage from a revenue seat, and became argumentative with crew members. Local authorities assisted with the removal. Amtrak Police notified.

Delay: 21 (28) 11"

Train 1(27) Passenger Removal at Richmond, Texas – Improper Conduct

26-FOI-00217 00000005560 "UNCLASSIFIED" 1/5/2026

29DEC25, Passenger on PNR D84C2D, traveling from New Orleans, LA to Los Angeles, CA was removed by the local police at Richmond, TX (MP33.1 on the UP Railroad on the Glidden Subdivision) due to cursing and being confrontational with the crew and the other passengers. Amtrak Police notified.

Delay: 1(27) 1'10"

Train 48(27) Passenger Removal at Toledo, Ohio – Improper Conduct

29DEC25, Passenger on PNR 0731D8, traveling from Chicago, IL to Bryan, OH was removed by the Assistant Conductor at Toledo, OH due to not following instructions, hiding from the crew, and taking a seat check from another passenger to place over his seat. Amtrak Police notified.

Delay: 48(27) None

Train 3(27) Passenger Incident at Albuquerque, New Mexico – Other

29DEC25, Passenger on PNR 1D0F5A, traveling from Albuquerque, NM to Los Angeles, CA was stepping up on train and lost her balance and fell backwards. She refused medical attention. She stated that her hip and lower back have been bothering her for a while and gave out on her. Amtrak Police notified.

Delay: 3(27) None

Train 27(28) Passenger Removal at Milwaukee, Wisconsin – Improper Conduct

29DEC25, Passenger on PNR 3C0F9A, traveling from Chicago, IL to La Crosse, WI was removed by the Conductor at Milwaukee, WI due to being laid out across the floor of the lounge car right in the middle of the aisle. He cursed at the Conductor and refused to cooperate. Advised he needed to get off, or the police would be called. He refused to give his name or destination. Station agent said he had no recollection of anything or what train he was on but mentioned he was an alcoholic. Amtrak Police notified.

Delay: 27(28) None

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Consist Deviations

26-FOI-00217

00000005560

"UNCLASSIFIED"

1/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
175 (29)	BOS	Operate Consist 1 Coach Short vs Plan due to high shop count, lack of equipment, no passenger impact	none	0	
6 (27)	DEN	33040 set out @ den due to wheel defects	N/A	0	33040
284 (29)	NFL	No HEP in 48186, No Business Class, No Cafe sales	xcl'd	375	48186
518 (29)	PDX	Talgo set switched to Amfleet due to high shop count. Over capacity in coach and business class.	yes passengers advised of overcapacity	38	
505 (29)	SEA	Talgo set switched to Amfleet due to high shop count. Downgrade overbooked business class passengers to coach.	passengers advise of overcapacity	6	
170 (29)	WAS	Operate Consist 1 Coach Short vs Plan due to high shop count, lack of equipment, no passenger impact	none	0	

Reverse Consists

Train Number	Station	Reason
84 (29)	NFK	Consist reversed Business class seat orientation may have changed At Front
174 (29)	NPN	Consist reversed Business class seat orientation may have changed At Front
93 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front
2124 (29)	WAS	Acela consist reversed First class at Front
111 (29)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (29)	NYP	Consist reversed Business class seat orientation may have changed At Front
114 (29)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (29)	NYP	Consist reversed Business class seat orientation may have changed At Front
133 (29)	NYP	Consist reversed Business class seat orientation may have changed At Front
182 (29)	WAS	Consist reversed Business class seat orientation may have changed At Rear

Train Number	Station	Reason	
		26-FOI-00217	00000005560 "UNCLASSIFIED" 1/5/2026
192 (29)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
193 (29)	NYP	Consist reversed Business class seat orientation may have changed At Front	
138 (29)	NFK	Consist reversed Business class seat orientation may have changed At Front	
184 (29)	WAS	Consist reversed Business class seat orientation may have changed At Front	