



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, December 31, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/30/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	62	80.2%	9,086	1,445	84.1%	26,995	3,635	86.5%
Central Division	85.5%	68	13	80.9%	1,993	295	85.2%	6,015	664	89.0%
Northeast Division	80.0%	102	22	78.4%	2,920	512	82.5%	8,516	1,264	85.2%
Southeast Division	72.5%	73	16	78.1%	2,075	349	83.2%	6,274	866	86.2%
Southwest Division	77.0%	70	11	84.3%	2,098	289	86.2%	6,190	841	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00217 00000005559 "UNCLASSIFIED" 1/5/2026 Endpoint Arrival Dates through 12/30/25

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	108,240	29,810	72%	3,028,229	771,488	75%	9,222,963	2,019,693	78%
Northeast Corridor	81%	42,697	12,016	72%	1,332,490	354,669	73%	4,123,891	872,553	79%
Acela	83%	8,929	3,883	57%	284,268	90,210	68%	876,468	207,889	76%
Northeast Regional	79%	33,768	8,133	76%	1,048,222	264,459	75%	3,247,423	664,664	80%
Richmond / Newport News / Norfolk	77%	11,057	1,229	89%	324,637	87,570	73%	990,643	231,075	77%
Springfield Shuttles	89%	952	0	100%	25,117	2,981	88%	58,639	6,676	89%
Roanoke	79%	2,682	278	90%	81,746	15,863	81%	250,499	42,612	83%
On Spine Northeast Regional	80%	19,077	6,626	65%	616,722	158,045	74%	1,947,642	384,301	80%
State Supported	80%	48,050	10,602	78%	1,295,075	274,827	79%	3,941,749	757,882	81%
Borealis	60%	623	209	66%	17,063	4,319	75%	53,353	13,890	74%
Capitol Corridor	90%	3,077	410	87%	99,620	10,447	90%	318,213	33,843	89%
Carolinian	60%	1,031	56	95%	33,056	9,447	71%	106,202	30,349	71%
Cascades	63%	2,658	1,087	59%	71,751	16,512	77%	218,040	51,849	76%
Downeaster	82%	1,422	356	75%	42,193	5,441	87%	133,451	17,217	87%
Empire	78%	6,944	1,873	73%	173,524	41,601	76%	489,708	103,146	79%
Adirondack	72%	550	164	70%	9,846	4,757	52%	30,745	11,308	63%
Ethan Allen Express	70%	656	299	54%	16,909	4,675	72%	53,902	16,196	70%
Maple Leaf	70%	912	653	28%	22,171	13,009	41%	57,553	24,797	57%
New York - Albany	85%	3,293	172	95%	84,093	11,081	87%	222,700	30,203	86%
New York - Niagara Falls	75%	1,533	585	62%	40,505	8,079	80%	124,808	20,642	83%
Gold Runner	73%	2,814	614	78%	76,706	28,386	63%	230,754	84,031	64%
Heartland Flyer	65%	255	1	100%	6,767	722	89%	19,276	8,292	57%
Hiawatha	90%	1,718	559	67%	51,554	8,664	83%	158,007	19,579	88%
Illinois	78%	2,730	1,036	62%	71,759	25,474	65%	221,596	64,792	71%
Carl Sandburg / Illinois Zephyr	85%	458	204	55%	13,442	3,704	72%	38,600	10,262	73%
Illini / Saluki	85%	813	227	72%	22,313	7,556	66%	77,137	21,015	73%
Lincoln Service	70%	1,459	605	59%	36,004	14,214	61%	105,859	33,515	68%
Keystone	92%	8,163	695	91%	247,930	33,243	87%	743,508	74,054	90%
Lincoln / Missouri	60%	913	175	81%	23,322	10,313	56%	71,622	34,969	51%
Mardi Gras Service	80%	413	56	86%	11,481	919	92%	39,154	4,678	88%
Michigan	69%	2,312	548	76%	60,160	25,064	58%	179,495	54,952	69%
Blue Water	70%	726	245	66%	13,403	6,110	54%	44,188	13,405	70%
Pere Marquette	85%	325	0	100%	8,346	2,390	71%	24,242	4,319	82%
Wolverine	65%	1,261	303	76%	38,411	16,564	57%	111,065	37,228	66%
Missouri	80%	368	0	100%	7,426	1,499	80%	21,996	5,035	77%
Pacific Surfliner	85%	9,153	1,494	84%	199,340	28,878	86%	612,328	87,025	86%
Pennsylvanian	72%	1,000	4	100%	27,786	3,022	89%	84,810	9,220	89%
Piedmont	73%	1,050	75	93%	33,078	5,406	84%	117,407	27,237	77%
Vermont	75%	1,406	1,354	4%	40,559	15,470	62%	122,829	33,724	73%
Long Distance	56%	17,493	7,192	59%	397,224	141,725	64%	1,153,883	388,991	66%
Auto Train	57%	964	0	100%	23,063	2,995	87%	62,888	10,206	84%
California Zephyr	50%	1,336	149	89%	28,581	8,846	69%	85,389	24,517	71%
Cardinal	55%	0	0	-	7,944	2,987	62%	25,300	11,292	55%
City Of New Orleans	75%	866	314	64%	21,544	4,682	78%	64,870	14,404	78%
Coast Starlight	60%	2,162	1,148	47%	37,655	12,209	68%	108,193	34,584	68%
Crescent	70%	1,107	52	95%	29,965	5,181	83%	89,080	20,963	76%
Empire Builder	55%	2,246	1,714	24%	32,963	15,332	53%	93,380	35,593	62%
Floridian	40%	2,063	532	74%	53,436	32,065	40%	157,337	86,437	45%
Lake Shore Ltd	73%	1,326	776	41%	33,437	11,104	67%	89,365	19,365	78%
Palmetto	65%	993	0	100%	28,981	6,763	77%	88,790	15,194	83%
Silver Meteor	45%	1,117	86	92%	32,691	12,103	63%	95,440	30,437	68%
Southwest Chief	40%	935	734	21%	24,289	15,127	38%	75,863	45,481	40%
Sunset Ltd	70%	510	139	73%	9,948	1,873	81%	26,330	6,097	77%
Texas Eagle	50%	1,868	1,548	17%	32,727	10,458	68%	91,658	34,421	62%
Seasonal Trains	%	0	0	-	3,440	267	92%	3,440	267	92%
Winter Park Express	75%	0	0	-	3,440	267	92%	3,440	267	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00217 00000005550 "UNCLASSIFIED" 1/5/2020

Train Index Dates Through December 30, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	191,640	3,238,705	592	521,522	9,747,498	535

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,949	947,188	84	20,304	2,849,424	71
INFRASTRUCTURE PLANNED	135	4,756	947,188	50	15,337	2,849,424	54
FLEET RELIABILITY	90	33,930	3,238,705	105	81,814	9,747,498	84
TRAIN OPERATIONS	424	145,005	3,238,705	448	404,067	9,747,498	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/30/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	62	80.2%	9,086	1,445	84.1%	26,995	3,635	86.5%
Central Division	85.5%	68	13	80.9%	1,993	295	85.2%	6,015	664	89.0%
Northeast Division	80.0%	102	22	78.4%	2,920	512	82.5%	8,516	1,264	85.2%
Southeast Division	72.5%	73	16	78.1%	2,075	349	83.2%	6,274	866	86.2%
Southwest Division	77.0%	70	11	84.3%	2,098	289	86.2%	6,190	841	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/30/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	62	80.2%	9,086	1,445	84.1%	26,995	3,635	86.5%
Central Division	85.5%	68	13	80.9%	1,993	295	85.2%	6,015	664	89.0%
CDL	90.0%	2	0	100.0%	39	2	94.9%	153	8	94.8%
CHI	85.0%	28	3	89.3%	806	139	82.8%	2,439	276	88.7%
CHM	-	-	-	-	13	5	61.5%	13	5	61.5%
DEN	-	-	-	-	6	2	66.7%	6	2	66.7%
EUG	86.5%	2	1	50.0%	59	11	81.4%	176	26	85.2%
GRR	98.0%	1	1	0.0%	29	3	89.7%	90	3	96.7%
KCY	84.5%	2	1	50.0%	59	5	91.5%	179	16	91.1%
MKE	86.5%	6	0	100.0%	175	16	90.9%	531	46	91.3%
MSP	94.0%	1	0	100.0%	30	0	100.0%	91	3	96.7%
PDX	78.0%	5	1	80.0%	150	15	90.0%	456	61	86.6%
PNT	91.5%	3	0	100.0%	89	16	82.0%	215	21	90.2%
PTH	93.0%	1	0	100.0%	29	4	86.2%	90	6	93.3%
QCY	87.5%	2	1	50.0%	60	5	91.7%	182	17	90.7%
SEA	80.0%	8	3	62.5%	238	45	81.1%	723	119	83.5%
SPK	92.0%	1	-	100.0%	33	4	87.9%	94	5	94.7%
STL	88.0%	4	2	50.0%	117	21	82.1%	359	39	89.1%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	55	2	96.4%	177	6	96.6%
WIP	-	-	-	-	6	0	100.0%	6	0	100.0%
Northeast Division	80.0%	102	22	78.4%	2,920	512	82.5%	8,516	1,264	85.2%
ALB	91.5%	8	2	75.0%	240	25	89.6%	607	46	92.4%
BON	43.5%	5	1	80.0%	149	11	92.6%	436	43	90.1%
BOS	86.5%	19	6	68.4%	563	103	81.7%	1,661	206	87.6%
BRK	88.0%	5	1	80.0%	149	7	95.3%	416	20	95.2%
BTN	48.0%	1	0	100.0%	30	1	96.7%	90	18	80.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	58	5	91.4%	174	14	92.0%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	30	6	80.0%	91	17	81.3%
NFL	96.5%	2	0	100.0%	61	4	93.4%	183	8	95.6%
NHV	75.5%	6	0	100.0%	166	17	89.8%	473	80	83.1%
NYP	77.5%	44	12	72.7%	1,210	322	73.4%	3,586	752	79.0%
SAB	98.0%	1	0	100.0%	30	0	100.0%	89	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	205	8	96.1%	554	24	95.7%
TWO	84.0%	1	0	100.0%	29	3	89.7%	89	19	78.7%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	73	16	78.1%	2,075	349	83.2%	6,274	866	86.2%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	1	80.0%	150	11	92.7%	455	36	92.1%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	2	84.6%	336	88	73.8%	1,016	186	81.7%
LOR	69.5%	1	1	0.0%	30	4	86.7%	91	9	90.1%

Information Management

26-FOI-001000 Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/30/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	62	80.2%	9,086	1,445	84.1%	26,995	3,635	86.5%
Southeast Division	72.5%	73	16	78.1%	2,075	349	83.2%	6,274	866	86.2%
MIA	87.5%	2	0	100.0%	60	6	90.0%	182	19	89.6%
MOE	94.0%	2	0	100.0%	60	0	100.0%	182	3	98.4%
NFK	86.0%	3	1	66.7%	85	13	84.7%	255	28	89.0%
NOL	92.0%	4	0	100.0%	133	6	95.5%	402	20	95.0%
NPN	96.0%	2	0	100.0%	60	3	95.0%	157	10	93.6%
PGH	92.0%	1	0	100.0%	30	2	93.3%	91	3	96.7%
PHL	45.0%	5	4	20.0%	137	90	34.3%	418	213	49.0%
RGH	97.0%	4	0	100.0%	120	6	95.0%	360	9	97.5%
RNK	85.5%	2	0	100.0%	60	7	88.3%	181	21	88.4%
RVM	86.0%	1	0	100.0%	30	2	93.3%	101	13	87.1%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	30	2	93.3%	91	2	97.8%
SFA	70.5%	1	0	100.0%	30	0	100.0%	91	3	96.7%
WAS	70.0%	26	7	73.1%	724	109	84.9%	2,193	286	87.0%
Southwest Division	77.0%	70	11	84.3%	2,098	289	86.2%	6,190	841	86.4%
ARN	60.5%	1	1	0.0%	30	2	93.3%	91	7	92.3%
BFD	75.5%	7	2	71.4%	198	50	74.7%	545	134	75.4%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	35	19	45.7%	98	36	63.3%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	30	0	100.0%	90	3	96.7%
GTA	72.5%	3	0	100.0%	90	8	91.1%	266	25	90.6%
LAX	77.5%	9	0	100.0%	282	31	89.0%	842	92	89.1%
OKC	96.0%	1	0	100.0%	30	0	100.0%	91	3	96.7%
OKJ	79.0%	11	1	90.9%	328	90	72.6%	988	242	75.5%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	14	4	71.4%	415	44	89.4%	1,203	130	89.2%
SAN	77.0%	12	0	100.0%	352	23	93.5%	1,045	88	91.6%
SAS	85.0%	1	0	100.0%	30	1	96.7%	91	4	95.6%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	3	57.1%	210	17	91.9%	635	57	91.0%
SLO	62.0%	2	0	100.0%	59	3	94.9%	176	14	92.0%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	40	12	4	66.7%	39	8	79.5%	13	2	84.6%	39	6	84.6%
3		30	7	76.7%	91	11	87.9%	29	12	58.6%	90	35	61.1%
4	290	29	8	72.4%	90	14	84.4%	29	20	31.0%	90	58	35.6%
5		30	8	73.3%	90	15	83.3%	29	7	75.9%	88	13	85.2%
6		28	12	57.1%	89	29	67.4%	28	6	78.6%	89	27	69.7%
7	157	30	6	80.0%	91	10	89.0%	26	8	69.2%	87	15	82.8%
8	225	30	19	36.7%	91	39	57.1%	30	17	43.3%	91	44	51.6%
11		30	7	76.7%	90	18	80.0%	30	8	73.3%	88	15	83.0%
14		30	1	96.7%	91	10	89.0%	30	3	90.0%	90	21	76.7%
19		30	10	66.7%	91	18	80.2%	30	2	93.3%	91	13	85.7%
20		30	0	100.0%	91	6	93.4%	30	2	93.3%	91	8	91.2%
21		30	5	83.3%	90	13	85.6%	30	7	76.7%	90	18	80.0%
22	63	30	1	96.7%	91	4	95.6%	30	5	83.3%	90	18	80.0%
23		30	0	100.0%	91	3	96.7%	30	3	90.0%	91	13	85.7%
24		30	5	83.3%	91	7	92.3%	30	3	90.0%	91	9	90.1%
25		30	0	100.0%	91	0	100.0%	30	1	96.7%	91	10	89.0%
26	18	30	0	100.0%	91	2	97.8%	30	3	90.0%	91	14	84.6%
27	235	30	3	90.0%	91	4	95.6%	29	10	65.5%	90	20	77.8%
28	151	29	7	75.9%	90	20	77.8%	29	4	86.2%	90	12	86.7%
40		30	5	83.3%	91	14	84.6%	30	12	60.0%	91	34	62.6%
41		30	15	50.0%	91	33	63.7%	30	18	40.0%	91	57	37.4%
42		30	2	93.3%	91	3	96.7%	30	3	90.0%	91	12	86.8%
43		30	3	90.0%	91	8	91.2%	30	1	96.7%	91	4	95.6%
48		30	8	73.3%	91	13	85.7%	30	7	76.7%	91	10	89.0%
49	44	30	3	90.0%	91	13	85.7%	30	8	73.3%	91	13	85.7%
52		30	0	100.0%	91	3	96.7%	30	2	93.3%	91	14	84.6%
53		30	4	86.7%	91	9	90.1%	30	4	86.7%	91	12	86.8%
55	43	21	0	100.0%	63	0	100.0%	21	7	66.7%	63	13	79.4%
56	45	21	6	71.4%	63	13	79.4%	21	5	76.2%	63	11	82.5%
58		30	1	96.7%	90	3	96.7%	30	7	76.7%	89	14	84.3%
59		30	4	86.7%	89	7	92.1%	30	6	80.0%	89	9	89.9%
63	38	30	17	43.3%	91	38	58.2%	29	18	37.9%	90	47	47.8%
64	20	30	4	86.7%	90	20	77.8%	30	11	63.3%	90	21	76.7%
66	44	30	3	90.0%	91	13	85.7%	30	5	83.3%	91	18	80.2%
67	23	21	2	90.5%	63	4	93.7%	21	4	81.0%	63	11	82.5%
68		30	6	80.0%	91	17	81.3%	30	20	33.3%	91	45	50.5%
69	18	30	4	86.7%	91	11	87.9%	30	6	80.0%	91	13	85.7%
71	43	30	1	96.7%	91	1	98.9%	30	8	73.3%	91	24	73.6%
72		30	5	83.3%	91	10	89.0%	30	12	60.0%	91	22	75.8%
73		30	2	93.3%	91	3	96.7%	30	10	66.7%	90	43	52.2%
74		30	2	93.3%	91	7	92.3%	30	5	83.3%	91	25	72.5%
75		30	1	96.7%	91	3	96.7%	30	11	63.3%	91	39	57.1%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		30	0	100.0%	91	4	95.6%	30	5	83.3%	91	35	61.5%
77		30	2	93.3%	91	4	95.6%	30	8	73.3%	91	30	67.0%
78		30	1	96.7%	91	4	95.6%	30	2	93.3%	91	11	87.9%
79		30	10	66.7%	91	21	76.9%	30	4	86.7%	90	15	83.3%
80		30	3	90.0%	91	11	87.9%	30	5	83.3%	90	10	88.9%
84		21	0	100.0%	63	3	95.2%	21	7	66.7%	63	12	81.0%
85		21	2	90.5%	63	3	95.2%	21	9	57.1%	63	24	61.9%
86		21	1	95.2%	63	5	92.1%	20	14	30.0%	62	33	46.8%
89		30	5	83.3%	91	17	81.3%	30	9	70.0%	91	15	83.5%
90		30	2	93.3%	91	2	97.8%	30	3	90.0%	91	9	90.1%
93		21	4	81.0%	63	10	84.1%	21	3	85.7%	62	13	79.0%
94		21	10	52.4%	63	16	74.6%	20	6	70.0%	62	18	71.0%
95		21	1	95.2%	63	2	96.8%	21	8	61.9%	63	19	69.8%
97		30	23	23.3%	91	41	54.9%	30	3	90.0%	91	19	79.1%
98		30	1	96.7%	91	5	94.5%	30	12	60.0%	91	23	74.7%
110		21	11	47.6%	63	30	52.4%	21	4	81.0%	63	7	88.9%
111	17	21	7	66.7%	63	11	82.5%	21	5	76.2%	63	8	87.3%
112	18	21	2	90.5%	63	6	90.5%	21	4	81.0%	63	9	85.7%
114		21	5	76.2%	63	13	79.4%	20	2	90.0%	62	2	96.8%
119		21	6	71.4%	63	15	76.2%	21	5	76.2%	63	8	87.3%
125		21	0	100.0%	63	2	96.8%	21	9	57.1%	63	15	76.2%
129	20	21	11	47.6%	63	24	61.9%	21	3	85.7%	63	9	85.7%
130	18	21	1	95.2%	63	5	92.1%	21	2	90.5%	63	6	90.5%
131	69	21	6	71.4%	63	10	84.1%	21	5	76.2%	63	5	92.1%
133	26	21	8	61.9%	63	27	57.1%	21	6	71.4%	63	26	58.7%
134		21	2	90.5%	63	6	90.5%	21	4	81.0%	63	12	81.0%
136		21	4	81.0%	63	7	88.9%	20	2	90.0%	63	5	92.1%
137		21	6	71.4%	61	14	77.0%	21	8	61.9%	61	18	70.5%
138	18	21	3	85.7%	63	9	85.7%	21	3	85.7%	63	5	92.1%
141		21	0	100.0%	63	3	95.2%	21	6	71.4%	63	14	77.8%
148		21	2	90.5%	63	6	90.5%	21	1	95.2%	62	10	83.9%
151		30	16	46.7%	91	30	67.0%	30	9	70.0%	90	25	72.2%
170	25	21	3	85.7%	60	6	90.0%	21	12	42.9%	60	21	65.0%
171		21	2	90.5%	63	5	92.1%	21	7	66.7%	63	12	81.0%
172	23	21	5	76.2%	63	9	85.7%	19	9	52.6%	61	24	60.7%
173	108	21	6	71.4%	63	8	87.3%	21	12	42.9%	63	27	57.1%
174		21	0	100.0%	63	3	95.2%	21	5	76.2%	63	13	79.4%
175		21	8	61.9%	63	10	84.1%	21	11	47.6%	63	19	69.8%
176		21	2	90.5%	63	5	92.1%	21	1	95.2%	63	4	93.7%
177		21	6	71.4%	63	14	77.8%	21	7	66.7%	63	27	57.1%
178	144	21	3	85.7%	63	10	84.1%	20	4	80.0%	63	9	85.7%
179		21	2	90.5%	63	6	90.5%	20	4	80.0%	63	14	77.8%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181		21	9	57.1%	63	15	76.2%	20	2	90.0%	62	3	95.2%
182		21	3	85.7%	63	12	81.0%	21	2	90.5%	63	5	92.1%
183		21	7	66.7%	63	18	71.4%	21	4	81.0%	63	10	84.1%
184	27	21	4	81.0%	63	12	81.0%	21	6	71.4%	63	11	82.5%
185		21	4	81.0%	63	12	81.0%	21	3	85.7%	63	4	93.7%
186		21	2	90.5%	63	9	85.7%	21	3	85.7%	63	15	76.2%
190		21	10	52.4%	63	26	58.7%	21	5	76.2%	63	15	76.2%
192		21	2	90.5%	61	8	86.9%	21	1	95.2%	61	2	96.7%
193	17	21	8	61.9%	63	21	66.7%	21	9	57.1%	63	23	63.5%
196		21	1	95.2%	63	1	98.4%	21	1	95.2%	63	3	95.2%
197		21	9	57.1%	63	24	61.9%	21	7	66.7%	63	13	79.4%
232		30	1	96.7%	91	2	97.8%	30	0	100.0%	91	6	93.4%
233		30	11	63.3%	91	24	73.6%	30	8	73.3%	91	20	78.0%
234		30	1	96.7%	91	4	95.6%	30	1	96.7%	91	3	96.7%
235		30	4	86.7%	30	4	86.7%	30	6	80.0%	30	6	80.0%
236		30	0	100.0%	91	1	98.9%	30	5	83.3%	91	16	82.4%
237		29	5	82.8%	90	15	83.3%	28	3	89.3%	89	7	92.1%
238		30	6	80.0%	30	6	80.0%	30	3	90.0%	30	3	90.0%
239		30	9	70.0%	90	24	73.3%	30	2	93.3%	90	4	95.6%
240		30	3	90.0%	91	9	90.1%	30	5	83.3%	91	12	86.8%
241		30	8	73.3%	91	24	73.6%	30	4	86.7%	91	14	84.6%
243		21	6	71.4%	63	22	65.1%	21	4	81.0%	64	12	81.3%
244		30	3	90.0%	91	5	94.5%	30	3	90.0%	91	18	80.2%
280	19	30	1	96.7%	91	4	95.6%	30	7	76.7%	91	17	81.3%
281		30	1	96.7%	91	9	90.1%	30	5	83.3%	91	10	89.0%
283		30	11	63.3%	91	19	79.1%	30	6	80.0%	91	15	83.5%
284		30	2	93.3%	91	3	96.7%	29	2	93.1%	90	7	92.2%
290	19	30	1	96.7%	91	19	79.1%	30	10	66.7%	90	31	65.6%
291		30	5	83.3%	91	18	80.2%	30	3	90.0%	91	15	83.5%
300	51	30	8	73.3%	91	10	89.0%	30	11	63.3%	90	25	72.2%
301		29	1	96.6%	89	2	97.8%	29	7	75.9%	88	16	81.8%
302	29	28	6	78.6%	88	12	86.4%	28	10	64.3%	86	27	68.6%
305		30	7	76.7%	91	12	86.8%	29	15	48.3%	89	35	60.7%
306		29	4	86.2%	89	6	93.3%	29	9	69.0%	88	20	77.3%
307		30	5	83.3%	90	10	88.9%	29	9	69.0%	89	20	77.5%
311		30	3	90.0%	90	10	88.9%	29	6	79.3%	89	20	77.5%
316		29	2	93.1%	89	5	94.4%	29	6	79.3%	89	18	79.8%
318		30	3	90.0%	91	12	86.8%	30	11	63.3%	90	36	60.0%
319	20	30	2	93.3%	91	4	95.6%	30	12	60.0%	91	48	47.3%
329		21	2	90.5%	63	3	95.2%	21	3	85.7%	63	5	92.1%
330		25	0	100.0%	76	2	97.4%	25	4	84.0%	76	5	93.4%
331		30	7	76.7%	91	11	87.9%	30	8	73.3%	91	14	84.6%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		30	4	86.7%	91	9	90.1%	30	11	63.3%	91	16	82.4%
334		30	1	96.7%	91	2	97.8%	30	8	73.3%	90	12	86.7%
335	12	30	7	76.7%	91	14	84.6%	29	8	72.4%	89	17	80.9%
336		30	3	90.0%	91	4	95.6%	30	1	96.7%	91	5	94.5%
337	17	30	1	96.7%	91	5	94.5%	30	7	76.7%	91	12	86.8%
338		30	6	80.0%	91	21	76.9%	29	10	65.5%	89	22	75.3%
339	37	30	5	83.3%	91	19	79.1%	30	8	73.3%	91	19	79.1%
341	45	28	7	75.0%	88	16	81.8%	27	6	77.8%	87	14	83.9%
342	19	30	2	93.3%	91	8	91.2%	30	8	73.3%	90	16	82.2%
350		30	1	96.7%	73	3	95.9%	30	19	36.7%	73	41	43.8%
351		30	9	70.0%	91	12	86.8%	30	12	60.0%	91	38	58.2%
352	19	30	3	90.0%	91	7	92.3%	29	11	62.1%	88	25	71.6%
353		30	3	90.0%	70	5	92.9%	30	11	63.3%	70	16	77.1%
354	40	30	5	83.3%	91	8	91.2%	28	14	50.0%	89	28	68.5%
355		29	4	86.2%	90	9	90.0%	28	12	57.1%	89	25	71.9%
364		29	12	58.6%	90	17	81.1%	28	12	57.1%	89	20	77.5%
365		29	4	86.2%	90	6	93.3%	28	11	60.7%	89	27	69.7%
370		30	3	90.0%	91	5	94.5%	30	7	76.7%	91	16	82.4%
371		29	3	89.7%	90	3	96.7%	29	7	75.9%	90	11	87.8%
380	29	30	5	83.3%	91	15	83.5%	30	8	73.3%	91	21	76.9%
381		30	1	96.7%	91	2	97.8%	30	4	86.7%	91	11	87.9%
382		30	0	100.0%	91	2	97.8%	30	8	73.3%	91	23	74.7%
383	19	30	4	86.7%	91	9	90.1%	29	14	51.7%	89	36	59.6%
390	18	22	5	77.3%	75	9	88.0%	21	8	61.9%	74	24	67.6%
391		22	2	90.9%	76	2	97.4%	21	3	85.7%	74	15	79.7%
392		30	2	93.3%	91	4	95.6%	30	13	56.7%	90	28	68.9%
393		30	2	93.3%	91	7	92.3%	30	10	66.7%	90	25	72.2%
417		21	2	90.5%	60	10	83.3%	20	1	95.0%	57	2	96.5%
425		21	1	95.2%	60	2	96.7%	21	1	95.2%	60	2	96.7%
448		30	12	60.0%	32	13	59.4%	29	12	58.6%	30	12	60.0%
449		29	1	96.6%	29	1	96.6%	29	5	82.8%	29	5	82.8%
470		23	8	65.2%	65	13	80.0%	21	5	76.2%	63	12	81.0%
471		21	1	95.2%	60	1	98.3%	21	0	100.0%	60	0	100.0%
473		21	0	100.0%	63	3	95.2%	21	0	100.0%	63	1	98.4%
474		21	5	76.2%	61	18	70.5%	20	7	65.0%	57	18	68.4%
475		21	0	100.0%	63	0	100.0%	21	0	100.0%	63	1	98.4%
478		21	3	85.7%	61	13	78.7%	21	1	95.2%	61	7	88.5%
479		21	3	85.7%	63	7	88.9%	21	2	90.5%	63	3	95.2%
486		21	1	95.2%	64	8	87.5%	21	5	76.2%	63	11	82.5%
490		21	2	90.5%	40	7	82.5%	21	0	100.0%	40	2	95.0%
494		21	0	100.0%	65	9	86.2%	21	4	81.0%	62	11	82.3%
495		21	0	100.0%	63	2	96.8%	21	0	100.0%	63	1	98.4%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
500	37	30	1	96.7%	91	6	93.4%	30	5	83.3%	90	10	88.9%
502	25	30	1	96.7%	91	7	92.3%	30	5	83.3%	90	21	76.7%
503		30	3	90.0%	88	11	87.5%	30	7	76.7%	87	22	74.7%
504		30	3	90.0%	91	8	91.2%	29	6	79.3%	90	25	72.2%
505		30	6	80.0%	91	16	82.4%	30	4	86.7%	89	17	80.9%
506		30	5	83.3%	90	14	84.4%	30	4	86.7%	89	13	85.4%
507		30	4	86.7%	91	11	87.9%	30	9	70.0%	91	31	65.9%
508		30	9	70.0%	89	20	77.5%	30	8	73.3%	89	21	76.4%
509		30	3	90.0%	91	7	92.3%	30	12	60.0%	91	25	72.5%
511	36	30	6	80.0%	91	10	89.0%	30	5	83.3%	91	17	81.3%
516	33	28	0	100.0%	89	9	89.9%	28	9	67.9%	89	37	58.4%
517		30	1	96.7%	91	2	97.8%	30	9	70.0%	90	31	65.6%
518	41	30	0	100.0%	91	13	85.7%	30	18	40.0%	91	54	40.7%
519		28	1	96.4%	89	4	95.5%	28	4	85.7%	89	13	85.4%
521		20	0	100.0%	61	0	100.0%	20	1	95.0%	61	4	93.4%
522		20	5	75.0%	61	9	85.2%	19	1	94.7%	60	5	91.7%
523		20	0	100.0%	61	0	100.0%	20	4	80.0%	61	8	86.9%
524		20	0	100.0%	61	2	96.7%	20	1	95.0%	61	4	93.4%
525		20	2	90.0%	61	3	95.1%	19	1	94.7%	60	6	90.0%
526		20	4	80.0%	61	10	83.6%	19	2	89.5%	60	6	90.0%
527		20	0	100.0%	61	1	98.4%	20	1	95.0%	61	3	95.1%
528		20	1	95.0%	61	6	90.2%	20	3	85.0%	61	13	78.7%
529	38	20	1	95.0%	61	4	93.4%	20	6	70.0%	61	13	78.7%
530		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
531		20	0	100.0%	61	1	98.4%	20	3	85.0%	61	6	90.2%
532		20	4	80.0%	61	5	91.8%	20	1	95.0%	61	8	86.9%
535		16	5	68.8%	54	6	88.9%	15	3	80.0%	53	4	92.5%
536		20	6	70.0%	61	10	83.6%	18	2	88.9%	59	3	94.9%
538		20	4	80.0%	61	10	83.6%	20	4	80.0%	61	9	85.2%
539		15	2	86.7%	15	2	86.7%	15	8	46.7%	15	8	46.7%
540		20	3	85.0%	61	7	88.5%	19	1	94.7%	58	2	96.6%
541		20	3	85.0%	61	8	86.9%	20	4	80.0%	61	15	75.4%
542		20	2	90.0%	61	5	91.8%	20	1	95.0%	60	11	81.7%
543		20	0	100.0%	61	6	90.2%	20	3	85.0%	61	15	75.4%
544	Cncld	20	3	85.0%	60	5	91.7%	19	3	84.2%	59	7	88.1%
545		20	2	90.0%	61	6	90.2%	20	1	95.0%	60	5	91.7%
547	20	20	2	90.0%	61	6	90.2%	20	6	70.0%	61	13	78.7%
548		20	2	90.0%	61	10	83.6%	20	1	95.0%	61	6	90.2%
549		20	3	85.0%	58	13	77.6%	18	1	94.4%	55	7	87.3%
550	40	15	3	80.0%	15	3	80.0%	15	2	86.7%	15	2	86.7%
562		30	3	90.0%	89	11	87.6%	30	3	90.0%	88	9	89.8%
564		30	3	90.0%	89	9	89.9%	29	2	93.1%	85	12	85.9%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
566		30	1	96.7%	89	6	93.3%	30	2	93.3%	86	8	90.7%
572		30	1	96.7%	88	7	92.0%	29	3	89.7%	86	17	80.2%
573		30	3	90.0%	89	12	86.5%	29	2	93.1%	87	10	88.5%
577		30	2	93.3%	87	7	92.0%	30	6	80.0%	83	8	90.4%
580		30	0	100.0%	89	2	97.8%	30	2	93.3%	89	9	89.9%
581		30	2	93.3%	89	9	89.9%	30	3	90.0%	89	15	83.1%
582		30	2	93.3%	89	6	93.3%	30	3	90.0%	87	7	92.0%
586		30	8	73.3%	89	19	78.7%	28	2	92.9%	84	11	86.9%
587		30	1	96.7%	89	4	95.5%	28	1	96.4%	85	10	88.2%
591		30	1	96.7%	89	2	97.8%	29	2	93.1%	88	8	90.9%
593		30	5	83.3%	89	14	84.3%	28	4	85.7%	81	9	88.9%
595		30	5	83.3%	88	19	78.4%	30	4	86.7%	87	14	83.9%
600		21	1	95.2%	63	2	96.8%	21	1	95.2%	63	5	92.1%
601		21	16	23.8%	63	35	44.4%	21	2	90.5%	63	15	76.2%
605		21	19	9.5%	63	40	36.5%	21	4	81.0%	62	6	90.3%
607		21	1	95.2%	63	4	93.7%	21	3	85.7%	62	4	93.5%
609		21	4	81.0%	62	5	91.9%	21	1	95.2%	62	4	93.5%
620		21	9	57.1%	62	18	71.0%	21	1	95.2%	60	3	95.0%
624		21	9	57.1%	63	19	69.8%	20	4	80.0%	63	13	79.4%
639		21	8	61.9%	63	18	71.4%	21	3	85.7%	63	7	88.9%
640	13	21	3	85.7%	63	5	92.1%	20	14	30.0%	62	32	48.4%
641		21	9	57.1%	63	14	77.8%	21	5	76.2%	63	12	81.0%
642		21	2	90.5%	62	4	93.5%	21	4	81.0%	62	8	87.1%
643		21	7	66.7%	63	14	77.8%	21	7	66.7%	62	10	83.9%
644	22	21	5	76.2%	63	10	84.1%	21	9	57.1%	63	14	77.8%
645		21	5	76.2%	63	8	87.3%	21	5	76.2%	63	11	82.5%
646	13	21	8	61.9%	63	15	76.2%	21	16	23.8%	62	36	41.9%
647		21	5	76.2%	63	7	88.9%	21	4	81.0%	63	16	74.6%
648		21	8	61.9%	63	14	77.8%	21	6	71.4%	63	10	84.1%
649		21	5	76.2%	63	11	82.5%	21	2	90.5%	62	9	85.5%
650	17	21	5	76.2%	63	14	77.8%	21	8	61.9%	63	15	76.2%
651		21	0	100.0%	63	5	92.1%	21	5	76.2%	63	18	71.4%
652		21	4	81.0%	63	12	81.0%	21	4	81.0%	62	12	80.6%
653		21	4	81.0%	63	12	81.0%	21	3	85.7%	63	17	73.0%
654		21	9	57.1%	63	14	77.8%	21	3	85.7%	63	5	92.1%
655		21	6	71.4%	61	18	70.5%	21	11	47.6%	60	19	68.3%
656		21	9	57.1%	63	16	74.6%	21	0	100.0%	63	5	92.1%
657		21	0	100.0%	63	3	95.2%	21	3	85.7%	63	12	81.0%
658		21	2	90.5%	63	9	85.7%	21	4	81.0%	63	10	84.1%
680		22	0	100.0%	65	2	96.9%	22	4	81.8%	65	7	89.2%
681		22	1	95.5%	65	3	95.4%	22	6	72.7%	65	19	70.8%
682		22	0	100.0%	65	0	100.0%	22	4	81.8%	65	14	78.5%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
683	35	22	1	95.5%	48	4	91.7%	22	6	72.7%	48	15	68.8%
684	16	21	5	76.2%	46	9	80.4%	21	6	71.4%	46	14	69.6%
685		21	4	81.0%	63	8	87.3%	21	4	81.0%	63	17	73.0%
686		22	2	90.9%	65	15	76.9%	22	4	81.8%	65	14	78.5%
687		22	3	86.4%	65	9	86.2%	22	5	77.3%	65	11	83.1%
688		22	0	100.0%	65	1	98.5%	22	2	90.9%	65	14	78.5%
689	Cncld	18	1	94.4%	54	5	90.7%	16	1	93.8%	52	4	92.3%
701		23	6	73.9%	23	6	73.9%	23	2	91.3%	23	2	91.3%
702		30	3	90.0%	91	18	80.2%	30	5	83.3%	90	24	73.3%
703		30	8	73.3%	91	23	74.7%	30	8	73.3%	91	24	73.6%
704		23	3	87.0%	23	3	87.0%	22	4	81.8%	22	4	81.8%
710		30	11	63.3%	91	35	61.5%	30	6	80.0%	91	34	62.6%
711		28	4	85.7%	85	8	90.6%	25	5	80.0%	78	12	84.6%
712		30	5	83.3%	91	22	75.8%	29	9	69.0%	89	32	64.0%
713	Cncld	27	3	88.9%	88	12	86.4%	22	6	72.7%	77	33	57.1%
714		30	11	63.3%	85	30	64.7%	28	8	71.4%	78	24	69.2%
715		30	8	73.3%	91	30	67.0%	26	13	50.0%	84	42	50.0%
716		30	17	43.3%	91	40	56.0%	29	17	41.4%	89	40	55.1%
717	78	30	10	66.7%	82	23	72.0%	28	14	50.0%	75	27	64.0%
718		30	17	43.3%	91	39	57.1%	29	13	55.2%	90	29	67.8%
719		30	11	63.3%	91	35	61.5%	30	15	50.0%	89	31	65.2%
761		30	0	100.0%	89	3	96.6%	30	5	83.3%	89	14	84.3%
765		30	1	96.7%	89	8	91.0%	30	3	90.0%	89	16	82.0%
769	21	30	3	90.0%	89	7	92.1%	30	6	80.0%	87	17	80.5%
770		30	3	90.0%	89	10	88.8%	30	5	83.3%	89	14	84.3%
774		30	1	96.7%	89	7	92.1%	30	7	76.7%	88	18	79.5%
779		30	0	100.0%	89	4	95.5%	30	9	70.0%	88	18	79.5%
784	36	30	4	86.7%	89	10	88.8%	30	18	40.0%	88	47	46.6%
785		30	0	100.0%	89	0	100.0%	30	7	76.7%	89	14	84.3%
790		30	1	96.7%	89	6	93.3%	30	4	86.7%	89	11	87.6%
794		30	2	93.3%	89	7	92.1%	30	6	80.0%	88	16	81.8%
821		30	0	100.0%	91	3	96.7%	30	6	80.0%	91	46	49.5%
822		30	0	100.0%	91	3	96.7%	30	3	90.0%	91	47	48.4%
1333		30	6	80.0%	91	10	89.0%	30	10	66.7%	90	36	60.0%
1340	22	30	0	100.0%	91	3	96.7%	30	9	70.0%	91	22	75.8%
2103	19	21	2	90.5%	62	5	91.9%	21	4	81.0%	62	5	91.9%
2104		21	4	81.0%	33	6	81.8%	21	3	85.7%	33	5	84.8%
2107		21	5	76.2%	63	12	81.0%	21	5	76.2%	61	5	91.8%
2108		21	4	81.0%	63	6	90.5%	21	2	90.5%	61	2	96.7%
2117		21	7	66.7%	33	10	69.7%	21	5	76.2%	33	6	81.8%
2121		21	5	76.2%	61	8	86.9%	21	3	85.7%	61	6	90.2%
2122		21	5	76.2%	63	11	82.5%	21	1	95.2%	63	4	93.7%

Amtrak On Time Performance

Trains Arriving Through: 12/30/2025

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2124		16	3	81.3%	46	7	84.8%	16	2	87.5%	46	3	93.5%
2150	45	21	6	71.4%	63	15	76.2%	19	7	63.2%	61	16	73.8%
2151	47	20	0	100.0%	62	0	100.0%	20	7	65.0%	61	13	78.7%
2152	38	21	1	95.2%	59	3	94.9%	21	16	23.8%	58	25	56.9%
2153		21	3	85.7%	63	9	85.7%	21	5	76.2%	63	14	77.8%
2154	19	21	4	81.0%	63	18	71.4%	20	12	40.0%	60	33	45.0%
2155	194	21	3	85.7%	63	5	92.1%	21	12	42.9%	61	21	65.6%
2159	17	21	2	90.5%	62	3	95.2%	20	9	55.0%	61	16	73.8%
2162	17	21	0	100.0%	63	2	96.8%	20	8	60.0%	61	17	72.1%
2163	Cncld	21	2	90.5%	63	6	90.5%	20	8	60.0%	62	18	71.0%
2166		21	1	95.2%	63	6	90.5%	21	6	71.4%	61	12	80.3%
2167	141	19	5	73.7%	61	10	83.6%	19	8	57.9%	61	16	73.8%
2168	50	20	2	90.0%	62	4	93.5%	20	3	85.0%	62	9	85.5%
2169	85	21	15	28.6%	59	25	57.6%	21	17	19.0%	59	32	45.8%
2170	19	21	5	76.2%	63	12	81.0%	19	5	73.7%	61	14	77.0%
2172	196	21	2	90.5%	63	8	87.3%	21	6	71.4%	63	13	79.4%
2173		21	5	76.2%	62	12	80.6%	21	6	71.4%	62	24	61.3%
2190	Cncld	20	4	80.0%	62	9	85.5%	18	5	72.2%	60	9	85.0%
2193	21	21	2	90.5%	62	3	95.2%	21	12	42.9%	62	21	66.1%

Amtrak Endpoint OTP Details

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/30/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2103	WAS	19	CTP	22	CTP	22	BAL-XNY	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C DISABLED MK401 AT MP 104
2150	BOS	45	WTR	26	WTR	11	RTE-BBY	AM	Wet / slippery rail, Milepost, rte, bby, held at RTE disable AM 2190 between Plains to Cove on trk 2. Due to ice.
2151	WAS	47	DMW	18	DMW	18	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2152	BOS	38	WTR	37	WTR	23	RTE-BBY	AM	Ice / snow on or under equipment, Control Point, Forest, Waiting at Forest for AM173 due to disable AM 2190 between Plains to Cove on trk 2. Due to ice.
2154	BOS	19	WTR	21	WTR	11	RTE-BBY	AM	Ice / snow on or under equipment, Control Point, XRF, Control Point, XT1, Held at Plains for 137 to clear trk2 a/c ice patrol on trk1
2155	WAS	194	SVS	89	SVS	89	BOS-BOS	AM	Water, commissary, toilet/trash dumping, Delayed loading commissary
2159	WAS	17	OTH	12	CAR	8	BWI-BWI	AM	Door, C/3548
2162	BOS	17	OTH	21	CAR	10	NHV-NHV	AM	Door, 3061, DOOR ISSUES
2163	XHM	Trn Cancelled							
2167	WAS	141	ITI	68	ITI	68	BOS-BOS	AM	Service, turn, or wye train, 2150, Late turn
2168	BOS	50	DBS	32	DBS	32	PVD-RTE	AM	Animal strike, Control Point, 212.95, ANIMAL ON TRK
2169	WAS	85	ITI	62	ITI	62	BOS-BOS	AM	Service, turn, or wye train, 2152, LATE TURN OF 2152
2170	BOS	19	OTH	23	DSR	14	STM-NHV	MN	Per bulletin Control Point, cp241, 15, 4
2172	BOS	196	ITI	162	ITI	162	WAS-WAS	AM	Service, turn, or wye train, 2155, DUE TO MULTIPLE MECH ISSUES FROM BOSTON AND THROUGHOUT THE ENTIRE TRIP
2190	BOS	Trn Cancelled	OTH	15	OTH	6	PVD-RTE	AM	Lost time - N.A.R.
2193	NYP	21	DSR	10	SMW	10	XSH-NYP	AM	Scheduled in track usage program, Other, XPB, HELD A/C SINGLE TRACKING PELHAM BAY TO LEGGETT DUE TO SCHEDULED MAINTENANCE WORK ON NO.1 TRK
66	BOS	44	WTR	48	WTR	46	RTE-BBY	AM	Ice / snow on or under equipment, Milepost, rte, bby, held for disable AM2190 lost catenary

Amtrak Endpoint OTP Details

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/30/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
67	NPN	23	HLD	7	DSR	6	BRP-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.6, 30, 1	
111	WAS	17	CTP	25	CTP	15	BAL-BWI	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C DISABLED MK401 AT MP 104	
112	NYP	18	WTR	20	WTR	20	NWK-NYP	AM	Ice / snow on or under equipment, Other, XBH, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE	
129	WAS	20	OTH	20	OTH	15	PHL-PHL	AM	Person pulling emergency cord	
130	NYP	18	CTI	10	CTI	10	NWK-NYP	AM	Follow, NJT, NJ3934, Other, NWK-NYP	
131	WAS	69	SVS	51	SVS	51	NYP-NYP	AM	Routine inspections, NECESSARY FOR ENG.613 TO RUNN AROUND TRAIN A/C ONLY 1 ENGINE IN CONSIST	
133	WAS	26	PTI	12	PTI	12	XPV-BAL	AM	Follow, 2121, Control Point, GRACE, HELD FOR AMTRAK 2121	
138	NYP	18	TRS	35	TRS	35	XPV-WIL	AM	Vehicle strike, Control Point, Church crossing, HELD A/C HOLD ON ALL TRACKS SEPTA 5227 VEHICLE STRIKE. MP 36.0	
170	BOS	25	OTH	23	WTR	18	RTE-BBY	AM	Ice / snow on or under equipment, Milepost, RTE, BBY, disable AM 2190 between Plains to Cove on trk 2. Due to ice.	
172	BOS	23	WTR	22	WTR	20	NWK-NYP	AM	Ice / snow on or under equipment, Other, XBH, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE	
173	WAS	108	ENG	84	ENG	71	BOS-BOS	AM	Other electrical failure, 640, late release from yard had a hot journal alarm	
178	BOS	144	ENG	307	ENG	154	WAS-XNY	AM	Other electrical failure, 654, ENG - THE TRAIN DP ON TIME AND STOPPED DUE TO JOURNAL ALARM IN THE ENG 654. 178 DP WAS 6: 35 PM.	
184	BOS	27	DBS	31	DBS	31	PVD-RTE	AM	Animal strike, Milepost w/Letters, PVD, RTE, ANIMAL ON TRK AT MP 212.95	
193	WAS	17	HLD	10	BSP	6	PHL-WIL	AM	Bridge strike, Milepost, 15.50, .	
640	NYP	13	CTI	19	CTI	9	NWK-NYP	AM	Follow, NJT, NJ3224, Other, ALLIED-NYP	
644	NYP	22	WTR	23	WTR	23	NWK-NYP	AM	Ice / snow on or under equipment, Other, XBH, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE	
646	NYP	13	PTI	12	PTI	12	PJC-NWK	AM	Follow, AM2162, Other, XIS-NWK	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/30/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
650	NYP	17	PTI	9	PTI	6	PJC-NWK	AM	Cross over or go around, AM2166, Other, PJC-NWK, OPR NO.1 TRK PJC-MIDWAY A/C AM2166 ON 2 TRK, THEN CONTIUED FOLLOWING AM2166 ON NO.2 TRK COUNTY TO NEWARK.	
683	BRK	35	PTI	35	PTI	23	WEM-SAO	CS	Meet 686, Control Point, wells	
684	BON	16	ITI	15	ITI	15	BRK-BRK	CS	Service, turn, or wye train 684	
689	BRK	Trn Cancelled	PTI	85	PTI	85	POR-FRE	CS	Wait for station track yard, Other, 1.63 mountain	
63	TWO	38	HLD	23	DBB	20	NYP-NYP	AM	Escalator malfunction, Other, NYP, LATE LOADING A/C ESCALATOR MALFUNCTION ON 7/8 TRK PLATFORM	
64	ALB	20	CUI	47	CUI	47	NFL-NFL	CS	United States	
69	MTR	-19	CUI	36	CUI	36	XLQ-XLQ	CN	Canada	
280	NYP	19	FTI	23	FTI	13	UCA-AMS	CS	Follow R66, Milepost, 200.0, 182.0	
290	NYP	19	CTI	26	PTI	15	XWH-FED	DH	Meet 69, Control Point, 56	
49	CHI	44	FTI	36	WTR	30	BUF-ERI	CS	High winds Milepost w/Letters, QD37.00, QD75.00	
71	CLT	43	TEN	52	TEN	29	DNC-GRO	NS	HEP HEP shutdown attempted to restart at on both engines at Mebane, NC1893	
55	WAS	43	DSR	22	DSR	14	BRP-STM	MN	Per bulletin Control Point, 241, 15, 2	
56	SAB	45	CAR	31	CAR	29	WAS-WAS	AM	Air / Brake / Wheel, 48154, BRAKES WOULDN'T APPLY NEC'Y TO DUMP TRN AND RECHARGE	
26	MOE	18	FTI	38	FTI	27	PAG-MOE	CS	Follow M606, Milepost, 000678, 000668.4	
529	SJC	38	CAR	37	CAR	37	ARN-ARN	UP	Air / Brake / Wheel C8301, Shelling issues and mechanical hold for authorization of movement	
544	SAC	Trn Cancelled								
547	SJC	20	MBO	21	MBO	21	SUI-MTZ	UP	For maritime traffic Other, Benicia	
550	SAC	40	SVS	29	SVS	29	OKJ-EMY	UP	Planned set out / pick out of locomotives, cars or section of train Dropped dead 544 in yard, Other, OMF	
500	SEA	37	FTI	20	FTI	17	CTL-CTL	BN	Follow Waited for BNSF 6918 to go restricted speed to clear the block, BNSF 6918, Other, CTL station	
502	SEA	25	PTI	22	PTI	15	XNI-TAC	ST	Meet 11, Control Point, Manitou	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 12/30/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
511	PDX	36	FTI	29	FTI	29	XA4-XTW	BN	Meet BNSF 8250, BNSF 7424, Control Point, Pacific
516	VAC	33	FTI	31	FTI	16	XF2-X1J	BN	Cross over or go around Control Point, North Road, CN 2307
518	VAC	41	CTI	46	CTI	24	TAC-XTW	ST	Meet Sound Transit, Control Point, Portland Ave
7	SEA	157	DCS	204	DCS	155	FAR-GFK	BN	Power switch failure Maintainer is working on DL Switch, Control Point, spirit
8	CHI	225	RTE	160	RTE	157	SBY-SBY	BN	Dispatcher hold Due to broken down freight at dunkirk bn 5068, Control Point, sby
27	PDX	42	CAR	78	CAR	60	WIH-WIH	BN	Set out defective car 32028, Hot bearing
28	SPK	151	ITI	171	ITI	171	PDX-PDX	BN	Service, turn, or wye train 27
335	MKE	12	CTI	10	CTI	10	GLN-XRO	ME	Follow Going to the Fox Lake sub, Metra, 2117, Milepost, 21.1, 27.8
337	MKE	17	DCS	11	DCS	11	SVT-MKA	CP	Issue with automatic road crossing protection Milepost, 65.51, 65.51, Milepost, 65.94, 65.94
339	MKE	37	DCS	18	DCS	18	SVT-MKA	CP	Issue with automatic road crossing protection Had Procedure #1's at Kraut Rd (65.51) and Cty Hwy K (65.94) No flaggers were present, had to protect both crossings. Had to contend with a fair amount of traffic on Cty Hwy K., Milepost, 65.51, 65.51, Milepost, 65.94, 65.94
341	MKE	45	ENG	29	ENG	29	CHI-CHI	AM	HEP 53
342	CHI	19	DCS	8	DCS	8	MKA-SVT	CP	Issue with automatic road crossing protection Procedure #1's at both Cty Hwy K (65.94) and Kraut Rd (65.51). Flaggers were present at Kraut Rd, but we had to flag Cty Hwy K ourselves., Milepost, 65.94, 65.94, Milepost, 65.51, 65.51
352	PNT	19	PTI	19	PTI	19	JXN-ARB	MI	Meet am355, Control Point, 52
354	PNT	40	PTI	34	PTI	34	KAL-XGO	MI	Meet amt355, Other, 124
769	GTA	21	CTI	21	CTI	12	SNC-IRV	SC	Meet Elevator out of service/meet Metrolink @ CP Bake., Metrolink, Control Point, Bake
784	SAN	36	PTI	46	PTI	15	SBA-CPN	UP	Meet amtk, Other, south sba
713	OKJ	Trn Cancelled	DCS	8	DCS	4	WAC-COC	BN	Issue with automatic road crossing protection Pond road box2, Milepost, 921.45, 921.45
717	OKJ	78	ENG	49	ENG	49	BFD-BFD	BN	Loading problem Locomotive drops the load at run 2 losing traction., C2124
4	CHI	290	ENG	305	ENG	300	LAX-LAX	SC	Set out defective locomotive 136, 22

Amtrak Endpoint OTP Details

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/30/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2	NOL	40	RTE	77	FTI	23	NIB-SCH	BN	Follow UP 1500, Milepost, 70.8, 55.7	
22	CHI	63	FTI	138	FTI	102	MHL-TXA	UP	Meet UPRR cond inspecting train for dragging equipment., up 3073, Other, Sulphur	
300	CHI	51	DCS	63	DCS	59	CRV-SPI	UP	Power switch failure Signal/switch failure., Control Point, X210	
302	CHI	29	DCS	44	DCS	36	CRV-SPI	UP	Restrictive signal(s) from unknown cause Track light, flagged by 214, Stop, Milepost, 214, 206	
380	CHI	29	DCS	30	DCS	22	MDT-PLO	BN	Power switch failure Put to the 2B switch on hand, XO 2-1, Control Point, Electrics	
383	QCY	19	FTI	18	FTI	11	NPV-PLO	BN	Meet bnsf, Control Point, Eola	
390	CHI	18	DSR	19	FTI	11	RTL-GLM	CC	Cross over or go around cn8914, Siding, Paxton	
319	KCY	20	CAR	37	CAR	24	WAR-LEE	UP	Air / Brake / Wheel ID4016, Air hose and Mr	
1340	CHI	22	DCS	13	DCS	10	MKA-SVT	CP	Issue with automatic road crossing protection Milepost, 65.94, 65.94, Milepost, 65.51, 65.51	

Amtrak Initial Terminal Details

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/30/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	72	12/30	11	11	Service, turn, or wye train 71
HAR	646	12/30	1		
HAR	648	12/30	3	3	Door, ENTIRE TRAIN
LOR	53	12/30	10	10	Routine inspections Milepost, 92.1, 92.1
NFK	94	12/30	6	6	Dispatcher hold NS held us @ Princess waiting on a signal, Control Point, Princess
PHL	110	12/30	2	2	Passenger and/or baggage, LATE RUNNERS PER CNDR; 649AM
PHL	151	12/30	(No OS)		
PHL	601	12/30	1		
PHL	605	12/30	2	2	Passenger and/or baggage
WAS	56	12/30	29	29	Air / Brake / Wheel, 48154, BRAKES WOULDN'T APPLY NEC'Y TO DUMP TRN AND RECHARGE
WAS	114	12/30	5	5	Door, 82752
WAS	136	12/30	40	40	Disabled train ahead, Other, X, ARRIVED LATE DUE TO FOLLOWING DELAYED 2155
WAS	172	12/30	3	3	Other late crew, ENGNR STUCK ON ON LATE MARC TRN
WAS	2108	12/30	1		
WAS	2122	12/30	10	10	Cab signal failure, 2014-2019, ATC FAULT
WAS	2172	12/30	162	162	Service, turn, or wye train, 2155, DUE TO MULTIPLE MECH ISSUES FROM BOSTON AND THROUGHOUT THE ENTIRE TRIP
ALB	238	12/30	4	4	Pick up equipment Control Point, alb
ALB	448	12/29	3	3	Planned set out / pick out of locomotives, cars or section of train Control Point, 142
BON	685	12/30	2	2	Lost signal code Control Point, bon
BOS	93	12/30	5	5	Ice / snow on or under equipment, Milepost, bos, bos, OCS power down
BOS	173	12/30	71	71	Other electrical failure, 640, late release from yard had a hot journal alarm
BOS	2155	12/30	89	89	Water, commissary, toilet/trash dumping, Delayed loading commissary
BOS	2163	12/30	(Trn Cxld)		Equipment Issues
BOS	2167	12/30	68	68	Service, turn, or wye train, 2150, Late turn
BOS	2169	12/30	62	62	Service, turn, or wye train, 2152, LATE TURN OF 2152
BRK	684	12/30	15	15	Service, turn, or wye train 684
NYP	63	12/30	20	20	Escalator malfunction, Other, NYP, LATE LOADING A/C ESCALATOR MALFUNCTION ON 7/8 TRK PLATFORM

Amtrak Initial Terminal Details

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/30/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	79	12/30	4	4	Passenger and/or baggage, LOADING
NYP	97	12/30	8	8	Water, commissary, toilet/trash dumping, LATE RELEASE F/SSYD A/C CATERING
NYP	111	12/30	2	2	Passenger and/or baggage, LATE BOARDING PSGRS
NYP	119	12/30	16	16	Ice / snow on or under equipment, Other, NYP
NYP	131	12/30	51	51	Routine inspections, NECESSARY FOR ENG.613 TO RUNN AROUND TRAIN A/C ONLY 1 ENGINE IN CONSIST
NYP	193	12/30	4	4	Passenger and/or baggage, BOARDING
NYP	233	12/30	4	4	Passenger and/or baggage, BOARDING
NYP	645	12/30	8	8	Ice / snow on or under equipment, Other, NYP, CONGESTION LATE TRAINS AHD DUE TO ICE PATROL IN SOUTH TUBE
NYP	649	12/30	4	4	Passenger and/or baggage, LOADING
NYP	2117	12/30	8	8	Ice / snow on or under equipment, Other, NYP, LATE TURN OFF AM2104 A/C ICE PATROL IN SOUTH TUBE
NYP	2153	12/30	10	10	Delay in Block, UNSPECIFIED PAPERWORK ISSUE
CHI	7	12/30	27	27	Service, turn, or wye train 8
CHI	41	12/30	7	7	Failure of diesel engine Sander needed looked at by mechanical, 15
CHI	341	12/30	29	29	HEP 53
EUG	508	12/30	4	4	Clear the siding at Eugene for the arrival of the UP 2076 North prior to our departure. UP 2076, Siding, Eugene
GRR	371	12/30	7	7	Door ID4111, ID4129, ID4202, ID4306, Cut-out door
KCY	318	12/30	1		
PDX	28	12/30	22	22	Service, turn, or wye train 27
QCY	380	12/30	3	3	Door ID4106, Stairs wouldn't retract
SEA	8	12/30	119	119	Service, turn, or wye train 7, Late 8 arrival, wye, engine swap, late release by mechanical
SEA	11	12/30	5	5	Inability to contact dispatcher Radioed dispatch at around 9:16. Radioed periodically and didn't hear back until 9:35. Got a light to shove at 9:37, Other, seattle yard
SEA	507	12/30	1		
STL	300	12/30	1	1	Conductor working alone/crew shortage.
STL	302	12/30	1		
ARN	529	12/30	37	37	Air / Brake / Wheel C8301, Shelling issues and mechanical hold for authorization of movement

Amtrak Initial Terminal Details

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/30/2025

Terminal	Train	Date	Late	Delay	Cause
BFD	703	12/30	4	4	Air / Brake Engine 2010 goes into emergency after PTC logged in., C2010
BFD	717	12/30	49	49	Loading problem Locomotive drops the load at run 2 losing traction., C2124
OKJ	536	12/30	4	4	Loading problem Late release from maintenance yard, C2102
SAC	535	12/30	1		
SAC	539	12/30	2	2	Door C8310, Could not get a door light initially. Went to the cab car and was able to extinguish the door light for departure.
SAC	547	12/30	2	2	Mobility Impaired
SAC	702	12/30	1		
SJC	530	12/30	12	12	Dispatcher did not give us our lineup acct routing Caltrain 118 instead. Stop signal Alameda. Caltrain, 118, Control Point, Alameda
SJC	544	12/30	(Trn Cxld)		Third Party Engine Failure
SJC	550	12/30	2	2	Meet cal train, Control Point, alameda

Eastern Region

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	94.5	97.5	94.8	309	17
CDOT	95.0	90.0	92.0	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	86.5	92.5	93.8	364	49
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 449(31) - Boston, MA - Car Failure

31DEC25: Train 449(31) will operate BOS-ALB without a sleeper car due to 62507 being shopped at Boston. Nineteen (19) passengers were downgraded to coach.

West of Route 128 - Police Related Hold on All Tracks

30DEC25: Transit Police requested and received a hold on all tracks due to reports of a "pet" on the tracks at MP 212.95. The hold was released after approximately 30".

Train	Delay	Comment
184 (30)	31"	
2168 (30)	32"	

SEPTA 5227 - South of Wilmington, DE - Trespasser Incident

30DEC25: 7:57pm Septa Train 5227, with E/160, plus 3 cars was impacted by a motor vehicle on No. 1 track, at Churchman's Crossing Station/MP 34.3 on the Amtrak PW Line. There were no reports of injuries to crew or passengers. The status of the vehicle occupant(s) were unknown at the time of this reporting. This did not occur at a grade crossing. All traffic on the NEC at this location was temporarily halted. After an initial assessment by Amtrak Police, Track No. 2 and Track No. 3 were cleared for traffic at restricted speed between MP 34 and MP 35.

National Response Center Number: 1451679

Train	Delay	Comment
SEPTA 5227	Terminated	
192 (30)	15"	
138 (30)	35"	
137 (30)	09"	
2167 (30)	09"	
2169 (30)	10"	
90 (30)	10"	
55 (30)	08"	

Amtrak Cancellations - Due to Lack of Equipment / Engine Failure

30DEC25: Legacy trains 2151(31) 00000005569168 (UNCLASSIFIED) cancelled in their entirety due to the lack of equipment.

Train	Delay	Comment
2151(31)	cancelled	
2168(31)	cancelled	

Train 2169(30) Boston, MA - Servicing

30DEC25: Next Gen 2169(30) with set 21 and PC/2129, PC/2122 was delayed departing Boston due to turning off late 2152(30) and congestion in the station and servicing equipment.

Train	Delay	Comment
2169(30)	1'02"	

Train 64(30) Niagara Falls, NY - Customs and Immigration

30DEC25: Train 64(30) was delayed at Niagara Falls due to heavy travel and being held at customs.

Train	Delay	Comment
64(30)	47"	

Train 2167(30) Boston, MA - Servicing

30DEC25: Next Gen Train 2167(30) was delayed departing Boston due to Next Gen set 22 needing to be looped due to PC/2125 was a do not lead.

Train	Delay	Comment
2167(30)	1'08"	

Train 131(30) New York, NY - Servicing

30DEC25: Train 131(30) was delayed departing New York due to running E/613 around the consist due to train 112(30) operating with a single engine. Train 136(30) was also delayed departing Washington due to late turn off 131(30) and operating with one engine.

Train	Delay	Comment
131(30)	51"	
136(30)	40"	

Train 173(30) Boston, MA - Engine Failure

30DEC25: Train 173(30) with E/640 and 10 cars was delayed departing Boston yard due to having a hot journal alarm. Mechanical was working on making necessary repairs. Mechanical inspected the equipment and took no exceptions they operated the equipment to the station and the fault cleared.

Train	Delay	Comment
173(30)	1'10"	

Train 2153(30) Originate at New York, NY - Acela Cancellations

30DEC25: Due to equipment failure, Train 2153(30) was cancelled from Boston to New York. This train 2153(30) was originated out New York with Next Gen set 20.

Train	Delay	Comment
2153(30)	10"	Orig NYP

Train 2190(30) Boston, MA - Catenary or Wayside Failure

30DEC25: At 936A-ET, The Power Director reported that they can not hold between MP 224.30/Plains and MP 228.0/Cove on track 2 due to ice build up on the catenary. Train 2190(30) was terminated at Back Bay Boston and passengers were accommodated on MBTA 626 that was on track 3 at Back Bay. MBTA train 926(30) was also delayed behind 2190(30). Once the ET Bucket truck arrived and knocked off the ice build up train 2190(30) equipment was advanced into Boston and used for train 2163(30).

As of 1126A-ET, The power director reported the power was restored between Cove and Plains. Train 2190(30) was rebuilding air but was unable to get the MCB closed. High Speed mechanical was enroute to Back Bay station. Assistant Superintendent of Operations was on scene and trying to get a rescue worked up out of the yard to tow into south station. As of 1238p-ET, Rescue E/119 departed Boston to bring train 2190(30) equipment into Boston.

Train 2190(30) equipment did turn for 2163(30) extremely late due to multiple issues the set needed to be put on ground power, be cleaned and paperwork updated and problems releasing the brakes. The equipment finally left as deadhead equipment only to Washington.

Train	Delay	Comment
2190(30)	TERM BBY	
2163(30)	CANCELLED	DHE BOS-WAS

Train 2155(30) Boston, MA - Servicing

30DEC25: Next Gen 2155(30) set 12 PC/2133,PC/2124 was delayed departing Boston due to commissary loading and the last minute change from Legacy to Next Gen equipment. This also delayed train 2172(30) departing Washington due to the late arrival of equipment.

Train	Delay	Comment
2155(30)	1'29"	
2172(30)	2'42"	late turn off 2155(30)

Eastern Region

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 48/448(30) Chicago, IL - Car Failure

30DEC25: Train 48/448(30) shopped coach C/25103 which operates Chicago, IL to Boston, MA. Passengers between Chicago, IL and Albany, NY were re-accommodated to another section of the train. Train 448(300) was over capacity by 33 passengers between Albany, NY and Boston, MA. Alternate transportation was secured to accommodate passenger, one(1) 54-seater bus will protect the following stops: Pittsfield, MA, Springfield, MA, Worcester, MA and Boston, MA. Framingham, MA and Boston Back Bay, MA stops will not be protected.

WBS#: B.TR.100150.6359

Train	Delay	Comment
48/448(30)		B/O COACH ALB-BOS

Train 511(30) North of Tukwila, WA - Freight Train Interference

31DEC25: Train 511(30) operating with E/90252, 4 cars and 72 passengers onboard, stopped at MP 23.1 on BNSF Seattle Subdivision approximately 13 miles north of Tukwila, WA Station holding for freight train BNSF 8250 and BNSF 7424 to pass. They also held for Amtrak Train 506(30) before proceeding south.

Train	Delay	Comment
511(30)	29"	FTI BNSF 8250 and 7424
511(30)	06"	PTI 506(30)

Train 319(30) West of Sedalia, MO - Car Failure

31DEC25: Train 319(30) operating with E/IDTX 4622, 7 cars and 181 passengers onboard, stopped at MP 206.5 on UPRR Sedalia Subdivision with an air hose separation issue between C/IDTX 4016 and C/IDTX 4112. The Crew repaired/corrected the problem and were back on the move. Train 319(30) stopped again at MP 229.9 with main reservoir issues. The crew correct and continue west. When Train 319(30) arrived into Lee Summit, MO Station they had both air hose and a main reservoir issue between the same two (2) cars, C/IDTX 4016 and C/IDTX 4112. Once corrected they proceeded to Kansas City, MO without further issue.

Train	Delay	Comment
319(20)	24"	WAR - LEE
319(30)	13"	SED - WAR

Train 40(29) Pittsburgh, PA - Freight Train Interference

31DEC25: Train 40(29) operating with E/378, E/37, 10 cars and 172 passengers onboard, was delayed departing the Pittsburgh, PA Station on NS Pittsburgh Line Subdivision due freight stopped in the station. Freight C57 was stopped due to bad switch ahead, thus blocking the crossing that granted the fuel truck access to the station. With not estimate time of arrival of the maintainer, the truck was re-routed and was able to fuel the train.

Train	Delay	Comment
40(29)	46"	

Train 518(30) North of Tacoma WA - Commuter Train Trunc

30DEC25: Train 518(30) ~~26-FOI-00217~~ ~~la00000005559~~ ~~le~~ "UNCLASSIFIED" a sl 1/5/2026 operating Sounder train. The unidentified commuter train was tailed from Tacoma Dome station for 40 miles thru to Seattle station.

Train	Delay	Comment
518(30)	37"	

Train 8(30) Initial Terminal Delay at Seattle, WA - Servicing Equipment

30DEC25: Train 8(30) was delayed departing Seattle after turning and servicing equipment off inbound train 7(28) which arrived in Seattle at 2:06PM-PDT, 2 hours 37 minutes late. Train 8(30) departed Seattle at 6:54PM-PT.

Cause: Pending

Train	Delay	Comment
8(30)	1'59"	SEA- ITD - Servicing

Train 14(29) North of Vancouver, WA - Vehicle on Tracks

30DEC25: Train 14(29) experienced a delay after a vehicle became immobilized on the tracks approximately six miles north of Vancouver Station, near Felida (MP 130.7) on the BNSF Seattle Subdivision. Rail operations were temporarily suspended to facilitate the safe removal of the vehicle and to allow for a comprehensive track inspection. Following confirmation that the track was safe for continued operations, the train proceeded to Kelso. Amtrak Police were notified.

Train	Delay	Comment
14(29)	24"	

Train 1(29) West of El Paso, TX - Car Failure

30DEC25: Train 1(29) operating with E/176, E/77, 9 cars and 126 passengers onboard, departed El Paso, TX Station on time and stopped approximately 20 miles west of the station in the Santa Teresa Yard on UPRR Lordsburg Subdivision to fuel the train. While in the yard, C/32045 and C/39031 toilets were dumped. Once completed the train was on the move west.

Train	Delay	Comment
1(29)	39"	FUELING
1(29)	39"	TOILETS C/32045, C/39031

Train 713(30) Terminates Emeryville, CA - Non-Working Windshield Wipers

30DEC25: Train 713(30) departed Bakersfield with locomotive CDTX/2104 leading. Cab Car CDTX/8307(on the rear of the train) was reported non-compliant with no working windshield wipers. This required the train terminate in Emeryville to enter Oakland Maintenance Facility via Kirkham entrance to turn for 718(30). Thirty two (32) passengers travelling to Oakland transferred to train 543(30) after a 45 minute wait.

Cause: Pending

Train	Delay	Comment
713(30)	Terminates Emeryville	Passengers to 543(30)

Train 544(30) – San Jose, CA – Cancelled Due to Locomotive Failure

30DEC25: Train 544(30) dep. San Jose, CA 11:55 PM. Locomotive CDTX2009 failed to start. Contracted technicians assisted the crew and identified a likely starter abutment fault that could not be repaired onsite. As a result, the train was cancelled. Passengers scheduled to board between San Jose and Oakland Coliseum were directed to Train 550(30). Those boarding between Oakland Jack London Square and Davis were advised to use Train 548(30).

Inbound Train 543(30) was coupled to the 544(30) equipment in San Jose, and both trains operated as a combined consist to the Oakland Maintenance Facility. There, the Train 544(30) equipment was removed for repair, enabling Train 550(30) to continue to Emeryville.

UPDATE: Locomotive CDTX/2009 could not be repaired overnight, leading to the cancellation of train 525(31), affected passengers advised to board train 527(31).

Cause: Pending

Train	Delay	Comment
544(30)	Cancelled	Passengers to 548(30) or 550(30)
525(31)	Cancelled	Passengers to 527(31)
550(30)	29"	Oakland Maintenance Facility - Remove 544(30)

Train 717(30) – Bakersfield, CA – Initial Terminal Delay - Locomotive Brake Issue

30DEC25: During pre-departure inspection, a brake fault was identified on locomotive CDTX/2124. The train could not move forward without penalty brake applications. With assistance from local technicians and the Bakersfield Road Foreman, the crew discovered the train brake bypass switch engaged. Once this switch was correctly positioned the problem was resolved, allowing the train to resume service.

Cause: Pending

Train	Delay	Comment
717(30)	49	

Train 8/28(29) West of Browning, MT - Vehicle Strike

30DEC25: At approximately 1246PM-MT, Train 8/28(29), E/372-E/353-E373 & 10 cars, with 194 passengers, struck an occupied vehicle at a non gated crossing (DOT 088110F) at MP1132.0, 10 miles west of Browning, MT, Glacier County, on the BNSF Hi Line Subdivision. There were no reported injuries to passengers or crew. The two occupants of the vehicle were fatalities. There were no reported damages to equipment and Train 8/28(29) maintained HEP. The weather was reported as 35 degrees and clear. Local authorities responded to the scene. Train 8/28(29) was delayed holding for completion of investigation and release by local authorities. As service recovery, snack packs, water, tea and coffee were made available to all passengers.

National Response Center Number: 1451664

Work Element Number: B.TR,100150.6357

WBS#: B.TR.100150.6357

National Response Center Number: 1451664

Train	Delay	Comment
8/28(29)	52"	

Train 5(29) West of Granby, CO - Rocks on Track Ahead

30DEC25: Train 5(29) 26-FCI-00247la 00000005559 MP11 UNCLASSIFIED 1/5/2026 of Granby, CO, on the UPRR Moffat Tunnel Subdivision, due to multiple rocks reported on the main ahead at Yarmony/MP121.81. Train 5(29) held for MW to respond and clear rocks ahead.

Train	Delay	Comment
5(29)	1'28"	

Train 27(28) West of Pasco, WA - Trackside Detector Activation – Sleeper Car Removal - Wishram

30DEC25: Train 27(28) was stopped 111 miles West of Pasco when activating a trackside warning device. The device - measuring wheel temperature- is located at MP 120.2, Fallbridge Subdivision BNSF Railway. This required that the train be visually inspected for any unusually hot wheels or journal bearings. The crew -reported 'warm' journals on sleeper car C/32028 L3 wheel. After reporting this to BNSF Railway, the crew were instructed the temperature was out or working tolerance Car C/32028 was required to be removed from the train. The train advanced to Wishram station where the car was removed. All affected passengers were downgraded to coach class accommodation for the remainder of the trip. With no replacement available in Portland, passengers booked in car C/32028 on train 28(30) were also downgraded to Coach Class.

Train 28(30) service recovery was initiated for passengers that were downgraded from sleeper line 2830 to coach between Portland, OR and Chicago, IL. The diner staff will provide complimentary breakfast, lunch and dinner for all affected passengers.

Cause: Pending

Train	Delay	Comment
28(30)	22"	PDX - ITD - Servicing inbound 27
27(28)	1'00"	

Train 22(30)/422(28) South of Fort Worth, TX - Broken Rail

30DEC25: Train 22(30)/422(28) was delayed at Crowley/MP334.2, 12 miles south of Fort Worth, TX, on the BNSF Fort Worth Subdivision, due to an impassable broken rail ahead at MP341.1. Train 21(29) was also delayed at Fort Worth due to the broken rail ahead. Trains 22(30)/422(28) and 21(29) were delayed holding for BNSF MW to respond and complete repairs at MP341.1.

Train	Delay	Comment
21(29)	37"	FTW
21(29)	35"	S/FTW, meet BNSF 8112
22(30)/422(28)	2'07"	

Train 3(29) La Junta, CO - Crew Rest

30DEC25: Train 3(29) was delayed at La Junta, CO/MP554.9, on the BNSF Boise City Subdivision, due to crew rest. The crew signed up on rest at 818AM-MT off Train 4(28) which arrived in La Junta at 1158PM-MT, 5 hours and 05 minutes late.

Train	Delay	Comment
3(29)	36"	

Train 48/448(29) East of Sandusky, OH - Freight Train Interference

30DEC25: Train 48/448(29) was delayed at Tolono/MP137.5, 10 miles south of Champaign, IL, on the CN Champaign Subdivision, due to freight stopped ahead waiting on repairs to a broken rail on the NS side of the diamond. Train 58(29) held for the MW to complete repairs and the cross-traffic to clear the diamond ahead.

Train	Delay	Comment
48/448 (29)	36"	

Train 58(29) South of Champaign-Urbana, IL - M of W Work

30DEC25: Train 58(29) was delayed at Tolono/MP137.5, 10 miles south of Champaign, IL, on the CN Champaign Subdivision, due to freight stopped ahead waiting on repairs to a broken rail on the NS side of the diamond. Train 58(29) held for the MW to complete repairs and the cross-traffic to clear the diamond ahead.

Train	Delay	Comment
58 (29)	43"	

Train 300(30) South of Springfield, IL - Signal/Switch Issues

30DEC25: Train 300(30) was delayed at Girard/MP210, 25 miles south of Springfield, IL, on the UPRR Springfield Subdivision, due to signal and switch issues. UPRR maintainer responded and assisted crew in hand lining switches. Train 300(30) was delayed flagging through the affected area. Train 302(30) was also delayed due to the ongoing signal and switch issues at Girard.

Train	Delay	Comment
300 (30)	59"	
302 (30)	36"	

Train 529(30) Initial Terminal Auburn, CA - Third Party Contractor Cab Car Failure/Freight Interference

30DEC25: Train 529(30) was delayed departing Auburn, MP 124.3/UPRR Roseville Subdivision, as a result of wheel inspection on cab car C/8301 following reports of wheel shelling. Once inspections were completed and authorization for movement was granted, additional delay was incurred waiting on eastbound UPRR freight train AMICXX29 to pass on the mainline. Train 529(30) departed Auburn at 7:13AM-PT.

In order to facilitate movement of car C/8301 to the Oakland Maintenance Facility for repairs:

-Train 529(30) had a cross platform equipment swap at Sacramento. Equipment off inbound Train 522(30) was turned to represent Train 529(30) Sacramento to San Jose.

-The original 529(30) was used to represent Train 531(30) Sacramento to Oakland, then proceeded into the Oakland Maintenance Facility.

Train	Delay	Comment
529(30)	10"	SAC - equipment change
529(30)	37"	ARN - ITD

30DEC25: Train 365(30), E/IDTX4628 & 5 cars, was over capacity by 42 seats due to the fourth car, C/ID4305 frozen doors and the fifth car, C/ID4132 electrical issues, and both cars deadheading inline. One supplemental bus was secured and operated Lansing, MI to Chicago, IL, express.
Train 353(30), E/IDTX4628 & 5 cars, was over capacity by 44 seats due to the second car, C/ID4133 with electrical issues and car operating deadhead inline only. One supplemental bus was secured and operated Ann Arbor, MI to Chicago express.

WBS#: B.TR.100150.6356

Train 8/28(29) - Initial Terminal Delay

29DEC25: Train 8(29) operating with E/353, E373 was delayed depart Seattle, WA due to the late inbound Train 7(27). Train 7(27) arrived Seattle 508P-PT, 5'39" late. The equipment needed to be turned and cleaned, causing Train 8(29) to depart late. Train 7(29) departed Seattle, WAS 734P-PT.

Service recover for Late 8(29)

Passengers departing Seattle, WA were provided sandwiches at the station from Subway, and the OBS Staff continued service recovery for the train.

for 12/30/2025:

1. Sleeping car passengers will be feed breakfast, lunch and dinner in the dining car
2. Snack packs and water will be distributed
3. Lounge car is offering complimentary coffee, tea and juice. Discounted and complimentary meals as needed.

29DEC25: Train 28(29) operating with E/372 was delayed departing Portland, OR due to the late inbound Train 27(27). Train 27(27) arrived Portland 442P-PT, 5'25" late. The equipment needed to be turned and cleaned, causing Train 28(29) to depart late. Train 28(29) departed Portland, OR 734P-PT.

31DEC25: Due to the late operation of Train 8/28(30), on time busing was secure to protect passenger Minneapolis, MN to to Chicago, IL.

Bus A: Protecting travel from Minneapolis, MN to Chicago, IL express

Bus B: Protecting travel from Minneapolis, MN to Milwaukee, WI making all stops, passengers traveling beyond Milwaukee, WI will be protected on the next available train from Milwaukee to Chicago.

Bus C: Protecting travel at La Crosse, WI, Tomah, WI and Wisconsin Dells, WI to Chicago, IL

WBS#: B.TR.100150.6358

Train	Delay	Comment
8(29)	3'22"	SEA
28(29)	2'51"	PDX

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

-715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.

-718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

716(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
-716(22) Modified Equipment for 00000005559F from UNCLASSIFIED) after 1/5/2026 repairs completed.

23DEC25

-714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
-713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

-520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
-535(24) Cancelled. Turn of equipment from cancelled train 520(24).
-534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

-Train 736(25-28) Cancelled - No alternate transportation.
-Train 737(25-28) Cancelled - No alternate transportation.
-Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

-Train 520(29-30) Cancelled - No alternate transportation.
-Train 534(29-30) Cancelled - No alternate transportation.
-Train 535(29) Cancelled - No alternate transportation.
-Train 537(30) Cancelled - No alternate transportation.
-Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DEC25

-Train 520(31) Cancelled - No alternate transportation.
-Train 534(31) Cancelled - No alternate transportation.
-Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

-Train 736(01-04) Cancelled - No alternate transportation.
-Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-05MAR) Cancelled - No alternate transportation.
- TRAIN 713(05JAN-06MAR) Cancelled - No alternate transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
-------	-------	---------

718 (21)	Originate	Passengers to 744 (21) OKJ-EMY
	EMY	
718 (22)	Originate	Passengers to 744 (22) OKJ-EMY
	EMY	
714 (22)	1'07"	ITD - OKJ - Late change of equipment
718 (21)	37"	ITD - EMY
716 (22)	20"	
718 (22)	3'10"	ITD - EMY
714 (23)	.	CANCELLED
713 (24)	.	CANCELLED
535 (24)	Cancelled	
520 (24)	Cancelled	
534 (24)	Cancelled	
736 (25-28)	Cancelled	
737 (25-28)	Cancelled	
749 (28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751 (28)
551 (29-30)	Cancelled	Replacement Bus SAC-OKJ
520 (29-31)	Cancelled	No alternate transportation.
534 (29-31)	Cancelled	No alternate transportation.
736 (01JAN-04JAN))	Cancelled	No alternate transportation
737 (01JAN-04JAN)	Cancelled	No alternate transportation
535 (29)	Cancelled	No alternate transportation.
537 (30-31)	Cancelled	No Alternate Transportation
713 (05JAN-06MAR)	CANCELLED	No Alternate Transport Offered
714 (05JAN-05MAR)	CANCELLED	No Alternate Transport Offered

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
6 (27)	DEN		33040	Wheel defects

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 580(28) Passenger Removal at San Diego, California – Improper Conduct***

30DEC25, Passengers on PNR 3AA573, traveling from Los Angeles, CA to San Diego, CA were told to not consume their personal 6-pack of alcohol and they agreed, but still consumed the alcohol. When the Conductor tried to wake them, they didn't respond and EMS had to be called to help get them up. They left on their own accord intoxicated at San Diego, CA. Amtrak Police notified.

Delay: 580 (28) None

Train 6(28) Passenger Removal at Elko, Nevada – Medical

30DEC25, Passenger on PNR 33C171, traveling from Reno, NV to Elko, NV was removed by EMS due to being intoxicated and unresponsive when the train arrived at Elko, NV. He was taken to the hospital. Amtrak Police notified.

Delay: 6 (28) 29"

Consist Deviations

26-FOI-00217

00000005559

"UNCLASSIFIED"

1/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2151 (30)	BOS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
2155 (30)	BOS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
2167 (30)	BOS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
2193 (30)	BOS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
95 (30)	BOS	Business Class on headend. Car is facing the correct direction, no schedule change is needed.	none	0	81527
390 (30)	CDL	bad order toilets	none	0	34028
390 (30)	CDL	bad order toilets	none	0	
390 (31)	CDL	bad order toilets	c/34028 - bad order toilets	74	34028
364 (29)	CHI	bad order electrical	none	0	ID4132
354 (29)	CHI	bad order electrical	none	0	ID4133
393 (29)	CHI	bad order toilets	none	0	34028
393 (30)	CHI	bad order toilets	none	0	34028
41 (30)	CHI	AMI coach in lieu of AMII coach	none	0	82756
40 (28)	MIA	AMI coach in lieu of AMII coach	none	0	82756
84 (31)	NFK	Business Class on headend. Car is facing the correct direction, no schedule change is needed.	N/A	0	81527
84 (30)	NFK	A-end of cafe car 43390 not against adjacent A-end.	N/A	0	43390
111 (29)	NYP	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81529
133 (29)	NYP	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81503

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00217 00000005559	"UNCLASSIFIED" 1/5/2026		
181 (30)	NYP	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81503
129 (30)	NYP	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81503
49 (30)	NYP	Viewliner II in lieu of viewliner I	none	0	62523
48 (31)	NYP	viewliner II in lieu of viewliner I	one passenger reaccommodated	0	62523
19 (28)	NYP	sleeper in lieu of bag dorm	N/A	0	62010
19 (28)	NYP	baggage car in lieu of bag dorm	N/A	0	61068
193 (31)	NYP	Business Class on headend. Car is facing the correct direction, no schedule change is needed.	N/A	0	81527
183 (30)	NYP	Business Class car on rear of train, with B-end against consist. Business class seating will not be facing the correct direction.	Business Class car on rear of train, with B-end against consist. Business class seating will not be facing the correct direction.	30	81535
28 (30)	PDX	No sleeper account set out for warm bearing from 27(28). Please check war reports and re-accommodate/downgrade all affected passengers.			
353 (30)	PNT	bad order electrical	yes passengers expressed bussed from ARB-CHI	49	ID4133
365 (30)	PTH	bad order frozn doors	passengers express bussed from LNS-CHI	42	ID4305
365 (30)	PTH	bad order electrical	passenger express bus from LNS-CHI	42	ID4132
182 (30)	WAS	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81503
192 (29)	WAS	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81503
114 (30)	WAS	Business Class used in lieu of Amfleet 1 coach - 10 less seats vs plan	none	0	81503

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00217 00000005559 "UNCLASSIFIED" 1/5/2026			
2150 (30)	WAS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
2168 (30)	WAS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
2162 (30)	WAS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
2172 (30)	WAS	Operate with NextGen Acela in lieu of Legacy Acela due to high shop count of Legacy equipment	none	0	
184 (30)	WAS	Business Class car on rear of train, with B-end against consist. Business class seating will not be facing the correct direction.	Business Class car on rear of train, with B-end against consist. Business class seating will not be facing the correct direction.	31	81535
27 (28)	WIH	32028 reported warm bearing and per safety rule can not run on the train. Car being set out at WIH.	32028 reported warm bearing and per safety rule can not run on the train. Car being set out at WIH.	17	32028

Reverse Consists

Train Number	Station	Reason
95 (30)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (30)	BOS	Consist reversed Business class seat orientation may have changed At Front
94 (30)	NFK	Consist reversed Business class seat orientation may have changed At Front
85 (30)	BOS	Consist reversed Business class seat orientation may have changed At Front
2167 (30)	BOS	Acela consist reversed First class at Rear
2166 (30)	WAS	Acela consist reversed First class at Front
2166 (30)	WAS	Acela consist reversed First class at Rear
134 (31)	RNK	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00217	00000005559 "UNCLASSIFIED" 1/5/2026
85 (31)	BOS	Consist reversed Business class seat orientation may have changed At Front	
197 (31)	NYP	Consist reversed Business class seat orientation may have changed At Rear	