

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, January 31, 2026

Rules: 3-13



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/30/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	266	70	73.7%	8,513	1,352	84.1%	35,822	5,025	86.0%
Central Division	85.5%	55	5	90.9%	1,927	258	86.6%	8,011	925	88.5%
Northeast Division	80.0%	84	47	44.0%	2,717	526	80.6%	11,334	1,808	84.0%
Southeast Division	72.5%	58	11	81.0%	1,884	312	83.4%	8,231	1,189	85.6%
Southwest Division	77.0%	69	7	89.9%	1,985	256	87.1%	8,246	1,103	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00297 00000005673 "UNCLASSIFIED" 2/9/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	82,305	39,031	53%	2,420,767	582,679	76%	11,716,143	2,619,244	78%
Northeast Corridor	81%	33,498	18,787	44%	1,066,606	288,281	73%	5,223,447	1,169,245	78%
Acela	83%	4,235	3,194	25%	200,974	78,266	61%	1,084,394	289,294	73%
Northeast Regional	79%	29,263	15,593	47%	865,632	210,015	76%	4,139,053	879,951	79%
Richmond / Newport News / Norfolk	77%	10,942	5,682	48%	273,813	77,474	72%	1,275,114	310,515	76%
Springfield Shuttles	89%	805	225	72%	19,710	2,859	85%	71,383	8,783	88%
Roanoke	79%	2,548	1,224	52%	67,485	12,822	81%	320,355	56,444	82%
On Spine Northeast Regional	80%	14,968	8,462	43%	504,624	116,860	77%	2,472,201	504,209	80%
State Supported	80%	38,937	15,961	59%	1,059,722	204,632	81%	5,028,465	966,873	81%
Borealis	60%	552	208	62%	11,725	2,973	75%	65,633	16,851	74%
Capitol Corridor	90%	3,905	304	92%	101,235	10,013	90%	420,852	43,773	90%
Carolinian	60%	1,333	610	54%	26,642	6,535	75%	133,872	36,866	72%
Cascades	63%	2,644	830	69%	65,950	12,330	81%	286,469	64,766	77%
Downeaster	82%	1,549	1,115	28%	36,541	4,550	88%	171,612	22,255	87%
Empire	78%	3,805	2,271	40%	136,747	33,487	76%	626,421	133,919	79%
Adirondack	72%	158	158	0%	7,691	2,885	62%	38,777	14,421	63%
Ethan Allen Express	70%	548	12	98%	13,693	3,562	74%	68,221	19,760	71%
Maple Leaf	70%	468	460	2%	17,499	9,327	47%	70,395	30,996	56%
New York - Albany	85%	1,184	430	64%	61,576	8,672	86%	286,513	38,855	86%
New York - Niagara Falls	75%	1,447	1,211	16%	36,288	9,041	75%	162,515	29,887	82%
Gold Runner	73%	2,292	994	57%	61,748	19,784	68%	294,587	104,741	64%
Heartland Flyer	65%	144	137	5%	3,815	1,033	73%	23,454	9,382	60%
Hiawatha	90%	1,325	626	53%	37,291	4,464	88%	196,722	24,033	88%
Illinois	78%	1,614	691	57%	54,500	12,092	78%	278,808	77,259	72%
Carl Sandburg / Illinois Zephyr	85%	187	129	31%	8,894	1,997	78%	48,021	12,300	74%
Illini / Saluki	85%	958	358	63%	20,153	4,709	77%	98,164	25,927	74%
Lincoln Service	70%	469	204	57%	25,453	5,386	79%	132,623	39,032	71%
Keystone	92%	7,691	5,223	32%	199,681	27,719	86%	944,401	102,133	89%
Lincoln / Missouri	60%	766	626	18%	17,616	5,863	67%	90,092	41,081	54%
Mardi Gras Service	80%	293	11	96%	10,191	1,086	89%	50,313	5,812	88%
Michigan	69%	511	204	60%	41,804	16,039	62%	223,246	71,624	68%
Blue Water	70%	0	0	-	9,313	4,364	53%	53,910	18,233	66%
Pere Marquette	85%	0	0	-	4,807	1,726	64%	29,263	6,034	79%
Wolverine	65%	511	204	60%	27,684	9,949	64%	140,073	47,357	66%
Missouri	80%	174	0	100%	4,290	436	90%	26,655	5,534	79%
Pacific Surfliner	85%	7,405	938	87%	170,722	32,732	81%	788,690	121,595	85%
Pennsylvanian	72%	972	472	51%	22,895	2,676	88%	108,551	12,419	89%
Piedmont	73%	1,203	30	98%	26,584	3,890	85%	144,450	31,583	78%
Vermont	75%	759	671	12%	29,745	6,930	77%	153,637	41,247	73%
Long Distance	56%	9,339	4,283	54%	283,461	89,766	68%	1,450,185	482,859	67%
Auto Train	57%	800	0	100%	21,821	4,467	80%	85,616	15,227	82%
California Zephyr	50%	792	249	69%	27,839	7,727	72%	114,494	32,567	72%
Cardinal	55%	181	50	72%	4,938	1,777	64%	30,443	13,065	57%
City Of New Orleans	75%	0	0	-	12,778	1,730	86%	78,512	16,161	79%
Coast Starlight	60%	830	121	85%	23,094	7,208	69%	132,695	41,936	68%
Crescent	70%	854	227	73%	18,206	2,611	86%	108,368	23,590	78%
Empire Builder	55%	707	671	5%	20,753	10,134	51%	114,629	45,988	60%
Floridian	40%	1,974	1,462	26%	38,757	20,927	46%	198,105	108,310	45%
Lake Shore Ltd	73%	844	724	14%	23,461	8,983	62%	112,982	27,975	75%
Palmetto	65%	0	0	-	21,044	2,000	90%	110,721	17,239	84%
Silver Meteor	45%	847	276	67%	24,202	5,342	78%	120,783	36,313	70%
Southwest Chief	40%	546	338	38%	18,592	8,819	53%	95,267	55,001	42%
Sunset Ltd	70%	539	105	81%	7,407	2,240	70%	34,114	8,407	75%
Texas Eagle	50%	425	60	86%	20,569	5,801	72%	113,456	41,080	64%
Seasonal Trains	%	531	0	100%	10,978	0	100%	14,046	267	98%
Winter Park Express	75%	531	0	100%	10,978	0	100%	14,046	267	98%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00207 00000005070 "UNCLASSIFIED" 2/0/2020

Train Index Dates Through January 30, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	163,885	2,932,775	559	692,161	12,793,313	541

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,390	839,064	88	28,129	3,721,189	76
INFRASTRUCTURE PLANNED	135	4,616	839,064	55	19,991	3,721,189	54
FLEET RELIABILITY	90	35,909	2,932,775	122	119,189	12,793,313	93
TRAIN OPERATIONS	424	115,970	2,932,775	395	524,852	12,793,313	410

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/30/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	266	70	73.7%	8,513	1,352	84.1%	35,822	5,025	86.0%
Central Division	85.5%	55	5	90.9%	1,927	258	86.6%	8,011	925	88.5%
Northeast Division	80.0%	84	47	44.0%	2,717	526	80.6%	11,334	1,808	84.0%
Southeast Division	72.5%	58	11	81.0%	1,884	312	83.4%	8,231	1,189	85.6%
Southwest Division	77.0%	69	7	89.9%	1,985	256	87.1%	8,246	1,103	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/30/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	266	70	73.7%	8,513	1,352	84.1%	35,822	5,025	86.0%
Central Division	85.5%	55	5	90.9%	1,927	258	86.6%	8,011	925	88.5%
CDL	90.0%	2	0	100.0%	59	1	98.3%	214	9	95.8%
CHI	85.0%	20	3	85.0%	757	149	80.3%	3,224	428	86.7%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	17	0	100.0%	23	2	91.3%
EUG	86.5%	2	0	100.0%	59	7	88.1%	237	33	86.1%
GRR	98.0%	-	-	-	25	2	92.0%	116	5	95.7%
KCY	84.5%	2	0	100.0%	58	2	96.6%	239	17	92.9%
MKE	86.5%	6	0	100.0%	176	10	94.3%	713	56	92.1%
MSP	94.0%	1	0	100.0%	24	0	100.0%	116	3	97.4%
PDX	78.0%	5	0	100.0%	143	18	87.4%	604	79	86.9%
PNT	91.5%	1	1	0.0%	78	17	78.2%	297	39	86.9%
PTH	93.0%	-	-	-	27	2	92.6%	118	9	92.4%
QCY	87.5%	1	0	100.0%	57	3	94.7%	241	20	91.7%
SEA	80.0%	8	1	87.5%	232	24	89.7%	963	143	85.2%
SPK	92.0%	1	-	100.0%	27	8	70.4%	122	13	89.3%
STL	88.0%	2	0	100.0%	111	13	88.3%	474	51	89.2%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	60	1	98.3%	239	7	97.1%
WIP	-	1	0	100.0%	17	1	94.1%	23	1	95.7%
Northeast Division	80.0%	84	47	44.0%	2,717	526	80.6%	11,334	1,808	84.0%
ALB	91.5%	6	1	83.3%	231	41	82.3%	846	87	89.7%
BON	43.5%	5	4	20.0%	143	16	88.8%	584	60	89.7%
BOS	86.5%	14	3	78.6%	490	85	82.7%	2,170	294	86.5%
BRK	88.0%	5	2	60.0%	142	13	90.8%	563	33	94.1%
BTN	48.0%	-	-	-	25	4	84.0%	116	22	81.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	57	7	87.7%	233	22	90.6%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	1	0.0%	25	6	76.0%	117	23	80.3%
NFL	96.5%	2	0	100.0%	60	4	93.3%	245	12	95.1%
NHV	75.5%	6	2	66.7%	158	31	80.4%	636	112	82.4%
NYP	77.5%	34	29	14.7%	1,137	291	74.4%	4,766	1,054	77.9%
SAB	98.0%	-	-	-	25	1	96.0%	115	1	99.1%
SAO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	8	3	62.5%	194	15	92.3%	755	39	94.8%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	84.0%	1	1	0.0%	29	11	62.1%	119	30	74.8%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	58	11	81.0%	1,884	312	83.4%	8,231	1,189	85.6%
ATL	-	-	-	-	14	0	100.0%	15	0	100.0%
CLT	92.0%	5	0	100.0%	141	10	92.9%	601	47	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%

Information Management

26-FOI-00113 Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/30/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	266	70	73.7%	8,513	1,352	84.1%	35,822	5,025	86.0%
Southeast Division	72.5%	58	11	81.0%	1,884	312	83.4%	8,231	1,189	85.6%
HAR	62.0%	11	2	81.8%	302	62	79.5%	1,331	252	81.1%
JAX	-	-	-	-	3	1	66.7%	3	1	66.7%
LOR	69.5%	1	1	0.0%	28	5	82.1%	120	14	88.3%
MIA	87.5%	1	1	0.0%	55	6	89.1%	239	25	89.5%
MOE	94.0%	2	0	100.0%	60	0	100.0%	244	3	98.8%
NFK	86.0%	2	0	100.0%	62	8	87.1%	320	36	88.8%
NOL	92.0%	4	0	100.0%	106	1	99.1%	513	21	95.9%
NPN	96.0%	2	0	100.0%	55	4	92.7%	214	14	93.5%
PGH	92.0%	1	0	100.0%	29	2	93.1%	121	5	95.9%
PHL	45.0%	5	3	40.0%	136	70	48.5%	560	284	49.3%
RGH	97.0%	4	0	100.0%	115	6	94.8%	479	15	96.9%
RNK	85.5%	2	1	50.0%	55	10	81.8%	238	31	87.0%
RVM	86.0%	-	-	-	11	0	100.0%	113	13	88.5%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	28	0	100.0%	120	2	98.3%
SFA	70.5%	1	0	100.0%	28	5	82.1%	120	8	93.3%
WAS	70.0%	16	3	81.3%	656	122	81.4%	2,873	413	85.6%
Southwest Division	77.0%	69	7	89.9%	1,985	256	87.1%	8,246	1,103	86.6%
ARN	60.5%	1	1	0.0%	29	3	89.7%	121	10	91.7%
BFD	75.5%	6	1	83.3%	182	31	83.0%	734	166	77.4%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	36	6	83.3%	135	42	68.9%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	1	0.0%	27	1	96.3%	118	4	96.6%
GTA	72.5%	3	0	100.0%	102	8	92.2%	371	33	91.1%
IRV	-	-	-	-	2	2	0.0%	2	2	0.0%
LAX	77.5%	11	0	100.0%	276	29	89.5%	1,128	121	89.3%
OKC	96.0%	1	0	100.0%	26	0	100.0%	118	3	97.5%
OKJ	79.0%	9	4	55.6%	285	68	76.1%	1,284	310	75.9%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	14	0	100.0%	412	38	90.8%	1,629	167	89.7%
SAN	77.0%	12	0	100.0%	310	35	88.7%	1,367	126	90.8%
SAS	85.0%	1	0	100.0%	25	3	88.0%	117	7	94.0%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	210	22	89.5%	852	81	90.5%
SLO	62.0%	2	0	100.0%	48	5	89.6%	226	20	91.2%
SNC	-	-	-	-	15	5	66.7%	17	5	70.6%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		12	1	91.7%	52	2	96.2%	13	2	84.6%	53	3	94.3%
2		13	2	84.6%	53	10	81.1%	12	2	83.3%	51	8	84.3%
3		30	8	73.3%	122	20	83.6%	30	9	70.0%	121	45	62.8%
4	46	30	3	90.0%	121	17	86.0%	30	15	50.0%	121	74	38.8%
5		30	8	73.3%	121	23	81.0%	29	8	72.4%	118	21	82.2%
6		30	5	83.3%	120	34	71.7%	30	10	66.7%	120	37	69.2%
7	65	25	7	72.0%	117	17	85.5%	23	7	69.6%	111	22	80.2%
8	34	25	11	56.0%	117	50	57.3%	24	14	41.7%	116	59	49.1%
11		30	4	86.7%	121	22	81.8%	27	3	88.9%	116	18	84.5%
14		30	6	80.0%	122	16	86.9%	30	10	66.7%	121	31	74.4%
19	40	27	8	70.4%	119	26	78.2%	27	1	96.3%	119	14	88.2%
20		27	0	100.0%	119	6	95.0%	27	3	88.9%	119	11	90.8%
21		25	1	96.0%	116	14	87.9%	24	4	83.3%	115	22	80.9%
22		25	2	92.0%	117	6	94.9%	25	7	72.0%	116	26	77.6%
23		30	0	100.0%	122	3	97.5%	30	6	80.0%	122	19	84.4%
24		30	1	96.7%	122	8	93.4%	30	1	96.7%	122	10	91.8%
25		30	0	100.0%	122	0	100.0%	30	5	83.3%	122	15	87.7%
26		30	0	100.0%	122	2	98.4%	30	2	93.3%	122	16	86.9%
27	39	24	7	70.8%	116	9	92.2%	22	8	63.6%	113	28	75.2%
28	79	22	6	72.7%	113	26	77.0%	22	7	68.2%	113	19	83.2%
40		27	4	85.2%	119	18	84.9%	28	10	64.3%	120	44	63.3%
41	160	27	12	55.6%	119	45	62.2%	28	21	25.0%	120	79	34.2%
42		29	2	93.1%	121	5	95.9%	28	3	89.3%	120	15	87.5%
43	40	29	9	69.0%	121	17	86.0%	29	4	86.2%	121	8	93.4%
48	51	28	12	57.1%	120	25	79.2%	28	8	71.4%	120	18	85.0%
49	300	28	10	64.3%	120	24	80.0%	28	8	71.4%	120	21	82.5%
50	87	11	3	72.7%	50	10	80.0%	11	5	54.5%	51	24	52.9%
52		28	5	82.1%	120	8	93.3%	28	3	89.3%	120	17	85.8%
53		28	5	82.1%	120	14	88.3%	28	5	82.1%	120	18	85.0%
55	Cncld	19	3	84.2%	83	3	96.4%	18	3	83.3%	82	16	80.5%
56		19	2	89.5%	83	15	81.9%	18	2	88.9%	82	13	84.1%
63	131	30	21	30.0%	122	60	50.8%	30	16	46.7%	121	64	47.1%
64	23	29	11	62.1%	120	31	74.2%	29	8	72.4%	120	29	75.8%
66		28	6	78.6%	120	19	84.2%	28	4	85.7%	120	23	80.8%
67		19	0	100.0%	82	4	95.1%	19	2	89.5%	83	13	84.3%
68	95	30	10	66.7%	122	27	77.9%	30	15	50.0%	122	61	50.0%
69	Cncld	26	6	76.9%	118	17	85.6%	24	3	87.5%	116	16	86.2%
71		28	0	100.0%	120	1	99.2%	28	3	89.3%	120	27	77.5%
72		28	1	96.4%	120	11	90.8%	28	2	92.9%	120	25	79.2%
73		29	2	93.1%	121	5	95.9%	29	11	62.1%	120	55	54.2%
74		29	3	89.7%	121	10	91.7%	29	9	69.0%	121	34	71.9%
75	15	29	2	93.1%	121	5	95.9%	27	10	63.0%	119	49	58.8%

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		29	4	86.2%	121	8	93.4%	26	7	73.1%	118	42	64.4%
77		28	2	92.9%	120	6	95.0%	27	4	85.2%	119	35	70.6%
78		27	1	96.3%	119	6	95.0%	27	2	92.6%	119	14	88.2%
79		28	2	92.9%	120	23	80.8%	28	3	89.3%	119	18	84.9%
80		28	1	96.4%	120	12	90.0%	28	2	92.9%	119	12	89.9%
85		20	4	80.0%	84	7	91.7%	20	7	65.0%	84	31	63.1%
86	65	20	2	90.0%	84	7	91.7%	20	12	40.0%	83	45	45.8%
89	51	28	6	78.6%	120	24	80.0%	28	6	78.6%	120	21	82.5%
90	39	28	0	100.0%	120	2	98.3%	28	1	96.4%	120	10	91.7%
93		19	2	89.5%	83	12	85.5%	19	3	84.2%	82	16	80.5%
94		20	6	70.0%	84	22	73.8%	20	9	55.0%	83	27	67.5%
95	101	19	0	100.0%	83	2	97.6%	19	6	68.4%	83	25	69.9%
97		28	16	42.9%	120	57	52.5%	28	2	92.9%	120	21	82.5%
98		27	2	92.6%	119	7	94.1%	27	6	77.8%	119	30	74.8%
110	80	18	10	44.4%	82	41	50.0%	18	2	88.9%	82	9	89.0%
125	25	20	2	90.0%	84	4	95.2%	20	8	60.0%	84	23	72.6%
129		19	4	78.9%	83	28	66.3%	19	2	89.5%	83	11	86.7%
134		20	6	70.0%	84	12	85.7%	20	3	85.0%	84	15	82.1%
136	19	20	2	90.0%	84	9	89.3%	19	3	84.2%	83	8	90.4%
137	48	19	4	78.9%	81	18	77.8%	19	7	63.2%	81	25	69.1%
138		20	1	95.0%	84	10	88.1%	20	2	90.0%	84	7	91.7%
141	29	19	0	100.0%	83	3	96.4%	19	4	78.9%	83	19	77.1%
148	160	19	3	84.2%	83	9	89.2%	19	7	63.2%	82	17	79.3%
151		27	7	74.1%	119	34	71.4%	27	5	81.5%	118	30	74.6%
170	34	18	3	83.3%	79	9	88.6%	18	4	77.8%	79	25	68.4%
171	25	20	2	90.0%	84	7	91.7%	20	7	65.0%	84	19	77.4%
172	59	19	2	89.5%	83	11	86.7%	19	7	63.2%	81	31	61.7%
173	25	19	3	84.2%	83	11	86.7%	19	6	68.4%	83	33	60.2%
174		20	8	60.0%	84	11	86.9%	20	4	80.0%	84	17	79.8%
175	46	20	4	80.0%	84	14	83.3%	20	9	55.0%	84	28	66.7%
176		19	3	84.2%	83	8	90.4%	19	2	89.5%	83	6	92.8%
177		20	2	90.0%	84	16	81.0%	20	4	80.0%	84	31	63.1%
178		20	5	75.0%	84	15	82.1%	20	3	85.0%	84	12	85.7%
179	33	20	3	85.0%	84	9	89.3%	20	4	80.0%	84	18	78.6%
181		16	4	75.0%	80	19	76.3%	16	2	87.5%	79	5	93.7%
183	41	19	4	78.9%	83	23	72.3%	19	3	84.2%	83	13	84.3%
184		20	5	75.0%	84	17	79.8%	20	4	80.0%	84	15	82.1%
185	48	20	6	70.0%	84	19	77.4%	20	4	80.0%	84	8	90.5%
186		19	1	94.7%	83	10	88.0%	19	1	94.7%	83	16	80.7%
190	33	19	10	47.4%	83	37	55.4%	19	7	63.2%	83	22	73.5%
192	30	19	5	73.7%	81	13	84.0%	19	4	78.9%	81	6	92.6%
193	40	20	12	40.0%	84	33	60.7%	20	8	60.0%	84	31	63.1%

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
196	23	19	3	84.2%	83	4	95.2%	19	7	63.2%	83	10	88.0%
197		20	10	50.0%	84	34	59.5%	20	5	75.0%	84	19	77.4%
198		14	2	85.7%	16	4	75.0%	13	0	100.0%	15	0	100.0%
232		30	3	90.0%	122	5	95.9%	30	2	93.3%	122	8	93.4%
234	22	30	5	83.3%	122	9	92.6%	30	6	80.0%	122	9	92.6%
237	45	30	7	76.7%	121	22	81.8%	30	9	70.0%	120	16	86.7%
239		30	11	63.3%	121	35	71.1%	29	6	79.3%	120	10	91.7%
240		30	3	90.0%	122	12	90.2%	29	3	89.7%	121	15	87.6%
241	374	30	7	76.7%	122	31	74.6%	30	6	80.0%	122	20	83.6%
280	24	30	2	93.3%	122	6	95.1%	30	8	73.3%	122	25	79.5%
281	127	30	5	83.3%	122	14	88.5%	30	8	73.3%	122	18	85.2%
283	70	30	8	73.3%	122	28	77.0%	30	9	70.0%	122	24	80.3%
284	46	30	2	93.3%	122	5	95.9%	30	8	73.3%	121	15	87.6%
290		30	7	76.7%	122	26	78.7%	29	9	69.0%	120	40	66.7%
291		29	7	75.9%	121	25	79.3%	29	5	82.8%	121	20	83.5%
301	36	30	2	93.3%	120	4	96.7%	29	4	86.2%	118	20	83.1%
306		29	2	93.1%	119	8	93.3%	29	4	86.2%	118	24	79.7%
311		30	4	86.7%	121	14	88.4%	29	3	89.7%	119	23	80.7%
316		29	2	93.1%	119	7	94.1%	29	3	89.7%	119	21	82.4%
318	28	29	0	100.0%	121	11	90.9%	29	11	62.1%	120	48	60.0%
319	42	30	1	96.7%	122	5	95.9%	29	10	65.5%	121	58	52.1%
329	92	21	3	85.7%	85	6	92.9%	21	5	76.2%	85	10	88.2%
330		25	0	100.0%	102	2	98.0%	25	3	88.0%	102	8	92.2%
331		30	5	83.3%	122	16	86.9%	30	6	80.0%	122	20	83.6%
332	15	30	1	96.7%	122	10	91.8%	30	6	80.0%	122	22	82.0%
334		30	2	93.3%	122	4	96.7%	30	4	86.7%	121	16	86.8%
335		30	2	93.3%	122	16	86.9%	30	6	80.0%	120	23	80.8%
336		30	2	93.3%	122	6	95.1%	30	1	96.7%	122	6	95.1%
337	76	30	1	96.7%	122	6	95.1%	30	3	90.0%	122	15	87.7%
338	27	30	5	83.3%	122	26	78.7%	30	9	70.0%	120	31	74.2%
339	32	30	5	83.3%	122	25	79.5%	30	7	76.7%	122	26	78.7%
341		27	5	81.5%	116	21	81.9%	25	4	84.0%	113	18	84.1%
342	16	30	0	100.0%	122	8	93.4%	29	4	86.2%	120	20	83.3%
350	48	29	6	79.3%	103	9	91.3%	27	20	25.9%	101	61	39.6%
355		27	9	66.7%	118	19	83.9%	23	10	56.5%	113	35	69.0%
381	17	30	3	90.0%	122	5	95.9%	30	5	83.3%	122	16	86.9%
382	24	30	1	96.7%	122	3	97.5%	30	5	83.3%	122	28	77.0%
390	75	30	1	96.7%	106	10	90.6%	30	11	63.3%	105	36	65.7%
391	31	30	1	96.7%	107	3	97.2%	29	7	75.9%	104	22	78.8%
392		29	0	100.0%	121	4	96.7%	28	5	82.1%	119	33	72.3%
393	118	30	3	90.0%	122	10	91.8%	30	8	73.3%	121	33	72.7%
417	Cncld	20	6	70.0%	81	16	80.2%	17	2	88.2%	75	4	94.7%

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
425	29	18	1	94.4%	79	3	96.2%	18	1	94.4%	79	3	96.2%
448	282	25	9	64.0%	58	22	62.1%	26	9	65.4%	57	21	63.2%
449	58	27	3	88.9%	57	4	93.0%	27	3	88.9%	57	8	86.0%
470		20	4	80.0%	86	18	79.1%	19	2	89.5%	83	14	83.1%
471		18	0	100.0%	79	1	98.7%	18	0	100.0%	79	0	100.0%
473		20	2	90.0%	84	5	94.0%	20	3	85.0%	84	4	95.2%
474	Cncld	20	7	65.0%	82	25	69.5%	18	6	66.7%	76	24	68.4%
475		20	2	90.0%	84	2	97.6%	20	1	95.0%	84	2	97.6%
478		17	3	82.4%	79	16	79.7%	17	2	88.2%	79	9	88.6%
479		20	3	85.0%	84	11	86.9%	18	0	100.0%	82	3	96.3%
486	30	20	4	80.0%	85	12	85.9%	18	5	72.2%	82	16	80.5%
490	21	19	5	73.7%	60	13	78.3%	19	5	73.7%	60	7	88.3%
494		20	2	90.0%	86	11	87.2%	20	9	55.0%	83	20	75.9%
495		16	1	93.8%	80	3	96.3%	16	1	93.8%	80	2	97.5%
500	39	30	3	90.0%	122	9	92.6%	30	3	90.0%	121	13	89.3%
502		30	2	93.3%	122	9	92.6%	29	6	79.3%	120	27	77.5%
503	38	30	2	93.3%	119	13	89.1%	29	11	62.1%	117	33	71.8%
504	21	30	3	90.0%	122	11	91.0%	30	7	76.7%	121	32	73.6%
505	55	30	5	83.3%	122	21	82.8%	30	9	70.0%	120	26	78.3%
506		30	3	90.0%	121	17	86.0%	30	2	93.3%	120	15	87.5%
507		30	1	96.7%	122	12	90.2%	30	8	73.3%	122	40	67.2%
508		30	5	83.3%	120	26	78.3%	30	3	90.0%	120	25	79.2%
509		30	1	96.7%	122	8	93.4%	30	3	90.0%	122	28	77.0%
511		30	3	90.0%	122	13	89.3%	30	3	90.0%	122	20	83.6%
516		30	0	100.0%	120	9	92.5%	30	9	70.0%	120	47	60.8%
517	53	30	0	100.0%	122	2	98.4%	30	7	76.7%	121	38	68.6%
518		30	3	90.0%	122	16	86.9%	30	21	30.0%	122	75	38.5%
519		30	1	96.7%	120	5	95.8%	30	4	86.7%	120	18	85.0%
521		20	2	90.0%	82	2	97.6%	20	3	85.0%	82	7	91.5%
522		20	4	80.0%	82	13	84.1%	20	0	100.0%	81	6	92.6%
523		20	0	100.0%	82	0	100.0%	20	1	95.0%	82	9	89.0%
524		20	1	95.0%	82	3	96.3%	19	1	94.7%	81	5	93.8%
525		20	1	95.0%	81	4	95.1%	19	0	100.0%	79	6	92.4%
527		20	1	95.0%	82	2	97.6%	20	1	95.0%	82	4	95.1%
528		20	2	90.0%	82	8	90.2%	20	2	90.0%	82	15	81.7%
529	25	20	3	85.0%	82	7	91.5%	20	4	80.0%	82	17	79.3%
530		20	0	100.0%	36	2	94.4%	20	4	80.0%	36	5	86.1%
532		20	5	75.0%	82	10	87.8%	20	2	90.0%	82	10	87.8%
535		14	2	85.7%	69	8	88.4%	12	2	83.3%	66	6	90.9%
536		20	4	80.0%	82	14	82.9%	20	2	90.0%	80	5	93.8%
538	13	20	5	75.0%	82	15	81.7%	20	3	85.0%	82	12	85.4%
539		20	2	90.0%	36	4	88.9%	20	9	55.0%	36	18	50.0%

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
540	17	20	4	80.0%	82	11	86.6%	19	4	78.9%	78	6	92.3%
541		20	2	90.0%	82	10	87.8%	20	0	100.0%	82	15	81.7%
542		20	2	90.0%	82	7	91.5%	20	2	90.0%	81	13	84.0%
543		20	2	90.0%	82	8	90.2%	20	7	65.0%	82	22	73.2%
544		20	1	95.0%	81	7	91.4%	20	2	90.0%	80	9	88.8%
545		20	1	95.0%	82	7	91.5%	19	2	89.5%	80	7	91.3%
547		20	6	70.0%	82	12	85.4%	20	6	70.0%	82	20	75.6%
548		20	2	90.0%	82	12	85.4%	20	0	100.0%	82	6	92.7%
549		20	2	90.0%	79	15	81.0%	20	2	90.0%	76	9	88.2%
550		20	2	90.0%	36	5	86.1%	20	5	75.0%	36	7	80.6%
551		20	0	100.0%	79	7	91.1%	20	0	100.0%	77	7	90.9%
562	31	28	3	89.3%	118	14	88.1%	27	7	74.1%	116	16	86.2%
564	32	28	2	92.9%	118	11	90.7%	26	3	88.5%	112	15	86.6%
566	45	28	1	96.4%	118	7	94.1%	28	7	75.0%	115	15	87.0%
572		26	3	88.5%	115	10	91.3%	25	7	72.0%	112	25	77.7%
573		28	4	85.7%	118	16	86.4%	26	7	73.1%	114	17	85.1%
579		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
580		28	3	89.3%	118	5	95.8%	27	3	88.9%	117	12	89.7%
581		28	4	85.7%	118	14	88.1%	28	11	60.7%	118	27	77.1%
584	34	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
586		28	2	92.9%	118	21	82.2%	26	5	80.8%	111	16	85.6%
587		26	1	96.2%	116	6	94.8%	26	7	73.1%	112	18	83.9%
588		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
591		28	3	89.3%	118	5	95.8%	28	4	85.7%	117	12	89.7%
593		25	4	84.0%	115	18	84.3%	23	3	87.0%	105	12	88.6%
595		28	5	82.1%	117	24	79.5%	28	6	78.6%	116	20	82.8%
600	51	18	2	88.9%	82	4	95.1%	18	3	83.3%	82	8	90.2%
605		19	10	47.4%	83	51	38.6%	19	2	89.5%	82	8	90.2%
607		18	1	94.4%	82	5	93.9%	18	1	94.4%	81	5	93.8%
609	59	20	4	80.0%	83	9	89.2%	20	3	85.0%	83	7	91.6%
622		14	5	64.3%	14	5	64.3%	14	1	92.9%	14	1	92.9%
639	112	19	5	73.7%	83	23	72.3%	19	5	73.7%	83	12	85.5%
640	48	19	0	100.0%	83	5	94.0%	19	10	47.4%	82	42	48.8%
641	35	19	3	84.2%	83	17	79.5%	19	2	89.5%	83	14	83.1%
642	73	19	0	100.0%	82	4	95.1%	19	4	78.9%	82	12	85.4%
643	24	20	4	80.0%	84	18	78.6%	20	5	75.0%	83	15	81.9%
645	82	20	3	85.0%	84	11	86.9%	20	8	60.0%	84	19	77.4%
646	28	20	6	70.0%	84	22	73.8%	20	10	50.0%	83	47	43.4%
647	32	20	2	90.0%	84	9	89.3%	20	4	80.0%	84	20	76.2%
648		19	8	57.9%	83	22	73.5%	19	1	94.7%	83	11	86.7%
649		20	6	70.0%	84	17	79.8%	20	4	80.0%	83	13	84.3%
650		20	4	80.0%	84	18	78.6%	20	0	100.0%	84	15	82.1%

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
651		19	1	94.7%	83	6	92.8%	19	1	94.7%	83	19	77.1%
652		20	1	95.0%	84	13	84.5%	19	5	73.7%	82	17	79.3%
653	132	20	4	80.0%	84	16	81.0%	19	4	78.9%	83	21	74.7%
654	45	20	6	70.0%	84	21	75.0%	20	2	90.0%	84	7	91.7%
655	63	20	11	45.0%	82	29	64.6%	19	9	52.6%	80	28	65.0%
656	50	20	5	75.0%	84	22	73.8%	20	5	75.0%	84	10	88.1%
657	68	20	7	65.0%	84	10	88.1%	18	7	61.1%	82	19	76.8%
658	25	20	4	80.0%	84	13	84.5%	20	4	80.0%	84	15	82.1%
680	32	21	2	90.5%	87	4	95.4%	21	6	71.4%	87	13	85.1%
681	19	21	1	95.2%	87	4	95.4%	19	6	68.4%	85	25	70.6%
682		20	2	90.0%	86	2	97.7%	20	3	85.0%	86	17	80.2%
683	57	20	2	90.0%	69	6	91.3%	20	2	90.0%	69	18	73.9%
684	58	21	4	81.0%	68	13	80.9%	21	4	81.0%	68	18	73.5%
685	72	19	2	89.5%	83	11	86.7%	19	2	89.5%	83	19	77.1%
686	33	22	5	77.3%	88	20	77.3%	22	4	81.8%	88	19	78.4%
687	63	22	6	72.7%	88	15	83.0%	21	5	76.2%	87	16	81.6%
688	41	20	0	100.0%	86	1	98.8%	20	5	75.0%	86	19	77.9%
689		19	3	84.2%	73	8	89.0%	18	3	83.3%	71	7	90.1%
701		30	1	96.7%	54	7	87.0%	29	1	96.6%	53	3	94.3%
702		29	2	93.1%	121	19	84.3%	29	8	72.4%	120	32	73.3%
703		30	10	66.7%	122	34	72.1%	29	7	75.9%	121	31	74.4%
704	51	29	1	96.6%	53	4	92.5%	29	6	79.3%	52	11	78.8%
710		30	6	80.0%	122	41	66.4%	30	4	86.7%	122	38	68.9%
711		29	2	93.1%	115	10	91.3%	27	7	74.1%	106	19	82.1%
712	36	30	8	73.3%	122	30	75.4%	29	9	69.0%	119	42	64.7%
715		29	3	89.7%	121	33	72.7%	29	15	48.3%	114	58	49.1%
716	175	30	10	66.7%	122	50	59.0%	29	10	65.5%	119	51	57.1%
717	146	29	7	75.9%	112	30	73.2%	24	7	70.8%	100	35	65.0%
718		30	11	63.3%	122	50	59.0%	30	9	70.0%	121	38	68.6%
719	69	30	8	73.3%	122	43	64.8%	27	5	81.5%	117	37	68.4%
761		30	1	96.7%	120	5	95.8%	28	6	78.6%	118	20	83.1%
765		30	6	80.0%	120	14	88.3%	30	2	93.3%	120	19	84.2%
769	54	30	6	80.0%	120	13	89.2%	30	6	80.0%	118	24	79.7%
770		30	2	93.3%	120	12	90.0%	30	11	63.3%	120	25	79.2%
774		30	5	83.3%	120	12	90.0%	30	7	76.7%	119	26	78.2%
777		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
782		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
785		30	1	96.7%	120	1	99.2%	30	6	80.0%	120	20	83.3%
790		30	1	96.7%	120	7	94.2%	28	2	92.9%	118	13	89.0%
794		30	3	90.0%	120	11	90.8%	30	9	70.0%	119	25	79.0%
821	26	26	0	100.0%	118	3	97.5%	26	7	73.1%	118	53	55.1%
822	73	26	1	96.2%	118	4	96.6%	26	10	61.5%	118	57	51.7%

Amtrak On Time Performance

Trains Arriving Through: 1/30/2026

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1105		17	0	100.0%	23	2	91.3%	17	0	100.0%	23	1	95.7%
1106		17	1	94.1%	23	1	95.7%	17	1	94.1%	23	1	95.7%
1333		26	4	84.6%	118	14	88.1%	24	7	70.8%	115	43	62.6%
1340	34	25	0	100.0%	117	3	97.4%	25	6	76.0%	117	28	76.1%
2104	25	18	0	100.0%	52	7	86.5%	18	2	88.9%	51	7	86.3%
2109	18	18	2	88.9%	18	2	88.9%	17	2	88.2%	17	2	88.2%
2117	59	19	5	73.7%	52	15	71.2%	19	4	78.9%	52	10	80.8%
2124	26	17	2	88.2%	63	9	85.7%	17	4	76.5%	63	7	88.9%
2159	27	18	2	88.9%	81	5	93.8%	18	5	72.2%	80	21	73.8%
2162	75	19	3	84.2%	83	5	94.0%	18	11	38.9%	80	28	65.0%
2163	Cncld	19	7	63.2%	83	14	83.1%	16	13	18.8%	79	31	60.8%
2166	22	20	3	85.0%	84	10	88.1%	20	6	70.0%	82	18	78.0%
2190		19	4	78.9%	82	14	82.9%	19	6	68.4%	80	16	80.0%
2193	32	19	8	57.9%	82	11	86.6%	19	10	47.4%	82	31	62.2%

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2104	NYP	25	CTP	21	CTP	21	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C NJX359 DISABLED AT BERGEN	
2109	WAS	18	MTI	15	MTI	12	NYP-NWK	AM	Disabled train ahead, Other, NYP-NWK, CONGESTION A/C AM51 DISABLED AT PORTAL INT	
2117	WAS	59	WTR	51	WTR	51	NYP-NYP	AM	Snow removal equipment working ahead, Other, NYP, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE	
2124	NYP	26	PTI	16	DET	15	NWK-NYP	AM	Catenary failure, Other, XBH-NYP, SINGLE TRACKING A/C LOSS OF CATENARY POWER IN THE SOUTH TUBE	
2159	WAS	27	SYS	12	SYS	12	XGX-NHV	AM	Engineer restroom break	
2162	BOS	75	DBS	32	DBS	32	NYP-NYP	AM	Debris blocking track (no debris strike), Other, NYP, DEBRIS ON TRACKS AHD	
2163	XHM	Trn Cancelled								
2166	BOS	22	WTR	13	WTR	7	PVD-RTE	AM	Wet / slippery rail, Milepost w/Letters, PVD, RTE, WHEELSLIP	
2193	NYP	32	ITI	26	ITI	26	BOS-BOS	AM	Service, turn, or wye train, 2162, Late turn	
86	BOS	65	CTI	50	DMW	44	WBG-RVM	CS	Had to make a reverse move at Coney Island an talked by stop signal at rivanna jct due to track work Milepost, 84.0, 84.7	
95	NFK	101	SVS	39	SVS	39	OSB-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Removing Diesel engine @ NHV	
110	NYP	80	MTI	52	MTI	28	NWK-NYP	AM	Disabled train ahead, Other, NWK-NYP, CONGESTION A/C AM51 DISABLED AT PORTAL	
125	NPN	25	OTH	22	SVS	16	NHV-NHV	MN	Planned set out / pick out of locomotives, cars or section of train Control Point, 273	
136	SPG	19	SVS	20	SVS	20	NHV-NHV	AM	Fuel, DELAYED DUE TO WARMING UP ENGINE	
137	WAS	48	CAR	35	CAR	11	BOS-BOS	AM	Door, all consist, Door issues	
141	WAS	29	CAR	15	CAR	15	MET-TRE	AM	Air / Brake / Wheel, 00000, ACTUATED DED SECURED DRAGGING HOSES	
148	SPG	160	ENG	88	ENG	88	WAS-WAS	AM	Air / Brake, 606, MTR 606 SHOPPED AT DP TIME DUE TO MAIN RSS NEC'Y TO TOW OFF AND REPLACE	

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
170	BOS	34	MTI	41	MTI	25	NWK-NYP	AM	Disabled train ahead, Other, NWK-NYP, CONGESTION A/C AM51 DISABLED AT PORTAL	
171	RNK	25	WTR	27	OTH	13	XSH-NYP	AM	Lost time - N.A.R.	
172	BOS	59	CTP	45	CTP	45	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C NJX359 DISABLED AT BERGEN	
173	WAS	25	ENG	21	ENG	21	MET-XHM	AM	Air / Brake, 668, STOPPED AT GRUNDY A/C AIR PROBLEMS	
175	WAS	46	MTI	20	MTI	20	BWI-XNY	AM	Disabled train ahead, Control Point, NEW CARROLLTON, TRANSFER OF PSGRS FROM DISABLED 55 ON NO. 3 STATION TRK	
179	PHL	33	SMW	14	SMW	9	XHM-PHL	AM	Diversions around M/W work, Control Point, LEHIGH-GIRARD, OPR AROUND NOS 3 AND 4 TRKS O/S	
183	WAS	41	MTI	30	MTI	30	NYP-NYP	AM	Disabled train ahead, Other, NYP, HELD SINGLE TRACKING A/C AM51 DISABLED IN BERGEN INT	
185	WAS	48	MTI	51	MTI	51	NYP-NYP	AM	Disabled train ahead, Other, NYP, LATE TURN OFF AM110 A/C AM51 DISABLED AT PORTAL	
190	BOS	33	MTI	19	MTI	19	NWK-NYP	AM	Disabled train ahead, Other, "A" INT, AM641 FOULING "A" INT A/C AM51 DISABLED IN NORTH TUBE	
192	NYP	30	DET	37	DET	37	NWK-NYP	AM	Catenary failure, Other, XBH-NYP, SINGLE TRACKING A/C LOSS OF CATENARY POWER IN THE SOUTH TUBE	
193	WAS	40	CAR	20	CAR	20	NYP-NYP	AM	Door, 82783 82571 82808 82696, LATE F/SSYD AND DOOR ISSUES IN STATION	
196	NYP	23	PTI	21	DET	17	NWK-NYP	AM	Catenary failure, Other, XBH-NYP, SINGLE TRACKING A/C LOSS OF CATENARY POWER IN THE SOUTH TUBE	
417	NHV	Trn Cancelled								
425	SPG	29	DCS	36	DCS	36	GFD-NHT	MA	Restrictive signal(s) from known wayside signal failure Running at restricted speed cpr33 to cpr20, Stop, Control Point, cpr33	
474	SPG	Trn Cancelled								
486	GFD	30	CON	35	CON	35	NHV-NHV	AM	Hold for connecting train	

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
490	SPG	21	SVS	18	SVS	18	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from yard
600	NYP	51	CTP	30	CTP	30	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C NJX359 DISABLED AT BERGEN
609	HAR	59	SYS	49	SYS	49	NYP-NYP	AM	Delay in Block, NECESSARY TO RUN AROUND EQUIPMENT A/C NO CONTROL CAR IN CONSIST
639	PHL	112	SYS	104	SYS	104	NYP-NYP	AM	Alleged crew rules violation
640	NYP	48	MTI	48	MTI	27	TRE-NWK	AM	Disabled train ahead, Other, XUN-NWK, CONGESTION A/C AM51 DISABLED AT PORTAL
641	HAR	35	MTI	38	MTI	20	NYP-NWK	AM	Disabled train ahead, Other, "A" INT, HELD SINGLE TRACKING A/C AM51 DISABLED IN BERGEN INT
642	NYP	73	CTP	62	CTP	60	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, HELD AT REA A/C NJX359 DISABLED AT BERGEN
643	HAR	24	MTI	14	MTI	14	NYP-NYP	AM	Disabled train ahead, Other, NYP, LATE TURN OFF AM640 A/C AM51 DISABLED AT PORTAL
645	HAR	82	WTR	60	WTR	52	NYP-NYP	AM	Snow removal equipment working ahead, Other, NYP, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE
646	NYP	28	WTR	23	WTR	14	NWK-NYP	AM	Snow removal equipment working ahead, Other, XBH, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE
647	HAR	32	ENG	27	ENG	27	EWR-TRE	AM	Other electrical failure, 608, STOPPED ON NO.3 TRK AT COUNTY A/C HOSE CAME OFF BETWEEN CAB CAR AND FIRST CAR.
653	HAR	132	SYS	134	SYS	134	NYP-NYP	AM	Alleged crew rules violation, HELD IN SSYD DUE TO STOP SIGNAL VIOLATION
654	NYP	45	SVS	62	SVS	26	HAR-HAR	AM	Unplanned Wye, NO CAB CAR
655	HAR	63	SYS	45	SYS	45	NYP-NYP	AM	Alleged crew rules violation
656	NYP	50	WTR	21	SVS	20	ARD-PHL	AM	Unplanned Wye, NO CAB CAR
657	HAR	68	SYS	49	SYS	49	NYP-NYP	AM	Delay in Block, NECESSARY TO LOOP TRAIN A/C OPERATING WITH NO CONTROL CAR

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
658	NYP	25	DET	22	DET	22	NWK-NYP	AM	Catenary failure, Other, XBH-NYP, SINGLE TRACKING A/C LOSS OF CATENARY POWER IN THE SOUTH TUBE
19	NOL	40	DCS	57	CAR	33	WAS-WAS	AM	Heat / AC, 62035, COLD SLEEPER
680	BON	32	DCS	37	DCS	32	HHL-WOB	MT	Power switch failure Control Point, FR
681	BRK	19	PTI	18	PTI	18	POR-FRE	CS	Meet 684, Control Point, Royal
683	BRK	57	PTI	38	PTI	38	EXR-DHM	CS	Meet 684, Control Point, Rockingham
684	BON	58	SVS	40	SVS	40	BRK-BRK	CS	Planned wye off Lewiston Industrial in Brunswick
685	BRK	72	SVS	30	SVS	30	BON-BON	MT	Wye the train in Boston
686	BON	33	DMW	16	DMW	16	WEM-DOV	CS	Held for or routed around MW work or equipment Track 2 Out of service held at Willie for late 683 Meet, Control Point, Willie
687	BRK	63	ITI	56	ITI	49	BON-WOB	MT	Service, turn, or wye train 686, Late turn off Amtrak 686 had to WYE the train in Boston due to non comply crack in windshield run from opposite end
688	BON	41	FTI	18	FTI	18	POR-SAO	CS	Meet M426, Control Point, Cooks
63	TWO	131	FTI	75	MTI	31	NYP-NYP	AM	Disabled train ahead, Other, NYP, AM641 FOULING "A" INT A/C AM51 DISABLED IN NORTH TUBE
64	ALB	23	FTI	36	FTI	24	ROC-XSV	CS	Follow csxt, Control Point, 334
68	NYP	95	CAR	31	CAR	31	HUD-HUD	AM	Air / Brake / Wheel 48188, Sticky brakes, had to thaw with fusee
69	MTR	Trn Cancelled							
234	NYP	22	DCS	22	DCS	22	CRT-YNP	MN	Power switch failure Frozen Switch... Maintainer fixing, Control Point, 25
237	ALB	45	WTR	31	WTR	19	RHI-RHI	AM	Ice / snow on or under equipment Had to beat the door open with sludge hammer and pry bar all doors are frozen shut, Other, RHI
241	ALB	374	SYS	370	SYS	370	NYP-NYP	AM	Alleged crew rules violation
280	NYP	24	WTR	27	OTH	12	XSD-NYP	AM	Lost time - N.A.R.
281	NFL	127	ENG	99	ENG	99	XSV-ROC	CS	Air / Brake 127
283	NFL	70	FTI	58	FTI	25	ROC-BUF	CS	Follow Ran on approaches and approach limiteds the whole way, csx unknown, Milepost, 371, 429

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
284	NYP	46	DCS	37	DCS	31	UCA-AMS	CS	Power switch failure Control Point, 196
48	NYP	51	FTI	112	FTI	52	X81-ERI	CS	Follow Followed from 175 to Erie Station, I-16229, Control Point, 175
49	CHI	300	DCS	135	DCS	135	ERI-X81	CS	Power switch failure Control Point, 171
448	BOS	223	FTI	142	FTI	73	SPG-SPG	CS	Cross Traffic LL3830, LL12, Other, SPG
449	ALB	58	FTI	30	FTI	25	WOR-SPG	CS	Meet m484, Control Point, 48
43	PGH	40	WTR	54	WTR	54	NYP-NYP	AM	Snow removal equipment working ahead, Other, NYP, LATE ARRIVAL HELD ON SUB 3 A/C ICE PATROL IN LINE 4
75	CLT	15	PTI	8	PTI	8	CYN-DNC	NS	Meet #Am72, Control Point, Nelson
89	SAV	51	FTI	88	FTI	38	PTB-RMT	CS	Follow 409, Milepost w/Letters, a48.8, a78.5
90	NYP	39	FTI	105	FTI	79	RMT-PTB	CS	Meet CSX409, Control Point, Emporia
55	WAS	Trn Cancelled	ITI	101	ITI	99	SPG-SPG	AM	Service, turn, or wye train, 56, LATE TURN OF AM56
41	MIA	160	WTR	197	WTR	195	CHI-CHI	AM	Was told to use WTR code by CHI. Other, CUS
529	SJC	25	PTI	24	PTI	14	EMY-OKJ	UP	Wait for station track amtrak 712, Control Point, king St
538	ARN	13	FTI	22	FTI	12	RSV-RLN	UP	Meet UP, Control Point, RSV
540	SAC	17	MBO	21	MBO	21	MTZ-SUI	UP	For maritime traffic Control Point, rv033
50	NYP	87	WTR	74	WTR	71	WAS-WAS	AM	Ice / snow on or under equipment, Other, 25 TRK, LOW TEMPS CAUSED FROZEN LINES ON MTR 656, NEC'Y TO WYE MTR. TRAIN HAS VERY LIMITED DWELL ALLOTMENT
500	SEA	39	POL	33	POL	33	CTL-OLW	BN	Removal of passenger by police 503 removing passenger at OLW. Police requested
503	EUG	38	POL	59	POL	36	OLW-OLW	BN	Fare evader refused to detrain, police called, before police arrived a passenger paid for a ticket for the fare evader
504	SEA	21	DSR	15	DSR	6	PDX-VAN	BN	Per MW foreman Per form B 5638 (Jones), Milepost, 5.0, 7.5, 25, M1
505	PDX	55	SVS	25	SVS	25	VAN-PDX	BN	Unplanned Wye Control Point, T6
517	PDX	53	FTI	34	FTI	25	KEL-VAN	BN	Cross Traffic BNSF YARD JOB, Control Point, VANCOUVER CENTER

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
7	SEA	65	WTR	154	WTR	154	CHI-CHI	AM	Extremely cold weather conditions Other, C U S
8	CHI	-90	FTI	120	CON	86	SPK-SPK	BN	Hold for thruway bus The Seattle short bus got lost and had to double back to Wenatchee; sounds like it skipped Leavenworth and had to go back to Iwa after they did Wenatchee; bus was 2 hours behind other busses. Train departed Spokane at 0241(1 hour and 26 min late)
27	PDX	-68	DSR	6	DSR	5	VAN-PDX	BN	Per MW foreman Form B 5638, Milepost, 7.5, 5.0, 25, 1
28	SPK	79	DMW	99	DMW	63	WIH-PSC	BN	Hold for defect repair Milepost, 158.4, 158.4
821	FTW	26	DSR	27	INJ	19	GLE-FTW	BN	Injured or sick passenger
822	OKC	73	SYS	68	SYS	68	FTW-FTW	BN	Regular engineer was on PTO,no fill in engineer was called in until the on duty time for train 822.Train had to wait for an extra board engineer to show up to FTW.
329	MKE	92	CAR	54	CAR	54	CHI-CHI	AM	Diaphragm ID4203
332	CHI	15	CTI	8	CTI	8	GLN-XWA	ME	Follow Followed a late 2126 to Mayfair where we crossed over 2->1 to go around. Back 1->2 at A-3., Metra, 2126, Milepost, 17.5, 9.0
337	MKE	76	DCS	71	DCS	71	GLN-XRO	ME	Power switch failure Control Point, A-20
338	CHI	27	CTI	29	CTI	16	GLN-XWA	ME	Follow Metra, 2140, Milepost, 17.8, 2.9
339	MKE	32	CTI	39	CTI	33	GLN-XRO	ME	Follow Followed 2135, which was following 2133, and some eastbound Metras were making crossover moves in front of them. Signal issues at A20 earlier in the day caused the backup of traffic., Metra, 2135, Metra, 2133, Milepost, 17.8, 28.7
342	CHI	16	CTI	20	CTI	14	GLN-XWA	ME	Follow Followed 2156 from GLN to Mayfair, Metra, 2156, Other, GLENVIEW
350	PNT	48	CAR	38	CAR	30	ARB-DER	MI	Air / Brake / Wheel ID4303, ID4006, Main res hose separated put back together. All is good
562	SAN	31	CTI	19	PTI	13	XRJ-FUL	BN	Meet 561, Control Point, santa fe
564	SAN	32	PTI	23	PTI	23	SNC-SNP	SC	Meet 567, Control Point, serra
566	SAN	45	PTI	36	PTI	32	SNC-SNP	SC	Meet 769, Siding, cp serra
584	SAN	34	PTI	25	PTI	17	SNC-SNP	SC	Meet amtk 587, Control Point, serra

Amtrak Endpoint OTP Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/30/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
769	GTA	54	DCS	34	CTI	17	VNC-CWT	SC	Meet Two-stepping behind ML 114 because the siding platform is out of service., ml, 114, Control Point, Burnsen	
704	BFD	51	DBS	41	DBS	34	MCD-MDR	BN	Debris strike 717 debris strike with BNSF 5824, Train/ wood, Siding, le grand	
712	BFD	36	PTI	25	TCC	19	MCD-MCD	BN	PTC- IETMS recycle breaker to clear fault C8302	
716	BFD	175	TEN	126	TEN	126	OKJ-OKJ	UP	Failure of diesel engine Engine kept shutting down dropping HEP. TASI mechanical fit it running but it took two hours, C2124	
717	OKJ	146	INJ	175	INJ	175	MDR-MCD	BN	Injured or sick employee	
719	OKJ	69	PTI	63	PTI	49	MDR-MCD	BN	715 debris strike caused delay. amt715, Control Point, legrand	
4	CHI	46	FTI	136	FTI	45	LAP-FMD	BN	Follow BN 7600 E, Milepost w/Letters, W Merrill, Ortho	
301	STL	36	DCS	58	DCS	58	XTF-XUD	UP	Signal issues at UD Tower. Waited on MoW to fix issue. Control Point, UD Tower	
381	QCY	17	CTI	15	CTI	11	XUA-LAG	BN	Follow Milepost, 1.2, 13.0, Metra, 1217	
382	CHI	24	DCS	23	DCS	23	LAG-XUA	BN	Restrictive signal(s) from known wayside signal failure Signal dropping at Laverne, Stop, Control Point, lavernge	
390	CHI	75	SYS	81	SYS	75	HMW-XCS	CC	PTC-caused slow-down or penalty stop	
391	CDL	31	DCS	37	DCS	37	EFG-CEN	CC	Diamond was having issues timing out for up had to wait on maintainer to fix Control Point, kinmundy	
393	CDL	118	ENG	120	ENG	37	CHM-MAT	CC	Connection for horn issues slow down at crossings ID4628	
318	CHI	28	WTR	26	WTR	26	PON-PON	UP	Ice / snow on or under equipment Steps on unit 4011 would not retract B end bypass and manual to close steps, Other, Pontiac	
319	KCY	42	ENG	57	ENG	21	SMT-SMT	CC	Trouble Shoot XITCS error msg, and also getting authorization to cut out XITCS. From CNOC Mechanical IDTX4607	
1340	CHI	34	CTI	22	ITI	21	MKE-MKE	CP	Late inbound crew 337	

Amtrak Initial Terminal Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/30/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	654	01/30	26	26	Unplanned Wye, NO CAB CAR
HAR	656	01/30	8	8	Ice / snow on or under equipment, Control Point, ., FROZEN DOORS
LOR	53	01/30	3	3	34 carriers had to do a double double Milepost, 92.1, 92.1
MIA	98	01/30	3	3	Passenger and/or baggage Passenger came to train with folding recliner chair. Station asking conductor about baggage policies.
PHL	110	01/30	24	24	Electrical failure, ., Late equipment a/c frozen component on car.
PHL	190	01/30	11	11	Door, ENTIRE TRAIN, FROZEN DOORS
PHL	607	01/30	14	14	Planned set out / pick out of locomotives, cars or section of train, Late equipment out the yard.
RNK	178	01/30	109	109	Ice / snow on or under equipment Door frozen open in car # 82566 A-end fireman side. QMP was called to come out remove a bolt, force close the door, and red tag it out., Other, RNK Yard and RNK Station
WAS	148	01/30	128	40	Toilet, WHOLE TRAIN, LATE NOTICE TO SWAP SETS DUE TO FULL TOILETS
WAS	148	01/30	128	88	Air / Brake, 606, MTR 606 SHOPPED AT DP TIME DUE TO MAIN RSS NEC'Y TO TOW OFF AND REPLACE
WAS	176	01/30	7	7	Undesired emergency application, 602, MOTOR NEEDED TO BE RECYCLED. ONCE MECHANICAL CLEARED AT 334P THE CREW COMPLETED A BRAKE TEST BEFORE DP
WAS	196	01/30	3	4	Follow, A148, Control Point, WAS, FOLLOWING LATE A148
ALB	69	01/30	(No OS)		
BON	683	01/30	1	1	Mobility Impaired
BON	685	01/30	33	3	Copy authority / restriction Copy form d for a line 12, Other, at BON station
BON	685	01/30	33	30	Wye the train in Boston
BON	687	01/30	7	7	Service, turn, or wye train 686, Late turn off Amtrak 686 had to WYE the train in Boston due to non comply crack in windshield run from opposite end
BON	689	01/30	2	2	Passenger carried his bags onto train, then had to run back into station to get his bike.
BOS	137	01/30	11	11	Door, all consist, Door issues
BOS	2163	01/30	(Trn Cxld)		Engine Issue
BOS	2193	01/30	26	26	Service, turn, or wye train, 2162, Late turn
BRK	684	01/30	40	40	Planned wye off Lewiston Industrial in Brunswick
BRK	686	01/30	1		
GFD	425	01/30	4	4	Train 5552 ran restricting between cpr18 and cpr 33 5552
MTR	68	01/30	(Trn Cxld)		Equipment Issues

Amtrak Initial Terminal Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/30/2026

Terminal	Train	Date	Late	Delay	Cause
NHV	470	01/30	20	14	Hold for connecting train
NHV	470	01/30	20	6	Hold for connecting train
NHV	470	01/30	20	14	Hold for connecting train
NHV	470	01/30	20	6	Hold for connecting train
NHV	474	01/30	(Trn Cxld)		Engine Issue
NHV	490	01/30	18	18	Planned set out / pick out of locomotives, cars or section of train, Late release from yard
NYP	19	01/30	2	3	Passenger and/or baggage, LOADING
NYP	43	01/30	54	54	Snow removal equipment working ahead, Other, NYP, LATE ARRIVAL HELD ON SUB 3 A/C ICE PATROL IN LINE 4
NYP	49	01/30	50	50	Ice / snow on or under equipment, Other, SSYD
NYP	51	01/30	41	41	Ice / snow on or under equipment, Other, NYP, LATE F/SSYD A/C WEATHER RELATED ISSUES
NYP	63	01/30	31	31	Disabled train ahead, Other, NYP, AM641 FOULING "A" INT A/C AM51 DISABLED IN NORTH TUBE
NYP	89	01/30	3	3	Passenger and/or baggage, LATE BOARDING PSGRS
NYP	97	01/30	79	79	Other electrical failure, 622, DELAYED F/SSYD A/C NEED MOTOR OFF AM98
NYP	129	01/30	7	7	Passenger and/or baggage, boarding
NYP	181	01/30	12	12	Water, commissary, toilet/trash dumping, LATE RELEASE BY MENCHANICAL
NYP	183	01/30	30	30	Disabled train ahead, Other, NYP, HELD SINGLE TRACKING A/C AM51 DISABLED IN BERGEN INT
NYP	185	01/30	51	51	Disabled train ahead, Other, NYP, LATE TURN OFF AM110 A/C AM51 DISABLED AT PORTAL
NYP	193	01/30	20	20	Door, 82783 82571 82808 82696, LATE F/SSYD AND DOOR ISSUES IN STATION
NYP	197	01/30	10	10	Alleged crew rules violation
NYP	237	01/30	11	11	Service, turn, or wye train, 284, LATE TURN OFF AM284
NYP	239	01/30	5	5	Passenger and/or baggage, BOARDING
NYP	241	01/30	370	370	Alleged crew rules violation
NYP	281	01/30	6	6	Service, turn, or wye train, 234, LATE TURN OFF AM234
NYP	283	01/30	4	4	Passenger and/or baggage, LOADING
NYP	291	01/30	2	2	Lost time - N.A.R.
NYP	609	01/30	52	3	Passenger and/or baggage, LOADING

Amtrak Initial Terminal Details

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/30/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	609	01/30	52	49	Delay in Block, NECESSARY TO RUN AROUND EQUIPMENT A/C NO CONTROL CAR IN CONSIST
NYP	639	01/30	104	104	Alleged crew rules violation
NYP	641	01/30	18	18	Disabled train ahead, Other, NYP, HELD A/C AM51 DISABLED IN NORTH TUBE
NYP	643	01/30	14	14	Disabled train ahead, Other, NYP, LATE TURN OFF AM640 A/C AM51 DISABLED AT PORTAL
NYP	645	01/30	52	52	Snow removal equipment working ahead, Other, NYP, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE
NYP	649	01/30	20	20	Water, commissary, toilet/trash dumping, LATE SERVICING F/SSYD
NYP	653	01/30	134	134	Alleged crew rules violation, HELD IN SSYD DUE TO STOP SIGNAL VIOLATION
NYP	655	01/30	45	45	Alleged crew rules violation
NYP	657	01/30	84	84	Catenary maintenance , Other, NYP, HELD A/C SINGLE TRACKING A/C LOSS OF CATENARY POWER IN THE SOUTH TUBE
NYP	2117	01/30	51	51	Snow removal equipment working ahead, Other, NYP, HELD SINGLE TRACKING A/C ICE PATROL IN SOUTH TUBE
SPG	55	01/30	99	99	Service, turn, or wye train, 56, LATE TURN OF AM56
SPG	125	01/30	15	15	Hold for connecting train, Holding for pax connect.off late 495
SPG	417	01/30	(Trn Cxld)		Engine Issue
TWO	64	01/30	2		
CHI	7	01/30	23	23	Hold for connecting train Late inbound Amtrak 49/449
CHI	48	01/30	33	33	Service, turn, or wye train 49, Late arrival 49
CHI	329	01/30	54	54	Diaphragm ID4203
PNT	355	01/30	1	1	Mechanical had to finish there work with the train consists
SEA	511	01/30	1	1	Waited for 14 arrival 14, Control Point, sea
ARN	529	01/30	10	10	Meet freight 6037, Control Point, auburn, 6037
BFD	703	01/30	17	17	Service, turn, or wye train 712
FTW	822	01/30	68	68	Regular engineer was on PTO,no fill in engineer was called in until the on duty time for train 822.Train had to wait for an extra board engineer to show up to FTW.
OKJ	532	01/30	7	7	Door C8812, AMT 535 arrived at coach yard with door problems, train was blue flagged- departed late for OKJ
OKJ	536	01/30	1		
OKJ	540	01/30	6	6	Follow 716, Milepost, 7.0, 7.0
OKJ	716	01/30	126	126	Failure of diesel engine Engine kept shutting down dropping HEP. TASI mechanical fit it running but it took two hours, C2124

Eastern Region

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	NO DATA	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	No Data	No Data	93.8	No Data	N
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 53(30) North of Florence, SC - Freight Train Interference

31JAN26: Train 53(30) operating with engines 322, 511, 358, and 568 passengers, was delayed 20.5 miles north of Florence, SC, at milepost 272.3, on CSX South End subdivision, due to following freight train I137 from milepost 267-292 and freight train I036 from milepost 194-197.

Train	Delay	Comment
53(30)	57"	

Catenary Failure - South Tube New York, NY - Catenary or Wayside Failure

31JAN26: Penn Station Control Center reports catenary failure in the south tube which caused delays to multiple trains.

Train	Delay	Comment
65(30)	9"	
50(29)	39"	
90(30)	4"	
639(30)	11"	
177(30)	17"	
192(30)	37"	
658(30)	22"	
656(30)	16"	
657(30)	1'24"	
178(30)	28"	
2124(30)	15"	
196(30)	17"	
136(30)	13"	
148(30)	9"	
654(30)	11"	
80(30)	9"	
176(30)	18"	
20(30)	15"	

Train 19(29) South of Hattiesburg, MS - Freight Train Interference

30JAN26: Train 19(29) was delayed at MP90.9, 2 miles south of Hattiesburg, MS station on the Norfolk Southern N.O. & N.E. subdivision due to a meet with Norfolk Southern freight train 130(30).

Train	Delay	Comment
19(29)	30"	

Train 55(30) Springfield, MA - Servicing

30JAN26: Train 55(30) was delayed departing Springfield, MA station, on CSX Berkshire subdivision, due to turning from late inbound train 56(30). When 56(30) arrived in Springfield the equipment also had to be wye'd before it could load passengers and depart.

Train	Delay	Comment
55(30)	1'39"	

Train 687(30) Boston, MA - Initial Terminal Delay

30JAN26: Train 687(30) was delayed departing initial terminal of Boston, MA station/MP0.0 on the MBTA Boston Terminal subdivision due to a crack in the window making it necessary to wye the equipment.

Train	Delay	Comment
687(30)	56"	

Train 448(29) Springfield, MA - Freight Train Interference

30JAN26: Train 448(29) operating with engine 122 and 101, 3 coaches and 57 passengers, was delayed departing Springfield, MA on CSX Berkshire subdivision, due to holding for cross traffic freight trains LL3830 and LL12.

Train 448(29) was further delayed east of Springfield, MA, due to more freight train interference. CSX was straight railing east of Springfield, MA, due to weather.

Due to the late operation of the train, 448(29) had to perform their daily inspection on engine 122 at Framingham, MA

Train	Delay	Comment
448(29)	1'04"	East of SPG
448(29)	1'13"	
448(29)	41"	

Train 685(30) Boston, MA - Servicing

30JAN26: Train 685(30) was delayed departing initial terminal of Boston MA station/MP0.0 on the MBTA Boston Terminal subdivision due to wyeing the train before departure.

Train	Delay	Comment
685(30)	30"	

Train 609(30) New York, NY - System

30JAN26: Train 609(30) was delayed departing initial terminal of New York Penn Station, NY/MP0.0 on the Amtrak NYP Line due to not having a control car making it necessary to loop.

Train	Delay	Comment
609(30)	49"	

Train 684(30) Brunswick, ME - Servicing

30JAN26: Train 684(30) was delayed departing initial terminal of Brunswick, ME station on the CSX Portland subdivision due to a planned wye.

Train	Delay	Comment
684(30)	40"	

Train 683(30) South of Durham, NH - Passenger Train Interference

30JAN26: Train 683(30) was delayed at MP70.0, 6 miles south of Durham NH station on the CSX Portland subdivision due to a meet with train 684(30).

Train	Delay	Comment
683(30)	30"	

Train 486(30) New Haven, CT - Hold for Connection

30JAN26: Train 486(30) was delayed departing initial terminal of New Haven, CT on the MNRR New Have line holding for 24 connections off train 86(30). Train 486(30) departed New Haven CT station at 325pm with the connections.

Train	Delay	Comment
486(30)	35"	

Train 40(29) South of Petersburg, VA - M of W Work

30JAN26: Train 40(29) was delayed at MP57.8, 36.9 miles south of Petersburg, VA station on the CSX North End subdivision after setting off hot bearing defect detection. Crew inspected and found no exceptions. Train 40(29) was back on the move at 1248PM ET.

Train	Delay	Comment
40(29)	54"	

Train 97(30) New York, NY - Engine Failure

30JAN26: Train 97(30) was delayed departing initial terminal of New York Penn Station, NY/MP0.0 due to an engine swap. Engine 637 was shopped for electrical faults and train 97(30)'s original engine 636 was used as a replacement engine for train 183(30). It was necessary for 97(30) to wait for engine 622 off inbound train 98(29). Train 97(30) departed New York Penn station, NY. at 349PM ET after adding engine 622.

Train	Delay	Comment
97(30)	1'19"	

Train 53(30) South of Lorton, VA - Passenger Train Interference

30JAN26: Train 53(30) was delayed at MP92.0, 3.8 miles south of Lorton, VA station meeting 138(30), 80(30) and one freight train.

Train	Delay	Comment
53(30)	15"	80(30)
53(30)	29"	138(30)
53(30)	18"	Freight

Train 148(30) Washington, DC - Engine Failure

30JAN26: Train 148(30) was delayed departing initial terminal of Washington, DC/MP136 due to main reservoir issues with engine 606 after swapping sets due to full toilets on the original set. Engine was cut out and replaced with engine 665. Train 148(30) departed Washington DC station at 502PM ET.

Train	Delay	Comment
148(30)	2'07"	

30JAN26: Due to an all-~~28-FOI-00297~~ ~~00000005673~~ ~~UNCLASSIFIED~~ ~~29/2026~~ a 2 broken switches, number 37 and 39 switch, being ran through, damaging both switches. The equipment involved in the incident was intended for train 651(30) and consisted on engine 655, cabcar 9633, and 4 coaches. Multiple trains were delayed due to this equipment being taken out of service. Keystone trains had to short turn from other sets of equipment.

Due to the broken switches, train 241(30) was unable to depart the yard until repairs were made. C&S department responded for emergency repairs and the progress was slow going due to the extreme cold causing equipment and materials to freeze while they were making repairs. C&S department was able to make an emergency repair to allow train 241(30) to depart the yard. Train 241(30) was set into the station at 12:42am-et, with 129 passengers to board.

Train	Delay	Comment
241(30)	6'10"	
653(30)	2'14"	
655(30)	45"	
639(30)	1'44"	

Train 655(30) New York, NY - Cab Car Failure

30JAN26: Train 655(30) operating with engine 661, 5 coaches and 301 passengers was delayed departing New York, NY Penn Station, due to adding engine 661 on top of Cab Car 9635. Cab Car cannot lead due to bad cab signals. This also required train 655(30) to wye its equipment in Philadelphia, PA before heading to Harrisburg, PA.

Train	Delay	Comment
655(30)	38"	
655(30)	38"	Wye PHL

Train 51(30) East of Clifton Forge, VA - M of W Work

30JAN26: Train 51(30) was delayed 2 miles east of Clifton Forge, VA, on Buckingham Branch Railroad North Mountain subdivision, due to Maintenance inspecting the rails after a signal failure. Once maintenance cleared the tracks for operations, 51(30) was able to proceed.

Train	Delay	Comment
51(30)	34"	

Train 49(30) New York, NY - Weather

30JAN26: Train 49(30) was delayed departing initial terminal of New York Penn Station, NY/MP0.0 on the Amtrak NYP line due to frozen equipment in the yard.

Train	Delay	Comment
49(30)	50"	

Train 53(30) Fredericksburg, VA - Car Failure

30JAN26: 53(30) Operating with Engines 322, 511, 358, and 572 passengers was delayed at Fredericksburg, VA (milepost 53.9), on CSX Richmond Fredericksbur CFP Subdivision, due to sticking brakes on car 34121. Amtrak management responded and the crew was able to cut out the truck with the defective brake and get back on the move.

Train	Delay	Comment
53(30)	43"	

Train 281(30) West of Syracuse, NY - Car Failure

30JAN26: Train 281(30) operating with engine 127, 5 coaches, and 90 passengers, was delayed 24 miles west of Syracuse, NY, on CSX Rochester QC subdivision, due to frozen air lines on engine 127. The crew utilized fusees on the train to slowly thaw out the airlines and get back on the move.

Train	Delay	Comment
281(30)	1'39"	

Train 80(30) Petersburg, VA - Freight Train Interference

30JAN26: Train 80(30) was delayed beginning at MP78.5, 57.6 miles south of Petersburg, VA station on the CSX North End subdivision meeting freights 410 & 409.

Train	Delay	Comment
80(30)	1'09"	

Train 90(30) North of Rocky Mount, NC - Freight Train Interference

30JAN26: Train 90(30) was delayed at MP64.9, 77.5 miles north of Rocky Mount, NC station on the CSX North End subdivision meeting several trains.

Train	Delay	Comment
90(30)	10"	Meet 80(30)
90(30)	1'19"	Meet CSX409
90(30)	13"	Meet CSX
90(30)	10"	Meet 79(30)

Train 79(30) Rocky Mount, NC - Passenger Train Interference

30JAN26: Train 79(30) was delayed beginning at MP41.9, 81.9 miles north of Rocky Mount, NC station on the CSX North End subdivision following train 89(30).

Train	Delay	Comment
79(30)	37"	

Train 51(30) Charlottesville, VA - Freight Train Interference

30JAN26: Train 51(30) operating with engine 339, 25, 5 coaches and 78 passengers, was delayed at Charlottesville, VA, on Buckingham Branch Railroad North Mountain subdivision, due to holding for freight train G788(28).

Train	Delay	Comment
51(30)	32"	

Train 69(30) Terminated at Albany-Rensselaer, NY - Engine Failure

30JAN26: Train 69(30) arrived at Albany, NY/MP142.1 on the Amtrak Hudson line exhibiting engine issues on E/121. Passengers were brought in to the station while mechanical worked to resolve the issues. The decision was made to terminate Train 69(30) at Albany, NY due to HEP issues on engine E/121 and multiple doors frozen throughout the consist. Alternate transportation was provided to 58 passengers between Albany and Montreal. Due to equipment balance, Train 68(30) was also canceled between Montreal and Albany, NY, with no alternate transportation for 68 affected passengers.

- 68(31-03) Will terminate AT Albany, NY (ALB) No alternate transportation
- 69(31-02) Will originate at Albany, NY (ALB) No alternate transportation

Train 80(30) Rocky Mount, NC - Broken Rail

30JAN26: Train 80(30) was delayed at Rocky Mount, NC due to a broken rail at MP108.5 on the CSX South End Subdivision. Once maintainer arrived, repaired the rail and track inspected, Train 80(30) was able to proceed.

Train	Delay	Comment
80(30)	49"	

Train 178(30) Roanoke, VA - Weather

30JAN26: Train 178(30) was delayed departing initial terminal of Roanoke, VA/MP257.6 due to a door frozen open on the A end fireman side of car 82566. Mechanical responded to assist. Mechanical removed a bolt from the door and forced it closed. The door was red tagged and taken out of service. Train 178(30) departed Roanoke VA station at 1144AM ET.

Train	Delay	Comment
178(30)	1'49"	

Train 51(30) West of New York, NY - Engine Failure

30JAN26: Train 51(30) operating with engines 659 and 664, 5 coaches, and 88 passengers was delayed west of New York, NY, on Amtrak NYP Line, at milepost 3.6, due to a broken brake pipe on engine 659. The crew was able to repair the broken brake pipe and proceed into Newark, NJ. 51(30) was then instructed to wait at Newark, NJ for a rescue engine out of New York, which contained Amtrak Road Foreman who was to assist. It was determined that the repairs made to 51(30) would suffice and train 51(30) departed Newark, NJ.

Train 51(30) stopped again west of Newark, NJ at milepost 13.6 due to low main reservoir. The rescue engine with the Amtrak road foreman departed from Newark, NJ to meet the train and assist. The engineer on train 51(30) reported a split hoses in the consist and repairs were made. Train 51(30) was able to proceed.

50(30) was delayed departing Washington, DC, due to frozen pipes on engine 659. Mechanical responded and was able to thaw the pipes and restore proper functionality. Engine 659 also needed to be wyed.

Train	Delay	Comment
51(30)	2'14"	
63(30)	31"	
141(30)	05"	
640(30)	48"	
641(30)	38"	
2109(30)	15"	
110(30)	52"	
170(30)	41"	
643(30)	14"	
183(30)	30"	
185(30)	51"	
93(30)	08"	
50(30)	1'11"	

Acela Cancellations - Shopped Equipment

30JAN26: Due to multiple Acela sets "UNCLASSIFIED" due to wheel wear, cab signal issues and a current high shop count, causing shop congestion with limited material, multiple Acela trains were canceled until shop counts improve.

-Acela Trains 2153, 2155, 2192, 2167, 2150, 2171, 2107, 2192, 2108, 2121, 2150, 2168, 2170, 2122, 2126(30) were canceled in entirety.

-Acela Trains 2249, 2255, 2252, 2201, 2218(31) were canceled in entirety.

Empire Cancellations High Shop Counts - Engine Failure

30JAN26: The following service adjustments are in affect due to high shop counts in Albany-Rensselaer, NY.

Cancelled In Entirety

236-238-244-233-235(31, 01, 02)

245(31, 01)

243(02)

69(31, 01, 02) - TERM ALB; cancelled ALB - MTR - No ALT transportation

68(31, 01, 02, 03) - ORIG ALB; cancelled MTR-ALB - No ALT transportation

Winter Storm Gianna Cancellations

29JAN26: Due to Winter Storm Gianna, the following service adjustments are in the place: Floridian Service:

-Train 41(30) is cancelled entirely with no alternate between Chicago and Miami.

-Train 40(30) is cancelled entirely with no alternate between Miami and Chicago.

-Train 41(31) will originate at Jacksonville, FL to operate to Miami. No alternate between Chicago and Jacksonville.

-Train 40(31) will terminate at Jacksonville, FL with no alternate between Jacksonville and Chicago.

Palmetto:

- Train 89, 90 (31) cancelled in their entirety, no alternate transportation

Virginia Service

- Train 65(30) will terminate at Richmond-Staples Mill, VA, cancelled between Richmond-Staples Mill and Newport News, VA, no alternate transportation *Equipment will represent Train 124(31)*

- Train 99(31) will terminate in Richmond-Staples Mill, VA, cancelled Richmond-Staples Mill, VA and Newport News, VA, no alternate transportation *Equipment will represent Train 164(01)*

- Train 87(31) will terminate in Washington, DC, cancelled Washington to Norfolk, VA, no alternate transportation *Equipment will represent Train 128(31)*

- Train 124(31) will originate in Richmond-Staples Mill, VA, cancelled Newport News, VA to Richmond-Staples Mill, VA, no alternate transportation.

- Train 128(31) will originate in Washington, DC, cancelled Norfolk, VA to Washington, no alternate transportation.

- Train 164(01) will originate in Richmond-Staples Mill, VA, canceled Newport News, VA to Richmond-Staples Mill, VA, no alternate transportation.

Piedmont:

- Trains 71, 72, 77, 78 (31) cancelled in their entirety

WBS#: B.TR.100150.6446

27JAN26: Train 55(27) 26-FOT-00297/100500005673 5 ca UNCLASSIFIED" 113 2/9/2026 engers onboard reported they derailed E/145 and the headend truck of C/48190 in the interlocking at MP 110.5 on the NECR Palmer subdivision in Windham County. They were operating under 241 with C&S on scene. There were no injuries reported to passengers or crew. The equipment was upright and able to maintain HEP. Buses were secured and passengers were able to transfer at North Field interlocking.

Due to this train 56(27) turned in Springfield for 55(27). Train 55(27) had 3 busses for passengers from Brattleboro to Springfield and train 56(27) had 4 busses for passengers from Springfield to Brattleboro. They used 417(27) set to pull 56(27) equipment between Springfield and New Haven due to track conditions so train 417(27) was cancelled.

This will also have train 55(28) originate at New Haven with alternate bus service from St Albans to New Haven.

Train 474(27) departed New Haven at 501P-ET with E/111 and one traction motor cut out.

28JAN26: Car C/4819 was re-railed at 4:03AM-ET. and Engine E/145 was re-railed at 620AM-ET.

Train 56(28) was Terminated at NHV and 55(29) originated at NHV. 4 DATTCO busses were secured for alternate transportation between NHV-SAB for both trains.

Train 54(31) will operate thru to SAB on Saturday January 31st

Train 57(31) will originate NHV with alternate bus transportation SAB-NHV. Train will operate without food service NHV-WAS.

WBS#: B.TR.100150.6440

National Response Center Number: 1453529

Train	Delay	Comment
55(27)	TERM BRA	BUS BRA-SPG
56(27)	TERM SPG	BUS SPG-SAB
417(27)	cancelled	
474(27)	36"	NHV
55(28)	ORIG NHV	BUS SAB-NHV
55(27)	54"	Recrew at BAL
55(29)	Originated NHV	w/ALT
56(28)	Terminated NHV	w/ALT

10OCT25: To accommodate the above outlined infrastructure work, Amtrak's Crescent Service will be adjusted as follows:

- Train 19 (5Jan-7Jan, 11Jan-14Jan, 18Jan-21Jan, 25Jan-28Jan, 1Feb-4Feb, 8Feb-11Feb, 16Feb-18Feb, 22Feb-25Feb, 1Mar-4Mar), which normally operates between NYP and NOL, will terminate at ATL.
- Train 20 (6Jan-8Jan, 12Jan-15Jan, 19Jan-22Jan, 26Jan-29Jan, 2Feb-5Feb, 9Feb-12Feb, 17Feb-19Feb, 23Feb-26Feb, 2Mar-5Mar), which normally operates between NOL and NYP, will originate at ATL.

ALTERNATE TRANSPORTATION:

- Local Bus 3119 will provide alternate transportation between ATL and NOL, making all scheduled station stops.
- Express Bus 3019 will provide alternate transportation from ATL to NOL only.
- Local Bus 3120 will provide alternate transportation between NOL and ATL, making all scheduled station stops.
- Express Bus 3020 will provide alternate transportation from NOL to ATL only.

Weekly Friday through Sunday (This INCLUDES Monday February 16th) - No Track Work Scheduled:

- Trains 19 & 20 will operate normal schedule and route between Atlanta and New Orleans.
- Trains may incur delays of 20-30 minutes operating through the track work area, due to residual slow orders and congestion.

WBS#: B.TR.100150.6165

Long Bridge Replacement Outage - Scheduled M/W Work

18DEC25: Starting January 12, 2026 CSX Long Bridge replacement trackwork will commence causing reduced service and schedule changes through March 08, 2026 as follows:

January 11th will commence transition plan with 195 terminating New York and 153 terminating Washington D.C.

Monday through Friday: 114 cancelled, 133 cancelled, 141 terminates Washington D.C., 85 terminates Washington D.C., 176 originates Washington D.C., 174 originates Washington D.C., 84 originates Washington D.C., 134 originates Washington D.C., 86 originates Newport News, VA, 178 originates Roanoke, VA.

New trains operating Monday through Friday : 113 originating New York, NY and 198 originating Washington D.C.

Saturday: 167 terminates Philadelphia, PA, 153 terminates Washington D.C., 195 terminates Washington D.C., 155 operates through to Norfolk, VA, 164 originates Newport News, VA, 194 originates Washington D.C., 128 originates Norfolk, VA, 88 originates Washington D.C., 82 originates Washington D.C.

New train operating Saturday: 109 originates New York, NY

Sunday: 106 cancelled, 107 cancelled, 157 terminates Washington D.C., 155 operates through to Norfolk, VA, 195 terminates Washington D.C., 128 originates Norfolk, VA, 96 originates Washington D.C., 88 originates Washington D.C.

New trains operating Sunday: 117 originates Philadelphia, PA, 100 originates Washington D.C.

WBS#: B.TR.100150.6327

Eastern Region

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

West of Glenview, IL - Signal

30JAN26: Due to signal failure at Tower A20 approximately 3 miles west of Glenview, IL on CPKC C&M subdivision, Amtrak trains were delayed operating through that area.

Train	Delay	Comment
7(30)	28"	XWA-GLN / CTI
7(30)	30"	DCS
337(30)	07"	GLN / CTI
337(30)	1'11"	DCS
338(30)	11"	XRO-GLN / CTI
339(30)	33"	GLN-XRO / CTI

Train 393(30) Mattoon, IL - Engine Failure

30JAN26: Train 393(30) operating with E/IDTX 4628, 7 cars and 64 passengers onboard, had issues with the horn on E/IDTX 4628 on CN Champaign Subdivision approximately 18 miles north of Mattoon, IL. The crew troubleshoot and was able to make temporary repairs so they could continue south to Carbondale, IL where mechanical inspected.

Train	Delay	Comment
393(30)	17"	MAT
393(30)	23"	MAT - EFG
393(30)	37"	CHM - MAT
393(30)	16"	EFG
393(30)	25"	EFG - CEN

Train 6(29) East of Fort Morgan, CO - Injured or Sick Passenger or Employee

30JAN26: Train 6(29) operating with E/5, E/6, 8 cars and 89 passengers onboard, was delayed due to a passenger removal at MP 375 approximately 87 miles east of Fort Morgan, CO on BNSF Akron Subdivision. The passenger and his area was covered in an unknown white powder in C/31019. Local police and EMS removed the passenger, but left their personal items on the train. Arrangements were made with local police to meet Train 6(29) when it arrived at the Mc Cook, NE Station to have the passengers personal items safely removed. As a precaution, passengers were relocated into another coach car.

Train	Delay	Comment
6(29)	02"	
6(29)	45"	

Train 548(30) Martinez, CA - Passenger Removal - Medical

30JAN26: Train 548(30) was delayed departing Martinez when paramedics were called to assist a passenger. Passenger (PNR# 4680F5) travelling between Emeryville and Sacramento fell in the gap between the train step and platform causing scraped shin. Paramedics attended the train removing the passenger for treatment at a nearby medical facility. Amtrak Police Notified.

Train	Delay	Comment
548(30)	09"	

Train 48/448(30) - Initial Terminal Delay

30JAN26: Train 48/448(30) operating with E/108, E/113, 8 cars and 183 passengers onboard, was delayed departing Chicago, IL on Amtrak Chicago South Subdivision due to the turning of late inbound Train 49(29) that arrived 312P-CT, 5 hours late. Equipment went to the yard for servicing and inspection. The non-ACSES equipped trail E/154 in OKM status and replaced with ACSES equipped E/113 in the lead. There was a delay coupling E/113 onto E/108 due to an ice packed knuckle on the front of E/108. Mechanical released the train and it shoved to the station for boarding.

Train	Delay	Comment
48/448(30)	33"	

Train 5(30) West of Osceola, IA - Engine Failure

30JAN26: Train 5(30) operating with E/164, E/79, 8 cars and 102 passengers onboard, experienced issues with train unit e/79 which had a coolant leak west of Osceola, IA on BNSF Ottumwa Subdivision. Amtrak Road Foreman will meet the train in Omaha, NE for further examination. A freight engine was request from BNSF, Train 5(30) took a delay at the Lincoln, NE Station adding BNSF engine 9100.

Train	Delay	Comment
5(30)	10"	CRN - LNK
5(30)	16"	OTM - OSC
5(30)	1'32"	LNK

Train 14(30) North of Paso Robles CA, Delayed by Vehicle on Tracks

30JAN26: Train 14(30) was delayed for removal of a car on the tracks at, MP 168.68 on the Union Pacific Railroad, Coast Subdivision, 42 miles North of Paso Robles. The car was stuck on the tracks not at a designated crossing in San Lucas, Monterey County. Once the vehicle was removed and tracks were inspected, train 14(30) was able to resume. Amtrak Police Notified

Train	Delay	Comment
14(30)	15"	

Train 717(30) West of Madera Acres, CA - Debris Strike

30JAN26: At 4:47PM-PT . Train 717(30) -operating with camera equipped locomotive CDTX/2104 - was delayed 18 miles west of Madera after colliding with lumber overhanging a freight train in the siding. Train 717(30) was passing BNSF freight train BNSF/5284 at Legrand Siding - MP 1042.7, Stockton Subdivision of the BNSF Railway - when the incident occurred. There were no reported injuries to 129 passengers on board. The Engineer was transported - by paramedics - to Mercy Medical Center in Merced, for evaluation of chest pains. Locomotive CDTX/2124 provided Head End Power for the duration of the incident. Local weather was reported as 50°F , cloudy. Locomotive CDTX/2104 sustained extensive cosmetic damage to the front sections. Amtrak Merced Road Foreman along with Amtrak Police Officer responded. Once the relief engineer boarded and briefed, and BNSF officials inspected the scene , train 717(30) resumed. Amtrak Police Notified

National Response Center Number: 1453788

Train	Delay	Comment
704(30)	07"	
719(30)	49"	
716(30)	33"	
717(30)	2'55"	

Train 4(29) East of Gallup, NM - Freight Train Interference

30JAN26: Train 4(29) was delayed starting 26.1 miles east of Gallup, NM Station/MP 157 on BNSF Gallup Subdivision, from MP 156.7 to MP 94.4 following a BNSF 6165 freight train.

Train	Delay	Comment
4(29)	36"	

Train 716(30) Oakland Jack London - Initial Terminal - Cab Car Power Fault

30JAN26: Train 716(30) was delayed departing Oakland Jack London Square. Cab car CDTX/8314 was unable to receive power from trailing locomotive CDTX/2124. Technicians from Oakland Maintenance Facility attended the train to repair. After extensive diagnosing technicians were able to make repairs to restore power. Delays were extended waiting for Positive Train Control data to be updated. This was after a plan was made to use train 711(30) equipment for 716(30). This plan was cancelled when 716(30) was repaired.

Train	Delay	Comment
716(30)	2'06"	OKJ - ITD
540(30)	06"	OKJ - ITD - Follow 716(30)

Train 4(28) East of La Plata, MO - Freight Train Interference

30JAN26: Train 4(28) was delayed starting 47.9 miles east of La Plata, MO/MP312.7, on the BNSF Marceline Subdivision, between West Medill/MP264.8 and Ortho/MP237.1 following BNSF 7600. Additional delay at West Fort Madison/MP236.2 meeting BNSF 5541.

Train	Delay	Comment
4(28)	45"	Follow BNSF 7600
4(28)	14"	Meet BNSF 5541

Train 2(28) West of Houston, TX - Freight Train Interference

30JAN26: Train 2(28) was delayed west of Houston, TX/MP362.3, on the UPRR Glidden Subdivision, at Rosenberg/MP38.6 due to eastbound UP8812 in an undesired emergency ahead at Richmond/MP34. The freight crew walked their 12,000-foot train and was able to identify the issue to restore their air. Once recovered, UP8812 moved up in between the switches at Richmond to allow Train 2(28) to get around in the siding.

Train	Delay	Comment
2(28)	1'10"	

Train 390(30) North of Homewood, IL - Signal

30JAN26: Train 390(30), ID4627-7 Cars, stopped 9.9 miles north of Homewood, IL/MP13.6, on the CNRR Chicago Subdivision, at MP13.6 due signal failure causing PTC to drop. The crew contacted the CN PTC desk and was authorized to cutout PTC. Once complete, Train 390(30) continued to Chicago Union Station.

Train	Delay	Comment
390(30)	1'19"	

Train 391(30) North of Centralia, IL - Signal

30JAN26: Train 391(30) was delayed at Centralia, IL/MP252.3, on the CNRR Champaign Subdivision, due to the signals timing out at the Union Pacific Kinmundy diamond/MP229.4. Maintenance of Way responded to the location and was able to get the issue resolved to allow Train 391(30) to continue to Carbondale.

Train	Delay	Comment
391(30)	37"	

Train 350(30) East of Ann Arbor, MI - Air Hose Separation

30JAN26: At 12:43PM-ET, Train 350(30), E/57-6 Cars, stopped 6.7 miles east of Ann Arbor, MI/MP37.5, on the Amtrak Michigan Line, at MP30.8 after losing their main reservoir. The crew inspected their consist and found an air hose separation between cars ID4303 and ID4006. Head end power was intermittent while the crew worked in between the cars with 157 passengers onboard and the outside temperature reading 8 degrees. Once the hose was fixed and air restored, Train 350(30) was back on the move east at 1:10PM-ET.

Train	Delay	Comment
350(30)	30"	

Train 503(30) South of Oregon City, OR - Track Obstruction

30JAN26: Train 503(30) was delayed at Hito, MP 741.1/UPRR Brooklyn Subdivision, 15.2 miles south of Oregon City, waiting for downed commercial power lines to be removed from the tracks ahead.

Train	Delay	Comment
503(30)	23"	

Train 319(30) Summit, IL - XITCS Failure

30JAN26: Train 319(30), E/ID4607-7 Cars, was delayed at Summit, IL/MP11.8, on the CNRR Joliet Subdivision, from XITCS failure. The crew reported XITCS Error Code #C13004 occurred while coming into the station and contacted CNOC mechanical while at the station to troubleshoot. Unable to resolve so the crew received permission to cutout XITCS and continue to St. Louis not exceeding 79MPH.

Train	Delay	Comment
319(30)	26"	SMT
319(30)	31"	Operate Not Exceeding 79MPH

Train 49/449(29) West of Sandusky, OH - Freight Train Interference

30JAN26: Train 49/449(29) was delayed starting 25.5 miles west of Sandusky, OH/MP241.5, on the NSRR Chicago Line, between MP267.1 and Toledo, OH/MP288.3 following NS 334.

Train	Delay	Comment
49/449(29)	46"	

Train 566(30) South of San Juan Capistrano, CA - Passenger Train Interference

30JAN26: Train 566(30) was delayed at Serra, MP 199.7/SCRRA-Metrolink Orange Subdivision, 2.4 miles south of San Juan Capistrano, meeting Train 769(30).

Train	Delay	Comment
566(30)	32"	

Train 4(29) East of Flagstaff, AZ - Freight Train Interference

30JAN26: Train 4(29) was delayed approximately five miles east of Flagstaff, AZ/MP344.2, on the BNSF Seligman Subdivision, from MP338.3 to Winslow, AZ/MP285.5 following BNSF 7496.

Train	Delay	Comment
4(29)	52"	

Train 562 (30) – East of San Juan Capistrano, CA: Signal Failure

30JAN26: Train 562 (30) was delayed approximately five miles east of San Juan Capistrano after the dispatcher unable to remotely control of signals and grade crossings between Lantern (MP 202.2) and San Clemente Pier (MP 204.3) on the Metrolink Orange Subdivision. The crew obtained authority to pass affected signals and proceeded at reduced speed while protecting all crossings. Subsequent trains experienced additional delays due to single track congestion while signal maintainers completed repairs.

Train	Delay	Comment
562(30)	12"	Protecting Crossings
562(30)	03"	Lantern
564(30)	13"	Lantern
564(30)	23"	SERRA - Meet 567(30)
566(30)	32"	SERRA - Meet 769(30)
566(30)	08"	Protecting Crossings
769(30)	16"	Protecting Crossings
769(30)	13"	Songs - Meet 564(30)
567(30)	Not Reported	

Train 8/28(29) West of Whitefish, MT - Freight Interference / Tunnel Flush

30JAN26: Train 8/28(29) held 52.9 miles west of Whitefish, MT/MP1219.3, on the BNSF Kootenai River Subdivision, at Rock Creek/MP1272.2 meeting westbound BNSF 7092. Once the meeting was complete, additional delay was incurred waiting on the Flathead Tunnel/MP1271.6 to flush. Once the flush was complete, Train 8/28(29) was released to continue east.

Train	Delay	Comment
8/28(29)	1'00"	

Train 301(30) North of Joliet, IL - Signal

30JAN26: Train 301(30) was delayed 0.8 miles north of Joliet, IL/MP37.3, on the UPRR Joliet Subdivision, at MP36.5 due to a signal failure at UD Tower/MP37.4. Maintenance of Way responded to resolve the issue. Once complete, Train 301(30) was released to proceed into the station.

Train	Delay	Comment
301(30)	58"	

Train 49/449(29) East of Cleveland, OH - Frozen Switch

30JAN26: Train 49/449 (26-P01-00297) 100000005673 delayed UNCLASSIFIED 29/2026 east of Cleveland, OH/MP181.6, on the CSX Erie Subdivision, due to a frozen switch at CP171/MP171.4. The crew tried to manually line the switch, but all efforts were unsuccessful. Maintenance of Way responded to the location to thaw and line the switch for movement. Once complete, Train 49/449(29) continued into the station.

Train 7/27(30) was delayed departing Chicago, IL holding for the passenger connections from 49/449(29) that arrived at 3:12PM, 5 hours late.

Train	Delay	Comment
49/449 (29)	2'32"	
7/27 (30)	23"	

Train 503(30) Olympia-Lacey, WA - Police Related

30JAN26: Train 503(30) was delayed at the Olympia-Lacey depot, MP 32.2/BNSF Seattle Subdivision, waiting on local police to arrive and remove a fare evader. However, prior to the arrival of the police, another passenger purchased a ticket for the individual and the train was then able to proceed.

Train 500(30) was delayed at Tenino, MP 43.5, waiting on Train 503(30) to clear Olympia.

Train	Delay	Comment
503 (30)	36"	
500 (30)	33"	

Train 3(29) East of Lamar, CO - Air Hose Separation

30JAN26: At 5:43AM-MT, Train 3(29), E/190-E/192-6 Cars, went into emergency 27.2 miles east of Lamar, CO/MP502.1, on the BNSF La Junta Subdivision, at MP474.9. The Conductor reported that the brake pipe hose between trail engine 192 and crew dorm car 39017 struck the crossing which broke the glad hand. Head end power was intermittent while the crew worked in between the cars. There were 100 passengers onboard with an outside temperature of 22 degrees. Once the hose was replaced, Train 3(29) was back on the move west at 6:14AM-MT.

Train	Delay	Comment
3 (29)	30"	

Train 329(30) Chicago, IL - Car Failure

30JAN26: Train 329(30), E/ID4617-4 Cars-E/ID4618, was delayed departing Chicago, IL account a bad order replacement car. At 11:18pm, coach C/ID4004 was bad ordered for shelling to be replaced with C/ID4215. At 4:28am, replacement car C/ID4215 was bad ordered for diaphragm issues. It was determined that the car could be switched to the end of the consist which would rectify the situation. Once this was complete, the equipment set in the station to load the 17 waiting passengers. Train 329(30) departed CUS at 704am, 54 minutes late. After departure, 329(30) was further delayed from signal failure at CP Canal/MP0.57. After two Metra trains were talked passed the signal at CP Lake/MP0.47, Train 329(30) received authority past the stop signal. Once by, track speed resumed.

Train	Delay	Comment
329 (30)	54"	ITD CHI
329 (30)	21"	Signal

30JAN26: Train 28(29) at 00000005673 with E/139-3 Cars-E/ID4618, 79 passengers onboard, was delayed at MP 158.3 on BNSF Fallbridge Subdivision approximately 14 miles west of Pasco, WA due to track defect repairs ahead.

Train	Delay	Comment
28(29)	1'03"	

Chicago Delays / Cancellations - Frozen Equipment

28JAN26: Multiple trains were delayed or cancelled in Chicago, IL as a result of frozen equipment and late releases from mechanical.

29JAN26: Due to extreme weather, cancellations are now extended on the Midwest Corridor State supported trains through 01FEB

DELAYS:

-Train 329(28), E/139-3 Cars-E/ID4618, departed Chicago, IL 1 hour and 54 minutes late account frozen equipment and traction motor issues. Once the equipment was thawed, additional delay was incurred due to traction motor issues with engine 139. Chicago Mechanical responded to the train and was able to resolve the issue.

-Train 301(28), E/ID4613-5 Cars, departed Chicago, IL 2 hours and 37 minutes late as a result of frozen equipment. Mechanical was able to get all cars except business class car ID4210 to thaw for service. The business class car ID4210 deadheaded in line which resulted in 21 business class passengers downgraded to coach. Additional delay holding in the station for commissary to stock the train.

-Train 3(28) E/199, E/55, and 6 cars departed Chicago, IL 1 hour and 28 minutes late account of the late release of E/55 that needed to be thawed in the diesel pit.

-Train 5(28) E/76, E/194, and 8 cars departed Chicago, IL 1 hour and 38 minutes late account of replacing bad order diner car 38061 for refrigeration issues. It was necessary to switch Train 7/28(28) first and complete the drain and blow on the bad order car. Diner car 38061 was replaced with diner-lounge car 37009.

-Train 7/27(28) E/58, E/343, E/340 and 9 cars departed Chicago, IL 2 hours and 34 minutes late account of weather issues. Train 7/27(28) was made up with a replacement diner, coach and sleeper. Once released, and after two engines were wyeed, it was necessary for the pit to complete the daily inspection on E/343. the consist was watered and it was reported that they did not have a working dishwasher would would needed stock from the commissary to accommodate.

Train 41(28) E/48, E/163 and 10 cars departed Chicago, IL 3 hours and 15 minutes late as a result replacing an ogontz valve in sleeping car 62034, thawing frozen toilets in sleeping car 62044 and sleeping car 62503 was bad ordered due to a busted pipe and freeze damage. With no sleeping car replacement, 22 passengers were downgraded to coach seating. Train 41(28) used E/48 and E/163 off Train 6(26) which arrived at 214P-CT and had to be serviced.

CANCELLATIONS:

Wolverine:

- Train 352(28JAN) cancelled with two alternate buses secured.
- Trains 350-351-352-354-355(29JAN) cancelled with alternate buses secured.
- Trains 352-354(30JAN-01FEB) cancelled - sourcing alternate transportation.
- Trains 351-353(30JAN-02FEB) cancelled - sourcing alternate transportation.

Blue Water:

- Train 364(28JAN-31FEB) cancelled - sourcing alternate transportation.
- Train 365(29JAN-01FEB) cancelled - sourcing alternate transportation.

Pere Marquette

- Train 370(28JAN-01FEB) cancelled - sourcing alternate transportation.
- Train 371(29JAN-01FEB) cancelled - sourcing alternate transportation.

-Train 302(29JAN-02FEB) cancelled - sourcing alternate transportation.
 -Train 305(28JAN-01FEB) cancelled - sourcing alternate transportation.
 -Train 307(28JAN-01FEB) cancelled - sourcing alternate transportation.

Illinois Zephyr

-Train 383(28JAN-01FEB) cancelled - sourcing alternate transportation.
 -Train 380(29JAN-01FEB) cancelled - sourcing alternate transportation.

WBS#: B.TR.100150.6442

Train	Delay	Comment
301(28)	2'21"	ITD CHI
329(28)	1'54"	ITD CHI
3(28)	1'28"	ITD CHI
5(28)	1'38"	ITD CHI
7/27(28)	2'34"	ITD CHI
41(28)	3'15"	ITD

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

-715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
 -718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

-714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
 -718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
 -716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

-714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
 -713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

-520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
 -535(24) Cancelled. Turn of equipment from cancelled train 520(24).
 -534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

-Train 736(25-28) Cancelled - No alternate transportation.
 -Train 737(25-28) Cancelled - No alternate transportation.
 -Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

-Train 520(29-30) Cancelled - No alternate transportation.
 -Train 534(29-30) Cancelled - No alternate transportation.
 -Train 535(29) Cancelled - No alternate transportation.
 -Train 537(30) Cancelled - No alternate transportation.
 -Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

-Train 520(31) Cancelled - No alternate transportation.
 -Train 534(31) Cancelled - No alternate transportation.
 -Train 537(31) Cancelled - No alternate transportation.

Train 737(01-01) Cancelled - No alternate transportation.

05JAN26- 05MAR26

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

- TRAIN 714(05JAN-06MAR) Cancelled - No alternate transportation.
- TRAIN 713(06JAN-07MAR) Cancelled - No alternate transportation.

10JAN26 - 11JAN26

- Train 736(10-11) Cancelled - No alternate transportation.
- Train 737(10-11) Cancelled - No alternate transportation.

12JAN26 - 13JAN26

- Train 520(12-13) Cancelled - No alternate transportation.
- Train 534(12-13) Cancelled - No alternate transportation.
- Train 535(12-13) Cancelled - No alternate transportation.

14JAN26:

- Train 520(14) Cancelled - No alternate transportation.
- Train 537(14) Cancelled - No alternate transportation.
- Train 534(14) Cancelled - No alternate transportation.

15JAN26:

- Train 520(15-16) Cancelled - No Alternate Transport offered
- Train 534(15-16) Cancelled - No Alternate Transport offered
- Train 535(16) Cancelled - No Alternate Transport offered
- Train 537(15) Cancelled - No Alternate Transport offered

17JAN26:

- Train 718(17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744(17) OKJ-EMY.

21JAN26:

- Train 526(21) Cancelled - No Alternate Transport offered
- Train 534(21) Cancelled - No Alternate Transport offered
- Train 535(21) Cancelled - No Alternate Transport offered

23JAN26:

- Train 520(23) Cancelled - No Alternate Transport offered
- Train 534(23) Cancelled - No Alternate Transport offered
- Train 535(23) Cancelled - No Alternate Transport offered
- Train 736(23JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 737(23JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 520(26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 526(26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 534(26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 531(26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 537(26JAN-01MAR) Cancelled - No Alternate Transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train

Delay

Comment

718 (21)	Originate	Passengers to 744 (21)	OKJ-EMY
	EMY		
718 (22)	26-FOI-00297	00000005673	"UNCLASSIFIED" 2/9/2026
	Originate	Passengers to 744 (22)	OKJ-EMY
	EMY		
714 (22)	1'07"	ITD - OKJ - Late change of equipment	
718 (21)	37"	ITD - EMY	
716 (22)	20"		
718 (22)	3'10"	ITD - EMY	
714 (23)	.	CANCELLED	
713 (24)	.	CANCELLED	
535 (24)	Cancelled		
520 (24)	Cancelled		
534 (24)	Cancelled		
736 (25-28)	Cancelled		
737 (25-28)	Cancelled		
749 (28)	Cancelled	Balance Fleet to Protect Morning Service -	
		Passengers to 751 (28)	
551 (29-30)	Cancelled	Replacement Bus SAC-OKJ	
520 (29-31)	Cancelled	No alternate transportation.	
534 (29-31)	Cancelled	No alternate transportation.	
736 (01JAN-04JAN))	Cancelled	No alternate transportation	
737 (01JAN-04JAN)	Cancelled	No alternate transportation	
535 (29)	Cancelled	No alternate transportation.	
537 (30-31)	Cancelled	No Alternate Transportation	
713 (06JAN-07MAR)	CANCELLED	No Alternate Transport Offered	
714 (05JAN-06MAR)	CANCELLED	No Alternate Transport Offered	
736 (10-11JAN)	Cancelled	No Alternate Transport Offered	
737 (10-11JAN)	Cancelled	No Alternate Transport Offered	
520 (12-13-14- 15-16 JAN)	Cancelled	No alternate transportation	
534 (12-13-14-15-16 JAN)	Cancelled	No alternate transportation	
535 (12-13-16JAN)	Cancelled	No alternate transportation	
537 (14-15JAN)	Cancelled	No Alternate Transport offered	
718 (17)	Originate	Pax to 744 OKJ-EMY	
	EMY		
718 (17)	35"		
526 (21Jan)	Cancelled	No alternate transportation	
534 (21-23JAN)	Cancelled	No alternate transportation	
535 (21-23JAN)	Cancelled	No alternate transportation	
520 (23JAN)	Cancelled	No Alternate Transport Offered	
736/737 (23JAN-01MAR)	Cancelled	No Alternate Transportation	
520/526/534/531/537 (26JAN-01MAR)	Cancelled	No Alternate Transportation	

Western Region

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
8 (15)	SCD	369		Locked axle
5 (2)	GSC	51		Strike DMG
300 (26)	BNL	ID4633		Poss locked axle

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (30)	LNK	BNSF9100	Coolant leak		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 6(29) Passenger Removal at Fort Morgan, Colorado - Medical

30JAN26, Passenger on PNR 564944, traveling from Denver, CO to Chicago, IL was removed from the train by EMS after having a medical emergency. Amtrak Police notified.

Delay: 6 (29) 60"

Consist Deviations

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
448 (29)	ALB	4820 car on 448(*29*) will only operate live CHI-ALB. ALB will not switch it into the BOS-section therefore there will be no sleeper service for 448(29) ALB-BOS. please reaccom pax. sales closed.	car 4820 alb- bos dg to coach	14	NOCAR
93 (30)	BOS	business class in lieu of coach car on rearmost. over capacity	N/A	0	81544
93 (30)	BOS	BUSINESS CLASS OPERATING IN LIEU OF COACH	na	0	81544
449 (31)	BOS	449(*31*) will not have a 4920 sleeper BOS-ALB. there will be a third sleeper on 49(31) out of NYP for 4920 pax travelling ALB-CHI.	coach space was added for pax trvl BOS-ALB	5	82XXX
350 (30)	CHI	Extra car DH inline OKM.	N/A	0	ID4001
448 (30)	CHI	448(30) 4820 SLPR no car in consist please reaccommodate any passengers impacted by this. 4820 SLPR CHI-ALB ONLY, ALB-BOS canceled.	passengers reaccommodated and notified.	0	NO SLPR CAR
331 (30)	CHI	In lieu of single coach.	na	0	ID4206 ID4102
335 (30)	CHI	In lieu of single coach.	0	0	ID4306 ID4129
339 (30)	CHI	In lieu of single coach.	na	0	ID4306 ID4129
343 (30)	CHI	In lieu of single car coach.	na	0	ID4306 ID4129
3 (31)	CHI	Sleeper in lieu of crew dorm. schedule change has been performed.	war rpt	0	32065
1333 (30)	CHI	mainline clog on 34114. 35002 operating in lieu of 34xxx. no negative inventory impact.	n/a	0	34114, 35002
341 (31)	CHI	mainline clog on 34114. 35002 operating in lieu of 34xxx. no negative inventory impact.	na	0	35002, 34114

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00297 00000005673	"UNCLASSIFIED" 2/9/2026		
331 (31)	CHI	venture cafe pair in lieu of single coach. Y capacity increased.	na	0	ID4306, ID4129
335 (30)	CHI	venture cafe pair in lieu of single coach. Y capacity increased.	na	0	ID4306, ID4129
339 (31)	CHI	venture cafe pair in lieu of single coach. Y capacity increased.	na	0	ID4306, ID4129
6 (31)	EMY	Sleeper in lieu of crew dorm. schedule change performed, no impact to customers.	Passenger PNRs updated to reflect new rooms.	6	32038
600 (30)	HAR	NO cab car- inventory over capacities. No push pull.	over capacity email sent to have pa notified	67	NOCAR
642 (30)	HAR	NO cab car- inventory over capacities. No push pull.	n/a	0	NOCAR
648 (30)	HAR	SHORT ONE CAR DUE SHOP EQUIP	N/A	0	
330 (30)	MKE	In lieu of single coach.	na	0	ID4306 ID4129
334 (30)	MKE	In Lieu of single coach	na	0	ID4306 ID4129
338 (30)	MKE	In lieu of single coach.	na	0	ID4306 ID4129
342 (30)	MKE	In lieu of single car coach.	na	0	ID4306 ID4129
332 (30)	MKE	mainline clog on 34114. 35002 operating in lieu of 34xxx. no negative inventory impact.	na	0	34114, 35002
330 (31)	MKE	venture cafe pair in lieu of single coach. Y capacity increased.	na	0	ID412, ID4306
334 (31)	MKE	venture cafe pair in lieu of single coach. Y capacity increased.	na	0	ID4306, ID4129
338 (31)	MKE	venture cafe pair in lieu of single coach. Y capacity increased.	na	0	ID4306, ID4129
1340 (31)	MSP	mainline clog on 34114. 35002 operating in lieu of 34xxx. no negative inventory impact.	na	0	35002, 34114
449 (29)	NYP	62515 was planned to deadhead from NYP to run live in ALB for 449(29)	OBS reaccom some passengers to coach and we have	10	NOCAR

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00297 00000005673 "UNCLASSIFIED" 2/9/2026 section. 62515 is reported to NOT be in consist. 449(29) does not have a sleeper or lounge- only 1 coach	reaccommodated 4pax		
97 (30)	NYP	No lounge car in consist. only a diner.	obg mgr j smith will account for provisions for pax count	0	NOCAR
97 (30)	NYP	97(30) has no sleeper car for 9710 car. please reaccommodate impacted customers.	Passenger reaccommodated to coach	20	NOCAR
97 (30)	NYP	only 3 live coaches in consist. Y capped to 172 with no overages.	-7 / capacity cap tre-phl no pax impact	0	NOCAR
49 (30)	NYP	DH car inline okm a/c 98(29) turn intact.	N/A	0	62521 28016 25027
609 (30)	NYP	SHORT ONE CAR DUE SHOP EQUIP, NO WIFI	N/A	0	
645 (30)	NYP	SHORT ONE CAR DUE SHOP EQUIP, NO WIFI	SELF MOD / OVER CAP	45	
647 (30)	NYP	SHORT ONE CAR DUE SHOP EQUIP	-2 AT EWR	2	
355 (30)	PNT	Extra car DH inline OKM.	NA	0	ID4001
765 (30)	SAN	NO BV SERVICE	affected passengers notified	0	90215
22 (30)	SAS	Deadhead BYD HVAC inline; no replacement.	passengers to be moved to 422(28) side coach and rooms if needed	34	34030
794 (30)	SLO	NO BV SERVICE	affected passengers notified	0	90215
141 (30)	SPG	SHORT 1 CAR DUE SHOPPED EQUIPMENT	N/A	0	
143 (31)	SPG	short one coach 82637 shopped off 141(29)	no pax impact	0	82637
146 (31)	SPG	short one coach due to 82637 shopped off 141(29JAN)	no pax impact	0	82637
147 (31)	SPG	SHORT COACH DUE SHOPPED EQUIPMENT	N/A	0	
136 (30)	WAS	EQUIPMENT SWAP WITH 148(30) DUE CARS NEEDING TO BE DUMPED, AS RESULT 136 IS OVER CAP BY 72	OVER CAP SELF MOD LINK SNT TO PAX	72	

Reverse Consists

26-FOI-00297

00000005673

"UNCLASSIFIED"

2/9/2026

Train Number	Station	Reason
171 (30)	BOS	Consist reversed Business class seat orientation may have changed At Front
190 (30)	PHL	Consist reversed Business class seat orientation may have changed At Front
181 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front
125 (30)	SPG	Consist reversed Business class seat orientation may have changed At Rear
2117 (30)	NYP	Acela consist reversed First class at Rear
174 (30)	WAS	Consist reversed Business class seat orientation may have changed At Front
197 (30)	NYP	Consist reversed Business class seat orientation may have changed At Rear
147 (30)	SPG	Consist reversed Business class seat orientation may have changed At Front
156 (31)	RNK	Consist reversed Business class seat orientation may have changed At Front
192 (30)	WAS	Consist reversed Business class seat orientation may have changed At Rear
147 (31)	SPG	Consist reversed Business class seat orientation may have changed At Front
143 (31)	SPG	Consist reversed Business class seat orientation may have changed At Front