

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, February 01, 2026

Rules: 0-13



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/31/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/31/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	238	66	72.3%	8,751	1,418	83.8%	36,060	5,091	85.9%
Central Division	85.5%	55	8	85.5%	1,982	266	86.6%	8,066	933	88.4%
Northeast Division	80.0%	70	33	52.9%	2,787	559	79.9%	11,404	1,841	83.9%
Southeast Division	72.5%	51	13	74.5%	1,935	325	83.2%	8,282	1,202	85.5%
Southwest Division	77.0%	62	12	80.6%	2,047	268	86.9%	8,308	1,115	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00297 00000005672 "UNCLASSIFIED" 2/9/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	78,066	32,978	58%	2,502,006	617,575	75%	11,797,382	2,654,140	78%
Northeast Corridor	81%	33,681	16,472	51%	1,101,609	305,511	72%	5,258,450	1,186,475	77%
Acela	83%	3,531	660	81%	204,594	79,003	61%	1,088,014	290,031	73%
Northeast Regional	79%	30,150	15,812	48%	897,015	226,508	75%	4,170,436	896,444	79%
Richmond / Newport News / Norfolk	77%	8,789	5,267	40%	283,064	82,955	71%	1,284,365	315,996	75%
Springfield Shuttles	89%	264	139	47%	19,997	2,999	85%	71,670	8,923	88%
Roanoke	79%	1,664	377	77%	69,274	13,285	81%	322,144	56,907	82%
On Spine Northeast Regional	80%	19,433	10,029	48%	524,680	127,289	76%	2,492,257	514,618	79%
State Supported	80%	32,559	11,111	66%	1,093,700	216,649	80%	5,062,443	978,890	81%
Borealis	60%	436	0	100%	12,187	2,989	75%	66,095	16,867	74%
Capitol Corridor	90%	2,191	937	57%	103,436	10,950	89%	423,053	44,710	89%
Carolinian	60%	753	422	44%	27,466	6,996	75%	134,696	37,327	72%
Cascades	63%	2,341	419	82%	68,454	12,784	81%	288,973	65,220	77%
Downeaster	82%	1,188	903	24%	37,781	5,504	85%	172,852	23,209	87%
Empire	78%	3,111	1,997	36%	139,950	35,531	75%	629,624	135,963	78%
Adirondack	72%	0	0	-	7,701	2,895	62%	38,787	14,431	63%
Ethan Allen Express	70%	482	77	84%	14,197	3,639	74%	68,725	19,837	71%
Maple Leaf	70%	436	436	0%	17,952	9,779	46%	70,848	31,448	56%
New York - Albany	85%	1,103	676	39%	62,703	9,353	85%	287,640	39,536	86%
New York - Niagara Falls	75%	1,090	808	26%	37,397	9,865	74%	163,624	30,711	81%
Gold Runner	73%	2,127	406	81%	64,020	20,289	68%	296,859	105,246	65%
Heartland Flyer	65%	123	2	98%	3,940	1,037	74%	23,579	9,386	60%
Hiawatha	90%	1,270	616	51%	38,607	5,108	87%	198,038	24,677	88%
Illinois	78%	1,157	60	95%	55,713	12,159	78%	280,021	77,326	72%
Carl Sandburg / Illinois Zephyr	85%	187	0	100%	9,085	2,000	78%	48,212	12,303	74%
Illini / Saluki	85%	704	35	95%	20,893	4,748	77%	98,904	25,966	74%
Lincoln Service	70%	266	25	91%	25,735	5,411	79%	132,905	39,057	71%
Keystone	92%	5,788	2,281	61%	206,091	30,546	85%	950,811	104,960	89%
Lincoln / Missouri	60%	505	128	75%	18,146	6,012	67%	90,622	41,230	55%
Mardi Gras Service	80%	488	268	45%	10,682	1,354	87%	50,804	6,080	88%
Michigan	69%	469	383	18%	42,286	16,425	61%	223,728	72,010	68%
Blue Water	70%	0	0	-	9,313	4,364	53%	53,910	18,233	66%
Pere Marquette	85%	44	0	100%	4,851	1,726	64%	29,307	6,034	79%
Wolverine	65%	425	383	10%	28,122	10,335	63%	140,511	47,743	66%
Missouri	80%	116	0	100%	4,408	436	90%	26,773	5,534	79%
Pacific Surfliner	85%	8,306	1,437	83%	179,036	34,169	81%	797,004	123,032	85%
Pennsylvanian	72%	818	0	100%	23,733	2,683	89%	109,389	12,426	89%
Piedmont	73%	263	69	74%	26,906	3,960	85%	144,772	31,653	78%
Vermont	75%	1,109	783	29%	30,858	7,717	75%	154,750	42,034	73%
Long Distance	56%	11,017	5,395	51%	294,906	95,415	68%	1,461,630	488,508	67%
Auto Train	57%	899	574	36%	22,720	5,041	78%	86,515	15,801	82%
California Zephyr	50%	844	54	94%	28,687	7,781	73%	115,342	32,621	72%
Cardinal	55%	268	268	0%	5,208	2,045	61%	30,713	13,333	57%
City Of New Orleans	75%	781	652	17%	13,559	2,382	82%	79,293	16,813	79%
Coast Starlight	60%	885	80	91%	23,989	7,290	70%	133,590	42,018	69%
Crescent	70%	710	74	90%	18,928	2,689	86%	109,090	23,668	78%
Empire Builder	55%	697	322	54%	21,450	10,456	51%	115,326	46,310	60%
Floridian	40%	1,696	1,587	6%	40,467	22,528	44%	199,815	109,911	45%
Lake Shore Ltd	73%	919	844	8%	24,384	9,831	60%	113,905	28,823	75%
Palmetto	65%	909	508	44%	21,953	2,508	89%	111,630	17,747	84%
Silver Meteor	45%	864	162	81%	25,071	5,504	78%	121,652	36,475	70%
Southwest Chief	40%	578	213	63%	19,170	9,032	53%	95,845	55,214	42%
Sunset Ltd	70%	0	0	-	7,418	2,243	70%	34,125	8,410	75%
Texas Eagle	50%	967	57	94%	21,902	6,085	72%	114,789	41,364	64%
Seasonal Trains	%	809	0	100%	11,791	0	100%	14,859	267	98%
Winter Park Express	75%	809	0	100%	11,791	0	100%	14,859	267	98%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00207 00000005072 "UNCLASSIFIED" 2/0/2020

Train Index Dates Through January 31, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	169,510	3,020,274	561	697,786	12,880,813	542

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,507	860,921	87	28,246	3,743,046	75
INFRASTRUCTURE PLANNED	135	4,950	860,921	57	20,325	3,743,046	54
FLEET RELIABILITY	90	36,966	3,020,274	122	120,246	12,880,813	93
TRAIN OPERATIONS	424	120,087	3,020,274	398	528,969	12,880,813	411

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/31/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/31/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	238	66	72.3%	8,751	1,418	83.8%	36,060	5,091	85.9%
Central Division	85.5%	55	8	85.5%	1,982	266	86.6%	8,066	933	88.4%
Northeast Division	80.0%	70	33	52.9%	2,787	559	79.9%	11,404	1,841	83.9%
Southeast Division	72.5%	51	13	74.5%	1,935	325	83.2%	8,282	1,202	85.5%
Southwest Division	77.0%	62	12	80.6%	2,047	268	86.9%	8,308	1,115	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/31/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/31/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	238	66	72.3%	8,751	1,418	83.8%	36,060	5,091	85.9%
Central Division	85.5%	55	8	85.5%	1,982	266	86.6%	8,066	933	88.4%
CDL	90.0%	2	0	100.0%	61	1	98.4%	216	9	95.8%
CHI	85.0%	20	6	70.0%	777	155	80.1%	3,244	434	86.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	18	0	100.0%	24	2	91.7%
EUG	86.5%	2	0	100.0%	61	7	88.5%	239	33	86.2%
GRR	98.0%	-	-	-	25	2	92.0%	116	5	95.7%
KCY	84.5%	2	0	100.0%	60	2	96.7%	241	17	92.9%
MKE	86.5%	6	1	83.3%	182	11	94.0%	719	57	92.1%
MSP	94.0%	1	0	100.0%	25	0	100.0%	117	3	97.4%
PDX	78.0%	5	0	100.0%	148	18	87.8%	609	79	87.0%
PNT	91.5%	1	0	100.0%	79	17	78.5%	298	39	86.9%
PTH	93.0%	-	-	-	27	2	92.6%	118	9	92.4%
QCY	87.5%	1	0	100.0%	58	3	94.8%	242	20	91.7%
SEA	80.0%	8	0	100.0%	240	24	90.0%	971	143	85.3%
SPK	92.0%	1	0	100.0%	28	8	71.4%	123	13	89.4%
STL	88.0%	2	1	50.0%	113	14	87.6%	476	52	89.1%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	62	1	98.4%	241	7	97.1%
WIP	-	1	0	100.0%	18	1	94.4%	24	1	95.8%
Northeast Division	80.0%	70	33	52.9%	2,787	559	79.9%	11,404	1,841	83.9%
ALB	91.5%	6	3	50.0%	237	44	81.4%	852	90	89.4%
BON	43.5%	5	3	40.0%	148	19	87.2%	589	63	89.3%
BOS	86.5%	13	5	61.5%	503	90	82.1%	2,183	299	86.3%
BRK	88.0%	5	3	40.0%	147	16	89.1%	568	36	93.7%
BTN	48.0%	-	-	-	25	4	84.0%	116	22	81.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	1	1	0.0%	58	8	86.2%	234	23	90.2%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	-	-	-	25	6	76.0%	117	23	80.3%
NFL	96.5%	2	0	100.0%	62	4	93.5%	247	12	95.1%
NHV	75.5%	4	3	25.0%	162	34	79.0%	640	115	82.0%
NYP	77.5%	27	13	51.9%	1,164	304	73.9%	4,793	1,067	77.7%
SAB	98.0%	-	-	-	25	1	96.0%	115	1	99.1%
SAO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	1	83.3%	200	16	92.0%	761	40	94.7%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	84.0%	1	1	0.0%	30	12	60.0%	120	31	74.2%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	51	13	74.5%	1,935	325	83.2%	8,282	1,202	85.5%
ATL	-	-	-	-	14	0	100.0%	15	0	100.0%
CLT	92.0%	3	0	100.0%	144	10	93.1%	604	47	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/31/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/31/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	238	66	72.3%	8,751	1,418	83.8%	36,060	5,091	85.9%
Southeast Division	72.5%	51	13	74.5%	1,935	325	83.2%	8,282	1,202	85.5%
HAR	62.0%	7	1	85.7%	309	63	79.6%	1,338	253	81.1%
JAX	-	-	-	-	3	1	66.7%	3	1	66.7%
LOR	69.5%	1	0	100.0%	29	5	82.8%	121	14	88.4%
MIA	87.5%	2	1	50.0%	57	7	87.7%	241	26	89.2%
MOE	94.0%	2	0	100.0%	62	0	100.0%	246	3	98.8%
NFK	86.0%	1	1	0.0%	63	9	85.7%	321	37	88.5%
NOL	92.0%	5	0	100.0%	111	1	99.1%	518	21	95.9%
NPN	96.0%	1	0	100.0%	56	4	92.9%	215	14	93.5%
PGH	92.0%	1	0	100.0%	30	2	93.3%	122	5	95.9%
PHL	45.0%	4	4	0.0%	140	74	47.1%	564	288	48.9%
RGH	97.0%	2	0	100.0%	117	6	94.9%	481	15	96.9%
RNK	85.5%	2	1	50.0%	57	11	80.7%	240	32	86.7%
RVM	86.0%	-	-	-	11	0	100.0%	113	13	88.5%
RVR	-	1	0	100.0%	1	0	100.0%	4	3	25.0%
SAV	91.5%	-	-	-	28	0	100.0%	120	2	98.3%
SFA	70.5%	1	1	0.0%	29	6	79.3%	121	9	92.6%
WAS	70.0%	18	4	77.8%	674	126	81.3%	2,891	417	85.6%
Southwest Division	77.0%	62	12	80.6%	2,047	268	86.9%	8,308	1,115	86.6%
ARN	60.5%	1	0	100.0%	30	3	90.0%	122	10	91.8%
BFD	75.5%	6	0	100.0%	188	31	83.5%	740	166	77.6%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	1	0.0%	37	7	81.1%	136	43	68.4%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	28	1	96.4%	119	4	96.6%
GTA	72.5%	3	1	66.7%	105	9	91.4%	374	34	90.9%
IRV	-	-	-	-	2	2	0.0%	2	2	0.0%
LAX	77.5%	10	0	100.0%	286	29	89.9%	1,138	121	89.4%
OKC	96.0%	1	0	100.0%	27	0	100.0%	119	3	97.5%
OKJ	79.0%	7	4	42.9%	292	72	75.3%	1,291	314	75.7%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	10	4	60.0%	422	42	90.0%	1,639	171	89.6%
SAN	77.0%	12	1	91.7%	322	36	88.8%	1,379	127	90.8%
SAS	85.0%	1	0	100.0%	26	3	88.5%	118	7	94.1%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	217	23	89.4%	859	82	90.5%
SLO	62.0%	2	0	100.0%	50	5	90.0%	228	20	91.2%
SNC	-	-	-	-	15	5	66.7%	17	5	70.6%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/31/2026

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		31	8	74.2%	123	20	83.7%	31	9	71.0%	122	45	63.1%
4		31	3	90.3%	122	17	86.1%	31	15	51.6%	122	74	39.3%
5		31	8	74.2%	122	23	81.1%	30	8	73.3%	119	21	82.4%
6		31	6	80.6%	121	35	71.1%	31	10	67.7%	121	37	69.4%
7		26	8	69.2%	118	18	84.7%	24	7	70.8%	112	22	80.4%
8	158	26	11	57.7%	118	50	57.6%	25	15	40.0%	117	60	48.7%
11		31	4	87.1%	122	22	82.0%	28	3	89.3%	117	18	84.6%
14		31	6	80.6%	123	16	87.0%	31	10	67.7%	122	31	74.6%
19		28	9	67.9%	120	27	77.5%	28	1	96.4%	120	14	88.3%
20		28	0	100.0%	120	6	95.0%	28	3	89.3%	120	11	90.8%
21		26	1	96.2%	117	14	88.0%	25	4	84.0%	116	22	81.0%
22		26	2	92.3%	118	6	94.9%	26	7	73.1%	117	26	77.8%
23	78	31	0	100.0%	123	3	97.6%	31	7	77.4%	123	20	83.7%
24	143	31	1	96.8%	123	8	93.5%	31	2	93.5%	123	11	91.1%
25		31	0	100.0%	123	0	100.0%	31	5	83.9%	123	15	87.8%
26		31	0	100.0%	123	2	98.4%	31	2	93.5%	123	16	87.0%
27		25	7	72.0%	117	9	92.3%	23	8	65.2%	114	28	75.4%
28		23	6	73.9%	114	26	77.2%	23	7	69.6%	114	19	83.3%
40		28	4	85.7%	120	18	85.0%	30	10	66.7%	122	44	63.9%
40		28	4	85.7%	120	18	85.0%	30	10	66.7%	122	44	63.9%
41	131	28	13	53.6%	120	46	61.7%	29	22	24.1%	121	80	33.9%
42		30	2	93.3%	122	5	95.9%	29	3	89.7%	121	15	87.6%
43		30	9	70.0%	122	17	86.1%	30	4	86.7%	122	8	93.4%
48	56	29	13	55.2%	121	26	78.5%	29	9	69.0%	121	19	84.3%
49	153	29	11	62.1%	121	25	79.3%	29	9	69.0%	121	22	81.8%
51	278	11	6	45.5%	51	24	52.9%	12	2	83.3%	50	14	72.0%
52		29	6	79.3%	121	9	92.6%	29	3	89.7%	121	17	86.0%
53	134	29	5	82.8%	121	14	88.4%	29	6	79.3%	121	19	84.3%
54		10	1	90.0%	38	1	97.4%	10	1	90.0%	38	5	86.8%
58		23	0	100.0%	114	3	97.4%	23	3	87.0%	113	17	85.0%
59	38	23	6	73.9%	113	13	88.5%	23	2	91.3%	113	11	90.3%
63	181	31	22	29.0%	123	61	50.4%	31	17	45.2%	122	65	46.7%
64	193	30	12	60.0%	121	32	73.6%	30	9	70.0%	121	30	75.2%
65		10	1	90.0%	39	6	84.6%	10	0	100.0%	38	7	81.6%
66		29	6	79.3%	121	19	84.3%	29	4	86.2%	121	23	81.0%
68	164	31	11	64.5%	123	28	77.2%	31	16	48.4%	123	62	49.6%
73		30	2	93.3%	122	5	95.9%	30	11	63.3%	121	55	54.5%
74	119	30	3	90.0%	122	10	91.8%	30	10	66.7%	122	35	71.3%
75		30	2	93.3%	122	5	95.9%	28	10	64.3%	120	49	59.2%
76	12	30	4	86.7%	122	8	93.4%	27	8	70.4%	119	43	63.9%
79		29	3	89.7%	121	24	80.2%	29	3	89.7%	120	18	85.0%
80	47	29	1	96.6%	121	12	90.1%	29	3	89.7%	120	13	89.2%

Amtrak On Time Performance

Trains Arriving Through: 1/31/2026

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
82		7	2	71.4%	21	2	90.5%	7	2	71.4%	21	3	85.7%
87	20	11	4	63.6%	39	10	74.4%	11	3	72.7%	39	8	79.5%
88	29	11	4	63.6%	39	5	87.2%	11	4	63.6%	39	8	79.5%
97		29	17	41.4%	121	58	52.1%	29	2	93.1%	121	21	82.6%
98		28	3	89.3%	120	8	93.3%	28	6	78.6%	120	30	75.0%
99	259	10	3	70.0%	38	5	86.8%	10	6	40.0%	37	18	51.4%
101		7	0	100.0%	21	1	95.2%	7	1	85.7%	21	1	95.2%
103	18	10	3	70.0%	38	6	84.2%	10	2	80.0%	38	3	92.1%
106	24	9	1	88.9%	37	3	91.9%	9	3	66.7%	37	6	83.8%
107	43	9	4	55.6%	37	10	73.0%	9	3	66.7%	37	5	86.5%
109		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
118		10	0	100.0%	38	2	94.7%	10	1	90.0%	38	3	92.1%
124	17	9	0	100.0%	37	2	94.6%	9	2	77.8%	37	6	83.8%
135	126	10	2	80.0%	38	7	81.6%	10	7	30.0%	38	21	44.7%
136		20	2	90.0%	84	9	89.3%	20	3	85.0%	84	8	90.5%
140	134	10	0	100.0%	38	2	94.7%	10	2	80.0%	38	8	78.9%
142		7	2	71.4%	21	2	90.5%	7	0	100.0%	21	0	100.0%
143	18	10	0	100.0%	38	2	94.7%	10	1	90.0%	38	4	89.5%
144	26	7	6	14.3%	22	14	36.4%	7	3	57.1%	22	3	86.4%
146	95	10	2	80.0%	38	7	81.6%	10	6	40.0%	38	15	60.5%
147	144	7	0	100.0%	21	3	85.7%	7	1	85.7%	21	3	85.7%
150	43	11	5	54.5%	39	27	30.8%	11	7	36.4%	39	26	33.3%
151	39	28	8	71.4%	120	35	70.8%	28	6	78.6%	119	31	73.9%
152		7	0	100.0%	21	0	100.0%	7	1	85.7%	21	5	76.2%
153		11	0	100.0%	39	2	94.9%	11	2	81.8%	39	5	87.2%
155	20	11	2	81.8%	39	5	87.2%	11	2	81.8%	39	6	84.6%
156		11	1	90.9%	39	4	89.7%	11	1	90.9%	39	6	84.6%
158	48	10	1	90.0%	38	1	97.4%	10	2	80.0%	38	3	92.1%
159	55	7	4	42.9%	21	5	76.2%	7	4	42.9%	21	4	81.0%
160		10	0	100.0%	38	0	100.0%	10	3	70.0%	36	7	80.6%
161	48	10	2	80.0%	38	3	92.1%	10	9	10.0%	38	24	36.8%
162		11	0	100.0%	39	2	94.9%	11	6	45.5%	39	17	56.4%
163	70	7	2	71.4%	21	4	81.0%	7	5	28.6%	21	13	38.1%
164		11	1	90.9%	39	5	87.2%	11	3	72.7%	39	12	69.2%
165	35	11	3	72.7%	39	11	71.8%	11	6	45.5%	39	14	64.1%
167		7	2	71.4%	21	4	81.0%	7	3	57.1%	21	4	81.0%
168	40	7	0	100.0%	21	2	90.5%	7	6	14.3%	21	10	52.4%
178	126	20	5	75.0%	84	15	82.1%	21	4	81.0%	85	13	84.7%
179	57	20	3	85.0%	84	9	89.3%	21	5	76.2%	85	19	77.6%
194		7	3	57.1%	21	6	71.4%	6	1	83.3%	20	3	85.0%
195	43	11	0	100.0%	39	0	100.0%	11	9	18.2%	39	28	28.2%
198		14	2	85.7%	16	4	75.0%	14	0	100.0%	16	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 1/31/2026

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
232		31	3	90.3%	123	5	95.9%	31	2	93.5%	123	8	93.5%
234		31	5	83.9%	123	9	92.7%	31	6	80.6%	123	9	92.7%
237	88	31	8	74.2%	122	23	81.1%	31	10	67.7%	121	17	86.0%
239	43	31	12	61.3%	122	36	70.5%	30	7	76.7%	121	11	90.9%
240	23	31	4	87.1%	123	13	89.4%	30	4	86.7%	122	16	86.9%
241		31	7	77.4%	123	31	74.8%	31	6	80.6%	123	20	83.7%
280	300	31	2	93.5%	123	6	95.1%	31	9	71.0%	123	26	78.9%
281	19	31	5	83.9%	123	14	88.6%	31	9	71.0%	123	19	84.6%
283	33	31	8	74.2%	123	28	77.2%	31	10	67.7%	123	25	79.7%
284	128	31	2	93.5%	123	5	95.9%	31	9	71.0%	122	16	86.9%
290		31	7	77.4%	123	26	78.9%	30	9	70.0%	121	40	66.9%
291		30	8	73.3%	122	26	78.7%	30	5	83.3%	122	20	83.6%
301		31	2	93.5%	121	4	96.7%	30	4	86.7%	119	20	83.2%
306		30	2	93.3%	120	8	93.3%	30	4	86.7%	119	24	79.8%
311		31	5	83.9%	122	15	87.7%	30	3	90.0%	120	23	80.8%
316		30	2	93.3%	120	7	94.2%	30	3	90.0%	120	21	82.5%
318	30	30	0	100.0%	122	11	91.0%	30	12	60.0%	121	49	59.5%
319		31	1	96.8%	123	5	95.9%	30	10	66.7%	122	58	52.5%
330		26	0	100.0%	103	2	98.1%	26	3	88.5%	103	8	92.2%
331	49	31	6	80.6%	123	17	86.2%	31	7	77.4%	123	21	82.9%
332		31	1	96.8%	123	10	91.9%	31	6	80.6%	123	22	82.1%
334	43	31	2	93.5%	123	4	96.7%	31	5	83.9%	122	17	86.1%
335	42	31	3	90.3%	123	17	86.2%	31	7	77.4%	121	24	80.2%
336		31	2	93.5%	123	6	95.1%	31	1	96.8%	123	6	95.1%
337		31	1	96.8%	123	6	95.1%	31	3	90.3%	123	15	87.8%
338	37	31	6	80.6%	123	27	78.0%	31	10	67.7%	121	32	73.6%
339	12	31	6	80.6%	123	26	78.9%	31	8	74.2%	123	27	78.0%
341		28	5	82.1%	117	21	82.1%	26	4	84.6%	114	18	84.2%
342	21	31	0	100.0%	123	8	93.5%	30	5	83.3%	121	21	82.6%
343		5	1	80.0%	18	2	88.9%	5	1	80.0%	18	5	72.2%
350	33	30	6	80.0%	104	9	91.3%	28	21	25.0%	102	62	39.2%
355	20	28	9	67.9%	119	19	84.0%	24	11	54.2%	114	36	68.4%
370		27	8	70.4%	119	13	89.1%	24	9	62.5%	116	25	78.4%
381		31	3	90.3%	123	5	95.9%	31	5	83.9%	123	16	87.0%
382		31	1	96.8%	123	3	97.6%	31	5	83.9%	123	28	77.2%
390		31	1	96.8%	107	10	90.7%	31	11	64.5%	106	36	66.0%
391		31	1	96.8%	108	3	97.2%	30	7	76.7%	105	22	79.0%
392		30	0	100.0%	122	4	96.7%	29	5	82.8%	120	33	72.5%
393		31	3	90.3%	123	10	91.9%	31	8	74.2%	122	33	73.0%
400	Cncld	11	1	90.9%	37	3	91.9%	10	0	100.0%	35	1	97.1%
405	16	11	0	100.0%	35	0	100.0%	11	1	90.9%	35	3	91.4%
449		28	3	89.3%	58	4	93.1%	28	3	89.3%	58	8	86.2%

Amtrak On Time Performance

Trains Arriving Through: 1/31/2026

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
450	32	12	5	58.3%	37	13	64.9%	11	5	54.5%	36	13	63.9%
460	71	11	6	45.5%	37	18	51.4%	10	5	50.0%	34	12	64.7%
461	Cncld	11	1	90.9%	38	4	89.5%	10	0	100.0%	37	1	97.3%
463		7	1	85.7%	20	2	90.0%	7	0	100.0%	20	0	100.0%
464	78	12	6	50.0%	37	10	73.0%	11	2	81.8%	36	10	72.2%
467		7	0	100.0%	20	1	95.0%	7	0	100.0%	19	0	100.0%
488	Cncld	11	5	54.5%	39	12	69.2%	9	3	66.7%	34	7	79.4%
500		31	3	90.3%	123	9	92.7%	31	3	90.3%	122	13	89.3%
502	21	31	2	93.5%	123	9	92.7%	30	7	76.7%	121	28	76.9%
503		31	2	93.5%	120	13	89.2%	30	11	63.3%	118	33	72.0%
504		31	3	90.3%	123	11	91.1%	31	7	77.4%	122	32	73.8%
505		31	5	83.9%	123	21	82.9%	31	9	71.0%	121	26	78.5%
506		31	3	90.3%	122	17	86.1%	31	2	93.5%	121	15	87.6%
507		31	1	96.8%	123	12	90.2%	31	8	74.2%	123	40	67.5%
508		31	5	83.9%	121	26	78.5%	31	3	90.3%	121	25	79.3%
509		31	1	96.8%	123	8	93.5%	31	3	90.3%	123	28	77.2%
511	30	31	3	90.3%	123	13	89.4%	31	4	87.1%	123	21	82.9%
516		31	0	100.0%	121	9	92.6%	31	9	71.0%	121	47	61.2%
517	63	31	0	100.0%	123	2	98.4%	31	8	74.2%	122	39	68.0%
518		31	3	90.3%	123	16	87.0%	31	21	32.3%	123	75	39.0%
519		31	1	96.8%	121	5	95.9%	31	4	87.1%	121	18	85.1%
562		29	3	89.7%	119	14	88.2%	28	7	75.0%	117	16	86.3%
564		29	2	93.1%	119	11	90.8%	27	3	88.9%	113	15	86.7%
566		29	1	96.6%	119	7	94.1%	29	7	75.9%	116	15	87.1%
572		27	3	88.9%	116	10	91.4%	26	7	73.1%	113	25	77.9%
573		29	4	86.2%	119	16	86.6%	27	7	74.1%	115	17	85.2%
579		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
580		29	3	89.7%	119	5	95.8%	28	3	89.3%	118	12	89.8%
581		29	4	86.2%	119	14	88.2%	29	11	62.1%	119	27	77.3%
584		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
586		29	2	93.1%	119	21	82.4%	27	5	81.5%	112	16	85.7%
587		27	1	96.3%	117	6	94.9%	27	7	74.1%	113	18	84.1%
588		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
591		29	3	89.7%	119	5	95.8%	29	4	86.2%	118	12	89.8%
593		26	4	84.6%	116	18	84.5%	24	3	87.5%	106	12	88.7%
595		29	5	82.8%	118	24	79.7%	29	6	79.3%	117	20	82.9%
611		7	7	0.0%	21	18	14.3%	7	2	71.4%	21	3	85.7%
657	92	20	7	65.0%	84	10	88.1%	19	8	57.9%	83	20	75.9%
660	22	11	1	90.9%	39	3	92.3%	11	5	54.5%	39	16	59.0%
661		11	0	100.0%	39	3	92.3%	11	5	54.5%	39	11	71.8%
662		7	0	100.0%	23	0	100.0%	7	0	100.0%	23	0	100.0%
663	88	11	2	81.8%	39	5	87.2%	11	1	90.9%	39	2	94.9%

Amtrak On Time Performance

Trains Arriving Through: 1/31/2026

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
664	19	10	1	90.0%	38	6	84.2%	10	3	70.0%	38	4	89.5%
665		11	0	100.0%	39	6	84.6%	11	3	72.7%	39	14	64.1%
666		11	3	72.7%	39	13	66.7%	11	0	100.0%	39	3	92.3%
667	76	11	3	72.7%	39	6	84.6%	11	3	72.7%	39	9	76.9%
669		10	2	80.0%	38	4	89.5%	10	5	50.0%	38	15	60.5%
670	22	11	2	81.8%	39	6	84.6%	11	2	81.8%	39	4	89.7%
671		10	2	80.0%	38	3	92.1%	10	1	90.0%	38	5	86.8%
672		11	2	81.8%	39	5	87.2%	11	3	72.7%	39	5	87.2%
674		10	6	40.0%	38	14	63.2%	10	1	90.0%	38	1	97.4%
689	11	19	3	84.2%	73	8	89.0%	19	4	78.9%	72	8	88.9%
690		9	0	100.0%	35	0	100.0%	9	0	100.0%	35	1	97.1%
691	77	9	0	100.0%	35	2	94.3%	9	3	66.7%	35	9	74.3%
692	55	9	1	88.9%	35	2	94.3%	9	1	88.9%	35	8	77.1%
693	48	9	2	77.8%	35	5	85.7%	9	1	88.9%	35	8	77.1%
694	41	9	1	88.9%	35	5	85.7%	9	1	88.9%	35	4	88.6%
695	51	9	1	88.9%	35	4	88.6%	9	2	77.8%	35	7	80.0%
696	126	9	2	77.8%	35	3	91.4%	9	3	66.7%	35	8	77.1%
697	87	9	2	77.8%	35	5	85.7%	9	2	77.8%	35	7	80.0%
698	13	8	0	100.0%	34	0	100.0%	8	1	87.5%	34	4	88.2%
701		31	1	96.8%	55	7	87.3%	30	1	96.7%	54	3	94.4%
702		30	2	93.3%	122	19	84.4%	30	8	73.3%	121	32	73.6%
703		31	10	67.7%	123	34	72.4%	30	7	76.7%	122	31	74.6%
704	125	30	2	93.3%	54	5	90.7%	30	7	76.7%	53	12	77.4%
710		31	6	80.6%	123	41	66.7%	31	4	87.1%	123	38	69.1%
711		30	2	93.3%	116	10	91.4%	28	7	75.0%	107	19	82.2%
712		31	8	74.2%	123	30	75.6%	30	9	70.0%	120	42	65.0%
715		30	3	90.0%	122	33	73.0%	30	15	50.0%	115	58	49.6%
716		31	10	67.7%	123	50	59.3%	30	10	66.7%	120	51	57.5%
717		30	7	76.7%	113	30	73.5%	25	7	72.0%	101	35	65.3%
718	1420	31	12	61.3%	123	51	58.5%	31	10	67.7%	122	39	68.0%
719		31	8	74.2%	123	43	65.0%	28	5	82.1%	118	37	68.6%
720	52	11	1	90.9%	41	3	92.7%	11	1	90.9%	41	2	95.1%
723		11	1	90.9%	41	4	90.2%	11	1	90.9%	41	4	90.2%
724		11	1	90.9%	41	1	97.6%	11	3	72.7%	41	5	87.8%
727		11	1	90.9%	41	4	90.2%	11	1	90.9%	41	7	82.9%
728	28	11	2	81.8%	41	4	90.2%	11	3	72.7%	41	8	80.5%
729		11	1	90.9%	41	4	90.2%	11	0	100.0%	41	7	82.9%
732	Cncld	11	3	72.7%	41	8	80.5%	10	2	80.0%	40	6	85.0%
733	18	11	3	72.7%	41	6	85.4%	11	4	63.6%	37	11	70.3%
734	66	11	1	90.9%	41	10	75.6%	11	1	90.9%	41	7	82.9%
738	48	11	3	72.7%	41	8	80.5%	11	1	90.9%	39	3	92.3%
741		11	0	100.0%	41	7	82.9%	11	0	100.0%	41	4	90.2%

Amtrak On Time Performance

Trains Arriving Through: 1/31/2026

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
742	42	11	1	90.9%	41	5	87.8%	11	1	90.9%	40	4	90.0%
743		11	1	90.9%	41	5	87.8%	11	1	90.9%	41	3	92.7%
744	30	11	1	90.9%	41	4	90.2%	11	1	90.9%	41	12	70.7%
745		11	0	100.0%	41	3	92.7%	11	1	90.9%	41	8	80.5%
746	23	11	1	90.9%	41	1	97.6%	11	2	81.8%	41	4	90.2%
747	49	11	2	81.8%	41	9	78.0%	11	3	72.7%	41	9	78.0%
748	46	11	1	90.9%	40	7	82.5%	11	2	81.8%	40	5	87.5%
751		11	3	72.7%	41	10	75.6%	11	1	90.9%	40	6	85.0%
761	27	31	1	96.8%	121	5	95.9%	29	7	75.9%	119	21	82.4%
765		31	6	80.6%	121	14	88.4%	31	2	93.5%	121	19	84.3%
769		31	7	77.4%	121	14	88.4%	31	6	80.6%	119	24	79.8%
770	28	31	2	93.5%	121	12	90.1%	31	12	61.3%	121	26	78.5%
774		31	5	83.9%	121	12	90.1%	31	7	77.4%	120	26	78.3%
777	110	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
782		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
785		31	1	96.8%	121	1	99.2%	31	6	80.6%	121	20	83.5%
790	51	31	1	96.8%	121	7	94.2%	29	3	89.7%	119	14	88.2%
794		31	3	90.3%	121	11	90.9%	31	9	71.0%	120	25	79.2%
821		27	0	100.0%	119	3	97.5%	27	7	74.1%	119	53	55.5%
822		27	1	96.3%	119	4	96.6%	27	10	63.0%	119	57	52.1%
1105		18	0	100.0%	24	2	91.7%	18	0	100.0%	24	1	95.8%
1106		18	1	94.4%	24	1	95.8%	18	1	94.4%	24	1	95.8%
1333		27	4	85.2%	119	14	88.2%	25	7	72.0%	116	43	62.9%
1340		26	0	100.0%	118	3	97.5%	26	6	76.9%	118	28	76.3%
2203		7	0	100.0%	21	0	100.0%	7	2	71.4%	21	2	90.5%
2205		10	1	90.0%	38	4	89.5%	10	1	90.0%	38	3	92.1%
2214		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
2216		7	0	100.0%	21	1	95.2%	7	0	100.0%	21	0	100.0%
2248		8	0	100.0%	35	4	88.6%	8	1	87.5%	35	8	77.1%
2250		10	2	80.0%	38	5	86.8%	10	3	70.0%	38	14	63.2%
2259		7	2	71.4%	21	9	57.1%	7	4	42.9%	20	12	40.0%
2271	60	8	1	87.5%	22	2	90.9%	8	5	37.5%	22	11	50.0%

Amtrak Endpoint OTP Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/31/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2271	WAS	60	DCS	30	DCS	30	PVD-XGX	AM	T.O.L, Control Point, XDR, delay going through Davisville due to the TOL that's on trk 1
87	WAS	20	HLD	34	HLD	24	NHV-NHV	MN	Fire alarm at NHV station
88	BOS	29	CAR	46	CAR	46	WAS-WAS	AM	Air / Brake / Wheel, ALL, FROZEN EQUIPMENT
99	RVR	259	TRS	169	TRS	89	XVG-ALX	CS	Trespasser strike Other, CFP 111.2
103	WAS	18	ITI	17	ITI	17	NYP-NYP	AM	Service, turn, or wye train, 144
106	NYP	24	SMW	11	SMW	11	NWK-NYP	AM	Scheduled in track usage program, Other, NWK NYP
107	WAS	43	ITI	22	ITI	22	NYP-NYP	AM	Service, turn, or wye train, 106
124	PHL	12	PTI	41	PTI	41	ALX-ALX	CS	99 involved in trespasser strike at cfp111.5. Held at ALX until investigation is completed to allow passengers from 124 to make alternative arrangements to was if they wanted p09931, Other, alx
135	WAS	126	WTR	54	WTR	40	NYP-NYP	AM	Ice / snow on or under equipment, Other, FROZEN DOORS
140	SPG	134	SVS	134	SVS	134	NHV-NHV	AM	Planned Switch, AM140 reports E/88 has water pump issues, engine will be swapped to E/98 NHV
143	WAS	18	CTI	11	ENG	9	MDN-WFD	AM	Cab signal failure, 112, Cabs dropped to restricting State. St to MP61.0
144	NYP	26	WTR	46	WTR	46	PHL-PHL	AM	Snow removal equipment working ahead, Control Point, ., Equipment shifted around a/c frozen doors.
146	SPG	95	WTR	42	SVS	40	WAS-WAS	AM	Water, commissary, toilet/trash dumping, ALL TOILETS FULL, NEC'Y TO DUMP TRAIN AFTER WYING
147	RNK	144	WTR	117	WTR	80	LYH-RNK	NS	Ice / snow on or under equipment Switches frozen, Control Point, Webster
150	BOS	43	SVS	43	SVS	43	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
151	RNK	39	WTR	37	WTR	37	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, A-INTERLOCKING, 27 SW AND 27 DERAIL DUE TO ICE IN SWITCH POINTS
155	NFK	20	PTI	18	ENG	14	WAS-WAS	AM	HEP, 302
158	NYP	48	ENG	27	ENG	27	NFK-NFK	NS	Loading problem 330

Amtrak Endpoint OTP Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/31/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
159	WAS	55	WTR	28	SMW	24	NYP-NWK	AM	Scheduled in track usage program, Other, HUDSON-LACK 55HR OUTAGE SINGLE TRACKING	
161	WAS	48	CAR	16	DCS	10	KIN-XGX	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), Stop and protect on approach to Mystic River, Milepost, XM6, XM6	
163	WAS	70	SVS	36	SVS	36	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Engine shopped E/624	
165	WAS	35	CAR	18	SVS	15	BOS-BOS	AM	Water, commissary, toilet/trash dumping, AM165 dp BOS 15" late a/c being cleaned	
168	BOS	40	SYS	14	SYS	14	NYP-NYP	AM	Other late crew	
178	BOS	126	WTR	150	WTR	109	RNK-RNK	NS	Ice / snow on or under equipment Door frozen open in car # 82566 A-end fireman side. QMP was called to come out remove a bolt, force close the door, and red tag it out., Other, RNK Yard and RNK Station	
179	PHL	57	SYS	44	SYS	44	NHV-BRP	MN	Other late crew Crew arrived on train 148 which was late at nhv once arrived a job briefing and class 2 brake test needed to be performed.... Error in delay report we departed much later, Control Point, 272	
195	WAS	43	SMW	20	SMW	20	NYP-NWK	AM	Scheduled in track usage program, Other, XPT-XPT, HELD A/C SINGLE TRACKING NO.2 TRK LACK TO HUDSON	
400	GFD	Trn Cancelled								
405	NHV	16	DCS	13	DCS	13	MDN-WFD	AM	T.O.L, Milepost, xhc, xhc, Rule 241 Eng.9640 south of Holt R/S cabs Holt	
450	SPG	32	CON	26	CON	21	NHV-NHV	AM	Hold for connecting train	
460	SPG	71	SVS	71	SVS	71	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from mechanical	
461	NHV	Trn Cancelled								
464	SPG	78	SVS	83	SVS	83	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, delayed out of NHV due to frozen equipment	
488	GFD	Trn Cancelled								

Amtrak Endpoint OTP Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/31/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
53	SFA	134	FTI	117	CAR	43	XDJ-XRV	CS	Air / Brake / Wheel 34121, Brakes would release had to cut them out
80	NYP	47	DCS	65	DCS	65	HPT-GRO	NS	Power switch failure Switch problems @ CP:COX place in hand after waiting for maintainer., Control Point, COX
657	HAR	92	DET	84	DET	84	NYP-NYP	AM	Catenary maintenance , Other, NYP, HELD A/C SINGLE TRACKING A/C LOSS OF CATENARY POWER IN THE SOUTH TUBE
660	NYP	22	DCS	11	DCS	11	PHL-XHM	AM	T.O.L, Control Point, clearfield-shore
663	HAR	88	ENG	106	ENG	106	NYP-NYP	AM	Undesired emergency application, 651, LATE F/SSYD A/C FAULTS ON ENG.651
664	NYP	19	SVS	19	SVS	19	PAO-PHL	AM	Unplanned Wye, Wye'd on the inbound a/c bad equipment
667	HAR	76	POL	34	SVS	23	PHL-ARD	AM	Unplanned Wye, NO CAB CAR
670	NYP	22	PTI	14	SMW	11	NWK-NYP	AM	Scheduled in track usage program, Other, HUDSON- LACK 55HR OUTAGE SINGLE TRACKING
689	BRK	11	DCS	9	DCS	5	XP0-EXR	CS	Issue with automatic road crossing protection Form D Line 12 Protect Crossing, Other, Front St MP PLD 75.85
691	BRK	77	DCS	59	DCS	35	WOB-HHL	MT	Power switch failure Control Point, Vale, Control Point, FR, Control Point, JK
692	BON	55	SVS	21	SVS	11	BRK-BRK	CS	Unplanned Wye Cab car 90214 PTC initialization failure, Control Point, Brunswick West
693	BRK	48	PTI	24	PTI	17	EXR-DHM	CS	Meet 694, Control Point, Rockingham
694	BON	41	DCS	31	DCS	16	WEM-DOV	CS	Issue with automatic road crossing protection Picked up a clear at 51.8, Other, Elm St mp PLD 49.28
695	BRK	51	SVS	26	SVS	26	BON-BON	MT	Wye the train in Boston Other, BON
696	BON	126	DCS	74	DCS	55	HHL-WOB	MT	Power switch failure Had to throw cp vale locks frozen, Control Point, Vale
697	BRK	87	ITI	86	ITI	86	BON-BON	MT	Service, turn, or wye train 696, Late turn off of Amtrak 696
698	BON	13	PTI	16	PTI	16	DHM-EXR	CS	Meet 697, Control Point, rockingham
63	TWO	181	SVS	97	SVS	82	NYP-NYP	AM	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
64	ALB	193	FTI	62	FTI	21	UCA-AMS	CS	Follow m364, Milepost, 237, 178

Amtrak Endpoint OTP Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/31/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
68	NYP	14							
237	ALB	88	ITI	80	ITI	80	NYP-NYP	AM	Service, turn, or wye train, 290
239	ALB	43	ITI	45	ITI	45	NYP-NYP	AM	Service, turn, or wye train, 280
240	NYP	23	SVS	31	SVS	31	ALB-ALB	AM	Late release from shop due to frozen equipment
280	NYP	300	DCS	206	DCS	200	BUF-ROC	CS	Power switch failure - Stopped @ QC 415.3 behind a freight - Switches at CP 410 frozen, freight crew could not resolve, waited for maintainer, Control Point, CP 410
281	NFL	19	CTI	29	CTI	25	CRT-POU	MN	Follow metro north, local, Control Point, 46
283	NFL	33	SVS	22	SVS	22	ALB-ALB	AM	Compressor issue after back up hose test ALB mechanical reset the system
284	NYP	128	FTI	75	SVS	48	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train Waiting for switching work to be finished on late Amtrak train 280, Other, alb
48	NYP	56	FTI	163	FTI	74	ROC-SYR	CS	Follow ?, Control Point, 329
49	CHI	153	FTI	119	WTR	50	NYP-NYP	AM	Ice / snow on or under equipment, Other, SSYD
74	RGH	119	TRS	91	TRS	91	SAL-HPT	NS	Vehicle on track ahead Vehicle stuck on track ahead; waiting for removal and track inspection., Milepost, 317.9, 317.9
76	RGH	12	FTI	20	FTI	20	KAN-GRO	NS	Follow NS 12R, Control Point, Lake
41	MIA	131	ENG	66	ITI	30	CHI-CHI	AM	Service, turn, or wye train 41, Late turn of equipment off inbound 40(27) which arv'd at 12:15pm, 3 hours and 30 minutes late.
23	NOL	78	FTI	106	FTI	106	GUF-BAS	CS	Meet M520/CSX 4743 N, Amtk 24, Siding, Harbin
24	MOE	143	FTI	188	FTI	67	BIX-PAG	CS	Follow M52030, Milepost, 727, 706.6
720	SAC	52	MBO	35	MBO	35	MTZ-SUI	UP	For maritime traffic 2 Ships, Control Point, Vista
728	SAC	28	PTI	5	PTI	5	FFV-DAV	UP	Meet Amtk 743 West, Control Point, West DAV
732	SAC	Trn Cancelled							
733	SJC	18	CTI	9	CTI	9	GAC-SCC	UP	Meet Caltrain, 625, Control Point, Coast

Amtrak Endpoint OTP Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/31/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
734	SAC	66	PTI	20	TCR	15	SUI-SUI	UP	Legitimate wayside HBD or DED actuation C8031, 8032 axel 2 was the hottest using heat gun 103 on the fireman side and 102 on the engineer side Let mechanical know and will see what next detector says temple-stick rated for 210
738	SAC	48	DCS	47	DCS	15	DAV-SAC	UP	Restrictive signal(s) from unknown cause PTC PENALTY AT RV988 and RV989. Reinitialize to get into Sac., Red, Siding, RV988
742	SAC	42	TCR	40	TCR	20	MTZ-SUI	UP	HOT BOX DETECTOR failed. Stop to inspect. PTC held us to 30 mph to the next DET. C8312, Nothing found.
744	ARN	30	DCS	35	DCS	14	MTZ-SUI	UP	Wayside detector failure including false actuation Hotbox restricted to 30mph to next detector, Milepost, 45.0, 45.0
746	SAC	23	PTI	31	PTI	15	OKJ-OKJ	UP	Meet Held at OKJ station for 15 minutes for 747., AMT747, Other, okj station
747	SJC	49	ITI	18	ITI	18	SAC-SAC	UP	Service, turn, or wye train 534, AMT 534 arrived late into SAC turned around as AMT 747
748	SAC	46	DCS	34	MBO	29	MTZ-SUI	UP	For maritime traffic Control Point, rv034
51	CHI	278	FTI	238	FTI	139	IND-CRF	CS	Meet M641, Control Point, CP Hunt
502	SEA	21	FTI	19	FTI	19	PDX-VAN	BN	Meet Freight switching on main, bnsf 7073, Control Point, willbridge
511	PDX	30	TRS	38	TRS	38	TAC-XNI	ST	Vehicle on track ahead Held @ Prairie Jct waiting for clearance, Milepost, 10.39, 10.39
517	PDX	63	SVS	38	SVS	30	VAN-PDX	BN	Unplanned Wye Other, T6
59	NOL	38	FTI	52	PTI	30	MCB-HMD	CC	Meet AMTK 58, Milepost, 856.3, 856.3
8	CHI	158	FTI	254	FTI	60	LIB-WFH	BN	Meet bn7092, Control Point, rock creek
331	MKE	49	ENG	33	ENG	33	CHI-CHI	AM	Engine 40 was capped with 154. The move had to be made and a fair amount of snow and ice had to be removed from the front end of 40. 40
334	CHI	43	ENG	26	ENG	26	MKE-MKA	CP	Unrecoverable penalty (PCS) Engine 154 was added to the consist- starting getting braking faults on 4206. Pulled MU cable between 40 and 154 and it cleared the issue., 154
335	MKE	42	ITI	43	ITI	43	CHI-CHI	AM	Service, turn, or wye train 335
338	CHI	37	ITI	32	ITI	32	MKE-MKE	CP	Service, turn, or wye train 335

Amtrak Endpoint OTP Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/31/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
339	MKE	12	ITI	16	ITI	16	CHI-CHI	AM	Service, turn, or wye train 338
342	CHI	21	POL	21	POL	21	SVT-XRO	CP	Right of Way police hold Police activity held at MP 55.0
350	PNT	33	OTH	18	SYS	8	XB0-XA5	MI	PTC- IETMS Software Download
355	CHI	20	WTR	12	CAR	8	NLS-NLS	AM	Door ID4006, Stair issue
761	GTA	27	PTI	21	PTI	17	OXN-VEC	UP	Meet Amtk 774, Control Point, North Ventura
770	SAN	28	CTI	31	CTI	24	SNC-SNP	SC	Meet Metrolink, 1663, Control Point, serra
777	SLO	110	RTE	75	RTE	75	MPK-XMR	SC	Flagged cp las posas from metrolink Ventura sub onto the the UP main Flagged passed las posas but was getting a red hash box onto the UP. Both dispatchers said we needed to talk to the other dispatch, then eventually metrolink voided their authority to us and issued it to us the old fashion way and
790	SAN	51	PTI	81	PTI	56	CML-CML	UP	Meet 777 is dealing with signal issues in MPK, now it is flagging by Las Posas., 777, Control Point, co 415
704	BFD	No OS Rpt	POL	152	POL	117	SAC-SAC	UP	RR blocked by trespasser or vehicle strike by another train
718	BFD	1420	PTI	20	PTI	12	MOD-TRK	BN	Meet Shuffle, 717, Control Point, east denair
318	CHI	30	ENG	37	FTI	25	SMT-XTF	CC	Cross Traffic bnsf, Control Point, corwith

Amtrak Initial Terminal Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/31/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	674	01/31	1		
MIA	98	01/31	1	1	Passenger and/or baggage Numerous late passengers
NFK	158	01/31	27	27	Loading problem 330
PHL	144	01/31	46	46	Snow removal equipment working ahead, Control Point, ., Equipment shifted around a/c frozen doors.
PHL	150	01/31	43	43	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	151	01/31	29	29	Door, ENTIRE TRAINS, LATE OUT OF YARD DUE TO DOOR ISSUES OPENING AND CLOSING
PHL	611	01/31	1		
RNK	156	01/31	1		
SFA	52	01/31	6	6	Service, turn, or wye train 53
WAS	54	01/31	4	4	Air / Brake / Wheel, 82726, NOT WATERED
WAS	88	01/31	46	46	Air / Brake / Wheel, ALL, FROZEN EQUIPMENT
WAS	142	01/31	5	5	Water, commissary, toilet/trash dumping, TRAIN WAS NOT CLEANED, TRN WAS ORDERED OUT
WAS	146	01/31	80	40	Water, commissary, toilet/trash dumping, ALL TOILETS FULL, NEC'Y TO DUMP TRAIN AFTER WYING
WAS	146	01/31	80	40	Ice / snow on or under equipment, Control Point, WAS, FROZEN DOORS, UNABLE TO OPERATE DOORS, NEC'Y TO REMOVE ICE BUILD UP
ALB	68	01/31	132		
ALB	240	01/31	31	31	Late release from shop due to frozen equipment
BON	693	01/31	8	8	Service, turn, or wye train 692, Late arrival and wye train
BON	695	01/31	28	2	Power switch failure Other, crossover switch north of the draw
BON	695	01/31	28	26	Wye the train in Boston Other, BON
BON	697	01/31	86	86	Service, turn, or wye train 696, Late turn off of Amtrak 696
BOS	87	01/31	18	18	Planned set out / pick out of locomotives, cars or section of train, Late release from yard
BOS	99	01/31	33	33	Door, ALL CONSIST, Power door issues
BOS	135	01/31	14	13	Water, commissary, toilet/trash dumping, pipes being frozen in the restrooms
BOS	163	01/31	36	36	Planned set out / pick out of locomotives, cars or section of train, Engine shopped E/624
BOS	165	01/31	15	15	Water, commissary, toilet/trash dumping, AM165 dp BOS 15" late a/c being cleaned

Amtrak Initial Terminal Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/31/2026

Terminal	Train	Date	Late	Delay	Cause
BRK	692	01/31	11	11	Unplanned Wye Cab car 90214 PTC initialization failure, Control Point, Brunswick West
BRK	694	01/31	2	2	DTMF not working, called EB to give us the signal at Brunswick West Control Point, Brunswick West
BRK	696	01/31	50	50	Service, turn, or wye train 691, Late turn over from Amtrak 691
GFD	461	01/31	(Trn Cxld)		Equipment Issues
NHV	450	01/31	22	21	Hold for connecting train
NHV	450	01/31	22	5	Hold for connecting train
NHV	450	01/31	22	21	Hold for connecting train
NHV	450	01/31	22	5	Hold for connecting train
NHV	460	01/31	71	71	Planned set out / pick out of locomotives, cars or section of train, Late release from mechanical
NHV	464	01/31	83	83	Planned set out / pick out of locomotives, cars or section of train, delayed out of NHV due to frozen equipment
NHV	488	01/31	(Trn Cxld)		Equipment Issues
NYP	19	01/31	5	5	Passenger and/or baggage, HEAVY LOADING PER PSCC
NYP	49	01/31	50	50	Water, commissary, toilet/trash dumping
NYP	63	01/31	82	82	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	79	01/31	3	3	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	97	01/31	67	69	Water, commissary, toilet/trash dumping
NYP	103	01/31	16	17	Service, turn, or wye train, 144
NYP	107	01/31	22	22	Service, turn, or wye train, 106
NYP	159	01/31	20	20	Ice / snow on or under equipment, Other, SSYD DELAYED FROZEN DOORS
NYP	237	01/31	80	80	Service, turn, or wye train, 290
NYP	239	01/31	45	45	Service, turn, or wye train, 280
NYP	291	01/31	8	8	Service, turn, or wye train, 240
NYP	663	01/31	106	106	Undesired emergency application, 651, LATE F/SSYD A/C FAULTS ON ENG.651
NYP	667	01/31	11	11	Re-crew / job briefing, LATE ENGR
SPG	400	01/31	(Trn Cxld)		Equipment Issues
TWO	64	01/31	139		
CHI	7	01/31	153	153	Extremely cold weather Other, C U S

Amtrak Initial Terminal Details

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/31/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	48	01/31	244		
CHI	50	01/31	132	132	Service, turn, or wye train 51
CHI	331	01/31	33	33	Engine 40 was capped with 154. The move had to be made and a fair amount of snow and ice had to be removed from the front end of 40. 40
CHI	335	01/31	43	43	Service, turn, or wye train 335
CHI	339	01/31	16	16	Service, turn, or wye train 338
MKE	338	01/31	32	32	Service, turn, or wye train 335
STL	311	01/31	1	1	Wheelchair Came down late from station. Large wheelchair.
EMY	6	01/31	1		
GTA	782	01/31	2	2	Restrictive signal(s) from known wayside signal failure Wa for signal to time out., Stop, Control Point, South Ellwood
OKJ	718	01/31	5	5	Right of Way police hold
OKJ	720	01/31	1		
OKJ	732	01/31	(Trn Cxld)		Third Party Engine Failure
OKJ	742	01/31	1		
SAC	704	01/31	117	117	RR blocked by trespasser or vehicle strike by another train
SAC	723	01/31	9	6	Train seat spot on wrong track. Track 6 East.
SAC	723	01/31	9	3	Fuel Other, SAC Station
SAC	733	01/31	2	2	Restrictive signal(s) from unknown cause Restricting, Control Point, RV989
SAC	747	01/31	18	18	Service, turn, or wye train 534, AMT 534 arrived late into SAC turned around as AMT 747
SAN	769	01/31	2	2	Loading problem C2119
SJC	728	01/31	(Trn Cxld)		Third Party Engine Failure

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.3	98.9	94.8	149	1
CDOT	95.0	81.3	90.8	92.4	16	3
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	79.2	86	93.8	192	40
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 98(31) Rocky Mount, NC - Car Failure

01FEB26: Train 98(31) operating with engines 329, 38, and 193, with 10 coaches and 223 passengers, was delayed departing Rocky Mount, NC, on CSX North End subdivision, due to excessive ice build up on the brakes of the train. The conductors used the broomsticks on the train with the chisels on the end to break up the ice on the brake pads. Once the ice was removed and the brakes applied and released normally, train 98(31) was able to depart.

Train	Delay	Comment
98(31)	35"	

Train 98(31), 53(31) North and South of Florence, SC - Frozen Switches

01FEB26: Train 98(31) and train 53(31) were both delayed north of Florence, SC, on CSX South End subdivision, at milepost 286 due to frozen switches at milepost 286.5. CSX maintainers responded to clear the switches of snow and ice. Once the switches were cleared both trains were able to proceed.

Train 52(31) was delayed south of Florence, SC due to frozen switches at milepost 310.5. CSX maintainers were able to clear the ice and snow from the switches.

Train	Delay	Comment
98(31)	55"	
53(31)	1'56"	

Train 147(31) East of Roanoke, VA - Frozen Switch

01FEB26: Train 147(31) operating with engine 307, 8 coaches, and 26 passengers, was delayed 9 miles east of Roanoke, VA, on NS Blue Ridge subdivision, due to a frozen switch. NS switch maintainers responded to clear ice and snow from the switches. Once the ice and snow was removed, train 147(31) was able to proceed.

Train	Delay	Comment
147(31)	1'20"	

Train 146(31) Washington, DC - Servicing

31JAN26: Train 146(31) was delayed departing Washington, DC/MP136.0 on the Amtrak WT line due to late release from the yard. Train 146(31) equipment needed to be wye'd, have the restrooms dumped and the equipment was frozen. Train 146(31) departed Washington DC Union station at 545PM ET.

Train	Delay	Comment
146(31)	1'20"	

Train 237(31) New York, NY - Initial Terminal Delay

31JAN26: Train 237(31) was delayed departing New York Penn Station, NY/MP0.0 due to a short turn off train 290(37).

Train	Delay	Comment
237(31)	1'20"	

Train 98(31) North of Charleston, SC - Switch Failure.

31JAN26: Train 98(31) operating with engine 329, 38 and 193, 10 coaches, and 217 passengers was delayed 20 miles north of Charleston, SC, on CSX Charleston subdivision, due to a switch failure. CSX switch maintainers were on the scene working when train 98(31) arrived and was able to restore the switches function.

Train	Delay	Comment
98(31)	35"	

Train 63(31) East of Syracuse, NY - Freight Train Interference

31JAN26: Train 63(31) was delayed at MP270.8, 25.4 miles east of Syracuse, NY station on the CSX Syracuse subdivision following freight I019.

Train	Delay	Comment
63(31)	1'02"	

Train 48/448(30) Buffalo, NY - Freight Train Interference

31JAN26: Train 48/448(30) was delayed beginning at MP30.9, 42.8 miles west of Buffalo, NY station on the CSX Great Lakes subdivision following freight train I10430.

Train	Delay	Comment
48/448(30)	1'54"	

Train 140(31) New Haven, CT - Engine Failure

31JAN26: Train 140(31) operating with engine 657, 8 coaches and 107 passengers was delayed departing New Haven, CT, on MNCW New Haven Line, due to low water on original loco 657. As a result loco 657 was replaced with loco 98. This move took abnormally long due to major yard congestion. Due to the delay passengers were accommodated on local CT Rail trains. Once the congestion cleared and the loco was added, train 140(31) was able to proceed making all stops to Springfield, MA.

Train	Delay	Comment
140(31)	2'14"	

Train 163(31) Boston, MA - Servicing

31JAN26: Train 163(31) was delayed departing New York Penn Station, NY on the Amtrak NYP line due to a planned set out of engine 624 to be shopped for propulsion/dynamic brake issues. Engine 624 set out and replaced with engine 644.

Train	Delay	Comment
163(31)	36"	

Train 23(31) South of Gulfport, MS - Freight Train Interference

31JAN26: Train 23(31) was delayed at MP746.8, 7.43 miles south of Gulfport, MS station on the CSX N O and M subdivision holding in the siding to meet freight trains M520 and CSX4743. Once both freight trains cleared, 23(31) was on the move south.

Train	Delay	Comment
23(31)	1'46"	

Train 24(31) North of New Orleans, LA - Freight Train Interference

31JAN26: Train 24(31) was delayed beginning at MP766.5, 46.51 miles north of New Orleans, LA station on the N O and M subdivision following freight M52030. Train 24(31) followed M52030 all the way to Mobile, AL station.

Train	Delay	Comment
24(31)	3'08"	

Train 280(31) East of Buffalo, NY - Signal

31JAN26: Train 280(31) was delayed beginning at MP417.9, 21 miles east of Buffalo, NY station on the CSX Buffalo Terminal due to power switch failure at CP410. Maintainers responded and were able to line the switch. Trains 284(31) and freight M368 were also delayed behind the switch causing congestion once the switch was lined. Train 280(31) and 284(31) had to follow M368 until CP372 where the freight diverged to the West Shore subdivision.

Train	Delay	Comment
284(31)	26"	Switch
280(31)	3'20"	Switch
280(31)	34"	Follow M368
239(31)	45"	Late Turn 280(31)
284(31)	45"	Follow M368

Train 97(31) - Servicing

31JAN26: Train 97(31) was delayed departing New York Penn Station, NY on the Amtrak NYP line due to late release from the yard waiting on engine 600 from inbound 98(30).

Train	Delay	Comment
97(32)	1'09"	

Train 464(31) New Haven, CT - Servicing

31JAN26: Train 464(31) was delayed departing New Haven, CT station/MP72.3 on the MNRR New Haven Line due to frozen equipment.

Train	Delay	Comment
464(31)	1'23"	

Train 88(31) Washington, DC - Car Failure

31JAN26: Train 88(31) was delayed departing Washington, DC Union Station/MP136 due to frozen equipment.

Train	Delay	Comment
88(31)	46"	

Train 63(31) New York, NY - Servicing

31JAN26: Train 63(31) was delayed departing New York Penn Station, NY/MP0.0 due to a late release from mechanical in the yard.

Train	Delay	Comment
63(31)	1'22"	

Train 49(31) New York, NY - Servicing

31JAN26: Train 49(31) was delayed departing New York Penn Station, NY/MP0.0 due to watering, commissary, restroom pumping, and trash removal.

Train	Delay	Comment
49(31)	50"	

Train 99(31) South of Washington, DC - Trespasser Strike

31JAN26: Train 99(31) operating with engine 356, 9 coaches and 112 passengers went into emergency south of Washington, DC, at milepost 111.2 after striking a trespasser. This incident did not occur at a crossing and the weather was 16 degrees and cloudy. No injuries of crew or passengers reported, and no damage to equipment reported. Head End Power remained active the entire time. The crew requested relief. Local police and EMS responded to the scene as well as an Amtrak Road Foreman. APD was notified. The strike was reported non fatal.

Once police concluded their investigation and the trespasser was taken away by EMS, the crew agreed to take the train to Alexandria, VA to wait for a re-crew.

NRC# 1453839

National Response Center Number: 1453839

Train	Delay	Comment
99(31)	1'29"	Trespasser strike
99(31)	1'20"	Hold ALX for Re-Crew

Train 19(30) North of Meridian, MS - Passenger Train Interference

31JAN26: Train 19(30) was delayed at MP230.0, 65 miles north of Meridian, MS station on the Norfolk Southern AGS South division due to a meet with train 20(31). Once train 20(31) proceeded north, train 19(30) was back on the move south into Meridian, MS station.

Train	Delay	Comment
19(30)	41"	

Train 280(31) East of Buffalo, NY - Signal

31JAN26: Train 280(31) was delayed 3'20" at MP415.3 east of Buffalo, NY on the CSX Buffalo Terminal Subdivision due to a power switch failure. Train was also behind an unknown freight unit that was attempting to throw the switch due to it being frozen. A maintainer was dispatched and once the switch was lined, Train 280(31) was able to proceed following the freight from MP410 to MP382 further delaying the train.

Train	Delay	Comment
280(31)	3'20"	
280(31)	34"	Following freight

Train 74(31) East of Salisbury, NC - Vehicle on Tracks

31JAN26: Train 74(31) was delayed 14 miles east of Salisbury, NC at Maybelle/MP319.4 on the NSRR Montview-Salisbury Subdivision due to a vehicle on the tracks at MP317.9. Once the vehicle was removed and tracks inspected, Train 74(31) was able to proceed.

Train	Delay	Comment
74(31)	1'31"	

Train 691(31) North of Woburn, MA - Signal

31JAN26: Train 691(31) was delayed starting 9 miles north of Woburn, MA/MP12.7, on the MBTA Portland Subdivision, due to power switch failure at CPF Vale/MP104.3 and CPF FR/MP99.2. Train 692(31) was also delayed through the area.

Train 696(31) was delayed departing Brunswick, ME/MP0.8, on the Maine DOT Brunswick Branch, due to a late turn of Train 691(31) that arrived at 1:27PM, 1 hour and 17 minutes late.

Train	Delay	Comment
691(31)	35"	
696(31)	50"	ITD BRK
692(31)	11"	
696(31)	55"	CP Vale
697(31)	1'26"	Late Turn 696(31)

Train 64(31) Toronto, ON - Initial Terminal Delay

01FEB26: Train 64(31) was delayed at MP7.1, Toronto ON station/MP7.1 on the GOT Oakville subdivision due to a broken bell on engine 104. Mechanical responded and repaired the bell on engine 104. Train 64(31) departed Toronto, ON. station at 1039AM ET.

Train	Delay	Comment
64(31)	2'19"	
68(31)	2'12"	

Multiple Initial Terminal Delays - Philadelphia, PA - Servicing

31JAN26: There were multiple initial terminal delays at Philadelphia due to frigid temperatures account of a weather event causing late release from the yard due to servicing and frozen equipment.

Train	Delay	Comment
150(31)	43"	
144(31)	46"	
151(31)	29"	

Lake Shore Limited Service Adjustments - Shopped Equipment

31JAN26: Due to shopped equipment, the following service adjustments were necessary as follows:

Train 449(01) originated at Albany, NY, cancelled between Boston, MA and Albany, NY, with alt bus transportation provided BOS-ALB.

Train 448(02) terminated at Albany, NY, cancelled between Albany, NY and Boston MA, with alt bus transportation provided.

Acela Cancellations - Shopped Equipment

30JAN26: Due to multiple Acela trainsets shopped due to wheel wear, cab signal issues and a current high shop count, causing shop congestion with limited material, multiple Acela trains were canceled until shop counts improve.

-Acela Trains 2153, 2155, 2192, 2167, 2150, 2171, 2107, 2192, 2108, 2121, 2150, 2168, 2170, 2122, 2126(30) were canceled in entirety.

-Acela Trains 2249, 2255, 2252, 2201, 2218(31) were canceled in entirety.

-Acela Trains 2292, 2257, 2256, 2295, 2252, 2207, 2222(01) were canceled in entirety.

Empire Cancellations High Shop Counts - Engine Failure

30JAN26: The following service adjustments are in affect due to high shop counts in Albany-Rensselaer, NY.

Cancelled In Entirety

236-238-244-233-235(31, 01, 02)

245(31, 01)

243(02)

69(31, 01, 02) - TERM ALB; cancelled ALB - MTR - No ALT transportation

68(31, 01, 02, 03) - ORIG ALB; cancelled MTR-ALB - No ALT transportation

Winter Storm Gloria Cancellations

29JAN26: Due to Winter Storm Gloria the following adjustments are in the place:
26-FOI-00297 00000005672 UNCLASSIFIED 2/9/2026
Floridian Service:

- Train 41(30) is cancelled entirely with no alternate between Chicago and Miami.
- Train 40(30) is cancelled entirely with no alternate between Miami and Chicago.
- Train 41(31) will originate at Jacksonville, FL to operate to Miami. No alternate between Chicago and Jacksonville.
- Train 40(31) will terminate at Jacksonville, FL with no alternate between Jacksonville and Chicago.

Palmetto:

- Train 89, 90 (31) cancelled in their entirety, no alternate transportation

Virginia Service

- Train 65(30) will terminate at Richmond-Staples Mill, VA, cancelled between Richmond-Staples Mill and Newport News, VA, no alternate transportation *Equipment will represent Train 124(31)*
- Train 99(31) will terminate in Richmond-Staples Mill, VA, cancelled Richmond-Staples Mill, VA and Newport News, VA, no alternate transportation *Equipment will represent Train 164(01)*
- Train 87(31) will terminate in Washington, DC, cancelled Washington to Norfolk, VA, no alternate transportation *Equipment will represent Train 128(31)*
- Train 124(31) will originate in Richmond-Staples Mill, VA, cancelled Newport News, VA to Richmond-Staples Mill, VA, no alternate transportation.
- Train 128(31) will originate in Washington, DC, cancelled Norfolk, VA to Washington, no alternate transportation.

- Trains 71, 72, 77, 78 (31) cancelled in their entirety

February 1st Cancellations

Carolinian

- Trains 79, 80 (01) cancelled in their entirety, no alternate transportation

Piedmont

- Trains 71, 72, 75, 76 (01) cancelled in their entirety

Virginia Service

- Train 164(01) will originate in Richmond-Staples Mill, VA, canceled Newport News, VA to Richmond-Staples Mill, VA, no alternate transportation.

WBS#: B.TR.100150.6446

10OCT25: To accommodate the above outlined infrastructure work, Amtrak's Crescent Service will be adjusted as follows:

- Train 19 (5Jan-7Jan, 11Jan-14Jan, 18Jan-21Jan, 25Jan-28Jan, 1Feb-4Feb, 8Feb-11Feb, 16Feb-18Feb, 22Feb-25Feb, 1Mar-4Mar), which normally operates between NYP and NOL, will terminate at ATL.
- Train 20 (6Jan-8Jan, 12Jan-15Jan, 19Jan-22Jan, 26Jan-29Jan, 2Feb-5Feb, 9Feb-12Feb, 17Feb-19Feb, 23Feb-26Feb, 2Mar-5Mar), which normally operates between NOL and NYP, will originate at ATL.

ALTERNATE TRANSPORTATION:

- Local Bus 3119 will provide alternate transportation between ATL and NOL, making all scheduled station stops.
- Express Bus 3019 will provide alternate transportation from ATL to NOL only.
- Local Bus 3120 will provide alternate transportation between NOL and ATL, making all scheduled station stops.
- Express Bus 3020 will provide alternate transportation from NOL to ATL only.

Weekly Friday through Sunday (This INCLUDES Monday February 16th) - No Track Work Scheduled:

- Trains 19 & 20 will operate normal schedule and route between Atlanta and New Orleans.
- Trains may incur delays of 20-30 minutes operating through the track work area, due to residual slow orders and congestion.

WBS#: B.TR.100150.6165

Long Bridge Replacement Outage - Scheduled M/W Work

18DEC25: Starting January 12, 2026 CSX Long Bridge replacement trackwork will commence causing reduced service and schedule changes through March 08, 2026 as follows:

January 11th will commence transition plan with 195 terminating New York and 153 terminating Washington D.C.

Monday through Friday: 114 cancelled, 133 cancelled, 141 terminates Washington D.C., 85 terminates Washington D.C., 176 originates Washington D.C., 174 originates Washington D.C., 84 originates Washington D.C., 134 originates Washington D.C., 86 originates Newport News, VA, 178 originates Roanoke, VA.

New trains operating Monday through Friday : 113 originating New York, NY and 198 originating Washington D.C.

Saturday: 167 terminates Philadelphia, PA, 153 terminates Washington D.C., 195 terminates Washington D.C., 155 operates through to Norfolk, VA, 164 originates Newport News, VA, 194 originates Washington D.C., 128 originates Norfolk, VA, 88 originates Washington D.C., 82 originates Washington D.C.

New train operating Saturday: 109 originates New York, NY

Sunday: 106 cancelled, 107 cancelled, 157 terminates Washington D.C., 155 operates through to Norfolk, VA, 195 terminates Washington D.C., 128 originates Norfolk, VA, 96 originates Washington D.C., 88 originates Washington D.C.

New trains operating Sunday: 117 originates Philadelphia, PA, 100 originates Washington D.C.

WBS#: B.TR.100150.6327

Eastern Region

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 22(31) North of Mineola, TX - Freight Train Interference

01FEB26: Train 22(31) operating with E/56, 6 cars and 75 passengers onboard, was delayed following UP freight train UP9045 from MP 132 to MP 89 on UP Mineola Subdivision.

Train	Delay	Comment
22(31)	43"	

Train 50(31) Chicago, IL - Servicing

31JAN26: Train 50(31) operating with E/339, 5 cars and 83 passengers onboard with a scheduled departure of 555P-CT, was delayed departing Chicago on Amtrak Chicago South Subdivision due to a late turn of inbound equipment of Train 51(30) with E/339, E/25 and 5 cars which arrived at 303P-CT, 4 hours and 38 minutes late. The train went out to the yard and set out non-compliant E/25. The train was sent for servicing with coach C/25091 and sleeper C/62515 having toilet issues. Mechanical was able to repair the sleeper C/62515, but not the ADA restroom in the coach C/25091. They were released and shoved to the station. Due to bad order C/25091, it created an over capacity of 12 passengers. Passengers were reaccommodated throughout the train, utilizing open sleeper space and the lounge car for seating. With one operating restroom in the C/25091, passengers were given the option to sit in that car for their travel. Once the train was loaded, Train 50(31) departed Chicago at 807P-CT.

Train	Delay	Comment
50(31)	2'12"	

Train 48/448(31) Chicago, IL - Servicing

31JAN26: Train 48/448(31) operating with E/153, E/93, 13 cars and 113 passengers onboard with a scheduled 930P-CT, was delayed departing Chicago, IL on Amtrak Chicago South Subdivision due to the servicing of late inbound equipment off Train 49/449(30). Train 49/449(30) arrived into Chicago at 1245p-CT with E/93 and E/97 which needed to be thawed. E/97 was replaced with E/153 which produced a late release from the diesel pit. Train was serviced and inspected in the yard, then moved to the station for final inspection and passenger loading. Train 48/448(31) departing Chicago at 134A-ct.

Train 511(31) Tacoma, WA - Trespasser Incident

31JAN26: Train 511(31) operating with E/90252, 3 cars, E/WDTX 1403 and 100 passengers onboard, was delayed at MP 8.9 approximately 8 miles south of Tacoma, WA due to ahead at MP 10. Once car was removed Train 511(31) was able to proceed south.

Train	Delay	Comment
511(31)	38"	

Train 704(31) Sacramento, CA - Freight Train Interference

31JAN26: Train 704(31) departed the terminal of Sacramento, CA (SAC) on the Union Pacific Railway Martinez Subdivision. A freight train, MWCRVB-30 (UPRR/6507), was involved in a trespasser incident. Tracks were closed while local authorities responded to and investigated the incident. With the extended delays, passengers were accommodated on bus 3718(31) SAC-LOD-SKN to meet train 718(31) for travel to Bakersfield. Downline passengers between SKN and BFD were also accommodated on train 718(31). Once the scene was released, train 704(31) was able to proceed.

Train	Delay	Comment
704(31)	2'12"	

Train 777(31) Moorpark, CA - Signal

31JAN26: Train 777(31) was delayed north of Moorpark, CA (MPK) at CP Los Posas on the Union Pacific Railway Santa Barbara Subdivision. There was a problem with the signal system at CP Los Posas which required the train crew to obtain verbal authority from both the Metrolink Ventura Sub dispatcher and the Union Pacific Dispatcher and then operate at reduced speeds to Camarillo, CA (CML).

Train	Delay	Comment
777(31)	1'35"	
794(31)	18"	bad meet at Seacliff with late 777
790(31)	1'31"	

Train 3(30) East of Gallup, NM - Engine Failure

31JAN26: Train 3(30) operating with E/203, E/15, E321, 6 cars and 106 passengers onboard, stopped on BNSF Gallup Subdivision at MP 150 approximately 7 miles east of Gallup, NM hit a rough switch and their main reservoir hose disconnected between E/15 and Charger E/321. They were able to reconnect, restore air, but had issues with the hand break not releasing. BN reached out to carmen in Gallup for assistance. Break released and they were on the move west.

Train 3(30) with 100 passengers onboard, stopped at MP 264, on BNSF Gallup Subdivision approximately 10 miles east of Winslow, AZ lost both BP and main reservoir hoses between E/15 and Charger E/321 after going over a crossing. BN had responders sent out to the train and they were able to make repairs and the train was back on the move. A pilot crew was called out of Needles on duty at 1201A-PT with a dog catch crew out of Kingman that will sign-up at 119A-PT and meet up with the train.

Train	Delay	Comment
3(30)	1'40"	XIA - GLP / MP 150
3(30)	1'01"	GLP - WLO / MP 264

Train 517(31) Vancouver, BC - Wye Train

31JAN26: Train 517(31) was delayed south of Vancouver, WA (VAN) at CP T6 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. Account an issue with cab car CC/7911, the crew was instructed to operate the train around the wye track on the approach to Portland, OR (PDX) to minimize servicing delays for outbound train 506(31).

Train	Delay	Comment
517(31)	30"	

Train 777(31) Anaheim, CA - Police Related

31JAN26: Train 777(31) ~~26-FOI-00297 doc0009005872~~ at A "UNCLASSIFIED" CA (2/9/2026) on the Southern California Regional Rail Authority Orange Subdivision. Local Fire officials had requested all train traffic halted while attending to an incident on or near the track ahead. Once the track was released by the fire department, train 777(31) was able to proceed, departing ANA at 3:02 PM-PT.

Train	Delay	Comment
777(31)	49"	

Train 21(30) South of Cleburne, TX - Car Failure

31JAN26: Train 21(30), E/63-8 Cars, stopped 23 miles south of Cleburne, TX/MP317.5, on the BNSF Fort Worth Subdivision, at MP294.5 to inspect sleeper car 32028. The car set off a wayside detector located at MP301.1 for a Level 1 warm bearing alarm. The crew inspected and took no exceptions. BNSF authorized Train 21(30) to continue south and would monitor as they operated by wayside detectors.

Train	Delay	Comment
21(30)	35"	

Train 59(30) North of Hammond, LA - Passenger Train Interference

31JAN26: Train 59(30) held 2.8 miles north of Hammond, LA/MP859.1, on the CNRR McComb Subdivision, at Natalbany/MP856.3 meeting Train 58(31).

Train	Delay	Comment
59(30)	30"	

Train 728(31) San Jose, CA - Third Party Contractor Engine Failure

31JAN26: Train 728(31) was delayed departing the initial terminal of San Jose, CA (SJC) on the Union Pacific Railway Coast Subdivision. There was a defect (condemnable flat spot) found on locomotive CDTX/2123 in San Jose. As a result the following operating recovery plan was enacted:

- 728(31) Originate from Oakland, CA (OKJ) - no alternate transportation - passengers fare protected and able to self-modify reservations.
- 732(31) Cancelled - no alternate transportation - passengers fare protected and able to self-modify reservations.
- 749(31) Cancelled - no alternate transportation - passengers fare protected and able to self-modify reservations.
- Once cleared by technicians (QMP) from the mechanical department, original 728(31) equipment was able to operated deadhead to Oakland, CA for repairs with a max speed of 50MPH.

Train	Delay	Comment
728(31)	39"	Depart OKJ late after equipment swap
728(31)	Originate OKJ	no alternate transportation
732(31)	Cancelled	no alternate transportation
749(31)	Cancelled	no alternate transportation

Train 8/28(30) East of Shelby, MT - Freight Train Interference

31JAN26: Train 8/28(30) was delayed starting 94.7 miles east of Shelby, MT/MP1065.7, on the BNSF Hi Line and Milk River Subdivision, following BNSF 3904 from Burnham/MP971.0 to Havre, MT/MP430.3.

Train	Delay	Comment
8/28(30)	41"	

Train 7/27(31) Chicago, IL - Engine / Car Failure

31JAN26: Train 7/27(31) was delayed departing Chicago, IL after coach car 34101 was late bad ordered for freeze damage and replaced with car 34135. After bad ordering the car, engine 301 was bad ordered for a frozen sandbox and replaced with engine 312.

Train	Delay	Comment
7/27(31)	2'33"	

Train 720(31) Martinez, CA - Drawbridge Opening

31JAN26: Train 720(31) was delayed east of Martinez, CA (MTZ) at CP RV033 on the Union Pacific Railway Martinez Subdivision. The movable lift span of the Suisun Bay Bridge was raised to allow the safe passage of maritime traffic. Once the traffic was clear and the lift span lowered into position, train 720(31) was able to proceed.

Additional trains were delayed throughout the day for the Suisun Bay Bridge from separate lift incidents.

Train	Delay	Comment
720(31)	35"	
6(31)	29"	
734(21)	13"	Separate Bridge Lift

Train 331(31) Chicago, IL - Engine Failure

31JAN26: Train 331(31) was delayed departing Chicago, IL, due to capping off E/40, which was unable to maintain cab temperature, with E/154. Addition delay incurred thawing frozen electrical and multiple unit (M/U) plugs on the front of E/40 before capping. Train 331(31) departed Chicago at 8:58AM-CT, operating 33 minutes late.

Train 334(31), E/ID4602-5 Cars-E/40-E/154, stopped 1.9 miles east of Milwaukee, WI/MP85.4, on the CP RR C&M Subdivision, at MP83.5 due to multiple engine faults with ID4602 related to engine 154. The multiple unit cable between engine 40 and engine 154 was pulled which resolved the issue. Once complete, Train 334(31) continued to Chicago.

Train 335(31) was delayed departing Chicago, IL due to a late turn of equipment and updating equipment paperwork. Train 334(31) arrived to Chicago at 1:12PM, 43 minutes late. Due to needing to replace and engine ditch light and look at the M/U fault, it was decided to update the locomotives while the train was flagged in. Once competed, mechanical cleared the train at 1:45PM-CT. Train 335(31) departed Chicago at 1:48PM, operating 43 minutes late.

Train 338(31) was delayed departing Milwaukee, WI due to a late turn of Train 335(31)'s equipment that arrived at 3:16PM, 42 minutes late.

Train 339(31) was delayed departing Chicago, IL due to a late turn of Train 338(31)'s equipment that arrived at 5:06PM, 37 minutes late.

Train	Delay	Comment
331(31)	33"	
334(31)	28"	
335(31)	43"	ITD CHI
338(31)	32"	ITD MKE
339(31)	16"	ITD CHI

Train 7/27(30) West of Devils Lake, ND - Broken Rail

31JAN26: Train 7/27(30) was delayed starting 33.6 miles west of Devils Lake, ND/MP85.1, on the BNSF Devils Lake Subdivision, due to a red signal at West Leeds/MP115.9. The crew reported being talked passed the red signal and then proceeded at restricted speed to the broken rail found at MP128.2. Maintenance of Way was onsite to walk the train over. At MP131.0, a clear signal was established, and Train 7/27(30) was able to resume track speed.

Train	Delay	Comment
7/27(30)	48"	

Train 49/449(30) West of Erie, PA - Freight Train Interference

31JAN26: Train 49/449(30) was delayed starting 33.6 miles west of Erie, PA/MP86.9, on the CSX Erie West Subdivision, between MP148 and the South Yard/MP174.4 following CSX I-00730. At the South Yard, Train 49/449(30) stopped to fuel lead engine 93 after it was unable to be fueled in Albany. Additional delay incurred west of Cleveland, OH, on the NSRR Chicago Line, following NS 16N from Max/MP190.7 to CP197/MP197.8.

Train	Delay	Comment
49/449(30)	44"	Follow I-00730
49/449(30)	20"	Fuel
49/449(30)	36"	Follow 16N

Train 51(30) West of Indianapolis, IN - Freight Train Interference

31JAN26: Train 51(30) was delayed 9.5 miles west of Indianapolis, IN/MP0.0, on the CSX Indianapolis Terminal Subdivision, at North Hunt/MP9.5 from freight interference. CSX M332 was disabled in the CSX yard with air issues blocking CSX M641 from clearing off the main line. Once CSX M332 recovered, CSX M641 was able to finish clearing in the yard. Once this was complete, Train 51(30) was back on the move west. Additional delay was incurred 3.1 miles north of Dyer, IN/MP27.9, on the UPRR Villa Grove Subdivision, at 162nd St/MP19.8 meeting a Union Pacific freight train.

Train	Delay	Comment
51(30)	2'19"	CP Hunt
51(30)	40"	162nd St

Train 4(30) East of Needles, CA - Freight Train Interference

31JAN26: Train 4(30) was delayed starting 38.5 miles east of Needles, CA/MP578.0, on the BNSF Seligman Subdivision, between Yucca/MP539.5 and Kingman, AZ/MP516.3 following a BNSF freight train.

Train	Delay	Comment
4(30)	30"	

Train 8/28(29) East of Glasgow, MT - Freight Train Interference

31JAN26: Train 8/28(29) delayed 51 minutes at start of Glasgow, MT/MP277.5, on the BNSF Glasgow Subdivision, at Nashau/MP262.2 meeting BNSF 8220 and at Kintyre/MP251.4 meeting BNSF 6023. Additional delay following BNSF 7386 from Kintyre to Poplar/MP205.3. Train 8/28(29) continued for 26.5 miles before stopping again at Blair/MP178.8 to meet BNSF 8150 and BNSF 9041. As a result of all of the freight delays, Train 8/28(29) had to hold 23.1 miles west of Minot, ND/MP203.3X at the East Crosby Junction/MP23.1 for the recrew and pilots to van out from Minot. Once the recrew was onboard and job briefing complete, Train 8/28(29) continued east.

Train	Delay	Comment
8/28(29)	51"	Follow BNSF 7386
8/28(29)	15"	Nashau/Kintyre Meet
8/28(29)	15"	Blair Meet
8/28(29)	43"	Hold For Recrew

Chicago Delays / Cancellations - Frozen Equipment

28JAN26: Multiple trains were delayed or cancelled in Chicago, IL as a result of frozen equipment and late releases from mechanical.

29JAN26: Due to extreme weather, cancellations are now extended on the Midwest Corridor State supported trains through 01FEB.

31JAN26: Pere Marquette Service has been restored reinstating Train 370(31) and Train 371(01) to run live as a train.

DELAYS:

-Train 329(28), E/139-3 Cars-E/ID4618, departed Chicago, IL 1 hour and 54 minutes late account frozen equipment and traction motor issues. Once the equipment was thawed, additional delay was incurred due to traction motor issues with engine 139. Chicago Mechanical responded to the train and was able to resolve the issue.

-Train 301(28), E/ID4613-5 Cars, departed Chicago, IL 2 hours and 37 minutes late as a result of frozen equipment. Mechanical was able to get all cars except business class car ID4210 to thaw for service. The business class car ID4210 deadheaded in line which resulted in 21 business class passengers downgraded to coach. Additional delay holding in the station for commissary to stock the train.

-Train 3(28) E/199, E/55, and 6 cars departed Chicago, IL 1 hour and 28 minutes late account of the late release of E/55 that needed to be thawed in the diesel pit.

-Train 5(28) E/76, E/194, and 8 cars departed Chicago, IL 1 hour and 38 minutes late account of replacing bad order diner car 38061 for refrigeration issues. It was necessary to switch Train 7/28(28) first and complete the drain and blow on the bad order car. Diner car 38061 was replaced with diner-lounge car 37009.

-Train 7/27(28) E/58, E/343, E/340 and 9 cars departed Chicago, IL 2 hours and 34 minutes late account of weather issues. Train 7/27(28) was made up with a replacement diner, coach and sleeper. Once released, and after two engines were wyed, it was necessary for the pit to complete the daily inspection on E/343. the consist was watered and it was reported that they did not have a working dishwasher would would needed stock from the commissary to accommodate.

Train 41(28) E/48, E/163 and 10 cars departed Chicago, IL 3 hours and 15 minutes late as a result replacing an ogontz valve in sleeping car 62034, thawing frozen toilets in sleeping car 62044 and sleeping car 62503 was bad ordered due to a busted pipe and freeze damage. With no sleeping car replacement, 22 passengers were downgraded to coach seating. Train 41(28) used E/48 and E/163 off Train 6(26) which arrived at 214P-CT and had to be serviced.

CANCELLATIONS:

Wolverine:

-Train 352(28JAN) cancelled with two alternate buses secured.

-Trains 350-351-352-354-355(28JAN) cancelled with alternate buses secured

Blue Water:

- Train 364(28JAN-31FEB) cancelled - sourcing alternate transportation.
- Train 365(29JAN-01FEB) cancelled - sourcing alternate transportation.

Pere Marquette ***31JAN: Services have been restored reinstating Train 370(31) and Train 371(01) to run live as a train**

- Train 370(28JAN-30JAN) cancelled - sourcing alternate transportation.
- Train 371(29JAN-31JAN) cancelled - sourcing alternate transportation.

Lincoln Service

- Train 300(29JAN-02FEB) cancelled - sourcing alternate transportation.
- Train 302(29JAN-02FEB) cancelled - sourcing alternate transportation.
- Train 305(28JAN-01FEB) cancelled - sourcing alternate transportation.
- Train 307(28JAN-01FEB) cancelled - sourcing alternate transportation.

Illinois Zephyr

- Train 383(28JAN-01FEB) cancelled - sourcing alternate transportation.
- Train 380(29JAN-01FEB) cancelled - sourcing alternate transportation.

WBS#: B.TR.100150.6442

Train	Delay	Comment
301(28)	2'21"	ITD CHI
329(28)	1'54"	ITD CHI
3(28)	1'28"	ITD CHI
5(28)	1'38"	ITD CHI
7/27(28)	2'34"	ITD CHI
41(28)	3'15"	ITD

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

-Train 535(29) Cancelled - No alternate transportation.
-Train 551(29-30) Cancelled - No alternate transportation. 26-FOI-00297 Requester's name is UNCLASSIFIED. Document 2/9/2026A to Oakland, CA.

31DCE25

-Train 520(31) Cancelled - No alternate transportation.
-Train 534(31) Cancelled - No alternate transportation.
-Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

-Train 736(01-04) Cancelled - No alternate transportation.
-Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-06MAR) Cancelled - No alternate transportation.
- TRAIN 713(06JAN-07MAR) Cancelled - No alternate transportation.

10JAN26 - 11JAN26

-Train 736(10-11) Cancelled - No alternate transportation.
-Train 737(10-11) Cancelled - No alternate transportation.

12JAN26 - 13JAN26

-Train 520(12-13) Cancelled - No alternate transportation.
-Train 534(12-13) Cancelled - No alternate transportation.
-Train 535(12-13) Cancelled - No alternate transportation.

14JAN26:

-Train 520(14) Cancelled - No alternate transportation.
-Train 537(14) Cancelled - No alternate transportation.
-Train 534(14) Cancelled - No alternate transportation.

15JAN26:

-Train 520(15-16) Cancelled - No Alternate Transport offered
-Train 534(15-16) Cancelled - No Alternate Transport offered
-Train 535(16) Cancelled - No Alternate Transport offered
-Train 537(15) Cancelled - No Alternate Transport offered

17JAN26:

-Train 718(17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744(17) OKJ-EMY.

21JAN26:

-Train 526(21) Cancelled - No Alternate Transport offered
-Train 534(21) Cancelled - No Alternate Transport offered
-Train 535(21) Cancelled - No Alternate Transport offered

23JAN26:

-Train 520(23) Cancelled - No Alternate Transport offered
-Train 534(23) Cancelled - No Alternate Transport offered
-Train 535(23) Cancelled - No Alternate Transport offered
-Train 736(23JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 737(23JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 520(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 526(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 534(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 531(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 537(26JAN-01MAR) Cancelled - No Alternate Transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
-------	-------	---------

718 (21)	Originate	Passengers to 744 (21)	OKJ-EMY
	EMY		
718 (22)	26-FOI-00297	00000005672	"UNCLASSIFIED" 2/9/2026
	Originate	Passengers to 744 (22)	OKJ-EMY
	EMY		
714 (22)	1'07"	ITD - OKJ - Late change of equipment	
718 (21)	37"	ITD - EMY	
716 (22)	20"		
718 (22)	3'10"	ITD - EMY	
714 (23)	.	CANCELLED	
713 (24)	.	CANCELLED	
535 (24)	Cancelled		
520 (24)	Cancelled		
534 (24)	Cancelled		
736 (25-28)	Cancelled		
737 (25-28)	Cancelled		
749 (28)	Cancelled	Balance Fleet to Protect Morning Service -	
		Passengers to 751 (28)	
551 (29-30)	Cancelled	Replacement Bus SAC-OKJ	
520 (29-31)	Cancelled	No alternate transportation.	
534 (29-31)	Cancelled	No alternate transportation.	
736 (01JAN-04JAN))	Cancelled	No alternate transportation	
737 (01JAN-04JAN)	Cancelled	No alternate transportation	
535 (29)	Cancelled	No alternate transportation.	
537 (30-31)	Cancelled	No Alternate Transportation	
713 (06JAN-07MAR)	CANCELLED	No Alternate Transport Offered	
714 (05JAN-06MAR)	CANCELLED	No Alternate Transport Offered	
736 (10-11JAN)	Cancelled	No Alternate Transport Offered	
737 (10-11JAN)	Cancelled	No Alternate Transport Offered	
520 (12-13-14- 15-16 JAN)	Cancelled	No alternate transportation	
534 (12-13-14-15-16 JAN)	Cancelled	No alternate transportation	
535 (12-13-16JAN)	Cancelled	No alternate transportation	
537 (14-15JAN)	Cancelled	No Alternate Transport offered	
718 (17)	Originate	Pax to 744 OKJ-EMY	
	EMY		
718 (17)	35"		
526 (21Jan)	Cancelled	No alternate transportation	
534 (21-23JAN)	Cancelled	No alternate transportation	
535 (21-23JAN)	Cancelled	No alternate transportation	
520 (23JAN)	Cancelled	No Alternate Transport Offered	
736/737 (23JAN-01MAR)	Cancelled	No Alternate Transportation	
520/526/534/531/537 (26JAN-01MAR)	Cancelled	No Alternate Transportation	

Western Region

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
8 (15)	SCD	369		Shelled wheels
5 (2)	GSC	51		Strike damage
300 (26)	BNL	ID4633		Poss locked axle//return CHI 966 (31)

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (30)	LNK	BNSF9100	Significant coolant leak	EMY	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 587(27) Passenger Removal at Fullerton, California – Fare Evader

31Jan26, Passenger on PNR 6ED1D0, traveling from San Juan Capistrano, CA to Las Angeles, CA was reportedly asked attempted to travel without a valid ticket and was asked to detrain at Fullerton, CA without incident were the passenger brought a ticket. Amtrak Police notified.

Delay: 587 (31) 2"

Consist Deviations

26-FOI-00297

00000005672

"UNCLASSIFIED"

2/9/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2259 (31)	BOS	LEGACY ACELA IN LIEU OF NEXT GENERATION ACELA	n/a	0	
449 (31)	BOS	coach in lieu of sleeper to 49			82560
350 (31)	CHI	Extra car DH inline OKM.	N/A	0	ID4001
448 (01)	CHI	4820 Sleeper on 448(01) will operate live CHI-ALB. but since it's in the NY-section, sleeper pax travelling ALB-BOS will need to be downgraded. 448(01) also using AMI coach and club dinette.	Passengers downgraded partially coach ALB-BOS	7	82560
6 (31)	EMY	sleeper in lieu of crew dorm-trans sleeper	Passengers reaccommodated to like rooms.	5	32038
790 (31)	GTA	NO BIKE SALES	A.C.N. NOTIFICATIONS COMPLETED	6	90215
664 (31)	HAR	SHORT ONE COACH, OVER CAP BY 25	notificaions sent over cap	32	
586 (31)	LAX	No bike space, customer service notified.	n/a	0	90225
566 (31)	LAX	No bike space, customer service notified.	PASSENGERS NOTIFIED	2	90225
2205 (31)	NYP	LEGACY ACELA IN LIEU OF NEXT GENERATION ACELA	N/A	0	
97 (31)	NYP	(9712) Viewliner I in lieu of Viewliner II sleeper	N/A	0	62031
97 (31)	NYP	Diner only, no lounge due to turning off of 48 & winter storm.	n/a	0	NOCAR
654 (30)	PHL	OVER CAP DUE SHORT EQUIPMENT	over capacity starting at PHL	37	
355 (31)	PNT	Extra car DH inline OKM.	N/A	0	ID4001
769 (31)	SAN	NO BIKE SALES	A.C.N. NOTIFICATION DONE	4	90215
579 (31)	SAN	No bike space, customer service notified.	PASSENGERS NOTIFIED	2	90225
157 (01)	SPG	SHORT ONE COACH, OVER CAP BY 39			

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2250 (31)	WAS	LEGACY ACELA IN LIEU OF NEXT GENERATION ACELA	N/A	0	
2216 (31)	WAS	LEGACY ACELA IN LIEU OF NEXT GENERATION ACELA	WAR REPORT reviewed and completed.	227	
100 (31)	WAS	SHORT ONE COACH DUE EQUIP SWAP			

Reverse Consists

Train Number	Station	Reason
195 (31)	BOS	Consist reversed Business class seat orientation may have changed At Front
109 (31)	NYP	Consist reversed Business class seat orientation may have changed At Front
101 (31)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (31)	NYP	Consist reversed Business class seat orientation may have changed At Front
150 (31)	PHL	Consist reversed Business class seat orientation may have changed At Front
144 (31)	PHL	Consist reversed Business class seat orientation may have changed At Rear
156 (01)	WAS	Consist reversed Business class seat orientation may have changed At Front
103 (31)	NYP	Consist reversed Business class seat orientation may have changed At Front
106 (31)	WAS	Consist reversed Business class seat orientation may have changed At Rear
107 (31)	NYP	Consist reversed Business class seat orientation may have changed At Front