

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, February 02, 2026

Rules: 0-13



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 02/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 02/01/2026			ITP February 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	247	70	71.7%	247	70	71.7%	36,307	5,161	85.8%
Central Division	85.5%	55	7	87.3%	55	7	87.3%	8,121	940	88.4%
Northeast Division	80.0%	76	34	55.3%	76	34	55.3%	11,480	1,875	83.7%
Southeast Division	72.5%	54	21	61.1%	54	21	61.1%	8,336	1,223	85.3%
Southwest Division	77.0%	62	8	87.1%	62	8	87.1%	8,370	1,123	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00297

00000005671

Endpoint Arrival Dates through 2/1/26

"UNCLASSIFIED"

2/9/2026

	Day				Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	76,749	31,524	59%	76,749	31,524	59%	11,876,246	2,686,756	77%
Northeast Corridor	81%	34,546	17,977	48%	34,546	17,977	48%	5,294,204	1,205,216	77%
Acela	83%	4,464	2,302	48%	4,464	2,302	48%	1,092,584	292,385	73%
Northeast Regional	79%	30,082	15,675	48%	30,082	15,675	48%	4,201,620	912,831	78%
Richmond / Newport News / Norfolk	77%	8,361	2,106	75%	8,361	2,106	75%	1,293,076	318,323	75%
Springfield Shuttles	89%	423	143	66%	423	143	66%	72,152	9,112	87%
Roanoke	79%	3,332	1,348	60%	3,332	1,348	60%	325,502	58,256	82%
On Spine Northeast Regional	80%	17,966	12,078	33%	17,966	12,078	33%	2,510,890	527,140	79%
State Supported	80%	32,321	9,196	72%	32,321	9,196	72%	5,095,604	988,391	81%
Borealis	60%	627	0	100%	627	0	100%	66,748	16,867	75%
Capitol Corridor	90%	2,805	119	96%	2,805	119	96%	425,865	44,831	89%
Carolinian	60%	0	0	-	0	0	-	134,738	37,360	72%
Cascades	63%	2,624	359	86%	2,624	359	86%	291,704	65,602	78%
Downeaster	82%	1,174	100	91%	1,174	100	91%	174,081	23,360	87%
Empire	78%	3,385	2,678	21%	3,385	2,678	21%	633,138	138,722	78%
Adirondack	72%	53	53	0%	53	53	0%	38,840	14,484	63%
Ethan Allen Express	70%	138	138	0%	138	138	0%	68,897	19,981	71%
Maple Leaf	70%	562	343	39%	562	343	39%	71,441	31,822	55%
New York - Albany	85%	1,189	958	19%	1,189	958	19%	288,858	40,514	86%
New York - Niagara Falls	75%	1,443	1,186	18%	1,443	1,186	18%	165,102	31,921	81%
Gold Runner	73%	2,322	829	64%	2,322	829	64%	299,270	106,088	65%
Heartland Flyer	65%	186	122	34%	186	122	34%	23,767	9,508	60%
Hiawatha	90%	1,270	0	100%	1,270	0	100%	199,345	24,691	88%
Illinois	78%	1,527	732	52%	1,527	732	52%	281,604	78,059	72%
Carl Sandburg / Illinois Zephyr	85%	144	62	57%	144	62	57%	48,361	12,365	74%
Illini / Saluki	85%	937	294	69%	937	294	69%	99,878	26,261	74%
Lincoln Service	70%	446	376	16%	446	376	16%	133,365	39,433	70%
Keystone	92%	4,878	1,920	61%	4,878	1,920	61%	955,887	106,933	89%
Lincoln / Missouri	60%	828	135	84%	828	135	84%	91,465	41,371	55%
Mardi Gras Service	80%	331	132	60%	331	132	60%	51,137	6,212	88%
Michigan	69%	538	265	51%	538	265	51%	224,286	72,289	68%
Blue Water	70%	0	0	-	0	0	-	53,910	18,233	66%
Pere Marquette	85%	64	0	100%	64	0	100%	29,376	6,034	79%
Wolverine	65%	474	265	44%	474	265	44%	141,000	48,022	66%
Missouri	80%	193	0	100%	193	0	100%	26,968	5,534	79%
Pacific Surfliner	85%	7,187	455	94%	7,187	455	94%	804,197	123,487	85%
Pennsylvanian	72%	882	338	62%	882	338	62%	110,293	12,764	88%
Piedmont	73%	396	0	100%	396	0	100%	145,194	31,667	78%
Vermont	75%	1,168	1,012	13%	1,168	1,012	13%	155,917	43,046	72%
Long Distance	56%	9,037	4,351	52%	9,037	4,351	52%	1,470,722	492,882	66%
Auto Train	57%	873	542	38%	873	542	38%	87,388	16,343	81%
California Zephyr	50%	934	513	45%	934	513	45%	116,280	33,134	72%
Cardinal	55%	164	164	0%	164	164	0%	30,877	13,497	56%
City Of New Orleans	75%	512	199	61%	512	199	61%	79,807	17,014	79%
Coast Starlight	60%	943	150	84%	943	150	84%	134,542	42,169	69%
Crescent	70%	681	229	66%	681	229	66%	109,774	23,897	78%
Empire Builder	55%	887	310	65%	887	310	65%	116,216	46,622	60%
Floridian	40%	0	0	-	0	0	-	199,828	109,922	45%
Lake Shore Ltd	73%	362	362	0%	362	362	0%	114,272	29,190	74%
Palmetto	65%	936	8	99%	936	8	99%	112,566	17,755	84%
Silver Meteor	45%	1,031	898	13%	1,031	898	13%	122,690	37,373	70%
Southwest Chief	40%	551	327	41%	551	327	41%	96,401	55,541	42%
Sunset Ltd	70%	249	5	98%	249	5	98%	34,374	8,415	76%
Texas Eagle	50%	914	644	30%	914	644	30%	115,707	42,010	64%
Seasonal Trains	%	845	0	100%	845	0	100%	15,716	267	98%
Winter Park Express	75%	845	0	100%	845	0	100%	15,716	267	98%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00207 00000005071 "UNCLASSIFIED" 2/0/2020

Train Index Dates Through February 01, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	8,231	94,417	872	707,114	12,975,030	545

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	237	24,845	95	28,490	3,767,878	76
INFRASTRUCTURE PLANNED	135	583	24,845	235	20,949	3,767,878	56
FLEET RELIABILITY	90	2,429	94,417	257	123,006	12,975,030	95
TRAIN OPERATIONS	424	4,982	94,417	528	534,669	12,975,030	412

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 02/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 02/01/2026			ITP February 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	247	70	71.7%	247	70	71.7%	36,307	5,161	85.8%
Central Division	85.5%	55	7	87.3%	55	7	87.3%	8,121	940	88.4%
Northeast Division	80.0%	76	34	55.3%	76	34	55.3%	11,480	1,875	83.7%
Southeast Division	72.5%	54	21	61.1%	54	21	61.1%	8,336	1,223	85.3%
Southwest Division	77.0%	62	8	87.1%	62	8	87.1%	8,370	1,123	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-00110 Initial Terminal Performance By Terminal

Scheduled Departure Date: 02/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 02/01/2026			ITP February 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	247	70	71.7%	247	70	71.7%	36,307	5,161	85.8%
Central Division	85.5%	55	7	87.3%	55	7	87.3%	8,121	940	88.4%
CDL	90.0%	2	0	100.0%	2	0	100.0%	218	9	95.9%
CHI	85.0%	20	4	80.0%	20	4	80.0%	3,264	438	86.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	1	0	100.0%	25	2	92.0%
EUG	86.5%	2	0	100.0%	2	0	100.0%	241	33	86.3%
GRR	98.0%	1	0	100.0%	1	0	100.0%	117	5	95.7%
KCY	84.5%	2	0	100.0%	2	0	100.0%	243	17	93.0%
MKE	86.5%	5	0	100.0%	5	0	100.0%	724	57	92.1%
MSP	94.0%	1	0	100.0%	1	0	100.0%	118	3	97.5%
PDX	78.0%	5	0	100.0%	5	0	100.0%	614	79	87.1%
PNT	91.5%	1	0	100.0%	1	0	100.0%	299	39	87.0%
PTH	93.0%	-	-	-	-	-	-	118	9	92.4%
QCY	87.5%	1	1	0.0%	1	1	0.0%	243	21	91.4%
SEA	80.0%	8	1	87.5%	8	1	87.5%	979	144	85.3%
SPK	92.0%	1	0	100.0%	1	0	100.0%	124	13	89.5%
STL	88.0%	2	1	50.0%	2	1	50.0%	478	53	88.9%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	2	0	100.0%	243	7	97.1%
WIP	-	1	0	100.0%	1	0	100.0%	25	1	96.0%
Northeast Division	80.0%	76	34	55.3%	76	34	55.3%	11,480	1,875	83.7%
ALB	91.5%	7	6	14.3%	7	6	14.3%	859	96	88.8%
BON	43.5%	5	1	80.0%	5	1	80.0%	594	64	89.2%
BOS	86.5%	15	5	66.7%	15	5	66.7%	2,198	304	86.2%
BRK	88.0%	5	1	80.0%	5	1	80.0%	573	37	93.5%
BTN	48.0%	-	-	-	-	-	-	116	22	81.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	2	0	100.0%	236	23	90.3%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	-	-	-	-	-	-	117	23	80.3%
NFL	96.5%	2	1	50.0%	2	1	50.0%	249	13	94.8%
NHV	75.5%	3	2	33.3%	3	2	33.3%	643	117	81.8%
NYP	77.5%	30	18	40.0%	30	18	40.0%	4,823	1,085	77.5%
SAB	98.0%	1	0	100.0%	1	0	100.0%	116	1	99.1%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	5	0	100.0%	5	0	100.0%	766	40	94.8%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	84.0%	1	0	100.0%	1	0	100.0%	121	31	74.4%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	54	21	61.1%	54	21	61.1%	8,336	1,223	85.3%
ATL	-	-	-	-	-	-	-	15	0	100.0%
CLT	92.0%	2	0	100.0%	2	0	100.0%	606	47	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 02/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 02/01/2026			ITP February 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	247	70	71.7%	247	70	71.7%	36,307	5,161	85.8%
Southeast Division	72.5%	54	21	61.1%	54	21	61.1%	8,336	1,223	85.3%
HAR	62.0%	7	2	71.4%	7	2	71.4%	1,345	255	81.0%
JAX	-	-	-	-	-	-	-	3	1	66.7%
LOR	69.5%	1	1	0.0%	1	1	0.0%	122	15	87.7%
MIA	87.5%	2	0	100.0%	2	0	100.0%	243	26	89.3%
MOE	94.0%	2	0	100.0%	2	0	100.0%	248	3	98.8%
NFK	86.0%	2	1	50.0%	2	1	50.0%	323	38	88.2%
NOL	92.0%	4	0	100.0%	4	0	100.0%	522	21	96.0%
NPN	96.0%	1	0	100.0%	1	0	100.0%	216	14	93.5%
PGH	92.0%	1	0	100.0%	1	0	100.0%	123	5	95.9%
PHL	45.0%	4	2	50.0%	4	2	50.0%	568	290	48.9%
RGH	97.0%	2	0	100.0%	2	0	100.0%	483	15	96.9%
RNK	85.5%	2	1	50.0%	2	1	50.0%	242	33	86.4%
RVM	86.0%	-	-	-	-	-	-	113	13	88.5%
RVR	-	1	0	100.0%	1	0	100.0%	5	3	40.0%
SAV	91.5%	1	1	0.0%	1	1	0.0%	121	3	97.5%
SFA	70.5%	1	1	0.0%	1	1	0.0%	122	10	91.8%
WAS	70.0%	21	12	42.9%	21	12	42.9%	2,912	429	85.3%
Southwest Division	77.0%	62	8	87.1%	62	8	87.1%	8,370	1,123	86.6%
ARN	60.5%	1	0	100.0%	1	0	100.0%	123	10	91.9%
BFD	75.5%	6	1	83.3%	6	1	83.3%	746	167	77.6%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	1	0	100.0%	137	43	68.6%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	1	0	100.0%	120	4	96.7%
GTA	72.5%	3	2	33.3%	3	2	33.3%	377	36	90.5%
IRV	-	-	-	-	-	-	-	2	2	0.0%
LAX	77.5%	11	0	100.0%	11	0	100.0%	1,149	121	89.5%
OKC	96.0%	1	0	100.0%	1	0	100.0%	120	3	97.5%
OKJ	79.0%	6	2	66.7%	6	2	66.7%	1,297	316	75.6%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	10	1	90.0%	10	1	90.0%	1,649	172	89.6%
SAN	77.0%	12	1	91.7%	12	1	91.7%	1,391	128	90.8%
SAS	85.0%	1	0	100.0%	1	0	100.0%	119	7	94.1%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	7	1	85.7%	866	83	90.4%
SLO	62.0%	2	0	100.0%	2	0	100.0%	230	20	91.3%
SNC	-	-	-	-	-	-	-	17	5	70.6%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 2/1/2026

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		1	0	100.0%	54	10	81.5%	1	0	100.0%	52	8	84.6%
3	90	1	0	100.0%	124	20	83.9%	1	1	0.0%	123	46	62.6%
4	43	1	0	100.0%	123	17	86.2%	1	1	0.0%	123	75	39.0%
5	79	1	0	100.0%	123	23	81.3%	1	1	0.0%	120	22	81.7%
6		1	0	100.0%	122	35	71.3%	1	0	100.0%	122	37	69.7%
7		1	1	0.0%	119	19	84.0%	1	0	100.0%	113	22	80.5%
8		1	1	0.0%	119	51	57.1%	1	0	100.0%	118	60	49.2%
11		1	0	100.0%	123	22	82.1%	1	0	100.0%	118	18	84.7%
14		1	0	100.0%	124	16	87.1%	1	0	100.0%	123	31	74.8%
19		1	0	100.0%	121	27	77.7%	1	0	100.0%	121	14	88.4%
20	85	1	0	100.0%	121	6	95.0%	1	1	0.0%	121	12	90.1%
21		1	0	100.0%	118	14	88.1%	1	0	100.0%	117	22	81.2%
22		1	0	100.0%	119	6	95.0%	1	0	100.0%	118	26	78.0%
23		1	0	100.0%	124	3	97.6%	1	0	100.0%	124	20	83.9%
24	47	1	0	100.0%	124	8	93.5%	1	1	0.0%	124	12	90.3%
25		1	0	100.0%	124	0	100.0%	1	0	100.0%	124	15	87.9%
26	36	1	0	100.0%	124	2	98.4%	1	1	0.0%	124	17	86.3%
27		1	1	0.0%	118	9	92.4%	1	0	100.0%	115	28	75.7%
28		1	0	100.0%	115	26	77.4%	1	0	100.0%	115	19	83.5%
42		1	0	100.0%	123	5	95.9%	1	0	100.0%	122	15	87.7%
43		1	1	0.0%	123	18	85.4%	1	0	100.0%	123	8	93.5%
48	No OS	1	0	100.0%	122	26	78.7%	1	1	0.0%	122	20	83.6%
49	67	1	1	0.0%	122	26	78.7%	1	1	0.0%	122	23	81.1%
50	73	0	0	0.0%	51	11	78.4%	1	1	0.0%	52	25	51.9%
52		1	1	0.0%	122	10	91.8%	1	0	100.0%	122	17	86.1%
53	113	1	1	0.0%	122	15	87.7%	1	1	0.0%	122	20	83.6%
54	44	1	1	0.0%	39	2	94.9%	1	1	0.0%	39	6	84.6%
57	45	1	0	100.0%	38	2	94.7%	1	1	0.0%	38	2	94.7%
58		1	0	100.0%	115	3	97.4%	1	0	100.0%	114	17	85.1%
59	76	1	0	100.0%	114	13	88.6%	1	1	0.0%	114	12	89.5%
63		1	1	0.0%	124	62	50.0%	1	0	100.0%	123	65	47.2%
64	60	1	0	100.0%	122	32	73.8%	1	1	0.0%	122	31	74.6%
65		0	0	0.0%	39	6	84.6%	1	0	100.0%	39	7	82.1%
66		1	0	100.0%	122	19	84.4%	1	0	100.0%	122	23	81.1%
68	118	1	1	0.0%	124	29	76.6%	1	1	0.0%	124	63	49.2%
73		1	0	100.0%	123	5	95.9%	1	0	100.0%	122	55	54.9%
74		1	0	100.0%	123	10	91.9%	1	0	100.0%	123	35	71.5%
77		1	0	100.0%	121	6	95.0%	1	0	100.0%	120	35	70.8%
78		1	0	100.0%	120	6	95.0%	1	0	100.0%	120	14	88.3%
87	124	1	0	100.0%	40	10	75.0%	1	1	0.0%	40	9	77.5%
88		1	0	100.0%	40	5	87.5%	1	0	100.0%	40	8	80.0%
89		1	0	100.0%	121	24	80.2%	1	0	100.0%	121	21	82.6%

Amtrak On Time Performance

Trains Arriving Through: 2/1/2026

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
90		1	1	0.0%	121	3	97.5%	1	0	100.0%	121	10	91.7%
96	22	1	1	0.0%	18	2	88.9%	1	1	0.0%	18	6	66.7%
97	55	1	1	0.0%	122	59	51.6%	1	1	0.0%	122	22	82.0%
98	145	1	0	100.0%	121	8	93.4%	1	1	0.0%	121	31	74.4%
99	43	1	0	100.0%	39	5	87.2%	1	1	0.0%	38	19	50.0%
100	34	1	1	0.0%	3	2	33.3%	1	1	0.0%	2	1	50.0%
103		1	0	100.0%	39	6	84.6%	1	0	100.0%	39	3	92.3%
104		1	1	0.0%	16	2	87.5%	1	0	100.0%	16	0	100.0%
105	78	1	1	0.0%	19	9	52.6%	1	1	0.0%	19	3	84.2%
117		1	0	100.0%	2	1	50.0%	1	0	100.0%	2	1	50.0%
118	31	1	1	0.0%	39	3	92.3%	1	1	0.0%	39	4	89.7%
120		1	0	100.0%	19	3	84.2%	1	0	100.0%	19	2	89.5%
121	157	1	1	0.0%	18	6	66.7%	1	1	0.0%	18	5	72.2%
122	127	1	1	0.0%	18	7	61.1%	1	1	0.0%	18	3	83.3%
123	44	1	1	0.0%	20	2	90.0%	1	1	0.0%	20	1	95.0%
124		1	0	100.0%	38	2	94.7%	1	0	100.0%	38	6	84.2%
128		1	0	100.0%	40	7	82.5%	1	0	100.0%	39	3	92.3%
132	68	1	0	100.0%	18	1	94.4%	1	1	0.0%	18	2	88.9%
135	137	1	0	100.0%	39	7	82.1%	1	1	0.0%	39	22	43.6%
140	24	1	1	0.0%	39	3	92.3%	1	1	0.0%	39	9	76.9%
143		1	0	100.0%	39	2	94.9%	1	0	100.0%	39	4	89.7%
145	66	1	1	0.0%	18	4	77.8%	1	1	0.0%	18	6	66.7%
146	19	1	0	100.0%	39	7	82.1%	1	1	0.0%	39	16	59.0%
149	34	1	0	100.0%	19	0	100.0%	1	1	0.0%	19	8	57.9%
150	39	1	1	0.0%	40	28	30.0%	1	1	0.0%	40	27	32.5%
151		1	0	100.0%	121	35	71.1%	1	0	100.0%	120	31	74.2%
153		1	0	100.0%	40	2	95.0%	1	0	100.0%	40	5	87.5%
154	31	1	1	0.0%	18	3	83.3%	1	1	0.0%	18	11	38.9%
155	59	1	1	0.0%	40	6	85.0%	1	1	0.0%	40	7	82.5%
156		1	1	0.0%	40	5	87.5%	1	0	100.0%	40	6	85.0%
157		1	0	100.0%	18	1	94.4%	1	0	100.0%	18	9	50.0%
158		1	1	0.0%	39	2	94.9%	1	0	100.0%	39	3	92.3%
160	164	1	0	100.0%	39	0	100.0%	1	1	0.0%	37	8	78.4%
161	430	1	0	100.0%	39	3	92.3%	1	1	0.0%	39	25	35.9%
162	132	1	1	0.0%	40	3	92.5%	1	1	0.0%	40	18	55.0%
164	34	1	0	100.0%	40	5	87.5%	1	1	0.0%	40	13	67.5%
165	217	1	1	0.0%	40	12	70.0%	1	1	0.0%	40	15	62.5%
169		1	0	100.0%	39	4	89.7%	1	0	100.0%	38	9	76.3%
189	153	1	1	0.0%	18	7	61.1%	1	1	0.0%	18	9	50.0%
195	20	1	0	100.0%	40	0	100.0%	1	1	0.0%	40	29	27.5%
232		1	1	0.0%	124	6	95.2%	1	0	100.0%	124	8	93.5%
234		1	1	0.0%	124	10	91.9%	1	0	100.0%	124	9	92.7%

Amtrak On Time Performance

Trains Arriving Through: 2/1/2026

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
237	73	1	1	0.0%	123	24	80.5%	1	1	0.0%	122	18	85.2%
239	94	1	1	0.0%	123	37	69.9%	1	1	0.0%	122	12	90.2%
240	56	1	1	0.0%	124	14	88.7%	1	1	0.0%	123	17	86.2%
241	157	1	1	0.0%	124	32	74.2%	1	1	0.0%	124	21	83.1%
280	25	1	0	100.0%	124	6	95.2%	1	1	0.0%	124	27	78.2%
281		1	0	100.0%	124	14	88.7%	1	0	100.0%	124	19	84.7%
283	30	1	1	0.0%	124	29	76.6%	1	1	0.0%	124	26	79.0%
284	85	1	1	0.0%	124	6	95.2%	1	1	0.0%	123	17	86.2%
290	197	1	1	0.0%	124	27	78.2%	1	1	0.0%	122	41	66.4%
291	Cncld	1	1	0.0%	123	27	78.0%	0	0	0.0%	122	20	83.6%
301	16	1	1	0.0%	122	5	95.9%	1	1	0.0%	120	21	82.5%
306	26	1	0	100.0%	121	8	93.4%	1	1	0.0%	120	25	79.2%
311		1	1	0.0%	123	16	87.0%	1	0	100.0%	121	23	81.0%
316		1	0	100.0%	121	7	94.2%	1	0	100.0%	121	21	82.6%
318		1	0	100.0%	123	11	91.1%	1	0	100.0%	122	49	59.8%
319		1	0	100.0%	124	5	96.0%	1	0	100.0%	123	58	52.8%
331		1	0	100.0%	124	17	86.3%	1	0	100.0%	124	21	83.1%
332		1	0	100.0%	124	10	91.9%	1	0	100.0%	124	22	82.3%
334		1	0	100.0%	124	4	96.8%	1	0	100.0%	123	17	86.2%
335		1	0	100.0%	124	17	86.3%	1	0	100.0%	122	24	80.3%
336		1	0	100.0%	124	6	95.2%	1	0	100.0%	124	6	95.2%
337		1	0	100.0%	124	6	95.2%	1	0	100.0%	124	15	87.9%
338		1	0	100.0%	124	27	78.2%	1	0	100.0%	122	32	73.8%
339		1	0	100.0%	124	26	79.0%	1	0	100.0%	124	27	78.2%
341		1	0	100.0%	118	21	82.2%	1	0	100.0%	115	18	84.3%
342		1	0	100.0%	124	8	93.5%	1	0	100.0%	122	21	82.8%
350	21	1	0	100.0%	105	9	91.4%	1	1	0.0%	103	63	38.8%
355	23	1	0	100.0%	120	19	84.2%	1	1	0.0%	115	37	67.8%
370	110	1	1	0.0%	120	14	88.3%	1	1	0.0%	117	26	77.8%
371		1	0	100.0%	117	5	95.7%	1	0	100.0%	116	17	85.3%
381		1	0	100.0%	124	5	96.0%	1	0	100.0%	124	16	87.1%
382	26	1	1	0.0%	124	4	96.8%	1	1	0.0%	124	29	76.6%
390	25	1	0	100.0%	108	10	90.7%	1	1	0.0%	107	37	65.4%
391	41	1	0	100.0%	109	3	97.2%	1	1	0.0%	106	23	78.3%
392		1	0	100.0%	123	4	96.7%	1	0	100.0%	121	33	72.7%
393		1	0	100.0%	124	10	91.9%	1	0	100.0%	123	33	73.2%
400		1	0	100.0%	38	3	92.1%	1	0	100.0%	36	1	97.2%
409		1	0	100.0%	17	1	94.1%	1	0	100.0%	17	2	88.2%
448	Cncld	1	1	0.0%	60	24	60.0%	0	0	0.0%	57	21	63.2%
450	103	1	1	0.0%	38	14	63.2%	1	1	0.0%	37	14	62.2%
460	66	1	1	0.0%	38	19	50.0%	1	1	0.0%	35	13	62.9%
461		1	0	100.0%	39	4	89.7%	1	0	100.0%	38	1	97.4%

Amtrak On Time Performance

Trains Arriving Through: 2/1/2026

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
465		1	0	100.0%	17	0	100.0%	1	0	100.0%	17	0	100.0%
488		1	0	100.0%	40	12	70.0%	1	0	100.0%	35	7	80.0%
499		1	0	100.0%	35	6	82.9%	1	0	100.0%	34	3	91.2%
500		1	0	100.0%	124	9	92.7%	1	0	100.0%	123	13	89.4%
502		1	0	100.0%	124	9	92.7%	1	0	100.0%	122	28	77.0%
503		1	0	100.0%	121	13	89.3%	1	0	100.0%	119	33	72.3%
504		1	0	100.0%	124	11	91.1%	1	0	100.0%	123	32	74.0%
505		1	0	100.0%	124	21	83.1%	1	0	100.0%	122	26	78.7%
506		1	0	100.0%	123	17	86.2%	1	0	100.0%	122	15	87.7%
507		1	0	100.0%	124	12	90.3%	1	0	100.0%	124	40	67.7%
508		1	0	100.0%	122	26	78.7%	1	0	100.0%	122	25	79.5%
509		1	0	100.0%	124	8	93.5%	1	0	100.0%	124	28	77.4%
511		1	0	100.0%	124	13	89.5%	1	0	100.0%	124	21	83.1%
516	18	1	0	100.0%	122	9	92.6%	1	1	0.0%	122	48	60.7%
517		1	0	100.0%	124	2	98.4%	1	0	100.0%	123	39	68.3%
518	20	1	0	100.0%	124	16	87.1%	1	1	0.0%	124	76	38.7%
519	17	1	0	100.0%	122	5	95.9%	1	1	0.0%	122	19	84.4%
562		1	0	100.0%	120	14	88.3%	1	0	100.0%	118	16	86.4%
564		1	0	100.0%	120	11	90.8%	1	0	100.0%	114	15	86.8%
566		1	0	100.0%	120	7	94.2%	1	0	100.0%	117	15	87.2%
572		1	0	100.0%	117	10	91.5%	1	0	100.0%	114	25	78.1%
573	54	1	0	100.0%	120	16	86.7%	1	1	0.0%	116	18	84.5%
579		1	0	100.0%	7	1	85.7%	1	0	100.0%	7	1	85.7%
580		1	0	100.0%	120	5	95.8%	1	0	100.0%	119	12	89.9%
581		1	0	100.0%	120	14	88.3%	1	0	100.0%	120	27	77.5%
584		1	0	100.0%	7	0	100.0%	1	0	100.0%	7	2	71.4%
586		1	0	100.0%	120	21	82.5%	1	0	100.0%	113	16	85.8%
587		1	0	100.0%	118	6	94.9%	1	0	100.0%	114	18	84.2%
588		1	0	100.0%	7	0	100.0%	1	0	100.0%	7	0	100.0%
591		1	0	100.0%	120	5	95.8%	1	0	100.0%	119	12	89.9%
593		1	0	100.0%	117	18	84.6%	1	0	100.0%	107	12	88.8%
595		1	0	100.0%	119	24	79.8%	1	0	100.0%	118	20	83.1%
612		1	0	100.0%	18	2	88.9%	1	0	100.0%	18	0	100.0%
615		1	1	0.0%	18	9	50.0%	1	0	100.0%	18	3	83.3%
660		1	0	100.0%	40	3	92.5%	1	0	100.0%	40	16	60.0%
661	34	1	1	0.0%	40	4	90.0%	1	1	0.0%	40	12	70.0%
663	252	1	1	0.0%	40	6	85.0%	1	1	0.0%	40	3	92.5%
664	13	1	0	100.0%	39	6	84.6%	1	1	0.0%	39	5	87.2%
665	12	1	0	100.0%	40	6	85.0%	1	1	0.0%	40	15	62.5%
666	15	1	1	0.0%	40	14	65.0%	1	1	0.0%	40	4	90.0%
667	30	1	0	100.0%	40	6	85.0%	1	1	0.0%	40	10	75.0%
669	31	1	0	100.0%	39	4	89.7%	1	1	0.0%	39	16	59.0%

Amtrak On Time Performance

Trains Arriving Through: 2/1/2026

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
670	103	1	1	0.0%	40	7	82.5%	1	1	0.0%	40	5	87.5%
671		1	0	100.0%	39	3	92.3%	1	0	100.0%	39	5	87.2%
672	24	1	0	100.0%	40	5	87.5%	1	1	0.0%	40	6	85.0%
674	22	1	0	100.0%	39	14	64.1%	1	1	0.0%	39	2	94.9%
690	12	1	1	0.0%	36	1	97.2%	1	1	0.0%	36	2	94.4%
691		1	0	100.0%	36	2	94.4%	1	0	100.0%	36	9	75.0%
692		1	0	100.0%	36	2	94.4%	1	0	100.0%	36	8	77.8%
693	16	1	0	100.0%	36	5	86.1%	1	1	0.0%	36	9	75.0%
694		1	0	100.0%	36	5	86.1%	1	0	100.0%	36	4	88.9%
695		1	0	100.0%	36	4	88.9%	1	0	100.0%	36	7	80.6%
696		1	0	100.0%	36	3	91.7%	1	0	100.0%	36	8	77.8%
697		1	1	0.0%	36	6	83.3%	1	0	100.0%	36	7	80.6%
698		1	0	100.0%	35	0	100.0%	1	0	100.0%	35	4	88.6%
699		1	0	100.0%	28	2	92.9%	1	0	100.0%	27	0	100.0%
701		1	0	100.0%	56	7	87.5%	1	0	100.0%	55	3	94.5%
702	24	1	0	100.0%	123	19	84.6%	1	1	0.0%	122	33	73.0%
703		1	1	0.0%	124	35	71.8%	1	0	100.0%	123	31	74.8%
704		1	0	100.0%	55	5	90.9%	1	0	100.0%	54	12	77.8%
710		1	0	100.0%	124	41	66.9%	1	0	100.0%	124	38	69.4%
711	21	1	0	100.0%	117	10	91.5%	1	1	0.0%	108	20	81.5%
712		1	0	100.0%	124	30	75.8%	1	0	100.0%	121	42	65.3%
715		1	0	100.0%	123	33	73.2%	1	0	100.0%	116	58	50.0%
716	70	1	1	0.0%	124	51	58.9%	1	1	0.0%	121	52	57.0%
717		1	0	100.0%	114	30	73.7%	1	0	100.0%	102	35	65.7%
718		1	1	0.0%	124	52	58.1%	1	0	100.0%	123	39	68.3%
719		1	0	100.0%	124	43	65.3%	1	0	100.0%	119	37	68.9%
720		1	0	100.0%	42	3	92.9%	1	0	100.0%	42	2	95.2%
723		1	0	100.0%	42	4	90.5%	1	0	100.0%	42	4	90.5%
724		1	0	100.0%	42	1	97.6%	1	0	100.0%	42	5	88.1%
727		1	0	100.0%	42	4	90.5%	1	0	100.0%	42	7	83.3%
728		1	0	100.0%	42	4	90.5%	1	0	100.0%	42	8	81.0%
729		1	0	100.0%	42	4	90.5%	1	0	100.0%	42	7	83.3%
733		1	0	100.0%	42	6	85.7%	1	0	100.0%	38	11	71.1%
734		1	0	100.0%	42	10	76.2%	1	0	100.0%	42	7	83.3%
738		1	0	100.0%	42	8	81.0%	1	0	100.0%	40	3	92.5%
741		1	0	100.0%	42	7	83.3%	1	0	100.0%	42	4	90.5%
742		1	0	100.0%	42	5	88.1%	1	0	100.0%	41	4	90.2%
743		1	1	0.0%	42	6	85.7%	1	0	100.0%	42	3	92.9%
744		1	0	100.0%	42	4	90.5%	1	0	100.0%	42	12	71.4%
745		1	0	100.0%	42	3	92.9%	1	0	100.0%	42	8	81.0%
746		1	1	0.0%	42	2	95.2%	1	0	100.0%	42	4	90.5%
747		1	0	100.0%	42	9	78.6%	1	0	100.0%	42	9	78.6%

Amtrak On Time Performance

Trains Arriving Through: 2/1/2026

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
748	17	1	0	100.0%	41	7	82.9%	1	1	0.0%	41	6	85.4%
751		1	0	100.0%	42	10	76.2%	1	0	100.0%	41	6	85.4%
761		1	0	100.0%	122	5	95.9%	1	0	100.0%	120	21	82.5%
765		1	1	0.0%	122	15	87.7%	1	0	100.0%	122	19	84.4%
769	Cncld	1	0	100.0%	122	14	88.5%	0	0	0.0%	119	24	79.8%
770		1	1	0.0%	122	13	89.3%	1	0	100.0%	122	26	78.7%
774		1	0	100.0%	122	12	90.2%	1	0	100.0%	121	26	78.5%
777	26	1	0	100.0%	7	0	100.0%	1	1	0.0%	7	2	71.4%
782		1	0	100.0%	7	1	85.7%	1	0	100.0%	7	0	100.0%
785		1	0	100.0%	122	1	99.2%	1	0	100.0%	122	20	83.6%
790		1	1	0.0%	122	8	93.4%	1	0	100.0%	120	14	88.3%
794		1	0	100.0%	122	11	91.0%	1	0	100.0%	121	25	79.3%
821		1	0	100.0%	120	3	97.5%	1	0	100.0%	120	53	55.8%
822	19	1	0	100.0%	120	4	96.7%	1	1	0.0%	120	58	51.7%
1105		1	0	100.0%	25	2	92.0%	1	0	100.0%	25	1	96.0%
1106		1	0	100.0%	25	1	96.0%	1	0	100.0%	25	1	96.0%
1333		1	0	100.0%	120	14	88.3%	1	0	100.0%	117	43	63.2%
1340		1	0	100.0%	119	3	97.5%	1	0	100.0%	119	28	76.5%
2205	29	1	0	100.0%	39	4	89.7%	1	1	0.0%	39	4	89.7%
2226	92	1	1	0.0%	17	5	70.6%	1	1	0.0%	17	4	76.5%
2248	89	1	0	100.0%	36	4	88.9%	1	1	0.0%	36	9	75.0%
2250	54	1	0	100.0%	39	5	87.2%	1	1	0.0%	39	15	61.5%
2255	80	1	0	100.0%	37	6	83.8%	1	1	0.0%	37	15	59.5%
2258		1	0	100.0%	18	8	55.6%	1	0	100.0%	17	6	64.7%
2259	88	1	1	0.0%	22	10	54.5%	1	1	0.0%	21	13	38.1%
2265	199	1	1	0.0%	19	1	94.7%	1	1	0.0%	19	10	47.4%
2271		1	0	100.0%	23	2	91.3%	1	0	100.0%	23	11	52.2%
2290		1	0	100.0%	17	2	88.2%	1	0	100.0%	17	5	70.6%

Amtrak Endpoint OTP Details

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 2/1/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2205	WAS	29	ENG	27	ENG	27	XPV-BAL	AM	Undesired emergency application, 2103, TRAIN IN EMERGENCY	
2226	NYP	92	ITI	66	ITI	66	WAS-WAS	AM	Service, turn, or wye train, 2265, PC2123 dnl OCS issues at BOS	
2248	BOS	89	MTI	66	MTI	66	NHV-XGX	AM	Disabled train ahead, Milepost w/Letters, NHV, XGX, AM2248 held until AM162 departed NLC, the rescue set was east of Shaw's Cove to deal with disabled AM161	
2250	BOS	54	MTI	29	MTI	29	XNH-XGX	AM	Disabled train ahead, Milepost w/Letters, NHV, XGX, AM2250 was held due to disabled AM161 at NLC	
2255	WAS	80	MTI	68	MTI	68	PVD-XGX	AM	Disabled train ahead, Milepost w/Letters, PVD, XGX, AM2255 was held due to disabled AM161 being on trk 1 in NLC	
2259	WAS	88	ITI	77	ITI	77	BOS-BOS	AM	Service, turn, or wye train, 2248, late turn of AM2248	
2265	WAS	199	MTI	132	MTI	115	PVD-XGX	AM	Disabled train ahead, Milepost, PVD, XGX, holding while psgrs are being transferred to 87 in New London FROM DISABLE AM 161	
87	NFK	124	MTI	115	MTI	47	NLC-NLC	AM	Disabled train ahead, Milepost, NLC, NLC, TRAIN 87 HOLDING TO TRANSFER 348 PSGRS OF Train AM161 A/C lost HEP just east of New London station	
96	BOS	22	WTR	26	WTR	16	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, C INTERLOCKING, FROZEN DOORS 81519 AND 82729	
99	NPN	43	FTI	22	FTI	19	FBG-ASD	CS	Follow x40931, Other, cfp 51.7-Asd	
100	NYP	34	ENG	23	ENG	23	XHM-NWK	AM	Air / Brake, 665, ENGR REPORTED LOOSE BRAKE PIPE BETWEEN FIRST AND SECOND HOSE AT DELCO.	
105	WAS	78	ITI	81	ITI	81	NYP-NYP	AM	Service, turn, or wye train, 120	
118	NYP	31	SYS	31	SYS	31	WAS-WAS	AM	Other late crew, IT TOOK THE CREW 40" AFTER THEY WERE CALLED TO GET THE MTR OFF 89, WE HAD TO CHANGE TO THE 660 MTR COMING FROM THE PIT. AND 89 MTR WENT ON 154	
121	WAS	157	WTR	94	WTR	94	NYP-NYP	AM	Snow removal equipment working ahead, Other, NYP-NYP, HELD AT "F" INT A/C ICE PATROL IN LINE 4	
122	NYP	127	ITI	99	ITI	99	WAS-WAS	AM	Service, turn, or wye train, 121	

Amtrak Endpoint OTP Details

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 2/1/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
123	PHL	44	SVS	29	SVS	29	NYP-NYP	AM	Routine inspections, MECHANICAL REQUESTED DUE TO PAPER WORK ISSUE	
132	BOS	68	ENG	70	ENG	70	OSB-OSB	AM	HEP, 607, lost hep at osb	
135	WAS	137	CAR	51	CAR	39	NHV-NHV	MN	HEP 81540, Short loop cables	
140	SPG	24	CAR	23	CAR	23	WAS-WAS	AM	Air / Brake / Wheel, ., YD MASTER REQUESTED THE DERAILS DOWN AT 1139 AND DOWN AT	
145	RNK	66	CAR	37	CAR	37	NYP-NYP	AM	Set out defective car, UNSPECIFIED, LATE F/SYD A/C UTILIZING TWO COACH CARS FROM AM79 EQUIPMENT	
146	SPG	19	SMW	20	SMW	18	NWK-NYP	AM	Scheduled in track usage program, Other, HUDSON- LACK 55HR OUTAGE SINGLE TRACKING	
149	WAS	34	CTI	25	CTI	15	BRP-STM	MN	Follow MTA, Control Point, 234	
150	BOS	39	DCS	11	PTI	11	KIN-PVD	AM	Follow, 2290, Milepost, xdr, pvd	
154	BOS	31	ENG	33	ENG	33	WAS-WAS	AM	Traction motor, 609 , SHOPPED FOR TRACTION MTR , HIGH SHOP COUNT IN WAS.	
155	NFK	59	ENG	46	ENG	29	BAL-BWI	AM	Onboard HBD alarm, 652	
160	BOS	164	MTI	171	MTI	164	NHV-NLC	AM	Disabled train ahead, Milepost, xvw, xvw, holding at View while psgrs are being transferred to 87 in New London off 161	
161	WAS	430	ENG	371	ENG	243	NLC-NLC	AM	HEP, 630, both pans are down with no HEP	
162	BOS	132	MTI	66	MTI	55	OSB-NLC	AM	Disabled train ahead, Milepost, xna, xna, holding while psgrs are being transferred to 87 in New London a/c disable AM161	
164	BOS	34	HLD	26	SMW	9	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.2 TRK HUDSON TO LACK	
165	WAS	217	ITI	143	ITI	143	BOS-BOS	AM	Service, turn, or wye train, 160, late turn of AM160	
189	WAS	153	DMW	116	DMW	116	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, DISBALED TRACK CAR LINE 1	
195	WAS	20	SMW	13	SMW	13	NYP-NWK	AM	Scheduled in track usage program, Other, XPT-XPT, HELD A/C SINGLE TRACKING NO.2 TRK LACK TO HUDSON	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Region: ALL

Service: ALL

Arriving On: 2/1/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
450	SPG	103	SVS	105	SVS	105	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from Mechanical	
460	SPG	66	ITI	62	ITI	62	NHV-NHV	AM	Service, turn, or wye train, 461, Late turn	
53	SFA	113	WTR	116	WTR	116	XSE-XFL	CS	Switches frozen at Mars Bluff account snow storm Snow Storm, Control Point, Mars Bluff	
661	HAR	34	CCR	34	CCR	20	PHL-ARD	AM	Electrical failure, cc/9644, CAB CAR ISSUES NECESSARY TO WYE	
663	HAR	252	CCR	233	CCR	233	NYP-NYP	AM	Set out defective cab car, 9643, LATE F/SSYD A/C SHOPPED CAB CAR 9643	
664	NYP	13	SVS	15	SVS	15	PAO-PHL	AM	Unplanned Wye, WYE'D COMING INTO 30TH ST	
665	HAR	12	SMW	11	SMW	11	NYP-NWK	AM	Scheduled in track usage program, Other, XPT-XPT, HELD A/C SINGLE TRACKING NO.2 TRK LACK TO HUDSON	
666	NYP	15	SVS	38	SVS	33	ARD-PHL	AM	Unplanned Wye, WYE'D COMING INTO 30TH ST DUE TO LACK OF A CAB CAR	
667	HAR	30	SVS	24	SVS	24	PHL-ARD	AM	Unplanned Wye, No Cab Car	
669	HAR	31	CCR	25	CCR	25	PHL-ARD	AM	Electrical failure, 9644, Cab car issues, necessary to wye	
670	NYP	103	ITI	101	ITI	101	HAR-HAR	AM	Service, turn, or wye train, 615, Late turn	
672	NYP	24	SVS	24	SVS	24	ARD-PHL	AM	Unplanned Wye, No Cab Car	
674	NYP	22	SMW	25	SMW	25	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XBH, SINGLE TRACKING ON NO.2 TRACK BTWN HUDSON AND LACK A/C 3 TRK O/O/S.	
20	NYP	85	ENG	76	ENG	76	WAS-WAS	AM	Air / Brake, 656 AND 664, 656 FROZEN MAIN RES. 664 FOR HW TRACTION MTR FAULT	
690	BON	12	TRS	10	TRS	10	DHM-EXR	CS	Bridge strike by a vehicle or boat Control Point, New Fields	
693	BRK	16	PTI	12	PTI	12	EXR-DHM	CS	Meet 694, Control Point, rockingham	
64	ALB	60	FTI	43	FTI	18	UCA-AMS	CS	Follow csx, Milepost, 231, 177	
68	NYP	118	SVS	91	SVS	91	ALB-ALB	AM	Pick up equipment Control Point, 142	
237	ALB	73	ITI	50	ITI	50	NYP-NYP	AM	Service, turn, or wye train, 284	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Region: ALL

Service: ALL

Arriving On: 2/1/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
239	ALB	94	ITI	82	ITI	82	NYP-NYP	AM	Service, turn, or wye train, 284, MECHANICAL ISSUE WITH RELAY, DISABLED TRACK CAR IN LINE 1, OPERATE LINE 4	
240	NYP	56	SVS	48	SVS	48	ALB-ALB	AM	Frozen equipment responsible for late release from shop	
241	ALB	157	ITI	145	ITI	145	NYP-NYP	AM	Service, turn, or wye train, 290	
280	NYP	25	DMW	9	DMW	9	CRT-CRT	MN	Waiting for MW clearance Control Point, 33	
283	NFL	30	FTI	26	FTI	26	AMS-UCA	CS	Follow csx, Milepost, 186, 235	
284	NYP	85	SVS	83	SVS	76	ALB-ALB	AM	Departed ALB . Found 1st car had no heat . Shoved back to ALB . Waited for new set of equipment and cross platform all passengers to new equipment Other, ALB	
290	NYP	170	CCR	176	CCR	176	ALB-ALB	AM	Set out defective cab car 11760, Car was taken out before I receive Train. That's not the right car number in the notes.	
291	BTN	Trn Cancelled	ITI	44	ITI	44	NYP-NYP	AM	Service, turn, or wye train, 240	
48	NYP	No OS Rpt	FTI	156	ITI	153	CHI-CHI	AM	Service, turn, or wye train 49, Per CD7	
49	CHI	67	FTI	69	SVS	50	NYP-NYP	AM	Water, commissary, toilet/trash dumping	
448	BOS	Trn Cancelled								
97	MIA	55	SVS	78	SVS	69	NYP-NYP	AM	Water, commissary, toilet/trash dumping	
98	NYP	145	DMW	58	DMW	55	FLO-XDI	CS	Hold for defect repair Control Point, mars bluff	
54	SAB	44	INJ	42	INJ	28	HFD-HFD	AM	Injured or sick passenger, AM54 was delayed at HART due to psngr having panic attack on train	
57	WAS	45	SVS	36	SVS	36	NHV-NHV	MN	Pick up equipment Control Point, 272	
24	MOE	47	FTI	80	FTI	59	PAG-MOE	CS	Meet m60530, Siding, st elmo	
26	MOE	36	FTI	55	FTI	45	PAG-MOE	CS	Follow M60201, Milepost, 678.0, 669.4	
5	EMY	79	ENG	206	ENG	92	LNK-LNK	BN	Pick up rescue locomotive due to mechanical failure Add BN9100 in LNK, 79	
748	SAC	17	DBS	22	DBS	22	DAV-SAC	UP	Debris strike Bike, Milepost, 78.6, 78.6	
50	NYP	73	ITI	132	ITI	132	CHI-CHI	AM	Service, turn, or wye train 51	
516	VAC	18	FTI	16	FTI	16	XF2-X1J	BN	Blocked from station track Control Point, Still Creek, Main Yard Switch Job	

Amtrak Endpoint OTP Details

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 2/1/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
518	VAC	20	PTI	17	PTI	17	STW-MVW	BN	Meet 519, Siding, S MVW
519	SEA	17	CUI	29	CUI	29	X8B-X8B	BN	U.S. Border Patrol Pax had Canada brand chicken, salmon and other Canadian products declared which were confiscated during a thorough inspection
59	NOL	76	RTE	115	RTE	110	JAN-JAN	CC	Dispatcher hold Control Point, JAN
822	OKC	19	FTI	20	FTI	20	FTW-GLE	BN	Follow All red @ FTW - ran freight in front of us then follow to 350, bnsf 7347, Other, FTW
350	PNT	21	FTI	16	FTI	16	XT6-X1W	CR	Cross Traffic cp2135, Control Point, lou
355	CHI	23	PTI	17	PTI	17	XPI-HMI	NS	Meet 48, Milepost, 494, 497
370	GRR	110	CAR	99	CAR	99	CHI-CHI	AM	Bad ordered car 4014 ID4014
573	LAX	54	POL	44	POL	44	SNA-SNA	SC	On-train police or DEA activity Conductor assaulted
769	GTA	Trn Cancelled	TRS	77	TRS	77	CPN-SBA	UP	Trespasser strike Other, Millpass St. Xing.
777	SLO	26	PTI	46	PTI	43	CPN-SBA	UP	Meet 11, Control Point, South Santa Barbara
702	BFD	24	TEN	30	TEN	30	LOD-SKT	UP	HEP Lost HEP. Had to short loop HEP cable to locomotive., C2106
711	OKJ	21	DCS	22	DCS	22	SKN-SKN	BN	Power switch failure Threw both switches by hand in block, Control Point, keddie junction
716	BFD	70	TEN	73	TEN	49	OKJ-OKJ	UP	HEP HEP motor stopped and wouldn't start. TASI responded to OKJ and was able to restart HEP engine with the help of Engineer Ohman and Klitzing, C2006
3	LAX	90	ENG	168	ENG	100	XIA-GLP	BN	Air / Brake Main res pipe disconnected between 15 and charger unit 321, 203, 15
4	CHI	43	FTI	90	FTI	30	NDL-KNG	BN	Follow BNSF, Control Point, Yucca
301	STL	16	WTR	23	WTR	23	CHI-CHI	AM	Ice / snow on or under equipment Late release due to thawing equipment, Other, chi yard
306	CHI	26	FTI	50	FTI	45	SMT-XTF	AM	Cross Traffic Freight had problems with key to throw switch, NS 33G, Other, 21st street
382	CHI	26	FTI	22	FTI	18	MDT-PLO	BN	Meet Freight crossing in front of us MT1-MT2, Control Point, Earlville, 7851, BNSF
390	CHI	25	PTI	25	PTI	25	CHM-RTL	CC	Meet 391, Siding, LEVERETTE JCT
391	CDL	41	RTE	30	RTE	27	CEN-DQN	CC	Dispatcher hold Hold for system outage, Control Point, Centralia

Amtrak Initial Terminal Details

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 2/1/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	666	02/01	1		
HAR	670	02/01	101	101	Service, turn, or wye train, 615, Late turn
LOR	53	02/01	567	567	Ice / snow on or under equipment Delayed do to DRUMMAC having to remove snow out of car carriers so they could unload and load cars and short on man power, Other, Lorton
NFK	158	02/01	17	17	Arrived to the storage tracks, to take scheduled equipment, it was still under blueflag protection and was still being cleaned. Had to speak with Trainmaster Houston who instructed me to call CNOC Ops and have us switched to the train designated for 128.
PHL	150	02/01	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	615	02/01	1		
RNK	156	02/01	1		
SAV	90	02/01	15	15	Blue flag protection was present upon arrival. Had to wait on mechanical to arrive and remove flag and ok the train for departure. 8930
SFA	52	02/01	92	92	Delay offloading train 53 due to weather 53
WAS	54	02/01	12	12	Air / Brake, 654, EGN KEEP DUMPING AIR.
WAS	96	02/01	16	16	Ice / snow on or under equipment, Control Point, C INTERLOCKING, FROZEN DOORS 81519 AND 82729
WAS	100	02/01	1		
WAS	104	02/01	1		
WAS	118	02/01	31	31	Other late crew, IT TOOK THE CREW 40" AFTER THEY WERE CALLED TO GET THE MTR OFF 89, WE HAD TO CHANGE TO THE 660 MTR COMING FROM THE PIT. AND 89 MTR WENT ON 154
WAS	122	02/01	99	99	Service, turn, or wye train, 121
WAS	140	02/01	23	23	Air / Brake / Wheel, ., YD MASTER REQUESTED THE DERAILS DOWN AT 1139 AND DOWN AT
WAS	154	02/01	33	33	Traction motor, 609 , SHOPPED FOR TRACTION MTR , HIGH SHOP COUNT IN WAS.
WAS	162	02/01	24	24	Other electrical failure, ALL, HIGH SHOP COUNT FOR WAS. NO MTR EARLY TO PUT ON THE TRAIN.
WAS	2226	02/01	66	66	Service, turn, or wye train, 2265, PC2123 dnl OCS issues at BOS
WAS	2228	02/01	49	49	Service, turn, or wye train, 2255, after dp PVD took 70" delay
WAS	2274	02/01	7	7	Air / Brake, 2038, SNOW BRAKE TRIPPED AND KEEP THE PARKING BRAKE FROM DISENGAGING
ALB	68	02/01	121	91	Pick up equipment Control Point, 142

Amtrak Initial Terminal Details

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 2/1/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	68	02/01	121	30	Initial terminal
ALB	232	02/01	9	9	Late from shop.
ALB	234	02/01	7	7	Late coming from the shop Control Point, 142
ALB	240	02/01	48	48	Frozen equipment responsible for late release from shop
ALB	290	02/01	203	176	Set out defective cab car 11760, Car was taken out before I receive Train. That's not the right car number in the notes.
ALB	448	01/31	(No OS)		
BON	697	02/01	1		
BOS	139	02/01	78	78	Service, turn, or wye train, 162, late turn of AM162
BOS	165	02/01	143	143	Service, turn, or wye train, 160, late turn of AM160
BOS	2259	02/01	77	77	Service, turn, or wye train, 2248, late turn of AM2248
BOS	2265	02/01	42	42	Onboard HBD alarm, 2121-3472, rpts 2265eq (2121-2123) went back to the yard to clear Alarms
BOS	2275	02/01	45	45	Water, commissary, toilet/trash dumping, delayed due to late commissary loading the cafe car
BRK	690	02/01	4	4	Restrictive signal(s) from unknown cause Stop, Control Point, Brunswick West
NFL	284	02/01	1		
NHV	450	02/01	105	105	Planned set out / pick out of locomotives, cars or section of train, Late release from Mechanical
NHV	460	02/01	62	62	Service, turn, or wye train, 461, Late turn
NYP	43	02/01	22	22	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	49	02/01	388	390	Service, turn, or wye train, 98
NYP	51	02/01	53	53	Scheduled in track usage program, Other, NYP-NYP, LATE F/SSYD A/C LINE 1 OOS
NYP	63	02/01	15	15	Scheduled in track usage program, Other, NYP-NYP, LATE F/SSYD A/C LINE 1 OOS
NYP	97	02/01	134	134	Service, turn, or wye train, 80, (7490 01FEB26) SLEEPER FROM 80(01)
NYP	105	02/01	80	81	Service, turn, or wye train, 120
NYP	121	02/01	154	60	PTC - On Board Cab Signal or PTC Failure, 9647, PAPERWORK ISSUES
NYP	121	02/01	154	94	Snow removal equipment working ahead, Other, NYP-NYP, HELD AT "F" INT A/C ICE PATROL IN LINE 4
NYP	123	02/01	27	29	Routine inspections, MECHANICAL REQUESTED DUE TO PAPER WORK ISSUE

Amtrak Initial Terminal Details

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 2/1/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	145	02/01	37	37	Set out defective car, UNSPECIFIED, LATE F/SYD A/C UTILIZING TWO COACH CARS FROM AM79 EQUIPMENT
NYP	155	02/01	18	18	Air / Brake / Wheel, 82738, BRAKE PROBLEMS ON CAR 82738
NYP	189	02/01	116	116	Held for or routed around MW work or equipment, Other, DISBALED TRACK CAR LINE 1
NYP	237	02/01	50	50	Service, turn, or wye train, 284
NYP	239	02/01	80	82	Service, turn, or wye train, 284, MECHANICAL ISSUE WITH RELAY, DISABLED TRACK CAR IN LINE 1, OPERATE LINE 4
NYP	241	02/01	143	145	Service, turn, or wye train, 290
NYP	283	02/01	3	3	Passenger and/or baggage, BOARDING
NYP	291	02/01	42	44	Service, turn, or wye train, 240
NYP	661	02/01	7	7	Scheduled in track usage program, Other, NYP-NYP, LATE F/SSYD A/C LINE 1 OOS
NYP	663	02/01	233	233	Set out defective cab car, 9643, LATE F/SSYD A/C SHOPPED CAB CAR 9643
CHI	7	02/01	27	27	Switching and signal issues in the yard Cleaners also got on unannounced and without informing glasshouse while trying to board, slowing down boarding., Other, CHI Yard
CHI	41	02/01	37	37	Needed windshield washer fluid 303
CHI	301	02/01	23	23	Ice / snow on or under equipment Late release due to thawing equipment, Other, chi yard
CHI	370	02/01	99	99	Bad ordered car 4014 ID4014
QCY	382	02/01	5	5	Inability to contact dispatcher Signal to get out of stub track, Control Point, XO West Quincy
SEA	8	02/01	11	11	Routine inspections Other, SEA Holgate Crew Base
STL	311	02/01	3	3	Unable to reach ticket agent in STL for the release of passengers. Finally established contact at 0800.
BFD	703	02/01	2	2	Hold for thruway bus
GTA	770	02/01	1		
GTA	790	02/01	(Trn Cxld)		Trespasser Strike
OKJ	716	02/01	49	49	HEP HEP motor stopped and wouldn't start. TASI responded to OKJ and was able to restart HEP engine with the help of Engineer Ohman and Klitzing, C2006
OKJ	718	02/01	2	2	Meet 745, Control Point, north jack london
SAC	743	02/01	1		
SAN	765	02/01	1	1	PTC problem or failure (cause unknown) Other, SAN

Amtrak Initial Terminal Details

26-FOI-00297 00000005671 "UNCLASSIFIED" 2/9/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 2/1/2026

Terminal	Train	Date	Late	Delay	Cause
SJC	746	02/01	2	2	Meet San Jose south told us we would be waiting for one before we could leave SJC., Caltrain, 636, Other, SJC STATION

Eastern Region

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	97.3	97.3	94.8	150	4
CDOT	95.0	62.5	62.5	92.4	16	6
MARC	95.0	75.0	75.0	90.2	12	3
SEPTA	95.0	99.0	99.0	91.5	103	1
NJT-NED	95.0	82.3	82.3	93.8	192	34
NJT-SED	95.0	100.0	100.0	97.2	24	0

Operating Highlights

Wilson, NC - Frozen Switches

02FEB26: Train 97(01) and Train 98(01) both incurred significant delay as they traversed the CSX South End Subdivision in Wilson, NC due to a series of frozen switches. CSX dispatched MOW crews to resolve the issues.

Train	Delay	Comment
97(01)	2'04"	
98(01)	2'07"	

Train 135(01) - New Haven, CT - Car Failure

02FEB26: Train 135(01) was delayed at New Haven Station/MP 72.2 due to an issue impacting traction power and HEP. Mechanical crews took HEP down for a few moments while they worked to resolve the issue. It was found that 480 cables between the engine and first car (81540) needed to be replaced.

Train	Delay	Comment
135(01)	39"	

Train 68/64(01) - Rensselaer, NY - Servicing

02FEB26: Combo Train 64/68(01) was delayed departing Albany-Rensselaer Station due to late servicing of the equipment before it traveled south to New York Penn Station. The Albany Yardmaster advised required regular inspections and servicing were the cause for the delay.

Train	Delay	Comment
68/64(01)	2'01"	

Train 2275(01) - Boston, MA - Servicing

02FEB26: Train 2275(01) was delayed at its initial terminal at Boston South due to late servicing. The commissary restock, dumping and watering were delayed.

Train	Delay	Comment
2275(01)	45"	

Train 19(01) - Charlottesville, VA - Recrew

02FEB26: Train 19(01) 26-FEB-2026 0000005871 Charlottesville/MP 112.2 on the Norfolk Southern Danville/Alexandria-Montview Subdivision due to holding for Engineer recrew. The recrew was delayed due to a mix up with the engineer's transportation to the train at CVS.

Train	Delay	Comment
19(01)	1'05"	

Train 132(01) - Old Saybrook, CT - Engine Failure

01FEB26: Train 132(01) became disabled on the Amtrak New Haven to Boston Line at Old Saybrook Station/MP 105.1. The train lost HEP. The crew consulted with RFE Williams and CNOC Mechanical. A trainline issue was discovered and resolved, which restored HEP. Service recovery was initiated. Amtrak Police responded to the train.

Train	Delay	Comment
132(01)	1'10"	

Train 52(01) - Sanford, FL - Weather

01FEB26: Train 52(01) was delayed at its initial terminal at Sanford, FL due weather related issues with offloading train 53(31).

Train	Delay	Comment
52(01)	1'32"	

Train 53(01) Lorton, VA - Initial Terminal Delay

01FEB26: Train 53(01) was delayed departing Lorton on the CSX RF&P subdivision due to late loading cars.

Train	Delay	Comment
53(01)	9'27"	

Train 49(01) New York, NY - Initial Terminal Delay

01FEB26: Train 49(01) was delayed departing New York due to a late makeup utilizing 98(31) equipment, which arrived New York at 105PM-ET, 2 hours, and 25 minutes late. The delay was hampered due to a track car disabled in line 1, which caused the equipment to be held at Penn Station until a rescue engine was able to clear the track equipment. The equipment arrived to Sunnyside yard at 345PM-ET to be turned and serviced.

Train	Delay	Comment
49(01)	6'38"	

Train 97(01) New York, NY - Initial Terminal Delay

01FEB26: Train 97(01) was delayed departing New York due to late makeup and it being necessary to add a sleeper car from the cancelled train 80 equipment. Once the equipment was made up and set in the station, 168 passengers were welcomed aboard, and 97(01) departed New York at 444PM-ET, 2 hours, and 14 minutes late. Diner C/68021 was bad ordered and deadhead in line. Customer service recovery was provided from the lounge car with a plan to add food enroute downline.

Train	Delay	Comment
97(01)	2'14"	

Train 284(01) Albany-Kenilworth, NY - Car Failure

01FEB26: Train 284(01) was delayed departing Albany on the Amtrak Hudson Main Line due to C/82509 with 480 issues. As a result, Albany swapped equipment and 284(01) departed Albany at 236PM-ET, 1 hour, and 31 minutes late. Due to late operation, train 237(01) was delayed departing New York due to this late turn of equipment.

Train	Delay	Comment
284(01)	1'16"	
237(01)	52"	

Train 145(01) New York, NY - Car Failure

01FEB26: Train 145(01) was delayed departing New York due to a late makeup as it was necessary to add two coach cars from the cancelled train 79 equipment. Once made up and set in the station, 496 customers were welcomed aboard, and train 145(01) departed New York at 132PM-ET, 37 minutes late.

Train	Delay	Comment
145(01)	37"	

Train 105(01) New York, NY - Initial Terminal Delay

01FEB26: Train 105(01) was delayed departing New York due to it being necessary to loop the equipment that arrived with a single locomotive due to a high locomotive shop count in Washington. Once the equipment was looped and set in the station, 584 customers were welcomed aboard, and 105(01) departed New York at 144PM-ET, 1 hour, and 20 minutes late.

Train	Delay	Comment
105(01)	1'20"	

Train 155(01) South of Baltimore, MD - Defect Detector Actuation

01FEB26: Train 155(01) was delayed seven miles south of Baltimore on the Amtrak Philadelphia to Washington Main Line at MP 102.7 due to a HBD alarm on C/43366. The crew inspected the consist and reported no exceptions. The alarm was unable to be silenced. As a result, 155(01) continued to Washington at 80mph.

Train	Delay	Comment
155(01)	17"	Reduced speed
155(01)	29"	S/BAL
143(01)	08"	
140(01)	09"	

Train 24(01) West of Mobile, AL - Freight Train Interference

01FEB26: Train 24(01) was delayed 19 miles west of Mobile on the CSX NO&M subdivision at Elmo/MP 658.6 due to meeting M605-30.

Train	Delay	Comment
24(01)	59"	

Train 161(01) East of New London, CT - Engine Failure

01FEB26: 1125AM-ET, Train 161(01) with E/630 was delayed one and a half car lengths east of New London/ MP 122.9 on the Amtrak New Haven to Boston Main Line due to E/630 with the roof hatch undone and fused to the bus bar. Both pantographs were reported down with a loss of head end power. There were 348 passengers on board and the ambient temperature was 18 degrees. There were no reported injuries to the passengers or the crew. Amtrak police, road foreman, and ET personnel responded to the scene to assist. There was no reported wire damage. A plan was implemented and train 87(01) rescued train 161(01) passengers enroute to New Haven. Due to standee conditions onboard train 87(01), some passengers were instructed to alight in New Haven and either board the next available service or wait for the delayed Train 161(01). CDOT equipment 1713, two cars, and 6703 was dispatched from New Haven to rescue 161(01) equipment and bring it to New Haven. At New Haven, E/658 was added to the consist and 161(01) continued to Washington. During the service disruption, multiple trains were delayed operating through the area due to single track conditions; west bound trains 87(01), 2265(01), and 149(01) fleeted first, followed by 160(01), 162(01), CDOT extra rescue set, 2250(01), and 2248(01). Trains 2255(01) and 135(01) were delayed holding for the east bounds to clear. Additionally, subsequent turns of equipment were delayed due to the late operation of these trains.

Train	Delay	Comment
2226(01)	1'06"	
2259(01)	1'17"	
139(01)	1'18"	
165(01)	2'23"	
135(01)	2'05"	
2255(01)	1'08"	
2250(01)	40"	
2248(01)	1'15"	
162(01)	1'06"	
160(01)	2'44"	
149(01)	16"	
2265(01)	2'12"	
87(01)	47"	
161(01)	6'25"	

Train 240(01) Albany-Rensselaer, NY - Initial Terminal Delay

01FEB26: Train 240(01) was delayed departing Albany on the Amtrak Hudson Main Line due to a late release for frozen equipment. Once the equipment was released and set in the station, 173 customers were welcomed aboard, and 240(01) departed Albany at 1203PM-ET, 48" late. As a result, train 291(01) was delayed departing New York due to the late turn of this equipment.

Train	Delay	Comment
240(01)	48"	
291(01)	42"	

Train 460(01) New Haven, CT - Initial Terminal Delay

01FEB26: Train 460(01) was delayed departing New Haven due to short turning equipment from 461(01). Once the equipment was turned and serviced, 37 customers were welcomed aboard, and 460(01) departed New Haven at 1202PM-ET, 1 hour, and 2 minutes late.

Train	Delay	Comment
460(01)	1'02"	

Train 121(01) New York, NY - Initial Terminal Delay

01FEB26: Train 121(01) was delayed departing New York due to Map 100 paperwork issues. The delay was hampered due to ice patrol on Line 4. Once the Map 100 was up to date and ice patrol was clear, 121(01) welcomed 527 passengers aboard, and departed New York at 103PM-ET, 2 hours, and 34 minutes late. As a result, train 122(01) was delayed departing Washington due to the late turn of this equipment.

Train	Delay	Comment
121(01)	2'34"	
122(01)	1'39"	

Train 118(01) Washington, DC - Engine Failure

01FEB26: Train 118(01) was delayed departing Washington due to a high locomotive shop count. E/660 was identified and added to the consist. Train 118(01) departed Washington at 1031AM-ET, 31 minutes late. Train 154(01) was delayed for the same reason and utilized E/643 from inbound 89(01). Train 154(01) departed Washington at 1053AM-ET, 33 minutes late.

Train	Delay	Comment
118(01)	31"	
154(01)	33"	

Train 2265(01) Boston, MA - Initial Terminal Delay

01FEB26: Train 2265(01) was delayed departing Boston on the Amtrak New Haven to Boston Main Line due to onboard alarms PC/2121 and C/3472 and necessary to go back to the yard to clear the alarms. Train 2265(01) departed Boston at 1007AM-ET, 42 minutes late.

Train	Delay	Comment
2265(01)	42"	

Train 450(01) New Haven, CT - Initial Terminal Delay

01FEB26: Train 450(01) was delayed departing New Haven due to late makeup of equipment and necessary to loop the locomotive. Once the equipment was made up, 45 passengers were welcomed aboard, and 450(01) departed New Haven at 1040AM-ET, 1 hour, and 45 minutes late.

Train	Delay	Comment
450(01)	1'45"	

Train 98(01) North of Miami, FL - M of W Work

01FEB26: Train 98(01) was delayed after departing Miami on the SFRTA Miami subdivision due to a broken rail at Tompkins/MP 1031.6.

Train	Delay	Comment
98(01)	30"	

Train 290(01) Burlington, VT - Car Failure

01FEB26: Train 290(01) 26-FEB-2026 E/0000005671ive "UNCLASSIFIED" E/2/9/2026 originated at Albany with no alternate transportation due to only one operable door on the equipment in Burlington. Train 290(01) equipment deadhead Burlington to Albany. Train 290(01) was delayed departing Albany due to a late makeup. Once the equipment was made up and set in the station, 116 customers were welcomed aboard, and 290(01) departed Albany at 611PM-ET, 3 hours, and 23 minutes late. As a result, train 241(01) was delayed departing New York due to the late turn of this equipment.

Train	Delay	Comment
290(01)	3'23"	
241(01)	2'23"	

Amtrak Keystone Service - Cab Car Failure

01FEB26: Multiple trains were delayed due to operating without a cab car or operating with a defective cab car. Trains wyeed at the necessary locations due to the circumstances.

Train 663(02) with E/615, four cars, and CC/9643 was delayed departing New York due to air brake issues with CC/9643. As a result, CC/9643 was removed from the consist. Once the equipment was made up, the delay was prolonged due to ice patrol on line 4. The equipment arrived Penn Station, the crew welcomed 123 customers onboard, and 663(01) departed New York at 102PM-ET, 3 hours, and 53 minutes late. As a result, train 615(01) turned for train 670(01) at Harrisburg. Train 670(01) departed Harrisburg at 346PM-ET, 1 hour, and 41 minutes late. The Harrisburg protect set was utilized for train 672(01), which departed Harrisburg on-time. Train 663(01) equipment remained in Harrisburg as the protect set.

Train	Delay	Comment
661(01)	21"	
669(01)	24"	
666(01)	05"	HAR
666(01)	33"	PHL
664(01)	15"	
667(01)	27"	
663(01)	3'53"	NYP - set out CC/9643
663(01)	26"	PHL
670(01)	1'41"	HAR - turned off 615(01)
672(01)	24"	

Lake Shore Limited Service Adjustments - Shopped Equipment

31JAN26: Due to shopped equipment Lake Shore Limited Service Adjustments were necessary as follows:

Train 448(31) terminated at Albany, NY , cancelled between Albany, NY and Boston, MA with alternate bus transportation provided.

Train 449(02) originated at Albany, NY, cancelled between Boston, MA and Albany, NY, with alternate bus transportation provided.

Train 449(01) originated at Albany, NY, cancelled between Boston, MA and Albany, NY. with alternate bus transportation provided.

Train 448(02) terminated at Albany, NY, cancelled between Albany, NY and Boston MA, with alternate bus transportation provided.

Acela Cancellations - Shopped Equipment

30JAN26: Due to multiple Acela sets "UNCLASSIFIED" due to wheel wear, cab signal issues and a current high shop count, causing shop congestion with limited material, multiple Acela trains were canceled until shop counts improve.

-Acela Trains 2153, 2155, 2192, 2167, 2150, 2171, 2107, 2192, 2108, 2121, 2150, 2168, 2170, 2122, 2126(30) were canceled in entirety.

-Acela Trains 2249, 2255, 2252, 2201, 2218(31) were canceled in entirety.

-Acela Trains 2292, 2257, 2256, 2295, 2252, 2207, 2222(01) were canceled in entirety.

-Acela Trains 2153, 2168, 2150, 2171, 2192, 2167, 2124(02) were canceled in their entirety.

Empire Cancellations High Shop Counts - Engine Failure

30JAN26: The following service adjustments are in affect due to high shop counts in Albany-Rensselaer, NY.

Cancelled In Entirety

236-238-244-233-235(31, 01, 02)

245(31, 01)

243(02)

69(31, 01, 02) - TERM ALB; cancelled ALB - MTR - No ALT transportation

68(31, 01, 02, 03) - ORIG ALB; cancelled MTR-ALB - No ALT transportation

Winter Storm Gloria Cancellations

29JAN26: Due to Winter Storm Gloria the following adjustments are in the place:
26-FOI-00297 00000005671 UNCLASSIFIED 2/19/2026
Floridian Service:

- Train 41(30) is cancelled entirely with no alternate between Chicago and Miami.
- Train 40(30) is cancelled entirely with no alternate between Miami and Chicago.
- Train 41(31) will originate at Jacksonville, FL to operate to Miami. No alternate between Chicago and Jacksonville.
- Train 40(31) will terminate at Jacksonville, FL with no alternate between Jacksonville and Chicago.

Palmetto:

- Train 89, 90 (31) cancelled in their entirety, no alternate transportation

Virginia Service

- Train 65(30) will terminate at Richmond-Staples Mill, VA, cancelled between Richmond-Staples Mill and Newport News, VA, no alternate transportation *Equipment will represent Train 124(31)*
 - Train 99(31) will terminate in Richmond-Staples Mill, VA, cancelled Richmond-Staples Mill, VA and Newport News, VA, no alternate transportation *Equipment will represent Train 164(01)*
 - Train 87(31) will terminate in Washington, DC, cancelled Washington to Norfolk, VA, no alternate transportation *Equipment will represent Train 128(31)*
 - Train 124(31) will originate in Richmond-Staples Mill, VA, cancelled Newport News, VA to Richmond-Staples Mill, VA, no alternate transportation.
 - Train 128(31) will originate in Washington, DC, cancelled Norfolk, VA to Washington, no alternate transportation.
- Trains 71, 72, 77, 78 (31) cancelled in their entirety

February 1st Cancellations

Carolinian

- Trains 79, 80 (01) cancelled in their entirety, no alternate transportation

Piedmont

- Trains 71, 72, 75, 76 (01) cancelled in their entirety

Virginia Service

- Train 164(01) will originate in Richmond-Staples Mill, VA, canceled Newport News, VA to Richmond-Staples Mill, VA, no alternate transportation.

WBS#: B.TR.100150.6446

Train 51(01) New York, NY - Scheduled M/W Work

2/9/2026

01FEB26: Train 51(01) was delayed departing New York due to line 1 out of service, which resulted in a late release from Sunnyside yard.

Train	Delay	Comment
51(01)	53"	

Crescent NS Gulf Division TW - Scheduled M/W Work

10OCT25: To accommodate the above outlined infrastructure work, Amtrak's Crescent Service will be adjusted as follows:

- Train 19 (5Jan-7Jan, 11Jan-14Jan, 18Jan-21Jan, 25Jan-28Jan, 1Feb-4Feb, 8Feb-11Feb, 16Feb-18Feb, 22Feb-25Feb, 1Mar-4Mar), which normally operates between NYP and NOL, will terminate at ATL.
- Train 20 (6Jan-8Jan, 12Jan-15Jan, 19Jan-22Jan, 26Jan-29Jan, 2Feb-5Feb, 9Feb-12Feb, 17Feb-19Feb, 23Feb-26Feb, 2Mar-5Mar), which normally operates between NOL and NYP, will originate at ATL.

ALTERNATE TRANSPORTATION:

- Local Bus 3119 will provide alternate transportation between ATL and NOL, making all scheduled station stops.
- Express Bus 3019 will provide alternate transportation from ATL to NOL only.
- Local Bus 3120 will provide alternate transportation between NOL and ATL, making all scheduled station stops.
- Express Bus 3020 will provide alternate transportation from NOL to ATL only.

Weekly Friday through Sunday (This INCLUDES Monday February 16th) - No Track Work Scheduled:

- Trains 19 & 20 will operate normal schedule and route between Atlanta and New Orleans.
- Trains may incur delays of 20-30 minutes operating through the track work area, due to residual slow orders and congestion.

WBS#: B.TR.100150.6165

Long Bridge Replacement Outage - Scheduled M/W Work

18DEC25: Starting January 26, 2026, the replacement trackwork will commence causing reduced service and schedule changes through March 08, 2026 as follows:

January 11th will commence transition plan with 195 terminating New York and 153 terminating Washington D.C.

Monday through Friday: 114 cancelled, 133 cancelled, 141 terminates Washington D.C., 85 terminates Washington D.C., 176 originates Washington D.C., 174 originates Washington D.C., 84 originates Washington D.C., 134 originates Washington D.C., 86 originates Newport News, VA, 178 originates Roanoke, VA.

New trains operating Monday through Friday : 113 originating New York, NY and 198 originating Washington D.C.

Saturday: 167 terminates Philadelphia, PA, 153 terminates Washington D.C., 195 terminates Washington D.C., 155 operates through to Norfolk, VA, 164 originates Newport News, VA, 194 originates Washington D.C., 128 originates Norfolk, VA, 88 originates Washington D.C., 82 originates Washington D.C.

New train operating Saturday: 109 originates New York, NY

Sunday: 106 cancelled, 107 cancelled, 157 terminates Washington D.C., 155 operates through to Norfolk, VA, 195 terminates Washington D.C., 128 originates Norfolk, VA, 96 originates Washington D.C., 88 originates Washington D.C.

New trains operating Sunday: 117 originates Philadelphia, PA, 100 originates Washington D.C.

WBS#: B.TR.100150.6327

Eastern Region

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 3(01) East of Newton, KS - Passenger Train Interference

02FEB26: Train 3(01) was delayed at Walton Siding/MP176.4 9 miles east of Newton, KS/MP185.5 on the BNSF La Junta subdivision meeting Amtrak train 4(31). Once the route was clear, train 3(01) continued west.

Train	Delay	Comment
3(01)	30"	

Train 748(01) East of Davis, CA - Struck Bicycle

02FEB26: Train 748(01), with cab car CDTX8310, engine CDTX2003, 4 cars, and 62 passengers, struck an unmanned bicycle in Davis, CA/MP78.6 3 miles east of Davis Station, CA/MP75.5 on the UP Martinez subdivision. There were no injuries reported by the passengers or crew. There was no damage reported to the equipment. HEP remained active until intentionally shut down briefly for the crew to reattach an air hose. Once air pressure was restored, train 748(01) continued east.

Train	Delay	Comment
748(01)	22"	

Train 14(01) Oakland, CA - Servicing

02FEB26: Train 14(01) was routed into Oakland Yard after departing Jack London Station, CA/MP7.1 on the UP Niles subdivision due to a program move to cut off the rear car 38039 to restore a protect in Oakland, CA. Oakland Mechanical also attempted to restore the HVAC in sleeper car 32051 but was unable. Once the program move was complete, train 14(01) continued to Emeryville, CA.

Train	Delay	Comment
14(01)	47"	

Train 58(01) South of Newbern-Dyersburg, TN - Freight Train Interference

02FEB26: Train 58(01) was delayed at Rialto/MP347.6 42 miles south of Newbern-Dyersburg, TN/MP305.6 on the CN Fulton subdivision meeting multiple CN freights, CN/2282 and CN/8904. Once the route was clear, train 58(01) continued north.

Train	Delay	Comment
58(01)	30"	

Train 777(01) Santa Barbara, CA - Passenger Train Interference

01FEB26: Train 777(01) was delayed south of Santa Barbara, CA (SBA) at CP S. Santa Barbara on the Union Pacific Railway Santa Barbara Subdivision. Train 777(01) was held for opposing train 11(01) to clear the track ahead. Once the track ahead was clear, train 777(01) was able to proceed.

Train	Delay	Comment
777(01)	43"	

Train 7/27(01) East of St. Paul-Minneapolis, MN - Freight Train Interference

02FEB26: Train 7/27(01) was delayed at "UNCLASSIFIED"/MP218.1 18 miles east of St Paul-Minneapolis, MN/MP410.3 on the CPKC River subdivision meeting multiple BNSF freights, BN/6632 and BN/4644. Once the route was clear, train 7/27(01) continued west.

Train	Delay	Comment
7/27(01)	31"	

Train 306(01) South of Chicago, IL - Freight Train Interference

02FEB26: Train 306(01) was delayed at 21st Street/MP1.61 1.61 miles south of the Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision meeting NS freight 33G. NS 33G was having trouble with the key to line switches in the yard. Once the route was clear, train 306(01) continued north.

Train	Delay	Comment
306(01)	45"	

Train 21/421(01) North of Arcadia, MO - Deer Strike

02FEB26: Train 21/421(01), with engine 59, 8 cars, and 72 passengers, struck a deer at Mineral Point/MP61.6 17 miles north of Arcadia, MO/MP88.8 on the UP Desoto subdivision. There were no injuries reported by the passengers or crew. There was no damage reported to the equipment. HEP remained active until intentionally shut down briefly for the crew to reattach an air hose. Once air pressure was restored, train 21/421(01) continued south.

Train	Delay	Comment
21/421(01)	06"	

Train 22(01)/422(30) West of Longview, TX - Freight Train Interference

01FEB26: Train 22(01)/422(30) was delayed at East Glade Water/MP104.0 14.5 miles west of Longview, TX/MP89.5 on the UP Mineola subdivision meeting an UP freight. Once the route was clear, train 22(01)/422(30) continued north.

Train	Delay	Comment
22(01)/422(30)	34"	

Train 716(01) Oakland, CA - Third Party Contractor Engine Failure

01FEB26: Train 716(01) was delayed departing the initial terminal of Oakland, CA (OKJ) on the Union Pacific Railway Niles Subdivision. Locomotive CDTX/2006 stopped providing Head End Power (HEP) prior to departure. Passengers were evacuated into the station while the crew worked with TASI Mechanical Contractors to resolve the issue. Once the issue was resolved and passengers boarded, train 716(01) departed OKJ at 3:07 PM-PT.

Train 716(01) incurred additional delays at Stockton, CA (SKN) on the Burlington Northern Santa Fe Railway Stockton Subdivision. Locomotive CDTX/2006 failed to provide HEP a second time. Members of the train crew were able to resolve the issue, and train 716(01) departed SKN at 5:16 PM-PT.

Train	Delay	Comment
716(01)	49"	OKJ
716(01)	24"	SKN

Train 4(31) West of Raton, NM - Unruly Passenger

01FEB26: Train 4(31) was delayed approximately 10 miles west of Raton, NM on the BNSF Raton subdivision meeting Springer police and EMS to assess two passengers, PNR# 6D4593 and 6E8CCE, who were creating a disturbance. Springer police attempted to deescalate the situation but both passengers were ultimately arrested and removed from the train. Train 4(31) continued into Ration, NM.

Train	Delay	Comment
4(31)	1'23"	

Train 769(01) Santa Barbara, CA - Trespasser Incident

01FEB26: At approximately 1:42 PM-PT train 769(01) - operating with camera equipped locomotive CDTX/2112 and six cars - struck and fatally injured a trespasser on the tracks at MP 368.46 on the Union Pacific Railway Santa Barbara Subdivision in the City of Santa Barbara, Santa Barbara County, California. This incident did NOT occur on a public highway crossing at grade. Train 769(01) was operating north on the main track at an estimated 42 MPH at the time the incident occurred. There were no reports of injuries to 150 passengers or crew. Local Authorities and Amtrak Management responded to the scene. Once released train 769(01) advanced to and was terminated at Santa Barbara, CA (SBA) with remaining passengers being provided a bus from Santa Barbara, CA (SBA) to Goleta, CA (GTA). Account extended delays the following adjustments were made to Pacific Surfliner Service:

-769(01) Terminate Santa Barbara, CA - Passengers provided bus to Goleta, CA.

-790(01) Originate Los Angeles, CA - Passengers scheduled to board between Goleta, CA and Los Angeles, CA were fare protected and able to modify reservations for alternate departures.

Google Maps Location of Incident:

<https://maps.app.goo.gl/DcjShFL5wsuDJfTB7>

34.418131, -119.676176

East Beach, Santa Barbara, CA 93103

National Response Center: 1453878

California Office of Emergency Services: 26-0523

WBS#: B.TR.100150.6448

National Response Center Number: 143878

Train	Delay	Comment
769(01)	Terminate SBA	Pax on bus SBA-GTA
769(01)	1'17"	
790(01)	Originate LAX	Pax provided fare protection and able to book alternatives

Train 41(01) Chicago, IL - Engine Failure

02FEB26: Train 41(01), with engines 303 and 201, 11 cars, and 261 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due the late release of the equipment by Chicago Mechanical. Once the equipment shoved into the depot and passengers were boarding, the crew requested additional mechanical assistance refilling the windshield wiper fluid. Once the windshield wiper fluid was filled, train 41(01) departed Chicago, IL.

Train	Delay	Comment
41(01)	37"	

Train 58(01) South of Greenwood, MS - Freight Train Interference

02FEB26: Train 58(01) was delayed at Greenwood/MP129.2 miles south of Greenwood, MS/MP122.5 on the CN Yazoo subdivision meeting CN freight trains G889 and 320. Once the route was clear, train 58(01) continued north.

Train	Delay	Comment
58(01)	42"	

Train 573(01) Santa Ana, CA - Police Related

01FEB26: Train 573(01) was delayed at Santa Ana, CA (SNA) on the Southern California Regional Rail Authority Orange Subdivision. Train crew had requested police assistance to remove a disruptive passenger. Once the passenger was removed, train 573(01) was able to proceed, departing SNA at 1:47 PM-AZ.

Train	Delay	Comment
573(01)	44"	

Train 370(01) Chicago, IL - Car Indicator Lights

02FEB26: Train 370(01), with engine IDTX4627, 4 cars, and 91 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late shopping of car IDTX4014 for non-working brake indicator lights. IDTX4008 was added as a replacement. The yard crew requested mechanical assistance to reseal the door bypass feature on engine IDTX4627. Once train 370(01) shoved into the depot and boarded passengers, the crew reported a trainline fault. Train 370(01) departed Chicago, IL once the issue was resolved.

Train	Delay	Comment
370(01)	07"	Trainline fault at the depot
370(01)	1'39"	B/O IDTX4014

Train 8/28(31) East of Libby, MT - Freight Train Interference

01FEB26: Train 8/28(31) was delayed at Brimstone/MP1253.9, 65 miles east of Libby, MT, on the BNSF Kootenai River Subdivision, meeting BNSF 8096 and BNSF 8136.

Train	Delay	Comment
8/28(31)	39"	

Train 2(30) East of San Antonio, TX - Freight Train Interference

01FEB26: Train 2(30) was delayed at Weimar/MP101.1, 108 miles east of San Antonio, TX, on the UPRR Glidden Subdivision, meeting UP 5809 and UP 7785.

Train	Delay	Comment
2(30)	38"	

Train 8/28(30) East of St. Paul-Minneapolis, MN - Switch Failure

01FEB26: Train 8/28(30) was delayed at St. Croix/MP392.1, 18 miles east of St. Paul-Minneapolis, MN, on the CPKC River Subdivision, due to power switch failure. Train 8/28(30) was delayed hand lining switches and operating through the affected area.

Train	Delay	Comment
8/28(30)	39"	

Train 59(31) Jackson, MS - CN Dispatch System Outage

01FEB26: Train 59(31), 26-FCI-002971270000005674 Passenger UNCLASSIFIED delay 2/8/2026 Jackson, MS/MP728.7, on the CN McComb Subdivision, due to CN dispatch system issues. CN reported sporadic brown outs across the Southern Region began at approximately 1140AM-CT. Initial troubleshooting efforts were unsuccessful. AT 1230PM-CT CN reported RTC's unable to control any functions within the system and issue was escalated. Train 59(31) was delayed at Jackson holding for dispatch systems to be restored. 130PM-CT CN system restored and Train 59(31) was able proceed south. Train 391(01) was also delayed as a result of the CN system issues and held at Centralia, IL/MP252.3, on the CN Centralia Subdivision, until system restored.

Train	Delay	Comment
59(31)	1'50"	
391(01)	27"	

Train 48/448(31) West of Elkhart, IN - Freight Train Interference

01FEB26: Train 48/448(31) was delayed at MP426, 5 miles west of Elkhart, IN, on the NS Elkhart West Subdivision, meeting NS276. Train 48/448(31) was further delayed at MP255, 32 miles east of Toledo, OH, on the NS Toledo East Subdivision, operating restricted speed due to a possible broken rail in area.

Train	Delay	Comment
48/448(31)	51"	W/EKH, MP426
48/448(31)	40"	E/TOL, MP255

Train 14(31) South of Chico, CA - Police Related

01FEB26: Train 14(31) was delayed just south of Chico, CA/MP184.1, on the UPRR Valley Subdivision, due to a hold in effect ahead at MP184.12 due to an auto accident with possible concrete debris on/near the track. Train 14(31) held for track inspection and open route ahead.

Train	Delay	Comment
14(31)	50"	

Train 702(01) Lodi, CA - Third Party Contractor Engine Failure

01FEB26: Train 702(01), CC/6962-5 cars-E/CDTX2106, with 52 passengers, was delayed at Lodi, CA/MP71.8, on the UPRR Fresno Subdivision, due to HEP dropped and alarms on E/CDTX2106. Crew reported alarms silenced and HEP restored. As Train 702(01) began to pull to depart Lodi, HEP dropped again. Crew short-looped between the rear car, C/C6361 and E/CDTX2106, on the fireman's side and restored HEP.

Train	Delay	Comment
702(01)	30"	

Train 7/27(31) East of Staples, MN - Switch Issues

01FEB26: Train 7/27(31) was delayed at Philbrook/MP134, 14 miles east of Staples, MN, on the BNSF Staples Subdivision, due to switch issues. Train 7/27(31) was delayed hand lining power switch and swing nose frog and operating restricted speed through the area.

Train	Delay	Comment
7/27(31)	35"	

01FEB26: Train 22(30) 26-FOI-00297, 00000005671 MP43 UNCLASSIFIED Files 2/19/2026h of Arcadia, MO, on the UPRR DeSoto Subdivision, due to an auto on the track ahead. Train 22(30) held for auto removal and track inspection to be completed.

Train	Delay	Comment
22(30)	47"	

Train 21(31) South of Little Rock, AR - Freight Train Interference

01FEB26: Train 21(30) was delayed at Haskell/MP373.2, 28 miles south of Little Rock, AR, on the UPRR Little Rock Subdivision, due to ILBMN-28 (UP 9045) ahead setting out mid DPU unit due to mechanical issues. Train 21(30) held for UP 9045 to complete set out and operate in the clear, and was then further delayed meeting UP 5841.

Train	Delay	Comment
21(31)	1'41"	

Chicago Delays / Cancellations - Frozen Equipment

28JAN26: Multiple trains were delayed or cancelled in Chicago, IL as a result of frozen equipment and late releases from mechanical.

29JAN26: Due to extreme weather, cancellations are now extended on the Midwest Corridor State supported trains through 01FEB.

31JAN26: Pere Marquette Service has been restored reinstating Train 370(31) and Train 371(01) to run live as a train.

01FEB26: Due to ongoing extreme weather, Midwest Corridor State supported adjustments for Blue Water service extended through 02FEB.

DELAYS:

-Train 329(28), E/139-3 Cars-E/ID4618, departed Chicago, IL 1 hour and 54 minutes late account frozen equipment and traction motor issues. Once the equipment was thawed, additional delay was incurred due to traction motor issues with engine 139. Chicago Mechanical responded to the train and was able to resolve the issue.

-Train 301(28), E/ID4613-5 Cars, departed Chicago, IL 2 hours and 37 minutes late as a result of frozen equipment. Mechanical was able to get all cars except business class car ID4210 to thaw for service. The business class car ID4210 deadheaded in line which resulted in 21 business class passengers downgraded to coach. Additional delay holding in the station for commissary to stock the train.

-Train 3(28) E/199, E/55, and 6 cars departed Chicago, IL 1 hour and 28 minutes late account of the late release of E/55 that needed to be thawed in the diesel pit.

-Train 5(28) E/76, E/194, and 8 cars departed Chicago, IL 1 hour and 38 minutes late account of replacing bad order diner car 38061 for refrigeration issues. It was necessary to switch Train 7/28(28) first and complete the drain and blow on the bad order car. Diner car 38061 was replaced with diner-lounge car 37009.

-Train 7/27(28) E/58, E/343, E/340 and 9 cars departed Chicago, IL 2 hours and 34 minutes late account of weather issues. Train 7/27(28) was made up with a replacement diner, coach and sleeper. Once released, and after two engines were wyed, it was necessary for the pit to complete the daily inspection on E/343. the consist was watered and it was reported that they did not have a working dishwasher would would needed stock from the commissary to accommodate.

Train 41(28) E/48, E/163 and 10 cars departed Chicago, IL 3 hours and 15 minutes late as a result replacing an ogontz valve in sleeping car 62034, thawing frozen toilets in sleeping car 62044 and sleeping car 62503 was bad ordered due to a busted pipe and freeze damage. With no sleeping car replacement, 22 passengers were downgraded to coach seating. Train 41(28) used E/48 and E/163 off Train 6(26) which arrived at 214P-CT and had to be serviced.

Wolverine:

- Train 352(28JAN) cancelled with two alternate buses secured.
- Trains 350-351-352-354-355(29JAN) cancelled with alternate buses secured.
- Trains 352-354(30JAN-02FEB) cancelled - sourcing alternate transportation.
- Trains 351-353(30JAN-03FEB) cancelled - sourcing alternate transportation.

Blue Water:

- Train 364(28JAN-02FEB) cancelled - sourcing alternate transportation.
- Train 365(29JAN-03FEB) cancelled - sourcing alternate transportation.

Pere Marquette ***31JAN: Services have been restored reinstating Train 370(31) and Train 371(01) to run live as a train**

- Train 370(28JAN-30JAN) cancelled - sourcing alternate transportation.
- Train 371(29JAN-31JAN) cancelled - sourcing alternate transportation.

Lincoln Service

- Train 300(29JAN-03FEB) cancelled - sourcing alternate transportation.
- Train 302(29JAN-03FEB) cancelled - sourcing alternate transportation.
- Train 305(28JAN-02FEB) cancelled - sourcing alternate transportation.
- Train 307(28JAN-02FEB) cancelled - sourcing alternate transportation.

Illinois Zephyr

- Train 383(28JAN-02FEB) cancelled - sourcing alternate transportation.
- Train 380(29JAN-03FEB) cancelled - sourcing alternate transportation.

WBS#: B.TR.100150.6442

Train	Delay	Comment
301(28)	2'21"	ITD CHI
329(28)	1'54"	ITD CHI
3(28)	1'28"	ITD CHI
5(28)	1'38"	ITD CHI
7/27(28)	2'34"	ITD CHI
41(28)	3'15"	ITD
301(01)	23"	CHI, ITD

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

-Train 736(25-28) Cancelled - No alternate transportation. UNCLASSIFIED//
2/9/2026

-Train 737(25-28) Cancelled - No alternate transportation.

-Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

-Train 520(29-30) Cancelled - No alternate transportation.

-Train 534(29-30) Cancelled - No alternate transportation.

-Train 535(29) Cancelled - No alternate transportation.

-Train 537(30) Cancelled - No alternate transportation.

-Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DEC25

-Train 520(31) Cancelled - No alternate transportation.

-Train 534(31) Cancelled - No alternate transportation.

-Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

-Train 736(01-04) Cancelled - No alternate transportation.

-Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 05MAR26

- TRAIN 714(05JAN-06MAR) Cancelled - No alternate transportation.

- TRAIN 713(06JAN-07MAR) Cancelled - No alternate transportation.

10JAN26 - 11JAN26

-Train 736(10-11) Cancelled - No alternate transportation.

-Train 737(10-11) Cancelled - No alternate transportation.

12JAN26 - 13JAN26

-Train 520(12-13) Cancelled - No alternate transportation.

-Train 534(12-13) Cancelled - No alternate transportation.

-Train 535(12-13) Cancelled - No alternate transportation.

14JAN26:

-Train 520(14) Cancelled - No alternate transportation.

-Train 537(14) Cancelled - No alternate transportation.

-Train 534(14) Cancelled - No alternate transportation.

15JAN26:

-Train 520(15-16) Cancelled - No Alternate Transport offered

-Train 534(15-16) Cancelled - No Alternate Transport offered

-Train 535(16) Cancelled - No Alternate Transport offered

-Train 537(15) Cancelled - No Alternate Transport offered

17JAN26:

-Train 718(17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744(17) OKJ-EMY.

21JAN26:

-Train 526(21) Cancelled - No Alternate Transport offered

-Train 534(21) Cancelled - No Alternate Transport offered

-Train 535(21) Cancelled - No Alternate Transport offered

23JAN26:

-Train 520(23) Cancelled - No Alternate Transport offered

-Train 534(23) Cancelled - No Alternate Transport offered

-Train 535(23) Cancelled - No Alternate Transport offered

-Train 736(23JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 737(23JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 520(26JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 526(26JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 534(26JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 531(26JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 537(26JAN-01MAR) Cancelled - No Alternate Transportation.

-Train 702(01FEB) Cancelled - No Alternate Transportation.
 -Train 712(02FEB-04FEB) 26-FEB-00237 11 00000005673 Alt UNCLASSIFIED 2/9/2026
 -Train 717(02FEB-04FEB) Cancelled - No Alternate Transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate	Passengers to bus 6615 EMY-OKJ-SFC
	EMY	
718(21)	Originate	Passengers to 744(21) OKJ-EMY
	EMY	
718(22)	Originate	Passengers to 544(22) OKJ-EMY
	EMY	
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
714(23)	.	CANCELLED
713(24)	.	CANCELLED
535(24)	Cancelled	
520(24)	Cancelled	
534(24)	Cancelled	
736(25-28)	Cancelled	
737(25-28)	Cancelled	
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
551(29-30)	Cancelled	Replacement Bus SAC-OKJ
520(29-31)	Cancelled	No alternate transportation.
534(29-31)	Cancelled	No alternate transportation.
736(01JAN-04JAN)	Cancelled	No alternate transportation
737(01JAN-04JAN)	Cancelled	No alternate transportation
535(29)	Cancelled	No alternate transportation.
537(30-31)	Cancelled	No Alternate Transportation
713(06JAN-07MAR)	CANCELLED	No Alternate Transport Offered
714(05JAN-06MAR)	CANCELLED	No Alternate Transport Offered
736(10-11JAN)	Cancelled	No Alternate Transport Offered
737(10-11JAN)	Cancelled	No Alternate Transport Offered
520(12-13-14- 15-16 JAN)	Cancelled	No alternate transportation
534(12-13-14-15-16 JAN)	Cancelled	No alternate transportation
535(12-13-16JAN)	Cancelled	No alternate transportation
537(14-15JAN)	Cancelled	No Alternate Transport offered
718(17)	Originate	Pax to 744 OKJ-EMY
	EMY	
718(17)	35"	
526(21Jan)	Cancelled	No alternate transportation
534(21-23JAN)	Cancelled	No alternate transportation
535(21-23JAN)	Cancelled	No alternate transportation
520(23JAN)	Cancelled	No Alternate Transport Offered
736/737(23JAN-01MAR)	Cancelled	No Alternate Transportation
520/526/534/531/537(26JAN-01MAR)	Cancelled	No Alternate Transportation
732(01FEB)	Cancelled	No Alternate Transport
712(01FEB-04FEB)	Cancelled	No Alternate Transport
749(01FEB)	Cancelled	No Alternate Transport
717(01FEB-04FEB)	Cancelled	No Alternate Transport

Western Region

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
8 (15)	SCD	369		Shelled wheels

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (17)	DEN	UP7426	E/163 blower fault	OKJ	1/19/26
5 (30)	LNK	BN9100	E/79 Coolant Leak	OKJ	2/1/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
516	EVR	1	BEL	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
693 (01)	BON	NO BUSINESS CLASS AND NO CAFE-Short equipment	Passengers downgraded to coach	12	NOCAR
699 (01)	BON	NO BUSINESS CLASS AND NO CAFE-Short equipment	Passengers downgraded to coach	12	NOCAR
161 (01)	BOS	82748 will run as deadhead okm car. no sales impact.	n/a	0	82748
87 (01)	BOS	train is 1 coach short. please accomodate over capacity	Passengers notified	0	
149 (01)	BOS	Due to multiple shopped cafe cars, 149(01) will operate with a club-dinette in lieu of an all table cafe.	NONE	0	48183
698 (01)	BRK	NO BUSINESS CLASS AND NO CAFE-Short equipment	Passengers downgraded to coach	12	NOCAR
692 (01)	BRK	NO BUSINESS CLASS AND NO CAFE-Short equipment	Passengers downgraded to coach	12	NOCAR
370 (31)	CHI	Deadhead inline BYD id4130 and	passengers were placed in coach on board tickets already lifted.	5	ID4130, ID4214

Train Number	Station	Reason 26-FOI-00297 00000005671	Customer Impact "UNCLASSIFIED" 2/9/2026	Affected Psgr	Unit Number(s)
		id4214. Sales adjusted to reflect- with over capacities. NO BUSINESS CLASS.			
50 (31)	CHI	deadhead BYD toilets- over capacity	passengers reaccommodate where possible	32	25091
48 (31)	CHI	62009 deadhead inline. 62521 will run live 4811 car. Viewliner II in lieu of Viewliner I.	room change for two pnrs	2	62521
301 (01)	CHI	Trains 301(1) and 306(01) will not have business class seating sue to d/h car id4217 (BYD- toilets).	PASSENGERS NOTIFIED AND DOWNGRADED	21	ID4217
41 (01)	CHI	Team due to a correction with the equipment (62025) it was necessary to perform a schedule change on train 41(01) - line 4111. Please utilize the WAR report to ensure all affected passengers have been	PASSENGERS REACCOMODATED/DOWNGRADED	4	62025
371 (01)	GRR	Deadhead inline BYD	Passengers being downgraded to coach	7	ID4130, ID4214

Train Number	Station	Reason 26-FOI-00297 00000005671	Customer Impact "UNCLASSIFIED" 2/9/2026	Affected Psgr	Unit Number(s)
		id4130 and id4214. Sales adjusted to reflect- with over capacities. NO BUSINESS CLASS.			
371 (02)	GRR	Due to a change in equipment train 371(02) is over capacity in business class seating.	PAX NOTIFIED	2	48184
782 (01)	GTA	NO BIKE SPACE	passenger notifications initiated	4	90225
664 (01)	HAR	no cab car- NOT a push pull set. sales over capacity	passenger notification initiated PHL- NYP	37	NOCAR
612 (01)	HAR	no cab car- NOT a push pull set.	NONE	0	NOCAR
672 (01)	HAR	Consist operating with no cab car, capcity has been reduced by 66 seats.	PAX NOTIFIED OVER CAPACITY	35	
580 (01)	LAX	NO BIKE SPACE	pax notifications	2	90215
98 (01)	MIA	running with only 3 coaches. short equipment	N/A	0	NOCAR
671 (31)	NYP	no cab car due to 9633 being shopped for busted air pipe. Sales	was still slightly over capacity	15	NOCAR

Train Number	Station	Reason 26-FOI-00297 00000005671	Customer Impact "UNCLASSIFIED" 2/9/2026	Affected Psgr	Unit Number(s)
		are adjusted to reflect.			
667 (01)	NYP	no cab car-NOT a push pull set. sales over capacity	Passenger notifications initiated NYP-PHL	66	NOCAR
97 (01)	NYP	Train 97(01) will depart today with only 2 sleepers instead of 3 as required do to BYD sleepers. Hence It was necessary to perform a schedule change to remove the 9710 line. Please utilize the WAR rep	PASSENGERS NOTIFIED AND DOWNGRADED	16	62XXX
637 (01)	NYP	Consist operating with no cab car, capacity has been reduced by 66 seats.	NONE	0	
567 (01)	SAN	NO BIKE SPACE	n/a	0	90215
591 (01)	SAN	NO BIKE SPACE	n/a	0	90215
761 (01)	SAN	NO BIKE SPACE	passenger notification initiated	4	90225
593 (01)	SAN	NO BIKE SPACE	n/a	0	90225
306 (01)	STL	Trains 301(1) and 306(01) will not have business class seating due to d/h car id4217 (BYD-toilets).	PASSENGERS NOTIFIED AND DOWNGRADED	8	ID4217

Reverse Consists

26-FOI-00297

00000005671

"UNCLASSIFIED"

2/9/2026

Train Number	Station	Reason
143 (01)	SPG	Consist reversed Business class seat orientation may have changed At Front
150 (01)	PHL	Consist reversed Business class seat orientation may have changed At Front
151 (01)	PHL	Consist reversed Business class seat orientation may have changed At Front
145 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
103 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
105 (01)	NYP	Consist reversed Business class seat orientation may have changed At Rear
66 (01)	RNK	Consist reversed Business class seat orientation may have changed At Front
158 (01)	NFK	Consist reversed Business class seat orientation may have changed At Front
135 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front
145 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
2265 (01)	BOS	Acela consist reversed First class at Rear DNL on PC2123
2265 (01)	BOS	Acela consist reversed First class at Rear
149 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front