



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, October 21, 2025

Rules: 1-1



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/20/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	43	85.8%	5,849	755	87.1%	5,849	755	87.1%
Central Division	85.5%	65	10	84.6%	1,315	149	88.7%	1,315	149	88.7%
Northeast Division	80.0%	95	10	89.5%	1,822	270	85.2%	1,822	270	85.2%
Southeast Division	72.5%	73	8	89.0%	1,363	130	90.5%	1,363	130	90.5%
Southwest Division	77.0%	70	15	78.6%	1,349	206	84.7%	1,349	206	84.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00072 00000005031 UNCLASSIFIED Endpoint Arrival Dates through 10/20/25 10/29/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	120,874	26,547	78%	2,215,861	415,747	81%	2,215,861	415,747	81%
Northeast Corridor	81%	50,010	8,967	82%	990,248	145,815	85%	990,248	145,815	85%
Acela	83%	12,031	2,286	81%	194,750	29,597	85%	194,750	29,597	85%
Northeast Regional	79%	37,979	6,681	82%	795,498	116,218	85%	795,498	116,218	85%
Richmond / Newport News / Norfolk	77%	10,702	2,812	74%	245,756	41,124	83%	245,756	41,124	83%
Springfield Shuttles	89%	753	119	84%	17,504	1,376	92%	17,504	1,376	92%
Roanoke	79%	2,479	563	77%	62,719	8,067	87%	62,719	8,067	87%
On Spine Northeast Regional	80%	24,045	3,187	87%	469,519	65,651	86%	469,519	65,651	86%
State Supported	80%	48,568	11,289	77%	958,440	179,436	81%	958,440	179,436	81%
Borealis	60%	593	345	42%	13,281	3,378	75%	13,281	3,378	75%
Capitol Corridor	90%	4,220	857	80%	78,309	8,219	90%	78,309	8,219	90%
Carolinian	60%	1,396	613	56%	27,025	8,319	69%	27,025	8,319	69%
Cascades	63%	2,391	311	87%	52,495	14,078	73%	52,495	14,078	73%
Downeaster	82%	1,341	375	72%	34,087	7,962	77%	34,087	7,962	77%
Empire	78%	6,176	1,220	80%	121,601	23,366	81%	121,601	23,366	81%
Adirondack	72%	394	23	94%	8,655	2,496	71%	8,655	2,496	71%
Ethan Allen Express	70%	647	505	22%	13,640	3,904	71%	13,640	3,904	71%
Maple Leaf	70%	714	68	90%	16,674	6,109	63%	16,674	6,109	63%
New York - Albany	85%	2,884	521	82%	52,005	6,401	88%	52,005	6,401	88%
New York - Niagara Falls	75%	1,537	103	93%	30,627	4,456	85%	30,627	4,456	85%
Heartland Flyer	65%	234	223	5%	4,705	3,535	25%	4,705	3,535	25%
Hiawatha	90%	1,762	0	100%	39,623	6,283	84%	39,623	6,283	84%
Illinois	78%	3,057	449	85%	56,757	14,460	75%	56,757	14,460	75%
Carl Sandburg / Illinois Zephyr	85%	421	0	100%	9,417	2,707	71%	9,417	2,707	71%
Illini / Saluki	85%	1,013	0	100%	20,632	3,288	84%	20,632	3,288	84%
Lincoln Service	70%	1,623	449	72%	26,708	8,465	68%	26,708	8,465	68%
Keystone	92%	8,646	631	93%	174,858	12,843	93%	174,858	12,843	93%
Lincoln / Missouri	60%	1,800	1,004	44%	17,610	9,688	45%	17,610	9,688	45%
Mardi Gras Service	80%	394	0	100%	10,166	1,935	81%	10,166	1,935	81%
Michigan	69%	2,368	60	97%	42,655	8,572	80%	42,655	8,572	80%
Blue Water	70%	632	15	98%	11,413	2,768	76%	11,413	2,768	76%
Pere Marquette	85%	328	0	100%	5,971	1,094	82%	5,971	1,094	82%
Wolverine	65%	1,408	45	97%	25,271	4,710	81%	25,271	4,710	81%
Missouri	80%	243	0	100%	4,955	1,340	73%	4,955	1,340	73%
Pacific Surfliner	85%	7,366	3,743	49%	146,213	17,277	88%	146,213	17,277	88%
Pennsylvanian	72%	995	30	97%	20,223	2,254	89%	20,223	2,254	89%
Piedmont	73%	1,401	321	77%	30,679	10,927	64%	30,679	10,927	64%
San Joaquins	73%	2,755	475	83%	53,133	17,547	67%	53,133	17,547	67%
Vermont	75%	1,430	632	56%	30,065	7,453	75%	30,065	7,453	75%
Long Distance	56%	22,296	6,291	72%	267,173	90,496	66%	267,173	90,496	66%
Auto Train	57%	1,324	0	100%	13,127	2,250	83%	13,127	2,250	83%
California Zephyr	50%	1,558	122	92%	20,634	7,613	63%	20,634	7,613	63%
Cardinal	55%	1,359	1,039	24%	6,756	4,043	40%	6,756	4,043	40%
City Of New Orleans	75%	1,474	86	94%	15,823	3,219	80%	15,823	3,219	80%
Coast Starlight	60%	2,341	641	73%	24,508	7,194	71%	24,508	7,194	71%
Crescent	70%	1,766	1,516	14%	20,526	7,227	65%	20,526	7,227	65%
Empire Builder	55%	1,376	137	90%	22,673	5,995	74%	22,673	5,995	74%
Floridian	40%	2,811	744	74%	36,023	16,972	53%	36,023	16,972	53%
Lake Shore Ltd	73%	1,584	0	100%	19,929	2,647	87%	19,929	2,647	87%
Palmetto	65%	881	31	96%	20,650	4,002	81%	20,650	4,002	81%
Silver Meteor	45%	2,144	513	76%	20,853	5,117	75%	20,853	5,117	75%
Southwest Chief	40%	1,159	828	29%	18,865	12,601	33%	18,865	12,601	33%
Sunset Ltd	70%	512	109	79%	5,675	1,614	72%	5,675	1,614	72%
Texas Eagle	50%	2,007	525	74%	21,131	10,002	53%	21,131	10,002	53%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00072 00000000001 "UNCLASSIFIED" 10/20/2025

Train Index Dates Through October 20, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	105,052	2,125,245	494	105,052	2,125,245	494

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	4,054	613,311	66	4,054	613,311	66
INFRASTRUCTURE PLANNED	130	3,158	613,311	51	3,158	613,311	51
FLEET RELIABILITY	90	15,096	2,125,245	71	15,096	2,125,245	71
TRAIN OPERATIONS	427	82,744	2,125,245	389	82,744	2,125,245	389

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/20/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	43	85.8%	5,849	755	87.1%	5,849	755	87.1%
Central Division	85.5%	65	10	84.6%	1,315	149	88.7%	1,315	149	88.7%
Northeast Division	80.0%	95	10	89.5%	1,822	270	85.2%	1,822	270	85.2%
Southeast Division	72.5%	73	8	89.0%	1,363	130	90.5%	1,363	130	90.5%
Southwest Division	77.0%	70	15	78.6%	1,349	206	84.7%	1,349	206	84.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/20/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	43	85.8%	5,849	755	87.1%	5,849	755	87.1%
Central Division	85.5%	65	10	84.6%	1,315	149	88.7%	1,315	149	88.7%
CDL	90.0%	2	0	100.0%	40	3	92.5%	40	3	92.5%
CHI	85.0%	26	3	88.5%	534	59	89.0%	534	59	89.0%
EUG	86.5%	2	0	100.0%	38	4	89.5%	38	4	89.5%
GRR	98.0%	1	0	100.0%	20	0	100.0%	20	0	100.0%
KCY	84.5%	2	0	100.0%	38	4	89.5%	38	4	89.5%
MKE	86.5%	6	0	100.0%	117	17	85.5%	117	17	85.5%
MSP	94.0%	1	0	100.0%	20	0	100.0%	20	0	100.0%
PDX	78.0%	5	2	60.0%	100	15	85.0%	100	15	85.0%
PNT	91.5%	2	0	100.0%	13	1	92.3%	13	1	92.3%
PTH	93.0%	1	0	100.0%	20	1	95.0%	20	1	95.0%
QCY	87.5%	2	1	50.0%	40	8	80.0%	40	8	80.0%
SEA	80.0%	8	3	62.5%	160	23	85.6%	160	23	85.6%
SPK	92.0%	1	-	100.0%	20	1	95.0%	20	1	95.0%
STL	88.0%	4	1	75.0%	80	5	93.8%	80	5	93.8%
TRM	-	-	-	-	35	5	85.7%	35	5	85.7%
VAC	95.0%	2	0	100.0%	40	3	92.5%	40	3	92.5%
Northeast Division	80.0%	95	10	89.5%	1,822	270	85.2%	1,822	270	85.2%
ALB	91.5%	6	1	83.3%	120	2	98.3%	120	2	98.3%
BON	43.5%	5	0	100.0%	92	18	80.4%	92	18	80.4%
BOS	86.5%	19	0	100.0%	351	29	91.7%	351	29	91.7%
BRK	88.0%	5	0	100.0%	84	5	94.0%	84	5	94.0%
BTN	48.0%	1	0	100.0%	20	7	65.0%	20	7	65.0%
GFD	86.0%	2	0	100.0%	40	2	95.0%	40	2	95.0%
HFD	-	2	0	100.0%	28	2	92.9%	28	2	92.9%
MTR	79.5%	1	0	100.0%	20	3	85.0%	20	3	85.0%
NFL	96.5%	2	0	100.0%	40	3	92.5%	40	3	92.5%
NHV	75.5%	5	0	100.0%	97	23	76.3%	97	23	76.3%
NYP	77.5%	40	9	77.5%	774	156	79.8%	774	156	79.8%
SAB	98.0%	1	0	100.0%	20	0	100.0%	20	0	100.0%
SPG	88.0%	5	0	100.0%	109	6	94.5%	109	6	94.5%
TWO	84.0%	1	0	100.0%	19	7	63.2%	19	7	63.2%
WEM	-	-	-	-	8	7	12.5%	8	7	12.5%
Southeast Division	72.5%	73	8	89.0%	1,363	130	90.5%	1,363	130	90.5%
ATL	-	-	-	-	1	0	100.0%	1	0	100.0%
CLT	92.0%	5	1	80.0%	100	9	91.0%	100	9	91.0%
HAR	62.0%	13	1	92.3%	223	20	91.0%	223	20	91.0%
LOR	69.5%	1	0	100.0%	20	2	90.0%	20	2	90.0%
MIA	87.5%	2	1	50.0%	40	3	92.5%	40	3	92.5%
MOE	94.0%	2	0	100.0%	40	3	92.5%	40	3	92.5%
NFK	86.0%	3	0	100.0%	57	4	93.0%	57	4	93.0%
NOL	92.0%	5	0	100.0%	88	4	95.5%	88	4	95.5%
NPN	96.0%	2	0	100.0%	40	3	92.5%	40	3	92.5%
PGH	92.0%	1	0	100.0%	20	1	95.0%	20	1	95.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/20/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	303	43	85.8%	5,849	755	87.1%	5,849	755	87.1%
Southeast Division	72.5%	73	8	89.0%	1,363	130	90.5%	1,363	130	90.5%
PHL	45.0%	5	3	40.0%	91	23	74.7%	91	23	74.7%
RGH	97.0%	4	0	100.0%	80	2	97.5%	80	2	97.5%
RNK	85.5%	2	0	100.0%	40	5	87.5%	40	5	87.5%
RVM	86.0%	1	0	100.0%	20	1	95.0%	20	1	95.0%
SAV	91.5%	1	0	100.0%	20	0	100.0%	20	0	100.0%
SFA	70.5%	1	0	100.0%	20	1	95.0%	20	1	95.0%
WAS	70.0%	25	2	92.0%	463	49	89.4%	463	49	89.4%
Southwest Division	77.0%	70	15	78.6%	1,349	206	84.7%	1,349	206	84.7%
ARN	60.5%	1	1	0.0%	20	3	85.0%	20	3	85.0%
BFD	75.5%	6	1	83.3%	114	30	73.7%	114	30	73.7%
DAL	-	-	-	-	1	0	100.0%	1	0	100.0%
EMY	50.0%	1	0	100.0%	20	8	60.0%	20	8	60.0%
FNO	-	-	-	-	1	0	100.0%	1	0	100.0%
FTW	89.5%	1	0	100.0%	19	2	89.5%	19	2	89.5%
GTA	72.5%	3	1	66.7%	60	6	90.0%	60	6	90.0%
LAX	77.5%	9	1	88.9%	189	21	88.9%	189	21	88.9%
OKC	96.0%	1	0	100.0%	20	2	90.0%	20	2	90.0%
OKJ	79.0%	12	3	75.0%	213	50	76.5%	213	50	76.5%
SAC	73.5%	14	6	57.1%	256	41	84.0%	256	41	84.0%
SAN	77.0%	12	1	91.7%	228	20	91.2%	228	20	91.2%
SAS	85.0%	1	0	100.0%	20	3	85.0%	20	3	85.0%
SJC	87.5%	7	1	85.7%	139	12	91.4%	139	12	91.4%
SLO	62.0%	2	0	100.0%	39	7	82.1%	39	7	82.1%
SNC	-	-	-	-	2	0	100.0%	2	0	100.0%
SOL	-	-	-	-	8	1	87.5%	8	1	87.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

28-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	172	9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
3		20	2	90.0%	20	2	90.0%	20	8	60.0%	20	8	60.0%
4		20	2	90.0%	20	2	90.0%	20	15	25.0%	20	15	25.0%
5		19	3	84.2%	19	3	84.2%	18	3	83.3%	18	3	83.3%
6		20	8	60.0%	20	8	60.0%	20	9	55.0%	20	9	55.0%
7		20	3	85.0%	20	3	85.0%	20	1	95.0%	20	1	95.0%
8		20	7	65.0%	20	7	65.0%	20	6	70.0%	20	6	70.0%
11		19	2	89.5%	19	2	89.5%	17	2	88.2%	17	2	88.2%
14		20	3	85.0%	20	3	85.0%	19	4	78.9%	19	4	78.9%
19	43	20	3	85.0%	20	3	85.0%	20	8	60.0%	20	8	60.0%
20		20	2	90.0%	20	2	90.0%	20	0	100.0%	20	0	100.0%
21		20	2	90.0%	20	2	90.0%	20	5	75.0%	20	5	75.0%
22		20	3	85.0%	20	3	85.0%	20	5	75.0%	20	5	75.0%
23		20	3	85.0%	20	3	85.0%	20	6	70.0%	20	6	70.0%
24		20	0	100.0%	20	0	100.0%	20	2	90.0%	20	2	90.0%
25		20	0	100.0%	20	0	100.0%	20	3	85.0%	20	3	85.0%
26		20	0	100.0%	20	0	100.0%	20	4	80.0%	20	4	80.0%
27		20	2	90.0%	20	2	90.0%	20	3	85.0%	20	3	85.0%
28		20	5	75.0%	20	5	75.0%	20	1	95.0%	20	1	95.0%
40		20	2	90.0%	20	2	90.0%	20	6	70.0%	20	6	70.0%
41	31	20	9	55.0%	20	9	55.0%	20	15	25.0%	20	15	25.0%
42		20	1	95.0%	20	1	95.0%	20	2	90.0%	20	2	90.0%
43		20	1	95.0%	20	1	95.0%	20	1	95.0%	20	1	95.0%
48		20	2	90.0%	20	2	90.0%	20	1	95.0%	20	1	95.0%
49		20	3	85.0%	20	3	85.0%	20	1	95.0%	20	1	95.0%
51	125	9	5	44.4%	9	5	44.4%	9	5	44.4%	9	5	44.4%
52		20	1	95.0%	20	1	95.0%	20	2	90.0%	20	2	90.0%
53		20	2	90.0%	20	2	90.0%	20	2	90.0%	20	2	90.0%
55		14	0	100.0%	14	0	100.0%	14	3	78.6%	14	3	78.6%
56		14	1	92.9%	14	1	92.9%	14	4	71.4%	14	4	71.4%
58		19	1	94.7%	19	1	94.7%	19	2	89.5%	19	2	89.5%
59		19	3	84.2%	19	3	84.2%	19	2	89.5%	19	2	89.5%
63		20	10	50.0%	20	10	50.0%	20	13	35.0%	20	13	35.0%
64		19	7	63.2%	19	7	63.2%	19	5	73.7%	19	5	73.7%
66	76	20	4	80.0%	20	4	80.0%	20	5	75.0%	20	5	75.0%
67		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
68		20	3	85.0%	20	3	85.0%	20	10	50.0%	20	10	50.0%
69		20	0	100.0%	20	0	100.0%	20	2	90.0%	20	2	90.0%
71		20	0	100.0%	20	0	100.0%	20	7	65.0%	20	7	65.0%
72		20	1	95.0%	20	1	95.0%	20	2	90.0%	20	2	90.0%
73	19	20	1	95.0%	20	1	95.0%	20	13	35.0%	20	13	35.0%
74		20	1	95.0%	20	1	95.0%	20	7	65.0%	20	7	65.0%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

28-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		20	0	100.0%	20	0	100.0%	20	11	45.0%	20	11	45.0%
76	17	20	3	85.0%	20	3	85.0%	20	15	25.0%	20	15	25.0%
77	16	20	1	95.0%	20	1	95.0%	20	13	35.0%	20	13	35.0%
78		20	2	90.0%	20	2	90.0%	20	5	75.0%	20	5	75.0%
79		20	6	70.0%	20	6	70.0%	20	5	75.0%	20	5	75.0%
80	58	20	2	90.0%	20	2	90.0%	20	2	90.0%	20	2	90.0%
84		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
85	55	14	1	92.9%	14	1	92.9%	14	6	57.1%	14	6	57.1%
86		14	1	92.9%	14	1	92.9%	14	7	50.0%	14	7	50.0%
89		20	4	80.0%	20	4	80.0%	20	1	95.0%	20	1	95.0%
90		20	0	100.0%	20	0	100.0%	20	4	80.0%	20	4	80.0%
93	116	14	1	92.9%	14	1	92.9%	14	5	64.3%	14	5	64.3%
94	26	14	2	85.7%	14	2	85.7%	14	6	57.1%	14	6	57.1%
95		14	0	100.0%	14	0	100.0%	14	4	71.4%	14	4	71.4%
97	107	20	6	70.0%	20	6	70.0%	20	6	70.0%	20	6	70.0%
98		20	1	95.0%	20	1	95.0%	20	2	90.0%	20	2	90.0%
110		14	5	64.3%	14	5	64.3%	14	1	92.9%	14	1	92.9%
111		14	4	71.4%	14	4	71.4%	14	0	100.0%	14	0	100.0%
112		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
114		14	4	71.4%	14	4	71.4%	14	0	100.0%	14	0	100.0%
119		14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
125		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
128		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
129		14	5	64.3%	14	5	64.3%	14	2	85.7%	14	2	85.7%
130		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
131		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
132		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
133	19	14	7	50.0%	14	7	50.0%	14	5	64.3%	14	5	64.3%
134		14	1	92.9%	14	1	92.9%	14	4	71.4%	14	4	71.4%
137		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
138		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
139		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
141		14	2	85.7%	14	2	85.7%	14	4	71.4%	14	4	71.4%
148		14	3	78.6%	14	3	78.6%	14	6	57.1%	14	6	57.1%
151		20	4	80.0%	20	4	80.0%	20	6	70.0%	20	6	70.0%
166		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
169		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
170		11	2	81.8%	11	2	81.8%	11	2	81.8%	11	2	81.8%
171	140	14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
172		14	2	85.7%	14	2	85.7%	14	7	50.0%	14	7	50.0%
173		14	1	92.9%	14	1	92.9%	14	6	57.1%	14	6	57.1%
174		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

28-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
175		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
176		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
177	54	14	4	71.4%	14	4	71.4%	14	6	57.1%	14	6	57.1%
181		14	4	71.4%	14	4	71.4%	14	0	100.0%	14	0	100.0%
182		14	3	78.6%	14	3	78.6%	14	0	100.0%	14	0	100.0%
183		14	4	71.4%	14	4	71.4%	14	3	78.6%	14	3	78.6%
184	47	14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
185		14	3	78.6%	14	3	78.6%	14	0	100.0%	14	0	100.0%
186		14	2	85.7%	14	2	85.7%	14	3	78.6%	14	3	78.6%
190		14	4	71.4%	14	4	71.4%	14	3	78.6%	14	3	78.6%
192		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
193		14	4	71.4%	14	4	71.4%	14	5	64.3%	14	5	64.3%
196		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
197	18	14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
232		20	0	100.0%	20	0	100.0%	20	1	95.0%	20	1	95.0%
233		20	5	75.0%	20	5	75.0%	20	4	80.0%	20	4	80.0%
234		20	0	100.0%	20	0	100.0%	20	0	100.0%	20	0	100.0%
236		20	0	100.0%	20	0	100.0%	20	2	90.0%	20	2	90.0%
237		20	5	75.0%	20	5	75.0%	20	2	90.0%	20	2	90.0%
239		20	6	70.0%	20	6	70.0%	20	0	100.0%	20	0	100.0%
240		20	0	100.0%	20	0	100.0%	20	1	95.0%	20	1	95.0%
241	23	20	5	75.0%	20	5	75.0%	20	4	80.0%	20	4	80.0%
243		14	5	64.3%	14	5	64.3%	15	3	80.0%	15	3	80.0%
244	27	20	2	90.0%	20	2	90.0%	20	5	75.0%	20	5	75.0%
245		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
280		20	2	90.0%	20	2	90.0%	20	3	85.0%	20	3	85.0%
281		20	4	80.0%	20	4	80.0%	20	1	95.0%	20	1	95.0%
283		20	2	90.0%	20	2	90.0%	20	3	85.0%	20	3	85.0%
284		20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
290	23	20	7	65.0%	20	7	65.0%	20	9	55.0%	20	9	55.0%
291		20	5	75.0%	20	5	75.0%	20	2	90.0%	20	2	90.0%
300		20	0	100.0%	20	0	100.0%	20	5	75.0%	20	5	75.0%
301		20	0	100.0%	20	0	100.0%	20	4	80.0%	20	4	80.0%
302		20	2	90.0%	20	2	90.0%	20	7	65.0%	20	7	65.0%
305		20	1	95.0%	20	1	95.0%	20	7	65.0%	20	7	65.0%
306		20	0	100.0%	20	0	100.0%	19	2	89.5%	19	2	89.5%
307		20	2	90.0%	20	2	90.0%	20	1	95.0%	20	1	95.0%
311		19	2	89.5%	19	2	89.5%	19	4	78.9%	19	4	78.9%
316		19	1	94.7%	19	1	94.7%	19	5	73.7%	19	5	73.7%
318		20	4	80.0%	20	4	80.0%	19	9	52.6%	19	9	52.6%
319	69	20	1	95.0%	20	1	95.0%	20	14	30.0%	20	14	30.0%
329		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
330		17	1	94.1%	17	1	94.1%	17	1	94.1%	17	1	94.1%
331		20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
332		20	3	85.0%	20	3	85.0%	20	1	95.0%	20	1	95.0%
334		20	1	95.0%	20	1	95.0%	19	2	89.5%	19	2	89.5%
335		20	5	75.0%	20	5	75.0%	19	7	63.2%	19	7	63.2%
336		20	1	95.0%	20	1	95.0%	20	4	80.0%	20	4	80.0%
337		20	4	80.0%	20	4	80.0%	20	4	80.0%	20	4	80.0%
338		20	9	55.0%	20	9	55.0%	19	8	57.9%	19	8	57.9%
339		20	9	55.0%	20	9	55.0%	20	5	75.0%	20	5	75.0%
341		20	2	90.0%	20	2	90.0%	20	4	80.0%	20	4	80.0%
342		20	2	90.0%	20	2	90.0%	19	1	94.7%	19	1	94.7%
351		20	1	95.0%	20	1	95.0%	20	4	80.0%	20	4	80.0%
352		20	1	95.0%	20	1	95.0%	19	3	84.2%	19	3	84.2%
354		20	1	95.0%	20	1	95.0%	20	5	75.0%	20	5	75.0%
355		20	3	85.0%	20	3	85.0%	20	2	90.0%	20	2	90.0%
364		20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
365		20	1	95.0%	20	1	95.0%	20	4	80.0%	20	4	80.0%
370		20	0	100.0%	20	0	100.0%	20	4	80.0%	20	4	80.0%
371		20	0	100.0%	20	0	100.0%	20	1	95.0%	20	1	95.0%
380		20	7	65.0%	20	7	65.0%	20	6	70.0%	20	6	70.0%
381		20	0	100.0%	20	0	100.0%	20	4	80.0%	20	4	80.0%
382		20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
383		20	1	95.0%	20	1	95.0%	20	8	60.0%	20	8	60.0%
390		20	2	90.0%	20	2	90.0%	20	4	80.0%	20	4	80.0%
391		20	0	100.0%	20	0	100.0%	19	1	94.7%	19	1	94.7%
392		20	1	95.0%	20	1	95.0%	19	2	89.5%	19	2	89.5%
393		20	3	85.0%	20	3	85.0%	19	5	73.7%	19	5	73.7%
417		14	3	78.6%	14	3	78.6%	13	0	100.0%	13	0	100.0%
425		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
470		14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
471		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
473		14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%
474		14	5	64.3%	14	5	64.3%	13	1	92.3%	13	1	92.3%
475	35	14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
478		14	7	50.0%	14	7	50.0%	14	2	85.7%	14	2	85.7%
479		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
486		15	5	66.7%	15	5	66.7%	14	2	85.7%	14	2	85.7%
494		15	6	60.0%	15	6	60.0%	14	3	78.6%	14	3	78.6%
495		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
500	24	20	2	90.0%	20	2	90.0%	20	3	85.0%	20	3	85.0%
502		20	3	85.0%	20	3	85.0%	20	4	80.0%	20	4	80.0%
503		20	4	80.0%	20	4	80.0%	19	6	68.4%	19	6	68.4%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

28-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		20	1	95.0%	20	1	95.0%	20	7	65.0%	20	7	65.0%
505		20	3	85.0%	20	3	85.0%	19	2	89.5%	19	2	89.5%
506		19	2	89.5%	19	2	89.5%	19	3	84.2%	19	3	84.2%
507		20	2	90.0%	20	2	90.0%	20	10	50.0%	20	10	50.0%
508		20	4	80.0%	20	4	80.0%	20	4	80.0%	20	4	80.0%
509		20	0	100.0%	20	0	100.0%	20	5	75.0%	20	5	75.0%
511		20	1	95.0%	20	1	95.0%	20	5	75.0%	20	5	75.0%
516	59	20	3	85.0%	20	3	85.0%	20	11	45.0%	20	11	45.0%
517		20	1	95.0%	20	1	95.0%	19	8	57.9%	19	8	57.9%
518		20	3	85.0%	20	3	85.0%	20	13	35.0%	20	13	35.0%
519		20	2	90.0%	20	2	90.0%	20	5	75.0%	20	5	75.0%
520		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
521		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
522		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
523		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
524		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
525	11	14	1	92.9%	14	1	92.9%	14	4	71.4%	14	4	71.4%
526	85	14	3	78.6%	14	3	78.6%	14	3	78.6%	14	3	78.6%
527		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
528	19	14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
529	15	14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
531		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
532		14	1	92.9%	14	1	92.9%	14	3	78.6%	14	3	78.6%
534		11	1	90.9%	11	1	90.9%	11	0	100.0%	11	0	100.0%
535		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
536		14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%
537		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
538		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
540		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
541	33	14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
542	13	14	2	85.7%	14	2	85.7%	13	4	69.2%	13	4	69.2%
543	25	14	3	78.6%	14	3	78.6%	14	5	64.3%	14	5	64.3%
544		14	2	85.7%	14	2	85.7%	14	0	100.0%	14	0	100.0%
545	30	14	3	78.6%	14	3	78.6%	14	3	78.6%	14	3	78.6%
546		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
547		14	3	78.6%	14	3	78.6%	14	3	78.6%	14	3	78.6%
548		14	3	78.6%	14	3	78.6%	14	1	92.9%	14	1	92.9%
549		11	3	72.7%	11	3	72.7%	10	2	80.0%	10	2	80.0%
551		14	2	85.7%	14	2	85.7%	13	2	84.6%	13	2	84.6%
562	35	20	3	85.0%	20	3	85.0%	19	2	89.5%	19	2	89.5%
564	31	20	1	95.0%	20	1	95.0%	19	2	89.5%	19	2	89.5%
566	19	20	2	90.0%	20	2	90.0%	20	1	95.0%	20	1	95.0%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572	53	19	2	89.5%	19	2	89.5%	19	3	84.2%	19	3	84.2%
573	31	20	4	80.0%	20	4	80.0%	19	2	89.5%	19	2	89.5%
577		18	0	100.0%	18	0	100.0%	18	0	100.0%	18	0	100.0%
580		20	2	90.0%	20	2	90.0%	20	2	90.0%	20	2	90.0%
581		20	0	100.0%	20	0	100.0%	20	4	80.0%	20	4	80.0%
582		20	2	90.0%	20	2	90.0%	20	2	90.0%	20	2	90.0%
586		20	3	85.0%	20	3	85.0%	18	2	88.9%	18	2	88.9%
587		20	1	95.0%	20	1	95.0%	19	3	84.2%	19	3	84.2%
591		20	1	95.0%	20	1	95.0%	20	2	90.0%	20	2	90.0%
593		20	3	85.0%	20	3	85.0%	18	2	88.9%	18	2	88.9%
595		20	3	85.0%	20	3	85.0%	20	6	70.0%	20	6	70.0%
600		14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
601	14	14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
605		14	2	85.7%	14	2	85.7%	14	0	100.0%	14	0	100.0%
607		14	1	92.9%	14	1	92.9%	13	0	100.0%	13	0	100.0%
609		13	0	100.0%	13	0	100.0%	13	1	92.3%	13	1	92.3%
620		14	5	64.3%	14	5	64.3%	13	1	92.3%	13	1	92.3%
637		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
639		14	5	64.3%	14	5	64.3%	14	2	85.7%	14	2	85.7%
640	12	14	0	100.0%	14	0	100.0%	14	8	42.9%	14	8	42.9%
641		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
642		13	0	100.0%	13	0	100.0%	13	1	92.3%	13	1	92.3%
643		14	1	92.9%	14	1	92.9%	13	1	92.3%	13	1	92.3%
644		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
645		14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
646	Cncld	14	1	92.9%	14	1	92.9%	13	6	53.8%	13	6	53.8%
647	14	14	0	100.0%	14	0	100.0%	14	6	57.1%	14	6	57.1%
648	23	14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%
649		14	2	85.7%	14	2	85.7%	13	1	92.3%	13	1	92.3%
650		14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%
651		14	2	85.7%	14	2	85.7%	14	5	64.3%	14	5	64.3%
652		14	2	85.7%	14	2	85.7%	13	3	76.9%	13	3	76.9%
653	17	14	4	71.4%	14	4	71.4%	14	7	50.0%	14	7	50.0%
654		14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
656		14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
657		14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
658		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
680		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%
681	14	14	2	85.7%	14	2	85.7%	14	6	57.1%	14	6	57.1%
682		14	0	100.0%	14	0	100.0%	14	5	64.3%	14	5	64.3%
683	19	6	2	66.7%	6	2	66.7%	6	5	16.7%	6	5	16.7%
684	19	6	3	50.0%	6	3	50.0%	6	4	33.3%	6	4	33.3%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

28-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685	36	14	0	100.0%	14	0	100.0%	14	5	64.3%	14	5	64.3%
686		14	7	50.0%	14	7	50.0%	14	5	64.3%	14	5	64.3%
687		14	3	78.6%	14	3	78.6%	14	3	78.6%	14	3	78.6%
688		14	0	100.0%	14	0	100.0%	14	5	64.3%	14	5	64.3%
699		6	2	66.7%	6	2	66.7%	6	0	100.0%	6	0	100.0%
702		20	7	65.0%	20	7	65.0%	20	7	65.0%	20	7	65.0%
703		20	5	75.0%	20	5	75.0%	20	4	80.0%	20	4	80.0%
710		20	8	60.0%	20	8	60.0%	20	9	55.0%	20	9	55.0%
711		19	2	89.5%	19	2	89.5%	19	2	89.5%	19	2	89.5%
712		20	6	70.0%	20	6	70.0%	20	10	50.0%	20	10	50.0%
713		20	4	80.0%	20	4	80.0%	19	9	52.6%	19	9	52.6%
714		17	4	76.5%	17	4	76.5%	16	5	68.8%	16	5	68.8%
715	39	20	8	60.0%	20	8	60.0%	19	10	47.4%	19	10	47.4%
716		20	7	65.0%	20	7	65.0%	20	6	70.0%	20	6	70.0%
717		16	3	81.3%	16	3	81.3%	14	3	78.6%	14	3	78.6%
718		20	8	60.0%	20	8	60.0%	20	6	70.0%	20	6	70.0%
719		20	8	60.0%	20	8	60.0%	20	7	65.0%	20	7	65.0%
761	63	20	2	90.0%	20	2	90.0%	20	4	80.0%	20	4	80.0%
765	41	20	4	80.0%	20	4	80.0%	20	6	70.0%	20	6	70.0%
769	53	20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
770		20	3	85.0%	20	3	85.0%	20	1	95.0%	20	1	95.0%
774	82	20	4	80.0%	20	4	80.0%	19	3	84.2%	19	3	84.2%
779		20	2	90.0%	20	2	90.0%	19	0	100.0%	19	0	100.0%
784		20	2	90.0%	20	2	90.0%	20	7	65.0%	20	7	65.0%
785		20	0	100.0%	20	0	100.0%	20	3	85.0%	20	3	85.0%
790		20	1	95.0%	20	1	95.0%	20	2	90.0%	20	2	90.0%
794	39	20	3	85.0%	20	3	85.0%	20	5	75.0%	20	5	75.0%
821	28	20	2	90.0%	20	2	90.0%	20	14	30.0%	20	14	30.0%
822	55	20	2	90.0%	20	2	90.0%	20	17	15.0%	20	17	15.0%
1333	17	20	0	100.0%	20	0	100.0%	20	12	40.0%	20	12	40.0%
1340	21	20	0	100.0%	20	0	100.0%	20	3	85.0%	20	3	85.0%
2103		14	3	78.6%	14	3	78.6%	14	0	100.0%	14	0	100.0%
2107		14	3	78.6%	14	3	78.6%	12	0	100.0%	12	0	100.0%
2108		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
2121		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
2122		14	4	71.4%	14	4	71.4%	14	2	85.7%	14	2	85.7%
2124		10	2	80.0%	10	2	80.0%	10	1	90.0%	10	1	90.0%
2150		14	3	78.6%	14	3	78.6%	14	5	64.3%	14	5	64.3%
2151		14	0	100.0%	14	0	100.0%	13	0	100.0%	13	0	100.0%
2152		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
2153		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
2154		14	3	78.6%	14	3	78.6%	13	7	46.2%	13	7	46.2%

Amtrak On Time Performance

Trains Arriving Through: 10/20/2025

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2155		14	0	100.0%	14	0	100.0%	12	3	75.0%	12	3	75.0%
2159	51	14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
2162		14	0	100.0%	14	0	100.0%	13	0	100.0%	13	0	100.0%
2163	38	14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
2166		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
2167		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
2168		14	0	100.0%	14	0	100.0%	14	4	71.4%	14	4	71.4%
2169		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
2170	19	14	2	85.7%	14	2	85.7%	14	6	57.1%	14	6	57.1%
2172		14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
2173		13	3	76.9%	13	3	76.9%	13	4	69.2%	13	4	69.2%
2190	36	14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
2193	23	13	0	100.0%	13	0	100.0%	13	2	84.6%	13	2	84.6%
2275		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Region: ALL

Service: ALL

Arriving On: 10/20/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2159	WAS	51	CTI	25	WTR	15	RTE-PVD	AM	Wet / slippery rail, Milepost, RTE, PVD, Heavy thunderstorms moving through the area of RI and Mass. All trains reporting excessive wheel slip	
2163	WAS	38	DCS	19	CTP	19	RTE-PVD	AM	Delay due to mechanical problems on a Commuter train, JUNCTION TO HOLDEN LATE 827, 85, AND 831 AHEAD	
2170	BOS	19	CTI	18	CTI	8	NWK-NYP	AM	Follow, NJ, 6658 3860 3896, Other, NWK-NYP, FLWD NJ6658 AND NJ3860 AND NJ3896 IN SOUTH TUBE	
2190	BOS	36	WTR	49	WTR	17	NHV-XGX	AM	Wet / slippery rail, Milepost, NHV, XGX, HEAVY WHEELSLIP UNABLE TO MAINTAIN TRK SPEED	
2193	NYP	23	DSR	15	DSR	15	XNH-STM	MN	Per bulletin Milepost, 71.5, 71.1, 30, 1, Milepost, 60.2, 60.1, 30, 1, Milepost, 57.0, 56.6, 30, 1, Milepost, 48.6, 48.4, 30, 1, Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.6, 30, 2, Milepost, 33.6, 32.3, 30, 2	
66	BOS	76	DET	68	DET	68	PVD-RTE	AM	Catenary failure, Milepost, xmf, xmf, Waiting at Manfield for 2159 to crossover track 2-1 A/C 171 DISABLED AT SHARON STATION	
85	RVM	55	CTP	38	CTP	38	RTE-PVD	AM	Delay due to mechanical problems on a Commuter train, 85 behind 827, 827 EXPERIENCING EXCESSIVE WHEELSLIP. UNABLE TO EXCEED 8MPH	
93	NFK	116	MTI	62	MTI	62	RTE-PVD	AM	Disabled train ahead, Milepost, xjc, xmf, Waiting at Junction to crossover track 1-2	
94	BOS	26	DSR	30	DMW	13	X3V-XV7	CS	Waiting on track maintenance Control Point, appomatox	
133	WAS	19	HLD	12	HLD	12	NYP-NYP	AM	Passenger and/or baggage, BOARDING	
171	RNK	140	DET	140	DET	140	RTE-PVD	AM	Catenary failure, Milepost, RTE, PVD, STOPPED AT SHAROM STATION A/C BROKEN PANTOGRAPH ALARM. WIRE FROM HANGER IN PANTOGRAPH	
177	PHL	54	POL	40	POL	29	TRE-TRE	AM	Removal of passenger by police, POLICE REMOVED PSGR WHO BOARDED THE TRAIN IN PRINCETON-JUNCTION, REFUSING TO PAY FARE.	
184	BOS	47	ENG	25	ENG	25	WAS-WAS	AM	HEP, 648	
197	WAS	18	OTH	17	OTH	11	BWI-XNY	AM	Lost time - N.A.R.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Region: ALL

Service: ALL

Arriving On: 10/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
475	NHV	35	INJ	31	INJ	31	MDN-MDN	AM	Injured or sick passenger, AM475 held at MDN station due to psngr needing medical assistance, EMS removed psngr
80	NYP	58	ENG	78	ENG	75	CLT-CLT	NS	Pick up rescue locomotive due to mechanical failure Add locomotive 355 from Am 20 b, 37
601	HAR	14	OTH	6	CTC	5	PHL-PHL	AM	PTC - Stop Bypass Permission Required, Control Point, N. PENN, STOP BY PASS DEPARTING THE YARD
640	NYP	12	CTI	16	PTI	7	TRE-NWK	AM	Wait for station track, AM170, Other, NWK, AM170 AHD
646	XHM	Trn Cancelled	WTR	3	WTR	3	MJY-MJY	AM	Wet / slippery rail, Control Point, .
647	HAR	14	PTI	7	PTI	7	XHM-PHL	AM	Wait for station track, 42, Control Point, Penn, held for departing 42
648	NYP	23	MTI	15	MTI	15	LNC-PAO	AM	Disabled train ahead, Control Point, ., MAKING TERMINATED 646 STOPS
653	HAR	17	CTI	9	CTI	9	NYP-NWK	AM	Follow, NJ, 3511 3725 3949, Other, NYP-NWK, FLWD NJ3511 AND NJ3725 AND NJ3949 IN NORTH TUBE
19	NOL	43	DBS	146	DBS	146	XA1-MSS	NS	Debris blocking track (no debris strike) Tree on tracks (Track 1). Reverse-move to (CP) Edsall (mp 12.9). Waited for trains 50 and 66 to pass us. Proceeded SB on track 2., Milepost, 17.8, 17.8
681	BRK	14	HLD	10	HLD	6	WOB-WOB	MT	Group
683	BRK	19	DCS	10	SYS	8	WOB-HHL	MT	Copy authority / restriction Phone copy a line 12 form D
684	BON	19	PTI	8	PTI	5	DHM-EXR	CS	Meet 683, Control Point, newfields
686	BON	36	PTI	28	PTI	22	POR-SAO	CS	Dispatchers delayed our on-time train in favor of train 683 that was already 22 minutes late instead of running our on time train and holding the late train. So now we have two late passenger trains and no viable excuse for it. amtk 683, Control Point, Surf
241	ALB	23	CTI	21	CTI	18	CRT-POU	MN	Follow metro, 875, Milepost, 61, 72
244	NYP	27	DMW	23	DMW	23	ALB-HUD	AM	Held for or routed around MW work or equipment Single track conditions, hold for 291, Control Point, 124, Control Point, 114

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Region: ALL

Service: ALL

Arriving On: 10/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
290	NYP	23	CTI	23	DSR	18	BTN-VRN	VR	Per bulletin Milepost, 116.5, 115.5, 25, main, Milepost, 113.40, 107, 25, main, Milepost, 105.68, 104.97, 25, main
73	CLT	19	FTI	12	FTI	10	KAN-CLT	NS	Cross over or go around #NSp49, Control Point, Junker, Control Point, AT&O Jct
76	RGH	17	OTH	13	PTI	9	GRO-DNC	NS	Meet amt 79, Siding, Haw river
77	CLT	16	FTI	16	FTI	13	HPT-SAL	NS	Cross over or go around I heard no train id's. I feel the root cause was dispatcher forgot about us., Milepost, 324.5, 333.2, Ns unknown
97	MIA	107	SYS	111	SYS	68	FLO-FLO	CS	Other late crew Engineer stuck in traffic
41	MIA	31	ADA	49	DCS	15	LAK-TPA	CS	Wayside detector failure including false actuation Milepost, 874.6, 874.6
525	OKJ	11	PTI	16	PTI	10	SUI-MTZ	UP	Meet 522, Milepost, 38.0, 38.0
526	SAC	85	ENG	82	ENG	61	EMY-EMY	UP	Loading problem Coolant censor fault, C2012
528	SAC	19	TRS	15	TRS	15	SCC-GAC	UP	Near-miss Milepost, 42, 41
529	SJC	15	PTI	17	PTI	17	OAC-HAY	UP	Meet 528, Milepost, 13, 13
541	SJC	33	ITI	30	ITI	30	SAC-SAC	UP	Wait for 528 trainset 528
542	SAC	13	TEN	9	SYS	8	SJC-SJC	UP	Re-crew / job briefing Crew arrived late on Amtk541 also still needed to do proper job briefing and shuffle from track 8 to 1, Milepost, 47.6, 46.9
543	SJC	25	ITI	33	ITI	33	SAC-SAC	UP	Service, turn, or wye train 532
545	OKJ	30	TEN	26	TEN	19	SAC-SAC	UP	Low coolant on engine 2012. Had to add water. Has been activating Low Coolant sensor all day. C2012
51	CHI	125	FTI	175	FTI	90	XH0-COI	CS	Meet m36118, Control Point, McGonigle
500	SEA	24	MBO	17	MBO	17	PDX-VAN	BN	For maritime traffic Bridge, wilamette
516	VAC	59	FTI	56	FTI	51	XF2-X1J	BN	Meet CN 5754, Control Point, Still Creek
821	FTW	28	DSR	29	RTE	19	GLE-FTW	BN	Lined for circus track instead of heartland lead had to wait for switch to time out Other, FTW
822	OKC	55	FTI	40	FTI	33	FTW-GLE	BN	Meet bnsf, Siding, metro
562	SAN	35	CTI	28	DCS	13	LAX-XRJ	BN	Restrictive signal(s) from known wayside signal failure Code brown dispatcher signal problems flagged, Red / san pedro jct, Control Point, san pedro jct

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Region: ALL

Service: ALL

Arriving On: 10/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
564	SAN	31	DCS	32	CTI	13	SOL-SOL	SN	Meet coaster, Control Point, valley
566	SAN	19	DCS	27	DCS	14	LAX-XRJ	BN	Restrictive signal(s) from known wayside signal failure Waited for authority to pass a red signal at Soto, Stop, Control Point, soto
572	SAN	53	DCS	41	DCS	31	LAX-XRJ	BN	Restrictive signal(s) from unknown cause Flagging at Soto, Stop, Control Point, soto
573	LAX	31	DCS	30	DCS	30	FUL-XRJ	BN	Restrictive signal(s) from known wayside signal failure BNSF signal problems, Red / east hobart, Control Point, east hobart
761	SLO	63	DCS	50	DCS	30	FUL-XRJ	BN	Signal suspension Major signal "meltdown" (possibly precipitated by AWS). Affected all tracks, all trains. Had to be flagged thru several red signals., Other, East Hobart-Soto
765	GTA	41	DCS	64	DCS	59	FUL-XRJ	BN	Flagging at San Pedro and Soto Control Point, San Pedro, Control Point, Soto
769	GTA	53	DCS	47	DCS	41	FUL-XRJ	BN	CTC system failure Control Point, W. Hobart
774	SAN	82	DCS	110	DCS	66	LPS-X3G	UP	Restrictive signal(s) from known wayside signal failure Red, Control Point, sudden
794	SAN	39	POL	41	POL	41	SIM-SIM	SC	Right of Way police hold
715	OKJ	39	FTI	33	FTI	17	BFD-WAC	BN	Meet bnsf 3943, Siding, Wasco
3	LAX	172	FTI	140	SYS	68	LAJ-LAJ	BN	Crew rest
319	KCY	69	FTI	35	FTI	25	JEF-SED	UP	Meet Saw by move and take conductor to head end once in the clear, UP5714, Siding, Dow
1333	MSP	17	DSR	20	DSR	14	XH8-MSP	CP	Per bulletin Milepost, 402.5, 402.6, 25, 2, Milepost, 410.6, 410.9, 25, 2, Milepost, 406.2, 406.3, 25, 2, Milepost, 422.1, 422.3, 25, 2
1340	CHI	21	OTH	17	OTH	13	XRO-GLN	ME	Unk emergency application.

Amtrak Initial Terminal Details

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/20/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	80	10/20	75	75	Pick up rescue locomotive due to mechanical failure Add locomotive 355 from Am 20 b, 37
HAR	624	10/20	1		
MIA	40	10/20	66	66	PTC- Unplanned PTC system /server outage PTC unable to initialize w/ only SFRTA. Contacted CNOC PTC support to diagnose system. Received permission to run w/o PTC from SFRTA., Other, MIA
PHL	110	10/20	1		
PHL	190	10/20	1		
PHL	601	10/20	5	5	PTC - Stop Bypass Permission Required, Control Point, N. PENN, STOP BY PASS DEPARTING THE YARD
WAS	184	10/20	35	25	HEP, 648
WAS	184	10/20	35	10	Re-crew / job briefing, CREW HELD OFF BOARDING
WAS	2122	10/20	2	2	Service, turn, or wye train, 2159, Train arrived late
ALB	244	10/20	3	3	PTC-caused slow-down or penalty stop Control Point, 142
NYP	19	10/20	2	2	Passenger and/or baggage, BOARDING
NYP	49	10/20	6	6	Other electrical failure, 710 702, OPERATING ON DEISEL ENGINE OUT OF THE YARD A/C NOT ABLE TO DRAW ENOUGH POWER FOR THE CONSIST
NYP	97	10/20	50	50	Hold for connecting train, HLD FOR 10 CONNECTIONS OF AM93
NYP	129	10/20	4	4	Wait for station track, 49, Other, NYP-NYP, LATE FROM SSYD A/C CONGESTION CAUSED BY AM49
NYP	133	10/20	12	12	Passenger and/or baggage, BOARDING
NYP	183	10/20	6	6	Passenger and/or baggage, LATE LOADING
NYP	193	10/20	4	4	Wait for station track, 49, Other, NYP-NYP, LEFT SSYD LATE A/C CONGESTION ON LINE 1 CAUSED BY AM49 OPERATING UNDER DIESEL TO CLEAR TUNNEL
NYP	237	10/20	3	3	Passenger and/or baggage, LOADING
NYP	239	10/20	2	2	Passenger and/or baggage, LOADING
CHI	7	10/20	85	85	Set out defective car 32057, Bad ordered @ 1:48
CHI	41	10/20	2	2	Wheelchair Lift
CHI	319	10/20	2	2	Rear door on service side was left open when departing station in business class.
PDX	28	10/20	19	19	Late bulletins due to Amtrak cause Contacted Pasco West dispatcher at 4:04 pm. for orders. Per Pasco West dispatcher, "Train 28 not scheduled." Will send orders. Delay waiting on orders., Other, Portland Station
PDX	518	10/20	6	6	Held for or routed around MW work or equipment Reports of water main breakage; held @ PDX to await inspection/repair if required, Milepost, 1.5, 1.5

Amtrak Initial Terminal Details

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/20/2025

Terminal	Train	Date	Late	Delay	Cause
QCY	380	10/20	1	1	Door issues with amfleet cars :cafe
SEA	8	10/20	225	165	Late train WYE and late equipment swop Sleeper car. Equipment later removed and bad ordered.. Train 8
SEA	505	10/20	5	5	Air / Brake / Wheel 7911, Late spot at depot due to mechanical truing wheels on cabcar
SEA	511	10/20	10	10	Late Yard Release
STL	302	10/20	8	8	Late bulletins due to Amtrak cause
ARN	529	10/20	1		
BFD	717	10/20	1		
GTA	784	10/20	1	1	Passenger and/or baggage Coach passengers walked from north end business area to south end of platform for coaches with large bags.
LAX	14	10/20	13	13	Hold for connecting train 765
OKJ	712	10/20	2	2	Door C9013
OKJ	714	10/20	2	2	Waiting for MW clearance Other, Okj depot
OKJ	718	10/20	6	6	Wait to leave yard until they passed amt 542, Control Point, magnolia
SAC	541	10/20	30	30	Wait for 528 trainset 528
SAC	543	10/20	33	33	Service, turn, or wye train 532
SAC	545	10/20	24	19	Low coolant on engine 2012. Had to add water. Has been activating Low Coolant sensor all day. C2012
SAC	547	10/20	1	1	Passenger and/or baggage Passenger issue needed to be addressed before departure.
SAC	551	10/20	2	2	Loading problem C2001
SAC	702	10/20	1		
SAN	765	10/20	3	3	Meet Waited for Coaster 620 at CP Ash. Per dispatcher., coaster, 620, Control Point, ash
SJC	542	10/20	8	8	Re-crew / job briefing Crew arrived late on Amtk541 also still needed to do proper job briefing and shuffle from track 8 to 1, Milepost, 47.6, 46.9

Eastern Region

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	96.8	98.8	94.8	309	10
CDOT	95.0	100	97.3	92.4	20	0
MARC	95.0	77.2	89.6	83.5	57	13
SEPTA	95.0	92.9	93.8	91.5	210	15
NJT-NED	95.0	91.5	93.2	93.8	370	32
NJT-SED	95.0	95.8	99.3	97.2	24	1

Operating Highlights

Train 177(20) Trenton, NJ - Police Related

20OCT25: Train 177(20) operating with engine 618, 10 cars and 257 passengers onboard, Amtrak AMT Northeast subdivision, was delayed at the Trenton Station due to a fare evader. The passenger was spoken to by an Amtrak Police Officer and the conductor onboard the train prior to their arrival into the Princeton Junction Station. They were advised that they would be removed at the Princeton Junction Station due to fare evasion but refused to get off the train. New Jersey Transit Police were contacted and met the train upon its arrival into the Trenton, NJ Station. The police spoke with the passenger for a period before convincing them to detrain.

Train	Delay	Comment
177(20)	11"	PJC
177(20)	29"	TRE

Train 475(20) Meriden, CT - Passenger Related

20OCT25: Train 475(20) was delayed at Meriden station due to a passenger in need of EMS. The passenger was removed by EMS. Passengers connecting to train 175(20) were transferred to CT 4461.

Train	Delay	Comment
475(20)	31"	

Train 40(20) North of Lakeland, FL -Vehicle Strike/ Freight Train Interference

20OCT25: Train 40(20) operating with engine 313 and 368, 10 cars and 188 passengers, was delayed north of Lakeland on the CSX Lakeland subdivision at SE Cherry / MP 863.4 due to freight train CSX IO44-20 that struck a vehicle ahead at MP A869.4. The vehicle was removed, Train 40(20) had to wait for CSX IO44-20 to clear before proceeding north.

Train	Delay	Comment
40(20)	1'16"	

Train 20(20) South of Meridian, MS - Freight Train Interference

20OCT25: Train 20(20) was delayed at the NS 160255 subdivision at MP 2.4 due to meeting NS345.

Train	Delay	Comment
20(20)	51"	

Train 184(20) Washington, DC - Engine Failure

20OCT25: Train 184(20) was delayed departing Washington due to E/648 being shopped and replaced with E/667.

Train	Delay	Comment
184(20)	35"	

Train 40(20) Miami, FL - SFRTA PTC Issues/Signal

20OCT25: Train 40(20) with E/313,E/36 was delayed departing Miami due to having problems with PTC. The crew and Road Foreman were troubleshooting with CNOC Mechanical and determined that the issue was on the SFRTA. The SFRTA approved the train to operate with no PTC.

Train	Delay	Comment
40(20)	1'06"	

New York to Philadelphia Main Line - Bridge Strike

20OCT25: At 1137A-ET A vehicle struck the bridge at McClellan ST., MP 12.37, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph on tracks 2,3, and 4 until an inspection could be performed. At 1242P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
2155(20)	04"	
119(20)	04"	

New York to Philadelphia Main Line - Bridge Strike

20OCT25: At 928A-ET A vehicle struck the bridge at Nottingham Way, MP 55.2, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 1014A-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
98(19)	06"	
2151(20)	03"	
112(20)	07"	
600(20)	07"	
172(20)	06"	
141(20)	05"	

Train 646(20) Lancaster, PA - Car Failure

20OCT25: Train 646(20) with E/668 and C/668 with 96 passengers onboard was stopped at Lancaster station due to C/82751 having possible 3-3.5 inch flat spots. Amtrak Mechanical was enroute to the train. Train 646(20) discharged the 96 passengers onboard and they were picked up by 648(20). Train 646(20) equipment was okayed by mechanical to shift east of Conestoga to open station track in Lancaster then proceed at 10MPH back into Harrisburg. Due to this train 646(20) was terminated at Lancaster and Train 655(20) was cancelled New York to Harrisburg.

Train	Delay	Comment
646(20)	TERM LNC	
655(20)	CANCELLED	

Train 171(20) West of Route 128, MA - Pantograph Alarm/Engine Failure

20OCT25: Train 171(20) with E/652 and 8 cars with 376 passengers onboard stopped on the New Haven to Boston main line at MP 210.6/Sharon on track 1 due to a pantograph alarm. The crew inspected and found a wire tangled around the pantograph. Amtrak ET and Road Foreman was enroute. Train 171(20) conductor confirmed the train was without HEP since 825A-ET. Keolis 825 will pick up approximately 40 passengers from 171(20) to take them to Providence. The weather was 64 degrees and cloudy. Boston was getting rescue engines ready with management and a tech onboard. Service Recovery was initiated with snack packs and water. Passengers conditions onboard were reported as good. As of 942A-ET, ET and Amtrak Road Foreman arrived on scene. Train 93(20) and 85(20) were held for a possible transfer. As of 952A-ET, Amtrak Road Foreman placed a hold on track 2 at 171(20) location to assist ET. As of 1018A-ET, Amtrak Road Foreman reported that the wire was removed and they were attempting to raise the pantograph but they were still in process of charging the air to raise pantograph with the aux motor. As of 1035A-ET, The pantograph was raised and as of 1040A-ET the HEP was restored. No passengers were transferred.

Trains 97(20) was held in New York due to 10 connections off late 93(20).

WBS#: B.TR.100151.0785

Train	Delay	Comment
93(20)	34"	
171(20)	2'08"	
85(20)	38"	
97(20)	50"	NYP FOR CONNECTIONS

Train 97(19) Florence, SC - Miscellaneous Amtrak Responsible

20OCT25: Train 97(19) operating with engines 340 and 348, 11cars and 137 passengers, was delayed departing Florence, SC due to the late arrival of the outbound engineer. After the engineer arrived, they had PTC issues which further delayed the train.

Train	Delay	Comment
97(19)	1'37"	

Train 80(20) Charlotte, NC - Engine Failure

20OCT25: Train 80(20) ~~26-FOI-00072~~ ~~00000005031~~ engine 37 car 10/29/2026 86 passengers, took a delay departing Charlotte, NC due to engine faults experienced on Train 79(19). The crew experienced amperage and loading issue on Train 79(19). To protect service, an engine was taken off inbound late Train 20(19), currently operating with engines 355 and 302, at Charlotte, NC and it was added to Train 80(20). Train 80(20) will operate with engines 355 and 37 from Charlotte, NC to Washington, D.C. and Train 20(19) operated with a single engine 302 from Charlotte, NC to Washington, DC.

Train	Delay	Comment
80(20)	1'15"	
20(19)	NONE	CUTTING E/355

26 F O C 0 0 7 7 0000005031 UNCLASSIFIED
Downeaster Trackwork CSX Portland Sub-M of W Work

22SEP25: Downeaster Service Adjustments due to CSX Portland Subdivision trackwork between Brunswick, ME and Boston North, MA station. They are welding , switch timbers and tie pickup between Wells, MA and Brunswick on the following Tuesday thru Thursday from 8A-ET to 530P-ET. On September 30,2025 to October 02,2025, October 7-9, 2025, October 14-16, 2025, October 21-23, 2025, October 28-30, 2025 and November 4-6, 2025. The following service adjustments will be made:

Northbound:

- Train 681(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BON and BRK, will terminate at WEM.
- Train 683(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BON and BRK is cancelled in its entirety with no alternate transportation.

Southbound:

- Train 684(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BRK and BON, is cancelled in its entirety with no alternate transportation.
- Train 686(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BRK and BON, will originate at WEM.

WBS#: B.TR.100151.0776

Train	Delay	Comment
681	TERM WEM	WITH ALT TRANS
684	CANCELLED	NO ALT TRANS
686	ORIG WEM	WITH ALT TRANS
683	CANCELLED	NO ALT TRANS

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(02JUN-26JUL) terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02JUN-28JUL) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

22APR25: Amtrak MRS-26-FOI-00072 No 00000005031 t D UNCLASSIFIED track 10/29/2025 between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

• Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

• Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

• Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

• Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

• Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

• Bus 3470 will provide alternate transportation between HFD and SPG

• Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

• Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

• Deadhead Train 426 will turn for Train 471 at HFD

• Train 470 will turn for Train 473 at HFD

Eastern Region

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 475(20) Passenger Removal at Meriden, Connecticut – Medical***

20OCT25, Passenger on CT Rail Ticket boarded the train at Hartford, CT traveling to New Haven, CT was removed by EMS at Meriden, CT due to throwing up in his seat, sweating profusely and seemed to be very confused. Amtrak Police notified.

Delay: 475 (20) 31"

Train 177(20) Passenger Removal at Trenton, New Jersey – Improper Conduct

20OCT25, Passenger boarded the train at New York, NY trying to get to Philadelphia, PA. She was being disruptive in the quiet car causing a disturbance to the other passengers. She refused to listen to anything the Conductor or Assistant Conductor had to say. She was removed by New Jersey Transit Police at Trenton, NJ. Amtrak Police notified.

Delay: 177 (20) 29"

Operating Highlights

Train 5(19) Salt Lake City, UT - Servicing

21OCT25: Train 5(19) was delayed at Salt Lake City, UT/MP745.1 on the UP Provo subdivision holding for a scheduled pump truck. The truck was reportedly running forty five minutes late. Train 5(19) held for the truck due to ADA passengers in coach car 34116 that could not be moved. Once the cars were pumped, train 5(19) continued west.

Train	Delay	Comment
5(19)	1'24"	

Train 562(20) East of Los Angeles, CA - Signal

20OCT25: Train 562(20) was delayed east of Los Angeles, CA (LAX) at CP Sudden on the Burlington Northern Santa Fe Railway San Bernardino Subdivision. There was a problem with the signal system between CP Soto and CP Hobart which required the engineer to obtain verbal authority from the train dispatcher and operate at reduced speeds in the area. Once clear of CP Hobart train 562(20) was able to resume operation at maximum authorized track speeds.

UPDATE: This issue continued to exist for the majority of the day while technicians from the BNSF Signal department worked on repairs. Multiple trains were delayed as a result.

Train	Delay	Comment
562(20)	25"	
566(20)	27"	
564(20)	30"	
572(20)	31"	
761(20)	35"	
765(20)	1'03"	
770(20)	24"	
774(20)	36"	
769(20)	47"	
14(20)	13"	ITD - LAX Hold for connection from late 765(20)
573(20)	30"	

Train 8(20) Seattle, WA - Car Failure

20OCT25: Train 8(20) was delayed departing the initial terminal at Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. There was a mechanical issue with sleeping car C/32064 which required the car be removed from the train prior to departure. Once the car was removed and passengers accommodated train 8(20) was able to depart SEA.

WBS#: B.TR.100150.6192

Train	Delay	Comment
8(20)	2'45"	

Train 41(20) West of South Bend, IN - Freight Train Interference

20OCT25: Train 41(20) was delayed between mile post 435.0 and mile post 426.0 beginning 3.5 miles west of South Bend, IN/MP438.6 on the NS Elkhart West subdivision following NS freight NS268. Once the route was clear, train 41(20) continued west.

Train	Delay	Comment
41(20)	41"	

Train 822(20) South of Gainesville, TX - Freight Train Interference

20OCT25: Train 822(20) was delayed at siding MP388.5 22 miles south of Gainesville, TX/MP410.78 on the BNSF Fort Worth subdivision meeting BNSF freight. Once the route was clear, train 822(20) continued north.

Train	Delay	Comment
822(20)	33"	

Train 3(19) Albuquerque, NM - Car Failure

20OCT25: Train 3(19) was delayed departing Albuquerque, NM/MP902.45 on the NMRX Albuquerque subdivision setting out coach car 34134 for a broken carriage bolt. Lower level passengers were moved to coach or reaccommodated. Once the equipment was made up again, train 3(19) departed Albuquerque, NM.

Train	Delay	Comment
3(19)	1'49"	

Train 516(20) North of Bellingham, WA - Freight Train Interference

20OCT25: Train 516(20) was delayed north of Bellingham, WA (BEL) at CP Still Creek on the Canadian National New Westminster Subdivision. Train 516(20) was held for a freight train, CN/5754 to clear the single main track ahead. Once the track ahead was clear, train 516(20) was able to proceed north.

Train	Delay	Comment
516(20)	51"	

Train 59(19) North of New Orleans, LA - Freight Train Interference

20OCT25: Train 59(19) was delayed at East Bridge/MP906.0, 5 miles north of New Orleans, LA, on the CN McComb Subdivision, waiting on freight cross-traffic to clear ahead.

Train	Delay	Comment
59(19)	45"	

Train 1(20) West of Lake Charles, LA - Fire Department Activity

20OCT25: Train 1(20) was delayed at Sulphur/MP229.6, 11 miles west of Lake Charles, LA, on the UPRR Lafayette Subdivision, due to local fire crews on the scene of multiple tie fires ahead between MP236 and MP239. Train 1(20) was delayed holding for open route through the area. UPRR carman responded to location and found MIKEW-20 (UP 6619) with a loaded coal car dropping smoldering coal resulting in the tie/brush fires. UP 6619 cleared into Echo siding and planned to set out car once traffic resumed. Train 1(20) held for track inspection and fire department to clear route ahead.

Due to the late operation of train 1(20) the following service recovery is in effect:

- First Class passenger meals will not be affected.
- Snack packs and water have been distributed among the passengers.
- Coffee, tea, juice, and discounted or comped items from the lounge are available.

Train	Delay	Comment
1(20)	1'59"	

Train 526(20) Emeryville, CA - Third Party Contractor Engine Failure

20OCT25: Train 526(20) 26-FOR-00072 del 0000005031 Eme UNCLASSIFIED CA 10/25/2025 on the Union Pacific Railway Martinez Subdivision. Locomotive CDTX/2012 shut down and failed to provide tractive effort, head end power remained operational off the auxiliary generator and was not interrupted. Technicians from the state mechanical contractor responded to the scene to assist the crew with repairs; simultaneously a protect locomotive was prepped at Oakland Maintenance Facility to be dispatched as a rescue locomotive for train 526(20) in the event that repairs were not able to be made. Technicians were able to identify the issue as a failed coolant level sensor, and were able to replace the sensor in the field, enabling train 526(20) to resume operation. With repairs complete, train 526(20) departed EMY at 9:48 PM-PT.

UPDATE: Train 526(20) was further delayed east of Davis, CA (DAV) on the Union Pacific Railway Martinez Subdivision. Locomotive CDTX/2012 failed to provide tractive effort a second time. The crew was able to resolve the issue and limpt the train to Sacramento, CA. The following modification were made to Capitol Corridor Service account the repeated failures of locomotive CDTX/2012:

- 528(20) would turn in Sacramento, CA to represent train 541(20).
- 532(20) would turn in Sacramento, CA to represent train 543(20).
- Once a mechanical assessment was complete, 526(20) would turn in Sacramento to represent train 545(20), a technicians from TASI Mechanical would ride on the locomotive to assist in the event of another failure and monitor the performance of the locomotive.

Service Recovery: 20% Discount on cafe car purchases.

Train	Delay	Comment
526(20)	1'01"	
526(20)	21"	E. DAV
541(20)	30"	ITD- SAC abnormal equipment rotation
543(20)	33"	ITD- SAC abnormal equipment rotation
545(20)	19"	ITD - SAC - Add coolant to CDTX/2012
542(20)	08"	ITD - SJC - Late turn inbound crew from 541

Train 7/27(20) Late Departure Chicago, IL - Car Failure

20OCT25: Train 7/27(20), E/163-E/311 & 10 cars, was delayed departing Chicago, IL, due to late shop of sleeper C/32057 for a water leak. It was necessary to send equipment back to the yard to swap out. C/32057 was cut out and replaced with C/32023.

Train	Delay	Comment
7/27(20)	1'25"	

Train 774(20) South of Lompoc-Surf, CA - Signal

20OCT25: Train 774(20) was delayed south of Lompoc, CA (LPS) on the Union Pacific Railway Santa Barbara Subdivision. There was a problem with the signal system at CP Sudden, and a signal maintainer had track authority to hi-rail into the location to being repairs. Train 774(20) was held at MP 304.6 to allow the signal maintainer to safely access the location. Once the signal maintainer released their main track authority, train 774(20) was able to proceed on verbal authority from the train dispatcher and operate at reduced speed through the affected area.

Train	Delay	Comment
774(20)	1'06"	
761(20)	26"	Seacliff, meet late 774
761(20)	16"	Signal Issues

Train 3(19) La Junta, CO - Programmed Equipment Move

20OCT25: Train 3(19) was delayed at La Junta, CO/MP554.9, on the BNSF Boise City Subdivision, cutting off E/134-E/85-C/43382-C/10020, for a planned equipment move.

Train	Delay	Comment
3(19)	1'09"	

Train 1(20) North of New Orleans, LA - Freight Train Interference

20OCT25: Train 1(20) was delayed at East Bridge Junction/MP3.0, 5 miles north of New Orleans, LA, on the New Orleans Public Belt, waiting on UPRR cross-traffic to clear ahead.

Train	Delay	Comment
1(20)	33"	

Train 8/28(19) Sandpoint, ID - Passenger Removal

20OCT25: Train 8/28(19) was delayed at Sandpoint, ID/MP3.1, on the BNSF Kootenai River Subdivision, due to local police responding for a disorderly passenger (PNR C732E2 PDX-CHI) that assaulted the assistant conductor. Local PD removed the passenger and then took statements from the assistant conductor and witnesses. APD notified.

Train	Delay	Comment
8/28(19)	30"	

Train 7/27(19) Minot, ND - MW Curfew

20OCT25: Train 7/27(19) was delayed at Minot, ND/MP0.5, on the BNSF Glasgow Subdivision, due to CPKC MW curfew just west of Minot at SOO Tower/MP0.7. Train 7/27(19) was delayed holding for open route ahead.

Train	Delay	Comment
7/27(19)	44"	

Train 5(19) West of McCook, NE - Weather

20OCT25: Train 5(19) was delayed west of McCook, NE/MP287.8, on the BNSF Brush Subdivision, operating through high wind warnings between MP453 and MP476 and between MP506 and MP521. Train 5(19) was delayed operating 20MPH MAX through the affected area.

Train	Delay	Comment
5(19)	1'59"	

Train 21/421(19) South of Hope, AR - Freight Train Interference

20OCT25: Train 21/421(19) was delayed at MP459.3, 2 miles south of Hope, AR, on the UPRR Little Rock Subdivision, due to UPRR work train WMLMRE-14 (UP 4583) stalled on the main ahead at MP460. MEWNL-19 (UP 6453) tied down train at MP469 and cut lite power to assist UP 4583 in the clear. Train 21/421(19) was delayed holding for open route through the area.

Train	Delay	Comment
21/421(19)	1'38"	

Train 51(19) West of Cincinnati, OH - Freight Train Interference

20OCT25: Train 51(19) was delayed beginning at Chillicothe/MP322.1 31 miles west of Cincinnati, OH/MP2.1 on the CSX Indianapolis subdivision meeting multiple CSX freights. Once the route was clear, train 51(19) continued west.

Train	Delay	Comment
51(19)	1'30"	

Train 3(18) West of Flagstaff, AZ - Freight Train Interference

20OCT25: Train 3(18) was delayed beginning at Chalender/MP368.1 24 miles west of Flagstaff, AZ/MP344.2 on the BNSF Seligman subdivision due to heavy freight congestion. Once the route was clear, train 3(18) continued west at track speed. Train 3(18) was further delayed following freight traffic between MP439.5 and MP483.9.

Train	Delay	Comment
3(18)	35"	MP344.8-MP362.1
3(18)	43"	MP439.5-MP483.9

Train 8(19) East of Everett, WA - Freight Train Interference

19OCT25: Train 8(19) was delayed east of Everett, WA (EVR) at CP Baring on the Burlington Northern Santa Fe Railway Scenic Subdivision. A freight train, V-SPOTAC1-18A (BNSF/5807), was stopped blocking the single main track ahead between CP Skykomish and CP Scenic with a broken draw bar. Crews worked to set out the disabled car into the siding track at CP Skykomish and then advance the rest of the freight train into the siding at CP Scenic to open at route for train 8(19). Once an open route was available, train 8(19) was able to proceed east.

20OCT25: Due to the late operation of Train 8/28(19), alternate transportation was secured at St. Paul-Minneapolis, MN and La Crosse, WI, for passengers with connecting travel out of Chicago.

WBS#: B.TR.100150.6190

Train	Delay	Comment
8(19)	5'31"	

26-501-07073 00000040311 "UNCLASSIFIED" 06/23/2025

Michigan Department of Transportation Michigan Line affecting Wolverine Service - Scheduled M/W Work

05MAY25: Amtrak will be performing a track rehabilitation by modifying a curve between Chelsea, MI / MP 56.0 and Ypsilanti, MI / MP 28.2, which encompasses the Ann Arbor, MI station at MP 37.5, on the Michigan Department of Transportation Michigan Line. The follow operating plan will be placed in to effect:

May 5th through June 26th (except for May 26th and June 19th):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

August 4th through October 30th (except for September 1st):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

WBS#: B.TR.100150.5512

Train	Delay	Comment
350 & 353 (27MAY - 29MAY)	Cancel	
350 & 353 (16JUN - 18JUN)	Cancel	
350 & 353 (23JUN - 26JUN)	Cancel	
350 & 353 (04AUG - 07AUG)	Cancel	
350 & 353 (11AUG - 14AUG)	Cancel	
350 & 353 (18AUG - 21AUG)	Cancel	
350 & 353 (25AUG - 28AUG)	Cancel	
350 & 353 (02SEP - 04SEP)	Cancel	
350 & 353 (08SEP - 11SEP)	Cancel	
350 & 353 (15SEP - 18SEP)	Cancel	
350 & 353 (22SEP - 25SEP)	Cancel	
350 & 353 (29SEP - 02OCT)	Cancel	
350 & 353 (06OCT - 09OCT)	Cancel	
350 & 353 (13OCT - 16OCT)	Cancel	
350 & 353 (20OCT - 23OCT)	Cancel	
350 & 353 (27OCT - 30OCT)	Cancel	

Western Region

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
6 (3)	GSC	205		Boulder strike

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
8(20)	3	No	Pax were partially downgraded to coach SEA-SPK & were given a room SPK to their destination due to c/32065/0831 being set out at SEA

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Passengers	Disposition	Cost
None			

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 354(20) Passenger Removal at New Buffalo, Michigan – Improper Conduct***

20OCT25, Passengers on PNR 9AAA89, traveling from Chicago, IL to Jackson, MI were removed by Conductor at New Buffalo, MI due to having a verbal altercation the one passenger went to spit on that other passenger and missed and spit on an unrelated passenger. The police were contacted and when they found out they were coming they left the train and headed toward the beach yelling at each other. Amtrak Police notified.

Delay: 354(20) 03"

Train 6(20) Passenger Removal at Winnemucca, Nevada – Improper Conduct

20OCT25, Passenger on PNR C904DC, traveling from Reno, NV to Salt Lake City, UT was removed by the Lander County Sheriff at Winnemucca, NV due to being extremely intoxicated from consuming their own alcohol. Passenger started making racial comments to other passengers making them uncomfortable. Amtrak Police notified.

Delay: 6(20) 09"

Train 794(20) Passenger Removal at Carpinteria, California – Improper Conduct

26-FOI-00072 00000005031 "UNCLASSIFIED" 10/29/2025

20OCT25, Passenger on PNR CA0BBA, traveling from Santa Barbara, CA to San Diego, CA was removed by the Conductor at Carpinteria, CA due to yelling that someone stole her wallet making a big scene. The Assistant Conductor pointed out her wallet was in her bag. She started saying she was going the wrong way and wanted to get off. At Carpinteria the Conductor talked her off the train. She was disturbing everyone around her. Amtrak Police notified.

Delay: **794(20)** **05"**

Consist Deviations

26-FOI-00072

00000005031

"UNCLASSIFIED"

10/29/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
5 (20)	CHI	38056 REPLACED B/O 33044 BEST AVAILABLE	NA	0	38056
58 (20)	NOL	37009 Cross-Country Diner in lieu of standard 33XXX series lounge car, no OKM lounge in NOL.	N/A	0	37009

Reverse Consists

Train Number	Station	Reason
171 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front
134 (20)	RNK	Consist reversed Business class seat orientation may have changed At Front
138 (20)	NFK	Consist reversed Business class seat orientation may have changed At Front
197 (20)	NYP	Consist reversed Business class seat orientation may have changed At Rear
183 (20)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (20)	NYP	Consist reversed Business class seat orientation may have changed At Front
182 (20)	NYP	Consist reversed Business class seat orientation may have changed At Rear
133 (20)	NYP	Consist reversed Business class seat orientation may have changed At Front
192 (20)	WAS	Consist reversed Business class seat orientation may have changed At Rear
85 (21)	BOS	Consist reversed Business class seat orientation may have changed At Front