



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, July 16, 2025

Rules:0-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/15/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	296	42	85.8%	4,316	549	87.3%	83,023	8,218	90.1%
Central Division	91.5%	65	7	89.2%	992	112	88.7%	19,021	1,852	90.3%
Northeast Division	95.0%	95	16	83.2%	1,359	199	85.4%	27,314	2,962	89.2%
Southeast Division	94.5%	67	10	85.1%	946	127	86.6%	18,375	1,841	90.0%
Southwest Division	90.5%	69	9	87.0%	1,019	111	89.1%	18,313	1,563	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/15/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	93,423	29,148	69%	1,574,597	504,423	68%	26,959,990	7,222,404	73%
Northeast Corridor	80%	42,231	12,345	71%	675,407	204,860	70%	11,975,817	3,081,506	74%
Acela	82%	8,776	1,861	79%	136,040	40,404	70%	2,489,957	595,070	76%
Northeast Regional	78%	33,455	10,484	69%	539,367	164,456	70%	9,485,860	2,486,436	74%
Richmond / Newport News / Norfolk	73%	10,457	3,895	63%	171,993	73,889	57%	3,062,145	1,046,426	66%
Springfield Shuttles	89%	389	74	81%	6,338	1,300	79%	172,335	25,944	85%
Roanoke	70%	2,641	1,020	61%	46,163	13,790	70%	800,340	211,015	74%
On Spine Northeast Regional	83%	19,968	5,495	72%	314,873	75,477	76%	5,451,040	1,203,051	78%
State Supported	80%	37,468	8,646	77%	694,920	180,348	74%	11,506,467	2,540,081	78%
Borealis	60%	537	394	27%	9,602	6,391	33%	166,309	69,569	58%
Capitol Corridor	90%	3,611	651	82%	53,002	4,239	92%	862,197	92,943	89%
Carolinian	60%	1,002	926	8%	15,564	8,809	43%	331,374	137,233	59%
Cascades	60%	2,211	455	79%	45,894	12,505	73%	728,774	250,531	66%
Downeaster	82%	1,599	359	78%	28,059	8,020	71%	406,741	101,013	75%
Empire	83%	5,048	1,627	68%	88,761	34,194	61%	1,550,743	336,490	78%
Adirondack	75%	368	357	3%	6,355	4,099	35%	84,350	26,798	68%
Ethan Allen Express	85%	548	88	84%	9,635	6,216	35%	154,846	39,540	74%
Maple Leaf	75%	760	687	10%	13,670	8,346	39%	209,747	63,509	70%
New York - Albany	90%	2,202	495	78%	34,741	8,587	75%	721,717	112,021	84%
New York - Niagara Falls	75%	1,170	0	100%	21,920	5,438	75%	375,753	92,337	75%
Berkshire Flyer	60%	0	0	-	2,440	1,508	38%	4,330	2,285	47%
Heartland Flyer	70%	217	82	62%	3,780	2,955	22%	63,299	29,018	54%
Hiawatha	90%	1,621	243	85%	32,512	3,909	88%	483,024	63,274	87%
Illinois	78%	1,133	82	93%	43,641	15,213	65%	714,053	172,290	76%
Carl Sandburg / Illinois Zephyr	80%	301	71	76%	7,470	1,552	79%	114,148	14,641	87%
Illini / Saluki	80%	559	0	100%	14,310	4,207	71%	252,607	33,078	87%
Lincoln Service	75%	273	11	96%	21,861	9,454	57%	347,298	124,571	64%
Keystone	92%	8,497	309	96%	113,927	9,966	91%	2,078,715	284,648	86%
Lincoln / Missouri	60%	714	706	1%	13,202	9,039	32%	207,179	113,920	45%
Michigan	69%	1,829	505	72%	38,403	9,966	74%	556,418	156,425	72%
Blue Water	70%	458	295	36%	9,568	2,479	74%	138,167	40,371	71%
Pere Marquette	85%	254	0	100%	4,587	693	85%	73,663	9,325	87%
Wolverine	65%	1,117	210	81%	24,248	6,794	72%	344,588	106,729	69%
Missouri	80%	186	157	16%	3,999	3,094	23%	62,831	22,582	64%
Pacific Surfliner	85%	5,121	239	95%	113,511	16,726	85%	1,648,120	266,077	84%
Pennsylvanian	72%	809	139	83%	14,629	4,285	71%	250,644	66,666	73%
Piedmont	73%	689	414	40%	14,762	5,497	63%	323,953	78,919	76%
San Joaquins	73%	1,959	759	61%	41,612	19,113	54%	705,424	193,483	73%
Vermont	75%	685	599	13%	20,060	6,427	68%	366,669	105,000	71%
Long Distance	57%	13,724	8,157	41%	204,270	119,215	42%	3,434,181	1,597,215	53%
Auto Train	57%	783	373	52%	12,635	4,062	68%	215,407	135,265	37%
California Zephyr	45%	1,575	1,319	16%	17,701	13,967	21%	280,344	120,467	57%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	0	0	-	4,075	2,031	50%	78,125	39,046	50%
City Of New Orleans	75%	619	479	23%	8,227	3,271	60%	183,027	51,480	72%
Coast Starlight	65%	962	431	55%	16,342	5,070	69%	302,143	125,816	58%
Crescent	60%	976	547	44%	16,284	6,649	59%	248,352	64,173	74%
Empire Builder	55%	1,767	608	66%	18,377	11,156	39%	273,368	119,659	56%
Floridian	40%	1,618	1,340	17%	23,358	19,043	18%	386,713	282,823	27%
Lake Shore Ltd	70%	1,041	702	33%	17,170	6,534	62%	289,007	79,162	73%
Palmetto	65%	892	347	61%	15,098	8,042	47%	283,246	109,158	61%
Silver Meteor	45%	872	502	42%	16,258	10,787	34%	265,644	138,693	48%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,623	987	39%	16,391	12,618	23%	229,327	139,544	39%
Sunset Ltd	50%	0	0	-	3,988	2,124	47%	75,627	27,920	63%
Texas Eagle	60%	996	522	48%	18,366	13,861	25%	266,256	141,513	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 15, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	111,111	1,555,875	714	1,823,292	29,999,812	608

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	5,548	453,475	122	96,632	8,781,554	110
INFRASTRUCTURE PLANNED	90	2,983	453,475	66	90,129	8,781,554	103
FLEET RELIABILITY	83	18,951	1,555,875	122	287,831	29,999,812	96
TRAIN OPERATIONS	382	83,629	1,555,875	538	1,348,700	29,999,812	450

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 79(15) - Salisbury, NC - Trespasser Incident

16JUL25: Train 79(15) was delayed on the Norfolk Southern Montview-Salisbury Subdivision at Salisbury Station/MP 333.7 due to a vehicle stuck on the tracks ahead. Once the vehicle was removed and tracks were inspected, Train 79(15) continued.

Train	Delay	Comment
79(15)	35"	

Train 79(15) - South of Petersburg Station, VA - Weather

15JUL25: Train 79(15) was delayed on the CSX North End Subdivision ay MP 41.7 due to flash flood warnings.

Train	Delay	Comment
79(15)	39"	

Train 179(15) - Boston, MA - Engine Failure

15JUL25: Train 179(15) was delayed departing Boston South Station due to a late equipment swap at Southampton Yard. Reports from Southampton Yard reflect the engine being swapped.

Train	Delay	Comment
179(15)	2'02"	

Train 68(15) - South of Albany, NY - Engine Failure

15JUL25: Train 68(15) was delayed shortly after departing Albany-Rensselaer Station at MP 140.2 on the Amtrak Hudson Line due to an air brake fault on E/708. Mechanical support was dispatched from Albany to assist. The cause of the failure was an MU cabling malfunction. The train proceeded to NYP powered by trail engine 130.

Train	Delay	Comment
68(15)	49"	

CSX Heat Orders - Northeast and Southeast Regions

15JUL25:Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Alleghany, Kanawha, and New River.

Train	Delay	Comment
687(15)	06"	
685(15)	13"	
686(15)	10"	
683(15)	02"	
98(14)	07"	

Train 2108(15) Baltimore, MD - Engine Failure

15JUL25: Train 2108(15) with set 12 PC/2006,PC/2037 was delayed due to PC/2006 going to into undesired emergency. The crew was able to figure out it was a leaking toilet causing compressor issues. The train continued to proceed but was disabled in Newark with reports of smoke in the cab. Train 2108(15) was terminated in Newark, the passengers were transferred to trains 114(15) and 174(15) into New York. Rescue engine was sent from New York to take 2108(15) equipment back to Washington. Amtrak Road Foreman was on scene at 3P-ET. This caused Washington to short turn train 2163(15) for 2124(15) .

Train	Delay	Comment
2108(15)	TERM NWK	
2121(15)	CANCELLED	
2124(15)	16"	Turn off 2163(15)

Train 20(15) North of New Orleans, LA - Side Swipe Vehicle/Debris

15JUL25: Train 20(15) with E/325,E/324 and 8 cars reported they side swiped the passenger side mirror off a pick up truck working on a generator on the right way under the company name High Performance on the NS New Orleans subdivision at MP 7.1. No injuries reported to passengers or crew or the vehicle driver. Crew inspected the equipment and took no exceptions they were able to proceed north.

National Response Center Number: 1436959

Train	Delay	Comment
20(15)	21"	

Train 55(15) Originate Springfield, MA - Engine Failure

15JUL25: Train 55(15) with E/94 was experiencing head end power loss when attempting to accelerating at St Albans at departure time. Amtrak Road Foreman and Drummack responded but were unable to correct the problem. It was determined to deadhead 55(15) equipment to Springfield MA station and coupled with 475(15) equipment. No alternate transportation for passengers between St. Albans and Springfield.

Train	Delay	Comment
55(15)	1'15"	DHE TO SPG
475(15)	1'05"	SPG
55(15)	2'12"	SPG

Train 98(15) Miami, FL - Initial Terminal Delay

15JUL25: Train 98(15) was delayed outside Miami Station due to a SFRTA RTA 301 trespasser strike at Pompano MP SX 1001.68. This was a confirmed fatality. Local police and EMS were on scene. This also had train 40(15) holding in Miami . As of 1220P-ET, SFRTA released one track thru the area and train 98(15) and 40(15) were able to depart Miami.

Train	Delay	Comment
98(15)	4'20"	
40(15)	1'35"	

Train 84(15) Petersburg, VA - Weather - Flood Warnings

15JUL25: Train 84(15) was delayed due to flash flood warnings on NS Norfolk subdivision.

Train	Delay	Comment
84(15)	41"	

Train 63(15) New York, NY - Initial Terminal Delay

15JUL25: TRAIN 63(15) WAS DELAYED DEPARTING NEW YORK DUE TO ENGINE ISSUES.

Train	Delay	Comment
63(15)	32"	

Train 111(15) New York, NY - Initial Terminal Delay

15JUL25: Train 111(15) was delayed departing New York due to late release from the yard. This also delayed train 114(15) departing Washington due to late turn of equipment off 111(15).

Train	Delay	Comment
111(15)	1'09"	
114(15)	31"	

Northeast Corridor - Acela Cancellations

15JUL25: due to Acela Trainset 18 having FIP Faults and Propulsions issues, Trains 2155(15) and 2172(15) were cancelled in their entirety with no alternate transportation.

Train	Delay	Comment
2155(15)	Cancelled	
2172(15)	Cancelled	

Train 1(14)/421(13) East of Alpine, TX - Freight Train Interference

15JUL25: Train 1(14)/421(13) was delayed at Altuda/MP593, 14 miles east of Alpine, TX, on the UPRR Sanderson Subdivision, due to MEWWC-13 (UP 5950) ahead at MP603 with damaged cars from tie fire. UP 5950 cut away from rear section of train to clear tie fire leaving the rear cut on the bridge at that location. UPRR reported several damaged air hoses on cars requiring repair before recoupling to pull in the clear. UPRR mechanical, b&b and track responded to the scene. The bridge and track was inspected and okayed for service. Train 1(14)/421(13) was delayed holding for UP 5950 to repair air hoses to several cars, set out three damaged cars in Alpine siding and then couple to remainder of consist and pull in the clear. Train 1(14)/421(13) was further delayed following freight UP/5950 to Quebec Siding/MP660.9 in Valentine, TX.

Due to the late operation of train 1(14)/421(13) the following service recovery was put into effect:
Dinner for July 15th:
-Papa John's Pizza to be delivered in El Paso, TX for the coach passengers
-Normal traditional dining for the sleeper passengers
Breakfast for July 16th:
-Continental breakfast items - groceries to be delivered in El Paso, TX
-Passengers in El Paso, TX received Jimmy John's, snacks, and drinks, while awaiting train 1(14)/421(13).

Train	Delay	Comment
1(14)/421(13)	4'55"	
1(14)/421(13)	1'12"	FTI ALP-XVL

Train 4(15) East of Barstow, CA - Freight Train Interference

16JUL25: 4(15) was delayed between Ibis/MP592.2 and Needles, CA/MP578.0 on the BNSF Needles subdivision meeting disabled BN freight Q-DENSBD4-14A ahead. Train 4(15) was ordered to crossover to main track one at Ibis, following BN/8002W, and crossing back over to main track 3 to enter Needles Station, CA. Once the station work was completed, train 4(15) departed Needles, CA.

Train	Delay	Comment
4(15)	1'10"	

Train 50(15) Chicago, IL - Car Failure

16JUL25: Train 50(15) was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late release of the equipment by Mechanical. Car 62524, bound for Beech Grove, IN, was bad ordered for gouged wheels. In an effort to reduce delay, the Beech Grove, IN bound portion of the consist was cut off from the revenue section of train 50(15). Crew dorm car 69009 was found to have trainline communication failure and remained in consist dead. Six passenger reservations were downgraded to coach to accommodate the lost rooms. Once released by Mechanical, train 50(15) shoved to the station, boarded passengers, and departed.

Train	Delay	Comment
50(15)	1'24"	

Train 5(15) East of Omaha, NE - High Wind Warnings

16JUL25: Train 5(15) was delayed between Omaha/MP16.0 1 mile east of Omaha Station, NE/MP16.7 on the BNSF Omaha subdivision and Hall/MP60.0 2 miles west of Lincoln, NE/MP0.8 on the BNSF Ravenna subdivision due to high wind warnings requiring operating at reduced speeds. Once the through the affected area, train 5(15) continued at maximum authorized speed.

Train	Delay	Comment
5(15)	1'39"	

Train 3(14) West of Winslow, AZ - Signal

16JUL25: Train 3(14) was delayed at High Water Bridge/MP290.5 5 miles west of Winslow, AZ/MP285.5 on the BNSF Seligman subdivision following restrictive signals enforced while the High Water Bridge was inspected. Once the route was cleared for traffic, train 3(14) proceeded west.

Train	Delay	Comment
3(14)	40"	

Train 546(15) East of Martinez, CA - Drawbridge Opening

16JUL25: Train 546(15) was delayed at Vista/MP32.8 1 mile east of Martinez, CA/MP31.5 on the UP Martinez subdivision holding for maritime traffic at the Suisun Bay Bridge/MP33.2. Once the route was clear, train 546(15) continued east.

Train 548(15) was also delayed by the Suisun Bay Bridge opening. Train 14(15) was later delayed by the Suisun Bay Bridge opening.

Train	Delay	Comment
546(15)	37"	
548(15)	27"	
14(15)	47"	

Train 59(15) Chicago, IL - Engine Failure

16JUL25: Train 59(15) was delayed departing Chicago Union Station, IL/MP521.0 on the NS Chicago subdivision due to the late release of the equipment. Engine 77 and diner car 37014 were held out of inbound 58(14) and replaced by engine 837 and diner car 37005. After the equipment was made up complete, serviced, and brake tests were performed, Mechanical assistance was requested to resolve a parking brake issue. Once train 5(15) initialized PTC, shoved into Chicago Union Station, IL, and boarded passengers, train 59(15) departed.

Train	Delay	Comment
59(15)	1'32"	

Train 22(15)/422(13) Cleburne, TX - Freight Train Interference

15JUL25: Train 22(15)/422(13) was delayed between Kopperl/MP294.0 and Midway/MP320.0 beginning 24 miles south of Cleburne, TX/MP317.5 on the BNSF Fort Worth subdivision following freight BN/4251. Once the route was clear, train 22(15)/422(13) proceeded north.

Train	Delay	Comment
22(15)/422(13)	32"	

Train 547(15) - Engine Failure

15JUL25: Train 547(15) encountered a delay starting out in Sacramento, CA (SAC), MP 88.9 UPRR Martinez Subdivision, due to turning from late 534(15). After turning from 534, train 547 experienced air issues and could not take off yet. After attempts to reboot were unsuccessful, the crew pulled the MU cable and still no success. As time went on and departure time for 549(15) approached, it was determined that train 547 would take train 549's equipment : C2105, C8022, C8206, C8810, C8302. Train 549 would be canceled but deadhead with 547's equipment to Oak Yard: C2106, C8028, C8006, C8802, C6964. With 549 being the turn for train 548(15), Train 545(15) was told to come back out of OAK Yard and run as train 548: C2107, C8011, C8205, C8811, C8308.

Train	Delay	Comment
547(15)	1'5"	
549(15)	CANCELED	DEADHEAD WITH 547'S EQUIP TO OMF

Train 4(14) East of Lamy, NM - Passenger Train Interference

15JUL25: Train 4(14) was delayed at East Fox/MP820.0 15 miles east of Lamy, NM/MP835.2 on the BNSF Glorieta subdivision meeting Amtrak train 3(14). Once the route was clear, train 4(14) proceeded east.

Train	Delay	Comment
4(14)	33"	

Train 534(15) Emeryville, CA - Engine Failure

15JUL25: Train 534(15) was delayed in Oakland Yard, MP 5.8 UPRR Niles Subdivision, while waiting for mechanical to replace a shattered headlight on CDTX 2106. Once the headlight was fixed it was determined that train 534 would start out in EMY to avoid traffic building at OKJ. Train 534 departed EMY 59 minutes late.

Train 534 turns for train 547(15) in SAC and could see an Initial Departure Delay.

Train	Delay	Comment
534(15)	59"	ORIG EMY

Train 352(15) Late Departure Chicago, IL - Engine

15JUL25: Train 352(15) was delayed departing Chicago, IL, due to E/IDTX4617 with gas alarms just prior to scheduled departure. Mechanical determined a replacement engine was necessary. To minimize delay, crew and passengers transferred to equipment planned for Train 305(15), E/IDTX4606 & 5 cars, which was used to as late Train 352(15). 329PM-CT Train 352(15) departed Chicago, 1 hour and 14 minutes late.

Train 305(15) was delayed departing Chicago, IL. due to the replacement engine E/IDTX4625 needing to be wye'd before coupling to the equipment. Adding IDTX4625 was delayed by a power switch issue at Lumber St.

Train	Delay	Comment
352(15)	1'14"	
305(15)	2'40"	DCS at Lumber St
305(15)	1'00"	Adding IDTX4625

Train 5(14) West of Hastings, NE - Freight Train Interference

15JUL25: Train 5(14) was delayed at MP197, 41 miles west of Hastings, NE, on the BNSF Hastings Subdivision, meeting BNSF 7530.

Train	Delay	Comment
5(14)	41"	

Train 381(15) Late Departure Chicago, IL - Car Failure

15JUL25: Train 381(15) was delayed departing Chicago, IL, due to late shop of C/48164 at 442AM-CT for bad order service portion. Due to no available replacement food cars, axle count replacement car C/61020 was added. Service recovery food items were added onboard due to Trains 381(15) & 382(15) operating without a food service car. Train 381(15) departed Chicago at 811AM-CT, 31 minutes late.

Train	Delay	Comment
381(15)	31"	

Trains 710(15) & 717(15) Cancelled - Cab Car Failure

15JUL25: Trains 710(15) and 717(15) were cancelled as a result of headlight failure on cab car C/90218.

- Passengers ticketed for Train 710(15) were reaccommodated onto Train 712(15).
- Passengers ticketed for Train 717(15) were reaccommodated onto Train 719(15).

Work Element WBS # B.TR.100150.5889

WBS#: B.TR.100150.5889

Train	Delay	Comment
717(15)	Cancelled	Psgrs to 719(15)
710(15)	Cancelled	Psgrs to 712(15)

Train 6(15) Initial Terminal Emeryville, CA - Late Yard Release

15JUL25: Train 6(15) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of ongoing servicing and cleaning of equipment as well as HVAC repairs on 3 cars. Train 6(15) departed Emeryville at 9:10AM-PT.

UPDATE: As a result of Train 6(15) departing Emeryville prior to the posted estimated departure of 1'30" late, several passengers missed boarding the train and were reaccommodated onto Train 528(15) to Sacramento. Train 6(15) incurred further delay holding at Sacramento to board the passengers transferring off of 528(15).

Train	Delay	Comment
6(15)	32"	SAC - held for connecting psgrs off inbound 528(15)
6(15)	45"	EMY - ITD

UPRR Flash Flood Warnings - Sunset Limited Service

15JUL25: Union Pacific Railroad reported flash flood warnings beginning 17 miles west of Del Rio, TX, on the UPRR Sanderson and Del Rio subdivisions, between MP395.0 and MP307. Sunset Limited trains 1(14)/421(13) and 2/422(13) were delayed operating through the affected areas.

At 3:16AM CT Union Pacific Railroad reported water over the track at Obi/MP316.2. Train 2/422(13) was held at MP324.1 and Train 1(14)/421(13) at MP302.9. UPRR track inspector on site determined it was necessary to wait for water levels to recede before traffic could resume through the area. Once track inspector okayed traffic to resume at reduced speed, UP 6805 flagged through the location, followed by Train 2/422(13) and then Train 1(14)/421(13).

Train 22(15)/422(13) was delayed departing San Antonio, TX, holding for late connecting Train 422(13) which arrived at 945AM-CT, 4 hours and 45 minutes late.

WBS#: B.TR.100150.5890

Train	Delay	Comment
2/422(13)	39"	Flash flood warnings
2/422(13)	3'43"	E/DRT, water over rail MP324.1
1(14)/421(13)	2'51"	E/DRT, water over rail MP316.25
1(14)/421(13)	47"	Flash flood warnings
22(15)/422(13)	3'55"	SAS

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak MRS Line, MassDOT, Conn River Mainline - M of W Work

26JUN25: Beginning Friday, July 11th at 11:00PM through Monday, July 14th at 6:00AM, the Amtrak MRS Main Line, MassDOT, and the Connecticut River Main Line have schedule trackwork. To accommodate, Amtrak's Hartford Line, Valley Flyer, Northeast Regional, and Vermonter Service will be adjusted as follows:

Amtrak Hartford Line

- Trains 405/463/467(12Jul), which normally operates between SPG and NHV, will be replaced in entirety by bus.
- Trains 405/409/465/497(13Jul), which normally operates between SPG and NHV, will be replaced in entirety by bus.
- Trains 450/460/464 (12Jul, 13Jul), which normally operates between NHV and SPG, will be replaced in entirety by bus.
- Train 416(13Jul), which normally operates between NHV and SPG, will be replaced in entirety by bus.

Valley Flyer

- Train 461(12Jul, 13Jul), which normally operates between GFD and NHV, will originate at NHT and terminate at SPG.
- Train 499(12Jul, 13Jul), which normally operates between GFD and SPG, will originate at NHT.
- Train 488(12Jul, 13Jul), which normally operates between NHV and GFD, will originate at SPG and terminate at NHT.
- Train 400(12Jul, 13Jul), which normally operates between SPG and GFD, will terminate at NHT.

Northeast Regional

- Train 136(11Jul), which normally operates between WAS and SPG, will terminate at NHV.
- Train 148(11Jul), which normally operates between WAS and SPG, will terminate at NHV.
- Train 140(12Jul, 13Jul), which normally operates between WAS and SPG, will terminate at NHV.
- Train 146(12Jul, 13Jul), which normally operates between WAS and SPG, will terminate at NHV.
- Train 143(12Jul, 13Jul), which normally operates between SPG and WAS, will originate at NHV.
- Train 147(12Jul), which normally operates between SPG and RNK, will originate at NHV.
- Train 157(13Jul), which normally operates between SPG and NFK, will originate at NHV.
- Train 141(14Jul), which normally operates between SPG and NFK, will originate at NHV.
- Train 125(14Jul), which normally operates between SPG and NPN, will originate at NHV.

Vermonter

- Train 57(12Jul, 13Jul), which normally operates between SAB and WAS, will originate at NHV.
- Train 54(12Jul, 13Jul), which normally operates between WAS and SAB, will terminate at NHV.

ALTERNATE TRANSPORTATION

Hartford Flyer

- Buses 3405, 3463, 3467, 3409, 3465, and 3497 will provide alternate transportation

between SPG and NHV

-Buses 3150, 3460, 3464, and 3416 will provide alternate transportation between NHV and SPG

Valley Flyer

-Bus 3461 will provide alternate transportation between SPG and NHV

-Bus 3188 will provide alternate transportation between NHV and SPG

-There will be no alternate transportation between NHT and GFD.

Northeast Regional

-Buses 3143, 3147, 3157, 3141, and 3125 will provide alternate transportation between SPG and NHV

-Buses 3136, 3148, 3140, and 3146 will provide alternate transportation between NHV and SPG

Vermont

-Bus 3057 will provide alternate transportation between SAB and NHV for all stops except RPH, WNM, CLA, HLK, and MDN.

-Bus 3054 will provide alternate transportation between NHV and SAB for all stops except MDN, HLK, CLA, WNM, and RPH.

WBS#: B.TR.100150.5807

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

-Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.

-Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.

-Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.

-Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.

-Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Philadelphia to Washington Main Line - South of Philadelphia, PA - M of W Work

15JUL25: At 931A-ET, CETC reported that Amtrak Foreman and placed TSR on track 2 limits of Holly interlocking MP 20.3 of 10MPH Passenger, 10MPH Freight due to Frog Tread. Trains were receiving additions to the TSRB. As of 957A-ET, Track Supervisor was estimated to be 90 minutes out. As of 1131A-ET, Foreman removed track 2 from service between Landlith MP 25.4 to Hook MP 16.8 to make repairs to the 12A SW at Holly MP 16.8. Single tracking Holly MP 16.8 to MP Landlith MP 25.4 on track 3. As of 259P-ET, Foreman placed a M/W Hold on track 2 at Landlith to Hook and track 1 and 1F at Holly due to the conditions of the 12SW. Repairs may be done tonight.

Train	Delay	Comment
148 (15)	19"	
176 (15)	04"	
20 (14)	16"	
2122 (15)	14"	
84 (15)	17"	
114 (15)	07"	
134 (15)	15"	
133 (15)	07"	
2108 (15)	06"	
2166 (15)	05"	
2168 (15)	05"	
56 (15)	12"	
86 (15)	06"	
182 (15)	05"	
2162 (15)	07"	
SE2518	08"	
SE220	23"	

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

BNSF Fallbridge Subdivision Track Work- Empire Builder 13th - 14th July

13JUL25: BNSF has scheduled trackwork for a bridge replacement on the Fallbridge Subdivision for 36 hours starting Sunday, July 13th at 7:00AM through Monday, July 14th at 7:00PM. To accommodate this infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(11Jul, 12Jul), which normally operates between Chicago (CHI) and Portland (PDX) , will terminate at Spokane (SPK).
- Train 28 (13Jul, 14Jul), which normally operates between Portland (PDX) and Chicago (CHI) , will originate at Spokane (SPK).

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between Spokane (SPK) and Portland (PDX) making all stops except Wishram (WIH).
- Bus 4028 will provide alternate transportation between Portland (PDX) and Spokane (SPK) making all stops except Wishram (WIH).

EQUIPMENT

- Equipment for Train 27(11Jul, 12Jul) will stay coupled to Train 7 at Spokane (SPK)
- Equipment for Train 28(13Jul, 14Jul) will be coupled to Train 8 departing Seattle (SEA)

WBS#: B.TR.100150.5751

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/15/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	296	42	85.8%	4,316	549	87.3%	83,023	8,218	90.1%
Central Division	91.5%	65	7	89.2%	992	112	88.7%	19,021	1,852	90.3%
Northeast Division	95.0%	95	16	83.2%	1,359	199	85.4%	27,314	2,962	89.2%
Southeast Division	94.5%	67	10	85.1%	946	127	86.6%	18,375	1,841	90.0%
Southwest Division	90.5%	69	9	87.0%	1,019	111	89.1%	18,313	1,563	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/15/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	296	42	85.8%	4,316	549	87.3%	83,023	8,218	90.1%
Central Division	91.5%	65	7	89.2%	992	112	88.7%	19,021	1,852	90.3%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	35	2	94.3%	578	16	97.2%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	27	6	77.8%	401	63	84.3%	7,677	948	87.7%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	30	0	100.0%	554	19	96.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	14	0	100.0%	287	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	29	1	96.6%	558	38	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	1	83.3%	87	3	96.6%	1,650	91	94.5%
MSP	95.0%	1	0	100.0%	15	2	86.7%	276	14	94.9%
PDX	78.0%	5	0	100.0%	71	7	90.1%	1,383	159	88.5%
PNT	94.0%	3	0	100.0%	44	0	100.0%	791	56	92.9%
PTH	96.0%	1	0	100.0%	15	0	100.0%	286	11	96.2%
QCY	94.0%	2	0	100.0%	28	0	100.0%	558	18	96.8%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	0	100.0%	121	24	80.2%	2,248	324	85.6%
SPK	92.0%	1	0	100.0%	13	1	92.3%	284	14	95.1%
STL	96.0%	2	0	100.0%	55	5	90.9%	1,132	58	94.9%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	30	0	100.0%	551	12	97.8%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	95	16	83.2%	1,359	199	85.4%	27,314	2,962	89.2%
ALB	96.0%	6	1	83.3%	90	3	96.7%	1,939	125	93.6%
BON	94.5%	5	0	100.0%	74	8	89.2%	1,338	91	93.2%
BOS	97.0%	18	2	88.9%	265	28	89.4%	5,382	494	90.8%
BRK	97.0%	2	0	100.0%	49	2	95.9%	1,310	68	94.8%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	15	2	86.7%	286	19	93.4%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	27	2	92.6%	554	54	90.3%
HFD	-	2	0	100.0%	20	4	80.0%	166	17	89.8%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/15/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	296	42	85.8%	4,316	549	87.3%	83,023	8,218	90.1%
Northeast Division	95.0%	95	16	83.2%	1,359	199	85.4%	27,314	2,962	89.2%
MTR	97.0%	1	0	100.0%	15	2	86.7%	286	28	90.2%
NFL	97.0%	2	0	100.0%	30	1	96.7%	576	24	95.8%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	1	80.0%	70	12	82.9%	1,477	146	90.1%
NYP	94.5%	41	10	75.6%	576	115	80.0%	11,569	1,753	84.8%
POR	-	3	0	100.0%	24	8	66.7%	24	8	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	1	0.0%	13	3	76.9%	284	8	97.2%
SPG	95.5%	5	1	80.0%	71	7	90.1%	1,767	83	95.3%
TWO	96.0%	1	0	100.0%	15	0	100.0%	285	11	96.1%
WEM	-	-	-	-	1	1	0.0%	42	18	57.1%
Southeast Division	94.5%	67	10	85.1%	946	127	86.6%	18,375	1,841	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	72	9	87.5%	1,426	94	93.4%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	0	100.0%	165	11	93.3%	3,110	99	96.8%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	15	3	80.0%	282	91	67.7%
MIA	90.0%	2	1	50.0%	29	3	89.7%	554	50	91.0%
NFK	94.5%	3	2	33.3%	42	10	76.2%	792	64	91.9%
NOL	92.0%	2	0	100.0%	31	3	90.3%	638	46	92.8%
NPN	96.0%	2	1	50.0%	30	3	90.0%	549	20	96.4%
PGH	92.0%	1	0	100.0%	15	2	86.7%	287	16	94.4%
PHL	97.0%	5	1	80.0%	63	15	76.2%	1,229	172	86.0%
RGH	97.0%	4	0	100.0%	52	2	96.2%	1,155	36	96.9%
RNK	94.0%	1	0	100.0%	27	1	96.3%	544	63	88.4%
RVM	90.0%	1	0	100.0%	15	1	93.3%	279	34	87.8%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	13	0	100.0%	269	10	96.3%
SFA	83.0%	1	0	100.0%	15	1	93.3%	282	79	72.0%
WAS	94.5%	25	5	80.0%	352	53	84.9%	6,826	934	86.3%
Southwest Division	90.5%	69	9	87.0%	1,019	111	89.1%	18,313	1,563	91.5%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	15	0	100.0%	288	7	97.6%
BFD	90.0%	5	0	100.0%	88	11	87.5%	1,711	147	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	15	13	13.3%	295	89	69.8%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	14	2	85.7%	320	42	86.9%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/15/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/15/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	296	42	85.8%	4,316	549	87.3%	83,023	8,218	90.1%
Southwest Division	90.5%	69	9	87.0%	1,019	111	89.1%	18,313	1,563	91.5%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	45	2	95.6%	841	62	92.6%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	1	88.9%	141	15	89.4%	2,200	306	86.1%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	12	0	100.0%	283	6	97.9%
OKJ	91.0%	12	3	75.0%	164	23	86.0%	3,017	273	91.0%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	2	85.7%	195	22	88.7%	3,426	147	95.7%
SAN	90.0%	12	0	100.0%	178	11	93.8%	2,600	229	91.2%
SAS	85.0%	1	1	0.0%	15	5	66.7%	284	40	85.9%
SJC	95.0%	7	1	85.7%	104	6	94.2%	1,844	72	96.1%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	30	0	100.0%	563	27	95.2%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	2	0	100.0%	49	11	77.6%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	257	6	1	83.3%	121	22	81.8%	7	3	57.1%	117	22	81.2%
3		15	5	66.7%	282	55	80.5%	15	11	26.7%	278	152	45.3%
4	98	15	3	80.0%	283	68	76.0%	15	11	26.7%	282	142	49.6%
5	209	15	9	40.0%	285	48	83.2%	14	11	21.4%	282	94	66.7%
6	131	15	13	13.3%	285	82	71.2%	15	12	20.0%	284	94	66.9%
7		15	3	80.0%	279	39	86.0%	15	5	66.7%	274	72	73.7%
8	63	15	11	26.7%	280	103	63.2%	15	11	26.7%	278	132	52.5%
11		15	2	86.7%	287	46	84.0%	15	2	86.7%	280	63	77.5%
14	110	15	5	66.7%	288	87	69.8%	15	6	60.0%	286	126	55.9%
19	123	15	0	100.0%	288	33	88.5%	15	7	53.3%	287	56	80.5%
20		15	1	93.3%	288	14	95.1%	15	4	73.3%	287	46	84.0%
21		15	1	93.3%	287	35	87.8%	15	6	60.0%	281	89	68.3%
22	38	15	5	66.7%	284	42	85.2%	15	13	13.3%	283	121	57.2%
27		13	5	61.5%	275	22	92.0%	12	5	58.3%	265	91	65.7%
40		15	2	86.7%	245	35	85.7%	14	10	28.6%	240	149	37.9%
41	122	14	10	28.6%	243	105	56.8%	14	13	7.1%	239	190	20.5%
42		15	2	86.7%	288	17	94.1%	15	4	73.3%	288	78	72.9%
43		15	2	86.7%	288	25	91.3%	15	4	73.3%	288	64	77.8%
48		15	3	80.0%	287	51	82.2%	15	4	73.3%	287	45	84.3%
49	183	15	6	60.0%	288	56	80.6%	15	4	73.3%	288	51	82.3%
52		15	1	93.3%	282	79	72.0%	15	4	73.3%	282	151	46.5%
53		15	3	80.0%	282	91	67.7%	15	4	73.3%	282	144	48.9%
55	No OS	10	2	80.0%	199	8	96.0%	10	4	60.0%	199	43	78.4%
56	70	10	2	80.0%	199	35	82.4%	10	7	30.0%	198	50	74.7%
58		15	2	86.7%	280	23	91.8%	15	2	86.7%	277	55	80.1%
59		15	4	73.3%	279	56	79.9%	14	4	71.4%	275	31	88.7%
63	86	15	9	40.0%	288	55	80.9%	15	14	6.7%	288	146	49.3%
64		15	0	100.0%	288	11	96.2%	15	2	86.7%	288	70	75.7%
66		15	2	86.7%	286	55	80.8%	15	1	93.3%	284	37	87.0%
67		10	0	100.0%	198	17	91.4%	10	2	80.0%	196	41	79.1%
68	91	15	2	86.7%	288	28	90.3%	15	12	20.0%	288	116	59.7%
69	47	15	2	86.7%	288	22	92.4%	14	6	57.1%	283	33	88.3%
71	17	14	2	85.7%	287	7	97.6%	14	8	42.9%	285	66	76.8%
72	12	15	3	80.0%	288	22	92.4%	15	6	60.0%	286	73	74.5%
73	20	15	3	80.0%	288	15	94.8%	15	8	46.7%	286	143	50.0%
74		15	1	93.3%	284	21	92.6%	15	8	46.7%	282	98	65.2%
75	28	15	3	80.0%	286	8	97.2%	15	10	33.3%	284	117	58.8%
76	32	15	4	73.3%	284	20	93.0%	14	10	28.6%	282	123	56.4%
77	19	15	2	86.7%	285	12	95.8%	15	8	46.7%	283	128	54.8%
78	25	15	0	100.0%	286	10	96.5%	14	5	64.3%	285	69	75.8%
79	122	15	4	73.3%	288	39	86.5%	13	5	61.5%	285	103	63.9%
80	137	15	3	80.0%	288	24	91.7%	15	9	40.0%	288	82	71.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
84	38	10	0	100.0%	198	8	96.0%	10	6	40.0%	197	75	61.9%
85		10	0	100.0%	196	16	91.8%	10	7	30.0%	195	133	31.8%
86	25	10	1	90.0%	196	23	88.3%	10	9	10.0%	196	134	31.6%
89		15	1	93.3%	287	35	87.8%	15	5	66.7%	285	103	63.9%
90		15	0	100.0%	287	11	96.2%	14	7	50.0%	282	71	74.8%
93		10	0	100.0%	199	14	93.0%	10	6	40.0%	198	92	53.5%
94		10	4	60.0%	199	18	91.0%	10	6	40.0%	198	72	63.6%
95	42	10	0	100.0%	199	5	97.5%	10	5	50.0%	199	86	56.8%
97		15	12	20.0%	284	133	53.2%	15	9	40.0%	283	93	67.1%
98	60	15	1	93.3%	284	16	94.4%	15	10	33.3%	284	146	48.6%
110	56	10	3	70.0%	197	36	81.7%	10	1	90.0%	195	40	79.5%
111	95	10	2	80.0%	196	49	75.0%	10	2	80.0%	194	32	83.5%
112		10	2	80.0%	191	37	80.6%	10	2	80.0%	189	23	87.8%
114	39	10	2	80.0%	195	53	72.8%	10	3	70.0%	191	30	84.3%
119		10	0	100.0%	193	38	80.3%	10	1	90.0%	190	28	85.3%
125		10	1	90.0%	199	10	95.0%	10	7	30.0%	199	114	42.7%
129		10	3	70.0%	197	41	79.2%	10	4	60.0%	196	42	78.6%
130		10	1	90.0%	193	20	89.6%	10	0	100.0%	190	21	88.9%
131		10	2	80.0%	190	34	82.1%	10	2	80.0%	188	28	85.1%
133		10	5	50.0%	197	73	62.9%	10	9	10.0%	197	102	48.2%
134	45	10	0	100.0%	198	15	92.4%	10	7	30.0%	198	98	50.5%
136	22	10	0	100.0%	199	39	80.4%	10	3	70.0%	197	41	79.2%
137		10	3	70.0%	199	24	87.9%	10	4	60.0%	199	79	60.3%
138		10	2	80.0%	198	23	88.4%	10	6	40.0%	198	49	75.3%
141		10	0	100.0%	199	3	98.5%	10	6	40.0%	199	96	51.8%
148		10	1	90.0%	199	18	91.0%	10	4	60.0%	199	43	78.4%
151		15	3	80.0%	285	35	87.7%	15	3	80.0%	284	96	66.2%
170	52	10	0	100.0%	198	12	93.9%	10	5	50.0%	198	50	74.7%
171	43	10	1	90.0%	199	8	96.0%	10	7	30.0%	199	101	49.2%
172		10	2	80.0%	198	15	92.4%	10	3	70.0%	196	62	68.4%
173		10	0	100.0%	199	26	86.9%	10	2	80.0%	199	65	67.3%
174		10	2	80.0%	199	6	97.0%	10	5	50.0%	198	47	76.3%
175		10	4	60.0%	198	34	82.8%	10	5	50.0%	197	71	64.0%
176		10	3	70.0%	199	19	90.5%	10	1	90.0%	198	25	87.4%
177		10	2	80.0%	199	28	85.9%	10	4	60.0%	198	41	79.3%
178		10	1	90.0%	199	30	84.9%	10	6	40.0%	198	42	78.8%
179	144	10	2	80.0%	197	14	92.9%	10	7	30.0%	197	68	65.5%
181		10	4	60.0%	194	38	80.4%	10	1	90.0%	190	27	85.8%
182		10	2	80.0%	194	48	75.3%	10	6	40.0%	193	51	73.6%
183		10	2	80.0%	199	26	86.9%	10	1	90.0%	199	25	87.4%
184		10	5	50.0%	199	29	85.4%	10	2	80.0%	198	25	87.4%
185		10	1	90.0%	199	33	83.4%	10	1	90.0%	199	25	87.4%

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
186		10	1	90.0%	196	12	93.9%	10	6	40.0%	194	56	71.1%
190		10	4	60.0%	199	39	80.4%	10	4	60.0%	199	49	75.4%
192		10	2	80.0%	95	16	83.2%	10	3	70.0%	93	12	87.1%
193	21	10	4	60.0%	197	34	82.7%	10	6	40.0%	196	72	63.3%
196		10	0	100.0%	199	69	65.3%	10	2	80.0%	196	58	70.4%
197	33	10	6	40.0%	198	50	74.7%	10	3	70.0%	197	55	72.1%
232		15	0	100.0%	276	9	96.7%	15	0	100.0%	276	21	92.4%
233		13	4	69.2%	284	84	70.4%	13	7	46.2%	283	98	65.4%
234		15	0	100.0%	276	6	97.8%	15	1	93.3%	276	21	92.4%
236		15	0	100.0%	276	5	98.2%	15	1	93.3%	275	45	83.6%
237		13	0	100.0%	272	28	89.7%	13	2	84.6%	270	32	88.1%
239	52	15	3	80.0%	275	28	89.8%	15	4	73.3%	275	20	92.7%
240	17	15	0	100.0%	280	24	91.4%	15	5	66.7%	279	27	90.3%
241		15	3	80.0%	288	36	87.5%	14	4	71.4%	287	40	86.1%
243		10	3	70.0%	199	35	82.4%	10	4	60.0%	198	26	86.9%
244	18	13	1	92.3%	284	8	97.2%	13	8	38.5%	284	47	83.5%
280		15	0	100.0%	287	11	96.2%	15	1	93.3%	287	52	81.9%
281		15	2	86.7%	288	60	79.2%	14	3	78.6%	286	58	79.7%
283		15	6	60.0%	288	63	78.1%	15	6	60.0%	287	59	79.4%
284		15	1	93.3%	288	13	95.5%	15	0	100.0%	287	58	79.8%
290		15	2	86.7%	288	21	92.7%	14	10	28.6%	286	63	78.0%
291	35	15	6	60.0%	288	44	84.7%	15	10	33.3%	287	56	80.5%
300		13	1	92.3%	277	8	97.1%	13	3	76.9%	275	66	76.0%
305	237	15	2	86.7%	282	21	92.6%	15	12	20.0%	281	108	61.6%
311	34	14	2	85.7%	278	17	93.9%	14	13	7.1%	274	109	60.2%
316	40	14	1	92.9%	276	19	93.1%	14	13	7.1%	274	102	62.8%
318	89	15	0	100.0%	284	19	93.3%	15	10	33.3%	280	157	43.9%
319	37	15	1	93.3%	286	19	93.4%	15	14	6.7%	281	175	37.7%
329		10	1	90.0%	200	17	91.5%	10	0	100.0%	200	16	92.0%
330		12	1	91.7%	232	5	97.8%	12	1	91.7%	231	15	93.5%
331		15	1	93.3%	279	20	92.8%	15	2	86.7%	275	27	90.2%
332		15	0	100.0%	284	16	94.4%	15	2	86.7%	283	43	84.8%
334		15	0	100.0%	284	9	96.8%	15	3	80.0%	279	71	74.6%
335		15	2	86.7%	287	31	89.2%	15	4	73.3%	278	60	78.4%
336	16	15	0	100.0%	273	6	97.8%	15	4	73.3%	272	79	71.0%
337	17	15	1	93.3%	276	16	94.2%	15	4	73.3%	275	61	77.8%
338	15	15	2	86.7%	286	37	87.1%	15	7	53.3%	276	122	55.8%
339		15	0	100.0%	286	42	85.3%	15	2	86.7%	284	50	82.4%
341		14	7	50.0%	271	52	80.8%	14	7	50.0%	265	54	79.6%
342		15	0	100.0%	287	18	93.7%	15	1	93.3%	286	44	84.6%
350		15	1	93.3%	247	26	89.5%	15	10	33.3%	244	123	49.6%
351		15	0	100.0%	276	24	91.3%	15	4	73.3%	275	77	72.0%

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
352	102	15	3	80.0%	281	27	90.4%	15	8	46.7%	276	79	71.4%
353		15	0	100.0%	240	6	97.5%	15	1	93.3%	235	36	84.7%
354		14	0	100.0%	280	26	90.7%	14	4	71.4%	277	102	63.2%
355		14	0	100.0%	280	30	89.3%	14	3	78.6%	276	71	74.3%
364		15	1	93.3%	286	55	80.8%	15	3	80.0%	285	77	73.0%
365	20	15	0	100.0%	286	11	96.2%	15	5	66.7%	285	83	70.9%
370		14	1	92.9%	287	11	96.2%	13	1	92.3%	286	34	88.1%
371		14	0	100.0%	287	4	98.6%	14	2	85.7%	287	27	90.6%
380		15	1	93.3%	285	11	96.1%	15	1	93.3%	285	27	90.5%
381	29	15	2	86.7%	285	8	97.2%	15	5	66.7%	284	28	90.1%
382		15	1	93.3%	284	11	96.1%	15	4	73.3%	284	37	87.0%
383	27	15	0	100.0%	286	29	89.9%	15	7	53.3%	285	66	76.8%
390		15	2	86.7%	283	12	95.8%	15	7	53.3%	281	43	84.7%
391		15	0	100.0%	286	6	97.9%	15	3	80.0%	284	52	81.7%
392		15	0	100.0%	286	8	97.2%	15	4	73.3%	283	30	89.4%
393		15	1	93.3%	285	13	95.4%	15	7	53.3%	282	40	85.8%
417		10	2	80.0%	195	32	83.6%	9	1	88.9%	192	29	84.9%
425		10	0	100.0%	183	5	97.3%	10	0	100.0%	183	7	96.2%
470		11	2	81.8%	201	15	92.5%	9	2	77.8%	196	28	85.7%
471		10	2	80.0%	199	14	93.0%	9	0	100.0%	197	11	94.4%
473		10	2	80.0%	199	7	96.5%	9	1	88.9%	198	3	98.5%
474		10	2	80.0%	197	30	84.8%	9	4	55.6%	193	58	69.9%
475	97	10	2	80.0%	198	8	96.0%	10	1	90.0%	195	17	91.3%
478		10	1	90.0%	199	21	89.4%	9	1	88.9%	197	20	89.8%
479		10	1	90.0%	199	30	84.9%	10	1	90.0%	198	23	88.4%
486		10	0	100.0%	201	16	92.0%	10	4	60.0%	199	68	65.8%
494		10	4	60.0%	204	31	84.8%	10	5	50.0%	198	55	72.2%
495		10	0	100.0%	196	2	99.0%	10	1	90.0%	196	5	97.4%
500		15	1	93.3%	277	22	92.1%	14	3	78.6%	275	81	70.5%
502		15	0	100.0%	275	13	95.3%	14	1	92.9%	273	79	71.1%
503	18	15	1	93.3%	288	30	89.6%	15	5	66.7%	277	86	69.0%
504		15	0	100.0%	276	9	96.7%	14	3	78.6%	275	110	60.0%
505		15	2	86.7%	280	33	88.2%	14	5	64.3%	277	102	63.2%
506		15	3	80.0%	280	27	90.4%	14	3	78.6%	278	69	75.2%
507	39	15	3	80.0%	279	33	88.2%	15	6	60.0%	278	86	69.1%
508		15	0	100.0%	283	13	95.4%	15	4	73.3%	281	82	70.8%
509	27	15	3	80.0%	278	31	88.8%	14	4	71.4%	277	98	64.6%
511		15	1	93.3%	279	23	91.8%	15	3	80.0%	276	75	72.8%
516		15	0	100.0%	279	24	91.4%	15	7	53.3%	277	125	54.9%
517		15	0	100.0%	280	5	98.2%	15	6	60.0%	279	169	39.4%
518	18	15	3	80.0%	280	32	88.6%	15	6	60.0%	278	167	39.9%
519		15	0	100.0%	277	11	96.0%	15	3	80.0%	276	58	79.0%

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
520		10	2	80.0%	31	4	87.1%	10	0	100.0%	31	1	96.8%
521		10	0	100.0%	199	4	98.0%	10	0	100.0%	198	15	92.4%
522		10	1	90.0%	199	4	98.0%	9	0	100.0%	198	11	94.4%
523		10	0	100.0%	200	4	98.0%	10	0	100.0%	200	25	87.5%
524	16	10	1	90.0%	200	6	97.0%	9	2	77.8%	199	35	82.4%
525		10	0	100.0%	198	4	98.0%	10	0	100.0%	197	10	94.9%
526		10	0	100.0%	31	4	87.1%	10	2	80.0%	31	6	80.6%
527		10	0	100.0%	200	3	98.5%	10	0	100.0%	199	29	85.4%
528		10	0	100.0%	199	5	97.5%	10	1	90.0%	199	31	84.4%
529		10	0	100.0%	200	0	100.0%	10	2	80.0%	200	38	81.0%
531		10	1	90.0%	199	3	98.5%	10	2	80.0%	198	15	92.4%
532		10	0	100.0%	200	9	95.5%	10	0	100.0%	198	20	89.9%
534	50	10	1	90.0%	200	14	93.0%	10	1	90.0%	199	15	92.5%
535		10	2	80.0%	31	3	90.3%	9	0	100.0%	30	2	93.3%
536		10	0	100.0%	200	8	96.0%	10	1	90.0%	198	9	95.5%
537		9	0	100.0%	30	1	96.7%	9	0	100.0%	30	2	93.3%
538		10	1	90.0%	200	5	97.5%	10	2	80.0%	200	36	82.0%
540		10	0	100.0%	200	5	97.5%	10	2	80.0%	195	20	89.7%
541		10	0	100.0%	200	8	96.0%	10	3	70.0%	200	43	78.5%
542		10	1	90.0%	200	8	96.0%	10	3	70.0%	200	35	82.5%
543		10	0	100.0%	200	6	97.0%	10	7	30.0%	200	31	84.5%
544		9	1	88.9%	198	11	94.4%	9	0	100.0%	197	15	92.4%
545		10	1	90.0%	200	8	96.0%	10	1	90.0%	198	21	89.4%
546	25	10	0	100.0%	200	7	96.5%	10	3	70.0%	199	31	84.4%
547	62	10	2	80.0%	200	9	95.5%	10	3	70.0%	200	29	85.5%
548		10	0	100.0%	198	12	93.9%	10	0	100.0%	196	11	94.4%
549	Cncld	10	4	60.0%	200	23	88.5%	9	0	100.0%	194	29	85.1%
551		10	0	100.0%	200	10	95.0%	10	0	100.0%	195	17	91.3%
562		15	0	100.0%	284	31	89.1%	15	1	93.3%	275	31	88.7%
564		15	3	80.0%	282	20	92.9%	15	2	86.7%	279	26	90.7%
566		15	0	100.0%	107	10	90.7%	15	0	100.0%	107	11	89.7%
572		15	2	86.7%	237	21	91.1%	15	5	66.7%	233	43	81.5%
573		15	0	100.0%	276	37	86.6%	15	0	100.0%	270	43	84.1%
577		15	0	100.0%	30	0	100.0%	15	2	86.7%	30	2	93.3%
580		15	0	100.0%	284	21	92.6%	15	1	93.3%	283	53	81.3%
581		15	2	86.7%	284	35	87.7%	15	3	80.0%	280	54	80.7%
582		15	0	100.0%	30	0	100.0%	15	2	86.7%	30	3	90.0%
586		15	1	93.3%	235	30	87.2%	15	2	86.7%	228	40	82.5%
587		15	2	86.7%	235	27	88.5%	14	2	85.7%	228	48	78.9%
591		15	0	100.0%	284	32	88.7%	15	2	86.7%	280	40	85.7%
593		15	3	80.0%	30	5	83.3%	15	4	73.3%	30	7	76.7%
595		15	2	86.7%	276	60	78.3%	15	1	93.3%	274	49	82.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
600		10	1	90.0%	198	3	98.5%	10	1	90.0%	196	25	87.2%
601		10	2	80.0%	198	19	90.4%	10	2	80.0%	197	33	83.2%
605		10	0	100.0%	198	10	94.9%	10	0	100.0%	196	26	86.7%
607		10	1	90.0%	199	18	91.0%	10	0	100.0%	198	10	94.9%
609		10	1	90.0%	199	13	93.5%	9	1	88.9%	198	30	84.8%
620		10	1	90.0%	199	6	97.0%	10	2	80.0%	197	26	86.8%
622		8	1	87.5%	157	7	95.5%	8	1	87.5%	156	46	70.5%
639		10	1	90.0%	199	26	86.9%	10	2	80.0%	198	24	87.9%
640		10	0	100.0%	199	0	100.0%	10	1	90.0%	199	99	50.3%
641		10	0	100.0%	199	18	91.0%	10	0	100.0%	199	34	82.9%
642		10	1	90.0%	199	1	99.5%	10	0	100.0%	198	41	79.3%
643		10	0	100.0%	199	13	93.5%	10	0	100.0%	198	41	79.3%
644		10	1	90.0%	199	9	95.5%	9	1	88.9%	196	45	77.0%
645		10	1	90.0%	199	15	92.5%	9	2	77.8%	198	51	74.2%
646		10	1	90.0%	199	18	91.0%	10	3	70.0%	196	99	49.5%
647		10	1	90.0%	199	15	92.5%	9	4	55.6%	198	79	60.1%
648		10	0	100.0%	199	12	94.0%	10	4	60.0%	197	34	82.7%
649		10	0	100.0%	199	20	89.9%	10	4	60.0%	198	39	80.3%
650		10	0	100.0%	199	10	95.0%	10	1	90.0%	198	30	84.8%
651		10	2	80.0%	199	25	87.4%	10	3	70.0%	199	80	59.8%
652		10	1	90.0%	199	4	98.0%	10	4	60.0%	199	36	81.9%
653		10	0	100.0%	199	13	93.5%	10	4	60.0%	198	66	66.7%
654		10	1	90.0%	199	5	97.5%	10	0	100.0%	197	20	89.8%
655		10	1	90.0%	198	30	84.8%	10	3	70.0%	196	69	64.8%
656		10	2	80.0%	199	5	97.5%	10	2	80.0%	198	45	77.3%
657		10	1	90.0%	199	14	93.0%	10	1	90.0%	199	50	74.9%
658		10	0	100.0%	199	6	97.0%	10	3	70.0%	198	53	73.2%
680		11	0	100.0%	201	2	99.0%	11	1	90.9%	200	32	84.0%
681		11	0	100.0%	200	12	94.0%	11	6	45.5%	197	79	59.9%
682		11	0	100.0%	201	5	97.5%	11	1	90.9%	201	95	52.7%
683	20	10	0	100.0%	153	4	97.4%	10	6	40.0%	153	62	59.5%
684	14	10	3	70.0%	153	12	92.2%	10	6	40.0%	152	82	46.1%
685	28	10	0	100.0%	157	12	92.4%	10	7	30.0%	157	58	63.1%
686	30	11	5	54.5%	200	41	79.5%	11	7	36.4%	200	84	58.0%
687	23	11	1	90.9%	201	29	85.6%	11	6	45.5%	201	78	61.2%
688		11	0	100.0%	201	7	96.5%	11	2	81.8%	201	89	55.7%
689		3	1	66.7%	148	7	95.3%	3	1	66.7%	149	30	79.9%
702	34	15	2	86.7%	288	19	93.4%	15	9	40.0%	287	94	67.2%
703		15	2	86.7%	288	29	89.9%	15	7	53.3%	288	72	75.0%
710	Cncld	15	3	80.0%	288	45	84.4%	14	8	42.9%	281	78	72.2%
711		15	0	100.0%	287	10	96.5%	15	5	66.7%	278	31	88.8%
712		15	1	93.3%	288	44	84.7%	14	8	42.9%	285	86	69.8%

Amtrak On Time Performance													
Trains Arriving Through: 7/15/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
713	42	14	0	100.0%	286	9	96.9%	12	8	33.3%	269	58	78.4%
714	42	15	3	80.0%	287	38	86.8%	15	8	46.7%	282	70	75.2%
715		15	3	80.0%	287	42	85.4%	14	10	28.6%	276	87	68.5%
716		15	4	73.3%	287	32	88.9%	14	3	78.6%	286	59	79.4%
718		15	5	66.7%	288	42	85.4%	14	3	78.6%	286	52	81.8%
719		15	3	80.0%	288	26	91.0%	15	6	60.0%	280	63	77.5%
761		15	0	100.0%	284	17	94.0%	15	1	93.3%	284	34	88.0%
765		15	0	100.0%	284	12	95.8%	15	1	93.3%	275	40	85.5%
769		15	0	100.0%	282	11	96.1%	15	1	93.3%	278	51	81.7%
770		15	0	100.0%	284	17	94.0%	15	5	66.7%	281	39	86.1%
774		15	0	100.0%	284	8	97.2%	15	3	80.0%	280	65	76.8%
779		15	0	100.0%	30	1	96.7%	15	3	80.0%	30	7	76.7%
784	16	15	1	93.3%	284	33	88.4%	15	8	46.7%	281	113	59.8%
785		15	2	86.7%	284	15	94.7%	15	1	93.3%	282	44	84.4%
790		15	1	93.3%	284	15	94.7%	15	1	93.3%	281	42	85.1%
794		15	0	100.0%	284	22	92.3%	15	1	93.3%	283	58	79.5%
821	12	12	0	100.0%	283	6	97.9%	12	10	16.7%	283	144	49.1%
822	81	14	2	85.7%	285	13	95.4%	14	14	0.0%	285	145	49.1%
1333	49	15	1	93.3%	281	51	81.9%	15	13	13.3%	280	179	36.1%
1340	19	15	2	86.7%	280	14	95.0%	15	11	26.7%	278	94	66.2%
2103		10	0	100.0%	196	11	94.4%	10	1	90.0%	193	23	88.1%
2107		10	3	70.0%	195	36	81.5%	10	1	90.0%	191	27	85.9%
2108	Cncld	10	0	100.0%	192	19	90.1%	9	2	77.8%	189	29	84.7%
2121	Cncld	10	1	90.0%	193	32	83.4%	9	3	66.7%	188	44	76.6%
2122		10	3	70.0%	194	37	80.9%	10	4	60.0%	188	35	81.4%
2124		8	1	87.5%	155	27	82.6%	8	2	75.0%	152	34	77.6%
2150		10	0	100.0%	199	7	96.5%	10	2	80.0%	199	62	68.8%
2151		10	0	100.0%	199	0	100.0%	10	4	60.0%	199	49	75.4%
2152	30	10	1	90.0%	197	6	97.0%	10	7	30.0%	191	81	57.6%
2153		9	0	100.0%	194	5	97.4%	9	6	33.3%	192	45	76.6%
2154	30	10	1	90.0%	197	15	92.4%	9	5	44.4%	193	84	56.5%
2159	11	10	2	80.0%	196	16	91.8%	10	4	60.0%	191	62	67.5%
2162		10	1	90.0%	198	16	91.9%	9	3	66.7%	192	67	65.1%
2163		10	0	100.0%	198	15	92.4%	10	6	40.0%	192	78	59.4%
2166	43	10	2	80.0%	198	11	94.4%	10	5	50.0%	196	44	77.6%
2167		10	1	90.0%	199	28	85.9%	10	5	50.0%	197	51	74.1%
2168		10	3	70.0%	199	17	91.5%	10	4	60.0%	198	46	76.8%
2169		10	4	60.0%	196	49	75.0%	9	4	55.6%	189	66	65.1%
2170		9	2	77.8%	189	14	92.6%	8	2	75.0%	185	44	76.2%
2173		9	0	100.0%	193	19	90.2%	9	3	66.7%	193	46	76.2%
2190		10	0	100.0%	198	14	92.9%	10	0	100.0%	195	16	91.8%
2193		9	0	100.0%	194	25	87.1%	9	3	66.7%	187	66	64.7%

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2108	NYP	Trn Cancelled	ENG	40	ENG	12	PHL-PHL	AM	Undesired emergency application, E/2006
2121	XHM	Trn Cancelled							
2152	BOS	30	DCS	26	DCS	18	XGX-PVD	AM	Power switch failure, Milepost w/Letters, xgx, pvd, delayed a/c 21sw at Packard is out of correspondence after 2163 passed
2154	BOS	30	CTI	29	CTI	15	PVD-RTE	AM	Follow, KEOLIS, 844, Other, LAWN - HEBRONVILLE
2159	WAS	11	DCS	12	DCS	12	PVD-XGX	AM	T.O.L, Other, LBERTY - HIGH ST, RULE 241 AT LIBERTY AND OPERATED RES UNTIL MP 153.9 TRK 1
2166	BOS	43	ENG	30	ENG	11	XHM-XCY	AM	Cab signal failure, 2010 2015, AT CP CLARK CUT OUT ACSES ON LEAD POWER CAR #2010
84	NYP	38	WTR	41	WTR	41	NFK-X3V	NS	Flash flood warning Other, ns
86	BOS	25	PTI	19	PTI	8	RVM-RVR	CS	Follow Stop Signal, 98, Control Point, AY
95	NFK	42	CTI	44	WTR	28	X3V-NFK	NS	Flash flood warning Milepost w/Letters, N 66.2, N 42.7
110	NYP	56	PTI	30	ITI	25	PHL-PHL	AM	Service, turn, or wye train, 179, Late turn
111	WAS	95	SVS	69	SVS	69	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD A/C OBS CLEANING OF EQUIPMENT
114	NYP	39	ITI	31	ITI	31	WAS-WAS	AM	Service, turn, or wye train, 111, swapped P&P sets to decrease amount of delay on #182
134	NYP	45	DMW	26	DMW	12	WIL-WIL	AM	Held for or routed around MW work or equipment, Control Point, ., Single tracking, held for Amtrak 131 a/c outage Wilmington - Holly int
136	SPG	22	WTR	19	WTR	13	TRE-MET	AM	Storm, Other, XH1-MET, OPRD 1TRK NJ3877 AND NJ3879 ON 2TRK A/C MICROLOCK FAILED ON 43SW AT DELCO
170	BOS	52	CTI	35	DCS	14	KIN-PVD	AM	Power switch failure, Milepost w/Letters, KIN, PVD, 21sw at Packard is out of correspondence after 2163 passed
171	RNK	43	WTR	42	WTR	22	LYH-RNK	NS	Flash flood warning Milepost, 172.0, 270.0
179	PHL	144	CON	98	CON	98	NHV-NHV	MN	Hold for bus with passengers from train
193	WAS	21	ITI	13	ITI	13	NYP-NYP	AM	Service, turn, or wye train, 84, LATE FROM SSYD A/C LATE TURN OFF AM84

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
197	WAS	33	CTI	18	CAR	12	PHL-PHL	AM	Heat / AC, ., OPR 90MPH
475	NHV	97	ENG	65	ENG	65	SPG-SPG	AM	Pick up rescue locomotive due to mechanical failure, n/a, AM 475 rescued AM55 as double draft
79	CLT	122	WTR	72	WTR	39	PTB-RMT	CS	Flash flood warning Milepost w/Letters, a 56.0, a 79.0
80	NYP	137	FTI	40	SYS	22	RGH-SSM	NS	PTC- PTC enforced braking train went into penalty
19	NOL	123	DBS	190	DBS	190	MSS-CLP	NS	Debris blocking track (no debris strike) Downed Power lines blocking the tracks ahead, Control Point, Nokesville
683	POR	20	PTI	16	PTI	13	SAO-ORB	CS	Cross over or go around 686, Control Point, surf
684	BON	14	PTI	6	PTI	6	DHM-EXR	CS	Cross over or go around 683 Eng AMTK 106, Control Point, Rockingham JCT
685	POR	28	WTR	18	TRS	8	SAO-ORB	CS	Near-miss Trespasser dancing in the gauge; engineer applied emergency brakes and stopped train 2 train car lengths before individual. Witness and train crew called police and train dispatcher respectively to report the trespasser close call., Control Point, Surf
686	BON		PTI	14	PTI	9	HHL-WOB	MT	Meet 685, Control Point, wwj
687	BRK	23	DSR	8	DSR	8	POR-FRE	CS	Per dispatcher (radio/phone) Milepost, 0.1, 3.9, 25, 2, Milepost, 16.7, 15.5, 25, s
63	TWO	86	SVS	32	SVS	32	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
68	NYP	91	ENG	69	ENG	51	ALB-HUD	AM	Loading problem Had to wait for Mechanical to come fix, 708
69	MTR	-25	POL	48	POL	48	FTC-FTC	DH	Fire department hold
239	ALB	52	CTI	11	ENG	8	CRT-CRT	MN	Tried to start rear unit 90
240	NYP	17	DSR	6	CTI	5	POU-CRT	MN	Meet metro north, Control Point, 46
244	NYP	18	CTI	23	CTI	19	POU-CRT	MN	Follow MNRR, Control Point, 58
291	BTN	35	DSR	18	CAR	16	ALB-SDY	AM	Had to water cafe car 48177
49	CHI	183	TRS	192	TRS	192	ROC-BUF	CS	Trespasser strike Milepost, 386, 386
71	CLT	17	WTR	12	WTR	8	CYN-DNC	NS	Flash flood warning Milepost, 72.6, 60.5
72	RGH	12	FTI	9	FTI	9	GRO-BNC	NS	Meet #ns94z, Siding, Superior

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
73	CLT	20	DSR	11	DSR	11	DNC-BNC	NS	Per bulletin Milepost w/Letters, 46.3nc, 46.2nc, 40, 1, Milepost w/Letters, 44.6nc, 44.4nc, 10, 1, Milepost w/Letters, 42.8nc, 42.6nc, 25, 1, Milepost w/Letters, 42.3nc, 42.1nc, 10, 1
75	CLT	28	DSR	14	PTI	11	CYN-DNC	NS	Meet #Amt72, Control Point, D&S Jct
76	RGH	32	WTR	23	WTR	16	GRO-DNC	NS	Flash flood warning Milepost, 9.1, 13.9, Milepost, 19.7, 32.4
77	CLT	19	DMW	8	DMW	8	DNC-BNC	NS	Hold for defect repair Stop signal at King. Assuming MOW due to fact a fresh 10 was put out just ahead of us via PTC, Control Point, King
78	RGH	25	WTR	25	WTR	11	HPT-GRO	NS	Flash flood warning Milepost, 298.0, 284.5
98	NYP	60	WTR	67	WTR	36	RMT-PTB	CS	Flash flood warning Per EC-1, Milepost w/Letters, A 12.9, A 63.0
55	WAS	No OS Rpt	ENG	162	ENG	132	SPG-SPG	AM	HEP, 94, HEP issues on E/94 and is now disabled. AM475 is tied onto AM55 to double draft
56	SAB	70	DSR	70	DSR	35	ESX-SAB	NE	Per bulletin Milepost, 114.39, 114.59, 25, Track, Milepost, 121, 126, 10, Track, Milepost, 128, 126, 25, Track
41	MIA	122	SVS	115	SVS	100	CHI-CHI	AM	Planned set out / pick out of locomotives, cars or section of train Lead unit was not equipped with cab signals. Had to switch Lead unit and trailing unit.
5	EMY	209	TRS	163	TRS	163	XXP-WIP	UP	Trespasser strike Milepost, 38.58, 40.1
6	CHI	131	SVS	96	SVS	87	EMY-EMY	UP	Water, commissary, toilet/trash dumping Other, oakland yard
524	SAC	16	PTI	12	FTI	8	MTZ-SUI	UP	Meet UP 9923, Control Point, Cordelia, manifest
534	SAC	50	ENG	59	ENG	59	EMY-EMY	UP	Other electrical failure SHATTERED HEADLIGHT IN YARD. WAIT FOR MECHANICAL TO REPLACE., C2106
546	SAC	25	MBO	37	MBO	37	MTZ-SUI	UP	For maritime traffic Control Point, Vista
547	SJC	62	ENG	69	ENG	65	SAC-SAC	UP	Air / Brake C2106
549	OKJ	Trn Cancelled							
503	EUG	18	WTR	31	WTR	17	ALY-EUG	UP	Heat order Milepost, 750.33, 618.55
507	EUG	39	WTR	32	WTR	13	ORC-SLM	UP	Heat order Level 2, Milepost, 750.33, 618.55

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
509	PDX	27	PTI	21	PTI	21	CTL-KEL	BN	Meet 506 / 14, Control Point, chehalis jct
518	VAC	18	FTI	13	FTI	13	BEL-X8B	BN	Cross Traffic BNSF, Control Point, swift, coal
14	SEA	110	DSR	73	CAR	55	OKJ-EMY	UP	Sewer smell 38061, Into yard to address
8	CHI	63	FTI	75	CAR	64	SEA-SEA	BN	Toilet 32086
821	FTW	12	DSR	24	DSR	12	GLE-FTW	BN	Per bulletin Milepost, 389.7, 389.5, 40, m, Milepost, 374.8, 374.4, 50, m, Milepost, 372.8, 372.4, 25, m, Milepost, 365.4, 365.3, 60, 1m, Milepost, 364.8, 364.6, 30, 1m, Milepost, 358.5, 358.4, 30, 1m, Milepost, 355.7, 355.5, 65, 1m, Milepost, 354.5, 354.0, 40, 1m, Milepost, 347.0, 346.7, 25, 1m
822	OKC	81	DSR	69	DSR	26	GLE-ADM	BN	Per bulletin Milepost, 413.6, 450, 40, m
336	CHI	16	DMW	8	DMW	8	SVT-XRO	ME	Waiting for MW clearance Control Point, XRO
337	MKE	17	DCS	12	DCS	10	SVT-MKA	CP	Issue with automatic road crossing protection Milepost, 70.71, 70.71
338	CHI	15	CTI	12	CTI	6	GLN-XWA	ME	Follow Metra, Control Point, A3
352	PNT	102	ENG	76	ENG	74	CHI-CHI	AM	Set out defective locomotive ID4606
365	CHI	20	MBO	19	MBO	19	XH6-XTF	NS	For maritime traffic Bridge, 509
784	SAN	16	PTI	30	PTI	19	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
702	BFD	34	FTI	46	FTI	15	MDR-FNO	BN	Follow bnsf 3913, Control Point, madera
710	BFD	Trn Cancelled							
713	OKJ	42	PTI	22	FTI	15	HNF-FNO	BN	Follow BNSF 4023, Control Point, sunmaid
714	BFD	42	FTI	27	PTI	17	ACA-SKN	BN	Meet AMTK 713, Control Point, Holt
4	CHI	98	DSR	101	SYS	47	NDL-KNG	BN	Meet 3, hold out of Kingman due to AMTK 3 experiencing engine loading issues, Control Point, Griffith
2	NOL	257	WTR	253	WTR	223	XPF-XHT	UP	Flood / washout Siding, obi
22	CHI	38	FTI	120	FTI	34	TPL-MCG	BN	Switcher blocking route Other, TPL yard, BNSF 1914
305	STL	237	DCS	160	DCS	160	CHI-CHI	AM	Power switch failure Other, Lumber
381	QCY	29	CAR	31	CAR	31	CHI-CHI	AM	Set out defective car 48164
383	QCY	27	FTI	36	FTI	20	MAC-QCY	BN	Meet bn 7013, Siding, golden
311	KCY	34	PTI	25	PTI	25	JEF-SED	UP	Meet Wait for an hour late 318 Next siding open, Amtk 318, Siding, Dow

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/15/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
316	STL	40	FTI	46	FTI	11	SED-JEF	UP	Meet AMT 319, Siding, Shell	
318	CHI	89	FTI	67	FTI	28	LEE-WAR	UP	Meet 2x freights, ??, Siding, centerview	
319	KCY	37	ENG	34	ENG	9	JOL-DWT	UP	X-ITCS not working reduced to 79mph 55	
1333	MSP	49	DSR	25	DSR	16	WIN-RDW	CP	Per bulletin Milepost, 349.2, 353.6, 25, main, Milepost, 353.6, 353.8, 10, main, Milepost, 353.8, 354.9, 25, main, Milepost, 362.7, 363, 40, main, Milepost, 364.9, 365.1, 40, main	
1340	CHI	19	DSR	29	DSR	16	RDW-WIN	CP	Per bulletin Milepost, 365.1, 364.9, 40, m, Milepost, 363.0, 362.7, 40, m, Milepost, 354.9, 353.8, 25, m, Milepost, 353.8, 353.6, 10, m, Milepost, 353.6, 349.2, 25, m, Milepost, 310.4, 310.2, 10, m, Milepost, 306.3, 305.9, 25, m	

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/15/2025

Terminal	Train	Date	Late	Delay	Cause
MIA	40	07/15	95	95	Trespasser strike Trirail had an incident at Pompano, Control Point, Pompano
NFK	94	07/15	4	4	Hold for thruway bus
NFK	138	07/15	5	5	Bridge not down at our scheduled departure time of 12:54. Milepost, 4.8, 1.3
NPN	186	07/15	8	8	Hold for thruway bus
PHL	110	07/15	25	25	Service, turn, or wye train, 179, Late turn
WAS	114	07/15	31	31	Service, turn, or wye train, 111, swapped P&P sets to decrease amount of delay on #182
WAS	172	07/15	7	7	HEP, 635, OPEN DOOR INDICATIONS ON THE MOTOR, ENGR REQUESTED AUTHORIZATION FOR BYPASS CNDR VERIFIED ALL DOORS CLOSED
WAS	182	07/15	9	9	Service, turn, or wye train, 111, swapped P&P sets to decrease amount of delay
WAS	184	07/15	10	10	Other late crew, mechanical were performing pre-departure test and the crew were interrupting those test which delayed boarding which began at 1:01p
WAS	2124	07/15	16	16	Service, turn, or wye train, 2163
ALB	69	07/15	4		
BOS	179	07/15	122	122	Planned set out / pick out of locomotives, cars or section of train, Dp Bos late a/c engine swap
BOS	2169	07/15	4	4	Service, turn, or wye train, 2152, Late turn of eq from AM2152
NHV	494	07/15	7	7	Planned set out / pick out of locomotives, cars or section of train, Late from yard a/c of switching engine w/ AM475 to use for disabled AM55
NYP	49	07/15	17	17	Electrical failure, 62033, LATE FROM SSYD A/C SHOPPED CAR #62033 FOR LOW AIR PRESSURE REPLACED WITH CAR #62037
NYP	63	07/15	32	32	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	79	07/15	28	28	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	97	07/15	13	13	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C LATE RELEASE BY MECHANICAL
NYP	111	07/15	69	69	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD A/C OBS CLEANING OF EQUIPMENT
NYP	129	07/15	6	6	Service, turn, or wye train, 114, LATE FROM SSYD A/C LATE TURN OFF AM114
NYP	151	07/15	19	19	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD BY OBS CLEANING OF THE EQUIPMENT
NYP	181	07/15	10	10	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD A/C OBS CLEANING OF EQUIPMENT
NYP	193	07/15	13	13	Service, turn, or wye train, 84, LATE FROM SSYD A/C LATE TURN OFF AM84

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/15/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	2121	07/15	(Trn Cxld)		Engine Failure
SAB	55	07/15	(Trn Cxld)		Engine Failure
SPG	475	07/15	65	65	Pick up rescue locomotive due to mechanical failure, n/a, AM 475 rescued AM55 as double draft
CHI	5	07/15	10	10	Late shove to the platform due to Amt365 blocking Amt365, Other, Station platform
CHI	50	07/15	84	84	Set out defective car 90250, All equipment going to beech grove cut off
CHI	59	07/15	92	92	Turn and service 837 from train #4 837
CHI	305	07/15	220	160	Power switch failure Other, Lumber
CHI	305	07/15	220	60	Failure of diesel engine 4606
CHI	352	07/15	74	74	Set out defective locomotive ID4606
CHI	381	07/15	31	31	Set out defective car 48164
MKE	338	07/15	4	4	Other electrical failure End door relay, ID4608
EMY	6	07/15	45	45	Service, turn, or wye train 5, Dirty train
LAX	564	07/15	5	5	PTC problem or failure (cause unknown) No information in PTC engineer manual entered would no except information. Cnoc PTC fixed problem.
OKJ	534	07/15	(Trn Cxld)		equipment issues
OKJ	710	07/15	(Trn Cxld)		Cab Car Failure
OKJ	718	07/15	12	12	Planned set out / pick out of locomotives, cars or section of train Add/Hold
SAC	547	07/15	65	65	Air / Brake C2106
SAC	549	07/15	(Trn Cxld)		equipment issues
SAS	22	07/15	235	235	Hold for connecting train Train 2 arrival at 9:45am Cut off transfer cars Mech inspection Respot train 22 on track 3 was blocked by Train 2 Baggage passenger loading, 2
SJC	544	07/15	5	5	Meet Caltrain, 416, Control Point, Alameda

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	91.1	95.2	341	3
CDOT	95.0	95.0	95.6	96.4	20	1
MARC	95.0	No Data	No Data	83.5	No Data	No Data
SEPTA	95.0	No Data	No Data	96.2	No Data	No Data
NJT-NED	95.0	96.7	91.8	95.2	368	12
NJT-SED	95.0	No Data	No Data	91.2	No Data	No Data

Operating Highlights

Train 79(15) - Salisbury, NC - Trespasser Incident

16JUL25: Train 79(15) was delayed on the Norfolk Southern Montview-Salisbury Subdivision at Salisbury Station/MP 333.7 due to a vehicle stuck on the tracks ahead. Once the vehicle was removed and tracks were inspected, Train 79(15) continued.

Train	Delay	Comment
79(15)	35"	

Train 79(15) - South of Petersburg Station, VA - Weather

15JUL25: Train 79(15) was delayed on the CSX North End Subdivision ay MP 41.7 due to flash flood warnings.

Train	Delay	Comment
79(15)	39"	

Train 179(15) - Boston, MA - Engine Failure

15JUL25: Train 179(15) was delayed departing Boston South Station due to a late equipment swap at Southampton Yard. Reports from Southampton Yard reflect the engine being swapped.

Train	Delay	Comment
179(15)	2'02"	

Train 68(15) - South of Albany, NY - Engine Failure

15JUL25: Train 68(15) was delayed shortly after departing Albany-Rensselaer Station at MP 140.2 on the Amtrak Hudson Line due to an air brake fault on E/708. Mechanical support was dispatched from Albany to assist. The cause of the failure was an MU cabling malfunction. The train proceeded to NYP powered by trail engine 130.

Train	Delay	Comment
68(15)	49"	

CSX Heat Orders - Northeast and Southeast Regions

15JUL25:Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Alleghany, Kanawha, and New River.

Train	Delay	Comment
687 (15)	06"	
685 (15)	13"	
686 (15)	10"	
683 (15)	02"	
98 (14)	07"	

Train 2108(15) Baltimore, MD - Engine Failure

15JUL25: Train 2108(15) with set 12 PC/2006,PC/2037 was delayed due to PC/2006 going to into undesired emergency. The crew was able to figure out it was a leaking toilet causing compressor issues. The train continued to proceed but was disabled in Newark with reports of smoke in the cab. Train 2108(15) was terminated in Newark, the passengers were transferred to trains 114(15) and 174(15) into New York. Rescue engine was sent from New York to take 2108(15) equipment back to Washington. Amtrak Road Foreman was on scene at 3P-ET. This caused Washington to short turn train 2163(15) for 2124(15) .

Train	Delay	Comment
2108 (15)	TERM NWK	
2121 (15)	CANCELLED	
2124 (15)	16"	Turn off 2163(15)

Train 20(15) North of New Orleans, LA - Side Swipe Vehicle/Debris

15JUL25: Train 20(15) with E/325,E/324 and 8 cars reported they side swiped the passenger side mirror off a pick up truck working on a generator on the right way under the company name High Performance on the NS New Orleans subdivision at MP 7.1. No injuries reported to passengers or crew or the vehicle driver. Crew inspected the equipment and took no exceptions they were able to proceed north.

National Response Center Number: 1436959

Train	Delay	Comment
20 (15)	21"	

Train 55(15) Originate Springfield, MA - Engine Failure

15JUL25: Train 55(15) with E/94 was experiencing head end power loss when attempting to accelerating at St Albans at departure time. Amtrak Road Foreman and Drummack responded but were unable to correct the problem. It was determined to deadhead 55(15) equipment to Springfield MA station and coupled with 475(15) equipment. No alternate transportation for passengers between St. Albans and Springfield.

Train	Delay	Comment
55 (15)	1'15"	DHE TO SPG
475 (15)	1'05"	SPG
55 (15)	2'12"	SPG

Train 98(15) Miami, FL - Initial Terminal Delay

15JUL25: Train 98(15) was delayed outside Miami Station due to a SFRTA RTA 301 trespasser strike at Pompano MP SX 1001.68. This was a confirmed fatality. Local police and EMS were on scene. This also had train 40(15) holding in Miami . As of 1220P-ET, SFRTA released one track thru the area and train 98(15) and 40(15) were able to depart Miami.

Train	Delay	Comment
98 (15)	4'20"	
40 (15)	1'35"	

Train 84(15) Petersburg, VA - Weather - Flood Warnings

15JUL25: Train 84(15) was delayed due to flash flood warnings on NS Norfolk subdivision.

Train	Delay	Comment
84 (15)	41"	

Train 63(15) New York, NY - Initial Terminal Delay

15JUL25: TRAIN 63(15) WAS DELAYED DEPARTING NEW YORK DUE TO ENGINE ISSUES.

Train	Delay	Comment
63 (15)	32"	

Train 111(15) New York, NY - Initial Terminal Delay

15JUL25: Train 111(15) was delayed departing New York due to late release from the yard. This also delayed train 114(15) departing Washington due to late turn of equipment off 111(15).

Train	Delay	Comment
111 (15)	1'09"	
114 (15)	31"	

Northeast Corridor - Acela Cancellations

15JUL25: due to Acela Trainset 18 having FIP Faults and Propulsions issues, Trains 2155(15) and 2172(15) were cancelled in their entireties with no alternate transportation.

Train	Delay	Comment
2155 (15)	Cancelled	
2172 (15)	Cancelled	

Maintenance of Way Highlights

Philadelphia to Washington Main Line - South of Philadelphia, PA - M of W Work

15JUL25: At 931A-ET, CETC reported that Amtrak Foreman and placed TSR on track 2 limits of Holly interlocking MP 20.3 of 10MPH Passenger, 10MPH Freight due to Frog Tread. Trains were receiving additions to the TSRB. As of 957A-ET, Track Supervisor was estimated to be 90 minutes out. As of 1131A-ET, Foreman removed track 2 from service between Landlith MP 25.4 to Hook MP 16.8 to make repairs to the 12A SW at Holly MP 16.8. Single tracking Holly MP 16.8 to MP Landlith MP 25.4 on track 3. As of 259P-ET, Foreman placed a M/W Hold on track 2 at Landlith to Hook and track 1 and 1F at Holly due to the conditions of the 12SW. Repairs may be done tonight.

Train	Delay	Comment
148(15)	19"	
176(15)	04"	
20(14)	16"	
2122(15)	14"	
84(15)	17"	
114(15)	07"	
134(15)	15"	
133(15)	07"	
2108(15)	06"	
2166(15)	05"	
2168(15)	05"	
56(15)	12"	
86(15)	06"	
182(15)	05"	
2162(15)	07"	
SE2518	08"	
SE220	23"	

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak MRS Line, MassDOT, Conn River Mainline - M of W Work

26JUN25: Beginning Friday, July 11th at 11:00PM through Monday, July 14th at 6:00AM, the Amtrak MRS Main Line, MassDOT, and the Connecticut River Main Line have schedule trackwork. To accommodate, Amtrak's Hartford Line, Valley Flyer, Northeast Regional, and Vermonter Service will be adjusted as follows:

Amtrak Hartford Line

- Trains 405/463/467(12Jul), which normally operates between SPG and NHV, will be replaced in entirety by bus.
- Trains 405/409/465/497(13Jul), which normally operates between SPG and NHV, will be replaced in entirety by bus.
- Trains 450/460/464 (12Jul, 13Jul), which normally operates between NHV and SPG, will be replaced in entirety by bus.
- Train 416(13Jul), which normally operates between NHV and SPG, will be replaced in entirety by bus.

Valley Flyer

- Train 461(12Jul, 13Jul), which normally operates between GFD and NHV, will originate at NHT and terminate at SPG.
- Train 499(12Jul, 13Jul), which normally operates between GFD and SPG, will originate at

NHT.

-Train 488(12Jul, 13Jul), which normally operates between NHV and GFD, will originate at SPG and terminate at NHT.

-Train 400(12Jul, 13Jul), which normally operates between SPG and GFD, will terminate at NHT.

Northeast Regional

-Train 136(11Jul), which normally operates between WAS and SPG, will terminate at NHV.

-Train 148(11Jul), which normally operates between WAS and SPG, will terminate at NHV.

-Train 140(12Jul, 13Jul), which normally operates between WAS and SPG, will terminate at NHV.

-Train 146(12Jul, 13Jul), which normally operates between WAS and SPG, will terminate at NHV.

-Train 143(12Jul, 13Jul), which normally operates between SPG and WAS, will originate at NHV.

-Train 147(12Jul), which normally operates between SPG and RNK, will originate at NHV.

-Train 157(13Jul), which normally operates between SPG and NFK, will originate at NHV.

-Train 141(14Jul), which normally operates between SPG and NFK, will originate at NHV.

-Train 125(14Jul), which normally operates between SPG and NPN, will originate at NHV.

Vermonter

-Train 57(12Jul, 13Jul), which normally operates between SAB and WAS, will originate at NHV.

-Train 54(12Jul, 13Jul), which normally operates between WAS and SAB, will terminate at NHV.

ALTERNATE TRANSPORTATION

Hartford Flyer

-Buses 3405, 3463, 3467, 3409, 3465, and 3497 will provide alternate transportation between SPG and NHV

-Buses 3150, 3460, 3464, and 3416 will provide alternate transportation between NHV and SPG

Valley Flyer

-Bus 3461 will provide alternate transportation between SPG and NHV

-Bus 3188 will provide alternate transportation between NHV and SPG

-There will be no alternate transportation between NHT and GFD.

Northeast Regional

-Buses 3143, 3147, 3157, 3141, and 3125 will provide alternate transportation between SPG and NHV

-Buses 3136, 3148, 3140, and 3146 will provide alternate transportation between NHV and SPG

Vermonter

-Bus 3057 will provide alternate transportation between SAB and NHV for all stops except RPH, WNM, CLA, HLK, and MDN.

-Bus 3054 will provide alternate transportation between NHV and SAB for all stops except MDN, HLK, CLA, WNM, and RPH.

WBS#: B.TR.100150.5807

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 19(14) Passenger Injury at Anniston, Alabama – Medical

15JUL25, Passenger on PNR 35A5A0, traveling from Salisbury, NC to Meridian, MS fell says she must have dozed off and fell. She had lacerations to her arm and nose. Paramedics dressed wounds. Amtrak Police notified.

Delay: 19 (14) 12"

Train 64(15) Passenger Removal at Utica, New York -Medical

15JUL25, Passenger on PNR 3389DA, traveling from Buffalo (Exchange), NY to New York, NY was removed by EMS at Utica, NY due to having either a possible heart attack or stroke. Amtrak Police notified.

Delay: 64 (15) 23"

Western Region

Operating Highlights

Train 4(15) East of Barstow, CA - Freight Train Interference

16JUL25: 4(15) was delayed between Ibis/MP592.2 and Needles, CA/MP578.0 on the BNSF Needles subdivision meeting disabled BN freight Q-DENSBD4-14A ahead. Train 4(15) was ordered to crossover to main track one at Ibis, following BN/8002W, and crossing back over to main track 3 to enter Needles Station, CA. Once the station work was completed, train 4(15) departed Needles, CA.

Train	Delay	Comment
4(15)	1'10"	

Train 50(15) Chicago, IL - Car Failure

16JUL25: Train 50(15) was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late release of the equipment by Mechanical. Car 62524, bound for Beech Grove, IN, was bad ordered for gouged wheels. In an effort to reduce delay, the Beech Grove, IN bound portion of the consist was cut off from the revenue section of train 50(15). Crew dorm car 69009 was found to have trainline communication failure and remained in consist dead. Six passenger reservations were downgraded to coach to accommodate the lost rooms. Once released by Mechanical, train 50(15) shoved to the station, boarded passengers, and departed.

Train	Delay	Comment
50(15)	1'24"	

Train 5(15) East of Omaha, NE - High Wind Warnings

16JUL25: Train 5(15) was delayed between Omaha/MP16.0 1 mile east of Omaha Station, NE/MP16.7 on the BNSF Omaha subdivision and Hall/MP60.0 2 miles west of Lincoln, NE/MP0.8 on the BNSF Ravenna subdivision due to high wind warnings requiring operating at reduced speeds. Once the through the affected area, train 5(15) continued at maximum authorized speed.

Train	Delay	Comment
5(15)	1'39"	

Train 3(14) West of Winslow, AZ - Signal

16JUL25: Train 3(14) was delayed at High Water Bridge/MP290.5 5 miles west of Winslow, AZ/MP285.5 on the BNSF Seligman subdivision following restrictive signals enforced while the High Water Bridge was inspected. Once the route was cleared for traffic, train 3(14) proceeded west.

Train	Delay	Comment
3(14)	40"	

Train 546(15) East of Martinez, CA - Drawbridge Opening

16JUL25: Train 546(15) was delayed at Vista/MP32.8 1 mile east of Martinez, CA/MP31.5 on the UP Martinez subdivision holding for maritime traffic at the Suisun Bay Bridge/MP33.2. Once the route was clear, train 546(15) continued east.

Train 548(15) was also delayed by the Suisun Bay Bridge opening. Train 14(15) was later delayed by the Suisun Bay Bridge opening.

Train	Delay	Comment
546(15)	37"	
548(15)	27"	
14(15)	47"	

Train 59(15) Chicago, IL - Engine Failure

16JUL25: Train 59(15) was delayed departing Chicago Union Station, IL/MP521.0 on the NS Chicago subdivision due to the late release of the equipment. Engine 77 and diner car 37014 were held out of inbound 58(14) and replaced by engine 837 and diner car 37005. After the equipment was made up complete, serviced, and brake tests were performed, Mechanical assistance was requested to resolve a parking brake issue. Once train 5(15) initialized PTC, shoved into Chicago Union Station, IL, and boarded passengers, train 59(15) departed.

Train	Delay	Comment
59(15)	1'32"	

Train 22(15)/422(13) Cleburne, TX - Freight Train Interference

15JUL25: Train 22(15)/422(13) was delayed between Kopperl/MP294.0 and Midway/MP320.0 beginning 24 miles south of Cleburne, TX/MP317.5 on the BNSF Fort Worth subdivision following freight BN/4251. Once the route was clear, train 22(15)/422(13) proceeded north.

Train	Delay	Comment
22(15)/422(13)	32"	

Train 547(15) - Engine Failure

15JUL25: Train 547(15) encountered a delay starting out in Sacramento, CA (SAC), MP 88.9 UPRR Martinez Subdivision, due to turning from late 534(15). After turning from 534, train 547 experienced air issues and could not take off yet. After attempts to reboot were unsuccessful, the crew pulled the MU cable and still no success. As time went on and departure time for 549(15) approached, it was determined that train 547 would take train 549's equipment : C2105, C8022, C8206, C8810, C8302. Train 549 would be canceled but deadhead with 547's equipment to Oak Yard: C2106, C8028, C8006, C8802, C6964. With 549 being the turn for train 548(15), Train 545(15) was told to come back out of OAK Yard and run as train 548: C2107, C8011, C8205, C8811, C8308.

Train	Delay	Comment
547(15)	1'5"	
549(15)	CANCELED	DEADHEAD WITH 547'S EQUIP TO OMF

Train 4(14) East of Lamy, NM - Passenger Train Interference

15JUL25: Train 4(14) was delayed at East Fox/MP820.0 15 miles east of Lamy, NM/MP835.2 on the BNSF Glorieta subdivision meeting Amtrak train 3(14). Once the route was clear, train 4(14) proceeded east.

Train	Delay	Comment
4(14)	33"	

Train 534(15) Emeryville, CA - Engine Failure

15JUL25: Train 534(15) was delayed in Oakland Yard, MP 5.8 UPRR Niles Subdivision, while waiting for mechanical to replace a shattered headlight on CDTX 2106. Once the headlight was fixed it was determined that train 534 would start out in EMY to avoid traffic building at OKJ. Train 534 departed EMY 59 minutes late.

Train 534 turns for train 547(15) in SAC and could see an Initial Departure Delay.

Train	Delay	Comment
534(15)	59"	ORIG EMY

Train 352(15) Late Departure Chicago, IL - Engine

15JUL25: Train 352(15) was delayed departing Chicago, IL, due to E/IDTX4617 with gas alarms just prior to scheduled departure. Mechanical determined a replacement engine was necessary. To minimize delay, crew and passengers transferred to equipment planned for Train 305(15), E/IDTX4606 & 5 cars, which was used to as late Train 352(15). 329PM-CT Train 352(15) departed Chicago, 1 hour and 14 minutes late.

Train 305(15) was delayed departing Chicago, IL. due to the replacement engine E/IDTX4625 needing to be wye'd before coupling to the equipment. Adding IDTX4625 was delayed by a power switch issue at Lumber St.

Train	Delay	Comment
352(15)	1'14"	
305(15)	2'40"	DCS at Lumber St
305(15)	1'00"	Adding IDTX4625

Train 5(14) West of Hastings, NE - Freight Train Interference

15JUL25: Train 5(14) was delayed at MP197, 41 miles west of Hastings, NE, on the BNSF Hastings Subdivision, meeting BNSF 7530.

Train	Delay	Comment
5(14)	41"	

Train 381(15) Late Departure Chicago, IL - Car Failure

15JUL25: Train 381(15) was delayed departing Chicago, IL, due to late shop of C/48164 at 442AM-CT for bad order service portion. Due to no available replacement food cars, axle count replacement car C/61020 was added. Service recovery food items were added onboard due to Trains 381(15) & 382(15) operating without a food service car. Train 381(15) departed Chicago at 811AM-CT, 31 minutes late.

Train	Delay	Comment
381(15)	31"	

Trains 710(15) & 717(15) Cancelled - Cab Car Failure

15JUL25: Trains 710(15) and 717(15) were cancelled as a result of headlight failure on cab car C/90218.

-Passengers ticketed for Train 710(15) were reaccommodated onto Train 712(15).

-Passengers ticketed for Train 717(15) were reaccommodated onto Train 719(15).

Work Element WBS # B.TR.100150.5889

WBS#: B.TR.100150.5889

Train	Delay	Comment
717(15)	Cancelled	Psgrs to 719(15)
710(15)	Cancelled	Psgrs to 712(15)

Train 6(15) Initial Terminal Emeryville, CA - Late Yard Release

15JUL25: Train 6(15) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of ongoing servicing and cleaning of equipment as well as HVAC repairs on 3 cars. Train 6(15) departed Emeryville at 9:10AM-PT.

UPDATE: As a result of Train 6(15) departing Emeryville prior to the posted estimated departure of 1'30" late, several passengers missed boarding the train and were reaccommodated onto Train 528(15) to Sacramento. Train 6(15) incurred further delay holding at Sacramento to board the passengers transferring off of 528(15).

Train	Delay	Comment
6(15)	32"	SAC - held for connecting psgrs off inbound 528(15)
6(15)	45"	EMY - ITD

UPRR Flash Flood Warnings - Sunset Limited Service

15JUL25: Union Pacific Railroad reported flash flood warnings beginning 17 miles west of Del Rio, TX, on the UPRR Sanderson and Del Rio subdivisions, between MP395.0 and MP307. Sunset Limited trains 1(14)/421(13) and 2/422(13) were delayed operating through the affected areas.

At 3:16AM CT Union Pacific Railroad reported water over the track at Obi/MP316.2. Train 2/422(13) was held at MP324.1 and Train 1(14)/421(13) at MP302.9. UPRR track inspector on site determined it was necessary to wait for water levels to recede before traffic could resume through the area. Once track inspector okayed traffic to resume at reduced speed, UP 6805 flagged through the location, followed by Train 2/422(13) and then Train 1(14)/421(13).

Train 22(15)/422(13) was delayed departing San Antonio, TX, holding for late connecting Train 422(13) which arrived at 945AM-CT, 4 hours and 45 minutes late.

WBS#: B.TR.100150.5890

Train	Delay	Comment
2/422(13)	39"	Flash flood warnings
2/422(13)	3'43"	E/DRT, water over rail MP324.1
1(14)/421(13)	2'51"	E/DRT, water over rail MP316.25
1(14)/421(13)	47"	Flash flood warnings
22(15)/422(13)	3'55"	SAS

Train 1(14)/421(13) East of Alpine, TX - Freight Train Interference

15JUL25: Train 1(14)/421(13) was delayed at Altuda/MP593, 14 miles east of Alpine, TX, on the UPRR Sanderson Subdivision, due to MEWWC-13 (UP 5950) ahead at MP603 with damaged cars from tie fire. UP 5950 cut away from rear section of train to clear tie fire leaving the rear cut on the bridge at that location. UPRR reported several damaged air hoses on cars requiring repair before recoupling to pull in the clear. UPRR mechanical, b&b and track responded to the scene. The bridge and track was inspected and okayed for service. Train 1(14)/421(13) was delayed holding for UP 5950 to repair air hoses to several cars, set out three damaged cars in Alpine siding and then couple to remainder of consist and pull in the clear. Train 1(14)/421(13) was further delayed following freight UP/5950 to Quebec Siding/MP660.9 in Valentine, TX.

Due to the late operation of train 1(14)/421(13) the following service recovery was put into effect:
Dinner for July 15th:
-Papa John's Pizza to be delivered in El Paso, TX for the coach passengers
-Normal traditional dining for the sleeper passengers
Breakfast for July 16th:
-Continental breakfast items - groceries to be delivered in El Paso, TX
-Passengers in El Paso, TX received Jimmy John's, snacks, and drinks, while awaiting train 1(14)/421(13).

Train	Delay	Comment
1(14)/421(13)	4'55"	
1(14)/421(13)	1'12"	FTI ALP-XVL

Re: Train 318(14) East of St. Louis, MO - Engine Failure

14JUL25: Train 318(14), engine IDTX4615, 7 cars, and 176 passengers, was delayed after departing St Louis, MO/MP1.5 on the TRRA Merchants subdivision due to X-ITCS failure on engine IDTX4615, limiting train 318(14) to 79MPH to Chicago, IL.

Train	Delay	Comment
318(14)	41"	

Train 302(14) North of Summit, IL - Engine

14JUL25: Train 302(14), E/IDTX4625 & 6 cars, with 237 passengers, was delayed at MP9.4, 2 miles north of Summit, IL, on the CN Joliet Subdivision, due to E/IDTX4625 shut-down. Crew contacted mechanical to troubleshoot and was able to restore HEP and resolve issues. Train 302(14) proceeded north and stopped again at MP8.7 due to E/IDTX4625 shut-down again. Crew worked with mechanical, reset multiple faults and performed hard restart to resolve issues again.
Train 305(14) was delayed departing Chicago Union Station, IL due to mechanical forces swapping engine IDTX4625 for engine 53 as well as swapping out the bad ordered married pair IDTX4104 and IDTX4212 with married pair IDTX4203 and IDTX4125. Once the equipment was made up completed, train 305(14) departed Chicago Union Station, IL.

Train	Delay	Comment
302(14)	15"	MP8.7
302(14)	30"	MP9.4
305(14)	37"	ITD CHI

Train 5(13) West of Denver, CO - Struck Semi

14JUL25: 1024AM-MT, Train 5(13), E/81-E/22 & 10 cars, with 279 passengers, struck a semi at MP38.53, 38 miles west of Denver, CO, in Nederland, CO, Boulder County, on the UPRR Moffat Tunnel Subdivision. There were no reported injuries to passengers or crew. Local authorities responded to the scene. The occupant of the semi was injured and required an air lift from the scene. Amtrak trainmaster and UPRR MW and B&B responded to the scene. Train 5(13) maintained HEP. There was some cosmetic damage and radio antenna damage to E/81. No other exceptions to equipment were reported. The conductor requested relief and the assistant conductor moved up as conductor for remainder of trip to Grand Junction. Train 5(13) held for completion of investigation by local authorities and once released was able to proceed west.

Train 6(13) was delayed at Yarmony Siding/MP124.6 51 miles west of Granby, CO/MP75.8 on the UP Moffat Tunnel subdivision splitting the crew, leaving an engineer and an assistant conductor to protect train 5(13) into Grand Junction, CO/MP449.5.

Train 5(13), E/81-E/22 & 10 cars, with 189 passengers, was further delayed east of Provo, TX/MP701.3 due to dynamic brake issues while operating on a grade.

WBS#: B.TR.100150.5884

National Response Center Number: 1436865

Train	Delay	Comment
6(13)	32"	W/GRA - split crew for 5(13)
5(13)	2'43"	
5(13)	36"	E/PRO

Train 712(14) Originated at Emeryville, CA - Late Yard Release/Locomotive Issues

14JUL25: Train 712(14) originated at Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of NPCU being set-out due to mechanical problems and replaced with locomotive E/C2108. The train then incurred further delay as a result of air issues on E/C2108.

Passengers for 712(14) boarding at Oakland were reaccommodated onto Train 528(14) to Emeryville to make the connection.

Train 712(14) departed Emeryville at 11:30AM-PT.

Train	Delay	Comment
712(14)	1'44"	Originated at EMY

Re: Train 3(12) Flagstaff, AZ - Engine Failure

14JUL25: Train 3(12), with engines 136 and 199, 9 cars, and 186 passengers, was delayed at Flagstaff, TX/MP344.3 on the BNSF Seligman subdivision inspecting engine 199 for loading issues. The crew worked with CNOC Mechanical Desk and Los Angeles Mechanical by phone but ultimately isolated the engine to prevent reoccurring faults. Train 3(12) was further delayed at Needles, CA/MP578.0 adding BNSF freight BNSF/5142. Once the freight was added, train 3(12) proceeded west.

Work Element WBS # B.TR.100150.5883

WBS#: B.TR.100150.5883

Train	Delay	Comment
3(12)	1'02"	GLP-FLG
3(12)	2'47"	NDL - adding freight

Re: Train 8(13) Seattle, WA - Car Failure

13JUL25: Train 8(13) was delayed departing the initial terminal of Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. There was a problem with the septic system on car C/32086 which required additional time for technicians to resolve. Once the septic system was repaired train 8(13) departed SEA at 5:59 PM-PT.

Train	Delay	Comment
8(13)	1'04"	

Re: Train 370(13) St. Joseph-Benton Harbor, MI - Engine Failure

13JUL25: Train 370(13), 3 cars, and 161 passengers, stopped at St Joseph, MI/MP87.7 0.1 mile east of St Joseph-Benton Harbor Station, MI/MP87.8 on the CSX Grand Rapids subdivision due to a hot journal alarm on the engine IDTX/4607. The crew inspected the right side of axle 4 and found the bearing was too hot on account of it melted a Tempilstik. Train 370(13) was terminated at St Joseph, MI. HEP remained active while buses were sourced to take the passengers to their destinations.

Train 371(14) was cancelled in its entirety with three buses sourced.

Service recovery consisted of water and snack packs for passengers as they awaited the arrival of the three buses.

14JUL25: Due to no available equipment in Chicago, Train 370(14) was cancelled, with alternate transportation between Chicago, IL and Grand Rapids, MI. Amtrak mechanical responded to MP86.5 and repaired a bad sensor on E/IDTX4607. An extra crew was on duty in Grand Rapids at 400PM-ET, vanned to MP86.5 and deadheaded equipment off Train 370(13) to Grand Rapids to be in position for Train 371(15).

WBS#: B.TR.100150.5881

Train	Delay	Comment
371(14)	Cancelled	with alt
370(13)	Terminated	SJM
370(14)	Cancelled	

Train 714(13) Merced, CA - Cab Car Failure

13JUL25: Train 714(13) was delayed at Merced, CA (MCD) on the Burlington Northern Santa Fe Railway Stockton Subdivision. There was a problem with the Positive Train Control (PTC) system on cab car CC/8303. The crew was able to resolve the issue rebooting the system. Once the PTC system was working as intended train 714(13) was able to depart MCD at 3:12 PM-PT.

Train	Delay	Comment
714(13)	30"	

Re: Train 5(12) West of Grand Junction, CO - Car Failure

13JUL25: Train 5(12), with engines 151 and 169, 10 cars, and 190 passengers, stopped at Castle Valley, UT/MP493.6 45 miles west of Grand Junction, UT/MP449.5 on the UP Green River subdivision due to reported smoke conditions on a passenger car in consist. The crew inspected but was unable to contact any mechanical forces due to poor cell service. Train 5(12) continued to Cisco, UT/MP504.0 to reinspect. Crew found smoldering debris underneath diner car 33027, on the B end fireman side. A fire extinguisher was used to put out the fire and a stick was used to clear the debris. Once the debris was removed, train 5(12) continued west.

Train	Delay	Comment
5(12)	1'08"	

BNSF Flash Flood Warnings North of Temple, TX - Texas Eagle Service

13JUL25: BNSF flash flood warnings were in effect on the Fort Worth Subdivision between Temple, TX/MP218 and Kopperl/MP294.9, 22 miles south of Cleburne, TX, until 530PM-CT. Texas Eagle service Trains 22(13)/422(11) and 21(12) were delayed operating reduced speeds through the affected areas.

Train	Delay	Comment
22(13)/422(11)	1'39"	

Re: Train 710(13) Emeryville, CA - Cab Car Failure

13JUL25: Train 710(13), CC/90278-6 cars-E/CDTX2010, was delayed at Emeryville, CA/MP4.4, on the UPRR Martinez Subdivision, due to headlights not working on CC/90278. Train 710(13) was delayed holding for mechanical forces from Oakland to arrive and assist.

Train	Delay	Comment
710(13)	1'13"	

Re: Train 733(12) Oakland, CA - Engine Failure

12JUL25: Train 733(12) was terminated enroute at Oakland, CA (OKJ) on the Union Pacific Railway Niles Subdivision. Locomotive CDTX/2101 was reported as having intermittent issues providing tractive effort. To allow sufficient time for repairs to the locomotive, train 733(12) terminated at OKJ with equipment returning to Oakland Maintenance Facility for repairs; passengers continuing to Oakland Coliseum were accommodated by taxi/uber.

Train	Delay	Comment
733(12)	Terminate OKJ	Pax to OAX provided taxi OKJ-OAC

Maintenance of Way Highlights

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

BNSF Fallbridge Subdivision Track Work- Empire Builder 13th - 14th July

13JUL25: BNSF has scheduled trackwork for a bridge replacement on the Fallbridge Subdivision for 36 hours starting Sunday, July 13th at 7:00AM through Monday, July 14th at 7:00PM. To accommodate this infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(11Jul, 12Jul), which normally operates between Chicago (CHI) and Portland (PDX) , will terminate at Spokane (SPK).
- Train 28 (13Jul, 14Jul), which normally operates between Portland (PDX) and Chicago (CHI) , will originate at Spokane (SPK).

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between Spokane (SPK) and Portland (PDX) making all stops except Wishram (WIH).
- Bus 4028 will provide alternate transportation between Portland (PDX) and Spokane (SPK) making all stops except Wishram (WIH).

EQUIPMENT

- Equipment for Train 27(11Jul, 12Jul) will stay coupled to Train 7 at Spokane (SPK)
- Equipment for Train 28(13Jul, 14Jul) will be coupled to Train 8 departing Seattle (SEA)

WBS#: B.TR.100150.5751

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage
7 (8)	WTN	348		HEP
6 (6)	DEN	155		Trucks cut out

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
22(14)	LRK	1	STL	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 14(14) Passenger Removal at Klamath Falls, Oregon – Improper Conduct

15JUL25, Passenger on PNR 3544CC, traveling from Martinez, CA to Portland, OR was removed due to becoming loud and argumentative. Amtrak Police notified.

Delay: **14 (14)** **None**

Train 14(14) Passenger Removal at Klamath Falls, Oregon – Improper Conduct

15JUL25, Passenger on PNR 300A78, traveling from Sacramento, CA to Seattle, WA was removed due to the behavior of the dog. Amtrak Police notified.

Delay: **14 (14)** **07"**

Train 14(14) Passenger Incident at Chemult, Oregon – Improper Conduct

15JUL25, Passenger on PNR D6FF1C, traveling from San Luis Obispo, CA to Eugene, OR was accused of touching another passenger. Amtrak Police notified.

Delay: **14 (14)** **12"**

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/15/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	294	23	92%	4,315	376	91%	83,084	6,401	92%
Northeast Corridor	98%	80	9	89%	1,133	151	87%	22,318	2,384	89%
Acela	98%	22	4	82%	314	52	83%	6,229	820	87%
Northeast Regional	98%	58	5	91%	819	99	88%	16,089	1,564	90%
State Supported	98%	188	10	95%	2,771	148	95%	52,194	2,661	95%
Long Distance	98%	26	4	85%	411	77	81%	8,434	1,350	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay
Mechanical Arrival Performance through 7/15/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	294	23	92%	4,315	376	91%	83,084	6,401	92%
Northeast Corridor	98%	80	9	89%	1,133	151	87%	22,318	2,384	89%
Acela	98%	22	4	82%	314	52	83%	6,229	820	87%
Northeast Regional	98%	58	5	91%	819	99	88%	16,089	1,564	90%
On Spine Northeast Regional	98%	30	3	90%	424	50	88%	8,158	828	90%
Richmond / Newport News / Norfolk	98%	12	1	92%	175	41	77%	3,355	505	85%
Roanoke	98%	4	-	100%	60	3	95%	1,146	153	87%
Springfield Shuttles	98%	12	1	92%	160	5	97%	3,430	78	98%
State Supported	98%	188	10	95%	2,771	148	95%	52,194	2,661	95%
Borealis	98%	2	-	100%	30	5	83%	561	64	89%
Capitol Corridor	98%	28	2	93%	388	13	97%	6,848	148	98%
Carolinian	98%	2	-	100%	30	4	87%	576	46	92%
Cascades	98%	14	-	100%	210	11	95%	3,911	279	93%
Downeaster	98%	10	-	100%	148	1	99%	2,736	45	98%
Empire	98%	20	3	85%	300	20	93%	6,186	320	95%
Adirondack	98%	2	1	50%	30	2	93%	576	43	93%
Berkshire Flyer	98%	-	-	100%	6	1	83%	12	3	75%
Ethan Allen Express	98%	2	1	50%	30	5	83%	576	39	93%
Maple Leaf	98%	2	-	100%	30	2	93%	576	56	90%
New York - Albany	98%	10	1	90%	144	4	97%	3,295	91	97%
New York - Niagara Falls	98%	4	-	100%	60	6	90%	1,151	88	92%
Heartland Flyer	98%	2	-	100%	26	1	96%	568	17	97%
Hiawatha	98%	12	-	100%	173	6	97%	3,286	121	96%
Illinois	98%	10	2	80%	203	14	93%	3,970	270	93%
Carl Sandburg / Illinois Zephyr	98%	4	1	75%	60	2	97%	1,140	45	96%
Illini / Saluki	98%	4	-	100%	60	5	92%	1,140	41	96%
Lincoln Service	98%	2	1	50%	83	7	92%	1,690	184	89%
Keystone	98%	27	-	100%	342	21	94%	6,656	409	94%
Lincoln / Missouri	98%	2	1	50%	30	8	73%	570	83	85%
Michigan	98%	10	1	90%	146	13	91%	2,750	267	90%
Blue Water	98%	2	-	100%	30	4	87%	572	86	85%
Pere Marquette	98%	2	-	100%	28	1	96%	574	26	95%
Wolverine	98%	6	1	83%	88	8	91%	1,604	155	90%
Missouri	98%	2	-	100%	28	1	96%	554	15	97%
Pacific Surfliner	98%	24	-	100%	360	6	98%	6,138	228	96%
Pennsylvanian	98%	2	-	100%	30	5	83%	576	65	89%
Piedmont	98%	8	-	100%	119	-	100%	2,288	32	99%
San Joaquins	98%	11	-	100%	178	14	92%	3,444	195	94%
Vermont	98%	2	1	50%	30	5	83%	576	57	90%
Long Distance	98%	26	4	85%	411	77	81%	8,434	1,350	84%
Auto Train	98%	2	-	100%	30	3	90%	564	96	83%
California Zephyr	98%	2	1	50%	30	11	63%	573	133	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	-	-	100%	12	6	50%	244	50	80%
City Of New Orleans	98%	2	-	100%	30	4	87%	562	50	91%
Coast Starlight	98%	2	1	50%	32	1	97%	579	86	85%
Crescent	98%	2	-	100%	30	4	87%	576	68	88%
Empire Builder	98%	3	1	67%	55	7	87%	1,106	140	87%
Floridian	98%	2	-	100%	29	8	72%	486	169	65%
Lake Shore Ltd	98%	2	-	100%	30	8	73%	974	109	89%
Palmetto	98%	2	-	100%	30	2	93%	574	36	94%
Silver Meteor	98%	2	-	100%	30	6	80%	572	114	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	30	7	77%	574	144	75%
Sunset Ltd	98%	1	-	100%	13	4	69%	243	43	82%
Texas Eagle	98%	2	-	100%	30	6	80%	646	87	87%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/15/25											
Day					Month to Date			Year to Date			
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	
Amtrak System	98%	297	10	97%	4,333	107	98%	83,112	1,979	98%	
Northeast Corridor	98%	80	2	98%	1,133	30	97%	22,270	628	97%	
Acela	98%	22	-	100%	314	8	97%	6,231	164	97%	
Northeast Regional	98%	58	2	97%	819	22	97%	16,039	464	97%	
State Supported	98%	189	5	97%	2,772	43	98%	52,179	863	98%	
Long Distance	98%	28	3	89%	428	34	92%	8,525	486	94%	
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%	
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%	

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/15/25											
Day			Month to Date					Year to Date			
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	297	10	97%		4,333	107	98%	83,112	1,979	98%
Central Division	98%	65	6	91%		994	45	95%	19,033	652	97%
Northeast Division	98%	96	2	98%		1,374	25	98%	27,390	639	98%
Southeast Division	98%	67	1	99%		946	25	97%	18,376	433	98%
Southwest Division	98%	69	1	99%		1,019	12	99%	18,313	255	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/15/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	297	10	97%	4,333	107	98%	83,112	1,979	98%
Central Division	98%	65	6	91%	994	45	95%	19,033	652	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	35	-	100%	578	2	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	27	5	81%	401	35	91%	7,677	422	95%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	30	-	100%	554	3	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	14	-	100%	287	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	29	-	100%	558	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	1	83%	87	2	98%	1,650	11	99%
MSP	98%	1	-	100%	15	1	93%	276	7	97%
PDX	98%	5	-	100%	71	1	99%	1,383	36	97%
PNT	98%	3	-	100%	44	-	100%	791	7	99%
PTH	98%	1	-	100%	15	-	100%	286	6	98%
QCY	98%	2	-	100%	28	-	100%	558	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	121	5	96%	2,248	118	95%
SPK	98%	1	-	100%	15	-	100%	296	2	99%
STL	98%	2	-	100%	55	1	98%	1,132	17	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	30	-	100%	551	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	96	2	98%	1,374	25	98%	27,390	639	98%
ALB	98%	7	-	100%	105	-	100%	2,014	25	99%
BON	98%	5	-	100%	74	-	100%	1,338	3	100%
BOS	98%	18	-	100%	265	5	98%	5,382	127	98%
BRK	98%	2	-	100%	49	-	100%	1,310	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	15	-	100%	286	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	27	-	100%	554	-	100%
HFD	98%	2	-	100%	20	-	100%	166	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	15	1	93%	286	6	98%
NFL	98%	2	-	100%	30	-	100%	576	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	70	-	100%	1,477	35	98%
NYP	98%	41	1	98%	576	18	97%	11,570	403	97%
POR	98%	3	-	100%	24	-	100%	24	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	13	-	100%	284	1	100%
SPG	98%	5	1	80%	71	1	99%	1,767	20	99%
TWO	98%	1	-	100%	15	-	100%	285	-	100%
WEM	98%	-	-	100%	1	-	100%	42	-	100%
Southeast Division	98%	67	1	99%	946	25	97%	18,376	433	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	72	1	99%	1,426	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/15/25										
Day				Month to Date				Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	297	10	97%	4,333	107	98%	83,112	1,979	98%
Southeast Division	98%	67	1	99%	946	25	97%	18,376	433	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	165	2	99%	3,110	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	15	-	100%	282	11	96%
MIA	98%	2	-	100%	29	1	97%	554	29	95%
NFK	98%	3	-	100%	42	1	98%	792	4	99%
NOL	98%	2	-	100%	31	1	97%	638	21	97%
NPN	98%	2	-	100%	30	1	97%	549	4	99%
PGH	98%	1	-	100%	15	-	100%	287	3	99%
PHL	98%	5	-	100%	63	3	95%	1,229	36	97%
RGH	98%	4	-	100%	52	-	100%	1,155	5	100%
RNK	98%	1	-	100%	27	-	100%	544	8	99%
RVM	98%	1	-	100%	15	-	100%	279	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	13	-	100%	269	-	100%
SFA	98%	1	-	100%	15	-	100%	282	18	94%
WAS	98%	25	1	96%	352	15	96%	6,827	262	96%
Southwest Division	98%	69	1	99%	1,019	12	99%	18,313	255	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	15	-	100%	288	-	100%
BFD	98%	5	-	100%	88	-	100%	1,711	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	15	2	87%	295	22	93%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	14	-	100%	320	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	45	-	100%	841	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	-	100%	141	1	99%	2,200	63	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	12	-	100%	283	-	100%
OKJ	98%	12	-	100%	164	5	97%	3,017	66	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	1	93%	195	2	99%	3,426	14	100%
SAN	98%	12	-	100%	178	1	99%	2,600	23	99%
SAS	98%	1	-	100%	15	1	93%	284	3	99%
SJC	98%	7	-	100%	104	-	100%	1,844	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	30	-	100%	563	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	2	-	100%	49	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DATE 7/15/2025 12:00..	Diesel Locomotive	High Speed Trainset		Amfleet I	Superliner II	Electric Locomotives		California Cars (Caltrans)	Viewliner I	Surfliner	Superliner I	Grand Total
	ENG	ENG	MTI	CAR	CAR	ENG	CAR	CAR	CAR	CAR	CAR	
HEP Problems	227											227
Auxiliary Faults	134											134
Electrical Problems	59	19				19			17			114
Hand/Parking Brak..	92											92
Loading Problems	80											80
Odor/Smell					55							55
Door Problems	4			12		7		18		13		54
Air/Brake Problems				31							10	41
ACSES Failure		30										30
Engineer Cab Furn..							17					17
Water Problems				16								16
I-ETMS Problem	13											13
Air Leak			12									12
Overspeed Penalty	12											12
Air Compressor Pr..		11										11
PCS Faults		9										9
Engine Dead/Shut ..	8											8
Engine Coolant Le..	7											7
Speedometer Defe..	4											4
Grand Total	640	69	12	59	55	26	17	18	17	13	10	936