



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, July 17, 2025

Rules:0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/16/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/16/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	34	88.7%	4,616	584	87.3%	83,323	8,253	90.1%
Central Division	91.5%	65	9	86.2%	1,057	121	88.6%	19,086	1,861	90.2%
Northeast Division	95.0%	95	11	88.4%	1,454	210	85.6%	27,409	2,973	89.2%
Southeast Division	94.5%	69	5	92.8%	1,015	133	86.9%	18,444	1,847	90.0%
Southwest Division	90.5%	71	9	87.3%	1,090	120	89.0%	18,384	1,572	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/16/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	89,437	32,501	64%	1,669,511	538,369	68%	27,054,904	7,256,350	73%
Northeast Corridor	80%	39,575	11,306	71%	718,078	216,969	70%	12,018,488	3,093,615	74%
Acela	82%	10,029	2,795	72%	146,744	43,343	70%	2,500,661	598,009	76%
Northeast Regional	78%	29,546	8,511	71%	571,334	173,626	70%	9,517,827	2,495,606	74%
Richmond / Newport News / Norfolk	73%	10,455	2,282	78%	183,134	76,438	58%	3,073,286	1,048,975	66%
Springfield Shuttles	89%	369	72	80%	6,756	1,386	79%	172,753	26,030	85%
Roanoke	70%	2,434	99	96%	48,773	14,001	71%	802,950	211,226	74%
On Spine Northeast Regional	83%	16,288	6,058	63%	332,671	81,801	75%	5,468,838	1,209,375	78%
State Supported	80%	37,468	12,690	66%	734,608	193,599	74%	11,546,155	2,553,332	78%
Borealis	60%	512	435	15%	10,170	6,870	32%	166,877	70,048	58%
Capitol Corridor	90%	3,367	437	87%	56,375	4,678	92%	865,570	93,382	89%
Carolinian	60%	926	634	32%	16,527	9,479	43%	332,337	137,903	59%
Cascades	60%	2,137	907	58%	48,306	13,487	72%	731,186	251,513	66%
Downeaster	82%	1,164	118	90%	29,328	8,172	72%	408,010	101,165	75%
Empire	83%	5,061	1,449	71%	94,189	35,759	62%	1,556,171	338,055	78%
Adirondack	75%	254	168	34%	6,628	4,286	35%	84,623	26,985	68%
Ethan Allen Express	85%	547	345	37%	10,254	6,574	36%	155,465	39,898	74%
Maple Leaf	75%	733	236	68%	14,437	8,611	40%	210,514	63,774	70%
New York - Albany	90%	2,325	297	87%	37,191	8,939	76%	724,167	112,373	84%
New York - Niagara Falls	75%	1,202	403	66%	23,239	5,841	75%	377,072	92,740	75%
Berkshire Flyer	60%	0	0	-	2,440	1,508	38%	4,330	2,285	47%
Heartland Flyer	70%	197	191	3%	4,005	3,174	21%	63,524	29,237	54%
Hiawatha	90%	1,705	348	80%	34,377	4,288	88%	484,889	63,653	87%
Illinois	78%	2,023	1,383	32%	45,742	16,602	64%	716,154	173,679	76%
Carl Sandburg / Illinois Zephyr	80%	299	71	76%	7,791	1,629	79%	114,469	14,718	87%
Illini / Saluki	80%	650	295	55%	15,016	4,502	70%	253,313	33,373	87%
Lincoln Service	75%	1,074	1,017	5%	22,935	10,471	54%	348,372	125,588	64%
Keystone	92%	7,832	1,847	76%	122,347	11,813	90%	2,087,135	286,495	86%
Lincoln / Missouri	60%	745	526	29%	13,988	9,606	31%	207,965	114,487	45%
Michigan	69%	1,855	638	66%	40,351	10,629	74%	558,366	157,088	72%
Blue Water	70%	401	377	6%	9,996	2,856	71%	138,595	40,748	71%
Pere Marquette	85%	257	104	60%	4,868	797	84%	73,944	9,429	87%
Wolverine	65%	1,197	157	87%	25,487	6,976	73%	345,827	106,911	69%
Missouri	80%	184	21	89%	4,193	3,125	25%	63,025	22,613	64%
Pacific Surfliner	85%	5,177	570	89%	118,698	17,296	85%	1,653,307	266,647	84%
Pennsylvanian	72%	785	387	51%	15,471	4,675	70%	251,486	67,056	73%
Piedmont	73%	811	238	71%	15,650	5,769	63%	324,841	79,191	76%
San Joaquins	73%	1,638	1,356	17%	43,474	20,537	53%	707,286	194,907	72%
Vermont	75%	1,349	1,205	11%	21,417	7,640	64%	368,026	106,213	71%
Long Distance	57%	12,394	8,505	31%	216,825	127,801	41%	3,446,736	1,605,801	53%
Auto Train	57%	770	405	47%	13,405	4,467	67%	216,177	135,670	37%
California Zephyr	45%	1,069	1,008	6%	18,778	14,984	20%	281,421	121,484	57%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	0	0	-	4,075	2,031	50%	78,125	39,046	50%
City Of New Orleans	75%	696	425	39%	8,927	3,696	59%	183,727	51,905	72%
Coast Starlight	65%	955	436	54%	17,329	5,526	68%	303,130	126,272	58%
Crescent	60%	843	256	70%	17,144	6,920	60%	249,212	64,444	74%
Empire Builder	55%	1,130	689	39%	19,514	11,852	39%	274,505	120,355	56%
Floridian	40%	1,630	1,630	0%	24,996	20,681	17%	388,351	284,461	27%
Lake Shore Ltd	70%	946	414	56%	18,125	6,950	62%	289,962	79,578	73%
Palmetto	65%	881	381	57%	16,028	8,430	47%	284,176	109,546	61%
Silver Meteor	45%	817	700	14%	17,083	11,487	33%	266,469	139,393	48%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	976	744	24%	17,368	13,363	23%	230,304	140,289	39%
Sunset Ltd	50%	720	671	7%	4,708	2,795	41%	76,347	28,591	63%
Texas Eagle	60%	961	746	22%	19,345	14,619	24%	267,235	142,271	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 16, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	118,184	1,666,451	709	1,830,365	30,110,388	608

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	6,002	486,203	123	97,086	8,814,282	110
INFRASTRUCTURE PLANNED	90	3,185	486,203	66	90,331	8,814,282	102
FLEET RELIABILITY	83	19,863	1,666,451	119	288,743	30,110,388	96
TRAIN OPERATIONS	382	89,134	1,666,451	535	1,354,205	30,110,388	450

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 20(16) North of Anniston, AL - Freight Train Interference

17JUL25: Train 20(16) was delayed 33 miles north of Anniston, AL at MP703.1 on the Norfolk Southern East End Subdivision, due to meeting freight unit NS156-15. Train was also delayed due to unknown freight cross-traffic at MP139.8.

Train	Delay	Comment
20(16)	46"	

Train 52(16) South of Florence, SC - Freight Train Interference

17JUL25: Train 52(16) was delayed 13.4 miles south of Florence, SC at New Hope/MP A306.1 on the CSX Charleston Subdivision. due to CSX single-tracking though the Florence station, 52(16) had to wait for 53(16), I031-16 and I137-16. to clear, prior to proceeding north to Florence.

Train	Delay	Comment
52(16)	58"	
52(16)	15"	Meeting 53(16)

Train 243(16) New York, NY - Power Switch Failure

17JUL25: Train 243(16) was delayed departing New York, NY due to the 749 power switch failing. Train 243(16) was re-routed from Line 1 to through the Loop to Line 3, then to a lower track in NYP station, prior to departure.

Train	Delay	Comment
243(16)	53"	

PW Line High Water - North of Aberdeen, MD

17JUL25: Trains 175(16) and 66(16) were delayed North of Aberdeen, MD on the Amtrak PW Line due to high water reported above the rails between Oak/MP62.9 and Grace/MP61.5 and also between Perry/MP59.5 and Prince/MP57.3.

Train	Delay	Comment
66(16)	1'04"	
175(16)	31"	

Train 56(16) North of Essex Junction-Burlington, VT - Temporary Speed Restrictions

17JUL25:Train 56(16) was delayed 11 miles north of Essex Junction-Burlington, VT on the NECR Palmer Subdivision due to temporary speed restrictions in place between MP119 and MP128 operating 10 MPH.

Train	Delay	Comment
56(16)	56"	

Train 655(16) Paoli, PA - Disabled SE9547

16JUL25: Train 655(16) was delayed departing Paoli, PA/MP19.9 on the Amtrak PH Line due to disabled SEPTA SE9547, that experienced multiple penalties, and was unable to take power while trying to depart Paoli. Train 655(16) was able to fit into the station, then had to reverse and cross-over to get around the disabled SEPTA train. Train 620(16) and 622(16) were also delayed due to this. SEPTA SE9547 was rescued into Frazer yard at 1012P-ET.

Train	Delay	Comment
655(16)	1'05"	
622(16)	10"	
620(16)	25"	

PW Line T.O.L. - North of New Carrollton, MD

16JUL25: At 6:20PM, CETC reported a TOL at Carroll/MP127, on the Amtrak PW Line, with the 32 switch locked reverse. C&S responded to the location. At xxxPM, C&S was able to clear the TOL. Multiple trains were delayed through the area as a result.

Train	Delay	Comment
97(16)	1'06"	
85(16)	25"	
2167(16)	19"	
173(16)	21"	
129(16)	20"	
192(16)	03"	
138(16)	04"	
2124(16)	12"	
80(16)	14"	
196(16)	10"	
4 MARC's	08" - 1'16"	

Train 64(16) East of Syracuse, NY - Freight Train Interference

16JUL25: Train 64(16) held 0.7 miles east of Syracuse, NY/MP291.4, on the CSX Syracuse Terminal Subdivision, at MP290.7 meeting a CSX freight train.

Train	Delay	Comment
64(16)	39"	

Train 2166(16) East of New York, NY - Car Failure

17JUL25: Train 2166(16) TS1, PC2004, PC2018, was delayed just west of Manor at MP17 on the Amtrak NYS Line due to a ground detector fault on car 3217. Per rule, they were restricted to 20mph then were able to clear the fault and proceed at maximum C-speeds, accumulating additional delay.

Train	Delay	Comment
2166(16)	28"	ADTL 20" NHV-BOS

Train 68(16) South of St-Lambert, QC - Heat Orders

16JUL25: Train 68(16) was delayed starting 2.2 miles south of St-Lambert, QC/MP70.3, on the CNRR Rouses Point Subdivision, due to 25MPH heat orders between Southwark/MP42.7 and Rouses Point/MP0.0. Additional delay at the Rouses Point station waiting on customs to finish clearing the train.

Train	Delay	Comment
68(16)	41"	Heat Orders
68(16)	42"	RSP - Customs

CSX Heat Orders

16JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Alleghany, Kanawha, Mohawk, New River, and Syracuse Terminal.

Train	Delay	Comment
48 (15)	16"	
64 (16)	31"	
281 (16)	14"	
283 (16)	25"	
683 (16)	05"	
686 (16)	07"	
687 (16)	06"	

NJT 3924 Trespasser Strike - West of Newark, NJ

16JUL25: At 8:11AM, NJT 3924, CC/7044 and 8 Cars, reported striking a trespasser on the No. 2 track within the Hunter Interlocking limits at MP10.2. Exactly 1.4 miles west of the Newark, NJ station/MP8.8, on the Amtrak NYP Line. This is located in Newark NJ in Essex County. Amtrak Road Foreman Falkenstein and three members of the Amtrak Police Department responded. Local police, emergency services, medical examiner and members of the NJT transportation team also responded. The strike was confirmed fatal with the remains in the area of tracks 2 and 3. At 8:24AM, NJT police requested a hold on No. 1, 2, and 3 tracks. At 8:44AM, NJT police okayed the No. 1 track at restricted speed. During this time, Amtrak and New Jersey Transit trains operated through the area on Tracks 1 and 4 at restricted speed while the investigation was underway. At 10:11AM, NJT police reported all personnel were clear and all holds released with no speed restrictions. Normal operations resumed at this time.

National Response Center Number: 1437046

Train	Delay	Comment
190 (16)	11"	
2152 (16)	11"	
640 (16)	28"	
141 (16)	32"	
170 (16)	1'13"	
642 (16)	45"	
2151 (16)	47"	
643 (34)	34"	
2154 (16)	55"	
110 (16)	47"	
600 (16)	1'07"	
172 (16)	40"	
112 (16)	33"	
130 (16)	1'08"	
119 (16)	49"	ITD NYP - Turn of 130 (16)
644 (16)	37"	
56 (16)	21"	
175 (16)	21"	ITD BOS - Turn of 170 (16)
177 (16)	05"	ITD BOS - Turn off 172
53 NJT Trains	09" - 1'39"	

Train 67(15) Washington, DC - Car Failure

16JUL25: Train 67(15) was delayed at Washington Union Station, on the Amtrak WT Line, replacing Business Class / Café car 48156 with car 48181 due to an infestation. 67(15) was further delayed due to a coupling issue.

Train	Delay	Comment
67 (15)	31"	

Train 110(16) Philadelphia, PA - Engine Failure

16JUL25: Train 110(16) was delayed departing initial terminal of Philadelphia, PA/MP1.5, on the Amtrak PW Line, originally due to a late turn of equipment from train 179(15). Train 179(15) arrived to Philadelphia at 3:59AM EDT, 2 hours and 20 minutes late. Train 110(16) was further delayed due to engine 626 being shopped for failed self initialization and replaced with engine 643.

Train 185(16) was delayed departing New York, NY as a result of a late turn of Train 110(16)'s equipment that arrived at 11:20AM, 3 hours and 13 minutes late.

Train	Delay	Comment
110(16)	2'11"	
185(16)	2'33"	ITD NYP

Train 190(16) Philadelphia, PA - Car Failure

16JUL25: Train 190(16) was delayed departing Philadelphia, PA/MP1.5, on the Amtrak PW Line, after C/82986 was shopped for door bypass issues and replaced with C/82599.

Train 137(16) was delayed departing Boston, MA as a result of a late turn of Train 190(16)'s equipment that arrived at 1:10PM, 1 hours and 04 minutes late.

Train	Delay	Comment
190(16)	1'11"	
137(16)	26"	ITD BOS

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

- 370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

- 371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

Train	Delay	Comment
-------	-------	---------

301(15)	Cancelled, with alt CHI-STL
302(15)	Cancelled, with alt STL-CHI
307(14)	Cancelled, with alt CHI-STL
306(16-29)	Cancelled, no alternate
301(16-29)	Cancelled, no alternate

Train 6(14) Mendota, IL - Freight Train Interference

17JUL25: Train 6(14) was delayed 10 miles north of Mendota, IL, on BNSF Mendota subdivision, due to meeting train 383(16). These trains met due to 2 freight trains being tied down on main track 2.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(14)	50"	

Train 41(16) Chicago, IL - Initial Terminal Delay

17JUL25:Train 41(16) was delayed 30 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(14), replacing a bad order locomotive, and troubleshooting two cars with inoperative toilets. As background, inbound 40(14) arrived in Chicago at 1203pm; 3 hours and 18 minutes late due to 1 hour and 57 minutes of freight train interference, 1 hour and 7 minutes of weather restrictions, 43 minutes for ADA accommodations, and 26 minutes for a maritime bridge lift. Equipment set to the yard for servicing and inspection at 135pm. There were no scheduled program moves. At 335pm, lead engine AMTK 11 was bad ordered for wheel shelling. Blue flags were dropped at 416pm and replacement locomotive AMTK 62 was added in trail at 457pm. At 545pm, mechanical reported bad order toilets on coach 25049. Due to no replacement coaches, c/25049 to deadhead inline with the passengers downgraded (coach to be added in Washington, D.C). At 610pm, mechanical reported bad ordered toilets on sleeping car 62034. Due to no replacement sleepers, c/62034 to deadhead inline with the passengers downgraded. Train 41(16) was released by mechanical at 617pm, shoved from yard at 628pm, and set in the station at 638pm with 229 passengers to board. Train 41(16) departed Chicago at 710pm; 30 minutes late.

Train 41(16) was further delayed 1 mile south of Chicago, IL , due to a traction motor fault that would not reset. The crew worked with CNOC mechanical to resolve. After cycling the power the fault was reset and train 41(16) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(16)	30"	
41(16)	45"	

Train 14(16) Oakland, CA - Servicing

17JUL25: Train 14(16) was delayed at Oakland Yard/MP5.6, on UP Niles subdivision, setting out E/23 for a future Airo move.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(16)	46"	

Train 719(16) - Initial Terminal Delay

16JUL25: Train 719(16) was delayed departing Bakersfield station due to the late arrival of train 710(16) which arrived into the station at 4:25 pm 2 hours and 28 minutes late. 719(16) departed Bakersfield station at 5:05 pm 53" late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(16)	53"	

Train 393(16) South of Rantoul, IL - Debris

16JUL25: at approximately 7:24pm-ET, train 393(16) with E/4630, 7 coaches, and 164 passengers, went into emergency on CN, Chicago subdivision after striking a tree 8 miles north of Champaign, IL, at MP120.3. There were no reported injuries of passengers or crew and HEP remained active the entire time. There was minor damage reported of the sander on the motor which was hanging low to the rail and damage to the speed sensor as well. The crew determined that the sander was still high enough above the rail to be in compliance but the speed sensor caused issues with PTC. The crew was unable to resolve the issues with PTC and it was cut out, causing the train to operate a reduced speed of 59MPH from Champaign, IL, to Carbondale, IL.

Train 59(16) was delayed departing Chicago, IL, due to adding a rescue motor to its consist to be dropped off at Carbondale, IL for train 390(17).

Train	Delay	Comment
393(16)	53"	
59(16)	1'14"	

Train 581 - Commuter Train Interference

16JUL25: Train 581(16) was delayed outside of San Juan Capistrano station MP 197.2, Orange Subdivision of the San Diego Northern Railroad. A Metrolink train was blocking the station platform while they repaired a door issue on one of their cars. Once the door issue was resolved, the Metrolink train was able to depart and train 581(16) was able to enter into the station.

Train	Delay	Comment
581(16)	35"	

Train 7(15) East of Havre, MT - Freight Train Interference

17JUL25: Train 7(15) was delayed 3 miles east of Havre, MT, on BNSF Milk River subdivision due to CN8837 blocking the route into the station. Once the freight cleared and a route was made available, train 7(15) was able to proceed.

Train	Delay	Comment
7(15)	32"	

Train 508(16) - North of Eugene, OR - Signal Problems

16JUL25: Several attempts by the dispatcher failed to remotely prove the integrity of signals 20 miles north of Eugene at Alford, MP 667.6, Brooklyn Subdivision of the Union Pacific Railroad. This failure required The Engineer to verbally request permission to proceed past the first signal. The Engineer was then required to maintain verbal contact with the dispatcher, operating the train cautiously until within sight of the next verified remote signal, which was 10 miles away. Once clear of the affected area the train was able to continue at authorized track speed to Albany.

Train	Delay	Comment
508(16)	41"	

Train 717(16) - Engine Failure

16JUL25: Train 717(16) stopped shortly after departing Bakersfield station when locomotive C/2012 ceased providing electrical load. The train came to a halt at Jasper milepost 891.0, Bakersfield Subdivision, Burlington Northern Santa Fe Railway. The crew was advised to swap head end power from C/2012 to C/2005. Once this was complete, train 717(16) was able to proceed Wasco.

Train	Delay	Comment
717(16)	47"	

Train 3(16) West of Naperville, IL - Engine Failure

16JUL25: Train 3(16), operating with Locomotive 203, Locomotive 40 and 9 cars, was delayed at MP 34.6 on the Burlington Northern Santa Fe Chicago Subdivision, 6 miles west of the Naperville, IL station, duet o trail Locomotive 40 had a locked axle alarm. With assistance from CNOC Mechanical, the crew cut out traction motor #4 and continued.

Train 3(16) was further delayed adding BNSF5173 west of Kansas City, MO, at Argentine fuel rack.

Train	Delay	Comment
3(16)	1'13"	Locked Axle/Traction Motor Cutout
3(16)	48"	Adding BNSF Motor

Train 21(16) North of Bloomington-Normal, IL - Passenger Train Interference

17JUL25: Train 21(16) was delayed 20 miles north of Bloomington-Normal, IL, on UP Joliet subdivision, due to meeting train 22(15) Control Point 95.

Train	Delay	Comment
21(16)	30"	

Train 4(14) West of Princeton, IL - Passenger Train Interference

16JUL25: Train 4(14) was delayed at Buda / MP 116.7 on the Burlington Northern Santa Fe Mendota Subdivision, 13 miles west of the Princeton, IL station, meeting ECXNAM0-04 and Train 5(16).

Train	Delay	Comment
4(14)	1'20"	

Train 7(16) Chicago, IL - Engine Failure

17JUL25: Train 7(16) was delayed departing Chicago account a late release of E/333 due to a WiTronix update. E/333 was released from the diesel pit at 137PM, after waiting for a WiTronix Violet View software update. Once complete, E/333 was released at 137PM. The crew was on board shortly after, and departed the diesel pit at 203PM. After respotting the train to be in the clear on the North end of Track 9, Train 7(16) was given to mechanical and flagged in at 231PM. Mechanical released Train 7(16) at 253PM. Train 7(16) set in CUS at 303PM. Boarding began at 318PM and Train 7(16) departed Chicago at 341PM, 34" late.

Train	Delay	Comment
7(16)	34"	

Train 716(16) Oakland, CA - Servicing

16JUL25: Train 716(16) was delayed departing the Oakland Mechanical facility while waiting for the equipment to be fueled. Once fueling was complete, the train was released to the station to board passengers.

Train	Delay	Comment
716(16)	35"	

Train 22(15)/422(13) St. Louis, MO - System

16JUL25: Train 22(15) / 422(13) was delayed departing the St. Louis, MO Gateway Station due to a program move to add the local coach Car 35005.

Train	Delay	Comment
22(15) / 422(13)	30"	

Train 714(26) Initial Terminal Oakland, CA - Late Release/Equipment Turn

16JUL25: Train 714(26) was delayed departing Oakland, MP 7.0/UPRR Martinez Subdivision, following a late yard release as a result of turning and servicing equipment off inbound Train 711(16) which arrived Oakland 27 minutes late at 10:55AM-PT. Train 714(16) departed Oakland at 12:21PM-PT.

Train	Delay	Comment
714(26)	45"	

Train 365(16) East of Chicago, IL - Passenger Train Interference

16JUL25: Train 365(16) for 40 miles between Porter, IN and the Chicago, IL Union Station on the Norfolk Southern Chicago Terminal Subdivision following Train 40(14).

Train	Delay	Comment
365(16)	41"	

Train 391(16) South of Chicago, IL - Routing

16JUL25: Train 391(16) was delayed at 16th St / MP 2.1 on the Canadian National Freeport Subdivision, 2 miles south of the Chicago, IL Union Station, waiting on the Metra dispatching to line the signal.

Train	Delay	Comment
391(16)	31"	

Train 504(16) North of Salem, OR - Freight Train Interference

16JUL25: Train 504(16) was delayed holding in the siding at Hito, MP 742.4/UPRR Brooklyn Subdivision, 24.1 miles north of Salem, waiting on UPRR freight train MPDRV16 to clear the main track there (freight was also fouling the north switch at Hito) after its locomotive stalled. Mechanical forces were dispatched to the train to assist with repairs.

Train	Delay	Comment
504(16)	1'53"	

Train 6(16) Initial Terminal Emeryville, CA - Late Release/Servicing

16JUL25: Train 6(16) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of late equipment servicing and cleaning. Train 6(16) departed Emeryville at 9:32AM-PT.

Train	Delay	Comment
6(16)	1'07"	

Train 526(16) Martinez, CA - Drawbridge Opening

16JUL25: Train 526(16) was delayed at Vista, MP 33.0/UPRR Martinez Subdivision, 1 mile east of Martinez as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass.

Train	Delay	Comment
531(16)	21"	
526(16)	50"	
521(16)	1'08"	

Train 4(15) West of Gallup, NM - Trespasser Incident

16JUL25: 8:20 a.m. (MST), Train 4(15), operating Locomotive 193, Locomotive 163 and 9 cars, stopped at MP 213.8 on the Burlington Northern Santa Fe Gallup Subdivision, 57 miles west of the Gallup, NM station, after striking a cow. The crew found and secured several separated air hoses.

Train	Delay	Comment
4(15)	25"	

Train 710(16) Originated at Emeryville, CA - Locomotive Swap/Cab Car Issue

16JUL25: Train 710(16) originated at Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of delays incurred making a locomotive swap with 712(16)'s unit. Additional delay was then incurred due to a bad-ordered bell being repaired on cab car C/90218.

Passengers boarding at Oakland were reaccommodated onto Train 526(16) to Emeryville to make the train connection.

Train 710(16) departed Emeryville at 9:56AM-PT.

Work Element WBS #B.TR.100150.5892

WBS#: B.TR.100150.5892

Train	Delay	Comment
710(16)	2'10"	Originated at EMY

Capitol Corridor Drawbridge Malfunction West of Suisun, CA

16JUL25: Several Capitol Corridor trains were delayed as a result of the Suisun Bridge, MP 32.9/UPRR Martinez Subdivision (13.9 miles west of Suisun) having lockdown and signal problems. All train traffic was stopped pending repairs by bridge and signal maintainers. Train 521(16) held at the Suisun depot/MP 48.8. Train 523(16) held at the Fairfield-Vacaville depot/MP 53.8.

Mutual aid was in-effect for passengers on BART trains from Richmond to Berryessa/North San Jose and from Richmond to San Francisco (Civic Center). Mutual Aid was also available on ACE trains between Fremont and San Jose.

The bridge reopened to traffic at approximately 6:00AM-PT.

Train	Delay	Comment
520(16)	02"	
523(16)	16"	
521(16)	1'08"	

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Train 56(16) North of Essex Junction-Burlington, VT - M of W Work

17JUL25: Train 56(16) was delayed 6 miles north of Essex Junction-Burlington, VT at MP115 on the NECR Roxbury Subdivision, due to waiting for a maintenance of way truck crew to clear ahead.

Train	Delay	Comment
56(16)	1'22"	

BNSF Fallbridge Subdivision Track Work- Empire Builder 13th - 14th July

13JUL25: BNSF has scheduled trackwork for a bridge replacement on the Fallbridge Subdivision for 36 hours starting Sunday, July 13th at 7:00AM through Monday, July 14th at 7:00PM. To accommodate this infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(11Jul, 12Jul), which normally operates between Chicago (CHI) and Portland (PDX) , will terminate at Spokane (SPK).
- Train 28 (13Jul, 14Jul), which normally operates between Portland (PDX) and Chicago (CHI) , will originate at Spokane (SPK).

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between Spokane (SPK) and Portland (PDX) making all stops except Wishram (WIH).
- Bus 4028 will provide alternate transportation between Portland (PDX) and Spokane (SPK) making all stops except Wishram (WIH).

EQUIPMENT

- Equipment for Train 27(11Jul, 12Jul) will stay coupled to Train 7 at Spokane (SPK)
- Equipment for Train 28(13Jul, 14Jul) will be coupled to Train 8 departing Seattle (SEA)

WBS#: B.TR.100150.5751

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/16/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/16/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	34	88.7%	4,616	584	87.3%	83,323	8,253	90.1%
Central Division	91.5%	65	9	86.2%	1,057	121	88.6%	19,086	1,861	90.2%
Northeast Division	95.0%	95	11	88.4%	1,454	210	85.6%	27,409	2,973	89.2%
Southeast Division	94.5%	69	5	92.8%	1,015	133	86.9%	18,444	1,847	90.0%
Southwest Division	90.5%	71	9	87.3%	1,090	120	89.0%	18,384	1,572	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/16/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/16/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	34	88.7%	4,616	584	87.3%	83,323	8,253	90.1%
Central Division	91.5%	65	9	86.2%	1,057	121	88.6%	19,086	1,861	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	37	2	94.6%	580	16	97.2%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	26	5	80.8%	427	68	84.1%	7,703	953	87.6%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	32	0	100.0%	556	19	96.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	15	0	100.0%	288	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	31	1	96.8%	560	38	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	1	83.3%	93	4	95.7%	1,656	92	94.4%
MSP	95.0%	1	0	100.0%	16	2	87.5%	277	14	94.9%
PDX	78.0%	5	0	100.0%	76	7	90.8%	1,388	159	88.5%
PNT	94.0%	3	0	100.0%	47	0	100.0%	794	56	92.9%
PTH	96.0%	1	0	100.0%	16	0	100.0%	287	11	96.2%
QCY	94.0%	2	0	100.0%	30	0	100.0%	560	18	96.8%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	2	75.0%	129	26	79.8%	2,256	326	85.5%
SPK	92.0%	1	0	100.0%	14	1	92.9%	285	14	95.1%
STL	96.0%	3	1	66.7%	58	6	89.7%	1,135	59	94.8%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	32	0	100.0%	553	12	97.8%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	95	11	88.4%	1,454	210	85.6%	27,409	2,973	89.2%
ALB	96.0%	6	1	83.3%	96	4	95.8%	1,945	126	93.5%
BON	94.5%	4	0	100.0%	78	8	89.7%	1,342	91	93.2%
BOS	97.0%	19	2	89.5%	284	30	89.4%	5,401	496	90.8%
BRK	97.0%	2	0	100.0%	51	2	96.1%	1,312	68	94.8%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	16	2	87.5%	287	19	93.4%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	29	2	93.1%	556	54	90.3%
HFD	-	2	0	100.0%	22	4	81.8%	168	17	89.9%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/16/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/16/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	34	88.7%	4,616	584	87.3%	83,323	8,253	90.1%
Northeast Division	95.0%	95	11	88.4%	1,454	210	85.6%	27,409	2,973	89.2%
MTR	97.0%	1	0	100.0%	16	2	87.5%	287	28	90.2%
NFL	97.0%	2	0	100.0%	32	1	96.9%	578	24	95.8%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	0	100.0%	75	12	84.0%	1,482	146	90.1%
NYP	94.5%	42	7	83.3%	618	122	80.3%	11,611	1,760	84.8%
POR	-	-	-	-	24	8	66.7%	24	8	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	14	3	78.6%	285	8	97.2%
SPG	95.5%	5	0	100.0%	76	7	90.8%	1,772	83	95.3%
TWO	96.0%	1	0	100.0%	16	0	100.0%	286	11	96.2%
WEM	-	2	1	50.0%	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	69	5	92.8%	1,015	133	86.9%	18,444	1,847	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	77	9	88.3%	1,431	94	93.4%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	1	92.3%	178	13	92.7%	3,123	101	96.8%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	16	3	81.3%	283	91	67.8%
MIA	90.0%	2	0	100.0%	31	3	90.3%	556	50	91.0%
NFK	94.5%	3	0	100.0%	45	10	77.8%	795	64	91.9%
NOL	92.0%	3	0	100.0%	34	3	91.2%	641	46	92.8%
NPN	96.0%	2	0	100.0%	32	3	90.6%	551	20	96.4%
PGH	92.0%	1	0	100.0%	16	2	87.5%	288	16	94.4%
PHL	97.0%	5	3	40.0%	68	18	73.5%	1,234	175	85.8%
RGH	97.0%	4	0	100.0%	56	2	96.4%	1,159	36	96.9%
RNK	94.0%	2	0	100.0%	29	1	96.6%	546	63	88.5%
RVM	90.0%	1	0	100.0%	16	1	93.8%	280	34	87.9%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	14	0	100.0%	270	10	96.3%
SFA	83.0%	1	0	100.0%	16	1	93.8%	283	79	72.1%
WAS	94.5%	25	1	96.0%	377	54	85.7%	6,851	935	86.4%
Southwest Division	90.5%	71	9	87.3%	1,090	120	89.0%	18,384	1,572	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	16	0	100.0%	289	7	97.6%
BFD	90.0%	6	1	83.3%	94	12	87.2%	1,717	148	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	16	14	12.5%	296	90	69.6%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	15	2	86.7%	321	42	86.9%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/16/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/16/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	34	88.7%	4,616	584	87.3%	83,323	8,253	90.1%
Southwest Division	90.5%	71	9	87.3%	1,090	120	89.0%	18,384	1,572	91.4%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	48	2	95.8%	844	62	92.7%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	10	1	90.0%	151	16	89.4%	2,210	307	86.1%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	13	0	100.0%	284	6	97.9%
OKJ	91.0%	12	5	58.3%	176	28	84.1%	3,029	278	90.8%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	0	100.0%	209	22	89.5%	3,440	147	95.7%
SAN	90.0%	12	1	91.7%	190	12	93.7%	2,612	230	91.2%
SAS	85.0%	1	0	100.0%	16	5	68.8%	285	40	86.0%
SJC	95.0%	7	0	100.0%	111	6	94.6%	1,851	72	96.1%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	32	0	100.0%	565	27	95.2%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	2	0	100.0%	49	11	77.6%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/16/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	928	7	0	100.0%	122	15	87.7%	7	4	42.9%	122	34	72.1%
3	74	16	5	68.8%	283	55	80.6%	16	12	25.0%	279	153	45.2%
4	269	16	3	81.3%	284	68	76.1%	16	12	25.0%	283	143	49.5%
5	65	16	9	43.8%	286	48	83.2%	15	12	20.0%	283	95	66.4%
6	383	16	14	12.5%	286	83	71.0%	16	13	18.8%	285	95	66.7%
7		16	4	75.0%	280	40	85.7%	16	5	68.8%	275	72	73.8%
8	64	16	12	25.0%	281	104	63.0%	16	12	25.0%	279	133	52.3%
11		16	2	87.5%	288	46	84.0%	16	2	87.5%	281	63	77.6%
14		16	5	68.8%	289	87	69.9%	16	6	62.5%	287	126	56.1%
19		16	0	100.0%	289	33	88.6%	16	7	56.3%	288	56	80.6%
20		16	1	93.8%	289	14	95.2%	16	4	75.0%	288	46	84.0%
21		16	1	93.8%	288	35	87.8%	16	6	62.5%	282	89	68.4%
22	301	16	5	68.8%	285	42	85.3%	16	14	12.5%	284	122	57.0%
27		14	5	64.3%	276	22	92.0%	13	5	61.5%	266	91	65.8%
28		13	1	92.3%	269	66	75.5%	13	3	76.9%	268	75	72.0%
40	198	16	2	87.5%	246	35	85.8%	15	11	26.7%	241	150	37.8%
41	76	15	11	26.7%	244	106	56.6%	15	14	6.7%	240	191	20.4%
42	22	16	2	87.5%	289	17	94.1%	16	5	68.8%	289	79	72.7%
43	30	16	2	87.5%	289	25	91.3%	16	5	68.8%	289	65	77.5%
48		16	4	75.0%	288	52	81.9%	16	4	75.0%	288	45	84.4%
49		16	6	62.5%	289	56	80.6%	16	4	75.0%	289	51	82.4%
50	145	7	4	42.9%	123	39	68.3%	7	5	28.6%	122	87	28.7%
52		16	1	93.8%	283	79	72.1%	16	4	75.0%	283	151	46.6%
53		16	3	81.3%	283	91	67.8%	16	4	75.0%	283	144	49.1%
55	47	11	2	81.8%	200	8	96.0%	11	5	54.5%	200	44	78.0%
56	179	11	2	81.8%	200	35	82.5%	11	8	27.3%	199	51	74.4%
58		16	2	87.5%	281	23	91.8%	16	2	87.5%	278	55	80.2%
59	106	16	5	68.8%	280	57	79.6%	15	5	66.7%	276	32	88.4%
63		16	9	43.8%	289	55	81.0%	16	14	12.5%	289	146	49.5%
64	43	16	0	100.0%	289	11	96.2%	16	3	81.3%	289	71	75.4%
66		16	2	87.5%	287	55	80.8%	16	1	93.8%	285	37	87.0%
67	32	11	0	100.0%	199	17	91.5%	11	3	72.7%	197	42	78.7%
68	61	16	2	87.5%	289	28	90.3%	16	13	18.8%	289	117	59.5%
69		16	2	87.5%	289	22	92.4%	15	6	60.0%	284	33	88.4%
71		15	2	86.7%	288	7	97.6%	15	8	46.7%	286	66	76.9%
72		16	3	81.3%	289	22	92.4%	16	6	62.5%	287	73	74.6%
73	40	16	3	81.3%	289	15	94.8%	16	9	43.8%	287	144	49.8%
74		16	1	93.8%	285	21	92.6%	16	8	50.0%	283	98	65.4%
75		16	3	81.3%	287	8	97.2%	16	10	37.5%	285	117	58.9%
76	21	16	4	75.0%	285	20	93.0%	15	11	26.7%	283	124	56.2%
77		16	2	87.5%	286	12	95.8%	16	8	50.0%	284	128	54.9%
78		16	0	100.0%	287	10	96.5%	15	5	66.7%	286	69	75.9%

Amtrak On Time Performance													
Trains Arriving Through: 7/16/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79		16	5	68.8%	289	40	86.2%	14	5	64.3%	286	103	64.0%
80	64	16	3	81.3%	289	24	91.7%	16	10	37.5%	289	83	71.3%
84		11	0	100.0%	199	8	96.0%	11	6	45.5%	198	75	62.1%
85	31	11	0	100.0%	197	16	91.9%	11	8	27.3%	196	134	31.6%
86		11	1	90.9%	197	23	88.3%	11	9	18.2%	197	134	32.0%
89	51	16	1	93.8%	288	35	87.8%	16	6	62.5%	286	104	63.6%
90		16	0	100.0%	288	11	96.2%	15	7	53.3%	283	71	74.9%
93		11	0	100.0%	200	14	93.0%	11	6	45.5%	199	92	53.8%
94		11	4	63.6%	200	18	91.0%	11	6	45.5%	199	72	63.8%
95		11	0	100.0%	200	5	97.5%	11	5	54.5%	200	86	57.0%
97		16	13	18.8%	285	134	53.0%	16	9	43.8%	284	93	67.3%
98	208	16	1	93.8%	285	16	94.4%	16	11	31.3%	285	147	48.4%
110	193	11	4	63.6%	198	37	81.3%	11	2	81.8%	196	41	79.1%
111		11	2	81.8%	197	49	75.1%	11	2	81.8%	195	32	83.6%
112	24	11	2	81.8%	192	37	80.7%	11	3	72.7%	190	24	87.4%
114		11	2	81.8%	196	53	73.0%	11	3	72.7%	192	30	84.4%
119	39	11	1	90.9%	194	39	79.9%	11	2	81.8%	191	29	84.8%
125		11	1	90.9%	200	10	95.0%	11	7	36.4%	200	114	43.0%
129	24	11	3	72.7%	198	41	79.3%	11	5	54.5%	197	43	78.2%
130	61	11	1	90.9%	194	20	89.7%	11	1	90.9%	191	22	88.5%
131		11	2	81.8%	191	34	82.2%	11	2	81.8%	189	28	85.2%
133		11	6	45.5%	198	74	62.6%	11	9	18.2%	198	102	48.5%
134		11	0	100.0%	199	15	92.5%	11	7	36.4%	199	98	50.8%
136		11	0	100.0%	200	39	80.5%	11	3	72.7%	198	41	79.3%
137	19	11	4	63.6%	200	25	87.5%	11	5	54.5%	200	80	60.0%
138		11	2	81.8%	199	23	88.4%	11	6	45.5%	199	49	75.4%
141		11	0	100.0%	200	3	98.5%	11	6	45.5%	200	96	52.0%
148		11	1	90.9%	200	18	91.0%	11	4	63.6%	200	43	78.5%
151	17	16	3	81.3%	286	35	87.8%	16	4	75.0%	285	97	66.0%
170	80	11	0	100.0%	199	12	94.0%	11	6	45.5%	199	51	74.4%
171		11	1	90.9%	200	8	96.0%	11	7	36.4%	200	101	49.5%
172	70	11	2	81.8%	199	15	92.5%	11	4	63.6%	197	63	68.0%
173	40	11	0	100.0%	200	26	87.0%	11	3	72.7%	200	66	67.0%
174		11	2	81.8%	200	6	97.0%	11	5	54.5%	199	47	76.4%
175	72	11	5	54.5%	199	35	82.4%	11	6	45.5%	198	72	63.6%
176		11	3	72.7%	200	19	90.5%	11	1	90.9%	199	25	87.4%
177		11	2	81.8%	200	28	86.0%	11	4	63.6%	199	41	79.4%
178		11	1	90.9%	200	30	85.0%	11	6	45.5%	199	42	78.9%
179	140	11	2	81.8%	198	14	92.9%	11	8	27.3%	198	69	65.2%
181		11	4	63.6%	195	38	80.5%	11	1	90.9%	191	27	85.9%
182		11	2	81.8%	195	48	75.4%	11	6	45.5%	194	51	73.7%
183		11	2	81.8%	200	26	87.0%	11	1	90.9%	200	25	87.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/16/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		11	5	54.5%	200	29	85.5%	11	2	81.8%	199	25	87.4%
185	143	11	2	81.8%	200	34	83.0%	11	2	81.8%	200	26	87.0%
186		11	1	90.9%	197	12	93.9%	11	6	45.5%	195	56	71.3%
190	64	11	5	54.5%	200	40	80.0%	11	5	54.5%	200	50	75.0%
192		11	2	81.8%	96	16	83.3%	11	3	72.7%	94	12	87.2%
193		11	4	63.6%	198	34	82.8%	11	6	45.5%	197	72	63.5%
196		11	0	100.0%	200	69	65.5%	11	2	81.8%	197	58	70.6%
197		11	6	45.5%	199	50	74.9%	11	3	72.7%	198	55	72.2%
232	28	16	1	93.8%	277	10	96.4%	16	1	93.8%	277	22	92.1%
233		14	4	71.4%	285	84	70.5%	14	7	50.0%	284	98	65.5%
234		16	0	100.0%	277	6	97.8%	16	1	93.8%	277	21	92.4%
236		16	0	100.0%	277	5	98.2%	16	1	93.8%	276	45	83.7%
237		14	0	100.0%	273	28	89.7%	14	2	85.7%	271	32	88.2%
239		16	3	81.3%	276	28	89.9%	16	4	75.0%	276	20	92.8%
240		16	0	100.0%	281	24	91.5%	16	5	68.8%	280	27	90.4%
241		16	3	81.3%	289	36	87.5%	15	4	73.3%	288	40	86.1%
243		11	4	63.6%	200	36	82.0%	11	4	63.6%	199	26	86.9%
244		14	1	92.9%	285	8	97.2%	14	8	42.9%	285	47	83.5%
280		16	0	100.0%	288	11	96.2%	16	1	93.8%	288	52	81.9%
281	29	16	2	87.5%	289	60	79.2%	15	4	73.3%	287	59	79.4%
283	27	16	6	62.5%	289	63	78.2%	16	7	56.3%	288	60	79.2%
284		16	1	93.8%	289	13	95.5%	16	0	100.0%	288	58	79.9%
290	35	16	2	87.5%	289	21	92.7%	15	11	26.7%	287	64	77.7%
291	59	16	6	62.5%	289	44	84.8%	16	11	31.3%	288	57	80.2%
300	29	14	1	92.9%	278	8	97.1%	14	4	71.4%	276	67	75.7%
302	71	15	1	93.3%	283	19	93.3%	15	6	60.0%	280	96	65.7%
305	70	16	2	87.5%	283	21	92.6%	16	13	18.8%	282	109	61.3%
307	33	15	1	93.3%	282	37	86.9%	14	9	35.7%	279	104	62.7%
311		15	3	80.0%	279	18	93.5%	15	13	13.3%	275	109	60.4%
316		15	1	93.3%	277	19	93.1%	15	13	13.3%	275	102	62.9%
318	87	16	0	100.0%	285	19	93.3%	16	11	31.3%	281	158	43.8%
319	28	16	1	93.8%	287	19	93.4%	16	15	6.3%	282	176	37.6%
329		11	1	90.9%	201	17	91.5%	11	0	100.0%	201	16	92.0%
330		13	1	92.3%	233	5	97.9%	13	1	92.3%	232	15	93.5%
331		16	1	93.8%	280	20	92.9%	16	2	87.5%	276	27	90.2%
332		16	0	100.0%	285	16	94.4%	16	2	87.5%	284	43	84.9%
334		16	0	100.0%	285	9	96.8%	16	3	81.3%	280	71	74.6%
335		16	2	87.5%	288	31	89.2%	16	4	75.0%	279	60	78.5%
336	12	16	1	93.8%	274	7	97.4%	16	5	68.8%	273	80	70.7%
337	29	16	1	93.8%	277	16	94.2%	16	5	68.8%	276	62	77.5%
338		16	2	87.5%	287	37	87.1%	16	7	56.3%	277	122	56.0%
339		16	0	100.0%	287	42	85.4%	16	2	87.5%	285	50	82.5%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
341	18	15	8	46.7%	272	53	80.5%	15	8	46.7%	266	55	79.3%
342		16	0	100.0%	288	18	93.8%	16	1	93.8%	287	44	84.7%
350		16	1	93.8%	248	26	89.5%	16	10	37.5%	245	123	49.8%
351		16	0	100.0%	277	24	91.3%	16	4	75.0%	276	77	72.1%
352		16	3	81.3%	282	27	90.4%	16	8	50.0%	277	79	71.5%
353		16	0	100.0%	241	6	97.5%	16	1	93.8%	236	36	84.7%
354		15	0	100.0%	281	26	90.7%	15	4	73.3%	278	102	63.3%
355		15	0	100.0%	281	30	89.3%	15	3	80.0%	277	71	74.4%
364	20	16	1	93.8%	287	55	80.8%	16	4	75.0%	286	78	72.7%
365	34	16	0	100.0%	287	11	96.2%	16	6	62.5%	286	84	70.6%
370	18	15	1	93.3%	288	11	96.2%	14	2	85.7%	287	35	87.8%
371		15	0	100.0%	288	4	98.6%	15	2	86.7%	288	27	90.6%
380		16	1	93.8%	286	11	96.2%	16	1	93.8%	286	27	90.6%
381		16	2	87.5%	286	8	97.2%	16	5	68.8%	285	28	90.2%
382		16	1	93.8%	285	11	96.1%	16	4	75.0%	285	37	87.0%
383	17	16	0	100.0%	287	29	89.9%	16	8	50.0%	286	67	76.6%
390		16	2	87.5%	284	12	95.8%	16	7	56.3%	282	43	84.8%
391	40	16	0	100.0%	287	6	97.9%	16	4	75.0%	285	53	81.4%
392		16	0	100.0%	287	8	97.2%	16	4	75.0%	284	30	89.4%
393	109	16	1	93.8%	286	13	95.5%	16	8	50.0%	283	41	85.5%
417		11	2	81.8%	196	32	83.7%	10	1	90.0%	193	29	85.0%
425		11	0	100.0%	184	5	97.3%	11	0	100.0%	184	7	96.2%
470		12	2	83.3%	202	15	92.6%	10	2	80.0%	197	28	85.8%
471		11	2	81.8%	200	14	93.0%	10	0	100.0%	198	11	94.4%
473		11	2	81.8%	200	7	96.5%	10	1	90.0%	199	3	98.5%
474	22	11	2	81.8%	198	30	84.8%	10	5	50.0%	194	59	69.6%
475		11	2	81.8%	199	8	96.0%	11	1	90.9%	196	17	91.3%
478		11	1	90.9%	200	21	89.5%	10	1	90.0%	198	20	89.9%
479	20	11	1	90.9%	200	30	85.0%	11	2	81.8%	199	24	87.9%
486		11	0	100.0%	202	16	92.1%	11	4	63.6%	200	68	66.0%
494		11	4	63.6%	205	31	84.9%	11	5	54.5%	199	55	72.4%
495		11	0	100.0%	197	2	99.0%	11	1	90.9%	197	5	97.5%
500		16	1	93.8%	278	22	92.1%	15	3	80.0%	276	81	70.7%
502		16	0	100.0%	276	13	95.3%	15	1	93.3%	274	79	71.2%
503	31	16	1	93.8%	289	30	89.6%	16	6	62.5%	278	87	68.7%
504	148	16	0	100.0%	277	9	96.8%	15	4	73.3%	276	111	59.8%
505		16	2	87.5%	281	33	88.3%	15	5	66.7%	278	102	63.3%
506		16	3	81.3%	281	27	90.4%	15	3	80.0%	279	69	75.3%
507	77	16	3	81.3%	280	33	88.2%	16	7	56.3%	279	87	68.8%
508	77	16	0	100.0%	284	13	95.4%	16	5	68.8%	282	83	70.6%
509		16	3	81.3%	279	31	88.9%	15	4	73.3%	278	98	64.7%
511		16	1	93.8%	280	23	91.8%	16	3	81.3%	277	75	72.9%

Amtrak On Time Performance													
Trains Arriving Through: 7/16/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
516	24	16	1	93.8%	280	25	91.1%	16	8	50.0%	278	126	54.7%
517		16	0	100.0%	281	5	98.2%	16	6	62.5%	280	169	39.6%
518	56	16	3	81.3%	281	32	88.6%	16	7	56.3%	279	168	39.8%
519		16	0	100.0%	278	11	96.0%	16	3	81.3%	277	58	79.1%
520		11	2	81.8%	32	4	87.5%	11	0	100.0%	32	1	96.9%
521	65	11	0	100.0%	200	4	98.0%	11	1	90.9%	199	16	92.0%
522		11	1	90.9%	200	4	98.0%	10	0	100.0%	199	11	94.5%
523	14	11	0	100.0%	201	4	98.0%	11	1	90.9%	201	26	87.1%
524		11	1	90.9%	201	6	97.0%	10	2	80.0%	200	35	82.5%
525		11	0	100.0%	199	4	98.0%	11	0	100.0%	198	10	94.9%
526	41	11	0	100.0%	32	4	87.5%	11	3	72.7%	32	7	78.1%
527		11	0	100.0%	201	3	98.5%	11	0	100.0%	200	29	85.5%
528		11	0	100.0%	200	5	97.5%	11	1	90.9%	200	31	84.5%
529	11	11	0	100.0%	201	0	100.0%	11	3	72.7%	201	39	80.6%
531	19	11	1	90.9%	200	3	98.5%	11	3	72.7%	199	16	92.0%
532		11	0	100.0%	201	9	95.5%	11	0	100.0%	199	20	89.9%
534		11	2	81.8%	201	15	92.5%	11	1	90.9%	200	15	92.5%
535		11	2	81.8%	32	3	90.6%	10	0	100.0%	31	2	93.5%
536		11	0	100.0%	201	8	96.0%	11	1	90.9%	199	9	95.5%
537		10	0	100.0%	31	1	96.8%	10	0	100.0%	31	2	93.5%
538		11	1	90.9%	201	5	97.5%	11	2	81.8%	201	36	82.1%
540		11	0	100.0%	201	5	97.5%	11	2	81.8%	196	20	89.8%
541		11	0	100.0%	201	8	96.0%	11	3	72.7%	201	43	78.6%
542		11	1	90.9%	201	8	96.0%	11	3	72.7%	201	35	82.6%
543		11	0	100.0%	201	6	97.0%	11	7	36.4%	201	31	84.6%
544		10	1	90.0%	199	11	94.5%	10	0	100.0%	198	15	92.4%
545		11	1	90.9%	201	8	96.0%	11	1	90.9%	199	21	89.4%
546		11	0	100.0%	201	7	96.5%	11	3	72.7%	200	31	84.5%
547		11	2	81.8%	201	9	95.5%	11	3	72.7%	201	29	85.6%
548		11	0	100.0%	199	12	94.0%	11	0	100.0%	197	11	94.4%
549		11	4	63.6%	201	23	88.6%	10	0	100.0%	195	29	85.1%
551		11	0	100.0%	201	10	95.0%	11	0	100.0%	196	17	91.3%
562		16	0	100.0%	285	31	89.1%	16	1	93.8%	276	31	88.8%
564		16	3	81.3%	283	20	92.9%	16	2	87.5%	280	26	90.7%
566		16	0	100.0%	108	10	90.7%	16	0	100.0%	108	11	89.8%
572		16	2	87.5%	238	21	91.2%	16	5	68.8%	234	43	81.6%
573		16	0	100.0%	277	37	86.6%	16	0	100.0%	271	43	84.1%
577		16	0	100.0%	31	0	100.0%	16	2	87.5%	31	2	93.5%
580		16	0	100.0%	285	21	92.6%	16	1	93.8%	284	53	81.3%
581	47	16	2	87.5%	285	35	87.7%	16	4	75.0%	281	55	80.4%
582		16	0	100.0%	31	0	100.0%	16	2	87.5%	31	3	90.3%
586	23	16	1	93.8%	236	30	87.3%	16	3	81.3%	229	41	82.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/16/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
587		16	2	87.5%	236	27	88.6%	15	2	86.7%	229	48	79.0%
591		16	0	100.0%	285	32	88.8%	16	2	87.5%	281	40	85.8%
593		16	4	75.0%	31	6	80.6%	16	4	75.0%	31	7	77.4%
595		16	2	87.5%	277	60	78.3%	16	1	93.8%	275	49	82.2%
600	58	11	2	81.8%	199	4	98.0%	11	2	81.8%	197	26	86.8%
601		11	2	81.8%	199	19	90.5%	11	2	81.8%	198	33	83.3%
605		11	1	90.9%	199	11	94.5%	11	0	100.0%	197	26	86.8%
607		11	1	90.9%	200	18	91.0%	11	0	100.0%	199	10	95.0%
609		11	1	90.9%	200	13	93.5%	10	1	90.0%	199	30	84.9%
620	30	11	1	90.9%	200	6	97.0%	11	3	72.7%	198	27	86.4%
622	14	9	2	77.8%	158	8	94.9%	9	2	77.8%	157	47	70.1%
639		11	1	90.9%	200	26	87.0%	11	2	81.8%	199	24	87.9%
640	28	11	1	90.9%	200	1	99.5%	11	2	81.8%	200	100	50.0%
641		11	0	100.0%	200	18	91.0%	11	0	100.0%	200	34	83.0%
642	38	11	0	100.0%	200	0	100.0%	11	1	90.9%	199	42	78.9%
643	45	11	0	100.0%	200	13	93.5%	11	1	90.9%	199	42	78.9%
644	34	11	1	90.9%	200	9	95.5%	10	2	80.0%	197	46	76.6%
645	11	11	1	90.9%	200	15	92.5%	10	3	70.0%	199	52	73.9%
646		11	1	90.9%	200	18	91.0%	11	3	72.7%	197	99	49.7%
647		11	1	90.9%	200	15	92.5%	10	4	60.0%	199	79	60.3%
648		11	0	100.0%	200	12	94.0%	11	4	63.6%	198	34	82.8%
649		11	0	100.0%	200	20	90.0%	11	4	63.6%	199	39	80.4%
650		11	0	100.0%	200	10	95.0%	11	1	90.9%	199	30	84.9%
651		11	2	81.8%	200	25	87.5%	11	3	72.7%	200	80	60.0%
652		11	1	90.9%	200	4	98.0%	11	4	63.6%	200	36	82.0%
653		11	0	100.0%	200	13	93.5%	11	4	63.6%	199	66	66.8%
654		11	1	90.9%	200	5	97.5%	11	0	100.0%	198	20	89.9%
655	53	11	1	90.9%	199	30	84.9%	11	4	63.6%	197	70	64.5%
656		11	2	81.8%	200	5	97.5%	11	2	81.8%	199	45	77.4%
657		11	1	90.9%	200	14	93.0%	11	1	90.9%	200	50	75.0%
658		11	0	100.0%	200	6	97.0%	11	3	72.7%	199	53	73.4%
680		12	0	100.0%	202	2	99.0%	12	1	91.7%	201	32	84.1%
681		12	0	100.0%	201	12	94.0%	12	6	50.0%	198	79	60.1%
682		12	0	100.0%	202	5	97.5%	12	1	91.7%	202	95	53.0%
683		11	0	100.0%	154	4	97.4%	11	6	45.5%	154	62	59.7%
686		12	5	58.3%	201	41	79.6%	12	7	41.7%	201	84	58.2%
687	24	12	1	91.7%	202	29	85.6%	12	7	41.7%	202	79	60.9%
688		12	1	91.7%	202	8	96.0%	12	2	83.3%	202	89	55.9%
702	50	16	2	87.5%	289	19	93.4%	16	10	37.5%	288	95	67.0%
703		16	2	87.5%	289	29	90.0%	16	7	56.3%	289	72	75.1%
710	148	16	4	75.0%	289	46	84.1%	15	9	40.0%	282	79	72.0%
711	27	16	0	100.0%	288	10	96.5%	16	6	62.5%	279	32	88.5%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
712	33	16	2	87.5%	289	45	84.4%	15	9	40.0%	286	87	69.6%
713	28	15	0	100.0%	287	9	96.9%	13	9	30.8%	270	59	78.1%
714	72	16	4	75.0%	288	39	86.5%	16	9	43.8%	283	71	74.9%
715	31	16	3	81.3%	288	42	85.4%	15	11	26.7%	277	88	68.2%
716	72	16	5	68.8%	288	33	88.5%	15	4	73.3%	287	60	79.1%
717	41	15	3	80.0%	283	33	88.3%	13	4	69.2%	267	66	75.3%
718		16	5	68.8%	289	42	85.5%	15	3	80.0%	287	52	81.9%
719	123	16	4	75.0%	289	27	90.7%	16	7	56.3%	281	64	77.2%
761	22	16	0	100.0%	285	17	94.0%	16	2	87.5%	285	35	87.7%
765		16	0	100.0%	285	12	95.8%	16	1	93.8%	276	40	85.5%
769		16	0	100.0%	283	11	96.1%	16	1	93.8%	279	51	81.7%
770		16	0	100.0%	285	17	94.0%	16	5	68.8%	282	39	86.2%
774		16	0	100.0%	285	8	97.2%	16	3	81.3%	281	65	76.9%
779		16	0	100.0%	31	1	96.8%	16	3	81.3%	31	7	77.4%
784		16	1	93.8%	285	33	88.4%	16	8	50.0%	282	113	59.9%
785		16	2	87.5%	285	15	94.7%	16	1	93.8%	283	44	84.5%
790		16	1	93.8%	285	15	94.7%	16	1	93.8%	282	42	85.1%
794		16	0	100.0%	285	22	92.3%	16	1	93.8%	284	58	79.6%
821	44	13	0	100.0%	284	6	97.9%	13	11	15.4%	284	145	48.9%
822	60	15	2	86.7%	286	13	95.5%	15	15	0.0%	286	146	49.0%
1333	29	16	1	93.8%	282	51	81.9%	16	14	12.5%	281	180	35.9%
1340	39	16	2	87.5%	281	14	95.0%	16	12	25.0%	279	95	65.9%
1689	15	9	0	100.0%	69	0	100.0%	10	2	80.0%	69	15	78.3%
2103		11	0	100.0%	197	11	94.4%	11	1	90.9%	194	23	88.1%
2107		11	4	63.6%	196	37	81.1%	11	1	90.9%	192	27	85.9%
2108		11	0	100.0%	193	19	90.2%	10	2	80.0%	190	29	84.7%
2121	44	11	1	90.9%	194	32	83.5%	10	4	60.0%	189	45	76.2%
2122		11	3	72.7%	195	37	81.0%	11	4	63.6%	189	35	81.5%
2124	16	9	2	77.8%	156	28	82.1%	9	3	66.7%	153	35	77.1%
2150		11	0	100.0%	200	7	96.5%	11	2	81.8%	200	62	69.0%
2151	54	11	0	100.0%	200	0	100.0%	11	5	54.5%	200	50	75.0%
2152		11	1	90.9%	198	6	97.0%	11	7	36.4%	192	81	57.8%
2153	27	10	0	100.0%	195	5	97.4%	10	7	30.0%	193	46	76.2%
2154	58	11	1	90.9%	198	15	92.4%	10	6	40.0%	194	85	56.2%
2155		10	1	90.0%	190	13	93.2%	10	5	50.0%	183	78	57.4%
2159		11	2	81.8%	197	16	91.9%	11	4	63.6%	192	62	67.7%
2162		11	1	90.9%	199	16	92.0%	10	3	70.0%	193	67	65.3%
2163	27	11	0	100.0%	199	15	92.5%	11	7	36.4%	193	79	59.1%
2166	44	11	2	81.8%	199	11	94.5%	11	6	45.5%	197	45	77.2%
2167	18	11	1	90.9%	200	28	86.0%	11	6	45.5%	198	52	73.7%
2168		11	3	72.7%	200	17	91.5%	11	4	63.6%	199	46	76.9%
2169		11	4	63.6%	197	49	75.1%	10	4	60.0%	190	66	65.3%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
Train	Late												
2170		10	2	80.0%	190	14	92.6%	9	2	77.8%	186	44	76.3%
2172		10	2	80.0%	186	23	87.6%	10	5	50.0%	182	40	78.0%
2173		10	0	100.0%	194	19	90.2%	10	3	70.0%	194	46	76.3%
2190		11	0	100.0%	199	14	93.0%	11	0	100.0%	196	16	91.8%
2193		10	0	100.0%	195	25	87.2%	10	3	70.0%	188	66	64.9%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2121	WAS	44	PTI	26	ENG	23	PHL-PHL	AM	Air / Brake, 2025, PARKING BREAK ISSUE. RECIEVING A FAULT.
2124	NYP	16	DCS	12	DCS	12	XNY-BAL	AM	T.O.L, Milepost, 127, ., TOL over the 32 switch reverse
2151	WAS	54	TRS	47	TRS	39	NYP-NWK	AM	Trespasser strike, Other, NYP-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER
2153	WAS	27	PET	12	PET	8	XCY-XHM	AM	Scheduled in track usage program, Other, XMO-XHM, OPR 4 TRK A/C ET INSPECTION ON 3 TRK
2154	BOS	58	TRS	55	TRS	55	XCY-NWK	AM	Trespasser strike, Other, XUN-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER
2163	WAS	27	CTI	24	DMW	7	NHV-STM	MN	Waiting for MW clearance Milepost, 47.6, 46.5
2166	BOS	44	CAR	48	CAR	28	NYP-XSH	AM	Electrical failure, 3217, STOPPED AT MP17 WITH GROUND DETECTOR FAULT IN CAR 3217
2167	WAS	18	DCS	19	DCS	19	BWI-XNY	AM	T.O.L, Milepost, 127, ., TOL over the 32 switch reverse
67	NPN	32	CTI	17	SYS	11	RVR-RVM	CS	Efficiency test involving Amtrak officer(s) Joint rules test Amtrak/CSX, Milepost, 1.3, 1.3
85	RVM	31	DCS	25	DCS	25	BWI-NCR	AM	T.O.L, Milepost, 127, ., TOL over the 32 switch reverse
110	NYP	193	SVS	131	SVS	131	PHL-PHL	AM	Switch private or office cars
112	NYP	24	TRS	33	TRS	24	NWK-NYP	AM	Trespasser strike, Other, NWK-NYP, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER
119	WAS	39	ITI	49	ITI	49	NYP-NYP	AM	Service, turn, or wye train, 130, LATE TURN OFF AM130
129	WAS	24	DCS	20	DCS	20	BWI-XNY	AM	T.O.L, Milepost, 127, ., TOL over the 32 switch reverse
130	NYP	61	TRS	68	TRS	52	MET-NWK	AM	Trespasser strike, Other, XUN-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER
137	WAS	19	ITI	26	ITI	26	BOS-BOS	AM	Service, turn, or wye train, 190, Dp BOS late a/c late turn of 190
151	RNK	17	ENG	32	ENG	21	WAS-WAS	AM	PTC - On Board Cab Signal or PTC Failure 314

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
170	BOS	80	TRS	73	TRS	73	MET-NWK	AM	Trespasser strike, Other, MET-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER
172	BOS	70	TRS	40	TRS	20	NWK-NYP	AM	Trespasser strike, Other, NWK-NYP, OPR 4 TRK A/C ET INSPECTION ON 3 TRK
173	WAS	40	DCS	25	DCS	21	BWI-XNY	AM	T.O.L, Milepost, 127, ., TOL over the 32 switch reverse
175	WAS	72	WTR	31	WTR	26	XPV-BAL	AM	Flood / washout, Control Point, .
179	PHL	140	SVS	122	SVS	122	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Dp Bos late a/c engine swap
185	WAS	143	ITI	153	ITI	153	NYP-NYP	AM	Service, turn, or wye train, 110, LATE TURN OFF AM110
190	BOS	64	SVS	71	SVS	71	PHL-PHL	AM	Switch private or office cars, Late equipment a/c shopped car
474	SPG	22	DMW	12	DMW	12	WFD-MDN	AM	Held for or routed around MW work or equipment, Milepost w/Letters, WFD, MDN, Meet, Held at Holt for AM475 to clear single track WFD-MDN
479	NHV	20	DMW	10	DMW	10	WND-HFD	AM	Held for or routed around MW work or equipment, Milepost w/Letters, WND, HFD, Held at Hart for CTRail CT4466 to clear single track WND-HFD
80	NYP	64	PTI	60	FTI	33	QAN-ALX	CS	Follow M418, Other, Arkendale
600	NYP	58	TRS	67	TRS	53	TRE-NWK	AM	Trespasser strike, Other, XUN-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER
620	PHL	30	CTP	25	CTP	25	EXT-PAO	AM	Delay due to mechanical problems on a Commuter train, DISABLED SE9547 AT PAOLI STATION.
622	PHL	14	CTP	10	CTP	10	HAR-HAR	AM	Delay due to mechanical problems on a Commuter train, DISABLED SE9547 AT PAOLI STATION.
640	NYP	28	TRS	28	TRS	28	TRE-NWK	AM	Trespasser strike, Other, XLT-NWK, SINGLE TRACKING ON 4 TRK A/C NJ3924 STRUCK TRESPASSER AT HUNTER
642	NYP	38	TRS	45	TRS	45	TRE-NWK	AM	Trespasser strike, Other, XLT-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/16/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
643	HAR	45	TRS	34	TRS	34	NYP-NWK	AM	Trespasser strike, Other, NYP-NWK, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER	
644	NYP	34	TRS	37	TRS	27	NWK-NYP	AM	Trespasser strike, Other, NWK-NYP, CONGESTION A/C NJ3924 STRUCK TRESPASSER AT HUNTER	
645	HAR	11	DCS	11	DCS	11	NYP-NWK	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), N/A, Other, ERIE, C&S HAS LOCAL CONTROL AT ERIE	
655	HAR	53	CTP	66	CTP	48	PHL-PAO	AM	Delay due to mechanical problems on a Commuter train, DELAYED A/C DISABLED SE9547 AT PAOLI.	
687	BRK	24	PTI	14	PTI	14	DOV-WEM	CS	Meet Dispatcher took 688 into wells station first. 688 departed late out of station, 688, Control Point, willie	
1689	BRK	15	FTI	20	FTI	20	EXR-DHM	CS	Meet 427, Other, rockingham	
64	ALB	43	FTI	37	FTI	31	SYR-ROM	CS	Meet Control Point, 290, csx	
68	NYP	61	CUI	42	CUI	42	RSP-RSP	DH	United States	
232	NYP	28	SVS	27	SVS	27	ALB-ALB	AM	Unplanned Wye Control Point, 142	
281	NFL	29	PTI	33	PTI	27	ROM-SYR	CS	Meet 64, Milepost, 270, 270	
283	NFL	27	FTI	26	FTI	18	ROC-BUF	CS	Follow csx, Milepost, 388, 420	
290	NYP	35	DSR	39	DSR	21	BTN-VRN	VR	Per bulletin Milepost, 112, 111, 110, main, Milepost, 111, 105.68, 25, main, Milepost, 105.68, 105.19, 15, main, Milepost, 105.19, 102.36, 50, main, Milepost, 102.36, 102.36, 25, main, Milepost, 102.36, 100.63, 50, main	
291	BTN	59	DSR	35	PTI	10	FED-XWH	DH	Meet Run via ssdg at Fort ed due to meet with Amtrak 68, 68, Control Point, 56	
42	NYP	22	ENG	27	ENG	27	PHL-PHL	AM	Other electrical failure, 636	
43	PGH	30	FTI	19	FTI	18	TYR-ALT	NS	Follow NS 25P, Milepost, 222.2, 234.5	
73	CLT	40	PTI	26	PTI	26	RGH-CYN	NS	Meet #Ant40, #Amt80, Control Point, Fetner	
76	RGH	21	PTI	22	PTI	13	GRO-DNC	NS	Meet 79, Siding, funston	
89	SAV	51	FTI	61	FTI	28	FAY-DIL	CS	Follow Milepost w/Letters, a218.8, a262.2, i195	
98	NYP	208	POL	270	POL	270	MIA-HOL	FL	RR blocked by trespasser or vehicle strike by another train TriRail P301	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
55	WAS	47	DSR	42	DSR	30	SAB-ESX	NE	Per bulletin Milepost, 126, 128, 25, Track, Milepost, 121, 126, 10, Track, Milepost, 114.39, 114.59, 25, Track
56	SAB	179	DMW	97	DMW	82	ESX-SAB	NE	Waiting for MW clearance Waiting for truck crew to clear up, Milepost, 115, 115
40	CHI	198	FTI	116	WTR	28	TPA-LAK	CS	Flash flood warning Flash flood warning in effect on entire Lakeland Sub., Other, Lakeland Sub.
41	MIA	76	DSR	59	WTR	45	PTB-RMT	CS	Flash flood warning Other, North End
5	EMY	65	FTI	142	FTI	41	SLC-SLC	UP	Meet UP8799, Milepost, 745.0, 745.0, light power
6	CHI	383	DSR	198	SVS	90	EMY-EMY	UP	Water, commissary, toilet/trash dumping No coach cleaners work at night now, so Am crew has to get everything done, Control Point, Oakland yard
521	SJC	65	MBO	68	MBO	68	SUI-SUI	UP	Issues with bridge, could not be confirmed locked. Bridge, Suisun
523	SJC	14	DCS	16	DCS	9	SUI-MTZ	UP	Drawbridge stuck open Control Point, rv034
526	SAC	41	MBO	50	MBO	50	MTZ-SUI	UP	For maritime traffic Control Point, Vista
529	SJC	11	PTI	11	PTI	6	OKJ-OAC	UP	Wait for station track AMT 528, Other, OAC
531	OKJ	19	MBO	21	MBO	21	SUI-MTZ	UP	For maritime traffic Control Point, bencia
50	NYP	145	CAR	112	CAR	84	CHI-CHI	AM	Set out defective car 90250, All equipment going to beech grove cut off
503	EUG	31	WTR	25	PTI	11	CTL-KEL	BN	Meet amtk 502, Control Point, ostrander
504	SEA	148	FTI	128	FTI	113	SLM-ORC	UP	Meet UP7005 Stalled on the hill at Hito. Lots of troubleshooting-ended up shoving back to flat ground and taking another run at it., UP8030, Siding, Hito
507	EUG	77	DCS	27	DCS	19	KEL-VAN	BN	Red Signal Talked by Red. Restricted speed for 3.1 miles., Milepost, 102.6, 105.7
508	SEA	77	DCS	41	DCS	41	EUG-ALY	UP	CTC system failure Milepost, 667.6, 677.7
516	VAC	24	MBO	21	MBO	21	XF2-X1J	BN	For maritime traffic Bridge, Fraser
518	VAC	56	MBO	33	MBO	33	XF2-X1J	BN	For maritime traffic Bridge, Fraser
59	NOL	106	ENG	92	ENG	92	CHI-CHI	AM	Turn and service 837 from train #4 837
8	CHI	64	FTI	83	SYS	41	EVR-XEN	BN	Tunnel flush
821	FTW	44	DSR	65	DSR	26	ADM-GLE	BN	Per bulletin Milepost, 450, 413.6, 40, m

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	60	FTI	45	DSR	24	GLE-ADM	BN	Per bulletin Milepost, 413.6, 462.0, 40, m, Milepost, 414.6, 415.1, 60, m, Milepost, 423.6, 424.2, 50, m, Milepost, 426.3, 426.4, 50, m
336	CHI	12	ENG	5	ENG	5	MKE-MKE	CP	Failure of diesel engine ID4608
337	MKE	29	DMW	27	DMW	19	SVT-MKA	CP	Foreman did not remove yellow red flag in mt 1 follow rule 5.4.4b Milepost, 78.3, 78.5
341	MKE	18	ITI	14	ITI	14	CHI-CHI	AM	Service, turn, or wye train 1340
364	PTH	20	FTI	39	FTI	14	BTL-LNS	CC	Cross Traffic Unknown CSX, Control Point, Trowbridge
365	CHI	34	PTI	41	PTI	34	XH6-XTF	NS	Follow amt40, Milepost, 507, 521
370	GRR	18	WTR	15	WTR	15	XPI-SJM	CS	High winds Milepost, 136.4, 109.0
581	LAX	47	CTI	52	CTI	18	OSD-X98	SC	Follow metrolink, Control Point, Capistrano
586	SAN	23	CTI	17	DCS	10	LAX-XRJ	BN	Restrictive signal(s) from unknown cause All trains in vicinity had Stop indications, Stop, Control Point, san pedro jct
761	SLO	22	DCS	26	DCS	13	VNC-NRG	SC	Restrictive signal(s) from known wayside signal failure Stop, Restricting, Control Point, raymer
702	BFD	50	FTI	29	RTE	21	FNO-HNF	BN	Dispatcher hold Met BNSF 8255W, Siding, conejo
710	BFD	148	ITI	100	ITI	100	EMY-EMY	UP	Last minute loco swap with 712s equipment, 2108/90218 719
711	OKJ	27	DSR	32	DSR	27	FNO-MDR	BN	Per bulletin Milepost, 1003.5, 1009.2, 15, MT
712	BFD	33	PTI	32	SVS	29	OKJ-OKJ	UP	Routine inspections Late release from YARD due to swapping locomotives
713	OKJ	28	DSR	20	DSR	14	FNO-MDR	BN	Per bulletin Milepost, 1003.5, 1009.7, 25, Main Track
714	BFD	72	SVS	45	SVS	45	OKJ-OKJ	UP	Water, commissary, toilet/trash dumping Took over 711 equipment. Regular maintenance was done, Other, OMF
715	OKJ	31	PTI	34	PTI	23	HNF-FNO	BN	Meet 710, 712, Control Point, sunmaid
716	BFD	72	PTI	40	SVS	35	OKJ-OKJ	UP	Fuel Other, OMF
717	OKJ	41	ENG	47	ENG	47	BFD-WAC	BN	HEP Swapped to run hep off the 2005, C2012
719	OKJ	123	ITI	53	ITI	53	BFD-BFD	BN	Amtrak710 was late arriving into Bakersfield. Their equipment turns equipment turns as Amtrak719 710

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/16/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
3	LAX	74	DSR	127	DCS	40	WLO-FLG	BN	Restrictive signal(s) from unknown cause Stopped to inspect high water bridge at mp 290.5, Stop, Approach, Restricting, Milepost, 285.7, 290.8	
4	CHI	269	FTI	151	FTI	80	GBB-PCT	BN	Meet Also AMTK 5, bnsf 8599, Control Point, buda	
1	LAX	928	FTI	694	FTI	295	SND-ALP	UP	Blocked from station track Hold at Strobel for up 5950w repairing cars at alpine tx, up5950, Control Point, STROBEL	
22	CHI	301	CON	235	CON	235	SAS-SAS	UP	Hold for connecting train Train 2 arrival at 9:45am Cut off transfer cars Mech inspection Respot train 22 on track 3 was blocked by Train 2 Baggage passenger loading, 2	
300	CHI	29	FTI	27	FTI	16	CRV-SPI	UP	Meet Held in siding, UP 5756, Siding, Auburn	
302	CHI	71	FTI	43	FTI	27	BNL-PON	UP	Meet UP 7258, Siding, Ballard	
305	STL	70	ADA	28	PTI	28	DWT-PON	UP	Meet 318, Siding, odell	
307	STL	33	FTI	54	FTI	28	XQT-STL	TR	Cross Traffic NA, Milepost w/Letters, Gratiot, Gratiot	
383	QCY	17	CTI	16	FTI	8	NPV-PLO	BN	Meet BNSF, Control Point, Montgomery	
391	CDL	40	CTI	31	CTI	31	X9R-XCS	CT	Cross Traffic metra, Control Point, 16th street	
393	CDL	109	DBS	54	DBS	54	RTL-CHM	CC	Debris strike Tree, Milepost, 119.8, 119.8	
318	CHI	87	FTI	44	FTI	20	BNL-PON	UP	Follow UP 7897, Siding, Pontiac	
319	KCY	28	DSR	23	ADA	12	STL-STL	TR	Mobility Impaired Station called at 3:06, saying they had meet and assists for our train, they never brought the person down and she showed up on her own.	
1333	MSP	29	DSR	54	DSR	16	MKE-CBS	CP	Per bulletin Milepost, 146.8, 150.5, 10, 2	
1340	CHI	39	DSR	48	DSR	17	CBS-MKE	CP	Per bulletin Milepost, 150, 146.8, 10, m2	

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/16/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	622	07/16	10	10	Delay due to mechanical problems on a Commuter train, DISABLED SE9547 AT PAOLI STATION.
PHL	110	07/16	131	131	Switch private or office cars
PHL	190	07/16	71	71	Switch private or office cars, Late equipment a/c shopped car
PHL	605	07/16	5	5	PTC - Stop Bypass Permission Required, Control Point, .
WAS	2124	07/16	15		
ALB	232	07/16	27	27	Unplanned Wye Control Point, 142
BOS	137	07/16	26	26	Service, turn, or wye train, 190, Dp BOS late a/c late turn of 190
BOS	175	07/16	21	21	Service, turn, or wye train, 170, Depart BOS late a/c short turn equipment from late arrival of AM170
NYP	79	07/16	9	9	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	97	07/16	9	9	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE CATERING
NYP	119	07/16	49	49	Service, turn, or wye train, 130, LATE TURN OFF AM130
NYP	133	07/16	6	6	Passenger and/or baggage, HEAVY LOADING
NYP	185	07/16	153	153	Service, turn, or wye train, 110, LATE TURN OFF AM110
NYP	243	07/16	53	53	Power switch failure, Other, XHR-NYP, DELAYED DUE TO 749SW FAILURE , TRAIN WAS RE-ROUTED FROM LINE 1 TO THROUGH THE LOOP TO LINE 3, THEN SWUNG TO A LOWER TRACK IN NYP STATION.
NYP	2107	07/16	6	6	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
WEM	688	07/16	18	18	Wheelchair Bus wheelchair lift broke, had to wait for another bus
CHI	7	07/16	36	36	???? 333
CHI	41	07/16	33	3	Meet 307, Control Point, track 24
CHI	41	07/16	33	30	Train backed down @638. Departed @710
CHI	48	07/16	5	5	Hold for connecting train 4820 sleeper transferring needed a lift. Sent down after 9:25p.m., 318
CHI	59	07/16	74	74	Picked up extra engine 53
CHI	341	07/16	14	14	Service, turn, or wye train 1340
MKE	336	07/16	5	5	Failure of diesel engine ID4608
SEA	8	07/16	14	14	Heat / AC 32083, Had to back into yard for mechanical to work on air conditioning was running hot was working when left 14 minute delay
SEA	516	07/16	9	9	Extra long job briefing and train being located at the south end of the yard. Sounder traffic between yard and King Street. Arrived at station at 815 am Loaded 2 floats of checked luggage and all passengers.

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/16/2025

Terminal	Train	Date	Late	Delay	Cause
STL	311	07/16	4	4	Crew rest
BFD	719	07/16	53	53	Amtrak710 was late arriving into Bakersfield. Their equipment turns equipment turns as Amtrak719 710
EMY	6	07/16	67	67	Same story, all pm coach cleaners were laid off. And other mechanical workers. So nothing happens to the train until the AM, so we will always be delayed until further notice 39026, 38004, 34204, 33022, 33022, 32044, 32011, 31039, 32011, 31033
LAX	2	07/16	15	15	Passenger and/or baggage Held in Los Angeles Union Station for Baggage Department to finish they did not show up until three minutes after scheduled departure Per Station Services
OKJ	534	07/16	4	4	Dispatcher hold Held for 716 that was late, Other, OKJ station
OKJ	710	07/16	(Trn Cxld)		Engine Failure
OKJ	712	07/16	29	29	Routine inspections Late release from YARD due to swapping locomotives
OKJ	714	07/16	45	45	Water, commissary, toilet/trash dumping Took over 711 equipment. Regular maintenance was done, Other, OMF
OKJ	716	07/16	43	8	Door C8001, Breaker kept tripping and unable too get doors closed in car. After troubleshooting, crew figured out that the key station is bad. Car was reported with same problem 2 weeks ago but mechanical was unable to figure out the problem
OKJ	716	07/16	43	35	Fuel Other, OMF
SAN	593	07/16	9	9	Person pulling emergency cord Person pulling emergency fuel shut off on loco CDTX2109

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.8	91.7	95.2	341	4
CDOT	95.0	100	95.9	96.4	20	0
MARC	95.0	85.7	79.5	83.5	56	8
SEPTA	95.0	95.1	96.4	96.2	206	10
NJT-NED	95.0	78.3	90.8	95.2	369	80
NJT-SED	95.0	95.8	97.9	91.2	24	1

Operating Highlights

Train 20(16) North of Anniston, AL - Freight Train Interference

17JUL25: Train 20(16) was delayed 33 miles north of Anniston, AL at MP703.1 on the Norfolk Southern East End Subdivision, due to meeting freight unit NS156-15. Train was also delayed due to unknown freight cross-traffic at MP139.8.

Train	Delay	Comment
20 (16)	46"	

Train 52(16) South of Florence, SC - Freight Train Interference

17JUL25: Train 52(16) was delayed 13.4 miles south of Florence, SC at New Hope/MP A306.1 on the CSX Charleston Subdivision. due to CSX single-tracking though the Florence station, 52(16) had to wait for 53(16), I031-16 and I137-16. to clear, prior to proceeding north to Florence.

Train	Delay	Comment
52 (16)	58"	
52 (16)	15"	Meeting 53 (16)

Train 243(16) New York, NY - Power Switch Failure

17JUL25: Train 243(16) was delayed departing New York, NY due to the 749 power switch failing. Train 243(16) was re-routed from Line 1 to through the Loop to Line 3, then to a lower track in NYP station, prior to departure.

Train	Delay	Comment
243 (16)	53"	

PW Line High Water - North of Aberdeen, MD

17JUL25: Trains 175(16) and 66(16) were delayed North of Aberdeen, MD on the Amtrak PW Line due to high water reported above the rails between Oak/MP62.9 and Grace/MP61.5 and also between Perry/MP59.5 and Prince/MP57.3.

Train	Delay	Comment
66 (16)	1'04"	
175 (16)	31"	

Train 56(16) North of Essex Junction-Burlington, VT - Temporary Speed Restrictions

17JUL25:Train 56(16) was delayed 11 miles north of Essex Junction-Burlington, VT on the NECR Palmer Subdivision due to temporary speed restrictions in place between MP119 and MP128 operating 10 MPH.

Train	Delay	Comment
56(16)	56"	

Train 655(16) Paoli, PA - Disabled SE9547

16JUL25: Train 655(16) was delayed departing Paoli, PA/MP19.9 on the Amtrak PH Line due to disabled SEPTA SE9547, that experienced multiple penalties, and was unable to take power while trying to depart Paoli. Train 655(16) was able to fit into the station, then had to reverse and cross-over to get around the disabled SEPTA train. Train 620(16) and 622(16) were also delayed due to this. SEPTA SE9547 was rescued into Frazer yard at 1012P-ET.

Train	Delay	Comment
655(16)	1'05"	
622(16)	10"	
620(16)	25"	

PW Line T.O.L. - North of New Carrollton, MD

16JUL25: At 6:20PM, CETC reported a TOL at Carroll/MP127, on the Amtrak PW Line, with the 32 switch locked reverse. C&S responded to the location. At xxxPM, C&S was able to clear the TOL. Multiple trains were delayed through the area as a result.

Train	Delay	Comment
97(16)	1'06"	
85(16)	25"	
2167(16)	19"	
173(16)	21"	
129(16)	20"	
192(16)	03"	
138(16)	04"	
2124(16)	12"	
80(16)	14"	
196(16)	10"	
4 MARC's	08" - 1'16"	

Train 64(16) East of Syracuse, NY - Freight Train Interference

16JUL25: Train 64(16) held 0.7 miles east of Syracuse, NY/MP291.4, on the CSX Syracuse Terminal Subdivision, at MP290.7 meeting a CSX freight train.

Train	Delay	Comment
64(16)	39"	

Train 2166(16) East of New York, NY - Car Failure

17JUL25: Train 2166(16) TS1, PC2004, PC2018, was delayed just west of Manor at MP17 on the Amtrak NYS Line due to a ground detector fault on car 3217. Per rule, they were restricted to 20mph then were able to clear the fault and proceed at maximum C-speeds, accumulating additional delay.

Train	Delay	Comment
2166(16)	28"	ADTL 20" NHV-BOS

Train 68(16) South of St-Lambert, QC - Heat Orders

16JUL25: Train 68(16) was delayed starting 2.2 miles south of St-Lambert, QC/MP70.3, on the CNRR Rouses Point Subdivision, due to 25MPH heat orders between Southwark/MP42.7 and Rouses Point/MP0.0. Additional delay at the Rouses Point station waiting on customs to finish clearing the train.

Train	Delay	Comment
68(16)	41"	Heat Orders
68(16)	42"	RSP - Customs

CSX Heat Orders

16JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Alleghany, Kanawha, Mohawk, New River, and Syracuse Terminal.

Train	Delay	Comment
48(15)	16"	
64(16)	31"	
281(16)	14"	
283(16)	25"	
683(16)	05"	
686(16)	07"	
687(16)	06"	

NJT 3924 Trespasser Strike - West of Newark, NJ

16JUL25: At 8:11AM, NJT 3924, CC/7044 and 8 Cars, reported striking a trespasser on the No. 2 track within the Hunter Interlocking limits at MP10.2. Exactly 1.4 miles west of the Newark, NJ station/MP8.8, on the Amtrak NYP Line. This is located in Newark NJ in Essex County. Amtrak Road Foreman Falkenstein and three members of the Amtrak Police Department responded. Local police, emergency services, medical examiner and members of the NJT transportation team also responded. The strike was confirmed fatal with the remains in the area of tracks 2 and 3. At 8:24AM, NJT police requested a hold on No. 1, 2, and 3 tracks. At 8:44AM, NJT police okayed the No. 1 track at restricted speed. During this time, Amtrak and New Jersey Transit trains operated through the area on Tracks 1 and 4 at restricted speed while the investigation was underway. At 10:11AM, NJT police reported all personnel were clear and all holds released with no speed restrictions. Normal operations resumed at this time.

National Response Center Number: 1437046

Train	Delay	Comment
190(16)	11"	
2152(16)	11"	
640(16)	28"	
141(16)	32"	
170(16)	1'13"	
642(16)	45"	
2151(16)	47"	
643(34)	34"	
2154(16)	55"	
110(16)	47"	
600(16)	1'07"	
172(16)	40"	
112(16)	33"	
130(16)	1'08"	
119(16)	49"	ITD NYP - Turn of 130(16)
644(16)	37"	
56(16)	21"	
175(16)	21"	ITD BOS - Turn of 170(16)
177(16)	05"	ITD BOS - Turn off 172
53 NJT Trains	09" - 1'39"	

Train 67(15) Washington, DC - Car Failure

16JUL25: Train 67(15) was delayed at Washington Union Station, on the Amtrak WT Line, replacing Business Class / Café car 48156 with car 48181 due to an infestation. 67(15) was further delayed due to a coupling issue.

Train	Delay	Comment
67(15)	31"	

Train 110(16) Philadelphia, PA - Engine Failure

16JUL25: Train 110(16) was delayed departing initial terminal of Philadelphia, PA/MP1.5, on the Amtrak PW Line, originally due to a late turn of equipment from train 179(15). Train 179(15) arrived to Philadelphia at 3:59AM EDT, 2 hours and 20 minutes late. Train 110(16) was further delayed due to engine 626 being shopped for failed self initialization and replaced with engine 643.

Train 185(16) was delayed departing New York, NY as a result of a late turn of Train 110(16)'s equipment that arrived at 11:20AM, 3 hours and 13 minutes late.

Train	Delay	Comment
110(16)	2'11"	
185(16)	2'33"	ITD NYP

Train 190(16) Philadelphia, PA - Car Failure

16JUL25: Train 190(16) was delayed departing Philadelphia, PA/MP1.5, on the Amtrak PW Line, after C/82986 was shopped for door bypass issues and replaced with C/82599.

Train 137(16) was delayed departing Boston, MA as a result of a late turn of Train 190(16)'s equipment that arrived at 1:10PM, 1 hours and 04 minutes late.

Train	Delay	Comment
190(16)	1'11"	
137(16)	26"	ITD BOS

Maintenance of Way Highlights

Train 56(16) North of Essex Junction-Burlington, VT - M of W Work

17JUL25: Train 56(16) was delayed 6 miles north of Essex Junction-Burlington, VT at MP115 on the NECR Roxbury Subdivision, due to waiting for a maintenance of way truck crew to clear ahead.

Train	Delay	Comment
56(16)	1'22"	

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

· Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

· Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

· Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

· Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

· Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

· Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

· Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

· Bus 3470 will provide alternate transportation between HFD and SPG

· Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

· Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

· Deadhead Train 426 will turn for Train 471 at HFD

· Train 470 will turn for Train 473 at HFD

WBS#: B.TR.100151.0738

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
97	ORL	1	WPB	N/A
2122	NYP	2	NCL	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 90(16) Passenger Denied Travel at Florence, South Carolina – Improper Behavior

16JUL25, Passenger on PNR 267BB3, traveling from Florence, SC to Newark, NJ was reportedly denied travel by the conductor after she got into a verbal altercation with the assistant conductor and the conductor. Amtrak Police notified.

Delay: 90 (16) 05"

Train 50(15) Passenger Removal at Hinton, West Virginia–Other

16JUL25, Passenger on PNR Unknown, traveling from Chicago, IL to New York, NY was removed from the train by Hinton PD. The passenger boarded the train without a ticket gave a fake name and refused to purchase a ticket. Amtrak Police notified.

Delay: 50 (15) 3"

Western Region

Operating Highlights

Train 6(14) Mendota, IL - Freight Train Interference

17JUL25: Train 6(14) was delayed 10 miles north of Mendota, IL, on BNSF Mendota subdivision, due to meeting train 383(16). These trains met due to 2 freight trains being tied down on main track 2.

Train	Delay	Comment
6(14)	50"	

Train 41(16) Chicago, IL - Initial Terminal Delay

17JUL25:Train 41(16) was delayed 30 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(14), replacing a bad order locomotive, and troubleshooting two cars with inoperative toilets. As background, inbound 40(14) arrived in Chicago at 1203pm; 3 hours and 18 minutes late due to 1 hour and 57 minutes of freight train interference, 1 hour and 7 minutes of weather restrictions, 43 minutes for ADA accommodations, and 26 minutes for a maritime bridge lift. Equipment set to the yard for servicing and inspection at 135pm. There were no scheduled program moves. At 335pm, lead engine AMTK 11 was bad ordered for wheel shelling. Blue flags were dropped at 416pm and replacement locomotive AMTK 62 was added in trail at 457pm. At 545pm, mechanical reported bad order toilets on coach 25049. Due to no replacement coaches, c/25049 to deadhead inline with the passengers downgraded (coach to be added in Washington, D.C). At 610pm, mechanical reported bad ordered toilets on sleeping car 62034. Due to no replacement sleepers, c/62034 to deadhead inline with the passengers downgraded. Train 41(16) was released by mechanical at 617pm, shoved from yard at 628pm, and set in the station at 638pm with 229 passengers to board. Train 41(16) departed Chicago at 710pm; 30 minutes late.

Train 41(16) was further delayed 1 mile south of Chicago, IL , due to a traction motor fault that would not reset. The crew worked with CNOC mechanical to resolve. After cycling the power the fault was reset and train 41(16) was able to proceed.

Train	Delay	Comment
41(16)	30"	
41(16)	45"	

Train 14(16) Oakland, CA - Servicing

17JUL25: Train 14(16) was delayed at Oakland Yard/MP5.6, on UP Niles subdivision, setting out E/23 for a future Airo move.

Train	Delay	Comment
14(16)	46"	

Train 719(16) - Initial Terminal Delay

16JUL25: Train 719(16) was delayed departing Bakersfield station due to the late arrival of train 710(16) which arrived into the station at 4:25 pm 2 hours and 28 minutes late. 719(16) departed Bakersfield station at 5:05 pm 53" late.

Train	Delay	Comment
719(16)	53"	

Train 393(16) South of Rantoul, IL - Debris

16JUL25: at approximately 7:24pm-ET, train 393(16) with E/4630, 7 coaches, and 164 passengers, went into emergency on CN, Chicago subdivision after striking a tree 8 miles north of Champaign, IL, at MP120.3. There were no reported injuries of passengers or crew and HEP remained active the entire time. There was minor damage reported of the sander on the motor which was hanging low to the rail and damage to the speed sensor as well. The crew determined that the sander was still high enough above the rail to be in compliance but the speed sensor caused issues with PTC. The crew was unable to resolve the issues with PTC and it was cut out, causing the train to operate a reduced speed of 59MPH from Champaign, IL, to Carbondale, IL.

Train 59(16) was delayed departing Chicago, IL, due to adding a rescue motor to its consist to be dropped off at Carbondale, IL for train 390(17).

Train	Delay	Comment
393(16)	53"	
59(16)	1'14"	

Train 581 - Commuter Train Interference

16JUL25: Train 581(16) was delayed outside of San Juan Capistrano station MP 197.2, Orange Subdivision of the San Diego Northern Railroad. A Metrolink train was blocking the station platform while they repaired a door issue on one of their cars. Once the door issue was resolved, the Metrolink train was able to depart and train 581(16) was able to enter into the station.

Train	Delay	Comment
581(16)	35"	

Train 7(15) East of Havre, MT - Freight Train Interference

17JUL25: Train 7(15) was delayed 3 miles east of Havre, MT, on BNSF Milk River subdivision due to CN8837 blocking the route into the station. Once the freight cleared and a route was made available, train 7(15) was able to proceed.

Train	Delay	Comment
7(15)	32"	

Train 508(16) - North of Eugene, OR - Signal Problems

16JUL25: Several attempts by the dispatcher failed to remotely prove the integrity of signals 20 miles north of Eugene at Alford, MP 667.6, Brooklyn Subdivision of the Union Pacific Railroad. This failure required The Engineer to verbally request permission to proceed past the first signal. The Engineer was then required to maintain verbal contact with the dispatcher, operating the train cautiously until within sight of the next verified remote signal, which was 10 miles away. Once clear of the affected area the train was able to continue at authorized track speed to Albany.

Train	Delay	Comment
508(16)	41"	

Train 717(16) - Engine Failure

16JUL25: Train 717(16) stopped shortly after departing Bakersfield station when locomotive C/2012 ceased providing electrical load. The train came to a halt at Jasper milepost 891.0, Bakersfield Subdivision, Burlington Northern Santa Fe Railway. The crew was advised to swap head end power from C/2012 to C/2005. Once this was complete, train 717(16) was able to proceed Wasco.

Train	Delay	Comment
717(16)	47"	

Train 3(16) West of Naperville, IL - Engine Failure

16JUL25: Train 3(16), operating with Locomotive 203, Locomotive 40 and 9 cars, was delayed at MP 34.6 on the Burlington Northern Santa Fe Chicago Subdivision, 6 miles west of the Naperville, IL station, duet o trail Locomotive 40 had a locked axle alarm. With assistance from CNOC Mechanical, the crew cut out traction motor #4 and continued.

Train 3(16) was further delayed adding BNSF5173 west of Kansas City, MO, at Argentine fuel rack.

Train	Delay	Comment
3(16)	1'13"	Locked Axle/Traction Motor Cutout
3(16)	48"	Adding BNSF Motor

Train 21(16) North of Bloomington-Normal, IL - Passenger Train Interference

17JUL25: Train 21(16) was delayed 20 miles north of Bloomington-Normal, IL, on UP Joliet subdivision, due to meeting train 22(15) Control Point 95.

Train	Delay	Comment
21(16)	30"	

Train 4(14) West of Princeton, IL - Passenger Train Interference

16JUL25: Train 4(14) was delayed at Buda / MP 116.7 on the Burlington Northern Santa Fe Mendota Subdivision, 13 miles west of the Princeton, IL station, meeting ECXNAM0-04 and Train 5(16).

Train	Delay	Comment
4(14)	1'20"	

Train 7(16) Chicago, IL - Engine Failure

17JUL25: Train 7(16) was delayed departing Chicago account a late release of E/333 due to a WiTronix update. E/333 was released from the diesel pit at 137PM, after waiting for a WiTronix Violet View software update. Once complete, E/333 was released at 137PM. The crew was on board shortly after, and departed the diesel pit at 203PM. After respotting the train to be in the clear on the North end of Track 9, Train 7(16) was given to mechanical and flagged in at 231PM. Mechanical released Train 7(16) at 253PM. Train 7(16) set in CUS at 303PM. Boarding began at 318PM and Train 7(16) departed Chicago at 341PM, 34" late.

Train	Delay	Comment
7(16)	34"	

Train 716(16) Oakland, CA - Servicing

16JUL25: Train 716(16) was delayed departing the Oakland Mechanical facility while waiting for the equipment to be fueled. Once fueling was complete, the train was released to the station to board passengers.

Train	Delay	Comment
716(16)	35"	

Train 22(15)/422(13) St. Louis, MO - System

16JUL25: Train 22(15) / 422(13) was delayed departing the St. Louis, MO Gateway Station due to a program move to add the local coach Car 35005.

Train	Delay	Comment
22(15) / 422(13)	30"	

Train 714(26) Initial Terminal Oakland, CA - Late Release/Equipment Turn

16JUL25: Train 714(26) was delayed departing Oakland, MP 7.0/UPRR Martinez Subdivision, following a late yard release as a result of turning and servicing equipment off inbound Train 711(16) which arrived Oakland 27 minutes late at 10:55AM-PT. Train 714(16) departed Oakland at 12:21PM-PT.

Train	Delay	Comment
714(26)	45"	

Train 365(16) East of Chicago, IL - Passenger Train Interference

16JUL25: Train 365(16) for 40 miles between Porter, IN and the Chicago, IL Union Station on the Norfolk Southern Chicago Terminal Subdivision following Train 40(14).

Train	Delay	Comment
365(16)	41"	

Train 391(16) South of Chicago, IL - Routing

16JUL25: Train 391(16) was delayed at 16th St / MP 2.1 on the Canadian National Freeport Subdivision, 2 miles south of the Chicago, IL Union Station, waiting on the Metra dispatching to line the signal.

Train	Delay	Comment
391(16)	31"	

Train 504(16) North of Salem, OR - Freight Train Interference

16JUL25: Train 504(16) was delayed holding in the siding at Hito, MP 742.4/UPRR Brooklyn Subdivision, 24.1 miles north of Salem, waiting on UPRR freight train MPDRV16 to clear the main track there (freight was also fouling the north switch at Hito) after its locomotive stalled. Mechanical forces were dispatched to the train to assist with repairs.

Train	Delay	Comment
504(16)	1'53"	

Train 6(16) Initial Terminal Emeryville, CA - Late Release/Servicing

16JUL25: Train 6(16) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of late equipment servicing and cleaning. Train 6(16) departed Emeryville at 9:32AM-PT.

Train	Delay	Comment
6(16)	1'07"	

Train 526(16) Martinez, CA - Drawbridge Opening

16JUL25: Train 526(16) was delayed at Vista, MP 33.0/UPRR Martinez Subdivision, 1 mile east of Martinez as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass.

Train	Delay	Comment
531(16)	21"	
526(16)	50"	
521(16)	1'08"	

Train 4(15) West of Gallup, NM - Trespasser Incident

16JUL25: 8:20 a.m. (MST), Train 4(15), operating Locomotive 193, Locomotive 163 and 9 cars, stopped at MP 213.8 on the Burlington Northern Santa Fe Gallup Subdivision, 57 miles west of the Gallup, NM station, after striking a cow. The crew found and secured several separated air hoses.

Train	Delay	Comment
4(15)	25"	

Train 710(16) Originated at Emeryville, CA - Locomotive Swap/Cab Car Issue

16JUL25: Train 710(16) originated at Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of delays incurred making a locomotive swap with 712(16)'s unit. Additional delay was then incurred due to a bad-ordered bell being repaired on cab car C/90218.

Passengers boarding at Oakland were reaccommodated onto Train 526(16) to Emeryville to make the train connection.

Train 710(16) departed Emeryville at 9:56AM-PT.

Work Element WBS #B.TR.100150.5892

WBS#: B.TR.100150.5892

Train	Delay	Comment
710(16)	2'10"	Originated at EMY

Capitol Corridor Drawbridge Malfunction West of Suisun, CA

16JUL25: Several Capitol Corridor trains were delayed as a result of the Suisun Bridge, MP 32.9/UPRR Martinez Subdivision (13.9 miles west of Suisun) having lockdown and signal problems. All train traffic was stopped pending repairs by bridge and signal maintainers. Train 521(16) held at the Suisun depot/MP 48.8. Train 523(16) held at the Fairfield-Vacaville depot/MP 53.8.

Mutual aid was in-effect for passengers on BART trains from Richmond to Berryessa/North San Jose and from Richmond to San Francisco (Civic Center). Mutual Aid was also available on ACE trains between Fremont and San Jose.

The bridge reopened to traffic at approximately 6:00AM-PT.

Train	Delay	Comment
520(16)	02"	
523(16)	16"	
521(16)	1'08"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and

- Chicago.
- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
 - Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

Train 534(15) Emeryville, CA - Engine Failure

15JUL25: Train 534(15) was delayed in Oakland Yard, MP 5.8 UPRR Niles Subdivision, while waiting for mechanical to replace a shattered headlight on CDTX 2106. Once the headlight was fixed it was determined that train 534 would start out in EMY to avoid traffic building at OKJ. Train 534 departed EMY 59 minutes late.

Train 534 turns for train 547(15) in SAC and could see an Initial Departure Delay.

Train	Delay	Comment
534(15)	59"	ORIG EMY

Train 1(14)/421(13) East of Alpine, TX - Freight Train Interference

15JUL25: Train 1(14)/421(13) was delayed at Altuda/MP593, 14 miles east of Alpine, TX, on the UPRR Sanderson Subdivision, due to MEWWC-13 (UP 5950) ahead at MP603 with damaged cars from tie fire. UP 5950 cut away from rear section of train to clear tie fire leaving the rear cut on the bridge at that location. UPRR reported several damaged air hoses on cars requiring repair before recoupling to pull in the clear. UPRR mechanical, b&b and track responded to the scene. The bridge and track was inspected and okayed for service. Train 1(14)/421(13) was delayed holding for UP 5950 to repair air hoses to several cars, set out three damaged cars in Alpine siding and then couple to remainder of consist and pull in the clear. Train 1(14)/421(13) was further delayed following freight UP/5950 to Quebec Siding/MP660.9 in Valentine, TX.

Due to the late operation of train 1(14)/421(13) the following service recovery was put into effect:

- Dinner for July 15th:
- Papa John's Pizza to be delivered in El Paso, TX for the coach passengers
 - Normal traditional dining for the sleeper passengers
- Breakfast for July 16th:
- Continental breakfast items - groceries to be delivered in El Paso, TX
 - Passengers in El Paso, TX received Jimmy John's, snacks, and drinks, while awaiting train 1(14)/421(13).

16JUL25: Train 1(14)/421(13) was delayed 40 miles between Mescal / MP 1023.4 on the Union Pacific Lordsburg Subdivision and Tucson, AZ station / MP 983.9 on the Union Pacific Gila Subdivision, due to flash flood warnings and following ZG4CI-14 (UPRR 5577). Train 1(14)/421(13) was delayed at MP 975.7. Finally, Train 1(14)/421(13) was delayed at Noah / MP 775.7 on the Union Pacific Gila Subdivision, meeting ZLAMN3-16 (UPRR 8395) and ILBD1-16 (UPRR 5328).

Train	Delay	Comment
1(14)/421(13)	4'55"	
1(14)/421(13)	1'12"	FTI ALP-XVL
1(14)/421(13)	1'30"	Mescal to TUS
1(14)/421(13)	1'20"	West of TUS
1(14)/421(13)	2'21"	East of YUM

Maintenance of Way Highlights

BNSF Fallbridge Subdivision Track Work- Empire Builder 13th - 14th July

13JUL25: BNSF has scheduled trackwork for a bridge replacement on the Fallbridge Subdivision for 36 hours starting Sunday, July 13th at 7:00AM through Monday, July 14th at 7:00PM. To accommodate this infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(11Jul, 12Jul), which normally operates between Chicago (CHI) and Portland (PDX) , will terminate at Spokane (SPK).
- Train 28 (13Jul, 14Jul), which normally operates between Portland (PDX) and Chicago (CHI) , will originate at Spokane (SPK).

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between Spokane (SPK) and Portland (PDX) making all stops except Wishram (WIH).
- Bus 4028 will provide alternate transportation between Portland (PDX) and Spokane (SPK) making all stops except Wishram (WIH).

EQUIPMENT

- Equipment for Train 27(11Jul, 12Jul) will stay coupled to Train 7 at Spokane (SPK)
- Equipment for Train 28(13Jul, 14Jul) will be coupled to Train 8 departing Seattle (SEA)

WBS#: B.TR.100150.5751

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
6 (6)	DEN	155		Trucks
5 (2)	GSC	51		Strike DMG// MP372.5
7 (8)	WTN	348		Hot axle

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
3 (16)	XAR	BN5173	E/40 T/M #4 cutout//Raton pass		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 421(13) Passenger Removal at El Paso, Texas – Medical

16JUL25, Passenger on PNR 01C88C, traveling from Chicago, IL to Tucson, AZ was removed by EMS at El Paso, TX due to having dementia and being confused. She also had taken her clothes off and was disturbing the other passengers. Amtrak Police notified.

Delay: 421 (13) 17"

Train 14(15) Passenger Removal at Salem, Oregon –Improper Conduct

16JUL25, Passenger on PNR 30839B, traveling from Martinez, CA to Seattle, WA detrained before destination due being unsatisfied with conductor addressing luggage in empty seat. The passenger became aggressive and toward the conductor stating he was not getting off and to call the police. The passenger decided to get off the train once police were dispatched. Amtrak Police notified.

Delay: 14 (15) 1"

Train 591(16) Passenger Removal at Anaheim, California –Fare Evader

16JUL25, Passenger on PNR unknown, traveling from San Juan Capistrano, CA to Los Angeles, CA boarded the train without a ticket. The passenger tried to purchase a ticket onboard, but credit card declined. The passenger was asked to get off at the next stop. Amtrak Police notified.

Delay: 591(16) None

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/16/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	299	20	93%	4,614	397	91%	83,383	6,422	92%
Northeast Corridor	98%	82	6	93%	1,215	158	87%	22,400	2,391	89%
Acela	98%	24	3	88%	338	55	84%	6,253	823	87%
Northeast Regional	98%	58	3	95%	877	103	88%	16,147	1,568	90%
State Supported	98%	189	9	95%	2,960	157	95%	52,383	2,670	95%
Long Distance	98%	28	5	82%	439	82	81%	8,462	1,355	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/16/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	299	20	93%	4,614	397	91%	83,383	6,422	92%
Northeast Corridor	98%	82	6	93%	1,215	158	87%	22,400	2,391	89%
Acela	98%	24	3	88%	338	55	84%	6,253	823	87%
Northeast Regional	98%	58	3	95%	877	103	88%	16,147	1,568	90%
On Spine Northeast Regional	98%	30	1	97%	454	51	89%	8,188	829	90%
Richmond / Newport News / Norfolk	98%	12	1	92%	187	43	77%	3,367	507	85%
Roanoke	98%	4	1	75%	64	4	94%	1,150	154	87%
Springfield Shuttles	98%	12	-	100%	172	5	97%	3,442	78	98%
State Supported	98%	189	9	95%	2,960	157	95%	52,383	2,670	95%
Borealis	98%	2	-	100%	32	5	84%	563	64	89%
Capitol Corridor	98%	28	-	100%	416	13	97%	6,876	148	98%
Carolinian	98%	2	-	100%	32	4	88%	578	46	92%
Cascades	98%	14	1	93%	224	12	95%	3,925	280	93%
Downeaster	98%	8	-	100%	156	1	99%	2,744	45	98%
Empire	98%	20	1	95%	320	21	93%	6,206	321	95%
Adirondack	98%	2	-	100%	32	2	94%	578	43	93%
Berkshire Flyer	98%	-	-	100%	6	1	83%	12	3	75%
Ethan Allen Express	98%	2	-	100%	32	5	84%	578	39	93%
Maple Leaf	98%	2	-	100%	32	2	94%	578	56	90%
New York - Albany	98%	10	-	100%	154	4	97%	3,305	91	97%
New York - Niagara Falls	98%	4	1	75%	64	7	89%	1,155	89	92%
Heartland Flyer	98%	2	-	100%	28	1	96%	570	17	97%
Hiawatha	98%	12	-	100%	185	6	97%	3,298	121	96%
Illinois	98%	12	1	92%	215	15	93%	3,982	271	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	64	2	97%	1,144	45	96%
Illini / Saluki	98%	4	1	75%	64	6	91%	1,144	42	96%
Lincoln Service	98%	4	-	100%	87	7	92%	1,694	184	89%
Keystone	98%	27	-	100%	369	21	94%	6,683	409	94%
Lincoln / Missouri	98%	2	1	50%	32	9	72%	572	84	85%
Michigan	98%	10	-	100%	156	13	92%	2,760	267	90%
Blue Water	98%	2	-	100%	32	4	88%	574	86	85%
Pere Marquette	98%	2	-	100%	30	1	97%	576	26	95%
Wolverine	98%	6	-	100%	94	8	91%	1,610	155	90%
Missouri	98%	2	-	100%	30	1	97%	556	15	97%
Pacific Surfliner	98%	24	-	100%	384	6	98%	6,162	228	96%
Pennsylvanian	98%	2	1	50%	32	6	81%	578	66	89%
Piedmont	98%	8	-	100%	127	-	100%	2,296	32	99%
San Joaquins	98%	12	4	67%	190	18	91%	3,456	199	94%
Vermont	98%	2	-	100%	32	5	84%	578	57	90%
Long Distance	98%	28	5	82%	439	82	81%	8,462	1,355	84%
Auto Train	98%	2	-	100%	32	3	91%	566	96	83%
California Zephyr	98%	2	-	100%	32	11	66%	575	133	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	1		13	7	46%	245	51	79%
City Of New Orleans	98%	2	1	50%	32	5	84%	564	51	91%
Coast Starlight	98%	2	-	100%	34	1	97%	581	86	85%
Crescent	98%	2	-	100%	32	4	88%	578	68	88%
Empire Builder	98%	4	-	100%	59	7	88%	1,110	140	87%
Floridian	98%	2	1	50%	31	9	71%	488	170	65%
Lake Shore Ltd	98%	2	1	50%	32	9	72%	976	110	89%
Palmetto	98%	2	-	100%	32	2	94%	576	36	94%
Silver Meteor	98%	2	-	100%	32	6	81%	574	114	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	32	8	75%	576	145	75%
Sunset Ltd	98%	1	-	100%	14	4	71%	244	43	82%
Texas Eagle	98%	2	-	100%	32	6	81%	648	87	87%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/16/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	6	98%	4,634	113	98%	83,413	1,985	98%
Northeast Corridor	98%	82	-	100%	1,215	30	98%	22,352	628	97%
Acela	98%	24	-	100%	338	8	98%	6,255	164	97%
Northeast Regional	98%	58	-	100%	877	22	97%	16,097	464	97%
State Supported	98%	189	2	99%	2,961	45	98%	52,368	865	98%
Long Distance	98%	30	4	87%	458	38	92%	8,555	490	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/16/25											
Day			Month to Date					Year to Date			
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	6	98%		4,634	113	98%	83,413	1,985	98%
Central Division	98%	65	4	94%		1,059	49	95%	19,098	656	97%
Northeast Division	98%	96	-	100%		1,470	25	98%	27,486	639	98%
Southeast Division	98%	69	-	100%		1,015	25	98%	18,445	433	98%
Southwest Division	98%	71	2	97%		1,090	14	99%	18,384	257	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/16/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	6	98%	4,634	113	98%	83,413	1,985	98%
Central Division	98%	65	4	94%	1,059	49	95%	19,098	656	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	37	-	100%	580	2	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	26	2	92%	427	37	91%	7,703	424	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	32	-	100%	556	3	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	15	-	100%	288	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	31	-	100%	560	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	1	83%	93	3	97%	1,656	12	99%
MSP	98%	1	-	100%	16	1	94%	277	7	97%
PDX	98%	5	-	100%	76	1	99%	1,388	36	97%
PNT	98%	3	-	100%	47	-	100%	794	7	99%
PTH	98%	1	-	100%	16	-	100%	287	6	98%
QCY	98%	2	-	100%	30	-	100%	560	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	1	88%	129	6	95%	2,256	119	95%
SPK	98%	1	-	100%	16	-	100%	297	2	99%
STL	98%	3	-	100%	58	1	98%	1,135	17	99%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	32	-	100%	553	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	96	-	100%	1,470	25	98%	27,486	639	98%
ALB	98%	7	-	100%	112	-	100%	2,021	25	99%
BON	98%	4	-	100%	78	-	100%	1,342	3	100%
BOS	98%	19	-	100%	284	5	98%	5,401	127	98%
BRK	98%	2	-	100%	51	-	100%	1,312	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	16	-	100%	287	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	29	-	100%	556	-	100%
HFD	98%	2	-	100%	22	-	100%	168	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	16	1	94%	287	6	98%
NFL	98%	2	-	100%	32	-	100%	578	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	75	-	100%	1,482	35	98%
NYP	98%	42	-	100%	618	18	97%	11,612	403	97%
POR	98%	-	-	100%	24	-	100%	24	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	14	-	100%	285	1	100%
SPG	98%	5	-	100%	76	1	99%	1,772	20	99%
TWO	98%	1	-	100%	16	-	100%	286	-	100%
WEM	98%	2	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	69	-	100%	1,015	25	98%	18,445	433	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	77	1	99%	1,431	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/16/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	6	98%	4,634	113	98%	83,413	1,985	98%
Southeast Division	98%	69	-	100%	1,015	25	98%	18,445	433	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	178	2	99%	3,123	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	16	-	100%	283	11	96%
MIA	98%	2	-	100%	31	1	97%	556	29	95%
NFK	98%	3	-	100%	45	1	98%	795	4	99%
NOL	98%	3	-	100%	34	1	97%	641	21	97%
NPN	98%	2	-	100%	32	1	97%	551	4	99%
PGH	98%	1	-	100%	16	-	100%	288	3	99%
PHL	98%	5	-	100%	68	3	96%	1,234	36	97%
RGH	98%	4	-	100%	56	-	100%	1,159	5	100%
RNK	98%	2	-	100%	29	-	100%	546	8	99%
RVM	98%	1	-	100%	16	-	100%	280	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	14	-	100%	270	-	100%
SFA	98%	1	-	100%	16	-	100%	283	18	94%
WAS	98%	25	-	100%	377	15	96%	6,852	262	96%
Southwest Division	98%	71	2	97%	1,090	14	99%	18,384	257	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	16	-	100%	289	-	100%
BFD	98%	6	-	100%	94	-	100%	1,717	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	1		16	3	81%	296	23	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	15	-	100%	321	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	48	-	100%	844	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	10	-	100%	151	1	99%	2,210	63	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	13	-	100%	284	-	100%
OKJ	98%	12	1	92%	176	6	97%	3,029	67	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	209	2	99%	3,440	14	100%
SAN	98%	12	-	100%	190	1	99%	2,612	23	99%
SAS	98%	1	-	100%	16	1	94%	285	3	99%
SJC	98%	7	-	100%	111	-	100%	1,851	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	32	-	100%	565	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	2	-	100%	49	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DA.. 7/16/2025 12:00..	Diesel L ocomoti ve	High Speed Trainset		Amfleet I		Caltrans Locomo tive	Cab Car	Electric Locomo tives	Superlin er II	Californi a Cars (Caltran..	Grand Total
	ENG	ENG	CAR	CAR	CCR	ENG	CCR	ENG	CAR	CAR	
Loading Problems	85										85
Electrical Problems			48				4	30			82
HEP Problems	11					47					58
Support Bearing F..	45										45
ITCS Problem	32										32
Horn/Bell Problems							30				30
Traction Motor Pro..	25										25
Door Problems				14						10	24
I-ETMS Problem	24										24
Hand/Parking Brak..		23									23
Car Hot: Air Condi..				10					10		20
480V Trainline Pro..				19							19
Engine Dead/Shut ..	12										12
Computer Fault	11										11
Cab Signal Failure	10										10
Air/Brake Problems	9										9
Auxiliary Faults	6										6
Refrigeration/Free..					4						4
Tilt System Proble..			4								4
MCB Tripping		3									3
Toilets Inoperative									3		3
Grand Total	270	26	52	43	4	47	34	30	13	10	529