



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, July 18, 2025

Rules:1-50



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/17/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/17/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	4,916	616	87.5%	83,623	8,285	90.1%
Central Division	91.5%	66	8	87.9%	1,123	129	88.5%	19,152	1,869	90.2%
Northeast Division	95.0%	96	12	87.5%	1,550	222	85.7%	27,505	2,985	89.1%
Southeast Division	94.5%	68	10	85.3%	1,083	143	86.8%	18,512	1,857	90.0%
Southwest Division	90.5%	70	2	97.1%	1,160	122	89.5%	18,454	1,574	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/17/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	71,353	27,207	62%	1,746,757	567,594	68%	27,132,150	7,285,575	73%
Northeast Corridor	80%	30,255	10,326	66%	751,548	228,111	70%	12,051,958	3,104,757	74%
Acela	82%	7,588	3,322	56%	155,289	46,919	70%	2,509,206	601,585	76%
Northeast Regional	78%	22,667	7,004	69%	596,259	181,192	70%	9,542,752	2,503,172	74%
Richmond / Newport News / Norfolk	73%	6,012	1,774	70%	189,741	78,304	59%	3,079,893	1,050,841	66%
Springfield Shuttles	89%	253	35	86%	7,048	1,433	80%	173,045	26,077	85%
Roanoke	70%	2,604	961	63%	51,477	14,962	71%	805,654	212,187	74%
On Spine Northeast Regional	83%	13,798	4,234	69%	347,993	86,493	75%	5,484,160	1,214,067	78%
State Supported	80%	28,810	8,610	70%	765,875	203,269	73%	11,577,422	2,563,002	78%
Borealis	60%	487	467	4%	10,713	7,386	31%	167,420	70,564	58%
Capitol Corridor	90%	1,907	322	83%	58,289	5,001	91%	867,484	93,705	89%
Carolinian	60%	912	688	25%	17,482	10,196	42%	333,292	138,620	58%
Cascades	60%	1,438	377	74%	50,032	14,013	72%	732,912	252,039	66%
Downeaster	82%	1,138	143	87%	30,522	8,339	73%	409,204	101,332	75%
Empire	83%	4,232	2,425	43%	98,817	38,338	61%	1,560,799	340,634	78%
Adirondack	75%	258	219	15%	6,908	4,527	34%	84,903	27,226	68%
Ethan Allen Express	85%	520	360	31%	10,846	6,982	36%	156,057	40,306	74%
Maple Leaf	75%	721	595	17%	15,198	9,234	39%	211,275	64,397	70%
New York - Albany	90%	1,343	952	29%	38,714	9,892	74%	725,690	113,326	84%
New York - Niagara Falls	75%	1,390	299	78%	24,711	6,195	75%	378,544	93,094	75%
Berkshire Flyer	60%	0	0	-	2,440	1,508	38%	4,330	2,285	47%
Heartland Flyer	70%	175	162	7%	4,192	3,348	20%	63,711	29,411	54%
Hiawatha	90%	1,387	308	78%	35,934	4,640	87%	486,446	64,005	87%
Illinois	78%	1,492	216	86%	47,369	16,926	64%	717,781	174,003	76%
Carl Sandburg / Illinois Zephyr	80%	220	13	94%	8,046	1,666	79%	114,724	14,755	87%
Illini / Saluki	80%	494	67	86%	15,552	4,595	70%	253,849	33,466	87%
Lincoln Service	75%	778	136	83%	23,771	10,665	55%	349,208	125,782	64%
Keystone	92%	6,057	52	99%	128,996	11,873	91%	2,093,784	286,555	86%
Lincoln / Missouri	60%	574	134	77%	14,674	9,845	33%	208,651	114,726	45%
Michigan	69%	1,736	803	54%	42,208	11,494	73%	560,223	157,953	72%
Blue Water	70%	360	350	3%	10,388	3,238	69%	138,987	41,130	70%
Pere Marquette	85%	133	131	2%	5,022	949	81%	74,098	9,581	87%
Wolverine	65%	1,243	322	74%	26,798	7,307	73%	347,138	107,242	69%
Missouri	80%	117	72	38%	4,320	3,197	26%	63,152	22,685	64%
Pacific Surfliner	85%	3,698	508	86%	122,411	17,807	85%	1,657,020	267,158	84%
Pennsylvanian	72%	872	552	37%	16,401	5,268	68%	252,416	67,649	73%
Piedmont	73%	628	56	91%	16,352	5,842	64%	325,543	79,264	76%
San Joaquins	73%	1,237	920	26%	44,939	21,627	52%	708,751	195,997	72%
Vermont	75%	723	405	44%	22,224	8,129	63%	368,833	106,702	71%
Long Distance	57%	12,288	8,271	33%	229,334	136,214	41%	3,459,245	1,614,214	53%
Auto Train	57%	778	778	0%	14,183	5,245	63%	216,955	136,448	37%
California Zephyr	45%	1,122	1,088	3%	19,917	16,089	19%	282,560	122,589	57%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	592	342	42%	4,667	2,373	49%	78,717	39,388	50%
City Of New Orleans	75%	753	444	41%	9,687	4,147	57%	184,487	52,356	72%
Coast Starlight	65%	896	414	54%	18,248	5,958	67%	304,049	126,704	58%
Crescent	60%	844	162	81%	18,016	7,082	61%	250,084	64,606	74%
Empire Builder	55%	1,176	1,005	15%	20,699	12,862	38%	275,690	121,365	56%
Floridian	40%	1,571	1,527	3%	26,590	22,231	16%	389,945	286,011	27%
Lake Shore Ltd	70%	1,069	206	81%	19,204	7,166	63%	291,041	79,794	73%
Palmetto	65%	694	352	49%	16,761	8,792	48%	284,909	109,908	61%
Silver Meteor	45%	859	412	52%	17,959	11,916	34%	267,345	139,822	48%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	912	906	1%	18,284	14,273	22%	231,220	141,199	39%
Sunset Ltd	50%	0	0	-	4,710	2,797	41%	76,349	28,593	63%
Texas Eagle	60%	1,022	635	38%	20,409	15,283	25%	268,299	142,935	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 17, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	126,281	1,773,397	712	1,838,462	30,217,334	608

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	6,656	518,753	128	97,740	8,846,832	110
INFRASTRUCTURE PLANNED	90	3,386	518,753	65	90,532	8,846,832	102
FLEET RELIABILITY	83	22,087	1,773,397	125	290,967	30,217,334	96
TRAIN OPERATIONS	382	94,152	1,773,397	531	1,359,223	30,217,334	450

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 66(17) Washington, DC - Car Failure

18JUL25: Train 66(17) was delayed departing Washington, D.C. due to the yard crew had difficulties separating the diesels during the headend change. Then the 10-c paperwork was left with the diesel, causing an additional delay prior to departure.

Train	Delay	Comment
66(17)	52"	

Train 66(17) North Lynchburg, VA - Freight Train Interference

18JUL25: Train 66(17) was delayed beginning 29 miles north of Lynchburg, VA on the Norfolk Southern Alexandria-Montview Subdivision due to following freight unit 24X between MP143.7 to MP126.8.

Train	Delay	Comment
66(17)	54"	

Train 243(17) New York, NY - ITD/ Late Yard Release

18JUL25: Train 243(17) E/121, 5 cars, E/701, was delayed departing New York, NY due to a late yard release account of loading problems with engine E/121.

Train	Delay	Comment
243(17)	42"	

Train 49/449(17) West of Schenectady, NY - Engine Failure

17JUL25: Train 49/449(17) E/119, E/111, 11 cars, was delayed 8 miles west of Schenectady, NY at MP168.3 on the Amtrak Hudson Line due to brake issues. After troubleshooting with mechanical, crew was able to resolve and continued west.

Train	Delay	Comment
49/449(17)	53"	

Train 494(17) New Haven, CT - Hold for Connection

18JUL25: Train 494(17) was delayed departing New Haven, CT due to holding for connections from late 94(17).

Train	Delay	Comment
494(17)	31"	

Train 2124(17) Baltimore, MD - Engine Failure

18JUL25: Train 2124(17), TS18, PC/2023, 6 cars PC/2025, became disabled at approximately 7:05P-ET 1.7 miles north of Baltimore, MD at MP94 on the Amtrak PW Line. Crew reported both MCB's opened on Lead and Trail power cars, putting the train into emergency. There were approximately 250 passengers onboard and head end power remained intact. An Amtrak Road Foreman was dispatched to the scene, while crew worked with High Speed Rail mechanical to try to resolve issue. Train 196(17) was held behind 2124(17) in case a passenger transfer was necessary, with a rescue engine being sourced from Baltimore. Unable to resolve, the decision was made to terminate the train and transfer all passengers to the next 3 northbound trains 196/80/138(17) account of space availability. The passenger transfer was complete at 917P-ET, with 138(17) taking the last remaining passengers off of Train 2124(17). At 1045P-ET, The crew was able to restore power and departed with 2124's equipment back to Washington.

Due to this equipment being shopped, Acela Service Cancellations were necessary due to no replacement equipment. Trains 2103(18), 2108(18) and 2121(18) were all cancelled in their entirety with no alternate transportation provided.

Train	Delay	Comment
138(17)	1'40"	
196(17)	1'22"	
80(17)	1'04"	
192(17)	10"	
90(17)	07"	
186(17)	04"	
85(17)	21"	
193(17)	06"	
197(17)	22"	
173(17)	21"	
93(17)	19"	
2169(17)	03"	
2 MARC's	12-13"	
2124(17)	Terminated at MP94	

Train 2193(17) Boston, MA - Initial Terminal Delay

17JUL25: Train 2193(17) TS17, PC/2011, 6 CARS, PC/2022, was delayed departing Boston, MA due to the late turn off Train 2162(17) that arrived at Boston late account of needing to WYE at PHL due to lead PC/2022 going offline. Due to this, Train 2193(17) was looped at Boston prior to departure which caused an additional delay.

Train	Delay	Comment
2193(17)	1'13"	

Train 136(17) Washington, DC - Trainline Issue

17JUL25: Train 136(17), E/653, E612, 8 cars, E/659, was delayed departing Washington, D.C. due to train line 480 issues. Mechanical arrived on scene to troubleshoot and was able to resolve, allowing Train 136(17) to depart Washington.

Train	Delay	Comment
136(17)	31"	

Crossing Gate Failure at New London, CT - Signal

17JUL25: At approximately 2:05PM-ET, new London dispatcher reported State Street Crossing gate snapped off at New London, CT/MP122.8 causing delays to multiple trains. At 428P-ET, C&S reported State St. crossing working as intended.

Train	Delay	Comment
137(17)	15"	
2162(17)	45"	
2169(17)	20"	
2167(17)	07"	
86(17)	53"	
93(17)	11"	

Train 66(17) Roanoke, VA - Dispatcher Medical Emergency

17JUL25: Train 66(17) was delayed in the yard track at Roanoke, VA/MP257.6, on the NSRR Roanoke Terminal Subdivision, due to inability to contact their dispatcher. NS reported the issue was due to a medical emergency experienced by one of the dispatchers and worked to get another dispatcher to line Train 66(17) into the station. At 5:33PM, Train 66(17) departed Roanoke.

Train	Delay	Comment
66(17)	1'10"	

NHB Line Loss of OCS - East of Providence, RI

17JUL25: at approximately 342P-ET, Mainline dispatcher reported lost communication at Brayton and Orms. C&S arrived on scene to take local control and troubleshoot. Emergency plate order was in effect on tracks 1 and 3 from Hebronville to Holden with trains operating around on tracks 2 and 4, causing multiple trains to be delayed through the area. Wire reported down on Track 1 at MP197.34 and E.T. was dispatched to location. It was determined the wire was down account of broken weights. At 401A-ET, the catenary was reported repaired.

Train	Delay	Comment
177(17)	07"	
2168(17)	16"	
2173(17)	15"	
2193(17)	03"	
86(17)	04"	
67(17)	10"	
2162(17)	11"	
175(17)	08"	
172(17)	16"	
174(17)	20"	
2166(17)	04"	

Train 97(16) DeLand, FL - Commuter Train Interference

17JUL25: Train 97(16) received delays between Deland, FL/MP750.1 and Winter Park, FL/MP785.7, on the CFRC Orlando Subdivision, following CFRC 323.

Train	Delay	Comment
97(16)	33"	

Train 55(17) Claremont, NH - Freight Train Interference

17JUL25: Train 55(17) held at the Claremont, NH station/MP162.0, on the NECR Palmer Subdivision, due to freight interference. NECR 600 was disabled on the single main line at MP160.0. Unable to recover. Extensive delay incurred due to the freight crew having to van to Bellows Falls to pickup a rescue freight locomotive. Once the rescue locomotive was added, NECR 600 was able to clear the main line to allow Train 55(17) to continue south.

Train	Delay	Comment
55(17)	2'03"	Witronix

Train 93(17) Mystic, CT - Engine Failure / Shaws River Bridge Malfunction

17JUL25: At 10:48AM, Train 93(17), E/658-8 Cars, stopped just east of the Mystic, CT station/MP132.3, on the Amtrak NHB Line, at MP132.4 with engine issues. The crew reported E/658 was not charging and low on air. The train did have head end power with 330 passengers onboard. The issue was unable to be resolved so rescue E/634 was dispatched from New Haven departing at 11:14AM. One car was able to be spotted onto the platform allowing customers to get off the train and stretch their legs. An Amtrak Trainmaster and Road Foreman were on scene to coordinate. Service recovery was enacted consisting of comping items from the café car.

At 12:00PM, The New London Dispatcher reported that the Shaw's Cove Bridge at MP122.5, 0.4 miles west of the New London, CT station/MP122.9 was unable to lock for rail traffic. B&B responded quickly but spent a lot of time troubleshooting. The issue was found to be a broken screw jack which required come-alongs to get it closed and locked. The estimated track opening was set for 2:00PM. During this time, all traffic came to a halt. The rescue E/634 enroute to Train 93(17), along with trains 85(17), 2163(17), 173(17), 2154(17), and 172(17) were all heavily delayed during this time. At 1:56PM, the bridge was able to finally close and lock to allow rail traffic to resume. Also to note, Train 85(17) accommodated Train 93(17)'s downline passengers between New London and New York.

At 2:30PM, rescue E/634 arrived to Train 93(17) in order to couple up. At 3:00PM, Train 93(17) was back on the move west operating 4 hours and 14 minutes late.

Train	Delay	Comment
93(17)	4'11"	Disabled
85(17)	2'15"	Bridge
2173(17)	50"	ITD BOS - Turn of 2154(17)
177(17)	34"	ITD BOS - Turn of 172(17)
2163(17)	1'36"	Bridge
2154(17)	1'31"	Bridge
173(17)	1'22"	
172(17)	46"	Bridge

Train 79(17) Washington, DC - Engine Failure

17JUL25: Train 79(17), E/77-7 Cars, departed Washington Union Station on time then stopped just inside of the tunnel due to the brakes not releasing. The train shoved back to the station for mechanical to respond and troubleshoot. The issue was unable to be resolved so E/77 was cut and placed with E/194. At 12:13PM, Train 79(17) departed the station a second time operating 1 hour and 05 minutes late.

Train	Delay	Comment
79(17)	1'05"	

CSX Heat Orders

17JUL25: CSX Issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Alleghany, Baltimore Terminal, Capital, Kanawha, Metropolitan, Mohawk, New River, Old Main Line, RF&P, and Syracuse Terminal.

Train	Delay	Comment
63 (17)	06"	
53 (17)	21"	
79 (17)	06"	
80 (17)	27"	
90 (17)	16"	
95 (17)	12"	
125 (17)	25"	
138 (17)	10"	
141 (17)	18"	
171 (17)	02"	
186 (17)	07"	
281 (17)	22"	
283 (17)	16"	
41 (16)	36"	
40 (16)	12"	

Amtrak NYS Line - Signal Loss at Leggett Interlocking

17JUL25: At 10:18AM, the Amtrak NYS Line experienced signal loss at the Leggett Interlocking/MP9.5. Trains 95(17) and 2154(17) were the first trains stopped getting 241 permission at Leggett with instructions to stop and inspect the switch point. A C&S Maintainer arrived shortly after and reported unable to take local control. All trains received delays single tracking and operating with 241 permission during this time. At 11:40AM, control of Leggett Interlocking was returned to the Section A Dispatcher. All functions were restored.

At 3:45PM, Leggett interlocking lost communication again. During this time, 2163(17) and 2166(17) were delayed. C&S responded arriving to scene at 4:25PM to take local control allowing both trains to continue through the area.

Train	Delay	Comment
95 (17)	22"	
2155 (17)	40"	
2154 (17)	48"	
172 (17)	14"	
2166 (17)	17"	
2163 (17)	17"	

Train 40(16) Denmark, SC - Engine Failure

17JUL25: Train 40(16), E/124-E/126-10 Cars, was delayed at Denmark, SC/MP409.9, on the CSX Columbia Subdivision, after trail E/126 stopped loading, attaining maximum of only 19 amps. E/126 issue was unable to be resolved and was only able to provide head end power for the duration. As a result, an engine change was completed at Washington, DC/MP136.0, on the Amtrak WT Line, cutting E/124-E/126 and adding E/340-E/372.

After the engine swap, upon departure from Washington station, there was an air issue that led to half of the set not releasing, placing the train into penalty. A rescue motor pulled the train back in to Washington terminal, where mechanical was able to repair the air. Once resolved, Train 40(16) departed Washington.

Train	Delay	Comment
40 (16)	14"	DNK
40 (16)	13"	DNK-WAS
40 (16)	2'40"	WAS

Loss of OCS East of New Haven, CT - Catenary or Wayside Failure

17JUL25: at approximately 9:40A-ET, Shoreline Dispatcher reported no overhead power on track 1 between Branford/MP81.5 and Guilford/MP90.4 on the Amtrak NHB Line. ET responded to the scene and found an Osprey stick in the catenary at MP90.17. Multiple trains were delayed due to this. at 10:33A-ET, power was restored and normal operations resumed.

Train	Delay	Comment
2150(17)	25"	
170(17)	13"	
171(17)	27"	
190(17)	27"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

- 370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

- 371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).
- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).
- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.
- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.
- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).
- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

Train 58(17) South of Newbern-Dyersburg, TN - Freight Train Interference

18JUL25: Train 58(17) was delayed 15 miles south of Newbern-Dyersburg, TN, on CN Fulton subdivision, due to a freight train that went into emergency after possibly striking debris on the tracks. The last 4 cars of the disabled grain train sustained damage underneath and were leaking grain. Train 58(17) operated up to the freight train, inspecting the whole way, and reported multiple trees down in the area. CN personnel responded to inspect the freight cars and the tracks in the area. Once the freight recovered and the tracks were inspected, the freight was able to proceed, clearing a route for Train 58(17).

Train	Delay	Comment
58(17)	2'19"	

Train 587(17) South of San Clemente Pier, CA - Commuter Train Interference

18JUL25: Train 587(17) was delayed meeting Metrolink train 624 at Control Point Songs, on SCRRA San Diego subdivision. Once the Metrolink train cleared, train 587(17) was able to proceed.

Train 784(17) was delayed North of Oceanside, CA, on SCRRA Orange subdivision, meeting 784(17) at Serra siding.

Train	Delay	Comment
587(17)	35"	Meeting MetroLink Train
784(17)	50"	Meeting 587(17)

Train 3(16) West of Raton, NM - Miscellaneous Amtrak Responsible

18JUL25: Train 3(16) was delayed on the BNSF Raton subdivision, between Raton, NM and Las Vegas, NM due to storms in the area causing flash flood warnings. The BNSF also reported that due to the lightning they were had signal failure in the area as well, causing train 3(16) to receive unfavorable signals between MP694 and MP714.

Train 4(16) was delayed operating through the same weather restrictions and signal issues.

Train	Delay	Comment
3(16)	35"	Signal Issues
3(16)	45"	Flash Flood Warnings
4(16)	50"	Signal Issues
4(16)	22"	High Wind Warning

Train 822(17) North of Gainesville, TX - Heat Restrictions

17JUL25: Train 822(17) was delayed between MP 413.5X and MP 462.0 on the Burlington Northern Santa Fe Red Rock Subdivision, starting 3 miles north of the Gainesville, TX station, due to severe heat restrictions. The train was limited at 40 mph maximum authorize speed through the limits.

Train	Delay	Comment
822(17)	48"	

Train 22(17) Mineola, TX - UPRR Freight Derailment West of Longview, TX

17JUL25: Train 22(17) was delayed holding at Mineola, TX, on UP Mineola subdivision, due to a UP freight derailment of 18 cars west of Longview, TX, at MP90.2. UP reports 18 cars derailed on a single main track. As a result of the derailment, train 22(17) was routed through Pine Bluff subdivision, which bypassed Longview and Marshall Texas. Alternate bus transportation was secured for those bypassed stops. Bus 1 signed up at Longview at 730pm-ct and operated to Mineola. That bus then took all passengers traveling to Longview and Marshall. A second bus signed up at Marshall at 11pm-ct to take those passengers to Arkadelphia, AR to meet train 22(17). UP pilots were secured to assist with the operation over the Pine Bluff Subdivision.

21(17) Also operated over the Pine Bluff subdivision. UP pilots signed up at Texarkana, AR to assist. 1 ADA bus was secured and signed up at Texarkana at 530am and operated making stops at Marshall, TX, Longview, TX, and finally meeting the train at Mineola, TX.

WBS#: B.TR.100150.5894

Train	Delay	Comment
22(17)	4'06"	Holding at Mineola
22(17)	1'51"	Operating Pine Bluff Detour

Train 715(17) West of Wasco, CA - Freight Train Interference

17JUL25: Train 715(17) was delayed at Allensworth, MP 933.1/BNSF Bakersfield Subdivision, 20.1 miles west of Wasco, meeting BNSF freight train BNSF 6804.

Train	Delay	Comment
715(17)	37"	

Train 316(17) South of Lees Summit, MO - Freight Train Interference

18JUL25: Train 316(17) was delayed 1.5 miles south of Lees Summit, MO, on UP Sedalia subdivision, due to meeting UP7642 at Lees Summit Siding, and then meeting UP5335 at Strasburg siding.

Train	Delay	Comment
316(17)	40"	Strasburg Siding
316(17)	11"	Lee Summit Siding

Train 8(17) Initial Terminal Seattle, WA - Late Inbound Equipment

17JUL25: Train 8(17) was delayed departing Seattle, MP 0.0/BNSF Seattle Subdivision, following a late yard release due to the turning and servicing of equipment off late inbound Train 7(15) which arrived one hour, twelve minutes late at 12:41PM-PT (then equipment spotted in the yard at 2:40pm). Train 8(17) departed Seattle at 5:25PM-PT.

Train	Delay	Comment
8(17)	30"	

Train 11(16) South of Oakland, CA - Close Call with Vehicle

17JUL25: Train 11(16), operating with camera-equipped locomotives E/311-E/347 and 8 cars, emergency braking was applied to avoid striking a garbage truck fouling the the tracks in San Leandro at MP 15.8/UPRR Coast Subdivision, 8.8 miles south of Oakland. There were no injuries to passengers (166) or crew. There was no equipment damage. The truck fled the scene. The train was on-the-move following successful equipment inspection and air test. Amtrak Police notified.

Train	Delay	Comment
11(16)	05"	

Train 14(17) Carpinteria, CA - Injured or Sick Passenger or Employee

17JUL25: Train 14(17) was delayed at the Carpinteria depot, MP 377.6/UPRR Santa Barbara as a result of an onboard passenger medical emergency. Local EMS responded, removed the passenger and transported to Cottage Hospital in Santa Barbara.

Train	Delay	Comment
14 (17)	21"	

Train 371(17) East of Chicago, IL - Freight Train Interference

17JUL25: Train 371(17) was delayed between CP 487 / MP CD 487.1 and and CP 501 / MP CD 501.0 on the Norfolk Southern Chicago Terminal Subdivision, starting 37 miles east of the Chicago, IL Union Station, following 29G.

Train	Delay	Comment
371 (17)	35"	

Train 21(16) West of Longview, TX - Freight Train Interference

17JUL25: Train 21(16) was delayed at Gladewater / MP 105.5 on the Union Pacific Mineola Subdivision, 16 miles west of the Longview, TX station, due to MARAS-17 (UPRR 6312) experienced an undesired emergency brake application. UPRR Mechanical responded to assist.

Train	Delay	Comment
21 (16)	1'42"	

Train 332(17) Milwaukee, WI - System

17JUL25: Train 332(17) was delayed departing the Milwaukee, WI Intermodal Station due to issues initializing the positive train control on lead Locomotive 518. After assistance from troubleshooting, the crew was able to initialize the PTC before departing.

Train 1333(17) was delayed departing the Chicago, IL Union Station due to late arrival of Train 332(17) and the scheduled switching out of Locomotive 518. The replacement was Locomotive 517.

Train	Delay	Comment
332 (17)	47"	
1333 (17)	44"	

Train 329(17) East of Glenview, IL - Commuter Train Interference

17JUL25: Train 329(17) was delayed between Canal / MP 0.0 and Glenview / MP 17.32 on the Canadian Pacific and Kansas City Subdivision C & M Subdivision following Metra commuter train.

Train	Delay	Comment
329 (17)	36"	

Train 392(17) Effingham, IL - Signal

18JUL25: Train 392(17) was delayed 30 miles south of Effingham, IL, on CN Champaign subdivision, due to signal issues of an unknown origin, requiring the train to flag through the affected area. Once train 392(17) cleared the area affected by the bad signals, they were able to proceed at normal speed.

Train 4(15) Lamar, CO - Hlgh Wind/Flash Flood Warnings

17JUL25: Multiple trains were delayed operating through high wind and flash flood warnings due to severe weather on the BNSF La Junta and Seligman subdivisions.

Train 4(15) was delayed between Lamar, CO and Dodge City, KS.

Train 3(16) was delayed west of Kansas City, MO.

Train 3(15) was delayed between Flag Staff, AZ and Kingman, AZ.

Additional flooding occurred continued between Lawrence, KS and Kansas City, MO causing washout at MP 3.9 and MP 1.3 on the Burlington Northern Santa Fe Topeka Subdivision, 22 miles east of the Lawrence, KS station. BNSF MoW responded to the washouts. The initial estimated track opening was at 11:00 a.m. (CDT).

Train 4(15) had arrived at the Newton, KS at 6:25 a.m. (CDT) and held for update before advancing to the Topeka, KS station where they held for track opening.

Supplemental bussing for 4(15). Three supplemental buses secured between Topeka, KS and Chicago, IL.

WBS#: B.TR.100150.5893

Train	Delay	Comment
4(15)	1'02"	
3(15)	1'10"	
3(16)	34"	
4(15)	1'22"	NEW
4(15)	13"	East of LRC - Restriction over Repaired Washouts

Train 8/28(16) West of Sandpoint, ID - Car Failure

17JUL25: Train 8 / 28(16), operating with Locomotive 369, Locomotive 334 and 10 cars, stopped at MP 34.5 on the Burlington Northern Santa Fe Kootenai River Subdivision, 32 miles west of the Sand Point, ID, due to a wayside detector found a chipped wheel under Car 32083. BNSF Mechanical responded and reported the defect was not condemnable. The car was able to continue to Chicago for repair.

Train 7 / 27(15) was delayed at Silver / MP 36.0 waiting on relief crew.

Train	Delay	Comment
8/28(16)	1'39"	
7/27(15)	31"	Silver - Relief Crew

Train 41(16) Chicago, IL - Initial Terminal Delay

17JUL25:Train 41(16) was delayed 30 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(14), replacing a bad order locomotive, and troubleshooting two cars with inoperative toilets. As background, inbound 40(14) arrived in Chicago at 1203pm; 3 hours and 18 minutes late due to 1 hour and 57 minutes of freight train interference, 1 hour and 7 minutes of weather restrictions, 43 minutes for ADA accommodations, and 26 minutes for a maritime bridge lift. Equipment set to the yard for servicing and inspection at 135pm. There were no scheduled program moves. At 335pm, lead engine AMTK 11 was bad ordered for wheel shelling. Blue flags were dropped at 416pm and replacement locomotive AMTK 62 was added in trail at 457pm. At 545pm, mechanical reported bad order toilets on coach 25049. Due to no replacement coaches, c/25049 to deadhead inline with the passengers downgraded (coach to be added in Washington, D.C). At 610pm, mechanical reported bad ordered toilets on sleeping car 62034. Due to no replacement sleepers, c/62034 to deadhead inline with the passengers downgraded. Train 41(16) was released by mechanical at 617pm, shoved from yard at 628pm, and set in the station at 638pm with 229 passengers to board. Train 41(16) departed Chicago at 710pm; 30 minutes late.

Train 41(16) was further delayed 1 mile south of Chicago, IL , due to a traction motor fault that would not reset. The crew worked with CNOC mechanical to resolve. After cycling the power the fault was reset and train 41(16) was able to proceed.

17JUL25: Train 41(16) was delayed at Washington, DC/MP136.0, on the Amtrak WT Line, adding coach C/82985 to the head end. This was to alleviate oversold conditions after coach C/25049 and sleeper C/62034 were bad ordered out of Chicago.

Train	Delay	Comment
41(16)	45"	Traction Motor E/62
41(16)	33"	ITD CHI
41(16)	47"	WAS - Add Car

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Train 55(17) South of St. Albans, VT - M of W Work

17JUL25: Train 55(17) was delayed starting 4.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, due to a 10MPH speed restriction from MP128-MP119 due to Maintenance of Way working in the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
55 (17)	49"	

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/17/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/17/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	4,916	616	87.5%	83,623	8,285	90.1%
Central Division	91.5%	66	8	87.9%	1,123	129	88.5%	19,152	1,869	90.2%
Northeast Division	95.0%	96	12	87.5%	1,550	222	85.7%	27,505	2,985	89.1%
Southeast Division	94.5%	68	10	85.3%	1,083	143	86.8%	18,512	1,857	90.0%
Southwest Division	90.5%	70	2	97.1%	1,160	122	89.5%	18,454	1,574	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/17/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/17/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	4,916	616	87.5%	83,623	8,285	90.1%
Central Division	91.5%	66	8	87.9%	1,123	129	88.5%	19,152	1,869	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	39	2	94.9%	582	16	97.3%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	27	4	85.2%	454	72	84.1%	7,730	957	87.6%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	34	0	100.0%	558	19	96.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	16	0	100.0%	289	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	33	1	97.0%	562	38	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	1	83.3%	99	5	94.9%	1,662	93	94.4%
MSP	95.0%	1	0	100.0%	17	2	88.2%	278	14	95.0%
PDX	78.0%	5	1	80.0%	81	8	90.1%	1,393	160	88.5%
PNT	94.0%	3	1	66.7%	50	1	98.0%	797	57	92.8%
PTH	96.0%	1	0	100.0%	17	0	100.0%	288	11	96.2%
QCY	94.0%	2	0	100.0%	32	0	100.0%	562	18	96.8%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	1	87.5%	137	27	80.3%	2,264	327	85.6%
SPK	92.0%	1	-	100.0%	15	1	93.3%	286	14	95.1%
STL	96.0%	3	0	100.0%	61	6	90.2%	1,138	59	94.8%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	34	0	100.0%	555	12	97.8%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	96	12	87.5%	1,550	222	85.7%	27,505	2,985	89.1%
ALB	96.0%	6	1	83.3%	102	5	95.1%	1,951	127	93.5%
BON	94.5%	5	0	100.0%	83	8	90.4%	1,347	91	93.2%
BOS	97.0%	19	4	78.9%	303	34	88.8%	5,420	500	90.8%
BRK	97.0%	5	0	100.0%	56	2	96.4%	1,317	68	94.8%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	17	2	88.2%	288	19	93.4%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	31	2	93.5%	558	54	90.3%
HFD	-	2	0	100.0%	24	4	83.3%	170	17	90.0%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/17/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/17/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	4,916	616	87.5%	83,623	8,285	90.1%
Northeast Division	95.0%	96	12	87.5%	1,550	222	85.7%	27,505	2,985	89.1%
MTR	97.0%	1	0	100.0%	17	2	88.2%	288	28	90.3%
NFL	97.0%	2	0	100.0%	34	1	97.1%	580	24	95.9%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	0	100.0%	80	12	85.0%	1,487	146	90.2%
NYP	94.5%	41	7	82.9%	659	129	80.4%	11,652	1,767	84.8%
POR	-	-	-	-	24	8	66.7%	24	8	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	15	3	80.0%	286	8	97.2%
SPG	95.5%	5	0	100.0%	81	7	91.4%	1,777	83	95.3%
TWO	96.0%	1	0	100.0%	17	0	100.0%	287	11	96.2%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	68	10	85.3%	1,083	143	86.8%	18,512	1,857	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	82	9	89.0%	1,436	94	93.5%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	1	92.3%	191	13	93.2%	3,136	101	96.8%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	17	3	82.4%	284	91	68.0%
MIA	90.0%	2	1	50.0%	33	4	87.9%	558	51	90.9%
NFK	94.5%	3	0	100.0%	48	10	79.2%	798	64	92.0%
NOL	92.0%	2	0	100.0%	36	3	91.7%	643	46	92.8%
NPN	96.0%	2	1	50.0%	34	4	88.2%	553	21	96.2%
PGH	92.0%	1	0	100.0%	17	2	88.2%	289	16	94.5%
PHL	97.0%	5	1	80.0%	73	19	74.0%	1,239	176	85.8%
RGH	97.0%	4	0	100.0%	60	2	96.7%	1,163	36	96.9%
RNK	94.0%	2	1	50.0%	31	2	93.5%	548	64	88.3%
RVM	90.0%	1	0	100.0%	17	1	94.1%	281	34	87.9%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	1	0.0%	15	1	93.3%	271	11	95.9%
SFA	83.0%	1	0	100.0%	17	1	94.1%	284	79	72.2%
WAS	94.5%	25	4	84.0%	402	59	85.3%	6,876	940	86.3%
Southwest Division	90.5%	70	2	97.1%	1,160	122	89.5%	18,454	1,574	91.5%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	17	0	100.0%	290	7	97.6%
BFD	90.0%	6	0	100.0%	100	12	88.0%	1,723	148	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	0	100.0%	17	14	17.6%	297	90	69.7%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	16	2	87.5%	322	42	87.0%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/17/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/17/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	4,916	616	87.5%	83,623	8,285	90.1%
Southwest Division	90.5%	70	2	97.1%	1,160	122	89.5%	18,454	1,574	91.5%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	51	2	96.1%	847	62	92.7%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	1	88.9%	160	17	89.4%	2,219	308	86.1%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	14	0	100.0%	285	6	97.9%
OKJ	91.0%	12	0	100.0%	188	28	85.1%	3,041	278	90.9%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	0	100.0%	223	22	90.1%	3,454	147	95.7%
SAN	90.0%	12	1	91.7%	202	13	93.6%	2,624	231	91.2%
SAS	85.0%	1	0	100.0%	17	5	70.6%	286	40	86.0%
SJC	95.0%	7	0	100.0%	118	6	94.9%	1,858	72	96.1%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	34	0	100.0%	567	27	95.2%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	2	0	100.0%	49	11	77.6%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	109	17	5	70.6%	284	55	80.6%	17	13	23.5%	280	154	45.0%
4	361	17	3	82.4%	285	68	76.1%	17	13	23.5%	284	144	49.3%
5	117	17	9	47.1%	287	48	83.3%	16	13	18.8%	284	96	66.2%
6	143	17	14	17.6%	287	83	71.1%	17	14	17.6%	286	96	66.4%
7	72	17	4	76.5%	281	40	85.8%	17	6	64.7%	276	73	73.6%
8	47	17	13	23.5%	282	105	62.8%	17	13	23.5%	280	134	52.1%
11		17	2	88.2%	289	46	84.1%	17	2	88.2%	282	63	77.7%
14		17	6	64.7%	290	88	69.7%	17	6	64.7%	288	126	56.3%
19		17	0	100.0%	290	33	88.6%	17	7	58.8%	289	56	80.6%
20		17	1	94.1%	290	14	95.2%	17	4	76.5%	289	46	84.1%
21		17	1	94.1%	289	35	87.9%	17	6	64.7%	283	89	68.6%
22		17	5	70.6%	286	42	85.3%	17	14	17.6%	285	122	57.2%
27	69	15	4	73.3%	277	21	92.4%	14	6	57.1%	267	92	65.5%
28		14	2	85.7%	270	67	75.2%	14	3	78.6%	269	75	72.1%
40	139	17	2	88.2%	247	35	85.8%	16	12	25.0%	242	151	37.6%
41	94	16	11	31.3%	245	106	56.7%	16	15	6.3%	241	192	20.3%
42		17	2	88.2%	290	17	94.1%	17	5	70.6%	290	79	72.8%
43	49	17	2	88.2%	290	25	91.4%	17	6	64.7%	290	66	77.2%
48		17	4	76.5%	289	52	82.0%	17	4	76.5%	289	45	84.4%
49		17	6	64.7%	290	56	80.7%	17	4	76.5%	290	51	82.4%
51		7	1	85.7%	123	23	81.3%	7	2	71.4%	117	40	65.8%
52	38	17	1	94.1%	284	79	72.2%	17	5	70.6%	284	152	46.5%
53		17	3	82.4%	284	91	68.0%	17	4	76.5%	284	144	49.3%
55	210	12	2	83.3%	201	8	96.0%	12	6	50.0%	201	45	77.6%
56	110	12	2	83.3%	201	35	82.6%	12	9	25.0%	200	52	74.0%
58		17	2	88.2%	282	23	91.8%	17	2	88.2%	279	55	80.3%
59	228	17	5	70.6%	281	57	79.7%	16	6	62.5%	277	33	88.1%
63	34	17	10	41.2%	290	56	80.7%	17	15	11.8%	290	147	49.3%
64		17	0	100.0%	290	11	96.2%	17	3	82.4%	290	71	75.5%
66		17	3	82.4%	288	56	80.6%	17	1	94.1%	286	37	87.1%
67		12	0	100.0%	200	17	91.5%	12	3	75.0%	198	42	78.8%
68	49	17	2	88.2%	290	28	90.3%	17	14	17.6%	290	118	59.3%
69	37	17	2	88.2%	290	22	92.4%	16	7	56.3%	285	34	88.1%
71		16	2	87.5%	289	7	97.6%	16	8	50.0%	287	66	77.0%
72	16	17	3	82.4%	290	22	92.4%	17	7	58.8%	288	74	74.3%
73		17	3	82.4%	290	15	94.8%	17	9	47.1%	288	144	50.0%
74		17	1	94.1%	286	21	92.7%	17	8	52.9%	284	98	65.5%
75		17	3	82.4%	288	8	97.2%	17	10	41.2%	286	117	59.1%
76		17	4	76.5%	286	20	93.0%	16	11	31.3%	284	124	56.3%
77		17	2	88.2%	287	12	95.8%	17	8	52.9%	285	128	55.1%
78		17	0	100.0%	288	10	96.5%	16	5	68.8%	287	69	76.0%
79	50	17	5	70.6%	290	40	86.2%	15	6	60.0%	287	104	63.8%

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80	167	17	3	82.4%	290	24	91.7%	17	11	35.3%	290	84	71.0%
84		12	0	100.0%	200	8	96.0%	12	6	50.0%	199	75	62.3%
85	153	12	0	100.0%	198	16	91.9%	12	9	25.0%	197	135	31.5%
86	56	12	1	91.7%	198	23	88.4%	12	10	16.7%	198	135	31.8%
89	48	17	1	94.1%	289	35	87.9%	17	7	58.8%	287	105	63.4%
90		17	1	94.1%	289	12	95.8%	16	7	56.3%	284	71	75.0%
93	296	12	0	100.0%	201	14	93.0%	12	7	41.7%	200	93	53.5%
94	19	12	4	66.7%	201	18	91.0%	12	7	41.7%	200	73	63.5%
95	45	12	0	100.0%	201	5	97.5%	12	6	50.0%	201	87	56.7%
97	75	17	13	23.5%	286	134	53.1%	17	10	41.2%	285	94	67.0%
98		17	2	88.2%	286	17	94.1%	17	11	35.3%	286	147	48.6%
110	31	12	5	58.3%	199	38	80.9%	12	3	75.0%	197	42	78.7%
111		12	2	83.3%	198	49	75.3%	12	2	83.3%	196	32	83.7%
112		12	3	75.0%	193	38	80.3%	12	3	75.0%	191	24	87.4%
114		12	2	83.3%	197	53	73.1%	12	3	75.0%	193	30	84.5%
119		12	1	91.7%	195	39	80.0%	12	2	83.3%	192	29	84.9%
125	44	12	1	91.7%	201	10	95.0%	12	8	33.3%	201	115	42.8%
129	23	12	3	75.0%	199	41	79.4%	12	6	50.0%	198	44	77.8%
130		12	1	91.7%	195	20	89.7%	12	1	91.7%	192	22	88.5%
131		12	2	83.3%	192	34	82.3%	12	2	83.3%	190	28	85.3%
133	No OS	12	7	41.7%	199	75	62.3%	12	10	16.7%	199	103	48.2%
134		12	0	100.0%	200	15	92.5%	12	7	41.7%	200	98	51.0%
136		12	1	91.7%	201	40	80.1%	12	3	75.0%	199	41	79.4%
137	52	12	4	66.7%	201	25	87.6%	12	6	50.0%	201	81	59.7%
138	124	12	2	83.3%	200	23	88.5%	12	7	41.7%	200	50	75.0%
141	No OS	12	0	100.0%	201	3	98.5%	12	7	41.7%	201	97	51.7%
148		12	1	91.7%	201	18	91.0%	12	4	66.7%	201	43	78.6%
151		17	3	82.4%	287	35	87.8%	17	4	76.5%	286	97	66.1%
170		12	0	100.0%	200	12	94.0%	12	6	50.0%	200	51	74.5%
171	91	12	2	83.3%	201	9	95.5%	12	8	33.3%	201	102	49.3%
172	94	12	2	83.3%	200	15	92.5%	12	5	58.3%	198	64	67.7%
173	152	12	0	100.0%	201	26	87.1%	12	4	66.7%	201	67	66.7%
174		12	2	83.3%	201	6	97.0%	12	5	58.3%	200	47	76.5%
175		12	5	58.3%	200	35	82.5%	12	6	50.0%	199	72	63.8%
176		12	3	75.0%	201	19	90.5%	12	1	91.7%	200	25	87.5%
177	No OS	12	3	75.0%	201	29	85.6%	12	5	58.3%	200	42	79.0%
178		12	1	91.7%	201	30	85.1%	12	6	50.0%	200	42	79.0%
179		12	2	83.3%	199	14	93.0%	12	8	33.3%	199	69	65.3%
181		12	5	58.3%	196	39	80.1%	12	1	91.7%	192	27	85.9%
182	18	12	2	83.3%	196	48	75.5%	12	7	41.7%	195	52	73.3%
183		12	2	83.3%	201	26	87.1%	12	1	91.7%	201	25	87.6%
184		12	5	58.3%	201	29	85.6%	12	2	83.3%	200	25	87.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
185		12	2	83.3%	201	34	83.1%	12	2	83.3%	201	26	87.1%
186	31	12	2	83.3%	198	13	93.4%	12	7	41.7%	196	57	70.9%
190	29	12	5	58.3%	201	40	80.1%	12	6	50.0%	201	51	74.6%
192	34	12	3	75.0%	97	17	82.5%	12	4	66.7%	95	13	86.3%
193		12	4	66.7%	199	34	82.9%	12	6	50.0%	198	72	63.6%
196	95	12	1	91.7%	201	70	65.2%	12	3	75.0%	198	59	70.2%
197	19	12	7	41.7%	200	51	74.5%	12	4	66.7%	199	56	71.9%
232		17	1	94.1%	278	10	96.4%	17	1	94.1%	278	22	92.1%
233	48	15	5	66.7%	286	85	70.3%	15	8	46.7%	285	99	65.3%
234	24	17	1	94.1%	278	7	97.5%	17	2	88.2%	278	22	92.1%
236	28	17	0	100.0%	278	5	98.2%	17	2	88.2%	277	46	83.4%
237		15	0	100.0%	274	28	89.8%	15	2	86.7%	272	32	88.2%
239	62	17	4	76.5%	277	29	89.5%	17	5	70.6%	277	21	92.4%
240		17	0	100.0%	282	24	91.5%	17	5	70.6%	281	27	90.4%
241	25	17	3	82.4%	290	36	87.6%	16	5	68.8%	289	41	85.8%
243	61	12	5	58.3%	201	37	81.6%	12	5	58.3%	200	27	86.5%
244	22	15	1	93.3%	286	8	97.2%	15	9	40.0%	286	48	83.2%
280		17	0	100.0%	289	11	96.2%	17	1	94.1%	289	52	82.0%
281		17	2	88.2%	290	60	79.3%	16	4	75.0%	288	59	79.5%
283	21	17	6	64.7%	290	63	78.3%	17	8	52.9%	289	61	78.9%
284		17	1	94.1%	290	13	95.5%	17	0	100.0%	289	58	79.9%
290	25	17	2	88.2%	290	21	92.8%	16	12	25.0%	288	65	77.4%
291	20	17	6	64.7%	290	44	84.8%	17	12	29.4%	289	58	79.9%
300		15	1	93.3%	279	8	97.1%	15	4	73.3%	277	67	75.8%
302		16	1	93.8%	284	19	93.3%	16	6	62.5%	281	96	65.8%
305	28	17	2	88.2%	284	21	92.6%	17	14	17.6%	283	110	61.1%
307		16	1	93.8%	283	37	86.9%	15	9	40.0%	280	104	62.9%
311	29	16	3	81.3%	280	18	93.6%	16	14	12.5%	276	110	60.1%
316	43	16	1	93.8%	278	19	93.2%	16	14	12.5%	276	103	62.7%
318		17	0	100.0%	286	19	93.4%	17	11	35.3%	282	158	44.0%
319		17	1	94.1%	288	19	93.4%	17	15	11.8%	283	176	37.8%
329	48	12	2	83.3%	202	18	91.1%	12	1	91.7%	202	17	91.6%
330		14	1	92.9%	234	5	97.9%	14	1	92.9%	233	15	93.6%
331		17	1	94.1%	281	20	92.9%	17	2	88.2%	277	27	90.3%
332	58	17	1	94.1%	286	17	94.1%	17	3	82.4%	285	44	84.6%
334		17	0	100.0%	286	9	96.9%	17	3	82.4%	281	71	74.7%
335	14	17	2	88.2%	289	31	89.3%	17	5	70.6%	280	61	78.2%
336		17	1	94.1%	275	7	97.5%	17	5	70.6%	274	80	70.8%
337		17	1	94.1%	278	16	94.2%	17	5	70.6%	277	62	77.6%
338		17	2	88.2%	288	37	87.2%	17	7	58.8%	278	122	56.1%
339		17	0	100.0%	288	42	85.4%	17	2	88.2%	286	50	82.5%
341	20	16	9	43.8%	273	54	80.2%	16	9	43.8%	267	56	79.0%

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
342		17	0	100.0%	289	18	93.8%	17	1	94.1%	288	44	84.7%
350	24	17	2	88.2%	249	27	89.2%	17	11	35.3%	246	124	49.6%
351		17	0	100.0%	278	24	91.4%	17	4	76.5%	277	77	72.2%
352	28	17	3	82.4%	283	27	90.5%	17	9	47.1%	278	80	71.2%
353		17	0	100.0%	242	6	97.5%	17	1	94.1%	237	36	84.8%
354		16	0	100.0%	282	26	90.8%	16	4	75.0%	279	102	63.4%
355	40	16	1	93.8%	282	31	89.0%	16	4	75.0%	278	72	74.1%
364		17	1	94.1%	288	55	80.9%	17	4	76.5%	287	78	72.8%
365	33	17	0	100.0%	288	11	96.2%	17	7	58.8%	287	85	70.4%
370	48	16	1	93.8%	289	11	96.2%	15	3	80.0%	288	36	87.5%
371	32	16	0	100.0%	289	4	98.6%	16	3	81.3%	289	28	90.3%
380		17	1	94.1%	287	11	96.2%	17	1	94.1%	287	27	90.6%
381		17	2	88.2%	287	8	97.2%	17	5	70.6%	286	28	90.2%
382	18	17	1	94.1%	286	11	96.2%	17	5	70.6%	286	38	86.7%
383		17	0	100.0%	288	29	89.9%	17	8	52.9%	287	67	76.7%
390		17	2	88.2%	285	12	95.8%	17	7	58.8%	283	43	84.8%
391		17	0	100.0%	288	6	97.9%	17	4	76.5%	286	53	81.5%
392	22	17	0	100.0%	288	8	97.2%	17	5	70.6%	285	31	89.1%
393		17	1	94.1%	287	13	95.5%	17	8	52.9%	284	41	85.6%
417		12	2	83.3%	197	32	83.8%	11	1	90.9%	194	29	85.1%
425		12	0	100.0%	185	5	97.3%	12	0	100.0%	185	7	96.2%
470		13	2	84.6%	203	15	92.6%	11	2	81.8%	198	28	85.9%
471		12	2	83.3%	201	14	93.0%	11	0	100.0%	199	11	94.5%
473		12	2	83.3%	201	7	96.5%	11	1	90.9%	200	3	98.5%
474	32	12	2	83.3%	199	30	84.9%	11	6	45.5%	195	60	69.2%
475	19	12	2	83.3%	200	8	96.0%	12	2	83.3%	197	18	90.9%
478		12	1	91.7%	201	21	89.6%	11	1	90.9%	199	20	89.9%
479		12	1	91.7%	201	30	85.1%	12	2	83.3%	200	24	88.0%
486	87	12	0	100.0%	203	16	92.1%	12	5	58.3%	201	69	65.7%
494	25	12	4	66.7%	206	31	85.0%	12	6	50.0%	200	56	72.0%
495		12	0	100.0%	198	2	99.0%	12	1	91.7%	198	5	97.5%
500		17	1	94.1%	279	22	92.1%	16	3	81.3%	277	81	70.8%
502		17	0	100.0%	277	13	95.3%	16	1	93.8%	275	79	71.3%
503	21	17	1	94.1%	290	30	89.7%	17	7	58.8%	279	88	68.5%
504		17	0	100.0%	278	9	96.8%	16	4	75.0%	277	111	59.9%
505		17	2	88.2%	282	33	88.3%	16	5	68.8%	279	102	63.4%
506		17	3	82.4%	282	27	90.4%	16	3	81.3%	280	69	75.4%
507		17	3	82.4%	281	33	88.3%	17	7	58.8%	280	87	68.9%
508		17	0	100.0%	285	13	95.4%	17	5	70.6%	283	83	70.7%
509		17	3	82.4%	280	31	88.9%	16	4	75.0%	279	98	64.9%
511		17	1	94.1%	281	23	91.8%	17	3	82.4%	278	75	73.0%
516	41	17	1	94.1%	281	25	91.1%	17	9	47.1%	279	127	54.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
517		17	0	100.0%	282	5	98.2%	17	6	64.7%	281	169	39.9%
518	17	17	3	82.4%	282	32	88.7%	17	8	52.9%	280	169	39.6%
519		17	0	100.0%	279	11	96.1%	17	3	82.4%	278	58	79.1%
520		12	2	83.3%	33	4	87.9%	12	0	100.0%	33	1	97.0%
521		12	0	100.0%	201	4	98.0%	12	1	91.7%	200	16	92.0%
522		12	1	91.7%	201	4	98.0%	11	0	100.0%	200	11	94.5%
523		12	0	100.0%	202	4	98.0%	12	1	91.7%	202	26	87.1%
524		12	1	91.7%	202	6	97.0%	11	2	81.8%	201	35	82.6%
525		12	0	100.0%	200	4	98.0%	12	0	100.0%	199	10	95.0%
526		12	0	100.0%	33	4	87.9%	12	3	75.0%	33	7	78.8%
527		12	0	100.0%	202	3	98.5%	12	0	100.0%	201	29	85.6%
528		12	0	100.0%	201	5	97.5%	12	1	91.7%	201	31	84.6%
529	23	12	0	100.0%	202	0	100.0%	12	4	66.7%	202	40	80.2%
531		12	1	91.7%	201	3	98.5%	12	3	75.0%	200	16	92.0%
532		12	0	100.0%	202	9	95.5%	12	0	100.0%	200	20	90.0%
534		12	2	83.3%	202	15	92.6%	12	1	91.7%	201	15	92.5%
535		12	2	83.3%	33	3	90.9%	11	0	100.0%	32	2	93.8%
536		12	0	100.0%	202	8	96.0%	12	1	91.7%	200	9	95.5%
537		11	0	100.0%	32	1	96.9%	11	0	100.0%	32	2	93.8%
538		12	1	91.7%	202	5	97.5%	12	2	83.3%	202	36	82.2%
540		12	0	100.0%	202	5	97.5%	12	2	83.3%	197	20	89.8%
541	28	12	0	100.0%	202	8	96.0%	12	4	66.7%	202	44	78.2%
542		12	1	91.7%	202	8	96.0%	12	3	75.0%	202	35	82.7%
543	15	12	0	100.0%	202	6	97.0%	12	8	33.3%	202	32	84.2%
544		11	1	90.9%	200	11	94.5%	11	0	100.0%	199	15	92.5%
545		12	1	91.7%	202	8	96.0%	12	1	91.7%	200	21	89.5%
546		12	0	100.0%	202	7	96.5%	12	3	75.0%	201	31	84.6%
547		12	2	83.3%	202	9	95.5%	12	3	75.0%	202	29	85.6%
548		12	0	100.0%	200	12	94.0%	12	0	100.0%	198	11	94.4%
549		12	4	66.7%	202	23	88.6%	11	0	100.0%	196	29	85.2%
551		12	0	100.0%	202	10	95.0%	12	0	100.0%	197	17	91.4%
562		17	0	100.0%	286	31	89.2%	17	1	94.1%	277	31	88.8%
564		17	3	82.4%	284	20	93.0%	17	2	88.2%	281	26	90.7%
566		17	0	100.0%	109	10	90.8%	17	0	100.0%	109	11	89.9%
572		17	2	88.2%	239	21	91.2%	17	5	70.6%	235	43	81.7%
573	27	17	0	100.0%	278	37	86.7%	17	1	94.1%	272	44	83.8%
577		17	0	100.0%	32	0	100.0%	17	2	88.2%	32	2	93.8%
580		17	0	100.0%	286	21	92.7%	17	1	94.1%	285	53	81.4%
581		17	2	88.2%	286	35	87.8%	17	4	76.5%	282	55	80.5%
582		17	0	100.0%	32	0	100.0%	17	2	88.2%	32	3	90.6%
586		17	1	94.1%	237	30	87.3%	17	3	82.4%	230	41	82.2%
587	43	17	2	88.2%	237	27	88.6%	16	3	81.3%	230	49	78.7%

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
591		17	0	100.0%	286	32	88.8%	17	2	88.2%	282	40	85.8%
593		17	4	76.5%	32	6	81.3%	17	4	76.5%	32	7	78.1%
595	37	17	3	82.4%	278	61	78.1%	17	2	88.2%	276	50	81.9%
600		12	1	91.7%	200	3	98.5%	12	2	83.3%	198	26	86.9%
601		12	2	83.3%	200	19	90.5%	12	2	83.3%	199	33	83.4%
605		12	1	91.7%	200	11	94.5%	12	0	100.0%	198	26	86.9%
607		12	1	91.7%	201	18	91.0%	12	0	100.0%	200	10	95.0%
609		12	1	91.7%	201	13	93.5%	11	1	90.9%	200	30	85.0%
620		12	1	91.7%	201	6	97.0%	12	3	75.0%	199	27	86.4%
622		10	2	80.0%	159	8	95.0%	10	2	80.0%	158	47	70.3%
639		12	1	91.7%	201	26	87.1%	12	2	83.3%	200	24	88.0%
640		12	1	91.7%	201	1	99.5%	12	2	83.3%	201	100	50.2%
641		12	0	100.0%	201	18	91.0%	12	0	100.0%	201	34	83.1%
642		12	0	100.0%	201	0	100.0%	12	1	91.7%	200	42	79.0%
643		12	0	100.0%	201	13	93.5%	12	1	91.7%	200	42	79.0%
644		12	1	91.7%	201	9	95.5%	11	2	81.8%	198	46	76.8%
645		12	1	91.7%	201	15	92.5%	11	3	72.7%	200	52	74.0%
646		12	1	91.7%	201	18	91.0%	12	3	75.0%	198	99	50.0%
647		12	1	91.7%	201	15	92.5%	11	4	63.6%	200	79	60.5%
648		12	0	100.0%	201	12	94.0%	12	4	66.7%	199	34	82.9%
649		12	0	100.0%	201	20	90.0%	12	4	66.7%	200	39	80.5%
650		12	0	100.0%	201	10	95.0%	12	1	91.7%	200	30	85.0%
651		12	2	83.3%	201	25	87.6%	12	3	75.0%	201	80	60.2%
652	23	12	1	91.7%	201	4	98.0%	12	5	58.3%	201	37	81.6%
653	12	12	0	100.0%	201	13	93.5%	12	5	58.3%	200	67	66.5%
654		12	1	91.7%	201	5	97.5%	12	0	100.0%	199	20	89.9%
655		12	1	91.7%	200	30	85.0%	12	4	66.7%	198	70	64.6%
656		12	3	75.0%	201	6	97.0%	12	2	83.3%	200	45	77.5%
657		12	1	91.7%	201	14	93.0%	12	1	91.7%	201	50	75.1%
658		12	0	100.0%	201	6	97.0%	12	3	75.0%	200	53	73.5%
680		13	0	100.0%	203	2	99.0%	13	1	92.3%	202	32	84.2%
681	13	13	0	100.0%	202	12	94.1%	13	7	46.2%	199	80	59.8%
682		13	0	100.0%	203	5	97.5%	13	1	92.3%	203	95	53.2%
683		12	0	100.0%	155	4	97.4%	12	6	50.0%	155	62	60.0%
684	18	11	3	72.7%	154	12	92.2%	11	7	36.4%	153	83	45.8%
685		11	0	100.0%	158	12	92.4%	11	7	36.4%	158	58	63.3%
686		13	5	61.5%	202	41	79.7%	13	7	46.2%	202	84	58.4%
687		13	1	92.3%	203	29	85.7%	13	7	46.2%	203	79	61.1%
688		13	1	92.3%	203	8	96.1%	13	2	84.6%	203	89	56.2%
689		4	1	75.0%	149	7	95.3%	4	1	75.0%	150	30	80.0%
702	29	17	2	88.2%	290	19	93.4%	17	11	35.3%	289	96	66.8%
703		17	2	88.2%	290	29	90.0%	17	7	58.8%	290	72	75.2%

Amtrak On Time Performance													
Trains Arriving Through: 7/17/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
710	83	17	4	76.5%	290	46	84.1%	16	10	37.5%	283	80	71.7%
711		17	0	100.0%	289	10	96.5%	17	6	64.7%	280	32	88.6%
712	31	17	2	88.2%	290	45	84.5%	16	10	37.5%	287	88	69.3%
713	55	16	0	100.0%	288	9	96.9%	14	10	28.6%	271	60	77.9%
714		17	4	76.5%	289	39	86.5%	17	9	47.1%	284	71	75.0%
715	51	17	3	82.4%	289	42	85.5%	16	12	25.0%	278	89	68.0%
716		17	5	70.6%	289	33	88.6%	16	4	75.0%	288	60	79.2%
717		16	3	81.3%	284	33	88.4%	14	4	71.4%	268	66	75.4%
718		17	5	70.6%	290	42	85.5%	16	3	81.3%	288	52	81.9%
719	24	17	4	76.5%	290	27	90.7%	17	8	52.9%	282	65	77.0%
761		17	0	100.0%	286	17	94.1%	17	2	88.2%	286	35	87.8%
765		17	0	100.0%	286	12	95.8%	17	1	94.1%	277	40	85.6%
769		17	0	100.0%	284	11	96.1%	17	1	94.1%	280	51	81.8%
770		17	0	100.0%	286	17	94.1%	17	5	70.6%	283	39	86.2%
774		17	0	100.0%	286	8	97.2%	17	3	82.4%	282	65	77.0%
779		17	0	100.0%	32	1	96.9%	17	3	82.4%	32	7	78.1%
784	56	17	1	94.1%	286	33	88.5%	17	9	47.1%	283	114	59.7%
785		17	2	88.2%	286	15	94.8%	17	1	94.1%	284	44	84.5%
790		17	1	94.1%	286	15	94.8%	17	1	94.1%	283	42	85.2%
794		17	0	100.0%	286	22	92.3%	17	1	94.1%	285	58	79.6%
821	18	14	0	100.0%	285	6	97.9%	14	12	14.3%	285	146	48.8%
822	60	16	2	87.5%	287	13	95.5%	16	16	0.0%	287	147	48.8%
1333	117	17	2	88.2%	283	52	81.6%	17	15	11.8%	282	181	35.8%
1340	44	17	2	88.2%	282	14	95.0%	17	13	23.5%	280	96	65.7%
2103		12	0	100.0%	198	11	94.4%	12	1	91.7%	195	23	88.2%
2107		12	4	66.7%	197	37	81.2%	12	1	91.7%	193	27	86.0%
2108		12	0	100.0%	194	19	90.2%	11	2	81.8%	191	29	84.8%
2121		12	1	91.7%	195	32	83.6%	11	4	63.6%	190	45	76.3%
2122		12	3	75.0%	196	37	81.1%	12	4	66.7%	190	35	81.6%
2124	Cncld	10	2	80.0%	157	28	82.2%	9	3	66.7%	153	35	77.1%
2150	21	12	0	100.0%	201	7	96.5%	12	3	75.0%	201	63	68.7%
2151		12	0	100.0%	201	0	100.0%	12	5	58.3%	201	50	75.1%
2152		12	2	83.3%	199	7	96.5%	12	7	41.7%	193	81	58.0%
2153	14	11	0	100.0%	196	5	97.4%	11	8	27.3%	194	47	75.8%
2154	149	12	1	91.7%	199	15	92.5%	11	7	36.4%	195	86	55.9%
2155	47	11	1	90.9%	191	13	93.2%	11	6	45.5%	184	79	57.1%
2159		12	2	83.3%	198	16	91.9%	12	4	66.7%	193	62	67.9%
2162	101	12	1	91.7%	200	16	92.0%	11	4	63.6%	194	68	64.9%
2163	128	12	0	100.0%	200	15	92.5%	12	8	33.3%	194	80	58.8%
2166	32	12	2	83.3%	200	11	94.5%	12	7	41.7%	198	46	76.8%
2167	16	12	1	91.7%	201	28	86.1%	12	7	41.7%	199	53	73.4%
2168	44	12	3	75.0%	201	17	91.5%	12	5	58.3%	200	47	76.5%

Amtrak On Time Performance

Trains Arriving Through: 7/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2169	76	12	4	66.7%	198	49	75.3%	11	5	54.5%	191	67	64.9%
2170	22	11	2	81.8%	191	14	92.7%	10	3	70.0%	187	45	75.9%
2172	33	11	2	81.8%	187	23	87.7%	11	6	45.5%	183	41	77.6%
2173	44	11	1	90.9%	195	20	89.7%	11	4	63.6%	195	47	75.9%
2190		12	0	100.0%	200	14	93.0%	12	0	100.0%	197	16	91.9%
2193	104	11	1	90.9%	196	26	86.7%	11	4	63.6%	189	67	64.6%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/17/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2124	XHM	Tn Cancelled	CTI	5	CTI	5	XNY-BAL	AM	Follow, MARC, 440, Milepost, 98.2, 95.9	
2150	BOS	21	DET	25	DET	25	XNH-XGX	AM	Catenary failure, Milepost w/Letters, XNH, XGX, OSPRY STICK WAS ON WIRES AT MP90.17 CAUSING CATENARY LOSING POWER ON TRACK 1 BETWEEN BRANFORD AND GUILFORD ON THE NHB LINE. 2150 CONDUCT A 30MPH OVERHEAD CATENARY INSPECTION	
2153	WAS	14	OTH	10	PET	6	XCY-XHM	AM	Scheduled in track usage program, Other, XMO-XHM, OPR 4 TRK A/C ET INSPECTION ON 3 TRK	
2154	BOS	149	DBB	91	DBB	91	NHV-XGX	AM	Stuck open bridges, Bridge, shaws cove, Held at old Saybrook a/c shaws cove bridge broken	
2155	WAS	47	DCS	40	DCS	40	XSH-NYP	AM	Restrictive signal(s) from unknown cause, N/A, Other, XPB, HELD F/AM2154 A/C LOST INDICATION OF LEGGETT INT	
2162	BOS	101	DCS	45	DCS	25	NHV-XGX	AM	Issue with automatic road crossing protection, Milepost w/Letters, nhv, xgx, Stop and protect at state street crossing	
2163	WAS	128	DBB	96	DBB	65	PVD-XGX	AM	Stuck open bridges, Other, XSS, SHAWS COVE BRIDGE FAILURE	
2166	BOS	32	DCS	17	DCS	17	NYP-XSH	AM	Signal suspension, Other, XGG-XPB, HELD AT EAST OF LEGGETT A/C LOST INDICATION OF LEGGETT INTERLOCKING	
2167	WAS	16	DSR	12	MTI	10	PVD-XGX	AM	Disabled train ahead, Milepost w/Letters, pvd, xgx, Disabled AM93 ahead	
2168	BOS	44	DET	16	DET	16	PVD-RTE	AM	Catenary failure, Milepost w/Letters, PVD, RTE, Wires down Hebronville to Holden, Broken Counter Weights PVD-RTE	
2169	WAS	76	CTP	23	CTP	23	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, HELD IN STATION A/C NJX318 DISABLED IN THE SOUTH TUBE	
2170	BOS	22	OTH	12	DSR	9	STM-NHV	MN	Per bulletin Milepost, 41.7, 40.6, 30, 4	
2172	BOS	33	CTP	43	CTP	43	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, NJX318 DISABLED IN THE SOUTH TUBE	
2173	WAS	44	ITI	50	ITI	50	BOS-BOS	AM	Service, turn, or wye train, 2154, Dp BOS late a/c late turn of AM2154	
2193	NYP	104	ITI	73	ITI	73	BOS-BOS	AM	Service, turn, or wye train, 2162, DP BOS late a/c late turn of AM2162	

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/17/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
85	RVM	153	MTI	156	MTI	135	PVD-OSB	AM	Disabled train ahead, Milepost w/Letters, xdr, xm6, Stopped at High street crossover trk 1-2 after AM170 a/c disabled train ahead	
86	BOS	56	DCS	55	DCS	36	KIN-PVD	AM	Issue with automatic road crossing protection, Milepost w/Letters, kin, pvd, stop and protect	
93	NFK	296	ENG	255	ENG	251	MYS-MYS	AM	Air / Brake, E/658, AM 93 DISABLED AND STOPPED EAST OF MYS STATION; UNABLE TO RECOVER - E/658 NOT CHARGING / LOW AIR. TRAIN TO COUPLE SO THEY CAN CONTINUE WEST. THE TRAIN DOES HAVE HEP	
94	BOS	19	HLD	14	DCS	11	ALX-XVG	AM	Restrictive signal(s) from unknown cause Stop, Milepost w/Letters, cfp 111.5, cfp 111.5	
95	NFK	45	CTI	29	DCS	22	XSH-NYP	AM	Restrictive signal(s) from unknown cause, N/A, Other, LEGGETT, RULE 241 PERMISSION A/C LOST INDICATION OF LEGGETT INT	
110	NYP	31	PTI	28	SVS	13	PHL-PHL	AM	Switch private or office cars, Late out of Yard	
125	NPN	44	SMW	26	SMW	15	XSH-XPB	AM	Scheduled in track usage program, Other, XPB, HELD F/AM2154 A/C 2 TRK OOS LEGGETT TO PELHAM BAY	
129	WAS	23	PTI	15	PTI	15	XPV-BAL	AM	Follow, 2163, Milepost, 71.6, 95.7, held for 2163 ahead then followed	
133	WAS	No OS Rpt	ITI	9	ITI	9	NYP-NYP	AM	Service, turn, or wye train, 182, LATE TURN OFF AM182	
137	WAS	52	OTH	46	OTH	37	STM-NRO	MN	Lost time - N.A.R. Arrow system went down for majority of trip and did not update train status. unable to change times and it is giving an error for 37 minutes lost between Stamford and new Rochelle. Tried to change it but won't allow me to adjust times.	
138	NYP	124	MTI	100	MTI	67	BAL-BAL	AM	Disabled train ahead, Milepost, 94, ., held for disposition a/c 2124 disabled ahead on No. 2 track	
141	NFK	No OS Rpt	FTI	29	FTI	29	RVR-PTB	CS	Follow Milepost, 5.0, 20.9, i031	
171	RNK	91	PTI	30	PTI	30	CVS-LYH	NS	Meet 66, Control Point, Teel	
172	BOS	94	DBB	46	DBB	22	OSB-OSB	AM	Stuck open bridges, Control Point, xss, stopped a/c of malfunction of shaws cove bridge not closing	

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
173	WAS	152	MTI	103	MTI	82	KIN-KIN	AM	Disabled train ahead, Control Point, kin, Stopped at KIN a/c disabled train AM93 ahead
177	PHL	No OS Rpt	ITI	34	ITI	34	BOS-BOS	AM	Service, turn, or wye train, 172, TURN OF LATE #172
182	NYP	18	OTH	12	OTH	9	XHM-EWR	AM	Lost time - N.A.R., NO DELAY REPORTED PER CETC-8
186	NYP	31	PTI	19	PTI	14	XHM-MET	AM	Follow, AM138, Other, XCY-MET, FLWD AM138 ON NO.1 TRK
190	BOS	29	DET	27	DET	27	NHV-NLC	AM	Catenary failure, Milepost w/Letters, NHV, NLC, CANNOT HOLD CATENARY POWER ON TRACK 1 BETWEEN BRANFORD AND GUILFORD ON THE NHB LINE. AM 2150 STOPPED TO INSPECT OCS
192	NYP	34	ENG	33	ENG	33	WAS-WAS	AM	HEP, 618, shopped on arrival, waiting on replacement motor from the pit
196	NYP	95	MTI	85	MTI	37	BAL-XPV	AM	Disabled train ahead, Milepost, 94, ., received transfer from disabled 2124
197	WAS	19	MTI	22	MTI	22	ABE-BAL	AM	Disabled train ahead, Milepost, 94, ., single track a/c 2124 disabled on 2 trk
474	SPG	32	DMW	16	DMW	16	WFD-MDN	AM	Held for or routed around MW work or equipment, Milepost w/Letters, WFD, MDN, Held at Holt for AM475 to clear single track WFD-MDN
475	NHV	19	OTH	12	PTI	7	SPG-WNL	AM	Meet, 56, Other, SWEENEY, waited for AM56 to clear over the diamond
486	GFD	87	CON	6	CON	6	NHV-NHV	AM	Hold for connecting train, Held for late conx of AM86
494	GFD	25	CON	31	CON	31	NHV-NHV	AM	Hold for connecting train, Held for conx of AM94
52	LOR	38	FTI	65	FTI	58	XOU-XFL	CS	Meet IO-31, IO137, Control Point, New Hope
79	CLT	50	ENG	65	ENG	65	WAS-XVG	AM	Other electrical failure, 77, BRAKE VALVE ON DSL 77. HAD TO REVERSE BACK IN THE STATION TO SWITCH DSL'S
80	NYP	167	MTI	67	MTI	49	BAL-XPV	AM	Disabled train ahead, Milepost, 94, ., received transfer from disabled 2124
652	NYP	23	CTP	31	CTP	31	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, NJX318 DISABLED IN THE SOUTH TUBE
653	HAR	12	FTI	9	FTI	9	MID-HAR	AM	Meet, ., Control Point, .

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/17/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
681	BRK	13	PTI	10	PTI	10	POR-FRE	CS	Meet 684, Other, congress	
684	BON	18	DCS	8	DCS	8	HHL-WOB	MT	Restrictive signal(s) from known wayside signal failure Run time down., Stop, Control Point, clark	
63	TWO	34	SVS	28	SVS	28	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C SERVICING	
68	NYP	49	WTR	45	WTR	45	SLQ-RSP	CN	Heat order Milepost, 42.7, 0	
69	MTR	-12	PTI	57	PTI	35	FED-XWH	DH	Meet 290, Control Point, 58	
233	ALB	48	ITI	24	ITI	24	NYP-NYP	AM	Service, turn, or wye train, 236, LATE TURN OFF AM236	
234	NYP	24	CTI	20	CTI	20	POU-CRT	MN	Follow mnrr, local, Milepost, 72, 34	
236	NYP	28	POL	17	POL	17	HUD-HUD	AM	Removal of passenger by police Had fare evader removed	
239	ALB	62	ITI	37	ITI	37	NYP-NYP	AM	Service, turn, or wye train, 290, LATE TURN OFF AM290	
241	ALB	25	DSR	11	DSR	6	CRT-POU	MN	Per bulletin Milepost, 39.6, 40.0, 30, 1&2, Milepost, 40.0, 40.6, 2, 30, Milepost, 56.2, 56.3, 30, 1&2, Milepost, 65.0, 65.3, 30, main, Milepost, 73.5, 73.8, 30, main	
243	ALB	61	DCS	53	DCS	53	NYP-NYP	AM	Power switch failure, Other, XHR-NYP, DELAYED DUE TO 749SW FAILURE , TRAIN WAS RE-ROUTED FROM LINE 1 TO THROUGH THE LOOP TO LINE 3, THEN SWUNG TO A LOWER TRACK IN NYP STATION.	
244	NYP	22	CTI	15	CTI	12	POU-CRT	MN	Follow MNRR, Control Point, 53, Control Point, 35	
283	NFL	21	FTI	31	FTI	22	XSV-ROC	CS	Follow I003, Milepost, 332, 370	
290	NYP	25	DSR	29	OTH	17	XSD-NYP	AM	Lost time - N.A.R., NONE	
291	BTN	20	DSR	21	RTE	13	SDY-SDY	AM	Inability to contact dispatcher Stop signal cpf 485 for unknown reason. Initially unable to contact cp dispatcher., Control Point, cpf 485	
43	PGH	49	ENG	21	WTR	17	JST-LAB	NS	Pack saddle slide fence activation Milepost, 288, 300	
72	RGH	16	FTI	17	FTI	17	BNC-DNC	NS	Meet Control Point, Funston, 51E	
89	SAV	48	PTI	38	ENG	22	PTB-RMT	CS	Other electrical failure Communication cable came out of engine set off dragging equipment detector A82.6. Cable head tore off. Extra in engine no good as well. Got one off 90 as they passed us., 18	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/17/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
97	MIA	75	WTR	92	WTR	66	BAL-XNY	AM	Storm, Milepost, 127, 127, TOL over the 32 switch reverse	
55	WAS	210	FTI	121	FTI	100	CLA-CLA	NE	Held at Station to the stall freight train on the main line rescue engines and route NECR, Other, CLA Sta	
56	SAB	110	DSR	70	DSR	49	ESX-SAB	NE	Per bulletin Milepost, 117, 126, 10, main, Milepost, 126, 127, 25, main	
40	CHI	139	TRS	95	TRS	95	MIA-MIA	FL	Trespasser strike Trirail had an incident at Pompano, Control Point, Pompano	
41	MIA	94	FTI	136	FTI	45	ALC-PGH	NS	Meet 39 N, Control Point, Enon	
5	EMY	117	WTR	164	WTR	99	OMA-LNK	BN	High winds High winds at 70mph, Milepost, 16, 46.0, Milepost, 35.1, 60.0	
6	CHI	143	DSR	133	ITI	45	EMY-EMY	UP	Service, turn, or wye train 5, Dirty train	
529	SJC	23	FTI	14	FTI	14	RSV-SAC	UP	Meet 6027 EB UP, Control Point, Citrus Heights, Z	
541	SJC	28	POL	23	POL	23	OAC-OAC	UP	Fire department hold Fire near the ROW approx MP 21 with report of fire hoses across the tracks.	
543	SJC	15	PTI	15	MBO	13	SUI-MTZ	UP	For maritime traffic Control Point, cprv 035	
503	EUG	21	DMW	24	DMW	24	SLM-SLM	UP	Hold for defect repair Held for bridge inspection at 698.10., Milepost, 698.10, 698.10	
516	VAC	41	MBO	23	MBO	23	XF2-X1J	BN	For maritime traffic Bridge, Fraser River Bridge	
518	VAC	17	PTI	18	FTI	10	EDM-EVR	BN	Meet BNSF 6974, Control Point, Howarth Park, Z	
59	NOL	228	FTI	98	ENG	74	CHI-CHI	AM	Picked up extra engine 53	
7	SEA	72	FTI	113	FTI	32	MAL-HAV	BN	Blocked from station track CN 8837W, Control Point, Havre E	
8	CHI	47	FTI	77	SVS	47	MOT-MOT	BN	Routine inspections	
27	PDX	-64	DSR	6	DSR	5	SPK-XPW	BN	Per bulletin Milepost, 74.6, 74.8, 40, Main Track, Milepost, 75.7, 75.9, 30, Main Track, Milepost, 81.3, 81.4, 50, Main Track, Milepost, 35.8, 36.0, 60, Main Track, Milepost, 42.1, 42.2, 30, Main Track, Milepost, 44.1, 44.3, 30, Main Track	
821	FTW	18	FTI	28	FTI	12	PVL-ADM	BN	Follow bnsf, Control Point, sovereign	
822	OKC	60	DSR	62	DSR	27	GLE-ADM	BN	Per bulletin Milepost, 413.6, 450, 40, m	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
329	MKE	48	CTI	36	CAR	17	CHI-CHI	AM	Door 4206, Door seal not allowing to close to point where engine allowed movement. Forced door closed and locked it and door alarm stopped. Still leaking air at seal
332	CHI	58	ITI	39	ITI	39	MKE-MKE	CP	Service, turn, or wye train 329
335	MKE	14	CTI	11	CTI	11	GLN-XRO	ME	Follow Going to the Fox Lake subdivision, Metra, 2117, Milepost, 21.1, 31.1
341	MKE	20	ITI	19	ITI	19	CHI-CHI	AM	Service, turn, or wye train 1340
350	PNT	24	DSR	13	SVS	10	CHI-CHI	AM	Water, commissary, toilet/trash dumping COMMISSARY LATE TO BOARD STOCK., Other, CUS
352	PNT	28	TRS	29	TRS	29	XTF-XH6	NS	Dump truck struck viaduct in 10mph CP518 Control Point, 518
355	CHI	40	FTI	37	FTI	13	XMC-XPI	NS	Cross Traffic short timer, Control Point, 482
365	CHI	33	FTI	25	FTI	13	LNS-BTL	CC	Cross Traffic CN, Milepost, 192, 192
370	GRR	48	MBO	28	MBO	28	XTF-XH6	NS	For maritime traffic Control Point, 509
371	CHI	32	FTI	35	FTI	35	XPI-XH6	NS	Follow Control Point, 487, Control Point, 501, 29G
573	LAX	27	TRS	23	TRS	23	OSD-OSD	SN	Trespasser hit emergency fuel shutoff on CDTX 2121 Required extensive restart procedures., Other, OSD
587	LAX	43	CTI	35	CTI	35	OSD-X98	SC	Meet metrolink, 624, Control Point, songs
595	LAX	37	ITI	26	ITI	26	SAN-SAN	SN	Service, turn, or wye train 784
784	SAN	56	PTI	59	PTI	50	SNC-SNP	SC	Meet Amtk 587, Siding, Serra
702	BFD	29	FTI	31	DSR	18	MDR-FNO	BN	Per bulletin Milepost, 1009.7, 1008.3, 25, Main, Milepost, 1008.3, 1002.2, 15, Main
710	BFD	83	FTI	33	DSR	16	MDR-FNO	BN	Per bulletin Milepost, 1009.7, 1002.2, 25, MT
712	BFD	31	FTI	29	FTI	15	MDR-FNO	BN	Meet 6515, Siding, Figarden
713	OKJ	55	PTI	23	DSR	14	FNO-MDR	BN	Per bulletin Milepost, 1002.2, 1008.3, 25, MT
715	OKJ	51	FTI	41	FTI	37	WAC-COC	BN	Meet bnsf 6804, Control Point, west Allens worth
719	OKJ	24	PTI	27	PTI	16	BFD-WAC	BN	Meet How the Bakersfield for 712 DISPATCHER line them in first, 712, Other, Bakersfield Amtrak
3	LAX	109	DSR	92	WTR	38	FLG-KNG	BN	Flash flood warning Milepost, 344.5, 381
4	CHI	361	WTR	172	WTR	82	NEW-NEW	BN	Flood / washout Other, Newton station

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
305	STL	28	FTI	27	FTI	25	BNL-LCN	UP	Meet UP7889, Other, MCLEAN
382	CHI	18	FTI	22	FTI	22	QCY-MAC	BN	Cross over or go around 7992, Control Point, Ewbanks, BNSF
392	CHI	22	DCS	37	DCS	37	CEN-EFG	CC	Restrictive signal(s) from unknown cause Had to flag it after PTC stopped train then called PTC to report issue. Clear at 226.6, Stop, Control Point, kinmundy
311	KCY	29	DSR	14	PTI	14	JEF-SED	UP	Meet Amtk 318, Siding, Shell
316	STL	43	FTI	51	FTI	40	LEE-WAR	UP	Meet UP 5335, Siding, Strasburg
1333	MSP	117	DSR	62	ITI	44	CHI-CHI	AM	Service, turn, or wye train 332
1340	CHI	44	DSR	53	DSR	18	CBS-MKE	CP	Per bulletin Milepost, 150.5, 146.8, 10, 2

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/17/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	656	07/17	(No OS)		
MIA	98	07/17	8	8	Air / Brake Could not release brakes to perform Pre Departure Test. Had to call mechanical for assistance, 315
NPN	186	07/17	8	8	Hold for thruway bus
PHL	110	07/17	13	13	Switch private or office cars, Late out of Yard
RNK	66	07/17	70	70	Dispatcher not at their desk to give permission for us to leave storage facility Other, RNK storage track
SAV	90	07/17	4	4	Loading problem Door seal needed cut out. All doors were locked closed, 174
WAS	112	07/17	9	9	Other late crew, CREW REFUSED TO BOARD DUE TO FLAG
WAS	136	07/17	31	31	HEP, 653,612,659, TRAPPED AIR AND 480 ISSUES
WAS	192	07/17	33	33	HEP, 618, shopped on arrival, waiting on replacement motor from the pit
WAS	196	07/17	(No OS)		
ALB	234	07/17	9	9	Air conditioning not working. Cab was extremely hot. Mech. rectified situation 700
BOS	171	07/17	12	12	Routine inspections, Depart BOS late a/c late release from SHSY, cause under investigation
BOS	177	07/17	34	34	Service, turn, or wye train, 172, TURN OF LATE #172
BOS	2173	07/17	50	50	Service, turn, or wye train, 2154, Dp BOS late a/c late turn of AM2154
BOS	2193	07/17	73	73	Service, turn, or wye train, 2162, DP BOS late a/c late turn of AM2162
NYP	63	07/17	28	28	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C SERVICING
NYP	133	07/17	9	9	Service, turn, or wye train, 182, LATE TURN OFF AM182
NYP	181	07/17	5	5	Cross Traffic, NJT, NJX375, Other, NYP-NYP, NJX375 XING AHEAD AT TENTH AVENUE
NYP	197	07/17	14	14	Scheduled in track usage program, Other, NYP-NYP, OUT LATE HELD AT "F" FOR AM94 TO CLEAR LINE 1 A/C LINE 2 O/O/S
NYP	233	07/17	24	24	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	239	07/17	37	37	Service, turn, or wye train, 290, LATE TURN OFF AM290
NYP	243	07/17	42	42	Loading problem, 121, LATE FROM SSYD A/C LOADING ISSUES WITH ENG.121
CHI	329	07/17	17	17	Door 4206, Door seal not allowing to close to point where engine allowed movement. Forced door closed and locked it and door alarm stopped. Still leaking air at seal
CHI	341	07/17	19	19	Service, turn, or wye train 1340
CHI	350	07/17	10	10	Water, commissary, toilet/trash dumping COMMISSARY LATE TO BOARD STOCK., Other, CUS

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/17/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	1333	07/17	44	44	Service, turn, or wye train 332
MKE	332	07/17	47	39	Service, turn, or wye train 329
MKE	332	07/17	47	8	PTC problem or failure (cause unknown) Initialization failure
PDX	28	07/17	4	4	Toilet 2815 toilets not working before departure. Mechanical tried to fix, 31024
PNT	355	07/17	10	10	HEP ID4127, No HEP to car. Running on battery power. Troubleshooting with CNOC and PNT mechanical.
SEA	8	07/17	30	30	Routine inspections Train got wyed late.
LAX	14	07/17	5	5	Hold for connecting train 3
SAN	595	07/17	26	26	Service, turn, or wye train 784

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	95.2	No Data	No Data
CDOT	95.0	No Data	No Data	96.4	No Data	No Data
MARC	95.0	69.6	78.7	83.5	56	17
SEPTA	95.0	96.8	96.5	96.2	219	7
NJT-NED	95.0	96.2	91.2	95.2	369	14
NJT-SED	95.0	100	98.0	91.2	24	0

Operating Highlights

Train 66(17) Washington, DC - Car Failure

18JUL25: Train 66(17) was delayed departing Washington, D.C. due to the yard crew had difficulties separating the diesels during the headend change. Then the 10-c paperwork was left with the diesel, causing an additional delay prior to departure.

Train	Delay	Comment
66(17)	52"	

Train 66(17) North Lynchburg, VA - Freight Train Interference

18JUL25: Train 66(17) was delayed beginning 29 miles north of Lynchburg, VA on the Norfolk Southern Alexandria-Montview Subdivision due to following freight unit 24X between MP143.7 to MP126.8.

Train	Delay	Comment
66(17)	54"	

Train 243(17) New York, NY - ITD/ Late Yard Release

18JUL25: Train 243(17) E/121, 5 cars, E/701, was delayed departing New York, NY due to a late yard release account of loading problems with engine E/121.

Train	Delay	Comment
243(17)	42"	

Train 49/449(17) West of Schenectady, NY - Engine Failure

17JUL25: Train 49/449(17) E/119, E/111, 11 cars, was delayed 8 miles west of Schenectady, NY at MP168.3 on the Amtrak Hudson Line due to brake issues. After troubleshooting with mechanical, crew was able to resolve and continued west.

Train	Delay	Comment
49/449(17)	53"	

Train 494(17) New Haven, CT - Hold for Connection

18JUL25: Train 494(17) was delayed departing New Haven, CT due to holding for connections from late 94(17).

Train	Delay	Comment
494(17)	31"	

Train 2124(17) Baltimore, MD - Engine Failure

18JUL25: Train 2124(17), TS18, PC/2023, 6 cars PC/2025, became disabled at approximately 7:05P-ET 1.7 miles north of Baltimore, MD at MP94 on the Amtrak PW Line. Crew reported both MCB's opened on Lead and Trail power cars, putting the train into emergency. There were approximately 250 passengers onboard and head end power remained intact. An Amtrak Road Foreman was dispatched to the scene, while crew worked with High Speed Rail mechanical to try to resolve issue. Train 196(17) was held behind 2124(17) in case a passenger transfer was necessary, with a rescue engine being sourced from Baltimore. Unable to resolve, the decision was made to terminate the train and transfer all passengers to the next 3 northbound trains 196/80/138(17) account of space availability. The passenger transfer was complete at 917P-ET, with 138(17) taking the last remaining passengers off of Train 2124(17). At 1045P-ET, The crew was able to restore power and departed with 2124's equipment back to Washington.

Due to this equipment being shopped, Acela Service Cancellations were necessary due to no replacement equipment. Trains 2103(18), 2108(18) and 2121(18) were all cancelled in their entirety with no alternate transportation provided.

Train	Delay	Comment
138(17)	1'40"	
196(17)	1'22"	
80(17)	1'04"	
192(17)	10"	
90(17)	07"	
186(17)	04"	
85(17)	21"	
193(17)	06"	
197(17)	22"	
173(17)	21"	
93(17)	19"	
2169(17)	03"	
2 MARC's	12-13"	
2124(17)	Terminated at MP94	

Train 2193(17) Boston, MA - Initial Terminal Delay

17JUL25: Train 2193(17) TS17, PC/2011, 6 CARS, PC/2022, was delayed departing Boston, MA due to the late turn off Train 2162(17) that arrived at Boston late account of needing to WYE at PHL due to lead PC/2022 going offline. Due to this, Train 2193(17) was looped at Boston prior to departure which caused an additional delay.

Train	Delay	Comment
2193(17)	1'13"	

Train 136(17) Washington, DC - Trainline Issue

17JUL25: Train 136(17), E/653, E612, 8 cars, E/659, was delayed departing Washington, D.C. due to train line 480 issues. Mechanical arrived on scene to troubleshoot and was able to resolve, allowing Train 136(17) to depart Washington.

Train	Delay	Comment
136(17)	31"	

Crossing Gate Failure at New London, CT - Signal

17JUL25: At approximately 2:05PM-ET, new London dispatcher reported State Street Crossing gate snapped off at New London, CT/MP122.8 causing delays to multiple trains. At 428P-ET, C&S reported State St. crossing working as intended.

Train	Delay	Comment
137(17)	15"	
2162(17)	45"	
2169(17)	20"	
2167(17)	07"	
86(17)	53"	
93(17)	11"	

Train 66(17) Roanoke, VA - Dispatcher Medical Emergency

17JUL25: Train 66(17) was delayed in the yard track at Roanoke, VA/MP257.6, on the NSRR Roanoke Terminal Subdivision, due to inability to contact their dispatcher. NS reported the issue was due to a medical emergency experienced by one of the dispatchers and worked to get another dispatcher to line Train 66(17) into the station. At 5:33PM, Train 66(17) departed Roanoke.

Train	Delay	Comment
66(17)	1'10"	

NHB Line Loss of OCS - East of Providence, RI

17JUL25: at approximately 342P-ET, Mainline dispatcher reported lost communication at Brayton and Orms. C&S arrived on scene to take local control and troubleshoot. Emergency plate order was in effect on tracks 1 and 3 from Hebronville to Holden with trains operating around on tracks 2 and 4, causing multiple trains to be delayed through the area. Wire reported down on Track 1 at MP197.34 and E.T. was dispatched to location. It was determined the wire was down account of broken weights. At 401A-ET, the catenary was reported repaired.

Train	Delay	Comment
177(17)	07"	
2168(17)	16"	
2173(17)	15"	
2193(17)	03"	
86(17)	04"	
67(17)	10"	
2162(17)	11"	
175(17)	08"	
172(17)	16"	
174(17)	20"	
2166(17)	04"	

Train 97(16) DeLand, FL - Commuter Train Interference

17JUL25: Train 97(16) received delays between Deland, FL/MP750.1 and Winter Park, FL/MP785.7, on the CFRC Orlando Subdivision, following CFRC 323.

Train	Delay	Comment
97(16)	33"	

Train 55(17) Claremont, NH - Freight Train Interference

17JUL25: Train 55(17) held at the Claremont, NH station/MP162.0, on the NECR Palmer Subdivision, due to freight interference. NECR 600 was disabled on the single main line at MP160.0. Unable to recover. Extensive delay incurred due to the freight crew having to van to Bellows Falls to pickup a rescue freight locomotive. Once the rescue locomotive was added, NECR 600 was able to clear the main line to allow Train 55(17) to continue south.

Train	Delay	Comment
55(17)	2'03"	Witronix

Train 93(17) Mystic, CT - Engine Failure / Shaws River Bridge Malfunction

17JUL25: At 10:48AM, Train 93(17), E/658-8 Cars, stopped just east of the Mystic, CT station/MP132.3, on the Amtrak NHB Line, at MP132.4 with engine issues. The crew reported E/658 was not charging and low on air. The train did have head end power with 330 passengers onboard. The issue was unable to be resolved so rescue E/634 was dispatched from New Haven departing at 11:14AM. One car was able to be spotted onto the platform allowing customers to get off the train and stretch their legs. An Amtrak Trainmaster and Road Foreman were on scene to coordinate. Service recovery was enacted consisting of comping items from the café car.

At 12:00PM, The New London Dispatcher reported that the Shaw's Cove Bridge at MP122.5, 0.4 miles west of the New London, CT station/MP122.9 was unable to lock for rail traffic. B&B responded quickly but spent a lot of time troubleshooting. The issue was found to be a broken screw jack which required come-alongs to get it closed and locked. The estimated track opening was set for 2:00PM. During this time, all traffic came to a halt. The rescue E/634 enroute to Train 93(17), along with trains 85(17), 2163(17), 173(17), 2154(17), and 172(17) were all heavily delayed during this time. At 1:56PM, the bridge was able to finally close and lock to allow rail traffic to resume. Also to note, Train 85(17) accommodated Train 93(17)'s downline passengers between New London and New York.

At 2:30PM, rescue E/634 arrived to Train 93(17) in order to couple up. At 3:00PM, Train 93(17) was back on the move west operating 4 hours and 14 minutes late.

Train	Delay	Comment
93(17)	4'11"	Disabled
85(17)	2'15"	Bridge
2173(17)	50"	ITD BOS - Turn of 2154(17)
177(17)	34"	ITD BOS - Turn of 172(17)
2163(17)	1'36"	Bridge
2154(17)	1'31"	Bridge
173(17)	1'22"	
172(17)	46"	Bridge

Train 79(17) Washington, DC - Engine Failure

17JUL25: Train 79(17), E/77-7 Cars, departed Washington Union Station on time then stopped just inside of the tunnel due to the brakes not releasing. The train shoved back to the station for mechanical to respond and troubleshoot. The issue was unable to be resolved so E/77 was cut and placed with E/194. At 12:13PM, Train 79(17) departed the station a second time operating 1 hour and 05 minutes late.

Train	Delay	Comment
79(17)	1'05"	

CSX Heat Orders

17JUL25: CSX Issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Alleghany, Baltimore Terminal, Capital, Kanawha, Metropolitan, Mohawk, New River, Old Main Line, RF&P, and Syracuse Terminal.

Train	Delay	Comment
63 (17)	06"	
53 (17)	21"	
79 (17)	06"	
80 (17)	27"	
90 (17)	16"	
95 (17)	12"	
125 (17)	25"	
138 (17)	10"	
141 (17)	18"	
171 (17)	02"	
186 (17)	07"	
281 (17)	22"	
283 (17)	16"	
41 (16)	36"	
40 (16)	12"	

Amtrak NYS Line - Signal Loss at Leggett Interlocking

17JUL25: At 10:18AM, the Amtrak NYS Line experienced signal loss at the Leggett Interlocking/MP9.5. Trains 95(17) and 2154(17) were the first trains stopped getting 241 permission at Leggett with instructions to stop and inspect the switch point. A C&S Maintainer arrived shortly after and reported unable to take local control. All trains received delays single tracking and operating with 241 permission during this time. At 11:40AM, control of Leggett Interlocking was returned to the Section A Dispatcher. All functions were restored.

At 3:45PM, Leggett interlocking lost communication again. During this time, 2163(17) and 2166(17) were delayed. C&S responded arriving to scene at 4:25PM to take local control allowing both trains to continue through the area.

Train	Delay	Comment
95 (17)	22"	
2155 (17)	40"	
2154 (17)	48"	
172 (17)	14"	
2166 (17)	17"	
2163 (17)	17"	

Train 40(16) Denmark, SC - Engine Failure

17JUL25: Train 40(16), E/124-E/126-10 Cars, was delayed at Denmark, SC/MP409.9, on the CSX Columbia Subdivision, after trail E/126 stopped loading, attaining maximum of only 19 amps. E/126 issue was unable to be resolved and was only able to provide head end power for the duration. As a result, an engine change was completed at Washington, DC/MP136.0, on the Amtrak WT Line, cutting E/124-E/126 and adding E/340-E/372.

After the engine swap, upon departure from Washington station, there was an air issue that led to half of the set not releasing, placing the train into penalty. A rescue motor pulled the train back in to Washington terminal, where mechanical was able to repair the air. Once resolved, Train 40(16) departed Washington.

Train	Delay	Comment
40 (16)	14"	DNK
40 (16)	13"	DNK-WAS
40 (16)	2'40"	WAS

Loss of OCS East of New Haven, CT - Catenary or Wayside Failure

17JUL25: at approximately 9:40A-ET, Shoreline Dispatcher reported no overhead power on track 1 between Branford/MP81.5 and Guilford/MP90.4 on the Amtrak NHB Line. ET responded to the scene and found an Osprey stick in the catenary at MP90.17. Multiple trains were delayed due to this. at 10:33A-ET, power was restored and normal operations resumed.

Train	Delay	Comment
2150 (17)	25"	
170 (17)	13"	
171 (17)	27"	
190 (17)	27"	

Maintenance of Way Highlights

Train 55(17) South of St. Albans, VT - M of W Work

17JUL25: Train 55(17) was delayed starting 4.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, due to a 10MPH speed restriction from MP128-MP119 due to Maintenance of Way working in the area.

Train	Delay	Comment
55(17)	49"	

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
151	CVS	1	LYH	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 236(17) Passenger Removal at Hudson, New York –Fare Evader

17JUL25, Passenger on PNR Unknown, traveling from Albany, NY to New York, NY was removed from the train by Hudson PD. The passengers didn't have a ticket and didn't purchase one when asked to do so. The conductor told the passenger she would have to get off at the next stop and the passenger refused to do so. Amtrak Police notified.

Delay: **236 (17)** **17"**

Train 2122(17) Passenger Removal at Baltimore, Maryland –Fare Evader

17JUL25, Passenger on PNR Unknown, traveling from Washington, DC to Baltimore, MD was removed from the train by APD. The passengers didn't have a ticket and didn't purchase one. The passenger became verbally abusive to the onboard crew. Amtrak Police notified.

Delay: **2122 (17)** **None**

Train 19(17) Passenger Removal at Greensboro, North Carolina –Medical

17JUL25, Passenger on PNR 909396, traveling from Greensboro, NC to New Orleans, LA was removed from the train by Greensboro fire dept. The passenger approached the conductor and told him she wasn't feeling well. the conductor asked if medical attention was need and the passenger then

became disoriented and passed out in the conductor's arms.
Police notified.

Amtrak

Delay: 19(17) 17"

Western Region

Operating Highlights

Train 58(17) South of Newbern-Dyersburg, TN - Freight Train Interference

18JUL25: Train 58(17) was delayed 15 miles south of Newbern-Dyersburg, TN, on CN Fulton subdivision, due to a freight train that went into emergency after possibly striking debris on the tracks. The last 4 cars of the disabled grain train sustained damage underneath and were leaking grain. Train 58(17) operated up to the freight train, inspecting the whole way, and reported multiple trees down in the area. CN personnel responded to inspect the freight cars and the tracks in the area. Once the freight recovered and the tracks were inspected, the freight was able to proceed, clearing a route for Train 58(17).

Train	Delay	Comment
58(17)	2'19"	

Train 587(17) South of San Clemente Pier, CA - Commuter Train Interference

18JUL25: Train 587(17) was delayed meeting Metrolink train 624 at Control Point Songs, on SCRRA San Diego subdivision. Once the Metrolink train cleared, train 587(17) was able to proceed.

Train 784(17) was delayed North of Oceanside, CA, on SCRRA Orange subdivision, meeting 784(17) at Serra siding.

Train	Delay	Comment
587(17)	35"	Meeting MetroLink Train
784(17)	50"	Meeting 587(17)

Train 3(16) West of Raton, NM - Miscellaneous Amtrak Responsible

18JUL25: Train 3(16) was delayed on the BNSF Raton subdivision, between Raton, NM and Las Vegas, NM due to storms in the area causing flash flood warnings. The BNSF also reported that due to the lightning they were had signal failure in the area as well, causing train 3(16) to receive unfavorable signals between MP694 and MP714.

Train 4(16) was delayed operating through the same weather restrictions and signal issues.

Train	Delay	Comment
3(16)	35"	Signal Issues
3(16)	45"	Flash Flood Warnings
4(16)	50"	Signal Issues
4(16)	22"	High Wind Warning

Train 822(17) North of Gainesville, TX - Heat Restrictions

17JUL25: Train 822(17) was delayed between MP 413.5X and MP 462.0 on the Burlington Northern Santa Fe Red Rock Subdivision, starting 3 miles north of the Gainesville, TX station, due to severe heat restrictions. The train was limited at 40 mph maximum authorize speed through the limits.

Train	Delay	Comment
822(17)	48"	

Train 22(17) Mineola, TX - UPRR Freight Derailment West of Longview, TX

17JUL25: Train 22(17) was delayed holding at Mineola, TX, on UP Mineola subdivision, due to a UP freight derailment of 18 cars west of Longview, TX, at MP90.2. UP reports 18 cars derailed on a single main track. As a result of the derailment, train 22(17) was routed through Pine Bluff subdivision, which bypassed Longview and Marshall Texas. Alternate bus transportation was secured for those bypassed stops. Bus 1 signed up at Longview at 730pm-ct and operated to Mineola. That bus then took all passengers traveling to Longview and Marshall. A second bus signed up at Marshall at 11pm-ct to take those passengers to Arkadelphia, AR to meet train 22(17). UP pilots were secured to assist with the operation over the Pine Bluff Subdivision.

21(17) Also operated over the Pine Bluff subdivision. UP pilots signed up at Texarkana, AR to assist. 1 ADA bus was secured and signed up at Texarkana at 530am and operated making stops at Marshall, TX, Longview, TX, and finally meeting the train at Mineola, TX.

WBS#: B.TR.100150.5894

Train	Delay	Comment
22(17)	4'06"	Holding at Mineola
22(17)	1'51"	Operating Pine Bluff Detour

Train 715(17) West of Wasco, CA - Freight Train Interference

17JUL25: Train 715(17) was delayed at Allensworth, MP 933.1/BNSF Bakersfield Subdivision, 20.1 miles west of Wasco, meeting BNSF freight train BNSF 6804.

Train	Delay	Comment
715(17)	37"	

Train 316(17) South of Lees Summit, MO - Freight Train Interference

18JUL25: Train 316(17) was delayed 1.5 miles south of Lees Summit, MO, on UP Sedalia subdivision, due to meeting UP7642 at Lees Summit Siding, and then meeting UP5335 at Strasburg siding.

Train	Delay	Comment
316(17)	40"	Strasburg Siding
316(17)	11"	Lee Summit Siding

Train 8(17) Initial Terminal Seattle, WA - Late Inbound Equipment

17JUL25: Train 8(17) was delayed departing Seattle, MP 0.0/BNSF Seattle Subdivision, following a late yard release due to the turning and servicing of equipment off late inbound Train 7(15) which arrived one hour, twelve minutes late at 12:41PM-PT (then equipment spotted in the yard at 2:40pm). Train 8(17) departed Seattle at 5:25PM-PT.

Train	Delay	Comment
8(17)	30"	

Train 11(16) South of Oakland, CA - Close Call with Vehicle

17JUL25: Train 11(16), operating with camera-equipped locomotives E/311-E/347 and 8 cars, emergency braking was applied to avoid striking a garbage truck fouling the the tracks in San Leandro at MP 15.8/UPRR Coast Subdivision, 8.8 miles south of Oakland. There were no injuries to passengers (166) or crew. There was no equipment damage. The truck fled the scene. The train was on-the-move following successful equipment inspection and air test. Amtrak Police notified.

Train	Delay	Comment
11(16)	05"	

Train 14(17) Carpinteria, CA - Injured or Sick Passenger or Employee

17JUL25: Train 14(17) was delayed at the Carpinteria depot, MP 377.6/UPRR Santa Barbara as a result of an onboard passenger medical emergency. Local EMS responded, removed the passenger and transported to Cottage Hospital in Santa Barbara.

Train	Delay	Comment
14(17)	21"	

Train 371(17) East of Chicago, IL - Freight Train Interference

17JUL25: Train 371(17) was delayed between CP 487 / MP CD 487.1 and and CP 501 / MP CD 501.0 on the Norfolk Southern Chicago Terminal Subdivision, starting 37 miles east of the Chicago, IL Union Station, following 29G.

Train	Delay	Comment
371(17)	35"	

Train 21(16) West of Longview, TX - Freight Train Interference

17JUL25: Train 21(16) was delayed at Gladewater / MP 105.5 on the Union Pacific Mineola Subdivision, 16 miles west of the Longview, TX station, due to MARAS-17 (UPRR 6312) experienced an undesired emergency brake application. UPRR Mechanical responded to assist.

Train	Delay	Comment
21(16)	1'42"	

Train 332(17) Milwaukee, WI - System

17JUL25: Train 332(17) was delayed departing the Milwaukee, WI Intermodal Station due to issues initializing the positive train control on lead Locomotive 518. After assistance from troubleshooting, the crew was able to initialize the PTC before departing.

Train 1333(17) was delayed departing the Chicago, IL Union Station due to late arrival of Train 332(17) and the scheduled switching out of Locomotive 518. The replacement was Locomotive 517.

Train	Delay	Comment
332(17)	47"	
1333(17)	44"	

Train 329(17) East of Glenview, IL - Commuter Train Interference

17JUL25: Train 329(17) was delayed between Canal / MP 0.0 and Glenview / MP 17.32 on the Canadian Pacific and Kansas City Subdivision C & M Subdivision following Metra commuter train.

Train	Delay	Comment
329(17)	36"	

Train 392(17) Effingham, IL - Signal

18JUL25: Train 392(17) was delayed 30 miles south of Effingham, IL, on CN Champaign subdivision, due to signal issues of an unknown origin, requiring the train to flag through the affected area. Once train 392(17) cleared the area affected by the bad signals, they were able to proceed at normal speed.

Train 4(15) Lamar, CO - Hlgh Wind/Flash Flood Warnings

17JUL25: Multiple trains were delayed operating through high wind and flash flood warnings due to severe weather on the BNSF La Junta and Seligman subdivisions.

Train 4(15) was delayed between Lamar, CO and Dodge City, KS.

Train 3(16) was delayed west of Kansas City, MO.

Train 3(15) was delayed between Flag Staff, AZ and Kingman, AZ.

Additional flooding occurred continued between Lawrence, KS and Kansas City, MO causing washout at MP 3.9 and MP 1.3 on the Burlington Northern Santa Fe Topeka Subdivision, 22 miles east of the Lawrence, KS station. BNSF MoW responded to the washouts. The initial estimated track opening was at 11:00 a.m. (CDT).

Train 4(15) had arrived at the Newton, KS at 6:25 a.m. (CDT) and held for update before advancing to the Topeka, KS station where they held for track opening.

Supplemental bussing for 4(15). Three supplemental buses secured between Topeka, KS and Chicago, IL.

WBS#: B.TR.100150.5893

Train	Delay	Comment
4(15)	1'02"	
3(15)	1'10"	
3(16)	34"	
4(15)	1'22"	NEW
4(15)	13"	East of LRC - Restriction over Repaired Washouts

Train 8/28(16) West of Sandpoint, ID - Car Failure

17JUL25: Train 8 / 28(16), operating with Locomotive 369, Locomotive 334 and 10 cars, stopped at MP 34.5 on the Burlington Northern Santa Fe Kootenai River Subdivision, 32 miles west of the Sand Point, ID, due to a wayside detector found a chipped wheel under Car 32083. BNSF Mechanical responded and reported the defect was not condemnable. The car was able to continue to Chicago for repair.

Train 7 / 27(15) was delayed at Silver / MP 36.0 waiting on relief crew.

Train	Delay	Comment
8/28(16)	1'39"	
7/27(15)	31"	Silver - Relief Crew

Train 41(16) Chicago, IL - Initial Terminal Delay

17JUL25:Train 41(16) was delayed 30 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(14), replacing a bad order locomotive, and troubleshooting two cars with inoperative toilets. As background, inbound 40(14) arrived in Chicago at 1203pm; 3 hours and 18 minutes late due to 1 hour and 57 minutes of freight train interference, 1 hour and 7 minutes of weather restrictions, 43 minutes for ADA accommodations, and 26 minutes for a maritime bridge lift. Equipment set to the yard for servicing and inspection at 135pm. There were no scheduled program moves. At 335pm, lead engine AMTK 11 was bad ordered for wheel shelling. Blue flags were dropped at 416pm and replacement locomotive AMTK 62 was added in trail at 457pm. At 545pm, mechanical reported bad order toilets on coach 25049. Due to no replacement coaches, c/25049 to deadhead inline with the passengers downgraded (coach to be added in Washington, D.C). At 610pm, mechanical reported bad ordered toilets on sleeping car 62034. Due to no replacement sleepers, c/62034 to deadhead inline with the passengers downgraded. Train 41(16) was released by mechanical at 617pm, shoved from yard at 628pm, and set in the station at 638pm with 229 passengers to board. Train 41(16) departed Chicago at 710pm; 30 minutes late.

Train 41(16) was further delayed 1 mile south of Chicago, IL , due to a traction motor fault that would not reset. The crew worked with CNOC mechanical to resolve. After cycling the power the fault was reset and train 41(16) was able to proceed.

17JUL25: Train 41(16) was delayed at Washington, DC/MP136.0, on the Amtrak WT Line, adding coach C/82985 to the head end. This was to alleviate oversold conditions after coach C/25049 and sleeper C/62034 were bad ordered out of Chicago.

Train	Delay	Comment
41(16)	45"	Traction Motor E/62
41(16)	33"	ITD CHI
41(16)	47"	WAS - Add Car

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

- 370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

- 371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St.

Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

Train 393(16) South of Rantoul, IL - Debris

16JUL25: at approximately 7:24pm-ET, train 393(16) with E/4630, 7 coaches, and 164 passengers, went into emergency on CN, Chicago subdivision after striking a tree 8 miles north of Champaign, IL, at MP120.3. There were no reported injuries of passengers or crew and HEP remained active the entire time. There was minor damage reported of the sander on the motor which was hanging low to the rail and damage to the speed sensor as well. The crew determined that the sander was still high enough above the rail to be in compliance but the speed sensor caused issues with PTC. The crew was unable to resolve the issues with PTC and it was cut out, causing the train to operate a reduced speed of 59MPH from Champaign, IL, to Carbondale, IL.

Train 59(16) was delayed departing Chicago, IL, due to adding a rescue motor to its consist to be dropped off at Carbondale, IL for train 390(17).

Train	Delay	Comment
393(16)	53"	
59(16)	1'14"	
59(16)	1'14"``	CDL - Set-Out Locomotive

Train 3(16) West of Naperville, IL - Engine Failure

16JUL25: Train 3(16), operating with Locomotive 203, Locomotive 40 and 9 cars, was delayed at MP 34.6 on the Burlington Northern Santa Fe Chicago Subdivision, 6 miles west of the Naperville, IL station, due to Locomotive 40 had a locked axle alarm. With assistance from CNOC Mechanical, the crew cut out traction motor #4 and continued.

Train 3(16) was further delayed adding BNSF5173 west of Kansas City, MO, at Argentine fuel rack.

17JUL25: Train 3(16) was delayed at Lamy, NM, due to performing daily inspections on all 3 locos.

Train	Delay	Comment
3(16)	1'13"	Locked Axle/Traction Motor Cutout
3(16)	48"	Adding BNSF Motor
3(16)	1'23"	Operating at Freight Speeds
3(16)	1'30"	Daily Inspections LMY

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
301/306 (03)	-1			Buses ordered for overbooked consists

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike DMG// MP372.5
6 (6)	DEN	155		Trucks cut out// p/up 6 (16)
7 (8)	WTN	348		HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
3 (16)	XAR	BNSF5173	T/M #4 cut out	LAX	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
794	LAX	1	GDL	N/A
4	FMD	1	KCY	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 591(17) Passenger Removal at Irvine, California –Fare Evader

17JUL25, Passenger on PNR 3C0292, traveling from Solana Beach, CA to Oceanside, CA was removed from the train for not having the correct ticket. The passenger had a senior ticket and isn't a senior. The passenger is a habitual fare evader. Amtrak Police notified.

Delay: 591 (17) 3"

Train 3(16) Passenger Removal at Trinidad, Colorado–Fare Evader

17JUL25, Passenger on PNR 23E830, traveling from Chicago, IL to Los Angeles, CA was removed from the train by Trinidad PD. The passengers arguing and cussing and causing a disturbance. The passengers were shoving each other into the diner car. Amtrak Police notified.

Delay: 3 (16) 7"

Train 7(16) Passenger Removal at Stanley, North Dakota–Medical

17JUL25, Passenger on PNR 2F1815, traveling from Chicago, IL to East Glacier, MT was removed from the train by Stanley ND Paramedic. The passenger was having trouble breathing was a possible seizure. Amtrak Police notified.

Delay: 7 (16) 18"

Train 4(16) Passenger Removal at Gallup, New Mexico–Medical

17JUL25, Passenger on PNR 3AC80C, traveling from Winslow, AZ to Chicago, IL was removed from the train by Gallup NM Paramedic. The passenger was complaining of severe leg pain. Amtrak Police notified.

Delay: 4 (16) None

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/17/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	300	26	91%	4,914	425	91%	83,683	6,450	92%
Northeast Corridor	98%	82	14	83%	1,297	172	87%	22,482	2,405	89%
Acela	98%	24	4	83%	362	59	84%	6,277	827	87%
Northeast Regional	98%	58	10	83%	935	113	88%	16,205	1,578	90%
State Supported	98%	191	7	96%	3,151	164	95%	52,574	2,677	95%
Long Distance	98%	27	5	81%	466	89	81%	8,489	1,362	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/17/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	300	26	91%	4,914	425	91%	83,683	6,450	92%
Northeast Corridor	98%	82	14	83%	1,297	172	87%	22,482	2,405	89%
Acela	98%	24	4	83%	362	59	84%	6,277	827	87%
Northeast Regional	98%	58	10	83%	935	113	88%	16,205	1,578	90%
On Spine Northeast Regional	98%	30	6	80%	484	57	88%	8,218	835	90%
Richmond / Newport News / Norfolk	98%	12	4	67%	199	47	76%	3,379	511	85%
Roanoke	98%	4	-	100%	68	4	94%	1,154	154	87%
Springfield Shuttles	98%	12	-	100%	184	5	97%	3,454	78	98%
State Supported	98%	191	7	96%	3,151	164	95%	52,574	2,677	95%
Borealis	98%	2	-	100%	34	5	85%	565	64	89%
Capitol Corridor	98%	28	-	100%	444	12	97%	6,904	147	98%
Carolinian	98%	2	2		34	6	82%	580	48	92%
Cascades	98%	14	-	100%	238	12	95%	3,939	280	93%
Downeaster	98%	10	-	100%	166	1	99%	2,754	45	98%
Empire	98%	20	2	90%	340	23	93%	6,226	323	95%
Adirondack	98%	2	-	100%	34	2	94%	580	43	93%
Berkshire Flyer	98%	-	-	100%	6	1	83%	12	3	75%
Ethan Allen Express	98%	2	-	100%	34	5	85%	580	39	93%
Maple Leaf	98%	2	-	100%	34	2	94%	580	56	90%
New York - Albany	98%	10	1	90%	164	5	97%	3,315	92	97%
New York - Niagara Falls	98%	4	1	75%	68	8	88%	1,159	90	92%
Heartland Flyer	98%	2	-	100%	30	1	97%	572	17	97%
Hiawatha	98%	12	1	92%	197	7	96%	3,310	122	96%
Illinois	98%	12	-	100%	227	15	93%	3,994	271	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	68	2	97%	1,148	45	96%
Illini / Saluki	98%	4	-	100%	68	6	91%	1,148	42	96%
Lincoln Service	98%	4	-	100%	91	7	92%	1,698	184	89%
Keystone	98%	27	-	100%	396	21	95%	6,710	409	94%
Lincoln / Missouri	98%	2	-	100%	34	9	74%	574	84	85%
Michigan	98%	10	1	90%	166	14	92%	2,770	268	90%
Blue Water	98%	2	-	100%	34	4	88%	576	86	85%
Pere Marquette	98%	2	-	100%	32	1	97%	578	26	96%
Wolverine	98%	6	1	83%	100	9	91%	1,616	156	90%
Missouri	98%	2	-	100%	32	1	97%	558	15	97%
Pacific Surfliner	98%	24	-	100%	408	7	98%	6,186	229	96%
Pennsylvanian	98%	2	1	50%	34	7	79%	580	67	88%
Piedmont	98%	8	-	100%	135	-	100%	2,304	32	99%
San Joaquins	98%	12	-	100%	202	18	91%	3,468	199	94%
Vermont	98%	2	-	100%	34	5	85%	580	57	90%
Long Distance	98%	27	5	81%	466	89	81%	8,489	1,362	84%
Auto Train	98%	2	-	100%	34	3	91%	568	96	83%
California Zephyr	98%	2	-	100%	34	11	68%	577	133	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	14	7	50%	246	51	79%
City Of New Orleans	98%	2	1	50%	34	6	82%	566	52	91%
Coast Starlight	98%	2	-	100%	36	1	97%	583	86	85%
Crescent	98%	2	-	100%	34	4	88%	580	68	88%
Empire Builder	98%	4	1	75%	63	9	86%	1,114	142	87%
Floridian	98%	2	1	50%	33	10	70%	490	171	65%
Lake Shore Ltd	98%	2	-	100%	34	10	71%	978	111	89%
Palmetto	98%	2	1	50%	34	3	91%	578	37	94%
Silver Meteor	98%	2	-	100%	34	6	82%	576	114	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	-	100%	34	8	76%	578	145	75%
Sunset Ltd	98%	-	-	100%	14	4	71%	244	43	82%
Texas Eagle	98%	2	1	50%	34	7	79%	650	88	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/17/25										
Day			Month to Date					Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	8	97%	4,935	124	97%	83,714	1,996	98%
Northeast Corridor	98%	82	2	98%	1,297	32	98%	22,434	630	97%
Acela	98%	24	-	100%	362	8	98%	6,279	164	97%
Northeast Regional	98%	58	2	97%	935	24	97%	16,155	466	97%
State Supported	98%	191	4	98%	3,152	49	98%	52,559	869	98%
Long Distance	98%	28	2	93%	486	43	91%	8,583	495	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/17/25											
Day			Month to Date						Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	8	97%		4,935	124	97%	83,714	1,996	98%
Central Division	98%	66	2	97%		1,125	55	95%	19,164	662	97%
Northeast Division	98%	97	2	98%		1,567	27	98%	27,583	641	98%
Southeast Division	98%	68	4	94%		1,083	29	97%	18,513	437	98%
Southwest Division	98%	70	-	100%		1,160	13	99%	18,454	256	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/17/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	8	97%	4,935	124	97%	83,714	1,996	98%
Central Division	98%	66	2	97%	1,125	55	95%	19,164	662	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	39	-	100%	582	2	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	27	1	96%	454	40	91%	7,730	427	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	34	-	100%	558	3	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	16	-	100%	289	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	33	-	100%	562	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	99	3	97%	1,662	12	99%
MSP	98%	1	-	100%	17	1	94%	278	7	97%
PDX	98%	5	-	100%	81	1	99%	1,393	36	97%
PNT	98%	3	1	67%	50	1	98%	797	8	99%
PTH	98%	1	-	100%	17	-	100%	288	6	98%
QCY	98%	2	-	100%	32	-	100%	562	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	137	8	94%	2,264	121	95%
SPK	98%	1	-	100%	17	-	100%	298	2	99%
STL	98%	3	-	100%	61	1	98%	1,138	17	99%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	34	-	100%	555	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	97	2	98%	1,567	27	98%	27,583	641	98%
ALB	98%	7	1	86%	119	1	99%	2,028	26	99%
BON	98%	5	-	100%	83	-	100%	1,347	3	100%
BOS	98%	19	-	100%	303	5	98%	5,420	127	98%
BRK	98%	5	-	100%	56	-	100%	1,317	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	17	-	100%	288	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	31	-	100%	558	-	100%
HFD	98%	2	-	100%	24	-	100%	170	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	17	1	94%	288	6	98%
NFL	98%	2	-	100%	34	-	100%	580	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	80	-	100%	1,487	35	98%
NYP	98%	41	1	98%	659	19	97%	11,653	404	97%
POR	98%	-	-	100%	24	-	100%	24	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	15	-	100%	286	1	100%
SPG	98%	5	-	100%	81	1	99%	1,777	20	99%
TWO	98%	1	-	100%	17	-	100%	287	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	68	4	94%	1,083	29	97%	18,513	437	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	82	1	99%	1,436	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/17/25										
Day			Month to Date			Year to Date				
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	8	97%	4,935	124	97%	83,714	1,996	98%
Southeast Division	98%	68	4	94%	1,083	29	97%	18,513	437	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	191	2	99%	3,136	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	17	-	100%	284	11	96%
MIA	98%	2	1	50%	33	2	94%	558	30	95%
NFK	98%	3	-	100%	48	1	98%	798	4	99%
NOL	98%	2	-	100%	36	1	97%	643	21	97%
NPN	98%	2	-	100%	34	1	97%	553	4	99%
PGH	98%	1	-	100%	17	-	100%	289	3	99%
PHL	98%	5	-	100%	73	3	96%	1,239	36	97%
RGH	98%	4	-	100%	60	-	100%	1,163	5	100%
RNK	98%	2	-	100%	31	-	100%	548	8	99%
RVM	98%	1	-	100%	17	-	100%	281	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	1		15	1	93%	271	1	100%
SFA	98%	1	-	100%	17	-	100%	284	18	94%
WAS	98%	25	2	92%	402	17	96%	6,877	264	96%
Southwest Division	98%	70	-	100%	1,160	13	99%	18,454	256	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	17	-	100%	290	-	100%
bfd	98%	6	-	100%	100	-	100%	1,723	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	17	3	82%	297	23	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	16	-	100%	322	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	51	-	100%	847	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	-	100%	160	1	99%	2,219	63	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	14	-	100%	285	-	100%
OKJ	98%	12	-	100%	188	6	97%	3,041	67	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	223	1	100%	3,454	13	100%
SAN	98%	12	-	100%	202	1	100%	2,624	23	99%
SAS	98%	1	-	100%	17	1	94%	286	3	99%
SJC	98%	7	-	100%	118	-	100%	1,858	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	34	-	100%	567	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	2	-	100%	49	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT DATE 7/17/2025 12:00..	Diesel Locomotive			High Speed Trainset			Electric Locomotives		Amfleet I	Caltrans Locomotives	Surfliner	California Cars (..)	Viewliner II	Grand Total
	ENG	MTI	CCR	ENG	MTI	CAR	ENG	MTI	CAR	ENG	CAR	CAR	CAR	
Air/Brake Problems	241	5					254	82						582
MCB Tripping					530		26							556
HEP Problems	162													162
Loading Problems	77													77
PCS Faults	66													66
Electrical Problems	28			31										59
Door Problems	4								16		10	4		34
Pantograph Problem..							33							33
ACES Failure							30							30
Truck Problems										24				24
M/U Trainline Cabl..	22													22
Car Hot: Air Condi..									19					19
Cab Signal Failure	7		5											12
Engineer Cab Furn..	9													9
Engine Dead/Shut ..								8						8
I-ETMS Problem	7													7
Radio Problems							6							6
Toilets Inoperative						3							3	6
Auxiliary Faults							5							5
Radiator Problems							3							3
Traction Motor Pro..	3													3
Grand Total	626	5	5	31	530	3	357	90	35	24	10	4	3	1,723