



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, July 19, 2025

Rules:1-50



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/18/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/18/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	299	23	92.3%	5,215	636	87.8%	83,922	8,305	90.1%
Central Division	91.5%	65	7	89.2%	1,188	136	88.6%	19,217	1,876	90.2%
Northeast Division	95.0%	95	7	92.6%	1,645	229	86.1%	27,600	2,992	89.2%
Southeast Division	94.5%	68	4	94.1%	1,151	144	87.5%	18,580	1,858	90.0%
Southwest Division	90.5%	71	5	93.0%	1,231	127	89.7%	18,525	1,579	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/18/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	97,180	30,309	69%	1,874,739	611,805	67%	27,260,132	7,329,786	73%
Northeast Corridor	80%	45,559	11,219	75%	810,364	248,290	69%	12,110,774	3,124,936	74%
Acela	82%	9,521	1,492	84%	167,843	50,940	70%	2,521,760	605,606	76%
Northeast Regional	78%	36,038	9,727	73%	642,521	197,350	69%	9,589,014	2,519,330	74%
Richmond / Newport News / Norfolk	73%	12,421	6,509	48%	204,174	86,351	58%	3,094,326	1,058,888	66%
Springfield Shuttles	89%	562	262	53%	7,890	1,868	76%	173,887	26,512	85%
Roanoke	70%	3,038	297	90%	54,991	15,707	71%	809,168	212,932	74%
On Spine Northeast Regional	83%	20,017	2,659	87%	375,466	93,424	75%	5,511,633	1,220,998	78%
State Supported	80%	38,091	10,190	73%	820,728	218,013	73%	11,632,275	2,577,746	78%
Borealis	60%	686	547	20%	11,484	8,018	30%	168,191	71,196	58%
Capitol Corridor	90%	390	8	98%	60,616	5,107	92%	869,811	93,811	89%
Carolinian	60%	1,284	531	59%	18,973	10,934	42%	334,783	139,358	58%
Cascades	60%	2,881	1,168	59%	54,434	15,382	72%	737,314	253,408	66%
Downeaster	82%	1,979	0	100%	33,072	8,345	75%	411,754	101,338	75%
Empire	83%	6,285	2,523	60%	106,737	42,092	61%	1,568,719	344,388	78%
Adirondack	75%	425	27	94%	7,497	4,718	37%	85,492	27,417	68%
Ethan Allen Express	85%	676	384	43%	11,617	7,403	36%	156,828	40,727	74%
Maple Leaf	75%	958	655	32%	16,332	10,063	38%	212,409	65,226	69%
New York - Albany	90%	2,400	912	62%	42,246	11,623	72%	729,222	115,057	84%
New York - Niagara Falls	75%	1,530	412	73%	26,309	6,644	75%	380,142	93,543	75%
Berkshire Flyer	60%	296	133	55%	2,736	1,641	40%	4,626	2,418	48%
Heartland Flyer	70%	336	137	59%	4,631	3,588	23%	64,150	29,651	54%
Hiawatha	90%	2,264	637	72%	38,952	5,484	86%	489,464	64,849	87%
Illinois	78%	2,390	363	85%	50,942	17,771	65%	721,354	174,848	76%
Carl Sandburg / Illinois Zephyr	80%	474	57	88%	8,752	1,819	79%	115,430	14,908	87%
Illini / Saluki	80%	1,037	2	100%	16,999	4,763	72%	255,296	33,634	87%
Lincoln Service	75%	879	304	65%	25,191	11,189	56%	350,628	126,306	64%
Keystone	92%	7,210	0	100%	140,287	12,082	91%	2,105,075	286,764	86%
Lincoln / Missouri	60%	919	11	99%	15,728	9,897	37%	209,705	114,778	45%
Michigan	69%	2,925	360	88%	45,738	12,166	73%	563,753	158,625	72%
Blue Water	70%	638	0	100%	11,305	3,238	71%	139,904	41,130	71%
Pere Marquette	85%	557	179	68%	5,579	1,128	80%	74,655	9,760	87%
Wolverine	65%	1,730	181	90%	28,854	7,800	73%	349,194	107,735	69%
Missouri	80%	327	249	24%	4,757	3,551	25%	63,589	23,039	64%
Pacific Surfliner	85%	1,385	119	91%	126,392	18,401	85%	1,661,001	267,752	84%
Pennsylvanian	72%	1,015	0	100%	17,492	5,334	70%	253,507	67,715	73%
Piedmont	73%	1,291	143	89%	17,844	5,987	66%	327,035	79,409	76%
San Joaquins	73%	2,816	2,217	21%	48,698	24,549	50%	712,510	198,919	72%
Vermont	75%	1,708	1,177	31%	23,951	9,325	61%	370,560	107,898	71%
Long Distance	57%	13,530	8,900	34%	243,647	145,502	40%	3,473,558	1,623,502	53%
Auto Train	57%	800	0	100%	14,983	5,245	65%	217,755	136,448	37%
California Zephyr	45%	1,271	1,271	0%	21,199	17,371	18%	283,842	123,871	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	310	178	43%	4,977	2,551	49%	79,027	39,566	50%
City Of New Orleans	75%	645	329	49%	10,337	4,481	57%	185,137	52,690	72%
Coast Starlight	65%	530	64	88%	18,905	6,128	68%	304,706	126,874	58%
Crescent	60%	1,142	298	74%	19,288	7,380	62%	251,356	64,904	74%
Empire Builder	55%	1,297	1,260	3%	22,001	14,127	36%	276,992	122,630	56%
Floridian	40%	1,510	1,376	9%	28,110	23,617	16%	391,465	287,397	27%
Lake Shore Ltd	70%	1,494	673	55%	20,719	7,844	62%	292,556	80,472	72%
Palmetto	65%	925	899	3%	18,055	9,856	45%	286,203	110,972	61%
Silver Meteor	45%	1,065	933	12%	19,030	12,855	32%	268,416	140,761	48%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	971	964	1%	19,316	15,298	21%	232,252	142,224	39%
Sunset Ltd	50%	622	46	93%	5,332	2,843	47%	76,971	28,639	63%
Texas Eagle	60%	948	609	36%	21,395	15,906	26%	269,285	143,558	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 18, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	133,863	1,879,630	712	1,846,044	30,323,567	609

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	6,755	551,283	123	97,839	8,879,362	110
INFRASTRUCTURE PLANNED	90	3,627	551,283	66	90,773	8,879,362	102
FLEET RELIABILITY	83	23,397	1,879,630	124	292,277	30,323,567	96
TRAIN OPERATIONS	382	100,084	1,879,630	532	1,365,155	30,323,567	450

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 175(18) West of Trenton, NJ - Onboard HBD Alarm

18JUL25: Train 175(18), E/643-9 Cars, stopped 7 miles west of Trenton, NJ on the Amtrak NYP Line, at MP64 to inspect after their onboard hot box detector alarm went off on C/62749. The crew inspected and took no exceptions. They advanced to Philadelphia, PA to have mechanical inspect. Mechanical found a loose flange lube fitting on the F-end truck and was corrected. Train 175(18) continued to Washington operating track speed.

Train	Delay	Comment
175(18)	50"	
175(18)	07"	PHL

Train 494(18) New Haven, CT - Hold for Connection

18JUL25: Train 494(18) was delayed departing New Haven due to waiting for 23 passenger connections from Train 94(18), that arrived New Haven 1 hour and 13 minutes late..

Train	Delay	Comment
494(18)	1'01"	

Train 179(18) Boston, MA - Engine Swap

18JUL25: Train 179(18) was delayed departing Boston, MA due to engine E/660 being swapped out for overheating, replaced by engine E/637. Once engine was complete, Train 179(18) was able to depart.

Train	Delay	Comment
179(18)	40"	

Train 98(18) North Winter Park, FL - Commuter Train Interference

18JUL25: Train 98(18) received delays starting 17.7 miles north of Winter Park, FL/MP785.7, on the CFRF Orlando Subdivision, following a CFRC commuter and Train 52(18) from MP768.1 to MP750.

Train	Delay	Comment
98(18)	26"	CFRC
98(18)	11"	52(18)

Train 40(17) South of Fredericksburg, VA - Freight Train Interference

19JUL25: Train 40(17) was delayed on the CSX RF&P Subdivision due to following fright unit CSX410 Beginning 10 miles south of Fredericksburg, VA between MP49.9 and MP105.1. Train 80(18) was also delayed due to this, following 40(17).

Train	Delay	Comment
40(17)	47"	
80(18)	51"	

Train 56(18) North of Springfield, MA - Passenger Train Interference

18JUL25: Train 56(18) held just north of Springfield, MA/MP98.4, on the CSX Conn River Main Line, at CPR2/MP2.02 to meet Train 55(18).

Train	Delay	Comment
56(18)	32"	

Amtrak NHB Line - Commercial Power Outage

18JUL25: At 3:33PM, the Mainline Dispatcher reported a commercial power outage that resulted in a loss of comms between Brayton, MP184.9 and Orms/MP185.6, on the Amtrak NHB Line. The Providence station/MP185.1 also lost power. C&S arrived to the location at 4:14PM to take local control of the switches. During this time, trains traveling through the area were delayed. At 9:08PM-ET Providence ticket office power was restored. At 9:28PM-ET reported comms were back and C&S released local control.

Train	Delay	Comment
175(18)	10"	
86(18)	04"	
184(18)	05"	
2166(18)	04"	
2173(18)	03"	
177(18)	03"	
174(18)	03"	
2193(18)	03"	
2162(18)	14"	

Train 486(18) New Haven, CT - Hold for Connection

18JUL25: Train 486(18) was delayed departing New Haven, CT holding for the passenger connections from Train 86(18) that arrived at 3:04PM, 45 minutes late.

Train	Delay	Comment
486(18)	32"	

Train 41(17) Washington, DC - Crew

18JUL25: Train 41(17) arrived to Washington, DC, on time and then was delayed due to a Conductor crewing issue. A new Conductor was called and responded to the train quickly. Train 41(17) departed Washington at 2:35PM, operating 52 minutes late.

Train	Delay	Comment
41(17)	52"	

Train 281(18) North of Yonkers, NY - Cab Signals

18JUL25: Train 281(18), E/100-5 Cars-E/704, stopped 1.2 miles north of Yonkers, NY/MP15.2, on the Metro North Hudson Line, at MP16.4 due to E/100 cab signals reported dropping from normal to restricted. The crew recycled the breakers which was thought to have resolved the issue. Train 281(18) was back on the move for 1.8 miles until stopping again with the same issue at MP18.2. Permission was granted for cab signals to be cutout and proceed not exceeding 59MPH. At Albany, E/100 was cut and the equipment was wyeed to place E/704 in the lead in order to continue to Niagara Falls.

Train	Delay	Comment
281(18)	54"	Cab Signal Failure
281(18)	53"	Operating Per Rule 556
281(18)	13"	ALB - Cut E/100 and Wye Equipment

Train 90(18) North of Kingstree, SC - Semi on Tracks

18JUL25: Train 90(18) stopped 25.4 miles north of Kingstree, SC/MP331.5, on the CSX Charleston Subdivision, at New Hope/MP306.1 due to a semi reported on the tracks ahead at MP302.8. Once the semi was removed, Train 90(18) continued north.

Train	Delay	Comment
90(18)	35"	

CSX Heat Orders

18JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Capital, Charleston, Jacksonville Terminal, and Sanford.

Train	Delay	Comment
52 (18)	16"	
98 (18)	24"	

Train 41(16) South of Denmark, SC - Animal Strike

18JUL25: At 5:16AM, Train 41(16), E/204-E/62-11 Cars, reported striking an animal 25.2 miles south of Denmark, SC/MP409.9, on the CSX Columbia Subdivision, at MP435.1. The crew reported having to stop and rehang the hose on the front of lead E/204. No damage reported. No injuries to the crew or 211 passengers onboard. Head end power was on for the duration. At 5:20AM, Train 41(16) was back on the move south.

Train	Delay	Comment
41 (16)	04"	

Train 98(18) Miami, FL - PTC Issues

18JUL25: Train 98(18), E/324-E/325-11 Cars, departed Miami, FL on time then stopped right after departure due to PTC failure on lead E/324. The train reversed back and the engines were flat switched to place E/325 in the lead and E/324 to trail. At 9:21AM, Train 98(18) departed the station a second time operating 1 hour and 11 minutes late.

Train	Delay	Comment
98 (18)	1'11"	

Train 50(17) East of Huntington, WV - Near Miss

18JUL25: At 8:14AM, Train 50(17), E/201-5 Cars, went into emergency 37.7 miles east of Huntington, WV/MP503.9, on the CSX Kanawha Subdivision, to avoid striking a trespasser on the tracks at MP466.2. No strike occurred. The trespasser was reported sitting on the track, got up last minute, and then fled the scene. There were no injuries to the crew or 130 passengers onboard. There was no damage to the equipment. At 8:22AM, air was restored and Train 50(17) was back on the move east.

Train	Delay	Comment
50 (17)	12"	

Train 89(18) New York, NY - Engine Failure

18JUL25: Train 89(18) was delayed departing New York, NY after E/635 was late bad ordered after the cab lights wouldn't stay on and replaced with E/622.

Train	Delay	Comment
89 (18)	1'51"	

Train 40(16) East of Pittsburgh, PA - Cab Signal Failure

18JUL25: At 5:13AM, Train 40(16), E/340-E/372-10 Cars, stopped 0.6 miles east of Pittsburgh, PA/MP353.1, on the NSRR Pittsburgh Line, at Pitt/MP352.5 due to cab signal failure. Head end power on during this time. The crew contacted CNOC mechanical to troubleshoot. Pittsburgh Mechanical also responded to the train. At 6:53AM, the crew was granted permission to cut out cab signals and proceeded west.

Train	Delay	Comment
40(16)	1'46"	
40(16)	23"	Reduced - Cabs Cut Out

Train 40(17) North of Denmark, SC - Passenger Train Interference / Signals

18JUL25: Train 40(17) held 24.3 miles north of Denmark, SC/MP409.9, on the CSX Columbia Subdivision, at Woodford/MP385.1 meeting Train 41(16). Once on the move, additional delay incurred operating restricted speed from signal issues starting at Nassau/MP376.5 to Richland Holdout/MP369.7.

Train	Delay	Comment
40(17)	47"	Signals
40(17)	34"	Meet 41(16)

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold

371(19) - 10 oversold

305(18) - 13 oversold

300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold

371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold

371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses

were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL.

Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

Train 14(18) Oakland, CA - Car Failure

19JUL25: Train 14(18) was delayed departing Oakland, CA, on UP Niles subdivision due to waiting for mechanical to meet the train for a broken door on room E in C/32060. Mechanical was unable to meet the train and the room was taken out of inventory and any passengers booked in that room were moved.

Train	Delay	Comment
14(18)	34"	

Train 28(18) Bingen-White Salmon, WA - Police Related

18JUL25: Train 28(18) was delayed west of Bingen, WA (BNG) at MP 65.6 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. The local fire department had requested train traffic halted account a brush fire in the area. Train 8(18) held at MP 65.6 until cleared to advance to BNG station. At BNG train 28(18) again held until tracks were released by the fire department and was allowed to operate at reduced speeds until clear of the fire at MP 82.5.

Train	Delay	Comment
28(18)	45"	

Train 21(18) South of Arcadia, MO - Flash Flood Warnings

19JUL25: Train 21(18) was delayed 11 miles south of Arcadia, MO, on UP Desoto subdivision, due to operating through flash flood warning speed restrictions between mp 101 and 119. Once train 21(18) cleared the affected area it was able to proceed at normal speed.

Train	Delay	Comment
21(18)	1'03"	

Train 4(18) Los Angeles, CA - Engine Failure

18JUL25: Train 4(18) was delayed departing the initial terminal of Los Angeles, CA (LAX) on the Southern California Regional Rail Authority (Metrolink) River Subdivision. There was a problem initializing the Positive Train Control System (PTC) on locomotive AMTK/7, which required to the train crew to reboot the system. Once the reset was complete, train 4(18) was able to depart LAX at 5:58 PM-PT.

Train	Delay	Comment
4(18)	39"	

Train 6(18) Winnemucca, NV - Freight Train Interference

18JUL25: Train 6(18) was delayed just west of Winnemucca, NV (WNN) on the Union Pacific Railway Nevada Subdivision. There was a disabled freight train, IOANP-17 (UP/8563), stopped at CP Weso, blocking the opposing absolute signals (OS). A second freight train, ZLTG2-18 (UP/6245) was stopped between the disabled train and train 6(18) blocking the depot at WNN. The disabled freight had 2 broken knuckles. UP dispatched mechanical and managers to the location. By the time the repairs were made on the disabled freight the crews on both UP freight ran out of hours of service. Train 6(18) held for the freight re-crews to arrive. 1 crew arrived to the scene and moved the disabled freight into the clear and then was transported by UP management to the second freight. Once the second freight began to move, train 6(18) followed that freight into the station.

Train	Delay	Comment
6(18)	6'30"	WITRONIX ESTIMATE

Train 518(18) Olympia-Lacey, WA - Police Related

18JUL25: Train 518(18) was delayed at Olympia, WA (OLW) on the Burlington Northern Santa Fe Railway Seattle Subdivision. Local fire officials had requested all train traffic halted while attending to a brush fire in the area. Once tracks were reported clear train traffic was resumed and train 518(18) was able to depart OLW at 5:07 PM-PT.

Train	Delay	Comment
518(18)	48"	

Train 22(18) Longview, TX - Engine Failure

18JUL25: Train 22(18) was delayed departing Longview, TX, on UP Little Rock subdivision, due to E/56 having independent brake failure which caused to independent brake on E/56 to not release. After working with CNOC mechanical as well as LAX mechanical, 22(18) was unsuccessful in resolving the issue. It was at this time that a UP freight unit was requested to rescue train 22(18). UP provided a freight unit and train 22(18) waited for a UP crew that signed up at 810pm to move the motor to the train. Once the motor was added to train 22(18) they were able to depart Longview, tx and continue.

Train 22(18) was further delayed 8 miles east of Longview station due to PTC issues on the UP freight. The crew was able to resolve the issues with the aid of the PTC desk.

Train	Delay	Comment
22(17)	4'08"	Waiting for UP Freight Unit LVW
22(17)	42"	PTC Issues

Train 6(18) Truckee, CA - Freight Train Interference

18JUL25: Train 6(18) was delayed at Truckee, CA (TRU) on the Union Pacific Railway Roseville Subdivision. A crew operating freight train, MSPRV-18 (UP/7888), had expired on hours of service and delays were expected at CP RV220 as a result. Train 6(18) held at Truckee to allow passengers opportunities to step off the train while waiting for track ahead to clear. Once it was reported the tracks were expected to clear shortly, train 6(18) advanced to CP RV220 to wait for a route. With a route available train 6(18) was able to proceed from CP RV220 at 3:28 PM-PT.

Train	Delay	Comment
6(18)	1'01"	

Train 352(18) west of Pontiac, MI - Debris

18JUL25: Train 352(18) with E/4628, 5 coaches and 32 passengers, was delayed 5 miles west of Pontiac, MI due to striking a boulder. Once the train hit the boulder the engine shut down which caused HEP to also be shut down. After working with CNOC mechanical as well as Siemens techs, train 352(18) was able to recover.

Train	Delay	Comment
352(18)	1'06"	

Train 5(16) Truckee, CA - Freight Train Interference

18JUL25: Train 5(16) was delayed east of Truckee, CA (TRU) at MP 208.4 (East Truckee) on the Union Pacific Railway Roseville Subdivision. Train 5(16) held for a freight train, UP/6254, to clear the track ahead. Once the track was clear train 5(16) was able to proceed at 11:52 AM-PT.

Train	Delay	Comment
5(16)	41"	

Train 528(18) East of Martinez, CA - Drawbridge Opening

18JUL25: Train 528(18) was delayed east of Martinez, CA (MTZ) at CP RV033 on the Union Pacific Railway Martinez Subdivision. The movable lift-span of the Suisun Bay Bridge was raised to allow the safe passage of maritime traffic. Once the maritime traffic was cleared, the bridge was lowered into the closed position and train traffic was resumed.

Train	Delay	Comment
528(18)	22"	
535(18)	36"	

Train 336(18) East of Glenview, IL - Signal

18JUL25: Train 336(18) was delayed at Mayfair / MP 9.0 on the Canadian Pacific and Kansas City C & M Subdivision, 8 miles east of the Glenview, IL station, due to a signal outage. The crew was flagged by the location.

Train	Delay	Comment
336(18)	27"	
337(18)	07"	CHI - Turn Late Inbound 336(18)
337(18)	25"	
7/27(18)	28"	

Train 713(19) West of Hanford, CA - Freight Train Interference

18JUL25: Train 713(19) was delayed at Calwa, MP 993.7/BNSF Bakersfield Subdivision, 25.7 miles west of Hanford, meeting BNSF freight trains BN 8133 and BN 7094. This was caused by several speed restrictions between Fresno, CA (FNO) and Madera, CA (MDR), and excessive train interference resulting from the speed restrictions.

WBS#: B.TR.100150.5898

Train	Delay	Comment
713(19)	1'01"	
702(18)	51"	
710(18)	49"	
712(18)	15"	
714(18)	15"	
715(18)	37"	
719(18)	23"	
716(18)	22"	
717(18)	26"	

Train 302(18) St. Louis, MO - Car Failure

18JUL25: Train 302(18), operating with Locomotive ID4623 and 5 cars, was delayed departing the St. Louis, MO Gateway Station, due to issues with the doors on Car ID 46130.

Train	Delay	Comment
302(18)	33"	

Train 14(17) North of Sacramento, CA - Engine Failure

18JUL25: Train 14(17) with E61/313, 8 coaches, and 217 passengers, stopped north of Sacramento, CA, on UP Valley subdivision after trail unit E/313 shut down and stopped providing HEP. The crew switched HEP from the trail unit to the lead unit E/61 and proceeded to 10 miles north to Haggin siding to further trouble shoot E/313. The crew worked with CNOC mechanical and rebooted the trail unit. Once the unit was rebooted the crew operated at a reduced speed of 35MPH for 10 miles per CNOC mechanical instructions.

As a result of ongoing issues with E/313, UPRR freight locomotive UP 8105 was added to Train 14(17) at Dunsmuir, MP 321.3/UPRR Black Butte Subdivision.

Train 14(17) then incurred further delay at Mt. Shasta, MP 336.4 for a recrew as a result of the onboard crew expiring on hours at 10:44AM-PT. A UPRR pilot and the Portland-based Amtrak crew were dispatched from Klamath Falls.

The late operation and arrival of train 14(17) to Klamath Falls, OR (KFS) resulted in the operating crew arriving later than usual and not being fully rested for an on-time departure of train 11(18). Once the outbound crew was legally rested under Hours of Service regulations they went on-duty at 11:30 pm-pt. Once the crew was on-duty train 11(18) was able to depart KFS.

Work Element WBS #B.TR.100150.5895

WBS#: B.TR.100150.5895

Train	Delay	Comment
14(17)	2'09"	DUN - added freight loco UP 8105
14(17)	2'27"	SAC-RDD
14(17)	1'09"	Recrew at Mt. Shasta
11(18)	1'09"	KFF - Hold for crew rest
14(17)	50"	Daily Inspection PDX

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Train 19(17) South of Birmingham, AL - NS Work Truck Broken Down

18JUL25: Train 19(17) was delayed 0.3 miles south of Birmingham, AL/MP143.0, on the NSRR AGS South Subdivision, at MP143.3 due to an NS work truck broken down at 14th Street/MP143.5. Once the work truck was removed, Train 19(17) continued south.

Train	Delay	Comment
19(17)	40"	

Train 55(18) South of St. Albans, VT - Slow Orders / Freight Interference

18JUL25: Train 55(18) was delayed starting 6.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, account 10MPH slow orders from MP126 to MP117 due to trackwork. Additional delay through the area following NECR 4658 to MP108.0.

Train	Delay	Comment
55(18)	50"	Slow Orders
55(18)	20"	Freight

A-Report Detail



Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/18/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/18/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	299	23	92.3%	5,215	636	87.8%	83,922	8,305	90.1%
Central Division	91.5%	65	7	89.2%	1,188	136	88.6%	19,217	1,876	90.2%
Northeast Division	95.0%	95	7	92.6%	1,645	229	86.1%	27,600	2,992	89.2%
Southeast Division	94.5%	68	4	94.1%	1,151	144	87.5%	18,580	1,858	90.0%
Southwest Division	90.5%	71	5	93.0%	1,231	127	89.7%	18,525	1,579	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/18/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/18/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	299	23	92.3%	5,215	636	87.8%	83,922	8,305	90.1%
Central Division	91.5%	65	7	89.2%	1,188	136	88.6%	19,217	1,876	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	41	2	95.1%	584	16	97.3%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	26	4	84.6%	480	76	84.2%	7,756	961	87.6%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	36	0	100.0%	560	19	96.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	17	0	100.0%	290	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	35	1	97.1%	564	38	93.3%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	0	100.0%	105	5	95.2%	1,668	93	94.4%
MSP	95.0%	1	0	100.0%	18	2	88.9%	279	14	95.0%
PDX	78.0%	5	1	80.0%	86	9	89.5%	1,398	161	88.5%
PNT	94.0%	3	0	100.0%	53	1	98.1%	800	57	92.9%
PTH	96.0%	1	0	100.0%	18	0	100.0%	289	11	96.2%
QCY	94.0%	2	0	100.0%	34	0	100.0%	564	18	96.8%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	1	87.5%	145	28	80.7%	2,272	328	85.6%
SPK	92.0%	1	-	100.0%	16	1	93.8%	287	14	95.1%
STL	96.0%	3	1	66.7%	64	7	89.1%	1,141	60	94.7%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	36	0	100.0%	557	12	97.8%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	95	7	92.6%	1,645	229	86.1%	27,600	2,992	89.2%
ALB	96.0%	6	0	100.0%	108	5	95.4%	1,957	127	93.5%
BON	94.5%	5	0	100.0%	88	8	90.9%	1,352	91	93.3%
BOS	97.0%	19	2	89.5%	322	36	88.8%	5,439	502	90.8%
BRK	97.0%	5	0	100.0%	61	2	96.7%	1,322	68	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	18	2	88.9%	289	19	93.4%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	33	2	93.9%	560	54	90.4%
HFD	-	2	0	100.0%	26	4	84.6%	172	17	90.1%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/18/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/18/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	299	23	92.3%	5,215	636	87.8%	83,922	8,305	90.1%
Northeast Division	95.0%	95	7	92.6%	1,645	229	86.1%	27,600	2,992	89.2%
MTR	97.0%	1	0	100.0%	18	2	88.9%	289	28	90.3%
NFL	97.0%	2	0	100.0%	36	1	97.2%	582	24	95.9%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	0	100.0%	85	12	85.9%	1,492	146	90.2%
NYP	94.5%	40	4	90.0%	699	133	81.0%	11,692	1,771	84.9%
POR	-	-	-	-	24	8	66.7%	24	8	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	16	3	81.3%	287	8	97.2%
SPG	95.5%	5	1	80.0%	86	8	90.7%	1,782	84	95.3%
TWO	96.0%	1	0	100.0%	18	0	100.0%	288	11	96.2%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	68	4	94.1%	1,151	144	87.5%	18,580	1,858	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	87	9	89.7%	1,441	94	93.5%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	0	100.0%	204	11	94.6%	3,149	99	96.9%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	18	3	83.3%	285	91	68.1%
MIA	90.0%	2	0	100.0%	35	4	88.6%	560	51	90.9%
NFK	94.5%	3	2	33.3%	51	12	76.5%	801	66	91.8%
NOL	92.0%	2	0	100.0%	38	3	92.1%	645	46	92.9%
NPN	96.0%	2	0	100.0%	36	4	88.9%	555	21	96.2%
PGH	92.0%	1	0	100.0%	18	2	88.9%	290	16	94.5%
PHL	97.0%	5	0	100.0%	78	19	75.6%	1,244	176	85.9%
RGH	97.0%	4	0	100.0%	64	2	96.9%	1,167	36	96.9%
RNK	94.0%	2	0	100.0%	33	2	93.9%	550	64	88.4%
RVM	90.0%	1	0	100.0%	18	1	94.4%	282	34	87.9%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	16	1	93.8%	272	11	96.0%
SFA	83.0%	1	0	100.0%	18	1	94.4%	285	79	72.3%
WAS	94.5%	25	2	92.0%	427	60	85.9%	6,901	941	86.4%
Southwest Division	90.5%	71	5	93.0%	1,231	127	89.7%	18,525	1,579	91.5%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	18	0	100.0%	291	7	97.6%
BFD	90.0%	6	1	83.3%	106	13	87.7%	1,729	149	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	0	100.0%	18	14	22.2%	298	90	69.8%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	17	2	88.2%	323	42	87.0%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/18/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/18/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	299	23	92.3%	5,215	636	87.8%	83,922	8,305	90.1%
Southwest Division	90.5%	71	5	93.0%	1,231	127	89.7%	18,525	1,579	91.5%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	54	2	96.3%	850	62	92.7%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	10	2	80.0%	170	19	88.8%	2,229	310	86.1%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	15	0	100.0%	286	6	97.9%
OKJ	91.0%	12	1	91.7%	200	29	85.5%	3,053	279	90.9%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	0	100.0%	237	22	90.7%	3,468	147	95.8%
SAN	90.0%	12	1	91.7%	214	14	93.5%	2,636	232	91.2%
SAS	85.0%	1	0	100.0%	18	5	72.2%	287	40	86.1%
SJC	95.0%	7	0	100.0%	125	6	95.2%	1,865	72	96.1%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	36	0	100.0%	569	27	95.3%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	2	0	100.0%	49	11	77.6%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/18/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		7	0	100.0%	122	15	87.7%	8	4	50.0%	123	34	72.4%
2		8	2	75.0%	123	23	81.3%	8	3	62.5%	118	22	81.4%
3	878	18	5	72.2%	285	55	80.7%	18	14	22.2%	281	155	44.8%
4	152	18	4	77.8%	286	69	75.9%	18	14	22.2%	285	145	49.1%
5	60	18	9	50.0%	288	48	83.3%	17	14	17.6%	285	97	66.0%
6	86	18	14	22.2%	288	83	71.2%	18	15	16.7%	287	97	66.2%
7	49	18	4	77.8%	282	40	85.8%	18	7	61.1%	277	74	73.3%
8	117	18	14	22.2%	283	106	62.5%	18	14	22.2%	281	135	52.0%
11		18	2	88.9%	290	46	84.1%	18	2	88.9%	283	63	77.7%
14	No OS	18	6	66.7%	291	88	69.8%	18	7	61.1%	289	127	56.1%
19	36	18	0	100.0%	291	33	88.7%	18	8	55.6%	290	57	80.3%
20		18	1	94.4%	291	14	95.2%	18	4	77.8%	290	46	84.1%
21		18	1	94.4%	290	35	87.9%	18	6	66.7%	284	89	68.7%
22	267	18	5	72.2%	287	42	85.4%	18	15	16.7%	286	123	57.0%
27		16	4	75.0%	278	21	92.4%	15	6	60.0%	268	92	65.7%
28		15	3	80.0%	271	68	74.9%	15	3	80.0%	270	75	72.2%
40	452	18	2	88.9%	248	35	85.9%	17	13	23.5%	243	152	37.4%
41	161	16	11	31.3%	245	106	56.7%	17	16	5.9%	242	193	20.2%
42		18	2	88.9%	291	17	94.2%	18	5	72.2%	291	79	72.9%
43		18	2	88.9%	291	25	91.4%	18	6	66.7%	291	66	77.3%
48		18	5	72.2%	290	53	81.7%	18	4	77.8%	290	45	84.5%
49	36	18	6	66.7%	291	56	80.8%	18	5	72.2%	291	52	82.1%
50	58	8	4	50.0%	124	39	68.5%	8	6	25.0%	123	88	28.5%
52		18	1	94.4%	285	79	72.3%	18	5	72.2%	285	152	46.7%
53		18	3	83.3%	285	91	68.1%	18	4	77.8%	285	144	49.5%
55	84	13	2	84.6%	202	8	96.0%	13	7	46.2%	202	46	77.2%
56	89	13	2	84.6%	202	35	82.7%	13	10	23.1%	201	53	73.6%
58	153	18	2	88.9%	283	23	91.9%	18	3	83.3%	280	56	80.0%
59		18	6	66.7%	282	58	79.4%	17	6	64.7%	278	33	88.1%
63	75	18	11	38.9%	291	57	80.4%	18	16	11.1%	291	148	49.1%
64		18	0	100.0%	291	11	96.2%	18	3	83.3%	291	71	75.6%
66		18	3	83.3%	289	56	80.6%	18	1	94.4%	287	37	87.1%
67		12	0	100.0%	200	17	91.5%	13	3	76.9%	199	42	78.9%
68		18	2	88.9%	291	28	90.4%	18	14	22.2%	291	118	59.5%
69		18	2	88.9%	291	22	92.4%	17	7	58.8%	286	34	88.1%
71		17	2	88.2%	290	7	97.6%	17	8	52.9%	288	66	77.1%
72		18	3	83.3%	291	22	92.4%	18	7	61.1%	289	74	74.4%
73		18	3	83.3%	291	15	94.8%	18	9	50.0%	289	144	50.2%
74		18	1	94.4%	287	21	92.7%	18	8	55.6%	285	98	65.6%
75		18	3	83.3%	289	8	97.2%	18	10	44.4%	287	117	59.2%
76	33	18	4	77.8%	287	20	93.0%	17	12	29.4%	285	125	56.1%
77		18	2	88.9%	288	12	95.8%	18	8	55.6%	286	128	55.2%

Amtrak On Time Performance													
Trains Arriving Through: 7/18/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		18	0	100.0%	289	10	96.5%	17	5	70.6%	288	69	76.0%
79		18	5	72.2%	291	40	86.3%	16	6	62.5%	288	104	63.9%
80	68	18	3	83.3%	291	24	91.8%	18	12	33.3%	291	85	70.8%
84		13	0	100.0%	201	8	96.0%	13	6	53.8%	200	75	62.5%
85	55	13	0	100.0%	199	16	92.0%	13	10	23.1%	198	136	31.3%
86	54	13	1	92.3%	199	23	88.4%	13	11	15.4%	199	136	31.7%
89	119	18	2	88.9%	290	36	87.6%	18	8	55.6%	288	106	63.2%
90	35	18	1	94.4%	290	12	95.9%	17	8	52.9%	285	72	74.7%
93	92	13	0	100.0%	202	14	93.1%	13	8	38.5%	201	94	53.2%
94	79	13	5	61.5%	202	19	90.6%	13	8	38.5%	201	74	63.2%
95	64	13	0	100.0%	202	5	97.5%	13	7	46.2%	202	88	56.4%
97		18	13	27.8%	287	134	53.3%	18	10	44.4%	286	94	67.1%
98	107	18	2	88.9%	287	17	94.1%	18	12	33.3%	287	148	48.4%
110		13	5	61.5%	200	38	81.0%	13	3	76.9%	198	42	78.8%
111		13	3	76.9%	199	50	74.9%	13	2	84.6%	197	32	83.8%
112		13	3	76.9%	194	38	80.4%	13	3	76.9%	192	24	87.5%
114		13	3	76.9%	198	54	72.7%	13	3	76.9%	194	30	84.5%
119	21	13	1	92.3%	196	39	80.1%	13	3	76.9%	193	30	84.5%
125		13	1	92.3%	202	10	95.0%	13	8	38.5%	202	115	43.1%
129		13	3	76.9%	200	41	79.5%	13	6	53.8%	199	44	77.9%
130		13	1	92.3%	196	20	89.8%	13	1	92.3%	193	22	88.6%
131		13	2	84.6%	193	34	82.4%	13	2	84.6%	191	28	85.3%
133		13	7	46.2%	200	75	62.5%	13	10	23.1%	200	103	48.5%
134		13	0	100.0%	201	15	92.5%	13	7	46.2%	201	98	51.2%
136	25	13	1	92.3%	202	40	80.2%	13	4	69.2%	200	42	79.0%
137		13	4	69.2%	202	25	87.6%	13	6	53.8%	202	81	59.9%
138	191	13	3	76.9%	201	24	88.1%	13	8	38.5%	201	51	74.6%
141		13	0	100.0%	202	3	98.5%	13	7	46.2%	202	97	52.0%
148		13	1	92.3%	202	18	91.1%	13	4	69.2%	202	43	78.7%
151		18	3	83.3%	288	35	87.8%	18	4	77.8%	287	97	66.2%
170		13	0	100.0%	201	12	94.0%	13	6	53.8%	201	51	74.6%
171		13	3	76.9%	202	10	95.0%	13	8	38.5%	202	102	49.5%
172		13	2	84.6%	201	15	92.5%	13	5	61.5%	199	64	67.8%
173		13	0	100.0%	202	26	87.1%	13	4	69.2%	202	67	66.8%
174		13	2	84.6%	202	6	97.0%	13	5	61.5%	201	47	76.6%
175	No OS	13	5	61.5%	201	35	82.6%	13	7	46.2%	200	73	63.5%
176		13	4	69.2%	202	20	90.1%	13	1	92.3%	201	25	87.6%
177	17	13	3	76.9%	202	29	85.6%	13	6	53.8%	201	43	78.6%
178		13	1	92.3%	202	30	85.1%	13	6	53.8%	201	42	79.1%
179	50	13	3	76.9%	200	15	92.5%	13	9	30.8%	200	70	65.0%
181		13	6	53.8%	197	40	79.7%	13	1	92.3%	193	27	86.0%
182	17	13	2	84.6%	197	48	75.6%	13	8	38.5%	196	53	73.0%

Amtrak On Time Performance													
Trains Arriving Through: 7/18/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		13	2	84.6%	202	26	87.1%	13	1	92.3%	202	25	87.6%
184		13	5	61.5%	202	29	85.6%	13	2	84.6%	201	25	87.6%
185		13	2	84.6%	202	34	83.2%	13	2	84.6%	202	26	87.1%
186		13	2	84.6%	199	13	93.5%	13	7	46.2%	197	57	71.1%
190		13	5	61.5%	202	40	80.2%	13	6	53.8%	202	51	74.8%
192		13	3	76.9%	98	17	82.7%	13	4	69.2%	96	13	86.5%
193		13	4	69.2%	200	34	83.0%	13	6	53.8%	199	72	63.8%
196		13	1	92.3%	202	70	65.3%	13	3	76.9%	199	59	70.4%
197		13	7	46.2%	201	51	74.6%	13	4	69.2%	200	56	72.0%
232		18	1	94.4%	279	10	96.4%	18	1	94.4%	279	22	92.1%
233		16	5	68.8%	287	85	70.4%	16	8	50.0%	286	99	65.4%
234		18	1	94.4%	279	7	97.5%	18	2	88.9%	279	22	92.1%
236		18	0	100.0%	279	5	98.2%	18	2	88.9%	278	46	83.5%
239	19	18	4	77.8%	278	29	89.6%	18	6	66.7%	278	22	92.1%
240		18	0	100.0%	283	24	91.5%	18	5	72.2%	282	27	90.4%
241	28	18	3	83.3%	291	36	87.6%	17	6	64.7%	290	42	85.5%
243	42	13	5	61.5%	202	37	81.7%	13	6	53.8%	201	28	86.1%
244		16	1	93.8%	287	8	97.2%	16	9	43.8%	287	48	83.3%
280		18	0	100.0%	290	11	96.2%	18	1	94.4%	290	52	82.1%
281	81	18	2	88.9%	291	60	79.4%	17	5	70.6%	289	60	79.2%
283		18	6	66.7%	291	63	78.4%	18	8	55.6%	290	61	79.0%
284		18	1	94.4%	291	13	95.5%	18	0	100.0%	290	58	80.0%
290	45	18	2	88.9%	291	21	92.8%	17	13	23.5%	289	66	77.2%
291	31	18	6	66.7%	291	44	84.9%	18	13	27.8%	290	59	79.7%
300		16	1	93.8%	280	8	97.1%	16	4	75.0%	278	67	75.9%
302	40	17	2	88.2%	285	20	93.0%	17	7	58.8%	282	97	65.6%
305		18	2	88.9%	285	21	92.6%	18	14	22.2%	284	110	61.3%
307		17	1	94.1%	284	37	87.0%	16	9	43.8%	281	104	63.0%
311	18	17	3	82.4%	281	18	93.6%	17	15	11.8%	277	111	59.9%
316	16	17	1	94.1%	279	19	93.2%	17	15	11.8%	277	104	62.5%
318		18	0	100.0%	287	19	93.4%	18	11	38.9%	283	158	44.2%
319		18	1	94.4%	289	19	93.4%	18	15	16.7%	284	176	38.0%
329		13	2	84.6%	203	18	91.1%	13	1	92.3%	203	17	91.6%
330		15	1	93.3%	235	5	97.9%	15	1	93.3%	234	15	93.6%
331		18	1	94.4%	282	20	92.9%	18	2	88.9%	278	27	90.3%
332		18	1	94.4%	287	17	94.1%	18	3	83.3%	286	44	84.6%
334		18	0	100.0%	287	9	96.9%	18	3	83.3%	282	71	74.8%
335		18	2	88.9%	290	31	89.3%	18	5	72.2%	281	61	78.3%
336	30	18	1	94.4%	276	7	97.5%	18	6	66.7%	275	81	70.5%
337	37	18	2	88.9%	279	17	93.9%	18	6	66.7%	278	63	77.3%
338		18	2	88.9%	289	37	87.2%	18	7	61.1%	279	122	56.3%
339		18	0	100.0%	289	42	85.5%	18	2	88.9%	287	50	82.6%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
341	23	17	10	41.2%	274	55	79.9%	17	10	41.2%	268	57	78.7%
342		18	0	100.0%	290	18	93.8%	18	1	94.4%	289	44	84.8%
350	26	18	2	88.9%	250	27	89.2%	18	12	33.3%	247	125	49.4%
351		18	0	100.0%	279	24	91.4%	18	4	77.8%	278	77	72.3%
352	57	18	3	83.3%	284	27	90.5%	18	10	44.4%	279	81	71.0%
353		18	0	100.0%	243	6	97.5%	18	1	94.4%	238	36	84.9%
354		17	0	100.0%	283	26	90.8%	17	4	76.5%	280	102	63.6%
355		17	1	94.1%	283	31	89.0%	17	4	76.5%	279	72	74.2%
364		18	1	94.4%	289	55	81.0%	18	4	77.8%	288	78	72.9%
365		18	0	100.0%	289	11	96.2%	18	7	61.1%	288	85	70.5%
370		17	1	94.1%	290	11	96.2%	16	3	81.3%	289	36	87.5%
371		17	0	100.0%	290	4	98.6%	17	3	82.4%	290	28	90.3%
380		18	1	94.4%	288	11	96.2%	18	1	94.4%	288	27	90.6%
381		18	2	88.9%	288	8	97.2%	18	5	72.2%	287	28	90.2%
382		18	1	94.4%	287	11	96.2%	18	5	72.2%	287	38	86.8%
383		18	0	100.0%	289	29	90.0%	18	8	55.6%	288	67	76.7%
390		18	2	88.9%	286	12	95.8%	18	7	61.1%	284	43	84.9%
391		18	0	100.0%	289	6	97.9%	18	4	77.8%	287	53	81.5%
392		18	0	100.0%	289	8	97.2%	18	5	72.2%	286	31	89.2%
393		18	1	94.4%	288	13	95.5%	18	8	55.6%	285	41	85.6%
417		13	2	84.6%	198	32	83.8%	12	1	91.7%	195	29	85.1%
425		13	0	100.0%	186	5	97.3%	13	0	100.0%	186	7	96.2%
470		14	2	85.7%	204	15	92.6%	12	2	83.3%	199	28	85.9%
471		13	2	84.6%	202	14	93.1%	12	0	100.0%	200	11	94.5%
473		13	2	84.6%	202	7	96.5%	12	1	91.7%	201	3	98.5%
474		13	2	84.6%	200	30	85.0%	12	6	50.0%	196	60	69.4%
475	21	13	2	84.6%	201	8	96.0%	13	3	76.9%	198	19	90.4%
478		13	1	92.3%	202	21	89.6%	12	1	91.7%	200	20	90.0%
479		13	1	92.3%	202	30	85.1%	13	2	84.6%	201	24	88.1%
486	30	13	0	100.0%	204	16	92.2%	13	6	53.8%	202	70	65.3%
494	57	13	4	69.2%	207	31	85.0%	13	7	46.2%	201	57	71.6%
495	38	13	1	92.3%	199	3	98.5%	13	2	84.6%	199	6	97.0%
500	32	18	1	94.4%	280	22	92.1%	17	4	76.5%	278	82	70.5%
502		18	0	100.0%	278	13	95.3%	17	1	94.1%	276	79	71.4%
503		18	1	94.4%	291	30	89.7%	18	7	61.1%	280	88	68.6%
504		18	0	100.0%	279	9	96.8%	17	4	76.5%	278	111	60.1%
505		18	2	88.9%	283	33	88.3%	17	5	70.6%	280	102	63.6%
506	28	18	3	83.3%	283	27	90.5%	17	4	76.5%	281	70	75.1%
507		18	3	83.3%	282	33	88.3%	18	7	61.1%	281	87	69.0%
508		18	0	100.0%	286	13	95.5%	18	5	72.2%	284	83	70.8%
509	22	18	3	83.3%	281	31	89.0%	17	5	70.6%	280	99	64.6%
511	23	18	1	94.4%	282	23	91.8%	18	4	77.8%	279	76	72.8%

Amtrak On Time Performance													
Trains Arriving Through: 7/18/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
516		18	1	94.4%	282	25	91.1%	18	9	50.0%	280	127	54.6%
517	17	18	0	100.0%	283	5	98.2%	18	7	61.1%	282	170	39.7%
518	24	18	3	83.3%	283	32	88.7%	18	9	50.0%	281	170	39.5%
519		18	0	100.0%	280	11	96.1%	18	3	83.3%	279	58	79.2%
520		13	2	84.6%	34	4	88.2%	13	0	100.0%	34	1	97.1%
521		13	0	100.0%	202	4	98.0%	13	1	92.3%	201	16	92.0%
522		13	1	92.3%	202	4	98.0%	12	0	100.0%	201	11	94.5%
523		13	0	100.0%	203	4	98.0%	13	1	92.3%	203	26	87.2%
524		13	1	92.3%	203	6	97.0%	12	2	83.3%	202	35	82.7%
525		13	0	100.0%	201	4	98.0%	13	0	100.0%	200	10	95.0%
526		13	0	100.0%	34	4	88.2%	13	3	76.9%	34	7	79.4%
527		13	0	100.0%	203	3	98.5%	13	0	100.0%	202	29	85.6%
528	17	13	0	100.0%	202	5	97.5%	13	2	84.6%	202	32	84.2%
529		13	0	100.0%	203	0	100.0%	13	4	69.2%	203	40	80.3%
531		13	1	92.3%	202	3	98.5%	13	3	76.9%	201	16	92.0%
532		13	0	100.0%	203	9	95.6%	13	0	100.0%	201	20	90.0%
534		13	2	84.6%	203	15	92.6%	13	1	92.3%	202	15	92.6%
535	28	13	2	84.6%	34	3	91.2%	12	1	91.7%	33	3	90.9%
536		13	0	100.0%	203	8	96.1%	13	1	92.3%	201	9	95.5%
537		12	0	100.0%	33	1	97.0%	12	0	100.0%	33	2	93.9%
538	16	13	1	92.3%	203	5	97.5%	13	3	76.9%	203	37	81.8%
540		13	0	100.0%	203	5	97.5%	13	2	84.6%	198	20	89.9%
541		13	0	100.0%	203	8	96.1%	13	4	69.2%	203	44	78.3%
542		13	1	92.3%	203	8	96.1%	13	3	76.9%	203	35	82.8%
543		13	0	100.0%	203	6	97.0%	13	8	38.5%	203	32	84.2%
544		12	1	91.7%	201	11	94.5%	12	0	100.0%	200	15	92.5%
545		13	1	92.3%	203	8	96.1%	13	1	92.3%	201	21	89.6%
546		13	0	100.0%	203	7	96.6%	13	3	76.9%	202	31	84.7%
547		13	2	84.6%	203	9	95.6%	13	3	76.9%	203	29	85.7%
548		13	0	100.0%	201	12	94.0%	13	0	100.0%	199	11	94.5%
549		13	4	69.2%	203	23	88.7%	12	0	100.0%	197	29	85.3%
551		13	0	100.0%	203	10	95.1%	13	0	100.0%	198	17	91.4%
562		18	1	94.4%	287	32	88.9%	18	1	94.4%	278	31	88.8%
564		18	3	83.3%	285	20	93.0%	18	2	88.9%	282	26	90.8%
566		18	0	100.0%	110	10	90.9%	18	0	100.0%	110	11	90.0%
572		18	2	88.9%	240	21	91.3%	18	5	72.2%	236	43	81.8%
573		18	0	100.0%	279	37	86.7%	18	1	94.4%	273	44	83.9%
577		18	0	100.0%	33	0	100.0%	18	2	88.9%	33	2	93.9%
580		18	0	100.0%	287	21	92.7%	18	1	94.4%	286	53	81.5%
581		18	2	88.9%	287	35	87.8%	18	4	77.8%	283	55	80.6%
582		18	0	100.0%	33	0	100.0%	18	2	88.9%	33	3	90.9%
586		18	1	94.4%	238	30	87.4%	18	3	83.3%	231	41	82.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/18/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
587	23	18	3	83.3%	238	28	88.2%	17	4	76.5%	231	50	78.4%
591		18	0	100.0%	287	32	88.9%	18	2	88.9%	283	40	85.9%
593		18	4	77.8%	33	6	81.8%	18	4	77.8%	33	7	78.8%
595		18	3	83.3%	279	61	78.1%	18	2	88.9%	277	50	81.9%
600		13	1	92.3%	201	3	98.5%	13	2	84.6%	199	26	86.9%
601		13	2	84.6%	201	19	90.5%	13	2	84.6%	200	33	83.5%
605		13	1	92.3%	201	11	94.5%	13	0	100.0%	199	26	86.9%
607		13	1	92.3%	202	18	91.1%	13	0	100.0%	201	10	95.0%
609		13	1	92.3%	202	13	93.6%	12	1	91.7%	201	30	85.1%
620		13	1	92.3%	202	6	97.0%	13	3	76.9%	200	27	86.5%
639		13	1	92.3%	202	26	87.1%	13	2	84.6%	201	24	88.1%
640		13	0	100.0%	202	0	100.0%	13	2	84.6%	202	100	50.5%
641		13	0	100.0%	202	18	91.1%	13	0	100.0%	202	34	83.2%
642		13	0	100.0%	202	0	100.0%	13	1	92.3%	201	42	79.1%
643		13	0	100.0%	202	13	93.6%	13	1	92.3%	201	42	79.1%
644		13	1	92.3%	202	9	95.5%	12	2	83.3%	199	46	76.9%
645		13	1	92.3%	202	15	92.6%	12	3	75.0%	201	52	74.1%
646		13	1	92.3%	202	18	91.1%	13	3	76.9%	199	99	50.3%
647		13	1	92.3%	202	15	92.6%	12	4	66.7%	201	79	60.7%
648		13	0	100.0%	202	12	94.1%	13	4	69.2%	200	34	83.0%
649		13	0	100.0%	202	20	90.1%	13	4	69.2%	201	39	80.6%
650		13	0	100.0%	202	10	95.0%	13	1	92.3%	201	30	85.1%
651		13	2	84.6%	202	25	87.6%	13	3	76.9%	202	80	60.4%
652		13	1	92.3%	202	4	98.0%	13	5	61.5%	202	37	81.7%
653		13	0	100.0%	202	13	93.6%	13	5	61.5%	201	67	66.7%
654		13	1	92.3%	202	5	97.5%	13	0	100.0%	200	20	90.0%
655		13	1	92.3%	201	30	85.1%	13	4	69.2%	199	70	64.8%
656		13	2	84.6%	202	5	97.5%	13	2	84.6%	201	45	77.6%
657		13	1	92.3%	202	14	93.1%	13	1	92.3%	202	50	75.2%
658		13	0	100.0%	202	6	97.0%	13	3	76.9%	201	53	73.6%
680		14	0	100.0%	204	2	99.0%	14	1	92.9%	203	32	84.2%
681		14	0	100.0%	203	12	94.1%	14	7	50.0%	200	80	60.0%
682		14	0	100.0%	204	5	97.5%	14	1	92.9%	204	95	53.4%
683	13	13	0	100.0%	156	4	97.4%	13	7	46.2%	156	63	59.6%
684		12	3	75.0%	155	12	92.3%	12	7	41.7%	154	83	46.1%
685		12	0	100.0%	159	12	92.5%	12	7	41.7%	159	58	63.5%
686		14	5	64.3%	203	41	79.8%	14	7	50.0%	203	84	58.6%
687		14	1	92.9%	204	29	85.8%	14	7	50.0%	204	79	61.3%
688		14	1	92.9%	204	8	96.1%	14	2	85.7%	204	89	56.4%
702	76	18	2	88.9%	291	19	93.5%	18	12	33.3%	290	97	66.6%
703	65	18	2	88.9%	291	29	90.0%	18	8	55.6%	291	73	74.9%
710	78	18	5	72.2%	291	47	83.8%	17	11	35.3%	284	81	71.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/18/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
711	23	18	0	100.0%	290	10	96.6%	18	7	61.1%	281	33	88.3%
712	20	18	2	88.9%	291	45	84.5%	17	11	35.3%	288	89	69.1%
713	90	17	0	100.0%	289	9	96.9%	15	11	26.7%	272	61	77.6%
714		18	4	77.8%	290	39	86.6%	18	9	50.0%	285	71	75.1%
715	44	18	3	83.3%	290	42	85.5%	17	13	23.5%	279	90	67.7%
716	20	18	5	72.2%	290	33	88.6%	17	5	70.6%	289	61	78.9%
717	63	17	3	82.4%	285	33	88.4%	15	5	66.7%	269	67	75.1%
718		18	5	72.2%	291	42	85.6%	17	3	82.4%	289	52	82.0%
719	30	18	5	72.2%	291	28	90.4%	18	9	50.0%	283	66	76.7%
761		18	0	100.0%	287	17	94.1%	18	2	88.9%	287	35	87.8%
765		18	0	100.0%	287	12	95.8%	18	1	94.4%	278	40	85.6%
769		18	0	100.0%	285	11	96.1%	18	1	94.4%	281	51	81.9%
770		18	0	100.0%	287	17	94.1%	18	5	72.2%	284	39	86.3%
774		18	0	100.0%	287	8	97.2%	18	3	83.3%	283	65	77.0%
779		18	0	100.0%	33	1	97.0%	18	3	83.3%	33	7	78.8%
784	24	18	1	94.4%	287	33	88.5%	18	10	44.4%	284	115	59.5%
785		18	2	88.9%	287	15	94.8%	18	1	94.4%	285	44	84.6%
790		18	1	94.4%	287	15	94.8%	18	1	94.4%	284	42	85.2%
794		18	0	100.0%	287	22	92.3%	18	1	94.4%	286	58	79.7%
821	15	15	0	100.0%	286	6	97.9%	15	13	13.3%	286	147	48.6%
822	34	17	2	88.2%	288	13	95.5%	17	17	0.0%	288	148	48.6%
1237	17	3	1	66.7%	5	2	60.0%	3	2	33.3%	5	4	20.0%
1333	40	18	2	88.9%	284	52	81.7%	18	16	11.1%	283	182	35.7%
1340	42	18	2	88.9%	283	14	95.1%	18	14	22.2%	281	97	65.5%
1689		11	0	100.0%	71	0	100.0%	11	2	81.8%	70	15	78.6%
2107		13	4	69.2%	198	37	81.3%	13	1	92.3%	194	27	86.1%
2122		13	3	76.9%	197	37	81.2%	13	4	69.2%	191	35	81.7%
2130		3	1	66.7%	42	6	85.7%	3	1	66.7%	41	8	80.5%
2150		13	0	100.0%	202	7	96.5%	13	3	76.9%	202	63	68.8%
2151		13	0	100.0%	202	0	100.0%	13	5	61.5%	202	50	75.2%
2152		13	1	92.3%	200	6	97.0%	13	7	46.2%	194	81	58.2%
2153		12	0	100.0%	197	5	97.5%	12	8	33.3%	195	47	75.9%
2154	20	13	1	92.3%	200	15	92.5%	12	8	33.3%	196	87	55.6%
2155		12	1	91.7%	192	13	93.2%	12	6	50.0%	185	79	57.3%
2159	20	13	2	84.6%	199	16	92.0%	13	5	61.5%	194	63	67.5%
2162	31	13	1	92.3%	201	16	92.0%	12	5	58.3%	195	69	64.6%
2163	11	13	0	100.0%	201	15	92.5%	13	9	30.8%	195	81	58.5%
2166		13	2	84.6%	201	11	94.5%	13	7	46.2%	199	46	76.9%
2167		13	1	92.3%	202	28	86.1%	13	7	46.2%	200	53	73.5%
2168		13	3	76.9%	202	17	91.6%	13	5	61.5%	201	47	76.6%
2169		13	4	69.2%	199	49	75.4%	12	5	58.3%	192	67	65.1%
2170		12	2	83.3%	192	14	92.7%	11	3	72.7%	188	45	76.1%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
Train	Late												
2172		12	2	83.3%	188	23	87.8%	12	6	50.0%	184	41	77.7%
2173		12	1	91.7%	196	20	89.8%	12	4	66.7%	196	47	76.0%
2190		13	0	100.0%	201	14	93.0%	13	0	100.0%	198	16	91.9%
2193		12	1	91.7%	197	26	86.8%	12	4	66.7%	190	67	64.7%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/18/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2154	BOS	20	PET	9	PET	9	XHM-XCY	AM	Scheduled in track usage program, Other, XHM-TRE, OPERATED NO.1 TRK A/C NO.2 TRK OOS HOLMES TO MORRIS FOR CATENARY INSPECTION	
2159	WAS	20	CAR	32	CAR	19	RTE-PVD	AM	Air / Brake / Wheel, 3316, STOPPED AT MP 197,7 TO INSPECT CAR FOR SMOKE.	
2162	BOS	31	DSR	13	UTL	10	PVD-PVD	AM	Commercial power outage, Milepost, 184.9, 185.6, LOST COMMS BRAYTON/MP184.9 TO ORMS/MP185.6 Switches to be thrown manually	
2163	WAS	11	PTI	12	PTI	9	BWI-XNY	AM	Follow, 19, Milepost, 106.3, 134.6	
85	RVM	55	DCS	30	DCS	30	RVR-RVM	CS	Issue with automatic road crossing protection Car stuck on crossing. Had to wait until tow truck could clear crossing., Milepost w/Letters, SRN 1.2, SRN 1.2	
86	BOS	54	HLD	19	SYS	15	WAS-WAS	AM	Delay in Block, 15" SYS- CREW ASKED FOR FOUL TIME TO CUT 86 POWER BUT K TOWER COULDN'T GIVE IT TO THEM DUE TO 98 ARRIVING 5" SVS- 86 AND 98'S MOTOR CAME DOWN TOGETHER HAD TO GIVE TIME TO SPLIT AWAY	
93	NFK	92	CTI	32	WTR	24	X3V-NFK	NS	Flash flood warning Milepost, 82.1, 66.0, Milepost, 35.8, 25.5	
94	BOS	79	PTI	33	DMW	28	ASD-FBG	CS	Hold for defect repair Switch maintainers repairing switch at Milford, Control Point, Milford	
95	NFK	64	PTI	62	PTI	40	FBG-RVR	CS	Wait for station track amt, Milepost w/Letters, cfp 5.0, cfp 5.0	
119	WAS	21	CTI	15	PTI	7	EWB-TRE	AM	Follow, AM95, Other, MET-TRE	
136	SPG	25	ENG	31	ENG	31	WAS-WAS	AM	HEP, 653,612,659, TRAPPED AIR AND 480 ISSUES	
138	NYP	191	ITI	129	ITI	129	NFK-NFK	NS	Crew rest 138, Crew not rested late departure	
175	WAS	No OS Rpt	CAR	50	CAR	50	TRE-XHM	AM	Onboard HBD alarm, 62749, HOT AXEL DETECTOR ACTUATED MP62.5 ON NO.3 TRK	
177	PHL	17	SMW	24	SMW	24	XSH-NYP	AM	Scheduled in track usage program, Other, XM9, HLD A/C SINGLE TRACKING XGG-XPB	
179	PHL	50	OTH	34	OTH	24	BRP-STM	MN	Single issues between cp 240 and 235	
182	NYP	17	PTI	25	PTI	14	XHM-EWR	AM	Follow, AM98, Other, XH1-TRE	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/18/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
475	NHV	21	DCS	10	DCS	10	WNL-WND	AM	Issue with automatic road crossing protection, Milepost w/Letters, wnl, wnd, Stop and protect at Hayden a/c gates down at MP 43.6
486	GFD	30	CON	32	CON	32	NHV-NHV	AM	Hold for connecting train, Held for late conx of AM86
494	GFD	57	CON	61	CON	61	NHV-NHV	AM	Hold for connecting train, Held for late AM94
495	NHV	38	RTE	19	RTE	19	SPG-SPG	AM	Inability to contact dispatcher, Other, SWEENEY, WAITING FOR CSX DSPR
80	NYP	68	PTI	104	PTI	39	QAN-ALX	CS	Follow 40, Other, north possum point
19	NOL	36	SYS	40	TRS	40	BHM-TCL	NS	Vehicle on track ahead NS work truck stuck on track just south of the 13th st signal, Control Point, 13th st
683	BRK	13	PTI	11	PTI	7	SAO-ORB	CS	Meet 686, Control Point, Ocean Park
63	TWO	75	CUI	50	CUI	50	NFL-NFL	XC	United States
239	ALB	19	CTI	12	CTI	12	CRT-POU	MN	Follow mn, Control Point, 46
241	ALB	28	DSR	13	CTI	9	CRT-POU	MN	Meet metro, Milepost, 32, 49
243	ALB	42	ENG	42	ENG	42	NYP-NYP	AM	Loading problem, 121, LATE FROM SSYD A/C LOADING ISSUES WITH ENG.121
281	NFL	81	ENG	107	ENG	49	XSD-CRT	MN	Cab signal failure Stopped at Glenwood due to constant cab signal flips between Normal cab and Restricting. Called RTC & was advised to call our RFE or Mechanical. CNOC mech had us recycle cab signal system. Proceeded north but cab signals flipped continuously. Failed train, 100
290	NYP	45	DSR	46	DSR	25	BTN-VRN	VR	Per bulletin Milepost w/Letters, mp 113.30, mp 111.0, 10, main, Milepost w/Letters, mp 111.0, mp 105.68, 25, main, Milepost w/Letters, mp 105.68, mp 105.19, 15, main, Other, mp 102.36, 25, main
291	BTN	31	DSR	37	DSR	19	VRN-BTN	VR	Per bulletin Milepost, 100.68, 102.36, 50, main, Other, Mile 102.36, 25, main, Milepost, 102.36, 105.19, 50, main, Milepost, 105.19, 105.68, 15, main, Milepost, 105.68, 111.0, 25, main, Milepost, 111.0, 113.30, 10, main
1237	ALB	17	DSR	9	DSR	8	HUD-ALB	AM	Per bulletin Milepost, 128.0, 131.0, 30, 1, Milepost, 131.0, 135.0, 60, 1

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/18/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
49	CHI	36	FTI	57	ENG	53	SDY-XHF	AM	Air / Brake Loco engr unable to "bail off" (release locomotive) brakes using automatic brake handle. Also unable to bail off using independent brake either. Troubleshoot w/mech dept, Inspect engines, knock down, set up brakes, reset. Brake test. Depart., 119, 111
76	RGH	33	PTI	18	PTI	18	GRO-DNC	NS	Meet #Amt79, Control Point, Isom
89	SAV	119	ENG	111	ENG	111	NYP-NYP	AM	Undesired emergency application, 635, LATE F/SSYD A/C SHOPPE ENG.635 FOR ENG.622
90	NYP	35	TRS	35	TRS	35	KTR-FLO	CS	Vehicle on track ahead Milepost, 302.8, 3028
98	NYP	107	FTI	68	PTI	24	SAV-YEM	CS	Meet Siding, N. Talgo, 89
55	WAS	84	DSR	71	DSR	50	SAB-ESX	NE	Per bulletin Milepost, 127, 126, 25, main, Milepost, 126, 117, 10, main, Milepost, 114.59, 114.39, 25, main
56	SAB	89	DSR	71	DSR	50	ESX-SAB	NE	Per bulletin Milepost, 114.39, 114.59, 25, Main, Milepost, 117.00, 125.00, 10, Main
40	CHI	452	ENG	319	ENG	163	WAS-XQN	AM	HEP, 340, 372, loss HEP after departure between H&K signal bridges on 39 trk had to reverse back into the terminal for troubleshooting
41	MIA	161	DSR	55	CAR	47	WAS-WAS	AM	Heat / AC, 25049, ADDING COACH TO HEAD END DUE TO IN LINE SHOP CAR 25049 FOR HVAC
5	EMY	60	FTI	130	FTI	41	RNO-TRU	UP	Meet UP6245, Control Point, E Truckee
6	CHI	86	FTI	91	CAR	67	EMY-EMY	UP	Same story, all pm coach cleaners were laid off. And other mechanical workers. So nothing happens to the train until the AM, so we will always be delayed until further notice 39026, 38004, 34204, 33022, 33022, 32044, 32011, 31039, 32011, 31033
528	SAC	17	MBO	22	MBO	22	MTZ-SUI	UP	For maritime traffic Control Point, RV033
535	OKJ	28	MBO	36	MBO	36	SUI-MTZ	UP	For maritime traffic Bridge, Benicia
538	ARN	16	ADA	13	FTI	8	FMT-HAY	UP	Follow UP5308, Control Point, shinn
50	NYP	58	DSR	36	FTI	17	MNG-THN	CS	Meet CSXT 7416, Control Point, Sewell
500	SEA	32	TRS	29	TRS	29	VAN-KEL	BN	Vehicle on track ahead Vehicle on tracks. Waited at FRUIT VALLEY for vehicle to be removed., Milepost, 130.46, 130.46
506	SEA	28	FTI	15	FTI	10	KEL-CTL	BN	Meet up 6476, Control Point, napavine

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/18/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
509	PDX	22	PTI	22	PTI	22	CTL-KEL	BN	Meet Amtrak 506, Control Point, Chehalis Jct.	
511	PDX	23	DCS	28	DCS	28	KEL-VAN	BN	CTC system failure Signal failure at 39th street, Control Point, 39th Street	
517	PDX	17	ADA	9	ADA	5	TUK-TUK	BN	Wheelchair LIFT	
518	VAC	24	POL	53	POL	48	OLW-OLW	BN	Fire department hold Fire near tracks at MP 26.4	
58	CHI	153	FTI	169	FTI	139	MEM-NBN	CC	Blocked from station track Broken freight, CN 8911, Milepost, 321.1, 314.8	
14	SEA	No OS Rpt	ENG	285	ENG	129	RDD-DUN	UP	Pick up rescue locomotive due to mechanical failure Up 8105 was picked up, 313	
7	SEA	49	FTI	115	ENG	36	CHI-CHI	AM	???? 333	
8	CHI	117	CAR	113	CAR	99	SPK-SPT	BN	Air / Brake / Wheel 32083, Instructed to stop and inspect wheel L2 on 831 sleeper for defects at the Control Point at Silver. BNSF mechanical came and inspected wheel. Confirmed Ok to proceed track speed.	
821	FTW	15	DSR	37	DSR	18	GLE-FTW	BN	Per bulletin Milepost, 404.6, 404.4, 50, m, Milepost, 402.3, 402.1, 50, m, Milepost, 401.2, 401, 50, m, Milepost, 389.7, 389.5, 40, m, Milepost, 385.8, 385.6, 50, m, Milepost, 374.8, 374.4, 50, m, Milepost, 372.8, 372.4, 25, m, Milepost, 365.4, 365.3, 60, m1, Milepost, 364.8, 364.6, 30, m1, Milepost	
822	OKC	34	DSR	41	DSR	23	GLE-ADM	BN	Per bulletin Milepost, 413.6, 462.0, 40, m, Milepost, 414.6, 415.1, 60, m, Milepost, 423.6, 424.2, 50, m, Milepost, 426.3, 426.4, 50, m	
336	CHI	30	DCS	27	DCS	27	GLN-XWA	ME	Restrictive signal(s) from unknown cause Faulty circuit, Stop, Control Point, Mayfair	
337	MKE	37	DCS	25	DCS	25	XWA-GLN	ME	Restrictive signal(s) from unknown cause Stop, Control Point, Mayfair	
341	MKE	23	ITI	22	ITI	22	CHI-CHI	AM	Service, turn, or wye train 1340	
350	PNT	26	PTI	31	PTI	15	XB0-XA5	MI	Meet 353, Siding, Albion	
352	PNT	57	DBS	66	DBS	66	TRM-PNT	CC	Debris strike MP 20.7, Milepost, 20.7, 20.9	
587	LAX	23	CAR	13	CAR	13	SAN-SAN	SN	Door 6404, Stuck open. San Diego mechanical locked out.	
784	SAN	24	DCS	28	DCS	10	XRJ-FUL	BN	Restrictive signal(s) from unknown cause Flagging, Red, Control Point, East Hobart	
702	BFD	76	FTI	43	FTI	20	MDR-FNO	BN	Meet up9789, Control Point, E Figarden, Man	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/18/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
703	SAC	65	DCS	47	DCS	20	MOD-XSK	BN	Power switch failure Control Point, Keddie Jct
710	BFD	78	DSR	34	DSR	30	MDR-FNO	BN	Per bulletin Milepost, 1009.7, 1004.5, 25, MT, Milepost, 1004.5, 1001, 15, MT
711	OKJ	23	DSR	28	DSR	23	FNO-MDR	BN	Per bulletin Milepost, 1001.0, 1004.5, 15, MT, Milepost, 1004.5, 1009.7, 25, MT
712	BFD	20	DSR	17	DSR	13	MDR-FNO	BN	Per bulletin Milepost, 1007.9, 1001.0, 25, main
713	OKJ	90	FTI	99	FTI	61	HNF-FNO	BN	Meet 8183, 7094, Control Point, calwa crossing
715	OKJ	44	PTI	33	PTI	11	COC-HNF	BN	Meet 710, Milepost, 953, 953
716	BFD	20	PTI	23	DSR	14	MDR-FNO	BN	Per bulletin Through Figarden siding around bnsf3812 E (25 mph restriction main and siding), Milepost, 1006.0, 1001.0, 25, main and siding
717	OKJ	63	PTI	50	PTI	22	MOD-SKN	BN	Meet Amt 718, Control Point, Hanshaw
719	OKJ	30	DSR	26	DSR	23	FNO-MDR	BN	Per bulletin Milepost, 998, 1004, 15, Main, Siding, 1004, 1005, Figarden, Milepost, 1005, 1006, 25, Main
3	LAX	878	FTI	279	SVS	90	LMY-LMY	NM	Routine inspections Completing Daily Inspection, Other, Lamy Station
4	CHI	152	DSR	123	DCS	50	LSV-RAT	BN	Restrictive signal(s) from unknown cause Yellow/7222, 7202, Red/ 7174, Yellow/7126, 7102, Red/E Colmor, 7062, 7042, 7012, Red/ W Springer, Milepost, 722.7, 698.1
22	CHI	267	RTE	248	RTE	246	MIN-MIN	UP	Dispatcher hold Freight derailment in Longview, Control Point, R136
302	CHI	40	CAR	33	CAR	33	STL-STL	TR	Door ID4130
311	KCY	18	ADA	10	RTE	6	STL-XGA	TR	Dispatcher hold Control Point, Grand Ave
316	STL	16	DSR	20	DSR	10	WAH-KWD	UP	Per MW foreman Milepost, 43.0, 41.0, 25, 2
1333	MSP	40	DSR	33	DSR	12	LSE-WIN	CP	Per bulletin Milepost, 301.9, 302.2, 10, main, Milepost, 294.5, 294.7, 10, main
1340	CHI	42	DSR	39	SVS	10	MSP-XH8	CP	Wyed equipment upon departure from SPUD Milepost, 5305, 0.3, Milepost, 0.3, 429.9

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/18/2025

Terminal	Train	Date	Late	Delay	Cause
NFK	94	07/18	26	26	HEP Original set of equipment's engine kept dropping HEP, NFK mechanical had us take 138's equipment instead., 817
NFK	138	07/18	129	129	Crew rest 138, Crew not rested late departure
WAS	114	07/18	4	4	Meet, MARC, 416, Control Point, WAS, 416 WENT INTO EMERGENCY AHEAD. DEPARTED ONCE PENALTY WAS CLEARED
WAS	176	07/18	9	9	Other late crew, 14A WAS CALL OUT TO SPLIT THE SOUTH MOTOR OFF THE TRAIN BEFORE DP TIME. LATE TO THE MOVE.
BOS	171	07/18	8	8	Other electrical failure, 606, LATE FROM YARD A/C A/C PROBLEM IN THE ENGINE
BOS	179	07/18	40	40	Planned set out / pick out of locomotives, cars or section of train, Engine Swap
NYP	63	07/18	19	19	Passenger and/or baggage, STILL BOARDING AT DEPARTURE TIME PER PSCC
NYP	89	07/18	111	111	Undesired emergency application, 635, LATE F/SSYD A/C SHOPPE ENG.635 FOR ENG.622
NYP	111	07/18	7	7	Undesired emergency application, 665, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	181	07/18	14	14	Undesired emergency application, 611, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
SPG	495	07/18	19	19	Inability to contact dispatcher, Other, SWEENEY, WAITING FOR CSX DSPR
CHI	48	07/18	8	5	Wheelchair Passenger lift was one inch wider to be able to clear the handbrake on the car. He had to get out of the wheelchair in order to fold it. Passengers couldn't board during that time. That was the 5th lift in 5 different cars.
CHI	48	07/18	8	3	Loading problem Engine wouldn't load. Engineer resolved issue., 119
CHI	59	07/18	9	9	Crew rest 58
CHI	337	07/18	7	7	Service, turn, or wye train 336
CHI	341	07/18	22	22	Service, turn, or wye train 1340
PDX	28	07/18	9	9	Hold for thruway bus Hold for 5528 bus transfers
SEA	8	07/18	8	8	Service, turn, or wye train 8, Late turnaround for train 8.
STL	302	07/18	33	33	Door ID4130
BFD	719	07/18	6	6	Waited for 712 to arrive into station before 719 can depart. 712, Other, Amtrak Station
LAX	4	07/18	39	39	PTC problem or failure (cause unknown) Unable to sync up address reset breaker, Milepost, 0.0, 0.0
LAX	562	07/18	15	15	Late release of 562 equipment with Del Mar Block 562, Cut off Del Mar block at LAX

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/18/2025

Terminal	Train	Date	Late	Delay	Cause
OKJ	710	07/18	5	5	Loading problem Engineer checked MU cables and noticed voltage was low, 90218
SAN	587	07/18	13	13	
					Door 6404, Stuck open. San Diego mechanical locked out.

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	92.7	95.2	341	0
CDOT	95.0	100	95.5	96.4	20	0
MARC	95.0	67.9	78.0	83.5	56	18
SEPTA	95.0	97.3	96.5	96.2	221	6
NJT-NED	95.0	97.8	91.7	95.2	368	8
NJT-SED	95.0	100	98.1	91.2	24	0

Operating Highlights

Train 175(18) West of Trenton, NJ - Onboard HBD Alarm

18JUL25: Train 175(18), E/643-9 Cars, stopped 7 miles west of Trenton, NJ on the Amtrak NYP Line, at MP64 to inspect after their onboard hot box detector alarm went off on C/62749. The crew inspected and took no exceptions. They advanced to Philadelphia, PA to have mechanical inspect. Mechanical found a loose flange lube fitting on the F-end truck and was corrected. Train 175(18) continued to Washington operating track speed.

Train	Delay	Comment
175(18)	50"	
175(18)	07"	PHL

Train 494(18) New Haven, CT - Hold for Connection

18JUL25: Train 494(18) was delayed departing New Haven due to waiting for 23 passenger connections from Train 94(18), that arrived New Haven 1 hour and 13 minutes late..

Train	Delay	Comment
494(18)	1'01"	

Train 179(18) Boston, MA - Engine Swap

18JUL25: Train 179(18) was delayed departing Boston, MA due to engine E/660 being swapped out for overheating, replaced by engine E/637. Once engine was complete, Train 179(18) was able to depart.

Train	Delay	Comment
179(18)	40"	

Train 98(18) North Winter Park, FL - Commuter Train Interference

18JUL25: Train 98(18) received delays starting 17.7 miles north of Winter Park, FL/MP785.7, on the CFRF Orlando Subdivision, following a CFRC commuter and Train 52(18) from MP768.1 to MP750.

Train	Delay	Comment
98(18)	26"	CFRC
98(18)	11"	52(18)

Train 40(17) South of Fredericksburg, VA - Freight Train Interference

19JUL25: Train 40(17) was delayed on the CSX RF&P Subdivision due to following freight unit CSX410 Beginning 10 miles south of Fredericksburg, VA between MP49.9 and MP105.1. Train 80(18) was also delayed due to this, following 40(17).

Train	Delay	Comment
40(17)	47"	
80(18)	51"	

Train 56(18) North of Springfield, MA - Passenger Train Interference

18JUL25: Train 56(18) held just north of Springfield, MA/MP98.4, on the CSX Conn River Main Line, at CPR2/MP2.02 to meet Train 55(18).

Train	Delay	Comment
56(18)	32"	

Amtrak NHB Line - Commercial Power Outage

18JUL25: At 3:33PM, the Mainline Dispatcher reported a commercial power outage that resulted in a loss of comms between Brayton, MP184.9 and Orms/MP185.6, on the Amtrak NHB Line. The Providence station/MP185.1 also lost power. C&S arrived to the location at 4:14PM to take local control of the switches. During this time, trains traveling through the area were delayed. At 9:08PM-ET Providence ticket office power was restored. At 9:28PM-ET reported comms were back and C&S released local control.

Train	Delay	Comment
175(18)	10"	
86(18)	04"	
184(18)	05"	
2166(18)	04"	
2173(18)	03"	
177(18)	03"	
174(18)	03"	
2193(18)	03"	
2162(18)	14"	

Train 486(18) New Haven, CT - Hold for Connection

18JUL25: Train 486(18) was delayed departing New Haven, CT holding for the passenger connections from Train 86(18) that arrived at 3:04PM, 45 minutes late.

Train	Delay	Comment
486(18)	32"	

Train 41(17) Washington, DC - Crew

18JUL25: Train 41(17) arrived to Washington, DC, on time and then was delayed due to a Conductor crewing issue. A new Conductor was called and responded to the train quickly. Train 41(17) departed Washington at 2:35PM, operating 52 minutes late.

Train	Delay	Comment
41(17)	52"	

Train 281(18) North of Yonkers, NY - Cab Signals

18JUL25: Train 281(18), E/100-5 Cars-E/704, stopped 1.2 miles north of Yonkers, NY/MP15.2, on the Metro North Hudson Line, at MP16.4 due to E/100 cab signals reported dropping from normal to restricted. The crew recycled the breakers which was thought to have resolved the issue. Train 281(18) was back on the move for 1.8 miles until stopping again with the same issue at MP18.2. Permission was granted for cab signals to be cutout and proceed not exceeding 59MPH. At Albany, E/100 was cut and the equipment was wyeed to place E/704 in the lead in order to continue to Niagara Falls.

Train	Delay	Comment
281(18)	54"	Cab Signal Failure
281(18)	53"	Operating Per Rule 556
281(18)	13"	ALB - Cut E/100 and Wye Equipment

Train 90(18) North of Kingstree, SC - Semi on Tracks

18JUL25: Train 90(18) stopped 25.4 miles north of Kingstree, SC/MP331.5, on the CSX Charleston Subdivision, at New Hope/MP306.1 due to a semi reported on the tracks ahead at MP302.8. Once the semi was removed, Train 90(18) continued north.

Train	Delay	Comment
90(18)	35"	

CSX Heat Orders

18JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Capital, Charleston, Jacksonville Terminal, and Sanford.

Train	Delay	Comment
52(18)	16"	
98(18)	24"	

Train 41(16) South of Denmark, SC - Animal Strike

18JUL25: At 5:16AM, Train 41(16), E/204-E/62-11 Cars, reported striking an animal 25.2 miles south of Denmark, SC/MP409.9, on the CSX Columbia Subdivision, at MP435.1. The crew reported having to stop and rehang the hose on the front of lead E/204. No damage reported. No injuries to the crew or 211 passengers onboard. Head end power was on for the duration. At 5:20AM, Train 41(16) was back on the move south.

Train	Delay	Comment
41(16)	04"	

Train 98(18) Miami, FL - PTC Issues

18JUL25: Train 98(18), E/324-E/325-11 Cars, departed Miami, FL on time then stopped right after departure due to PTC failure on lead E/324. The train reversed back and the engines were flat switched to place E/325 in the lead and E/324 to trail. At 9:21AM, Train 98(18) departed the station a second time operating 1 hour and 11 minutes late.

Train	Delay	Comment
98(18)	1'11"	

Train 50(17) East of Huntington, WV - Near Miss

18JUL25: At 8:14AM, Train 50(17), E/201-5 Cars, went into emergency 37.7 miles east of Huntington, WV/MP503.9, on the CSX Kanawha Subdivision, to avoid striking a trespasser on the tracks at MP466.2. No strike occurred. The trespasser was reported sitting on the track, got up last minute, and then fled the scene. There were no injuries to the crew or 130 passengers onboard. There was no damage to the equipment. At 8:22AM, air was restored and Train 50(17) was back on the move east.

Train	Delay	Comment
50(17)	12"	

Train 89(18) New York, NY - Engine Failure

18JUL25: Train 89(18) was delayed departing New York, NY after E/635 was late bad ordered after the cab lights wouldn't stay on and replaced with E/622.

Train	Delay	Comment
89(18)	1'51"	

Train 40(16) East of Pittsburgh, PA - Cab Signal Failure

18JUL25: At 5:13AM, Train 40(16), E/340-E/372-10 Cars, stopped 0.6 miles east of Pittsburgh, PA/MP353.1, on the NSRR Pittsburgh Line, at Pitt/MP352.5 due to cab signal failure. Head end power on during this time. The crew contacted CNOC mechanical to troubleshoot. Pittsburgh Mechanical also responded to the train. At 6:53AM, the crew was granted permission to cut out cab signals and proceeded west.

Train	Delay	Comment
40(16)	1'46"	
40(16)	23"	Reduced - Cabs Cut Out

Train 40(17) North of Denmark, SC - Passenger Train Interference / Signals

18JUL25: Train 40(17) held 24.3 miles north of Denmark, SC/MP409.9, on the CSX Columbia Subdivision, at Woodford/MP385.1 meeting Train 41(16). Once on the move, additional delay incurred operating restricted speed from signal issues starting at Nassau/MP376.5 to Richland Holdout/MP369.7.

Train	Delay	Comment
40(17)	47"	Signals
40(17)	34"	Meet 41(16)

Train 2124(17) Baltimore, MD - Engine Failure

18JUL25: Train 2124(17), TS18, PC/2023, 6 cars PC/2025, became disabled at approximately 7:05P-ET 1.7 miles north of Baltimore, MD at MP94 on the Amtrak PW Line. Crew reported both MCB's opened on Lead and Trail power cars, putting the train into emergency. There were approximately 250 passengers onboard and head end power remained intact. An Amtrak Road Foreman was dispatched to the scene, while crew worked with High Speed Rail mechanical to try to resolve issue. Train 196(17) was held behind 2124(17) in case a passenger transfer was necessary, with a rescue engine being sourced from Baltimore. Unable to resolve, the decision was made to terminate the train and transfer all passengers to the next 3 northbound trains 196/80/138(17) account of space availability. The passenger transfer was complete at 917P-ET, with 138(17) taking the last remaining passengers off of Train 2124(17). At 1045P-ET, The crew was able to restore power and departed with 2124's equipment back to Washington.

Due to this equipment being shopped, Acela Service Cancellations were necessary due to no replacement equipment. Trains 2103(18), 2108(18) and 2121(18) were all cancelled in their entirety with no alternate transportation provided.

Train	Delay	Comment
138(17)	1'40"	
196(17)	1'22"	
80(17)	1'04"	
192(17)	10"	
90(17)	07"	
186(17)	04"	
85(17)	21"	
193(17)	06"	
197(17)	22"	
173(17)	21"	
93(17)	19"	
2169(17)	03"	
2 MARC's	12-13"	
2124(17)	Terminated at MP94	
2103/2108/2121(18)	Cancelled No Alternate	

Train 93(17) Mystic, CT - Engine Failure / Shaws River Bridge Malfunction

17JUL25: At 10:48AM, Train 93(17), E/658-8 Cars, stopped just east of the Mystic, CT station/MP132.3, on the Amtrak NHB Line, at MP132.4 with engine issues. The crew reported E/658 was not charging and low on air. The train did have head end power with 330 passengers onboard. The issue was unable to be resolved so rescue E/634 was dispatched from New Haven departing at 11:14AM. One car was able to be spotted onto the platform allowing customers to get off the train and stretch their legs. An Amtrak Trainmaster and Road Foreman were on scene to coordinate. Service recovery was enacted consisting of comping items from the café car.

At 12:00PM, The New London Dispatcher reported that the Shaw's Cove Bridge at MP122.5, 0.4 miles west of the New London, CT station/MP122.9 was unable to lock for rail traffic. B&B responded quickly but spent a lot of time troubleshooting. The issue was found to be a broken screw jack which required come-alongs to get it closed and locked. The estimated track opening was set for 2:00PM. During this time, all traffic came to a halt. The rescue E/634 enroute to Train 93(17), along with trains 85(17), 2163(17), 173(17), 2154(17), and 172(17) were all heavily delayed during this time. At 1:56PM, the bridge was able to finally close and lock to allow rail traffic to resume. Also to note, Train 85(17) accommodated Train 93(17)'s downline passengers between New London and New York.

At 2:30PM, rescue E/634 arrived to Train 93(17) in order to couple up. At 3:00PM, Train 93(17) was back on the move west operating 4 hours and 14 minutes late.

18JUL25: Train 138(18) was delayed departing Norfolk, VA/MP4.8, on the NSRR Norfolk Terminal Subdivision, due to crew rest. The crew signed up at 1:00PM off of inbound Train 93(17) that arrived 3:39AM, 4 hours and 56 minutes late. The crew was further delayed due to a van issue that delayed them from their hotel the that station. At 3:03PM, Train 138(18) departed Norfolk operating 2 hours and 09 minutes late.

Train	Delay	Comment
93(17)	4'11"	Disabled
85(17)	2'15"	Bridge
2173(17)	50"	ITD BOS - Turn of 2154(17)
177(17)	34"	ITD BOS - Turn of 172(17)
2163(17)	1'36"	Bridge
2154(17)	1'31"	Bridge
173(17)	1'22"	
172(17)	46"	Bridge
138(18)	2'09"	ITD NFK

Maintenance of Way Highlights

Train 19(17) South of Birmingham, AL - NS Work Truck Broken Down

18JUL25: Train 19(17) was delayed 0.3 miles south of Birmingham, AL/MP143.0, on the NSRR AGS South Subdivision, at MP143.3 due to an NS work truck broken down at 14th Street/MP143.5. Once the work truck was removed, Train 19(17) continued south.

Train	Delay	Comment
19(17)	40"	

Train 55(18) South of St. Albans, VT - Slow Orders / Freight Interference

18JUL25: Train 55(18) was delayed starting 6.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, account 10MPH slow orders from MP126 to MP117 due to trackwork. Additional delay through the area following NECR 4658 to MP108.0.

Train	Delay	Comment
55(18)	50"	Slow Orders
55(18)	20"	Freight

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

· Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

· Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

· Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

· Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

· Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

· Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

· Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

· Bus 3470 will provide alternate transportation between HFD and SPG

· Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

· Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

· Deadhead Train 426 will turn for Train 471 at HFD

· Train 470 will turn for Train 473 at HFD

WBS#: B.TR.100151.0738

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 158(13) Passenger Removal at Ivor, Virginia – Improper Conduct

18JUL25, Passenger on PNR 338D94, traveling from Norfolk, VA to Washington, D.C. reportedly offered a ticket for the wrong train and was advised to purchase a ticket for travel. At some point the passenger became unruly wielding the train broom and sledgehammer towards other travelers and crew. The Sheriff's departments from Isle of Wight and South Hampton Counties assisted with the removal at milepost 41.7 on the Norfolk Subdivision of the NS Railroad. Amtrak Police notified.

Delay: 158 (13) None

Train 125(17) Passenger Removal at Washington, DC – Improper Conduct

18JUL25, Passenger on PNR 2E24FD, traveling from Philadelphia, PA to Richmond, VA was removed at Washington, DC for improper conduct with assistance from Amtrak PD. Passenger became irate with Conductor after asking passenger to step away from the door while smoking. Amtrak police notified.

Delay: 125 (17) 5"

Train 97(17) Passenger Removal at Sebring, Florida – Improper Conduct

18JUL25, Passenger on PNR 3BEE12, traveling from Fayetteville, NC to West Palm Beach, FL was removed of the train by HCSO. The passenger was blocking ADA seats from ADA passenger and companion. The passenger became argumentative when asked to go to assigned seat. Amtrak police notified.

Delay: 97(17) 5"

Train 190(18) Passenger Removal at Stamford, Connecticut – Other

18JUL25, Passenger on PNR 381471, traveling from New York, NY to Boston, MA was removed of the train by the conductor. The passenger didn't have the proper carrier for pet. Amtrak police notified.

Delay: 190(18) None

Western Region

Operating Highlights

Train 14(18) Oakland, CA - Car Failure

19JUL25: Train 14(18) was delayed departing Oakland, CA, on UP Niles subdivision due to waiting for mechanical to meet the train for a broken door on room E in C/32060. Mechanical was unable to meet the train and the room was taken out of inventory and any passengers booked in that room were moved.

Train	Delay	Comment
14 (18)	34"	

Train 28(18) Bingen-White Salmon, WA - Police Related

18JUL25: Train 28(18) was delayed west of Bingen, WA (BNG) at MP 65.6 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. The local fire department had requested train traffic halted account a brush fire in the area. Train 8(18) held at MP 65.6 until cleared to advance to BNG station. At BNG train 28(18) again held until tracks were released by the fire department and was allowed to operate at reduced speeds until clear of the fire at MP 82.5.

Train	Delay	Comment
28 (18)	45"	

Train 21(18) South of Arcadia, MO - Flash Flood Warnings

19JUL25: Train 21(18) was delayed 11 miles south of Arcadia, MO, on UP Desoto subdivision, due to operating through flash flood warning speed restrictions between mp 101 and 119. Once train 21(18) cleared the affected area it was able to proceed at normal speed.

Train	Delay	Comment
21 (18)	1'03"	

Train 4(18) Los Angeles, CA - Engine Failure

18JUL25: Train 4(18) was delayed departing the initial terminal of Los Angeles, CA (LAX) on the Southern California Regional Rail Authority (Metrolink) River Subdivision. There was a problem initializing the Positive Train Control System (PTC) on locomotive AMTK/7, which required to the train crew to reboot the system. Once the reset was complete, train 4(18) was able to depart LAX at 5:58 PM-PT.

Train	Delay	Comment
4 (18)	39"	

Train 6(18) Winnemucca, NV - Freight Train Interference

18JUL25: Train 6(18) was delayed just west of Winnemucca, NV (WNN) on the Union Pacific Railway Nevada Subdivision. There was a disabled freight train, IOANP-17 (UP/8563), stopped at CP Weso, blocking the opposing absolute signals (OS). A second freight train, ZLTG2-18 (UP/6245) was stopped between the disabled train and train 6(18) blocking the depot at WNN. The disabled freight had 2 broken knuckles. UP dispatched mechanical and managers to the location. By the time the repairs were made on the disabled freight the crews on both UP freight ran out of hours of service. Train 6(18) held for the freight re-crews to arrive. 1 crew arrived to the scene and moved the disabled freight into the clear and then was transported by UP management to the second freight. Once the second freight began to move, train 6(18) followed that freight into the station.

Train	Delay	Comment
6(18)	6'30"	WITRONIX ESTIMATE

Train 518(18) Olympia-Lacey, WA - Police Related

18JUL25: Train 518(18) was delayed at Olympia, WA (OLW) on the Burlington Northern Santa Fe Railway Seattle Subdivision. Local fire officials had requested all train traffic halted while attending to a brush fire in the area. Once tracks were reported clear train traffic was resumed and train 518(18) was able to depart OLW at 5:07 PM-PT.

Train	Delay	Comment
518(18)	48"	

Train 22(18) Longview, TX - Engine Failure

18JUL25: Train 22(18) was delayed departing Longview, TX, on UP Little Rock subdivision, due to E/56 having independent brake failure which caused to independent brake on E/56 to not release. After working with CNOC mechanical as well as LAX mechanical, 22(18) was unsuccessful in resolving the issue. It was at this time that a UP freight unit was requested to rescue train 22(18). UP provided a freight unit and train 22(18) waited for a UP crew that signed up at 810pm to move the motor to the train. Once the motor was added to train 22(18) they were able to depart Longview, tx and continue.

Train 22(18) was further delayed 8 miles east of Longview station due to PTC issues on the UP freight. The crew was able to resolve the issues with the aid of the PTC desk.

Train	Delay	Comment
22(17)	4'08"	Waiting for UP Freight Unit LVW
22(17)	42"	PTC Issues

Train 6(18) Truckee, CA - Freight Train Interference

18JUL25: Train 6(18) was delayed at Truckee, CA (TRU) on the Union Pacific Railway Roseville Subdivision. A crew operating freight train, MSPRV-18 (UP/7888), had expired on hours of service and delays were expected at CP RV220 as a result. Train 6(18) held at Truckee to allow passengers opportunities to step off the train while waiting for track ahead to clear. Once it was reported the tracks were expected to clear shortly, train 6(18) advanced to CP RV220 to wait for a route. With a route available train 6(18) was able to proceed from CP RV220 at 3:28 PM-PT.

Train	Delay	Comment
6(18)	1'01"	

Train 352(18) west of Pontiac, MI - Debris

18JUL25: Train 352(18) with E/4628, 5 coaches and 32 passengers, was delayed 5 miles west of Pontiac, MI due to striking a boulder. Once the train hit the boulder the engine shut down which caused HEP to also be shut down. After working with CNOC mechanical as well as Siemens techs, train 352(18) was able to recover.

Train	Delay	Comment
352(18)	1'06"	

Train 5(16) Truckee, CA - Freight Train Interference

18JUL25: Train 5(16) was delayed east of Truckee, CA (TRU) at MP 208.4 (East Truckee) on the Union Pacific Railway Roseville Subdivision. Train 5(16) held for a freight train, UP/6254, to clear the track ahead. Once the track was clear train 5(16) was able to proceed at 11:52 AM-PT.

Train	Delay	Comment
5(16)	41"	

Train 528(18) East of Martinez, CA - Drawbridge Opening

18JUL25: Train 528(18) was delayed east of Martinez, CA (MTZ) at CP RV033 on the Union Pacific Railway Martinez Subdivision. The movable lift-span of the Suisun Bay Bridge was raised to allow the safe passage of maritime traffic. Once the maritime traffic was cleared, the bridge was lowered into the closed position and train traffic was resumed.

Train	Delay	Comment
528(18)	22"	
535(18)	36"	

Train 336(18) East of Glenview, IL - Signal

18JUL25: Train 336(18) was delayed at Mayfair / MP 9.0 on the Canadian Pacific and Kansas City C & M Subdivision, 8 miles east of the Glenview, IL station, due to a signal outage. The crew was flagged by the location.

Train	Delay	Comment
336(18)	27"	
337(18)	07"	CHI - Turn Late Inbound 336(18)
337(18)	25"	
7/27(18)	28"	

Train 713(19) West of Hanford, CA - Freight Train Interference

18JUL25: Train 713(19) was delayed at Calwa, MP 993.7/BNSF Bakersfield Subdivision, 25.7 miles west of Hanford, meeting BNSF freight trains BN 8133 and BN 7094. This was caused by several speed restrictions between Fresno, CA (FNO) and Madera, CA (MDR), and excessive train interference resulting from the speed restrictions.

WBS#: B.TR.100150.5898

Train	Delay	Comment
713(19)	1'01"	
702(18)	51"	
710(18)	49"	
712(18)	15"	
714(18)	15"	
715(18)	37"	
719(18)	23"	
716(18)	22"	
717(18)	26"	

Train 302(18) St. Louis, MO - Car Failure

18JUL25: Train 302(18), operating with Locomotive ID4623 and 5 cars, was delayed departing the St. Louis, MO Gateway Station, due to issues with the doors on Car ID 46130.

Train	Delay	Comment
302(18)	33"	

Train 14(17) North of Sacramento, CA - Engine Failure

18JUL25: Train 14(17) with E61/313, 8 coaches, and 217 passengers, stopped north of Sacramento, CA, on UP Valley subdivision after trail unit E/313 shut down and stopped providing HEP. The crew switched HEP from the trail unit to the lead unit E/61 and proceeded to 10 miles north to Haggin siding to further trouble shoot E/313. The crew worked with CNOC mechanical and rebooted the trail unit. Once the unit was rebooted the crew operated at a reduced speed of 35MPH for 10 miles per CNOC mechanical instructions.

As a result of ongoing issues with E/313, UPRR freight locomotive UP 8105 was added to Train 14(17) at Dunsmuir, MP 321.3/UPRR Black Butte Subdivision.

Train 14(17) then incurred further delay at Mt. Shasta, MP 336.4 for a recrew as a result of the onboard crew expiring on hours at 10:44AM-PT. A UPRR pilot and the Portland-based Amtrak crew were dispatched from Klamath Falls.

The late operation and arrival of train 14(17) to Klamath Falls, OR (KFS) resulted in the operating crew arriving later than usual and not being fully rested for an on-time departure of train 11(18). Once the outbound crew was legally rested under Hours of Service regulations they went on-duty at 11:30 pm-pt. Once the crew was on-duty train 11(18) was able to depart KFS.

Work Element WBS #B.TR.100150.5895

WBS#: B.TR.100150.5895

Train	Delay	Comment
14(17)	2'09"	DUN - added freight loco UP 8105
14(17)	2'27"	SAC-RDD
14(17)	1'09"	Recrew at Mt. Shasta
11(18)	1'09"	KFF - Hold for crew rest
14(17)	50"	Daily Inspection PDX

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on

371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage
7 (8)	WTN	348		HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
3 (16)	XAR	BNSF5173	TM#4 cutout// Helper Raton pass	LAX	
14 (17)	DUN	UP8105	Shutdown	SEA	
22 (18)	LVW	UPRR6347	Independent brake inop	CHI	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/18/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	298	30	90%	5,212	456	91%	83,981	6,481	92%
Northeast Corridor	98%	79	10	87%	1,376	183	87%	22,561	2,416	89%
Acela	98%	21	3	86%	383	62	84%	6,298	830	87%
Northeast Regional	98%	58	7	88%	993	121	88%	16,263	1,586	90%
State Supported	98%	190	10	95%	3,341	174	95%	52,764	2,687	95%
Long Distance	98%	29	10	66%	495	99	80%	8,518	1,372	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/18/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	298	30	90%	5,212	456	91%	83,981	6,481	92%
Northeast Corridor	98%	79	10	87%	1,376	183	87%	22,561	2,416	89%
Acela	98%	21	3	86%	383	62	84%	6,298	830	87%
Northeast Regional	98%	58	7	88%	993	121	88%	16,263	1,586	90%
On Spine Northeast Regional	98%	30	3	90%	514	61	88%	8,248	839	90%
Richmond / Newport News / Norfolk	98%	12	2	83%	211	49	77%	3,391	513	85%
Roanoke	98%	4	2	50%	72	6	92%	1,158	156	87%
Springfield Shuttles	98%	12	-	100%	196	5	97%	3,466	78	98%
State Supported	98%	190	10	95%	3,341	174	95%	52,764	2,687	95%
Borealis	98%	2	-	100%	36	5	86%	567	64	89%
Capitol Corridor	98%	28	2	93%	472	14	97%	6,932	149	98%
Carolinian	98%	2	-	100%	36	6	83%	582	48	92%
Cascades	98%	14	-	100%	252	12	95%	3,953	280	93%
Downeaster	98%	10	-	100%	176	1	99%	2,764	45	98%
Empire	98%	20	2	90%	360	25	93%	6,246	325	95%
Adirondack	98%	2	-	100%	36	2	94%	582	43	93%
Berkshire Flyer	98%	1	-	100%	7	1	86%	13	3	77%
Ethan Allen Express	98%	2	-	100%	36	5	86%	582	39	93%
Maple Leaf	98%	2	-	100%	36	2	94%	582	56	90%
New York - Albany	98%	9	1	89%	173	6	97%	3,324	93	97%
New York - Niagara Falls	98%	4	1	75%	72	9	88%	1,163	91	92%
Heartland Flyer	98%	2	-	100%	32	1	97%	574	17	97%
Hiawatha	98%	12	-	100%	209	7	97%	3,322	122	96%
Illinois	98%	12	2	83%	239	17	93%	4,006	273	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	72	2	97%	1,152	45	96%
Illini / Saluki	98%	4	1	75%	72	7	90%	1,152	43	96%
Lincoln Service	98%	4	1	75%	95	8	92%	1,702	185	89%
Keystone	98%	26	1	96%	422	22	95%	6,736	410	94%
Lincoln / Missouri	98%	2	-	100%	36	9	75%	576	84	85%
Michigan	98%	10	-	100%	176	14	92%	2,780	268	90%
Blue Water	98%	2	-	100%	36	4	89%	578	86	85%
Pere Marquette	98%	2	-	100%	34	1	97%	580	26	96%
Wolverine	98%	6	-	100%	106	9	92%	1,622	156	90%
Missouri	98%	2	-	100%	34	1	97%	560	15	97%
Pacific Surfliner	98%	24	2	92%	432	9	98%	6,210	231	96%
Pennsylvanian	98%	2	-	100%	36	7	81%	582	67	88%
Piedmont	98%	8	-	100%	143	-	100%	2,312	32	99%
San Joaquins	98%	12	1	92%	214	19	91%	3,480	200	94%
Vermont	98%	2	-	100%	36	5	86%	582	57	90%
Long Distance	98%	29	10	66%	495	99	80%	8,518	1,372	84%
Auto Train	98%	2	-	100%	36	3	92%	570	96	83%
California Zephyr	98%	2	1	50%	36	12	67%	579	134	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	15	7	53%	247	51	79%
City Of New Orleans	98%	2	-	100%	36	6	83%	568	52	91%
Coast Starlight	98%	2	1	50%	38	2	95%	585	87	85%
Crescent	98%	2	-	100%	36	4	89%	582	68	88%
Empire Builder	98%	4	2	50%	67	11	84%	1,118	144	87%
Floridian	98%	2	2		35	12	66%	492	173	65%
Lake Shore Ltd	98%	2	1	50%	36	11	69%	980	112	89%
Palmetto	98%	2	1	50%	36	4	89%	580	38	93%
Silver Meteor	98%	2	-	100%	36	6	83%	578	114	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	36	9	75%	580	146	75%
Sunset Ltd	98%	2	1	50%	16	5	69%	246	44	82%
Texas Eagle	98%	2	-	100%	36	7	81%	652	88	87%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/18/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	300	8	97%	5,235	133	97%	84,014	2,005	98%
Northeast Corridor	98%	80	4	95%	1,377	37	97%	22,514	635	97%
Acela	98%	22	-	100%	384	8	98%	6,301	164	97%
Northeast Regional	98%	58	4	93%	993	29	97%	16,213	471	97%
State Supported	98%	192	3	98%	3,344	52	98%	52,751	872	98%
Long Distance	98%	28	1	96%	514	44	91%	8,611	496	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/18/25											
Day			Month to Date					Year to Date			
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	300	8	97%		5,235	133	97%	84,014	2,005	98%
Central Division	98%	65	1	98%		1,190	56	95%	19,229	663	97%
Northeast Division	98%	96	4	96%		1,663	31	98%	27,679	645	98%
Southeast Division	98%	68	1	99%		1,151	31	97%	18,581	439	98%
Southwest Division	98%	71	2	97%		1,231	15	99%	18,525	258	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/18/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	300	8	97%	5,235	133	97%	84,014	2,005	98%
Central Division	98%	65	1	98%	1,190	56	95%	19,229	663	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	41	-	100%	584	2	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	26	-	100%	480	40	92%	7,756	427	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	36	-	100%	560	3	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	17	-	100%	290	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	35	-	100%	564	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	105	3	97%	1,668	12	99%
MSP	98%	1	-	100%	18	1	94%	279	7	97%
PDX	98%	5	-	100%	86	1	99%	1,398	36	97%
PNT	98%	3	-	100%	53	1	98%	800	8	99%
PTH	98%	1	-	100%	18	-	100%	289	6	98%
QCY	98%	2	-	100%	34	-	100%	564	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	145	8	94%	2,272	121	95%
SPK	98%	1	-	100%	18	-	100%	299	2	99%
STL	98%	3	1	67%	64	2	97%	1,141	18	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	36	-	100%	557	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	96	4	96%	1,663	31	98%	27,679	645	98%
ALB	98%	7	-	100%	126	1	99%	2,035	26	99%
BON	98%	5	-	100%	88	-	100%	1,352	3	100%
BOS	98%	19	1	95%	322	6	98%	5,439	128	98%
BRK	98%	5	-	100%	61	-	100%	1,322	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	18	-	100%	289	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	33	-	100%	560	-	100%
HFD	98%	2	-	100%	26	-	100%	172	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	18	1	94%	289	6	98%
NFL	98%	2	-	100%	36	-	100%	582	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	85	-	100%	1,492	35	98%
NYP	98%	40	3	93%	699	22	97%	11,693	407	97%
POR	98%	-	-	100%	24	-	100%	24	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	16	-	100%	287	1	100%
SPG	98%	5	-	100%	86	1	99%	1,782	20	99%
TWO	98%	1	-	100%	18	-	100%	288	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	68	1	99%	1,151	31	97%	18,581	439	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	87	1	99%	1,441	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/18/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	300	8	97%	5,235	133	97%	84,014	2,005	98%
Southeast Division	98%	68	1	99%	1,151	31	97%	18,581	439	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	204	2	99%	3,149	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	18	-	100%	285	11	96%
MIA	98%	2	-	100%	35	2	94%	560	30	95%
NFK	98%	3	1	67%	51	2	96%	801	5	99%
NOL	98%	2	-	100%	38	1	97%	645	21	97%
NPN	98%	2	-	100%	36	1	97%	555	4	99%
PGH	98%	1	-	100%	18	-	100%	290	3	99%
PHL	98%	5	-	100%	78	3	96%	1,244	36	97%
RGH	98%	4	-	100%	64	-	100%	1,167	5	100%
RNK	98%	2	-	100%	33	-	100%	550	8	99%
RVM	98%	1	-	100%	18	-	100%	282	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	16	1	94%	272	1	100%
SFA	98%	1	-	100%	18	-	100%	285	18	94%
WAS	98%	25	-	100%	427	18	96%	6,902	265	96%
Southwest Division	98%	71	2	97%	1,231	15	99%	18,525	258	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	18	-	100%	291	-	100%
BFD	98%	6	-	100%	106	-	100%	1,729	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	18	3	83%	298	23	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	17	-	100%	323	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	54	-	100%	850	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	10	-	100%	170	1	99%	2,229	63	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	15	-	100%	286	-	100%
OKJ	98%	12	1	92%	200	7	97%	3,053	68	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	237	1	100%	3,468	13	100%
SAN	98%	12	1	92%	214	2	99%	2,636	24	99%
SAS	98%	1	-	100%	18	1	94%	287	3	99%
SJC	98%	7	-	100%	125	-	100%	1,865	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	36	-	100%	569	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	2	-	100%	49	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DATE 7/18/2025 12:00..	Diesel Locomotive	Electric Locomotives			High Speed Trainset			Amfleet I	California Cars (C..	Surfliner	Cab Car	Talgo	Viewliner II	Grand Total
	ENG	ENG	CAR	MTI	ENG	CAR	MTI	CAR	CAR	CAR	ENG	CAR	CAR	
Fuel/Fuel Gauge P..	276													276
Electrical Problems	4	111												115
Cab Signal Failure	107													107
Wayside Hot Box ..		7	50											57
Air/Brake Problems	42						9							51
Door Problems								15	4	13		6	3	41
HEP Problems	38													38
Noise/Smoke Und..	6					28								34
On-Board Hot Jour..	24			10										34
480V Trainline Pro..		31												31
Paperwork Improp..			28											28
Loading Problems	4				10						8			22
Traction Motor Pro..	3	10												13
Horn/Bell Problems	10													10
I-ETMS Problem	10													10
Wheel Chair Lift									10					10
Engineer Cab Furn..		8												8
Tilt System Proble..						6								6
Wheel Defects						4								4
Grand Total	524	167	78	10	10	38	9	15	14	13	8	6	3	895