



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, July 20, 2025

Rules:1-50



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/19/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	259	22	91.5%	5,474	658	88.0%	84,181	8,327	90.1%
Central Division	91.5%	64	5	92.2%	1,252	141	88.7%	19,281	1,881	90.2%
Northeast Division	95.0%	78	7	91.0%	1,723	236	86.3%	27,678	2,999	89.2%
Southeast Division	94.5%	53	4	92.5%	1,204	148	87.7%	18,633	1,862	90.0%
Southwest Division	90.5%	64	6	90.6%	1,295	133	89.7%	18,589	1,585	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/19/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	91,613	25,810	72%	1,979,965	639,310	68%	27,365,358	7,357,291	73%
Northeast Corridor	80%	37,301	11,466	69%	848,255	259,871	69%	12,148,665	3,136,517	74%
Acela	82%	4,687	1,234	74%	172,579	52,181	70%	2,526,496	606,847	76%
Northeast Regional	78%	32,614	10,232	69%	675,676	207,690	69%	9,622,169	2,529,670	74%
Richmond / Newport News / Norfolk	73%	10,767	4,937	54%	215,092	91,368	58%	3,105,244	1,063,905	66%
Springfield Shuttles	89%	394	55	86%	8,340	1,939	77%	174,337	26,583	85%
Roanoke	70%	2,617	971	63%	57,646	16,678	71%	811,823	213,903	74%
On Spine Northeast Regional	83%	18,836	4,269	77%	394,598	97,705	75%	5,530,765	1,225,279	78%
State Supported	80%	40,395	8,241	80%	873,996	227,713	74%	11,685,543	2,587,446	78%
Borealis	60%	510	418	18%	11,999	8,438	30%	168,706	71,616	58%
Capitol Corridor	90%	2,379	326	86%	65,925	5,777	91%	875,120	94,481	89%
Carolinian	60%	1,019	323	68%	20,008	11,263	44%	335,818	139,687	58%
Cascades	60%	2,442	702	71%	57,221	16,258	72%	740,101	254,284	66%
Downeaster	82%	1,853	41	98%	34,992	8,386	76%	413,674	101,379	75%
Empire	83%	5,069	2,604	49%	111,923	44,724	60%	1,573,905	347,020	78%
Adirondack	75%	383	248	35%	7,898	4,966	37%	85,893	27,665	68%
Ethan Allen Express	85%	477	477	0%	12,103	7,887	35%	157,314	41,211	74%
Maple Leaf	75%	798	604	24%	17,148	10,676	38%	213,225	65,839	69%
New York - Albany	90%	2,092	571	73%	44,368	12,200	73%	731,344	115,634	84%
New York - Niagara Falls	75%	1,319	704	47%	27,651	7,350	73%	381,484	94,249	75%
Berkshire Flyer	60%	0	0	-	2,755	1,645	40%	4,645	2,422	48%
Heartland Flyer	70%	321	301	6%	4,952	3,889	21%	64,471	29,952	54%
Hiawatha	90%	1,939	0	100%	40,961	5,505	87%	491,473	64,870	87%
Illinois	78%	2,006	280	86%	52,996	18,061	66%	723,408	175,138	76%
Carl Sandburg / Illinois Zephyr	80%	425	19	96%	9,187	1,839	80%	115,865	14,928	87%
Illini / Saluki	80%	783	6	99%	17,801	4,769	73%	256,098	33,640	87%
Lincoln Service	75%	798	255	68%	26,008	11,453	56%	351,445	126,570	64%
Keystone	92%	5,268	0	100%	147,305	12,082	92%	2,112,093	286,764	86%
Lincoln / Missouri	60%	779	606	22%	16,533	10,503	36%	210,510	115,384	45%
Michigan	69%	2,282	326	86%	48,052	12,494	74%	566,067	158,953	72%
Blue Water	70%	488	62	87%	11,799	3,300	72%	140,398	41,192	71%
Pere Marquette	85%	200	0	100%	5,785	1,128	81%	74,861	9,760	87%
Wolverine	65%	1,594	264	83%	30,468	8,066	74%	350,808	108,001	69%
Missouri	80%	324	15	95%	5,086	3,571	30%	63,918	23,059	64%
Pacific Surfliner	85%	8,377	412	95%	141,983	19,513	86%	1,676,592	268,864	84%
Pennsylvanian	72%	814	0	100%	18,339	5,334	71%	254,354	67,715	73%
Piedmont	73%	1,146	108	91%	19,019	6,103	68%	328,210	79,525	76%
San Joaquins	73%	2,643	1,381	48%	51,511	26,077	49%	715,323	200,447	72%
Vermont	75%	1,224	398	67%	25,191	9,735	61%	371,800	108,308	71%
Long Distance	57%	13,917	6,103	56%	257,714	151,726	41%	3,487,625	1,629,726	53%
Auto Train	57%	790	0	100%	15,773	5,245	67%	218,545	136,448	38%
California Zephyr	45%	1,264	534	58%	22,465	17,907	20%	285,108	124,407	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	343	0	100%	5,323	2,554	52%	79,373	39,569	50%
City Of New Orleans	75%	680	214	69%	11,020	4,698	57%	185,820	52,907	72%
Coast Starlight	65%	1,071	552	48%	19,977	6,680	67%	305,778	127,426	58%
Crescent	60%	1,057	231	78%	20,349	7,612	63%	252,417	65,136	74%
Empire Builder	55%	1,472	600	59%	23,523	14,777	37%	278,514	123,280	56%
Floridian	40%	2,480	1,669	33%	30,595	25,291	17%	393,950	289,071	27%
Lake Shore Ltd	70%	1,165	102	91%	21,926	7,964	64%	293,763	80,592	73%
Palmetto	65%	943	135	86%	19,031	10,024	47%	287,179	111,140	61%
Silver Meteor	45%	1,016	795	22%	20,047	13,651	32%	269,433	141,557	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,049	684	35%	20,367	15,984	22%	233,303	142,910	39%
Sunset Ltd	50%	0	0	-	5,333	2,843	47%	76,972	28,639	63%
Texas Eagle	60%	587	587	0%	21,985	16,496	25%	269,875	144,148	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 19, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	139,925	1,977,979	707	1,852,106	30,421,916	609

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	6,941	576,202	120	98,025	8,904,281	110
INFRASTRUCTURE PLANNED	90	4,054	576,202	70	91,200	8,904,281	102
FLEET RELIABILITY	83	24,471	1,977,979	124	293,351	30,421,916	96
TRAIN OPERATIONS	382	104,459	1,977,979	528	1,369,530	30,421,916	450

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 1689(19) North of Saco, ME - Police Related

20JUL25: Train 1689(19) was delayed 3 miles north of Saco, ME at MP23.8 on the CSX Portland Subdivision due to a police hold for reported trespassers fouling the tracks ahead. Once hold was lifted, Train 1689(19) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1689(19)	39"	

Train 283(19) West of Buffalo, NY - Weather

19JUL25: Train 283(19) was delayed 4 miles west of Buffalo, NY Exchange Station at MP6.8 on the CSX Niagara Subdivision due to a reported sinkhole ahead. Crew walked the are to inspect, found no exceptions and proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
283(19)	53"	

Train 147(19) Alexandria, VA - Horn Failure

19JUL25: Train 147(19) E/44, 8 cars, was delayed at Alexandria, VA/ MP105.1 on the CSX RF&P Subdivision due to horn failure on engine E/44. Crew worked with CNOC mechanical to troubleshoot issue. Unable to resolve, and no available mechanical technician to send from Washington, the train continued to Manassas, VA to be met there by mechanical. The train lost additional time account of needing to protect each crossing enroute to Manassas. Mechanical met the train and was able to temporarily fix the issue allowing Train 147(19) to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
147(19)	38"	ALX
147(19)	41"	MSS
147(19)	13"	WAS - MSS

Train 2218(19) Washington, DC - Engine Failure

19JUL25: Train 2218(19), TS#17, was originally delayed at Washington, DC due to a short turn of Train 2251(19)'s equipment that arrived at 3:00PM. While in the station, mechanical started troubleshooting issues found with rear PC/2011. It was found that the emergency push button on PC/2011 was pushed in. This issue was thought be resolved but then the trainset experienced more issues reporting traction and brake issues. As a result, Train 2218(19) was cancelled in its entirety with all passengers moved to Train 142(19) to continue to their final destination.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2218(19)	Cancelled	

Train 156(19) Newark, DE - Deer Strike

19JUL25: Train 156(19) E/650, 8 cars, struck a deer operating north on No. 2 track between Bacon - Davis. Crew proceeded to Newark, DE station to inspect train and secured a loose hose. Once secured, Train 156(19) continued north at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
156(19)	16"	

Train 49(19) New York, NY - Engine Failure

19JUL25: Train 49(19), E/98-E/703, was delayed at New York, NY due to mechanical onboard troubleshooting head end power issues. Once resolved, Train 49(19) departed the station operating 41 minutes late.

Train	Delay	Comment
49(19)	41"	

Train 80(19) Richmond, VA - Pump Cars

19JUL25: Train 80(19) was delayed at Richmond, VA/MP4.6, on the CSX Richmond Terminal Subdivision, due to C/25054, C/81523, and C/25071 reported full and needing to be pumped. Train 153(19) held just north of the station for Train 80(19) to clear the station track.

Train	Delay	Comment
80(19)	1'12"	
153(19)	20"	

Train 68(19) South of St-Lambert, QC - Heat Orders

19JUL25: Train 68(19) was delayed starting 2.2 miles south of St-Lambert, QC/MP70.3, on the CNRR Rouses Point Subdivision, due to 25MPH heat orders between Southwark/MP42.7 and Rouses Point/MP0.0.

Train	Delay	Comment
68(19)	45"	

Train 153(19) South of Fredericksburg, VA - Passenger Medical

19JUL25: Train 153(19) stopped 8 miles south of Fredericksburg, VA/MP59.3, on the CSX RF&P Subdivision, at MP51.3 waiting on emergency services to respond for a passenger experiencing a seizure. The passenger was removed from the train by paramedics and brought to the local area hospital for observation.

Train	Delay	Comment
153(19)	44"	

Train 464(19) New Haven, CT - Engine Failure

19JUL25: Train 464(19) was cancelled in its entirety at New Haven, CT account E/93 bad ordered for wheels with no available replacement. Two alternate buses were secured. Bus #1 operated express making stations stops at New Haven, Hartford, and Springfield. Bus #2 made all station stops.

Due to this, the following trains were also adjusted/cancelled:

Train 400(20) canceled, no passengers affected. Train 497(20) canceled with alternate bus transportation. Train 461(20) canceled between Greenfield, MA and Springfield, MA with alternate bus transportation, train originated at SPG operating Springfield, MA to New Haven, CT.

WBS#: B.TR.100151.0760

Train	Delay	Comment
464(19)	Cancelled	W/ALT
497(20)	Cancelled	w/ALT
461(20)	Originates	SPG w/ALT
400(20)	Cancelled	

CFRC PTC / Server Outage - South of Deland, FL

19JUL25: CFRC reported their PTC and 48 Wayside Interface Units (WIU) were down due to an unplanned outage. This outage started 11.8 miles south of Deland, FL/MP750.1, on the CFRC Orlando Subdivision, between Lake Monroe/MP763.1 and MP788.9. During this time, Trains 41(17) and 97(18) were heavily delayed operating through the area. They proceeded at restricted speeds to each control point and then gain verbal permission to proceed to the next.

Train 98(19) was delayed through the area as well but the systems started to come back allowing them to resume track speed at MP777.0.

Train	Delay	Comment
41(17)	1'48"	
97(18)	1'16"	
98(19)	43"	
40(19)	13"	

CSX Heat orders

19JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Charleston, Jacksonville Terminal, Nahunta, Sanford, Savannah and South End.

Train	Delay	Comment
79(19)	05"	
52(19)	16"	
89(19)	24"	
90(19)	07"	
98(19)	27"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold
371(19) - 10 oversold
305(18) - 13 oversold
300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold
371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold
371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St.

Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

Train 22(19) Malvern, AR - Freight Train Interference

20JUL25: Train 22(19) was delayed 4 miles east of Malvern, AR, on UP Little Rock subdivision, due to following UP9815 from MP384 to MP345.

Train	Delay	Comment
22(19)	31"	

Train 48/448(19) Toledo, OH - Signal

20JUL25: Train 48/448(19) was delayed departing Toledo, OH, on NS Cleveland-Toledo subdivision, due to PTC initialization issues. After trouble shooting with NS PTC desk, train 48/448(19) was instructed to cut out PTC.

Train	Delay	Comment
48/448(19)	31"	

Train 370(19) Chicago, IL - Initial Terminal Delay

20JUL25: Train 370(19) was delayed 53 minutes departing Chicago, Illinois due to a disabled fuel truck and a venture car step issue. At 533pm, a Communicator Page was sent out stating that the fuel truck was disabled. This necessitated taking the entire train set to the 16th Street Diesel Shop to fuel the locomotive. Train 370(19) was released at 515pm, and the equipment spotted at the 16th Street Diesel Shop for fueling at 547pm. Fueling was completed at 602pm. Train 370(19) shoved to the station at 604pm and set in the station at 620pm with 132 passengers to board. Train was ready to depart at 637pm. However, the stairs would not retract on Venture car ID4111 requiring mechanical assistance. After retracting the stairs on Venture car ID4111, Train 370(19) departed Chicago at 723pm; 53 minutes late.

Train	Delay	Comment
370(19)	53"	

Train 307(19) Chicago, IL - Initial Terminal Delay

20JUL25: 19JUL25, Train 307(19) was delayed 1 hour and 29 minutes departing Chicago, Illinois account replacing a bad order locomotive. Charger locomotive ID4630 was bad ordered at 558pm account it would not pass an X-ITCS test. Replacement locomotive ID4623 was released at 602pm but could not be picked up until Train 370(19)'s equipment was done being fueled on D7. Note: Due to a disabled fuel truck in the yard, the entire Train 370(19) was brought to the locomotive shop for fueling. Blue flags were dropped on Train 307(19) at 644pm and replacement locomotive ID4623 tied on at 705pm. Train 307(19) was released by mechanical at 806pm and set in the station at 815pm with 230 passengers to board. Train 307(19) departed Chicago at 839pm; 1 hour and 29 minutes late. An additional 13-minute delay was incurred wyeing the train on departure.

Train	Delay	Comment
307(19)	1'42"	

Train 14(18) Oregon City, OR - Freight Train Interference

19JUL25: Train 14(18) was delayed at Oregon City, OR (ORC) on the Union Pacific Railway Brooklyn Subdivision. Union Pacific Railway reported a freight train had derailed in Albina, OR and tracks were blocked south of Portland with trains wainig to enter the Albina yard. A Union Pacific manager responded to the scene and assisted in getting trains to clear a route so that Amtrak trains could proceed. Train 14(18) and 508(19) were held at Oregon City, OR and train 507(19) was held at Portland, OR. Once a route was available train traffic was resumed.

Train	Delay	Comment
508(19)	1'15"	
507(19)	1'30"	
14(18)	2'47"	
14(18)	45"	Daily Inspection on Locos.

Train 507(19) Portland, OR - Signal

19JUL25: Train 507(19) was delayed north of Portland, OR (PDX) at MP 6.0 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. There was a "code brown" - train dispatchers temporarily lose control of the signals and switches - issued between MP 6.0 and PDX. Train crews were required to wait for verbal authority from the train dispatcher and operate at reduced speeds in the area.

Train	Delay	Comment
507(19)	15"	"code brown" signal problems
506(19)	27"	hold for inbound train 507(19)

Train 307(19) North of Summit, IL - Freight Train Interference

20JUL25: Train 307(19) was delayed 7 miles north of Summit, IL, on Cn Joliet subdivision, due to freight cross traffic obstructing the route at control point Brighton. Once the freight cleared and a route was made available, train 307(19) was able to proceed.

Train	Delay	Comment
307(19)	1'01"	

Train 519(19) Vancouver, BC - Freight Train Interference

19JUL25: Train 519(19) was delayed departing the initial terminal of Vancouver, BC (VAC) on the Canadian National Railway (CN) New Westminster Subdivision. A CN yard crew was assembling a freight train at Vancouver yard and blocking the route for train 519(19) to depart VAC. Once the yard crew cleared the track, train 519(29) was able to proceed. Train 519(29) incurred additional delay at MP 144.8 for a second CN Freight train, CN/8796, to clear the Fraser bridge.

Train	Delay	Comment
519(19)	45"	VAC
519(19)	29"	Fraser Bridge

Train 714(19) Fresno, CA - Trespasser Incident

19JUL25: At approximately 3:53 PM-PT train 714(19) - operating with camera equipped cab car CC/8311 in the lead, five (5) additional cars and locomotive CDTX/2007 pushing - struck an injured at trespasser at MP 999.53 on the Burlington Northern Santa Fe Railway Stockton Subdivision in the City of Fresno, Fresno County, California. This incident occurred on the public highway crossing at grade for East Olive Ave (US DOT 258569A). The crossing was equipped with quad gates, flashing lights and bells which were observed to be working at the time the incident occurred. Train traffic was halted in both directions while local authorities responded to and investigated the incident. Train 714(19) was operating east at 06 MPH on the single main track with a posted track speed of 35 MPH. There were no initial reports of injuries to the 59 passengers or crew, and no reports of damage to Amtrak equipment. Once the scene was released by authorities train 714(19) advanced to Fresno, CA where division management and a relief crew met the train. Once the relief crew assumed operation train 714(19) was able to depart FNO and proceed east.

National Response Center: 1437397
California Office of Emergency Services: 25-3589
Amtrak Police Case: 10370

Google Maps Location of Incident:
<https://maps.app.goo.gl/GpdDuvNwW7p1uLuR8>
36.757407, -119.787208
2004-2024 E Olive Ave, Fresno, CA 93701

WBS#: B.TR.100150.5902

National Response Center Number: 1437397

Train	Delay	Comment
717(19)	24"	
719(19)	36"	
716(19)	13"	
714(19)	1'27"	FNO - Hold for recrew
714(19)	1'06"	Trespasser Strike

Train 58(19) North of Hazlehurst, MS - Routing

19JUL25: Train 58(19) was delayed 11 miles north of Hazlehurst, MS, on CN McComb subdivision, due to rough tracks reported ahead of them. Train 58(19) held waiting for a track inspector to respond. Once the tracks were inspected, no exceptions were found and train 58(19) was able to proceed at normal operating speed.

Train	Delay	Comment
58(19)	58"	

Train 14(18) North of Chemult, OR - Freight Train Interference

19JUL25: Train 14(18) was delayed north of Chemult, OR (CMO) at Cruzatte Siding on the Union Pacific Railway Cascade Subdivision. A disabled freight train was blocking the single main track ahead after the train stalled out while in a tunnel and lost contact with the distributed power units (DPU) on the rear of the train. Union Pacific management responded to the scene and assisted the freight crew in reversing out of the tunnel, ensuring the remote connection to the DPU units was restored, and advancing the train clear of the siding track at Cruzatte to open a route for train 14(18). Once the route was established train 14(18) was able to proceed north.

Train	Delay	Comment
14(18)	1'55"	

Train 305(19) Chicago, IL - Initial Terminal Delay

20JUL25: Train 305(19) was delayed 41 minutes departing Chicago, Illinois account waiting for a re-crew engineer (10 minutes) and the X-ITCS cab signals not being tested on the locomotive (31 minutes). An additional 18-minute delay was then incurred testing the X-ITCS cab signals on the mainline. Equipment turned off inbound 351(19) this date and the diesel pit general foreman requested locomotive ID4602 be added off inbound 380(19) for a test run. An initial 10-minute delay was incurred due to a late arriving relief engineer. Once the relief engineer took charge of the equipment it was reported that Charger ID4602 had not had its X-ITCS cab signals tested. The unit was added off inbound 380(19) which is a PTC-only route. Once diesel personnel were onboard, Train 305(19) departed Chicago at 601pm; 41 minutes late. Testing of the X-ITCS cab signals resulted in an additional 18-minute delay on the mainline.

Train	Delay	Comment
305(19)	10"	WAITING FOR RE-CREW ENGINEER
305(19)	31"	X-ITCS NOT TESTED ON LOCO
305(19)	18"	TESTING X-ITCS ON MAINLINE

Train 6(17) Encompassing Princeton, IL - Car Failure

19JUL25: Train 6(17), operating with Locomotive 68, Locomotive 15 and 9 cars, stopped at MP 125.4 on the Burlington Northern Santa Fe Mendota Subdivision, 21 miles west of the Princeton, IL station, due to sleeper Car 32047 actuated a wayside detector. The reported axle had a history of trending hotter. BNSF instructed to crew to continue 30 miles to Zearing / MP 95.4, not exceeding 30 mph, before setting the car out.

Train	Delay	Comment
6(17)	2'07"	
6(17)	1'12"	HBD

Oakland, CA - Servicing

19JUL25: Trains were delayed departing the Oakland, CA Maintenance Facility (OMF) account of a short of personnel to service the equipment.

Train 720(19) was released at 7:25 a.m. (PDT), 13 minutes after the scheduled departure time from Oakland, CA Jack London Station. Train 720(19) departed OMF at 7:43 a.m. (PDT).

Train 710(19) was released at 7:55 a.m. (PDT), 19 minutes after the scheduled departure time from Oakland, CA Jack London Station. Train 710(19) departed OMF at 8:22 a.m. (PDT).

Train 6(19) was released at 8:40 a.m. (PDT), 15 minutes after the scheduled departure time from Emeryville, CA station. Crew reported head end power issues once the equipment was released, causing additional delays for technicians to repair. Train 6(19) departed OMF at 9:28 a.m. (PDT).

WBS#: B.TR.100150.5899

Train	Delay	Comment
720(19)	43"	
710(19)	1'01"	
6(19)	1'31"	

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

· Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

· Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

· Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

· Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

· Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

· Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

· Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

· Bus 3470 will provide alternate transportation between HFD and SPG

· Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

· Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

· Deadhead Train 426 will turn for Train 471 at HFD

· Train 470 will turn for Train 473 at HFD

Train 2252(19) Washington, DC - Short Turn

19JUL25: Due to Washington's 55-hour power outage, High Speed Rail had to short turn Train 2203(19) in Washington, DC that arrived on time at 10:57AM for Train 2252(19).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2252(19)	36"	

Train 57(19) South of St. Albans, VT - M of W Work

19JUL25: Train 57(19) was delayed starting 4.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, due to a 10MPH speed restriction from MP128-MP119 due to Maintenance of Way working in the area

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
57(19)	41"	

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/19/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	259	22	91.5%	5,474	658	88.0%	84,181	8,327	90.1%
Central Division	91.5%	64	5	92.2%	1,252	141	88.7%	19,281	1,881	90.2%
Northeast Division	95.0%	78	7	91.0%	1,723	236	86.3%	27,678	2,999	89.2%
Southeast Division	94.5%	53	4	92.5%	1,204	148	87.7%	18,633	1,862	90.0%
Southwest Division	90.5%	64	6	90.6%	1,295	133	89.7%	18,589	1,585	91.5%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/19/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	259	22	91.5%	5,474	658	88.0%	84,181	8,327	90.1%
Central Division	91.5%	64	5	92.2%	1,252	141	88.7%	19,281	1,881	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	1	50.0%	43	3	93.0%	586	17	97.1%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	25	3	88.0%	505	79	84.4%	7,781	964	87.6%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	38	0	100.0%	562	19	96.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	18	0	100.0%	291	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	37	1	97.3%	566	38	93.3%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	0	100.0%	111	5	95.5%	1,674	93	94.4%
MSP	95.0%	1	0	100.0%	19	2	89.5%	280	14	95.0%
PDX	78.0%	5	0	100.0%	91	9	90.1%	1,403	161	88.5%
PNT	94.0%	3	0	100.0%	56	1	98.2%	803	57	92.9%
PTH	96.0%	1	0	100.0%	19	0	100.0%	290	11	96.2%
QCY	94.0%	2	0	100.0%	36	0	100.0%	566	18	96.8%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	1	87.5%	153	29	81.0%	2,280	329	85.6%
SPK	92.0%	1	0	100.0%	17	1	94.1%	288	14	95.1%
STL	96.0%	3	0	100.0%	67	7	89.6%	1,144	60	94.8%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	38	0	100.0%	559	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	78	7	91.0%	1,723	236	86.3%	27,678	2,999	89.2%
ALB	96.0%	6	0	100.0%	114	5	95.6%	1,963	127	93.5%
BON	94.5%	5	0	100.0%	93	8	91.4%	1,357	91	93.3%
BOS	97.0%	14	1	92.9%	336	37	89.0%	5,453	503	90.8%
BRK	97.0%	5	0	100.0%	66	2	97.0%	1,327	68	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	19	2	89.5%	290	19	93.4%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	35	2	94.3%	562	54	90.4%
HFD	-	-	-	-	26	4	84.6%	172	17	90.1%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/19/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	259	22	91.5%	5,474	658	88.0%	84,181	8,327	90.1%
Northeast Division	95.0%	78	7	91.0%	1,723	236	86.3%	27,678	2,999	89.2%
MTR	97.0%	1	0	100.0%	19	2	89.5%	290	28	90.3%
NFL	97.0%	2	0	100.0%	38	1	97.4%	584	24	95.9%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	4	2	50.0%	89	14	84.3%	1,496	148	90.1%
NYP	94.5%	30	4	86.7%	729	137	81.2%	11,722	1,775	84.9%
POR	-	-	-	-	24	8	66.7%	24	8	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	17	3	82.4%	288	8	97.2%
SPG	95.5%	6	0	100.0%	92	8	91.3%	1,788	84	95.3%
TWO	96.0%	1	0	100.0%	19	0	100.0%	289	11	96.2%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	53	4	92.5%	1,204	148	87.7%	18,633	1,862	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	92	9	90.2%	1,446	94	93.5%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	7	0	100.0%	211	11	94.8%	3,156	99	96.9%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	19	3	84.2%	286	91	68.2%
MIA	90.0%	2	2	0.0%	37	6	83.8%	562	53	90.6%
NFK	94.5%	3	0	100.0%	54	12	77.8%	804	66	91.8%
NOL	92.0%	3	0	100.0%	41	3	92.7%	648	46	92.9%
NPN	96.0%	2	0	100.0%	38	4	89.5%	557	21	96.2%
PGH	92.0%	1	0	100.0%	19	2	89.5%	291	16	94.5%
PHL	97.0%	3	0	100.0%	81	19	76.5%	1,247	176	85.9%
RGH	97.0%	4	0	100.0%	68	2	97.1%	1,171	36	96.9%
RNK	94.0%	2	0	100.0%	35	2	94.3%	552	64	88.4%
RVM	90.0%	1	0	100.0%	19	1	94.7%	283	34	88.0%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	17	1	94.1%	273	11	96.0%
SFA	83.0%	1	0	100.0%	19	1	94.7%	286	79	72.4%
WAS	94.5%	17	2	88.2%	444	62	86.0%	6,918	943	86.4%
Southwest Division	90.5%	64	6	90.6%	1,295	133	89.7%	18,589	1,585	91.5%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	19	0	100.0%	292	7	97.6%
BFD	90.0%	6	0	100.0%	112	13	88.4%	1,735	149	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	19	15	21.1%	299	91	69.6%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	18	2	88.9%	324	42	87.0%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/19/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	259	22	91.5%	5,474	658	88.0%	84,181	8,327	90.1%
Southwest Division	90.5%	64	6	90.6%	1,295	133	89.7%	18,589	1,585	91.5%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	57	2	96.5%	853	62	92.7%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	1	88.9%	179	20	88.8%	2,238	311	86.1%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	16	0	100.0%	287	6	97.9%
OKJ	91.0%	9	4	55.6%	209	33	84.2%	3,062	283	90.8%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	11	0	100.0%	248	22	91.1%	3,479	147	95.8%
SAN	90.0%	12	0	100.0%	226	14	93.8%	2,648	232	91.2%
SAS	85.0%	1	0	100.0%	19	5	73.7%	288	40	86.1%
SJC	95.0%	7	0	100.0%	132	6	95.5%	1,872	72	96.2%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	38	0	100.0%	571	27	95.3%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	2	0	100.0%	49	11	77.6%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/19/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		19	5	73.7%	286	55	80.8%	19	14	26.3%	282	155	45.0%
4	231	19	5	73.7%	287	70	75.6%	19	15	21.1%	286	146	49.0%
5		19	9	52.6%	289	48	83.4%	18	14	22.2%	286	97	66.1%
6	265	19	15	21.1%	289	84	70.9%	19	16	15.8%	288	98	66.0%
7		19	4	78.9%	283	40	85.9%	19	7	63.2%	278	74	73.4%
8		19	14	26.3%	284	106	62.7%	19	14	26.3%	282	135	52.1%
11		19	2	89.5%	291	46	84.2%	19	2	89.5%	284	63	77.8%
14	No OS	19	6	68.4%	292	88	69.9%	19	8	57.9%	290	128	55.9%
19		19	0	100.0%	292	33	88.7%	19	8	57.9%	291	57	80.4%
20		19	1	94.7%	292	14	95.2%	19	4	78.9%	291	46	84.2%
21	89	19	1	94.7%	291	35	88.0%	19	7	63.2%	285	90	68.4%
22	762	19	5	73.7%	288	42	85.4%	19	16	15.8%	287	124	56.8%
27	89	17	4	76.5%	279	21	92.5%	16	7	56.3%	269	93	65.4%
28	37	16	3	81.3%	272	68	75.0%	16	4	75.0%	271	76	72.0%
40		19	3	84.2%	249	36	85.5%	19	14	26.3%	245	153	37.6%
40	75	19	3	84.2%	249	36	85.5%	19	14	26.3%	245	153	37.6%
41	125	17	12	29.4%	246	107	56.5%	18	17	5.6%	243	194	20.2%
42		19	2	89.5%	292	17	94.2%	19	5	73.7%	292	79	72.9%
43		19	2	89.5%	292	25	91.4%	19	6	68.4%	292	66	77.4%
48		19	5	73.7%	291	53	81.8%	19	4	78.9%	291	45	84.5%
49		19	7	63.2%	292	57	80.5%	19	5	73.7%	292	52	82.2%
51		8	1	87.5%	124	23	81.5%	8	2	75.0%	118	40	66.1%
52		19	1	94.7%	286	79	72.4%	19	5	73.7%	286	152	46.9%
53		19	3	84.2%	286	91	68.2%	19	4	78.9%	286	144	49.7%
54	66	6	0	100.0%	90	3	96.7%	6	1	83.3%	90	13	85.6%
57		6	1	83.3%	90	2	97.8%	6	0	100.0%	90	9	90.0%
58		19	2	89.5%	284	23	91.9%	19	3	84.2%	281	56	80.1%
59		19	6	68.4%	283	58	79.5%	18	6	66.7%	279	33	88.2%
63	29	19	12	36.8%	292	58	80.1%	19	17	10.5%	292	149	49.0%
64		19	0	100.0%	292	11	96.2%	19	3	84.2%	292	71	75.7%
65		7	1	85.7%	91	4	95.6%	6	1	83.3%	90	16	82.2%
66		19	3	84.2%	290	56	80.7%	19	1	94.7%	288	37	87.2%
68	51	19	2	89.5%	292	28	90.4%	19	15	21.1%	292	119	59.2%
69		19	2	89.5%	292	22	92.5%	18	7	61.1%	287	34	88.2%
71		18	2	88.9%	291	7	97.6%	18	8	55.6%	289	66	77.2%
72		19	3	84.2%	292	22	92.5%	19	7	63.2%	290	74	74.5%
73		19	3	84.2%	292	15	94.9%	19	9	52.6%	290	144	50.3%
74		19	1	94.7%	288	21	92.7%	19	8	57.9%	286	98	65.7%
75		19	3	84.2%	290	8	97.2%	19	10	47.4%	288	117	59.4%
76	42	19	4	78.9%	288	20	93.1%	18	13	27.8%	286	126	55.9%
77	11	19	2	89.5%	289	12	95.8%	19	9	52.6%	287	129	55.1%
78	19	19	0	100.0%	290	10	96.6%	18	6	66.7%	289	70	75.8%

Amtrak On Time Performance													
Trains Arriving Through: 7/19/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79		19	5	73.7%	292	40	86.3%	17	6	64.7%	289	104	64.0%
80	37	19	3	84.2%	292	24	91.8%	19	13	31.6%	292	86	70.5%
82	64	4	1	75.0%	48	2	95.8%	4	3	25.0%	48	15	68.8%
87	59	6	1	83.3%	90	6	93.3%	6	4	33.3%	90	43	52.2%
88	24	6	2	66.7%	90	8	91.1%	6	2	66.7%	90	24	73.3%
89	40	19	2	89.5%	291	36	87.6%	19	9	52.6%	289	107	63.0%
90		19	1	94.7%	291	12	95.9%	18	8	55.6%	286	72	74.8%
97		19	13	31.6%	288	134	53.5%	19	10	47.4%	287	94	67.2%
98	143	19	3	84.2%	288	18	93.8%	19	13	31.6%	288	149	48.3%
99	60	6	0	100.0%	90	2	97.8%	6	6	0.0%	90	55	38.9%
101		4	0	100.0%	48	3	93.8%	4	1	75.0%	48	8	83.3%
103		6	0	100.0%	90	13	85.6%	6	1	83.3%	90	14	84.4%
106		6	1	83.3%	61	13	78.7%	6	0	100.0%	60	11	81.7%
107		6	0	100.0%	61	15	75.4%	6	1	83.3%	60	16	73.3%
118		6	0	100.0%	90	10	88.9%	6	0	100.0%	90	12	86.7%
135		6	0	100.0%	90	8	91.1%	6	1	83.3%	89	30	66.3%
136		13	1	92.3%	202	40	80.2%	14	4	71.4%	201	42	79.1%
140		6	0	100.0%	90	10	88.9%	6	0	100.0%	90	30	66.7%
142		4	1	75.0%	48	7	85.4%	4	0	100.0%	48	4	91.7%
143		6	3	50.0%	90	4	95.6%	6	0	100.0%	90	6	93.3%
144		4	2	50.0%	47	17	63.8%	4	0	100.0%	47	5	89.4%
146	16	6	0	100.0%	90	11	87.8%	6	2	66.7%	90	37	58.9%
147	78	4	1	75.0%	48	4	91.7%	4	3	25.0%	48	12	75.0%
150		6	2	66.7%	90	22	75.6%	6	0	100.0%	90	34	62.2%
151		19	3	84.2%	289	35	87.9%	19	4	78.9%	288	97	66.3%
152		4	0	100.0%	48	0	100.0%	4	1	75.0%	48	15	68.8%
153	66	6	1	83.3%	90	11	87.8%	6	3	50.0%	90	36	60.0%
155		6	0	100.0%	90	12	86.7%	6	0	100.0%	90	9	90.0%
156	31	6	0	100.0%	90	4	95.6%	6	3	50.0%	90	30	66.7%
158		6	1	83.3%	90	9	90.0%	6	2	66.7%	90	20	77.8%
159		4	0	100.0%	48	1	97.9%	4	0	100.0%	48	7	85.4%
160		6	2	66.7%	90	10	88.9%	6	1	83.3%	89	11	87.6%
161	16	6	0	100.0%	90	3	96.7%	6	3	50.0%	90	52	42.2%
162	17	5	0	100.0%	89	4	95.5%	5	1	80.0%	88	25	71.6%
163		4	0	100.0%	48	5	89.6%	4	0	100.0%	48	21	56.3%
164		6	0	100.0%	90	13	85.6%	6	1	83.3%	90	37	58.9%
165		6	1	83.3%	90	17	81.1%	6	0	100.0%	90	27	70.0%
168		4	2	50.0%	48	6	87.5%	4	1	75.0%	47	7	85.1%
178	30	13	1	92.3%	202	30	85.1%	14	7	50.0%	202	43	78.7%
179	45	13	3	76.9%	200	15	92.5%	14	10	28.6%	201	71	64.7%
194		4	0	100.0%	48	1	97.9%	4	1	75.0%	47	13	72.3%
195	23	6	0	100.0%	90	1	98.9%	6	5	16.7%	90	63	30.0%

Amtrak On Time Performance													
Trains Arriving Through: 7/19/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
232		19	1	94.7%	280	10	96.4%	19	1	94.7%	280	22	92.1%
233	26	17	5	70.6%	288	85	70.5%	17	9	47.1%	287	100	65.2%
234		19	1	94.7%	280	7	97.5%	19	2	89.5%	280	22	92.1%
236		19	0	100.0%	280	5	98.2%	19	2	89.5%	279	46	83.5%
237		16	0	100.0%	275	28	89.8%	16	2	87.5%	273	32	88.3%
239		19	4	78.9%	279	29	89.6%	19	6	68.4%	279	22	92.1%
240		19	0	100.0%	284	24	91.5%	19	5	73.7%	283	27	90.5%
241	16	19	3	84.2%	292	36	87.7%	18	7	61.1%	291	43	85.2%
243		13	5	61.5%	202	37	81.7%	14	6	57.1%	202	28	86.1%
244	22	17	1	94.1%	288	8	97.2%	17	10	41.2%	288	49	83.0%
280		19	0	100.0%	291	11	96.2%	19	1	94.7%	291	52	82.1%
281		19	2	89.5%	292	60	79.5%	18	5	72.2%	290	60	79.3%
283	63	19	6	68.4%	292	63	78.4%	19	9	52.6%	291	62	78.7%
284	18	19	1	94.7%	292	13	95.5%	19	1	94.7%	291	59	79.7%
290	26	19	2	89.5%	292	21	92.8%	18	14	22.2%	290	67	76.9%
291	51	19	7	63.2%	292	45	84.6%	19	14	26.3%	291	60	79.4%
300	20	17	1	94.1%	281	8	97.2%	17	5	70.6%	279	68	75.6%
302		18	2	88.9%	286	20	93.0%	18	7	61.1%	283	97	65.7%
305	116	19	3	84.2%	286	22	92.3%	19	15	21.1%	285	111	61.1%
307		18	2	88.9%	285	38	86.7%	17	9	47.1%	282	104	63.1%
311		18	3	83.3%	282	18	93.6%	18	15	16.7%	278	111	60.1%
316		18	1	94.4%	280	19	93.2%	18	15	16.7%	278	104	62.6%
318	40	19	0	100.0%	288	19	93.4%	19	12	36.8%	284	159	44.0%
319	49	19	1	94.7%	290	19	93.4%	19	16	15.8%	285	177	37.9%
330		16	1	93.8%	236	5	97.9%	16	1	93.8%	235	15	93.6%
331		19	1	94.7%	283	20	92.9%	19	2	89.5%	279	27	90.3%
332		19	1	94.7%	288	17	94.1%	19	3	84.2%	287	44	84.7%
334		19	0	100.0%	288	9	96.9%	19	3	84.2%	283	71	74.9%
335		19	2	89.5%	291	31	89.3%	19	5	73.7%	282	61	78.4%
336		19	1	94.7%	277	7	97.5%	19	6	68.4%	276	81	70.7%
337		19	2	89.5%	280	17	93.9%	19	6	68.4%	279	63	77.4%
338		19	2	89.5%	290	37	87.2%	19	7	63.2%	280	122	56.4%
339		19	0	100.0%	290	42	85.5%	19	2	89.5%	288	50	82.6%
341	11	18	10	44.4%	275	55	80.0%	18	11	38.9%	269	58	78.4%
342		19	0	100.0%	291	18	93.8%	19	1	94.7%	290	44	84.8%
343		3	0	100.0%	42	1	97.6%	3	0	100.0%	42	4	90.5%
350	29	19	2	89.5%	251	27	89.2%	19	13	31.6%	248	126	49.2%
351		19	0	100.0%	280	24	91.4%	19	4	78.9%	279	77	72.4%
352		19	3	84.2%	285	27	90.5%	19	10	47.4%	280	81	71.1%
353		19	0	100.0%	244	6	97.5%	19	1	94.7%	239	36	84.9%
354		18	0	100.0%	284	26	90.8%	18	4	77.8%	281	102	63.7%
355		18	1	94.4%	284	31	89.1%	18	4	77.8%	280	72	74.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/19/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
364	18	19	1	94.7%	290	55	81.0%	19	5	73.7%	289	79	72.7%
365		19	0	100.0%	290	11	96.2%	19	7	63.2%	289	85	70.6%
370	69	18	2	88.9%	291	12	95.9%	17	4	76.5%	290	37	87.2%
371		18	0	100.0%	291	4	98.6%	18	3	83.3%	291	28	90.4%
380		19	1	94.7%	289	11	96.2%	19	1	94.7%	289	27	90.7%
381	38	19	2	89.5%	289	8	97.2%	19	6	68.4%	288	29	89.9%
382		19	1	94.7%	288	11	96.2%	19	5	73.7%	288	38	86.8%
383		19	0	100.0%	290	29	90.0%	19	8	57.9%	289	67	76.8%
390		19	3	84.2%	287	13	95.5%	19	7	63.2%	285	43	84.9%
391		19	0	100.0%	290	6	97.9%	19	4	78.9%	288	53	81.6%
392		19	0	100.0%	290	8	97.2%	19	5	73.7%	287	31	89.2%
393		19	1	94.7%	289	13	95.5%	19	8	57.9%	286	41	85.7%
400		6	0	100.0%	88	8	90.9%	6	0	100.0%	87	4	95.4%
405		4	0	100.0%	88	1	98.9%	4	0	100.0%	88	1	98.9%
450		4	1	75.0%	88	9	89.8%	4	1	75.0%	88	12	86.4%
460		4	0	100.0%	90	17	81.1%	4	0	100.0%	88	30	65.9%
461		6	0	100.0%	90	5	94.4%	6	0	100.0%	90	3	96.7%
463		3	0	100.0%	47	1	97.9%	3	0	100.0%	47	0	100.0%
464	Cncld	4	1	75.0%	88	4	95.5%	3	0	100.0%	86	29	66.3%
467		3	0	100.0%	47	4	91.5%	3	0	100.0%	47	3	93.6%
488		6	2	66.7%	90	9	90.0%	6	2	66.7%	88	15	83.0%
499		6	1	83.3%	88	15	83.0%	6	1	83.3%	88	10	88.6%
500		19	1	94.7%	281	22	92.2%	18	4	77.8%	279	82	70.6%
502		19	0	100.0%	279	13	95.3%	18	1	94.4%	277	79	71.5%
503		19	1	94.7%	292	30	89.7%	19	7	63.2%	281	88	68.7%
504		19	0	100.0%	280	9	96.8%	18	4	77.8%	279	111	60.2%
505		19	2	89.5%	284	33	88.4%	18	5	72.2%	281	102	63.7%
506	38	19	3	84.2%	284	27	90.5%	18	5	72.2%	282	71	74.8%
507	134	19	3	84.2%	283	33	88.3%	19	8	57.9%	282	88	68.8%
508	86	19	0	100.0%	287	13	95.5%	19	6	68.4%	285	84	70.5%
509	22	19	3	84.2%	282	31	89.0%	18	6	66.7%	281	100	64.4%
511		19	1	94.7%	283	23	91.9%	19	4	78.9%	280	76	72.9%
516	27	19	2	89.5%	283	26	90.8%	19	10	47.4%	281	128	54.4%
517		19	0	100.0%	284	5	98.2%	19	7	63.2%	283	170	39.9%
518		19	3	84.2%	284	32	88.7%	19	9	52.6%	282	170	39.7%
519	65	19	0	100.0%	281	11	96.1%	19	4	78.9%	280	59	78.9%
562		19	1	94.7%	288	32	88.9%	19	1	94.7%	279	31	88.9%
564		19	3	84.2%	286	20	93.0%	19	2	89.5%	283	26	90.8%
566		19	0	100.0%	111	10	91.0%	19	0	100.0%	111	11	90.1%
572	19	19	2	89.5%	241	21	91.3%	19	6	68.4%	237	44	81.4%
573		19	0	100.0%	280	37	86.8%	19	1	94.7%	274	44	83.9%
577		19	0	100.0%	34	0	100.0%	19	2	89.5%	34	2	94.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/19/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
580		19	0	100.0%	288	21	92.7%	19	1	94.7%	287	53	81.5%
581		19	2	89.5%	288	35	87.8%	19	4	78.9%	284	55	80.6%
582		19	0	100.0%	34	0	100.0%	19	2	89.5%	34	3	91.2%
586		19	1	94.7%	239	30	87.4%	19	3	84.2%	232	41	82.3%
587	23	19	3	84.2%	239	28	88.3%	18	5	72.2%	232	51	78.0%
591		19	0	100.0%	288	32	88.9%	19	2	89.5%	284	40	85.9%
593		19	4	78.9%	34	6	82.4%	19	4	78.9%	34	7	79.4%
595		19	3	84.2%	280	61	78.2%	19	2	89.5%	278	50	82.0%
611		4	1	75.0%	48	3	93.8%	4	0	100.0%	48	11	77.1%
624		3	0	100.0%	42	0	100.0%	3	1	66.7%	42	10	76.2%
660		6	0	100.0%	90	2	97.8%	6	0	100.0%	89	21	76.4%
661		6	1	83.3%	90	9	90.0%	6	1	83.3%	90	18	80.0%
662		4	0	100.0%	48	1	97.9%	4	0	100.0%	48	3	93.8%
663		6	0	100.0%	90	16	82.2%	6	0	100.0%	89	15	83.1%
664		6	0	100.0%	90	4	95.6%	6	0	100.0%	89	16	82.0%
665		6	0	100.0%	90	2	97.8%	6	0	100.0%	89	14	84.3%
666		6	0	100.0%	90	3	96.7%	6	0	100.0%	89	11	87.6%
667		6	0	100.0%	90	6	93.3%	6	0	100.0%	90	16	82.2%
669		6	0	100.0%	90	5	94.4%	6	0	100.0%	90	23	74.4%
670		6	0	100.0%	90	7	92.2%	6	0	100.0%	90	25	72.2%
671		6	1	83.3%	90	4	95.6%	6	0	100.0%	90	9	90.0%
672		6	0	100.0%	90	2	97.8%	6	0	100.0%	90	18	80.0%
674		3	0	100.0%	43	2	95.3%	3	0	100.0%	43	7	83.7%
690		5	0	100.0%	86	0	100.0%	4	1	75.0%	84	12	85.7%
691		5	2	60.0%	85	8	90.6%	5	4	20.0%	85	28	67.1%
692		5	0	100.0%	88	2	97.7%	5	1	80.0%	88	37	58.0%
693	12	5	1	80.0%	74	2	97.3%	5	4	20.0%	74	26	64.9%
694		5	1	80.0%	72	1	98.6%	5	3	40.0%	71	24	66.2%
695		5	0	100.0%	72	4	94.4%	5	1	80.0%	72	19	73.6%
696	15	5	2	60.0%	86	19	77.9%	5	4	20.0%	85	37	56.5%
697		5	3	40.0%	88	21	76.1%	5	3	40.0%	87	26	70.1%
698		5	0	100.0%	86	4	95.3%	5	1	80.0%	86	24	72.1%
702		19	2	89.5%	292	19	93.5%	19	12	36.8%	291	97	66.7%
703		19	2	89.5%	292	29	90.1%	19	8	57.9%	292	73	75.0%
710	66	19	6	68.4%	292	48	83.6%	18	12	33.3%	285	82	71.2%
711	19	19	0	100.0%	291	10	96.6%	19	8	57.9%	282	34	87.9%
712		19	3	84.2%	292	46	84.2%	18	11	38.9%	289	89	69.2%
713	25	18	0	100.0%	290	9	96.9%	16	12	25.0%	273	62	77.3%
714	157	19	4	78.9%	291	39	86.6%	19	10	47.4%	286	72	74.8%
715		19	3	84.2%	291	42	85.6%	18	13	27.8%	280	90	67.9%
716	27	19	5	73.7%	291	33	88.7%	18	6	66.7%	290	62	78.6%
717	49	18	3	83.3%	286	33	88.5%	16	6	62.5%	270	68	74.8%

Amtrak On Time Performance													
Trains Arriving Through: 7/19/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
718		19	6	68.4%	292	43	85.3%	18	3	83.3%	290	52	82.1%
719	23	19	5	73.7%	292	28	90.4%	19	10	47.4%	284	67	76.4%
720	32	6	2	66.7%	89	5	94.4%	6	1	83.3%	89	7	92.1%
723		6	0	100.0%	89	3	96.6%	6	0	100.0%	88	8	90.9%
724		6	0	100.0%	89	1	98.9%	6	0	100.0%	89	15	83.1%
727		6	1	83.3%	89	4	95.5%	6	0	100.0%	89	21	76.4%
728		6	0	100.0%	89	3	96.6%	6	0	100.0%	89	9	89.9%
729	26	6	0	100.0%	89	7	92.1%	6	2	66.7%	89	24	73.0%
732		6	0	100.0%	89	5	94.4%	5	0	100.0%	87	10	88.5%
733		6	0	100.0%	89	6	93.3%	5	1	80.0%	85	10	88.2%
734		6	1	83.3%	89	3	96.6%	5	1	80.0%	87	4	95.4%
736		6	0	100.0%	89	7	92.1%	6	1	83.3%	89	22	75.3%
737		6	0	100.0%	89	3	96.6%	6	0	100.0%	89	9	89.9%
738		6	1	83.3%	89	6	93.3%	5	0	100.0%	86	5	94.2%
741		6	0	100.0%	89	2	97.8%	5	0	100.0%	87	12	86.2%
742		6	0	100.0%	89	5	94.4%	6	1	83.3%	88	16	81.8%
743		6	0	100.0%	89	6	93.3%	5	0	100.0%	88	15	83.0%
744		6	1	83.3%	89	4	95.5%	5	0	100.0%	88	8	90.9%
745	18	6	0	100.0%	89	1	98.9%	5	1	80.0%	87	4	95.4%
746		6	1	83.3%	88	3	96.6%	5	0	100.0%	87	5	94.3%
747		6	2	66.7%	89	2	97.8%	5	0	100.0%	88	10	88.6%
748		6	1	83.3%	89	5	94.4%	5	0	100.0%	87	10	88.5%
749		6	2	66.7%	89	7	92.1%	5	0	100.0%	83	3	96.4%
751	13	6	4	33.3%	88	7	92.0%	5	1	80.0%	86	7	91.9%
761		19	0	100.0%	288	17	94.1%	19	2	89.5%	288	35	87.8%
765		19	0	100.0%	288	12	95.8%	19	1	94.7%	279	40	85.7%
769		19	0	100.0%	286	11	96.2%	19	1	94.7%	282	51	81.9%
770		19	0	100.0%	288	17	94.1%	19	5	73.7%	285	39	86.3%
774		19	0	100.0%	288	8	97.2%	19	3	84.2%	284	65	77.1%
779		19	0	100.0%	34	1	97.1%	19	3	84.2%	34	7	79.4%
784		19	1	94.7%	288	33	88.5%	19	10	47.4%	285	115	59.6%
785		19	2	89.5%	288	15	94.8%	19	1	94.7%	286	44	84.6%
790		19	1	94.7%	288	15	94.8%	19	1	94.7%	285	42	85.3%
794		19	0	100.0%	288	22	92.4%	19	1	94.7%	287	58	79.8%
821	34	16	0	100.0%	287	6	97.9%	16	14	12.5%	287	148	48.4%
822	35	18	2	88.9%	289	13	95.5%	18	18	0.0%	289	149	48.4%
1333	26	19	2	89.5%	285	52	81.8%	19	17	10.5%	284	183	35.6%
1340	26	19	2	89.5%	284	14	95.1%	19	15	21.1%	282	98	65.2%
1689		12	0	100.0%	72	0	100.0%	12	2	83.3%	71	15	78.9%
2174	25	3	0	100.0%	42	5	88.1%	3	3	0.0%	42	24	42.9%
2203		4	0	100.0%	47	1	97.9%	3	0	100.0%	45	6	86.7%
2205		6	0	100.0%	88	2	97.7%	6	1	83.3%	87	10	88.5%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2216		4	0	100.0%	46	4	91.3%	4	0	100.0%	46	3	93.5%
2218	Cncld	4	2	50.0%	47	4	91.5%	3	1	66.7%	46	7	84.8%
2248		6	0	100.0%	89	3	96.6%	6	0	100.0%	88	12	86.4%
2249	12	4	0	100.0%	47	4	91.5%	4	1	75.0%	47	8	83.0%
2250		6	0	100.0%	88	7	92.0%	6	1	83.3%	87	20	77.0%
2251		4	0	100.0%	48	2	95.8%	4	0	100.0%	44	0	100.0%
2252	82	6	2	66.7%	88	12	86.4%	6	1	83.3%	86	21	75.6%
2253		6	0	100.0%	90	8	91.1%	6	4	33.3%	88	42	52.3%
2254		6	1	83.3%	89	10	88.8%	6	0	100.0%	88	15	83.0%
2255		6	0	100.0%	86	4	95.3%	6	1	83.3%	85	22	74.1%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/19/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2174	BOS	25	PTI	19	PTI	15	NHV-NHV	AM	Follow, 136, Milepost w/Letters, NHV, NHV, Held in New Haven for AM136 to clear Mill River NHV	
2218	XHM	Trn Cancelled								
2249	WAS	12			DSR	10	NHV-STM	MN	Per bulletin Milepost, 71.1, 33.6, 30, 1	
2252	BOS	82			ITI	37	WAS-WAS	AM	Service, turn, or wye train, 2203, SHORT TURN OFF 2203 ARRIVE WAS AT 10:53 AM	
82	BOS	64	PTI	27	CCR	24	PHL-PHL	AM	Heat / AC, 82994, HOT CAR, CHECKED BY MECHANICAL.	
87	NFK	59	PTI	35	PTI	24	ASD-RVR	CS	Wait for station track 97 having PTC issues at station, AMT 97, Control Point, Greendale	
88	BOS	24	PTI	26	CTI	12	BAL-BAL	AM	Follow, ., ., Control Point, ., held for mk480 to shift onto 3trk at baltimore a/c no available track for Marc equipment.	
99	NPN	60	WTR	36	WTR	27	RVM-WBG	CS	Flash flood warning Milepost, 84.7, 53.9	
146	SPG	16	MBO	28	MBO	28	BAL-XPV	AM	For maritime traffic, Milepost, 71.6, ., Bush River Bridge opening	
147	RNK	78	ENG	92	ENG	41	ALX-ALX	CS	Horn failure. Took time to wait for Operations to decide how to proceed. 44	
153	NFK	66	INJ	44	INJ	44	FBG-ASD	CS	Injured or sick passenger Passenger was having a seizure at Crossing by CFP 51.3 waited for ems to take him off n send him to local hospital	
156	NYP	31	SMW	17	DBS	16	NRK-NRK	AM	Animal strike, Milepost, 46.7, ., secured hoses with a zip tie after deer strike at MP 46.7	
161	WAS	16	SMW	14	SMW	6	XSH-NYP	AM	Scheduled in track usage program, Other, XPB-XPB, HELD FOR AM164 ON NO.2 TRK A/C NO.1 TRK OOS PELHAM BAY TO LEGGETT	
162	BOS	17	CTI	14	CTI	9	STM-BRP	MN	Follow MN, Milepost, 33, 55	
178	BOS	30	INJ	21	INJ	21	NLC-NLC	AM	Injured or sick passenger, 178 stopped on track No. 2 at New London Station requesting EMS for an unconscious 57 year old female passenger. NLC	
179	PHL	45	SVS	40	SVS	40	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Engine Swap	
195	RVM	23	FTI	14	FTI	7	ASD-RVR	CS	Meet 418, Control Point, elmont	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
464	SPG	Tmn Cancelled							
80	NYP	37	SVS	74	SVS	74	RVR-RVR	CS	Water, commissary, toilet/trash dumping
693	BRK	12	HLD	9	PTI	8	EXR-DHM	CS	Meet 694, Control Point, Rockingham
696	BON	15	HLD	6	PTI	4	ORB-SAO	CS	Meet 693, Control Point, surf
63	TWO	29	HLD	18	DMW	14	CRT-POU	MN	Waiting for MW clearance Milepost, 56.1, 56.4
68	NYP	51	WTR	45	WTR	45	SLQ-RSP	CN	Heat order Other, RSP SD
233	ALB	26	DSR	14	CTI	10	CRT-POU	MN	Follow Followed 8819 through working limits also, mnrr, 8819, Milepost, 46, 72
241	ALB	16	DSR	15	DSR	11	HUD-ALB	AM	Per bulletin Milepost, 128, 131, 30, 1, Milepost, 131, 135, 30, 1
244	NYP	22	CTI	35	CTI	31	POU-CRT	MN	Follow Following MNRR local 856 at CP 72. Stopped at CP 58 for unknown reason. Waited for 1 MNRR northbound with MNRR eng. 223 to go by., MNRR, 856, Control Point, 72
283	NFL	63	WTR	53	WTR	53	BFX-NFL	CS	Sinkhole reported Sinkhole reported, crew walked area to inspect, Control Point, 7
284	NYP	18	DMW	24	DMW	24	POU-CRT	MN	Waiting for MW clearance Control Point, 58
290	NYP	26	DSR	36	DSR	29	BTN-VRN	VR	Per bulletin Milepost, 113.30, 111.0, 10, main, Milepost, 111.0, 105.68, 25, main, Milepost, 105.68, 105.19, 15, main, Milepost, 105.19, 102.36, 50, main, Other, mile 102.36, 25, main, Milepost, 102.36, 100.63, 50, main
291	BTN	51	DSR	33	ITI	17	NYP-NYP	AM	Service, turn, or wye train, 240
76	RGH	42	WTR	25	WTR	25	GRO-DNC	NS	Flash flood warning Milepost w/Letters, 6.0NC, 34.7NC
77	CLT	11	DCS	16	DCS	16	GRO-HPT	NS	Signal dropped as we went underneath. PTC enforced. Other, 285.6
78	RGH	19	WTR	21	WTR	12	GRO-BNC	NS	Flash flood warning Milepost w/Letters, 6.0 NC, 21.5 NC
89	SAV	40	FTI	56	FTI	32	YEM-SAV	CS	Cross over or go around Held at Hardeeville ...CSX 195 ahead on TRK 1, 195, Control Point, A 473.9
98	NYP	143	SYS	81	SYS	71	MIA-MIA	FL	PTC problem or failure (cause unknown) Unable to operate with PTC on engine 324, engines were flat switched at the station .
54	SAB	66	DSR	53	DSR	32	ESX-SAB	NE	Per bulletin Milepost, 117, 123, 10, main

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
40	CHI	75	FTI	72	DCS	47	DNK-CLB	CS	Restrictive signal(s) from unknown cause Restricted speed for 6.8 miles, Stop/NE Nassau, Control Point, NE Nassau, Control Point, Richland Holdout
41	MIA	125	DCS	122	DCS	103	DLD-WPK	FR	PTC- Unplanned PTC system /server outage Milepost w/Letters, 763.0, 785.4
6	CHI	265	CAR	163	CAR	127	PCT-NPV	BN	Set out defective car 32047
720	SAC	32	SVS	43	SVS	43	OKJ-OKJ	UP	Routine inspections Delayed in yard due to mechanical services that needed to be performed, Other, Oakland yard
729	SJC	26	SYS	16	SYS	16	HAY-FMT	UP	PTC problem or failure (cause unknown) PTC map suddenly went blank had to reset PTC breaker, Milepost, 21, 23
745	OKJ	18	ENG	28	ENG	28	SAC-DAV	UP	Failure of diesel engine C2123
751	OKJ	13	ENG	17	ENG	17	SUI-SUI	UP	Air / Brake 9:40 - Lost dynamic air coming into SUI station. Heavy electric smell in engine cab. Call into CNOC. They gave permission to proceed using air only. OPS and N. Wrought notified., C2003
506	SEA	38	PTI	35	PTI	27	PDX-VAN	BN	Meet amt507, Control Point, cp05
507	EUG	134	FTI	104	FTI	90	PDX-PDX	UP	Hold due to freight derailment Reporting Marks Unknown, Control Point, Albina Yard
508	SEA	86	FTI	100	FTI	75	ORC-ORC	UP	Hold due to freight derailment UP 622 blocking Steel Bridge due to freight derailment in Albina. Wait for 622 to shove back in the clear., Other, Oregon City, UP 622, Local/yard
509	PDX	22	FTI	12	RTE	10	VAN-PDX	BN	Routed in to wrong track, waited for signal to time out for re routing Control Point, cp 0.5
516	VAC	27	SYS	30	SYS	19	SEA-SEA	BN	Conductor working alone/crew shortage. Multiple ada while working conductor only 1 baggage person loading 200 bags
519	SEA	65	FTI	74	FTI	45	XVB-X1J	BN	CN yarding a train CN, Other, Glen yard
14	SEA	No OS Rpt	FTI	333	FTI	167	XH3-PDX	UP	Meet UP, Control Point, Steelbridge
27	PDX	89	FTI	120	FTI	31	WIH-BNG	BN	Meet bnsf 3728, Milepost, 104.8, 104.8
28	SPK	37	POL	26	POL	21	VAN-BNG	BN	Fire department hold Fire at MP 78.0; await clearance to BNG depot

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
821	FTW	34	DSR	30	DSR	18	GLE-FTW	BN	Per bulletin Milepost, 410.8, 410.4, 25, m, Milepost, 404.6, 404.4, 50, m, Milepost, 403.6, 403.4, 50, m, Milepost, 402.5, 402.3, 50, m, Milepost, 401.2, 401.0, 50, m, Milepost, 389.7, 389.5, 40, m, Milepost, 385.8, 385.6, 50, m, Milepost, 381.2, 381.0, 50, m, Milepost, 379.8, 379.6, 50, m, Milepost
822	OKC	35	DSR	59	DSR	23	GLE-ADM	BN	Per bulletin Milepost w/Letters, 413.6X, 450, 40, M
341	MKE	11	DCS	9	DCS	9	GLN-XRO	ME	Issue with automatic road crossing protection Milepost, 20.34, 20.34
350	PNT	29	PTI	30	PTI	23	XB0-XA5	MI	Meet 353, Siding, albion
364	PTH	18	FTI	35	FTI	14	FLN-LPE	CC	Blocked from station track Kersley was blocked by CN 2942 who went dead. Had to make a reverse move to CP Flint from Main 2 to the MAIN., CN 2942, Milepost, 270, 270
370	GRR	69	CAR	46	CAR	46	CHI-CHI	AM	Door ID4111
572	SAN	19	CTI	22	CTI	12	IRV-SNC	SC	Follow Metrolink, 1662, Control Point, Bake, Control Point, Trabuco
587	LAX	23	PTI	19	PTI	15	OSD-X98	SN	Meet 784, Control Point, Songs
710	BFD	66	ITI	61	ITI	61	OKJ-OKJ	UP	Service, turn, or wye train 719
711	OKJ	19	PTI	23	PTI	19	ACA-XPR	UP	Meet AMTK 710, Siding, Pittsburgh
713	OKJ	25	RTE	17	RTE	15	TRK-MOD	BN	Routed behind bnsf 7384 west mt2 east empire; returned west to mt after amtk 712, then east on mt1 to pass bnsf 7384 Control Point, east empire
714	BFD	157	TRS	160	TRS	87	FNO-FNO	BN	Trespasser strike Milepost, 999.5, 999.5
716	BFD	27	FTI	26	FTI	15	SKN-MOD	BN	Meet 6547, Siding, riverbank
717	OKJ	49	FTI	33	FTI	29	FNO-MDR	BN	Meet bnsf 7082, Control Point, sunmaid
719	OKJ	23	PTI	36	PTI	36	HNF-FNO	BN	Meet Waiting for 716 to recrew 714 in FNO after 714's trespasser incident, amt 716/714, Control Point, sunmaid
4	CHI	231	FTI	130	FTI	66	FMD-GBB	BN	Follow Follow from CP LOMAX to CP 1850, BNSF 7238, Control Point, LOMAX
21	SAS	89	FTI	190	WTR	63	ACD-PBF	UP	Flash flood warning Milepost, 101.00, 119.00
22	CHI	762	ENG	404	ENG	248	LVW-LVW	UP	Pick up rescue locomotive due to mechanical failure 56
300	CHI	20	FTI	21	FTI	10	CRV-SPI	UP	Meet UP 2576, Control Point, Hazel Dell

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/19/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
305	STL	116	FTI	60	ENG	31	CHI-CHI	AM	No XITCS waited for mechanical to ride to 16th street to try and get XITCS to operate ID4602	
381	QCY	38	WTR	37	WTR	30	MAC-QCY	BN	Flash flood warning FF warning @ mp 221. Critical areas @ 20 mph., Other, mp 221	
318	CHI	40	PTI	39	PTI	26	STL-XQT	TR	Meet amt319, Bridge, McArthur	
319	KCY	49	FTI	56	FTI	24	XTF-SMT	CC	Cross Traffic unknown, Control Point, corwith	
1333	MSP	26	DSR	18	FTI	15	XH8-MSP	CP	Meet Stopped at Newport for Freight train, Control Point, Newport, S TAC LPC	
1340	CHI	26	CTI	14	CTI	14	GLN-XWA	ME	Follow Metra, 2618, Control Point, XWA	

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/19/2025

Terminal	Train	Date	Late	Delay	Cause
MIA	40	07/19	5	5	Water, commissary, toilet/trash dumping Late release from yard due to commissary loading diner/cafe, Other, MIA
MIA	98	07/19	29	29	HEP 82757, 61012, 62507, Mechanical walked train looking for HEP cable problem, short looped fireman side between 61012 and 82757. Found another cable problem fireman side between 62507 and 61012 which they tighten HEP end with zip ties
WAS	2218	07/19	(Trn Cxld)		Engine Failure
WAS	2252	07/19	36	37	Service, turn, or wye train, 2203, SHORT TURN OFF 2203 ARRIVE WAS AT 10:53 AM
BOS	167	07/19	13	13	Planned set out / pick out of locomotives, cars or section of train, Mechanical working on equipment
NHV	450	07/19	8	8	Service, turn, or wye train, 405
NHV	464	07/19	(Trn Cxld)		Engine Failure
NYP	49	07/19	39	39	Unrecoverable penalty (PCS), 98/703
NYP	63	07/19	8	8	Passenger and/or baggage, STILL BOARDING AT DEPARTURE TIME
NYP	245	07/19	23	23	Cross over or go around, AM68, Other, NYP-NYP, HELD TO WAIT FOR AM68 COME INTO THE STATION.
NYP	291	07/19	15	17	Service, turn, or wye train, 240
CDL	390	07/19	10	10	Plow issues ID4603
CHI	305	07/19	41	31	No XITCS waited for mechanical to ride to 16th street to try and get XITCS to operate ID4602
CHI	305	07/19	41	10	Waited for recrew of engineer
CHI	307	07/19	89	89	Set out defective locomotive switch out the 4630 for the 4623, ID4623
CHI	370	07/19	53	7	Fuel
CHI	370	07/19	53	46	Door ID4111
SEA	516	07/19	19	19	Conductor working alone/crew shortage. Multiple ada while working conductor only 1 baggage person loading 200 bags
EMY	6	07/19	91	91	Heat / AC 34004, 32051
LAX	4	07/19	25	25	Radio failure 203 issues, 29, 203
OKJ	710	07/19	61	61	Service, turn, or wye train 719
OKJ	712	07/19	18	10	Routine inspections Other, oak yard
OKJ	712	07/19	18	8	Meet 11, Control Point, magnolia
OKJ	718	07/19	4	4	Door C6965
OKJ	720	07/19	43	43	Routine inspections Delayed in yard due to mechanical services that needed to be performed, Other, Oakland yard

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	92.9	95.2	167	0
CDOT	95.0	93.8	95.4	96.4	16	1
MARC	95.0	38.9	77.1	83.5	18	11
SEPTA	95.0	83.8	96.1	96.2	111	18
NJT-NED	95.0	95.9	91.8	95.2	196	8
NJT-SED	95.0	100	98.2	91.2	24	0

Operating Highlights

Train 1689(19) North of Saco, ME - Police Related

20JUL25: Train 1689(19) was delayed 3 miles north of Saco, ME at MP23.8 on the CSX Portland Subdivision due to a police hold for reported trespassers fouling the tracks ahead. Once hold was lifted, Train 1689(19) was able to proceed.

Train	Delay	Comment
1689(19)	39"	

Train 283(19) West of Buffalo, NY - Weather

19JUL25: Train 283(19) was delayed 4 miles west of Buffalo, NY Exchange Station at MP6.8 on the CSX Niagara Subdivision due to a reported sinkhole ahead. Crew walked the are to inspect, found no exceptions and proceeded west.

Train	Delay	Comment
283(19)	53"	

Train 147(19) Alexandria, VA - Horn Failure

19JUL25: Train 147(19) E/44, 8 cars, was delayed at Alexandria, VA/ MP105.1 on the CSX RF&P Subdivision due to horn failure on engine E/44. Crew worked with CNOC mechanical to troubleshoot issue. Unable to resolve, and no available mechanical technician to send from Washington, the train continued to Manassas, VA to be met there by mechanical. The train lost additional time account of needing to protect each crossing enroute to Manassas. Mechanical met the train and was able to temporarily fix the issue allowing Train 147(19) to proceed.

Train	Delay	Comment
147(19)	38"	ALX
147(19)	41"	MSS
147(19)	13"	WAS - MSS

Train 2218(19) Washington, DC - Engine Failure

19JUL25: Train 2218(19), TS#17, was originally delayed at Washington, DC due to a short turn of Train 2251(19)'s equipment that arrived at 3:00PM. While in the station, mechanical started troubleshooting issues found with rear PC/2011. It was found that the emergency push button on PC/2011 was pushed in. This issue was thought be resolved but then the trainset experienced more issues reporting traction and brake issues. As a result, Train 2218(19) was cancelled in its entirety with all passengers moved to Train 142(19) to continue to their final destination.

Train	Delay	Comment
2218(19)	Cancelled	

Train 156(19) Newark, DE - Deer Strike

19JUL25: Train 156(19) E/650, 8 cars, struck a deer operating north on No. 2 track between Bacon - Davis. Crew proceeded to Newark, DE station to inspect train and secured a loose hose. Once secured, Train 156(19) continued north at track speed.

Train	Delay	Comment
156(19)	16"	

Train 49(19) New York, NY - Engine Failure

19JUL25: Train 49(19), E/98-E/703, was delayed at New York, NY due to mechanical onboard troubleshooting head end power issues. Once resolved, Train 49(19) departed the station operating 41 minutes late.

Train	Delay	Comment
49(19)	41"	

Train 80(19) Richmond, VA - Pump Cars

19JUL25: Train 80(19) was delayed at Richmond, VA/MP4.6, on the CSX Richmond Terminal Subdivision, due to C/25054, C/81523, and C/25071 reported full and needing to be pumped. Train 153(19) held just north of the station for Train 80(19) to clear the station track.

Train	Delay	Comment
80(19)	1'12"	
153(19)	20"	

Train 68(19) South of St-Lambert, QC - Heat Orders

19JUL25: Train 68(19) was delayed starting 2.2 miles south of St-Lambert, QC/MP70.3, on the CNRR Rouses Point Subdivision, due to 25MPH heat orders between Southwark/MP42.7 and Rouses Point/MP0.0.

Train	Delay	Comment
68(19)	45"	

Train 153(19) South of Fredericksburg, VA - Passenger Medical

19JUL25: Train 153(19) stopped 8 miles south of Fredericksburg, VA/MP59.3, on the CSX RF&P Subdivision, at MP51.3 waiting on emergency services to respond for a passenger experiencing a seizure. The passenger was removed from the train by paramedics and brought to the local area hospital for observation.

Train	Delay	Comment
153(19)	44"	

Train 464(19) New Haven, CT - Engine Failure

19JUL25: Train 464(19) was cancelled in its entirety at New Haven, CT account E/93 bad ordered for wheels with no available replacement. Two alternate buses were secured. Bus #1 operated express making stations stops at New Haven, Hartford, and Springfield. Bus #2 made all station stops.

Due to this, the following trains were also adjusted/cancelled:

Train 400(20) canceled, no passengers affected. Train 497(20) canceled with alternate bus transportation. Train 461(20) canceled between Greenfield, MA and Springfield, MA with alternate bus transportation, train originated at SPG operating Springfield, MA to New Haven, CT.

WBS#: B.TR.100151.0760

Train	Delay	Comment
464(19)	Cancelled W/ALT	
497(20)	Cancelled w/ALT	
461(20)	Originates SPG w/ALT	
400(20)	Cancelled	

CFRC PTC / Server Outage - South of Deland, FL

19JUL25: CFRC reported their PTC and 48 Wayside Interface Units (WIU) were down due to an unplanned outage. This outage started 11.8 miles south of Deland, FL/MP750.1, on the CFRC Orlando Subdivision, between Lake Monroe/MP763.1 and MP788.9. During this time, Trains 41(17) and 97(18) were heavily delayed operating through the area. They proceeded at restricted speeds to each control point and then gain verbal permission to proceed to the next.

Train 98(19) was delayed through the area as well but the systems started to come back allowing them to resume track speed at MP777.0.

Train	Delay	Comment
41(17)	1'48"	
97(18)	1'16"	
98(19)	43"	
40(19)	13"	

CSX Heat orders

19JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Charleston, Jacksonville Terminal, Nahunta, Sanford, Savannah and South End.

Train	Delay	Comment
79(19)	05"	
52(19)	16"	
89(19)	24"	
90(19)	07"	
98(19)	27"	

Maintenance of Way Highlights

Train 2252(19) Washington, DC - Short Turn

19JUL25: Due to Washington's 55-hour power outage, High Speed Rail had to short turn Train 2203(19) in Washington, DC that arrived on time at 10:57AM for Train 2252(19).

Train	Delay	Comment
2252(19)	36"	

Train 57(19) South of St. Albans, VT - M of W Work

19JUL25: Train 57(19) was delayed starting 4.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, due to a 10MPH speed restriction from MP128-MP119 due to Maintenance of Way working in the area

Train	Delay	Comment
57(19)	41"	

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 153(19) Passenger Removal at Fredericksburg, Virginia –Medical

19JUL25, Passenger on PNR 28C35E, traveling from Wilmington, DE to Norfolk, VA was removed from the train by EMS. The passenger was having a seizure onboard. Amtrak Police notified.

Delay: **153 (19)** **None**

Train 186(18) Passenger Removal at Ashland, Virginia –Medical

19JUL25, Passenger on PNR 3BA7CE, traveling from Williamsburg, VA to Richmond (Staples Mills Rd), VA was removed from the train by local police. The passenger didn't have the proper ticket for his travel and couldn't obtain one. The passenger then became unruly with the conductor when he couldn't get the ticket and was told he would have to get off the train. Amtrak Police notified.

Delay: **186 (18)** **None**

Train 99(19) Passenger Removal at Alexandria, Virginia –Other

19JUL25, Passenger on PNR 3DECA3, traveling from Newark, NJ to Richmond, VA was removed from the train by conductor. The passenger didn't have the proper carrier for pet. Amtrak Police notified.

Delay: **99 (19)** **None**

Passenger Incident at Washington, DC – Service Dog

Train 97(19) 19JUL25, PNR 3CC467, Passenger traveling from Washington, DC to Florence, SC, Conductor checking in tickets advised passenger their dog would not be allowed on the seat unless had proper documentation. Passenger stated he didn't need to provide any paperwork, later the passenger verbally expressed this was rude to the Train Attendant and at Alexandria, VA station stop requested to speak to supervisor and would be contacting his lawyer. Other passengers witness this encounter (PNR 15C19B). Amtrak Police notified.

Delay: **97(19)** **NONE**

Passenger Incident Injury at Washington, DC – Injury

Train 98(18) 19JUL25, PNR 261C17, Passenger traveling from Deland, FL to Philadelphia, PA. While stepping down the stair's passenger cut their arm on a metal object, basic first aid applied, Passenger refused medical attention. Amtrak Police notified.

Delay: **98(18)** **NONE**

Western Region

Operating Highlights

Train 22(19) Malvern, AR - Freight Train Interference

20JUL25: Train 22(19) was delayed 4 miles east of Malvern, AR, on UP Little Rock subdivision, due to following UP9815 from MP384 to MP345.

Train	Delay	Comment
22 (19)	31"	

Train 48/448(19) Toledo, OH - Signal

20JUL25: Train 48/448(19) was delayed departing Toledo, OH, on NS Cleveland-Toledo subdivision, due to PTC initialization issues. After trouble shooting with NS PTC desk, train 48/448(19) was instructed to cut out PTC.

Train	Delay	Comment
48/448 (19)	31"	

Train 370(19) Chicago, IL - Initial Terminal Delay

20JUL25: Train 370(19) was delayed 53 minutes departing Chicago, Illinois due to a disabled fuel truck and a venture car step issue. At 533pm, a Communicator Page was sent out stating that the fuel truck was disabled. This necessitated taking the entire train set to the 16th Street Diesel Shop to fuel the locomotive. Train 370(19) was released at 515pm, and the equipment spotted at the 16th Street Diesel Shop for fueling at 547pm. Fueling was completed at 602pm. Train 370(19) shoved to the station at 604pm and set in the station at 620pm with 132 passengers to board. Train was ready to depart at 637pm. However, the stairs would not retract on Venture car ID4111 requiring mechanical assistance. After retracting the stairs on Venture car ID4111, Train 370(19) departed Chicago at 723pm; 53 minutes late.

Train	Delay	Comment
370 (19)	53"	

Train 307(19) Chicago, IL - Initial Terminal Delay

20JUL25: 19JUL25, Train 307(19) was delayed 1 hour and 29 minutes departing Chicago, Illinois account replacing a bad order locomotive. Charger locomotive ID4630 was bad ordered at 558pm account it would not pass an X-ITCS test. Replacement locomotive ID4623 was released at 602pm but could not be picked up until Train 370(19)'s equipment was done being fueled on D7. Note: Due to a disabled fuel truck in the yard, the entire Train 370(19) was brought to the locomotive shop for fueling. Blue flags were dropped on Train 307(19) at 644pm and replacement locomotive ID4623 tied on at 705pm. Train 307(19) was released by mechanical at 806pm and set in the station at 815pm with 230 passengers to board. Train 307(19) departed Chicago at 839pm; 1 hour and 29 minutes late. An additional 13-minute delay was incurred wyeing the train on departure.

Train	Delay	Comment
307 (19)	1'42"	

Train 14(18) Oregon City, OR - Freight Train Interference

19JUL25: Train 14(18) was delayed at Oregon City, OR (ORC) on the Union Pacific Railway Brooklyn Subdivision. Union Pacific Railway reported a freight train had derailed in Albina, OR and tracks were blocked south of Portland with trains wainig to enter the Albina yard. A Union Pacific manager responded to the scene and assisted in getting trains to clear a route so that Amtrak trains could proceed. Train 14(18) and 508(19) were held at Oregon City, OR and train 507(19) was held at Portland, OR. Once a route was available train traffic was resumed.

Train	Delay	Comment
508(19)	1'15"	
507(19)	1'30"	
14(18)	2'47"	
14(18)	45"	Daily Inspection on Locos.

Train 507(19) Portland, OR - Signal

19JUL25: Train 507(19) was delayed north of Portland, OR (PDX) at MP 6.0 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. There was a "code brown" - train dispatchers temporarily lose control of the signals and switches - issued between MP 6.0 and PDX. Train crews were required to wait for verbal authority from the train dispatcher and operate at reduced speeds in the area.

Train	Delay	Comment
507(19)	15"	"code brown" signal problems
506(19)	27"	hold for inbound train 507(19)

Train 307(19) North of Summit, IL - Freight Train Interference

20JUL25: Train 307(19) was delayed 7 miles north of Summit, IL, on Cn Joliet subdivision, due to freight cross traffic obstructing the route at control point Brighton. Once the freight cleared and a route was made available, train 307(19) was able to proceed.

Train	Delay	Comment
307(19)	1'01"	

Train 519(19) Vancouver, BC - Freight Train Interference

19JUL25: Train 519(19) was delayed departing the initial terminal of Vancouver, BC (VAC) on the Canadian National Railway (CN) New Westminster Subdivision. A CN yard crew was assembling a freight train at Vancouver yard and blocking the route for train 519(19) to depart VAC. Once the yard crew cleared the track, train 519(29) was able to proceed. Train 519(29) incurred additional delay at MP 144.8 for a second CN Freight train, CN/8796, to clear the Fraser bridge.

Train	Delay	Comment
519(19)	45"	VAC
519(19)	29"	Fraser Bridge

Train 714(19) Fresno, CA - Trespasser Incident

19JUL25: At approximately 3:53 PM-PT train 714(19) - operating with camera equipped cab car CC/8311 in the lead, five (5) additional cars and locomotive CDTX/2007 pushing - struck an injured at trespasser at MP 999.53 on the Burlington Northern Santa Fe Railway Stockton Subdivision in the City of Fresno, Fresno County, California. This incident occurred on the public highway crossing at grade for East Olive Ave (US DOT 258569A). The crossing was equipped with quad gates, flashing lights and bells which were observed to be working at the time the incident occurred. Train traffic was halted in both directions while local authorities responded to and investigated the incident. Train 714(19) was operating east at 06 MPH on the single main track with a posted track speed of 35 MPH. There were no initial reports of injuries to the 59 passengers or crew, and no reports of damage to Amtrak equipment. Once the scene was released by authorities train 714(19) advanced to Fresno, CA where division management and a relief crew met the train. Once the relief crew assumed operation train 714(19) was able to depart FNO and proceed east.

National Response Center: 1437397
California Office of Emergency Services: 25-3589
Amtrak Police Case: 10370

Google Maps Location of Incident:
<https://maps.app.goo.gl/GpdDuvNwW7p1uLuR8>
36.757407, -119.787208
2004-2024 E Olive Ave, Fresno, CA 93701

WBS#: B.TR.100150.5902

National Response Center Number: 1437397

Train	Delay	Comment
717(19)	24"	
719(19)	36"	
716(19)	13"	
714(19)	1'27"	FNO - Hold for recrew
714(19)	1'06"	Trespasser Strike

Train 58(19) North of Hazlehurst, MS - Routing

19JUL25: Train 58(19) was delayed 11 miles north of Hazlehurst, MS, on CN McComb subdivision, due to rough tracks reported ahead of them. Train 58(19) held waiting for a track inspector to respond. Once the tracks were inspected, no exceptions were found and train 58(19) was able to proceed at normal operating speed.

Train	Delay	Comment
58(19)	58"	

Train 14(18) North of Chemult, OR - Freight Train Interference

19JUL25: Train 14(18) was delayed north of Chemult, OR (CMO) at Cruzatte Siding on the Union Pacific Railway Cascade Subdivision. A disabled freight train was blocking the single main track ahead after the train stalled out while in a tunnel and lost contact with the distributed power units (DPU) on the rear of the train. Union Pacific management responded to the scene and assisted the freight crew in reversing out of the tunnel, ensuring the remote connection to the DPU units was restored, and advancing the train clear of the siding track at Cruzatte to open a route for train 14(18). Once the route was established train 14(18) was able to proceed north.

Train	Delay	Comment
14(18)	1'55"	

Train 305(19) Chicago, IL - Initial Terminal Delay

20JUL25: Train 305(19) was delayed 41 minutes departing Chicago, Illinois account waiting for a re-crew engineer (10 minutes) and the X-ITCS cab signals not being tested on the locomotive (31 minutes). An additional 18-minute delay was then incurred testing the X-ITCS cab signals on the mainline. Equipment turned off inbound 351(19) this date and the diesel pit general foreman requested locomotive ID4602 be added off inbound 380(19) for a test run. An initial 10-minute delay was incurred due to a late arriving relief engineer. Once the relief engineer took charge of the equipment it was reported that Charger ID4602 had not had its X-ITCS cab signals tested. The unit was added off inbound 380(19) which is a PTC-only route. Once diesel personnel were onboard, Train 305(19) departed Chicago at 601pm; 41 minutes late. Testing of the X-ITCS cab signals resulted in an additional 18-minute delay on the mainline.

Train	Delay	Comment
305(19)	10"	WAITING FOR RE-CREW ENGINEER
305(19)	31"	X-ITCS NOT TESTED ON LOCO
305(19)	18"	TESTING X-ITCS ON MAINLINE

Train 6(17) Encompassing Princeton, IL - Car Failure

19JUL25: Train 6(17), operating with Locomotive 68, Locomotive 15 and 9 cars, stopped at MP 125.4 on the Burlington Northern Santa Fe Mendota Subdivision, 21 miles west of the Princeton, IL station, due to sleeper Car 32047 actuated a wayside detector. The reported axle had a history of trending hotter. BNSF instructed to crew to continue 30 miles to Zearing / MP 95.4, not exceeding 30 mph, before setting the car out.

Train	Delay	Comment
6(17)	2'07"	
6(17)	1'12"	HBD

Oakland, CA - Servicing

19JUL25: Trains were delayed departing the Oakland, CA Maintenance Facility (OMF) account of a short of personnel to service the equipment.

Train 720(19) was released at 7:25 a.m. (PDT), 13 minutes after the scheduled departure time from Oakland, CA Jack London Station. Train 720(19) departed OMF at 7:43 a.m. (PDT).

Train 710(19) was released at 7:55 a.m. (PDT), 19 minutes after the scheduled departure time from Oakland, CA Jack London Station. Train 710(19) departed OMF at 8:22 a.m. (PDT).

Train 6(19) was released at 8:40 a.m. (PDT), 15 minutes after the scheduled departure time from Emeryville, CA station. Crew reported head end power issues once the equipment was released, causing additional delays for technicians to repair. Train 6(19) departed OMF at 9:28 a.m. (PDT).

WBS#: B.TR.100150.5899

Train	Delay	Comment
720(19)	43"	
710(19)	1'01"	
6(19)	1'31"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold

371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold

371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL

and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).
- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled,	with alt CHI-STL
302(15)	Cancelled,	with alt STL-CHI
307(14)	Cancelled,	with alt CHI-STL
306(16-29)	Cancelled,	no alternate
301(16-29)	Cancelled,	no alternate

Train 28(18) Bingen-White Salmon, WA - Police Related

18JUL25: Train 28(18) was delayed west of Bingen, WA (BNG) at MP 65.6 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. The local fire department had requested train traffic halted account a brush fire in the area. Train 8(18) held at MP 65.6 until cleared to advance to BNG station. At BNG train 28(18) again held until tracks were released by the fire department and was allowed to operate at reduced speeds until clear of the fire at MP 82.5.

19JUL25: Train 27(17) was delayed near Bingen, WA (BNG) account the same brush fire from July 18, 2025. Local fire officials were still working to extinguish "hot spots" that continued to flare up overnight. There was a backlog of freight traffic in the area and trains were required to operate at reduced speeds account fire personnel in the area.

Train	Delay	Comment
28(18)	45"	
27(19)	1'42"	Meet multiple freight trains and reduced operating speeds account brush fires

Train 22(18) Longview, TX - Engine Failure

18JUL25: Train 22(18) was delayed departing Longview, TX, on UP Little Rock subdivision, due to E/56 having independent brake failure which caused to independent brake on E/56 to not release. After working with CNOC mechanical as well as LAX mechanical, 22(18) was unsuccessful in resolving the issue. It was at this time that a UP freight unit was requested to rescue train 22(18). UP provided a freight unit and train 22(18) waited for a UP crew that signed up at 810pm to move the motor to the train. Once the motor was added to train 22(18) they were able to depart Longview, tx and continue. The UP freight was facing the wrong way so 22(18) operated longnose to Marshall, TX.

Train 22(18) was further delayed 8 miles east of Longview station due to PTC issues on the UP freight. The crew was able to resolve the issues with the aid of the PTC desk.

Train 22(18) was further delayed Wyeing the UP freight unit at Marshall.

19JUL25: Train 22(18) was further delayed at Arcadia, MO due to the UP freight running out of fuel and shutting down. This was due to a faulty fuel gauge that didn't display the correct fuel info. The UP freight was able to be used as a control stand while E/56, which could not lead due to independent brake failure, provided traction effort from the trailing position. Once the train arrived in Saint Louis, MO, Amtrak mechanical and Assistant Superintendent Kenner responded to address the UP freight. After refueling the UP freight was able to be restarted and train 22(18) was able to proceed.

Train	Delay	Comment
22(17)	4'08"	Waiting for UP Freight Unit LVW
22(17)	42"	PTC Issues
22(18)	52"	Trouble Shooting Frt ENG issues
22(18)	39"	Operating at reduced Speeds due to Frt ENG

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
370 (12) / 371 (13)		Business class		All JY pax downgraded to coach
305 (12) / 300 (13)		Business class		All JY pax downgraded to coach

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage
7 (8)	WTN	348		HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
22 (18)	LVW	UP6347	TM#4 cut out, make grade, Raton pass	CHI	7/20/25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 153(19) Passenger Removal at Fredericksburg, Virginia –Medical

19JUL25, Passenger on PNR 28C35E, traveling from Wilmington, DE to Norfolk, VA was removed from the train by EMS. The passenger was having a seizure onboard. Amtrak Police notified.

Delay: **153 (19)** **None**

Train 6(17) Passenger Removal at Mendota, Illinois - Conduct

19JUL24, PNR 3C6338, Passenger traveling from Galesburg, IL to Naperville, IL was removed at Mendota, IL by local Police department. At Princeton, IL passenger did not hear announcements and became disorderly with crew and passengers.

Delay: **6 (17)** **10"**

Passenger Incident at Simi Valley, California – Other

Train 790(19) 19JUL25, PNR 3C6E42, Passenger traveling from Santa Barbara, CA to Los Angeles, CA was seating in lower level accessible. Passengers were advised that they would need to vacate this seating area as a passenger boarding downline will be utilizing for their wheelchair. The party was relocated upper level with a quad seating area to be

accommodated. The party was not satisfied with being relocated. Amtrak Police notified.

Delay: **790 (19)** **NONE**

Passenger Incident of Injury on Board at Lawrence, KS - Injury

Train 4 (17), 19JUL25, PNR 1FB93A, Passenger traveling from Los Angeles, CA to Chicago, IL, on PNR1FB93A, fell while onboard moving train at Lawrence, KS. Passenger was in hallway, walking when stated to Conductor Tuck legs had given out from under them. Their appeared to no obvious injury bumps or bruises, passenger declined medical attention. Amtrak Police notified.

Delay: **4 (17)** **NONE**

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/19/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	262	19	93%	5,474	475	91%	84,243	6,500	92%
Northeast Corridor	98%	61	4	93%	1,437	187	87%	22,622	2,420	89%
Acela	98%	13	2	85%	396	64	84%	6,311	832	87%
Northeast Regional	98%	48	2	96%	1,041	123	88%	16,311	1,588	90%
State Supported	98%	173	9	95%	3,514	183	95%	52,937	2,696	95%
Long Distance	98%	28	6	79%	523	105	80%	8,546	1,378	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management Mechanical Arrival Performance by Service

Confidential - Internal Use Only

Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/19/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	262	19	93%	5,474	475	91%	84,243	6,500	92%
Northeast Corridor	98%	61	4	93%	1,437	187	87%	22,622	2,420	89%
Acela	98%	13	2	85%	396	64	84%	6,311	832	87%
Northeast Regional	98%	48	2	96%	1,041	123	88%	16,311	1,588	90%
On Spine Northeast Regional	98%	24	-	100%	538	61	89%	8,272	839	90%
Richmond / Newport News / Norfolk	98%	10	1	90%	221	50	77%	3,401	514	85%
Roanoke	98%	4	1	75%	76	7	91%	1,162	157	86%
Springfield Shuttles	98%	10	-	100%	206	5	98%	3,476	78	98%
State Supported	98%	173	9	95%	3,514	183	95%	52,937	2,696	95%
Borealis	98%	2	-	100%	38	5	87%	569	64	89%
Capitol Corridor	98%	22	2	91%	494	16	97%	6,954	151	98%
Carolinian	98%	2	-	100%	38	6	84%	584	48	92%
Cascades	98%	14	1	93%	266	13	95%	3,967	281	93%
Downeaster	98%	10	-	100%	186	1	99%	2,774	45	98%
Empire	98%	20	1	95%	380	26	93%	6,266	326	95%
Adirondack	98%	2	-	100%	38	2	95%	584	43	93%
Berkshire Flyer	98%	-	-	100%	7	1	86%	13	3	77%
Ethan Allen Express	98%	2	-	100%	38	5	87%	584	39	93%
Maple Leaf	98%	2	-	100%	38	2	95%	584	56	90%
New York - Albany	98%	10	-	100%	183	6	97%	3,334	93	97%
New York - Niagara Falls	98%	4	1	75%	76	10	87%	1,167	92	92%
Heartland Flyer	98%	2	-	100%	34	1	97%	576	17	97%
Hiawatha	98%	12	-	100%	221	7	97%	3,334	122	96%
Illinois	98%	12	3	75%	251	20	92%	4,018	276	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	76	2	97%	1,156	45	96%
Illini / Saluki	98%	4	1	75%	76	8	89%	1,156	44	96%
Lincoln Service	98%	4	2	50%	99	10	90%	1,706	187	89%
Keystone	98%	15	-	100%	437	22	95%	6,751	410	94%
Lincoln / Missouri	98%	2	-	100%	38	9	76%	578	84	85%
Michigan	98%	10	1	90%	186	15	92%	2,790	269	90%
Blue Water	98%	2	-	100%	38	4	89%	580	86	85%
Pere Marquette	98%	2	1	50%	36	2	94%	582	27	95%
Wolverine	98%	6	-	100%	112	9	92%	1,628	156	90%
Missouri	98%	2	-	100%	36	1	97%	562	15	97%
Pacific Surfliner	98%	24	-	100%	456	9	98%	6,234	231	96%
Pennsylvanian	98%	2	-	100%	38	7	82%	584	67	89%
Piedmont	98%	8	1	88%	151	1	99%	2,320	33	99%
San Joaquins	98%	12	-	100%	226	19	92%	3,492	200	94%
Vermont	98%	2	-	100%	38	5	87%	584	57	90%
Long Distance	98%	28	6	79%	523	105	80%	8,546	1,378	84%
Auto Train	98%	2	-	100%	38	3	92%	572	96	83%
California Zephyr	98%	2	1	50%	38	13	66%	581	135	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	16	7	56%	248	51	79%
City Of New Orleans	98%	2	-	100%	38	6	84%	570	52	91%
Coast Starlight	98%	2	1	50%	40	3	93%	587	88	85%
Crescent	98%	2	-	100%	38	4	89%	584	68	88%
Empire Builder	98%	4	-	100%	71	11	85%	1,122	144	87%
Floridian	98%	3	1	67%	38	13	66%	495	174	65%
Lake Shore Ltd	98%	2	1	50%	38	12	68%	982	113	88%
Palmetto	98%	2	-	100%	38	4	89%	582	38	93%
Silver Meteor	98%	2	-	100%	38	6	84%	580	114	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	38	10	74%	582	147	75%
Sunset Ltd	98%	-	-	100%	16	5	69%	246	44	82%
Texas Eagle	98%	2	1	50%	38	8	79%	654	89	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/19/25										
Day			Month to Date			Year to Date				
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	260	9	97%	5,495	142	97%	84,274	2,014	98%
Northeast Corridor	98%	61	-	100%	1,438	37	97%	22,575	635	97%
Acela	98%	12	-	100%	396	8	98%	6,313	164	97%
Northeast Regional	98%	49	-	100%	1,042	29	97%	16,262	471	97%
State Supported	98%	171	5	97%	3,515	57	98%	52,922	877	98%
Long Distance	98%	28	4	86%	542	48	91%	8,639	500	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/19/25											
Day			Month to Date						Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	260	9	97%		5,495	142	97%	84,274	2,014	98%
Central Division	98%	64	4	94%		1,254	60	95%	19,293	667	97%
Northeast Division	98%	79	1	99%		1,742	32	98%	27,758	646	98%
Southeast Division	98%	53	1	98%		1,204	32	97%	18,634	440	98%
Southwest Division	98%	64	3	95%		1,295	18	99%	18,589	261	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/19/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	260	9	97%	5,495	142	97%	84,274	2,014	98%
Central Division	98%	64	4	94%	1,254	60	95%	19,293	667	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	1	50%	43	1	98%	586	3	99%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	25	3	88%	505	43	91%	7,781	430	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	38	-	100%	562	3	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	18	-	100%	291	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	37	-	100%	566	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	111	3	97%	1,674	12	99%
MSP	98%	1	-	100%	19	1	95%	280	7	98%
PDX	98%	5	-	100%	91	1	99%	1,403	36	97%
PNT	98%	3	-	100%	56	1	98%	803	8	99%
PTH	98%	1	-	100%	19	-	100%	290	6	98%
QCY	98%	2	-	100%	36	-	100%	566	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	153	8	95%	2,280	121	95%
SPK	98%	1	-	100%	19	-	100%	300	2	99%
STL	98%	3	-	100%	67	2	97%	1,144	18	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	38	-	100%	559	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	79	1	99%	1,742	32	98%	27,758	646	98%
ALB	98%	7	-	100%	133	1	99%	2,042	26	99%
BON	98%	5	-	100%	93	-	100%	1,357	3	100%
BOS	98%	14	-	100%	336	6	98%	5,453	128	98%
BRK	98%	5	-	100%	66	-	100%	1,327	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	19	-	100%	290	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	35	-	100%	562	-	100%
HFD	98%	-	-	100%	26	-	100%	172	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	19	1	95%	290	6	98%
NFL	98%	2	-	100%	38	-	100%	584	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	4	-	100%	89	-	100%	1,496	35	98%
NYP	98%	30	1	97%	729	23	97%	11,723	408	97%
POR	98%	-	-	100%	24	-	100%	24	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	17	-	100%	288	1	100%
SPG	98%	6	-	100%	92	1	99%	1,788	20	99%
TWO	98%	1	-	100%	19	-	100%	289	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	53	1	98%	1,204	32	97%	18,634	440	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	92	1	99%	1,446	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/19/25										
Day			Month to Date			Year to Date				
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	260	9	97%	5,495	142	97%	84,274	2,014	98%
Southeast Division	98%	53	1	98%	1,204	32	97%	18,634	440	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	7	-	100%	211	2	99%	3,156	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	19	-	100%	286	11	96%
MIA	98%	2	1	50%	37	3	92%	562	31	94%
NFK	98%	3	-	100%	54	2	96%	804	5	99%
NOL	98%	3	-	100%	41	1	98%	648	21	97%
NPN	98%	2	-	100%	38	1	97%	557	4	99%
PGH	98%	1	-	100%	19	-	100%	291	3	99%
PHL	98%	3	-	100%	81	3	96%	1,247	36	97%
RGH	98%	4	-	100%	68	-	100%	1,171	5	100%
RNK	98%	2	-	100%	35	-	100%	552	8	99%
RVM	98%	1	-	100%	19	-	100%	283	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	17	1	94%	273	1	100%
SFA	98%	1	-	100%	19	-	100%	286	18	94%
WAS	98%	17	-	100%	444	18	96%	6,919	265	96%
Southwest Division	98%	64	3	95%	1,295	18	99%	18,589	261	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	19	-	100%	292	-	100%
BFD	98%	6	-	100%	112	-	100%	1,735	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	1		19	4	79%	299	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	18	-	100%	324	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	57	-	100%	853	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	1	89%	179	2	99%	2,238	64	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	16	-	100%	287	-	100%
OKJ	98%	9	1	89%	209	8	96%	3,062	69	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	11	-	100%	248	1	100%	3,479	13	100%
SAN	98%	12	-	100%	226	2	99%	2,648	24	99%
SAS	98%	1	-	100%	19	1	95%	288	3	99%
SJC	98%	7	-	100%	132	-	100%	1,872	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	38	-	100%	571	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	2	-	100%	49	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DATE 7/19/2025 12:00..	Diesel Locomotive	Superliner I	Amfleet I		Electric Locomotives		Viewliner II	High Speed Trainset		Surfliner	California Cars (Caltrans)	Grand Total
	ENG	CAR	CAR	CCR	ENG	CCR	CAR	ENG	CAR	CAR	CAR	
Wayside Hot Box ..		163										163
ITCS Problem	150											150
Car Hot: Air Condi..		91		24								115
Horn/Bell Problems	92											92
HEP Problems	39		14				29					82
Electrical Problems	53											53
Door Problems			11						4	25	4	44
Interior Fixtures/A..		34										34
Pantograph Proble..					8			15				23
Loading Problems	19											19
ACSES Failure					17							17
M/U Trainline Cabl..	17											17
Cab Signal Failure						4		9				13
Dragging/Loose E..	10											10
Window/Windshiel..	3											3
Grand Total	383	288	25	24	25	4	29	24	4	25	4	835