



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, July 21, 2025

Rules:1-50



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/20/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/20/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	271	46	83.0%	5,745	706	87.7%	84,452	8,375	90.1%
Central Division	91.5%	62	5	91.9%	1,314	146	88.9%	19,343	1,886	90.2%
Northeast Division	95.0%	89	20	77.5%	1,812	256	85.9%	27,767	3,019	89.1%
Southeast Division	94.5%	55	6	89.1%	1,259	156	87.6%	18,688	1,870	90.0%
Southwest Division	90.5%	65	15	76.9%	1,360	148	89.1%	18,654	1,600	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/20/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	92,010	32,589	65%	2,079,299	674,030	68%	27,464,692	7,392,011	73%
Northeast Corridor	80%	39,751	15,904	60%	891,515	276,745	69%	12,191,925	3,153,391	74%
Acela	82%	7,499	2,735	64%	180,343	54,962	70%	2,534,260	609,628	76%
Northeast Regional	78%	32,252	13,169	59%	711,172	221,783	69%	9,657,665	2,543,763	74%
Richmond / Newport News / Norfolk	73%	11,550	6,825	41%	227,514	98,541	57%	3,117,666	1,071,078	66%
Springfield Shuttles	89%	403	177	56%	8,770	2,126	76%	174,767	26,770	85%
Roanoke	70%	2,467	753	69%	60,324	17,539	71%	814,501	214,764	74%
On Spine Northeast Regional	83%	17,832	5,414	70%	414,564	103,577	75%	5,550,731	1,231,151	78%
State Supported	80%	39,822	11,114	72%	917,963	240,234	74%	11,729,510	2,599,967	78%
Borealis	60%	486	160	67%	12,568	8,676	31%	169,275	71,854	58%
Capitol Corridor	90%	2,387	34	99%	68,323	5,812	91%	877,518	94,516	89%
Carolinian	60%	1,097	122	89%	21,171	11,428	46%	336,981	139,852	58%
Cascades	60%	2,912	611	79%	60,539	17,054	72%	743,419	255,080	66%
Downeaster	82%	1,954	114	94%	37,117	8,505	77%	415,799	101,498	76%
Empire	83%	5,476	1,792	67%	117,786	46,755	60%	1,579,768	349,051	78%
Adirondack	75%	456	20	96%	8,388	5,024	40%	86,383	27,723	68%
Ethan Allen Express	85%	503	379	25%	12,712	8,372	34%	157,923	41,696	74%
Maple Leaf	75%	870	263	70%	17,940	10,850	40%	214,017	66,013	69%
New York - Albany	90%	1,803	183	90%	46,401	12,483	73%	733,377	115,917	84%
New York - Niagara Falls	75%	1,359	693	49%	29,105	8,127	72%	382,938	95,026	75%
Berkshire Flyer	60%	485	254	48%	3,240	1,899	41%	5,130	2,676	48%
Heartland Flyer	70%	336	320	5%	5,336	4,257	20%	64,855	30,320	53%
Hiawatha	90%	1,982	0	100%	43,308	5,504	87%	493,820	64,869	87%
Illinois	78%	2,321	770	67%	55,498	18,834	66%	725,910	175,911	76%
Carl Sandburg / Illinois Zephyr	80%	466	0	100%	9,704	1,842	81%	116,382	14,931	87%
Illini / Saluki	80%	607	0	100%	18,538	4,769	74%	256,835	33,640	87%
Lincoln Service	75%	1,248	770	38%	27,256	12,223	55%	352,693	127,340	64%
Keystone	92%	4,857	641	87%	152,627	12,723	92%	2,117,415	287,405	86%
Lincoln / Missouri	60%	788	236	70%	17,434	10,848	38%	211,411	115,729	45%
Michigan	69%	2,546	440	83%	50,781	12,961	74%	568,796	159,420	72%
Blue Water	70%	640	15	98%	12,496	3,332	73%	141,095	41,224	71%
Pere Marquette	85%	433	128	70%	6,218	1,256	80%	75,294	9,888	87%
Wolverine	65%	1,473	297	80%	32,067	8,373	74%	352,407	108,308	69%
Missouri	80%	316	62	80%	5,442	3,630	33%	64,274	23,118	64%
Pacific Surfliner	85%	6,590	2,751	58%	149,475	22,689	85%	1,684,084	272,040	84%
Pennsylvanian	72%	849	601	29%	19,268	5,935	69%	255,283	68,316	73%
Piedmont	73%	1,198	0	100%	20,320	6,124	70%	329,511	79,546	76%
San Joaquins	73%	2,350	1,607	32%	54,263	27,875	49%	718,075	202,245	72%
Vermonter	75%	1,377	853	38%	26,707	10,624	60%	373,316	109,197	71%
Long Distance	57%	12,437	5,571	55%	269,821	157,051	42%	3,499,732	1,635,051	53%
Auto Train	57%	845	434	49%	16,618	5,679	66%	219,390	136,882	38%
California Zephyr	45%	1,121	562	50%	23,586	18,466	22%	286,229	124,966	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	238	157	34%	5,561	2,711	51%	79,611	39,726	50%
City Of New Orleans	75%	714	498	30%	11,733	5,191	56%	186,533	53,400	71%
Coast Starlight	65%	879	319	64%	20,874	6,999	66%	306,675	127,745	58%
Crescent	60%	1,007	426	58%	21,390	8,061	62%	253,458	65,585	74%
Empire Builder	55%	1,237	253	80%	24,476	14,848	39%	279,467	123,351	56%
Floridian	40%	578	441	24%	31,237	25,781	17%	394,592	289,561	27%
Lake Shore Ltd	70%	981	351	64%	22,620	8,140	64%	294,457	80,768	73%
Palmetto	65%	1,095	10	99%	20,218	10,042	50%	288,366	111,158	61%
Silver Meteor	45%	1,021	562	45%	21,079	14,224	33%	270,465	142,130	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,029	911	11%	21,393	16,892	21%	234,329	143,818	39%
Sunset Ltd	50%	305	7	98%	5,633	2,850	49%	77,272	28,646	63%
Texas Eagle	60%	1,387	640	54%	23,403	17,167	27%	271,293	144,819	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 20, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	148,109	2,079,348	712	1,860,290	30,523,285	609

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	7,277	604,587	120	98,361	8,932,666	110
INFRASTRUCTURE PLANNED	90	4,809	604,587	80	91,955	8,932,666	103
FLEET RELIABILITY	83	26,578	2,079,348	128	295,458	30,523,285	97
TRAIN OPERATIONS	382	109,445	2,079,348	526	1,374,516	30,523,285	450

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 49(20) - East of Rochester, NY - Trespasser Strike

21JUL25: 2:37am Train 49(20) with E/88 and E/111 plus 11 cars, carrying 138 passengers struck a trespasser near MP 361.4 on the CSX Rochester Subdivision. There were no reported injuries to crew or passengers. The trespasser was a confirmed fatality. There was no reported damage to the equipment. HEP was maintained throughout. The weather at the time of incident was 66° with periodic clouds. This incident occurred in the City of Fairport, Monroe County, NY and did not occur at a grade crossing. Monroe County Sheriff's Department and Fairport Police responded to the scene. Amtrak Police Detective Smith was advised. Train 49(20) was released from the scene at 3:54am.

New York State notified 3:12am.

National Response Center Number: 1437486

Train	Delay	Comment
49(20)	2'16"	

South of Philadelphia, PA - PW Line - Police Hold All Tracks

21JUL25: Local Police Requested a hold on all tracks between PHIL/MP 3.6 and BALDWIN/MP 11.7 due to an investigation/pursuit on or near the right of way. Amtrak assisted local police.

Train	Delay	Comment
139(20)	34"	
128(20)	33"	

Train 97(20) - Philadelphia, PA - Car Failure

20JUL25: Upon arrival at 30th Street Station/MP 1.4 on the Amtrak PW Line in Philadelphia, Train 97(20) incurred substantial delay. Sleeper Car 62008 was inspected by Mechanical Personnel and it was discovered to have a cracked wheel. The car was removed from the consist with the assistance of the yard crew. Passengers on Train 97(20) who were ticketed for Baltimore and Washington, DC were transferred to Train 139(20).

Train	Delay	Comment
97(20)	2'54"	
139(20)	10"	

Train 97(20) - East of Philadelphia, PA - Recrew

20JUL25: Train 97(20) was delayed on the Amtrak New York to Philadelphia Line at MP 77.1 due to a combination of issues; The No. 32 Switch at Holmes interlocking failed. The train was not shoved back due to the crew being close to the limits of their hours of service. The train was held at Holmesburg Junction for a recrew.

Train	Delay	Comment
97(20)	1'25"	

Train 169(20) - Boston, MA - Initial Terminal Delay

20JUL25: Train 169(20) was delayed at its initial terminal at Boston South Station due to holding for its crew, which arrived on late running Train 2226(20).

Train	Delay	Comment
169(20)	33"	

Train 2222(20) - South of Baltimore, MD - Engine Failure

20JUL25: Train 2222(20) was delayed at MP 121.0 on the Amtrak Philadelphia top Washington Line due to a brake malfunction. The Engineer reported the brakes being applied and unable to release. The crew bypassed the onboard trainline to resolve the issue.

Train	Delay	Comment
2222(20)	35"	
80(20)	20"	
166(20)	18"	

Train 49(20) New York, NY - Servicing

20JUL25: Train 49(20) was delayed departing New York due to late released from the yard due to servicing. Train 49(20) was further delayed due to holding for mechanical personnel to inspect the baggage car for a possible coupler break they were coming over from the yard on train 97(20) that was released at 455P-ET.

Train	Delay	Comment
49(20)	3'33"	

Train 97(20) New York, NY - Servicing

20JUL25: Train 97(20) was delayed departing New York due to the late turn off 98(19) that arrived at 130P-ET 2 hours and 10 minutes late.

WBS#: B.TR.100151.0761

Train	Delay	Comment
97(20)	3'15"	

Train 464(20) New Haven, CT - Hold for Connection

20JUL25: Train 464(20) was held in New Haven due to holding for late connections off 164(20).

Train	Delay	Comment
464(20)	1'11"	

Train 2252(20) West of Newark Liberty Airport, NJ - Engine Failure

20JUL25: Train 2252(20) with set 17 PC/2022 and PC/2011 was disabled on the New York to Philadelphia main line at MP 11.3/Haynes with an unrecoverable brake application. There were 290 passengers onboard and the train was able to maintain HEP.

UPDATE: Train 2252(20) was able to recover but was running with cab signal failure. They were disabled for the second time an Amtrak Road Foreman was onboard and they proceeded into New York. Due to the on going issues with set 17 trains 2252(20) and 2253(20) swapped sets in New York after mechanical checked out both sets of equipment.

Train	Delay	Comment
2252(20)	1'04"	
2252(20)	43"	swapping sets NYP
2253(20)	1'04"	swapping sets NYP
118(20)	15"	
154(20)	17"	

Train 2250(20) BWI Marshall Airport, MD - Engine Failure

20JUL25: Train 2250(20) was delayed on the Philadelphia to Washington main line due to having multiple parking brake faults in the PC/2023. They were further delayed at Newark station the Philadelphia to New York main line with door issues. They were further delayed in New York per the request of the crew for mechanical to look at the equipment. Mechanical released the train and they had the same parking brake fault at JO interlocking just prior to the tunnel. It was decided to have them switch ends and bring the equipment back into the station. There was 264 passengers onboard. Train 2250(20) was terminated in New York.

UPDATE: New York reported that they are unable to operate from PC/ 2011 due to parking brake faults. Recue engine was enroute, Road Forman walking over to the train, High Speed Rail Mechanical. Trains departing New York will see 20-30 minutes delays due to the line 2 outage. Train 2250(20) that was disabled line 1 at JO interlocking the rescue engine was coupling to bring set back into the station and a code 500 was initiated at 3P-ET. There were no passenger issues reported at the time. As of 327P-ET train 2250(20) was back in the station and no passengers issues were reported. The code 500 was cancelled.

Train 2275(20) was cancelled in its entirety between Boston, MA and Washington, DC due to shopped equipment.

Train	Delay	Comment
2250(20)	11"	nwk door issues
2250(20)	51"	parking brake issues
2250(20)	TERM NYP	
2275(20)	CANCELLED	
2250(20)	2'16"	
283(20)	18"	
164(20)	54"	
161(20)	12"	
2162(21)	Cancelled	
2193(21)	Cancelled	

Train 1233(20) New York, NY - Cab Car Failure

20JUL25: Train 1233(20) was delayed departing New York due to having mechanical issues with CC/9700 in the station. Mechanical was working on fixing the issue.

Train	Delay	Comment
1233(20)	1'32"	

CSX Heat Orders - Northeast and Southeast Regions

20JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Charleston for 70 miles, Jacksonville Terminal, Nahunta, Sanford, Savannah, and South End.

Train	Delay	Comment
89 (20)	23"	
98 (20)	27"	
52 (20)	13"	
79 (20)	13"	
90 (20)	07"	

Washington, DC - Servicing

20JUL25: Several trains were delayed departing Washington due to overnight short staffing which caused delays of trains being released from the S&I.

Train	Delay	Comment
66 (19)	28"	
118 (20)	53"	
154 (20)	43"	
189 (20)	33"	LATE TURN OFF 118 (20)

Train 99(20) Boston, MA -Door Issues / Car Failure

20JUL25: Train 99(20) was delayed departing Boston due to having door issues in the S&I. It was determined to move train 149(20) up for 99(20) but it still needed to be cleaned and serviced.

Train 149(20) had to shop C/82571 for door issues and this had the train departing oversold.

Train 87(20) was delayed due to late release from the yard.

Train	Delay	Comment
87 (20)	36"	
99 (20)	2'18"	

NS PTC Outage - System

20JUL25: Several Trains were delayed due to NS Systemwide PTC Outage. Trains were unable to initialize PTC and operated under block protection at a reduced speed.

Train	Delay	Comment
48/448 (19)	56"	
49/449 (19)	19"	
19 (19)	1'08"	
20 (19)	21"	

Train 162(20) Washington, DC - Car Failure

20JUL25: Train 162(20) was delayed departing Washington due to shopping cafe car C/43347 and replacing with C/43366.

Train	Delay	Comment
162 (20)	37"	

Train 58(20) South of Memphis, TN - Signal

21JUL25: Train 58(20) was delayed at the CN Junction/MP393.5 2 miles south of Memphis, TN/MP391.8 on the CN Memphis subdivision due to a signal issue. BNSF maintainers were on the scene attempting to make repairs. A recrew engineer signed on at Memphis, TN and boarded train 58(20) as the engineer expired on hours of service while waiting for a route through the switch. Once CN Railroad instructed BNSF to allow trains to walk across the switch due to mounting congestion, train 58(20) proceeded through the affected area and into Memphis Station, TN.

Due to the late operation of train 58(20), the fuel vendor was no longer onsite at Memphis, TN. Train 58(20) was further delayed at Fulton, KY/MP404.6 for fueling.

Train	Delay	Comment
58(20)	1'28"	
58(20)	xx"	FTN - fueling

Train 11(19) South of Salinas, CA - Trespasser Incident

20JUL25: At approximately 1:35 PM-PT train 11(19) - operating with camera equipped locomotives AMTK/61, AMTK/339 and eight (8) cars - struck and injured a trespasser at MP 141.0 on the Union Pacific Railway Coast Subdivision in the city of Soledad, Monterey County, California. This incident did NOT occur on a public highway crossing at grade. Train 11(19) was operating south at an estimated 65 MPH on the main track with a posted track speed of 70 MPH. Local Police and Fire officials responded to the scene along with representatives from Amtrak management. There were no initial reports of injuries to the 202 passengers or crew and no reports of damage to Amtrak equipment. The operating crew requested relief, and the outbound crew from San Luis Obispo was transported to the scene where they assumed operation of the train. Once local authorities released the scene and the relief crew was onboard, train 11(19) was able to proceed.

Account the late operation of trian 11(19) caused by this event, train 2/422(20) was held in Los Angeles, CA (LAX) for 36 passengers with through connections. Once train 11(19) arrived and passengers safely transferred, train 2/422(20) departed LAX.

National Response Center: 1437463
California Office of Emergency Services: 25-3594

Google Maps Location of Incident:
<https://maps.app.goo.gl/PxdV9Gn8RYzo9TJVA>
36.420031, -121.318629
Soledad, California 93960

WBS#: B.TR.100150.5906

National Response Center Number: 1437463

Train	Delay	Comment
11(19)	3'41"	Trespasser Strike
2/422(20)	Est 4'30"	LAX - Hold for through passengers from train 11(19)
11(19)	1'10"	Calendar day inspection at Goleta Station

Train 5(20) Chicago, IL - Car Failure - Crew Issue

20JUL25: Train 5(20) was delayed departing Chicago due to the engineer signing up at 243PM-CT. Additional delays were attributed to C/31028 with a brake indicator issue at Union Station. Chicago mechanical responded to assist with repairs. Chicago mechanical had ordered car C/31028. Passengers were detrained and the equipment shoved back to the yard to replace C/31028 with C/31008. Due to crew availability issues, train 5(20) held at Chicago Union Station, IL waiting for the engineer off train 382(20). Once Chicago mechanical released the equipment, train 5(20) shoved back to the station, and passengers boarded again, train 5(20) departed Chicago Union Station.

Due to the late operation of 5(20), the following service recovery was in effect. Passengers were provided snack packs, water bottles, pizza, beverages, and dessert at the station. Sleeper passengers were provided station vouchers. Additional breakfast items were delivered to the lounge car for morning recovery. On Monday, July 21st, service recovery consisted of:

- Regular meals off the menu for Sleeper Passengers.
- Snack packs and water provided throughout the day.
- Lounge car will off coffee, tea, juice, muffins, coffee cake, and snacks.
- Lunch will be served out of the lounge car.

WBS#: B.TR.100150.5907

Train	Delay	Comment
5(20)	55"	Engineer sign up off 4' cut
5(20)	7'02"	Replace C/31028

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

- 370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

- 371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without businessclass. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

Train	Delay	Comment
-------	-------	---------

301(15)	Cancelled, with alt CHI-STL
302(15)	Cancelled, with alt STL-CHI
307(14)	Cancelled, with alt CHI-STL
306(16-29)	Cancelled, no alternate
301(16-29)	Cancelled, no alternate

North County Transit District - Planned Trackwork East of Solana Beach

North County Transit District - Trackwork East of Solana Beach, CA

19MAY24, Commencing 19th May, North County Transit District will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad.

Each project will be over selected Sunday and Monday nights:

from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

Sunday May 19 - Tuesday May 21
 Sunday June 02- Tuesday June 04
 Sunday June 16 - Tuesday June 18
 Sunday June 23 - no extended window account Padres game.
 Sunday June 30 - Tuesday July 2
 Sunday July 7 - Tuesday July 9
 Sunday July 14 - Tuesday July 16
 Sunday July 21 - Tuesday July 23
 Sunday July 28 - Tuesday July 30
 Sunday August 4 - Tuesday August 6
 Sunday August 11 - no extended window account Padres game
 Sunday August 18th - Tuesday 20th
 Sunday August 25 - Tuesday August 27
 Sunday September 8 - Tuesday September 10.
 Sunday September 15 - Monday September 16
 Sunday September 22 - Tuesday September 24.
 Sunday October 27 - Tuesday October 29.
 Sunday November 3 - Tuesday November 5.
 Sunday December 8-Tuesday December 10.
 Sunday December 15-Tuesday December 17.
 2025
 Sunday February 9 - Tuesday February 11.
 Sunday April 06th - Tuesday April 08th (CANCELLED)
 Sunday May 20 - Tuesday May 22

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790 (Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761 (Monday/Tuesday)	Originates SOL	Bus Service from SAN
765 (Monday/Tuesday)	Originates SOL	Bus Service from SAN
794 (Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Train 58(20) North of Marks, MS - Freight Train Interference

21JUL25: Train 58(20) was delayed at North Lake Cormorant/MP19.0 49 miles north of Mark, MS/MP67.3 on the CN Yazoo subdivision meeting freight CN/1011. Once the route was clear, train 58(20) proceeded north.

Train	Delay	Comment
58 (20)	32"	

Train 4(19) East of Garden City, KS - Signal

21JUL25: Train 4(19) was delayed between Garden City, KS/MP389.4 and Ingalls, KS/MP371.7 beginning 13 miles east of Garden City Station, KS due to restrictive signals. Once through the affected area, train 4(19) continued east.

Train	Delay	Comment
4 (19)	47"	

Train 307(20) East of St. Louis, MO - High Wind Warnings

21JUL25: Train 307(20) was delayed at WR Tower, IL/MP275.5 10 miles east of St Louis, MO/MP1.5 on the UP Springfield subdivision waiting for high wind warnings to expire. Once the route was clear, train 307(20) proceeded into St Louis Station, MO.

Train	Delay	Comment
307 (20)	34"	

Train 507(20) Tacoma, WA - Freight Train Interference

20JUL25: Train 507(20) was delayed south of Tacoma, WA (TAC) at CP Rill on the Sound Transit Lakewood Subdivision. A freight train, BNSF/193, was having problems climbing the grade and was required to "double the hill" (split train in two, take first half over, then go and get second half). Once the freight train was clear of the single main track ahead, train 507(20) was able to proceed south.

Train	Delay	Comment
507 (20)	1'01"	

Train 4(19) West of Raton, NM - High Wind Warnings

20JUL25: Train 4(19) was delayed between Las Vegas, NM/MP758.0 and Raton, NM/MP660.0 on the BNSF Raton subdivision due to high wind warnings that required operation at reduced speeds. Once through the affected area, train 4(19) proceeded into Raton Station, NM/MP659.3.

Train	Delay	Comment
4 (19)	37"	

Train 3(19) Albuquerque, NM - Servicing

20JUL25: Train 3(19), with engines 188 and 83, 10 cars, and 205 passengers, was delayed departing Albuquerque Station, NM/MP902.5 on the NMRX Albuquerque subdivision due to completing a regular calendar day inspection. Once the inspection was complete, train 3(19) departed Albuquerque Station, NM heading west.

Train	Delay	Comment
3(19)	30"	

Train 1(19)/421(18) East of Deming, NM - Signal

20JUL25: Train 1(19)/421(18) was delayed in Vado, NM/MP1268.2 60 miles east of Deming, AZ/MP1208.1 on the UP Lordsburg subdivision due to a power switch failure at control point 1268/MP1268.0. Once through the affected area, train 1(19)/421(18) continued to Deming, AZ.

Train	Delay	Comment
1(19)/421(18)	46"	

Train 770(20) Los Angeles, CA - Servicing

20JUL25: Train 770(20) was delayed at Los Angeles, CA (LAX) on the Southern California Regional Rail Authority River Subdivision. To accommodate the Del Mar race season, the Del Mar Block (Extra set of cars and locomotive), were added to the train at LAX to accommodate increased ridership. This took longer than anticipated account unforeseen air problems with the equipment. Technicians from LAX Depot Mechanical were able to resolve the problem and train 770(20) departed LAX at 10:48 AM-PT.

Train	Delay	Comment
770(20)	35"	

Train 22(20) South of Fort Worth, TX - Freight Train Interference

20JUL25: Train 22(20) was delayed one mile south of Fort Worth on the BNSF Fort Worth subdivision due to meeting MBDFW-20 at Tower 55/MP 345.3.

Train	Delay	Comment
22(20)	30"	

Train 7/27(20) Chicago, IL - Initial Terminal Delay

20JUL25: Train 7/27(20) with E/306-50 and 10 cars was delayed departing Chicago due to a broken knuckle on C/31024, which delayed the train makeup and release. Additional delays were attributed to C/33006 with a brake indicator light issue. Once the equipment was released and boarded, 7/27(20) departed Chicago at 347PM-CT, 42 minutes late.

Train	Delay	Comment
7/27(20)	42"	

Train 58(20) North of New Orleans, LA - Signal

20JUL25: Train 58(20) was delayed six miles north of New Orleans on the CN McComb subdivision due to a track circuit with UPRR freight blocking the route at East Bridge Jct./MP 906.4. Train 59(19) was delayed for the same reason. 203PM-CT, an UPRR maintainer arrived on scene. 318PM-CT, train 58(20) was being talked through the effected area followed by train 59(19).

Train	Delay	Comment
58 (20)	2'15"	
59 (19)	2'39"	

Train 59(19) North of Hazlehurst, MS - Debris

20JUL25: Train 59(19) with E/181 and 7 cars was delayed 14 miles north of Hazlehurst on the CN McComb subdivision due to striking a tree at MP 747.9. There were no reported injuries to the 105 passengers or the crew. The crew removed the tree and branches, reported minimal damage to the plow on E/181, and continued to Hazlehurst.

Train	Delay	Comment
59 (19)	12"	

Train 720(20) Oakland, CA - Initial Terminal Delay

20JUL25: Train 720(20) was delayed departing Oakland due to a late release from mechanical. Train 710(20) was delayed for the same reason. Once released and boarded, 720(20) departed Oakland at 721AM-PT, 9 minutes late and 710(20) departed Oakland at 803AM-PT, 27 minutes late.

WBS#: B.TR.100150.5905

Train	Delay	Comment
720 (20)	09"	
710 (20)	27"	
738 (20)	10"	

Train 22(20) South of San Marcos, TX - M/W Work

20JUL25: Train 22(20) was delayed two miles south of San Marcos on the UPRR Austin subdivision due to MOW overstay completing switch replacement. Once the tracks were released, 22(20) continued to San Marcos.

Train	Delay	Comment
22 (20)	1'41"	

Train 391(20) South of Chicago, IL - Engine Failure

20JUL25: Train 391(20) with E/ID4630 and 7 cars was delayed three miles south of Chicago on the NS Chicago district at 21st St/MP 521.1 due to PTC issues related to the speedometer on E/ID4630 from a prior debris strike. The crew worked with CNOC mechanical to recycle the breaker and were unsuccessful. As a result of PTC failure and unable to operate 392(20) out of Carbondale for said reason, 391(20) shoved back to Chicago and was cancelled with alternate bus transportation between Chicago and Carbondale. Train 392(20) was also cancelled between Carbondale and Chicago with alternate bus transportation.

WBS#: B.TR.100150.5904

Train	Delay	Comment
391 (20)	Canc	CHI-CDL W/alt
392 (20)	Canc	CDL-CHI W/alt

Train 22(20) St. Louis, MO - Crew

20JUL25: Train 22(20) was delayed departing St. Louis on the TRRA Merchants subdivision due to the crew signing up at 830AM-CT. Once the crew signed up, briefed, and boarded the train, 22(20) departed St. Louis at 906AM-CT, 56 minutes late.

Train	Delay	Comment
22(20)	56"	

Train 711(20) East of Wasco, CA - Police Related

20JUL25: Train 711(20) was delayed 13 miles east of Wasco on the BNSF Bakersfield subdivision due to a vehicle on the tracks at MP 903.017. Once the vehicle was removed and the tracks were inspected, 711(20) continued to Wasco.

Train	Delay	Comment
711(20)	51"	

Train 794(19) Solana Beach, CA - Freight Train Interference

20JUL25: Train 794(19) was delayed departing Solana Beach, CA on the SCRRA San Diego subdivision due to a disabled freight ahead with a broken knuckle and DPU issues. SCRRA mechanical forces responded and worked on repairing the knuckle. Mechanical had trouble finding a knuckle to fit the equipment and spent additional time locating one. The freight crew hours of service was up at 400AM-PT with a relief crew on duty in San Bernardino at 530AM-PT. With this being said, the initial estimated time for opening was 830AM-PT. As a result, train 794(19) was terminated at Solana Beach with 15 passengers provided alternate transportation via bus 5818(19). Train 761(20) originate at Los Angeles with an extra set of equipment and train 765(20) originated at Solana Beach utilizing 794(19) equipment. Passengers traveling between San Diego and Solana Beach on trains 761(20) and 765(20) were provided alternate bus transportation to Solana Beach, where they boarded 765(20). Train 562(20) was cancelled entirely between Los Angeles and San Diego with the crew vanning to San Diego for their turn and passengers accommodated on the next available services. Train 769(20) was delayed holding for open track at Old Town and 564(20) was delayed holding for open track at Oceanside.

Operations Recovery Plan:

- 794(19) terminate Solana Beach, CA - Replacement bus to San Diego, CA
- 765(20) originate Solana Beach, CA - Replacement bus from San Diego, CA
- 761(20) originate Los Angeles, CA- passengers to 765(20)
- 562(20) cancelled - passengers to 564(20)
- 769(20) hold at Old Town - San Diego, CA for open track
- 564(20) hold at Oceanside, CA for open track.

WBS#: B.TR.100150.5903

Train	Delay	Comment
769(20)	1'40"	OLT - hold for open track
564(20)	42"	OSD - hold for open track
573(20)	35"	Late crew - deadhead from LAX-SAN
765(20)	48"	Orig SOL - hold for replacement bus from SAN
562(20)	Cancelled	Pax to 564(20)
761(20)	Orig LAX	SAN-LAX pax to 765(20)
794(19)	Term SOL	Rescue Bus SOL-SAN
790(20)	1'15"	GTA - Late inbound equipment from 769(20)

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/20/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/20/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	271	46	83.0%	5,745	706	87.7%	84,452	8,375	90.1%
Central Division	91.5%	62	5	91.9%	1,314	146	88.9%	19,343	1,886	90.2%
Northeast Division	95.0%	89	20	77.5%	1,812	256	85.9%	27,767	3,019	89.1%
Southeast Division	94.5%	55	6	89.1%	1,259	156	87.6%	18,688	1,870	90.0%
Southwest Division	90.5%	65	15	76.9%	1,360	148	89.1%	18,654	1,600	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/20/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/20/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	271	46	83.0%	5,745	706	87.7%	84,452	8,375	90.1%
Central Division	91.5%	62	5	91.9%	1,314	146	88.9%	19,343	1,886	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	1	0	100.0%	44	3	93.2%	587	17	97.1%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	25	3	88.0%	530	82	84.5%	7,806	967	87.6%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	40	0	100.0%	564	19	96.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	19	0	100.0%	292	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	1	50.0%	39	2	94.9%	568	39	93.1%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	5	0	100.0%	116	5	95.7%	1,679	93	94.5%
MSP	95.0%	1	0	100.0%	20	2	90.0%	281	14	95.0%
PDX	78.0%	5	0	100.0%	96	9	90.6%	1,408	161	88.6%
PNT	94.0%	3	0	100.0%	59	1	98.3%	806	57	92.9%
PTH	96.0%	1	0	100.0%	20	0	100.0%	291	11	96.2%
QCY	94.0%	2	0	100.0%	38	0	100.0%	568	18	96.8%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	0	100.0%	161	29	82.0%	2,288	329	85.6%
SPK	92.0%	1	0	100.0%	18	1	94.4%	289	14	95.2%
STL	96.0%	3	1	66.7%	70	8	88.6%	1,147	61	94.7%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	40	0	100.0%	561	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	89	20	77.5%	1,812	256	85.9%	27,767	3,019	89.1%
ALB	96.0%	6	0	100.0%	120	5	95.8%	1,969	127	93.6%
BON	94.5%	5	0	100.0%	98	8	91.8%	1,362	91	93.3%
BOS	97.0%	19	6	68.4%	355	43	87.9%	5,472	509	90.7%
BRK	97.0%	5	0	100.0%	71	2	97.2%	1,332	68	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	1	0.0%	20	3	85.0%	291	20	93.1%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	1	0	100.0%	36	2	94.4%	563	54	90.4%
HFD	-	-	-	-	26	4	84.6%	172	17	90.1%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/20/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/20/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	271	46	83.0%	5,745	706	87.7%	84,452	8,375	90.1%
Northeast Division	95.0%	89	20	77.5%	1,812	256	85.9%	27,767	3,019	89.1%
MTR	97.0%	1	0	100.0%	20	2	90.0%	291	28	90.4%
NFL	97.0%	2	0	100.0%	40	1	97.5%	586	24	95.9%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	4	2	50.0%	93	16	82.8%	1,500	150	90.0%
NYP	94.5%	36	10	72.2%	765	147	80.8%	11,758	1,785	84.8%
POR	-	-	-	-	24	8	66.7%	24	8	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	18	3	83.3%	289	8	97.2%
SPG	95.5%	7	1	85.7%	99	9	90.9%	1,795	85	95.3%
TWO	96.0%	1	0	100.0%	20	0	100.0%	290	11	96.2%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	55	6	89.1%	1,259	156	87.6%	18,688	1,870	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	97	9	90.7%	1,451	94	93.5%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	7	0	100.0%	218	13	94.0%	3,163	101	96.8%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	20	3	85.0%	287	91	68.3%
MIA	90.0%	1	0	100.0%	38	6	84.2%	563	53	90.6%
NFK	94.5%	2	0	100.0%	56	12	78.6%	806	66	91.8%
NOL	92.0%	2	0	100.0%	43	3	93.0%	650	46	92.9%
NPN	96.0%	2	0	100.0%	40	4	90.0%	559	21	96.2%
PGH	92.0%	1	0	100.0%	20	2	90.0%	292	16	94.5%
PHL	97.0%	2	0	100.0%	83	19	77.1%	1,249	176	85.9%
RGH	97.0%	4	1	75.0%	72	3	95.8%	1,175	37	96.9%
RNK	94.0%	2	0	100.0%	37	2	94.6%	554	64	88.4%
RVM	90.0%	1	0	100.0%	20	1	95.0%	284	34	88.0%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	18	1	94.4%	274	11	96.0%
SFA	83.0%	1	0	100.0%	20	1	95.0%	287	79	72.5%
WAS	94.5%	23	5	78.3%	467	67	85.7%	6,941	948	86.3%
Southwest Division	90.5%	65	15	76.9%	1,360	148	89.1%	18,654	1,600	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	20	0	100.0%	293	7	97.6%
BFD	90.0%	6	1	83.3%	118	14	88.1%	1,741	150	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	20	16	20.0%	300	92	69.3%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	19	2	89.5%	325	42	87.1%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/20/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/20/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	271	46	83.0%	5,745	706	87.7%	84,452	8,375	90.1%
Southwest Division	90.5%	65	15	76.9%	1,360	148	89.1%	18,654	1,600	91.4%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	1	66.7%	60	3	95.0%	856	63	92.6%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	10	4	60.0%	189	24	87.3%	2,248	315	86.0%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	17	0	100.0%	288	6	97.9%
OKJ	91.0%	9	4	55.6%	218	37	83.0%	3,071	287	90.7%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	11	0	100.0%	259	22	91.5%	3,490	147	95.8%
SAN	90.0%	12	4	66.7%	238	18	92.4%	2,660	236	91.1%
SAS	85.0%	1	0	100.0%	20	5	75.0%	289	40	86.2%
SJC	95.0%	7	0	100.0%	139	6	95.7%	1,879	72	96.2%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	40	0	100.0%	573	27	95.3%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	2	0	100.0%	49	11	77.6%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/20/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		9	3	66.7%	124	24	80.6%	9	3	66.7%	119	22	81.5%
3	126	20	5	75.0%	287	55	80.8%	20	15	25.0%	283	156	44.9%
4	121	20	5	75.0%	288	70	75.7%	20	16	20.0%	287	147	48.8%
5		20	10	50.0%	290	49	83.1%	19	14	26.3%	287	97	66.2%
6	377	20	16	20.0%	290	85	70.7%	20	17	15.0%	289	99	65.7%
7		20	5	75.0%	284	41	85.6%	20	7	65.0%	279	74	73.5%
8		20	14	30.0%	285	106	62.8%	20	14	30.0%	283	135	52.3%
11	No OS	20	2	90.0%	292	46	84.2%	20	3	85.0%	285	64	77.5%
14		20	7	65.0%	293	89	69.6%	20	8	60.0%	291	128	56.0%
19		20	0	100.0%	293	33	88.7%	20	8	60.0%	292	57	80.5%
20	35	20	1	95.0%	293	14	95.2%	20	5	75.0%	292	47	83.9%
21		20	1	95.0%	292	35	88.0%	20	7	65.0%	286	90	68.5%
22	32	20	5	75.0%	289	42	85.5%	20	17	15.0%	288	125	56.6%
27		18	4	77.8%	280	21	92.5%	17	7	58.8%	270	93	65.6%
28		17	3	82.4%	273	68	75.1%	17	4	76.5%	272	76	72.1%
40	34	20	4	80.0%	250	37	85.2%	20	15	25.0%	246	154	37.4%
42	38	20	2	90.0%	293	17	94.2%	20	6	70.0%	293	80	72.7%
43		20	2	90.0%	293	25	91.5%	20	6	70.0%	293	66	77.5%
48		20	5	75.0%	292	53	81.8%	20	4	80.0%	292	45	84.6%
49		20	8	60.0%	293	58	80.2%	20	5	75.0%	293	52	82.3%
50	59	9	4	55.6%	125	39	68.8%	9	7	22.2%	124	89	28.2%
52	41	20	1	95.0%	287	79	72.5%	20	6	70.0%	287	153	46.7%
53		20	3	85.0%	287	91	68.3%	20	4	80.0%	287	144	49.8%
54	113	7	0	100.0%	91	3	96.7%	7	2	71.4%	91	14	84.6%
57		7	1	85.7%	91	2	97.8%	7	0	100.0%	91	9	90.1%
58	63	20	2	90.0%	285	23	91.9%	20	4	80.0%	282	57	79.8%
59	118	20	6	70.0%	284	58	79.6%	19	7	63.2%	280	34	87.9%
63	36	20	13	35.0%	293	59	79.9%	20	18	10.0%	293	150	48.8%
64		20	0	100.0%	293	11	96.2%	20	3	85.0%	293	71	75.8%
65		7	1	85.7%	91	4	95.6%	7	1	85.7%	91	16	82.4%
66		20	3	85.0%	291	56	80.8%	20	1	95.0%	289	37	87.2%
68		20	2	90.0%	293	28	90.4%	20	15	25.0%	293	119	59.4%
69		20	2	90.0%	293	22	92.5%	19	7	63.2%	288	34	88.2%
71		19	2	89.5%	292	7	97.6%	19	8	57.9%	290	66	77.2%
72		20	3	85.0%	293	22	92.5%	20	7	65.0%	291	74	74.6%
73		20	4	80.0%	293	16	94.5%	20	9	55.0%	291	144	50.5%
74		20	1	95.0%	289	21	92.7%	20	8	60.0%	287	98	65.9%
75		20	3	85.0%	291	8	97.3%	20	10	50.0%	289	117	59.5%
76		20	4	80.0%	289	20	93.1%	19	13	31.6%	287	126	56.1%
77		20	2	90.0%	290	12	95.9%	20	9	55.0%	288	129	55.2%
78		20	0	100.0%	291	10	96.6%	19	6	68.4%	290	70	75.9%
79		20	5	75.0%	293	40	86.3%	18	6	66.7%	290	104	64.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/20/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80		20	3	85.0%	293	24	91.8%	20	13	35.0%	293	86	70.6%
87		7	2	71.4%	91	7	92.3%	7	4	42.9%	91	43	52.7%
88	30	7	2	71.4%	91	8	91.2%	7	3	57.1%	91	25	72.5%
89		20	2	90.0%	292	36	87.7%	20	9	55.0%	290	107	63.1%
90		20	1	95.0%	292	12	95.9%	19	8	57.9%	287	72	74.9%
96		3	0	100.0%	43	0	100.0%	3	1	66.7%	43	19	55.8%
97		20	14	30.0%	289	135	53.3%	20	10	50.0%	288	94	67.4%
98	130	20	3	85.0%	289	18	93.8%	20	14	30.0%	289	150	48.1%
99	154	7	1	85.7%	91	3	96.7%	7	7	0.0%	91	56	38.5%
103		7	0	100.0%	91	13	85.7%	7	1	85.7%	91	14	84.6%
105		3	2	33.3%	42	24	42.9%	3	2	33.3%	41	10	75.6%
106		7	1	85.7%	62	13	79.0%	7	0	100.0%	61	11	82.0%
107	25	7	1	85.7%	62	16	74.2%	7	2	71.4%	61	17	72.1%
118	89	7	1	85.7%	91	11	87.9%	7	1	85.7%	91	13	85.7%
120		3	0	100.0%	43	4	90.7%	3	0	100.0%	41	6	85.4%
121		3	1	66.7%	40	12	70.0%	3	0	100.0%	40	7	82.5%
122		3	0	100.0%	40	12	70.0%	3	0	100.0%	40	8	80.0%
123		3	1	66.7%	43	3	93.0%	3	0	100.0%	43	1	97.7%
124		7	0	100.0%	91	6	93.4%	6	2	66.7%	90	18	80.0%
128		7	2	71.4%	91	27	70.3%	6	1	83.3%	90	23	74.4%
135	24	7	0	100.0%	91	8	91.2%	7	2	71.4%	90	31	65.6%
140		7	0	100.0%	91	10	89.0%	7	0	100.0%	91	30	67.0%
143		7	3	57.1%	91	4	95.6%	7	0	100.0%	91	6	93.4%
145		3	0	100.0%	43	2	95.3%	3	1	66.7%	43	20	53.5%
146	23	7	0	100.0%	91	11	87.9%	7	3	57.1%	91	38	58.2%
149		3	0	100.0%	43	5	88.4%	3	1	66.7%	43	11	74.4%
150		7	2	71.4%	91	22	75.8%	7	0	100.0%	91	34	62.6%
151		20	3	85.0%	290	35	87.9%	20	4	80.0%	289	97	66.4%
153	34	7	1	85.7%	91	11	87.9%	7	4	42.9%	91	37	59.3%
154	103	3	1	66.7%	43	13	69.8%	3	2	33.3%	43	18	58.1%
155		7	0	100.0%	91	12	86.8%	7	0	100.0%	91	9	90.1%
156	23	7	0	100.0%	91	4	95.6%	7	4	42.9%	91	31	65.9%
157		3	1	66.7%	43	1	97.7%	3	2	33.3%	43	20	53.5%
158		7	1	85.7%	91	9	90.1%	7	2	71.4%	91	20	78.0%
160		7	2	71.4%	91	10	89.0%	7	1	85.7%	90	11	87.8%
161	20	7	0	100.0%	91	3	96.7%	7	4	42.9%	91	53	41.8%
162	44	6	1	83.3%	90	5	94.4%	6	2	66.7%	89	26	70.8%
164	66	7	0	100.0%	91	13	85.7%	7	2	71.4%	91	38	58.2%
165		7	1	85.7%	91	17	81.3%	7	0	100.0%	91	27	70.3%
167		3	2	33.3%	47	17	63.8%	3	1	66.7%	47	15	68.1%
169		7	2	71.4%	91	9	90.1%	6	0	100.0%	89	8	91.0%
189	53	3	1	66.7%	43	9	79.1%	3	2	33.3%	43	12	72.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/20/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
195	50	7	0	100.0%	91	1	98.9%	7	6	14.3%	91	64	29.7%
232		20	1	95.0%	281	10	96.4%	20	1	95.0%	281	22	92.2%
234		20	1	95.0%	281	7	97.5%	20	2	90.0%	281	22	92.2%
236		20	0	100.0%	281	5	98.2%	20	2	90.0%	280	46	83.6%
237		17	0	100.0%	276	28	89.9%	17	2	88.2%	274	32	88.3%
239		20	4	80.0%	280	29	89.6%	20	6	70.0%	280	22	92.1%
240		20	0	100.0%	285	24	91.6%	20	5	75.0%	284	27	90.5%
241		20	3	85.0%	293	36	87.7%	19	7	63.2%	292	43	85.3%
245	20	7	1	85.7%	108	16	85.2%	6	1	83.3%	108	10	90.7%
280	27	20	0	100.0%	292	11	96.2%	20	2	90.0%	292	53	81.8%
281		20	2	90.0%	293	60	79.5%	19	5	73.7%	291	60	79.4%
283	26	20	7	65.0%	293	64	78.2%	20	10	50.0%	292	63	78.4%
284		20	1	95.0%	293	13	95.6%	20	1	95.0%	292	59	79.8%
290	43	20	3	85.0%	293	22	92.5%	19	15	21.1%	291	68	76.6%
291	28	20	8	60.0%	293	46	84.3%	20	15	25.0%	292	61	79.1%
300	22	18	1	94.4%	282	8	97.2%	18	6	66.7%	280	69	75.4%
302		19	3	84.2%	287	21	92.7%	19	7	63.2%	284	97	65.8%
305		20	3	85.0%	287	22	92.3%	20	15	25.0%	286	111	61.2%
307	137	19	2	89.5%	286	38	86.7%	18	10	44.4%	283	105	62.9%
311		19	3	84.2%	283	18	93.6%	19	15	21.1%	279	111	60.2%
316		19	1	94.7%	281	19	93.2%	19	15	21.1%	279	104	62.7%
318		20	1	95.0%	289	20	93.1%	20	12	40.0%	285	159	44.2%
319		20	1	95.0%	291	19	93.5%	20	16	20.0%	286	177	38.1%
331		20	1	95.0%	284	20	93.0%	20	2	90.0%	280	27	90.4%
332		20	1	95.0%	289	17	94.1%	20	3	85.0%	288	44	84.7%
334		20	0	100.0%	289	9	96.9%	20	3	85.0%	284	71	75.0%
335		20	2	90.0%	292	31	89.4%	20	5	75.0%	283	61	78.4%
336		20	1	95.0%	278	7	97.5%	20	6	70.0%	277	81	70.8%
337		20	2	90.0%	281	17	94.0%	20	6	70.0%	280	63	77.5%
338		20	2	90.0%	291	37	87.3%	20	7	65.0%	281	122	56.6%
339		20	0	100.0%	291	42	85.6%	20	2	90.0%	289	50	82.7%
341		19	10	47.4%	276	55	80.1%	19	11	42.1%	270	58	78.5%
342		20	0	100.0%	292	18	93.8%	20	1	95.0%	291	44	84.9%
350	22	20	2	90.0%	252	27	89.3%	20	14	30.0%	249	127	49.0%
351		20	0	100.0%	281	24	91.5%	20	4	80.0%	280	77	72.5%
352		20	3	85.0%	286	27	90.6%	20	10	50.0%	281	81	71.2%
353		20	0	100.0%	245	6	97.6%	20	1	95.0%	240	36	85.0%
354		19	0	100.0%	285	26	90.9%	19	4	78.9%	282	102	63.8%
355		19	1	94.7%	285	31	89.1%	19	4	78.9%	281	72	74.4%
364		20	1	95.0%	291	55	81.1%	20	5	75.0%	290	79	72.8%
365		20	0	100.0%	291	11	96.2%	20	7	65.0%	290	85	70.7%
370		19	2	89.5%	292	12	95.9%	18	4	77.8%	291	37	87.3%

Amtrak On Time Performance

Trains Arriving Through: 7/20/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
371		19	0	100.0%	292	4	98.6%	19	3	84.2%	292	28	90.4%
380		20	1	95.0%	290	11	96.2%	20	1	95.0%	290	27	90.7%
381		20	2	90.0%	290	8	97.2%	20	6	70.0%	289	29	90.0%
382		20	1	95.0%	289	11	96.2%	20	5	75.0%	289	38	86.9%
383		20	0	100.0%	291	29	90.0%	20	8	60.0%	290	67	76.9%
390		20	3	85.0%	288	13	95.5%	20	7	65.0%	286	43	85.0%
391	Cncld	20	1	95.0%	291	7	97.6%	19	4	78.9%	288	53	81.6%
393		20	1	95.0%	290	13	95.5%	20	8	60.0%	287	41	85.7%
405		5	0	100.0%	89	1	98.9%	5	0	100.0%	89	1	98.9%
409		2	0	100.0%	42	1	97.6%	2	0	100.0%	42	2	95.2%
450		5	2	60.0%	89	10	88.8%	5	1	80.0%	89	12	86.5%
460	25	5	1	80.0%	91	18	80.2%	5	1	80.0%	89	31	65.2%
461		7	0	100.0%	91	5	94.5%	7	0	100.0%	91	3	96.7%
464	79	5	1	80.0%	89	4	95.5%	4	1	75.0%	87	30	65.5%
465	Cncld	2	1	50.0%	41	1	97.6%	1	1	0.0%	40	1	97.5%
488		7	2	71.4%	91	9	90.1%	7	2	71.4%	89	15	83.1%
497	33	2	0	100.0%	41	0	100.0%	2	2	0.0%	41	7	82.9%
499		7	1	85.7%	89	15	83.1%	7	1	85.7%	89	10	88.8%
500		20	1	95.0%	282	22	92.2%	19	4	78.9%	280	82	70.7%
502		20	0	100.0%	280	13	95.4%	19	1	94.7%	278	79	71.6%
503		20	1	95.0%	293	30	89.8%	20	7	65.0%	282	88	68.8%
504		20	0	100.0%	281	9	96.8%	19	4	78.9%	280	111	60.4%
505		20	2	90.0%	285	33	88.4%	19	5	73.7%	282	102	63.8%
506		20	3	85.0%	285	27	90.5%	19	5	73.7%	283	71	74.9%
507	52	20	3	85.0%	284	33	88.4%	20	9	55.0%	283	89	68.6%
508		20	0	100.0%	288	13	95.5%	20	6	70.0%	286	84	70.6%
509		20	3	85.0%	283	31	89.0%	19	6	68.4%	282	100	64.5%
511		20	1	95.0%	284	23	91.9%	20	4	80.0%	281	76	73.0%
516		20	2	90.0%	284	26	90.8%	20	10	50.0%	282	128	54.6%
517	27	20	0	100.0%	285	5	98.2%	20	8	60.0%	284	171	39.8%
518		20	3	85.0%	285	32	88.8%	20	9	55.0%	283	170	39.9%
519		20	0	100.0%	282	11	96.1%	20	4	80.0%	281	59	79.0%
562	Cncld	20	2	90.0%	289	33	88.6%	19	1	94.7%	279	31	88.9%
564	77	20	3	85.0%	287	20	93.0%	20	3	85.0%	284	27	90.5%
566	32	20	0	100.0%	112	10	91.1%	20	1	95.0%	112	12	89.3%
572		20	2	90.0%	242	21	91.3%	20	6	70.0%	238	44	81.5%
573	37	20	1	95.0%	281	38	86.5%	20	2	90.0%	275	45	83.6%
577		20	0	100.0%	35	0	100.0%	20	2	90.0%	35	2	94.3%
580		20	0	100.0%	289	21	92.7%	20	1	95.0%	288	53	81.6%
581	39	20	3	85.0%	289	36	87.5%	20	5	75.0%	285	56	80.4%
582		20	1	95.0%	35	1	97.1%	20	2	90.0%	35	3	91.4%
586		20	1	95.0%	240	30	87.5%	20	3	85.0%	233	41	82.4%

Amtrak On Time Performance

Trains Arriving Through: 7/20/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
587		20	3	85.0%	240	28	88.3%	19	5	73.7%	233	51	78.1%
591		20	0	100.0%	289	32	88.9%	20	2	90.0%	285	40	86.0%
593		20	4	80.0%	35	6	82.9%	20	4	80.0%	35	7	80.0%
595		20	3	85.0%	281	61	78.3%	20	2	90.0%	279	50	82.1%
610		4	0	100.0%	48	2	95.8%	4	0	100.0%	48	12	75.0%
612		3	1	66.7%	42	2	95.2%	3	1	66.7%	42	3	92.9%
615		3	0	100.0%	43	3	93.0%	3	0	100.0%	42	10	76.2%
660		7	1	85.7%	91	3	96.7%	7	0	100.0%	90	21	76.7%
661		7	1	85.7%	91	9	90.1%	7	1	85.7%	91	18	80.2%
663		7	1	85.7%	91	17	81.3%	7	0	100.0%	90	15	83.3%
664	29	7	1	85.7%	91	5	94.5%	7	1	85.7%	90	17	81.1%
665		7	0	100.0%	91	2	97.8%	7	0	100.0%	90	14	84.4%
666		7	0	100.0%	91	3	96.7%	7	0	100.0%	90	11	87.8%
667		7	0	100.0%	91	6	93.4%	7	0	100.0%	91	16	82.4%
669		7	0	100.0%	91	5	94.5%	7	0	100.0%	91	23	74.7%
670		7	0	100.0%	91	7	92.3%	7	0	100.0%	91	25	72.5%
671		7	1	85.7%	91	4	95.6%	7	0	100.0%	91	9	90.1%
672	19	7	0	100.0%	91	2	97.8%	7	1	85.7%	91	19	79.1%
690		6	0	100.0%	87	0	100.0%	5	1	80.0%	85	12	85.9%
691		6	2	66.7%	86	8	90.7%	6	4	33.3%	86	28	67.4%
692		6	0	100.0%	89	2	97.8%	6	1	83.3%	89	37	58.4%
693		6	1	83.3%	75	2	97.3%	6	4	33.3%	75	26	65.3%
694		6	1	83.3%	73	1	98.6%	6	3	50.0%	72	24	66.7%
695		6	0	100.0%	73	4	94.5%	6	1	83.3%	73	19	74.0%
696		6	2	66.7%	87	19	78.2%	6	4	33.3%	86	37	57.0%
697		6	3	50.0%	89	21	76.4%	6	3	50.0%	88	26	70.5%
698		6	0	100.0%	87	4	95.4%	6	1	83.3%	87	24	72.4%
702	48	20	2	90.0%	293	19	93.5%	20	13	35.0%	292	98	66.4%
703		20	2	90.0%	293	29	90.1%	20	8	60.0%	293	73	75.1%
710	34	20	7	65.0%	293	49	83.3%	19	13	31.6%	286	83	71.0%
711	42	20	0	100.0%	292	10	96.6%	20	9	55.0%	283	35	87.6%
712	18	20	3	85.0%	293	46	84.3%	19	12	36.8%	290	90	69.0%
713		19	0	100.0%	291	9	96.9%	17	12	29.4%	274	62	77.4%
714		20	5	75.0%	292	40	86.3%	20	10	50.0%	287	72	74.9%
715	25	20	3	85.0%	292	42	85.6%	19	14	26.3%	281	91	67.6%
716		20	5	75.0%	292	33	88.7%	19	6	68.4%	291	62	78.7%
717		19	3	84.2%	287	33	88.5%	17	6	64.7%	271	68	74.9%
718	20	20	6	70.0%	293	43	85.3%	19	4	78.9%	291	53	81.8%
719	20	20	6	70.0%	293	29	90.1%	20	11	45.0%	285	68	76.1%
720		7	3	57.1%	90	6	93.3%	7	1	85.7%	90	7	92.2%
723		7	0	100.0%	90	3	96.7%	7	0	100.0%	89	8	91.0%
724		7	0	100.0%	90	1	98.9%	7	0	100.0%	90	15	83.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/20/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
727		7	1	85.7%	90	4	95.6%	7	0	100.0%	90	21	76.7%
728		7	0	100.0%	90	3	96.7%	7	0	100.0%	90	9	90.0%
729		7	0	100.0%	90	7	92.2%	7	2	71.4%	90	24	73.3%
732		7	0	100.0%	90	5	94.4%	6	0	100.0%	88	10	88.6%
733		7	0	100.0%	90	6	93.3%	6	1	83.3%	86	10	88.4%
734		7	1	85.7%	90	3	96.7%	6	1	83.3%	88	4	95.5%
736		7	0	100.0%	90	7	92.2%	7	1	85.7%	90	22	75.6%
737		7	0	100.0%	90	3	96.7%	7	0	100.0%	90	9	90.0%
738		7	2	71.4%	90	7	92.2%	6	0	100.0%	87	5	94.3%
741		7	0	100.0%	90	2	97.8%	6	0	100.0%	88	12	86.4%
742		7	0	100.0%	90	5	94.4%	7	1	85.7%	89	16	82.0%
743		7	0	100.0%	90	6	93.3%	6	0	100.0%	89	15	83.1%
744		7	1	85.7%	90	4	95.6%	6	0	100.0%	89	8	91.0%
745		7	0	100.0%	90	1	98.9%	6	1	83.3%	88	4	95.5%
746	11	7	1	85.7%	89	3	96.6%	6	1	83.3%	88	6	93.2%
747		7	2	71.4%	90	2	97.8%	6	0	100.0%	89	10	88.8%
748		7	1	85.7%	90	5	94.4%	6	0	100.0%	88	10	88.6%
749		7	2	71.4%	90	7	92.2%	6	0	100.0%	84	3	96.4%
751		7	4	42.9%	89	7	92.1%	6	1	83.3%	87	7	92.0%
761		20	1	95.0%	289	18	93.8%	20	2	90.0%	289	35	87.9%
765	33	20	1	95.0%	289	13	95.5%	20	2	90.0%	280	41	85.4%
769	107	20	0	100.0%	287	11	96.2%	20	2	90.0%	283	52	81.6%
770	41	20	0	100.0%	289	17	94.1%	20	6	70.0%	286	40	86.0%
774		20	0	100.0%	289	8	97.2%	20	3	85.0%	285	65	77.2%
779		20	0	100.0%	35	1	97.1%	20	3	85.0%	35	7	80.0%
784	23	20	1	95.0%	289	33	88.6%	20	11	45.0%	286	116	59.4%
785		20	2	90.0%	289	15	94.8%	20	1	95.0%	287	44	84.7%
790	32	20	2	90.0%	289	16	94.5%	20	2	90.0%	286	43	85.0%
794	Cncld	20	0	100.0%	289	22	92.4%	19	1	94.7%	287	58	79.8%
821	30	17	0	100.0%	288	6	97.9%	17	15	11.8%	288	149	48.3%
822	61	19	2	89.5%	290	13	95.5%	19	19	0.0%	290	150	48.3%
1233	111	3	1	66.7%	5	1	80.0%	3	2	33.3%	5	3	40.0%
1246		3	0	100.0%	5	0	100.0%	3	1	66.7%	5	1	80.0%
1333	47	20	2	90.0%	286	52	81.8%	20	18	10.0%	285	184	35.4%
1340		20	2	90.0%	285	14	95.1%	20	15	25.0%	283	98	65.4%
1689	37	12	0	100.0%	72	0	100.0%	13	3	76.9%	72	16	77.8%
2205		7	0	100.0%	89	2	97.8%	7	1	85.7%	88	10	88.6%
2222	42	3	0	100.0%	40	5	87.5%	3	1	66.7%	40	8	80.0%
2224	77	3	0	100.0%	42	4	90.5%	3	1	66.7%	42	6	85.7%
2226	22	3	1	66.7%	42	8	81.0%	3	1	66.7%	41	7	82.9%
2247		3	0	100.0%	42	5	88.1%	3	0	100.0%	41	9	78.0%
2248		7	0	100.0%	90	3	96.7%	7	0	100.0%	89	12	86.5%

Amtrak On Time Performance

Trains Arriving Through: 7/20/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
Train	Late												
2250	Cncld	7	0	100.0%	89	7	92.1%	6	1	83.3%	87	20	77.0%
2252	130	7	2	71.4%	89	12	86.5%	7	2	71.4%	87	22	74.7%
2253	70	7	1	85.7%	91	9	90.1%	7	5	28.6%	89	43	51.7%
2254	25	7	1	85.7%	90	10	88.9%	7	1	85.7%	89	16	82.0%
2255		7	0	100.0%	87	4	95.4%	7	1	85.7%	86	22	74.4%
2257		3	1	66.7%	42	6	85.7%	3	1	66.7%	39	10	74.4%
2258		3	0	100.0%	42	5	88.1%	3	0	100.0%	42	12	71.4%
2259		3	1	66.7%	42	5	88.1%	3	1	66.7%	41	13	68.3%
2262		3	0	100.0%	42	3	92.9%	3	0	100.0%	42	6	85.7%
2263	15	3	0	100.0%	42	1	97.6%	3	1	66.7%	42	8	81.0%
2265		3	0	100.0%	42	1	97.6%	3	1	66.7%	42	10	76.2%
2271	29	3	0	100.0%	42	0	100.0%	3	2	33.3%	42	14	66.7%
2275	Cncld	3	2	33.3%	41	8	80.5%	2	1	50.0%	39	13	66.7%
2290		3	0	100.0%	42	3	92.9%	3	0	100.0%	42	4	90.5%
2292		3	1	66.7%	42	1	97.6%	3	0	100.0%	42	3	92.9%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2222	NYP	42	ENG	29	ENG	29	XNY-BWI	AM	Air / Brake, 2010, 2222 stopped at mp 131 on 2trk with locked up brakes.
2224	NYP	77	SMW	11	PTI	7	BAL-XPV	AM	Follow, 166, Control Point, .
2226	NYP	22	ITI	30	ITI	30	WAS-WAS	AM	Service, turn, or wye train, 2247, short turn of equipment off 2247
2250	BOS	Trn Cancelled	CAR	147	CAR	136	NWK-NYP	AM	Air / Brake / Wheel, CONSITS, DISABLED LINE 1 STUCK HAND BRAKE ON ALL CARS
2252	BOS	130	ENG	107	ENG	64	XCY-NWK	AM	Unrecoverable penalty (PCS), PC2022
2253	WAS	70	ENG	34	ENG	34	NYP-NYP	AM	Other electrical failure, AM2252, EQUIPMENT SWAPP DUE TO AM2252 EAST OUT PC CAB ISSUES
2254	BOS	25	PTI	22	HLD	13	NYP-NYP	AM	Passenger and/or baggage, HELD FOR PSGRS OFF AM2250
2263	WAS	15	DSR	15	PTI	13	BAL-XNY	AM	Follow, 195, Control Point, .
2271	WAS	29	SMW	22	SMW	11	XSH-NYP	AM	Scheduled in track usage program, Other, LINE 2 O/O/S
2275	XHM	Trn Cancelled							
88	BOS	30	ADA	20	WTR	14	PTB-RVR	CS	Flash flood warning Control Point, Petersburg
99	NPN	154	CAR	144	CAR	138	BOS-BOS	AM	Door, 82571, DOOR ISSUES, REMOVED AND SWAPPED EQUIPMENT
107	WAS	25	ENG	18	ENG	18	NYP-NYP	AM	Other electrical failure, 654, SPEED SENSOR FAULT, TRAIN WYE, DOORS CUT OUT MECHANICAL ONBOARD
118	NYP	89	SYS	53	SYS	53	WAS-WAS	AM	Conductor working alone/crew shortage., yard crew shortages from previous shift and current shortages of yard crews contributed to a delay in servicing and inspecting equipment for the next day's service
135	WAS	24	DSR	15	MTI	15	TRE-XHM	AM	Disabled train ahead, Other, TRE , AM97 STOPPED NO.3 TRACKM MP68.3 ACUATED DRAGGER
146	SPG	23	SMW	18	SVS	11	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Engine swap
153	NFK	34	PTI	21	PTI	21	RVR-PTB	CS	Wait for station track p090, Control Point, Petersburg

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
154	BOS	103	SYS	43	SYS	43	WAS-WAS	AM	Conductor working alone/crew shortage., yard crew shortages from previous shift and current shortages of yard crews contributed to a delay in servicing and inspecting equipment for the next day's service
156	NYP	23	PTI	23	PTI	7	RNK-LYH	NS	Wait for station track Amtk 20, Control Point, Montview
161	WAS	20	HLD	14	MTI	12	NYP-NYP	AM	Disabled train ahead, Other, TRACK CHANGE A/C AM2250 DISABLED
162	BOS	44	CAR	37	CAR	37	WAS-WAS	AM	Door, 43347, center door inoperable shopped
164	BOS	66	MTI	54	MTI	54	NYP-NYP	AM	Disabled train ahead, Other, LINE 1, AM2250 DISABLED MADE REVERSE MOVE
189	WAS	53	ITI	35	ITI	35	NYP-NYP	AM	Service, turn, or wye train, 118
195	RVM	50	CTI	25	DCS	16	BRP-STM	MN	Restrictive signal(s) from unknown cause Stop Signal, Control Point, 235
460	SPG	25	SVS	25	SVS	25	NHV-NHV	AM	Water, commissary, toilet/trash dumping, DP NHV late a/c late servicing in the yard
464	SPG	79	CON	71	CON	71	NHV-NHV	AM	Hold for connecting train, Held for missed conx of AM164
465	NHV	Tn Cancelled							
497	NHV	33	PTI	24	PTI	24	SPG-WNL	AM	Meet, AM140, Milepost w/Letters, XF3, XF3, Held at Field for AM140 to clear.
52	LOR	41	WTR	44	ENG	28	XDD-XPX	CS	Undesired emergency application 358
664	NYP	29	PTI	18	PTI	12	NWK-NYP	AM	Meet, AM2250, Other, NWK, AM2250 AHEAD WITH DOOR ISSUES
672	NYP	19	DCS	27	DCS	27	PHL-XHM	AM	Power switch failure, Control Point, ., 32sw fails to normal at Holmes
20	NYP	35	HLD	43	HLD	24	ATL-ATL	NS	Passenger and/or baggage Had to wait on station services with special services. With one golf cart to service the train.
1689	BRK	37	POL	47	POL	39	SAO-ORB	CS	Right of Way police hold More Trespassers
63	TWO	36	HLD	20	CTI	15	CRT-POU	MN	Follow mn, Control Point, 56
245	ALB	20	PTI	23	PTI	23	NYP-NYP	AM	Cross over or go around, AM68, Other, NYP-NYP, HELD TO WAIT FOR AM68 COME INTO THE STATION.
280	NYP	27	DMW	30	DMW	30	POU-CRT	MN	Held for or routed around MW work or equipment Milepost, 56.1, 56.4

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
283	NFL	26	FTI	40	FTI	25	AMS-UCA	CS	Meet m, Control Point, 225
290	NYP	43	DSR	35	DMW	27	BTN-BTN	VR	Held for or routed around MW work or equipment Other, North Ferrisburg
291	BTN	28	DSR	24	DSR	17	VRN-BTN	VR	Per bulletin Other, VRN- mp100.63, 15, main, Other, mp 102.36, 25, main, Milepost, 105.19, 105.68, 15, main, Milepost, 105.68, 107.91, 25, main, Milepost, 107.91, 109.30, 25, main, Milepost, 109.30, 111.0, 25, main, Milepost, 111.0, 113.30, 10, main
1233	ALB	111	ENG	92	ENG	92	NYP-NYP	AM	Other electrical failure, 9700, MECHANICAL ISSUES
42	NYP	38	DCS	28	DCS	28	LAB-JST	NS	Slide fence restriction due to false actuation or out of service Started to slow down with an approach at mp 307 came to restricting at mp 303 to stop at mp 301 ... received permission past CP Pack to continue restricting speed on main 2 east past the Torrance slide fence at mp 298.0, Milepost, 298.0,
98	NYP	130	WTR	92	CAR	29	MIA-MIA	FL	HEP 82757, 61012, 62507, Mechanical walked train looking for HEP cable problem, short looped fireman side between 61012 and 82757. Found another cable problem fireman side between 62507 and 61012 which they tighten HEP end with zip ties
54	SAB	113	DMW	49	DMW	42	BRA-BRA	NE	Waiting for MW clearance Milepost, 122, 152
40	WAS	34	HLD	33	WTR	16	PTB-RVR	CS	Flash flood warning Other, PTB, Other, Rich term
6	CHI	377	FTI	516	FTI	350	XMS-WNN	UP	Blocked from station track UP 8563, Milepost, 416, 417
746	SAC	11	MBO	25	MBO	25	MTZ-SUI	UP	For maritime traffic Control Point, Vista
50	NYP	59	WTR	38	WTR	24	XJD-STA	BB	Heat order Control Point, JD-STA
507	EUG	52	FTI	62	FTI	61	TAC-XNI	ST	Meet switch job, BN 193, Control Point, Rill
517	PDX	27	MBO	12	DCS	11	TAC-XNI	ST	Issue with automatic road crossing protection Box 1. Lakewood Sub, Milepost, 4.29, 4.29
58	CHI	63	DSR	75	DMW	58	HAZ-JAN	CC	Waiting for MW clearance Milepost, 739.1, 739
59	NOL	118	DCS	159	DCS	159	HMD-XSU	CC	Restrictive signal(s) from unknown cause Signal issues on UP at East Bridge jct . Being held at Orleans jct on main 1 due to the signal issues and congestion, Stop, Control Point, Orleans jct

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/20/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
11	LAX	No OS Rpt	SVS	70	SVS	70	SLO-SBA	UP	Routine inspections Daily inspection conducted at Goleta Station, Other, Goleta Station	
821	FTW	30	RTE	31	RTE	31	GLE-FTW	BN	Run via siding or slower track due to N.A.R. Siding, Justin, Other, Alliance	
822	OKC	61	DSR	60	DSR	25	FTW-GLE	BN	Per bulletin Milepost, 346.7, 347, 25, m1, Milepost, 353.6, 353.8, 40, m2, Milepost, 354, 354.1, 35, m2, Milepost, 354.2, 354.4, 40, m2, Milepost, 355.6, 355.8, 40, m2, Milepost, 358.4, 358.5, 30, m1, Milepost, 364.6, 364.8, 30, m1, Milepost, 365.3, 365.4, 60, m1, Milepost, 370.5, 370.7, 30, m, Mile	
350	PNT	22	PTI	29	PTI	21	XB0-XA5	MI	Meet 353, Siding, Albion	
562	SAN	Trn Cancelled								
564	SAN	77	FTI	49	FTI	42	OSD-OSD	SN	Held due to BNSF freight blocking track at Mira Mar Bnsf, Control Point, Mira Mar	
566	SAN	32	PTI	31	PTI	14	SOL-OLT	SN	Follow 564, Milepost, 241, 252	
573	LAX	37	SYS	35	SYS	35	SAN-SAN	SN	Other late crew Due to disabled freight train BNSF 6940, Other, SAN	
581	LAX	39	CTI	26	CTI	24	OSD-X98	SC	Meet metrolink, Control Point, songs	
765	GTA	33	CON	48	CON	48	SOL-SOL	SN	Hold for thruway bus	
769	GTA	107	FTI	100	FTI	100	OLT-OLT	SN	Hold due to BNSF southbound manifest break apart (knuckle) on hill (Miramar). BNSF, Other, Old Town Sta	
770	SAN	41	SVS	35	SVS	35	LAX-LAX	SC	Pick up equipment The usual glitches that occur when adding the block on opening weekend of Delmar, including air test problems, loading issues, etc., Other, LAX	
784	SAN	23	PTI	35	PTI	23	VEC-OXN	UP	Meet 769, Control Point, north ventura	
790	SOL	32	ITI	75	ITI	75	GTA-GTA	UP	Service, turn, or wye train 769, The fuel truck arrived at 16:55.	
794	SAN	Trn Cancelled	HLD	10	HLD	8	SBA-SBA	UP	High passenger count	
702	BFD	48	PTI	33	FTI	29	XEC-LOD	UP	Pick up / drop off freight crew Per dispatcher, assisted UP 8347 conductor, giving him a ride, as needed., UP 8347, Control Point, N Need	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/20/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
710	BFD	34	PTI	29	SVS	28	OKJ-OKJ	UP	Routine inspections Delayed at OMF due to normal servicing. Crews also attending to train 6 and train 720., Other, Oakland Maintenance Facility	
711	OKJ	42	TRS	51	TRS	51	BFD-WAC	BN	Vehicle on track ahead Stopped at una cover for vehicle blocking tracks ahead. Multiple freights needing re-crew ahead., Control Point, west shafter	
712	BFD	18	PTI	14	PTI	14	MOD-TRK	BN	Meet 713, Other, turlock station	
715	OKJ	25	DSR	28	DSR	17	SKN-ACA	BN	Per bulletin Milepost, 1129.4, 1133.4, 15, MT1	
718	BFD	20	PTI	25	PTI	11	ACA-SKN	BN	Cross over or go around 717, Siding, orwood	
719	OKJ	20	CON	18	CON	18	BFD-BFD	BN	Hold for thruway bus	
3	LAX	126	FTI	86	SVS	30	ABQ-ABQ	NM	Routine inspections	
4	CHI	121	DSR	89	SYS	39	LAX-LAX	SC	PTC problem or failure (cause unknown) Unable to sync up address reset breaker, Milepost, 0.0, 0.0	
22	CHI	32	SVS	79	SVS	70	STL-STL	TR	Water, commissary, toilet/trash dumping Crew sign up @8:30a	
300	CHI	22	ENG	25	WTR	11	DWT-JOL	UP	Severe storm causing xing issues. Issue with automatic road crossing protection Milepost, 53.41, 53.41, Milepost, 42.47, 42.47, Milepost, 41.44, 41.44, Other, .	
307	STL	137	ENG	91	ENG	89	CHI-CHI	AM	Set out defective locomotive switch out the 4630 for the 4623, ID4623	
391	CDL	Trn Cancelled								
1333	MSP	47	DSR	26	MBO	14	RDW-XH8	CP	For maritime traffic Bridge, switch	

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/20/2025

Terminal	Train	Date	Late	Delay	Cause
RGH	73	07/20	4	4	Mobility Impaired Late arriving ADA pax.
WAS	41	07/19	4	4	Passenger and/or baggage, still loading at departure per CNDR
WAS	118	07/20	53	53	Conductor working alone/crew shortage., yard crew shortages from previous shift and current shortages of yard crews contributed to a delay in servicing and inspecting equipment for the next day's service
WAS	154	07/20	43	43	Conductor working alone/crew shortage., yard crew shortages from previous shift and current shortages of yard crews contributed to a delay in servicing and inspecting equipment for the next day's service
WAS	162	07/20	37	37	Door, 43347, center door inoperable shopped
WAS	2226	07/20	30	30	Service, turn, or wye train, 2247, short turn of equipment off 2247
BOS	67	07/20	17	17	Injured or sick passenger, AM67 dp BOS late due to a medical emergency with a psgr
BOS	87	07/20	36	36	Blocked by or assisting another, disabled Amtrak train, HELD IN YARD ACCOUNT 99 HAVING DOOR ISSUES AND 149 BEING CLEANED PLUS SWAPPED FOR 99 EQUIPMENT
BOS	99	07/20	138	138	Door, 82571, DOOR ISSUES, REMOVED AND SWAPPED EQUIPMENT
BOS	169	07/20	33	33	Other late crew, Crew on late from AM2226
BOS	2253	07/20	16	16	Blocked by or assisting another, disabled Amtrak train, CONGESTION IN YARD DUE TO TRAIN 99 CAR ISSUES/SWAP
BOS	2275	07/20	(Trn Cxld)		Engine Failure
BTN	290	07/20	27	27	Held for or routed around MW work or equipment Other, North Ferrisburg
NHV	450	07/20	9	9	Service, turn, or wye train, 405, SHORT TURN
NHV	460	07/20	25	25	Water, commissary, toilet/trash dumping, DP NHV late a/c late servicing in the yard
NYP	49	07/20	213	213	Other electrical failure, 706/96/94, DLYD DUE TO LATE RELEASE FROM THE YARD MECHANICAL HAD TO INSPECT EQUIPMENT TRAIN PARTED
NYP	63	07/20	5	5	High passenger count
NYP	97	07/20	195	195	Service, turn, or wye train, 98, Car 62519 was shopped for HVac issues REPLACEMENT OFF AM98 AND ENG 639
NYP	107	07/20	16	18	Other electrical failure, 654, SPEED SENSOR FAULT, TRAIN WYE, DOORS CUT OUT MECHANICAL ONBOARD
NYP	189	07/20	33	35	Service, turn, or wye train, 118
NYP	283	07/20	18	18	Disabled train ahead, Other, LINE 1, AM2250 DISABLED
NYP	291	07/20	12	12	Service, turn, or wye train, 240
NYP	663	07/20	10	10	Door, CONSITS, DELAYED SSYD A/C POSITIVE STOP PENALTY ISSUES, AND DOOR ISSUES

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/20/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	1233	07/20	92	92	Other electrical failure, 9700, MECHANICAL ISSUES
NYP	2292	07/20	5	6	Door, CONSITS
SPG	465	07/20	(Trn Cxld)		Engine Failure
CHI	5	07/20	477	55	Crew rest Engineer needing 4hr cut
CHI	5	07/20	477	422	Air / Brake / Wheel 31028, Brakes would not set on this car
CHI	7	07/20	42	42	Brake indicator light issue in the yard 33006
CHI	391	07/20	(Trn Cxld)		Engine Failure
KCY	318	07/20	12	12	AMTK4 had to block Gand Ave Signal to load it Passengers. Therefore we couldn't depart Amtk4, Control Point, Grand Ave
STL	302	07/20	28	28	Electrical failure ID4020, ID4116, Comm cable was bad between the cars, lost communication with the engine, engine was unable to load due to door indicator saying open., .
BFD	719	07/20	18	18	Hold for thruway bus
EMY	6	07/20	5		
GTA	790	07/20	75	75	Service, turn, or wye train 769, The fuel truck arrived at 16:55.
LAX	2	07/20	(No OS)		
LAX	14	07/20	24	24	Service, turn, or wye train 3
LAX	562	07/20	(Trn Cxld)		freight mech issues
LAX	582	07/20	10	8	Late bulletins due to Amtrak cause T&E Awaiting GTBs from Metrolink dispatcher for train 593
LAX	582	07/20	10	2	Door C6852
OKJ	710	07/20	28	28	Routine inspections Delayed at OMF due to normal servicing. Crews also attending to train 6 and train 720., Other, Oakland Maintenance Facility
OKJ	714	07/20	5	5	Restrictive signal(s) from unknown cause Erroneous indication at Dr. King, stop, Control Point, north jack london
OKJ	720	07/20	9	9	Blue flags were not dropped till 7am due to load test and air test still having to be done
OKJ	738	07/20	10	10	WAIT FOR BLUE FLAG TO DROP AND ATTAIN PROPER PAPERWORK FROM MECHANICAL C2003
SAN	573	07/20	35	35	Other late crew Due to disabled freight train BNSF 6940, Other, SAN
SAN	581	07/20	16	7	Service, turn, or wye train 770
SAN	581	07/20	16	9	Door 6303, Could not get train line. CNOC mechanical gave us permission to run with doors in override
SAN	761	07/20	(Trn Cxld)		freight mech issues

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/20/2025

Terminal	Train	Date	Late	Delay	Cause
SAN	765	07/20	(Trn Cxld)		freight mech issues

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.8	98.8	95.2	167	2
CDOT	95.0	100.0	100.0	96.4	16	0
MARC	95.0	83.3	77.2	83.5	12	2
SEPTA	95.0	93.6	96.0	96.2	109	7
NJT-NED	95.0	No Data	No Data	95.2	No Data	No Data
NJT-SED	95.0	87.5	97.7	91.2	24	3

Operating Highlights

Train 49(20) - East of Rochester, NY - Trespasser Strike

21JUL25: 2:37am Train 49(20) with E/88 and E/111 plus 11 cars, carrying 138 passengers struck a trespasser near MP 361.4 on the CSX Rochester Subdivision. There were no reported injuries to crew or passengers. The trespasser was a confirmed fatality. There was no reported damage to the equipment. HEP was maintained throughout. The weather at the time of incident was 66° with periodic clouds. This incident occurred in the City of Fairport, Monroe County, NY and did not occur at a grade crossing. Monroe County Sheriff's Department and Fairport Police responded to the scene. Amtrak Police Detective Smith was advised. Train 49(20) was released from the scene at 3:54am.

New York State notified 3:12am.

National Response Center Number: 1437486

Train	Delay	Comment
49(20)	2'16"	

South of Philadelphia, PA - PW Line - Police Hold All Tracks

21JUL25: Local Police Requested a hold on all tracks between PHIL/MP 3.6 and BALDWIN/MP 11.7 due to an investigation/pursuit on or near the right of way. Amtrak assisted local police.

Train	Delay	Comment
139(20)	34"	
128(20)	33"	

Train 97(20) - Philadelphia, PA - Car Failure

20JUL25: Upon arrival at 30th Street Station/MP 1.4 on the Amtrak PW Line in Philadelphia, Train 97(20) incurred substantial delay. Sleeper Car 62008 was inspected by Mechanical Personnel and it was discovered to have a cracked wheel. The car was removed from the consist with the assistance of the yard crew. Passengers on Train 97(20) who were ticketed for Baltimore and Washington, DC were transferred to Train 139(20).

Train	Delay	Comment
97(20)	2'54"	
139(20)	10"	

Train 97(20) - East of Philadelphia, PA - Recrew

20JUL25: Train 97(20) was delayed on the Amtrak New York to Philadelphia Line at MP 77.1 due to a combination of issues; The No. 32 Switch at Holmes interlocking failed. The train was not shoved back due to the crew being close to the limits of their hours of service. The train was held at Holmesburg Junction for a recrew.

Train	Delay	Comment
97(20)	1'25"	

Train 169(20) - Boston, MA - Initial Terminal Delay

20JUL25: Train 169(20) was delayed at its initial terminal at Boston South Station due to holding for its crew, which arrived on late running Train 2226(20).

Train	Delay	Comment
169(20)	33"	

Train 2222(20) - South of Baltimore, MD - Engine Failure

20JUL25: Train 2222(20) was delayed at MP 121.0 on the Amtrak Philadelphia top Washington Line due to a brake malfunction. The Engineer reported the brakes being applied and unable to release. The crew bypassed the onboard trainline to resolve the issue.

Train	Delay	Comment
2222(20)	35"	
80(20)	20"	
166(20)	18"	

Train 49(20) New York, NY - Servicing

20JUL25: Train 49(20) was delayed departing New York due to late released from the yard due to servicing. Train 49(20) was further delayed due to holding for mechanical personnel to inspect the baggage car for a possible coupler break they were coming over from the yard on train 97(20) that was released at 455P-ET.

Train	Delay	Comment
49(20)	3'33"	

Train 97(20) New York, NY - Servicing

20JUL25: Train 97(20) was delayed departing New York due to the late turn off 98(19) that arrived at 130P-ET 2 hours and 10 minutes late.

WBS#: B.TR.100151.0761

Train	Delay	Comment
97(20)	3'15"	

Train 464(20) New Haven, CT - Hold for Connection

20JUL25: Train 464(20) was held in New Haven due to holding for late connections off 164(20).

Train	Delay	Comment
464(20)	1'11"	

Train 2252(20) West of Newark Liberty Airport, NJ - Engine Failure

20JUL25: Train 2252(20) with set 17 PC/2022 and PC/2011 was disabled on the New York to Philadelphia main line at MP 11.3/Haynes with an unrecoverable brake application. There were 290 passengers onboard and the train was able to maintain HEP.

UPDATE: Train 2252(20) was able to recover but was running with cab signal failure. They were disabled for the second time an Amtrak Road Foreman was onboard and they proceeded into New York. Due to the on going issues with set 17 trains 2252(20) and 2253(20) swapped sets in New York after mechanical checked out both sets of equipment.

Train	Delay	Comment
2252(20)	1'04"	
2252(20)	43"	swapping sets NYP
2253(20)	1'04"	swapping sets NYP
118(20)	15"	
154(20)	17"	

Train 2250(20) BWI Marshall Airport, MD - Engine Failure

20JUL25: Train 2250(20) was delayed on the Philadelphia to Washington main line due to having multiple parking brake faults in the PC/2023. They were further delayed at Newark station the Philadelphia to New York main line with door issues. They were further delayed in New York per the request of the crew for mechanical to look at the equipment. Mechanical released the train and they had the same parking brake fault at JO interlocking just prior to the tunnel. It was decided to have them switch ends and bring the equipment back into the station. There was 264 passengers onboard. Train 2250(20) was terminated in New York.

UPDATE: New York reported that they are unable to operate from PC/ 2011 due to parking brake faults. Recue engine was enroute, Road Forman walking over to the train, High Speed Rail Mechanical. Trains departing New York will see 20-30 minutes delays due to the line 2 outage. Train 2250(20) that was disabled line 1 at JO interlocking the rescue engine was coupling to bring set back into the station and a code 500 was initiated at 3P-ET. There were no passenger issues reported at the time. As of 327P-ET train 2250(20) was back in the station and no passengers issues were reported. The code 500 was cancelled.

Train 2275(20) was cancelled in its entirety between Boston, MA and Washington, DC due to shopped equipment.

Train	Delay	Comment
2250(20)	11"	nwk door issues
2250(20)	51"	parking brake issues
2250(20)	TERM NYP	
2275(20)	CANCELLED	
2250(20)	2'16"	
283(20)	18"	
164(20)	54"	
161(20)	12"	
2162(21)	Cancelled	
2193(21)	Cancelled	

Train 1233(20) New York, NY - Cab Car Failure

20JUL25: Train 1233(20) was delayed departing New York due to having mechanical issues with CC/9700 in the station. Mechanical was working on fixing the issue.

Train	Delay	Comment
1233(20)	1'32"	

CSX Heat Orders - Northeast and Southeast Regions

20JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Charleston for 70 miles, Jacksonville Terminal, Nahunta, Sanford, Savannah, and South End.

Train	Delay	Comment
89 (20)	23"	
98 (20)	27"	
52 (20)	13"	
79 (20)	13"	
90 (20)	07"	

Washington, DC - Servicing

20JUL25: Several trains were delayed departing Washington due to overnight short staffing which caused delays of trains being released from the S&I.

Train	Delay	Comment
66 (19)	28"	
118 (20)	53"	
154 (20)	43"	
189 (20)	33"	LATE TURN OFF 118 (20)

Train 99(20) Boston, MA -Door Issues / Car Failure

20JUL25: Train 99(20) was delayed departing Boston due to having door issues in the S&I. It was determined to move train 149(20) up for 99(20) but it still needed to be cleaned and serviced.

Train 149(20) had to shop C/82571 for door issues and this had the train departing oversold.

Train 87(20) was delayed due to late release from the yard.

Train	Delay	Comment
87 (20)	36"	
99 (20)	2'18"	

NS PTC Outage - System

20JUL25: Several Trains were delayed due to NS Systemwide PTC Outage. Trains were unable to initialize PTC and operated under block protection at a reduced speed.

Train	Delay	Comment
48/448 (19)	56"	
49/449 (19)	19"	
19 (19)	1'08"	
20 (19)	21"	

Train 162(20) Washington, DC - Car Failure

20JUL25: Train 162(20) was delayed departing Washington due to shopping cafe car C/43347 and replacing with C/43366.

Train	Delay	Comment
162 (20)	37"	

Train 464(19) New Haven, CT - Engine Failure

19JUL25: Train 464(19) was cancelled in its entirety at New Haven, CT account E/93 bad ordered for wheels with no available replacement. Two alternate buses were secured. Bus #1 operated express making stations stops at New Haven, Hartford, and Springfield. Bus #2 made all station stops.

Due to this, the following trains were also adjusted/cancelled:

Train 400(20) canceled, no passengers affected. Train 461(20) canceled between Greenfield, MA and Springfield, MA with alternate bus transportation, train originated at SPG operating Springfield, MA to New Haven, CT.

UPDATE: Train 497(20) will operate normal between Springfield to New Haven. Trains 465(20) and 416(20) were both cancelled with alternate bus transportation between New Haven, CT to Springfield, MA.

WBS#: B.TR.100151.0760

Train	Delay	Comment
464(19)	Cancelled	W/ALT
497(20)	Cancelled	w/ALT
461(20)	Originates	SPG w/ALT
400(20)	Cancelled	

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 25JUL, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 26JUL, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 25, 26JUL, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 27JUL, 03AUG) will originate at Washington with no alternate transportation.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 195(20) Passenger Removal at New Haven, Connecticut - Refusal to Pay

20JUL25, Passenger on PNR unknown, traveling from Boston, MA to New Haven, CT was removed by Amtrak Police due to not having a ticket and not having the funds to purchase a ticket. Amtrak Police notified.

Delay: **195 (20)** **None**

Train 72(20) Passenger Removal at High Point, North Carolina – Improper Conduct

20JUL25, Passenger on PNR unknown, traveling from Charlotte, NC to Greensboro, NC was removed due to smoking in the restroom and using profanity. Amtrak Police notified.

Delay: **72 (20)** **None**

Train 97(19) Passenger Removal at Orlando, Florida – Improper Conduct

20JUL25, Passenger on PNR 19EBAB, traveling from Savannah, GA to West Palm Beach, FL was reportedly removed by local police due to being confrontational with crew. Amtrak Police notified.

Delay: 97 (20) None

Train 88(20) Passenger Removal at Providence, Rhode Island – Improper Conduct

20JUL25, Passenger on PNR 9C3C72, traveling from Bridgeport, CT to Boston (South), MA was removed by the local police at Providence, RI due to being unruly and disrupting the other passengers with his loud music and obscene language. Amtrak Police notified.

Delay: 88 (20) 08"

Western Region

Operating Highlights

Train 58(20) North of Marks, MS - Freight Train Interference

21JUL25: Train 58(20) was delayed at North Lake Cormorant/MP19.0 49 miles north of Mark, MS/MP67.3 on the CN Yazoo subdivision meeting freight CN/1011. Once the route was clear, train 58(20) proceeded north.

Train	Delay	Comment
58(20)	32"	

Train 58(20) South of Memphis, TN - Signal

21JUL25: Train 58(20) was delayed at the CN Junction/MP393.5 2 miles south of Memphis, TN/MP391.8 on the CN Memphis subdivision due to a signal issue. BNSF maintainers were on the scene attempting to make repairs. A recrew engineer signed on at Memphis, TN and boarded train 58(20) as the engineer expired on hours of service while waiting for a route through the switch. Once CN Railroad instructed BNSF to allow trains to walk across the switch due to mounting congestion, train 58(20) proceeded through the affected area and into Memphis Station, TN.

Train	Delay	Comment
58(20)	1'28"	

Train 4(19) East of Garden City, KS - Signal

21JUL25: Train 4(19) was delayed between Garden City, KS/MP389.4 and Ingalls, KS/MP371.7 beginning 13 miles east of Garden City Station, KS due to restrictive signals. Once through the affected area, train 4(19) continued east.

Train	Delay	Comment
4(19)	47"	

Train 307(20) East of St. Louis, MO - High Wind Warnings

21JUL25: Train 307(20) was delayed at WR Tower, IL/MP275.5 10 miles east of St Louis, MO/MP1.5 on the UP Springfield subdivision waiting for high wind warnings to expire. Once the route was clear, train 307(20) proceeded into St Louis Station, MO.

Train	Delay	Comment
307(20)	34"	

Train 507(20) Tacoma, WA - Freight Train Interference

20JUL25: Train 507(20) was delayed south of Tacoma, WA (TAC) at CP Rill on the Sound Transit Lakewood Subdivision. A freight train, BNSF/193, was having problems climbing the grade and was required to "double the hill" (split train in two, take first half over, then go and get second half). Once the freight train was clear of the single main track ahead, train 507(20) was able to proceed south.

Train	Delay	Comment
507(20)	1'01"	

Train 4(19) West of Raton, NM - High Wind Warnings

20JUL25: Train 4(19) was delayed between Las Vegas, NM/MP758.0 and Raton, NM/MP660.0 on the BNSF Raton subdivision due to high wind warnings that required operation at reduced speeds. Once through the affected area, train 4(19) proceeded into Raton Station, NM/MP659.3.

Train	Delay	Comment
4(19)	37"	

Train 3(19) Albuquerque, NM - Servicing

20JUL25: Train 3(19), with engines 188 and 83, 10 cars, and 205 passengers, was delayed departing Albuquerque Station, NM/MP902.5 on the NMRX Albuquerque subdivision due to completing a regular calendar day inspection. Once the inspection was complete, train 3(19) departed Albuquerque Station, NM heading west.

Train	Delay	Comment
3(19)	30"	

Train 1(19)/421(18) East of Deming, NM - Signal

20JUL25: Train 1(19)/421(18) was delayed in Vado, NM/MP1268.2 60 miles east of Deming, AZ/MP1208.1 on the UP Lordsburg subdivision due to a power switch failure at control point 1268/MP1268.0. Once through the affected area, train 1(19)/421(18) continued to Deming, AZ.

Train	Delay	Comment
1(19)/421(18)	46"	

Train 770(20) Los Angeles, CA - Servicing

20JUL25: Train 770(20) was delayed at Los Angeles, CA (LAX) on the Southern California Regional Rail Authority River Subdivision. To accommodate the Del Mar race season, the Del Mar Block (Extra set of cars and locomotive), were added to the train at LAX to accommodate increased ridership. This took longer than anticipated account unforeseen air problems with the equipment. Technicians from LAX Depot Mechanical were able to resolve the problem and train 770(20) departed LAX at 10:48 AM-PT.

Train	Delay	Comment
770(20)	35"	

Train 22(20) South of Fort Worth, TX - Freight Train Interference

20JUL25: Train 22(20) was delayed one mile south of Fort Worth on the BNSF Fort Worth subdivision due to meeting MBDFW-20 at Tower 55/MP 345.3.

Train	Delay	Comment
22(20)	30"	

Train 7/27(20) Chicago, IL - Initial Terminal Delay

20JUL25: Train 7/27(20) with E/306-50 and 10 cars was delayed departing Chicago due to a broken knuckle on C/31024, which delayed the train makeup and release. Additional delays were attributed to C/33006 with a brake indicator light issue. Once the equipment was released and boarded, 7/27(20) departed Chicago at 347PM-CT, 42 minutes late.

Train	Delay	Comment
7/27(20)	42"	

Train 58(20) North of New Orleans, LA - Signal

20JUL25: Train 58(20) was delayed six miles north of New Orleans on the CN McComb subdivision due to a track circuit with UPRR freight blocking the route at East Bridge Jct./MP 906.4. Train 59(19) was delayed for the same reason. 203PM-CT, an UPRR maintainer arrived on scene. 318PM-CT, train 58(20) was being talked through the effected area followed by train 59(19).

Train	Delay	Comment
58 (20)	2'15"	
59 (19)	2'39"	

Train 59(19) North of Hazlehurst, MS - Debris

20JUL25: Train 59(19) with E/181 and 7 cars was delayed 14 miles north of Hazlehurst on the CN McComb subdivision due to striking a tree at MP 747.9. There were no reported injuries to the 105 passengers or the crew. The crew removed the tree and branches, reported minimal damage to the plow on E/181, and continued to Hazlehurst.

Train	Delay	Comment
59 (19)	12"	

Train 720(20) Oakland, CA - Initial Terminal Delay

20JUL25: Train 720(20) was delayed departing Oakland due to a late release from mechanical. Train 710(20) was delayed for the same reason. Once released and boarded, 720(20) departed Oakland at 721AM-PT, 9 minutes late and 710(20) departed Oakland at 803AM-PT, 27 minutes late.

WBS#: B.TR.100150.5905

Train	Delay	Comment
720 (20)	09"	
710 (20)	27"	
738 (20)	10"	

Train 22(20) South of San Marcos, TX - M/W Work

20JUL25: Train 22(20) was delayed two miles south of San Marcos on the UPRR Austin subdivision due to MOW overstay completing switch replacement. Once the tracks were released, 22(20) continued to San Marcos.

Train	Delay	Comment
22 (20)	1'41"	

Train 391(20) South of Chicago, IL - Engine Failure

20JUL25: Train 391(20) with E/ID4630 and 7 cars was delayed three miles south of Chicago on the NS Chicago district at 21st St/MP 521.1 due to PTC issues related to the speedometer on E/ID4630 from a prior debris strike. The crew worked with CNOC mechanical to recycle the breaker and were unsuccessful. As a result of PTC failure and unable to operate 392(20) out of Carbondale for said reason, 391(20) shoved back to Chicago and was cancelled with alternate bus transportation between Chicago and Carbondale. Train 392(20) was also cancelled between Carbondale and Chicago with alternate bus transportation.

WBS#: B.TR.100150.5904

Train	Delay	Comment
391 (20)	Canc	CHI-CDL W/alt
392 (20)	Canc	CDL-CHI W/alt

Train 22(20) St. Louis, MO - Crew

20JUL25: Train 22(20) was delayed departing St. Louis on the TRRA Merchants subdivision due to the crew signing up at 830AM-CT. Once the crew signed up, briefed, and boarded the train, 22(20) departed St. Louis at 906AM-CT, 56 minutes late.

Train	Delay	Comment
22(20)	56"	

Train 711(20) East of Wasco, CA - Police Related

20JUL25: Train 711(20) was delayed 13 miles east of Wasco on the BNSF Bakersfield subdivision due to a vehicle on the tracks at MP 903.017. Once the vehicle was removed and the tracks were inspected, 711(20) continued to Wasco.

Train	Delay	Comment
711(20)	51"	

Train 794(19) Solana Beach, CA - Freight Train Interference

20JUL25: Train 794(19) was delayed departing Solana Beach, CA on the SCRRA San Diego subdivision due to a disabled freight ahead with a broken knuckle and DPU issues. SCRRA mechanical forces responded and worked on repairing the knuckle. Mechanical had trouble finding a knuckle to fit the equipment and spent additional time locating one. The freight crew hours of service was up at 400AM-PT with a relief crew on duty in San Bernardino at 530AM-PT. With this being said, the initial estimated time for opening was 830AM-PT. As a result, train 794(19) was terminated at Solana Beach with 15 passengers provided alternate transportation via bus 5818(19). Train 761(20) originate at Los Angeles with an extra set of equipment and train 765(20) originated at Solana Beach utilizing 794(19) equipment. Passengers traveling between San Diego and Solana Beach on trains 761(20) and 765(20) were provided alternate bus transportation to Solana Beach, where they boarded 765(20). Train 562(20) was cancelled entirely between Los Angeles and San Diego with the crew vanning to San Diego for their turn and passengers accommodated on the next available services. Train 769(20) was delayed holding for open track at Old Town and 564(20) was delayed holding for open track at Oceanside.

Operations Recovery Plan:

- 794(19) terminate Solana Beach, CA - Replacement bus to San Diego, CA
- 765(20) originate Solana Beach, CA - Replacement bus from San Diego, CA
- 761(20) originate Los Angeles, CA- passengers to 765(20)
- 562(20) cancelled - passengers to 564(20)
- 769(20) hold at Old Town - San Diego, CA for open track
- 564(20) hold at Oceanside, CA for open track.

WBS#: B.TR.100150.5903

Train	Delay	Comment
769(20)	1'40"	OLT - hold for open track
564(20)	42"	OSD - hold for open track
573(20)	35"	Late crew - deadhead from LAX-SAN
765(20)	48"	Orig SOL - hold for replacement bus from SAN
562(20)	Cancelled	Pax to 564(20)
761(20)	Orig LAX	SAN-LAX pax to 765(20)
794(19)	Term SOL	Rescue Bus SOL-SAN
790(20)	1'15"	GTA - Late inbound equipment from 769(20)

Train 11(19) South of Salinas, CA - Trespasser Incident

20JUL25: At approximately 1:35 PM-PT train 11(19) - operating with camera equipped locomotives AMTK/61, AMTK/339 and eight (8) cars - struck and injured a trespasser at MP 141.0 on the Union Pacific Railway Coast Subdivision in the city of Soledad, Monterey County, California. This incident did NOT occur on a public highway crossing at grade. Train 11(19) was operating south at an estimated 65 MPH on the main track with a posted track speed of 70 MPH. Local Police and Fire officials responded to the scene along with representatives from Amtrak management. There were no initial reports of injuries to the 202 passengers or crew and no reports of damage to Amtrak equipment. The operating crew requested relief, and the outbound crew from San Luis Obispo was transported to the scene where they assumed operation of the train. Once local authorities released the scene and the relief crew was onboard, train 11(19) was able to proceed.

Account the late operation of trian 11(19) caused by this event, train 2/422(20) was held in Los Angeles, CA (LAX) for 36 passengers with through connections. Once train 11(19) arrived and passengers safely transferred, train 2/422(20) departed LAX.

National Response Center: 1437463
California Office of Emergency Services: 25-3594

Google Maps Location of Incident:
<https://maps.app.goo.gl/PxdV9Gn8RYzo9TJVA>
36.420031, -121.318629
Soledad, California 93960

WBS#: B.TR.100150.5906

National Response Center Number: 1437463

Train	Delay	Comment
11(19)	3'41"	Trespasser Strike
2/422(20)	Est 4'30"	LAX - Hold for through passengers from train 11(19)
11(19)	1'10"	Calendar day inspection at Goleta Station

Train 5(20) Chicago, IL - Car Failure - Crew Issue

20JUL25: Train 5(20) was delayed departing Chicago due to the engineer signing up at 243PM-CT. Additional delays were attributed to C/31028 with a brake indicator issue at Union Station. Chicago mechanical responded to assist with repairs. Chicago mechanical bad ordered car C/31028. Passengers were detrained and the equipment shoved back to the yard to replace C/31028 with C/31008. Due to crew availability issues, train 5(20) held at Chicago Union Station, IL waiting for the engineer off train 382(20). Once Chicago mechanical released the equipment, train 5(20) shoved back to the station, and passengers boarded again, train 5(20) departed Chicago Union Station.

Due to the late operation of 5(20), the following service recovery was in effect. Passengers were provided snack packs, water bottles, pizza, beverages, and dessert at the station. Sleeper passengers were provided station vouchers. Additional breakfast items were delivered to the lounge car for morning recovery. On Monday, July 21st, service recovery consisted of:

- Regular meals off the menu for Sleeper Passengers.
- Snack packs and water provided throughout the day.
- Lounge car will off coffee, tea, juice, muffins, coffee cake, and snacks.
- Lunch will be served out of the lounge car.

WBS#: B.TR.100150.5907

Train	Delay	Comment
5(20)	55"	Engineer sign up off 4' cut
5(20)	7'02"	Replace C/31028

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold

conditions.

370(18) - 59 oversold

371(19) - 10 oversold

305(18) - 13 oversold

300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold

371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold

371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.
- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.
- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).
- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, no alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, no alternate transportation between St. Louis and Chicago.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
306(16-29)	Cancelled, no alternate	
301(16-29)	Cancelled, no alternate	

North County Transit District - Planned Trackwork East of Solana Beach

North County Transit District - Trackwork East of Solana Beach, CA
19MAY24, Commencing 19th May, North County Transit District will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:
from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

- Sunday May 19 - Tuesday May 21
- Sunday June 02- Tuesday June 04
- Sunday June 16 - Tuesday June 18
- Sunday June 23 - no extended window account Padres game.
- Sunday June 30 - Tuesday July 2
- Sunday July 7 - Tuesday July 9
- Sunday July 14 - Tuesday July 16
- Sunday July 21 - Tuesday July 23
- Sunday July 28 - Tuesday July 30
- Sunday August 4 - Tuesday August 6
- Sunday August 11 - no extended window account Padres game
- Sunday August 18th - Tuesday 20th
- Sunday August 25 - Tuesday August 27
- Sunday September 8 - Tuesday September 10.
- Sunday September 15 - Monday September 16
- Sunday September 22 - Tuesday September 24.
- Sunday October 27 - Tuesday October 29.
- Sunday November 3 - Tuesday November 5.
- Sunday December 8-Tuesday December 10.
- Sunday December 15-Tuesday December 17.

2025
Sunday February 9 - Tuesday February 11.
Sunday April 06th - Tuesday April 08th (CANCELLED)
Sunday May 20 - Tuesday May 22

During the project the following service adjustments will apply:
Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.
Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.
Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.
Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.
WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Maintenance of Way Highlights

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage
7 (8)	WTN	348		HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 4(19) Passenger Removal at Trinidad, Colorado – Improper Conduct

20JUL25, Passenger on PNR 3D0319, traveling from Los Angeles, CA to Kansas City, MO was removed by the local police at Trinidad, CO due to using a lot of profanity and talking about his gang. Amtrak Police notified.

Delay: **4 (19)** **05"**

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/20/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	267	32	88%	5,741	508	91%	84,510	6,533	92%
Northeast Corridor	98%	71	18	75%	1,508	205	86%	22,693	2,438	89%
Acela	98%	21	7	67%	417	71	83%	6,332	839	87%
Northeast Regional	98%	50	11	78%	1,091	134	88%	16,361	1,599	90%
State Supported	98%	169	10	94%	3,683	194	95%	53,106	2,707	95%
Long Distance	98%	27	4	85%	550	109	80%	8,573	1,382	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/20/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	267	32	88%	5,741	508	91%	84,510	6,533	92%
Northeast Corridor	98%	71	18	75%	1,508	205	86%	22,693	2,438	89%
Acela	98%	21	7	67%	417	71	83%	6,332	839	87%
Northeast Regional	98%	50	11	78%	1,091	134	88%	16,361	1,599	90%
On Spine Northeast Regional	98%	25	6	76%	563	67	88%	8,297	845	90%
Richmond / Newport News / Norfolk	98%	11	4	64%	232	54	77%	3,412	518	85%
Roanoke	98%	4	1	75%	80	8	90%	1,166	158	86%
Springfield Shuttles	98%	10	-	100%	216	5	98%	3,486	78	98%
State Supported	98%	169	10	94%	3,683	194	95%	53,106	2,707	95%
Borealis	98%	2	-	100%	40	5	88%	571	64	89%
Capitol Corridor	98%	22	1	95%	516	18	97%	6,976	153	98%
Carolinian	98%	2	1	50%	40	7	83%	586	49	92%
Cascades	98%	14	-	100%	280	13	95%	3,981	281	93%
Downeaster	98%	10	-	100%	196	1	99%	2,784	45	98%
Empire	98%	20	2	90%	400	28	93%	6,286	328	95%
Adirondack	98%	2	-	100%	40	2	95%	586	43	93%
Berkshire Flyer	98%	2	1	50%	9	2	78%	15	4	73%
Ethan Allen Express	98%	2	-	100%	40	5	88%	586	39	93%
Maple Leaf	98%	2	-	100%	40	2	95%	586	56	90%
New York - Albany	98%	8	-	100%	191	6	97%	3,342	93	97%
New York - Niagara Falls	98%	4	1	75%	80	11	86%	1,171	93	92%
Heartland Flyer	98%	2	-	100%	36	1	97%	578	17	97%
Hiawatha	98%	10	-	100%	231	7	97%	3,344	122	96%
Illinois	98%	11	3	73%	262	23	91%	4,029	279	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	80	2	98%	1,160	45	96%
Illini / Saluki	98%	3	-	100%	79	8	90%	1,159	44	96%
Lincoln Service	98%	4	3	25%	103	13	87%	1,710	190	89%
Keystone	98%	14	1	93%	451	23	95%	6,765	411	94%
Lincoln / Missouri	98%	2	-	100%	40	9	78%	580	84	86%
Michigan	98%	10	1	90%	196	16	92%	2,800	270	90%
Blue Water	98%	2	-	100%	40	4	90%	582	86	85%
Pere Marquette	98%	2	-	100%	38	2	95%	584	27	95%
Wolverine	98%	6	1	83%	118	10	92%	1,634	157	90%
Missouri	98%	2	-	100%	38	1	97%	564	15	97%
Pacific Surfliner	98%	24	1	96%	480	10	98%	6,258	232	96%
Pennsylvanian	98%	2	-	100%	40	7	83%	586	67	89%
Piedmont	98%	8	-	100%	159	1	99%	2,328	33	99%
San Joaquins	98%	12	-	100%	238	19	92%	3,504	200	94%
Vermonter	98%	2	-	100%	40	5	88%	586	57	90%
Long Distance	98%	27	4	85%	550	109	80%	8,573	1,382	84%
Auto Train	98%	2	1	50%	40	4	90%	574	97	83%
California Zephyr	98%	2	-	100%	40	13	68%	583	135	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	17	7	59%	249	51	80%
City Of New Orleans	98%	2	-	100%	40	6	85%	572	52	91%
Coast Starlight	98%	2	-	100%	42	3	93%	589	88	85%
Crescent	98%	2	1	50%	40	5	88%	586	69	88%
Empire Builder	98%	4	-	100%	75	11	85%	1,126	144	87%
Floridian	98%	1	-	100%	39	13	67%	496	174	65%
Lake Shore Ltd	98%	2	1	50%	40	13	68%	984	114	88%
Palmetto	98%	2	-	100%	40	4	90%	584	38	93%
Silver Meteor	98%	2	1	50%	40	7	83%	582	115	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	-	100%	40	10	75%	584	147	75%
Sunset Ltd	98%	1	-	100%	17	5	71%	247	44	82%
Texas Eagle	98%	2	-	100%	40	8	80%	656	89	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/20/25										
Day			Month to Date					Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	272	12	96%	5,767	154	97%	84,546	2,026	98%
Northeast Corridor	98%	73	4	95%	1,511	41	97%	22,648	639	97%
Acela	98%	21	1	95%	417	9	98%	6,334	165	97%
Northeast Regional	98%	52	3	94%	1,094	32	97%	16,314	474	97%
State Supported	98%	170	5	97%	3,685	62	98%	53,092	882	98%
Long Distance	98%	29	3	90%	571	51	91%	8,668	503	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/20/25										
Day			Month to Date					Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	272	12	96%	5,767	154	97%	84,546	2,026	98%
Central Division	98%	62	3	95%	1,316	63	95%	19,355	670	97%
Northeast Division	98%	90	6	93%	1,832	38	98%	27,848	652	98%
Southeast Division	98%	55	1	98%	1,259	33	97%	18,689	441	98%
Southwest Division	98%	65	2	97%	1,360	20	99%	18,654	263	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/20/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	272	12	96%	5,767	154	97%	84,546	2,026	98%
Central Division	98%	62	3	95%	1,316	63	95%	19,355	670	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	1	-	100%	44	1	98%	587	3	99%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	25	2	92%	530	45	92%	7,806	432	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	40	-	100%	564	3	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	19	-	100%	292	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	39	-	100%	568	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	5	-	100%	116	3	97%	1,679	12	99%
MSP	98%	1	-	100%	20	1	95%	281	7	98%
PDX	98%	5	-	100%	96	1	99%	1,408	36	97%
PNT	98%	3	-	100%	59	1	98%	806	8	99%
PTH	98%	1	-	100%	20	-	100%	291	6	98%
QCY	98%	2	-	100%	38	-	100%	568	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	161	8	95%	2,288	121	95%
SPK	98%	1	-	100%	20	-	100%	301	2	99%
STL	98%	3	1	67%	70	3	96%	1,147	19	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	40	-	100%	561	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	90	6	93%	1,832	38	98%	27,848	652	98%
ALB	98%	7	-	100%	140	1	99%	2,049	26	99%
BON	98%	5	-	100%	98	-	100%	1,362	3	100%
BOS	98%	19	1	95%	355	7	98%	5,472	129	98%
BRK	98%	5	-	100%	71	-	100%	1,332	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	20	-	100%	291	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	1	-	100%	36	-	100%	563	-	100%
HFD	98%	-	-	100%	26	-	100%	172	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	20	1	95%	291	6	98%
NFL	98%	2	-	100%	40	-	100%	586	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	4	-	100%	93	-	100%	1,500	35	98%
NYP	98%	36	5	86%	765	28	96%	11,759	413	96%
POR	98%	-	-	100%	24	-	100%	24	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	18	-	100%	289	1	100%
SPG	98%	7	-	100%	99	1	99%	1,795	20	99%
TWO	98%	1	-	100%	20	-	100%	290	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	55	1	98%	1,259	33	97%	18,689	441	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	97	1	99%	1,451	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/20/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	272	12	96%	5,767	154	97%	84,546	2,026	98%
Southeast Division	98%	55	1	98%	1,259	33	97%	18,689	441	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	7	-	100%	218	2	99%	3,163	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	20	-	100%	287	11	96%
MIA	98%	1	-	100%	38	3	92%	563	31	94%
NFK	98%	2	-	100%	56	2	96%	806	5	99%
NOL	98%	2	-	100%	43	1	98%	650	21	97%
NPN	98%	2	-	100%	40	1	98%	559	4	99%
PGH	98%	1	-	100%	20	-	100%	292	3	99%
PHL	98%	2	-	100%	83	3	96%	1,249	36	97%
RGH	98%	4	-	100%	72	-	100%	1,175	5	100%
RNK	98%	2	-	100%	37	-	100%	554	8	99%
RVM	98%	1	-	100%	20	-	100%	284	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	18	1	94%	274	1	100%
SFA	98%	1	-	100%	20	-	100%	287	18	94%
WAS	98%	23	1	96%	467	19	96%	6,942	266	96%
Southwest Division	98%	65	2	97%	1,360	20	99%	18,654	263	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	20	-	100%	293	-	100%
BFD	98%	6	-	100%	118	-	100%	1,741	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	20	4	80%	300	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	19	-	100%	325	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	60	-	100%	856	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	10	-	100%	189	2	99%	2,248	64	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	17	-	100%	288	-	100%
OKJ	98%	9	1	89%	218	9	96%	3,071	70	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	11	-	100%	259	1	100%	3,490	13	100%
SAN	98%	12	1	92%	238	3	99%	2,660	25	99%
SAS	98%	1	-	100%	20	1	95%	289	3	99%
SJC	98%	7	-	100%	139	-	100%	1,879	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	40	-	100%	573	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	2	-	100%	49	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT DA.. 7/20/2025 12:00..	High Speed Trainset			Super liner I	Amfl eet I	Diesel Locomotive		Viewliner I		Caltr ans Loc..	View liner II	Elect ric L oco..	Surfli ner	Amfl eet II	Cab Car	Calif ornia Car..	Grand Tot al
	CAR	ENG	MTI	CAR	CAR	ENG	CCR	CAR	MTI	ENG	MTI	CAR	CAR	CAR	ENG	CAR	
Air/Brake Problems	147	221	142	422													932
Door Problems					187	10						16	16			4	233
Wheel Defects								166	9								175
I-ETMS Problem						73	6			16							95
ITCS Problem						55											55
Electrical Problems				42													42
Noise/Smoke Und..					37												37
Car Hot: Air Condi..					13									11			24
Loading Problems						24											24
Wayside Hot Box ..											22						22
Pantograph Proble..		18															18
Traction Motor Pro..										17							17
Computer Fault						11											11
Tilt System Proble..	5																5
Speedometer Defe..															4		4
Grand Total	152	239	142	464	237	173	6	166	9	33	22	16	16	11	4	4	1,694