# CNOC

## (CONSOLIDATED NATIONAL OPERATIONS CENTER)

# Amtrak Status Report

Sunday, October 25, 2026 Rules: 4-4




*This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.*

### Information Management

# Initial Terminal Performance By Division

Scheduled Departure Date: **10/24/2026**
Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/24/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 295 | 58 | 80.3% | 7,374 | 1,064 | 85.6% | 7,374 | 1,064 | 85.6% |
| Central Division | 86.0% | 57 | 9 | 84.2% | 1,379 | 99 | 92.8% | 1,379 | 99 | 92.8% |
| East Division | 82.0% | 153 | 27 | 82.4% | 3,919 | 600 | 84.7% | 3,919 | 600 | 84.7% |
| West Division | 86.0% | 85 | 22 | 74.1% | 2,076 | 365 | 82.4% | 2,076 | 365 | 82.4% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

# Customer On Time Performance

Endpoint Arrival Dates through 10/24/26

| Service | Target | Day | | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score |
| **Amtrak System** | **80%** | **87,542** | **24,695** | **72%** | **2,483,380** | **724,803** | **71%** | **2,483,380** | **724,803** | **71%** |
| ***Northeast Corridor*** | ***81%*** | ***33,816*** | ***3,838*** | ***89%*** | ***1,072,732*** | ***264,169*** | ***75%*** | ***1,072,732*** | ***264,169*** | ***75%*** |
| Acela | 83% | 3,532 | 829 | 77% | 196,246 | 41,695 | 79% | 196,246 | 41,695 | 79% |
| Northeast Regional | 79% | 30,284 | 3,009 | 90% | 876,486 | 222,474 | 75% | 876,486 | 222,474 | 75% |
| Richmond / Newport News / Norfolk | 77% | 8,664 | 661 | 92% | 217,533 | 58,680 | 73% | 217,533 | 58,680 | 73% |
| Springfield Shuttles | 89% | 467 | 59 | 87% | 18,345 | 4,507 | 75% | 18,345 | 4,507 | 75% |
| Roanoke | 79% | 2,740 | 95 | 97% | 78,260 | 21,373 | 73% | 78,260 | 21,373 | 73% |
| On Spine Northeast Regional | 80% | 18,413 | 2,194 | 88% | 562,348 | 137,914 | 75% | 562,348 | 137,914 | 75% |
| ***State Supported*** | ***80%*** | ***42,774*** | ***16,328*** | ***62%*** | ***1,116,568*** | ***325,858*** | ***71%*** | ***1,116,568*** | ***325,858*** | ***71%*** |
| Borealis | 80% | 725 | 223 | 69% | 17,585 | 3,510 | 80% | 17,585 | 3,510 | 80% |
| Capitol Corridor | 90% | 2,597 | 280 | 89% | 101,207 | 17,685 | 83% | 101,207 | 17,685 | 83% |
| Carolinian | 70% | 967 | 21 | 98% | 30,905 | 8,963 | 71% | 30,905 | 8,963 | 71% |
| Cascades | 75% | 2,865 | 697 | 76% | 68,090 | 19,465 | 71% | 68,090 | 19,465 | 71% |
| Downeaster | 82% | 2,059 | 348 | 83% | 45,491 | 11,803 | 74% | 45,491 | 11,803 | 74% |
| Empire | 78% | 6,122 | 1,431 | 77% | 157,128 | 38,370 | 76% | 157,128 | 38,370 | 76% |
| Adirondack | 72% | 330 | 221 | 33% | 10,551 | 1,721 | 84% | 10,551 | 1,721 | 84% |
| Ethan Allen Express | 70% | 490 | 131 | 73% | 14,680 | 5,986 | 59% | 14,680 | 5,986 | 59% |
| Maple Leaf | 70% | 887 | 0 | 100% | 21,307 | 6,515 | 69% | 21,307 | 6,515 | 69% |
| New York - Albany | 85% | 3,060 | 684 | 78% | 76,002 | 14,189 | 81% | 76,002 | 14,189 | 81% |
| New York - Niagara Falls | 75% | 1,355 | 395 | 71% | 34,588 | 9,959 | 71% | 34,588 | 9,959 | 71% |
| Gold Runner | 73% | 2,420 | 1,440 | 40% | 62,653 | 25,264 | 60% | 62,653 | 25,264 | 60% |
| Heartland Flyer | 70% | 229 | 222 | 3% | 5,014 | 4,396 | 12% | 5,014 | 4,396 | 12% |
| Hiawatha | 90% | 1,379 | 632 | 54% | 45,576 | 4,716 | 90% | 45,576 | 4,716 | 90% |
| Illinois | 78% | 3,096 | 1,648 | 47% | 66,496 | 21,915 | 67% | 66,496 | 21,915 | 67% |
| Carl Sandburg / Illinois Zephyr | 85% | 576 | 139 | 76% | 10,649 | 2,726 | 74% | 10,649 | 2,726 | 74% |
| Illini / Saluki | 85% | 996 | 470 | 53% | 22,205 | 9,358 | 58% | 22,205 | 9,358 | 58% |
| Lincoln Service | 70% | 1,524 | 1,039 | 32% | 33,642 | 9,831 | 71% | 33,642 | 9,831 | 71% |
| Keystone | 92% | 4,731 | 348 | 93% | 171,436 | 19,368 | 89% | 171,436 | 19,368 | 89% |
| Lincoln / Missouri | 70% | 989 | 575 | 42% | 21,161 | 10,714 | 49% | 21,161 | 10,714 | 49% |
| Mardi Gras Service | 80% | 420 | 189 | 55% | 7,031 | 2,240 | 68% | 7,031 | 2,240 | 68% |
| Michigan | 70% | 2,425 | 816 | 66% | 54,155 | 14,292 | 74% | 54,155 | 14,292 | 74% |
| Blue Water | 70% | 513 | 0 | 100% | 12,978 | 4,431 | 66% | 12,978 | 4,431 | 66% |
| Pere Marquette | 85% | 323 | 0 | 100% | 7,378 | 391 | 95% | 7,378 | 391 | 95% |
| Wolverine | 70% | 1,589 | 816 | 49% | 33,799 | 9,470 | 72% | 33,799 | 9,470 | 72% |
| Missouri | 80% | 406 | 168 | 59% | 7,215 | 1,472 | 80% | 7,215 | 1,472 | 80% |
| Pacific Surfliner | 85% | 7,511 | 6,442 | 14% | 165,041 | 95,194 | 42% | 165,041 | 95,194 | 42% |
| Pennsylvanian | 80% | 685 | 449 | 34% | 22,480 | 7,849 | 65% | 22,480 | 7,849 | 65% |
| Piedmont | 80% | 1,830 | 374 | 80% | 30,521 | 7,816 | 74% | 30,521 | 7,816 | 74% |
| Vermonter | 75% | 1,318 | 25 | 98% | 37,383 | 10,826 | 71% | 37,383 | 10,826 | 71% |
| ***Long Distance*** | ***70%*** | ***10,952*** | ***4,529*** | ***59%*** | ***294,080*** | ***134,776*** | ***54%*** | ***294,080*** | ***134,776*** | ***54%*** |
| Auto Train | 70% | 738 | 738 | 0% | 15,921 | 11,636 | 27% | 15,921 | 11,636 | 27% |
| California Zephyr | 70% | 955 | 1 | 100% | 22,908 | 6,787 | 70% | 22,908 | 6,787 | 70% |
| Cardinal | 70% | 83 | 13 | 84% | 5,423 | 2,544 | 53% | 5,423 | 2,544 | 53% |
| City Of New Orleans | 75% | 789 | 596 | 24% | 18,226 | 13,456 | 26% | 18,226 | 13,456 | 26% |
| Coast Starlight | 70% | 971 | 500 | 49% | 27,162 | 14,537 | 46% | 27,162 | 14,537 | 46% |
| Crescent | 70% | 877 | 24 | 97% | 23,313 | 2,817 | 88% | 23,313 | 2,817 | 88% |
| Empire Builder | 70% | 1,127 | 394 | 65% | 25,344 | 9,983 | 61% | 25,344 | 9,983 | 61% |
| Floridian | 60% | 830 | 396 | 52% | 34,071 | 20,277 | 40% | 34,071 | 20,277 | 40% |
| Lake Shore Ltd | 73% | 1,037 | 448 | 57% | 25,968 | 8,213 | 68% | 25,968 | 8,213 | 68% |
| Palmetto | 70% | 699 | 0 | 100% | 18,459 | 3,358 | 82% | 18,459 | 3,358 | 82% |
| Silver Meteor | 70% | 1,383 | 548 | 60% | 26,420 | 7,966 | 70% | 26,420 | 7,966 | 70% |
| Southwest Chief | 60% | 360 | 200 | 44% | 21,326 | 16,282 | 24% | 21,326 | 16,282 | 24% |
| Sunset Ltd | 70% | 0 | 0 | - | 6,990 | 3,410 | 51% | 6,990 | 3,410 | 51% |
| Texas Eagle | 70% | 1,103 | 671 | 39% | 22,549 | 13,510 | 40% | 22,549 | 13,510 | 40% |

**Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"**

# Amtrak Caused Delay Per 10K Train Miles - By Department

**Train Index Dates Through October 24, 2026**

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Service** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| Amtrak System | 585 | 149,542 | 2,410,237 | 620 | 149,542 | 2,410,237 | 620 |

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Department** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| INFRASTRUCTURE UNPLANNED | 107 | 6,846 | 692,945 | 99 | 6,846 | 692,945 | 99 |
| INFRASTRUCTURE PLANNED | 135 | 16,086 | 692,945 | 232 | 16,086 | 692,945 | 232 |
| FLEET RELIABILITY | 90 | 19,578 | 2,410,237 | 81 | 19,578 | 2,410,237 | 81 |
| TRAIN OPERATIONS | 424 | 107,032 | 2,410,237 | 444 | 107,032 | 2,410,237 | 444 |

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

### Information Management

# Initial Terminal Performance By Division

Scheduled Departure Date: **10/24/2026**
Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/24/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 295 | 58 | 80.3% | 7,374 | 1,064 | 85.6% | 7,374 | 1,064 | 85.6% |
| Central Division | 86.0% | 57 | 9 | 84.2% | 1,379 | 99 | 92.8% | 1,379 | 99 | 92.8% |
| East Division | 82.0% | 153 | 27 | 82.4% | 3,919 | 600 | 84.7% | 3,919 | 600 | 84.7% |
| West Division | 86.0% | 85 | 22 | 74.1% | 2,076 | 365 | 82.4% | 2,076 | 365 | 82.4% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/24/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/24/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 295 | 58 | 80.3% | 7,374 | 1,064 | 85.6% | 7,374 | 1,064 | 85.6% |
| Central Division | 86.0% | 57 | 9 | 84.2% | 1,379 | 99 | 92.8% | 1,379 | 99 | 92.8% |
| CDL | 95.0% | 2 | 0 | 100.0% | 32 | 2 | 93.8% | 32 | 2 | 93.8% |
| CHI | 86.0% | 26 | 5 | 80.8% | 650 | 54 | 91.7% | 650 | 54 | 91.7% |
| CHM | - | - | - | - | 15 | 2 | 86.7% | 15 | 2 | 86.7% |
| DAL | - | - | - | - | 2 | 0 | 100.0% | 2 | 0 | 100.0% |
| DET | - | - | - | - | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| FTW | 92.5% | 1 | 0 | 100.0% | 21 | 2 | 90.5% | 21 | 2 | 90.5% |
| GRR | 95.5% | 1 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| IND | - | 1 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| KCY | 92.0% | 2 | 0 | 100.0% | 48 | 1 | 97.9% | 48 | 1 | 97.9% |
| MKE | 92.0% | 5 | 1 | 80.0% | 140 | 8 | 94.3% | 140 | 8 | 94.3% |
| MOE | 97.5% | 2 | 0 | 100.0% | 41 | 0 | 100.0% | 41 | 0 | 100.0% |
| MSP | 96.5% | 1 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| NOL | 94.5% | 5 | 0 | 100.0% | 95 | 4 | 95.8% | 95 | 4 | 95.8% |
| OKC | 97.0% | 1 | 0 | 100.0% | 23 | 1 | 95.7% | 23 | 1 | 95.7% |
| PNT | 88.0% | 3 | 2 | 33.3% | 69 | 12 | 82.6% | 69 | 12 | 82.6% |
| PTH | 93.0% | 1 | 0 | 100.0% | 24 | 1 | 95.8% | 24 | 1 | 95.8% |
| QCY | 91.0% | 2 | 0 | 100.0% | 48 | 2 | 95.8% | 48 | 2 | 95.8% |
| SAS | 90.5% | 1 | 0 | 100.0% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| STL | 89.0% | 3 | 1 | 66.7% | 95 | 3 | 96.8% | 95 | 3 | 96.8% |
| East Division | 82.0% | 153 | 27 | 82.4% | 3,919 | 600 | 84.7% | 3,919 | 600 | 84.7% |
| ALB | 88.5% | 8 | 1 | 87.5% | 189 | 14 | 92.6% | 189 | 14 | 92.6% |
| ALX | - | 3 | 1 | 66.7% | 24 | 14 | 41.7% | 24 | 14 | 41.7% |
| ATL | - | 1 | 1 | 0.0% | 12 | 4 | 66.7% | 12 | 4 | 66.7% |
| BON | 87.5% | 5 | 0 | 100.0% | 120 | 11 | 90.8% | 120 | 11 | 90.8% |
| BOS | 85.5% | 7 | 1 | 85.7% | 321 | 16 | 95.0% | 321 | 16 | 95.0% |
| BRK | 92.5% | 5 | 0 | 100.0% | 120 | 9 | 92.5% | 120 | 9 | 92.5% |
| BTN | 82.0% | 1 | 0 | 100.0% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| CLT | 91.5% | 5 | 1 | 80.0% | 114 | 16 | 86.0% | 114 | 16 | 86.0% |
| GFD | 88.0% | 2 | 1 | 50.0% | 48 | 5 | 89.6% | 48 | 5 | 89.6% |
| GRO | - | - | - | - | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| HAR | 79.5% | 9 | 1 | 88.9% | 274 | 34 | 87.6% | 274 | 34 | 87.6% |
| HFD | - | - | - | - | 34 | 7 | 79.4% | 34 | 7 | 79.4% |
| JAX | - | 2 | 0 | 100.0% | 15 | 2 | 86.7% | 15 | 2 | 86.7% |
| LOR | 84.0% | 1 | 1 | 0.0% | 22 | 10 | 54.5% | 22 | 10 | 54.5% |
| MET | - | - | - | - | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| MIA | 89.5% | 2 | 0 | 100.0% | 47 | 8 | 83.0% | 47 | 8 | 83.0% |
| MTR | 79.0% | 1 | 1 | 0.0% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| NFK | 84.5% | 1 | 1 | 0.0% | 40 | 7 | 82.5% | 40 | 7 | 82.5% |
| NFL | 93.5% | 2 | 1 | 50.0% | 48 | 5 | 89.6% | 48 | 5 | 89.6% |
| NFS | - | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| NHV | 78.0% | 5 | 1 | 80.0% | 121 | 29 | 76.0% | 121 | 29 | 76.0% |
| NPN | 93.0% | - | - | - | 30 | 4 | 86.7% | 30 | 4 | 86.7% |
| NYP | 75.5% | 41 | 8 | 80.5% | 1,020 | 177 | 82.6% | 1,020 | 177 | 82.6% |

**Information Management**

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/24/2026**
Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/24/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 295 | 58 | 80.3% | 7,374 | 1,064 | 85.6% | 7,374 | 1,064 | 85.6% |
| East Division | 82.0% | 153 | 27 | 82.4% | 3,919 | 600 | 84.7% | 3,919 | 600 | 84.7% |
| PGH | 93.0% | 1 | 1 | 0.0% | 31 | 9 | 71.0% | 31 | 9 | 71.0% |
| PHL | 48.0% | 6 | 3 | 50.0% | 181 | 85 | 53.0% | 181 | 85 | 53.0% |
| RGH | 95.0% | 6 | 1 | 83.3% | 102 | 19 | 81.4% | 102 | 19 | 81.4% |
| RNK | 83.5% | 1 | 0 | 100.0% | 41 | 6 | 85.4% | 41 | 6 | 85.4% |
| SAB | 98.0% | 1 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| SAV | 96.0% | - | - | - | 15 | 0 | 100.0% | 15 | 0 | 100.0% |
| SFA | 88.0% | 1 | 0 | 100.0% | 22 | 5 | 77.3% | 22 | 5 | 77.3% |
| SPG | 92.5% | 6 | 0 | 100.0% | 130 | 9 | 93.1% | 130 | 9 | 93.1% |
| TWO | 73.0% | - | - | - | 23 | 8 | 65.2% | 23 | 8 | 65.2% |
| WAS | 84.0% | 29 | 1 | 96.6% | 696 | 75 | 89.2% | 696 | 75 | 89.2% |
| West Division | 86.0% | 85 | 22 | 74.1% | 2,076 | 365 | 82.4% | 2,076 | 365 | 82.4% |
| ARN | 92.0% | 1 | 1 | 0.0% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| BFD | 79.0% | 7 | 3 | 57.1% | 166 | 42 | 74.7% | 166 | 42 | 74.7% |
| EMY | 72.0% | 1 | 0 | 100.0% | 25 | 11 | 56.0% | 25 | 11 | 56.0% |
| EUG | 86.5% | 2 | 1 | 50.0% | 46 | 2 | 95.7% | 46 | 2 | 95.7% |
| GAC | - | - | - | - | 3 | 2 | 33.3% | 3 | 2 | 33.3% |
| GTA | 90.0% | 5 | 3 | 40.0% | 89 | 37 | 58.4% | 89 | 37 | 58.4% |
| IRV | - | - | - | - | 1 | 0 | 100.0% | 1 | 0 | 100.0% |
| LAX | 89.5% | 11 | 2 | 81.8% | 229 | 25 | 89.1% | 229 | 25 | 89.1% |
| OKJ | 74.5% | 9 | 4 | 55.6% | 280 | 86 | 69.3% | 280 | 86 | 69.3% |
| PDX | 86.0% | 5 | 0 | 100.0% | 120 | 11 | 90.8% | 120 | 11 | 90.8% |
| SAC | 88.5% | 12 | 1 | 91.7% | 354 | 32 | 91.0% | 354 | 32 | 91.0% |
| SAN | 90.5% | 13 | 4 | 69.2% | 271 | 58 | 78.6% | 271 | 58 | 78.6% |
| SEA | 85.0% | 8 | 1 | 87.5% | 191 | 23 | 88.0% | 191 | 23 | 88.0% |
| SJC | 89.0% | 7 | 1 | 85.7% | 167 | 23 | 86.2% | 167 | 23 | 86.2% |
| SLO | 90.0% | 1 | 1 | 0.0% | 43 | 9 | 79.1% | 43 | 9 | 79.1% |
| SPK | 90.0% | 1 | 0 | 100.0% | 23 | 0 | 100.0% | 23 | 0 | 100.0% |
| VAC | 97.0% | 2 | 0 | 100.0% | 44 | 2 | 95.5% | 44 | 2 | 95.5% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 3 | 485 | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 24 | 17 | 29.2% | 24 | 17 | 29.2% |
| 4 | 718 | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 20 | 16.7% | 24 | 20 | 16.7% |
| 5 | | 23 | 1 | 95.7% | 23 | 1 | 95.7% | 23 | 6 | 73.9% | 23 | 6 | 73.9% |
| 6 | | 23 | 11 | 52.2% | 23 | 11 | 52.2% | 23 | 7 | 69.6% | 23 | 7 | 69.6% |
| 7 | | 23 | 2 | 91.3% | 23 | 2 | 91.3% | 23 | 2 | 91.3% | 23 | 2 | 91.3% |
| 8 | | 23 | 6 | 73.9% | 23 | 6 | 73.9% | 23 | 14 | 39.1% | 23 | 14 | 39.1% |
| 11 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 13 | 45.8% | 24 | 13 | 45.8% |
| 14 | 178 | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 15 | 37.5% | 24 | 15 | 37.5% |
| 19 | | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 23 | 3 | 87.0% | 23 | 3 | 87.0% |
| 20 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 25 | 3 | 88.0% | 25 | 3 | 88.0% |
| 21 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 11 | 54.2% | 24 | 11 | 54.2% |
| 22 | 81 | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 24 | 16 | 33.3% | 24 | 16 | 33.3% |
| 23 | | 21 | 0 | 100.0% | 21 | 0 | 100.0% | 21 | 5 | 76.2% | 21 | 5 | 76.2% |
| 24 | | 20 | 0 | 100.0% | 20 | 0 | 100.0% | 20 | 5 | 75.0% | 20 | 5 | 75.0% |
| 25 | 69 | 20 | 0 | 100.0% | 20 | 0 | 100.0% | 20 | 6 | 70.0% | 20 | 6 | 70.0% |
| 26 | 68 | 21 | 0 | 100.0% | 21 | 0 | 100.0% | 21 | 8 | 61.9% | 21 | 8 | 61.9% |
| 27 | | 23 | 3 | 87.0% | 23 | 3 | 87.0% | 23 | 4 | 82.6% | 23 | 4 | 82.6% |
| 28 | | 23 | 3 | 87.0% | 23 | 3 | 87.0% | 23 | 3 | 87.0% | 23 | 3 | 87.0% |
| 40 | 78 | 24 | 10 | 58.3% | 24 | 10 | 58.3% | 24 | 12 | 50.0% | 24 | 12 | 50.0% |
| 41 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 25 | 12 | 52.0% | 25 | 12 | 52.0% |
| 42 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 43 | 18 | 24 | 8 | 66.7% | 24 | 8 | 66.7% | 23 | 10 | 56.5% | 23 | 10 | 56.5% |
| 48 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 49 | 56 | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 5 | 79.2% |
| 50 | | 11 | 0 | 100.0% | 11 | 0 | 100.0% | 11 | 4 | 63.6% | 11 | 4 | 63.6% |
| 51 | | 10 | 3 | 70.0% | 10 | 3 | 70.0% | 11 | 4 | 63.6% | 11 | 4 | 63.6% |
| 52 | 111 | 22 | 5 | 77.3% | 22 | 5 | 77.3% | 22 | 12 | 45.5% | 22 | 12 | 45.5% |
| 53 | 61 | 22 | 10 | 54.5% | 22 | 10 | 54.5% | 22 | 19 | 13.6% | 22 | 19 | 13.6% |
| 54 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 57 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 58 | 33 | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 22 | 8.3% | 24 | 22 | 8.3% |
| 59 | 67 | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 19 | 20.8% | 24 | 19 | 20.8% |
| 63 | | 24 | 10 | 58.3% | 24 | 10 | 58.3% | 24 | 22 | 8.3% | 24 | 22 | 8.3% |
| 64 | | 24 | 9 | 62.5% | 24 | 9 | 62.5% | 24 | 13 | 45.8% | 24 | 13 | 45.8% |
| 65 | | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 66 | | 23 | 3 | 87.0% | 23 | 3 | 87.0% | 23 | 2 | 91.3% | 23 | 2 | 91.3% |
| 68 | 47 | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 24 | 5 | 79.2% | 24 | 5 | 79.2% |
| 69 | | 24 | 9 | 62.5% | 24 | 9 | 62.5% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 71 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 3 | 87.5% | 24 | 3 | 87.5% |
| 72 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 73 | | 19 | 3 | 84.2% | 19 | 3 | 84.2% | 19 | 7 | 63.2% | 19 | 7 | 63.2% |
| 74 | 19 | 19 | 5 | 73.7% | 19 | 5 | 73.7% | 19 | 9 | 52.6% | 19 | 9 | 52.6% |

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 75 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 22 | 6 | 72.7% | 22 | 6 | 72.7% |
| 76 | | 23 | 4 | 82.6% | 23 | 4 | 82.6% | 22 | 8 | 63.6% | 22 | 8 | 63.6% |
| 77 | 36 | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 78 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 25 | 4 | 84.0% | 25 | 4 | 84.0% |
| 79 | | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 8 | 66.7% | 24 | 8 | 66.7% |
| 80 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 82 | | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 87 | | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 88 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 97 | | 24 | 8 | 66.7% | 24 | 8 | 66.7% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 98 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 25 | 9 | 64.0% | 25 | 9 | 64.0% |
| 99 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 101 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 103 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 106 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 107 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 109 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 118 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 124 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 126 | 41 | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 3 | 50.0% | 6 | 3 | 50.0% |
| 127 | | 6 | 2 | 66.7% | 6 | 2 | 66.7% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 135 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 140 | 64 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 142 | | 6 | 2 | 66.7% | 6 | 2 | 66.7% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 143 | 31 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 144 | | 6 | 5 | 16.7% | 6 | 5 | 16.7% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 146 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 147 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 5 | 16.7% | 6 | 5 | 16.7% |
| 150 | | 7 | 5 | 28.6% | 7 | 5 | 28.6% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 151 | | 14 | 11 | 21.4% | 14 | 11 | 21.4% | 14 | 3 | 78.6% | 14 | 3 | 78.6% |
| 152 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 153 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 155 | | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| 156 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 158 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 159 | | 6 | 5 | 16.7% | 6 | 5 | 16.7% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 160 | | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 161 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 162 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 163 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 164 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 165 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 167 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 168 | | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 194 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 195 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 230 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 1 | 95.8% |
| 232 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 233 | 35 | 24 | 11 | 54.2% | 24 | 11 | 54.2% | 24 | 11 | 54.2% | 24 | 11 | 54.2% |
| 234 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 1 | 95.8% | 24 | 1 | 95.8% |
| 235 | 118 | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 236 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 5 | 79.2% | 24 | 5 | 79.2% |
| 237 | 38 | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 238 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 1 | 95.8% | 24 | 1 | 95.8% |
| 239 | | 23 | 4 | 82.6% | 23 | 4 | 82.6% | 23 | 1 | 95.7% | 23 | 1 | 95.7% |
| 240 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 241 | | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 7 | 70.8% | 24 | 7 | 70.8% |
| 243 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| 244 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 7 | 70.8% | 24 | 7 | 70.8% |
| 245 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 280 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 10 | 58.3% | 24 | 10 | 58.3% |
| 281 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 3 | 87.5% | 24 | 3 | 87.5% |
| 283 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 284 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 290 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 23 | 10 | 56.5% | 23 | 10 | 56.5% |
| 291 | 71 | 24 | 15 | 37.5% | 24 | 15 | 37.5% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 301 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 302 | 24 | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 305 | 34 | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 8 | 66.7% | 24 | 8 | 66.7% |
| 306 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 8 | 66.7% | 24 | 8 | 66.7% |
| 307 | 171 | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 10 | 58.3% | 24 | 10 | 58.3% |
| 311 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 316 | 22 | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 7 | 70.8% | 24 | 7 | 70.8% |
| 318 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 10 | 58.3% | 24 | 10 | 58.3% |
| 319 | 58 | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 23 | 18 | 21.7% | 23 | 18 | 21.7% |
| 330 | Cncld | 21 | 0 | 100.0% | 21 | 0 | 100.0% | 20 | 1 | 95.0% | 20 | 1 | 95.0% |
| 331 | Cncld | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 23 | 1 | 95.7% | 23 | 1 | 95.7% |
| 332 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| 334 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| 335 | 24 | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 338 | 32 | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 7 | 70.8% | 24 | 7 | 70.8% |
| 339 | 16 | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 24 | 5 | 79.2% | 24 | 5 | 79.2% |
| 341 | | 23 | 5 | 78.3% | 23 | 5 | 78.3% | 23 | 2 | 91.3% | 23 | 2 | 91.3% |
| 342 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 24 | 3 | 87.5% |

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 343 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 350 | 36 | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 22 | 11 | 50.0% | 22 | 11 | 50.0% |
| 351 | 37 | 22 | 4 | 81.8% | 22 | 4 | 81.8% | 20 | 4 | 80.0% | 20 | 4 | 80.0% |
| 352 | 22 | 23 | 1 | 95.7% | 23 | 1 | 95.7% | 22 | 8 | 63.6% | 22 | 8 | 63.6% |
| 353 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 23 | 4 | 82.6% | 23 | 4 | 82.6% |
| 354 | 47 | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 23 | 9 | 60.9% | 23 | 9 | 60.9% |
| 355 | 227 | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 23 | 7 | 69.6% | 23 | 7 | 69.6% |
| 364 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 7 | 70.8% | 24 | 7 | 70.8% |
| 365 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 10 | 58.3% | 24 | 10 | 58.3% |
| 370 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 2 | 91.7% | 24 | 2 | 91.7% |
| 371 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 0 | 100.0% |
| 380 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 381 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 382 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 5 | 79.2% | 24 | 5 | 79.2% |
| 383 | 18 | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 11 | 54.2% | 24 | 11 | 54.2% |
| 390 | 22 | 23 | 3 | 87.0% | 23 | 3 | 87.0% | 23 | 6 | 73.9% | 23 | 6 | 73.9% |
| 391 | 32 | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 392 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 18 | 25.0% | 24 | 18 | 25.0% |
| 393 | 45 | 23 | 4 | 82.6% | 23 | 4 | 82.6% | 23 | 16 | 30.4% | 23 | 16 | 30.4% |
| 400 | 44 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 405 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 448 | | 21 | 9 | 57.1% | 21 | 9 | 57.1% | 21 | 6 | 71.4% | 21 | 6 | 71.4% |
| 449 | | 21 | 1 | 95.2% | 21 | 1 | 95.2% | 21 | 3 | 85.7% | 21 | 3 | 85.7% |
| 450 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 460 | | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 461 | 36 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 463 | | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 464 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 467 | | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 488 | | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 499 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 500 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 502 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 503 | | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 12 | 50.0% | 24 | 12 | 50.0% |
| 504 | | 23 | 1 | 95.7% | 23 | 1 | 95.7% | 23 | 9 | 60.9% | 23 | 9 | 60.9% |
| 505 | | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 506 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 23 | 6 | 73.9% | 23 | 6 | 73.9% |
| 507 | Cncld | 24 | 1 | 95.8% | 24 | 1 | 95.8% | 22 | 8 | 63.6% | 22 | 8 | 63.6% |
| 508 | 38 | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 509 | 36 | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 10 | 58.3% | 24 | 10 | 58.3% |
| 511 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 3 | 87.5% | 24 | 3 | 87.5% |
| 516 | 31 | 22 | 4 | 81.8% | 22 | 4 | 81.8% | 21 | 14 | 33.3% | 21 | 14 | 33.3% |

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 517 | | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 10 | 58.3% | 24 | 10 | 58.3% |
| 518 | 19 | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 23 | 11 | 52.2% | 23 | 11 | 52.2% |
| 519 | | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 3 | 86.4% | 22 | 3 | 86.4% |
| 562 | 26 | 22 | 2 | 90.9% | 22 | 2 | 90.9% | 22 | 14 | 36.4% | 22 | 14 | 36.4% |
| 564 | 58 | 22 | 0 | 100.0% | 22 | 0 | 100.0% | 22 | 14 | 36.4% | 22 | 14 | 36.4% |
| 566 | 69 | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 20 | 11 | 45.0% | 20 | 11 | 45.0% |
| 567 | | 22 | 3 | 86.4% | 22 | 3 | 86.4% | 21 | 7 | 66.7% | 21 | 7 | 66.7% |
| 572 | 56 | 19 | 6 | 68.4% | 19 | 6 | 68.4% | 18 | 14 | 22.2% | 18 | 14 | 22.2% |
| 573 | 39 | 22 | 2 | 90.9% | 22 | 2 | 90.9% | 22 | 11 | 50.0% | 22 | 11 | 50.0% |
| 579 | 45 | 19 | 1 | 94.7% | 19 | 1 | 94.7% | 18 | 12 | 33.3% | 18 | 12 | 33.3% |
| 580 | 16 | 22 | 2 | 90.9% | 22 | 2 | 90.9% | 21 | 11 | 47.6% | 21 | 11 | 47.6% |
| 581 | 84 | 22 | 10 | 54.5% | 22 | 10 | 54.5% | 20 | 16 | 20.0% | 20 | 16 | 20.0% |
| 584 | 31 | 22 | 3 | 86.4% | 22 | 3 | 86.4% | 20 | 18 | 10.0% | 20 | 18 | 10.0% |
| 587 | 123 | 22 | 5 | 77.3% | 22 | 5 | 77.3% | 20 | 15 | 25.0% | 20 | 15 | 25.0% |
| 588 | 46 | 19 | 3 | 84.2% | 19 | 3 | 84.2% | 18 | 11 | 38.9% | 18 | 11 | 38.9% |
| 591 | 34 | 22 | 5 | 77.3% | 22 | 5 | 77.3% | 22 | 16 | 27.3% | 22 | 16 | 27.3% |
| 593 | 68 | 17 | 8 | 52.9% | 17 | 8 | 52.9% | 14 | 7 | 50.0% | 14 | 7 | 50.0% |
| 595 | 72 | 18 | 11 | 38.9% | 18 | 11 | 38.9% | 18 | 15 | 16.7% | 18 | 15 | 16.7% |
| 600 | | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 3 | 86.4% | 22 | 3 | 86.4% |
| 607 | | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 1 | 95.5% |
| 626 | | 22 | 5 | 77.3% | 22 | 5 | 77.3% | 22 | 4 | 81.8% | 22 | 4 | 81.8% |
| 643 | | 22 | 6 | 72.7% | 22 | 6 | 72.7% | 22 | 3 | 86.4% | 22 | 3 | 86.4% |
| 645 | | 22 | 6 | 72.7% | 22 | 6 | 72.7% | 22 | 3 | 86.4% | 22 | 3 | 86.4% |
| 647 | | 21 | 3 | 85.7% | 21 | 3 | 85.7% | 21 | 1 | 95.2% | 21 | 1 | 95.2% |
| 649 | | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 4 | 81.8% | 22 | 4 | 81.8% |
| 650 | | 22 | 4 | 81.8% | 22 | 4 | 81.8% | 22 | 2 | 90.9% | 22 | 2 | 90.9% |
| 652 | | 22 | 2 | 90.9% | 22 | 2 | 90.9% | 22 | 1 | 95.5% | 22 | 1 | 95.5% |
| 655 | | 22 | 3 | 86.4% | 22 | 3 | 86.4% | 22 | 2 | 90.9% | 22 | 2 | 90.9% |
| 656 | | 22 | 4 | 81.8% | 22 | 4 | 81.8% | 22 | 5 | 77.3% | 22 | 5 | 77.3% |
| 658 | | 21 | 1 | 95.2% | 21 | 1 | 95.2% | 21 | 1 | 95.2% | 21 | 1 | 95.2% |
| 661 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 662 | 37 | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 664 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 667 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 690 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 691 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 692 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 693 | 16 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 694 | 20 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 695 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 696 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 697 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 698 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 701 | 41 | 24 | 4 | 83.3% | 24 | 4 | 83.3% | 24 | 7 | 70.8% | 24 | 7 | 70.8% |
| 702 | 30 | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 13 | 45.8% | 24 | 13 | 45.8% |
| 703 | | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 5 | 79.2% |
| 704 | | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 3 | 87.5% | 24 | 3 | 87.5% |
| 710 | 29 | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 711 | | 24 | 3 | 87.5% | 24 | 3 | 87.5% | 20 | 2 | 90.0% | 20 | 2 | 90.0% |
| 712 | | 24 | 8 | 66.7% | 24 | 8 | 66.7% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 713 | Cncld | 22 | 8 | 63.6% | 22 | 8 | 63.6% | 17 | 5 | 70.6% | 17 | 5 | 70.6% |
| 714 | 38 | 24 | 12 | 50.0% | 24 | 12 | 50.0% | 23 | 14 | 39.1% | 23 | 14 | 39.1% |
| 715 | | 24 | 5 | 79.2% | 24 | 5 | 79.2% | 23 | 13 | 43.5% | 23 | 13 | 43.5% |
| 716 | 118 | 23 | 13 | 43.5% | 23 | 13 | 43.5% | 22 | 6 | 72.7% | 22 | 6 | 72.7% |
| 717 | 47 | 24 | 11 | 54.2% | 24 | 11 | 54.2% | 21 | 9 | 57.1% | 21 | 9 | 57.1% |
| 718 | | 24 | 14 | 41.7% | 24 | 14 | 41.7% | 24 | 9 | 62.5% | 24 | 9 | 62.5% |
| 719 | | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 720 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 723 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 724 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 727 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 728 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 729 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 732 | | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 733 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 734 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 736 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 737 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 738 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 741 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 742 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 743 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 744 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 745 | 77 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 746 | 28 | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 747 | 20 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 748 | 28 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 749 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 751 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 757 | 155 | 22 | 0 | 100.0% | 22 | 0 | 100.0% | 22 | 12 | 45.5% | 22 | 12 | 45.5% |
| 761 | 58 | 22 | 0 | 100.0% | 22 | 0 | 100.0% | 22 | 9 | 59.1% | 22 | 9 | 59.1% |
| 765 | 31 | 22 | 0 | 100.0% | 22 | 0 | 100.0% | 22 | 14 | 36.4% | 22 | 14 | 36.4% |
| 769 | 77 | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 16 | 27.3% | 22 | 16 | 27.3% |
| 770 | 54 | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 21 | 14 | 33.3% | 21 | 14 | 33.3% |

## Amtrak On Time Performance

Trains Arriving Through: 10/24/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 774 | 45 | 22 | 7 | 68.2% | 22 | 7 | 68.2% | 21 | 18 | 14.3% | 21 | 18 | 14.3% |
| 777 | 36 | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 21 | 17 | 19.0% | 21 | 17 | 19.0% |
| 782 | 52 | 22 | 17 | 22.7% | 22 | 17 | 22.7% | 21 | 17 | 19.0% | 21 | 17 | 19.0% |
| 785 | 22 | 22 | 11 | 50.0% | 22 | 11 | 50.0% | 22 | 14 | 36.4% | 22 | 14 | 36.4% |
| 786 | 98 | 22 | 8 | 63.6% | 22 | 8 | 63.6% | 18 | 13 | 27.8% | 18 | 13 | 27.8% |
| 790 | 55 | 22 | 1 | 95.5% | 22 | 1 | 95.5% | 22 | 15 | 31.8% | 22 | 15 | 31.8% |
| 794 | 29 | 22 | 12 | 45.5% | 22 | 12 | 45.5% | 22 | 13 | 40.9% | 22 | 13 | 40.9% |
| 821 | 39 | 23 | 1 | 95.7% | 23 | 1 | 95.7% | 23 | 19 | 17.4% | 23 | 19 | 17.4% |
| 822 | 24 | 23 | 2 | 91.3% | 23 | 2 | 91.3% | 23 | 22 | 4.3% | 23 | 22 | 4.3% |
| 1019 | | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| 1020 | | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| 1040 | | 8 | 2 | 75.0% | 8 | 2 | 75.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| 1041 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 1071 | | 8 | 6 | 25.0% | 8 | 6 | 25.0% | 8 | 4 | 50.0% | 8 | 4 | 50.0% |
| 1078 | | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 8 | 3 | 62.5% | 8 | 3 | 62.5% |
| 1079 | | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| 1080 | | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| 1090 | | 8 | 1 | 87.5% | 8 | 1 | 87.5% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| 1094 | | 8 | 3 | 62.5% | 8 | 3 | 62.5% | 8 | 3 | 62.5% | 8 | 3 | 62.5% |
| 1095 | | 8 | 3 | 62.5% | 8 | 3 | 62.5% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| 1097 | | 8 | 4 | 50.0% | 8 | 4 | 50.0% | 8 | 1 | 87.5% | 8 | 1 | 87.5% |
| 1098 | 40 | 8 | 0 | 100.0% | 8 | 0 | 100.0% | 8 | 3 | 62.5% | 8 | 3 | 62.5% |
| 1128 | | 10 | 2 | 80.0% | 10 | 2 | 80.0% | 10 | 1 | 90.0% | 10 | 1 | 90.0% |
| 1169 | | 9 | 3 | 66.7% | 9 | 3 | 66.7% | 9 | 2 | 77.8% | 9 | 2 | 77.8% |
| 1179 | | 8 | 5 | 37.5% | 8 | 5 | 37.5% | 8 | 0 | 100.0% | 8 | 0 | 100.0% |
| 1180 | | 8 | 5 | 37.5% | 8 | 5 | 37.5% | 8 | 6 | 25.0% | 8 | 6 | 25.0% |
| 1333 | 32 | 24 | 2 | 91.7% | 24 | 2 | 91.7% | 24 | 6 | 75.0% | 24 | 6 | 75.0% |
| 1340 | | 24 | 0 | 100.0% | 24 | 0 | 100.0% | 24 | 4 | 83.3% | 24 | 4 | 83.3% |
| 1594 | 67 | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% | 1 | 1 | 0.0% |
| 1697 | | 2 | 0 | 100.0% | 2 | 0 | 100.0% | 2 | 1 | 50.0% | 2 | 1 | 50.0% |
| 2201 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2203 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 2205 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2216 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 2218 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 2220 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 2248 | 24 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2249 | 16 | 4 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 2250 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 2251 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 2252 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 2255 | 18 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |

## Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/24/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 2248 | NYP | 24 | SMW | 38 | SMW | 34 | NWK-NYP | AM | Scheduled in track usage program, Other, XHU-XHU, HELD A/C TOL NO.2 TRK SWIFT INT |
| 2249 | WAS | 16 | SMW | 43 | SMW | 28 | NYP-NWK | AM | Scheduled in track usage program, Other, XPT-XHU, TOL AT SWIFT |
| 2255 | WAS | | OTH | 14 | OTH | 5 | PHL-WIL | AM | Lost time - N.A.R., PRT |
| 126 | NYP | 41 | CAR | 48 | CAR | 48 | WAS-WAS | AM | Door, 82665\|AX\|AS, 82665 DOOR ISSUE |
| 140 | SPG | 64 | SVS | 55 | SVS | 55 | NHV-NHV | AM | Planned Switch, AM140 will dp NHV late a/c e/93 being taken off of AM467 |
| 143 | NHV | 31 | ENG | 10 | ENG | 10 | SPG-WNL | AM | Other electrical failure, 93\|DX\|BD, CAB Signal drop to Restricting between MP 57.5 and MP 56.25. |
| 400 | GFD | 44 | | | | | | | |
| 461 | NHV | 36 | SMW | 6 | SMW | 6 | STS-NHV | AM | Diversions around M/W work, Milepost, sts, nhv, Made a reverse move between Stat St. and Division post |
| 52 | LOR | 111 | FTI | 89 | FTI | 85 | XOU-XFL | CS | Stopped behind disabled freight 410 M410, Control Point, Ashley River |
| 53 | SFA | 61 | FTI | 95 | FTI | 25 | XSE-XFL | CS | Follow I031, Milepost, 255.0, 281.5 |
| 662 | NYP | 37 | SMW | 34 | SMW | 19 | NWK-NYP | AM | Scheduled in track usage program, Other, NWK-XPT, CONGESTION A/C TOL NO.2 TRK SWIFT INT |
| 693 | BRK | 16 | PTI | 13 | PTI | 13 | EXR-DHM | CS | Meet 694, Control Point, Rockingham |
| 694 | BON | 20 | DCS | 11 | PTI | 10 | FRE-POR | CS | Meet amt 691, Control Point, Allen |
| 68 | NYP | 47 | FTI | 110 | FTI | 68 | SAR-SAR | DH | Follow Wait for 228 to clear at SAR yard, Other, SAR Yard, 228 |
| 233 | ALB | 35 | CTI | 25 | CTI | 20 | CRT-POU | MN | Follow MNRR, 8819, Control Point, 29, Control Point, 72 |
| 235 | ALB | 118 | DCS | 110 | DCS | 51 | YNY-CRT | MN | Cab signal or ATS failure (wayside) Milepost, 15.2, 33.3 |
| 237 | ALB | 38 | PTI | 37 | PTI | 24 | CRT-POU | MN | Follow 235 had failed cabs. Followed them from 46-POU, 235, Control Point, CP 46 |
| 291 | BTN | 71 | FTI | 86 | FTI | 86 | XSY-SAR | DH | Cross Traffic 228, Control Point, 33 |
| 49 | CHI | 56 | FTI | 99 | MBO | 27 | XH6-XTF | NS | For maritime traffic Control Point, 21 |
| 43 | PGH | 18 | SMW | 26 | SMW | 26 | NYP-NWK | AM | Scheduled in track usage program, Other, XPT-XPT, HELD A/C TOL NO.2 TRK SWIFT INT |

## Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/24/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 74 | RGH | 19 | SYS | 17 | SYS | 17 | SAL-HPT | NS | Unscheduled passenger stop Special stop at Lexington., Milepost, 316.5, 316.5 |
| 77 | CLT | 36 | PTI | 40 | PTI | 25 | HPT-SAL | NS | Meet #Amtk76, Siding, Lake |
| 1098 | NYP | 40 | SMW | 48 | SMW | 44 | NWK-NYP | AM | Scheduled in track usage program, Other, NWK-XPT, CONGESTION A/C TOL NO.2 TRK SWIFT INT |
| 40 | CHI | | CON | 93 | CON | 93 | PGH-PGH | NS | Hold for bus with passengers from train AMT 43 had a service disruption due to freight derailment. Waited for connections. |
| 25 | NOL | 69 | FTI | 99 | FTI | 44 | BAS-XNO | CS | Follow 605, Milepost w/Letters, Bay Saint Louis, Paris Rd |
| 26 | MOE | 68 | FTI | 93 | FTI | 30 | BIX-PAG | CS | Meet 801, Siding, ocean springs |
| 745 | SJC | 77 | TRS | 85 | TRS | 85 | OKJ-OAC | UP | Trespasser strike Milepost, 11.8, 11.9 |
| 746 | SAC | 28 | PTI | 46 | PTI | 42 | HAY-OAC | UP | 745 had a trespasser strike, we held at coliseum 745, Control Point, coliseum |
| 747 | SJC | 20 | POL | 30 | POL | 30 | OKJ-OAC | UP | Right of Way police hold Hold at East Oakland |
| 748 | SAC | 28 | ITI | 35 | ITI | 35 | SJC-SJC | UP | Late departure at initial terminal due to late arrival of inbound equipment 745, Involved in earlier trespasser strike |
| 507 | EUG | Trn Cancelled | ENG | 36 | ENG | 36 | CTL-CTL | BN | Failure of diesel engine WS1407 |
| 508 | SEA | 38 | PTI | 45 | PTI | 21 | VAN-KEL | BN | Meet amtk 509, Control Point, kelso south |
| 509 | PDX | 36 | PTI | 36 | PTI | 36 | OLW-CTL | BN | Meet Held at wabash for 506 due to disabled 507 sitting on main one at CTL, 506, Control Point, wabash |
| 516 | VAC | 31 | MBO | 27 | MBO | 27 | XF2-X1J | BN | For maritime traffic Bridge, Fraser River Br |
| 518 | VAC | 19 | DSR | 20 | RTE | 11 | XF2-X1J | BN | Insufficient run time Control Point, spruce |
| 58 | CHI | 33 | DSR | 58 | DSR | 25 | MAT-CHM | CC | Per bulletin Milepost, 163.5, 156.0, 60, all tracks, Milepost, 162.4, 161.26, 25, main, Milepost, 160.5, 150.7, 25, main one and turnout south tuscola, Milepost, 133.4, 132.2, 30, main |
| 59 | NOL | 67 | DSR | 111 | FTI | 29 | MEM-MEM | CC | Cross Traffic Held while three westbound trains passed, BNSF, Control Point, CN Junction |
| 14 | SEA | 178 | RTE | 155 | RTE | 135 | SBA-SLO | UP | Dispatcher hold Held for spacex rocket launch, Control Point, north gaviota |

## Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/24/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 821 | FTW | 39 | FTI | 35 | FTI | 32 | GLE-FTW | BN | Meet BN 4065, BN Freight, BN 4274, Siding, Metro, Siding, Ponder, Siding, Haslet |
| 822 | OKC | 24 | DSR | 26 | DSR | 22 | FTW-GLE | BN | Per bulletin Milepost, 347.5, 347.9, 25, 1, Milepost, 349.6, 350.1, 25, 1, Milepost, 350.3, 350.4, 30, xo, Milepost, 350.9, 351.3, 60, 2, Milepost, 351.5, 352.3, 60, 2, Milepost, 352.8, 353.3, 60, 2, Milepost, 353.5, 354.1, 60, 2, Milepost, 354.7, 355.2, 60, 2, Milepost, 355.1, 355.6, 60, 2, Milepos |
| 330 | CHI | Trn Cancelled | | | | | | | |
| 331 | MKE | Trn Cancelled | | | | | | | |
| 335 | MKE | 24 | SVS | 17 | SVS | 15 | CHI-CHI | AM | Dropped off the set used for 330/331 (annulled due to mechanical issues) on track 19, proceeded to track 30 to board passengers. Took some time to make extra move. |
| 338 | CHI | 32 | ITI | 26 | ITI | 26 | MKE-MKE | CP | Late departure at initial terminal due to late arrival of inbound equipment 335 |
| 339 | MKE | 16 | PTI | 13 | PTI | 13 | XRO-SVT | CP | Meet 1340, Control Point, truesdale |
| 350 | PNT | 36 | FTI | 28 | PTI | 20 | XB0-XA5 | MI | Meet 353, Siding, Albion |
| 351 | CHI | 37 | DSR | 21 | DSR | 14 | PNT-TRM | CC | Per bulletin Milepost, 28.6, 16.94, 30, m1 |
| 352 | PNT | 22 | DSR | 20 | TRS | 15 | ARB-DER | MI | Vandalism Shopping cart on track, Milepost, 26.5, 26.5 |
| 354 | PNT | 47 | ITI | 48 | ITI | 48 | CHI-CHI | AM | Late departure at initial terminal due to late arrival of inbound equipment 353 |
| 355 | CHI | 227 | SVS | 119 | SVS | 117 | PNT-PNT | CC | Switch private or office cars |
| 562 | SAN | 26 | DCS | 37 | DCS | 27 | SNC-X98 | SC | Restrictive signal(s) from known wayside signal failure Dark, Control Point, pier |
| 564 | SAN | 58 | CTI | 42 | CTI | 33 | SNC-SNP | SC | Meet Scax, ML 1661, Control Point, Serra |
| 566 | SAN | 69 | PTI | 45 | PTI | 30 | SNC-SNP | SC | Meet 769, Control Point, serra |
| 572 | SAN | 56 | CTI | 29 | CTI | 15 | OSD-OSD | SN | Follow nctd, Control Point, escondido |
| 573 | LAX | 39 | CTI | 31 | DCS | 11 | OSD-X98 | SC | Restrictive signal(s) from known wayside signal failure Dark, Control Point, songs |
| 579 | LAX | 45 | CTI | 52 | CTI | 42 | OSD-X98 | SN | Follow metrolink, Control Point, songs |
| 580 | SAN | 16 | WTR | 11 | WTR | 6 | SNP-X98 | SC | Flood / washout Flagging, Control Point, pier |

## Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/24/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 581 | LAX | 84 | CTI | 25 | ITI | 23 | SAN-SAN | SN | Late departure at initial terminal due to late arrival of inbound equipment 770 |
| 584 | SAN | 31 | CTI | 26 | CTI | 12 | SOL-SOL | SN | Meet Coaster, 687, Control Point, Valley |
| 587 | LAX | 123 | PTI | 87 | PTI | 46 | OSD-X98 | SN | Meet 584, Control Point, Pulgas |
| 588 | SAN | 46 | PTI | 27 | PTI | 12 | SNC-SNP | SC | Follow 786, Control Point, Capistrano, Control Point, Lantern |
| 591 | LAX | 34 | DCS | 32 | DCS | 15 | OSD-X98 | SN | Flagging instructions. Control Point, Songs |
| 593 | LAX | 68 | PTI | 30 | PTI | 15 | OSD-X98 | SN | Meet 588, Control Point, songs |
| 595 | LAX | 72 | PTI | 70 | PTI | 70 | OSD-X98 | SN | Meet 790, Control Point, pulgas |
| 757 | SBA | 155 | POL | 156 | POL | 101 | OXN-OXN | UP | Right of Way police hold CSI investigation, they found a body on the tracks waiting to be released |
| 761 | GTA | 58 | DTR | 27 | DTR | 24 | OXN-VEC | UP | Police activity at 397.85. initial plan was for 757 to tie down set at Oxnard and have us 2 step out of Oxnard. Control Point, CO404, OXN, VEC |
| 765 | GTA | 31 | DCS | 32 | DCS | 17 | OSD-X98 | SC | CTC system failure Control Point, songs |
| 769 | GTA | 77 | DCS | 72 | DCS | 55 | OSD-X98 | SN | Restrictive signal(s) from known wayside signal failure Wait on two s-bound @ Songs: Amtk 564 and Metrolink 1857, Red/stop, Control Point, Songs |
| 770 | SAN | 54 | POL | 113 | POL | 113 | VEC-VEC | UP | Right of Way police hold |
| 774 | SAN | 45 | CON | 51 | CON | 51 | SBA-CPN | UP | Hold for thruway bus Waited for passengers from GTA |
| 777 | GTA | 36 | DCS | 24 | DCS | 13 | OSD-X98 | SN | Restrictive signal(s) from known wayside signal failure Flagging to X98 - 6 min for instructions, 7 min flagging., Stop, Control Point, Songs |
| 782 | SAN | 52 | PTI | 51 | PTI | 24 | VEC-OXN | UP | Meet LATE 769 DUE TO FLAGGING CO 404, AMTK769, Control Point, CO397 |
| 785 | GTA | 22 | PTI | 26 | PTI | 26 | CML-OXN | UP | Meet 794, Control Point, South Oxnard |
| 786 | SAN | 98 | ITI | 43 | ITI | 43 | LAX-LAX | SC | Late departure at initial terminal due to late arrival of inbound equipment 581 |
| 790 | SAN | 55 | RTE | 58 | RTE | 32 | SNC-SNP | SC | Dispatcher hold Track and time established ahead. Then wait for 593 to be flagged through cp songs and cp pier due to high tides., Control Point, serra |
| 794 | SAN | 29 | DCS | 28 | CON | 20 | SBA-SBA | UP | Hold for thruway bus |

## Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/24/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 1594 | VNC | 67 | | | | | | | |
| 701 | SAC | 41 | TEN | 62 | TEN | 29 | MCD-TRK | BN | Loading problem MUX Fault- 'Digital input system failure' message. We got to CP Fluhr on the Stockton Sub and the engine shutdown. Engineer was able to reset breakers and odor went away and same issue started to occur with MUX fault and losing load, C2009 |
| 702 | BFD | 30 | RTE | 32 | RTE | 30 | COC-WAC | BN | Line manual or spring switch Siding, East Corcoran |
| 710 | BFD | 29 | FTI | 33 | FTI | 22 | COC-WAC | BN | Follow 7425 E cleared up in Sandrini, bnsf 7425, Milepost, 950.9, 925.0 |
| 713 | OKJ | Trn Cancelled | TEN | 44 | TEN | 44 | HNF-FNO | BN | Other electrical failure Multiple fault codes, including hep ccu monitoring, fuel indicator system, tractive., C2103 |
| 714 | BFD | 38 | PTI | 33 | TCR | 28 | OKJ-OKJ | UP | Door C9013, Door closes but no door light. Manually shut and closed out |
| 716 | BFD | 118 | TSV | 120 | TSV | 120 | EMY-EMY | UP | Fixing train line door light issues between cab cars |
| 717 | OKJ | 47 | DCS | 42 | FTI | 22 | BFD-WAC | BN | Meet Short on time, bnsf 7425, Control Point, west wasco |
| 3 | LAX | 485 | FTI | 256 | SYS | 171 | FLG-KNG | BN | Re-crew / job briefing Recrew, Other, MP 435 |
| 4 | CHI | 718 | FTI | 606 | FTI | 235 | BAR-NDL | BN | Follow Broken Rail MP 670.4-670.2., BNSF 7121, Milepost w/Letters, East Pisgah, Homer |
| 22 | CHI | 81 | FTI | 171 | FTI | 44 | ARK-MVN | UP | Follow unknown, Milepost, 406, 388.8 |
| 302 | CHI | 24 | FTI | 42 | FTI | 23 | SMT-XTF | CC | Cross Traffic unknown, Control Point, Brighton |
| 305 | STL | 34 | PTI | 31 | PTI | 16 | BNL-BNL | UP | Meet Amtk306, Control Point, BNL |
| 307 | STL | 171 | PTI | 90 | SYS | 89 | JOL-DWT | UP | Blocked by or assisting another, disabled Amtrak train 305 having brake issues at Dwight, Milepost, 73, 73 |
| 383 | QCY | 18 | FTI | 15 | CTI | 10 | LAG-NPV | BN | Follow Metra, 2025, Control Point, Highlands, Control Point, East Naperville |
| 390 | CHI | 22 | DSR | 39 | DSR | 21 | MAT-CHM | CC | Per bulletin Milepost, 160.5, 150.7, 25, all |
| 391 | CDL | 32 | DSR | 32 | PTI | 26 | RTL-CHM | CC | Meet amtrak 390, Control Point, leverette |
| 393 | CDL | 45 | DSR | 28 | DSR | 23 | CHM-MAT | CC | Per bulletin Milepost, 132.2, 133.4, 30, m, Milepost, 150.7, 160.5, 25, m, Milepost, 156, 163.5, 60, All, Milepost, 161.26, 162.4, 25, M |

## Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/24/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 316 | STL | 22 | FTI | 27 | FTI | 8 | SED-JEF | UP | Meet UP, Siding, Shell |
| 319 | KCY | 58 | FTI | 53 | FTI | 26 | SMT-XUD | CC | Cross Traffic unknown, Control Point, canal |
| 1333 | MSP | 32 | FTI | 41 | FTI | 31 | XH8-MSP | CP | Meet Stopped at Oakland for freight, 375, 242, Control Point, Oakland |

## Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/24/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| ALB | 238 | 10/24 | 12 | 12 | Air / Brake 707 |
| ALX | 1179 | 10/24 | 15 | 15 | Held at ALX to fill oil on engine 174 |
| ATL | 19 | 10/23 | 9 | 9 | Blocked from station track Amtrak 19 arrived at train station @ 8:57, Other, Atlanta Station, 24R, 293, 203 |
| BOS | 449 | 10/24 | 2 | 2 | Single tracking on WOR LINE Keolis, 1853, Other, BOS |
| CLT | 72 | 10/24 | 2 | 2 | Late departure at initial terminal due to late arrival of inbound equipment 71 |
| GFD | 461 | 10/24 | 31 | 31 | Police activity |
| HAR | 626 | 10/24 | 1 | 1 | Passenger and/or baggage |
| LOR | 53 | 10/24 | 57 | 57 | DRUMMAC only had 10 drivers and 5 chocker's |
| MTR | 68 | 10/24 | 5 | 5 | Waiting to be unplugged from Shore Power |
| NFK | 1094 | 10/24 | 8 | 8 | Drawbridge stuck open Bridge, Bridge 5 |
| NFL | 284 | 10/24 | 20 | 20 | Inability to contact dispatcher Control Point, 28 |
| NFS | 64 | 10/24 | 8 | 7 | Air / Brake Compressor would not pump after engine put in stand by. Worked with NFL mechanical over radio and cleared fault in computer., 122 |
| NHV | 460 | 10/24 | 4 | 3 | Diversions around M/W work, Milepost, nhv, nhv, Held at NHV a/c track outage |
| NHV | 460 | 10/24 | 4 | 1 | Scheduled in track usage program, Milepost, nhv, nhv, Held at NHV a/c track outage |
| NYP | 43 | 10/24 | 2 | 2 | Passenger and/or baggage, LOADING |
| NYP | 63 | 10/24 | 3 | 3 | Meet, AM230, Other, NYP-NYP, HELD A/C AM230 XING AHEAD |
| NYP | 135 | 10/24 | 8 | 8 | Removal of passenger by police, RELAY CREW INJURED HELD FOR EMS SSYD |
| NYP | 159 | 10/24 | 2 | 2 | Passenger and/or baggage |
| NYP | 239 | 10/24 | 2 | 2 | Passenger and/or baggage |
| NYP | 245 | 10/24 | 10 | 10 | Other late crew, LATE CREW OFF AM68 |
| NYP | 655 | 10/24 | 4 | 6 | Passenger and/or baggage, LOADING |
| NYP | 1097 | 10/24 | 31 | 31 | Water, commissary, toilet/trash dumping, LATE RELEASE FROM THE YARD |
| PGH | 40 | 10/23 | 12 | 11 | Scheduled shove of the train Shove out of station track #4 onto main track #1 to board passengers .., Other, PGH station |
| PHL | 144 | 10/24 | 13 | 13 | Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF YARD. WAITED FOR ENGNE REPAIRS AND LEAVES TO BE CLEARED |
| PHL | 150 | 10/24 | 1 | 1 | Passenger and/or baggage, RED CAP ASSISTANCE |
| PHL | 151 | 10/24 | 1 | 1 | PTC - Stop Bypass Permission Required, Control Point, N. PENN |

## Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/24/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| RGH | 1180 | 10/24 | 5 | 5 | Re-crew / job briefing |
| WAS | 126 | 10/24 | 48 | 48 | Door, 82665\|AX\|AS, 82665 DOOR ISSUE |
| CHI | 7 | 10/24 | 8 | 8 | PTC - Initializing PTC ( no failure) Wrong car count & length,car 10020 was not included, had to CNOC to reconfigure |
| CHI | 59 | 10/24 | 3 | 3 | Wheelchair Multiple wheel chairs and no AC |
| CHI | 331 | 10/24 | (Trn Cxld) | | Engine Issue |
| CHI | 335 | 10/24 | 15 | 15 | Dropped off the set used for 330/331 (annulled due to mechanical issues) on track 19, proceeded to track 30 to board passengers. Took some time to make extra move. |
| CHI | 339 | 10/24 | 9 | 9 | Late departure at initial terminal due to late arrival of inbound equipment 338 |
| MKE | 338 | 10/24 | 26 | 26 | Late departure at initial terminal due to late arrival of inbound equipment 335 |
| PNT | 351 | 10/24 | 12 | 12 | Electrical failure ID4109, ID4303, Doors kept showing open on the engine even after triple checking all doors Mechanical found bad MU cables that connected cars, 4109 and the café car 4303 after replacing the MU cables we talked with CNOC and got the OK to put the doors in bypass to procee |
| PNT | 355 | 10/24 | 117 | 117 | Switch private or office cars |
| STL | 302 | 10/24 | 10 | 10 | Routine inspections Mechanical routine inspection |
| ARN | 729 | 10/24 | 1 | | |
| BFD | 701 | 10/24 | 23 | 23 | Air / Brake Brake pipe pressure was over 3psi. Kept giving us 116psi. And MUX fault was showing on the 2009. Mechanical restarted engine but MUX fault comes on and off and did another Class II but still same issue. Management allowed us to depart with same issues, C2009 |
| BFD | 715 | 10/24 | 7 | 7 | HEP C2012 |
| BFD | 719 | 10/24 | 1 | | |
| EUG | 508 | 10/24 | 17 | 4 | Mobility Impaired Lift required |
| EUG | 508 | 10/24 | 17 | 13 | Follow Amtrak 14, Control Point, Judkins, Control Point, Eug |
| GTA | 774 | 10/24 | (Trn Cxld) | | Police Activity |
| GTA | 782 | 10/24 | 8 | 8 | Meet Late 785 due to flagging CO 404, AMTK765, Control Point, S ELLWOOD |
| GTA | 786 | 10/24 | 16 | 16 | PTC problem or failure (cause unknown) PTC was successfully engaged shortly after arriving into Elwood on 765, while changing ends and preparing for 786. However, as we tried to go south at 14:30 we had no load and PTC was disengaged. We reported the error code and then flipped the breakers., Siding |
| LAX | 562 | 10/24 | 1 | 1 | Wheelchair Last minute power wheelchair stuck on ramp |
| LAX | 794 | 10/24 | 31 | 31 | Hold for thruway bus |
| OKJ | 712 | 10/24 | 7 | 7 | Routine inspections CDTX 2013 shut down. No power. No air. Had to start and get everything built up. |

## Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/24/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| OKJ | 714 | 10/24 | 28 | 28 | Door C9013, Door closes but no door light. Manually shut and closed out |
| OKJ | 716 | 10/24 | (Trn Cxld) | | Cab Car Issue |
| OKJ | 732 | 10/24 | 1 | | |
| SAC | 704 | 10/24 | 10 | 7 | Air / Brake C2009 |
| SAC | 704 | 10/24 | 10 | 3 | Door C9016 |
| SAN | 567 | 10/24 | 1 | 1 | Door 6414, Door 5 not closing properly. Conductors needed to manually close in order to get door circuit. |
| SAN | 581 | 10/24 | 23 | 23 | Late departure at initial terminal due to late arrival of inbound equipment 770 |
| SAN | 593 | 10/24 | 12 | 12 | Late departure at initial terminal due to late arrival of inbound equipment 782 |
| SAN | 785 | 10/24 | 4 | 4 | Late departure at initial terminal due to late arrival of inbound equipment 774 |
| SEA | 511 | 10/24 | 1 | 1 | Rounding error, departed on time at 1950 |
| SJC | 748 | 10/24 | 35 | 35 | Late departure at initial terminal due to late arrival of inbound equipment 745, Involved in earlier trespasser strike |
| SLO | 1594 | 10/24 | (No OS) | | |

# Eastern Region

## Commuter Services

| Service Type | OTP Goal | OTP Day | OTP MTD | OTP Prior Month | Trains Operated | Trains Late |
|---|---|---|---|---|---|---|
| MBTA | 95.0 | 100.0 | 99.33 | 99.14 | No Data | No Data |
| CDOT | 95.0 | No Data | No Data | 92.4 | No Data | No Data |
| MARC | 95.0 | 89.7 | 87.2 | 90.2 | 58 | 6 |
| SEPTA | 95.0 | 97.4 | 93.7 | 93.7 | 215 | 11 |
| NJT-NED | 95.0 | 97.5 | 91.1 | 88.6 | 200 | 5 |
| NJT-SED | 95.0 | 100.0 | 98.7 | 97.2 | 24 | 0 |

## Operating Highlights

### *Train 140(24) New Haven, CT - Program Move*

24OCT26: Train 140(24), with engine 93, 8 cars, and 107 customers onboard, was delayed at New Haven, CT/MP72.3 on the MNRR New Haven Line subdivision due to delays adding engine 93 off train 467(24). This was a program move. Once the equipment was made up complete, train 140(24) departed New Haven.

| Train | Delay | Comment |
|---|---|---|
| 140(24) | 55" | |

### *Train 448(23) West of Worcester, MA - Signal Failure*

24OCT26: Train 448(23), with 67 customers onboard, was delayed at control point 46/MP46.0, 1.8 miles west of Worcester, MA/MP44.2, on the CSX Boston subdivision due to a power switch failure. Once clear of the affected area, train 448(23) continued east.

| Train | Delay | Comment |
|---|---|---|
| 44(23) | 33" | |

### *Train 291(24) West of Saratoga Springs, NY - Freight Train Interference*

24OCT26: Train 291(24), with 82 customers onboard, was delayed at Ballston siding/MP32.9, 4.2 miles west of Saratoga Springs, on the Canadian Pacific Canadian subdivision meeting CP freight 228. CP 228 was shoving back into the Saratoga Yard. Once the route was open, train 291(24) continued east. Train 68(24) was also delayed by CP 228 on main track.

| Train | Delay | Comment |
|---|---|---|
| 291(24) | 1'26" | |
| 68(24) | 1'08" | |

### *Train 53(24) Lorton, VA - Initial Terminal Delay*

24OCT26: Train 53(24) operating with engines 348, 511, 354, 49 cars, and 511 customers onboard was delayed departing Lorton, VA on the CSX RF&P subdivision due to turn of late equipment and a shortage of Drummac drivers. Once the train was loaded and boarded, Train 53(24) departed the station at 4:57 PM-ET.

## *Train 1040(24) Tampa, FL - Trespasser Incident*

24OCT26: Train 1040(24) operating with engines 171, 182, 6 cars, and 144 customers onboard struck a trespasser while shoving back into Tampa Station on the CSX Tampa Terminal subdivision. The strike did not occur at a crossing. The trespasser got up and ran away. There were no reported injuries to the crew or customers. Police responded to the scene and released the train. Crew did not request relief.

| Train | Delay | Comment |
|---|---|---|
| 1040(24) | 58" | |

## *Train 126(24) Washington, DC - Initial Terminal Delay - Car Failure*

24OCT26: Train 126 operating with engine 628, 6 cars, cab car 9634, and 240 customers was delayed departing Washington, DC on the Amtrak WT Line due to a door issue on car 82665. Mechanical responded to the train and was able to close and secure the door. The train departed the station at 4:46 PM-ET.

| Train | Delay | Comment |
|---|---|---|
| 126(24) | 48" | |

## *Train 1097(24) New York, NY - Servicing*

24OCT26: Train 1097(24) operating with engine 660, 10 cars, engine 608, and 325 customers was delayed departing New York, NY on the Amtrak NYT Line due to late release from the yard. The train was delayed departing the yard due to a report of an unattended bag. Once the train was released, Train 1097 advanced into the station to be boarded and departed.

| Train | Delay | Comment |
|---|---|---|
| 1097(24) | 31" | |

## *Train 235(24) New York, NY - Cab Signal Failure*

24OCT26: Train 235(24), with engines 105 and 703, 5 cars, and 162 customers onboard, was delayed beginning at control point 12/MP11.8, 3.4 miles north of Yonker, NY/MP15.2, on the Metro North Hudson Line subdivision due to intermittent loss of cab signals. The delays continued for 235(24) throughout the run to Albany, NY/MP142.1.

| Train | Delay | Comment |
|---|---|---|
| 235(24) | 2'01" | |

## *NYP Line Swift Interlocking Track Occupancy Light - Signal*

24OCT26: At 10:19 AM-ET, A track occupancy light was reported on track two at Swift Interlocking on the Amtrak NYP Line. It was reported that the number 32 switch was locked out due to a work train in the out of service section. Trains scheduled to operate through the area saw delays due to the dispatcher needing to give permission through the area.

At 11:27 AM-ET, it was reported that the work train had been moved and the track occupancy light was cleared.

| Train | Delay | Comment |
|---|---|---|
| 2249(24) | 28" | |
| 662(24) | 34" | |
| 127(24) | 28" | |
| 2248(24) | 34" | |
| 1098(24) | 44" | |
| 43(24) | 26" | |

## *Train 57(24) White River Junction, VT - Debris*

24OCT26: Train 57(24), with engine 101, 6 cars, and 80 customers onboard, struck at tree at mile post 27.4, 13 miles north of White River Junction, VT/MP14.8 on the New England Central Railroad Palmer subdivision. The equipment advanced to White River Junction and stopped to inspect for a possible air leak. Once the equipment completed a successful air test, train 57(24) continued south.

| Train | Delay | Comment |
|---|---|---|
| 57(24) | 08" | |

## *Washington Terminal 'A' Interlocking - Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, Northeast Regional Services - M of W Work*

05OCT26: Due to Diamond Replacement at Washington Terminal 'A' interlocking from Friday, October 16, 2026 to Monday, October 26,2026. There will be several service adjustments made to the following services Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services will be adjusted as follows:

PALMETTO
Northbound
- Train 90 (16Oct-26Oct) is canceled in its entirety.
- Train 1090 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between SAV and WAS.

Southbound
- Train 89 (15Oct-25Oct) is canceled in its entirety.
- Train 1089 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and SAV.

CARDINAL
Eastbound
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct), which normally operates between CHI and NYP, will terminate at IND.

Westbound
- Train 51 (18Oct, 21Oct, 23Oct, 25Oct), which normally operates between NYP and CHI, will originate at IND.

EQUIPMENT
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct) will turn for Train 51 (18Oct, 21Oct, 23Oct, 25Oct) at IND.
  - (Note: Train 51's departure days from IND are 19Oct, 22Oct, 24Oct, and 26Oct)

CRESCENT
Northbound
- Train 20 (16Oct-25Oct), which normally operates between NOL and NYP, will terminate at ATL.
- Train 1020 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between ATL and WAS.

Southbound
- Train 19 (16Oct-25Oct), which normally operates between NYP and NOL, will originate at ATL.
- Train 1019 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and ATL.

EQUIPMENT
- Train 20 (16Oct-25Oct) will turn for Train 19 (16Oct-25Oct) at ATL.
  - (Note: Train 19's departure days from ATL are 17Oct-26Oct)

SILVER METEOR
Northbound

- There will be no service between JAX and WAS.

Southbound

- Train 97 (16Oct-25Oct), which normally operates between NYP and MIX, will originate at JAX.
- Train 1097 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and JAX.

EQUIPMENT

- Train 98 (16Oct-25Oct) will turn for Train 97 (16Oct-25Oct) at JAX.
  - (Note: Train 97's departure days from JAX are 17Oct-26Oct)

FLORIDIAN

Northbound

- Train 40 (16Oct-24Oct), which normally operates between MIA and CHI, will originate at PGH.
- Train 1040 (17Oct-24Oct) will operate and provide service between MIA and JAX.
- There will be no service between JAX and PGH.

Southbound

- Train 41 (16Oct-24Oct), which normally operates between CHI and MIA, will terminate at PGH.
- Train 1041 (18Oct-25Oct) will operate and provide service between JAX and MIA.
- There will be no service between PGH and JAX.

EQUIPMENT

- Train 41 (16Oct-24Oct) will turn for Train 40 (16Oct-24Oct) at PGH
  - (Note: Train 40's departure days from PGH are 17Oct-25Oct)
- Train 1040 (17Oct-24Oct) will turn for Train 1041 (18Oct-25Oct) at JAX

CAROLINIAN

Northbound

- Train 80 (17Oct-25Oct), which normally operates between CLT and NYP, will terminate at RGH.
- Train 1180 (17Oct-25Oct) is a new train that will operate between RGH and ALX, departing RGH at 11:00am.
- Train 1080 (17Oct-25Oct) is a new train that will operate between WAS and NYP, departing WAS at 5:15pm.

Southbound

- Train 79 (17Oct-25Oct), which normally operates between NYP and CLT, will originate at RGH.
- Train 1079 (17Oct-25Oct) is a new train that will operate between NYP and WAS, departing NYP at 7:05am.
- Train 1179 (17Oct-25Oct) is a new train that will operate between ALX and RGH, departing ALX at 1:00pm.

ALTERNATE TRANSPORTATION

- Train 1180 (17Oct-25Oct) will connect to Bus 1480 (17Oct-25Oct) at ALX
- Train 1079 (17Oct-25Oct) will connect to Bus 1479 (17Oct-25Oct) at WAS

EQUIPMENT

- Equipment for Train 1180 will deadhead on the rear of Train 79(16Oct) and will be cut in RGH
- Train 1179 (17Oct-24Oct) will turn at RGH for Train 1180 (18Oct-25Oct)
- Train 1179 (25Oct) will turn at RGH for Deadhead Train 80 to operate to WAS
- Northeast Regional Train 1094 (17Oct-25Oct) will make a same day turn at ALX for Train 1179 (17Oct-25Oct)
- Train 80 (17Oct-25Oct) will make a same day turn at RGH for Train 79 (17Oct-25Oct)

NORTHEAST REGIONAL

Norfolk

- Train 1094 (17Oct-25Oct) will operate between NFK and ALX
- Train 1095 (17Oct-25Oct) will operate between ALX and NFK

Roanoke

- Train 1071 (17Oct-25Oct) will operate between ALX and RNK
- Train 1078 (17Oct-25Oct) will operate between RNK and ALX

Newport News

- Train 65 (16OCt), which normally operates between BOS and NPN, will terminate at PHL.

- Train 67 (25Oct), which normally operates between BOS and NPN, is canceled in entirety with no alternate transportation.

ALTERNATE TRANSPORTATION

- Bus 1495 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1095 (17Oct-25Oct) at ALX
- Train 1094 (17Oct-25Oct) will connect to Bus 1494 (17Oct-25Oct) at ALX
- Bus 1471 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1071 (17Oct-25Oct) at ALX
- Train 1078 (17Oct-25Oct) will connect to Bus 1478 (17Oct-25Oct) at ALX
- Bus 1454 (17-Oct- 25Oct) will operate RNK - LYH - WAS.
- Bus 1455 (17-Oct- 25Oct) will operate WAS - LYH - RNK.
- Bus 1456 (17-Oct- 25Oct) will operate CVS - WAS
- Bus 1457 (17-Oct- 25Oct) will operate WAS - CVS

***ALX-WAS Buses will unload in front of Union Station utilizing the middle lane of Columbus Circle, with WAS-ALX buses boarding up on the Union Station bus deck***

EQUIPMENT

- Carolinian Train 1180 (17Oct-25Oct) will make a same day turn at ALX for Train 1071 (17Oct-25Oct)
- Train 1071 (17Oct-24Oct) will turn for Train 1078 (18Oct-25Oct) at RNK
- Train 1071 (25Oct) will turn for Train 156(26Oct) at RNK
- Train 1078 (17Oct-25Oct) will make a same day turn at ALX for Train 1095 (17Oct-25Oct)
- Train 1095 (17Oct-24Oct) will turn for Train 1094 (18Oct-25Oct) at NFK
- Train 1095 (25Oct) will turn for Train 94 (26Oct) at NFK

**WBS#: B.TR.100151.0856**

# Maintenance of Way Highlights

## *CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work*

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

**WBS#: B.TR.100150.6692**

## *Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork*

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:
- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION
- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

**WBS#: B.TR.100150.6530**

# Eastern Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| None | | | | |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| None | | | | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Eastern Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| | Projected Need | | Number Operated | | | |
|---|---|---|---|---|---|---|
| Train | Cars | Seats | Cars | Seats | Standees | Location |
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

# Western Region
# Operating Highlights

## *Train 745(24) Oakland, CA - Trespasser Incident*

25OCT26: Train 745(24), operating with Engine 2010, 5 coaches, and 41 customers, struck a trespasser at Oakland, CA Coliseum Airport station (MP 11.9) on the Union Pacific Niles Subdivision. The strike was non-fatal, and the trespasser reportedly walked away from the scene. The operating crew did not request relief, and no injuries to crew members or customers were reported. No equipment damage was reported. Local law enforcement responded, and the train was held pending release of the scene. During the incident, Union Pacific also reported a vehicle fire at MP 11.62, resulting in additional traffic delays. Train 745(24) was released and departed Oakland, CA Coliseum Airport station at 7:25P-PT, operating 1 hour and 30 minutes late. Train 746(24) was held outside the station awaiting Train 745(24) to clear.

CA DOT 26-5528

NRC 1476989

| Train | Delay | Comment |
|---|---|---|
| 745(24) | 1'25" | |
| 748(24) | 35" | Late turn of Equipment |
| 746(24) | 42" | Hold for open route |
| 747(24) | 30" | Hold for open route |

## *Train 48/448(24) Elkhart, IN - Engine Failure*

25OCT26: Train 48/448(24) was delayed holding at Elkhart IN station/MP421.6 on the Norfolk Southern Chicago 76 subdivision due to setting off a truck hunting alarm on engine 375. Elkhart mechanical responded to the station to inspect the flange. Mechanical found no issues and train 48/448(24) was released to continue east.

| Train | Delay | Comment |
|---|---|---|
| 48/448(24) | 1'21" | |

## *Train 355(24) East of Ann Arbor, MI - Freight Train Interference*

25OCT26: Train 355(24) was delayed holding at MP18.1, 19.80 miles east of Ann Arbor MI station on the Amtrak Michigan Line meeting CSX cross traffic.

| Train | Delay | Comment |
|---|---|---|
| 355(24) | 45" | |

## *Train 1333(24) West of St. Paul-Minneapolis, MN - Freight Train Interference*

25OCT26: Train 1333(24) was delayed holding at 426.7, 7.51 miles east of St. Paul-Minneapolis, MN. station on the BNSF St. Paul subdivision meeting freight trains 375 and 242.

| Train | Delay | Comment |
|---|---|---|
| 1333(24) | 31" | |

## *Train 22(24) South of Malvern, AR - Freight Train Interference*

25OCT26: Train 22(24) was delayed beginning at MP391, 2.20 miles south of Malvern AR station on the UPRR Little rock subdivision following UPRR freight train 7424. Train 22(24) followed the train until MP388.8.

| Train | Delay | Comment |
|---|---|---|
| 22(24) | 34" | |

## *Train 4(23) Trinidad, CO - Engine Failure*

24OCT26: Train 4(23) with engines 119 and 118, 9 cars and 147 customers was stopped at MP623.8, 21.20 miles east of Trinidad CO station on the BNSF Raton subdivision after engine 19 shut down with train line and high tm field faults. Crew brought head end power down while they troubleshot the faults with mechanical. Crew was able to get the engine restarted and brought head end power back on line. Train 4(23) was back on the move at 858PM MT with engine 19 restarted.

| Train | Delay | Comment |
|---|---|---|
| 4(23) | 45" | |

## *Train 11(24) North of Klamath Falls, OR - Freight Train Interference*

25OCT26: Train 11(24), operating with engines 318/322, 11 coaches, and 107 customers, was delayed 4 miles North of Klamath Falls, OR, on UPRR Cascade subdivision, due to meeting UP2732 and Wocus siding. Once the freight cleared and a route was made available, train 11(24) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 11(24) | 55" | |

## *Train 7/27(23) Whitefish, MT - PTC Reset*

25OCT26: Train 7/27(23), operating with engines 355/18, 10 coaches, and 96 customers, was delayed departing Whitefish, MT, on BNSF Kootenai River subdivision, due to performing a PTC breaker reset. After the reset the the train then had issues with the departure test. Once resolved, Train 7/27(23) was able to depart.

| Train | Delay | Comment |
|---|---|---|
| 7/27(23) | 32" | |

## *Train 26(24) South of Pascagoula, MS - Freight Train Interference*

24OCT26: Train 26(24) was delayed at MP723.1, 16.57 miles south of Pascagoula, MS station on the CSX NO and M subdivision meeting CSX freight train 801. Train 26(24) was back on the move north at 908PM CT.

| Train | Delay | Comment |
|---|---|---|
| 26(24) | 30" | |

## *Train 25(24) Gulfport, MS - Freight Train Interference*

24OCT26: Train 25(24) was delayed departing Gulfport MS station/MP739.38 on the CSX NO and M subdivision following CSX freight train 605. Train 25(24) continued to follow the freight until Paris road/MP796.

| Train | Delay | Comment |
|---|---|---|

## *Train 355(24) Pontiac, MI - Servicing*

24OCT26: Train 355(24) was delayed departing Pontiac MI station/MP25.9 on the CN Holly subdivision adding two private cars to their consist. After the cars were added train 355(24) wyed before arriving to the station. Train 355(24) departed Pontiac MI station at 700PM ET 1'57" late.

Train 354(24) was delayed holding at Kalamazoo, MI station/MP143.3 waiting for train 355(24) to approach Battle Creek MI station. Train 354(24) was back on the move at 1131PM ET.

| Train | Delay | Comment |
|---|---|---|
| 355(24) | 1'57" | |
| 354(24) | 2'52" | |

## *Train 507(24) Centralia, WA - Engine Failure*

25OCT26: At approximately 4pm-pt, Train 507(24), operating with Engine 1407, 4 cars, and 155 customers, experienced a head-end power (HEP) loss at Centralia, WA station on the Burlington Northern Santa Fe Seattle Subdivision. The train crew worked with CNOC Mechanical personnel and Siemens technicians to resolve the issue. HEP was restored; however, Siemens technicians advised that the issue would continue. As a result, Train 507(24) was terminated at Centralia, WA station and returned to Seattle, WA King Street Station for repairs. Train 507(24) arrived back at Seattle, WA King Street Station at 10:24P-PT.
As a result of the mechanical issue, the following service adjustments were implemented:
Customers from Train 507(24) were provided alternate transportation via 3 buses.
Train 504(25) was canceled.
Locomotive BNSF6949 was added to Train 507(24).

| Train | Delay | Comment |
|---|---|---|
| 507(24) | Term CTL | |
| 509(24) | 36" | |

## *Train 716(24) Emeryville, CA - Cab Car Failure*

25OCT26: Train 716(24), operating with Locomotive 2106, 8 cars, and 26 customers, was delayed departing Oakland, CA Jack London Square Station due to door light issues on the equipment. Mechanical personnel worked to resolve the issue; however, the train was annulled from Oakland, CA Jack London Square Station and originated at Emeryville, CA station. Customers at Oakland, CA Jack London Square Station were accommodated on Train 736(24). Train 716(24) departed Emeryville, CA station at 4:28P-PT.

| Train | Delay | Comment |
|---|---|---|
| 716(24) | 2'00" | |

## *Train 702(24) South of Corcoran, CA - Signal*

24OCT26: Train 702(24) operating with locomotive C2108, 7 cars, NPCU 90278 and 136 customers onboard was delated 1 mile south of Corcoran, CA due to having to manually line a switch at East Corcoran. Once the route was line and confirmed train 702(24) was able to proceed at restricted speed until they reached the first permissible signal.

| Train | Delay | Comment |
|---|---|---|
| 702(24) | 30" | |

## *Train 4(23) Albuquerque, NM - System*

24OCT26: Train 4(23), E/19-E/188-9 cars, was delayed departing Albuquerque, NM on the NMRX Glorieta Subdivision due to mechanical addressing issues on E/19. Once an air test was complete on E/19, a noise issues was then addressed. Once all issues were resolved, Train 4(23) departed.

| Train | Delay | Comment |
|---|---|---|
| 4(23) | 49" | |

## *Train 14(24) Ventura, CA - Passenger Train Interference*

24OCT26: Train 14(24) operating with locomotive 343-350, 9 cars and 215 customers onboard was delayed at MP 395 on the UPRR Santa Barbara meeting train 774(24). Once train 774(24) was cleared train 14(24) was able to proceed without further delay.

| Train | Delay | Comment |
|---|---|---|
| 14(24) | 33" | |

## *Train 4(23) Gallup, NM - Freight Train Interference*

24OCT26: Train 4(23) operating with locomotives 19-188, 8 cars, and 162 customers onboard was delayed 70 miles west of Gallup at MP 240 on the BNSF Gallup subdivision by freight train interference following BN236 at MP 240. Once train 4(23) was able to get routed around the freight they were able to return to track speed and operate without further delay.

| Train | Delay | Comment |
|---|---|---|
| 4(23) | 32" | |

## *Train 7/27(23) East of Glasgow, MT - Freight Train Interference*

25OCT26: Train 7/27(23), operating with engines 355/18, 10 coaches, and 98 customers, was delayed 33 miles east of Glasgow, MT, on BNSF Glasgow subdivision, due to following BNSF 5476 between milepost 249.2 and milepost 275.5.

| Train | Delay | Comment |
|---|---|---|
| 7/27(23) | 43" | |

## *Train 701(24) Bakersfield, CA - Engine Failure*

24OCT26: Train 701(24) operating with locomotive C2009, 7 cars, cab car 6963 and 40 customers onboard was delayed at the initial terminal of Bakersfield, CA due to mechanical issues on locomotive C2009. Mechanical inspected and identified an air brake issue with brake pipe pressure of 116 psi and MU faults. Mechanical restarted the locomotive and the MU faults remained. The train was released and crew was instructed to depart Bakersfield. While operating over the road locomotive C2009 began experiencing loading issues and was unable to attain track speed causing delays between station stops. After departing Merced locomotive C2009 displayed MU Faults and "Digital Input System Failure" message and the locomotive shutdown. The crew was able to recycle the breakers and restore the locomotive operations.

| Train | Delay | Comment |
|---|---|---|
| 701(24) | 23" | Initial terminal delay |
| 701(24) | 29" | Locomotive shutdown |
| 701(24) | 10" | Unable to make track speed |

## *Train 713(24) East of Fresno, CA - Third Party Contractor Engine Failure*

24OCT26: At 10:46A-PT, Train 713(24), E/C2103-5 cars-CC/C6965, stopped at MP 993.2, 4 miles east of Fresno, CA, on the BNSF Bakersfield Subdivision due to locomotive issues on E/C2103, losing head end power(HEP). There were 95 customers on board and the ambient outside temperature was 63 degrees and sunny. The crew contacted mechanical to troubleshoot. An Amtrak Road Foreman from Bakersfield, CA responded. At 11:22A-PT, the crew was able to restore HEP. Once HEP was restored and a brake test was complete, Train 713(24) proceeded west.

Due to the late operation of Train 713(24), it was terminated in Emeryville, CA with customers reaccommodated on Train 743(24). Equipment deadheaded into yard for servicing to turn for Train 718(24).

| Train | Delay | Comment |
|---|---|---|
| 713(24) | 44" | |

## *Train 821(24) South of Gainesville, TX - Freight Train Interference*

24OCT26: Train 821(24) was delayed 23.9 miles south of Gainesville, TX (MP410.7), on the BNSF Fort Worth Subdivision, at Metro (MP386.8) meeting BNSF 4065. Additional delay was incurred at Haslet (MP360.4) meeting BNSF 4274.

| Train | Delay | Comment |
|---|---|---|
| 821(24) | 32" | |

## *Train 1(24) East of Schriever, LA - Freight Train Interference*

24OCT26: Train 1(24) held 40.2 miles east of Schriever, LA (MP55.0), on the BNSF Lafayette Subdivision, at Live Oak (MP14.4) meeting BNSF 9217.

| Train | Delay | Comment |
|---|---|---|
| 1(24) | 32" | |

## *Train 21(23) North of Marshall, TX - Freight Train Interference*

24OCT26: Train 21(23) held 15.2 miles north of Marshall, TX (MP66.5), on the UPRR Little Rock Subdivision, waiting on cross traffic to clear at the KCS Interlocking (MP51.3) then met UP6281 before proceeding south.

| Train | Delay | Comment |
|---|---|---|
| 21(23) | 33" | |

## *Train 59(23) Memphis, TN - Freight Train Interference*

24OCT26: Train 59(23) was delayed at Memphis, TN (MP391.8), on the CNRR Memphis Subdivision, while Engine 45 completed fueling and subsequently waited for three westbound BNSF freight trains to clear at CN Jct (MP392.5). Once the route was established through the junction, Train 59(23) was released to continue south.

| Train | Delay | Comment |
|---|---|---|
| 59(23) | 04" | Fuel |
| 59(23) | 29" | Cross Traffic |

## *Train 330(24) Milwaukee, WI - Engine Failure*

24OCT26: Train 330(24), with E/ID4631-4 cars-E/ID4616, departed Milwaukee, WI (MP85.4) on the CPRR C&M Subdivision and stopped approximately 0.4 miles outside the station at MP85.0 after both units shut down, resulting in the loss of head end power at 6:16AM-CT. There were 88 customers onboard and temperatures were 49 degrees. At 6:41AM-CT, E/ID4616 was restarted and head end power was restored. Mechanical personnel worked with the crew to recycle E/ID4631 and successfully returned both engines to service. At 7:05AM-CT, Train 330(24) resumed movement and traveled approximately six miles before stopping again at MP79.1 after both units shut down a second time, resulting in the loss of head end power at 7:13AM-CT. At 7:25AM-CT, E/ID4616 was restarted, restoring head end power. Due to the continued locomotive failures, Train 330(24) reversed back to Milwaukee, arriving at 8:11AM-CT, where the train was terminated. No alternate transportation was available due to limited bus availability. The equipment was subsequently added to the rear of Train 334(24) for movement back to Chicago for repairs. Bus availability was further constrained by the World Series game being played in Milwaukee that evening.

As a result of the locomotive failure, Train 331(24), affecting 97 customers, was cancelled entirely with no alternate due to bus availability. Customers were advised to rebook to the next available service. Train 336(24), affecting 137 customers, was cancelled entirely with two alternate buses secured. Train 337(24), affecting 113 customers, was cancelled entirely with two alternate buses secured.

Train 335(24) was delayed departing Chicago, IL, to uncouple the inbound double-draft equipment from Train 334(24) prior to departure.

Train 338(24) was delayed departing Milwaukee, WI due to a late turn of Train 335(24)'s equipment.

**WBS#: B.TR.100150.7302**

| Train | Delay | Comment |
|---|---|---|
| 330(24) | 1'56" | Reverse & TERM MKE |
| 336(24) | Cancelled | |
| 331(24) | Cancelled | |
| 337(24) | Cancelled | |
| 335(24) | 15" | ITD CHI |
| 338(24) | 26" | ITD MKE |

## *Train 22(23) South of Malvern, AR - Freight Train Interference*

24OCT26: Train 22(23) was delayed beginning at MP406.2, 17.2 miles south of Malvern AR station on the UPRR Little Rock subdivision due to UP freight MHONL(23) stopped ahead setting out a car with defects. Once the car was set out train 22(23) was able to proceed north and was further delayed due to freight interference from MP406 to MP388.8.

Train 21(23) was also delayed through the area holding at the Little Rock, AR station (MP345.7), on the UPRR Little Rock subdivision, meeting UP 8207. Once the meet was complete, Train 21(23) advanced to Haskell (MP373.7) to meet UP 5311 and UP 5733.

| Train | Delay | Comment |
|---|---|---|
| 22(23) | 1'14" | |
| 21(23) | 36" | LRK |
| 21(23) | 30" | Haskell |

## *Train 22(23) South of Texarkana, AR - Freight Train Interference*

24OCT26: Train 22(23) was delayed at the KCS interlocker, south of Texarkana AR station/MP490.35 on the UPRR Little Rock subdivision due to freight cross traffic.

| Train | Delay | Comment |
|---|---|---|
| 22(23) | 30" | |

## *UPRR Santa Barbara Subdivision South of Ventura, CA - Police Hold*

24OCT26: At 6:17A-PT, the UPRR reported a police hold at MP 297.85, 2 miles south of Ventura, CA, on the UPRRR Santa Barbara Subdivision. Initial reports gave an estimate of track opening of a couple hours. Train 757(24) arrived at Oxnard, CA at 7:00A-PT and held for open track. The crew held while Amtrak Police and an Amtrak Road Foreman responded. Train 770(24) arrived into Ventura at 7:38A-PT, where they held for open track. With an uncertainty of the track opening, alternate bus transportation was sourced if a bus bridge between Oxnard and Ventura became necessary. Two buses were secured with an estimate of 9A into Ventura. At 7:45A, the UPRR gave an update of track opening to at least another hour. The Amtrak Road Foreman responding arrived on scene at 8:00A-PT. The next UPRR update came at 8:57A-PT with an estimate of 30 minutes before open tracks. The tracks were reopened at 9:27A-PT, therefore the bus bridge was cancelled. Train 757(24) was first to proceed north following southbound Train 770(24). Train 761(24) held for open track then proceeded north. Due to the late operation of Train 757(24), it was terminated in Santa Barbara, CA with alternate bus transportation between Santa Barbara and Goleta, CA. The equipment turned for Train 774(24), originating in Santa Barbara with alternate bus transportation between Goleta and Santa Barbara.

Due to the late operation of Train 770(24), equipment from the yard was used to operate an on-time section of Train 770(24) from Los Angeles, CA to San Diego, CA. Customers on board late Train 770(24) between Goleta, CA and Los Angeles, CA, and traveling between Los Angeles and San Diego, were reaccommodated on the next available service. In addition, train 757(24) was terminated at Santa Barbara to mitigate some additional delays and originate train 774(24) at Santa Barbara with alternate busing provided to customers traveling between Goleta and Santa Barbara.

**WBS#: B.TR.100150.7303**

| Train | Delay | Comment |
|---|---|---|
| 770(24) | 1'53" | |
| 757(24) | 2'36" | |
| 757(24) | TERM SBA | |
| 774(24) | 2'29" | ORIG SBA |

## *BNSF Gallup Subdivision East of Winslow, AZ- Flash Floods*

23OCT26: A severe storm with isolated showers and thunderstorms impacted the area between Gallup, NM and Albuquerque, NM bringing flash floods and reduced operating conditions. At 9:50A-PT, the BNSF reported flash floods on the Gallup Subdivision with confirmed water over the rails at MP 77.9, 80 miles east of Gallup, NM . Multiple freights were tied down with crews expired on hours of service between Laguna/MP 71.1 and Grants/MP 98.3 causing single tracking conditions over 100 miles. BNSF maintenance of way personnel responded to areas of potential water of the rails to inspect. Substantial delays were incurred operating through the affected area.

Train 4(22), with 159 customers on board, arrived into Winslow, AZ at 9:42A-PT and held for open track. While holding in Winslow, and in anticipation of further delay, the crew performed a calendar day inspection. Once a route was open, Train 4(22) proceeded east incurring further delay at MP 253.4, holding for the recrew to arrive and conduct a job briefing. Upon completion of their job briefing, Train 4(22) proceeded east.

Train 3(22) was also delayed operating through the affected area by high winds, flash floods, and freight meets.

24OCT26: Due to the late operation of Train 3(22), the crew expired on hours of service holding in Flagstaff, AZ. Train 3(22) held at Flagstaff with pilots on board beginning at 1:55A-PT for the recrew to arrive from Train 4(23), arriving at approximately 4:30A-PT. Once the recrew arrived and conducted their job briefing, Train 3(22) proceeded west.

To support customers and provide service recovery on Train 4(22), complimentary food and

provided complimentary beef stew, mashed potatoes, and beverages. During dinner service, sleeping car customers received the regular dinner service in the Dining Car, while coach customers were provided complimentary Salisbury steak, vegetables, and mashed potatoes.

Train 4(22) had five misconnections at Kansas City, MO to Train 318(24) that were provided an alternate bus to their final destination. Train 6(22) also provided aid to local customers on Train 4(22) that were boarding between Galesburg and Chicago.

24OCT26: Train 3(23), operating with engines 79/29, 9 coaches, and 153 customers, was stopped east of the Gallup, NM station due to severe weather resulting in water above the rail in multiple locations. Burlington Northern Santa Fe subsequently reported that there was no route available beyond Laguna (MP 71) due to flooding of the tracks and the adjacent highway. Reported flood damage included both main tracks under water with debris between MP 72.7 and MP 72.3, including approximately 800 feet of side scour on the Main Track 1 side; side scour and undercutting at a culvert near MP 72.4; water over a high-water detector bridge and both rails between MP 70.1 and MP 69.8; and water over both rails between MP 69.8 and MP 69.7, where inspection was not possible. As a result, Train 3(23) shoved back to Albuquerque, NM and arrived at 11:57P-MT. The train wye'd en route into the station and will return to its origin. As a result of the service disruption, the following service adjustments were implemented:
Train 3(23) arrived at Albuquerque, NM at 11:57P-MT, wye'd en route into the station, and will return to its origin.
Train 4(24) wye'd at Barstow, CA and was en route back to Los Angeles, CA Union Station.
Train 3(24) will reverse back to Kansas City, MO, wye, and return to its origin.
Train 4(25) was canceled. No alternate transportation was provided.

**WBS#: B.TR.100150.7301**

| Train | Delay | Comment |
|---|---|---|
| 4(22) | 1'32" | Hold WLO |
| 4(22) | 5'09" | Meeting multiple freights due to weather |
| 3(22) | 1'30" | High winds and flash floods |
| 3(22) | 2'43" | meeting multiple freights due to weather |
| 3(22) | 2'59" | Recrew FLG |
| 4(24) | Term BAR - Back to Origin | |
| 3(24) | Term KCY - Back to Origin | |
| 3(23) | Term ABQ - Back to Origin | |
| 4(25) | Cancelled | |

## *Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication*

17OCT26: Pacific Surfliner service experienced delays due to high-tide conditions affecting the NCTD San Diego Subdivision starting at Don/MP 216.38, 12 miles east of San Clemente Pier, to Serra/MP 199.9, 5 miles west. The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. Single-track operations between MP 216.8 and MP 199.9 contributed to additional train meets and cascading delays throughout the corridor.

Due to late Pacific Surfliner operations, the following additional service adjustments were implemented:

-Train 786(17) was terminated at Los Angeles, CA, with customers accommodated on the next available services, including Trains 588(17) and 790(17).
-Train 593(17) was canceled, with customers accommodated on Train 595(17).

18OCT26: Pacific Surfliner service continued to experienced delays due to ongoing signal issues and train interference. Trains were expected to receive up to an hour and 30 minutes of delay.

Due to late Pacific Surfliner operations, the following additional service adjustments were implemented:

-Train 786(18) was terminated at Los Angeles, CA, with customers accommodated on the next available service Train 588(18).
-Train 593(18) was canceled, with customers accommodated on Train 595(18).

| Train | Delay | Comment |
| --- | --- | --- |

| | | |
|---|---|---|
| 573(17) | 1'01" | |
| 774(17) | 1'03" | |
| 777(17) | 1'38" | |
| 579(17) | 59" | |
| 581(17) | 1'14" | late turn 770(17) |
| 581(17) | 2'07" | |
| 580(17) | 1'05" | |
| 785(17) | 1'34" | |
| 584(17) | 1'59" | |
| 593(17) | Canceled | |
| 782(17) | 2'25" | |
| 786(17) | Term LAX | |
| 790(17) | 21" | late turn 785(17) |
| 790(17) | 54" | |
| 588(17) | 1'19" | late turn 581(17) |
| 588(17) | 1'52" | |
| 587(17) | 37" | late turn 774(17) |
| 587(17) | 2'32" | |
| 595(17) | 1'37" | late turn 782(17) |
| 595(17) | 47" | |
| 794(17) | 18" | |
| 562(18) | 29" | |
| 769(18) | 58" | |
| 564(18) | 1'04" | |
| 566(18) | 24" | |
| 770(18) | 1'19" | |
| 573(18) | 34" | |
| 572(18) | 1'09" | |
| 777(18) | 50" | |
| 593(18) | Canceled | |
| 786(18) | Term LAX | |
| 774(18) | 1'35" | |
| 579(18) | 1'54" | |
| 581(18) | 31" | late turn 770(18) |
| 581(18) | 1'41" | |
| 580(18) | 1'24" | |
| 782(18) | 1'48" | |
| 584(18) | 41" | late turn 579(18) |
| 584(18) | 1'15" | |
| 785(18) | 1'11" | |
| 587(18) | 49" | |
| 588(18) | 39" | |
| 595(18) | 1'30" | late turn 584(18) |
| 595(18) | 24" | |
| 790(18) | 10" | |
| 794(18) | 30" | |
| 761(19) | 22" | |
| 765(19) | 12" | |
| 567(19) | 25 | |
| 769(19) | 22" | |
| 562(19) | 27" | |
| 564(19) | 41" | |
| 566(19) | 55" | |
| 573(19) | 14" | |
| 770(19) | 20" | |
| 790(18) | 32" | late turn 785(18) |
| 777(19) | 22" | |
| 572(19) | 10" | |
| 579(19) | 22" | |
| 581(19) | 27" | |
| 774(19) | 31" | |
| 785(19) | 30" | |
| 587(19) | 39" | |
| 580(19) | 24" | |
| 782(19) | 43" | |
| 591(19) | 44" | |
| 584(19) | 1'07" | |
| 593(19) | 43" | |
| 786(19) | 18" | |
| 595(19) | 49" | |
| 588(19) | 53" | |
| 794(19) | 24" | |
| 595(19) | 27" | late turn 584(19) |
| 790(19) | 50" | |
| 761(20) | 23" | |
| 567(20) | 33" | |

| Train | Delay | Comment |
|---|---|---|
| 566(20) | 30" | |
| 579(20) | 30" | |
| 770(20) | 19" | |
| 777(20) | 27" | |
| 572(20) | 45" | |
| 581(20) | 17" | |
| 774(20) | 1'04" | |
| 785(20) | 32" | |
| 785(20) | 11" | late turn 774(20) |
| 587(20) | 1'07" | |
| 580(20) | 25" | |
| 591(20) | 1'10" | |
| 782(20) | 57" | |
| 593(20) | 23" | |
| 584(20) | 1'27" | |
| 786(20) | 26" | |
| 595(20) | 42" | late turn 584(20) |
| 595(20) | 28" | |
| 588(20) | 23" | |
| 794(20) | 10" | |
| 790(20) | 26" | |
| 562(21) | 14" | |
| 564(21) | 25" | |
| 566(21) | 29" | |
| 765(21) | 17" | |
| 769(21) | 21" | |
| 573(21) | 15" | |
| 587(21) | 41" | |
| 785(21) | 52" | |
| 584(21) | 1'16" | |
| 790(21) | 52" | |
| 595(21) | 1'09" | Late turn of 584(21) |
| 595(21) | 30" | |
| 786(21) | 55" | |
| 794(21) | 1'12" | |
| 564(22) | 25" | |
| 562(22) | 33" | |
| 761(22) | 13" | |
| 765(22) | 22" | |
| 567(22) | 17" | |
| 769(22) | 26" | |
| 587(22) | 30" | |
| 584(22) | 37" | Meet 587(22) SNC |
| 593(22) | 40" | Meet 588(22) |
| 790(22) | 46" | |
| 595(23) | 33" | Late turn of 584(23) |
| 588(23) | 41" | |
| 593(23) | 1'23" | Late turn of Equipment |
| 782(23) | 51" | |
| 591(23) | 32" | |
| 584(23) | 44" | |
| 587(23) | 35" | |
| 765(24) | 19" | |
| 567(23) | 15" | |
| 769(24) | 14" | |
| 573(24) | 35" | |
| 769(24) | 57" | |
| 562(24) | 37" | |
| 566(24) | 50" | |
| 564(24) | 13" | |
| 595(24) | 1'10" | |
| 790(24) | 32" | |
| 587(24) | 46" | |
| 581(24) | 40" | |
| 786(24) | 43" | late turn of equipment |
| 579(24) | 42" | |

## *Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions*

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

| Train | Delay | Comment |
|---|---|---|
| 822(29) | 32" | |
| 821(29) | 27" | |
| 821(30) | 34" | |
| 822(30) | 30" | |
| 822(01) | 30" | |
| 821(02) | 34" | |
| 822(02) | 29" | |
| 822(03) | 33" | |
| 821(03) | 25" | |
| 821(04) | 35" | |
| 822(04) | 32" | |
| 821(05) | 35" | |
| 822(05) | 26" | |
| 821(06) | 26" | |
| 822(06) | 37" | |
| 821(07) | 35" | |
| 822(08) | 32" | |
| 821(09) | 32" | |
| 822(09) | 36" | |
| 822(10) | 23" | |
| 822(11) | 41" | |
| 822(12) | 48" | |
| 821(12) | 21" | |
| 821(13) | 22" | |
| 822(13) | 36" | |
| 821(14) | 35" | |
| 822(14) | 17" | |
| 821(15) | 26" | |
| 821(16) | 41" | |
| 822(15) | 34" | |
| 822(16) | 19" | |
| 821(17) | 24" | |
| 821(19) | 39" | |
| 822(19) | 22" | |
| 821(20) | 29" | |
| 822(20) | 32" | |
| 821(21) | 46" | |
| 821(22) | 32" | |
| 822(21) | 19" | |
| 822(22) | 30" | |
| 821(23) | 42" | |
| 822(23) | 23" | |
| 821(24) | 21" | |
| 822(24) | 22" | |

# Maintenance of Way Highlights

## *BNSF Bakersfield Subdivision East of Corcoran, CA Bridge Replacement - Scheduled M/W Work 27-011*

25OCT26: The BNSF scheduled bridge replacement work to begin Sunday, October 25th at 8AM-PT on the Bakersfield Subdivision at MP 947, 3 miles south of Corcoran, CA. To accommodate the infrastructure work, the Gold Runner service has been adjusted as follows.

SOUTH

· Train 702 (25Oct), which normally operates between Sacramento, CA and Bakersfield, CA, terminated at Fresno, CA.
· Train 710 (25Oct), which normally operates between Oakland, CA and Bakersfield, CA, terminated at Fresno, CA.
· Train 712 (25Oct), which normally operates between Oakland, CA and Bakersfield, CA, terminated at Fresno, CA.
· Train 714 (25Oct), which normally operates between Oakland, CA and Bakersfield, CA, terminated at Fresno, CA.
· Train 716 (25Oct), which normally operates between Oakland, CA and Bakersfield, CA, terminated at Fresno, CA.
· Train 704 (25Oct), which normally operates between Sacramento, CA and Bakersfield, CA, terminated at Fresno, CA.

NORTH

· Train 713 (25Oct), which normally operates between Bakersfield, CA and Oakland, CA, originated at Fresno.
· Train 715 (25Oct), which normally operates between Bakersfield, CA and Oakland, CA, originated at Fresno.
· Train 717 (25Oct), which normally operates between Bakersfield, CA and Oakland, CA, originated at Fresno.
· Train 719 (25Oct), which normally operates between Bakersfield, CA and Oakland, CA, originated at Fresno.
· Train 703 (25Oct), which normally operates between Bakersfield, CA and Sacramento, CA, originated at Fresno.

Buses 4302, 4304, 4310, 4312, 4314 and 4316 provided alternate transportation between Fresno and Bakersfield with an intermediate stop at Hanford.
Buses 4313, 4315, 4317, 4319, and 4303 provided alternate transportation between Bakersfield and Fresno with an intermediate stop at Hanford.

No alternate service was provided between Corcoran, CA and Wasco, CA.

**WBS#: B.TR.100150.7236**

## *Southern California Regional Rail Authority River Subdivision Glendale, CA to Los Angeles, CA - Scheduled M/W Work - TWA 27-015*

08OCT26: From October 24-26, 2026, Southern California Regional Rail Authority is performing signal upgrade work between Los Angeles, CA Union Station and the Glendale, CA station on the River Subdivision. As a result, Coast Starlight and Pacific Surfliner service is modified.

Coast Starlight
Trains 11(23OCT, 24OCT) terminate at the Emeryville, CA station. Alternate transportation is provided between the Sacramento, CA station and Los Angeles, CA Union

station via Gold Runner service.

Pacific Surfliner

Saturday, October 24, 2026
Train 794(24) operates as Train 1594(24) from the Goleta, CA station to the Van Nuys, CA station, as Bus 4894 to Los Angeles, CA Union Station, and as Train 794(24) to the San Diego, CA station.

Sunday, October 25, 2026
Alternate transportation is provided between Los Angeles, CA Union Station and the Van Nuys, CA station. Odd-numbered 4800-series buses operate northbound, and even-numbered 4800-series buses operate southbound. No alternate transportation is provided at the Burbank, CA Airport station, Burbank, CA Downtown station, or Glendale, CA station.

Southbound
Train 770(25) operates as Train 1570(25) from the Goleta, CA station to the Van Nuys, CA station, as Bus 4870 to Los Angeles, CA Union Station, and as Train 770(25) to the San Diego, CA station.
Train 774(25) operates as Train 1574(25) from the Goleta, CA station to the Van Nuys, CA station, as Bus 4874 to Los Angeles, CA Union Station, and as Train 774(25) to the San Diego, CA station.
Train 782(25) operates as Train 1582(25) from the Goleta, CA station to the Van Nuys, CA station, as Bus 4884 to Los Angeles, CA Union Station, and as Train 782(25) to the San Diego, CA station.
Train 790(25) operates as Train 1590(25) from the Goleta, CA station to the Van Nuys, CA station, as Bus 4890 to Los Angeles, CA Union Station, and as Train 790(25) to the San Diego, CA station.
Train 794(25) operates as Train 1594(25) from the Goleta, CA station to the Van Nuys, CA station, as Bus 4894 to Los Angeles, CA Union Station, and as Train 794(25) to the San Diego, CA station.
Train 786(25) originates at Los Angeles, CA Union Station. No alternate transportation is provided between the San Luis Obispo, CA station and Los Angeles, CA Union Station.

Northbound
Train 761(25) operates from the San Diego, CA station to Los Angeles, CA Union Station, as Bus 4861 to the Van Nuys, CA station, and as Train 1561(25) to the Goleta, CA station.
Train 765(25) operates from the San Diego, CA station to Los Angeles, CA Union Station, as Bus 4865 to the Van Nuys, CA station, and as Train 1565(25) to the Goleta, CA station.
Train 769(25) operates from the San Diego, CA station to Los Angeles, CA Union Station, as Bus 4869 to the Van Nuys, CA station, and as Train 1569(25) to the Goleta, CA station.
Train 777(25) operates from the San Diego, CA station to Los Angeles, CA Union Station, as Bus 4877 to the Van Nuys, CA station, and as Train 1577(25) to the Goleta, CA station.
Train 785(25) operates from the San Diego, CA station to Los Angeles, CA Union Station, as Bus 4885 to the Van Nuys, CA station, and as Train 1585(25) to the Goleta, CA station.
Train 757(25) is canceled in its entirety. No alternate transportation is provided.

**WBS#: B.TR.100150.7254**

| Train | Delay | Comment |
|---|---|---|
| 794(24) | 31" | Hold for throughway bus |

## *CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006*

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL. Beginning Monday October 12th, Bus 3391 will operate 41-minutes later between Champaign and Carbondale, departing Champaign at 1130am.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

**WBS#: B.TR.100150.7220**

## *Metra C&M Subdivision - Scheduled M/W Work 26-055*

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

**WBS#: B.TR.100150.6663**

# Western Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| 3550(21) | DER | ID4605 | | Vehicle strike |
| 351(22) | DER | ID4608 | | Vehicle strike |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| 507(24) | CTL | BN6949 | E/WS1407 NO HEP/ faults | SEA | |
| | | | | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Western Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| | Projected Need | | Number Operated | | | |
|---|---|---|---|---|---|---|
| Train | Cars | Seats | Cars | Seats | Standees | Location |
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| None | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

## Consist Deviations

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 662 (24) | HAR | 2nd loco in lieu of cab car and all table lounge for wi-fi | No impact | 0 | 96XX, 43386 |
| 566 (24) | LAX | extra car to lossan group | No impact | 0 | C6453 |
| 584 (24) | LAX | extra car for lossan group | No impact | 0 | C6453 |
| 562 (24) | LAX | Due to equipment swap operating with 90215 in consist. Inventory has been adjusted. CNOC Csv please reaccommodate any passengers impacted by this. | email sent for passener notifications | 6 | 90215 |
| 580 (24) | LAX | Due to equipment swap operating with 90215 in consist. Inventory has been adjusted. CNOC Csv please reaccommodate any passengers impacted by this. | NO BV | 6 | 90215 |
| 770 (24) | LAX | Swap of equipment, utilizing comet set will not be able to accommodate paxs with BV reservations or biz class. Inventory has been updated. CNOC CSV please reaccommodate passengers impacted by this. | NO JY -83 / O BV -2 | 85 | C5006 C5010 C5007 C5005 C5002 9700 |
| 579 (24) | SAN | extra car for lossan group | No impact | 0 | C6453 |
| 595 (24) | SAN | extra car for lossan group | No impact | 0 | C6453 |
| 573 (24) | SAN | Due to equipment swap operating with 90215 in consist. Inventory has been adjusted. CNOC Csv please reaccommodate any passengers impacted by this. | n/a | 0 | 90215 |
| 591 (24) | SAN | Due to equipment swap operating with 90215 in consist. Inventory has been adjusted. CNOC Csv please reaccommodate any passengers impacted by this. | NO BV | 6 | 90215 |
| 581 (25) | SAN | Operating with comet set unable to accommodate passengers in business class and BV reservations. CNOC customer service will need to reaccommodate passengers impacted. | was advise this was for the 24th | 0 | 9700 C5002 C5005 C5007 C5010 C5006 |

## Reverse Consists

| Train Number | Station | Reason |
|---|---|---|
| 195 (24) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |