



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, September 02, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/01/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/01/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	60	81.6%	326	60	81.6%	100,850	14,029	86.1%
Central Division	86.0%	59	7	88.1%	59	7	88.1%	19,254	1,782	90.7%
East Division	82.0%	175	22	87.4%	175	22	87.4%	52,995	8,156	84.6%
West Division	86.0%	92	31	66.3%	92	31	66.3%	28,601	4,091	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008772 UNCLASSIFIED Endpoint Arrival Dates through 9/1/26 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	83,067	20,103	76%	83,067	20,103	76%	33,680,213	8,608,324	74%
Northeast Corridor	81%	36,330	7,462	79%	36,330	7,462	79%	14,754,756	3,596,141	76%
Acela	83%	9,096	1,663	82%	9,096	1,663	82%	2,972,007	760,884	74%
Northeast Regional	79%	27,234	5,799	79%	27,234	5,799	79%	11,782,749	2,835,257	76%
Richmond / Newport News / Norfolk	77%	7,226	2,751	62%	7,226	2,751	62%	3,530,852	1,050,595	70%
Springfield Shuttles	89%	536	81	85%	536	81	85%	207,775	33,318	84%
Roanoke	79%	2,999	1,166	61%	2,999	1,166	61%	1,117,156	251,403	77%
On Spine Northeast Regional	80%	16,473	1,801	89%	16,473	1,801	89%	6,926,966	1,499,941	78%
State Supported	80%	36,988	9,104	75%	36,988	9,104	75%	14,825,926	3,220,257	78%
Borealis	80%	545	0	100%	545	0	100%	188,564	40,477	79%
Capitol Corridor	90%	4,185	423	90%	4,185	423	90%	1,236,311	164,811	87%
Carolinian	70%	739	311	58%	739	311	58%	378,124	148,430	61%
Cascades	75%	2,188	994	55%	2,188	994	55%	854,788	242,019	72%
Downeaster	82%	1,367	0	100%	1,367	0	100%	521,519	61,834	88%
Empire	78%	5,391	1,417	74%	5,391	1,417	74%	1,847,895	456,758	75%
Adirondack	72%	282	195	31%	282	195	31%	114,302	37,148	68%
Ethan Allen Express	70%	506	35	93%	506	35	93%	187,457	72,259	61%
Maple Leaf	70%	747	466	38%	747	466	38%	229,635	90,689	61%
New York - Albany	85%	2,539	485	81%	2,539	485	81%	851,972	149,041	83%
New York - Niagara Falls	75%	1,317	236	82%	1,317	236	82%	451,679	100,763	78%
Berkshire Flyer	60%	0	0	-	0	0	-	12,850	6,858	47%
Gold Runner	73%	1,612	1,366	15%	1,612	1,366	15%	831,793	310,270	63%
Heartland Flyer	70%	53	0	100%	53	0	100%	71,590	30,168	58%
Hiawatha	90%	1,465	0	100%	1,465	0	100%	585,532	63,876	89%
Illinois	78%	1,423	1,069	25%	1,423	1,069	25%	830,100	233,814	72%
Carl Sandburg / Illinois Zephyr	85%	171	39	77%	171	39	77%	137,984	39,399	71%
Illini / Saluki	85%	472	390	17%	472	390	17%	286,597	71,909	75%
Lincoln Service	70%	780	640	18%	780	640	18%	405,519	122,506	70%
Keystone	92%	7,748	408	95%	7,748	408	95%	2,534,356	258,169	90%
Lincoln / Missouri	70%	405	405	0%	405	405	0%	258,042	135,857	47%
Mardi Gras Service	80%	107	22	79%	107	22	79%	133,206	29,739	78%
Michigan	70%	1,538	465	70%	1,538	465	70%	674,843	226,005	67%
Blue Water	70%	330	21	94%	330	21	94%	159,001	65,188	59%
Pere Marquette	85%	194	3	98%	194	3	98%	86,713	16,361	81%
Wolverine	70%	1,014	441	57%	1,014	441	57%	429,129	144,456	66%
Missouri	80%	119	105	12%	119	105	12%	73,508	21,354	71%
Pacific Surfliner	85%	5,960	1,713	71%	5,960	1,713	71%	2,714,405	517,512	81%
Pennsylvanian	80%	670	0	100%	670	0	100%	293,426	55,871	81%
Piedmont	80%	366	1	100%	366	1	100%	371,151	94,621	75%
Vermont	75%	1,107	405	63%	1,107	405	63%	426,773	128,672	70%
Long Distance	70%	9,749	3,537	64%	9,749	3,537	64%	4,060,264	1,789,463	56%
Auto Train	70%	619	0	100%	619	0	100%	260,782	88,756	66%
California Zephyr	70%	862	355	59%	862	355	59%	321,994	126,349	61%
Cardinal	70%	0	0	-	0	0	-	77,082	39,300	49%
City Of New Orleans	75%	531	509	4%	531	509	4%	209,932	72,749	65%
Coast Starlight	70%	956	211	78%	956	211	78%	378,129	134,909	64%
Crescent	70%	618	76	88%	618	76	88%	305,686	94,430	69%
Empire Builder	70%	1,037	44	96%	1,037	44	96%	322,188	161,629	50%
Floridian	60%	1,395	577	59%	1,395	577	59%	521,461	360,726	31%
Lake Shore Ltd	73%	857	0	100%	857	0	100%	323,545	98,130	70%
Palmetto	70%	632	226	64%	632	226	64%	303,802	95,004	69%
Silver Meteor	70%	651	575	12%	651	575	12%	335,153	156,035	53%
Southwest Chief	60%	801	310	61%	801	310	61%	278,185	184,015	34%
Sunset Ltd	70%	0	0	-	0	0	-	95,778	38,518	60%
Texas Eagle	70%	790	654	17%	790	654	17%	326,547	138,913	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000772 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 01, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	5,906	111,273	531	2,005,734	35,387,357	567

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	522	35,345	148	96,987	10,242,780	95
INFRASTRUCTURE PLANNED	135	546	35,345	154	116,076	10,242,780	113
FLEET RELIABILITY	90	730	111,273	66	320,356	35,387,357	91
TRAIN OPERATIONS	424	4,108	111,273	369	1,472,315	35,387,357	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/01/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	60	81.6%	326	60	81.6%	100,850	14,029	86.1%
Central Division	86.0%	59	7	88.1%	59	7	88.1%	19,254	1,782	90.7%
East Division	82.0%	175	22	87.4%	175	22	87.4%	52,995	8,156	84.6%
West Division	86.0%	92	31	66.3%	92	31	66.3%	28,601	4,091	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-00777 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/01/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 09/01/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	60	81.6%	326	60	81.6%	100,850	14,029	86.1%
Central Division	86.0%	59	7	88.1%	59	7	88.1%	19,254	1,782	90.7%
CDL	95.0%	2	0	100.0%	2	0	100.0%	638	31	95.1%
CHI	86.0%	28	3	89.3%	28	3	89.3%	8,898	1,103	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	1	0.0%	1	1	0.0%	359	39	89.1%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	1	0	100.0%	315	11	96.5%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	2	0	100.0%	650	54	91.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	6	0	100.0%	1,965	126	93.6%
MOE	97.5%	2	1	50.0%	2	1	50.0%	669	10	98.5%
MSP	96.5%	1	0	100.0%	1	0	100.0%	329	7	97.9%
NOL	94.5%	4	0	100.0%	4	0	100.0%	1,414	64	95.5%
OKC	97.0%	1	0	100.0%	1	0	100.0%	330	6	98.2%
PNT	88.0%	3	0	100.0%	3	0	100.0%	879	73	91.7%
PTH	93.0%	1	0	100.0%	1	0	100.0%	324	13	96.0%
QCY	91.0%	2	1	50.0%	2	1	50.0%	633	49	92.3%
SAS	90.5%	1	1	0.0%	1	1	0.0%	333	40	88.0%
STL	89.0%	4	0	100.0%	4	0	100.0%	1,300	106	91.8%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	22	87.4%	175	22	87.4%	52,995	8,156	84.6%
ALB	88.5%	8	0	100.0%	8	0	100.0%	2,492	188	92.5%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	5	0	100.0%	1,626	175	89.2%
BOS	85.5%	18	1	94.4%	18	1	94.4%	5,723	641	88.8%
BRK	92.5%	5	0	100.0%	5	0	100.0%	1,600	112	93.0%
BTN	82.0%	1	1	0.0%	1	1	0.0%	320	43	86.6%
CLT	91.5%	4	0	100.0%	4	0	100.0%	1,635	167	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	1	0	100.0%	1	0	100.0%	649	60	90.8%
GRO	-	1	1	0.0%	1	1	0.0%	51	12	76.5%
HAR	79.5%	13	1	92.3%	13	1	92.3%	3,720	595	84.0%
HFD	-	2	0	100.0%	2	0	100.0%	234	19	91.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	1	0	100.0%	332	40	88.0%
MIA	89.5%	2	1	50.0%	2	1	50.0%	660	77	88.3%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/01/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	60	81.6%	326	60	81.6%	100,850	14,029	86.1%
East Division	82.0%	175	22	87.4%	175	22	87.4%	52,995	8,156	84.6%
MTR	79.0%	1	0	100.0%	1	0	100.0%	319	58	81.8%
NFK	84.5%	2	0	100.0%	2	0	100.0%	747	136	81.8%
NFL	93.5%	2	1	50.0%	2	1	50.0%	676	32	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	2	60.0%	5	2	60.0%	1,707	289	83.1%
NPN	93.0%	2	0	100.0%	2	0	100.0%	636	51	92.0%
NYP	75.5%	51	10	80.4%	51	10	80.4%	13,980	3,067	78.1%
PGH	93.0%	1	0	100.0%	1	0	100.0%	333	23	93.1%
PHL	48.0%	5	2	60.0%	5	2	60.0%	1,700	801	52.9%
PIT	76.0%	-	-	-	-	-	-	24	19	20.8%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	0	100.0%	2	0	100.0%	1,266	54	95.7%
RNK	83.5%	2	0	100.0%	2	0	100.0%	660	93	85.9%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	1	0	100.0%	315	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	1	0	100.0%	329	12	96.4%
SFA	88.0%	1	0	100.0%	1	0	100.0%	332	47	85.8%
SPG	92.5%	4	1	75.0%	4	1	75.0%	1,966	116	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	1	0	100.0%	321	63	80.4%
WAS	84.0%	33	1	97.0%	33	1	97.0%	8,402	1,075	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	92	31	66.3%	92	31	66.3%	28,601	4,091	85.7%
ARN	92.0%	1	0	100.0%	1	0	100.0%	334	28	91.6%
BFD	79.0%	7	3	57.1%	7	3	57.1%	2,120	451	78.7%
EMY	72.0%	1	1	0.0%	1	1	0.0%	350	101	71.1%
EUG	86.5%	2	0	100.0%	2	0	100.0%	662	59	91.1%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	1	1	0.0%	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	3	0	100.0%	1,005	172	82.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	2	80.0%	10	2	80.0%	3,329	371	88.9%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	12	6	50.0%	12	6	50.0%	3,631	959	73.6%
PDX	86.0%	5	2	60.0%	5	2	60.0%	1,602	219	86.3%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/01/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/01/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	60	81.6%	326	60	81.6%	100,850	14,029	86.1%
West Division	86.0%	92	31	66.3%	92	31	66.3%	28,601	4,091	85.7%
SAC	88.5%	16	5	68.8%	16	5	68.8%	4,735	525	88.9%
SAN	90.5%	13	3	76.9%	13	3	76.9%	4,050	395	90.2%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	4	50.0%	8	4	50.0%	2,569	392	84.7%
SJC	89.0%	7	2	71.4%	7	2	71.4%	2,347	231	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	3	0	100.0%	768	77	90.0%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	1	1	0.0%	315	31	90.2%
VAC	97.0%	2	1	50.0%	2	1	50.0%	655	15	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	Cncld	0	0	0.0%	142	36	74.6%	0	0	0.0%	137	29	78.8%
3		1	1	0.0%	334	67	79.9%	1	0	100.0%	331	157	52.6%
4		1	0	100.0%	333	53	84.1%	1	0	100.0%	333	221	33.6%
5		1	0	100.0%	332	57	82.8%	1	0	100.0%	328	111	66.2%
6	75	1	1	0.0%	331	92	72.2%	1	1	0.0%	331	126	61.9%
7		1	0	100.0%	323	51	84.2%	1	0	100.0%	314	86	72.6%
8		1	1	0.0%	323	146	54.8%	1	0	100.0%	322	198	38.5%
11		1	1	0.0%	334	73	78.1%	1	0	100.0%	328	67	79.6%
14		1	1	0.0%	335	55	83.6%	1	0	100.0%	332	105	68.4%
19		1	1	0.0%	333	84	74.8%	1	0	100.0%	330	82	75.2%
20		1	0	100.0%	333	23	93.1%	1	0	100.0%	333	65	80.5%
21	No OS	1	0	100.0%	330	36	89.1%	1	1	0.0%	329	100	69.6%
22	67	1	1	0.0%	331	38	88.5%	1	1	0.0%	329	100	69.6%
23	200	1	1	0.0%	335	7	97.9%	1	1	0.0%	333	91	72.7%
24		1	0	100.0%	335	16	95.2%	1	0	100.0%	334	65	80.5%
25		1	0	100.0%	334	3	99.1%	1	0	100.0%	331	94	71.6%
26		1	0	100.0%	334	5	98.5%	1	0	100.0%	331	66	80.1%
27		1	1	0.0%	302	23	92.4%	1	0	100.0%	295	98	66.8%
28		1	0	100.0%	294	67	77.2%	1	0	100.0%	294	60	79.6%
40		1	0	100.0%	324	47	85.5%	1	0	100.0%	320	172	46.3%
41	101	1	0	100.0%	324	124	61.7%	1	1	0.0%	321	248	22.7%
42		1	0	100.0%	335	25	92.5%	1	0	100.0%	333	58	82.6%
43		1	0	100.0%	334	45	86.5%	1	0	100.0%	333	76	77.2%
48		1	0	100.0%	333	62	81.4%	1	0	100.0%	332	51	84.6%
49		1	0	100.0%	333	84	74.8%	1	0	100.0%	333	70	79.0%
52		1	0	100.0%	332	47	85.8%	1	0	100.0%	331	77	76.7%
53		1	0	100.0%	332	40	88.0%	1	0	100.0%	331	106	68.0%
55		1	0	100.0%	212	9	95.8%	1	0	100.0%	209	46	78.0%
56	33	1	0	100.0%	213	25	88.3%	1	1	0.0%	209	41	80.4%
58	59	1	0	100.0%	308	17	94.5%	1	1	0.0%	306	98	68.0%
59	253	1	1	0.0%	307	52	83.1%	1	1	0.0%	302	82	72.8%
63	65	1	0	100.0%	336	144	57.1%	1	1	0.0%	330	198	40.0%
64	40	1	0	100.0%	334	71	78.7%	1	1	0.0%	333	134	59.8%
66	36	1	0	100.0%	333	64	80.8%	1	1	0.0%	328	61	81.4%
67		1	0	100.0%	231	14	93.9%	1	0	100.0%	230	40	82.6%
68	18	1	0	100.0%	336	67	80.1%	1	1	0.0%	335	135	59.7%
69		1	1	0.0%	323	80	75.2%	1	0	100.0%	318	56	82.4%
71		1	0	100.0%	331	3	99.1%	1	0	100.0%	329	86	73.9%
72		1	0	100.0%	327	36	89.0%	1	0	100.0%	325	69	78.8%
75	14	1	1	0.0%	324	18	94.4%	1	1	0.0%	318	152	52.2%
76		1	0	100.0%	324	31	90.4%	1	0	100.0%	314	130	58.6%
77		1	0	100.0%	326	21	93.6%	1	0	100.0%	323	133	58.8%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		1	0	100.0%	330	29	91.2%	1	0	100.0%	327	75	77.1%
79	42	1	0	100.0%	333	59	82.3%	1	1	0.0%	331	113	65.9%
80		1	0	100.0%	333	37	88.9%	1	0	100.0%	330	71	78.5%
84		1	0	100.0%	203	19	90.6%	1	0	100.0%	199	48	75.9%
85	60	1	0	100.0%	214	18	91.6%	1	1	0.0%	214	75	65.0%
86		1	0	100.0%	214	16	92.5%	1	0	100.0%	213	121	43.2%
89	32	1	0	100.0%	331	78	76.4%	1	1	0.0%	329	98	70.2%
90		1	0	100.0%	331	12	96.4%	1	0	100.0%	330	60	81.8%
93		1	0	100.0%	213	21	90.1%	1	0	100.0%	212	55	74.1%
94		1	0	100.0%	244	61	75.0%	1	0	100.0%	242	89	63.2%
95	57	1	0	100.0%	213	6	97.2%	1	1	0.0%	213	83	61.0%
97		1	1	0.0%	333	218	34.5%	1	0	100.0%	331	120	63.7%
98	61	1	1	0.0%	333	29	91.3%	1	1	0.0%	331	124	62.5%
110		1	0	100.0%	210	110	47.6%	1	0	100.0%	207	22	89.4%
111		1	0	100.0%	204	37	81.9%	1	0	100.0%	202	22	89.1%
112		1	0	100.0%	204	20	90.2%	1	0	100.0%	203	20	90.1%
113		1	0	100.0%	135	33	75.6%	1	0	100.0%	134	16	88.1%
119		1	0	100.0%	201	49	75.6%	1	0	100.0%	199	26	86.9%
125		1	0	100.0%	214	12	94.4%	1	0	100.0%	214	84	60.7%
129	119	1	1	0.0%	213	51	76.1%	1	1	0.0%	213	31	85.4%
130		1	0	100.0%	204	20	90.2%	1	0	100.0%	202	16	92.1%
131		1	0	100.0%	206	57	72.3%	1	0	100.0%	206	39	81.1%
134		1	0	100.0%	214	32	85.0%	1	0	100.0%	213	42	80.3%
136	144	1	0	100.0%	214	27	87.4%	1	1	0.0%	212	29	86.3%
137	21	1	0	100.0%	211	36	82.9%	1	1	0.0%	211	63	70.1%
138		1	0	100.0%	214	43	79.9%	1	0	100.0%	213	38	82.2%
141	73	1	1	0.0%	213	5	97.7%	1	1	0.0%	212	38	82.1%
148		1	0	100.0%	213	22	89.7%	1	0	100.0%	211	41	80.6%
151		1	0	100.0%	332	105	68.4%	1	0	100.0%	331	99	70.1%
170		1	0	100.0%	209	12	94.3%	1	0	100.0%	208	30	85.6%
171	39	1	0	100.0%	214	11	94.9%	1	1	0.0%	214	89	58.4%
172		1	0	100.0%	213	19	91.1%	1	0	100.0%	211	69	67.3%
173		1	0	100.0%	206	25	87.9%	1	0	100.0%	205	84	59.0%
174		1	0	100.0%	214	23	89.3%	1	0	100.0%	214	52	75.7%
175		1	0	100.0%	214	23	89.3%	1	0	100.0%	214	70	67.3%
176		1	0	100.0%	206	17	91.7%	1	0	100.0%	203	26	87.2%
177		1	0	100.0%	214	28	86.9%	1	0	100.0%	214	48	77.6%
178		1	0	100.0%	214	28	86.9%	1	0	100.0%	212	36	83.0%
179	23	1	0	100.0%	214	25	88.3%	1	1	0.0%	213	77	63.8%
181		1	0	100.0%	210	64	69.5%	1	0	100.0%	207	17	91.8%
182		1	0	100.0%	204	31	84.8%	1	0	100.0%	202	23	88.6%
183		1	0	100.0%	213	62	70.9%	1	0	100.0%	210	44	79.0%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		1	0	100.0%	214	36	83.2%	1	0	100.0%	213	28	86.9%
185		1	0	100.0%	214	41	80.8%	1	0	100.0%	214	18	91.6%
186		1	0	100.0%	213	29	86.4%	1	0	100.0%	212	61	71.2%
190		1	1	0.0%	213	76	64.3%	1	0	100.0%	212	44	79.2%
192		1	0	100.0%	211	24	88.6%	1	0	100.0%	211	19	91.0%
193	28	1	1	0.0%	209	84	59.8%	1	1	0.0%	208	91	56.3%
196		1	0	100.0%	210	23	89.0%	1	0	100.0%	208	17	91.8%
197	32	1	0	100.0%	214	77	64.0%	1	1	0.0%	214	72	66.4%
198		1	1	0.0%	146	18	87.7%	1	0	100.0%	145	22	84.8%
230		1	0	100.0%	169	4	97.6%	1	0	100.0%	169	9	94.7%
232		1	0	100.0%	335	12	96.4%	1	0	100.0%	335	23	93.1%
233		1	0	100.0%	296	66	77.7%	1	0	100.0%	295	101	65.8%
234		1	0	100.0%	336	23	93.2%	1	0	100.0%	335	29	91.3%
235		1	0	100.0%	260	42	83.8%	1	0	100.0%	259	60	76.8%
236		1	0	100.0%	320	10	96.9%	1	0	100.0%	319	43	86.5%
237		1	0	100.0%	333	61	81.7%	1	0	100.0%	331	59	82.2%
238		1	0	100.0%	260	23	91.2%	1	0	100.0%	258	22	91.5%
239		1	1	0.0%	334	84	74.9%	1	0	100.0%	333	42	87.4%
240		1	0	100.0%	335	23	93.1%	1	0	100.0%	332	69	79.2%
241	26	1	1	0.0%	335	83	75.2%	1	1	0.0%	335	82	75.5%
243		1	0	100.0%	271	71	73.8%	1	0	100.0%	270	39	85.6%
244	24	1	0	100.0%	295	12	95.9%	1	1	0.0%	295	66	77.6%
245		1	0	100.0%	216	41	81.0%	1	0	100.0%	215	30	86.0%
280		1	0	100.0%	336	17	94.9%	1	0	100.0%	335	78	76.7%
281		1	0	100.0%	336	40	88.1%	1	0	100.0%	336	60	82.1%
283	55	1	0	100.0%	336	85	74.7%	1	1	0.0%	336	67	80.1%
284		1	1	0.0%	336	14	95.8%	1	0	100.0%	333	61	81.7%
290		1	1	0.0%	336	53	84.2%	1	0	100.0%	333	137	58.9%
291		1	0	100.0%	335	112	66.6%	1	0	100.0%	331	90	72.8%
300		1	0	100.0%	319	22	93.1%	1	0	100.0%	316	73	76.9%
301	131	1	0	100.0%	333	10	97.0%	1	1	0.0%	329	64	80.5%
302	38	1	0	100.0%	314	34	89.2%	1	1	0.0%	310	91	70.6%
305	56	1	0	100.0%	317	31	90.2%	1	1	0.0%	312	123	60.6%
306	55	1	0	100.0%	331	17	94.9%	1	1	0.0%	329	90	72.6%
307	32	1	0	100.0%	324	44	86.4%	1	1	0.0%	320	99	69.1%
311	46	1	0	100.0%	328	28	91.5%	1	1	0.0%	322	85	73.6%
316	77	1	0	100.0%	324	24	92.6%	1	1	0.0%	318	102	67.9%
318	171	1	0	100.0%	334	35	89.5%	1	1	0.0%	331	167	49.5%
319	164	1	0	100.0%	335	20	94.0%	1	1	0.0%	330	194	41.2%
329		1	0	100.0%	237	12	94.9%	1	0	100.0%	237	19	92.0%
330		1	0	100.0%	285	6	97.9%	1	0	100.0%	285	15	94.7%
331		1	0	100.0%	336	33	90.2%	1	0	100.0%	335	44	86.9%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		1	0	100.0%	335	19	94.3%	1	0	100.0%	335	46	86.3%
334		1	0	100.0%	336	11	96.7%	1	0	100.0%	334	43	87.1%
335		1	0	100.0%	336	35	89.6%	1	0	100.0%	333	55	83.5%
336		1	0	100.0%	335	10	97.0%	1	0	100.0%	333	29	91.3%
337		1	0	100.0%	336	21	93.8%	1	0	100.0%	332	47	85.8%
338		1	0	100.0%	336	54	83.9%	1	0	100.0%	333	104	68.8%
339		1	0	100.0%	336	54	83.9%	1	0	100.0%	336	58	82.7%
341		1	0	100.0%	321	51	84.1%	1	0	100.0%	315	53	83.2%
342	13	1	0	100.0%	336	26	92.3%	1	1	0.0%	334	62	81.4%
350	50	1	0	100.0%	311	20	93.6%	1	1	0.0%	303	175	42.2%
351	100	1	0	100.0%	318	29	90.9%	1	1	0.0%	316	93	70.6%
352	32	1	0	100.0%	302	24	92.1%	1	1	0.0%	296	94	68.2%
353		1	0	100.0%	273	14	94.9%	1	0	100.0%	267	49	81.6%
354		1	0	100.0%	317	37	88.3%	1	0	100.0%	309	116	62.5%
355		1	0	100.0%	324	37	88.6%	1	0	100.0%	315	119	62.2%
364		1	0	100.0%	325	73	77.5%	1	0	100.0%	319	120	62.4%
365		1	0	100.0%	324	13	96.0%	1	0	100.0%	321	124	61.4%
370		1	0	100.0%	322	39	87.9%	1	0	100.0%	309	75	75.7%
371		1	0	100.0%	315	11	96.5%	1	0	100.0%	311	30	90.4%
380		1	0	100.0%	317	30	90.5%	1	0	100.0%	316	72	77.2%
381		1	0	100.0%	332	15	95.5%	1	0	100.0%	329	71	78.4%
382	24	1	1	0.0%	331	31	90.6%	1	1	0.0%	329	117	64.4%
383	Cncld	1	1	0.0%	322	28	91.3%	0	0	0.0%	318	138	56.6%
390	36	1	0	100.0%	317	24	92.4%	1	1	0.0%	315	87	72.4%
391	28	1	0	100.0%	318	14	95.6%	1	1	0.0%	313	89	71.6%
392	46	1	0	100.0%	331	11	96.7%	1	1	0.0%	326	104	68.1%
393	57	1	0	100.0%	335	19	94.3%	1	1	0.0%	331	105	68.3%
417		1	0	100.0%	222	47	78.8%	1	0	100.0%	213	25	88.3%
448		1	1	0.0%	260	50	80.8%	1	0	100.0%	256	89	65.2%
449		1	0	100.0%	257	34	86.8%	1	0	100.0%	257	45	82.5%
470	17	1	0	100.0%	237	40	83.1%	1	1	0.0%	231	28	87.9%
471		1	0	100.0%	226	14	93.8%	1	0	100.0%	226	6	97.3%
473		1	0	100.0%	233	15	93.6%	1	0	100.0%	230	10	95.7%
474		1	0	100.0%	229	66	71.2%	1	0	100.0%	214	71	66.8%
478	51	1	1	0.0%	225	37	83.6%	1	1	0.0%	223	29	87.0%
479		1	0	100.0%	232	36	84.5%	1	0	100.0%	230	36	84.3%
486		1	0	100.0%	236	35	85.2%	1	0	100.0%	230	61	73.5%
494	81	1	1	0.0%	239	48	79.9%	1	1	0.0%	231	65	71.9%
495		1	0	100.0%	220	4	98.2%	1	0	100.0%	218	3	98.6%
500		1	0	100.0%	310	16	94.8%	1	0	100.0%	307	36	88.3%
502	27	1	0	100.0%	318	19	94.0%	1	1	0.0%	314	62	80.3%
503		1	1	0.0%	332	41	87.7%	1	0	100.0%	325	102	68.6%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		1	0	100.0%	336	20	94.0%	1	0	100.0%	334	99	70.4%
505	16	1	0	100.0%	328	43	86.9%	1	1	0.0%	323	92	71.5%
506	49	1	1	0.0%	331	57	82.8%	1	1	0.0%	323	52	83.9%
507		1	0	100.0%	336	49	85.4%	1	0	100.0%	336	115	65.8%
508		1	0	100.0%	331	43	87.0%	1	0	100.0%	327	81	75.2%
509	16	1	1	0.0%	317	16	95.0%	1	1	0.0%	317	72	77.3%
511		1	0	100.0%	312	25	92.0%	1	0	100.0%	311	53	83.0%
516	16	1	0	100.0%	327	35	89.3%	1	1	0.0%	326	147	54.9%
517		1	0	100.0%	336	8	97.6%	1	0	100.0%	332	150	54.8%
518	80	1	1	0.0%	336	47	86.0%	1	1	0.0%	334	233	30.2%
519	No OS	1	1	0.0%	327	10	96.9%	1	1	0.0%	325	73	77.5%
520		1	1	0.0%	195	30	84.6%	1	0	100.0%	190	11	94.2%
521		1	0	100.0%	233	7	97.0%	1	0	100.0%	232	31	86.6%
522		1	0	100.0%	233	43	81.5%	1	0	100.0%	230	24	89.6%
523		1	0	100.0%	233	9	96.1%	1	0	100.0%	232	26	88.8%
524		1	0	100.0%	232	17	92.7%	1	0	100.0%	229	27	88.2%
525		1	0	100.0%	230	16	93.0%	1	0	100.0%	226	15	93.4%
526		1	0	100.0%	207	41	80.2%	1	0	100.0%	204	18	91.2%
527		1	0	100.0%	233	10	95.7%	1	0	100.0%	231	40	82.7%
528	88	1	0	100.0%	233	19	91.8%	1	1	0.0%	232	33	85.8%
529		1	0	100.0%	233	13	94.4%	1	0	100.0%	232	65	72.0%
530		1	1	0.0%	187	19	89.8%	1	0	100.0%	187	38	79.7%
531		1	1	0.0%	207	15	92.8%	1	0	100.0%	207	13	93.7%
532		1	1	0.0%	233	58	75.1%	1	0	100.0%	231	35	84.8%
534		1	0	100.0%	192	28	85.4%	1	0	100.0%	189	17	91.0%
535		1	1	0.0%	219	27	87.7%	1	0	100.0%	214	28	86.9%
536		1	0	100.0%	233	64	72.5%	1	0	100.0%	229	41	82.1%
537		1	1	0.0%	202	25	87.6%	1	0	100.0%	196	25	87.2%
538		1	0	100.0%	233	26	88.8%	1	0	100.0%	232	46	80.2%
539		1	0	100.0%	187	28	85.0%	1	0	100.0%	187	82	56.1%
540		1	0	100.0%	232	44	81.0%	1	0	100.0%	222	21	90.5%
541	64	1	1	0.0%	232	26	88.8%	1	1	0.0%	225	42	81.3%
542	18	1	0	100.0%	232	25	89.2%	1	1	0.0%	229	42	81.7%
543		1	0	100.0%	233	28	88.0%	1	0	100.0%	233	73	68.7%
544		1	0	100.0%	231	22	90.5%	1	0	100.0%	227	22	90.3%
545		1	1	0.0%	233	21	91.0%	1	0	100.0%	230	29	87.4%
547		1	0	100.0%	233	47	79.8%	1	0	100.0%	233	54	76.8%
549		1	0	100.0%	228	27	88.2%	1	0	100.0%	218	20	90.8%
550		1	1	0.0%	187	21	88.8%	1	0	100.0%	187	44	76.5%
551		1	0	100.0%	229	23	90.0%	1	0	100.0%	219	23	89.5%
562		1	0	100.0%	327	27	91.7%	1	0	100.0%	322	37	88.5%
564	36	1	0	100.0%	328	19	94.2%	1	1	0.0%	320	44	86.3%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
566		1	0	100.0%	326	29	91.1%	1	0	100.0%	323	54	83.3%
567		1	0	100.0%	213	11	94.8%	1	0	100.0%	211	14	93.4%
572		1	0	100.0%	323	27	91.6%	1	0	100.0%	315	95	69.8%
573		1	0	100.0%	325	44	86.5%	1	0	100.0%	317	58	81.7%
579		1	0	100.0%	213	14	93.4%	1	0	100.0%	206	45	78.2%
580	51	1	1	0.0%	328	19	94.2%	1	1	0.0%	321	38	88.2%
581	30	1	0	100.0%	328	58	82.3%	1	1	0.0%	325	76	76.6%
584	43	1	0	100.0%	212	32	84.9%	1	1	0.0%	205	133	35.1%
587		1	0	100.0%	320	21	93.4%	1	0	100.0%	311	65	79.1%
588		1	0	100.0%	211	23	89.1%	1	0	100.0%	209	43	79.4%
591	26	1	1	0.0%	325	27	91.7%	1	1	0.0%	318	50	84.3%
593	39	1	1	0.0%	318	54	83.0%	1	1	0.0%	295	42	85.8%
595		1	1	0.0%	321	61	81.0%	1	0	100.0%	318	73	77.0%
600		1	0	100.0%	241	9	96.3%	1	0	100.0%	239	22	90.8%
601		1	0	100.0%	224	90	59.8%	1	0	100.0%	221	27	87.8%
605		1	1	0.0%	231	140	39.4%	1	0	100.0%	227	23	89.9%
607		1	0	100.0%	240	30	87.5%	1	0	100.0%	237	25	89.5%
609		1	0	100.0%	231	23	90.0%	1	0	100.0%	230	23	90.0%
622	73	1	0	100.0%	138	35	74.6%	1	1	0.0%	135	6	95.6%
626		1	0	100.0%	145	20	86.2%	1	0	100.0%	143	18	87.4%
639		1	0	100.0%	211	40	81.0%	1	0	100.0%	209	20	90.4%
640		1	0	100.0%	231	7	97.0%	1	0	100.0%	229	84	63.3%
641	33	1	0	100.0%	213	43	79.8%	1	1	0.0%	213	28	86.9%
642		1	0	100.0%	229	11	95.2%	1	0	100.0%	228	27	88.2%
643		1	0	100.0%	243	44	81.9%	1	0	100.0%	240	39	83.8%
644		1	0	100.0%	235	28	88.1%	1	0	100.0%	233	56	76.0%
645		1	0	100.0%	243	42	82.7%	1	0	100.0%	240	55	77.1%
646		1	1	0.0%	232	57	75.4%	1	0	100.0%	230	113	50.9%
647		1	1	0.0%	243	36	85.2%	1	0	100.0%	241	51	78.8%
648		1	0	100.0%	239	59	75.3%	1	0	100.0%	239	35	85.4%
649		1	0	100.0%	244	44	82.0%	1	0	100.0%	240	34	85.8%
650		1	0	100.0%	243	45	81.5%	1	0	100.0%	240	39	83.8%
651		1	0	100.0%	243	17	93.0%	1	0	100.0%	240	43	82.1%
652		1	0	100.0%	244	31	87.3%	1	0	100.0%	240	41	82.9%
653	24	1	0	100.0%	232	36	84.5%	1	1	0.0%	228	42	81.6%
654		1	0	100.0%	233	44	81.1%	1	0	100.0%	229	20	91.3%
655	122	1	1	0.0%	241	75	68.9%	1	1	0.0%	238	77	67.6%
656		1	0	100.0%	243	54	77.8%	1	0	100.0%	241	33	86.3%
657	87	1	0	100.0%	232	29	87.5%	1	1	0.0%	230	31	86.5%
658		1	0	100.0%	243	37	84.8%	1	0	100.0%	241	35	85.5%
680		1	0	100.0%	238	12	95.0%	1	0	100.0%	236	27	88.6%
681		1	0	100.0%	238	18	92.4%	1	0	100.0%	231	93	59.7%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
682		1	0	100.0%	237	9	96.2%	1	0	100.0%	237	42	82.3%
683		1	0	100.0%	220	18	91.8%	1	0	100.0%	219	75	65.8%
684		1	0	100.0%	219	37	83.1%	1	0	100.0%	219	47	78.5%
685		1	0	100.0%	234	33	85.9%	1	0	100.0%	231	55	76.2%
686		1	0	100.0%	239	39	83.7%	1	0	100.0%	238	52	78.2%
687		1	0	100.0%	238	38	84.0%	1	0	100.0%	237	40	83.1%
688		1	0	100.0%	237	15	93.7%	1	0	100.0%	236	41	82.6%
701		1	0	100.0%	268	30	88.8%	1	0	100.0%	265	32	87.9%
702	33	1	0	100.0%	335	36	89.3%	1	1	0.0%	332	84	74.7%
703	No OS	1	1	0.0%	336	113	66.4%	1	1	0.0%	334	101	69.8%
704	29	1	0	100.0%	267	49	81.6%	1	1	0.0%	259	60	76.8%
710	19	1	1	0.0%	336	80	76.2%	1	1	0.0%	332	89	73.2%
711	22	1	1	0.0%	327	39	88.1%	1	1	0.0%	304	66	78.3%
712		1	0	100.0%	333	91	72.7%	1	0	100.0%	323	114	64.7%
713	29	1	0	100.0%	203	20	90.1%	1	1	0.0%	178	81	54.5%
714	26	1	1	0.0%	217	93	57.1%	1	1	0.0%	201	96	52.2%
715	17	1	0	100.0%	335	63	81.2%	1	1	0.0%	306	156	49.0%
716	169	1	1	0.0%	336	144	57.1%	1	1	0.0%	327	142	56.6%
717	103	1	1	0.0%	321	80	75.1%	1	1	0.0%	296	99	66.6%
718	89	1	1	0.0%	336	179	46.7%	1	1	0.0%	333	130	61.0%
719		1	0	100.0%	336	113	66.4%	1	0	100.0%	319	98	69.3%
757	23	1	0	100.0%	121	7	94.2%	1	1	0.0%	120	15	87.5%
761		1	0	100.0%	332	13	96.1%	1	0	100.0%	329	44	86.6%
765	51	1	0	100.0%	332	25	92.5%	1	1	0.0%	332	47	85.8%
769	30	1	0	100.0%	332	27	91.9%	1	1	0.0%	325	66	79.7%
770		1	0	100.0%	332	25	92.5%	1	0	100.0%	329	104	68.4%
774		1	0	100.0%	332	17	94.9%	1	0	100.0%	330	80	75.8%
777	16	1	0	100.0%	217	13	94.0%	1	1	0.0%	216	59	72.7%
782	91	1	0	100.0%	217	105	51.6%	1	1	0.0%	212	37	82.5%
785		1	0	100.0%	332	29	91.3%	1	0	100.0%	332	61	81.6%
786		1	0	100.0%	121	23	81.0%	1	0	100.0%	117	66	43.6%
790		1	0	100.0%	332	31	90.7%	1	0	100.0%	329	54	83.6%
794		1	0	100.0%	332	40	88.0%	1	0	100.0%	328	76	76.8%
821		1	0	100.0%	330	6	98.2%	1	0	100.0%	330	140	57.6%
822	Cncld	1	1	0.0%	332	19	94.3%	0	0	0.0%	329	170	48.3%
1333		1	0	100.0%	332	40	88.0%	1	0	100.0%	329	112	66.0%
1340		1	0	100.0%	331	7	97.9%	1	0	100.0%	330	56	83.0%
1689		1	0	100.0%	112	6	94.6%	1	0	100.0%	111	14	87.4%
2102		1	0	100.0%	90	16	82.2%	1	0	100.0%	89	7	92.1%
2103		1	0	100.0%	154	14	90.9%	1	0	100.0%	153	10	93.5%
2104		1	0	100.0%	180	10	94.4%	1	0	100.0%	178	13	92.7%
2105		1	0	100.0%	2	1	50.0%	1	0	100.0%	2	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 9/1/2026

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2107		1	0	100.0%	211	35	83.4%	1	0	100.0%	208	21	89.9%
2108		1	0	100.0%	211	28	86.7%	1	0	100.0%	205	27	86.8%
2109		1	0	100.0%	104	13	87.5%	1	0	100.0%	102	6	94.1%
2112		1	0	100.0%	51	6	88.2%	1	0	100.0%	49	2	95.9%
2113		1	0	100.0%	90	9	90.0%	1	0	100.0%	90	10	88.9%
2115		1	0	100.0%	90	13	85.6%	1	0	100.0%	89	12	86.5%
2116		1	0	100.0%	51	1	98.0%	1	0	100.0%	51	8	84.3%
2118		1	0	100.0%	51	4	92.2%	1	0	100.0%	51	12	76.5%
2119		1	0	100.0%	51	8	84.3%	1	0	100.0%	50	12	76.0%
2120		1	0	100.0%	51	19	62.7%	1	0	100.0%	49	23	53.1%
2123		1	1	0.0%	89	11	87.6%	1	0	100.0%	88	15	83.0%
2124		1	0	100.0%	182	38	79.1%	1	0	100.0%	180	24	86.7%
2126		1	0	100.0%	99	26	73.7%	1	0	100.0%	98	22	77.6%
2127		1	0	100.0%	51	10	80.4%	1	0	100.0%	50	9	82.0%
2128		1	0	100.0%	51	4	92.2%	1	0	100.0%	51	3	94.1%
2131		1	0	100.0%	51	10	80.4%	1	0	100.0%	51	6	88.2%
2150		1	0	100.0%	204	22	89.2%	1	0	100.0%	201	75	62.7%
2151	32	1	0	100.0%	153	7	95.4%	1	1	0.0%	151	42	72.2%
2152		1	0	100.0%	109	7	93.6%	1	0	100.0%	108	31	71.3%
2154	Cncld	1	0	100.0%	112	23	79.5%	0	0	0.0%	107	45	57.9%
2155	18	1	0	100.0%	213	17	92.0%	1	1	0.0%	209	103	50.7%
2156		1	0	100.0%	2	0	100.0%	1	0	100.0%	2	0	100.0%
2158		1	0	100.0%	50	6	88.0%	1	0	100.0%	50	16	68.0%
2159		1	0	100.0%	206	16	92.2%	1	0	100.0%	204	69	66.2%
2160		1	0	100.0%	51	2	96.1%	1	0	100.0%	50	28	44.0%
2162		1	0	100.0%	212	23	89.2%	1	0	100.0%	206	91	55.8%
2163		1	0	100.0%	164	17	89.6%	1	0	100.0%	158	69	56.3%
2165		1	0	100.0%	48	4	91.7%	1	0	100.0%	48	21	56.3%
2167	20	1	1	0.0%	199	21	89.4%	1	1	0.0%	199	42	78.9%
2171		1	0	100.0%	140	10	92.9%	1	0	100.0%	136	23	83.1%
2190		1	0	100.0%	209	29	86.1%	1	0	100.0%	207	24	88.4%

Amtrak Endpoint OTP Details

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2151	WAS	32	DCS	24	DCS	18	XSH-NYP	AM	T.O.L, Other, XM9-XPB, TOL ON 2 TRK
2154	BOS	Trn Cancelled	CAR	5	CAR	5	BWI-BAL	AM	Air / Brake / Wheel, 3532 LH LC, Stopped at MP 94.9 inspecting smell from brakes A/C brake plungers protruding.
2155	WAS	18	DCS	19	DCS	14	XSH-NYP	AM	T.O.L, Other, XM9-XPB, TOL ON 2 TRK
2167	WAS	20	OTH	12	ENG	8	BOS-BOS	AM	Other electrical failure, 2016 LH LP, UNKNOWN SPEED RESTRICTION PENALTY
66	BOS	36	SVS	26	SVS	26	NHV-NHV	AM	Pick up equipment, ADD ENG 105 TO CONSIST
85	WAS	60	ENG	71	ENG	39	NHV-NHV	MN	Air / Brake Added engine 651 at NHV, 603
95	NFK	57	WTR	45	DCS	28	XSH-NYP	AM	T.O.L, Other, XM9-XPB, TOL ON 2 TRK BETWEEN MANOR & PELHAM BAY
129	WAS	119	DET	81	DET	81	NYP-NYP	AM	Catenary maintenance , Other, SSYD, delayed departing NYS, due to a catenary power issue, the engine is stuck inside the engine house.
136	SPG	144	ENG	323	ENG	139	WND-WND	AM	Air / Brake, 85 DX BD, BAD COMPRESSOR
137	WAS	21	OTH	14	DSR	13	BRP-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 2
141	WAS	73	ITI	44	ITI	44	SPG-SPG	AM	Service, turn, or wye train, 136
171	RNK	39	DSR	32	CTI	10	XSH-NYP	AM	Cross Traffic, LG, LI751, Other, XHR
179	PHL	23	SMW	30	SMW	14	TRE-XHM	AM	Diversions around M/W work, Other, XGY-XHM, OPR ON NO.2 TRACK A/C 3 TRACK O/O/S DUE TO TEST TRAIN ON NO.3 TRACK AT GRUNDY.
193	WAS	28	CTI	20	SMW	12	WIL-NRK	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 3 track o/s between Davis & Bacon
197	WAS	32	PTI	23	SMW	10	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 3 track o/s between Davis & Bacon
470	HFD	17	CON	15	CON	15	NHV-NHV	AM	Hold for connecting train
478	SPG	51	SVS	20	SVS	20	NHV-NHV	AM	Fuel, AM478 may be late dp NHV a/c AM479 equip needs refuel
494	GFD	81	ITI	61	ITI	61	NHV-NHV	AM	Service, turn, or wye train, 417, Short turn of 417 today a/c 475 cancelled
79	CLT	42	WTR	60	WTR	22	PTB-RMT	CS	Heat order Other, PTB to RMT

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/1/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
622	PHL	73	WTR	82	WTR	55	LNC-PAR	AM	Trees down, Control Point, ., SINGLE TRACKING BETWEEN PARK AND PAOLI A/C TREE DOWN.	
641	HAR	33	ENG	29	ENG	29	PHL-PAO	AM	Undesired emergency application, 9644 CB CC, WYE OUTBOUND, WATER LEAK IN THE CAB CAR	
653	HAR	24	SVS	26	SVS	26	PHL-ARD	AM	Unplanned Wye	
655	HAR	122	WTR	94	WTR	20	DOW-PAR	AM	Trees down, Control Point, ., SINGLE TRACKING BETWEEN PARK AND PAOLI A/C TREE DOWN.	
657	HAR	87	WTR	87	WTR	73	PAO-PAO	AM	Trees down, Control Point, ., SINGLE TRACKING BETWEEN PARK AND PAOLI A/C TREE DOWN.	
63	TWO	65	FTI	19	SVS	16	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train	
64	NYP	40	CUI	21	CUI	21	NFL-NFL	CS	U.S. Border Patrol	
68	NYP	18	FTI	60	FTI	47	SLQ-RSP	CN	Meet 323, Siding, St. Jean	
241	ALB	26	DET	27	DET	27	NYP-NYP	AM	Catenary maintenance , Other, SSYD, LATE RELEASE F/SSYD A.D CATENARY OUTAGE	
244	NYP	24	CTI	24	CTI	19	POU-CRT	MN	Follow MNRR, 880, Milepost w/Letters, cp72, cp39	
283	NFL	55	FTI	60	FTI	20	ROC-BUF	CS	Follow I003, Milepost, 371, 431, mix	
75	CLT	14	TEN	14	TEN	14	SAL-SAL	NS	HEP NC1755	
89	SAV	32	PTI	30	WTR	16	PTB-RMT	CS	Heat order Other, NE Sub	
98	NYP	61	CAR	60	CAR	60	MIA-HOL	FL	Heat / AC 25124, 68024, Stopped at the back shop Mechanical forces tried to repair coach car condensers car was hott Dining car No hot water No working Microwave Fridges not operational Mechanical took out the microwave at the station And replaced it and hot water is good	
56	SAB	33	DSR	29	MBO	13	STM-BRP	MN	For maritime traffic Control Point, 240	
41	MIA	101	FTI	96	ENG	40	LAK-TPA	CS	Unrecoverable penalty (PCS) 145	
23	NOL	200	ENG	152	ENG	152	MOE-MOE	CS	Generator Field switch failure could not be lead unit 38	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
6	CHI	75	WTR	159	WTR	104	HER-GRI	UP	Waiting for MW clearance. Broken rail due to weather., Other, mp577
528	SAC	88	TRS	73	TRS	73	OAC-OAC	UP	Vehicle on track ahead Milepost, 10.78, 10.78
541	OKJ	64	ITI	46	ITI	46	SAC-SAC	UP	Late arriving inbound train 528
542	SAC	18	DCS	27	DCS	14	MTZ-SUI	UP	Power switch failure Control Point, Vista
502	SEA	27	FTI	24	PTI	13	XNI-TAC	ST	Meet 11, Control Point, manitou
505	PDX	16	CCR	10	CCR	10	SEA-TUK	BN	PTC - On Board Cab Signal or PTC Failure 7910, Would not select track (unresolved position)
506	SEA	49	DCS	44	DCS	44	PDX-PDX	BN	PTC system failure (wayside) BNSF system PTC failure. Unable to log in. Finally logged in after 11 failed attempts and resetting PTC breaker., Other, Portland station
509	PDX	16	DCS	13	DCS	13	SEA-SEA	BN	PTC- Unplanned PTC system /server outage Control Point, SEA
516	VAC	16	PTI	20	PTI	20	STW-MVW	BN	Meet AMTK 517, Siding, Logen
518	VAC	80	PTI	36	PTI	34	BEL-X8B	BN	Meet amtk 519, Siding, custer
519	SEA	No OS Rpt	DCS	170	DCS	160	VAC-VAC	BN	PTC- Unplanned PTC system /server outage Other, CN coach yard
58	CHI	59	DSR	54	PTI	23	CDL-CEN	CC	Meet amtk59, Control Point, n boise
59	NOL	253	POL	147	POL	120	HMW-HMW	CC	Fire department hold
822	OKC	Trn Cancelled							
342	CHI	13	CTI	14	CTI	14	GLN-XWA	ME	Follow Metra, 2156, Milepost, 11, 4
350	PNT	50	PTI	43	PTI	18	XB0-XA5	MI	Meet 353, Siding, Albion
351	CHI	100	POL	88	POL	88	ARB-JXN	MI	Right of Way police hold Dead body found at cp 78. Held at JXN station
352	PNT	32	PTI	36	PTI	36	JXN-ARB	MI	Meet am355, Control Point, 75
564	SAN	36	CTI	32	CTI	21	OSD-SOL	SN	Meet coaster, Control Point, escondido jct
580	SAN	51	ENG	51	ENG	51	LAX-LAX	SC	PTC - On Board Cab Signal or PTC Failure System wide PTC outage on BNSF per DS can run without it, C2120

Amtrak Endpoint OTP Details

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
581	LAX	30	SYS	28	SYS	26	ANA-ANA	SC	PTC problem or failure (cause unknown) Attempted BNSF CNOC inspection to recycle breaker.. Initially did not fix issue It suddenly worked
584	SAN	43	CTI	28	PTI	11	OSD-SOL	SN	Follow Amtk 782, Control Point, Ponto
591	LAX	26	PTI	24	PTI	13	OSD-X98	SC	Meet 588, Control Point, songs
593	LAX	39	PTI	50	PTI	50	SAN-SAN	SN	Late arrival of inbound 792 Late due to BNSF PTC outage 782 was incoming train for 593, 782, Control Point, san
757	SLO	23	DCS	36	PTI	18	OXN-VEC	UP	Meet 770, Siding, ventura
765	SLO	51	ENG	40	ENG	40	OLT-SOL	SN	HEP Proceeded at restricted speed to CP Cudahy after restarting, C2112
769	GTA	30	DCS	36	DCS	18	GDL-BUR	SC	Flag CP Allen per DS Control Point, Allen
777	SLO	16	DCS	29	DCS	12	MPK-XMR	UP	Restrictive signal(s) from known wayside signal failure Flag the block, Red, Control Point, Los Posas
782	SAN	91	PTI	43	SYS	41	LAX-LAX	SC	PTC problem or failure (cause unknown) BNSF nation wide outage
702	BFD	33	FTI	26	PTI	11	MCD-MDR	BN	Meet AMT 701, Siding, SHARON
703	SAC	No OS Rpt	SYS	66	SYS	66	BFD-BFD	BN	PTC failure/ BNSF PTC system wide outage. Running without PTC/ max speed is 59 mph
704	BFD	29	PTI	19	FTI	9	MDR-FNO	BN	Meet BNSF 3760, Control Point, Figarden
710	BFD	19	PTI	18	DCS	14	ACA-SKN	BN	Restrictive signal(s) from unknown cause No trains were met, Stop , Control Point, W. Stockton
711	OKJ	22	FTI	17	CON	14	BFD-BFD	BN	Hold for thruway bus
713	OKJ	29	PTI	24	PTI	12	SKN-ACA	BN	Meet AMTK 714, Control Point, Trull
714	BFD	26	FTI	22	FTI	11	SKN-MOD	BN	Cross Traffic 6286, Control Point, KEDDIE JCT
715	OKJ	17	PTI	31	PTI	10	RIC-EMY	UP	Wait for station track 716, Other, emeyville depot
716	BFD	169	TSV	167	TSV	167	EMY-EMY	UP	Planned set out / pick out of locomotives, cars or section of train
717	OKJ	103	PTI	54	DCS	33	BFD-BFD	BN	PTC system failure Unable to login to PTC, permission to run cut-out., Other, BFD Depot
718	BFD	89	ITI	66	ITI	66	OKJ-OKJ	UP	Service, turn, or wye train 715

Amtrak Endpoint OTP Details

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2	NOL	Trn Cancelled	FTI	135	SVS	38	XWJ-HOS	UP	Unplanned Wye Wye train at HOS for cancel train due to weather., Other, HOS
21	SAS	No OS Rpt	FTI	399	FTI	265	TXA-MHL	UP	Meet Control Point, SULPHUR, Control Point, BIVINS, Control Point, KILDARE, Control Point, JEFFERSON, 8261, 6034, 7060, 8999, 6694, 6358
22	CHI	67	WTR	133	WTR	29	MIN-LVW	UP	Heat order Level 2 heat restriction, Milepost, 136, 89
301	STL	131	WTR	90	WTR	36	SPI-ALN	UP	Heat order Milepost, 173, 281
302	CHI	38	WTR	64	WTR	26	DWT-JOL	UP	Heat order Milepost, 173, 36
305	STL	56	WTR	65	WTR	20	JOL-DWT	UP	Heat order Milepost, 36.8, 126.4
306	CHI	55	WTR	64	WTR	20	ALN-CRV	UP	Heat order Milepost, 281.45, 173.00
307	STL	32	FTI	34	FTI	24	BNL-LCN	UP	Follow 8443, Milepost w/Letters, MCLEAN, ATHOL
382	CHI	24	SYS	23	SYS	23	QCY-QCY	BN	PTC problem or failure (cause unknown) BNSF PTC system wide outage., Control Point, West Quincy
383	QCY	Trn Cancelled	SYS	109	SYS	109	CHI-CHI	AM	PTC- IETMS Software Download Control Point, cus
390	CHI	36	FTI	22	PTI	10	CHM-RTL	CC	Meet AMTK391, Siding, Leverett
391	CDL	28	WTR	28	SYS	9	CHM-CHM	CC	Conductor working alone/crew shortage.
392	CHI	46	WTR	55	PTI	18	KKI-HMW	CC	Meet amtrak 59, Siding, powers
393	CDL	57	CTI	38	CTI	34	XCS-HMW	CC	Cross Traffic metra, Control Point, kensington
311	KCY	46	WTR	51	WTR	17	JEF-SED	UP	Heat order Other, Sedalia Sub
316	STL	77	WTR	28	DCS	19	HEM-WAH	UP	Restrictive signal(s) from unknown cause Clear At 64.6, Approach @ 69.4, Restricting @ 67.8, Milepost, 69.4, 64.6
318	CHI	171	WTR	171	WTR	22	CRV-SPI	UP	Heat order LEVEL 2 HEAT RESTRICTION, Milepost, 223.8, 185.1
319	KCY	164	WTR	148	TRS	21	JOL-DWT	UP	Vehicle on track ahead Milepost, 45.77, 45.77

Amtrak Initial Terminal Details

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/1/2026

Terminal	Train	Date	Late	Delay	Cause
MOE	23	09/01	152	152	Generator Field switch failure could not be lead unit 38
BOS	2167	09/01	8	8	Other electrical failure, 2016 LH LP, UNKNOWN SPEED RESTRICTION PENALTY
BTN	290	09/01	1		
GRO	75	09/01	1		
HAR	646	09/01	10	10	
HAR	646	09/01	10	10	Catenary failure, Control Point, HAR, POWER TRIP PANTOGRAPHS DROPPED CAUSE UNKNOWN
MIA	98	09/01	7	7	Late GTB from SFRTA Other, Miami
NFL	284	09/01	1		
NHV	478	09/01	32	20	Fuel, AM478 may be late dp NHV a/c AM479 equip needs refuel
NHV	478	09/01	32	12	Service, turn, or wye train, 479, Late turn
NHV	494	09/01	72	11	Fuel, Also necessary to refuel at NHV
NHV	494	09/01	72	61	Service, turn, or wye train, 417, Short turn of 417 today a/c 475 cancelled
NYP	19	09/01	99	99	Catenary maintenance , Other, SSYD, delayed departing NYS, due to a catenary power issue, the engine is stuck inside the engine house.
NYP	69	09/01	2	2	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	97	09/01	211	211	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C SHORTAGE OF AVAILABLE LOUNGE CARS. IT WAS NECESSARY TO WAIT FOR LOUNGE CAR TO BE RELEASED FROM THE CAR SHOP TO COMPLETE CONSIST.
NYP	129	09/01	81	81	Catenary maintenance , Other, SSYD, delayed departing NYS, due to a catenary power issue, the engine is stuck inside the engine house.
NYP	193	09/01	4	4	Catenary maintenance , Other, SSYD, delayed departing NYS, due to a catenary power issue, the engine is stuck inside the engine house.
NYP	239	09/01	2	2	Passenger and/or baggage, BOARDING
NYP	241	09/01	27	27	Catenary maintenance , Other, SSYD, LATE RELEASE F/SSYD A.D CATENARY OUTAGE
NYP	647	09/01	7	7	Wheelchair
NYP	655	09/01	14	14	Catenary maintenance , Other, SSYD, LATE RELEASE F/SSYD A/C CATENARY ISSUES IN YARD
NYP	2123	09/01	3	3	Passenger and/or baggage, BOARDING
PHL	190	09/01	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	605	09/01	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD

Amtrak Initial Terminal Details

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/1/2026

Terminal	Train	Date	Late	Delay	Cause
SPG	141	09/01	44	44	Service, turn, or wye train, 136
WAS	198	09/01	26	26	Catenary failure, Other, SUNNY SIDE YD NYP, CATENARY ISSUES AT SUNNY SIDE YD DELAYED ARRIVAL OF A85
CHI	3	09/01	56	56	Late make up of engines Other, CHI
CHI	59	09/01	114	114	HEP Replaced hep motherboard, 29
CHI	383	09/01	(Trn Cxld)	109	Engine Issue
FTW	822	09/01	(Trn Cxld)		Utility Line Issues
QCY	382	09/01	23	23	PTC problem or failure (cause unknown) BNSF PTC system wide outage., Control Point, West Quincy
SAS	22	09/01	3	3	Service, turn, or wye train 2, Waited on 422 transfer. Mechanical inspection
BFD	703	09/01	66	66	PTC failure/ BNSF PTC system wide outage. Running without PTC/ max speed is 59 mph
BFD	711	09/01	14	14	Hold for thruway bus
BFD	717	09/01	33	33	PTC system failure Unable to login to PTC, permission to run cut-out., Other, BFD Depot
EMY	6	09/01	24	24	Set out defective locomotive 81
GAC	552	09/01	16		
LAX	14	09/01	12	12	Hold for connecting train 765
LAX	580	09/01	51	51	PTC - On Board Cab Signal or PTC Failure System wide PTC outage on BNSF per DS can run without it, C2120
OKJ	520	09/01	13	13	Air / Brake / Wheel 8830, Air blowing hard under engineer side of Cap car
OKJ	532	09/01	2	2	Meet 537 working inside, 537, Other, jack london square
OKJ	710	09/01	1	1	PTC - On Board Cab Signal or PTC Failure C6964, Per engineer, departing OKJ, cab car PTC display, all soft key buttons displays disappeared from screen and red fence stayed displayed
OKJ	714	09/01	5	5	Meet WAIT IN YARD FOR 711 TO COME IN., 711, Control Point, MAGNOLIA
OKJ	716	09/01	(Trn Cxld)		Third Party Engine Failure
OKJ	718	09/01	28	14	Routine inspections Flags dropped 17:40
OKJ	718	09/01	28	14	Water, commissary, toilet/trash dumping Flags dropped 17:40
PDX	506	09/01	44	44	PTC system failure (wayside) BNSF system PTC failure. Unable to log in. Finally logged in after 11 failed attempts and resetting PTC breaker., Other, Portland station
PDX	518	09/01	7	7	PTC problem or failure (cause unknown) PTC screen frozen. Reset PTC breaker and radio breaker to see if it would restart. Had to call CNOC mechanical to remote login to reset it. Called BNSF for train manifest as well

Amtrak Initial Terminal Details

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/1/2026

Terminal	Train	Date	Late	Delay	Cause
SAC	531	09/01	4	4	Wheelchair
SAC	535	09/01	1	1	Restrictive signal(s) from unknown cause Stop, Control Point, RV989
SAC	537	09/01	8	8	Engine shutdown multiple times. With low oil faults. Tasi Oakland was notified. Sac mechanical restarted engine more than once and wa able to get it to stabilize. JPBX921
SAC	541	09/01	46	46	Late arriving inbound train 528
SAC	545	09/01	2	2	PTC problem or failure (cause unknown) Issue logging into PTC. Had to wait for PTC to initialize, Other, Sac depot track 6
SAN	591	09/01	11	11	Service, turn, or wye train 580, Late 580 due to BNSF PTC outage
SAN	593	09/01	50	50	Late arrival of inbound 792 Late due to BNSF PTC outage 782 was incoming train for 593, 782, Control Point, san
SAN	595	09/01	17	17	Service, turn, or wye train 584
SEA	8	09/01	154	154	PTC- Unplanned PTC system /server outage Other, seattle
SEA	11	09/01	5	5	Passenger and/or baggage Late gate closure and late bike release. This was due to the TAC having a large line and making no apparent attempts to expedite the process.
SEA	503	09/01	10	10	PTC - On Board Cab Signal or PTC Failure Due to PTC and speedometer failure on the 90252 required to Y train and crew change ends per mechanical, 90252
SEA	509	09/01	13	13	PTC- Unplanned PTC system /server outage Control Point, SEA
SJC	530	09/01	1		
SJC	550	09/01	2	2	Door C8805, Service door A-End jammed
SPK	27	08/30	5	5	HEP 39021, HEP cable on the receptacle side is bad (engineer side). When you wiggle the cable it goes train line incomplete.
VAC	519	09/01	160	160	PTC- Unplanned PTC system /server outage Other, CN coach yard

Eastern Region

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.3	98.3	94.8	342	6
CDOT	95.0	90.0	90.0	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	93.5	93.5	88.6	355	23
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Multiple Locations - PH Line - Weather Related Delays

02SEP26: An intense line of storm weather moved through the Southeastern, Pennsylvania region between the hours of 7:30pm and 9:30pm. The severe weather left multiple errant track occupancy lights, fallen trees in the catenary, and caused 100 HZ outages at State/MP 104.3, Rheems/MP 83.4, Caln/MP 36.6, and Thorn/MP 35.1. Trans traveling through these impacted interlockings had to proceed at restricted speed. 100 HZ Power was returned to all interlockings by 10:54pm.

Train	Delay	Comment
655 (01)	1'22"	
657 (01)	1'13"	
622 (01)	55"	

New York, NY - Sunnyside Yard - Catenary or Wayside Failure

01SEP26: At 415P-ET, New York reported an emergency plate order was in affect due to no overhead catenary power in Sunnyside yard and Sub 2 and Line 4. As of 425P-ET, The 2 lead and the upper body tracks AC Power was restored. Sub 1 was ok for AC moves. Train 129(01) was in the power outage and needed to be rescued with a diesel after ET gave the ok to move. Train 97(01) was also further delayed getting into the station.

Train	Delay	Comment
129 (01)	1'21"	
19 (01)	1'39"	
241 (01)	27"	
655 (01)	14"	

Train 41(30) South of Lakeland, FL - Engine Failure

01SEP26: Train 41(30) with E/145, E/199 and 10 cars with 101 customers onboard was delayed on the CSX Carters subdivision at MP 879.4 due to having an unrecoverable penalty on E/145.

Train	Delay	Comment
41 (30)	40"	

Train 68(01) South of St-Lambert, QC - Freight Train Interference

01SEP26: Train 68(01) with E/118 and 15 cars with 118 customers onboard was delayed on the CN Rouses Point at MP 24.7 due to meeting CN 323.

Train	Delay	Comment
68(01)	47"	

New York, NY - Late Release from the Yard - Servicing

01SEP26: Trains 19(01) and 97(01) were both delayed departing New York due to the late release from the yard.

Train 19(01) was holding for an E/660 off inbound 98(31) that arrived at 1151A-ET 1 hour and 1 minute late.

Train 97(01) was late being release due to making up a double header with E/632, E/604. They were further delayed departing the yard due to Sunnyside having AC power outage.

Train	Delay	Comment
19(01)	1'39"	
97(01)	3'31"	

Train 85(01) East of Providence, RI - Engine Failure

01SEP26: Train 85(01) with E/603 and 9 cars with 343 customers onboard was delayed at MP 168.7/Davisville on track 1 account the pantograph dropped and dropped again at Kingston station. The crew was able recycle and reconfigure the pantographs.

Upon arrival into New Haven the capped it with E/651.

Train	Delay	Comment
85(01)	32"	PVD-OSB
85(01)	39"	ADDING ENG NHV

CSX Heat Orders - Weather

01SEP26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Monon, Baltimore Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, North End, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Lakeland, Nahunta, Savannah and Tampa Terminal.

Train	Delay	Comment
95(01)	43"	
53(01)	28"	
98(01)	17"	
125(01)	31"	
79(01)	50"	
186(01)	28"	
90(01)	51"	
40(01)	52"	
89(01)	46"	
138(01)	27"	
171(01)	03"	
80(01)	29"	
40(31)	17"	
97(31)	26"	
41(31)	14"	

Train 170(01) North of New York, NY - Signal

01SEP26: Train 170(01) with E/615, E/616 and 10 cars with 427 customers onboard was delayed on the Amtrak NYS Line due to TOL's on track 2 between MP 2.7/Pelham Bay and MP 0.2/Manor.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
170(01)	33"	

Train 98(01) North of Miami, FL - Passenger Train Interference

01SEP26: Train 98(01) with E/5, E/61 and 10 cars with 60 customers onboard was delayed on the SFRTA South at MP 1025.6 meeting 2 Tri Rails P608 and P301.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(01)	38"	

Train 97(31) South of Yemassee, SC - Freight Train Interference

01SEP26: Train 97(31) with E/174, E/369 and 10 cars with 187 customers onboard was delayed on the CSX Charleston subdivision at MP 477.4 due to meeting CSX M494-01.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(31)	32"	

Train 2154(01) Baltimore, MD - Engine Failure

01SEP26: At 913A-ET, Legacy Train 2154(01) with set 11 PC/2036, PC/2017 the engineer requested mechanical and Road Foreman assistance due to a brake smell. Mechanical was inspecting the equipment. As of 942A-ET, After they performed a brake test and during the roll by mechanical stopped the train and requested the train reverse back into the station for further inspection. Mechanical found a sticking brake on C/3532 and had to cut out a truck. Train 2154(01) equipment was returned to Washington.

It was determined to transfer the customers to 182(01) and train 2193(01) was cancelled Boston to New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2154(01)	TERM BAL	
2193(01)	CANCELLED	
182(01)	16"	

Train 41(31) North of Pittsburgh, PA - Struck Tree/Debris

01SEP26: Train 41(31) with E/356, E/319 and 10 cars with 139 customers onboard reported that they struck a tree at MP 305.1 that damaged the HEP cable between E/319 and C/25095. The crew was able to secure the cables and operated dark into Connellsville. Pittsburgh mechanical was enroute to Connellsville and Amtrak Road Foreman was enroute.

Mechanical and the Train arrived into Connellsville as of 815A-ET. After accessing the damage mechanical determined they were able to short loop between E/319 AND C/25095. The HEP was restored as of 900A-ET and the train was able to proceed south.

Train 41(31) was further delayed in Washington due to C/25095 being removed and 2 new diesels being worked up.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(31)	2'02"	
41(31)	37"	WAS

Train 136(31) - South of Springfield, MA - Engine Failure

01SEP26: Train 136(31) 26-F01-00731 00000008772 8 UNCLASSIFIED 9/18/2026 trying to get passengers stopped at MP 43.2 on the Amtrak Springfield, MRS Line after the compressor on E/85 failed. The crew consulted with the on duty Road Foreman but could not resolve the issue. A Rescue set was readied at Springfield by the switcher crew. The Shuttle set with E/86 plus one car plus the cab car 9636 was used to rescue the disabled Train 136(01).

Due to the failure of E/85, DH Train 5552(01) and Train 425(01) were cancelled with alternate bus transportation being provided for the passengers ticketed for Train 425(01). Dattco secured one bus for 425(01)

Due to the shortage of engines Train 475(01) was cancelled and 2 buses were confirmed for alternate transportation Dattco bus #1 will operate SPG-WNL-WND-HFD-NHV and Bus #2 will operate from HFD-BER-MDN-WFD-STS-NHV

WBS#: B.TR.100151.0846

Train	Delay	Comment
425(01)	Cancelled	
136(31)	2'10"	
DH 5552(01)	Cancelled	
141(01)	44"	Turn off late 136(01)
475(01)	Cancelled	
494(01)	1'12"	Short turn off 417(01)

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

Train	Delay	Comment
240(29)	29"	
280(29)	18"	
233(29)	54"	
283(29)	64"	
284(29)	39"	
291(29)	36"	
290(29)	47"	
49(29)	49"	
235(29)	49"	
48(28)	31"	
237(29)	36"	
239(29)	1'10"	
69(30)	51"	
240(30)	35"	
1233(30)	18"	
291(30)	45"	LATE TURN OFF 240(30)

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

- Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.
- Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.
- Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.
- Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.
- Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.
- Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.
- Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct), will operate on an adjusted schedule.
- Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.
- Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.
- Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.
- Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.
- Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008772 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008772 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 80(01) Passenger Removal at Cary, North Carolina – Improper Conduct

01SEP26, Passenger on PNR DA1F25, traveling from Durham, NC to Richmond Staples Mills, VA was reportedly removed by local police due to disruptive behavior and using foul language towards crew. Amtrak Police notified.

Delay: 80(01) 02"

Western Region

Operating Highlights

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Train 519(01) North of Everett, WA - Freight Train Interference

01SEP26: Train 519(01) was delayed on the BNSF Scenic subdivision just north of Everett at PA Jct./MP 1782.5 due to meeting unknown BNSF.

Train	Delay	Comment
519(01)	35"	

Train 519(01) North of Bellingham, WA - Freight Train Interference

01SEP26: Train 519(01) was delayed on the BNSF Bellingham subdivision 13 miles north of Bellingham at Ferndale/MP 106.4 due to meeting BNSF 4289.

Train	Delay	Comment
519(01)	44"	

Train 703(01) East of Fresno, CA - Passenger Train Interference

01SEP26: Train 703(01) was delayed on the BNSF Stockton subdivision 10 miles east of Fresno at Bowles/MP 989.2 due to meeting train 716(01).

Train	Delay	Comment
703(01)	38"	

Train 518(01) North of Bellingham, WA - Passenger Train Interference

01SEP26: Train 518(01) was delayed on the BNSF Bellingham subdivision 18 miles north of Bellingham at Custer/MP 111.2 due to meeting train 519(01).

Train	Delay	Comment
518(01)	34"	

Train 3(31) West of Winslow, AZ - Freight Train Interference

01SEP26: Train 3(31) with 109 customers was delayed on the BNSF Seligman subdivision starting three miles west of Winslow between West Winslow/MP 288.0 and East Flagstaff/MP 340.8 due to following BN 6532.

Train	Delay	Comment
3(31)	1'11"	

Train 22(01)/422(30) Marshall, TX - Crew Rest

01SEP26: Train 22(01)/422(30), with 135 customers onboard, was delayed at Marshall, TX/MP66.5 on the UP Little Rock subdivision due to the outbound crew's sign up time of 9:08PM CT. Once the outbound crew had control of the equipment, train 22(01)/422(30) departed Marshall and continued north.

Train	Delay	Comment
22(01)/422(30)	1'04"	

Train 352(01) West of Jackson, MI - Passenger Train Interference

01SEP26: Train 352(01) with 1153 customers onboard was delayed at Control Point 75/MP75.7, 0.2 miles west of Jackson, MI/MP75.5, on the Michigan DOT Michigan Line subdivision meeting Amtrak 355(01). Once the route was clear, train 352(01) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(01)	36"	

Train 59(01) Chicago, IL - Engine Failure

01SEP26: Train 59(01), with engine 29, 7 cars, and 137 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to HEP problems on engine 29. Chicago Mechanical repaired the HEP system and the equipment was released again. Once train 59(01) shoved into the depot, the customers boarded and train 59(01) departed Chicago.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(01)	1'54"	

Train 393(01) Homewood, IL - Commuter Train Interference

01SEP26: Train 393(01), with 116 customers onboard, was delayed at Kensington/MP14.5, 9 miles north of Homewood, IL/MP23.5, on the CN Chicago subdivision meeting Metra Commuter cross traffic. Once the route was the clear, train 393(01) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
393(01)	34"	

Train 19(31) South of Tuscaloosa, AL - Freight Train Interference

01SEP26: Train 19(31) was delayed at Eutaw / MP 232.5 on the Norfolk Southern AGS South District, 34 miles south of the Tuscaloosa, AL station, meeting freight 340 and Train 20(01).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(31)	26"	Meet NS 340
19(31)	18"	Meet 20(01)
20(01)	21"	Meet 19(31)
20(01)	16"	FTI Cross traffic

Train 3(01) Chicago, IL - Servicing

01SEP26: Train 3(01) was delayed departing the Chicago, IL Union Station due to late release of Locomotive 164 and Locomotive 57 from servicing.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(01)	56"	CHI

Train 716(01) Oakland, CA - Third Party Contractor Engine Failure

01SEP26: Train 716(01) with CC/8303, seven cars, and C/2102 originated at Emeryville due to C/2102 with derate and replaced with C/2106. Customers were accommodated between Oakland and Emeryville on train 538(01). Once the equipment was made up, released, and set in the station, 716(01) departed Emeryville at 515PM-PT, 2 hours, and 47 minutes late.

Train 528(01) Oakland, CA - Vehicle on Tracks

01SEP26: Train 528(01) with 31 passengers was delayed at Oakland Coliseum Station in Oakland, CA due to a vehicle fouling the tracks ahead. The vehicle was reported north of Oakland Coliseum (N/OAC) at MP 10.78 on the Niles Subdivision. As a safety precaution, all rail traffic was stopped in the affected area while a tow truck was dispatched to remove the vehicle from the right-of-way. A track inspector responded to the scene to assess conditions and ensure the track was safe for service before train operations resumed. The delay resulted from the trespass incident and the time required to clear the obstruction and inspect the track.

Service Recovery initiated- 20% Cafe Discount

Capitol Corridor Voucher

Train	Delay	Comment
528 (01)	1'13"	
541 (01)	46"	Late turn

Train 58(01) North of New Orleans, LA - Switch Failure

01SEP26: Train 58(01) was delayed at East Bridge Junction / MP 906.4 on the Canadian National McComb Subdivision 9 miles north of the New Orleans, LA Union Passenger Terminal, account of a switch failure. The crew was instructed to manually line the switch.

Train	Delay	Comment
58 (01)	30"	

Train 503(01) Seattle, WA - Cab Car Failure

01SEP26: Train 503(01) with 88 customers was delayed departing Seattle, WA, on the BNSF Seattle Subdivision. While en route to the station, the crew reported a PTC failure and speedometer issue on cab car 90252. Mechanical personnel responded and inspected the equipment but determined that repairs could not be completed because the necessary parts were unavailable. To mitigate the issue and maintain service, the crew was instructed to wye the train at Stacy Yard after departure so the train could be operated from locomotive E/186. The delay was attributed to mechanical issues affecting the cab car and the operational adjustments required to reposition the train for safe operation.

Train	Delay	Comment
503 (01)	10"	Yard to Station
503 (01)	26"	WYE

Train 4(31) North of Gallup, NM - Broken Rail

01SEP26: Train 4(31) with 136 customers was held at MP 107 on the BNSF Gallup Subdivision, north of Gallup, NM, due to a broken rail. The rail defect was located on Main Track 1 between East Grants (MP 94.3) and McCartys (MP 82.6). As a result of the damaged rail, operations were restricted to single-tracking through the affected territory, causing delays to train movements. Train 4(31) remained stopped until traffic conditions allowed for movement through the single-track area.

Train	Delay	Comment
4 (31)	54"	

Train 765(01) San Diego, CA - Engine Failure

01SEP26: Train 765(01) with 61 passengers UNCLASSIFIED at Old Town San Diego, CA (MP 264.1) on the SCRRA/Metrolink Subdivision. Upon departing the station, the crew reported a loss of Head End Power (HEP) on locomotive C2112. The crew stopped the train and conducted troubleshooting efforts. San Diego Mechanical was dispatched to assist. The locomotive was subsequently restarted, and HEP was successfully restored. Service was able to continue following restoration of power.

Train	Delay	Comment
765(01)	40"	

Train 351(01) Jackson, MI - Police Related

01SEP26: Train 351(01), with 131 customers, was delayed departing the Jackson, MI station, account of a police investigation of a body found on the tracks at MP 78.0 on the Michigan Line, 3 miles west of the Jackson, MI station.

Three buses were secured for the customers but were canceled account the release of tracks from police and Amtrak IMCS. Customers boarding at Battle Creek and Kalamazoo were accommodated on Train 365(01).

WBS#: B.TR.100150.7123

Train	Delay	Comment
351(01)	1'12"	

Train 23(01) Mobile, AL - Engine Failure / Freight Interference

01SEP26: Train 23(01) was delayed departing the Mobile, AL station account of loading issues on Locomotive 38. The crew found the Gen Field switch was bad. The train was further delayed account of wying the train prior to departure.

Train 23(01) was delayed at Brookley / MP 000 671.1 on the CSX NO & M South Subdivision, 5 miles south of the Mobile station, meeting 606-01.

Train 23(01) was finally delayed between NOT junction / MP 7.0 and Paris Road / MP 5.9 on the Norfolk Southern New Orleans Terminal Subdivision, starting 8 miles north of the New Orleans, LA Union Passenger Terminal, following Y105.

Train	Delay	Comment
23(01)	2'32"	MOE
23(01)	38"	Brookley
23(01)	40"	NOT Jct to Paris Road

Train 21(31) Texarkana, AR - Freight Train Interference

01SEP26: Train 21(31) was delayed departing the Texarkana, AR station / MP 0.0 on the Union Pacific Little Rock Subdivision due to MBZAS-30 (UPRR 8261) separated two knuckles and caused a 5 freight train backlog. Once the MBZAS-30 (UPRR 8261) was repaired, Train 21(31) advanced to Sulphur / MP 9.0 to meet 3 freight trains. The crew on the third freight train was delayed account tying their equipment down and moving a freight train with an expired crew into Queen City Siding / MP 20.0 before advancing north.

Train 21(31) was further delayed at Jefferson / MP 51.0, 10 miles north of the Marshall, TX station, account of KCS cross traffic. Once cleared, Train 21(31) was delayed meeting 2 additional freight trains.

Train 21(30) was again delayed at Lawrence / MP 188.2 on the Union Pacific Mineola Subdivision, 29 miles east of the Dallas, TX Eddie Bernice Johnson Union Station, due to LBM59-01 (UPRR 1517) experiencing air issues. UPRR Mechanical was able to make repairs and the LBM59-01 cleared in Marith Siding / MP 198.3. Once the freight was cleared, Train 21(30) was delayed meeting Train 22(01)/422(30).

Train	Delay	Comment
21(31)	5'06"	
22(01)/422(30)	11"	East of DAL
21(31)	32"	East of DAL
21(31)	15"	Meet 22(01)/422(30)

Train 1(31) San Antonio, TX - Hold for Connection from 421(30)

01SEP26: Train 1(31) was delayed departing the San Antonio, TX station account of the late connecting section of 421(30) of Train 21/421(30). The train arrived in San Antonio at 2:47A-CDT, 4 hours and 01 minute late.

Train	Delay	Comment
1(31)	1'21"	

BNSF Systemwide Outage - System

01SEP26: 230PM-ET, BNSF conducted a change of train sheets involving a code change. After the change, multiple trains were delayed account of BNSF experiencing a nationwide train sheet outage that hampered crews from logging into PTC. The BNSF attempted to back out the application change and the back out failed. Attempts were made to utilize a server that was unchanged, which failed. Rebooting the impacted servers failed. Crews were advised to contact the dispatcher, recycle the PTC breaker, and manually enter their information to attempt to initialize during the outage.

The FRA granted BNSF a waiver under 49 CFR 236.1029(B) that permitted trains to depart without active PTC. After communicating with the dispatcher, trains that could not go active were permitted to depart without active PTC. Crews were advised to review GCOR 18.12 to determine maximum authorized speed.

Train	Delay	Comment
580 (01)	51"	LAX
3 (31)	23"	ABQ
509 (01)	13"	SEA
581 (01)	28"	SNC-ANA
506 (01)	44"	PDX
782 (01)	41"	LAX
591 (01)	11"	SAN - late turn of equip 580 (01)
593 (01)	50"	SAN - late turn of equip 782 (01)
4 (31)	33"	LAJ
6 (31)	1'00"	DEN
383 (01)	Canceled	CHI
704 (01)	17"	SKT-MOD
785 (01)	12"	SAN-ANA
6 (01)	18"	RNO
518 (01)	26"	SEA
508 (01)	11"	PDX-VAN
703 (01)	1'10"	BFD-COC
28 (01)	17"	PSC
717 (01)	46"	BFD-MTZ
7/27 (01)	35"	W/RDW
3 (01)	2'49"	W/FMD
519 (01)	2'35"	VAC-STW
3 (01)	42"	E/LAP
718 (01)	1'49"	MTZ-WAC
8 (01)	2'49"	SEA-WEN

Train 822(01) and Train 821(02) Canceled - Utility Company Failure

01SEP26: Burlington Northern Santa Fe reported several power lines down across the tracks at MP 383.5 on the Fort Worth Subdivision, 27 miles south of Gainesville, TX. The initial estimated track opening was 12:00A-CDT.

Train 822(01) with 43 customers and Train 821(02) with 36 customers were canceled in their entirety. One bus was secured for each train.

WBS#: B.TR.100150.7125

Train	Delay	Comment
822 (01)	Canceled	
821 (02)	Canceled	

Train 6(01) East of Roseville, CA - Engine Failure

01SEP26: Train 6(01), 254-POI-00731 E/206 000000087721 car UNCLASSIFIED 153 customers, was delayed at Roseville, CA, on the UPRR Martinez Subdivision. The train had been scheduled to depart Emeryville, CA, with locomotive E/81 in the lead, but E/81 was removed from service due to dynamic brake faults. With no replacement locomotive immediately available, Train 6(01) departed Emeryville operating with a single locomotive, E/206. Upon arrival at Roseville (RSV), Union Pacific Railroad (UPRR) provided locomotive UP 5179 to protect the train for continued operation. The additional locomotive was added to support the train's movement through to Chicago, IL.

Train	Delay	Comment
6(01)	1'21"	

Tropical Storm Edouardo Beaumont, TX - Weather

01SEP26: Tropical Storm Edouard made land fall and is expected to drop up to 20 inches of rain between Houston, TX and Beaumont, TX. Winds were expected in excess of 80mph. The forecast had shifted the storm east and placed it in Beaumont at the same time as Train 2(31)'s scheduled departure time. As a result the following operating plan was placed into effect:

Train 2(31) was terminated in Houston, TX.
Two buses were secured to provide alternate transportation to the 59 customers. The buses departed Houston at 1:05P-CDT, 55 minutes late

Train 1(02) will originate in Houston, TX.
Buses are being held off waiting on conditions of the storm.

WBS#: B.TR.100150.7122

Train	Delay	Comment
2(30)	Terminated	HOS
1(02)	Originate	HOS

Union Pacific Sedalia, Jefferson City Subdivision Kansas City, MO to St. Louis, MO to Joliet, IL - Heat Restrictions

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

31AUG26: Union Pacific placed Level 2 heat restrictions on the entire Sedalia and Jefferson City Sub division from Kansas City, MO and St. Louis, MO. Trains were limited to 40mph.

Train 311(31), 316(31), 318(31), and Train 319(31) were delayed account of the restrictions.

01SEP26: Union Pacific also added Level 2 heat restrictions on the Joliet and Springfield Subdivision from St. Louis, MO and Joliet, IL. Trains were limited to 50mph.

Train 311(01), Train 316(01), Train 318(01), Train 319(01), Train 301(01), Train 302(01), Train 22(31)/422(30AUG), Train 21/421(01), Train 305(01), Train 306(01) and Train 307(01) were delayed account of the restrictions.

Train	Delay	Comment
316(31)	31"	
319(31)	32"	
318(31)	14"	
311(31)	12"	
301(01)	1'30"	JOL to STL
302(01)	1'04"	LCN to JOL
311(01)	51"	HEM to KCY
305(01)	1'05"	JOL-LCN
22(31)	1'02"	ALN-JOL
307(01)	20"	JOL-DWT
21(01)	1'58"	JOL-ALN
306(01)	1'04"	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 00900008772"UNCLASSIFIED" 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		Struck rocks
22 (18)	XNT	315		I/O 47

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (1)	RSV	UP5197	E/81 shopped for dyn brake in OKJ		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 518(01) Passenger Denied Travel at Vancouver, Washington – Medical

01SEP26, Passenger on PNR DD169A, traveling from Vancouver, WA to Everett, WA was reportedly denied travel due to needing a companion to travel with. Passenger was requesting crew to perform lifesaving tasks in the event of a seizure. Amtrak Police notified.

Delay: 518(01) 06"

Consist Deviations

26-FOI-00731

00000008772

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
562 (02)	LAX	no bike space or wifi	passnegers notified no bike space no wifi	1	90225
580 (02)	LAX	no bike space or wifi	passnegers notified no bike space no wifi	1	90225
40 (01)	MIA	Due to a change in equipment it was necessary to perform a schedule change for trains 40(01) car 62514-line 4011 and 41(03) car 62514-line 4111. Please utilize the WAR report to ensure all passengers	None	0	62514
573 (02)	SAN	no bike space or wifi	passnegers notified no bike space no wifi	0	90225
591 (02)	SAN	no bike space or wifi	passneger notified no bike space no wifi	0	90225

Reverse Consists

Train Number	Station	Reason
171 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front
95 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front
178 (01)	RNK	Consist reversed Business class seat orientation may have changed At Front
138 (01)	NFK	Consist reversed Business class seat orientation may have changed At Front
141 (01)	SPG	Consist reversed Business class seat orientation may have changed At Front
125 (01)	SPG	Consist reversed Business class seat orientation may have changed At Rear
190 (01)	PHL	Consist reversed Business class seat orientation may have changed At Front
174 (01)	WAS	Consist reversed Business class seat orientation may have changed At Front
184 (01)	WAS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
136 (01)	WAS	Consist reversed Business class seat orientation may have changed At Front
198 (01)	WAS	Consist reversed Business class seat orientation may have changed At Rear
178 (02)	RNK	Consist reversed Business class seat orientation may have changed At Front
125 (02)	SPG	Consist reversed Business class seat orientation may have changed At Front
137 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front
193 (01)	WAS	Consist reversed Business class seat orientation may have changed At Rear
197 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front