



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, September 03, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/02/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/02/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	63	80.9%	655	123	81.2%	101,179	14,092	86.1%
Central Division	86.0%	58	9	84.5%	117	16	86.3%	19,312	1,791	90.7%
East Division	82.0%	178	30	83.1%	353	52	85.3%	53,173	8,186	84.6%
West Division	86.0%	93	24	74.2%	185	55	70.3%	28,694	4,115	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008773 Endpoint Arrival Dates through 9/2/26 9/18/2026 UNCLASSIFIED

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	83,653	21,354	74%	169,818	42,513	75%	33,766,956	8,629,818	74%
Northeast Corridor	81%	38,341	4,976	87%	76,245	12,933	83%	14,794,664	3,600,756	76%
Acela	83%	10,119	717	93%	19,397	2,412	88%	2,982,307	761,633	74%
Northeast Regional	79%	28,222	4,259	85%	56,848	10,521	81%	11,812,357	2,839,123	76%
Richmond / Newport News / Norfolk	77%	6,971	1,318	81%	14,619	4,215	71%	3,538,245	1,051,620	70%
Springfield Shuttles	89%	693	57	92%	1,237	150	88%	208,471	33,387	84%
Roanoke	79%	3,130	63	98%	6,204	1,294	79%	1,120,361	251,114	78%
On Spine Northeast Regional	80%	17,428	2,821	84%	34,788	4,862	86%	6,945,280	1,503,002	78%
State Supported	80%	36,220	11,648	68%	74,633	21,292	71%	14,863,570	3,232,385	78%
Borealis	80%	508	146	71%	1,075	146	86%	189,094	40,623	79%
Capitol Corridor	90%	3,978	564	86%	8,266	988	88%	1,240,391	165,376	87%
Carolinian	70%	815	378	54%	1,582	698	56%	378,967	148,817	61%
Cascades	75%	1,716	435	75%	4,049	1,495	63%	856,649	242,520	72%
Downeaster	82%	1,377	0	100%	2,771	0	100%	522,923	61,834	88%
Empire	78%	5,130	1,785	65%	10,665	3,249	70%	1,853,169	458,530	75%
Adirondack	72%	325	176	46%	615	377	39%	114,635	37,330	67%
Ethan Allen Express	70%	527	24	95%	1,035	59	94%	187,986	72,283	62%
Maple Leaf	70%	740	150	80%	1,524	640	58%	230,412	90,863	61%
New York - Albany	85%	2,332	661	72%	4,924	1,157	77%	854,357	149,713	82%
New York - Niagara Falls	75%	1,206	774	36%	2,567	1,016	60%	452,929	101,483	78%
Berkshire Flyer	60%	0	0	-	0	0	-	12,850	6,858	47%
Gold Runner	73%	1,128	822	27%	2,899	2,333	20%	833,080	311,237	63%
Heartland Flyer	70%	43	43	0%	98	43	56%	71,635	30,211	58%
Hiawatha	90%	1,539	44	97%	3,050	44	99%	587,117	63,920	89%
Illinois	78%	1,432	839	41%	2,919	1,955	33%	831,596	234,700	72%
Carl Sandburg / Illinois Zephyr	85%	255	140	45%	434	181	58%	138,247	39,541	71%
Illini / Saluki	85%	306	39	87%	808	453	44%	286,933	71,972	75%
Lincoln Service	70%	871	660	24%	1,677	1,321	21%	406,416	123,187	70%
Keystone	92%	7,713	3,384	56%	15,693	3,795	76%	2,542,301	261,556	90%
Lincoln / Missouri	70%	314	312	-1%	729	727	0%	258,366	136,179	47%
Mardi Gras Service	80%	251	0	100%	383	29	92%	133,482	29,746	78%
Michigan	70%	1,465	936	36%	3,030	1,409	53%	676,335	226,949	66%
Blue Water	70%	180	0	100%	518	22	96%	159,189	65,189	59%
Pere Marquette	85%	251	125	50%	446	128	71%	86,965	16,486	81%
Wolverine	70%	1,034	811	22%	2,066	1,259	39%	430,181	145,274	66%
Missouri	80%	107	101	6%	228	208	9%	73,617	21,457	71%
Pacific Surfliner	85%	6,458	1,134	82%	12,685	3,012	76%	2,721,130	518,811	81%
Pennsylvanian	80%	685	190	72%	1,371	190	86%	294,127	56,061	81%
Piedmont	80%	382	0	100%	770	1	100%	371,555	94,621	75%
Vermont	75%	1,179	535	55%	2,370	970	59%	428,036	129,237	70%
Long Distance	70%	9,092	4,730	48%	18,940	8,288	56%	4,069,455	1,794,214	56%
Auto Train	70%	666	0	100%	1,285	0	100%	261,448	88,756	66%
California Zephyr	70%	793	376	53%	1,659	731	56%	322,791	126,725	61%
Cardinal	70%	0	0	-	0	0	-	77,082	39,300	49%
City Of New Orleans	75%	405	405	0%	941	919	2%	210,342	73,159	65%
Coast Starlight	70%	976	363	63%	1,940	574	70%	379,113	135,272	64%
Crescent	70%	593	185	69%	1,214	261	79%	306,282	94,615	69%
Empire Builder	70%	1,001	129	87%	2,048	173	92%	323,199	161,758	50%
Floridian	60%	1,199	1,068	11%	2,600	1,651	37%	522,666	361,800	31%
Lake Shore Ltd	73%	871	265	70%	1,769	265	85%	324,457	98,395	70%
Palmetto	70%	593	501	16%	1,236	728	41%	304,406	95,506	69%
Silver Meteor	70%	343	193	44%	998	772	23%	335,500	156,232	53%
Southwest Chief	60%	748	613	18%	1,552	924	40%	278,936	184,629	34%
Sunset Ltd	70%	203	43	79%	203	43	79%	95,981	38,561	60%
Texas Eagle	70%	701	589	16%	1,495	1,247	17%	327,252	139,506	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000770 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 02, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	12,761	225,582	566	2,012,127	35,500,244	567

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	639	70,856	90	97,082	10,278,291	94
INFRASTRUCTURE PLANNED	135	1,168	70,856	165	116,704	10,278,291	114
FLEET RELIABILITY	90	1,878	225,582	83	321,537	35,500,244	91
TRAIN OPERATIONS	424	9,076	225,582	402	1,476,804	35,500,244	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/02/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	63	80.9%	655	123	81.2%	101,179	14,092	86.1%
Central Division	86.0%	58	9	84.5%	117	16	86.3%	19,312	1,791	90.7%
East Division	82.0%	178	30	83.1%	353	52	85.3%	53,173	8,186	84.6%
West Division	86.0%	93	24	74.2%	185	55	70.3%	28,694	4,115	85.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-00770 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/02/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	63	80.9%	655	123	81.2%	101,179	14,092	86.1%
Central Division	86.0%	58	9	84.5%	117	16	86.3%	19,312	1,791	90.7%
CDL	95.0%	2	1	50.0%	4	1	75.0%	640	32	95.0%
CHI	86.0%	27	4	85.2%	55	7	87.3%	8,925	1,107	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	2	1	50.0%	360	39	89.2%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	2	0	100.0%	316	11	96.5%
HOS	-	1	1	0.0%	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	4	1	75.0%	652	55	91.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	12	0	100.0%	1,971	126	93.6%
MOE	97.5%	2	0	100.0%	4	1	75.0%	671	10	98.5%
MSP	96.5%	1	0	100.0%	2	0	100.0%	330	7	97.9%
NOL	94.5%	4	0	100.0%	8	0	100.0%	1,418	64	95.5%
OKC	97.0%	-	-	-	1	0	100.0%	330	6	98.2%
PNT	88.0%	3	0	100.0%	6	0	100.0%	882	73	91.7%
PTH	93.0%	1	0	100.0%	2	0	100.0%	325	13	96.0%
QCY	91.0%	2	0	100.0%	4	1	75.0%	635	49	92.3%
SAS	90.5%	1	0	100.0%	2	1	50.0%	334	40	88.0%
STL	89.0%	4	2	50.0%	8	2	75.0%	1,304	108	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	178	30	83.1%	353	52	85.3%	53,173	8,186	84.6%
ALB	88.5%	8	2	75.0%	16	2	87.5%	2,500	190	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	10	0	100.0%	1,631	175	89.3%
BOS	85.5%	19	0	100.0%	37	1	97.3%	5,742	641	88.8%
BRK	92.5%	5	0	100.0%	10	0	100.0%	1,605	112	93.0%
BTN	82.0%	1	0	100.0%	2	1	50.0%	321	43	86.6%
CLT	91.5%	4	0	100.0%	8	0	100.0%	1,639	167	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	3	0	100.0%	651	60	90.8%
GRO	-	1	0	100.0%	2	1	50.0%	52	12	76.9%
HAR	79.5%	13	5	61.5%	26	6	76.9%	3,733	600	83.9%
HFD	-	2	0	100.0%	4	0	100.0%	236	19	91.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	2	0	100.0%	333	40	88.0%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/02/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	63	80.9%	655	123	81.2%	101,179	14,092	86.1%
East Division	82.0%	178	30	83.1%	353	52	85.3%	53,173	8,186	84.6%
MIA	89.5%	2	0	100.0%	4	1	75.0%	662	77	88.4%
MTR	79.0%	1	0	100.0%	2	0	100.0%	320	58	81.9%
NFK	84.5%	2	1	50.0%	4	1	75.0%	749	137	81.7%
NFL	93.5%	2	0	100.0%	4	1	75.0%	678	32	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	10	2	80.0%	1,712	289	83.1%
NPN	93.0%	2	1	50.0%	4	1	75.0%	638	52	91.8%
NYP	75.5%	51	16	68.6%	102	26	74.5%	14,031	3,083	78.0%
PGH	93.0%	1	0	100.0%	2	0	100.0%	334	23	93.1%
PHL	48.0%	5	2	60.0%	10	4	60.0%	1,705	803	52.9%
PIT	76.0%	-	-	-	-	-	-	24	19	20.8%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	0	100.0%	4	0	100.0%	1,268	54	95.7%
RNK	83.5%	2	0	100.0%	4	0	100.0%	662	93	86.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	2	0	100.0%	316	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	2	0	100.0%	330	12	96.4%
SFA	88.0%	1	0	100.0%	2	0	100.0%	333	47	85.9%
SPG	92.5%	5	0	100.0%	9	1	88.9%	1,971	116	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	2	0	100.0%	322	63	80.4%
WAS	84.0%	33	3	90.9%	66	4	93.9%	8,435	1,078	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	93	24	74.2%	185	55	70.3%	28,694	4,115	85.7%
ARN	92.0%	1	0	100.0%	2	0	100.0%	335	28	91.6%
BFD	79.0%	7	4	42.9%	14	7	50.0%	2,127	455	78.6%
EMY	72.0%	1	0	100.0%	2	1	50.0%	351	101	71.2%
EUG	86.5%	2	0	100.0%	4	0	100.0%	664	59	91.1%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	6	0	100.0%	1,008	172	82.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	2	81.8%	21	4	81.0%	3,340	373	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	10	23.1%	25	16	36.0%	3,644	969	73.4%
PDX	86.0%	5	2	60.0%	10	4	60.0%	1,615	229	85.8%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/02/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/02/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	63	80.9%	655	123	81.2%	101,179	14,092	86.1%
West Division	86.0%	93	24	74.2%	185	55	70.3%	28,694	4,115	85.7%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	2	87.5%	32	7	78.1%	4,751	527	88.9%
SAN	90.5%	13	1	92.3%	26	4	84.6%	4,063	396	90.3%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	16	5	68.8%	2,569	385	85.0%
SJC	89.0%	7	2	71.4%	14	4	71.4%	2,354	233	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	6	0	100.0%	771	77	90.0%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	2	1	50.0%	316	31	90.2%
VAC	97.0%	2	0	100.0%	4	1	75.0%	657	15	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		1	1	0.0%	143	13	90.9%	1	0	100.0%	142	41	71.1%
3		2	1	50.0%	335	67	80.0%	2	0	100.0%	332	157	52.7%
4	186	2	0	100.0%	334	53	84.1%	2	1	50.0%	334	222	33.5%
5		2	1	50.0%	333	58	82.6%	2	0	100.0%	329	111	66.3%
6	284	2	1	50.0%	332	92	72.3%	2	2	0.0%	332	127	61.7%
7		2	0	100.0%	324	51	84.3%	2	0	100.0%	315	86	72.7%
8		2	1	50.0%	324	146	54.9%	2	0	100.0%	323	198	38.7%
11		2	1	50.0%	335	73	78.2%	2	0	100.0%	329	67	79.6%
14		2	2	0.0%	336	56	83.3%	2	0	100.0%	333	105	68.5%
19		2	1	50.0%	334	84	74.9%	2	0	100.0%	331	82	75.2%
20		2	0	100.0%	334	23	93.1%	2	0	100.0%	334	65	80.5%
21	103	2	0	100.0%	331	36	89.1%	2	2	0.0%	330	101	69.4%
22	224	2	1	50.0%	332	38	88.6%	2	2	0.0%	330	101	69.4%
23		2	1	50.0%	336	7	97.9%	2	1	50.0%	334	91	72.8%
24		2	0	100.0%	336	16	95.2%	2	0	100.0%	335	65	80.6%
25		2	0	100.0%	335	3	99.1%	2	0	100.0%	332	94	71.7%
26		2	0	100.0%	335	5	98.5%	2	0	100.0%	332	66	80.1%
27		2	2	0.0%	303	23	92.4%	2	0	100.0%	296	98	66.9%
28		2	0	100.0%	295	67	77.3%	2	0	100.0%	295	60	79.7%
40	80	2	0	100.0%	325	47	85.5%	2	1	50.0%	321	173	46.1%
41	212	2	1	50.0%	325	125	61.5%	2	2	0.0%	322	249	22.7%
42		2	0	100.0%	336	25	92.6%	2	0	100.0%	334	58	82.6%
43	28	2	0	100.0%	335	45	86.6%	2	1	50.0%	334	77	76.9%
48		2	0	100.0%	334	62	81.4%	2	0	100.0%	333	51	84.7%
49		2	0	100.0%	334	84	74.9%	2	0	100.0%	334	70	79.0%
50	140	1	0	100.0%	136	34	75.0%	1	1	0.0%	134	84	37.3%
52		2	0	100.0%	333	47	85.9%	2	0	100.0%	332	77	76.8%
53		2	0	100.0%	333	40	88.0%	2	0	100.0%	332	106	68.1%
55		2	0	100.0%	213	9	95.8%	2	0	100.0%	210	46	78.1%
56		2	0	100.0%	214	25	88.3%	2	1	50.0%	210	41	80.5%
58	44	2	0	100.0%	309	17	94.5%	2	2	0.0%	307	99	67.8%
59	148	2	1	50.0%	308	52	83.1%	2	2	0.0%	303	83	72.6%
63	62	2	1	50.0%	337	145	57.0%	2	2	0.0%	331	199	39.9%
64		2	0	100.0%	335	71	78.8%	2	1	50.0%	334	134	59.9%
66		2	0	100.0%	334	64	80.8%	2	1	50.0%	329	61	81.5%
67		2	0	100.0%	232	14	94.0%	2	0	100.0%	231	40	82.7%
68	24	2	0	100.0%	337	67	80.1%	2	2	0.0%	336	136	59.5%
69		2	1	50.0%	324	80	75.3%	2	0	100.0%	319	56	82.4%
71		2	0	100.0%	332	3	99.1%	2	0	100.0%	330	86	73.9%
72		2	0	100.0%	328	36	89.0%	2	0	100.0%	326	69	78.8%
75		2	1	50.0%	325	18	94.5%	2	1	50.0%	319	152	52.4%
76		2	0	100.0%	325	31	90.5%	2	0	100.0%	315	130	58.7%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		2	0	100.0%	327	21	93.6%	2	0	100.0%	324	133	59.0%
78		2	0	100.0%	331	29	91.2%	2	0	100.0%	328	75	77.1%
79	36	2	0	100.0%	334	59	82.3%	2	2	0.0%	332	114	65.7%
80		2	0	100.0%	334	37	88.9%	2	0	100.0%	331	71	78.5%
84	16	2	0	100.0%	204	19	90.7%	2	1	50.0%	200	49	75.5%
85		2	0	100.0%	215	18	91.6%	2	1	50.0%	215	75	65.1%
86		2	0	100.0%	215	16	92.6%	2	0	100.0%	214	121	43.5%
89	70	2	0	100.0%	332	78	76.5%	2	2	0.0%	330	99	70.0%
90		2	0	100.0%	332	12	96.4%	2	0	100.0%	331	60	81.9%
93	103	2	0	100.0%	214	21	90.2%	2	1	50.0%	213	56	73.7%
94		2	0	100.0%	245	61	75.1%	2	0	100.0%	243	89	63.4%
95		2	0	100.0%	214	6	97.2%	2	1	50.0%	214	83	61.2%
97	468	2	2	0.0%	334	219	34.4%	2	1	50.0%	332	121	63.6%
98		2	1	50.0%	334	29	91.3%	2	1	50.0%	332	124	62.7%
110		2	0	100.0%	211	110	47.9%	2	0	100.0%	208	22	89.4%
111		2	0	100.0%	205	37	82.0%	2	0	100.0%	203	22	89.2%
112		2	1	50.0%	205	21	89.8%	2	0	100.0%	204	20	90.2%
113		2	0	100.0%	136	33	75.7%	2	0	100.0%	135	16	88.1%
119		2	0	100.0%	202	49	75.7%	2	0	100.0%	200	26	87.0%
125		2	0	100.0%	215	12	94.4%	2	0	100.0%	215	84	60.9%
129		2	1	50.0%	214	51	76.2%	2	1	50.0%	214	31	85.5%
130		2	0	100.0%	205	20	90.2%	2	0	100.0%	203	16	92.1%
131		2	0	100.0%	207	57	72.5%	2	0	100.0%	207	39	81.2%
134		2	0	100.0%	215	32	85.1%	2	0	100.0%	214	42	80.4%
136	29	2	1	50.0%	215	28	87.0%	2	2	0.0%	213	30	85.9%
137		2	0	100.0%	212	36	83.0%	2	1	50.0%	212	63	70.3%
138		2	1	50.0%	215	44	79.5%	2	0	100.0%	214	38	82.2%
141		2	1	50.0%	214	5	97.7%	2	1	50.0%	213	38	82.2%
148		2	0	100.0%	214	22	89.7%	2	0	100.0%	212	41	80.7%
151		2	0	100.0%	333	105	68.5%	2	0	100.0%	332	99	70.2%
170		2	0	100.0%	210	12	94.3%	2	0	100.0%	209	30	85.6%
171		2	0	100.0%	215	11	94.9%	2	1	50.0%	215	89	58.6%
172	75	2	0	100.0%	214	19	91.1%	2	1	50.0%	212	70	67.0%
173		2	0	100.0%	207	25	87.9%	2	0	100.0%	206	84	59.2%
174		2	0	100.0%	215	23	89.3%	2	0	100.0%	215	52	75.8%
175	57	2	0	100.0%	215	23	89.3%	2	1	50.0%	215	71	67.0%
176		2	0	100.0%	207	17	91.8%	2	0	100.0%	204	26	87.3%
177		2	0	100.0%	215	28	87.0%	2	0	100.0%	215	48	77.7%
178		2	0	100.0%	215	28	87.0%	2	0	100.0%	213	36	83.1%
179		2	0	100.0%	215	25	88.4%	2	1	50.0%	214	77	64.0%
181		2	1	50.0%	211	65	69.2%	2	0	100.0%	208	17	91.8%
182	73	2	0	100.0%	205	31	84.9%	2	1	50.0%	203	24	88.2%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		2	1	50.0%	214	63	70.6%	2	0	100.0%	211	44	79.1%
184		2	0	100.0%	215	36	83.3%	2	0	100.0%	214	28	86.9%
185		2	0	100.0%	215	41	80.9%	2	0	100.0%	215	18	91.6%
186	29	2	1	50.0%	214	30	86.0%	2	1	50.0%	213	62	70.9%
190		2	1	50.0%	214	76	64.5%	2	0	100.0%	213	44	79.3%
192		2	0	100.0%	212	24	88.7%	2	0	100.0%	212	19	91.0%
193		2	2	0.0%	210	85	59.5%	2	1	50.0%	209	91	56.5%
196		2	0	100.0%	211	23	89.1%	2	0	100.0%	209	17	91.9%
197	40	2	1	50.0%	215	78	63.7%	2	2	0.0%	215	73	66.0%
198	35	2	1	50.0%	147	18	87.8%	2	1	50.0%	146	23	84.2%
230		2	0	100.0%	170	4	97.6%	2	0	100.0%	170	9	94.7%
232	26	2	0	100.0%	336	12	96.4%	2	1	50.0%	336	24	92.9%
233		2	1	50.0%	297	67	77.4%	2	0	100.0%	296	101	65.9%
234		2	0	100.0%	337	23	93.2%	2	0	100.0%	336	29	91.4%
235		2	0	100.0%	261	42	83.9%	2	0	100.0%	260	60	76.9%
236		2	0	100.0%	321	10	96.9%	2	0	100.0%	320	43	86.6%
237	44	2	1	50.0%	334	62	81.4%	2	1	50.0%	332	60	81.9%
238		2	0	100.0%	261	23	91.2%	2	0	100.0%	259	22	91.5%
239		2	1	50.0%	335	84	74.9%	2	0	100.0%	334	42	87.4%
240		2	0	100.0%	336	23	93.2%	2	0	100.0%	333	69	79.3%
241	24	2	2	0.0%	336	84	75.0%	2	2	0.0%	336	83	75.3%
243		2	1	50.0%	272	72	73.5%	2	0	100.0%	271	39	85.6%
244		2	1	50.0%	296	13	95.6%	2	1	50.0%	296	66	77.7%
245		2	0	100.0%	217	41	81.1%	2	0	100.0%	216	30	86.1%
280	28	2	0	100.0%	337	17	95.0%	2	1	50.0%	336	79	76.5%
281		2	0	100.0%	337	40	88.1%	2	0	100.0%	337	60	82.2%
283	36	2	0	100.0%	337	85	74.8%	2	2	0.0%	337	68	79.8%
284	60	2	1	50.0%	337	14	95.8%	2	1	50.0%	334	62	81.4%
290		2	1	50.0%	337	53	84.3%	2	0	100.0%	334	137	59.0%
291		2	0	100.0%	336	112	66.7%	2	0	100.0%	332	90	72.9%
300		2	0	100.0%	320	22	93.1%	2	0	100.0%	317	73	77.0%
301	53	2	0	100.0%	334	10	97.0%	2	2	0.0%	330	65	80.3%
302	37	2	1	50.0%	315	35	88.9%	2	2	0.0%	311	92	70.4%
305	50	2	1	50.0%	318	32	89.9%	2	2	0.0%	313	124	60.4%
306	57	2	0	100.0%	332	17	94.9%	2	2	0.0%	330	91	72.4%
307	32	2	0	100.0%	325	44	86.5%	2	2	0.0%	321	100	68.8%
311	57	2	1	50.0%	329	29	91.2%	2	2	0.0%	323	86	73.4%
316	57	2	0	100.0%	325	24	92.6%	2	2	0.0%	319	103	67.7%
318	134	2	1	50.0%	335	36	89.3%	2	2	0.0%	332	168	49.4%
319	281	2	0	100.0%	336	20	94.0%	2	2	0.0%	331	195	41.1%
329		2	0	100.0%	238	12	95.0%	2	0	100.0%	238	19	92.0%
330		2	0	100.0%	286	6	97.9%	2	0	100.0%	286	15	94.8%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		2	0	100.0%	337	33	90.2%	2	0	100.0%	336	44	86.9%
332	13	2	0	100.0%	336	19	94.3%	2	1	50.0%	336	47	86.0%
334		2	0	100.0%	337	11	96.7%	2	0	100.0%	335	43	87.2%
335		2	0	100.0%	337	35	89.6%	2	0	100.0%	334	55	83.5%
336		2	0	100.0%	336	10	97.0%	2	0	100.0%	334	29	91.3%
337		2	0	100.0%	337	21	93.8%	2	0	100.0%	333	47	85.9%
338		2	0	100.0%	337	54	84.0%	2	0	100.0%	334	104	68.9%
339		2	0	100.0%	337	54	84.0%	2	0	100.0%	337	58	82.8%
341		2	0	100.0%	322	51	84.2%	2	0	100.0%	316	53	83.2%
342	20	2	0	100.0%	337	26	92.3%	2	2	0.0%	335	63	81.2%
350	26	2	0	100.0%	312	20	93.6%	2	2	0.0%	304	176	42.1%
351	35	2	0	100.0%	319	29	90.9%	2	2	0.0%	317	94	70.3%
352	54	2	0	100.0%	303	24	92.1%	2	2	0.0%	297	95	68.0%
353	18	2	0	100.0%	274	14	94.9%	2	1	50.0%	268	50	81.3%
354	29	2	0	100.0%	318	37	88.4%	2	1	50.0%	310	117	62.3%
355		2	0	100.0%	325	37	88.6%	2	0	100.0%	316	119	62.3%
364	42	2	0	100.0%	326	73	77.6%	2	1	50.0%	320	121	62.2%
365		2	0	100.0%	325	13	96.0%	2	0	100.0%	322	124	61.5%
370		2	0	100.0%	323	39	87.9%	2	0	100.0%	310	75	75.8%
371	21	2	0	100.0%	316	11	96.5%	2	1	50.0%	312	31	90.1%
380		2	0	100.0%	318	30	90.6%	2	0	100.0%	317	72	77.3%
381		2	0	100.0%	333	15	95.5%	2	0	100.0%	330	71	78.5%
382	18	2	1	50.0%	332	31	90.7%	2	2	0.0%	330	118	64.2%
383		2	1	50.0%	323	28	91.3%	1	0	100.0%	319	138	56.7%
390		2	0	100.0%	318	24	92.5%	2	1	50.0%	316	87	72.5%
391	25	2	0	100.0%	319	14	95.6%	2	2	0.0%	314	90	71.3%
392	Cncld	2	1	50.0%	332	12	96.4%	1	1	0.0%	326	104	68.1%
393	Cncld	2	1	50.0%	336	20	94.0%	1	1	0.0%	331	105	68.3%
417		2	0	100.0%	223	47	78.9%	2	0	100.0%	214	25	88.3%
425		1	0	100.0%	225	7	96.9%	1	0	100.0%	224	7	96.9%
448		2	2	0.0%	261	51	80.5%	2	0	100.0%	257	89	65.4%
449		2	0	100.0%	258	34	86.8%	2	0	100.0%	258	45	82.6%
470		2	0	100.0%	238	40	83.2%	2	1	50.0%	232	28	87.9%
471		2	0	100.0%	227	14	93.8%	2	0	100.0%	227	6	97.4%
473		2	0	100.0%	234	15	93.6%	2	0	100.0%	231	10	95.7%
474		2	0	100.0%	230	66	71.3%	2	0	100.0%	215	71	67.0%
475		1	0	100.0%	230	8	96.5%	1	0	100.0%	230	16	93.0%
478		2	1	50.0%	226	37	83.6%	2	1	50.0%	224	29	87.1%
479		2	0	100.0%	233	36	84.5%	2	0	100.0%	231	36	84.4%
486		2	0	100.0%	237	35	85.2%	2	0	100.0%	231	61	73.6%
494		2	1	50.0%	240	48	80.0%	2	1	50.0%	232	65	72.0%
495		2	0	100.0%	221	4	98.2%	2	0	100.0%	219	3	98.6%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
500	76	2	1	50.0%	311	17	94.5%	2	1	50.0%	308	37	88.0%
502		2	0	100.0%	319	19	94.0%	2	1	50.0%	315	62	80.3%
503		2	1	50.0%	333	41	87.7%	2	0	100.0%	326	102	68.7%
504		2	0	100.0%	337	20	94.1%	2	0	100.0%	335	99	70.4%
505	101	2	0	100.0%	329	43	86.9%	2	2	0.0%	324	93	71.3%
506	Cncld	2	1	50.0%	332	57	82.8%	1	1	0.0%	323	52	83.9%
507	51	2	0	100.0%	337	49	85.5%	2	1	50.0%	337	116	65.6%
508	52	2	0	100.0%	332	43	87.0%	2	1	50.0%	328	82	75.0%
509		2	1	50.0%	318	16	95.0%	2	1	50.0%	318	72	77.4%
511		2	1	50.0%	313	26	91.7%	2	0	100.0%	312	53	83.0%
516		2	0	100.0%	328	35	89.3%	2	1	50.0%	327	147	55.0%
517		2	0	100.0%	337	8	97.6%	2	0	100.0%	333	150	55.0%
518	No OS	2	2	0.0%	337	48	85.8%	2	2	0.0%	335	234	30.1%
519		2	1	50.0%	328	10	97.0%	2	1	50.0%	326	73	77.6%
520		2	1	50.0%	196	30	84.7%	2	0	100.0%	191	11	94.2%
521		2	0	100.0%	234	7	97.0%	2	0	100.0%	233	31	86.7%
522		2	1	50.0%	234	44	81.2%	2	0	100.0%	231	24	89.6%
523		2	0	100.0%	234	9	96.2%	2	0	100.0%	233	26	88.8%
524		2	1	50.0%	233	18	92.3%	2	0	100.0%	230	27	88.3%
525	Cncld	2	1	50.0%	231	17	92.6%	1	0	100.0%	226	15	93.4%
526	Cncld	2	1	50.0%	208	42	79.8%	1	0	100.0%	204	18	91.2%
527		2	0	100.0%	234	10	95.7%	2	0	100.0%	232	40	82.8%
528		2	0	100.0%	234	19	91.9%	2	1	50.0%	233	33	85.8%
529		2	0	100.0%	234	13	94.4%	2	0	100.0%	233	65	72.1%
530		2	1	50.0%	188	19	89.9%	2	0	100.0%	188	38	79.8%
531		2	1	50.0%	208	15	92.8%	2	0	100.0%	208	13	93.8%
532	38	2	2	0.0%	234	59	74.8%	2	1	50.0%	232	36	84.5%
534		2	1	50.0%	193	29	85.0%	2	0	100.0%	190	17	91.1%
535		2	1	50.0%	220	27	87.7%	2	0	100.0%	215	28	87.0%
536	45	2	1	50.0%	234	65	72.2%	2	1	50.0%	230	42	81.7%
537		2	1	50.0%	203	25	87.7%	2	0	100.0%	197	25	87.3%
538		2	0	100.0%	234	26	88.9%	2	0	100.0%	233	46	80.3%
539	12	2	0	100.0%	188	28	85.1%	2	1	50.0%	188	83	55.9%
540		2	1	50.0%	233	45	80.7%	2	0	100.0%	223	21	90.6%
541		2	1	50.0%	233	26	88.8%	2	1	50.0%	226	42	81.4%
542		2	0	100.0%	233	25	89.3%	2	1	50.0%	230	42	81.7%
543	25	2	0	100.0%	234	28	88.0%	2	1	50.0%	234	74	68.4%
544		2	0	100.0%	232	22	90.5%	2	0	100.0%	228	22	90.4%
545		2	1	50.0%	234	21	91.0%	2	0	100.0%	231	29	87.4%
547		2	0	100.0%	234	47	79.9%	2	0	100.0%	234	54	76.9%
548		1	0	100.0%	225	22	90.2%	1	0	100.0%	222	17	92.3%
549		2	0	100.0%	229	27	88.2%	2	0	100.0%	219	20	90.9%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
550	12	2	2	0.0%	188	22	88.3%	2	1	50.0%	188	45	76.1%
551		2	0	100.0%	230	23	90.0%	2	0	100.0%	220	23	89.5%
552		1	1	0.0%	5	3	40.0%	1	0	100.0%	5	2	60.0%
562		2	0	100.0%	328	27	91.8%	2	0	100.0%	323	37	88.5%
564		2	0	100.0%	329	19	94.2%	2	1	50.0%	321	44	86.3%
566		2	0	100.0%	327	29	91.1%	2	0	100.0%	324	54	83.3%
567		2	0	100.0%	214	11	94.9%	2	0	100.0%	212	14	93.4%
572		2	0	100.0%	324	27	91.7%	2	0	100.0%	316	95	69.9%
573		2	0	100.0%	326	44	86.5%	2	0	100.0%	318	58	81.8%
579	44	2	0	100.0%	214	14	93.5%	2	1	50.0%	207	46	77.8%
580		2	1	50.0%	329	19	94.2%	2	1	50.0%	322	38	88.2%
581	23	2	0	100.0%	329	58	82.4%	2	2	0.0%	326	77	76.4%
584	38	2	0	100.0%	213	32	85.0%	2	2	0.0%	206	134	35.0%
587		2	0	100.0%	321	21	93.5%	2	0	100.0%	312	65	79.2%
588		2	0	100.0%	212	23	89.2%	2	0	100.0%	210	43	79.5%
591		2	1	50.0%	326	27	91.7%	2	1	50.0%	319	50	84.3%
593		2	1	50.0%	319	54	83.1%	2	1	50.0%	296	42	85.8%
595		2	2	0.0%	322	62	80.7%	2	0	100.0%	319	73	77.1%
600	24	2	0	100.0%	242	9	96.3%	2	1	50.0%	240	23	90.4%
601	158	2	1	50.0%	225	91	59.6%	2	1	50.0%	222	28	87.4%
605	Cncld	2	2	0.0%	232	141	39.2%	1	0	100.0%	227	23	89.9%
607	76	2	1	50.0%	241	31	87.1%	2	1	50.0%	238	26	89.1%
609		2	0	100.0%	232	23	90.1%	2	0	100.0%	231	23	90.0%
622		2	0	100.0%	139	35	74.8%	2	1	50.0%	136	6	95.6%
626		2	0	100.0%	146	20	86.3%	2	0	100.0%	144	18	87.5%
639		2	0	100.0%	212	40	81.1%	2	0	100.0%	210	20	90.5%
640	81	2	1	50.0%	232	8	96.6%	2	1	50.0%	230	85	63.0%
641	22	2	0	100.0%	214	43	79.9%	2	2	0.0%	214	29	86.4%
642		2	1	50.0%	230	12	94.8%	2	0	100.0%	229	27	88.2%
643	40	2	1	50.0%	244	45	81.6%	2	1	50.0%	241	40	83.4%
644	32	2	0	100.0%	236	28	88.1%	2	1	50.0%	234	57	75.6%
645		2	0	100.0%	244	42	82.8%	2	0	100.0%	241	55	77.2%
646	117	2	2	0.0%	233	58	75.1%	2	1	50.0%	231	114	50.6%
647	25	2	2	0.0%	244	37	84.8%	2	1	50.0%	242	52	78.5%
648	69	2	1	50.0%	240	60	75.0%	2	1	50.0%	240	36	85.0%
649		2	1	50.0%	245	45	81.6%	2	0	100.0%	241	34	85.9%
650	27	2	0	100.0%	244	45	81.6%	2	1	50.0%	241	40	83.4%
651		2	0	100.0%	244	17	93.0%	2	0	100.0%	241	43	82.2%
652	11	2	0	100.0%	245	31	87.3%	2	1	50.0%	241	42	82.6%
653		2	1	50.0%	233	37	84.1%	2	1	50.0%	229	42	81.7%
654		2	0	100.0%	234	44	81.2%	2	0	100.0%	230	20	91.3%
655		2	2	0.0%	242	76	68.6%	2	1	50.0%	239	77	67.8%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
656		2	1	50.0%	244	55	77.5%	2	0	100.0%	242	33	86.4%
657		2	0	100.0%	233	29	87.6%	2	1	50.0%	231	31	86.6%
658		2	0	100.0%	244	37	84.8%	2	0	100.0%	242	35	85.5%
680		2	0	100.0%	239	12	95.0%	2	0	100.0%	237	27	88.6%
681		2	0	100.0%	239	18	92.5%	2	0	100.0%	232	93	59.9%
682		2	0	100.0%	238	9	96.2%	2	0	100.0%	238	42	82.4%
683		2	0	100.0%	221	18	91.9%	2	0	100.0%	220	75	65.9%
684		2	0	100.0%	220	37	83.2%	2	0	100.0%	220	47	78.6%
685		2	0	100.0%	235	33	86.0%	2	0	100.0%	232	55	76.3%
686		2	0	100.0%	240	39	83.8%	2	0	100.0%	239	52	78.2%
687		2	0	100.0%	239	38	84.1%	2	0	100.0%	238	40	83.2%
688		2	0	100.0%	238	15	93.7%	2	0	100.0%	237	41	82.7%
701	129	2	0	100.0%	269	30	88.8%	2	1	50.0%	266	33	87.6%
702	63	2	1	50.0%	336	37	89.0%	2	2	0.0%	333	85	74.5%
703	No OS	2	2	0.0%	337	114	66.2%	2	2	0.0%	335	102	69.6%
704	16	2	0	100.0%	268	49	81.7%	2	2	0.0%	260	61	76.5%
710	Cncld	2	1	50.0%	337	80	76.3%	1	1	0.0%	332	89	73.2%
711		2	1	50.0%	328	39	88.1%	2	1	50.0%	305	66	78.4%
712	100	2	1	50.0%	334	92	72.5%	2	1	50.0%	324	115	64.5%
713	Cncld	2	1	50.0%	204	21	89.7%	1	1	0.0%	178	81	54.5%
714	53	2	2	0.0%	218	94	56.9%	2	2	0.0%	202	97	52.0%
715	Cncld	2	0	100.0%	336	63	81.3%	1	1	0.0%	306	156	49.0%
716	42	2	2	0.0%	337	145	57.0%	2	2	0.0%	328	143	56.4%
717	133	2	2	0.0%	322	81	74.8%	2	2	0.0%	297	100	66.3%
718	127	2	2	0.0%	337	180	46.6%	2	2	0.0%	334	131	60.8%
719	No OS	2	1	50.0%	337	114	66.2%	2	1	50.0%	320	99	69.1%
757		2	0	100.0%	122	7	94.3%	2	1	50.0%	121	15	87.6%
761		2	0	100.0%	333	13	96.1%	2	0	100.0%	330	44	86.7%
765		2	0	100.0%	333	25	92.5%	2	1	50.0%	333	47	85.9%
769		2	0	100.0%	333	27	91.9%	2	1	50.0%	326	66	79.8%
770		2	0	100.0%	333	25	92.5%	2	0	100.0%	330	104	68.5%
774		2	0	100.0%	333	17	94.9%	2	0	100.0%	331	80	75.8%
777	22	2	0	100.0%	218	13	94.0%	2	2	0.0%	217	60	72.4%
782		2	0	100.0%	218	105	51.8%	2	1	50.0%	213	37	82.6%
785		2	0	100.0%	333	29	91.3%	2	0	100.0%	333	61	81.7%
786		2	0	100.0%	122	23	81.1%	2	0	100.0%	118	66	44.1%
790		2	0	100.0%	333	31	90.7%	2	0	100.0%	330	54	83.6%
794		2	0	100.0%	333	40	88.0%	2	0	100.0%	329	76	76.9%
822	29	2	1	50.0%	333	19	94.3%	1	1	0.0%	330	171	48.2%
1333	21	2	0	100.0%	333	40	88.0%	2	1	50.0%	330	113	65.8%
1340		2	0	100.0%	332	7	97.9%	2	0	100.0%	331	56	83.1%
1689		1	0	100.0%	112	6	94.6%	2	0	100.0%	112	14	87.5%

Amtrak On Time Performance

Trains Arriving Through: 9/2/2026

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2102		2	0	100.0%	91	16	82.4%	2	0	100.0%	90	7	92.2%
2103		2	0	100.0%	155	14	91.0%	2	0	100.0%	154	10	93.5%
2104		2	0	100.0%	181	10	94.5%	2	0	100.0%	179	13	92.7%
2105		2	0	100.0%	3	1	66.7%	2	0	100.0%	3	0	100.0%
2108		2	0	100.0%	212	28	86.8%	2	0	100.0%	206	27	86.9%
2109		2	0	100.0%	105	13	87.6%	2	0	100.0%	103	6	94.2%
2112		2	0	100.0%	52	6	88.5%	2	0	100.0%	50	2	96.0%
2113		2	0	100.0%	91	9	90.1%	2	0	100.0%	91	10	89.0%
2115		2	0	100.0%	91	13	85.7%	2	0	100.0%	90	12	86.7%
2116		2	0	100.0%	52	1	98.1%	2	0	100.0%	52	8	84.6%
2118		2	0	100.0%	52	4	92.3%	2	0	100.0%	52	12	76.9%
2119		2	0	100.0%	52	8	84.6%	2	0	100.0%	51	12	76.5%
2120		2	0	100.0%	52	19	63.5%	2	0	100.0%	50	23	54.0%
2123		2	1	50.0%	90	11	87.8%	2	0	100.0%	89	15	83.1%
2124		2	0	100.0%	183	38	79.2%	2	0	100.0%	181	24	86.7%
2126		2	0	100.0%	100	26	74.0%	2	0	100.0%	99	22	77.8%
2127		2	0	100.0%	52	10	80.8%	2	0	100.0%	51	9	82.4%
2128		2	0	100.0%	52	4	92.3%	2	0	100.0%	52	3	94.2%
2131		2	0	100.0%	52	10	80.8%	2	0	100.0%	52	6	88.5%
2150		2	0	100.0%	205	22	89.3%	2	0	100.0%	202	75	62.9%
2151		2	0	100.0%	154	7	95.5%	2	1	50.0%	152	42	72.4%
2152		2	0	100.0%	110	7	93.6%	2	0	100.0%	109	31	71.6%
2154		2	1	50.0%	113	24	78.8%	1	0	100.0%	108	45	58.3%
2155		2	0	100.0%	214	17	92.1%	2	1	50.0%	210	103	51.0%
2156		2	0	100.0%	3	0	100.0%	2	0	100.0%	3	0	100.0%
2158		2	0	100.0%	51	6	88.2%	2	0	100.0%	51	16	68.6%
2159		2	0	100.0%	207	16	92.3%	2	0	100.0%	205	69	66.3%
2160		2	0	100.0%	52	2	96.2%	2	0	100.0%	51	28	45.1%
2162		2	0	100.0%	213	23	89.2%	2	0	100.0%	207	91	56.0%
2163		2	0	100.0%	165	17	89.7%	2	0	100.0%	159	69	56.6%
2165		2	0	100.0%	49	4	91.8%	2	0	100.0%	49	21	57.1%
2167		2	1	50.0%	200	21	89.5%	2	1	50.0%	200	42	79.0%
2171	39	2	0	100.0%	141	10	92.9%	2	1	50.0%	137	24	82.5%
2190		2	0	100.0%	210	29	86.2%	2	0	100.0%	208	24	88.5%
2193		1	0	100.0%	204	26	87.3%	1	0	100.0%	202	50	75.2%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2171	WAS	39	DCS	40	DCS	40	RTE-RTE	AM	Power switch failure, Control Point, JCT, 21sw at JCT out of correspondence
84	NYP	16	BSP	14	BSP	14	TRE-MET	AM	Bridge strike, Other, SUTTON PLACE
93	NFK	103	ENG	72	ENG	72	WAS-WAS	AM	HEP, 383 DX AG, LATE DSLS FROM THE PIT
136	SPG	29	OTH	22	OTH	11	WNL-SPG	AM	Lost time - N.A.R.
172	BOS	75	DCS	40	DCS	38	PVD-RTE	AM	Power switch failure, Control Point, JCT, 21sw at JCT out of correspondence
175	WAS	57	DCS	47	DCS	47	BBY-RTE	AM	Power switch failure, Control Point, JCT, 21sw at JCT out of correspondence
182	BOS	73	ENG	60	ENG	55	PVD-RTE	AM	PTC - On Board Cab Signal or PTC Failure, 669 EX ES, Cab & ACSES failure, capped at 59mph
186	PHL	29	WTR	32	BSP	19	XPV-WIL	AM	Bridge strike, Milepost, 42.51, .
197	WAS	40	CTI	22	CTP	19	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, HELD FOR SINGLE TRACKING A/C NJ3721 DISABLED AHD AT PORTAL
198	NYP	35	ENG	26	ENG	26	WAS-WAS	AM	Set out defective locomotive, 603 EX ES, CATENARY ISSUES AT SUNNY SIDE YD DELAYED ARRIVAL OF A85; Setting off Shopped ACS-64 603 after arriving in WAS.
79	CLT	36	WTR	30	DCS	17	RGH-RGH	NS	PTC system failure (wayside) CSX , unable to log in., Other, RGH
600	NYP	24	WTR	33	WTR	17	PAR-DOW	AM	Storm, Control Point, PAR TO DOW
601	HAR	158	WTR	159	WTR	57	PHL-ARD	AM	Storm, Control Point, PHL TO ARD
605	HAR	Trn Cancelled							
607	HAR	76	WTR	66	WTR	66	EXT-LNC	AM	Storm, Control Point, EXT TO LNC
640	NYP	81	WTR	83	WTR	34	LNC-LNC	AM	Trees down, Control Point, ., HELD FOR DISPOSITION A/C TREES IN OCS DOWNLINE .
641	HAR	22	WTR	24	WTR	24	DOW-PAR	AM	Storm, Control Point, DOW TO PAR
643	HAR	40	WTR	21	ITI	17	NYP-NYP	AM	Service, turn, or wye train, 642, TURNED OFF AM642
644	NYP	32	WTR	37	WTR	37	LNC-PAO	AM	Storm, Control Point, LNC TO PAO
646	NYP	117	WTR	113	WTR	72	HAR-HAR	AM	Storm, Control Point, HAR, LATE TURN OFF 601

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
647	HAR	25	SYS	30	SYS	30	NYP-NYP	AM	Other late crew, LATE CREW OFF AM646
648	NYP	69	WTR	75	WTR	64	HAR-HAR	AM	Storm, Control Point, HAR, LATE TURN OFF 607
650	NYP	27	WTR	38	WTR	26	HAR-MID	AM	Storm, Control Point, HAR TO MID, SIGNAL POWER LOSS
652	NYP	11	CTP	20	CTP	20	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION AHD DUE TO SINGLE TRACKING A/C NJ3721 DISABLED AHD AT PORTAL
63	TWO	62	DSR	33	DSR	18	XSV-ROC	CS	Per dispatcher (radio/phone) Flash flood warning, Milepost, 296.9, 313.1, 40, all
68	NYP	24	WTR	42	WTR	42	SLQ-RSP	CN	Heat order Milepost, 42.5, 0.0
232	NYP	26	RTE	18	RTE	18	ALB-HUD	AM	Inability to contact dispatcher N.A.R tried calling both on radio and phone multiple times., Control Point, 124
237	ALB	44	CTI	18	CTI	18	CRT-POU	MN	Follow Waited for them to pass going northbound then followed after A48 passed, MN, 849, Control Point, 39
241	ALB	24	CTP	18	CTP	18	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A "F-INT A/C NJ3721 DISABLED AT PORTAL
280	NYP	28	ENG	23	ENG	11	POU-CRT	MN	PTC - On Board Cab Signal or PTC Failure 701
283	NFL	36	WTR	65	WTR	65	XSV-ROC	CS	High winds - winds up to 70 MPH QC 320.0 - QC 338.0 (20MPH) - winds up to 60 MPH QC 338.0 - ROC (40 MPH), Milepost w/Letters, QC 320.0, ROC
284	NYP	60	WTR	62	WTR	31	BUF-ROC	CS	High winds Milepost, 429, 330
43	PGH	28	DSR	22	WTR	13	LNC-ELT	AM	Storm, Control Point, LNC TO ELT, SIGNAL POWER LOSS
89	SAV	70	WTR	46	FTI	23	CHS-YEM	CS	Meet 410, Milepost, 392.6, 392.6
97	MIA	468	BSP	1265	BSP	1265	NWK-TRE	AM	Bridge strike, Other, MP29, HELD AT COUNTY A/C BRIDGE STRIKE
40	CHI	80	WTR	95	POL	41	WTI-WTI	NS	Fire department hold Medical emergency
41	MIA	212	WTR	113	DBS	54	XFI-COV	CS	TR41(31) struck a tree at MP 304.9 and severed HEP cable on the Fireman side rear of trail E319 and left side B end of C/25095., Other,
6	CHI	284	DCS	144	DCS	60	DEN-DEN	RT	PTC- Unplanned PTC system /server outage Other, DEN

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
525	OKJ	Trn Cancelled							
526	SAC	Trn Cancelled							
532	SAC	38	TEN	37	TEN	37	OKJ-OKJ	UP	PTC- IETMS recycle breaker to clear fault JPBX920
536	SAC	45	TEN	50	TEN	50	EMY-EMY	UP	PTC - On Board Cab Signal or PTC Failure JPBX921
539	SJC	12	PTI	7	RTE	7	SUI-MTZ	UP	Single track at Marsh due to bridge maintenance Meet AMT 530, Control Point, Marsh
543	SJC	25	PTI	23	PTI	12	GAC-SCC	UP	Meet ACE A8, Siding, Expressway
550	SAC	12	DSR	16	DSR	5	MTZ-SUI	UP	Per bulletin Milepost, 43.50, 44.0, 15, MT 2
50	NYP	140	DSR	62	WTR	24	XJD-STA	BB	Heat order Milepost, 276.0, 220.9
500	SEA	76	SYS	57	SYS	53	PDX-PDX	BN	PTC problem or failure (cause unknown) PTC wouldn't engage. Cycled PTC breaker twice. Had GPS issues
505	PDX	101	CCR	76	CCR	76	VAN-PDX	BN	Air / Brake / Wheel 7911, Brake pipe came apart under cab just before angle cock.
506	SEA	Trn Cancelled	CCR	34	CCR	12	KEL-CTL	BN	Air / Brake / Wheel 7911, Cab car cut out. Restricted to freight speed
507	EUG	51	WTR	52	WTR	52	ORC-SLM	UP	Trees down Milepost, 748.25, 748.25
508	SEA	52	WTR	63	WTR	60	SLM-ORC	UP	Trees down Milepost, 748.25, 748.25
518	VAC	No OS Rpt	ITI	169	ITI	169	PDX-PDX	BN	Service, turn, or wye train 505, Amtrak 505 had a brake pipe break in route to PDX. Unable to fix at PDX. Changed equipment to 517's and needed a daily done on the set and fueling
58	CHI	44	DSR	59	DCS	30	XSU-HMD	CC	Power switch failure East bridge crossover switch, Other, CDL 903 switch
59	NOL	148	ENG	114	ENG	114	CHI-CHI	AM	HEP Replaced hep motherboard, 29
822	OKC	29	DSR	22	DSR	16	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, 1, Milepost, 350.7, 351.1, 50, 1, Milepost, 355.5, 355.9, 50, 1, Milepost, 382.5, 382.7, 40, M, Milepost, 383.4, 384, 25, M, Milepost, 385.3, 385.5, 30, M, Milepost, 387.6, 388.2, 15, M, Milepost, 389, 389.7, 25, M, Milepost, 396.2, 396.3, 30, M
332	CHI	13	CTI	12	CTI	10	GLN-XWA	ME	Follow Metra, 2228, Milepost, 5, 3

Amtrak Endpoint OTP Details

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
342	CHI	20	SYS	11	SYS	7	XRO-GLN	ME	Copy authority / restriction
350	PNT	26	PTI	31	MBO	20	HMI-XPI	NS	For maritime traffic Control Point, 503
351	CHI	35	OTH	32	OTH	32	ARB-JXN	MI	Track work CP 52
352	PNT	54	DCS	31	DCS	31	XH6-XPI	AM	T.O.L Other, 238
353	CHI	18	DCS	23	DCS	21	ARB-JXN	MI	Signal suspension Signal at 49 was clear then dropped to approach then back to clear. We stopped informed train director. He told us to proceed to cp 52 then talked us by the stop indication at 52, Control Point, 52
354	PNT	29	DCS	24	DCS	24	NBU-NLS	AM	Restrictive signal(s) from known wayside signal failure Stop, Other, 213 & 211
364	PTH	42	ENG	60	ENG	60	CHI-XTF	AM	AC not working on lead engine IDTX4630 ID4630
371	CHI	21	FTI	36	FTI	23	XH6-XTF	NS	Follow NS, Milepost, 507, 511
579	LAX	44	DCS	37	DCS	24	FUL-XRJ	BN	Restrictive signal(s) from known wayside signal failure Line switches 1A and 1B. 1A had binding issues, Stop, Control Point, Hobart
581	LAX	23	PTI	16	PTI	11	OLT-SOL	SN	Meet 774, Control Point, Torrey
584	SAN	38	CTI	23	DCS	18	XRJ-FUL	BN	Restrictive signal(s) from unknown cause Stop, Control Point, W. Hobart
777	SLO	22	DCS	23	CAR	17	GDL-GDL	SC	Loudspeaker noise coming from Engine. Called Mechanical to help resolve the issue. C2122
701	SAC	129	SYS	129	SYS	126	TRK-MOD	BN	Blocked by or assisting another, disabled Amtrak train AMT 710 with CDTX 2013 (LOCO FAILURE)., Other, MOD DEPOT
702	BFD	63	FTI	53	FTI	24	WAC-BFD	BN	Meet BNSF 6577, Control Point, CP GOMEZ
703	SAC	No OS Rpt	ITI	110	ITI	110	BFD-BFD	BN	Service, turn, or wye train 714, Late turn of AMT 714. 703 took 714s equipment instead of usual 712s equipment. Waiting for 714s late arrival.
704	BFD	16	DCS	34	DCS	25	SKT-SKT	UP	Power switch failure Switch at Market would not line from track 1 to track 2. Shove back to el pinal to get onto track 2/ then proceeded onward., Control Point, market
710	BFD	Trn Cancelled	PTI	6	PTI	6	ACA-SKN	BN	Meet AMTK 711, Control Point, Bixler
712	BFD	100	FTI	69	FTI	30	MOD-TRK	BN	Meet BNSF6243, Control Point, E EMPIRE

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
713	OKJ	Trn Cancelled	PTI	49	TSV	35	HNF-FNO	BN	Fuel REFUEL AT CALWA YARD. BNSF ADDED 500 gals
714	BFD	53	FTI	37	FTI	18	MOD-TRK	BN	Meet BNSF, Control Point, East Empire, z train
715	OKJ	Trn Cancelled	SYS	58	SYS	39	TRK-MOD	BN	Blocked by or assisting another, disabled Amtrak train Rescued AMTRAK 710, Milepost, 1087, 1090.8
716	BFD	42	FTI	46	FTI	20	SKN-MOD	BN	Follow Had a restricting at 1103 and shortly after came to a stop, bnsf, Milepost, 1103, 1101.1
717	OKJ	133	FTI	88	FTI	60	COC-COC	BN	Disabled freight train Guernsey 4248, Other, Guernsey
718	BFD	127	DCS	122	DCS	15	WAC-BFD	BN	PTC system failure Other, BNSF
719	OKJ	No OS Rpt	ITI	164	ITI	164	BFD-BFD	BN	Service, turn, or wye train 712, Train 710 cancelled. 712 turns for 719 waiting on 712 equipment.
4	CHI	186	FTI	156	SYS	109	KCY-KCY	KC	Crew rest
21	SAS	103	WTR	137	DCS	40	Lrk-MVN	UP	CTC system failure CPA 371 red, flag to cpa 374 and hand op switch at cpa374, then flag to mp 375 clear sig, Control Point, cpa 471
22	CHI	224	WTR	175	SYS	64	MHL-MHL	UP	Crew rest RELIEVING CREW GIVEN A SIGN UP TIME OF 2108 HRS.
301	STL	53	WTR	65	WTR	33	SPI-ALN	UP	Heat order 50mph, Milepost, 173, 281.45
302	CHI	37	WTR	62	WTR	23	DWT-JOL	UP	Heat order Other, DWT-JOL
305	STL	50	WTR	69	WTR	23	PON-BNL	UP	Heat order Milepost, 36.88, 126.4
306	CHI	57	WTR	61	WTR	18	CRV-SPI	UP	Heat order Milepost, 223, 185
307	STL	32	FTI	24	WTR	20	JOL-DWT	UP	Heat order Milepost, 36, 73
382	CHI	18	FTI	23	FTI	12	PLO-NPV	BN	Meet Going towards aurora sub, bnsf, Control Point, aurora
391	CDL	25	WTR	33	SYS	9	GLM-RTL	CC	PTC problem or failure (cause unknown)
392	CHI	Trn Cancelled							
393	CDL	Trn Cancelled							
311	KCY	57	WTR	44	WTR	12	HEM-JEF	UP	Heat order Lvl 2, Other, Jeff city sub
316	STL	57	WTR	36	WTR	17	SED-JEF	UP	Heat order Other, Sedalia Sub

Amtrak Endpoint OTP Details

26-FOI-0073100000008773"UNCLASSIFIED"9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/2/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
318	CHI	134	DSR	141	DSR	19	LCN-BNL	UP	Per bulletin Level 2 heat restriction, Milepost, 156.4, 124.1, 50, all	
319	KCY	281	FTI	155	FTI	78	PON-PON	UP	Stopped at Pon station there is a disabled freight train south of BNL. Rescue train is on the way to BNL to move the train out of the way. UP 2557 disabled freight train south of BNL, Other, X124, UP 2557	
1333	MSP	21	DSR	33	DSR	20	XH8-MSP	CP	Per bulletin Milepost w/Letters, 395.6C, 402.5C, 25, 1	

Amtrak Initial Terminal Details

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/2/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	244	09/02	12	12	Air / Brake Eab-reduced braking fault, 9705
ALB	448	09/01	29	13	Split of train and fueling engines Other, ALB
ALB	448	09/01	29	16	48 late into ALB due to weather restrictions out west 48
HAR	640	09/02	1	1	Passenger and/or baggage
HAR	642	09/02	(Trn Cxld)		Catenary Power Loss -Amtrak
HAR	646	09/02	72	72	Storm, Control Point, HAR, LATE TURN OFF 601
HAR	648	09/02	64	64	Storm, Control Point, HAR, LATE TURN OFF 607
HAR	656	09/02	1	1	Passenger and/or baggage
NFK	138	09/02	1		
NPN	186	09/02	17	17	PTC- IETMS Software Download Air brake system showing not cut in . Wouldn't allow engineer to log into PTC. mechanical had to reboot the system
NYP	63	09/02	10	10	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	97	09/02	50	50	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR INBOUND TRAIN AM98 AND ADD FOUR COACHES AND SERVICE THE EQUIPMENT
NYP	181	09/02	5	5	Held for or routed around MW work or equipment, Other, NYP-NYP, HELD TO WAIT FOR AM2190 TO CLEAR LINE 2 A.C LINE O/O/S
NYP	183	09/02	9	9	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	193	09/02	11	11	Delay due to mechanical problems on a Commuter train, HELD FOR SINGLE TRACKING A/C NJ3721 DISABLED AHD AT PORTAL
NYP	197	09/02	19	19	Delay due to mechanical problems on a Commuter train, HELD FOR SINGLE TRACKING A/C NJ3721 DISABLED AHD AT PORTAL
NYP	233	09/02	2	2	Passenger and/or baggage, BOARDING
NYP	237	09/02	10	10	Service, turn, or wye train, 290, LATE TURN OFF AM290
NYP	241	09/02	18	18	Delay due to mechanical problems on a Commuter train, CONGESTION A "F-INT A/C NJ3721 DISABLED AT PORTAL
NYP	243	09/02	8	8	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	607	09/02	19	19	Undesired emergency application, 609 EX ES, AM607 ARRIVES psny 34" LATE AND DEPARTS NYP 19" LATE ACCOUNT MECHANICAL ISSUES IN SSYD.
NYP	643	09/02	17	17	Service, turn, or wye train, 642, TURNED OFF AM642
NYP	647	09/02	30	30	Other late crew, LATE CREW OFF AM646
NYP	649	09/02	13	13	Service, turn, or wye train, 648, LATE TURN OFF AM648
NYP	653	09/02	5	5	Delay due to mechanical problems on a Commuter train, HELD FOR SINGLE TRACKING A/C NJ3721 DISABLED AHD AT PORTAL

Amtrak Initial Terminal Details

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/2/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	655	09/02	2	2	Passenger and/or baggage, TRAVEL
PHL	601	09/02	16	16	Storm, Control Point, PHL, TREES DOWN PH LINE
PHL	605	09/02	(Trn Cxld)		Downed Trees
WAS	112	09/02	7	7	Planned set out / pick out of locomotives, cars or section of train, EQUIP LATE SPOTTING IN THE STATION.
WAS	136	09/02	3	3	Passenger and/or baggage, PAX BOARDED AFTER GATE
WAS	2154	09/02	2	2	Other late crew, RADIO COMMUNICATION ISSUE BETWEEN CNDR & ENG
CDL	392	09/02	(Trn Cxld)		Police Activity
CHI	5	09/02	12	12	PTC failure (initializing / logging in)
CHI	41	09/02	28	28	Onboard HBD alarm Fault on engine, 341
CHI	305	09/02	3	3	Door ID4313, LSA forgot to close the door after the commissary brought down her items right before we departed from Chicago
CHI	393	09/02	(Trn Cxld)		Police Activity
HOS	1	09/02	6		
KCY	318	09/02	1		
STL	302	09/02	1	1	Mobility Impaired Station agents brought passengers in people mover to train at 634am
STL	311	09/02	1	1	Line manual or spring switch Switch lined against us/ for movement into track 53, Other, STL Station
BFD	703	09/02	110	110	Service, turn, or wye train 714, Late turn of AMT 714. 703 took 714s equipment instead of usual 712s equipment. Waiting for 714s late arrival.
BFD	713	09/02	4	4	Fuel ENGINE NOT FUELED IN BFD. GAUGE SHOWS 650gal.
BFD	717	09/02	24	24	Service, turn, or wye train 702
BFD	719	09/02	164	164	Service, turn, or wye train 712, Train 710 cancelled. 712 turns for 719 waiting on 712 equipment.
LAX	2	09/02	5	5	Amtrak PD on train with passenger w/Service animal in a stroller that continues to bark at people.
LAX	14	09/02	8	8	Fuel Late arrival from the yard. Using code SVS to due some issue with fueling, as instructed by the Road Foreman., Other, 8th. Street Yard
OKJ	522	09/02	2	2	Flags down @5:50 Air test/PTC Held for 521 Approach @King Air test/ waiting on PTC Late flag drop chain reaction

Amtrak Initial Terminal Details

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/2/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	526	09/02	(Trn Cxld)		Late Operation - Inbound Train Did not Run
OKJ	532	09/02	37	37	PTC- IETMS recycle breaker to clear fault JPBX920
OKJ	534	09/02	2	2	Door C6964, Door #6 not closing
OKJ	536	09/02	(Trn Cxld)		Third Party Engine Failure
OKJ	540	09/02	1	1	Meet 543, Control Point, ni007
OKJ	712	09/02	1	1	Loading problem No load at departure time.Not due to doors., C2012
OKJ	714	09/02	7	7	PTC - On Board Cab Signal or PTC Failure C8301
OKJ	716	09/02	2	2	Late departure from the yard due to multiple capitols working okj
OKJ	718	09/02	(Trn Cxld)		Third Party Engine Failure
PDX	500	09/02	53	53	PTC problem or failure (cause unknown) PTC wouldn't engage. Cycled PTC breaker twice. Had GPS issues
PDX	518	09/02	169	169	Service, turn, or wye train 505, Amtrak 505 had a brake pipe break in route to PDX. Unable to fix at PDX. Changed equipment to 517's and needed a daily done on the set and fueling
SAC	525	09/02	(Trn Cxld)		PTC Failure
SAC	702	09/02	1		
SAN	595	09/02	3	3	Service, turn, or wye train 584
SEA	511	09/02	4	4	Re-crew / job briefing Came from train 14 with an arrival of 19:50, job briefed with engineers, and left
SJC	524	09/02	10	10	PTC - On Board Cab Signal or PTC Failure C8311, No PTC on CalTrain side
SJC	550	09/02	3	3	Inability to contact dispatcher Waited for San Jose Control South to give us a signal, Other, SJC Station

Eastern Region

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	99.1	94.8	342	0
CDOT	95.0	100	95	92.4	20	0
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	93.0	93.1	88.6	358	25
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 19(02) North of Lynchburg, VA - Freight Train Interference

03SEP26: Train 19(02), operating with engines 328/122, 8 coaches, and 148 customers, was delayed 1.3 miles north of Lynchburg, VA, on BS Montview-Salisbury, subdivision, due to NS freight train 28R clearing ahead. The freight was given priority due to the crew being short on Hours of Service.

Train	Delay	Comment
19(02)	1'03"	

Engine Swaps - Washington DC

02SEP26: Due to late release of engines from the Pit in Washington, DC the following trains were delayed departing. trains 19(02), 97(02), 93(02) were all delayed. The engines were delayed due to last minute engine shops requiring new engines to be worked up.

Train	Delay	Comment
97(02)	27"	
19(02)	1'26"	
93(02)	1'12"	

Train 49(02) West of Syracuse, NY - Freight Train Interference

03SEP26: Train 49(02), operating with engines 126/124, 11 coaches and 216 customers, was delayed 22 miles west of Syracuse, NY, on CSX Rochester_QC subdivision, due to following an unknown CSX freight between milepost 313 and 335.

Train	Delay	Comment
49(02)	38"	

Train 41(01) South of Petersburg, VA - Weather

02SEP26: Train 41(01), 26-FC-00731, 00000008773 engines 102/136, 9/18/2026 coaches and 114 customers, was delayed south of Petersburg, VA, on CSX North End subdivision, was delayed operating between Petersburg and Rocky Mount due to signal issues caused by lightning striking a signal causing signal issues. This required train 41(01) to operate at a restricted speed and get permission from CSX dispatchers through the affected area.

Train	Delay	Comment
41(01)	1'51"	
53(02)	59"	

Train 283(02) Rochester, NY - Weather

02SEP26: Due to high winds in excess of 70MPH, train 283(02), operating with engines 114/705, 5 coaches, and 144 customers, was delayed west of Rochester, NY, on CSX Rochester subdivision between milepost 320 and 371.

Train	Delay	Comment
283(02)	1'05"	

Train 182(02) Providence, RI - Engine Failure

02SEP26: Train 182(02) with E/669, E/606 and 8 cars was delayed on the New Haven to Boston main Line at MP 190.5 due to having engine problems. Amtrak Road Foreman reported that the crew had to cut out Cabs and ACSES and will be capped at 59MPH.

Train	Delay	Comment
182(02)	1'00"	

Train 52(02) Sanford, FL - Engine Failure

02SEP26: Train 52(02) with E/317, E/352 and 42 cars reported that they went into PTC emergency at MP 755.4 on the CFRC Orlando subdivision. The crew inspected the equipment and nothing was found. They also reported that CFRC reported to them they had a systemwide PTC outage.

Train	Delay	Comment
52(02)	32"	

New Haven to Boston Main Line - East of Route 128, MA - Switch Failure/Signal

02SEP26: At 313P-ET, Boston Chief reported that the 21SW at MP 213.9/Junction was out of correspondence on the New Haven to Boston main line. C&S was on scene. Several trains were delayed through the area. As of 409P-ET, C&S reported that the 21SW was in the normal position at Junction and trains were back on the move.

Train	Delay	Comment
175(02)	47"	
2171(02)	40"	
172(02)	38"	

Train 97(02) New York, NY - Servicing

02SEP26: Train 97(02) with E/644 and 10 cars was delayed departing New York due to needing equipment off late inbound 98(01) that arrived at 1104A-ET 14 minutes late.

Train	Delay	Comment
-------	-------	---------

Train 284(02) North of Buffalo, NY - Weather

02SEP26: Train 284(02) with E/98 and 5 cars was delayed on the CSX Buffalo Terminal subdivision due to High Wind Warnings from MP 429 to MP 330 then again from MP 372 to MP 330.

Train	Delay	Comment
284(02)	1'02	

New York to Philadelphia Main Line - Bridge Strike

02SEP26: At 203P-ET A vehicle struck the bridge at Sutton Ave., MP 29-30, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 300P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
84(02)	14"	
2112(02)	06"	
2119(02)	06"	

Train 68(02) South of St-Lambert, QC - Weather

02SEP26: Train 68(02) with E/98 and 5 cars was delayed on the CN Rouses Point subdivision due to heat orders from MP 42.5 to MP 0.0.

Train	Delay	Comment
68(02)	42"	

New York to Philadelphia Main Line - Bridge Strike

02SEP26: At 1157A-ET A vehicle struck the bridge at Deans Lane, MP 38.6, New York to Philadelphia Main Line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 1229P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
119(02)	01"	
2108(02)	02"	
125(02)	05"	

CSX Heat Orders - Weather

02SEP26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Grand Rapids, Monon, Cumberland, Kanawha, Metropolitan, North End, Old Main Line, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Charleston, Lakeland, Nahunta, Savannah, South End and Tampa Terminal.

Train	Delay	Comment
40(02)	53"	
53(02)	28"	
79(02)	30"	
80(02)	26"	
89(02)	56"	
90(02)	1'35"	
95(02)	31"	
98(02)	14"	
125(02)	29"	
138(02)	24"	

Train 2107(02) New York, NY - Miscellaneous Amtrak Responsible

02SEP26: Train 2107(02) cancelled out of New York due to no available equipment.

Train	Delay	Comment
2107(02)	CANCELLED	

Philadelphia, PA to Harrisburg, PA - Trees Down/OCS Power Outages

02SEP26: 5:17am Wilmington CETC reported multiple locations of downed trees on the PH Line. At MP 42.1 a tree obstructed the route and at MP 98.1 a tree was reported to be on fire in the catenary. There was a report of branches in the transmission wire at MP 41.0, 42.1, 42.3, 42.5 on track 4. Signal power loss at Thorn Interlocking. Once the Foreman arrived and crews worked on clearing the route trains were able to proceed thru the area. As of 930A-ET, Track 4 from Zoo to Stiles service was restored and the hold was lifted on track 4 from Thorn to Park.

During this time, OCS/Commercial Power was lost at ZOO interlocking.

Septa service was suspended at Frazer to Thorn

Due to more impending storms coming thru the area between Harrisburg and Philadelphia. There were 4 buses secured for both Philadelphia and Harrisburg and on stand by.

WBS#: B.TR.100151.0848

Train	Delay	Comment
605(02)	CANCELLED	
642(02)	02"	ORIG PHL
601(02)	2'39"	
640(02)	1'23"	
646(02)	1'12"	LATE TURN OFF 601(02)
607(02)	1'06"	
644(02)	1'04"	
648(02)	1'04"	late turn off 607(02)
650(02)	38"	
643(02)	17"	ITD NYP
647(02)	30"	holding for crew off 646(02)
649(02)	13"	late turn off 648(02)

Train 97(01) - Fayetteville, NC - Trespasser Incident

02SEP26: 4:53AM - Train 97(01) with E/134 and E/324 and 10 cars carrying 119 passengers struck a trespasser on the CSX South End Subdivision at MP 209.3. This did not occur at a crossing and was in Cumberland County, NC. This was a confirmed fatality. The coroner was on scene around 6A-ET. There were no reports of injuries to crew or passengers. The weather at the time was 77° and clear. Amtrak Assistant Superintendent of Operations was on scene and Amtrak Road Foreman was enroute with the recrew.

Service Recovery was initiated with coach passengers received complimentary beef stew for all coach passengers and First Class passengers were served lunch in the dining car as normal.

Train	Delay	Comment
97(01)	2'48"	

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outage on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

26-FOI-00731 00000008773 UNCLASSIFIED

9/18/2026

Train	Delay	Comment
240 (29)	29"	
280 (29)	18"	
233 (29)	54"	
283 (29)	64"	
284 (29)	39"	
291 (29)	36"	
290 (29)	47"	
49 (29)	49"	
235 (29)	49"	
48 (28)	31"	
237 (29)	36"	
239 (29)	1' 10"	
69 (30)	51"	
240 (30)	35"	
1233 (30)	18"	
291 (30)	45"	LATE TURN OFF 240 (30)

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

- Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.
- Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.
- Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.
- Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.
- Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.
- Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.
- Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct), will operate on an adjusted schedule.
- Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.
- Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.
- Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.
- Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule.
- Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.
- Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-4Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008773 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008773 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None		1		

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Train 508(02) Oregon City, OR - Reported Power Lines and Trees Down

02SEP26: Trains 508(02) and 507(02) were delayed after Union Pacific Railroad reported power lines and trees down near the tracks south of Oregon City, OR, at MP 748.25 on the Union Pacific Brooklyn Subdivision. As a result, Train 507(02), carrying 42 customers onboard, was held at Oregon City Station, while Train 508(02), carrying 61 customers onboard, was held south of the station near MP 742.4 pending assessment of the situation. Portland Electric personnel and a Union Pacific Track Inspector responded to the scene and determined that the downed power lines were adjacent to, rather than across, the tracks. Following the inspection and confirmation that train operations could safely resume, the route was reopened and both trains continued their scheduled operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
508(02)	1'03"	
507(02)	52"	

Train 49/449(02) East of Erie, PA - Weather

03SEP26: Train 49/449(02) with 236 customers was delayed on the CSX Erie West subdivision six miles east of Erie at CD 81.0 due to a large tree across both tracks at MP 84.8 that required a logging company for removal.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
49/449(02)	Est. 3'00"	

Train 718(02) East of Madera, CA - Freight Train Interference

03SEP26: Train 718(02) was delayed east of Madera, CA, while holding at Kismet Siding (MP 1024.8) on the BNSF Stockton Subdivision to meet BNSF 6577 and BNSF 3760.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(02)	31"	

Train 40(01) West of Pittsburgh, PA - System

03SEP26: Train 40(01) with E/327-330, ten cars, and 157 customers was delayed on the NS Pittsburgh East district starting five miles west of Pittsburgh due to the crew cutting out cab signals and operating on C lights between Bell/MP 4.8 and Cleveland/MP 181.6. The crew was restricted to 20mph between MP 74.0 through MP 86.0 as well as MP 94.0 through MP 102.0 due to PTC showing as interlocking.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(01)	48"	PGH-ALC

Train 4(02) East of Victorville, CA - Freight Train Interference

03SEP26: Train 4(02), carrying 160 customers, was delayed east of Victorville, CA, after stopping at East Oro Grande (MP 29.7) on the BNSF Cajon Subdivision due to a disabled freight train ahead. BNSF freight train SLBEALT131 experienced air system issues attributed to vandalism, blocking the route through the affected territory. An operating plan was implemented to route Train 4(02) around the disabled freight train via the adjacent main track once freight train HBARWCL cleared the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(02)	36"	

Train 5(01) East of Helper, UT - Police Related, Car Leaking CO2

02SEP26: Train 5(01), carrying 155 customers onboard, was delayed east of Helper, UT, at MP 622.1 on the Union Pacific Green River Subdivision due to a reported CO₂ leak from a railcar in a yard ahead. As a precaution, train movements through the area were halted while local police assessed the situation. Train 5(01) remained stopped until given clearance to proceed through area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(01)	1'19"	

Train 532(02) Oakland, CA - Third Party Contractor Engine Failure

02SEP26: Train 532(02), operating with locomotive JPBX920 and five cars, was delayed departing Oakland Jack London Square, CA, due to a Positive Train Control (PTC) fault on locomotive JPBX920. The crew recycled the PTC system in an effort to restore functionality. Once the system was successfully activated and verified operational, Train 532(02) departed and continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
532(02)	37"	

Train 5(01) East of Helper, UT - Injured or Sick Passenger

02SEP26: Train 5(01), carrying 155 customers onboard, was delayed approximately 13 miles east of Helper, UT, at MP 613.69 on the Union Pacific Green River Subdivision to meet emergency medical personnel for a customer requiring medical attention.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(01)	50"	

Train 8/28(01) West of Glasgow, MT - Freight Train Interference

02SEP26: Train 8/28(01) was delayed west of Glasgow, MT, while holding at Saco Siding (MP 318.1) on the BNSF Milk River Subdivision to meet BNSF freight traffic.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(01)	1'01"	

Train 319(02) West of Hermann, MO - Freight Train Interference

02SEP26: Train 319(02) with 53 customers was delayed on the UPRR Jefferson City subdivision 21 miles west of Hermann due to meeting MFXAS-02 at Ames/MP 102.1.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 3(02) West of Fort Madison, IA - Freight Train Interference

02SEP26: Train 3(02) with 180 customers was delayed on the BNSF Marceline subdivision starting 13 miles west of Fort Madison between Argyle/MP 246.2 and West Medill/MP 264.8 due to following BN 6022 and BN 5366.

Train	Delay	Comment
3(02)	1'03"	

Train 782(02) East of Los Angeles, CA - Switch Issue

02SEP26: Train 782(02), carrying 172 customers onboard, was delayed east of Los Angeles, CA, at West Hobart (MP 144.2) due to a switch malfunction. The crew attempted to manually line the switch; however, the switch would not properly lock into position. As a result, an alternate routing was utilized to move the train through the affected area.

Train	Delay	Comment
782(02)	34"	

Train 717(02) Corcoran, CA - Freight Train Interference

02SEP26: Train 717(02), carrying 74 customers onboard, was delayed while holding at Corcoran Station (MP 950.9) on the BNSF Bakersfield Subdivision due to a disabled freight train ahead. BNSF freight train Z-WSPST01-30A experienced brake issues, preventing train movements through the affected territory. Train 712(02) carrying 88 customers was also delayed at Hanford Station (MP 968.0) on the opposite side of the outage due to the same freight train malfunction. Once the freight train's air and brake issues were resolved, traffic through the area resumed and both trains continued their scheduled operations.

Train	Delay	Comment
717(02)	1'00"	
712(02)	33"	

Train 715(02) Modesto, CA - Freight Train Interference

02SEP26: Train 715(02), carrying 80 customers onboard, was delayed east of Modesto, CA, at Empire Junction (MP 1089.3) on the BNSF Stockton Subdivision while meeting a BNSF Z-train, symbol unknown. Once the meet was completed, Train 715(02) continued its scheduled operation.

Train	Delay	Comment
715(02)	30"	

Train 364(02) Chicago, IL - Engine Failure

02SEP26: Train 364(02) with E/ID4621, six cars, E/4630, and 113 customers was delayed after departing Chicago due to wyeing the equipment account of E/ID4621 with HVAC issues. After wyeing the equipment, the crew continued to Port Huron operating with E/ID4630 in the lead.

Train	Delay	Comment
364(02)	1'00"	

Train 352(02) West of Michigan City, IN - Signal

02SEP26: Train 352(02) with 165 passengers was delayed 31 miles west of Michigan City on the NS Chicago district at CP 482/MP 240.57 due to being held off the Amtrak Michigan line for at TOL reported at CP 238/MP 238.9. Maintainers were on scene, cleared the TOL, and 352(02) continued to New Buffalo.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(02)	31"	

Canadian National Centralia Subdivision Du Quoin, IL - Building Fire

02SEP26: Canadian National reported a fire department hold at MP288.5 on the Centralia Subdivision, just south of the Du Quoin, IL station. Multiple fire crews were on scene to tackle a fire involving three commercial buildings. Due to the report of a water main break, the fire department had two hydrant lines draped across the tracks. CN MOW and track inspector worked to bury the hoses under the ballast to open the route for train movement. At approximately 740PM-CT, the route was opened for train movement at reduced speed. The following operating plan was placed into effect:

392(02) was canceled. 4 buses secured for the 183 customers.

393(02) was canceled. 3 buses secured for the 153 customers.

WBS#: B.TR.100150.7129

Train 8/28(01) Shelby, MT to Wolf Point, MT - High Wind Warnings

02SEP26: Train 8/28(02) was delayed operating across BNSF territory east of Shelby, MT, due to multiple high wind warnings requiring reduced-speed operation. The train first encountered wind restrictions on the BNSF Hi Line Subdivision between Shelby (MP 1065.0) and MP 1053.0. Additional high wind restrictions were encountered between MP 998.0 on the Hi Line Subdivision and Havre, MT (MP 430.4) on the BNSF Milk River Subdivision. The restrictions remained in effect east of Havre, requiring reduced speeds between Havre and MP 345.0 on the Milk River Subdivision. The train incurred further delays east of Malta, MT, and west of Glasgow, MT, between MP 302.0 and MP 277.5, and again east of Glasgow and west of Wolf Point, MT, on the BNSF Glasgow Subdivision between MP 277.5 and MP 228.0. The high wind restrictions impacted train operations across multiple territories as the train traversed eastern Montana.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(01)	45"	SBY-HAV
8/28(01)	18"	MAL-GGW
8/28(01)	1'04"	HAV-MAL
8/28(01)	26"	GGW-WPT

Train 6(31) West of Galesburg, IL - Routing

02SEP26: Train 6(31) with 202 customers was delayed on the BNSF Ottumwa subdivision 13 miles west of Galesburg at CP1705/MP 170.5 due to crew inability to contact the dispatcher and holding for a route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(31)	31"	

Train 7/27(01) Glasgow, MT - Freight Train Interference

02SEP26: Train 7/27(01) was delayed east of Glasgow, MT, while holding at Whatley (MP 270.8) on the BNSF Glasgow Subdivision to meet BNSF 7705.

Train 505(02) East of Portland, OR - Cab Car Failure

02SEP26: Train 505(02) with 63 customers, locomotive WS1406, and carrying 63 customers onboard, was delayed east of Portland, OR, at MP 3.8 on the BNSF Fallbridge Subdivision following an emergency brake application. During the resulting inspection, the crew identified an air leak from a brake pipe compression fitting beneath cab car 7911 that prevented the train's air system from recovering. A BNSF carman was requested to assist, and a decision was made to cut out the cab car and shove the train into Portland to minimize customer impacts.

The equipment defect resulted in the following service impacts and recovery actions:

- Train 518(02) was unable to utilize the affected equipment after mechanical personnel in Portland were unsuccessful in repairing cab car 7911.
- Train 518(02) subsequently operated using inbound Train 517(02) equipment, resulting in delays to customers.
- The affected equipment was reassigned to Train 506(02); however, due to the cut-out brake system on cab car 7911, the train was restricted to freight speeds.
- To mitigate further impacts, Train 506(02) was terminated at Olympia-Lacey, WA.
- Two buses were secured to transport customers from Olympia-Lacey to Seattle, WA.
- Following customer accommodation, the equipment operated deadhead to the Seattle Maintenance Facility for inspection and repair.

WBS#: B.TR.100150.7131

Train	Delay	Comment
505(02)	1'16"	
506(02)	34"	TERM OLV
518(02)	2'49"	

Train 352(02) West of Hammond-Whiting, IN - M of W Work

02SEP26: Train 352(02) with 165 customers was delayed on the NS Chicago district six miles west of Hammond-Whiting at CP 513/MP 513.3 due to holding for MOW clearance.

Train	Delay	Comment
352(02)	31"	

Train 5(31) East of Colfax, CA - Freight Train Interference

02SEP26: Train 5(31) was delayed east of Colfax, CA, while holding at Gold Run (MP 152.8) on the Union Pacific Roseville Subdivision to meet UP 5447.

Train	Delay	Comment
5(31)	43"	

Train 58(02) Jackson, MS - System

02SEP26: Train 58(02) with 104 customers was delayed on the CN McComb subdivision at Jackson station/MP 728.7 due to holding for a relief engineer. Once the engineer arrived, briefed, and boarded the train, 58(02) departed Jackson at 429PM-CT, 49 minutes late.

Train	Delay	Comment
58(02)	49"	

Train 710(02) Modesto, CA - Third Party Contractor Engine Failure

02SEP26: Train 710(02) was operating with locomotive C2012 and carrying approximately 80 customers onboard, became disabled at Modesto, CA, on the BNSF Stockton Subdivision after the locomotive experienced a loss-of-load condition and would not restart. The crew worked with TASI to troubleshoot the issue and reported alarm code 3833 (Failed Feedback). Head-end power remained available throughout the incident.

Due to the locomotive failure, all customers were detrained at Modesto and accommodated onto Train 712(02). To clear the route, Train 701(02) coupled onto the disabled equipment and moved it to Main Track 2 at Empire (MP 1089.2). Once the movement was completed and the route was clear, Train 701(02) resumed its scheduled operation.

The incident resulted in the following service impacts and recovery actions:

- Train 710(02) was terminated at Modesto, CA.
- After troubleshooting efforts were unsuccessful, Train 715(02) was assigned to couple onto the disabled equipment and double-draft the consist to Emeryville, CA.
- Upon arrival in Emeryville, the equipment was removed from service and routed to the Oakland Maintenance Facility for inspection and repair.
- Train 712(02) equipment was utilized to operate Train 719(02).
- Train 714(02) equipment was utilized to operate Train 703(02).
- Train 713(03) was canceled.

WBS#: B.TR.100150.7130

Train	Delay	Comment
710(02)	Terminated MOD	
713(03)	Canceled	
701(02)	2'06"	
715(02)	51"	Tow 710(02) & TERM EMY
712(02)	24"	
719(02)	2'44"	late turn from 712(02)
703(02)	1'50"	late turn from 714(02)

Train 6(02) West of Colfax, CA - Freight Train Interference

02SEP26: Train 6(02), carrying 144 customers onboard, was delayed west of Colfax, CA, at Bowman (MP 128.8) on the Union Pacific Roseville Subdivision while meeting freight train Z9821.

Train	Delay	Comment
6(02)	49"	

Train 713(02) East of Fresno, CA - Refueling

02SEP26: Train 713(02) was delayed east of Fresno, CA, at Calwa Yard (MP 994.3) on the BNSF Stockton Subdivision while refueling locomotive C2006, as fueling operations were no longer being performed in Bakersfield, CA. Additional delays were incurred en route due to freight traffic interference and passenger train meets along the route. As a result of the cumulative delays, a decision was made to terminate Train 713(02) at Emeryville, CA. Train 718(02) subsequently experienced delays turning from the late inbound equipment and was originated from Emeryville, CA, rather than its normal point of origin.

Train	Delay	Comment
718(02)	1'10"	ORIG EMY
713(02)	35"	TERM EMY

Union Pacific Springfield Subdivision South of Bloomington-Normal, IL - Freight Train Interference

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

02SEP26: Union Pacific reported ITUG4-29 (UPRR 2557) disabled on single main track at approximately MP 127.0 on the Springfield Subdivision, 3 miles south of the Bloomington-Normal, IL station. IG4LB-02 at Mazonia / MP 63.0 was en route to rescue. Upon arriving the IG4LB-02 separated its locomotives to drag the equipment into the clear before returning to its trainset.

Train 319(02) was held at the Pontiac, IL station / MP 92.1 and Train 22(01)/422(30) was held at the Lincoln, IL Station / MP 156.4.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(02)	1'18"	
22(01)/422(30)	52"	

Train 6(31) West of Creston, IA - Injured or Sick Passenger

02SEP26: 10:00A-CDT, Train 6(31) stopped in Villisca, IA in Montgomery County at MP 427.1 on the Burlington Northern Santa Fe Creston Subdivision, 34 miles west of the Creston, IA station, account of an unresponsive customer. EMTs responded and attempted to resuscitate the customer. The customer was transported from the location by EMT. Three family members detrain and were transported with the individual.

National Response Center Number: 1472524

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(31)	26"	

Train 500(02) Portland, OR - PTC Failure

02SEP26: Train 500 (02) with WS1405 and 55 customers experienced a delayed departure from Portland, OR, on the BNSF Fallbridge Subdivision due to Positive Train Control (PTC) issues. After extensive troubleshooting, the cause was determined to be a GPS-related issue that prevented PTC initialization. The train crew was authorized to advance the equipment, which successfully engaged the GPS signal and allowed PTC to initialize properly. Once PTC was established, Train 500(02) departed and continued its route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
500(02)	53"	

Train 525(02) Sacramento, CA - PTC Failure

02SEP26: Train 525(02) ^{26-FOI-00731 JPBX921 00000008773 UNCLASSIFIED 9/18/2028} experienced a delayed departure from Sacramento, CA, on the UPRR Martinez Subdivision due to an inability to initialize Positive Train Control (PTC). The crew worked with the UPRR PTC Desk and TASI to troubleshoot the issue. UPRR did not authorize operation in cutout mode from the initial terminal, requiring passengers to be re-accommodated on Train 527 (02).

During troubleshooting, the locomotive initially would not provide sufficient digits for the engineer to enter their employee ID and log in. After cycling the PTC breaker, the crew was able to successfully log in; however, consist information was not displayed. The PTC Desk re-entered the consist information, which then populated correctly. Despite these corrective actions, the PTC system remained disengaged and would not transition to an active state or provide track selection options to the engineer. The crew also attempted to move the train approximately two train lengths to facilitate PTC initialization, but the issue persisted.

Due to the unresolved PTC failure, Train 525/526(02) were canceled in their entirety.

Train 536(02) operating the same equipment of E/JPBX921 and 5 cars was delayed departing the yard for continued PTC issues with this unit. Decision was made to wye the set and originate the train at Emeryville, CA station. The next turn train 549(02) was also wyeed before its departure from Sacramento.

Train	Delay	Comment
525(02)	Canceled	
526(02)	Canceled	
536(02)	50"	ORIG EMY

Train 21/421(01) North of Malvern, AR - Signal

02SEP26: Train 21/421(01) was delayed between Haskell / MP 371.4 and Traskwood / MP 377.1 on the Union Pacific Little Rock Subdivision, starting 18 mile north of the Malvern, AR station, due to signal failure. The crew was flagged through the area.

Train 21/421(01) was further delayed at the CPKC X-ing / MP 51.3, 15 miles north of the Marshall, TX station, account of a signal failure. The crew was instructed to operate the signal box.

Train	Delay	Comment
21/421(01)	40"	North of Malvern
21/421(01)	30"	North of Marshall

Train 351(02) West of Ann Arbor, MI - M of W Work

02SEP26: Train 351(02) was delayed at CP 52 / MP 52.0 on the Michigan Department of Transportation Michigan Line, 15 miles west of the Ann Arbor, MI station waiting on Amtrak IMCS to clear. Once clear, The crew was instructed to operate by the signal.

Train	Delay	Comment
351(02)	30"	

Train 40(31) Waterloo, IN - Injured Passenger

02SEP26: Train 40(31) was delayed departing the Waterloo, IN station due to a passenger injury. Local Fire department met the train to evaluate the customer.

Train 49/449(01) was held just east of the station to allow the fire department to assist the customer.

Train	Delay	Comment
40(31)	41"	
49(01)	30"	

Train 4(01) West of Kingman, AZ - Passenger Train Interference

02SEP26: Train 4(01) delayed at E-Griffith/MP 528.8 on the BNSF Seligman Subdivision, 12 miles west of Kingman, AZ due to meeting Train 3(01).

Train	Delay	Comment
4(01)	30"	

Train 6(02) East of Colfax, CA - Engine Failure

02SEP26: Train 6(02), operating with locomotives E/163 and E/139, nine cars, and 144 customers onboard, was delayed approximately 16 miles east of Colfax, CA, at MP 158.4 on the Union Pacific Roseville Subdivision due to a traction loss issue on trailing locomotive E/139. The crew worked to troubleshoot the locomotive; however, the unit remained unable to provide tractive effort. As a result, the train was required to climb the mountain grade from its stopping location toward Norden (MP 192) utilizing only the lead locomotive, E/163. The reduced available power resulted in repeated stalls and recovery attempts as the train continued toward Truckee, CA. To protect service and ensure continued operation, Union Pacific locomotive 8997 was secured at Sparks, NV, and added to the head end of the train for additional power.

Train	Delay	Comment
6(02)	2'52"	ENG failure, Climb Donner Pass
6(02)	1'05"	Add UP8997

BNSF Systemwide Outage - System

01SEP26: 230PM-ET, BNSF conducted a change of train sheets involving a code change. After the change, multiple trains were delayed account of BNSF experiencing a nationwide train sheet outage that hampered crews from logging into PTC. The BNSF attempted to back out the application change and the back out failed. Attempts were made to utilize a server that was unchanged, which failed. Rebooting the impacted servers failed. Crews were advised to contact the dispatcher, recycle the PTC breaker, and manually enter their information to attempt to initialize during the outage.

The FRA granted BNSF a waiver under 49 CFR 236.1029(B) that permitted trains to depart without active PTC. After communicating with the dispatcher, trains that could not go active were permitted to depart without active PTC. Crews were advised to review GCOR 18.12 to determine maximum authorized speed.

Train 383(01) was canceled in its entirety. 2 buses were secured for 59 customers.

BNSF reported PTC restored at 5:15A-EDT.

02SEP26: Train 4(31) was delayed departing the Kansas City, MO Union Station, waiting on crew rest from late inbound Train 3(02). The crew signed up on duty at 9:45A-CT.

WBS#: B.TR.100150.7128

Train	Delay	Comment
580(01)	51"	LAX
3(31)	23"	ABQ
509(01)	13"	SEA
581(01)	28"	SNC-ANA
506(01)	44"	PDX
782(01)	41"	LAX
591(01)	11"	SAN - late turn of equip 580(01)
593(01)	50"	SAN - late turn of equip 782(01)
4(31)	33"	LAJ
6(31)	1'00"	DEN
383(01)	Canceled	CHI
704(01)	17"	SKT-MOD
785(01)	12"	SAN-ANA
6(01)	18"	RNO
518(01)	26"	SEA
508(01)	11"	PDX-VAN
703(01)	1'10"	BFD-COC
28(01)	17"	PSC
717(01)	46"	BFD-MTZ
7/27(01)	35"	W/RDW
3(01)	2'49"	W/FMD
519(01)	2'35"	VAC-STW
3(01)	42"	E/LAP
718(01)	1'49"	MTZ-WAC
8(01)	2'49"	SEA-WEN
6(31)	1'00"	FMG-HLD
4(31)	1'49"	KCY - Crew Rest from Late 3(01)

Train 822(01) and Train 821(02) Canceled - Utility Company Failure

01SEP26: Burlington Northern Santa Fe reported several power lines down across the tracks at MP 383.5 on the Fort Worth Subdivision, 27 miles south of Gainesville, TX. The initial estimated track opening was 12:00A-CDT.

Train 822(01) with 43 customers and Train 821(02) with 36 customers were canceled in their entirety. One bus was secured for each train.

WBS#: B.TR.100150.7125

Train	Delay	Comment
822(01)	Canceled	
821(02)	Canceled	

Train 6(01) East of Roseville, CA - Engine Failure

01SEP26: Train 6(01), 254-POL-00731 E/206 and 153 cars, was delayed at Roseville, CA, on the UPRR Martinez Subdivision. The train had been scheduled to depart Emeryville, CA, with locomotive E/81 in the lead, but E/81 was removed from service due to dynamic brake faults. With no replacement locomotive immediately available, Train 6(01) departed Emeryville operating with a single locomotive, E/206.

Upon arrival at Roseville (RSV), Union Pacific Railroad (UPRR) provided locomotive UP 5179 to protect the train for continued operation. The additional locomotive was added to support the train's movement through to Chicago, IL.

02SEP26: Train 6(01) was delayed departing the Grand Junction, CO station due to radio issues on lead Locomotive UP 5179. With assistance from mechanical, the crew was able to make repairs.

Train	Delay	Comment
6(01)	1'21"	
6(01)	39"	GJT
6(01)	1'02"	RNO to GJT - Operating with freight

Tropical Storm Edouardo Beaumont, TX - Weather

01SEP26: Tropical Storm Edouard made land fall and is expected to drop up to 20 inches of rain between Houston, TX and Beaumont, TX. Winds were expected in excess of 80mph. The forecast had shifted the storm east and placed it in Beaumont at the same time as Train 2(31)'s scheduled departure time. As a result the following operating plan was placed into effect:

Train 2(31) was terminated in Houston, TX.
Two buses were secured to provide alternate transportation to the 59 customers. The buses departed Houston at 1:05P-CDT, 55 minutes late
Train 1(02) will originate in Houston, TX.
Buses are being held off waiting on conditions of the storm.

02SEP26: Two buses were secured for the 62 affected customers on Train 1(02). One bus expressed from New Orleans to Houston while the second bus made all stops.

WBS#: B.TR.100150.7122

Train	Delay	Comment
2(30)	Terminated	HOS
1(02)	Originate	HOS

Union Pacific Sedalia, Jefferson City, Springfield and Joliet Subdivision Kansas City, MO to St. Louis, MO to Joliet, IL - Heat Restrictions

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

31AUG26: Union Pacific placed Level 2 heat restrictions on the entire Sedalia and Jefferson City Sub division from Kansas City, MO and St. Louis, MO. Trains were limited to 40mph.

Train 311(31), 316(31), 318(31), and Train 319(31) were delayed account of the restrictions.

01SEP26: Union Pacific also added Level 2 heat restrictions on the Joliet and Springfield Subdivision from St. Louis, MO and Joliet, IL. Trains were limited to 50mph.

Train 311(01), Train 316(01), Train 318(01), Train 319(01), Train 301(01), Train 302(01), Train 22(31)/422(30AUG), Train 21/421(01), Train 305(01), Train 306(01) and Train 307(01) were delayed account of the restrictions.

02SEP26: Continued Union Pacific Level 2 heat restrictions on the Joliet, Springfield, Sedalia and Jefferson City Subdivision.

WBS#: B.TR.100150.7132

Train	Delay	Comment
316(31)	31"	
319(31)	32"	
318(31)	14"	
311(31)	12"	
301(01)	1'30"	JOL to STL
302(01)	1'04"	LCN to JOL
311(01)	51"	HEM to KCY
305(01)	1'05"	JOL-LCN
22(31)	1'02"	ALN-JOL
307(01)	20"	JOL-DWT
21(01)	1'58"	JOL-ALN
306(01)	1'04"	
301(02)	1'05"	
22(01)/422(30)	1'58"	
302(02)	1'02"	
21(02)	1'57"	
319(02)	1'53"	
307(02)	24"	
305(02)	1'09"	
318(02)	1'57"	
306(02)	1'01"	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
 - Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
 - Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 009000087731"UNCLASSIFIED" 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues
22 (18)	XNT	315		I/O 47 faults
	Corwith	347		Braking Issues R3

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (1)	RSV	UP5179	Single engine from EMY		
6 (2)	RNO	UP8997	E/139 No Load		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00731

00000008773

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
98 (02)	MIA	VIEW II REPLACED WITH VIEW I 62029 9812	n/a	0	62029

Reverse Consists

Train Number	Station	Reason
95 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
178 (02)	RNK	Consist reversed Business class seat orientation may have changed At Front
125 (02)	SPG	Consist reversed Business class seat orientation may have changed At Front
94 (02)	NFK	Consist reversed Business class seat orientation may have changed At Front
190 (02)	PHL	Consist reversed Business class seat orientation may have changed At Front
113 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
137 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
86 (03)	NPN	Consist reversed Business class seat orientation may have changed At Front.. **Train 86(03)**
136 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
84 (02)	WAS	Consist reversed Business class seat orientation may have changed At Rear
178 (03)	RNK	Consist reversed Business class seat orientation may have changed At Front.. **Train 178(03)**
94 (03)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 94(03)**
174 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
184 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
148 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
141 (03)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 141(03)**