27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, October 30, 2026 Rules: 4-4



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-001

Initial Terminal Performance By Division

Scheduled Departure Date: **10/29/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/29/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	302	41	86.4%	8,888	1,272	85.7%	8,888	1,272	85.7%
Central Division	86.0%	53	2	96.2%	1,659	121	92.7%	1,659	121	92.7%
East Division	82.0%	158	25	84.2%	4,699	702	85.1%	4,699	702	85.1%
West Division	86.0%	91	14	84.6%	2,530	449	82.3%	2,530	449	82.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/29/26

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**76%**	**93,069**	**24,342**	**74%**	**2,944,885**	**842,347**	**71%**	**2,944,885**	**842,347**	**71%**
Northeast Corridor	***78%***	***42,499***	***11,211***	***74%***	***1,272,429***	***309,491***	***76%***	***1,272,429***	***309,491***	***76%***
Acela	80%	6,512	1,330	80%	227,426	45,423	80%	227,426	45,423	80%
Northeast Regional	78%	35,987	9,881	73%	1,045,003	264,068	75%	1,045,003	264,068	75%
Richmond / Newport News / Norfolk	75%	8,110	3,908	52%	251,500	68,932	73%	251,500	68,932	73%
Springfield Shuttles	89%	723	43	94%	21,557	4,647	78%	21,557	4,647	78%
Roanoke	75%	2,675	1,410	47%	90,894	26,050	71%	90,894	26,050	71%
On Spine Northeast Regional	80%	24,479	4,520	82%	681,052	164,439	76%	681,052	164,439	76%
State Supported	***80%***	***41,678***	***9,515***	***77%***	***1,329,502***	***378,849***	***72%***	***1,329,502***	***378,849***	***72%***
Borealis	80%	627	177	72%	20,808	4,060	80%	20,808	4,060	80%
Capitol Corridor	90%	4,265	966	77%	120,971	23,623	80%	120,971	23,623	80%
Carolinian	70%	1,414	557	61%	37,620	11,885	68%	37,620	11,885	68%
Cascades	75%	2,596	927	64%	81,657	23,975	71%	81,657	23,975	71%
Downeaster	82%	1,574	211	87%	53,779	12,435	77%	53,779	12,435	77%
Empire	78%	5,518	608	89%	185,864	44,680	76%	185,864	44,680	76%
Adirondack	72%	322	0	100%	12,257	2,064	83%	12,257	2,064	83%
Ethan Allen Express	70%	528	12	98%	17,385	6,511	63%	17,385	6,511	63%
Maple Leaf	70%	780	143	82%	25,268	8,030	68%	25,268	8,030	68%
New York - Albany	85%	2,731	218	92%	90,119	16,576	82%	90,119	16,576	82%
New York - Niagara Falls	75%	1,157	235	80%	40,835	11,499	72%	40,835	11,499	72%
Gold Runner	73%	2,459	448	82%	73,649	28,906	61%	73,649	28,906	61%
Heartland Flyer	70%	178	176	1%	5,781	4,957	14%	5,781	4,957	14%
Hiawatha	90%	1,694	157	91%	54,252	5,756	89%	54,252	5,756	89%
Illinois	78%	2,583	716	72%	79,091	26,289	67%	79,091	26,289	67%
Carl Sandburg / Illinois Zephyr	85%	352	152	57%	12,591	3,247	74%	12,591	3,247	74%
Illini / Saluki	85%	951	391	59%	26,587	11,623	56%	26,587	11,623	56%
Lincoln Service	70%	1,280	173	86%	39,913	11,419	71%	39,913	11,419	71%
Keystone	92%	6,521	100	98%	202,725	20,804	90%	202,725	20,804	90%
Lincoln / Missouri	70%	833	123	85%	25,163	12,448	51%	25,163	12,448	51%
Mardi Gras Service	80%	253	0	100%	8,609	2,573	70%	8,609	2,573	70%
Michigan	70%	590	295	50%	62,967	16,268	74%	62,967	16,268	74%
Blue Water	70%	299	295	1%	15,673	4,742	70%	15,673	4,742	70%
Pere Marquette	85%	291	0	100%	8,777	508	94%	8,777	508	94%
Wolverine	70%	0	0	-	38,517	11,018	71%	38,517	11,018	71%
Missouri	80%	234	104	56%	8,378	1,621	81%	8,378	1,621	81%
Pacific Surfliner	85%	6,996	3,115	55%	200,192	106,941	47%	200,192	106,941	47%
Pennsylvanian	80%	914	0	100%	27,166	8,961	67%	27,166	8,961	67%
Piedmont	80%	964	344	64%	35,615	10,014	72%	35,615	10,014	72%
Vermonter	75%	1,465	491	66%	45,215	12,653	72%	45,215	12,653	72%
Long Distance	***58%***	***8,892***	***3,616***	***59%***	***342,954***	***154,007***	***55%***	***342,954***	***154,007***	***55%***
Auto Train	70%	660	660	0%	19,428	14,174	27%	19,428	14,174	27%
California Zephyr	70%	835	419	50%	27,427	8,051	71%	27,427	8,051	71%
Cardinal	70%	381	267	30%	6,087	3,012	51%	6,087	3,012	51%
City Of New Orleans	75%	626	480	23%	21,701	15,357	29%	21,701	15,357	29%
Coast Starlight	70%	375	375	0%	31,338	16,496	47%	31,338	16,496	47%
Crescent	70%	905	251	72%	27,837	4,368	84%	27,837	4,368	84%
Empire Builder	70%	889	433	51%	30,278	11,888	61%	30,278	11,888	61%
Floridian	60%	1,389	119	91%	39,441	22,109	44%	39,441	22,109	44%
Lake Shore Ltd	73%	866	206	76%	30,693	9,746	68%	30,693	9,746	68%
Palmetto	70%	433	71	84%	21,300	4,785	78%	21,300	4,785	78%
Silver Meteor	70%	796	313	61%	30,594	8,853	71%	30,594	8,853	71%
Southwest Chief	60%	0	0	-	22,399	17,116	24%	22,399	17,116	24%
Sunset Ltd	70%	0	0	-	8,200	3,879	53%	8,200	3,879	53%
Texas Eagle	70%	737	22	97%	26,231	14,173	46%	26,231	14,173	46%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27-FOI-00101 00000000046 "UNCLASSIFIED" 11/2/2026~~

Train Index Dates Through October 29, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	178,147	2,888,549	617	178,147	2,888,549	617

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	9,094	822,024	111	9,094	822,024	111
INFRASTRUCTURE PLANNED	135	18,896	822,024	230	18,896	822,024	230
FLEET RELIABILITY	90	24,502	2,888,549	85	24,502	2,888,549	85
TRAIN OPERATIONS	424	125,655	2,888,549	435	125,655	2,888,549	435

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-001

Initial Terminal Performance By Division

Scheduled Departure Date: **10/29/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/29/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	302	41	86.4%	8,888	1,272	85.7%	8,888	1,272	85.7%
Central Division	86.0%	53	2	96.2%	1,659	121	92.7%	1,659	121	92.7%
East Division	82.0%	158	25	84.2%	4,699	702	85.1%	4,699	702	85.1%
West Division	86.0%	91	14	84.6%	2,530	449	82.3%	2,530	449	82.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

27-FOI-001

Scheduled Departure Date: **10/29/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/29/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	302	41	86.4%	8,888	1,272	85.7%	8,888	1,272	85.7%
Central Division	86.0%	53	2	96.2%	1,659	121	92.7%	1,659	121	92.7%
CDL	95.0%	1	0	100.0%	38	3	92.1%	38	3	92.1%
CHI	86.0%	25	1	96.0%	778	66	91.5%	778	66	91.5%
CHM	-	1	0	100.0%	19	3	84.2%	19	3	84.2%
DAL	-	-	-	-	2	0	100.0%	2	0	100.0%
DET	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	26	2	92.3%	26	2	92.3%
GRR	95.5%	1	0	100.0%	29	0	100.0%	29	0	100.0%
IND	-	-	-	-	4	0	100.0%	4	0	100.0%
KCY	92.0%	2	0	100.0%	59	1	98.3%	59	1	98.3%
MKE	92.0%	6	1	83.3%	169	12	92.9%	169	12	92.9%
MOE	97.5%	2	0	100.0%	51	0	100.0%	51	0	100.0%
MSP	96.5%	1	0	100.0%	29	0	100.0%	29	0	100.0%
NOL	94.5%	4	0	100.0%	117	5	95.7%	117	5	95.7%
OKC	97.0%	1	0	100.0%	28	2	92.9%	28	2	92.9%
PNT	88.0%	-	-	-	78	12	84.6%	78	12	84.6%
PTH	93.0%	1	0	100.0%	29	1	96.6%	29	1	96.6%
QCY	91.0%	2	0	100.0%	58	3	94.8%	58	3	94.8%
SAS	90.5%	1	0	100.0%	28	6	78.6%	28	6	78.6%
STL	89.0%	4	0	100.0%	115	3	97.4%	115	3	97.4%
TAY	-	-	-	-	1	1	0.0%	1	1	0.0%
East Division	82.0%	158	25	84.2%	4,699	702	85.1%	4,699	702	85.1%
ALB	88.5%	8	0	100.0%	229	18	92.1%	229	18	92.1%
ALX	-	-	-	-	27	14	48.1%	27	14	48.1%
ATL	-	-	-	-	14	4	71.4%	14	4	71.4%
BON	87.5%	5	1	80.0%	145	12	91.7%	145	12	91.7%
BOS	85.5%	12	1	91.7%	374	22	94.1%	374	22	94.1%
BRK	92.5%	5	1	80.0%	145	10	93.1%	145	10	93.1%
BTN	82.0%	1	1	0.0%	29	5	82.8%	29	5	82.8%
CLT	91.5%	5	0	100.0%	139	18	87.1%	139	18	87.1%
GFD	88.0%	2	0	100.0%	58	6	89.7%	58	6	89.7%
GRO	-	1	0	100.0%	11	0	100.0%	11	0	100.0%
HAR	79.5%	13	0	100.0%	334	35	89.5%	334	35	89.5%
HFD	-	2	1	50.0%	42	8	81.0%	42	8	81.0%
JAX	-	-	-	-	18	2	88.9%	18	2	88.9%
LOR	84.0%	1	0	100.0%	27	11	59.3%	27	11	59.3%
MET	-	-	-	-	1	1	0.0%	1	1	0.0%
MIA	89.5%	2	0	100.0%	57	8	86.0%	57	8	86.0%
MTR	79.0%	1	0	100.0%	29	8	72.4%	29	8	72.4%
NFK	84.5%	2	0	100.0%	47	8	83.0%	47	8	83.0%
NFL	93.5%	2	0	100.0%	58	5	91.4%	58	5	91.4%
NFS	-	-	-	-	3	3	0.0%	3	3	0.0%
NHV	78.0%	5	0	100.0%	147	32	78.2%	147	32	78.2%
NPN	93.0%	2	0	100.0%	36	4	88.9%	36	4	88.9%

Information Management

27-FOI-001

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/29/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/29/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	302	41	86.4%	8,888	1,272	85.7%	8,888	1,272	85.7%
East Division	82.0%	158	25	84.2%	4,699	702	85.1%	4,699	702	85.1%
NYP	75.5%	39	8	79.5%	1,216	210	82.7%	1,216	210	82.7%
PGH	93.0%	1	0	100.0%	37	10	73.0%	37	10	73.0%
PHL	48.0%	11	6	45.5%	231	107	53.7%	231	107	53.7%
RGH	95.0%	3	1	66.7%	118	21	82.2%	118	21	82.2%
RNK	83.5%	2	2	0.0%	47	6	87.2%	47	6	87.2%
SAB	98.0%	1	0	100.0%	29	0	100.0%	29	0	100.0%
SAV	96.0%	1	0	100.0%	18	0	100.0%	18	0	100.0%
SFA	88.0%	1	0	100.0%	27	5	81.5%	27	5	81.5%
SPG	92.5%	5	0	100.0%	157	10	93.6%	157	10	93.6%
TWO	73.0%	1	0	100.0%	26	8	69.2%	26	8	69.2%
WAS	84.0%	24	3	87.5%	823	91	88.9%	823	91	88.9%
West Division	86.0%	91	14	84.6%	2,530	449	82.3%	2,530	449	82.3%
ARN	92.0%	1	0	100.0%	29	2	93.1%	29	2	93.1%
BFD	79.0%	7	2	71.4%	195	48	75.4%	195	48	75.4%
EMY	72.0%	1	0	100.0%	33	14	57.6%	33	14	57.6%
EUG	86.5%	2	0	100.0%	55	3	94.5%	55	3	94.5%
FNO	-	-	-	-	5	4	20.0%	5	4	20.0%
GAC	-	-	-	-	3	2	33.3%	3	2	33.3%
GTA	90.0%	6	2	66.7%	119	48	59.7%	119	48	59.7%
IRV	-	-	-	-	1	0	100.0%	1	0	100.0%
LAX	89.5%	10	1	90.0%	279	31	88.9%	279	31	88.9%
OKJ	74.5%	13	5	61.5%	341	107	68.6%	341	107	68.6%
PDX	86.0%	5	0	100.0%	145	12	91.7%	145	12	91.7%
SAC	88.5%	15	0	100.0%	428	41	90.4%	428	41	90.4%
SAN	90.5%	13	3	76.9%	335	68	79.7%	335	68	79.7%
SEA	85.0%	8	1	87.5%	231	27	88.3%	231	27	88.3%
SJC	89.0%	7	0	100.0%	202	32	84.2%	202	32	84.2%
SLO	90.0%	-	-	-	42	8	81.0%	42	8	81.0%
SPK	90.0%	1	0	100.0%	28	0	100.0%	28	0	100.0%
VAC	97.0%	2	0	100.0%	54	1	98.1%	54	1	98.1%
VNC	-	-	-	-	5	1	80.0%	5	1	80.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
5	55	28	2	92.9%	28	2	92.9%	28	8	71.4%	28	8	71.4%
6		28	12	57.1%	28	12	57.1%	28	8	71.4%	28	8	71.4%
7		28	2	92.9%	28	2	92.9%	28	2	92.9%	28	2	92.9%
8	60	28	7	75.0%	28	7	75.0%	28	16	42.9%	28	16	42.9%
11	No OS	29	4	86.2%	29	4	86.2%	29	18	37.9%	29	18	37.9%
14	198	29	7	75.9%	29	7	75.9%	29	17	41.4%	29	17	41.4%
19	76	29	5	82.8%	29	5	82.8%	28	6	78.6%	28	6	78.6%
20		29	3	89.7%	29	3	89.7%	29	3	89.7%	29	3	89.7%
21		29	2	93.1%	29	2	93.1%	28	12	57.1%	28	12	57.1%
22		29	7	75.9%	29	7	75.9%	29	18	37.9%	29	18	37.9%
23		26	0	100.0%	26	0	100.0%	26	6	76.9%	26	6	76.9%
24		25	0	100.0%	25	0	100.0%	25	6	76.0%	25	6	76.0%
25		25	0	100.0%	25	0	100.0%	25	7	72.0%	25	7	72.0%
26		26	0	100.0%	26	0	100.0%	26	8	69.2%	26	8	69.2%
27		28	3	89.3%	28	3	89.3%	28	6	78.6%	28	6	78.6%
28	18	28	3	89.3%	28	3	89.3%	28	6	78.6%	28	6	78.6%
40		29	10	65.5%	29	10	65.5%	29	14	51.7%	29	14	51.7%
41		29	3	89.7%	29	3	89.7%	29	13	55.2%	29	13	55.2%
42		29	3	89.7%	29	3	89.7%	29	10	65.5%	29	10	65.5%
43		29	8	72.4%	29	8	72.4%	28	12	57.1%	28	12	57.1%
48		29	4	86.2%	29	4	86.2%	29	11	62.1%	29	11	62.1%
49		29	5	82.8%	29	5	82.8%	29	6	79.3%	29	6	79.3%
51	58	12	3	75.0%	12	3	75.0%	13	5	61.5%	13	5	61.5%
52	27	27	5	81.5%	27	5	81.5%	27	15	44.4%	27	15	44.4%
53	80	27	11	59.3%	27	11	59.3%	27	23	14.8%	27	23	14.8%
55		21	0	100.0%	21	0	100.0%	21	5	76.2%	21	5	76.2%
56		21	3	85.7%	21	3	85.7%	21	3	85.7%	21	3	85.7%
58	75	29	1	96.6%	29	1	96.6%	29	25	13.8%	29	25	13.8%
59	44	29	2	93.1%	29	2	93.1%	29	21	27.6%	29	21	27.6%
63	64	29	12	58.6%	29	12	58.6%	29	26	10.3%	29	26	10.3%
64		29	11	62.1%	29	11	62.1%	29	16	44.8%	29	16	44.8%
66	28	28	4	85.7%	28	4	85.7%	28	4	85.7%	28	4	85.7%
67		20	4	80.0%	20	4	80.0%	20	5	75.0%	20	5	75.0%
68		29	8	72.4%	29	8	72.4%	29	7	75.9%	29	7	75.9%
69		29	10	65.5%	29	10	65.5%	29	2	93.1%	29	2	93.1%
71	29	29	2	93.1%	29	2	93.1%	29	5	82.8%	29	5	82.8%
72		29	5	82.8%	29	5	82.8%	29	3	89.7%	29	3	89.7%
73	21	24	4	83.3%	24	4	83.3%	24	11	54.2%	24	11	54.2%
74		24	5	79.2%	24	5	79.2%	24	11	54.2%	24	11	54.2%
75		29	2	93.1%	29	2	93.1%	27	6	77.8%	27	6	77.8%
76	16	28	4	85.7%	28	4	85.7%	27	11	59.3%	27	11	59.3%
77		29	4	86.2%	29	4	86.2%	29	10	65.5%	29	10	65.5%

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		29	4	86.2%	29	4	86.2%	30	6	80.0%	30	6	80.0%
79	73	29	6	79.3%	29	6	79.3%	29	11	62.1%	29	11	62.1%
80		29	0	100.0%	29	0	100.0%	29	6	79.3%	29	6	79.3%
89		18	1	94.4%	18	1	94.4%	18	8	55.6%	18	8	55.6%
90	60	18	0	100.0%	18	0	100.0%	18	6	66.7%	18	6	66.7%
94		18	3	83.3%	18	3	83.3%	18	3	83.3%	18	3	83.3%
97		29	10	65.5%	29	10	65.5%	29	4	86.2%	29	4	86.2%
98		29	3	89.7%	29	3	89.7%	29	10	65.5%	29	10	65.5%
230		29	1	96.6%	29	1	96.6%	29	1	96.6%	29	1	96.6%
232		29	1	96.6%	29	1	96.6%	29	2	93.1%	29	2	93.1%
233	19	29	11	62.1%	29	11	62.1%	29	12	58.6%	29	12	58.6%
234		29	0	100.0%	29	0	100.0%	29	1	96.6%	29	1	96.6%
235		29	4	86.2%	29	4	86.2%	29	8	72.4%	29	8	72.4%
236		29	0	100.0%	29	0	100.0%	29	5	82.8%	29	5	82.8%
237		29	4	86.2%	29	4	86.2%	29	9	69.0%	29	9	69.0%
238		29	4	86.2%	29	4	86.2%	29	3	89.7%	29	3	89.7%
239		28	5	82.1%	28	5	82.1%	28	2	92.9%	28	2	92.9%
240		29	3	89.7%	29	3	89.7%	29	2	93.1%	29	2	93.1%
241		29	5	82.8%	29	5	82.8%	29	8	72.4%	29	8	72.4%
243	73	29	5	82.8%	29	5	82.8%	29	1	96.6%	29	1	96.6%
244		29	0	100.0%	29	0	100.0%	29	10	65.5%	29	10	65.5%
245	37	29	4	86.2%	29	4	86.2%	29	5	82.8%	29	5	82.8%
280	91	29	3	89.7%	29	3	89.7%	29	12	58.6%	29	12	58.6%
281		29	5	82.8%	29	5	82.8%	29	3	89.7%	29	3	89.7%
283		29	1	96.6%	29	1	96.6%	29	4	86.2%	29	4	86.2%
284		29	2	93.1%	29	2	93.1%	29	3	89.7%	29	3	89.7%
290		29	5	82.8%	29	5	82.8%	28	11	60.7%	28	11	60.7%
291		29	16	44.8%	29	16	44.8%	29	7	75.9%	29	7	75.9%
300		28	1	96.4%	28	1	96.4%	28	7	75.0%	28	7	75.0%
301		29	0	100.0%	29	0	100.0%	29	4	86.2%	29	4	86.2%
302		29	1	96.6%	29	1	96.6%	29	8	72.4%	29	8	72.4%
305	26	29	1	96.6%	29	1	96.6%	29	11	62.1%	29	11	62.1%
306		29	0	100.0%	29	0	100.0%	29	9	69.0%	29	9	69.0%
307		29	1	96.6%	29	1	96.6%	29	10	65.5%	29	10	65.5%
311		29	1	96.6%	29	1	96.6%	29	4	86.2%	29	4	86.2%
316	17	29	0	100.0%	29	0	100.0%	29	8	72.4%	29	8	72.4%
318		29	1	96.6%	29	1	96.6%	29	11	62.1%	29	11	62.1%
319	86	29	0	100.0%	29	0	100.0%	28	21	25.0%	28	21	25.0%
329		21	1	95.2%	21	1	95.2%	21	1	95.2%	21	1	95.2%
330		25	0	100.0%	25	0	100.0%	24	1	95.8%	24	1	95.8%
331		29	2	93.1%	29	2	93.1%	27	1	96.3%	27	1	96.3%
332		29	3	89.7%	29	3	89.7%	29	1	96.6%	29	1	96.6%

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		29	1	96.6%	29	1	96.6%	29	1	96.6%	29	1	96.6%
335		29	5	82.8%	29	5	82.8%	29	3	89.7%	29	3	89.7%
336		28	0	100.0%	28	0	100.0%	28	1	96.4%	28	1	96.4%
337		28	1	96.4%	28	1	96.4%	28	1	96.4%	28	1	96.4%
338	193	29	4	86.2%	29	4	86.2%	29	9	69.0%	29	9	69.0%
339	Cncld	29	8	72.4%	29	8	72.4%	28	6	78.6%	28	6	78.6%
341		28	5	82.1%	28	5	82.1%	28	2	92.9%	28	2	92.9%
342	Cncld	29	4	86.2%	29	4	86.2%	28	3	89.3%	28	3	89.3%
364	No OS	29	1	96.6%	29	1	96.6%	29	8	72.4%	29	8	72.4%
365	42	29	1	96.6%	29	1	96.6%	29	11	62.1%	29	11	62.1%
370		29	0	100.0%	29	0	100.0%	29	3	89.7%	29	3	89.7%
371		29	0	100.0%	29	0	100.0%	29	0	100.0%	29	0	100.0%
380		29	1	96.6%	29	1	96.6%	29	9	69.0%	29	9	69.0%
381		29	0	100.0%	29	0	100.0%	29	6	79.3%	29	6	79.3%
382	49	29	2	93.1%	29	2	93.1%	29	7	75.9%	29	7	75.9%
383	22	29	0	100.0%	29	0	100.0%	29	12	58.6%	29	12	58.6%
390		28	5	82.1%	28	5	82.1%	28	8	71.4%	28	8	71.4%
391		29	2	93.1%	29	2	93.1%	29	6	79.3%	29	6	79.3%
392	115	29	1	96.6%	29	1	96.6%	29	23	20.7%	29	23	20.7%
393	29	28	4	85.7%	28	4	85.7%	28	18	35.7%	28	18	35.7%
417		21	5	76.2%	21	5	76.2%	20	6	70.0%	20	6	70.0%
425		21	0	100.0%	21	0	100.0%	21	3	85.7%	21	3	85.7%
448		26	11	57.7%	26	11	57.7%	26	7	73.1%	26	7	73.1%
449		26	1	96.2%	26	1	96.2%	26	3	88.5%	26	3	88.5%
470		21	3	85.7%	21	3	85.7%	21	8	61.9%	21	8	61.9%
471	16	21	6	71.4%	21	6	71.4%	21	6	71.4%	21	6	71.4%
473		21	2	90.5%	21	2	90.5%	21	0	100.0%	21	0	100.0%
474		21	7	66.7%	21	7	66.7%	20	8	60.0%	20	8	60.0%
475		21	0	100.0%	21	0	100.0%	21	2	90.5%	21	2	90.5%
478		21	2	90.5%	21	2	90.5%	21	1	95.2%	21	1	95.2%
479		21	3	85.7%	21	3	85.7%	20	7	65.0%	20	7	65.0%
486		21	3	85.7%	21	3	85.7%	20	3	85.0%	20	3	85.0%
494		22	3	86.4%	22	3	86.4%	21	5	76.2%	21	5	76.2%
495		21	0	100.0%	21	0	100.0%	21	1	95.2%	21	1	95.2%
500		29	2	93.1%	29	2	93.1%	29	5	82.8%	29	5	82.8%
502	24	29	1	96.6%	29	1	96.6%	29	5	82.8%	29	5	82.8%
503		29	6	79.3%	29	6	79.3%	29	13	55.2%	29	13	55.2%
504	68	27	1	96.3%	27	1	96.3%	27	12	55.6%	27	12	55.6%
505	42	29	1	96.6%	29	1	96.6%	29	6	79.3%	29	6	79.3%
506		29	2	93.1%	29	2	93.1%	28	6	78.6%	28	6	78.6%
507	43	29	3	89.7%	29	3	89.7%	27	10	63.0%	27	10	63.0%
508		29	3	89.7%	29	3	89.7%	29	11	62.1%	29	11	62.1%

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
509	20	29	0	100.0%	29	0	100.0%	29	13	55.2%	29	13	55.2%
511		29	1	96.6%	29	1	96.6%	29	4	86.2%	29	4	86.2%
516	23	27	4	85.2%	27	4	85.2%	26	16	38.5%	26	16	38.5%
517		29	2	93.1%	29	2	93.1%	29	12	58.6%	29	12	58.6%
518		29	3	89.7%	29	3	89.7%	28	12	57.1%	28	12	57.1%
519		27	0	100.0%	27	0	100.0%	27	4	85.2%	27	4	85.2%
520		21	0	100.0%	21	0	100.0%	21	0	100.0%	21	0	100.0%
521	21	21	1	95.2%	21	1	95.2%	19	3	84.2%	19	3	84.2%
522	59	21	6	71.4%	21	6	71.4%	21	2	90.5%	21	2	90.5%
523		21	3	85.7%	21	3	85.7%	20	5	75.0%	20	5	75.0%
524		21	3	85.7%	21	3	85.7%	20	3	85.0%	20	3	85.0%
525		21	3	85.7%	21	3	85.7%	19	1	94.7%	19	1	94.7%
526		21	7	66.7%	21	7	66.7%	19	2	89.5%	19	2	89.5%
527	26	21	1	95.2%	21	1	95.2%	21	6	71.4%	21	6	71.4%
528	23	21	2	90.5%	21	2	90.5%	21	7	66.7%	21	7	66.7%
529		21	2	90.5%	21	2	90.5%	21	9	57.1%	21	9	57.1%
530		21	4	81.0%	21	4	81.0%	21	5	76.2%	21	5	76.2%
531	Cncld	21	1	95.2%	21	1	95.2%	20	2	90.0%	20	2	90.0%
532	Cncld	21	8	61.9%	21	8	61.9%	20	1	95.0%	20	1	95.0%
534		21	4	81.0%	21	4	81.0%	21	0	100.0%	21	0	100.0%
535	Cncld	21	0	100.0%	21	0	100.0%	20	2	90.0%	20	2	90.0%
536	23	21	8	61.9%	21	8	61.9%	21	1	95.2%	21	1	95.2%
537		20	1	95.0%	20	1	95.0%	19	1	94.7%	19	1	94.7%
538		21	2	90.5%	21	2	90.5%	21	1	95.2%	21	1	95.2%
539		21	5	76.2%	21	5	76.2%	21	8	61.9%	21	8	61.9%
540		20	3	85.0%	20	3	85.0%	19	0	100.0%	19	0	100.0%
541		21	2	90.5%	21	2	90.5%	21	3	85.7%	21	3	85.7%
542		21	4	81.0%	21	4	81.0%	20	2	90.0%	20	2	90.0%
543		21	4	81.0%	21	4	81.0%	21	10	52.4%	21	10	52.4%
544	31	21	5	76.2%	21	5	76.2%	21	6	71.4%	21	6	71.4%
547		21	2	90.5%	21	2	90.5%	21	5	76.2%	21	5	76.2%
548		21	1	95.2%	21	1	95.2%	21	1	95.2%	21	1	95.2%
549		21	2	90.5%	21	2	90.5%	20	2	90.0%	20	2	90.0%
550		21	3	85.7%	21	3	85.7%	21	4	81.0%	21	4	81.0%
551		21	2	90.5%	21	2	90.5%	21	4	81.0%	21	4	81.0%
562		27	2	92.6%	27	2	92.6%	27	14	48.1%	27	14	48.1%
564		27	0	100.0%	27	0	100.0%	27	15	44.4%	27	15	44.4%
566		27	1	96.3%	27	1	96.3%	25	12	52.0%	25	12	52.0%
567		27	4	85.2%	27	4	85.2%	26	7	73.1%	26	7	73.1%
572		24	8	66.7%	24	8	66.7%	22	14	36.4%	22	14	36.4%
573		27	2	92.6%	27	2	92.6%	27	12	55.6%	27	12	55.6%
579	32	24	2	91.7%	24	2	91.7%	23	13	43.5%	23	13	43.5%

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
580		27	2	92.6%	27	2	92.6%	26	12	53.8%	26	12	53.8%
581	55	27	11	59.3%	27	11	59.3%	25	18	28.0%	25	18	28.0%
584		27	3	88.9%	27	3	88.9%	25	19	24.0%	25	19	24.0%
587		26	6	76.9%	26	6	76.9%	24	15	37.5%	24	15	37.5%
588	Cncld	24	4	83.3%	24	4	83.3%	22	12	45.5%	22	12	45.5%
591		27	5	81.5%	27	5	81.5%	27	17	37.0%	27	17	37.0%
593		22	9	59.1%	22	9	59.1%	19	7	63.2%	19	7	63.2%
595		23	11	52.2%	23	11	52.2%	23	16	30.4%	23	16	30.4%
600		27	1	96.3%	27	1	96.3%	27	3	88.9%	27	3	88.9%
601		21	9	57.1%	21	9	57.1%	21	4	81.0%	21	4	81.0%
605		21	10	52.4%	21	10	52.4%	20	1	95.0%	20	1	95.0%
607		27	1	96.3%	27	1	96.3%	27	1	96.3%	27	1	96.3%
609		21	2	90.5%	21	2	90.5%	21	0	100.0%	21	0	100.0%
622		19	2	89.5%	19	2	89.5%	19	1	94.7%	19	1	94.7%
626		27	5	81.5%	27	5	81.5%	27	5	81.5%	27	5	81.5%
640		21	1	95.2%	21	1	95.2%	21	4	81.0%	21	4	81.0%
641		21	4	81.0%	21	4	81.0%	21	2	90.5%	21	2	90.5%
642		21	1	95.2%	21	1	95.2%	21	2	90.5%	21	2	90.5%
643		27	7	74.1%	27	7	74.1%	27	3	88.9%	27	3	88.9%
644		21	2	90.5%	21	2	90.5%	21	6	71.4%	21	6	71.4%
645		27	8	70.4%	27	8	70.4%	27	4	85.2%	27	4	85.2%
646		21	5	76.2%	21	5	76.2%	21	2	90.5%	21	2	90.5%
647		26	3	88.5%	26	3	88.5%	26	1	96.2%	26	1	96.2%
648		21	0	100.0%	21	0	100.0%	21	1	95.2%	21	1	95.2%
649		27	2	92.6%	27	2	92.6%	27	4	85.2%	27	4	85.2%
650		27	4	85.2%	27	4	85.2%	27	2	92.6%	27	2	92.6%
651		21	0	100.0%	21	0	100.0%	21	4	81.0%	21	4	81.0%
652		27	2	92.6%	27	2	92.6%	27	1	96.3%	27	1	96.3%
653		20	6	70.0%	20	6	70.0%	20	2	90.0%	20	2	90.0%
654		20	4	80.0%	20	4	80.0%	20	3	85.0%	20	3	85.0%
655		27	3	88.9%	27	3	88.9%	27	2	92.6%	27	2	92.6%
656		27	4	85.2%	27	4	85.2%	27	5	81.5%	27	5	81.5%
657		21	8	61.9%	21	8	61.9%	21	1	95.2%	21	1	95.2%
658		26	1	96.2%	26	1	96.2%	26	1	96.2%	26	1	96.2%
680	25	21	3	85.7%	21	3	85.7%	21	1	95.2%	21	1	95.2%
681		21	0	100.0%	21	0	100.0%	20	9	55.0%	20	9	55.0%
682		21	3	85.7%	21	3	85.7%	21	3	85.7%	21	3	85.7%
683		21	0	100.0%	21	0	100.0%	21	15	28.6%	21	15	28.6%
684		21	2	90.5%	21	2	90.5%	21	8	61.9%	21	8	61.9%
685		21	3	85.7%	21	3	85.7%	21	7	66.7%	21	7	66.7%
686		21	1	95.2%	21	1	95.2%	21	9	57.1%	21	9	57.1%
687		21	5	76.2%	21	5	76.2%	21	7	66.7%	21	7	66.7%

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
688		21	0	100.0%	21	0	100.0%	21	5	76.2%	21	5	76.2%
701		29	4	86.2%	29	4	86.2%	29	7	75.9%	29	7	75.9%
702		29	2	93.1%	29	2	93.1%	29	13	55.2%	29	13	55.2%
703		29	9	69.0%	29	9	69.0%	29	6	79.3%	29	6	79.3%
704		29	6	79.3%	29	6	79.3%	29	4	86.2%	29	4	86.2%
710		29	6	79.3%	29	6	79.3%	29	7	75.9%	29	7	75.9%
711	30	29	5	82.8%	29	5	82.8%	24	4	83.3%	24	4	83.3%
712		29	10	65.5%	29	10	65.5%	29	12	58.6%	29	12	58.6%
713		26	9	65.4%	26	9	65.4%	21	6	71.4%	21	6	71.4%
714		29	15	48.3%	29	15	48.3%	28	15	46.4%	28	15	46.4%
715	42	29	6	79.3%	29	6	79.3%	28	15	46.4%	28	15	46.4%
716	78	28	15	46.4%	28	15	46.4%	27	7	74.1%	27	7	74.1%
717		29	13	55.2%	29	13	55.2%	26	11	57.7%	26	11	57.7%
718		29	18	37.9%	29	18	37.9%	29	12	58.6%	29	12	58.6%
719		29	6	79.3%	29	6	79.3%	29	7	75.9%	29	7	75.9%
757	44	26	2	92.3%	26	2	92.3%	26	14	46.2%	26	14	46.2%
761		27	0	100.0%	27	0	100.0%	27	11	59.3%	27	11	59.3%
765	43	27	0	100.0%	27	0	100.0%	27	17	37.0%	27	17	37.0%
769		27	2	92.6%	27	2	92.6%	27	19	29.6%	27	19	29.6%
770	59	27	3	88.9%	27	3	88.9%	26	17	34.6%	26	17	34.6%
774	115	27	12	55.6%	27	12	55.6%	26	22	15.4%	26	22	15.4%
777		27	1	96.3%	27	1	96.3%	26	18	30.8%	26	18	30.8%
782	29	27	19	29.6%	27	19	29.6%	26	18	30.8%	26	18	30.8%
785	28	27	15	44.4%	27	15	44.4%	27	17	37.0%	27	17	37.0%
786		27	8	70.4%	27	8	70.4%	23	13	43.5%	23	13	43.5%
790	35	27	1	96.3%	27	1	96.3%	27	16	40.7%	27	16	40.7%
794		27	12	55.6%	27	12	55.6%	27	14	48.1%	27	14	48.1%
821	34	28	2	92.9%	28	2	92.9%	28	23	17.9%	28	23	17.9%
822	17	28	2	92.9%	28	2	92.9%	28	24	14.3%	28	24	14.3%
1082		14	2	85.7%	14	2	85.7%	14	3	78.6%	14	3	78.6%
1087		14	1	92.9%	14	1	92.9%	13	1	92.3%	13	1	92.3%
1088		14	2	85.7%	14	2	85.7%	14	3	78.6%	14	3	78.6%
1099	27	14	0	100.0%	14	0	100.0%	14	5	64.3%	14	5	64.3%
1103		14	7	50.0%	14	7	50.0%	14	2	85.7%	14	2	85.7%
1107		14	5	64.3%	14	5	64.3%	14	2	85.7%	14	2	85.7%
1109		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
1111		14	2	85.7%	14	2	85.7%	14	0	100.0%	14	0	100.0%
1116		14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%
1118		14	2	85.7%	14	2	85.7%	14	0	100.0%	14	0	100.0%
1124	64	12	2	83.3%	12	2	83.3%	12	5	58.3%	12	5	58.3%
1126	18	14	0	100.0%	14	0	100.0%	14	4	71.4%	14	4	71.4%
1127		14	3	78.6%	14	3	78.6%	14	1	92.9%	14	1	92.9%

Amtrak On Time Performance

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1128		14	2	85.7%	14	2	85.7%	13	1	92.3%	13	1	92.3%
1129		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
1135		14	2	85.7%	14	2	85.7%	14	11	21.4%	14	11	21.4%
1138	23	13	1	92.3%	13	1	92.3%	13	2	84.6%	13	2	84.6%
1140		14	4	71.4%	14	4	71.4%	14	1	92.9%	14	1	92.9%
1142	45	14	3	78.6%	14	3	78.6%	14	4	71.4%	14	4	71.4%
1143		14	0	100.0%	14	0	100.0%	14	5	64.3%	14	5	64.3%
1144	36	14	11	21.4%	14	11	21.4%	14	4	71.4%	14	4	71.4%
1146		14	3	78.6%	14	3	78.6%	14	1	92.9%	14	1	92.9%
1147		14	0	100.0%	14	0	100.0%	14	3	78.6%	14	3	78.6%
1150		14	9	35.7%	14	9	35.7%	14	2	85.7%	14	2	85.7%
1151	40	14	4	71.4%	14	4	71.4%	14	8	42.9%	14	8	42.9%
1152		14	2	85.7%	14	2	85.7%	14	3	78.6%	14	3	78.6%
1153		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
1155	31	13	2	84.6%	13	2	84.6%	13	5	61.5%	13	5	61.5%
1156	24	11	2	81.8%	11	2	81.8%	11	8	27.3%	11	8	27.3%
1160		14	0	100.0%	14	0	100.0%	14	7	50.0%	14	7	50.0%
1161		14	0	100.0%	14	0	100.0%	14	10	28.6%	14	10	28.6%
1162	51	14	0	100.0%	14	0	100.0%	14	7	50.0%	14	7	50.0%
1163	46	14	1	92.9%	14	1	92.9%	14	10	28.6%	14	10	28.6%
1164		13	1	92.3%	13	1	92.3%	13	4	69.2%	13	4	69.2%
1165		14	0	100.0%	14	0	100.0%	14	7	50.0%	14	7	50.0%
1167		14	4	71.4%	14	4	71.4%	14	5	64.3%	14	5	64.3%
1168		14	4	71.4%	14	4	71.4%	14	4	71.4%	14	4	71.4%
1169		13	3	76.9%	13	3	76.9%	12	2	83.3%	12	2	83.3%
1194		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
1195		13	0	100.0%	13	0	100.0%	13	1	92.3%	13	1	92.3%
1333	30	29	3	89.7%	29	3	89.7%	29	9	69.0%	29	9	69.0%
1340		29	0	100.0%	29	0	100.0%	29	4	86.2%	29	4	86.2%
1689		14	0	100.0%	14	0	100.0%	13	3	76.9%	13	3	76.9%
2101		14	1	92.9%	14	1	92.9%	14	1	92.9%	14	1	92.9%
2103		21	1	95.2%	21	1	95.2%	21	2	90.5%	21	2	90.5%
2105		21	1	95.2%	21	1	95.2%	21	1	95.2%	21	1	95.2%
2106		14	0	100.0%	14	0	100.0%	14	2	85.7%	14	2	85.7%
2114		14	3	78.6%	14	3	78.6%	14	3	78.6%	14	3	78.6%
2115	122	21	0	100.0%	21	0	100.0%	20	3	85.0%	20	3	85.0%
2116		21	2	90.5%	21	2	90.5%	21	0	100.0%	21	0	100.0%
2118		21	2	90.5%	21	2	90.5%	20	3	85.0%	20	3	85.0%
2120		21	3	85.7%	21	3	85.7%	21	3	85.7%	21	3	85.7%
2122		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
2123		21	2	90.5%	21	2	90.5%	21	2	90.5%	21	2	90.5%
2133		14	0	100.0%	14	0	100.0%	14	1	92.9%	14	1	92.9%

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak On Time Performance

Trains Arriving Through: 10/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2148		14	1	92.9%	14	1	92.9%	13	2	84.6%	13	2	84.6%
2149	27	14	2	85.7%	14	2	85.7%	14	13	7.1%	14	13	7.1%
2150		21	0	100.0%	21	0	100.0%	20	11	45.0%	20	11	45.0%
2151	40	21	0	100.0%	21	0	100.0%	21	13	38.1%	21	13	38.1%
2152		21	1	95.2%	21	1	95.2%	21	2	90.5%	21	2	90.5%
2155		21	1	95.2%	21	1	95.2%	20	2	90.0%	20	2	90.0%

Amtrak Endpoint OTP Details

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2115	WAS	122	DCS	119	DCS	87	BAL-XNY	AM	Power switch failure, Milepost, 112.4, ., 21 switch out of correspondence at Grove
2149	WAS	27	DMW	15	DMW	15	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2151	WAS	40	OTH	20	POL	19	NWK-XCY	AM	Removal of passenger by police, UNSCHEDULED METROPARK STOP F/PSGR PASSED OUT ON TRAIN
66	BOS	28	SVS	13	SVS	13	NHV-NHV	AM	Planned Switch, adding engine to consist at NHV
471	NHV	16	ITI	15	ITI	15	HFD-HFD	AM	Late departure at initial terminal due to late arrival of inbound equipment, 426, Late turn
1099	NPN	27	TRS	30	TRS	30	RVR-RVM	CS	Vehicle on track ahead Other, SRN 1.2
1124	PHL	64	DCS	43	DCS	43	XNY-BWI	AM	Power switch failure, Milepost, 112.4, ., 21 switch out of correspondence at Grove
1126	NYP	18	SMW	9	SMW	9	NWK-NYP	AM	Scheduled in track usage program, Other, HUDSON, HELD A/C SINGLE TRACKING SWIFT-PORTAL DUE TO PORTAL OUTAGE
1138	NYP	23	DCS	33	DCS	20	BWI-BWI	AM	T.O.L, Milepost, 95.9, ., held for disposition a/c TOL over the 13 switch at Charles
1142	NYP	45	DCS	59	DCS	59	BWI-BAL	AM	T.O.L, Milepost, 95.9, ., TOL over the 13 switch at Charles
1144	NYP	36	SVS	42	SVS	42	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE
1151	RNK	40	SVS	29	SVS	19	PHL-PHL	AM	Planned Switch, engine swap
1155	NFK	31	FTI	44	FTI	27	ALX-ALX	CS	Cross Traffic 409/301, Other, ALX
1156	NYP	24	FTI	23	FTI	23	BCV-ALX	CS	Meet M415, Milepost, 104.3, 104.3
1162	BOS	51	ADA	18	SMW	12	NLC-XGX	AM	Diversions around M/W work, Control Point, xgx, Held at Groton for 1163 a/c run around
1163	WAS	46	OTH	17	PTI	9	BAL-BAL	AM	Cross over or go around, 2155, Milepost, 95.7, ., held for 2155 ahead then followed
52	LOR	27	FTI	61	FTI	38	XOU-XFL	CS	Meet M809-26, IO37, Control Point, Pinopolis, Control Point, N •Lane
53	SFA	80	FTI	84	FTI	35	XFL-XOU	CS	Meet M410-28, Control Point, west branch
79	CLT	73	PTI	69	PTI	34	XVG-ALX	CS	Follow 89, Other, slaters
19	NOL	76	FTI	130	FTI	55	GNS-ATL	NS	Follow NS203, Milepost, 626.3, 633.3
680	BON	25	SYS	25	SYS	25	BRK-BRK	CS	PTC problem or failure (cause unknown)

Amtrak Endpoint OTP Details

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
63	TWO	64	FTI	20	PTI	19	ROM-SYR	CS	Meet 48, Control Point, 270
233	ALB	19	DMW	19	DMW	19	RHI-HUD	AM	Held for or routed around MW work or equipment Single track conditions, hold for southbound 284, Control Point, 114
243	ALB	73	ENG	83	ENG	61	NYP-NYP	AM	Traction motor, 715|DX|DM, DELAYED DEPARTURE FROM NYP ACCT MECHANICAL ISSUES ON MOTOR 715 IN SSYD.
245	ALB	37	ITI	48	ITI	48	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 68
280	NYP	91	FTI	122	FTI	41	BFX-BUF	CS	Stop signal cp 437. Track 1 oos cp 437-cp 433 due to work area/track work. I150 stopped on track 2 at cp 434 for recrew. 280 waited for I150 to recrew and clear cp 437. Control Point, cp 437, I150
71	CLT	29	DSR	10	SYS	8	RGH-RGH	NS	PTC problem or failure (cause unknown) Other, yard
73	CLT	21	PTI	15	PTI	15	CYN-DNC	NS	Meet #am80, Control Point, D and S JCT
76	RGH	16	PTI	10	PTI	10	KAN-GRO	NS	Meet #Amt77, Control Point, Spencer
90	NYP	60	DCS	61	DCS	32	NCR-BWI	AM	Power switch failure, Milepost, 112.4, ., 21 switch out of correspondence at Grove
5	EMY	55	FTI	193	FTI	103	FMG-XID	BN	Disabled freight train Freight train in Barr, BN6158, Siding, Hudson
521	SJC	21	DCS	24	DCS	13	MTZ-RIC	UP	CTC system failure Vandalism due to cut wires, Control Point, RV014
522	SAC	59	ENG	51	ENG	51	OKJ-OKJ	UP	Traction motor Loco alarm, wheel slip. TM and Tasi Sup contacted. Tasi @OKJ worked on and fixed the issue., C2010
527	SJC	26	DCS	20	DCS	20	RIC-BKY	UP	Power switch failure Take switches into hand. Flagging with 6-83 authority m1 to M1 s, Control Point, stege
528	SAC	23	MBO	30	MBO	30	MTZ-SUI	UP	For maritime traffic Control Point, RV033
531	OKJ	Trn Cancelled	RTE	2	RTE	2	FFV-SUI	UP	Crossover(s) due to N.A.R. 2 to 1 , Control Point, Tolenas
532	SAC	Trn Cancelled							
535	OKJ	Trn Cancelled	SYS	53	SYS	53	SUI-MTZ	UP	Blocked by or assisting another, disabled Amtrak train Hooked up to Amt 531 to take back to OAK, Control Point, Marsh
536	SAC	23	OTH	2	OTH	2	MTZ-SUI	UP	Lost time - N.A.R.

Amtrak Endpoint OTP Details

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
544	SAC	31	INJ	39	INJ	39	RIC-MTZ	UP	Injured or sick passenger Intoxicated passenger, has to call EMS.
51	CHI	58	DSR	43	PTI	22	CVS-STA	BB	Meet amtk 50, Control Point, crozet
502	SEA	24	DSR	12	FTI	10	VAN-KEL	BN	Follow BN 9141, Milepost, 136.5, 133.5
504	SEA	68	RTE	65	RTE	54	VAN-KEL	BN	Dispatcher hold Movement planner botched a bunch of trains., Control Point, Interstate South
505	PDX	42	DCS	46	DCS	46	KEL-VAN	BN	Restrictive signal(s) from known wayside signal failure Stop, Control Point, Longview Jct S.
507	EUG	43	ENG	36	ENG	36	SEA-SEA	BN	Windshield wipers inoperable Switched Trainset for train 500, but that train had more mechanical problems. Then switched back to original equipment with bad cab car. Was able to get wipers working for cab car., 90340
509	PDX	20	DCS	15	DCS	8	VAN-PDX	BN	Restrictive signal(s) from unknown cause Approach medium, Approach medium , Approach Restricting, Control Point, E. St. Johns, Control Point, W. St. Johns, Control Point, Willamette Br.
516	VAC	23	DSR	22	PTI	10	STW-MVW	BN	Meet AMTK 517, Siding, Logen
58	CHI	75	DSR	68	FTI	30	MAT-CHM	CC	Follow up7864, Milepost w/Letters, may, Tuscola
59	NOL	44	DSR	92	FTI	21	FTN-NBN	CC	Meet In behind 432, let 431 pass, then back out, A432, A431, Control Point, North Rives
11	LAX	No OS Rpt	DCS	167	DCS	71	SLO-SBA	UP	Signal suspension Control Point, CPCO 295, Control Point, CPCO 356
14	SEA	198	DCS	138	SYS	91	SLO-SLO	UP	Waiting for Amtrak to make a decision regarding the wash out at Elkhorn Slew.
8	CHI	60	FTI	104	ENG	51	RDW-RDW	CP	HEP 335
28	SPK	18	FTI	46	FTI	38	PSC-XPW	BN	Follow Milepost, 123.9, 72.5, bnsf 6217, bnsf 5777
821	FTW	34	DSR	28	DSR	23	GLE-FTW	BN	Per bulletin Milepost, 407.9, 407.1, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 384.2, 383.4, 25, M, Milepost, 380.8, 379.5, 40, M, Milepost, 376.2, 376, 30, M, Milepost, 371.6, 371.4, 25, M, Milepost, 355.9, 355.5, 50, 1, Milepost, 355.4, 351.2, 25, 1, Milepost, 351.1, 350.7, 50, 1, Milepost, 35

Amtrak Endpoint OTP Details

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	17	DSR	37	DSR	33	FTW-GLE	BN	Per bulletin Milepost, 347.5, 347.9, 25, m1, Milepost, 349.6, 350.1, 25, m1, Milepost, 351.2, 351.6, 25, main1, Milepost, 354.6, 355.4, 25, m1, Milepost, 371.4, 371.6, 25, main, Milepost, 376.0, 376.2, 30, main, Milepost, 383.4, 384.2, 25, main, Milepost, 379.5, 380.8, 40, main, Milepost, 389.0, 389
338	CHI	193	ENG	180	ENG	92	SVT-XRO	CP	Unrecoverable penalty (PCS) Known problem on AMTK 63. Called CNOC, instructed on how to resolve the problem. Recovered the brakes on 63 and needed to go back to 4603 to clear a fault on it. Got moving again and happened again at MP 38.0. Shoved all the way into CUS, 63
339	MKE	Trn Cancelled							
342	CHI	Trn Cancelled							
364	PTH	No OS Rpt	FTI	34	FTI	20	DRD-FLN	CC	Follow cn, Control Point, west flint
365	CHI	42	FTI	59	FTI	23	LNS-BTL	CC	Follow CN149, Control Point, Haydon
579	LAX	32	DCS	20	DCS	16	OSD-X98	SC	Flagging Instructions. Control Point, Songs
581	LAX	55	DCS	25	ITI	23	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 770
588	SAN	Trn Cancelled							
757	GTA	44	PTI	32	PTI	32	VEC-CPN	UP	Meet Waited for delayed AMTK 770, AMTK 770, Control Point, CO 385
765	GTA	43	PTI	41	PTI	27	CML-CML	UP	Meet amtk, Other, cml station
770	SAN	59	CTI	46	ENG	27	GTA-GTA	UP	Air / Brake Angle cock, main Rez in wrong position between cars one and two, 345
774	SAN	115	PTI	52	PTI	27	SBA-CPN	UP	Meet AMTK 761, Control Point, CO 369
782	SAN	29	PTI	55	PTI	25	SNC-SNP	SC	Meet 785, Control Point, Serra
785	GTA	28	WTR	24	WTR	20	OSD-X98	SN	High tide Control Point, songs
790	SAN	35	CTI	21	PTI	16	CPN-VEC	UP	Meet 777, Control Point, South Seacliff
711	OKJ	30	TEN	16	TEN	16	RIC-RIC	UP	PTC- IETMS recycle breaker to clear fault PTC lost communication. Had to recycle breaker and log back in, C2014
715	OKJ	42	PTI	49	PTI	17	ACA-XPR	BN	Meet Had to shuffle at e. Pittsburg for train 716 to pass, amtrak 716, Siding, e. pittsburg

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/29/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
716	BFD	78	TEN	61	TEN	61	OKJ-OKJ	UP	Traction motor Engine change of CDTX 2014 to CDTX 2003 at OMF, C2014
305	STL	26	FTI	23	FTI	18	BNL-BNL	UP	Meet Freight, Siding, Normal
382	CHI	49	DCS	28	DCS	28	PLO-NPV	BN	Power switch failure 3A switch, Control Point, Aurora
383	QCY	22	FTI	22	FTI	9	PLO-MDT	BN	Meet Other, electrics, bnsf 5868
392	CHI	115	DSR	3	DSR	3	CDL-DQN	CC	Per bulletin Milepost, 300.2, 199.8, 25, m
393	CDL	29	PTI	20	PTI	20	CHM-MAT	CC	Meet AM 392, Control Point, N Tolono
316	STL	17	FTI	24	FTI	8	SED-JEF	UP	Meet UP 1234, Siding, Shell
319	KCY	86	FTI	89	FTI	58	WAR-LEE	UP	Follow Milepost w/Letters, war, lee, up 2695
1333	MSP	30	FTI	34	FTI	34	XH8-MSP	CP	Follow Mixed, Control Point, 3998, CPKC 2-249

Amtrak Initial Terminal Details

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/29/2026

Terminal	Train	Date	Late	Delay	Cause
BON	687	10/29	2	2	Restrictive signal(s) from known wayside signal failure Issues with signals, Stop signal, Control Point, tower a
BOS	1167	10/29	10	10	Late departure at initial terminal due to late arrival of inbound equipment, 1162, late turn of AM1162
BRK	680	10/29	25	25	PTC problem or failure (cause unknown)
BTN	290	10/29	1		
HFD	471	10/29	15	15	Late departure at initial terminal due to late arrival of inbound equipment, 426, Late turn
NYP	63	10/29	2	2	Cross Traffic, NJT, NJ8621, Other, NYP
NYP	97	10/29	39	39	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C LATE SERVICING
NYP	243	10/29	61	61	Traction motor, 715|DX|DM, DELAYED DEPARTURE FROM NYP ACCT MECHANICAL ISSUES ON MOTOR 715 IN SSYD.
NYP	1103	10/29	6	6	Late departure at initial terminal due to late arrival of inbound equipment, 1144, LATE TURN OFF AM1144
NYP	1111	10/29	2	2	Passenger and/or baggage, LOADING
NYP	1127	10/29	2	2	Cross Traffic, NJT, NJ3508, Other, NYP
NYP	1129	10/29	2	3	Passenger and/or baggage, BOARDING
NYP	2155	10/29	2	2	Other electrical failure, 2145|NG|NP, HELD IN STATION A/C MECHANCIAL ONBOARD TO DE-PREPARE TRAIN DUE TO MECHANICAL ISSUES
PHL	601	10/29	15	15	Planned set out / pick out of locomotives, cars or section of train, late out of yard a/c equipment issues
PHL	605	10/29	1	1	Passenger and/or baggage
PHL	645	10/29	2	2	PTC - Stop Bypass Permission Required, Control Point, PHL
PHL	1144	10/29	42	42	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE
PHL	1150	10/29	3	3	PTC - Stop Bypass Permission Required, Control Point, ., multiple stop bypasses
PHL	1151	10/29	29	19	Planned Switch, engine swap
PHL	1151	10/29	29	10	Planned Switch, engine swap
RGH	71	10/29	8	8	PTC problem or failure (cause unknown) Other, yard
RNK	66	10/29	18	18	Held for or routed around MW work or equipment Control Point, 8 1/2
RNK	1156	10/29	13	13	Other electrical failure 44
WAS	56	10/29	3	3	PTC problem or failure (cause unknown), ENGR IDENTIFIED & RESOLVED ACCESS ISSUE
WAS	1082	10/29	3	3	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE

Amtrak Initial Terminal Details

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/29/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	1168	10/29	3	3	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE
CHI	339	10/29	(Trn Cxld)		Engine Issue
MKE	342	10/29	(Trn Cxld)		Engine Issue
BFD	711	10/29	3	3	Door C8305, B-end of cab car is locked out but when doors are train lined toward the rear, door triggers 'open', does not close via train line; has to be closed from outside physical door. *Troubleshooted @MCD when doors are CLOSED cab door opens
BFD	717	10/29	2	2	Copy authority / restriction Stop signal to copy a Procedure 2 crossing warning., Control Point, Amtrak Lead
GTA	770	10/29	42	27	Air / Brake Angle cock, main Rez in wrong position between cars one and two, 345
GTA	770	10/29	42	15	Lake GTB's from Metrolink
GTA	774	10/29	48		
LAX	572	10/29	8	8	Miss communication with extra board engineer in crew base from other crew. Thought we were taking late equipment over. Milepost, 0.0, 0.0
OKJ	522	10/29	51	51	Traction motor Loco alarm, wheel slip. TM and Tasi Sup contacted. Tasi @OKJ worked on and fixed the issue., C2010
OKJ	532	10/29	(Trn Cxld)		Third Party Engine Failure
OKJ	536	10/29	(Trn Cxld)		Third Party Cab Car Failure
OKJ	714	10/29	4	4	Wait for station track Waited for train 711 to come into the OMF. So we could head to OKJ, 711, Other, oakland maintenance facility
OKJ	716	10/29	61	61	Traction motor Engine change of CDTX 2014 to CDTX 2003 at OMF, C2014
SAN	579	10/29	2	2	PTC problem or failure (cause unknown) Milepost, 267.0, 267.0
SAN	581	10/29	23	23	Late departure at initial terminal due to late arrival of inbound equipment 770
SAN	587	10/29	13	13	Late departure at initial terminal due to late arrival of inbound equipment 774
SEA	507	10/29	36	36	Windshield wipers inoperable Switched Trainset for train 500, but that train had more mechanical problems. Then switched back to original equipment with bad cab car. Was able to get wipers working for cab car., 90340

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.3	99.14	342	1
CDOT	95.0	79.2	87.4	92.4	24	5
MARC	95.0	77.6	87.0	90.2	58	13
SEPTA	95.0	87.7	89.0	93.7	219	27
NJT-NED	95.0	86.6	91.5	88.6	202	27
NJT-SED	95.0	100.0	99.0	97.2	24	0

Operating Highlights

Train 243(29) New York, NY - Engine Failure

29OCT26: Train 243(29) operating with engine 715, 9705, and 213 customers to board was delayed departing New York Penn Station due to engine issues on inbound engine 715. Train 68(29) was utilized as the turn while mechanical worked on the original set of equipment and turned it for train 245(29).

Train	Delay	Comment
243(29)	1'01"	

PW Line - North of New Carrollton, MD - Carroll Interlocking

29OCT26: The 32 switch at Carroll Interlocking milepost 127.0 located north of New Carrollton, MD was reported out of correspondence causing single track conditions. The issue was able to be resolved causing minimal delay to traffic.

Train	Delay	Comment
1163(29)	09"	
2155(29)	13"	
9449(29)	35"	
9446(29)	24"	

Train 1099(29) South of Richmond, VA - Trespasser Incident

29OCT26: Train 1099(29) operating with engine 333 and 180 customers onboard was delayed 1 mile south of Richmond, VA on the CSX Bellwood subdivision holding at milepost 3.6 for a vehicle on the tracks ahead at milepost 3.35 crossing ID 623518E. A tow truck and track inspector arrived on scene to remove the vehicle and inspect the tracks for train traffic to proceed.

Train	Delay	Comment
1099(29)	30"	

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

PW Line - North of New Carrollton, MD - Grove Interlocking

29OCT26: It was reported that the 21 switch in Grove interlocking milepost 112.4 north of New Carrollton, MD was out of correspondence causing single track conditions. Train 2115(29) was delayed holding on 2 track for the maintainer to spike the switch while all other rail traffic proceeded on 3 track. Once the switch was spiked, all traffic received rule 241 to operate through until service was fully restored.

Train	Delay	Comment
2115(29)	1'27"	
90(29)	29"	
1129(29)	17"	
9642(29)	1'51"	
9544(29)	1'39"	

PW Line - South of Baltimore, MD - Charles Interlocking

29OCT26: At 6:10 p.m. a track occupancy light was reported over the 13 switch in Charles interlocking milepost 95.9 causing single track conditions. The track occupancy light was in place on 3 track from Baltimore Penn Station to south Charles interlocking. C&S was notified and sent personnel to the scene to resolve the issue.

Train	Delay	Comment
1138(29)	04"	
1142(29)	59"	
1138(29)	20"	
2115(29)	32"	
97(29)	44"	
9440(29)	30"	MARC
9536(29)	54"	MARC
9449(29)	13"	MARC
9438(29)	09"	

Washington Union Station - Commercial Power Outage - B&B Work Due to Defect

29OCT26: At approximately 2:25 PM, a water leak at Washington Union Station above the main commercial electrical supply caused a building power outage. The emergency generator started and subsequently failed, resulting in the loss of station lighting, passenger information displays, ticketing systems, kiosks, and the intercom. Emergency lighting and mobile public address systems were deployed, and station personnel manually directed customers. Portable lighting and security coverage were placed in low-light areas, and the food court was closed while the commissary and west loading dock remained operational. Some customers missed departures because boarding alerts, display boards, and overhead announcements were unavailable. Departing customers were proactively fare protected and directed to the Customer Care Center for rebooking, and additional cabs were arranged for missed connections in the Richmond and Raleigh districts. Inbound customers received outage and station-condition notices 15 minutes before arrival, and departing customers received similar notices 60 minutes before departure. Train operations continued normally, as radio, signals, overhead wire, switches, catenary power, and crew movements remained unaffected. The plumbing contractor isolated the leak, building engineers evaluated additional ceiling leakage in the ticketed passenger waiting room, and an electrical inspection was conducted after the contractor arrived. APD personnel, station security, and National Guard personnel supported operations in the food court and low-light areas.

At 8:13 p.m. all commercial power was restored to the station. At 8:53 p.m. all network services and business operations were restored allowing all critical systems to function normally.

WBS#: B.TR.100151.0862

27-FOI-00101 00000098043 "UNCLASSIFIED" 11/2/2026

Train 1156(29) Alexandria, VA - Freight Train Interference

29OCT26: Train 1156(29) operating with locomotive 44, 2 cars and 266 customers onboard was delayed at Alexandria Station for freight train interference meeting CSX M415. Once the freight was clear an open route was established and train 1156(29) was able to depart Alexandria.

Train	Delay	Comment
1156(29)	23"	

Train 89(29) North of Alexandria, VA - Engine Failure

29OCT26: Train 89(29) operating with locomotive 387, 7 cars and 181 customers onboard was delayed 2 miles north of Alexandria station due to engine radio failure on locomotive 387. The crew was unable to contact the CSX Maintenance of Way foreman to get permission into the out of service limits. The crew ultimately was able to contact the foreman via cell phone to gain permission and proceed. The crew stopped a second time at MP 53.7 when radio communication was lost a second time. Amtrak Mechanical was requested to meet the train at Richmond where a spare radio was placed on the train and Savannah Mechanical will repair upon arrival. Trains on the RF&P subdivision were delayed as a result of routing around train 89(29) in addition to trains 79(29), 1155(29) and 41(28) following train 89(29).

Train	Delay	Comment
89(29)	31"	WAS-ALX
79(29)	34"	
41(28)	20"	

Train 97(29) New York, NY - Servicing

29OCT26: Train 97(29) operating with locomotive 656, 11 cars and 215 customers was delayed at the initial terminal of New York due to a late release of equipment from the yard. Once the equipment was released the train was moved into the station where 215 customers were boarded and train 97(29) departed New York.

Train	Delay	Comment
97(29)	39"	

Train 48(28) West of Rochester, NY - Freight Train Interference

29OCT26: Train 48(28) operating with locomotives 114-108, 12 cars and 125 customers onboard was delayed 39 miles west of Rochester, NY at MP 409 on the CSX Buffalo Terminal subdivision due to freight train interference following M204-27 from MP 409 to CP 287 on the No. 2 track. At CP 287 train 48(28) was crossed over to the No. 1track and an open route was established to allow train 48(28) to proceed without further delay.

Train	Delay	Comment
48(28)	38"	

27-FOI-00101 0000009043 UNCLASSIFIED 11/2/2026

Train 1144(29) Philadelphia, PA - Initial Terminal Delay - Servicing

29OCT26: Train 1144(29) operating with locomotives 660-640, 10 cars and 513 customers onboard was delayed at the initial terminal of Philadelphia due to a late release of equipment from the yard. Once Mechanical completed their servicing and inspections the equipment was released to Transportation and the equipment was moved into the station. After the 513 customers boarded the train, train 1144(29) departed Philadelphia.

As a result of the late operation of train 1144(29) the turn of equipment resulted in an initial terminal delay to train 1103(29).

Train	Delay	Comment
1144(29)	42"	
1103(29)	06"	Initial terminal delay

Train 41(28) West of Connellsville, PA - Freight Train Interference

29OCT26: Train 41(28) operating with locomotives 374-171, 9 cars and 120 customers on board was delayed 4 miles west on Connellsville, PA at MP 274 on the CSX Pittsburg subdivision due to freight train interference with I016 and M416 at Bradford. Once an open route was established train 41(28) was able to proceed.

Train	Delay	Comment
41(28)	31"	

Train 1151(29) Philadelphia, PA - Engine Failure

29OCT26: Train 1151(29) operating with engine 621 and 95 customers was delayed departing Philadelphia, PA due to swapping engine 621 for engine 611 for mechanical defects. Once the equipment was released from Mechanical the train was placed in the station and the 95 customers were boarded and train 1151(29) departed.

Train	Delay	Comment
1151(29)	29"	

Maintenance of Way Highlights

Veltri Schedule Adjustments - 10/10/26 to 11/15/26 - Scheduled M/W Work

27.5OL.00101 0000009046 UNCLASSIFIED 11/3/2026

26OCT26: Due to the Veltri continuous outage on the New Haven to Boston main line from October 10,2026 to November 15,2026. The following service adjustments have been made:

Train 2155(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York.
Train 1169(12OCT-13NOV) will originate New York and will be cancelled between Boston - New York
Train 2255(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 169(7-15NOV) will originate New York and will be cancelled Boston- New York
Train 1152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 2152(12OCT-13NOV) will terminate New York and will be cancelled New York to Boston
Train 152(7-15NOV) will terminate New York and will be cancelled New York to Boston
Train 2252(7-15NOV) will terminate New York and be cancelled New York to Boston

Piedmont and Carolinian NS Track Work - 10/26-10/29 - 11/2-11/5 TWA 24-016

27-FOI-00101 08000009043 UNCLASSIFIED 11/2/2026

26AUG26: The NS / NC Interchange Subdivision between MP NC 0.6 and MP NC 31.6 for Rail Pick up and Switch Replacement occurring between 900A-ET and 600P-ET on Monday, October 26 to Thursday, October 29 and Monday, November 2 to Thursday, November 6. To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

· Train 72 (26Oct-29Oct, 2Nov-5Nov), which normally operates between CLT and RGH, will terminate at GRO.

· Train 74 (26Oct-27Oct, 2Nov-3Nov), which normally operates between CLT and RGH, will terminate at GRO.

· Train 74 (28Oct-29Oct, 4Nov-5Nov) will operate 10-minutes Earlier between CLT and BNC, and 8-minutes Earlier between DNC and RGH.

· Train 76 (26Oct-27Oct, 2Nov-3Nov) will operate 30-minutes Later between CLT and GRO, add a BNC stop at 7:21pm, and operate 34-minutes Later between DNC and RGH.

· Train 76 (28Oct-29Oct, 4Nov-5Nov) will operate 30-minutes Later between CLT and RGH, departing CLT at 5:35pm.

WESTBOUND

· Train 71 (26Oct-29Oct, 2Nov-5Nov) will operate 15-minutes Earlier, departing RGH at 6:15am.

· Train 73 (26Oct-29Oct, 2Nov-5Nov) will depart RGH 55-minutes Earlier, at 9:05am, and operate on an earlier schedule between RGH and CLT. See schedule grid below.

· Train 75 (26Oct-27Oct, 2Nov-3Nov), which normally operates between RGH and CLT, will originate at GRO, departing 14-minutes Later at 2:34pm.

· Train 75 (28Oct-29Oct, 4Nov-5Nov), which normally operates between RGH and CLT, will originate at GRO.

· Train 77 (26Oct-27Oct, 2Nov-3Nov), which normally operates between RGH and CLT, will originate at GRO, departing 44-minutes Later at 5:35pm.

· Train 77 (28Oct-29Oct, 4Nov-5Nov) will operate 30-minutes Later between RGH and CLT, departing RGH at 3:45pm.

ALTERNATE TRANSPORTATION:

· Bus 3172 (26Oct-29Oct, 2Nov-5Nov) will provide alternate transportation between GRO and RGH making all stops except BNC.

· Bus 3174 (26Oct-27Oct, 2Nov-3Nov) will provide alternate transportation between GRO and RGH making all stops except BNC.

· Bus 3175 (26Oct-29Oct, 2Nov-5Nov) will provide alternate transportation between RGH and GRO making all stops except BNC.

· Bus 3177 (26Oct-27Oct, 2Nov-3Nov) will provide alternate transportation between RGH and GRO making all stops except BNC.

WBS#: B.TR.100150.7292

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

27-FOI-00101, D00000009043 UNCLASSIFIED 11/2/2026

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

27-FOI-00101, 00000009043 "UNCLASSIFIED" 11/2/2026

09MAR26: Beginning April 21, 2026 and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.

- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:
- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION
- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Train 14(29) North of Salinas, CA - Weather

29OCT26: Train 14(29) was delayed 15 miles north of Salinas, CA, on the UPRR Coast Subdivision due to weather conditions. High tide conditions impacted operations between MP107 and MP97, resulting in restricted train movements until conditions improved. Train 11(28) was also delayed going through the area.

Train	Delay	Comment
11(28)	30"	
14(29)	42"	

Train 544(29) East of Richmond, CA - Injured Passenger

30OCT26: Train 544(29) was delayed 8 miles east of Richmond, CA at MP20.04 on the UPRR Martinez Subdivision, waiting for EMS to arrive for an unresponsive passenger in the restroom. The customer was removed by local EMS for medical treatment upon arrival.

Train	Delay	Comment
544(29)	39"	

Train 790(29) Los Angeles, CA - Engine Failure

30OCT26: Train 790(29) CC/6907, 5 cars, E/C2110, with 209 ticketed customers, was delayed at Los Angeles, CA due to HVAC issues on E/C2110. The mechanical team worked to troubleshoot the issue. Unable to resolve, and in order to help minimize customer delay, the decision was made to swap out equipment sets with inbound train 587. Once the equipment was swapped, and all customers re-boarded, Train 790(29) departed Los Angeles, CA with E/C2121, 5 cars, CC/6906. Due to no replacement equipment available, Train 567(30) was cancelled in entirety.

Due to the unplanned equipment change, Train 790(29) did not have cafe or business class services available between LAX-SAN. This was due to the inbound train 587 that was utilized for service was already stripped of all commissary items upon arrival into Los Angeles. This would also affect business and cafe service the following day, until the train could be re-stocked upon return to Los Angeles.

Train	Delay	Comment
790(29)	31"	
567(30)	Cancelled	

Train 588(29) Terminated at Irvine, CA - Engine Failure

30OCT26: Train 588(29) E/345, 5 cars, CC/6900, with 67 ticketed customers onboard, was terminated at Irvine, CA due to an irrecoverable coolant fault on engine E/345. The crew called in to CNOC mechanical reporting the engine showing as overheating. After the crew worked to troubleshoot the issue with a Siemens technician and unable to resolve, the decision was made to terminate the train at Irvine, CA and deadhead the equipment back to Los Angeles for repair. All affected passengers were accommodated on train 790(29).

Train	Delay	Comment
588(29)	Terminated IRV	

27-FOI-00101 0000009043 UNCLASSIFIED 11/2/2026

Train 59(29) South of Homewood, IL - Police Related

30OCT26: Train 59(29), operating with engines 196, 7 coaches, and 243 customers, was stopped approximately 7 miles south of Homewood, IL, on the Canadian National Chicago Subdivision due to a police hold for a vehicle stuck on the tracks at MP 32.9. Train 392(29) was also stopped south of the incident at MP 41.5. The vehicle was reported to be on the tracks as the result of a driver medical emergency. Emergency Medical Services were dispatched to the scene, as well as a track inspector. The vehicle was to be removed after the driver was extricated and then towed from the crossing. The vehicle was subsequently removed, allowing Train 59(29) and Train 392(29) to resume operation.

Train	Delay	Comment
59(29)	1'42"	
392(29)	1'35"	

Train 364(29) East of East Lansing, MI - Trespasser Incident

30OCT26: At approximately 9:09P-ET, Train 364(29), operating with engines 4606/4617, 6 coaches, and 82 customers, went into emergency at MP 229.8 on the Canadian National Flint Subdivision, 9 miles east of East Lansing, MI, after striking a trespasser. The incident resulted in a confirmed fatality. There were no reported injuries to the crew or customers, no damage to the equipment, and head-end power (HEP) remained active. The operating crew requested relief. Local law enforcement responded to the scene and the coroner conducted an investigation. The weather was reported as 53°F and clear. After local authorities concluded their investigation, Train 364(29) was released and advanced to Shaftsburg Siding to clear the main line, where it was held pending arrival of a relief crew. A Road Foreman of Engines met the train at the siding.

NRC # 1477382

National Response Center Number: 1477382

Train 319(29) West of Warrensburg, MO - Freight Train Interference

30OCT26: Train 319(29), operating with engine 4633, 7 coaches and 103 customers, was delayed operating between Warrensburg, MO, and Lees Summit, MO, on UP Sedalia subdivision, due to following UP2695.

Train	Delay	Comment
319(29)	22"	SED-WAR
319(29)	58"	WAR - LEE

Train 3(28) Albuquerque, NM - System

29OCT26: Train 3(28) was delayed departing Albuquerque, NM/MP902.4 on the NMRX Albuquerque Subdivision, due to receiving late bulletins account of a crew set back.

Train	Delay	Comment
3(28)	44"	

Train 25(29) West of Bay Saint Louis, MS - Freight Train Interference

30OCT26: Train 25(29), operating with engines 365/154, 3 coaches and 76 customers, was delayed 13.5 miles west of Bay Saint Louis, MS, on CSX NO&M subdivision, due to meeting CSX602 at Claiborne siding.

Train	Delay	Comment
25(29)	42"	

27-FOI-00101 00000090043 "UNCLASSIFIED" 11/2/2026

Train 1333(29) East of St. Paul-Minneapolis, MN - Freight Train Interference

30OCT26: Train 133(29) operating with engines E3/58, 4 coaches and 180 customers, was delayed 10 miles east of St. Paul-Minneapolis, MN, on CPCK River subdivision, due to meeting multiple freights at Control Point 3998.

Train	Delay	Comment
1333(29)	34"	

Train 21(28) South of Taylor, TX - Engine Failure

30OCT26: At approximately 6:21P-CT, Train 21(28), operating with engine 310, 6 coaches, and 116 customers, was stopped south of Taylor, TX at MP 155.2 after engine 310 shut down, resulting in a loss of head-end power (HEP). The crew worked with CNOC Mechanical personnel to troubleshoot the issue and successfully restored HEP. The train subsequently resumed operation. The weather was reported as 68°F and cloudy.

Train	Delay	Comment
21(28)	34"	

Train 2/422(28) El Paso, TX - Freight Train Interference

30OCT26: Train 2/422(28), operating with engines 23/14, 11 coaches and 180 customers, was delayed 53 miles south of El Paso, TX, on UPRR Valentine subdivision, due to meeting UP6732 at Control Point Iser.

Train	Delay	Comment
2/422(28)	35"	

Train 716(29) Oakland, CA - Third Party Contractor Engine Failure

29OCT26: Train 716(29) CC//C8305, 7 cars, E/C8314, was delayed departing Oakland, CA due to a traction motor fault on E/C8314. Unable to resolve, the engine was swapped out for E/C2003. Once the engine was swapped out and replaced, and the consist was made complete, the train proceeded to Oakland, CA station and boarded 21 customers.

Train	Delay	Comment
716(29)	1'01"	

Train 6(28) West of Denver, CO - Police Related

29OCT26: Train 6(28), operating with engines 163/146, 8 coaches, and 154 customers, was held west of Denver, CO station at MP 24.4 on the Union Pacific Moffat Tunnel Subdivision after Union Pacific reported a body on the tracks. The track was taken out of service while local authorities conducted an investigation and the coroner responded to the scene. Law enforcement subsequently cleared the area, allowing Train 6(28) to resume operation. The train continued its trip after being released by Union Pacific.

Train	Delay	Comment
6(28)	2'38"	

27-FOI-00101 D0000009043 UNCLASSIFIED 11/2/2026

Train 536(29) Originated Emeryville, CA - Cab Car Failure

29OCT26: Train 536(29) originated at Emeryville, CA, due to a late mechanical release from the yard account of the toilets in cab car CC/C8314 were overflowing. Once mechanical made the necessary repairs, the train was released and proceeded to Emeryville, CA behind Train 716(29). All 12 affected customers were accommodated on Train 716(29) between Oakland and Emeryville.

Train	Delay	Comment
536(29)	31"	

Train 507(29) Seattle, WA - Servicing

29OCT26: Train 507(29) was delayed departing Seattle, WA due to a late yard release account of a change of equipment. Windshield wipers were inoperable on cab car CC/90340, and switched to trainset from 500. That equipment had more mechanical problems and the equipment was swapped back. Once the wipers on the cab car were repaired, Train 507(29) was released to the station.

Train	Delay	Comment
507(29)	36"	

Train 3(29) Galesburg, IL - Routing

29OCT26: Train 3(29), operating with Locomotives 157 and 77, 9 coaches, and 188 customers, was held at Galesburg, IL station after Burlington Northern Santa Fe reported a bridge fire on the Marceline Subdivision 7.2 miles east of La Plata, MO (MP 305.5). Burlington Northern Santa Fe evaluated the affected area and operated 2 of its trains through the location before conducting a follow-up inspection. Following the inspection, Train 3(29) received a route and departed Galesburg, IL station at 5:58P-CT. The train subsequently passed through the bridge fire location under a 40 mph speed restriction imposed by Burlington Northern Santa Fe.

Train 3(29) was further delayed after departing Galesburg, IL due to multiple BNSF freight trains that were tied down as a result of hours of service issues stemming from the track hold for the bridge fire.

Train	Delay	Comment
3(29)	1'34"	
3(29)	1'45"	**Meeting and Following Multiple Freights**

Train 19(28) North of Tuscaloosa, AL - Passenger Train Interference

29OCT26: Train 19(28) held 11.1 miles north of Tuscaloosa, AL (MP198.4), on the NSRR AGS South Subdivision, at Fleming (MP187.3) meeting Train 20(29).

Train	Delay	Comment
19(28)	38"	

27-FOI-00101 00000090043 UNCLASSIFIED 11/2/2026

Train 338(29) South of Sturtevant, WI - Engine Failure

30OCT26: Train 338(29) operating with engine 4603 and 14 cars, was stopped east of the Sturtevant, WI station at MP 40.4 due to cab signal issues. The train retained head-end power (HEP), and Mechanical personnel provided troubleshooting assistance. Train 338(29) resumed operation at 4:13P-CT but subsequently experienced another penalty application east of the Sturtevant, WI station at MP 37.9. The train changed ends and operated to Chicago, IL Union Station at a maximum speed of 30 mph, arriving at 7:42P-CT.
As a result of the mechanical issue, the following service adjustments were implemented:
Train 339(29) was canceled. Three buses were sourced as alternate transportation, and any remaining customers were accommodated on Train 341(29).
Train 342(29) was canceled. Two of the buses assigned to Train 339(29) were turned to provide alternate transportation for Train 342(29).

Train	Delay	Comment
338(29)	1'32"	Initial eng issue
338(29)	1'28"	Shoving to CHI

Train 1(28)/421(27) East of El Paso, TX - Freight Train Interference

29OCT26: Train 1(28)/421(27) was delayed 0.5 miles east of El Paso, TX (MP1296.0), on the UPRR Lordsburg Subdivision, at Campbell St (MP1296.5), while waiting for UP 7511 to clear ahead. The freight train had gone into emergency to avoid striking a semi-truck, resulting in a temporary blockage of the route. Once the route was established and UP 7511 cleared, Train 1(28)/421(27) proceeded west.

Train	Delay	Comment
1(28)/421(27)	32"	

Train 505(29) South of Kelso-Longview, WA - Signal

29OCT26: Train 505(29) operating with cab car 7911, 12 cars, engine WDTX 1403, and 123 customers onboard was delayed beginning at milepost 101.8, 4 miles south of Kelso-Longview, WA on the BNSF Seattle subdivision due to restrictive signals from a known wayside signal failure. Once the train received more favorable signals, the train advanced to the next station at normal authorized speed.

Train	Delay	Comment
505(29)	46"	

Train 504(29) South of Kelso-Longview, WA - Freight Train Interference

29OCT26: Train 504(29) operating with engine WDTX 1400, 3 cars, cab car 90251, and 142 customers onboard was delayed at milepost 114.1, 1 mile south of Kelso-Longview, WA on the BNSF Seattle subdivision due to freight congestion in the area. Once the congestion was cleared, Train 504(29) was able to advance to the next station.

Train	Delay	Comment
504(29)	54"	

Train 19(28) South of Anniston, AL - M of W Work

29OCT26: Train 19(28) was delayed 47.7 miles south of Anniston, AL, at Central, AL (MP782.7) on the NSRR East End Subdivision, while awaiting track clearance due to Maintenance of Way personnel performing work in the area. Once the work window was released and clearance was received, the train resumed its route.

Train	Delay	Comment

Train 19(28) South of Atlanta, GA - Freight Train Interference

29OCT26: Train 19(28) held 17 miles south of Atlanta, GA (MP633.3), on the NSRR Atlanta North Subdivision, at Howell (MP635.0) waiting on cross traffic to clear.

Train	Delay	Comment
19(28)	32"	

Train 528(29) East of Martinez, CA - Drawbridge Opening

29OCT26: Train 528(29) operating with cab car 8312, 4 cars, engine CDTX 2006, and 82 customers onboard was delayed at milepost 32.8, 1 mile east of Martinez, CA on the UPRR Martinez subdivision due to Suisun Bay Bridge being opened. Once the bridge closed, Train 528(29) was able to advance to the next station.

Train	Delay	Comment
528(29)	30"	

Train 757(29) South of Carpinteria, CA - Passenger Train Interference

29OCT26: Train 757(29) operating with engine CDTX 2121, 5 cars, cab car 6906, and 9 customers onboard was delayed at milepost 385.3, 8 miles south of Carpinteria, CA on the UPRR Santa Barbara subdivision due to meeting late Train 770(29). Once the passenger train cleared, Train 757(29) advanced to the next station.

Train	Delay	Comment
757(29)	32"	
774(29)	48"	ITD Turn of late equipment

Train 531(29) West of Suisun-Fairfield, CA - Third Party Contractor Engine Failure

29OCT26: Train 531(29) operating with engines CDTX 2002, CDTX 2001, 5 cars, and 61 customers onboard was terminated at milepost 38.3, 11 miles west of Suisun-Fairfield, CA on the UPRR Martinez subdivision due to engine failure on CDTX 2002. It was reported that train had a low oil sensor. The crew attempted to troubleshoot with TASI unsuccessfully. The train was couple with Train 535(29) and taken to Oakland Maintenance Facility. Trains 532(29) and 545(29) were cancelled in their entirety due to lack of available equipment. Customers were reaccommodated on the next available transportation. Train 531(29) equipment was deadheaded to Sacramento after the engines were changed at the maintenance facility.

Train	Delay	Comment
531(29)	Term SUI	
532(29)	Cancelled	
545(29)	Cancelled	
535(29)	53"	

BNSF Gallup Subdivision East of Winslow, AZ- Southwest Chief Service Disruption

23OCT26: A severe storm with isolated showers and thunderstorms impacted the area between Gallup, NM and Albuquerque, NM bringing flash floods and reduced operating conditions. At 9:50A-PT, the BNSF reported flash floods on the Gallup Subdivision with confirmed water over the rails at MP 77.9, 80 miles east of Gallup, NM . Multiple freights were tied down with crews expired on hours of service between Laguna/MP 71.1 and Grants/MP 98.3 causing single tracking conditions over 100 miles. BNSF maintenance of way personnel responded to areas of potential water of the rails to inspect. Substantial delays were incurred operating through the affected area.

Train 4(22), with 159 customers on board, arrived into Winslow, AZ at 9:42A-PT and held for open track. While holding in Winslow, and in anticipation of further delay, the crew

Train 3(22) was also delayed operating through the affected area by high winds, flash floods, and freight meets.

24OCT26: Due to the late operation of Train 3(22), the crew expired on hours of service holding in Flagstaff, AZ. Train 3(22) held at Flagstaff with pilots on board beginning at 1:55A-PT for the recrew to arrive from Train 4(23), arriving at approximately 4:30A-PT. Once the recrew arrived and conducted their job briefing, Train 3(22) proceeded west.

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

To support customers and provide service recovery on Train 4(22), complimentary food and beverage offerings were provided. All coach customers received complimentary snack packs, bottled water, and hot beverages. During lunch service, sleeping car customers received the regular lunch service in the Dining Car, while coach customers were provided complimentary beef stew, mashed potatoes, and beverages. During dinner service, sleeping car customers received the regular dinner service in the Dining Car, while coach customers were provided complimentary Salisbury steak, vegetables, and mashed potatoes.

Train 4(22) had five misconnections at Kansas City, MO to Train 318(24) that were provided an alternate bus to their final destination. Train 6(22) also provided aid to local customers on Train 4(22) that were boarding between Galesburg and Chicago.

24OCT26: Train 3(23), operating with engines 79/29, 9 coaches, and 153 customers, was stopped east of the Gallup, NM station due to severe weather resulting in water above the rail in multiple locations. Burlington Northern Santa Fe subsequently reported that there was no route available beyond Laguna (MP 71) due to flooding of the tracks and the adjacent highway. Reported flood damage included both main tracks under water with debris between MP 72.7 and MP 72.3, including approximately 800 feet of side scour on the Main Track 1 side; side scour and undercutting at a culvert near MP 72.4; water over a high-water detector bridge and both rails between MP 70.1 and MP 69.8; and water over both rails between MP 69.8 and MP 69.7, where inspection was not possible. As a result, Train 3(23) shoved back to Albuquerque, NM and arrived at 11:57P-MT. The train wye'd en route into the station and will return to its origin.

As a result of the service disruption, the following service adjustments were implemented:
- Train 3(23) arrived at Albuquerque, NM at 11:57P-MT, wyed enroute into the station, and operated back to Chicago, IL, returning customers to points of origination.
- Train 4(24), with 135 customers, wyed at Barstow, CA and operated back to Los Angeles, CA Union Station.
- Train 3(24), with 136 customers, reversed back to Kansas City, MO, wyed, and planned to return to its origin.

Due to crew availability in Kansas City, Train 3(24) held in Kansas City for the arrival of Train 4(23) and was coupled to operate as a combo set to Chicago, returning Train 3(24) customers to points of origination.
- Train 4(25) was canceled. No alternate transportation was provided.

25OCT26: Train 3(23) departed Albuquerque, NM, at 125AM-MT operating eastward back to Chicago. Train 3(23) was delayed at Fox/MP820.0, 15 miles east of Lamy, NM, on the BNSF Glorieta Subdivision, after operating through code line failure at E. Fox, the crew reported while operating through the switch, with it on hand, the switch handle popped up as train started into the switch. Train 3(23) was delayed due to possible switch damage and due to holding for a required recrew to arrive.

As of 700AM-CT on Sunday October 25th, BNSF reported still no estimate for open track. Due to the ongoing issues on the BNSF Gallup Subdivision, additional Southwest Chief service adjustments were necessary:
- Train 3(25) terminated in Kansas City, MO. No alternate transportation between Kansas City and Los Angeles.
- Train 4(25) was reinstated between Kansas City and Chicago only. Train 4(25) originated in Kansas City with no alternate transportation between Los Angeles and Kansas City.
- Train 4(27) cancelled entirely. No alternate transportation between Los Angeles and Chicago.

1201AM-MT Tuesday October 27th. Due to the ongoing issues on the BNSF Gallup subdivision the following additional service adjustments were necessary:
- Train 3(26) cancelled entirely, no alternate transportation between Chicago and Los Angeles.
27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026
- Train 4(26) cancelled entirely, no alternate transportation between Los Angeles and Chicago.
BNSF advised an extremely large volume of freight traffic has been holding for open route and expect it to be heavily congested across the subdivision upon track opening.

27OCT26: A revised Main Track 1 estimate has been changed to "pending" due to a new washout that was identified at Milepost 50.2, with approximately 500 feet of side scour (erosion of the soil, rock, or ballast along the side of the railroad embankment (roadbed) caused by flowing water). Repair efforts are underway, with a ballast train placing material. Main Track Two between Laguna and Marmon is expected to reopen at 12:01 AM CT on the 27th under a 10 MPH speed restriction. BNSF has advised there are still a significant amount of Freight Trains tied down which will cause significant congestion through the area. Restoration efforts remain fluid due to changing water levels along the right-of-way.

- Train 3 (27) canceled in its entirety between Chicago and Los Angeles. No alternate transportation will be provided.
- Train 4(28) cancelled entirely, no alternate transportation between Los Angeles and Chicago.

29OCT26: Trains continued to see heavy delays in the area due to ongoing repairs and congestion.

WBS#: B.TR.100150.7301

Train	Delay	Comment
4(22)	1'32"	Hold WLO
4(22)	5'09"	Meeting multiple freights due to weather
3(22)	1'30"	High winds and flash floods
3(22)	2'43"	meeting multiple freights due to weather
3(22)	2'59"	FLG, recrew
4(25)	Originated KCY	
3(23)	Terminated ABQ	Returned to origin
3(24)	Terminated KCY	Returned to origin
4(24)	Terminated BAR	Returned to origin
3(25)	Terminated KCY	
4(27)	Cancelled	
3(23)	5'18"	E/LMY, switch issue/recrew
3(26)	Cancelled	
4(26)	Cancelled	
3(27)	Cancelled	
4(28)	Cancelled	
4(29)	47"	BAR-NDL Congestion
3(28)	1'07"	ABQ-KNG Congestion

Train 522(29) Oakland, CA - Initial Terminal Delay - Engine Failure

29OCT26: Train 522(29) operating with cab car 6964, 4 cars, engine CDTX 2010, and 5 customers was delayed departing Oakland, CA on the UPRR Niles subdivision due to there being a traction motor alarm for wheel slip on cab car 6964. TASI responded to the train and was able to rectify the issue. Once the issue was fixed, Train 522(29) departed Oakland at 7:19 AM-PT.

Train	Delay	Comment
522(29)	51"	

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Train 8/28(27) Red Wing, MN - Engine Failure

29OCT26: At 9:45AM-CT, Train 8/28(27), E/335-E/202-10 Cars, lead engine 335 experienced HEP inverter faults while arriving at the Red Wing, MN station (MP370.7) on the CPRR River Subdivision. This resulted in no head end power onboard. Weather conditions were 47 degrees and sunny, with 213 customers onboard. Upon arrival at the station, the crew contacted CNOC Mechanical and troubleshooting efforts were initiated to diagnose the head end power issue. At 10:35AM-CT, head end power was restored to the trainset. At 10:43AM-CT, Train 8/28(27) departed Red Wing en route to Chicago Union Station.

Train	Delay	Comment
8/28(27)	57"	

Train 58(29) Mattoon, IL - Freight Train Interference

29OCT26: Train 58(29) was delayed on the CNRR Champaign subdivision following UP 7864 from Mattoon, IL (MP172.3) to Tuscola (MP148.3).

Train	Delay	Comment
58(29)	30"	

Train 2/422(28) West of Yuma, AZ - Freight Train Interference

29OCT26: Train 2/422(28) operating with engines 23, 14, 11 cars, and 215 customers onboard was delayed beginning at milepost 676.0, 57 miles west of Yuma, AZ on the UPRR Yuma subdivision due to following UP freight train from milepost 676.0 to milepost 715.0. Once the freight train cleared, Train 2/422(28) was able to advance to the next station.

Train	Delay	Comment
2/422(28)	37"	

Train 22(29) North of San Antonio, TX - Trespasser Incident

29OCT26: Train 22(29) held 4.7 miles north of San Antonio, TX (MP209.5), on the UPRR Austin Subdivision, at MP256.3 due to a reported vehicle on the tracks at MP249.9. Inclement weather in the area caused delays to the wrecker and track inspector arriving to the location. Once the vehicle was removed and track inspection complete, Train 22(29) was released to continue north.

Train	Delay	Comment
22(29)	1'41"	

UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority

27-POI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

16OCT26: The UPRR placed numerous trackers in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected area due to signal issues where crews operated at restricted speed and stopped to flag crossings.

17OCT26: In order to minimize customer delays due to this, the following Service Adjustments were implemented:

Train 761(17) and 765(17) were originated at Los Angeles, CA, no alternate transportation provided.
Trains 757/ 765/ 777(17-01NOV) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-01NOV) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

23OCT26: The operating plan was extended through at least Sunday November 1, with further extensions anticipated.

WBS#: B.TR.100150.7278

Train	Delay	Comment
774(16)	1'39"	
757(16)	1'34"	
786(16)	1'35"	ITD SLO- Turn of 757(16)
786(16)	1'35"	ITD SLO- Equip off 757
765(16)	1'22"	
794(16)	38"	ITD SLO- Equip off 765
794(16)	2'08"	
14(16)	2'21"	
786(16)	2'57"	
11(15)	1'23"	
14(17)	1'13"	
11(16)	1'51"	
11(17)	1'15"	
14(18)	1'19"	
14(19)	1'01"	
11(18)	1'08"	
11(19)	1'10"	
14(20)	1'40"	
11(19)	51"	waiting for & meeting 14(20) at Tangair
14(21)	40"	
11(20)	1'05"	meet 14(21)
11(20)	1'14"	
11(21)	1'02"	
14(22)	59"	
11(22)	1'51"	
14(23)	1'03"	
782(23)	48"	
14(24)	1'03"	
11(25)	1'52"	
14(27)	1'31"	
11(26)	1'29"	
11(28)	1'11"	
14(28)	1'07"	
14(29)	45"	

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

27-FOI-00101 0000000090443 "UNCLASSIFIED" 11/2/2026

29SEP26: Train 821(29) was delayed beginning about 2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	
821(07)	35"	
822(08)	32"	
821(09)	32"	
822(09)	36"	
822(10)	23"	
822(11)	41"	
822(12)	48"	
821(12)	21"	
821(13)	22"	
822(13)	36"	
821(14)	35"	
822(14)	17"	
821(15)	26"	
821(16)	41"	
822(15)	34"	
822(16)	19"	
821(17)	24"	
821(19)	39"	
822(19)	22"	
821(20)	29"	
822(20)	32"	
821(21)	46"	
821(22)	32"	
822(21)	19"	
822(22)	30"	
821(23)	42"	
822(23)	23"	
821(24)	21"	
822(24)	22"	
821(25)	34"	
822(25)	43"	
821(26)	52"	
822(27)	34"	
822(26)	21"	
821(28)	30"	
822(28)	31"	
821(29)	23"	
822(29)	33"	

Maintenance of Way Highlights

27-FOI-00101 0000000000043 UNCLASSIFIED 11212025

Amtrak/MDOT Michigan Line - Scheduled M/W Work TWA 27-008

28OCT26: Amtrak/MDOT Michigan Line has signal cutover and AMTEC system cutover work starting October 28th through October 30th between CP 37 and CP72. To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

-Train 350 (28Oct-30Oct) is canceled in entirety. No alternate transportation will be provided on 28Oct. Bus 3350 (29Oct, 30Oct) will provide alternate transportation between Chicago, IL and Pontiac, MI.

-Train 351 (28Oct-30Oct) is canceled in entirety. No alternate transportation will be provided on 29Oct. Bus 3351(28Oct, 30Oct) will provide alternate transportation between Pontiac, MI and Chicago, IL.

-Train 352 (28Oct-30Oct) is canceled in entirety. No alternate transportation will be provided on 30Oct. Bus 3352 (28Oct, 29Oct) will provide alternate transportation between Chicago, IL and Pontiac, MI.

-Train 353 (28Oct-30Oct) is canceled in entirety. Bus 3353 (28Oct, 29Oct, 30Oct) will provide alternate transportation between Pontiac, MI and Chicago, IL.

-Train 354 (28Oct-30Oct) is canceled in entirety. No alternate transportation will be provided on 28Oct and 29Oct. Bus 3354 (30Oct) will provide alternate transportation between Chicago, IL and Pontiac, MI.

-Train 355 (28Oct-30Oct) is canceled in entirety. No alternate transportation will be provided on 28Oct, 29Oct, and 30Oct.

WBS#: B.TR.100150.7211

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL. Beginning Monday October 12th, Bus 3391 will operate 41-minutes later between Champaign and Carbondale, departing Champaign at 1130am.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-085

29JUL26: Amtrak / MDOT has extra gang scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
27OCT26: Track work was extended one day through and including 01NOV.
-Train 352 (03Aug-01NOV) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (01Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (03Aug-01NOV) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (01Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

	Projected Need		Number Operated			
Train	Cars	Seats	Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

27-FOI-00101 00000009043 "UNCLASSIFIED" 11/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
5 (30)	CHI	Operating with standard coach in lieu of bag coach. Inventory has been increased to reflect lower level seating.			34055
6 (30)	EMY	Operating with standard coach in lieu of bag coach. Inventory has been increased to reflect lower level seating.			34038
770 (30)	GTA	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 9700 BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.			9700
588 (30)	LAX	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 9700 BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.			9700
19 (29)	NYP	VIEWLINER II IN LIEU OF A VIEWLINER I. PLEASE NOTIFY ANY EFFECTED PAX.			62523
581 (30)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 9700 BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.			9700

Reverse Consists

Train Number	Station	Reason
1087 (29)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
67 (29)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1135 (29)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1138 (30)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
1124 (30)	NPN	Consist reversed | Business class seat orientation may have changed | At Front
2118 (29)	WAS	Acela consist reversed | First class at Front