



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, October 17, 2025

Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/16/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	300	38	87.3%	4,696	618	86.8%	4,696	618	86.8%
Central Division	85.5%	66	7	89.4%	1,052	119	88.7%	1,052	119	88.7%
Northeast Division	80.0%	93	15	83.9%	1,463	229	84.3%	1,463	229	84.3%
Southeast Division	72.5%	72	9	87.5%	1,099	107	90.3%	1,099	107	90.3%
Southwest Division	77.0%	69	7	89.9%	1,082	163	84.9%	1,082	163	84.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00048 00000004859 UNCLASSIFIED Endpoint Arrival Dates through 10/16/25 10/20/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	101,923	22,491	78%	1,662,125	322,161	81%	1,662,125	322,161	81%
Northeast Corridor	81%	45,361	6,392	86%	751,083	118,916	84%	751,083	118,916	84%
Acela	83%	9,108	209	98%	146,782	24,508	83%	146,782	24,508	83%
Northeast Regional	79%	36,253	6,183	83%	604,301	94,408	84%	604,301	94,408	84%
Richmond / Newport News / Norfolk	77%	10,862	2,692	75%	188,087	34,517	82%	188,087	34,517	82%
Springfield Shuttles	89%	795	57	93%	12,802	1,060	92%	12,802	1,060	92%
Roanoke	79%	2,749	412	85%	48,521	6,379	87%	48,521	6,379	87%
On Spine Northeast Regional	80%	21,847	3,022	86%	354,891	52,452	85%	354,891	52,452	85%
State Supported	80%	44,730	10,709	76%	711,694	133,014	81%	711,694	133,014	81%
Borealis	60%	626	276	56%	10,100	2,511	75%	10,100	2,511	75%
Capitol Corridor	90%	4,256	594	86%	59,354	4,647	92%	59,354	4,647	92%
Carolinian	60%	1,317	463	65%	19,524	6,074	69%	19,524	6,074	69%
Cascades	63%	2,240	760	66%	38,148	10,546	72%	38,148	10,546	72%
Downeaster	82%	1,154	404	65%	25,551	6,428	75%	25,551	6,428	75%
Empire	78%	5,761	2,315	60%	92,021	17,762	81%	92,021	17,762	81%
Adirondack	72%	583	372	36%	6,495	2,181	66%	6,495	2,181	66%
Ethan Allen Express	70%	638	39	94%	10,273	2,910	72%	10,273	2,910	72%
Maple Leaf	70%	724	593	18%	13,097	5,005	62%	13,097	5,005	62%
New York - Albany	85%	2,554	562	78%	39,459	4,608	88%	39,459	4,608	88%
New York - Niagara Falls	75%	1,262	749	41%	22,697	3,058	87%	22,697	3,058	87%
Heartland Flyer	65%	95	94	1%	3,336	2,217	34%	3,336	2,217	34%
Hiawatha	90%	1,912	0	100%	29,736	5,405	82%	29,736	5,405	82%
Illinois	78%	1,882	621	67%	40,659	9,509	77%	40,659	9,509	77%
Carl Sandburg / Illinois Zephyr	85%	391	129	67%	6,567	2,616	60%	6,567	2,616	60%
Illini / Saluki	85%	482	10	98%	14,909	2,551	83%	14,909	2,551	83%
Lincoln Service	70%	1,009	482	52%	19,183	4,342	77%	19,183	4,342	77%
Keystone	92%	9,677	952	90%	136,530	11,996	91%	136,530	11,996	91%
Lincoln / Missouri	60%	818	500	39%	13,180	6,783	49%	13,180	6,783	49%
Mardi Gras Service	80%	380	62	84%	7,768	1,610	79%	7,768	1,610	79%
Michigan	69%	2,017	547	73%	30,350	5,787	81%	30,350	5,787	81%
Blue Water	70%	572	314	45%	8,203	1,684	79%	8,203	1,684	79%
Pere Marquette	85%	410	218	47%	4,324	706	84%	4,324	706	84%
Wolverine	65%	1,035	15	99%	17,823	3,397	81%	17,823	3,397	81%
Missouri	80%	252	0	100%	3,884	792	80%	3,884	792	80%
Pacific Surfliner	85%	6,819	629	91%	105,010	11,567	89%	105,010	11,567	89%
Pennsylvanian	72%	873	409	53%	15,033	2,198	85%	15,033	2,198	85%
Piedmont	73%	1,222	695	43%	21,209	6,492	69%	21,209	6,492	69%
San Joaquins	73%	2,034	843	59%	37,943	14,647	61%	37,943	14,647	61%
Vermont	75%	1,395	545	61%	22,358	6,043	73%	22,358	6,043	73%
Long Distance	56%	11,832	5,390	54%	199,348	70,231	65%	199,348	70,231	65%
Auto Train	57%	676	450	33%	9,678	1,775	82%	9,678	1,775	82%
California Zephyr	50%	924	530	43%	15,846	6,306	60%	15,846	6,306	60%
Cardinal	55%	425	269	37%	4,790	2,610	46%	4,790	2,610	46%
City Of New Orleans	75%	671	326	51%	11,702	2,437	79%	11,702	2,437	79%
Coast Starlight	60%	1,005	283	72%	17,561	5,839	67%	17,561	5,839	67%
Crescent	70%	905	435	52%	15,149	4,651	69%	15,149	4,651	69%
Empire Builder	55%	1,144	765	33%	17,237	5,155	70%	17,237	5,155	70%
Floridian	40%	1,583	995	37%	27,327	13,696	50%	27,327	13,696	50%
Lake Shore Ltd	73%	848	41	95%	15,093	2,061	86%	15,093	2,061	86%
Palmetto	65%	995	102	90%	15,392	3,167	79%	15,392	3,167	79%
Silver Meteor	45%	895	7	99%	14,879	4,318	71%	14,879	4,318	71%
Southwest Chief	40%	923	530	43%	15,005	9,604	36%	15,005	9,604	36%
Sunset Ltd	70%	0	0	-	4,082	940	77%	4,082	940	77%
Texas Eagle	50%	838	657	22%	15,607	7,672	51%	15,607	7,672	51%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00040 00000004050 "UNCLASSIFIED" 10/20/2025

Train Index Dates Through October 16, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	84,974	1,700,834	500	84,974	1,700,834	500

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	2,806	493,344	57	2,806	493,344	57
INFRASTRUCTURE PLANNED	130	2,391	493,344	48	2,391	493,344	48
FLEET RELIABILITY	90	12,978	1,700,834	76	12,978	1,700,834	76
TRAIN OPERATIONS	427	66,799	1,700,834	393	66,799	1,700,834	393

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/16/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	300	38	87.3%	4,696	618	86.8%	4,696	618	86.8%
Central Division	85.5%	66	7	89.4%	1,052	119	88.7%	1,052	119	88.7%
Northeast Division	80.0%	93	15	83.9%	1,463	229	84.3%	1,463	229	84.3%
Southeast Division	72.5%	72	9	87.5%	1,099	107	90.3%	1,099	107	90.3%
Southwest Division	77.0%	69	7	89.9%	1,082	163	84.9%	1,082	163	84.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0001Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/16/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	300	38	87.3%	4,696	618	86.8%	4,696	618	86.8%
Central Division	85.5%	66	7	89.4%	1,052	119	88.7%	1,052	119	88.7%
CDL	90.0%	2	1	50.0%	32	3	90.6%	32	3	90.6%
CHI	85.0%	27	2	92.6%	427	48	88.8%	427	48	88.8%
EUG	86.5%	2	0	100.0%	30	3	90.0%	30	3	90.0%
GRR	98.0%	1	0	100.0%	16	0	100.0%	16	0	100.0%
KCY	84.5%	2	0	100.0%	32	4	87.5%	32	4	87.5%
MKE	86.5%	6	1	83.3%	94	15	84.0%	94	15	84.0%
MSP	94.0%	1	0	100.0%	16	0	100.0%	16	0	100.0%
PDX	78.0%	5	0	100.0%	80	9	88.8%	80	9	88.8%
PNT	91.5%	2	0	100.0%	2	0	100.0%	2	0	100.0%
PTH	93.0%	1	0	100.0%	16	1	93.8%	16	1	93.8%
QCY	87.5%	2	0	100.0%	32	7	78.1%	32	7	78.1%
SEA	80.0%	8	2	75.0%	128	18	85.9%	128	18	85.9%
SPK	92.0%	1	-	100.0%	16	1	93.8%	16	1	93.8%
STL	88.0%	4	0	100.0%	64	2	96.9%	64	2	96.9%
TRM	-	-	-	-	35	5	85.7%	35	5	85.7%
VAC	95.0%	2	1	50.0%	32	3	90.6%	32	3	90.6%
Northeast Division	80.0%	93	15	83.9%	1,463	229	84.3%	1,463	229	84.3%
ALB	91.5%	6	0	100.0%	96	1	99.0%	96	1	99.0%
BON	43.5%	4	1	75.0%	72	17	76.4%	72	17	76.4%
BOS	86.5%	18	4	77.8%	280	26	90.7%	280	26	90.7%
BRK	88.0%	3	0	100.0%	64	5	92.2%	64	5	92.2%
BTN	48.0%	1	0	100.0%	16	6	62.5%	16	6	62.5%
GFD	86.0%	2	1	50.0%	32	2	93.8%	32	2	93.8%
HFD	-	2	0	100.0%	24	2	91.7%	24	2	91.7%
MTR	79.5%	1	0	100.0%	16	2	87.5%	16	2	87.5%
NFL	96.5%	2	0	100.0%	32	3	90.6%	32	3	90.6%
NHV	75.5%	5	1	80.0%	78	21	73.1%	78	21	73.1%
NYP	77.5%	41	8	80.5%	627	126	79.9%	627	126	79.9%
SAB	98.0%	1	0	100.0%	16	0	100.0%	16	0	100.0%
SPG	88.0%	5	0	100.0%	86	6	93.0%	86	6	93.0%
TWO	84.0%	1	0	100.0%	16	5	68.8%	16	5	68.8%
WEM	-	1	0	100.0%	8	7	12.5%	8	7	12.5%
Southeast Division	72.5%	72	9	87.5%	1,099	107	90.3%	1,099	107	90.3%
ATL	-	-	-	-	1	0	100.0%	1	0	100.0%
CLT	92.0%	5	2	60.0%	80	8	90.0%	80	8	90.0%
HAR	62.0%	13	2	84.6%	183	20	89.1%	183	20	89.1%
LOR	69.5%	1	0	100.0%	16	2	87.5%	16	2	87.5%
MIA	87.5%	2	0	100.0%	32	2	93.8%	32	2	93.8%
MOE	94.0%	2	0	100.0%	32	3	90.6%	32	3	90.6%
NFK	86.0%	3	1	66.7%	46	4	91.3%	46	4	91.3%
NOL	92.0%	4	0	100.0%	70	3	95.7%	70	3	95.7%
NPN	96.0%	2	1	50.0%	32	3	90.6%	32	3	90.6%
PGH	92.0%	1	0	100.0%	16	1	93.8%	16	1	93.8%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/16/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	300	38	87.3%	4,696	618	86.8%	4,696	618	86.8%
Southeast Division	72.5%	72	9	87.5%	1,099	107	90.3%	1,099	107	90.3%
PHL	45.0%	5	0	100.0%	74	14	81.1%	74	14	81.1%
RGH	97.0%	4	0	100.0%	64	2	96.9%	64	2	96.9%
RNK	85.5%	2	0	100.0%	32	4	87.5%	32	4	87.5%
RVM	86.0%	1	0	100.0%	16	1	93.8%	16	1	93.8%
SAV	91.5%	1	0	100.0%	16	0	100.0%	16	0	100.0%
SFA	70.5%	1	0	100.0%	16	1	93.8%	16	1	93.8%
WAS	70.0%	25	3	88.0%	373	39	89.5%	373	39	89.5%
Southwest Division	77.0%	69	7	89.9%	1,082	163	84.9%	1,082	163	84.9%
ARN	60.5%	1	0	100.0%	16	2	87.5%	16	2	87.5%
BFD	75.5%	6	1	83.3%	90	26	71.1%	90	26	71.1%
DAL	-	-	-	-	1	0	100.0%	1	0	100.0%
EMY	50.0%	1	0	100.0%	16	8	50.0%	16	8	50.0%
FNO	-	-	-	-	1	0	100.0%	1	0	100.0%
FTW	89.5%	1	0	100.0%	15	2	86.7%	15	2	86.7%
GTA	72.5%	3	1	66.7%	48	5	89.6%	48	5	89.6%
LAX	77.5%	9	2	77.8%	152	18	88.2%	152	18	88.2%
OKC	96.0%	1	0	100.0%	16	2	87.5%	16	2	87.5%
OKJ	79.0%	12	2	83.3%	171	41	76.0%	171	41	76.0%
SAC	73.5%	14	0	100.0%	206	26	87.4%	206	26	87.4%
SAN	77.0%	11	1	90.9%	183	15	91.8%	183	15	91.8%
SAS	85.0%	1	0	100.0%	16	2	87.5%	16	2	87.5%
SJC	87.5%	7	0	100.0%	112	10	91.1%	112	10	91.1%
SLO	62.0%	2	0	100.0%	31	5	83.9%	31	5	83.9%
SOL	-	-	-	-	8	1	87.5%	8	1	87.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		16	1	93.8%	16	1	93.8%	16	5	68.8%	16	5	68.8%
4	40	16	1	93.8%	16	1	93.8%	16	12	25.0%	16	12	25.0%
5		15	2	86.7%	15	2	86.7%	14	3	78.6%	14	3	78.6%
6	48	16	8	50.0%	16	8	50.0%	16	7	56.3%	16	7	56.3%
7		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
8	92	16	5	68.8%	16	5	68.8%	16	6	62.5%	16	6	62.5%
11		15	2	86.7%	15	2	86.7%	13	2	84.6%	13	2	84.6%
14	43	16	2	87.5%	16	2	87.5%	15	4	73.3%	15	4	73.3%
19	37	16	2	87.5%	16	2	87.5%	16	5	68.8%	16	5	68.8%
20		16	1	93.8%	16	1	93.8%	16	0	100.0%	16	0	100.0%
21		16	2	87.5%	16	2	87.5%	16	5	68.8%	16	5	68.8%
22	216	16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
23		16	3	81.3%	16	3	81.3%	16	6	62.5%	16	6	62.5%
24		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
25	27	16	0	100.0%	16	0	100.0%	16	3	81.3%	16	3	81.3%
26		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
27		16	2	87.5%	16	2	87.5%	16	2	87.5%	16	2	87.5%
28		16	4	75.0%	16	4	75.0%	16	1	93.8%	16	1	93.8%
40		16	1	93.8%	16	1	93.8%	16	5	68.8%	16	5	68.8%
41	70	16	8	50.0%	16	8	50.0%	16	13	18.8%	16	13	18.8%
42		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
43	39	16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
48		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
49		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
51	57	7	4	42.9%	7	4	42.9%	7	3	57.1%	7	3	57.1%
52		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
53		16	2	87.5%	16	2	87.5%	16	1	93.8%	16	1	93.8%
55		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
56		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
58	427	15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
59		15	3	80.0%	15	3	80.0%	15	1	93.3%	15	1	93.3%
63	27	16	8	50.0%	16	8	50.0%	16	11	31.3%	16	11	31.3%
64	31	16	5	68.8%	16	5	68.8%	16	4	75.0%	16	4	75.0%
66		16	4	75.0%	16	4	75.0%	16	3	81.3%	16	3	81.3%
67		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
68	23	16	2	87.5%	16	2	87.5%	16	9	43.8%	16	9	43.8%
69		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
71	54	16	0	100.0%	16	0	100.0%	16	5	68.8%	16	5	68.8%
72	25	16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
73	24	16	1	93.8%	16	1	93.8%	16	10	37.5%	16	10	37.5%
74		16	1	93.8%	16	1	93.8%	16	5	68.8%	16	5	68.8%
75		16	0	100.0%	16	0	100.0%	16	9	43.8%	16	9	43.8%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	19	16	3	81.3%	16	3	81.3%	16	12	25.0%	16	12	25.0%
77	17	16	1	93.8%	16	1	93.8%	16	9	43.8%	16	9	43.8%
78		16	2	87.5%	16	2	87.5%	16	3	81.3%	16	3	81.3%
79		16	5	68.8%	16	5	68.8%	16	3	81.3%	16	3	81.3%
80		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
84		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
85		12	1	91.7%	12	1	91.7%	12	5	58.3%	12	5	58.3%
86	73	12	1	91.7%	12	1	91.7%	12	7	41.7%	12	7	41.7%
89		16	3	81.3%	16	3	81.3%	16	1	93.8%	16	1	93.8%
90		16	0	100.0%	16	0	100.0%	16	3	81.3%	16	3	81.3%
93		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
94		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
95	40	12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
97		16	3	81.3%	16	3	81.3%	16	5	68.8%	16	5	68.8%
98		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
110		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
111		12	4	66.7%	12	4	66.7%	12	0	100.0%	12	0	100.0%
112		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
114		12	3	75.0%	12	3	75.0%	12	0	100.0%	12	0	100.0%
119		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
125		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
129		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
130		12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
131		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
133		12	6	50.0%	12	6	50.0%	12	4	66.7%	12	4	66.7%
134		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
136		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
137		10	3	70.0%	10	3	70.0%	10	1	90.0%	10	1	90.0%
138		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
141		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
148		12	2	83.3%	12	2	83.3%	12	6	50.0%	12	6	50.0%
151		16	2	87.5%	16	2	87.5%	16	5	68.8%	16	5	68.8%
170		9	1	88.9%	9	1	88.9%	9	2	77.8%	9	2	77.8%
171		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
172	25	12	2	83.3%	12	2	83.3%	12	7	41.7%	12	7	41.7%
173	41	12	1	91.7%	12	1	91.7%	12	5	58.3%	12	5	58.3%
174		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
175		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
176		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
177		12	4	66.7%	12	4	66.7%	12	5	58.3%	12	5	58.3%
178		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
179		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181		12	4	66.7%	12	4	66.7%	12	0	100.0%	12	0	100.0%
182		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
183		12	3	75.0%	12	3	75.0%	12	3	75.0%	12	3	75.0%
184		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
185		12	3	75.0%	12	3	75.0%	12	0	100.0%	12	0	100.0%
186		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
190	28	12	3	75.0%	12	3	75.0%	12	3	75.0%	12	3	75.0%
192		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
193		12	2	83.3%	12	2	83.3%	12	5	58.3%	12	5	58.3%
196		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
197		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
232		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
233		16	5	68.8%	16	5	68.8%	16	4	75.0%	16	4	75.0%
234		16	0	100.0%	16	0	100.0%	16	0	100.0%	16	0	100.0%
236		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
237	63	16	3	81.3%	16	3	81.3%	16	2	87.5%	16	2	87.5%
239		16	4	75.0%	16	4	75.0%	16	0	100.0%	16	0	100.0%
240		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
241	16	16	4	75.0%	16	4	75.0%	16	3	81.3%	16	3	81.3%
243		12	5	58.3%	12	5	58.3%	13	3	76.9%	13	3	76.9%
244		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
280		16	2	87.5%	16	2	87.5%	16	2	87.5%	16	2	87.5%
281		16	4	75.0%	16	4	75.0%	16	1	93.8%	16	1	93.8%
283	28	16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
284	49	16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
290		16	6	62.5%	16	6	62.5%	16	7	56.3%	16	7	56.3%
291		16	5	68.8%	16	5	68.8%	16	2	87.5%	16	2	87.5%
300		16	0	100.0%	16	0	100.0%	16	3	81.3%	16	3	81.3%
301		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
302	27	16	0	100.0%	16	0	100.0%	16	5	68.8%	16	5	68.8%
305	29	16	1	93.8%	16	1	93.8%	16	5	68.8%	16	5	68.8%
306		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
307		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
311		16	2	87.5%	16	2	87.5%	16	2	87.5%	16	2	87.5%
316		16	1	93.8%	16	1	93.8%	16	4	75.0%	16	4	75.0%
318	21	16	3	81.3%	16	3	81.3%	16	7	56.3%	16	7	56.3%
319	36	16	0	100.0%	16	0	100.0%	16	10	37.5%	16	10	37.5%
329		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
330		14	1	92.9%	14	1	92.9%	14	0	100.0%	14	0	100.0%
331		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
332		16	3	81.3%	16	3	81.3%	16	1	93.8%	16	1	93.8%
334		16	1	93.8%	16	1	93.8%	15	2	86.7%	15	2	86.7%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		16	3	81.3%	16	3	81.3%	15	6	60.0%	15	6	60.0%
336		16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%
337		16	3	81.3%	16	3	81.3%	16	3	81.3%	16	3	81.3%
338		16	8	50.0%	16	8	50.0%	15	7	53.3%	15	7	53.3%
339		16	7	56.3%	16	7	56.3%	16	5	68.8%	16	5	68.8%
341		16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
342		16	2	87.5%	16	2	87.5%	15	1	93.3%	15	1	93.3%
351		16	1	93.8%	16	1	93.8%	16	4	75.0%	16	4	75.0%
352		16	1	93.8%	16	1	93.8%	15	2	86.7%	15	2	86.7%
354		16	1	93.8%	16	1	93.8%	16	4	75.0%	16	4	75.0%
355		16	2	87.5%	16	2	87.5%	16	1	93.8%	16	1	93.8%
364		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
365	30	16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
370		16	0	100.0%	16	0	100.0%	16	3	81.3%	16	3	81.3%
371		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
380		16	6	62.5%	16	6	62.5%	16	6	62.5%	16	6	62.5%
381		16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%
382		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
383		16	1	93.8%	16	1	93.8%	16	8	50.0%	16	8	50.0%
390		16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
391	Cncld	16	0	100.0%	16	0	100.0%	15	0	100.0%	15	0	100.0%
392	Cncld	16	1	93.8%	16	1	93.8%	15	1	93.3%	15	1	93.3%
393		16	3	81.3%	16	3	81.3%	15	4	73.3%	15	4	73.3%
417		12	3	75.0%	12	3	75.0%	11	0	100.0%	11	0	100.0%
425		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
470		12	3	75.0%	12	3	75.0%	12	2	83.3%	12	2	83.3%
471		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
473		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
474		12	4	66.7%	12	4	66.7%	11	1	90.9%	11	1	90.9%
475		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
478		12	7	41.7%	12	7	41.7%	12	2	83.3%	12	2	83.3%
479		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
486	43	13	4	69.2%	13	4	69.2%	12	2	83.3%	12	2	83.3%
494		13	6	53.8%	13	6	53.8%	12	3	75.0%	12	3	75.0%
495		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
500		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
502	40	16	2	87.5%	16	2	87.5%	16	3	81.3%	16	3	81.3%
503		16	3	81.3%	16	3	81.3%	15	5	66.7%	15	5	66.7%
504		16	1	93.8%	16	1	93.8%	16	7	56.3%	16	7	56.3%
505		16	2	87.5%	16	2	87.5%	15	1	93.3%	15	1	93.3%
506		15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
507		16	2	87.5%	16	2	87.5%	16	8	50.0%	16	8	50.0%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
508		16	3	81.3%	16	3	81.3%	16	3	81.3%	16	3	81.3%
509	21	16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%
511		16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%
516	275	16	3	81.3%	16	3	81.3%	16	9	43.8%	16	9	43.8%
517	17	16	1	93.8%	16	1	93.8%	15	7	53.3%	15	7	53.3%
518		16	1	93.8%	16	1	93.8%	16	11	31.3%	16	11	31.3%
519	67	16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
520		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
521		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
522	16	12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
523		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
524		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
525		12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
526		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
527	13	12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
528	25	12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
529		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
531		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
532	15	12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
534		9	1	88.9%	9	1	88.9%	9	0	100.0%	9	0	100.0%
535		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
536		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
537		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
538		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
540		12	1	91.7%	12	1	91.7%	12	0	100.0%	12	0	100.0%
541		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%
542		12	1	91.7%	12	1	91.7%	11	3	72.7%	11	3	72.7%
543		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
544		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
545	14	12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
546		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
547		12	2	83.3%	12	2	83.3%	12	3	75.0%	12	3	75.0%
548		12	3	75.0%	12	3	75.0%	12	1	91.7%	12	1	91.7%
549		9	3	66.7%	9	3	66.7%	8	2	75.0%	8	2	75.0%
551		12	1	91.7%	12	1	91.7%	11	2	81.8%	11	2	81.8%
562		16	2	87.5%	16	2	87.5%	15	0	100.0%	15	0	100.0%
564	Cncl'd	16	1	93.8%	16	1	93.8%	15	1	93.3%	15	1	93.3%
566		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
572	17	16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
573		16	2	87.5%	16	2	87.5%	15	0	100.0%	15	0	100.0%
580		16	3	81.3%	16	3	81.3%	16	2	87.5%	16	2	87.5%
581		16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
582		16	2	87.5%	16	2	87.5%	16	2	87.5%	16	2	87.5%
586		16	3	81.3%	16	3	81.3%	14	2	85.7%	14	2	85.7%
587		16	1	93.8%	16	1	93.8%	15	3	80.0%	15	3	80.0%
591		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
593		16	3	81.3%	16	3	81.3%	14	2	85.7%	14	2	85.7%
595		16	3	81.3%	16	3	81.3%	16	5	68.8%	16	5	68.8%
600		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
601		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
605		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
607		12	1	91.7%	12	1	91.7%	11	0	100.0%	11	0	100.0%
609		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
620		12	5	58.3%	12	5	58.3%	11	1	90.9%	11	1	90.9%
624		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
639	12	12	5	58.3%	12	5	58.3%	12	2	83.3%	12	2	83.3%
640	12	12	0	100.0%	12	0	100.0%	12	7	41.7%	12	7	41.7%
641		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
642		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
643		12	1	91.7%	12	1	91.7%	11	1	90.9%	11	1	90.9%
644		12	1	91.7%	12	1	91.7%	12	2	83.3%	12	2	83.3%
645	27	12	3	75.0%	12	3	75.0%	12	2	83.3%	12	2	83.3%
646	30	12	1	91.7%	12	1	91.7%	12	6	50.0%	12	6	50.0%
647	20	12	0	100.0%	12	0	100.0%	12	5	58.3%	12	5	58.3%
648		12	2	83.3%	12	2	83.3%	12	0	100.0%	12	0	100.0%
649		12	1	91.7%	12	1	91.7%	11	1	90.9%	11	1	90.9%
650		12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%
651		12	2	83.3%	12	2	83.3%	12	5	58.3%	12	5	58.3%
652		12	2	83.3%	12	2	83.3%	11	3	72.7%	11	3	72.7%
653		12	4	66.7%	12	4	66.7%	12	5	58.3%	12	5	58.3%
654		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
655		11	4	63.6%	11	4	63.6%	11	3	72.7%	11	3	72.7%
656		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
657		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
658		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
680	22	12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
681		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
682		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
685	42	12	0	100.0%	12	0	100.0%	12	5	58.3%	12	5	58.3%
686		12	7	41.7%	12	7	41.7%	12	3	75.0%	12	3	75.0%
687		12	3	75.0%	12	3	75.0%	12	3	75.0%	12	3	75.0%
688	46	12	0	100.0%	12	0	100.0%	12	5	58.3%	12	5	58.3%
689		10	3	70.0%	10	3	70.0%	9	1	88.9%	9	1	88.9%
702		16	5	68.8%	16	5	68.8%	16	6	62.5%	16	6	62.5%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
703	24	16	4	75.0%	16	4	75.0%	16	4	75.0%	16	4	75.0%
710		16	7	56.3%	16	7	56.3%	16	8	50.0%	16	8	50.0%
711		15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
712	41	16	4	75.0%	16	4	75.0%	16	8	50.0%	16	8	50.0%
713		16	4	75.0%	16	4	75.0%	15	8	46.7%	15	8	46.7%
714		13	3	76.9%	13	3	76.9%	12	4	66.7%	12	4	66.7%
715		16	8	50.0%	16	8	50.0%	15	8	46.7%	15	8	46.7%
716		16	6	62.5%	16	6	62.5%	16	6	62.5%	16	6	62.5%
717		12	1	91.7%	12	1	91.7%	10	3	70.0%	10	3	70.0%
718	No OS	16	7	56.3%	16	7	56.3%	16	6	62.5%	16	6	62.5%
719	80	16	8	50.0%	16	8	50.0%	16	6	62.5%	16	6	62.5%
761		16	2	87.5%	16	2	87.5%	16	3	81.3%	16	3	81.3%
765		16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
769		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
770		16	3	81.3%	16	3	81.3%	16	1	93.8%	16	1	93.8%
774		16	4	75.0%	16	4	75.0%	15	2	86.7%	15	2	86.7%
779		16	2	87.5%	16	2	87.5%	15	0	100.0%	15	0	100.0%
784	35	16	1	93.8%	16	1	93.8%	16	6	62.5%	16	6	62.5%
785		16	0	100.0%	16	0	100.0%	16	3	81.3%	16	3	81.3%
790		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
794		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
821	18	16	2	87.5%	16	2	87.5%	16	10	37.5%	16	10	37.5%
822	274	16	2	87.5%	16	2	87.5%	16	13	18.8%	16	13	18.8%
1333	37	16	0	100.0%	16	0	100.0%	16	9	43.8%	16	9	43.8%
1340		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
2103		12	3	75.0%	12	3	75.0%	12	0	100.0%	12	0	100.0%
2107		12	2	83.3%	12	2	83.3%	11	0	100.0%	11	0	100.0%
2108		12	0	100.0%	12	0	100.0%	12	0	100.0%	12	0	100.0%
2121		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
2122		12	3	75.0%	12	3	75.0%	12	2	83.3%	12	2	83.3%
2124		9	2	77.8%	9	2	77.8%	9	1	88.9%	9	1	88.9%
2150		12	2	83.3%	12	2	83.3%	12	5	58.3%	12	5	58.3%
2151	Cncld	12	0	100.0%	12	0	100.0%	11	0	100.0%	11	0	100.0%
2152		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
2153		12	2	83.3%	12	2	83.3%	12	2	83.3%	12	2	83.3%
2154		12	3	75.0%	12	3	75.0%	11	7	36.4%	11	7	36.4%
2155		12	0	100.0%	12	0	100.0%	10	3	70.0%	10	3	70.0%
2159		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
2162	Cncld	12	0	100.0%	12	0	100.0%	11	0	100.0%	11	0	100.0%
2163		12	0	100.0%	12	0	100.0%	12	1	91.7%	12	1	91.7%
2166		12	0	100.0%	12	0	100.0%	12	2	83.3%	12	2	83.3%
2167		12	1	91.7%	12	1	91.7%	12	1	91.7%	12	1	91.7%

Amtrak On Time Performance

Trains Arriving Through: 10/16/2025

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2168		12	0	100.0%	12	0	100.0%	12	3	75.0%	12	3	75.0%
2169		8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
2170		12	2	83.3%	12	2	83.3%	12	4	66.7%	12	4	66.7%
2172		12	3	75.0%	12	3	75.0%	12	2	83.3%	12	2	83.3%
2173	57	11	2	81.8%	11	2	81.8%	11	3	72.7%	11	3	72.7%
2190	158	12	2	83.3%	12	2	83.3%	12	1	91.7%	12	1	91.7%

Amtrak Endpoint OTP Details

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2151	XHM	Trn Cancelled	DSR	13	DSR	11	NHV-STM	MN	Per bulletin Milepost, 72.6, 40.6, 30, 1,2,4
2162	BOS	Trn Cancelled	ENG	105	ENG	96	MET-MET	AM	Unrecoverable penalty (PCS), 2030, UNABLE TO CLEAR FAULT ON PC2030
2173	WAS	57	CAR	55	CAR	46	MET-MET	AM	Door, 3655 3658, DOOR TROUBLE ON CAR #3655 AND #3658
2190	BOS	158	ENG	167	ENG	167	NHV-XGX	AM	Air / Brake, 2026, the lead power car is out of the dead section and the rear 2029
86	BOS	73	MTI	75	MTI	52	MET-MET	AM	Disabled train ahead, Other, MET, PICKING UP DISABLED AM2162'S PSGRS
95	NFK	40	MTI	49	MTI	49	MET-TRE	AM	Disabled train ahead, Other, XCY, PICKING UP DISABLED AM2151'S PSGRS
172	BOS	25	HLD	29	OTH	8	NWK-NYP	AM	Lost time - N.A.R.
173	WAS	41	PTI	42	PTI	12	NLC-NHV	AM	Meet, 172, Milepost w/Letters, NLC, NHV, AM173 met AM172 at Crescent
190	BOS	28	MTI	33	MTI	27	NHV-NLC	AM	Disabled train ahead, Milepost, xm4, xgu, behind 2190 the lead power car is out
486	GFD	43	CON	54	CON	50	NHV-NHV	AM	Hold for connecting train, AM486 dp a/c of late connection of AM86
639	PHL	12	MTI	7	MTI	7	EWR-MET	AM	Disabled train ahead, Other, XIS-MET, PLATFORMED OFF 1TRK AT METROPARK AFTER NJ3880 CLEARED A/C AM2173 DISABLED ON 4TRK
640	NYP	12	OTH	20	CTI	7	CWH-TRE	AM	Follow, SE, SE703, Other, CWH-XMO
645	HAR	27	MTI	17	MTI	17	NWK-TRE	AM	Disabled train ahead, Other, NWK-TRE, OPR 4 TRK A/C AM2151 DISABLED ON 3 TRK AT COUNTY
646	NYP	30	MTI	17	MTI	17	PJC-NWK	AM	Disabled train ahead, Other, XCY-XUN, CONGESTION A/C AM2162 DISABLED IN METROPARK
647	HAR	20	PTI	15	PTI	7	EWR-TRE	AM	Follow, 2121, Other, XLT-XH1, FLWD AM2121 ON 3TRK
19	NOL	37	FTI	29	FTI	18	TCL-MEI	NS	Meet Control Point, breyer, ns 312
680	BON	22	DCS	23	DCS	23	HHL-WOB	MT	Power switch failure Hand line switch. Rule 241, Control Point, FR
685	BRK	42	DSR	23	RTE	14	SAO-POR	CS	Operate dual control switch at Oil Plant, then proceed with a 241 Switch was open either side, operated to complete the line up for track one to track one, Other, Oil Plant

Amtrak Endpoint OTP Details

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
688	BON	46	PTI	30	PTI	20	POR-SAO	CS	Meet Amt 687, Control Point, surf
63	TWO	27	DCS	31	DCS	31	SDY-XHF	AM	Restrictive signal(s) from unknown cause Stop and proceed, Milepost, 160, 169
64	ALB	31	HLD	25	HLD	25	NFS-NFS	XC	High passenger count Many people with many heavy bags
68	NYP	23	FTI	40	FTI	40	SLQ-RSP	DH	Meet 529, Control Point, 191
237	ALB	63	SYS	36	SYS	36	NYP-NYP	AM	Re-crew / job briefing, CREW CONFUSION
241	ALB	16	CTI	6	CTI	6	NYP-XSD	AM	Cross Traffic, MN, NA, Other, XSD-XSD, MNRR TRAIN RTED AHD
283	NFL	28	CON	37	CON	37	NYP-NYP	AM	Hold for connecting train, HELD F/PSGRS OFF AM86
284	NYP	49	DCS	51	DCS	27	XHF-SDY	AM	Power switch failure Control Point, 169
43	PGH	39	MTI	46	MTI	46	NWK-TRE	AM	Disabled train ahead, Other, XCY, AM95 PICKING UP DISABLED AM21151'S PSGRS AHD
71	CLT	54	DMW	48	DMW	48	DNC-GRO	NS	Held for or routed around MW work or equipment Broken rail, Milepost, 34.1, 31.7
72	RGH	25	ITI	29	ITI	29	CLT-CLT	NS	Service, turn, or wye train 71, Also a lot of mobility impaired customers
73	CLT	24	FTI	14	FTI	14	KAN-CLT	NS	Follow Control Point, Shamrock, NS 28N
76	RGH	19	FTI	13	FTI	13	KAN-GRO	NS	Follow #NS119, Control Point, Lake
77	CLT	17	PTI	15	PTI	15	HPT-SAL	NS	Meet Held at Sharp for 76 to come up 2 and cross over in front of us. Didn't pass anything on 1 between there and Spencer., #Amt76, Control Point, Sharp
41	MIA	70	FTI	91	DCS	26	XH6-XPI	NS	PTC system failure Communication failure between PTC and switch @487, Milepost, 487, 487
25	NOL	27	DCS	17	DCS	17	BAS-XNO	CS	PTC system failure Penalty stop, PTC messages was status unknown , train didn't go into emergency. Called double a and ptc. Got permission from both parties. Went restricted speed until the next signal mp 777, Milepost, 775.0, 777
6	CHI	48	PTI	114	PTI	45	XNV-XSZ	UP	Meet Take the siding, AMT 5, Siding, Stauffer
522	SAC	16	ENG	24	ENG	24	OKJ-OKJ	UP	Unrecoverable penalty (PCS) PCS light wouldn't go off had to do numerous class 2 and reset PTC, C8308
527	SJC	13	TRS	13	TRS	13	SUI-MTZ	UP	Near-miss Milepost, 44, 43.7

Amtrak Endpoint OTP Details

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
528	SAC	25	MBO	18	MBO	18	MTZ-SUI	UP	For maritime traffic Control Point, rv033
532	SAC	15	MBO	25	MBO	25	MTZ-SUI	UP	For maritime traffic Milepost w/Letters, vista, vista
545	OKJ	14	DCS	21	DCS	21	FFV-SUI	UP	Power switch failure Take switch in hand throw., Control Point, RV052
51	CHI	57	ENG	62	ENG	62	IND-IND	CS	Air / Brake Brake cylinder would not go higher than 44. Dumped air multiple times, checked other engines, engine 517 was set for lead but in third position. Independent brake was cut in, but signed off on. Did engine brake test on all units, set and release. Left 520, 150
502	SEA	40	FTI	37	FTI	25	KEL-CTL	BN	Meet Control Point, vader, bnsf6750
509	PDX	21	DCS	10	DCS	10	CTL-KEL	BN	Movement planner had us on track 2 we were on track one needing to cross over to 2 for our station stop at kelso Control Point, ostrander
516	VAC	275	ENG	280	ENG	265	SEA-SEA	BN	Engine swap WDTX 1408 to AMTK 158 due to many issues. Wye at Stacy prior to departure due to non Canadian compliant Engine 158. WS1408
517	PDX	17	CCR	14	CCR	14	STW-EVR	BN	Air / Brake / Wheel 7910, Air dumped 3x leaving Stanwood. No known reason. Air tests, then departed. Never lost door closed light.
519	SEA	67	ITI	67	ITI	67	VAC-VAC	BN	Service, turn, or wye train 518, Late arrival due to WDTX1408 being removed due to mechanical failure. Engine 158 was added in Seattle after a significant delay.
58	CHI	427	ENG	383	ENG	205	MEM-MEM	CC	Fuel pump failure on engine 61. CN mechanical replaced the fuel pump in about 20min. We were instructed to send Cond. and engineer to get a freight engine to put in the lead as precaution. 61, CN2257
14	SEA	43	SVS	58	SVS	58	KEL-CTL	BN	Pick up equipment Add sleeper car 32064 to consist., Other, Rocky Point
8	CHI	92	FTI	163	FTI	47	GGW-WPT	BN	Meet BNSF 7640 W, BNSF 6085 W, Siding, Oswego

Amtrak Endpoint OTP Details

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
821	FTW	18	DSR	24	DSR	18	GLE-FTW	BN	Per bulletin Milepost, 410.8, 410.5, 60, m, Milepost, 409.1, 409.0, 30, m, Milepost, 406.0, 405.8, 60, m, Milepost, 404.0, 403.8, 60, m, Milepost, 399.9, 399.8, 40, m, Milepost, 394.1, 393.8, 30, m, Milepost, 393.0, 392.9, 60, m, Milepost, 389.7, 389.5, 40, m, Milepost, 386.0, 385.3, 60, m, Milepost
822	OKC	274	FTI	256	FTI	218	PVL-PVL	BN	Freight train broke down and was hanging out on the main blocking us bnsf 6886, Other, PVL
365	CHI	30	DSR	25	TRS	17	XH6-XTF	NS	Bridge strike by a vehicle or boat Control Point, 518
564	SAN	Trn Cancelled							
572	SAN	17	DMW	16	DMW	9	XRJ-FUL	BN	Waiting for MW clearance Milepost, 147.0, 148.2
784	SAN	35	CTI	35	CTI	10	OSD-OSD	SN	Meet Coaster, 645, Control Point, Escondido Jct.
703	SAC	24	FTI	17	FTI	13	MOD-XSK	BN	Meet Control Point, hashaw, oakdale, BNSF
712	BFD	41	RTE	19	RTE	19	MOD-TRK	BN	Stop signal at E. Denair After waiting for the freight train to pass, we got a stop signal at E. Denair because the dispatcher failed to inform the change of crew known we were shuffling., Siding, Denair
718	BFD	No OS Rpt	TRS	203	TRS	203	SKN-MOD	BN	Trespasser strike Milepost, 1120.4, 1120.4
719	OKJ	80	POL	92	POL	58	MOD-SKN	BN	RR blocked by trespasser or vehicle strike by another train
4	CHI	40	FTI	82	FTI	30	KNG-FLG	BN	Follow Met two Westbound's at Chalender., Unknown, Milepost, 513.1, 502.9
22	CHI	216	DSR	91	DMW	52	MCG-CBR	BN	Waiting for MW clearance Form b 6159. Foreman was hard to hear on radio. Had to get close to his limits and prepare to stop short until we could hear him, Milepost, 256.6, 256.6
302	CHI	27	FTI	8	FTI	8	BNL-PON	UP	Meet UP 7384, Siding, Pon
305	STL	29	FTI	24	FTI	24	BNL-BNL	UP	Meet Freight, Milepost, 124, 124
391	CDL	Trn Cancelled	ENG	35	ENG	17	HMW-HMW	CC	Traction motor Reboot engine, ID4611
392	CHI	Trn Cancelled							
318	CHI	21	ENG	29	PTI	10	DWT-JOL	UP	Meet amtk305, Control Point, Hitt

Amtrak Endpoint OTP Details

26-FOI-0004800000004859"UNCLASSIFIED"10/20/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
319	KCY	36	FTI	47	FTI	37	WAR-LEE	UP	Follow up 7826, Milepost w/Letters, war, lee
1333	MSP	37	RTE	29	RTE	17	GLN-XRO	ME	Stopped at A20 single tracking waiting our turn to crossover 1-2 Control Point, A20

Amtrak Initial Terminal Details

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/16/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	72	10/16	29	29	Service, turn, or wye train 71, Also a lot of mobility impaired customers
CLT	80	10/16	8	8	Wait for station track Ant 20, Other, Charlotte Station
HAR	624	10/16	1		
HAR	658	10/16	1		
NFK	138	10/16	4	4	Bridge was up upon arriving. No marine traffic was visible. Bridge didn't start going down until 2 minutes before departure. Bridge, 5
NPN	186	10/16	1		
WAS	114	10/16	2	2	Delay in Block, APPLIED HANDBRAKE DISCOVERED AT DP TIME
WAS	182	10/16	3	3	Delay in Block, CNDR DELAYED BOARDING WITH CUSTOMER SERVICE UNTIL 9:12 AM.
WAS	2154	10/16	2	2	Door, 3656, RESETTING DOORS ON CAR #5(3656)
BON	687	10/16	1		
BOS	85	10/16	30	30	Planned set out / pick out of locomotives, cars or section of train, Equipment swaps
BOS	93	10/16	11	11	Waiting for MW clearance, Other, SHSY, LATE FROM YARD
BOS	137	10/16	15	15	Service, turn, or wye train, 190, LATE TURN AT 190
BOS	171	10/16	19	19	Door, 82531, 171 has swapped equipment with 93 due to door issues on C/82531
GFD	479	10/16	12		
NHV	486	10/16	54	50	Hold for connecting train, AM486 dp a/c of late connection of AM86
NHV	486	10/16	54	4	Hold for connecting train, held for late connection of AM86
NHV	486	10/16	54	50	Hold for connecting train, AM486 dp a/c of late connection of AM86
NHV	486	10/16	54	4	Hold for connecting train, held for late connection of AM86
NHV	494	10/16	8	8	Wheelchair, special service request for psngr in a wheelchair
NYP	19	10/16	12	12	Door, 00000, LATE F/SSYD A/C UNSPECIFIED DOOR PROBLEMS
NYP	43	10/16	4	4	Enforcement of carry-on baggage policy, NECESSARY F/PSGR TO CHECK BICYCLE IN BAGGAGE CAR
NYP	129	10/16	7	7	Cross over or go around, 237, Other, NYP-NYP, OUT LATE A/C NECY TO SWING AM237 FROM 14TRK TO 5TRK THRU LINE 1
NYP	185	10/16	3	3	Passenger and/or baggage, BOARDING
NYP	237	10/16	36	36	Re-crew / job briefing, CREW CONFUSION
NYP	243	10/16	5	6	Re-crew / job briefing, LATE FROM SSYD A/C WAITIED FOR A CREW TO GET ON TRAIN
NYP	283	10/16	37	37	Hold for connecting train, HELD F/PSGRS OFF AM86

Amtrak Initial Terminal Details

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/16/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	2107	10/16	2	2	Passenger and/or baggage, LATE BOARDING PSGRS
CDL	392	10/16	(Trn Cxld)		Locomotive Failure
CHI	50	10/16	7	7	PTC problem or failure (cause unknown)
CHI	59	10/16	11	11	Service, turn, or wye train 58, Late inbound train AMTK 58 late turn of equipment. Train set pulled into CUS late.
MKE	332	10/16	1	1	Service, turn, or wye train 329
SEA	8	10/16	29	29	Water, commissary, toilet/trash dumping
SEA	516	10/16	265	265	Engine swap WDTX 1408 to AMTK 158 due to many issues. Wye at Stacy prior to departure due to non Canadian compliant Engine 158. WS1408
BFD	713	10/16	1		
GTA	770	10/16	2	2	PTC- I-ETMS Red Fence/Signal Status Unknown Red fence while shoving out of the spur, Control Point, S Elwood
LAX	564	10/16	(Trn Cxld)		car failure
LAX	580	10/16	1		
OKJ	522	10/16	24	24	Unrecoverable penalty (PCS) PCS light wouldn't go off had to do numerous class 2 and reset PTC, C8308
OKJ	718	10/16	1		
SAN	779	10/16	1	1	Gave highball at 12:00:20. No response. Gave again. Engineer responded after 1 with apparent radio volume issue.
VAC	519	10/16	67	67	Service, turn, or wye train 518, Late arrival due to WDTX1408 being removed due to mechanical failure. Engine 158 was added in Seattle after a significant delay.

Eastern Region

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	98.8	94.8	309	1
CDOT	95.0	95	96.7	92.4	20	1
MARC	95.0	93	90.9	83.5	57	4
SEPTA	95.0	93	93.7	91.5	214	15
NJT-NED	95.0	83	92.9	93.8	370	63
NJT-SED	95.0	100	99.4	97.2	24	0

Operating Highlights

Train 2173(16) South of Newark, DE - Debris

17OCT25: Next generation Acela 2173(16) reportedly struck a deer 7 miles south of Newark, DE on the Amtrak PW Line at milepost 46.0. The train did not take any exceptions and there were no damage or injuries.

Train 20(16) South of Atlanta, GA - Freight Train Interference

17OCT25: Train 20(16) operating with engines 306, 171, and 8 cars was delayed 9 miles south of Atlanta, GA on the Norfolk Southern Atlanta North District meeting Norfolk Southern 153-16 at Jackmac milepost 143.0 and Howell Wye milepost 635.0.

Train	Delay	Comment
20(16)	42"	

Train 2173(16) Metro Park, NJ - Car Failure

16OCT25: At 9:00 p.m. next generation Acela 2173(16) operating with power car 2133, 9 cars, and power car 2124 was delayed departing Metro Park, NJ due to 1 door trouble on cars 3655 and 3658. An onboard Alstom technician worked with the Alstom technician in office at CNOC to attempt to resolve the issue. Superintendent of mechanical was enroute to the scene as was the local road forman from New York. In addition, multiple trains were impacted and delayed due to available track to work. At 9:50 p.m. the crew was able to reset the doors and secure them properly. 2173(16) departed Metro Park at 9:50 p.m.

Train	Delay	Comment
657(16)	13"	
639(16)	07"	
138(16)	04"	
2173(16)	46"	

16OCT25: Due to late 28:FOI-00048 on 00000004859 original document 10/20/2025 UNCLASSIFIED" presenting 237(16), a different set was moved up in the yard to represent the train and optimally mitigate delay to departure. The move up in equipment caused train 237(16) to depart New York Penn Station at 5:21 p.m.

Train	Delay	Comment
237(16)	36"	

Train 63(16) North of Buffalo, NY - Near Miss

16OCT25: At 4:31PM, Train 63(16), E/127-5 Cars, Engineer placed the train emergency 8.2 miles north of Buffalo, NY/MP1.9, on the CSX Niagara Subdivision, at MP10.1 to avoid striking a trespasser on the tracks. The Conductor reported a young trespasser walking on the tracks who jumped away in time. No strike occurred. There were no injuries to the crew or passengers and no damage to the equipment. At 4:37PM, air was restored and Train 63(16) continued north.

Train	Delay	Comment
63(16)	06"	

Train 41(15) Fredericksburg, VA - Police Related

16OCT25: Train 41(15) made a special stop at the Fredericksburg, VA station/MP59.3, on the CSX RF&P Subdivision, to meet police for the removal of an unruly passenger onboard.

Train	Delay	Comment
41(15)	55"	

Train 68(16) Rouses Point, NY - Freight Train Interference

16OCT25: Train 68(16) was delayed 0.5 miles south of Rouse Point, NY/MP191.1, on the CNRR Canadian Subdivision, at CPC191/MP190.6 meeting CP 529.

Train	Delay	Comment
68(16)	40"	

Train 94(16) South of Petersburg, VA - B&B Work Due to Defect

16OCT25: Train 94(16) held 1.4 miles south of Petersburg, VA/MP22.0, on the CSX North End Subdivision, at MP23.4 waiting for B&B to finish repair of the Appomattox Bridge at MP23.2. Once the bridge was seated and locked, Train 94(16) was released to continue north.

Train	Delay	Comment
94(16)	31"	

Train 2162(16) Metropark, NJ - Engine Failure

16OCT25: At 11:45AM, Train 2162(16) was disabled with 282 passengers onboard at the Metropark, NJ station/MP23.2, on the Amtrak NYP Line, due to an unrecoverable fault on power car 2030. Train 86(16) was able to close in behind Train 2162(06) to allow one of their doors on to the platform to receive and discharge passengers. 280 of the 282 passengers onboard 2162(16) were transferred to Train 86(16) to continue through to Boston. The two remaining passengers, one ADA and their companion, stayed on until New York. Head end power was on for the duration. The crew and High Speed Rail Mechanical worked to troubleshoot the issue. Amtrak Transportation Management responded to the train to assist. At 1:27PM, Train 2162(16) was on the move to New York arriving at 2:05PM, 1 hour and 41 minutes late. The train was then terminated with the last two passengers moved to the next available eastbound Train 2168(16) to their final destination of Boston. The equipment deadheaded back to Washington to balance the fleet after 7:00PM.

Train 283(16) was delayed departing New York due to hold for the 23 passenger connections from Train 86(16) that arrived at 1:45PM, 1 hour and 30 minutes late.

Train 486(16) was delayed departing New Haven, CT holding for the passenger connections from Train 86(16) that arrived at 3:37PM, 1 hour and 18 minutes late.

Train	Delay	Comment
2162(16)	1'36"	MET
2162(16)	09"	MET-NWK
2162(16)	TERM NYP	
86(16)	1'15"	
283(16)	37"	ITD NYP
114(16)	21"	
486(16)	54"	ITD NHV

Train 63(16) and 284(16) West of Schenectady, NY - M of W Work

16OCT25: Trains 63(16) and 284(16) were both delayed west of Schenectady, NY/MP159.8, on the Amtrak Hudson Line, between CP169/MP169.9 and CP161/MP169.7. CSX Maintenance of Way was completing surfacing work at CP169 which affected the signals at CP169 and the automatics on the single main track. As a result, both trains had to receive a Rule 241 at CP169 and then the automatics were reported as stop and proceed through the area. Later, when Train 48(15) operated through the area, the Engineer reported that all signals were working as intended.

Train 237(16) was delayed departing New York, NY as a result of Train 284(16). Equipment for Train 239(16) was moved up from the yard to the station to represent Train 237(16). Once the passengers were loaded onto the new set, Train 237(16) departed New York at 5:23PM, 38 minutes late.

Train	Delay	Comment
284(16)	51"	
237(16)	38"	
63(16)	36"	Witronix

16OCT25: At 9:40AM, Train 2151(16) was delayed on the Amtrak NYP Line at County/MP32.8 with both main circuit breakers (MCBs) open on power cars 2012 and 2013 with no head end power onboard. County is located 24 miles west of Newark, NJ/MP8.8 on the Amtrak NYP Line. There were 262 passengers onboard with weather reported 55 degrees and sunny. The crew worked with their Road Foreman to try and resolve. At 9:45AM, the Engineer reported both MCBs were closed and head end power was restored however the trainset experienced air issues.

The crew walked the train to try and locate the cause. Upon inspection, they found a broken inner car air hose. Believed to have resolved the issue, the crew tried to build air but was unsuccessful. Due to the ongoing issues, Train 2151(16) was terminated at location. 261 of the 262 passengers were transferred with standee conditions onto Train 95(16) through to final. The train to train transfer started at 11:25AM and commenced at 12:00PM. The one remaining passenger suffered a panic attack was taken by APD to where they needed to go. Amtrak Transportation Management and APD was onsite to assist. Rescue E/618 was dispatched to train, tacked on, and deadheaded the equipment through to New York for repair.

WBS#: B.TR.100151.0783

Train	Delay	Comment
2151(16)	TERM NWK	
84(16)	04"	
2159(16)	09"	
125(16)	10"	
95(16)	49"	
119(16)	12"	
2155(16)	05"	
2153(16)	02"	
185(16)	04"	
43(16)	46"	
609(16)	05"	
645(16)	17"	
646(16)	17"	
644(16)	10"	
643(16)	05"	

Train 171(16) Boston, MA - Car Failure

16OCT25: Train 171(16) was delayed departing Boston, MA/MP228.7, on the Amtrak NHB Line, after C/82531 was bad ordered for door issues. To try and minimize delay, equipment was moved up which led to initial terminal delays also to Trains 93(16) and 85(16).

Train	Delay	Comment
171(16)	19"	ITD BOS
93(16)	11"	ITD BOS
85(16)	30"	ITD BOS

Train 71(16) West of Durham, NC - Broken Rail

16OCT25: Train 71(16) held 23.6 miles west of Durham, NC/MP55.2, on the NSRR Goldsboro-Greensboro Subdivision, at Mebane/MP31.6 due to a reported broken rail at MP27.6. Maintenance of Way responded to bar up the defect and place a 25MPH speed restriction over the area. Once this was complete, Train 71(16) was back on the move west.

Train 72(16) was delayed departing Charlotte, NC/MP376.0, on the NSRR Charlotte District, due to a late turn of 71(16)'s equipment that arrived at 10:22AM, 54 minutes late.

Train	Delay	Comment
71(16)	51"	
72(16)	29"	ITD CLT

Train 2190(16) East of New Haven, CT - Engine Failure

16OCT25: At 7:18AM, Train 2190(16) Trainset #120, with 210 passengers onboard became disabled at the Branford dead section with no head power around MP81.4. Located 8.8 miles east of New Haven, CT/MP72.3, on the Amtrak NHB Line. The lead power car 2026 was out of the dead section but the rear power car 2029 was in it. The crew was unable to restore head end power to the trainset. The weather was 43 degrees and partly cloudy. All passengers stayed on the train for the duration with onboard conditions reported comfortable. Transportation management responded to the train. E/600, with mechanical onboard, was dispatched from New Haven departing at 8:32AM to hook on and move the equipment out of the dead section to restore head end power. At 10:00AM, E/600 was added, head end power restored, and the train was on the move east through to Boston. High Speed Rail was able to utilize trainset #12 in Boston for an on-time turn of Train 2163(16).

Train	Delay	Comment
2190(16)	2'47"	
190(16)	33"	

Downeaster Trackwork CSX Portland Sub-M of W Work

22SEP25: Downeaster Service Adjustments due to CSX Portland Subdivision trackwork between Brunswick, ME and Boston North, MA station. They are welding , switch timbers and tie pickup between Wells, MA and Brunswick on the following Tuesday thru Thursday from 8A-ET to 530P-ET. On September 30,2025 to October 02,2025, October 7-9, 2025, October 14-16, 2025, October 21-23, 2025, October 28-30, 2025 and November 4-6, 2025. The following service adjustments will be made:

Northbound:

- Train 681(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BON and BRK, will terminate at WEM.
- Train 683(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BON and BRK is cancelled in its entirety with no alternate transportation.

Southbound:

- Train 684(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BRK and BON, is cancelled in its entirety with no alternate transportation.
- Train 686(30Sep-20Oct, 70Oct-90Oct, 140Oct-160Oct, 210Oct-230Oct, 280Oct-300Oct, 4Nov-6Nov), which normally operates between BRK and BON, will originate at WEM.

WBS#: B.TR.100151.0776

Train	Delay	Comment
681	TERM WEM	WITH ALT TRANS
684	CANCELLED	NO ALT TRANS
686	ORIG WEM	WITH ALT TRANS
683	CANCELLED	NO ALT TRANS

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(02JUN-26JUL) terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02JUN-28JUL) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

22APR25: Amtrak MRS-26-FOI-000481-000000048591 UNCLASSIFIED track 10/20/2025 between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

• Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

• Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

• Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-30Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27Oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

• Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

• Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

• Bus 3470 will provide alternate transportation between HFD and SPG

• Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

• Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

• Deadhead Train 426 will turn for Train 471 at HFD

• Train 470 will turn for Train 473 at HFD

Eastern Region

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 69(16) Passenger Removal at St. Lambert, Quebec – Customs***

16OCT25, Passenger on PNR BB9160, traveling from New York, NY to Montreal, QC was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 69(16) None

Train 79(16) Passenger Removal at Rocky Mount, North Carolina –Improper Conduct

16OCT25, Passenger on PNR 869AC2, traveling from Newark, NJ to Wilson, NC was removed from the train by Rocky Mount PD. The passenger used their cellular phone on speakerphone. The passenger was asked to headphones and refused. Amtrak Police notified.

Delay: 79(16) None

Train 97(16) Passenger Removal at Richmond Staples Mill Rd, Virginia –Medical

16OCT25, Passenger on PNR C2FD39, traveling from Wilmington, DE to Kingstree, SC was removed from the train by Lakeside EMS. The passenger became sick vomiting on the carpet after he had consumed an unknown substance. Amtrak Police notified.

Delay: 97(16) None

Operating Highlights***Train 40(15) East of Alliance, OH - Freight Train Interference***

17OCT25: Train 40(15) was delayed at MP PC81.9 on the Norfolk Southern Conway West Subdivision, 1 mile east of the Alliance, OH station due to 12N-16 stopped with a broken coupler. NSRR Mechanical had responded to assist in replacing the coupler.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(15)	1'01"	

Train 14(16) East of Martinez, CA - Drawbridge Opening

16OCT25: Train 14(16) was delayed at Vista / MP 32.8 on the Union Pacific Martinez Subdivision, 1 mile east of the Martinez, CA station due to the Suisun Bay Bridge opening for maritime traffic.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(16)	30"	

Train 3(15) West of Flagstaff, AZ - Engine Failure

16OCT25: Train 3(15), operating with Locomotive 179, Locomotive 40 and 9 cars, was delayed at MP 378.0 on the Burlington Northern Santa Fe Seligman Subdivision, 34 miles west of the Flagstaff, AZ station, account of a locked axle alarm on trail Locomotive 40. The crew inspected and found the wheel rolling freely. They were instructed by CNOC Mechanical to cut out the traction motor and continue but BNSF Mechanical held the train until their personnel could inspect the equipment. BNSF responded, inspected the equipment and took no exception.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(15)	1'50"	

Train 6(15) Denver, CO - Engine Failure

16OCT25: Train 6(15), operating with Locomotive 60, Locomotive 164, 8 cars and Locomotive 205 was delayed departing the Denver, CO Union station, due to setting out Locomotive 205 for failing the calendar day inspection and flat-switching locomotive 60 to the trail position account of radio failure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(15)	2'25"	

Train 48(16) West of South Bend, IN - Freight Train Interference

16OCT25: Train 48(16) was delayed between CP 479 / MP CD479.3 and CP 466 / MP CD466.6 on the Norfolk Southern Elkhart West Subdivision, starting 41 miles west of the South Bend, IN station, following 216-16.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48(16)	35"	

Train 718(16) East of Stockton, CA - Fatal Trespasser Strike

16OCT25: At approximately 7:00 PM PDT, "UNCLASSIFIED" 718(16) struck and fatally injured a trespasser 1 mile east of Stockton Station, MP 1120.4 on Stockton Subdivision, BNSF Railroad. The incident did not occur at a designated rail crossing in San Joaquin County. There were no reported injuries to crew or 149 passengers on board the train. There was no reported damage to the train. The weather was reported as dark, clear with a temperature of 61 degrees. The track speed is 60mph. Locomotive CDTX/2107 provided Head End Power for the duration of the incident. The train crew requested and was granted relief at the scene. Stockton Police and Fire Department responded and investigated the incident. Amtrak Merced Road Foreman of Engines and Amtrak Police Officer responded to assist the investigation.

Service Recovery: San Joaquins service offers complimentary snacks and canned soft drinks.

Amtrak Police and EAP advised.

California Office of Emergency Services report:25-2575

National Response Center Number: 1445648

Train	Delay	Comment
718(16)	3'23"	
719(16)	1'32"	

Train 822(16) South of Pauls Valley, OK - Freight Train Interference

16OCT25: Train 822(16) was delayed at Pauls Valley siding / MP 495.3 on the Burlington Northern Santa Fe Red Rock Subdivision, just south of the Pauls Valley, OK station, due to GBETEAP9-12 (BNSF 6886) disabled with a portion of the train on single main track. The freight train had compressor failure on two of its locomotives. Rescue locomotive was set off from a freight train nearby to assist.

Once cleared, Train 822(16) followed the assisting freight train to Oklahoma City.

Train	Delay	Comment
822(16)	3'43"	

Train 319(16) West of Warrensburg, MO - Freight Train Interference

16OCT25: Train 319(16) was delayed at Centerview / MP 225.5 on the Union Pacific Sedalia Subdivision, miles west of the Warrensburg, MO station, performing a "saw-by" move to get around a 11,467-foot long MASNP-16 (UPRR 7826).

Train	Delay	Comment
319(16)	37"	

Train 14(15) North of Kelso, WA - Picking-Up Sleeper Car

16OCT25: Train 14(15) was delayed at Rocky Point Siding Track, MP 95.8 BNSF Seattle Subdivision, 2 miles North of Kelso, WA. This was to add sleeper car C/32064. The Sleeper Car had originally been removed from train 14(09) for reporting hot bearings. After adding the car with the necessary safety test completed train 14(15) continued to Olympia.

Train	Delay	Comment
14(15)	58"	

Train 6(16) at Seattle - Initial Terminal Delay - Waste Tanks

16OCT25: Train 8(16) was delayed at the maintenance facility while waiting for sewage truck to arrive to empty waste tanks. The truck was delayed in baseball event traffic in downtown Seattle. Once the tanks had been emptied and function restored, the train was able to depart the facility to board passengers in Seattle King Street station.

Cause: Pending

Train	Delay	Comment
8(16)	29"	SEA - ITD

Train 8/28(15) West of Havre, MT - Freight Train Interference

16OCT25: Train 8/28(15) was delayed at MP432, 2 miles west of Havre, MT, on the BNSF Milk River Subdivision, due to BNSF freight ahead with mechanical issues. Train 8/28(15) was delayed holding for BNSF freight to resolve issue and clear route ahead.

Train	Delay	Comment
8/28(15)	1'03"	

Train 22(16) North of McGregor, TX - Freight Train Interference

16OCT25: Train 22(16) was delayed north of McGregor, TX/MP243.5, on the BNSF Fort Worth Subdivision, following BNSF 7379 between Manhattan/MP253.6 and Blum/MP302.4. BNSF reported congestion through the area following previous bridge strike and engine set-out at Manhattan.

Train	Delay	Comment
22(16)	44"	

Train 21(16) South of Chicago, IL - Freight Train Interference

16OCT25: Train 21(16) was delayed at Corwith/MP6.6, 6 miles south of Chicago, IL, on the CN Joliet Subdivision, waiting on freight cross-traffic to clear ahead.

Train	Delay	Comment
21(16)	1'34"	

Train 6(16) East of Colfax, CA - Freight Train Interference

16OCT25: Train 6(16) was delayed at east Colfax - MP 141.96, Roseville Subdivision, Union Pacific Railroad - waiting for Union Pacific freight train UPRR/5462 to clear the crossover switches ahead. With the tracks clear train 6(16) continued for 30 miles to Switch 9, (MP 171.2) to allow for Union Pacific train UPRR/7494 to pass on the single track. Once the track was cleared train 6(16) continued to Truckee.

Train	Delay	Comment
6(16)	1'03"	

Train 27(14) East of Wishram, WA - Signal

16OCT25: Train 27(14) was delayed at W. Whitcomb/MP169.3, 61 miles east of Wishram, WA, on the BNSF Fallbridge Subdivision, due to signal issues. Train 27(14) was talked by signal at MP169.3 and then operated on restricting signals to MP161.

Train	Delay	Comment
27(14)	31"	

16OCT25: Train 6(15) 26-FOI-00048 00000004859 MP483 UNCLASSIFIED 10/20/2025 34 miles west of Grand Junction, CO, on the UPRR Green River Subdivision, due to inability to contact dispatcher due to radio dead zone at Utaline/MP483. Signal maintainer responded and was able to assist with communications to UPRR dispatcher regarding a track indication ahead. Train 6(15) was then further delayed flagging signals between MP472 and MP470.

Train	Delay	Comment
6(15)	1'14"	

Train 516(16) Late Departure Seattle, WA - Engine

16OCT25: Train 516(16), CC/90251-3 cars-E/WDTX1408, was delayed departing Seattle, WA, due to mechanical replacing a bad order sensor and the battery panel on E/WDTX1408. Train 516(16) was further delayed departing Seattle due to issues with the ongoing repairs to E/WDTX1408. It was necessary to return equipment to yard to cut-off E/WDTX1408 and replace with E/158. Train 516(16) wyeed equipment to depart Seattle CC/90251 lead due to E/158 Canada non-compliant.

Train	Delay	Comment
516(16)	15"	Wye (turn) Train approaching Vancouver, BC
516(16)	4'24"	SEA - ITD
519(16)	1'07"	VAC - ITD Equipment from 516(16)

Train 391(16) Terminated Effingham, IL - Engine

16OCT25: Train 391(16), E/IDTX4611 & 7 cars, reported loading and traction motor issues south of Chicago, IL, on the CN Chicago Subdivision. Train 391(16) was delayed at Homewood, IL/MP23.5 while crew contacted mechanical to troubleshoot. Train 391(16) was able to restore No 3 and No 4 traction motors and proceeded south. As precaution, busses were ordered to shadow train enroute. Train 391(16) was delayed at Effingham, IL/MP199.22, on the CN Champaign Subdivision, due to E/IDTX4611 shut-down upon arrival. Crew contacted mechanical and found battery charger tripped on E/IDTX4611. After troubleshooting with mechanical, E/IDTX4611 was restarted and HEP restored. Due to the ongoing enroute engine issues, Train 391(16) terminated at Effingham. Train held for the shadow bus to arrive on location. Once passengers were reaccommodatd on the bus, equipment deadheaded to Carbondale.

Train 392(16) was cancelled, with alternate transportation between Carbondale and Chicago. Equipment planned to deadhead to Chicago after mechanical inspection at Carbondale.

WBS#: B.TR.100150.6181

Train	Delay	Comment
391(16)	35"	S/CHI-EFG
391(16)	Terminated	EFG
392(16)	Cancelled	

Train 527(16) West of Suisun-Fairfield, CA - Trespasser Incident

16OCT25: Train 527(16), E/CDTX2106-3 cars-C/8302, stopped in emergency at MP44.10, 5 miles west of Suisun-Fairfield, CA, on the UPRR Martinez Subdivision, due to a near miss with a pick-up truck. There were no reported injuries to passengers or crew. The crew inspected consist and took no exceptions. Train 527(16) was on the move west after crew restored air and performed class 2 brake test. APD notified.

Train	Delay	Comment
527(16)	13"	
11(15)	21"	DAV-MTZ Follow 527(16)

Train 7/27(15) East of Fargo, ND - Freight Train Interference

16OCT25: Train 7/27(15) was delayed 39 minutes at Warrensburg, MO, 10 miles east of Fargo, ND, on the BNSF KO Subdivision, due to BNSF 8354 ahead with air brake faults. Train 7/27(15) held for BNSF 8354 to resolve issue and clear route into Fargo station track.

Train	Delay	Comment
7/27(15)	39"	

Union Pacific Sedalia Subdivision East of Warrensburg, MO - Freight Train Derailment

17OCT25: At approximately 1:30 a.m. (CDT), Union Pacific reported CWNLA9-16 (UPRR 2725) derailed several empty coal cars on single main track at MP 208.0 on the Sedalia Subdivision 10 miles east of the Warrensburg, MO station. The cars were upright. There was no estimated track opening. As a result, the following operating plan was placed into effect:

Train 311(16) with 219 affected passengers and Train 316 with 143 affected passengers were canceled in their entirety.

Train 318(16) with 385 affected passengers originate in St. Louis, MO (canceled from Kansas City, MO and St. Louis, MO)

Train 319(16) with 211 affected passengers terminated in St. Louis MO (canceled from St. Louis, MO and Kansas City, MO).

At the time of publication, attempts are being made to secure buses to provide alternate transportation.

WBS#: B.TR.100150.6183

Train 528(16) East of Martinez, CA - Marine Traffic

16OCT25: Train 528(16) was delayed 1 mile east of Martinez at Vista MP 33.0 Martinez subdivision of the Union Pacific Railroad. The structure was raised to allow for the passage of marine traffic. Once the vessels had cleared, the bridge was lowered and train 528(16) was able to continue to Suisun..

Train	Delay	Comment
528(16)	18"	
532(116)	25"	

Trains 564(16) & 577(16) Cancelled - Car Failure

16OCT25: Train 564(16), E/CDTX2120 & 5 cars, was cancelled due to no power on the second car business class C/6804 and mechanical unable to resolve issue. Passengers were reaccommodated on Train 566(16) between Los Angeles and San Diego. Train 577(16) was also cancelled, with passengers accommodated on Train 779(16) between San Diego and Los Angeles. Equipment originally scheduled to operate on Train 564(16) returned to Los Angeles yard for repairs and was then utilized for Train 582(16).

Train	Delay	Comment
564(16)	Cancelled	
577(16)	Cancelled	

Train 50(07) North O Dye, IN - Engine Failure

07OCT25: Train 50(07)26-FOI-00048 en 10000004859 518,"UNCLASSIFIED" and 10/20/2025 9 cars, and 119 passengers, stopped at Roosevelt Ave/MP.74 0.74 miles from Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to difficulty pulling the equipment. The crew inspected the equipment and found the brakes not releasing on axles 2 and 4 on the engine 377. Chicago Mechanical met the train to assist and, after extensive troubleshooting, the decision was made to return to Chicago, IL and remove engine 377 from the consist. After the equipment was made up complete the second time, train 50(07) departed Chicago, IL.

16OCT25: Train 50(16), operating with Locomotive 150, Locomotive 377 (non-revenue) and 5 cars, stopped at MP CD 521.3 on the Norfolk Southern Chicago Terminal Subdivision, 6 miles east of the Chicago, IL Union station, after the brakes on axle #2 and #4 on Locomotive 377 would not release. Attempts to release the brakes were unsuccessful. Amtrak Chicago Mechanical responded to scene and was able to release the brakes. The train made a reverse move back to the Chicago Union Station before setting out Locomotive 377. There were 103 passengers onboard during the disruption.

Switching out of Locomotive 377 off Train 50(16) was delayed while waiting for EMS to respond to the Chicago Union station account of a passenger medical emergency. The passenger was removed and taken to a local area hospital.

WBS#: B.TR.100150.6162

Train	Delay	Comment
50(07)	3'18"	
50(16)	6'23"	

04OCT25: At 2:39PM-MT, 6(03) operated with E/205-E/182-E/377-8 Cars, reported striking a rock 40.3 miles east of Glenwood Springs, CO/MP360.1, on the UPRR Glenwood Springs Subdivision, on a single main track at MP144.63. As a result of the strike, the main reservoir valve on E/205 was damaged causing the main reservoir to not hold or build. The rock was reported 1.5x2 feet in diameter and was broken into pieces after striking. There were no injuries reported to the crew or 172 passengers onboard. Head end power was on for the duration. The Union Pacific Track Inspector responded to the location arriving at 4:00PM-MT. At 4:44PM-MT train 6(03) held at Dell siding/MP142.0 meeting Amtrak train 1005(03). Before shoving out of Dell siding, train 6(03) set out lead engine 205 at mile post 142.4.

Train 6(03) was further delayed at Fraser, CO waiting for a recrew.

Train 6(03) was delayed at Denver, CO. as crews worked to add UP freight UP/5859. The freight engine was declined after the crew encountered air issues and then managed to resolve the PTC issue on lead engine 182.

Due to the late operation of train 6(03) the following service recovery was put into effect:

- First class passenger meals were unaffected.
- Snack packs and water were distributed to all passengers.
- Lounge car offered coffee, tea, and juice as well as discounted and comp items as needed.
- Breakfast snack items were sent to Denver, CO Station for AM service.

05OCT25: Train 6(03) was delayed departing the Holdrege, NE station, waiting for the relief crew and BNSF pilots.

16OCT25: Train 6(16) was delayed adding Locomotive 205 to the rear position after it had been repaired. Locomotive 205 was then set out in Denver, CO Union Station account it would not pass the Calendar Day test.

WBS#: B.TR.100150.6156

Train	Delay	Comment
6(03)	3'13"	
6(03)	1'30"	HLD - Relief Crew and BNSF Pilots
6(03)	1'57"	Recrew at Fraser
6(03)	1'09"	Attempted to add freight at DEN
6(15)	1'13"	Pick Up L/205

26-FBI-07048 00000004859 "UNCLASSIFIED" 10/20/2022

May 5th through June 26th (except for May 26th and June 19th):

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 350 (Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

WBS#: B.TR.100150.5512

Train	Delay	Comment
350 & 353 (27MAY - 29MAY)	Cancel	
350 & 353 (16JUN - 18JUN)	Cancel	
350 & 353 (23JUN - 26JUN)	Cancel	
350 & 353 (04AUG - 07AUG)	Cancel	
350 & 353 (11AUG - 14AUG)	Cancel	
350 & 353 (18AUG - 21AUG)	Cancel	
350 & 353 (25AUG - 28AUG)	Cancel	
350 & 353 (02SEP - 04SEP)	Cancel	
350 & 353 (08SEP - 11SEP)	Cancel	
350 & 353 (15SEP - 18SEP)	Cancel	
350 & 353 (22SEP - 25SEP)	Cancel	
350 & 353 (29SEP - 02OCT)	Cancel	
350 & 353 (06OCT - 09OCT)	Cancel	
350 & 353 (13OCT - 16OCT)	Cancel	
350 & 353 (20OCT - 23OCT)	Cancel	
350 & 353 (27OCT - 30OCT)	Cancel	

19MAY24, Commencing 12:00PM-PT, 00000004859 Court UNCLASSIFIED 10/20/2025
 Project will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:

from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

- Sunday August 4 - Tuesday August 6
- Sunday August 11 - no extended window account Padres game
- Sunday August 18th - Tuesday 20th
- Sunday August 25 - Tuesday August 27
- Sunday September 8 - Tuesday September 10.
- Sunday September 15 - Monday September 16
- Sunday September 22 - Tuesday September 24.
- Sunday October 27 - Tuesday October 29.
- Sunday November 3 - Tuesday November 5.
- Sunday December 8-Tuesday December 10.
- Sunday December 15-Tuesday December 17.
- 2025
- Sunday February 9 - Tuesday February 11.
- Sunday April 06th - Tuesday April 08th (CANCELLED)
- Sunday May 20 - Tuesday May 22
- Sunday July 20th - Tuesday July 22nd
- Sunday August 3rd - Tuesday August 5th
- Sunday August 10th - Tuesday August 12th
- Sunday August 24th - Tuesday August 26th
- Sunday October 5th - Tuesday October 7th.
- Sunday October 12th - Tuesday October 14th.

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Western Region

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
6 (3)	DEN	205		Boulder strike

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
58 (15)	MEM	IC9625	Rescue into MEM station	MEM	10/16/25
58 (15)	MEM	CN2257	E/61 Fuel pump/starter, deliver BRP 10/18/25	CHI	10/16/25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
14	SLM	1	PDX B1F717	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 1(15) Passenger Removal at Alpine, Texas – Improper Behavior

16OCT25, Passenger on PNR BF8CEC, traveling from San Antonio, TX to Los Angeles, CA was removed from the train by local Police for touch and threatening another passenger. Amtrak Police notified.

Delay: 1(15) None

Train 3(15) Passenger Removal at Albuquerque, New Mexico – Intoxication

16OCT25, Passenger on PNR C069FB, traveling from Newton, KS to Los Angeles, CA was removed from the train by Albuquerque PD. The passenger was intoxicated and drinking personal alcohol. The passenger became aggressive getting in the car attendants face. Amtrak Police notified.

Delay: 3(15) None

Train 5(16) Passenger Removal at Galesburg, Illinois – Improper Conduct

16OCT25, Passenger on PNR BF17DD, traveling from Chicago, IL to Omaha, NE was removed from the train by the conductor. The passenger jumped onto a moving train. Amtrak Police notified.

Delay: 5(16) 20"

Train 4(15) Passenger Removal at Albuquerque, New Mexico –Other

26-FOI-00048 00000004859 UNCLASSIFIED 10/20/2025

16OCT25, Passenger on PNR C10B0E, traveling from San Bernardino, CA to Kansas City, MO was removed from the train by the conductor. The passenger had a personal hygiene issue. The passenger was given a chance to correct the issue by the conductor. The passengers' clothing held a foul odor, and they had no change of clothing. Amtrak Police notified.

Delay: 4(15) None

Train 50(16) Passenger Removal at Chicago, Illinois –Medical

16OCT25, Passenger on PNR AD222E, traveling from Chicago, IL to Indianapolis, IN, was removed from the train by the Chicago Fire Department. The passenger possibly had a heart attack. Amtrak Police notified.

Delay: 50(16) None

Consist Deviations

26-FOI-00048

00000004859

"UNCLASSIFIED"

10/20/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
48 (15)	CHI	VII sleeper in lieu of a VI for the 4812 car. Schedule change performed.	Passenger will be moved to another room	1	62522
329 (16)	CHI	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			ID4209
332 (16)	CHI	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
331 (17)	CHI	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
335 (17)	CHI	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
339 (17)	CHI	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
343 (17)	CHI	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
40 (16)	MIA	VII sleeper in lieu of VI. two less revenue rooms. schedule change performed.	One passenger moved to another room. 2 passenger downgraded.	3	62506
336 (16)	MKE	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
330 (17)	MKE	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
334 (17)	MKE	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
338 (17)	MKE	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209
342 (17)	MKE	49-seat coach used in lieu of 68-seat coach. train is not overcapacity.			id4209

Reverse Consists

Train Number	Station	Reason	
		26-FOI-00048 00000004859 "UNCLASSIFIED"	10/20/2025
134 (16)	RNK	Consist reversed Business class seat orientation may have changed At Front	
86 (16)	RVM	Consist reversed Business class seat orientation may have changed At Front	
86 (17)	RVM	Consist reversed Business class seat orientation may have changed At Front	
2154 (16)	WAS	Acela consist reversed First class at Front	
110 (16)	PHL	Consist reversed Business class seat orientation may have changed At Rear	
185 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front	
176 (16)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
133 (16)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
93 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front Due equip swaps	