



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, July 17, 2026

Rules: 2-39



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/16/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	36	88.4%	4,870	722	85.2%	85,728	11,767	86.3%
Central Division	86.0%	56	3	94.6%	873	88	89.9%	16,321	1,436	91.2%
East Division	82.0%	162	23	85.8%	2,557	441	82.8%	45,143	7,053	84.4%
West Division	86.0%	92	10	89.1%	1,440	193	86.6%	24,264	3,278	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00603 00000008328 UNCLASSIFIED Endpoint Arrival Dates through 7/16/26 7/21/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	107,473	42,990	60%	1,688,536	628,087	63%	28,635,860	7,102,373	75%
Northeast Corridor	81%	44,855	16,225	64%	724,324	282,830	61%	12,568,105	3,066,023	76%
Acela	83%	11,126	4,393	61%	161,003	62,509	61%	2,497,768	665,186	73%
Northeast Regional	79%	33,729	11,832	65%	563,321	220,321	61%	10,070,337	2,400,837	76%
Richmond / Newport News / Norfolk	77%	9,416	4,421	53%	175,115	85,094	51%	3,125,843	898,715	71%
Springfield Shuttles	89%	861	331	62%	10,381	3,294	68%	178,415	27,508	85%
Roanoke	79%	4,914	2,754	44%	54,150	25,378	53%	947,210	200,663	79%
On Spine Northeast Regional	80%	18,538	4,326	77%	323,675	106,555	67%	5,818,869	1,273,951	78%
State Supported	80%	48,981	17,456	64%	757,829	211,273	72%	12,543,877	2,573,637	79%
Borealis	80%	578	2	100%	9,556	2,101	78%	160,526	32,547	80%
Capitol Corridor	90%	4,224	262	94%	60,569	9,821	84%	1,061,788	139,017	87%
Carolinian	70%	475	467	2%	16,955	11,026	35%	326,929	126,932	61%
Cascades	75%	2,820	1,191	58%	49,912	12,793	74%	737,556	201,353	73%
Downeaster	82%	2,034	308	85%	30,609	7,770	75%	428,107	53,240	88%
Empire	78%	6,368	3,184	50%	96,987	36,203	63%	1,550,992	350,620	77%
Adirondack	72%	372	291	22%	6,789	3,185	53%	93,222	28,669	69%
Ethan Allen Express	70%	574	541	6%	9,225	6,221	33%	160,190	53,828	66%
Maple Leaf	70%	910	463	49%	13,829	5,705	59%	188,648	72,492	62%
New York - Albany	85%	3,149	1,107	65%	43,259	10,597	76%	720,424	114,497	84%
New York - Niagara Falls	75%	1,363	782	43%	21,807	9,089	58%	383,266	78,868	79%
Berkshire Flyer	60%	0	0	-	2,078	1,406	32%	5,242	2,266	57%
Gold Runner	73%	2,311	566	76%	41,804	16,599	60%	715,424	248,697	65%
Heartland Flyer	70%	251	105	58%	4,390	2,237	49%	60,095	22,730	62%
Hiawatha	90%	2,126	161	92%	31,500	2,228	93%	489,194	52,776	89%
Illinois	78%	2,779	1,710	38%	41,082	14,977	64%	703,237	191,021	73%
Carl Sandburg / Illinois Zephyr	85%	457	341	25%	7,537	2,666	65%	117,091	30,472	74%
Illini / Saluki	85%	801	678	15%	14,274	4,906	66%	247,936	58,933	76%
Lincoln Service	70%	1,521	691	55%	19,271	7,405	62%	338,210	101,616	70%
Keystone	92%	9,480	698	93%	113,987	18,696	84%	2,171,064	228,631	89%
Lincoln / Missouri	70%	873	622	29%	11,088	6,393	42%	219,607	110,209	50%
Mardi Gras Service	80%	443	20	95%	6,555	2,445	63%	117,503	24,906	79%
Michigan	70%	1,881	918	51%	36,939	15,461	58%	556,686	180,416	68%
Blue Water	70%	712	348	51%	9,445	6,442	32%	129,671	51,776	60%
Pere Marquette	85%	574	284	51%	5,348	1,267	76%	72,920	14,597	80%
Wolverine	70%	595	286	52%	22,146	7,752	65%	354,095	114,043	68%
Missouri	80%	275	115	58%	2,724	1,093	60%	61,960	14,333	77%
Pacific Surfliner	85%	9,238	5,923	36%	158,654	32,291	80%	2,241,178	359,453	84%
Pennsylvanian	80%	910	69	92%	14,360	5,895	59%	253,070	48,054	81%
Piedmont	80%	612	526	14%	10,534	4,177	60%	323,919	82,731	74%
Vermont	75%	1,303	609	53%	19,624	9,067	54%	365,042	105,971	71%
Long Distance	70%	13,637	9,309	32%	206,383	133,984	35%	3,484,611	1,460,250	58%
Auto Train	70%	771	371	52%	13,231	5,366	59%	222,075	76,194	66%
California Zephyr	70%	1,042	957	8%	16,361	10,884	33%	276,424	96,181	65%
Cardinal	70%	598	445	26%	4,066	2,884	29%	67,740	33,126	51%
City Of New Orleans	75%	655	417	36%	2,906	2,246	23%	180,270	51,863	71%
Coast Starlight	70%	1,178	502	57%	20,137	6,532	68%	324,901	110,984	66%
Crescent	70%	965	398	59%	15,206	9,036	41%	265,699	81,128	69%
Empire Builder	70%	1,191	920	23%	19,951	13,051	35%	273,012	131,803	52%
Floridian	60%	1,499	1,246	17%	25,077	23,636	6%	455,242	307,279	33%
Lake Shore Ltd	73%	1,107	744	33%	18,940	8,577	55%	270,577	80,187	70%
Palmetto	70%	1,170	659	44%	14,186	10,215	28%	261,959	76,313	71%
Silver Meteor	70%	991	842	15%	17,007	14,225	16%	289,388	124,377	57%
Southwest Chief	60%	998	990	1%	16,277	12,195	25%	234,927	150,607	36%
Sunset Ltd	70%	0	0	-	5,251	3,213	39%	83,636	29,894	64%
Texas Eagle	70%	1,472	818	44%	17,787	11,924	33%	278,761	110,314	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FOI-00000 00000000020 "UNCLASSIFIED" 7/21/2020

Train Index Dates Through July 16, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	110,854	1,681,841	659	1,677,787	30,312,926	553

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	5,930	494,484	120	79,270	8,702,981	91
INFRASTRUCTURE PLANNED	135	8,062	494,484	163	86,934	8,702,981	100
FLEET RELIABILITY	90	16,900	1,681,841	100	269,889	30,312,926	89
TRAIN OPERATIONS	424	79,962	1,681,841	475	1,241,694	30,312,926	410

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/16/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	36	88.4%	4,870	722	85.2%	85,728	11,767	86.3%
Central Division	86.0%	56	3	94.6%	873	88	89.9%	16,321	1,436	91.2%
East Division	82.0%	162	23	85.8%	2,557	441	82.8%	45,143	7,053	84.4%
West Division	86.0%	92	10	89.1%	1,440	193	86.6%	24,264	3,278	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/16/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	36	88.4%	4,870	722	85.2%	85,728	11,767	86.3%
Central Division	86.0%	56	3	94.6%	873	88	89.9%	16,321	1,436	91.2%
CDL	95.0%	2	0	100.0%	30	3	90.0%	547	21	96.2%
CHI	86.0%	27	1	96.3%	410	45	89.0%	7,404	865	88.3%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	16	1	93.8%	312	35	88.8%
GBB	-	1	1	0.0%	7	6	14.3%	7	6	14.3%
GRR	95.5%	1	0	100.0%	15	0	100.0%	274	8	97.1%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	23	2	91.3%	561	42	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	94	6	93.6%	1,692	103	93.9%
MOE	97.5%	2	0	100.0%	32	1	96.9%	577	9	98.4%
MSP	96.5%	1	0	100.0%	16	0	100.0%	282	5	98.2%
NOL	94.5%	4	0	100.0%	61	6	90.2%	1,211	59	95.1%
OKC	97.0%	1	0	100.0%	16	0	100.0%	283	6	97.9%
PNT	88.0%	1	0	100.0%	39	4	89.7%	742	62	91.6%
PTH	93.0%	1	0	100.0%	16	1	93.8%	277	11	96.0%
QCY	91.0%	1	0	100.0%	22	3	86.4%	553	43	92.2%
SAS	90.5%	1	1	0.0%	16	2	87.5%	285	29	89.8%
STL	89.0%	4	0	100.0%	59	7	88.1%	1,116	97	91.3%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	162	23	85.8%	2,557	441	82.8%	45,143	7,053	84.4%
ALB	88.5%	8	1	87.5%	124	7	94.4%	2,138	168	92.1%
ATL	-	-	-	-	-	-	-	35	5	85.7%
BON	87.5%	5	2	60.0%	79	12	84.8%	1,391	152	89.1%
BOS	85.5%	14	0	100.0%	263	15	94.3%	4,899	576	88.2%
BRK	92.5%	5	0	100.0%	76	13	82.9%	1,377	97	93.0%
BTN	82.0%	1	0	100.0%	16	1	93.8%	275	40	85.5%
CLT	91.5%	4	3	25.0%	62	14	77.4%	1,403	146	89.6%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	32	4	87.5%	563	54	90.4%
GRO	-	1	0	100.0%	4	0	100.0%	33	10	69.7%
HAR	79.5%	13	0	100.0%	169	23	86.4%	3,192	529	83.4%
HFD	-	2	0	100.0%	22	4	81.8%	169	12	92.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	16	1	93.8%	285	35	87.7%
MIA	89.5%	2	0	100.0%	31	3	90.3%	570	63	88.9%
MTR	79.0%	1	0	100.0%	16	4	75.0%	272	50	81.6%

Information Management

26-FOI-0060 Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/16/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	36	88.4%	4,870	722	85.2%	85,728	11,767	86.3%
East Division	82.0%	162	23	85.8%	2,557	441	82.8%	45,143	7,053	84.4%
NFK	84.5%	2	0	100.0%	32	9	71.9%	653	118	81.9%
NFL	93.5%	2	0	100.0%	32	3	90.6%	582	25	95.7%
NFS	-	1	1	0.0%	1	1	0.0%	7	6	14.3%
NHV	78.0%	5	1	80.0%	77	14	81.8%	1,483	237	84.0%
NPN	93.0%	2	0	100.0%	30	3	90.0%	543	38	93.0%
NYP	75.5%	47	10	78.7%	724	181	75.0%	11,775	2,642	77.6%
PGH	93.0%	1	0	100.0%	16	3	81.3%	287	22	92.3%
PHL	48.0%	5	0	100.0%	79	34	57.0%	1,479	711	51.9%
PIT	76.0%	-	-	-	4	4	0.0%	10	9	10.0%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	2	0	100.0%	42	5	88.1%	1,099	46	95.8%
RNK	83.5%	2	1	50.0%	32	5	84.4%	566	82	85.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	13	0	100.0%	272	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	14	0	100.0%	282	10	96.5%
SFA	88.0%	1	0	100.0%	16	1	93.8%	285	38	86.7%
SPG	92.5%	5	1	80.0%	76	6	92.1%	1,728	98	94.3%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	-	-	-	15	1	93.3%	274	57	79.2%
WAS	84.0%	26	3	88.5%	440	66	85.0%	7,033	907	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	92	10	89.1%	1,440	193	86.6%	24,264	3,278	86.5%
ARN	92.0%	1	0	100.0%	16	4	75.0%	287	23	92.0%
BFD	79.0%	7	1	85.7%	107	24	77.6%	1,793	365	79.6%
EMY	72.0%	1	1	0.0%	16	7	56.3%	303	93	69.3%
EUG	86.5%	2	0	100.0%	32	0	100.0%	568	52	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	1	50.0%	3	2	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	48	13	72.9%	864	127	85.3%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	0	100.0%	167	15	91.0%	2,599	258	90.1%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	3	76.9%	189	55	70.9%	3,088	791	74.4%
PDX	86.0%	5	0	100.0%	80	5	93.8%	1,417	171	87.9%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	0	100.0%	240	21	91.3%	4,045	431	89.3%

Information Management

26-FOI-006 Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/16/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	310	36	88.4%	4,870	722	85.2%	85,728	11,767	86.3%
West Division	86.0%	92	10	89.1%	1,440	193	86.6%	24,264	3,278	86.5%
SAN	90.5%	13	2	84.6%	207	16	92.3%	3,451	310	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	128	16	87.5%	2,270	326	85.6%
SJC	89.0%	7	1	85.7%	112	13	88.4%	2,019	195	90.3%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	48	2	95.8%	627	62	90.1%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	16	1	93.8%	282	21	92.6%
VAC	97.0%	2	0	100.0%	32	0	100.0%	562	14	97.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	122	16	2	87.5%	287	56	80.5%	16	7	56.3%	285	124	56.5%
4	89	16	1	93.8%	286	43	85.0%	16	10	37.5%	286	189	33.9%
5	73	16	2	87.5%	285	45	84.2%	15	12	20.0%	281	75	73.3%
6	105	16	7	56.3%	284	84	70.4%	16	11	31.3%	284	93	67.3%
7		16	2	87.5%	276	37	86.6%	16	6	62.5%	269	67	75.1%
8	326	16	8	50.0%	276	119	56.9%	16	13	18.8%	275	162	41.1%
11	117	16	3	81.3%	287	53	81.5%	16	3	81.3%	281	57	79.7%
14		16	2	87.5%	288	43	85.1%	16	2	87.5%	286	85	70.3%
19		16	8	50.0%	286	73	74.5%	16	10	37.5%	284	69	75.7%
20		16	4	75.0%	286	22	92.3%	16	9	43.8%	286	56	80.4%
21		16	0	100.0%	283	22	92.2%	16	11	31.3%	282	73	74.1%
22		16	2	87.5%	284	27	90.5%	16	11	31.3%	282	73	74.1%
23		16	1	93.8%	289	6	97.9%	16	8	50.0%	287	77	73.2%
24		16	2	87.5%	289	16	94.5%	16	6	62.5%	288	49	83.0%
25		16	0	100.0%	288	3	99.0%	16	6	62.5%	286	75	73.8%
26		16	0	100.0%	288	5	98.3%	16	5	68.8%	286	57	80.1%
27	75	16	3	81.3%	274	17	93.8%	16	7	56.3%	270	88	67.4%
28	31	16	2	87.5%	270	61	77.4%	16	2	87.5%	270	53	80.4%
40	71	15	2	86.7%	281	40	85.8%	15	13	13.3%	280	145	48.2%
41	71	15	8	46.7%	281	110	60.9%	15	15	0.0%	279	211	24.4%
42		16	3	81.3%	288	23	92.0%	16	6	62.5%	286	48	83.2%
43		16	1	93.8%	287	42	85.4%	16	9	43.8%	287	65	77.4%
48		16	3	81.3%	286	56	80.4%	16	3	81.3%	286	41	85.7%
49	93	16	4	75.0%	286	71	75.2%	16	7	56.3%	286	59	79.4%
51	156	7	3	57.1%	119	52	56.3%	7	5	28.6%	115	42	63.5%
52	67	16	1	93.8%	285	38	86.7%	16	5	68.8%	284	66	76.8%
53		16	1	93.8%	285	35	87.7%	16	5	68.8%	284	90	68.3%
55		11	0	100.0%	179	6	96.6%	11	3	72.7%	176	37	79.0%
56		11	0	100.0%	180	22	87.8%	10	5	50.0%	176	31	82.4%
58	39	6	0	100.0%	265	16	94.0%	5	4	20.0%	263	69	73.8%
59	43	4	1	75.0%	262	29	88.9%	4	4	0.0%	259	50	80.7%
63	93	16	9	43.8%	289	126	56.4%	15	13	13.3%	284	153	46.1%
64	28	16	2	87.5%	287	65	77.4%	16	9	43.8%	287	100	65.2%
66		16	4	75.0%	286	58	79.7%	14	2	85.7%	282	51	81.9%
67		11	1	90.9%	198	12	93.9%	11	3	72.7%	198	34	82.8%
68	23	16	4	75.0%	289	59	79.6%	16	9	43.8%	289	112	61.2%
69	41	16	3	81.3%	276	62	77.5%	16	7	56.3%	272	39	85.7%
71	16	16	0	100.0%	284	3	98.9%	16	9	43.8%	283	75	73.5%
72		12	1	91.7%	280	30	89.3%	12	3	75.0%	279	58	79.2%
73	46	11	2	81.8%	283	18	93.6%	11	6	45.5%	281	132	53.0%
74	124	11	2	81.8%	281	32	88.6%	11	7	36.4%	279	101	63.8%
77	63	11	3	72.7%	280	20	92.9%	11	8	27.3%	278	116	58.3%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78	15	16	5	68.8%	284	25	91.2%	16	10	37.5%	283	60	78.8%
79	78	16	0	100.0%	286	55	80.8%	16	12	25.0%	285	96	66.3%
80	58	16	5	68.8%	286	33	88.5%	15	8	46.7%	283	57	79.9%
85	18	11	0	100.0%	181	16	91.2%	11	5	54.5%	181	66	63.5%
86		11	1	90.9%	181	15	91.7%	11	8	27.3%	180	108	40.0%
89	35	16	5	68.8%	284	63	77.8%	16	11	31.3%	282	81	71.3%
90		16	0	100.0%	284	10	96.5%	16	11	31.3%	283	48	83.0%
93	36	11	0	100.0%	180	18	90.0%	11	6	45.5%	179	43	76.0%
94	48	11	3	72.7%	211	53	74.9%	11	8	27.3%	209	77	63.2%
95	62	11	1	90.9%	180	4	97.8%	11	6	45.5%	180	65	63.9%
97	49	16	14	12.5%	286	187	34.6%	16	13	18.8%	284	89	68.7%
98	57	16	1	93.8%	286	22	92.3%	16	15	6.3%	284	95	66.5%
110		11	4	63.6%	177	100	43.5%	11	2	81.8%	174	18	89.7%
111		11	0	100.0%	171	32	81.3%	11	1	90.9%	169	21	87.6%
112		11	0	100.0%	171	16	90.6%	11	2	81.8%	170	19	88.8%
113		11	1	90.9%	102	23	77.5%	11	1	90.9%	101	12	88.1%
125		11	2	81.8%	181	10	94.5%	11	5	54.5%	181	71	60.8%
129		11	2	81.8%	180	46	74.4%	11	2	81.8%	180	25	86.1%
130		11	1	90.9%	171	17	90.1%	11	1	90.9%	169	16	90.5%
131		11	5	54.5%	173	52	69.9%	11	6	45.5%	173	35	79.8%
134	32	11	3	72.7%	181	24	86.7%	11	5	54.5%	180	31	82.8%
136		11	3	72.7%	181	23	87.3%	11	4	63.6%	179	21	88.3%
137		11	2	81.8%	178	32	82.0%	11	3	72.7%	178	55	69.1%
138	168	11	3	72.7%	181	38	79.0%	11	6	45.5%	180	33	81.7%
141		11	0	100.0%	180	3	98.3%	11	2	81.8%	179	30	83.2%
148	43	11	1	90.9%	180	18	90.0%	11	4	63.6%	178	34	80.9%
151	174	16	4	75.0%	285	90	68.4%	16	9	43.8%	284	93	67.3%
170		11	0	100.0%	176	12	93.2%	11	0	100.0%	175	29	83.4%
171	58	11	0	100.0%	181	10	94.5%	11	9	18.2%	181	70	61.3%
172		11	0	100.0%	180	14	92.2%	11	4	63.6%	178	59	66.9%
174	21	11	0	100.0%	181	20	89.0%	11	6	45.5%	181	44	75.7%
175	28	11	0	100.0%	181	21	88.4%	11	3	72.7%	181	58	68.0%
177		11	1	90.9%	181	25	86.2%	11	0	100.0%	181	44	75.7%
178	84	11	0	100.0%	181	24	86.7%	11	4	63.6%	179	27	84.9%
179	23	11	2	81.8%	181	21	88.4%	11	6	45.5%	180	64	64.4%
181		11	1	90.9%	177	55	68.9%	11	2	81.8%	175	14	92.0%
182		11	1	90.9%	171	29	83.0%	11	2	81.8%	169	18	89.3%
183		11	3	72.7%	180	51	71.7%	11	2	81.8%	178	35	80.3%
184		11	3	72.7%	181	32	82.3%	11	4	63.6%	180	27	85.0%
185	23	11	1	90.9%	181	37	79.6%	11	2	81.8%	181	13	92.8%
186	58	11	1	90.9%	180	18	90.0%	11	5	54.5%	179	45	74.9%
190	20	11	2	81.8%	180	64	64.4%	11	3	72.7%	179	40	77.7%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
192	17	11	4	63.6%	178	23	87.1%	11	2	81.8%	178	16	91.0%
197	23	11	4	63.6%	181	72	60.2%	11	8	27.3%	181	61	66.3%
198		11	3	72.7%	113	17	85.0%	11	3	72.7%	112	19	83.0%
230		16	0	100.0%	123	4	96.7%	16	0	100.0%	123	6	95.1%
232		16	0	100.0%	289	11	96.2%	16	0	100.0%	289	17	94.1%
233	60	12	3	75.0%	263	59	77.6%	12	9	25.0%	263	82	68.8%
234		16	1	93.8%	289	20	93.1%	16	0	100.0%	289	24	91.7%
235	56	16	2	87.5%	213	29	86.4%	16	6	62.5%	213	47	77.9%
236		16	1	93.8%	273	8	97.1%	16	2	87.5%	273	38	86.1%
237		16	2	87.5%	287	54	81.2%	16	5	68.8%	285	48	83.2%
238		16	0	100.0%	213	19	91.1%	16	1	93.8%	212	15	92.9%
239		16	4	75.0%	288	76	73.6%	16	4	75.0%	287	34	88.2%
240		16	0	100.0%	288	20	93.1%	16	7	56.3%	286	51	82.2%
241		16	4	75.0%	289	72	75.1%	16	3	81.3%	289	69	76.1%
243		16	6	62.5%	225	61	72.9%	16	4	75.0%	224	30	86.6%
244	26	12	2	83.3%	263	12	95.4%	12	6	50.0%	263	44	83.3%
245	56	16	4	75.0%	170	31	81.8%	16	3	81.3%	169	20	88.2%
280	60	16	2	87.5%	289	13	95.5%	16	3	81.3%	289	53	81.7%
281		16	3	81.3%	289	32	88.9%	16	7	56.3%	289	54	81.3%
283		16	4	75.0%	289	68	76.5%	16	7	56.3%	289	59	79.6%
284	32	16	1	93.8%	289	11	96.2%	16	9	43.8%	287	51	82.2%
290	56	16	1	93.8%	289	49	83.0%	16	12	25.0%	287	103	64.1%
291	17	16	8	50.0%	288	83	71.2%	16	9	43.8%	286	67	76.6%
300		16	1	93.8%	273	20	92.7%	16	8	50.0%	271	64	76.4%
301		16	0	100.0%	287	9	96.9%	16	3	81.3%	284	53	81.3%
302		10	1	90.0%	268	32	88.1%	10	3	70.0%	264	75	71.6%
305	43	10	0	100.0%	271	28	89.7%	10	7	30.0%	267	109	59.2%
306	19	16	0	100.0%	285	15	94.7%	16	6	62.5%	284	77	72.9%
307	19	16	3	81.3%	277	38	86.3%	16	7	56.3%	274	77	71.9%
311		13	2	84.6%	284	25	91.2%	12	5	58.3%	278	55	80.2%
316	127	12	1	91.7%	280	17	93.9%	11	6	45.5%	276	70	74.6%
318	64	15	4	73.3%	287	30	89.5%	15	11	26.7%	284	135	52.5%
319	99	15	1	93.3%	288	18	93.8%	12	8	33.3%	283	153	45.9%
329		12	0	100.0%	204	8	96.1%	12	0	100.0%	204	13	93.6%
330		14	0	100.0%	245	4	98.4%	14	1	92.9%	245	14	94.3%
331		16	1	93.8%	289	30	89.6%	16	1	93.8%	289	41	85.8%
332		16	2	87.5%	289	16	94.5%	16	3	81.3%	289	42	85.5%
334		16	0	100.0%	289	9	96.9%	16	1	93.8%	288	37	87.2%
335		16	0	100.0%	289	30	89.6%	16	3	81.3%	287	46	84.0%
336		16	1	93.8%	289	9	96.9%	16	2	87.5%	287	27	90.6%
337		16	1	93.8%	289	18	93.8%	16	2	87.5%	285	35	87.7%
338	20	16	3	81.3%	289	44	84.8%	16	6	62.5%	287	87	69.7%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
339		16	2	87.5%	289	48	83.4%	16	2	87.5%	289	50	82.7%
341		16	3	81.3%	278	38	86.3%	16	2	87.5%	273	37	86.4%
342		16	0	100.0%	289	21	92.7%	16	2	87.5%	287	55	80.8%
351	98	16	2	87.5%	272	27	90.1%	16	5	68.8%	270	73	73.0%
352		16	0	100.0%	256	20	92.2%	16	4	75.0%	250	75	70.0%
354	Cncld	16	6	62.5%	270	34	87.4%	13	7	46.2%	263	96	63.5%
364		16	2	87.5%	278	62	77.7%	16	10	37.5%	272	100	63.2%
365	70	16	1	93.8%	277	11	96.0%	16	11	31.3%	275	103	62.5%
370		16	1	93.8%	280	34	87.9%	15	3	80.0%	272	68	75.0%
371		15	0	100.0%	274	8	97.1%	15	2	86.7%	273	29	89.4%
380	35	15	3	80.0%	274	27	90.1%	15	7	53.3%	274	56	79.6%
381		14	0	100.0%	287	11	96.2%	14	4	71.4%	286	52	81.8%
382	29	14	6	57.1%	286	22	92.3%	14	8	42.9%	286	92	67.8%
383	45	16	1	93.8%	278	26	90.6%	15	8	46.7%	275	113	58.9%
390	32	16	1	93.8%	271	18	93.4%	16	6	62.5%	270	69	74.4%
391	30	14	1	92.9%	272	9	96.7%	14	5	64.3%	269	70	74.0%
392	29	14	2	85.7%	286	7	97.6%	14	9	35.7%	284	87	69.4%
393	30	16	0	100.0%	289	16	94.5%	16	10	37.5%	286	87	69.6%
417		11	3	72.7%	191	41	78.5%	11	2	81.8%	182	19	89.6%
425		11	0	100.0%	193	6	96.9%	11	0	100.0%	193	7	96.4%
448		16	4	75.0%	219	42	80.8%	16	6	62.5%	217	74	65.9%
449		16	1	93.8%	217	31	85.7%	16	4	75.0%	217	40	81.6%
470		11	1	90.9%	204	35	82.8%	11	1	90.9%	198	24	87.9%
471		11	3	72.7%	194	9	95.4%	11	2	81.8%	194	4	97.9%
473		11	1	90.9%	200	14	93.0%	11	0	100.0%	197	8	95.9%
474	58	14	8	42.9%	198	59	70.2%	11	9	18.2%	183	56	69.4%
475		11	0	100.0%	198	5	97.5%	11	3	72.7%	198	13	93.4%
478	22	11	2	81.8%	192	29	84.9%	11	3	72.7%	190	23	87.9%
479		11	2	81.8%	199	31	84.4%	11	5	54.5%	197	27	86.3%
486		11	1	90.9%	203	29	85.7%	11	4	63.6%	197	54	72.6%
494	35	12	4	66.7%	205	39	81.0%	11	9	18.2%	198	53	73.2%
495		11	0	100.0%	189	3	98.4%	11	0	100.0%	187	3	98.4%
500		16	1	93.8%	280	16	94.3%	15	1	93.3%	277	33	88.1%
502		16	1	93.8%	287	16	94.4%	15	1	93.3%	283	57	79.9%
503	37	16	1	93.8%	285	26	90.9%	16	9	43.8%	279	83	70.3%
504	16	16	0	100.0%	289	17	94.1%	16	4	75.0%	287	86	70.0%
505		16	1	93.8%	287	37	87.1%	15	6	60.0%	282	79	72.0%
506		16	1	93.8%	284	39	86.3%	16	3	81.3%	279	44	84.2%
507		16	1	93.8%	289	35	87.9%	16	4	75.0%	289	92	68.2%
508	40	16	0	100.0%	284	39	86.3%	16	3	81.3%	281	65	76.9%
509	46	16	1	93.8%	286	13	95.5%	16	3	81.3%	286	66	76.9%
511		16	0	100.0%	281	21	92.5%	16	0	100.0%	280	45	83.9%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
516	32	16	1	93.8%	281	28	90.0%	16	3	81.3%	280	126	55.0%
517	17	16	0	100.0%	289	8	97.2%	16	11	31.3%	285	119	58.2%
518	20	16	0	100.0%	289	35	87.9%	16	11	31.3%	287	194	32.4%
519		16	0	100.0%	281	9	96.8%	16	1	93.8%	279	64	77.1%
520		12	0	100.0%	162	24	85.2%	12	0	100.0%	159	9	94.3%
521		12	0	100.0%	200	7	96.5%	12	3	75.0%	200	26	87.0%
522		12	0	100.0%	200	36	82.0%	12	0	100.0%	197	18	90.9%
523		12	0	100.0%	200	6	97.0%	12	0	100.0%	199	22	88.9%
524		12	2	83.3%	200	13	93.5%	12	2	83.3%	198	22	88.9%
525		12	2	83.3%	198	14	92.9%	11	0	100.0%	194	13	93.3%
526		12	4	66.7%	174	33	81.0%	12	2	83.3%	171	14	91.8%
527		12	1	91.7%	200	10	95.0%	12	4	66.7%	199	36	81.9%
528		12	2	83.3%	200	17	91.5%	12	1	91.7%	199	30	84.9%
529		12	0	100.0%	200	11	94.5%	12	3	75.0%	199	53	73.4%
530	29	12	3	75.0%	154	17	89.0%	12	5	58.3%	154	31	79.9%
531		12	0	100.0%	174	12	93.1%	12	2	83.3%	174	13	92.5%
532		12	6	50.0%	200	49	75.5%	12	3	75.0%	199	30	84.9%
534		12	0	100.0%	159	24	84.9%	12	1	91.7%	157	16	89.8%
535		12	1	91.7%	187	24	87.2%	12	1	91.7%	182	21	88.5%
536		12	4	66.7%	200	53	73.5%	11	0	100.0%	196	37	81.1%
537	Cncld	12	2	83.3%	171	20	88.3%	11	2	81.8%	165	18	89.1%
538	14	12	0	100.0%	200	23	88.5%	12	4	66.7%	199	41	79.4%
539	40	12	1	91.7%	154	21	86.4%	12	3	75.0%	154	67	56.5%
540		11	3	72.7%	199	38	80.9%	10	0	100.0%	191	18	90.6%
541		12	0	100.0%	199	21	89.4%	11	1	90.9%	193	34	82.4%
542		12	0	100.0%	199	21	89.4%	12	3	75.0%	197	35	82.2%
543		12	2	83.3%	200	21	89.5%	12	8	33.3%	200	58	71.0%
544		12	0	100.0%	198	20	89.9%	12	2	83.3%	195	17	91.3%
545		12	2	83.3%	200	17	91.5%	11	1	90.9%	197	23	88.3%
547		12	1	91.7%	200	38	81.0%	12	1	91.7%	200	45	77.5%
548		11	1	90.9%	195	21	89.2%	10	0	100.0%	193	14	92.7%
549		12	1	91.7%	195	26	86.7%	11	1	90.9%	187	17	90.9%
550		12	2	83.3%	154	16	89.6%	12	2	83.3%	154	33	78.6%
551		12	0	100.0%	196	19	90.3%	12	0	100.0%	188	17	91.0%
562	40	16	1	93.8%	281	22	92.2%	16	1	93.8%	278	30	89.2%
564	34	16	1	93.8%	281	18	93.6%	16	3	81.3%	273	33	87.9%
566	50	16	1	93.8%	279	18	93.5%	16	3	81.3%	276	35	87.3%
567	56	16	1	93.8%	166	9	94.6%	16	1	93.8%	164	7	95.7%
572	59	16	0	100.0%	276	22	92.0%	15	7	53.3%	270	72	73.3%
573	27	16	0	100.0%	279	40	85.7%	16	2	87.5%	272	46	83.1%
579	22	16	0	100.0%	166	8	95.2%	16	4	75.0%	161	30	81.4%
580		16	0	100.0%	281	14	95.0%	16	2	87.5%	276	23	91.7%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
581	34	16	3	81.3%	281	46	83.6%	16	4	75.0%	279	58	79.2%
584	38	16	4	75.0%	165	21	87.3%	15	12	20.0%	160	94	41.3%
587		15	0	100.0%	275	15	94.5%	15	5	66.7%	266	43	83.8%
588		16	2	87.5%	166	14	91.6%	16	2	87.5%	165	24	85.5%
591		16	0	100.0%	280	18	93.6%	16	1	93.8%	274	30	89.1%
593		16	4	75.0%	275	41	85.1%	15	1	93.3%	256	28	89.1%
595		16	3	81.3%	276	44	84.1%	16	3	81.3%	273	49	82.1%
600		11	0	100.0%	208	9	95.7%	11	2	81.8%	206	17	91.7%
601		11	5	54.5%	191	77	59.7%	11	1	90.9%	188	24	87.2%
605		11	7	36.4%	198	125	36.9%	11	2	81.8%	194	21	89.2%
607		11	4	63.6%	207	28	86.5%	11	3	72.7%	204	25	87.7%
609		11	1	90.9%	198	23	88.4%	11	3	72.7%	197	18	90.9%
622		9	1	88.9%	112	31	72.3%	9	0	100.0%	110	5	95.5%
626	11	11	2	81.8%	112	14	87.5%	11	2	81.8%	110	17	84.5%
639		10	1	90.0%	178	38	78.7%	10	0	100.0%	177	19	89.3%
640		11	0	100.0%	198	7	96.5%	11	2	81.8%	196	78	60.2%
641		11	4	63.6%	180	38	78.9%	11	1	90.9%	180	26	85.6%
642		11	0	100.0%	196	9	95.4%	11	3	72.7%	195	26	86.7%
643		11	1	90.9%	210	40	81.0%	11	1	90.9%	207	33	84.1%
644		11	0	100.0%	202	27	86.6%	11	3	72.7%	200	51	74.5%
645		11	2	81.8%	210	40	81.0%	10	5	50.0%	207	44	78.7%
646	23	11	4	63.6%	199	50	74.9%	11	7	36.4%	197	96	51.3%
647		11	1	90.9%	210	32	84.8%	11	3	72.7%	209	46	78.0%
648		11	2	81.8%	206	52	74.8%	11	2	81.8%	206	33	84.0%
649		11	4	63.6%	211	41	80.6%	11	1	90.9%	208	32	84.6%
650	15	11	0	100.0%	210	39	81.4%	11	3	72.7%	207	33	84.1%
651		11	0	100.0%	210	16	92.4%	11	3	72.7%	208	42	79.8%
652		11	1	90.9%	211	28	86.7%	11	3	72.7%	207	35	83.1%
653	13	11	3	72.7%	199	33	83.4%	11	4	63.6%	196	38	80.6%
654		11	3	72.7%	200	39	80.5%	10	0	100.0%	196	16	91.8%
655		11	2	81.8%	208	71	65.9%	11	3	72.7%	206	71	65.5%
656		11	0	100.0%	210	45	78.6%	11	4	63.6%	209	25	88.0%
657		11	1	90.9%	199	27	86.4%	11	1	90.9%	198	29	85.4%
658		11	0	100.0%	210	34	83.8%	11	1	90.9%	208	31	85.1%
680		12	2	83.3%	205	11	94.6%	12	1	91.7%	204	25	87.7%
681		12	1	91.7%	205	15	92.7%	12	6	50.0%	200	78	61.0%
682		12	0	100.0%	204	5	97.5%	12	3	75.0%	204	36	82.4%
683	11	12	0	100.0%	187	15	92.0%	12	10	16.7%	186	61	67.2%
684		12	4	66.7%	186	31	83.3%	12	4	66.7%	186	42	77.4%
685		12	3	75.0%	201	31	84.6%	12	7	41.7%	198	51	74.2%
686	39	12	3	75.0%	206	36	82.5%	12	7	41.7%	205	43	79.0%
687	15	12	3	75.0%	205	33	83.9%	12	4	66.7%	204	35	82.8%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
688	26	12	4	66.7%	204	13	93.6%	12	6	50.0%	203	36	82.3%
701		16	3	81.3%	221	24	89.1%	16	2	87.5%	218	22	89.9%
702		16	1	93.8%	288	32	88.9%	15	4	73.3%	285	64	77.5%
703		16	8	50.0%	289	85	70.6%	15	8	46.7%	287	78	72.8%
704		16	1	93.8%	220	33	85.0%	15	2	86.7%	214	40	81.3%
710		16	6	62.5%	289	75	74.0%	16	4	75.0%	285	77	73.0%
711		16	3	81.3%	280	31	88.9%	12	1	91.7%	259	46	82.2%
712		16	5	68.8%	286	76	73.4%	15	4	73.3%	277	91	67.1%
713		12	1	91.7%	158	15	90.5%	11	4	63.6%	144	60	58.3%
714		15	9	40.0%	170	67	60.6%	15	8	46.7%	158	66	58.2%
715		16	2	87.5%	288	60	79.2%	13	6	53.8%	266	131	50.8%
716		16	7	56.3%	289	114	60.6%	15	5	66.7%	283	107	62.2%
717		15	2	86.7%	274	64	76.6%	14	6	57.1%	255	76	70.2%
718		16	7	56.3%	289	143	50.5%	16	9	43.8%	287	100	65.2%
719	44	16	5	68.8%	289	93	67.8%	15	6	60.0%	274	78	71.5%
757	61	16	1	93.8%	74	4	94.6%	16	3	81.3%	73	7	90.4%
761	40	16	1	93.8%	285	12	95.8%	16	2	87.5%	282	36	87.2%
765	60	16	0	100.0%	285	24	91.6%	16	1	93.8%	285	37	87.0%
769	39	16	1	93.8%	285	26	90.9%	16	2	87.5%	279	51	81.7%
770	54	16	0	100.0%	285	21	92.6%	16	7	56.3%	283	81	71.4%
774	57	16	0	100.0%	285	16	94.4%	16	5	68.8%	284	61	78.5%
777	20	16	1	93.8%	170	10	94.1%	16	3	81.3%	169	37	78.1%
782		16	13	18.8%	170	69	59.4%	16	2	87.5%	165	17	89.7%
785	27	16	2	87.5%	285	19	93.3%	16	3	81.3%	285	49	82.8%
786	16	16	1	93.8%	74	17	77.0%	16	7	56.3%	73	34	53.4%
790		16	0	100.0%	285	26	90.9%	16	3	81.3%	282	35	87.6%
794		16	1	93.8%	285	32	88.8%	16	3	81.3%	282	58	79.4%
821	15	16	0	100.0%	283	6	97.9%	16	9	43.8%	283	112	60.4%
822	18	16	1	93.8%	285	15	94.7%	16	11	31.3%	283	129	54.4%
1333		16	2	87.5%	285	30	89.5%	16	5	68.8%	282	93	67.0%
1340		16	0	100.0%	284	5	98.2%	16	3	81.3%	284	45	84.2%
1689		8	0	100.0%	82	5	93.9%	9	1	88.9%	82	9	89.0%
2102		11	0	100.0%	57	12	78.9%	11	1	90.9%	56	5	91.1%
2103		11	2	81.8%	121	12	90.1%	11	0	100.0%	120	9	92.5%
2104		11	0	100.0%	147	9	93.9%	11	2	81.8%	145	12	91.7%
2107		11	3	72.7%	178	33	81.5%	11	0	100.0%	175	20	88.6%
2108		11	0	100.0%	178	25	86.0%	11	2	81.8%	172	19	89.0%
2109		11	0	100.0%	71	9	87.3%	11	0	100.0%	70	4	94.3%
2112		11	1	90.9%	18	3	83.3%	10	2	80.0%	16	2	87.5%
2113		11	2	81.8%	57	5	91.2%	11	1	90.9%	57	8	86.0%
2115		11	2	81.8%	57	7	87.7%	11	4	63.6%	56	8	85.7%
2116		11	0	100.0%	18	0	100.0%	11	3	72.7%	18	5	72.2%

Amtrak On Time Performance

Trains Arriving Through: 7/16/2026

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2118	22	11	2	81.8%	18	2	88.9%	11	6	45.5%	18	8	55.6%
2119	36	11	1	90.9%	18	3	83.3%	11	7	36.4%	18	8	55.6%
2120	100	11	5	54.5%	18	8	55.6%	10	6	40.0%	17	9	47.1%
2123		11	2	81.8%	56	8	85.7%	10	2	80.0%	55	15	72.7%
2124	23	11	8	27.3%	150	31	79.3%	11	8	27.3%	148	21	85.8%
2127	18	11	4	63.6%	18	5	72.2%	11	5	54.5%	17	5	70.6%
2128		11	2	81.8%	18	2	88.9%	11	1	90.9%	18	1	94.4%
2131		11	5	54.5%	18	5	72.2%	11	1	90.9%	18	1	94.4%
2150		11	0	100.0%	171	22	87.1%	11	3	72.7%	168	70	58.3%
2151		11	0	100.0%	120	6	95.0%	11	3	72.7%	118	32	72.9%
2155	18	11	2	81.8%	180	16	91.1%	11	5	54.5%	176	95	46.0%
2158	33	11	0	100.0%	18	2	88.9%	11	5	54.5%	18	5	72.2%
2159		11	1	90.9%	173	12	93.1%	11	7	36.4%	171	55	67.8%
2160	23	11	0	100.0%	18	0	100.0%	10	8	20.0%	17	12	29.4%
2162	19	11	2	81.8%	179	15	91.6%	11	5	54.5%	173	82	52.6%
2171		11	0	100.0%	107	8	92.5%	11	3	72.7%	104	21	79.8%

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2118	NYP	22	WTR	15	WTR	6	WIL-PHL	AM	Heat order, Milepost, 10.0, 11.0, 30MPH NO 1 TRK	
2119	WAS	36	OTH	16	OTH	7	PHL-WIL	AM	Lost time - N.A.R., PRT	
2120	NYP	100	POL	65	POL	65	WIL-PHL	AM	Right of Way police hold, POLICE HOLD HOLLY TO HOOK	
2124	NYP	23	ITI	17	ITI	17	WAS-WAS	AM	Service, turn, or wye train, 2119, TURN TRN 2119 DID NOT ARRIVE UNTIL 548P	
2127	WAS	18	POL	18	POL	15	PHL-XPV	AM	Right of Way police hold, POLICE HOLD HOLLY TO HOOK	
2155	WAS	18	OTH	23	PTI	7	BAL-XNY	AM	Follow, 95, Milepost, 95.7, 134.6	
2158	BOS	33	ENG	26	ENG	26	WIL-PHL	AM	HEP, 2121 NG NP, LOSS OF POWER IN BOTH POWER CARS; RECYCLED AND PERFORMED A POSITIVE BRAKE TEST	
2160	BOS	23	WTR	21	CTP	19	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION AHD A/C SINGLE TRACKING SOUTH TUBE A/C NJ3363 DISABLED IN NORTH TUBE	
2162	BOS	19	SMW	15	ENG	11	NYP-NYP	AM	Other electrical failure, 2148 NG NP, HELD IN STATION FOR HSP MECHANICAL DUE TO RE-SETTING	
85	WAS	18	DET	20	DET	20	RTE-PVD	AM	Catenary failure, Other, LAWN, OCS inspection from Holden - Lawn at 30mph track 2 ACCOUNT POWER DIRECTOR UNABLE TO HOLD POWER (TREE IN WIRE EAST OF LAWN TRK 2)	
93	NFK	36	PTI	22	DMW	17	ALX-QAN	CS	Waiting for MW clearance Had to contact dispatcher to reach him, Milepost, 97.8, 95.7	
94	BOS	48	DCS	22	CTP	20	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION AHD A/C SINGLE TRACKING SOUTH TUBE A/C NJ3363 DISABLED IN NORTH TUBE	
95	NFK	62	DSR	63	DSR	52	X3V-NFK	NS	Per bulletin Heat, Milepost w/Letters, N77.7, N52.2, 25, both	
134	NYP	32	SMW	14	SMW	8	WIL-PHL	AM	Scheduled in track usage program, Control Point, PHIL TO BALDWIN, 2 TRACK O/S	
138	NYP	168	WTR	124	WTR	110	NFK-X3V	NS	Heat order Milepost w/Letters, 5.1, 3.1	
148	SPG	43	CTI	24	CAR	15	PHL-PHL	AM	Heat / AC, 82669 AX AS, LOOKING TO MEET WITH MECHANICAL A/C HOT CAR; MECHANICAL COULDNT FIX THE ISSUE/DID NOT SHOW	

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
151	RNK	174	WTR	64	DBS	60	ALX-MSS	CS	Debris blocking track (no debris strike) Control Point, Edsal
171	RNK	58	WTR	41	FTI	21	MSS-CLP	NS	Follow Milepost, 36.4, 56.0, 27A
174	BOS	21	SMW	19	SMW	8	WIL-PHL	AM	Scheduled in track usage program, Control Point, PHIL TO BALDWIN, 2 TRACK O/S
175	WAS	28	CTI	28	POL	24	WIL-XPV	AM	Right of Way police hold, HELD FOR DISPOSITION A/C HOLD ON ALL TRACKS BETWEEN BACON AND DAVIS DUE TO POLICE ACTIVITY AT NEWARK STATION THEN OPERATED RESTRICTED SPEED BETWEEN MP 38.0 AND MP 39.0 FOLLOWING POLICE HOLD
178	BOS	84	WTR	69	CTI	35	BCV-ALX	CS	Meet VRE, 305, Control Point, AF
179	PHL	23	CTI	12	CTI	7	NLC-NHV	AM	Follow, CDOT, 1695, Milepost w/Letters, XGU, XM4, AM179 followed signals of CD1695
185	WAS	23	CTI	13	DCS	13	TRE-XHM	AM	Power switch failure, Other, XMO, HELD TO OPERATE 2 TRK A/C 34 SWITCH AT GRUNDY ON CENTER
186	PHL	58	POL	46	POL	46	XPV-WIL	AM	Right of Way police hold, HELD FOR DISPOSITION A/C HOLD ON ALL TRACKS BETWEEN BACON AND DAVIS DUE TO POLICE ACTIVITY AT NEWARK STATION THEN OPERATED RESTRICTED SPEED BETWEEN MP 38.0 AND MP 39.0 FOLLOWING POLICE HOLD
190	BOS	20	DET	17	DET	17	PVD-RTE	AM	Catenary failure, Other, lawn, held at lawn for westbound traffic a/c tree in OCS
192	NYP	17	CAR	18	CAR	18	BAL-BAL	AM	Heat / AC, 82811 AX AS, 4th car was hot, mechanical was able to correct problem
197	WAS	23	OTH	16	CTI	8	BAL-XNY	AM	Follow, MARC, 455, Milepost, 120.5, 134.6
474	SPG	58	CON	24	CON	24	NHV-NHV	AM	Hold for connecting train, late connection of AM174
478	SPG	22	CON	21	CON	21	NHV-NHV	AM	Hold for connecting train
494	GFD	35	CON	51	CON	50	NHV-NHV	AM	Hold for connecting train
52	LOR	67	PTI	98	PTI	89	XOU-XFL	CS	Meet P089, Other, YEM XO
79	CLT	78	WTR	75	WTR	30	PTB-RMT	CS	Heat order Milepost, 22.0, 119.6
80	NYP	58	WTR	51	POL	37	WIL-PHL	AM	Right of Way police hold, POLICE HOLD HOLLY TO HOOK

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
626	NYP	11	ENG	18	ENG	18	PAR-DOW	AM	HEP, 657 EX ES, PANS DROPPED AND LOST HEP; RECYCLED ENGINE AND RESTORED POWER
646	NYP	23	OTH	15	RTE	10	PJC-NWK	AM	Routed to abnormal station track due to N.A.R., N/A, Other, XUN-XEO, ROUTED TO "A" TRK IN ERROR
650	NYP	15	PTI	12	HLD	5	PHL-PHL	AM	High passenger count, PER DSPR; 233P
653	HAR	13	CTP	12	CTP	12	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, HELD AT DEPARTURE A/C SINGLE TRACKING IN SOUTH TUBE DUE TO NJ3363 DISABLED IN NORTH TUBE
683	BRK	11	DCS	9	DCS	5	EXR-DHM	CS	Restrictive signal(s) from unknown cause Approach medium, Control Point, Newfield
686	BON	39	DMW	12	DMW	12	DHM-EXR	CS	Held for or routed around MW work or equipment Track car on single track within view. No information from the dispatcher as to how long we would be stopped., Control Point, newfields
687	BRK	15	ITI	11	ITI	11	BON-BON	MT	Service, turn, or wye train 686
688	BON	26	PTI	13	PTI	13	FRE-POR	CS	Meet 685, Control Point, mountain
63	TWO	93	FTI	24	FTI	14	XSV-ROC	CS	Follow csx, Milepost, 325, 369
64	NYP	28	FTI	40	CON	33	NFS-NFS	XC	Hold for bus with passengers from train Held for bus from Toronto
68	NYP	23	WTR	41	WTR	41	SLQ-RSP	CN	Heat order 25 mph, Milepost, 42, 2
69	MTR	41	CUI	46	CUI	46	XLQ-XLQ	CN	Canada
233	ALB	60	PTI	26	PTI	24	CRT-POU	MN	Meet Held at cp 39 for 3 trains. A metro north local 858, Amtrak 280 and then was told by dispatcher we were also being held for 240 as well, 280 and 240, Control Point, 39
235	ALB	56	RTE	45	RTE	45	CRT-POU	MN	Dispatcher hold Control Point, 39
244	NYP	26	CTI	26	CTI	12	RHI-XCP	AM	Meet Amtrak, 235, Control Point, 75
245	ALB	56	ENG	45	ENG	45	NYP-NYP	AM	Unrecoverable penalty (PCS), 704 DX DM
280	NYP	60	DMW	27	DMW	13	XSV-SYR	CS	Unable to contact dispatcher / MW foreman Approach Foreman Kratzer's working limits towards the end of his limits being in effect. Heard Foreman talking to other workers or trains, but no answer when called. Look out for stop boards, workers, and equipment., Milepost, 292.0, 290.0

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
284	NYP	32	CTI	43	CTI	40	POU-CRT	MN	Cross Traffic Single track, mn, Control Point, 46
290	NYP	56	CTI	50	CTI	29	POU-CRT	MN	Meet Single tracking due to working limits. Waiting for a north bound train and for working limits to end, metro north, Control Point, 46
291	BTN	17	PTI	28	PTI	15	CRT-POU	MN	Cross over or go around amtrak, Control Point, 39
49	CHI	93	FTI	91	FTI	41	SYR-ROC	CS	Follow N/A, Other, SYR-ROC
71	CLT	16	DCS	11	DCS	6	RGH-CYN	NS	Restrictive signal(s) from unknown cause Couldn't reach dispatcher. ,radio and phone, Stop, Milepost, 164.8, 164.8
73	CLT	46	WTR	50	WTR	24	HPT-SAL	NS	Heat order Milepost, 298.8, 333.4
74	RGH	124	WTR	75	ITI	51	CLT-CLT	NS	Service, turn, or wye train 73
77	CLT	63	WTR	81	WTR	22	HPT-SAL	NS	Heat order NS Heat Order 40mph, Milepost, 299, 333.5
78	RGH	15	ITI	29	ITI	29	CLT-CLT	NS	Service, turn, or wye train 77
89	SAV	35	WTR	52	DMW	19	PTB-RMT	CS	Held for or routed around MW work or equipment Milepost w/Letters, a91.2, a101.5
97	MIA	49	CTI	55	CTI	22	DLD-WPK	FR	Follow CFRC, Other, DLD - OCC
98	NYP	57	CTI	72	WTR	26	PAK-JAX	CS	Heat order Control Point, sanford sub, Control Point, Jacksonville sub
40	CHI	71	WTR	87	FTI	28	XDJ-ALX	CS	Meet 407, I031, Control Point, N. Possum Pt., Control Point, AF
41	MIA	71	FTI	67	CTI	31	XVG-ALX	CS	Meet Single tracking at ALX station, vre, Control Point, slaters
5	EMY	73	DSR	123	FTI	39	BRL-BRL	BN	Hold due to freight derailment Held for MOW to clear up derailed cars ahead at MP214, BNSF, Other, Burlington Station
6	CHI	105	DSR	143	WTR	29	WNN-XW6	UP	Heat order Milepost w/Letters, A535.70, A561, Milepost, 561, 612
530	SAC	29	TRS	34	TRS	34	MTZ-SUI	UP	Trespasser strike Strike up ahead at mp 50 caused train congestion so we could single track... we are waiting for two westbound trains, Control Point, cordelia
537	OKJ	Trn Cancelled	DSR	3	DSR	3	SAC-DAV	UP	Per bulletin Form A Nos. 23270 & 23334., Milepost, 85.00, 83.7, 45, MT1, Milepost, 81.3, 81.1, 45, MT1
538	ARN	14	PTI	6	PTI	3	GAC-FMT	UP	Meet AMT 539, Control Point, Cherry

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
539	SJC	40	TRS	26	TRS	26	FFV-FFV	UP	Trespasser strike Held in station at FFV until clear., Milepost, 50.4, 50.4
51	CHI	156	WTR	90	PTI	30	MSS-CLP	NS	Meet 178, Control Point, Remington
503	EUG	37	DMW	39	DMW	24	KEL-VAN	BN	Hold for defect repair Broken rail M1, Control Point, Fruit Valley
504	SEA	16	DSR	15	DCS	5	TAC-XTW	BN	Restrictive signal(s) from known wayside signal failure Signal dropped on approach to signal, both in field and in PTC, before returning to Diverging Clear. Reported and did Class 2, before departing., Stop, Control Point, T R Junction
508	SEA	40	FTI	28	FTI	16	SLM-ORC	UP	Meet UP 8173, Siding, Gervais
509	PDX	46	CCR	33	CCR	26	SEA-TUK	BN	PTC - On Board Cab Signal or PTC Failure 90253, Had to wye train after departure
516	VAC	32	FTI	20	FTI	14	XF2-X1J	BN	Meet Control Point, Piper, CP 8793 S
517	PDX	17	PTI	18	PTI	9	MVW-STW	BN	Meet Amtrak 516, Control Point, Logen
518	VAC	20	FTI	23	FTI	23	PDX-VAN	BN	Cross Traffic ROC, Control Point, CP 05
58	CHI	39	DSR	64	DCS	30	MEM-NBN	CC	Restrictive signal(s) from unknown cause Signal pumping through all aspects. Talked by signal Flag to mp343.8., Red, Control Point, N rialto
59	NOL	43	DSR	60	PTI	34	MCB-HMD	CC	Meet AMTK58, Control Point, Hammond Jct.
11	LAX	117	PTI	96	POL	59	SAC-SAC	UP	Removal of passenger by police 255F8E - APD attempted to remove passenger. Train was advised to advance to MTZ for back-up officers.
8	CHI	326	FTI	331	PTI	47	DVL-GFK	BN	Meet Amtrak 7 west, Siding, emarado
27	PDX	29	FTI	72	FTI	53	PSC-WIH	BN	Meet Signal dropped causing the freight train to go into emergency., BNSF 6750, Siding, yellepit
28	SPK	31	FTI	28	FTI	22	XPW-SPK	BN	Follow BN 6277, Control Point, Babb, Control Point, Lakeside Jct
821	FTW	15	DSR	27	DSR	23	GLE-FTW	BN	Per bulletin Milepost, 408, 407.7, 30, M, Milepost, 407.4, 407, 30, M, Milepost, 405.8, 405.6, 30, M, Milepost, 401, 400.2, 25, M, Milepost, 396.3, 396.2, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 385.5, 385.3, 30, M, Milepost, 383.6, 383.4, 30, M, Milepost, 361.1, 360.6, 30, 1, Milepost, 350.4,

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
822	OKC	18	DSR	31	DSR	22	FTW-GLE	BN	Per bulletin Milepost, 350.7, 351.1, 50, m1, Milepost, 354, 354.5, 70, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 360.6, 361.1, 60, m1, Milepost, 360.8, 361.3, 30, m1, Milepost, 364.7, 365.1, 48, m1, Milepost, 369.5, 369.9, 50, m, Milepost, 371, 371.5, 50, m, Milepost, 374, 374.1, 60, m, Milepost	
338	CHI	20	DCS	8	DCS	8	GLN-XWA	ME	Power switch failure Control Point, A5	
351	CHI	98	ENG	50	SVS	50	XA5-XB0	MI	Pick up equipment Pick up 354 equipment, Siding, albion	
354	PNT	Trn Cancelled	ENG	278	ENG	260	ALI-ALI	MI	Failure of diesel engine Gas detection alarm. Lost HEP and engine shut down. Train terminated in ALI., ID4608	
365	CHI	70	DSR	31	OTH	24	LNS-BTL	CC	Thorough fair move had to get permission from Lansing yard master and Battle Creek yard master for Hope & Mill	
562	SAN	40	PTI	32	PTI	32	SNC-X98	SC	Meet Amtk 765, Control Point, Serra	
564	SAN	34	PTI	27	PTI	25	SNC-SNP	SC	Meet 765, Control Point, Capistrano	
566	SAN	50	CTI	19	CTI	17	OSD-SOL	SN	Follow coaster, 632, Control Point, escondido jct, Control Point, swami	
567	LAX	56	PTI	30	PTI	30	OSD-X98	SN	Meet 562, Control Point, SONGS	
572	SAN	59	CTI	36	DCS	12	SNC-SNP	SC	Restrictive signal(s) from known wayside signal failure Flag lantern an restricted speed, Dark / dark, Control Point, lantern	
573	LAX	27	DCS	18	DCS	6	FUL-XRJ	BN	Restrictive signal(s) from unknown cause Stop, Control Point, East Hobart	
579	LAX	22	DCS	13	PTI	12	OSD-X98	SN	Meet 774, Control Point, Songs	
581	LAX	34	ITI	16	ITI	16	SAN-SAN	SN	Service, turn, or wye train 770	
584	SAN	38	CTI	31	CTI	16	XRJ-FUL	BN	Follow Metrolink, 624, Control Point, Bandini	
757	SLO	61	DCS	46	DCS	38	GTA-X3G	UP	Restrictive signal(s) from unknown cause Flagging red signals from north Elwood to mp342, Red stop, Control Point, north ellwood	
761	GTA	40	DCS	44	DCS	39	OSD-X98	SN	PTC- I-ETMS Red Fence/Signal Status Unknown Red fence over yellow fence Problem looked to be on Orange Sub side, Other, Starting about Songs switch	
765	SLO	60	DCS	40	DCS	23	OSD-X98	SN	Power switch failure Flag songs / authority to occupy, Control Point, songs	

Amtrak Endpoint OTP Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
769	GTA	39	DCS	20	DCS	13	X98-SNP	SC	CTC system failure Dispatcher unable to clear signal/flagging., Control Point, Pier
770	SAN	54	PTI	29	PTI	13	OSD-SOL	SN	Meet Amrk 579, Control Point, Carl
774	SAN	57	DCS	57	DCS	32	SNC-SNP	SC	CTC system failure Flag cp lantern-SNP, Control Point, lantern
777	SLO	20	RTE	19	RTE	19	GTA-X3G	UP	Two step due to up train at Elwood siding Control Point, elwood
785	GTA	27	ITI	28	ITI	28	SAN-SAN	SN	Late train equipment 774
786	SAN	16	PTI	25	CTI	19	SIM-CWT	SC	Meet metrolink, Siding, davis
719	OKJ	44	TEN	35	TEN	35	BFD-WAC	BN	Undesired Emergency due to Audible Alerter not working. Dumped train set multiple times to recover. Per TASI SUPV run with Alerter cut out. Qualified conductor on headend. C2009
3	LAX	122	WTR	118	WTR	64	XIA-GLP	BN	High winds Milepost, 50.0, 144.0
4	CHI	89	FTI	99	CAR	59	LAX-LAX	SC	Heat / AC 32103, Substituted 32006 for car with failed AC
305	STL	43	FTI	37	FTI	30	XTF-SMT	CC	Cross Traffic Unknown, Control Point, Brighton
306	CHI	19	PTI	33	PTI	24	PON-DWT	UP	Meet AMT307, Other, ODELL
307	STL	19	DSR	25	ADA	10	JOL-JOL	UP	Mobility Impaired
380	CHI	35	DSR	21	DSR	12	PLO-NPV	BN	Per bulletin Milepost, 52.0, 50.0, 15, 2, Milepost, 48.0, 45.6, 30, 2
382	CHI	29	CTI	21	FTI	14	GBB-GBB	BN	Meet Train coming into yard, Control Point, APlant, 5364, BNSF
383	QCY	45	FTI	22	FTI	12	GBB-MAC	BN	Meet BNSF 6725, Control Point, Knox
390	CHI	32	DSR	26	DCS	10	CEN-EFG	CC	Wait for signal to time out. Waited for signal to timeout at Kinmundy to reset the interlocking., Control Point, Kinmundy
391	CDL	30	PTI	27	PTI	27	RTL-CHM	CC	Meet Pull into outbound yard lead Back out CN Freight in siding, AM 390, Control Point, Leaverett Jct
392	CHI	29	WTR	28	FTI	13	CEN-EFG	CC	Cross Traffic Control Point, kinmundy, eastbound up
393	CDL	30	DSR	35	PTI	15	CHM-MAT	CC	Meet 392, Siding, Tolono
316	STL	127	WTR	92	WTR	32	WAR-SED	UP	Flash flood warning Milepost, 218.0, 188.0

Amtrak Endpoint OTP Details										
Late Trains For			26-FOI-00603		00000008328		"UNCLASSIFIED"		7/21/2026	
Region:			ALL							
Service:			ALL							
Arriving On:			7/16/2026							
			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
318	CHI	64	FTI	44	FTI	21	CRV-SPI	UP	Cross Traffic NS freight, Control Point, Illes	
319	KCY	99	FTI	123	FTI	65	JEF-SED	UP	Follow Milepost w/Letters, Dow, smithton, up 8821	

Amtrak Initial Terminal Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/16/2026

Terminal	Train	Date	Late	Delay	Cause
NFS	64	07/16	34	33	Hold for bus with passengers from train Held for bus from Toronto
ALB	448	07/15	3	3	Re-crew / job briefing Had to have a job briefing with Trainmaster about passengers boarding or using buses for hot ordered car, Other, ALB
BON	687	07/16	11	11	Service, turn, or wye train 686
BON	689	07/16	1		
CLT	74	07/16	51	51	Service, turn, or wye train 73
CLT	78	07/16	29	29	Service, turn, or wye train 77
CLT	80	07/16	2	2	Mobility Impaired Multiple mobility impaired passengers including a last minute lift
NHV	474	07/16	48	24	Other electrical failure, 114 DX BD, mechanical issue
NHV	474	07/16	48	24	Hold for connecting train, late connection of AM174
NHV	494	07/16	51	50	Hold for connecting train
NHV	494	07/16	51	1	Hold for connecting train
NHV	494	07/16	51	50	Hold for connecting train
NHV	494	07/16	51	1	Hold for connecting train
NYP	19	07/16	4	4	Hold for connecting train, HELD F/PSGRS OFF AM280
NYP	63	07/16	10	10	Passenger and/or baggage, BOARDING
NYP	131	07/16	2	2	Passenger and/or baggage, BOARDING
NYP	233	07/16	2	2	Cross Traffic, NJT, NJ6332, Other, NYP
NYP	237	07/16	6	6	Service, turn, or wye train, 284, LATE TURN OFF AM284
NYP	241	07/16	3	3	Cross over or go around, AM48, Other, "A" INT, HELD A/C AM48 RTD AHD IN "A" INT
NYP	653	07/16	12	12	Delay due to mechanical problems on a Commuter train, HELD AT DEPARTURE A/C SINGLE TRACKING IN SOUTH TUBE DUE TO NJ3363 DISABLED IN NORTH TUBE
NYP	2123	07/16	2	2	Passenger and/or baggage, BOARDING
NYP	2127	07/16	5	5	Delay due to mechanical problems on a Commuter train, DELAYED AT DEPARTURE A/C NJ3363 DIABLED IN NORTH TUBE
NYP	2131	07/16	2	2	Passenger and/or baggage, BOARDING
RNK	66	07/16	98	98	Service, turn, or wye train 151
SPG	125	07/16	7	7	Other electrical failure, 145 DX BD, late a/c bad windshield wiper on eng 145
WAS	136	07/16	2	2	Cross Traffic, MARC, 641, Control Point, K Int
WAS	192	07/16	8	2	Other electrical failure, 625, FLAG DID NOT COME DOWN UNTIL 2 MIN AFTER DP TIME.

Amtrak Initial Terminal Details

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/16/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	192	07/16	8	6	Heat order, Other, TRK 12, CNDR HELD OFF BOARDING DUE TO TRN NOT HAVING PWR FOR OVER AN HOUR IN EXTREME HEAT. (501 PAX)
WAS	2124	07/16	17	17	Service, turn, or wye train, 2119, TURN TRN 2119 DID NOT ARRIVE UNTIL 548P
CHI	50	07/16	33	33	Set out defective locomotive 328
GBB	382	07/16	14	14	Meet Train coming into yard, Control Point, APlant, 5364, BNSF
SAS	22	07/16	8	8	Service, turn, or wye train 21, Amtrak 21 arrived late waiting on mechanical release
BFD	711	07/16	1	1	Passenger and/or baggage Grandma with baby showed up after doors were closing with a wagon full of belongings that we had to unload first
EMY	6	07/16	4	4	Restrictive signal(s) from unknown cause No signal to depart at east Emeryville could not contact dispatcher., Stop, Control Point, e emy
GTA	782	07/16	8	8	Meet 14, Control Point, CO 358
OKJ	536	07/16	(Trn Cxld)		Trespasser Strike
OKJ	710	07/16	1	1	Loading problem Engineer reported loading problem, C2009
OKJ	716	07/16	1		
SAN	581	07/16	16	16	Service, turn, or wye train 770
SAN	785	07/16	28	28	Late train equipment 774
SEA	509	07/16	7	7	PTC - On Board Cab Signal or PTC Failure 90253
SJC	530	07/16	1		

Eastern Region

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.0	98.4	94.8	342	7
CDOT	95.0	80.0	83.6	92.4	20	4
MARC	95.0	93.1	79.0	90.2	58	4
SEPTA	95.0	94.2	94.9	91.5	207	12
NJT-NED	95.0	96.1	90.9	88.6	355	14
NJT-SED	95.0	100	95.5	97.2	24	0

Operating Highlights

Train 98(16) North of Jesup, GA - Freight Train Interference

17JUL26: Train 98(16) operating with engines 152, 305, 10 cars. and 226 customers onboard was delayed 11 miles north of Jesup, GA on the CSX Nahunta subdivision following CSX M407-14 from milepost 533.8 until milepost 503.5. 98(16) was further delayed north of Florence, SC on the South End subdivision following the CSX M408-16 from milepost 292 to milepost 260.

Train	Delay	Comment
98(17)	30"	FLO
98(16)	35"	JSP

Train 494(16) New Haven, CT - Hold for Connection

17JUL26: Train 494(16) was delayed departing New Haven, CT due to late inbound 94(16) carrying 26 connecting customers.

Train	Delay	Comment
494(16)	51"	

CSX Heat Orders - Weather

17JUL26: CSX has imposed a code 3 between 7/21/2026 and 7/21/2026 for the following subdivisions: Grand Rapids, Monon, Alleghany, Baltimore Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, New River, Old Main Line, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah, South End and Tampa Terminal.

Train	Delay	Comment
80 (16)	1'04"	
90 (16)	1'07"	
94 (16)	06"	
79 (16)	1'45"	
40 (15)	1'40"	
98 (16)	1'05"	
89 (16)	1'25"	
40 (16)	1'05"	
186 (16)	29"	
97 (15)	1'23"	
20 (15)	46"	
41 (15)	27"	
95 (16)	40"	
52 (16)	06"	
171 (16)	22"	
53 (16)	16"	
138 (16)	06"	
125 (16)	1'35"	

Newark, DE - Police Related

16JUL26: Multiple trains were impacted by a police hold that went into effect at approximately 10:00 p.m. at Newark Station in Delaware, milepost 38.9. All north and southbound traffic was delayed in a holding pattern until the area was released.

Train	Delay	Comment
175 (16)	21"	
186 (16)	42"	
198 (16)	23"	
138 (16)	45"	

Train 626(16) East of Parkesburg, PA - Deer Strike

16JUL26: Train 626(16) operating with engine 657, 4 cars, cab car, 9649, and 49 customers onboard was delayed departing Coatesville, PA on the Amtrak PH Line after striking a deer between Parkesburg, PA milepost 44.2 and Coatesville, PA milepost 38.5 causing headend power to temporarily drop while located on track 1. The crew was able to recycle the engine, raise pantographs, perform a brake test, and depart Coatesville with headend power functional.

Train	Delay	Comment
626 (16)	15"	

Train 69(16) Lacolle, QC - Customs and Immigration

16JUL26: Train 69(16) operating with engine 112, 5 cars, and 95 customers onboard was delayed at Canadian customs in Lacolle, QC.

Train	Delay	Comment
69 (16)	46"	

North of Wilmington, DE - Police Related

16JUL26: At 6:44 p.m. 26-FBI-00803 00000008328 was UNCLASSIFIED to 7/21/2028 hold on all tracks north of Wilmington, DE on the Amtrak NYP Line between Hook interlocking milepost 16.8 and Holly interlocking milepost 20.3 while police searched for a suspect related to a crime. Multiple southbound and northbound trains were impacted in a holding pattern until APD released the hold.

Train	Delay	Comment
2120(16)	1'00"	
136(16)	55"	
SE9226	53"	
80(16)	31"	
SE8299	31"	
SE9228	34"	
2127(16)	11"	

Train 474(16) New Haven, CT - Engine Failure

16JUL26: Train 474(16) operating with locomotives 95-114, 1 car, cab car 9636 and 65 customers onboard was delayed at the initial terminal of New Haven due to holding for connecting customers off 174(16).

Additionally, train 174(16) was delayed for mechanical issues with locomotive 114 being unable to supply HEP after being moved into the station. New Haven Mechanical responded and was able to correct the issue allowing train 474(16) to depart.

Train	Delay	Comment
474(16)	23"	Hold for connections
474(16)	23"	Engine

Train 2158(16) South of Philadelphia, PA - Engine Failure

16JUL26: Next Gen Acela 2158 operating with TS-23 and 308 customers onboard was delayed south of Philadelphia on the PW line due to a reported loss of tractive effort on both power cars. The crew was required to de-prepare and re-prepare the trainset causing a loss of HEP while performing the deliberate task. After the train was re-prepared HEP and full tractive effort were restored and train 2158(16) was able to proceed.

Train	Delay	Comment
2158(16)	26"	

Train 138(16) East of Petersburg, VA - Tie Fire

16JUL26: Train 138(16) operating with locomotive 151, 9 cars and 133 customers onboard was delayed 30 miles east of Petersburg at MP 46 on the NS Norfolk division due to holding for a tie fire. Local authorities and fire rescue responded to the location of a tire fire obstructing the route for train 138(16). Once the fire was contained train 138(16) was able to proceed.

Train	Delay	Comment
138(16)	44"	

Train 68(16) St-Lambert, QC - Weather

16JUL26: Train 68(15) operating with locomotive 103, 5 cars, and 85 customers was delayed on the CN Rouses Point subdivision for heat orders between St. Lambert and Rouses Point.

Train	Delay	Comment
-------	-------	---------

Amtrak NHB Line - Tree in Catenary

16JUL26: Multiple trains delayed on the Amtrak NHB Line east of Providence due to a tree in the overhead catenary system on the No.2 track between Lawn and Hebronville interlockings. At 10:30am-ET the Zone 10 Power Director reported they were unable to hold the power on the No.2 track between Lawn and Hebronville. Train 85(16) performed a slow speed inspection at 35mph on the No.1 track through the affected area and found a tree in the catenary on the No.2 track. An emergency power place was placed on the No.2 track between Lawn and Mansfield creating a 16 mile single track route on the No.1 track. ET personnel responded to the scene and begun to remove the tree. Upon completion of the removal of the tree ET personnel reported damage to the wire requiring necessary repairs to be made. Once completed, the emergency power plate was removed, the line was reenergized, and normal operations were able to resume.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
85(16)	20"	
190(16)	17"	
2150(16)	17"	
170(16)	08"	
172(16)	13"	

Train 52(16) South of Jacksonville, FL - Temporary Speed Restrictions

16JUL26: Auto Train 52(16) operating with engines 380, 364, and 406 customers onboard was delayed 20 miles south of Jacksonville, FL on the CSX Sanford subdivision operating through signal issues from milepost 667.0 to milepost 639.6.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(16)	40"	

Train 151(16) South of Alexandria, VA - Downed Tree

16JUL26: Train 151(16) operating with locomotive 124, 5 cars and 111 customers onboard was delayed 4 miles south of Alexandria on the NS Hagerstown Division due to a downed tree ahead. NS personnel responded to the location of the downed tree to remove it and allow for an open route. Once completed train 151(16) was able to resume operations toward Manassas.

Due to the additional delay encountered from the downed tree, train 151(16) operated over the road during the NS heat orders further delaying the train which would have otherwise completed its trip prior to the commencement of the heat orders.

Train 66(16) was delayed at the initial terminal of Roanoke due to the late performance of train 151(16) and the turn of equipment. After servicing and inspections were completed train 66(16) departed Roanoke.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
151(16)	60"	
66(16)	1'38"	

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008328 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FBI-00893 a 00000008328 in "UNCLASSIFIED" open 7/21/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train 14(16) South of Paso Robles, CA - Passenger Train Interference

17JUL26: Train 14(16) was delayed at Templeton / MP218.4 on the UPRR Coast Subdivision, 5.5 miles south of Paso Robles, CA due to meeting Train 11(15).

Train	Delay	Comment
14(16)	30"	

Train 3(15) East of Flagstaff, AZ - Freight Train Interference

17JUL26: Train 3(15) was delayed at West Darling / MP329.6 on the BNSF Seligman Subdivision, 14 miles east of the Flagstaff Station, due to meeting multiple BNSF freights.

Train	Delay	Comment
3(15)	30"	

Train 1(15)/421(14) El Paso, TX - Car Failure

16JUL26: Train 1(15)/421(14) with E/361-164, nine cars, and 197 customers was delayed on the UPRR Lordsburg subdivision seven miles west of El Paso due to C/31045 with a sticking brake. The crew confirmed the hand brake was released, utilized a crow bar to gently free the brake pad from the wheel, performed the necessary tests, and continued to Deming.

Train	Delay	Comment
1(15)/421(14)	36"	

Train 11(15) South of Salinas, CA - Signal

16JUL26: Train 11(15) was delayed south of Salinas, CA on the UPRR Coast Subdivision due to signal issues, receiving restricting signals and needing to flag between MP140 and MP157. Train was also delayed due to issues with multiple automatic road crossing protection beginning at at MP117.39 to MP156.35.

Train	Delay	Comment
11(15)	1'00"	

Train 50(16) South of Dyer, IN - Car Failure

16JUL26: Train 50(16) with E/328-336, five cars, and 141 customers was delayed on the CSX Monon subdivision nine miles south of Dyer at MP 36.8 due to C/25071 with a hot box detector. The crew inspected, found no exceptions, and continued to Rensselaer.

Train	Delay	Comment
50(16)	39"	

Train 719(16) West of Bakersfield, CA - Third Party Contractor Engine Failure

16JUL26: Train 719(16) E/C2009, 00000008328, was delayed at 7/21/2026 Bakersfield / MP887.5 on the BNSF Mojave Subdivision, 0.6 miles west of Bakersfield, CA after the train went into emergency due to an inaudible alerter issue on E/C2009. The train had 143 passengers onboard and head-end power remained active during this event. The crew worked with TASI mechanical in order to troubleshoot the issue. Unable to resolve, a qualified conductor was able to ride on the head end with the Engineer in order to proceed west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(16)	35"	

Train 25(16) West of Gulfport, MS - Trespasser Incident

16JUL26: 628PM-CT, Train 25(16) with E/365, three cars, E/38, and 115 customers was delayed on the CSX NO&M subdivision one mile west of Gulfport at Broad St./MP 740.65 (DOT#340249F) in Gulfport Mississippi, located in Harrison County due to a near miss with a pickup truck with a trailer that was on the crossing with the gates down. The engineer was able to safely bring the train to a stop short of the crossing. There were no reported injuries to the customers or the crew and no damages reported to the equipment. The operator of the truck cleared the crossing and train 25(16) continued to Bay St. Louis.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(16)	08"	

Train 316(16) West of Sedalia, MO - Freight Train Interference

16JUL26: Train 316(16) with 92 customers was delayed on the UPRR Sedalia subdivision starting 14 miles west of Sedalia due to meeting MASNP-16 at Dresden/MP 195.7 and then CWLNA9-16 eight miles east of Sedalia at Smithton/MP 180.9. Train 319(16) held at Dow/MP 166.9 to meet 316(16) and then performed a saw by at Smithton/MP 180.9 with CWLNA9-16. Train 319(16) was further delayed following MASNP-16 between Sedalia/MP 188.9 and Centerview/MP 225.5, where they performed an additional saw by to overtake this freight. Train 316(16) was further delayed meeting CIMNA-15 at Shell/MP 151.6.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(16)	06"	Shell
316(16)	10"	Dresden
316(16)	23"	Smithton
319(16)	1'05"	Dow
319(16)	53"	Sedalia - Centerview

Train 5(14) West of Roseville, CA - Near Miss

16JUL26: Train 5(14) with E/18, E/136, 9 cars and 188 customers was delayed 11.5 miles west of Roseville, CA at MP 94.5 on the UPRR Martinez Subdivision. The engineer initiated an emergency brake application to avoid an impact with a vehicle. No impact was made and the train proceeded with its normal operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(14)	10"	

Train 8/28(14) West of Grand Forks, ND - Passenger Train Interference

16JUL26: Train 8/28(14) with E/306-336, five cars, and 188 customers, was delayed, 12 miles west of Grand Fork, ND, in BNSF Devils Lake subdivision, due to meeting train 7/27(15) at Emarado siding. Once train 7/27(15) cleared and a route was made available, train 8/28(14) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(14)	47"	

Train 50(16) Chicago, IL - Initial Terminal Delay

16JUL26: Train 50(16) with E/328-336, five cars, and 140 customers was delayed departing Chicago due to late train makeup account of E/355 removed for preventative maintenance and replaced with E/336. Once the train was made up and set in the station, all customers were welcomed aboard, and 50(16) departed Chicago at 628PM-CT, 33 minutes late. CSX was advised.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(16)	33"	

Train 305(16) South of Chicago, IL - Freight Train Interference

16JUL26: Train 305(16) with 259 customers was delayed on the CN Joliet subdivision five miles south of Chicago at Brighton/MP 5.1 due to meeting unknown freight.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
305(16)	30"	

Train 3(15) West of Las Vegas, NM - Passenger Train Interference

16JUL26: Train 3(15) was delayed at W. Blanchard/MP794 on the BNSF Glorieta Subdivision, 24 miles west of Las Vegas, NM due to meeting Train 4(15).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(15)	43"	

Train 59(15) North of Hammond, LA - Passenger Train Interference

16JUL26: Train 59(15) with 180 customers was delayed on the CN McComb subdivision just north of Hammond at Hammond Jct./MP 585.8 due to meeting train 58(16).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(15)	34"	

Train 316(16) East of Independence, MO - Weather

16JUL26: Train 316(16) was delayed on the UPRR Sedalia subdivision starting three miles east of Independence between the following areas due to flash flood warnings: MP 270.0 through MP 259.0, MP 243.0 through MP 218.0, MP 188.0 through MP 161.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(16)	09"	MP 270.0 - MP 259.0
316(16)	18"	MP 243.0 - MP 218.0
316(16)	32"	MP 218.0 - MP 188.0
316(16)	30"	MP 188.0 - MP 161.0

Train 51(15) East of Dyer, IN - Freight Train Interference

16JUL26: Train 51(15), 26-FC-00603, 100000008328 engine UNCLASSIFIED 355/328, 7/21/2026 coaches and 144 customers, was delayed 22 miles east of Dyer, IN, on CSX Monon subdivision, due to meeting and unknown CSX freight train at Shelby siding.

Train	Delay	Comment
51(15)	30"	

Train 3(16) - Freight Train Interference

16JUL26: Train 3(16) with E/77-19, 9 coaches, and 246 customers, was delayed 12 miles west of Naperville, IL at Montgomery/MP 40.2 on the BNSF Chicago subdivision, due BNSF 2288 tied down with single track conditions. Train 3(16) met trains 6(14) and 4(14) at Montgomery and then crossed over to get around BNSF 2288. Train 5(16) was delayed for the same reason, following 3(16).

Train	Delay	Comment
3(16)	1'18"	
5(16)	1'03"	

Train 537(16) Suisun-Fairfield, CA - Fatal Trespasser Strike

16JUL26: Train 537(16) with CDTX 6964, 4 cars, CDTX 2004, and 32 customers onboard fatally struck a trespasser at milepost 50.4 on the UPRR Martinez subdivision. The strike occurred at a crossing. The train was able to maintain head end power and remained intact on the rails. There were no reported injuries to the crew or customers. The strike occurred in Solano County and the weather was 87 degrees and sunny. The local authorities, local management, and APD responded to the scene. Track 1 was reopened at 12:44 PM-PT. Train 539(19) had been holding in Fairfield and was able to advance to train 537(16) for a train to train transfer. A relief crew arrived at train 537(16) at 12:49 PM-PT. Once the investigation was complete and the train released, train 537 was able to depart the scene.

The equipment from train 537(16) was used for train 536(16). Due to late operation of the train and needing to go to the yard, train 536(16) originated in Emeryville.

National Response Center Number: 1468070

Train	Delay	Comment
539(16)	39"	
536(16)	Orig EMY	
530(16)	34"	
537(16)	Term SUI	

Train 757(16) North of Goleta, CA - Passenger Train Interference

16JUL26: Train 757(16) with CDTX 2112, 6 cars and 25 customers onboard was delayed beginning at milepost 356.0, 2 miles north of Goleta, CA on the UPRR Santa Barbara due to meeting train 774(16). Once the passenger train was cleared, train 757(16) was able to advance.

Train	Delay	Comment
757(16)	35"	

Train 757(16) North of Goleta, CA - Signal Issues

16JUL26: Train 757(16) with engines 346/347, 9 cars, and 104 customers onboard was delayed beginning at milepost 356.0, 2 miles north of Goleta, CA on the UPRR Santa Barbara due to restrictive signals from an unknown reason. The train was required to flag red signals from milepost 356.0 to milepost 342.0. Once the train was through the affected area, train 757(16) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
757(16)	38"	

Train 27(14) West of Pasco, WA - Freight Train Interference

16JUL26: Train 27(14) with engine 346, 4 cars, and 104 customers onboard was delayed at milepost 215.3, 17 miles west of Pasco, WA on the BNSF Fallbridge subdivision due to meeting BNSF freight train 6750. The signal in front of the freight dropped and the train went into emergency. Once the freight train recovered and cleared, train 27(14) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
27(14)	53"	

Train 11(15) Sacramento, CA - Passenger Removal - Police Related

16JUL26: Train 11(15) with engines 349, 378, 9 cars, and 191 customers onboard was delayed departing Sacramento, CA on the UPRR Martinez subdivision due to requesting police assistance to remove a passenger. APD attempted to remove the passenger and was not able to. The train was advised to advance to Martinez to be met by more police officers. In Martinez, the passenger was removed and the train was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(15)	59"	

Train 8/28(14) East Grand Forks, ND - Near Miss

16JUL26: Train 8/28(14), operating with engines 306/376, 10 coaches, and 181 customers, went into emergency east of Grand Forks, ND, at milepost 63.7, on BNSF Hillsboro subdivision, to avoid striking a semi truck. There was no strike. Once the train recovered their air and performed their brake test, they were able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(14)	13"	

Train 24(16) East of New Orleans, LA - Freight Train Interference

16JUL26: Train 24(16), operating with engines 38/365, 3 coaches and 101 customers was delayed 4 miles east of New Orleans, LA, on Amtrak Noyup-E subdivision, due to meeting unknown freight train 8169. Once the freight cleared and a route was made available, train 24(16) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(16)	37"	

Train 58(15) South of Newbern-Dyersburg, TN - Signal

16JUL26: Train 58(15) delayed at MP343.8 south Newbern-Dyersburg TN station due to a restrictive signal from an unknown cause. Train 58(15) was talked through the signal to MP343.8.

Train	Delay	Comment
58(15)	30"	

Train 354(15) Albion, MI - Engine Failure

16JUL26: Train 354(15) with engine ID4608, 5 cars and 220 customers lost HEP due to a gas pressure fault coming into Albion MI station/MP95.8 on the Amtrak Michigan Line. Crew worked with CNOC mechanical and were able to get the engine restarted with HEP restored. Due to the nature of the fault train 354(15) was terminated at Albion MI station with five alternate buses secured to accommodate passengers Albion MI to Pontiac MI. Road Foreman arrived on scene at 109AM ET. Bus one operated from Albion MI to Ann Arbor MI, bus two operated from Albion MI to Jackson MI and Ann Arbor MI, bus three operated from Albion MI to Dearborn and Pontiac MI, bus four operated from Albion MI to Detroit MI, bus five operated from Albion MI making all stops. All buses departed Albion MI station at 246AM ET.

Train 353(16) was cancelled in it's entirety with six supplement buses secured to accommodate passengers. Bus one operated from Detroit MI to Chicago IL, bus two operated from Ann Arbor MI to Chicago IL, bus three operated from Dearborn MI to Chicago IL, bus four operated from Royal Oak MI. to Detroit, MI, Ann Arbor, MI Jackson MI, Battle Creek, MI, Niles MI, New Buffalo MI and Chicago IL, bus five operated from Troy MI to Kalamazoo, MI and Chicago IL, bus six operated from Pontiac MI and made all stops.

Train 354(15) was coupled to train 351(16) and taken to Chicago. Once enroute the double train set received an alarm that required them to stop and inspect the equipment. It was discovered that the equipment was not set up properly and had to be reconfigured.

Train	Delay	Comment
354(15)	Term ALI	
353(16)	Cancelled	
351(16)	50"	Adding 354(14)
351(16)	44"	Reconfiguring equipment

Metrolink Orange Subdivision Signal Issues - San Clemente Pier, CA

15JUL26: Multiple trains delayed by signal issues on the San Clemente Pier, CA/ MP204.8 on the Metrolink Orange Subdivision and Songs/ MP 209.16, due to signal issues. The crews were delayed flagging, hand-throwing switches, and operating at reduced speeds as a result of the signal problems, and further delayed throughout the area account of congestion related delays caused by this.

16JUL26: Delays continued into the day until 5:30PM-PT when Metrolink reported all signals back to normal operations.

Train	Delay	Comment
790 (15)	46"	
595 (15)	32"	
786 (15)	44"	
785 (15)	23"	
580 (15)	25"	
567 (16)	30"	
765 (16)	36"	
774 (16)	35"	
579 (16)	21"	
782 (16)	35"	
562 (16)	51"	
587 (15)	1'05"	
588 (15)	1'21"	
591 (15)	1'17"	
761 (16)	54"	
581 (16)	17"	
777 (16)	11"	
573 (16)	16"	
769 (16)	24"	
785 (16)	28"	ITD SAN - Equip from 774

UPRR Del Rio Subdivision West of San Antonio, TX - Weather

16JUN26: Union Pacific Railroad reported multiple washouts west of San Antonio on the Del Rio Subdivision. Maintenance personnel were dispatched to the affected area; however, no estimated time of arrival was available at the time of the report. As a precautionary measure, Train 1(15)/421(14) was held at San Antonio pending further information regarding track conditions and the availability of any open routes.

Subsequent inspections confirmed at least one washout in the Yucca Siding area between Mileposts 285 and 288, along with multiple locations where water had overtopped the rail. Track inspectors continued evaluating the extent of the damage while maintenance equipment was assembled for repair efforts. A ballast train was positioned in San Antonio to support recovery operations. Based on initial assessments, UPRR estimated that the affected tracks would remain out of service for a minimum of eight hours, with the expected reopening time subject to revision as inspections progressed.

As a result of the two confirmed washouts west of San Antonio and the widespread flooding conditions through the area, the following service adjustments were implemented for the Sunset Limited. Train 1(15)/421(14) were cancelled between San Antonio and El Paso and train 2/422(15) were cancelled between El Paso and San Antonio. A bus bridge was established between the two cities to accommodate all affected customers. Train 1(15) equipment was turned in San Antonio and operated as train 2(15) to New Orleans. Train 2/422(15) equipment was turned in El Paso and operated as train 1(15)/421(14) to Los Angeles.

Four express buses representing train 1(15)/421(14) departed San Antonio at 1140AM-CT and continued to El Paso. An additional bus making local stops departed shortly after. Additionally, three express buses and one local bus were secured to represent train 2/422(15) and departed El Paso at 542PM-MT enroute to San Antonio. As part of the service recovery plan, meal boxes were provided for the affected customers with all buses making a meal stop enroute. Once all buses arrived on location in El Paso, customers and baggage were loaded onto the train, and train 1(15)/421(14) departed El Paso at 900PM-MT, 7 hours, and 10 minutes late.

Further assessments by UPRR revealed that the situation was more extensive than initially reported. Railroad personnel confirmed a total of seven washouts across the affected territory, along with multiple locations experiencing power outages and track occupied light indications. Several additional locations were identified with substantial water over the rail. Inspectors were unable to access approximately 33 miles of track, preventing a complete evaluation of the effected territory. Based on the expanded scope of the damage and accessibility challenges, UPRR revised its estimates and projected a 48-hour service outage, with an estimated time of restoration of July 19 at 200PM-CT. Considering the information and to support continued service recovery efforts, alternate transportation was being sourced to establish a bus bridge operation for trains 2/422(17) and 1(18)/421(17) between the affected locations.

A final report on July 16 revealed a total of 12 washout locations totaling .53 miles of track repairs with no estimated time for track opening. Crews continued to work diligently on repairs with 74 ballast cars in position. It would be necessary to install 120 ties at MP 293.35.

WBS#: B.TR.100150.6898

Train	Delay	Comment
1(15)/421(14)	SAS-ELP, bus bridge	
2/422(15)	ELP-SAS, bus bridge	
1(18)/421(17)	SAS-ELP, bus bridge	
2/422(17)	ELP-SAS, bus bridge	

UPRR Desoto Subdivision Washout - North of Poplar Bluff, MO

10JUL26: At 3:30AM-CT 26-FBI-00603 60000008328 UNCLASSIFIED 7/21/2026 the UPRR DeSoto Subdivision at Annapolis (MP108), located 57.6 miles north of Poplar Bluff, MO (MP165.6). As a result, Train 22(09) arrived at the Poplar Bluff station at 4:04AM-CT with 144 customers onboard and held for disposition.

A Union Pacific Manager of Track Maintenance responded to the washout location at 4:20AM-CT and provided a preliminary estimated track restoration time of 2:00PM-CT. A detour route was available via the Chester Subdivision between Poplar Bluff and St. Louis, bypassing Arcadia. No customer impact occurred at Arcadia, as no customers were scheduled to board or detrain at that location. Union Pacific pilot crews went on duty at 6:10AM-CT and responded to the train, arriving at 7:00AM-CT. Upon the pilots' arrival, Train 22(09) departed Poplar Bluff at 7:21AM-CT and proceeded over the detour route via the Chester Subdivision.

At 12:00PM-CT, Union Pacific reported that floodwaters were not expected to begin receding until Saturday, July 11. Following the water's recession, a track inspection would be required before rail operations could resume through the area. As a result:

-Train 21/421(10) detoured via the Chester Subdivision with 6 on / 0 off at Arcadia. The affected six customers were notified and advised to rebook on the next available departure.

-Train 22(10)/422(08) detoured via the Chester Subdivision with 0 on / 5 off at Arcadia. A sprinter van transported passengers from Saint Louis, MO back to Arcadia, MO.

11JUL26: Union Pacific reported that the floodwaters were not expected to recede until Sunday, July 12th. As a result, Trains 22(11) and 21(11) were also routed via the Chester Subdivision detour with no alternate provided to/from Arcadia.

12JUL26: UPRR revised eto was updated to 930AM-CT 12JUL. Due to no available UPRR pilots to support the detour, Train 22(11), with 109 customers, was delayed at Poplar Bluff, MO, holding for dispo of the route ahead and then further delayed through the area. Train 22(11) was delayed due to the 10MPH speed restriction through the washout area and also signal issues between MP107 and MP92. Train 21/421(12) was also delayed operating at 10MPH through the washout site.

13JUL26: UPRR 10MPH slow orders remained in effect between MP95 and MP110. Trains 22(12)/422(10) and 21(13) were delayed operating through the affected area.

Train	Delay	Comment
22(09)	3'14"	Hold PBF
22(09)	1'09"	Detour
21(11)	1'08"	Detour
22(10)/422(08)	3'21"	
21/421(10)	2'13"	
22(11)	1'09"	PBF
22(11)	2'42"	N/PBF
21/421(12)	1'47"	
22(12)/422(10)	1'13"	
21(13)	50"	
21/421(14)	49"	
21(15)	23"	
22(15)	31"	
21(16)	1'32"	

Heat Dome affect Entire Network - Weather

08JUL26: A heat dome ~~28-FOI-006031 00000008328~~ ~~UNCLASSIFIED~~ ~~7/21/2025~~ bringing scorching high temps in excess of 100° throughout the country. It will begin to expand as the week goes along and shift to the east affecting the entire nation. The first few days will be focused from the southwest through the Rockies to the Great Plains. It will then shift east affecting the Upper Midwest through the Northeast. Trains will be restricted to high temperature restriction. The high temperatures, there will be increase of severe thunderstorms and high winds.

The heat dome is expected to persist until the remainder of July.

14JUL26: Vermonter Service Train 56(14) terminated in Springfield, MA. The equipment was deadhead to New Haven, CT where Train 55(15) originated.

Three buses were secured for the 119 customers for Train 56(14) between Springfield to St. Albans.

Buses were secured for the 221 customers for Train 55(14) between St. Albans and New Haven.

14JUL26: Additional Cancellations on the Northeast Corridor impacting Regional and Acela services were put into place to protect overall service:

Northeast Regional Trains 84, 119, 173, 176, 193, 196, (15-16)

Acela Trains 2152, 2154, 2165, 2167, 2193 (15-16)

On Corridor WBS # B.TR.100151.0830

WBS#: B.TR.100151.0830

Train	Delay	Comment
6(08)	32"	Heat Orders WNN-ELK
5(06)	31"	Heat orders - ELK to WNN
6(08)	49"	Heat orders- GRI to GJT
5(08)	28"	Heat Orders GRA-GJT
5(08)	43"	Heat Orders GJT-HER
6(08)	17"	Heat Orders MTZ-RSV
3(08)	45"	High Winds RAT - GLP
6(10)	1'25"	Heat Orders RNO - ELK
6(11)	1'20"	Heat Orders RNO-ELK
5(10)	46"	Heat Orders GRA-GRI
8(10)	1'59"	Heat Orders
7(10)	2'40"	Heat Orders
7/27(11)	2'22"	GGW-SBY
8/28(11)	2'03"	SBY-WPT
5(11)	1'12"	DEN-PRO
6(11)	49"	GRI-GRA
68(13)	48"	
5(12)	54"	GRA-HER
6(12)	47"	WNN-DEN
7/27(12)	2'00"	WTN-HAV
8/28(12)	50"	HAV-GGW
56(14)	Term SPG	New England storms
55(15)	Orig NHV	New England storms
68(14)	40"	
64(14)	24"	
8/28(13)	1'00"	HAV-GGW
7/27(13)	1'28"	WTN-HAV
6(14)	43"	WNN-ELK
5(12)	29"	RSV-MTZ
5(13)	1'13"	GRA-HER
5(13)	51"	ELK-MTZ
6(15)	38"	Heat Orders WNN-ELK
3(14)	40"	Flash Flood Warnings E/WLO
3(14)	1'18"	Winds GLP-WLO
28(15)	16"	High Winds WIH-PSC
5(14)	1'15"	Heat Orders
5(15)	52"	Heat Orders
6(16)	40"	Heat Orders WNN-ELK

Midwest State Supported Service Adjustments - Equipment

08JUL26: The following Midwest State Supported Service Adjustments are in effect due to equipment availability issues in Chicago, IL:

10JUL26: Additional adjustments have been added to the schedule through 12JUL.

12JUL26: Lincoln and Wolverine service adjustments extended through 13JUL.

13JUL26: Lincoln and Illini/Saluki service adjustments in effect on Tuesday July 14th.

14JUL26: Illini/Saluki service adjustments extended to Wednesday July 15th.

Carl Sandburg Service:

- Trains 381(09-10) cancelled entirely, with alternate transportation for customers between Chicago and Quincy, IL.

- Trains 382(09-10) cancelled entirely, with alternate transportation for customers between Quincy and Chicago.

Lincoln Service:

- Trains 305(08-13) cancelled entirely, with alternate transportation for customers between Chicago, IL and St. Louis, MO.

- Trains 302(09-14) cancelled entirely, with alternate transportation for customers between St. Louis and Chicago.

Wolverine Service:

- Trains 350(11-13) cancelled entirely, with alternate transportation for customers between Chicago, IL and Pontiac, MI.

- Trains 355(11-13) cancelled entirely, with alternate transportation for customers between Pontiac, MI and Chicago, IL.

- Trains 350(16) cancelled entirely, with alternate transportation for customers between Chicago, IL and Pontiac, MI.

- Trains 355(16) cancelled entirely, with alternate transportation for customers between Pontiac, MI and Chicago, IL.

Illini/Saluki Service:

- Train 391(14-15) cancelled entirely, with alternate transportation for customers between Chicago, IL and Carbondale, IL.

- Train 392(14-15) cancelled entirely, with alternate transportation for customers between Carbondale and Chicago.

12JUL26: One of the busses providing alternate transportation for Train 302(12), Bus 3, was involved in an auto accident at the Bloomington-Normal, IL station. There were four passengers onboard at the time. No injuries were reported. The station secured transportation for the affected passengers.

WBS#: B.TR.100150.6872

Train	Delay	Comment
381(09-10)	Cancelled	
382(09-10)	Cancelled	
302(09-14)	Cancelled	
305(08-13)	Cancelled	
355(11-13)	Cancelled	
350(11-13)	Cancelled	
391(14-15)	Cancelled	
392(14-15)	Cancelled	

Wolverine Track Work-Scheduled M/W Work

100000008328

"UNCLASSIFIED"

WBS#: B.TR.100150.6897

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

09JUL26: This outage was originally scheduled to conclude on Friday July 31st, but will now conclude 2-weeks Earlier on Friday July 17th. The following adjustments are now in place.

- Train 59(21Jun-15Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (16Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-16Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(17Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track construction projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,

Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,

Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,

Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,

Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,

Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,

Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,

Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,

Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00603

00000008328

"UNCLASSIFIED"

7/21/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
392 (16)	CDL	NO BUSINESS CLASS- over capacity. NO CAFE SERVICE 35005 deadhead inline; no replacement	Passengers notified	25	35005
391 (16)	CHI	NO BUSINESS CLASS- over capacity. NO CAFE SERVICE	Passengers notified. Business class downgraded	24	35005
391 (17)	CHI	391(17) NO BUSINESS CLASS/CAFE SERVICE- OVER CAPACITY. 35005 WILL DHD IN-LINE W/ NO REPLACEMENT.	Passengers downgraded	28	35005
1059 (16)	CHI	1059(16) 33004 will deadhead BYD HVAC behind engine for axle count. There is no replacement lounge. Consist still has 37005(diner/lounge) in consist. Please alert/accomodate			NOCAR, 33004
506 (15)	KEL	Business Class sales closed (IY, ZY, and JY) due to BYD Hvac 48182. Please accommodate all passengers who have been affected.	Passegers downgraded	25	48182
573 (16)	LAX	NO BIKE SPACE. NO WIFI SERVICE.	Pax notified	106	90225
562 (16)	LAX	NO BIKE SPACE- over capacity. NO WIFI SERVICE.	Pax notified	83	90225
580 (16)	LAX	NO BIKE SPACE- over capacity. NO WIFI SERVICE.	Pax notified	92	90225
591 (16)	SAN	NO BIKE SPACE. NO WIFI SERVICE.	Pax notified	64	90225

Reverse Consists

Train Number	Station	Reason
111 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
110 (16)	PHL	Consist reversed Business class seat orientation may have changed At Rear
95 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00603	00000008328 "UNCLASSIFIED" 7/21/2026
93 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front	
179 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front	
174 (16)	WAS	Consist reversed Business class seat orientation may have changed At Front	
182 (16)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
129 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front	
129 (16)	NYP	Business class change only Business class seating orientation may have changed At Front. B-end leading	
184 (16)	WAS	Business class change only Business class seating orientation may have changed At Rear. B-end leading	