



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, July 19, 2026

Rules: 2-39



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Amtrak or Commuter: **Amtrak**

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00603 00000008326 UNCLASSIFIED Endpoint Arrival Dates through 7/18/26 7/21/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	99,627	43,495	56%	1,914,305	708,850	63%	28,861,629	7,183,136	75%
Northeast Corridor	81%	37,082	21,100	43%	814,952	318,956	61%	12,658,733	3,102,149	75%
Acela	83%	6,015	3,934	35%	180,218	67,930	62%	2,516,983	670,607	73%
Northeast Regional	79%	31,067	17,166	45%	634,734	251,026	60%	10,141,750	2,431,542	76%
Richmond / Newport News / Norfolk	77%	9,608	5,639	41%	198,286	97,273	51%	3,149,014	910,894	71%
Springfield Shuttles	89%	556	52	91%	11,788	3,543	70%	179,822	27,757	85%
Roanoke	79%	3,187	2,108	34%	61,720	29,136	53%	954,780	204,421	79%
On Spine Northeast Regional	80%	17,716	9,367	47%	362,940	121,074	67%	5,858,134	1,288,470	78%
State Supported	80%	47,228	12,173	74%	865,399	238,620	72%	12,651,447	2,600,984	79%
Borealis	80%	568	0	100%	10,793	2,308	79%	161,763	32,754	80%
Capitol Corridor	90%	2,613	204	92%	67,292	10,025	85%	1,068,511	139,221	87%
Carolinian	70%	574	338	41%	19,463	12,965	33%	329,437	128,871	61%
Cascades	75%	2,998	574	81%	56,593	14,109	75%	744,237	202,669	73%
Downeaster	82%	2,007	0	100%	34,963	8,243	76%	432,461	53,713	88%
Empire	78%	5,248	1,360	74%	109,652	39,681	64%	1,563,657	354,098	77%
Adirondack	72%	469	141	70%	7,724	3,598	53%	94,157	29,082	69%
Ethan Allen Express	70%	515	451	12%	10,452	6,999	33%	161,417	54,606	66%
Maple Leaf	70%	522	182	65%	15,323	6,122	60%	190,142	72,909	62%
New York - Albany	85%	2,487	496	80%	48,835	11,626	76%	726,000	115,526	84%
New York - Niagara Falls	75%	1,255	90	93%	24,686	9,486	62%	386,145	79,265	79%
Berkshire Flyer	60%	0	0	-	2,632	1,850	30%	5,796	2,710	53%
Gold Runner	73%	2,876	823	71%	48,221	19,304	60%	721,841	251,402	65%
Heartland Flyer	70%	322	39	88%	5,045	2,607	48%	60,750	23,100	62%
Hiawatha	90%	2,240	170	92%	35,918	2,402	93%	493,612	52,950	89%
Illinois	78%	2,682	1,477	45%	46,807	17,394	63%	708,962	193,438	73%
Carl Sandburg / Illinois Zephyr	85%	434	144	67%	8,534	3,204	62%	118,088	31,010	74%
Illini / Saluki	85%	761	757	1%	15,790	5,920	63%	249,452	59,947	76%
Lincoln Service	70%	1,487	576	61%	22,483	8,270	63%	341,422	102,481	70%
Keystone	92%	5,671	753	87%	128,622	19,893	85%	2,185,699	229,828	89%
Lincoln / Missouri	70%	827	339	59%	12,871	7,266	44%	221,390	111,082	50%
Mardi Gras Service	80%	324	203	37%	7,295	2,737	62%	118,243	25,198	79%
Michigan	70%	2,748	298	89%	42,698	16,186	62%	562,445	181,141	68%
Blue Water	70%	589	0	100%	10,798	6,821	37%	131,024	52,155	60%
Pere Marquette	85%	374	0	100%	6,159	1,268	79%	73,731	14,598	80%
Wolverine	70%	1,785	298	83%	25,741	8,097	69%	357,690	114,388	68%
Missouri	80%	263	1	100%	3,377	1,244	63%	62,613	14,484	77%
Pacific Surfliner	85%	11,760	3,783	68%	184,209	39,218	79%	2,266,733	366,380	84%
Pennsylvanian	80%	843	327	61%	16,179	6,503	60%	254,889	48,662	81%
Piedmont	80%	1,446	878	39%	13,170	6,236	53%	326,555	84,790	74%
Vermont	75%	1,218	606	50%	22,231	10,299	54%	367,649	107,203	71%
Long Distance	70%	15,317	10,222	33%	233,954	151,274	35%	3,512,182	1,477,540	58%
Auto Train	70%	860	0	100%	14,885	6,160	59%	223,729	76,988	66%
California Zephyr	70%	1,070	969	9%	18,496	12,413	33%	278,559	97,710	65%
Cardinal	70%	600	360	40%	4,670	3,248	30%	68,344	33,490	51%
City Of New Orleans	75%	741	741	0%	4,394	3,478	21%	181,758	53,095	71%
Coast Starlight	70%	1,985	671	66%	22,751	7,308	68%	327,515	111,760	66%
Crescent	70%	992	614	38%	17,238	9,944	42%	267,731	82,036	69%
Empire Builder	70%	1,803	1,689	6%	22,533	15,155	33%	275,594	133,907	51%
Floridian	60%	2,300	2,246	2%	28,251	26,756	5%	458,416	310,399	32%
Lake Shore Ltd	73%	1,172	272	77%	21,421	9,137	57%	273,058	80,747	70%
Palmetto	70%	990	773	22%	16,147	11,389	29%	263,920	77,487	71%
Silver Meteor	70%	1,135	760	33%	19,316	15,881	18%	291,697	126,033	57%
Southwest Chief	60%	1,004	676	33%	18,328	13,518	26%	236,978	151,930	36%
Sunset Ltd	70%	0	0	-	5,903	3,645	38%	84,288	30,326	64%
Texas Eagle	70%	665	451	32%	19,621	13,242	33%	280,595	111,632	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FOI-00000 00000000020 "UNCLASSIFIED" 7/21/2020

Train Index Dates Through July 18, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	127,715	1,902,623	671	1,694,648	30,533,707	555

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,640	557,750	137	80,980	8,766,247	92
INFRASTRUCTURE PLANNED	135	9,160	557,750	164	88,032	8,766,247	100
FLEET RELIABILITY	90	19,157	1,902,623	101	272,146	30,533,707	89
TRAIN OPERATIONS	424	91,758	1,902,623	482	1,253,490	30,533,707	411

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak or Commuter: **Amtrak**

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-006310-000000

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/18/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	284	41	85.6%	5,480	816	85.1%	86,824	11,937	86.3%
Central Division	86.0%	59	5	91.5%	990	101	89.8%	16,681	1,492	91.1%
CDL	95.0%	2	1	50.0%	33	4	87.9%	550	22	96.0%
CHI	86.0%	27	4	85.2%	465	55	88.2%	7,702	918	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	18	1	94.4%	314	35	88.9%
GBB	-	-	-	-	8	7	12.5%	8	7	12.5%
GRR	95.5%	1	0	100.0%	17	0	100.0%	276	8	97.1%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	27	2	92.6%	565	42	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	106	6	94.3%	1,704	103	94.0%
MOE	97.5%	2	0	100.0%	36	1	97.2%	581	9	98.5%
MSP	96.5%	1	0	100.0%	18	0	100.0%	284	5	98.2%
NOL	94.5%	5	0	100.0%	70	6	91.4%	1,220	59	95.2%
OKC	97.0%	1	0	100.0%	18	0	100.0%	285	6	97.9%
PNT	88.0%	3	0	100.0%	45	4	91.1%	748	62	91.7%
PTH	93.0%	1	0	100.0%	18	1	94.4%	279	11	96.1%
QCY	91.0%	2	0	100.0%	25	3	88.0%	556	43	92.3%
SAS	90.5%	1	0	100.0%	18	3	83.3%	287	30	89.5%
STL	89.0%	4	0	100.0%	67	7	89.6%	1,124	97	91.4%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	141	23	83.7%	2,873	498	82.7%	45,459	7,110	84.4%
ALB	88.5%	8	0	100.0%	139	8	94.2%	2,153	169	92.2%
ATL	-	-	-	-	-	-	-	35	5	85.7%
BON	87.5%	5	0	100.0%	89	12	86.5%	1,401	152	89.2%
BOS	85.5%	15	4	73.3%	296	21	92.9%	4,932	582	88.2%
BRK	92.5%	5	0	100.0%	86	13	84.9%	1,387	97	93.0%
BTN	82.0%	1	0	100.0%	18	1	94.4%	277	40	85.6%
CLT	91.5%	5	0	100.0%	71	17	76.1%	1,412	149	89.4%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	36	4	88.9%	567	54	90.5%
GRO	-	-	-	-	4	0	100.0%	33	10	69.7%
HAR	79.5%	7	0	100.0%	189	25	86.8%	3,212	531	83.5%
HFD	-	-	-	-	24	4	83.3%	171	12	93.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	18	1	94.4%	287	35	87.8%
MIA	89.5%	2	0	100.0%	35	5	85.7%	574	65	88.7%
MTR	79.0%	1	0	100.0%	18	4	77.8%	274	50	81.8%

Information Management

26-FOI-0060 Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/18/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/18/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	284	41	85.6%	5,480	816	85.1%	86,824	11,937	86.3%
East Division	82.0%	141	23	83.7%	2,873	498	82.7%	45,459	7,110	84.4%
NFK	84.5%	2	0	100.0%	36	9	75.0%	657	118	82.0%
NFL	93.5%	2	0	100.0%	36	3	91.7%	586	25	95.7%
NFS	-	-	-	-	1	1	0.0%	7	6	14.3%
NHV	78.0%	4	0	100.0%	86	14	83.7%	1,492	237	84.1%
NPN	93.0%	2	0	100.0%	34	4	88.2%	547	39	92.9%
NYP	75.5%	36	6	83.3%	811	199	75.5%	11,862	2,660	77.6%
PGH	93.0%	1	0	100.0%	18	3	83.3%	289	22	92.4%
PHL	48.0%	4	1	75.0%	88	37	58.0%	1,488	714	52.0%
PIT	76.0%	-	-	-	5	5	0.0%	11	10	9.1%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	4	0	100.0%	49	6	87.8%	1,106	47	95.8%
RNK	83.5%	2	1	50.0%	36	8	77.8%	570	85	85.1%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	15	0	100.0%	274	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	16	0	100.0%	284	10	96.5%
SFA	88.0%	1	0	100.0%	18	1	94.4%	287	38	86.8%
SPG	92.5%	6	0	100.0%	87	6	93.1%	1,739	98	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	17	1	94.1%	276	57	79.3%
WAS	84.0%	22	11	50.0%	493	82	83.4%	7,086	923	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	84	13	84.5%	1,617	217	86.6%	24,684	3,335	86.5%
ARN	92.0%	1	1	0.0%	18	5	72.2%	289	24	91.7%
BFD	79.0%	7	0	100.0%	121	26	78.5%	1,807	367	79.7%
EMY	72.0%	1	0	100.0%	18	7	61.1%	305	93	69.5%
EUG	86.5%	2	1	50.0%	36	1	97.2%	572	53	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	1	50.0%	3	2	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	54	14	74.1%	870	128	85.3%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	188	20	89.4%	2,863	296	89.7%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	9	2	77.8%	211	58	72.5%	3,110	794	74.5%
PDX	86.0%	5	0	100.0%	90	6	93.3%	1,427	172	87.9%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	4	66.7%	268	27	89.9%	4,073	437	89.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/18/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/18/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	284	41	85.6%	5,480	816	85.1%	86,824	11,937	86.3%
West Division	86.0%	84	13	84.5%	1,617	217	86.6%	24,684	3,335	86.5%
SAN	90.5%	13	1	92.3%	233	17	92.7%	3,477	311	91.1%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	144	17	88.2%	2,286	327	85.7%
SJC	89.0%	7	2	71.4%	126	15	88.1%	2,033	197	90.3%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	54	2	96.3%	633	62	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	18	1	94.4%	284	21	92.6%
VAC	97.0%	2	0	100.0%	36	0	100.0%	566	14	97.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	521	18	2	88.9%	289	56	80.6%	18	9	50.0%	287	126	56.1%
4		18	1	94.4%	288	43	85.1%	18	10	44.4%	288	189	34.4%
5	150	18	3	83.3%	287	46	84.0%	17	14	17.6%	283	77	72.8%
6	126	18	7	61.1%	286	84	70.6%	18	12	33.3%	286	94	67.1%
7	73	18	2	88.9%	278	37	86.7%	18	7	61.1%	271	68	74.9%
8	189	18	9	50.0%	278	120	56.8%	18	15	16.7%	277	164	40.8%
11		18	3	83.3%	289	53	81.7%	18	3	83.3%	283	57	79.9%
14		18	3	83.3%	290	44	84.8%	18	3	83.3%	288	86	70.1%
19	154	18	9	50.0%	288	74	74.3%	18	11	38.9%	286	70	75.5%
20		18	4	77.8%	288	22	92.4%	18	9	50.0%	288	56	80.6%
21	174	18	1	94.4%	285	23	91.9%	18	13	27.8%	284	75	73.6%
22	131	18	3	83.3%	286	28	90.2%	18	13	27.8%	284	75	73.6%
23	18	18	1	94.4%	291	6	97.9%	18	9	50.0%	289	78	73.0%
24	87	18	2	88.9%	291	16	94.5%	18	7	61.1%	290	50	82.8%
25		18	0	100.0%	290	3	99.0%	18	7	61.1%	288	76	73.6%
26	23	18	0	100.0%	290	5	98.3%	18	6	66.7%	288	58	79.9%
27	88	18	4	77.8%	276	18	93.5%	18	8	55.6%	272	89	67.3%
28		18	2	88.9%	272	61	77.6%	18	2	88.9%	272	53	80.5%
40	128	17	3	82.4%	283	41	85.5%	17	15	11.8%	282	147	47.9%
40	Cncld	17	3	82.4%	283	41	85.5%	17	15	11.8%	282	147	47.9%
41	226	17	8	52.9%	283	110	61.1%	17	17	0.0%	281	213	24.2%
42		18	3	83.3%	290	23	92.1%	18	6	66.7%	288	48	83.3%
43	29	18	1	94.4%	289	42	85.5%	18	11	38.9%	289	67	76.8%
48		18	3	83.3%	288	56	80.6%	18	3	83.3%	288	41	85.8%
49		18	4	77.8%	288	71	75.3%	18	7	61.1%	288	59	79.5%
51		8	4	50.0%	120	53	55.8%	8	5	37.5%	116	42	63.8%
52		18	1	94.4%	287	38	86.8%	18	6	66.7%	286	67	76.6%
53		18	1	94.4%	287	35	87.8%	18	6	66.7%	286	91	68.2%
54	99	6	1	83.3%	106	7	93.4%	6	3	50.0%	106	16	84.9%
57		6	1	83.3%	105	5	95.2%	6	3	50.0%	105	9	91.4%
59	50	6	2	66.7%	264	30	88.6%	5	5	0.0%	260	51	80.4%
63	92	18	10	44.4%	291	127	56.4%	17	15	11.8%	286	155	45.8%
64	240	18	2	88.9%	289	65	77.5%	18	10	44.4%	289	101	65.1%
65	111	7	0	100.0%	90	12	86.7%	5	1	80.0%	88	12	86.4%
66		18	6	66.7%	288	60	79.2%	16	2	87.5%	284	51	82.0%
68		18	4	77.8%	291	59	79.7%	18	10	44.4%	291	113	61.2%
69	28	18	3	83.3%	278	62	77.7%	18	8	55.6%	274	40	85.4%
71	11	18	0	100.0%	286	3	99.0%	18	11	38.9%	285	77	73.0%
72		14	2	85.7%	282	31	89.0%	14	4	71.4%	281	59	79.0%
73	22	13	2	84.6%	285	18	93.7%	13	8	38.5%	283	134	52.7%
74	24	13	3	76.9%	283	33	88.3%	13	9	30.8%	281	103	63.3%
75	28	9	1	88.9%	279	15	94.6%	8	6	25.0%	273	131	52.0%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	19	9	2	77.8%	279	28	90.0%	8	5	37.5%	270	109	59.6%
77	17	12	3	75.0%	281	20	92.9%	12	9	25.0%	279	117	58.1%
78		17	5	70.6%	285	25	91.2%	17	10	41.2%	284	60	78.9%
79	75	18	0	100.0%	288	55	80.9%	18	14	22.2%	287	98	65.9%
80	131	18	5	72.2%	288	33	88.5%	17	10	41.2%	285	59	79.3%
82	60	4	2	50.0%	71	9	87.3%	4	4	0.0%	71	24	66.2%
87	73	6	0	100.0%	109	24	78.0%	6	5	16.7%	109	38	65.1%
88	37	3	1	66.7%	105	15	85.7%	3	1	66.7%	105	23	78.1%
89		18	5	72.2%	286	63	78.0%	18	12	33.3%	284	82	71.1%
90		18	0	100.0%	286	10	96.5%	18	11	38.9%	285	48	83.2%
97		18	16	11.1%	288	189	34.4%	18	14	22.2%	286	90	68.5%
98	200	18	2	88.9%	288	23	92.0%	18	17	5.6%	286	97	66.1%
99	160	6	0	100.0%	108	12	88.9%	4	3	25.0%	105	60	42.9%
101		4	0	100.0%	70	6	91.4%	4	0	100.0%	70	11	84.3%
103		6	0	100.0%	107	21	80.4%	6	1	83.3%	107	9	91.6%
106		2	0	100.0%	86	9	89.5%	2	1	50.0%	85	12	85.9%
107		2	1	50.0%	86	28	67.4%	2	1	50.0%	85	13	84.7%
109	50	4	0	100.0%	53	8	84.9%	4	1	75.0%	53	6	88.7%
118	17	6	2	66.7%	107	8	92.5%	6	2	66.7%	107	7	93.5%
124	95	6	1	83.3%	106	8	92.5%	6	6	0.0%	105	29	72.4%
126	40	4	1	75.0%	49	8	83.7%	4	4	0.0%	49	12	75.5%
127	22	4	2	50.0%	49	14	71.4%	4	1	75.0%	49	6	87.8%
135	28	6	0	100.0%	108	17	84.3%	6	5	16.7%	108	56	48.1%
136		12	3	75.0%	182	23	87.4%	13	5	61.5%	181	22	87.8%
140		6	0	100.0%	107	12	88.8%	6	2	66.7%	106	22	79.2%
142	112	2	1	50.0%	69	7	89.9%	2	2	0.0%	68	9	86.8%
143		6	2	66.7%	106	11	89.6%	6	2	66.7%	106	24	77.4%
144		4	2	50.0%	71	47	33.8%	4	0	100.0%	70	9	87.1%
146	63	6	1	83.3%	106	17	84.0%	6	5	16.7%	106	39	63.2%
147	121	4	1	75.0%	72	8	88.9%	4	4	0.0%	72	24	66.7%
150		6	2	66.7%	105	56	46.7%	6	2	66.7%	103	50	51.5%
151	141	18	5	72.2%	287	91	68.3%	18	10	44.4%	286	94	67.1%
152	83	4	1	75.0%	71	6	91.5%	4	2	50.0%	71	27	62.0%
153		6	2	66.7%	107	10	90.7%	6	2	66.7%	107	16	85.0%
155	23	6	3	50.0%	109	18	83.5%	6	6	0.0%	109	39	64.2%
156	65	6	1	83.3%	109	11	89.9%	6	6	0.0%	109	37	66.1%
158	86	6	3	50.0%	108	18	83.3%	6	6	0.0%	108	26	75.9%
159	49	2	0	100.0%	69	7	89.9%	2	2	0.0%	69	11	84.1%
160	Cncld	6	1	83.3%	106	6	94.3%	5	2	60.0%	103	25	75.7%
161	99	6	0	100.0%	107	9	91.6%	6	6	0.0%	106	69	34.9%
162	161	6	2	66.7%	107	7	93.5%	6	5	16.7%	107	54	49.5%
163	115	2	0	100.0%	69	15	78.3%	2	2	0.0%	69	56	18.8%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
164	145	6	1	83.3%	109	9	91.7%	6	3	50.0%	109	47	56.9%
167	98	4	1	75.0%	72	16	77.8%	4	2	50.0%	71	22	69.0%
168	56	4	2	50.0%	70	12	82.9%	4	4	0.0%	70	26	62.9%
178		12	1	91.7%	182	25	86.3%	13	5	61.5%	181	28	84.5%
179		12	2	83.3%	182	21	88.5%	13	6	53.8%	182	64	64.8%
194	53	4	2	50.0%	71	17	76.1%	4	4	0.0%	70	22	68.6%
195		6	0	100.0%	107	4	96.3%	6	4	33.3%	107	56	47.7%
198		12	3	75.0%	114	17	85.1%	13	4	69.2%	114	20	82.5%
230		18	0	100.0%	125	4	96.8%	18	0	100.0%	125	6	95.2%
232		18	0	100.0%	291	11	96.2%	18	0	100.0%	291	17	94.2%
233		13	3	76.9%	264	59	77.7%	13	9	30.8%	264	82	68.9%
234		18	1	94.4%	291	20	93.1%	18	0	100.0%	291	24	91.8%
235		18	2	88.9%	215	29	86.5%	18	6	66.7%	215	47	78.1%
236		18	2	88.9%	275	9	96.7%	18	3	83.3%	275	39	85.8%
237		18	3	83.3%	289	55	81.0%	18	5	72.2%	287	48	83.3%
238		18	0	100.0%	215	19	91.2%	18	1	94.4%	214	15	93.0%
239		18	4	77.8%	290	76	73.8%	18	4	77.8%	289	34	88.2%
240	23	18	0	100.0%	290	20	93.1%	18	9	50.0%	288	53	81.6%
241		18	4	77.8%	291	72	75.3%	18	3	83.3%	291	69	76.3%
243	47	18	7	61.1%	227	62	72.7%	18	5	72.2%	226	31	86.3%
244	41	13	2	84.6%	264	12	95.5%	13	7	46.2%	264	45	83.0%
245		18	4	77.8%	172	31	82.0%	18	3	83.3%	171	20	88.3%
280		18	2	88.9%	291	13	95.5%	18	3	83.3%	291	53	81.8%
281		18	3	83.3%	291	32	89.0%	18	7	61.1%	291	54	81.4%
283		18	6	66.7%	291	70	75.9%	18	7	61.1%	291	59	79.7%
284		18	1	94.4%	291	11	96.2%	18	9	50.0%	289	51	82.4%
290	28	18	1	94.4%	291	49	83.2%	18	13	27.8%	289	104	64.0%
291		18	10	44.4%	290	85	70.7%	18	9	50.0%	288	67	76.7%
300		18	1	94.4%	275	20	92.7%	18	8	55.6%	273	64	76.6%
301		18	0	100.0%	289	9	96.9%	18	3	83.3%	286	53	81.5%
302	45	12	1	91.7%	270	32	88.1%	12	4	66.7%	266	76	71.4%
305		12	0	100.0%	273	28	89.7%	12	7	41.7%	269	109	59.5%
306		18	0	100.0%	287	15	94.8%	18	6	66.7%	286	77	73.1%
307	30	18	3	83.3%	279	38	86.4%	18	8	55.6%	276	78	71.7%
311		15	2	86.7%	286	25	91.3%	14	5	64.3%	280	55	80.4%
316		14	1	92.9%	282	17	94.0%	13	6	53.8%	278	70	74.8%
318		17	4	76.5%	289	30	89.6%	17	11	35.3%	286	135	52.8%
319	32	17	1	94.1%	290	18	93.8%	14	10	28.6%	285	155	45.6%
330		16	0	100.0%	247	4	98.4%	16	1	93.8%	247	14	94.3%
331		18	2	88.9%	291	31	89.3%	18	1	94.4%	291	41	85.9%
332		18	2	88.9%	291	16	94.5%	18	3	83.3%	291	42	85.6%
334		18	0	100.0%	291	9	96.9%	18	1	94.4%	290	37	87.2%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		18	0	100.0%	291	30	89.7%	18	4	77.8%	289	47	83.7%
336		18	1	94.4%	291	9	96.9%	18	2	88.9%	289	27	90.7%
337		18	1	94.4%	291	18	93.8%	18	2	88.9%	287	35	87.8%
338		18	3	83.3%	291	44	84.9%	18	6	66.7%	289	87	69.9%
339		18	2	88.9%	291	48	83.5%	18	2	88.9%	291	50	82.8%
341	26	18	5	72.2%	280	40	85.7%	18	4	77.8%	275	39	85.8%
342		18	0	100.0%	291	21	92.8%	18	2	88.9%	289	55	81.0%
343	13	3	0	100.0%	41	3	92.7%	3	1	66.7%	41	10	75.6%
350		14	1	92.9%	268	18	93.3%	12	5	58.3%	261	141	46.0%
351		18	2	88.9%	274	27	90.1%	18	5	72.2%	272	73	73.2%
352	43	18	1	94.4%	258	21	91.9%	18	5	72.2%	252	76	69.8%
353		14	1	92.9%	229	13	94.3%	14	2	85.7%	223	37	83.4%
354		18	7	61.1%	272	35	87.1%	15	7	53.3%	265	96	63.8%
355		14	2	85.7%	281	29	89.7%	14	8	42.9%	274	93	66.1%
364		18	2	88.9%	280	62	77.9%	18	11	38.9%	274	101	63.1%
365		18	1	94.4%	279	11	96.1%	18	11	38.9%	277	103	62.8%
370		18	1	94.4%	282	34	87.9%	17	3	82.4%	274	68	75.2%
371		17	0	100.0%	276	8	97.1%	17	2	88.2%	275	29	89.5%
380		17	3	82.4%	276	27	90.2%	17	8	52.9%	276	57	79.3%
381		16	0	100.0%	289	11	96.2%	16	4	75.0%	288	52	81.9%
382	134	16	7	56.3%	288	23	92.0%	16	10	37.5%	288	94	67.4%
383	32	18	1	94.4%	280	26	90.7%	17	10	41.2%	277	115	58.5%
390	171	18	1	94.4%	273	18	93.4%	18	7	61.1%	272	70	74.3%
391	212	16	2	87.5%	274	10	96.4%	16	7	56.3%	271	72	73.4%
392	126	15	3	80.0%	287	8	97.2%	15	10	33.3%	285	88	69.1%
393	92	18	1	94.4%	291	17	94.2%	18	12	33.3%	288	89	69.1%
400		6	0	100.0%	88	6	93.2%	6	0	100.0%	86	2	97.7%
405		4	0	100.0%	81	0	100.0%	4	0	100.0%	81	4	95.1%
448		18	5	72.2%	221	43	80.5%	18	6	66.7%	219	74	66.2%
449		18	2	88.9%	219	32	85.4%	18	4	77.8%	219	40	81.7%
450		4	0	100.0%	85	26	69.4%	4	2	50.0%	83	26	68.7%
460		4	0	100.0%	84	27	67.9%	4	3	25.0%	81	28	65.4%
461		6	0	100.0%	89	5	94.4%	6	0	100.0%	88	2	97.7%
463		3	0	100.0%	45	4	91.1%	3	0	100.0%	45	0	100.0%
464		4	0	100.0%	84	16	81.0%	4	1	75.0%	82	25	69.5%
467		3	0	100.0%	45	1	97.8%	3	1	66.7%	44	3	93.2%
488		7	4	42.9%	93	25	73.1%	6	2	66.7%	84	13	84.5%
499		6	2	66.7%	85	13	84.7%	6	0	100.0%	82	6	92.7%
500		18	1	94.4%	282	16	94.3%	17	1	94.1%	279	33	88.2%
502		18	1	94.4%	289	16	94.5%	17	1	94.1%	285	57	80.0%
503		18	1	94.4%	287	26	90.9%	18	9	50.0%	281	83	70.5%
504	122	18	0	100.0%	291	17	94.2%	18	5	72.2%	289	87	69.9%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		18	1	94.4%	289	37	87.2%	17	6	64.7%	284	79	72.2%
506		18	2	88.9%	286	40	86.0%	18	3	83.3%	281	44	84.3%
507		18	1	94.4%	291	35	88.0%	18	5	72.2%	291	93	68.0%
508		18	1	94.4%	286	40	86.0%	18	4	77.8%	283	66	76.7%
509		18	1	94.4%	288	13	95.5%	18	3	83.3%	288	66	77.1%
511		18	0	100.0%	283	21	92.6%	18	0	100.0%	282	45	84.0%
516		18	1	94.4%	283	28	90.1%	18	3	83.3%	282	126	55.3%
517	65	18	0	100.0%	291	8	97.3%	18	12	33.3%	287	120	58.2%
518	33	18	0	100.0%	291	35	88.0%	18	12	33.3%	289	195	32.5%
519		18	0	100.0%	283	9	96.8%	18	1	94.4%	281	64	77.2%
562		18	1	94.4%	283	22	92.2%	18	1	94.4%	280	30	89.3%
564		18	1	94.4%	283	18	93.6%	18	3	83.3%	275	33	88.0%
566	38	18	3	83.3%	281	20	92.9%	18	4	77.8%	278	36	87.1%
567		18	1	94.4%	168	9	94.6%	18	1	94.4%	166	7	95.8%
572	19	18	0	100.0%	278	22	92.1%	17	9	47.1%	272	74	72.8%
573		18	0	100.0%	281	40	85.8%	18	2	88.9%	274	46	83.2%
579		18	0	100.0%	168	8	95.2%	18	4	77.8%	163	30	81.6%
580		18	0	100.0%	283	14	95.1%	18	2	88.9%	278	23	91.7%
581		18	3	83.3%	283	46	83.7%	18	4	77.8%	281	58	79.4%
584	56	18	5	72.2%	167	22	86.8%	17	14	17.6%	162	96	40.7%
587	33	17	0	100.0%	277	15	94.6%	17	7	58.8%	268	45	83.2%
588		18	2	88.9%	168	14	91.7%	18	2	88.9%	167	24	85.6%
591		18	0	100.0%	282	18	93.6%	18	2	88.9%	276	31	88.8%
593		18	4	77.8%	277	41	85.2%	17	1	94.1%	258	28	89.1%
595	41	18	4	77.8%	278	45	83.8%	18	4	77.8%	275	50	81.8%
611		4	4	0.0%	42	30	28.6%	4	0	100.0%	42	4	90.5%
624	16	3	1	66.7%	117	38	67.5%	3	1	66.7%	118	30	74.6%
660		5	1	80.0%	78	12	84.6%	4	0	100.0%	77	25	67.5%
661		5	0	100.0%	106	11	89.6%	5	2	60.0%	105	39	62.9%
662		4	0	100.0%	44	0	100.0%	4	0	100.0%	44	1	97.7%
663		6	4	33.3%	79	14	82.3%	5	1	80.0%	78	7	91.0%
664	26	6	2	66.7%	78	8	89.7%	6	5	16.7%	78	11	85.9%
665	40	6	2	66.7%	79	10	87.3%	6	5	16.7%	79	24	69.6%
666		4	2	50.0%	77	22	71.4%	4	0	100.0%	77	7	90.9%
667	22	4	0	100.0%	77	6	92.2%	2	2	0.0%	75	16	78.7%
669		5	0	100.0%	77	7	90.9%	3	2	33.3%	75	22	70.7%
670		6	2	66.7%	79	12	84.8%	4	2	50.0%	77	15	80.5%
671		5	2	60.0%	77	8	89.6%	3	2	33.3%	75	9	88.0%
672		6	1	83.3%	79	8	89.9%	6	3	50.0%	79	15	81.0%
674		5	3	40.0%	77	25	67.5%	5	2	60.0%	77	6	92.2%
690		5	0	100.0%	83	2	97.6%	5	0	100.0%	82	4	95.1%
691		5	0	100.0%	83	7	91.6%	5	2	60.0%	81	23	71.6%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
692		5	0	100.0%	83	3	96.4%	5	1	80.0%	82	14	82.9%
693		5	0	100.0%	83	12	85.5%	4	2	50.0%	81	23	71.6%
694		4	2	50.0%	82	8	90.2%	4	0	100.0%	82	14	82.9%
695		4	1	75.0%	81	10	87.7%	4	0	100.0%	81	14	82.7%
696		5	1	80.0%	83	9	89.2%	5	4	20.0%	83	24	71.1%
697		5	2	60.0%	83	18	78.3%	5	2	60.0%	83	17	79.5%
698		5	0	100.0%	81	2	97.5%	5	0	100.0%	81	7	91.4%
701		18	3	83.3%	223	24	89.2%	18	3	83.3%	220	23	89.5%
702		18	1	94.4%	290	32	89.0%	17	5	70.6%	287	65	77.4%
703		18	9	50.0%	291	86	70.4%	17	9	47.1%	289	79	72.7%
704		18	2	88.9%	222	34	84.7%	17	2	88.2%	216	40	81.5%
710		18	6	66.7%	291	75	74.2%	18	5	72.2%	287	78	72.8%
711		18	3	83.3%	282	31	89.0%	14	2	85.7%	261	47	82.0%
712		18	5	72.2%	288	76	73.6%	17	4	76.5%	279	91	67.4%
713	23	14	1	92.9%	160	15	90.6%	13	6	53.8%	146	62	57.5%
714		17	10	41.2%	172	68	60.5%	17	9	47.1%	160	67	58.1%
715	42	18	2	88.9%	290	60	79.3%	14	7	50.0%	267	132	50.6%
716		18	7	61.1%	291	114	60.8%	17	5	70.6%	285	107	62.5%
717		17	2	88.2%	276	64	76.8%	16	6	62.5%	257	76	70.4%
718	33	18	8	55.6%	291	144	50.5%	18	10	44.4%	289	101	65.1%
719		18	6	66.7%	291	94	67.7%	17	7	58.8%	276	79	71.4%
720		5	0	100.0%	90	9	90.0%	5	1	80.0%	90	5	94.4%
723		5	1	80.0%	90	6	93.3%	5	0	100.0%	90	9	90.0%
724		5	0	100.0%	90	3	96.7%	5	2	60.0%	90	17	81.1%
727		5	0	100.0%	90	6	93.3%	5	0	100.0%	90	14	84.4%
728		5	0	100.0%	90	6	93.3%	5	1	80.0%	90	16	82.2%
729	Cncld	5	5	0.0%	89	14	84.3%	4	1	75.0%	88	21	76.1%
732		5	0	100.0%	88	14	84.1%	5	1	80.0%	86	15	82.6%
733		5	1	80.0%	90	14	84.4%	5	2	60.0%	86	29	66.3%
734		5	0	100.0%	90	14	84.4%	5	2	60.0%	89	19	78.7%
736	Cncld	5	2	60.0%	66	6	90.9%	3	0	100.0%	64	7	89.1%
737		5	1	80.0%	66	7	89.4%	4	0	100.0%	65	11	83.1%
738	12	5	2	60.0%	90	14	84.4%	5	3	40.0%	86	13	84.9%
741		5	1	80.0%	90	13	85.6%	5	2	60.0%	90	17	81.1%
742		5	1	80.0%	90	11	87.8%	5	0	100.0%	88	7	92.0%
743		5	2	60.0%	90	17	81.1%	5	1	80.0%	89	9	89.9%
744		5	3	40.0%	90	14	84.4%	5	3	40.0%	90	31	65.6%
745		5	1	80.0%	90	8	91.1%	5	0	100.0%	90	14	84.4%
746		5	1	80.0%	90	7	92.2%	5	1	80.0%	90	13	85.6%
747	34	5	0	100.0%	90	14	84.4%	5	2	60.0%	90	20	77.8%
748		5	0	100.0%	89	12	86.5%	5	0	100.0%	89	13	85.4%
749	Cncld	5	1	80.0%	87	13	85.1%	4	1	75.0%	79	10	87.3%

Amtrak On Time Performance

Trains Arriving Through: 7/18/2026

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
751	52	5	1	80.0%	89	15	83.1%	5	2	60.0%	87	11	87.4%
757		18	1	94.4%	76	4	94.7%	18	3	83.3%	75	7	90.7%
761		18	1	94.4%	287	12	95.8%	18	2	88.9%	284	36	87.3%
765	57	18	0	100.0%	287	24	91.6%	18	2	88.9%	287	38	86.8%
769		18	1	94.4%	287	26	90.9%	18	2	88.9%	281	51	81.9%
770	39	18	0	100.0%	287	21	92.7%	18	8	55.6%	285	82	71.2%
774		18	0	100.0%	287	16	94.4%	18	5	72.2%	286	61	78.7%
777		18	1	94.4%	172	10	94.2%	18	3	83.3%	171	37	78.4%
782	18	18	14	22.2%	172	70	59.3%	18	3	83.3%	167	18	89.2%
785		18	2	88.9%	287	19	93.4%	18	3	83.3%	287	49	82.9%
786	16	18	1	94.4%	76	17	77.6%	18	9	50.0%	75	36	52.0%
790		18	0	100.0%	287	26	90.9%	18	3	83.3%	284	35	87.7%
794		18	1	94.4%	287	32	88.9%	18	3	83.3%	284	58	79.6%
821		18	0	100.0%	285	6	97.9%	18	10	44.4%	285	113	60.4%
822		18	1	94.4%	287	15	94.8%	18	12	33.3%	285	130	54.4%
1058	39	1	0	100.0%	3	1	66.7%	1	1	0.0%	3	2	33.3%
1333		18	2	88.9%	287	30	89.5%	18	6	66.7%	284	94	66.9%
1340		18	0	100.0%	286	5	98.3%	18	3	83.3%	286	45	84.3%
1689		10	0	100.0%	84	5	94.0%	10	1	90.0%	83	9	89.2%
2207		4	1	75.0%	22	5	77.3%	4	0	100.0%	22	5	77.3%
2208	74	6	3	50.0%	8	3	62.5%	6	3	50.0%	8	3	62.5%
2211		4	0	100.0%	5	1	80.0%	4	0	100.0%	5	1	80.0%
2219	58	6	2	66.7%	8	3	62.5%	6	4	33.3%	8	4	50.0%
2224	18	6	1	83.3%	23	5	78.3%	6	2	66.7%	23	4	82.6%
2250	Cncld	4	3	25.0%	103	11	89.3%	3	1	66.7%	102	35	65.7%
2252	173	5	1	80.0%	103	9	91.3%	5	3	40.0%	101	31	69.3%
2254	135	5	2	60.0%	38	2	94.7%	5	4	20.0%	38	12	68.4%
2255		6	0	100.0%	105	11	89.5%	6	4	33.3%	104	50	51.9%
2258	22	6	0	100.0%	41	9	78.0%	6	6	0.0%	40	18	55.0%
2259	51	6	1	83.3%	61	24	60.7%	6	4	33.3%	60	29	51.7%
2260	24	6	0	100.0%	6	0	100.0%	6	6	0.0%	6	6	0.0%
2262	33	4	2	50.0%	20	4	80.0%	4	4	0.0%	20	7	65.0%
2265	173	6	0	100.0%	42	3	92.9%	6	6	0.0%	41	26	36.6%
2271		5	1	80.0%	88	10	88.6%	5	4	20.0%	87	46	47.1%
2293	No OS	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Region: ALL

Service: ALL

Arriving On: 7/18/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2208	NYP	74	UTL	57	UTL	57	WAS-WAS	AM	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
2219	WAS	58	DCS	25	DCS	18	BAL-BWI	AM	Power switch failure, Milepost, 112.4, ., single tracking a/c 23 switch at Grove out of correspondence
2224	NYP	18	WTR	14	WTR	14	BAL-XPV	AM	Storm, Milepost, 71.6, 62.9, TOL on 2 track caused by a thunder storm
2250	BOS	Trn Cancelled							
2252	BOS	173	UTL	119	UTL	119	WAS-WAS	AM	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
2254	BOS	135	UTL	129	UTL	129	WAS-WAS	AM	Commercial power outage, Control Point, C INT, K INT, IVY CITY , OBSTRUCTED ALL MOVEMENTS FROM THE YARD TO THE TERMINAL, DELAYED OUTBOUNDS, REASSIGNED POWER FOR THE EQUIPMENT.
2258	BOS	22	OTH	17	DET	12	XHM-XCY	AM	Catenary maintenance , Other, XMW-XCY OPERTAED NO.1 TRACK
2259	WAS	51	ENG	29	ENG	29	BOS-BOS	AM	Air / Brake, 2153 NG NP, An ACSES and Brake test will be conducted/ multiple fault
2260	BOS	24	OTH	13	DCS	11	XPV-PHL	AM	T.O.L, Control Point, PHIL TO PENN, 241 A/C TOL ON NO. 3 TRK BETWEEN PHIL AND PENN; UNABLE TO DISPLAY SIGNALS
2262	BOS	33	ENG	36	ENG	30	BAL-XPV	AM	Traction motor, 2148 NG NP, stopped just south of Aberdeen a/c two unknown faults, crew was able to rectify the issue
2265	WAS	173	TRS	140	TRS	140	XPV-BAL	AM	Trespasser strike, Milepost, 65.5, .
2293	NYP	No OS Rpt	DSR	21	DSR	9	STM-XSH	MN	Per bulletin Stop signal trespasser strike and they were doing train to train transfer ahead, Control Point, 229, 0, 1
65	NPN	111	UTL	122	UTL	116	NCR-NCR	AM	Commercial power outage, Control Point, ., HELD FOR DISPOSITION A/C K AND C INTERLOCKINGS IN WASHINGTON TERMINAL HAD MULTIPLE TOLS ACROSS ALL TRACKS.

Amtrak Endpoint OTP Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/18/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
82	BOS	60	UTL	38	UTL	38	WAS-WAS	AM	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment	
87	NFK	73	DCS	64	DCS	55	BAL-BAL	AM	Power switch failure, Milepost, 112.4, ., single tracking a/c 23 switch at Grove out of correspondence	
88	BOS	37	PTI	23	DCS	11	WIL-PHL	AM	T.O.L, Control Point, PHIL, HELD ON NO. 1 TRK AT PHIL FOR 2255 SOUTH ON NO. 3 TRACK. TOL ON NO. 3 TRK BETWEEN PHIL AND PENN	
99	NPN	160	DCS	231	DCS	109	BAL-BWI	AM	Power switch failure, Milepost, 112.4, ., had to reverse & single tracking a/c 23 switch at Grove out of correspondence	
109	WAS	50	DCS	59	DCS	59	PHL-PHL	AM	Signal suspension, Control Point, PENN, HELD FOR DISPOSITION A/C POWER ISSUES AT K TOWER	
118	NYP	17	DCS	17	DCS	17	WIL-PHL	AM	T.O.L, Control Point, PHIL, HELD ON NO. 1 TRK FOR 127 SOUTH ON NO. 3 TRK. TOL ON NO. 3 TRK BETWEEN PHIL AND PENN	
124	PHL	95	WTR	67	WTR	30	WBG-RVM	CS	High winds Not exceeding 20 51.9-61.0 Not exceeding 40 61.0-76.2, Milepost, 51.9, 76.2	
126	NYP	40	WTR	33	WTR	24	BAL-XPV	AM	Storm, Milepost, 71.6, 62.9, TOL on 2 track caused by a thunder storm	
127	WAS	22	ENG	29	ENG	29	NWK-PJC	AM	HEP, 645 EX ES, STOPPED AT MP36 NO.4 TRK NO HEP ON ENG.645	
135	WAS	28	MTI	22	MTI	22	XSH-NYP	AM	Disabled train ahead, Other, AM194	
142	NYP	112	DCS	83	DCS	72	NCR-BWI	AM	Power switch failure, Milepost, 112.4, ., single tracking a/c 23 switch at Grove out of correspondence	
146	SPG	63	SVS	32	SVS	32	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Loop engine prior to power swap.	
147	RNK	121	DCS	50	DCS	28	BAL-BAL	AM	Power switch failure, Milepost, 112.4, ., single tracking a/c 23 switch at Grove out of correspondence	

Amtrak Endpoint OTP Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/18/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
151	RNK	141	UTL	128	UTL	73	BWI-BWI	AM	Commercial power outage, Control Point, ., HELD FOR DISPOSITION A/C K AND C INTERLOCKINGS IN WASHINGTON TERMINAL HAD MULTIPLE TOLS ACROSS ALL TRACKS.
152	BOS	83	UTL	57	UTL	57	WAS-WAS	AM	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
155	NFK	23	DSR	30	DSR	23	RVR-PTB	CS	Per dispatcher (radio/phone) High wind, Other, RVR, 40, all
156	NYP	65	PTI	47	PTI	16	XNY-BWI	AM	Follow, 2260, Milepost, 112.4, 106.3, held for 2260 ahead then followed
158	NYP	86	DCS	58	DCS	25	ASD-FBG	CS	Cab signal or ATS failure (wayside) Milepost, 43.3, 49.9
159	WAS	49	TRS	23	TRS	23	XPV-BAL	AM	Trespasser strike, Milepost, 65.5, ., 2165 trespasser strike
160	BOS	Trn Cancelled							
161	WAS	99	DCS	27	WTR	21	WIL-XPV	AM	Storm, Milepost, 57.3, 59.5, TOL on 3 track caused by a thunder storm
162	BOS	161	UTL	99	UTL	94	WAS-WAS	AM	Commercial power outage, Control Point, C INT, K INT, IVY CITY , OBSTRUCTED ALL MOVEMENTS FROM THE YARD TO THE TERMINAL, DELAYED OUTBOUNDS; REASSIGNED POWER FOR THE EQUIPMENT.
163	WAS	115	SYS	45	SYS	36	WIL-WIL	AM	Re-crew / job briefing, AWAITING A RECREW FROM WILMINGTON SHOPS
164	BOS	145	RTE	119	RTE	104	ALX-XVG	CS	Dispatcher hold Stop signal behind p098. Being held by k tower for unknown reasons, Other, cfp111.2
167	PHL	98	ITI	74	ITI	74	BOS-BOS	AM	Service, turn, or wye train, 162, late turn of AM162 BOS
168	BOS	56	WTR	31	WTR	22	BAL-XPV	AM	Storm, Milepost, 71.6, 62.9, TOL on 2 track caused by a thunder storm
194	BOS	53	ENG	43	ENG	35	NYP-XSH	AM	Air / Brake, 635 EX ES, ENGR REPORTED LOST AIR STOPPED ON NO.1 TRACK
79	CLT	75	WTR	51	FTI	30	RVR-PTB	CS	Follow IO31, Milepost w/Letters, CFP 4.6, A 22.0

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Region: ALL

Service: ALL

Arriving On: 7/18/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
80	NYP	131	DCS	94	DCS	84	XNY-BAL	AM	Power switch failure, Milepost, 112.4, ., single tracking a/c 23 switch at Grove out of correspondence	
624	NYP	16	SMW	20	SMW	20	NWK-NYP	AM	Scheduled in track usage program, Other, XBH-NYP, SINGLE TRACKING IN THE NORTH TUBE A/C SOUTHTUBE O/O/S	
664	NYP	26	WTR	24	WTR	24	TRE-NWK	AM	Flood / washout, Other, EWR-EWR, HELD A/C FLOODING	
665	HAR	40	WTR	56	WTR	21	NYP-NYP	AM	Flood / washout, Other, NYP-NYP, HELD A/C FLOODING AT EWR	
667	HAR	22	WTR	22	WTR	12	MJY-ELT	AM	Storm, Control Point, ROY, SIGNAL POWER LOST AT ROY A/C LIGHTNING STRIKE. RESTRICTIVE SIGNALS RHEEMS TO ROY.	
19	NOL	154	FTI	250	FTI	139	TCL-MEI	NS	Meet 342, 344, M30, Siding, Tuscaloosa, Siding, Bolligee, Siding, York	
63	TWO	92	WTR	76	WTR	61	ROC-BUF	CS	Flash flood warning Control Point, 385	
64	NYP	240	CUI	172	CUI	172	NFL-NFL	CS	United States	
69	MTR	28	CUI	38	CUI	38	XLQ-XLQ	CN	Canada	
240	NYP	23	CTI	26	CTI	26	POU-CRT	MN	Follow 8832 Failed Train, MNRR, 8832, Control Point, 53, Control Point, 39	
243	ALB	47	ENG	35	ENG	35	NYP-NYP	AM	HEP, 9707 CB DC, delayed out of the SSYD due to not being able to pull power.	
244	NYP	41	CTI	46	CTI	25	POU-CRT	MN	Follow Followed MNRR 8856 the entire way, MNRR, 8856, Milepost w/Letters, POU, CRT	
290	NYP	28	CTI	30	CTI	30	POU-CRT	MN	Follow metro, 8848, Milepost, 72, 39	
43	PGH	29	DSR	31	CON	18	PHL-PHL	AM	Hold for connecting train	
71	CLT	11	DSR	10	DCS	3	DNC-GRO	NS	Issue with automatic road crossing protection False activation, Milepost, 20.63, 20.63	
73	CLT	22	DSR	12	DSR	4	CYN-DNC	NS	Per bulletin Milepost w/Letters, 58.2NC, 58.1NC, 25, main track 1, Milepost w/Letters, 56.7NC, 56.6NC, 25, main track 1	
74	RGH	24	DSR	13	PTI	7	SAL-HPT	NS	Meet #AMTK75, Control Point, sharp	
75	CLT	28	DSR	15	DSR	4	CYN-DNC	NS	Per bulletin Milepost w/Letters, 58.2NC, 58.1NC, 25, 1	
76	RGH	19	TEN	10	PTI	7	KAN-GRO	NS	Meet Amtk 77, Control Point, Spencer	
77	CLT	17	PTI	14	PTI	14	DNC-BNC	NS	Meet #Amt74, Control Point, Merrill	

Amtrak Endpoint OTP Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
98	NYP	200	DCS	96	DCS	96	ALX-XVG	AM	Amtrak signal/power issue Control Point, Virginia
54	SAB	99	UTL	118	UTL	118	WAS-WAS	AM	Commercial power outage, Control Point, C Int; K Int, Ivy City, obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
40	CHI	128	WTR	107	FTI	47	RMT-PTB	CS	Follow G956, Milepost, 51.1, 42.2
40	PGH	Trn Cancelled							
41	MIA	226	CTI	115	CTI	103	HOL-MIA	FL	Follow Broke down train ahead p687, SFRTA, Control Point, HOL—MIA
23	NOL	18	PTI	17	PTI	17	BAS-XNO	CS	Meet AMTK 24, Siding, Nicholson Ave
24	MOE	87	ENG	81	ENG	81	GUF-GUF	CS	HEP Lost HEP Had too short loop, 365
26	MOE	23	FTI	25	FTI	10	BIX-PAG	CS	Meet Siding, Gautier, unknown
5	EMY	150	FTI	146	FTI	63	NPV-PCT	BN	Meet Single track due to multiple freights on M1. Wait for Amt4 & Amt6 to pass on M2, Amt4, Control Point, Montgomery
6	CHI	126	WTR	103	HLD	33	RNO-RNO	UP	Hold for passengers arriving from EMY via uber.
729	SJC	Trn Cancelled	TRS	51	TRS	51	RSV-SAC	UP	Trespasser strike Trespasser strike non fatal, Milepost, 104.4, 104.4
736	SAC	Trn Cancelled	TEN	40	TEN	38	RIC-MTZ	UP	Failure of diesel engine C2004
738	SAC	12	DCS	20	DCS	20	DAV-SAC	UP	Wayside detector failure including false actuation False hot box MP88.8. Inspect train proceed to MP 85.2 at 30 mph., Milepost, 78.7, 85.2
747	SJC	34	MBO	25	MBO	25	SUI-MTZ	UP	For maritime traffic Stop, Control Point, rv035
749	OKJ	Trn Cancelled							
751	EMY	52	TEN	44	TEN	44	FFV-FFV	UP	Failure of diesel engine C2004
504	SEA	122	POL	129	POL	129	CTL-OLW	BN	Right of Way police hold ATV struck the rails, held at wabash for police and rail inspection
517	PDX	65	POL	55	POL	55	OLW-CTL	BN	Right of Way police hold
518	VAC	33	RTE	28	MBO	11	X8B-XF2	BN	For maritime traffic Bridge, fraser river bridge
59	NOL	50	SYS	67	SYS	58	CHI-CHI	AM	Crew rest

Amtrak Endpoint OTP Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1058	CHI	39	FTI	52	PTI	32	XSU-HMD	CC	Meet amtk 59 s, Siding, manchac
7	SEA	73	FTI	129	WTR	54	MAL-HAV	BN	Heat order Milepost, 360, 430
8	CHI	189	FTI	198	WTR	70	HAV-MAL	BN	Heat order Milepost, 427, 360
27	PDX	-91	CON	114	CON	114	SPK-SPK	BN	Late arrival of 7 into SPK
341	MKE	26	CAR	28	CAR	28	CHI-CHI	AM	Air / Brake / Wheel 34034
343	MKE	13	PTI	14	PTI	14	SVT-MKA	CP	Meet Stopped at OAKWOOD due to 341 being extremely late disp tried contacting 341 to comply with the signal change with no response due to a recrew and performance of mechanical assessment., 341, Control Point, OAKWOOD
352	PNT	43	CAR	75	CAR	75	CHI-CHI	AM	PA system not working ID4301, PA system doesn't work through whole train. Only locally in each car.
566	SAN	38	SYS	20	SYS	20	LAX-LAX	SC	Late release of train by mechanical at 8th St Yard Other, Yard
572	SAN	19	CTI	14	CTI	7	XRJ-FUL	BN	Follow metrolink, 1662, Control Point, commerce
584	SAN	56	CTI	47	CTI	27	SNC-SNP	SC	Meet mtlk, Control Point, Serra
587	LAX	33	CTI	31	CTI	31	OSD-X98	SC	Meet metrolink, Control Point, songs
595	LAX	41	ITI	16	ITI	16	SAN-SAN	SN	Service, turn, or wye train 584, Late arriving equipment from train 584.
765	SLO	57	PTI	51	POL	24	CML-CML	UP	Removal of passenger by police Case number 26-92593
770	SAN	39	PTI	25	CTI	17	SNC-SNP	SC	Meet Metrolink, 1663, Control Point, Serra
782	SAN	18	PTI	22	PTI	16	CPN-VEC	UP	Meet 769, Control Point, CO 386
786	SAN	16	CTI	21	CTI	7	BUR-BBK	SC	Waited metrolink, Control Point, butbank jct.
713	OKJ	23	PTI	20	PTI	20	MCD-TRK	BN	Meet Shuffled in/out east Denair after 712, 712, Siding, Denair
715	OKJ	42	PTI	49	PTI	10	WAC-COC	BN	Meet AMTK 702, Siding, Sandrini
718	BFD	33	ITI	32	ITI	32	EMY-EMY	UP	Service, turn, or wye train 715
3	LAX	521	WTR	444	WTR	319	KNG-NDL	BN	Flood / washout Advance to Topock and hold for a clear route @NDL. Due to flooding on all MT at station, Control Point, topock
21	SAS	174	FTI	181	CAR	124	CHI-CHI	AM	Toilet 315, BAS ORDERED, CAR D/H INLINE

Amtrak Endpoint OTP Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
22	CHI	131	FTI	238	FTI	90	MHL-TXA	UP	Meet BNSF 9244, Control Point, marshall
302	CHI	45	FTI	67	FTI	46	SMT-XTF	CC	Cross Traffic unk, Control Point, corwith
307	STL	30	FTI	53	FTI	23	PON-BNL	UP	Meet UP5768, Milepost, 109, 109
382	CHI	134	FTI	130	FTI	115	MAC-GBB	BN	BNSF 9314 broken down between Avon and West Abingdon bnsf 9314, Control Point, Avon, coal train
383	QCY	32	CTI	19	FTI	15	KEE-GBB	BN	Blocked from station track BNSF, Control Point, B Plant
390	CHI	171	FTI	126	FTI	112	RTL-GLM	CC	Meet Freight train stalled out. Waited for rescue engines from Champaign yard to arrive and move train out of the Main Track., L500, Control Point, North Paxton
391	CDL	212	FTI	205	FTI	189	GLM-RTL	CC	Freight train stalled having engine problems unknown, Milepost, 95.0, 95.0
392	CHI	126	ITI	107	ITI	107	CDL-CDL	CC	Late arrival of AM 391 391
393	CDL	92	ITI	55	ITI	55	CHI-CHI	AM	Service, turn, or wye train 390
319	KCY	32	FTI	43	FTI	24	JEF-SED	UP	Meet UP Freight, Siding, Smithton

Amtrak Initial Terminal Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/18/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	07/17	20	20	Hold for connecting train 48
BOS	167	07/18	74	74	Service, turn, or wye train, 162, late turn of AM162 BOS
BOS	449	07/18	6	6	Sleeper passengers were being downgraded due to bad ordered room.
BOS	2259	07/18	29	29	Air / Brake, 2153 NG NP, An ACSES and Brake test will be conducted/ multiple fault
BOS	2271	07/18	3	3	Passenger and/or baggage, slow boarding
NHV	488	07/18	13	2	Hold for connecting train
NHV	488	07/18	13	11	Hold for connecting train, late connection of AM88
NHV	488	07/18	13	2	Hold for connecting train
NHV	488	07/18	13	11	Hold for connecting train, late connection of AM88
NYP	97	07/18	6	6	Water, commissary, toilet/trash dumping, LOADING
NYP	243	07/18	35	35	HEP, 9707 CB DC, delayed out of the SSYD due to not being able to pull power.
NYP	283	07/18	29	29	Routine inspections, LATE F/SSYD A/C LATE RELEASE BY MECHANICAL
NYP	291	07/18	26	26	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	665	07/18	21	21	Flood / washout, Other, NYP-NYP, HELD A/C FLOODING AT EWR
NYP	2219	07/18	6	6	Service, turn, or wye train, 2208, LOADING
PHL	611	07/18	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
RNK	66	07/18	61	61	Service, turn, or wye train 151, Train arrived late, had to wait for train to get serviced and cleaned
WAS	54	07/18	118	118	Commercial power outage, Control Point, C Int; K Int, Ivy City, obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
WAS	82	07/18	38	38	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
WAS	88	07/18	2	2	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
WAS	142	07/18	3	3	Other electrical failure, 636 EX ES, DOOR ISSUES, KEPT SHOWING OPEN/CLOSED. PLACED IN BYPASS
WAS	152	07/18	57	57	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
WAS	160	07/18	(Trn Cxld)		Signal Outage

Amtrak Initial Terminal Details

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/18/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	162	07/18	94	94	Commercial power outage, Control Point, C INT, K INT, IVY CITY , OBSTRUCTED ALL MOVEMENTS FROM THE YARD TO THE TERMINAL, DELAYED OUTBOUNDS; REASSIGNED POWER FOR THE EQUIPMENT.
WAS	2208	07/18	57	57	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
WAS	2250	07/18	(Trn Cxld)		Signal Outage
WAS	2252	07/18	119	119	Commercial power outage, Control Point, C INT, K INT, IVY CITY , obstructed all movements from the yard to the terminal; delayed outbounds; reassigned power for the equipment
WAS	2254	07/18	129	129	Commercial power outage, Control Point, C INT, K INT, IVY CITY , OBSTRUCTED ALL MOVEMENTS FROM THE YARD TO THE TERMINAL, DELAYED OUTBOUNDS, REASSIGNED POWER FOR THE EQUIPMENT.
CDL	392	07/18	107	107	Late arrival of AM 391 391
CHI	341	07/18	28	28	Air / Brake / Wheel 34034
CHI	352	07/18	75	75	PA system not working ID4301, PA system doesn't work through whole train. Only locally in each car.
CHI	354	07/18	28	28	Defects. Out of date fire extinguisher in engine room. Neither sander working., ID4609
CHI	393	07/18	55	55	Service, turn, or wye train 390
ARN	729	07/18	3	3	Meet Held at rv124 by dispatch for freight. Red signal, union pacific, Control Point, rv124
EUG	508	07/18	1	1	Mobility Impaired Assisted by EUG agents.
LAX	566	07/18	20	20	Late release of train by mechanical at 8th St Yard Other, Yard
OKJ	714	07/18	4	4	NO PAPER WORK IN CAB CAR AT THE YARD. SAND BOX DOOR OPENED. WAITED ON TASI TO CORRECT.
OKJ	716	07/18	3	3	Wait for station track Called for the light at 1350 to come out of the yard to the main at Magnolia. DS62 stated to wait at yard for 534 to get by us. Got the light out of the yard at 1405 Got into OKJ at 1410. We still had to do air test and change ends and log into PTC, 534, Other, Yard Oakland
SAC	704	07/18	6	6	Toilet C6962, Mechanical trying to get toilet working.
SAC	723	07/18	1	1	Door light issue, door was jammed
SAC	733	07/18	1	1	Board the last pax from 729.
SAC	749	07/18	(Trn Cxld)		Third Party Engine Failure
SAN	595	07/18	16	16	Service, turn, or wye train 584, Late arriving equipment from train 584.

Amtrak Initial Terminal Details

Late Trains For:

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Region: ALL

Division: ALL

Data Through: 7/18/2026

Terminal	Train	Date	Late	Delay	Cause
SEA	8	07/18	24	24	Service, turn, or wye train 7, Released from mechanical to Switch crew to Wye at 4:45. Met switch crew at Station.
SJC	738	07/18	1		
SJC	744	07/18	1		
SPK	27	07/16	114	114	Late arrival of 7 into SPK

Eastern Region

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.2	98.3	94.8	166	3
CDOT	95.0	87.5	84.3	92.4	16	2
MARC	95.0	55.6	79.1	90.2	18	8
SEPTA	95.0	88.7	94.9	91.5	106	12
NJT-NED	95.0	92.3	91.4	88.6	194	15
NJT-SED	95.0	95.8	95.6	97.2	24	1

Operating Highlights

Train 97(18) South of Selma, NC - Signal

19JUL26: Train 97(18) operating with engines 37, 152, 10 cars, and 267 customers onboard was delayed 21 miles south of Selma, NC on the CSX South End subdivision after operating through Benson hotbox detector and falsely actuating it. 97(18) operating 30mph from milepost 181.0 to Wade hotbox detector at milepost 200.5 to ensure the reading was false. The train was able to regain track speed after confirmation was shown the actuation was false.

Train	Delay	Comment
97(18)	31"	
98(18)	34"	

Train 52(18) Florence, SC - Map 100

19JUL26: Train 52(18) operating with engines 352, 364, and 453 customers onboard was delayed departing Florence, SC on the CSX Charleston subdivision due to Map 100 paperwork being incorrectly filled out by Sanford Mechanical. The paperwork was able to be properly completed and 52(18) proceeded north at 2:15 a.m.

Train	Delay	Comment
52(18)	37"	

Train 146(18) New Haven, CT - Servicing

18JUL26: Train 146(18) operating with engine 651, 8 cars, and 159 customers onboard was delayed departing New Haven, CT due to a late turn of equipment.

Train	Delay	Comment
146(18)	58"	

Train 243(18) New York, NY - Engine Failure

18JUL26: Train 243(18) operating with engine 9707, 5 cars, engine 701, and 208 customers onboard was delayed departing New York Penn due to an issue in SSYD which caused the consist to not pull power. The issue was resolved and train 243(18) proceeded to the station to begin boarding.

Train 41(17) Washington D.C. - Tree Strike

18JUL26: Train 41(17) operating with engines 179, 326, 10 cars, and 123 customers onboard was delayed departing Washington D.C. after the conductor reported two emergency windows were out in car 25050 after hitting a tree at an unspecified location. Washington mechanical was unable to repair the windows causing the car to deadhead in line and over capacity conditions with the highest 35 at Deland, FL. All customers were accommodated to other services.

Train 41(16) North of Miami, FL - Commuter Train Interference

18JUL26: Train 41(16) operating with engines 179, 326, 10 cars, and 80 customers onboard was delayed 5 miles north of Miami, FL on the SFRTA Miami subdivision holding at milepost 1029.1 for a disabled SFRTA commuter train ahead. A rescue set was sent to move the commuter train and allow 41(16) to proceed south to Miami.

Train	Delay	Comment
41(16)	1'43"	

Train 2265(18) South of Aberdeen, MD - Trespasser Incident

18JUL26: Train 2265(18) operating with power car 2141, 9 power vehicles, power car 2104, and 238 customers onboard non fatally struck a trespasser south of Aberdeen, MD on the Amtrak PW Line less than 1 mile south of the station near milepost 65.0 between Bush/71.6 and Oak/62.9 interlockings. Upon inspection the crew found the trespasser to be alive and EMS arrived on scene approximately 30 minutes after the strike to tend to the trespasser. Headend power remained operational and no injuries were reported by crew or customers onboard. Amtrak management and local authorities responded to the scene and APD was notified. Once the scene was clear, 2265(18) was able to proceed south to Washington D.C.

Train	Delay	Comment
163(18)	07"	
2265(18)	2'20"	
159(18)	23"	
80(18)	10"	
142(18)	11"	

Multiple Trains - PW Line South of Baltimore - Switch Failure

18JUL26: Multiple Trains were delayed on the Amtrak PW Line South of Baltimore due to the switches at Grove Interlocking being out of correspondence. Trains were delayed due to single tracking between Grove and Fulton. A signal maintainer responded to the location and made repairs to the switch to allow it to return to normal operation. Once completed train were able to resume operation without further delays.

Train	Delay	Comment
80(18)	1'24"	
158(18)	18"	
87(18)	55"	
142(18)	1'17"	
161(18)	19"	
97(18)	07"	
2219(18)	23"	
97(18)	17"	
147(18)	43"	
2259(18)	03"	
146(18)	25"	
19(18)	34"	
99(18)	1'49"	

Train 41(17) West of Rockville, MD - Downed Tree

18JUL26: Train 41(17) operating with locomotives 46-148, 10 cars and 173 customers onboard was delayed 20 miles west of Rockville at MP 34 on the CSX Metropolitan Subdivision holding for a large, downed tree. CSX dispatched a grapple truck to the location to remove the tree with a estimated time of arrival of 1'30". The conductor expired on HOS while holding at the location and a recrew conductor was sent to Dickerson Marc Station where the CSX grapple truck picked up the crew member and high railed to the location of the train and tree. Once they arrived at the location the conductor boarded the train and the CSX crew began removal of the tree at 6:30 p.m.

WBS#: B.TR.100150.6904

Train	Delay	Comment
41(17)	2'45"	

Multiple Trains - PH Line Signal Power Loss - Weather

18JUL26: Multiple trains were delayed on the PH line 10 miles east of Harrisburg at Roy Interlocking after a lightning strike took out signal power to the interlocking. Trains operating thru Roy interlocking were required to get a rule 241 to operate past the stop signal and then proceed at restricted speed until passing a more favorable signal. IMCS personnel responded to the location to make repairs and restore the interlocking. After repairs were completed train operations were able to resume without further delays.

Train	Delay	Comment
43(18)	04"	
670(18)	08"	
42(18)	18"	
663(18)	08"	
665(18)	35"	
674(18)	08"	
667(18)	12"	
669(18)	05"	

Train 41(17) East of Pittsburgh, PA - Engine Failure

18JUL26: Train 41(17) operating with locomotives 46-148, 10 cars and 173 customers onboard was delayed 25 miles east of Pittsburgh at MP 327 on the CSX Pittsburgh subdivision due to locomotive failure. After being stopped for a vehicle on the tracks and authorized to resume locomotive 46 was unable to draw power and provide tractive effort. Working with CNOC Mechanical the crew was unable to restore the tractive effort and was required to configure the two locomotives to have trailing unit 148 provide all tractive effort and HEP. After the setup was complete train 41(17) was able to resume operations.

Train	Delay	Comment
41(17)	1'05"	

Train 41(17) East of Pittsburgh, PA - Vehicle on Tracks

18JUL26: Train 41(17) operating with locomotive 46-148, 10 cars and 173 customers was delayed 25 miles east of Pittsburgh at MP 327 on the CSX Pittsburgh subdivision after a car became disabled on the track at MP 326.5. After the car was removed, the train was further delayed waiting for a CSX track inspector to arrive on scene an inspect the tracks. Upon arrival and inspection, the track inspector found no defects and authorized train operation to resume.

Train	Delay	Comment
41(17)	35"	

Multiple Trains - NYP Line Flooding East of Newark, NJ Airport - Weather

18JUL26: Multiple trains were delayed on the NJ Line East of Newark Airport due to reported high water over the rail on tracks No.1, No.2, No.4 and No.5. Trains were delayed operating with only a single track accessible due to a hold placed on the tracks with water over the rail. After the water receded the holds were lifted and normal operations resumed.

Train	Delay	Comment
2208 (18)	03"	
147 (18)	01"	
99 (18)	10"	
665 (18)	21"	
152 (18)	36"	
118 (18)	11"	
147 (18)	24"	
2254 (18)	08"	
54 (18)	10"	
664 (18)	24"	

Train 64(18) Niagara Falls, NY - Customs and Immigration

18JUL26: Train 64(18) operating with locomotive 92, 5 cars and 131 customers was delayed at Niagara Falls Station as a result of a US Customs and Border Protection inspection. During the routine border inspection process a K9 officer and handler with the Niagara County Sherriff's Office made a positive hit on an area of the train consist. Per protocol a second K9 officer and handler responded and confirmed a positive hit on the consist. As a result of 2 positive hits and for the safety of the general public the train was requested to move to a location that was more accessible and a call was made to have the Niagara County Sherriff Bomb Squad to respond. Upon arrival the Bomb Squad conducted an investigation and inspection of the train consist and found nothing to indicate a safety hazard to property or life. At the conclusion of the inspection the equipment was released back into service. The train was repositioned back in the passenger station, and all customers were reboarded and train 64(18) was able to depart Niagara Falls.

Train	Delay	Comment
64 (18)	3'27"	

South of Philadelphia, PA - TOL Phil Interlocking

18JUL26: Multiple train operators affected "UNCLASSIFIED" 7/21/2026 241 to operate through Phil interlocking at milepost 3.6 south of Philadelphia, PA on the Amtrak PW Line due to a track occupancy light.

Train	Delay	Comment
109 (18)	59"	
2255 (18)	03"	
2254 (18)	05"	
2252 (18)	08"	
2208 (18)	08"	
195 (18)	03"	
2255 (18)	03"	
164 (18)	32"	
152 (18)	06"	
143 (18)	06"	
127 (18)	03"	
118 (18)	17"	
82 (18)	12"	
88 (18)	11"	
54 (18)	18"	
140 (18)	12"	
2258 (18)	08"	
194 (18)	02"	
99 (18)	03"	
147 (18)	05"	
106 (18)	07"	
2219 (18)	02"	
19 (18)	06"	
161 (18)	08"	
87 (18)	09"	
2260 (18)	11"	
168 (18)	11"	
156 (18)	15"	
146 (18)	03"	
126 (18)	13"	
163 (18)	09"	
2262 (18)	06"	

Train 97(17) Savannah, GA - Freight Train Interference

18JUL26: Train 97(17), operating with engines 83/316, 10 coaches and 255 customers, was delayed departing Savannah, GA, on CSX Savannah_A subdivision, due to being blocked by freight train M-592-18. Once the freight cleared and a route was made available, train 97(17) was able to depart the station.

Train	Delay	Comment
97 (17)	31"	

Washington D.C. - K and C Interlocking TOL

18JUL26: At 3:56 a.m. multiple train occupancy lights across K and C Interlocking located within the terminal. Maintainers were on scene shortly after the report to search for the issue. All terminal train operations were impacted due to the inability to make moves for inbound and departing trains. No equipment moves were able to be made between the yard and the terminal further delaying train make-up and servicing. Trains were required to be held out of the terminal to include 95(18) at New Carrollton, 151(18) at BWI, 109(18) at Philadelphia and 98(17) and 164(17) holding out south of Washington.

Initial reports from IMCS indicated a loss of commercial power causing the terminal operations halting. Peco Utilities was notified of outage and dispatched personnel to make repairs.

IMCS was able to establish a single route thru the affected area allowing train 162(18) to depart Washington and 65(17) and 151(17) to arrive.

At 8:15am-et commercial and signal power was restored to the terminal allowing operations to resume. Trains that were made up and prepared to depart did so. Terminal operations including equipment moves from the S&I, locomotive power changes and train make-up were able to resume for the necessary trains.

Train	Delay	Comment
2250(18)	Cancelled	
2267(18)	Cancelled	
160(18)	Cancelled	
65(17)	1'56"	Hold NCR
165(18)	Cancelled	
151(18)	35"	Hold BWI
164(18)	1'44"	Hold out WAS
98(17)	1'36"	Hold out WAS
109(18)	59"	Hold PHL
162(18)	1'34"	Initial Terminal WAS
2252(18)	1'59"	Initial Terminal WAS
54(18)	1'58"	Initial Terminal WAS
2254(18)	2'09"	Initial Terminal WAS
152(18)	57"	Initial Terminal WAS
2208(18)	57"	Initial Terminal WAS
82(18)	38"	Initial Terminal WAS
88(18)	02"	Initial Terminal WAS

Maintenance of Way Highlights

26-FOI-00603 00000008326 "UNCLASSIFIED" 7/21/2026

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Train 26-F01-00803 delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

UNCLASSIFIED 7/21/2026

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008328 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00893 a 00000008326 in "UNCLASSIFIED" open 7/21/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train 19(17) North of New Orleans, LA - Freight Train Interference

19JUL26: Train 19(17) was delayed holding at MP186.7 north of New Orleans NO station on the Norfolk Southern NO and NE subdivision meeting freight train 346. Train 19(17) was back on the move at 1112PM CT after the freight cleared to the north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(17)	30"	

Train 50(18) Crawfordsville, IN - Debris

19JUL26: Train 50(18) was delayed holding at Crawfordsville, IN/MP147.5 station on the CSX Monon subdivision due to a tree down on the tracks ahead at MP42.0. Train 50(18) was back on the move at 117AM ET after the tree was removed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(18)	40"	

Train 21(17) North of Taylor, TX - Signal

19JUL26: Train 21(17) was delayed beginning at MP885.9, 33.77 miles north of Taylor TX station on the UPRR Waco subdivision due to restrictive signals from an unknown cause. Train 21(17) stopped and then proceeded through the signals at restricted speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(17)	38"	

Train 11(18) South of Chemult, OR - Vehicle Strike

18JUL26: At approximately 9:14PM-PDT, train 11(18) operating with E/170, E/313, 9 Cars struck a vehicle at MP 502.240 on the UPRR Cascade Subdivision, 1 mile south of Chemult station, in Chemult, OR Klamath county, USFS Road Crossing, DOT# 749018H . There were no reported injuries to the 269 passengers or crew onboard, and no damages to the train. The weather was a reported 75 degrees. The driver of the vehicle was unable to be found, and reportedly fled the scene. The Crew requested relief, but agreed to take the train to Klamath Falls. Local authorities responded and conducted an investigation of the incident. Once the investigation was complete, train 11(18) was released and continued south. Amtrak Police and EAP advised.

Due to this, Train 14(18) was delayed departing Klamath Falls, OR waiting for a crew vanning in from Portland, OR, expected to arrive at 9:15AM-PT

National Response Center Number: 1468253

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(18)	1'56"	
14(18)	Est 1'35"	Re-crew from PDX

Train 50(18) North of Crawfordsville, IN - Freight Train Interference

19JUL26: Train 50(18) was delayed beginning at MP120, 28.6 miles north of Crawfordsville, IN station on the CSX Monon subdivision following CSX freight train M639 until MP147.4.

Train 28(18) Wishram, WA - Freight Train Interference

18JUL26: Train 28(18) was delayed at Wishram, WA due to disabled BNSF freight train ahead just before Towal siding at MP123 on the BNSF Fallbridge Subdivision. Train 28(18) was held at Wishram until the freight completed repairs, then advanced to Maryhill/MP112.9 and was held until the freight cleared into the Towal siding. Once route was clear, Train 28(18) was able to proceed east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
28(18)	1'24"	

Train 4(18) East of Fullerton, CA - Commuter Train Interference

18JUL26: Train 4(18) was delayed approximately 4 miles east of Fullerton, CA at MP41.4 on the BNSF San Bernardino Subdivision due to a police hold on the tracks ahead between Atwood/ MP40.6 and Esperanza/ MP35.8 account of disabled Metrolink 1752. The train's engine had shutdown, without air conditioning and all of the train's passengers had self evacuated, fouling the tracks. Once the Metrolink train had recovered, and tracks were clear, the hold was lifted and Train 4(18) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(18)	1'56"	

Train 382(18) Galesburg, IL - Freight Train Interference

18JUL26: Train 382(18) was delayed holding at MP180.9, 19.8 miles west of Galesburg, IL station on the BNSF Brookfield subdivision due to BNSF Freight 9314 stopped ahead with air and PTC issues. Mechanical responded to the train out of Galesburg but was unable to resolve the issues with the lead motor. BNSF Freight shoved back to Abingdon siding/MP175.2 to clear a route for 382(18). Train 382(18) was back on the move at 830PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
382(18)	1'55"	

Train 587(18) San Clemente Pier, CA - Commuter Train Interference

18JUL26: Train 587(18) was delayed at Songs /MP 209.16 on the SCRRA-NCTD San Diego Subdivision, 4.36 miles east of San Clemente Pier, CA station, due to meeting a Metrolink train. As a result, Train 584(18) was then delayed meeting 587(18) and another Metrolink train at Serra/ MP 199.9.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
587(18)	31"	CTI
584(18)	15"	Meeting 587(18)
584(18)	27"	CTI

Train 736(18) East of Richmond, CA - Third Party Contractor Engine Failure

18JUL26: Train 736(18) E/C2004, 500000083265, with 24 ticketed passengers onboard, was delayed east of Richmond, CA at MP18 on the UPRR Martinez Subdivision due to engine E/C2004 losing its load and coming to a stop. Crew worked with TASI mechanical and Amtrak field management to troubleshoot the issue. The crew was able to recycle the engine and clear the faults, allowing the train to proceed east.

Just prior to arriving at at the Fairfield-Vacaville station (FFV), the engine lost load again and the train coasted into the station. Head-end power was active during the entirety of these events. The crew again worked with mechanical in order to troubleshoot. Train 738(18) was 2 stops away, approximately 15 minutes and the decision was made to transfer all passengers to train 738(18) since the issue was not resolved upon arrival. Train 736(18) was terminated at FFV. As a result, the turn of equipment, Train 749(18) was cancelled in entirety, with train 738's equipment turning for 751(18).

736 equipment was to DH to Sacramento and be coupled to 751(18) then towed to OMF. Unable to load the engine, Train 751(18) was delayed at FFV while the train was coupled in trail, in order to get the equipment to OMF. Due to operating as a double-set, Train 751(18) was terminated at Emeryville with all 13 passengers destined Oakland were accommodated on Bus 6653.

Train	Delay	Comment
736(18)	40"	Terminated FFV
738(18)	06"	FFV
749(18)	Cancelled	
751(18)	44"	FFV- Coupling to 736 EQ

Train 20(18) West of Meridian, MS - Freight Train Interference

18JUL26: Train 20(18), operating with engines, 201/369, 8 coaches and 150 customers was delayed 1 mile west of Meridian, MS, on NS NO&NE subdivision due to a freight train entering the yard ahead of them, blocking their route into the station. Once the freight cleared and route was made available, train 20(18) was able to proceed.

Train	Delay	Comment
20(18)	30"	

Train 390(18) South of Chicago, IL - M of W Work

18JUL26: Train 390(18) operating with engine 4629, 7 coaches and 223 customers, was delayed 3 miles south of Chicago, IL, on CN Chicago subdivision due to maintenance of way workers fouling the tracks. Once the workers cleared train 390(18) was able to proceed.

Train	Delay	Comment
390(18)	42"	

Train 504(18) North of Centralia, WA - Police Related

18JUL26: Train 504(18) operating with WDTX 1401, 4 cars, and 160 customers onboard was stopped at milepost 49.7, 5 miles north of Centralia, WA on the BNSF Seattle subdivision due to a police hold placed on the tracks. The police hold was placed due to an ATV rolling across the tracks. A BNSF track inspector responded to the scene. Once the tracks were inspected and the police hold was lifted, train 504(18) advanced to the next station. Train 517(18) was also delayed due to this, holding at MP43.1.

Train	Delay	Comment
504(18)	2'09"	
517(18)	55"	

Train 352(18) Chicago, IL - Car Failure

18JUL26: Train 352(18), operating with locomotive 1680, 5/21/2026, and 272 customers, was delayed departing Chicago, IL, on Amtrak Chicago Terminal subdivision, due to a inoperable PA system. Mechanical met the train placed it under blue flag protection while they worked to resolved the issue. They replaced a cable and reset the PA system. Once mechanical finished they released the train for departure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(18)	1'15"	

Train 20(18)/19(17) West of Meridian, MS - Freight Train Interference

18JUL26: Train 20(18) and 19(17) were delayed west of Meridian, MS, on NS AGS South subdivision due to disabled freight train NS344 loosing power on a single main. NS dispatched a rescue motor to meet the disabled train. trains 19(17) and 20(18) held waiting for the disabled freight to be rescued. Train 20(18) was back on the move at 459PM CT but was delayed continuing to follow the previously disabled freight. Train 19(17) was back on the move 544PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(18)	1'58"	
19(17)	2'19"	

Train 729(18) East of Roseville, CA - Trespasser Strike

18JUL26: Train 729(18), operating with locomotive CDTX/2124, four cars, cab car CDTX/8307 struck and injured a trespasser approximately 2 miles east of Roseville, CA Station, at MP 104.4 on the Union Pacific Martinez Subdivision in Sacramento County, CA. The incident did not occur at a public highway grade crossing. There were 59 passengers on board, with no reported injuries on board the train. Local authorities, including the Sacramento County Sheriff's Office and Roseville Police and Fire Department, responded to the scene, and Sacramento Amtrak Road Foreman responded to provide on-site support. The trespasser was transported to a local hospital for treatment of unknown injuries. Weather conditions at the time were reported as 70°F and clear. Once the scene was released by authorities, Train 729(18) was authorized to proceed to Sacramento Station, where the train was re-crewed. The passengers were transferred to Train 733(18). Train 729(18) was terminated in Sacramento, and the equipment was deadheaded to San Jose.

National Response Center Number: 1468214

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
729(18)	TERM SAC	

Train 390/391(18) Rantoul, IL - Freight Train Interference

18JUL26:

Copilot said:

Trains 390(18) and 391(18) were delayed north of Rantoul, IL on CN Chicago subdivision, due to a stalled CN freight train. CN initially estimated the delay at approximately 60 minutes. After the freight train was reported back on the move, CN coordinated train movements and determined that 390(18) would proceed north first because of 391(18)'s crew Hours of Service limitations. A relief crew assigned to 390(18) was arranged to meet 391(18). Train 390(18) subsequently proceeded north to make the scheduled meet, and shortly thereafter 391(18) resumed movement and continued its trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
390(18)	1'52"	

Train 302(18) East of Summit, IL - Freight Train Interference

18JUL26: Train 302(18) operating with 46257, 5 coaches, 273 customers, was delayed 5.5 miles east of Summit, IL, on CN Joliet subdivision, due to an unknown freight train crossing in front. Once the freight cleared and a route was made available, train 302(18) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
302(18)	46"	

Train 8/28(17) West of Whitefish, MT - Freight Train Interference

18JUL26: Train 8/28(17) with engines 332, 379, 10 cars, and 162 customers onboard was delayed at milepost 1251.8, 33 miles west of Whitefish, MT on the BNSF Kootenai River subdivision due to meeting BNSF freight trains 7631 and 6962.

Train 8/28(17) was further delayed at Oswego/MP237.8 on the BNSF Glasgow Subdivision, 10 miles west of Wolf Point, MT meeting BNSF trains 6151 and 7704. Once the freight trains cleared, train 8/28(17) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(17)	49"	
8/28(17)	30"	Oswego

Train 5(16) West of Salt Lake City, UT - Restrictive Signals

18JUL26: Train 5(16) with engines 135, 29, 9 cars, and 139 customers onboard was delayed beginning at milepost 825.0, 103 miles west of Salt Lake City, UT on the UPRR Shafter subdivision due to restrictive signals and flagging between milepost 825.0 and milepost 816.0. Train 6(17) with 157 customers onboard went through the same area and experienced the same delays.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(16)	30"	
6(17)	27"	

Train 7/27(16) West of Essex, MT - Freight Train Interference

18JUL26: Train 7/27(16) with engines 5, 193, 10 cars, and 248 customers onboard was delayed at milepost 1170.3, 2 miles west of Essex, MT on the BNSF Hi Line subdivision due to meeting BNSF freight trains 8450 and 4666. Once the freight trains were cleared, train 7/27(16) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(16)	38"	

Train 6(16) East of Ottumwa, IA - Engine Failure

18JUL26:

Copilot said:

Train 6(16), operating with locomotives 188 and 146, 10 coaches, and carrying 201 customers, was stopped east of Ottumwa at Milepost 256.2 on the BNSF Ottumwa Subdivision due to an air hose separation. Upon inspecting the equipment, the crew discovered a damaged air hose between cars 32094 and 32002. The crew replaced the damaged hose and conducted the required brake tests to ensure the train was safe for operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(16)	29"	

Washout BNSF Needles Subdivision - Needles, CA

18JUL26: Due to flash flooding on 7/21/2026 BNSF Needles Subdivision, affecting main track No.4 at Needles, CA station/ MP 578.0 on the BNSF Needles Subdivision and main track No.2 at East Needles/ MP 574.6, and multiple freight trains in the area with hours of service issues. Train 4(17) was held at MP 592.6, and Train 3(16) was held at Kingman, AZ station. BNSF worked to shove back a stack train in order to route trains through the area, temporarily through the siding. When freight traffic began to move, damage to main track 1 was found. There was no clear route through the area. BNSF continued to work on clearing a route for the trains. Main track 2 was returned to service at 9:30 AM-MT. Main track one was returned to service at 11:30 AM-MT. Train 3(16) had to hold for freight traffic to clear and then was able advance. The train had to operate at a reduced speed through the area.

Train 4(17) had to be recrewed where it stood and again in Needles. The recrew was transported by van from Train 3(16) to Train 4(17). Another crew was sent in a van from Kingman to Needles. Train 3(16) met a recrew enroute at milepost 648.9. Train 3(16) was on the move after the recrew arrived at 12:34 PM-MT.

Trains 3(16) and 4(17) did not make the station stop in Needles due to no safe way for the passengers to get to the station. All passengers were reaccommodated. Trains 3(17) and 4(18) were scheduled to bypass the stop due to main track 4 remaining closed. BNSF was able to re-open main track 4 at 3:30PM-MT, earlier than planned, and 3(17) and 4(18) were able to make the Needles station stop. Both trains were delayed through the are due to reduced speeds and freight congestion.

Train 4(17) was further delayed at Gallup, NM performing a Calendar day inspection.

Alternate transportation was secured for an on-time portion of Train 4(17) from Kansas City to Chicago. Two buses were able to be confirmed. One bus operated Kansas City to Chicago. The second bus was secured to make stops at Kansas City, LaPlata, Ft. Madison, Galesburg, Princeton, Mendota, Naperville, and Chicago.

WBS#: B.TR.100150.6902

Train	Delay	Comment
3(16)	1'39"	KNG
3(16)	6'14"	KNG-NDL
4(17)	12'03"	BAR-NDL
3(16)	58"	Recrew
4(17)	1'04"	Recrew
3(17)	36"	KNG- Crew Rest
4(17)	1'07"	GLP- Calendar Day

UPRR Del Rio Subdivision West of San Antonio, TX - Weather

16JUN26: Union Pacific Railroad reported multiple washouts west of San Antonio on the Del Rio Subdivision. Maintenance personnel were dispatched to the affected area; however, no estimated time of arrival was available at the time of the report. As a precautionary measure, Train 1(15)/421(14) was held at San Antonio pending further information regarding track conditions and the availability of any open routes.

Subsequent inspections confirmed at least one washout in the Yucca Siding area between Mileposts 285 and 288, along with multiple locations where water had overtopped the rail. Track inspectors continued evaluating the extent of the damage while maintenance equipment was assembled for repair efforts. A ballast train was positioned in San Antonio to support recovery operations. Based on initial assessments, UPRR estimated that the affected tracks would remain out of service for a minimum of eight hours, with the expected reopening time subject to revision as inspections progressed.

As a result of the two confirmed washouts west of San Antonio and the widespread flooding conditions through the area, the following service adjustments were implemented for the Sunset Limited. Train 1(15)/421(14) were cancelled between San Antonio and El Paso and train 2/422(15) were cancelled between El Paso and San Antonio. A bus bridge was established between the two cities to accommodate all affected customers. Train 1(15) equipment was turned in San Antonio and operated as train 2(15) to New Orleans. Train 2/422(15) equipment was turned in El Paso and operated as train 1(15)/421(14) to Los Angeles.

Four express buses representing train 1(15)/421(14) departed San Antonio at 1140AM-CT and continued to El Paso. An additional bus making local stops departed shortly after. Additionally, three express buses and one local bus were secured to represent train 2/422(15) and departed El Paso at 542PM-MT enroute to San Antonio. As part of the service recovery plan, meal boxes were provided for the affected customers with all buses making a meal stop enroute. Once all buses arrived on location in El Paso, customers and baggage were loaded onto the train, and train 1(15)/421(14) departed El Paso at 900PM-MT, 7 hours, and 10 minutes late.

Further assessments by UPRR revealed that the situation was more extensive than initially reported. Railroad personnel confirmed a total of seven washouts across the affected territory, along with multiple locations experiencing power outages and track occupied light indications. Several additional locations were identified with substantial water over the rail. Inspectors were unable to access approximately 33 miles of track, preventing a complete evaluation of the effected territory. Based on the expanded scope of the damage and accessibility challenges, UPRR revised its estimates and projected a 48-hour service outage, with an estimated time of restoration of July 19 at 200PM-CT. Considering the information and to support continued service recovery efforts, alternate transportation was being sourced to establish a bus bridge operation for trains 2/422(17) and 1(18)/421(17) between the affected locations.

A final report on July 16 revealed a total of 12 washout locations totaling .53 miles of track repairs with no estimated time for track opening. Crews continued to work diligently on repairs with 74 ballast cars in position. It would be necessary to install 120 ties at MP 293.35.

WBS#: B.TR.100150.6898

Train	Delay	Comment
1(15)/421(14)	SAS-ELP, bus bridge	
2/422(15)	ELP-SAS, bus bridge	
1(18)/421(17)	SAS-ELP, bus bridge	
2/422(17)	ELP-SAS, bus bridge	
2(15)	42"	Holding for Bus

UPRR Desoto Subdivision Washout - North of Poplar Bluff, MO

10JUL26: At 3:30AM-CT 26-FBI-00603 60000008326 reported a washout on the UPRR DeSoto Subdivision at Annapolis (MP108), located 57.6 miles north of Poplar Bluff, MO (MP165.6). As a result, Train 22(09) arrived at the Poplar Bluff station at 4:04AM-CT with 144 customers onboard and held for disposition.

A Union Pacific Manager of Track Maintenance responded to the washout location at 4:20AM-CT and provided a preliminary estimated track restoration time of 2:00PM-CT. A detour route was available via the Chester Subdivision between Poplar Bluff and St. Louis, bypassing Arcadia. No customer impact occurred at Arcadia, as no customers were scheduled to board or detrain at that location. Union Pacific pilot crews went on duty at 6:10AM-CT and responded to the train, arriving at 7:00AM-CT. Upon the pilots' arrival, Train 22(09) departed Poplar Bluff at 7:21AM-CT and proceeded over the detour route via the Chester Subdivision.

At 12:00PM-CT, Union Pacific reported that floodwaters were not expected to begin receding until Saturday, July 11. Following the water's recession, a track inspection would be required before rail operations could resume through the area. As a result:

-Train 21/421(10) detoured via the Chester Subdivision with 6 on / 0 off at Arcadia. The affected six customers were notified and advised to rebook on the next available departure.

-Train 22(10)/422(08) detoured via the Chester Subdivision with 0 on / 5 off at Arcadia. A sprinter van transported passengers from Saint Louis, MO back to Arcadia, MO.

11JUL26: Union Pacific reported that the floodwaters were not expected to recede until Sunday, July 12th. As a result, Trains 22(11) and 21(11) were also routed via the Chester Subdivision detour with no alternate provided to/from Arcadia.

12JUL26: UPRR revised eto was updated to 930AM-CT 12JUL. Due to no available UPRR pilots to support the detour, Train 22(11), with 109 customers, was delayed at Poplar Bluff, MO, holding for dispo of the route ahead and then further delayed through the area. Train 22(11) was delayed due to the 10MPH speed restriction through the washout area and also signal issues between MP107 and MP92. Train 21/421(12) was also delayed operating at 10MPH through the washout site.

13JUL26: UPRR 10MPH slow orders remained in effect between MP95 and MP110. Trains 22(12)/422(10) and 21(13) were delayed operating through the affected area.

Train	Delay	Comment
22(09)	3'14"	Hold PBF
22(09)	1'09"	Detour
21(11)	1'08"	Detour
22(10)/422(08)	3'21"	
21/421(10)	2'13"	
22(11)	1'09"	PBF
22(11)	2'42"	N/PBF
21/421(12)	1'47"	
22(12)/422(10)	1'13"	
21(13)	50"	
21/421(14)	49"	
21(15)	23"	
22(15)	31"	
21(16)	1'32"	

Heat Dome affect Entire Network - Weather

08JUL26: A heat dome evolving in the west will be bringing high temps in excess of 100° throughout the country. It will begin to expand as the week goes along and shift to the east affecting the entire nation. The first few days will be focused from the southwest through the Rockies to the Great Plains. It will then shift east affecting the Upper Midwest through the Northeast. Trains will be restricted to high temperature restriction. The high temperatures, there will be increase of severe thunderstorms and high winds.

was deadhead to New Haven, CT where Train 55(15) originated.
 Three buses were secured for the 119 customers for Train 56(14) between Springfield to St. Albans.
 Buses were secured for 221 customers for Train 55(14) between St. Albans and New Haven.

14JUL26: Additional Cancellations on the Northeast Corridor impacting Regional and Acela services were put into place to protect overall service:
 Northeast Regional Trains 84, 119, 173, 176, 193, 196, (15-16)
 Acela Trains 2152, 2154, 2165, 2167, 2193 (15-16)

17JUL26: Piedmont Service adjustments for NS heat orders: trains 77(17) and 78(17) cancelled in their entirety with alternate busing.

On Corridor WBS # B.TR.100151.0830

WBS#: B.TR.100151.0830

Train	Delay	Comment
6(08)	32"	Heat Orders WNN-ELK
5(06)	31"	Heat orders - ELK to WNN
6(08)	49"	Heat orders- GRI to GJT
5(08)	28"	Heat Orders GRA-GJT
5(08)	43"	Heat Orders GJT-HER
6(08)	17"	Heat Orders MTZ-RSV
3(08)	45"	High Winds RAT - GLP
6(10)	1'25"	Heat Orders RNO - ELK
6(11)	1'20"	Heat Orders RNO-ELK
5(10)	46"	Heat Orders GRA-GRI
8(10)	1'59"	Heat Orders
7(10)	2'40"	Heat Orders
7/27(11)	2'22"	GGW-SBY
8/28(11)	2'03"	SBY-WPT
5(11)	1'12"	DEN-PRO
6(11)	49"	GRI-GRA
68(13)	48"	
5(12)	54"	GRA-HER
6(12)	47"	WNN-DEN
7/27(12)	2'00"	WTN-HAV
8/28(12)	50"	HAV-GGW
56(14)	Term SPG	New England storms
55(15)	Orig NHV	New England storms
68(14)	40"	
64(14)	24"	
8/28(13)	1'00"	HAV-GGW
7/27(13)	1'28"	WTN-HAV
6(14)	43"	WNN-ELK
5(12)	29"	RSV-MTZ
5(13)	1'13"	GRA-HER
5(13)	51"	ELK-MTZ
6(15)	38"	Heat Orders WNN-ELK
3(14)	40"	Flash Flood Warnings E/WLO
3(14)	1'18"	Winds GLP-WLO
28(15)	16"	High Winds WIH-PSC
5(14)	1'15"	Heat Orders
5(15)	52"	Heat Orders
6(16)	40"	Heat Orders WNN-ELK
8/28(16)	1'10"	Heat Orders
7/27(16)	54"	Heat Orders
5(16)	41"	Heat Orders
6(17)	39"	Heat Orders
7/27(17)	3'24"	Heat Orders
8/28(17)	1'38"	Heat Orders
6(18)	41"	Heat Orders
4(17)	1'29"	Flash Flood Warnings E/KNG
5(17)	30"	Heat Orders

Midwest State Supported Service Adjustments - Equipment

08JUL26: The following Midwest State Supported Service Adjustments are in effect due to equipment availability issues in Chicago, IL:

10JUL26: Additional adjustments have been added to the schedule through 12JUL.

12JUL26: Lincoln and Wolverine service adjustments extended through 13JUL.

13JUL26: Lincoln and Illini/Saluki service adjustments in effect on Tuesday July 14th.

14JUL26: Illini/Saluki service adjustments extended to Wednesday July 15th.

Carl Sandburg Service:

- Trains 381(09-10) cancelled entirely, with alternate transportation for customers between Chicago and Quincy, IL.

- Trains 382(09-10) cancelled entirely, with alternate transportation for customers between Quincy and Chicago.

Lincoln Service:

- Trains 305(08-13) cancelled entirely, with alternate transportation for customers between Chicago, IL and St. Louis, MO.

- Trains 302(09-14) cancelled entirely, with alternate transportation for customers between St. Louis and Chicago.

Wolverine Service:

- Trains 350(11-13) cancelled entirely, with alternate transportation for customers between Chicago, IL and Pontiac, MI.

- Trains 355(11-13) cancelled entirely, with alternate transportation for customers between Pontiac, MI and Chicago, IL.

- Trains 350(16) cancelled entirely, with alternate transportation for customers between Chicago, IL and Pontiac, MI.

- Trains 355(16) cancelled entirely, with alternate transportation for customers between Pontiac, MI and Chicago, IL.

Illini/Saluki Service:

- Train 391(14-15) cancelled entirely, with alternate transportation for customers between Chicago, IL and Carbondale, IL.

- Train 392(14-15) cancelled entirely, with alternate transportation for customers between Carbondale and Chicago.

12JUL26: One of the busses providing alternate transportation for Train 302(12), Bus 3, was involved in an auto accident at the Bloomington-Normal, IL station. There were four passengers onboard at the time. No injuries were reported. The station secured transportation for the affected passengers.

WBS#: B.TR.100150.6872

Train	Delay	Comment
381(09-10)	Cancelled	
382(09-10)	Cancelled	
302(09-14)	Cancelled	
305(08-13)	Cancelled	
355(11-13)	Cancelled	
350(11-13)	Cancelled	
391(14-15)	Cancelled	
392(14-15)	Cancelled	

Maintenance of Way Highlights

Gold Runner Service 25.FOL-00003 / 0000000326 / UNCLASSIFIED / 7/2/2026 **Burlington Northern Santa Fe Scheduled M/W Work TWA 26-074**

19JUL26: Burlington Northern Santa Fe Bridge Panel Replacement and Track Maintenance will start at 9:00 AM-PDT with a 24-hr curfew to complete the project. The work will be between Escalon / MP 1191.1 and MP / 1123.9 Modesto, CA station and Stockton, CA Amtrak San Joaquin Station on the Stockton Subdivision. All Gold Runner service will originate and terminate at Merced, CA.

To accommodate the project, the following operating plan will be in effect:

Southbound

- Train 702(19) originated Merced. Customers accommodated on Bus 4302 between Sacramento and Merced.
- Train 710(19) originated Merced. Customers accommodated on Bus 4310 between San Francisco Mission Street and Merced.
- Train 712(19) originated Merced. Customers accommodated on Train 720(19) between Oakland and Martinez, and Bus 4312 between Martinez and Merced.
- Train 714(19) originated Merced. Customers accommodated on Train 724(19) between Oakland and Martinez, and Bus 4314 between Martinez and Merced.
- Train 716(19) originated Merced. Customers accommodated on Train 732(19) between Oakland and Martinez, and Bus 4316 between Martinez and Merced.
- Train 704(19) originated Merced. Customers accommodated on Bus 4304 between Sacramento and Merced.
- Train 718(19) originated Merced. Customers accommodated on Train 738 between Oakland and Martinez, and Bus 4318 between Martinez and Merced.

Northbound

- Train 711(19) terminated at Merced. Customers accommodated on Bus 4311 between Merced and Martinez, and Train 737 between Martinez and Oakland.
- Train 701(19) terminated at Merced. Customers accommodated on Bus 4301 between Merced and Sacramento.
- Train 713(19) terminated at Merced. Customers accommodated on Bus 4313 between Merced and Martinez, and Train 745 between Martinez and Oakland.
- Train 715(19) terminated at Merced. Customers accommodated on Bus 4315 between Merced and Martinez, and Train 747 between Martinez and Oakland.
- Train 717(19) terminated at Merced. Customers accommodated on Bus 4317 between Merced and Martinez, and Train 751 between Martinez and Oakland.
- Train 719(19) terminated at Merced. Customers accommodated on Bus 4319 between Merced and San Francisco Mission Street.
- Train 703(19) operated 30-minutes EARLIER, departing Bakersfield at 5:32pm, and terminated at Merced. Customers accommodated on Bus 4303 between Merced and Sacramento.

All buses will bypass Antioch, CA and Turlock - Denair, CA station with no alternate transportation provided for these two stops.

WBS#: B.TR.100150.6860

Wolverine Track Work- Scheduled M/W Work

15JUL26:

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

BNSF Track Work West of Macomb, IL - Carl Sandburg Service TWA 26-073

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th.

14JUL26: Track was extended one additional week, Monday July 20th through Friday July 24th.

To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL), Train 382(13JUL-17JUL) and Train 382(20JUL-24JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL), Train 381(13JUL-17JUL) and Train 381(20JUL-24JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

09JUL26: This outage was originally scheduled to conclude on Friday July 31st, but will now conclude 2-weeks Earlier on Friday July 17th. The following adjustments are now in place.

- Train 59(21Jun-15Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (16Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-16Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(17Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track construction projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,

Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,

Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,

Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,

Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,

Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,

Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,

Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,

Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
14 (16)	PDX	377		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 517(18) Passenger Removal at Seattle, Washington – Passenger Removal

18JUL26, Passenger on PNR 97B18F, traveling from Seattle, WA to Vancouver, WA was removed from the train by the Conductor for vaping, smoking marijuana, and foul language. Amtrak Police notified.

Delay: 517(18) None

Train 305(18) Passenger Removal at Joliet, Illinois – Passenger Removal

18JUL26, Passenger on PNR 9103C2, traveling from Chicago, IL to St Louis, MO was removed from the train by local Police for intoxication and using profanity towards the crew and other passengers. Amtrak Police notified.

Delay: 305(18) 5"

Consist Deviations

26-FOI-00603

00000008326

"UNCLASSIFIED"

7/21/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
234 (18)	ALB	82681 BYD HVAC; no replacement. Over capacity.	Over by 10 at CRT	10	NOCAR
163 (18)	BOS	Business Class in lieu of Coach	No impact	0	81514
3 (18)	CHI	Operating with snack coach in lieu of baggage coach a/c no good cars on the chi yard.	NO PAX IMPACTED	0	35002
5 (18)	CHI	Operating with snack coach 35008 a/c 31043 shopped for hvac issues no good cars on the yard to replace.	NO IMPACTED PAX	0	35008
7/27 (18)	CHI	Operating with 39006 a/c no good cars to correct consist. Schedule change has been made. CNOC customer svc please run war report and reaccomodate passenger impacted by this. DS / FS reservations.	10 Pax downgraded fully/partially	10	39006
6 (19)	EMY	Operating with standard coach in lieu of baggage coach. Lower level seating will be adjusted to reflect changes.	no pax inpaced	0	34207
566 (18)	LAX	Due to equip change, will be operating w/90225 in consist. We will not be able to accommodate paxs with BV res.Inventory has been adjusted. CNOC CSV Please reaccomodate any paxs impacted by this.	-5 PAX IMPACTED	5	90225
584 (18)	LAX	Due to equip change, will be operating w/90225 in consist. We will not be able to accommodate paxs with BV res.Inventory has been adjusted. CNOC CSV Please reaccomodate any paxs impacted by this.	NO PAX IMPACTED	0	90225
40 (18)	MIA	Viewliner II in lieu of Viewliner I sleeper. Please accomodate all passengers who may be affected-war report	NO IMPACTED PAX	0	62504
58 (19)	NOL	Operating with diner 38040 in lieu of diner /lounge return trip.	NO IMPACTED PAX	0	38040
281 (18)	NYP	82681 BYD HVAC; no replacement. Over capacity.	Passengers notified	60	NOCAR
579 (18)	SAN	Due to equip change, will be operating w/90225 in consist. We	-4 PAX IMPACTED	4	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00603 00000008326 "UNCLASSIFIED"	7/1/18		
		will not be able to accommodate paxs with BV res.Inventory has been adjusted. CNOC CSV Please reaccommodate any paxs impacted by this.			
579 (18)	SAN	Due to equip change, will be operating w/90225 in consist. We will not be able to accommodate paxs with BV res.Inventory has been adjusted. CNOC CSV Please reaccommodate any paxs impacted by this.	-4 PAX IMPACTED	4	90225

Reverse Consists

Train Number	Station	Reason
151 (18)	PHL	Consist reversed Business class seat orientation may have changed At Front Business Class/cafe car at front
150 (18)	PHL	Consist reversed Business class seat orientation may have changed At Front
109 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front
161 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
135 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
158 (19)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 158(19)**
194 (18)	WAS	Consist reversed Business class seat orientation may have changed At Front
142 (18)	WAS	Consist reversed Business class seat orientation may have changed At Front