



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, July 20, 2026

Rules: 2-39



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/19/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/19/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	296	45	84.8%	5,776	861	85.1%	87,120	11,982	86.2%
Central Division	86.0%	55	5	90.9%	1,045	106	89.9%	16,736	1,497	91.1%
East Division	82.0%	156	27	82.7%	3,029	525	82.7%	45,615	7,137	84.4%
West Division	86.0%	85	13	84.7%	1,702	230	86.5%	24,769	3,348	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00603 00000008325 UNCLASSIFIED Endpoint Arrival Dates through 7/19/26 7/21/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	114,339	32,450	72%	2,035,095	744,097	63%	28,982,419	7,218,383	75%
Northeast Corridor	81%	52,514	14,417	73%	869,894	335,097	61%	12,713,675	3,118,290	75%
Acela	83%	9,855	2,673	73%	190,350	70,799	63%	2,527,115	673,476	73%
Northeast Regional	79%	42,659	11,744	72%	679,544	264,298	61%	10,186,560	2,444,814	76%
Richmond / Newport News / Norfolk	77%	13,196	4,050	69%	212,238	101,896	52%	3,162,966	915,517	71%
Springfield Shuttles	89%	885	71	92%	12,718	3,617	72%	180,752	27,831	85%
Roanoke	79%	3,975	1,266	68%	65,762	30,457	54%	958,822	205,742	79%
On Spine Northeast Regional	80%	24,603	6,357	74%	388,826	128,328	67%	5,884,020	1,295,724	78%
State Supported	80%	49,615	11,788	76%	918,882	251,384	73%	12,704,930	2,613,748	79%
Borealis	80%	536	0	100%	11,350	2,308	80%	162,320	32,754	80%
Capitol Corridor	90%	3,291	297	91%	70,817	10,413	85%	1,072,036	139,609	87%
Carolinian	70%	1,795	1,307	27%	21,289	14,291	33%	331,263	130,197	61%
Cascades	75%	3,300	650	80%	60,104	14,812	75%	747,748	203,372	73%
Downeaster	82%	2,375	0	100%	37,439	8,243	78%	434,937	53,713	88%
Empire	78%	7,074	2,329	67%	116,878	42,067	64%	1,570,883	356,484	77%
Adirondack	72%	489	0	100%	8,237	3,601	56%	94,670	29,085	69%
Ethan Allen Express	70%	627	594	5%	11,094	7,605	31%	162,059	55,212	66%
Maple Leaf	70%	1,230	371	70%	16,563	6,496	61%	191,382	73,283	62%
New York - Albany	85%	2,645	715	73%	51,551	12,368	76%	728,716	116,268	84%
New York - Niagara Falls	75%	1,522	409	73%	26,240	9,907	62%	387,699	79,686	79%
Berkshire Flyer	60%	561	240	57%	3,193	2,090	35%	6,357	2,950	54%
Gold Runner	73%	1,443	914	37%	49,910	20,256	59%	723,530	252,354	65%
Heartland Flyer	70%	321	308	4%	5,373	2,915	46%	61,078	23,408	62%
Hiawatha	90%	2,230	277	88%	38,242	2,691	93%	495,936	53,239	89%
Illinois	78%	3,325	946	72%	50,299	18,452	63%	712,454	194,496	73%
Carl Sandburg / Illinois Zephyr	85%	758	228	70%	9,324	3,449	63%	118,878	31,255	74%
Illini / Saluki	85%	898	425	53%	16,745	6,400	62%	250,407	60,427	76%
Lincoln Service	70%	1,669	293	82%	24,230	8,603	64%	343,169	102,814	70%
Keystone	92%	5,586	225	96%	134,454	20,141	85%	2,191,531	230,076	90%
Lincoln / Missouri	70%	960	946	1%	13,859	8,224	41%	222,378	112,040	50%
Mardi Gras Service	80%	436	336	23%	7,753	3,088	60%	118,701	25,549	78%
Michigan	70%	2,475	632	74%	45,232	16,833	63%	564,979	181,788	68%
Blue Water	70%	364	356	2%	11,180	7,177	36%	131,406	52,511	60%
Pere Marquette	85%	401	0	100%	6,565	1,268	81%	74,137	14,598	80%
Wolverine	70%	1,710	276	84%	27,487	8,388	69%	359,436	114,679	68%
Missouri	80%	286	135	53%	3,669	1,379	62%	62,905	14,619	77%
Pacific Surfliner	85%	10,532	2,161	79%	196,690	41,795	79%	2,279,214	368,957	84%
Pennsylvanian	80%	930	1	100%	17,129	6,508	62%	255,839	48,667	81%
Piedmont	80%	1,345	324	76%	14,602	6,619	55%	327,987	85,173	74%
Vermont	75%	1,375	0	100%	23,793	10,349	57%	369,211	107,253	71%
Long Distance	70%	12,210	6,245	49%	246,319	157,616	36%	3,524,547	1,483,882	58%
Auto Train	70%	903	0	100%	15,788	6,160	61%	224,632	76,988	66%
California Zephyr	70%	1,147	637	44%	19,648	13,055	34%	279,711	98,352	65%
Cardinal	70%	0	0	-	4,670	3,248	30%	68,344	33,490	51%
City Of New Orleans	75%	723	314	57%	5,122	3,797	26%	182,486	53,414	71%
Coast Starlight	70%	1,379	790	43%	24,143	8,098	66%	328,907	112,550	66%
Crescent	70%	1,000	936	6%	18,246	10,887	40%	268,739	82,979	69%
Empire Builder	70%	1,169	909	22%	23,710	16,072	32%	276,771	134,824	51%
Floridian	60%	0	0	-	28,260	26,765	5%	458,425	310,408	32%
Lake Shore Ltd	73%	1,181	129	89%	22,619	9,266	59%	274,256	80,876	71%
Palmetto	70%	945	330	65%	17,153	11,763	31%	264,926	77,861	71%
Silver Meteor	70%	1,131	1,013	10%	20,453	16,896	17%	292,834	127,048	57%
Southwest Chief	60%	514	275	46%	18,852	13,798	27%	237,502	152,210	36%
Sunset Ltd	70%	343	97	72%	6,246	3,742	40%	84,631	30,423	64%
Texas Eagle	70%	1,775	815	54%	21,409	14,069	34%	282,383	112,459	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FOI-00000 00000000025 "UNCLASSIFIED" 7/21/2026

Train Index Dates Through July 19, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	135,323	2,006,784	674	1,702,256	30,637,869	556

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	8,099	587,890	138	81,439	8,796,387	93
INFRASTRUCTURE PLANNED	135	9,540	587,890	162	88,412	8,796,387	101
FLEET RELIABILITY	90	20,057	2,006,784	100	273,046	30,637,869	89
TRAIN OPERATIONS	424	97,627	2,006,784	486	1,259,359	30,637,869	411

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/19/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/19/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	296	45	84.8%	5,776	861	85.1%	87,120	11,982	86.2%
Central Division	86.0%	55	5	90.9%	1,045	106	89.9%	16,736	1,497	91.1%
East Division	82.0%	156	27	82.7%	3,029	525	82.7%	45,615	7,137	84.4%
West Division	86.0%	85	13	84.7%	1,702	230	86.5%	24,769	3,348	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0060 Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/19/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 07/19/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	296	45	84.8%	5,776	861	85.1%	87,120	11,982	86.2%
Central Division	86.0%	55	5	90.9%	1,045	106	89.9%	16,736	1,497	91.1%
CDL	95.0%	2	0	100.0%	35	4	88.6%	552	22	96.0%
CHI	86.0%	25	4	84.0%	490	59	88.0%	7,727	922	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	19	1	94.7%	315	35	88.9%
GBB	-	-	-	-	8	7	12.5%	8	7	12.5%
GRR	95.5%	1	0	100.0%	18	0	100.0%	277	8	97.1%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	29	2	93.1%	567	42	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	1	80.0%	111	7	93.7%	1,709	104	93.9%
MOE	97.5%	2	0	100.0%	38	1	97.4%	583	9	98.5%
MSP	96.5%	1	0	100.0%	19	0	100.0%	285	5	98.2%
NOL	94.5%	4	0	100.0%	74	6	91.9%	1,224	59	95.2%
OKC	97.0%	1	0	100.0%	19	0	100.0%	286	6	97.9%
PNT	88.0%	3	0	100.0%	48	4	91.7%	751	62	91.7%
PTH	93.0%	1	0	100.0%	19	1	94.7%	280	11	96.1%
QCY	91.0%	2	0	100.0%	27	3	88.9%	558	43	92.3%
SAS	90.5%	1	0	100.0%	19	3	84.2%	288	30	89.6%
STL	89.0%	4	0	100.0%	71	7	90.1%	1,128	97	91.4%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	156	27	82.7%	3,029	525	82.7%	45,615	7,137	84.4%
ALB	88.5%	7	0	100.0%	146	8	94.5%	2,160	169	92.2%
ATL	-	-	-	-	-	-	-	35	5	85.7%
BON	87.5%	5	0	100.0%	94	12	87.2%	1,406	152	89.2%
BOS	85.5%	17	4	76.5%	313	25	92.0%	4,949	586	88.2%
BRK	92.5%	5	1	80.0%	91	14	84.6%	1,392	98	93.0%
BTN	82.0%	1	0	100.0%	19	1	94.7%	278	40	85.6%
CLT	91.5%	5	0	100.0%	76	17	77.6%	1,417	149	89.5%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	38	4	89.5%	569	54	90.5%
GRO	-	-	-	-	4	0	100.0%	33	10	69.7%
HAR	79.5%	7	2	71.4%	196	27	86.2%	3,219	533	83.4%
HFD	-	-	-	-	24	4	83.3%	171	12	93.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	19	1	94.7%	288	35	87.8%
MIA	89.5%	2	1	50.0%	37	6	83.8%	576	66	88.5%
MTR	79.0%	1	0	100.0%	19	4	78.9%	275	50	81.8%

Information Management

26-FOI-0060 Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/19/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	296	45	84.8%	5,776	861	85.1%	87,120	11,982	86.2%
East Division	82.0%	156	27	82.7%	3,029	525	82.7%	45,615	7,137	84.4%
NFK	84.5%	2	0	100.0%	38	9	76.3%	659	118	82.1%
NFL	93.5%	2	0	100.0%	38	3	92.1%	588	25	95.7%
NFS	-	-	-	-	1	1	0.0%	7	6	14.3%
NHV	78.0%	5	1	80.0%	91	15	83.5%	1,497	238	84.1%
NPN	93.0%	2	0	100.0%	36	4	88.9%	549	39	92.9%
NYP	75.5%	42	11	73.8%	853	210	75.4%	11,904	2,671	77.6%
PGH	93.0%	1	0	100.0%	19	3	84.2%	290	22	92.4%
PHL	48.0%	4	3	25.0%	92	40	56.5%	1,492	717	51.9%
PIT	76.0%	1	1	0.0%	6	6	0.0%	12	11	8.3%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	4	0	100.0%	53	6	88.7%	1,110	47	95.8%
RNK	83.5%	2	0	100.0%	38	8	78.9%	572	85	85.1%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	16	0	100.0%	275	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	17	0	100.0%	285	10	96.5%
SFA	88.0%	1	0	100.0%	19	1	94.7%	288	38	86.8%
SPG	92.5%	7	0	100.0%	94	6	93.6%	1,746	98	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	18	1	94.4%	277	57	79.4%
WAS	84.0%	27	3	88.9%	520	85	83.7%	7,113	926	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	85	13	84.7%	1,702	230	86.5%	24,769	3,348	86.5%
ARN	92.0%	1	0	100.0%	19	5	73.7%	290	24	91.7%
BFD	79.0%	7	2	71.4%	128	28	78.1%	1,814	369	79.7%
EMY	72.0%	1	0	100.0%	19	7	63.2%	306	93	69.6%
EUG	86.5%	2	0	100.0%	38	1	97.4%	574	53	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	1	50.0%	3	2	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	57	15	73.7%	873	129	85.2%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	1	90.9%	199	21	89.4%	2,874	297	89.7%
MCD	-	7	6	14.3%	7	6	14.3%	15	13	13.3%
OKJ	74.5%	4	1	75.0%	215	59	72.6%	3,114	795	74.5%
PDX	86.0%	5	0	100.0%	95	6	93.7%	1,432	172	88.0%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	10	1	90.0%	278	28	89.9%	4,083	438	89.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/19/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/19/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	296	45	84.8%	5,776	861	85.1%	87,120	11,982	86.2%
West Division	86.0%	85	13	84.7%	1,702	230	86.5%	24,769	3,348	86.5%
SAN	90.5%	13	0	100.0%	246	17	93.1%	3,490	311	91.1%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	152	18	88.2%	2,294	328	85.7%
SJC	89.0%	7	0	100.0%	133	15	88.7%	2,040	197	90.3%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	57	2	96.5%	636	62	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	19	1	94.7%	285	21	92.6%
VAC	97.0%	2	0	100.0%	38	0	100.0%	568	14	97.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		9	3	66.7%	124	28	77.4%	8	2	75.0%	120	22	81.7%
3		19	2	89.5%	290	56	80.7%	19	9	52.6%	288	126	56.3%
4	No OS	19	1	94.7%	289	43	85.1%	19	11	42.1%	289	190	34.3%
5		19	3	84.2%	288	46	84.0%	18	14	22.2%	284	77	72.9%
6		19	7	63.2%	287	84	70.7%	19	12	36.8%	287	94	67.2%
7	98	19	2	89.5%	279	37	86.7%	19	8	57.9%	272	69	74.6%
8	86	19	10	47.4%	279	121	56.6%	19	16	15.8%	278	165	40.6%
11	114	19	3	84.2%	290	53	81.7%	19	4	78.9%	284	58	79.6%
14		19	3	84.2%	291	44	84.9%	19	3	84.2%	289	86	70.2%
19		19	10	47.4%	289	75	74.0%	19	11	42.1%	287	70	75.6%
20	63	19	4	78.9%	289	22	92.4%	19	10	47.4%	289	57	80.3%
21	35	19	1	94.7%	286	23	92.0%	19	14	26.3%	285	76	73.3%
22		19	3	84.2%	287	28	90.2%	19	13	31.6%	285	75	73.7%
23	33	19	1	94.7%	292	6	97.9%	19	10	47.4%	290	79	72.8%
24	73	19	2	89.5%	292	16	94.5%	19	8	57.9%	291	51	82.5%
25	39	19	0	100.0%	291	3	99.0%	19	8	57.9%	289	77	73.4%
26		19	0	100.0%	291	5	98.3%	19	6	68.4%	289	58	79.9%
27	148	19	4	78.9%	277	18	93.5%	19	9	52.6%	273	90	67.0%
28	73	19	2	89.5%	273	61	77.7%	19	3	84.2%	273	54	80.2%
41	485	17	8	52.9%	283	110	61.1%	18	18	0.0%	282	214	24.1%
42		19	3	84.2%	291	23	92.1%	19	6	68.4%	289	48	83.4%
43		19	1	94.7%	290	42	85.5%	19	11	42.1%	290	67	76.9%
48		19	3	84.2%	289	56	80.6%	19	3	84.2%	289	41	85.8%
49		19	4	78.9%	289	71	75.4%	19	7	63.2%	289	59	79.6%
50	No OS	8	2	75.0%	119	28	76.5%	9	8	11.1%	119	71	40.3%
52		19	1	94.7%	288	38	86.8%	19	6	68.4%	287	67	76.7%
53		19	1	94.7%	288	35	87.8%	19	6	68.4%	287	91	68.3%
54		7	1	85.7%	107	7	93.5%	7	3	57.1%	107	16	85.0%
57		7	1	85.7%	106	5	95.3%	7	3	57.1%	106	9	91.5%
58		8	0	100.0%	267	16	94.0%	7	4	42.9%	265	69	74.0%
59	148	7	3	57.1%	265	31	88.3%	6	6	0.0%	261	52	80.1%
63	27	19	10	47.4%	292	127	56.5%	18	16	11.1%	287	156	45.6%
64		19	2	89.5%	290	65	77.6%	19	10	47.4%	290	101	65.2%
65	43	7	0	100.0%	90	12	86.7%	6	2	66.7%	89	13	85.4%
66		19	6	68.4%	289	60	79.2%	17	2	88.2%	285	51	82.1%
68		19	4	78.9%	292	59	79.8%	19	10	47.4%	292	113	61.3%
69		19	3	84.2%	279	62	77.8%	19	8	57.9%	275	40	85.5%
71		19	0	100.0%	287	3	99.0%	19	11	42.1%	286	77	73.1%
72		15	2	86.7%	283	31	89.0%	15	4	73.3%	282	59	79.1%
73	13	14	2	85.7%	286	18	93.7%	14	9	35.7%	284	135	52.5%
74	15	14	3	78.6%	284	33	88.4%	14	10	28.6%	282	104	63.1%
75		10	1	90.0%	280	15	94.6%	9	6	33.3%	274	131	52.2%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76	21	10	2	80.0%	280	28	90.0%	9	6	33.3%	271	110	59.4%
77	18	13	3	76.9%	282	20	92.9%	13	10	23.1%	280	118	57.9%
78		18	5	72.2%	286	25	91.3%	18	10	44.4%	285	60	78.9%
79		19	0	100.0%	289	55	81.0%	19	14	26.3%	288	98	66.0%
80	37	19	5	73.7%	289	33	88.6%	18	11	38.9%	286	60	79.0%
87	79	7	0	100.0%	110	24	78.2%	7	6	14.3%	110	39	64.5%
88		4	1	75.0%	106	15	85.8%	4	1	75.0%	106	23	78.3%
89	46	19	5	73.7%	287	63	78.0%	19	13	31.6%	285	83	70.9%
90		19	0	100.0%	287	10	96.5%	19	11	42.1%	286	48	83.2%
96		3	1	66.7%	37	8	78.4%	3	1	66.7%	37	10	73.0%
97	37	19	17	10.5%	289	190	34.3%	19	15	21.1%	287	91	68.3%
98	66	19	3	84.2%	289	24	91.7%	19	18	5.3%	287	98	65.9%
99		7	0	100.0%	109	12	89.0%	5	3	40.0%	106	60	43.4%
100		3	1	66.7%	22	5	77.3%	3	2	33.3%	21	4	81.0%
103		7	0	100.0%	108	21	80.6%	7	1	85.7%	108	9	91.7%
104		2	0	100.0%	34	4	88.2%	2	0	100.0%	34	3	91.2%
105		2	2	0.0%	36	17	52.8%	2	1	50.0%	36	6	83.3%
117		3	1	66.7%	21	12	42.9%	3	1	66.7%	21	4	81.0%
118		7	2	71.4%	108	8	92.6%	7	2	71.4%	108	7	93.5%
120		3	0	100.0%	37	5	86.5%	3	1	66.7%	37	4	89.2%
121	27	3	1	66.7%	37	10	73.0%	3	2	33.3%	37	16	56.8%
122		2	1	50.0%	36	14	61.1%	2	0	100.0%	36	8	77.8%
123		3	0	100.0%	39	6	84.6%	3	0	100.0%	39	1	97.4%
124		7	1	85.7%	107	8	92.5%	7	6	14.3%	106	29	72.6%
128	46	7	0	100.0%	110	19	82.7%	6	5	16.7%	109	21	80.7%
132		3	0	100.0%	37	3	91.9%	3	0	100.0%	37	4	89.2%
135		7	0	100.0%	109	17	84.4%	7	5	28.6%	109	56	48.6%
140	17	7	0	100.0%	108	12	88.9%	7	3	57.1%	107	23	78.5%
143	50	7	2	71.4%	107	11	89.7%	7	3	57.1%	107	25	76.6%
145	39	3	1	66.7%	37	6	83.8%	3	3	0.0%	37	13	64.9%
146		7	1	85.7%	107	17	84.1%	7	5	28.6%	107	39	63.6%
149		2	1	50.0%	37	3	91.9%	2	0	100.0%	37	14	62.2%
150		7	3	57.1%	106	57	46.2%	7	2	71.4%	104	50	51.9%
151		19	5	73.7%	288	91	68.4%	19	10	47.4%	287	94	67.2%
153		7	2	71.4%	108	10	90.7%	7	2	71.4%	108	16	85.2%
154		3	1	66.7%	37	5	86.5%	3	1	66.7%	37	20	45.9%
155	100	7	3	57.1%	110	18	83.6%	7	7	0.0%	110	40	63.6%
156		7	1	85.7%	110	11	90.0%	7	6	14.3%	110	37	66.4%
157		3	1	66.7%	37	3	91.9%	3	0	100.0%	37	11	70.3%
158		7	3	57.1%	109	18	83.5%	7	6	14.3%	109	26	76.1%
160		7	1	85.7%	107	6	94.4%	6	2	66.7%	104	25	76.0%
161	28	7	0	100.0%	108	9	91.7%	7	7	0.0%	107	70	34.6%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
162		7	2	71.4%	108	7	93.5%	7	5	28.6%	108	54	50.0%
164		7	1	85.7%	110	9	91.8%	7	3	57.1%	110	47	57.3%
165		6	0	100.0%	108	27	75.0%	6	5	16.7%	108	45	58.3%
169		7	0	100.0%	108	12	88.9%	6	2	66.7%	107	23	78.5%
189	20	2	0	100.0%	36	10	72.2%	2	2	0.0%	36	15	58.3%
195	18	7	0	100.0%	108	4	96.3%	7	5	28.6%	108	57	47.2%
230		19	0	100.0%	126	4	96.8%	19	0	100.0%	126	6	95.2%
232		19	0	100.0%	292	11	96.2%	19	0	100.0%	292	17	94.2%
234		19	1	94.7%	292	20	93.2%	19	0	100.0%	292	24	91.8%
235	24	19	3	84.2%	216	30	86.1%	19	7	63.2%	216	48	77.8%
236		19	2	89.5%	276	9	96.7%	19	3	84.2%	276	39	85.9%
237		19	3	84.2%	290	55	81.0%	19	5	73.7%	288	48	83.3%
238	22	19	0	100.0%	216	19	91.2%	19	2	89.5%	215	16	92.6%
239		19	4	78.9%	291	76	73.9%	19	4	78.9%	290	34	88.3%
240		19	0	100.0%	291	20	93.1%	19	9	52.6%	289	53	81.7%
241		19	4	78.9%	292	72	75.3%	19	3	84.2%	292	69	76.4%
243		19	7	63.2%	228	62	72.8%	19	5	73.7%	227	31	86.3%
245		19	4	78.9%	173	31	82.1%	19	3	84.2%	172	20	88.4%
280		19	2	89.5%	292	13	95.5%	19	3	84.2%	292	53	81.8%
281		19	4	78.9%	292	33	88.7%	19	7	63.2%	292	54	81.5%
283	28	19	7	63.2%	292	71	75.7%	19	8	57.9%	292	60	79.5%
284		19	1	94.7%	292	11	96.2%	19	9	52.6%	290	51	82.4%
290	28	19	1	94.7%	292	49	83.2%	19	14	26.3%	290	105	63.8%
291	19	19	10	47.4%	291	85	70.8%	19	10	47.4%	289	68	76.5%
300		19	1	94.7%	276	20	92.8%	19	8	57.9%	274	64	76.6%
301	17	19	0	100.0%	290	9	96.9%	19	4	78.9%	287	54	81.2%
302		13	1	92.3%	271	32	88.2%	13	4	69.2%	267	76	71.5%
305		13	0	100.0%	274	28	89.8%	13	7	46.2%	270	109	59.6%
306		19	0	100.0%	288	15	94.8%	19	6	68.4%	287	77	73.2%
307		19	3	84.2%	280	38	86.4%	19	8	57.9%	277	78	71.8%
311	46	16	2	87.5%	287	25	91.3%	15	6	60.0%	281	56	80.1%
316		15	1	93.3%	283	17	94.0%	14	6	57.1%	279	70	74.9%
318	61	18	4	77.8%	290	30	89.7%	18	12	33.3%	287	136	52.6%
319	50	18	2	88.9%	291	19	93.5%	15	11	26.7%	286	156	45.5%
331	27	19	3	84.2%	292	32	89.0%	19	2	89.5%	292	42	85.6%
332		19	2	89.5%	292	16	94.5%	19	3	84.2%	292	42	85.6%
334		19	1	94.7%	292	10	96.6%	19	1	94.7%	291	37	87.3%
335		19	0	100.0%	292	30	89.7%	19	4	78.9%	290	47	83.8%
336		19	1	94.7%	292	9	96.9%	19	2	89.5%	290	27	90.7%
337		19	1	94.7%	292	18	93.8%	19	2	89.5%	288	35	87.8%
338		19	3	84.2%	292	44	84.9%	19	6	68.4%	290	87	70.0%
339		19	2	89.5%	292	48	83.6%	19	2	89.5%	292	50	82.9%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
341		19	5	73.7%	281	40	85.8%	19	4	78.9%	276	39	85.9%
342		19	0	100.0%	292	21	92.8%	19	2	89.5%	290	55	81.0%
350	16	15	1	93.3%	269	18	93.3%	13	6	53.8%	262	142	45.8%
351		19	2	89.5%	275	27	90.2%	19	5	73.7%	273	73	73.3%
352		19	1	94.7%	259	21	91.9%	19	5	73.7%	253	76	70.0%
353		15	1	93.3%	230	13	94.3%	15	2	86.7%	224	37	83.5%
354		19	7	63.2%	273	35	87.2%	16	7	56.3%	266	96	63.9%
355		15	2	86.7%	282	29	89.7%	15	8	46.7%	275	93	66.2%
364	39	19	2	89.5%	281	62	77.9%	19	12	36.8%	275	102	62.9%
365	25	19	1	94.7%	280	11	96.1%	19	12	36.8%	278	104	62.6%
370		19	1	94.7%	283	34	88.0%	18	3	83.3%	275	68	75.3%
371		18	0	100.0%	277	8	97.1%	18	2	88.9%	276	29	89.5%
380		18	3	83.3%	277	27	90.3%	18	8	55.6%	277	57	79.4%
381	24	17	1	94.1%	290	12	95.9%	17	5	70.6%	289	53	81.7%
382		17	7	58.8%	289	23	92.0%	17	10	41.2%	289	94	67.5%
383		19	1	94.7%	281	26	90.7%	18	10	44.4%	278	115	58.6%
390	37	19	1	94.7%	274	18	93.4%	19	8	57.9%	273	71	74.0%
391	36	17	2	88.2%	275	10	96.4%	17	8	52.9%	272	73	73.2%
392		16	3	81.3%	288	8	97.2%	16	10	37.5%	286	88	69.2%
393		19	1	94.7%	292	17	94.2%	19	12	36.8%	289	89	69.2%
400		7	0	100.0%	89	6	93.3%	7	0	100.0%	87	2	97.7%
405		5	0	100.0%	82	0	100.0%	5	0	100.0%	82	4	95.1%
409		2	0	100.0%	39	1	97.4%	2	1	50.0%	39	4	89.7%
416		2	0	100.0%	35	4	88.6%	2	0	100.0%	35	3	91.4%
448	194	19	5	73.7%	222	43	80.6%	19	7	63.2%	220	75	65.9%
449		19	2	89.5%	220	32	85.5%	19	4	78.9%	220	40	81.8%
450	33	5	1	80.0%	86	27	68.6%	5	3	40.0%	84	27	67.9%
460		5	0	100.0%	85	27	68.2%	5	3	40.0%	82	28	65.9%
461		7	0	100.0%	90	5	94.4%	7	0	100.0%	89	2	97.8%
464		5	0	100.0%	85	16	81.2%	5	1	80.0%	83	25	69.9%
465		2	0	100.0%	39	1	97.4%	2	0	100.0%	39	1	97.4%
488		8	4	50.0%	94	25	73.4%	7	2	71.4%	85	13	84.7%
497		2	0	100.0%	36	1	97.2%	2	0	100.0%	36	7	80.6%
499		7	2	71.4%	86	13	84.9%	7	0	100.0%	83	6	92.8%
500		19	1	94.7%	283	16	94.3%	18	1	94.4%	280	33	88.2%
502		19	1	94.7%	290	16	94.5%	18	1	94.4%	286	57	80.1%
503		19	1	94.7%	288	26	91.0%	19	9	52.6%	282	83	70.6%
504		19	0	100.0%	292	17	94.2%	19	5	73.7%	290	87	70.0%
505		19	1	94.7%	290	37	87.2%	18	6	66.7%	285	79	72.3%
506	20	19	2	89.5%	287	40	86.1%	19	4	78.9%	282	45	84.0%
507	18	19	1	94.7%	292	35	88.0%	19	6	68.4%	292	94	67.8%
508		19	1	94.7%	287	40	86.1%	19	4	78.9%	284	66	76.8%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
509		19	1	94.7%	289	13	95.5%	19	3	84.2%	289	66	77.2%
511		19	0	100.0%	284	21	92.6%	19	0	100.0%	283	45	84.1%
516		19	1	94.7%	284	28	90.1%	19	3	84.2%	283	126	55.5%
517		19	0	100.0%	292	8	97.3%	19	12	36.8%	288	120	58.3%
518	32	19	0	100.0%	292	35	88.0%	19	13	31.6%	290	196	32.4%
519		19	0	100.0%	284	9	96.8%	19	1	94.7%	282	64	77.3%
562		19	1	94.7%	284	22	92.3%	19	1	94.7%	281	30	89.3%
564		19	1	94.7%	284	18	93.7%	19	3	84.2%	276	33	88.0%
566		19	4	78.9%	282	21	92.6%	19	4	78.9%	279	36	87.1%
567		19	1	94.7%	169	9	94.7%	19	1	94.7%	167	7	95.8%
572		19	0	100.0%	279	22	92.1%	18	9	50.0%	273	74	72.9%
573		19	0	100.0%	282	40	85.8%	19	2	89.5%	275	46	83.3%
579		19	0	100.0%	169	8	95.3%	19	4	78.9%	164	30	81.7%
580		19	0	100.0%	284	14	95.1%	19	2	89.5%	279	23	91.8%
581		19	3	84.2%	284	46	83.8%	19	4	78.9%	282	58	79.4%
584	27	19	5	73.7%	168	22	86.9%	18	15	16.7%	163	97	40.5%
587	46	18	0	100.0%	278	15	94.6%	18	8	55.6%	269	46	82.9%
588		19	2	89.5%	169	14	91.7%	19	2	89.5%	168	24	85.7%
591		19	0	100.0%	283	18	93.6%	19	2	89.5%	277	31	88.8%
593	17	19	4	78.9%	278	41	85.3%	18	2	88.9%	259	29	88.8%
595	30	19	4	78.9%	279	45	83.9%	19	5	73.7%	276	51	81.5%
612		2	1	50.0%	36	5	86.1%	2	1	50.0%	36	1	97.2%
615	30	3	3	0.0%	37	21	43.2%	2	2	0.0%	36	7	80.6%
637		7	1	85.7%	61	7	88.5%	6	0	100.0%	60	4	93.3%
660		6	1	83.3%	79	12	84.8%	5	0	100.0%	78	25	67.9%
661		6	0	100.0%	107	11	89.7%	6	2	66.7%	106	39	63.2%
663		7	4	42.9%	80	14	82.5%	6	1	83.3%	79	7	91.1%
664		7	2	71.4%	79	8	89.9%	7	5	28.6%	79	11	86.1%
665		7	2	71.4%	80	10	87.5%	7	5	28.6%	80	24	70.0%
666		5	2	60.0%	78	22	71.8%	5	0	100.0%	78	7	91.0%
667		5	1	80.0%	78	7	91.0%	3	2	33.3%	76	16	78.9%
669		6	0	100.0%	78	7	91.0%	4	2	50.0%	76	22	71.1%
670		7	3	57.1%	80	13	83.8%	5	2	60.0%	78	15	80.8%
671		6	2	66.7%	78	8	89.7%	4	2	50.0%	76	9	88.2%
672		7	1	85.7%	80	8	90.0%	7	3	57.1%	80	15	81.3%
674		6	4	33.3%	78	26	66.7%	6	2	66.7%	78	6	92.3%
690		6	0	100.0%	84	2	97.6%	6	0	100.0%	83	4	95.2%
691		6	0	100.0%	84	7	91.7%	6	2	66.7%	82	23	72.0%
692		6	0	100.0%	84	3	96.4%	6	1	83.3%	83	14	83.1%
693		6	0	100.0%	84	12	85.7%	5	2	60.0%	82	23	72.0%
694		5	3	40.0%	83	9	89.2%	5	0	100.0%	83	14	83.1%
695		5	1	80.0%	82	10	87.8%	5	0	100.0%	82	14	82.9%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
696		6	1	83.3%	84	9	89.3%	6	4	33.3%	84	24	71.4%
697		6	2	66.7%	84	18	78.6%	6	2	66.7%	84	17	79.8%
698		6	0	100.0%	82	2	97.6%	6	0	100.0%	82	7	91.5%
701		19	3	84.2%	224	24	89.3%	19	3	84.2%	221	23	89.6%
702		19	1	94.7%	291	32	89.0%	18	5	72.2%	288	65	77.4%
703	50	19	10	47.4%	292	87	70.2%	18	10	44.4%	290	80	72.4%
704	61	19	3	84.2%	223	35	84.3%	18	3	83.3%	217	41	81.1%
710	58	19	7	63.2%	292	76	74.0%	19	6	68.4%	288	79	72.6%
711		19	3	84.2%	283	31	89.0%	15	2	86.7%	262	47	82.1%
712	19	19	6	68.4%	289	77	73.4%	18	5	72.2%	280	92	67.1%
713		15	1	93.3%	161	15	90.7%	14	6	57.1%	147	62	57.8%
714	74	18	11	38.9%	173	69	60.1%	18	10	44.4%	161	68	57.8%
715		19	2	89.5%	291	60	79.4%	15	7	53.3%	268	132	50.7%
716	83	19	8	57.9%	292	115	60.6%	18	6	66.7%	286	108	62.2%
717	43	18	2	88.9%	277	64	76.9%	17	7	58.8%	258	77	70.2%
718		19	9	52.6%	292	145	50.3%	19	10	47.4%	290	101	65.2%
719	80	19	7	63.2%	292	95	67.5%	18	8	55.6%	277	80	71.1%
720		6	0	100.0%	91	9	90.1%	6	1	83.3%	91	5	94.5%
723		6	1	83.3%	91	6	93.4%	6	0	100.0%	91	9	90.1%
724	13	6	0	100.0%	91	3	96.7%	6	3	50.0%	91	18	80.2%
727		6	0	100.0%	91	6	93.4%	6	0	100.0%	91	14	84.6%
728		6	0	100.0%	91	6	93.4%	6	1	83.3%	91	16	82.4%
729		6	5	16.7%	90	14	84.4%	5	1	80.0%	89	21	76.4%
732	64	6	1	83.3%	89	15	83.1%	6	2	66.7%	87	16	81.6%
733		6	1	83.3%	91	14	84.6%	6	2	66.7%	87	29	66.7%
734	11	6	0	100.0%	91	14	84.6%	6	3	50.0%	90	20	77.8%
736		6	2	66.7%	67	6	91.0%	4	0	100.0%	65	7	89.2%
737		6	1	83.3%	67	7	89.6%	5	0	100.0%	66	11	83.3%
738		6	2	66.7%	91	14	84.6%	6	3	50.0%	87	13	85.1%
741		6	1	83.3%	91	13	85.7%	6	2	66.7%	91	17	81.3%
742		6	1	83.3%	91	11	87.9%	6	0	100.0%	89	7	92.1%
743		6	2	66.7%	91	17	81.3%	6	1	83.3%	90	9	90.0%
744		6	3	50.0%	91	14	84.6%	6	3	50.0%	91	31	65.9%
745		6	2	66.7%	91	9	90.1%	6	0	100.0%	91	14	84.6%
746		6	1	83.3%	91	7	92.3%	6	1	83.3%	91	13	85.7%
747		6	0	100.0%	91	14	84.6%	6	2	66.7%	91	20	78.0%
748		6	0	100.0%	90	12	86.7%	6	0	100.0%	90	13	85.6%
749		6	1	83.3%	88	13	85.2%	5	1	80.0%	80	10	87.5%
751		6	1	83.3%	90	15	83.3%	6	2	66.7%	88	11	87.5%
757		19	1	94.7%	77	4	94.8%	19	3	84.2%	76	7	90.8%
761		19	1	94.7%	288	12	95.8%	19	2	89.5%	285	36	87.4%
765		19	0	100.0%	288	24	91.7%	19	2	89.5%	288	38	86.8%

Amtrak On Time Performance

Trains Arriving Through: 7/19/2026

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
769		19	1	94.7%	288	26	91.0%	19	2	89.5%	282	51	81.9%
770	31	19	0	100.0%	288	21	92.7%	19	9	52.6%	286	83	71.0%
774		19	0	100.0%	288	16	94.4%	19	5	73.7%	287	61	78.7%
777		19	1	94.7%	173	10	94.2%	19	3	84.2%	172	37	78.5%
782		19	15	21.1%	173	71	59.0%	19	3	84.2%	168	18	89.3%
785		19	2	89.5%	288	19	93.4%	19	3	84.2%	288	49	83.0%
786	76	19	1	94.7%	77	17	77.9%	19	10	47.4%	76	37	51.3%
790	25	19	0	100.0%	288	26	91.0%	19	4	78.9%	285	36	87.4%
794		19	1	94.7%	288	32	88.9%	19	3	84.2%	285	58	79.6%
821	30	19	0	100.0%	286	6	97.9%	19	11	42.1%	286	114	60.1%
822	23	19	1	94.7%	288	15	94.8%	19	13	31.6%	286	131	54.2%
1233	38	6	2	66.7%	12	4	66.7%	6	4	33.3%	12	7	41.7%
1246		6	6	0.0%	12	11	8.3%	6	4	33.3%	12	5	58.3%
1333		19	2	89.5%	288	30	89.6%	19	6	68.4%	285	94	67.0%
1340		19	0	100.0%	287	5	98.3%	19	3	84.2%	287	45	84.3%
1689		10	0	100.0%	84	5	94.0%	11	1	90.9%	84	9	89.3%
2208		7	3	57.1%	9	3	66.7%	7	3	57.1%	9	3	66.7%
2209		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
2212		3	0	100.0%	4	0	100.0%	3	1	66.7%	4	1	75.0%
2213	27	3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
2215		3	1	66.7%	23	9	60.9%	3	1	66.7%	23	13	43.5%
2216		3	0	100.0%	71	3	95.8%	3	1	66.7%	71	3	95.8%
2218	67	3	2	33.3%	68	13	80.9%	3	2	33.3%	68	12	82.4%
2219		7	2	71.4%	9	3	66.7%	7	4	42.9%	9	4	55.6%
2222	18	3	0	100.0%	53	3	94.3%	3	2	33.3%	52	6	88.5%
2223		3	0	100.0%	23	5	78.3%	3	1	66.7%	22	4	81.8%
2224		7	1	85.7%	24	5	79.2%	7	2	71.4%	24	4	83.3%
2226		3	0	100.0%	36	7	80.6%	2	1	50.0%	34	9	73.5%
2227		3	1	66.7%	3	1	66.7%	3	0	100.0%	3	0	100.0%
2233		3	2	33.3%	21	5	76.2%	3	2	33.3%	21	4	81.0%
2252		6	1	83.3%	104	9	91.3%	6	3	50.0%	102	31	69.6%
2254		6	2	66.7%	39	2	94.9%	6	4	33.3%	39	12	69.2%
2255		7	0	100.0%	106	11	89.6%	7	4	42.9%	105	50	52.4%
2258		7	0	100.0%	42	9	78.6%	7	6	14.3%	41	18	56.1%
2259	25	7	1	85.7%	62	24	61.3%	7	5	28.6%	61	30	50.8%
2260		7	1	85.7%	7	1	85.7%	7	6	14.3%	7	6	14.3%
2265	17	7	0	100.0%	43	3	93.0%	7	7	0.0%	42	27	35.7%
2267	42	5	2	60.0%	5	2	60.0%	4	4	0.0%	4	4	0.0%
2271		6	2	66.7%	89	11	87.6%	6	4	33.3%	88	46	47.7%
2290		2	2	0.0%	35	9	74.3%	2	0	100.0%	34	7	79.4%
2293		6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Region: ALL

Service: ALL

Arriving On: 7/19/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2213	WAS	27	CTI	24	CTI	9	BWI-XNY	AM	Follow, Marc, 9485, Milepost, 106.3, 134.6
2218	NYP	67	CAR	71	CAR	38	BAL-BAL	AM	Door, ENTIRE TRAIN, DOOR ISSUES.
2222	NYP	18	CTI	9	CTI	9	NWK-NYP	AM	Follow, NJ, 8898, Other, SECAUCUS CONGESTION A/C FIFA GAME TRAVEL
2259	WAS	25	MBO	11	MBO	11	XGX-NHV	AM	For maritime traffic, Bridge, SHAWS COVE
2265	WAS	17	OTH	16	DSR	11	NHV-STM	MN	Per bulletin Control Point, 273/234, 30, 1/2
2267	WAS	42	ENG	21	ENG	21	BOS-BOS	AM	Other electrical failure, 2022 LH LP, LOST POWER AND BACK TO BOS
65	NPN	43	WTR	70	WTR	58	FBG-ASD	CS	Trees down Stopped by a tree collision, troubleshoot the engine, and proceeded., Milepost, 24.8, 24.8
87	NFK	79	ENG	51	ENG	51	WAS-WAS	AM	Other electrical failure, XXXXX, LATE DSLS FROM PIT DUE TO HIGH SHOP COUNT. NEC'Y TO USE 80'S DSL WHICH AR WAS 538P
121	WAS	27	PTI	15	MTI	14	WIL-XPV	AM	Disabled train ahead, Control Point, ., Held at Bacon a/c Amtrak 155 stopped on No.3 trk with Pantograph issues
128	NYP	46	DCS	33	DCS	27	WIL-PHL	AM	T.O.L, Control Point, HOOK, FOLLOWED 124 ON NO. 1 TRK. TOL ON NO. 3 TRK BETWEEN PHIL AND PENN
140	SPG	17	DSR	14	PTI	14	WND-WNL	AM	Meet, 497, Milepost w/Letters, WND, WNL, AM140 waited for AM497 to clear single track
143	WAS	50	MTI	43	MTI	43	WIL-XPV	AM	Disabled train ahead, Control Point, Perry, Opr No.1 trk a/c Amtrak 155 stopped on No.3 trk with Pantograph issues
145	RNK	39	DCS	30	DCS	27	CVS-LYH	NS	Restrictive signal(s) from known wayside signal failure Hamner, Control Point, Hamner
155	NFK	100	ENG	84	ENG	82	XPV-BAL	AM	HEP, 629 EX ES, Stopped No.3 track in Perry int with broken carbon strip alarm, pantograph dropped.
161	WAS	28	DBB	12	DBB	12	NYP-NWK	AM	Malfunction of platform structure at Amtrak station, Other, SECAUCUS, ENGR REPORTED STOPPED ON NO.3 TRACK FOR REROUTE DUE TO RUBRAIL FOULING TRACK
189	WAS	20	OTH	10	DCS	4	PHL-WIL	AM	T.O.L, Control Point, PHIL TO PENN, TOL ON NO. 3 TRK BETWEEN PHIL AND PENN; RESTRICTIVE SIGNALS
195	WAS	18	SMW	13	PTI	12	PHL-WIL	AM	Follow, 2255, Control Point, .

Amtrak Endpoint OTP Details

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/19/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
450	SPG	33	POL	21	POL	21	HFD-HFD	AM	Right of Way police hold, wnd pd	
80	NYP	37	HLD	41	HLD	27	GRO-GRO	NS	Passenger and/or baggage Had to wait for transfer passengers from train 20	
615	HAR	30	DCS	33	DCS	33	PHL-PHL	AM	Power switch failure, Control Point, PENN, 79 SW FAILED AT PENN; HAD TO SHIFT AROUND IT AND BE REROUTED TO HEAD WEST	
20	NYP	63	FTI	212	FTI	118	MEI-TCL	NS	NS 344 had engine problems and had to get power brought to them. After power was hooked up we followed them from McGregor to Eutaw NS 344, Milepost, 266.9, 232.5	
63	TWO	27	HLD	5	SYS	5	SYR-SYR	CS	Re-crew / job briefing	
235	ALB	24	RTE	14	RTE	9	RHI-HUD	AM	Dispatcher hold Control Point, 114	
238	NYP	22	CTI	28	CTI	28	POU-CRT	MN	Follow Followed a MN train, then at 34 they had a disabled train and they were doing train to train transfer at station, waited outside at 34 for then to finish up, MN, Milepost, 53, 34	
283	NFL	28	SVS	55	SVS	55	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING	
290	NYP	28	CTI	30	CTI	30	POU-CRT	MN	Follow metro, 8848, Milepost, 72, 39	
291	BTN	19	DCS	14	PTI	11	NYP-XSD	AM	Follow, AM283 , Other, NYP XSD	
1233	PIT	38	FTI	24	FTI	24	ALB-XRD	CS	Cross over or go around 427, Control Point, 187	
448	BOS	194	WTR	184	WTR	184	SPG-WOR	CS	Trees down Milepost, 76.9, 76.9	
73	CLT	13	TCC	13	ADA	5	CYN-CYN	NS	Mobility Impaired 2 wheelchair lifts	
74	RGH	15	FTI	12	FTI	12	CLT-KAN	NS	Meet #NS28N, Control Point, shamrock	
76	RGH	21	WTR	10	WTR	10	GRO-DNC	NS	Flash flood warning Milepost w/Letters, 16.0NC, 25.4NC	
77	CLT	18	PTI	19	PTI	19	DNC-BNC	NS	Meet Amt 74, Milepost, 25.5, 23.5	
89	SAV	46	WTR	63	WTR	19	PTB-RMT	CS	High winds Milepost, 22.0, 54.0	
97	MIA	37	WTR	58	DCS	31	XSE-FAY	CS	Wayside detector failure including false actuation Hotbox malfunction at Benson dd 30 mph from A 181 to A200.5, Milepost w/Letters, A181, A200.5	
98	NYP	66	PTI	72	PTI	34	FAY-XSE	CS	Cross over or go around EC1 and wait for 97 (hotbox issue), 97, Control Point, south beard	
41	MIA	485	ENG	157	ENG	105	XFI-COV	CS	Loading problem 46	

Amtrak Endpoint OTP Details

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/19/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
23	NOL	33	FTI	53	FTI	26	BAS-XNO	NS	Cross Traffic unknown, Control Point, 802	
24	MOE	73	FTI	129	FTI	63	PAG-MOE	CS	Follow 606, Milepost w/Letters, pay, moe	
25	NOL	39	FTI	44	FTI	37	BAS-XNO	CS	Meet 60219, UNK, Siding, Claiborne, Control Point, N. Gentilly	
724	SAC	13	DCS	16	DCS	13	HAY-OAC	UP	Restrictive signal(s) from unknown cause Signal went dark causing PTC emergency break application. Inspected train, performed class II , highball, runner, Dark signal , Milepost, 16.7, 16.7	
732	SAC	64	TEN	61	TEN	61	EMY-EMY	UP	Set out defective locomotive Late release from yard. CDTX 2004 swapped for 2001 and JPBX 921. 921 rear railing bent by switching incident and was touching the car coupled behind it. Also, during inspection, 2001 did not lose load when doors were opened train line. 921 was set out, JPBX921, C2004	
734	SAC	11	PTI	31	PTI	7	OKJ-EMY	UP	Follow 732, Control Point, NI905	
50	NYP	No OS Rpt	FTI	177	FTI	110	LAF-CRF	CS	Follow m639, Milepost, 120, 147.4	
506	SEA	20	FTI	21	FTI	18	KEL-CTL	BN	Follow bnsf 6910, Milepost, 74.3, 58.7	
507	EUG	18	PTI	15	PTI	15	PDX-ORC	UP	Meet Amtk 508, Siding, Clackamas	
518	VAC	32	DSR	19	FTI	17	EDM-EVR	BN	Meet BN6077, Control Point, Howarth Park	
59	NOL	148	MBO	123	MBO	123	HMD-XSU	CC	Signal and rail down errors at Mancha bridge Bridge, Mancha	
11	LAX	114	TRS	120	TRS	116	CMO-KFS	UP	Vehicle strike Other, mp 502	
7	SEA	98	WTR	204	WTR	119	HAV-SBY	BN	Heat order Other, high line sub	
8	CHI	86	FTI	131	WTR	54	HAV-MAL	BN	Heat order 40mph from havre to WPT, Milepost, 990, 227	
27	PDX	-13	FTI	56	FTI	31	PSC-WIH	BN	Follow BNSF 6787, Siding, BERRIAN, Siding, Patterson	
28	SPK	73	FTI	104	FTI	62	WIH-PSC	BN	Freight train broke down bnsf 6787, Siding, maryhill	
821	FTW	30	DSR	29	DSR	25	GLE-FTW	BN	Per bulletin Milepost, 408.0, 407.7, 30, mt, Milepost, 407.4, 407.0, 30, mt, Milepost, 405.8, 405.6, 30, mt, Milepost, 405.3, 404.9, 50, mt, Milepost, 401.0, 400.2, 25, mt, Milepost, 397.5, 397.3, 50, mt, Milepost, 396.3, 396.2, 30, mt, Milepost, 396.0, 395.9, 50, mt, Milepost, 393.6, 393.5, 50, mt,	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Region: ALL

Service: ALL

Arriving On: 7/19/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	23	DSR	42	DSR	19	FTW-GLE	BN	Per MW foreman Milepost, 350.7, 351.1, 50, m1, Milepost, 354, 354.5, 70, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 360.6, 361.1, 60, m1, Milepost, 369.5, 396.9, 50, m, Milepost, 371, 371.5, 50, m, Milepost, 374, 374.1, 60, m, Milepost, 377.5, 378.3, 75, m, Milepost, 379.5, 380, 60, m, Milepost,
331	MKE	27	CTI	23	CTI	16	XWA-GLN	ME	Follow METRA, 2601, Control Point, XWA
350	PNT	16	DCS	27	DCS	27	DOA-KAL	AM	Issue with automatic road crossing protection 144.08 West Main St. 143.75 West Nedge Ave. 143.60 N Park St. 143.55 Church St., Other, crossings
364	PTH	39	FTI	40	FTI	35	BTL-LNS	CC	Follow Stop at Emmett 15 min following on Approach signals, CN eng 3227, Control Point, Emmett, Control Point, Lacey
365	CHI	25	SYS	30	SYS	30	BTL-BTL	CC	PTC- IETMS incorrect consist Had to call and update the consist then throw the breaker with mechanical then add everything back in and do a departure test twice because it timed out and then we departed, Other, btl
584	SAN	27	CTI	24	CTI	18	SNC-SNP	SC	Meet mtlk, Control Point, Serra
587	LAX	46	TRS	26	TRS	26	IRV-IRV	SC	Vehicle strike Held at IRV station for metrolink vehicle strike ahead., Milepost, 176, 176
593	LAX	17	DSR	14	DSR	12	IRV-SNA	SC	Per dispatcher (radio/phone) 2x procedure 1 @ McFadden ave. & ritchey st., Milepost, 176.87, 176.75, 15, 1
595	LAX	30	PTI	17	PTI	15	OSD-X98	SN	Meet 790, Control Point, songs
770	SAN	31	CTI	31	CTI	11	OSD-SOL	SN	Follow NCTD, 678, Control Point, ponto
786	SAN	76	ENG	56	ENG	56	CML-XMR	UP	Failure of diesel engine Were able to reset and restart with assistance from Mechanical desk and Siemens, C2121
790	SAN	25	PTI	36	PTI	19	IRV-SNC	SC	Meet 593, Control Point, trabucco
703	MCD	50	TSV	24	TSV	24	BFD-BFD	BN	Fuel
704	BFD	61	ITI	71	ITI	71	MCD-MCD	BN	Service, turn, or wye train 719, Late arriving train set from 719
710	BFD	58	CON	72	CON	72	MCD-MCD	BN	Hold for connecting train Held for bus #4310 with crew for AMTK 710(19) on board, 4310
712	BFD	19							
714	BFD	74	CON	27	CON	27	MCD-MCD	BN	Hold for thruway bus

Amtrak Endpoint OTP Details

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/19/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
716	BFD	83	CON	104	CON	104	MCD-MCD	BN	Hold for bus with passengers from train
717	MCD	43	DCS	32	DCS	32	HNF-FNO	BN	Restrictive signal(s) from unknown cause Stop, Restricting , Other, shirley to conejo
719	MCD	80	POL	70	POL	64	BFD-BFD	BN	Right of Way police hold Container train on MT2 stopped being robbed/pilfered so we had to wait for amtk 712 to arrive before we could depart.
4	CHI	No OS Rpt	WTR	812	WTR	683	BAR-NDL	BN	Flood / washout Held here for the washout at the Needles, Control Point, Ibis
21	SAS	35	FTI	231	FTI	108	TAY-AUS	UP	Cross over or go around up6445, up7800, Siding, Sneed
301	STL	17	PTI	32	PTI	32	BNL-SPI	UP	Meet Dispatcher hold, amt 22, Control Point, x182
381	QCY	24	CAR	19	CAR	19	CHI-CHI	AM	Door 4315, Door on B end of cafe car 4315 would not close. After troubleshooting with mechanical, used door bypass on engine to depart.
390	CHI	37	ENG	23	ENG	23	EFG-EFG	CC	Engine fault code 0960 high coolant temp By CNOC mechanical direction evaluate coolant level via sight glass Worked with Siemens and CNOC to find sight glass. CNOC direction to continue with watching coolant levels during operation. ID4621
391	CDL	36	DSR	22	FTI	11	CHM-MAT	CC	Meet Wait in Humboldt for CN407 to pass northbound, CN 407, Siding, humboldt
311	KCY	46	FTI	48	FTI	16	WAR-LEE	UP	Follow UP 5323, Siding, Strasburg
318	CHI	61	FTI	43	PTI	25	PON-DWT	UP	Meet Amtrak 305, Siding, O Dell
319	KCY	50	FTI	35	FTI	18	WAH-HEM	UP	Meet up 8792, Control Point, berger

Amtrak Initial Terminal Details

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/19/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	67	07/19	140	140	Other electrical failure, 96 DX BD, AM67 e/96 was removed, set will not take power still in SHSY. Mech currently trouble shooting. Further delayed.
BOS	2267	07/19	21	21	Other electrical failure, 2022 LH LP, LOST POWER AND BACK TO BOS
BOS	2271	07/19	45	45	HEP, 2012 LH LP, AM2252eq turn of AM2271 ar in BOS with HEP issues. HSR insp and rpts no exceptions. AM2271 rpts HEP shut down and doors are closed
BOS	2293	07/19	12	12	HEP, 2012 LH LP, AM2293 dp BOS 12" late a/c HEP issues being fixed by HSR
BRK	694	07/19	1	1	Conductor radio not working for new DTMFcode. Control Point, brk
HAR	670	07/19	1	1	Wait for scheduled departure time
HAR	674	07/19	2	2	Re-crew / job briefing, ENGR ESTABLISHING COMMS WITH CNDR
MIA	98	07/19	6	6	Parking break not showing released 343
NHV	450	07/19	9	9	Service, turn, or wye train, 405
NYP	19	07/19	41	41	Water, commissary, toilet/trash dumping, DLYD DUE TO LATE RELEASE FROM CATERING
NYP	97	07/19	129	129	Water, commissary, toilet/trash dumping, AM97 will be delayed out of SSYD due to late servicing
NYP	105	07/19	1	1	Wait for scheduled departure time, DEPARTED ON TIME
NYP	121	07/19	3	3	Passenger and/or baggage, BOARDING
NYP	235	07/19	5	5	Service, turn, or wye train, 284
NYP	281	07/19	2	2	Passenger and/or baggage, BOARDING
NYP	283	07/19	55	55	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	637	07/19	2	2	Scheduled in track usage program, Other, NYP-NYP, DELAYED DEPARTURE DUE TO SINGLE TRACKING IN THE SOUTH TUBE A/C THE NORTH TUBE O/O/S.
NYP	667	07/19	6	6	High passenger count
NYP	2233	07/19	8	8	Other electrical failure, 2141 NG NP, POSSIBLE PAPERWORK ISSUE
NYP	2290	07/19	4	4	Passenger and/or baggage, BOARDING
PHL	117	07/19	1	1	Wait for scheduled departure time
PHL	150	07/19	1	1	Wait for scheduled departure time
PHL	615	07/19	33	33	Power switch failure, Control Point, PENN, 79 SW FAILED AT PENN; HAD TO SHIFT AROUND IT AND BE REROUTED TO HEAD WEST
PIT	1246	07/19	35	35	Cross over or go around 427, Control Point, 187
WAS	122	07/19	6	6	Electrical failure, XXX, MECHANICAL SERVICING TRAIN

Amtrak Initial Terminal Details

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/19/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2218	07/19	33	33	Air / Brake / Wheel, XXX, SHOPPED ORIGINAL TRAINSET FOR TRUCK HUNTING
WAS	2260	07/19	13	13	Air / Brake, 2122 NG NP, 2129 NG NP, 2129 NG NP, WHEEL SLIP ISSUES
CHI	59	07/19	2	2	Toilet 34090
CHI	319	07/19	12	12	Door ID4121, Steps wouldn't retract car #4121
CHI	331	07/19	11	11	Dispatch verified incorrect DOB. Had to obtain correct DOB and verify. Incorrect DOB, Control Point, TRK 19
CHI	381	07/19	19	19	Door 4315, Door on B end of cafe car 4315 would not close. After troubleshooting with mechanical, used door bypass on engine to depart.
MKE	334	07/19	11	11	Service, turn, or wye train 331
BFD	703	07/19	24	24	Fuel
BFD	719	07/19	64	64	Right of Way police hold Container train on MT2 stopped being robbed/pilfered so we had to wait for amtk 712 to arrive before we could depart.
GTA	782	07/19	10	10	Meet 14, Control Point, CO 358
LAX	566	07/19	1	1	Door C6952, When boarding, pax knocked door out of track
MCD	704	07/19	71	71	Service, turn, or wye train 719, Late arriving train set from 719
MCD	710	07/19	72	72	Hold for connecting train Held for bus #4310 with crew for AMTK 710(19) on board, 4310
MCD	712	07/19	24		
MCD	714	07/19	27	27	Hold for thruway bus
MCD	716	07/19	104	104	Hold for bus with passengers from train
MCD	718	07/19	53	53	Service, turn, or wye train 703
OKJ	732	07/19	(Trn Cxld)		Third Party Engine Failure
SAC	745	07/19	1		
SEA	8	07/19	18	18	Water, commissary, toilet/trash dumping

Eastern Region

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	98.4	94.8	166	0
CDOT	95.0	93.8	84.6	92.4	16	1
MARC	95.0	100.0	79.4	90.2	12	0
SEPTA	95.0	96.0	95.0	91.5	101	4
NJT-NED	95.0	91.2	91.4	88.6	192	17
NJT-SED	95.0	95.8	95.6	97.2	24	1

Operating Highlights

Train 40(18) - South of Connellsville, PA - Freight Train Interference

20JUL26: Train 40(18) was delayed on the CSX Keystone Subdivision at MP 252.2 due to meeting/following CSX Train 421-19.

Train	Delay	Comment
40(18)	47"	

Train 98(19) - North Charleston, SC - Freight Train Interference

20JUL26: Train 98(19) was delayed on the CSX Charleston Subdivision at MP 388.7 due to meeting CSX Train I138-19.

Train	Delay	Comment
98(19)	38"	

Train 448(18) - East of Springfield, MA - Weather

19JUL26: Train 448(18) with E/107 and E/127, plus four cars, carrying 96 passengers, struck a tree near MP 76.9 on the CSX Boston QB Subdivision. The tree was lodged underneath the lead engine. HEP remained up. CSX dispatched MW personnel to assist with the tree removal. There was an extended delay for the arrival of CSX MW personnel.

Train	Delay	Comment
448(18)	3'08"	

Train 67(19) - Boston, MA - Engine Failure

19JUL26: Train 67(19) was delayed at its initial terminal at Boston South Station due to E/96, which was originally added to the consist for movement to Washington, DC, being mechanically condemned. After the E/96 was removed the E639 and E/612 would not take power. Southampton Yard Mechanical responded and ultimately rectified the issue.

Train	Delay	Comment
67(19)	2'20"	

Train 290(19) South of Poughkeepsie, NY - Commuter Train Interference

19JUL26: Train 290(19) with E/700 and 6 cars was delayed 304 minutes on board due to following MNRR 8848 from MP 72 to MP 39.

Train	Delay	Comment
290(19)	30"	

Train 2271(19) Boston, MA - Engine Failure

19JUL26: Train 2271(19) was delayed departing Boston due to short turning off 2254(19) this was due to set 16 being shopped for HEP issues. Set 16 was sent to the yard for repairs to come back out as 2293(19).

Train	Delay	Comment
2271(19)	45"	
2293(19)	12"	

Train 40(18) North of Petersburg, VA - Freight Train Interference

19JUL26: Train 40(18) with E/335, E/139 and 13 cars was delayed on the CSX RF&P subdivision at MP 1.2 due to being stopped and crossing over to go around the CSX IO31.

Train	Delay	Comment
40(18)	35"	

Train 2260(19) - Washington, DC - Short Turn Equipment/Engine Failure

19JUL26: Next Gen Train 2260(19) was delayed departing Washington due to short turning off inbound 2255(19). This was caused by Next Gen set 21 being shopped for truck hunting upon arrival off 2213(19). This also caused train 2218(19) to come off the S&I.

Train 2218(19) was further delayed at Baltimore due to having door problems. The doors were closed but the power car was giving door open faults. The crew was working on recycling the engine.

Train	Delay	Comment
2260(19)	13"	
2218(19)	33"	
2218(19)	38"	BAL

Train 615(19) Philadelphia, PA - Signal

19JUL26: Train 615(19) was delayed departing Philadelphia due to the 79SW failing to reverse. It was necessary for the train to be shifted north then south. Maintainer was enroute to the switch. As of 259P-ET the Maintainer was on scene.

Train	Delay	Comment
615(19)	33"	

Several Trains Delayed - New York, NY - Servicing

19JUL26: Several trains were delayed departing New York due to the late release from the yard due to catering and late turn of equipment.

Train	Delay	Comment
283(19)	55"	
10(19)	41"	

Train 155(19) South of Newark, DE - Engine Failure

19JUL26: At 1131A-ET, Train 155(19) with E/620 and 9 cars with 529 customers onboard was delayed on the Philadelphia to Washington at MP 59.3 due to having a broken pantograph alarm. The crew inspected the pantograph and found a chip in the carbon strip. The crew attempted to reconfigure the pantograph but could not get the front pantograph to raise and did not have HEP. After troubleshooting with CNOC Mechanical they were attempted a hard reset to restore the HEP but the front pantograph would not raise.

Train 154(19) was inspecting catenary from Perry Interlocking to Wilmington station at normal speed. CETC sent ET A -man out to the scene and started transferring passengers to trains 143(19). Mechanical tech was on train 88(19) and met the train in Perryville. Amtrak Police were sending Officers to Perryville. The crew did raise the bad pantograph to restore HEP for the customers. Rescue engine 637 was being readied in Philadelphia to couple to the equipment.

Train	Delay	Comment
155(19)	1'23"	
88(19)	06"	DROPPING OFF TECH
143(19)	43"	

CSX Heat Orders - Weather

19JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions North End, Peninsula, Richmond Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
53(19)	13"	
98(19)	19"	
40(19)	57"	
89(19)	20"	
52(19)	31"	
128(19)	06"	
155(19)	18"	
79(19)	18"	
124(19)	12"	
90(19)	22"	
80(19)	27"	
41(18)	10"	
97(18)	29"	

Train 19(18) South of Gainesville, GA - Freight Train Interference

19JUL26: Train 19(18) with E/163, E/372 and 9 cars with 175 customers onboard was delayed on the NS Greenville district due to meeting a freight at CP Arcadia and then following NS 154 to CP Lenox.

Train	Delay	Comment
19(18)	1'04"	

Train 65(18) South of Fredericksburg, VA - Debris

19JUL26: Train 65(18) 26-FOI-00603E/00000008326 5 "UNCLASSIFIED" 2247/21/2026 customers onboard reported that they struck a tree at MP 24.8 on the CSX RF&P subdivision. The crew was trouble shooting with CNOC Mechanical due to the engine shutting down. Amtrak Road Foreman's were enroute. The train was without HEP as 846A-ET. There was no injuries reported to the customers or crew. It was 83 degrees and partly sunny. After speaking with mechanical the crew was able to get the engine back up and running with HEP and reported exterior damage.

Train	Delay	Comment
65(18)	58"	

Maintenance of Way Highlights

26-FOI-00603 00000008325 "UNCLASSIFIED" 7/21/2026

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Train 26-F01-00803 delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

26-F01-00803 00000008325 UNCLASSIFIED 7/21/2026

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008325 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FBI-00893 a 00000008325 in "UNCLASSIFIED" open 7/21/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Train 21/421(19) South of Walnut Ridge, AR - Passenger Train Interference

20JUL26: Train 21/421(19), with 162 customers onboard, was delayed at Tuckerman/MP251.8, 27 miles south of Walnut Ridge, AR/MP224.9, on the UP Hoxie subdivision meeting Amtrak train 22(19)/422(17). Once the route was clear, train 21/421(19) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(19)	44"	

Train 1(18)/421(17) West of Tucson, AZ - Freight Train Interference

19JUL26: Train 1(18)/421(17), with 181 customers onboard, was delayed at Stockham siding/MP977.8, 14 miles west of Tucson, AZ/MP983.9, on the UP Gila subdivision meeting UP freight UP/7928. Once the route was clear, train 1(18)/421(17) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(18)/421(17)	37"	

Train 718(19) Merced, CA - Initial Terminal Delay

20JUL26: Train 718(19) was delayed departing Merced, CA Station due to the late arrival and turn of inbound Train 703(19). Train 703(19) was initially delayed departing Bakersfield, CA Station while awaiting a fuel truck to service the locomotive. En route, the train incurred additional delays meeting multiple freight trains between Bakersfield and Wasco at Gomez, Shafter, and Kit Fox Sidings. The train also held for a meet with Amtrak Train 716(19) at Calwa prior to arrival.

The cumulative delays resulted in Train 703(19) arriving 50" late into Merced, which subsequently delayed the departure of Train 718(19). Once the equipment was turned and prepared for service, Train 718(19) continued its trip without further incident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(19)	53"	late turn off 703(19)
703(19)	19"	BFD-WAC frt meets
703(19)	24"	BFD fueling
703(19)	09"	716 meet

Train 3(18) East of Flagstaff, AZ - Freight Train Interference

19JUL26: Train 3(18), carrying 226 customers onboard, was delayed east of Flagstaff, AZ, while holding at West Canyon Diablo (MP 311.7) on the BNSF Seligman Subdivision due to freight traffic congestion. A Q-train ahead was stopped to conduct an inspection following a detector integrity failure, resulting in multiple freight movements, including trains led by BNSF 6556, BNSF 6513, and BNSF 4360, occupying the territory. As a result, Train 3(18) was required to hold for the freight activity and associated meets before continuing westward.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(18)	56"	

Train 22(19)/422(17) South of Hope, AR - Debris Strike

19JUL26: Train 22(19)/422(17) engine 2215 and 1452, 9 cars, and 201 customers onboard, struck debris on the rail at mile post 468.0, 10 miles south of Hope, AR/MP457.8, on the UP Little Rock subdivision. No injuries were reported by the customers or crew. No damage was reported to the equipment. The crew reported problems restoring air pressure. Once the air pressure was restored and a brake test was completed, train 22(19)/422(17) continued north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(19)/422(17)	28"	

Train 14(19) North of Paso Robles, CA - Trespasser Incident

19JUL26: Train 14(19), carrying 269 customers onboard, was delayed approximately 48 miles north of Paso Robles, CA, at MP 165.6 on the Union Pacific Coast Subdivision due to a vehicle stopped on a grade crossing ahead. Rail traffic was halted after reports indicated the vehicle owner was experiencing a personal crisis, requiring intervention by responding authorities. The vehicle owner was safely assisted and ultimately moved the vehicle clear of the crossing. Once authorities completed their response and RMCC released the track for service, Train 14(19) resumed its northbound trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(19)	1'05"	

Train 364(19) East of Battle Creek, MI - Freight Train Interference

19JUL26: Train 364(19), with 315 customers onboard, was delayed between Emmett Street/MP178.6 and Lacey/MP191.7, beginning 3 miles east of Battle Creek, MI/MP175.7, on the CN Flint subdivision following CN freight CN/3227. Once the route was clear, train 364(19) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(19)	35"	

Train 6(19) Winnemucca, NV - Heat Orders

19JUL26: Train 6(19), carrying 155 customers onboard, was delayed while operating across the Union Pacific Nevada and Elko Subdivisions due to heat-related speed restrictions. The train operated at reduced speeds on the Nevada Subdivision from approximately MP 249 through Winnemucca, NV (MP 417.4) under heat order conditions. Additional delay was incurred east of Winnemucca on the Union Pacific Elko Subdivision, where the train continued to operate at reduced speeds between MP 536.7 and MP 612.1 due to the same heat restrictions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(19)	57"	RNO-WNN
6(19)	30"	WNN-XW6

Train 307(19) South of Chicago, IL - Freight Train Interference

19JUL26: Train 307(19), with 264 customers onboard, was delayed at Lumber Street/MP1.4, 1.4 miles south of Chicago Union Station, IL/MP0.0, on the Amtrak Chicago Subdivision meeting disabled NS freight 33G. The freight had gone into emergency. Once the issue was resolved, NS freight 33G pulled into the clear and train 307(19) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
307(19)	41"	

Train 786(19) South of Camarillo, CA - Engine Failure

19JUL26: Train 786(19) was delayed at approximately 419.5 miles south of Camarillo, CA, with CC-06954, five locomotive E/C2121, and 306 customers onboard, was delayed south of Camarillo, CA, at approximately MP 419.5 on the Union Pacific Santa Barbara Subdivision after the locomotive shut down, resulting in a loss of head-end power (HEP). The crew coordinated with the Mechanical Desk to troubleshoot the issue while the train remained stopped. The locomotive was successfully restarted, restoring both tractive effort and HEP after 25 minutes. With outside temperatures reported at approximately 88°F, the crew ensured all systems were functioning properly before resuming operation. Once restored, Train 786(19) continued its trip without further incident.

Train	Delay	Comment
786(19)	56"	

Train 719(19) Bakersfield, CA - Police Related

19JUL26: Train 719(19) was delayed departing Bakersfield, CA Station with 133 customers on the BNSF Mojave Subdivision due to law enforcement activity involving container trains in the area. A container train on Main Track 2 was stopped while authorities investigated reports of theft and trespassing activity, requiring Train 719(19) to hold until Train 712(19) arrived and routing could be established. Additional delay was incurred due to a second right-of-way police hold involving another container train on Main Track 1 near Uña. Train 719(19) was required to operate at restricted speed while passing the law enforcement activity.

Train 704(19) was delayed departing Merced, CA turning from the late inbound 719(19).

Train	Delay	Comment
719(19)	1'10"	
704(19)	1'11"	late turn

Train 25(19) South of Bay Saint Louis, MS - Freight Train Interference

19JUL26: Train 25(19), with 125 customers onboard, was delayed between Claiborne siding/MP768.1 and North Gentilly/MP799.2, beginning 14 miles south of Bay Saint Louis, MS/MP754.48, on the CSX N.O.&M. subdivision following freight 60219. Once the freight was clear of the route, train 25(19) continued south.

Train	Delay	Comment
25(19)	37"	

Train 21(18) North of Austin, TX - Freight Train Interference

19JUL26: Train 21(18), with 114 customers onboard, was delayed at Sneed siding/MP174.0, 5 miles north of Austin, TX/MP179.4, on the UP Austin subdivision meeting disabled freight UP/6445. The freight crew repaired a broken knuckle and could not couple the freight cars. UP freight UP/7800 stopped behind UP/6445 and attempted to push the train back together but engine issues caused additional delay. Once the UP freights pulled into the clear, train 21(18) departed Sneed and continued south into Austin Station, TX.

Train	Delay	Comment
21(18)	1'48"	

Train 14(19) South of Paso Robles, CA - Passenger Train Interference

19JUL26: Train 14(19), carrying 260 customers onboard, was delayed south of Paso Robles, CA Station, while holding at Templeton Siding (MP 217.7) on the Union Pacific Coast Subdivision to meet Amtrak Train 11(18).

Train	Delay	Comment
14(19)	57"	

Train 717(19) West of Hanford, CA - Signal

19JUL26: Train 717(19), carrying 131 customers onboard, was delayed while operating between Hanford, CA and Fresno, CA on the BNSF Bakersfield Subdivision due to signal issues between Shirley (MP 972.4) and Conejo (MP 983.1). The train was required to operate at restricted speed through the affected territory.

As a result of the same signal issues, Train 714(19), carrying 70 customers onboard, was delayed while holding at Figarden (MP 1004.4) on the BNSF Stockton Subdivision awaiting the arrival of Train 717(19). Afterward, Train 714(19) was also required to operate at restricted speed through the affected signal territory before continuing its trip.

Train	Delay	Comment
714(19)	24"	holding Figarden
714(19)	25"	signals
717(19)	32"	signals

Train 19(18) South of Meridian, MS - Routing

19JUL26: Train 19(18), with 132 customers onboard, was delayed at 27 Avenue/MP295.4, 0.4 miles south of Meridian Station, on the NS AGS South subdivision due to a switch issue at Flintco. Crew hand-lined the switch and continued south.

Train	Delay	Comment
19(18)	34"	

Train 7/27(18) East of Havre, MT - Freight Train Interference

19JUL26: Train 7/27(18), carrying 235 customers onboard, was delayed while operating between Malta, MT and Havre, MT on the BNSF Milk River Subdivision due to freight train interference. The train was required to follow BNSF 6417 from Lohman (MP 416.2) through Havre Station (MP 430.3), resulting in reduced speeds through the territory.

Train	Delay	Comment
7/27(18)	31"	

Train 786(19) North of Lompoc-Surf, CA - Passenger Train Interference

19JUL26: Train 786(19), carrying 119 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.6) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(19) & 14(19).

Train	Delay	Comment
786(19)	34"	

Train 27(17) West of Pasco, WA - Freight Train Interference

19JUL26: Train 27(17) with 125 customers was delayed 31 minutes west of Pasco, WA on the BNSF Fallbridge subdivision due to freight interference. Train 27(17) followed BNSF 6787 from Berrian siding at MP203.9 to Patterson siding at MP179.1.

Train	Delay	Comment
27(17)	31"	

Train 59(18) South of Hammond, LA - Drawbridge Opening

19JUL26: Train 59(18) with 165 customers was delayed on the CN McComb subdivision 15 miles south of Hammond due to the Manchac Bridge not properly seated. Once repairs were completed, train 59(18) continued south.

WBS#: B.TR.100150.6905

Train	Delay	Comment
59(18)	2'03"	

Train 732(19) Oakland, CA - Third Party Contractor Engine Failure

19JUL26: Train 732(19), led by locomotive C2001 with JPBX921 trailing and carrying 83 downline customers, was delayed departing Oakland, CA on the Union Pacific Niles Subdivision following a late release from the Oakland Maintenance Facility. The initial delay was caused by a handrail defect on JPBX921 that required corrective repairs. During the repair process, JPBX921 also developed door light issues, and a decision was made to remove the unit from the consist. The additional troubleshooting and car removal extended the delay, resulting in the train originating from Emeryville, CA rather than Oakland.

The late operation also impacted connecting transportation. Bus 4316, which was providing substitute transportation between Martinez and Merced due to scheduled track work, held at Martinez for the late arrival of Train 732(19). As a result, Train 716(19) experienced a delayed initial departure from Merced, CA while awaiting connecting customers.

Train	Delay	Comment
734(19)	29"	following 732(19)
716(19)	1'44"	waiting for bus
732(19)	1'01"	Orig EMY

Train 2(17) West of Lake Charles, LA - Signal Issues

19JUL26: Train 2(17), with 117 customers onboard, was delayed between mile post 223.0 and mile post 218.0, beginning 4 miles west of Lake Charles, LA/MP218.9, on the UP Lafayette subdivision due to signal issues. Train 2(17) was flagged across signals 223, 221, and 220. Train 2(17) was ordered to inspect rail conditions at the CPKCS interlocking at mile post 222.8 and the signal at mile post 218.0. Once through the affected area, train 2(17) continued east.

Train	Delay	Comment
2(17)	34"	

Train 1(18)/421(17) East of Sanderson, TX - Signal

19JUL26: Train 1(18)/421(17) with 140 customers was delayed on the UPRR Sanderson subdivision six miles east of Sanderson due to switch issues at Fedora/MP 501.1. The crew took the switch in hand and continued to Sanderson.

Train 49/449(18) West of South Bend, IN - Freight Train Interference

19JUL26: Train 49/449(18) with 222 customers was delayed on the NS Chicago district starting 39 miles west of South Bend due to following 29G-18 between CP 469 and CP 479.

Train	Delay	Comment
49/449(18)	33"	

Train 301(19) North of Springfield, IL - Passenger Train Interference

19JUL26: Train 301(19) with 261 customers was delayed on the UPRR Springfield subdivision two miles north of Springfield at Ridgely/MP 183.3 due to meeting train 22(18).

Train	Delay	Comment
301(19)	32"	

Train 19(18) North of Atlanta, GA - Freight Train Interference

19JUL26: Train 19(18) with 175 customers was delayed on the NS Norcross district one mile north of Atlanta at Armour/MP 632.5 due to meeting NS 153-17.

Train	Delay	Comment
19(18)	1'00"	

Train 24(19) East of New Orleans, LA - Freight Train Interference

19JUL26: Train 24(19) with 131 customers was delayed on the CSX NO&M subdivision starting 20 miles east of New Orleans due to following M606 between Chef Menteur Bridge/MP 787.2 and Mobile/MP 666.7.

Train	Delay	Comment
24(19)	2'09"	

Amtrak Michigan Line West of Kalamazoo, MI - Signal

19JUL26: Trains were delayed on the Amtrak Michigan Line just west of Kalamazoo due to the following crossings with gates stuck down in the lowered position: Main Street/MP 144.08, Westnedge Avenue/MP 143.75, North Park Street/MP 143.60, and Church Street/MP 143.55. It was necessary for crews to stop and protect each crossing.

Train	Delay	Comment
351(19)	20"	
350(19)	27"	
365(19)	17"	

Train 3(18) West of Dodge City, KS - Signal

19JUL26: Train 3(18) with 230 customers was delayed on the BNSF La Junta subdivision starting 25 miles west of Dodge City due to signal issues between MP 377.3 and MP 398.2.

Train	Delay	Comment
3(18)	54"	

Train 11(18) South of Chemult, OR - Vehicle Strike

18JUL26: At approximately 0814PM, DFE train 11(18) operating with E/170, E/313, 9 Cars struck a vehicle at MP 502.240 on the UPRR Cascade Subdivision, 1 mile south of Chemult station, in Chemult, OR Klamath county, USFS Road Crossing, DOT# 749018H. There were no reported injuries to the 269 passengers or crew onboard, and no damages to the train. The weather was a reported 75 degrees. The driver of the vehicle was unable to be found and reportedly fled the scene. The Crew requested relief but agreed to take the train to Klamath Falls. Local authorities responded and conducted an investigation of the incident. Once the investigation was complete, train 11(18) was released and continued south. Amtrak Police and EAP advised.

Due to late operation of 11(18), an extra bus was ordered for customers that needed to make connections to train 2/422(19). Those customers were accommodated on American Nation bus operating as special schedule route 5262 Santa Barbara, CA to Ontario, CA.

WBS#: B.TR.100150.6906

National Response Center Number: 1468253

Train	Delay	Comment
11(18)	1'56"	

Washout BNSF Needles Subdivision - Needles, CA

18JUL26: Due to flash flooding on 7/21/2026 BNSF Needles Subdivision, affecting main track No.4 at Needles, CA station/ MP 578.0 on the BNSF Needles Subdivision and main track No.2 at East Needles/ MP 574.6, and multiple freight trains in the area with hours of service issues. Train 4(17) was held at MP 592.6, and Train 3(16) was held at Kingman, AZ station. BNSF worked to shove back a stack train in order to route trains through the area, temporarily through the siding. When freight traffic began to move, damage to main track 1 was found. There was no clear route through the area. BNSF continued to work on clearing a route for the trains. Main track 2 was returned to service at 9:30 AM-MT. Main track one was returned to service at 11:30 AM-MT. Train 3(16) had to hold for freight traffic to clear and then was able advance. The train had to operate at a reduced speed through the area.

Train 4(17) had to be recrewed where it stood and again in Needles. The recrew was transported by van from Train 3(16) to Train 4(17). Another crew was sent in a van from Kingman to Needles. Train 3(16) met a recrew enroute at milepost 648.9. Train 3(16) was on the move after the recrew arrived at 12:34 PM-MT.

Trains 3(16) and 4(17) did not make the station stop in Needles due to no safe way for the passengers to get to the station. All passengers were reaccommodated. Trains 3(17) and 4(18) were scheduled to bypass the stop due to main track 4 remaining closed. BNSF was able to re-open main track 4 at 3:30PM-MT, earlier than planned, and 3(17) and 4(18) were able to make the Needles station stop. Both trains were delayed through the are due to reduced speeds and freight congestion.

Train 4(17) was further delayed at Gallup, NM performing a Calendar day inspection.

Alternate transportation was secured for an on-time portion of Train 4(17) from Kansas City to Chicago. Two buses were able to be confirmed. One bus operated Kansas City to Chicago. The second bus was secured to make stops at Kansas City, LaPlata, Ft. Madison, Galesburg, Princeton, Mendota, Naperville, and Chicago.

WBS#: B.TR.100150.6902

Train	Delay	Comment
3(16)	1'39"	KNG
3(16)	6'14"	KNG-NDL
4(17)	12'03"	BAR-NDL
3(16)	58"	Recrew
4(17)	1'04"	Recrew
3(17)	36"	KNG- Crew Rest
4(17)	1'07"	GLP- Calendar Day
4(18)	33"	congestion KNG-FLG
4(18)	1'49"	NDL-KNG
4(18)	2'00"	

Train 1(18)/421(17) West of Maricopa, AZ - Freight Train Interference

20JUL26: Train 1(18)/421(17), carrying 178 customers onboard, was delayed west of Maricopa, AZ, while holding at Estrella (MP 876.5) on the Union Pacific Gila Subdivision to meet freight train ILBG4-19, led by UP 5932.

Maintenance of Way Highlights

Gold Runner Service Burlington Northern Santa Fe Scheduled M/W Work TWA 26-074

25.FOI.00003 / 0000000325 / "UNCLASSIFIED" 7/2/2026

19JUL26: Burlington Northern Santa Fe Bridge Panel Replacement and Track Maintenance will start at 9:00 AM-PDT with a 24-hr curfew to complete the project. The work will be between Escalon / MP 1191.1 and MP / 1123.9 Modesto, CA station and Stockton, CA Amtrak San Joaquin Station on the Stockton Subdivision. All Gold Runner service will originate and terminate at Merced, CA.

To accommodate the project, the following operating plan will be in effect:

Southbound

- Train 702(19) originated Merced. Customers accommodated on Bus 4302 between Sacramento and Merced.
- Train 710(19) originated Merced. Customers accommodated on Bus 4310 between San Francisco Mission Street and Merced.
- Train 712(19) originated Merced. Customers accommodated on Train 720(19) between Oakland and Martinez, and Bus 4312 between Martinez and Merced.
- Train 714(19) originated Merced. Customers accommodated on Train 724(19) between Oakland and Martinez, and Bus 4314 between Martinez and Merced.
- Train 716(19) originated Merced. Customers accommodated on Train 732(19) between Oakland and Martinez, and Bus 4316 between Martinez and Merced.
- Train 704(19) originated Merced. Customers accommodated on Bus 4304 between Sacramento and Merced.
- Train 718(19) originated Merced. Customers accommodated on Train 738 between Oakland and Martinez, and Bus 4318 between Martinez and Merced.

Northbound

- Train 711(19) terminated at Merced. Customers accommodated on Bus 4311 between Merced and Martinez, and Train 737 between Martinez and Oakland.
- Train 701(19) terminated at Merced. Customers accommodated on Bus 4301 between Merced and Sacramento.
- Train 713(19) terminated at Merced. Customers accommodated on Bus 4313 between Merced and Martinez, and Train 745 between Martinez and Oakland.
- Train 715(19) terminated at Merced. Customers accommodated on Bus 4315 between Merced and Martinez, and Train 747 between Martinez and Oakland.
- Train 717(19) terminated at Merced. Customers accommodated on Bus 4317 between Merced and Martinez, and Train 751 between Martinez and Oakland.
- Train 719(19) terminated at Merced. Customers accommodated on Bus 4319 between Merced and San Francisco Mission Street.
- Train 703(19) operated 30-minutes EARLIER, departing Bakersfield at 5:32pm, and terminated at Merced. Customers accommodated on Bus 4303 between Merced and Sacramento.

All buses will bypass Antioch, CA and Turlock - Denair, CA station with no alternate transportation provided for these two stops.

WBS#: B.TR.100150.6860

Train	Delay	Comment
710(19)	1'12"	Crew on late bus 4310

Wolverine Track Work- Scheduled M/W Work

15JUL26:

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

BNSF Track Work West of Macomb, IL - Carl Sandburg Service TWA 26-073

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th.

14JUL26: Track was extended one additional week, Monday July 20th through Friday July 24th.

To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL), Train 382(13JUL-17JUL) and Train 382(20JUL-24JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL), Train 381(13JUL-17JUL) and Train 381(20JUL-24JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track construction projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 518(19) Passenger injury at Centralia, Washington – Passenger Injury***

19JUL26, Passenger on PNR 85D672, traveling from Portland, OR to Centralia, WA reported that passenger lost balance while detraining on Main Track 2 due to his knee locking as he stepped onto a required step box at the uneven asphalt platform. The Assistant Conductor was able to prevent a more serious fall by assisting the passenger. After briefly remaining seated to regain his bearings, the passenger was assisted to the station people mover by the crew. He declined medical attention and reported only minor scrapes. Amtrak Police was notified

Delay: 518(19)**5"**

Consist Deviations

26-FOI-00603

00000008325

"UNCLASSIFIED"

7/21/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
99 (19)	BOS	99(19) operating with a club-dinette in lieu of a cafe car.	NONE	0	48174
139 (19)	BOS	139(19) will operate with Business Class car 81518 in lieu of a coach.	NONE	0	81518
449 (19)	BOS	Car 62515 (BYD-HVAC) will d/h in line on 449(19) and 448(20). Please reaccommodate all affected passengers	PASSENGERS DOWNGRADED ON 449	30	62515
392 (19)	CDL	short equipment no car; replacement for axle count. Please check all sales and accommodate all passengers affected.	No impact	0	NOCAR
391 (19)	CHI	short equipment no car; replacement for axle count. Please check all sales and accommodate all passengers affected.	No impact	0	NOCAR
448 (20)	CHI	Car 62515 (BYD-HVAC) will d/h in line on 448(20) and 449(19). Please reaccommodate all affected passengers			62515
41 (20)	CHI	Due to a change in equipment it was necessary to perform a schedule change on train 41(20) line 4111. Please utilize the WAR report to ensure all affected passenger have been accommodated			62504
562 (19)	LAX	NO BIKE SERVICE- over capacity	Pax notified	2	90225
580 (19)	LAX	NO BIKE SERVICE- over capacity	pax notified	2	90225
562 (20)	LAX	no bike space or wifi	NONE	0	90225
580 (20)	LAX	no bike space or wifi	NONE	0	90225
280 (19)	NFL	Inbound 281(17) shopped 1 coach with no replacement to run 1 coach short. Please accommodate all passengers who are affected.	Passengers notified	54	NOCAR
86 (20)	NPN	86(20) will operate with a club-dinette in lieu of a cafe car.	NONE	0	48174

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00603 00000008325 "UNCLASSIFIED" 7/21/2026			
189 (19)	NYP	189(19) will operate with Business Class car 81527 in lieu of a coach.	NONE	0	81527
573 (19)	SAN	NO BIKE SERVICE- over capacity	Pax notified	3	90225
591 (19)	SAN	NO BIKE SERVICE- over capacity	Pax notified	3	90225
573 (20)	SAN	no bike space or wifi	NONE	0	90225
591 (20)	SAN	no bike space or wifi	NONE	0	90225
41 (17)	WAS	car will deadhead WAS-MIA- over capacity. 2 emergency windows were pulled.			25050
162 (19)	WAS	Short equipment; business class in lieu of coach. Please accommodate all passengers affected.	Over capacity by 4	4	81518
118 (19)	WAS	short equipment; business class in lieu of coach. Please accommodate all affected passengers.	No impact	0	81527
154 (19)	WAS	short equipment; business class in lieu of coach. Please accommodate all affected passengers.	Over capacity -12	12	81514

Reverse Consists

Train Number	Station	Reason
87 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front
151 (19)	PHL	Consist reversed Business class seat orientation may have changed At Front
150 (19)	PHL	Consist reversed Business class seat orientation may have changed At Front
145 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front
66 (19)	RNK	Consist reversed Business class seat orientation may have changed At Front
135 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front
158 (19)	NFK	Consist reversed Business class seat orientation may have changed At Front
186 (20)	NPN	Consist reversed Business class seat orientation may have changed At

Train Number	Station	Reason	
		26-FOI-00603	00000008325 "UNCLASSIFIED" 7/21/2026
		Front	
138 (20)	NFK	Consist reversed Business class seat orientation may have changed At Front	
178 (20)	RNK	Consist reversed Business class seat orientation may have changed At Front	
149 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front	
122 (19)	WAS	Business class change only Business class seating orientation may have changed At Front	
79 (19)	NYP	Business class change only Business class seating orientation may have changed At Rear	
80 (20)	CLT	Business class change only Business class seating orientation may have changed At Rear	
118 (19)	WAS	Business class change only Business class seating orientation may have changed At Rear	
88 (19)	WAS	Consist reversed Business class seat orientation may have changed At Front	
132 (19)	WAS	Business class change only Business class seating orientation may have changed At Rear	