



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, December 01, 2025

Rules: 2-6



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 11/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/30/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	289	48	83.4%	8,840	1,148	87.0%	17,913	2,198	87.7%
Central Division	85.5%	65	14	78.5%	1,988	166	91.6%	4,024	369	90.8%
Northeast Division	80.0%	94	16	83.0%	2,753	386	86.0%	5,597	754	86.5%
Southeast Division	72.5%	65	10	84.6%	2,065	312	84.9%	4,200	519	87.6%
Southwest Division	77.0%	65	8	87.7%	2,034	284	86.0%	4,092	556	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00167 00000005503 UNCLASSIFIED 12/17/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	131,933	37,450	72%	3,141,791	673,396	79%	6,278,694	1,258,870	80%
Northeast Corridor	81%	53,147	17,416	67%	1,411,955	303,416	79%	2,820,140	521,177	82%
Acela	83%	9,341	4,227	55%	298,743	69,628	77%	593,892	117,572	80%
Northeast Regional	79%	43,806	13,189	70%	1,113,212	233,788	79%	2,226,248	403,605	82%
Richmond / Newport News / Norfolk	77%	12,558	4,042	68%	337,610	84,504	75%	676,689	145,418	79%
Springfield Shuttles	89%	1,144	228	80%	24,420	3,303	86%	40,908	4,663	89%
Roanoke	79%	3,218	476	85%	86,858	13,996	84%	170,454	27,141	84%
On Spine Northeast Regional	80%	26,886	8,443	69%	664,324	131,985	80%	1,338,197	226,383	83%
State Supported	80%	61,552	14,772	76%	1,346,778	249,007	82%	2,696,246	488,747	82%
Borealis	60%	680	200	71%	17,417	3,980	77%	36,459	9,630	74%
Capitol Corridor	90%	5,039	400	92%	117,003	15,950	86%	232,082	24,907	89%
Carolinian	60%	1,630	225	86%	34,723	8,380	76%	73,598	20,933	72%
Cascades	63%	3,272	461	86%	74,584	15,847	79%	146,923	35,396	76%
Downeaster	82%	2,091	216	90%	45,492	2,312	95%	93,974	11,785	87%
Empire	78%	7,225	1,369	81%	158,005	31,061	80%	323,132	63,392	80%
Adirondack	72%	519	8	98%	9,641	2,770	71%	20,989	6,588	69%
Ethan Allen Express	70%	763	103	87%	17,872	6,456	64%	37,247	11,664	69%
Maple Leaf	70%	1,129	675	40%	21,796	6,848	69%	40,178	13,227	67%
New York - Albany	85%	2,847	509	82%	66,864	8,824	87%	139,998	19,298	86%
New York - Niagara Falls	75%	1,967	74	96%	41,832	6,163	85%	84,720	12,615	85%
Gold Runner	73%	6,358	1,997	69%	82,166	32,639	60%	155,672	56,110	64%
Heartland Flyer	65%	333	13	96%	6,170	2,840	54%	12,550	7,567	40%
Hiawatha	90%	2,231	823	63%	52,999	3,903	93%	107,932	10,961	90%
Illinois	78%	3,148	2,620	17%	70,984	21,636	70%	150,052	39,097	74%
Carl Sandburg / Illinois Zephyr	85%	602	416	31%	12,627	3,237	74%	25,039	6,315	75%
Illini / Saluki	85%	1,415	1,372	3%	25,147	8,530	66%	54,961	13,415	76%
Lincoln Service	70%	1,131	832	26%	33,210	9,869	70%	70,052	19,367	72%
Keystone	92%	7,665	1,153	85%	247,394	22,940	91%	510,262	41,932	92%
Lincoln / Missouri	60%	1,033	433	58%	23,512	11,556	51%	48,557	24,805	49%
Mardi Gras Service	80%	251	0	100%	11,947	1,245	90%	26,874	3,722	86%
Michigan	69%	3,582	2,848	20%	61,105	17,616	71%	119,856	29,965	75%
Blue Water	70%	746	736	1%	14,767	3,143	79%	30,896	7,312	76%
Pere Marquette	85%	560	152	73%	7,796	868	89%	15,972	1,932	88%
Wolverine	65%	2,276	1,960	14%	38,542	13,605	65%	72,988	20,721	72%
Missouri	80%	408	60	85%	7,213	1,700	76%	14,497	3,513	76%
Pacific Surfliner	85%	11,356	1,265	89%	228,416	38,082	83%	419,420	58,910	86%
Pennsylvanian	72%	1,183	292	75%	27,694	1,970	93%	57,143	5,947	90%
Piedmont	73%	2,298	276	88%	40,972	7,271	82%	84,733	21,900	74%
Vermont	75%	1,769	121	93%	38,982	8,079	79%	82,530	18,275	78%
Long Distance	56%	17,234	5,262	69%	383,058	120,973	68%	762,308	248,946	67%
Auto Train	57%	1,092	0	100%	20,829	4,389	79%	40,018	7,251	82%
California Zephyr	50%	1,326	70	95%	27,471	5,537	80%	57,072	15,721	72%
Cardinal	55%	315	299	5%	8,116	3,323	59%	17,377	8,310	52%
City Of New Orleans	75%	894	355	60%	21,154	4,689	78%	43,428	9,766	78%
Coast Starlight	60%	855	10	99%	36,851	12,195	67%	70,875	22,516	68%
Crescent	70%	1,390	338	76%	29,696	6,377	79%	59,109	15,801	73%
Empire Builder	55%	2,240	695	69%	31,872	11,273	65%	62,607	20,826	67%
Floridian	40%	2,426	988	59%	52,367	27,746	47%	104,339	54,567	48%
Lake Shore Ltd	73%	1,558	447	71%	27,935	4,880	83%	56,117	8,306	85%
Palmetto	65%	1,356	386	72%	30,262	3,475	89%	60,053	8,449	86%
Silver Meteor	45%	1,581	157	90%	33,354	11,109	67%	63,095	18,408	71%
Southwest Chief	40%	1,135	696	39%	25,292	13,399	47%	51,974	30,524	41%
Sunset Ltd	70%	413	233	44%	8,283	2,055	75%	16,846	4,369	74%
Texas Eagle	50%	653	588	10%	29,576	10,526	64%	59,398	24,132	59%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00107 00000005500 "UNCLASSIFIED" 12/17/2025

Train Index Dates Through November 30, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	165,473	3,214,092	515	329,607	6,508,860	506

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	6,156	938,293	66	12,340	1,902,236	65
INFRASTRUCTURE PLANNED	135	4,924	938,293	52	10,581	1,902,236	56
FLEET RELIABILITY	90	23,771	3,214,092	74	47,485	6,508,860	73
TRAIN OPERATIONS	424	130,622	3,214,092	406	259,201	6,508,860	398

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 11/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/30/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	289	48	83.4%	8,840	1,148	87.0%	17,913	2,198	87.7%
Central Division	85.5%	65	14	78.5%	1,988	166	91.6%	4,024	369	90.8%
Northeast Division	80.0%	94	16	83.0%	2,753	386	86.0%	5,597	754	86.5%
Southeast Division	72.5%	65	10	84.6%	2,065	312	84.9%	4,200	519	87.6%
Southwest Division	77.0%	65	8	87.7%	2,034	284	86.0%	4,092	556	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 11/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/30/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	289	48	83.4%	8,840	1,148	87.0%	17,913	2,198	87.7%
Central Division	85.5%	65	14	78.5%	1,988	166	91.6%	4,024	369	90.8%
CDL	90.0%	2	0	100.0%	52	1	98.1%	114	6	94.7%
CHI	85.0%	26	9	65.4%	806	66	91.8%	1,634	137	91.6%
EUG	86.5%	2	0	100.0%	60	10	83.3%	117	15	87.2%
GRR	98.0%	1	0	100.0%	30	0	100.0%	61	0	100.0%
KCY	84.5%	2	0	100.0%	60	5	91.7%	120	11	90.8%
MKE	86.5%	5	2	60.0%	174	9	94.8%	356	30	91.6%
MSP	94.0%	1	0	100.0%	30	3	90.0%	61	3	95.1%
PDX	78.0%	5	1	80.0%	150	22	85.3%	306	46	85.0%
PNT	91.5%	3	0	100.0%	88	3	96.6%	127	5	96.1%
PTH	93.0%	1	0	100.0%	30	0	100.0%	61	2	96.7%
QCY	87.5%	2	0	100.0%	60	4	93.3%	122	12	90.2%
SEA	80.0%	8	1	87.5%	240	32	86.7%	485	74	84.7%
SPK	92.0%	1	0	100.0%	30	0	100.0%	61	1	98.4%
STL	88.0%	4	1	75.0%	118	10	91.5%	242	18	92.6%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	60	1	98.3%	122	4	96.7%
Northeast Division	80.0%	94	16	83.0%	2,753	386	86.0%	5,597	754	86.5%
ALB	91.5%	7	2	71.4%	181	16	91.2%	367	21	94.3%
BON	43.5%	5	2	60.0%	146	11	92.5%	287	32	88.9%
BOS	86.5%	19	2	89.5%	543	54	90.1%	1,098	103	90.6%
BRK	88.0%	5	0	100.0%	140	7	95.0%	267	13	95.1%
BTN	48.0%	1	0	100.0%	29	7	75.9%	60	17	71.7%
DOV	-	-	-	-	3	2	33.3%	3	2	33.3%
GFD	86.0%	2	1	50.0%	54	6	88.9%	116	9	92.2%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	30	6	80.0%	61	11	82.0%
NFL	96.5%	2	1	50.0%	60	1	98.3%	122	5	95.9%
NHV	75.5%	5	2	60.0%	155	38	75.5%	307	63	79.5%
NYP	77.5%	38	6	84.2%	1,167	215	81.6%	2,377	431	81.9%
SAB	98.0%	1	0	100.0%	28	0	100.0%	59	0	100.0%
SAR	-	-	-	-	1	1	0.0%	1	1	0.0%
SPG	88.0%	7	0	100.0%	183	9	95.1%	349	16	95.4%
TWO	84.0%	1	0	100.0%	30	12	60.0%	60	16	73.3%
WEM	-	-	-	-	3	1	66.7%	17	11	35.3%
Southeast Division	72.5%	65	10	84.6%	2,065	312	84.9%	4,200	519	87.6%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	150	9	94.0%	305	25	91.8%
GRO	-	-	-	-	4	2	50.0%	4	2	50.0%
HAR	62.0%	8	1	87.5%	326	71	78.2%	680	98	85.6%
LOR	69.5%	1	0	100.0%	30	3	90.0%	61	5	91.8%
MIA	87.5%	2	0	100.0%	60	7	88.3%	122	13	89.3%
MOE	94.0%	2	0	100.0%	60	0	100.0%	122	3	97.5%
NFK	86.0%	2	0	100.0%	81	6	92.6%	170	15	91.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 11/30/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/30/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	289	48	83.4%	8,840	1,148	87.0%	17,913	2,198	87.7%
Southeast Division	72.5%	65	10	84.6%	2,065	312	84.9%	4,200	519	87.6%
NOL	92.0%	4	0	100.0%	133	8	94.0%	269	14	94.8%
NPN	96.0%	2	0	100.0%	48	4	91.7%	98	8	91.8%
PGH	92.0%	1	0	100.0%	30	0	100.0%	61	1	98.4%
PHL	45.0%	4	2	50.0%	139	90	35.3%	282	123	56.4%
RGH	97.0%	4	0	100.0%	116	0	100.0%	240	3	98.8%
RNK	85.5%	2	0	100.0%	59	5	91.5%	121	14	88.4%
RVM	86.0%	1	1	0.0%	35	5	85.7%	70	11	84.3%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	30	0	100.0%	61	0	100.0%
SFA	70.5%	1	0	100.0%	30	2	93.3%	61	3	95.1%
WAS	70.0%	25	6	76.0%	734	100	86.4%	1,469	178	87.9%
Southwest Division	77.0%	65	8	87.7%	2,034	284	86.0%	4,092	556	86.4%
ARN	60.5%	1	0	100.0%	30	2	93.3%	61	5	91.8%
BFD	75.5%	6	2	66.7%	170	42	75.3%	347	84	75.8%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	30	7	76.7%	63	17	73.0%
FNO	-	-	-	-	5	3	40.0%	6	3	50.0%
FTW	89.5%	1	0	100.0%	30	0	100.0%	60	3	95.0%
GTA	72.5%	3	0	100.0%	89	10	88.8%	176	17	90.3%
LAX	77.5%	10	2	80.0%	283	33	88.3%	560	62	88.9%
OKC	96.0%	1	0	100.0%	30	1	96.7%	61	3	95.1%
OKJ	79.0%	9	2	77.8%	323	81	74.9%	660	152	77.0%
SAC	73.5%	11	2	81.8%	384	36	90.6%	788	86	89.1%
SAN	77.0%	12	0	100.0%	358	41	88.5%	693	68	90.2%
SAS	85.0%	1	0	100.0%	30	0	100.0%	61	3	95.1%
SBA	-	-	-	-	1	1	0.0%	1	1	0.0%
SJC	87.5%	7	0	100.0%	209	23	89.0%	425	40	90.6%
SLO	62.0%	2	0	100.0%	60	4	93.3%	117	11	90.6%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	2	0	100.0%	10	1	90.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	52	13	2	84.6%	27	4	85.2%	13	2	84.6%	26	4	84.6%
3		30	2	93.3%	61	4	93.4%	30	11	63.3%	61	23	62.3%
4	45	30	4	86.7%	61	6	90.2%	30	16	46.7%	61	38	37.7%
5		30	3	90.0%	60	7	88.3%	30	1	96.7%	59	6	89.8%
6		30	7	76.7%	61	17	72.1%	30	10	66.7%	61	21	65.6%
7		30	1	96.7%	61	4	93.4%	30	4	86.7%	61	7	88.5%
8	38	30	7	76.7%	61	20	67.2%	30	15	50.0%	61	27	55.7%
11		30	5	83.3%	60	11	81.7%	30	3	90.0%	58	7	87.9%
14	No OS	30	4	86.7%	61	9	85.2%	30	12	60.0%	60	18	70.0%
19		30	4	86.7%	61	8	86.9%	30	2	93.3%	61	11	82.0%
20	62	30	3	90.0%	61	6	90.2%	30	5	83.3%	61	6	90.2%
21	43	29	6	79.3%	60	8	86.7%	29	5	82.8%	60	11	81.7%
22	Cncld	30	0	100.0%	61	3	95.1%	29	7	75.9%	60	13	78.3%
23		30	0	100.0%	61	3	95.1%	30	2	93.3%	61	10	83.6%
24		30	2	93.3%	61	2	96.7%	30	1	96.7%	61	6	90.2%
25		30	0	100.0%	61	0	100.0%	30	5	83.3%	61	9	85.2%
26		30	2	93.3%	61	2	96.7%	30	7	76.7%	61	11	82.0%
27		30	2	93.3%	61	3	95.1%	30	4	86.7%	61	10	83.6%
28	33	30	6	80.0%	61	13	78.7%	30	4	86.7%	61	8	86.9%
40		30	5	83.3%	61	9	85.2%	30	13	56.7%	61	22	63.9%
41		30	7	76.7%	61	18	70.5%	30	18	40.0%	61	39	36.1%
42	92	30	0	100.0%	61	1	98.4%	30	4	86.7%	61	9	85.2%
43		30	4	86.7%	61	5	91.8%	30	1	96.7%	61	3	95.1%
48		30	3	90.0%	61	5	91.8%	30	1	96.7%	61	3	95.1%
49	52	30	6	80.0%	61	10	83.6%	30	4	86.7%	61	5	91.8%
50	35	13	2	84.6%	26	4	84.6%	13	6	53.8%	27	13	51.9%
52		30	2	93.3%	61	3	95.1%	30	9	70.0%	61	12	80.3%
53		30	3	90.0%	61	5	91.8%	30	5	83.3%	61	8	86.9%
54		11	0	100.0%	19	0	100.0%	11	1	90.9%	19	1	94.7%
57		11	1	90.9%	19	1	94.7%	11	0	100.0%	19	0	100.0%
58		30	1	96.7%	60	2	96.7%	30	2	93.3%	59	7	88.1%
59		30	0	100.0%	59	3	94.9%	30	0	100.0%	59	3	94.9%
63	50	30	7	76.7%	61	21	65.6%	30	12	60.0%	61	29	52.5%
64		30	12	60.0%	60	16	73.3%	30	2	93.3%	60	10	83.3%
65		10	2	80.0%	19	3	84.2%	11	3	72.7%	19	5	73.7%
66		30	3	90.0%	61	10	83.6%	30	6	80.0%	61	13	78.7%
68		30	6	80.0%	61	11	82.0%	30	10	66.7%	61	25	59.0%
69		30	5	83.3%	61	7	88.5%	30	2	93.3%	61	7	88.5%
71		30	0	100.0%	61	0	100.0%	30	5	83.3%	61	16	73.8%
72		30	2	93.3%	61	5	91.8%	30	4	86.7%	61	10	83.6%
73	25	30	0	100.0%	61	1	98.4%	30	14	53.3%	60	33	45.0%
74		30	2	93.3%	61	5	91.8%	30	10	66.7%	61	20	67.2%

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		30	2	93.3%	61	2	96.7%	30	9	70.0%	61	28	54.1%
76		30	1	96.7%	61	4	93.4%	30	9	70.0%	61	30	50.8%
77		30	0	100.0%	61	2	96.7%	30	6	80.0%	61	22	63.9%
78		30	0	100.0%	61	3	95.1%	30	2	93.3%	61	9	85.2%
79		30	4	86.7%	61	11	82.0%	29	4	86.2%	60	11	81.7%
80		30	4	86.7%	61	8	86.9%	29	2	93.1%	60	5	91.7%
87	65	11	3	72.7%	19	4	78.9%	11	4	63.6%	19	4	78.9%
88	35	11	1	90.9%	19	1	94.7%	11	2	81.8%	19	2	89.5%
89		30	6	80.0%	61	12	80.3%	30	1	96.7%	61	6	90.2%
90		30	0	100.0%	61	0	100.0%	30	2	93.3%	61	6	90.2%
96		6	0	100.0%	10	1	90.0%	6	2	66.7%	10	3	70.0%
97		30	10	66.7%	61	18	70.5%	30	7	76.7%	61	16	73.8%
98		30	2	93.3%	61	4	93.4%	30	9	70.0%	61	11	82.0%
99	59	11	1	90.9%	19	1	94.7%	11	8	27.3%	18	8	55.6%
102		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
103		11	0	100.0%	19	3	84.2%	11	0	100.0%	19	0	100.0%
105		6	3	50.0%	10	4	60.0%	6	0	100.0%	10	0	100.0%
106	50	11	1	90.9%	19	1	94.7%	11	1	90.9%	19	2	89.5%
107	93	11	1	90.9%	19	2	89.5%	11	1	90.9%	19	1	94.7%
108	40	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
118		11	1	90.9%	19	1	94.7%	11	0	100.0%	19	0	100.0%
120		6	1	83.3%	10	1	90.0%	6	0	100.0%	10	0	100.0%
121		6	3	50.0%	10	3	70.0%	6	2	66.7%	10	2	80.0%
122		6	2	66.7%	10	2	80.0%	6	1	83.3%	10	1	90.0%
123		6	0	100.0%	9	0	100.0%	6	0	100.0%	9	0	100.0%
124		11	1	90.9%	19	3	84.2%	11	2	81.8%	19	4	78.9%
128		11	2	81.8%	19	3	84.2%	10	1	90.0%	18	1	94.4%
132		6	1	83.3%	10	1	90.0%	6	0	100.0%	10	0	100.0%
135		11	2	81.8%	19	2	89.5%	11	6	45.5%	19	9	52.6%
139		6	0	100.0%	10	0	100.0%	5	1	80.0%	9	2	77.8%
140	16	11	1	90.9%	19	2	89.5%	11	3	72.7%	19	4	78.9%
143		11	2	81.8%	19	2	89.5%	11	1	90.9%	19	1	94.7%
145		6	1	83.3%	10	1	90.0%	6	3	50.0%	10	4	60.0%
146	21	11	2	81.8%	19	2	89.5%	11	3	72.7%	19	5	73.7%
149	25	6	0	100.0%	10	0	100.0%	6	2	66.7%	10	3	70.0%
150	57	11	9	18.2%	19	13	31.6%	11	9	18.2%	19	12	36.8%
151		30	7	76.7%	61	14	77.0%	29	6	79.3%	60	16	73.3%
153		11	1	90.9%	19	1	94.7%	11	0	100.0%	19	0	100.0%
154	23	6	0	100.0%	10	0	100.0%	6	3	50.0%	10	5	50.0%
155		11	1	90.9%	19	1	94.7%	11	1	90.9%	19	1	94.7%
156	66	11	1	90.9%	19	1	94.7%	11	1	90.9%	19	2	89.5%
157		6	1	83.3%	10	1	90.0%	6	3	50.0%	10	5	50.0%

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
158		11	0	100.0%	19	0	100.0%	11	0	100.0%	19	0	100.0%
160		11	0	100.0%	19	0	100.0%	10	1	90.0%	18	1	94.4%
161	127	11	0	100.0%	19	0	100.0%	11	6	45.5%	19	8	57.9%
162	40	11	1	90.9%	19	1	94.7%	11	4	63.6%	19	6	68.4%
164		11	3	72.7%	19	3	84.2%	11	4	63.6%	19	4	78.9%
165	35	11	2	81.8%	19	3	84.2%	11	4	63.6%	19	4	78.9%
166	29	6	0	100.0%	10	0	100.0%	5	2	60.0%	9	2	77.8%
169		11	0	100.0%	19	2	89.5%	10	2	80.0%	18	3	83.3%
189	39	6	2	66.7%	10	3	70.0%	6	3	50.0%	10	3	70.0%
195	36	11	0	100.0%	19	0	100.0%	11	9	18.2%	19	13	31.6%
199		2	1	50.0%	2	1	50.0%	1	0	100.0%	1	0	100.0%
232	28	30	0	100.0%	61	1	98.4%	30	3	90.0%	61	6	90.2%
233		30	7	76.7%	61	13	78.7%	30	6	80.0%	61	12	80.3%
234		30	3	90.0%	61	3	95.1%	30	2	93.3%	61	2	96.7%
236		30	1	96.7%	61	1	98.4%	30	6	80.0%	61	11	82.0%
237		30	4	86.7%	61	10	83.6%	30	1	96.7%	61	4	93.4%
239		29	6	79.3%	60	15	75.0%	29	1	96.6%	60	2	96.7%
240		30	6	80.0%	61	6	90.2%	30	6	80.0%	61	7	88.5%
241	44	30	9	70.0%	61	16	73.8%	30	2	93.3%	61	10	83.6%
244		30	0	100.0%	61	2	96.7%	30	3	90.0%	61	15	75.4%
245		11	3	72.7%	19	5	73.7%	10	0	100.0%	18	1	94.4%
280		30	0	100.0%	61	3	95.1%	30	6	80.0%	61	10	83.6%
281		30	3	90.0%	61	8	86.9%	30	3	90.0%	61	5	91.8%
283		30	6	80.0%	61	8	86.9%	30	4	86.7%	61	9	85.2%
284		30	1	96.7%	61	2	96.7%	30	1	96.7%	61	5	91.8%
290		30	8	73.3%	61	18	70.5%	29	11	62.1%	60	21	65.0%
291		30	8	73.3%	61	13	78.7%	30	6	80.0%	61	12	80.3%
300	17	30	1	96.7%	61	2	96.7%	29	8	72.4%	60	14	76.7%
301	18	29	1	96.6%	60	1	98.3%	28	4	85.7%	59	9	84.7%
302		29	3	89.7%	60	6	90.0%	27	7	74.1%	58	17	70.7%
305	154	30	4	86.7%	61	5	91.8%	30	11	63.3%	60	20	66.7%
306	138	29	1	96.6%	60	2	96.7%	29	6	79.3%	59	11	81.4%
307	64	29	3	89.7%	60	5	91.7%	29	9	69.0%	60	11	81.7%
311		30	5	83.3%	60	7	88.3%	30	6	80.0%	60	14	76.7%
316		30	2	93.3%	60	3	95.0%	30	6	80.0%	60	12	80.0%
318	78	30	3	90.0%	61	9	85.2%	30	11	63.3%	60	25	58.3%
319		30	1	96.7%	61	2	96.7%	30	16	46.7%	61	36	41.0%
331		30	1	96.7%	61	4	93.4%	30	3	90.0%	61	6	90.2%
332		30	2	93.3%	61	5	91.8%	30	3	90.0%	61	5	91.8%
334		30	0	100.0%	61	1	98.4%	30	1	96.7%	60	4	93.3%
335	58	30	1	96.7%	61	7	88.5%	30	2	93.3%	60	9	85.0%
336		30	0	100.0%	61	1	98.4%	30	0	100.0%	61	4	93.4%

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
337		30	0	100.0%	61	4	93.4%	30	1	96.7%	61	5	91.8%
338	61	30	4	86.7%	61	15	75.4%	30	3	90.0%	60	12	80.0%
339	193	30	5	83.3%	61	14	77.0%	30	4	86.7%	61	11	82.0%
341		29	6	79.3%	60	9	85.0%	29	4	86.2%	60	8	86.7%
342	174	30	3	90.0%	61	6	90.2%	30	5	83.3%	60	8	86.7%
350	100	30	1	96.7%	43	2	95.3%	30	19	36.7%	43	22	48.8%
351	98	30	2	93.3%	61	3	95.1%	30	17	43.3%	61	26	57.4%
352	79	30	2	93.3%	61	4	93.4%	29	10	65.5%	59	14	76.3%
353	21	28	0	100.0%	40	2	95.0%	28	3	89.3%	40	5	87.5%
354	61	30	2	93.3%	61	3	95.1%	30	7	76.7%	61	14	77.0%
355		30	1	96.7%	61	5	91.8%	30	9	70.0%	61	13	78.7%
364	28	30	3	90.0%	61	5	91.8%	30	2	93.3%	61	8	86.9%
365	67	30	0	100.0%	61	2	96.7%	30	7	76.7%	61	16	73.8%
370		30	1	96.7%	61	2	96.7%	30	4	86.7%	61	9	85.2%
371		30	0	100.0%	61	0	100.0%	30	2	93.3%	61	4	93.4%
380	55	30	3	90.0%	61	10	83.6%	30	6	80.0%	61	13	78.7%
381	20	30	1	96.7%	61	1	98.4%	30	2	93.3%	61	7	88.5%
382		30	1	96.7%	61	2	96.7%	30	10	66.7%	61	15	75.4%
383	33	30	4	86.7%	61	5	91.8%	29	11	62.1%	60	22	63.3%
390	19	22	1	95.5%	53	4	92.5%	22	11	50.0%	53	16	69.8%
391	39	23	0	100.0%	54	0	100.0%	23	7	69.6%	53	12	77.4%
392	40	30	0	100.0%	61	2	96.7%	30	11	63.3%	60	15	75.0%
393	20	30	2	93.3%	61	5	91.8%	30	8	73.3%	60	15	75.0%
400		10	1	90.0%	18	1	94.4%	9	0	100.0%	17	0	100.0%
405		7	0	100.0%	15	0	100.0%	7	1	85.7%	15	1	93.3%
409		4	0	100.0%	8	0	100.0%	4	0	100.0%	8	0	100.0%
416		4	0	100.0%	8	0	100.0%	4	1	75.0%	8	1	87.5%
448		2	2	0.0%	2	2	0.0%	1	0	100.0%	1	0	100.0%
450	32	8	4	50.0%	16	4	75.0%	8	5	37.5%	16	6	62.5%
460	28	8	6	25.0%	16	7	56.3%	7	4	42.9%	15	4	73.3%
461		10	1	90.0%	18	1	94.4%	10	0	100.0%	18	1	94.4%
464		8	2	75.0%	16	2	87.5%	8	2	75.0%	16	4	75.0%
465		5	0	100.0%	9	0	100.0%	5	0	100.0%	9	0	100.0%
488	51	11	6	45.5%	19	6	68.4%	9	4	55.6%	17	4	76.5%
497		4	0	100.0%	8	0	100.0%	4	0	100.0%	8	0	100.0%
499	46	9	3	66.7%	17	3	82.4%	9	2	77.8%	17	2	88.2%
500		30	3	90.0%	61	5	91.8%	29	1	96.6%	60	5	91.7%
502		30	1	96.7%	61	6	90.2%	29	7	75.9%	60	16	73.3%
503		30	2	93.3%	58	8	86.2%	30	7	76.7%	57	15	73.7%
504		30	4	86.7%	61	5	91.8%	30	8	73.3%	61	19	68.9%
505	26	30	4	86.7%	61	10	83.6%	29	6	79.3%	59	13	78.0%
506		30	5	83.3%	60	9	85.0%	30	4	86.7%	59	9	84.7%

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507	37	30	4	86.7%	61	7	88.5%	30	7	76.7%	61	22	63.9%
508		30	6	80.0%	59	11	81.4%	30	8	73.3%	59	13	78.0%
509		30	3	90.0%	61	4	93.4%	30	6	80.0%	61	13	78.7%
511		30	2	93.3%	61	4	93.4%	30	6	80.0%	61	12	80.3%
516		30	5	83.3%	61	9	85.2%	30	12	60.0%	61	28	54.1%
517		30	0	100.0%	61	1	98.4%	30	10	66.7%	60	22	63.3%
518		30	7	76.7%	61	13	78.7%	30	14	53.3%	61	36	41.0%
519		30	1	96.7%	61	3	95.1%	30	3	90.0%	61	9	85.2%
562		30	5	83.3%	59	8	86.4%	30	3	90.0%	58	6	89.7%
564		30	4	86.7%	59	6	89.8%	28	5	82.1%	56	10	82.1%
566		30	3	90.0%	59	5	91.5%	27	4	85.2%	56	6	89.3%
572		30	3	90.0%	58	6	89.7%	29	9	69.0%	57	14	75.4%
573		30	3	90.0%	59	9	84.7%	30	4	86.7%	58	8	86.2%
577		30	5	83.3%	57	5	91.2%	26	1	96.2%	53	2	96.2%
580	19	30	0	100.0%	59	2	96.6%	30	4	86.7%	59	7	88.1%
581		30	7	76.7%	59	7	88.1%	30	6	80.0%	59	12	79.7%
582		30	2	93.3%	59	5	91.5%	28	2	92.9%	57	4	93.0%
586	59	30	6	80.0%	59	11	81.4%	29	7	75.9%	56	9	83.9%
587		30	1	96.7%	59	3	94.9%	30	6	80.0%	57	9	84.2%
591		30	0	100.0%	59	1	98.3%	30	4	86.7%	59	6	89.8%
593		30	5	83.3%	59	9	84.7%	27	2	92.6%	53	5	90.6%
595		30	10	66.7%	58	14	75.9%	30	4	86.7%	57	10	82.5%
612		6	1	83.3%	10	1	90.0%	6	0	100.0%	10	0	100.0%
615		6	4	33.3%	10	5	50.0%	6	1	83.3%	10	2	80.0%
623	68	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
630		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
637		7	0	100.0%	11	0	100.0%	6	0	100.0%	10	0	100.0%
660	17	11	1	90.9%	19	1	94.7%	11	5	54.5%	19	8	57.9%
661		11	2	81.8%	19	3	84.2%	11	3	72.7%	19	5	73.7%
662		7	0	100.0%	11	0	100.0%	7	0	100.0%	11	0	100.0%
663		11	1	90.9%	19	2	89.5%	11	1	90.9%	19	1	94.7%
664		11	2	81.8%	19	4	78.9%	11	0	100.0%	19	1	94.7%
665		11	2	81.8%	19	2	89.5%	11	6	45.5%	19	8	57.9%
666		11	3	72.7%	19	6	68.4%	11	1	90.9%	19	1	94.7%
667		11	0	100.0%	19	2	89.5%	11	0	100.0%	19	3	84.2%
669		11	0	100.0%	19	0	100.0%	11	6	45.5%	19	7	63.2%
670	53	11	2	81.8%	19	2	89.5%	11	1	90.9%	19	1	94.7%
671		11	1	90.9%	19	1	94.7%	11	0	100.0%	19	1	94.7%
672		11	2	81.8%	19	2	89.5%	11	1	90.9%	19	1	94.7%
674		11	3	72.7%	19	4	78.9%	11	0	100.0%	19	0	100.0%
690		10	0	100.0%	18	0	100.0%	10	0	100.0%	18	1	94.4%
691		10	1	90.0%	18	2	88.9%	10	2	80.0%	18	6	66.7%

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
692		10	1	90.0%	18	1	94.4%	10	1	90.0%	18	5	72.2%
693		10	1	90.0%	18	3	83.3%	10	1	90.0%	18	5	72.2%
694		10	3	70.0%	18	4	77.8%	10	0	100.0%	18	1	94.4%
695		10	1	90.0%	18	2	88.9%	10	1	90.0%	18	5	72.2%
696		10	0	100.0%	18	1	94.4%	10	1	90.0%	18	3	83.3%
697	26	10	2	80.0%	18	3	83.3%	10	1	90.0%	18	4	77.8%
698		10	0	100.0%	18	0	100.0%	10	0	100.0%	18	2	88.9%
699		7	0	100.0%	14	2	85.7%	6	0	100.0%	13	0	100.0%
702		30	8	73.3%	61	15	75.4%	30	10	66.7%	60	19	68.3%
703		30	8	73.3%	61	15	75.4%	30	9	70.0%	61	16	73.8%
710		30	12	60.0%	61	24	60.7%	30	15	50.0%	61	28	54.1%
711		28	2	92.9%	57	4	93.0%	25	5	80.0%	53	7	86.8%
712		30	10	66.7%	61	17	72.1%	29	11	62.1%	60	23	61.7%
713	18	30	4	86.7%	61	9	85.2%	26	14	46.2%	55	27	50.9%
714		29	13	55.2%	55	19	65.5%	26	9	65.4%	50	16	68.0%
715	54	30	10	66.7%	61	22	63.9%	29	14	51.7%	58	29	50.0%
716		30	12	60.0%	61	23	62.3%	30	16	46.7%	60	23	61.7%
717		27	10	63.0%	52	13	75.0%	25	8	68.0%	47	13	72.3%
718		30	11	63.3%	61	22	63.9%	30	6	80.0%	61	16	73.8%
719	26	30	11	63.3%	61	24	60.7%	29	6	79.3%	59	16	72.9%
720		12	1	91.7%	20	2	90.0%	12	0	100.0%	20	1	95.0%
723		12	1	91.7%	20	3	85.0%	12	2	83.3%	20	2	90.0%
724		12	0	100.0%	20	0	100.0%	12	0	100.0%	20	0	100.0%
727	16	12	1	91.7%	20	3	85.0%	12	5	58.3%	20	6	70.0%
728		12	0	100.0%	20	2	90.0%	12	4	66.7%	20	4	80.0%
729		12	2	83.3%	20	2	90.0%	12	5	58.3%	20	5	75.0%
732		12	3	75.0%	20	3	85.0%	12	4	66.7%	20	4	80.0%
733		12	2	83.3%	20	3	85.0%	12	2	83.3%	17	3	82.4%
734		12	5	58.3%	20	8	60.0%	12	5	58.3%	20	6	70.0%
736		12	1	91.7%	20	1	95.0%	12	3	75.0%	20	4	80.0%
737	39	12	0	100.0%	20	2	90.0%	12	3	75.0%	20	3	85.0%
738		12	1	91.7%	20	3	85.0%	11	1	90.9%	18	1	94.4%
741		12	2	83.3%	20	3	85.0%	12	3	75.0%	20	4	80.0%
742		12	3	75.0%	20	3	85.0%	11	0	100.0%	19	3	84.2%
743		12	2	83.3%	20	2	90.0%	12	0	100.0%	20	1	95.0%
744	17	12	1	91.7%	20	1	95.0%	12	2	83.3%	20	5	75.0%
745		12	0	100.0%	20	2	90.0%	12	2	83.3%	20	2	90.0%
746		12	0	100.0%	20	0	100.0%	12	0	100.0%	20	1	95.0%
747		12	2	83.3%	20	3	85.0%	12	1	91.7%	20	2	90.0%
748		12	3	75.0%	19	5	73.7%	12	1	91.7%	19	1	94.7%
749		12	2	83.3%	20	4	80.0%	9	0	100.0%	16	2	87.5%
751		12	0	100.0%	20	4	80.0%	12	2	83.3%	20	4	80.0%

Amtrak On Time Performance

Trains Arriving Through: 11/30/2025

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
761		30	1	96.7%	59	3	94.9%	30	5	83.3%	59	9	84.7%
765		30	4	86.7%	59	9	84.7%	30	7	76.7%	59	13	78.0%
769		30	2	93.3%	59	4	93.2%	28	6	78.6%	57	11	80.7%
770		30	4	86.7%	59	7	88.1%	30	7	76.7%	59	9	84.7%
774		30	2	93.3%	59	6	89.8%	30	8	73.3%	58	11	81.0%
779	39	30	2	93.3%	59	4	93.2%	30	8	73.3%	58	9	84.5%
784		30	3	90.0%	59	6	89.8%	30	18	40.0%	58	29	50.0%
785		30	1	96.7%	59	1	98.3%	30	3	90.0%	59	7	88.1%
790		30	4	86.7%	59	5	91.5%	30	5	83.3%	59	7	88.1%
794		30	2	93.3%	59	5	91.5%	29	3	89.7%	58	10	82.8%
821		30	1	96.7%	61	3	95.1%	30	18	40.0%	61	40	34.4%
822		30	0	100.0%	61	3	95.1%	30	18	40.0%	61	44	27.9%
1108		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
1123		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1161		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
1333		30	2	93.3%	61	4	93.4%	29	10	65.5%	60	26	56.7%
1340	16	30	3	90.0%	61	3	95.1%	30	5	83.3%	61	13	78.7%
2205		11	3	72.7%	19	3	84.2%	11	1	90.9%	19	1	94.7%
2222		6	0	100.0%	10	0	100.0%	6	0	100.0%	10	0	100.0%
2224	26	6	3	50.0%	10	3	70.0%	6	1	83.3%	10	1	90.0%
2226	41	6	2	66.7%	10	2	80.0%	6	1	83.3%	10	1	90.0%
2247	101	6	1	83.3%	10	2	80.0%	6	3	50.0%	10	3	70.0%
2248		11	1	90.9%	19	2	89.5%	11	2	81.8%	19	3	84.2%
2250		11	2	81.8%	19	3	84.2%	11	6	45.5%	19	8	57.9%
2252		11	0	100.0%	19	1	94.7%	11	1	90.9%	19	2	89.5%
2253	75	11	1	90.9%	19	2	89.5%	11	7	36.4%	19	10	47.4%
2254	18	11	0	100.0%	19	0	100.0%	11	4	63.6%	19	4	78.9%
2255	16	11	0	100.0%	19	2	89.5%	11	4	63.6%	19	6	68.4%
2257	16	6	0	100.0%	10	0	100.0%	6	3	50.0%	10	3	70.0%
2258		6	2	66.7%	10	5	50.0%	6	2	66.7%	10	4	60.0%
2259	22	6	4	33.3%	10	4	60.0%	6	5	16.7%	10	5	50.0%
2262	28	6	1	83.3%	10	2	80.0%	6	2	66.7%	10	3	70.0%
2263	Cncld	6	0	100.0%	10	0	100.0%	5	0	100.0%	9	0	100.0%
2265	92	6	0	100.0%	10	0	100.0%	6	2	66.7%	10	2	80.0%
2271		6	1	83.3%	10	1	90.0%	6	1	83.3%	10	2	80.0%
2275	19	6	1	83.3%	10	2	80.0%	5	3	40.0%	9	4	55.6%
2290	33	6	0	100.0%	9	0	100.0%	6	2	66.7%	9	2	77.8%
2292		6	0	100.0%	9	0	100.0%	6	0	100.0%	9	0	100.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 11/30/2025

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2224	NYP	26	ITI	32	ITI	32	WAS-WAS	AM	Service, turn, or wye train, 2265, Due to late inbound 2265
2226	NYP	41	ITI	40	ITI	40	WAS-WAS	AM	Crew rest, 2247
2247	WAS	101	POL	66	POL	66	RTE-PVD	AM	Fire department hold, held at orms bc hold on all tracks pvd station account #2263 cars on fire, smoke in station plus closed
2253	WAS	75	PTI	41	POL	19	RTE-PVD	AM	Fire department hold, Hold on all tracks
2254	BOS	18	DCS	17	DCS	17	NHV-XGX	AM	Issue with automatic road crossing protection, Control Point, XSS, Copy Form D, at Shaw's Cove, Stop & Protect, Bank St Ext, 122.5
2255	WAS	16	WTR	12	DSR	9	NHV-STM	MN	Per bulletin Other, cat 533-535, 15, 2
2257	WAS	16	INJ	35	INJ	35	NHV-STM	MN	Injured or sick passenger Passenger passed out in aisle just east of BRP. Contacted District F for EMS and medical services. Stopped at Fairfield/BlackRock MNRR station and EMS arrived shortly and attended to the passenger. Passenger was removed by EMS
2259	WAS	22	OTH	22	DCS	10	XGX-NHV	AM	Issue with automatic road crossing protection, Control Point, XSS, Copy Form D, at Shaw's Cove, Stop & Protect, Bank St Ext, 122.5
2262	BOS	28	PTI	21	MTI	19	PHL-XHM	AM	Disabled train ahead, Control Point, ., Opr No.3 trk a/c Amtrak 42 stopped No.2 trk
2263	XHM	Trn Cancelled	ENG	14	ENG	14	RTE-PVD	AM	Undesired emergency application, 2006, Stopped at MP 194.69 with an unknown penalty
2265	WAS	92	POL	94	POL	94	RTE-PVD	AM	Fire department hold, held at orms bc hold on all tracks pvd station account #2263 cars on fire, smoke in station plus closed
2275	WAS	19	MBO	31	MBO	31	PVD-XGX	AM	For maritime traffic, Bridge, Mystic River Bridge, Mystic River Bridge Tender rpts boat parade
2290	BOS	33	POL	42	POL	42	XGX-PVD	AM	Fire department hold, all tracks hold
87	NFK	65	POL	68	POL	68	RTE-PVD	AM	Fire department hold, held at orms bc hold on all tracks pvd station account #2263 cars on fire, smoke in station plus closed
88	BOS	35	DCS	20	DCS	20	OSB-NLC	AM	Issue with automatic road crossing protection, Control Point, XSS, Copy Form D, at Shaw's Cove, Stop & Protect, Bank St Ext, 122.5

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 11/30/2025

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
99	NPN	59	HLD	24	CTI	17	RTE-PVD	AM	Follow, mbta, 5821, Milepost, xmf, xhe, Signals of MB5821 ahead
106	NYP	50	MTI	46	MTI	46	PHL-XHM	AM	Disabled train ahead, Control Point, ., Opr No.1 trk a/c Amtrak 42 stopped No.2 trk
107	WAS	93	ITI	95	ITI	95	NYP-NYP	AM	Service, turn, or wye train, 106
108	NYP	40	ITI	67	ITI	67	WAS-WAS	AM	Service, turn, or wye train, 161
140	SPG	16	ADA	6	SMW	6	NYP-XPB	AM	Scheduled in track usage program, Other, NYP XSH
146	SPG	21	WTR	8	WTR	6	STS-WFD	AM	Wet / slippery rail, Milepost w/Letters, STS, WFD, 60 MPH S/r
149	WAS	25	CAR	19	CAR	8	NYP-NWK	AM	Door, 82625
150	BOS	57	POL	31	POL	31	KIN-PVD	AM	Fire department hold, hold all track a/c AM2265 fire on Car
154	BOS	23	POL	21	POL	16	NCR-NCR	AM	On-train police or DEA activity
156	NYP	66	PTI	54	MTI	30	PHL-XHM	AM	Disabled train ahead, Control Point, ., Opr No.1 trk a/c Amtrak 42 stopped No.2 trk
161	WAS	127	POL	78	POL	78	RTE-PVD	AM	Fire department hold, held at orms bc hold on all tracks pvd station account #2263 cars on fire, smoke in station plus closed
162	BOS	40	WTR	18	WTR	10	NHV-OSB	AM	Wet / slippery rail, Milepost, nhv, osb, Excessive wheelslip per ENGR
165	WAS	35	HLD	20	SMW	12	XSH-NYP	AM	Scheduled in track usage program, Other, XSH NYP
166	BOS	29	PTI	15	ENG	9	RTE-BBY	AM	Undesired emergency application, 651, Unknown penalty application, recovered, on the move RTE-BBY
189	WAS	39	HLD	27	HLD	17	NRK-NRK	AM	High passenger count, per crew at 6:52pm
195	RVM	36	HLD	22	FTI	9	FBG-ASD	CS	Follow 409, Milepost, 30.0, 21.0
450	SPG	32	CTI	14	CTI	14	WND-WNL	AM	Meet, ctrail, 6401, Milepost, xha, xha, Held for CT6401 to clear
460	SPG	28	CTI	13	CTI	13	WND-WNL	AM	Meet, ctrail, 6403, Control Point, hayden, Waited for Ctrail train to clear
488	GFD	51	TRS	46	TRS	46	WFD-MDN	AM	Vehicle on track ahead, Milepost w/Letters, WFD, MDN, Meriden PD rpts a car on the trks at E. Main st MP 18.6. W. Parise, APD ntfd. AM488 will hold at Holt
499	SPG	46							

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 11/30/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
623	HAR	68	CCR	64	CCR	41	PHL-PHL	AM	HEP, CC/9640, Loss of HEP, will WYE
660	NYP	17	WTR	16	CTI	5	TRE-PJC	AM	Follow, NJT, NJ7824, Other, TRE-PJC
670	NYP	53	MTI	48	MTI	48	PHL-XHM	AM	Disabled train ahead, Control Point, ., Opr No.1 trk a/c Amtrak 42 stopped No.2 trk
20	NYP	62	HLD	51	MTI	33	PHL-XHM	AM	Disabled train ahead, Control Point, ., Opr No.1 trk a/c Amtrak 42 stopped No.2 trk
697	BRK	26	DCS	19	DCS	15	BON-WOB	MT	Restrictive signal(s) from unknown cause Red, Other, starter, draw, and front ladder
63	TWO	50	ENG	51	ENG	51	NYP-XSD	AM	Set out defective locomotive, 112, STOPPED SOUTH OF EMPIRE A/C ENGINE NOT LOADING
232	NYP	28	MTI	32	MTI	32	XSD-NYP	AM	Disabled train ahead, Other, XEE-XEE, HELD A/C AM63 DISABLED SOUTH OF EMPIRE
241	ALB	44	CON	30	CON	30	NYP-NYP	AM	Hold for connecting train
49	CHI	52	CAR	37	CAR	37	CLE-CLE	NS	Air / Brake / Wheel 62017, Had to replace the B end Brake Pipe Air hose. Massive leak
42	NYP	92	ENG	82	ENG	82	PHL-XHM	AM	Air / Brake, E/129, Stopped No.2 trk A/C parking brake issues
73	CLT	25	DCS	33	DCS	22	CYN-DNC	NS	Restrictive signal(s) from unknown cause Restricted/72.3nc, Milepost w/Letters, 72.3nc, 67.0nc
727	SJC	16	PTI	16	PTI	8	OKJ-OAC	UP	Wait for station track amtrak724, Control Point, 66th ave
737	SJC	39	TEN	35	TEN	35	MTZ-MTZ	UP	HEP Complete loss of HEP at MTZ station, C2106
744	SAC	17	TCC	23	TCC	23	DAV-SAC	UP	PTC - On Board Cab Signal or PTC Failure C6964, Onboard recoverable PTC fault brought the train to a stop in penalty. Required reinitialization and departure test before proceeding. UP PTC ticket number 14189063.
50	NYP	35	FTI	49	FTI	21	REN-LAF	CS	Meet unknown yard, Control Point, Q 115.5
505	PDX	26	DCS	22	DCS	22	CTL-KEL	BN	Power switch failure Switch 2a out of correspondence. Talked by stop signal. Took 2a and f2a in hand. Restricted speed to next signal., Control Point, napavine s
508	SEA	37	PTI	66	PTI	61	SLM-SLM	UP	Waiting for Amtrak 14 to clear from tresser strike Amtrak 14, Milepost, 718.2, 718.2

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 11/30/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
14	SEA	No OS Rpt	ENG	199	TRS	90	SLM-XH3	UP	Trespasser strike Trespasser strike. Trespasser taken in ambulance by EMTs, Other, mp 721.8
8	CHI	38	FTI	75	CON	59	SPK-SPK	BN	Hold for connecting train 28
28	SPK	33	DCS	45	DCS	45	WIH-PSC	BN	Restrictive signal(s) from unknown cause Talked by E McCredie R/S to mp 163.8, Red/stop, Milepost, 158.4, 163.8
335	MKE	58	SYS	68	SYS	44	XRO-SVT	CP	PTC problem or failure (cause unknown) CP RR PTC issues. Auth run cut out PTC 59mph, Control Point, XRO
338	CHI	61	ITI	68	ITI	68	MKE-MKE	CP	Service, turn, or wye train 335, 335 had PTC issues
339	MKE	193	ITI	197	ITI	197	CHI-CHI	AM	Service, turn, or wye train 338
342	CHI	174	ITI	175	ITI	175	MKE-MKE	CP	Service, turn, or wye train 339
350	PNT	100	DSR	8	DSR	6	TRM-PNT	CC	Per bulletin Milepost, 18.4, 19.0, 30, 1, Milepost, 20.0, 21.2, 30, 1, Milepost, 22.86, 22.86, 30, 1
351	CHI	98	WTR	105	WTR	94	KAL-X90	AM	Ice / snow on or under equipment Other, 169
352	PNT	79	ITI	43	ITI	43	CHI-CHI	AM	Train 352 in need of service. 352 was blue flagged while mechanical attached back up hair hose pipe. Train then showed air leak. Mechanical found leak and fixed leak. Train then was able to perform brake test. 352 told to use ITI delay code by glasshouse 352
353	CHI	21	PTI	36	PTI	36	XA5-XB0	MI	Meet am350, Control Point, baron
354	PNT	61	PTI	55	PTI	50	KAL-XGO	MI	Meet Amtrak 355, Control Point, Gord
364	PTH	28	ENG	33	ENG	33	CHI-CHI	AM	Set out defective locomotive Swap out engines, 4623
365	CHI	67	OTH	35	OTH	35	LNS-BTL	CC	Hit blue flag at MP 179.3 and stopped at 178.9 to inspect the train.
580	SAN	19	PTI	11	PTI	9	SOL-OLT	SN	Meet 587, Control Point, Del Mar
586	SAN	59	ITI	37	ITI	37	LAX-LAX	SC	Service, turn, or wye train 784
779	SLO	39	PTI	50	PTI	22	VEC-CPN	UP	Meet 794, Siding, Seacliff
713	OKJ	18	PTI	15	PTI	8	TRK-MOD	BN	Meet amtk 712, Control Point, denair
715	OKJ	54	PTI	43	PTI	12	WAC-COC	BN	Meet Amt 710, Control Point, Allensworth
719	OKJ	26	FTI	16	PTI	10	HNF-FNO	BN	Meet amtrak716, Control Point, calwa
4	CHI	45	SVS	82	FTI	35	FMD-GBB	BN	Meet bnsf 7745, Control Point, Armonde

Amtrak Endpoint OTP Details

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 11/30/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2	NOL	52	FTI	186	FTI	151	XKG-XFA	UP	Disabled freight train Other, MP 153, UP8630
21	SAS	43	FTI	115	ENG	84	STL-STL	TR	Air / Brake Electrical issue with locomotive showing 2lbs of brake pressure still being applied when releasing brake for regular test (securement or running brake.) contacted CNOC mechanical who performed series of resets to computer, verify brakes will perform., 57
22	CHI	Trn Cancelled	FTI	70	FTI	29	XDZ-WNR	UP	Follow up, Milepost w/Letters, Campbell, wnr
300	CHI	17	FTI	18	FTI	11	CRV-SPI	UP	Cross over or go around unknown, Control Point, Auburn
301	STL	18	PTI	16	PTI	16	JOL-BNL	UP	Meet amt 300, Control Point, x045
305	STL	154	RTE	56	RTE	44	SMT-SMT	CC	Dispatcher hold Waiting for train 22 derailment to clear up, Milepost, 11.9, 11.9
306	CHI	138	DMW	156	DMW	156	XUD-SMT	CC	Held for or routed around MW work or equipment CN m/w allowed 3 southbound trains and 1 northbound clearance in affected area. However held the 306 until derailment was cleared., Control Point, lambert
307	STL	64	DCS	64	DCS	64	PON-BNL	UP	Restrictive signal(s) from unknown cause Giving authority passed stop signal at X109. Dispatcher then gave instructions to go restricted speed from X109 to X121, Stop, Control Point, X109
380	CHI	55	FTI	44	FTI	32	MAC-GBB	BN	Cross over or go around Ran us through Galesburg yard, Control Point, saluda, bns6357, mixed
381	QCY	20	FTI	23	FTI	23	KEE-GBB	BN	Follow Follow FTI - stop at Bishop, BNSF, Control Point, Bishop
383	QCY	33	HLD	16	HLD	6	LAG-LAG	BN	High passenger count 25+
390	CHI	19	DSR	21	FTI	12	MAT-CHM	CC	Follow UP2000, Milepost w/Letters, TUSCOLA, CHM
391	CDL	39	DSR	17	DSR	15	HMW-KKI	CC	Per bulletin Milepost, 40.3, 43.2, 25, main, Milepost, 46.2, 47.6, 25, main
392	CHI	40	PTI	34	PTI	27	KKI-HMW	CC	Meet amtrak 59, Siding, peotone
393	CDL	20	DSR	22	SVS	18	CHI-CHI	AM	Pick up equipment Blue flagged, Servicing toilets and dropping rear engine
318	CHI	78	RTE	109	RTE	101	XUD-SMT	CC	Dispatcher hold Derailment at CP Justice congestion due to Amtrak 22, Control Point, Lambert

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-0016700000005503"UNCLASSIFIED"12/17/2025

Region:ALL

Service:ALL

Arriving On:11/30/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1340	CHI	16	ENG	14	ENG	14	MKE-MKE	CP Air / Brake 139	

Amtrak Initial Terminal Details

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 11/30/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	674	11/30	1		
PHL	151	11/30	2		
PHL	630	11/30	3		
RVM	164	11/30	2	2	Restrictive signal(s) from unknown cause Stop signal and yard traffic congestion, Stop signal, Control Point, hermitage
WAS	108	11/30	67	67	Service, turn, or wye train, 161
WAS	128	11/30	5	5	Service, turn, or wye train, 189, AND ADDING A MTR TO NORTH END
WAS	1108	11/30	1		
WAS	2224	11/30	32	32	Service, turn, or wye train, 2265, Due to late inbound 2265
WAS	2226	11/30	40	40	Crew rest, 2247
WAS	2262	11/30	2	2	Kill time to prevent early arrival
ALB	69	11/30	14		
ALB	448	11/29	7	7	Toilet 25049
BON	691	11/30	1		
BON	697	11/30	1		
BOS	165	11/30	3	4	Passenger and/or baggage, had to wait for non-psngr to deboard the train
BOS	2259	11/30	7	7	Other late crew, AM2259 dp BOS 8" late due to the late arrival of crew. Crew were delayed after the earlier incident at PVD
GFD	499	11/30	39		
NFL	284	11/30	1	1	EDR reported wrong departure time. 284 departed at 6:47.
NHV	450	11/30	12	12	Service, turn, or wye train, 405, LATE TRAIN
NHV	460	11/30	6	6	Dispatcher hold, Other, yard, Late release from yard
NYP	107	11/30	95	95	Service, turn, or wye train, 106
NYP	189	11/30	2	2	Passenger and/or baggage
NYP	199	11/30	9	9	Air / Brake, 664/629, STUCK HAND BRAKE ON THE EAST END.
NYP	241	11/30	30	30	Hold for connecting train
NYP	245	11/30	2	2	Usher didn't start boarding until 9 minutes prior to departure with nearly 300 passengers due to keystone train arriving on track 6
NYP	623	11/30	(No OS)		
CHI	21	11/30	137	137	Hold due to passenger train derailment
CHI	48	11/30	225	225	Replace sleeping car 62512, 62522, Train was rearranged to have 448 section restored. Issues with new sleeping car pulled from yard.

Amtrak Initial Terminal Details

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 11/30/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	305	11/30	26	26	Re-crew / job briefing Waited for decree to depart CUS first to rescue train 22 derailment at CP Justice
CHI	339	11/30	197	197	Service, turn, or wye train 338
CHI	341	11/30	3	3	Ice buildup on rear engine needed to be cleared before able to use wiper correctly Other, chi
CHI	352	11/30	43	43	Train 352 in need of service. 352 was blue flagged while mechanical attached back up hair hose pipe. Train then showed air leak. Mechanical found leak and fixed leak. Train then was able to perform brake test. 352 told to use ITI delay code by glasshouse 352
CHI	354	11/30	34	34	Set out defective locomotive 55
CHI	364	11/30	33	33	Set out defective locomotive Swap out engines, 4623
CHI	393	11/30	18	18	Pick up equipment Blue flagged, Servicing toilets and dropping rear engine
MKE	338	11/30	68	68	Service, turn, or wye train 335, 335 had PTC issues
MKE	342	11/30	175	175	Service, turn, or wye train 339
PDX	500	11/30	13	13	Other late crew Late arrival of engineer. Engineer showed up just after departure time, 0646, Other, Portland Station
SEA	8	11/30	6	6	Routine inspections
STL	311	11/30	6	6	Door 48184, Door bypass fault on IDTK 4627. Cut out door bypass per CNOC MECHANICAL.
BFD	703	11/30	1		
BFD	719	11/30	5	5	Hold for thruway bus
LAX	582	11/30	1		
LAX	586	11/30	40	3	Door 6802, Door 7 or 8 red light door issue. Mechanical attempted to fix it. After 3 minutes I called CNOC MECHANICAL to get permission to go in to override
LAX	586	11/30	40	37	Service, turn, or wye train 784
OKJ	716	11/30	8	8	Speedometer +3mph off C6963, Written up submitted by incoming engineer train 711. Not corrected
OKJ	718	11/30	2	2	Loading problem C2001
SAC	702	11/30	2	2	Mobility Impaired 7 ADA pax boarded in SAC
SAC	733	11/30	8	8	Dispatcher hold Held for train 6 to arrive in to Sacramento, Other, Sacramento station

Eastern Region

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	99.5	93.5	93.8	194	1
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 241(30) - New York Penn Station - NY - Hold for Connection

30NOV25: Train 241(30) was delayed at its initial terminal at New York Penn Station due to being held for connections on late arriving Train 156(30).

Train	Delay	Comment
241(30)	30"	

Train 623(30) - Philadelphia, PA - Cab Car Failure

30NOV25: Train 623(30) was delayed at 30th Street Station in Philadelphia due to a mechanical issue with Cab Car 9640. In addition to the brake problem, the HEP was dropped. Management made the decision to wye the train on the outbound at PHL.

Train	Delay	Comment
623(30)	1'04"	

Train 53(30) - North of Rocky Mount, NC - Trespasser Incident/Vehicle Strike

30NOV25: 6:59pm Train 53(30) with E/352 and E357, plus 16 passenger cars and 47 auto carriers, carrying 475 passengers, struck an unoccupied vehicle, while operating southbound on No. 1 track, on the CSX North End Subdivision at MP 87.3, in the City of Halifax, Halifax County, NC, at DOT Grade Crossing # 629656N, Reese's Store Road/SR-1621. The crossing was designated with pavement markings, automated gate arms and mast mounted flashing lights; all of which were operational at the time of the incident. There were no reported injuries to crew or passengers. The lead engine 352 took moderate damage and shut down immediately upon impact. HEP was temporarily lost, then brought back online with the trail engine 357. Lead engine 352 was later brought back online. The weather at the time of the incident was 49° with light to moderate rain. North Carolina State Police responded. Amtrak and CSX Management responded. Once the scene and train were cleared to resume operation by the authorities, Train 53(30) was walked by the vehicle wreckage on No. 2 track. Train 41(29) was delayed due to being held north of the incident scene.

National Response Center Number: 1449151

Train	Delay	Comment
53(30)	2'11"	
41(29)	1'44"	

Train 488(30) - Menden, CT - Police Related

30NOV25: Train 488(30) ddd000006503 on the MR912/17/2025 at MP 16.3, due to a police hold on all tracks ahead. The hold was released after approximately 30 minutes.

Train	Delay	Comment
488(30)	34"	

Train 42(30) North of Philadelphia, PA - Engine Failure

30NOV25: Train 42(30) with E/630,E/129 and 7 cars with 282 passengers onboard was stopped on track 2 at MP 80.1/Bridesburg due to parking brake applied on the rear. Crew was trouble shooting the issues and a Mechanical rider was on scene. Amtrak Road Foreman was enroute. The crew cut out the parking brake and preformed a roll by but it was unsuccessful. Some passengers were transferred to train 106(30) and 670(30) while the crew and mechanical kept working on releasing the brakes. Several trains were delayed due to picking up the passengers off train 42(30) they were transferred to trains 106(30), 670(30), 20(29) and 156(30).

UPDATE: As of 513P-ET, The protection on track 3 was released train 42(30) did successfully cut out the parking brake and performed a good roll by. Train 670(30) was also back on the move with no passenger transfer.

Train	Delay	Comment
670(30)	48"	
42(30)	1'14"	
106(30)	40"	
20(29)	33"	
156(30)	28"	
2262(30)	19"	
667(30)	04"	
2247(30)	02"	
2253(30)	05"	
107(30)	1'35"	LATE TURN OFF 106(30)

Train 2263(30) Providence, RI - Car Failure

30NOV25: As of 915A-ET, Chief "UNCLASSIFIED" 12/17/2025
PC/2037, PC/2006 was in Providence station with reports of heavy smoke coming from the wheels of C/3538. The PC/2006 was offline due to being do not lead for ATC. Amtrak Road Foreman and Mechanical was on scene. They took the power from the train to access the problem. All 220 passengers were deboarded at MP 185.1/Providence station. There were no reports of open flames and the Providence Fire Department was enroute. The station manager and Amtrak Police were instructed to evacuate the station. About 15 passengers were transferred to train 99(30). Rescue protect engine arrived and was used to couple to the High Speed set to drag out of the station. Train 2263(30) was terminated at Providence. As of 955A-ET, The local Fire Department placed a hold on all tracks and evacuated the station. The remaining passengers were accommodated to trains 2265(30), 161(30) and 87(30) once the station was reopened. Service recovery was initiated on trains 2265(30), 161(30) and 87(30) due to the termination of 2263(30). As of 1034A-ET, Acela 2263(30) equipment was clear of the station and advanced to Brayton Interlocking for the Fire Department to inspect. As of 1025A-ET, The Power Director reported an emergency plate was placed at Providence station and ET was on scene. As of 1115A-ET, Fire Department released track 2 at Providence station and allowed east bound 2290(30) and 150(30) followed by 4 west bounds 2265(30), 161(30) and 87(30) picking up 2263(30) passengers then 2247(30). At 1132A-ET, There was a 30MPH speed restriction between MP 184.9/Brayton and MP 183.5/Atwells due to foam being sprayed for disabled 2263(30). As of 1211P-ET, The 30MPH speed restriction was lifted. The preliminary cause of the smoke was hydraulic fluid leaking in the tilt system of C/3538.

Train	Delay	Comment
2263(30)	TERM PVD	
2265(30)	1'40"	
150(30)	35"	
161(30)	1'17"	
2247(30)	1'06"	
2290(30)	28"	
87(30)	1'09"	
99(30)	29"	
2292(30)	15"	
2253(30)	19"	
3 MBTA's	17"-27"	
2224(30)	32"	late turn off 2265(30)
2226(30)	40"	Turn off 2247(30)
108(30)	1'07"	Turn off late 161(30)

Train 63/69(30) North of New York, NY - Engine Failure

30NOV25: As of 731A-ET, Train 63/69(30) combo with E/112, E/716 and 10 cars with a total of 417 passengers onboard reported that E/112 shut down and they without HEP. PSCC was getting the rescue E/700 readied. As of 800A-ET, The crew was able to reset E/112 and proceed north with the rescue E/700 following. Albany rider was able to get off train 232(30) and on the 63/69(30) combo. Crew reported that the passengers were comfortable. Train 232(30) was also delayed due to holding for a route.

Train	Delay	Comment
63/69(30)	51"	
232(30)	32"	

26 JUL 2016 14:00:05Z UNCLASSIFIED 12/17/2025
Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-28Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

23OCT25: Train 448(29NOV) and Train 449(01DEC) will be the first trains operating normal when service resumes on 30NOV.

WBS#: B.TR.100150.5746

Eastern Region

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (24)	RMT	326		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

none

Operating Highlights***Train 352(30) East of Jackson, MI - Passenger Train Interference***

01DEC25: Train 352(30) was delayed at control point 72/MP72.7 3 miles east of Jackson, MI/MP75.5 on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(30). Once the route was clear, train 352(30) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(30)	30"	

Train 3(29) East of Gallup, NM - Freight Train Interference

01DEC25: Train 3(29) was delayed between mile post 90.5 and mile post 144.2 beginning 67 miles east of Gallup, NM/MP157.5 on the BNSF Gallup subdivision following BNSF freight BN/6238. Once the route was clear, train 3(29) continued into Gallup, NM.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(29)	35"	

Train 307(30) South of Chicago, IL - Freight Train Interference

01DEC25: Train 307(30) was delayed at Brighton/MP5.1 5 miles south of the Chicago Union Station, IL/MP0.0 on the CN Joliet subdivision meeting freight cross traffic. Once the route was clear, train 307(30) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
307(30)	36"	

Train 364(30) Kalamazoo, MI - Trespasser Incident

01DEC25: At 7:38PM CT, train 364(30), with engines IDTX4621 and IDTX4625, 6 cars, and 339 passengers, struck a trespasser while entering Kalamazoo Station, MI/MP143.4 on the Michigan Department of Transportation Michigan Line subdivision. There were no injuries reported by the passengers or crew and no damage to the equipment. HEP remained active. The weather was 27 degrees and partly cloudy. Kalamazoo Police and emergency responders arrived on scene. The trespasser was on her feet and walking around. Kalamazoo Police determined that only her bag had been clipped by train 364(30) but declared the incident a trespasser strike. The trespasser refused medical treatment. Once the scene was released, train 364(30) completed their station work and departed Kalamazoo, MI.

National Response Center Number: 1449152

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(30)	23"	

Train 7/27(29) East of Glasgow, MT - Freight Train Interference

01DEC25: Train 7/27(29) was delayed at Glasgow siding/MP275.9 2.4 miles east of Glasgow, MT/MP277.5 on the BNSF Glasgow subdivision meeting multiple BNSF freights, BN/8018, BN/7857, and BN/3381. Once the route was clear, train 7/27(29) continued into Glasgow, MT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(29)	43"	

Train 354(30) Chicago, IL - Servicing

01DEC25: Train 354(30) was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late release of the equipment by Chicago Mechanical. Engine 55 was cut off of inbound train 353(30) and held off for train 21(01). Replacement engine IDTX4613 was added to the consist and then released by Chicago Mechanical. Train 354(30) shoved to the depot, boarded passengers, and departed Chicago Union Station, IL.

Train	Delay	Comment
354(30)	33"	

Train 364(30) Chicago, IL - Servicing

01DEC25: Train 364(30) was delayed departing Chicago Union Station, IL/MP0.0 due to the late release by Chicago Mechanical. Engine IDTX4623 was cut off of inbound train 365(3), which arrived one hour and seven minutes late, for maintenance. The replacement engine IDTX4625 was added to the consist. Once the equipment was released, train 364(30) shoved into the depot, boarded passengers, and departed Chicago Union Station, IL.

Train	Delay	Comment
364(30)	33"	

Train 5(30) West of Naperville, IL - Freight Train Interference

01DEC25: Train 5(30) was delayed between Bristol/MP45.8 and Electrics/MP80.5 beginning 17 miles west of Naperville, IL/MP28.5 on the BNSF Mendota subdivision following BNSF freight. Once the route was clear, train 5(30) continued west.

Train	Delay	Comment
5(30)	35"	

Train 7/27(29) Minot, ND - Servicing

01DEC25: Train 7/27(29), with engines 372, 311, and 369, 10 cars, and 100 passengers, was delayed departing Minot, ND/MP0.5 on the BNSF Glasgow subdivision due to routine inspections requiring additional time to complete. Once the inspection was completed, train 7/27(29) departed Minot, ND.

Train	Delay	Comment
7/27(29)	35"	

Train 353(30) East of Battle Creek, MI - Passenger Train Interference

01DEC25: Train 353(30) was delayed at Baron/MP176.7 1 mile east of Battle Creek, MI/MP175.74 on the CN South Bend subdivision meeting Amtrak train 350(30). Once the route was clear, train 353(30) continued west.

Train	Delay	Comment
353(30)	36"	

Train 7/27(29) East of St. Paul-Minneapolis, MN - Servicing

01DEC25: Train 7/27(29) was delayed at Hoffman/MP408.9 1.5 miles east of St Paul-Minneapolis, MN/MP410.3 on the CPKC BN St Paul subdivision due to switch failure. Four power switches had to be hand lined and then returned to their original positions. Once clear of the area, train 7/27(20) continued west.

Train	Delay	Comment
-------	-------	---------

Train 5(29) East of Holdrege, NE - Signal

01DEC25: Train 5(29) was delayed at 0000005503 East of Holdrege, NE/MP210.9 on the BNSF Hastings subdivision due to power switch failure. The crew had to hand line the switch into position. Once through the affected area, train 5(29) continued west.

Train	Delay	Comment
5(29)	47"	

Train 14(29) North of Salem, OR - Trespasser Incident

30NOV25: At approximately 5:12 PM-PT, train 14(29) - operating with UPRR/7156, AMTK/313, AMTK/349 and 9 cars - struck and injured a trespasser at MP 721.8 on the Union Pacific Railway Brooklyn Subdivision in the city of Salem, Marion County, Oregon. This incident did NOT occur on a public highway crossing at grade. Train 14(29) was operating northbound on the main track at an estimated 61 MPH with a posted track speed of 79 MPH. There were no initial reports of injuries to passengers (242) or crew and no damage to Amtrak equipment. Tracks were closed while emergency services responded and investigated the scene. Local Police, Fire, and Union Pacific Railway Management responded to the scene. Once the scene was released by officials train 14(29) advanced to the siding track, clear of the main line at Gervais to wait for a relief crew to arrive. Once the relief crew arrived, train 14(29) was able to proceed.

National Response Center: 1449153

Oregon Office of Emergency Services: 2025-2944

Google Maps Location of Incident:

<https://maps.app.goo.gl/oGCWaJLfrNwcUL5B8>

44.978909, -123.003392

Northgate, Salem, OR

National Response Center Number: 1449153

Train	Delay	Comment
508(30)	1'01"	Hold for route
14(29)	1'14"	Hold for relief crew
507(30)	10"	Hold for route
14(29)	1'30"	Trespasser Incident

Train 784(30) Simi Valley, CA - Commuter Train Interference

30NOV25: Train 784(30) was delayed at Simi Valley, CA (SIM) on the Southern California Regional Rail Authority (Metrolink) Ventura Subdivision. There was a disabled Metrolink commuter train at SIM, ML/1162, blocking the single main track. Train 784(30) assisted the disabled train by coupling to and pushing the disabled train south into the siding track at Simi Valley. Once the disabled train was pushed clear of the main, train 784(30) was able to resume travel south at 5:09 PM-PT. Account the delays incurred to train 784(30) the following recovery plan was enacted:

- "on-time" section of train 784(30) operated from Los Angeles, CA to San Diego, CA using 586(30) equipment.
- 586(30) used inbound equipment from train 784(30) Los Angeles, CA to San Diego, CA.

Train	Delay	Comment
784(30)	1'37"	Assist Metrolink 1162
784(30)	03"	On-time section LAX-SAN
586(30)	40"	LAX - Hold for inbound equipt from original 784(30)

Train 737(30) Martinez, CA - Third Party Contractor Engine Failure

30NOV25: Train 737(30) delayed at Martinez, CA (MTZ) on the Union Pacific Railway Martinez Subdivision. There was a problem with locomotive CDTX/2106 where the locomotive failed to provide head end power (HEP). Passengers were able to exit the train and wait in the station lobby and use station facilities while the train crew worked with division management and the mechanical contractor to resolve the problem. Once the issue was resolved, train 737(30) was departed MTZ at 12:34 PM-PT.

Service Recovery: 10% Cafe Car Discount

Duration of HEP loss: ~30"

Train	Delay	Comment
737(30)	35"	

Train 335(30) West of Glenview, IL - PTC

30NOV25: Train 335(30), E/IDTX4603-4 cars-E/514, was delayed west of Glenview, IL/MP17.32, on the CPKC C&M Subdivision, due to E/IDTX4603 PTC failure. Train 335(30) was delayed enroute to Milwaukee, WI, operating 59MPH Max. Train 338(30) was delayed departing Milwaukee due to late turn of equipment off Train 335(30). Train 339(30) was delayed departing Chicago due to late turn of equipment off Train 338(30) and necessary to cap E/IDTX4603 with E/56. Train 342(30) was delayed departing Milwaukee due to the late arriving 339(30).

Train	Delay	Comment
335(30)	1'12"	
338(30)	1'08"	MKE, late turn of equip off 335(30)
339(30)	3'17"	Late turn of 338(30), changing engines
342(30)	2'55"	

Train 22(29) North of Joliet, IL - Engine Derailment

30NOV25: Approximate 26:18 PM 11/25/2025 Train 22(29) E/68 and 39031 cars, with 253 passengers, reported E/68 derailed at Justice/MP15.3, 21 miles north of Joliet, IL, in Cook County, on the CN Joliet Subdivision. The engineer of Amtrak train 22(30) was given verbal authority from the CN Dispatcher to pass the stop signal at CP Justice from Main 2 to Main I. The switch was gapped resulting in the derailment of locomotive E/68 and the first axle of the first car C/39031. E/68 both trucks and the first axle of car 39031 derailed in the cross-over at MP15.3 while Train 22(29) was operating at slow speeds Main 1 to Main 2. E/68 and C/39031 were upright and HEP remained up and running. There were no reported injuries to passengers or crew. CN reported both Mains initially blocked and no route through the area. Central Northwest Division transportation, mechanical, customer service and APD all responded to the location.

Alternate transportation secured and staged at Willow Springs Metra station, approximately 2 miles south of location. Train 21/421(30) was delayed departing Chicago, holding for dispo of recovery plan for Train 22(29). Train 21/421(30) stopped at Willow Springs, shoved back to the on-rail portion of train 22(29), coupled to the equipment, and advanced to Willow Springs. Passengers were reaccommodated on five busses to destination. Train 21/421(30) cut off the portion of train 22(29) and continued south. The rescue locomotive, E/517 operated lite Chicago to Willow Springs for the non derailed portion of Train 22(29) consist. Train 22(29) was terminated at the location. E/517 tied on to the 6 cars of Train 22(29) at Willow Springs and pulled cars south to Willow Springs station where . E/68 remained at location. Hulcher was estimated to arrive on scene at approximately 400PM-CT.

Lincoln Service trains 305(30), 307(30), and 318(30) was delayed holding for open track through the area of the derailment. Train 306(30) was delayed at Lemont, IL/MP21.9 holding for open track while engine 68 and car 39031 were rerailed.

Due to the late operation train 21/421(30), the following service recovery was put into effect:

- Snack packs, as well as water, coffee, juice, were distributed among all passengers. Discounted items on the cafe car were also available.
- The cafe car was kept open to allow all passengers to get something to eat.

Rescue engine 517 picked up 6 cars at Willow Springs and then engine 68 and car 39031 after rerailing was completed at mile post 15.3. The equipment then returned to Chicago, IL at restricted speed.

NRC 1449138
WBS B.TR.100150.6281

WBS#: B.TR.100150.6281

National Response Center Number: 1449138

Train	Delay	Comment
22(29)	Terminated N/JOL	
305(30)	26"	CUS waiting behind rescue E/517
305(30)	39"	Restrictive speed through the area
305(30)	44"	SMT holding for open track
318(30)	1'41"	Holding for open track
306(30)	2'35"	Holding for open track
21/421(30)	2'17"	CHI
21/421(30)	2'56"	Assisting 22(29)
307(30)	53"	Holding for open track

Train 4(28) West of Galesburg, IL - Freight Train Interference

30NOV25: Train 4(28) was delayed at Ormonde/MP191.9, 14 miles west of Galesburg, IL, on the BNSF Chillicothe Subdivision, meeting BNSF 7745.

Train	Delay	Comment
4(28)	35"	

Train 302(30) North of Carlinville, IL - Air Hose Separation

30NOV25: Train 302(30), E/IDTX4606-5 cars-E/IDTX4606, was delayed at MP210, 13 miles north of Carlinville, IL, on the UPRR Springfield Subdivision, due to an air hose separation between the second and third cars, C/ID4105 and C/ID4013. Train 302(30) was on the move north after crew secured hose and performed brake test.

Train	Delay	Comment
302(30)	10"	

Train 58(29) South of Carbondale, IL - Passenger Train Interference

30NOV25: Train 58(29) was delayed at S. Anna/MP327.8, 19 miles south of Carbondale, IL, on the CN Centralia Subdivision, in the siding behind CN G897 to meet Train 59(29). Once Train 59(29) cleared, Train 58(29) shoved out of siding and proceeded north.

Train	Delay	Comment
58(29)	54"	

Train 365(30) East of Battle Creek, MI - M of W Work

30NOV25: Train 365(30), E/IDTX4623-6 cars-E/IDTX4621, was delayed at MP178.9, 4 miles east of Battle Creek, MI, on the CN Flint Subdivision, due to striking a CN MW blue flag. Train 365(30) reported operating on limited clear signals when the snow covered blue flag was struck. There were no damages and no exceptions to the equipment reported. CN dispatcher took no exceptions to Train 365(30) resuming movement through the area once train was inspected.

Train	Delay	Comment
365(30)	35"	

Train 351(30) West of Kalamazoo, MI - Air Hose Separation

30NOV25: Train 351(30), E/IDTX4632-5 cars-E/63, with 279 passengers, stopped in emergency at MP169.1, 25 miles west of Kalamazoo, MI, on the Amtrak Michigan Line. Crew inspected consist and reported snow and ice build up under cars, and air hoses separated between the 3rd and 4th cars, C/ID4116 and C/ID4312. There were no other exceptions to equipment reported. Crew reported glad hand damaged on C/4116 and difficulty removing and changing out hoses. MW was in the vicinity and assisted crew. Once hoses were replaced and air restored, Train 351(30) was able to proceed west. Trains 350(30) and 365(30) were delayed holding for Train 351(30) to restore air and operate in the clear ahead.

Train 352(30) was delayed departing the Chicago, IL Union Station due to servicing late inbound Train 351(30) and a planned move to set out E/IDTX4632 for Train 305(30). Train 351(30) had arrived in Chicago at 12:10 p.m. (CST), 1 hour and 38 minutes late.

Train	Delay	Comment
351(30)	1' 34"	
365(30)	35"	
352(30)	43"	CHI - Service Late Inbound 351(30)
350(30)	1' 52"	

Train 380(30) West of Galesburg, IL - Freight Train Interference

30NOV25: Train 380(30) was delayed at Grand Saline/MP173.6, 15 miles west of Galesburg, IL, on the BNSF Brookfield Subdivision, meeting BNSF 6357, and then crossing over to route through Galesburg yard. BNSF reported congestion through the area due to previous broken rail at MP173.6 and winter action plan in effect, limiting meet locations.

Train	Delay	Comment
380(30)	17"	W/GBB, MP173.6
380(30)	32"	

Train 21(29) West of Mineola, TX - Freight Train Interference

30NOV25: Train 21(29) was delayed at Grand Saline/MP151.5, 15 miles west of Mineola, TX, on the UPRR Mineola Subdivision, due to UP5840 ahead completing repairs to a broken knuckle. Upon completion of repairs, UP5840 reported a second bad knuckle and necessary to repair prior to clearing route. Train 21(29) was delayed holding for UP 5840 to repair both bad order knuckles and operate in the clear.

Train	Delay	Comment
21(29)	1'18"	

Train 2(28) East of San Antonio, TX - Stalled Freight Ahead

30NOV25: Train 2(28), with 142 passengers, was delayed at Kingsbury/MP161.7, 43 miles east of San Antonio, TX, on the UPRR Glidden Subdivision, due to UP8630 stalled ahead at MP153.

Train	Delay	Comment
2(28)	2'31"	

Train 8/28(29) East of Libby, MT - Disabled Freight Ahead

30NOV25: Train 8/28(29), with 181 passengers, was delayed at MP1262.8, 58 miles east of Libby, MT, on the BNSF Kootenai River Subdivision, due to BNSF 3895 stopped on the grade ahead with a bad order knuckle. BNSF mechanical responded to assist. Due to BNSF crew on short-time, a BNSF recrew also responded to scene. As BNSF recrew was putting consist back together after the knuckle replacement, crew reported a wrong-end drawbar. Train 8/28(29) was then further delayed holding for completion of repairs and for BNSF freight to operate in the clear.

WBS#: B.TR.100150.6280

Train	Delay	Comment
8/28(29)	4'31"	

Train 49(29) East of Elkhart, IN - Near Miss with Vehicle

30NOV25: Train 49(29), E/124-E/99 & 11 cars, stopped in emergency at MP413.97, 8 miles east of Elkhart, IN, on the NS Toledo-Elkhart Subdivision, due to a near miss with a vehicle that drove around crossing gates. There were no reported injuries to passengers (342) or crew. The crew inspected consist and took no exceptions. Train 49(29) was on the move west after air restored and brake test performed.

Train	Delay	Comment
49(29)	17"	

Train 3(28) East of Barstow, CA - Freight Train Interference

30NOV25: Train 3(28) was delayed at Ludlow/MP69.1, 54.1 miles east of Barstow, CA, on the BNSF Needles Subdivision, due to BNSF freight ahead with a container fire and a hold on all traffic through the area. Train 3(28) was delayed holding for fire to be extinguished and hold released. Train 3(28) was further delayed operating restricted speed through the area.

Train	Delay	Comment
3(28)	1'18"	

Train 8/28(29) Spokane, WA - Servicing

30NOV25: Train 8/28(29) was delayed departing Spokane, WA/MP71.6 on the BNSF Spokane subdivision completing routine inspections. Once the inspections were complete, train 8/28(29) departed Spokane, WA.

Train	Delay	Comment
8/28(29)	41"	

Train 48(29) West of Toledo, OH - Freight Train Interference

30NOV25: Train 48(29) was delayed at mile post 288.0 0.2 miles west of Toledo, OH/MP288.2 on the NS Cleveland-Toledo subdivision meeting NS freight 22M. Once the route was clear, train 48(29) continued east.

Train	Delay	Comment
48(29)	30"	

Train 14(29) Sacramento, CA - Battery Charger Failure

30NOV25: Train 14(29), E/313-E/349 & 9 cars, was delayed at Sacramento, CA/MP89.1 on the UP Martinez subdivision troubleshooting a battery charger failure on engine 349. HEP was moved to the leader 313 to maintain HVAC for passengers. The crew worked with Siemens technicians over the phone but were unable to restore functionality to the battery charger. Engine 349 was set up dead-in-tow and train 14(29) departed Sacramento, CA. Train 14(29) was delayed at Culp/MP244.9, 14 miles south of Redding, CA, on the UPRR Valley Subdivision, adding UPRR E/UP7156 ahead due to the battery charger issue on trail E/349.

Train	Delay	Comment
14(29)	59"	SAC
14(29)	1'25"	S/RDD, add UP E/UP7156

Train 5(29) East of Omaha, NE - Signal

30NOV25: Train 5(29) was delayed at West Pacific Junction/MP0.2 16.5 miles east of Omaha, NE/MP16.7 on the BNSF Creston subdivision due to a power switch failure. BNSF signal maintainers responded and repaired the switch. Once the route was clear, train 5(29) continued west.

Train	Delay	Comment
5(29)	56"	

Train 21(29) St. Louis, MO - Engine Failure

30NOV25: Train 21(29) failed at St. Louis, MO/MP1.5 on 12/17/2025 TRRA Merchants subdivision troubleshooting possible trapped air preventing the brakes from fully releasing. The crew worked with an Amtrak Road Foreman and CNOC Mechanical Desk over the phone. The crew confirmed that the brakes were releasing as intended. After passing air and brake tests, train 21(29) departed St Louis, MO.

Train 21(29) was further delayed at Ft Worth, TX/MP346.2 adding engine 30 to the head of the consist after engine 59 failed to pass a daily inspection.

Train	Delay	Comment
21(29)	1'24"	
21(29)	1'08"	Adding E/30 at FTW

Western Region

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
NONE				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 48(29) Passenger Denied Travel at South Bend, Indiana – Other

29NOV25, Passenger on PNR EFDDEE, was reportedly denied travel due to attempting to board with a large cello which she did not have a ticket for. Due to train capacity, there was not anywhere to safely place the instrument. Amtrak Police notified.

Delay: 48(29) 02"

Train 8(29) Passenger Removed at Spokane, Washington – Improper Conduct

30NOV25, Passengers on PNR 4FDD99, traveling from Edmonds, WA to Libby, MT were removed at Spokane, WA. While train 8(29) started switching moves, Passenger Maggie was on the platform, John who was onboard pulled the emergency brake valve. Crew was informed John has Alzheimer and didn't know where Maggie's whereabouts. Crew had further safety concerns if the party continued to travel this evening. Passengers were removed without any further incident. Amtrak Police notified.

Delay: 8(29) NONE

Train 765(30) Passenger Removal at Anaheim, California – Fare Evader

26-FOI-00167 00000005503 "UNCLASSIFIED" 12/17/2025

30NOV25, 2 unticketed passengers, boarded train at Irvin, CA destined for Los Angeles, CA. Passengers unable to provide a ticket or valid reservation for passage. Conductor instructed passengers at next stop to exit the train and purchase tickets. Passengers became irate and threatening. Police requested passengers both exited the train Anaheim, CA. Amtrak Police notified.

Delay: 765(30) 4"

Consist Deviations

26-FOI-00167

00000005503

"UNCLASSIFIED"

12/17/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
--------------	---------	--------	-----------------	---------------	----------------

Reverse Consists

Train Number	Station	Reason
66 (30)	RNK	Business class change only Business class seating orientation may have changed At Rear
151 (30)	PHL	Business class change only Business class seating orientation may have changed At Rear
145 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front
132 (30)	WAS	Consist reversed Business class seat orientation may have changed At Front
103 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front
2222 (30)	WAS	Acela consist reversed First class at Front
2222 (30)	WAS	Acela consist reversed First class at Front