



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, July 25, 2026

Rules: 4-41



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	52	84.2%	7,406	1,109	85.0%	88,760	12,230	86.2%
Central Division	86.0%	59	6	89.8%	1,335	134	90.0%	17,026	1,525	91.0%
East Division	82.0%	177	27	84.7%	3,909	647	83.4%	46,505	7,260	84.4%
West Division	86.0%	93	19	79.6%	2,162	328	84.8%	25,229	3,445	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00621 00000008478 UNCLASSIFIED 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	114,471	33,827	70%	2,607,831	920,838	65%	29,555,155	7,395,124	75%
Northeast Corridor	81%	46,913	10,508	78%	1,118,965	394,136	65%	12,962,746	3,177,329	75%
Acela	83%	11,822	3,229	73%	250,877	84,286	66%	2,587,642	686,963	73%
Northeast Regional	79%	35,091	7,279	79%	868,088	309,850	64%	10,375,104	2,490,366	76%
Richmond / Newport News / Norfolk	77%	12,089	2,873	76%	270,489	122,722	55%	3,221,217	936,343	71%
Springfield Shuttles	89%	715	298	58%	15,906	4,799	70%	183,940	29,013	84%
Roanoke	79%	4,354	1,120	74%	85,287	35,790	58%	978,347	211,075	78%
On Spine Northeast Regional	80%	17,933	2,988	83%	496,406	146,539	70%	5,991,600	1,313,935	78%
State Supported	80%	54,061	15,342	72%	1,175,144	331,790	72%	12,961,192	2,694,154	79%
Borealis	80%	607	190	69%	14,376	2,803	81%	165,346	33,249	80%
Capitol Corridor	90%	3,781	900	76%	91,288	13,592	85%	1,092,507	142,788	87%
Carolinian	70%	1,165	334	71%	26,997	16,506	39%	336,971	132,412	61%
Cascades	75%	2,851	834	71%	74,170	19,666	73%	761,814	208,226	73%
Downeaster	82%	2,217	3	100%	47,490	9,078	81%	444,988	54,548	88%
Empire	78%	7,149	1,093	85%	149,365	51,988	65%	1,603,370	366,405	77%
Adirondack	72%	491	1	100%	10,579	4,206	60%	97,012	29,690	69%
Ethan Allen Express	70%	661	8	99%	14,138	9,696	31%	165,103	57,303	65%
Maple Leaf	70%	1,130	221	80%	20,450	8,263	60%	195,269	75,050	62%
New York - Albany	85%	2,792	144	95%	66,957	14,720	78%	744,122	118,620	84%
New York - Niagara Falls	75%	1,531	719	53%	33,474	13,000	61%	394,933	82,779	79%
Berkshire Flyer	60%	544	0	100%	3,767	2,103	44%	6,931	2,963	57%
Gold Runner	73%	2,997	2,432	19%	62,806	28,106	55%	736,426	260,204	65%
Heartland Flyer	70%	395	393	1%	6,793	4,040	41%	62,498	24,533	61%
Hiawatha	90%	2,369	19	99%	49,192	3,896	92%	506,886	54,444	89%
Illinois	78%	3,134	1,074	66%	64,395	22,257	65%	726,550	198,301	73%
Carl Sandburg / Illinois Zephyr	85%	486	277	43%	11,652	4,518	61%	121,206	32,324	73%
Illini / Saluki	85%	981	229	77%	20,685	6,890	67%	254,347	60,917	76%
Lincoln Service	70%	1,667	568	66%	32,058	10,849	66%	350,997	105,060	70%
Keystone	92%	8,452	936	89%	181,413	25,973	86%	2,238,490	235,908	89%
Lincoln / Missouri	70%	930	308	67%	18,421	10,912	41%	226,940	114,728	49%
Mardi Gras Service	80%	470	312	34%	9,070	3,896	57%	120,018	26,357	78%
Michigan	70%	2,574	971	62%	59,206	21,396	64%	578,953	186,351	68%
Blue Water	70%	353	0	100%	14,647	8,367	43%	134,873	53,701	60%
Pere Marquette	85%	430	0	100%	8,534	1,483	83%	76,106	14,813	81%
Wolverine	70%	1,791	971	46%	36,025	11,546	68%	367,974	117,837	68%
Missouri	80%	338	95	72%	5,087	2,022	60%	64,323	15,262	76%
Pacific Surfliner	85%	11,216	4,687	58%	244,902	67,064	73%	2,327,426	394,226	83%
Pennsylvanian	80%	958	32	97%	20,885	7,506	64%	259,595	49,665	81%
Piedmont	80%	1,205	729	40%	19,320	8,484	56%	332,705	87,038	74%
Vermont	75%	1,253	0	100%	29,968	12,605	58%	375,386	109,509	71%
Long Distance	70%	13,497	7,977	41%	313,722	194,912	38%	3,591,950	1,521,178	58%
Auto Train	70%	815	442	46%	19,641	7,352	63%	228,485	78,180	66%
California Zephyr	70%	1,074	428	60%	25,159	16,719	34%	285,222	102,016	64%
Cardinal	70%	298	170	43%	6,089	4,183	31%	69,763	34,425	51%
City Of New Orleans	75%	818	660	19%	8,732	5,241	40%	186,096	54,858	71%
Coast Starlight	70%	1,907	1,300	32%	30,474	12,233	60%	335,238	116,685	65%
Crescent	70%	449	132	71%	21,868	12,341	44%	272,361	84,433	69%
Empire Builder	70%	1,335	1,058	21%	30,314	18,948	37%	283,375	137,700	51%
Floridian	60%	760	742	2%	35,670	33,304	7%	465,835	316,947	32%
Lake Shore Ltd	73%	1,336	248	81%	28,901	10,445	64%	280,538	82,055	71%
Palmetto	70%	957	360	62%	21,865	13,785	37%	269,638	79,883	70%
Silver Meteor	70%	1,068	1,011	5%	25,513	21,728	15%	297,894	131,880	56%
Southwest Chief	60%	1,076	871	19%	24,385	17,818	27%	243,035	156,230	36%
Sunset Ltd	70%	418	245	41%	7,839	4,375	44%	86,224	31,056	64%
Texas Eagle	70%	1,186	310	74%	27,272	16,440	40%	288,246	114,830	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00021 00000000470 "UNCLASSIFIED" 07/2020

Train Index Dates Through July 24, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	172,730	2,563,465	674	1,740,262	31,195,698	558

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	10,290	759,886	135	83,680	8,969,363	93
INFRASTRUCTURE PLANNED	135	12,547	759,886	165	91,447	8,969,363	102
FLEET RELIABILITY	90	25,782	2,563,465	101	279,032	31,195,698	89
TRAIN OPERATIONS	424	124,111	2,563,465	484	1,286,103	31,195,698	412

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

26-FOI-006Initial Terminal Performance By Division

Scheduled Departure Date:	07/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	52	84.2%	7,406	1,109	85.0%	88,760	12,230	86.2%
Central Division	86.0%	59	6	89.8%	1,335	134	90.0%	17,026	1,525	91.0%
East Division	82.0%	177	27	84.7%	3,909	647	83.4%	46,505	7,260	84.4%
West Division	86.0%	93	19	79.6%	2,162	328	84.8%	25,229	3,445	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	52	84.2%	7,406	1,109	85.0%	88,760	12,230	86.2%
Central Division	86.0%	59	6	89.8%	1,335	134	90.0%	17,026	1,525	91.0%
CDL	95.0%	2	1	50.0%	45	5	88.9%	562	23	95.9%
CHI	86.0%	28	3	89.3%	628	76	87.9%	7,865	939	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	24	1	95.8%	320	35	89.1%
GBB	-	1	1	0.0%	13	11	15.4%	13	11	15.4%
GRR	95.5%	1	0	100.0%	23	0	100.0%	282	8	97.2%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	39	3	92.3%	577	43	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	141	9	93.6%	1,739	106	93.9%
MOE	97.5%	2	0	100.0%	46	1	97.8%	591	9	98.5%
MSP	96.5%	1	0	100.0%	24	0	100.0%	290	5	98.3%
NOL	94.5%	4	0	100.0%	93	6	93.5%	1,243	59	95.3%
OKC	97.0%	1	0	100.0%	24	0	100.0%	291	6	97.9%
PNT	88.0%	3	0	100.0%	63	6	90.5%	766	64	91.6%
PTH	93.0%	1	0	100.0%	24	1	95.8%	285	11	96.1%
QCY	91.0%	1	0	100.0%	32	3	90.6%	563	43	92.4%
SAS	90.5%	1	1	0.0%	24	4	83.3%	293	31	89.4%
STL	89.0%	4	0	100.0%	91	7	92.3%	1,148	97	91.6%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	177	27	84.7%	3,909	647	83.4%	46,505	7,260	84.4%
ALB	88.5%	7	0	100.0%	185	8	95.7%	2,199	169	92.3%
ATL	-	-	-	-	1	1	0.0%	36	6	83.3%
BON	87.5%	5	0	100.0%	119	14	88.2%	1,431	154	89.2%
BOS	85.5%	18	1	94.4%	401	31	92.3%	5,041	593	88.2%
BRK	92.5%	5	0	100.0%	116	18	84.5%	1,417	102	92.8%
BTN	82.0%	1	0	100.0%	24	1	95.8%	283	40	85.9%
CLT	91.5%	5	1	80.0%	101	18	82.2%	1,442	150	89.6%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	48	7	85.4%	579	57	90.2%
GRO	-	-	-	-	4	0	100.0%	33	10	69.7%
HAR	79.5%	13	0	100.0%	262	36	86.3%	3,285	542	83.5%
HFD	-	2	0	100.0%	34	5	85.3%	181	13	92.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	24	2	91.7%	293	36	87.7%
MIA	89.5%	2	1	50.0%	47	7	85.1%	586	67	88.6%
MTR	79.0%	1	0	100.0%	24	4	83.3%	280	50	82.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/24/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/24/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	52	84.2%	7,406	1,109	85.0%	88,760	12,230	86.2%
East Division	82.0%	177	27	84.7%	3,909	647	83.4%	46,505	7,260	84.4%
NFK	84.5%	2	0	100.0%	48	12	75.0%	669	121	81.9%
NFL	93.5%	2	1	50.0%	48	4	91.7%	598	26	95.7%
NFS	-	-	-	-	1	1	0.0%	7	6	14.3%
NHV	78.0%	5	2	60.0%	116	24	79.3%	1,522	247	83.8%
NPN	93.0%	2	0	100.0%	46	5	89.1%	559	40	92.8%
NYP	75.5%	51	7	86.3%	1,105	250	77.4%	12,159	2,711	77.7%
PGH	93.0%	1	0	100.0%	23	3	87.0%	294	22	92.5%
PHL	48.0%	5	2	60.0%	117	50	57.3%	1,517	727	52.1%
PIT	76.0%	1	0	100.0%	7	6	14.3%	13	11	15.4%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	4	1	75.0%	73	7	90.4%	1,130	48	95.8%
RNK	83.5%	2	0	100.0%	48	8	83.3%	582	85	85.4%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	21	1	95.2%	280	5	98.2%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	22	0	100.0%	290	10	96.6%
SFA	88.0%	1	0	100.0%	24	2	91.7%	293	39	86.7%
SPG	92.5%	5	1	80.0%	119	12	89.9%	1,771	104	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	23	2	91.3%	282	58	79.4%
WAS	84.0%	31	9	71.0%	674	104	84.6%	7,270	945	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	93	19	79.6%	2,162	328	84.8%	25,229	3,445	86.3%
ARN	92.0%	1	1	0.0%	24	6	75.0%	295	25	91.5%
BFD	79.0%	7	3	57.1%	163	40	75.5%	1,849	381	79.4%
EMY	72.0%	1	1	0.0%	24	9	62.5%	311	94	69.8%
EUG	86.5%	2	0	100.0%	48	3	93.8%	584	55	90.6%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	1	50.0%	3	2	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	72	20	72.2%	888	134	84.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	1	90.9%	251	32	87.3%	2,926	308	89.5%
MCD	-	-	-	-	7	6	14.3%	15	13	13.3%
OKJ	74.5%	13	3	76.9%	280	77	72.5%	3,179	813	74.4%
PDX	86.0%	5	1	80.0%	120	10	91.7%	1,457	176	87.9%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	4	75.0%	358	40	88.8%	4,163	450	89.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/24/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/24/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	329	52	84.2%	7,406	1,109	85.0%	88,760	12,230	86.2%
West Division	86.0%	93	19	79.6%	2,162	328	84.8%	25,229	3,445	86.3%
SAN	90.5%	13	1	92.3%	311	34	89.1%	3,555	328	90.8%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	191	26	86.4%	2,333	336	85.6%
SJC	89.0%	7	1	85.7%	168	20	88.1%	2,075	202	90.3%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	72	3	95.8%	651	63	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	24	1	95.8%	290	21	92.8%
VAC	97.0%	2	0	100.0%	47	0	100.0%	577	14	97.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	Cncld	10	0	100.0%	125	8	93.6%	11	6	45.5%	126	29	77.0%
2		11	4	63.6%	126	29	77.0%	9	2	77.8%	121	22	81.8%
3		24	4	83.3%	295	58	80.3%	24	12	50.0%	293	129	56.0%
4	131	24	3	87.5%	294	45	84.7%	24	14	41.7%	294	193	34.4%
5	55	24	3	87.5%	293	46	84.3%	23	19	17.4%	289	82	71.6%
6		24	9	62.5%	292	85	70.9%	24	15	37.5%	292	97	66.8%
7		24	3	87.5%	284	38	86.6%	24	8	66.7%	277	69	75.1%
8	263	24	12	50.0%	284	123	56.7%	24	19	20.8%	283	168	40.6%
11		24	4	83.3%	295	54	81.7%	24	6	75.0%	289	60	79.2%
14		24	4	83.3%	296	45	84.8%	24	7	70.8%	294	90	69.4%
19	229	24	10	58.3%	294	75	74.5%	23	12	47.8%	291	71	75.6%
20		24	5	79.2%	294	23	92.2%	24	11	54.2%	294	58	80.3%
21		24	2	91.7%	291	24	91.8%	24	15	37.5%	290	77	73.4%
22		24	4	83.3%	292	29	90.1%	24	15	37.5%	290	77	73.4%
23	16	23	1	95.7%	296	6	98.0%	23	13	43.5%	294	82	72.1%
24	23	23	2	91.3%	296	16	94.6%	23	11	52.2%	295	54	81.7%
25	48	23	0	100.0%	295	3	99.0%	23	11	52.2%	293	80	72.7%
26		23	0	100.0%	295	5	98.3%	23	6	73.9%	293	58	80.2%
27		24	4	83.3%	282	18	93.6%	24	10	58.3%	278	91	67.3%
28		24	3	87.5%	278	62	77.7%	24	3	87.5%	278	54	80.6%
40	292	23	3	87.0%	289	41	85.8%	22	19	13.6%	287	151	47.4%
41	368	22	10	54.5%	288	112	61.1%	22	22	0.0%	286	218	23.8%
42		24	4	83.3%	296	24	91.9%	24	8	66.7%	294	50	83.0%
43		24	1	95.8%	295	42	85.8%	23	13	43.5%	294	69	76.5%
48		24	4	83.3%	294	57	80.6%	24	3	87.5%	294	41	86.1%
49		24	5	79.2%	294	72	75.5%	24	7	70.8%	294	59	79.9%
50	75	10	3	70.0%	121	29	76.0%	11	10	9.1%	121	73	39.7%
52		24	2	91.7%	293	39	86.7%	24	8	66.7%	292	69	76.4%
53	100	24	2	91.7%	293	36	87.7%	24	7	70.8%	292	92	68.5%
55		17	1	94.1%	185	7	96.2%	17	4	76.5%	182	38	79.1%
56		17	1	94.1%	186	23	87.6%	16	6	62.5%	182	32	82.4%
58	66	13	0	100.0%	272	16	94.1%	12	5	58.3%	270	70	74.1%
59		12	4	66.7%	270	32	88.1%	11	7	36.4%	266	53	80.1%
63	36	24	12	50.0%	297	129	56.6%	22	19	13.6%	291	159	45.4%
64		24	3	87.5%	295	66	77.6%	24	14	41.7%	295	105	64.4%
66		24	6	75.0%	294	60	79.6%	22	4	81.8%	290	53	81.7%
67		16	2	87.5%	203	13	93.6%	16	4	75.0%	203	35	82.8%
68		24	4	83.3%	297	59	80.1%	24	12	50.0%	297	115	61.3%
69		24	4	83.3%	284	63	77.8%	24	9	62.5%	280	41	85.4%
71	16	24	0	100.0%	292	3	99.0%	24	13	45.8%	291	79	72.9%
72	58	20	2	90.0%	288	31	89.2%	20	6	70.0%	287	61	78.7%
73	32	19	2	89.5%	291	18	93.8%	19	12	36.8%	289	138	52.2%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74		19	3	84.2%	289	33	88.6%	19	12	36.8%	287	106	63.1%
75	97	15	2	86.7%	285	16	94.4%	14	9	35.7%	279	134	52.0%
76	85	15	3	80.0%	285	29	89.8%	14	9	35.7%	276	113	59.1%
77		18	3	83.3%	287	20	93.0%	18	13	27.8%	285	121	57.5%
78		23	5	78.3%	291	25	91.4%	23	12	47.8%	290	62	78.6%
79		24	1	95.8%	294	56	81.0%	24	15	37.5%	293	99	66.2%
80	164	24	5	79.2%	294	33	88.8%	23	12	47.8%	291	61	79.0%
84	48	14	2	85.7%	176	13	92.6%	14	7	50.0%	174	42	75.9%
85		17	0	100.0%	187	16	91.4%	17	8	52.9%	187	69	63.1%
86		17	1	94.1%	187	15	92.0%	17	11	35.3%	186	111	40.3%
89		24	6	75.0%	292	64	78.1%	24	13	45.8%	290	83	71.4%
90		24	0	100.0%	292	10	96.6%	24	12	50.0%	291	49	83.2%
93		17	0	100.0%	186	18	90.3%	17	8	52.9%	185	45	75.7%
94		17	5	70.6%	217	55	74.7%	17	11	35.3%	215	80	62.8%
95	61	17	1	94.1%	186	4	97.8%	17	9	47.1%	186	68	63.4%
97	267	24	22	8.3%	294	195	33.7%	24	20	16.7%	292	96	67.1%
98	91	24	4	83.3%	294	25	91.5%	24	22	8.3%	292	102	65.1%
110		17	5	70.6%	183	101	44.8%	17	2	88.2%	180	18	90.0%
111		17	2	88.2%	177	34	80.8%	17	1	94.1%	175	21	88.0%
112		17	1	94.1%	177	17	90.4%	17	2	88.2%	176	19	89.2%
113		17	2	88.2%	108	24	77.8%	17	2	88.2%	107	13	87.9%
119		14	1	92.9%	174	44	74.7%	14	2	85.7%	172	22	87.2%
125		17	2	88.2%	187	10	94.7%	17	7	58.8%	187	73	61.0%
129	34	17	3	82.4%	186	47	74.7%	17	4	76.5%	186	27	85.5%
130		17	2	88.2%	177	18	89.8%	17	1	94.1%	175	16	90.9%
131		17	5	70.6%	179	52	70.9%	17	6	64.7%	179	35	80.4%
134	23	17	4	76.5%	187	25	86.6%	17	8	52.9%	186	34	81.7%
136	32	17	4	76.5%	187	24	87.2%	17	7	58.8%	185	24	87.0%
137		17	4	76.5%	184	34	81.5%	17	6	64.7%	184	58	68.5%
138		17	4	76.5%	187	39	79.1%	17	6	64.7%	186	33	82.3%
141	122	17	0	100.0%	186	3	98.4%	17	4	76.5%	185	32	82.7%
148	41	17	2	88.2%	186	19	89.8%	17	5	70.6%	184	35	81.0%
151	36	24	8	66.7%	293	94	67.9%	24	11	54.2%	292	95	67.5%
170		17	0	100.0%	182	12	93.4%	17	0	100.0%	181	29	84.0%
171	17	17	0	100.0%	187	10	94.7%	17	12	29.4%	187	73	61.0%
172		17	0	100.0%	186	14	92.5%	17	4	76.5%	184	59	67.9%
173		14	1	92.9%	179	24	86.6%	14	4	71.4%	178	77	56.7%
174		17	0	100.0%	187	20	89.3%	17	9	47.1%	187	47	74.9%
175		17	0	100.0%	187	21	88.8%	17	5	70.6%	187	60	67.9%
176	18	14	1	92.9%	179	15	91.6%	14	6	57.1%	177	21	88.1%
177	21	17	1	94.1%	187	25	86.6%	17	1	94.1%	187	45	75.9%
178		17	1	94.1%	187	25	86.6%	17	6	64.7%	185	29	84.3%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		17	3	82.4%	187	22	88.2%	17	8	52.9%	186	66	64.5%
181		17	3	82.4%	183	57	68.9%	17	2	88.2%	181	14	92.3%
182	81	17	2	88.2%	177	30	83.1%	17	4	76.5%	175	20	88.6%
183	Cncld	17	6	64.7%	186	54	71.0%	16	5	68.8%	183	38	79.2%
184		17	4	76.5%	187	33	82.4%	17	4	76.5%	186	27	85.5%
185		17	1	94.1%	187	37	80.2%	17	3	82.4%	187	14	92.5%
186	17	17	3	82.4%	186	20	89.2%	17	9	47.1%	185	49	73.5%
190		17	4	76.5%	186	66	64.5%	17	4	76.5%	185	41	77.8%
192		17	5	70.6%	184	24	87.0%	17	3	82.4%	184	17	90.8%
193		14	5	64.3%	183	76	58.5%	14	6	57.1%	182	86	52.7%
196		14	1	92.9%	183	19	89.6%	14	0	100.0%	182	15	91.8%
197		17	6	64.7%	187	74	60.4%	17	11	35.3%	187	64	65.8%
198	No OS	17	3	82.4%	119	17	85.7%	17	5	70.6%	118	21	82.2%
230		24	0	100.0%	131	4	96.9%	24	0	100.0%	131	6	95.4%
232	20	24	0	100.0%	297	11	96.3%	24	1	95.8%	297	18	93.9%
234		24	1	95.8%	297	20	93.3%	24	0	100.0%	297	24	91.9%
235		24	3	87.5%	221	30	86.4%	24	9	62.5%	221	50	77.4%
236		24	2	91.7%	281	9	96.8%	24	3	87.5%	281	39	86.1%
237		24	3	87.5%	295	55	81.4%	24	5	79.2%	293	48	83.6%
238		24	0	100.0%	221	19	91.4%	24	2	91.7%	220	16	92.7%
239		24	5	79.2%	296	77	74.0%	24	4	83.3%	295	34	88.5%
240		24	0	100.0%	296	20	93.2%	24	11	54.2%	294	55	81.3%
241		24	5	79.2%	297	73	75.4%	24	3	87.5%	297	69	76.8%
243		24	8	66.7%	233	63	73.0%	24	5	79.2%	232	31	86.6%
245		24	5	79.2%	178	32	82.0%	24	3	87.5%	177	20	88.7%
280	30	24	2	91.7%	297	13	95.6%	24	8	66.7%	297	58	80.5%
281		24	5	79.2%	297	34	88.6%	24	9	62.5%	297	56	81.1%
283		24	9	62.5%	297	73	75.4%	24	8	66.7%	297	60	79.8%
284		24	2	91.7%	297	12	96.0%	24	10	58.3%	295	52	82.4%
290		24	1	95.8%	297	49	83.5%	24	18	25.0%	295	109	63.1%
291		24	12	50.0%	296	87	70.6%	24	13	45.8%	294	71	75.9%
300	22	24	1	95.8%	281	20	92.9%	24	10	58.3%	279	66	76.3%
301		24	1	95.8%	295	10	96.6%	24	5	79.2%	292	55	81.2%
302		18	1	94.4%	276	32	88.4%	18	4	77.8%	272	76	72.1%
305		18	0	100.0%	279	28	90.0%	18	9	50.0%	275	111	59.6%
306		24	0	100.0%	293	15	94.9%	24	8	66.7%	292	79	72.9%
307	22	24	3	87.5%	285	38	86.7%	24	10	58.3%	282	80	71.6%
311		21	2	90.5%	292	25	91.4%	20	8	60.0%	286	58	79.7%
316	47	20	1	95.0%	288	17	94.1%	19	10	47.4%	284	74	73.9%
318	46	23	5	78.3%	295	31	89.5%	23	16	30.4%	292	140	52.1%
319		23	3	87.0%	296	20	93.2%	20	15	25.0%	291	160	45.0%
329		18	0	100.0%	210	8	96.2%	18	0	100.0%	210	13	93.8%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
330		21	0	100.0%	252	4	98.4%	21	1	95.2%	252	14	94.4%
331	12	24	3	87.5%	297	32	89.2%	24	3	87.5%	297	43	85.5%
332		24	2	91.7%	297	16	94.6%	24	3	87.5%	297	42	85.9%
334		24	1	95.8%	297	10	96.6%	24	2	91.7%	296	38	87.2%
335		24	1	95.8%	297	31	89.6%	24	5	79.2%	295	48	83.7%
336		24	1	95.8%	297	9	97.0%	24	2	91.7%	295	27	90.8%
337		24	1	95.8%	297	18	93.9%	24	2	91.7%	293	35	88.1%
338		24	4	83.3%	297	45	84.8%	24	8	66.7%	295	89	69.8%
339		24	3	87.5%	297	49	83.5%	24	3	87.5%	297	51	82.8%
341		24	5	79.2%	286	40	86.0%	24	4	83.3%	281	39	86.1%
342		24	1	95.8%	297	22	92.6%	24	3	87.5%	295	56	81.0%
350		20	1	95.0%	274	18	93.4%	18	10	44.4%	267	146	45.3%
351	23	24	2	91.7%	280	27	90.4%	24	9	62.5%	278	77	72.3%
352		24	1	95.8%	264	21	92.0%	24	6	75.0%	258	77	70.2%
353		20	1	95.0%	235	13	94.5%	20	2	90.0%	229	37	83.8%
354	21	24	7	70.8%	278	35	87.4%	21	8	61.9%	271	97	64.2%
355	37	20	4	80.0%	287	31	89.2%	20	11	45.0%	280	96	65.7%
364	35	24	3	87.5%	286	63	78.0%	24	14	41.7%	280	104	62.9%
365		24	1	95.8%	285	11	96.1%	24	14	41.7%	283	106	62.5%
370		24	2	91.7%	288	35	87.8%	22	3	86.4%	279	68	75.6%
371		23	0	100.0%	282	8	97.2%	23	2	91.3%	281	29	89.7%
380	33	23	3	87.0%	282	27	90.4%	23	11	52.2%	282	60	78.7%
381	30	22	1	95.5%	295	12	95.9%	22	9	59.1%	294	57	80.6%
382		22	11	50.0%	294	27	90.8%	22	11	50.0%	294	95	67.7%
383		24	1	95.8%	286	26	90.9%	23	12	47.8%	283	117	58.7%
390		24	1	95.8%	279	18	93.5%	24	8	66.7%	278	71	74.5%
391		22	3	86.4%	280	11	96.1%	22	9	59.1%	277	74	73.3%
392	20	21	4	81.0%	293	9	96.9%	21	11	47.6%	291	89	69.4%
393		24	1	95.8%	297	17	94.3%	24	12	50.0%	294	89	69.7%
417		17	6	64.7%	197	44	77.7%	17	5	70.6%	188	22	88.3%
425		17	0	100.0%	199	6	97.0%	17	0	100.0%	199	7	96.5%
448	64	24	5	79.2%	227	43	81.1%	24	9	62.5%	225	77	65.8%
449	40	24	2	91.7%	225	32	85.8%	24	6	75.0%	225	42	81.3%
470		17	2	88.2%	210	36	82.9%	17	1	94.1%	204	24	88.2%
471		17	4	76.5%	200	10	95.0%	17	3	82.4%	200	5	97.5%
473		17	1	94.1%	206	14	93.2%	17	1	94.1%	203	9	95.6%
474	22	20	11	45.0%	204	62	69.6%	17	14	17.6%	189	61	67.7%
475	58	17	1	94.1%	204	6	97.1%	17	5	70.6%	204	15	92.6%
478	29	17	4	76.5%	198	31	84.3%	17	6	64.7%	196	26	86.7%
479	131	17	5	70.6%	205	34	83.4%	17	9	47.1%	203	31	84.7%
486	36	17	3	82.4%	209	31	85.2%	17	7	58.8%	203	57	71.9%
494	99	18	5	72.2%	211	40	81.0%	17	12	29.4%	204	56	72.5%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
495		17	1	94.1%	195	4	97.9%	17	0	100.0%	193	3	98.4%
500	74	24	1	95.8%	288	16	94.4%	23	3	87.0%	285	35	87.7%
502		24	2	91.7%	295	17	94.2%	23	1	95.7%	291	57	80.4%
503		24	2	91.7%	293	27	90.8%	23	11	52.2%	286	85	70.3%
504	31	24	1	95.8%	297	18	93.9%	24	6	75.0%	295	88	70.2%
505	137	24	2	91.7%	295	38	87.1%	23	8	65.2%	290	81	72.1%
506		24	3	87.5%	292	41	86.0%	23	4	82.6%	286	45	84.3%
507		24	1	95.8%	297	35	88.2%	24	9	62.5%	297	97	67.3%
508		24	2	91.7%	292	41	86.0%	23	4	82.6%	288	66	77.1%
509		24	2	91.7%	294	14	95.2%	24	3	87.5%	294	66	77.6%
511		24	2	91.7%	289	23	92.0%	24	3	87.5%	288	48	83.3%
516	71	23	1	95.7%	288	28	90.3%	23	6	73.9%	287	129	55.1%
517		24	0	100.0%	297	8	97.3%	24	15	37.5%	293	123	58.0%
518	112	24	1	95.8%	297	36	87.9%	24	18	25.0%	295	201	31.9%
519		23	0	100.0%	288	9	96.9%	23	1	95.7%	286	64	77.6%
520		18	1	94.4%	168	25	85.1%	18	0	100.0%	165	9	94.5%
521		18	0	100.0%	206	7	96.6%	18	4	77.8%	206	27	86.9%
522	45	18	3	83.3%	206	39	81.1%	18	2	88.9%	203	20	90.1%
523		18	1	94.4%	206	7	96.6%	18	0	100.0%	205	22	89.3%
524		18	4	77.8%	206	15	92.7%	18	3	83.3%	204	23	88.7%
525		18	2	88.9%	204	14	93.1%	17	0	100.0%	200	13	93.5%
526		18	4	77.8%	180	33	81.7%	18	2	88.9%	177	14	92.1%
527	22	18	2	88.9%	206	11	94.7%	18	5	72.2%	205	37	82.0%
528		18	2	88.9%	206	17	91.7%	18	1	94.4%	205	30	85.4%
529	19	18	1	94.4%	206	12	94.2%	18	6	66.7%	205	56	72.7%
530	18	18	2	88.9%	160	16	90.0%	18	6	66.7%	160	32	80.0%
531		18	2	88.9%	180	14	92.2%	18	2	88.9%	180	13	92.8%
532		18	6	66.7%	206	49	76.2%	18	4	77.8%	205	31	84.9%
534		18	1	94.4%	165	25	84.8%	18	1	94.4%	163	16	90.2%
535		18	2	88.9%	193	25	87.0%	18	2	88.9%	188	22	88.3%
536	12	18	6	66.7%	206	55	73.3%	17	1	94.1%	202	38	81.2%
537		18	4	77.8%	177	22	87.6%	17	3	82.4%	171	19	88.9%
538		18	0	100.0%	206	23	88.8%	18	5	72.2%	205	42	79.5%
539		18	3	83.3%	160	23	85.6%	18	6	66.7%	160	70	56.3%
540		17	3	82.4%	205	38	81.5%	16	0	100.0%	197	18	90.9%
541		18	1	94.4%	205	22	89.3%	17	3	82.4%	199	36	81.9%
542	105	18	3	83.3%	205	24	88.3%	17	4	76.5%	202	36	82.2%
543		18	3	83.3%	206	22	89.3%	18	11	38.9%	206	61	70.4%
544	46	18	0	100.0%	204	20	90.2%	18	3	83.3%	201	18	91.0%
545		18	2	88.9%	206	17	91.7%	17	2	88.2%	203	24	88.2%
547	72	18	3	83.3%	206	40	80.6%	18	2	88.9%	206	46	77.7%
548	11	17	1	94.1%	201	21	89.6%	16	1	93.8%	199	15	92.5%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
549		18	1	94.4%	201	26	87.1%	17	1	94.1%	193	17	91.2%
550		18	3	83.3%	160	17	89.4%	18	4	77.8%	160	35	78.1%
551	25	18	3	83.3%	202	22	89.1%	17	2	88.2%	193	19	90.2%
562		24	1	95.8%	289	22	92.4%	24	4	83.3%	286	33	88.5%
564		24	2	91.7%	289	19	93.4%	24	5	79.2%	281	35	87.5%
566		24	5	79.2%	287	22	92.3%	24	7	70.8%	284	39	86.3%
567		24	1	95.8%	174	9	94.8%	24	3	87.5%	172	9	94.8%
572	35	24	1	95.8%	284	23	91.9%	23	13	43.5%	278	78	71.9%
573		24	0	100.0%	287	40	86.1%	24	4	83.3%	280	48	82.9%
579	34	24	1	95.8%	174	9	94.8%	24	7	70.8%	169	33	80.5%
580	21	24	0	100.0%	289	14	95.2%	24	5	79.2%	284	26	90.8%
581	51	24	4	83.3%	289	47	83.7%	24	7	70.8%	287	61	78.7%
584	56	24	6	75.0%	173	23	86.7%	23	20	13.0%	168	102	39.3%
587	39	23	1	95.7%	283	16	94.3%	23	12	47.8%	274	50	81.8%
588	76	24	5	79.2%	174	17	90.2%	24	6	75.0%	173	28	83.8%
591	60	24	2	91.7%	288	20	93.1%	24	6	75.0%	282	35	87.6%
593	61	24	8	66.7%	283	45	84.1%	21	5	76.2%	262	32	87.8%
595	53	24	9	62.5%	284	50	82.4%	24	9	62.5%	281	55	80.4%
600	32	17	0	100.0%	214	9	95.8%	17	4	76.5%	212	19	91.0%
601		17	9	47.1%	197	81	58.9%	17	2	88.2%	194	25	87.1%
605		17	8	52.9%	204	126	38.2%	17	3	82.4%	200	22	89.0%
607		17	5	70.6%	213	29	86.4%	17	3	82.4%	210	25	88.1%
609	13	17	1	94.1%	204	23	88.7%	17	4	76.5%	203	19	90.6%
626		17	3	82.4%	118	15	87.3%	17	3	82.4%	116	18	84.5%
639		16	1	93.8%	184	38	79.3%	16	0	100.0%	183	19	89.6%
640	13	17	0	100.0%	204	7	96.6%	17	4	76.5%	202	80	60.4%
641		17	4	76.5%	186	38	79.6%	17	1	94.1%	186	26	86.0%
642		17	0	100.0%	202	9	95.5%	17	3	82.4%	201	26	87.1%
643		17	3	82.4%	216	42	80.6%	17	4	76.5%	213	36	83.1%
644		17	0	100.0%	208	27	87.0%	17	3	82.4%	206	51	75.2%
645		17	3	82.4%	216	41	81.0%	16	6	62.5%	213	45	78.9%
646		17	5	70.6%	205	51	75.1%	17	11	35.3%	203	100	50.7%
647		17	1	94.1%	216	32	85.2%	17	4	76.5%	215	47	78.1%
648		17	5	70.6%	212	55	74.1%	17	2	88.2%	212	33	84.4%
649		17	4	76.5%	217	41	81.1%	17	3	82.4%	214	34	84.1%
650	17	17	1	94.1%	216	40	81.5%	17	5	70.6%	213	35	83.6%
651		17	0	100.0%	216	16	92.6%	17	3	82.4%	214	42	80.4%
652		17	2	88.2%	217	29	86.6%	17	5	70.6%	213	37	82.6%
653		17	3	82.4%	205	33	83.9%	17	4	76.5%	202	38	81.2%
654		17	3	82.4%	206	39	81.1%	16	1	93.8%	202	17	91.6%
655		17	3	82.4%	214	72	66.4%	17	5	70.6%	212	73	65.6%
656	36	17	1	94.1%	216	46	78.7%	17	7	58.8%	215	28	87.0%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
657		17	1	94.1%	205	27	86.8%	17	1	94.1%	204	29	85.8%
658	12	17	1	94.1%	216	35	83.8%	17	2	88.2%	214	32	85.0%
680		18	3	83.3%	211	12	94.3%	18	3	83.3%	210	27	87.1%
681	11	18	2	88.9%	211	16	92.4%	17	11	35.3%	205	83	59.5%
682		18	1	94.4%	210	6	97.1%	18	4	77.8%	210	37	82.4%
683	13	18	1	94.4%	193	16	91.7%	18	14	22.2%	192	65	66.1%
684		18	5	72.2%	192	32	83.3%	18	5	72.2%	192	43	77.6%
685		18	3	83.3%	207	31	85.0%	18	8	55.6%	204	52	74.5%
686		18	4	77.8%	212	37	82.5%	18	9	50.0%	211	45	78.7%
687		18	3	83.3%	211	33	84.4%	18	4	77.8%	210	35	83.3%
688		18	4	77.8%	210	13	93.8%	18	6	66.7%	209	36	82.8%
701	134	24	3	87.5%	229	24	89.5%	24	5	79.2%	226	25	88.9%
702	23	24	1	95.8%	296	32	89.2%	23	8	65.2%	293	68	76.8%
703		24	14	41.7%	297	91	69.4%	23	12	47.8%	295	82	72.2%
704		24	3	87.5%	228	35	84.6%	23	4	82.6%	222	42	81.1%
710		24	7	70.8%	297	76	74.4%	24	7	70.8%	293	80	72.7%
711	77	24	5	79.2%	288	33	88.5%	20	4	80.0%	267	49	81.6%
712	74	24	8	66.7%	294	79	73.1%	23	9	60.9%	285	96	66.3%
713	29	20	2	90.0%	166	16	90.4%	18	9	50.0%	151	65	57.0%
714	24	23	14	39.1%	178	72	59.6%	21	11	47.6%	164	69	57.9%
715	24	24	2	91.7%	296	60	79.7%	20	11	45.0%	273	136	50.2%
716	35	24	12	50.0%	297	119	59.9%	23	10	56.5%	291	112	61.5%
717	29	23	4	82.6%	282	66	76.6%	22	10	54.5%	263	80	69.6%
718		24	12	50.0%	297	148	50.2%	24	12	50.0%	295	103	65.1%
719		24	10	58.3%	297	98	67.0%	23	9	60.9%	282	81	71.3%
757		24	1	95.8%	82	4	95.1%	24	3	87.5%	81	7	91.4%
761		24	1	95.8%	293	12	95.9%	24	5	79.2%	290	39	86.6%
765		24	0	100.0%	293	24	91.8%	24	4	83.3%	293	40	86.3%
769		24	1	95.8%	293	26	91.1%	24	5	79.2%	287	54	81.2%
770		24	0	100.0%	293	21	92.8%	24	11	54.2%	291	85	70.8%
774	19	24	0	100.0%	293	16	94.5%	24	8	66.7%	292	64	78.1%
777	63	24	3	87.5%	178	12	93.3%	24	6	75.0%	177	40	77.4%
782		24	20	16.7%	178	76	57.3%	24	7	70.8%	173	22	87.3%
785		24	3	87.5%	293	20	93.2%	24	6	75.0%	293	52	82.3%
786	60	24	1	95.8%	82	17	79.3%	22	13	40.9%	79	40	49.4%
790	73	24	0	100.0%	293	26	91.1%	24	8	66.7%	290	40	86.2%
794		24	2	91.7%	293	33	88.7%	24	7	70.8%	290	62	78.6%
821	30	24	0	100.0%	291	6	97.9%	24	14	41.7%	291	117	59.8%
822	69	24	1	95.8%	293	15	94.9%	24	18	25.0%	291	136	53.3%
1233		7	2	71.4%	13	4	69.2%	7	4	42.9%	13	7	46.2%
1246		7	6	14.3%	13	11	15.4%	7	4	42.9%	13	5	61.5%
1333	182	24	3	87.5%	293	31	89.4%	24	7	70.8%	290	95	67.2%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2026

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1340		24	0	100.0%	292	5	98.3%	24	4	83.3%	292	46	84.2%
1689	15	15	0	100.0%	89	5	94.4%	15	3	80.0%	88	11	87.5%
2102		17	0	100.0%	63	12	81.0%	17	1	94.1%	62	5	91.9%
2103		17	2	88.2%	127	12	90.6%	17	0	100.0%	126	9	92.9%
2104		17	1	94.1%	153	10	93.5%	17	2	88.2%	151	12	92.1%
2107		17	3	82.4%	184	33	82.1%	17	0	100.0%	181	20	89.0%
2108		17	0	100.0%	184	25	86.4%	17	2	88.2%	178	19	89.3%
2109		17	1	94.1%	77	10	87.0%	17	0	100.0%	76	4	94.7%
2112		17	2	88.2%	24	4	83.3%	16	2	87.5%	22	2	90.9%
2113		17	3	82.4%	63	6	90.5%	17	1	94.1%	63	8	87.3%
2115		17	4	76.5%	63	9	85.7%	17	6	64.7%	62	10	83.9%
2116		17	1	94.1%	24	1	95.8%	17	4	76.5%	24	6	75.0%
2118	33	17	2	88.2%	24	2	91.7%	17	7	58.8%	24	9	62.5%
2119		17	1	94.1%	24	3	87.5%	17	8	52.9%	24	9	62.5%
2120		17	5	70.6%	24	8	66.7%	16	8	50.0%	23	11	52.2%
2123		17	2	88.2%	62	8	87.1%	16	2	87.5%	61	15	75.4%
2124		17	9	47.1%	156	32	79.5%	17	9	47.1%	154	22	85.7%
2127		17	6	64.7%	24	7	70.8%	17	6	64.7%	23	6	73.9%
2128	30	17	3	82.4%	24	3	87.5%	17	2	88.2%	24	2	91.7%
2131		17	5	70.6%	24	5	79.2%	17	2	88.2%	24	2	91.7%
2150		17	0	100.0%	177	22	87.6%	17	4	76.5%	174	71	59.2%
2151	41	17	0	100.0%	126	6	95.2%	17	7	58.8%	124	36	71.0%
2152		14	3	78.6%	82	6	92.7%	14	4	71.4%	81	30	63.0%
2154		13	2	84.6%	85	22	74.1%	12	3	75.0%	81	39	51.9%
2155		17	2	88.2%	186	16	91.4%	17	6	64.7%	182	96	47.3%
2158	50	17	2	88.2%	24	4	83.3%	17	10	41.2%	24	10	58.3%
2159	22	17	2	88.2%	179	13	92.7%	17	10	41.2%	177	58	67.2%
2160	25	17	1	94.1%	24	1	95.8%	16	11	31.3%	23	15	34.8%
2162		17	3	82.4%	185	16	91.4%	17	6	64.7%	179	83	53.6%
2165	70	14	2	85.7%	21	2	90.5%	14	8	42.9%	21	10	52.4%
2167		14	2	85.7%	173	20	88.4%	14	1	92.9%	173	37	78.6%
2171		17	1	94.1%	113	9	92.0%	17	4	76.5%	110	22	80.0%
2190		14	3	78.6%	182	27	85.2%	14	1	92.9%	180	23	87.2%
2193		12	1	91.7%	177	24	86.4%	12	2	83.3%	175	47	73.1%

Amtrak Endpoint OTP Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2118	NYP	33	ENG	28	ENG	28	XCY-NWK	AM	Undesired emergency application, 2152 NG NP, MULTIPLE FAULTS PC2152 MP31.8
2128	NYP	30	PTI	18	ITI	9	WAS-WAS	AM	Service, turn, or wye train, 2165, LATE INBOUND AM2165
2151	WAS	41	CTI	17	DSR	16	NHV-STM	MN	Per bulletin Also DPO and speed restrictions, Control Point, 248, 30, 1/2, Control Point, 241, 15, 2/4
2158	BOS	50	ENG	26	CAR	25	WAS-WAS	AM	Electrical failure, XXX, SHORT TURN 2151 FOR 2158 DUE TO SHOPPED 2109
2159	WAS	22	SVS	19	SVS	19	BOS-BOS	AM	Water, commissary, toilet/trash dumping, Late release from the commissary
2160	BOS	25	CTI	16	CTI	10	NYP-XSH	AM	Cross Traffic, MN, MN, Other, XSH-XSH, MNRR TRAIN ROUTED AHEAD
2165	WAS	70	ENG	36	ENG	31	XGX-NHV	AM	Traction motor, 2116 NG NP, No. 2167 is stopped on trk 1 at mp 182.3. ENGR said MCB opened on the lead power car 2033 and it has 100% traction loss.
84	NYP	48	ENG	35	ENG	28	BAL-BAL	AM	Other electrical failure, 604 EX ES, met with mechanical a/c lost power on rear Engine and pantograph keeps dropping.
95	NFK	61	PTI	76	PTI	27	FBG-RVR	CS	Follow amt 41, Milepost w/Letters, cfp 41.1, cfp 11.4
129	WAS	34	ENG	25	ENG	15	NWK-NBK	AM	Undesired emergency application, 658 EX ES, REAR PAN WENT DOWN STOPPED AT METROPARK TO INSPECT
134	NYP	23	HLD	11	ADA	6	WAS-WAS	AM	Wheelchair, LATE ADA PAX
136	SPG	32	SYS	34	SYS	34	NYP-NYP	AM	Other late crew, LATE ARRIVAL OF ENGR
141	WAS	122	MTI	83	MTI	68	EWR-MET	AM	Disabled train ahead, Other, XEO-XUN, PICKING UP DISABLED AM183'S PSGRS
148	SPG	41	WTR	37	WTR	23	BER-BER	AM	Trees down, Control Point, BER, Held at Berlin a/c congestion due to tree across single trk at MP 51.5
151	RNK	36	DCS	25	DCS	25	MSS-CLP	NS	SIGNAL DROP AT REMINGTON PUT US AN EMERGENCY WALK TRAIN DID CLASS TWO BREAK TEST SHOVED BACK FIVE CARS TO GET THE SIGNAL, Control Point, REMINGTON
171	RNK	17	HLD	14	SMW	7	XSH-NYP	AM	Scheduled in track usage program, Other, XSH-XGG
176	BOS	18	SMW	22	DSR	9	STM-BRP	MN	Per bulletin Milepost, 41.7, 42.0, 15, 2

Amtrak Endpoint OTP Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/24/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
177	PHL	21	CTI	29	CTI	18	BRP-STM	MN	Follow mn, Milepost w/Letters, not, stm
182	NYP	81	ENG	78	ENG	51	PHL-PHL	AM	HEP, 625 EX ES
183	WAS	Trn Cancelled							
186	PHL	17	OTH	18	OTH	9	ALX-XVG	CS	K-Tower Hold. Waited on a track assignment.
198	NYP	No OS Rpt	SMW	14	SMW	8	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XBH, SINGLE TRACKING ON NO.3 TRACK HUDSON TO LACK A/C 2 TRK O/O/S.
474	SPG	22	DCS	11	DCS	11	STS-WFD	AM	T.O.L, Milepost w/Letters, STS, WFD, AM474 crossed over at Cedar due to TOL on trk 2
475	NHV	58	CCR	30	CCR	18	SPG-WNL	AM	Cab signal failure, 9647, AM475 e/9647 declared cab signal failure at MP 56.0 on trk 1
478	SPG	29	SVS	28	SVS	28	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, delayed due to needing to swap around equipment from AM417
479	NHV	131	WTR	115	WTR	111	SPG-SPG	AM	Trees down, Control Point, SPG, AM479 held at SPG tree across single trk at MP 51.5
486	GFD	36	PTI	29	PTI	29	WND-WNL	AM	Meet, 475, Milepost w/Letters, WND, WNL, AM486 held a/c AM475 dealing with cab signal failure
494	GFD	99	WTR	84	WTR	25	BER-BER	AM	Trees down, Control Point, BER, Held at BER due to congestion a/c tree across single trk at MP 51.5
53	SFA	100	ITI	120	ITI	120	LOR-LOR	CS	Service, turn, or wye train 5222, Late inbound train 52
80	NYP	164	INJ	199	INJ	199	RMT-PTB	CS	Injured or sick employee Engineer got sick, was taken by EMS,
600	NYP	32	ENG	38	ENG	38	PHL-XHM	AM	Undesired emergency application, 9651 CB CC, WYE OUTBOUND, CC CAN'T LEAD
609	HAR	13	ENG	21	ENG	21	PHL-PAO	AM	Undesired emergency application, 645 EX ES, WYE OUTBOUND
640	NYP	13	CTI	13	TRS	9	PHL-PHN	AM	Near-miss, Milepost, 86.8, 86.8
650	NYP	17	CTI	16	CTI	16	NWK-NYP	AM	Follow, NJT, NJ3252, Other, NWK-NYP, FOLLOWED NJ3252
656	NYP	36	ENG	30	ENG	30	PHL-XHM	AM	Undesired emergency application, 645 EX ES, WYE OUTBOUND

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/24/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
658	NYP	12	CTI	10	CTI	6	NWK-NYP	AM	Follow, NJT, 6674, Other, XPT-NYP	
19	NOL	229	FTI	268	FTI	167	ATN-BHM	NS	Blocked from station track 713 operated through 20th st switch, wait for recrow, shove back to 27th then down to 14th & back into BHM station, NS 713, Control Point, 20th st	
681	BRK	11	PTI	13	PTI	8	POR-FRE	CS	Meet 684, Control Point, Congress	
683	BRK	13	PTI	9	PTI	9	EXR-DHM	CS	Meet 684, Control Point, Rockingham	
1689	BRK	15	FTI	16	FTI	16	DOV-WEM	CS	Follow LO80, Other, Dover East to Varney	
63	TWO	36	DSR	5	RTE	3	BUF-BFX	CS	Dispatcher hold Approach at 435. Stop signal at 437., Control Point, 437	
232	NYP	20	CTI	25	CTI	23	XCP-CRT	MN	Follow mnrr, 834, Milepost, 72, 34	
280	NYP	30	RTE	39	RTE	32	ALB-HUD	AM	Dispatcher hold Control Point, 141	
448	BOS	64	FTI	79	FTI	52	XRD-PIT	CS	Meet M275, M427, Control Point, 171	
449	ALB	40	CTI	38	CTI	19	BBY-FRA	MT	Meet Single tracking for the working limits between 21 and 11. Waited for the commuter to crossover in front of us at 11., Keolis, 542, Control Point, 11	
71	CLT	16	DCS	14	DCS	14	GRO-SAL	NS	Restrictive signal(s) from unknown cause Restricted speed 307.9 to Lake, Dark, Milepost, 307.9, 307.9	
72	RGH	58	PTI	36	DCS	24	SAL-HPT	NS	CTC system failure Power outage restricted speed Lake to Thomasville, Control Point, Lake	
73	CLT	32	FTI	10	FTI	10	RGH-CYN	NS	Cross over or go around Held at the station due to AMTK 80 coming into RGH and NS 350 stopped on Main 2., Control Point, Boylan, #NS350	
75	CLT	97	POL	66	POL	66	RGH-RGH	NS	Right of Way police hold	
76	RGH	85	ITI	56	ITI	56	CLT-CLT	NS	Service, turn, or wye train 75	
97	MIA	267	FTI	106	ENG	91	WAS-WAS	AM	Other electrical failure, 83-366, WAITING FOR DSLs FROM THE PIT	
98	NYP	91	FTI	62	CTI	25	XDJ-ALX	CS	Follow vre, Milepost, 61.0, 105.2	
40	CHI	292	FTI	157	POL	60	PAK-JAX	CS	RR blocked by trespasser or vehicle strike by another train P052-22 vehicle strike ahead. stopped at NE Yukon	
41	MIA	368	ENG	218	ENG	218	CHI-CHI	AM	Eng 124 bad ordered Eng 124 bad ordered, 78	

Amtrak Endpoint OTP Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
23	NOL	16	FTI	27	PTI	27	BAS-XNO	CS	Meet 24, Siding, Nicholson
24	MOE	23	FTI	38	FTI	23	PAG-MOE	CS	Meet CSX M52122, Siding, Orange Grove
25	NOL	48	FTI	59	FTI	48	BAS-XNO	CS	Meet Control Point, Paris Rd, 602-24
5	EMY	55	DSR	142	CAR	41	RIC-EMY	UP	Air / Brake / Wheel 39031, Broke an air hose had to replace
522	SAC	45	ITI	27	ITI	27	OKJ-OKJ	UP	Service, turn, or wye train 529, Turned from Train 529 (23). Trainline door light issues and air leakage issues in CDTX 8204.
527	SJC	22	TEN	24	TEN	16	GAC-SCC	UP	PTC - On Board Cab Signal or PTC Failure Cycle the PTC breaker per Caltrain. Finally able to initialize., C2004
529	SJC	19	TEN	25	TEN	25	ARN-ARN	UP	Missing vertical axle snubber from running gear. Called for clearance to operate C2010
530	SAC	18	DCS	20	DCS	17	DAV-SAC	UP	Restrictive signal(s) from unknown cause Red, Control Point, RV087
536	SAC	12	PTI	21	PTI	21	DAV-SAC	UP	Wait for station track Routine wait for amt547 to depart station track 3, so we can park in the location., amt547, Control Point, w sac
542	SAC	105	POL	96	POL	96	RIC-RIC	UP	Fire department hold Tracksides fire @ mp 15.29
544	SAC	46	POL	56	POL	33	RIC-RIC	UP	Fire department hold Held in station fire track fire ahead.
547	SJC	72	POL	66	POL	49	MTZ-MTZ	UP	Fire department hold
548	SAC	11	PTI	16	PTI	13	RIC-MTZ	UP	Follow Amtk 544, Milepost, 17.2, 31.0
551	OKJ	25	POL	32	POL	28	SAC-SAC	UP	Fire department hold Late inbound equipment turnaround due to earlier Fire department hold/ tracksides for at MP 15.29 Martinez sub.
50	NYP	75	DSR	56	DSR	23	STA-CVS	BB	Per bulletin Milepost, 194.8, 184.3, 25, main
500	SEA	74	FTI	88	FTI	72	TAC-XTW	BN	BNSF 7336 undesired emergency brake application. Held at TR jct due to disabled freight train, BNSF 7336, Control Point, Clear Creek
504	SEA	31	PTI	31	PTI	19	KEL-CTL	BN	Wait for station track AMTK 505 was having mechanical issues with Talgo Set and was blocking MT 2 for station work for both AMTK 11 and AMTK 504., AMTK 505, AMTK 11, Control Point, Centralia South
505	PDX	137	CAR	60	FTI	49	XA4-XTW	BN	Meet BNSF 7336 went into emergency. Had to get an extension air hose to recover their air., bnsf 7336, Control Point, stewart

Amtrak Endpoint OTP Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/24/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
516	VAC	71	MBO	38	MBO	38	XF2-X1J	BN	For maritime traffic 2 big boats, Bridge, Fraser	
518	VAC	112	ITI	45	ITI	45	PDX-PDX	BN	Service, turn, or wye train 505	
58	CHI	66	FTI	82	FTI	30	MEM-NBN	CC	Meet Wait on southbound A407 to pass at Woodstock, Control Point, woodstock, A407	
8	CHI	263	FTI	175	SYS	62	STN-MOT	BN	Re-crew / job briefing BNSF had no pilots	
821	FTW	30	DSR	44	DSR	28	GLE-FTW	BN	Per bulletin Milepost, 408.5, 408.1, 60, m, Milepost, 407, 406.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 396.3, 396.2, 30, m, Milepost, 396, 395.9, 50, m, Milepost, 393.6, 393.5, 50, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 385.5,	
822	OKC	69	FTI	54	FTI	34	FTW-GLE	BN	Meet BN 7626, Siding, Metro	
331	MKE	12	CTI	12	CTI	12	X9L-XWA	ME	Follow Following Metra Equipment out of CUS. Multiple trains stopped on Main 1, Metra, Equipment, Control Point, CP Morgan	
351	CHI	23	SYS	24	SYS	24	XMC-XPI	AM	Copy authority / restriction Talk by signal at MP 239	
354	PNT	21	MBO	32	MBO	32	XTF-XH6	NS	For maritime traffic Bridge, 509	
355	CHI	37	MBO	44	MBO	44	XPI-HMI	NS	Malfunction Bridge, 503	
364	PTH	35	FTI	41	FTI	26	XH6-XPI	NS	Follow B09, Milepost, 497, 483	
572	SAN	35	CTI	21	CTI	13	SOL-OLT	SN	Meet NCTD, 633, Control Point, skripp	
579	LAX	34	DCS	20	DCS	20	IRV-SNA	SC	Power switch failure Power switch problem at Maple. Single tracking from Santa Ana to Anaheim., Control Point, Fourth St	
580	SAN	21	CTI	23	CTI	10	XFT-ANA	SC	Follow metrolink 620, Control Point, college	
581	LAX	51	DCS	24	DCS	15	IRV-SNA	SC	T.O.L Stop signal at Aliso, then single tracking due to signal vandalism, Control Point, Aliso	
584	SAN	56	PTI	60	PTI	28	SNC-SNP	SC	Meet 587, Control Point, serra	
587	LAX	39	CTI	43	CTI	43	OSD-X98	SC	Meet Restricted speed from songs to Pier, metrolink, Control Point, Songs	
588	SAN	76	PTI	54	PTI	43	SNC-SNP	SC	Meet 591, Control Point, Serra	
591	LAX	60	DCS	31	DCS	25	OSD-X98	SN	Restrictive signal(s) from known wayside signal failure Flagging., Stop, Control Point, Songs	
593	LAX	61	PTI	41	PTI	32	OSD-X98	SN	Meet a588, Control Point, songs	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
595	LAX	53	PTI	41	PTI	40	OSD-X98	SN	Meet 790, Control Point, Songs
774	SAN	19	PTI	23	PTI	17	SNC-SNP	SC	Meet 777, Control Point, Serra
777	SLO	63	RTE	34	RTE	31	SNA-ANA	SC	Line manual or spring switch Control Point, Lincoln
786	SAN	60	DCS	40	CTI	27	SIM-CWT	SC	Meet metrolink, Siding, santa susana
790	SAN	73	PTI	55	PTI	55	SNC-SNP	SC	Meet 593, Control Point, serra
701	SAC	134	FTI	172	FTI	117	BFD-WAC	BN	Follow Stopped at E Wasco due to BNSF 7322 needing to make a repair., Milepost, 889.7, 911, BNSF 7322, Z
702	BFD	23	PTI	23	PTI	11	FNO-HNF	BN	Meet 702, Siding, conejo
711	OKJ	77	DCS	45	DCS	45	HNF-FNO	BN	Restrictive signal(s) from unknown cause Per BNSF BFD Sub DS, flagged signals @ E Conejo & W Conejo. Instructed to hand throw switch @ W Conejo., Stop, Control Point, E. Conejo, Control Point, W. Conejo
712	BFD	74	PTI	48	PTI	20	SKN-MOD	BN	Meet 701, 713, Siding, riverbank
713	OKJ	29	FTI	25	FTI	25	WAC-COC	BN	Meet z train, Siding, sandrini, z train 5095
714	BFD	24	FTI	20	FTI	20	ACA-SKN	BN	Meet bnsf 7322, Control Point, Holt
715	OKJ	24	PTI	27	PTI	11	HNF-FNO	BN	Meet 710, Control Point, Calwa Crossing
716	BFD	35	DCS	29	DCS	15	SKN-MOD	BN	Signal suspension Flagging, Control Point, CP Lake, Milepost, 1104, 1102
717	OKJ	29	PTI	13	PTI	10	FNO-MDR	BN	Meet 714, Control Point, madera
4	CHI	131	DSR	80	DCS	40	DDG-HUT	BN	Restrictive signal(s) from unknown cause Permission past stop signal at east end spearville, restricted speed until clear at 329.8, Approach , Stop, Milepost, 339.5, 329.8
2	NOL	Trn Cancelled	POL	929	POL	929	ELP-ELP	UP	RR blocked by trespasser or vehicle strike by another train Service Disruption, Held Train in El Paso Texas until authorized to continue.
300	CHI	22	DCS	26	DCS	15	BNL-PON	UP	Issue with automatic road crossing protection Complied with Procedure XG, Milepost, 124.68, 123.40
307	STL	22	PTI	25	PTI	25	DWT-PON	UP	Meet Amt 306, Siding, Odell
380	CHI	33	DCS	32	DCS	32	MDT-PLO	BN	Signal department wanted us to run through the 30mph on MT 1 where the shunting issues are, had to wait for AMTK 381 to go through it first Milepost, 72.5, 59.6

Amtrak Endpoint OTP Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
381	GBB	30	DSR	19	DSR	17	PLO-MDT	BN	Per bulletin Milepost, 59.6, 72.5, 30, MT1
392	CHI	20	FTI	19	FTI	17	MAT-CHM	CC	Follow cn 2890, Control Point, tuscola
316	STL	47	DBS	55	DBS	55	WAH-KWD	UP	Animal strike Deer strike killed engine Took several attempts to restart, Control Point, Labadie Jct
318	CHI	46	ENG	42	ENG	42	STL-STL	TR	ENGINE ROOM FULL OF OIL, MECHANICAL FOUND THE CAP WAS NOT FULLY ON AND WAS LEAKING OIL, ORIGINALLY THOUGHT THAT IT WOULD NEED OIL ADDED TO IT AND THEN DECIDED THERE WAS ENOUGH OIL TO MAKE THE TRIP TO CHI ID4613
1333	MSP	182	FTI	195	FTI	195	WIN-RDW	CP	Held for disabled freight cp 8144/280, Control Point, weaver

Amtrak Initial Terminal Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/24/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	2159	07/24	19	19	Water, commissary, toilet/trash dumping, Late release from the commissary
CLT	76	07/24	56	56	Service, turn, or wye train 75
GFD	479	07/24	9	9	Late train 486 486
MIA	98	07/24	69	69	Flat switch Eng 10 to the rear for A/C failure 331 in lead now. 10, 331
NFL	284	07/24	21	21	Other late crew Engineer change/recrew
NHV	478	07/24	28	28	Planned set out / pick out of locomotives, cars or section of train, delayed due to needing to swap around equipment from AM417
NHV	494	07/24	28	6	Hold for connecting train
NHV	494	07/24	28	3	Cab signal failure, 9647 CB CC, AM494 used equipment of AM475 with cab issues
NHV	494	07/24	28	19	Cab signal failure, 9647 CB CC, AM494 used equipment of AM475 with cab issues
NYP	49	07/24	2	2	Leaf fire under equipment, Other, NYP-NYP, HELD A/C FIRE UNDER TRACKS 7 AND 8
NYP	51	07/24	12	12	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	63	07/24	2	2	Meet, AM230, Other, NYP, HELD F/INBOUND AM230
NYP	97	07/24	80	31	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C NEEDED CARS OFF AM98
NYP	97	07/24	80	49	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C NEEDING CARS OFF AM98
NYP	111	07/24	7	7	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	129	07/24	2	2	Cross Traffic, NJT, NJ3723, Other, NYP-NYP, HELD A/C NJ3723 XING AHEAD
NYP	193	07/24	2	2	Meet, AM2160, Other, NYP-NYP, HELD A/C AM2160 XING AHEAD
PHL	190	07/24	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	601	07/24	1	1	PTC - Stop Bypass Permission Required, Control Point, PHL
RGH	75	07/24	66	66	Right of Way police hold
WAS	134	07/24	6	6	Wheelchair, LATE ADA PAX
WAS	136	07/24	26	26	Electrical failure, xxx, LOOSE/MISSING CABLING, ISSUES WITH COMM CABLES
WAS	148	07/24	8	8	Disabled train ahead, Control Point, K INT, LATE ARRIVAL OF EQUIPMENT DUE TO EARLIER DISABLED A183; CASCADING EQUIP SWAPS FOR A184, A136, A148
WAS	182	07/24	3	3	Power switch failure, Control Point, K INT, 118 POWER SWITCH FAILURE
WAS	184	07/24	30	30	Disabled train ahead, Milepost, 15.7 , 15.7 , LATE ARRIVAL OF EQUIPMENT 185 DUE TO DISABLED 183

Amtrak Initial Terminal Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/24/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2104	07/24	16	16	Removal of passenger by police, PAX PULLED EMERGENCY HANDLE, PAX HANDED OVER TO APD.
WAS	2116	07/24	9	9	Electrical failure, XXX, DELAY CAUSED BY SHOPPED EQUIPMENT 2109
WAS	2128	07/24	9	9	Service, turn, or wye train, 2165, LATE INBOUND AM2165
WAS	2158	07/24	25	25	Electrical failure, XXX, SHORT TURN 2151 FOR 2158 DUE TO SHOPPED 2109
CDL	392	07/24	9	2	Conductor working alone/crew shortage.
CDL	392	07/24	9	7	Copy authority / restriction
CHI	7	07/24	231	231	Late release of engines from diesel pit and yard Trailer unit is really the 353 but it is not showing up on the list ., 48, 140
CHI	21	07/24	163	163	Set out defective locomotive LATE SETOUT OF AMTK62 AND REPLACED WITH AMTK311, 62
CHI	364	07/24	6	6	Door ID4305, Steps stuck
GBB	382	07/24	10	10	Other late crew Crew arrived 1845
SAS	22	07/24	18	18	Hold for thruway bus Train 2 canceled
ARN	529	07/24	25	25	Missing vertical axle snubber from running gear. Called for clearance to operate C2010
BFD	703	07/24	20	20	Service, turn, or wye train 712
BFD	713	07/24	4	4	Broken window downstairs in car 3. Had to wait for maintenance to clean it
BFD	719	07/24	27	27	Hold for thruway bus
EMY	6	07/24	1		
GTA	782	07/24	7	7	Meet 14, Control Point, CO 358
LAX	4	07/24	11	11	Had to trade out malfunctioning 39041 for 39028 39041
OKJ	522	07/24	32	3	Amtrak Hold Per UP DS62, hold until 0658hrs, per Amtrak management. No reason given., Other, OKJ Depot
OKJ	522	07/24	32	27	Service, turn, or wye train 529, Turned from Train 529 (23). Trainline door light issues and air leakage issues in CDTX 8204.
OKJ	522	07/24	32	2	Door C8019, Door Leaves 5 and 6 in coach car CDTX 8019 would not fully close to give a door light. Doors had to be located then manually forced closed.
OKJ	716	07/24	3	3	Water, commissary, toilet/trash dumping Late turn and following capital AMTK 539 and AMTK 534
OKJ	718	07/24	(Trn Cxld)		Third Party Car Failure
PDX	518	07/24	60	15	505 was routed to depot 4, which caused a 518 boarding delay due to 11 being on depot 3, 505 could have gone in on depot 2 to board and fuel Control Point, pdx
PDX	518	07/24	60	45	Service, turn, or wye train 505

Amtrak Initial Terminal Details

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/24/2026

Terminal	Train	Date	Late	Delay	Cause
SAC	527	07/24	1	1	PTC - On Board Cab Signal or PTC Failure Difficulty logging in to PTC. Pulled down to board and fuel at 6:40., C2004
SAC	531	07/24	1		
SAC	547	07/24	2	2	Hold for thruway bus Bus # 3704
SAC	551	07/24	28	28	Fire department hold Late inbound equipment turnaround due to earlier Fire department hold/ trackside for at MP 15.29 Martinez sub.
SAN	595	07/24	16	16	Service, turn, or wye train 584, Late arriving equipment from train 584.
SEA	8	07/24	7	7	Service, turn, or wye train 7
SEA	505	07/24	18	18	Air / Brake / Wheel 7562, Late release from Seattle yard. Mechanical said they were repairing brakes. Blue flags dropped at 8:40.
SJC	524	07/24	8	8	PTC - On Board Cab Signal or PTC Failure C6965

Eastern Region

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	NO DATA	NO DATA	94.8	NO DATA	NO DATA
CDOT	95.0	NO DATA	NO DATA	92.4	NO DATA	NO DATA
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	95.5	92.3	88.6	356	16
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 40(24) South of Savannah, GA - Freight Train Interference

25JUL26: Train 40(24), operating with engines 346/326, 11 coaches, and 201 customers, was delayed 8 miles south of Savannah, GA, on CSC Savannah_A subdivision due to freight trains M492 and I26 blocking the route into the station. Once the trains cleared and route was made available, Train 40(24) was able to proceed.

Train	Delay	Comment
40(24)	51"	

TREE ON TRACKS N/WNL

25JUL26: A tree was reported across the single main track at MP 51.9 on the N/WNL, resulting in a blockage of the route. a track foreman was dispatched to the scene, with the foreman initially estimated to arrive within 60 to 90 minutes. As a result of the obstruction, Train 479(24) was held at Springfield (SPG) awaiting an open route. To protect passenger connections, Train 179(24) was held at New Haven (NHV) for connections from Train 479(24). Train 494(24) was also held at Berlin (BER). The track foreman subsequently arrived on scene and began assessing the situation around 9:00pm-et.

The track foreman then commenced work to remove the tree from the track. Upon completion of the removal efforts, the foreman reported that the tree had been cleared and the track had been restored to service. Following the reopening of the route, Train 479(24) departed Springfield at 10:12 PM, operating 1 hour and 56 minutes late. Once the track was declared safe for operations, all affected trains resumed movement and normal train operations were restored.

Train	Delay	Comment
494(24)	1'23"	
479(24)	1'51"	
179(24)	1'34"	Witronix estimate - hold for connections

Train 49(24) West of Syracuse, NY - Freight Train Interference

25JUL26: Train 49(24), operating with engines 127/98, 11 coaches and 237 customers, was delayed 22 miles west of Syracuse, NY, on CSX Rochester_QC subdivision, due to holding for freight train N367 that was in emergency. The freight crew was able to recover and get back on the move, creating a roue for train 49(24).

Train 656(24) Philadelphia, PA - Engine Failure

25JUL26: Train 656(24) operating with engines 645, 872 and 9632, 4 coaches and cabcar 9632, was delayed at Philadelphia, PA, due to wyeing the equipment as it was departing the station. The train was required to wye due to a defect on the cabcar which resulted in it being tagged by mechanical as a Do-Not-Lead. While wyeing the equipment the train went into emergency which then required the train to be inspected by the crew and another brake test was required.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
656(24)	30"	

Train 49(24) Albany-Rensselaer, NY - Servicing

25JUL26: Train 49(24), operating with engines 127/98, 11 coaches and 181 customers, was delayed departing Albany, NY, on Amtrak Hudson Line, due to adding 449(24) equipment to the consist. Train 449(24) arrived approximately 40" late due to enroute delays.

Train 97(24) New York, NY - Initial Terminal Delay - Servicing

24JUL26: Train 97(24) operating with engine 626, 12 cars, and 158 customers was delayed departing New York, NY on the Amtrak NYT due to a late release from the yard. The train had to wait for cars to arrive off of train 98(23). Once the consist was together and all necessary testing completed, Train 97(24) boarded the customers and departed the station at 3:50 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(24)	1'20"	

Train 448(24) West of Pittsfield, MA - Passenger Train Interference

24JUL26: Train 448(23), operating with engines 374/101, 4 coaches and 109 customers, was delayed 22 miles west of Pittsfield, MA, on CSX Berkshire subdivision, due to meeting freight trains M275 and M427 at control point 171.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
448(24)	52"	

Train 51(24) Charlottesville, VA - M of W Work

24JUL26: Train 51(24) operating with engine 37, 5 cars, and 135 customers was delayed departing Charlottesville, VA on the Buckingham Branch North Mountain due to waiting for a clear route around maintenance of way work. Once there was a clear route, Train 51(24) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
51(24)	34"	

Train 97(23) North of DeLand, FL - Passenger Train Interference

24JUL26: Train 97(23), operating with engines 83/366, 11 coaches and 277 customers, was delayed 12.5 miles north of DeLand, FL, on CSX Sanford subdivision, due to meeting train 98(24) at Barberville siding.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(23)	35"	

Train 2165(24) North of New Haven, CT - Engine Failure

24JUL26: Train 2165(24) operating with 250 passengers on board was stopped at milepost 105.1, 32 miles north of New Haven, CT on the Amtrak NHB line due to power car 2033 losing all traction power. The crew reported that the MCBs opened and caused the traction loss. The crew troubleshooted with the road foreman and high speed rail to fix the problem. Traction power was able to be regained. The train did lose power in the Cafe car. Once the train finished troubleshooting, Train 2165(24) advanced to the next station.

26.FOI-00621 00000008478 UNCLASSIFIED 8/7/2026

Train	Delay	Comment
2165(24)	31"	
2165(24)	23"	NYP

CN Heat Orders - Weather

24JUL26: CN imposed heat orders between Rouses Point, NY and St. Lambert, QC which created delays for trains 68 and 69.

Train	Delay	Comment
68(24)	37"	
69(24)	45"	

Train 75(24) Raleigh, NC - Police Related

24JUL26: Train 75(24) operating with NC103, 4 cars, NC1893, and 82 customers was delayed departing Raleigh, NC on the NS East Carolina Business Unit District due to a trespasser assaulting the conductor of the train. Police and emergency services responded to the train. The trespasser was arrested and the conductor was transported to the hospital. Once the police hold was lifted, Train 75(24) departed Raleigh at 1:51 PM-ET.

Train	Delay	Comment
75(24)	1'06"	
76(24)	56"	Late Turn of Equipment

CSX Heat Orders - Weather

24JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(24)	1'11"	
49(24)	6"	
51(24)	7"	
52(24)	32"	
53(24)	19"	
63(24)	5"	
79(24)	13"	
86(24)	15"	
89(24)	18"	
90(24)	9"	
93(24)	4"	
94(24)	7"	
97(24)	12"	
97(24)	54"	
125(24)	1"	
151(24)	2"	
171(24)	2"	
186(24)	2"	
280(24)	10"	
281(24)	14"	
283(24)	5"	

Train 80(24) South of Petersburg, VA - Injured or Sick Passenger or Employee

24JUL26: Train 80(24) operating with engine 236, 7 cars, and 274 customers was stopped at milepost 65.5, 42 miles south of Petersburg, VA on the CSX North End subdivision due to the engineer having a medical emergency. The engineer brought the train to a safe stop at Liberty Road. Emergency services responded to the train and the engineer was taken to the local hospital. A relief engineer was sourced out of Richmond. Once the relief engineer arrived at the train, Train 80(24) was on the move at 3:42 PM-ET.

Train	Delay	Comment
80(24)	3'19"	

Train 182(24) Philadelphia, PA - Engine Failure

24JUL26: Train 182(24) operating with engine 625, 9 cars, engine 635, and 487 customers was delayed departing Philadelphia, PA on the Amtrak PW line due to continued faults on engine 625. The train was met by mechanical in Philadelphia and mechanical was able to rectify the problem. It was reported as a set up problem between the two motors. Train 182(24) departed Philadelphia at 1:00 PM-ET.

Train	Delay	Comment
182(24)	51"	PHL
182(24)	13"	WIL
182(24)	08"	XPV-WIL

Train 280(24) South of Albany-Rensselaer, NY - Routing

24JUL26: Train 280(24) operating with engine 111, 5 cars, and 281 customers onboard was delayed at milepost 141.4, 1 mile south of Albany-Rensselaer, NY on the Amtrak HUD Line due to the dispatcher holding the train at control point 141. Once the train was given a route, Train 280(24) advanced to the next station.

Train	Delay	Comment
280(24)	32"	

Train 600(24) Philadelphia, PA - Engine Failure

24JUL26: Train 600(24) operating with engine 654, 4 cars, cab car 9651, and 241 customers onboard was delayed departing Philadelphia, PA on the Amtrak PH Line due to cab car 9651 operating as a coach only. The train was required to go around the wye upon departing the station. Once the train was wye'd, Train 600(24) advanced to the next station.

Train	Delay	Comment
600(24)	38"	

Train 183(24) West of Newark, NJ - Engine Failure

24JUL26: Train 183(24) operating with engines 657, 658, 8 cars, and 310 customers onboard was stopped at milepost 15.7, 7 miles west of Newark, NJ on the Amtrak NYP Line due to the rear pantograph dropping. The crew inspected the equipment and found the pantograph to be bent and it would not lock down. The train maintained head end power. ET and Road Foreman responded to the train. ET was not able to lock down the pantograph and reported that it needed to be cut off. Train 183(24) was terminated where it stood. The customers were transferred to trains 141(24) and 185(24). ET took power after the customer transfer was completed and removed the pantograph. The equipment was deadheaded to Washington to operate as train 184(24)

Train	Delay	Comment
141(24)	1'08"	
183(24)	Term NWK	
184(24)	30"	Late turn of equipment

Train 98(24) Miami, FL - Initial Terminal Delay - Engine Failure

24JUL26: Train 98(24) operating with engines 10, 331, 11 cars, and 81 customers was delayed departing Miami, FL on the SFRTA SFRTA subdivision due to engine 10 having HVAC failure. The engines were flat switched to place engine 331 in the lead. Once the engines were swapped, the train was boarded and departed Miami at 8:15 AM-ET.

Train	Delay	Comment
98(24)	1'09"	

Train 41(23) Pittsburgh, PA - Late Crew Member - System

24JUL26: Train 41(23) operating with engines 198, 339, 10 cars, and 157 customers onboard was delayed departing Pittsburgh, PA on the NS Pittsburgh Line District due to waiting for the outbound engineer to arrive. Once the engineer arrived, Train 41(23) departed Pittsburgh at 6:24 AM-ET.

Train	Delay	Comment
41(23)	50"	

Train 40(23) North of Columbia, SC - Passenger Train Interference

24JUL26: Train 40(23) operating with engines 335, 139, 10 cars, and 196 customers onboard was delayed at milepost 348.8, 12 miles north of Columbia, SC on the CSX Hamlet subdivision due to meeting Train 41(22). Once the passenger train cleared, Train 40(23) advanced to the next station.

Train	Delay	Comment
40(23)	40"	

Train 52(23) South of Fayetteville, NC - Freight Train Interference

24JUL26: Train 52(23) operating with engines 354, 322, 36 cars, and 365 customers onboard was delayed beginning at milepost 213.4, 4 miles south of Fayetteville, NC on the CSX South End subdivision due to following CSX freight train M408 from milepost 213.4 to milepost 197.2. Once the freight train cleared, train 52(23) was able to advance.

Train	Delay	Comment
52(23)	30"	

Maintenance of Way Highlights

26/FBI/DOJ/2026
00000008473
"UNCLASSIFIED"
8/7/2026

Empire and Maple Leaf Services CSX Mohawk Subdivision TW - Scheduled M/W Work

24JUL26: CSX will performing a rail repair due to a Sperry rail defect on Thursday July 30th, 2026 to milepost QC 177.6 on the CSX Mohawk Subdivision. To accommodate the infrastructure work, the following service adjustments will be made to the Empire and Maple Leaf Services:

Train 280(30JUL) will bypass AMS with no alternate transportation. Passengers will be given the option to board/detrain at SDY.

Train 284(30JUL) will bypass AMS with no alternate transportation. Passengers will be given the option to board/detrain at SDY.

Train 63(30Jul) will bypass AMS with no alternate transportation. Passengers will be given the option to board/detrain at SDY.

WBS#: B.TR.100150.6934

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00621 00000008478 "UNCLASSIFIED" 8/7/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	
240(23)	31"	
233(23)	30"	
235(23)	30"	
284(23)	27"	
290(23)	52"	
291(23)	47"	
281(23)	31"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00621a 00000008478 UNCLASSIFIED 187/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Train 7/27(23) East of Browning, MT - Freight Train Interference

25JUL26: Train 7/27(23) was delayed 2 miles east of Browning, MT at Browning siding/MP1121.9 on the BNSF Hi Line Subdivision, meeting 3 BNSF freights (7192, 6598, 7338)

Train	Delay	Comment
7/27(23)	57"	

Train 587(24) East of San Juan Capistrano, CA - Signal

25JUL26: Train 587(24) was delayed at Songs /MP 209.16 on the SCRRA-NCTD San Diego Subdivision, 4.36 miles east of San Clemente Pier, CA station, due to meeting a Metrolink train. This was due to signal issues, with trains flagging at Songs and receiving restrictions into Pier/MP204.8. Multiple trains were delayed meeting each other and flagging through the affected area.

Train	Delay	Comment
587(24)	48"	
595(24)	48"	
790(24)	1'21"	
593(24)	51"	
591(24)	46"	
587(24)	50"	
588(24)	1'18"	

Train 718(24) Oakland, CA - Third Party Contractor Car Failure

25JUL26: Train 718(24) C/2108, 5 cars, E/C2107, was delayed departing Oakland, CA due to replacing the window that was broken on car C/8803, which was discovered prior to train 713(24) departure causing a 4 minute delayed initial terminal departure at Bakersfield. Once the window was replaced, the engine still needed to be fueled. As a result of the lengthy delay, Train 718(24) was originated at Emeryville, and all Oakland passengers were accommodated on Train 544(24).

Train	Delay	Comment
713(24)	04"	BFD
718(24)	1'05"	Originated EMY

Train 3(23) East of Gallup, NM - Freight Train Interference

25JUL26: Train 3(23) was delayed beginning 68.8 miles east of Gallup, NM on the BNSF Gallup Subdivision at MP88.7 meeting BNSF 5941. Train also followed BNSF8329 between MP120.7 and MP157.

Train 3(23) was then stopped at West Hibbard/ MP275.5 due to BNSF 6848 setting out a bad locomotive ahead, blocking the Winslow station track. Once the freight set out the locomotive, and a route into the station was clear, Train 3(23) proceeded.

Train 3(23) was further delayed 31 miles west of Winslow, AZ between MP316.3 and MP340.6 on the BNSF Seligman Subdivision, due to following BNSF 9189.

Train	Delay	Comment
3(23)	41"	BN9189
3(23)	1'07"	BN6848
3(23)	51"	BN5941, BN8329

Train 19(23) Picayune, MS - System

25JUL26: Train 19(13) 26-FCI-00821 00000008478 Picayune, MS 4MP148 8/7/2026 the Norfolk Southern NO & NE subdivision performing a calendar day inspection. Train 19(23) crew completed their inspection and departed Picayune station at 1135PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(23)	35"	

Train 6(23) West of Denver, CO - Debris

25JUL26: Train 6(23) was delayed holding at MP27.90, 28 miles west of Denver, CO. station on the UPRR Moffat Tunnel subdivision due to high winds scattering rocks across the tracks. Maintainers on scene removed the rocks from the tracks and train 6(23) was back on the move at 656PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(23)	35"	

Train 316(24) West of Kirkwood, MO - Debris

25JUL26: Train 316(24) E/ID4605, 8 cars and 100 passengers was delayed at MP44.6, 31.14 miles west of Kirkwood, MO on UPRR Jefferson City subdivision after striking a deer. Engine ID4605 shut down and the train lost head end power upon impact with the deer. Train crew called in to CNOC to help troubleshoot the engine issues. Initial attempts to restart the engine and head end power were unsuccessful. The crew knifed the engine and then let it set several minutes before they were able to successfully restart the engine restoring head end power. Train 316(24) was back on the move at 927PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(24)	55"	

Train Train 355(24) East of Hammond-Whiting, IN - Drawbridge Opening

25JUL26: Train 355(24) was delayed holding at MP503, 5.7 miles east of Hammond-Whiting, IN. station on the Norfolk Southern Chicago 76 subdivision due to the drawbridge not seating. Maintainers responded to the scene and were able to get the drawbridge to seat. Train 355(24) was back on the move at 1053PM CT. Train 48/448(24) was also delayed holding at MP504 waiting for the drawbridge to seat.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
Train 355(24)	44"	
48/448(24)	29"	

Train 1333(24) East of Red Wing, MN - Freight Train Interference

24JUL26: Train 1333(24) was delayed holding at MP326.4, 45.33 miles east of Red Wing MN station on the CPKC River subdivision due to CPKC Freight train 280 stopped ahead with a broken knuckle. Crew attempted to repair the broken knuckle but could not get it removed. Mechanical and field personal responded to the scene and were able to successfully repair the broken knuckle. Train 1333(24) was back on the move at 830PM CT after the freight cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(24)	3'15"	

Train 19(23) North of Laurel, MS - Freight Train Interference

24JUL26: Train 19(23) was delayed holding at MP32.0, 5.5 miles north of Laurel MS station on the Norfolk Southern NO and NE subdivision routing around Norfolk Southern freight train 62Q that was stopped due to PTC issues. Train 19(23) completed the routing around the freight at MP49.5 and resumed operating at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(23)	1'01"	

Train 25(24) North of New Orleans, LA - Freight Train Interference

24JUL26: Train 25(24) was delayed holding at MP795.8, 16..21 miles north of New Orleans LA station on the CSX NO and M meeting CSX Freight train 602(24). The freight cleared to the north and train 25(24) was back on the move south at 828PM CT

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(24)	48"	

Train 822(24) South of Gainesville, TX - Freight Train Interference

24JUL26: Train 822(24) was delayed holding at MP388.3, 22.30 miles south of Gainesville TX station on the BNSF Fort Worth subdivision for a meet with BNSF Freight train 7625. Train 822(24) was back on the move at 645PM CT after the freight cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
822(24)	34"	

UPRR Martinez Subdivision East of Richmond, CA - Fire Near Tracks

24JUL26: Multiple Amtrak trains were delayed on the UPRR Martinez subdivision due to a fire reported near the tracks at milepost 15.29. RMCC placed a hold on all tracks. Train 542(24) was the first train affected, and was held at Richmond, CA for a clear route. The initial estimate for open track was a few hours, due to it being reported as a large vegetation fire affecting the ties and track as well. An Amtrak Trainmaster and Road Foreman as well as UPRR track Foreman responded to the scene. Once the fire was extinguished and the tracks were released for normal service, all trains resumed operations with residual congestion delays in the area. Trains 547(24), 544(24) and 718(24) were also delayed due to this.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
542(24)	1'36"	
544(24)	56"	
547(24)	1'06"	
718(24)	21"	
551(24)	28"	ITD- Equip off 542

Train 22(24) West of Longview, TX - Freight Train Interference

24JUL26: Train 22(24) was delayed holding at MP113.2, 23.9 miles west of Longview TX station on the UPRR Mineola subdivision due to UPRR freight 7258 losing an engine at MP112.9. Freight crew had to set out cars in the siding after losing the engine. Crew set the cars in the siding, put the train back together and proceeded back to the head end. Freight cleared the route and train 22(24) was back on the move at 715PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(24)	1'23"	

Train 4(23) East of Las Vegas, NM - High Wind Warnings

24JUL26: Train 4(23) was delayed beginning 2 miles east of Las Vegas, NM, on the BNSF Raton Subdivision between MP757 to MP726 operating reduced speeds due to high wind warnings.

Train	Delay	Comment
4 (23)	39"	

Metrolink Orange Subdivision - Signal Delays

25JUL26: Multiple trains were delayed between Lincoln/ MP174.7 and Maple / MP172.4 on the SCRR Metrolink Orange Subdivision, 1.58 miles east of Anaheim, CA station, due to vandalism causing signal issues. Train 777(24) was the first train delayed through the area. Once the issue was repaired, normal operations resumed.

Train	Delay	Comment
777 (24)	1'13"	
579 (24)	30"	
782 (24)	09"	
584 (24)	1'18"	

Train 318(24) St. Louis, MO - Engine Failure

24JUL26: Train 318(24), E/ID4613-7 Cars, was delayed at St. Louis, MO (MP1.5) on the TRRA Merchants Subdivision due to mechanical forces repairing an oil leak in the engine room on locomotive ID4613. Head end power was off to the trainset while mechanical forces completed the repair. During the delay, the 193 customers onboard had access to the staffed station and platform, where outdoor temperatures were 76 degrees with cloudy conditions. Once repairs were completed, Train 318(24) was released to continue en route to Chicago.

Train	Delay	Comment
318 (24)	42"	

Train 19(23) North of Birmingham, AL - Freight Train Interference

24JUL26: Train 19(23) was heavily delayed 0.7 miles north of Birmingham, AL (MP143.0), on the NSRR AGS South Subdivision, due to NS 713 being involved in a moving violation ahead that blocked the route into the station. Additional delay was incurred while awaiting the freight recrew to arrive and for the investigation to be completed. Once a route was established, Train 19(23) was able to proceed into the station.

Train	Delay	Comment
19 (23)	2'47"	

Train 20(24) North of Meridian, MS - Freight Train Interference

24JUL26: Train 20(24) was delayed beginning at MP294.8, .2 miles north of Meridian MS station on the Norfolk Southern AGS South subdivision following Norfolk Southern Freight train 130. Train 20(24) followed the freight until MP257 and resumed operating track speed once they were clear of the freight.

Train	Delay	Comment
20 (24)	42"	

Train 7/27(24) Chicago, IL - Engine Failure

24JUL26: Train 7/27(24), E/448-E/353-46 Cars, was delayed departing Chicago Union Station due to locomotive issues. Engine 353 was initially bad ordered for a hydraulic leak, and engine 140 was identified as the replacement. However, engine 140 was subsequently bad ordered due to traction motor issues. Mechanical forces then worked to fully repair the hydraulic leak on engine 353. Once the necessary repairs were completed and engine 353 was returned to service, Train 7/27(24) departed Chicago Union Station at 653PM CT, operating 03 hours and 51 minutes late.

Train	Delay	Comment
7/27(24)	3'51"	

Train 21(24) Chicago, IL - Engine Failure

24JUL26: Train 21(24), E/311-E/171-9 cars, was delayed departing Chicago Union Station due to lead engine 62 being late bad ordered for a burnt HEP coil. Replacement engine 311 was identified and arrived on inbound Train 58(23) at 10:21AM-CT. Engine 311 was then wye'd prior to being added to the head end, resulting in the delayed departure from Chicago, IL. Once engine 311 was positioned and coupled to the consist, Train 21(24) was authorized to depart and continued its scheduled route. Train 21(24) departed Chicago Union station at 453PM CT.

Train	Delay	Comment
21(24)	2'43"	

Havre, MT and Williston, ND - Heat Restrictions

24JUL26: Temperatures in the Great Plains reached temperatures exceeding 100°F. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow and Milk River Subdivision from Havre, MT to Williston, ND. Trains were restricted to 40MPH maximum authorized speed through the affected limits until temperatures recedes below 95°F. Train 7 / 27(23) and Train 8 / 28(23) were affected by the restrictions and freight interference.

Train	Delay	Comment
8/28(23)	2'16"	
7/27(23)	2'55"	

Train 516(24) South of Vancouver, BC - Drawbridge Opening and Freight Interference

24JUL26: Train 516(24) was delayed at Fraser River Junction / MP 142.8 on the Canadian National New Westminster Subdivision, 14 miles south of the Vancouver, British Columbia Pacific Central Station, waiting on CN freight cross traffic and bridge opening for maritime traffic.

Train	Delay	Comment
516(24)	46"	

Train 505(24) Tacoma, WA to Centralia, WA - Car Failure

24JUL26: Train 505(24), operating with Cab Car 7911, 12 cars and Locomotive WS1406, experienced multiple emergency brake application between the Tacoma, WA station and Centralia, WA station. Upon arrival at the Centralia station, the crew was able to cut out the door override which prevented the emergency brake application to return.

Train	Delay	Comment
505(24)	08"	Multiple Brake Applications

Train 500(24) North of Tacoma, WA - Freight Train Interference

24JUL26: Train 500(24) was delayed 1'12" at MP 29.7X on the Burlington Northern Santa Fe Seattle Subdivision, 1 mile north of the Tacoma, WA station, due to HPASVE1-23 (BNSF 7336) experienced an undesired emergency brake application. The freight crew inspected and found a missing extension air hose. It was necessary to hold for a BNSF Carman to respond and deliver a hose extension. Once on the move, Train 500(24) followed the HPASEVE1-23 and XTACBYUL9-24 to Sumner / MP 29.7X.

Train 500(24) and Train 11(24) held at Stewart / MP 34.8X meeting the two freight trains, Train 500(24) and Sounder 1518.

Train	Delay	Comment
500(24)	1'12"	
505(24)	1'02"	
11(24)	29"	
502(24)	14"	

Train 351(24) West of New Buffalo, MI - Signal

24JUL26: Train 351(24) was delayed 20.8 miles west of New Buffalo, MI (MP 218.9) on the Amtrak Michigan Line due to signal issues at CP239 (MP 239.7). Norfolk Southern (NS) was able to provide blocking protection; however, they were unable to acknowledge the westbound signal request. As a result, Train 351(24) was talked through the signal, resulting in delay. Train 365(24) was also delayed through the area due to the same signal issues at CP239.

Train	Delay	Comment
351(24)	24"	
365(24)	20"	

Train 711(24) West of Hanford, CA - Signal Failure

24JUL26: Train 711(24) was delayed between Conejo / MP 981.3 and Anderson / MP 986.4 on the Burlington Northern Santa Fe Bakersfield Subdivision, starting 13 miles west of the Hanford, CA station, account of a code brown failure. The crew was instructed to flag the area.

Train	Delay	Comment
711(24)	45"	

Train 701(24) East of Wasco, CA - Freight Train Interference

24JUL26: Train 701(24) was delayed at MP 910.9 on the Burlington Northern Santa Fe Bakersfield Subdivision, 3 miles east of the Wasco, CA station, due to ZWSPNBY1-22 (BNSF 7322) actuated a wayside detector. The freight crew inspected and found a hot bearing. The car with the hot bearing needed to be set out at Wasco Siding / MP 912.3 before continuing.

One customer was was provided alternate transportation (Uber) between Merced, CA and Los Banos, CA after missing bus connection 4101.

WBS#: B.TR.100150.6935

Train	Delay	Comment
701(24)	2'23"	
713(24)	25"	

Train 522(24) Oakland, CA - Third Party Contractor Car Failure

24JUL26: Train 522(24) departed the Oakland, CA Jack London Station account of late release from mechanical. Mechanical replaced an air valve in Car C8204.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
522(24)	32"	

Train 8/28(23) East of Libby, MT - Switch Failure

24JUL26: Train 8 / 28(23) was delayed at Rock Creek / MP 1272.2 on the Burlington Northern Santa Fe Kootenai River Subdivision, 47 miles east of the Libby, MT station, account of a switch failure. BNSF MoW had been on scene to make repairs.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(23)	37"	

Train 8/28(22) East of Devils Lake, ND - Passenger Train Interference

24JUL26: Train 8/28(22) held 35.1 miles east of Devils Lake, ND (MP85.1), on the BNSF Devils Lake Subdivision, at Michigan (MP50.0) in order to meet Train 7/27(23).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(22)	37"	

Train 40(22) West of Pittsburgh, PA - Freight Train Interference

24JUL26: Train 40(22) was delayed starting 73.7 miles west of Pittsburgh, PA (MP353.1), on the NSRR Cleveland Subdivision, following NS 27G-23 from Murph (MP73.5) to Ravenna (MP85.9). Service recovery was enacted which consisted of complimentary snack packs, bottled water, coffee, and tea out of the cafe for all coach customers. First class customers were served breakfast from the dining car as normal.

WBS#: B.TR.100150.6933

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(22)	46"	

Train 4(22) East of Dodge City, KS - Signal

24JUL26: Train 4(22) was delayed starting 13 miles east of Dodge City, KS (MP352.5), on the BNSF La Junta Subdivision, due to signal issues at East Spearville (MP335.2). As a result, operating speeds were restricted starting at MP339.5 until a clear signal was reached at MP329.8. Train 3(23) was also delayed operating westward through the signal issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(22)	40"	
3(23)	42"	

Train 22(23) South of Walnut Ridge, AR - Freight Train Interference

24JUL26: Train 22(23) was delayed holding at MP281.0, 56.06 miles south of Walnut Ridge AR on the UPRR Hoxie subdivision due to UPRR Freight 7923 stopped ahead after activating a hot wheel detector. Crew inspected and found no issues. UPRR Freight 7923 advanced to the siding clearing a route for 22(23). Train 22(23) was back on the move at 137AM CT.

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station related to WBS 5622 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05, 07, 10JUL)	BYPASS PSN	
1 (01, 04, 08JUL) / 421 (03, 07JUL)	BYPASS PSN	
2/422 (19, 22 JUL)	Bypass	
1 (18, 20, 22JUL) / 421 (17, 19, 21JUL)	Bypass	

Maintenance of Way Highlights

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.

-Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.

-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

-Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

BNSF Track Work West of Macomb, IL - Carl Sandburg Service TWA 26-073

29JUN26: BNSF tie gang will perform trackwork on Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th.

14JUL26: Track was extended one additional week, Monday July 20th through Friday July 24th.

To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL), Train 382(13JUL-17JUL) and Train 382(20JUL-24JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL), Train 381(13JUL-17JUL) and Train 381(20JUL-24JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.

- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track construction project on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Western Region

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		MU issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
318(12)	STL	1	Carried passenger to ALN to wait for Train 21	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00621

00000008478

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
6 (25)	EMY	Operating with ada coach in lieu of bag coach.. Lower level seating inventory has been increased to reflect change.	NO IMPACTED PAX	0	34207
562 (24)	LAX	NO BIKE SERVICE- over capacity. NO WIFI SERVICE.	Passengers notified	314	90225
580 (24)	LAX	NO BIKE SERVICE. NO WIFI SERVICE.	Passengers notified	295	90225
4 (24)	LAX	Operating w/o baggage car a/c 61060 pulled due PM. All checked baggage will be accommodated in the bag coach 31045.	no impacted pax	0	NOCAR
40 (24)	MIA	Viewliner I Sleeper in lieu of Bag Car	No impact	0	62002
609 (24)	NYP	9632 DNL; capped with E/645. Consist is not a push/pull.	NO impact	0	9632
573 (24)	SAN	NO BIKE SERVICE. NO WIFI SERVICE.	Passenger notified	378	90225
591 (24)	SAN	NO BIKE SERVICE- over capacity. NO WIFI SERVICE.	Passengers notified	331	90225
170 (24)	WAS	Business Class in lieu of Coach	no impact	0	81522
134 (24)	WAS	Business class in lieu of Coach.	na	0	81527

Reverse Consists

Train Number	Station	Reason
93 (24)	BOS	Consist reversed Business class seat orientation may have changed At Front
181 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front
113 (24)	NYP	Consist reversed Business class seat orientation may have changed At Rear
183 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front
110 (24)	PHL	Consist reversed Business class seat orientation may have changed At Rear
190 (24)	PHL	Consist reversed Business class seat orientation may have changed At Front
182 (24)	WAS	Consist reversed Business class seat orientation may have changed At Rear

Train Number	Station	Reason	
		26-FOI-00621 00000008478	"UNCLASSIFIED" 8/7/2026
137 (24)	BOS	Consist reversed Business class seat orientation may have changed At Front	
185 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front	
84 (24)	WAS	Consist reversed Business class seat orientation may have changed At Front	
198 (24)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
179 (24)	BOS	Consist reversed Business class seat orientation may have changed At Front	
148 (24)	WAS	Consist reversed Business class seat orientation may have changed At Front	
143 (25)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 143(25)**	
193 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front	
128 (25)	NFK	Consist reversed Business class seat orientation may have changed At Front	