

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, July 28, 2026

Rules: 4-41



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/27/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	47	85.4%	8,301	1,236	85.1%	89,655	12,357	86.2%
Central Division	86.0%	57	7	87.7%	1,504	150	90.0%	17,195	1,541	91.0%
East Division	82.0%	175	23	86.9%	4,379	705	83.9%	46,975	7,318	84.4%
West Division	86.0%	91	17	81.3%	2,418	381	84.2%	25,485	3,498	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00625 00000008486 UNCLASSIFIED 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	109,078	30,085	72%	2,954,614	1,027,106	65%	29,901,938	7,501,392	75%
Northeast Corridor	81%	47,660	8,249	83%	1,268,557	425,093	66%	13,112,338	3,208,286	76%
Acela	83%	11,127	3,036	73%	278,566	89,592	68%	2,615,331	692,269	74%
Northeast Regional	79%	36,533	5,213	86%	989,991	335,501	66%	10,497,007	2,516,017	76%
Richmond / Newport News / Norfolk	77%	11,270	3,246	71%	309,276	133,839	57%	3,260,004	947,460	71%
Springfield Shuttles	89%	579	116	80%	17,902	5,484	69%	185,936	29,698	84%
Roanoke	79%	2,964	651	78%	95,687	38,169	60%	988,747	213,454	78%
On Spine Northeast Regional	80%	21,720	1,200	94%	567,126	158,009	72%	6,062,320	1,325,405	78%
State Supported	80%	47,009	13,226	72%	1,328,505	379,544	71%	13,114,553	2,741,908	79%
Borealis	80%	551	442	20%	16,234	3,758	77%	167,204	34,204	80%
Capitol Corridor	90%	3,754	385	90%	100,504	15,231	85%	1,101,723	144,427	87%
Carolinian	70%	1,080	42	96%	30,468	16,897	45%	340,442	132,803	61%
Cascades	75%	2,706	933	66%	84,734	22,714	73%	772,378	211,274	73%
Downeaster	82%	1,846	0	100%	54,135	9,545	82%	451,633	55,015	88%
Empire	78%	6,786	1,685	75%	169,562	59,119	65%	1,623,567	373,536	77%
Adirondack	72%	514	23	96%	12,077	4,614	62%	98,510	30,098	69%
Ethan Allen Express	70%	650	622	4%	16,040	11,415	29%	167,005	59,022	65%
Maple Leaf	70%	914	354	61%	23,253	9,406	60%	198,072	76,193	62%
New York - Albany	85%	3,223	325	90%	75,897	17,472	77%	753,062	121,372	84%
New York - Niagara Falls	75%	1,485	361	76%	37,880	13,795	64%	399,339	83,574	79%
Berkshire Flyer	60%	0	0	-	4,415	2,417	45%	7,579	3,277	57%
Gold Runner	73%	2,526	1,546	39%	71,506	31,782	56%	745,126	263,880	65%
Heartland Flyer	70%	260	14	95%	7,789	4,186	46%	63,494	24,679	61%
Hiawatha	90%	1,682	717	57%	55,547	5,400	90%	513,241	55,948	89%
Illinois	78%	2,850	1,118	61%	72,901	24,497	66%	735,056	200,541	73%
Carl Sandburg / Illinois Zephyr	85%	451	398	12%	13,305	5,186	61%	122,859	32,992	73%
Illini / Saluki	85%	781	292	63%	23,457	7,349	69%	257,119	61,376	76%
Lincoln Service	70%	1,618	428	74%	36,139	11,962	67%	355,078	106,173	70%
Keystone	92%	8,708	1	100%	201,757	26,887	87%	2,258,834	236,822	90%
Lincoln / Missouri	70%	352	29	92%	20,800	12,659	39%	229,319	116,475	49%
Mardi Gras Service	80%	341	150	56%	10,406	4,285	59%	121,354	26,746	78%
Michigan	70%	1,869	817	56%	67,074	23,904	64%	586,821	188,859	68%
Blue Water	70%	294	293	0%	16,573	8,992	46%	136,799	54,326	60%
Pere Marquette	85%	207	0	100%	9,511	1,572	83%	77,083	14,902	81%
Wolverine	70%	1,368	524	62%	40,990	13,340	67%	372,939	119,631	68%
Missouri	80%	101	93	8%	5,756	2,553	56%	64,992	15,793	76%
Pacific Surfliner	85%	8,741	4,288	51%	278,814	84,972	70%	2,361,338	412,134	83%
Pennsylvanian	80%	853	0	100%	23,569	8,104	66%	262,279	50,263	81%
Piedmont	80%	763	59	92%	22,795	9,079	60%	336,180	87,633	74%
Vermont	75%	1,240	907	27%	34,154	13,972	59%	379,572	110,876	71%
Long Distance	70%	14,409	8,610	40%	357,552	222,469	38%	3,635,780	1,548,735	57%
Auto Train	70%	870	453	48%	22,276	9,126	59%	231,120	79,954	65%
California Zephyr	70%	907	644	29%	28,563	19,206	33%	288,626	104,503	64%
Cardinal	70%	372	46	88%	7,037	4,681	33%	70,711	34,923	51%
City Of New Orleans	75%	792	579	27%	11,004	6,353	42%	188,368	55,970	70%
Coast Starlight	70%	1,376	342	75%	34,687	14,116	59%	339,451	118,568	65%
Crescent	70%	1,006	126	87%	25,294	13,211	48%	275,787	85,303	69%
Empire Builder	70%	972	789	19%	33,392	21,566	35%	286,453	140,318	51%
Floridian	60%	1,856	1,604	14%	41,879	38,248	9%	472,044	321,891	32%
Lake Shore Ltd	73%	1,314	424	68%	32,625	12,222	63%	284,262	83,832	71%
Palmetto	70%	955	143	85%	24,961	14,943	40%	272,734	81,041	70%
Silver Meteor	70%	1,229	1,059	14%	28,857	24,269	16%	301,238	134,421	55%
Southwest Chief	60%	978	957	2%	27,528	20,707	25%	246,178	159,119	35%
Sunset Ltd	70%	608	579	5%	8,447	4,954	41%	86,832	31,635	64%
Texas Eagle	70%	1,174	865	26%	31,002	18,867	39%	291,976	117,257	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00025 00000000400 "UNCLASSIFIED" 8/7/2026

Train Index Dates Through July 27, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	193,394	2,878,419	672	1,760,926	31,510,653	559

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	11,129	851,999	131	84,519	9,061,476	93
INFRASTRUCTURE PLANNED	135	14,713	851,999	173	93,613	9,061,476	103
FLEET RELIABILITY	90	28,121	2,878,419	98	281,371	31,510,653	89
TRAIN OPERATIONS	424	139,431	2,878,419	484	1,301,423	31,510,653	413

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/27/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	47	85.4%	8,301	1,236	85.1%	89,655	12,357	86.2%
Central Division	86.0%	57	7	87.7%	1,504	150	90.0%	17,195	1,541	91.0%
East Division	82.0%	175	23	86.9%	4,379	705	83.9%	46,975	7,318	84.4%
West Division	86.0%	91	17	81.3%	2,418	381	84.2%	25,485	3,498	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/27/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/27/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	47	85.4%	8,301	1,236	85.1%	89,655	12,357	86.2%
Central Division	86.0%	57	7	87.7%	1,504	150	90.0%	17,195	1,541	91.0%
CDL	95.0%	2	0	100.0%	51	5	90.2%	568	23	96.0%
CHI	86.0%	26	3	88.5%	705	86	87.8%	7,942	949	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	1	0	100.0%	1	0	100.0%	59	3	94.9%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	27	1	96.3%	323	35	89.2%
GBB	-	-	-	-	13	11	15.4%	13	11	15.4%
GRR	95.5%	1	0	100.0%	26	0	100.0%	285	8	97.2%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	-	-	-	43	3	93.0%	581	43	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	2	66.7%	158	12	92.4%	1,756	109	93.8%
MOE	97.5%	2	0	100.0%	52	1	98.1%	597	9	98.5%
MSP	96.5%	1	0	100.0%	27	0	100.0%	293	5	98.3%
NOL	94.5%	5	1	80.0%	106	7	93.4%	1,256	60	95.2%
OKC	97.0%	1	0	100.0%	27	0	100.0%	294	6	98.0%
PNT	88.0%	3	0	100.0%	72	6	91.7%	775	64	91.7%
PTH	93.0%	1	0	100.0%	27	1	96.3%	288	11	96.2%
QCY	91.0%	2	0	100.0%	38	3	92.1%	569	43	92.4%
SAS	90.5%	1	0	100.0%	28	5	82.1%	297	32	89.2%
STL	89.0%	4	1	75.0%	102	8	92.2%	1,159	98	91.5%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	23	86.9%	4,379	705	83.9%	46,975	7,318	84.4%
ALB	88.5%	8	0	100.0%	208	8	96.2%	2,222	169	92.4%
ATL	-	-	-	-	1	1	0.0%	36	6	83.3%
BON	87.5%	5	1	80.0%	134	16	88.1%	1,446	156	89.2%
BOS	85.5%	18	0	100.0%	453	32	92.9%	5,093	594	88.3%
BRK	92.5%	5	0	100.0%	131	18	86.3%	1,432	102	92.9%
BTN	82.0%	1	0	100.0%	27	1	96.3%	286	40	86.0%
CLT	91.5%	5	0	100.0%	116	18	84.5%	1,457	150	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	54	7	87.0%	585	57	90.3%
GRO	-	-	-	-	4	0	100.0%	33	10	69.7%
HAR	79.5%	13	4	69.2%	289	40	86.2%	3,312	546	83.5%
HFD	-	2	0	100.0%	36	5	86.1%	183	13	92.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	27	3	88.9%	296	37	87.5%
MIA	89.5%	2	0	100.0%	53	8	84.9%	592	68	88.5%
MTR	79.0%	1	0	100.0%	27	5	81.5%	283	51	82.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/27/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/27/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	47	85.4%	8,301	1,236	85.1%	89,655	12,357	86.2%
East Division	82.0%	175	23	86.9%	4,379	705	83.9%	46,975	7,318	84.4%
NFK	84.5%	2	0	100.0%	54	14	74.1%	675	123	81.8%
NFL	93.5%	2	0	100.0%	54	4	92.6%	604	26	95.7%
NFS	-	-	-	-	1	1	0.0%	7	6	14.3%
NHV	78.0%	5	4	20.0%	128	30	76.6%	1,534	253	83.5%
NPN	93.0%	2	0	100.0%	52	6	88.5%	565	41	92.7%
NYP	75.5%	50	9	82.0%	1,233	273	77.9%	12,287	2,734	77.7%
PGH	93.0%	1	0	100.0%	26	3	88.5%	297	22	92.6%
PHL	48.0%	5	2	60.0%	130	55	57.7%	1,530	732	52.2%
PIT	76.0%	-	-	-	8	6	25.0%	14	11	21.4%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	4	0	100.0%	85	7	91.8%	1,142	48	95.8%
RNK	83.5%	2	0	100.0%	54	9	83.3%	588	86	85.4%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	24	1	95.8%	283	5	98.2%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	25	0	100.0%	293	10	96.6%
SFA	88.0%	1	1	0.0%	27	4	85.2%	296	41	86.1%
SPG	92.5%	4	0	100.0%	135	12	91.1%	1,787	104	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	26	2	92.3%	285	58	79.6%
WAS	84.0%	31	2	93.5%	753	112	85.1%	7,349	953	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	91	17	81.3%	2,418	381	84.2%	25,485	3,498	86.3%
ARN	92.0%	1	0	100.0%	27	7	74.1%	298	26	91.3%
BFD	79.0%	7	2	71.4%	184	45	75.5%	1,870	386	79.4%
EMY	72.0%	1	0	100.0%	27	9	66.7%	314	94	70.1%
EUG	86.5%	2	0	100.0%	54	3	94.4%	590	55	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	3	2	33.3%	4	3	25.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	81	22	72.8%	897	136	84.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	5	50.0%	282	41	85.5%	2,957	317	89.3%
MCD	-	-	-	-	7	6	14.3%	15	13	13.3%
OKJ	74.5%	13	2	84.6%	310	83	73.2%	3,209	819	74.5%
PDX	86.0%	5	2	60.0%	134	13	90.3%	1,471	179	87.8%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	1	93.8%	398	46	88.4%	4,203	456	89.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/27/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	47	85.4%	8,301	1,236	85.1%	89,655	12,357	86.2%
West Division	86.0%	91	17	81.3%	2,418	381	84.2%	25,485	3,498	86.3%
SAN	90.5%	12	2	83.3%	348	44	87.4%	3,592	338	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	214	31	85.5%	2,356	341	85.5%
SJC	89.0%	7	0	100.0%	189	24	87.3%	2,096	206	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	81	3	96.3%	660	63	90.5%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	26	2	92.3%	292	22	92.5%
VAC	97.0%	2	0	100.0%	53	0	100.0%	583	14	97.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	805	12	1	91.7%	127	9	92.9%	12	7	41.7%	127	30	76.4%
3	208	27	4	85.2%	298	58	80.5%	27	15	44.4%	296	132	55.4%
4	218	27	4	85.2%	297	46	84.5%	27	17	37.0%	297	196	34.0%
5	69	27	5	81.5%	296	48	83.8%	26	21	19.2%	292	84	71.2%
6	79	27	9	66.7%	295	85	71.2%	28	19	32.1%	296	101	65.9%
7	374	27	5	81.5%	287	40	86.1%	27	11	59.3%	280	72	74.3%
8	342	27	15	44.4%	287	126	56.1%	27	22	18.5%	286	171	40.2%
11		27	5	81.5%	298	55	81.5%	27	6	77.8%	292	60	79.5%
14		27	6	77.8%	299	47	84.3%	27	8	70.4%	297	91	69.4%
19		27	10	63.0%	297	75	74.7%	26	12	53.8%	294	71	75.9%
20		27	5	81.5%	297	23	92.3%	27	11	59.3%	297	58	80.5%
21	71	27	2	92.6%	294	24	91.8%	27	17	37.0%	293	79	73.0%
22	409	27	5	81.5%	295	30	89.8%	27	17	37.0%	293	79	73.0%
23	53	26	1	96.2%	299	6	98.0%	26	14	46.2%	297	83	72.1%
24		26	2	92.3%	299	16	94.6%	26	12	53.8%	298	55	81.5%
25	21	26	0	100.0%	298	3	99.0%	26	13	50.0%	296	82	72.3%
26		26	0	100.0%	298	5	98.3%	26	6	76.9%	296	58	80.4%
40		26	3	88.5%	292	41	86.0%	25	20	20.0%	290	152	47.6%
41	205	25	10	60.0%	291	112	61.5%	25	24	4.0%	289	220	23.9%
42		27	4	85.2%	299	24	92.0%	27	8	70.4%	297	50	83.2%
43		27	1	96.3%	298	42	85.9%	26	14	46.2%	297	70	76.4%
48		27	4	85.2%	297	57	80.8%	27	4	85.2%	297	42	85.9%
49		27	6	77.8%	297	73	75.4%	27	8	70.4%	297	60	79.8%
51		12	5	58.3%	124	54	56.5%	12	6	50.0%	120	43	64.2%
52		27	4	85.2%	296	41	86.1%	27	10	63.0%	295	71	75.9%
53	154	27	3	88.9%	296	37	87.5%	27	9	66.7%	295	94	68.1%
55		18	1	94.4%	186	7	96.2%	18	4	77.8%	183	38	79.2%
56	45	18	1	94.4%	187	23	87.7%	17	7	58.8%	183	33	82.0%
58	45	15	0	100.0%	274	16	94.2%	15	6	60.0%	273	71	74.0%
63	93	27	13	51.9%	300	130	56.7%	25	22	12.0%	294	162	44.9%
64	19	27	3	88.9%	298	66	77.9%	27	17	37.0%	298	108	63.8%
66		27	7	74.1%	297	61	79.5%	25	4	84.0%	293	53	81.9%
67		18	2	88.9%	205	13	93.7%	17	4	76.5%	204	35	82.8%
68		27	5	81.5%	300	60	80.0%	27	13	51.9%	300	116	61.3%
69		27	6	77.8%	287	65	77.4%	27	10	63.0%	283	42	85.2%
71	20	27	0	100.0%	295	3	99.0%	27	14	48.1%	294	80	72.8%
72		23	2	91.3%	291	31	89.3%	23	6	73.9%	290	61	79.0%
73	12	22	2	90.9%	294	18	93.9%	22	14	36.4%	292	140	52.1%
74		22	3	86.4%	292	33	88.7%	22	13	40.9%	290	107	63.1%
75		18	2	88.9%	288	16	94.4%	17	10	41.2%	282	135	52.1%
76		18	3	83.3%	288	29	89.9%	17	10	41.2%	279	114	59.1%
77		21	3	85.7%	290	20	93.1%	21	14	33.3%	288	122	57.6%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		26	5	80.8%	294	25	91.5%	26	12	53.8%	293	62	78.8%
79		27	1	96.3%	297	56	81.1%	27	15	44.4%	296	99	66.6%
80		27	5	81.5%	297	33	88.9%	26	13	50.0%	294	62	78.9%
84		15	2	86.7%	177	13	92.7%	15	7	53.3%	175	42	76.0%
85		18	0	100.0%	188	16	91.5%	18	8	55.6%	188	69	63.3%
86	23	18	1	94.4%	188	15	92.0%	18	12	33.3%	187	112	40.1%
89		27	6	77.8%	295	64	78.3%	27	15	44.4%	293	85	71.0%
90		27	0	100.0%	295	10	96.6%	27	12	55.6%	294	49	83.3%
93		18	0	100.0%	187	18	90.4%	18	8	55.6%	186	45	75.8%
94	34	18	5	72.2%	218	55	74.8%	18	12	33.3%	216	81	62.5%
95		18	1	94.4%	187	4	97.9%	18	9	50.0%	187	68	63.6%
97		27	24	11.1%	297	197	33.7%	27	21	22.2%	295	97	67.1%
98	34	27	5	81.5%	297	26	91.2%	27	25	7.4%	295	105	64.4%
110		18	5	72.2%	184	101	45.1%	18	2	88.9%	181	18	90.1%
111		18	3	83.3%	178	35	80.3%	18	1	94.4%	176	21	88.1%
112		18	1	94.4%	178	17	90.4%	18	2	88.9%	177	19	89.3%
113		18	2	88.9%	109	24	78.0%	18	2	88.9%	108	13	88.0%
119		15	1	93.3%	175	44	74.9%	15	2	86.7%	173	22	87.3%
125		18	2	88.9%	188	10	94.7%	18	7	61.1%	188	73	61.2%
128	55	9	0	100.0%	112	19	83.0%	9	6	33.3%	112	22	80.4%
129		18	3	83.3%	187	47	74.9%	18	4	77.8%	187	27	85.6%
130		18	2	88.9%	178	18	89.9%	18	1	94.4%	176	16	90.9%
131		18	5	72.2%	180	52	71.1%	18	6	66.7%	180	35	80.6%
134		18	4	77.8%	188	25	86.7%	18	8	55.6%	187	34	81.8%
137		18	4	77.8%	185	34	81.6%	18	6	66.7%	185	58	68.6%
138		18	4	77.8%	188	39	79.3%	18	6	66.7%	187	33	82.4%
139		4	0	100.0%	38	5	86.8%	4	2	50.0%	38	13	65.8%
141		18	0	100.0%	187	3	98.4%	18	4	77.8%	186	32	82.8%
148		18	2	88.9%	187	19	89.8%	18	5	72.2%	185	35	81.1%
151		27	9	66.7%	296	95	67.9%	27	11	59.3%	295	95	67.8%
166		4	1	75.0%	38	5	86.8%	4	2	50.0%	37	13	64.9%
169		9	0	100.0%	110	12	89.1%	9	3	66.7%	110	24	78.2%
170		18	0	100.0%	183	12	93.4%	18	0	100.0%	182	29	84.1%
171	40	18	0	100.0%	188	10	94.7%	18	13	27.8%	188	74	60.6%
172		18	0	100.0%	187	14	92.5%	18	4	77.8%	185	59	68.1%
173		15	1	93.3%	180	24	86.7%	15	4	73.3%	179	77	57.0%
174		18	0	100.0%	188	20	89.4%	18	9	50.0%	188	47	75.0%
175		18	0	100.0%	188	21	88.8%	18	5	72.2%	188	60	68.1%
176		15	1	93.3%	180	15	91.7%	15	6	60.0%	178	21	88.2%
177		18	1	94.4%	188	25	86.7%	18	1	94.4%	188	45	76.1%
181		18	3	83.3%	184	57	69.0%	18	2	88.9%	182	14	92.3%
182	36	18	2	88.9%	178	30	83.1%	18	5	72.2%	176	21	88.1%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		18	7	61.1%	187	55	70.6%	17	5	70.6%	184	38	79.3%
184		18	4	77.8%	188	33	82.4%	18	4	77.8%	187	27	85.6%
185		18	1	94.4%	188	37	80.3%	18	3	83.3%	188	14	92.6%
186		18	3	83.3%	187	20	89.3%	18	9	50.0%	186	49	73.7%
190		18	4	77.8%	187	66	64.7%	18	4	77.8%	186	41	78.0%
192		18	5	72.2%	185	24	87.0%	18	3	83.3%	185	17	90.8%
193		15	5	66.7%	184	76	58.7%	15	6	60.0%	183	86	53.0%
196		15	1	93.3%	184	19	89.7%	15	0	100.0%	183	15	91.8%
197	17	18	7	61.1%	188	75	60.1%	18	12	33.3%	188	65	65.4%
230		27	0	100.0%	134	4	97.0%	27	0	100.0%	134	6	95.5%
232		27	0	100.0%	300	11	96.3%	27	2	92.6%	300	19	93.7%
233		19	4	78.9%	270	60	77.8%	19	13	31.6%	270	86	68.1%
234		27	1	96.3%	300	20	93.3%	27	0	100.0%	300	24	92.0%
235		27	5	81.5%	224	32	85.7%	27	10	63.0%	224	51	77.2%
236		27	2	92.6%	284	9	96.8%	27	3	88.9%	284	39	86.3%
237		27	4	85.2%	298	56	81.2%	27	7	74.1%	296	50	83.1%
238		27	0	100.0%	224	19	91.5%	27	3	88.9%	223	17	92.4%
239		27	5	81.5%	299	77	74.2%	27	6	77.8%	298	36	87.9%
240	24	27	0	100.0%	299	20	93.3%	27	14	48.1%	297	58	80.5%
241		27	5	81.5%	300	73	75.7%	27	3	88.9%	300	69	77.0%
243		27	8	70.4%	236	63	73.3%	27	5	81.5%	235	31	86.8%
244		19	2	89.5%	270	12	95.6%	19	9	52.6%	270	47	82.6%
245		27	5	81.5%	181	32	82.3%	27	3	88.9%	180	20	88.9%
280		27	2	92.6%	300	13	95.7%	27	8	70.4%	300	58	80.7%
281		27	6	77.8%	300	35	88.3%	27	9	66.7%	300	56	81.3%
283		27	9	66.7%	300	73	75.7%	27	8	70.4%	300	60	80.0%
284	21	27	2	92.6%	300	12	96.0%	27	12	55.6%	298	54	81.9%
290	43	27	1	96.3%	300	49	83.7%	27	21	22.2%	298	112	62.4%
291	47	27	15	44.4%	299	90	69.9%	27	15	44.4%	297	73	75.4%
300		27	1	96.3%	284	20	93.0%	27	10	63.0%	282	66	76.6%
301		26	1	96.2%	297	10	96.6%	25	5	80.0%	293	55	81.2%
302		21	2	90.5%	279	33	88.2%	21	5	76.2%	275	77	72.0%
305	26	21	0	100.0%	282	28	90.1%	21	11	47.6%	278	113	59.4%
306	29	26	0	100.0%	295	15	94.9%	26	9	65.4%	294	80	72.8%
307		27	3	88.9%	288	38	86.8%	27	11	59.3%	285	81	71.6%
318		26	5	80.8%	298	31	89.6%	26	18	30.8%	295	142	51.9%
319		26	3	88.5%	299	20	93.3%	23	17	26.1%	294	162	44.9%
329		19	0	100.0%	211	8	96.2%	19	0	100.0%	211	13	93.8%
330		23	0	100.0%	254	4	98.4%	23	1	95.7%	254	14	94.5%
331		27	3	88.9%	300	32	89.3%	27	3	88.9%	300	43	85.7%
332	29	27	3	88.9%	300	17	94.3%	27	4	85.2%	300	43	85.7%
334		27	1	96.3%	300	10	96.7%	27	3	88.9%	299	39	87.0%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335	12	27	2	92.6%	300	32	89.3%	27	7	74.1%	298	50	83.2%
336		27	1	96.3%	300	9	97.0%	27	2	92.6%	298	27	90.9%
337		27	1	96.3%	300	18	94.0%	27	3	88.9%	296	36	87.8%
338	20	27	5	81.5%	300	46	84.7%	27	10	63.0%	298	91	69.5%
339	105	27	4	85.2%	300	50	83.3%	27	4	85.2%	300	52	82.7%
341	65	27	7	74.1%	289	42	85.5%	27	5	81.5%	284	40	85.9%
342	91	27	2	92.6%	300	23	92.3%	27	5	81.5%	298	58	80.5%
350		23	1	95.7%	277	18	93.5%	21	11	47.6%	270	147	45.6%
351		27	2	92.6%	283	27	90.5%	27	10	63.0%	281	78	72.2%
352	187	27	1	96.3%	267	21	92.1%	27	9	66.7%	261	80	69.3%
353	72	23	1	95.7%	238	13	94.5%	23	3	87.0%	232	38	83.6%
354	19	27	7	74.1%	281	35	87.5%	24	10	58.3%	274	99	63.9%
355	51	23	4	82.6%	290	31	89.3%	23	12	47.8%	283	97	65.7%
364	101	27	4	85.2%	289	64	77.9%	27	16	40.7%	283	106	62.5%
365	29	27	1	96.3%	288	11	96.2%	27	15	44.4%	286	107	62.6%
370	Cncld	27	2	92.6%	291	35	88.0%	24	3	87.5%	281	68	75.8%
371		26	0	100.0%	285	8	97.2%	26	2	92.3%	284	29	89.8%
380	36	26	3	88.5%	285	27	90.5%	26	12	53.8%	285	61	78.6%
381	21	25	1	96.0%	298	12	96.0%	25	10	60.0%	297	58	80.5%
382	27	25	11	56.0%	297	27	90.9%	25	13	48.0%	297	97	67.3%
383		27	1	96.3%	289	26	91.0%	26	14	46.2%	286	119	58.4%
390	25	27	1	96.3%	282	18	93.6%	27	9	66.7%	281	72	74.4%
391		25	3	88.0%	283	11	96.1%	25	10	60.0%	280	75	73.2%
392		24	4	83.3%	296	9	97.0%	24	11	54.2%	294	89	69.7%
393	21	27	1	96.3%	300	17	94.3%	27	13	51.9%	297	90	69.7%
417		18	6	66.7%	198	44	77.8%	18	5	72.2%	189	22	88.4%
425		18	0	100.0%	200	6	97.0%	18	0	100.0%	200	7	96.5%
448	42	27	6	77.8%	230	44	80.9%	27	10	63.0%	228	78	65.8%
449		27	2	92.6%	228	32	86.0%	27	6	77.8%	228	42	81.6%
470		18	3	83.3%	211	37	82.5%	18	1	94.4%	205	24	88.3%
471		18	4	77.8%	201	10	95.0%	18	3	83.3%	201	5	97.5%
473		18	1	94.4%	207	14	93.2%	18	1	94.4%	204	9	95.6%
474	21	21	12	42.9%	205	63	69.3%	18	15	16.7%	190	62	67.4%
475		18	1	94.4%	205	6	97.1%	18	5	72.2%	205	15	92.7%
478	47	18	5	72.2%	199	32	83.9%	18	7	61.1%	197	27	86.3%
479		18	5	72.2%	206	34	83.5%	18	9	50.0%	204	31	84.8%
486		18	3	83.3%	210	31	85.2%	18	7	61.1%	204	57	72.1%
494	83	19	6	68.4%	212	41	80.7%	18	13	27.8%	205	57	72.2%
500		27	1	96.3%	291	16	94.5%	26	3	88.5%	288	35	87.8%
502		27	3	88.9%	298	18	94.0%	26	1	96.2%	294	57	80.6%
503	71	27	2	92.6%	296	27	90.9%	26	13	50.0%	289	87	69.9%
504		27	1	96.3%	300	18	94.0%	27	7	74.1%	298	89	70.1%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		27	3	88.9%	298	39	86.9%	26	9	65.4%	293	82	72.0%
506		27	3	88.9%	295	41	86.1%	26	4	84.6%	289	45	84.4%
507		27	2	92.6%	300	36	88.0%	27	10	63.0%	300	98	67.3%
508		27	2	92.6%	295	41	86.1%	26	4	84.6%	291	66	77.3%
509		27	2	92.6%	297	14	95.3%	27	3	88.9%	297	66	77.8%
511		27	2	92.6%	292	23	92.1%	27	3	88.9%	291	48	83.5%
516	54	26	1	96.2%	291	28	90.4%	26	8	69.2%	290	131	54.8%
517	77	27	0	100.0%	300	8	97.3%	27	17	37.0%	296	125	57.8%
518	23	27	1	96.3%	300	36	88.0%	27	20	25.9%	298	203	31.9%
519		26	0	100.0%	291	9	96.9%	26	1	96.2%	289	64	77.9%
520		19	1	94.7%	169	25	85.2%	19	0	100.0%	166	9	94.6%
521		19	0	100.0%	207	7	96.6%	19	4	78.9%	207	27	87.0%
522		19	4	78.9%	207	40	80.7%	19	2	89.5%	204	20	90.2%
523		19	1	94.7%	207	7	96.6%	19	0	100.0%	206	22	89.3%
524		19	4	78.9%	207	15	92.8%	19	3	84.2%	205	23	88.8%
525		19	2	89.5%	205	14	93.2%	18	0	100.0%	201	13	93.5%
526		19	4	78.9%	181	33	81.8%	19	2	89.5%	178	14	92.1%
527		19	1	94.7%	207	10	95.2%	19	5	73.7%	206	37	82.0%
528		19	2	89.5%	207	17	91.8%	19	1	94.7%	206	30	85.4%
529	16	19	1	94.7%	207	12	94.2%	19	7	63.2%	206	57	72.3%
530		19	2	89.5%	161	16	90.1%	19	6	68.4%	161	32	80.1%
531		19	1	94.7%	181	13	92.8%	19	2	89.5%	181	13	92.8%
532		19	7	63.2%	207	50	75.8%	19	4	78.9%	206	31	85.0%
534		19	1	94.7%	166	25	84.9%	19	1	94.7%	164	16	90.2%
535		19	2	89.5%	194	25	87.1%	19	2	89.5%	189	22	88.4%
536		19	6	68.4%	207	55	73.4%	18	1	94.4%	203	38	81.3%
537	22	19	4	78.9%	178	22	87.6%	18	4	77.8%	172	20	88.4%
538		19	0	100.0%	207	23	88.9%	19	5	73.7%	206	42	79.6%
539	11	19	3	84.2%	161	23	85.7%	19	7	63.2%	161	71	55.9%
540		18	3	83.3%	206	38	81.6%	17	0	100.0%	198	18	90.9%
541		19	1	94.7%	206	22	89.3%	18	3	83.3%	200	36	82.0%
542		19	3	84.2%	206	24	88.3%	18	4	77.8%	203	36	82.3%
543	54	19	4	78.9%	207	23	88.9%	19	12	36.8%	207	62	70.0%
544	24	19	0	100.0%	205	20	90.2%	19	4	78.9%	202	19	90.6%
545		19	2	89.5%	207	17	91.8%	18	2	88.9%	204	24	88.2%
547		19	3	84.2%	207	40	80.7%	19	2	89.5%	207	46	77.8%
548		18	1	94.4%	202	21	89.6%	17	1	94.1%	200	15	92.5%
549		19	1	94.7%	202	26	87.1%	18	1	94.4%	194	17	91.2%
550		19	3	84.2%	161	17	89.4%	19	4	78.9%	161	35	78.3%
551		19	3	84.2%	203	22	89.2%	18	2	88.9%	194	19	90.2%
562	32	26	1	96.2%	291	22	92.4%	26	5	80.8%	288	34	88.2%
564	32	27	2	92.6%	292	19	93.5%	27	7	74.1%	284	37	87.0%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
566	44	27	7	74.1%	290	24	91.7%	27	10	63.0%	287	42	85.4%
567		27	2	92.6%	177	10	94.4%	27	3	88.9%	175	9	94.9%
572	30	27	1	96.3%	287	23	92.0%	26	16	38.5%	281	81	71.2%
573		27	0	100.0%	290	40	86.2%	27	6	77.8%	283	50	82.3%
579		27	2	92.6%	177	10	94.4%	27	9	66.7%	172	35	79.7%
580	Cncld	27	1	96.3%	292	15	94.9%	26	7	73.1%	286	28	90.2%
581		27	5	81.5%	292	48	83.6%	27	8	70.4%	290	62	78.6%
584	54	27	7	74.1%	176	24	86.4%	26	23	11.5%	171	105	38.6%
587		26	1	96.2%	286	16	94.4%	26	14	46.2%	277	52	81.2%
588	52	27	6	77.8%	177	18	89.8%	27	9	66.7%	176	31	82.4%
593	41	27	10	63.0%	286	47	83.6%	24	8	66.7%	265	35	86.8%
595	No OS	27	12	55.6%	287	53	81.5%	27	12	55.6%	284	58	79.6%
600		18	0	100.0%	215	9	95.8%	18	4	77.8%	213	19	91.1%
601		18	10	44.4%	198	82	58.6%	18	2	88.9%	195	25	87.2%
605		18	9	50.0%	205	127	38.0%	18	3	83.3%	201	22	89.1%
607		18	5	72.2%	214	29	86.4%	18	3	83.3%	211	25	88.2%
609		18	1	94.4%	205	23	88.8%	18	4	77.8%	204	19	90.7%
622		14	2	85.7%	117	32	72.6%	14	0	100.0%	115	5	95.7%
626		18	4	77.8%	119	16	86.6%	18	3	83.3%	117	18	84.6%
637	11	9	1	88.9%	63	7	88.9%	9	1	88.9%	63	5	92.1%
639		17	1	94.1%	185	38	79.5%	17	0	100.0%	184	19	89.7%
640		18	0	100.0%	205	7	96.6%	18	4	77.8%	203	80	60.6%
641		18	4	77.8%	187	38	79.7%	18	1	94.4%	187	26	86.1%
642		18	0	100.0%	203	9	95.6%	18	3	83.3%	202	26	87.1%
643		18	3	83.3%	217	42	80.6%	18	4	77.8%	214	36	83.2%
644		18	1	94.4%	209	28	86.6%	18	3	83.3%	207	51	75.4%
645		18	3	83.3%	217	41	81.1%	17	6	64.7%	214	45	79.0%
646		18	5	72.2%	206	51	75.2%	18	11	38.9%	204	100	51.0%
647		18	1	94.4%	217	32	85.3%	18	4	77.8%	216	47	78.2%
648	13	18	5	72.2%	213	55	74.2%	18	3	83.3%	213	34	84.0%
649		18	4	77.8%	218	41	81.2%	18	3	83.3%	215	34	84.2%
650		18	2	88.9%	217	41	81.1%	18	5	72.2%	214	35	83.6%
651		18	0	100.0%	217	16	92.6%	18	3	83.3%	215	42	80.5%
652		18	2	88.9%	218	29	86.7%	18	5	72.2%	214	37	82.7%
653		18	3	83.3%	206	33	84.0%	18	4	77.8%	203	38	81.3%
654		18	3	83.3%	207	39	81.2%	17	1	94.1%	203	17	91.6%
655		18	3	83.3%	215	72	66.5%	18	5	72.2%	213	73	65.7%
656	12	18	2	88.9%	217	47	78.3%	18	8	55.6%	216	29	86.6%
657		18	1	94.4%	206	27	86.9%	18	1	94.4%	205	29	85.9%
658		18	1	94.4%	217	35	83.9%	18	2	88.9%	215	32	85.1%
680		19	3	84.2%	212	12	94.3%	19	3	84.2%	211	27	87.2%
681		19	2	89.5%	212	16	92.5%	18	11	38.9%	206	83	59.7%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
682	13	19	1	94.7%	211	6	97.2%	19	5	73.7%	211	38	82.0%
683		19	2	89.5%	194	17	91.2%	19	14	26.3%	193	65	66.3%
684	13	19	5	73.7%	193	32	83.4%	19	6	68.4%	193	44	77.2%
685		19	3	84.2%	208	31	85.1%	19	8	57.9%	205	52	74.6%
686		19	4	78.9%	213	37	82.6%	19	9	52.6%	212	45	78.8%
687		19	3	84.2%	212	33	84.4%	19	4	78.9%	211	35	83.4%
688		19	4	78.9%	211	13	93.8%	19	6	68.4%	210	36	82.9%
701		27	4	85.2%	232	25	89.2%	27	5	81.5%	229	25	89.1%
702		27	1	96.3%	299	32	89.3%	26	8	69.2%	296	68	77.0%
703	No OS	27	15	44.4%	300	92	69.3%	26	14	46.2%	298	84	71.8%
704	Cncld	27	4	85.2%	231	36	84.4%	25	5	80.0%	224	43	80.8%
710		27	8	70.4%	300	77	74.3%	27	7	74.1%	296	80	73.0%
711		27	5	81.5%	291	33	88.7%	23	4	82.6%	270	49	81.9%
712	131	27	8	70.4%	297	79	73.4%	26	10	61.5%	288	97	66.3%
713		23	2	91.3%	169	16	90.5%	20	9	55.0%	153	65	57.5%
714	21	26	15	42.3%	181	73	59.7%	24	14	41.7%	167	72	56.9%
715	80	27	2	92.6%	299	60	79.9%	23	13	43.5%	276	138	50.0%
716	29	27	12	55.6%	300	119	60.3%	26	12	53.8%	294	114	61.2%
717	32	26	4	84.6%	285	66	76.8%	25	12	52.0%	266	82	69.2%
718	102	27	13	51.9%	300	149	50.3%	27	15	44.4%	298	106	64.4%
719		27	13	51.9%	300	101	66.3%	26	10	61.5%	285	82	71.2%
757		27	1	96.3%	85	4	95.3%	27	4	85.2%	84	8	90.5%
761	28	27	1	96.3%	296	12	95.9%	27	6	77.8%	293	40	86.3%
765		27	0	100.0%	296	24	91.9%	27	4	85.2%	296	40	86.5%
769	59	27	1	96.3%	296	26	91.2%	27	7	74.1%	290	56	80.7%
770		27	0	100.0%	296	21	92.9%	27	12	55.6%	294	86	70.7%
774	80	27	0	100.0%	296	16	94.6%	27	10	63.0%	295	66	77.6%
777		27	3	88.9%	181	12	93.4%	27	7	74.1%	180	41	77.2%
782		27	22	18.5%	181	78	56.9%	27	9	66.7%	176	24	86.4%
785		27	4	85.2%	296	21	92.9%	27	6	77.8%	296	52	82.4%
786	74	27	1	96.3%	85	17	80.0%	25	16	36.0%	82	43	47.6%
790	98	27	0	100.0%	296	26	91.2%	27	11	59.3%	293	43	85.3%
794	30	27	2	92.6%	296	33	88.9%	26	8	69.2%	292	63	78.4%
821	12	27	0	100.0%	294	6	98.0%	27	15	44.4%	294	118	59.9%
822		27	1	96.3%	296	15	94.9%	27	20	25.9%	294	138	53.1%
1059	54	2	1	50.0%	4	1	75.0%	2	1	50.0%	4	1	75.0%
1333	93	27	4	85.2%	296	32	89.2%	27	9	66.7%	293	97	66.9%
1340	72	27	0	100.0%	295	5	98.3%	27	6	77.8%	295	48	83.7%
1689		17	0	100.0%	91	5	94.5%	18	3	83.3%	91	11	87.9%
2102		18	0	100.0%	64	12	81.3%	18	1	94.4%	63	5	92.1%
2103		18	2	88.9%	128	12	90.6%	18	0	100.0%	127	9	92.9%
2104		18	1	94.4%	154	10	93.5%	18	2	88.9%	152	12	92.1%

Amtrak On Time Performance

Trains Arriving Through: 7/27/2026

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2107		18	4	77.8%	185	34	81.6%	18	0	100.0%	182	20	89.0%
2108	20	18	0	100.0%	185	25	86.5%	18	3	83.3%	179	20	88.8%
2109		18	1	94.4%	78	10	87.2%	18	0	100.0%	77	4	94.8%
2112		18	2	88.9%	25	4	84.0%	17	2	88.2%	23	2	91.3%
2113		18	3	83.3%	64	6	90.6%	18	1	94.4%	64	8	87.5%
2115	55	18	5	72.2%	64	10	84.4%	18	7	61.1%	63	11	82.5%
2116		18	1	94.4%	25	1	96.0%	18	4	77.8%	25	6	76.0%
2118		18	2	88.9%	25	2	92.0%	18	7	61.1%	25	9	64.0%
2119		18	1	94.4%	25	3	88.0%	18	8	55.6%	25	9	64.0%
2120	53	18	6	66.7%	25	9	64.0%	17	9	47.1%	24	12	50.0%
2123		18	2	88.9%	63	8	87.3%	17	2	88.2%	62	15	75.8%
2124		18	9	50.0%	157	32	79.6%	18	9	50.0%	155	22	85.8%
2127		18	6	66.7%	25	7	72.0%	18	6	66.7%	24	6	75.0%
2128		18	3	83.3%	25	3	88.0%	18	2	88.9%	25	2	92.0%
2131		18	5	72.2%	25	5	80.0%	18	2	88.9%	25	2	92.0%
2150	61	18	0	100.0%	178	22	87.6%	18	5	72.2%	175	72	58.9%
2151		18	0	100.0%	127	6	95.3%	18	7	61.1%	125	36	71.2%
2152		15	3	80.0%	83	6	92.8%	15	4	73.3%	82	30	63.4%
2154	21	14	2	85.7%	86	22	74.4%	13	4	69.2%	82	40	51.2%
2155		18	2	88.9%	187	16	91.4%	18	6	66.7%	183	96	47.5%
2158	44	18	2	88.9%	25	4	84.0%	18	11	38.9%	25	11	56.0%
2159	39	18	2	88.9%	180	13	92.8%	18	11	38.9%	178	59	66.9%
2160		18	1	94.4%	25	1	96.0%	17	11	35.3%	24	15	37.5%
2162	72	18	4	77.8%	186	17	90.9%	18	7	61.1%	180	84	53.3%
2165		15	2	86.7%	22	2	90.9%	15	8	46.7%	22	10	54.5%
2167		15	2	86.7%	174	20	88.5%	15	1	93.3%	174	37	78.7%
2171	33	18	1	94.4%	114	9	92.1%	18	5	72.2%	111	23	79.3%
2190		15	3	80.0%	183	27	85.2%	15	1	93.3%	181	23	87.3%
2193		13	1	92.3%	178	24	86.5%	13	2	84.6%	176	47	73.3%
2264	51	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/27/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2108	NYP	20	ENG	18	ENG	18	NWK-NYP	AM	Unrecoverable penalty (PCS), 2121 NG NP, MULTIPLE FAULTS ON PC2121	
2115	WAS	55	ENG	45	ENG	45	NYP-NYP	AM	PTC - On Board Cab Signal or PTC Failure, 2136 NG NP, LATE F/SSYD NECESSARY TO LOOP EQUIPMENT A/C DNL ON PC2144	
2120	NYP	53	ITI	29	ITI	29	WAS-WAS	AM	Service, turn, or wye train, 2159, LATE TURN OFF INBOUND AM2159	
2150	BOS	61	CTI	21	CAR	21	STM-STM	MN	Heat / AC 3473, 3719, 3718, HVAC Temps in each car reading 72-75 degrees with no working blowers. CNOC Mechanical Desk & RTC District Q notified. Train was de-prepared per mechanical department to reset HVAC Systems & brake test performed. HVAC in affected cars now working normally.	
2154	BOS	21	CTI	22	DSR	12	XSH-STM	MN	Per bulletin Milepost, 24.1, 24.3, 30, 4, Milepost, 32.3, 33.6, 30, 4	
2158	BOS	44	POL	34	POL	29	WIL-WIL	AM	Fire department hold, held for fire ahead at Folcroft	
2159	WAS	39	POL	32	POL	32	PHL-PHL	AM	Fire department hold, held for fire ahead at Folcroft	
2162	BOS	72	ENG	44	ENG	44	WAS-WAS	AM	Other electrical failure, 2144 NG NP, NO OPERATING FORWARD FACING CAMERA ON POWER CAR 2144. TRAIN HAD TO WYE IN NYP AND WHEN IT ARRIVED IN WAS.	
2171	WAS	33	ENG	22	ENG	14	NYP-NYP	AM	Other electrical failure, 2145 NG NP, HELD IN STATION A/C MECHANICAL ISSUES, TO CLEAR FAULT	
2264	BOS	51	CAR	24	CAR	24	PHL-PHL	AM	Door, MULTIPLE CARS, MET WITH MECH A/C CARS 3,4,5 ALL WITH DOOR ISSUES; CUT DOORS OUT	
86	BOS	23	WTR	33	WTR	13	ASD-FBG	CS	Flash flood warning All until the 28.0, Milepost, 5.0, 28.0	
94	BOS	34	FTI	20	FTI	18	RVR-ASD	CS	Meet M419, Control Point, Elmont	
128	NYP	55	DCS	55	DCS	55	NFK-X3V	NS	Issue with automatic road crossing protection Milepost, 3.6, 3.6	
171	RNK	40	POL	43	POL	30	PHL-PHL	AM	Fire department hold, held for fire ahead at Folcroft	
182	NYP	36	DDA	33	DDA	33	BAL-XPV	AM	HBD - no exceptions, Control Point, MP 67.4, Stopped at Grace No.2 trk	

Amtrak Endpoint OTP Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
197	WAS	17	CTI	18	CTI	18	BAL-XNY	AM	Follow, MARC, 455, Control Point, .
474	SPG	21	SVS	12	SVS	12	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, late release from yard NHV
478	SPG	47	ITI	38	ITI	38	NHV-NHV	AM	Service, turn, or wye train, 479, delayed to to short turn of AM479
494	GFD	83	SVS	69	SVS	69	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, late from yard, ITEMS issues NHV
53	SFA	154	FTI	233	FTI	120	XSA-XJG	CS	Freight Train Separation M69126, Control Point, McIntosh
637	PHL	11	CTI	9	CTI	9	NWK-MET	AM	Follow, NJT, NJ7885, Other, XIS-MET
648	NYP	13	MTI	16	MTI	16	NWK-NYP	AM	Disabled train ahead, Other, XBH, HELD A/C AM2108 DISABLED AHD IN SOUTH TUBE
656	NYP	12	DCS	15	DCS	15	TRE-TRE	AM	T.O.L, Other, HAM INT LIMIT, HELD A/C TOL AHD AT HAM INT LIMIT 23 SW
682	BON	13	DCS	8	DCS	8	WEM-DOV	CS	Issue with automatic road crossing protection Other, elm st 49.2
684	BON	13	DCS	9	DCS	7	WOB-BON	MT	Cab signals dropped at 10.7to approach and restocking at mantvale yard Control Point, western route
63	TWO	93	DMW	55	DMW	55	XSV-ROC	CS	Unable to contact dispatcher / MW foreman Control Point, 343
64	NYP	19	RTE	25	CTI	22	POU-CRT	MN	Follow mnrr, local, Control Point, 72
240	NYP	24	DMW	18	DMW	15	POU-CRT	MN	Held for or routed around MW work or equipment Control Point, 46
284	NYP	21	PTI	12	PTI	12	ALB-HUD	AM	Meet 233, Control Point, 124
290	NYP	43	RTE	54	RTE	49	POU-CRT	MN	Dispatcher hold Control Point, 46
291	BTN	47	PTI	39	PTI	24	XSY-SAR	DH	Meet 68, Control Point, 480
448	BOS	42	FTI	64	FTI	59	SPG-WOR	CS	Meet I013, Control Point, 48
71	CLT	20	WTR	12	WTR	6	CYN-DNC	NS	Flash flood warning Milepost, 66.0, 60.9
73	CLT	12	TCC	7	HLD	3	CYN-CYN	NS	Passenger and/or baggage
98	NYP	34	WTR	75	FTI	25	RMT-PTB	CS	Meet G627, Other, Bullock
56	SAB	45	DSR	32	POL	26	MDN-HFD	AM	Fire department hold, AM56 held at BER for fire department activity north of Willow interlocking

Amtrak Endpoint OTP Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
41	MIA	205	FTI	162	FTI	129	SAV-XJG	CS	Follow Followed 31 thru the Bottle neck of trains caused by the M-691-26 drawbar debacle., I-031-26, Milepost, 510.0, 550.5
23	NOL	53	TRS	34	TRS	34	BAS-XNO	CS	Vehicle strike Struck an 18 wheeler at Louisa street, Other, louisa street crossing
25	NOL	21	DSR	24	PTI	17	BAS-XNO	CS	Meet Amtrak 26, Siding, Nicholson
5	EMY	69	WTR	92	PTI	25	HAS-HLD	BN	Meet amtk 6, Siding, axtel
6	DEN	79	WTR	117	WTR	49	XMS-WNN	UP	Heat order Milepost, 318.6, 421.26
529	SJC	16	PTI	23	PTI	13	OKJ-OAC	UP	Meet amt 528, Control Point, e oakland
537	OKJ	22	TEN	24	TEN	24	SAC-DAV	UP	Loading problem C2104
539	SJC	11	PTI	7	PTI	7	GAC-SCC	UP	Shuffle at CP Expressway AMT 538, Control Point, Expressway
543	SJC	54	PTI	34	PTI	16	FMT-GAC	UP	Meet 544, Siding, albrea
544	SAC	24	MBO	31	MBO	31	MTZ-SUI	UP	For maritime traffic Control Point, Vista
503	EUG	71	CCR	60	CCR	31	TUK-XA4	BN	Y train due to failure of speedometers 90252
516	VAC	54	FTI	58	FTI	49	XF2-X1J	BN	Meet KCS 4850, Control Point, Piper
517	PDX	77	FTI	43	FTI	43	X8B-BEL	BN	Meet Control Point, Ferndale, BNSF 7863
518	VAC	23	DSR	26	MBO	22	XF2-X1J	BN	For maritime traffic Bridge, Fraser River Br
58	CHI	45	DSR	70	SYS	16	MKS-MEM	CC	PTC-caused slow-down or penalty stop CN engineer pilot to cover Memphis engineer job
1059	NOL	54	DCS	76	DCS	46	MKS-GWD	CC	Restrictive signal(s) from known wayside signal failure Track circuit between South Swan Lake and North Money; flagged by stop signal; first clear at 110.1; fifteen miles at restricted speed, Stop, Control Point, South Swan Lake
7	SPK	374	WTR	177	WTR	112	WTN-WPT	BN	Heat order Milepost, 121, 227
8	CHI	342	FTI	183	ITI	120	SEA-SEA	BN	Service, turn, or wye train 7
821	FTW	12	DSR	38	DSR	27	GLE-FTW	BN	Per bulletin Milepost, 408.5, 408.1, 60, m, Milepost, 407.4, 406.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 396.3, 396.2, 30, m, Milepost, 394.1, 393.5, 60, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 385.5, 385.3, 30, m, Milepost, 38

Amtrak Endpoint OTP Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
332	CHI	29	ENG	24	ENG	16	MKE-MKE	CP	PTC- IETMS recycle breaker to clear fault Switched sets in Milwaukee to find that #50 had quit running overnight. Instructed by management to drag it downtown. Also, PTC was down in engine 514, instructed by CNOC to cycle the breaker., 514, 50
335	MKE	12	CTI	12	CTI	9	XWA-GLN	ME	Cross Traffic 35 min late Metra 627 crossing at Mayfair, Metra, 627, Control Point, Mayfair
338	CHI	20	CTI	8	CTI	7	GLN-XWA	ME	Cross Traffic METRA, Control Point, Mayfair, Control Point, A5, Control Point, A3
339	MKE	105	WTR	102	WTR	102	GLN-XRO	ME	Trees down Trees down from storm., Milepost, 28.5, 32.3
341	MKE	65	ITI	48	ITI	48	CHI-CHI	AM	Service, turn, or wye train 1340
342	CHI	91	ITI	70	ITI	70	MKE-MKE	CP	Service, turn, or wye train 339
352	PNT	187	WTR	155	WTR	76	XPI-XMC	AM	Trees down Milepost, 239, 238
353	CHI	72	WTR	97	WTR	90	HMI-XTF	NS	High winds Other, 509
354	PNT	19	DSR	21	DSR	11	TRM-PNT	CC	Per bulletin Milepost, 17, 17.4, 30, MAIN ONE, Milepost, 17.9, 18, 30, MAIN ONE, Milepost, 18.4, 19, 30, MAIN ONE, Milepost, 20, 21.2, 30, MAIN ONE
355	CHI	51	PTI	41	PTI	20	XA5-XB0	MI	Slow down due to late AMT 352. AMT 352 crew takes this train west out of BTL. AMT 352, Milepost w/Letters, XA5, XB0
364	PTH	101	WTR	73	WTR	73	XPI-XMC	AM	Trees down Control Point, 238
365	CHI	29	FTI	35	FTI	35	LPE-FLN	CC	Meet CN 148, Siding, Lapeer
370	GRR	Trn Cancelled							
562	SAN	32	DCS	26	DCS	26	SNC-X98	SC	CTC system failure Control Point, pier
564	SAN	32	PTI	15	SYS	11	SNP-SNP	SC	Copy authority / restriction Control Point, pier
566	SAN	44	SVS	27	SVS	27	LAX-LAX	SC	LATE RELEASE FROM MECHANICAL Other, 8th ST YARD
572	SAN	30	CTI	22	CTI	10	SNA-IRV	SC	Follow Follow 612, Metrolink, 612, Control Point, Tinkham
580	SAN	Trn Cancelled							
584	SAN	54	DCS	26	DCS	14	SNP-X98	SC	CTC system failure Control Point, Pier
588	SAN	52	DCS	29	DCS	15	SNP-SNP	SC	Dispatcher hold Control Point, Pier

Amtrak Endpoint OTP Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
593	LAX	41	PTI	30	PTI	30	OSD-X98	SN	Meet a588, Control Point, songs
595	LAX	No OS Rpt	PTI	74	PTI	66	OSD-X98	SN	Meet 790, Control Point, songs
761	GTA	28	CAR	27	CAR	27	OXN-OXN	UP	Air / Brake / Wheel 6300, Requesting direction from management regarding possible flat spot and/or shelling.
769	GTA	59	DCS	33	DCS	19	OSD-X98	SC	CTC system failure Control Point, Songs
774	SAN	80	ENG	63	ENG	63	LAX-LAX	SC	HVAC inoperative CDTX 2121, equipment swap with 573 C2121
786	SAN	74	PTI	44	PTI	22	GUA-LPS	UP	Meet 14, Siding, Tangier
790	SAN	98	PTI	67	PTI	33	SNC-SNP	SC	Meet 593, Control Point, serra
794	SAN	30	DCS	28	PTI	18	X3G-GTA	UP	Meet AMTK 777, Siding, Gaviota
703	SAC	No OS Rpt	TEN	199	TEN	199	COC-HNF	BN	Loading problem Lost load leaving Corcoran, tried to reset gen field breaker as well as engine. It was unsuccessful. Had to couple into 704 equipment, C2009
704	BFD	Trn Cancelled	PTI	25	PTI	25	TRK-MCD	BN	Meet amtrak 719, Control Point, fluhr
712	BFD	131	TEN	123	TEN	96	TRK-TRK	BN	Loading problem C2009
714	BFD	21	PTI	27	PTI	8	TRK-MCD	BN	Follow Followed train from Turlock/Denair Station to Merced Station., AMTK 712, Control Point, East Denair
715	OKJ	80	POL	38	POL	38	MCD-TRK	BN	Fire department hold Bridge fire at 1069.3
716	BFD	29	DSR	25	PTI	11	COC-WAC	BN	Meet amt 703, Siding, angiola
717	OKJ	32	PTI	27	FTI	20	MDR-MCD	BN	Meet Control Point, plandada, bnsf, bnsf
718	BFD	102	POL	99	POL	99	ACA-SKN	BN	Train was brought to a stop due to police searching for a man who was wandering the tracks
3	LAX	208	FTI	232	RTE	89	LAP-LAP	BN	Dispatcher hold extensive maintenance and freight congestion, Control Point, Laplata
4	CHI	218	FTI	228	FTI	105	KNG-FLG	BN	Follow bnsf unknown, Milepost, 488, 442.3
1	LAX	805	FTI	445	FTI	379	XAS-XHT	UP	Meet Stopped for broke down freight train, UP 8824, Siding, Lacoste
21	SAS	71	SYS	170	SYS	168	MHL-MHL	UP	Crew rest
22	CHI	409	CON	397	CON	397	SAS-SAS	UP	Hold for connecting train Waiting for the 2 422 transfer cars off train 2, 2
305	STL	26	FTI	23	FTI	16	CRV-ALN	UP	Meet Freight, Milepost, 243, 243

Amtrak Endpoint OTP Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
306	CHI	29	FTI	27	FTI	25	SMT-XTF	CC	Cross Traffic NA, Other, CORWITH
380	CHI	36	DSR	22	DSR	18	MDT-PLO	BN	Speed Milepost, 72.5, 59.6, 30, 1
381	QCY	21	DSR	21	DSR	17	PLO-MDT	BN	Per bulletin Milepost, 59.6, 72.6, 30, MT1
382	CHI	27	FTI	26	FTI	14	MAC-GBB	BN	Follow bnsf 6234, Control Point, bushnell-abingdon
390	CHI	25	FTI	27	FTI	15	HMW-XCS	CC	Meet I583, Control Point, kelley
393	CDL	21	DSR	25	CTI	16	XCS-HMW	CC	Meet South Shore, Control Point, Kensington
1333	MSP	93	ENG	85	ENG	85	CHI-CHI	AM	Failure of diesel engine Engine #50 quit running around 3 in the morning, dragged it to Chicago on 332. As a result, MR was not staying up. Mechanical elected to repair rather than replace or cap it., 50
1340	CHI	72	DBS	39	DBS	39	SVT-SVT	CP	Debris blocking track (no debris strike) Disp hold for down trees near lake forest area, Other, lake forest area

Amtrak Initial Terminal Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/27/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	1	07/27	235	235	Late departure due to late arriving train 2 2
BON	683	07/27	1		
HAR	626	07/27	2	2	Other electrical failure, 9638 CB CC, door cut out
HAR	644	07/27	2	2	Door, ENTIRE CONSIST
HAR	650	07/27	1	1	Door, ENTIRE CONSIST
HAR	656	07/27	1	1	Passenger and/or baggage
NHV	470	07/27	9	4	Service, turn, or wye train, 471
NHV	470	07/27	9	5	Service, turn, or wye train, 471
NHV	474	07/27	12	12	Planned set out / pick out of locomotives, cars or section of train, late release from yard NHV
NHV	478	07/27	38	38	Service, turn, or wye train, 479, delayed to to short turn of AM479
NHV	494	07/27	69	69	Planned set out / pick out of locomotives, cars or section of train, late from yard, ITEMS issues NHV
NYP	63	07/27	3	3	Cross Traffic, NJT, NJX377, Other, NYP
NYP	97	07/27	44	44	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR AM98 TO COMPLETE CONSIST AND SERVICE CARS
NYP	111	07/27	7	7	Waiting for MW clearance, Other, NYP-NYP, Departed late account bridge plate work in PSNY
NYP	183	07/27	6	6	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	197	07/27	2	2	Passenger and/or baggage, BOARDING
NYP	281	07/27	2	2	Passenger and/or baggage, TRAVEL
NYP	291	07/27	19	19	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	2107	07/27	2	2	Passenger and/or baggage, LOADING
NYP	2115	07/27	45	45	PTC - On Board Cab Signal or PTC Failure, 2136 NG NP, LATE F/SSYD NECESSARY TO LOOP EQUIPMENT A/C DNL ON PC2144
PHL	601	07/27	1	1	Passenger and/or baggage
PHL	605	07/27	2	2	PTC - Stop Bypass Permission Required, Control Point, PHL
SFA	52	07/27	75	75	Service, turn, or wye train 53
WAS	2120	07/27	29	29	Service, turn, or wye train, 2159, LATE TURN OFF INBOUND AM2159
WAS	2162	07/27	44	44	Other electrical failure, 2144 NG NP, NO OPERATING FORWARD FACING CAMERA ON POWER CAR 2144. TRAIN HAD TO WYE IN NYP AND WHEN IT ARRIVED IN WAS.

Amtrak Initial Terminal Details

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/27/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	7	07/27	30	30	Set out defective car 38004, Stock
CHI	341	07/27	48	48	Service, turn, or wye train 1340
CHI	1333	07/27	85	85	Failure of diesel engine Engine #50 quit running around 3 in the morning, dragged it to Chicago on 332. As a result, MR was not staying up. Mechanical elected to repair rather than replace or cap it., 50
MKE	332	07/27	16	16	PTC- IETMS recycle breaker to clear fault Switched sets in Milwaukee to find that #50 had quit running overnight. Instructed by management to drag it downtown. Also, PTC was down in engine 514, instructed by CNOC to cycle the breaker., 514, 50
MKE	342	07/27	70	70	Service, turn, or wye train 339
STL	302	07/27	2	2	ENGINE SCREEN SHOWING TRAIN CAR DOOR OPEN HOWEVER ALL DOORS CLOSED AND ALL STAIRS STOWED AFTER INSPECTED ID4626
BFD	703	07/27	72	72	Service, turn, or wye train 712, Waiting for 712 equipment to arrive due to earlier disruption
BFD	719	07/27	9	9	Hold for thruway bus
GTA	782	07/27	44	44	Air / Brake / Wheel C6451, Sticking brake pad. Cut out truck.
LAX	4	07/27	14	14	Service, turn, or wye train 782, Hold for 4 transfer pax's
LAX	14	07/27	6	6	The train is arriving late from the yard because of a door on 338 being stuck. 338
LAX	566	07/27	27	27	LATE RELEASE FROM MECHANICAL Other, 8th ST YARD
LAX	580	07/27	(Trn Cxld)		Car Issue
LAX	584	07/27	5	5	Hold for connecting train 782
OKJ	522	07/27	1		
OKJ	532	07/27	6	6	Waiting for signal-
PDX	28	07/27	(No OS)		
PDX	502	07/27	1		
SAC	543	07/27	9	9	No reverser. Retrieved one from cab car and it would not move throttle. Had to wait for RFE Barton to assist JPBX922
SAN	567	07/27	1	1	Meet NCTD, Coaster 622, Control Point, Ash
SAN	595	07/27	24	24	Service, turn, or wye train 584
SEA	8	07/27	(No OS)		
SPK	8	07/26	90	87	Hold for bus with passengers from train Held for last bus to arrive with passengers

Eastern Region

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	98.5	94.8	342	1
CDOT	95.0	90.0	84.5	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	97.9	92.4	88.6	343	7
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 478(27) - New Haven, CT - Initial Terminal Delay

28JUL26: Train 478(27) was delayed at its initial terminal at New Haven Station due to being short turned off the 479(27) equipment.

Train	Delay	Comment
478 (27)	38"	

Train 494(27) - New Haven, CT - Hold for Connection

27JUL26: Train 494(27) was delayed at its initial terminal at New Haven Station due to being held for connections on late arriving Train 94(27) and being short turned off Train 417(27).

Train	Delay	Comment
494 (27)	1'09"	

Train 98(27) - North of Jesup, GA - Freight Train Interference

27JUL26: Train 98(27) was delayed on the CSX Nahunta Subdivision at MP 533.6 due to meeting CSX Trains M693-26 and I197.27.

Train	Delay	Comment
98 (27)	37"	

Train 2120(27) Washington, DC - Servicing

27JUL26: Next Gen Train 2120(27) set 13 PC/2140, PC/2139 was delayed departing due to late arrival of 2159(27) that arrived 39 minutes late. They were further delayed due to having door issues.

Train	Delay	Comment
2120 (27)	29"	

Train 52(27) Sanford, FL - Servicing

27JUL26: Train 52(27) 26-FCI-00625 00000008486 UNCLASSIFIED 8/7/2026 delayed in departing due to turning off late 53(26) that arrived at 1133A-ET 2 hours and 34 minutes late.

Train	Delay	Comment
52(27)	1'15"	

Train 63(27) West of Syracuse, NY - M of W Work

27JUL26: Train 63(27) E/104 and 5 cars on the CSX Rochester subdivision was delayed due to being unable to contact the dispatcher and M/W working ahead at MP 343.

Train	Delay	Comment
63(27)	55"	

Train 68(27) South of St-Lambert, QC - Weather

27JUL26: Train 68(27) was delayed on the CN Rouses Point subdivision due to heat orders from MP 2 to MP 42.

Train	Delay	Comment
68(27)	43"	
69(27)	38"	

Philadelphia to Washington main line - Folcroft, PA - Fire/Police Related

27JUL26: As of 225P-ET, CETC reported that there was a fire on the Philadelphia to Washington main line at Folcroft station track 4. There was a Police hold on all tracks from Phil to Baldwin. The Amtrak Police were notified and enroute. Assistant Superintendent of Operation and Road Foreman were enroute. As of 247P-ET the hold was release on all tracks from Phil-Baldwin and the Fire was out.

Train	Delay	Comment
171(27)	30"	PHL
2159(27)	32"	PHL
2158(27)	34"	WIL
184(27)	04"	

Train 97(27) New York, NY - Servicing

27JUL26: Train 97(27) with E/616 and 12 cars was delayed departing New York due to replacing shopped sleeper and replacing with sleeper off inbound 98(26).

Train	Delay	Comment
97(27)	44"	

Train 182(27) South of Aberdeen, MD - Defect Detector Actuation

27JUL26: Train 182(27) with E/603, E/628 and 9 cars was delayed on the Philadelphia to Washington main line MP 61.7 due to actuating a hot box detector at MP 67.4. The crew inspected the equipment and took no exceptions.

Train	Delay	Comment
182(27)	33"	

Train 2115(27) New York, NY - Engine Failure

27JUL26: Next Gen Train 2115(27) delayed departing New York due to PC/2144 being a Do not lead for the forward camera making it necessary to loop the equipment upon arrival off 2104(27).

This also caused train 2162(27) to be delayed due to the equipment having to wye'd upon arrival in Washington.

Train	Delay	Comment
2115(27)	45"	
2162(27)	44"	

CSX Heat Orders - Weather

27JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions North End, Peninsula, Richmond Terminal, Auburndale, Jacksonville Terminal, Nahunta, Sanford and Savannah.

Train	Delay	Comment
98(27)	37"	
53(27)	08"	
40(27)	38"	
52(27)	08"	
79(27)	22"	
186(27)	22"	
95(27)	07"	
89(27)	20"	
138(27)	04"	
90(27)	19"	
80(27)	24"	
41(26)	16"	
97(26)	24"	
40(26)	09"	

Train 97(26) South of Savannah, GA - Freight Train Interference

27JUL26: Train 97(26) with E/88, E/63 and 12 cars was delayed on the CSX Nahunta subdivision due to following CSX 493 from MP 518 to MP 548.

Train	Delay	Comment
97(26)	35"	

Trains 53(26) and 41(25) - South of Savannah, GA - Freight Train Interference

27JUL26: CSX Train M691-26 went into emergency at MP 522.0 on the CSX Nahunta Subdivision after breaking a drawbar. This initially delayed Train 41(25) at Savannah Station/MP 491 and Train 53(26) at MP 498.8 just north of Savannah Station.

The CSX Passenger Operations Desk advised the disabled train would make a standing cut and shove clear of the main while another crew coupled to the section left on the main - and cleared it.

Both Amtrak trains were advanced south to CP Ogeechee/MP 505.7 to hold for open route. Once the route was open they were able to proceed south but lost some more time due to the freight congestion in the area.

Train	Delay	Comment
53(26)	2'58"	
41(25)	2'23"	

Train 450(26), 409(26) and 416(26) - Springfield, MA and New Haven, CT - Cab Car Failure

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

26JUL26: Due to cab cars 9647 and 9643 being shopped, Hartford Line trains 450(26), 409(26) and 416(26) were cancelled in their entirety. Three busses were sourced for each route.

26JUL26: 11:41pm Ongoing shop count issues with the cab cars in the shuttle fleet necessitated the cancellation of Train 495(27). No alternate transportation was sourced for this cancellation. Passengers instead, were moved to Train 125(27).

WBS#: B.TR.100151.0834

Train	Delay	Comment
450(26)	Cancelled	
409(26)	Cancelled	
416(26)	CANCELLED	
495(27)	Cancelled	No Alt - PAX to Train 125(27)

Maintenance of Way Highlights

16-FOI-006257

80090008486

"UNCLASSIFIED"

9/7/2026

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00625 00000008486 "UNCLASSIFIED" 8/7/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	
240(23)	31"	
233(23)	30"	
235(23)	30"	
284(23)	27"	
290(23)	52"	
291(23)	47"	
281(23)	31"	
284(26)	25"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00625a 00000008488 UNCLASSIFIED 187/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No Data

Eastern Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Train2160(27) Passenger Removal at Philadelphia, Pennsylvania-Intoxication

27JUL26, Passenger, on PNR 9B952D, traveling from Philadelphia PA, to Boston, MA reportedly was intoxicated and disturbing passengers, passengers were removed at Philadelphia. Amtrak Police notified.

Delay: 2160(27) NONE

Western Region

Operating Highlights

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train 59(27) North of Centralia, IL - Freight Train Interference

27JUL26: Train 59(27), with 176 customers onboard, was delayed at Tonti siding/MP238.0, 14.3 miles north of Centralia, IL/MP252.3, on the CN Champaign subdivision meeting CN freight CN/3150. Once the route was clear, train 59(27) continued south.

Train	Delay	Comment
59(27)	46"	

Train 544(27) East of Martinez, CA - Drawbridge Opening

27JUL26: Train 544(27), with 70 customers onboard, held at Vista/MP32.8, 1.3 miles east of Martinez, CA/MP31.5, on the UP Martinez subdivision for the Suisun Bay Bridge to close. Once the route was open, train 544(27) continued east. Train 549(27) was also delayed, holding at Benicia/MP34.5 for open track.

Train	Delay	Comment
544(27)	31"	
549(27)	08"	

Train 6(27) West of Elko, NV - Heat Orders

27JUL26: Train 6(27), with 82 customers onboard, was delayed between mile post 535.0 and mile post 646.0, beginning 22 miles west of Elko, NV/MP557.0, on the UP Elko subdivision following heat orders. Once clear of the affected area, train 6(27) continued east.

Train	Delay	Comment
6(27)	46"	

Train 354(27) East of Kalamazoo, MI - Passenger Train Interference

27JUL26: Train 354(27), with 221 customers onboard, was delayed at CP140/MP139.9, 3.5 miles east of Kalamazoo, MI/MP143.4, on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(27). Once the route was clear, train 354(27) continued east.

Train	Delay	Comment
354(27)	45"	

Train 8/28(26) East of Malta, MT - Passenger Train Interference

27JUL26: Train 8/28(26), carrying 221 customers onboard, was delayed east of Malta, MT, while holding at Saco Siding (MP 318.1) on the BNSF Milk River Subdivision to meet Amtrak Train 7/27(26) and freight traffic in the area.

Train	Delay	Comment
8/28(26)	1'09"	

Train 1(25)/421(24) West of Palm Springs, CA - Freight Train Interference

27JUL26: Train 1(25)/421(24) was delayed west of Palm Springs, CA, on the Union Pacific Yuma Subdivision due to freight train interference. The train was required to follow UP 5275 from approximately MP 588.3 to MP 561.8, resulting in reduced speeds through the territory.

Train	Delay	Comment
1(25)/421(24)	30"	

Train 59(27) South of Chicago, IL - Routing

27JUL26: Train 59(27), with 168 customers onboard, was delayed at Kelley/MP2.19, 2.19 miles south of Chicago Union Station/MP0.0, on the CN Chicago subdivision hand-lining a switch. Once clear of the affected area, train 59(27) continued south.

Train	Delay	Comment
59(27)	35"	

Train 3(26) East of Albuquerque, NM - Commuter Train Interference

27JUL26: Train 3(26), carrying 148 customers onboard, was delayed east of Albuquerque, NM, while meeting New Mexico Rail Runner Express (NMRX) traffic near East Domingo (MP 865) on the NMRX Glorieta Subdivision. The train was required to hold for commuter train movements through the territory before continuing westward.

Train	Delay	Comment
3(26)	44"	

Train 715(27) East of Turlock-Denair, CA - Fire on Tracks

26JUL26: Train 715(27), carrying 145 customers onboard, was delayed east of Turlock-Denair, CA, at MP 1069.6 on the BNSF Stockton Subdivision due to a fire near the tracks ahead. The train was required to hold while the local fire department responded and addressed the incident. Once the fire was controlled and the track was cleared for safe operation, Train 715(27) resumed its trip.

Train	Delay	Comment
715(27)	38"	
714(27)	07"	
712(27)	12"	

Train 712(27) Turlock-Denair, CA - Third Party Contractor Engine Failure

27JUL26: Train 712(27) 26-FOJ-00625 00000008486 cab UNCLASSIFIED 8/7/2026, with 11 empty cars, locomotive E/C2009, and 233 customers onboard, was delayed at Turlock-Denair Station (MP 1079.6) on the BNSF Stockton Subdivision due to a loss of traction power on the locomotive. The crew worked with TASI Mechanical to troubleshoot the issue and ultimately determined the cause to be a loose generator field circuit breaker. After correcting the condition, tractive effort was restored and Train 712(27) continued toward Bakersfield, CA under its own power.

As a result of the late arrival of Train 712(27), Train 703(27) experienced a delayed departure from Bakersfield, CA. While operating west of Corcoran, CA, Train 703(27) encountered the same locomotive issue with E/C2009 and stopped at MP 955.1 on the BNSF Bakersfield Subdivision for troubleshooting. Although the train was initially able to resume movement, the locomotive failed again approximately 10 miles later, requiring additional operational adjustments.

To recover service, Train 704(27), which was holding at Hanford Station, was terminated, with customers accommodated on Train 718(27) for continued travel to Bakersfield. The Train 704(27) equipment was then used to rescue Train 703(27), and the combined consist operated in double-draft configuration to Sacramento, CA.

As a result of the equipment failure and equipment reassignment, Train 713(28) was canceled, with customers directed to next available service.

Train	Delay	Comment
712(27)	2'13"	
703(27)	1'12"	late turn 712
703(27)	3'19"	
704(27)	TERM HNF	
713(28)	Canceled	

Train 3(26) West of Las Vegas, NM - Passenger Train Interference

27JUL26: Train 3(26), carrying 151 customers onboard, was delayed west of Las Vegas, NM, while holding at Blanchard Siding (MP 794.0) on the BNSF Glorieta Subdivision to meet Amtrak Train 4(26).

Train	Delay	Comment
3(26)	49"	

Train 786(27) North of Lompoc-Surf, CA - Passenger Train Interference

27JUL26: Train 786(27), carrying 98 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.6) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(27) and 14(27).

Train	Delay	Comment
786(27)	42"	

Train 352(27) East of Chicago, IL - Freight Train Interference

27JUL26: Train 352(27), with 266 customers onboard, was delayed between 21st St/MP521.1 and the CP509 Bridge/MP509.7, beginning 1.61 miles east of Chicago, IL/MP0.0, on the NS Chicago Terminal subdivision following freight 64. Once the route was clear, train 352(27) continued east.

Train	Delay	Comment
352(27)	31"	

Train 774(27) Los Angeles, CA - Engine Failure

27JUL26: Train 774(27) departed Los Angeles, CA, on the SCRR River Subdivision. The outbound crew reported that air conditioning in coach CDTX 2121 was inoperative upon arrival in Los Angeles. At the time, the ambient temperature was 88 degrees. Mechanical personnel responded to investigate the issue but were unable to restore the air conditioning. Equipment swaps were subsequently made to minimize the delay and allow the train to continue service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
774(27)	1'03"	

Train 4(25) East of Kansas City, MO - Freight Train Interference

27JUL26: Train 4(25) was delayed on the BNSF Marceline subdivision starting 14 miles east of Kansas City due to following unknown freight between Eton/MP 436.6 and Marceline/MP 347.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(25)	44"	

Train 782(27) Goleta, CA - Car Failure

27JUL26: Train 782(27), operating with CC/C6907, five cars, locomotive E/C2122, was delayed departing Goleta, CA due to a brake malfunction on car 6300, where the brakes failed to fully release. The crew coordinated with Mechanical forces to troubleshoot the issue and ultimately cut out the affected truck to allow continued operation. As a result, the train operated at reduced freight speeds between Goleta and Los Angeles, CA.

Due to the resulting service disruption, the following Pacific Surfliner service adjustments were implemented:

-Train 580(27) was canceled, with customers accommodated on an on-time supplemental section of Train 782S using 774's equipment.

-Train 591(27) was canceled, with customers accommodated on Train 593(27).

-Customers on the affected northbound Train 782(27) traveling beyond Los Angeles were accommodated on the next available southbound service as appropriate.

Upon arrival in Los Angeles, the affected 782(27) equipment was routed to the 8th Street Yard for inspection and repair.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
782(27)	44"	GTA ITD
782(27)	1'07"	GTA-LAX
580(27)	Canceled	
591(27)	Canceled	

Train 7/27(27) Chicago, IL - Initial Terminal Delay

27JUL26: Train 7/27(27) with 257 customers was delayed departing Chicago due to late loading of the commissary. Once the commissary was loaded, 7/27(27) departed Chicago at 335PM-CT, 30 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(27)	30"	

Train 7/27(26) Williston, ND to Malta, MT - Freight Train Interference

27JUL26: Train 7/27(26) was delayed while waiting between Williston, ND, and Wolf Point, MT, on the BNSF Glasgow Subdivision due to freight train interference. The train was required to follow BNSF 6720 from approximately MP 121.0 to MP 192.0, with extended holding occurring at Trenton (MP 141.3) and again at Culbertson (MP 173.6) while awaiting available track capacity.

Additional delay was incurred west of Wolf Point, MT, where the train was required to follow BNSF 5326 from approximately MP 228.0 to the Whatley area (MP 272.7) on the BNSF Milk River Subdivision.

Continuing west of Glasgow, MT, Train 7/27(26) encountered further freight congestion and was required to follow a double grain train led by BNSF 5936 through Hinsdale (MP 304.9) on the BNSF Milk River Subdivision.

Train	Delay	Comment
7/27(26)	2'00"	WTN-WPT
7/27(26)	34"	WPT-GGW
7/27(26)	48"	GGW-MAL

Train 8/28(25) West of Red Wing, MN - M of W Work

27JUL26: Train 8/28(25) with 260 customers was delayed 12 miles west of Red Wing on the CPKC River subdivision at East Blackbird/MP 382.8 due to MOW working ahead with a crane broke down.

Train	Delay	Comment
8/28(25)	50"	

Amtrak Chicago District Chicago, IL - Signal

27JUL26: Trains were delayed on the Amtrak Chicago district due to a TOL on main track 4 and 5 at CP Lumber/MP 1.4 with 54 and 58 switch issues. C&S responded and resolved the issue. Due to 54 switch unable to be thrown remotely, train 352(27) shoved back towards Chicago Union Station and was routed around. Train 21(27) was also delayed operating through the area.

Train	Delay	Comment
352(27)	1'07"	
21/421(27)	40"	Additional WTR delays N/JOL
21/421(27)	31"	WTR delays S/CHI

Train 20(27) North of Meridian, MS - Passenger Train Interference

27JUL26: Train 20(27), with 160 customers onboard, was delayed at McClure siding/MP230.0, 65 miles north of Meridian, MS/MP295.0, the NS AGS South subdivision meeting Amtrak train 19(26). Once the route was clear, train 20(27) continued north.

Train	Delay	Comment
20(27)	30"	

Train 19(26) South of Birmingham, AL - Freight Train Interference

27JUL26: Train 19(26) was delayed on the NS AGS South district starting 18 miles south of Birmingham due to following 355-27 between McCalla/MP 161.44 and Tuscaloosa/MP 199.1.

Train	Delay	Comment
19(26)	31"	

Train 353(27) West of Hammond-Whiting, IN - Weather

27JUL26: Train 353(27) with 167 customers onboard was delayed arriving into Hammond, IN on the NS Chicago district two miles west of Hammond-Whiting due to being held at CP 509/MP 509.7 for tornado and high wind warnings.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
353(27)	1'37"	

Train 517(27) North of Bellingham, WA - Freight Train Interference

27JUL26: Train 503(27) with 167 customers onboard was delayed arriving into Bellingham, WA on the BNSF Bellingham subdivision due to meeting freight BNSF 7863.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
517(27)	43"	

Train 503(27) Tukwila, WA - Cab Car Failure

27JUL26: Train 503(27), operating with Cab Car 90252 leading and carrying 88 passengers, departed Tukwila, WA, on the BNSF Seattle Subdivision behind schedule. Upon arrival in Tukwila, all speedometers in Cab Car 90252 failed. After troubleshooting efforts were unsuccessful, a decision was made to wye the equipment so the train could operate with Locomotive WS1408 in the lead. The train proceeded north of Tukwila to Stacy Yard to perform the wye movement. Once the maneuver was completed, the train resumed its southbound journey.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
503(27)	29"	TUK-TUK
503(27)	22"	meet 500(27)
503(27)	31"	WYE
503(27)	9"	Meet 502(27)

Train 5(26) East of Glenwood Springs, CO - Passenger Train Interference

27JUL26: Train 5(26), with 114 customers onboard, was delayed at Range siding/MP156.0, 29 miles east of Glenwood Springs, CO/MP360.1, on the UP Glenwood Springs subdivision meeting Amtrak train 6(26). Once the route was clear, train 5(26) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(26)	33"	

Train 7/27(25) East of Libby, MT - Freight Train Interference

27JUL26: Train 7/2(25) was delayed approximately 54 miles east of Libby, MT, on the BNSF Kootenai River Subdivision due to congestion caused by following BNSF freight trains 7290 and 8372.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(25)	1'12"	

Train 3(26) West of La Junta, CO - Signal Issues

27JUL26: Train 3(26), 26-FOI-00625 00000008486 UNCLASSIFIED, 6/7/2026 delayed while operating on the BNSF Raton Subdivision due to restrictive signal indications of an unknown cause. The train first encountered delays west of La Junta, CO, operating through a series of approach, stop, and restricting signals between approximately MP 612.2 and MP 620.9, requiring reduced-speed operation and compliance with signal restrictions through the territory. Additional delay was incurred west of Raton, NM, where the train again encountered restrictive signal conditions between approximately MP 706.5 and MP 720.6, including restrictive indications near Colmor and Levy.

Train	Delay	Comment
3 (26)	25"	LAJ-TRI
3 (26)	31"	RAT-LSV

Train 1333(27) Chicago, IL - Initial Terminal Delay

27JUL26: Train 1333(27) with E/50, four cars, E/514, and 178 customers was delayed departing Chicago due to E/50 with air issues. Mechanical was on scene working on repairs. Once the issues were resolved, 1333(27) departed Chicago at 1235PM-CT, 1 hour, and 25 minutes late.

Train	Delay	Comment
1333(27)	1'25"	

Train 23(27) East of New Orleans, LA - Trespasser Incident

27JUL26: 953AM-CT, Train 23(27) with E/11, three cars, E/180, and 83 customers struck the rear of a tractor trailer on the CSX NO&M subdivision nine miles east of New Orleans at Louisa Street/MP 801.99 (DOT# 341072U) in the city of New Orleans located in Orleans Parish. There were no reported injuries to the customers or the crew. The truck was coming through the crossing and the crossing gates came down on top of the truck. After the train struck the truck, the truck driver fled the scene. The crew reported ladder damage to E/11 and a dent in the side of C/41871. Head end power and air was maintained during the service disruption. Local authorities and Amtrak Police responded to the scene for an investigation. Once the investigation was complete, train 23(27) continued to New Orleans.

National Response Center Number: 1469062

Train	Delay	Comment
23(27)	34"	

Train 4(26) E/ Flagstaff, AZ - Freight Train Interference

27JUL26: Train 4(26), carrying 250 passengers, was delayed approximately 11.2 miles east of Flagstaff, AZ, on the BNSF Seligman Subdivision. The delay was caused by a disabled freight train, HBARLUB, which blocked the route ahead of Train 4(26). Before the train could be rerouted around the disabled freight and continue eastward, it was required to wait for four westbound freight trains to pass.

Train	Delay	Comment
4 (26)	1'02"	

Train 1059(26) South of Marks, MS - Signal

27JUL26: Train 1059(26) with 46 customers was delayed on the CN Yazoo subdivision starting 27 miles south of Marks due to signal issues between South Swan Lake/MP 94.3 and North Money/MP 112.3.

Train	Delay	Comment
1059(26)	46"	

Train 8/28(26) Spokane, WA - Hold for Connection

27JUL26: Train 8/28(26) experienced a delayed departure from Spokane, WA, on the BNSF Spokane Subdivision. As a result of the late operation, Train 7/27(24) was terminated in Spokane, WA, and alternate transportation was provided for affected passengers. Subsequently, Train 8/28(26) originated in Spokane, WA, with alternate transportation also arranged for passengers.

One of the buses transporting passengers from Seattle to Spokane encountered delays due to road closures. Train 8/28(26) was held in Spokane to accommodate those connecting passengers.

Train	Delay	Comment
8/28(26)	1'27"	

Train 365(27) West of Lapeer, MI - Freight Train Interference

27JUL26: Train 365(27) with 47 customers was delayed on the CN Flint subdivision two miles west of Lapeer at West Lapeer/MP 287.0 due to meeting CN 148.

Train	Delay	Comment
365(27)	35"	

East and West of Chicago, IL - Downed Trees

27JUL26: The Hiawatha, Pere Marquette, Floridian, Lake Shore Limited, and Empire Builder Services reported downed trees between west of Glenview, IL/MP17.32 and west of Porter, IN/MP482.2. Local Maintenance of Way teams were dispatched to their territories to clear the tracks but significant delays were incurred.

Train 370(27) terminated at Porter, IN/MP482.2 due to a four-hour estimate to open track from CSX Railroad. Four buses were secured:

- Bus one operated express to Holland, MI.
- Buses two and three operated express to Grand Rapids, MI.
- Bus four operated St Joseph and Bangor.

WBS#: B.TR.100150.6954

Train	Delay	Comment
370(27)	Terminated XPI	Near Porter, IN
383(27)	19"	LAG
1340(27)	39"	SVT
352(27)	1'16"	XPI
339(27)	1'42"	W/GLN
364(27)	1'13"	XPI
342(27)	1'10"	Late Turn off 339(27)
7/27(27)	2'58"	GLN
341(27)	48"	Late Turn off 1340(27)
41(27)	3'18"	XPI

West of Kirkwood, MO - UP Freight Train Derailment

26JUL26: Due to a UPRR freight derailed west of Kirkwood, MO/MP13.49, with 28 coal cars derailed and 900 feet of track damaged, train 316(26) is terminated at Washington, MO. with alternate buses secured. The equipment operated deadhead with BNSF pilots across a detour between Pacific/MP34.7 and St Louis, MO/MP1.5. Missouri River Runner Service is adjusted at follows:

-Train 311(27) was cancelled with alternate buses sourced. Bus One operated between St Louis, Kirkwood, Lee's Summit, and Kansas City. Bus Two operated between St Louis and Kansas City making all stops.

-Train 318(27) originated at St Louis with alternate buses sourced. Bus One operated express between Kansas City and St Louis. Bus Two operated between Kansas City, Lee's Summit, Kirkwood, and St Louis. Bus Three operated between Kansas City and St Louis making all stops.

-Train 316(27) was cancelled in its entirety with an alternate bus secured. Bus One operated between Kansas City and St Louis making all stops.

-Train 319(27) terminated at St Louis, with alternate buses secured. Bus One operated express between St Louis and Kansas City. Bus Two operated between St Louis, Kirkwood, Lee's Summit, and Kansas City. Bus Three operated between St Louis and Kansas City making all stops.

Train 316(26) was further delayed en route to Washington, MO by UP freight UP/5285 at Dow siding. The freight crew was having trouble repairing a broken knuckle.

27JUL26: UPRR advised the tentative track opening was midday on July 28. As a result, trains 311(28) and 316(28) were cancelled entirely with alternate transportation. Train 318(28) originated at St. Louis with alternate transportation and train 319(28) terminated at St. Louis with alternate transportation.

WBS#: B.TR.100150.6946

Train	Delay	Comment
316(26)	Terminated WAH	
316(27)	Cancelled	w/Alternate Bus
311(27)	Cancelled	w/Alternate Bus
318(27)	Originates at St Louis	w/Alternate Buses
319(27)	Terminates St Louis	w/Alternate Buses
311(28)	Cancelled	w/Alternate
316(28)	Cancelled	w/Alternate
318(28)	Originates STL	w/Alternate
319(28)	Terminates STL	w/Alternate
316(26)	2'47"	FTI E/SED

Train 1(25)/421(24) West of San Antonio, TX - Freight Train Interference

26JUL26: Train 1(25)/421(24) 00000008486 175 "UNCLASSIFIED" 8/7/2026 was delayed on the UPRR Del Rio subdivision 25 miles west of San Antonio at Lacoste/MP 235.9 due to east bound ZLBHO-23 stopped ahead at Dunlay/MP 247.4 with their lead locomotive shut down due to a low oil pressure fault and unable to restart. A rescue locomotive from MEWWC-24 at Noonan/MP 242.8 was dispatched to assist and clear the route. After accessing the main line, the rescue locomotive was bad ordered for crankcase pressure, rendering it unusable. A freight crew moved the bad ordered rescue locomotive back to the Noonan siding and delivered a second rescue locomotive long hood forward to continue the rescue effort. Train 2/422(24) with 209 customers held at Medina/MP 254.9 for an open route. Once the route was cleared, train 1(25)/421(24) continued to Hacienda/MP 307.5 to pickup a relief crew. Train 2/422(24) then followed ZLBHO-23 towards San Antonio and to Macdona/MP 225.4. Train 22(26) was delayed departing San Antonio due to holding for the late 422(24) section. Train 22(26)/422(24) departed San Antonio at 125PM-CT, 6 hours, and 37 minutes late.

27JUL26: Train 22(26)/422(24) arrived Marshall at 219AM-CT, 7 hours, and 15 minutes late. As a result, train 21/421(26) was delayed at Marshall due to the crew signing up on rest at 1030AM-CT. Once the crew signed up, briefed, and boarded the train, 21/421(26) departed Marshall at 1055AM-CT, 2 hours, and 33 minutes late.

Train 2(24) arrived New Orleans at 351AM-CT, 6 hours, and 11 minutes late. As a result, train 1(27) was delayed departing New Orleans due to the late turn of this equipment. Once the equipment was turned and serviced, 91 customers were welcomed aboard, and train 1(27) departed New Orleans at 1255PM-CT, 3 hours, and 55 minutes late.

WBS#: B.TR.100150.6944

Train	Delay	Comment
1(25)/421(24)	6'19"	W/SAS - ZLBHO-23
1(25)/421(24)	34"	Hacienda - relief crew
2/422(24)	6'11"	W/SAS - ZLBHO-23
22(26)	6'37"	SAS - held for connecting train 422(24)
1(27)	3'55"	NOL - late turn of equip 2(24)
21/421(26)	2'48"	MHL - crew rest

Pacific Surfliners San Clemente Pier, CA - Ocean Water Affecting Track Indication

25JUL26: Multiple Pacific Surfliner trains experienced delays due to high tide ocean conditions affecting the Metrolink Orange Subdivision east of San Clemente Pier, between approximately MP 206 and MP 207. The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. These restrictions resulted in cascading delays throughout the corridor, including additional train meets, congestion, and late-turn equipment impacts.

At approximately 11:50 PM PT, Metrolink reported a track-blocking event caused by a ballast washout in the same area. Maintenance crews were mobilized to make repairs, and rail service through the location was suspended pending restoration of the track structure.

Due to the overnight outage and the inability to secure bus transportation, the following Pacific Surfliner service adjustments were implemented:

- Train 595(25), carrying 461 customers onboard, was terminated at Oceanside (OSD) and returned toward its origin as a drop-off-only movement.
- Train 794(25), carrying 132 customers onboard, was terminated at Irvine (IRV) and returned toward its origin as a drop-off-only movement.
- Train 562(26) was canceled in its entirety, with customers directed to the next available service.
- Train 761(26) was canceled between San Diego and Los Angeles and instead originated in Los Angeles for service to Goleta (GTA).

Maintenance forces continued repair efforts while rail operators implemented service recovery measures across the corridor.

27JUL26: Track indication issues persist as high tides and oceans water reach the tracks.

Train	Delay	26-FOI-00625	00000008486 Comment	"UNCLASSIFIED"	8/7/2026
794 (25)	Term IRV				
562 (26)	Cancel				
761 (26)	Cancel SAN-LAX				
782 (25)	1'14"				
786 (25)	1'58"				
584 (25)	1'55"				
593 (25)	58"		late turn 782		
593 (25)	1'05"				
591 (25)	1'41"				
588 (25)	2'09"				
587 (25)	1'19"				
790 (25)	1'14"				
595 (25)	1'21"		late turn 584		
595 (25)	1'10"		Term OSD		
567 (26)	23"				
564 (26)	1'07"				
769 (26)	1'09"				
566 (26)	58"				
573 (26)	44"				
770 (44)	1'20"				
580 (26)	27"				
581 (26)	47"		late turn 770 (26)		
785 (26)	13"		late turn 774 (26)		
785 (26)	26"				
782 (26)	1'41"				
587 (26)	1'17"				
584 (26)	1'51'				
786 (26)	1'51"				
591 (26)	12"		late turn 580 (26)		
591 (26)	1'05"				
593 (26)	1'10"		late turn 782 (26)		
593 (26)	38"				
588 (26)	1'40"				
790 (26)	56"				
595 (26)	1'48"		late turn 584 (26)		
794 (26)	15"				
595 (26)	1'45"				
567 (20)	10"				
562 (27)	26"				
769 (27)	33"				
564 (27)	27"				
786 (27)	23"				
588 (27)	1'04"				
584 (27)	25"				
587 (27)	22"				
790 (27)	1'35"				
794 (27)	47"				
593 (27)	56"				
595 (27)	24"		late turn 584 (27)		
595 (27)	1'21"				

Havre, MT and Williston, ND - Heat Restrictions

24JUL26: Temperatures with the Great Plains reached temperatures exceeding 100°F. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow and Milk River Subdivision from Havre, MT to Williston, ND. Trains were restricted to 40MPH maximum authorized speed through the affected limits until temperatures recedes below 95°F. Train 7 / 27(23) and Train 8 / 28(23) were affected by the restrictions and freight interference.

25JUL26: Train 7(23) arrived into Seattle, WA 2'46" late causing late departure of 8(25). Train 27(23) arrived into Portland, OR 3'51" late causing late departure of 28(25).

25JUL26: Temperatures continue to be in excess of 100°F in the Great Plains. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow, Milk River and Hi-Line Subdivision from Stanley, ND and Cutbank, MT. Train 7 / 27(24) and Train 8 / 28(24) were affected by the restrictions and freight interference caused by the restrictions.

Due to late operation of 7/27(24) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(24) from Spokane to Seattle and for 27(24) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(26) Seattle to Spokane and 28(26) Portland to Spokane with Train 8/28(26) originating Spokane, WA.

27JUL26: Due to late operation of 7/27(25) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(25) from Spokane to Seattle and for 27(25) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(27) Seattle to Spokane and 28(27) Portland to Spokane with Train 8/28(27) originating Spokane, WA.

WBS#: B.TR.100150.6937

Train	Delay	Comment
8/28(23)	2'16"	
7/27(23)	2'55"	
8/28(24)	2'16"	
7/27(24)	2'20"	Term SPK
28(25)	57"	late turn 27(23)
8(25)	2'00"	late turn 7(23)
7/27(25)	2'26"	Term SPK
8/28(27)		Orig SPK
8/28(25)	1'46"	
8/28(26)	1'16"	Orig SPK
7/27(26)		Term SPK
8/28(28)		Orig SPK

Maintenance of Way Highlights

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.

-Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.

-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

-Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00625 00000008486 UNCLASSIFIED 8/7/2026racked scheduled C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No Data

Western Region

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train352(27) Passenger Removal at Kalamazoo, Michigan—Improper Conduct

27JUL26, Passenger, on PNR D432CA, traveling from Chicago, IL to Jackson, MI reportedly observed a group of passengers consuming their own alcoholic beverages onboard. The group was warned multiple times regarding prohibited behavior. Additionally, several passengers complained that the individuals were being excessively loud and disruptive. As a result, the passengers involved were removed from the train in Kalamazoo, MI. Amtrak Police notified.

Delay: 352 (27) NONE

Consist Deviations

26-FOI-00625

00000008486

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
173 (27)	BOS	Business Class car 81522 is operating in lieu of a coach.	NONE	0	81522
566 (28)	LAX	no bike space or wifi	NONE	0	90225
584 (28)	LAX	no bike space or wifi	NONE	0	90225
98 (27)	MIA	Due to a change of equipment on 98(27) line 9811 it was necessary to perform a schedule change. Utilize the WAR report to ensure all affected passengers are accommodated.	PASSENGERS REACCOMODATED	2	62507
40 (27)	MIA	Due to a change in equipment it was necessary to perform a schedule change on 40(27) car 62524-line-4011 and 41(29) car 62524-line 4111 . Please utilize the WAR report to ensure all passengers are acc	NONE	0	62524
185 (27)	NYP	185(27) will operate with a club-dinette in lieu of a cafe car.	NONE	0	48174
110 (27)	PHL	433XX CAFE REPLACED WITH SPLIT CLUB 48174	NONE	0	48174
579 (28)	SAN	no bike space or wifi	NONE	0	90225
595 (28)	SAN	no bike space or wifi	NONE	0	90225
125 (27)	SPG	125(28) will operate with a club-dinette in lieu of a cafe car.	NONE	0	48174
136 (27)	WAS	136(27) will operate with a club-dinette in lieu of a cafe car.	NONE	0	48174

Reverse Consists

Train Number	Station	Reason
94 (27)	NFK	Consist reversed Business class seat orientation may have changed At Front
93 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
173 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
190 (27)	PHL	Consist reversed Business class seat orientation may have changed At Front
181 (27)	NYP	Consist reversed Business class seat orientation may have changed At Front
170 (27)	WAS	Business class change only Business class seating orientation may have changed At Rear
175 (27)	BOS	Business class change only Business class seating orientation may have changed At Rear
136 (27)	WAS	Consist reversed Business class seat orientation may have changed At Front
137 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
94 (27)	NFK	Consist reversed Business class seat orientation may have changed At Front
171 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
125 (27)	SPG	Consist reversed Business class seat orientation may have changed At Front
184 (27)	WAS	Consist reversed Business class seat orientation may have changed At Front
178 (28)	RNK	Consist reversed Business class seat orientation may have changed At Front
138 (28)	NFK	Consist reversed Business class seat orientation may have changed At Front
173 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front