

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, August 17, 2026

Rules: 1-46



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/16/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	287	42	85.4%	4,809	779	83.8%	95,681	13,323	86.1%
Central Division	86.0%	53	3	94.3%	864	95	89.0%	18,220	1,661	90.9%
East Division	82.0%	155	27	82.6%	2,617	413	84.2%	50,287	7,831	84.4%
West Division	86.0%	79	12	84.8%	1,328	271	79.6%	27,174	3,831	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00671 00000008593 "UNCLASSIFIED" 9/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	98,045	30,792	69%	1,721,885	543,848	68%	32,054,883	8,185,198	74%
Northeast Corridor	81%	40,957	15,544	62%	746,236	206,537	72%	14,047,749	3,462,565	75%
Acela	83%	8,294	3,530	57%	153,647	38,692	75%	2,814,071	740,243	74%
Northeast Regional	79%	32,663	12,014	63%	592,589	167,845	72%	11,233,678	2,722,322	76%
Richmond / Newport News / Norfolk	77%	12,399	3,713	70%	184,993	69,061	63%	3,484,969	1,030,522	70%
Springfield Shuttles	89%	723	194	73%	9,820	1,582	84%	197,547	31,450	84%
Roanoke	79%	2,652	1,018	62%	58,714	17,560	70%	1,063,998	236,216	78%
On Spine Northeast Regional	80%	16,889	7,089	58%	339,062	79,642	77%	6,487,164	1,424,134	78%
State Supported	80%	46,187	10,610	77%	778,607	219,169	72%	14,088,226	3,025,094	79%
Borealis	80%	588	46	92%	9,714	2,244	77%	179,340	37,876	79%
Capitol Corridor	90%	2,568	477	81%	58,372	10,288	82%	1,174,091	156,037	87%
Carolinian	70%	1,271	182	86%	18,192	8,648	52%	363,074	143,647	60%
Cascades	75%	1,695	526	69%	28,119	14,539	48%	811,369	229,575	72%
Downeaster	82%	2,023	228	89%	33,580	3,709	89%	493,893	59,664	88%
Empire	78%	6,641	2,901	56%	102,494	35,650	65%	1,746,207	419,109	76%
Adirondack	72%	668	217	68%	7,350	3,903	47%	107,313	34,748	68%
Ethan Allen Express	70%	595	588	1%	9,551	5,989	37%	178,459	66,338	63%
Maple Leaf	70%	904	481	47%	14,693	6,568	55%	215,042	83,411	61%
New York - Albany	85%	2,382	723	70%	45,613	12,332	73%	807,961	138,259	83%
New York - Niagara Falls	75%	1,500	302	80%	22,985	5,090	78%	427,017	90,771	79%
Berkshire Flyer	60%	592	590	0%	2,302	1,768	23%	10,415	5,582	46%
Gold Runner	73%	2,690	866	68%	40,878	20,502	50%	796,444	290,955	63%
Heartland Flyer	70%	275	167	39%	4,163	2,983	28%	68,846	28,405	59%
Hiawatha	90%	2,123	162	92%	33,542	3,008	91%	554,461	60,705	89%
Illinois	78%	2,643	1,864	29%	43,386	17,754	59%	789,610	222,309	72%
Carl Sandburg / Illinois Zephyr	85%	620	318	49%	7,443	3,435	54%	132,243	37,593	72%
Illini / Saluki	85%	965	842	13%	13,211	6,421	51%	273,098	68,321	75%
Lincoln Service	70%	1,058	704	33%	22,732	7,898	65%	384,269	116,395	70%
Keystone	92%	4,776	748	84%	124,448	7,419	94%	2,406,567	246,965	90%
Lincoln / Missouri	70%	518	492	5%	13,964	9,757	30%	246,455	128,065	48%
Mardi Gras Service	80%	372	72	81%	5,163	1,113	78%	128,884	28,728	78%
Michigan	70%	2,690	329	88%	39,816	19,005	52%	637,241	211,426	67%
Blue Water	70%	730	4	99%	10,111	5,297	48%	149,769	61,125	59%
Pere Marquette	85%	165	0	100%	3,946	593	85%	82,380	15,717	81%
Wolverine	70%	1,795	325	82%	25,759	13,115	49%	405,092	134,584	67%
Missouri	80%	281	209	26%	4,558	2,414	47%	70,394	18,850	73%
Pacific Surfliner	85%	11,496	562	95%	167,166	46,296	72%	2,579,338	476,003	82%
Pennsylvanian	80%	871	196	77%	14,011	2,556	82%	279,813	53,633	81%
Piedmont	80%	1,366	0	100%	16,393	3,126	81%	356,667	91,778	74%
Vermont	75%	1,300	583	55%	20,648	8,158	60%	405,532	121,364	70%
Long Distance	70%	10,901	4,638	57%	197,042	118,142	40%	3,879,641	1,695,076	56%
Auto Train	70%	926	0	100%	13,876	3,143	77%	248,285	83,932	66%
California Zephyr	70%	1,012	650	36%	16,243	12,321	24%	307,837	118,978	61%
Cardinal	70%	0	0	-	2,134	1,307	39%	73,615	36,850	50%
City Of New Orleans	75%	570	558	2%	9,644	7,441	23%	200,868	65,620	67%
Coast Starlight	70%	957	184	81%	15,874	8,639	46%	360,551	129,101	64%
Crescent	70%	938	603	36%	14,112	4,138	71%	293,765	90,121	69%
Empire Builder	70%	1,023	122	88%	16,235	10,294	37%	304,602	152,499	50%
Floridian	60%	0	0	-	23,937	19,826	17%	501,703	346,868	31%
Lake Shore Ltd	73%	1,210	375	69%	18,475	7,840	58%	305,712	92,946	70%
Palmetto	70%	998	533	47%	14,824	8,051	46%	290,927	90,660	69%
Silver Meteor	70%	1,112	498	55%	16,121	10,604	34%	321,321	147,955	54%
Southwest Chief	60%	779	655	16%	14,830	11,902	20%	265,296	174,495	34%
Sunset Ltd	70%	266	145	45%	3,832	2,932	23%	92,198	35,700	61%
Texas Eagle	70%	1,110	315	72%	16,905	9,704	43%	312,961	129,351	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00071 0000000000 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 16, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	107,638	1,683,357	639	1,897,717	33,631,294	564

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	6,048	514,301	118	91,960	9,711,303	95
INFRASTRUCTURE PLANNED	135	10,646	514,301	207	106,701	9,711,303	110
FLEET RELIABILITY	90	16,021	1,683,357	95	302,161	33,631,294	90
TRAIN OPERATIONS	424	74,923	1,683,357	445	1,396,895	33,631,294	415

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/16/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	287	42	85.4%	4,809	779	83.8%	95,681	13,323	86.1%
Central Division	86.0%	53	3	94.3%	864	95	89.0%	18,220	1,661	90.9%
East Division	82.0%	155	27	82.6%	2,617	413	84.2%	50,287	7,831	84.4%
West Division	86.0%	79	12	84.8%	1,328	271	79.6%	27,174	3,831	85.9%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/16/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	287	42	85.4%	4,809	779	83.8%	95,681	13,323	86.1%
Central Division	86.0%	53	3	94.3%	864	95	89.0%	18,220	1,661	90.9%
CDL	95.0%	2	0	100.0%	30	3	90.0%	606	28	95.4%
CHI	86.0%	24	3	87.5%	399	64	84.0%	8,413	1,028	87.8%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	16	0	100.0%	343	36	89.5%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	11	0	100.0%	299	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	1	0	100.0%	16	3	81.3%	573	45	92.1%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	0	100.0%	92	6	93.5%	1,872	120	93.6%
MOE	97.5%	2	0	100.0%	32	0	100.0%	637	9	98.6%
MSP	96.5%	1	0	100.0%	16	1	93.8%	313	7	97.8%
NOL	94.5%	4	0	100.0%	70	2	97.1%	1,343	62	95.4%
OKC	97.0%	1	0	100.0%	16	0	100.0%	314	6	98.1%
PNT	88.0%	3	0	100.0%	45	5	88.9%	832	69	91.7%
PTH	93.0%	1	0	100.0%	16	2	87.5%	308	13	95.8%
QCY	91.0%	2	0	100.0%	27	2	92.6%	604	45	92.5%
SAS	90.5%	1	0	100.0%	16	3	81.3%	317	36	88.6%
STL	89.0%	4	0	100.0%	61	3	95.1%	1,230	100	91.9%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	155	27	82.6%	2,617	413	84.2%	50,287	7,831	84.4%
ALB	88.5%	8	0	100.0%	118	6	94.9%	2,368	181	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	80	10	87.5%	1,546	168	89.1%
BOS	85.5%	16	1	93.8%	275	19	93.1%	5,438	623	88.5%
BRK	92.5%	5	1	80.0%	80	7	91.3%	1,532	109	92.9%
BTN	82.0%	-	-	-	15	1	93.3%	305	42	86.2%
CLT	91.5%	5	0	100.0%	80	8	90.0%	1,557	158	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	25	2	92.0%	618	59	90.5%
GRO	-	-	-	-	8	0	100.0%	41	10	75.6%
HAR	79.5%	7	1	85.7%	172	28	83.7%	3,536	576	83.7%
HFD	-	-	-	-	19	3	84.2%	210	18	91.4%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	16	0	100.0%	316	38	88.0%
MIA	89.5%	2	1	50.0%	29	4	86.2%	629	72	88.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/16/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	287	42	85.4%	4,809	779	83.8%	95,681	13,323	86.1%
East Division	82.0%	155	27	82.6%	2,617	413	84.2%	50,287	7,831	84.4%
MTR	79.0%	1	0	100.0%	16	5	68.8%	303	57	81.2%
NFK	84.5%	2	0	100.0%	32	6	81.3%	715	129	82.0%
NFL	93.5%	2	0	100.0%	32	1	96.9%	644	30	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	77	21	72.7%	1,631	274	83.2%
NPN	93.0%	2	0	100.0%	32	5	84.4%	604	46	92.4%
NYP	75.5%	42	14	66.7%	734	167	77.2%	13,218	2,945	77.7%
PGH	93.0%	1	0	100.0%	16	1	93.8%	317	23	92.7%
PHL	48.0%	4	2	50.0%	74	31	58.1%	1,624	771	52.5%
PIT	76.0%	1	1	0.0%	5	5	0.0%	20	17	15.0%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	0	100.0%	56	2	96.4%	1,214	51	95.8%
RNK	83.5%	2	0	100.0%	32	2	93.8%	628	89	85.8%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	13	0	100.0%	300	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	16	1	93.8%	313	11	96.5%
SFA	88.0%	1	0	100.0%	16	1	93.8%	316	42	86.7%
SPG	92.5%	7	0	100.0%	77	5	93.5%	1,884	110	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	16	3	81.3%	305	63	79.3%
WAS	84.0%	27	5	81.5%	456	69	84.9%	7,928	1,036	86.9%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	79	12	84.8%	1,328	271	79.6%	27,174	3,831	85.9%
ARN	92.0%	1	0	100.0%	16	1	93.8%	318	27	91.5%
BFD	79.0%	7	2	71.4%	111	27	75.7%	2,008	420	79.1%
EMY	72.0%	1	0	100.0%	16	3	81.3%	334	97	71.0%
EUG	86.5%	2	0	100.0%	32	2	93.8%	630	58	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	5	3	40.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	48	15	68.8%	957	158	83.5%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	0	100.0%	164	18	89.0%	3,163	344	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	9	1	88.9%	182	70	61.5%	3,443	898	73.9%
PDX	86.0%	3	1	66.7%	41	27	34.1%	1,529	208	86.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/16/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	287	42	85.4%	4,809	779	83.8%	95,681	13,323	86.1%
West Division	86.0%	79	12	84.8%	1,328	271	79.6%	27,174	3,831	85.9%
SAC	88.5%	12	4	66.7%	229	26	88.6%	4,495	488	89.1%
SAN	90.5%	13	1	92.3%	203	19	90.6%	3,844	363	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	3	0	100.0%	66	30	54.5%	2,451	377	84.6%
SJC	89.0%	7	1	85.7%	111	10	91.0%	2,235	219	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	48	6	87.5%	720	71	90.1%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	5	3	40.0%	303	29	90.4%
VAC	97.0%	2	0	100.0%	32	0	100.0%	623	14	97.8%
VAN	-	2	1	50.0%	23	14	39.1%	23	14	39.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		7	4	42.9%	136	35	74.3%	7	2	71.4%	131	26	80.2%
3	115	16	3	81.3%	318	62	80.5%	15	11	26.7%	315	147	53.3%
4	177	16	1	93.8%	317	47	85.2%	16	12	25.0%	317	211	33.4%
5	101	16	3	81.3%	316	53	83.2%	16	14	12.5%	312	102	67.3%
6	33	16	3	81.3%	315	88	72.1%	16	15	6.3%	315	118	62.5%
7		16	4	75.0%	307	46	85.0%	15	7	53.3%	298	81	72.8%
8		16	10	37.5%	307	139	54.7%	16	12	25.0%	306	187	38.9%
11		16	13	18.8%	318	70	78.0%	16	5	68.8%	312	65	79.2%
14		16	2	87.5%	319	51	84.0%	15	10	33.3%	316	102	67.7%
19	94	16	2	87.5%	317	79	75.1%	16	4	75.0%	314	75	76.1%
20	31	16	0	100.0%	317	23	92.7%	16	4	75.0%	317	62	80.4%
21		16	6	62.5%	314	31	90.1%	16	5	68.8%	313	87	72.2%
22	56	16	3	81.3%	315	34	89.2%	16	9	43.8%	313	90	71.2%
23		16	0	100.0%	319	6	98.1%	16	3	81.3%	317	88	72.2%
24		16	0	100.0%	319	16	95.0%	16	5	68.8%	318	61	80.8%
25	83	16	0	100.0%	318	3	99.1%	15	6	60.0%	315	89	71.7%
26		16	0	100.0%	318	5	98.4%	15	1	93.3%	315	61	80.6%
42		16	1	93.8%	319	25	92.2%	16	3	81.3%	317	55	82.6%
43	21	16	2	87.5%	318	44	86.2%	16	2	87.5%	317	72	77.3%
48	38	16	4	75.0%	317	61	80.8%	16	5	68.8%	316	47	85.1%
49		16	5	68.8%	317	80	74.8%	16	5	68.8%	317	67	78.9%
50	No OS	5	1	80.0%	129	31	76.0%	4	3	25.0%	128	79	38.3%
52		16	1	93.8%	316	42	86.7%	16	0	100.0%	315	72	77.1%
53		16	0	100.0%	316	38	88.0%	16	5	68.8%	315	100	68.3%
54		6	0	100.0%	115	8	93.0%	6	0	100.0%	115	16	86.1%
57	75	6	0	100.0%	114	5	95.6%	6	1	83.3%	114	10	91.2%
58	84	15	1	93.3%	292	17	94.2%	14	12	14.3%	290	85	70.7%
59	283	16	10	37.5%	291	43	85.2%	15	12	20.0%	286	69	75.9%
63	136	16	7	56.3%	320	139	56.6%	16	16	0.0%	314	182	42.0%
64	54	16	3	81.3%	318	71	77.7%	16	12	25.0%	317	121	61.8%
65		5	0	100.0%	98	12	87.8%	6	1	83.3%	97	14	85.6%
66	58	16	1	93.8%	317	62	80.4%	16	4	75.0%	313	58	81.5%
68		16	5	68.8%	320	66	79.4%	16	10	37.5%	319	128	59.9%
69		16	8	50.0%	307	76	75.2%	16	8	50.0%	302	51	83.1%
71		16	0	100.0%	315	3	99.0%	15	4	73.3%	313	85	72.8%
72	11	16	3	81.3%	311	34	89.1%	15	6	60.0%	309	67	78.3%
73		16	2	87.5%	314	21	93.3%	16	4	75.0%	312	146	53.2%
74		16	0	100.0%	312	33	89.4%	16	4	75.0%	310	112	63.9%
75		16	0	100.0%	308	16	94.8%	16	7	56.3%	302	144	52.3%
76		16	1	93.8%	308	30	90.3%	16	7	56.3%	299	124	58.5%
77		16	0	100.0%	310	20	93.5%	16	4	75.0%	308	127	58.8%
78		16	1	93.8%	314	26	91.7%	16	8	50.0%	313	71	77.3%

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79		16	2	87.5%	317	58	81.7%	16	6	62.5%	316	107	66.1%
80		16	3	81.3%	317	36	88.6%	16	8	50.0%	314	71	77.4%
87	49	6	2	66.7%	118	26	78.0%	6	5	16.7%	118	44	62.7%
88	16	6	0	100.0%	114	15	86.8%	6	2	66.7%	114	25	78.1%
89	61	16	8	50.0%	315	73	76.8%	16	9	43.8%	313	94	70.0%
90		16	1	93.8%	315	11	96.5%	16	6	62.5%	314	57	81.8%
96		3	0	100.0%	41	8	80.5%	3	0	100.0%	41	10	75.6%
97		16	10	37.5%	317	208	34.4%	16	11	31.3%	315	111	64.8%
98		16	0	100.0%	317	26	91.8%	16	9	43.8%	315	117	62.9%
99	37	6	0	100.0%	117	12	89.7%	6	4	33.3%	114	65	43.0%
100		3	0	100.0%	26	5	80.8%	3	0	100.0%	25	4	84.0%
103		6	3	50.0%	116	24	79.3%	6	2	66.7%	116	11	90.5%
104		3	0	100.0%	38	4	89.5%	3	0	100.0%	38	3	92.1%
105	18	3	2	33.3%	40	19	52.5%	3	2	33.3%	40	8	80.0%
117		3	3	0.0%	25	16	36.0%	3	0	100.0%	25	4	84.0%
118		6	0	100.0%	116	8	93.1%	6	0	100.0%	116	8	93.1%
120		3	0	100.0%	41	5	87.8%	3	1	66.7%	41	5	87.8%
121	49	3	1	66.7%	41	12	70.7%	3	2	33.3%	41	18	56.1%
122	21	3	2	33.3%	40	17	57.5%	3	3	0.0%	40	11	72.5%
123		3	1	66.7%	43	7	83.7%	3	0	100.0%	43	1	97.7%
124		6	0	100.0%	115	8	93.0%	6	2	66.7%	114	32	71.9%
128		6	0	100.0%	118	19	83.9%	5	1	80.0%	117	23	80.3%
132		3	0	100.0%	41	3	92.7%	3	1	66.7%	41	5	87.8%
135	58	6	1	83.3%	117	18	84.6%	6	1	83.3%	117	57	51.3%
140	17	6	1	83.3%	116	13	88.8%	6	3	50.0%	115	27	76.5%
143	85	6	2	66.7%	115	13	88.7%	6	2	66.7%	115	27	76.5%
145	20	3	1	66.7%	41	7	82.9%	3	2	33.3%	41	16	61.0%
146	64	6	1	83.3%	115	18	84.3%	6	2	66.7%	115	41	64.3%
149	21	3	0	100.0%	41	3	92.7%	3	1	66.7%	41	15	63.4%
150	114	6	3	50.0%	114	60	47.4%	6	1	83.3%	112	52	53.6%
151		16	6	62.5%	316	101	68.0%	16	2	87.5%	315	97	69.2%
153		6	1	83.3%	116	11	90.5%	6	3	50.0%	116	19	83.6%
154		3	0	100.0%	41	5	87.8%	3	0	100.0%	41	20	51.2%
155		6	2	66.7%	118	20	83.1%	6	2	66.7%	118	42	64.4%
156		6	1	83.3%	118	12	89.8%	6	2	66.7%	118	40	66.1%
157		3	1	66.7%	41	4	90.2%	3	0	100.0%	41	12	70.7%
158		6	2	66.7%	117	22	81.2%	6	1	83.3%	117	27	76.9%
160		6	1	83.3%	115	7	93.9%	6	0	100.0%	112	26	76.8%
161	30	6	1	83.3%	116	10	91.4%	6	5	16.7%	115	77	33.0%
162	18	6	3	50.0%	116	10	91.4%	6	2	66.7%	116	57	50.9%
164	19	6	0	100.0%	118	9	92.4%	6	3	50.0%	118	50	57.6%
165	17	6	0	100.0%	116	27	76.7%	6	2	66.7%	116	47	59.5%

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
169	24	6	0	100.0%	116	12	89.7%	5	1	80.0%	115	25	78.3%
189	23	3	1	66.7%	40	12	70.0%	3	3	0.0%	40	18	55.0%
195	39	6	1	83.3%	116	5	95.7%	6	4	33.3%	116	63	45.7%
230		16	0	100.0%	153	4	97.4%	16	0	100.0%	153	7	95.4%
232		16	0	100.0%	319	11	96.6%	16	2	87.5%	319	23	92.8%
234		16	0	100.0%	320	22	93.1%	16	0	100.0%	319	25	92.2%
235		16	7	56.3%	244	41	83.2%	16	5	68.8%	243	57	76.5%
236		16	0	100.0%	304	10	96.7%	16	3	81.3%	303	42	86.1%
237		16	0	100.0%	317	56	82.3%	16	3	81.3%	315	54	82.9%
238	20	16	3	81.3%	244	23	90.6%	16	3	81.3%	242	21	91.3%
239		16	2	87.5%	318	81	74.5%	16	2	87.5%	317	40	87.4%
240	41	16	1	93.8%	319	22	93.1%	16	5	68.8%	316	65	79.4%
241		16	6	62.5%	319	80	74.9%	16	7	56.3%	319	78	75.5%
243		16	4	75.0%	255	69	72.9%	16	3	81.3%	254	36	85.8%
245	82	16	4	75.0%	200	37	81.5%	16	5	68.8%	199	27	86.4%
280	31	16	1	93.8%	320	16	95.0%	16	6	62.5%	319	67	79.0%
281		16	1	93.8%	320	38	88.1%	16	2	87.5%	320	59	81.6%
283		16	8	50.0%	320	82	74.4%	16	3	81.3%	320	64	80.0%
284		16	0	100.0%	320	13	95.9%	16	1	93.8%	317	55	82.6%
290	24	16	1	93.8%	320	51	84.1%	16	11	31.3%	317	125	60.6%
291	46	16	10	37.5%	319	103	67.7%	15	7	53.3%	316	83	73.7%
300	24	14	1	92.9%	302	21	93.0%	14	5	64.3%	300	73	75.7%
301	86	16	0	100.0%	317	10	96.8%	16	5	68.8%	313	60	80.8%
302	55	15	0	100.0%	298	33	88.9%	15	7	53.3%	294	85	71.1%
305	53	14	1	92.9%	300	29	90.3%	14	4	71.4%	296	119	59.8%
306	50	16	1	93.8%	315	17	94.6%	15	4	73.3%	313	86	72.5%
307		16	2	87.5%	308	40	87.0%	15	5	66.7%	304	87	71.4%
311	26	16	1	93.8%	313	27	91.4%	16	9	43.8%	307	72	76.5%
316		16	3	81.3%	309	21	93.2%	16	11	31.3%	304	89	70.7%
318	33	16	1	93.8%	318	32	89.9%	16	11	31.3%	315	155	50.8%
319	328	16	0	100.0%	319	20	93.7%	16	15	6.3%	314	180	42.7%
331		16	0	100.0%	320	33	89.7%	15	0	100.0%	319	44	86.2%
332		15	1	93.3%	319	18	94.4%	15	2	86.7%	319	45	85.9%
334		16	1	93.8%	320	11	96.6%	15	1	93.3%	318	41	87.1%
335		16	0	100.0%	320	34	89.4%	16	3	81.3%	318	54	83.0%
336		16	0	100.0%	320	10	96.9%	16	0	100.0%	318	28	91.2%
337		16	1	93.8%	320	19	94.1%	16	5	68.8%	316	41	87.0%
338		16	3	81.3%	320	50	84.4%	16	6	62.5%	318	100	68.6%
339		16	3	81.3%	320	53	83.4%	16	3	81.3%	320	56	82.5%
341	17	15	4	73.3%	307	48	84.4%	15	8	46.7%	301	49	83.7%
342		16	1	93.8%	320	25	92.2%	16	0	100.0%	318	60	81.1%
350	17	14	0	100.0%	295	18	93.9%	14	11	21.4%	288	162	43.8%

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
351		15	2	86.7%	302	29	90.4%	15	7	53.3%	300	85	71.7%
352		15	2	86.7%	286	23	92.0%	15	7	53.3%	280	88	68.6%
353		16	0	100.0%	258	13	95.0%	16	6	62.5%	252	44	82.5%
354		16	1	93.8%	301	36	88.0%	16	12	25.0%	294	113	61.6%
355	24	14	3	78.6%	308	34	89.0%	13	11	15.4%	300	110	63.3%
364		16	5	68.8%	309	70	77.3%	16	8	50.0%	303	115	62.0%
365		16	2	87.5%	308	13	95.8%	15	7	53.3%	305	116	62.0%
371		11	0	100.0%	299	8	97.3%	11	0	100.0%	298	29	90.3%
380	58	13	1	92.3%	302	28	90.7%	12	4	66.7%	301	67	77.7%
381	64	14	1	92.9%	316	13	95.9%	14	8	42.9%	315	68	78.4%
382	30	14	1	92.9%	315	28	91.1%	14	11	21.4%	315	111	64.8%
383		14	1	92.9%	307	27	91.2%	14	8	42.9%	304	131	56.9%
390	67	15	3	80.0%	301	22	92.7%	14	9	35.7%	299	82	72.6%
391	48	15	1	93.3%	302	12	96.0%	15	10	33.3%	298	86	71.1%
392	93	15	0	100.0%	315	10	96.8%	14	6	57.1%	311	96	69.1%
393	38	16	1	93.8%	320	19	94.1%	15	10	33.3%	316	101	68.0%
400		4	0	100.0%	95	6	93.7%	4	0	100.0%	93	2	97.8%
405		4	0	100.0%	88	0	100.0%	4	0	100.0%	88	4	95.5%
409		2	0	100.0%	41	1	97.6%	2	0	100.0%	41	4	90.2%
416		2	0	100.0%	37	4	89.2%	2	0	100.0%	37	3	91.9%
448		10	2	80.0%	244	45	81.6%	9	4	55.6%	240	84	65.0%
450	38	4	1	75.0%	91	28	69.2%	4	1	75.0%	89	29	67.4%
460		4	1	75.0%	91	29	68.1%	4	0	100.0%	88	30	65.9%
461		4	0	100.0%	96	5	94.8%	4	0	100.0%	95	2	97.9%
464	18	5	4	20.0%	92	20	78.3%	4	1	75.0%	89	26	70.8%
465	24	2	0	100.0%	42	1	97.6%	2	1	50.0%	42	2	95.2%
488		4	0	100.0%	101	28	72.3%	4	0	100.0%	91	13	85.7%
497		2	0	100.0%	39	1	97.4%	2	0	100.0%	39	7	82.1%
499		4	0	100.0%	92	13	85.9%	4	0	100.0%	89	6	93.3%
503		16	12	25.0%	316	39	87.7%	16	12	25.0%	309	99	68.0%
504		16	1	93.8%	320	20	93.8%	16	4	75.0%	318	94	70.4%
505		10	1	90.0%	312	42	86.5%	10	4	60.0%	307	88	71.3%
506		16	11	31.3%	315	53	83.2%	14	3	78.6%	307	49	84.0%
507		16	10	37.5%	320	46	85.6%	16	10	37.5%	320	110	65.6%
508	21	16	1	93.8%	315	42	86.7%	16	10	37.5%	311	78	74.9%
516		16	6	62.5%	311	35	88.7%	16	8	50.0%	310	142	54.2%
517	33	16	0	100.0%	320	8	97.5%	16	13	18.8%	316	140	55.7%
518	42	16	8	50.0%	320	45	85.9%	16	16	0.0%	318	223	29.9%
519		16	0	100.0%	311	9	97.1%	16	4	75.0%	309	70	77.3%
562		16	2	87.5%	311	25	92.0%	16	0	100.0%	307	35	88.6%
564		16	0	100.0%	312	19	93.9%	16	3	81.3%	304	41	86.5%
566		16	3	81.3%	310	28	91.0%	16	6	62.5%	307	51	83.4%

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
567		16	0	100.0%	197	10	94.9%	16	2	87.5%	195	11	94.4%
572		16	1	93.8%	307	25	91.9%	16	7	56.3%	300	90	70.0%
573		16	2	87.5%	309	42	86.4%	16	3	81.3%	302	54	82.1%
579		16	1	93.8%	197	12	93.9%	15	3	80.0%	191	40	79.1%
580		16	1	93.8%	312	17	94.6%	16	4	75.0%	305	32	89.5%
581		16	3	81.3%	312	53	83.0%	16	7	56.3%	310	71	77.1%
584	39	16	3	81.3%	196	28	85.7%	16	16	0.0%	191	124	35.1%
587		16	2	87.5%	305	18	94.1%	16	4	75.0%	296	57	80.7%
588		14	1	92.9%	195	19	90.3%	14	5	64.3%	194	38	80.4%
591		16	1	93.8%	309	22	92.9%	15	4	73.3%	302	43	85.8%
593		13	2	84.6%	303	49	83.8%	13	1	92.3%	282	38	86.5%
595		14	3	78.6%	305	56	81.6%	14	4	71.4%	302	64	78.8%
612		3	2	33.3%	40	7	82.5%	3	0	100.0%	40	1	97.5%
615		3	1	66.7%	41	22	46.3%	3	0	100.0%	40	7	82.5%
637	46	6	0	100.0%	69	7	89.9%	5	1	80.0%	68	6	91.2%
660		6	1	83.3%	87	13	85.1%	6	1	83.3%	86	26	69.8%
661		6	0	100.0%	115	12	89.6%	6	1	83.3%	114	42	63.2%
663		6	1	83.3%	88	15	83.0%	6	0	100.0%	87	8	90.8%
664		6	0	100.0%	87	8	90.8%	6	2	66.7%	87	13	85.1%
665		6	0	100.0%	88	10	88.6%	6	1	83.3%	88	25	71.6%
666		6	0	100.0%	86	22	74.4%	6	0	100.0%	86	7	91.9%
667		6	0	100.0%	86	7	91.9%	6	0	100.0%	84	16	81.0%
669		6	0	100.0%	86	7	91.9%	6	0	100.0%	84	22	73.8%
670		6	0	100.0%	88	13	85.2%	6	1	83.3%	86	16	81.4%
671	14	6	0	100.0%	86	8	90.7%	6	1	83.3%	84	10	88.1%
672	15	6	1	83.3%	88	9	89.8%	6	2	66.7%	88	17	80.7%
674		6	3	50.0%	86	29	66.3%	6	0	100.0%	86	7	91.9%
690		6	0	100.0%	92	2	97.8%	6	1	83.3%	91	5	94.5%
691	39	6	1	83.3%	92	8	91.3%	6	3	50.0%	90	26	71.1%
692		6	1	83.3%	92	4	95.7%	6	1	83.3%	91	15	83.5%
693	15	6	1	83.3%	92	13	85.9%	6	5	16.7%	90	29	67.8%
694		6	1	83.3%	91	10	89.0%	6	1	83.3%	91	15	83.5%
695		6	0	100.0%	90	10	88.9%	6	2	66.7%	90	16	82.2%
696		6	2	66.7%	92	11	88.0%	6	2	66.7%	92	27	70.7%
697		6	3	50.0%	92	22	76.1%	6	2	66.7%	92	19	79.3%
698		6	1	83.3%	90	3	96.7%	6	1	83.3%	90	8	91.1%
701	17	16	2	87.5%	252	27	89.3%	16	3	81.3%	249	28	88.8%
702	51	16	0	100.0%	319	32	90.0%	16	6	62.5%	316	76	75.9%
703		16	12	25.0%	320	105	67.2%	16	9	43.8%	318	94	70.4%
704	63	16	5	68.8%	251	42	83.3%	15	5	66.7%	243	51	79.0%
710		16	1	93.8%	320	78	75.6%	16	4	75.0%	316	85	73.1%
711		16	2	87.5%	311	36	88.4%	15	8	46.7%	289	60	79.2%

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
712		16	8	50.0%	317	88	72.2%	16	8	50.0%	308	106	65.6%
713	18	15	0	100.0%	187	16	91.4%	12	8	33.3%	168	75	55.4%
714		16	10	37.5%	201	85	57.7%	14	10	28.6%	185	86	53.5%
715		16	1	93.8%	319	62	80.6%	13	7	46.2%	293	148	49.5%
716		16	12	25.0%	320	132	58.8%	15	12	20.0%	313	130	58.5%
717		16	3	81.3%	305	71	76.7%	13	4	69.2%	283	90	68.2%
718		16	12	25.0%	320	165	48.4%	15	11	26.7%	317	120	62.1%
719	45	16	7	56.3%	320	110	65.6%	15	7	53.3%	303	91	70.0%
720		6	0	100.0%	99	9	90.9%	6	0	100.0%	99	6	93.9%
723		6	0	100.0%	99	5	94.9%	6	2	66.7%	99	11	88.9%
724		6	2	66.7%	99	5	94.9%	4	1	75.0%	97	20	79.4%
727		6	0	100.0%	99	7	92.9%	6	1	83.3%	99	15	84.8%
728		6	1	83.3%	99	7	92.9%	6	1	83.3%	99	18	81.8%
729		6	1	83.3%	98	16	83.7%	6	3	50.0%	97	24	75.3%
732		6	3	50.0%	97	18	81.4%	6	3	50.0%	95	20	78.9%
733		6	0	100.0%	99	14	85.9%	6	2	66.7%	94	31	67.0%
734	104	6	1	83.3%	99	15	84.8%	6	2	66.7%	98	23	76.5%
736	55	6	0	100.0%	75	7	90.7%	6	3	50.0%	73	12	83.6%
737		6	0	100.0%	75	7	90.7%	6	1	83.3%	74	13	82.4%
738		6	0	100.0%	99	15	84.8%	5	0	100.0%	93	13	86.0%
741		6	0	100.0%	99	13	86.9%	6	0	100.0%	99	18	81.8%
742		5	2	60.0%	97	13	86.6%	4	0	100.0%	94	7	92.6%
743	Cncld	6	3	50.0%	99	20	79.8%	3	1	66.7%	95	11	88.4%
744		6	0	100.0%	99	15	84.8%	6	1	83.3%	99	33	66.7%
745	56	6	2	66.7%	99	12	87.9%	6	1	83.3%	98	15	84.7%
746		6	1	83.3%	99	9	90.9%	6	1	83.3%	98	14	85.7%
747	65	6	1	83.3%	99	16	83.8%	6	3	50.0%	99	24	75.8%
748		6	1	83.3%	98	14	85.7%	6	1	83.3%	98	14	85.7%
749		6	1	83.3%	96	15	84.4%	6	2	66.7%	87	12	86.2%
751		6	0	100.0%	98	16	83.7%	5	0	100.0%	94	11	88.3%
757		16	1	93.8%	105	6	94.3%	16	2	87.5%	104	10	90.4%
761		16	1	93.8%	316	13	95.9%	16	2	87.5%	313	43	86.3%
765		16	0	100.0%	316	25	92.1%	16	3	81.3%	316	45	85.8%
769		16	0	100.0%	316	27	91.5%	16	4	75.0%	310	61	80.3%
770		16	2	87.5%	316	24	92.4%	16	10	37.5%	314	99	68.5%
774		16	0	100.0%	316	16	94.9%	16	5	68.8%	315	74	76.5%
777	21	16	0	100.0%	201	12	94.0%	16	8	50.0%	200	50	75.0%
782		16	12	25.0%	201	94	53.2%	16	5	68.8%	196	30	84.7%
785		16	4	75.0%	316	26	91.8%	16	5	68.8%	316	58	81.6%
786		16	2	87.5%	105	21	80.0%	15	9	40.0%	101	56	44.6%
790		16	1	93.8%	316	29	90.8%	16	3	81.3%	313	49	84.3%
794		16	4	75.0%	316	37	88.3%	16	6	62.5%	312	72	76.9%

Amtrak On Time Performance

Trains Arriving Through: 8/16/2026

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
821		16	0	100.0%	314	6	98.1%	16	11	31.3%	314	132	58.0%
822	27	16	0	100.0%	316	16	94.9%	16	14	12.5%	314	156	50.3%
1233	76	5	1	80.0%	20	5	75.0%	3	3	0.0%	18	11	38.9%
1246	48	5	5	0.0%	20	17	15.0%	5	3	40.0%	20	10	50.0%
1333		16	4	75.0%	316	36	88.6%	16	4	75.0%	313	103	67.1%
1340		16	1	93.8%	315	7	97.8%	16	4	75.0%	315	55	82.5%
1689		10	1	90.0%	105	6	94.3%	11	2	81.8%	105	13	87.6%
2208		6	1	83.3%	17	4	76.5%	6	1	83.3%	17	4	76.5%
2209		3	0	100.0%	7	0	100.0%	3	1	66.7%	7	2	71.4%
2212		3	1	66.7%	8	1	87.5%	2	0	100.0%	7	1	85.7%
2213		3	1	66.7%	7	1	85.7%	3	0	100.0%	7	2	71.4%
2215	29	3	0	100.0%	27	9	66.7%	3	1	66.7%	27	14	48.1%
2216		3	0	100.0%	75	3	96.0%	3	1	66.7%	75	4	94.7%
2218		3	1	66.7%	72	15	79.2%	3	1	66.7%	72	14	80.6%
2219	22	6	0	100.0%	17	3	82.4%	6	1	83.3%	17	5	70.6%
2222	41	3	1	66.7%	57	5	91.2%	3	2	33.3%	56	9	83.9%
2223	18	3	1	66.7%	27	6	77.8%	2	1	50.0%	25	5	80.0%
2224		6	1	83.3%	32	6	81.3%	5	0	100.0%	31	4	87.1%
2226		3	1	66.7%	39	8	79.5%	3	1	66.7%	37	10	73.0%
2227		3	1	66.7%	7	2	71.4%	3	0	100.0%	7	0	100.0%
2252		6	0	100.0%	112	9	92.0%	6	0	100.0%	110	32	70.9%
2254		6	0	100.0%	47	3	93.6%	6	1	83.3%	47	13	72.3%
2255	22	6	0	100.0%	114	11	90.4%	6	3	50.0%	113	53	53.1%
2258	31	6	0	100.0%	50	9	82.0%	6	4	33.3%	49	23	53.1%
2259	40	6	1	83.3%	70	25	64.3%	6	2	66.7%	69	32	53.6%
2260	46	6	0	100.0%	16	2	87.5%	6	4	33.3%	16	12	25.0%
2265	43	6	2	66.7%	51	6	88.2%	6	2	66.7%	50	29	42.0%
2267	40	6	0	100.0%	14	3	78.6%	6	3	50.0%	13	8	38.5%
2271	22	6	0	100.0%	97	11	88.7%	6	1	83.3%	96	47	51.0%
2290		3	1	66.7%	39	10	74.4%	3	0	100.0%	38	7	81.6%
2293		6	2	66.7%	15	3	80.0%	6	0	100.0%	15	3	80.0%

Amtrak Endpoint OTP Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/16/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2215	WAS	29	SMW	39	SMW	29	NYP-NWK	AM	Scheduled in track usage program, Other, XBH-XPT, HELD AT LACK A/C SINGLE TRACKING NO.3 TRK LACK TO HUDSON	
2219	WAS	22	SMW	16	SMW	11	NYP-NWK	AM	Scheduled in track usage program, Other, LACK-HUDSON SINGLE TRACKING	
2222	NYP	41	DCS	44	DCS	44	NWK-NYP	AM	T.O.L, Other, OVER NO.23SW AT HUDSON	
2223	WAS	18	OTH	15	PSR	10	XCY-XHM	AM	Slow bys, Other, 60MPH S/R NO.4 TRACK EL HAM FLWD AM2265	
2255	WAS	22	CTI	36	CTI	16	NHV-STM	MN	Follow mn, Milepost, 72, 33	
2258	BOS	31	DCS	12	DCS	12	RTE-BBY	AM	T.O.L, Milepost w/Letters, RTE, BBY, TOL trk 2 east of Read	
2259	WAS	40	SMW	26	SMW	23	XGX-NHV	AM	Scheduled in track usage program, Control Point, Mill River, Held at Mill River for Metro North track outage	
2260	BOS	46	ENG	35	ENG	35	NHV-XGX	AM	Other electrical failure, 2154 NG NP, AM2260 E/2154 stopped east of Mill River, back otm east after having to de-prepare	
2265	WAS	43	ENG	30	ENG	30	NWK-MET	AM	HEP, 2129 NG NP, STOPPED NO.3 TRACK RECONFIGURING PANTOGRAPH REPORTS NO HEP	
2267	WAS	40	SMW	23	SMW	12	XSH-NYP	AM	Scheduled in track usage program, Other, XSH NYP	
2271	WAS	22	DSR	22	DSR	22	NHV-STM	MN	Per bulletin Milepost w/Letters, NHV, STM, 30, 2	
66	BOS	58	SVS	30	SVS	30	NHV-NHV	AM	Pick up equipment, ADD PROTECTO ENGINE TO GIVE TO BOSTON	
87	NFK	49	WTR	45	WTR	18	FBG-ASD	CS	High winds Milepost, 43.0, 14.8	
88	BOS	16	SMW	15	SMW	13	NWK-NYP	AM	Scheduled in track usage program, Other, HUDSON-LACK SINGLE TRACKING	
99	NPN	37	WTR	42	WTR	35	RVM-WBG	CS	High winds Other, rvm-wbg	
105	WAS	18	SMW	30	SMW	30	NYP-NWK	AM	Scheduled in track usage program, Other, XBH-XPT, HELD AT ERIE A/C SINGLE TRACKING NO.3 TRK LACK TO HUDSON	
121	WAS	49	SMW	24	SMW	22	NYP-NWK	AM	Scheduled in track usage program, Other, XPT-XPT, HELD A/C SINGLE TRACKING NO.3 TRK LACK TO HUDSON	
122	NYP	21	CAR	36	CAR	36	WAS-WAS	AM	HEP, 9651, BATTERIES DEAD IN CAB CAR, NO MARKER LIGHTS ON	
135	WAS	58	ITI	41	ITI	35	BOS-BOS	AM	Service, turn, or wye train, 150, Late turn	

Amtrak Endpoint OTP Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/16/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
140	SPG	17	SMW	16	PTI	10	WND-WNL	AM	Meet, 497, Other, XHA
143	WAS	85	SMW	41	SVS	31	NHV-NHV	MN	Adding engine 653 to consist. Waited for train 66 to be capped with protect engine.
145	RNK	20	PTI	38	PTI	26	CLP-CVS	NS	Meet 66, Control Point, gilbert
146	SPG	64	SVS	43	SVS	43	WAS-WAS	AM	Water, commissary, toilet/trash dumping, SHORT TURN INBOUND 143
149	WAS	21	SMW	17	PTI	6	PHL-WIL	AM	Follow, 2267, Control Point, .
150	BOS	114	CAR	102	CAR	102	PHL-PHL	AM	Set out defective car, 82705 AX AS, late out of the yard a/c car was shopped
161	WAS	30	SMW	29	SMW	11	OSB-NHV	AM	Scheduled in track usage program, Control Point, Branford-Guilford, track outage single track
162	BOS	18	SMW	17	SMW	11	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK
164	BOS	19	CTI	18	SMW	10	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XHU, HELD A/C SINGLE TRACKING NO.3 TRK HUDSON TO LACK
165	WAS	17	DCS	16	DCS	16	NYP-NWK	AM	T.O.L, Other, TOL OVER NO.23SW REVERSE HUDSON
169	PHL	24	DCS	19	DCS	17	MET-TRE	AM	Power switch failure, Other, XH1-XH1, CONGESTION AHEAD DUE TO 21SW FAILURE AT HAM.
189	WAS	23	SMW	11	SMW	8	WIL-NRK	AM	Diversions around M/W work, Control Point, ., operated 1trk ragan to bacon a/c 3trk davis to bacon o/s.
195	WAS	39	SMW	37	SMW	21	XSH-NYP	AM	Scheduled in track usage program, Other, XM9-XM9, HELD FOR AM162 A/C NO.1 TRK OOS MANOR TO LEGGETT
450	SPG	38	CON	29	CON	29	NHV-NHV	AM	Hold for connecting train, Held for late connection of delayed No. 150 then released without connecting on account of further delays.
464	SPG	18	CON	14	CON	12	NHV-NHV	AM	Hold for connecting train, late connection of AM164
465	NHV	24	PTI	19	PTI	19	SPG-WNL	AM	Meet, 464, Milepost w/Letters, SPG, WNL, AM465 waited for AM464 to clear single track
637	PHL	46	DCS	37	DCS	34	MET-TRE	AM	Power switch failure, Other, XH1-XH1, CONGESTION DUE TO 21SW FAILURE TO REMAIN NORMAL AT HAM

Amtrak Endpoint OTP Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
671	HAR	14	DCS	14	DCS	14	NYP-NWK	AM	T.O.L, Other, OVER NO.23SW AT HUDSON
672	NYP	15	PTI	14	SMW	9	NWK-NYP	AM	Scheduled in track usage program, Other, HUDSON-LACK SINGLE TRACKING
19	NOL	94	WTR	122	WTR	62	TCL-MEI	NS	Heat order Milepost, 143.5, 292.7
20	NYP	31	WTR	87	WTR	54	MEI-TCL	NS	Heat order 40mph, Milepost, 292.7, 143.5
691	BRK	39	FTI	27	FTI	12	EXR-EXR	CS	Hold for freight to clear at New Fields M426, Other, EXE
693	BRK	15	PTI	7	PTI	7	SAO-ORB	CS	Meet 696, Control Point, Ocean Park
63	TWO	136	DSR	2	DSR	2	XSV-ROC	CS	Per bulletin Milepost, 353.9, 354.2, 50, 1
64	NYP	54	HLD	25	HLD	19	NFS-NFS	XC	High passenger count Two doors, low platform VIA Rail had to unload then we had to load
238	NYP	20	PTI	24	PTI	21	POU-CRT	MN	Meet 1233, Control Point, 72
240	NYP	41	RTE	34	RTE	15	POU-CRT	MN	Dispatcher hold Control Point, 72
245	ALB	82	ITI	84	ITI	84	NYP-NYP	AM	Service, turn, or wye train, 68
280	NYP	31	RTE	49	RTE	47	POU-CRT	MN	Dispatcher hold Control Point, 46
290	NYP	13	CTI	22	CTI	16	POU-CRT	MN	Follow metro, 8844, Milepost, 62, 38
291	BTN	46	DSR	25	ITI	23	NYP-NYP	AM	Service, turn, or wye train, 240
1233	PIT	76	PTI	42	PTI	30	CRT-POU	MN	Meet Held for 240, 240, Control Point, 58
1246	NYP	48	ITI	71	ITI	71	PIT-PIT	CS	Service, turn, or wye train 1233
48	NYP	38	PTI	45	PTI	28	POU-CRT	MN	Meet 49, Control Point, 72
43	PGH	21	WTR	25	WTR	25	JST-LAB	NS	Flash flood warning Milepost, 271.4, 280.7
72	RGH	11	PTI	9	PTI	9	DNC-CYN	NS	Meet #AM75, Siding, Sullivan
89	SAV	61	FTI	76	TRS	46	KTR-CHS	CS	Vehicle on track ahead Control Point, A 385.7
57	WAS	75	DCS	50	DCS	50	NYP-NWK	AM	T.O.L, Other, NO.23SW AT HUDSON CAUSED DELAY
25	NOL	83	WTR	92	WTR	67	MOE-PAG	CS	High winds Milepost, 677.9, 723.0
5	EMY	101	DBS	116	DBS	115	DAV-MTZ	UP	Debris blocking track (no debris strike) Report of Power Lines down. Held CP RV065., Milepost, 55.6, 55.6
6	CHI	33	RTE	97	RTE	85	XXP-XFJ	UP	Dispatcher hold Wait for track inspector and bridge inspector for possible bridge strike @ 8.63 Moffat tunnel sub, Control Point, DS012

Amtrak Endpoint OTP Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
734	SAC	104	POL	114	POL	114	FFV-FFV	UP	Fire department hold Downed power lines
736	SAC	55	DBS	64	DBS	64	SUI-SUI	UP	Debris blocking track (no debris strike) Power lines down across tracks, Milepost, 55.4, 55.4
743	OKJ	Trn Cancelled	PTI	2	PTI	2	FFV-SUI	UP	Cross over or go around Amt732, Control Point, Rv052
745	SJC	56	DMW	65	DMW	65	DAV-DAV	UP	Hold for defect repair Power lines down., Milepost, 55.35, 55.4
747	SJC	65	TEN	60	TEN	60	SAC-SAC	UP	Failure of diesel engine THE JPBX 922 WAS THE ENGINE FAIL We jumped trains and took over 734's equipment w/the 2013, C2013
50	NYP	No OS Rpt	WTR	29	WTR	25	CHW-MNG	CS	Flash flood warning Restricted speed at times looking for flooding and downed trees., Milepost, 451.9, 427.8
508	PDX	21	DSR	20	PTI	9	EUG-ALY	UP	Meet Amtrak 11, Milepost, 667.6, 667.6
517	VAN	33	SVS	31	SVS	31	SEA-TUK	BN	Fuel
518	VAC	42	DSR	49	PTI	12	VAN-KEL	BN	Meet amt517, Control Point, kelso south
58	CHI	84	WTR	114	WTR	22	HMD-MCB	CC	Heat order Other, mcomcomb sub
59	NOL	283	FTI	147	FTI	61	MCB-HMD	CC	Meet Run around cn5262 @ osyka after 3, cn2264, cn7773, Other, osyka
822	OKC	27	DSR	38	DSR	25	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, m1, Milepost, 350.7, 351.1, 50, m1, Milepost, 353.7, 354.1, 60, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 360.6, 361.1, 60, m1, Milepost, 364.7, 365.1, 45, m1, Milepost, 368.6, 369.1, 60, m, Milepost, 371.4, 371.5, 50, m, Milepost, 374, 374.1, 60, m, Milepo
341	MKE	17	ENG	17	ENG	6	XRO-SVT	CP	Rough ride 517
350	PNT	17	PTI	36	PTI	15	KAL-XGO	MI	Meet 365, Control Point, 140
355	CHI	24	DSR	24	PTI	14	ARB-JXN	MI	Meet AMTK352, Control Point, 56
584	SAN	39	CTI	23	CTI	15	SNC-SNP	SC	Meet mtlk, Control Point, serra
777	SLO	21	CTI	24	CTI	24	MPK-XMR	UP	Meet Metrolink, 1164, Control Point, Las Posas
701	SAC	17	TRS	21	TRS	17	LOD-LOD	UP	Vehicle on track ahead Dispatcher held Train at Lodi depot until vehicle removed from tracks and clear., Milepost, 71.45, 71.45
702	BFD	51	FTI	80	FTI	64	MDR-FNO	BN	Vandalism to train air hoses train broke down Siding, Gregg, bnsf 8004

Amtrak Endpoint OTP Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
704	BFD	63	SYS	51	SYS	40	SAC-SAC	UP	Re-crew / job briefing Waited for engineer
713	OKJ	18	FTI	14	FTI	11	FNO-FNO	BN	HOLD AT FNO FOR DIASBLED FREIGHT AT 1007.2 Other, FNO STA, 8372
719	OKJ	45	PTI	57	PTI	25	XPR-MTZ	UP	Meet 751, 748, Control Point, ferry
3	LAX	115	FTI	114	DCS	53	GCK-LMR	BN	Restrictive signal(s) from unknown cause A/M, Appr x 2, Stop, Restr x 4, Dark, Clr, Milepost, 411.1, 431.7
4	CHI	177	FTI	234	FTI	80	NDL-KNG	BN	Follow Approaching trains slow, had been single tracking, due to washout East of Kingman. Red signal, East Griffith. Met BNSF 3865 W, BNSF 7544 W, BNSF 6875 W. Instructed by DS to pass red signal on the lookout for an occupancy. Next signal restricting., BNSF unknown, Milepost, 528, 516
22	CHI	56	FTI	117	FTI	50	MVN-LRK	UP	Follow Frt had hot bearings issue, up 2645, Milepost, 371.3, 345.9
300	CHI	24	RTE	26	RTE	24	DWT-JOL	UP	Line manual or spring switch Milepost, 55, 55
301	STL	86	DCS	86	DCS	61	JOL-BNL	UP	Restrictive signal(s) from unknown cause Code line failure, Stop, Control Point, x045
302	CHI	55	DCS	63	DCS	63	DWT-JOL	UP	Power switch failure Milepost, 55, 55
305	STL	53	WTR	55	WTR	55	XWR-XQT	UP	High winds Control Point, Q Tower
306	CHI	50	FTI	48	FTI	16	XUD-SMT	CC	Cross Traffic unknown, Control Point, CANAL
380	CHI	58	FTI	36	FTI	21	MAC-GBB	BN	Meet BNSF 6876, Control Point, Abingdon
381	QCY	64	FTI	72	FTI	72	MAC-QCY	BN	Follow bnsf6876, Milepost, 242, 259, key train
382	CHI	30	DSR	11	CAR	10	PCT-MDT	BN	Air / Brake / Wheel ID4004, Dragging main res. Hose on rear car
390	CHI	67	WTR	51	SYS	10	CHM-RTL	CC	Re-crew / job briefing Other, levertt jct
391	CDL	48	WTR	43	PTI	14	RTL-CHM	CC	Meet AM 390, Siding, Leaverett
392	CHI	93	WTR	70	PTI	33	MAT-CHM	CC	Meet amtrak 393, Control Point, south humboldt
393	CDL	38	WTR	35	WTR	8	HMW-KKI	CC	Heat order Milepost, 24, 55
311	KCY	26	DSR	19	RTE	10	STL-XGA	TR	Inability to contact dispatcher Due to Dispatcher not answering phone, AMT22 was lined into the station and prevented AMT311 from departing station on time. Scheduled departure time is 0810., Other, STL Station

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/16/2026

26-FOI-00671 00000008693 "UNCLASSIFIED" 9/2/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
318	CHI	33	FTI	50	DSR	12	XUD-SMT	CC	Per bulletin Milepost, 18.0, 17.0, 10, MT, Milepost, 15.35, 15.15, 30, MT2	
319	KCY	328	FTI	150	TRS	100	SPI-CRV	UP	Tree on Track ahead of train Waited for tree removal, Milepost, 190.2, 190.2	

Amtrak Initial Terminal Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/16/2026

Terminal	Train	Date	Late	Delay	Cause
TWO	64	08/16	1		
BOS	135	08/16	41	35	Service, turn, or wye train, 150, Late turn
BOS	135	08/16	41	6	Service, turn, or wye train, 150, Late turn
BRK	696	08/16	8	8	Freight traffic caused late inbound 691
HAR	612	08/16	2	2	Passenger and/or baggage
MIA	40	08/16	10	10	Service, turn, or wye train 41
NHV	464	08/16	14	2	Hold for connecting train
NHV	464	08/16	14	12	Hold for connecting train, late connection of AM164
NHV	464	08/16	14	2	Hold for connecting train
NHV	464	08/16	14	12	Hold for connecting train, late connection of AM164
NYP	19	08/16	22	22	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING AND OBS CLEANING
NYP	51	08/16	15	15	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	79	08/16	37	20	Set out defective car, 61052, STOPPED IN LINE 4 WITH AIR BLOWING IN THE LAST 2 CARS
NYP	79	08/16	37	17	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	89	08/16	5	5	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATRERING
NYP	97	08/16	34	34	Water, commissary, toilet/trash dumping, SSYD DELAYED
NYP	103	08/16	2	2	Passenger and/or baggage, BOARDING
NYP	155	08/16	4	4	Door, 0000, DOOR LIGHTS
NYP	235	08/16	3	3	Passenger and/or baggage
NYP	241	08/16	2	4	Passenger and/or baggage
NYP	283	08/16	10	10	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE RELEASE BY CATERING
NYP	291	08/16	23	23	Service, turn, or wye train, 240
NYP	663	08/16	2	2	Cross over or go around, AM155, Other, NYP-NYP , HELD A/C AM155 XING AHEAD
NYP	2233	08/16	8	8	Other late crew
NYP	2290	08/16	4	4	Passenger and/or baggage, BOARDING
PHL	117	08/16	1	1	Passenger and/or baggage

Amtrak Initial Terminal Details

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/16/2026

Terminal	Train	Date	Late	Delay	Cause
PHL	150	08/16	102	102	Set out defective car, 82705 AX AS, late out of the yard a/c car was shopped
PIT	1246	08/16	71	71	Service, turn, or wye train 1233
WAS	122	08/16	36	36	HEP, 9651, BATTERIES DEAD IN CAB CAR, NO MARKER LIGHTS ON
WAS	146	08/16	48	43	Water, commissary, toilet/trash dumping, SHORT TURN INBOUND 143
WAS	146	08/16	48	5	Meet, AM2259, Bridge, J, AM2259 ARRIVING
WAS	166	08/16	2	2	Delay in Block, CREW IDENTIFIED OPENED DOOR, DOOR LIGHT SHOWING
WAS	2218	08/16	4	4	Re-crew / job briefing, DESCREANCIES IN PAPERWORK, 2 MAP 100s. ENGINEER NEEDED ASSISTANCE FROM MECHANICAL.
WAS	2222	08/16	4	2	Meet, MARC, MK491, Bridge, J, MK491 ARRIVING
WAS	2222	08/16	4	2	Meet, AM2259, Bridge, J, AM2259 ARRIVING
CHI	41	08/16	8	8	Brought down late from the yard Train brought down late and the yard crew didn't have a face to face with the engineer, so we had to do a class 2 brake test before departing., Other, CUS tk 28
CHI	354	08/16	1	1	Unticketed or fare evading passenger Regular fare evader removed from train by APD, Other, CHI
CHI	1333	08/16	21	21	Service, turn, or wye train 332, Adding car 34030 due to car 34136 not having bathrooms, 514 swapped for 518
BFD	703	08/16	3	3	Passenger and/or baggage Passenger with multiple children, plus two infants insisted on waiting at the door where we were boarding two pax with the lift, then refused to hurry.
BFD	717	08/16	13	13	Water, commissary, toilet/trash dumping
GTA	782	08/16	10	10	Meet CO 358, Control Point, Los Posas
OKJ	716	08/16	1	1	Wait for station track AMTK 734, Control Point, Magnolia
PDX	11	08/16	10	10	Hold for busses from SEA
SAC	704	08/16	40	40	Re-crew / job briefing Waited for engineer
SAC	745	08/16	1		
SAC	747	08/16	60	60	Failure of diesel engine THE JPBX 922 WAS THE ENGINE FAIL We jumped trains and took over 734's equipment w/the 2013, C2013
SAC	749	08/16	3	3	Meet 742 arrived on track six due to equipment swap, 742, Control Point, RV988
SAN	595	08/16	5	5	Service, turn, or wye train 584
SJC	748	08/16	10	10	Service, turn, or wye train 745
VAN	506	08/16	1	1	Loading problem Engineer wasn't sure why it wasn't loading but after turning off and back on the hep among a couple other things the load came back., 186

Eastern Region

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	99.2	94.8	166	1
CDOT	95.0	75.0	88.5	92.4	16	4
MARC	95.0	100.0	83.7	90.2	12	0
SEPTA	95.0	100.0	94.7	91.5	108	0
NJT-NED	95.0	79.5	91.4	88.6	190	39
NJT-SED	95.0	100.0	99.3	97.2	24	0

Operating Highlights

Train 99(16) - South of Richmond, VA - Weather

16AUG26: Train 99(16) was delayed on the CSX Peninsula Subdivision between MP 83.4 and MP 39.4 due to high winds warnings.

Train	Delay	Comment
99(16)	35"	

Train 57(16) - West of New York Penn Station - TOL/Signal

16AUG26: Train 57(16) was delayed on the Amtrak NYP Line at Hudson/MP 8.3 due to the NO. 23 switch failing and an errant track occupancy light.

Train	Delay	Comment
57(16)	50"	

Train 2260(16) - East of New Haven, CT - Engine Failure

16AUG26: Train 2260(16) was delayed on the Amtrak New Haven to Boston Line near MP 73.6 due to a mechanical issue. The Engineer de-prepared the train to resolve the issue.

Train	Delay	Comment
2260(16)	35"	

Train 2265(16) North of New York, NY - Engine Failure

16AUG26: Next Gen Train 2265(16) with set 21 PC/2129 and PC/2122 reported they were stopped on track 3 with power issues and they had no HEP. The crew was trouble shooting with mechanical and was able to reconfigure the pantograph and restore the HEP.

Train	Delay	Comment
2265(16)	30"	

Train 146(16) Washington, DC - Servicing

16AUG26: Train 146(16) with E/650 and 8 "UNCLASSIFIED" delayed departing Washington due to turning off late 143(16) that arrived 256P-ET 1 hour and 25 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
146(16)	48"	

Train 122(16) Washington, DC - Servicing

16AUG26: Train 122(16) with E/626, CC/9650 was delayed departing Washington due to CC/9650 having problems after mechanical attempted to make repairs but it was necessary to remove the car.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
122(16)	36"	

Train 97(16) New York, NY - Servicing

16AUG26: Train 97(16) with E/614 and 11 cars was delayed departing New York due to late release from catering.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(16)	36"	

Train 135(16) Boston, MA - Servicing

16AUG26: Train 135(16) with E/631 and 9 cars was delayed departing Boston due to turning off late 150(16) that arrived at 110P-ET 1 hour and 54 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
135(16)	41"	

New York to Philadelphia main line - Bridge Strike

16AUG26: At 1256P-ET A vehicle struck the bridge at Parsonage RD., MP 24.38, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 129P-ET, the bridge was inspected and released for normal service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2215(16)	03"	
118(16)	13"	

Train 280(16) South of Poughkeepsie, NY - Routing

16AUG26: Train 280(16) with E/97 and 5 cars was delayed on the MNRR Hudson Line at MP 46.2 due to a dispatcher hold.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
280(16)	47"	

CSX Heat Orders - Weather

16AUG26: Multiple trains were delayed by CSX heat orders that were in place from 1300-1900 on the following subdivisions Alleghany, Kanawha, New River, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, Tampa Terminal and NO&M.

Train	Delay	Comment
40 (16)	32"	
98 (16)	40"	
52 (16)	19"	
97 (15)	20"	

Train 98(16) Miami, FL - Car Failure

16AUG26: Train 98(16) was delayed north of Miami due to the water pump being shorted out on C/28021 and mechanical meeting the train to replace.

Train	Delay	Comment
98 (16)	32"	

Train 66(15) New Haven, CT - Adding Engine/Servicing

16AUG26: Train 66(15) with E/658 and 5 cars was delayed departing New Haven due to E/620 being added for Boston.

Train 143(16) was also delayed departing New Haven due to holding for their engine change.

Train	Delay	Comment
66 (15)	30"	
143 (16)	31"	

Train 79(16) New York, NY - Car Failure

16AUG26: Train 79(16) with E/603 and 7 cars was delayed departing New York due to being stopped in line 4 at MP 1.77 due to the last two cars blowing air. The rescue engine was being prepared. The crew on 79(16) was able to build the air back up and complete a brake test and proceed to the station.

Train	Delay	Comment
79 (16)	37"	

Train 280(16) South of Niagara Fall, NY - Debris

16AUG26: Train 280(16) operating with engine 97, 5 cars, engine 709, and 5 customers onboard struck a deer and took no exceptions 2 miles south of Niagara Fall, NY on the CSX Niagara subdivision.

Train	Delay	Comment
280 (16)	06"	

Train 150(16) Philadelphia, PA - Servicing

16AUG26: Train 150(16) operating with engine 631, 9 cars, and 300 customers onboard was delayed departing Philadelphia, PA on the Amtrak NYP Line due to a late yard release caused by late inbound 169(15). Train 150(16) was further delayed departing Philadelphia due to shopping the rear coach and replacing it due to connectivity issues.

Train 50(15) Montgomery, WV -Water Over the Rail/Weather

16AUG26: Train 50(15) 26:FOI-00671 00000008693 car UNCLASSIFIED 9/2/2026 delayed at the CSX New River subdivision at MP CA 424.6 due to water over the rail at MP CA398.0 on both mains between Fayette and Swell. CSX Maintainer arrived and was inspecting the area and found multiple trees and slides in the area.

Due to this the following service adjustments were made: train 50(15) terminated at Charleston, WV and Originate at Washington, DC and train 51(16) terminated at Washington, DC and Originate at Charleston, WV.

Busses for train 51(16) departed at 418P-ET and busses for train 50(15) arrived Charleston at 338P-ET.

Service Recovery for train 50(15) passengers was initiated with food and drinks ordered to the Charleston station.

Due to crew Hours of Service and Recrew location concerns, Train 51(16) was advanced to Huntington where it was recrewed. Train 51(16) then held for the LSA and TA on the last bus from WAS. The bus was delayed near Oak Hill, WV due to mechanical failure.

UPDATE: After more consideration, Train 51(16) was released from Huntington without the LSA and TA, as they were at least another 2 hours out.

WBS#: B.TR.100150.7044

Train	Delay	Comment
51(16)	5'31"	ORIG CHW
50(15)	9'04"	ORIG WAS
51(16)	30"	Hold at HUN for LSA/TA
51(16)	00"	TERM WAS
50(15)	00"	TERM CHW

Metro North Track Outage - Croton, NY - M of W Work

15AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

Train	Delay	Comment
235(15)	43"	
236(15)	10"	
280(15)	16"	
230(15)	02"	
233(15)	50"	
290(15)	24"	
238(15)	12"	
239(15)	29"	
49(15)	43"	
48(14)	1'00"	
1233(16)	1'08"	
240(16)	31"	
291(16)	25"	late turn off 240(16)
1246(16)	1'11"	LATE TURN OFF 1233(16)

Downeaster Service - CSX Trackwork - M of W Work - 8/17 - 8/20

28JUL26: CSX Portland, ME is conducting a "UNCLASSIFIED" trackwork between Boston North station and Brunswick, ME MP BRU 5.0 to MP BRU 0.5 from Monday, August 17, 2026 to Thursday, August 20, 2026 from 7A-3P. The following service adjustments have been made:

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound:

- Train 681 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.
- Train 683 (17Aug-20Aug), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 684 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 686 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.
- Train 688 (17Aug-20Aug), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3683 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, and 3688 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100151.0835

Maintenance of Way Highlights

Train 105(16) West of New York, NY - Scheduled M/W Work

16AUG26: Train 105(16) with E/655, E/611 and 10 cars was delayed on the New York to Philadelphia due to being held at Erie account single tracking on track 3 Lack to Hudson.

Train	Delay	Comment
105(16)	30"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by ~~26 For 00671 00000008693~~ exp ~~UNCLASSIFIED~~ 1 local 8/2/2026

- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No data

Eastern Region

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Train 1(15)/421(14) East of Yuma, AZ - Freight Train Interference

17AUG26: Train 1(15)/421(14) with 230 customers was delayed east of Yuma, AZ, near Stoval (MP 802) at MP 804.0 on the Union Pacific Gila Subdivision due to freight traffic interference. The train was held while UP freight train ZG2LC-14 set out locomotive UP 7697 in Stoval Siding due to a locked axle condition. While the setout was being completed, Train 1(15)/421(14) was also delayed behind UP freight train ZAILA-15 with UP 6063. An operating plan was implemented to move ZAILA-15 into Stoval Siding after the first train cleared, allowing Train 1(15)/421(14) to proceed around the train. Train 1(15)/421(14) resumed its trip, although it continued to follow ZG2LC-14 eastward toward Wellton (MP 770.9) where it was able to pass.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(15)/421(14)	1'16"	

Train 307(16) North of Alton, IL - Freight Train Interference

16AUG26: Train 307(16) was delayed on the UPRR Springfield subdivision 12 miles north of Alton at Miles/MP 243.2 due to meeting CGMBV-16.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
307(16)	1'06"	

Train 319(16) East of Sedalia, MO - Freight Train Interference

16AUG26: Train 319(16) with 140 customers was delayed on the UPRR Sedalia subdivision starting 17 miles east of Sedalia between MP 172.3 and Pleasant Hill/MP 249.8 due to following MASP-16. A saw by was performed at Pleasant Hill and 319(16) continued to Lees Summit operating in the clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(16)	1'48"	

Train 4(15) East of Lamar, CO - Weather

16AUG26: Train 4(15) was delayed on the BNSF La Junta subdivision starting 19 miles east of Lamar between MP 483.0 and MP 417.0 due to high wind warnings.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(15)	45"	

Train 4(16) East of Victorville, CA - Freight Train Interference

16AUG26: Train 4(16), carrying 136 customers onboard, was delayed approximately 10 miles east of Victorville, CA, while holding at MP 26.4 on the BNSF Cajon Subdivision to meet BNSF freight traffic.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(16)	42"	

Train 305(16) East of St. Louis, MO - Weather

17AUG26: Train 305(16) was delayed on the BNSF Merchant subdivision one mile east of St. Louis due to high wind warnings at the Merchant Bridge/MP 1.0.

Train	Delay	Comment
305(16)	55"	

Train 3(16) West of La Plata, MO - Freight Train Interference

16AUG26: Train 3(16) with 182 customers was delayed on the BNSF Marceline subdivision starting 34 miles west of La Plata between East Marceline/MP 346.9 and Congo/MP 444.3 due to following BN 8102.

Train	Delay	Comment
3(16)	30"	

Train 392(16) North of Mattoon, IL - Passenger Train Interference

16AUG26: Train 392(16) with 96 customers was delayed on the CN Champaign subdivision 11 miles north of Mattoon at Humboldt/MP 161.2 due to meeting train 393(16).

Train	Delay	Comment
392(16)	32"	

Train 747(16) Sacramento, CA - Third Party Contractor Engine Failure

16AUG26: Train 747(16) was delayed due to mechanical issues with its assigned equipment consisting of CC/C8302, four cars, and locomotive JPBX922. After troubleshooting efforts were unable to resolve the condition, a decision was made to utilize the inbound Train 734(16) equipment to operate the service. 734(16) was late arriving due to power lines across tracks east of Fairfield-Vacaville station, but once arrived and reassigned, 747(16) departed.

Service recovery was initiated with customers receiving 20% cafe discount.

Train	Delay	Comment
747(16)	1'00"	

Train 704(16) Sacramento, CA - Crew Issue

16AUG26: Train 704(16) was delayed departing Sacramento, CA, while awaiting the arrival of an engineer. Once the engineer arrived and all required safety briefings and operational checks were completed, Train 704(16) departed with 110 customers onboard.

Train	Delay	Comment
704(16)	40"	

Train 734(16) East of Fairfield-Vacaville, CA - Power Lines on Tracks

16AUG26: Train 734(16) carrying 00000008693 "UNCLASSIFIED" on 8/2/2026, was delayed at Fairfield-Vacaville, CA, Station due to power lines down across the tracks east of the depot at MP 55.4 on the Union Pacific Martinez Subdivision. A Union Pacific Track Inspector and local utility personnel responded to the scene to remove the obstruction and restore safe operations. Once the affected area was cleared, train movements resumed through the territory under a 40 MPH restriction.

The incident also impacted several other trains operating in the corridor:

-Train 5(14), carrying 145 customers onboard, was held west of Davis, CA, at MP 66.26 on the Union Pacific Martinez Subdivision while awaiting the reopening of the affected territory.

-Train 745(16), carrying 241 customers onboard, was held at Davis, CA, Station pending track clearance.

-Train 736(16), carrying 66 customers onboard, was held at Suisun-Fairfield, CA, Station until train movements resumed.

Service Recovery was initiated on trains 734(16), 736(16), and 745(16) with customers receiving 20% cafe discount.

Train	Delay	Comment
734(16)	1'54"	
5(14)	1'55"	
736(16)	1'04"	
745(16)	1'05"	

Train 25(16) West of Mobile, AL - Weather

16AUG26: Train 25(16) was delayed on the CSX NO&M subdivision starting 11 miles west of New Orleans between MP 677.9 and MP 723.0 due to high wind warnings. Additional delay was taken at MP 684.8 due to downed trees.

Train	Delay	Comment
25(16)	15"	Downed trees
25(16)	1'17"	High winds

Train 4(14) West of Galesburg, IL - Freight Train Interference

16AUG26: Train 4(14) was delayed at Cameron Jct/MP169.8, 8 miles west of Galesburg, IL, on the BNSF Ottumwa Subdivision, meeting eastbound BNSF freight traffic.

Train	Delay	Comment
4(14)	35"	

Train 3(15) West of Las Vegas, NM - Passenger Train Interference

16AUG26: Train 3(15) with 138 customers was delayed west of Las Vegas, NM on the BNSF Glorieta subdivision. The train was delayed due to meeting train 4(15) at Fox siding.

Train	Delay	Comment
3(15)	47"	
4(15)	15"	

Train 8(15) West of Havre, MT - Freight Train Interference

16AUG26: Train 8(15), carrying 118 customers, was delayed approximately one mile west of Havre, MT, on the BNSF Milk River Subdivision. The delay occurred while meeting two BNSF freight trains, BN7387 and BN8342, at Havre West.

Train 786(16) North of Lompoc-Surf, CA - Passenger Train Interference

16AUG26: Train 786(16) carrying 100 customers onboard was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.6) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Train 14(16).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(16)	32"	

Train 517(16) Seattle, WA - Fueling

16AUG26: Train 517(16), carrying 202 customers onboard, was delayed after departing Seattle, WA, on the BNSF Seattle subdivision. The train operated to Seattle Yard to fuel E/186. Once fueling was completed, the train departed and continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
517(16)	31"	

Train 319(16) South of Springfield, IL - Downed Tree

16AUG26: Train 319(16), with 278 customers, was delayed at MP190.5, 5 miles south of Springfield, IL, on the UPRR Springfield Subdivision, due to a downed tree ahead. Train 319(16) held for UPRR MoW to arrive and clear tree from track.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(16)	1'40"	

Train 19(15) North of Birmingham, AL - Freight Train Interference

16AUG26: Train 19(15) was delayed just north of Birmingham, AL/MP143, on the NS AGS South District, holding for freight cross traffic to clear and then operating down to 14th and shoving back to the Birmingham station due to a track light on after the freight cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(15)	38"	

Train 381(16) East of Quincy, IL - Freight Train Interference

16AUG26: Train 381(16) was delayed beginning 16 miles east of Quincy, IL, on the BNSF Brookfield Subdivision, following BNSF 6876 between MP242 and MP258. Train 381(16) was further delayed due to BNSF 6876 stopped in emergency ahead at MP253.9 and necessary for BNSF crew to inspect consist and restore air before proceeding south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
381(16)	1'12"	

Train 4(14) West of La Plata, MO - Freight Train Interference

16AUG26: Train 4(14) was delayed at MP351.8, 38 miles west of La Plata, MO, on the BNSF Marceline Subdivision, meeting BNSF 7922, BNSF 7576 and BNSF 5301. BNSF reported switch failure at E. Marceline/MP346.9 contributed to congestion and delays through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(14)	55"	

Train 59(15) North of McComb, MS - Freight Train Interference

16AUG26: Train 59(15) 26-FOI-00671 100000008693 "UNCLASSIFIED" 8/2/2026, carrying 131 customers, was delayed at MP805.8, 1 mile north of McComb, MS, on the CN McComb Subdivision, due to CN local disabled on the single Main ahead at North Arcola/MP837.4. Train 58(16), with 235 customers, was also delayed and held at MP837.8, 22 miles north of Hammond, LA. A CN yard job at McComb set off cars and operated lite power to MP837.4 to assist. CN lite power tied on to the disabled local and shoved train into the Arcola siding to clear route. Once the lite power departed McComb, Train 59(15) was able to advance to McComb and then proceed to Osyka/MP823 to hold. Trains 59(15) and 58(16) were delayed holding for open route through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(15)	54"	N/MCB
59(15)	1'27"	S/MCB
58(16)	2'11"	

Train 702(16) West of Fresno, CA - Freight Train Interference

16AUG26: Train 702(16), carrying 131 customers, was stopped at MP 1010.6 on the BNSF Stockton Subdivision west of Fresno, CA, due to a disabled Z train at MP 1007.2. The Z train had gone into emergency and was unable to recover air. After walking the train, the conductor found a cut air hose and a closed anglecock, and mechanical assistance was requested. Repairs were subsequently completed, and train operations resumed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
702(16)	1'04"	
713(16)	11"	

Train 8(15) East of Essex, MT - Freight Train Interference

16AUG26: Train 8(15), carrying 123 customers, was delayed east of Essex, MT, on the BNSF Hi Line Subdivision. The delay occurred while following BNSF 2026 between MP 1165 and MP 1145, resulting in reduced operating speeds and extended travel time through the territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8(15)	33"	

Train 332(16) Over Capacity - Car Failure

16AUG26: Train 332(16), E/514-3 cars-E/150, was over capacity by 12 seats due to the first car, C/34136 deadhead only Milwaukee, WI to Chicago, IL, due to inoperative toilets. Train 1333(16) was delayed departing Chicago due to turning off Train 332(16) and necessary to add C/34030 for sufficient capacity due to the bad order restrooms on C/34136 inbound.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
332(16)	Over capacity	SVT-CHI
1333(16)	21"	

Train 3(14) East of Victorville, CA - Freight Train Interference

16AUG26: Train 3(14), carrying 145 customers, experienced a delay upon arrival at Victorville, CA, on the BNSF Cajon Subdivision. The delay occurred because the station track was blocked by BNSF locomotive 3952, which was experiencing mechanical issues and was unable to clear the track in a timely manner.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 301(16) South of Joliet, IL - Code Line Failure

16AUG26: Train 301(16) delayed south of Joliet, IL/MP37.3, on the UPRR Joliet Subdivision, due to code line failure ahead at Hitt/MP55.1. Train 301(16) was delayed flagging signals between MP45 and MP55.1. Trains 300(16), 302(16) and 319(16) were also delayed hand-lining switches and flagging through the affected area. UPRR maintainer responded to the location and made some preliminary repairs and had to return with a new power module to complete repairs. After replacing the power module there were still signal issues affecting southbound traffic through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
301(16)	1'01"	
300(16)	24"	
302(16)	1'03"	
319(16)	31"	
22(15)	09"	

Train 380(16) East of Quincy, IL - Engine Failure

16AUG26: Train 380(16), E/BN6106-E/IDTX4610 & 5 cars, was delayed enroute between Quincy, IL and Chicago, IL, operating reduced speed, 69MPH, due to utilizing BNSF freight engine, BN6106 ahead due to PTC issues on E/IDTX4610.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
380(16)	32"	

Train 1(15)/421(14) West of San Antonio, TX - Freight Train Interference

16AUG26: Train 1(15)/421(14) was delayed at Macdona/MP223.6, 13 miles west of San Antonio, TX, on the UPRR Del Rio Subdivision, meeting UP7107.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(15)/421(14)	48"	

Train 381(16) and 382(16) - Consist Devo

16AUG26: Trains 381(16) and 382(16) operated without business class due to 480V issues on C/ID4216 and car operated deadhead only. 17 customers on Train 381(16) and 14 customers on 382(16) were downgraded to coach accommodations.

Train 22(15) South of Little Rock, AR - Freight Train Interference

16AUG26: Train 22(15) was delayed beginning at MP371.3, 25.8 miles south of Little Rock, AR station on the UPRR Little Rock subdivision due to UPRR freight 2645 activating a hot bearing detector. UPRR Freight crew stopped and inspected the bearing and determined it to be hot. Car department arrived on scene and determined the train was okay to proceed to Little Rock to set the car out. Train 22(15) was back on the move at 1232AM CT following the freight at reduced speed into Little Rock AR station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(15)	50"	

Amtrak Crescent Service - Norfolk Southern Heat Orders

15AUG26: Norfolk Southern issued blanket heat orders on the NSRR South Subdivision beginning 45 miles north of Picayune, MS (MP149.0), from MP104 to MP0.5. . The heat orders were in place from 1:00PM-CT to 6:00PM-CT and required operating speeds to be reduced to 40MPH through the affected areas, causing delays to Trains 19(14) and 20(15). Additional heat orders were in effect on the NSRR AGS South Subdivision beginning 2.3 miles north of Meridian, MS (MP295.0), from MP292.7 to MP143.5.

16AUG26: NS heat orders remained in effect between 1:00PM-CT and 6:00PM-CT on the AGS South Subdivision between Birmingham, AL/MP143.5 and Meridian, MS/MP295. Trains 19(15) and 20(16) were delayed operating through the affected areas.

Train	Delay	Comment
19(14)	2'30"	
20(15)	1'25"	
19(15)	2'02"	
20(16)	1'35"	

CN Blanket Heat Orders - City of New Orleans / Illini / Saluki Service

12AUG26: Canadian National issued blanket heat orders for the entire route from Chicago, IL and New Orleans, LA starting at 9:00AM-CT on 12AUG to remain in effect until temperatures decline. Expected to remain through the weekend. During this time, the maximum authorized speed was reduced to 15 MPH below timetable speed throughout most of the territory, with additional 40 MPH speed restrictions in designated areas. On the McComb Subdivision, 40 MPH restrictions were in effect between MP731-MP735 and MP823-MP849. On the Yazoo Subdivision, 40 MPH restrictions were in effect between MP15-MP21, MP70-MP71, MP136-MP137, MP172-MP189, and MP210-MP216. The heat orders caused delays to Amtrak's City of New Orleans, Illini, and Saluki Service.

-Train 58(12) had service recovery enacted, with snack packs, bottled water, coffee, hot tea, and juice provided to all coach customers, while all First Class customers were provided breakfast in the dining car.

-Train 59(12) had service recovery enacted, with snack packs and bottled water provided to all coach customers, while First Class customers received their scheduled meal service in the dining car.

16AUG16: Heat orders remained in effect with ongoing delays to City of New Orleans, Illini and Saluki services through the affected areas.

Train	Delay	Comment
58(12)	2'35"	NOL-CHI
390(13)	37"	
391(13)	46"	
392(13)	53"	CDL-CHI
393(13)	49"	CHI-CDL
59(12)	310"	CHI-NOL
391(14)	1'04"	
390(14)	51"	
58(14)	57"	Crew Rest JAN
392(14)	42"	
393(14)	42"	
59(13)	3'32"	CHI-NOL
390(15)	43"	
391(15)	32"	
58(14)	2'44"	NOL-CHI
392(15)	48"	
58(15)	1'54"	NOL-CHI
59(14)	2'24"	CHI-NOL
58(14)	2'49"	NOL-CHI
390(16)	51"	
391(16)	40"	
59(15)	41"	MEM, hold for CN engineer pilot
58(16)	33"	
59(15)	2'16"	CHI-NOL

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments in "UNCLASSIFIED" 9/2/2026

07AUG26: Due to equipment availability in Chicago, IL, the Midwest Corridor adjustments are now in place through 21AUG:

Pere Marquette:

- Train 370(04) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(07) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(08) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(09) cancelled entirely, with 4 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(10) cancelled entirely, with 4 alternate buses secured between Grand Rapids and Chicago.
- Train 370(13), with 143 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(14), with 162 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(16), with 151 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(17), with 149 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.
- Train 370(20), with 90 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Grand Rapids, MI.
- Train 371(21)m with 155 impacted customers, is cancelled entirely with 3 alternate buses secured between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with 5 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with 4 alternate buses secured between St. Louis and Chicago.
- Train 305(08) cancelled entirely, with 2 alternate buses secured between Chicago, IL and St. Louis, MO.
- Train 300(09) cancelled entirely, with 3 alternate buses secured between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, with 5 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 351(07) cancelled entirely, with 5 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(11) cancelled entirely, with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(11) cancelled entirely, with 2 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(15), with 163 impacted customers, is cancelled entirely with 3 alternate buses secured between Chicago, IL and Pontiac, MI.
- Train 355(15), with 108 impacted customers, is cancelled entirely with 3 alternate buses secured between Pontiac, MI and Chicago, IL.
- Train 350(18), with 31 impacted customers, is cancelled entirely with no alternate transportation provided.
- Train 355(18), with 11 impacted customers, is cancelled entirely with no alternate transportation provided.

Quincy Service:

- Train 381(10) cancelled entirely, with 2 alternate buses secured between Chicago, IL.

- Train 381(14), with 22 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL
- Train 382(14), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago, IL. "UNCLASSIFIED" 9/2/2026
- Train 381(17), with 47 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(17), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.
- Train 381(21), with 15 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Quincy, IL.
- Train 382(21), with 11 impacted customers, is cancelled entirely with 1 alternate bus secured between Quincy, IL and Chicago IL.

Saluki/Illini Service

- Train 391(12), with 54 impacted customers, is cancelled entirely with 1 alternate bus secured between Chicago, IL and Carbondale, IL.
- Train 392(12), with 45 impacted customers, is cancelled entirely with 1 alternate buses secured between Carbondale, IL and Chicago, IL.
- Train 391(19), with 55 impacted customers, is cancelled entirely with 2 alternate buses secured between Chicago, IL and Carbondale, IL.
- Train 392(19), with 18 impacted customers, is cancelled entirely with 2 alternate buses secured between Carbondale, IL and Chicago, IL.

WBS#: B.TR.100150.6992

BNSF Fallbridge Subdivision - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and the Empire Builder services adjusted through to Friday August 7, 2026.

13AUG26: Due to the structural integrity of the building and the need for demolition, the service adjustments on the Cascades, Coast Starlight, and the Empire Builder were adjusted through Sunday, August 16th. Multiple trains were delayed holding for bus connections.

15AUG26: Initial plan is to start detonation of the water tower on Monday, August 17th with the demolition of the remaining structure on Tuesday, August 18th. As a result, the following adjustments have been extended through Wednesday, August 19th.

- Train 500 (04-19) Cancelled entirely, no alternate Transportation.
- Train 502 (04-19) Cancelled entirely, with alternate transportation via Bus 3502.
- Train 504 (04-19) Terminated in Portland, OR, with alternate transportation via Bus 3504.
- Train 518 (04-07) Originated in Seattle, WA with alternate bus transportation.
- Train 518 (08-19) Originated in Vancouver, WA with alternate bus transportation via Bus 3518.
- Train 517 (04-19) Terminated in Vancouver, WA, no alternate transportation (04-10); alternate bus transportation via Bus 3517(11-19)
- Train 506 (04-19) Originated in Vancouver, WA, no alternate Transportation (04-10); alternate bus transportation via Bus 3506(11-19)
- Train 508 (04-19) Terminated in Portland, OR with alternate transportation via Bus 3508.
- Train 503 (04-19) Originated in Portland, OR, with alternate transportation via Bus 3503.
- Train 505 (04-07) Cancelled entirely with alternate bus transportation.
- Train 505 (08-19) Terminated in Vancouver, WA, no alternate transportation(04-10); alternate bus transportation via Bus 3505(11-19)
- Train 507 (04-19) Originated in Portland, OR, with alternate transportation via Bus 3507, operating 1 hour earlier at 1:20P-PT.
- Train 509 (04-19) Cancelled entirely, with alternate transportation via Bus 3509.
- Train 511 (04-19) Cancelled entirely, no alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

- Train 27 (02-17) Will Terminate at Spokane, WA. Alternate Transportation provided.
- Train 28 (04-19) Will Originate at Spokane, WA. Alternate Transportation provided.

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

- Train 14 (04-11) Terminated in Portland, OR, no alternate transportation provided.
- Train 14 (12-18) Terminated in Portland, OR with alternate transportation secured via Bus 3014.
- Train 11 (05-12) Originated in Portland, OR, no alternate transportation provided.
- Train 11 (13-19) Terminated in Portland, OR with alternate transportation secured via Bus 3011.

Bus to operate earlier 8/11-8/16 - Arrow
Bus 3507 to depart 1 hour earlier at 1:20pm
Train 505 Bus VAN-PDX depart VAN at 12pm
Train 518 bus PDX-VAN depart PDX at 1:30pm
Train 517 bus VAN-PDX depart VAN at 330pm
Train 506 bus PDX-VAN depart PDX at 5:20pm

Due to inability to secure other fueling options, Train 517(11-14) was delayed departing Seattle, WA for fueling the equipment.

507(02)	1'41"	bus VAN-PDX	
506(02)	Canceled		
508(02)	45"	bus PDX-VAN	
509(02)	77"	couple 509-511(02)	
509(02)	75"	detour through UP yard	26-59400671 00000008690 "UNCLASSIFIED" 9/2/2026
511(02)	76"	Detour through UP yard	
500(03)	Canceled		
502(03)	Canceled		
511(03)	Canceled		
505(03)	Canceled		
518(03)	Canceled	between SEA-PDX	
507(03)	Canceled	between SEA-PDX	
508(03)	Term PDX		
504(03)	Term PDX		
509(03)	Canceled		
517(03)	Term VAN		
506(03)	Orig VAN		
503(03)	24"	canceled SEA-PDX	
507(03)	1'10"	waiting for bus at PDX	
14(02)	58"	detour	
11(03)	51"	detour	
14(04)	term PDX		
506(04)	1'03"	wait for inbound bus	
518(04)	1'27"	wait for inbound bus	
507(05)	1'09"	PDX- wait for inbound bus	
507(06)	1'06"	PDX- inbound bus	
503(07)	33"	PDX- inbound bus	
507(07)	1'21"	PDX- inbound bus	
503(08)	22"	PDX- inbound buses	
503(09)	28"	bus connections	
518(09)	27"	bus connections	
518(10)	34"	bus connections	
503(10)	45"	bus connections	
503(12)	28"	PDX- inbound bus connections	
517(12)	47"	Fuel in SEA yard due to no Fueling in VAN	
507(12)	1'15"	Connecting Bus	
517(13)	44"	Fuel in SEA Yard	
517(14)	59"	Fuel in SEA Yard	
503(15)	26"	PDX- inbound bus connections	
11(15)	25"	PDX - inbound bus connections	

UPRR Joliet Sub - Chenoa Diamond Air Hose Separations

11JUL25: The following information is in "UNCLASSIFIED" 28-FOI-00671 00000008693 9/2/2028
Diamond/MP102 on the UPRR Joliet Subdivision:

-Train 22(10JUL), E/56-7 Cars, experienced an air hose separation between C/31006 and C/34024. Delay - 45"

09AUG25: Train 22(08AUG), E/58, E/514 and 9 cars, experienced an air hose separation at Car 34049. The crew was able to secure and continue. Delay - 45"

14AUG25: Train 305(14) E/4628 and 5 cars, experienced air hose separation and broken glad hand on car 4008. The crew was able to replace the hose and continue. Delay - 25"

02SEP25: Train 300(02) E/4619 and 5 cars, experienced air hose separation between cars 4116 & 4002. The crew was able to replace the hose and continue. Delay - 4"

03SEP25: Train 300(03) E/4619 and 5 cars, experienced air hose separation between cars 4116 & 4002. The crew was able to replace the hose and continue. Delay - 11"

15OCT25: Train 302(15) E/IDTX4617 and 5 cars, experienced air hose separation between the 3rd and 4th cars, C/ID4121 and C/ID4128. The crew was able to replace the hose and continue.
Delay - 10"

12NOV25: Train 302(15), E/IDTX4617 - 5 cars-EIDTX4626, experienced an air hose separation between 3rd and 4th cars, C/ID4008 and C/ID4130. The was able to secure hose and Train 302(15) was able to proceed north.
Delay - 10"

15NOV25: Train 307(15), E/IDTX4617 and 5 cars, experienced an air hose separation between the 2nd and 3rd cars, C/ID4130 and ID4008. The crew was able to replace the hose and continue.
Delay - 10"

12DEC25: At 7:45AM-CT, Train 300(12), E/63-6 Cars, went into emergency after striking unknown debris after crossing over the Chenoa diamond at MP102.3 and coming to a stop at MP94.4. The Chenoa Diamond is located 21.7 miles north of the Bloomington-Normal, IL station on the UPRR Joliet Subdivision. The strike caused the main reservoir hose on the B-End of C/ID4128 to rip off and go missing. There were no injuries reported to the crew or 277 passengers onboard and no damage to the equipment. The main reservoir was cutoff to the car and then the crew completed a brake test. At 8:00AM-CT, Train 300(12) was back on the move north. Delay ~ 20"

06FEB26: Train 306(06) operating with engine 4603, 5 coaches, and 250 passengers, went into emergency 9.6 miles south of Pontiac, IL, on UPRR Joliet subdivision, after an air hose on car 4116 snapped, causing the train to come to a stop. The crew found the broken air hose and replaced it. Once the hose was replaced and the crew performed their brake test, train 306(06) was able to proceed. Delay 43".

15JUN26: Train 302(15), E/IDTX4625 and 6 cars, with 200 customers, was delayed at MP101.9, 23 miles north of Bloomington-Normal, IL, on the UPRR Joliet Subdivision, due to an air hose separation while operating over the Chenoa diamond at MP102. The crew resecured air hose between the first and second cars, C/ID4001 and C/ID4301. There were no other exceptions to equipment reported. Train 302(15) was on the move north after crew secured hose and performed brake test.

16AUG26: Train 319(16), E/IDTX4624 & 7 cars, with 281 customers, went into emergency over the Chenoa diamond/MP102.3, 10 miles south of Pontiac, IL, on the UPRR Joliet Subdivision. Crew inspected consist and found parted air hose between the 6th and 7th cars, C/ID4310 and C/ID4121. There were no other exceptions to equipment reported. Train 319(16) was on the move south after crew secured hose and performed brake test.

Train	Delay	Comment
319(16)	10"	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task 26-FOI-00671 00000008663 UNCLASSIFIED 5/2/2026 C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No data

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00671

00000008693

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2267 (16)	BOS	2267 will operate with Next Gen equipment in lieu of Legacy equipment.	PASSENGERS NOTIFIED	500	
381 (16)	CHI	Due to a last minute change in equipment trains 381/382(16) caused by BYD car (ID4216/D/H B/O 480V) are over capacity in JY seating. Trains will not have business class seating.	PASSENGERS DOWNGRADED AND NOTIFIED	17	ID4216
41 (17)	CHI	Due to a change in equipment train 41(17) required a schedule change. Line 4111 car 62038 will d/h and we will use 62514. Use WAR report to accommodate all affected passengers.	passengers reaccomodated to ms room	4	62514
566 (17)	LAX	no bike space or wifi	email sent for customer notifications to be sent no bike space no wifi	0	9700
584 (17)	LAX	no bike space or wifi	email sent for customer notifications to be sent no bike space no wifi	0	9700
2290 (16)	NYP	TRAIN OPERATNG WITH NEX GEN EQUIPMENT	N/A	0	3269
2219 (16)	NYP	2219(16) will operate with Next Gen equipment in lieu of Legacy equipment.	PASSENGERS NOTIFIED	229	
382 (16)	QCY	Due to a last minute change in equipment trains 381/382(16) caused by BYD car (ID4216/D/H B/O 480V) are over capacity in JY seating. Trains will not have business class seating.	PASSENGERS NOTIFIED AND DOWNGRADED	13	ID4216
579 (17)	SAN	no bike space or wifi	email sent for customer notifications to be sent no bike space no wifi	0	9700
595 (17)	SAN	no bike space or wifi	email sent for customer	0	9700

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
			notifications to be sent no bike space no wifi		
518 (16)	SEA	Due to cross platform to non-talgo equipment, train is oversold in business class. Please downgrade oversold business class passengers to coach.	PASSENGERS NOTIFIED	18	
2208 (16)	WAS	TRAIN OPERATING WITH NEX GEN EQUIPMENT	N/A	0	3275
2224 (16)	WAS	2224(16) will operate with Next Gen equipment in lieu of Legacy equipment.	PASSENGERS NOTIFIED	125	
122 (16)	WAS	9651 has no 480 power, will deadhead inline WAS-NYP. Capacity reduced 66 seats with no impact to passengers.	NONE	0	9651

Reverse Consists

Train Number	Station	Reason
161 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
99 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
166 (16)	WAS	Consist reversed Business class seat orientation may have changed At Front
150 (16)	PHL	Consist reversed Business class seat orientation may have changed At Front
153 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
103 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
145 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
128 (16)	NFK	Consist reversed Business class seat orientation may have changed At Front
135 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
158 (16)	NFK	Consist reversed Business class seat orientation may have changed At Front
154 (16)	WAS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00671	00000008693 "UNCLASSIFIED" 9/2/2026
118 (16)	WAS	Business class change only Business class seating orientation may have changed At Rear	
189 (16)	NYP	Business class change only Business class seating orientation may have changed At Rear	
86 (17)	NPN	Consist reversed Business class seat orientation may have changed At Front	
129 (17)	NYP	Consist reversed Business class seat orientation may have changed At Front	
178 (17)	RNK	Consist reversed Business class seat orientation may have changed At Front	
155 (16)	NYP	Business class change only Business class seating orientation may have changed At Rear	
94 (17)	NFK	Business class change only Business class seating orientation may have changed At Rear	
88 (16)	WAS	Consist reversed Business class seat orientation may have changed At Front	
171 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front	
95 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front	
85 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front	